

Project	Bedford Beverly Brownfield Site	Report No.	211
BCP Site	BCP Site No. C224384	Date	08/20/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	62-74 °F
Contractor	Haley & Aldrich, Maman	Wind	NW to SE, 11 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Cloudy	Personnel on	E. Nunez
		Site	
11	720/	Times on Cite	8:00am ta 2:00mm
Humidity	72%	Time on Site	8:00am to 3:00pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

## Daily Observations:

• Contractor (International Concrete) continued installation of foundation elements within Lots 14 and Lot 53.

## Waste Disposal/Backfill Import Tracking:

# **Material Export:**

- o None.
- Soil/Fill disposal is summarized below:

	Facility: Bayshore Soil Management, Keasbey, NJ (Non- Haz Soil)		Facility: P Park I Park, NJ (No	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	449 Loads	9,580 CY	2,093 Loads	41,860 CY	955 Loads	19,900 CY	
	Facility: Posil	lico Materials	Facility: Republi	c Environmental	Facility: Conestoga Republic		
	Permitted Wo	ash Plant, LLC,	Systems, LLC, H	atfield PA (Haz	Environmental Systems, LLC,		
	Farmingdale, N	Y (Non-Haz Soil)	So	il)	Prospect Park, NJ (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	687 Loads	13,740CY	5 Loads	100 CY	44 Loads	880 CY	
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present				
Today:	0 Loads	0 CY	in the Final Engineering Report (FER)				
Total:	4.371 Loads	87.420 CY					



• Asphalt disposal is summarized below:

	Facility: Flush Recycling, F		,	Mount		
	(Aspl	_	Materials, Fairless Hills, PA (Asphalt)			
					Tota	ls:
Today:	0 Loads	0 CY	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>117 Loads</u>	<u>2,340 CY</u>	43 Loads	<u>860 CY</u>	<u>160 Loads</u>	3,200 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

o C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	4,640 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

## **Material Import:**

- o None.
- Stone import is summarized below:

	Facility: Mount Hope		Facility:	Mount Hope		
	Quarry,		Quarry,			
	Wharton, NJ		Wharton, NJ			
	(AS	TM #57)	(AS	STM #3)	7	otals:
Today:	0 Loads	Loads 0 Tons		0 Loads 0 Tons		0 Tons
<u>Total:</u>	<u>120 Loads</u>	2,975.76 Tons	36 loads	931.33 Tons	<u>156 Loads</u>	3,907.09 Tons

RCA import is summarized below:

	Facility: Recycling Ltd N	l., Brooklyn,		
	(RC	A)	Tota	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	127 Loads	2,540 CY	<u>127 Loads</u>	2,540 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

## Samples Collected:

No samples were collected.



# **CAMP Activities:**

•	Air monitoring during ground-intrusive activities was performed at two locations during ground
	intrusive work from 9:00 am to 2:15 pm. No 15-minute average concentration of volatiles
	organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller
	than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed
	leaving the site perimeter.

	than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.
•	



# Site Photographs:




Photo 1: View of site conditions in Lot 14, facing northwest.



Photo 2: View of site conditions in Lot 14, facing north.





#### 2360 Bedford Avenue, Brooklyn NY

#### Air Monitoring Log

Date: 2024-08-20

Personnel: E. Nunez

Weather: Cloudy

Humidity: 72%

Wind Direction : NW to SE, 11 mph

Particulate Background (ug/m3) : 7.355

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
09:00		7.355		3.723		0.0		0.0		
09:15		5.134		4.213		0.0		0.3		
09:30		3.946		4.858		0.0		0.0		
09:45		5.468		4.773		0.0		0.0		
10:00		5.207		3.746		0.0		0.0		
10:15		6.089		4.122		0.0		0.0		
10:30		4.122		3.957		0.0		0.0		
10:45		3.952		10.606		0.0		0.0		

# 2360 Bedford Avenue, Brooklyn NY

# Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00		4.999		10.3		0.0		0.0		
11:15		4.537		4.5		0.0		0.0		
11:30		4.808		4.8		0.0		0.0		
11:45		4.527		5.8		0.0		0.0		
12:00		3.954		3.8		0.0		0.0		
12:15		3.584		3.7		0.0		0.0		
12:30		3.727		3.7		0.0		0.0		
12:45		3.818		3.5		0.0		0.0		
13:00		4.520		10.6		0.0		0.0		
13:15		9.035		22.1		0.0		0.0		
13:30		4.329		5.9		0.0		0.0		
13:45		3.868		3.9		0.0		0.0		
14:00		3.546		3.7		0.0		0.0		
14:15		3.185		5.7		0.0		0.0		

