

Project	Bedford Beverly Brownfield Site	Report No.	215
BCP Site	BCP Site No. C224384	Date	08/26/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	68-84 °F
Contractor	Haley & Aldrich, Maman	Wind	NW to SE, 4 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Sunny	Personnel on	E. Nunez
		Site	
Humidity	71%	Time on Site	8:00am to 3:00am
numarty	/170	Time on Site	8:00am to 3:00pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

Daily Observations:

• Contractor (International Concrete) continued installation of foundation elements within Lots 14 and Lot 53.

Waste Disposal/Backfill Import Tracking:

Material Export:

- o None.
- Soil/Fill disposal is summarized below:

	Facility: Bayshore Soil Management, Keasbey, NJ (Non- Haz Soil)		Facility: P Park I Park, NJ (No	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	449 Loads	9,580 CY	2,093 Loads	41,860 CY	955 Loads	19,900 CY	
	Facility: Posillico Materials		Facility: Republi	c Environmental	Facility: Conestoga Republic		
	Permitted Wo	ash Plant, LLC,	Systems, LLC, H	latfield PA (Haz	Environmental Systems, LLC,		
	Farmingdale, N	Y (Non-Haz Soil)	Soil)		Prospect Park, NJ (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
Total:	687 Loads	13,740CY	5 Loads	100 CY	44 Loads	880 CY	
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present				
Today:	0 Loads	0 CY	in the Final Engin	eering Report (FER)		
Total:	4.371 Loads	87.420 CY					



o Asphalt disposal is summarized below:

	Recycling, F	Recycling, Flushing NY (Asphalt) Facility: Mount Materials, Fairless Hills, PA (Asphalt)				
					Tota	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>117 Loads</u>	<u>2,340 CY</u>	43 Loads 860 CY		<u>160 Loads</u>	3,200 CY

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

o C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	<u>4,640 CY</u>

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Material Import:

- o None.
- o Stone import is summarized below:

	Facility: Mount Hope Quarry, Wharton, NJ		Facility:	Mount Hope		
			Q	uarry,		
			Who	arton, NJ		
	(AS	TM #57)	(ASTM #3)		7	otals:
Today:	0 Loads	0 Tons	0 Loads	0 Tons	0 Loads	0 Tons
<u>Total:</u>	<u>120 Loads</u>	2,975.76 Tons	36 loads	931.33 Tons	<u>156 Loads</u>	3,907.09 Tons

RCA import is summarized below:

	Facility:			
	Recycling Ltd	l., Brooklyn,		
	N.	Υ		
	(RC	A)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>127 Loads</u>	2,540 CY	<u>127 Loads</u>	2,540 CY

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

Samples Collected:

No samples were collected.



CAMP Activities:

•	Air monitoring during ground-intrusive activities was performed at two locations during ground
	intrusive work from 8:45 am to 2:00 pm. No 15-minute average concentration of volatiles
	organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller
	than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed
	leaving the site perimeter.

	than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.									
Activitio •	 tivities Planned for Coming Week: Contractor (International Concrete) will continue footing and subgrade preparation in Lots 14 and 53. 									



Site Photographs:




Photo 1: View of site conditions in Lot 14, facing northwest.



Photo 2: View of site conditions in Lot 14, facing northwest.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2024-08-26

Personnel : E. Nunez

Weather: Sunny 71%

Wind Direction : NW to SE, 4 mph

Particulate Background (ug/m3) : 32.670

PID Background (ppm): 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
08:45		32.670		45.960		0.0		0.0		
09:00		24.840		29.542		0.0		0.0		
09:15		24.771		28.322		0.0		0.0		
09:30		32.297		24.140		0.0		0.0		
09:45		24.348		22.460		0.0		0.0		
10:00		22.686		23.480		0.0		0.0		
10:15		19.751		28.338		0.0		0.0		
10:30		19.902		28.262		0.0		0.0		
10:45		32.573		20.117		0.0		0.0		

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00		28.534		19.2		0.0		0.1		
11:15		29.050		17.5		0.1		0.0		
11:30		34.180		18.8		0.1		0.0		
11:45		25.943		20.6		0.1		0.0		
12:00		46.485		16.1		0.1		0.0		
12:15		27.446		15.3		0.0		0.0		
12:30		19.096		13.6		0.0		0.0		
12:45		22.714		25.5		0.1		0.0		
13:00		35.056		60.3		0.0		0.0		
13:15		58.647		36.2		0.0		0.0		
13:30		67.469		28.8		0.0		0.0		
13:45		51.717		28.6		0.0		0.0		
14:00		36.933		28.6		0.0		0.0		