

Project	Bedford Beverly Brownfield Site	Report No.	238
BCP Site	BCP Site No. C224384	Date	09/16/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	59-77 °F
Contractor	Haley & Aldrich, Maman	Wind	NE to SW, 8 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Sunny	Personnel on	E. Nunez
		Site	
Humidity	79%	Time on Site	6:20am to 2:20nm
number	1370	Time on Site	6:30am to 2:30pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

Daily Observations:

• Contractor (International Concrete) continued installation of foundation elements within Lot 14.

Waste Disposal/Backfill Import Tracking:

Material Export:

- o None.
- Soil/Fill disposal is summarized below:

	Facility: Bayshore Soil Management, Keasbey, NJ (Non- Haz Soil)		Facility: P Park I Park, NJ (No	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	458 Loads	9,760 CY	2,096 Loads	41,920 CY	955 Loads	19,900 CY	
	Facility: Posil	lico Materials	Facility: Republi	c Environmental	Facility: Conestoga Republic		
	Permitted Wo	ash Plant, LLC,	Systems, LLC, H	atfield PA (Haz	Environmental Systems, LLC,		
	Farmingdale, N	Y (Non-Haz Soil)	Soil)		Prospect Park, NJ (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
Total:	687 Loads	13,740CY	5 Loads	100 CY	44 Loads	880 CY	
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present				
Today:	0 Loads	0 CY	in the Final Engin	eering Report (FER)		
Total:	4.343 Loads	87.660 CY					



o Asphalt disposal is summarized below:

	Facility: Flush Recycling, F		,	Mount		
	(Aspl	_	Materials, Fairless Hills, PA (Asphalt)			
					Tota	ls:
Today:	0 Loads	0 CY	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>117 Loads</u>	<u>2,340 CY</u>	43 Loads 860 CY		<u>160 Loads</u>	<u>3,200 CY</u>

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

o C&D disposal is summarized below:

	Facility:			
	Mate Fairless I	,		
	(Non-Haz	,	Total	ls:
Today:	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	<u>4,640 CY</u>

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Material Import:

- o None.
- Stone import is summarized below:

	Facility: Mount Hope Quarry, Wharton, NJ		Facility:	Mount Hope		
			Q	luarry,		
			Who	arton, NJ		
	(AS	TM #57)	(ASTM #3)		7	otals:
Today:	0 Loads 0 Tons		0 Loads 0 Tons		0 Loads	0 Tons
<u>Total:</u>	128 Loads 3,172.31 Tons		36 loads 931.33 Tons		<u>164 Loads</u>	4,103.64 Tons

o RCA import is summarized below:

	Facility:			
	Recycling Ltd	I., Brooklyn,		
	N'	Υ		
	(RC	A)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	127 Loads	2,540 CY	<u>127 Loads</u>	2,540 CY

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

Samples Collected:

• No samples were collected.



CAMP Activities:

 Air monitoring during ground-intrusive activities was performed at two locations during ground intrusive work from 7:45 am to 2:00 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities	Planned	for Coming	: Week:
------------	----------------	------------	---------

•	Contractor (International	Concrete)	will	continue	footing	and su	ubgrade	pre	paration	in	Lot	14.
---	--------------	---------------	-----------	------	----------	---------	--------	---------	-----	----------	----	-----	-----

• Contractor (International Concrete) will continue building construction in Lots 14 and 53.



Site Photographs:




Photo 1: View of site conditions in Lot 14, facing northwest.



Photo 2: View of site conditions in Lot 14, facing southwest.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2024-09-16

Personnel: E. Nunez

Weather: Sunny
Humidity: 79%

Wind Direction : NE to SW, 8 mph

Particulate Background (ug/m3): 42.352

PID Background (ppm) : 0.1

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
07:45		42.352		6.008		0.1		0.0		
08:00		19.088		3.657		0.1		0.0		
08:15		19.026		5.987		0.2		0.0		
08:30		25.756		2.910		0.1		0.0		
08:45		40.865		8.468		0.1		0.0		
09:00		26.392		10.314		0.1		0.0		
09:15				12.328				0.0		
09:30		10.585		10.013		0.0		0.0		
09:45		8.778		7.812		0.1		0.0		
10:00		8.510		6.934		0.1		0.0		
10:15		8.605		5.389		0.1		0.0		
10:30		13.258				0.0				
10:45		11.172				0.1				

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00		28.179				0.1				
11:15		10.369				0.1				
11:30		12.819		13.2		0.1		0.0		
11:45		9.784		5.4		0.1		0.0		
12:00		11.008		4.3		0.1		0.0		
12:15		7.964		3.8		0.1		0.0		
12:30		9.204		6.4		0.2		0.0		
12:45		7.113		6.4		0.1		0.0		
13:00		9.718		7.8		0.0		0.0		
13:15		25.983		15.2		0.1		0.0		
13:30		44.570		13.6		0.1		0.0		
13:45		10.544		5.9		0.1		0.0		
14:00		33.474		16.9		0.1		0.0		

