Day 145



SITE OBSERVATION REPORT

PROJECT No.: 170381202

CLIENT:

DATE: Tuesday, June 20, 2023

PROJECT:

LOCATION:

250 Water Street

New York, NY

LLC

250 Seaport District,

c/o The Howard Hughes WE

Corporation

WEATHER: Sunny, 64–77 °F

Wind: NE @ 4 – 7 mph

7:45 am - 9:00 am

MONITOR Jack Millman

TIME:

BCP SITE ID: C231127

EQUIPMENT:

CAT 335 Excavator Jerome J505 Mercury Vapor Analyzer RKI GX-6000 Photoionization Detector

(PID)

Aeroqual ASQ1 Air Monitoring Station

PRESENT AT SITE:

Langan (Environmental) Jack Millman, Michael Au

Suffolk Construction (Suffolk) (General Contractor) Anthony Galu, Jay

Kwon

East Coast Drilling, Inc. (ECD) (Foundation Contractor) Gary Smith, Danny

Rodgers

New York State Department of Environmental Conservation

(NYSDEC) Rafi Alam

OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:

Langan was present to document remediation activities in accordance with the NYSDEC-approved November 2021 Remedial Action Work Plan (RAWP) at the 250 Water Street site (NYSDEC Brownfield Cleanup Program [BCP] Site No C231127).

Site Activities

Suffolk continued mobilizing equipment in preparation for the next phase of remediation. An on-site meeting
was attended by Suffolk, Langan, ECD, and the NYSDEC to discuss project expectations during
implementation of the RAWP.

Cc:	M. Raygorodetsky, P. McMahon, M. Au	Ву:	Jack Millman
			LANGAN



Page 2 of 5

SITE OBSERVATION REPORT

Material Tracking

- No material was exported from the site.
- No material was imported to the site.

Material Import Summary									
Facility Name Location Type of Material	Stone Industries, Inc. Haledon, NJ 1.5/2.5-inch Virgin Stone		Stone Industries, Inc. Haledon, NJ 0.75-inch Virgin Stone		Impact Reuse & Recovery Center or Impact Materials Jersey City, Lyndhurst/Jersey City, NJ 1.5-inch Clean Bluestone		Impact Reuse & Recovery Center, Lyndhurst, NJ General Fill		
Quantities	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)	
Today	0	0	0	0	0	0	0	0	
Project Total	8	184.42	0	0	15	339.65	336	8,216.79	
NYSDEC Approved:	1 800 tons			ions*		720 tons*		19,500 tons*	

*0.75-inch, 1.5-inch, and 2.5-inch virgin stone from the Stone Industries, Inc. facility and 1.5-inch clean bluestone from the Impact Reuse & Recovery Center (IRRC) facility were approved for import of 1,000 cubic yards (CY) and 400 CY, respectively. Assuming a conversion factor of 1.8, each quantity was converted to tons in order to accurately compare with import weight tickets. General fill from the IRRC facility was approved for import of 13,000 CY and a conversion factor of 1.5 is applied.

Material Export Summary (1 of 2)								
Facility Name Location Type of Material	Allocco Recycling Brooklyn, NY Construction & Demolition (C&D) Debris		IRRC Lyndhurst, NJ Construction & Demolition (C&D) Debris		Clean Earth of North Jersey Kearny, NJ Hazardous Lead-Impacted Soil/Fill		Clean Earth of North Jersey Kearny, NJ Non-hazardous Soil/Fill	
Quantities	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)
Today	0	0	0	0	0	0	0	0
Project Total	5	85	42	840	95	1,900	216	4,320

Material Export Summary (2 of 2)								
Facility Name Location Type of Material	Middlesex County Landfill East Brunswick, NJ Non-hazardous Soil/Fill		Keas	oil Management Bbey, NJ mpacted Soil/Fill	Clean Earth of Carteret, NJ Carteret, NJ Non-hazardous Soil/Fill			
Quantities	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)		
Today	Today 0 0 0		0	0	0			
Project Total 261 5,220		267	5,340	66	1,320			

Cc:	M. Raygorodetsky, P. McMahon, M. Au, J. Frey	Ву:	Jack Millman
			LANGAN



Page 3 of 5


SITE OBSERVATION REPORT

<u>Sampl</u>	<u>ing</u>		
•	No samples were collected.		
CAMP	<u>Activities</u>		
•	The community air monitoring plan (CAMP) was n	ot impl	lemented due to a lack of ground-intrusive activities.
<u>Antici</u>	pated Activities		
•	Suffolk and ECD will continue mobilization in pre	paratio	n for the next phase of remediation.
Cc:	M. Raygorodetsky, P. McMahon, M. Au, J. Frey	Dv.	Jack Millman
CC.	ivi. Naygorouetsky, F. Ivicivianon, Ivi. Au, J. Frey	Ву:	LANGAN
	I and the second se	1	



Page 4 of 5

SITE OBSERVATION REPORT





Page 5 of 5

SITE OBSERVATION REPORT

Select Site Photographs:




Photo 1: General view of the site (facing west)

Cc: M. Raygorodetsky, P. McMahon, M. Au, J. Frey By: Jack Millman

LANGAN