

Daily Report for July 1, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4. -Poured concrete in C7, C8, and D5- D8.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C fifth through seventh floors.

Photo 1- View of rebar and formwork in C7 and C8.	
Photo 2- View of pouring concrete in D5 and D6.	





Daily Report for July 2, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4. -Graded soil in C8 and D8.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C fifth through seventh floors.

Photo 1- View of rebar and formwork in C7 and C8.	<image/>
Photo 2- View of formwork, rebar, utility installation in C5 and C6.	





Daily Report for July 6, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4. -Graded soil in C8 and D8.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C fifth through seventh floors.

Photo 1- View of rebar and formwork in C7 and C8.	<image/>
Photo 2- View of formwork, rebar, utility installation in D3, D4, E3, and E4.	





Daily Report for July 7, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Graded stone in C5 and D5.

-Poured concrete in A1-A4, and B1-B4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors. -Continue formwork and rebar installation for Building C fifth through seventh floors.

Photo 1- View of rebar and formwork in C7 and C8.	<image/>
Photo 2- View of grading stone in C5 and D5.	





Daily Report for July 8, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in C5-C8, and D5-D6.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C seventh through ninth floors.

Photo 1- View of pouring concrete, rebar, utility, and formwork installation in C7 and C8.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	

Photo 3- View of pouring concrete in C5 and C6, and rebar, utility, and formwork installation in D3, D4, E3, and E4.





Daily Report for July 9, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors. -Continue formwork and rebar installation for Building C seventh through ninth floors. -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C7 and C8.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 10, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1-A4, and B1-B4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C seventh through ninth floors.

Photo 1- View of rebar, utility, and formwork installation in C7 and C8.	
Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 13, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4. -Poured concrete in C6 and D6.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C seventh through ninth floors.

Photo 1- View of rebar, utility, and formwork installation in C7 and C8.	<image/>
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 14, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1- A4, and B1- B4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of rebar, utility, and formwork installation in C7 and C8.	
Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 15, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4. -Poured concrete in C5 and D5.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of rebar, utility, and formwork installation in C7 and C8.	<image/>
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 16, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors. -Continue formwork and rebar installation for Building C ninth through eleventh floors. -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6, C7, and C8.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 17, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors. -Continue formwork and rebar installation for Building C ninth through eleventh floors. -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6, C7, and D5.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	<image/>





Daily Report for July 20, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1-A4, B1-B4, C5-C8, and D5-D6.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of rebar, utility, and formwork installation in C6, C7, and D5.	<image/>
Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 21, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2- F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1-A4, B1-B4, C5-C8, and D5-D6.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of pouring concrete, rebar, utility, and formwork installation in C6, C7, and D5.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 22, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).


-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

Photo 1- View of rebar, utility, and formwork in C6-C8.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 23, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities







Daily Report for July 24, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1-A4, B1-B4, C5, C6, and D5.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.


-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of rebar, utility, and formwork in C6-C8.	<image/>
Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 27, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in C5-C8, and D5.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.	
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 28, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in C5-C8, and D5.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.	<image/>
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	<image/>





Daily Report for July 29, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.	<image/>
Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.	





Daily Report for July 30, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities







Daily Report for July 31, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.

-Brickwork in C3, C4, and D4.

-Poured concrete in A1-A4, and B1-B4 for Building C.

2. Locations of work and quantities of material imported and exported from the Site.

-No materials were exported from the site today.

-No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B twelfth through thirteenth floors.

-Continue formwork and rebar installation for Building C ninth through eleventh floors.

Photo 1- View of rebar, utility, and formwork in C6-C8.	
Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.	

