



Daily Report for August 3, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Poured concrete in C5-C8 for Building H.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- View of pouring concrete, rebar, utility, and formwork installation in A3, A4, B3, and B4.



Photo 3- View of rebar, utility, and formwork in D3, D4, E3, and E4.





Daily Report for August 4, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Poured concrete in C5-C8 for Building H.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.



Photo 3- View of rebar, utility, and formwork in D3, D4, E3, and E4.





Daily Report for August 5, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 for utilities installation.
- Brickwork in C3, C4, and D4.
- Poured concrete in C5-C8 for Building H.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of rebar, utility, and formwork in D3, D4, E3, and E4.





Daily Report for August 6, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of rebar, utility, and formwork in D3, D4, E3, and E4.





Daily Report for August 7, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C5-C8, and D5.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of rebar, utility, and formwork in D3, D4, E3, and E4.





Daily Report for August 10, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C5-C8, and D5.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of excavated area in A5 for utility installation.





Daily Report for August 11, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 and B5 for utilities installation.
- Installed filter fabric and stone in A5 and B5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- 3 loads of nonhazardous soil from grid F4(0-7) exported to the Posillico Facility in Farmingdale, New York.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of loading out of non-hazardous soil in B5.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of installed filter fabric and stone in A5 and B5 for utilities.





Daily Report for August 12, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 and B5 for utilities installation.
- Installed filter fabric and stone in A5 and B5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C ninth through eleventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of excavated area in A5 for utility installation.



Photo 3- View of installed filter fabric and stone in A5 and B5 for utilities.





Daily Report for August 13, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 and B5 for utilities installation.
- Installed filter fabric and stone in A5 and B5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of utility installation in A5.



Photo 3- View
of utility
installation in
B5.





Daily Report for August 14, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated soil in A5 and B5 for utilities installation.
- Installed filter fabric and stone in A5 and B5 for utilities installation.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- 9 loads of nonhazardous soil from grid F4 (0-7) were exported to the Posillico Facility in Farmingdale, New York.
- 2 loads of 3/8 inch gravel were imported to the site today from the Posillico Facility in Farmingdale, NY.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of utility installation in A5 and B5.



Photo 3- View of loading out truck with soil for export offsite.





Daily Report for August 18, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Poured concrete in C5-C8, and D5.
- Stockpiled clean fill in A5.
- Installed utilities in A5 and B5.
- Backfilled utilities with gravel in A5 and B5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of stockpiling clean fill.



Photo 3- View of rebar, utility, and formwork in A1-A4, and B1-B4.





Daily Report for August 19, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Poured concrete in C5-C8, and D5.
- Stockpiled clean fill in A5 and B5.
- Installed utilities in A5 and B5.
- Backfilled utilities with gravel in A5 and B5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- View of backfilling with clean fill in A5 and B5.



Photo 3- View of installing filter fabric and waterproofing membrane around utilities in A5 and B5.





Daily Report for August 20, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Poured concrete in C5-C8, and D5.
- Stockpiled clean fill in A5 and B5.
- Installed utilities in A5 and B5.
- Backfilled utilities with gravel in A5 and B5.
- Poured concrete in C5- C8, and D5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in D3, D4, E3, and E4.



Photo 2- View of backfilling with clean fill in A5 and B5.



Photo 3- View
of tamping
down clean fill
in A5.





Daily Report for August 21, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Installed utilities in A5 and B5.
- Backfilled utilities with gravel in A5 and B5.
- Poured concrete in C5- C8, and D5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- utility, and formwork in A3, A4, B3, and B4.



Photo 3- View
of backfilling
with clean fill in
A5.





Daily Report for August 24, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Installed utilities in A5 and B5.
- Backfilled utilities with gravel in A5 and B5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- Excavating in C5.



Photo 3- View
of backfilling
with clean fill in
A5.





Daily Report for August 25, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Installed utilities in A5 and B5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork in C6-C8.



Photo 2- Installing utilities in A5 and B5.



Photo 3- View of rebar, utility, and formwork in A3, A4, B3, and B4.





Daily Report for August 27, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Poured concrete in C5-C8, and D5 for Building H 10th floor.
- Excavated in A5, B5, and C5 to install utilities.
- Installed utilities in A5, B5, and C5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete, rebar, utility, and formwork in C6-C8.



Photo 2- View of installing utilities in A5, B5, and C5.



Photo 3- View
of excavating
clean fill in B5.





Daily Report for August 28, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2-F4.
- Installed utilities in A5, B5, and C5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of installing utilities in B5, and C5.



Photo 3- View
of installing
utilities in B5
and C5.





Daily Report for August 31, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- Installed utilities in A5, B5, and C5.
- Brickwork in C3, C4, and D4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of installing utilities in B5, and C5.



Photo 3- View
of installing
utilities in B5
and C5.

