

#### Daily Report for September 2, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Installed utilities in A5, B5, and C5.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.



Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 3, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.



Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 4, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.



Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 8, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by Thomas Brown of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.




Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.



Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 9, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by Thomas Brown of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.




Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 10, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Brickwork in C3, C4, and D4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by Thomas Brown of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of rebar, utility, and formwork installation in D3, D4, E3, and E4.



Photo 3- View of rebar, utility, and formwork installation in A3, A4, B3, and B4.





#### Daily Report for September 15, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Backfilling in A5, B5, and C5 with clean fill.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of backfilling A5, B5, and C5 with clean fill.



Photo 3- View of rebar, utility, and formwork installation in D4, D5, E4, and E5.





#### Daily Report for September 16, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of clean fill in A5.
- -Utility installation in A5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8.



Photo 2- View of utility installation in A5.

Photo 3- View of excavating clean fill in A5.





#### Daily Report for September 17, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

# 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in C5.
- -Backfilling and compacting clean fill in A5, B5, and D6-D8.
- -Poured concrete in C5-C8 and D5.
- -Utility installation in A5.

#### 2. Locations of work and quantities of material imported and exported from the Site.

- -No materials were exported from the site today.
- -6 loads of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of clean fill grading and compaction in D6-D8.



Photo 2- View of clean fill compaction in D6-D8.



Photo 3- View of excavating in A5.





#### Daily Report for September 18, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5 and B5.
- -Backfilling and compacting clean fill in B5, C7, and C8.
- -Utility installation in A5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -2 loads of nonhazardous soil from grid F4(0-7) were exported to the Posillico Facility in Farmingdale, NY.
- -9 loads (~225 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of loading out soil in B5. Photo 2- View of clean fill compaction in B5.

Photo 3- View of excavation and utility installation in A5.





#### Daily Report for September 21, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5.
- -Utility installation in A5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8. Photo 2- View of grading soil in A5 and B5.

Photo 3- View of excavation and utility installation in A5.





### Daily Report for September 22, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5.
- -Utility installation in A5.
- -Poured concrete in C5-C8 and D5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -9 loads (~225 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, utility, and formwork installation in C6-C8. Photo 2- View of excavation and utility installation in A5 and B5.

Photo 3- View of excavation and utility installation in A5.





### Daily Report for September 23, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in B4.
- -Utility installation in A5.
- -Backfilled and compacted soil in D6-D8.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -9 loads (~225 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of importing clean fill in D6-D8. Photo 2- View of backfilling in D6-D8.

Photo 3- View of excavation and utility installation in B4.





### Daily Report for September 24, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5, B4, and B5.
- -Utility installation in A5, B4, and B5.
- -Backfilled and compacted soil in B4, and D6-D8.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -9 loads (~225 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of importing clean fill in D6-D8.



Photo 2- View of excavating soil and utility installation in A5 and B5.

Photo 3- View of excavation and utility installation in B4.





### Daily Report for September 25, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

# 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.

- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5, B4, and B5.
- -Utility installation in A5, B4, and B5.
- -Backfilled and compacted soil in B4, and D6-D8.
- -Poured concrete in C5-C8 and D5.


## 2. Locations of work and quantities of material imported and exported from the Site.

- -No materials were exported from the site today.
- -9 loads (~225 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of importing clean fill in D6-D8. Photo 2- View of excavating soil and utility installation in A5 and B5. (1) (1) (1) (1)

Photo 3- View of pouring concrete in C6-C8 and D5.





### Daily Report for September 28, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5, B4, and B5.
- -Utility installation in A5, B4, and B5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of excavating soil in B5. Photo 2- View of excavating soil and utility installation in A5 and B5.

Photo 3- View of utility installation in B5.





### Daily Report for September 29, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5, B4, B5, and C1.
- -Utility installation in A5, B4, B5, and C1.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, formwork, and utility installation in C6-C8.



Photo 2- View of excavating soil and utility installation in A5 and B5.



Photo 3- View of utility installation in C1.





### Daily Report for September 30, 2020

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavation of soil in A5, B4, B5, and C1.
- -Utility installation in A5, B4, B5, and C1.
- -Poured concrete in C5-C8 and D5.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No materials were exported from the site today.
- -No materials were imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of rebar, formwork, and utility installation in C6-C8.






Photo 3- View of pouring concrete in C5-C8 and D5.

