



Daily Report for January 4, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in B1 and B2.
- Backfilling in D5 and E5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by Thomas Brown of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in D5 and E5.



Photo 2- View of excavation for utility installation in B1 and B2.



Photo 3- View
of utility
installation in
B1 and B2.





Daily Report for January 5, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in A5 and B5.
- Backfilling in B1 and B2.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating clean fill in A5 and B5.



Photo 2- View of backfilling with clean fill in B1 and B2.



Photo 3- View
of utility
installation in
B1 and B2.





Daily Report for January 6, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in A5 and C5.
- Graded soil in B1 and B2.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View
of excavating
clean fill in A5.



Photo 2- View
of graded clean
fill in B1 and
B2.



Photo 3- View
of utility
installation in
C5.





Daily Report for January 7, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in A5 and C5.
- Endpoint samples EP-91(7), EP-92(9), EP-93(9), and EP-94(9) were collected.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating clean fill in A5.



Photo 2- View of utility and formwork installation in A3, A4, B3, and B4.



Photo 3- View
of utility
installation in
C5.





Daily Report for January 8, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in C5, D5, and E5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating clean fill in D5.



Photo 2- View of utility and formwork installation in C5.



Photo 3- View
of grading
clean fill in E5.





Daily Report for January 11, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Backfilled in C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling in C8.



Photo 2- View of utility and formwork installation in C8.



Photo 3- View of formwork and utility installation in C6-C8.





Daily Report for January 12, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in A5 and C7.
- Poured concrete in B5, C5, and C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating in C7.



Photo 2- View of utility and formwork installation in C7.



Photo 3- View
of grading
clean fill in A5.





Daily Report for January 13, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in C7.
- Backfilled around utilities in C7.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating in C7.



Photo 2- View of utility work and backfilling in C7.



Photo 3- View of utility and formwork in A3, A4, B3, and B4.





Daily Report for January 14, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in C5.
- Utility installation in A5 and C5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating in C5.



Photo 2- View of utility work in A5.



Photo 3- View
of utility and
formwork in
C6-C8.





Daily Report for January 15, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in C7.
- Utility installation in A5 and C7.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavating in C7.



Photo 2- View of utility and formwork in A3, A4, B3, and B4.



Photo 3- View
of utility and
formwork in
C6-C8.





Daily Report for January 18, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavation in E5 and F5.
- Backfilled in E5 and F5.
- Utility installation in E5 and F5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of utility installation in E5 and F5.



Photo 2- View of backfilling and grading clean fill in E5 and F5.



Photo 3- View of utility and formwork in A3, A4, B3, and B4.





Daily Report for January 19, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.

2. Locations of work and quantities of material imported and exported from the Site.

-No material was exported from the site today.

-No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B.

-Continue formwork and rebar installation for Building C.

-Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of utility and formwork in C6-C8.



Photo 2- View of utility and formwork in D4, D5, E4, and E5.



Photo 3- View of utility and formwork in A3, A4, B3, and B4.





Daily Report for January 20, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.

2. Locations of work and quantities of material imported and exported from the Site.

-No material was exported from the site today.

-No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B.

-Continue formwork and rebar installation for Building C.

-Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of utility and formwork in C6-C8.



Photo 2- View of utility and formwork in D4, D5, E4, and E5.



Photo 3- View of utility and formwork in A3, A4, B3, and B4.





Daily Report for January 21, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

-Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.

2. Locations of work and quantities of material imported and exported from the Site.

-No material was exported from the site today.

-No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

-No complaints.

4. A summary of CAMP findings (air and dust readings).

-No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

-Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

-Continue formwork and rebar installation for Building B.

-Continue formwork and rebar installation for Building C.

-Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of utility and formwork in C7.



Photo 2- View of utility and formwork in A3, A4, B3, and B4.



Photo 3- View
of utility and
formwork in
C6-C8.





Daily Report for January 22, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated in C5, E5 and F5.
- Backfilled in C5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavation and utility installation in C5.



Photo 2- View of excavation and utility installation in E5 and F5.



Photo 3- View
of utility
installation in
D5.





Daily Report for January 25, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated in E5 and F5.
- Utility installation in E5 and F5.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- No material was imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of utility installation in C5.



Photo 2- View of excavation and utility installation in E5 and F5.



Photo 3- View
of utility
installation in
E5 and F5.





Daily Report for January 26, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated in B6, C5, C6, D5, E5, and F5.
- Utility installation in C5, D5, E5, and F5.
- Backfilled in B6, C5, C6, D5, E5, and F5.

2. Locations of work and quantities of material imported and exported from the Site.

- 20 loads of nonhazardous soil from grids B6 and C6 (0-7) were exported to the Posillico Facility in Farmingdale, NY
- 10 loads (~250 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavation in B6 and C6.



Photo 2- View of excavation and utility installation in E5 and F5.



Photo 3- View
of utility
installation in
E5 and F5.





Daily Report for January 27, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated in B5, B6, C5, and C6.
- Backfilled in B6, C5, C6, and C7.

2. Locations of work and quantities of material imported and exported from the Site.

- 24 loads of nonhazardous soil from grids B5, B6, C5, and C6 (0-7) were exported to the Posillico Facility in Farmingdale, NY
- 20 loads (~500 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavation in B6 and C6.



Photo 2- View of backfilling in C7.



Photo 3- View
of utility
installation in
C8.





Daily Report for January 28, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Excavated in B5, B6, C5, and C6.
- Backfilled in B6, C5, C6, and C7.

2. Locations of work and quantities of material imported and exported from the Site.

- 6 loads of nonhazardous soil from grids B5, B6, C5, and C6 (0-7) were exported to the Posillico Facility in Farmingdale, NY
- 21 loads (~525 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of excavation in B6 and C6.



Photo 2- View of backfilling in C6.



Photo 3- View
of backfilling in
C6.





Daily Report for January 29, 2021

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2-F4.
- Backfilled in B6, C5, C6, C7, and C8.
- Excavated in B1.

2. Locations of work and quantities of material imported and exported from the Site.

- No material was exported from the site today.
- 6 loads (~150 tons) of approved clean fill were imported to the site today from the P Park facility in Prospect Park, NJ.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B.
- Continue formwork and rebar installation for Building C.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfill compaction in C6 and C7.



Photo 2- View of grading in C7 and C8.



Photo 3- View
of backfilling in
B1.

