



Mr. Jesse Gallo Environmental Coordinator Central Hudson Gas & Electric Corporation 284 South Avenue Poughkeepsie, NY 12601

Re: Periodic Review Report | CH - Kingston Gas Works | NYSDEC

Site No. C356017 | Kingston, New York

File: 1126476.1940107697

#### Dear Mr. Gallo:

This Periodic Review Report (PRR) was prepared by Ramboll Americas Engineering Solutions, Inc. (Ramboll) at the request of Central Hudson Gas & Electric Corporation (Central Hudson) to document the status of the Engineering Controls (ECs) and Institutional Controls (ICs) established in accordance with the November 2017, updated November 2021, Site Management Plan (SMP) for the Kingston Former Manufactured Gas Plant (MGP) Site (New York State Department of Environmental Conservation (NYSDEC) Site Number: C356017) located in Kingston, New York, and to provide a summary of information generated during the reporting period for the site. The reporting period for this PRR is May 25, 2023 through May 25, 2024. The SMP addressed the means for implementing and periodically inspecting ECs/ICs required by the remedy for the site.

#### ECS/ICS at the Site Include

**Environmental Easement** – A series of ICs are required by the Decision Document in the form of an Environmental Easement to: (1) implement, maintain, and monitor Engineering Control Systems; (2) prevent future exposure to remaining contamination; and (3) limit the use and development of the site to commercial or industrial uses only. Adherence to these ICs on the site is required by the Environmental Easement and implemented under the SMP.

**Soil Cover** – Exposure to remaining MGP-related residuals at the site is managed by a cover system placed over the site. The cover system comprises a minimum of 12 inches of clean soil, asphalt pavement, or concrete slab over shallow excavations and within the gas exclusion area. In areas where *in-situ* solidification (ISS) was performed and MGP-residuals in the form of a monolith are present, the cover comprises a minimum of 48 inches of clean soil. Procedures for monitoring the system are included in Section 4.3 of the SMP. The SMP also addresses severe condition inspections if a severe condition, which may affect controls at the site, occurs.

**Sediment Cap** –Biota exposure to the remaining MGP-related residuals within the gas utility crossing in the Rondout Creek is managed by a composite

Date May 30, 2024

Ramboll 333 West Washington Street Syracuse, NY 13202 USA

T 315-956-6100 F 315-463-7554 https://ramboll.com



subaqueous cap. The composite cap comprises a nominal 6-inch-thick sand bedding layer, one layer of reactive core mat (RCM) with Organoclay $^{\text{TM}}$ , a 12-inch thick TRITON® marine mattress, and 6-inches of light stone fill. Procedures for monitoring the system are included in Section 4.4 of the SMP. The SMP also addresses severe condition inspections if a severe condition, which may affect controls at the site, occurs.

#### EC/IC Inspection Results and On-Going Non-Aqueous Phase Liquid (NAPL) Monitoring Summary

In accordance with the SMP, an annual site-wide inspection was conducted on April 16, 2024. The soil cover system inspection and sediment cap inspection activities were conducted concurrently with the annual site inspection. It was observed during the site-wide inspection that all ICs were in place and remain effective. A copy of the Engineering Controls Monitoring Checklist and photographs are included as Attachment 1 to this PRR.

As documented in Attachment 1, each of the ECs were in place performing properly, and remain effective. Potential settlement of the soil cover was identified in four areas of the Site. The areas were generally minor, ranging in depths between 2 and 7 inches. The soil cover is approximately 5 feet thick in the areas where minor settlement or rutting was observed. There is an area to the north where the cover is 1 foot thick. The location and details of each area are provided in Attachment 1. If settlement in the identified areas continue, corrective measures may be required.

Attachment 1 also includes the results of the bathymetric survey completed on April 16, 2024. Changes in elevation in comparison to the 2017 bathymetric survey within the limits of pipeline crossing cap range between approximately 2.5 inches of erosion and/or settlement, and 2.5 inches of sediment deposits. These ranges are within the thickness of the light stone fill, indicating that the cap remains in place. The Institutional and Engineering Controls Certification Form for the reporting period is included as Attachment 2.

The annual NAPL monitoring event was conducted on August 17, 2023. Measurable free product was not present in any of the wells. Results of the NAPL monitoring event are detailed in the August 2023 – Annual Monitoring Event Results report included as Exhibit 1.

#### Certification of ICS and ECS

For each institutional or engineering control identified for the site, I certify that all of the following statements are true:

- The inspection of the site to confirm the effectiveness of the institutional and engineering controls required by the remedial program was performed under my direction;
- The institutional control and/or engineering control employed at this site is unchanged from the date the control was put in place, or last approved by the Department;
- Nothing has occurred that would impair the ability of the control to protect the public health and environment;
- Nothing has occurred that would constitute a violation or failure to comply with any Site Management Plan for this control;



- Access to the site will continue to be provided to the Department to evaluate the remedy, including
  access to evaluate the continued maintenance of this control;
- If a financial assurance mechanism is required under the oversight document for the site, the mechanism remains valid and sufficient for the intended purpose under the document;
- Use of the site is compliant with the environmental easement;
- The engineering control systems are preforming as designed and are effective;
- To the best of my knowledge and belief, the work and conclusions described in this certification are
  in accordance with the requirements of the site remedial program [and generally accepted
  engineering practices]; and
- The information presented in this report is accurate and complete.

I certify that all information and statements in this certification form are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the penal Law. I, Stephen W. Anagnost, of Ramboll, 333 West Washington St Syracuse, NY, am certifying as Owner's/Remedial Party's Designated Site Representative for the site.

No. 068269	5/30/2024	10 06829 5
NYS Professional Engineer #	Date	Sig <del>nat</del> ure

Yours sincerely

Stephen W. Anagnost, PE

DIVISION MANAGER-2 071-E&H ENGINEERING RES

D 315-956-6259

steve.anagnost@ramboll.com

Enclosures: Attachment 1 - Engineering Controls Monitoring Checklist

Attachment 2 - Enclosure 2 Site Management Periodic Review Report Notice Institutional

and Engineering Controls Certification Form

Exhibit 1 - NAPL Monitoring



ATTACHMENT 1
ENGINEERING CONTROLS MONITORING CHECKLIST





Mr. Michael Squire New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway, 11<sup>th</sup> FI

Re: Annual Monitoring Event Results | CH - Kingston Gas Works |

NYSDEC Site No. C356017 | Kingston, New York

File: 12678.1940107697

#### Dear Mr. Squire:

This letter serves to document the annual inspection event conducted on April 16, 2024 at the Central Hudson Gas & Electric Corporation's former manufactured gas plant site located in Kingston, NY. In accordance with the 2015 Decision Document and the approved Site Management Plan (November 2017; updated in November 2021), the annual inspection included:

Date May 30, 2024

- · Site Wide Inspection
- Soil Cover System Inspection
- Sediment Cap System Inspection

The associated inspection forms are presented attached.

Yours sincerely

Stephen W. Anagnost, PE

DIVISION MANAGER-2 071-E&H ENGINEERING RES

D 315-956-6259

steve.anagnost@ramboll.com

Ramboll 333 West Washington Street Syracuse, NY 13202 USA

T 315-956-6100 F 315-463-7554 https://ramboll.com



Engineering Controls Monitoring Checklist - Soil Cover and Sediment Cap Site Management Plan Central Hudson Gas & Electric Corporation

Kingston Former MGP Site, Kingston, New York

Date Monitoring Performed: April 16, 2024 Weather: 68° F, Sunny

## Section I: Engineering Controls (to be completed in the field at the time of the monitoring. Use additional space if necessary).

The site engineering controls consist of a soil cover and a sediment cap. The engineering controls will be

monitored to verify their integrity and to identify areas that may require maintenance.

	Observation	Yes	No	N/A	Comments
1.	Are there any eroded areas or areas of scour? If yes, describe.		X		No areas of erosion or scour observed within limits of the soil cover or sediment cap
2.	Are there any areas of settlement? If yes, describe.	X			The soil cover remains in place. There are a few areas of minor settlement noted throughout. Refer to the attached photolog.
3.	Is there any ponded water on the ground surface? If yes, describe.		X		
4.	Are there any areas of accumulated large debris or obstructions (e.g., logs, railroad ties, etc.)? If yes, describe type and location		X		
5.	Scour or holes within the limits of sheeting over sediment cap based on bathymetric survey? If yes, describe.		X		See bathymetric survey, bathymetric comparison (Figure 1), and additional information
6.	Is the RCM of the sediment cap exposed within the limits of sheeting based on diver survey (if necessary)?			X	
7.	Are photographs attached? If yes, list photograph numbers and provide description in Section II.	X			Please refer to Section II and the attached Photo Log
8.	Are the Site records complete and up to date, and stored at the CHGE office?	X			Records located at 284 South Avenue Poughkeepsie, NY 12601 and the Environmental Easement is recorded with the Ulster County Clerk.

Additional Information: Describe any other relevant observations noted during this monitoring event.



Soil Cover: The soil/stone cover remains intact but there are areas of noted settlement as shown in photos 2,5, 6, 8, 9, and 11 through 13. The noted settlements are generally less than 7 inches deep. Areas of vegetative cover show established vegetation (Photo 14). Areas of asphalt or concrete show no signs of deterioration (Photo 15). The settlement will continue to be monitored and if required, corrective actions will be implemented.

Sediment Cap: Based on the results of the bathymetric survey completed on April 16, 2024, changes in elevation in comparison to the 2017 bathymetric survey within the limits of pipeline crossing cap range between approximately 2.5 inches of erosion and/or settlement, and 2.5 inches of sediment deposits. These ranges are within the thickness of the light stone fill, signaling that the cap remains in place. The bathymetric survey and bathymetric comparison (Figure 1) are attached.

Photograph	Date	Attach photographs if applicable. Use additional pages as necessary)  Photograph Description	Direction Facing	
1	4/16/24	Bulkhead on south boundary of Site. Signs of settlement or rutting noted in minimal areas	West	
2	4/16/24	Area of noted settlement along the bulkhead on south boundary of Site.	South	
3	4/16/24	Bulkhead on south boundary of Site.	East	
4	4/16/24	Vessels moored adjacent to Site on Rondout Creek limiting extents of bathymetric survey.	West	
5	4/16/24	Limits of minor settlement at southeast portion of the Site between bulkhead and fence line.	West	
6	4/16/24	Photo showing approximately 5 inches of settlement within southeast portion of the Site between the bulkhead and fence line.	West	
7	4/16/24	Cover within exclusion zone	Southwest	
8	4/16/24	Limits of previously noted settlement at southeast portion of Site within the fence line.	East	
9	4/16/24	Photo showing approximately 4 inches of settlement at southeast portion of the Site within fence line.	East	
10	4/16/24	View of the cover system from northwest corner.	Southeast	
11	4/16/24	Northside of Site, just west of exclusion zone where some minor depressions/settlement is noted.	North	
12	4/16/24	Area of minor settlement at north side of Site.	North	
13	4/16/24	Photo showing up to 3 inches of settlement at north side of Site.	North	
14	4/16/24	Soil cover on property west of Central Hudson Property.	West	
15	4/16/24	Soil cover east of the Central Hudson property.	North	
16	4/16/24	Northern boundary of the Site,	West	



17	4/16/24	Site plan showing a	pproximate location of noted settlement.	N/A
Section III. A	dditional Field	l Observations		
Section IV. Co				
			noted above, the monitoring was performed	
			Manufactured Gas Plant Site, Kingston, New	
November 201	17, and that the	above information is	true and correct to the best of my knowledge.	
N. C.	D 17: 1 147		mul D : M	
	d) Victor Warne	er	Title: Project Manager	
-	e with a	J	7 (00 (0)	
Signature:			Date: 5/30/24	

## ENVIRONMENT & HEALTH

CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|19401076


**РНОТО NO.** 

DATE:

4/16/2024

#### **DESCRIPTION**

Bulkhead on south boundary of site. Signs of settlement noted in minimal areas.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Area of noted settlement along the Bulkhead on south boundary of site.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107

**РНОТО NO.** 

DATE:

4/16/2024

#### **DESCRIPTION**

Bulkhead on south boundary of Site facing east.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

**SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Vessels moored adjacent to site on Rondout Creek limiting extents of bathymetric survey.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

**SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Limits of minor settlement at southeast portion of the site between the bulkhead and fence line.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

**SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Photo showing approximately 5 inches of settlement within southeast portion of the site between the bulkhead and fence line.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Cover within exclusion zone.

Photo taken in northeast corner
of Central Hudson Property
facing southwest.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

**SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Limits of settlement at southeast portion of the Site within the fence line. This area has been noted previously since 2022. The limits and depth do not appear to have expanded.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Photo showing approximately 4 inches of settlement at southeast portion of the Site within the fence line.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|19401076

97

**PHOTO NO.** 10

DATE:

4/16/2024

#### **DESCRIPTION**

View of site from northwest corner showing a majority of the cover system. Site is currently being used as a laydown area for off-site natural gas line installation.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|19401076 97


PHOTO NO.

11

**DATE:** 4/16/2024

#### **DESCRIPTION**

View of northside of the Site, just west of the exclusion zone where some minor depression/settlement is noted. Expected that the area was utilized for storing materials and/or equipment.



<b>CLIENT NAME:</b> CENTRAL
HUDSON GAS & FLECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO. 12

4/16/2024

DATE:

#### **DESCRIPTION**

Area of minor settlement at north side of the Site.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|19401076 97

PHOTO NO.

13

**DATE:** 4/16/2024

#### **DESCRIPTION**

Photo showing approximately 3 inches of settlement at north side of the Site.



**CLIENT NAME:** CENTRAL **HUDSON GAS & ELECTRIC**  SITE LOCATION: FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|19401076 97

PHOTO NO.

DATE:

4/16/2024

#### **DESCRIPTION**

Soil cover on property west of Central Hudson Property. Photo taken from west side of Central Hudson Property facing west.



**CLIENT NAME:** CENTRAL **HUDSON GAS & ELECTRIC**  **SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

**РНОТО NO.** 15

DATE:

4/16/2024

#### **DESCRIPTION**

Soil cover east of the Central Hudson property. Photo taken east of property facing north.



CLIENT NAME: CENTRAL HUDSON GAS & ELECTRIC

**SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107

**PHOTO NO.** 16

**DATE:** 4/16/2024

#### **DESCRIPTION**

Northern boundary of Site. Photo taken in northeast corner of site facing west.





**CLIENT NAME:** CENTRAL **HUDSON GAS & ELECTRIC**  **SITE LOCATION:** FORMER KINGSTON MGP SITE

PROJECT NO.

1126476|1940107 697

PHOTO NO. 17


DATE:

4/16/2024

#### **DESCRIPTION**

Location plan of noted settlement.







ATTACHMENT 2
ENCLOSURE 2 SITE MANAGEMENT PERIODIC REVIEW REPORT NOTICE
INSTITUTINAL AND ENGINEERING CONTROLS CERTIFICATION FORM



# Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Sit	e No.	Site Details e No. C356017			Box 1	
Sit	e Name	CH - Kingston Gas	Works			
Cit Co	y/Town: unty: Uls	ss: North Street Kingston ster ge: 1.610	Zip Code: 12401			
		Period: May 25, 2023	to May 25, 2024			
	. 3	<b>,</b> -,			YES	NO
1.	Is the i	nformation above corr	ect?		X	
	If NO, i	include handwritten ab	pove or on a separate sheet.			
2.		•	operty been sold, subdivided, merged, or undergone a his Reporting Period?		X	
3.		ere been any change NYCRR 375-1.11(d))?	of use at the site during this Reporting Period			XI
4.			or local permits (e.g., building, discharge) been issued his Reporting Period?		X	
			estions 2 thru 4, include documentation or evidence en previously submitted with this certification form.			
5.	Is the s	site currently undergoi	ng development?			<b>X</b>
					Box 2	
					YES	NO
6.		current site use consis ercial and Industrial	tent with the use(s) listed below?		<b>X</b> i	
7.	Are all	ICs in place and funct	ioning as designed?	X		
	IF		THER QUESTION 6 OR 7 IS NO, sign and date below and ETHE REST OF THIS FORM. Otherwise continue.	t		
Corre	ective Mo	easures Work Plan mu	ust be submitted along with this form to address these	issu	es.	
Sig	inature of	f Owner Remedial Part	y or Designated Representative Date			
Oig	ji latare o	. Owner, Remodian Fall	y or boolynated representative Date			

#### **SITE NO. C356017**

#### **Description of Institutional Controls**

Parcel

Owner

Institutional Control

56.36-01-18

Central Hudson Gas & Electric Corp

Ground Water Use Restriction Soil Management Plan Landuse Restriction Monitoring Plan

Site Management Plan

IC/EC Plan

The property may be used for Commercial uses as described in 6 NYCRR Part 375.1(g)(2)(iii) or Industrial uses as described in 6 NYCRR Part 375.1.8(g)(2)(iv);

The use of groundwater underlying the property is prohibited without necessary water quality treatment as determined by the NYSDOH or the Ulster County Department of Health to render it safe for use as drinking water for industrial purposes, and the user must first notify and obtain written approval to do so from the Department;

Monitoring must be performed as defined in the SMP; and

All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with the SMP.

#### **Description of Engineering Controls**

Parcel

**Engineering Control** 

56.36-01-18

Subsurface Barriers Monitoring Wells Cover System

Exposure to remaining contamination at the site is prevented by a cover system placed over the site. The cover system is comprised of a minimum of one foot of clean soil, asphalt pavement, gravel, or concrete slab. In areas where ISS was performed the cover system is comprised of a minimum of 4 feet of clean soil.

Exposure to remaining MGP-related residuals by biota within the Rondout Creek is managed by a composite subaqueous cap. The composite cap is comprised of a nominal 6-inch thick sand bedding layer, one layer of RCM with Organoclay<sup>™</sup>,, and a 12-inch thick TRITON® marine mattress.

Exposure to remaining sediment contamination within the Rondout Creek is prevented by a composite subaqueous cap. The composite cap consists of a nominal 6-inch thick sand bedding layer, one layer of RCM with Organoclay, and a 12-inch thick TRITON marine mattress.

Exposure to remaining MGP-related residuals by biota within the Rondout Creek is managed by a composite subaqueous cap. The composite cap is comprised of a nominal 6-inch thick sand bedding layer, one layer of RCM with Organoclay, an da 12-inch thick TRITON marine mattress.

Periodic Review Report (PRR) Certification Statements		
I certify by checking "YES" below that:		
<ul> <li>a) the Periodic Review report and all attachments were prepared under the direction reviewed by, the party making the Engineering Control certification;</li> </ul>	n of, and	I
b) to the best of my knowledge and belief, the work and conclusions described in the		
are in accordance with the requirements of the site remedial program, and generally	YES	d NO
	<b>X</b> i	
<ol><li>For each Engineering control listed in Box 4, I certify by checking "YES" below that all of following statements are true:</li></ol>	the	
(a) The Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;		
(b) nothing has occurred that would impair the ability of such Control, to protect public healt the environment;	h and	
(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;		
(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and		
(e) if a financial assurance mechanism is required by the oversight document for the site, th and sufficient for its intended purpose established in the document.	e mecha	ınism remains valio
	YES	NO
	X	
IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.		
A Corrective Measures Work Plan must be submitted along with this form to address these	issues.	
Signature of Owner, Remedial Party or Designated Representative Date		-

#### IC CERTIFICATIONS SITE NO. C356017

Box 6

#### SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal aw.

Mark L. McLean	at	Central Hudson Gas & Electric Corp. 284 South Avenue, Poughkeepsie, NY 12601
print name		print business address
am certifying as	Owner	(Owner or Remedial Party)
for the Site named in the Site Signature of Owner, Remedi Rendering Certification	1/6	5/29/24

#### **EC CERTIFICATIONS**

Box 7

#### **Qualified Environmental Professional Signature**

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

at Ramboll, 333 West Washington Street, Syracuse, NY 13221 Stephen Anagnost print business address print name Owner am certifying as a Qualified Environmental Professional for the \_ (Owner or Remedial Party)

Signature of Qualified Environmental Professional, for the Owner or Remedial Party, Rendering Certification

5/30/2024

(Required for PE)

Date



EXIHIBIT 1
2023 NAPL MONITORING REPORT



Submitted via email

August 18, 2023

John Spellman New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway, 11<sup>th</sup> Floor Albany, NY 12233-7014

Re: Kingston MGP Site (C356017)

<u>August 2023 – Annual Monitoring Event Results</u>

Dear Mr. Spellman:

This letter serves to document the results of the annual monitoring event conducted on August 17, 2023 at Central Hudson Gas & Electric Corporation's (Central Hudson's) former manufactured gas plant (MGP) site located in Kingston, NY (Figure 1). In accordance with the June 2015 Decision Document, and approved November 2017 Site Management Plan (SMP) [revised in 2021], four monitoring wells were installed at the site to monitor for the presence of non-aqueous phase liquid (NAPL). The monitoring wells were installed within an area that was precluded from in-situ stabilization (ISS) remediation due to the location of active gas infrastructure.

#### **Results**

Depth to water ranged from 4.27 feet below top of casing (fbtoc) to 4.65 fbtoc in monitoring wells RW-2 and RW-1/RW-4, respectively (Table 1). A heavy sheen was observed in RW-1 (approximately 0.10') and a light sheen was observed on the probe tip when gauging RW-2; however, NAPL thickness was not measurable.

The next monitoring event is tentatively scheduled to be performed in August 2024. Please contact me at (845) 486-5641 or <a href="mailto:igallo@cenhud.com">igallo@cenhud.com</a> if you have any questions.

Sincerely

Jessé N. Gallo

**Environmental Coordinator** 

Attachments

ec. Amen Omorogbe – NYSDEC Kristin Kulow – NYSDOH Mark McLean, Central Hudson



#### Table 1 Monitoring Well Gauging Data August 2023

Well ID	DTW	DTP	DTB
RW-1	4.65	0.1*	20.53
RW-2	4.27	Trace*	18.31
RW-3	4.45	ND	21.61
RW-4	4.65	ND	20.72

#### Notes:


\* - Sheen observed on probe tip

DTW - Depth to water (feet below top of casing)
DTP - Depth to product (feet below top of casing)

DTB - Depth to bottom (feet below top of casing)

ND - Not detected





RECOVERY WELL LOCATION PLAN

PLAN SUPERSEDED
REFER TO NMB LAND SURVEYING
POST CONSTRUCTION
SHEET 1 OF 1
DATED 6/27/17

RECOVERY WELL TABLE					
WELL ID	NORTHING	EASTING	GRADE ELEVATION (FEET)	TOP OF CASING ELEVATION (FEET)	DEPTH OF WELL (FEET BGS)
RW-1	1125862.194	636244.317	6.5	8.6	19
RW-2	1125866.377	636283.183	6.1	8.0	18
RW-3	1125904.711	636381.694	5.7	7.9	19
RW-4	1125796.653	636373.703	5.3	7.6	19



GRAVEL AREA

VEGETATED SURFACE

RECOVERY WELL LOCATION

RW-01

THIS DRAWING WAS PREPARED AT THE SCALE INDICATED IN THE TITLE BLOCK. INACCURACIES IN THE STATED SCALE MAY BE INTROJUCED WHEN DRAWINGS ARE REPRODUCED BY ANY MEANS. USE THE GRAPHIC SCALE BAR IN THE TITLE BLOCK TO DETERMINE THE ACTUAL SCALE OF THIS DRAWING.

IT IS A VIOLATION OF LAW FOR ANY PERSON, UNLESS ACTING UNDER THE DIRECTION OF A LICENSED ENGI-NEER, TO ALTER THIS DOCUMENT.



)	11/2/17	RECORD DRAWING	BEW			
ο.	DATE	REVISION	INIT.			

SCALE AS NOTED



O'BRIEN & GERE ENGINEERS, INC



CENTRAL HUDSON GAS & ELECTRIC FORMER KINGSTON MGP SITE SITE NO. C356017 KINGSTON, NEW YORK

## RECOVERY WELL LOCATION PLAN

	FILE NO.	Ī
CHARGE OF	12678.62871.126	
SIGNED BY CHECKED BY		
SIGNED BY CHECKED BY	DATE	
AWN BY	NOV. 2017	