



## MONTHLY STATUS REPORT

Prepared By: Trevor Treglia

WEATHER	Snow		Rain		Overcast		Partly Cloudy	x	Bright Sun	
TEMP.	< 32		32-50		50-70		70-85		>85	x

BCP No.:	C546047	PVE Project No.:	561231	Date:	4/28/2021
Project Name:	42 Gates Avenue, Village of Victory, Saratoga County, NY				

Consultant: PVE	Consultant On-Site: Trevor Treglia
General Contractor: N/A	General Contractor Contact: N/A

### Work Activities Performed:

PVE was retained by Victory Mills LLC (the Volunteer) for the ongoing investigation and remediation activities in accordance with the NYSDEC BCP requirements.

### Site Activities:

- No excavation activities were undertaken during the month of April.
- No field activities were undertaken during the month of April.
- On site structures continue to deteriorate within the BCP boundary.

### Waste Disposal:

- No waste disposal was undertaken during site activities.

### Problems Encountered:

- Moderate deterioration of on-site structures.

### Planned Activities for Next Month:

- Next BCP inspection scheduled for May 2021.

#### **PA Corporate**

Waterfront Corporate Park III  
 Suite 101  
 2000 Georgetowne Drive  
 Sewickley, PA 15143  
 724.444.1100

#### **New York City**

25 West 39<sup>th</sup> Street  
 12<sup>th</sup> Floor  
 New York, NY 10018  
 646.602.4999

#### **California**

535 Mission Street  
 14<sup>th</sup> Floor  
 San Francisco, CA 94105  
 628-243-6445

#### **Ohio**

1156 E. State Street  
 Salem, OH 44460  
 330.332.5200

#### **Texas**

3250 Briarpark Drive  
 Suite 140  
 Houston, TX 77042  
 713.375.1400



BCP Boundary Map



**Photo Log**

Photo 1 –

Overview of BCP Site.



Photo 2 –

View of northwestern side of main structure.





Photo 3 –

Interior of main structure.



Photo 4 –

View of northern side of main structure.





Photo 5 –

View of northern wooded area.



Photo 6 –

View of eastern side of main structure.





Photo 7 –

Typical view of adjoining stream along eastern side of BCP Area.



Photo 8 –

View of southern side of main structure.





Photo 9 –

Typical view of southern grassed area.



Photo 10 –

Typical interior view of main structure.





Photo 11 –

Typical basement view of main structure.

