



MONTHLY STATUS REPORT

Prepared By: Trevor Treglia

WEATHER	Snow		Rain		Overcast		Partly Cloudy	x	Bright Sun	
TEMP.	< 32		32-50	x	50-70		70-85		>85	

BCP No.:	C546047	PVE Project No.:	561231	Date:	11/24/2021
Project Name:	42 Gates Avenue, Village of Victory, Saratoga County, NY				

Consultant: PVE	Consultant On-Site: Trevor Treglia
General Contractor: N/A	General Contractor Contact: N/A

Work Activities Performed:

PVE was retained by Victory Mills LLC (the Volunteer) for the ongoing investigation and remediation activities in accordance with the NYSDEC BCP requirements.

Site Activities:

- No excavation activities were undertaken during the month of November.
- No field activities were undertaken during the month of November.
- On site structures continue to deteriorate within the BCP boundary.

Waste Disposal:

- No waste disposal was undertaken during site activities.

Problems Encountered:

- Moderate deterioration of on-site structures.

Planned Activities for Next Month:

- Next BCP inspection scheduled for December 2021.

PA Corporate

Waterfront Corporate Park III
 Suite 101
 2000 Georgetown Drive
 Sewickley, PA 15143
 724.444.1100

New York City

25 West 39th Street
 12th Floor
 New York, NY 10018
 646.602.4999

California

535 Mission Street
 14th Floor
 San Francisco, CA 94105
 628-243-6445

Ohio

1156 E. State Street
 Salem, OH 44460
 330.332.5200

Texas

3250 Briarpark Drive
 Suite 140
 Houston, TX 77042
 713.375.1400



BCP Boundary Map



Photo Log

Photo 1 –

Overview of BCP Site from
the west/southwest.



Photo 2 –

View of northwestern side of
main structure.



Photo 3 –

Main garage structure has been locked and secured.



Photo 4 –

View of northern side of main structure.



Photo 5 –

View of the entrance to the northern wooded area.



Photo 6 –

View of eastern side of main structure.



Photo 7 –

Typical view of adjoining stream along eastern side of BCP Area.



Photo 8 –

View of southern side of main structure.



Photo 9 –

Typical view of southern grassed area.



Photo 10 –

Typical interior view of main structure.



Photo 11 –

Typical basement view of
main structure.

