

December 10, 2009

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **November 2009 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during November 2009 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

There were no Remedial Investigation (RI) field activities in November. DuPont has repaired the breaches in the perimeter fencing that were noted in the field inspection reports. The revised RI report, which will include the second round groundwater and metals delineation soil results, is scheduled to be submitted to the New York State Department of Environmental Conservation (NYSDEC) in late 2009.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. Site inspection reports from inspections completed in November are attached.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,

PARSONS



Jeffrey S. Poulsen
Project Manager

Attachment: Site Inspection Forms(2)

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Comerford, NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carol Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 445424 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 11/17/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: breeches remain at end of Valcon St by tree
- c) **Slatted Fencing Condition:** Remarks: one section still down
- d) **Vegetative Overgrowth–** Remarks: N/A at this time

X 2) **Site Status**

- a) **Debris –** No debris at this time
- b) **Surface Staining –** Remarks: no stains at this time
- c) **Storm Drains –** Remarks: semi clear and functioning
- d) **Monitoring Wells –** Remarks: monitoring wells check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: pavement condition check fair and clear

X 3) **Other –** Fabric repair not completed but is in to be fixed – same with slatted fence section –looking at repair being 2 weeks out, with next week being a short week, looking at it being the first or second week of December. Shall we create temporary fix? Please respond and let us know.

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 11/30/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: breaches under repair to day 11/30/09
- c) **Slatted Fencing Condition:** Remarks: was repaired today
- d) **Vegetative Overgrowth–** Remarks: N/A at this time

X 2) **Site Status**

- a) **Debris –** No debris at this time
- b) **Surface Staining –** Remarks: no stains at this time
- c) **Storm Drains –** Remarks: semi obstructed and functioning
- d) **Monitoring Wells –** Remarks: monitoring wells check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: pavement condition check fair

X3) Other – North gate has leaves accumulating over storm grating. Repairs were made to fencing, pictures to be taken showing repair was made at next visit to site.

REQUIRED MAINTENANCE ACTIVITIES:
