



SITE INSPECTION REPORT

Site Name: 211 Franklin Street

Site Number: C905038

Location: 211 Franklin Street, Olean, NY 14760

Inspection Date: June 5, 2026

Site Project Manager: Brad Demo

Personnel Onsite: N/A (only inspected building exterior on this date).

Weather Conditions: AM: Sunny, warm.

Description of Work Performed: NYSDEC conducting routine site exterior inspection.

- Site cover in acceptable condition although some ruts in the driveway along the south side of the facility require monitoring.
- Electric vehicle chargers have been installed on the northern side of the facility. A battery pad was not observed as previously described during the last site inspection.
- Excess imported soil (previously approved) stockpile remains covered on southern side of the facility.

Inspector: Bradley Demo

Signature:

Site Inspection Report

211 Franklin Street

June 5, 2026

Page 2

Photolog:



Covered excess imported backfill material stockpile on southwestern portion of facility. Material import request was previously approved.

Site Inspection Report

211 Franklin Street

June 5, 2026

Page 3



Site/cover conditions facing north.

Site Inspection Report

211 Franklin Street

June 5, 2026

Page 4



Stockpile of pea gravel for driveway repairs.

Site Inspection Report

211 Franklin Street

June 5, 2026

Page 5



Site/cover conditions west side of facility facing north. Active work was observed to be occurring on the roof on this date.