

INDEPENDENT ENVIRONMENTAL

ENGINEERS, SCIENTISTS

AND CONSULTANTS

report (915175. Zoo 7-01-03, 2006 Ammel Trapection Report Malcolm Pirnie, Inc

50 Fountain Plaza

Suite 600

Buffalo, NY 14202

T: 716-667-0900

F: 716-667-0279

www.pirnie.com

RECEIVED

JAN 0 3 2007

NYSDEC REG 9

YREL UNREL

December 28, 2006

Mr. David S. Szymanski Environmental Engineering Technician III New York State Department of Environmental Conservation 270 Michigan Ave. Buffalo, New York 14203-2999

Re:

2006 Annual Inspection Report

CertainTeed Site (Site # C915185) Buffalo, New York

Dear Mr. Szymanski:

On behalf of the Krog Corp., Malcolm Pirnie, Inc. (Pirnie) hereby submits the attached Environmental Inspection Form with attachments for the above captioned site. As discussed during the site meeting of November 17, 2006, this will serve as the first annual inspection for the site as required in the Operations, Maintenance, and Monitoring Work Plan (OMMWP) for this Brownfield Cleanup Program (BCP) Site. Attached to this letter are the following pertinent items:

- **Environmental Inspection Form**
- Site Map identifying areas in need of attention
- Photos of areas in need of attention

As you are aware, the establishment of complete grass cover was hampered by the unusually wet growing season in 2006. The site was reseeded using a slit seeder which resulted in significant improvement to the grass cover. However, a few areas of sparse grass cover remain. Also, where trucks cut corners at pavement turns, grass cover is impacted. These areas have been identified and documented on the attached EIF and will be addressed in 2007.

Thank you for your cooperation and patience as we work to comply with the BCP requirements.

Very truly yours,

MALCOLM PIRNIE, INC.

Kent R. McManus, PE

Senior Associate

Board Certified Environmental Engineer

cc:

Pat Sheedy (Krog)

Rob Wenrich (Ship Certain) Dave Locey (NYSDEC) Jim Richert (Pirnie)

Enclosures

f/3198004.technical.certannualinsp.2006

ENVIRONMENTAL INSPECTION FORM

CertainTeed Site (Portions of Parcels 1 and 2 of Hanna Furnace)

Property Name: <u>CERTAINTEED SITE</u>	Inspection Dat	e: <u>November 17,</u>	2006
Property Address: 231 Ship Canal Parkway			
City: <u>Buffalo</u> State: <u>New York</u> Zip Code: <u>14218</u>			
Property ID: (Tax Assessment Map)			
Section: <u>132.20</u> Block: <u>1</u> Lot(s): <u>11</u>			
Total Acreage: 25 Acres			
Weather (during inspection): Temperature: 40° Condithe west - 20 mph.	itions: <u>Cloudy, with n</u>	o precipitation. V	Vinds from
SIGNATURE:			
The findings of this inspection were discussed with apprand implementation was mutually agreed upon:	opriate personnel, co	orrective actions w	vere identified
Inspector:			Date:
Next Scheduled Inspection Date: <u>April, 2007</u>			
INDOOR	<u>AREAS</u>		
		Yes	No
1. Are there settled of uneven areas?	NA		
2. Are there indications of seepage or flooding?			
SECURITY AN	ID ACCESS		
		Yes	No
3. Access controlled by perimeter fencing?			NA_
Are there sections of the fence material damage	d or missing?		
Are the fence or gate post foundations structura	lly sound?		
4. "No Trespass" signs posted in appropriate languages	P		_NA
Are the signs securely attached to the fencing or	· posts?		
Are there sufficient signs; are the signs adequate	ely spaced		
around the perimeter of the property?			
5. Is there evidence of trespassing?			_ X
Is there evidence of illegal dumping?			X


COVER & VEGETATION

	Yes	No
6. Final cover in acceptable condition?		X
Is there evidence of sloughing, crosion, ponding or settlement?	X	
Is there evidence of unintended traffic; rutting?	<u>X</u>	
Is there evidence of distressed vegetation/turf?		X
7. Final cover sufficiently covers soil/fill material?		_ <u>X</u>
Are there cracks visible in the soil or pavement?		<u>X</u>
Is there evidence of erosion in the stormwater channels or swales?		<u>NA</u>
Is there damage to the synthetic erosion control fabric in the		
channels or swales?		<u>NA</u>
ACTIVITY ON SITE		
ACTIVITION SITE		
8. Any activity on site that mechanically disturbed soil cover?		
ADDITIONAL FACILITY INFORMATION		
Development on or near the site? (Specify size and type: e.g., residential, 40 acr	res, well and so	eptic)
<u>COMMENTS</u>		
<u>Item #</u>		
1) Sparse grass cover on eastern site berm - See photo #2.		
2) Sparse grass cover and related soil erosion on south side of west entrance to see photos #4 and #6.	rear materials	storage yard -
3) Grass cover impacted by truck traffic at turns in pavement - see photos #1, #	‡3 and #5.	
Mitigation of these items is anticipated in late spring of 2007.		
-		

ATTACHMENTS

1. Site Sketch

2. Photographs



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Location:

Project No.

Date:

Certainteed Site

3198-004

Photo No.

11/17/06

Direction Photo Taken:

South

Description:

East entrance to storage yard.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Location:

Project No.

Certainteed Site

3198-004

Photo No.

Date:

2 11/17/06 Direction Photo Taken:

Northwest

Description:

East berm.





PHOTOGRAPHIC LOG

Project:

Location:

Certainteed Site

Project No.

Date:

3198-004

Photo No.

11/17/06

Direction Photo Taken:

South

Description:

East side of plant.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Location:

Project No.

Photo No.

Date: 11/17/06

Direction Photo Taken:

East

Description:

South side of West entrance to storage yard.



PHOTOGRAPHIC LOG

Project:

Location:

Project No.

Date:

Certainteed Site

3198-004

Photo No. 11/17/06 5

Direction Photo Taken:

Northeast

Description:

West entrance to Storage yard.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Location:

Project No.

Certainteed Site

3198-004

Photo No.

Date: 11/17/06

Direction Photo Taken:

Southeast

Description:

West Side of storage yard.





December 28, 2006

RECEIVED

JAN 0 3 2007

NYSDEC REG 9 FOIL REL UNREL Malcolm Pirnie, Inc.

50 Fountain Plaza Suite 600

Buffalo, NY 14202 T: 716-667-0900

F: 716-667-0279 www.pirnie.com

Mr. David Locey New York State Department of Environmental Conservation Division of Environmental Remediation, Region 9 270 Michigan Avenue Buffalo, NY 14203-2999

Re:

Summary of Site Visit/Inspection

Cobey, LLC Site – Buffalo Lakeside Commerce Park Site (Site #C915202)

Dear Mr. Locey:

On behalf of the Krog Corp., Malcolm Pirnie Inc., (Malcolm Pirnie) has prepared this summary of our meeting/site visit with took place on November 17, 2006 at the above captioned site. Present at the meeting were:

NYSDEC representatives:

Dave Locey and Dave Szymanski

Krog Corp representative:

Andy Metzger Iim Richert

Pirnie representative:

The purpose of our meeting was to observe the condition of the site cover system, in particular the grass cover for compliance to the Operations, Maintenance, and Monitoring Work Plan (OMMWP) for the site in relation to issuance of the Certificate of Completion. As documented in the Remedial Action Report (RAR) and discussed during our meeting, all required cover layers (concrete, blacktop, and clean soil) have been placed per the Remedial Work Plan. The soil cover layer was placed, graded, and seeded in stages as work progressed. Due to record precipitation during the late summer and early fall, three areas that were seeded near the end of the project have not yet achieved the desired level of grass cover and probably will not until the next growing season. These areas include:

- At the western end of the site near were the field trailer was located
- North of and adjacent to the manufacturing building where planting of ornamental trees was completed.
- To the east of the eastern paved lot.

Attached to this letter are photographs of these three areas.

Completion of the grass cover will occur as soon as growing conditions allow next spring.

If you have questions or require further information please contact me at 667-6654.

Very truly yours,

MALCOLM PIRNIE, INC.

James J. Richert CPG

Sr. Project Hydrogeologist

cc:

D. Szymanski (NYSDEC)

P. Sheedy (Krog Corp)

K. McManus (Pirnie)

File: CC

f/3198-005.122806.nysdec.cobey 111706sitevisitltr.

MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project: Site visit of 11/17/06

Location: Cobey.LLC site

Project No. 3198-005

Photo No.

Date:

0009 11/17/06 Direction Photo Taken:

East

Description:

East end of Eastern paved lot.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project: Site visit of 11/17/06

Location: Cobey.LLC site

Project No.

Photo No.


Date:

0010 11/17/06 Direction Photo Taken:

West

Description:

Area between Northern wall of building and main parking lot.



MALCOLM PIRNIE		PHOTOGRAPHIC LOC		
Project: Site visit of 11/	7/06 L	ocation: Cobey.LLC site	Project No. 3198-005	
Photo No. Date: 0012 11/17/06 Direction Photo Taken North	The State of the State of the	Attack of the section		
Description: Area North of Western facility entrance.				

MALCOLM PIRNIE	PHOTOGRAPHIC LOG	
Project:	Location:	Project No.
Photo No. Date:		
Direction Photo Taken:		
Description:		