

Proactive by Design



# 2021 PERIODIC REVIEW REPORT BUFFALO LAKESIDE COMMERCE PARK (CertainTeed Site) BUFFALO, NEW YORK BROWNFIELD CLEANUP PROGRAM Site Number C915185

April 30, 2021 File No. 21.0056854.00



### **PREPARED FOR:**

Ship Certain, L.L.C. 15260 Ventura Boulevard Suite 1120 Sherman Oaks, CA 91403

### **GZA GeoEnvironmental of New York**

300 Pearl Street, Suite 700 | Buffalo, New York 14202 716-685-2300

32 Offices Nationwide www.gza.com

Copyright© 2021 GZA GeoEnvironmental of New York



Proactive by Design

GEOTECHNICAL

ENVIRONMENTA

ECOLOGICAL

WATER

CONSTRUCTION MANAGEMENT

GZA GeoEnvironmental of NY 300 Pearl Street Suite 700 Buffalo, NY 14202 T: 716-685-2300 F: 716-248-1472

www.gza.com



### **VIA EMAIL**

April 30, 2021 File No. 21.0056854.00

Mr. Megan Kuczka
New York State Department of Environmental Conservation
Division of Environmental Remediation
270 Michigan Avenue
Buffalo, New York 14203
email: megan.kuczka@dec.ny.gov

Re: 2021 Periodic Review Report
Buffalo Lakeside Commerce Park (CertainTeed Site)
231 Ship Canal Parkway, Buffalo, New York
Brownfield Cleanup Program Site (Number C915185)

Dear Ms. Kuczka:

GZA GeoEnvironmental of New York (GZA) is pleased to submit this Periodic Review Report (PRR) on behalf of Ship Certain LLC., owner and operator of the Buffalo Lakeside Commerce Park Brownfield Cleanup Program (BCP) Site (No. 915185). GZA prepared this PRR in general conformance with the guidelines provided to the former owner (Ship Certain, L.L.C.) in the 45-day reminder notice letter dated February 22, 2021.

If you have any questions or need additional information, please call Jim Richert at (716) 844-7048.

Sincerely,

GZA GEOENVIRONMENTAL OF NEW YORK

James J. Richert, P.G.

Senior Project Manager

Bart A. Klettke, P.E.

Principal

Cc: James Martin (Ship Certain) George Hicker (Ship Certain)

1.0 EXECUTIVE SUMMARY	1
1.1 BACKGROUND	1
1.2 EFFECTIVENESS OF THE REMEDIAL PROGRAM	1
1.3 COMPLIANCE	
1.4 RECOMMENDATIONS	1
2.0 SITE OVERVIEW	2
	2
2.1 SITE LOCATION AND FEATURES	2
2.2 INVESTIGATION AND REMEDIAL HISTORY	
3.0 EVALUATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS	3
4.0 INSTITUTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT	3
4.1 IC/EC REQUIREMENTS AND COMPLIANCE	3
4.2 IC/EC CERTIFICATION	4
5.0 PRR CONCLUSIONS AND RECOMMENDATIONS	4
5.1 PRR CONCLUSIONS	4
5.2 PRR RECOMMENDATIONS	
FIGURES	

FIGURE 1 SITE LOCATION MAP

FIGURE 2A SITE PLAN WITH PHOTO LOCATIONS (9.28.2018)

FIGURE 2B SITE PLAN WITH PHOTO LOCATIONS (10.29.2019)

FIGURE 2C SITE PLAN WITH PHOTO LOCATIONS (9.16.2020)

### **APPENDICES**

APPENDIX A SITE INSPECTION FORMS

APPENDIX B PHOTOGRAPH LOGS

APPENDIX C 60-DAY ADVANCED NOTICE OF SITE CHANGE OF USE, TRANSFER OF COC, AND/OR OWNERDHIP

APPENDIX D IC/EC CERTIFICATION FORM



### 1.1 BACKGROUND

The Buffalo Lakeside Commerce Park Site (CertainTeed Site or Site) is an active manufacturing facility located on a 25.1-acre parcel with an address of 231 Ship Canal Parkway. The Site is situated within the greater 113acre Buffalo Lakeside Commerce Park of Buffalo, New York. (Figure 1). The Site is located on what was a railroad yard of the former Hanna Furnace iron manufacturing facility. Environmental Site investigations confirmed the presence of semi-volatile organic compounds (SVOCs) and metals in the soil/fill at concentrations greater than NYSDEC Part 375 Technical and Administrative Guidance Memorandum (TAGM) 4046 soil cleanup objectives. Also, groundwater was determined to have elevated pH. Considering Site contaminants of concern are not volatile, the focus of the Site remedy was to minimize the exposure risks of direct contact and/or inhalation with site contaminants in the soil/fill and the high pH groundwater. The Remedial Action Objectives (RAOs) for the Site included:

- Addressing soils with contaminants above the NYSDEC guidance values in the upper 1-foot;
- Prevention of ingestion or direct contact with groundwater and with soil containing contaminants exceeding the guidance values;
- Implementation and maintenance of engineering and institutional controls.

### **Institutional Controls Include:**

- Property use may include restricted industrial use only;
- Groundwater may not be used without prior treatment and approval of the regulator.

### The Engineering Control is:

 Cover System: hardscape and/or imported clean soil (minimum of 12 inches) underlain by a demarcation grid of high visibility yellow ribbon.

The Environmental Easement (EE) which includes greater specificity of the above ICs and ECs was signed by NYSDEC on September 22, 2005.

### 1.2 EFFECTIVENESS OF THE REMEDIAL PROGRAM

Based upon our annual PRR inspections conducted on September 28, 2018, October 29, 2019, and September 16, 2020 the site cover system was confirmed to be in place and appeared to be complete, in good condition, and functioning as intended. Therefore, the Site remedy continues to be effective at meeting Site RAOs. The need for minor repairs of pavement and re-seeding of grass cover at some locations was identified.

### 1.3 COMPLIANCE

Ownership of the Site was transferred on April 23, 2021 from Ship Certain, LLC to James Martin. A 60-Day Advance Notification of Site Change of Use, Transfer of Certificate of Completion, and/or Ownership was submitted to NYSDEC by an owner representative on February 1, 2021.

GZA identified the Site to be in compliance with the SMP. The Institutional Controls and Engineering Controls (IC/ECs) remain in place and there are no active remedial systems requiring monitoring or operation and maintenance.

### 1.4 RECOMMENDATIONS

GZA and CertainTeed recommend no changes to the SMP nor to the frequency of Site inspections and PRR submittals. Implementation of the SMP, including the Excavation Work Plan and maintenance of the Site cover system will continue as the Site continues operations as a manufacturing facility.

### 2.0 SITE OVERVIEW

### 2.1 SITE LOCATION AND FEATURES

The Site is in the southeast corner of the Buffalo Lakeside Commerce Park which is bounded by the Hamburg Turnpike (RT 5) to the west, the boundary between the Cities of Buffalo and Lackawanna to the south, railroad tracks to the east, and wetlands and Tifft Street to the north. The Site is flat and in area of the City that was formerly used for heavy industry but is currently sparsely developed by manufacturing and rail uses. (Figure 1). In 2005 the Site (NYSDEC Site No. C915185) was remediated under the Brownfield Cleanup Program (BCP) for restricted industrial use.

### 2.2 INVESTIGATION AND REMEDIAL HISTORY

Based on information obtained from environmental Site investigations, SVOCs and metals were identified at concentrations above applicable regulatory guidance (TAGM-4046). Other than elevated pH, no contaminants of concern were identified in the on-Site groundwater.

The Remedial Action Objectives (RAOs) for the Site were:

- Address soils with contaminants above the TAGM-46 levels in the upper 1-foot;
- Prevent ingestion or direct contact with soil contaminants;
- Institute and maintain institutional and engineering controls to assure the Site is not used in a manner inconsistent with the future anticipated use (restricted industrial).

The selected site remedy included placement of a site cover system, made up of either clean soil at a minimum thickness of 1-foot or hardscapes including paved roads, parking lots, sidewalks, and/or building slab foundations.

The Site remedy was completed in 2005 and a Certificate of Completion (COC) was issued by NYSDEC.



### 3.0 EVALUATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS

GZA performed three annual Site Inspections during the reporting period of March 31, 2018 to March 31, 2021. The Site inspections were performed on September 28, 2018, October 29, 2019, and September 16, 2020. The completed Site Inspection Forms are provided in Appendix A. Photo logs of each of three inspections are provided in Appendix B and maps showing the location and orientation of the Site photos are provided as Figures 2A, 2B, and 2C. Since the previous Site inspection and PRR in 2018. The required cover system is being maintained per the SMP and was observed to be providing complete coverage of the Site. The Site remedy, therefore, continues to be effective at meeting the Site RAOs for protection of current and intended future site users.

### 4.0 INSTITUTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT

### 4.1 IC/EC REQUIREMENTS AND COMPLIANCE

IC/ECs for the Site were determined by NYSDEC and specified in the EE issued by NYSDEC on September 22, 2005. Summary lists of the ICs and ECs are provided as follows:

### **Summary of Site Institutional Controls:**

- Property use may include restricted industrial use only;
- Groundwater may not be used without prior treatment and approval of the regulator.

### **Summary of Site Engineering Control:**

Cover System: hardscape and imported clean soil (minimum of 12 inches) vegetated and underlain by a grid of high visibility yellow ribbon. Hardscapes may include paved roads, parking lots, sidewalks, and/or building slab foundations.

On February 1, 2021, a representative of the Site Owner filed with NYSDEC a completed 60-Day Advance Notification of Site Change of Use, Transfer of Certificate of Completion, and/or Ownership, indicating a change in ownership and transfer of Certificate of Completion (COC) to Mr. James Martin. A copy of the 60-Day Notice is provided in Attachment C. The change of ownership was completed on April 23, 2021.

No significant changes to the Site cover system were reported or observed since submittal of the previous PRR on April 23, 2018.

CertainTeed and their operations appear to be in general compliance with the SMP with a few relatively minor areas in need of improvement as follows:

- The vegetative cover of the soil cover system has a few areas of bare spots due mostly to trucks driving slightly off pavement, cutting corners, and material storage extending off paved surfaces; (see Photos # 1, 2, 3, and 19).
- One area of the paved Site road showed signs of cracking, and weathering; (See Photo # 4).

Buffalo Lakeside Commerce Park -CertainTeed, BCP Site No. C915185 – 2021 Periodic Review Report

File No. 21.0056854.00

Page | 4

Grass cover is missing in areas where product storage extends off of pavement; (See Photo #16).

Based on observations made during GZA's Site inspections Ship Certain is complying with provisions of the SMP relative to IC/ECs. Manufacturing activity continues at the Site and CertainTeed is aware that monitoring and observation by a QEP is required during earth moving activities. Although not a required EC, additional protection of the Site was provided by a six-feet high PVC perimeter fence which was installed in 2018 and restricts access to the Site.

### 4.2 IC/EC CERTIFICATION

The Site-specific IC/EC Certification Form, for reporting period of March 31, 2018 to March 31, 2021, was provided to Ship Certain as an attachment to the February 22, 2021 Reminder Notice letter sent by NYSDEC. This form has been completed by Ship Certain and Certified by GZA as QEP. The completed and certified IC/EC Certification Form for this reporting period is included in **Appendix D** of this PRR.

### 5.0 PRR CONCLUSIONS AND RECOMMENDATIONS

### 5.1 PRR CONCLUSIONS

The IC/ECs remain in place and are performing as intended. There are no active remedial systems requiring operation, monitoring, or maintenance. CertainTeed and their operations appear to be in general compliance with the SMP with a few relatively minor areas in need of improvement as follows:

- The vegetative cover of the soil cover system has a few areas of bare spots due mostly to trucks driving slightly off pavement, cutting corners, and material storage extending off paved surfaces; (see Photos # 1, 2, 3, and 19).
- One area of the paved Site road showed signs of cracking, and weathering; (See Photo # 4).
- Grass cover is missing in areas where product storage extends off of pavement; (See Photo #16).


### 5.2 PRR RECOMMENDATIONS


GZA and CertainTeed recommend no changes to the SMP nor to the frequency of site inspections (annual) and PRR submittals (Triennial). Implementation of the SMP, including the Excavation Work Plan and maintenance of the Site cover system will continue as Site manufacturing operations continue.


During the spring and summer of 2021, CertainTeed will repair vegetative cover and pavement in the areas mentioned above. The next site inspection is planned for early fall (September/October) of 2021 to demonstrate the above improvements.




**FIGURES** 











### **APPENDIX A**

**SITE INPECTION FORMS** 

# ENVIRONMENTAL INSPECTION FORM Hanna Furnace - Former Railroad Yard Area (Subparcel 1)

Buffalo Lakeside commerce Park certainteed site 95185 Inspection Date: Sept. 26, 2018 Property Name: Property Address: 231 Ship canal Parkway State: 1 Property ID: (Tax Assessment Map) Block: Total Acreage: Weather (during inspection): Temperature: 66 Konditions! SIGNATURE: The findings of this inspection were discussed with appropriate personnel, corrective actions were identified and implementation was mutually agreed upon: Date: 9-26-18 Next Scheduled Inspection Date: Summer 2019 SECURITY AND ACCESS 1. Access controlled by perimeter fencing? Are there sections of the fence material damaged or missing? Are the fence or gate post foundations structurally sound? 2. "No Trespass" signs posted in appropriate languages? Are the signs securely attached to the fencing or posts? Are there sufficient signs; are the signs adequately spaced around the perimeter of the property? 3. Is there evidence of trespassing? Is there evidence of illegal dumping? COVER & VEGETATION 4. Final cover in acceptable condition? Is there evidence of sloughing, erosion, ponding or settlement? Is there evidence of unintended traffic; rutting? Is there evidence of distressed vegetation/turf?

	Yes	No
5. Final cover sufficiently covers soil/fill material?  Are there cracks visible in the soil or pavement?  Is there evidence of erosion in the stormwater channels or swales?  Is there damage to the synthetic erosion control fabric in the channels or swales?		X N/A
ACTIVITY ON SITE		
6. Any activity on site that mechanically disturbed soil cover?	X	:
ADDITIONAL FACILITY INFORMATION  Development on or near the site? (Specify size and type: e.g., residential, 40  Perimeter PVC Fed  during SPIMGY SUMMER OF 2  were driven Not excavated	acres, well an	d septic) NSTalled Fence Po
COMMENTS		
Item#  SITE COVES SYSTEM IS CONTAINED NO DE CONCESSOR TO REPOSE	omflo issu	es
1. Site Sketch 2. Photographs	PR	

Laboratory Report (s)

# ENVIRONMENTAL INSPECTION FORM

Hanna Furnace - Former Railroad Yard Area (Subparcel 1)

2713/85	NOT 29 2019
Property Name: CertainTeel SiTe Inspection Date:	ocied just
Property Address: 23/ Ship cand Parkway	149/8
City: Buffalo State: NY	Zip Code:
Property ID: (Tax Assessment Map)	r1 ***
Section: 132.20 Block: Lot(s)	: <i>f)</i>
Total Acreage:	
Weather (during inspection): Temperature: 67 FC conditions: Mos7	14 cloudy
SIGNATURE:	
The findings of this inspection were discussed with appropriate personnel, correct	tive actions were identified
and implementation was mutually agreed upon:	ate: 10-29-19
HISDECTOL II	atc.
Next Scheduled Inspection Date: Summer 2020	
SECURITY AND ACCESS	Yes No
1. Access controlled by perimeter fencing?  Are there sections of the fence material damaged or missing?  Are the fence or gate post foundations structurally sound?	× NA =
2. "No Trespass" signs posted in appropriate languages?  Are the signs securely attached to the fencing or posts?  Are there sufficient signs; are the signs adequately spaced around the perimeter of the property?	PX NA NA
3. Is there evidence of trespassing?  Is there evidence of illegal dumping?	
COVER & VEGETATION	
4. Final cover in acceptable condition?  Is there evidence of sloughing, erosion, ponding or settlement?  Is there evidence of unintended traffic; rutting?	<u>X</u> <u>X</u> <u>X</u>
Is there evidence of distressed vegetation/turf?	

	Yes	No
5. Final cover sufficiently covers soil/fill material?  Are there cracks visible in the soil or pavement?  Is there evidence of erosion in the stormwater channels or swales?  Is there damage to the synthetic erosion control fabric in the channels or swales?  ACTIVITY ON SITE  6. Any activity on site that mechanically disturbed soil cover?	<u>X</u>	X MA
ADDITIONAL FACILITY INFORMATION		
Development on or near the site? (Specify size and type: e.g., residential, 40 a	cres, well and	septic)
COMMENTS		
<u>Item #</u>		/-
is well maintained.		l tion,
No issues of concern to le	eport	
ATTACHMENTS		
<ol> <li>Site Sketch</li> <li>Photographs</li> <li>Laboratory Report (s)</li> </ol>	RR	

# ENVIRONMENTAL INSPECTION FORM

Hanna Furnace - Former Railroad Yard Area (Subparcel 1)

Property Name: CertainTeed site Inspection Date: Sept. 16,2020
Property Address: 231 Ship Canal Parkway
7 Code 17311
City. 4001
Property ID: (Tax Assessment Map) Section: 132 20 Block: Lot(s):
Section. · O
Total Acreage:
Weather (during inspection): Temperature: 65 Conditions: 65 UNING
SIGNATURE:
The findings of this inspection were discussed with appropriate personnel, corrective actions were identified
and implementation was mutually agreed upon:
Inspector: Juni Rechert Date: 9-16-00
Next Scheduled Inspection Date: SUMMER 3021
SECURITY AND ACCESS Yes No
intropulited.
1. Access controlled by perimeter fencing?  Are there sections of the fence material damaged or missing?
Are the fence or gate post foundations structurally sound?
<i>1</i>
2. "No Trespass" signs posted in appropriate languages? Not required X
Are the signs securely attached to the lending of posts:
Are there sufficient signs; are the signs adequately spaced around the perimeter of the property?
around the perimeter of the property
3. Is there evidence of trespassing?
Is there evidence of illegal dumping?
COVER & VEGETATION
COVER & VEGETATION
4. Final cover in acceptable condition?
Is there evidence of sloughing, erosion, ponding or settlement?
Is there evidence of unintended traffic; rutting?
Is there evidence of distressed vegetation/turf?

	Yes No
5. Final cover sufficiently covers soil/fill material?  Are there cracks visible in the soil or pavement?  Is there evidence of erosion in the stormwater channels or swales?  Is there damage to the synthetic erosion control fabric in the	X Zimited X NA
channels or swales?	
ACTIVITY ON SITE	
6. Any activity on site that mechanically disturbed soil cover?	X
ADDITIONAL FACILITY INFORMATION	
Development on or near the site? (Specify size and type: e.g., residential, 40	acres, well and septic)
-	
COMMENTS	
Item#	
Site cover semains in Place condition. ARENS FOR imp - Vegetative cover missing in Lin Truck Tikes of STOLAGE	1 - MCCIO
- ASPHALT POVEMENT CRICKER IN LIMITER A PER, SEE	#1216+1842/
:	
:	
<u>ATTACHMENTS</u>	
1. Site Sketch	
Photographs 2	

Laboratory Report (s)



**APPENDIX B** 

**PHOTO LOGS** 



**Client Name:** CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Northeast

### **Description:**

Newly planted trees for landscaping, replaced ash trees that died.



Photo No.

2

**Date:** 9-26-18

**Direction Photo Taken:** 

Northeast

### **Description:**

Perimeter road and new perimeter fence at northern end of Site property.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Southwest

**Description:** 

Perimeter road – view facing toward site entrance.



Photo No.

4

**Date:** 9-26-18

**Direction Photo Taken:** 

South

**Description:** 

View of rear loading docks.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Southeast

### **Description:**

Area of removed and planned replacement of concrete pavement (between two rail lines).




Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

South

### **Description:**

Perimeter road at eastern corner of the property. New PVC perimeter fence in background.





**Client Name:** CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No. 7

**Date:** 9-26-18

**Direction Photo Taken:** 

East

### **Description:**

Marked (in yellow) areas of planned pavement repairs.



Photo No.

0

**Date:** 9-26-18

**Direction Photo Taken:** 

Southwest

### **Description:**

Typical good condition of asphalt pavement, rear product storage lot.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Northeast

### **Description:**

Complete vegetative cover between rear product storage lot and rear perimeter fence.



Photo No.

10

**Date:** 9-26-18

**Direction Photo Taken:** 

Northeast

### **Description:**

West Side loading dock.





**Client Name:** CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Southeast

### **Description:**

Complete vegetative cover of western side of Site. Note new PVC perimeter fence in background.



Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

Northwest

### **Description:**

Perimeter road along west side of site.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

East

**Description:** 

Site building as seen from Site entrance.



Photo No.

**Date:** 9-26-18

**Direction Photo Taken:** 

North

**Description:** 

Site Entrance with large boulder to limit trucks from driving over the vegetated soil cover.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 10-29-19

**Direction Photo Taken:** 

Southwest

## **Description:**

Site Entrance Road from inside of the Site perimeter fence.



Photo No.

2

**Date:** 10-29-19

**Direction Photo Taken:** 

Southeast

### **Description:**

View of lawn at western corner of plant building.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 3 10-29-19

**Direction Photo Taken:** 

Northeast

**Description:** 

Employee parking lot.



Photo No. Date: 4 10-29-19

**Direction Photo Taken:** 

East

**Description:** 

Southwestern corner of Site.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No. 5

**Date:** 10-29-19

**Direction Photo Taken:** 

West

### **Description:**

Concrete block support building at SW corner of the Site.



Photo No.

**Date:** 10-29-19

**Direction Photo Taken:** 

Southeast

### **Description:**

Western end of property, grass vegetated.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 7 10-29-19

**Direction Photo Taken:** 

Southeast

### **Description:**

Asphalt drive and product storage at western end of fenced area.




Photo No.

**Date:** 10-29-19

**Direction Photo Taken:** 

South

### **Description:**

View of southern corner of Site. Products and supplies staged on pavement, non-paved area is fully vegetated.





**Client Name:** CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 10-29-19

**Direction Photo Taken:** 

Northeast

**Description:** 

Paved exterior product storage.




Photo No.

**Date:** 10-29-19

**Direction Photo Taken:** 

Southeast

**Description:** 

SE extent of exterior product storage, site perimeter fence.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

 Photo No.
 Date:

 11
 10-29-19

**Direction Photo Taken:** 

Southwest

### **Description:**

Back of plant building and rear paved exterior product storage area.



Photo No. Date: 12 10-29-19

**Direction Photo Taken:** 

Northeast

**Description:** 

Site Perimeter road and fence.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 13 10-29-19

**Direction Photo Taken:** 

Southeast

### **Description:**

Rear perimeter road and rail siding.



Photo No. Date: 14 10-29-19

### **Direction Photo Taken:**

South

### **Description:**

Eastern corner of site with perimeter road and fence.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No. Date: 1 9-16-20

**Direction Photo Taken:** 

NE

### **Description:**

View along Site Entrance Road. Limited areas of missing grass cover along road edges from vehicle tires.



Photo No.

2 ...

**Date:** 9-16-20

**Direction Photo Taken:** 

SW

### **Description:**

Bare patches in grass cover along entrance road.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

South

### **Description:**

Missing grass by employee parking lot due to vehicle traffic.



Photo No.

4

**Date:** 9-16-20

**Direction Photo Taken:** 

SW

### **Description:**

Cracked and weathered asphalt pavement of entrance road. Pavement cover still complete.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 5 9-16-20

**Direction Photo Taken:** 

SE

**Description:** 

Materials receiving and storage side of building.



Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

SE

**Description:** 

Perimeter road by materials receiving and storage.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

South

#### **Description:**

Outside of NE gate/side of fenced product storage yard.



Photo No.

**Date:** 9-16-18

**Direction Photo Taken:** 

SW

#### **Description:**

Pavement of fenced product storage yard along building.





**Client Name:** CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

SE

**Description:** 

Paved fenced product storage yard.



Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

SW

**Description:** 

Paved fenced product storage yard.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

East

#### **Description:**

Grass cover at rear of fenced product storage yard.



Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

NW

#### **Description:**

Paved fenced product storage yard.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

NW

#### **Description:**

Paved, non-fenced, product storage area.



Photo No.

**Date:** 9-16-20

**Direction Photo Taken:** 

South

#### **Description:**

Southern corner of property – fully covered with vegetation.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 15 9-16-20

**Direction Photo Taken:** 

North

**Description:** 

Paved loading dock area.



Photo No. Date: 16 9-16-20

**Direction Photo Taken:** 

SE

**Description:** 

Product storage extending off pavement. Missing grass cover observed as a result.





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

**Photo No. Date:** 17 9-16-20

**Direction Photo Taken:** 

West

**Description:** 

Fire suppression building.



Photo No. Date: 18 9-16-20

**Direction Photo Taken:** 

East

**Description:** 

Front lawn of property





Client Name: CertainTeed Corporation

Site Location: 231 Ship Canal Parkway, Buffalo, NY

**Project No.** 21.0056854.00

Photo No. 19 **Date:** 9-16-20

**Direction Photo Taken:** 

NW

#### **Description:**

Missing grass cover along Site road to loading docks – caused by truck tires.



Photo No.

Date:

20 9-16-20

**Direction Photo Taken:** 

East

#### **Description:**

Paved site entrance road and parking lot.





**APPENDIX C** 

**60-DAY NOTICE** 

### NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION



## 60-Day Advance Notification of Site Change of Use, Transfer of Certificate of Completion, and/or Ownership

Required by 6NYCRR Part 375-1.11(d) and 375-1.9(f)

To be submitted at least 60 days prior to change of use to:

Chief, Site Control Section

	New York State Department of Environmental Conservation Division of Environmental Remediation, 625 Broadway
I.	Albany NY 12233-7020  Certain Feed Site  Site Name: DEC Site ID No. C9/15/85
1.	Site Maine. 27.77
II.	Contact Information of Person Submitting Notification:
	Name: GEORGE HICKER
	Address 1: GO CARDINAC TNOUST RUAL CHECKER ON
	Address2: 15260 VENTURA BUD., #10, 549140
	Phone: \$18789-5600 E-mail: 660165 @ CARO (NT) U ST.
	COM
III.	Type of Change and Date: Indicate the Type of Change(s) (check all that apply):
	Change in Ownership or Change in Remedial Party(ies)
	Transfer of Certificate of Completion (CoC)
	Other (e.g., any physical alteration or other change of use)
	Proposed Date of Change (mm/dd/yyyy): 3. 25 202
IV	
	parcel information.
	Sale by Ship Certain UC
	to Dames Martin with Certain Teed
	remaining on lease until 12/31/29
	If "Other," the description must explain <u>and</u> advise the Department how such change may or may not affect the site's proposed, ongoing, or completed remedial program (attach additional sheets if
	needed).
	. 0

V.	<b>Certification Statement:</b> Where the change of use results in a change in ownership or in responsibility for the proposed, ongoing, or completed remedial program for the site, the following certification must be completed (by owner or designated representative; see §375-1.11(d)(3)(i)):
	I hereby certify that the prospective purchaser and/or remedial party has been provided a copy of any order, agreement, Site Management Plan, or State Assistance Contract regarding the Site's remedial program as well as a copy of all approved remedial work plans and reports.
	Name:  (Signature)  (Date)  (Print Name)  (Print Name)
	Address1: CO CHRIWAL T. ND 15260 VENTUR GI # 1120 Address2: ETERMAN OAKS, CAL
	Phone: 518-789-560 E-mail: 680 RGB CHRIVING 51.403
VI.	Contact Information for New Owner, Remedial Party, or CoC Holder: If the site will be sold or there will be a new remedial party, identify the prospective owner(s) or party(ies) along with contact information. If the site is subject to an Environmental Easement, Deed Restriction, or Site Management Plan requiring periodic certification of institutional controls/engineering controls (IC/ECs), indicate who will be the certifying party (attach additional sheets if needed).
	Prospective Owner Prospective Remedial Party Prospective Owner Representative
	Name: DARS MARTIN
	Address1: 180 Pitts ford Victor Read \$200
	Address2: FIFT S foll N. T. 19539  Phone: 585-381-0570 E-mail: Sames M @ LBM Development of the RNEY: JESFREY DEVOESICK 585-672—com
	Certifying Party Name:
	Address1:
	Address2:
	Phone: E-mail:

VII. Agreement to Notify DEC after Transfer: If Section VI applies, and all or part of the site will be sold, a letter to notify the DEC of the completion of the transfer must be provided. If the current owner is also the holder of the CoC for the site, the CoC should be transferred to the new owner using DEC's form found at <a href="http://www.dec.nv.gov/chemical/54736.html">http://www.dec.nv.gov/chemical/54736.html</a>. This form has its own filing requirements (see 6NYCRR Part 375-1.9(t)).

Signing below indicates that these notices will be provided to the DEC within the specified time frames. If the sale of the site also includes the transfer of a CoC, the DEC agrees to accept the notice given in VII.3 below in satisfaction of the notice required by VII.1 below (which normally must be submitted within 15 days of the sale of the site).

Within 30 days of the sale of the site, I agree to submit to the DEC:

- 1. the name and contact information for the new owner(s) (see §375-1.11(d)(3)(ii));
- 2. the name and contact information for any owner representative; and

3. a notice of transfer using the DEC's form found at <a href="http://www.dec.ny.gov/chemical/54736.html">http://www.dec.ny.gov/chemical/54736.html</a>

(see §2	375-1.9(f)).	10	,	/
Name:	Muyet	all	1/29/	202
÷	(Signature)	1/4 /4	(Date)	
	(De016)	EMARCA		
	(Print Name)		•	
Address1:	C/6 C/	PAINAL I	-ND.	2 HORADW
Address2:		NTURA BL,	#1120	WARS,
Phone:	17 789 560	ro E-mail: GORGE	ARNINDUS!	- ac.
	010	•	com	914,3
	1. Ann 1.		$\sim$	11/0/

# **Continuation Sheet** Prospective Owner/Holder Prospective Remedial Party Prospective Owner Representative Address1: Address2: E-mail: Phone: Prospective Owner/Holder Prospective Remedial Party Prospective Owner Representative Name: Address1: Address2: \_\_\_\_\_ E-mail: \_\_\_\_\_ Phone: Prospective Owner/Holder Prospective Remedial Party Prospective Owner Representative Name: Address1: Address2: E-mail: Phone: Prospective Owner/Holder Prospective Remedia/Party Prospective Owner Representative Name: Address1: Address2: E-mail: \_\_\_\_\_ Phone: Prospective Owner/Holder Prospective Remedial Party Prospective Owner Representative Name: Address1: \_\_\_\_\_ Address2: \_\_\_\_\_ E-mail: \_\_\_\_\_ Phone: Prospective Owner/Holder Prospective Remedial Party Prospective Owner Representative Name: Address1: Address2: \_\_\_\_\_ E-mail: \_\_\_\_\_



#### APPENDIX D

IC/EC CERTIFICATION FORM



# Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Site	Site Details e No. C915185	Box 1	3				
Site	Site Name Buffalo Lakeside Commerce Park						
City Cou	Site Address: 231 SHIP CANAL PARKWAY Zip Code: 14218 City/Town: Buffalo County: Erie Site Acreage: 25.000						
Rep	porting Period: March 31, 2018 to March 31, 2021						
		YES	NO				
1.	Is the information above correct?	×					
	If NO, include handwritten above or on a separate sheet.						
2.	Has some or all of the site property been sold, subdivided, merged, or underg tax map amendment during this Reporting Period?	gone a	×				
3.	Has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))?		×				
4.	Have any federal, state, and/or local permits (e.g., building, discharge) been if for or at the property during this Reporting Period?	issued	X				
	If you answered YES to questions 2 thru 4, include documentation or even that documentation has been previously submitted with this certification.						
5.	Is the site currently undergoing development?		X				
		Box 2					
		YES	NO				
6.	Is the current site use consistent with the use(s) listed below?  Commercial and Industrial	K					
7.	Are all ICs in place and functioning as designed?	X o					
IF THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.							
A Corrective Measures Work Plan must be submitted along with this form to address these issues.							
Sig	gnature of Owner, Remedial Party or Designated Representative	Date					

SITE NO. C915185 Box 3

#### **Description of Institutional Controls**

**Parcel** 

Owner

132.20-1-11

Ship Certain LLC

Institutional Control

Soil Management Plan Landuse Restriction Building Use Restriction

Ground Water Use Restriction O&M Plan

1. Commercial/industrial site use only, commercial day care, child care or medical care prohibited.

2. Site cover to include pavement, structures, or minimum of 12 inches of clean soil with vegetative growth. Existing soil excavated from beneath cover is to be managed, characterized and disposed in accordance with the soil management plan.

Box 4

#### **Description of Engineering Controls**

<u>Parcel</u>

**Engineering Control** 

132.20-1-11

Cover System

1. Commercial/industrial site use only, commercial day care, child care or medical care prohibited.

2. Site cover to include pavement, structures, or minimum of 12 inches of clean soil with vegetative growth. Existing soil excavated from beneath cover is to be managed, characterized and disposed in accordance with the soil management plan.

		Box 5
	Periodic Review Report (PRR) Certification Statements	
1.	I certify by checking "YES" below that:	
	<ul> <li>a) the Periodic Review report and all attachments were prepared under the direction of, a reviewed by, the party making the Engineering Control certification;</li> </ul>	and
	<ul> <li>b) to the best of my knowledge and belief, the work and conclusions described in this cer are in accordance with the requirements of the site remedial program, and generally acce engineering practices; and the information presented is accurate and compete.</li> </ul>	tification pted
	YES	NO
2.	For each Engineering control listed in Box 4, I certify by checking "YES" below that all of the following statements are true:	
	(a) The Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;	
	(b) nothing has occurred that would impair the ability of such Control, to protect public he the environment;	alth and
	<ul> <li>(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;</li> </ul>	
	(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and	
	(e) if a financial assurance mechanism is required by the oversight document for the site, mechanism remains valid and sufficient for its intended purpose established in the document.	the ent.
	YES	NO

IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.

A Corrective Measures Work Plan must be submitted along with this form to address these issues.

Signature of Owner, Remedial Party or Designated Representative

X

Date

#### IC CERTIFICATIONS SITE NO. C915185

Box 6

## SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

print name at 231 Ship Canal print business address	Parkway,
am certifying as	(Owner or Remedial Party)
for the Site named in the Site Details Section of this form.  Signature of Owner, Remedial Party, or Designated Representative Rendering Certification	4 27 202  Date

#### **EC CERTIFICATIONS**

Box 7

#### **Professional Engineer Signature**

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

Print name at 300 PEARL STREET SUITE 700 BOFFALO, NY 14202, print name print business address

am certifying as a Professional Engineer for the SHIP CERTAIN MANAGEMENT, LLC

am certifying as a Professional Engineer for the \_\_\_

emedial Party)

Signature of Professional Engineer, for the Owner or Remedial Party, Rendering Certification

Stamp (Required for PE)



GZA GeoEnvironmental, Inc.