HARRIS BEACH ∄

ATTORNEYS AT LAW

726 EXCHANGE STREET, SUITE 1000 BUFFALO, NY 14210 (716) 200-5050

ROBERT G. MURRAY

DIRECT: (716) 200-5180 FAX: (716) 200-5224 BMURRAY@HARRISBEACH.COM

September 21, 2007

VIA FEDERAL EXPRESS

Kelly Lewandowski Chief, Site Control Section New York State Dept. of Environmental Conservation Division of Environmental Remediation 625 Broadway Albany, NY 12233

Re: Pierce Arrow Development Project

Brownfield Cleanup Program Application

Site ID: C915220

Dear Kelly:

Enclosed please find additional materials related to the Brownfield Cleanup Program Application by Pierce Arrow Development, LLC with respect to the former Pierce Arrow manufacturing site located in Buffalo, New York. These materials are being sent to you as a follow up to a meeting I had with DEC Region 9 staff on September 13, 2007.

Should you have any questions or concerns, please feel free to call me at 716-200-5180.

Very truly yours,

Harris Beach PLLC


Robert G. Murray

RGM:kd


cc: Martin Doster

Exhibit 1

Supplement to: Application to NYS Brownfield Cleanup Program Former Pierce Arrow Manufacturing Site 255 Great Arrow Way, Buffalo, New York







MALCOLM PIRNIE

6062001 SEPTEMBER 2007

SITE AERIAL VIEW
FORMER PIERCE ARROW MANUFACTURING SITE
BUFFALO, NEW YORK




PROPOSED PROJECT PHASING


PIERCE ARROW DEVELOPMENT PROJECT BUFFALO, NEW YORK











SOURCE/POTENTIAL SOURCE OF CONTAMINATION

<u>LEGEND:</u>

SITE/BUILDING AREA BOUNDARY PHOTO LOCATION, NUMBER, DIRECTION OF VIEW


PIERCE ARROW DEVELOPMENT, LLC 255 GREAT ARROW WAY

PIERCE ARROW REDEVELOPMENT PROJECT


PIERCE ARROW REDEVELOPMENT SITE
SUMMARY OF ENVIRONMENTAL CONDITIONS BUILDING W AREA

SEPTEMBER 2007 MALCOLM PIRNIE, INC. FIGURE

6062F002



SCALE: 1" = 50




BUILDING "B"


SUSPECT PIPE LOCATION —

LIMITED VEHICLE STORAGE—NOW IN DISREPAIR


HOTEL

HEAVY MANUFACTURING PIERCE ARROW





User: shafer Spec: PIRNIE STANDARD File: F: \Projects\6062001\CADD\FIGURES\6062F005.DWG Scale: 1:1 Date: 09/19/2007 Time: 13: 55 Layout: Layout1





Project:

Photo No.

1

Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY Project No.

Date: 9/18/2007 6062-001

Direction Photo Taken:

West

Description:

Building B – South outer wall of building.



PHOTOGRAPHIC LOG

Project:

Photo No.

Location:

Project No.

Former Pierce Arrow Manufacturing Site Date:

Buffalo, NY

6062-001

9/18/2007 2 **Direction Photo Taken:**

West

Description:

Building B - Inside south wall.





Project:

Former Pierce Arrow Manufacturing Site

Location:Buffalo, NY

Project No. 6062-001

Photo No.

Date: 9/18/2007

Direction Photo Taken:

Southwest

Description:

Building B – Rotting wood flooring of drum storage site south wall of building.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY **Project No.** 6062-001

Photo No.


Date: 9/18/2007

Direction Photo Taken:

Southwest

Description:

Building B – Suspect pipe on floor at west wall.





Project:

Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY Project No.

6062-001

Photo No. 5

Date: 9/18/2007

Direction Photo Taken:

North

Description:

Building A - Mineral spirits storage area.



PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Project No.

Date:

Buffalo, NY

6062-001

9/18/2007 6

Direction Photo Taken:

Photo No.

West

Description:

Building A – South side walls inside building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

East

Description:

Building A – Rotting wood floor at southeast corner of building.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 8 Date: 9/18/2007
Direction Photo Taken:

West

Description:

Building A – Rotting, oilsoaked wood block floor at east end of building.





Project:Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY **Project No.** 6062-001

Photo No. 9 **Date:** 9/18/2007

Direction Photo Taken:

Northwest

Description:

Building A – Open compromised bags containing unknown black substance.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY **Project No.** 6062-001

Photo No.

Date: 9/18/2007

Direction Photo Taken:

West

Description:

Building A – Southwest floor with green moss.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

South

Description:

Building A – Red door of former cyanide room.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

West

Description:

Building A – Inside north wall.





Project:

Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY Project No. 6062-001

Photo No. 17

Date:

9/18/2007

Direction Photo Taken:

South



Description:

Building A – Oily stained floor and 5 gallon bucket of penetrating oil in building.

PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Project No.

Buffalo, NY

6062-001

Photo No. 36

Date: 9/18/2007

Direction Photo Taken:

East

Description:

Building A – Tank fill pipe - center of west wall.





Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No. 6062-001

Photo No. 37 **Date:** 9/18/2007

Direction Photo Taken:

East

Description:

Building A – Tank fill pipe north of center of west wall.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Project No.

TOTTICLE TICIOC ALTOW IV

Photo No. 38

Date: 9/18/2007

Direction Photo Taken:

East

Description:

Building A - 2 pipes - 1 fuel oil fill pipe northwest corner.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 39 9/18/2007
Direction Photo Taken:

East

Description:

Building A – Close up of northwest fill pipe.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

South

Description:

Building A – View of west side of site.





Project:


Former Pierce Arrow Manufacturing Site

Location:

Project No.

Buffalo, NY

6062-001



South



Description:

Building A – Fuel fill pipe and possible excavation backfill on north wall of building.

MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project: Former Pierce Arrow Manufacturing Site Location: Buffalo, NY Project No. 6062-001

Photo No. Date: 9/18/2007 43 **Direction Photo Taken:**

South

Description:

Building A – Old furnace on outside north wall of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 41

Date: 9/18/2007

Direction Photo Taken:

East

Description:

Building A – View of north side of site.





Project:

Location:

Project No.

Former Pierce Arrow Manufacturing Site

Buffalo, NY

6062-001

Photo No.

Date: 9/18/2007

Direction Photo Taken:

North

Description:

Building C – Compromise waste drum storage area.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001


Photo No. 14 **Date:**

14 9/18/2007 Direction Photo Taken:

South

Description:

Building C – Compromise waste drum storage area.





Project:

Former Pierce Arrow Manufacturing Site

Location:

Project No.

Buffalo, NY

6062-001

Photo No. 15 **Date:** 9/18/2007

Direction Photo Taken:

Southwest

Description:

Building C – Southwest corner of building.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:
Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY Project No.

Photo No. 16 **Date:** 9/18/2007

Direction Photo Taken:

South

Description:

Building C – Crate of fluorescent light ballasts in north area of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

West

Description:

Building C – Boiler room - asbestos coating on boiler.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

Southwest

Description:

Building C – Outside wall of east side of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007

Direction Photo Taken:

Northeast

Description:

Building C – Empty UST for boiler.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

West

Description:

Building C – Fuel pump room – buckets of oil and staining.





Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No. Date: 9/18/2007

Direction Photo Taken:

South

Description:

Building C – Fuel pump room – oil soaked floor.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

West

Description:

Building D – North side of site



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

East

Description:

Building D – North side of site.





Project No.

Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Photo No. 25

Date: 9/18/2007

Direction Photo Taken:

West



Building D – Loading dock at southwest corner of building.



PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No. 26

Date: 9/18/2007

Direction Photo Taken:

North

Description:

Building D – Loading dock at southwest corner of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

Southeast

Description:

Building D – Southeast corner of site.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

28 9/18/2007 Direction Photo Taken:

Date:

Northeast

Photo No.

Description:

Building D – View of southeast corner of building.





Project:

Former Pierce Arrow Manufacturing Site

Location: Buffalo, NY Project No.

6062-001

Photo No. 29

Date: 9/18/2007

Direction Photo Taken:

West

Description:

Building D – Inside view of west half of building.



PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site Date:

Location:

Buffalo, NY

Project No.

6062-001

30 9/18/2007


Photo No.

Direction Photo Taken:

East

Description:

Building D – Inside view of east half of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 45 Date: 9/18/2007
Direction Photo Taken:

Southwest

Description:

Building D – View of northeast corner of building.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. Date: 9/18/2007
Direction Photo Taken:

Southwest

Description:

Building D – View of northeast corner of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 47 **Date:** 9/18/2007

Direction Photo Taken:

South

Description:

Building D – Western area of property.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 48 **Date:** 9/18/2007

Direction Photo Taken:

West

Description:

Building D – Exterior of south side of building.





Project:Location:Project No.Former Pierce Arrow Manufacturing SiteBuffalo, NY6062-001

Photo No. 49 **Date:** 9/18/2007

Direction Photo Taken:

East

Description:

Building D – Oily stained soil at east end of site.





Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No.

Date: 9/18/2007

Direction Photo Taken:

West



Building G & H – West tank fill-port in courtyard with suspected UST.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No. 32

Date: 9/18/2007

Direction Photo Taken:

East

Description:

Building G & H – Courtyard between building with suspected UST.





Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No. 34

Date: 9/18/2007

Direction Photo Taken:

West



Building G & H – Furnace room of building courtyard containing unknown debris.



MALCOLM PIRNIE

PHOTOGRAPHIC LOG

Project:

Former Pierce Arrow Manufacturing Site

Location:

Buffalo, NY

Project No.

6062-001

Photo No. 55

Date: 9/18/2007

Direction Photo Taken:

North

Description:

Building G & H – Front of building adjacent to historic UST locations.

