



Groundwater & Environmental Services, Inc.

63 E Main Street, Unit 3  
Pawling, New York 12564

T. 800.360.9405

September 26, 2024

Mr. Matthew Hubicki  
New York State Department of Environmental Conservation  
Division of Environmental Remediation  
Remedial Bureau C  
625 Broadway  
Albany, New York 12233-7014

**Re: Non-Routine Maintenance Report**  
Carmel Shop-Rite Plaza  
180 Gleneida Avenue  
Carmel, New York  
NYSDEC Site Number V00104

Dear Mr. Hubicki:

Groundwater & Environmental Services, Inc. (GES) on behalf of Regency Centers has prepared this *Non-Routine Maintenance Report* for the above referenced Site.

On July 23, 2024, a periodic site inspection was completed at the Carmel Shop-Rite Center (the Site), located at 180 Gleneida Avenue, Carmel, New York. All sub-slab depressurization system (SSDS) components were operational at the time of the site inspection. A copy of the SSDS Operation and Maintenance (O&M) Checklist is included as **Attachment A**.

The next SSD inspections will be completed during the fourth quarter of 2024.

If you have any questions or comments regarding this submittal, please contact Michael DeGloria of GES at (800) 866-839-5195, extension 3839.

Sincerely,

Michael C. DeGloria, P.G.  
Principal Project Manager

cc: Monica Roth, Regency Centers

## Attachment A

---

**Europa Pizza**

**SUB-SLAB DEPRESSURIZATION O&M CHECKLIST**

**Name:** Richard Brown

**Date:** 07/23/2024

**ROUTINE SYSTEM MAINTENANCE:**

**Note:** the following checklist should be performed for each slab entry point.

**FANS:**

☒

Check that the fan is running.

☒

Check that no new air intakes have been installed within 20 feet of exhaust pipe.

**SEALS:**

☒

If possible, observe suction point where PVC pipe enters the floor slab.

☒

Observe the seal around PVC pipes for visual cracks or a loud audible hissing. Indications of leaks should be reported to GES as soon as possible.

**PIPING:**

☒

Check liquid manometers (look like U-shaped thermometers) for a difference in water level on each side of the U-shape.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no damage has occurred.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no unauthorized piping connections have been made.

☒

Where piping is visible check that labeling and liquid manometers remain in place.

**IF THE INTEGRITY OF THE SYSTEM HAS BEEN COMPROMISED PLEASE REPORT TO GES AS  
SOON AS POSSIBLE AT 866-839-5195**

**New Journey nails and spa**

**SUB-SLAB DEPRESSURIZATION O&M CHECKLIST**

**Name:** Richard Brown

**Date:** 07/23/2024

**ROUTINE SYSTEM MAINTENANCE:**

**Note:** the following checklist should be performed for each slab entry point.

**FANS:**

☒

Check that the fan is running.

☒

Check that no new air intakes have been installed within 20 feet of exhaust pipe.

**SEALS:**

☒

If possible, observe suction point where PVC pipe enters the floor slab.

☒

Observe the seal around PVC pipes for visual cracks or a loud audible hissing. Indications of leaks should be reported to GES as soon as possible.

**PIPING:**

☐ NA

Check liquid manometers (look like U-shaped thermometers) for a difference in water level on each side of the U-shape.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no damage has occurred.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no unauthorized piping connections have been made.

☒

Where piping is visible check that labeling and liquid manometers remain in place.

**IF THE INTEGRITY OF THE SYSTEM HAS BEEN COMPROMISED PLEASE REPORT TO GES AS SOON AS POSSIBLE AT 866-839-5195**

**Electric Paradise**

**SUB-SLAB DEPRESSURIZATION O&M CHECKLIST**

**Name:** Richard Brown **Date:** 07/23/2024

**ROUTINE SYSTEM MAINTENANCE:**

**Note:** the following checklist should be performed for each slab entry point.

**FANS:**

☒

Check that the fan is running.

☒

Check that no new air intakes have been installed within 20 feet of exhaust pipe.

**SEALS:**

☒

If possible, observe suction point where PVC pipe enters the floor slab.

☐ NA

Observe the seal around PVC pipes for visual cracks or a loud audible hissing. Indications of leaks should be reported to GES as soon as possible.

**PIPING:**

☒

Check liquid manometers (look like U-shaped thermometers) for a difference in water level on each side of the U-shape.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no damage has occurred.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no unauthorized piping connections have been made.

☒

Where piping is visible check that labeling and liquid manometers remain in place.

**IF THE INTEGRITY OF THE SYSTEM HAS BEEN COMPROMISED PLEASE REPORT TO GES AS SOON AS POSSIBLE AT 866-839-5195**

**Chinatown**

**SUB-SLAB DEPRESSURIZATION O&M CHECKLIST**

**Name:** Richard Brown

**Date:** 07/23/2024

**ROUTINE SYSTEM MAINTENANCE:**

**Note:** the following checklist should be performed for each slab entry point.

**FANS:**

☒

Check that the fan is running.

☒

Check that no new air intakes have been installed within 20 feet of exhaust pipe.

**SEALS:**

☒

If possible, observe suction point where PVC pipe enters the floor slab.

☒

Observe the seal around PVC pipes for visual cracks or a loud audible hissing. Indications of leaks should be reported to GES as soon as possible.

**PIPING:**

☐ NA

Check liquid manometers (look like U-shaped thermometers) for a difference in water level on each side of the U-shape.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no damage has occurred.

☒

Inspect all system pipes and/or pipe enclosures to ensure that no unauthorized piping connections have been made.

☒

Where piping is visible check that labeling and liquid manometers remain in place.

**IF THE INTEGRITY OF THE SYSTEM HAS BEEN COMPROMISED PLEASE REPORT TO GES AS  
SOON AS POSSIBLE AT 866-839-5195**