

#### **ADVANCED SITE RESTORATION**

ENVIRONMENTAL SERVICES (A DIVISION OF LAUREL ENVIRONMENTAL GEOSCIENCES, D.P.C.)

December 13, 2024

New York State Department of Environmental Conservation Superfund and Brownfield Cleanup Section, Region 2 Division of Environmental Remediation Attention: Hasan Ahmed 47-40 21<sup>st</sup> Street, Long Island City, NY 11101

Re: Nassau Metals, OU-2

Voluntary Cleanup Program Site No. V00159

June 2024 Renovations Report

ASR Project #A22-115

Dear Mr. Ahmed,

Advanced Site Restoration ("ASR"), a division of Laurel Environmental Geosciences ("Laurel") is submitting this report documenting the renovation work that was performed on the Nassau Metals, Operable Unit No. 2 (the "Site") in accordance with the New York State Department of Environmental Conservation ("NYSDEC")-approved work plan, dated June 20, 2024. The ground intrusive work was completed on June 21, 2024, and the capping system was restored by June 28, 2024. The location of the work area is shown on the attached Figure 1 and the proposed plans are included in Appendix A.

#### **Modifications to the Capping System**

The following modifications to the capping system were performed:

- The on-grade patio was determined to be placed on top of the pre-construction cap and was removed without disturbing the pre-existing capping system.
- A concrete stairway was demolished. The concrete stairway was part of the pre-construction concrete cap.
- A concrete ramp was demolished. The concrete ramp was part of the pre-construction concrete cap. Pea gravel was encountered inside of the concrete ramp, and some of this material was reused in the dumpster area west of the pickleball courts as shown on the attached Figure 2.
- The top 2 inches of the existing pre-construction asphalt cap was milled, and asphalt was imported to raise the grade approximately 6 to 8 inches and level the area. The imported asphalt was added to the capping system in the footprint of the ramp, stairway, and patio.

Asphalt was sourced from City Asphalt, located at 1900 South Ave, Staten Island, New York. Approximately 40 cubic yards of construction and demolition debris was disposed of at South Shore Recycling, LLC. d/b/a South Shore Material & Supply, Inc., located at 18 Zarelli Court (aka 327 Industrial Loop), Staten Island, New York, a NYSDEC Part 360 registered facility (ID # 43M56), and T. M. Maintenance, Inc. d/b/a Staten Island Recycling, located at 451 Spencer St, Staten Island, NY, a NYSDEC Part 360 registered facility (ID #43W46). The disposal tickets are included in Appendix B. No soil or other solid waste was generated or disposed of as part of this work.





#### **ADVANCED SITE RESTORATION**

ENVIRONMENTAL SERVICES (A DIVISION OF LAUREL ENVIRONMENTAL GEOSCIENCES, D.P.C.)

#### **ASR Oversight**

ASR provided Qualified Environmental Professional ("QEP") oversight and implemented the Community Air Monitoring Program ("CAMP") for the Site during the demolition work. All work was documented in the daily report dated June 21, 2024. ASR confirmed that no organic material was encountered or exposed as part of the planned renovations, and that no exceedances of the CAMP limits occurred. The concrete ramp and stairways were determined to have been constructed on top of the pre-construction concrete and asphalt caps, and the existing demarcation barriers (the pre-construction concrete and asphalt caps) were not breached at any time during this work. As such, the pre-construction concrete and asphalt caps will continue to serve as the demarcation barriers in this area of the Site. A photo log documenting the work performed is included in Appendix C.

#### **Capping System Modification / Restoration**

As previously described, the pre-construction concrete and asphalt caps in this area of the Site were modified through the addition of approximately 6 to 8 inches of asphalt on top of the existing demarcation barriers. No material other than asphalt was imported to the Site as part of the capping system modification.

The updated as-builts will be included in the 2024 Periodic Review Report ("PRR") for the Site. The capping system was restored in accordance with Detail 9 of the 2018 As-Built Drawings (Typical As-Built Asphalt Added TO Existing Asphalt Cap). The restored cap consists of a pre-existing demarcation barrier, asphalt millings, bituminous base course, and a bituminous top course and is greater than 6 inches in combined thickness.

Please let us know if you have any questions or need additional information.

Respectfully submitted,

Jamie Burgher

Project Manager, Geologist III

Advanced Site Restoration

### **Appendices**

Figure 1.0: Location of Work Area

Figure 2.0: Location of the Reused Material

Appendix A: DOB Approved Plans

Appendix B: Disposal Tickets for C&D Debris

Appendix C: Photo Log





### **ADVANCED SITE RESTORATION**


ENVIRONMENTAL SERVICES (A DIVISION OF LAUREL ENVIRONMENTAL GEOSCIENCES, D.P.C.)


I, Dan Noll, certify that the restoration of the capping system to be conducted on June 28, 2024, at the Nassau Metals OU-2 Site, was overseen by myself, a New York State Registered Professional Engineer, and performed in compliance with the Site Management Plan and approved Excavation Work Plan.

Dan Noll, PE LaBella Associates

VP, Environmental Technical Manager









53 West Hills Road Huntington Station, NY 11746

PHONE: 631-673-0612 FAX: 631-427-5323

WWW.ASKASR.COM

#### FIGURE 1.0 Location of Work Area

Nassau Metals OU-2, 286 Richmond Valley Road, Staten Island, NY. I

DRAWING DATE: 6/4/24 DRAWN BY: JB

CHECKED BY: SY
REVISIONS: N/A

PROJECT: A22-115


#### **KEY**





Work Area







53 West Hills Road Huntington Station, NY 11746

PHONE: 631-673-0612 FAX: 631-427-5323

WWW.ASKASR.COM

#### FIGURE 2.0

Location of Reused Material

Nassau Metals OU-2, 286 Richmond Valley Road, Staten Island, NY.

#### KEY

DRAWING DATE: 12/5/24



REVISIONS:

PROJECT: A22-115


Reused Material Loaction

- — — Site Boundary



# APPENDIX A

**DOB Approved Plans** 



# **APPENDIX B**

**Disposal Tickets for C&D Debris** 

South Shore Materials #119440
327 Industrial Loop • Staten Island, New York 10309
718-494-8973 • Fax: 718-477-0887

Ma	mmb)	Λ	- 6-22 20 24 236 Demand vary Ro American Materials			
SHIPPE	ED FROM _	<i>✓</i>	distributed dely lo			
NAME	30	Flme	cican Mater	ia15		
ADDRE	:SS	2				
TRUCK NO. # 302		DELIVERY	MATERIAL IN	MATERIAL OUT		
: Y	SAND		CU. YARD	6.5		
	3/4" STO	NE (REC) (BLUE)	CU. YARD			
	ASPHALT		CU. YARD			
CLEAN FILL		ILL	CU. YARD			
K y HAJ	3/4" BLEN	ND	CU. YARD			
8	TOP SOIL	_/LANDSCAPE MIX	CU. YARD			
20	CONCRETE		CU. YARD	Jegun TH		
	сомроз	ST .	CU. YARD	J' T'		
	1/4 FINES		CU. YARD			
	OVERSIZ	ED STONE	CU. YARD	×		
	MULCH		CU. YARD			

RECEIVED BY



## T. M. MAINTENANCE, INC.

334758

### d/b/a

### STATEN ISLAND RECYCLING 451 Spencer Street, Staten Island, NY 10314

451 Spencer Street, Staten Island, NY 10314 (718) 477-DUMP (3867) • (718) 761-2984 Fax: (718) 370-9560

ruck # _ Bill To:	Amarcan Marcan N						
hone #			, Price		These		
Time In	<u>Yds</u>	Description		Amount	Sig		
16.	20	Concrete					
waru mas				n 18 4			
	25. J.	·		9			
		236 Rich					
		Action w					
			·				
		Mamodu	-				
-		11 0	Total				
gnature		and the second s					

Once Load is Signed For and Dumped No Claims or Adjustments Will Be Made.

Thank You

# **APPENDIX C**

**Photo Log** 



Photo 1: View of the work zone, facing south



Photo 2: View of the concrete stairway being demolished



Photo 3: View of the crushed stone encountered in the void space beneath the stairs



Photo 4: View of pea gravel encountered in the void space beneath the stairs



Photo 5: View of asphalt surface beneath the former stairs



Photo 6: View of concrete ramp being demolished




Photo 7: View of pea gravel encountered in the void space beneath the concrete ramp



Photo 8: View of concrete surface beneath the former concrete ramp



Photo 9: View of asphalt being placed on the pre-construction capping system(s)




Photo 10: View of finished pickleball courts



Photo 10: View of the reused material from the ramp in the dumpster area