


New York Department of Environmental Conservation  
Division of Environmental Remediation  
Region 9 Office-Buffalo



**FIELD INSPECTION REPORT**

**Date:** July 20, 2007  
**Site Name:** Mineral Springs Works  
**Site Number:** V00195  
**Location:** West Seneca (T), Erie County  
**Project Engineer:** David Szymanski, NYSDEC - Buffalo  
**Contractor:** Nature's Way Environmental (for NFG).

**Weather Conditions:** Partly Cloudy, ~70 degrees F., Winds SW 5-10 mph

**Purpose of Inspection:** Site inspection for direct-push soil borings; Stream bank excavation.

**Observations:**

- 1330 -1400 Hours, on Site.
- Nature's Way drill rig on Calais Street. MW-21 has been repaired. Elevation of well set with survey level.
- MW-20 has broken concrete collar, but looks to still be usable. Noted by Nature's Way for NFG's information.
- Soil borings southwest of Building #8 completed yesterday. Await decision from NFG on course of action.
- No excavation work at stream bank yet.



< MW-21

MW-20 >



