

David Szymanski - Fencepost Installation Summary

From: Brad Walker <WalkerB@natfuel.com>
To: dsszyman@gw.dec.state.ny.us
Date: 7/3/2013 2:29 PM
Subject: Fencepost Installation Summary
CC: AlexanderT@natfuel.com
Attachments: National Fuel Fence Install Summary Figure.pdf; National Fuel Fence Install Summary.pdf

Dave,

Attached is a summary of the materials encountered during the recent fencepost installations at our Mineral Springs facility. Please let me know if you have any questions.

Brad Walker, CPG
Senior Environmental Analyst
National Fuel Gas Distribution Corporation
Orchard Park Service Center
5955 New Taylor Rd
Orchard Park, NY 14127
716-667-5559 walkerb@natfuel.com



July 3, 2013

Mr. Dave Szymanski
New York State Department of Environmental Conservation
270 Michigan Avenue
Buffalo, New York 14203

Re: Summary of Materials Encountered
Mineral Springs Fence Replacement

Dear Dave,

As we discussed, on June 26, 2013 some suspected purifier box wastes were encountered while advancing four new fencepost holes near the southwestern corner at our Mineral Springs facility. These locations are within National Fuels' property boundaries, adjacent to a buried NYMO transmission cable as shown on the attached figure and Photo 004. The materials exhibited the characteristic deep Prussian blue color. All suspect material was containerized in a new 55-gallon drum and will be sampled and disposed of properly.

Should you have any questions regarding this matter, please feel free to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Brad Walker", written in a cursive style.

Brad Walker
Senior Environmental Analyst

Attachments

cc: Tanya Alexander



Photo 001: Suspect purifier box waste




Photo 002: Suspect purifier box waste





Photo 003: Suspect purifier box waste



Photo 004: View facing west-northwest of new fencepost holes with suspect purifier box waste.



DETAIL



LEGEND	
	EXISTING STRUCTURE
	REMEDIAL CONSTRUCTION
	MONITORING WELLS
	APRE ADDITIONAL PURIFIER RESIDUALS EXCAVATION
	B3EAC BUILDING 3 EAST ASPHALT CAP
	B3SAC BUILDING 3 SOUTH ASPHALT CAP
	B8WAC BUILDING 8 WEST ASPHALT CAP
	B10AC BUILDING 10 ASPHALT CAP
	CC CLAY CAP
	CTBE CENTRAL TAR BOILS EXCAVATION
	DPE DIESEL PAD EXCAVATION
	EDD EASTERN DRAINAGE DITCH
	ESHG EASTERN SWALE HDPE CAP
	ESNAC EASTERN SWALE NORTH ASPHALT CAP
	ESSAC EASTERN SWALE SOUTH ASPHALT CAP
	ETBE EASTERN TAR BOILS EXCAVATION
	NTBE NORTHERN TAR BOILS EXCAVATION
	RTW1 RECOVERY TEST WELL AND DNAPL SHED
	SETLE SOUTHEASTERN TAR LENSES EXCAVATION
	SPE SEPARATOR PITS EXCAVATION
	SWPRE SOUTHWEST RESIDUALS EXCAVATION
	WTBE WESTERN TAR BOILS EXCAVATION
	CLAY CAP
	ASPHALT CAP
	HDPE CAP
	REMEDIAL CONSTRUCTION
	NEW FENCE
	AREA OF DETAIL

