



Geotechnical  
Environmental  
Water Resources  
Ecological

August 6, 2014  
Project 1326870

Mr. Todd Caffoe, P.E.  
New York State Dept. of Environ. Conservation  
Region 8  
6274 E. Avon-Lima Road  
Avon, NY 14414

Re: Site Management Periodic Review Report  
And IC/EC Certification Submittal (2014)  
Brewer Street Site (V00214-8)  
Rochester, NY

Dear Mr. Caffoe:

On behalf of Rochester Gas & Electric Corporation and Monroe County Department of Environmental services, GEI Consultants (GEI) is submitting the attached Periodic Review Report and IC/EC Certification Submittal for the Brewer Street Site. If you have any questions please contact the undersigned or Mr. Dan Kennedy of RG&E at (585) 724-8386.

Sincerely yours,  
GEI CONSULTANTS, INC., P.C.

A handwritten signature in black ink, appearing to read "Kelly R. McIntosh".

Kelly R. McIntosh, Ph.D., P.E.

Cc: Dan Kennedy, RG&E (by email)  
Drew Smith, Monroe County (by email)  
Ed Harding, Monroe County (by email)

# **Site Management Periodic Review Report and IC/EC Certification (2014)**

Brewer Street Site (V00214-8)  
Rochester, New York

**Submitted to:**

New York State Department of Environmental Conservation  
Division of Environmental Remediation, Region 8  
Avon, New York

**Submitted by:**

GEI Consultants, Inc., P.C.  
90B John Muir Drive, Suite 104  
Amherst, NY 14228

**On behalf of:**

Rochester Gas and Electric Corporation  
89 East Avenue  
Rochester, New York

August 2014

Project 1326870

# Table of Contents

---

<b>1.</b>	<b>Executive Summary</b>	<b>1</b>
<b>2.</b>	<b>Site Overview</b>	<b>2</b>
2.1	Site Description	2
2.2	Site Remedial Program Summary	2
2.2.1	2003 Remedial Action	2
2.2.2	2006 Remedial Action	3
2.2.3	Site Management Plan	4
<b>3.</b>	<b>Remedy Performance Evaluation</b>	<b>5</b>
3.1	Vegetative Cover	5
3.2	Rock Ledge Cap	5
3.2.1	Quarterly Routine Inspections	5
3.2.2	Annual Inspection	6
<b>4.</b>	<b>IC/EC Plan Compliance</b>	<b>7</b>
4.1	IC/EC Requirements	7
4.2	IC/EC Compliance	7
4.3	IC/EC Certification	7
<b>5.</b>	<b>Inspection Plan Compliance</b>	<b>8</b>
5.1	Inspection Requirements	8
5.2	Inspection Compliance	8
<b>6.</b>	<b>Conclusions and Recommendations</b>	<b>9</b>

## **Figures**

---

- 1 Site Location Map
- 2 Site Plan and Pre-Remediation Features
- 3 Soil Excavation and Land Site Limits
- 4 Rock Ledge Remediation Area (2006)

## **Appendices**

---

- A Brewer Street Inspection Forms
- B Institutional and Engineering Controls Certification Form

# 1. Executive Summary

---

GEI Consultants, Inc., P.C. (GEI) was retained to conduct the Site Management Periodic Review Report (PRR) and IC/EC Certification submittal for the Brewer Street Site located in Rochester, New York (Figure 1). The remediation of the Brewer Street Site was conducted jointly by the Rochester Pure Waters District and Monroe County through the Monroe County Department of Environmental Services (MCDES) and Rochester Gas and Electric Corporation (RG&E) pursuant to a Voluntary Cleanup Agreement (VCA, Index #B8-0547-98-12) executed with the New York State Department of Environmental Conservation (NYSDEC), on July 18, 2002.

The Brewer Street site was remediated to address the presence of aromatic volatile organic compounds (VOCs) including benzene, toluene, ethylbenzene and xylene (BTEX), and polyaromatic hydrocarbons (PAHs) in the aqueous phase and a dense non-aqueous phase liquid (DNAPL). Remediation programs were conducted in 2003 and 2006 and a post-remediation Site Management Plan (SMP) was implemented (See Section 2, below).

In conducting this periodic review, GEI found each component of the SMP was complied with during this reporting period (July 16, 2013 through July 16, 2014):

- ICs/ECs have been in place and effective
- Inspections were performed as required

Based upon the inspections and compliance with the SMP, the site remedy continues to meet the remedial objectives for the site.

## 2. Site Overview

---

### 2.1 Site Description

As shown on Figure 1, the Site is located adjacent to the Middle Falls Dam in the Genesee River Gorge in Rochester, NY. The Site plan showing pre-remediation topography and features is shown on Figure 2. The approximate 3.25-acre Site was used to manage tunnel cuttings (i.e., “tunnel muck”) and waters (i.e., “construction water”) generated when the Cliff Street Siphon Tunnel was constructed under the Genesee River as part of the Monroe County Pure Waters Combined Sewer Overflow Abatement Program between 1984 and 1985. The tunnel muck and construction water were transferred to the Site and treated using settling and polishing ponds prior to effluent discharge. The tunnel muck contained aromatic volatile organic compounds (VOCs) including benzene, toluene, ethylbenzene and xylene (BTEX), and polyaromatic hydrocarbons (PAHs) in the aqueous phase and a dense non-aqueous phase liquid (DNAPL).

Site characterization data are presented in reports titled “Site Characterization and Remedial Alternatives Evaluation Report” prepared by Blasland, Bouck & Lee, Inc. (BBL), dated August 1998 and "Supplemental Investigation Report (SIR)" prepared by Geomatrix, dated February 2002. The SIR was approved by the NYSDEC on April 11, 2003. Collectively, these investigations identified impacted on-Site soils and two distinct areas of impacted Genesee River sediment designated as the “North Lobe” and the “South Lobe”. Site soils and Genesee River sediments adjacent to the Site were impacted primarily by PAHs and, to a lesser extent, aromatic VOCs.

### 2.2 Site Remedial Program Summary

The voluntary cleanup actions were conducted in two phases. The first phase was a large scale excavation of impacted soils, weathered bedrock and river sediments and off-Site disposal of the excavated materials. This was conducted in 2003 and is referred to herein as the 2003 Remedial Action.

The second phase of the voluntary cleanup entailed pressure grouting of the bedrock near the dam to displace and/or immobilize residual DNAPL and construction of a concrete cap on the exposed Rock Ledge at the base of the dam. This work was conducted in 2006-2007 and is referred to herein as the 2006 Remedial Action.

#### 2.2.1 2003 Remedial Action

Monroe County and RG&E submitted the RWP for the 2003 Remediation in June 2003. The RWP was approved by NYSDEC by letter dated July 9, 2003. The remediation activities

conducted during 2003 involved excavation of impacted soils and river sediments for disposal at the permitted off-Site facility; the Mill Seat Landfill located in Riga, NY.

The approved cleanup objectives for the project were as follows:

Media	Cleanup Objective
<b>Surface and Subsurface Soil</b>	Removal of non-aqueous phase liquids
<b>Marsh Area Surface Soils (upper 2 feet)</b>	4 mg/kg total PAHs
<b>Surface Soils (upper 1 foot non-wetland areas)</b>	5 mg/kg total carcinogenic PAHs 10 mg/kg total PAHs, 1 mg/kg VOCs
<b>Subsurface Soils (Site-wide)</b>	100 mg/kg total PAHs 10 mg/kg total VOCs

Soils excavation proceeded until cleanup objectives were attained at all locations. River sediments were excavated to bedrock within the areas designated for remediation in the approved RWP. A total of 62,195 tons of soils, weathered bedrock and sediment were removed from the Site between July 23, 2003 and October 10, 2003. The soil excavations were backfilled with clean soil and the Site was graded in accordance with the approved grading plan presented in the RWP. The 2003 remediation soil excavation areas are shown on Figure 3.

These actions are documented in the Construction Closeout Report and Final Engineering Report (May 2004) prepared by Geomatrix Consultants and its design/construction subcontractor TurnKey Environmental Restoration, LLC (TurnKey).

### **2.2.2 2006 Remedial Action**

The 2006 Remedial Action was undertaken pursuant to Section 13.0 of the RWP to mitigate migration of potential DNAPL presence in shallow bedrock. The work performed is described in the Supplemental Remediation Work Plan (SRWP) (prepared by Geomatrix and dated September 7, 2006) which was approved by the NYSDEC by letter dated September 19, 2006.

The 2003 Remedial Action removed the DNAPL source within the Site overburden and weathered upper bedrock. Based on the Supplemental Investigation results supported by post-remediation monitoring conducted during 2004-2006, potential DNAPL presence remaining at the Site was found to be limited to the upper 10 feet of bedrock in the immediate vicinity of the dam headwall and in the upper 5 to 8 feet of bedrock at the exposed rock ledge within the area

between the eastern dam headwall (Abutment A) and Pier B (Rock Ledge). This area of the Site is shown on Figure 4. The 2006 remediation utilized grout injection to:

1. Displace mobile DNAPL upward to the Rock Ledge containment area (where it was removed); and
2. Immobilize any residual DNAPL presence within the bedrock fractures.

After completion of the pressure grouting and removal of displaced DNAPL, the Rock Ledge surface was sealed by capping with reinforced concrete constructed to withstand uplift force associated with the reservoir “pond level” behind the adjacent dam. In addition, the Rock Ledge Cap was designed to accommodate backfill and a new support wall required to stabilize Abutment A. The new support wall was constructed in 2007 from Pier B to Abutment A along the northern side of the Rock Ledge Cap.

Construction of this support wall created a configuration where the Rock Ledge Cap is completely surrounded by walls (i.e., the wall replacing Gate 1, Pier B, the new support wall and the existing Abutment A). To provide additional stabilization of the headwall, the interior of the walled-in area was subsequently filled with 18 to 24 inches of clean washed stone overlain with clean soil.

Details of the 2006 Remedial Action are presented in the Final Engineering Report (FER), prepared by Geomatrix (June 2007).

### **2.2.3 Site Management Plan**

The Site Management Plan (SMP), approved by NYSDEC letter dated June 9, 2009, provides the following:

1. Protocols for future site excavations and soil management (see SMP Section 2.0);
2. Provisions for periodic inspection of the exposed outer (northern) edge of the Rock Ledge Cap, new support wall and associated drains (See SMP Section 3.0); and
3. Provisions for periodic certification (See SMP Section 4.0).
4. Copy of the filed deed restriction limiting land use to restricted residential or other restricted uses (see SMP Section 5.0);



## 3. Remedy Performance Evaluation

---

The remedial performance is evaluated based on the following:

1. Periodic inspection of the site vegetation cover
2. Periodic inspection of the rock ledge cap

### 3.1 Vegetative Cover

The annual inspection of the vegetative cover was performed June 18, 2014 by Mr. Kelly McIntosh, P.E. of GEI. The vegetative cover over areas that are not covered by rock outcrop, crushed stone, asphalt, concrete or structures was observed to be maintained as provided in the SMP.

### 3.2 Rock Ledge Cap

#### 3.2.1 *Semiannual Routine Inspections*

During this reporting period, semiannual inspections of the rock ledge cap were conducted from the dam without physically entering the rock ledge surface as described in the SMP. These “routine” inspections consist of the following:

1. Examine the exposed edge of the cap for DNAPL or sheen presence, water seepage, and evidence of physical deterioration.
2. Examine the new support wall for the same.
3. Examine the flow (if any) from the new support wall drain pipes for DNAPL or sheen presence.
4. Examine the face of the waterfall adjacent to the Rock Ledge for DNAPL seepage.
5. Examine the surface of the river adjacent to the Rock Ledge for sheen presence.

The frequency of the routine inspections is specified in the SMP as quarterly for the first year, semiannually for the second year and annually thereafter. During this reporting period, semiannual inspections were performed. Inspections are conducted by RGE or their designate. The routine inspection for this reporting period was conducted by Mr. Daniel Kennedy of RG&E.

Inspection logs are included in Appendix A. No DNAPL or sheen presence was observed the routine inspection event. No deterioration of the exposed edge of the cap was observed in the routine inspection event. No structural defects in the cap were observed.

### **3.2.2 Annual Inspection**

In addition to the routine inspection, at a frequency of once per year, inspection personnel physically enter the former spillway and rock ledge area to examine the rock ledge for the indications of DNAPL seepage (sheen presence, odors). This requires gate manipulation by RG&E to divert water away from the rock ledge area.

The annual inspection was conducted on June 18, 2014. The inspection was conducted by Mr. Daniel Kennedy of RG&E and Mr. Kelly McIntosh, P.E. of GEI. As in past, Gate 2 was held prior to the inspection per RG&E's operational procedures. This was in order to allow safe access downstream of the gates and allow personnel to access the rock ledge area. River safety and activity-specific health and safety protocols (i.e., fall protection, safety tailboard discussion and sign in / mark up sheet for gate hold) were implemented by RG&E in accordance with RG&E requirements prior to accessing the rock ledge.

No DNAPL, DNAPL-staining or oil sheen was observed on the Rock Ledge during the annual inspection. As in past inspections, iron oxide residue was observed on the lower portion of the retaining wall and on the rock surfaces. A reddish film was observed a puddle of water adjacent to the exposed edge of the cap. However, this film was observed to be "brittle", breaking up when disturbed and did not adhere to oil absorbent pads. This film was concluded to be either biological, iron oxide, or both.

## **4. IC/EC Plan Compliance**

---

### **4.1 IC/EC Requirements**

ICs include the following;

- Groundwater Use Restriction
- Site Management Plan
- Land Use Restriction

Site use of the property is limited to restricted residential, commercial, or industrial use, which include both operation and maintenance of RG&E's hydroelectric facilities and passive recreation including hiking, biking, parking and fishing.

ECs include the vegetative cover and rock ledge cap as described in the SMP and Section 2.0 of this PRR.

### **4.2 IC/EC Compliance**

The NYSDEC approved SMP is in place. All required inspections were performed in accordance with the SMP. All site restrictions have been complied with during this reporting period.

### **4.3 IC/EC Certification**

The IC/EC Certification is included in Appendix B.

## **5. Inspection Plan Compliance**

---

### **5.1 Inspection Requirements**

The inspection requirements as specified in the SMP are presented in Section 3.

### **5.2 Inspection Compliance**

The inspections were conducted in accordance with the SMP.

## 6. Conclusions and Recommendations

---


Each component of the SMP was complied with:

- ICs/ECs have been in place and effective
- Inspections were performed as required

Based upon the inspections and compliance with the SMP, the site remedy continues to meet the remedial objectives for the site.

# Figures

---




SITE LOCATION MAP  
Operations, Maintenance and Monitoring Plan  
Brewer Street Site

USGS Topographic Map  
Rochester West/East Quadrangle

Project No.  
9252  
Figure  
1

DATE: AUGUST 2020  
 FILEPATH: \\s:\umark\code\geomatics-brewer\street\red\figure 1-2\ site plan and existing site topography.dwg  
 DRAFTED BY: EDH



**LEGEND**

- 400 5-FOOT LAND CONTOURS
- 402 1-FOOT LAND CONTOURS
- 385 5-FOOT RIVER BED CONTOURS
- 384 1-FOOT RIVER BED CONTOURS
- SITE LIMITS (3.25 ACRES)

**NOTES:**

- 1.) ALL ELEVATIONS SHOWN ON THIS MAP ARE BASED ON THE NGVD 1929 DATUM GENERATED FROM USC&GS BENCH MARK "ST.PAUL."
- 2.) ALL PROPERTY LINE AND R.O.W. INFORMATION SHOWN ON THIS MAP WAS DETERMINED FROM CURRENT TAX MAP INFORMATION ONLY.
- 3.) ALL LOCATIONS ON THIS MAP ARE BASED ON THE NEW YORK STATE PLANE COORDINATE SYSTEM (WEST ZONE). NO SUBSURFACE UTILITIES WERE DETECTED.
- 4.) EDGE OF WATER AS OF 10-6-93
- 5.) SITE BENCH MARK IS NORTHWEST CORNER OF BLOWOFF CHAMBER, ELEV.=415.69
- 6.) SUMP, POND AND STOCKPILE LOCATIONS ARE APPROXIMATE.
- 7.) BASE MAP SOURCE: BBL (1998)



SCALE: 1 INCH = 60 FEET  
 SCALE IN FEET  
 (approximate)

**SITE PLAN AND PRE-REMEDIATION FEATURES  
 BREWER STREET SITE  
 ROCHESTER, NEW YORK**




Project No.  
 9252

Figure  
 2



DATE: AUGUST 2020  
 FILEPATH: \\s:\urney\code\geomatrix-brewer street rca\Figure 1-2, site plan and existing site topography.dwg  
 DRAFTED BY: EDH




**LEGEND**

- EXCAVATION LIMITS
- LAND-SITE LIMITS

**NOTES:**

- 1.) ALL ELEVATIONS SHOWN ON THIS MAP ARE BASED ON THE NGVD 1929 DATUM GENERATED FROM USC&GS BENCH MARK "ST.PAUL."
- 2.) ALL PROPERTY LINE AND R.O.W. INFORMATION SHOWN ON THIS MAP WAS DETERMINED FROM CURRENT TAX MAP INFORMATION ONLY.
- 3.) ALL LOCATIONS ON THIS MAP ARE BASED ON THE NEW YORK STATE PLANE COORDINATE SYSTEM (WEST ZONE). NO SUBSURFACE UTILITIES WERE DETECTED.
- 4.) EDGE OF WATER AS OF 10-6-93
- 5.) SITE BENCH MARK IS NORTHWEST CORNER OF BLOWOFF CHAMBER, ELEV.=415.69
- 6.) SUMP, POND AND STOCKPILE LOCATIONS ARE APPROXIMATE.
- 7.) BASE MAP SOURCE: BBL (1998)
- 8.) LAND- SITE LIMITS ARE AS IDENTIFIED IN THE VOLUNTARY CLEANUP AGREEMENT, EXCLUDING AREAS WITHIN THE GENESEE RIVER.




**SOIL EXCAVATION AND LAND-SITE LIMITS  
 BREWER STREET SITE  
 ROCHESTER, NEW YORK**



Project No.  
0028-007-200

Figure  
**3**



ROCK LEDGE REMEDIATION AREA (2006)  
 BREWER STREET SITE  
 ROCHESTER, NEW YORK

Project No.  
 9252

Figure  
 4

# **Appendix A**

---

## **Brewer Street Inspection Forms**

# Inspection Form

## Brewer Street, #1 Bay Area,

Date: December 6, 2013  
Time: 0745

- 1) Examine the exposed edge of the cap for DNAPL or sheen presence, water seepage and evidence of physical deterioration.

No DNAPL - No Sheen

- 2) Examine the new support wall for the same.

No DNAPL - NO Sheen

- 3) Examine the flow (if any) from the new support wall drain pipes for DNAPL or sheen presence. (5-4" drains thru wall)

Flow thru all 5 drains

- 4) Examine the face of the waterfall adjacent to the rock ledge for DNAPL seepage.

NO DNAPL

- 5) Examine the surface of the river adjacent to the Rock Ledge for sheen presence.

No sheen

Inspection frequency will be quarterly for the first year, semi-annually for the second year and annually thereafter. After 5 years re-evaluate the need for inspections.

Inspected by: Daniel Kennedy

Comments / observations: Viewed from Bridge deck & Pier C - used binos  
No pics - camera battery dead -

Quarterly - 1<sup>st</sup> year, Bi-annual-2<sup>nd</sup> year, Annually - 3<sup>rd</sup> - 5<sup>th</sup> years. Results reported annually by letter.

Inspection form #001 for Brewer Street, old # 1 gate area- 4-23-2009- DMK-

During inspection, the dam will be operated such that the edge of the cap is not inundated with water. (This may necessitate closing of Gate #2)

The inspection will be performed from Pier C using binoculars- as needed(9.2) (SMP)

# Inspection Form

## Brewer Street, #1 Bay Area,

Date: June 18, 2014  
Time: 10:00

- 1) Examine the exposed edge of the cap for DNAPL or sheen presence, water seepage and evidence of physical deterioration.

No DNAPL, slight sheen <sup>(SMP)</sup> puddled water at east corner, placed absorbent pads, sheen broke up no absorb to pad => mineral, no DNAPL accumulation on rock surface below sheen

- 2) Examine the new support wall for the same.

No DNAPL no sheen

- 3) Examine the flow (if any) from the new support wall drain pipes for DNAPL or sheen presence. (5-4" drains thru wall)

4 drains wet but no current flow. 1 drain dry (easternmost)

- 4) Examine the face of the waterfall adjacent to the rock ledge for DNAPL seepage.

No DNAPL

- 5) Examine the surface of the river adjacent to the Rock Ledge for sheen presence.

No sheen

Inspection frequency will be quarterly for the first year, semi-annually for the second year and annually thereafter. After 5 years re-evaluate the need for inspections.

Inspected by: Kump MCA

Comments / observations: 3<sup>rd</sup> Annual Inspection: McIntosh & Dan Kennedy accessed the rock ledge

Quarterly - 1<sup>st</sup> year, Bi-annual-2<sup>nd</sup> year, Annually - 3<sup>rd</sup> - 5<sup>th</sup> years. Results reported annually by letter.

Inspection form #001 for Brewer Street, old # 1 gate area- 4-23-2009- DMK-  
During inspection, the dam will be operated such that the edge of the cap is not inundated with water. (This may necessitate closing of Gate #2)  
The inspection will be performed from Pier C using binoculars- as needed(9.2) (SMP)

# **Appendix B**

---

## **Institutional and Engineering Controls Certification Form**



Enclosure 2  
**NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Site Management Periodic Review Report Notice**  
**Institutional and Engineering Controls Certification Form**



	Site Details	Box 1	
<b>Site No.</b> V00214			
<b>Site Name</b> Brewer Street			
Site Address: Foot of Brewer Street	Zip Code: 14621		
City/Town: Rochester			
County: Monroe			
Site Acreage: 3.3			
Reporting Period: July 16, 2013 to July 16, 2014			
		YES	NO
1. Is the information above correct?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
If NO, include handwritten above or on a separate sheet.			
2. Has some or all of the site property been sold, subdivided, merged, or undergone a tax map amendment during this Reporting Period?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
3. Has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
4. Have any federal, state, and/or local permits (e.g., building, discharge) been issued for or at the property during this Reporting Period?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>If you answered YES to questions 2 thru 4, include documentation or evidence that documentation has been previously submitted with this certification form.</b>			
5. Is the site currently undergoing development?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
		<b>Box 2</b>	
		YES	NO
6. Is the current site use consistent with the use(s) listed below? <i>- Restricted Residential, Commercial and Industrial</i>		<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Are all ICs/ECs in place and functioning as designed?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>IF THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.</b>			
<b>A Corrective Measures Work Plan must be submitted along with this form to address these issues.</b>			
_____ Signature of Owner, Remedial Party or Designated Representative		_____ Date	

**Description of Institutional Controls**

<u>Parcel</u>	<u>Owner</u>	<u>Institutional Control</u>
105.28-2-3.1	Rochester Gas and Electric	Ground Water Use Restriction Site Management Plan Landuse Restriction

Site use of the the property is limited to restricted residential, commercial, or industrial use, which uses include both operation and maintenance of RG&E's hydroelectric facilities and passive recreation including hiking, biking, parking and fishing.

The following long-term institutional controls are implemented:

- The Department approved site management plan (SMP) is in place;
- All excavations shall be implemented in accordance with the site management plan;
- The results of site inspections shall be periodically reported to the Department as provided in the SP;
- Groundwater underlying the site is prohibited unless specifically approved by the Department as provided in the SMP; and
- Periodic certifications are required as specified in the SMP at a frequency specified by the Department.

**Description of Engineering Controls**

<u>Parcel</u>	<u>Engineering Control</u>
105.28-2-3.1	Cover System Fencing/Access Control

The following long-term engineering controls are implemented:

- The vegetative cover over areas that are not covered by rock outcrop, crushed stone, asphalt, concrete, or structures shall be continually maintained, as provided in the SMP & #59;  
*KDM*
- The cap constructed over the rock ledge at the easternmost base the middle falls dam, shall be maintained and periodically inspected for structural integrity and evidence of any seepage of dense non-aqueous phase liquid on a schedule as agreed upon with the Department as noted in the SMP & #59;  
*KDM*



**Periodic Review Report (PRR) Certification Statements**

1. I certify by checking "YES" below that:

a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;

b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted

YES NO

2. If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:

(a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;

(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;

(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;

(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and

(e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.

YES NO

**IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.**

**A Corrective Measures Work Plan must be submitted along with this form to address these issues.**

\_\_\_\_\_  
Signature of Owner, Remedial Party or Designated Representative

\_\_\_\_\_  
Date

**SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE**

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

I Kelly R. McIntosh at 6EI Consultants, Inc. P.C.  
90 B John Muir Drive  
Amherst, NY 14228  
print name print business address

am certifying as Owner's Designated Representative (Owner or Remedial Party)

for the Site named in the Site Details Section of this form.

Kelly R. McIntosh  
Signature of Owner, Remedial Party, or Designated Representative  
Rendering Certification

8/5/14  
Date

IC/EC CERTIFICATIONS

Box 7

Professional Engineer Signature

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

i Kelly R McIntosh at 6EI Consultants, Inc., P.C.  
90 B John Muir Drive  
Amherst, NY 14228  
print name print business address

am certifying as a Professional Engineer for the Owner  
(Owner or Remedial Party)

*Kelly R McIntosh*

Signature of Professional Engineer, for the Owner or Remedial Party, Rendering Certification



Stamp  
(Required for PE)

Date 8/5/14