

June 27, 2024

Mr. Gerald Pratt, P.G. New York State Department of Environmental Conservation Division of Environmental Remediation, 12th Floor 625 Broadway Albany, New York 12233-7014

Subject: 2024 Annual Site-Wide Inspection Report

RG&E Brockport MGP Site

Village of Brockport, Monroe County, New York

NYSDEC Site #V00301-8

Dear Mr. Pratt:

On behalf of Rochester Gas and Electric Corporation (RG&E), and in accordance with the requirements of the Site Management Plan (SMP), NEU-VELLE, LLC (NEU-VELLE) has completed the annual Site-Wide Inspection of the Brockport Former Manufactured Gas Plant (MGP) Site, located near the intersection of Erie and Perry Streets in Brockport, New York (the "Site").

The Site-Wide Inspection was performed by NEU-VELLE on April 16, 2024. A completed Site Inspection Form is provided as **Attachment A**. Photographs taken during the Site-Wide Inspection are provided as **Attachment B**. No significant deficiencies were noted during the inspection.

Please feel free to contact me at (585) 478-3167, or via email at lreid@neu-velle.com, with any questions you may have regarding this report, or contact Mr. Jeremy Wolf, RG&E's Project Manager for the project at (585) 500-8392.

Sincerely,

Logan Reid NEU-VELLE, LLC

Attachment A - 2024 Site Inspection Form

Attachment B – 2024 Site-Wide Inspection Photographs

cc: Mr. Jeremy Wolf, RG&E

Attachment A Site Inspection Form



SITE INSPECTION FORM

Brockport Former Manufactured Gas Plant Site

| SITE INSPECTION | ON DATE: 4/16/2 | 024 TIM | E OF ARRIVAL: | 12:00 |
|----------------------------------|--|---|----------------------|---------------------------|
| | ~ ~ ~ B . | | DEPARTURE: | 15:30 |
| WEATHER: | 65-70°F | SUNNY lie | ht breeze | |
| Site Inspector | (s) and Affiliation: | | RothAss -N | yev- whe |
| INSPECTION TY | PE: | Annual Inspect | on or Emergency Ir | snection |
| (if an emergen | cy describe the event t | | | Annval |
| | ional Controls in place comply with NYSDEC-ap | | | ı effective? (res) No |
| | | .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | |
| properties? | ations of encroachme | | | (Yesv/ No |
| MW' | 15 is associa of Petrolevi | ited with | a still res | sulting in |
| 1-3 ++ | of Petrolevi | n product | inside wel | (|
| Has ownersnip | of the property chang | ed since the las | t inspection? | Yes / 🔞 |
| | | VIII. | | |
| Are there any of the SMP or Inst | changes to the site use titutional Controls? | (Restricted Res | idential) that would | l affect Yes(No) |
| | | | | |
| Is site used for | agricultural purpose o | r vegetable gard | lens? | Yes /No |
| ls groundwater | used as source of pota | able or process | water onsite? | Yes (No |
| If yes to the about treatment? | ove – does water go th | rough the nece | ssary water quality | Yes/No |

SITE INSPECTION FORM Brockport Former Manufactured Gas Plant Site

| (tar, stained soil) visible? | Yes/No |
|--|----------------|
| Is the vegetative cover fully intact over the site soils? (Yes)/ No | Yes/No |
| are the Engineering Controls in place, performing properly, and remain effective | e? |
| Surface Cover Intact (I.e. no evidence of erosion, excavations)? | (Yes) No |
| | |
| GENERAL SITE OBSERVATIONS: Have there been any changes to the property since the last inspection? (e.g. new | / natural gas |
| Regulator equipment or facilities, changes in site topography, erosion, vegetative | e cover. etc.) |
| No Changes to the site | |
| | |
| NOTE: Inspections should be made a minimum and a second at the second | |
| NOTE: Inspections should be made a minimum once a year and within 5 days or emergency, such as a natural disaster or an unforeseen failure or damage to the occurs. Inspections will be conducted by RG&E (or their agent) and results repo NYSDEC. | e building |
| COMPLETED BY: Andrew Potefus REVIEWED BY: Albert | 6. Lyons, |
| SIGNATURE: A. Pontoto SIGNATURE Alle S. | Jan L |

Attachment B Site Photographs





Photo 1 – Looking northwest at the northwestern portion of the Site.



Photo 2 – Looking east across the northern portion of the Site and the northerly adjacent NYS Canal Corporation property.



Photo 3 – Looking south across the central portion of the Site.



Photo 4 – Looking east across the Site.



Photo 5 – Looking southeast across the central portion of the Site.



Photo 6 – Looking southwest across the Site.



Photo 7 – Looking northeast across central portion of the Site, MW-20 visible in foreground.