

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



Joe Martens

Commissioner

INSPECTION REPORT

Site Number: V00685

Date: February 28, 2012

Site Name: Excelsior Steel Ball

Location: 303 Woodward Ave. Tonawanda, N.Y.

Project Manager; Site Management: Brian Sadowski

Site Owner: Erie County. Contact: Kenneth J. Swanekamp

RP Consultant: Unknown

Job Phone: None

Weather: Cloudy, ~35 degrees F.

HEALTH & SAFETY: Level D

DESCRIPTION OF WORK PERFORMED: Site inspected. The site is mostly landlocked and surrounded on the north, west and south sides by the Praxair Tonawanda facility. The east side of the site is bounded by the CSX rail line. Frontage on Woodward Avenue is approximately 20 feet. The frontage is used as an access road to the site. Travel is about 210 feet before the area opens to the site property. The site was level with a mixed ground surface cover of gravel and dormant vegetation of variable lengths. Two groundwater micro-wells were observed. One was intact at approximately four feet in height. The second was damaged that was possibly hit by a mower or other vehicle. Groundwater quality or hydraulic monitoring is not required. The site otherwise appeared undisturbed. All ICEC's are in place.

Attachments: Photos

Inspector's Name (Print): Brian Sadowski

Date: March 2nd, 2012



Cover-1



Cover-2



Micro-Well



Sheared Micro-Well



Site When Inspected