






- Legend**
- Aquatic Vegetation Survey
 - Emergent Aquatic Vegetation
 - Subemergent Aquatic Vegetation
 - Remedy Alternative 3 Footprint
 - Remediation Type
 - Dredge
 - Cap

Notes:
 --Aquatic vegetation provided by MACTEC 2008
 --Aerial imagery provided by ESRI online services 09/2009





Legend

Aquatic Vegetation Survey

--- Emergent Aquatic Vegetation

--- Submergent Aquatic Vegetation

Remedy Alternative 4 Footprint

Remediation Type


Dredge


Cap

Notes:

--Aquatic vegetation provided by MACTEC 2008

--Aerial imagery provided by ESRI online services 09/2009





Legend

Aquatic Vegetation Survey

Emergent Aquatic Vegetation

Submergent Aquatic Vegetation

Remedy Alternative 5 Footprint

Remediation Type


Dredge

Cap

Notes:


--Aquatic vegetation provided by MACTEC 2008

--Aerial imagery provided by ESRI online services 09/2009




REMEDY ALTERNATIVE 5 - REMEDIATION LIMITS AND AQUATIC VEGETATION SURVEY BUFFALO, NY


**Figure
6-1c**



Remedy Alternative 5: Vertical Profiles of Total PAH Concentrations for the Buffalo River, Buffalo, NY


Figure 6-2a






Remedy Alternative 5: Vertical Profiles of Mercury Concentrations for the Buffalo River, Buffalo, NY


Figure 6-2c





Remedy Alternative 5: Vertical Profiles of Total PCB Concentrations for the Buffalo River, Buffalo, NY

Figure 6-2d














Legend

Shoreline Characteristics

- Capped Piles/Walls
- Uncapped Piles/Walls
- Sloped Stone
- Docks

Remedy Alternative 4 Footprint

Remediation Type

- Dredge
- Cap

Notes:

--Aerial imagery provided by ESRI online services 09/2009



**REMEDY ALTERNATIVE 4 - REMEDIATION LIMITS AND
EXISTING SHORELINE CHARACTERISTICS
BUFFALO, NY**

**Figure
6-4b**



Legend

Shoreline Characteristics

- Capped Piles/Walls
- Uncapped Piles/Walls
- Sloped Stone
- Docks

Remedy Alternative 5 Footprint

Remediation Type

- Dredge
- Cap

Notes:

--Aerial imagery provided by ESRI online services 09/2009

