

LEGEND

- DESTROYED MONITORING WELLS
- INTERIOR MONITORING WELL (INSIDE THE BUILDING)
- DEEP/SHALLOW MONITORING WELL CLUSTER
- SHALLOW MONITORING WELL
- SM INTERIOR SUMP
- FENCE LINE
- D APPROXIMATE LOCATION OF DRAIN SPOUT
- APPROXIMATE VICINITY OF PREVIOUS EXCAVATED & STOCKPILED SOILS
- ROW RIGHT OF WAY
- M SEWER MANHOLE (APPROX 12' DEEP)
- ST UNDERGROUND STORM SEWER
- TOC TOP OF CASING ELEVATION (feet)
- DTW DEPTH TO WATER (feet)
- GW EL GROUNDWATER ELEVATION (feet)
- 16.53 GROUNDWATER CONTOUR LINE (feet)

MW	TOC	DTW	GW EL
9D	20.49	3.98	16.51
11D	20.75	4.20	16.55
13D	19.99	3.56	16.43

DRAFTED BY: W.G.S. (N.J.)

CHECKED BY:

REVIEWED BY:

NORTH

SITE GROUNDWATER CONTOUR MAP
DEEP MONITORING WELLS
JULY 28, 2003

COMPREHENSIVE REMEDIAL INVESTIGATION REPORT
STANDARD MOTOR PRODUCTS, INC. SITE
LONG ISLAND CITY, NEW YORK

CDM

SCALE IN FEET 0 50

DATE 1-29-04

FIGURE 3-16