New York State Department of Environmental Conservation
Division of Environmental Remediation
Remedial Bureau C, 11th Floor

Alexander B. Grannis
Commissioner

DAILY INSPECTION REPORT

Site Code #:546033	**Date: May 26, 2010**	**Report #:**

Site Name: Mechanicville Central Ave. MGP
Location:
PRP Proj. Mgr.:
DEC Proj. Mgr.:
Consultant Proj. Mgr.:
Proj. Contr.:
Site Phone & Fax:

	AM	PM
Weather		sunny
Temperature		90s F
Wind Direction		calm

No contractors on site. I visited site at 3:30 pm to see how plantings were coming along. Clover has taken over bank. Where seeps are occurring, which are areas along the lower bank, grass is weakly established. Maples look good. The other varieties have leaves, but on many the leaves are only on a portion of the tree.

The seeping in the Anthony Kill was only found in one spot, the area between the stones with the arrows painted on them, about 3 feet from shoreline. Shoreline was the bottom edge of placed riprap. Hard to spot, I only saw sheen when the sun was behind me. It would appear as a floating sheen about palm size and would last about one to two seconds. I observed for about ten minutes and saw about 8 sheens.

I disturbed the sediment around the bank in the area between the arrows. No sheens were produced. I left site at 4:00pm

Representative: John Spellman **Date: May 27, 2010**

Representative's signature:









