Emerging Contaminant Sampling Initiative
EC Form 1: Initial Groundwater Sampling Results Evaluation

Site Name: Verona Research Facility Site ID: 633046

Date(s) Sampled: 10/21/20 Class: 4

Number of Monitoring Wells: 7 (attach figure showing sampling locations)

Groundwater Screening

Chemical	Screening level (DWQC Recommended MCL)	Max. concentration detected	Check box if level exceeded
1,4-dioxane in groundwater	1 ug/L (ppb)	ND	☐
PFOA in groundwater	10 ng/L (ppt)	4.2	☐
PFOS in groundwater	10 ng/L (ppt)	11	☑
Awareness			
Other PFAS (**not** PFOA/PFOS)	Any one compound over 100 ng/L	10 (PFBA)	☐
Total PFAS (incl. PFOA/PFOS)	Total concentration over 500 ng/L	26.4	☐

STOP here if no screening levels are exceeded. No further action required at this time.

Proximity to Water Supplies

Water supply type	Any wells within ½ mile of site?	Distance (ft)	Method(s) used to confirm water supply well locations
Public well(s)	1	1320	DEC GIS mapper
Private well(s)	19	660 (closest)	DEC GIS mapper

If water supply wells are confirmed within ½ mile of site, discuss need for sampling these supply wells with DOH. Create a *EC Water Supply Sampling* project in UIS to track drinking water sampling efforts as directed.

Apparent Source(s)

Chemical	Past use or storage of chemical on-site?	Describe reasons for suspecting apparent source(s)
1,4-dioxane	possibly	formerly active federal testing facility (electronics)
PFAS	possibly	formerly active federal testing facility (electronics)

If an apparent on-site source is suspected, incorporate further work into ongoing remedial program if possible.

Further action required at this time? ☐ Yes ☑ No

Use the box at the bottom of page 2 to summarize site-specific next steps or provide rationale for not recommending further action if screening levels are exceeded.

Jenelle Gaylord
Digitally signed by Jenelle Gaylord
Date: 2021.03.26 11:42:07 -04'00'
Project Manager

Jeffrey Dyber
Digitally signed by Jeffrey Dyber
Date: 2021.03.26 09:28:36 -04'00'
Section Chief

Michael J Cruden
Bureau Director

3/25/2021
Date Signed

Emerging Contaminant Sampling Initiative
EC Form 1: Initial Groundwater Sampling Results Evaluation

Checklist for Completing EC Form 1:

- ☑ Did you include a value in "Maximum Level Detected" even if the screening levels were not exceeded?
- ☑ Did you enter "ND" if nothing detected or "NA" if not analyzed?
- ☑ Did you check your units (ug/L vs ng/L)?
- ☑ Did you include PFOA & PFOS when totaling "Total PFAS"?
- ☑ Did you check yes or no for "Is further action required at this time?"
- ☑ Did you include "next steps", or provide justification for not recommending further action, if RMCLs are exceeded?
- ☑ Did you attach a figure with sampling locations?
- ☑ Did you attach emerging contaminant data? (not the full data package—only enough for all reviewers to double check that the form is filled out properly)
- ☑ Did you read through the internal DER Emerging Contaminant website for guidance on what to do if you have exceedances?
- ☑ Did you check with DOH-BEEI to help confirm the existence of public and private drinking water wells? DOH will handle communications with public water suppliers and local health departments.
- ☑ Is the data in EQuIS?
- ☑ Did you complete the UIS EC project current status per the internal DER Emerging Contaminant website?

This form is to be uploaded to DecDocs when completed. A copy of the signed form is to be sent to Caryn Bower (OGC) and Eric Hausamann (DER Bureau D/Sec D).

Site-specific next steps or rationale for not recommending further action

The exceedance was barely over our standards and the public well is upgradient of the site, DOH concurrence that no additional sampling is required.

TABLE 1
SUMMARY OF ANALYTICAL RESULTS - EMERGING CONTAMINANTS IN GROUNDWATER
VERONA RESEARCH FACILITY
GERMANY ROAD, VERONA, NEW YORK
NYSDEC SITE NO. 633046

Compound	NYSDEC Groundwater Standards/ Guidance Values	SAMPLE ID/DATE							
		TPW-33R	B1231-MW-03	B1243-W05	MW-1253 IR	B1219-W06	B-54 B1266-W12	TPW-14	DUP*
		10/21/20	10/21/20	10/21/20	10/21/20	10/21/20	10/21/20	10/21/20	10/21/20
EPA Method 8270									
1,4-Dioxane	1,000	ND	ND	ND	ND	ND	ND	ND	ND
PFAS - Modified 537									
Perfluorobutanoic acid (PFBA)	100	1.8 J	10	2.0 J	ND	7.4	4.9	ND	10
Perfluoropentanoic acid (PFPeA)	100	ND	2.2	ND	ND	ND	ND	ND	2.2
Perfluorohexanoic acid (PFHxA)	100	0.75 J	2.4	ND	ND	ND	ND	ND	2.4
Perfluoroheptanoic acid (PFHpA)	100	0.50 J	2.5	0.44 J	ND	0.60 J	0.54 J	ND	2.8
Perfluorooctanoic acid (PFOA)	10	1.3 J	3.3	4.2	ND	1.3 J	1.7	ND	3.5
Perfluorononanoic acid (PFNA)	100	ND	1.0 J	ND	ND	ND	ND	ND	1.1 J
Perfluorododecanoic acid (PFDoA)	100	ND	ND	ND	ND	ND	ND	0.62 J-	ND
Perfluorobutanesulfonic acid (PFBS)	100	0.71 J	0.96 J	ND	ND	0.71 J	1.0 J	ND	1.1 J
Perfluorohexanesulfonic acid (PFHxS)	100	3.8	1.5 J	5.0	ND	ND	1.1 J	ND	1.3 J
Perfluorooctanesulfonate acid (PFOS)	10	6.0	1.9	**11**	1.8	0.94 J	4.5	ND	2.0
1H, 1H, 2H, 2H-perfluorooctanesulfonic acid	100	ND	ND	ND	1.1 J	ND	ND	ND	ND
Total Compounds	500	14.86	25.76	22.64	2.90	10.95	13.74	0.62 J	26.40

NOTES:
- All results reported in ng/L (parts per trillion)
- All analytical results have been validated by NYSDEC personnel (Attachment 1).
- ND = Compound not detected above method detection limit
- J = Estimated concentration between the method detection limit (MDL) and the reporting limit (RL).
- J- = The analyte was positively identified; the associated numerical value is an estimated quantity that may be biased low.
- Boldfaced font/highlighted cell indicates exceedance of the applicable NYSDEC Guidance Value

* Duplicate collected at well B1231-MW-03

PRECISION ENVIRONMENTAL SERVICES, INC
831 NYS Route 67, Lot 38A
Ballston Spa, NY 12020
518-885-4399

General Site Map

Date: November - 2020

Not to Scale

Germany, Road
Verona, NY

Updated By : JJJ

Figure: 2

LEGEND

B1243-W05 - Groundwater Monitoring Well Location

*Sampled on 10/21/20 - Not necessarily representative of all onsite monitoring wells.

Groundwater Elevation

Sample ID	Casing Elevation	Depth to Water	Groundater Elevation	Sample ID	Casing Elevation	Depth to Water	Groundater Elevation
Unknown	445.60	2.37	443.23	B1243-WO5	451.86	8.48	443.38
1266-WO7R	447.83	1.45	446.38	B1287-W08	447.37	0.99	446.38
B-39/GPW-39	450.09	2.90	447.19	B50/GPW-50	464.49	4.50	459.99
B-40/GPW40	447.80	2.83	444.97	B53/B1266-W10	448.27	1.94	446.33
B-41/GPW-41	447.81	2.16	445.65	B55/B1266-W11	448.76	2.34	446.42
B-52/BN1219-W09	449.00	2.65	446.35	PZ4	448.82	2.32	446.50
B-54/B1266-W12	450.59	4.26	446.33	TP-13/TPW-13	446.94	2.58	444.36
B1219-W06	449.28	2.91	446.37	TP-20/TPW-20	445.64	3.03	442.61
B1227-W02	446.51	2.50	444.01	TP26/TPW-26	449.88	3.27	446.61
B1231-W03	444.61	0.60	444.01	TP33/TPW-33R	450.09	5.26	444.83
B1231E	447.40	3.72	443.68	TPW-14	448.91	2.56	446.35



DATE: JANUARY 2014

SCALE: 1 inch= 500 feet

DRAWN/CHECKED: SMK/GLA

DATA SOURCE:
NYS GIS CLEARINGHOUSE
ORTHOIMAGERY

SITEWIDE GROUNDATER CONTOUR
VERONA RESEARCH FACILITY
VERONA, NY

Lu Engineers
ENVIRONMENTAL • TRANSPORTATION • CIVIL