

Newsday
235 Pinelawn Road
Melville, New York 11747

PHASE I ENVIRONMENTAL SITE ASSESSMENT

OCTOBER 8, 2018

PREPARED FOR:
Hartz Mountain Industries, Inc.
400 Plaza Drive, P.O. Box 1515
Secaucus, NJ 07096
Attn: Mr. Curtis L. Michael

PREPARED BY:
The Vertex Companies, Inc.
3322 Route 22 West, Suite 907
Branchburg, NJ 08876
PHONE 908-448-2627

VERTEX PROJECT NO: 51921

October 8, 2018

Hartz Mountain Industries, Inc.
400 Plaza Drive, P.O. Box 1515
Secaucus, NJ 07096-1515
Attn: Curtis L. Michael

RE: Phase I Environmental Site Assessment
Newsday
235 Pinelawn Road
Melville, New York 11747
VERTEX Project No. 51921

Dear Mr. Michael:

The Vertex Companies, Inc. (VERTEX) is pleased to submit this Phase I Environmental Site Assessment (ESA) report for the above referenced property (the site). The purpose of this assessment was to identify Recognized Environmental Conditions (RECs) in connection with the site. A REC is defined as "the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment." It does not include *de minimis* conditions that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Our work was conducted in general conformance with proposal P.1728.18, executed by Mr. Curt L. Michael on July 26, 2018, and in accordance with the general provisions of the E 1527-13 American Society for Testing and Materials (ASTM) document entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" for commercial real estate, as well as the U.S. Environmental Protection Agency's (USEPA) All Appropriate Inquires (AAI) Final Rule of November 1, 2005, as amended December 30, 2013. To the best of our knowledge, this Phase I ESA report is true and accurate.

VERTEX also assessed the site for the potential presence of asbestos-containing materials (ACMs) and lead-based paint (LBP).

We declare that, to the best of our professional knowledge and belief, we meet the definition of an Environmental Professional as defined in 40 C.F.R. Part 312.10. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312.

Please do not hesitate to contact us at your convenience should you have any questions or comments regarding this report or our recommendations. It has been a pleasure working with you on this project.

Sincerely,

The Vertex Companies, Inc.





Christopher K. Cook
Senior Project Manager

Stephen P. McCarthy
Vice President – Due Diligence

TABLE OF CONTENTS

1.0 SUMMARY 1

2.0 SITE AND VICINITY CHARACTERISTICS 9

2.1 Site Description 9
2.2 Site Improvements 9
2.3 Tenant Operations 10
2.4 Current Uses of Adjoining Properties 10
2.5 Physical Setting Source(s) 11
2.5.1 Topography 11
2.5.2 Surface Water 12
2.5.3 Geologic Conditions 12
2.5.4 Groundwater 12

3.0 USER-PROVIDED INFORMATION 13

4.0 INTERVIEWS 14

5.0 HISTORICAL RECORDS REVIEW 15

5.1 Historical Site Use Summary 15
5.2 Historical Adjoining Properties Use Summary 15
5.3 Previous Environmental Reports 16
5.4 Prior Ownership 21
5.5 City Directories 22
5.6 Aerial Photography 23
5.7 Topographic Maps 25
5.8 Sanborn Fire Insurance Maps 26

6.0 REGULATORY RECORDS REVIEW 27

6.1 On-Site Listings 29
6.2 Off-Site Listings 33
6.3 Additional Environmental Record Sources 35

7.0 SITE RECONNAISSANCE 44

7.1 Access Restrictions 44
7.2 Site Observations 44

8.0 DATA GAPS/DEVIATIONS 56

9.0 ADDITIONAL SERVICES 57

9.1 Asbestos-Containing Materials (ACMs) 57
9.2 Lead-Based Paint (LBP) 58

10.0 CONCLUSIONS 59

11.0 SCOPE AND LIMITATIONS 61

11.1 Purpose 61
11.2 Detailed Scope-of-Services 62
11.3 Significant Assumptions 64
11.4 Limitations and Exceptions 65
11.5 Special Terms and Conditions 66
11.6 User Reliance 66

12.0 REFERENCES 68

FIGURES

Figure 1 Site Locus Map
Figure 2 Site Schematic

APPENDICES

Appendix A: Photographic Documentation
Appendix B: Relevant Documents
Appendix C: City Directories
Appendix D: Aerial Photographs
Appendix E: Topographic Maps
Appendix F: Sanborn Fire Insurance Maps
Appendix G: Regulatory Database Report
Appendix H: Resumes of Environmental Professionals

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Newsday
235 Pinelawn Road
Melville, New York 11747
VERTEX Project No. 51921

1.0 SUMMARY

On July 26, 2018, The Vertex Companies, Inc. (VERTEX) was contracted by Hartz Mountain Industries, Inc. to conduct a Phase I Environmental Site Assessment (ESA) of the Newsday facility located at 235 Pinelawn Road, Melville, New York (the site). According to the Town of Huntington Assessor's Office, the site consists of two parcels of land totaling 53.17 acres, which are identified Tax Map Numbers 0400-270.00-01.00-008.001 and 0400-270.00-01.00-024.001. The site is improved with a one and two-story Newsday facility (main building), a wastewater treatment plant (WWTP) building, and three guard shacks. The main building was constructed in 1978 and 1986 and consists of approximately 523,000 square feet of space. The site currently is owned by Tribune ND Inc. Newsday currently leases the site from Tribune ND, Inc.

The purpose of this assessment was to identify Recognized Environmental Conditions (RECs), including controlled RECs (CRECs) and Historical (HRECs), in connection with the site as part of due diligence activities related to the planned acquisition of the site.

ASTM Findings

- According to available historical information, the site was primarily unimproved agricultural land with farm-related structures from the late 1800s to the mid-1970s. An unpaved road also traversed the site from at least the 1940s to early 1970s. The original portion of the current site building was constructed in 1978, which was expanded in 1986 bringing the site building into its current configuration. The site building has been occupied by Newsday since it was developed. Operations included newspaper printing until June 2018, when the

operations were reduced to administrative and packaging only. The historic printing operations from 1978 to June 2018 are considered a REC.

- The site is utilized by Newsday as a newspaper production facility. Operations at the time of site inspection included newspaper packaging and administrative functions. Newspaper printing operations were discontinued in June 2018. Hazardous substances and petroleum products utilized at the site include printing press oils, fuel oil, diesel fuel, and other general maintenance materials and lubricants. These products are stored within underground storage tanks (USTs), aboveground storage tanks (ASTs), 55-gallon drums, or smaller containers.

- At the time of site inspection, VERTEX observed a hazardous materials storage shed to the north of the WWTP. Several 55-gallon drums of press waste oil were observed within the shed. The shed appeared contained with no evidence of releases. The shed was historically utilized for the storage of hazardous substances. Given the historical use of the shed without documentation of subsurface investigations, it is considered a REC.

- Numerous ASTs were observed during the site inspection. Many of these ASTs have been emptied since printing operations are no longer performed on-site. Chemicals currently or formerly stored within these ASTs included diesel fuel, ink, parts washer solvent, water treatment chemicals, lube oil, methanol, hydraulic fluid, fountain solution, and press waste oil. According to the site contact, 60 ASTs are in the process of being decommissioned and will be removed from the site in near future.

- Four USTs are currently located at the site including three 20,000-gallon diesel fuel USTs that were previously utilized to fuel company vehicles (southern fueling area) and one 2,500-gallon No. 2 fuel oil UST associated with an emergency generator (western emergency generator area). The diesel fuel USTs were empty at the time of site inspection and are no

longer utilized. The No. 2 fuel oil UST was in operation and is used to power an emergency generator. Reportedly, the USTs recently passed tank tightness testing. No releases have been reported in associated with these USTs, which were installed in 2010 (diesel USTs) and 1987 (No. 2 fuel oil). These current USTs are considered an environmental concern.

- Records reviewed indicate 11 USTs were formerly in operation at the site. These included three 20,000-gallon diesel fuel USTs (Tanks 1-3), one 12,000-gallon gasoline UST (Tank 4), one 2,000-gallon spill containment/solvent UST (Tank 5), one 25,000-gallon No. 6 fuel oil UST (Tank 6), one 25,000-gallon No. 2 fuel oil UST (Tank 7), one 4,000-gallon spent fixer and developer waste UST (Tank 8), and three 20,000-gallon diesel fuel USTs (Tanks 14-16).

  Tanks 1 through 4 were located to the northeast of the fire suppression pond in a former fueling station area. These USTs were installed in 1978 and removed in 1986 prior to building expansion activities. No closure documentation associated with these former USTs was identified during this assessment. These former USTs without closure documentation are considered a REC. However, the USTs were located under a current structure, shallow impacted soils, if present, would have likely been removed during building expansion activities.

  Tank 5 was located to the east of the fire suppression pond in the area of the current 2,500-gallon diesel fuel UST. The UST was installed in 1979 and reportedly closed by removal in 1988. No additional details on this former UST was provided. This former UST without closure documentation is considered a REC.

  Tanks 6 and 7 were installed in 1978 and abandoned in place in 2014. These tanks are located to the southeast of the site building. A tank tightness test was performed on these tanks in 2012, which resulted in a failed leak test (Spill #1203029). According to a subsequent spill closure report, concentrations of contaminants were found below cleanup levels. Therefore, the New York State Department of Environmental Conservation (NYSDEC) closed the tanks

and spill case on April 7, 2014 without requiring remedial action. These USTs and associated spill case are considered a HREC.

Tank 8 was located to the southeast of the site building before basement boiler room expansion, which now covers the location of this former tank. The UST was installed in 1978 and was closed by removal in 1989. According to information obtained, this tank was removed with no evidence of releases identified.

Tanks 14 through 16 were located in the area of the current fueling station on the southern portion of the site. These tanks were installed in 1985 and closed by removal in 2010. During removal of these USTs, impacted soil was identified triggering Spill #1000551. Impacted soils were removed during closure and a subsequent soil sampling investigation did not find impacts over cleanup standards. Therefore, the NYSDEC closed the spill case on March 30, 2011. These USTs and associated spill case are considered a HREC.

- In addition to the two spill incidents described above, 18 additional spill incidents were reported at the facility from 1989 to 2017. These incidents were primarily associated with releases from generators, fuel tanks, wastewater treatment operations, and ink tanks. All of these spill incidents were remediated and closed by the NYSDEC with no further action required. Based on the case closed status, these former spill incidents are considered HRECs.

- A WWTP is currently located on the western portion of the site. Wastewater generated from current and former operations is/was discharged through floor drains to an oil/water separator before treatment at the WWTP. The wastewater is treated using a combination of pre-equalization screens, rotary aerators, membrane clarifiers, and sludge settling tanks. Treated wastewater is discharged to underground cistern systems including 11 underground leaching pools to the west of the WWTP and to discharge leaching basins to the north of the WWTP. The WWTP area appeared to be in good condition at the time of site inspection. However, according to the State Pollution Discharge Elimination System (SPDES) permit

documentation provided, several discharge outfall exceedances were reported historically including 1,1,1-trichloroethane (TCA), 1,2,4,5-tetramethylbenzene, 1,3,5-trimethylbenzene, benzene, cyanide, flow, total nitrogen, oil and grease, p-ethyltoluene, pH, total recoverable phenolics, silver, total dissolved solids, toluene, total toxic organics, and xylenes. Given the historical exceedances of wastewater discharge allowable limits to leaching basins, the operations of the WWTP are considered a REC.

- Numerous stormwater dry wells are located on-site, primarily in parking areas and driveways. In addition, three dry wells were observed in the ventilated basement area. These dry wells are part of the existing SPDES permit. Staining was observed on concrete in the area of one dry well located in the southern ventilated basement area. The staining observed adjacent to this dry well is considered a REC.

- Septic systems including septic tanks and leaching fields are located adjacent to guard houses located on the southeastern and northern portions of the site. Discharges to these septic systems are limited to guard shack restrooms. Based on the sanitary nature of the discharge directed to the septic systems, they do not represent a REC.

- A closure workplan for the Resource Conservation and Recovery Act (RCRA) permitted hazardous waste areas was approved by the NYSDEC on August 10, 2018. RCRA closure activities will reportedly be completed in the near future. Closure activities will include the removal of all hazardous wastes, decontamination of the hazardous waste storage areas, confirmatory rinsate and subsurface soil sampling, and removal of all wastes generated during closure.

- The site is identified on numerous databases in the Environmental Data Resources, Inc. (EDR) database report associated with tanks, hazardous waste generation, air compliance, spill incidents, and wastewater discharges. Concerns associated with former tanks, hazardous,

waste, spill incidents, and wastewater discharges are described above. No active violations associated with regulatory permits or open release cases were identified. Refer to Section 6.1 for additional discussion of these listings.

- The site is located in an area of commercial and residential properties. VERTEX conducted a regulatory review that included a search of state and federal regulatory databases to identify environmental concerns for the site and surrounding properties. Numerous facilities were identified within the ASTM search distances of the site. Based on distance, apparent gradient relationship, regulatory status, and/or other facility-specific characteristics, no RECs in connection with the site were identified with respect to these facilities.

Non-ASTM Additional Services

In accordance with the scope of work, VERTEX conducted additional services as discussed in Section 9.0 of this report, including the assessment of: asbestos-containing materials (ACMs) and lead-based paint (LBP). The following Business Environmental Risks (BERs) were identified during this assessment:

- Suspect ACMs were identified within the site building, which included thermal systems insulation, pipe wrap, ceiling tile, vinyl floor tile and associated mastics, and wallboard. These materials appeared to be in primarily good condition. During an ACM survey completed in June 2018, regulated ACMs (greater than 1% asbestos) were identified within the site building including vinyl floor tile mastic and adhesives. These materials were found in undamaged, non-friable condition. Materials found to contain less than 1% asbestos included black mastic and spray-on fireproofing.

Conclusions

VERTEX has performed a Phase I ESA in conformance with the scope and limitations of ASTM E 1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, of the Newsday facility located at 235 Pinelawn Road, Melville, New York. Any exceptions to, or deletions from, this practice are described in Section 8.0 of this report. This assessment has revealed no evidence of RECs in connection with the site, except for the following:

- Historical printing operations on-site from 1978 to 2018.
- Former diesel fuel and gasoline USTs located to the northeast of the fire suppression pond, which were removed in 1986. No closure documentation associated with these USTs was provided.
- A former 2,000-gallon spill containment/solvent UST to the east of the fire suppression pond, which was removed in 1988. No closure documentation associated with this UST was provided.
- Historical wastewater discharge exceedances to on-site leaching basins.
- Staining adjacent to the dry well located in the southern basement area.
- The historical use of the hazardous materials storage shed.

The following HRECs were identified during this assessment:

- Twenty spill cases from 1989 to 2017, which have been closed by the NYSDEC. These include releases associated with USTs removed or abandoned in place in 2010 and 2014.

The following environmental concerns were identified during this assessment:

- The three 20,000-gallon diesel fuel USTs and one 2,500-gallon No. 2 fuel oil UST located at the site.
- The two 25,000-gallon fuel oil USTs, which were abandoned in place in 2014.
- The stormwater dry wells located throughout the site.
- The active WWTP at the facility.
- Ongoing RCRA closure activities at the site.

Based on the findings of this assessment, VERTEX recommends the following:

- A subsurface investigation should be completed to evaluate subsurface soil and groundwater quality.
- The active USTs should be closed by removal in accordance with applicable regulations.
- The 25,000-gallon fuel oil USTs previously abandoned in place should be removed as part of site redevelopment activities.
- If the stormwater dry wells will be removed during site redevelopment, they should be closed in accordance with applicable regulations.
- During site redevelopment activities, the current septic systems should be abandoned in accordance with applicable regulations.
- The WWTP operations and associated permits should be transferred to future owners of the property. If the WWTP will no longer be utilized, it should be closed in accordance with applicable regulations.
- The RCRA Closure Plan should be implemented and completed with no further action by the NYSDEC.
- Prior to demolition, an ACM survey should be completed to supplement the previous ACM survey completed at the site in 2018. Suspect or known ACMs should be appropriately managed prior to demolition activities in accordance with applicable regulations.

2.0 SITE AND VICINITY CHARACTERISTICS

2.1 Site Description

The site is located at 235 Pinelawn Road, Melville, New York. According to the Town of Huntington Assessor's Office, the site consists of two parcels of land totaling 53.17 acres, which are identified Tax Map Numbers 0400-270.00-01.00-008.001 and 0400-270.00-01.00-024.001. The site location is shown on Figure 1 - Site Locus Map.

2.2 Site Improvements

The site is improved with a one and two-story Newsday facility (main building), a WWTP building, and three guard shacks. The main building was constructed in 1978 and 1986 and consists of approximately 523,000 square feet of space situated on the central portion of the site. The main building is constructed of steel framing with concrete block, corrugated metal, exterior finishes and a flat roof on a primarily slab-on-grade foundation. A small section of the eastern portion of the main building is underlain by a basement. Interior finishes in the main building consist of ceiling tiles, wallboard, vinyl floor tile, wood, carpet, and concrete. Cooling for the main building is provided by heating, ventilation and air conditioning (HVAC) units located on the roof of the building. Heating is provided by boiler systems, which utilize No. 2 fuel oil.

The WWTP building was constructed in 1978 and consists of approximately 900 square feet of floor space situated on the western portion of the site. The WWTP building is constructed of steel framing with concrete block exterior finishes and a flat roof on a slab-on-grade foundation.

Three guard shacks are located on the northern, west-central, and southeastern portions of the site. These buildings were constructed in the 2000s and consist of less than 600 square feet of combined floor space.

Exterior areas include asphalt-paved parking areas and driveways, a WWTP and associated tanks, aerators, and membranes, storage sheds, landscaped areas, concrete sidewalks, a ball field, loading areas, emergency generators, tanks, and a truck fueling area. The site is surrounded by fencing. For a layout of the site, please refer to Figure 2 – Site Schematic. Photographic documentation of the site and surrounding areas is presented in Appendix A.

2.3 Tenant Operations

The site is currently utilized by Newsday for newspaper packaging and administrative functions. Printing operations at the facility ceased on June 9, 2018. The administrative areas are primarily located within the northern and eastern portions of the main building. The central and northwestern portions of the building include numerous printing presses, which were out of operation during the inspection. The southern portion of the main building primarily includes packaging, loading, and storage areas. The WWTP is utilized treat and dispose of wastewater generated at the site and the guard shacks are utilized for security.

Hazardous substances and petroleum products utilized at the site include various oils, diesel fuel, No. 2 fuel oil, and other general maintenance and lubrication products. These products are stored within USTs, ASTs, 55-gallon drums, or smaller containers. Refer to Section 7.2 for additional information on the current use of hazardous substances and petroleum products associated with site operations.

2.4 Current Uses of Adjoining Properties

The site is located in a commercial and light industrial area. Adjoining properties were observed (from the site or from public access areas) for signs of RECs and their potential to pose an environmental concern to the site. The uses and features of adjoining properties are described

in the following table. The locations of these properties relative to the site are depicted on Figure 2 – Site Schematic.

NEARBY/ADJOINING PROPERTY SUMMARY		
DIRECTION	**PROPERTY USE**	**CONCERNS**
North	Ruland Road, followed by an office building and wooded land.	None
Northeast	Half-Hollow Hills Racquet Club (100 County Route 5), followed by the intersection of Ruland Road and Pinelawn Road.	None
Northwest	Ruland Road, followed by residential areas.	None
East	Pinelawn Road, followed by Pinelawn Cemetery.	None
South	Three light industrial buildings including Clare Rose beer distributor (99 Marcus Drive), Baby King and Pet King (101 Marcus Drive), and a vacant building (103 Marcus Drive).	None
West	Deshon Drive, followed by a vacant light industrial building (80 Ruland Road), BAPS temple (2 Deshon Drive), and The Club at Melville Condominiums (25 Deshon Drive).	None

2.5 Physical Setting Source(s)

Physical setting sources specified in Section 12.0 of this report were reviewed to provide information about the geology and hydrogeology of the site.

2.5.1 Topography

A review of the 2013 United States Geologic Survey (USGS) Topographic Quadrangle Map of Huntington, New York indicates that the surface elevation of the site is approximately 100 to 110 feet above mean sea level. The topography of the site gradually slopes to the south and southeast. The surrounding properties slope to the southeast.

2.5.2 Surface Water

No naturally-occurring surface water bodies were observed on or adjoining the site. Based on the Federal Emergency Management Agency (FEMA), Flood Insurance Rate Map (FIRM) 3604970038F, the site is not located in a 100- or 500-year floodplain.

2.5.3 Geologic Conditions

According to the United States Department of Agriculture (USDA) Web Soil Survey, soils at the site consist of Haven, highly decomposed plant material. These soils are well drained with moderate infiltration rates. Bedrock outcrops were not observed during the site reconnaissance.

According to previous subsurface investigations completed at the site, fill materials in the form of crushed stone, sand, and gravel were present at the site to depths of four feet below grade. These fill materials were underlain by native sand and gravel with cobbles to depths of 26 feet below grade.

2.5.4 Groundwater

Based on surface topography and information obtained from previous subsurface investigations, groundwater is anticipated to flow to the southeast. Groundwater has been encountered at the site between approximately 38 and 46 feet below grade. Actual local groundwater flow direction can be influenced by factors such as local surface topography, underground structures, seasonal fluctuations, soil and bedrock geology, and production wells, none of which were considered during this study.

3.0 USER-PROVIDED INFORMATION

VERTEX requested the following information about the site from the Client (User):

- An evaluation of the presence of environmental cleanup liens for the site;
- Activity and use limitations (AULs) such as engineering controls (e.g., slurry walls, caps) and land use restrictions or institutional controls (e.g., deed restrictions, covenants) that may be in place for the site;
- Specialized knowledge that includes personal knowledge or experience related to the site or nearby properties based on professional experience or knowledge of the site;
- Fair market value (FMV) to evaluate whether the purchase price of any parcel was significantly below FMV;
- Obvious indicators that involve past or present spills, stains, releases, cleanups on or near the site;
- Common knowledge about use of specific chemicals, possible contamination, or past use of the site and surrounding area; and
- Reason for performing the ESA.

The Phase I ESA was conducted in support of the planned acquisition of the site. No other responsive information regarding the site was provided by the Client. VERTEX interviewed Mr. Stephen Zimmerman with Newsday, who provided information regarding environmental conditions of the site, which are discussed throughout this report. In addition, previous environmental reports and associated documentation were provided, which are generally discussed in Section 5.3.

4.0 INTERVIEWS

VERTEX conducted interviews regarding site history and the current on-site operations with the following individuals:

INTERVIEWS		
NAME/COMPANY	**TITLE/POSITION**	**INFORMATION PROVIDED**
Mr. Stephen Zimmerman / Newsday	Director Engineering Services	Provided information regarding site history and operations. Mr. Zimmerman escorted VERTEX during the site visit and answered questions regarding site operations.
Mr. Tim Winter / Newsday	Manager Security	Provided information regarding site history and operations. Mr. Winter escorted VERTEX during the site visit and answered questions regarding site operations.
Municipal Officials	Various	Provided municipal information.

Information obtained from these interviews is discussed in relevant sections of this report. Please refer to Section 6.3 for a summary of information obtained from municipal inquiries.

5.0 HISTORICAL RECORDS REVIEW

Past land uses for the site and adjoining properties were assessed to identify historical practices or conditions that may have impacted the site. This was accomplished by reviewing historical information from several sources including but not limited to interviews with site representatives, review of available previous environmental reports and ownership records, and review of historical information obtained from regulatory sources, aerial photographs, city directories, and historical maps.

5.1 Historical Site Use Summary

According to available historical information, the site was primarily unimproved agricultural land with farm-related structures from the late 1800s to the mid-1970s. An unpaved road also traversed the site from at least the 1940s to early 1970s. The original portion of the current site building was constructed in 1978, which was expanded in 1986 bringing the site building into its current configuration. The site building has been occupied by Newsday since it was developed. Operations included newspaper printing until June 2018, when the operations were reduced to administrative and packaging only. Given the length of former printing operations, the historical operations at the site are considered a REC.

5.2 Historical Adjoining Properties Use Summary

The site is in an area of commercial and residential properties. According to available historical information, the surrounding areas consisted of primarily unimproved agricultural land, residences, and roads from the late 1800s to 1960s. By the late 1960s, the current cemetery was developed to the east of the site. By 1970, light industrial development began to the south of the site, which increased in coverage through the 1980s. These structures have been occupied by distribution companies, publishing companies, and news companies. The current fitness center was developed to the northeast in the late 1970s. Light industrial development began to

the west in the 1970s and office building development began to the north in the 1990s. The light industrial building to the west at 25 Deshon Drive was historically occupied by Newsday. No environmental concerns associated with the current or historical uses of surrounding properties were identified during this assessment.

5.3 Previous Environmental Reports

VERTEX was provided with the following previous environmental reports for review:

Phase I Environmental Site Assessment – DRAFT, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated July 2017

At the time of this previous assessment, the site was operated by Newsday as a newspaper publishing and distribution company. Operations consisted of printing, plate development, digital photographic development, ink mixing, and newspaper sorting, bundling, and distribution. Newsday stored inks in ten ASTs and operated three large printing presses, five digital photo developing lines, and four plate development lines. Maintenance included cleaning plates and parts washing, and fluid replenishing for printing presses. Fueling of vehicles via the 20,000-gallon diesel fuel USTs was also performed on-site during this previous assessment.

Chemical storage areas included three bermed areas for fountain solution ASTs, press oil, and degreasers; ink AST storage rooms in the production area on the first floor, and an ink reclamation room and maintenance rooms on the second floor.

RPS identified the historical site operations (printing operations, wastewater discharge, historical release incidents) and an open release incident (compressor oil release in 2016) as RECs. According to RPS, no previous sampling was provided for three diesel fuel USTs, one gasoline UST, one spill containment UST, and an industrial waste UST.

RPS identified the three 20,000-gallon diesel fuel USTs closed in 2010 as a CREC. During removal, evidence of impacts was identified and reported to the NYSDEC. After additional investigation, the spill case and USTs were closed by the NYSDEC.

VERTEX generally concurs with this report with the following exceptions:

- The former 20,000-gallon diesel fuel USTs removed in 2010 and associated spill case with closure from the NYSDEC is a HREC, not a CREC.
- RPS did not identify dry wells at the site.
- RPS did not identify the current septic systems associated with the guard shacks.

Limited Phase II Investigation Report – DRAFT, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated March 8, 2018

RPS performed Phase II activities at the site in January 2018, which included six soil borings, five sub-slab soil vapor sampling points, three additional soil-gas sampling points, and two temporary monitoring wells. Borings were advanced to evaluate the historical industrial operations (two soil borings and five soil-gas sampling points), the WWTP/former USTs (one soil boring and one temporary monitoring well), presumed location of former gasoline and diesel fuel USTs (one soil boring and one soil-gas point), and areas to the north of the site building (two soil borings and two soil-gas points). Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), polynuclear aromatic hydrocarbons (PAHs), and total or dissolved RCRA metals. Soil vapor samples were analyzed for VOCs. The following sampling results were identified:

- Soil analytical results did not identify targeted compounds above NYSDEC standards. RPS recommended no additional action for site soils.

- No VOCs or metals were detected above NYSDEC standards in the groundwater samples. One PAH was detected in a groundwater sample above NYSDEC standards; however, this detection was attributed to method blank contamination. Based on this and the lack of potable well receptors, RPS recommended no additional action for site groundwater.
- Carbon tetrachloride and 1,2,4-trimethylbenzene were detected in soil vapor sampling collected underneath the site building in excess of the applicable NYSBCP toxicity value. Based on the "hit or miss" detections and the lack of "severe or widespread VOC detections below the floor slab," no additional action for soil gas underneath the building was recommended.
- 1,2,4-trimethylbenzene and 1,3-butadiene were detected in exterior soil gas samples above United States Environmental Protection Agency (USEPA) OSWER values. These detections were not considered a concern as they would not be indicative of a groundwater impact.

Summary of Environmental Conditions, Newsday Media Group Facility, 235 Pinelawn Road, Melville, New York 11747, prepared by RPS, dated May 22, 2018

This report summarized the Phase I and II environmental assessments discussed above. The report indicated that subsequent to the Phase I ESA, the open spill case associated with the release of four gallons of compressor oil had been closed by the NYSDEC on November 9, 2017. Based on these findings, RPS did not recommend additional assessment or mitigation.

Asbestos-Containing Material Survey, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated June 2018

An ACM survey was completed at the facility by RPS between April 18 and 21, 2018. A total of 238 bulk samples of suspect ACMs from 65 homogenous materials were collected. A total of 188 samples were submitted for laboratory analysis. The following building materials containing greater than 1% asbestos were identified during the survey:

- Approximately 30 square feet of 12”X12” black adhesive mastic was found on the first floor below a raised floor at a ramp outside the intermediate distribution frame. This material was found in good condition and not friable.
- Approximately 25 square feet of 12”X12” black mastic associated with vinyl floor tile was found on a first-floor cafeteria closet. This material was found in good condition and not friable.

The following building materials were found to contain less than 1% asbestos:

- Approximately 15,000 square feet of black mastic associated with vinyl floor tile was found throughout the building. This material was found in good condition and not friable.
- Approximately 45,000 square feet of tan spray-on fireproofing was found throughout the building. This material was found in good condition.

The ACM Survey focused on accessible interior building systems and components within the production/office structure with the potential to contain asbestos and did not include the assessment or sampling of any suspect exterior building materials or systems, including (but not limited to) roofing and all other suspect ACMs on the roof level. WJE Engineers and Architects was separately retained to obtain roof core samples and submit them for laboratory analysis. The laboratory analysis data associated with these roof samples was provided to RPS and is presented alongside RPS’s findings in the body of the ACM survey report. RPS noted that the data provided by WJE Engineers and Architects was not obtained through conventional protocols, and therefore could not be relied upon in connection with renovation and demolition, because an insufficient number of samples were collected to characterize the roofing system. These samples were non-detect for ACM, however, RPS noted that roofing and other exterior materials may require additional sampling to confirm the non-detect finding prior to renovation or demolition involving exterior materials.

RCRA Closure Plan, Newsday LLC, 235 Pinelawn Road, Melville, New York 11747, prepared by H2M, dated July 18, 2018

This closure plan was created to formally cease and document completion of regulated waste activities. The purpose of completing the closure is to eliminate post-closure maintenance of hazardous waste generation sources and hazardous waste storage areas at the site and to minimize the potential for a post-closure release of hazardous waste to the environment. Hazardous waste streams generated by Newsday included ink waste, spent photographic developer, and spent photographic fixer. The closure of the facility will include the removal of all hazardous wastes, decontamination of the hazardous waste storage areas, confirmatory rinsate and subsurface soil sampling, and removal of all wastes generated during closure. The plan outlined proposed rinsate and soil sampling procedures in the former silver recovery room and photo waste room, and in the ink recovery room. The plan also described proposed removal and sampling of several areas of industrial waste piping associated with spent fixer and developer.

It should be noted that the closure plan described the 4,000-gallon spent fixer and developer waste UST, which was closed by removal in June 1989. The UST was located on the exterior of the building and was removed prior to expansion of the basement boiler area. The area of the former spent fixer and developer waste UST was over excavated to a depth of 18.5 feet below grade. No contaminated soil was identified during closure of this UST.

Closure of Facility, Newsday LLC, 235 Pinelawn Road, Melville, NY, prepared by the NYSDEC, dated August 10, 2018

This letter approved the RCRA Closure Plan described above. The approval required public notice of the closure plan.

Facility Drawings provided by Newsday, various dates

In addition to the documentation summarized above, VERTEX was provided with various drawings of the facility from the late 1970s to 2000s. The majority of the information was related to building expansions, alterations, and mechanical systems. According to a Site Demolition Plan from 1983, which was created as part of the facility expansion, a fueling station was located to the northeast of the fire suppression pond. This fueling station consisted of three 20,000-gallon diesel fuel USTs and one 12,000-gallon gasoline UST. In addition, a 2,000-gallon solvent storage tank was identified to the east of the fire suppression pond in the proximal location of the current 2,500-gallon fuel oil UST. The proposed expansion of the building included the area of this former fueling station. The fueling station was to be relocated to the southern portion of the site where the current fueling area is located.

Refer to Appendix B for a copy of select previous environmental documentation.

5.4 Prior Ownership

VERTEX obtained site ownership information from the Suffolk County Clerk's Office. The site currently is owned by Tribune ND Inc. Newsday currently leases the site from Tribune ND, Inc. Available ownership information for this property is summarized below.

DEED RECORDS REVIEW				
GRANTOR	**GRANTEE**	**DOCUMENT TYPE**	**LIBER/PAGE**	**DATE**
Tribune Company	Tribune ND Inc.	Deed	D00012573 / 072	11/26/2008
TMCT LLC	Tribune Company	Deed	D00012549 / 224	4/30/2008
Newsday Inc.	TMCT LLC	Deed	D00011845 / 801	8/12/1997

Deed records dated prior to 1997 were unavailable for review. No environmental liens or AULs were noted through review of ownership records. Prior owners of the site were not available to be interviewed.

5.5 City Directories

VERTEX reviewed historical city directory information for the site and adjoining properties. Excerpts from the city directory report are included in Appendix C. A summary of listings is presented below.

CITY DIRECTORY REVIEW (PINELAWN ROAD)			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
1972	No listings	130: Herman Heinlein 146: E. Reckner 255: Britannc & Erpn Auto, Unex Prods Corp.	None
1977	No listings	130: Ward Reilly 146: E. Reckner 255: Imperial News Co., NAPA Imports	None
1982	235: Newsday Inc.	130: John Goze 255: Cable News, Imperial News Company, NAPA Imports, Select Magazine	On-site printing
1987	235: Newsday Inc.	130: John Goze Tennis, George E. Hoffman, Pinelawn Supply Co. 135: Charles Schwab, Chase Manhattan Bank, Greenway Plaza, Northern Telecom, RK&L Enterprises 255: Cable News, Imperial News Company, NAPA Imports, Select Magazine, Warner Publisher	On-site printing
1992	235: Newsday Inc.	255: TV Guide	On-site printing
1995	235: Corporate Travel Consultants, Distribution Systems of America, Newsday Community Service Fund, Newsday Inc, The Times Mirror Company	255: Clare Rose of Nassau Inc., TV Guide	On-site printing
2000	235: Corporate Travel Consultants, Distinction Magazine, Inc., Distribution Systems of America, Newsday Community Service Fund, Newsday LLC, Star Community Pubg Group LLC, This Week/Pennysaver	255: Clare Rose Inc., Dee Gee Express, News America Publications	On-site printing

CITY DIRECTORY REVIEW (PINELAWN ROAD)			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
2005	235: Distinction Magazine, Inc., Long Island Parents & Children of New York City, Newsday Community Service Fund, Newsday LLC, This Week/Pennysaver	255: Clare Rose Inc.	On-site printing
2010	235: Distinction Magazine, Inc., Long Island Parents & Children, Newsday Community Service Fund, Newsday Employee Recreation Fund, Newsday LLC, Star Community Pubg Group LLC, Tribune NM Inc.	255: Clare Rose Inc.	On-site printing
2014	235: Distinction Magazine, Inc., Newsday LLC, Star Community Pubg Group LLC	255: Clare Rose Inc.	On-site printing

The review of city directories did not identify environmental concerns associated with the site and surrounding property listings with the exception of the on-site Newsday printing facility from 1982 to 2014. Additional information on the operations and environmental concerns associated with the historical printing operations on-site are discussed throughout this report.

5.6 Aerial Photography

VERTEX reviewed aerial photographs including the site and adjoining properties. Copies of the aerial photographs are included in Appendix D. A summary of information obtained from the review is provided in the table below.

AERIAL PHOTOGRAPHY REVIEW			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
1938 1947 1953	The site appears to be primarily agricultural land with a road bisecting the central portion of the property from east to west. What appears to be two structures, possibly residential and farm-related, is visible on the southeastern portion of the site.	Roads, agricultural land, and residences are located on adjacent properties.	None
1957	Similar to the 1953 aerial photograph with additional small structures added to the southeastern portion of the site. What appear to be storage areas are visible on the northeastern corner of the site.	Similar to the 1953 aerial photograph. Additional residences are visible to the northwest.	None

AERIAL PHOTOGRAPHY REVIEW			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
1962 1966	Similar to the 1957 aerial photograph.	Similar to the 1957 aerial photograph. The adjacent property to the northeast has been cleared for redevelopment. The current cemetery to the east is now visible.	None
1970	Similar to the 1966 aerial photograph.	Similar to the 1966 aerial photograph. One of the current light industrial buildings has been developed to the south.	None
1976	Similar to the 1970 aerial photograph. The road previously located on the central portion of the site is overgrown and abandoned. What appear to be greenhouses or chicken coops are visible on the southeastern corner of the site.	Roads and residences are visible to the north. The current structure occupied by a gym adjoins the site to the northeast. A road is visible to the east, followed by a cemetery. Two light industrial buildings are visible to the south. A road is visible to the west, followed by a light industrial building to the southwest and cleared land to the west.	None
1980	The northern portion of the site is agricultural land. The central portion of the site is developed with a large portion of the current main building. The WWTP and fire pond are located on the western portion of the site. Parking areas are visible to the south and northwest of the site building. A possible fueling pad is located to the northeast of the fire pond.	Similar to the 1976 aerial photograph. The current light industrial building to the southwest is now visible.	On-site industrial operations
1985	Similar to the 1980 aerial photograph. The northern portion of the site appears to be under construction with a parking lot. Areas to the south of the main building appear to be disturbed and possibly under construction.	Similar to the 1980 aerial photograph. A light industrial building has been developed to the northwest.	On-site industrial operations
1994	The main building has been expanded into its current configuration. The parking lots on the northern portions of the site have been completed. The far northwestern portion of the site is a vacant field. The current fueling area on the southwestern portion of the site is visible. The remaining portions of the site appear similar to the 1985 aerial photograph.	Similar to the 1985 aerial photograph.	On-site industrial operations.
2008 2011	The site is developed similar to current configuration.	Similar to the 1994 aerial photograph.	On-site industrial operations.
2015	Similar to current configuration.	Similar to current configuration. The current townhomes and BAPS buildings to the west have been constructed.	On-site industrial operations.

The review of historical aerial photographs identified the site as agricultural land with a road and small structures likely associated with agricultural operations from 1938 to 1976. By 1980, the site was redeveloped with the current industrial building, which was expanded by 1994. The historical industrial uses of the site are discussed throughout this report. The historical uses of surrounding properties were not identified as environmental concerns in the aerial photographs reviewed.

5.7 Topographic Maps

VERTEX reviewed historical topographic maps including the site and surrounding areas. Copies of the topographic maps are included in Appendix E. A summary of information obtained from the review is provided in the table below.

TOPOGRAPHIC MAP REVIEW			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
1901 1903 1904	The site is primarily depicted as unimproved. Two small structures are visible along the eastern site boundary.	Roads and small structures are visible on surrounding properties.	None
1942	A road is depicted traversing the central portion of the site. The remainder of the site is depicted as unimproved.	Roads and unimproved land are depicted on surrounding properties.	None
1947	An unpaved road is depicted traversing the central portion of the site. Two small structures are visible on the southeastern corner of the site.	Roads and small structures are visible to the north. A road and small structures are visible to the east. Two small structures are visible to the southeast. Unimproved land is visible to the south and southwest. An unpaved road and two small structures are visible to the west.	None
1954	Similar to the 1947 map.	Similar to the 1947 map. The Long Island National Cemetery is depicted to the east.	None
1967	Similar to the 1954 map. The road on the central portion of the site has been replaced with powerlines.	Similar to the 1954 map with the addition of small structures and man-made ponds to the north and northeast.	None

TOPOGRAPHIC MAP REVIEW			
YEAR	**SUMMARY (ON-SITE)**	**SUMMARY (OFF-SITE)**	**CONCERNS**
1979	Similar to the 1967 map.	Ruland Road is depicted to the north, followed by several small structures. The current gym building is depicted to the northeast. Wellwood Avenue is depicted to the east, followed by the Long Island National Cemetery. Two light industrial buildings are depicted to the south. One light industrial building is depicted to the southwest.	None
2013	Roadways are depicted on-site. Specific structures are not depicted on this version of topographic map.	The surrounding properties included roads and the Long Island National Cemetery. Specific structures are not depicted on this version of topographic map.	None

The review of historical topographic maps did not identify environmental concern in connection with the site.

5.8 Sanborn Fire Insurance Maps

Sanborn fire insurance maps that include the site were requested from EDR; however, EDR indicated that no historical map coverage is available for the site. A copy of EDR's statement of no coverage is provided in Appendix F.

6.0 REGULATORY RECORDS REVIEW

VERTEX obtained a regulatory database report as specified in Section 12.0. Review of databases and files from federal, state, and local environmental regulatory agencies was used to identify use, generation, storage, treatment, or disposal of hazardous materials and chemicals, or release incidents of such materials that might have impacted the site. The databases discussed in the following sections address ASTM requirements. Additional federal and state databases may have also been reviewed, and if so, are listed in the table below. A copy of the database report is included in Appendix G.

VERTEX's review of these listings assessed the potential for soil, groundwater, and/or soil vapor impacts to the site from on-site listings or listings at surrounding facilities, taking into account such factors as the groundwater depth and inferred flow direction, regulatory status, distance from the site, and other information reported by the regulatory database(s) and/or other sources of information.

A summary of the database information is provided in the following table.

Database	Radius	Subject Site	Surrounding Facilities
National Priorities List (NPL)	1 Mile	0	1
Delisted NPL	1 Mile	0	1
Proposed NPL	1 Mile	0	0
Record of Decision (ROD)	1 Mile	0	2
RCRA Corrective Action (CORRRACTS) Facilities	1 Mile	0	1
Superfund Enterprise Management System (SEMS)	½ Mile	0	0
SEMS-ARCHIVE	½ Mile	1	0
RCRA Treatment, Storage & Disposal Facilities (TSDF)	½ Mile	0	0
RCRA Large Quantity Generators (LQG)	¼ Mile	1	1
RCRA Small Quantity Generators (SQG)	¼ Mile	0	4
RCRA Conditionally Exempt SQGs (CESQG)	¼ Mile	0	1
RCRA NonGen/NLR (Former Generators)	¼ Mile	1	10
US Institutional & Engineering Controls (INST/ENG CONTROLS)	½ Mile	0	0
Emergency Response Notification System (ERNS)	Target Property	0	

Database	Radius	Subject Site	Surrounding Facilities
US BROWNFIELDS	½ Mile	0	0
NY Brownfields	½ Mile	0	0
State Hazardous Waste Sites (SHWS)	1 Mile	0	7
NY Delisted SHWS (DEL SHWS)	1 Mile	0	1
State Solid Waste Facilities/Landfills (SWF/LF)	½ Mile	0	0
Indian Leaking Underground Storage Tank (LUST)	½ Mile	0	0
New York Leaking Tanks (NY LTANKS)	½ Mile	1	20
New York UST (NY UST)	¼ Mile	2	23
New York AST (NY AST)	¼ Mile	2	15
NY Voluntary Cleanup Program (VCP)	½ Mile	0	3
NY ENG Controls	½ Mile	0	1
NY INST CONTROLS	½ Mile	0	1
NY Restrictive Declarations Listings (RES DECL)	⅛ Mile	0	0
Spills Information Database (NY SPILLS)	⅛ Mile	3	12
NY Environmental Restoration Program (ERP)	½ Mile	0	0
Facility and Manifest Data (MANIFEST)	¼ Mile	3	25
Enforcement & Compliance History Online (ECHO)	Target Property	2	
Facility Index System (FINDS)	Target Property	2	
Integrated Compliance Information System (ICIS)	Target Property	1	
US AIRS	Target Property	1	
NY AIRS	Target Property	1	
NY DRYCLEANERS	¼ Mile	0	0
NY SPDES	Target Property	1	
NY VAPOR REOPENED	½ Mile	0	2
EDR Manufactured Gas Plant	1 Mile	0	0
EDR Historical Auto Stations	⅛ Mile	0	0
EDR Historical Dry Cleaners	⅛ Mile	0	0

The database report includes an orphan summary. This summary identifies facilities that are listed on one of the above-referenced databases or lists but do not include complete or accurate geographic data. Consequently, EDR was unable to map the facilities in relation to the site. VERTEX reviewed the orphan summary prior to inspecting the site and surrounding properties. Orphan properties located within ASTM search distances of the site (if any) were incorporated into VERTEX's review.

6.1 On-Site Listings

The site was identified in several databases in the EDR database report. These listings are summarized below.

- **NY UST**: The site is listed for several USTs currently or formerly operated on-site. These include the following:
    - Three 25,000-gallon diesel fuel USTs installed in 1978 and identified as removed in 1986.
    - One 12,000-gallon gasoline UST installed in 1978 and identified as removed in 1986.
    - One 2,000-gallon spill containment UST installed in 1978 and identified as removed.
    - One 4,000-gallon industrial waste UST installed in 1978 and identified as removed.
    - Two 20,000-gallon diesel fuel USTs installed in 1985 and identified as removed in 2010.
    - Two 25,000-gallon fuel oil USTs installed in 1978 and abandoned in place in 2014.
    - One 2,500-gallon fuel oil UST installed in 1985 and identified as active.
    - Three 20,000-gallon diesel fuel USTs identified as active.

Additional details on former and current USTs in operation at the site is summarized in Section 7.2.

- **NY AST**: The site is listed for several ASTs currently or formerly operated on-site. Based on information obtained from EDR, site contacts, site observations, and other historical information provided, a table summarizing these ASTs was created and can be found in Section 7.2.
- **RCRA-LQG, NY MANIFEST, NJ MANIFEST**: Newsday was registered as a LQG of hazardous waste from 1980 to 2014. Hazardous wastes generated at the site included corrosive waste, silver waste, spent halogenated solvents, spent nonhalogenated solvents, 2-propanone, acetic acid, formaldehyde, benzene, 1,1,2-trichloroethane, ethane. Chlorinated solvent

waste was generated at the site in 1980, 1981, 2004, 2006, 2008, and 2014. Newsday received several Notices of Violations (NOVs) related to regulations, records/reporting, manifests, contingency plan/emergency procedures, general facility standards, small quantity handlers, container use and management, and pre-transporting of hazardous waste from 1986 to 2015, all of which have achieved compliance.

- **SEMS-ARCHIVE**: A CERCLIS Preliminary Assessment was conducted at the site in 1989. The site was not placed on the NPL and in 1998 the site was issued No Further Remedial Action Planned (NFRAP) status. No other information was available regarding the reason for the Preliminary Assessment or the basis for issuing the NFRAP status.
- **NY SPILLS/NY LTANKS:** The site was identified several times on these databases associated with releases, including releases from tanks. These listings are summarized below. It should be noted that VERTEX received several spill files for the facility from the NYSDEC as part of this assessment. Additional details provided by the NYSDEC can be found in Section 6.3.
    - Spill #8907176 was generated on October 20, 1989 for a release from an emergency generator, which impacted a nearby dry well. The spill was cleaned up and closed by the NYSDEC on August 23, 1990.
    - Spill #9201246 was generated on April 30, 1992 due to a failed tank test associated with a 25,000-gallon diesel fuel UST. Two yards of contaminated soil was removed. The spill case was closed by the NYSDEC on May 27, 1998.
    - Spill #9312349 was generated on January 21, 1994 for a release of 50-gallons of petroleum oil due to a broken line on a fuel truck. The spill was cleaned up and the case was closed on March 28, 1994.
    - Spill #9706042 was generated on August 18, 1997 for the release of 20 gallons of hydraulic oil. Corrective action was taken, and the incident was closed by the NYSDEC on December 1, 1997.
    - Spill #9709711 was generated on November 20, 1997 for a failed tank test due to interference when testing. Following tests passed and the spill case was closed by the NYSDEC on December 11, 2009.
    - Spill #0008603 was reported at the site on October 23, 2000 for the release of 1,600-

gallons of diesel fuel due to a tank overfill. A third-party contractor was notified to clean up the release and the incident was closed with the NYSDEC on December 14, 2000. Refer to Section 6.3 for additional information on this release case.

- Spill #0125175 was generated on August 27, 2001 for the release of 20 gallons of hydraulic oil from a dumpster truck. Corrective action was taken, and the incident was closed by the NYSDEC on September 16, 2004.
- Spill #0203990 was generated on July 17, 2002 associated with a spill of 20-gallons
- of hydraulic oil due to a ruptured line in a truck. The spill was cleaned up and the case was closed by the NYSDEC on the same date.
- Spill #0507524 was generated on September 22, 2005 for the release of 100 gallons of ink from the ink reclamation machine. The released ink was filtered and recycled. The area of the release was bermed and the incident was closed by the NYSDEC on March 14, 2006.
- Spill #1000551 was generated on April 13, 2010 due to impacted soils identified during the removal of three 20,000-gallon diesel fuel USTs. A total of 166.83 tons of petroleum-impacted soils were removed. The spill case was closed by the NYSDEC on March 30, 2011.
- Spill #1108374 was generated on October 1, 2011 for the release of six gallons of diesel fuel from a fleet vehicle (not owned by Newsday) as it was exiting the site. No drains were reportedly affected and a third-party contractor cleaned up the release. The incident was closed by the NYSDEC on October 3, 2011.
- Spill #1200716 was generated on April 23, 2012 for the release of 500 gallons of combined industrial/sanitary wastewater sewage at the site. The spill was cleaned up on-site and closed by the NYSDEC on October 22, 2012.
- Spill #1203029 was generated on June 26, 2012 for a tank test failure associated with a 25,000-gallon UST. The tank was listed as abandoned in place. The spill case was closed by the NYSDEC on April 7, 2014.
- Spill #1205313 was generated on August 26, 2012 due to a release of 2,000-gallons of ink from a broken ink feeding tube on a printing machine. All of the material was

reportedly contained within the printing shop and no floor drains were affected. The incident was closed by the NYSDEC on October 3, 2012.

- Spill #1402877 was generated on June 17, 2014 for a release of five gallons of diesel fuel from a generator day tank. The spill was not reported to have migrated outside and was subsequently closed by the NYSDEC on August 12, 2014.
- Spill #1508951 was generated on December 2, 2015 for a release of 60 gallons of antifreeze due to a burst on a generator inside the site building, which migrated to a dry well outside. The dry well was confirmed to have no outlets and a sand bottom. The NYSDEC confirmed the sand soaked up the entire product, and the incident was subsequently closed On December 9, 2015.
- Spill #1606790 was generated on October 11, 2016 for a release of four gallons of compressor oil due to equipment failure. Drains in the production areas are connected to an oil/water separator and discharge to the on-site wastewater treatment plant. According to information obtained during this assessment, the spill area was cleaned and closed by the NYSDEC on November 9, 2017.
- Spill #1610337 was generated on February 15, 2017 due to a release of 1,000-gallons of printing ink into a containment area. The entire spill was contained and closed by the NYSDEC on November 9, 2017.
- Spill #1703192 was generated on July 1, 2017 for a spill of wastewater into a drain. The drain was pumped out and the spill case was closed by the NYSDEC on July 3, 2017.

- **ICIS**: This listing is associated with a formal administrative violation associated with the facility's SPDES permit. No additional relevant information was provided.
- **US AIRS, NY AIRS**: This listing is associated with air permitting requirements for facility operations. No violations were reported.
- **FINDS, ECHO:** These listings are associated with Federal and state environmental tracking systems.

- **NY SPDES**: This listing is associated with the active SPDES permit for wastewater discharges from the facility. Additional information on the permit is summarized in Section 6.3.
- **RCRA NonGen/NLR, FINDS, ECHO, NY MANIFEST**: Nalco Chemical was registered as a SQG of corrosive waste in 1996 with no violations found. Nalco Chemical was registered as a non-generator of hazardous waste in 2007. Based on the lack of spills or released associated with the hazardous waste generation and the nature of the listings, no concerns were identified. The FINDS, ECHO and NY MANIFEST listings are related to environmental compliance and not indicative of impact.

6.2 Off-Site Listings

A review of state and federal regulatory records revealed several facilities within ASTM-specified search radii of the site. Facilities located proximal to the site are discussed further in the table below. The remaining facilities are not a concern based on the current regulatory status, relative distance from the site, and/or inferred direction of groundwater flow.

OFF-SITE STATE AND FEDERAL LISTINGS			
FACILITY	**DISTANCE AND DIRECTION/ GRADIENT**	**REGULATORY STATUS**	**CONCERNS**
Eastern Athletic 100 Ruland Road	Adjoining northeast / Crossgradient	**NY UST**: Listed for two active 1,000-gallon No. 2 fuel oil USTs. **NY Spills**: Spill #0910535 was generated in 2009 for a release of 15 gallons of No. 2 fuel oil when a plow hit an UST fill pipe. The spill was cleaned up and closed on December 28, 2009.	None
Business 255 Pinelawn Road	Adjoining southeast / Downgradient	**NY Spills**: Spill #1303748 was generated in 2013 due to a release of three gallons from a transformer. The spill was cleaned up and closed on December 16, 2013.	None

OFF-SITE STATE AND FEDERAL LISTINGS			
FACILITY	**DISTANCE AND DIRECTION/ GRADIENT**	**REGULATORY STATUS**	**CONCERNS**
Imperial News Company 255 Pinelawn Road	Adjoining southeast / Downgradient	**NY Spills**: Spill #0906309 was generated in 2009 due to a 10-gallon release of fuel oil from a truck. The spill was cleaned up and closed on March 22, 2010. Spill #8603300 was generated in 1986 due to a failed tank tightness test. The tank re-passed the test and was closed on October 1, 1986. Spill #9308159 was reported in 1993 due to leakage from the bottom of a tank. The spill was cleaned up and closed on June 2, 2004. **RCRA NonGen/NLR, FINDS, ECHO, NY MANIFEST**: Listed for the historical generation and disposal of hazardous waste from facility operations. No violations were reported.	None
Clare Rose 255 Pinelawn Road	Adjoining southeast / Downgradient	**NY Spills**: Spill #0890480 was generated in 2008 due to a release reported during the removal of an UST. The spill was remediated, and the case was closed on June 12, 2008. Spill #9402856 was reported in 1994 associated with impacted soils found during removal of a 10,000-gallon No. 2 fuel oil UST. The spill was cleaned up and closed on November 9, 1994. **NY UST**: Listed for 10 removed USTs. The USTs contained No. 2 fuel oil, waste oil, diesel fuel, and gasoline, and were also associated with two oil/water separators. **NY AST**: Listed for five ASTs storing No. 2 fuel oil, diesel fuel, motor oil, and gasoline. The ASTs appear to be active but specific details were not provided.	None
MRP Family Holdings LLC 101 Marcus Drive	Adjoining south / Downgradient	**NY UST**: Listed for a 15,000-gallon No. 2 fuel oil, which was removed. No releases were reported.	None
Pergament Home Center 101 Marcus Drive	Adjoining south / Downgradient	**NY Spills**: Spill #0013423 was reported in 2001 for a release of No. 2 fuel oil from a boiler room. The spill was cleaned up and closed on October 3, 2001.	None
Linotype – Hell Co. 80 Ruland Road	~100 feet northwest / Upgradient	**NY AST**: Listed for a drum storage area and a photo wastewater tank. No releases were reported.	None
Heidelberg Publishing Services 80 Ruland Road	~100 feet northwest / Upgradient	**RCRA NonGen/NLR, FINDS, ECHO, NY MANIFEST**: Listed for the historical generation and disposal of hazardous waste from facility operations. No violations were reported.	None
Tribune Company 25 Deshon Drive	~250 feet southwest / Crossgradient	**RCRA NonGen/NLR, FINDS, ECHO, NY MANIFEST**: Listed for the historical generation and disposal of hazardous waste from facility operations. No violations were reported.	None

OFF-SITE STATE AND FEDERAL LISTINGS			
FACILITY	**DISTANCE AND DIRECTION/ GRADIENT**	**REGULATORY STATUS**	**CONCERNS**
Newsday 25 Deshon Drive	~250 feet southwest / Crossgradient	**NY AST**: Listed for 12 ASTs containing boiler chemicals, cooling tower chemicals, No. 2 fuel oil, industrial waste, motor oil, and a boiler additive. No releases were reported. **NY UST**: Listed for three removed No. 2 fuel oil USTs. The USTs were removed in 1989 and 2013. No releases were reported. **NY Spills**: Spill #9309731 was reported in 1993 due to a 15-gallon spill of diesel fuel from a vehicle. The spill was cleaned and closed on December 24, 1993. Spill #0550849 was reported in 2005 due to a release of 50-gallons of petroleum oil from a boiler room to a drain leading to a septic system. The area was remediated, and the spill was closed on September 9, 2005.	None
Patterson Building 25 Deshon Drive	~250 feet southwest / Crossgradient	**NY Spills**: Spill #0106454 was reported in 2001 for a release of 10-gallons of petroleum from a truck. The spill was cleaned up and closed on September 27, 2001.	None
Unknown Pinelawn and Ruland Road	~370 feet northeast / Crossgradient	**NY Spills**: Spill #8600899 was generated in 1986 due to a release of 50-gallons of diesel fuel during a traffic accident. The spill was cleaned up and closed on April 22, 1987. Spill #0303103 was reported in 2003 associated with a release of 40 gallons of diesel fuel from a truck. The spill was cleaned up and closed on July 2,2 003.	None
Otto Keil Florist 107 Ruland Road	~500 feet west-northwest / Upgradient	**NY AST**: Listed for a 5,000-gallon No. 2 fuel oil AST. No releases were reported.	None

Based on apparent gradient relationship, regulatory status, and/or other facility-specific characteristics, no RECs to the site were identified with respect to the off-site listings.

6.3 Additional Environmental Record Sources

VERTEX contacted local agencies to request information relevant to the site and vicinity. A summary of the agencies contacted, and the information obtained is included in the following table.

LOCAL RESEARCH SUMMARY		
OFFICE	**INFORMATION OBTAINED**	**CONCERNS**
Town of Huntington Assessor's Office	VERTEX obtained parcel information via the Town of Huntington online portal. Information obtained can be found throughout this report.	None
Town of Huntington Building and Housing Department	VERTEX submitted a request to this department on August 1, 2018. According to a response, available building department records are available through the Town of Huntington website. A summary of these permits is provided below.	See below
Town of Huntington Office of the Fire Marshal	VERTEX submitted a request to this department on August 1, 2018. According to a response, no relevant documentation is on file with this department.	None
Suffolk County Department of Health, Office of Wastewater Management	VERTEX received site plans for the property from this department. See below for a discussion of these site plans.	See below
Suffolk County Department of Health, Office of Pollution Control	VERTEX submitted a request to the department on August 6, 2018. As of the date of this report, a response to this request has not been received. According to the SCDHS FOIL coordinator, due to backlog of FOIL requests, a response from this office may not be received until November or December 2018.	Response pending
Suffolk County Department of Health, Office of Water Resources	According to a response from the department, requested environmental records are not maintained by this department.	None
Suffolk County Clerk's Office	VERTEX obtained historical property ownership records from this department.	Refer to Section 5.4
New York State Department of Environmental Conservation (NYSDEC)	VERTEX was provided with documentation associated with historic spill incidents at the facility as well as documentation associated with the SPDES permit. Relevant documentation provided is summarized below.	See below

Town of Huntington Building and Housing Department

Numerous permits were listed online through the Town of Huntington Land Management Site History Report. Relevant permits listed included the following:

- November 18, 1977 – Erect a sewage plant control building and treatment units.
- November 11, 1978 – Install three 25,000-gallon and one 12,000-gallon diesel fuel tanks.

- November 5, 1981 – Removal and relocation of four 10,000-gallon gasoline storage tanks and dispensers. According to the excerpt, the tanks were removed and relocated with Permit #625854, which is the permit issued on December 11, 1985 discussed below.
- December 11, 1985 – Replacement of existing fueling station including the installation of three 20,000-gallon USTs and associated appurtenances.
- August 21, 1986 – Erect a three-story addition to the existing newspaper plant.
- September 16, 1986 – Installation of one hydraulic freight elevator.
- September 8, 1988 – Demolish one 2,000-gallon UST.

It should be noted that several of the permits listed did not list the specific reason for the permit.

Suffolk County Department of Health, Office of Wastewater Management

VERTEX was provided three drawings from this department, which included the following:

Proposed Plumbing and Septic System Plan and Notes, Newsday, prepared by Cameron Engineering & Associates, LLP, dated February 6, 2004

This site plan included diagrams of exterior wastewater features at the site. This included three proposed septic systems at guard houses located on the southeastern, northern, and northwestern portions of the site. The systems included 1,000-gallon tanks and leaching pools. The diagram also depicted three existing leaching pools on the southwestern portion of the site. Reportedly, the proposed septic system located on the northwestern portion of the site was never installed and the remaining two proposed septic systems depicted on this figure are currently located on-site.

Areas 1, 2, and 3 Security Booth and Main Office Basement Plumbing Plans, Newsday, prepared by Cameron Engineering & Associates, LLP, dated February 6, 2004

This drawing depicted additional details on the proposed septic system plans for the guard booths and a plumbing plan for the basement area within the site building. The basement detail included connection of the paint booth area to the domestic water line. No additional relevant information was provided in this drawing.

Proposed Plumbing and Septic System Details, Newsday, prepared by Cameron Engineering & Associates, LLP, dated February 6, 2004

This drawing provided additional details for the proposed septic systems at the guard houses. No additional relevant information was provided in this drawing.

New York State Department of Environmental Conservation

As part of this assessment, VERTEX requested available files for the facility from the NYSDEC. The NYSDEC provided documentation pertaining to the SPDES permit and historical spill incidents. Relevant information is discussed below.

SPDES Documentation

The following SPDES documents were provided:

- *Newsday Violations Report, undated* – This document listed effluent gross discharge exceedances of the SPDES permit from 1996 to 2012. Chemicals exceeding included 1,1,1-TCA, 1,2,4,5-tetramethylbenzene, 1,3,5-trimethylbenzene, benzene, cyanide, flow, total nitrogen, oil and grease, p-ethyltoluene, pH, total recoverable phenolics, silver, total dissolved solids, toluene, total toxic organics, and xylenes.
- *SPDES Discharge Permit, dated October 16, 1996* – The permit outlined the effluent limitations and monitoring requirements. Outfall 001 is identified as the industrial and

sanitary wastewater outfall. Outfall 002 is identified as the stormwater outfall. Industrial wastewater sources include platemaking rinse, photographic rinse, and porters slop sinks, which discharge to the sewage treatment plant before distribution to leaching pools. Photographic wastewater goes through silver reclamation, which is transported off-site by a licensed transporter.

- *SPDES Permit Renewal, dated September 7, 2001* – This was the five-year SPDES permit renewal.
- *SPDES Permit Modification Approval, dated November 2, 2001* – This modification included a new outfall, Outfall 003. Outfall 003 is associated with non-contact compressor cooling water, which is discharged to leaching basins located to the northwest and southeast of the main building.
- *SPDES Permit Modification Approval, dated September 14, 2005* – This modification included the additional of sanitary wastewater discharges from two security booths. Sanitary wastewater from the booths is discharged to adjacent leaching basins. Outfall 004 is located adjacent to the security guard booth on the southeastern portion of the site. Outfall 005 is located on the northern portion of the site adjacent to a security guard booth.
- *SPDES Permit Renewal, dated March 14, 2006* – This renewal included modifications to the WWTP. The industrial photo chemistry process was eliminated.
- *Report of Noncompliance Event, dated December 2007* – This was a self-reported non-compliance pH limits, total nitrogen, and toluene. Corrective actions were identified and implemented.
- *SPDES Permit Modification, dated May 30, 2008* – This modification included new requirements for discharge monitoring reports.
- *SPDES Permit Renewal, dated December 1, 2011* – This permit renewal included removal of the monitoring requirements for phenol, silver, toluene, and cyanide. These were removed due to the elimination of many chemicals associated with photo wet chemistry. The current SPDES permit expires in 2021.

Spill Incident Documentation

VERTEX was provided files for 20 spill incidents at the site. These included the following:

- **Spill #8907176** was generated on October 20, 1989 for a release of approximately 40-gallons of diesel fuel from an emergency generator, which impacted a nearby dry well underneath the fresh air intakes of the basement. The spill occurred during testing of the day tanks associated with the emergency generators. Five yards of impacted soil were remediated from the dry well. No post-excavation soil samples were collected. The spill case was subsequently closed by the NYSDEC on August 23, 1990.
- **Spill #9201246** was generated on April 30, 1992 due to a failed tank test associated with a 25,000-gallon diesel fuel UST. Two yards of contaminated soil was removed. No post-excavation soil samples were collected. The spill case was closed by the NYSDEC on May 27, 1998.
- **Spill #9312349** was generated on January 21, 1994 for a release of 50-gallons of petroleum oil due to a broken line on a fuel truck. The spill was cleaned up and the case was closed on March 28, 1994.
- **Spill #9706042** was generated on August 18, 1997 for the release of 20 gallons of hydraulic oil from a trash compactor. Corrective action was taken, and the incident was closed by the NYSDEC on December 1, 1997.
- **Spill #9709711** was generated on November 20, 1997 for a failed tank test due to interference when testing. Following tests passed and the spill case was closed by the NYSDEC on December 11, 2009.
- **Spill #9825125** was generated on November 12, 1998 due to the observation of diesel fuel on soil during station upgrade activities. The soil was removed and placed into drums for off-site disposal. Additional contaminated soil below dispenser and above the tank were unable to be excavated. Soil borings around the perimeter tank area did not identify soil contamination. Based on these observations, the NYSDEC closed the spill case on August 17,

1999.

- **Spill #0008603** was reported at the site on October 23, 2000 for the release of 1,600-gallons of diesel fuel due to a tank overfill of two 25,000-gallon USTs. Product entered nearby catch basins, leaching basins, and dry wells on-site. Remediation included removal of free product, contaminated sediment from five drains, and post-excavation soil sampling. The majority of free product entered catch basin CB-114. The drains were remediated to five feet below the bottoms of the drains. Catch basin CB-114 was remediated to a depth of 30 feet below grade and approximately 60 cubic yards of soil was removed for off-site disposal. Post-excavation soil sample results were found below applicable cleanup levels. The incident was closed by the NYSDEC on December 14, 2000.
- **Spill #0125175** was generated on August 27, 2001 for the release of 20 gallons of hydraulic oil from a dumpster truck. Corrective action was taken, and the incident was closed by the NYSDEC on September 16, 2004.
- **Spill #0203990** was generated on July 17, 2002 associated with a spill of 20-gallon of hydraulic oil due to a ruptured line in a truck. The spill was cleaned up and the case was closed by the NYSDEC on the same date.
- **Spill #0507524** was generated on September 22, 2005 for the release of 100 gallons of ink from the ink reclamation machine. The released ink was filtered and recycled. The area of the release was bermed and the incident was closed by the NYSDEC on March 14, 2006.
- **Spill #1000551** was generated on April 13, 2010 due to impacted soils identified around a dispenser as part of the removal of three 20,000-gallon diesel fuel USTs. A total of 166.83 tons of petroleum-impacted soils were removed. Post-excavation soil and groundwater samples were collected, and the results were found below applicable cleanup levels. The spill case was closed by the NYSDEC on March 30, 2011.
- **Spill #1108374** was generated on October 1, 2011 for the release of six gallons of diesel fuel from a fleet **v**ehicle (not owned by Newsday) as it was exiting the site. No drains were reportedly affected and a third-party contractor cleanup up the rele**a**se. The incident was closed by the NYSDEC on October 3, 2011.

- **Spill #1200716** was generated on April 23, 2012 for the release of 500 gallons of combined industrial/sanitary wastewater sewage at the site due to a weather-related malfunction. The spill was cleaned up and closed by the NYSDEC on October 22, 2012.
- **Spill #1203029** was generated on June 26, 2012 for a tank test failure associated with a 25,000-gallon UST. The tank was listed as abandoned in place. The spill case was closed by the NYSDEC on April 7, 2014.
- **Spill #1205313** was generated on August 26, 2012 due to a release of 2,000-gallons of ink from a broken ink feeding tube on a printing machine. All of the material was reportedly contained within the printing shop and no floor drains were affe**c**ted. The incident was closed by the NYSDEC on October 3, 2012.
- **Spill #1402877** was generated on June 17, 2014 for a release of five gallons of diesel fuel from a generator day tank, which entered a catch basin. Endpoint samples were reportedly clean. The spill was not reported to have migrated outside and was subsequently closed by the NYSDEC on August 12, 2014.
- **Spill #1508951** was generated on December 2, 2015 for a release of 60 gallons of antifreeze due to a burst on a generator inside the site building, which migrated to a dry well outside. The dry well was located in the vented areas in the southern portion of the basement. The dry well was confirmed to have no outlets and a sand bottom. The NYSDEC confirmed the sand soaked up the entire product. No endpoint samples were collected. The incident was subsequently closed On December 9, 2015.
- **Spill #1606790** was generated on October 11, 2016 for a release of four gallons of compressor oil due to equipment failure. Drains in the production areas are connected to an oil/water separator and discharge to the on-site wastewater treatment plant. According to information obtained during this assessment, the spill area was cleaned and closed by the NYSDEC on November 9, 2017.
- **Spill #1610337** was generated on February 15, 2017 due to a release of 1,000-gallons of printing ink into a containment area. The entire spill was contained and closed by the NYSDEC on November 9, 2017.

- **Spill #1703192** was generated on July 1, 2017 for a spill of wastewater into a storm drain. The drain was pumped out and the spill case was closed by the NYSDEC on July 3, 2017.

7.0 SITE RECONNAISSANCE

A site visit was conducted by VERTEX representative Mr. Christopher K. Cook, Senior Project Manager, on September 6, 2018 between 8:00 a.m. and 12:30 p.m. Messrs. Steve Zimmerman and Tim Winter with Newsday escorted VERTEX during the site visit and answered questions regarding site operations.

During the site visit, the weather was sunny with a temperature of approximately 85^{o} Fahrenheit. The site visit consisted of a walk-through of the site and visual reconnaissance of neighboring properties from curbside. Photographic documentation of the site visit is included in Appendix A.

7.1 Access Restrictions

VERTEX visually and physically observed accessible areas of the site. The majority of the interior and exterior of the site building were observed. Due to parked vehicles in property driveways and parking areas, visual observation of some exterior portions of the site were limited. No other limitations imposed by physical obstructions or other limiting conditions were observed.

7.2 Site Observations

Observations of site conditions were made during the site reconnaissance and are summarized in the table below. Issues of concern are discussed in greater detail following the table.

SITE OBSERVATIONS		
DESCRIPTION	**REPORTED/ OBSERVED ON-SITE Y/N**	**COMMENTS**
Hazardous Substances and Petroleum Products	Y	Hazardous substances and petroleum products observed during the site inspection are discussed below. <u>Ink Reclamation Room of Main Building</u> Tanks formerly utilized for the storage and reclamation of inks were identified in this room. According to the site contact, these tanks have been emptied. Ink staining was observed on the epoxy-coated flooring in this room. <u>Former Press Rooms of Main Building</u> One 55-gallon drum of used oil was observed in former printing press area. This drum was observed within containment and no spills were identified. Propane cylinders for forklifts were also observed in former press rooms. <u>Second Floor Maintenance Shop of Main Building</u> Acetylene and oxygen cylinders were observed in the second maintenance shop. In addition, general maintenance chemicals were observed, which included spray lubricants, paints, cleaners and degreasers. Stained concrete in an area of a former parts washer and in a former wash area were observed in this maintenance area. The concrete in stained areas appeared to be in good condition. <u>Tank #68 Drum Storage Area of Main Building</u> Several empty 55-gallon drums were observed in this area. De minimis staining of epoxy coated flooring was observed in this former drum storage area. <u>Tank #90 Oil/Water Separator Area of Main Building</u> De minimis staining on concrete was observed adjacent to the Tank #90 oil/water separator area. The concrete in this area appeared to be in good condition. <u>Tank #17 Area of Main Building</u> Staining adjacent to a diesel fuel generator Tank #17 in the basement. Oil absorbent material was observed in this area. The concrete in this area appeared to be in good condition. <u>Hazardous Materials Storage Shed</u> Several 55-gallon drums of press waste oil were observed in this shed, which is also identified as Tank #84. These containers were located within containment and no concerns were identified. <u>WWTP Building</u> The methanol drum storage room (Tank #65) included drums of methanol and citric acid. These containers were located within containment and no concerns were identified.

SITE OBSERVATIONS		
DESCRIPTION	**REPORTED/ OBSERVED ON-SITE Y/N**	**COMMENTS**
		The remaining chemicals observed at the site included small quantities of maintenance materials, diesel fuel and fuel oil in tanks, water treatment chemicals in tanks, and hydraulic fluid in tanks. See below for a discussion of tanks identified at the site.
UST(s)	Y	See below for a discussion of USTs currently and formerly in operation at the site.
AST(s)	Y	See below for a discussion of ASTs currently and formerly in operation at the site.
Strong, Pungent, or Noxious Odors	N	Not identified during the site visit.
Pools of Liquid	N	Not identified during the site visit.
Drums	Y	Drums observed on-site are discussed above.
Unidentified Substance Containers	N	Not identified during the site visit.
Polychlorinated Biphenyls (PCB)-containing Equipment	Y	Two pad-mounted transformers were observed to the north of the site building, which are owned by PSEG. The transformers were not labeled for PCB-content. However, based on utility ownership, it is assumed these transformers are non-PCB containing. In the event of a release, PSEG would be responsible for cleanup.
Utilities (Electricity/ Natural Gas)	Y	Electricity – supplied by PSEG Natural gas – supplied by National Grid
Hydraulic Equipment	Y	Four hydraulic elevators are located within the site building, which include three freight and one passenger elevator. The elevator pits were not accessible at the time of site inspection. No concerns associated with the operation of these elevators was identified.
Water Supply	Y	Water is currently supplied to the site by the South Huntington Water District. The facility was connected to the municipal water supply when developed in 1978.
Wells	Y	Several dry wells are located on-site. See the stormwater discussion below for additional information.

SITE OBSERVATIONS		
DESCRIPTION	**REPORTED/ OBSERVED ON-SITE Y/N**	**COMMENTS**
Wastewater	Y	Wastewater generated from the main building production areas is directed through floor drains to an oil/water separator before being treated in the WWTP. Sanitary wastewater from the main building is also directed to the WWTP. Wastewater is treated using a combination of pre-equalization screens, rotary aerators, membrane clarifiers, and sludge settling tanks. The wastewater is discharged to an underground cistern system including 11 underground pools from where it is discharged to the ground surface west of the WWTP and to leaching basins located to the north of the WWTP. Since printing operations ceased in June 2018, wastewater generated from the production areas is minimal. No additional treatment of process wastewater and floor wash water is required. Non-contact cooling water from the facility is discharged to leaching basins located to the southeast of the main building (Outfall 003). Current and former discharges at the site are currently regulated under the existing SPDES permit, which was originally created in 1980. The SPDES permit will be transferred to Tribune in the near future.
Septic	Y	Two septic systems are located on-site, one adjacent to the southeast guard shack and the second adjacent to the northern guard shack. The systems include 1,000-gallon tanks and leaching pools. The septic discharges are identified as Outfalls 004 and 005 in the SPDES permit. Based on the sanitary nature of the discharge directed to the septic system, these systems do not represent a REC.
Stormwater	Y	Stormwater from roof drains and parking areas discharges to greater than 100 dry wells located primarily in parking areas and driveways of the site. VERTEX also observed three dry wells in open areas of the basement. These stormwater discharges are regulated under the existing SPDES permit and are identified as Outfall 002.
Flood Plain	N	According to the FEMA FIRM, the site is not located in a 100- or 500-year floodplain.
Pits, Ponds, Lagoons	Y	A fire suppression pond is located to the west of the site building.
Stained Soil, Stained Pavement, Corrosion to Pavement	N	Not identified during the site visit.
Stressed Vegetation	N	Not identified during the site visit.

SITE OBSERVATIONS		
DESCRIPTION	**REPORTED/ OBSERVED ON-SITE Y/N**	**COMMENTS**
Solid Waste	Y	Sources of solid waste at the site included general trash and recycling, cardboard, and used rags. General refuse and recyclables are stored in two 40-yard dumpsters and transported off-site by Selmark. Cardboard is stored in a compactor, which is transported off-site by Selmark. Scrap metal is stored in two 40-yard dumpsters and transported off-site by Two Brothers Scrap Metal. No evidence of staining or a release of hazardous substances or petroleum was identified around the dumpsters or compactor.
Hazardous Waste Management	Y	According to the site contact, hazardous waste is no longer generated at the site. Used oil is transported off-site as a non-hazardous waste on a regular basis by United Industrial Services. No concerns associated with current hazardous and non-hazardous waste management was identified.
Heating/Cooling	Y	The office area of the site building is cooled by roof-mounted HVAC units. The office and production areas of the site building are heating via oil-fired boiler systems. No concerns were identified.
Drains, Sumps, Oil/Water Separators/Sand Traps	Y	Floor drains were observed in the warehouse and production areas of the main building, which are connected to subsurface piping with an eventual discharge to the WWTP. Three above grade oil/water separators associated with air compressors are located on-site. No concerns were identified. An out of use above-grade grease trap was observed within the site building. No concerns were identified.
Vapor Intrusion	N	As part of this assessment, VERTEX assessed the potential for impacts to the site from potential on- and off-site sources of vapor intrusion. The potential for impacts from off-site properties included a review of current off-site operations (see Section 2.4), a review of historical operations (see Section 5.2), and a review of regulatory database records (see Section 6.2). Potential sources of on- or off-site vapor intrusion were not identified.

Aboveground Storage Tanks

The following is a list of current or former ASTs in operation at the site.

Tank ID	Capacity (Gallons)	Substance	Location	Status
9	275	Diesel Fuel	Fire Pump Room	Active
10	8,000	Black Ink	Basement	Inactive. Installed in 1978.
11	8,000	Black Ink	Basement	Inactive. Installed in 1978.
12	8,000	Black Ink	Basement	Inactive. Installed in 1978.

Tank ID	Capacity (Gallons)	Substance	Location	Status
13	100	Industrial Waste	Unknown	Removed in 2001. Installed in 1978.
17	100	Diesel Fuel	Basement	Active. Installed in 1978.
21	4,675	Drum Storage	Not Applicable	Never Installed
22	1,380	Drum Storage	Inside – Solvent Storage Area	Inactive. Installed in 1991.
23	200	Black Ink - Reclaim	Inside – Solvent Storage Area	Inactive. Installed in 1991.
24	200	Black Ink - Reclaim	Inside – Solvent Storage Area	Inactive
25	500	Black Ink - Reclaim	Inside – Solvent Storage Area	Inactive
26	2,000	Industrial Waste	Unknown	Removed in 2002. Installed in 1989.
27	2,000	Industrial Waste	Unknown	Removed in 2002. Installed in 1989.
28	250	Industrial Waste	Unknown	Removed in 2003. Installed in 1989.
29	2,640	Drum Storage	Unknown	Removed. Installed in 1992.
30	1,500	Caustic	Unknown	Removed in 2006
31	7,900	Black Ink	Inside – Tank Ink Room	Inactive
32	7,900	Black Inc	Inside – Tank Ink Room	Inactive
33	7,900	Black Ink	Inside – Tank Ink Room	Inactive
34	1,900	Cyan Ink	Inside – Tank Ink Room	Inactive
35	1,900	Yellow Ink	Inside – Tank Ink Room	Inactive
36	1,900	Red Ink	Inside – Tank Ink Room	Inactive
37	1,900	Magenta Ink	Inside – Tank Ink Room	Inactive
38	125	Diesel Fuel	Basement – Day Tank Emergency Generator	Active
39	300	Cooling Tower Blow Down	Unknown	Removed in 2003
40	25	Diesel Fuel	2nd Floor – Day Tank Emergency Generator	Active
41	550	Cooling Water Blow Down	Unknown	Removed
42	50	Industrial Waste	Unknown	Removed in 2002. Installed in 1998.
43	100	Industrial Waste	Unknown	Removed in 2002. Installed in 1998.
45	100	Developer	Unknown	Removed
46	100	Fixer	Unknown	Removed
47	100	Fixer	Unknown	Removed
50	40	Parts Washer Solvent	Inside – Substation B	Inactive
51	330	Fountain Solution	Unknown	Removed in 2002
52	330	Fountain Solution	Unknown	Removed in 2002
53	330	Fountain Solution	Unknown	Removed in 2002
54	330	Fountain Solution	Unknown	Removed in 2002

Tank ID	Capacity (Gallons)	Substance	Location	Status
55	1,250	Diesel Fuel	Unknown	Removed in 2006
56	1,250	Diesel Fuel	Unknown	Removed in 2006
57	80	Water Treatment Chemicals	Basement	Active
58	80	Water Treatment Chemicals	Basement	Active
59	80	Water Treatment Chemicals	Basement	Active
60	80	Water Treatment Chemicals	Basement	Active
61	80	Water Treatment Chemicals	Basement	Active
62	140	Water Treatment Chemicals	Basement	Active
63	80	Water Treatment Chemicals	MER 3	Active
64	140	Water Treatment Chemicals	MER 3	Active
65	220	Methanol	Inside	Active
66	595	Lube Oil	Inside	Active
67	440	Drum Storage	Unknown	Removed
68	5,280	Press Products	Inside	Inactive
69	10	Salt/Sand Storage	Unknown	Removed
70	101	Hydraulic Fluid	Inside	Active
71	81	Hydraulic Fluid	Unknown	Removed in 2013
72	600	Hydraulic Fluid	Unknown	Removed in 2001
73	120	Hydraulic Fluid	Compactor Reservoir	Active
74	275	Drum Storage	Unknown	Removed
75	500	Fountain Solution	Reel Room	Inactive
76	500	Fountain Solution	Reel Room	Inactive
77	500	Fountain Solution	Reel Room	Inactive
78	500	Fountain Solution	Reel Room	Inactive
79	660	Fountain Solution	Reel Room	Inactive
80	60	Industrial Waste	Unknown	Removed
81	60	Industrial Waste	Unknown	Removed
82	50	Industrial Waste	Unknown	Removed
83	500	Industrial Waste	Unknown	Removed
84	2,860	Press Waste Oil	Hazardous Materials Storage Shed	Active
85	77	Parts Washer Solvent	Solvent Storage Area	Inactive
86	1,100	Diesel Fuel	CAT Generator	Active
87	1,100	Diesel Fuel	CAT Generator	Active
88	210	Oil/Water Separator	Air Compressors	Active
89	210	Oil/Water Separator	Air Compressors	Active
90	210	Oil/Water Separator	Air Compressors	Active
97	15,000	Diesel Fuel	General Receiving Area	Active
A	73	Hydraulic Fluid	Collating Area	Active
B	80	Hydraulic Fluid	RP Paper Rec	Active

According to the site contact, 60 permitted ASTs are scheduled to be decommissioned with the SCDHS in the near future. Since printing operations ceased in June 2018, the majority of the ASTs have been emptied and are no longer utilized (described as inactive above). No concerns associated with the current use of ASTs was identified during the site inspection. Refer to Section 6.3 for a discussion of historical spill incidents from ASTs.

Underground Storage Tanks

The following is a list of current or former USTs in operation at the site.

Tank ID	Substance	Capacity (Gallons)	Location	Install Date	Tank Construction	Piping Construction	Tank Leak Detection	Piping Leak Detection	Status
1	Diesel Fuel	25,000	Northeast of fire pond	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1986
2	Diesel Fuel	25,000	Northeast of fire pond	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1986
3	Diesel Fuel	25,000	Northeast of fire pond	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1986
4	Gasoline	12,000	Northeast of fire pond	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1986
5	Spill Containment / Solvent	2,000	East of fire pond	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1988
6	No. 6 Fuel Oil	25,000	Southeast exterior of building	1978	Unknown	Unknown	Unknown	Unknown	Closed in place in 2014
7	No. 2 Fuel Oil	25,000	Southeast exterior of building	1978	Unknown	Unknown	Unknown	Unknown	Closed in place in 2014
8	Industrial Waste	4,000	Under current basement	1978	Unknown	Unknown	Unknown	Unknown	Removed in 1989
14	Diesel Fuel	20,000	South-central fueling area	1985	Unknown	Unknown	Unknown	Unknown	Removed in 2010

Tank ID	Substance	Capacity (Gallons)	Location	Install Date	Tank Construction	Piping Construction	Tank Leak Detection	Piping Leak Detection	Status
15	Diesel Fuel	20,000	South-central fueling area	1985	Unknown	Unknown	Unknown	Unknown	Removed in 2010
16	Diesel Fuel	20,000	South-central fueling area	1985	Unknown	Unknown	Unknown	Unknown	Removed in 2010
18	No. 2 fuel oil	2,500	West exterior of building	1987	Double-walled fiberglass	Steel	Electronic leak probes	Tightness testing	Active
93	Diesel fuel	20,000	South-central fueling area	2010	Double-walled fiberglass	Fiberglass reinforced plastic	Electronic leak probes	Electronic leak probes and auto line detection	Out of Use
94	Diesel fuel	20,000	South-central fueling area	2010	Double-walled fiberglass	Fiberglass reinforced plastic	Electronic leak probes	Electronic leak probes and auto line detection	Out of Use
95	Diesel fuel	20,000	South-central fueling area	2010	Double-walled fiberglass	Fiberglass reinforced plastic	Electronic leak probes	Electronic leak probes and auto line detection	Out of Use

In addition to the above, a building permit with the Town of Huntington indicated four 10,000-gallon gasoline USTs and associated dispensers were to be removed and relocated at the site in 1981. However, the permit references an additional permit to replace an existing fueling station with three 20,000-gallon USTs installed on the southern portion of the site in 1985. No additional information on these potential former gasoline USTs was obtained during this assessment. However, based on the information reviewed during this assessment, it is likely these USTs were related to the three diesel fuel USTs and one gasoline UST located to the northeast of the fire pond, which were removed in 1986. The tanks were likely not relocated in 1981 and the permit remains on file in error. The fueling operations were later relocated to the current area on the southern portion of the site.

Tanks 18, 93, 94, and 95 (Current Diesel Fuel USTs and No. 2 Fuel Oil UST)

Tanks 93, 94, and 95 include three dispensers. According to the site contact, the diesel fuel USTs have been emptied and are no longer utilized. Reportedly, the ownership of these USTs will be transferred to Tribune in the near future. According to the site contact, these USTs were recently tightness tested and passed. VERTEX was not provided with a copy of these tightness testing results.

Tank 18 remains active and is associated with an emergency generator. According to the site contact, this UST was recently tightness tested and passed. VERTEX was not provided with a copy of these tightness testing results.

While releases have not been reported, these USTs are considered an environmental concern and should be closed by removal in accordance with applicable regulations.

Several former USTs operated at the site. Closure, sampling, and removal information associated with these USTs, if any, is discussed below.

Tanks 1, 2, 3, and 4 (25,000-Gallon Diesel Fuel USTs and 12,000-Gallon Gasoline UST)

Based on a review of historical information, these USTs and associated dispensers were located to the northeast of the current fire suppression pond. Due to building expansion in the mid-1980s, the USTs were removed and fueling operations were relocated to the southern portion of the site. No closure documentation associated with these former USTs was identified during this assessment. These former USTs without closure documentation are considered a REC. However, the USTs were located under a current structure, shallow impacted soils, if present, would have likely been removed during building expansion activities.

Tank 5 (2,000-Gallon Spill Containment/Solvent UST)

According to previous reports and facility drawings from the 1980s, this UST was located to the east of the fire suppression pond proximal to the current 2,500-gallon No.2 fuel oil UST. The UST was reportedly closed by removal in 1988. No additional details on this former UST was provided. This former UST without closure documentation is considered a REC.

Tanks 6 and 7 (25,000-Gallon No. 6 and 2 Oil USTs)

According to a spill closure report prepared in April 2014 by ERM, these USTs were originally proposed for abandonment in 2013. Prior to abandonment, tightness testing was performed on the tanks. Tank 6 passed the tightness test; however, Tank 7 failed and was immediately pumped out. Tank 6 remained in service for emergency generator fuel storage until early 2014 when it was replaced by an AST, emptied, and abandoned. Four soil samples were obtained beneath fuel oil Tank 7 and analyzed for VOCs and SVOCs prior to tank abandonment. No samples were obtained from beneath Tank 6 prior to its abandonment and no groundwater sampling was obtained. Soil sampling results for Tank 7 met cleanup levels except for benzo(a)anthracene and chrysene, which were above cleanup levels in two samples; however, in accordance with New York regulations, since the concentration of total PAH was below 500 milligrams per kilogram (mg/kg) in each sample, then the sample was considered to meet the cleanup level even with individual constituents exceeding their associated cleanup levels. Based on these sampling results, the NYSDEC allowed the tanks to be abandoned in place without requiring remedial actions. Based on the information provided, these USTs are not considered a REC to the site. However, as part of redevelopment activities, these USTs should be removed. Any residual subsurface impacts identified during removal should be remediated at that time.

Tank 8 (4,000-Gallon Industrial Waste UST)

According to the RCRA Closure Plan dated July 18, 2018, former spent developer and fixer drained directly into this former 4,000-gallon fiberglass UST. The UST was located outdoors near the southeast portion of the building. The 4,000-gallon UST was removed by Tyree Bros. Environmental Services, Inc. (Tyree) on June 12, 1989 and disposed of at Gershow Recycling in Medford, New York. The UST was removed as part of a basement boiler room expansion project. The basement foundation slab extended 18.5 feet below the first-floor slab. The 4,000-gallon UST had a diameter of seven feet and the bottom of the tank was situated at approximately 12.5 feet below grade. Therefore, at the time of the basement expansion project, the area with the former spent fixer and developer UST was over-excavated to a minimum depth of 18.5 feet below grade. No contaminated soil was identified during the tank excavation.

Tanks 14, 15, and 16 (20,000-Gallon Diesel Fuel USTs)

Three 20,000-gallon diesel USTs were installed in 1985 and removed in 2010 from the southern portion of the site. A LUST incident was reported upon removal of these USTs. A subsurface investigation was subsequently conducted, which included sampling the soil and groundwater around the former USTs and laboratory analysis of the samples for VOCs and SVOCs. Results of the 2010 sampling indicate that contaminant concentrations were below applicable cleanup standards. The results of the 2010 subsurface investigation were used to obtain regulatory closure of this LUST incident through the NYSDEC.

Refer to Appendix B for a copy of documents obtained from the NYSDEC.

8.0 DATA GAPS/DEVIATIONS

Significant data gaps that would affect VERTEX's ability to identify RECs at the site were not encountered during this assessment.

Deviations or deletions from the scope of work defined by ASTM E 1527-13 were not made. Our conclusions regarding the potential environmental impact of nearby, off-site facilities on the site are based on readily ascertainable information from the environmental databases and the assumed groundwater flow direction as inferred from the topography of the site and surrounding area. A detailed file review for these facilities was beyond the scope of work.

9.0 ADDITIONAL SERVICES

The following additional (non-ASTM) services were performed as part of this assessment.

9.1 Asbestos-Containing Materials (ACMs)

A visual survey of limited building areas was performed to assess major classes of accessible suspect ACM that may be present. Suspect ACM observed in the site building included thermal systems insulation, pipe wrap, vinyl floor tiles and associated mastics, ceiling tiles, and wallboard. The materials assessed were observed to be in primarily good physical condition. According to a June 2018 ACM survey completed at the site, ACMs (greater than 1%) were identified including approximately 30 square feet of 12”X12” black adhesive mastic on the first floor below a raised floor at a ramp outside the intermediate distribution frame and approximately 25 square feet of 12”X12” black mastic associated with vinyl floor tile in a first-floor cafeteria closet. These materials were found to be in good condition and non-friable. In addition, approximately 15,000 square feet of black mastic associated with vinyl floor tile and approximately 45,000 square feet of tan spray-on fireproofing was found throughout the building containing less than 1% asbestos. These materials were found to be in good condition.

While an ACM survey was recently completed, prior to demolition/renovation activities or other activities that could potentially disturb suspect ACM, including those areas/materials not tested during the previous ACM survey, additional sampling and analysis of suspect ACM will need to be conducted. Future activities that involve disturbance or removal of confirmed or suspect ACM are required to be conducted in accordance with NESHAP and other applicable local, state, and federal regulations. VERTEX has found that a written O&M Program assists owners in maintaining compliance with these applicable regulations.

9.2 Lead-Based Paint (LBP)

Based on the ages of the site buildings, LBP may be present in buildings at the site. LBP, if present, should be appropriately managed during proposed renovations or demolitions of site structures.

10.0 CONCLUSIONS

VERTEX has performed a Phase I ESA in conformance with the scope and limitations of ASTM E 1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, of the Newsday facility located at 235 Pinelawn Road, Melville, New York. Any exceptions to, or deletions from, this practice are described in Section 8.0 of this report. This assessment has revealed no evidence of RECs in connection with the site, except for the following:

- Historical printing operations on-site from 1978 to 2018.
- Former diesel fuel and gasoline USTs located to the northeast of the fire suppression pond, which were removed in 1986. No closure documentation associated with these USTs was provided.
- A former 2,000-gallon spill containment/solvent UST to the east of the fire suppression pond, which was removed in 1988. No closure documentation associated with this UST was provided.
- Historical wastewater discharge exceedances to on-site leaching basins.
- Staining adjacent to the dry well located in the southern basement area.
- The historical use of the hazardous materials storage shed.

The following HRECs were identified during this assessment:

- Twenty spill cases from 1989 to 2017, which have been closed by the NYSDEC. These include releases associated with USTs removed or abandoned in place in 2010 and 2014.

The following environmental concerns were identified during this assessment:

- The three 20,000-gallon diesel fuel USTs and one 2,500-gallon No. 2 fuel oil UST located at the site.
- The two 25,000-gallon fuel oil USTs, which were abandoned in place in 2014.
- The stormwater dry wells located throughout the site.
- The septic systems located adjacent to guard shacks.
- The active WWTP at the facility.
- Ongoing RCRA closure activities at the site.

Based on the findings of this assessment, VERTEX recommends the following:

- A subsurface investigation should be completed to evaluate subsurface soil and groundwater quality.
- The active USTs should be closed by removal in accordance with applicable regulations.
- The 25,000-gallon fuel oil USTs previously abandoned in place should be removed as part of site redevelopment activities.
- If the stormwater dry wells will be removed during site redevelopment, they should be closed in accordance with applicable regulations.
- During site redevelopment activities, the current septic systems should be abandoned in accordance with applicable regulations.
- The WWTP operations and associated permits should be transferred to future owners of the property. If the WWTP will no longer be utilized, it should be closed in accordance with applicable regulations.
- The RCRA Closure Plan should be implemented and completed with no further action by the NYSDEC.
- Prior to demolition, a comprehensive ACM survey should be completed. Suspect or known ACMs should be abated prior to demolition activities.

11.0 SCOPE AND LIMITATIONS

11.1 Purpose

The primary purpose of this assessment is to identify, to the extent feasible pursuant to the processes prescribed in ASTM E 1527-13, RECs in connection with the site. As defined in ASTM E 1527-13, a REC is "the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment." It does not include *de minimis* conditions that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A "historical REC" is defined in ASTM E 1527-13 as "a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls)." ASTM E 1527-13 defines the term "controlled REC" as "a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls)."

In conducting this assessment, VERTEX followed ASTM E 1527-13, as well as the U.S. Environmental Protections Agency's All Appropriate Inquires (AAI) Final Rule of November 1, 2005 as amended December 30, 2013. There were no exceptions to or deletions from this

practice, as described in Section 8.0 of the report. ASTM defines good commercial and customary practice for conducting an ESA of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. 9601) and petroleum products. This practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability. The practice constitutes "all appropriate inquiries into the previous ownership and uses of the facility in accordance with generally accepted good commercial and customary standards and practices" as defined at 42 U.S.C. 9601(35)(B).

As part of ASTM E 1527-13, Phase I ESAs must be conducted by or under the supervision of a qualified Environmental Professional. The AAI Final Rule defines an Environmental Professional as someone who possesses sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases on, at, in, or to a property, sufficient to meet the objectives and performance factors of the rule. We declare that to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 40 C.F.R. 312.10. We have the specific qualifications based on education, training and experience to assess a property of the nature, history, and setting of the site. We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312.

11.2 Detailed Scope-of-Services

As part of this Phase I ESA, and in accordance with the provisions of ASTM E 1527-13, VERTEX performed a visual reconnaissance of the site, noted use of adjoining properties, and conducted historical and regulatory records research. The following provides a more detailed description of the scope of services:

- Visual assessment of the site building(s), if present, and grounds to identify potential for on-site petroleum or hazardous material release(s).

- Visual assessment and categorization of the use of abutting and adjoining properties as potential off-site sources of petroleum or hazardous material contamination to the site.

- Review of reasonably ascertainable state and federal regulatory records related to on-site activities and to potential off-site activities to identify sources of petroleum or hazardous material contamination to the site.

- Review of reasonably ascertainable historical information to assess for potential on-site and off-site sources of petroleum or hazardous material contamination to the site.

- Review of reasonably ascertainable local records related to historical site ownership, usage, and development. This includes obtaining information from local environmental authorities to identify complaints, violations, citations, inspections, environmental liens, AULs, or institutional and engineering controls related to the site.

- Review of reasonably ascertainable documents and other resources for the site and site vicinity to evaluate current and historical development and renovation activities.

- Visual assessment for suspect Polychlorinated Biphenyl (PCB) containing equipment, e.g., transformers, elevators. Please note, this scope of work does not include an evaluation for or testing of suspect PCBs in building materials such as caulking, mastic/adhesives, oil-based paints, coatings and sealants. Currently, there are no regulatory requirements to test in-place building materials for the presence of PCBs. Although testing is not required for in place materials, owners are required to know the content of the waste streams that they generate and potentially sign waste profiles prior to disposal facility acceptance. Therefore, if

renovation or demolition activities are to be conducted at the site that will result in the generation of demolition debris, a contractor or waste disposal facility may request certification of knowledge of the waste stream or testing to determine if the material(s) contain PCBs for proper handling and disposal purposes.

- Visual assessment of the accessible areas of the site and review of available public records to assess the presence or absence of the following ASTM E 1527-13 non-scope considerations: ACMs and LBP.

- Preparation of a Phase I ESA report.

11.3 Significant Assumptions

Information obtained from the Client, the Client's representative, site representatives, individuals interviewed, and prior environmental reports is considered to be accurate unless VERTEX's reasonable inquiries clearly revealed otherwise.

Conditions observed were considered to be representative of areas that were not observed unless otherwise indicated.

The primary direction of groundwater flow is assumed to follow topography, unless otherwise indicated by measurement of the potentiometric surface or other quantifiable data.

VERTEX reviewed reasonably ascertainable public records with respect to past operations and ownership of the site in an attempt to determine past site usage. VERTEX is not a professional title insurance firm and makes no guarantee, express or implied, that the listing reviewed represented a comprehensive delineation of past site ownership or tenancy for legal purposes. The accuracy and completeness of information maintained in public records by public agencies

or other entities is assumed to be sufficient for the purposes of this Phase I ESA, and independent verification of its validity is beyond the scope of this investigation.

11.4 Limitations and Exceptions

Our professional services have been performed, our findings obtained, and our recommendations prepared in accordance with customary principles and practices in the fields of environmental science and engineering. The findings within this ESA utilized information that was practically reviewable per ASTM Practice E 1527-13, meaning that only relevant data relating to the subject site has been incorporated into the findings, disregarding extraordinary analysis of irrelevant data. The investigation conducted for this ESA was limited to data that were reasonably ascertainable, meaning that the information was publicly available, obtainable within the cost and time constraints under the scope of services for this project, and practically available. VERTEX is not responsible for the independent conclusions, opinions, or recommendations made by others based on the records review, site inspection, field exploration, and laboratory test data presented in this report.

It should be noted that all surficial environmental assessments are inherently limited in the sense that conclusions are drawn and recommendations developed from information obtained from limited research and site evaluation. Subsurface conditions were not field-investigated as part of this study and may differ from the conditions implied by the surficial observations. Additionally, the passage of time may result in a change in the environmental characteristics at this site and surrounding properties. VERTEX does not warrant against future operations or conditions, or against operations or conditions present of a type or at a location not investigated. VERTEX does not assume responsibility for other environmental issues that may be associated with the subject site.

This study is not intended to assess or otherwise determine if soil contamination, waste emplacement, or groundwater contamination exists. These data are accessible only by sampling

of subsurface material and groundwater through the completion of soil borings and the installation of monitoring wells and the chemical analyses of soil and groundwater samples. The scope of work, determined by the client, did not include these activities.

In view of the rapidly changing status of environmental laws, regulations and guidelines, VERTEX cannot be responsible for changes in laws, regulations, or guidelines that occur after the study has been completed and that may affect the subject site.

It must be noted that no investigation can absolutely rule out the existence of hazardous materials at a given site. This assessment has been based upon prior site history and observable conditions. Existing hazardous materials and contaminants can escape detection using these methods.

There were no significant data gaps or accessibility limitations that would affect VERTEX's ability to identify RECs at the sites, as discussed in Section 8.0.

While VERTEX may comment on environmental compliance matters that fall under the scope of this assessment, this study does not constitute a regulatory compliance audit, and does not document compliance with applicable state, federal, or local regulations.

11.5 Special Terms and Conditions

No special Terms and Conditions were agreed upon between the User and the Environmental Professional.

11.6 User Reliance

This report is for the exclusive use of the following entities:

- Hartz Mountain Industries, Inc., a New York corporation
- 235 Pinelawn Road South LLC, a Delaware limited liability company
- 235 Pinelawn Road North LLC, a Delaware limited liability company
- Hartz Mountain Associates, a New Jersey general partnership
- Ridge Associates II Limited Partnership, a New Jersey limited partnership
- API Stewart Holdings LLC, a California limited liability company
- Asset Preservation, Inc., a California corporation

No other party shall have the right to rely on any service provided by VERTEX without prior written consent. Use of this report by any other party shall be at such party's sole risk.

12.0 REFERENCES

Agencies Contacted:

Town of Huntington Assessor's Office

Town of Huntington Building and Housing Department

Town of Huntington Office of the Fire Marshal

Suffolk County Department of Health, Office of Wastewater Management

Suffolk County Department of Health, Office of Pollution Control

Suffolk County Department of Health, Office of Water Resources

Suffolk County Clerk's Office

New York State Department of Environmental Conservation (NYSDEC)

Other Documents Reviewed:

EDR Database Report, June 19, 2018

Aerial photographs dated 1938, 1947, 1953, 1957, 1962, 1966, 1970, 1976, 1980, 1985, 1994, 2008, 2011, and 2015.

Sanborn Fire Insurance Maps Unmapped Property Letter dated June 19, 2018

City directories dated 1972 to 2014.

Topographic maps dated 1901, 1903, 1904, 1942, 1947, 1954, 1967, 1969, 1979, and 2013.

Phase I Environmental Site Assessment – DRAFT, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated July 2017

Limited Phase II Investigation Report – DRAFT, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated March 8, 2018

Summary of Environmental Conditions, Newsday Media Group Facility, 235 Pinelawn Road, Melville, New York 11747, prepared by RPS, dated May 22, 2018

Asbestos-Containing Material Survey, Newsday, 235 Pinelawn Road, Melville, NY, prepared by RPS, dated June 2018


RCRA Closure Plan, Newsday LLC, 235 Pinelawn Road, Melville, New York 11747, prepared by H2M, dated July 18, 2018

Interviews:

Mr. Stephen Zimmerman, Directory of Engineering Services with Newsday


Mr. Tim Winter, Manager of Security with Newsday

FIGURES



USGS Topographic Map, 2013
Huntington, NY Quadrangle
Contour Interval: 15 Feet

SITE LOCUS MAP Newsday 235 Pinelawn Road Melville, NY	SCALE: 1:25,000 September 2018 VERTEX Proj. No. 51921	**FIGURE NO. 1**



	Base Map Source: GEOMATRIX PHASE I ESA FIGURE 2 DATED MARCH 2008	**SITE SCHEMATIC** NEWSDAY 235 PINELAWN ROAD, MELVILLE, NY	**FIGURE NO. 2** VERTEX Project No. 51921	VERTEX® THE VERTEX COMPANIES, INC.

APPENDIX A:

PHOTOGRAPHIC DOCUMENTATION

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #1: Northwestern exterior of the site building.



Photo #2: Western exterior of the site building.



Photo #3: 15,000-gallon No. 2 fuel oil AST on the eastern portion of the site.



Photo #4: 2,500-gallon No. 2 No. 2 fuel oil UST located along the western exterior of the building.



Photo #5: Location of three 20,000-gallon diesel fuel USTs and associated pump islands on the southwestern portion of the site.



Photo #6: Effluent recharge area to the north of the wastewater treatment plant.

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #7: Wastewater treatment plant building.



Photo #8: Wastewater treatment aerators.



Photo #9: Methanol drum storage in the wastewater treatment building.



Photo #10: View of the chemical storage building.



Photo #11: Used oil drums in the chemical storage building.



Photo #12: Emergency generators located along the northwestern exterior of the building.

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #13: Fields on the northwestern portion of the site.



Photo #14: View of the printing press machines within the site building.



Photo #15: Packaging area within the site building.



Photo #16: Out of use parts washer located in a machine room on the 2nd floor.



Photo #17: Press products drum storage area.



Photo #18: Out of use parts washer.

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #19: View of a machine shop within the site building.



Photo #20: Floor staining located in a wash area.



Photo #21: Oil/water separator.



Photo #22: Drums utilized for storage of trash within the site building.



Photo #23: Water treatment chemicals.



Photo #24: Sump with staining adjacent to an oil/water separator.

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #25: Water treatment chemicals.



Photo #26: Grease trap.



Photo #27: Dry well located in the exterior southern basement.



Photo #28: Emergency generator diesel fuel day tank located in the southern basement area.



Photo #29: Tank located in the ink reclamation area.



Photo #30: Diesel fuel day tank with associated staining.

Photographic Documentation
Newsday
235 Pinelawn Road
Melville, NY 11747
VERTEX Proj. No. 51921



Photo #31: Adjacent BAPS temple to the west across Deshon Drive.



Photo #32: Adjacent light industrial building to the south.



Photo #33: Adjacent light industrial building to the southwest.



Photo #34: Adjacent gym to the northeast.

APPENDIX B:

RELEVANT DOCUMENTS

RPS

Formerly GaiaTech

Confidential

Phase I Environmental Site Assessment - DRAFT

Newsday

235 Pinelawn Road | Melville, New York

July 2017 | RPS GaiaTech Project No. 166126.613.00

Prepared for: Tribune Media Company



Energy | Environmental Risk | Infrastructure | Ocean Science

EXECUTIVE SUMMARY

Tribune Media Company retained GaiaTech Incorporated dba RPS GaiaTech to conduct a Phase I Environmental Site Assessment (ESA) of the Newsday facility located at 235 Pinelawn Road in Melville, Suffolk County, New York (the site). RPS GaiaTech conducted the Phase I ESA to identify Recognized Environmental Conditions (RECs), as defined by ASTM International *Standard Practice for Environmental Site Assessments* - E 1527-13 (ASTM-13). RPS GaiaTech performed the Phase I ESA to constitute all appropriate inquiry consistent with good commercial and customary practice.

The site is owned by Tribune ND, Inc. (successor-in-interest to Tribune Company). Newsday leases the site from Tribune ND, Inc. Newsday operates a newspaper publishing and distribution company producing approximately 350,000 newspapers per day. Operations consist of the printing, plate development, digital photographic development, ink mixing, and newspaper sorting, bundling, and distribution. Newsday stores inks in ten aboveground storage tanks (ASTs) and operates three large printing presses, five digital photo developing lines and four plate development lines. Printing equipment maintenance conducted at the site includes cleaning (plate cleaning and parts washing) and fluid replenishing (press oil for printing presses and propane cylinders for forklifts). Newsday operates approximately 30 electric forklifts, 2 propane forklifts, 8 clamp trucks, 1 maintenance truck and 1 van. The forklifts are serviced on-site by Newsday employees; no other vehicles are serviced on site and no vehicle washing occurs on site. Fueling of fleet vehicles is conducted on site using three underground storage tanks (UST) systems. Treatment of process wastewater and floor wash water is conducted in an on-site wastewater treatment plant located outside the building, which ultimately discharges to the exterior ground surface. The UST systems and wastewater treatment plant are discussed further below.

The approximately 50-acre site is developed with an approximately 539,000-square-foot production building, which is divided between an office area and production areas, and a wastewater treatment plant. The production areas contain a packaging and bundling area, a reel room (where paper reels are fed to the printing lines), two levels of printing presses (including the printing presses, photo developing lines, and plate developing lines discussed above), boiler rooms, emergency generator rooms, a cooling tower room, various chemical storage areas, mechanical rooms, electrical rooms, maintenance shops, and a paper reel storage warehouse. Chemical storage areas include three bermed areas (containing fountain solution ASTs, press oil and degreasers), and ink AST storage rooms on the first floor of the production area, and in an ink reclamation room and maintenance rooms on the second floor. Exterior features include two emergency generators (with two associated 1,100-gallon diesel fuel ASTs), trash compactors, scrap metal dumpsters, pallet storage and two pad-mounted transformers to the north of the building. To the west of the building is the wastewater treatment plant, a chemical storage shed (containing glycol, oil and paints), a fire suppression pond, out of use equipment (trash compactors, 40-yard dumpsters, pallets, etc.), a 40-yard recycling dumpster, a trash compactor, and a semi-enclosed emergency generator (with one 2,500-gallon fuel oil UST); the wastewater treatment plant includes sludge settling tanks, aerators and membranes, 11 underground pools, and a building containing two air compressors, a storage area for

wastewater treatment chemicals, and a laboratory. Three 20,000-gallon diesel fuel USTs with associated fuel dispensers (for vehicle fueling) are located to the southwest of the building and one 15,000-gallon fuel oil AST used to fuel boilers is located to the east of the building. Security guard stands, a baseball field and basketball court are present on the northern portion of the site.

By the early 1900s, the site consisted of agricultural land with a road traversing the central portion from east to west. Also at this time, associated farmstead residences were present on the southeast corner of the site. The site remained unchanged until the early 1950s, when an additional residence was constructed on the northeast corner of the site. In the mid-1970s the farmsteads on the southeast and northeast corners of the site were razed and in 1977, the site was redeveloped with the original portion of the current production building, the fire suppression water pond, the chemical storage shed, and the wastewater treatment plant. By the early 1990s, the production building was expanded to the south and west and the fuel pump island was constructed on the southern portion of the site. By the mid-2000s, a baseball field was constructed on the northwest corner of the site, bringing the site into its current configuration. According to the site representative, the site converted from chemical to digital photo development and has downsized in printing operations over the last 10 years. Historical site operations including current and historical use of USTs and ASTs are discussed further below.

Based on available historical records, RPS GaiaTech was able to identify a total of 15 underground tanks that are currently or were formerly operated at the site. Eight of these tanks were installed for Newsday in 1978, which include three 25,000-gallon diesel USTs, one 12,000-gallon gasoline UST and one 2,000-gallon underground spill containment tank (all removed in 1986); a 25,000-gallon No. 6 fuel oil UST and a 25,000-gallon No. 2 fuel oil UST (abandoned in place in 2010); and a 4,000-gallon industrial waste UST removed in 1987. One 2,500-gallon fuel oil UST was installed in 1987 currently still in use at the site. Three 20,000-gallon diesel USTs were installed in 1985 and replaced in 2010 with three new 20,000-gallon diesel USTs, which remain active. These USTs are discussed further below.

The site is located in an area currently characterized by residential development, commercial warehouses, and light industrial developments. In the early 1900s, the site area was agricultural land with associated farmsteads. Rural residential development expanded between the early 1950s and the early 1960s. By the mid-1960s, Ruland Road was constructed to the north and Pinelawn Road was constructed to the east of the site. Also at this time, light industrial and commercial development began to the north and farther south of the site. Light industrial development along Ruland Road and Deshon Drive continued through the 1990s including facilities on the northeast, south, southwest and west-adjacent properties. By the mid-2000s, residential development expanded farther west. The west-adjacent light industrial building was razed by 2013, and the current west-adjacent apartment complex and light industrial building were constructed by 2016, bringing the surrounding properties into their current configuration. Surrounding properties with a potential for impact are discussed below.

Findings

RPS GaiaTech has performed this Phase I ESA in conformance with the scope and limitations of ASTM-13 of the Newsday facility located at 235 Pinelawn Road in Melville, Suffolk County, New York. Environmental conditions and issues associated with the site are characterized as RECs, Controlled RECs (CRECs), Historical RECs (HRECs), de minimis conditions, noteworthy condition, or other issues as defined in Section 1.0 of this report. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report.

This assessment identified the following RECs in connection with the site:

- **Historical Site Operations:** Newsday has operated as a newspaper printing facility since the late 1970s. Printing operations have included the use of inks, washes, oils, and chlorinated solvents, the generation of hazardous wastes such as silver and spent chlorinated and non-chlorinated solvents, use of several current and historical USTs, and wastewater treatment operations; treated wastewater has been discharged to the exterior ground surface. Additionally, records of several release incidents were identified in historical records with regulatory closure. Many of these releases involved limited quantities of material, but also included incidents in 2000 related to a release of 1,600 gallons of diesel and in 2012 related to release of 500 gallons of combined industrial/wastewater sewage. Although regulatory closure was achieved for these releases, confirmatory sampling information was not provided to demonstrate no impacts remain from these incidents. Subsurface investigations were conducted around three former diesel fuel USTs and two fuel oil USTs (discussed further below); however, it appears that no subsurface investigations have been conducted to specifically address the other six former USTs. The long duration of printing operations involving the on-site discharge of treated wastewater, historical use of chlorinated solvents, operation of USTs, and history of repeated release incidents represents a potential for impact to the site.

- **Open Release Incident:** A release of 4 gallons of compressor oil was reported at the site in 2016 due to equipment failure. Drains in the production areas are connected to an oil/water separator before discharging to the on-site wastewater treatment plant. The spill was not listed as closed on the New York Department of Environmental Conservation (NYDEC) spills database. Because the spill involved a very limited quantity of oil and the release was captured by the wastewater treatment plant the potential for environmental impact from this release is low. However, it appears that the incident has not received regulatory closure; therefore, additional regulatory action may be required.

This assessment identified the following CREC in connection with the site:

- **Recently Closed USTs:** Three 20,000-gallon diesel USTs were installed in 1985 and removed in 2010 from the southern portion of the site. A Leaking UST (LUST) incident was reported upon removal of these USTs. A subsurface investigation was subsequently conducted, which included sampling the soil and groundwater around the former USTs and laboratory analysis of the samples for volatile organic compounds (VOCs) and Semi-VOCs (SVOCs). Results of the 2010 sampling results indicate that contaminant

concentrations were below applicable cleanup standards; however, because the full closure report was not provided for RPS GaiaTech's review, the exact location of the samples could not be determined. The results of the 2010 subsurface investigation were used to obtain regulatory closure of this LUST incident through the NYDEC. Additional subsurface soil sampling was conducted in 2014 after the abandonment of two 25,000-gallon fuel oil USTs. The investigation was conducted beneath one of the two USTs and identified two individual polycyclic aromatic hydrocarbons (PAHs) in the soil above applicable cleanup standards, but because total PAH was below 500 milligrams/kilograms (mg/kg) in each sample, the samples are considered to meet the cleanup standards even with individual exceedances; groundwater was not sampled during this investigation. Based on the sampling results, the USTs were given clean closure with no reported release. Available sampling data indicates that remaining contaminant concentrations around these former USTs are below applicable risk-based screening levels and regulatory closure has been granted for the reported release incidents, full UST closure documents to confirm the location sampling; therefore, RPS GaiaTech cannot confirm that confirmation sampling was conducted adequately to identify potential impacts.

This assessment identified the following noteworthy condition in connection with the site:

- **Surrounding Properties:** The surrounding area has been occupied by various light industrial facilities since at least the mid-1960s. Four adjacent facilities were identified with ASTs, USTs, hazardous waste generation, and releases. Records of 17 USTs and 10 reported releases were identified on these four facilities. The long history of industrial operations in the surrounding area with USTs and reported releases represents a potential for impact; however, because each of the reported releases were issued regulatory closure, the potential for impact to the site appears to be low.

This assessment identified the following other consideration in connection with the site:

- **Asbestos Containing Materials (ACMs):** RPS GaiaTech identified suspect and presumed ACMs in the form of drywall systems, drop ceiling tiles, vinyl floor tile and associated mastics and thermal system insulation (TSI) pipe wrapping in the production area of the building. Since the building was constructed prior to 1981 and due to the presence of vinyl floor tile, surfacing material and TSI, the OSHA regulations regarding management of vinyl floor tile and presumed ACMs (PACMs) in building materials apply to the site. It does not appear that there are programs in place at the site to address these requirements.

This Executive Summary is not intended to be used as a "stand alone" document, but is a summary of the complete Phase I ESA report. Information included in the Executive Summary is subject to the scope of services and limitations noted in the proposal and complete report text.

ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that, to the best of my/our professional knowledge and belief, I meet the definition of Environmental Professional as defined in 40 CFR Part 312, and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Prepared by:

DRAFT

Grace Riordan
Environmental Consultant

Technical Review and Concurrence by:

DRAFT

Robert B. Anderson
Principal Consultant
Environmental Professional



Contents

Executive Summary

1.0 Introduction

2.0 Current Site Description

3.0 Site Inspection and Reconnaissance

4.0 User Information Provided

5.0 Environmental Database Review

6.0 Site History

7.0 Surrounding Properties

8.0 Non-ASTM Scope of Work

9.0 Findings

10.0 References

11.0 Limitations, Exceptions and Significant Assumptions

Appendices

1.0 INTRODUCTION

Tribune Media Company retained GaiaTech Incorporated dba RPS GaiaTech to conduct a Phase I Environmental Site Assessment (ESA) of the Newsday facility located at 235 Pinelawn Road in Melville, Suffolk County, New York (the site).

The purpose of the Phase I ESA was to identify Recognized Environmental Conditions (RECs), as defined by the ASTM International *Standard Practice for Environmental Site Assessments* - E 1527-13 (ASTM-13) or the existence of hazardous substances under the federal AAI standards. RPS GaiaTech performed the Phase I ESA to constitute all appropriate inquiry consistent with good commercial and customary practice.

Based on the Environmental Professional's (EP's) evaluation of available information, findings of this report are classified and defined as follows:

- REC: the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment.
- Controlled REC (CREC): a REC that resulted from a past release that has been addressed to the satisfaction of the applicable regulatory authority, with contamination allowed to remain in place subject to the implementation of required controls;
- Historical REC (HREC): a past release that has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls;
- De minimis condition: a condition that could otherwise be considered a REC but in the EP's opinion does not appear to represent a threat to human health or the environment and/or would not likely be the subject of an enforcement action if brought to the attention of appropriate governmental agencies;
- Noteworthy condition: a contingent site risk that does not clearly fall within the ASTM definition of a REC, HREC, or de minimis condition and/or a risk that can have a material environmental or environmentally-driven impact on the business.
- Other consideration: an environmental issue or condition (e.g. asbestos, radon, or mold) at a property that falls outside of the scope of the ASTM-13 practice.

1.1 Scope of Work

RPS GaiaTech conducted the Phase I ESA in overall accordance with industry standards, including the requirements of ASTM-13 or the federal All Appropriate Inquiry (AAI) standard.

This report documents the research methodology used by qualified environmental professionals of RPS GaiaTech to conduct the Phase I ESA of the site and presents the findings of the assessment. The Phase I ESA included the following activities, subject to any limitations noted in this report:

1. Interviews with site owner(s), key site manager(s), and major occupant(s) and a review of site records with regard to current and former site operations that may have impacted the site.

   Information was provided to RPS GaiaTech by:

   - Mr. Stephen Zimmerman, Director of Engineering Services for Newsday, associated with the site for 33 years
   - Ms. Joe Marino, Senior Facilities Manager for Newsday, associated with the site for 19 years

2. A comprehensive site inspection to identify and evaluate potential sources of environmental impact, including but not limited to waste and chemical storage areas, underground storage tanks (USTs), aboveground storage tanks (ASTs), equipment containing polychlorinated biphenyls (PCBs), and wastewater and stormwater discharges. The inspection included observations for evidence of chemical spills, releases, or on-site waste disposal. A Site Location Map and a Site Layout and Area Map are included in Appendix A. Photographs of the site are included in Appendix B.

3. A review of historical information for potential on- or off-site sources of impact to the site. To the extent feasible under the conditions of the assessment, the historical information obtained included: verbal information and records from site and/or local agency representatives; previous reports; construction plans; building permits; property record cards; topographic maps; fire insurance maps; historical city directories; and aerial photographs. Copies of relevant historical documentation are included in Appendix C.

4. A visual survey of the properties in the vicinity of the site as observed from the site boundaries and public rights-of-way to evaluate the potential for impact to the site from these properties. A Site Layout and Area Map is included in Appendix A.

5. A review of tribal, state, and federal environmental database information, provided by Environmental Data Resources, Inc. (EDR) supplemented by agency interviews and record review, where appropriate. The database search was conducted using ASTM-designated search parameters; for parameters requiring a search of the site and adjacent properties only, the search radii were extended to ensure that ASTM-13 required search distances from the property boundary were met. Facilities listed in the database report as "unplottable" were reviewed to evaluate whether any are located in the immediate vicinity of the site, based on field observations. The database search report is included as Appendix D.

6. As determined necessary by the EP and beneficial in determining the environmental risk associated with nearby facilities, supplemental research (potentially including the review

of agency files, interviews with agency representatives, or others familiar with surrounding properties) was conducted.

7. Review of public health records and records of institutional and engineering controls pertaining to the site, as available through state listings provided by EDR, recorded on the current deed, or readily available in land title records. RPS GaiaTech notes this is not a professional lien search. The User of this report (as defined by ASTM-13) did not provide a professional environmental liens search for the site and did not request RPS GaiaTech to obtain one.

8. Environmental concerns, which are beyond the scope of a Phase I ESA as defined by ASTM-13 include the following: asbestos-containing materials (ACMs), lead-based paint (LBP), radon, lead in drinking water (LIDW), mold and wetlands. These issues may affect environmental risk at the site and may warrant discussion and/or assessment; however, are considered non-scope issues. If specifically requested by the Client, these non-scope issues are discussed in Section 8.0.

9. A review of vapor migration associated with on and off-site sources of known and potential environmental impact.

Information sources used to develop the conclusions of this report are presented in Section 10.0.

1.2 Project-Specific Limitations

No project-specific limitations were identified that would constitute a data gap or potentially affect the ability of the EP to form a conclusion regarding the site.

1.3 User Reliance

RPS GaiaTech performed this Phase I ESA on behalf of and exclusively for Tribune Media Company. This report and the findings shall not be relied upon, in whole or in part, by any other party, except by or with the express consent of RPS GaiaTech and an authorized representative of Tribune Media Company.

Any reliance upon this report by third parties beyond its intended purpose shall be at the parties' sole risk. In the event reliance on this report to additional parties is authorized in writings, these parties may become "users" as defined by ASTM-13 and should independently confirm that they have addressed the User requirements outlined in ASTM-13. Reliance by authorized parties is subject to RPS GaiaTech's standard terms and conditions.

2.0 CURRENT SITE DESCRIPTION

2.1 Site Location and Ownership

The approximately 50-acre site is located at 235 Pinelawn Road in Melville, Suffolk County, New York. The site is accessible from Ruland Road, Deshon Drive and Pinelawn Road which border the site to the north, east and west, respectively.

The site is currently owned by Tribune ND, Inc. (successor-in-interest to Tribune Company). The most recent deed identified in the records reviewed was a Deed to Tribune ND, Inc. from Tribune Company, dated December 26, 2008. No environmental liens or Activity and Use Limitations (AULs) were attached to the deed or otherwise identified in the historical resources.

Newsday leases the site from Tribune ND, Inc. RPS GaiaTech reviewed a lease agreement dated May 11, 2008 between Tribune Company and Newsday.

2.2 Current Occupants and Operations

Newsday operates a newspaper publishing and distribution company producing approximately 350,000 newspapers per day. Operations consist of the printing, plate development, digital photographic development, ink mixing, and newspaper sorting, bundling, and distribution. Newsday stores inks in ten aboveground storage tanks (ASTs) and operates three large printing presses, five digital photo developing lines and four plate development lines. Printing equipment maintenance conducted at the site includes cleaning (plate cleaning and parts washing) and fluid replenishing (press oil for printing presses and propane cylinders for forklifts). Newsday operates approximately 30 electric forklifts, 2 propane forklifts, 8 clamp trucks, 1 maintenance truck and 1 van. The forklifts are serviced on-site by Newsday employees; no other vehicles are serviced on site and no vehicle washing occurs on site. Fueling of fleet vehicles is conducted on site using three underground storage tanks (UST) systems. Treatment of process wastewater and floor wash water is conducted in an on-site wastewater treatment plant located outside the building, which ultimately discharges to the exterior ground surface.

2.3 Site Layout

The general site layout depicting buildings, structures and other pertinent features is shown in the Site Layout and Area Map, Appendix A. These features are briefly described in the following sections.

2.3.1 Buildings and Interior Features

The approximately 50-acre site is developed with an approximately 539,000-square-foot production building, which is divided between an office area and production areas, and a wastewater treatment plant. The production areas contain a packaging and bundling area, a reel room (where paper reels are fed to the printing lines), two levels of printing presses (including

the printing presses, photo developing lines, and plate developing lines discussed above), boiler rooms, emergency generator rooms, a cooling tower room, various chemical storage areas, mechanical rooms, electrical rooms, maintenance shops, and a paper reel storage warehouse. Chemical storage areas include three bermed areas (containing fountain solution ASTs, press oil and degreasers), and ink AST storage rooms on the first floor of the production area, and in an ink reclamation room and maintenance rooms on the second floor. These features are further described in Section 3.0, as needed.

2.3.2 Exterior Features

Exterior features include two emergency generators (with two associated 1,100-gallon diesel fuel ASTs), trash compactors, scrap metal dumpsters, pallet storage and two pad-mounted transformers to the north of the building. To the west of the building is the wastewater treatment plant, a chemical storage shed (containing glycol, oil and paints), a fire suppression pond, out of use equipment (trash compactors, 40-yard dumpsters, pallets, etc.), a 40-yard recycling dumpster, a trash compactor, and a semi-enclosed emergency generator (with one 2,500-gallon fuel oil UST); the wastewater treatment plant includes sludge settling tanks, aerators and membranes, 11 underground pools, and a building containing two air compressors, a storage area for wastewater treatment chemicals, and a laboratory. Three 20,000-gallon diesel fuel USTs with associated fuel dispensers (for vehicle fueling) are located to the southwest of the building and one 15,000-gallon fuel oil AST used to fuel boilers is located to the east of the building. Security guard stands, a baseball field and basketball court are present on the northern portion of the site. These features are further described in Section 3.0, as needed.

2.3.3 Paving, Landscaping and Unimproved Areas

The majority of the site is paved and landscaping is present around building perimeters and at various locations throughout the site.

2.4 Utilities

The building is heated with natural gas and diesel-fueled boilers and cooled electrically. Water and sanitary sewer services are municipally provided. No current or historical potable wells or septic systems were identified at the site.

2.5 Physical Setting

Topography and Drainage

The 7.5-minute topographic map of the area (*Huntington, New York* quadrangle, 2013) indicates that the site is located at an approximate elevation of 100 feet above mean sea level. The site is located in a relatively flat area that drains in various directions toward local drainage features that discharge southeast into the Carlls River, located approximately three miles to the southeast. The Carlls River then flows south into Great South Bay.

Soil and Geology

According to information provided in the environmental database search report and the *Web Soil Survey* (published on-line by the Natural Resource Conservation Service), the soils in the site area consist primarily of the Haven loam, which consists of well-drained silty clay with a moderate infiltration rate. Based on the 2008 report, the near-surface geology is composed of sandy materials mingled with outwash sand and gravel. Depth to bedrock was not available.

Hydrogeology
Area topography indicates that groundwater flow in the site area is likely to the southeast, and properties to the northwest are presumed to be upgradient. Site-specific groundwater depth information was not available. Based on the online Long Island Depth to Water Viewer, groundwater is approximately 31 to 50 feet bgs.

2.6 Water Resources and Wells

Drinking water is provided to the site and surrounding properties by the Dix Hills Water District, which obtains water from municipal wells and the Glacial and Magothy aquifers. Fifteen private water wells were noted within one mile from the site. No municipal or public water supply wells were identified within 1-mile of the site.

3.0 SITE INSPECTION AND RECONNAISSANCE

RPS GaiaTech conducted the site inspection on June 26, 2017, and the following sections present RPS GaiaTech's observations at that time. The site reconnaissance was limited to readily accessible areas and did not include areas beneath floors, above ceilings or behind walls.

3.1 Aboveground Storage Tanks (ASTs)

ASTs present during the site inspection are provided below. Unless otherwise described, no leaks, spills, stains or other evidence of releases were identified in connection with the ASTs. No evidence of historical ASTs was identified during the site reconnaissance.

Currently In-Use AST Summary			
Contents	***Capacity***	***Location***	***Storage Conditions***
Printing ink	Four 2,000-gallon and six 8,000-gallon ASTs	Various ink storage rooms	On epoxy-coated concrete floors
No. 2 fuel oil	One 25-gallon AST, and one 15,000-gallon AST	Within emergency generators/boiler rooms inside and east of the building	Within the emergency generators with secondary containment
Diesel fuel	One 275-gallon AST, two 100-gallon ASTs, two 1,110-gallon ASTs and one 125-gallon AST	Within emergency generators inside and north of the building	Within secondary containment
Industrial waste	Two 50-gallon, one 60-gallon, two 200-gallon ASTs, two 500-gallon AST	Press room storage areas	Within secondary containment
Cooling tower blow down water	One 550-gallon AST	Cooling tower room	Within secondary containment
Fountain solution	Six 500-gallon ASTs	Printing press area	Within secondary and tertiary containment
Descaling fluid	Four 8-gallon reservoirs and four 80 to 140-gallon ASTs	Boiler rooms and the cooling tower room	Within secondary and tertiary containment

The following historical ASTs were identified at the site:

UST System(s) Summary				
Tank ID	*Contents*	*Capacity*	*Installment Date*	*Removal Date*
13	Industrial Waste	100	1978	2001
26	Industrial Waste	2,000	1989	2002
27	Industrial Waste	2,000	1989	2002
28	Industrial Waste	250	1989	2003
30	Caustic	1,500	Unknown	2006

39	Cooling tower blow down	300	Unknown	2003
43	Industrial Waste	100	1998	2002
45	Developer	100	Unknown	Unknown
46	Fixer	100	Unknown	Unknown
47	Fixer	100	Unknown	Unknown
50	Parts washer solvent	200	Unknown	2005
51	Fountain solution	330	Unknown	2002
52	Fountain solution	330	Unknown	2002
53	Fountain solution	330	Unknown	2002
54	Fountain solution	330	Unknown	2002
55	Diesel	1,250	Unknown	2006
56	Diesel	1,250	Unknown	2006
65	Methanol	225	Unknown	Unknown
71	Hydraulic oil	81	Unknown	2013
72	Hydraulic oil	600	Unknown	2001

3.2 Underground Storage Tanks (USTs)

Newsday currently operates UST systems at the site that consist of four USTs, four fuel dispensers, and associated underground piping. Three of the UST systems are located on the southern portion of the site near the fuel pump island, and the fourth UST is located west of the building, as depicted in Appendix A. The following UST system information summary was developed based on information obtained from the New York Department of Environmental Conservations (NYDEC) and the site representatives:

UST System(s) Summary				
Item	*Tank 1*	*Tank 2*	*Tank 3*	*Tank 4*
Tank ID	*93*	*94*	*95*	*18*
Status and Registration	Currently in use; registered	Currently in use; registered	Currently in use; registered	Currently in use; registered
Contents	Diesel	Diesel	Diesel	#2 Fuel Oil
Date of installation	2010	2010	2010	1987
Capacity	20,000 gallons	20,000 gallons	20,000 gallons	2,500 gallons
Tank Construction	Double-walled Fiberglass	Double-walled Fiberglass	Double-walled Fiberglass	Double-walled Fiberglass
Piping Construction	Fiberglass-reinforced plastic (FRP)	Fiberglass-FRP	Fiberglass-FRP	Steel
Piping Type	Unknown	Unknown	Unknown	Unknown
Tank Leak Detection	Electronic Leak Probes	Electronic Leak Probes	Electronic Leak Probes	Electronic Leak Probes
Piping Leak Detection	Electronic Leak Probe & Auto Line	Electronic Leak Probe & Auto Line	Electronic Leak Probe & Auto	Tightness Testing

	Leak Detector	Leak Detector	Line Leak Detector	
Spill and Overfill Protection	Overfill or spill bucket and/or sump	Overfill or spill bucket and/or sump	Overfill or spill bucket and/or sump	Overfill or spill bucket and/or sump

The following historical USTs were identified at the site:

UST System(s) Summary				
Tank ID	*Contents*	*Capacity*	*Installment Date*	*Removal Date*
1	Diesel	25,000	1978	1986
2	Diesel	25,000	1978	1986
3	Diesel	25,000	1978	1986
4	Gasoline	12,000	1978	1986
5	Spill containment	2,000	1978	1988
6	No. 6 fuel oil	25,000	1978	Abandoned 2010
7	No. 2 fuel oil	25,000	1978	Abandoned 2010
8	Industrial Waste	4,000	1978	1987
14	Diesel	20,000	1985	2010
15	Diesel	20,000	1985	2010
16	Diesel	20,000	1985	2010

The status of the current and historical USTs are discussed is Section 6.1.

3.3 Petroleum and Hazardous Substances

In addition to materials stored in ASTs and/or USTs, described above, the types and quantities of chemicals used and stored on site are listed in the following table. Unless otherwise described below, no leaks, spills, stains or other evidence of releases were identified in the chemical storage areas.

Material	***Use***	***Location***	***Container Type and Maximum Quantity***
EZ Blue Cleaner	Degreaser	Caged drum storage within the first floor of the printing press	20, 55-gallon drums
Welding gases (acetylene and oxygen)	Welding operations	Welding room in the second floor press shop	9 cylinders
Propane	Forklifts	Rack within the press room	10 cylinders
Press Oil	Machine maintenance	Printing press	30, 55-gallon drums
Dowfrost glycol	Compressors	Hazardous materials storage building	4, 55-gallon drums
Biological phosphorus removal additive	Wastewater treatment	Wastewater treatment building	5, 55-gallon drums

Material	*Use*	*Location*	*Container Type and Maximum Quantity*
Plate cleaning solvent (non-chlorinated)	Plate cleaner	Ink reclaiming area	16, 55-gallon drums
Parts washer solvent (non-chlorinated)	Parts cleaning	Maintenance shop	One 200-gallon and two 40-gallon parts washers
Hydraulic oil	Fueling and maintaining elevator equipment	Elevator equipment room and elevator pits	Approximately 30-gallon equipment reservoir

3.4 Solid and Hazardous Waste

The following non-hazardous solid and special wastes are generated and managed at the site:

Waste Stream	*On-Site Storage*	*Transporter*
Trash and recycling	2, 40-yard dumpsters	City of Melville
Scrap metal	2, 40-yard dumpsters	Two Brothers Scrap Metal
Cardboard	Compactor	City of Melville
Used rags	5-yard dumpster	United Industrial Services
Grease trap solids	Grease trap	Local hauler
Used oil, empty drums and used containers	Within drum storage areas of the production areas	United Industrial Services
Parts washer fluid (petroleum distillates)	One 200-gallon and two 40-gallon parts washers	Safety Kleen

3.5 Stormwater

Stormwater infiltrates into soil, landscaped and gravel covered areas, or discharges into on-site stormwater collection features. These features include storm drains in the paved parking lots and a fire suppression water pond west of the building. No visual indications of oil or other pollutants were noted in the vicinity of the drains or the pond. No staining or stressed vegetation was noted; no sheen was noted on the surface of the water in the pond.

3.6 Spills, Releases, and Distressed Vegetation

RPS GaiaTech did not observe evidence of spills, releases, or stressed/dead vegetation.

3.7 Other Pertinent Site Features and Conditions

Additional pertinent features and conditions identified at the time of the site reconnaissance are listed in the following table. Additional discussion pertaining to those features and/or conditions observed is provided below the table.

Item	*Identified?*	
	Yes	*No*
Potential PCB-Containing Equipment	X	

On-Site Waste Disposal or Miscellaneous Debris		X
Septic Systems		X
Wastewater Discharges (Non-Sanitary)	X	
Sinks, Drains, Sumps	X	
Oil-Water Separators, Sand Traps, Clarifiers	X	
Pits, Ponds, Lagoons	X	
Strong, Pungent or Noxious Odors		X
Fill Material (Non-Structural), Terrain Anomalies		X
Unidentified Substances or Containers		X

Potential PCB-Containing Equipment

Two pad-mounted oil-filled transformers were observed at the site. The transformers were not labeled as "non-PCB". No leaks or stains were observed around the base of the transformers. The transformers are owned by ComEd.

Wastewater Discharges

Wastewater generated from newspaper production and wastewater in the production areas is directed through floor drains in the production areas to an oil/water separator before being treated at the wastewater treatment plant west of the building. Wastewater is treated using a combination of pre-equalization screens, rotary aerators, membrane clarifiers and sludge settling tanks. The treated wastewater is discharged to an underground cistern system (including 11 underground pools) from where it is discharged to the ground surface west of the wastewaster treatment plant. No spills or stains were observed near the wastewater treatment plant.

Grease Trap

The sinks located within the food preparation and cooking areas of the cafeteria discharge through an aboveground grease trap located in the basement before being discharged to the sanitary sewer system. Grease from the trap is pumped out and removed from the site by an outside contractor as needed basis. The site representative was unaware of how long the grease trap has been in use at the site. Given the environmentally benign nature of materials discharged to the grease trap, and because the grease trap is routinely cleaned, the grease trap does not represent a potential for impact.

Sinks, Drains, Sumps

RPS GaiaTech observed floor drains in the warehouse and production areas of the building. According to the site representative, the floor drains are connected to subsurface piping are discharge to the on-site wastewater treatment plant (discussed above). No spills or stains were observed near the drains. No materials or liquid chemicals are stored near the drains.

Fire Suppression Water Pond

A large pond is present west of the building and used to store water for firefighting purposes. No drains are discharged to the pond from the production area. No spills or stains were observed near the pond and no materials or liquid chemicals are stored near the pond.

4.0 USER PROVIDED INFORMATION

The purpose for performing this Phase I ESA was assumed to be (at least in part) to satisfy one of the requirements for the User to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability.

A questionnaire consistent with Appendix X3 of the ASTM-13 Standard was provided to Tribune Media Company to be completed as User of the report. At the time of issuance of this report, RPS GaiaTech had not received the completed questionnaire.

5.0 ENVIRONMENTAL DATABASE REVIEW

EDR was retained to provide an environmental database search report of ASTM-required federal, state and tribal environmental databases to identify whether the site, adjoining or nearby properties represent a known or potential impact. This review also included an evaluation of vapor migration using available historical, subsurface, and regulatory information, as well as published regulatory guidance, industry standards (including critical screening distances) and our professional experience.

Detailed descriptions of the environmental databases that were searched and definitions of acronyms are included within the Executive Summary Section and the Government Records Section of the environmental database search report (Appendix D).

5.1 Site Listings

A summary of the database listings identified for the site address is provided below:

Site Occupant	*Database Listing*	*Discussion*
Newsday	RCRA-LQG	Newsday was registered as a Large Quantity Generator (LQG) in 1980. Hazardous wastes generated at the site include corrosive waste, silver waste, spent halogenated solvents, spent nonhalogenated solvents, 2-propanone, acetic acid, formaldehyde, benzene, 1,1,2-trichloroethane, ethane. The site was subsequently registered as a NonGen in 1981, and registered again as a LQG from 1980 to 2014. Chlorinated solvents were generated at the site in 1980, 1981, 2004, 2006, 2008 and 2014. Newsday received several Notices of Violations (NOVs) related to regulations, records/ reporting, manifests, contingency plan/ emergency procedures, general facility standards, small quantity handlers, container use and management and pre-transporting of hazardous waste from 1986 to 2015, all of which have achieved compliance. The long history of chlorinated solvent waste generation represents a potential for impact to the site
Newsday	SEMS-ARCHIVE,	A CERCLIS Preliminary Assessment was conducted at the site in 1989. The site was not placed on the National Priority List (NPL) and in 1998 the site was issued No Further Remedial Action Planned (NFRAP) status. No other information was available regarding the reason for the Preliminary Assessment or the basis for issuing the NFRAP status. However, based on the regulatory status, it appears that this listing is not related to known subsurface impacts.
Newsday	NY AST, NY UST, NY LTANKS, NY Spills,	A spills incident was reported at the site in 1997 for the release of 20 gallons of hydraulic oil. Corrective action was taken and the incident was closed in 1997. A spills incident was reported at the site in 2000 for the release of 1,600-gallons of diesel. A third party contractor was notified to clean

		up the release and the incident was closed with the NYDEC in 2000; however associated spill documents were not available. A spills incident was reported for the site in 2001 for the release of 20 gallons of hydraulic oil. Corrective action was taken and the incident was closed in 2002. A spills incident was reported for the site in 2001 for the release of 20 gallons of hydraulic oil due to a failure of the hydraulic hose on a dumpster truck. Corrective action was taken and the incident was closed in 2004. A spills incident was reported for the site in 2005 for the release of 100 gallons of ink from the ink reclamation machine. The released ink was filtered and recycled. The area of the release was bermed and the incident was closed in 2006. A spills incident was reported in 2010 during the removal of three 20,000-gallon diesel USTs. Contamination was identified under the dispenser pumps and 166.83 tons of petroleum-impacted soil were excavated and disposed off-site. According to the database listing, laboratory analysis indicated all compounds were identified within acceptable concentrations (i.e. below applicable cleanup standards). The spill incident was closed in 2011. This release incident is discussed further in Section 6.1. A spills incident was reported in 2011 for the release of 6 gallons of diesel fuel from a fleet vehicle (not owned by Newsday) as it was exiting the site. No drains were reportedly affected and a third party contractor cleanup up the release. The incident was closed in 2011. A spills incident of 2,000-gallons of ink was reported for the site in 2012 due to a broken ink feeding tube on a printing machine. All of the material was reportedly contained within the printing shop and no floor drains were affected. The incident was closed in 2012. A spills incident was reported for the site in 2012 for the release of 500 gallons of combined industrial/sanitary wastewater sewage at the site. The spill was cleaned up on-site and closed in 2012; however, according to the NYDEC spill database, soil was affected. No other information or documents on the release were provided. A spills incident was reported for the site in 2014 for a release of 5 gallons of diesel fuel from a generator day tank. The spill was not reported to have migrated outside and was subsequently closed in 2014. A spills incident was reported for the site in 2015 for a release of 60 gallons of antifreeze due to a burst on a generator inside of the site,

		but the spill was reported to have migrated to a drain outside. The drywell was confirmed to have no outlets and a sand bottom. The DEC also confirmed the sand soaked up the entire product, and the incident was subsequently closed in 2015. A spills incident was reported for the site in 2016 for a release of 4 gallons of compressor oil due to equipment failure. Drains in the production areas are connected to an oil/water separator and discharge to the on-site wastewater treatment plant. The spill was not listed as closed on the EDR or the NYDEC spills database. While the quantity of oil released was limited, given the active status of the spill, the potential for impact exists. While 11 of the 12 releases at the site achieved regulatory closure, documentation for several of the releases were not provided through the resources reviewed; therefor the potential for impact to the site from the spills listings exists. Details regarding the ASTs and USTs installed at the site are discussed in Section 3.1 and 3.2.
Newsday	ICIS, US AIRS, FINDS, ECHO, NY MANIFEST, NJ MANIFEST, NY SPDES	The ICIS, US AIRS, FINDS, ECHO, NY MANIFEST, NJ MANIFEST and NY SPDES listings are related to environmental compliance and not indicative of impact.
Nalco Chemical (appears to be a subcontractor related to operation of boilers)	RCRA NonGen/NLR, FINDS, ECHO, NY MANIFEST	Nalco Chemical was registered as a Small Quantity Generator (SQG) of corrosive waste in 1996 with no violations found. Nalco Chemical was registered as a NonGen in 2007. Based on the lack of spills or released associated with the hazardous waste generation, the potential for impact is low. The FINDS, ECHO and NY MANIFEST listings are related to environmental compliance and not indicative of impact.

5.2 Adjacent and Surrounding Properties

Relevant listings for adjacent and surrounding properties are presented in the following table. Although other properties may be listed in the environmental database search report, based on location and/or regulatory status, these other properties do not have a potential for environmental significance to the site. Details regarding these properties are presented in the database search report. Unless noted below, the EP determined that a file review was not necessary for the facilities discussed in the following section.

Facility	***Relative Location/Gradient***	***Database Listing(s)***	***Discussion***
Imperial	southeast adjacent;	NY Spills, RCRA	Clare Rose was registered with one 1,000-

Facility	Relative Location/Gradient	Database Listing(s)	Discussion
News/ Clare Rose 255 Pinelawn Road	presumed downgradient	NonGen/NLR, NY UST, NY AST, FINDS, ECHO, NY MANIFEST	gallon #2 fuel oil UST installed in 1972 and removed in 1994, one 1,000-gallon #2 fuel oil UST installed in 1979 and removed in 1994, one 3,000-gallon #2 fuel oil UST installed in 1978 and removed in 1994, one 500-gallon waste oil UST installed in 1978 and removed in 1991, one 12,000-gallon diesel UST installed in 1979 and removed in 1991, one 2,000-gallon gasoline UST installed in 1979 and removed in 1991, one 12,000-gallon diesel UST installed in 1978 and removed in 1991, one 8,000-gallon gasoline UST installed in 1979 and removed in 1991 and two 550-gallon oil/water separators installed on an unknown date and removed in 1993. Clare Rose was registered with one 1,000-gallon diesel AST that is listed as never being installed. Additionally, this facility is listed with one 275-gallon #2 fuel oil AST, one 275-gallon motor oil AST, one 275-gallon waste oil AST and one 651-gallon diesel fuel AST that were installed in 1982. A spill incident was reported in August 1986 for an unknown amount of diesel fuel. The spill achieved closure in October 1986. A spill incident was reported in October 1993 for an unknown amount of waste oil; long term leaking from three or four holes in the bottom of a tank during which time the building was abandoned. Soil was excavated and the spill achieved closure in June 2004. A spill incident was reported in May 1994 for an unknown amount of fuel oil during tank removal. There were no holes in the tank and the spillage came from the top of the tanked. Cleanup actions were performed and the spill achieved closure in November 1994. A spill incident was reported in June 2008. During excavation a previously abandoned 1,000-gallon tank was encountered. The tank contained water and had a gasoline odor, and some of the water inside the tank spilled into

Facility	Relative Location/Gradient	Database Listing(s)	Discussion
			the excavation. The tank was removed in June 2008 and the spill achieved closure in April 2009. A spill incident was reported in August 2009 involving the release of ten gallons of diesel due to a vandalized broken meter on the diesel fuel pump. The report states that the spill was to asphalt and a small amount may have entered a catch basin on the property. The spill to the asphalt was cleaned up. The spill achieved closure in March 2010. A spill incident was reported in July 2013. A pad-mounted transformer released 3-gallons of transformer oil onto cement bottom and surrounding soil. Cleanup action was performed and the spill achieved closure in December 2013. Hazardous waste in the form of ignitable waste was generated at the facility for the years 1991 and 2006. No violations were found. The FINDS, ECHO, and NY MANIFEST listings indicates the facility is identified on other environmental databases. This is not indicative of impact to the site. Given the lack of spills or releases related to the ASTs and USTs, closure status of the spills listings and gradient, the potential for impact is reduced.
Tribune/ Newsday/ J.M Albrizzio 25 Deshon Drive	west adjacent; presumed downgradient	NY UST, NY AST, NY Spills	Hazardous waste in the form of ignitable waste and spent non-halogenated solvents were generated and reported at the facility in 1986, 1999, and 2006. The facility registered with non-generator status in 2007. One 15,000-gallon #2 fuel oil UST was removed in 1989. One 6,000-gallon #2 fuel oil UST was installed in 1991, and removed in 2013. Two 2,000-gallon #2 fuel oil USTs with an unknown installation date are currently in-use at the facility. The Newsday facility was registered with one

Facility	Relative Location/Gradient	Database Listing(s)	Discussion
			550-gallon industrial waste AST installed in 1983 and removed in 1992. One 100-gallon #2 fuel oil AST was installed in 1991 and is still in use. Four 80-gallon boiler chemical ASTs, two 80-gallon cooling tower chemical ASTs, and one 140-gallon boiler additive AST with unknown installation dates are still present at the facility. The Tribune facility was registered with two 60-gallon motor oil ASTs that were removed in 2013 and a 100-gallon #2 fuel oil AST that was removed in 2013. A spill incident was reported in November 1993. A driver transporting diesel hit a curb and approximately 15-gallons of diesel spilled on the road and parking lot. Corrective action was taken and the spill incident was closed in December 1993. A spill incident was reported in August 2005. Approximately 50-gallons of #2 fuel oil spilled in the boiler room. Corrective action was taken and the spill incident was closed in September 2005.
Eastern Athletic Club 100 Ruland Road	North adjacent; presumed upgradient	NY Spills, NY UST	The facility has two 1,000-gallon #2 fuel oil USTs that were installed in 1984, and are currently in-use. A spill incident was reported on December 26, 2009. Approximately 15-gallons of #2 fuel oil leaked from a fill pipe. Corrective action was taken and the site reached closure on December 28, 2009.
Heidelberg Publishing/ Linotype-Hell Co 80 Ruland Road	West-adjacent; presumed cross-gradient	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY AST	Hazardous waste in the form of corrosive waste and silver was generated and reported at the facility for the years 1998, 2001, and 2006. The facility was listed as a non-generator in 2007. The facility is registered with one 1,000-gallon drum storage AST and one 100-gallon photo wastewater AST, which are currently in-use.

Facility	Relative Location/Gradient	Database Listing(s)	Discussion
Pergament/ MRP Family Holdings 101 Marcus Drive	South-adjacent	NY Spills, NY MANIFEST, NY UST	The facility is registered with a 15,000-gallon #2 fuel oil UST that was removed in 2003. A spill incident was reported at the facility in March 2001. Approximately 300 gallons of #2 fuel oil leaked from the boiler room into the parking lot. Corrective action was taken and the spill incident was closed in December 2001.

6.0 SITE HISTORY

Reasonably ascertainable standard historical sources as outlined in ASTM Standard E1527-13 were used to determine previous occupants and uses of the site that are likely to have resulted in RECs in connection with the site. Historical data reviewed included, but was not limited to, aerial photographs, historical city directories, Sanborn fire insurance maps, building department records, and other agency files and documents. Historical resources are referenced in Section 10.0.

6.1 Site History Summary

By the early 1900s, the site consisted of agricultural land with a road traversing the central portion from east to west. Also at this time, associated farmstead residences were present on the southeast corner of the site. The site remained unchanged until the early 1950s, when an additional residence was constructed on the northeast corner of the site. In the mid-1970s the farmsteads on the southeast and northeast corners of the site were razed and in 1977, the site was redeveloped with the original portion of the current production building, the fire suppression water pond, the chemical storage shed, and the wastewater treatment plant. By the early 1990s, the production building was expanded to the south and west and the fuel pump island was constructed on the southern portion of the site. By the mid-2000s, a baseball field was constructed on the northwest corner of the site, bringing the site into its current configuration. According to the site representative, the site converted from chemical to digital photo development and has downsized in printing operations over the last 10 years. Historical site operations including current and historical use of USTs and ASTs are discussed further below.

Based on available historical records, RPS GaiaTech was able to identify a total of 15 underground tanks that are currently or were formerly operated at the site. Eight of these tanks were installed for Newsday in 1978, which include three 25,000-gallon diesel USTs, one 12,000-gallon gasoline UST and one 2,000-gallon underground spill containment tank (all removed in 1986); a 25,000-gallon No. 6 fuel oil UST and a 25,000-gallon No. 2 fuel oil UST (abandoned in place in 2010); and a 4,000-gallon industrial waste UST removed in 1987. One 2,500-gallon fuel oil UST was installed in 1987 currently still in use at the site. Three 20,000-gallon diesel USTs were installed in 1985 and replaced in 2010 with three new 20,000-gallon diesel USTs, which remain active..

Newsday has operated as a newspaper printing facility since the late 1970s. Printing operations have included the use of inks, washes, oils, and chlorinated solvents, the generation of hazardous wastes such as silver and spent chlorinated and non-chlorinated solvents, use of several current and historical USTs, and wastewater treatment operations; treated wastewater has been discharged to the exterior ground surface. Additionally, records of several release incidents were identified in historical records with regulatory closure. Many of these releases involved limited quantities of material, but also included incidents in 2000 related to a release of 1,600 gallons of diesel and in 2012 related to release of 500 gallons of combined industrial/wastewater sewage. Although regulatory closure was achieved for these releases,

confirmatory sampling information was not provided to demonstrate no impacts remain from these incidents. Subsurface investigations were conducted around three former diesel fuel USTs and two fuel oil USTs (discussed further below); however, it appears that no subsurface investigations have been conducted to specifically address the other six former USTs. The long duration of printing operations involving the on-site discharge of treated wastewater, historical use of chlorinated solvents, operation of USTs, and history of repeated release incidents represents a potential for impact to the site.

A release of 4 gallons of compressor oil was reported at the site in 2016 due to equipment failure. Drains in the production areas are connected to an oil/water separator before discharging to the on-site wastewater treatment plant. The spill was not listed as closed on the NYDEC spills database. Because the spill involved a very limited quantity of oil and the release was captured by the wastewater treatment plant the potential for environmental impact from this release is low. However, it appears that the incident has not received regulatory closure; therefore, additional regulatory action may be required.

Three 20,000-gallon diesel USTs were installed in 1985 and removed in 2010 from the southern portion of the site. A Leaking UST (LUST) incident was reported upon removal of these USTs. A subsurface investigation was subsequently conducted, which included sampling the soil and groundwater around the former USTs and laboratory analysis of the samples for volatile organic compounds (VOCs) and Semi-VOCs (SVOCs). Results of the 2010 sampling results indicate that contaminant concentrations were below applicable cleanup standards; however, because the full closure report was not provided for RPS GaiaTech's review, the exact location of the samples could not be determined. The results of the 2010 subsurface investigation were used to obtain regulatory closure of this LUST incident through the New York Department of Environmental Conservation (NYDEC). Additional subsurface soil sampling was conducted in 2014 after the abandonment of two 25,000-gallon fuel oil USTs. The investigation was conducted beneath one of the two USTs and identified two individual polycyclic aromatic hydrocarbons (PAHs) in the soil above applicable cleanup standards, but because total PAH was below 500 milligrams/kilograms (mg/kg) in each sample, the samples are considered to meet the cleanup standards even with individual exceedances; groundwater was not sampled during this investigation. Based on the sampling results, the USTs were given clean closure with no reported release. Available sampling data indicates that remaining contaminant concentrations around these former USTs are below applicable risk-based screening levels and regulatory closure has been granted for the associated reported release incident; however, sampling was only conducted beneath one of the abandoned fuel oil USTs and full UST closure documents were not provided to RPS GaiaTech to confirm sampling locations; therefore, RPS GaiaTech cannot confirm that adequate confirmation sampling was conducted to identify potential impacts.

6.2 Historical Maps and Photographs

RPS GaiaTech reviewed available historical aerial photographs, and topographic maps from the sources listed in Section 10.0. According to EDR, no Sanborn fire insurance maps were available for the site area. The information from these sources is summarized below. Copies of key maps and photographs are provided in Appendix C.

Source	Site Use Description
1903 Topo 1912 Topo 1924 Topo 1938 Aerial 1938 Topo 1947 Aerial	The site consisted of agricultural land with a road running through the central portion, from east to west. An associated farmstead residence is present on the southeast corner of the site.
1953 Aerial 1956 Topo 1962 Aerial 1966 Aerial 1969 Topo 1970 Aerial 1976 Aerial	Additional farmstead residences have been constructed on the northeast corner of the site.
1980 Aerial 1985 Aerial 1989 Topo	The farmsteads on the southeast and northeast corners of the site are no longer present. The original portion of the production building is present with associated parking areas to the south and southwest. The fire suppression water pond, chemical storage shed, wastewater treatment plant (with associated building) have been constructed west of the production building. The northern portion of the site appears undeveloped.
1994 Aerial 2001 Aerial 2004 Aerial	The production building was expanded to the south and west. Paved parking areas were added to the northern half of the site. The fuel pump island has been constructed on the southern portion of the site.
2006 Aerial 2007 Aerial 2008 Aerial 2009 Aerial 2011 Aerial 2013 Topo 2013 - 2017 Aerials	A baseball field is present on the northwest corner of the site and an additional building west of the wastewater treatment plant has been constructed, bringing the site into its current configuration.

6.3 Agency Record Review

RPS GaiaTech contacted or filed Freedom of Information Act (FOIA) requests with various agencies to obtain environmentally relevant information regarding the site. As of the date of this report, the following agencies had not responded to the FOIA requests:

- Town of Huntington Fire Prevention Bureau
- Suffolk County Department of Health Services
- New York Department of Environmental Conservation (NYDEC)

Pertinent information obtained from the agency resources is summarized as follows:

Town of Huntington Assessor: The production building was originally constructed in 1977.

Town of Huntington Building and Housing Department: According to a property record file for the site, construction permits and plans were identified for the following actions:

-1978: alterations to existing building and new construction of a lobby
-2005: installation of an antenna/dish
-2016: installation of one 100-gallon liquid petroleum tank
-2017: installation of one 100-gallon liquid petroleum tank

Additionally, various building addition, electrical, utilities and plumbing permits were issued between 1976 and 2017.

6.4 Prior Environmental Reports

Tribune Media Company provided historical documentation in connection with the site. A copy of the text and pertinent appendices of the reports are provided in Appendix C. A summary of this information follows:

Phase I Environmental Site Assessment, Newsday Main, 235 Pinelawn Road, Melville, New York, prepared by Geomatrix Consultants, Inc. (Geomatrix) for Tribune Company, dated March 2008 (the 2008 Phase I).

The 2008 Phase I was conducted for the purposes of a property transaction that included the site. At the time of the 2008 Phase I, the site was occupied by Newsday and operations were generally consistent with present day operations. The 2008 Phase I identified two 25,000-gallon #2 fuel oil USTs near the southeastern entrance of the building. The USTs were not present during RPS GaiaTech's inspection, and no evidence of a release from the former USTs was observed.

The 2008 Phase I indicated that minor staining was identified around the base of some of the ink ASTs; however, the associated spilled material appeared to be contained and the epoxy coating on the floor was in good condition. RPS GaiaTech also observed ink staining around the base of the ASTs at the time of the site inspection. The floor and base of the ASTs also appeared in good condition at the time of RPS GaiaTech's inspection. The 2008 Phase I did not identify any RECs; however, at the time of the 2008 report and at the time of RPS GaiaTech's inspection, UST removal and abandon reports pertaining to the leaking USTs/ spills listings for the site were not available. The 2008 Phase I also indicated the site is located in an area with several hazardous waste generators and/or petroleum storage facilities; however, the 2008 report did not expect these facilities to present a potential for impact to the site.

Tank Island Upgrade Construction Review, Newsday Main, 235 Pinelawn Road, Melville, New York, prepared by ERM for Tribune Company, dated July 2010 (the limited 2010 UST removal report).

According to the limited UST removal report, in 2010, three 20,000-gallon diesel USTs were removed from the site and replaced with three new 20,000-gallon USTs. A Tank

Commissioner's report provided to RPS stated that no holes were noted on the USTs and no soil staining was observed during UST removal. A diesel spill incident provided by the NYDEC (through the NYDEC spills database) in 2010 reported several rounds of soil and groundwater samples were obtained after the removal of the three USTs. While a full UST removal report was not provided, soil and groundwater samples for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were available. Sampling results indicated that contaminant concentrations in soil and groundwater were identified below New York Department of Environmental Conservation soil cleanup levels and the spill release incident, provided by the NYDEC spills database, was subsequently closed in March 2011. While the sampling results were below soil cleanup levels, based on the lack of UST removal documentation, it is not known where the soil and groundwater samples were obtained.

Spill Closure Report, Newsday Main, 235 Pinelawn Road, Melville, New York, prepared by ERM for Tribune Company, dated April 2014 (the 2014 spill closure report).

In the 2014 spill closure report, two 25,000-gallon #2 fuel oil USTs (Tanks 6 and 7) were proposed for abandonment south of the building at the site. Tank 6 passed the tightness test; however, Tank 7 failed and was immediately pumped out. Tank 6 remained in service for emergency generator fuel storage until early 2014 when it was replaced by an AST, emptied and abandoned. Four soil samples were obtained beneath fuel oil Tank 7 and analyzed for VOCs and SVOCs prior to tank abandonment. No samples were obtained from beneath tank 6 prior to its abandonment and no groundwater sampling was obtained. Soil sampling results for Tank 7 met cleanup levels except for benzo(a)anthracene and chrysene, which were above cleanup levels in two samples; however, in accordance with New York regulations, since the concentration of total PAH was below 500 milligrams/kilograms (mg/kg) in each sample, then the sample is considered to meet the cleanup level even with individual constituents exceeding their associated cleanup levels. Based on these sampling results, the State allowed the tanks to be abandoned in place without requiring remedial actions.

6.5 Interviews

6.5.1 Site Representative and Occupants

Mr. Stephen Zimmerman indicated that he had no information pertaining to any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the site; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the site; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

Mr. Joe Mariano indicated that two major additions have been constructed to the building to include a larger printing floor to add printing presses and an expansion to the newspaper bundling and palletizing area and shipping docks on the south side of the building. Mr. Mariano

also indicated that 10 years ago the site converted from chemical to digital photo development. Mr. Mariano noted that since Newsday stopped using fixer and developer chemicals for photo development, the site has not since generated any silver waste. Mr. Mariano also indicated Newsday historically operated 10 printing presses in the press room, but within the last 5 years, 4 of the printing presses were abandoned in place and the 4 remaining presses were combined to make the 3 large printing presses currently operating at the site.

6.5.2 Site Owner

Mr. Stephen Zimmerman is also a representative of the site owner, Tribune Media Company.

6.5.3 Past Owners, Operators and Occupants

Interviews with past owners and occupants regarding historical on-site operations were not reasonably ascertainable.

6.6 City Directories and Other Historical Sources

RPS GaiaTech reviewed available historical city directories obtained from the Environmental Database Report for the years 1973 to 2013 at approximately five-year intervals. Information from these sources is summarized below.

Year	*Description*
1973 to 1978	No Listings
1981 to 1988	Newsday Inc.
1992	New York Newsday Advertising, New York Newsday Circulation, Newsday in Education, Newsday Inc.
1995	Newsday
1999	Distinction Magazine, Newsday Incorporated, This Week Publications
2003	Distinction Magazine, DSA Community Publishing LLC, Long Island Parents & Children, Newsday, Newsday Community Service Fund, Newsday Riverhead Bureau, This Week Publications
2008	Corporate Travel Consultants, Distinction Inc., Newsday Community Service Fund, Newsday Inc. Advertising, Newsday Inc. Circulation, Newsday Medical Group, Newsday Long Island Parents & Childe, Riverhead Chamber
2013	Newsday

7.0 SURROUNDING PROPERTIES

7.1 Surrounding Property Summary

The site is located in an area currently characterized by residential development, commercial warehouses, and light industrial developments. In the early 1900s, the site area was agricultural land with associated farmsteads. Rural residential development expanded between the early 1950s and the early 1960s. By the mid-1960s, Ruland Road was constructed to the north and Pinelawn Road was constructed to the east of the site. Also at this time, light industrial and commercial development began to the north and farther south of the site. Light industrial development along Ruland Road and Deshon Drive continued through the 1990s including facilities on the northeast, south, southwest and west-adjacent properties. By the mid-2000s, residential development expanded farther west. The west-adjacent light industrial building was razed by 2013, and the current west-adjacent apartment complex and light industrial building were constructed by 2016, bringing the surrounding properties into their current configuration.

The surrounding area has been occupied by various light industrial facilities since at least the mid-1960s. Four adjacent facilities were identified with ASTs, USTs, hazardous waste generation, and releases. Records of 17 USTs and 10 reported releases were identified on these four facilities. The long history of industrial operations in the surrounding area with USTs and reported releases represents a potential for impact; however, because each of the reported releases were issued regulatory closure, the potential for impact to the site appears to be low.

7.2 Current Use of Adjoining and Nearby Properties

The site reconnaissance included a visual survey of the properties adjoining and in the vicinity of the site as observed from the site boundaries and public rights-of-way. The site is located in an area characterized by commercial warehouse developments and residential developments. The current uses of adjoining properties were observed:

North: Eastern Athletic Clubs (sports complex) and Ruland Road, followed by single family residences and commercial warehouses.

East: Pinelawn Road, followed by Pinelawn Memorial Park and Cemetery. Farther east is agricultural land.

South: An unnamed road, Clare Rose Inc. (beer distributor), Regent Baby Products Corporation (baby products manufacturer and distributor), and a distribution warehouse (formerly occupied by a Newsday inserting facility), followed by additional light industrial developments.

West: Deshon Drive, followed by a multi-tenant light industrial building, a temple, apartments and single-family residences.

7.3 Historical Maps and Photographs

Reasonably ascertainable historical sources were used to determine previous occupants and uses of adjacent and surrounding properties that are likely to have resulted in RECs in connection with the site. The summary below was developed based on information obtained from available resources that may have included aerial photographs, and historical topographic maps. According to EDR, no Sanborn fire insurance maps were available for the site area. Historical resources are referenced in Section 10.0.

Source	*Description*
1903 Topo 1912 Topo 1924 Topo 1938 Aerial 1947 Aerial	Surrounding properties consist of agricultural land with associated farmsteads.
1953 Aerial 1956 Topo 1957 Aerial 1962 Aerial	Single-family residences and farm silo/farm equipment are scattered throughout the properties to the north.
1966 Aerial	Ruland Road has been constructed to the north and Pinelawn Road has been constructed east of the site. Light industrial and commercial warehouse developments are present farther south of the site. A cemetery is present to the southeast and a retail structure is present farther north.
1969 Topo 1970 Aerial	The south-adjacent property is developed with a light industrial warehouse; light industrial developments are also present on properties farther to the south.
1976 Aerial	Deshon Drive has been constructed to the west, an unnamed road has been constructed to the south, and Marcus Drive has been constructed farther south of the site. Three industrial/warehousing buildings are present on the south-adjacent property (the former Newsday inserting facility), the northeast-adjacent property, and the southwest-adjacent property.
1980 Aerial	Light industrial buildings fill in to the south and southwest properties. Light industrial and commercial buildings are present farther north.
1985 Aerial 1989 Topo 2001 Aerial 1994 Aerial	A light industrial building/warehouse is present on the west-adjacent property
2006 Aerial 2007 Aerial 2008 Aerial 2009 Aerial 2011 Aerial	Multi-family residential development is present farther west.

Source	Description
2013 Aerial 2013 Topo 2014 Aerial 2015 Aerial	The west-adjacent facility has been razed.
2016 Aerial 2017 Aerial	West-adjacent apartment buildings and the current west-adjacent commercial buildings have been constructed, bringing the surrounding properties into their current configuration.

7.4 City Directories

RPS GaiaTech reviewed available historical city directories as presented in Section 6.6. The following summarizes the surrounding properties identified in the records reviewed:

Facility	Period	Occupant
255 Pinelawn Road ***Southeast adjacent; presumed cross-gradient***	1973	Britannc & ERPN Auto; NAPA Imports; Unex Prods Carr
	1978	Imperial News Co.; NAPA Imports
	1983	Cable News; Imperial News Co.; NAPA Imports; Select Magazine
	1988	Cable News; Imperial News Co.; NAPA Imports; Select Magazine; Warner Publisher
	1992	No Listings
	1995 - 2013	Clare Rose of Naussau Inc.; Dee Gee Express
25 Deshon Drive ***West-adjacent presumed cross-gradient***	1976	Belmil Computer
	1981 - 1986	Apt. Advertising; Belmil Computer; Belwin Mills Pub; CSG Creative SVC; Music Boutique
	1986	Dal Moline MSC Typ
	2007	Newsday Inc.

The Clare Rose was identified on the environmental database and is discussed further in Section 5.2.

7.5 Interviews and Other Historical Sources

No additional pertinent information concerning adjacent or surrounding properties was identified during the review of historical resources.

8.0 NON-ASTM SCOPE OF WORK

In addition to the Phase I ESA, Tribune Media Company requested RPS GaiaTech to conduct an assessment of certain additional non-ASTM scope items which may affect the environmental risk at the site. These non-ASTM scope items are discussed in the following sections.

8.1 Asbestos-Containing Materials (ACMs)

Previous Asbestos Surveys

Mr. Stephen Zimmerman was not aware of asbestos surveys for the site and none were identified in available site records.

Current Site Conditions

RPS GaiaTech identified suspect and presumed ACMs in the form of drywall systems, drop ceiling tiles, and vinyl floor tile and associated mastics throughout the interior of the building. Thermal system insulation (TSI) pipe wrapping was also identified on piping observed around the boilers. Suspect and presumed ACMs were observed to be in good condition.

Based on the date of construction (1977), before asbestos stopped being commonly used in the construction industry, there is potential for the materials identified to contain asbestos. It should be noted that additional suspect or presumed ACMs may be present in inaccessible areas of the site structure, such as above fixed ceilings, behind walls or in roofing systems, and were therefore not observed during the site reconnaissance.

Since the building was constructed prior to 1981 and due to the presence of vinyl floor tile, surfacing material and TSI, the OSHA regulations regarding management of vinyl floor tile and presumed ACMs (PACMs) in building materials apply to the site. It does not appear that there are programs in place at the site to address these requirements.

8.2 Mold

RPS GaiaTech performed a limited visual inspection for the presence of mold, water-damaged materials, and other evidence of water infiltrations at the site. The limited survey was conducted by observing interior areas of the building to identify the presence of mold and focused on areas of restricted air circulation such as storage spaces and utility closets, areas under sinks and around bathroom fixtures, areas at elevated risk of water intrusion such as exterior walls and windowsills, and common areas.

RPS GaiaTech did not note obvious visual or olfactory indications of the presence of mold, nor did RPS GaiaTech observe obvious indications of significant water infiltration or damage in accessible areas. In addition, site representatives were not aware of water infiltration or mold issues at the site.

8.3 Wetlands

Based on a review of the EDR Radius Map Report and the US Fish and Wildlife Service National Wetlands Inventory Map, provided by the City of Melville, it does not appear that mapped wetlands are present at the site. Other than the man-made pond on the western portion of the site, no obvious physical evidence of wetlands indicators was identified during RPS GaiaTech's site reconnaissance. The site observations and review of wetlands documentation provides an indication of the potential for wetlands at the site and does not constitute a wetlands determination or delineation.

9.0 FINDINGS

RPS GaiaTech has performed this Phase I ESA in conformance with the scope and limitations of ASTM-13 for the Newsday facility located at 235 Pinelawn Road in Melville, Suffolk County, New York. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report.

This assessment identified the following RECs in connection with the site:

- **Historical Site Operations:** Newsday has operated as a newspaper printing facility since the late 1970s. Printing operations have included the use of inks, washes, oils, and chlorinated solvents, the generation of hazardous wastes such as silver and spent chlorinated and non-chlorinated solvents, use of several current and historical USTs, and wastewater treatment operations; treated wastewater has been discharged to the exterior ground surface. Additionally, records of several release incidents were identified in historical records with regulatory closure. Many of these releases involved limited quantities of material, but also included incidents in 2000 related to a release of 1,600 gallons of diesel and in 2012 related to release of 500 gallons of combined industrial/wastewater sewage. Although regulatory closure was achieved for these releases, confirmatory sampling information was not provided to demonstrate no impacts remain from these incidents. Subsurface investigations were conducted around three former diesel fuel USTs and two fuel oil USTs (discussed further below); however, it appears that no subsurface investigations have been conducted to specifically address the other six former USTs. The long duration of printing operations involving the on-site discharge of treated wastewater, historical use of chlorinated solvents, operation of USTs, and history of repeated release incidents represents a potential for impact to the site.

- **Open Release Incident:** A release of 4 gallons of compressor oil was reported at the site in 2016 due to equipment failure. Drains in the production areas are connected to an oil/water separator before discharging to the on-site wastewater treatment plant. The spill was not listed as closed on the NYDEC spills database. Because the spill involved a very limited quantity of oil and the release was captured by the wastewater treatment plant the potential for environmental impact from this release is low. However, it appears that the incident has not received regulatory closure; therefore, additional regulatory action may be required.

This assessment identified the following CREC in connection with the site:

- **Recently Closed USTs:** Three 20,000-gallon diesel USTs were installed in 1985 and removed in 2010 from the southern portion of the site. A LUST incident was reported upon removal of these USTs. A subsurface investigation was subsequently conducted, which included sampling the soil and groundwater around the former USTs and laboratory analysis of the samples for VOCs and SVOCs. Results of the 2010 sampling results indicate that contaminant concentrations were below applicable cleanup standards; however, because the full closure report was not provided for RPS

GaiaTech's review, the exact location of the samples could not be determined. The results of the 2010 subsurface investigation were used to obtain regulatory closure of this LUST incident through the NYDEC. Additional subsurface soil sampling was conducted in 2014 after the abandonment of two 25,000-gallon fuel oil USTs. The investigation was conducted beneath one of the two USTs and identified two individual PAHs in the soil above applicable cleanup standards, but because total PAH was below 500 mg/kg in each sample, the samples are considered to meet the cleanup standards even with individual exceedances; groundwater was not sampled during this investigation. Based on the sampling results, the USTs were given clean closure with no reported release. Available sampling data indicates that remaining contaminant concentrations around these former USTs are below applicable risk-based screening levels and regulatory closure has been granted for the reported release incidents, full UST closure documents to confirm the location sampling; therefore, RPS GaiaTech cannot confirm that confirmation sampling was conducted adequately to identify potential impacts.

This assessment identified the following noteworthy condition in connection with the site:

- **Surrounding Properties:** The surrounding area has been occupied by various light industrial facilities since at least the mid-1960s. Four adjacent facilities were identified with ASTs, USTs, hazardous waste generation, and releases. Records of 17 USTs and 10 reported releases were identified on these four facilities. The long history of industrial operations in the surrounding area with USTs and reported releases represents a potential for impact; however, because each of the reported releases were issued regulatory closure, the potential for impact to the site appears to be low.

This assessment identified the following other consideration in connection with the site:

- **Asbestos Containing Materials (ACMs):** RPS GaiaTech identified suspect and presumed ACMs in the form of drywall systems, drop ceiling tiles, vinyl floor tile and associated mastics and TSI pipe wrapping in the production area of the building. Since the building was constructed prior to 1981 and due to the presence of vinyl floor tile, surfacing material and TSI, the OSHA regulations regarding management of vinyl floor tile and PACMs in building materials apply to the site. It does not appear that there are programs in place at the site to address these requirements.

10.0 REFERENCES

The following sources were used in conducting the Phase I Environmental Site Assessment detailed in this report. Where information obtained from these sources was determined to be useful by the Environmental Professional, it is summarized in the body of this report.

Agency/Company	*Person Contacted*	*Telephone/Web Address*	*Regarding*
Newsday (Site Representatives)	Mr. Stephen Zimmerman and Mr. Joe Marino	631.843.2000	General site information and site history
Town of Huntington Assessor 100 Main Street Huntington, NY	Online information search	631.425.0128 http://www.huntingtonny.gov/	General site information and site ownership information
Suffolk County Recorder of Deeds 300 Center Drive Riverhead, NY	Individual records search	631.852.1551 https://kiosk.suffolkcountyny.gov/KioskWeb/Notifications.aspx	Site ownership information and historical deeds
Town of Huntington Building & Housing Department 100 Main Street Huntington, NY	Building Permits Coordinator	631.351.2821	Historical building permits, certificates of occupancy, utility connection information
Dix Hills Water District 683 Caledonia Road Dix Hills, NY	Online information search	http://huntingtonny.gov/content/	Drinking water source and water quality information
Town of Huntington Fire Prevention Bureau 100 Main Street Huntington, NY	Fire Marshal	631.351.3138	USTs, ASTs, spills, hazardous materials response calls, fires, inspections
Suffolk County Department of Health Services 3500 Sunrise Highway Great River, NY	Counter representative	631.854.0100	Historical septic tank and water well information
NYDEC 625 Broadway Albany, NY	FOIA request	www.dec.ny.gov/	USTs, ASTs, spills, hazardous materials, petroleum products, permits, inspections

Agency/Company	*Person Contacted*	*Telephone/Web Address*	*Regarding*
U.S. Geological Survey	7.5-Minute Topographic Map	NA	Topography
U.S Fish and Wildlife Service Local service center	Records service center	888.123.4567	Wetlands
Environmental Data Resources 6 Armstrong Road Shelton, CT	Account representative	888-732-8811	Environmental database search report, historical aerial photographs, Sanborn map search, chain-of-title/liens search report
Internet Resources	NA		Aerial photographs (NETR Online, Google Earth), NRCS Web Soil Survey

11.0 LIMITATIONS, EXCEPTIONS, AND SIGNIFICANT ASSUMPTIONS

This assessment is subject to the stated limitations of ASTM-13 or the federal AAI standard, as applicable, and other qualifications as described within the report.

This review was based on the time frame, budget and scope of the project. The review was intended to identify issues of relevance to the contemplated transaction that this report was prepared to support.

This assessment was conducted by or under the supervision of an individual(s) meeting the definition of an Environmental Professional under ASTM-13 and the federal AAI standard. Tasks not performed by an Environmental Professional were performed by individuals qualified based on education, training and experience to conduct such tasks for a property of the nature, history and setting of the site.

ASTM defines "data gaps" as an inability to obtain information required for the review despite good faith efforts (such as the lack of historical information back to 1940 or to the first developed use of the property [whichever is earlier]) or as an incompleteness in any of the activities required for the review (such as limited site accessibility or the inability to interview a key site representative). Unless otherwise described in the body of this report, if any one or more of the standard sources under ASTM-13 was not reviewed, this was due to information from the source not being readily available or a determination by the Environmental Professional that the standard source was not likely to be useful. Similarly, unless otherwise noted in this report, any incompleteness in connection with the review was determined not to affect the Environmental Professional's ability to form conclusions regarding the site.

Unless otherwise indicated herein, RPS GaiaTech was not made aware of any specialized knowledge of the landowner or client, any relationship of the purchase price to the fair market value of the site that may be indicative of an environmental concern, or any environmental liens or other activity and use limitations known by the client or user of the report. In the absence of this information, RPS GaiaTech is not able to form conclusions about the environmental condition of the site that may otherwise have been evident had any such information been made available. Unless otherwise indicated herein, the reason for performing this Phase I ESA is assumed to be (at least in part) to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser liability defense under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA).

It should be noted that past agricultural use is considered a developed use under ASTM; any past use of the site for agricultural purposes suggests a potential for residual agricultural chemicals at the site. Unless otherwise stated in this report, no evidence or reports of chemical spills or misuse of agricultural chemicals at the site was identified.

During this Phase I ESA, RPS GaiaTech relied upon the information provided by site representatives, regulatory officials and other informed individuals. RPS GaiaTech has assumed,

where reasonable, that the information reviewed is true and accurate but assumes no responsibility or liability for its accuracy or completeness.

RPS GaiaTech's site observations are of the conditions observed at the time of the assessment. RPS GaiaTech did not observe areas of the site or features of the site where that inspection would have interfered with operations. Additionally, RPS GaiaTech did not enter confined spaces. Pits, trenches or other subsurface features were inspected as thoroughly as possible from access points, vault openings, and through grated drains/lids. RPS GaiaTech did not test the integrity or engineering adequacy of subsurface pits, trenches, sewers, or containment features, aboveground containment systems or tanks. RPS GaiaTech's observations of such equipment/systems are limited to visual evidence of releases or significant deterioration.

RPS GaiaTech reviewed an environmental database search report. RPS GaiaTech's conclusions based on the search report are limited to the accuracy of that report. To the extent practicable, RPS GaiaTech's field observations were used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site, consistent with the federal AAI standard.

RPS GaiaTech evaluates environmental database listings and the potential for additional documentation maintained by regulatory authorities to materially alter the Environmental Professional's opinion with regard to the environmental condition of the site. Except where otherwise described in this report, the pursuit of additional documentation either through regulatory agency file reviews or requests for additional information from the site operator, site owner or the owners/operators of nearby properties, was determined to be unnecessary as it would not alter the findings of the assessment.

Conclusions provided with regard to subsurface soil and groundwater impacts are limited to those that can be formed based on a non-intrusive investigation. RPS GaiaTech has considered all the information collected during this assessment to ascertain the potential presence of a release or threatened release of hazardous substances at the property. Based on the totality of information, RPS GaiaTech has assessed whether or not an obvious conclusion may be drawn that there are conditions indicative of a release or threatened release, and considered whether the parties should be able to detect the release by conducting a subsurface investigation. Where RPS GaiaTech concludes that the potential for impact is present, it should be understood that such impact can only be identified or ruled out through subsurface investigation. The absence of environmental hazards in the subsurface cannot be guaranteed based on conditions observed on the surface. The scope of this project did not include subsurface soil or groundwater sampling.

RPS GaiaTech evaluates the potential for the presence or likely presence of COC vapors in the subsurface of the site using our professional judgment and evaluation of the available information and may use portions of ASTM E2600-10 as a guide. Note that this evaluation is not a full Vapor Encroachment Screen (VES) pursuant to ASTM E2600-10. The vapor evaluation is not exhaustive and cannot wholly eliminate uncertainty regarding the presence or potential presence of COC vapors in the subsurface of the site.

The estimated groundwater gradients (flow directions) referenced throughout this report are based on field observations of the topography of the area, review of topographic map(s), information in the database search report, and other information as available. It should be noted that groundwater flow directions can be highly variable in neighboring areas, and can be influenced by factors such as water production wells or re-grading or development in the area.

ASTM does not include an assessment of wetlands. Unless otherwise noted, a wetlands assessment was not conducted. If conducted, the review of available wetlands information was intended for purposes of evaluating risks associated with potential on-site impacts and does not represent a jurisdictional wetlands delineation. A certified wetlands delineation may be necessary prior to further site development.

ASTM does not include an assessment of mold. Unless otherwise noted in this report, an inspection for mold was not conducted. If conducted, the visual assessment for water infiltration, water-damaged building materials, or the presence of mold or other microbial contamination was limited to easily accessible, visible areas for the purpose of identifying the potential need for additional review/sampling. Unless otherwise noted, sample collection or materials testing for water or microbial presence is also excluded from this assessment.

ASTM does not include an assessment of asbestos-containing materials (ACMs). Unless otherwise noted in this report, an inspection for ACMs was not conducted. The visual inspection for suspect ACMs included materials that have historically been shown to have a potential to contain asbestos. Unless otherwise noted in this report, RPS GaiaTech's review of ACMs is limited to interior building materials. The limited visual survey for suspect ACMs is intended to provide an indication of the potential for significant environmental issues associated with ACMs and should not be regarded as a comprehensive survey for demolition or other purposes. Testing should generally be conducted to identify regulated ACMs prior to remodeling or demolition of the site structures.

ASTM does not include an assessment of lead-based-paint (LBP). Unless otherwise noted in this report, an assessment or testing for LBP was not conducted. If conducted, RPS GaiaTech's review of LBP was limited to easily accessible and visible painted building materials. The limited visual survey for potential LBP is intended to provide an indication of the potential for significant environmental issues associated with LBP and should not be regarded as a comprehensive survey.

ASTM does not include an assessment of lead-in-drinking water (LIDW). Unless otherwise noted in this report, an assessment of LIDW was not conducted. LIDW testing, if performed, is intended as a limited screening for LIDW; additional testing may be required. Identified LIDW is limited to the areas tested and should not be relied on as a comprehensive survey for all water-related piping associated with the building(s).

ASTM does not include an assessment of radon. Unless otherwise noted in this report, an assessment of radon was not conducted. If conducted, the radon evaluation and/or screening,

was intended to provide available data or limited screening results within a defined scope and is not intended as a comprehensive radon survey.

The scope of this report is limited to matters expressly covered. Implementation or use of the recommendations, findings or conclusions of this report does not preclude the potential for present or future environmental liability or ensure the fulfillment of a property owner's obligation to provide full environmental disclosure in accordance with any local, state or federal laws.



United States | Canada | Brazil | UK | Ireland | Netherlands | Australia Asia Pacific | Russia | Middle East | Africa


135 South LaSalle Street, Suite 3500 | Chicago, IL | 60603 | (877) 599-4597

Appendix A

Site Maps and Diagrams

- **Site Location Map**
- **Site Layout and Area Map**





Scale 1:24 000
Contour Interval 20 Feet

1 MILE
7000 FEET
1 KILOMETER


Quadrangle Location

UNITED STATES GEOLOGICAL SURVEY
DEPARTMENT OF THE INTERIOR/USGS
HUNTINGTON QUADRANGLE
NEW YORK – SUFFOLK COUNTY
7.5 MINUTE SERIES (TOPOGRAPHIC)

2016

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00

Site Location Map


NORTH
SINGLE-FAMILY RESIDENCES
SINGLE-FAMILY RESIDENCES
RULAND ROAD
BASEBALL FIELD AND BASKETBALL COURT
EASTERN ATHLETIC CLUBS (SPORTS COMPLEX) 100 RULAND ROAD
MULTI-TENANT LIGHT INDUSTRIAL BUILDING 80 RULAND ROAD
PINELAWN MEMORIAL PARK & CEMETERY
2x EMERGENCY GENERATORS (EACH WITH ONE 1,100-GALLON DIESEL ASTs) AND 2x PAD-MOUNTED TRANSFORMERS
DESHON DRIVE
PINELAWN ROAD
HAZARDOUS WASTE STORAGE BUILDING
DIESEL DAY TANKS
FORMER 25,000-GALLON NO.6 AND NO.2 FUEL OIL USTs
15,000-GALLON #2 FUEL OIL AST
TEMPLE 2 DESHON DRIVE
2,500-GALLON #2 FUEL OIL UST
APARTMENT COMPLEX
WASTEWATER TREATMENT PLANT (LAB BUILDING, SLUDGE TANKS, AERATORS AND MEMBRANES)
3x 20,000-GALLON DIESEL USTs AND FUEL PUMPS
REGENT BABY PRODUCTS CORPORATION (BABY PRODUCT MANUFACTURER AND DISTRIBUTOR) 101 MARCUS DRIVE
LIGHT INDUSTRIAL BUILDING
CLARE ROSE INC. (BEER DISTRIBUTOR) 255 PINELAWN ROAD
LEGEND
SITE BOUNDARY
DESCRIPTION:
NEWSDAY
235 PINELAWN ROAD
MELVILLE, NEW YORK
DRAWN: JB
SCALE: NTS
DATE: 7/17/17
FILE: 166126.613.00
FIGURE:
SITE LAYOUT AND AREA MAP
RPS

Appendix B

Site Photographs





Photo 1: Front-facing view of Newsday.




Photo 2: Reel room (first floor of the press room).



Photo 3: 500-gallon fountain solution ASTs in the press room.



Photo 4: 55-gallon drums of press oil in the press room.



Photo 5: One 8,000-gallon black ink AST.



Photo 6: Digital photographic development room.



Photo 7: Newspaper sorting and bundling portion of the warehouse.



Photo 8: Three 20,000-gallon diesel fuel USTs and pump island.



Photo 9: Wastewater treatment plant west of the building.



Photo 10: Fire pond west of the building.



Photo 11: Pad-mounted transformers and emergency generators (with 1,100-gallon diesel ASTs) north of the building.





Photo 12: 15,000-gallon diesel AST east of the building.

Appendix C

Historical Documentation

- **Aerial Photographs**
- **Previous Environmental Reports**





Scale: 1” = 500’

Aerial Photograph

1938

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00



Scale: 1" = 500'

Aerial Photograph

1957

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00

RPS



Scale: 1” = 500’

Aerial Photograph

1980

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00



Scale: 1" = 500'

Aerial Photograph

1994

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00

RPS



Scale: 1” = 500’

Aerial Photograph

2011

Newsday
235 Pinelawn Road
Melville, New York
Project No. 166126.613.00

RPS

CONFIDENTIAL

Phase I Environmental Site Assessment

Newsday Main

235 Pinelawn Road

Melville, New York

Prepared for:

Tribune Company
435 N. Michigan Avenue
Chicago, Illinois 60611

March 2008

Project No. 14023.005.0

Geomatrix

Geomatrix

CONFIDENTIAL

PHASE I ENVIRONMENTAL SITE ASSESSMENT
Newsday Main
235 Pinelawn Road
Melville, New York

March 2008
Project 14023.005.0

This report was prepared by the staff of Geomatrix Consultants, Inc., under the supervision of the Engineer(s) and/or Geologist(s) whose seal(s) and signature(s) appear hereon.

The findings, recommendations, specifications, or professional opinions are presented within the limits described by the client, in accordance with generally accepted professional engineering and geologic practice. No warranty is expressed or implied.



Calvin H. Hardcastle
Principal Engineer

CONFIDENTIAL

TABLE OF CONTENTS

Page

1.0 INTRODUCTION 1
1.1 PURPOSE 1
1.2 REASON FOR PERFORMING THE ESA 2
1.3 SCOPE OF SERVICES 2
1.4 EXCLUSIONS 3
1.5 SIGNIFICANT ASSUMPTIONS 3
1.6 LIMITATIONS 3
1.7 USER RELIANCE 4

2.0 SITE DESCRIPTION 5
2.1 LOCATION AND LEGAL DESCRIPTION 5
2.2 SUBJECT PROPERTY AND VICINITY GENERAL CHARACTERISTICS 5
2.2.1 General Site Setting 5
2.2.2 Geology and Hydrogeology 5
2.3 CURRENT USE OF THE SITE AND ADJOINING PARCELS 6

3.0 INFORMATION PROVIDED BY TRIBUNE 7
3.1 ENVIRONMENTAL LIENS 7
3.2 SPECIALIZED KNOWLEDGE 8

4.0 ENVIRONMENTAL RECORDS REVIEW 10
4.1 STANDARD ENVIRONMENTAL RECORD SOURCES 10
4.1.1 Subject Site 10
4.1.2 FINDS 11
4.1.3 NY Manifest 11
4.1.4 RCRA-NonGen 11
4.1.5 AST 11
4.1.6 LTANKS 12
4.1.7 NY Spills 12
4.1.8 NY Historical Spills 13
4.1.9 HIST LTANKS 13
4.1.10 RCRA-LQG 14
4.1.11 CERCLIS-NFRAP 14
4.1.12 SPDES 14
4.1.13 UST 15
4.1.14 Surrounding Properties 15
4.2 ADDITIONAL RECORDS REVIEW 16

5.0 HISTORICAL DOCUMENT REVIEW 17
5.1 AERIAL PHOTOGRAPHS 17
5.2 HISTORICAL TOPOGRAPHIC MAPS 18
5.3 HISTORICAL SANBORN MAPS 18

CONFIDENTIAL

TABLE OF CONTENTS

(continued)

5.4 CITY DIRECTORIES 19

6.0 SITE RECONNAISSANCE 19
6.1 METHODOLOGY AND LIMITING CONDITIONS 20
6.2 ON-SITE OBSERVATIONS 20
6.3 SURROUNDING PROPERTIES 22

7.0 INTERVIEWS 22

8.0 FINDINGS 23

9.0 OPINIONS 24

10.0 DATA GAPS 25

11.0 CONCLUSIONS 25

12.0 DEVIATIONS 25

13.0 ADDITIONAL SERVICES 25

14.0 REFERENCES 26

15.0 ENVIRONMENTAL PROFESSIONAL SIGNATURE AND STATEMENT 27

FIGURES

Figure 1 Site Location
Figure 2 Site Plan

APPENDIXES

Appendix A Regulatory Database Report
Appendix B Agency Correspondence
Appendix C Aerial Photographs and Historical Maps
Appendix D City Directory Abstract
Appendix E Site Reconnaissance Photographs
Appendix F Questionnaires
Appendix G Resumes of Environmental Professionals

Geomatrix

CONFIDENTIAL

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Newsday Main
235 Pinelawn Road
Melville, New York

1.0 INTRODUCTION

Geomatrix Consultants, Inc. (Geomatrix) has prepared this report to identify potential environmental concerns and to report key findings from a Phase I Environmental Site Assessment (ESA) of the Newsday Main (Newsday) facility located at 235 Pinelawn Road in Melville, New York (the Site or Subject Property). The Site location is shown on Figure 1. The ESA was performed at the request of Tribune Company (Tribune) and was conducted in conformance with the ASTM International (ASTM) E1527-05 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E1527-05). ASTM E 1527-05 complies with U.S. Environmental Protection Agency (EPA) All Appropriate Inquiries (AAI) Final Rule (40 CFR 312), which was promulgated November 1, 2005 and took effect November 1, 2006.

1.1 PURPOSE

The purpose of the ESA is to compile and review available information about the Site and immediate vicinity to identify *recognized environmental conditions* (RECs) to the extent feasible pursuant to ASTM E1527-05. According to ASTM E1527-05, an REC is defined as:

> "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include *de minimis* conditions that generally do not present a threat to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies."

The AAI Final Rule applies to:

> "…conditions indicative of releases and threatened releases of hazardous substances…(and) petroleum or petroleum products are excluded from the definition of hazardous substance…" (as referenced in 40 CRF 312.1).

1.2 REASON FOR PERFORMING THE ESA

Geomatrix understands that Tribune has commissioned this ESA as part of a potential property transaction and that Tribune may provide this ESA to potential buyers of the Subject Property as part of the disclosure documents when appropriate. As such, we understand that Tribune has commissioned this ESA to identify and summarize information required to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) liability (referred to as the landowner liability protections or LLPs). This ESA has been prepared using ASTM E1527 and constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at 42 United States Code (U.S.C.) §9601(35)(B).

1.3 SCOPE OF SERVICES

The scope of services for this ESA included the following tasks:

- conducting site reconnaissance to observe and document current conditions and activities at the Site;
- conducting a visual survey of immediately adjacent parcels from the Site or from public streets;
- interviewing the Site owner/occupant;
- interviewing past owners and occupants of the Site if identified by the current owner;
- interviewing a representative of a local environmental regulatory agency regarding potential environmental conditions, if applicable;
- reviewing historical documents, state, tribal, and local government records or other restrictions on the Site going back to the first time the Site had structures or was used for residential, agricultural, commercial, industrial, or governmental purposes, if readily available;
- reviewing available historical aerial photographs for the Site and vicinity;
- reviewing available Sanborn Fire Insurance (Sanborn) maps for the Site and vicinity;
- reviewing available historical topographic maps for the Site and vicinity;

- obtaining a regulatory database search report to identify reported on-site and off-site chemical releases that may affect soil or groundwater conditions at the Site;
- reviewing selected agency files identified in the regulatory database search report to obtain current status of environmental assessments and/or remediation at the Site and nearby properties;
- reviewing environmental documents related to the Site provided by Tribune;
- evaluating the data and identifying data gaps, open issues, and key uncertainties; and
- preparing a report documenting these activities and identified RECs, including our opinions on the significance of the data gaps insofar as they impact the ability to identify possible contamination.

1.4 EXCLUSIONS

ASTM E1527-05 includes the following list of "additional issues" that are non-scope considerations outside of the scope of the ASTM Phase I practice: asbestos-containing building materials; radon; lead-based paint; lead in drinking water; wetlands; regulatory compliance; cultural and historic resources; industrial hygiene; health and safety; ecological resources; endangered species; indoor air quality; and biologic agents and mold. These additional items were not included in our assessment of the Site: collection and chemical analysis of samples of bulk materials, wastes, soil, water, or air; or an evaluation of seismic or geotechnical characteristics.

1.5 SIGNIFICANT ASSUMPTIONS

Based on regional groundwater information reviewed and discussed in Section 2.2.2 of this report, the assumed direction of horizontal groundwater flow beneath the Site and in the Site vicinity is generally toward the southeast. Geomatrix did not measure groundwater elevations in any wells during this Phase I ESA to confirm groundwater flow direction in the Site vicinity.

1.6 LIMITATIONS

This report does not constitute legal advice. In addition, Geomatrix makes no determination or recommendations regarding the decision to lease, purchase, sell, or provide financing for the Subject Property.

Time Constraint

An ESA report is required to meet the transaction deadlines. The opinions and conclusions presented in this report are only based on the Site conditions observed and information reviewed at the time of this assessment. Information pertaining to Site conditions or changes may exist that Geomatrix is not aware of, or which we have not had the opportunity to evaluate within the time available for this ESA.

Uncertainty Not Eliminated

As acknowledged in ASTM E1527-05, no ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. The use of ASTM E1527-05 is intended to reduce, but not eliminate, this uncertainty.

Within the limitations of the agreed-upon scope of work and ASTM E1527-05, Geomatrix has conducted this ESA in a professional manner in accordance with generally accepted practices, using the degree of skill and care ordinarily exercised by environmental consultants under similar circumstances. Due to physical limitations inherent to this or any environmental assessment, Geomatrix does not warrant that the Site is free of pollutants or that all pollutants have been identified. As such, no absolute determination of environmental risks can be made. No other warranties, expressed or implied, are made.

Reliance on Information Provided by Others

Geomatrix has relied upon information provided by others in the evaluation of environmental site conditions reported herein. Geomatrix did not attempt to independently verify the accuracy or completeness of that information. To the extent that the opinion and conclusions in this report are based in whole or in part on such information, those conclusions are contingent on its accuracy and validity. Geomatrix assumes no responsibility for any consequence arising from any information or condition that was concealed, withheld, misrepresented, or otherwise not fully disclosed or available to Geomatrix.

1.7 USER RELIANCE

This ESA report has been prepared by Geomatrix for the express use of Tribune. No other parties shall rely on this report without the written consent from Geomatrix and Tribune. Tribune may release this report to third parties; however, such third party in using this report agrees that it shall have no legal recourse against Geomatrix or subsidiaries.

2.0 SITE DESCRIPTION

The characteristics and uses of the Site and vicinity are described in the following sections.

2.1 LOCATION AND LEGAL DESCRIPTION

The Site is located at 235 Pinelawn Road in Melville, New York. The Site is approximately 50 acres in size and is occupied by a building totaling approximately 539,000 square feet.

Title records were not provided to Geomatrix for review during this ESA, and a review of environmental liens is excluded from the scope of services for this ESA. Tribune is handling this matter with its counsel.

2.2 SUBJECT PROPERTY AND VICINITY GENERAL CHARACTERISTICS

The general Site setting and the geology and hydrogeology in the vicinity of the Site are summarized in the following subsections.

2.2.1 General Site Setting

The Site was identified on the United States Geological Survey (USGS) Huntington quadrangle topographic map, dated 1967 and photo-revised in 1979 (USGS, 1979). The USGS topographic map was used as the source for Site setting information.

The Site is located at an elevation of approximately 106 feet above mean sea level. The Site is located in a topographic low between higher elevations to the north, west, and east. The topography in the vicinity of the Site slopes to the southeast. The topography of the Site itself is relatively flat. The Site is in an urban area that has been developed for commercial and industrial land use.

2.2.2 Geology and Hydrogeology

The geology of the vicinity of the Site is described in the USGS document "Surficial and Northern Atlantic Coastal Plain Aquifer Systems, Long Island" (USGS, 1995). The vicinity of the Site is dominated by two sub-parallel ridges consisting of the Harbor Hill Terminal Moraine and the Ronkonkoma Terminal Moraine deposited during the Wisconsinian glacial age. The Ronkonkoma Terminal Moraine is closest to the Site. The moraines are dominated by sandy materials mingled with outwash sand and gravel. Coastal Plain sediments from the Cretaceous and Pleistocene ages underlie the moraines. The depth to bedrock is nearly 2,000 feet.

From shallowest to deepest, the Upper Glacial, the Magothy, and the Lloyd aquifers comprise the three main Long Island aquifers. Groundwater is the primary source of potable water on Long Island. Based on potentiometric maps of the aquifers, regional groundwater in the vicinity of the Site flows in a southeasterly direction.

2.3 CURRENT USE OF THE SITE AND ADJOINING PARCELS

The Site consists of 50 acres of land that was developed in 1977 as a newspaper printing facility. The Site layout is shown on Figure 2. Newsday publishes daily newspapers with a circulation of approximately 1.9 million readers weekly. Newsday also circulates flyers in the newspaper. The flyers are inserted at a separate facility located at the adjacent property to the west of the Site at 25 Deshon Drive in Melville, New York. The activities that are performed at the Site are described in greater detail below.

Photographic Development

Photographic development is currently performed using digital technology. Most of the chemical-based photo-processing equipment has been decommissioned (either removed from the Site or is scheduled to be removed in the near future). Mr. Joseph Marino, Manager, Facilities Engineering, Newsday, indicated that silver waste is no longer generated.

Platemaking

In platemaking, the copy is developed onto aluminum plates. A pre-coated plate is exposed to ultraviolet light. Developing solution is applied to the plates, followed by a gum-based sealing solution. The developed plates are bent to fit onto the plate cylinder on the presses. The used plates are recycled off-site.

Printing

The plates from platemaking are fixed to the plate cylinders on the printing presses. The printing process involves transfer of the image in ink from the plate to the cylindrical rubber blankets. The image then is transferred from the rubber blankets to a paper web (a continuously fed roll of paper) at high speed. The units on a Colorliner press use an ink injector system that automatically provides a measured amount of ink to the ink rail. A series of rollers takes the ink from the rail, works it into an even film, and transfers the ink to the printing plate. The printing plate in turn transfers the ink to the rubber blanket cylinder, which

prints the image onto the paper web. Ink volume settings are made at the operator's console that automatically controls the ink addition.

The Colorliner unit uses the Goss Spray Bar System with direct-to-plate dampener rollers that apply a dampening solution (a mixture of water and fountain solution) directly to the plate cylinder. The dampening solution is automatically mixed and pressurized for distribution to the spray bars through eight high-pressure spray nozzles. Dampener settings also are made at the operator's console.

Ink Mixing

Infrequently, colors that cannot be readily matched using the four-color printing process are custom mixed, placed in canisters, and attached to the ink injector system on various press units. The mixing canisters are cleaned by scraping excess ink out and placing the ink into a slop ink collection bin. These canisters are cleaned in a water washer. The slop ink is pumped out of the collection bins into a storage tank for reclaiming on site.

The Site is located in an area that appears to be primarily used for light industrial and commercial purposes. Ruland Road, commercial properties, and properties under development are present to the north of the Site. Parklawn Road and Long Island National Cemetery are present to the east of the Site. An unnamed service road and light industrial and office buildings are present to the south of the Site. Deshon Drive and the Newsday Patterson building are present to the west of the Site, with residential development beyond. Several surrounding properties were identified in the regulatory database search report prepared for this ESA, and environmental issues associated with these properties are further discussed in Section 4.1.2.

3.0 INFORMATION PROVIDED BY TRIBUNE

The following subsections present information provided by Tribune, the user of this Phase I ESA.

3.1 ENVIRONMENTAL LIENS

Title records were not provided to Geomatrix for review during this ESA, and a review of environmental liens is excluded from the scope of services for this ESA. Tribune is handling this matter with its counsel.

3.2 SPECIALIZED KNOWLEDGE

No specialized knowledge was provided by Tribune.

The following items of environmental interest were identified during review of Newsday's environmental files:

- A Compliance Stack Test Report, dated December 6, 2007, indicated that the air discharges from the Site met the requirements contained in the State Facility Air Permit 1-4726-00157/00003.
- Newsday received a letter from the New York State Department of Environmental Conservation (DEC) on January 2, 2008, citing 11 violations for a storage tank in the wastewater treatment plant (WWTP). Newsday responded to DEC on January 8, 2008, stating that the storage tank had been removed and the Site was in compliance.
- Newsday submitted an Annual Hazardous Waste Report to the DEC on February 22, 2007. Newsday reported that 30.2 tons of hazardous wastes were generated at the Site in 2006.
- A spill occurred in the solvent storage room in 2007. Approximately 55 gallons of C&W New Age L-50 WMB (blanket wash fluid) spilled from a drum. The fluid was collected and approximately 3 cubic yards of absorbent material were used to clean up the fluid.
- The 2007 annual report for State Pollutant Discharge Elimination System (SPDES) NY0136751 identified the following non-compliance events:
  - December 2007 – non-compliance for alkalinity (6.1 milligrams per liter [mg/L]).
  - March 2007 – non-compliance for nitrogen (48 mg/L).
  - February 2007 – non-compliance for nitrogen (41 mg/L).
- The following summarizes the most recent list of tanks for the Operating Permit Renewal for Registration No. 4-0094 as submitted to the DHS:

Tank ID	Capacity (gallons)	Product
6	25,000	No. 2 fuel oil
7	25,000	No. 2 fuel oil
9	275	No. 2 fuel oil

Tank ID	Capacity (gallons)	Product
10	8,000	black ink
11	8,000	black ink
12	8,000	black ink
14	20,000	diesel
15	20,000	diesel
16	20,000	diesel
17	100	No. 2 fuel oil
18	2,500	No. 2 fuel oil
22	1,380	drum storage
23	200	industrial waste
24	165	industrial waste
25	500	industrial waste
31	8,000	black ink
32	8,000	black ink
33	8,000	black ink
34	2,000	cyan ink
35	2,000	yellow ink
36	2,000	red ink
37	2,000	magenta ink
38	125	No. 2 fuel oil
40	25	No. 2 fuel oil
41	550	blowdown
42	550	industrial waste
44	55	developer
45	55	developer
46	55	fixer
47	55	fixer
48	66	photo chemicals
49	200	dry photo chemicals
57	80	boiler chemical
58	80	boiler chemical
59	80	boiler chemical
60	80	boiler chemical
61	80	cooling tower chemical
62	140	cooling tower chemical
63	80	cooling tower chemical
64	140	cooling tower chemical
65	220	methanol
66	660	drum storage
68	5,280	drum storage
70	120	elevator hydraulic oil

Tank ID	Capacity (gallons)	Product
71	80	compressor hydraulic oil
74	275	miscellaneous drums
75	500	fountain solution
76	500	fountain solution
77	500	fountain solution
78	500	fountain solution
79	660	transfer facility
80	60	industrial waste
81	60	industrial waste
82	50	industrial waste
83	500	industrial waste
84	2,860	unknown
85	200	degreaser
86	1,100	diesel
87	1,100	diesel
--	186,706	Total Gallons Storage

4.0 ENVIRONMENTAL RECORDS REVIEW

The findings of environmental records research and review are presented in the following subsections.

4.1 STANDARD ENVIRONMENTAL RECORD SOURCES

Geomatrix retained Environmental Data Resources, Inc. (EDR), of Milford, Connecticut to search federal, state, and tribal environmental regulatory databases to identify properties located within ASTM-specified radii of the Site with documented environmental releases and/or those properties that use, store, or dispose of regulated chemicals. The entire facility and all surrounding properties were captured by this search radius. A list of the regulatory databases searched and the results are presented in the EDR report provided in Appendix A.

4.1.1 Subject Site

The Site was identified by EDR as being listed on the following regulatory databases – Facility Index System/Facility Registration System (FINDS), New York Manifest (NY Manifest), Resource Conservation and Recovery Act Non-Hazardous Waste Generators (RCRA-NonGen), Aboveground Storage Tank (AST), Leaking Storage Tank Incident Reports (LTANKS), NY Spills, NY Historical Spills, Historical LTANKS (HIST LTANKS), RCRA Large Quantity

Generators (RCRA-LQG), Comprehensive Environmental Response, Compensation, and Liability Information System No Further Remedial Action Planned (CERCLIS-NFRAP), State Pollutant Discharge Elimination System (SPDES), and Underground Storage Tank (UST).

Summaries of the listings are described below.

4.1.2 FINDS

The FINDS database contains both facility information and 'pointers' to other sources that contain more detail. Nalco Chemical (provider of boiler and cooling tower descaler) at 235 Pinelawn Road is listed in NY Manifest and RCRA-NonGen databases as further discussed below.

4.1.3 NY Manifest

The NY Manifest database lists and tracks hazardous waste from the generator through transporters to a treatment storage, and disposal facility (TSDF). Nalco Chemical is listed for the Site's boiler house. The database lists the waste code as D002 (non-corrosive wastes) that are stored in metal drums or barrels. The wastes likely relate to the boiler descaler used at the Site. No violations or records of spills were reported for these wastes. Based on this information, the listing of NY Manifest is not expected to represent a significant environmental concern.

4.1.4 RCRA-NonGen

The RCRA-NonGen database contains records of non-generators that do not presently generate hazardous waste. Nalco Chemical is listed for the Site's boiler house. The database lists Nalco Chemical as a verified non-generator with no violations found. Based on the lack of violations, the listing of RCRA-NonGen is not expected to represent a significant environmental concern.

4.1.5 AST

The AST database contains information on ASTs that are registered with the DEC. A total of 70 AST records were recovered by EDR. These records relate to the storage of diesel fuel for the emergency generators, ink storage, descaler storage, and other materials related to the publishing process. Environmental issues pertaining to the ASTs are discussed further in Section 8.0.

4.1.6 LTANKS

The LTANKS database contains records of leaking storage tank incident reports from April 1, 1986 through to the most recent update. The following records were identified in the database:

- A failed tightness test for a 25,000-gallon UST was reported to the DEC on November 11, 1997. The "spill closed date" was not listed in the EDR report.
- A failed tightness test for a 25,000-gallon UST was reported to the DEC on April 30, 1992. The affected media was reported as soil. The tank and lines passed a tightness test on May 15, 1992. The release reportedly occurred from a compression pipe clamp below the surface-mounted fill cap. The fill box was replaced and approximately 2 cubic yards of contaminated soil were removed. The spill was closed on May 27, 1998.

Geomatrix was not provided with reports/documents pertaining to the leaking UST. In lieu of these documents, Geomatrix cannot rule out the possibility of residual subsurface contamination from the reported leaking UST(s).

4.1.7 NY Spills

The NY Spills database contains records of spills reported to the DEC. The following records were listed in the database:

- A release of 1,000 to 1,500 gallons of diesel fuel (initially reported as 100 to 200 gallons) occurred to the blacktop and storm drain on October 23, 2000. A remedial contractor was retained to clean the storm drain. The spill was closed on December 14, 2000.
- A release of 100 gallons of ink was reported to the DEC on September 22, 2005. The release reportedly occurred in a bermed area within a sealed floor. The spill was closed on March 14, 2006.
- A release of 40 gallons of No. 2 fuel oil was reported to DEC on October 20, 1989. The release reportedly occurred when a pump over-ran near an emergency generator and the fuel oil was released. The spill was closed on October 23, 1989.
- A release of 20 to 35 gallons of hydraulic oil was reported to DEC on August 18, 2007. The release reportedly occurred when a hydraulic line on a trash compactor was ruptured. The hydraulic oil was cleaned up using absorbent, which was subsequently placed into drums and disposed off-site. The spill was closed on December 1, 1997.

Based on regulatory closures, the listings of NY Spills are not expected to represent a significant environmental concern.

4.1.8 NY Historical Spills

The NY Historical Spills database contains records of chemical and petroleum spill incidents. The NY Historical Spills contains fields that are no longer available from the DEC as of January 1, 2002.

- A release of 100 to 200 gallons of diesel fuel occurred to the blacktop and storm drain on October 23, 2000. A remedial contractor was retained to clean the storm drain. The spill was closed on December 14, 2000. This release appears to be the same release discussed above in NY Spills.

- A release of 20 gallons of hydraulic oil from a truck was reported to the DEC on August 27, 2001. The spill reportedly was cleaned with speedy dry. The spill closed date was not listed in the EDR report.

- A release of 50 gallons of diesel fuel from a truck was reported to the DEC on January 21, 1994. The release was reportedly contained and cleaned up. The spill close date was March 29, 1994.

- A release of 40 gallons of No. 2 fuel oil was reported to DEC on October 20, 1989. The release reportedly occurred when a pump over-ran near an emergency generator and the fuel oil was released. The spill was closed on October 23, 1989. This release appears to be the same release discussed in NY Spills.

- A release of 20 to 35 gallons of hydraulic oil was reported to DEC on August 18, 2007. The release reportedly occurred when a hydraulic line on a trash compactor was ruptured. The hydraulic oil was cleaned up using absorbent, which was subsequently placed into drums and disposed off-site. The spill was closed on December 1, 1997. This release appears to be the same release discussed in NY Spills.

Based on regulatory closures, the listings of NY Historical Spills are not expected to represent a significant environmental concern.

4.1.9 HIST LTANKS

The HIST LTANKS database contains records of leaking USTs and ASTs. This database was no longer updated as of January 1, 2002. The following records were identified in the database:

- A failed tightness test for a 25,000-gallon UST was reported to the DEC on November 11, 1997. This release appears to be the same incident discussed in LTANKS.

- A failed tightness test for a 25,000-gallon UST was reported to the DEC on April 30, 1992. This release appears to be the same incident discussed in LTANKS.

Geomatrix was not provided with reports/documents pertaining to the leaking UST. In lieu of these documents, Geomatrix cannot rule out the possibility of residual subsurface contamination from the reported leaking UST(s).

4.1.10 RCRA-LQG

The RCRA-LQG database contains records of large-quantity generators of hazardous waste as defined by RCRA. LQGs generate over 1,000 kilograms of hazardous waste or over 1 kilogram of acutely hazardous wastes per month. The Site is listed as a LQG for batteries, lamps, ignitable hazardous wastes, corrosive hazardous wastes, and spent halogenated solvents. The EDR report indicates that Newsday has received 13 notices of violations. All of the violations are listed as having "written informal" enforcement action, with compliance being achieved for all violations. No documented releases of these wastes were reported. Based on the absence of documented releases, the RCRA listing is not expected to represent a significant environmental concern.

4.1.11 CERCLIS-NFRAP

The CERCLIS-NFRAP database lists sites that have been delisted due to completion of assessment activities where no further action will be taken to list the sites on the National Priorities List (NPL). The CERCLIS-NFRAP assessment process for the Site reportedly was completed on October 21, 1998. Based on the delisted status of the Site, the CERCLIS-NFRAP listing is not expected to represent a significant environmental concern.

4.1.12 SPDES

The SPDES database contains records of controlled wastewater and stormwater discharges in accordance with the Clean Water Act, including discharges to groundwater. The SPDES permit for the Site's WWTP expires on September 30, 2011. The average flow is listed as 45,000 gallons per day. The treated effluent reportedly is discharged to groundwater. No documented releases from the WWTP were reported. Based on the absence of documented releases, the SPDES listing is not expected to represent a significant environmental concern.

4.1.13 UST

The UST database contains records of facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. The UST database lists 14 registered USTs at the Site as follows:

Tank ID	Capacity (gallons)	Product	Comment
1	25,000	Diesel	Removed on 1/1/86
2	25,000	Diesel	Removed on 1/1/86
3	25,000	Diesel	Removed on 1/1/86
4	12,000	Gasoline	Removed on 1/1/86
5	2,000	Spill containment	Abandoned on 6/28/88
6	25,000	No. 2 fuel oil	Testing was due in 1997
7	25,000	No. 2 fuel oil	Next test due in 2008
8	4,000	Industrial waste	Removed on 1/1/87
14	20,000	Diesel	Permit runs out in 1990
15	20,000	Diesel	Permit runs out in 1990
16	20,000	Diesel	Permit runs out in 1990
18	2,500	No. 2 fuel oil	Permit runs out in 1992
19	4,000	Industrial waste	Never installed
20	10,000	Gasoline	Never installed

At the time of this report, DEC has not responded to Geomatrix's Freedom of Information Law (FOIL) request to review their records. In addition, previous environmental investigation reports to evaluate the potential for impact from the former USTs at the Site were not provided to Geomatrix. In lieu of these documents, Geomatrix cannot confirm the presence or absence of contaminated subsurface conditions at the Site relating to abandoned or removed USTs. Geomatrix reviewed UST registration and tightness testing records contained in Newsday's files. UST registration with the Suffolk County Department of Health Services (DHS) and tank tightness testing requirements appeared to be current and up-to-date. In addition, all operating USTs at the Site passed the most recent tank tightness test.

4.1.14 Surrounding Properties

Migration of contaminants to sites other than the release location generally is via groundwater. Therefore, only those contaminant release sites located hydrogeologically up gradient relative to the Site are expected to pose a significant potential for environmental concern to the Site. Contaminated sites located hydrogeologically down gradient of the Site are not expected to

represent a potential threat to the groundwater quality beneath the Site. Sites that are situated hydrogeologically cross gradient relative to the Site also are not expected to represent a concern unless close proximity allows for the potential of lateral migration. As discussed in Section 2.2.2, groundwater in the vicinity of the Site is assumed to flow to the southeast.

Based on a review of the EDR database search report, Geomatrix identified the following properties that required explanations in regards to their potential for adverse impact on the Site.

25 Deshon Drive (Newsday/Belwin Mills/J.M. Abrizzio)

This facility is located adjacent to the west (hydrogeologically cross gradient) of the Site across Deshon Drive. This facility is identified in the EDR report in the following databases: NY Manifest, RCRA, AST, NY Spills, Historical Spills, UST, and FINDS. Environmental issues at this property are not expected to represent significant environmental concern based on the assumed direction of groundwater flow. Environmental issues specifically targeting this property are presented in more detail in Geomatrix's separate Phase I ESA for this property.

255 Pinelawn Road (Imperial News Co./Clare Rose/Abandoned Building)

This facility is located within the immediate vicinity to the south (hydrogeologically cross gradient) of the Site. This facility is identified in the EDR report in the following databases: LTANK, LTANKS, NY Manifest, NY Spills, and Historical Spills. Environmental issues at this property are not expected to represent significant environmental concern based on the assumed direction of groundwater flow.

Based on the reported information in the EDR report, no other properties are expected to represent significant environmental concern. For additional regulatory database information of surrounding properties, refer to the database search report provided in Appendix A.

4.2 ADDITIONAL RECORDS REVIEW

Geomatrix submitted written FOIL requests to the DEC and Melville Fire District on February 1, 2008. The purpose of the FOIL requests was to obtain records that may provide information with respect to known environmental conditions at the Site. The Melville Fire District responded on February 19, 2008 with information regarding flammable material storage and fire suppression systems at the Site. The DEC responded on February 25, 2008 that they would provide a decision regarding access to files by March 27, 2008.

5.0 HISTORICAL DOCUMENT REVIEW

Geomatrix reviewed historical aerial photographs, historical topographical maps, and city directory abstracts to identify the historical use of the Site and adjacent properties.

The following sources of information were obtained and used to compile historical information about the Site:

- Aerial photographs dated 1957, 1966, 1976, 1980, and 1994;
- Topographic maps dated 1903, 1904, 1947, 1967, and 1979; and
- City directory abstracts dated 1971, 1976, 1981, 1986, 2002, and 2007.

No Sanborn maps were available for the Site and surrounding area. Below is a summary of the historical information review

5.1 AERIAL PHOTOGRAPHS

Geomatrix reviewed historical aerial photographs of the Site and vicinity from the years stated above. A summary of the information observed for the Site and surrounding areas is presented below. Copies of the aerial photographs are presented in Appendix D.

Date ***Description of Site and Surrounding Area***

1957 The Site and surrounding area appear to be in use for agricultural purposes.

1966 The Site still appears to be used for agricultural purposes. A cemetery is visible to the southeast of the Site. Commercial/industrial development is visible to the south of the Site. No other significant changes are evident on this aerial photograph.

1976 The Site is still in use for agricultural purposes. Commercial/industrial development is present at the adjoining property to the south of the Site. The current Newsday inserting facility at 25 Deshon Drive is evident to the west of the Site. A building is present at the property to the north of the Site. No other significant changes are evident on this aerial photograph.

1980 The Site appears to be developed. The original building is visible on the east side of the Site. A parking lot is present on the south side of the Site. The fire pond is visible on

the west side of the Site. The area to the north of the building appears undeveloped. Additional buildings have been constructed at the adjoining properties to the southwest of the Site. No other significant changes are evident on this aerial photograph.

1994 Additions are evident on the west and south sides of the original building. The WWTP is visible on the west side of the Site. A parking lot is visible on the north side of the Site. No other significant changes are evident on this aerial photograph.

5.2 HISTORICAL TOPOGRAPHIC MAPS

Topographic maps from 1903, 1904, 1947, 1967, and 1979 were provided by EDR. The topographic map scales ranged from 1:24000 to 1:125000. A description of the observations from the historical map review is presented below. Copies of the historical maps are included in Appendix C.

Date Description of Site and Surrounding Area

1903 Small structures (presumably farmhouses) are shown along the road in the vicinity of the Site. No other significant details are evident on this topographic map.

1904 The scale of the map (1:125000) precludes any observations regarding the use of the Site and surrounding area.

1947 No significant changes are evident compared to the 1903 topographic map.

1967 Small structures (presumably farmhouses) are still visible at the Site location. Industrial/commercial development is visible to the south of the Site. Long Island National Cemetery is present to the southeast of the Site.

1979 Additional industrial/commercial structures are visible, including 25 Deshon Drive and buildings at the adjoining property to the south of the Site. The Site appears to be undeveloped.

5.3 HISTORICAL SANBORN MAPS

No Sanborn maps were available for the Site and surrounding area. A copy of EDR's search results is provided in Appendix C.

5.4 CITY DIRECTORIES

Geomatrix reviewed a historical city directory abstract for the Site and surrounding area for the years listed in Section 5.0. The complete EDR listings are provided in the abstract in Appendix D. A review of past businesses of interest is discussed below.

Target Address (235 Pinelawn Drive, Melville, New York)

The Site is not listed in the city directory abstract until 1981. Newsday Inc. appears as the Site occupant in 1981, 1986, and 1991. Long Parents & Children, This Week Publications, and Wage Co. are listed as the Site occupants in 2002. "Office Building" is listed for 2007.

Surrounding Properties

The occupants of surrounding properties were not listed in the city directory abstract until 1976. A description of significant listings from the city directory review is presented below.

Address	*Date(s)*	*Listing*
25 Deshon Drive	1976	Belmil Computer
	1981-1986	Apt. Advertising Displays Belmil Computer Belwin Mills Pub CSG Creative Svc Music Boutique
	1986	Dal Moline MSC Typ
	2007	Newsday Inc
35 Deshon Drive	1976	Hampshire Press Maple Bindery

6.0 SITE RECONNAISSANCE

Mr. Rob Hoag of Geomatrix conducted reconnaissance of the Site on February 6, 2008. The following individuals accompanied Geomatrix on the Site reconnaissance:

- Mr. Joseph Marino, Manager, Facilities Engineering, Newsday.
- Mr. Mark Anderson, Director, Environmental Affairs, Tribune.

6.1 METHODOLOGY AND LIMITING CONDITIONS

The Site visit included a walk-through of the Site to observe current operations. No limitations were placed on access to the Site and Site personnel were cooperative. Selected photographs are provided in Appendix E. The weather was overcast and windy, with a temperature of approximately 64 degrees Fahrenheit. Geomatrix did not access the roof due to high winds. A description of the Site, as observed by Geomatrix, is provided in the following sections.

6.2 ON-SITE OBSERVATIONS

The following is a summary of on-site observations and information provided by Messrs Marino and Anderson during the reconnaissance:

- The Site is approximately 50 acres in size and is occupied by a building totaling approximately 539,000 square feet. Mr. Marino indicated that two additions have been constructed at the plant. The printing floor was expanded to the west approximately 15 years ago in order to accommodate additional printing presses. The newspaper bundling and palletizing area and shipping docks were expanded at the south side of the building.

- Ten printing presses are present. Six of the presses are the original presses that were installed when the facility was first developed. Four of presses were installed approximately six years ago. The presses and associated equipment are present over two floors. The lower floor consists of the support structures for the presses, ink storage areas, paper roll storage area, a boiler room, mechanical rooms, and emergency generators. The upper floor consists of the presses, mechanical rooms, and electrical rooms. Mr. Marino indicated that all transformers are dry-type and do not contain polychlorinated biphenyls. Descaling fluid is stored in plastic ASTs with secondary and tertiary containment in each of the boiler rooms (four 80-gallon ASTs) and the cooling tower room (four 80- to 140-gallon ASTs).

- Two 25,000-gallon, one 6,000-gallon, and one 2,000-gallon USTs and four small indoor ASTs (day tanks) are present to store No. 2 fuel oil in support of the boilers and emergency generators. Current permits from the DHS were displayed where ASTs were present.

- Printing ink is stored in several ASTs installed at various locations at the Site. Four 2,000-gallon ASTs are present for color ink (one each for cyan, magenta, yellow, and red) and six 8,000-gallon ASTs are present for black ink. Approximately 80 percent of the ink used is black, with cyan, magenta, and yellow inks used to create color print. All ink storage areas were observed to have secondary containment consisting of concrete floors and walls with epoxy coatings. The floors and walls in containment areas were observed to be in good conditions with no obvious signs of wear or cracking. All entrances to the ink storage areas are either

from an elevated doorway with staircase or raised threshold. A release of red ink reportedly occurred recently from a failed fitting associated with one of the ASTs. Red ink staining was observed on the piping and support structures in the vicinity of the release; however, the release appeared to have been contained and the epoxy coating on the floor and walls was in good condition. In general, the ink is relatively viscous and does not flow readily at ambient temperatures. Current permits from the DHS were displayed where ASTs were present.

- Geomatrix observed 55-gallon drums of lubricating oil at several locations throughout the printing area, including the machine shop, a mechanical room, adjacent to the printing presses, and a containment area on the first floor. All drum storage areas had secondary containment greater than 110-percent of the volume of oil stored. Current permits from the DHS were displayed in all storage areas.

- Newsday reportedly converted to digital photographic development approximately one year ago. Mr. Marino reported that minimal waste silver is currently produced at the facility. Geomatrix observed that the unused photo processing equipment and associated photochemical ASTs were either not in use or had already been removed.

- Offices are present on the first and second floors on the east side of the Site. The office areas are divided according to function, and include reporting and editorial staff, administration, accounting, marketing, classifieds, and engineering. A cafeteria is present near the northeast corner of the building.

- Outdoor surfaces consist of landscaped areas, concrete, and asphalt. Employee parking is provided on the north and southeast sides of the Site. The northwest area of the property appears to be undeveloped.

- Semi-enclosed emergency generators are present on the north and west sides of the Site. The USTs are supported by day tanks. Secondary containment of the day tanks was observed to be present. Mr. Marino indicated that UST tightness testing was up-to-date and that the USTs met regulatory requirements.

- Two trailer-mounted emergency generators are present outside on the north side of the building. Each trailer contains a 1,250-gallon AST with secondary containment.

- A vehicle refueling area is present on the southwest side of the Site. Three 20,000-gallon USTs are present to store diesel for refueling Newsday delivery vehicles. Three fuel dispensers are present. The tanks are equipped with leak detection probes at each end of the tanks. Mr. Marino indicated that UST tightness testing was up-to-date and that the USTs met regulatory requirements. A spill containment kit was present. The attendant indicated that daily reconciliation records are maintained and that no discrepancies have been noted. All USTs at the Site are connected to a Veeder Root automatic leak detection system. Two of the spill bucket lids in this area were observed to be cracked and in need of replacement.

- A large pond is present on the west side of the Site to store water for firefighting purposes.

- A reported explosion-proof structure is present in a fenced enclosure on the west side of the Site. Newsday stores hazardous and flammable materials in drums and pails inside this structure. An explosion-proof tote is stored in the fenced enclosure and is used to transport hazardous and flammable materials from the facility to the explosion-proof structure.

- An unused building is present on the west side of the Site near the security gate. The building was formerly used to screen incoming mail for biological agents after September 11, 2001.

- All wastewater generated at the Site is treated in the on-site WWTP. The WWTP operates under SPDES permit NY0136751. The WWTP reportedly was recently upgraded to improve treatment efficiency and has a design flow of 45,000 gallons per day per train. Wastewater is treated using a combination of screens, two rotary aerators, and two membrane clarifiers. Two sludge holding tanks are present. Treated wastewater is discharged to an underground cistern system. SPDES non-compliance issues occurred during changes to the WWTP. Newsday indicated that no significant SPDES violations had occurred since substantial completion of the WWTP upgrades. Geomatrix noted a non-compliance report in December 2007 for exceeding alkalinity limits.

- Newsday leases part of the parking lot on the west side to a snow-removal contractor for storage of snow-removal equipment.

6.3 SURROUNDING PROPERTIES

The Site is located in an area that appears to be primarily used for light industrial and commercial purposes. Ruland Road, commercial properties, and properties under development are present to the north of the Site. Parklawn Road and Long Island National Cemetery are present to the east of the Site. An unnamed service road and light industrial and office buildings are present to the south of the Site. Deshon Drive and the Newsday Patterson building are present to the west of the Site, with residential development beyond. No environmental issues were identified in viewing the surrounding properties from publicly accessible areas.

7.0 INTERVIEWS

Geomatrix interviewed the following personnel during the Site visit:

- Mr. Joseph Marino, Manager, Facilities Engineer, Newsday.

- Mr. Mark Anderson, Director, Environmental Affairs, Tribune.

Findings from interviews with Site personnel are included in Section 6.2. Mr. Marino indicated that he viewed the operation as clean and well-run with minimal risk of environmental impact. A Property Owner/Representative Questionnaire was completed by Mr. Joseph Marino, whose responses were consistent with the findings in the EDR report. A user questionnaire was completed by Mr. Mark Anderson. Copies of the completed questionnaires are provided in Appendix F.

8.0 FINDINGS

No RECs or historical RECs (HRECs) were identified at the Site. The following are findings of our ESA.

Potential environmental concerns include issues identified by Geomatrix that warrant discussion but are not considered RECs, as defined by ASTM E1527-05. The following potential environmental concerns associated with the Site and/or the surrounding properties were identified by Geomatrix:

- The EDR report identifies the Site on the FINDS, NY Manifest, RCRA-NonGen, AST, LTANKS, NY Spills, NY Historical Spills, HIST LTANKS, RCRA-LQG, CERCLIS-NFRAP, SPDES, and UST databases. Based on the reported information from the EDR report, overall good housekeeping observed, and reviews of agency records and historical information, these listings, except for the LTANKS with associated HIST LTANKS, UST, and NY Spills listings, are not expected to represent a significant environmental concern. At the time of this report, DEC has not responded to Geomatrix's FOIL request. In addition, previous environmental investigation reports to evaluate the potential for impact from the removed/abandoned USTs and the leaking UST at the Site were not provided to Geomatrix. Environmental issues pertaining to these USTs are discussed in Section 10.0.

- The EDR report identifies several properties within the respective search radii as having handled and or generated hazardous waste, and/or as having reported releases of hazardous substances or petroleum products. Based on the reported information about these properties, the identification of responsible parties, and/or the assumed groundwater flow direction, these properties are not expected to represent a significant environmental concern to the Site.

- The Site operates a WWTP, which discharges effluent to a cistern. Minor exceedances of SPDES discharge limits has occurred in the past. The exceedances appeared to have been addressed to the satisfaction of the DEC.

- Two spill bucket lids associated with the USTs in the vehicle refueling area are cracked and should be replaced.

- There has been long-term storage of materials, including diesel fuel, No. 2 fuel oil, inks, photo-processing chemicals, boiler and cooling tower descalers, and other potentially hazardous materials in USTs and ASTs. All permits were up-to-date. Site management procedures appeared to be appropriate. Based on the good housekeeping observed and the absence of significant spills of these materials, the presence of these chemicals is not expected to represent a significant environmental concern.

- The Site was previously used for agricultural purposes in 1957 and possibly earlier. By the late 1970's, the facility was under construction and newspaper publishing operations began. Environmental issues pertaining to the former agricultural use are discussed in Section 10.0.

- According to the EDR database search report, historic spills were identified at 255 Pinelawn Road, which is located immediately adjacent to the Site. The spills reportedly were remediated and closed by the DEC.

9.0 OPINIONS

ASTM E1527 requires the environmental professional's opinion of the potential impacts on the Subject Property of REC(s) identified. No RECs or historical RECs were identified for the Site. Our opinion regarding other findings is discussed below.

- The Site was identified by EDR as being listed on LTANKS with associated HIST LTANKS, UST, and NY Spills databases. A leaking UST was reported on April 30, 1992 and on November 20, 1997 from the 25,000-gallon UST. The leak from April 30, 1992, which reportedly impacted soil only, was closed on May 27, 1998. The current status of the leak from November 20, 1997, which reportedly impacted groundwater, is unknown. In addition, six former USTs were removed or abandoned-in-place between 1986 and 1988. Previous environmental investigation reports to evaluate the potential for impact from the removed/abandoned USTs and the leaking UST at the Site were not provided to Geomatrix. In lieu of these documents, Geomatrix cannot rule out the possibility of subsurface contamination from the USTs.

- The agricultural use of the Site prior to development may have included agricultural chemicals. No evidence of a release of agricultural chemicals was discovered during this ESA; therefore, the historical use alone does not represent a REC. In addition, the Site is either paved or covered by improvements that make direct contact with any potential residual agricultural chemicals in the soil unlikely. Furthermore, the Site is developed and used for commercial purposes. No further assessment related to the former agricultural use of the Site is recommended.

10.0 DATA GAPS

The DEC indicated that they would respond to our FOIL request to review their files by March 27, 2008, which is after the due date of this Phase I ESA. As required by ASTM E1527-05 Geomatrix has identified two data gaps:

- at the time of this report, DEC has not responded to Geomatrix's FOIL request; and
- previous environmental investigation reports to evaluate the potential for impact from the former USTs and the leaking UST at the Site were not provided to Geomatrix.

These data gaps preclude Geomatrix from ruling out the potential for as yet unrecognized RECs or other environmental concerns related to these matters.

11.0 CONCLUSIONS

Geomatrix performed a Phase I ESA of the Newsday facility located at 235 Pinelawn Road in Melville, New York in conformance with the scope and limitations of ASTM Standard E1527-05. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report. This ESA has not revealed any RECs or HRECs in connection with the Site; however, two data gaps were identified, as discussed in Section 10.0.

12.0 DEVIATIONS

No deviations or deletions from ASTM E1527-05 were made during preparation of this ESA.

13.0 ADDITIONAL SERVICES

No additional services were provided as part of this ESA.

14.0 REFERENCES

ASTM International (ASTM), 2005, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation: E 1527-05.

Environmental Data Resources, Inc. (EDR), 2008a, The EDR Radius Map with GeoCheck, 25 Deshon Drive & 235 Pinelawn Road, Melville, New York, January 29, 2008.

Environmental Data Resources, Inc. (EDR), 2008b, The EDR Aerial Photo Decade Package, 25 Deshon Drive & 235 Pinelawn Road, Melville, New York, January 29, 2008.

Environmental Data Resources, Inc. (EDR), 2008c, The EDR Historical Topographic Map Report, 25 Deshon Drive & 235 Pinelawn Road, Melville, New York, January 29, 2008.

Environmental Data Resources, Inc. (EDR), 2008d, Certified Sanborn Map Report, 25 Deshon Drive & 235 Pinelawn Road, Melville, New York, January 29, 2008.

Environmental Data Resources, Inc. (EDR), 2008e, The EDR – City Directory Abstract, 25 Deshon Drive & 235 Pinelawn Road, Melville, New York, January 29, 2008.

United States Geological Survey (USGS), 1995. Groundwater Atlas of the United States, Surficial and Northern Atlantic Coastal Plain Aquifer Systems, Long Island, HA730-M.

United States Geological Survey (USGS), 1979, 7.5 Minute Quadrangle Map, Huntington, New York.

15.0 ENVIRONMENTAL PROFESSIONAL SIGNATURE AND STATEMENT

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in section 312.10 of 40 Code of Federal Regulations (CFR) 312. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312. Resumes for the environmental professionals are included in Appendix G.

Tim Wood for Rob Hoag



Rob S. Hoag, MSc, PE
Senior Engineer

FIGURES




March 05, 2008–11:15am

Geomatrix

Geomatrix Consultants and Engineers, Inc.
420 Weber Street, North, Unit G
Waterloo, Ontario N2L 4E7
(519) 886-7500

FIGURE 1 – SITE LOCATION
PHASE 1 ENVIRONMENTAL SITE ASSESSMENT
NEWSDAY MAIN
235 PINELAWN DRIVE
MELVILLE, NEW YORK

DATE	PROJ. NO.
MARCH 2008	14023.005
FILE NO.	DWG. NO.
14023–figs	FIG-1



CAUTION: THIS PLAN MAY BE REDUCED 0 25mm 50mm ORIGINAL SCALE

NO.	REVISION	DATE	APRVD

DRAWN
DESIGNED
CHECKED
REVIEWED

Geomatrix

Geomatrix Consultants and Engineers, Inc.
420 Weber Street, North, Unit G
Waterloo, Ontario N2L 4E7
(519) 886-7500

FIGURE 2
PHASE I ENVIRONMENTAL SITE ASSESSMENT
NEWSDAY MAIN

235 PINELAWN DRIVE
MELVILLE, NEW YORK

DATE:	MARCH 2008
SCALE:	1" = 100'-0"
SHEET:	1 OF 1 SHEETS
PROJ No: 14023.005	FIG-2

Filepath: S:\Geomatrix 2008 081997-J Newsday Patterson (14023) 14023-main.dwg
Plot Time: Mar 05, 2008 - 10:50am, Plotted By: Dell Survey2

Environmental Testing Labs, Inc.

ETL Chain of Custody: 1004421							
Project: NEWSDAY							
Address: 235 Pi	Collected Date:		04/28/10	04/28/10	04/28/10	04/28/10	04/28/10
	Sample Type:		Grab	Grab	Grab	Grab	Grab
	Sample Name:		T-14 East	14 Center	T-14 West	T-15 East	15 Center
Analysis	**Analyte**	**Units**					
STARS Semivolatiles	Naphthalene	ug/Kg	<50.3	<50.8	<52.9	<52.5	<56.9
STARS Semivolatiles	Acenaphthene	ug/Kg	<34.7	<35.0	<36.5	<36.2	<39.2
STARS Semivolatiles	Fluorene	ug/Kg	<41.2	<41.6	<43.3	<43.1	<46.6
STARS Semivolatiles	Phenanthrene	ug/Kg	<51.3	<51.8	<53.9	<53.5	<57.9
STARS Semivolatiles	Anthracene	ug/Kg	<32.8	<33.1	<34.5	<34.3	<37.1
STARS Semivolatiles	Fluoranthene	ug/Kg	<48.2	<48.7	<50.7	<50.3	<54.5
STARS Semivolatiles	Pyrene	ug/Kg	<43.2	<43.7	<45.5	<45.2	<48.9
STARS Semivolatiles	Benzo(a)anthracene	ug/Kg	<52.8	<53.4	<55.5	<55.2	<59.7
STARS Semivolatiles	Chrysene	ug/Kg	<49.6	<50.1	<52.1	<51.8	<56.0
STARS Semivolatiles	Benzo(b)fluoranthene	ug/Kg	<64.3	<65.0	<67.6	<67.2	<72.7
STARS Semivolatiles	Benzo(k)fluoranthene	ug/Kg	<45.9	<46.3	<48.2	<47.9	<51.8
STARS Semivolatiles	Benzo(a)pyrene	ug/Kg	<46.7	<47.2	<49.1	<48.8	<52.8
STARS Semivolatiles	Indeno(1,2,3-cd)pyrene	ug/Kg	<48.8	<49.3	<51.3	<51.0	<55.2
STARS Semivolatiles	Dibenzo(a,h)anthracene	ug/Kg	<33.9	<34.2	<35.6	<35.4	<38.3
STARS Semivolatiles	Benzo(g,h,i)perylene	ug/Kg	<52.4	<52.9	<55.1	<54.7	<59.2
STARS Semivolatiles	Acenaphthylene	ug/Kg	<38.0	<38.3	<39.9	<39.6	<42.9
STARS Volatile Comp	MTBE	ug/Kg	<0.55	<0.55	<0.58	<0.57	<0.62
STARS Volatile Comp	Benzene	ug/Kg	<0.56	<0.56	<0.59	<0.58	<0.63
STARS Volatile Comp	Toluene	ug/Kg	<0.50	<0.51	<0.53	<0.53	<0.57
STARS Volatile Comp	Ethylbenzene	ug/Kg	<0.55	<0.55	<0.58	<0.57	<0.62
STARS Volatile Comp	m,p-xylene	ug/Kg	<0.94	<0.95	<1.00	<0.99	<1.07
STARS Volatile Comp	o-xylene	ug/Kg	<0.41	<0.41	<0.43	<0.43	<0.46
STARS Volatile Comp	Xylenes(Total)	ug/Kg	<0.94	<0.95	<1.00	<0.99	<1.07
STARS Volatile Comp	Isopropylbenzene	ug/Kg	<0.46	<0.47	<0.49	<0.48	<0.52
STARS Volatile Comp	n-Propylbenzene	ug/Kg	<0.48	<0.49	<0.51	<0.51	<0.55
STARS Volatile Comp	1,3,5-Trimethylbenzene	ug/Kg	<0.46	<0.47	<0.49	<0.48	<0.52
STARS Volatile Comp	tert-Butylbenzene	ug/Kg	<0.56	<0.56	<0.59	<0.58	<0.63
STARS Volatile Comp	1,2,4-Trimethylbenzene	ug/Kg	<0.39	<0.39	<0.41	<0.41	<0.44
STARS Volatile Comp	sec-Butylbenzene	ug/Kg	<0.47	<0.48	<0.50	<0.50	<0.54
STARS Volatile Comp	p-Isopropyltoluene	ug/Kg	0.71	<0.50	<0.52	<0.52	<0.56
STARS Volatile Comp	n-Butylbenzene	ug/Kg	<0.50	<0.51	<0.53	<0.53	<0.57
STARS Volatile Comp	Naphthalene	ug/Kg	<0.47	<0.48	<0.50	<0.50	<0.54
% Total Solids SM 254	% Solids	%	94.8	93.9	90.2	90.8	83.9

Environmental Testing Labs, Inc.

04/28/10 Grab T-15 West	04/28/10 Grab T-16 East	04/28/10 Grab 16 Center	04/28/10 Grab T-16 West
<56.8	<56.7	<53.3	<56.0
<39.2	<39.1	<36.8	<38.6
<46.5	<46.5	<43.7	<45.9
<57.9	<57.8	<54.3	<57.0
<37.0	<37.0	<34.7	<36.5
<54.4	<54.3	<51.1	<53.6
<48.8	<48.8	<45.8	<48.1
<59.6	<59.6	<56.0	<58.8
<56.0	<55.9	<52.5	<55.2
<72.6	<72.5	<68.2	<71.6
<51.8	<51.7	<48.6	<51.1
<52.7	<52.7	<49.5	<52.0
<55.1	<55.1	<51.7	<54.3
<38.2	<38.2	<35.9	<37.7
<59.2	<59.1	<55.5	<58.3
<42.9	<42.8	<40.2	<42.3
<0.62	<0.62	<0.58	<0.61
<0.63	<0.63	<0.59	<0.62
<0.57	<0.57	<0.54	<0.56
<0.62	<0.62	<0.58	<0.61
1.09	<1.07	<1.01	<1.05
<0.46	<0.46	<0.44	<0.46
1.09	<1.07	<1.01	<1.05
<0.52	<0.52	<0.49	<0.51
<0.55	<0.55	<0.52	<0.54
<0.52	<0.52	<0.49	<0.51
<0.63	<0.63	<0.59	<0.62
0.99	<0.44	<0.41	<0.43
<0.54	<0.54	<0.50	<0.53
<0.56	<0.56	<0.53	<0.55
<0.57	<0.57	<0.54	<0.56
<0.54	<0.54	<0.50	<0.53
84	84.1	89.5	85.2

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2177	0.55	0.55	ug/Kg	U
71-43-2	Benzene	B3054-2177	0.56	0.56	ug/Kg	U
108-88-3	Toluene	B3054-2177	0.51	0.51	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2177	0.55	0.55	ug/Kg	U
108-38-3	m,p-xylene	B3054-2177	0.95	0.95	ug/Kg	U
95-47-6	o-xylene	B3054-2177	0.41	0.41	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2177	0.95	0.95	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2177	0.49	0.49	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2177	0.56	0.56	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2177	0.39	0.39	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2177	0.48	0.48	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2177	0.50	0.50	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2177	0.51	0.51	ug/Kg	U
91-20-3	Naphthalene	B3054-2177	0.48	0.48	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2177	102.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2177	95.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2177	107.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2177	93.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-3
Client Sample ID: T-14 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2178	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2178	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2178	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2178	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2178	1.00	1.00	ug/Kg	U
95-47-6	o-xylene	B3054-2178	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2178	1.00	1.00	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2178	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2178	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2178	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2178	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2178	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2178	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2178	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2178	107.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2178	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2178	109.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2178	93.5 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-4
Client Sample ID: T-15 East
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 90.8%
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2179	0.57	0.57	ug/Kg	U
71-43-2	Benzene	B3054-2179	0.58	0.58	ug/Kg	U
108-88-3	Toluene	B3054-2179	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2179	0.57	0.57	ug/Kg	U
108-38-3	m,p-xylene	B3054-2179	0.99	0.99	ug/Kg	U
95-47-6	o-xylene	B3054-2179	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2179	0.99	0.99	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2179	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2179	0.58	0.58	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2179	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2179	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2179	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2179	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2179	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2179	110.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2179	94.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2179	114.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2179	95.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-5
Client Sample ID: T-15 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 83.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2180	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2180	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2180	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2180	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2180	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2180	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2180	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2180	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2180	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2180	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2180	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2180	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2180	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2180	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2180	104.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2180	98.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2180	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2180	95.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-6
Client Sample ID: T-15 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2181	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2181	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2181	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2181	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2181	1.07	1.09	ug/Kg	J
95-47-6	o-xylene	B3054-2181	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2181	1.07	1.09	ug/Kg	J
98-82-8	Isopropylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2181	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2181	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2181	0.44	0.99	ug/Kg	J
135-98-8	sec-Butylbenzene	B3054-2181	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2181	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2181	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2181	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2181	105.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2181	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2181	111.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2181	94.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-7
Client Sample ID: T-16 East
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84.1%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2182	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2182	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2182	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2182	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2182	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2182	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2182	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2182	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2182	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2182	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2182	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2182	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2182	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2182	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2182	108.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2182	92.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2182	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2182	94.3 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-8
Client Sample ID: T-16 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 89.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2185	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2185	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2185	0.54	0.54	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2185	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2185	1.01	1.01	ug/Kg	U
95-47-6	o-xylene	B3054-2185	0.44	0.44	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2185	1.01	1.01	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2185	0.52	0.52	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2185	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2185	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2185	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2185	0.53	0.53	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2185	0.54	0.54	ug/Kg	U
91-20-3	Naphthalene	B3054-2185	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2185	86.3 %	(89 - 121)	D
460-00-4	4-BROMOFLUOROBENZENE	B3054-2185	110.0 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2185	81.0 %	(81 - 129)	D
2037-26-5	TOLUENE-D8	B3054-2185	92.2 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-9
Client Sample ID: T-16 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 85.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2184	0.61	0.61	ug/Kg	U
71-43-2	Benzene	B3054-2184	0.62	0.62	ug/Kg	U
108-88-3	Toluene	B3054-2184	0.56	0.56	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2184	0.61	0.61	ug/Kg	U
108-38-3	m,p-xylene	B3054-2184	1.05	1.05	ug/Kg	U
95-47-6	o-xylene	B3054-2184	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2184	1.05	1.05	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2184	0.54	0.54	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2184	0.62	0.62	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2184	0.43	0.43	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2184	0.53	0.53	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2184	0.55	0.55	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2184	0.56	0.56	ug/Kg	U
91-20-3	Naphthalene	B3054-2184	0.53	0.53	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2184	111.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2184	89.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2184	113.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2184	96.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-1
Client Sample ID: T-14 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 94.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4986	50.3	50.3	ug/Kg	U
83-32-9	Acenaphthene	B2656-4986	34.7	34.7	ug/Kg	U
86-73-7	Fluorene	B2656-4986	41.2	41.2	ug/Kg	U
85-01-8	Phenanthrene	B2656-4986	51.3	51.3	ug/Kg	U
120-12-7	Anthracene	B2656-4986	32.8	32.8	ug/Kg	U
206-44-0	Fluoranthene	B2656-4986	48.2	48.2	ug/Kg	U
129-00-0	Pyrene	B2656-4986	43.2	43.2	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4986	52.8	52.8	ug/Kg	U
218-01-9	Chrysene	B2656-4986	49.6	49.6	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4986	64.3	64.3	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4986	45.9	45.9	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4986	46.7	46.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4986	48.8	48.8	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4986	33.9	33.9	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4986	52.4	52.4	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4986	38.0	38.0	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4986	52.8 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4986	46.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4986	66.8 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4987	50.8	50.8	ug/Kg	U
83-32-9	Acenaphthene	B2656-4987	35.0	35.0	ug/Kg	U
86-73-7	Fluorene	B2656-4987	41.6	41.6	ug/Kg	U
85-01-8	Phenanthrene	B2656-4987	51.8	51.8	ug/Kg	U
120-12-7	Anthracene	B2656-4987	33.1	33.1	ug/Kg	U
206-44-0	Fluoranthene	B2656-4987	48.7	48.7	ug/Kg	U
129-00-0	Pyrene	B2656-4987	43.7	43.7	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4987	53.4	53.4	ug/Kg	U
218-01-9	Chrysene	B2656-4987	50.1	50.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4987	65.0	65.0	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4987	46.3	46.3	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4987	47.2	47.2	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4987	49.3	49.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4987	34.2	34.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4987	52.9	52.9	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4987	38.3	38.3	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4987	70.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4987	66.1 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4987	68.6 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-3
Client Sample ID: T-14 West
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 90.2%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4988	52.9	52.9	ug/Kg	U
83-32-9	Acenaphthene	B2656-4988	36.5	36.5	ug/Kg	U
86-73-7	Fluorene	B2656-4988	43.3	43.3	ug/Kg	U
85-01-8	Phenanthrene	B2656-4988	53.9	53.9	ug/Kg	U
120-12-7	Anthracene	B2656-4988	34.5	34.5	ug/Kg	U
206-44-0	Fluoranthene	B2656-4988	50.7	50.7	ug/Kg	U
129-00-0	Pyrene	B2656-4988	45.5	45.5	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4988	55.5	55.5	ug/Kg	U
218-01-9	Chrysene	B2656-4988	52.1	52.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4988	67.6	67.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4988	48.2	48.2	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4988	49.1	49.1	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4988	51.3	51.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4988	35.6	35.6	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4988	55.1	55.1	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4988	39.9	39.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4988	66.9 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4988	63.6 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4988	72.0 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-4
Client Sample ID: T-15 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4989	52.5	52.5	ug/Kg	U
83-32-9	Acenaphthene	B2656-4989	36.2	36.2	ug/Kg	U
86-73-7	Fluorene	B2656-4989	43.1	43.1	ug/Kg	U
85-01-8	Phenanthrene	B2656-4989	53.5	53.5	ug/Kg	U
120-12-7	Anthracene	B2656-4989	34.3	34.3	ug/Kg	U
206-44-0	Fluoranthene	B2656-4989	50.3	50.3	ug/Kg	U
129-00-0	Pyrene	B2656-4989	45.2	45.2	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4989	55.2	55.2	ug/Kg	U
218-01-9	Chrysene	B2656-4989	51.8	51.8	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4989	67.2	67.2	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4989	47.9	47.9	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4989	48.8	48.8	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4989	51.0	51.0	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4989	35.4	35.4	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4989	54.7	54.7	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4989	39.6	39.6	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4989	64.6 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4989	56.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4989	67.1 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-5
Client Sample ID: T-15 Center
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 83.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4990	56.9	56.9	ug/Kg	U
83-32-9	Acenaphthene	B2656-4990	39.2	39.2	ug/Kg	U
86-73-7	Fluorene	B2656-4990	46.6	46.6	ug/Kg	U
85-01-8	Phenanthrene	B2656-4990	57.9	57.9	ug/Kg	U
120-12-7	Anthracene	B2656-4990	37.1	37.1	ug/Kg	U
206-44-0	Fluoranthene	B2656-4990	54.5	54.5	ug/Kg	U
129-00-0	Pyrene	B2656-4990	48.9	48.9	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4990	59.7	59.7	ug/Kg	U
218-01-9	Chrysene	B2656-4990	56.0	56.0	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4990	72.7	72.7	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4990	51.8	51.8	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4990	52.8	52.8	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4990	55.2	55.2	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4990	38.3	38.3	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4990	59.2	59.2	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4990	42.9	42.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4990	73.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4990	65.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4990	76.6 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-6
Client Sample ID: T-15 West
Matrix: Soil Type: Grab
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Collected: 4/28/2010 15:00
% Solid: 84%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4991	56.8	56.8	ug/Kg	U
83-32-9	Acenaphthene	B2656-4991	39.2	39.2	ug/Kg	U
86-73-7	Fluorene	B2656-4991	46.5	46.5	ug/Kg	U
85-01-8	Phenanthrene	B2656-4991	57.9	57.9	ug/Kg	U
120-12-7	Anthracene	B2656-4991	37.0	37.0	ug/Kg	U
206-44-0	Fluoranthene	B2656-4991	54.4	54.4	ug/Kg	U
129-00-0	Pyrene	B2656-4991	48.8	48.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4991	59.6	59.6	ug/Kg	U
218-01-9	Chrysene	B2656-4991	56.0	56.0	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4991	72.6	72.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4991	51.8	51.8	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4991	52.7	52.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4991	55.1	55.1	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4991	38.2	38.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4991	59.2	59.2	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4991	42.9	42.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4991	67.2 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4991	63.4 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4991	70.4 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-7
Client Sample ID: T-16 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84.1%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4992	56.7	56.7	ug/Kg	U
83-32-9	Acenaphthene	B2656-4992	39.1	39.1	ug/Kg	U
86-73-7	Fluorene	B2656-4992	46.5	46.5	ug/Kg	U
85-01-8	Phenanthrene	B2656-4992	57.8	57.8	ug/Kg	U
120-12-7	Anthracene	B2656-4992	37.0	37.0	ug/Kg	U
206-44-0	Fluoranthene	B2656-4992	54.3	54.3	ug/Kg	U
129-00-0	Pyrene	B2656-4992	48.8	48.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4992	59.6	59.6	ug/Kg	U
218-01-9	Chrysene	B2656-4992	55.9	55.9	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4992	72.5	72.5	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4992	51.7	51.7	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4992	52.7	52.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4992	55.1	55.1	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4992	38.2	38.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4992	59.1	59.1	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4992	42.8	42.8	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4992	66.0 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4992	60.7 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4992	74.5 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-8
Client Sample ID: T-16 Center
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 89.5%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4993	53.3	53.3	ug/Kg	U
83-32-9	Acenaphthene	B2656-4993	36.8	36.8	ug/Kg	U
86-73-7	Fluorene	B2656-4993	43.7	43.7	ug/Kg	U
85-01-8	Phenanthrene	B2656-4993	54.3	54.3	ug/Kg	U
120-12-7	Anthracene	B2656-4993	34.7	34.7	ug/Kg	U
206-44-0	Fluoranthene	B2656-4993	51.1	51.1	ug/Kg	U
129-00-0	Pyrene	B2656-4993	45.8	45.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4993	56.0	56.0	ug/Kg	U
218-01-9	Chrysene	B2656-4993	52.5	52.5	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4993	68.2	68.2	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4993	48.6	48.6	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4993	49.5	49.5	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4993	51.7	51.7	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4993	35.9	35.9	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4993	55.5	55.5	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4993	40.2	40.2	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4993	71.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4993	64.9 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4993	75.5 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-9
Client Sample ID: T-16 West
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 85.2%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4994	56.0	56.0	ug/Kg	U
83-32-9	Acenaphthene	B2656-4994	38.6	38.6	ug/Kg	U
86-73-7	Fluorene	B2656-4994	45.9	45.9	ug/Kg	U
85-01-8	Phenanthrene	B2656-4994	57.0	57.0	ug/Kg	U
120-12-7	Anthracene	B2656-4994	36.5	36.5	ug/Kg	U
206-44-0	Fluoranthene	B2656-4994	53.6	53.6	ug/Kg	U
129-00-0	Pyrene	B2656-4994	48.1	48.1	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4994	58.8	58.8	ug/Kg	U
218-01-9	Chrysene	B2656-4994	55.2	55.2	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4994	71.6	71.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4994	51.1	51.1	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4994	52.0	52.0	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4994	54.3	54.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4994	37.7	37.7	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4994	58.3	58.3	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4994	42.3	42.3	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4994	70.8 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4994	62.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4994	77.3 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

CONTAMINATED SOIL

Laboratory Identifier: 1004422
Received: 4/28/2010 16:29
Sampled by: James Woerner

Client: James Woerner Inc
130 Allen Blvd
Farmingdale,
NY 11735

Project: NEWSDAY
235 Pinelawn Road
Melville ,
NY

Manager: James Woerner

Respectfully submitted,

Technical Director

NYS Lab ID # 10969
NJ Cert. # 73812
CT Cert. # PH0645
MA Cert. # NY061
PA Cert. #002

The information contained in this report is confidential and intended only for the use of the client listed above. This report shall not be reproduced, except in full, without the written consent of Environmental Testing Laboratories, Inc. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

BTEX - SW 846 8260B

Sample: 1004422-1
Client Sample ID: T-17
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 16:00
% Solid: 93.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
71-43-2	Benzene	B3054-2175	1.13	1.13	ug/Kg	U
108-88-3	Toluene	B3054-2175	1.03	1.03	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2175	1.11	1.11	ug/Kg	U
1330-20-7	Xylenes	B3054-2175	1.93	**2.13**	ug/Kg	J

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2175	108.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2175	88.6 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2175	107.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2175	90.6 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

TCLP Benzene By SW846 8260

Sample: 1004422-1
Client Sample ID: T-17
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/30/2010
Preparation Date(s) :

Type: Grab

Collected: 4/28/2010 16:00
% Solid: 93.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
71-43-2	Benzene	C3541-2292	0.00043	0.00043	mg/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	C3541-2292	97.8 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	C3541-2292	94.5 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	C3541-2292	99.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	C3541-2292	96.5 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

TPH - Method 8015B

Sample: 1004422-1
Client Sample ID: T-17
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 16:00
% Solid: 93.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
	Diesel Range Organics	C1251-6	12.8	**726**	mg/Kg	

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
460-00-4	4-BROMOFLUOROBENZENE	C1251-6	57.5 %	(30 - 150)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

TCLP Lead by Method SW846 1311/6010

Sample: 1004422-1
Client Sample ID: T-17
Matrix: Soil
Remarks:
Analyzed Date: 4/30/2010
Preparation Date(s) : 4/30/2010

Type: Grab

Collected: 4/28/2010 16:00
% Solid: 93.5%

Analytical Results

Cas No	Analyte	MDL	Concentration	Units	Q
7439-92-1	Lead	0.0019	0.0019	mg/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

Case Narrative

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100, 150 and 200 ppb levels in the initial calibration curve:
Acetone
2-Butanone
4-Methyl-2-pentanone
2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and 300 ppb levels.
Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.
Tert Butyl Alcohol (TBA) was calibrated at 50,200,500,1000 and 1500 ppb levels.

All other compounds were calibrated at 5, 20, 50, 100 and 150 ppb levels.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

Case Narrative

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100,
150 and 200 ppb levels in the initial calibration curve:
Acetone
2-Butanone
4-Methyl-2-pentanone
2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and 300 ppb levels.
Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.
Tert Butyl Alcohol (TBA) was calibrated at 50,200,500,1000 and 1500 ppb levels.

All other compounds were calibrated at 5, 20, 50, 100 and 150 ppb levels.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

CHAIN OF CUSTODY

208 Route 109 Farmingdale, NY 11735
(Tel) 631-249-1456 (Fax) 631-249-8345

10-04422
1004422

Rec'vd Date 04/28/10 16:29

Client Information		Project Information		Analytical Information	Matrix Codes
Company Name	James Woerner Inc.	Project Name	Newsday		
Address	130 Allan Blvd.	Street	235 Pine Lawn Rd.		
City / State / Zip	Farmingdale NY	City / State / Zip	Melville NY		
Project Contact	James Woerner	Project #			
Phone # / Fax #	(631) 454-9330	Sampler's Name	James Woerner		
E-mail		Sampler's Signature			

LAB SAMPLE # (LAB USE ONLY)	Sample ID	Sample Type	Matrix Code	Date	Time	Sample Containers	Sample Type (LAB USE ONLY)
	T-17	G	S	4/27/10	3pm	3	

Analytical Information: ☐ 8260 ☐ 624 ☐ 8021 ☐ 601 ☐ BTEX ☐ MTBE ☐ TBA ☐ NAPH ☐ FCL ☐ STARS ☐ TCLP ☐ 8270 ☐ 625 ☐ FCL STARS ☐ AE ☐ LBN ☐ PAH ☐ TCLP ☐ TIC ☐ 410 ☐ 415 ☐ 625 ☐ 609 ☐ PEST ☐ PCB ☐ HERB ☐ TCLP ☐ VPH ☐ EPH ☐ DRO ☐ GRO ☐ 8100 ☐ NKOS ☐ 1500 ☐ METALS ☐ TOTAL ☐ DIAL ☐ RCRA ☐ TCLP ☐ Mercury ☐ Hardness ☐ Other ☐ 6010 ☐ TCL ☐ TAL ☐ 7000 ☐ TPH ☐ TPH ☐ Other ☐ TCLP ☐ Bac Water (1455)

Turnaround Time (Business Days)	(LAB USE ONLY) TAT Approved By / Date	Data Deliverable Information		Comments / Remarks
☐ Standard 7-10 Business Days		☒ Results Only (Level 1)	☐ CLP Category A (Level 3)	
☐ 5 Day RUSH		☐ Results plus Misc. QC (Level 2)	☐ CLP Category B (Level 4)	
☐ 4 Day RUSH		☐ Results plus Adv. QC (Level 3)	☐ ASP 97 Package (Level 4)	
☐ 3 Day RUSH		☐ MA QC Package (Level MA)	☐ Other _____	
☒ 2 Day RUSH		☐ NJ QC Package (Level NJ)	☐ EDD Format _____	
☐ 1 Day RUSH		(EDD Formats: Excel, pdf, EQUIS, GIS, SKey, SPDES, ASCII, TAGM, DENJ)		

ETL COC Review Check List (LAB USE ONLY)
☐ Task Log In and Initial Review Init: _____ Date/Time _____
☐ Final Review and Approval Init: _____ Date/Time _____
☐ Complete and Invoiced Init: _____ Date/Time _____

Sample custody must be documented below each time samples change possession with a signature, date, and time

Relinquished by Sampler	Date / Time	Received By	Relinquished By	Date / Time	Received By
1	1 4/28/10	1	2	2 4/28/10	2
Relinquished by	Date / Time	Received By	Relinquished By	Date / Time	Received By
3	3	3	4	4	4
Relinquished by	Date / Time	Received By			
5	5	5			

COOLER INFORMATION

ETL Chain of Custody: 1004422			
Project: NEWSDAY			
Address: 235 Pi	Collected Date:		04/28/10
	Sample Type:		Grab
	Sample Name:		T-17
Analysis	**Analyte**	**Units**	
TPH - Method 8015B	Diesel Range Organics	mg/Kg	726
BTEX - SW 846 8260	Benzene	ug/Kg	<1.13
BTEX - SW 846 8260	Toluene	ug/Kg	<1.03
BTEX - SW 846 8260	Ethylbenzene	ug/Kg	<1.11
BTEX - SW 846 8260	Xylenes	ug/Kg	2.13
TCLP Benzene By SW	Benzene	mg/L	<0.00043
TCLP Lead by Method	Lead	mg/L	<0.0019
% Total Solids SM 254	% Solids	%	93.5
	EPA 8260 VOLATILE ANALYSIS:		
	The following compounds were		
	calibrated at 25, 50, 100,		
	150 and 200 ppb levels in the		
	initial calibration curve:		
	Acetone		
	2-Butanone		
	4-Methyl-2-pentanone		
	2-Hexanone		
	M&P-Xylenes and		
	2-Chloroethylvinylether were		
	calibrated at 10, 40, 100, 200		
	and		
	300 ppb levels.		
	Acrolein/Acrylonitrile were		
	calibrated at 50,100,150,200 and		
	250 ppb levels.		
	Tert Butyl Alcohol (TBA) was		
	calibrated at 50,200,500,1000		
	and 1500 ppb levels.		
	All other compounds were		
	calibrated at 5, 20, 50, 100 and		
	150 ppb levels.		
	EPA 8260 VOLATILE ANALYSIS:		
	The following compounds were		
	calibrated at 25, 50, 100,		
	150 and 200 ppb levels in the		
	initial calibration curve:		
	Acetone		
	2-Butanone		
	4-Methyl-2-pentanone		
	2-Hexanone		

M&P-Xylenes and
2-Chloroethylvinylether were
calibrated at 10, 40, 100, 200
and
300 ppb levels.
Acrolein/Acrylonitrile were
calibrated at 50,100,150,200 and
250 ppb levels.
Tert Butyl Alcohol (TBA) was
calibrated at 50,200,500,1000
and 1500 ppb levels.

All other compounds were
calibrated at 5, 20, 50, 100 and
150 ppb levels.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

Laboratory Identifier: 1004421
Received: 4/28/2010 16:18
Sampled by: James Woerner

Client: James Woerner Inc
130 Allen Blvd
Farmingdale,
NY 11735

Project: NEWSDAY
235 Pinelawn Road
Melville ,
NY

Manager: James Woerner

Respectfully submitted,

Technical Director

NYS Lab ID # 10969
NJ Cert. # 73812
CT Cert. # PH0645
MA Cert. # NY061
PA Cert. #002

The information contained in this report is confidential and intended only for the use of the client listed above. This report shall not be reproduced, except in full, without the written consent of Environmental Testing Laboratories, Inc. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-1
Client Sample ID: T-14 East
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 94.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2176	0.55	0.55	ug/Kg	U
71-43-2	Benzene	B3054-2176	0.56	0.56	ug/Kg	U
108-88-3	Toluene	B3054-2176	0.50	0.50	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2176	0.55	0.55	ug/Kg	U
108-38-3	m,p-xylene	B3054-2176	0.94	0.94	ug/Kg	U
95-47-6	o-xylene	B3054-2176	0.41	0.41	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2176	0.94	0.94	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2176	0.46	0.46	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2176	0.48	0.48	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2176	0.46	0.46	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2176	0.56	0.56	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2176	0.39	0.39	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2176	0.47	0.47	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2176	0.49	**0.71**	ug/Kg	J
104-51-8	n-Butylbenzene	B3054-2176	0.50	0.50	ug/Kg	U
91-20-3	Naphthalene	B3054-2176	0.47	0.47	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2176	103.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2176	96.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2176	108.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2176	90.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2177	0.55	0.55	ug/Kg	U
71-43-2	Benzene	B3054-2177	0.56	0.56	ug/Kg	U
108-88-3	Toluene	B3054-2177	0.51	0.51	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2177	0.55	0.55	ug/Kg	U
108-38-3	m,p-xylene	B3054-2177	0.95	0.95	ug/Kg	U
95-47-6	o-xylene	B3054-2177	0.41	0.41	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2177	0.95	0.95	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2177	0.49	0.49	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2177	0.56	0.56	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2177	0.39	0.39	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2177	0.48	0.48	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2177	0.50	0.50	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2177	0.51	0.51	ug/Kg	U
91-20-3	Naphthalene	B3054-2177	0.48	0.48	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2177	102.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2177	95.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2177	107.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2177	93.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-3
Client Sample ID: T-14 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2178	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2178	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2178	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2178	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2178	1.00	1.00	ug/Kg	U
95-47-6	o-xylene	B3054-2178	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2178	1.00	1.00	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2178	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2178	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2178	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2178	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2178	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2178	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2178	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2178	107.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2178	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2178	109.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2178	93.5 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-4
Client Sample ID: T-15 East
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2179	0.57	0.57	ug/Kg	U
71-43-2	Benzene	B3054-2179	0.58	0.58	ug/Kg	U
108-88-3	Toluene	B3054-2179	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2179	0.57	0.57	ug/Kg	U
108-38-3	m,p-xylene	B3054-2179	0.99	0.99	ug/Kg	U
95-47-6	o-xylene	B3054-2179	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2179	0.99	0.99	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2179	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2179	0.58	0.58	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2179	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2179	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2179	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2179	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2179	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2179	110.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2179	94.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2179	114.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2179	95.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-5
Client Sample ID: T-15 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 83.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2180	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2180	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2180	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2180	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2180	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2180	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2180	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2180	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2180	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2180	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2180	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2180	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2180	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2180	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2180	104.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2180	98.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2180	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2180	95.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-6
Client Sample ID: T-15 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2181	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2181	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2181	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2181	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2181	1.07	**1.09**	ug/Kg	J
95-47-6	o-xylene	B3054-2181	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2181	1.07	**1.09**	ug/Kg	J
98-82-8	Isopropylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2181	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2181	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2181	0.44	**0.99**	ug/Kg	J
135-98-8	sec-Butylbenzene	B3054-2181	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2181	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2181	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2181	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2181	105.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2181	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2181	111.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2181	94.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-7
Client Sample ID: T-16 East
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84.1%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2182	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2182	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2182	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2182	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2182	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2182	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2182	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2182	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2182	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2182	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2182	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2182	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2182	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2182	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2182	108.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2182	92.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2182	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2182	94.3 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-8
Client Sample ID: T-16 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 89.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2185	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2185	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2185	0.54	0.54	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2185	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2185	1.01	1.01	ug/Kg	U
95-47-6	o-xylene	B3054-2185	0.44	0.44	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2185	1.01	1.01	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2185	0.52	0.52	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2185	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2185	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2185	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2185	0.53	0.53	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2185	0.54	0.54	ug/Kg	U
91-20-3	Naphthalene	B3054-2185	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2185	86.3 %	(89 - 121)	D
460-00-4	4-BROMOFLUOROBENZENE	B3054-2185	110.0 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2185	81.0 %	(81 - 129)	D
2037-26-5	TOLUENE-D8	B3054-2185	92.2 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-9
Client Sample ID: T-16 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 85.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2184	0.61	0.61	ug/Kg	U
71-43-2	Benzene	B3054-2184	0.62	0.62	ug/Kg	U
108-88-3	Toluene	B3054-2184	0.56	0.56	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2184	0.61	0.61	ug/Kg	U
108-38-3	m,p-xylene	B3054-2184	1.05	1.05	ug/Kg	U
95-47-6	o-xylene	B3054-2184	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2184	1.05	1.05	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2184	0.54	0.54	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2184	0.62	0.62	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2184	0.43	0.43	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2184	0.53	0.53	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2184	0.55	0.55	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2184	0.56	0.56	ug/Kg	U
91-20-3	Naphthalene	B3054-2184	0.53	0.53	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2184	111.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2184	89.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2184	113.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2184	96.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-1
Client Sample ID: T-14 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 94.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4986	50.3	50.3	ug/Kg	U
83-32-9	Acenaphthene	B2656-4986	34.7	34.7	ug/Kg	U
86-73-7	Fluorene	B2656-4986	41.2	41.2	ug/Kg	U
85-01-8	Phenanthrene	B2656-4986	51.3	51.3	ug/Kg	U
120-12-7	Anthracene	B2656-4986	32.8	32.8	ug/Kg	U
206-44-0	Fluoranthene	B2656-4986	48.2	48.2	ug/Kg	U
129-00-0	Pyrene	B2656-4986	43.2	43.2	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4986	52.8	52.8	ug/Kg	U
218-01-9	Chrysene	B2656-4986	49.6	49.6	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4986	64.3	64.3	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4986	45.9	45.9	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4986	46.7	46.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4986	48.8	48.8	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4986	33.9	33.9	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4986	52.4	52.4	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4986	38.0	38.0	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4986	52.8 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4986	46.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4986	66.8 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4987	50.8	50.8	ug/Kg	U
83-32-9	Acenaphthene	B2656-4987	35.0	35.0	ug/Kg	U
86-73-7	Fluorene	B2656-4987	41.6	41.6	ug/Kg	U
85-01-8	Phenanthrene	B2656-4987	51.8	51.8	ug/Kg	U
120-12-7	Anthracene	B2656-4987	33.1	33.1	ug/Kg	U
206-44-0	Fluoranthene	B2656-4987	48.7	48.7	ug/Kg	U
129-00-0	Pyrene	B2656-4987	43.7	43.7	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4987	53.4	53.4	ug/Kg	U
218-01-9	Chrysene	B2656-4987	50.1	50.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4987	65.0	65.0	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4987	46.3	46.3	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4987	47.2	47.2	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4987	49.3	49.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4987	34.2	34.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4987	52.9	52.9	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4987	38.3	38.3	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4987	70.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4987	66.1 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4987	68.6 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

20' & 26'

Laboratory Identifier: 1005075
Received: 5/6/2010 12:55
Sampled by: Justin Halpin

Client: James Woerner Inc
130 Allen Blvd
Farmingdale,
NY 11735

Project: NEWSDAY
235 Pinelawn Road
Melville ,
NY

Manager: James Woerner

Respectfully submitted,

_____
Technical Director

NYS Lab ID # 10969
NJ Cert. # 73812
CT Cert. # PH0645
MA Cert. # NY061
PA Cert. #002

The information contained in this report is confidential and intended only for the use of the client listed above. This report shall not be reproduced, except in full, without the written consent of Environmental Testing Laboratories, Inc. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY.

Environmental Testing Laboratories, Inc.

208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1005075-1
Client Sample ID: T-14 East@ 20'
Matrix: Soil
Type: Grab
Collected: 5/6/2010
% Solid: 94.9%
Remarks: See Case Narrative
Analyzed Date: 5/7/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3061-2307	1.10	1.10	ug/Kg	U
71-43-2	Benzene	B3061-2307	1.12	1.12	ug/Kg	U
108-88-3	Toluene	B3061-2307	1.01	1.01	ug/Kg	U
100-41-4	Ethylbenzene	B3061-2307	1.10	1.10	ug/Kg	U
108-38-3	m,p-xylene	B3061-2307	1.90	1.90	ug/Kg	U
95-47-6	o-xylene	B3061-2307	0.82	0.82	ug/Kg	U
1330-20-7	Xylenes(Total)	B3061-2307	1.90	1.90	ug/Kg	U
98-82-8	Isopropylbenzene	B3061-2307	0.93	0.93	ug/Kg	U
103-65-1	n-Propylbenzene	B3061-2307	0.97	0.97	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3061-2307	0.93	0.93	ug/Kg	U
98-06-6	tert-Butylbenzene	B3061-2307	1.12	1.12	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3061-2307	0.78	0.78	ug/Kg	U
135-98-8	sec-Butylbenzene	B3061-2307	0.95	0.95	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3061-2307	0.99	0.99	ug/Kg	U
104-51-8	n-Butylbenzene	B3061-2307	1.01	1.01	ug/Kg	U
91-20-3	Naphthalene	B3061-2307	0.95	1.34	ug/Kg	J

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3061-2307	112.0 %	(85 - 122)	
460-00-4	4-BROMOFLUOROBENZENE	B3061-2307	89.8 %	(77 - 130)	
4774-33-8	DIBROMOFLUOROMETHANE	B3061-2307	114.0 %	(72 - 129)	
2037-26-5	TOLUENE-D8	B3061-2307	91.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1005075-2
Client Sample ID: T-14 East @ 26'
Matrix: Soil
Type: Grab
Collected: 5/6/2010
% Solid: 96%
Remarks: See Case Narrative
Analyzed Date: 5/7/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3061-2308	1.08	1.08	ug/Kg	U
71-43-2	Benzene	B3061-2308	1.10	1.10	ug/Kg	U
108-88-3	Toluene	B3061-2308	1.00	1.00	ug/Kg	U
100-41-4	Ethylbenzene	B3061-2308	1.08	1.08	ug/Kg	U
108-38-3	m,p-xylene	B3061-2308	1.87	1.87	ug/Kg	U
95-47-6	o-xylene	B3061-2308	0.81	0.81	ug/Kg	U
1330-20-7	Xylenes(Total)	B3061-2308	1.87	1.87	ug/Kg	U
98-82-8	Isopropylbenzene	B3061-2308	0.92	0.92	ug/Kg	U
103-65-1	n-Propylbenzene	B3061-2308	0.96	0.96	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3061-2308	0.92	0.92	ug/Kg	U
98-06-6	tert-Butylbenzene	B3061-2308	1.10	1.10	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3061-2308	0.77	0.77	ug/Kg	U
135-98-8	sec-Butylbenzene	B3061-2308	0.94	0.94	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3061-2308	0.98	0.98	ug/Kg	U
104-51-8	n-Butylbenzene	B3061-2308	1.00	1.00	ug/Kg	U
91-20-3	Naphthalene	B3061-2308	0.94	0.94	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3061-2308	108.0 %	(85 - 122)	
460-00-4	4-BROMOFLUOROBENZENE	B3061-2308	89.2 %	(77 - 130)	
4774-33-8	DIBROMOFLUOROMETHANE	B3061-2308	111.0 %	(72 - 129)	
2037-26-5	TOLUENE-D8	B3061-2308	90.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

STARS Semivolatiles by SW846 8270C

Sample: 1005075-1
Client Sample ID: T-14 East@ 20'
Matrix: Soil
Type: Grab
Collected: 5/6/2010
% Solid: 94.9%
Remarks:
Analyzed Date: 5/7/2010
Preparation Date(s) : 5/7/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	C2429-1251	42.4	42.4	ug/Kg	U
83-32-9	Acenaphthene	C2429-1251	44.4	44.4	ug/Kg	U
86-73-7	Fluorene	C2429-1251	42.4	42.4	ug/Kg	U
85-01-8	Phenanthrene	C2429-1251	47.9	47.9	ug/Kg	U
120-12-7	Anthracene	C2429-1251	46.9	46.9	ug/Kg	U
206-44-0	Fluoranthene	C2429-1251	58.1	58.1	ug/Kg	U
129-00-0	Pyrene	C2429-1251	39.0	**72.9**	ug/Kg	J
56-55-3	Benzo(a)anthracene	C2429-1251	44.6	44.6	ug/Kg	U
218-01-9	Chrysene	C2429-1251	55.7	55.7	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	C2429-1251	43.7	43.7	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	C2429-1251	80.2	80.2	ug/Kg	U
50-32-8	Benzo(a)pyrene	C2429-1251	54.9	54.9	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	C2429-1251	48.7	48.7	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	C2429-1251	58.8	58.8	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	C2429-1251	80.5	80.5	ug/Kg	U
208-96-8	Acenaphthylene	C2429-1251	36.2	36.2	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	C2429-1251	70.6 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	C2429-1251	67.5 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	C2429-1251	77.1 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

STARS Semivolatiles by SW846 8270C

Sample: 1005075-2
Client Sample ID: T-14 East @ 26'
Matrix: Soil
Remarks:
Analyzed Date: 5/7/2010
Preparation Date(s) : 5/7/2010

Type: Grab

Collected: 5/6/2010
% Solid: 96%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	C2429-1252	41.9	41.9	ug/Kg	U
83-32-9	Acenaphthene	C2429-1252	43.9	43.9	ug/Kg	U
86-73-7	Fluorene	C2429-1252	41.9	41.9	ug/Kg	U
85-01-8	Phenanthrene	C2429-1252	47.4	47.4	ug/Kg	U
120-12-7	Anthracene	C2429-1252	46.4	46.4	ug/Kg	U
206-44-0	Fluoranthene	C2429-1252	57.4	57.4	ug/Kg	U
129-00-0	Pyrene	C2429-1252	38.5	**325**	ug/Kg	J
56-55-3	Benzo(a)anthracene	C2429-1252	44.1	44.1	ug/Kg	U
218-01-9	Chrysene	C2429-1252	55.1	55.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	C2429-1252	43.2	43.2	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	C2429-1252	79.3	79.3	ug/Kg	U
50-32-8	Benzo(a)pyrene	C2429-1252	54.3	54.3	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	C2429-1252	48.1	48.1	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	C2429-1252	58.1	58.1	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	C2429-1252	79.6	79.6	ug/Kg	U
208-96-8	Acenaphthylene	C2429-1252	35.8	35.8	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	C2429-1252	58.7 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	C2429-1252	57.0 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	C2429-1252	70.1 %	(18 - 137)	

BRD

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

Case Narrative

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100, 150 and 200 ppb levels in the initial calibration curve:
Acetone
2-Butanone
4-Methyl-2-pentanone
2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and 300 ppb levels.
Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.
Tert Butyl Alcohol (TBA) was calibrated at 50,200,500,1000 and 1500 ppb levels.

All other compounds were calibrated at 5, 20, 50, 100 and 150 ppb levels.

1005075-1 and -2 were analyzed at 1:2 dilutions. Results indicate high concentrations of non-target compounds present in the samples (mainly hydrocarbons).

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/7/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

ETL Chain of Custody: 1005075				
Project: NEWSDAY				
Address: 235 Pi	Collected Date:		05/06/10	05/06/10
	Sample Type:		Grab	Grab
	Sample Name:		T-14 East@ 20'	East @ 26'
Analysis	**Analyte**	**Units**		
STARS Semivolatiles I	Naphthalene	ug/Kg	<42.4	<41.9
STARS Semivolatiles I	Acenaphthene	ug/Kg	<44.4	<43.9
STARS Semivolatiles I	Fluorene	ug/Kg	<42.4	<41.9
STARS Semivolatiles I	Phenanthrene	ug/Kg	<47.9	<47.4
STARS Semivolatiles I	Anthracene	ug/Kg	<46.9	<46.4
STARS Semivolatiles I	Fluoranthene	ug/Kg	<58.1	<57.4
STARS Semivolatiles I	Pyrene	ug/Kg	72.9	325
STARS Semivolatiles I	Benzo(a)anthracene	ug/Kg	<44.6	<44.1
STARS Semivolatiles I	Chrysene	ug/Kg	<55.7	<55.1
STARS Semivolatiles I	Benzo(b)fluoranthene	ug/Kg	<43.7	<43.2
STARS Semivolatiles I	Benzo(k)fluoranthene	ug/Kg	<80.2	<79.3
STARS Semivolatiles I	Benzo(a)pyrene	ug/Kg	<54.9	<54.3
STARS Semivolatiles I	Indeno(1,2,3-cd)pyrene	ug/Kg	<48.7	<48.1
STARS Semivolatiles I	Dibenzo(a,h)anthracene	ug/Kg	<58.8	<58.1
STARS Semivolatiles I	Benzo(g,h,i)perylene	ug/Kg	<80.5	<79.6
STARS Semivolatiles I	Acenaphthylene	ug/Kg	<36.2	<35.8
STARS Volatile Comp	MTBE	ug/Kg	<1.10	<1.08
STARS Volatile Comp	Benzene	ug/Kg	<1.12	<1.10
STARS Volatile Comp	Toluene	ug/Kg	<1.01	<1.00
STARS Volatile Comp	Ethylbenzene	ug/Kg	<1.10	<1.08
STARS Volatile Comp	m,p-xylene	ug/Kg	<1.90	<1.87
STARS Volatile Comp	o-xylene	ug/Kg	<0.82	<0.81
STARS Volatile Comp	Xylenes(Total)	ug/Kg	<1.90	<1.87
STARS Volatile Comp	Isopropylbenzene	ug/Kg	<0.93	<0.92
STARS Volatile Comp	n-Propylbenzene	ug/Kg	<0.97	<0.96
STARS Volatile Comp	1,3,5-Trimethylbenzene	ug/Kg	<0.93	<0.92
STARS Volatile Comp	tert-Butylbenzene	ug/Kg	<1.12	<1.10
STARS Volatile Comp	1,2,4-Trimethylbenzene	ug/Kg	<0.78	<0.77
STARS Volatile Comp	sec-Butylbenzene	ug/Kg	<0.95	<0.94
STARS Volatile Comp	p-Isopropyltoluene	ug/Kg	<0.99	<0.98
STARS Volatile Comp	n-Butylbenzene	ug/Kg	<1.01	<1.00
STARS Volatile Comp	Naphthalene	ug/Kg	1.34	<0.94
% Total Solids SM 25	% Solids	%	94.9	96

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100, 150 and 200 ppb levels in the initial calibration curve:

Acetone

2-Butanone

4-Methyl-2-pentanone

2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and

	300 ppb levels.	
	Acrolein/Acrylonitrile were	
	calibrated at 50,100,150,200 and	
	250 ppb levels.	
	Tert Butyl Alcohol (TBA) was	
	calibrated at 50,200,500,1000	
	and 1500 ppb levels.	
	All other compounds were	
	calibrated at 5, 20, 50, 100 and	
	150 ppb levels.	
	1005075-1 and -2 were analyzed	
	at 1:2 dilutions. Results	
	indicate high concentrations of	
	non-target compounds present in	
	the samples (mainly	
	hydrocarbons).	

Environmental Testing Labs, Inc.

ETL Chain of Custody: 1004421							
Project: NEWSDAY							
Address: 235 Pi	Collected Date:		04/28/10	04/28/10	04/28/10	04/28/10	04/28/10
	Sample Type:		Grab	Grab	Grab	Grab	Grab
	Sample Name:		T-14 East	14 Center	T-14 West	T-15 East	15 Center
Analysis	**Analyte**	**Units**					
STARS Semivolatiles	Naphthalene	ug/Kg	<50.3	<50.8	<52.9	<52.5	<56.9
STARS Semivolatiles	Acenaphthene	ug/Kg	<34.7	<35.0	<36.5	<36.2	<39.2
STARS Semivolatiles	Fluorene	ug/Kg	<41.2	<41.6	<43.3	<43.1	<46.6
STARS Semivolatiles	Phenanthrene	ug/Kg	<51.3	<51.8	<53.9	<53.5	<57.9
STARS Semivolatiles	Anthracene	ug/Kg	<32.8	<33.1	<34.5	<34.3	<37.1
STARS Semivolatiles	Fluoranthene	ug/Kg	<48.2	<48.7	<50.7	<50.3	<54.5
STARS Semivolatiles	Pyrene	ug/Kg	<43.2	<43.7	<45.5	<45.2	<48.9
STARS Semivolatiles	Benzo(a)anthracene	ug/Kg	<52.8	<53.4	<55.5	<55.2	<59.7
STARS Semivolatiles	Chrysene	ug/Kg	<49.6	<50.1	<52.1	<51.8	<56.0
STARS Semivolatiles	Benzo(b)fluoranthene	ug/Kg	<64.3	<65.0	<67.6	<67.2	<72.7
STARS Semivolatiles	Benzo(k)fluoranthene	ug/Kg	<45.9	<46.3	<48.2	<47.9	<51.8
STARS Semivolatiles	Benzo(a)pyrene	ug/Kg	<46.7	<47.2	<49.1	<48.8	<52.8
STARS Semivolatiles	Indeno(1,2,3-cd)pyrene	ug/Kg	<48.8	<49.3	<51.3	<51.0	<55.2
STARS Semivolatiles	Dibenzo(a,h)anthracene	ug/Kg	<33.9	<34.2	<35.6	<35.4	<38.3
STARS Semivolatiles	Benzo(g,h,i)perylene	ug/Kg	<52.4	<52.9	<55.1	<54.7	<59.2
STARS Semivolatiles	Acenaphthylene	ug/Kg	<38.0	<38.3	<39.9	<39.6	<42.9
STARS Volatile Comp	MTBE	ug/Kg	<0.55	<0.55	<0.58	<0.57	<0.62
STARS Volatile Comp	Benzene	ug/Kg	<0.56	<0.56	<0.59	<0.58	<0.63
STARS Volatile Comp	Toluene	ug/Kg	<0.50	<0.51	<0.53	<0.53	<0.57
STARS Volatile Comp	Ethylbenzene	ug/Kg	<0.55	<0.55	<0.58	<0.57	<0.62
STARS Volatile Comp	m,p-xylene	ug/Kg	<0.94	<0.95	<1.00	<0.99	<1.07
STARS Volatile Comp	o-xylene	ug/Kg	<0.41	<0.41	<0.43	<0.43	<0.46
STARS Volatile Comp	Xylenes(Total)	ug/Kg	<0.94	<0.95	<1.00	<0.99	<1.07
STARS Volatile Comp	Isopropylbenzene	ug/Kg	<0.46	<0.47	<0.49	<0.48	<0.52
STARS Volatile Comp	n-Propylbenzene	ug/Kg	<0.48	<0.49	<0.51	<0.51	<0.55
STARS Volatile Comp	1,3,5-Trimethylbenzene	ug/Kg	<0.46	<0.47	<0.49	<0.48	<0.52
STARS Volatile Comp	tert-Butylbenzene	ug/Kg	<0.56	<0.56	<0.59	<0.58	<0.63
STARS Volatile Comp	1,2,4-Trimethylbenzene	ug/Kg	<0.39	<0.39	<0.41	<0.41	<0.44
STARS Volatile Comp	sec-Butylbenzene	ug/Kg	<0.47	<0.48	<0.50	<0.50	<0.54
STARS Volatile Comp	p-Isopropyltoluene	ug/Kg	0.71	<0.50	<0.52	<0.52	<0.56
STARS Volatile Comp	n-Butylbenzene	ug/Kg	<0.50	<0.51	<0.53	<0.53	<0.57
STARS Volatile Comp	Naphthalene	ug/Kg	<0.47	<0.48	<0.50	<0.50	<0.54
% Total Solids SM 254	% Solids	%	94.8	93.9	90.2	90.8	83.9

Environmental Testing Labs, Inc.

04/28/10 Grab T-15 West	04/28/10 Grab T-16 East	04/28/10 Grab 16 Center	04/28/10 Grab T-16 West
<56.8	<56.7	<53.3	<56.0
<39.2	<39.1	<36.8	<38.6
<46.5	<46.5	<43.7	<45.9
<57.9	<57.8	<54.3	<57.0
<37.0	<37.0	<34.7	<36.5
<54.4	<54.3	<51.1	<53.6
<48.8	<48.8	<45.8	<48.1
<59.6	<59.6	<56.0	<58.8
<56.0	<55.9	<52.5	<55.2
<72.6	<72.5	<68.2	<71.6
<51.8	<51.7	<48.6	<51.1
<52.7	<52.7	<49.5	<52.0
<55.1	<55.1	<51.7	<54.3
<38.2	<38.2	<35.9	<37.7
<59.2	<59.1	<55.5	<58.3
<42.9	<42.8	<40.2	<42.3
<0.62	<0.62	<0.58	<0.61
<0.63	<0.63	<0.59	<0.62
<0.57	<0.57	<0.54	<0.56
<0.62	<0.62	<0.58	<0.61
1.09	<1.07	<1.01	<1.05
<0.46	<0.46	<0.44	<0.46
1.09	<1.07	<1.01	<1.05
<0.52	<0.52	<0.49	<0.51
<0.55	<0.55	<0.52	<0.54
<0.52	<0.52	<0.49	<0.51
<0.63	<0.63	<0.59	<0.62
0.99	<0.44	<0.41	<0.43
<0.54	<0.54	<0.50	<0.53
<0.56	<0.56	<0.53	<0.55
<0.57	<0.57	<0.54	<0.56
<0.54	<0.54	<0.50	<0.53
84	84.1	89.5	85.2

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2177	0.55	0.55	ug/Kg	U
71-43-2	Benzene	B3054-2177	0.56	0.56	ug/Kg	U
108-88-3	Toluene	B3054-2177	0.51	0.51	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2177	0.55	0.55	ug/Kg	U
108-38-3	m,p-xylene	B3054-2177	0.95	0.95	ug/Kg	U
95-47-6	o-xylene	B3054-2177	0.41	0.41	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2177	0.95	0.95	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2177	0.49	0.49	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2177	0.47	0.47	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2177	0.56	0.56	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2177	0.39	0.39	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2177	0.48	0.48	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2177	0.50	0.50	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2177	0.51	0.51	ug/Kg	U
91-20-3	Naphthalene	B3054-2177	0.48	0.48	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2177	102.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2177	95.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2177	107.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2177	93.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-3
Client Sample ID: T-14 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2178	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2178	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2178	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2178	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2178	1.00	1.00	ug/Kg	U
95-47-6	o-xylene	B3054-2178	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2178	1.00	1.00	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2178	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2178	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2178	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2178	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2178	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2178	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2178	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2178	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2178	107.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2178	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2178	109.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2178	93.5 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-4
Client Sample ID: T-15 East
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 90.8%
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2179	0.57	0.57	ug/Kg	U
71-43-2	Benzene	B3054-2179	0.58	0.58	ug/Kg	U
108-88-3	Toluene	B3054-2179	0.53	0.53	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2179	0.57	0.57	ug/Kg	U
108-38-3	m,p-xylene	B3054-2179	0.99	0.99	ug/Kg	U
95-47-6	o-xylene	B3054-2179	0.43	0.43	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2179	0.99	0.99	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2179	0.51	0.51	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2179	0.48	0.48	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2179	0.58	0.58	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2179	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2179	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2179	0.52	0.52	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2179	0.53	0.53	ug/Kg	U
91-20-3	Naphthalene	B3054-2179	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2179	110.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2179	94.9 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2179	114.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2179	95.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-5
Client Sample ID: T-15 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 83.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2180	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2180	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2180	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2180	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2180	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2180	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2180	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2180	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2180	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2180	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2180	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2180	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2180	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2180	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2180	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2180	104.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2180	98.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2180	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2180	95.0 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-6
Client Sample ID: T-15 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2181	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2181	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2181	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2181	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2181	1.07	1.09	ug/Kg	J
95-47-6	o-xylene	B3054-2181	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2181	1.07	1.09	ug/Kg	J
98-82-8	Isopropylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2181	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2181	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2181	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2181	0.44	0.99	ug/Kg	J
135-98-8	sec-Butylbenzene	B3054-2181	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2181	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2181	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2181	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2181	105.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2181	94.3 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2181	111.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2181	94.1 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-7
Client Sample ID: T-16 East
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84.1%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2182	0.62	0.62	ug/Kg	U
71-43-2	Benzene	B3054-2182	0.63	0.63	ug/Kg	U
108-88-3	Toluene	B3054-2182	0.57	0.57	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2182	0.62	0.62	ug/Kg	U
108-38-3	m,p-xylene	B3054-2182	1.07	1.07	ug/Kg	U
95-47-6	o-xylene	B3054-2182	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2182	1.07	1.07	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2182	0.55	0.55	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2182	0.52	0.52	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2182	0.63	0.63	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2182	0.44	0.44	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2182	0.54	0.54	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2182	0.56	0.56	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2182	0.57	0.57	ug/Kg	U
91-20-3	Naphthalene	B3054-2182	0.54	0.54	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2182	108.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2182	92.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2182	110.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2182	94.3 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-8
Client Sample ID: T-16 Center
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 89.5%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2185	0.58	0.58	ug/Kg	U
71-43-2	Benzene	B3054-2185	0.59	0.59	ug/Kg	U
108-88-3	Toluene	B3054-2185	0.54	0.54	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2185	0.58	0.58	ug/Kg	U
108-38-3	m,p-xylene	B3054-2185	1.01	1.01	ug/Kg	U
95-47-6	o-xylene	B3054-2185	0.44	0.44	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2185	1.01	1.01	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2185	0.52	0.52	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2185	0.49	0.49	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2185	0.59	0.59	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2185	0.41	0.41	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2185	0.50	0.50	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2185	0.53	0.53	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2185	0.54	0.54	ug/Kg	U
91-20-3	Naphthalene	B3054-2185	0.50	0.50	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2185	86.3 %	(89 - 121)	D
460-00-4	4-BROMOFLUOROBENZENE	B3054-2185	110.0 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2185	81.0 %	(81 - 129)	D
2037-26-5	TOLUENE-D8	B3054-2185	92.2 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Volatile Compounds by SW 846 8260

Sample: 1004421-9
Client Sample ID: T-16 West
Matrix: Soil
Remarks: See Case Narrative
Analyzed Date: 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 85.2%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
1634-04-4	MTBE	B3054-2184	0.61	0.61	ug/Kg	U
71-43-2	Benzene	B3054-2184	0.62	0.62	ug/Kg	U
108-88-3	Toluene	B3054-2184	0.56	0.56	ug/Kg	U
100-41-4	Ethylbenzene	B3054-2184	0.61	0.61	ug/Kg	U
108-38-3	m,p-xylene	B3054-2184	1.05	1.05	ug/Kg	U
95-47-6	o-xylene	B3054-2184	0.46	0.46	ug/Kg	U
1330-20-7	Xylenes(Total)	B3054-2184	1.05	1.05	ug/Kg	U
98-82-8	Isopropylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
103-65-1	n-Propylbenzene	B3054-2184	0.54	0.54	ug/Kg	U
108-67-8	1,3,5-Trimethylbenzene	B3054-2184	0.51	0.51	ug/Kg	U
98-06-6	tert-Butylbenzene	B3054-2184	0.62	0.62	ug/Kg	U
95-63-6	1,2,4-Trimethylbenzene	B3054-2184	0.43	0.43	ug/Kg	U
135-98-8	sec-Butylbenzene	B3054-2184	0.53	0.53	ug/Kg	U
99-87-6	p-Isopropyltoluene	B3054-2184	0.55	0.55	ug/Kg	U
104-51-8	n-Butylbenzene	B3054-2184	0.56	0.56	ug/Kg	U
91-20-3	Naphthalene	B3054-2184	0.53	0.53	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	B3054-2184	111.0 %	(89 - 121)	
460-00-4	4-BROMOFLUOROBENZENE	B3054-2184	89.4 %	(77 - 114)	
4774-33-8	DIBROMOFLUOROMETHANE	B3054-2184	113.0 %	(81 - 129)	
2037-26-5	TOLUENE-D8	B3054-2184	96.8 %	(86 - 110)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-1
Client Sample ID: T-14 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 94.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4986	50.3	50.3	ug/Kg	U
83-32-9	Acenaphthene	B2656-4986	34.7	34.7	ug/Kg	U
86-73-7	Fluorene	B2656-4986	41.2	41.2	ug/Kg	U
85-01-8	Phenanthrene	B2656-4986	51.3	51.3	ug/Kg	U
120-12-7	Anthracene	B2656-4986	32.8	32.8	ug/Kg	U
206-44-0	Fluoranthene	B2656-4986	48.2	48.2	ug/Kg	U
129-00-0	Pyrene	B2656-4986	43.2	43.2	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4986	52.8	52.8	ug/Kg	U
218-01-9	Chrysene	B2656-4986	49.6	49.6	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4986	64.3	64.3	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4986	45.9	45.9	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4986	46.7	46.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4986	48.8	48.8	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4986	33.9	33.9	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4986	52.4	52.4	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4986	38.0	38.0	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4986	52.8 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4986	46.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4986	66.8 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-2
Client Sample ID: T-14 Center
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 93.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4987	50.8	50.8	ug/Kg	U
83-32-9	Acenaphthene	B2656-4987	35.0	35.0	ug/Kg	U
86-73-7	Fluorene	B2656-4987	41.6	41.6	ug/Kg	U
85-01-8	Phenanthrene	B2656-4987	51.8	51.8	ug/Kg	U
120-12-7	Anthracene	B2656-4987	33.1	33.1	ug/Kg	U
206-44-0	Fluoranthene	B2656-4987	48.7	48.7	ug/Kg	U
129-00-0	Pyrene	B2656-4987	43.7	43.7	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4987	53.4	53.4	ug/Kg	U
218-01-9	Chrysene	B2656-4987	50.1	50.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4987	65.0	65.0	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4987	46.3	46.3	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4987	47.2	47.2	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4987	49.3	49.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4987	34.2	34.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4987	52.9	52.9	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4987	38.3	38.3	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4987	70.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4987	66.1 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4987	68.6 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-3
Client Sample ID: T-14 West
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 90.2%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4988	52.9	52.9	ug/Kg	U
83-32-9	Acenaphthene	B2656-4988	36.5	36.5	ug/Kg	U
86-73-7	Fluorene	B2656-4988	43.3	43.3	ug/Kg	U
85-01-8	Phenanthrene	B2656-4988	53.9	53.9	ug/Kg	U
120-12-7	Anthracene	B2656-4988	34.5	34.5	ug/Kg	U
206-44-0	Fluoranthene	B2656-4988	50.7	50.7	ug/Kg	U
129-00-0	Pyrene	B2656-4988	45.5	45.5	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4988	55.5	55.5	ug/Kg	U
218-01-9	Chrysene	B2656-4988	52.1	52.1	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4988	67.6	67.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4988	48.2	48.2	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4988	49.1	49.1	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4988	51.3	51.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4988	35.6	35.6	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4988	55.1	55.1	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4988	39.9	39.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4988	66.9 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4988	63.6 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4988	72.0 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-4
Client Sample ID: T-15 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 90.8%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4989	52.5	52.5	ug/Kg	U
83-32-9	Acenaphthene	B2656-4989	36.2	36.2	ug/Kg	U
86-73-7	Fluorene	B2656-4989	43.1	43.1	ug/Kg	U
85-01-8	Phenanthrene	B2656-4989	53.5	53.5	ug/Kg	U
120-12-7	Anthracene	B2656-4989	34.3	34.3	ug/Kg	U
206-44-0	Fluoranthene	B2656-4989	50.3	50.3	ug/Kg	U
129-00-0	Pyrene	B2656-4989	45.2	45.2	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4989	55.2	55.2	ug/Kg	U
218-01-9	Chrysene	B2656-4989	51.8	51.8	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4989	67.2	67.2	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4989	47.9	47.9	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4989	48.8	48.8	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4989	51.0	51.0	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4989	35.4	35.4	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4989	54.7	54.7	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4989	39.6	39.6	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4989	64.6 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4989	56.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4989	67.1 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-5
Client Sample ID: T-15 Center
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 83.9%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4990	56.9	56.9	ug/Kg	U
83-32-9	Acenaphthene	B2656-4990	39.2	39.2	ug/Kg	U
86-73-7	Fluorene	B2656-4990	46.6	46.6	ug/Kg	U
85-01-8	Phenanthrene	B2656-4990	57.9	57.9	ug/Kg	U
120-12-7	Anthracene	B2656-4990	37.1	37.1	ug/Kg	U
206-44-0	Fluoranthene	B2656-4990	54.5	54.5	ug/Kg	U
129-00-0	Pyrene	B2656-4990	48.9	48.9	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4990	59.7	59.7	ug/Kg	U
218-01-9	Chrysene	B2656-4990	56.0	56.0	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4990	72.7	72.7	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4990	51.8	51.8	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4990	52.8	52.8	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4990	55.2	55.2	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4990	38.3	38.3	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4990	59.2	59.2	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4990	42.9	42.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4990	73.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4990	65.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4990	76.6 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-6
Client Sample ID: T-15 West
Matrix: Soil Type: Grab
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Collected: 4/28/2010 15:00
% Solid: 84%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4991	56.8	56.8	ug/Kg	U
83-32-9	Acenaphthene	B2656-4991	39.2	39.2	ug/Kg	U
86-73-7	Fluorene	B2656-4991	46.5	46.5	ug/Kg	U
85-01-8	Phenanthrene	B2656-4991	57.9	57.9	ug/Kg	U
120-12-7	Anthracene	B2656-4991	37.0	37.0	ug/Kg	U
206-44-0	Fluoranthene	B2656-4991	54.4	54.4	ug/Kg	U
129-00-0	Pyrene	B2656-4991	48.8	48.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4991	59.6	59.6	ug/Kg	U
218-01-9	Chrysene	B2656-4991	56.0	56.0	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4991	72.6	72.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4991	51.8	51.8	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4991	52.7	52.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4991	55.1	55.1	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4991	38.2	38.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4991	59.2	59.2	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4991	42.9	42.9	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4991	67.2 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4991	63.4 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4991	70.4 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-7
Client Sample ID: T-16 East
Matrix: Soil
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Type: Grab

Collected: 4/28/2010 15:00
% Solid: 84.1%

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4992	56.7	56.7	ug/Kg	U
83-32-9	Acenaphthene	B2656-4992	39.1	39.1	ug/Kg	U
86-73-7	Fluorene	B2656-4992	46.5	46.5	ug/Kg	U
85-01-8	Phenanthrene	B2656-4992	57.8	57.8	ug/Kg	U
120-12-7	Anthracene	B2656-4992	37.0	37.0	ug/Kg	U
206-44-0	Fluoranthene	B2656-4992	54.3	54.3	ug/Kg	U
129-00-0	Pyrene	B2656-4992	48.8	48.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4992	59.6	59.6	ug/Kg	U
218-01-9	Chrysene	B2656-4992	55.9	55.9	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4992	72.5	72.5	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4992	51.7	51.7	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4992	52.7	52.7	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4992	55.1	55.1	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4992	38.2	38.2	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4992	59.1	59.1	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4992	42.8	42.8	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4992	66.0 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4992	60.7 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4992	74.5 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-8
Client Sample ID: T-16 Center
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 89.5%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4993	53.3	53.3	ug/Kg	U
83-32-9	Acenaphthene	B2656-4993	36.8	36.8	ug/Kg	U
86-73-7	Fluorene	B2656-4993	43.7	43.7	ug/Kg	U
85-01-8	Phenanthrene	B2656-4993	54.3	54.3	ug/Kg	U
120-12-7	Anthracene	B2656-4993	34.7	34.7	ug/Kg	U
206-44-0	Fluoranthene	B2656-4993	51.1	51.1	ug/Kg	U
129-00-0	Pyrene	B2656-4993	45.8	45.8	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4993	56.0	56.0	ug/Kg	U
218-01-9	Chrysene	B2656-4993	52.5	52.5	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4993	68.2	68.2	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4993	48.6	48.6	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4993	49.5	49.5	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4993	51.7	51.7	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4993	35.9	35.9	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4993	55.5	55.5	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4993	40.2	40.2	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4993	71.1 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4993	64.9 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4993	75.5 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

STARS Semivolatiles by SW846 8270C

Sample: 1004421-9
Client Sample ID: T-16 West
Matrix: Soil
Type: Grab
Collected: 4/28/2010 15:00
% Solid: 85.2%
Remarks:
Analyzed Date: 4/29/2010
Preparation Date(s) : 4/29/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration*	Units	Q
91-20-3	Naphthalene	B2656-4994	56.0	56.0	ug/Kg	U
83-32-9	Acenaphthene	B2656-4994	38.6	38.6	ug/Kg	U
86-73-7	Fluorene	B2656-4994	45.9	45.9	ug/Kg	U
85-01-8	Phenanthrene	B2656-4994	57.0	57.0	ug/Kg	U
120-12-7	Anthracene	B2656-4994	36.5	36.5	ug/Kg	U
206-44-0	Fluoranthene	B2656-4994	53.6	53.6	ug/Kg	U
129-00-0	Pyrene	B2656-4994	48.1	48.1	ug/Kg	U
56-55-3	Benzo(a)anthracene	B2656-4994	58.8	58.8	ug/Kg	U
218-01-9	Chrysene	B2656-4994	55.2	55.2	ug/Kg	U
205-99-2	Benzo(b)fluoranthene	B2656-4994	71.6	71.6	ug/Kg	U
207-08-9	Benzo(k)fluoranthene	B2656-4994	51.1	51.1	ug/Kg	U
50-32-8	Benzo(a)pyrene	B2656-4994	52.0	52.0	ug/Kg	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2656-4994	54.3	54.3	ug/Kg	U
53-70-3	Dibenzo(a,h)anthracene	B2656-4994	37.7	37.7	ug/Kg	U
191-24-2	Benzo(g,h,i)perylene	B2656-4994	58.3	58.3	ug/Kg	U
208-96-8	Acenaphthylene	B2656-4994	42.3	42.3	ug/Kg	U

* Results are reported on a dry weight basis

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
321-60-8	2-FLUOROBIPHENYL	B2656-4994	70.8 %	(30 - 115)	
4165-60-0	NITROBENZENE-D5	B2656-4994	62.8 %	(23 - 120)	
1718-51-0	TERPHENYL-D14	B2656-4994	77.3 %	(18 - 137)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

4/30/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Laboratory Identifier: 1005123
Received: 5/10/2010 13:06
Sampled by: Jim Woerner

WATER SAMPLING
5/10/10 ANALYSIS

Client: James Woerner Inc
130 Allen Blvd
Farmingdale,
NY 11735

Project: NEWSDAY
235 Pinelawn Road
Melville ,
NY

Manager: James Woerner

Respectfully submitted,

Technical Director

NYS Lab ID # 10969
NJ Cert. # 73812
CT Cert. # PH0645
MA Cert. # NY061
PA Cert. #002

The information contained in this report is confidential and intended only for the use of the client listed above. This report shall not be reproduced, except in full, without the written consent of Environmental Testing Laboratories, Inc. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9000	2.32	2.32	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9000	1.80	1.80	ug/L	U
67-66-3	Chloroform	A3383-9000	1.94	1.94	ug/L	U
71-43-2	Benzene	A3383-9000	1.76	1.76	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9000	1.90	1.90	ug/L	U
74-83-9	Bromomethane	A3383-9000	2.04	2.04	ug/L	U
74-87-3	Chloromethane	A3383-9000	1.58	1.58	ug/L	U
74-95-3	Dibromomethane	A3383-9000	1.82	1.82	ug/L	U
74-97-5	Bromochloromethane	A3383-9000	1.82	1.82	ug/L	U
75-00-3	Chloroethane	A3383-9000	2.88	2.88	ug/L	U
75-01-4	Vinyl Chloride	A3383-9000	1.64	1.64	ug/L	U
75-09-2	Methylene Chloride	A3383-9000	2.16	2.16	ug/L	U
75-15-0	Carbon disulfide	A3383-9000	1.64	1.64	ug/L	U
75-25-2	Bromoform	A3383-9000	1.62	1.62	ug/L	U
75-27-4	Bromodichloromethane	A3383-9000	1.78	1.78	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9000	2.02	2.02	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9000	1.86	1.86	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9000	1.86	1.86	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9000	16.2	16.2	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9000	2.00	2.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9000	1.60	1.60	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9000	1.76	1.76	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9000	1.78	1.78	ug/L	U
78-93-3	2-Butanone	A3383-9000	1.52	1.52	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9000	1.80	1.80	ug/L	U
79-01-6	Trichloroethene	A3383-9000	1.88	1.88	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9000	1.50	1.50	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9000	1.24	1.24	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9000	1.58	1.58	ug/L	U
91-20-3	Naphthalene	A3383-9000	1.22	1.22	ug/L	U
95-47-6	o-xylene	A3383-9000	1.70	1.70	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9000	1.66	1.66	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9000	1.60	1.60	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9000	1.68	1.68	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9000	1.56	1.56	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9000	1.50	1.50	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9000	1.56	1.56	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9000	1.70	1.70	ug/L	U
98-82-8	Isopropylbenzene	A3383-9000	1.72	1.72	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9000	1.62	1.62	ug/L	U
100-41-4	Ethylbenzene	A3383-9000	1.78	1.78	ug/L	U
100-42-5	Styrene	A3383-9000	1.62	1.62	ug/L	U
103-65-1	n-Propylbenzene	A3383-9000	1.62	1.62	ug/L	U
104-51-8	n-Butylbenzene	A3383-9000	1.66	1.66	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9000	1.54	1.54	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9000	1.56	1.56	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9000	1.56	1.56	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9000	1.56	1.56	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9000	1.94	1.94	ug/L	U
107-13-1	Acrylonitrile	A3383-9000	7.56	7.56	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9000	1.72	1.72	ug/L	U
108-38-3	m,p-xylene	A3383-9000	3.48	3.48	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9000	1.64	1.64	ug/L	U
108-86-1	Bromobenzene	A3383-9000	1.60	1.60	ug/L	U
108-88-3	Toluene	A3383-9000	2.16	2.16	ug/L	U
108-90-7	Chlorobenzene	A3383-9000	1.72	1.72	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9000	2.84	2.84	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9000	1.34	1.34	ug/L	U
124-48-1	Dibromochloromethane	A3383-9000	1.66	1.66	ug/L	U
127-18-4	Tetrachloroethene	A3383-9000	1.68	1.68	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9000	1.56	1.56	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9000	1.66	1.66	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9000	1.78	1.78	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9000	1.90	1.90	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9000	1.54	1.54	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9000	1.60	1.60	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9000	1.74	1.74	ug/L	U
591-78-6	2-Hexanone	A3383-9000	1.22	1.22	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9000	1.62	1.62	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9000	1.72	1.72	ug/L	U
994-05-8	TAME	A3383-9000	1.72	1.72	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9000	1.76	1.76	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9000	1.74	1.74	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9000	1.58	1.58	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9000	100.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9000	105.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9000	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9000	106.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9001	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9001	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9001	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9001	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9001	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9001	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9001	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9001	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9001	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9001	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9001	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9001	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9001	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9001	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9001	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9001	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9001	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9001	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9001	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9001	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9001	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9001	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9001	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9001	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9001	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9001	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9001	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9001	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9001	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9001	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9001	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9001	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9001	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9001	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9001	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9001	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9001	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9001	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9001	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9001	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9001	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9001	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9001	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9001	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9001	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9001	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9001	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9001	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9001	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9001	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9001	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9001	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9001	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9001	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9001	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9001	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9001	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9001	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9001	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9001	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9001	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9001	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9001	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9001	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9001	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9001	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9001	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9001	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9001	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9001	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9001	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9001	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9001	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9001	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9001	101.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9001	104.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9001	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9001	103.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9002	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9002	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9002	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9002	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9002	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9002	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9002	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9002	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9002	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9002	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9002	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9002	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9002	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9002	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9002	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9002	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9002	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9002	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9002	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9002	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9002	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9002	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9002	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9002	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9002	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9002	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9002	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9002	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9002	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9002	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9002	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9002	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9002	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9002	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9002	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9002	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9002	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9002	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9002	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9002	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9002	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9002	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9002	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9002	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9002	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9002	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9002	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9002	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9002	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9002	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9002	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9002	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9002	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9002	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9002	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9002	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9002	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9002	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9002	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9002	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9002	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9002	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9002	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9002	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9002	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9002	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9002	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9002	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9002	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9002	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9002	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9002	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9002	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9002	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9002	100.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9002	105.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9002	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9002	101.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9003	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9003	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9003	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9003	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9003	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9003	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9003	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9003	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9003	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9003	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9003	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9003	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9003	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9003	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9003	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9003	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9003	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9003	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9003	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9003	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9003	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9003	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9003	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9003	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9003	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9003	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9003	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9003	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9003	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9003	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9003	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9003	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Type: Grab
Collected: 5/10/2010
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9003	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9003	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9003	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9003	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9003	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9003	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9003	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9003	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9003	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9003	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9003	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9003	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9003	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9003	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9003	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9003	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9003	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9003	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9003	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9003	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9003	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9003	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9003	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9003	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9003	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9003	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9003	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9003	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9003	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9003	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9003	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9003	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9003	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9003	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9003	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9003	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9003	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9003	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9003	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9003	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9003	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9003	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9003	99.9 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9003	106.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9003	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9003	102.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5065	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5065	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5065	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5065	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5065	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5065	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5065	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5065	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5065	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5065	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5065	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5065	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5065	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5065	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5065	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5065	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5065	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5065	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5065	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5065	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5065	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5065	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5065	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5065	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5065	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5065	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5065	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5065	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5065	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5065	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5065	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5065	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5065	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5065	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5065	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5065	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5065	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5065	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5065	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5065	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5065	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5065	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5065	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5065	1.12	1.12	ug/L	U
	Cresols	B2663-5065	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5065	0.95	**5.69**	ug/L	
117-84-0	Di-n-octyl phthalate	B2663-5065	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5065	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5065	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5065	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5065	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5065	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5065	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5065	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5065	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5065	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5065	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5065	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5065	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5065	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5065	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5065	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5065	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5065	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5065	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5065	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5065	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5065	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5065	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5065	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5065	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5065	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5065	1.44	**2.47**	ug/L	J

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5065	97.2 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5065	79.1 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5065	37.1 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5065	73.3 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5065	25.0 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5065	79.3 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5066	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5066	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5066	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5066	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5066	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5066	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5066	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5066	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5066	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5066	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5066	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5066	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5066	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5066	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5066	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5066	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5066	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5066	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5066	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5066	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5066	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5066	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5066	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5066	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5066	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5066	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5066	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5066	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5066	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5066	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5066	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5066	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5066	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5066	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5066	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5066	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5066	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5066	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5066	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5066	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5066	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5066	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5066	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5066	1.12	1.12	ug/L	U
	Cresols	B2663-5066	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5066	0.95	**4.33**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5066	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5066	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5066	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5066	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5066	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5066	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5066	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5066	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5066	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5066	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5066	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5066	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5066	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5066	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5066	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5066	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5066	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5066	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5066	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5066	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5066	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5066	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5066	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5066	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5066	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5066	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5066	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5066	93.8 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5066	74.7 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5066	33.6 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5066	70.3 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5066	22.8 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5066	75.0 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5067	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5067	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5067	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5067	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5067	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5067	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5067	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5067	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5067	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5067	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5067	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5067	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5067	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5067	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5067	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5067	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5067	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5067	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5067	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5067	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5067	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5067	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5067	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5067	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5067	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5067	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5067	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5067	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5067	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5067	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5067	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5067	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5067	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5067	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5067	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5067	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5067	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5067	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5067	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5067	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5067	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5067	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5067	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5067	1.12	1.12	ug/L	U
	Cresols	B2663-5067	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5067	0.95	**4.30**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5067	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5067	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5067	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5067	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5067	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5067	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5067	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5067	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5067	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5067	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5067	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5067	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5067	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5067	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5067	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5067	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5067	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5067	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5067	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5067	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5067	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5067	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5067	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5067	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5067	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5067	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5067	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5067	96.8 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5067	72.3 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5067	32.1 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5067	67.4 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5067	21.5 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5067	82.7 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5068	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5068	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5068	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5068	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5068	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5068	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5068	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5068	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5068	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5068	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5068	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5068	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5068	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5068	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5068	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5068	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5068	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5068	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5068	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5068	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5068	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5068	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5068	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5068	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5068	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5068	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5068	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5068	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5068	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5068	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5068	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5068	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5068	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5068	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5068	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5068	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5068	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5068	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5068	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5068	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5068	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5068	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5068	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5068	1.12	1.12	ug/L	U
	Cresols	B2663-5068	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5068	0.95	**2.48**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5068	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5068	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5068	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5068	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5068	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5068	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5068	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5068	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5068	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5068	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5068	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5068	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5068	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5068	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5068	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5068	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5068	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5068	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42'
Matrix: Liquid
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Type: Grab

Collected: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5068	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5068	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5068	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5068	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5068	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5068	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5068	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5068	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5068	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5068	94.7 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5068	67.1 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5068	27.6 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5068	60.8 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5068	18.0 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5068	80.8 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Case Narrative

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100, 150 and 200 ppb levels in the initial calibration curve:
Acetone
2-Butanone
4-Methyl-2-pentanone
2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and 300 ppb levels.
Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.
Tert Butyl Alcohol (TBA) was calibrated at 50,200,500,1000 and 1500 ppb levels.

All other compounds were calibrated at 5, 20, 50, 100 and 150 ppb levels.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

10-05123
1005123

Rec vd Date 05/10/10 13 06

CHAIN OF CUSTODY

208 Route 109, Farmingdale, NY 11735
(Tel.) 631-249-1456 (Fax) 631-249-8324

Client Information		Project Information		Analytical Information	Matrix Codes
Company Name	James Waerner	Project Name	Newsday		
Address		Street	Pinelawn Rd.		
City	Farmingdale	State NY	Zip 1735	City Melville	State NY Zip
Project Contact	James Waerner	Project #			
Phone #	5163131674	Fax #	Sampler's Name	Jim Waerner	
E-mail		Sampler's Signature			

LAB SAMPLE # (LAB USE ONLY)	Sample Information: Sample ID	Sample Type	Matrix Code	Sample Collection: Date	Time	Sample Containers: # of Containers Each / Preservative Code / Total # of Containers	Analytical Information	Sample Type (LAB USE ONLY)
	GW-1D 40-42'	G	L	5/7/10		3	X Y	
	GW-2D 40-42'	G	L			3	X Y	
	GW-3D 40-42'	G	L			3	X Y	
	GW-4D 40-42'	G	L			3	X Y	

Analytical Information: 8260 624 TBA DNAPH UIC DBE 8270 625 OTA OSTARS DAE UBN PAH UTCLP TIC 0-10 0-15 0-25 0-99 | PEST PCB DHERB UTCLP OVPH EPH OHRO OGRO 8010B TNRCSH1500 METALS TOTAL RTAL TRCRA UTCLP Mercury TNRCCE Cyanide RCRA Reactivity

Turnaround Time (Business Days)

- Standard 7-10 Business Days
- 5 Day RUSH
- 4 Day RUSH
- 3 Day RUSH
- 2 Day RUSH
- X 1 Day RUSH

(LAB USE ONLY) TAT Approved By/Date:

Data Deliverable Information

- X Results Only (Level 1)
- Results + Misc. QC (Level 2)
- Results + All QC (Level 3)
- MA DEP QC Package (Level 3)
- NJ DEP QC Package (Level 3)

ISSO Formats: Excel EQL & SIS Geo Knox ARCHIVE Any "TAB" DENJ

Comments / Remarks

ETL COC Review Check List (LAB USE ONLY)

- ☐ Task Log In and Initial Review — Init: ____ Date/Time ____
- ☐ Final Review and Approval — Init: ____ Date/Time ____
- ☐ Complete and Invoiced — Init: ____ Date/Time ____

Sample custody must be documented below each time samples change possession with a signature, date, and time.

Relinquished by Sampler	Date / Time	Received By	Relinquished By	Date / Time	Received By
1	5/10/10	1	2	5/10/10 13:00	2
Relinquished By	Date / Time	Received By	Relinquished By	Date / Time	Received By
3	3	3	4	4	4
Relinquished By	Date / Time	Received By	COOLER INFORMATION		

ETL Chain of Custody: 1005123						
Project: NEWSDAY						
Address: 235 Pi	Collected Date:		05/10/10	05/10/10	05/10/10	05/10/10
	Sample Type:		Grab	Grab	Grab	Grab
	Sample Name:		GW-1@ 40-42'	2 @ 40-42'	3 @ 40-42'	4 @ 40-42'
Analysis	**Analyte**	**Units**				
Semivolatile Compou	1,2,4-Trichlorobenzene	ug/L	<0.86	<0.86	<0.86	<0.86
Semivolatile Compou	1,2-Dichlorobenzene	ug/L	<0.79	<0.79	<0.79	<0.79
Semivolatile Compou	1,2-Diphenylhydrazine	ug/L	<0.75	<0.75	<0.75	<0.75
Semivolatile Compou	1,3-Dichlorobenzene	ug/L	<0.68	<0.68	<0.68	<0.68
Semivolatile Compou	1,4-Dichlorobenzene	ug/L	<0.88	<0.88	<0.88	<0.88
Semivolatile Compou	2,3,4,6-Tetrachlorophenol	ug/L	<1.18	<1.18	<1.18	<1.18
Semivolatile Compou	2,4,5-Trichlorophenol	ug/L	<0.67	<0.67	<0.67	<0.67
Semivolatile Compou	2,4,6-Trichlorophenol	ug/L	<0.93	<0.93	<0.93	<0.93
Semivolatile Compou	2,4-Dichlorophenol	ug/L	<0.53	<0.53	<0.53	<0.53
Semivolatile Compou	2,4-Dimethylphenol	ug/L	<0.76	<0.76	<0.76	<0.76
Semivolatile Compou	2,4-Dinitrophenol	ug/L	<2.68	<2.68	<2.68	<2.68
Semivolatile Compou	2,4-Dinitrotoluene	ug/L	<1.05	<1.05	<1.05	<1.05
Semivolatile Compou	2,6-Dinitrotoluene	ug/L	<0.78	<0.78	<0.78	<0.78
Semivolatile Compou	2-Chloronaphthalene	ug/L	<0.79	<0.79	<0.79	<0.79
Semivolatile Compou	2-Chlorophenol	ug/L	<0.66	<0.66	<0.66	<0.66
Semivolatile Compou	2-Methylnaphthalene	ug/L	<0.68	<0.68	<0.68	<0.68
Semivolatile Compou	2-Methylphenol	ug/L	<0.46	<0.46	<0.46	<0.46
Semivolatile Compou	2-Nitroaniline	ug/L	<0.37	<0.37	<0.37	<0.37
Semivolatile Compou	2-Nitrophenol	ug/L	<0.83	<0.83	<0.83	<0.83
Semivolatile Compou	3+4-Methylphenol	ug/L	<0.41	<0.41	<0.41	<0.41
Semivolatile Compou	3,3'-Dichlorobenzidine	ug/L	<1.05	<1.05	<1.05	<1.05
Semivolatile Compou	3-Nitroaniline	ug/L	<0.23	<0.23	<0.23	<0.23
Semivolatile Compou	4,6-Dinitro-2-methylphenol	ug/L	<0.42	<0.42	<0.42	<0.42
Semivolatile Compou	4-Bromophenyl phenyl ether	ug/L	<0.94	<0.94	<0.94	<0.94
Semivolatile Compou	4-Chloro-3-methylphenol	ug/L	<0.59	<0.59	<0.59	<0.59
Semivolatile Compou	4-Chloroaniline	ug/L	<0.39	<0.39	<0.39	<0.39
Semivolatile Compou	4-Chlorophenyl phenyl ether	ug/L	<0.87	<0.87	<0.87	<0.87
Semivolatile Compou	4-Nitroaniline	ug/L	<1.22	<1.22	<1.22	<1.22
Semivolatile Compou	4-Nitrophenol	ug/L	<1.92	<1.92	<1.92	<1.92
Semivolatile Compou	Acenaphthene	ug/L	<0.81	<0.81	<0.81	<0.81
Semivolatile Compou	Acenaphthylene	ug/L	<0.72	<0.72	<0.72	<0.72
Semivolatile Compou	Aniline	ug/L	<0.33	<0.33	<0.33	<0.33
Semivolatile Compou	Anthracene	ug/L	<0.85	<0.85	<0.85	<0.85
Semivolatile Compou	Benzidine	ug/L	<29.6	<29.6	<29.6	<29.6
Semivolatile Compou	Benzo(a)anthracene	ug/L	<0.92	<0.92	<0.92	<0.92
Semivolatile Compou	Benzo(a)pyrene	ug/L	<0.93	<0.93	<0.93	<0.93
Semivolatile Compou	Benzo(b)fluoranthene	ug/L	<0.91	<0.91	<0.91	<0.91
Semivolatile Compou	Benzo(g,h,i)perylene	ug/L	<1.02	<1.02	<1.02	<1.02
Semivolatile Compou	Benzo(k)fluoranthene	ug/L	<1.38	<1.38	<1.38	<1.38
Semivolatile Compou	Benzoic acid	ug/L	<8.53	<8.53	<8.53	<8.53
Semivolatile Compou	Benzyl alcohol	ug/L	<0.67	<0.67	<0.67	<0.67
Semivolatile Compou	Butyl benzyl phthalate	ug/L	<0.69	<0.69	<0.69	<0.69
Semivolatile Compou	Carbazole	ug/L	<1.04	<1.04	<1.04	<1.04
Semivolatile Compou	Chrysene	ug/L	<1.12	<1.12	<1.12	<1.12
Semivolatile Compou	Cresols	ug/L	<0.87	<0.87	<0.87	<0.87
Semivolatile Compou	Di-n-butyl phthalate	ug/L	5.69	4.33	4.3	2.48
Semivolatile Compou	Di-n-octyl phthalate	ug/L	<1.22	<1.22	<1.22	<1.22
Semivolatile Compou	Dibenz(a,h)anthracene	ug/L	<1.12	<1.12	<1.12	<1.12
Semivolatile Compou	Dibenzofuran	ug/L	<0.68	<0.68	<0.68	<0.68
Semivolatile Compou	Diethyl phthalate	ug/L	<0.88	<0.88	<0.88	<0.88
Semivolatile Compou	Dimethyl phthalate	ug/L	<0.85	<0.85	<0.85	<0.85
Semivolatile Compou	Fluoranthene	ug/L	<0.97	<0.97	<0.97	<0.97

Semivolatile Compou	Fluorene	ug/L	<0.83	<0.83	<0.83	<0.83
Semivolatile Compou	Hexachlorobenzene	ug/L	<0.95	<0.95	<0.95	<0.95
Semivolatile Compou	Hexachlorobutadiene	ug/L	<0.83	<0.83	<0.83	<0.83
Semivolatile Compou	Hexachlorocyclopentadiene	ug/L	<2.71	<2.71	<2.71	<2.71
Semivolatile Compou	Hexachloroethane	ug/L	<0.66	<0.66	<0.66	<0.66
Semivolatile Compou	Indeno(1,2,3-cd)pyrene	ug/L	<1.02	<1.02	<1.02	<1.02
Semivolatile Compou	Isophorone	ug/L	<0.47	<0.47	<0.47	<0.47
Semivolatile Compou	N-Nitrosodi-n-propylamine	ug/L	<0.55	<0.55	<0.55	<0.55
Semivolatile Compou	N-Nitrosodimethylamine	ug/L	<0.75	<0.75	<0.75	<0.75
Semivolatile Compou	N-Nitrosodiphenylamine	ug/L	<1.13	<1.13	<1.13	<1.13
Semivolatile Compou	Naphthalene	ug/L	<0.83	<0.83	<0.83	<0.83
Semivolatile Compou	Nitrobenzene	ug/L	<0.76	<0.76	<0.76	<0.76
Semivolatile Compou	Pentachlorophenol	ug/L	<0.73	<0.73	<0.73	<0.73
Semivolatile Compou	Phenanthrene	ug/L	<0.94	<0.94	<0.94	<0.94
Semivolatile Compou	Phenol	ug/L	<0.32	<0.32	<0.32	<0.32
Semivolatile Compou	Pyrene	ug/L	<0.84	<0.84	<0.84	<0.84
Semivolatile Compou	Pyridine	ug/L	<0.40	<0.40	<0.40	<0.40
Semivolatile Compou	bis(2-Chloroethoxy)methane	ug/L	<0.80	<0.80	<0.80	<0.80
Semivolatile Compou	bis(2-Chloroethyl)ether	ug/L	<0.70	<0.70	<0.70	<0.70
Semivolatile Compou	bis(2-Chloroisopropyl)ether	ug/L	<0.60	<0.60	<0.60	<0.60
Semivolatile Compou	bis(2-Ethylhexyl)phthalate	ug/L	2.47	<1.44	<1.44	<1.44
Volatiles - EPA 8260E	Acetone	ug/L	<2.32	<1.16	<1.16	<1.16
Volatiles - EPA 8260E	Carbon Tetrachloride	ug/L	<1.80	<0.90	<0.90	<0.90
Volatiles - EPA 8260E	Chloroform	ug/L	<1.94	<0.97	<0.97	<0.97
Volatiles - EPA 8260E	Benzene	ug/L	<1.76	<0.88	<0.88	<0.88
Volatiles - EPA 8260E	1,1,1-Trichloroethane	ug/L	<1.90	<0.95	<0.95	<0.95
Volatiles - EPA 8260E	Bromomethane	ug/L	<2.04	<1.02	<1.02	<1.02
Volatiles - EPA 8260E	Chloromethane	ug/L	<1.58	<0.79	<0.79	<0.79
Volatiles - EPA 8260E	Dibromomethane	ug/L	<1.82	<0.91	<0.91	<0.91
Volatiles - EPA 8260E	Bromochloromethane	ug/L	<1.82	<0.91	<0.91	<0.91
Volatiles - EPA 8260E	Chloroethane	ug/L	<2.88	<1.44	<1.44	<1.44
Volatiles - EPA 8260E	Vinyl Chloride	ug/L	<1.64	<0.82	<0.82	<0.82
Volatiles - EPA 8260E	Methylene Chloride	ug/L	<2.16	<1.08	<1.08	<1.08
Volatiles - EPA 8260E	Carbon disulfide	ug/L	<1.64	<0.82	<0.82	<0.82
Volatiles - EPA 8260E	Bromoform	ug/L	<1.62	<0.81	<0.81	<0.81
Volatiles - EPA 8260E	Bromodichloromethane	ug/L	<1.78	<0.89	<0.89	<0.89
Volatiles - EPA 8260E	1,1-Dichloroethane	ug/L	<2.02	<1.01	<1.01	<1.01
Volatiles - EPA 8260E	1,1-Dichloroethene	ug/L	<1.86	<0.93	<0.93	<0.93
Volatiles - EPA 8260E	Chlorodifluoromethane	ug/L	<1.86	<0.93	<0.93	<0.93
Volatiles - EPA 8260E	Tertiary butyl alcohol	ug/L	<16.2	<8.10	<8.10	<8.10
Volatiles - EPA 8260E	Trichlorofluoromethane	ug/L	<2.00	<1.00	<1.00	<1.00
Volatiles - EPA 8260E	Dichlorodifluoromethane	ug/L	<1.60	<0.80	<0.80	<0.80
Volatiles - EPA 8260E	1,1,2-Trichlorotrifluoroethane	ug/L	<1.76	<0.88	<0.88	<0.88
Volatiles - EPA 8260E	1,2-Dichloropropane	ug/L	<1.78	<0.89	<0.89	<0.89
Volatiles - EPA 8260E	2-Butanone	ug/L	<1.52	<0.76	<0.76	<0.76
Volatiles - EPA 8260E	1,1,2-Trichloroethane	ug/L	<1.80	<0.90	<0.90	<0.90
Volatiles - EPA 8260E	Trichloroethene	ug/L	<1.88	<0.94	<0.94	<0.94
Volatiles - EPA 8260E	1,1,2,2-Tetrachloroethane	ug/L	<1.50	<0.75	<0.75	<0.75
Volatiles - EPA 8260E	1,2,3-Trichlorobenzene	ug/L	<1.24	<0.62	<0.62	<0.62
Volatiles - EPA 8260E	Hexachlorobutadiene	ug/L	<1.58	<0.79	<0.79	<0.79
Volatiles - EPA 8260E	Naphthalene	ug/L	<1.22	<0.61	<0.61	<0.61
Volatiles - EPA 8260E	o-xylene	ug/L	<1.70	<0.85	<0.85	<0.85
Volatiles - EPA 8260E	2-Chlorotoluene	ug/L	<1.66	<0.83	<0.83	<0.83
Volatiles - EPA 8260E	1,2-Dichlorobenzene	ug/L	<1.60	<0.80	<0.80	<0.80
Volatiles - EPA 8260E	1,2,4-Trimethylbenzene	ug/L	<1.68	<0.84	<0.84	<0.84
Volatiles - EPA 8260E	1,2,4,5-Tetramethylbenzene	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	1,2-Dibromo-3-chloropropane	ug/L	<1.50	<0.75	<0.75	<0.75
Volatiles - EPA 8260E	1,2,3-Trichloropropane	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	tert-Butylbenzene	ug/L	<1.70	<0.85	<0.85	<0.85

Volatiles - EPA 8260E	Isopropylbenzene	ug/L	<1.72	<0.86	<0.86	<0.86
Volatiles - EPA 8260E	4-Isopropyltoluene	ug/L	<1.62	<0.81	<0.81	<0.81
Volatiles - EPA 8260E	Ethylbenzene	ug/L	<1.78	<0.89	<0.89	<0.89
Volatiles - EPA 8260E	Styrene	ug/L	<1.62	<0.81	<0.81	<0.81
Volatiles - EPA 8260E	n-Propylbenzene	ug/L	<1.62	<0.81	<0.81	<0.81
Volatiles - EPA 8260E	n-Butylbenzene	ug/L	<1.66	<0.83	<0.83	<0.83
Volatiles - EPA 8260E	p-Diethylbenzene	ug/L	<1.54	<0.77	<0.77	<0.77
Volatiles - EPA 8260E	4-Chlorotoluene	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	1,4-Dichlorobenzene	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	1,2-Dibromoethane	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	1,2-Dichloroethane	ug/L	<1.94	<0.97	<0.97	<0.97
Volatiles - EPA 8260E	Acrylonitrile	ug/L	<7.56	<3.78	<3.78	<3.78
Volatiles - EPA 8260E	4-Methyl-2-pentanone	ug/L	<1.72	<0.86	<0.86	<0.86
Volatiles - EPA 8260E	m,p-xylene	ug/L	<3.48	<1.74	<1.74	<1.74
Volatiles - EPA 8260E	1,3,5-Trimethylbenzene	ug/L	<1.64	<0.82	<0.82	<0.82
Volatiles - EPA 8260E	Bromobenzene	ug/L	<1.60	<0.80	<0.80	<0.80
Volatiles - EPA 8260E	Toluene	ug/L	<2.16	<1.08	<1.08	<1.08
Volatiles - EPA 8260E	Chlorobenzene	ug/L	<1.72	<0.86	<0.86	<0.86
Volatiles - EPA 8260E	2-Chloroethylvinylether	ug/L	<2.84	<1.42	<1.42	<1.42
Volatiles - EPA 8260E	1,2,4-Trichlorobenzene	ug/L	<1.34	<0.67	<0.67	<0.67
Volatiles - EPA 8260E	Dibromochloromethane	ug/L	<1.66	<0.83	<0.83	<0.83
Volatiles - EPA 8260E	Tetrachloroethene	ug/L	<1.68	<0.84	<0.84	<0.84
Volatiles - EPA 8260E	sec-Butylbenzene	ug/L	<1.56	<0.78	<0.78	<0.78
Volatiles - EPA 8260E	1,3-Dichloropropane	ug/L	<1.66	<0.83	<0.83	<0.83
Volatiles - EPA 8260E	c-1,2-Dichloroethene	ug/L	<1.78	<0.89	<0.89	<0.89
Volatiles - EPA 8260E	t-1,2-Dichloroethene	ug/L	<1.90	<0.95	<0.95	<0.95
Volatiles - EPA 8260E	1,3-Dichlorobenzene	ug/L	<1.54	<0.77	<0.77	<0.77
Volatiles - EPA 8260E	1,1-Dichloropropene	ug/L	<1.60	<0.80	<0.80	<0.80
Volatiles - EPA 8260E	2,2-Dichloropropane	ug/L	<1.74	<0.87	<0.87	<0.87
Volatiles - EPA 8260E	2-Hexanone	ug/L	<1.22	<0.61	<0.61	<0.61
Volatiles - EPA 8260E	p-Ethyltoluene	ug/L	<1.62	<0.81	<0.81	<0.81
Volatiles - EPA 8260E	1,1,1,2-Tetrachloroethane	ug/L	<1.72	<0.86	<0.86	<0.86
Volatiles - EPA 8260E	TAME	ug/L	<1.72	<0.86	<0.86	<0.86
Volatiles - EPA 8260E	Methyl t-butyl ether	ug/L	<1.76	<0.88	<0.88	<0.88
Volatiles - EPA 8260E	c-1,3-Dichloropropene	ug/L	<1.74	<0.87	<0.87	<0.87
Volatiles - EPA 8260E	t-1,3-Dichloropropene	ug/L	<1.58	<0.79	<0.79	<0.79

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100, 150 and 200 ppb levels in the initial calibration curve:

Acetone

2-Butanone

4-Methyl-2-pentanone

2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and 300 ppb levels.

Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.

Tert Butyl Alcohol (TBA) was

	calibrated at 50,200,500,1000				
	and 1500 ppb levels.				
	All other compounds were				
	calibrated at 5, 20, 50, 100 and				
	150 ppb levels.				

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Laboratory Identifier: 1005123
Received: 5/10/2010 13:06
Sampled by: Jim Woerner

Client: James Woerner Inc
130 Allen Blvd
Farmingdale,
NY 11735

Project: NEWSDAY
235 Pinelawn Road
Melville ,
NY

Manager: James Woerner

Respectfully submitted,

Technical Director

NYS Lab ID # 10969
NJ Cert. # 73812
CT Cert. # PH0645
MA Cert. # NY061
PA Cert. #002

The information contained in this report is confidential and intended only for the use of the client listed above. This report shall not be reproduced, except in full, without the written consent of Environmental Testing Laboratories, Inc. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Collected: 5/10/2010
Matrix: Liquid
Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9000	2.32	2.32	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9000	1.80	1.80	ug/L	U
67-66-3	Chloroform	A3383-9000	1.94	1.94	ug/L	U
71-43-2	Benzene	A3383-9000	1.76	1.76	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9000	1.90	1.90	ug/L	U
74-83-9	Bromomethane	A3383-9000	2.04	2.04	ug/L	U
74-87-3	Chloromethane	A3383-9000	1.58	1.58	ug/L	U
74-95-3	Dibromomethane	A3383-9000	1.82	1.82	ug/L	U
74-97-5	Bromochloromethane	A3383-9000	1.82	1.82	ug/L	U
75-00-3	Chloroethane	A3383-9000	2.88	2.88	ug/L	U
75-01-4	Vinyl Chloride	A3383-9000	1.64	1.64	ug/L	U
75-09-2	Methylene Chloride	A3383-9000	2.16	2.16	ug/L	U
75-15-0	Carbon disulfide	A3383-9000	1.64	1.64	ug/L	U
75-25-2	Bromoform	A3383-9000	1.62	1.62	ug/L	U
75-27-4	Bromodichloromethane	A3383-9000	1.78	1.78	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9000	2.02	2.02	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9000	1.86	1.86	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9000	1.86	1.86	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9000	16.2	16.2	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9000	2.00	2.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9000	1.60	1.60	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9000	1.76	1.76	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9000	1.78	1.78	ug/L	U
78-93-3	2-Butanone	A3383-9000	1.52	1.52	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9000	1.80	1.80	ug/L	U
79-01-6	Trichloroethene	A3383-9000	1.88	1.88	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9000	1.50	1.50	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9000	1.24	1.24	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9000	1.58	1.58	ug/L	U
91-20-3	Naphthalene	A3383-9000	1.22	1.22	ug/L	U
95-47-6	o-xylene	A3383-9000	1.70	1.70	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9000	1.66	1.66	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42'
Collected: 5/10/2010
Matrix: Liquid
Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9000	1.60	1.60	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9000	1.68	1.68	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9000	1.56	1.56	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9000	1.50	1.50	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9000	1.56	1.56	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9000	1.70	1.70	ug/L	U
98-82-8	Isopropylbenzene	A3383-9000	1.72	1.72	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9000	1.62	1.62	ug/L	U
100-41-4	Ethylbenzene	A3383-9000	1.78	1.78	ug/L	U
100-42-5	Styrene	A3383-9000	1.62	1.62	ug/L	U
103-65-1	n-Propylbenzene	A3383-9000	1.62	1.62	ug/L	U
104-51-8	n-Butylbenzene	A3383-9000	1.66	1.66	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9000	1.54	1.54	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9000	1.56	1.56	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9000	1.56	1.56	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9000	1.56	1.56	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9000	1.94	1.94	ug/L	U
107-13-1	Acrylonitrile	A3383-9000	7.56	7.56	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9000	1.72	1.72	ug/L	U
108-38-3	m,p-xylene	A3383-9000	3.48	3.48	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9000	1.64	1.64	ug/L	U
108-86-1	Bromobenzene	A3383-9000	1.60	1.60	ug/L	U
108-88-3	Toluene	A3383-9000	2.16	2.16	ug/L	U
108-90-7	Chlorobenzene	A3383-9000	1.72	1.72	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9000	2.84	2.84	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9000	1.34	1.34	ug/L	U
124-48-1	Dibromochloromethane	A3383-9000	1.66	1.66	ug/L	U
127-18-4	Tetrachloroethene	A3383-9000	1.68	1.68	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9000	1.56	1.56	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9000	1.66	1.66	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9000	1.78	1.78	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9000	1.90	1.90	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9000	1.54	1.54	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9000	1.60	1.60	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9000	1.74	1.74	ug/L	U
591-78-6	2-Hexanone	A3383-9000	1.22	1.22	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9000	1.62	1.62	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9000	1.72	1.72	ug/L	U
994-05-8	TAME	A3383-9000	1.72	1.72	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9000	1.76	1.76	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9000	1.74	1.74	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9000	1.58	1.58	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9000	100.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9000	105.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9000	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9000	106.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42'
Collected: 5/10/2010
Matrix: Liquid
Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9001	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9001	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9001	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9001	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9001	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9001	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9001	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9001	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9001	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9001	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9001	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9001	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9001	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9001	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9001	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9001	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9001	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9001	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9001	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9001	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9001	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9001	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9001	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9001	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9001	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9001	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9001	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9001	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9001	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9001	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9001	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9001	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9001	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9001	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9001	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9001	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9001	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9001	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9001	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9001	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9001	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9001	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9001	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9001	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9001	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9001	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9001	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9001	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9001	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9001	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9001	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9001	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9001	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9001	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9001	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9001	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9001	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9001	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9001	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9001	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9001	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9001	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9001	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9001	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9001	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9001	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9001	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9001	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9001	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9001	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9001	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9001	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9001	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9001	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9001	101.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9001	104.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9001	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9001	103.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9002	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9002	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9002	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9002	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9002	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9002	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9002	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9002	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9002	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9002	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9002	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9002	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9002	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9002	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9002	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9002	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9002	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9002	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9002	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9002	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9002	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9002	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9002	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9002	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9002	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9002	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9002	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9002	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9002	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9002	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9002	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9002	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9002	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9002	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9002	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9002	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9002	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9002	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9002	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9002	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9002	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9002	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9002	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9002	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9002	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9002	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9002	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9002	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9002	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9002	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9002	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9002	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9002	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9002	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9002	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9002	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9002	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9002	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9002	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9002	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9002	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9002	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9002	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9002	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9002	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9002	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9002	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9002	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9002	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9002	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9002	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9002	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9002	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9002	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9002	100.0 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9002	105.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9002	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9002	101.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
67-64-1	Acetone	A3383-9003	1.16	1.16	ug/L	U
56-23-5	Carbon Tetrachloride	A3383-9003	0.90	0.90	ug/L	U
67-66-3	Chloroform	A3383-9003	0.97	0.97	ug/L	U
71-43-2	Benzene	A3383-9003	0.88	0.88	ug/L	U
71-55-6	1,1,1-Trichloroethane	A3383-9003	0.95	0.95	ug/L	U
74-83-9	Bromomethane	A3383-9003	1.02	1.02	ug/L	U
74-87-3	Chloromethane	A3383-9003	0.79	0.79	ug/L	U
74-95-3	Dibromomethane	A3383-9003	0.91	0.91	ug/L	U
74-97-5	Bromochloromethane	A3383-9003	0.91	0.91	ug/L	U
75-00-3	Chloroethane	A3383-9003	1.44	1.44	ug/L	U
75-01-4	Vinyl Chloride	A3383-9003	0.82	0.82	ug/L	U
75-09-2	Methylene Chloride	A3383-9003	1.08	1.08	ug/L	U
75-15-0	Carbon disulfide	A3383-9003	0.82	0.82	ug/L	U
75-25-2	Bromoform	A3383-9003	0.81	0.81	ug/L	U
75-27-4	Bromodichloromethane	A3383-9003	0.89	0.89	ug/L	U
75-34-3	1,1-Dichloroethane	A3383-9003	1.01	1.01	ug/L	U
75-35-4	1,1-Dichloroethene	A3383-9003	0.93	0.93	ug/L	U
75-45-6	Chlorodifluoromethane	A3383-9003	0.93	0.93	ug/L	U
75-65-0	Tertiary butyl alcohol	A3383-9003	8.10	8.10	ug/L	U
75-69-4	Trichlorofluoromethane	A3383-9003	1.00	1.00	ug/L	U
75-71-8	Dichlorodifluoromethane	A3383-9003	0.80	0.80	ug/L	U
76-13-1	1,1,2-Trichlorotrifluoroethane	A3383-9003	0.88	0.88	ug/L	U
78-87-5	1,2-Dichloropropane	A3383-9003	0.89	0.89	ug/L	U
78-93-3	2-Butanone	A3383-9003	0.76	0.76	ug/L	U
79-00-5	1,1,2-Trichloroethane	A3383-9003	0.90	0.90	ug/L	U
79-01-6	Trichloroethene	A3383-9003	0.94	0.94	ug/L	U
79-34-5	1,1,2,2-Tetrachloroethane	A3383-9003	0.75	0.75	ug/L	U
87-61-6	1,2,3-Trichlorobenzene	A3383-9003	0.62	0.62	ug/L	U
87-68-3	Hexachlorobutadiene	A3383-9003	0.79	0.79	ug/L	U
91-20-3	Naphthalene	A3383-9003	0.61	0.61	ug/L	U
95-47-6	o-xylene	A3383-9003	0.85	0.85	ug/L	U
95-49-8	2-Chlorotoluene	A3383-9003	0.83	0.83	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
95-50-1	1,2-Dichlorobenzene	A3383-9003	0.80	0.80	ug/L	U
95-63-6	1,2,4-Trimethylbenzene	A3383-9003	0.84	0.84	ug/L	U
95-93-2	1,2,4,5-Tetramethylbenzene	A3383-9003	0.78	0.78	ug/L	U
96-12-8	1,2-Dibromo-3-chloropropane	A3383-9003	0.75	0.75	ug/L	U
96-18-4	1,2,3-Trichloropropane	A3383-9003	0.78	0.78	ug/L	U
98-06-6	tert-Butylbenzene	A3383-9003	0.85	0.85	ug/L	U
98-82-8	Isopropylbenzene	A3383-9003	0.86	0.86	ug/L	U
99-87-6	4-Isopropyltoluene	A3383-9003	0.81	0.81	ug/L	U
100-41-4	Ethylbenzene	A3383-9003	0.89	0.89	ug/L	U
100-42-5	Styrene	A3383-9003	0.81	0.81	ug/L	U
103-65-1	n-Propylbenzene	A3383-9003	0.81	0.81	ug/L	U
104-51-8	n-Butylbenzene	A3383-9003	0.83	0.83	ug/L	U
105-05-5	p-Diethylbenzene	A3383-9003	0.77	0.77	ug/L	U
106-43-4	4-Chlorotoluene	A3383-9003	0.78	0.78	ug/L	U
106-46-7	1,4-Dichlorobenzene	A3383-9003	0.78	0.78	ug/L	U
106-93-4	1,2-Dibromoethane	A3383-9003	0.78	0.78	ug/L	U
107-06-2	1,2-Dichloroethane	A3383-9003	0.97	0.97	ug/L	U
107-13-1	Acrylonitrile	A3383-9003	3.78	3.78	ug/L	U
108-10-1	4-Methyl-2-pentanone	A3383-9003	0.86	0.86	ug/L	U
108-38-3	m,p-xylene	A3383-9003	1.74	1.74	ug/L	U
108-67-8	1,3,5-Trimethylbenzene	A3383-9003	0.82	0.82	ug/L	U
108-86-1	Bromobenzene	A3383-9003	0.80	0.80	ug/L	U
108-88-3	Toluene	A3383-9003	1.08	1.08	ug/L	U
108-90-7	Chlorobenzene	A3383-9003	0.86	0.86	ug/L	U
110-75-8	2-Chloroethylvinylether	A3383-9003	1.42	1.42	ug/L	U
120-82-1	1,2,4-Trichlorobenzene	A3383-9003	0.67	0.67	ug/L	U
124-48-1	Dibromochloromethane	A3383-9003	0.83	0.83	ug/L	U
127-18-4	Tetrachloroethene	A3383-9003	0.84	0.84	ug/L	U
135-98-8	sec-Butylbenzene	A3383-9003	0.78	0.78	ug/L	U
142-28-9	1,3-Dichloropropane	A3383-9003	0.83	0.83	ug/L	U
156-59-2	c-1,2-Dichloroethene	A3383-9003	0.89	0.89	ug/L	U
156-60-5	t-1,2-Dichloroethene	A3383-9003	0.95	0.95	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Volatiles - EPA 8260B

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks: See Case Narrative
Analyzed Date: 5/10/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
541-73-1	1,3-Dichlorobenzene	A3383-9003	0.77	0.77	ug/L	U
563-58-6	1,1-Dichloropropene	A3383-9003	0.80	0.80	ug/L	U
590-20-7	2,2-Dichloropropane	A3383-9003	0.87	0.87	ug/L	U
591-78-6	2-Hexanone	A3383-9003	0.61	0.61	ug/L	U
622-96-8	p-Ethyltoluene	A3383-9003	0.81	0.81	ug/L	U
630-20-6	1,1,1,2-Tetrachloroethane	A3383-9003	0.86	0.86	ug/L	U
994-05-8	TAME	A3383-9003	0.86	0.86	ug/L	U
1634-04-4	Methyl t-butyl ether	A3383-9003	0.88	0.88	ug/L	U
10061-01-5	c-1,3-Dichloropropene	A3383-9003	0.87	0.87	ug/L	U
10061-02-6	t-1,3-Dichloropropene	A3383-9003	0.79	0.79	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
17060-07-0	1,2-DICHLOROETHANE-D4	A3383-9003	99.9 %	(73 - 129)	
460-00-4	4-BROMOFLUOROBENZENE	A3383-9003	106.0 %	(88 - 110)	
4774-33-8	DIBROMOFLUOROMETHANE	A3383-9003	102.0 %	(88 - 113)	
2037-26-5	TOLUENE-D8	A3383-9003	102.0 %	(92 - 107)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5065	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5065	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5065	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5065	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5065	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5065	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5065	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5065	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5065	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5065	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5065	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5065	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5065	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5065	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5065	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5065	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5065	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5065	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5065	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5065	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5065	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5065	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5065	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5065	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5065	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5065	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5065	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5065	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5065	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5065	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5065	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5065	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5065	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5065	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5065	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5065	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5065	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5065	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5065	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5065	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5065	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5065	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5065	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5065	1.12	1.12	ug/L	U
	Cresols	B2663-5065	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5065	0.95	**5.69**	ug/L	
117-84-0	Di-n-octyl phthalate	B2663-5065	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5065	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5065	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5065	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5065	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5065	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5065	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5065	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5065	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5065	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5065	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5065	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5065	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5065	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5065	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5065	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5065	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5065	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-1
Client Sample ID: GW-1@ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5065	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5065	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5065	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5065	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5065	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5065	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5065	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5065	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5065	1.44	**2.47**	ug/L	J

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5065	97.2 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5065	79.1 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5065	37.1 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5065	73.3 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5065	25.0 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5065	79.3 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5066	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5066	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5066	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5066	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5066	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5066	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5066	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5066	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5066	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5066	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5066	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5066	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5066	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5066	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5066	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5066	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5066	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5066	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5066	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5066	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5066	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5066	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5066	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5066	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5066	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5066	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5066	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5066	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5066	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5066	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5066	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5066	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5066	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5066	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5066	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5066	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5066	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5066	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5066	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5066	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5066	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5066	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5066	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5066	1.12	1.12	ug/L	U
	Cresols	B2663-5066	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5066	0.95	**4.33**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5066	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5066	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5066	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5066	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5066	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5066	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5066	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5066	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5066	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5066	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5066	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5066	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5066	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5066	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5066	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5066	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5066	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5066	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-2
Client Sample ID: GW-2 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5066	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5066	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5066	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5066	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5066	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5066	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5066	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5066	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5066	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5066	93.8 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5066	74.7 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5066	33.6 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5066	70.3 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5066	22.8 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5066	75.0 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5067	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5067	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5067	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5067	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5067	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5067	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5067	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5067	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5067	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5067	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5067	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5067	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5067	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5067	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5067	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5067	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5067	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5067	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5067	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5067	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5067	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5067	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5067	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5067	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5067	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5067	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5067	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5067	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5067	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5067	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5067	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5067	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5067	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5067	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5067	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5067	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5067	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5067	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5067	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5067	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5067	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5067	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5067	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5067	1.12	1.12	ug/L	U
	Cresols	B2663-5067	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5067	0.95	**4.30**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5067	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5067	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5067	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5067	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5067	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5067	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5067	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5067	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5067	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5067	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5067	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5067	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5067	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5067	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5067	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5067	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5067	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5067	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-3
Client Sample ID: GW-3 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5067	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5067	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5067	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5067	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5067	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5067	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5067	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5067	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5067	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5067	96.8 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5067	72.3 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5067	32.1 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5067	67.4 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5067	21.5 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5067	82.7 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-82-1	1,2,4-Trichlorobenzene	B2663-5068	0.86	0.86	ug/L	U
95-50-1	1,2-Dichlorobenzene	B2663-5068	0.79	0.79	ug/L	U
122-66-7	1,2-Diphenylhydrazine	B2663-5068	0.75	0.75	ug/L	U
541-73-1	1,3-Dichlorobenzene	B2663-5068	0.68	0.68	ug/L	U
106-46-7	1,4-Dichlorobenzene	B2663-5068	0.88	0.88	ug/L	U
58-90-2	2,3,4,6-Tetrachlorophenol	B2663-5068	1.18	1.18	ug/L	U
95-95-4	2,4,5-Trichlorophenol	B2663-5068	0.67	0.67	ug/L	U
88-06-2	2,4,6-Trichlorophenol	B2663-5068	0.93	0.93	ug/L	U
120-83-2	2,4-Dichlorophenol	B2663-5068	0.53	0.53	ug/L	U
105-67-9	2,4-Dimethylphenol	B2663-5068	0.76	0.76	ug/L	U
51-28-5	2,4-Dinitrophenol	B2663-5068	2.68	2.68	ug/L	U
121-14-2	2,4-Dinitrotoluene	B2663-5068	1.05	1.05	ug/L	U
606-20-2	2,6-Dinitrotoluene	B2663-5068	0.78	0.78	ug/L	U
91-58-7	2-Chloronaphthalene	B2663-5068	0.79	0.79	ug/L	U
95-57-8	2-Chlorophenol	B2663-5068	0.66	0.66	ug/L	U
91-57-6	2-Methylnaphthalene	B2663-5068	0.68	0.68	ug/L	U
95-48-7	2-Methylphenol	B2663-5068	0.46	0.46	ug/L	U
88-74-4	2-Nitroaniline	B2663-5068	0.37	0.37	ug/L	U
88-75-5	2-Nitrophenol	B2663-5068	0.83	0.83	ug/L	U
106-44-5	3+4-Methylphenol	B2663-5068	0.41	0.41	ug/L	U
91-94-1	3,3'-Dichlorobenzidine	B2663-5068	1.05	1.05	ug/L	U
99-09-2	3-Nitroaniline	B2663-5068	0.23	0.23	ug/L	U
534-52-1	4,6-Dinitro-2-methylphenol	B2663-5068	0.42	0.42	ug/L	U
101-55-3	4-Bromophenyl phenyl ether	B2663-5068	0.94	0.94	ug/L	U
59-50-7	4-Chloro-3-methylphenol	B2663-5068	0.59	0.59	ug/L	U
106-47-8	4-Chloroaniline	B2663-5068	0.39	0.39	ug/L	U
7005-72-3	4-Chlorophenyl phenyl ether	B2663-5068	0.87	0.87	ug/L	U
100-01-6	4-Nitroaniline	B2663-5068	1.22	1.22	ug/L	U
100-02-7	4-Nitrophenol	B2663-5068	1.92	1.92	ug/L	U
83-32-9	Acenaphthene	B2663-5068	0.81	0.81	ug/L	U
208-96-8	Acenaphthylene	B2663-5068	0.72	0.72	ug/L	U
62-53-3	Aniline	B2663-5068	0.33	0.33	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
120-12-7	Anthracene	B2663-5068	0.85	0.85	ug/L	U
92-87-5	Benzidine	B2663-5068	29.6	29.6	ug/L	U
56-55-3	Benzo(a)anthracene	B2663-5068	0.92	0.92	ug/L	U
50-32-8	Benzo(a)pyrene	B2663-5068	0.93	0.93	ug/L	U
205-99-2	Benzo(b)fluoranthene	B2663-5068	0.91	0.91	ug/L	U
191-24-2	Benzo(g,h,i)perylene	B2663-5068	1.02	1.02	ug/L	U
207-08-9	Benzo(k)fluoranthene	B2663-5068	1.38	1.38	ug/L	U
65-85-0	Benzoic acid	B2663-5068	8.53	8.53	ug/L	U
100-51-6	Benzyl alcohol	B2663-5068	0.67	0.67	ug/L	U
85-68-7	Butyl benzyl phthalate	B2663-5068	0.69	0.69	ug/L	U
86-74-8	Carbazole	B2663-5068	1.04	1.04	ug/L	U
218-01-9	Chrysene	B2663-5068	1.12	1.12	ug/L	U
	Cresols	B2663-5068	0.87	0.87	ug/L	U
84-74-2	Di-n-butyl phthalate	B2663-5068	0.95	**2.48**	ug/L	J
117-84-0	Di-n-octyl phthalate	B2663-5068	1.22	1.22	ug/L	U
53-70-3	Dibenz(a,h)anthracene	B2663-5068	1.12	1.12	ug/L	U
132-64-9	Dibenzofuran	B2663-5068	0.68	0.68	ug/L	U
84-66-2	Diethyl phthalate	B2663-5068	0.88	0.88	ug/L	U
131-11-3	Dimethyl phthalate	B2663-5068	0.85	0.85	ug/L	U
206-44-0	Fluoranthene	B2663-5068	0.97	0.97	ug/L	U
86-73-7	Fluorene	B2663-5068	0.83	0.83	ug/L	U
118-74-1	Hexachlorobenzene	B2663-5068	0.95	0.95	ug/L	U
87-68-3	Hexachlorobutadiene	B2663-5068	0.83	0.83	ug/L	U
77-47-4	Hexachlorocyclopentadiene	B2663-5068	2.71	2.71	ug/L	U
67-72-1	Hexachloroethane	B2663-5068	0.66	0.66	ug/L	U
193-39-5	Indeno(1,2,3-cd)pyrene	B2663-5068	1.02	1.02	ug/L	U
78-59-1	Isophorone	B2663-5068	0.47	0.47	ug/L	U
621-64-7	N-Nitrosodi-n-propylamine	B2663-5068	0.55	0.55	ug/L	U
62-75-9	N-Nitrosodimethylamine	B2663-5068	0.75	0.75	ug/L	U
86-30-6	N-Nitrosodiphenylamine	B2663-5068	1.13	1.13	ug/L	U
91-20-3	Naphthalene	B2663-5068	0.83	0.83	ug/L	U
98-95-3	Nitrobenzene	B2663-5068	0.76	0.76	ug/L	U

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Semivolatile Compounds - EPA 8270C

Sample: 1005123-4
Client Sample ID: GW-4 @ 40-42' Collected: 5/10/2010
Matrix: Liquid Type: Grab
Remarks:
Analyzed Date: 5/11/2010
Preparation Date(s) : 5/11/2010

Analytical Results

Cas No	Analyte	File ID	MDL	Concentration	Units	Q
87-86-5	Pentachlorophenol	B2663-5068	0.73	0.73	ug/L	U
85-01-8	Phenanthrene	B2663-5068	0.94	0.94	ug/L	U
108-95-2	Phenol	B2663-5068	0.32	0.32	ug/L	U
129-00-0	Pyrene	B2663-5068	0.84	0.84	ug/L	U
110-86-1	Pyridine	B2663-5068	0.40	0.40	ug/L	U
111-91-1	bis(2-Chloroethoxy)methane	B2663-5068	0.80	0.80	ug/L	U
111-44-4	bis(2-Chloroethyl)ether	B2663-5068	0.70	0.70	ug/L	U
108-60-1	bis(2-Chloroisopropyl)ether	B2663-5068	0.60	0.60	ug/L	U
117-81-7	bis(2-Ethylhexyl)phthalate	B2663-5068	1.44	1.44	ug/L	U

Surrogate Results

Cas No	Analyte	File ID	% Recovery	QC Limits	Q
118-76-6	2,4,6-TRIBROMOPHENOL	B2663-5068	94.7 %	(10 - 123)	
321-60-8	2-FLUOROBIPHENYL	B2663-5068	67.1 %	(43 - 116)	
367-12-4	2-FLUOROPHENOL	B2663-5068	27.6 %	(21 - 110)	
4165-60-0	NITROBENZENE-D5	B2663-5068	60.8 %	(35 - 114)	
13127-88-3	PHENOL-D6	B2663-5068	18.0 %	(10 - 110)	
1718-51-0	TERPHENYL-D14	B2663-5068	80.8 %	(33 - 141)	

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

Case Narrative

EPA 8260 VOLATILE ANALYSIS:

The following compounds were calibrated at 25, 50, 100,
150 and 200 ppb levels in the initial calibration curve:
Acetone
2-Butanone
4-Methyl-2-pentanone
2-Hexanone

M&P-Xylenes and 2-Chloroethylvinylether were calibrated at 10, 40, 100, 200 and
300 ppb levels.
Acrolein/Acrylonitrile were calibrated at 50,100,150,200 and 250 ppb levels.
Tert Butyl Alcohol (TBA) was calibrated at 50,200,500,1000 and 1500 ppb levels.

All other compounds were calibrated at 5, 20, 50, 100 and 150 ppb levels.

Environmental Testing Laboratories, Inc.
208 Route 109, Farmingdale NY 11735
Phone - 631-249-1456 Fax - 631-249-8344

5/11/2010

ORGANIC METHOD QUALIFIERS

Q - Qualifier - specified entries and their meanings are as follows:

U - The analytical result is not detected above the Method Detection Limit (MDL). All MDL's are lower than the lowest calibration standard concentration.

J - Indicates an estimated value. The concentration reported was between the Method Detection Limit (MDL) and the Practical Quantitation Limit (PQL).

B - The analyte was found in the associated method blank as well as the sample. It indicates possible/probable blank contamination and warns the data user to take appropriate action.

E - The concentration of the analyte exceeded the calibration range of the instrument.

D - This flag indicates a system monitoring compound diluted out.

INORGANIC METHOD QUALIFIERS

C - (Concentration) qualifiers are as follows:

B - Entered if the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL) but greater than or equal to the Method Detection Limit (MDL).

U - Entered when the analyte was analyzed for, but not detected above the Method Detection Limit (MDL) which is less than the lowest calibration standard concentration.

Q - Qualifier specific entries and their meanings are as follows:

E - Reported value is estimated because of the presence of interferences.

M - (Method) qualifiers are as follows:

A - Flame AA
AS - Semi-automated Spectrophotometric
AV - Automated Cold Vapor AA
C - Manual Spectrophotometric
F - Furnace AA
P - ICP
T - Titrimetric

OTHER QUALIFIERS

ND - Not Detected

New York State Department of Environmental Conservation
Spill Prevention and Response, Region One Headquarters
50 Circle Road - SUNY
Stony Brook, NY 11790-3409
Phone: (631) 444-0323 • FAX: (631) 444-0328
Website: http://www.dec.ny.gov

Joe Martens
Commissioner

April 7, 2014

Rita DeBoer
Assistant General Counsel
Tribune Company
435 N. Michigan Avenue, 6th Floor
Chicago, IL 60611

Re: Spill #12-03029, Newsday, 235 Pinelawn Rd., Melville, NY

Dear Ms. DeBoer:

The Department has reviewed the records and data submitted by you regarding the tank test failure at the above referenced site. Based on such review, the Department determined that you have completed all necessary actions, and no further activities are necessary.

Nothing contained herein shall be construed as barring, diminishing, or in any way limiting Department's authority under the Navigation Law or the Environmental Conservation Law, including the authority to require additional remedial work, if necessary.

Should you have any questions concerning this matter, you may call me at (631) 444-0324 or e-mail me at hmcirrit@gw.dec.state.ny.us.

Sincerely,
Hugh Cirrito

Hugh Cirrito, PE
Environmental Engineer 2

cc: K. Gomez, NYSDEC

Environmental Resources Management

105 Maxess Road
Suite 316
Melville, NY 11747
(631) 756-8900
(631) 756-8901 (fax)
http://www.erm.com

4 April 2014

Mr. Hugh Cirrito
NYSDEC
50 Circle Road
Stony Brook, NY 12561

Re: Spill Case No. 1203029
Spill Closure Report
235 Pinelawn Road, Melville, NY

Dear Mr. Cirrito:

On behalf of Tribune Company (Tribune), ERM Consulting & Engineering, Inc. (ERM) has prepared this summary letter report to document the investigation, and abandonment of two (2) 25,000-gallon fuel oil underground storage tanks (USTs) located at 235 Pinelawn Road, Melville, NY (the Property).

PROJECT BACKGROUND

On 15 November 2011, tightness testing was performed on adjacent Tank Nos. 6 & 7 located in a loading dock area south of the main building. A site plan showing the tank locations is provided as Figure 1. Both USTs were registered with the New York State Department of Environmental Conservation (NYSDEC) through the Suffolk County Department of Health Services (SCDOHS).

Tank No. 6 tested "tight" while Tank No. 7 failed the tightness test and was immediately pumped out. The NYSDEC was notified and NYSDEC Spill No. 1203029 was assigned. Subsequently, Tank No. 7 was cleaned and 4 soil samples were collected from beneath the tank invert and analyzed for Volatile Organic Compounds (VOCs) and Semi-VOCs (SVOC) on 25 October 2012. The analytical results were provided to the NYSDEC and authorization was given to abandon Tank No. 7 on 14 November 2012 (Appendix A). The sampling locations are identified in Figure 1 and a summary of the analytical results from the 25 October 2012 sampling event are provided as Table 1. A complete analytical data report is provided as Appendix B.

Although Tank No. 6 had tested tight, Tribune elected to preemptively abandon this tank and replace it with an above ground storage tank (AST). On 26 June 2013, an abandonment request for both tanks was submitted to SCDOHS which was subsequently approved by the SCDOHS on 13 September 2013. Copies of the abandonment request and approval letters are provided as Appendix C.

ABANDONMENT ACTIVITIES

Tank No. 6 remained in service for emergency generator fuel storage until early 2014 when it was replaced by an AST. Tank No. 6 was emptied on 7 March 2014 so that it could be abandoned along with Tank No. 7.

On 17 March 2014, ERM and its UST contractor, Metro Environmental Contracting Corporation (Metro) mobilized to the Site to abandon the two tanks. Metro Environmental vacuumed out the residual product and cleaned the interior of Tank No. 6. Three equidistant saw cuts were then made in the concrete above each tank and the soil was excavated to expose the tank tops. The tanks were then cut at each location to expose their interiors, and the vent pipes, fill ports and tank alarms were removed.

On 20 March 2014, Mr. Mike Seaman from SCDOHS inspected the tanks prior to backfilling to confirm that their interiors were clean and ready for abandonment. The SCDOHS was satisfied with the condition of the tanks and authorized the abandonment. The tanks were subsequently abandoned with 296-tons of clean sand. The bills of lading for the sand from 110 Sand Company is provided in Appendix D.

On 21 March 2014, Mr. Seaman (SCDOHS) returned to the Site to observe the backfilled tanks and issued the completed Tank Removal Checklist, which is provided in Appendix E. The open excavations were then backfilled using clean sand installed in compacted lifts, and finished to grade with 6-inches of 4,000 psi-rated concrete. The concrete patches were keyed into the existing pad/reinforced with rebar and steel mesh. The vent line for each tank was cut flush to grade and filled with concrete. The fill ports were directly atop each UST and were removed when the tanks were cut open and accessed. Pictures documenting the tank closure and restoration work are provided in Appendix F.

Waste Disposal

A total of 10 cubic yards of un-impacted concrete and soil from above the tanks was excavated and transported to Con Strux in Lindenhurst, NY, for recycling. Approximately 300 gallons of combined tank sludge and wash water were collected in the vacuum truck and transported to Advanced Waste and Water Technology in Farmingdale, NY. The adsorbant (SpeedyDry) used to clean the residual fuel oil in Tank No. 6 was collected in one (1) 55-gallon drum and transported to Republic Environmental Systems in Hatfield, PA, for disposal. The associated waste manifests are provided in Appendix G.

CONCLUSIONS AND RECOMMENDATIONS

The tank abandonment activities were completed under the supervision of SCDOHS and in accordance with all NYSDEC and SCDOHS regulations. On behalf of Tribune, ERM respectfully requests that NYSDEC Spill Case No. 1203029 be closed as soon as possible.

We look forward to your expeditious approval of this closure request. If you have any additional questions or comments, please do not hesitate to contact me at (631) 756-8900.

Sincerely,



Eugene Gabay
Senior Consultant

Attachments

cc: Chris Wong, SCDOH
Rita DeBoer, Tribune
Mark Bilut, McDermott Will & Emery LLP

FIGURE



Legend

- Tank Excavation
- Soil Sample Location

0 20 40

GRAPHIC SCALE IN FEET

N

TITLE

SITE PLAN
235 PINELAWN ROAD
MELVILLE, NY 11747

PREPARED FOR

TRIBUNE COMPANY

Environmental Resources Management

FIGURE 1

DRAWN BY	SCALE	DATE	JOB NO.
EMF	GRAPHIC	04/01/2014	0177133

R:\Scout\Projects\Tribune Company\CAD\2014-03 - Tribune - Site Plan.dwg (04/01/2014 - 2:27pm Melville)

TABLE

TABLE 1
Tank No. 6 Soil Sampling Results Summary
Spill No. 1203029
235 Pinelawn Road
Melville, New York

Client Sample ID:		NY CP-51 Table 2 - Gasoline Contaminated	NY CP-51 Table 3 - Fuel Oil Contaminated	TRIB-A	TRIB-B	TRIB-C	TRIB-D
Lab Sample ID:				JB20289-1	JB20289-2	JB20289-3	JB20289-4
Date Sampled:		Soil (NYDEC CP-51 10/10)	Soil (NYDEC CP-51 10/10)	10/25/2012	10/25/2012	10/25/2012	10/25/2012
Matrix:				Soil	Soil	Soil	Soil
GC/MS Volatiles (SW846 8260B)							
Benzene	ug/kg	60	60	ND (0.11)	ND (0.11)	0.42 J	ND (0.13)
n-Butylbenzene	ug/kg	12000	12000	ND (0.11)	ND (0.11)	ND (0.17)	ND (0.12)
sec-Butylbenzene	ug/kg	11000	11000	ND (0.11)	ND (0.11)	ND (0.18)	ND (0.12)
tert-Butylbenzene	ug/kg	5900	5900	ND (0.28)	ND (0.28)	ND (0.45)	ND (0.32)
Ethylbenzene	ug/kg	1000	1000	ND (0.25)	ND (0.25)	ND (0.41)	ND (0.28)
Isopropylbenzene	ug/kg	2300	2300	ND (0.072)	ND (0.070)	ND (0.11)	ND (0.080)
p-Isopropyltoluene	ug/kg	10000	10000	ND (0.10)	ND (0.098)	ND (0.16)	ND (0.11)
Methyl Tert Butyl Ether	ug/kg	930	-	ND (0.23)	ND (0.22)	ND (0.36)	ND (0.25)
Naphthalene	ug/kg	12000	12000	ND (0.12)	ND (0.11)	ND (0.19)	ND (0.13)
n-Propylbenzene	ug/kg	3900	3900	ND (0.11)	ND (0.11)	ND (0.18)	ND (0.13)
Toluene	ug/kg	700	700	ND (0.10)	ND (0.099)	ND (0.16)	ND (0.11)
1,2,4-Trimethylbenzene	ug/kg	3600	3600	ND (0.20)	ND (0.20)	ND (0.32)	ND (0.23)
1,3,5-Trimethylbenzene	ug/kg	8400	8400	ND (0.15)	ND (0.15)	ND (0.25)	ND (0.17)
m,p-Xylene	ug/kg	260	260	ND (0.17)	ND (0.16)	ND (0.27)	ND (0.19)
o-Xylene	ug/kg	260	260	ND (0.13)	ND (0.13)	ND (0.21)	ND (0.15)
Xylene (total)	ug/kg	260	260	ND (0.13)	ND (0.13)	ND (0.21)	ND (0.15)
GC/MS Semi-volatiles (SW846 8270D)							
Acenaphthene	ug/kg	-	20000	ND (8.7)	22.7 J	22.3 J	ND (11)
Acenaphthylene	ug/kg	-	100000	ND (9.6)	ND (11)	ND (11)	ND (12)
Anthracene	ug/kg	-	100000	ND (11)	490	503	ND (13)
Benzo(a)anthracene	ug/kg	-	1000	ND (9.8)	**1060**	**1400**	41
Benzo(a)pyrene	ug/kg	-	1000	ND (9.2)	497	615	18.1 J
Benzo(b)fluoranthene	ug/kg	-	1000	ND (10)	965	806	21.3 J
Benzo(g,h,i)perylene	ug/kg	-	100000	ND (11)	284	281	ND (14)
Benzo(k)fluoranthene	ug/kg	-	800	ND (11)	512	489	ND (14)
Chrysene	ug/kg	-	1000	ND (10)	**1070**	**1260**	33.4 J
Dibenzo(a,h)anthracene	ug/kg	-	330	ND (10)	118	116	ND (13)
Fluoranthene	ug/kg	-	100000	22.6 J	3210	3910	106
Fluorene	ug/kg	-	30000	ND (9.8)	35.5	35.5	ND (12)
Indeno(1,2,3-cd)pyrene	ug/kg	-	500	ND (10)	302	278	ND (13)
Naphthalene	ug/kg	12000	12000	ND (8.2)	ND (9.1)	ND (9.4)	ND (10)
Phenanthrene	ug/kg	-	100000	17.5 J	1340	1340	26.2 J
Pyrene	ug/kg	-	100000	13.8 J	2150	2920	75.7
General Chemistry							
Solids, Percent	%	-	-	98	93.5	85.1	85.9

Compound Detected
Compound Exceeds Criteria

APPENDIX A
NYSDEC ABANDONMENT APPROVAL

Eugene Gabay

From: Hugh Cirrito <hmcirrit@gw.dec.state.ny.us>
Sent: Wednesday, November 14, 2012 11:25 AM
To: Eugene Gabay
Subject: Re: Spill No. 1203029_ Sample Results

Gene,

I have reviewed the submitted sample results. You may abandon the tank in place. Please inform me when the work is completed.

Hugh Cirrito, PE
Environmental Engineer 2
NYSDEC Spill Response
(631) 444-0324
(631) 444-0328 fax

>>> Eugene Gabay <Eugene.Gabay@erm.com> 11/14/2012 11:11 AM >>>
Hello Hugh,

As discussed, ERM drilled core holes at 4 locations in the spine of the tank in order to obtain soil samples. The soil samples were collected from the soil just below the tank and analyzed for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) via EPA methods 8260 and 8270 by a New York State Department of Health-certified laboratory. The laboratory results are attached for your review. ERM's intention is to abandon the tank in place. Once you have had a chance to review the data could you please call me to discuss? My number is listed at the bottom of this email.

Thanks,
Gene

Eugene Gabay
Environmental Resources Management (ERM)
40 Marcus Drive
Suite 200
Melville, New York 11747

T: +1 631 756-8900 (Main)
T: +1 631 756-8954(Direct)
F: +1 631 756-8901
C: +1 516 250-6155

eugene.gabay@erm.com

www.erm.com

This electronic mail message may contain information which is (a) LEGALLY PRIVILEGED, PROPRIETARY IN NATURE, OR OTHERWISE PROTECTED BY LAW FROM DISCLOSURE, and (b) intended only for the use of the Addressee (s) names herein. If you are not the Addressee(s), or the person responsible for delivering this to the Addressee (s), you are hereby notified that reading, copying, or distributing this message is prohibited. If you have received this electronic mail message in error, please contact us immediately at (617) 646-7800 and take the steps necessary to delete the message completely from your computer

system. Thank you,

Please visit ERM's web site: http://www.erm.com

APPENDIX B
LAB DATA

New Jersey
ACCUTEST LABORATORIES

03/27/14



Technical Report for

ERM, Inc.

Tribune, Pinelawn Avenue, Melville, NY

0177133

Accutest Job Number: JB20289

Sampling Date: 10/25/12

Report to:

ERM, Inc.

eugene.gabay@erm.com

ATTN: Eugene Gabay

Total number of pages in report: **20**

Test results contained within this data package meet the requirements of the National Environmental Laboratory Accreditation Program and/or state specific certification programs as applicable.

Nancy Cole
Laboratory Director

Client Service contact: Tammy McCloskey 732-329-0200

Certifications: NJ(12129), NY(10983), CA, CT, DE, FL, IL, IN, KS, KY, LA, MA, MD, MI, MT, NC, OH VAP (CL0056), PA, RI, SC, TN, VA, WV, DoD ELAP (L-A-B L2248)

This report shall not be reproduced, except in its entirety, without the written approval of Accutest Laboratories. Test results relate only to samples analyzed.

Accutest Laboratories is the sole authority for authorizing edits or modifications to this document. Unauthorized modification of this report is strictly prohibited.

Sections: 1 2 3 4 5

Table of Contents

-1-

Section 1: Sample Summary **3**
Section 2: Case Narrative/Conformance Summary **4**
Section 3: Summary of Hits **6**
Section 4: Sample Results **8**
4.1: JB20289-1: TRIB-A 9
4.2: JB20289-2: TRIB-B 11
4.3: JB20289-3: TRIB-C 13
4.4: JB20289-4: TRIB-D 15
Section 5: Misc. Forms **17**
5.1: Chain of Custody 18

Sample Summary

ERM, Inc.

Job No: JB20289

Tribune, Pinelawn Avenue, Melville, NY
Project No: 0177133

Sample Number	Collected Date	Time	By	Received	Matrix Code	Type	Client Sample ID
JB20289-1	10/25/12	13:20	JM	10/26/12	SO	Soil	TRIB-A
JB20289-2	10/25/12	13:28	JM	10/26/12	SO	Soil	TRIB-B
JB20289-3	10/25/12	13:34	JM	10/26/12	SO	Soil	TRIB-C
JB20289-4	10/25/12	13:40	JM	10/26/12	SO	Soil	TRIB-D

Soil samples reported on a dry weight basis unless otherwise indicated on result page.

CASE NARRATIVE / CONFORMANCE SUMMARY

Client:	ERM, Inc.	**Job No**	JB20289
Site:	Tribune, Pinelawn Avenue, Melville, NY	**Report Date**	11/12/2012 4:09:42 P

On 10/26/2012, 4 Sample(s), 0 Trip Blank(s) and 0 Field Blank(s) were received at Accutest Laboratories at a temperature of 3 C. Samples were intact and chemically preserved, unless noted below. An Accutest Job Number of JB20289 was assigned to the project. Laboratory sample ID, client sample ID and dates of sample collection are detailed in the report's Results Summary Section.

Specified quality control criteria were achieved for this job except as noted below. For more information, please refer to the analytical results and QC summary pages.

Volatiles by GCMS By Method SW846 8260B

Matrix: SO **Batch ID:** VO5784

- All samples were analyzed within the recommended method holding time.
- All method blanks for this batch meet method specific criteria.
- Sample(s) JB20133-2MS, JB20133-2MSD were used as the QC samples indicated.

Extractables by GCMS By Method SW846 8270D

Matrix: SO **Batch ID:** OP61052

- All samples were extracted within the recommended method holding time.
- All method blanks for this batch meet method specific criteria.
- Sample(s) JB20508-1MS, JB20508-1MSD were used as the QC samples indicated.
- Matrix Spike Recovery(s) for Acenaphthylene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- Matrix Spike Duplicate Recovery(s) for Acenaphthylene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- Matrix Spike Recovery(s) for Acenaphthene, Anthracene, Benzo(a)anthracene, Benzo(a)pyrene, Benzo(b)fluoranthene, Benzo(g,h,i)perylene, Benzo(k)fluoranthene, Chrysene, Dibenzo(a,h)anthracene, Fluoranthene, Fluorene, Indeno(1,2,3-cd)pyrene, Naphthalene, Phenanthrene, Pyrene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- JB20289-4: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-3: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-3: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-2: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-1: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

Wet Chemistry By Method SM2540 G-97

Matrix: SO **Batch ID:** GN74854

- The data for SM2540 G-97 meets quality control requirements.

Accutest certifies that data reported for samples received, listed on the associated custody chain or analytical task order, were produced to specifications meeting Accutest's Quality System precision, accuracy and completeness objectives except as noted.

Estimated non-standard method measurement uncertainty data is available on request, based on quality control bias and implicit for standard methods. Acceptable uncertainty requires tested parameter quality control data to meet method criteria.

Accutest Laboratories is not responsible for data quality assumptions if partial reports are used and recommends that this report be used in its entirety. Data release is authorized by Accutest Laboratories indicated via signature on the report cover

Summary of Hits

Job Number: JB20289
Account: ERM, Inc.
Project: Tribune, Pinelawn Avenue, Melville, NY
Collected: 10/25/12

Lab Sample ID / Analyte	Client Sample ID	Result/ Qual	RL	MDL	Units	Method
JB20289-1	**TRIB-A**					
Fluoranthene [a]		22.6 J	30	13	ug/kg	SW846 8270D
Phenanthrene [a]		17.5 J	30	14	ug/kg	SW846 8270D
Pyrene [a]		13.8 J	30	12	ug/kg	SW846 8270D
JB20289-2	**TRIB-B**					
Acenaphthene [a]		22.7 J	33	9.7	ug/kg	SW846 8270D
Anthracene [a]		490	33	12	ug/kg	SW846 8270D
Benzo(a)anthracene [a]		1060	33	11	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		497	33	10	ug/kg	SW846 8270D
Benzo(b)fluoranthene [a]		965	33	11	ug/kg	SW846 8270D
Benzo(g,h,i)perylene [a]		284	33	12	ug/kg	SW846 8270D
Benzo(k)fluoranthene [a]		512	33	13	ug/kg	SW846 8270D
Chrysene [a]		1070	33	11	ug/kg	SW846 8270D
Dibenzo(a,h)anthracene [a]		118	33	11	ug/kg	SW846 8270D
Fluoranthene [a]		3210	33	15	ug/kg	SW846 8270D
Fluorene [a]		35.5	33	11	ug/kg	SW846 8270D
Indeno(1,2,3-cd)pyrene [a]		302	33	12	ug/kg	SW846 8270D
Phenanthrene [a]		1340	33	15	ug/kg	SW846 8270D
Pyrene [a]		2150	33	13	ug/kg	SW846 8270D
JB20289-3	**TRIB-C**					
Benzene		0.42 J	1.5	0.18	ug/kg	SW846 8260B
Acenaphthene [a]		22.3 J	34	10	ug/kg	SW846 8270D
Anthracene [a]		503	34	12	ug/kg	SW846 8270D
Benzo(a)anthracene [a]		1400	34	11	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		615	34	10	ug/kg	SW846 8270D
Benzo(b)fluoranthene [a]		806	34	11	ug/kg	SW846 8270D
Benzo(g,h,i)perylene [a]		281	34	13	ug/kg	SW846 8270D
Benzo(k)fluoranthene [a]		489	34	13	ug/kg	SW846 8270D
Chrysene [a]		1260	34	12	ug/kg	SW846 8270D
Dibenzo(a,h)anthracene [a]		116	34	12	ug/kg	SW846 8270D
Fluoranthene [a]		3910	69	30	ug/kg	SW846 8270D
Fluorene [a]		35.5	34	11	ug/kg	SW846 8270D
Indeno(1,2,3-cd)pyrene [a]		278	34	12	ug/kg	SW846 8270D
Phenanthrene [a]		1340	34	16	ug/kg	SW846 8270D
Pyrene [a]		2920	34	13	ug/kg	SW846 8270D
JB20289-4	**TRIB-D**					
Benzo(a)anthracene [a]		41.0	37	12	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		18.1 J	37	11	ug/kg	SW846 8270D

Summary of Hits

Job Number: JB20289
Account: ERM, Inc.
Project: Tribune, Pinelawn Avenue, Melville, NY
Collected: 10/25/12

Lab Sample ID / Analyte	Client Sample ID	Result/ Qual	RL	MDL	Units	Method
Benzo(b)fluoranthene [a]		21.3 J	37	12	ug/kg	SW846 8270D
Chrysene [a]		33.4 J	37	13	ug/kg	SW846 8270D
Fluoranthene [a]		106	37	16	ug/kg	SW846 8270D
Phenanthrene [a]		26.2 J	37	17	ug/kg	SW846 8270D
Pyrene [a]		75.7	37	14	ug/kg	SW846 8270D

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

New Jersey ACCUTEST LABORATORIES

Sample Results

Report of Analysis

Report of Analysis

Client Sample ID: TRIB-A
Lab Sample ID: JB20289-1
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 98.0

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131253.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.3 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	0.96	0.11	ug/kg	
104-51-8	n-Butylbenzene	ND	4.8	0.11	ug/kg	
135-98-8	sec-Butylbenzene	ND	4.8	0.11	ug/kg	
98-06-6	tert-Butylbenzene	ND	4.8	0.28	ug/kg	
100-41-4	Ethylbenzene	ND	0.96	0.25	ug/kg	
98-82-8	Isopropylbenzene	ND	4.8	0.072	ug/kg	
99-87-6	p-Isopropyltoluene	ND	4.8	0.10	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	0.96	0.23	ug/kg	
91-20-3	Naphthalene	ND	4.8	0.12	ug/kg	
103-65-1	n-Propylbenzene	ND	4.8	0.11	ug/kg	
108-88-3	Toluene	ND	0.96	0.10	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	4.8	0.20	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	4.8	0.15	ug/kg	
	m,p-Xylene	ND	0.96	0.17	ug/kg	
95-47-6	o-Xylene	ND	0.96	0.13	ug/kg	
1330-20-7	Xylene (total)	ND	0.96	0.13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	104%		70-130%
17060-07-0	1,2-Dichloroethane-D4	91%		70-122%
2037-26-5	Toluene-D8	110%		81-127%
460-00-4	4-Bromofluorobenzene	103%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-A
Lab Sample ID: JB20289-1
Matrix: SO - Soil
Method: SW846 8270D SW846 3550C
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 98.0

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45391.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	34.0 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	ND	30	8.7	ug/kg	
208-96-8	Acenaphthylene	ND	30	9.6	ug/kg	
120-12-7	Anthracene	ND	30	11	ug/kg	
56-55-3	Benzo(a)anthracene	ND	30	9.8	ug/kg	
50-32-8	Benzo(a)pyrene	ND	30	9.2	ug/kg	
205-99-2	Benzo(b)fluoranthene	ND	30	10	ug/kg	
191-24-2	Benzo(g,h,i)perylene	ND	30	11	ug/kg	
207-08-9	Benzo(k)fluoranthene	ND	30	11	ug/kg	
218-01-9	Chrysene	ND	30	10	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	ND	30	10	ug/kg	
206-44-0	Fluoranthene	22.6	30	13	ug/kg	J
86-73-7	Fluorene	ND	30	9.8	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	ND	30	10	ug/kg	
91-20-3	Naphthalene	ND	30	8.2	ug/kg	
85-01-8	Phenanthrene	17.5	30	14	ug/kg	J
129-00-0	Pyrene	13.8	30	12	ug/kg	J

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	67%		21-122%
321-60-8	2-Fluorobiphenyl	58%		30-117%
1718-51-0	Terphenyl-d14	74%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-B
Lab Sample ID: JB20289-2
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 93.5

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131254.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.7 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	0.94	0.11	ug/kg	
104-51-8	n-Butylbenzene	ND	4.7	0.11	ug/kg	
135-98-8	sec-Butylbenzene	ND	4.7	0.11	ug/kg	
98-06-6	tert-Butylbenzene	ND	4.7	0.28	ug/kg	
100-41-4	Ethylbenzene	ND	0.94	0.25	ug/kg	
98-82-8	Isopropylbenzene	ND	4.7	0.070	ug/kg	
99-87-6	p-Isopropyltoluene	ND	4.7	0.098	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	0.94	0.22	ug/kg	
91-20-3	Naphthalene	ND	4.7	0.11	ug/kg	
103-65-1	n-Propylbenzene	ND	4.7	0.11	ug/kg	
108-88-3	Toluene	ND	0.94	0.099	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	4.7	0.20	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	4.7	0.15	ug/kg	
	m,p-Xylene	ND	0.94	0.16	ug/kg	
95-47-6	o-Xylene	ND	0.94	0.13	ug/kg	
1330-20-7	Xylene (total)	ND	0.94	0.13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	105%		70-130%
17060-07-0	1,2-Dichloroethane-D4	92%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	103%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-B		
Lab Sample ID:	JB20289-2	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8270D SW846 3550C	**Percent Solids:**	93.5
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45392.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	32.1 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	22.7	33	9.7	ug/kg	J
208-96-8	Acenaphthylene	ND	33	11	ug/kg	
120-12-7	Anthracene	490	33	12	ug/kg	
56-55-3	Benzo(a)anthracene	1060	33	11	ug/kg	
50-32-8	Benzo(a)pyrene	497	33	10	ug/kg	
205-99-2	Benzo(b)fluoranthene	965	33	11	ug/kg	
191-24-2	Benzo(g,h,i)perylene	284	33	12	ug/kg	
207-08-9	Benzo(k)fluoranthene	512	33	13	ug/kg	
218-01-9	Chrysene	1070	33	11	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	118	33	11	ug/kg	
206-44-0	Fluoranthene	3210	33	15	ug/kg	
86-73-7	Fluorene	35.5	33	11	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	302	33	12	ug/kg	
91-20-3	Naphthalene	ND	33	9.1	ug/kg	
85-01-8	Phenanthrene	1340	33	15	ug/kg	
129-00-0	Pyrene	2150	33	13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	70%		21-122%
321-60-8	2-Fluorobiphenyl	64%		30-117%
1718-51-0	Terphenyl-d14	77%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-C		
Lab Sample ID:	JB20289-3	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8260B SW846 5035	**Percent Solids:**	85.1
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131255.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	3.8 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	0.42	1.5	0.18	ug/kg	J
104-51-8	n-Butylbenzene	ND	7.7	0.17	ug/kg	
135-98-8	sec-Butylbenzene	ND	7.7	0.18	ug/kg	
98-06-6	tert-Butylbenzene	ND	7.7	0.45	ug/kg	
100-41-4	Ethylbenzene	ND	1.5	0.41	ug/kg	
98-82-8	Isopropylbenzene	ND	7.7	0.11	ug/kg	
99-87-6	p-Isopropyltoluene	ND	7.7	0.16	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	1.5	0.36	ug/kg	
91-20-3	Naphthalene	ND	7.7	0.19	ug/kg	
103-65-1	n-Propylbenzene	ND	7.7	0.18	ug/kg	
108-88-3	Toluene	ND	1.5	0.16	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	7.7	0.32	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	7.7	0.25	ug/kg	
	m,p-Xylene	ND	1.5	0.27	ug/kg	
95-47-6	o-Xylene	ND	1.5	0.21	ug/kg	
1330-20-7	Xylene (total)	ND	1.5	0.21	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	106%		70-130%
17060-07-0	1,2-Dichloroethane-D4	96%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	104%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range

J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-C		
Lab Sample ID:	JB20289-3	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8270D SW846 3550C	**Percent Solids:**	85.1
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45393.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2 [a]	3E45398.D	2	11/08/12	OYA	11/07/12	OP61052	E3E1976

	Initial Weight	Final Volume
Run #1	34.2 g	1.0 ml
Run #2	34.2 g	1.0 ml

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	22.3	34	10	ug/kg	J
208-96-8	Acenaphthylene	ND	34	11	ug/kg	
120-12-7	Anthracene	503	34	12	ug/kg	
56-55-3	Benzo(a)anthracene	1400	34	11	ug/kg	
50-32-8	Benzo(a)pyrene	615	34	10	ug/kg	
205-99-2	Benzo(b)fluoranthene	806	34	11	ug/kg	
191-24-2	Benzo(g,h,i)perylene	281	34	13	ug/kg	
207-08-9	Benzo(k)fluoranthene	489	34	13	ug/kg	
218-01-9	Chrysene	1260	34	12	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	116	34	12	ug/kg	
206-44-0	Fluoranthene	3910 [b]	69	30	ug/kg	
86-73-7	Fluorene	35.5	34	11	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	278	34	12	ug/kg	
91-20-3	Naphthalene	ND	34	9.4	ug/kg	
85-01-8	Phenanthrene	1340	34	16	ug/kg	
129-00-0	Pyrene	2920	34	13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	61%	59%	21-122%
321-60-8	2-Fluorobiphenyl	56%	60%	30-117%
1718-51-0	Terphenyl-d14	73%	84%	31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
(b) Result is from Run# 2

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-D		
Lab Sample ID:	JB20289-4	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8260B SW846 5035	**Percent Solids:**	85.9
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131256.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.4 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	1.1	0.13	ug/kg	
104-51-8	n-Butylbenzene	ND	5.4	0.12	ug/kg	
135-98-8	sec-Butylbenzene	ND	5.4	0.12	ug/kg	
98-06-6	tert-Butylbenzene	ND	5.4	0.32	ug/kg	
100-41-4	Ethylbenzene	ND	1.1	0.28	ug/kg	
98-82-8	Isopropylbenzene	ND	5.4	0.080	ug/kg	
99-87-6	p-Isopropyltoluene	ND	5.4	0.11	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	1.1	0.25	ug/kg	
91-20-3	Naphthalene	ND	5.4	0.13	ug/kg	
103-65-1	n-Propylbenzene	ND	5.4	0.13	ug/kg	
108-88-3	Toluene	ND	1.1	0.11	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	5.4	0.23	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	5.4	0.17	ug/kg	
	m,p-Xylene	ND	1.1	0.19	ug/kg	
95-47-6	o-Xylene	ND	1.1	0.15	ug/kg	
1330-20-7	Xylene (total)	ND	1.1	0.15	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	105%		70-130%
17060-07-0	1,2-Dichloroethane-D4	93%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	104%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range

J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-D
Lab Sample ID: JB20289-4
Matrix: SO - Soil
Method: SW846 8270D SW846 3550C
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 85.9

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45394.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	31.2 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	ND	37	11	ug/kg	
208-96-8	Acenaphthylene	ND	37	12	ug/kg	
120-12-7	Anthracene	ND	37	13	ug/kg	
56-55-3	Benzo(a)anthracene	41.0	37	12	ug/kg	
50-32-8	Benzo(a)pyrene	18.1	37	11	ug/kg	J
205-99-2	Benzo(b)fluoranthene	21.3	37	12	ug/kg	J
191-24-2	Benzo(g,h,i)perylene	ND	37	14	ug/kg	
207-08-9	Benzo(k)fluoranthene	ND	37	14	ug/kg	
218-01-9	Chrysene	33.4	37	13	ug/kg	J
53-70-3	Dibenzo(a,h)anthracene	ND	37	13	ug/kg	
206-44-0	Fluoranthene	106	37	16	ug/kg	
86-73-7	Fluorene	ND	37	12	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	ND	37	13	ug/kg	
91-20-3	Naphthalene	ND	37	10	ug/kg	
85-01-8	Phenanthrene	26.2	37	17	ug/kg	J
129-00-0	Pyrene	75.7	37	14	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	71%		21-122%
321-60-8	2-Fluorobiphenyl	66%		30-117%
1718-51-0	Terphenyl-d14	90%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

New Jersey ACCUTEST LABORATORIES

Misc. Forms

Custody Documents and Other Forms

Includes the following where applicable:

- Chain of Custody

ACCUTEST LABORATORIES

CHAIN OF CUSTODY

2235 Route 130, Dayton, NJ 08810
Tel: 732-329-0200 FAX: 732-329-3499/3480
www.accutest.com

PAGE ___ OF ___

FED-EX Tracking #: | Bottle Order Control #:
Accutest Quote #: | Accutest Job #: JB20289

Client / Reporting Information

Company Name: ERM
Street Address: 40 MARCUS DR STE 200
City: MELVILLE State: NY Zip: 11747
Project Contact: EUGENE.GABAY@ERM.COM E-mail:
Phone #: 631 756 8900 Fax #: 8901
Sampler(s) Name(s): MADDOX Phone #:

Project Information

Project Name: TRIBUNE
Street: 235 PINELAWN
City: MELVILLE State: NY
Project #: 0177133
Client Purchase Order #:
Project Manager: GENE GABAY

Billing Information (if different from Report to)

Company Name:
Street Address:
City: State: Zip:
Attention:

Requested Analysis (see TEST CODE sheet)

8260 | 8270 | TCL/Metals

Matrix Codes

DW - Drinking Water
GW - Ground Water
WW - Water
SW - Surface Water
SO - Soil
SL - Sludge
SED-Sediment
OI - Oil
LIQ - Other Liquid
AIR - Air
SOL - Other Solid
WP - Wipe
FB-Field Blank
EB-Equipment Blank
RB- Rinse Blank
TB-Trip Blank

Accutest Sample #	Field ID / Point of Collection	MEOH Vial #	Collection Date	Collection Time	Sampled By	Matrix	# of bottles	Number of preserved bottles: HCl	NaOH	HNO3	H2SO4	NONE	DI Water	MEOH	ENCORE	8260	8270	TCL/Metals	LAB USE ONLY
-1	TRIB-A		10/25/12	1320	JMX	S	5					5				3	1	1	
-2	TRIB-B			1329			5					5				3	1	1	
-3	TRIB-C			1334			5					5				3	1	1	VOC 16
-4	TRIB-D		V	1340	V	V	5					5				3	1	1	8260 16 1461 4074

Turnaround Time (Business days)

- [X] Std. 15 Business Days
- [ ] Std. 10 Business Days (by Contract only)
- [ ] 10 Day RUSH
- [ ] 5 Day RUSH
- [ ] 3 Day EMERGENCY
- [ ] 2 Day EMERGENCY
- [ ] 1 Day EMERGENCY

Emergency & Rush T/A data available VIA Labnet

Approved By (Accutest PM) / Date:

Data Deliverable Information

- [ ] Commercial "A" (Level 1)
- [ ] Commercial "B" (Level 2)
- [ ] FULL T1 (Level 3+4)
- [ ] NJ Reduced
- [ ] Commercial "C"
- [ ] NYASP Category A
- [X] NYASP Category B
- [ ] State Forms
- [ ] EQD Format
- [ ] Other

Commercial "A" = Results Only
Commercial "B" = Results + QC Summary
NJ Reduced = Results + QC Summary + Partial Raw data

Comments / Special Instructions

3 Encores Picked

Sample Custody must be documented below each time samples change possession, including courier delivery.

	Relinquished by Sampler:	Date Time:	Received By:	Relinquished By:	Date Time:	Received By:
1		10/26/12 1035	1 Chris Law	2 Chris Law	10/26/12 1745	2
3	Relinquished by Sampler:	Date Time:	3	4 Relinquished By:	Date Time:	4 Received By:
5	Relinquished by:	Date Time:	5	Custody Seal # 3174	Intact / Not Intact	Preserved where applicable: On Ice: Cooler Temp: 3°C

JB20289: Chain of Custody
Page 1 of 3

Accutest Laboratories Sample Receipt Summary

Accutest Job Number: JB20289 **Client:** **Project:**

Date / Time Received: 10/26/2012 **Delivery Method:** **Airbill #'s:**

Cooler Temps (Initial/Adjusted): #1: (3/3); 0

Cooler Security	Y	or	N		Y	or	N
1. Custody Seals Present:	☑		☐	3. COC Present:	☑		☐
2. Custody Seals Intact:	☑		☐	4. Smpl Dates/Time OK	☑		☐

Cooler Temperature	Y	or	N
1. Temp criteria achieved:	☑		☐
2. Cooler temp verification:	Bar Therm		
3. Cooler media:	Ice (Bag)		
4. No. Coolers:	1		

Quality Control Preservation	Y	or	N	N/A
1. Trip Blank present / cooler:	☐		☑	☐
2. Trip Blank listed on COC:	☐		☑	☐
3. Samples preserved properly:	☑		☐	
4. VOCs headspace free:	☐		☐	☑

Sample Integrity - Documentation	Y	or	N
1. Sample labels present on bottles:	☑		☐
2. Container labeling complete:	☑		☐
3. Sample container label / COC agree:	☑		☐

Sample Integrity - Condition	Y	or	N
1. Sample recvd within HT:	☑		☐
2. All containers accounted for:	☑		☐
3. Condition of sample:	Intact		

Sample Integrity - Instructions	Y	or	N	N/A
1. Analysis requested is clear:	☑		☐	
2. Bottles received for unspecified tests	☐		☑	
3. Sufficient volume recvd for analysis:	☑		☐	
4. Compositing instructions clear:	☐		☐	☑
5. Filtering instructions clear:	☐		☐	☑

Comments

ACCUTEST LABORATORIES

Subject: Sample Storage – Tropical Storm

Date: November 2, 2012

To: Valued Clients

From: Phillip M. Worby
Director, Corporate Quality Assurance

As a result of the extraordinary damage from the Tropical Storm that hit the East Coast late Monday evening October 29, 2012, Accutest Laboratories Dayton, New Jersey had to temporarily suspend analytical operations until power could be restored.

While the laboratory did not sustain any physical damage, it was left without power as utility companies assessed the overall damage caused by the storm and as they continue restore power throughout the state.

Accutest Laboratories has endeavored to minimize the impact of the storm on lab operations. To that end, extra staff was brought in before the storm to work ahead and secure the building. After the storm, as soon as it was possible to safely bring staff in, external generators were put in place on storage refrigeration units to help maintain sample integrity in accordance with preservation requirements set by either the regulatory program or method specification.

Despite our efforts and planning, a storage temperature excursion above 6 degrees C. has been noted and documented. The affected analyte and/or test method is qualified in accordance with our quality system procedures and is indicated in the report.

To our valued clients, we appreciate your patience and understanding during this difficult period, and hope that your recovery efforts are also moving forward. We stand ready to help you with any and all sample needs as a result of this powerful storm.

JB20289: Chain of Custody
Page 3 of 3

APPENDIX C
SCDOHS ABANDONMENT
REQUEST AND APPLICATION

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES
APPLICATION FOR
CLOSURE OF UNDERGROUND STORAGE TANKS

Check #0013095 $200.00

OFFICIAL USE ONLY	File Reference Number	Facility Id. Number
	02,037	4-60974

Fac. Code	Rank	Sic Code	Hydro Zone	Article 7 Restricted	M S A	# # #	Insp. Zone	Multi-Occupied Building

Latitude Deg Min Sec	Longitude Deg Min Sec	PBS Reg	EPA Reg	Type of Petroleum Facility	Owner Type

Property Tax Map Number District 0400 Section 270 Block 100 Lot 241

Facility Name: Newsday Inc.

Physical Address	Community	State	Zip
235 Pinelawn Road	Melville	NY	11747

Property Owner's Name	Phone Number	Fax Number
Tribune Company	626-808-5728	

Mailing Address	Community	State	Zip
435 N. Michigan Avenue	Chicago	IL	60611

Contact Person	E-mail Address
Mark Anderson	manderson@tribune.com

Consultant/Agent (if applicable)	Phone Number	Fax Number
ERM	631-756-8900	

Mailing Address	Community	State	Zip
105 Maxess Road- Suite 316	Melville	NY	11747

Contact Person	E-mail Address
Eugene Gabay	eugene.gabay@erm.com

For **Abandonment Requests**, describe why that the tank(s) **cannot** be removed and provide supporting documentation (List **all** tanks to be removed and abandoned on the back of this form)

RECEIVED
JUL 5 2013
SUFFOLK COUNTY HEALTH SERVICES
Office of Pollution Control

I Certify that all information supplied hereon and in all attachments is true to the best of my knowledge.

Applicant Signature: _____ Print Name: Eugene Gabay Date: 6/26/13

☑ Abd. Request Approved ☐ Abd. Request Denied Date: 9/13/2013 Processed By: _____

See reverse side for required additional information.

Tank Information

Enter Information for all tank(s) to be removed or abandoned, below*:

SCDHS Tank #	Volume	Contents	Disposition (circle one)
SCDHS-6	25,000 gal	No. 2 Fuel Oil	Rem / Abd
SCDHS-7	25,000 gal	No. 2 Fuel Oil	Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd

*if additional space is needed, attach addendum.

Instructions

For All Requests, submit the following:

1. A site plan showing the location of the tank(s) as well as utilities and other structures that may interfere with removal. A sketch is acceptable with the initial application but a more detailed site plan may be required by the Department.

2. A check, per SCHDS Fee Schedule. $100/tank
3. Return the application to the address listed below. You will be contacted to schedule an appointment

For Abandonment Requests, in addition to the above, provide a submittal that includes the following:

1. For requests based upon Utility Infringement, provide diagram and photographs of the mark outs. Photos must indicate tank location.
2. For requests based upon Building Infringement, provide:
   (a) Burial depth of tank. Measure from grade to top of tank.
   (b) Distance of tank center line to any adjacent structure.
   (c) Diameter of tank.
   (d) Depth below grade of footings supporting the adjacent structure(s)
3. Diagrams and Photographic evidence of any other item(s) that are claimed to prevent removal of any tank.

If you have questions, call 854-2536

Submit all Information to:
Suffolk County Department of Health Services
15 Horseblock Pl.
Farmingville, NY 11738

COUNTY OF SUFFOLK

STEVEN BELLONE
SUFFOLK COUNTY EXECUTIVE

DEPARTMENT OF HEALTH SERVICES

JAMES L. TOMARKEN, MD
MSW, MPH, MBA, FRCPC, FACP
Commissioner

September 6, 2013

ERM
105 Maxess Road, Suite 316
Melville, NY 11747

Attn: Eugene Gabay

Re: **Application for In Place - Permanent Closure of Underground Storage Tank**
Facility Name: Newsday Inc.
File Reference No. 02037
Facility I.D. No. 4-0094

Dear Mr. Gabay:

Your application for in place permanent closure of underground storage tank is under review process and you are required to submit following information:

1. Provide a site plan to indicate the location and depth of any underground structures, such as septic tanks, leaching pools, storm drains, and dry wells, within 50' radius of the tank.
2. You are required to perform site assessment as pre NYS DEC S.P.O.T.S. 14 which pump out, clean and vapor free the Tank #7. You need to take 8 soil samples through the bottom of the Tank #7, 4' and 8' below tank bottom respectively and each sample must pass STARS 8620/8270 analysis in approved laboratory.

If you have any questions, please feel free to contact our office.

Sincerely,

Chris Wong
Assistant Public Health Engineer
Bureau of Environmental Engineering

Public Health
Prevent. Promote. Protect.

DIVISION OF ENVIRONMENTAL QUALITY
Office of Pollution Control, 15 Horseblock Place, Farmingville, NY 11738
Phone (631) 854-2502 Fax (631) 854-2505

COUNTY OF SUFFOLK

STEVEN BELLONE
SUFFOLK COUNTY EXECUTIVE

DEPARTMENT OF HEALTH SERVICES

JAMES L. TOMARKEN, MD
MSW, MPH, MBA, FRCPC, FACP
Commissioner

September 13, 2013

ERM
105 Maxes Road, Suite 316
Melville, NY 11747

Attn: Eugene Gabay

Re: **Application for In Place - Permanent Closure of Underground Storage Tank**
Facility Name: Newsday Inc.
File Reference No. 02037
Facility I.D. No. 4-0094

Dear Mr. Gabay:

Your application for in place permanent closure of underground storage tank is approved for following tank(s)

Tank #	Volume	Contents	Disposition
6	25,000 Gals.	#2 Fuel Oil	Abandonment
7	25,000 Gals.	#2 Fuel Oil	Abandonment

The Office of Pollution Control must be contacted at (631)854-2523 at least 2 business days prior to commencement of any work to arrange for the required inspections.

Contact the local building department and/or fire safety enforcement office for any additional requirements that may apply to your project.

The Office of Pollution Control reserves the right to revoke this permit as allowable by law.

Special Condition(s): Tanks must be filled with concrete slurry or clean sand.

If you have any questions, please feel free to contact our office.

Sincerely,

Chris Wong
Assistant Public Health Engineer
Bureau of Environmental Engineering

Public Health
Prevent. Promote. Protect.

DIVISION OF ENVIRONMENTAL QUALITY
Office of Pollution Control, 15 Horseblock Place, Farmingville, NY 11738
Phone (631) 854-2502 Fax (631) 854-2505

APPENDIX D
BILLS OF LADING

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542307

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
58.02	19.19	39.83	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	7:09		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 39.03
LOADS THIS ORDER TODAY 1

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542313

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
58.02	19.19	39.83	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	7:09		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 78.86
LOADS THIS ORDER TODAY 2

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

110 Sand Company

170 Cabot Street
West Babylon, New York 11704

CUSTOMER COPY

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542323

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
59.13	19.19	39.94	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	13:54		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 118.80
LOADS THIS ORDER TODAY 3

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

170 Cabot Street
West Babylon, New York 11704

CUSTOMER COPY

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542326

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
59.02	19.19	39.83	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	14:31		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 158.63
LOADS THIS ORDER TODAY 4

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542349

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
69.80	19.42	40.38	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

MATERIAL DESCRIPTION: PROCESSED FILL (A)

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	8:42		

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY	
QUANTITY THIS ORDER TODAY	40.38
LOADS THIS ORDER TODAY	1

OFFICE USE ONLY

RECEIVED BY:
BROMAN#26

CARRIER SIGNATURE _____

CUSTOMER SIGNATURE _____

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542358

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
60.32	19.42	40.90	TONS	JDW

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	9:28		

MATERIAL DESCRIPTION: PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 81.20
LOADS THIS ORDER TODAY 2

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#26

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542360

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
59.77	19.42	40.35	TONS	CAR

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	10:04		

MATERIAL DESCRIPTION: PROCESSED FILL (A)

119540 1.8

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 121.63
LOADS THIS ORDER TODAY 3

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#26

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
010001		8674	SHIPPING		012130	542375

CUSTOMER NAME: ENV-14Y

MATERIAL SALE - CHECK

GROSS	TARE	NET	UNIT	WEIGHED BY
27.27	11.02	16.25	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14	Y		13

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	11:53		857250

MATERIAL DESCRIPTION: SAND (A) 10-34F

DELIVERY ADDRESS

TOTAL TODAY

QUANTITY THIS ORDER TODAY

LOADS THIS ORDER TODAY

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

SEVILLE CENTRAL MIX, CORP.

SEVILLE CENTRAL MIX CORP.

MAILING ADDRESS:
157 ALBANY AVENUE
FREEPORT, N.Y. 11520

OLD BETHPAGE 293-6190 | HOLTSVILLE 293-6190 | CEDARHURST 239-8333

AUTHORIZATION TO ADD WATER
BY: _____
_____ GAL. WATER ADDED
The seller will not assume any responsibility for strength of concrete if water is added to the concrete on the job by the purchaser.

PLANT CODE	CENTRAL MIX	TRUCK MIX	PICK-UP	DELIVERY	SLUMP	TICKET REF. NO.
W1-20168					3.5	63370

ORDER # 600

DATE	DRIVER	TRUCK NO.	JOB NO.	ACCOUNT NO.
3/25/2014	Daniel16 D.	48		CONS

_____ HRS.
_____ MINS

SOLD TO
METRO ENVIRONMENTAL

GARY 516-216-0025
DASHON DR. TO GUARD BOOTH

SHIPPED TO
JOB #
NEWSDAY-MELVILLE/PINELAWN RD

PRODUCT NO.	DESCRIPTION	UNIT	QUANTITY	UNIT PRICE	AMOU
40A61	4000# STONE COMMERCIAL	CY	5.00		
W/C	WINTER CONCRETE	/Y	5.00		
PLC	PART LOAD CHARGE	/1	1.00		

CONTROLLED CONCRETE
WEIGHTS PER YD.

CEMENT _____ LBS.
COARSE AGG _____ LBS.
_____ LBS.
FINE AGG _____ LBS.
_____ GALS WATER/YD

ADMIXTURE

TO PRODUCE _____ LB. CONCRETE

TOTAL ORDERED	YARDS TO DAY	COLLECT GRAND TOTAL	SUB TOTAL
5.00	5.00		TAX
REC'D BY		ALLOWABLE TIME	TOTAL

SLIP NO
W 33

NOT RESPONSIBLE FOR VARIANCE IN COLOR
SUBJECT TO CONDITIONS ON REVERSE SIDE

CAUTION!—FRESHLY MIXED CEMENT, MORTAR, GROUT OR CONCRETE MAY CAUSE A SEVERE SKIN IRRITATION AND BURNS ON INDIVIDUALS WITH SENSITIVE SKIN. AVOID DIRECT CONTACT WITH SKIN IF POSSIBLE AND WASH EXPOSED SKIN AREAS PROMPTLY WITH WATER. IF ANY OF THESE MATERIALS GET INTO THE EYE, RINSE IMMEDIATELY AND REPEATEDLY WITH WATER AND GET PROMPT MEDICAL ATTENTION. KEEP CEMENT AND FRESHLY MIXED CEMENT PRODUCTS OUT OF THE REACH OF CHILDREN.

APPENDIX E
SCDOHS TANK REMOVAL CHECKLIST

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES
DIVISION OF ENVIRONMENTAL QUALITY
OFFICE OF POLLUTION CONTROL

TANK REMOVAL CHECKLIST

FILE REF NO: 02637 REG NO: 4-0094 DATE: 2/20/2014
FACILITY NAME: NEWSDAY
FACILITY ADDRESS: 235 PINELAWN RD MELVILLE
SCTM# 400-270-2-1 SITE GPS
400-270-1-24.1

TANK #	LOCATION	CAPACITY	CONTENTS	MATERIAL
6	UPRIGHT	25000	#2 FUEL OIL	PLW STL
7	LAYDOWN	25000	#2 FUEL OIL	PLW STL


1. CONDITION OF TANK AND PIPING: (Note any holes) CLEAN BTL LININGS AND SLUDGES REMOVED

2. WAS CONTAMINATION NOTED WITHIN EXCAVATION? Y / N
All Material Removed Under SCDHS Supervision: Y / N
Approximate Amount Of Contaminated Soil Removed: X cu yds / tons / drums
Was Ground Water Impacted: Y / (N)
DEC Notified: (Y) / N *(1-800-457-7362)* DEC Spill Number: 1203029

3. WERE ALL ASSOCIATED PIPES AND VENT LINES REMOVED? (Y) / N (If No, explain)

4. NAME OF CONTRACTOR: ERM SUB: METRO

Site Sketch:



N
PINELAWN

A Copy of This Document Was Given to: Bill Smith
(Owner's Representative)

Inspector: MICHAEL SEAMAN Inspector's Signature:

OFFICE USE:	
SCDHS Spill Number:	Spills Key:

APPENDIX F
PHOTOLOG



Photograph: *1*	*Saw cuts and jack hammered concrete on top of UST #6 and #7*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *2*	*Excavated debris from the saw cut holes on top of UST #6 and #7*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *3*	*UST #6 center hole after it was cleaned out*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *4*	*UST #6 eastern hole prior to backfilling with sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *5*	*UST #7 western hole prior to backfilling with sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *6*	*UST #7 eastern hole prior to backfilling with sand*	
Tribune Company	***ERM***	*285 Pinelawn Road* *Melville, NY*




Photograph: 7	End of work day all of the holes were secured with plywood, 2x4s and caution tape	
Tribune Company	**ERM**	235 Pinelawn Road Melville, NY



Photograph: 8	UST #6 being backfilled with clean sand	
Tribune Company	**ERM**	235 Pinelawn Road Melville, NY




Photograph: *9*	*UST #7 being backfilled with clean sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *10*	Vent lines filled with concrete	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *11*	*Tank excavations ready for concrete*	
Tribune Company	***ERM***	*235 Pinelawn Melville, NY*



Photograph: *12*	*Excavations restored to original condition*	
Tribune Company	***ERM***	*235 Pinelawn Melville, NY*

APPENDIX G
WASTE MANIFESTS

13-946 ✓

Con Strux - Lindenhurst
690 Muncy Avenue
Lindenhurst, NY 11757
Phone: (631) 669-3133

Customer: METR01
METRO ENVIRONMENTAL
690 A. NORTH QUEENS AVE
N.Y. NY 11757
631-884-1880
P/O:

Ship To:

Drw # 1
54889
Sls #
User SML
03/19/14
09:36

ITEM#	QTY	PRICE
D2	10	
CLEAN CONCRETE	CU	

Cash	*0.00*	Sub-Total	
Ccd		Disc	0.00
Check	*0.00*	Freight	0.00
Gft/Cpns/Fst	*0.00*	Tax (SUFF)	0.00
Store Credit	*0.00*	**TOTAL**	
Bill To A/R	*0.00*	Change Due	0.00

Auth# 04191G

METRO ENVIRONMENTAL

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N / A

Manifest Document No.: 3 8 9 2 1

2. Page 1 of 1

3. Generator's Name and Mailing Address:
Tribune
435 N. Michigan Avenue
Chicago, IL 60611

4. Generator's Phone (631) 843-2000

Newsday-235 Pinelawn Road
Melville, NY 11747

5. Transporter 1 Company Name: Metro Environmental Contracting

6. US EPA ID Number: N Y R 0 0 0 1 3 4 9 5 7

A. State Transporter's ID

B. Transporter 1 Phone: (631)884-1880

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address:
Advanced Waste & Water Technology,
208 Route 109
Farmingdale, NY 11735

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone: (631)249-3774

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oily Water Non-DOT Regulated Material	1	TT	100	G
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Stephen Zimmerman | Signature | Date: Month 3 Day 17 Year 14

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Keith Boncke | Signature: Keith Boncke | Date: Month 3 Day 17 Year 14

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Chris Brown | Signature | Date: Month 3 Day 18 Year 14

NON-HAZARDOUS WASTE

F-14 © 2002 LABELMASTER® (800) 621-5808 www.labelmaster.com

PRINTED WITH SOY INK

Rev. 3/95

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N/A

Manifest Document No.: 032014-01

2. Page 1 of 1

3. Generator's Name and Mailing Address
Tribune
435 N. Michigan Ave
Chicago, IL 60611
4. Generator's Phone (631) 843-2000

Newsday - 235 Pinelawn Rd
Melville, NY 11747

5. Transporter 1 Company Name: Metro Environmental Contracting
6. US EPA ID Number: NYR000134957
A. State Transporter's ID
B. Transporter 1 Phone: 631-884-1880

7. Transporter 2 Company Name
8. US EPA ID Number
C. State Transporter's ID
D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Advanced Waste Water Technology
208 Route 109
Farmingdale NY 11735
10. US EPA ID Number
E. State Facility's ID
F. Facility's Phone: 631-249-3774

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oily Water Non-DOT Regulated Material	1	TT	200	G
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Steve Ammerman
Signature:
Date: Month 3 Day 3 Year 2014

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Keith Baucke
Signature:
Date: Month 3 Day 3 Year 2014

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Jim Kidney
Signature: Jim Kidney
Date: Month 3 Day 21 Year 14

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N / A

Manifest Document No.: 38922

2. Page 1 of 1

3. Generator's Name and Mailing Address
Tribune
435 N. Michigan Avenue
Chicago, IL 60611

4. Generator's Phone (631) 843-2000

Newsday-235 Pinelawn Road
Melville, NY 11747

5. Transporter 1 Company Name: Metro Environmental Contracting

6. US EPA ID Number: NYR000134957

A. State Transporter's ID

B. Transporter 1 Phone: (631)884-1880

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Republic Environmental Systems
2869 Sandstone Drive
Hatfield, PA 19440

10. US EPA ID Number: PAD085690592

E. State Facility's ID

F. Facility's Phone: (215)822-8995

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oil Tank Bottoms Non-DOT Regulated Material	1	DM	100	~~LBS~~ (P) RQ
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
11a) 635017
Doc#

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Stephen Zimmerman | Signature | Date: Month 3 Day 17 Year 14

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Matthew S. Copeland | Signature | Date: Month 03 Day 17 Year 14

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name | Signature | Date: Month Day Year

NON-HAZARDOUS WASTE

Appendix D

Environmental Database Search Report



Newsday
235 Pinelawn Road
Melville, NY 11747

Inquiry Number: 4977850.2s
June 27, 2017

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	756
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

235 PINELAWN ROAD
MELVILLE, NY 11747

COORDINATES

Latitude (North):	40.7634510 - 40° 45' 48.42''
Longitude (West):	73.4066480 - 73° 24' 23.93''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	634487.5
UTM Y (Meters):	4513508.0
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940609 HUNTINGTON, NY
Version Date:	2013
South Map:	5940593 AMITYVILLE, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	NEWSDAY INC	235 PINELAWN RD	NY AST		TP
A2	INDUSTRIAL	235 PINELAWN RD	NY Spills		TP
A3	NEWSDAY	235 PINELAWN ROAD	NY Spills		TP
A4	NEWSDAY, LLC	235 PINELAWN ROAD	SEMS-ARCHIVE, RCRA-LQG, NY LTANKS, NY Spills,...		TP
A5	NEWSDAY INC	235 PINELAWN RD	NY UST		TP
A6	NEWSDAY LLC	235 PINELAWN RD	NY AST		TP
A7	NEWSDAY LLC	235 PINELAWN RD	NY UST		TP
A8	NALCO CHEMICAL	235 PINELAWN RD - BO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST		TP
B9	IMPERIAL NEWS CO	255 PINELAWN ROAD	NY Spills	Lower	15, 0.003, ESE
B10	CLARE ROSE	255 PINELAWN RD/MARC	NY Spills	Lower	15, 0.003, ESE
B11	CLARE ROSE	255 PINE LAWN ROAD	NY Spills	Lower	15, 0.003, ESE
B12	IMPERIAL NEWS	255 PINELAWN RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	15, 0.003, ESE
B13	CLARE ROSE	255 CNTY RD 3 PINELA	NY UST, NY AST	Lower	15, 0.003, ESE
C14	TRIBUNE COMPANY	25 DESHON DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	88, 0.017, WNW
C15	NEWSDAY	25 DESHON DR	NY UST	Higher	88, 0.017, WNW
C16	NEWSDAY	25 DESHON DR	NY AST	Higher	88, 0.017, WNW
C17	TRIBUNE LLC	25 DESHON DR	NY AST	Higher	88, 0.017, WNW
C18	J.M ALBRIZZIO	25 DESCHON DRIVE	NY Spills	Higher	88, 0.017, WNW
C19	TRIBUNE LLC	25 DESHON DR	NY UST	Higher	88, 0.017, WNW
C20	NEWSDAY	25 DESHON DRIVE	NY Spills	Higher	88, 0.017, WNW
D21	EASTERN ATHLETIC CLU	100 RULAND ROAD	NY Spills	Lower	168, 0.032, NNE
D22	EASTERN ATHLETIC	100 RULAND RD	NY UST	Lower	168, 0.032, NNE
D23	COSTCO	625 RULAND RD	RCRA NonGen / NLR	Lower	252, 0.048, NNE
E24	BUSINESS	255 PINELAWN ROAD	NY Spills	Lower	266, 0.050, SE
E25	CLARE ROSE INC	255 PINELAWN RD	NY UST	Lower	266, 0.050, SE
E26	CLARE ROSE INC	255 PINELAWN RD	NY AST	Lower	266, 0.050, SE
D27	UNKNOWN	PINELAWN ROAD/RULAND	NY Spills	Lower	368, 0.070, NNE
D28	UNKNOWN	PINE LAWN & RULAN RO	NY Spills	Lower	368, 0.070, NNE
29	PATTERSON BUILDING	25 DESHON DR/MARCUS	NY Spills	Higher	374, 0.071, WSW
F30	WOODBOURNE CULTURAL	301 COLONIAL SPRING	NY AST	Lower	435, 0.082, NNE
F31	WOODBOURNE CULTURAL	301 COLONIAL SPRING	NY UST, NY AST	Lower	435, 0.082, NNE
F32	WOODBOURNE CULTURAL	301 COLONIAL SPRINGS	NY Spills	Lower	435, 0.082, NNE
F33	WOODBOURNE CULTURAL	301 COLONIAL SPRING	NY UST	Lower	435, 0.082, NNE
G34	HEIDELBERG PUBLISHIN	80 RULAND RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	437, 0.083, WNW
G35	LINOTYPE-HELL CO	80 RULAND RD	NY AST	Higher	437, 0.083, WNW
H36	PERGAMENT	101 MARCUS DRIVE	NY Spills, NY MANIFEST	Lower	547, 0.104, South
H37	MRP FAMILY HOLDINGS	101 MARCUS DR	NY UST	Lower	547, 0.104, South
G38	OTTO KEIL FLORIST	107 RULAND RD	NY AST	Higher	548, 0.104, WNW
H39	RACANELLI COMMERCIAL	102 MARCUS DR	NY UST	Lower	628, 0.119, SSE

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H40	FONAR TRAVEL	102 MARCUS DR	NY UST	Lower	628, 0.119, SSE
H41	DON JAGODA INC	102 MARCUS DR	NY UST	Lower	628, 0.119, SSE
H42	RACANELLI ASSOCIATES	100 MARCUS DRIVE	NY LTANKS	Lower	673, 0.127, South
H43	ESPRIT BLDG	100 MARCUS DR	NY UST	Lower	673, 0.127, South
I44	NEW YORK STATE DRUG	175 PINELAWN RD SUIT	NY MANIFEST	Lower	731, 0.138, North
I45	HONEYWELL INC	175 PINELAWN RD	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	731, 0.138, North
46	85 MARCUS DR	85 MARCUS DR	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	745, 0.141, SW
J47	COMAX FLAVORS	130 BAYLISS RD	RCRA-LQG, NJ MANIFEST, NY MANIFEST	Higher	750, 0.142, NNW
J48	COMAX MANUFACTURING	130 BAYLIS RD	NY AST	Higher	750, 0.142, NNW
K49	MEDISYS HEALTH NETWO	80 MARCUS DR	NY UST	Lower	779, 0.148, SSW
K50	GENOVESE DRUG STORES	80 MARCUS DR	NY LTANKS, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	779, 0.148, SSW
L51	110 MARCUS DR	110 MARCUS DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NJ...	Lower	791, 0.150, SSE
L52	M & W RECKSON ASSOCI	110 MARCUS DR	NY UST	Lower	791, 0.150, SSE
M53	RULAND ROAD LLC	95 RULAND RD	NY UST	Lower	914, 0.173, WNW
M54	RULAND ROAD LLC	95 RULAND RD	NY AST	Lower	914, 0.173, WNW
55	CANADA DRY BOTTLING	135 BAYLIS RD	NY LTANKS, NY UST, NY AST	Lower	918, 0.174, NNW
N56	PARAGON ENTERPRISES	125 BAYLIS RD	NY UST	Higher	1056, 0.200, NNW
N57	OFFICE BUILDING	125 BAYLIS ROAD	NY LTANKS	Higher	1056, 0.200, NNW
58	NY TEL CO	84 DURYEA ROAD	NY LTANKS	Lower	1160, 0.220, NW
O59	LABORATORY CORP OF A	170 FINN CT	NY UST	Lower	1166, 0.221, SSE
O60	ROCHE BIOMEDICAL LAB	170 FINN CT	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1166, 0.221, SSE
O61	ROCHE BIOMEDICAL LAB	170 FINN CT	RCRA NonGen / NLR, NY MANIFEST	Lower	1166, 0.221, SSE
O62	ARTEK	170 FINN CT	NY UST	Lower	1166, 0.221, SSE
63	FALA INC	70 MARCUS DR	NY UST	Lower	1170, 0.222, SSW
64	WALAEL RESIDENCE	95 RULAND PLACE	NY LTANKS	Lower	1202, 0.228, West
O65	NATIONAL ENVIRONMENT	150 FINN CT	NY UST	Lower	1206, 0.228, SSE
O66	PRECIPART CORPORATIO	150 FINN COURT	RCRA-SQG, FINDS, ECHO, NY MANIFEST, RI MANIFEST	Lower	1206, 0.228, SSE
O67	MORRIS BROTHERS AUTO	150 FINN COURT	NY Spills, NY MANIFEST	Lower	1206, 0.228, SSE
O68	PRECIPART CORP	150 FINN COURT	PA MANIFEST	Lower	1206, 0.228, SSE
P69	MIP INC	130 FINN CT	NY AST	Lower	1211, 0.229, SSE
P70	MANUFACTURERS INDEXI	130 FINN CT	RCRA NonGen / NLR, NY MANIFEST	Lower	1211, 0.229, SSE
P71	PRECIPART CORP	100 FINN CT	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	1216, 0.230, SSE
P72	MAYTAG BLDG	100 FINN CT	NY UST	Lower	1216, 0.230, SSE
Q73	FALA DIRECT MARKETIN	75 MARCUS DR	NY UST	Lower	1216, 0.230, SW
Q74	FALA CCG INC	75 MARCUS DR	RCRA-SQG, NY LTANKS, FINDS, ECHO, NJ MANIFEST, NY...	Lower	1216, 0.230, SW
O75	AIRCRAFT PARTS INC	160 FINN CT	RCRA-SQG, NY LTANKS, NJ MANIFEST, NY MANIFEST	Lower	1261, 0.239, SSE
O76	AIRCRAFT PARTS CORP	160 FINN CT	NY UST	Lower	1261, 0.239, SSE
O77	AIRCRAFT PARTS INC	160 FINN COURT	NY AST, RCRA NonGen / NLR, FINDS, ECHO	Lower	1261, 0.239, SSE
78	NORTHROP GRUMMAN	65 MARCUS DRIVE	NY LTANKS, NY Spills	Lower	1351, 0.256, SW

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
79	WE'RE ASSOCIATES	100 BAYLIS ROAD	NY LTANKS	Higher	1483, 0.281, NW
R80	FIRST VEHICLE SERVIC	55 MARCUS DR	NY LTANKS, NY Spills, NY MANIFEST	Lower	1729, 0.327, WSW
81	SPILL NUMBER 9713313	98 REPUBLIC ROAD	NY LTANKS	Lower	1772, 0.336, West
82	KALMAR DESIGNS	485 SMITH STREET	NY LTANKS, NY Spills	Lower	1809, 0.343, South
S83	VENUS SCIENTIFIC INC	399 SMITH ST	NY LTANKS, NY UST, NY AST, RCRA NonGen / NLR,...	Lower	1862, 0.353, SSW
S84	HT STEEL	375 SMITH STREET	NY LTANKS, NY Spills	Lower	1889, 0.358, SSW
85	MINMILT REALTY (HYGR	540 SMITH STREET	NY SHWS, NY VAPOR REOPENED, NY VCP	Lower	1924, 0.364, South
R86	EAGLE FUEL TRANSPORT	50 REPUBLIC ROAD	NY LTANKS, NY Spills	Lower	1943, 0.368, SW
87	RECKSON ASSOCIATES	333 SMITH ST	NY VCP, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	2056, 0.389, SSW
88	WERE ASSOCIATES	80 BAYLIS ROAD	NY LTANKS	Higher	2064, 0.391, NW
89	CITICORP CREDIT SERV	135 DURYEA ROAD	NY LTANKS, NY Spills	Lower	2242, 0.425, WNW
90	ESTEE LAUDER INC RES	125 PINELAWN RD	RCRA-SQG, NY LTANKS, NY UST, NY Spills, NY...	Lower	2286, 0.433, North
91	CANTOR BROTHERS	50 ENGINEERS LANE	NY SHWS, NY VAPOR REOPENED, NY VCP, NY Spills	Lower	2446, 0.463, South
92	FORMERLY EMBASSY IND	300 SMITH ST	NY LTANKS, NY AST, NY Spills, RCRA NonGen / NLR,...	Lower	2534, 0.480, SSW
93	TRONIC PLATING CO.,	168 CENTRAL AVENUE	Delisted NPL, SEMS, CORRACTS, US ENG CONTROLS,...	Lower	2692, 0.510, South
T94	ASTRO ELECTROPLATING	170 CENTRAL AVENUE	NY SHWS, NY Spills	Lower	3162, 0.599, South
T95	TRONIC PLATING CO.,	168 CENTRAL AVENUE	NY DEL SHWS, NY Spills	Lower	3178, 0.602, South
96	MCGOVERN SOD FARM	PINELAWN ROAD & OLD	NY SHWS	Higher	3240, 0.614, North
97	I.W. INDUSTRIES, INC	35 MELVILLE PARK ROA	NY SHWS, NY LTANKS, NY ENG CONTROLS, NY INST...	Higher	4004, 0.758, NNW
98	ARCHON GROUP	25 MELVILLE PARK RD	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY VCP,...	Higher	4174, 0.791, NNW
U99	CIRCUITRON CORPORATI	82 MILBAR BOULEVARD	NY VAPOR REOPENED, NY AST, RCRA NonGen / NLR,...	Lower	5106, 0.967, SW
U100	UNITED STATES DEPT O	PROTECTION-SITE:82 M	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, RCRA...	Lower	5106, 0.967, SW
U101	CIRCUITRON CORP.	82 MILBAR BOULEVARD	NPL, SEMS, US ENG CONTROLS, LIENS 2, RCRA NonGen /...	Lower	5106, 0.967, SW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
NEWSDAY INC 235 PINELAWN RD MELVILLE, NY 11747	NY AST Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 07934 Facility Id: 07934	N/A
INDUSTRIAL 235 PINELAWN RD MELVILLE, NY	NY Spills Spill Number/Closed Date: 1606790 / Not Reported spillno: 1606790 Site ID: 533430	N/A
NEWSDAY 235 PINELAWN ROAD MELVILLE, NY	NY Spills Spill Number/Closed Date: 1508951 / 2015-12-09 spillno: 1508951 Site ID: 517549	N/A
NEWSDAY, LLC 235 PINELAWN ROAD MELVILLE, NY 11747	SEMS-ARCHIVE Site ID: 0202958 EPA Id: NYD052782497 RCRA-LQG EPA ID:: NYD052782497 NY LTANKS Spill Number/Closed Date: 9201246 / 1998-05-27 Spill Number/Closed Date: 9709711 / 2009-12-11 Spill Number/Closed Date: 1203029 / 2014-04-07 Site ID: 276627 Site ID: 276630 Site ID: 465817 Program Number: 9201246 Program Number: 9709711 Program Number: 1203029 NY Spills Spill Number/Closed Date: 1402877 / 2014-08-12 Spill Number/Closed Date: 1205313 / 2012-10-03 Spill Number/Closed Date: 1200716 / 2012-10-22 Spill Number/Closed Date: 1108374 / 2011-10-03 Spill Number/Closed Date: 1000551 / 2011-03-30 **Additional key fields are available in the Map Findings section* spillno: 0008603 spillno: 0125175	NYD052782497

spillno: 0203990
spillno: 0507524
spillno: 1000551
**Additional key fields are available in the Map Findings section*
Site ID: 276623
Site ID: 276624
Site ID: 276625
Site ID: 352993
Site ID: 431720
**Additional key fields are available in the Map Findings section*

ICIS
FRS ID:: 110000807761

US AIRS
Database: US AIRS (AFS), Date of Government Version: 10/12/2016
EPA plant ID:: 110000807761

FINDS
Registry ID:: 110000807761

ECHO
NY MANIFEST
EPA ID: NYD052782497

NJ MANIFEST
EPA Id: NYD052782497

NY SPDES
Limit Set Status Flag: A
Permit Number: NY0136751

NEWSDAY INC
235 PINELAWN RD
MELVILLE, NY 11747

NY UST N/A
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 07934
Facility ID: 07934

NEWSDAY LLC
235 PINELAWN RD
MELVILLE, NY 11747

NY AST N/A
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 02037
Status: ACTIVE
Facility Id: 02037

NEWSDAY LLC
235 PINELAWN RD
MELVILLE, NY 11747

NY UST N/A
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 02037
Status: ACTIVE
Facility ID: 02037

NALCO CHEMICAL
235 PINELAWN RD - BO
MELVILLE, NY 11747

RCRA NonGen / NLR NYR000024620

EXECUTIVE SUMMARY

EPA ID:: NYR000024620

FINDS
Registry ID:: 110004525443

ECHO
NY MANIFEST
EPA ID: NYR000024620

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF ---------- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

NY CBS UST Chemical Bulk Storage Database
NY MOSF UST Major Oil Storage Facilities Database
NY MOSF Major Oil Storage Facility Site Listing
NY CBS Chemical Bulk Storage Site Listing
NY CBS AST Chemical Bulk Storage Database
NY MOSF AST Major Oil Storage Facilities Database
INDIAN UST Underground Storage Tanks on Indian Land
NY TANKS Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY BROWNFIELDS Brownfields Site List
NY ERP Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY Registered Recycling Facility List
NY SWTIRE Registered Waste Tire Storage & Facility List
INDIAN ODI Report on the Status of Open Dumps on Indian Lands
ODI Open Dump Inventory
DEBRIS REGION 9 Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL Delisted National Clandestine Laboratory Register
US CDL National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST Historical Petroleum Bulk Storage Database
NY HIST AST Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS Spill Liens Information

Records of Emergency Release Reports

HMIRS Hazardous Materials Information Reporting System

NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PADS ---- PCB Activity Database System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY DRYCLEANERS ---- Registered Drycleaners
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY UIC ---- Underground Injection Control Wells

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---- EDR Proprietary Manufactured Gas Plants
EDR Hist Auto ---- EDR Exclusive Historic Gas Stations
EDR Hist Cleaner ---- EDR Exclusive Historic Dry Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 04/05/2017 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CIRCUITRON CORP.	***82 MILBAR BOULEVARD***	***SW 1/2 - 1 (0.967 mi.)***	***U101***	***736***

Federal Delisted NPL site list

Delisted NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may deleted from the NPL where no further response is appropriate.

A review of the Delisted NPL list, as provided by EDR, and dated 04/05/2017 has revealed that there is 1 Delisted NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	***168 CENTRAL AVENUE***	***S 1/2 - 1 (0.510 mi.)***	***93***	***548***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/12/2016 has revealed that there is 1

CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	*168 CENTRAL AVENUE*	*S 1/2 - 1 (0.510 mi.)*	*93*	*548*

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/12/2016 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMAX FLAVORS	*130 BAYLISS RD*	*NNW 1/8 - 1/4 (0.142 mi.)*	*J47*	*253*

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/12/2016 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORPORATIO	*150 FINN COURT*	*SSE 1/8 - 1/4 (0.228 mi.)*	*O66*	*367*
PRECIPART CORP	*100 FINN CT*	*SSE 1/8 - 1/4 (0.230 mi.)*	*P71*	*392*
FALA CCG INC	*75 MARCUS DR*	*SW 1/8 - 1/4 (0.230 mi.)*	*Q74*	*406*
AIRCRAFT PARTS INC	*160 FINN CT*	*SSE 1/8 - 1/4 (0.239 mi.)*	*O75*	*423*

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/12/2016 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
85 MARCUS DR	*85 MARCUS DR*	*SW 1/8 - 1/4 (0.141 mi.)*	*46*	*243*

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/14/2016 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCGOVERN SOD FARM Site Code: 57636	PINELAWN ROAD & OLD	N 1/2 - 1 (0.614 mi.)	96	576
I.W. INDUSTRIES, INC Site Code: 55868 Class Code: Site is properly closed - requires continued management.	***35 MELVILLE PARK ROA***	***NNW 1/2 - 1 (0.758 mi.)***	***97***	***578***
ARCHON GROUP Site Code: 57693 Class Code: Significant threat to the public health or environment - action required.	***25 MELVILLE PARK RD***	***NNW 1/2 - 1 (0.791 mi.)***	***98***	***632***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR Site Code: 55887 Class Code: Site is properly closed - requires continued management.	***540 SMITH STREET***	***S 1/4 - 1/2 (0.364 mi.)***	***85***	***473***
CANTOR BROTHERS Site Code: 57868 Class Code: Site is properly closed - requires continued management.	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.463 mi.)***	***91***	***532***
ASTRO ELECTROPLATING Site Code: 58178 Class Code: Significant threat to the public health or environment - action required.	***170 CENTRAL AVENUE***	***S 1/2 - 1 (0.599 mi.)***	***T94***	***568***
UNITED STATES DEPT O Site Code: 55856 Class Code: Site is properly closed - requires continued management.	***PROTECTION-SITE:82 M***	***SW 1/2 - 1 (0.967 mi.)***	***U100***	***705***

NY VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 06/01/2016 has revealed that there are 3 NY VAPOR REOPENED sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR	***540 SMITH STREET***	***S 1/4 - 1/2 (0.364 mi.)***	***85***	***473***

Facility Status: Underway
Site Code: 152147

CANTOR BROTHERS	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.463 mi.)***	***91***	***532***
Facility Status: Complete (Mitigate) Site Code: 152021				
CIRCUITRON CORPORATI	***82 MILBAR BOULEVARD***	***SW 1/2 - 1 (0.967 mi.)***	***U99***	***683***
Facility Status: Complete Site Code: 152082				

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/06/2017 has revealed that there are 20 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING Spill Number/Closed Date: 0104376 / 2001-09-07 Site ID: 127634 Program Number: 0104376	125 BAYLIS ROAD	NNW 1/8 - 1/4 (0.200 mi.)	N57	336
WE'RE ASSOCIATES Spill Number/Closed Date: 8803165 / 1988-08-25 Spill Number/Closed Date: 9003860 / 1995-04-05 Site ID: 224161 Site ID: 224162 Program Number: 8803165 Program Number: 9003860	100 BAYLIS ROAD	NW 1/4 - 1/2 (0.281 mi.)	79	441
WERE ASSOCIATES Spill Number/Closed Date: 8801432 / 1989-03-08 Site ID: 220411 Program Number: 8801432	80 BAYLIS ROAD	NW 1/4 - 1/2 (0.391 mi.)	88	492

Lower Elevation	Address	Direction / Distance	Map ID	Page
RACANELLI ASSOCIATES Spill Number/Closed Date: 8805457 / 1988-09-30 Site ID: 99721 Program Number: 8805457	100 MARCUS DRIVE	S 1/8 - 1/4 (0.127 mi.)	H42	233
GENOVESE DRUG STORES Spill Number/Closed Date: 9110046 / 1999-09-08 Site ID: 249892 Program Number: 9110046	***80 MARCUS DR***	***SSW 1/8 - 1/4 (0.148 mi.)***	***K50***	***291***
CANADA DRY BOTTLING Spill Number/Closed Date: 9700559 / 1999-04-14 Spill Number/Closed Date: 9304069 / 1994-02-10 Site ID: 159315	***135 BAYLIS RD***	***NNW 1/8 - 1/4 (0.174 mi.)***	***55***	***329***

Site ID: 203799
Program Number: 9700559
Program Number: 9304069

NY TEL CO	84 DURYEA ROAD	NW 1/8 - 1/4 (0.220 mi.)	58	337
Spill Number/Closed Date: 9109715 / 1992-01-10				
Site ID: 198367				
Program Number: 9109715				
WALAEL RESIDENCE	95 RULAND PLACE	W 1/8 - 1/4 (0.228 mi.)	64	365
Spill Number/Closed Date: 9903643 / 1999-09-28				
Site ID: 240480				
Program Number: 9903643				
FALA CCG INC	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.230 mi.)***	***Q74***	***406***
Spill Number/Closed Date: 8706743 / 1988-02-09				
Site ID: 288842				
Program Number: 8706743				
AIRCRAFT PARTS INC	***160 FINN CT***	***SSE 1/8 - 1/4 (0.239 mi.)***	***O75***	***423***
Spill Number/Closed Date: 9304294 / 2003-09-30				
Site ID: 144446				
Program Number: 9304294				
NORTHROP GRUMMAN	***65 MARCUS DRIVE***	***SW 1/4 - 1/2 (0.256 mi.)***	***78***	***439***
Spill Number/Closed Date: 8706384 / 1988-02-12				
Site ID: 145270				
Program Number: 8706384				
FIRST VEHICLE SERVIC	***55 MARCUS DR***	***WSW 1/4 - 1/2 (0.327 mi.)***	***R80***	***444***
Spill Number/Closed Date: 8805536 / 1988-10-31				
Site ID: 274806				
Program Number: 8805536				
SPILL NUMBER 9713313	98 REPUBLIC ROAD	W 1/4 - 1/2 (0.336 mi.)	81	448
Spill Number/Closed Date: 9713313 / 1998-08-26				
Site ID: 182849				
Program Number: 9713313				
KALMAR DESIGNS	***485 SMITH STREET***	***S 1/4 - 1/2 (0.343 mi.)***	***82***	***449***
Spill Number/Closed Date: 9209410 / 1992-11-13				
Site ID: 70689				
Program Number: 9209410				
VENUS SCIENTIFIC INC	***399 SMITH ST***	***SSW 1/4 - 1/2 (0.353 mi.)***	***S83***	***452***
Spill Number/Closed Date: 8803558 / 1988-09-29				
Site ID: 287908				
Program Number: 8803558				
HT STEEL	***375 SMITH STREET***	***SSW 1/4 - 1/2 (0.358 mi.)***	***S84***	***470***
Spill Number/Closed Date: 9311399 / 1994-02-15				
Site ID: 84738				
Program Number: 9311399				
EAGLE FUEL TRANSPORT	***50 REPUBLIC ROAD***	***SW 1/4 - 1/2 (0.368 mi.)***	***R86***	***478***
Spill Number/Closed Date: 9201913 / 1992-09-28				
Site ID: 243590				
Program Number: 9201913				
CITICORP CREDIT SERV	***135 DURYEA ROAD***	***WNW 1/4 - 1/2 (0.425 mi.)***	***89***	***494***
Spill Number/Closed Date: 9007825 / 1990-12-12				
Spill Number/Closed Date: 9204935 / 1995-04-05				
Site ID: 247914				

Site ID: 247915
Program Number: 9007825
Program Number: 9204935

ESTEE LAUDER INC RES	***125 PINELAWN RD***	***N 1/4 - 1/2 (0.433 mi.)***	***90***	***498***
FORMERLY EMBASSY IND	***300 SMITH ST***	***SSW 1/4 - 1/2 (0.480 mi.)***	***92***	***538***

Spill Number/Closed Date: 9100457 / 1991-07-22
Site ID: 144684
Program Number: 9100457

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 24 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWSDAY	25 DESHON DR	WNW 0 - 1/8 (0.017 mi.)	C15	155
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08596 Facility ID: 08596				
TRIBUNE LLC	25 DESHON DR	WNW 0 - 1/8 (0.017 mi.)	C19	167
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08656 Status: INACTIVE Facility ID: 08656				
PARAGON ENTERPRISES	125 BAYLIS RD	NNW 1/8 - 1/4 (0.200 mi.)	N56	334
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08235 Facility ID: 08235				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARE ROSE	***255 CNTY RD 3 PINELA***	***ESE 0 - 1/8 (0.003 mi.)***	***B13***	***141***
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07581 Facility ID: 07581				
EASTERN ATHLETIC	100 RULAND RD	NNE 0 - 1/8 (0.032 mi.)	D22	171
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 17467 Facility ID: 17467				
CLARE ROSE INC	255 PINELAWN RD	SE 0 - 1/8 (0.050 mi.)	E25	175
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 01373 Status: ACTIVE Facility ID: 01373				
WOODBOURNE CULTURAL	***301 COLONIAL SPRING***	***NNE 0 - 1/8 (0.082 mi.)***	***F31***	***191***
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015				

Site Ref#: 12333
Status: ACTIVE
Facility ID: 12333

WOODBOURNE CULTURAL	301 COLONIAL SPRING	NNE 0 - 1/8 (0.082 mi.)	F33	200
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07529 Facility ID: 07529				
MRP FAMILY HOLDINGS	101 MARCUS DR	S 0 - 1/8 (0.104 mi.)	H37	222
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 16483 Facility ID: 16483				
RACANELLI COMMERCIAL	102 MARCUS DR	SSE 0 - 1/8 (0.119 mi.)	H39	225
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 11311 Status: INACTIVE Facility ID: 11311				
FONAR TRAVEL	102 MARCUS DR	SSE 0 - 1/8 (0.119 mi.)	H40	226
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07114 Facility ID: 07114				
DON JAGODA INC	102 MARCUS DR	SSE 0 - 1/8 (0.119 mi.)	H41	227
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07203 Facility ID: 07203				
ESPRIT BLDG	100 MARCUS DR	S 1/8 - 1/4 (0.127 mi.)	H43	235
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07104 Facility ID: 07104				
MEDISYS HEALTH NETWO	80 MARCUS DR	SSW 1/8 - 1/4 (0.148 mi.)	K49	289
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07596 Facility ID: 07596				
M & W RECKSON ASSOCI	110 MARCUS DR	SSE 1/8 - 1/4 (0.150 mi.)	L52	312
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08229 Facility ID: 08229				
RULAND ROAD LLC	95 RULAND RD	WNW 1/8 - 1/4 (0.173 mi.)	M53	314
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 07153 Facility ID: 07153				
CANADA DRY BOTTLING	***135 BAYLIS RD***	***NNW 1/8 - 1/4 (0.174 mi.)***	***55***	***329***
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 06840 Facility ID: 06840				
LABORATORY CORP OF A	170 FINN CT	SSE 1/8 - 1/4 (0.221 mi.)	O59	338
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 00450 Facility ID: 00450				
ARTEK	170 FINN CT	SSE 1/8 - 1/4 (0.221 mi.)	O62	362
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 02248				

Facility ID: 02248

FALA INC	70 MARCUS DR	SSW 1/8 - 1/4 (0.222 mi.)	63	363
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08240 Facility ID: 08240				
NATIONAL ENVIRONMENT	150 FINN CT	SSE 1/8 - 1/4 (0.228 mi.)	O65	366
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 01116 Facility ID: 01116				
MAYTAG BLDG	100 FINN CT	SSE 1/8 - 1/4 (0.230 mi.)	P72	403
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 00363 Facility ID: 00363				
FALA DIRECT MARKETIN	75 MARCUS DR	SW 1/8 - 1/4 (0.230 mi.)	Q73	404
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08603 Facility ID: 08603				
AIRCRAFT PARTS CORP	160 FINN CT	SSE 1/8 - 1/4 (0.239 mi.)	O76	435
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 00100 Facility ID: 00100				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 13 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWSDAY	25 DESHON DR	WNW 0 - 1/8 (0.017 mi.)	C16	158
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 08596 Facility Id: 08596				
TRIBUNE LLC	25 DESHON DR	WNW 0 - 1/8 (0.017 mi.)	C17	163
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 08656 Status: INACTIVE Facility Id: 08656				
LINOTYPE-HELL CO	80 RULAND RD	WNW 0 - 1/8 (0.083 mi.)	G35	217
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 07760 Facility Id: 07760				
OTTO KEIL FLORIST	107 RULAND RD	WNW 0 - 1/8 (0.104 mi.)	G38	224
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 07769 Facility Id: 07769				
COMAX MANUFACTURING	130 BAYLIS RD	NNW 1/8 - 1/4 (0.142 mi.)	J48	284
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 08369 Facility Id: 08369				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARE ROSE	***255 CNTY RD 3 PINELA***	***ESE 0 - 1/8 (0.003 mi.)***	***B13***	***141***
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015				

Site Ref#: 07581
Facility Id: 07581

CLARE ROSE INC | 255 PINELAWN RD | SE 0 - 1/8 (0.050 mi.) | E26 | 180
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 01373
Status: ACTIVE
Facility Id: 01373

WOODBOURNE CULTURAL | 301 COLONIAL SPRING | NNE 0 - 1/8 (0.082 mi.) | F30 | 187
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 12333
Status: ACTIVE
Facility Id: 12333

WOODBOURNE CULTURAL | 301 COLONIAL SPRING | NNE 0 - 1/8 (0.082 mi.) | F31 | 191
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 07529
Facility Id: 07529

RULAND ROAD LLC | 95 RULAND RD | WNW 1/8 - 1/4 (0.173 mi.) | M54 | 321
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 07153
Facility Id: 07153

CANADA DRY BOTTLING | 135 BAYLIS RD | NNW 1/8 - 1/4 (0.174 mi.) | 55 | 329
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 06840
Facility Id: 06840

MIP INC | 130 FINN CT | SSE 1/8 - 1/4 (0.229 mi.) | P69 | 388
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 00431
Facility Id: 00431

AIRCRAFT PARTS INC | 160 FINN COURT | SSE 1/8 - 1/4 (0.239 mi.) | O77 | 436
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 00100
Facility Id: 00100

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 3 NY VCP sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR	***540 SMITH STREET***	***S 1/4 - 1/2 (0.364 mi.)***	***85***	***473***
Database: VCP, Date of Government Version: 11/14/2016 Site Code: 56903				
RECKSON ASSOCIATES	***333 SMITH ST***	***SSW 1/4 - 1/2 (0.389 mi.)***	***87***	***480***
Database: VCP, Date of Government Version: 11/14/2016 Site Code: 58757				
CANTOR BROTHERS	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.463 mi.)***	***91***	***532***
Database: VCP, Date of Government Version: 11/14/2016				

EXECUTIVE SUMMARY

Site Code: 57869

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 11/14/2016 has revealed that there is 1 NY DEL SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	***168 CENTRAL AVENUE***	***S 1/2 - 1 (0.602 mi.)***	***T95***	***573***

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/06/2017 has revealed that there are 12 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J.M ALBRIZZIO Spill Number/Closed Date: 9309731 / 1993-12-24 spillno: 9309731 Site ID: 134618	25 DESCHON DRIVE	WNW 0 - 1/8 (0.017 mi.)	C18	166
NEWSDAY Spill Number/Closed Date: 0550849 / 2005-09-09 spillno: 0550849 Site ID: 351331	25 DESHON DRIVE	WNW 0 - 1/8 (0.017 mi.)	C20	168
PATTERSON BUILDING Spill Number/Closed Date: 0106454 / 2001-09-27 spillno: 0106454 Site ID: 321344	25 DESHON DR/MARCUS	WSW 0 - 1/8 (0.071 mi.)	29	186

Lower Elevation	Address	Direction / Distance	Map ID	Page
IMPERIAL NEWS CO Spill Number/Closed Date: 0906309 / 2010-03-22 Spill Number/Closed Date: 9308159 / 2004-06-02 Spill Number/Closed Date: 8603300 / 1986-10-01 spillno: 0906309 spillno: 8603300 spillno: 9308159	255 PINELAWN ROAD	ESE 0 - 1/8 (0.003 mi.)	B9	132

Site ID: 418639
Site ID: 202109
Site ID: 202110

CLARE ROSE	255 PINELAWN RD/MARC	ESE 0 - 1/8 (0.003 mi.)	B10	135
Spill Number/Closed Date: 0890480 / 2009-04-30 spillno: 0890480 Site ID: 399610				
CLARE ROSE	255 PINE LAWN ROAD	ESE 0 - 1/8 (0.003 mi.)	B11	137
Spill Number/Closed Date: 9402856 / 1994-11-09 spillno: 9402856 Site ID: 329995				
EASTERN ATHLETIC CLU	100 RULAND ROAD	NNE 0 - 1/8 (0.032 mi.)	D21	170
Spill Number/Closed Date: 0910535 / 2009-12-28 spillno: 0910535 Site ID: 423296				
BUSINESS	255 PINELAWN ROAD	SE 0 - 1/8 (0.050 mi.)	E24	174
Spill Number/Closed Date: 1303748 / 2013-12-16 spillno: 1303748 Site ID: 484245				
UNKNOWN	PINELAWN ROAD/RULAND	NNE 0 - 1/8 (0.070 mi.)	D27	184
Spill Number/Closed Date: 0303103 / 2003-07-02 spillno: 0303103 Site ID: 110727				
UNKNOWN	PINE LAWN & RULAN RO	NNE 0 - 1/8 (0.070 mi.)	D28	185
Spill Number/Closed Date: 8600899 / 1987-04-22 spillno: 8600899 Site ID: 296193				
WOODBOURNE CULTURAL	301 COLONIAL SPRINGS	NNE 0 - 1/8 (0.082 mi.)	F32	199
Spill Number/Closed Date: 0801935 / 2008-10-30 spillno: 0801935 Site ID: 397985				
PERGAMENT	***101 MARCUS DRIVE***	***S 0 - 1/8 (0.104 mi.)***	***H36***	***219***
Spill Number/Closed Date: 0013423 / 2001-10-03 Spill Number/Closed Date: 0013428 / 2001-03-23 spillno: 0013423 spillno: 0013428 Site ID: 328273 Site ID: 328274				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/12/2016 has revealed that there are 11 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TRIBUNE COMPANY	***25 DESHON DR***	***WNW 0 - 1/8 (0.017 mi.)***	***C14***	***150***
HEIDELBERG PUBLISHIN	***80 RULAND RD***	***WNW 0 - 1/8 (0.083 mi.)***	***G34***	***207***

Lower Elevation	Address	Direction / Distance	Map ID	Page
IMPERIAL NEWS	***255 PINELAWN RD***	***ESE 0 - 1/8 (0.003 mi.)***	***B12***	***138***
COSTCO	625 RULAND RD	NNE 0 - 1/8 (0.048 mi.)	D23	173
HONEYWELL INC	***175 PINELAWN RD***	***N 1/8 - 1/4 (0.138 mi.)***	***I45***	***238***
GENOVESE DRUG STORES	***80 MARCUS DR***	***SSW 1/8 - 1/4 (0.148 mi.)***	***K50***	***291***
110 MARCUS DR	***110 MARCUS DR***	***SSE 1/8 - 1/4 (0.150 mi.)***	***L51***	***300***
ROCHE BIOMEDICAL LAB	***170 FINN CT***	***SSE 1/8 - 1/4 (0.221 mi.)***	***O60***	***339***
ROCHE BIOMEDICAL LAB	***170 FINN CT***	***SSE 1/8 - 1/4 (0.221 mi.)***	***O61***	***352***
MANUFACTURERS INDEXI	***130 FINN CT***	***SSE 1/8 - 1/4 (0.229 mi.)***	***P70***	***389***
AIRCRAFT PARTS INC	***160 FINN COURT***	***SSE 1/8 - 1/4 (0.239 mi.)***	***O77***	***436***

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 11/25/2013 has revealed that there are 2 ROD sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	***168 CENTRAL AVENUE***	***S 1/2 - 1 (0.510 mi.)***	***93***	***548***
CIRCUITRON CORP.	***82 MILBAR BOULEVARD***	***SW 1/2 - 1 (0.967 mi.)***	***U101***	***736***

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/30/2017 has revealed that there are 18 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TRIBUNE COMPANY EPA ID: NYD002052504	***25 DESHON DR***	***WNW 0 - 1/8 (0.017 mi.)***	***C14***	***150***
HEIDELBERG PUBLISHIN EPA ID: NYD986885457	***80 RULAND RD***	***WNW 0 - 1/8 (0.083 mi.)***	***G34***	***207***
COMAX FLAVORS EPA ID: NYD016914376	***130 BAYLISS RD***	***NNW 1/8 - 1/4 (0.142 mi.)***	***J47***	***253***

Lower Elevation	Address	Direction / Distance	Map ID	Page
IMPERIAL NEWS EPA ID: NYD986952588	***255 PINELAWN RD***	***ESE 0 - 1/8 (0.003 mi.)***	***B12***	***138***
PERGAMENT EPA ID: NYP000736259	***101 MARCUS DRIVE***	***S 0 - 1/8 (0.104 mi.)***	***H36***	***219***
NEW YORK STATE DRUG EPA ID: NYP000916015	175 PINELAWN RD SUIT	N 1/8 - 1/4 (0.138 mi.)	I44	236
HONEYWELL INC	***175 PINELAWN RD***	***N 1/8 - 1/4 (0.138 mi.)***	***I45***	***238***

EPA ID: NYR000004804

85 MARCUS DR	***85 MARCUS DR***	***SW 1/8 - 1/4 (0.141 mi.)***	***46***	***243***
EPA ID: NYD980766349				
GENOVESE DRUG STORES	***80 MARCUS DR***	***SSW 1/8 - 1/4 (0.148 mi.)***	***K50***	***291***
EPA ID: NYD012364949				
110 MARCUS DR	***110 MARCUS DR***	***SSE 1/8 - 1/4 (0.150 mi.)***	***L51***	***300***
EPA Id: NYD986908853				
ROCHE BIOMEDICAL LAB	***170 FINN CT***	***SSE 1/8 - 1/4 (0.221 mi.)***	***O60***	***339***
EPA ID: NYD986899219				
ROCHE BIOMEDICAL LAB	***170 FINN CT***	***SSE 1/8 - 1/4 (0.221 mi.)***	***O61***	***352***
EPA ID: NYD047645700				
PRECIPART CORPORATIO	***150 FINN COURT***	***SSE 1/8 - 1/4 (0.228 mi.)***	***O66***	***367***
EPA Id: NYR000087247				
Manifest Document Number: 002592282SKS				
MORRIS BROTHERS AUTO	***150 FINN COURT***	***SSE 1/8 - 1/4 (0.228 mi.)***	***O67***	***383***
EPA ID: NYP000786608				
MANUFACTURERS INDEXI	***130 FINN CT***	***SSE 1/8 - 1/4 (0.229 mi.)***	***P70***	***389***
EPA ID: NYR000021436				
PRECIPART CORP	***100 FINN CT***	***SSE 1/8 - 1/4 (0.230 mi.)***	***P71***	***392***
EPA ID: NYR000093864				
FALA CCG INC	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.230 mi.)***	***Q74***	***406***
EPA ID: NYR000067322				
AIRCRAFT PARTS INC	***160 FINN CT***	***SSE 1/8 - 1/4 (0.239 mi.)***	***O75***	***423***
EPA ID: NYD013561139				

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2015 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORP	150 FINN COURT	SSE 1/8 - 1/4 (0.228 mi.)	O68	387
Generator EPA Id: NYR000087247				

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2013 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORPORATIO	***150 FINN COURT***	***SSE 1/8 - 1/4 (0.228 mi.)***	***O66***	***367***
EPA Id: NYR000087247				
Manifest Document Number: 002592282SKS				

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2015 has revealed that there are 4 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMAX FLAVORS EPA ID: NYD016914376	***130 BAYLISS RD***	***NNW 1/8 - 1/4 (0.142 mi.)***	***J47***	***253***


Lower Elevation	Address	Direction / Distance	Map ID	Page
110 MARCUS DR EPA Id: NYD986908853	***110 MARCUS DR***	***SSE 1/8 - 1/4 (0.150 mi.)***	***L51***	***300***
FALA CCG INC EPA ID: NYR000067322	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.230 mi.)***	***Q74***	***406***
AIRCRAFT PARTS INC EPA ID: NYD013561139	***160 FINN CT***	***SSE 1/8 - 1/4 (0.239 mi.)***	***O75***	***423***

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
PINELAWN/FARMINGDALE - HORTONSPHER	NY SHWS
MELVILLE PLUME TRACKDOWN	NY SHWS
RJN ASSOCIATES; LTD	NY SWF/LF

OVERVIEW MAP - 4977850.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Pipelines

National Wetland Inventory


State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Newsday	CLIENT:	Gaiatech Real Estate Division
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Grace Riordan
		INQUIRY #:	4977850.2s
LAT/LONG:	40.763451 / 73.406648	DATE:	June 27, 2017 9:18 am

Copyright © 2017 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 4977850.2S



Target Property
Sites at elevations higher than or equal to the target property
Sites at elevations lower than the target property
Manufactured Gas Plants
Sensitive Receptors
National Priority List Sites
Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA
Power transmission lines
National Wetland Inventory
State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Newsday	CLIENT:	Gaiatech Real Estate Division
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Grace Riordan
LAT/LONG:	40.763451 / 73.406648	INQUIRY #:	4977850.2s
		DATE:	June 27, 2017 9:24 am

Copyright © 2017 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	1	NR	1
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500	1	0	0	0	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	1	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250	1	0	1	NR	NR	NR	2
RCRA-SQG	0.250		0	4	NR	NR	NR	4
RCRA-CESQG	0.250		0	1	NR	NR	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	2	5	NR	7
NY VAPOR REOPENED	1.000		0	0	2	1	NR	3
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500	1	0	8	12	NR	NR	21
NY HIST LTANKS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250	2	11	13	NR	NR	NR	26
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	0	NR	NR	NR	0
NY AST	0.250	2	8	5	NR	NR	NR	15
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	3	NR	NR	3
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	0	0	NR	NR	0
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	1	NR	1
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	3	12	NR	NR	NR	NR	15
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	4	7	NR	NR	NR	12
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	2	NR	2
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	1	NR	NR	NR	NR	NR	1
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.500		0	0	0	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250	2	4	14	NR	NR	NR	20
PA MANIFEST	0.250		0	1	NR	NR	NR	1
RI MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250	1	0	4	NR	NR	NR	5
NY SPDES	TP	1	NR	NR	NR	NR	NR	1
NY UIC	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		21	39	59	19	12	0	150

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **NEWSDAY INC** **NY AST** **1006305114**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 1 of 8 in cluster A

Actual:
105 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07934
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07934
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	NEWSDAY INC ATTN:J MARINO
Storage Owner Address:	235 PINELAWN RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	07934
Facility Reference #:	02037
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	10
Tank Key:	23077
Year Installed:	79
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

NEWSDAY INC (Continued) **1006305114**

Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	11
Tank Key:	23078
Year Installed:	78
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	12
Tank Key:	23079
Year Installed:	78
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

NEWSDAY INC (Continued) **1006305114**

Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	13
Tank Key:	23080
Year Installed:	78
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	020601

Tank ID:	17
Tank Key:	23084
Year Installed:	78
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

NEWSDAY INC (Continued) **1006305114**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	21
Tank Key:	23088
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000004675
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	22
Tank Key:	23089
Year Installed:	91
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	041991
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001380
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

NEWSDAY INC (Continued) **1006305114**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	23
Tank Key:	23090
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	041991
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	24
Tank Key:	23091
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	041991
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000165
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

NEWSDAY INC (Continued) **1006305114**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	25
Tank Key:	23092
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	041991
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	26
Tank Key:	23093
Year Installed:	89
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported

NEWSDAY INC (Continued) **1006305114**

Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	121602

Tank ID:	27
Tank Key:	23094
Year Installed:	89
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	121602

Tank ID:	28
Tank Key:	23095
Year Installed:	89
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

NEWSDAY INC (Continued) **1006305114**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	072903

Tank ID:	29
Tank Key:	23096
Year Installed:	92
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 03
Permit to Operate:	020601
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002640
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	072903

Tank ID:	30
Tank Key:	23097
Year Installed:	Not reported
Substance:	CAUSTIC
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 06
Permit to Operate:	020601
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

NEWSDAY INC (Continued) **1006305114**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	022306

Tank ID:	31
Tank Key:	23098
Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	32
Tank Key:	23099
Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported

NEWSDAY INC (Continued) **1006305114**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	33
Tank Key:	23100
Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	34
Tank Key:	23101
Year Installed:	86
Substance:	CYAN INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported

NEWSDAY INC (Continued) **1006305114**

Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	35
Tank Key:	23102
Year Installed:	86
Substance:	YELLOW INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	36
Tank Key:	23103
Year Installed:	86
Substance:	RED INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported

NEWSDAY INC (Continued) **1006305114**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	37
Tank Key:	23104
Year Installed:	86
Substance:	MAGENTA INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	38
Tank Key:	23105
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000125
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

NEWSDAY INC (Continued) **1006305114**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	39
Tank Key:	23106
Year Installed:	Not reported
Substance:	COOLING TOWER BLOW D
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	072903

Tank ID:	40
Tank Key:	23107
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000025
Date Permitted:	Not reported
Date Closed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	41
Tank Key:	23108
Year Installed:	Not reported
Substance:	COLLING WATER BLOW D
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	42
Tank Key:	43056
Year Installed:	1998
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000050
Date Permitted:	Not reported

NEWSDAY INC (Continued) **1006305114**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	43
Tank Key:	43057
Year Installed:	1998
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	121602

Tank ID:	44
Tank Key:	43058
Year Installed:	2000
Substance:	DEVELOPER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000055

NEWSDAY INC (Continued) **1006305114**

Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	45
Tank Key:	43059
Year Installed:	Not reported
Substance:	DEVELOPER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	46
Tank Key:	43060
Year Installed:	Not reported
Substance:	FIXER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported

NEWSDAY INC (Continued) **1006305114**

Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	47
Tank Key:	43061
Year Installed:	Not reported
Substance:	FIXER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	48
Tank Key:	43062
Year Installed:	Not reported
Substance:	PHOTO CHEMS
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE

NEWSDAY INC (Continued) **1006305114**

Tabk Status:	Not reported
Total Capacity:	0000000066
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	49
Tank Key:	43063
Year Installed:	Not reported
Substance:	DRY PHOTO CHEMS
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	50
Tank Key:	43064
Year Installed:	Not reported
Substance:	SOLVENT PARTS WASHER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 05
Permit to Operate:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	010605

Tank ID:	51
Tank Key:	43065
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	121602

Tank ID:	52
Tank Key:	43066
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02

NEWSDAY INC (Continued) **1006305114**

Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	121602

Tank ID:	53
Tank Key:	43067
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	121602

Tank ID:	54
Tank Key:	43068
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported

NEWSDAY INC (Continued) **1006305114**

Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	121602

Tank ID:	55
Tank Key:	43069
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 06
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	022306

Tank ID:	56
Tank Key:	43070
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL

NEWSDAY INC (Continued) **1006305114**

Dispenser:	Not reported
Official Use:	Removed Tank. 06
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	022306

Tank ID:	57
Tank Key:	43071
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	58
Tank Key:	43072
Year Installed:	Not reported
Substance:	BOILER CHEMICAL

NEWSDAY INC (Continued) **1006305114**

Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	59
Tank Key:	43073
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	60
Tank Key:	43074
Year Installed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	61
Tank Key:	43075
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	62
Tank Key:	43076

NEWSDAY INC (Continued) **1006305114**

Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	63
Tank Key:	43077
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	64

NEWSDAY INC (Continued) **1006305114**

Tank Key:	43078
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	65
Tank Key:	43079
Year Installed:	Not reported
Substance:	METHANOL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000225
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	66
Tank Key:	43080
Year Installed:	02
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000660
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	67
Tank Key:	43081
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000440
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	072903

NEWSDAY INC (Continued) **1006305114**

Tank ID:	68
Tank Key:	43082
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000005280
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	69
Tank Key:	43083
Year Installed:	Not reported
Substance:	SALT/SAND STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000010
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	101602

NEWSDAY INC (Continued) **1006305114**

Tank ID:	70
Tank Key:	43084
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000101
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	71
Tank Key:	43085
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000081
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	72
Tank Key:	43086
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000600
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	101602

Tank ID:	73
Tank Key:	43087
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000120
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	74
Tank Key:	43088
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	101602

Tank ID:	75
Tank Key:	44155
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	76
Tank Key:	44156
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	77
Tank Key:	44157
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	78
Tank Key:	44158
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	79
Tank Key:	44159
Year Installed:	Not reported
Substance:	TRANSFER FACILITY
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000660
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	80
Tank Key:	44160
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000060
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	81
Tank Key:	44161
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000060
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	82
Tank Key:	44162
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000050
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	83
Tank Key:	44163
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	072903
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	84
Tank Key:	44543
Year Installed:	Not reported
Substance:	Not reported
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121602
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002860
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	85
Tank Key:	47001
Year Installed:	Not reported
Substance:	DEGREASER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	010605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	86
Tank Key:	47927
Year Installed:	2006
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	87
Tank Key:	47928
Year Installed:	2006
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	022706
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	9
Tank Key:	23076
Year Installed:	78
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

A2 **INDUSTRIAL** **NY Spills** **S118952427**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY**

Site 2 of 8 in cluster A

Actual:
105 ft.

SPILLS:

Facility ID:	1606790
Facility Type:	ER
DER Facility ID:	422538
Site ID:	533430
DEC Region:	1
Spill Date:	2016-10-11
Spill Number/Closed Date:	1606790 / Not Reported
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	RJPOCZKA
Referred To:	Not reported
Reported to Dept:	2016-10-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

INDUSTRIAL (Continued) **S118952427**

UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2016-10-11
Spill Record Last Update:	2016-10-18
Spiller Name:	Not reported
Spiller Company:	NEWSDAY LLC
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	JOSEPH MARINO
Contact Phone:	(631) 843-2044
DEC Memo:	"10/11/16 @ 1130 AM -WG called Mr. Marino (Newsday LLC) -No answer. Left message. 10/11/16 @ 1230 PM--Rob was dispatched to the site. 10/11/16 1250 Hrs: RJP on location. Marino did not answer phone, RJP requested him at reception desk. Electric air compressor, 12 gal capacity of synthetic compressor oil, SAE 30 non-detergent. Failure of weld at joint, release of approx. 4 gallons. 4 gallons remains in equipment, 4 gallons recovered in buckets. Release to base of compressor, concrete floor, and floor drain. Absorbent pads placed, compressor out of service pending repairs. Drain connected to on-site wastewater collection and treatment facility. Facility operates oil/water separator and utilizes mechanical, chemical, and bacteriological treatment prior to discharge. Incident was also referred to the Water Unit."
Remarks:	"the spill went into the waste treatment plant that will go into underground pools. The cleanup is pending. It would be process or clean in the treatment plant."

Material:

Site ID:	533430
Operable Unit ID:	1282150
Operable Unit:	01
Material ID:	2287488
Material Code:	0811A
Material Name:	compressor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

A3 **NEWSDAY** **NY Spills** **S118460063**
Target **235 PINELAWN ROAD** **N/A**
Property **MELVILLE, NY**

Site 3 of 8 in cluster A

Actual: 105 ft.

SPILLS:

Facility ID:	1508951
Facility Type:	ER
DER Facility ID:	300411
Site ID:	517549
DEC Region:	1

NEWSDAY (Continued) **S118460063**

Spill Date:	2015-12-02
Spill Number/Closed Date:	1508951 / 2015-12-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	RJPOCZKA
Referred To:	Not reported
Reported to Dept:	2015-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-02
Spill Record Last Update:	2016-03-07
Spiller Name:	JOSEPH MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	JOSEPH MARINO
Contact Phone:	(631) 843-2044
DEC Memo:	"12/02/15 1050 Hrs (A): Called Marino- he said a hose burst on a generator INSIDE their facility, but the fluid spilled outside to a drywell. He confirmed that the drywell has no outlets and a sand bottom, and that MEG is responding. 12/02/15 1050 Hrs (B): DEC informed him that this office might have RJP (currently in Farmingdale) respond when finished there. DR 12/02/15 1052 Hrs: RJP called- he just finished in Farmingdale and saw this report, so he will respond at this time. DR 12/02/15 approx noon: As per RJP- ALL the product appears to have soaked into the sand at the bottom of the drywell. He will obtain a copy of the MSDS sheet from Newsday. DR 12/2/15 1135 Hrs: RJP on location w/ MEG. No recoverable liquid, no DEC action. Documents on D2. RJP"
Remarks:	"Spill contained to drive well, Miller environmental enroute for pump out of fluid."

Material:

Site ID:	517549
Operable Unit ID:	1266624
Operable Unit:	01
Material ID:	2270570
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	60.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

NEWSDAY (Continued) **S118460063**

Tank Test:

A4
Target
Property

NEWSDAY, LLC
235 PINELAWN ROAD
MELVILLE, NY 11747

Site 4 of 8 in cluster A

Actual:
105 ft.

SEMS-ARCHIVE **1000378809**
RCRA-LQG **NYD052782497**
NY LTANKS
NY Spills
ICIS
US AIRS
FINDS
ECHO
NY MANIFEST
NJ MANIFEST
NY SPDES

SEMS-ARCHIVE:
Site ID: 202958
EPA ID: NYD052782497
Federal Facility: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:
Site ID: 0202958
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Alias Name(s):
Alias Name: NEWSDAY INC
Alias Address: Not reported
SUFFOLK, NY

CERCLIS-NFRAP Assessment History:
Action: ARCHIVE SITE
Date Started: / /
Date Completed: 10/21/98
Priority Level: Not reported

Action: DISCOVERY
Date Started: / /
Date Completed: 02/28/89
Priority Level: Not reported

Action: SITE INSPECTION
Date Started: / /
Date Completed: 09/28/98
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

Action: PRELIMINARY ASSESSMENT
Date Started: 02/28/89
Date Completed: 03/31/89
Priority Level: Higher priority for further assessment

RCRA-LQG:
Date form received by agency: 03/06/2014

NEWSDAY, LLC (Continued) **1000378809**

Facility name:	NEWSDAY LLC
Facility address:	235 PINELAWN ROAD MELVILLE, NY 11747
EPA ID:	NYD052782497
Mailing address:	PINELAWN ROAD MELVILLE, NY 11747
Contact:	JOSEPH MARINO
Contact address:	PINELAWN ROAD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(631) 843-2044
Contact email:	JOE.MARINO@NEWSDAY.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	Not reported
Owner/operator telephone:	(516) 454-2020
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TRIBUNE ND INC
Owner/operator address:	N MICHIGAN AVENUE CHICAGO, IL 60611
Owner/operator country:	US
Owner/operator telephone:	(312) 222-9100
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/26/2008
Owner/Op end date:	Not reported

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN ROAD OPERCITY, NY 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(516) 454-2020
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Owner/Op end date: Not reported

Owner/operator name: NEWSDAY LLC
Owner/operator address: N MICHIGAN AVENUE
CHICAGO, IL 60611
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1979
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

NEWSDAY, LLC (Continued) **1000378809**

Historical Generators:
Date form received by agency: 01/01/2007
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 01/16/2006
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/15/2006
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 02/18/2004
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 11/19/2002
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: NEWSDAY INC
Classification: Large Quantity Generator

NEWSDAY, LLC (Continued) **1000378809**

Date form received by agency: 02/27/1998
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 06/10/1996
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/18/1994
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 02/14/1992
Site name: NEWSDAY, INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1981
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1981
Site name: NEWSDAY INC
Classification: Not a generator, verified

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K086
. Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE

NEWSDAY, LLC (Continued) **1000378809**

FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U227
. Waste name: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 10/29/1980
Site name: NEWSDAY INC
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL

NEWSDAY, LLC (Continued) **1000378809**

BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K086
. Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U227
. Waste name: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

NEWSDAY, LLC (Continued) **1000378809**

Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 09/29/2015
Date achieved compliance: 10/05/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/25/2012
Date achieved compliance: 09/11/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2012
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/13/2012
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 07/25/2012
Date achieved compliance: 07/25/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2012
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/13/2012
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

NEWSDAY, LLC (Continued) **1000378809**

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 12/07/2005
Date achieved compliance: 12/07/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Contingency Plan and Emergency Procedures
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

NEWSDAY, LLC (Continued) **1000378809**

Area of violation: TSD IS-Container Use and Management
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 12/07/2005
Date achieved compliance: 12/07/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

NEWSDAY, LLC (Continued) **1000378809**

Date violation determined: 03/31/1997
Date achieved compliance: 06/11/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/23/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/31/1997
Date achieved compliance: 06/11/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/31/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/29/1988
Date achieved compliance: 06/16/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/03/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/1986
Date achieved compliance: 10/24/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

NEWSDAY, LLC (Continued) **1000378809**

Area of violation: Generators - Records/Reporting
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 10/05/2015
Evaluation lead agency: State

Evaluation date: 07/25/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 09/11/2012
Evaluation lead agency: State

Evaluation date: 07/25/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 07/25/2012
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Records/Reporting
Date achieved compliance: 12/07/2005
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Contingency Plan and Emergency Procedures
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

NEWSDAY, LLC (Continued) **1000378809**

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-General Facility Standards
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 12/07/2005
Evaluation lead agency: State

Evaluation date: 03/07/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/11/1997
Evaluation lead agency: State

Evaluation date: 08/29/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 11/29/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/16/1989
Evaluation lead agency: State

Evaluation date: 05/20/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/24/1986
Evaluation lead agency: State

LTANKS:
Site ID: 276627
Spill Number/Closed Date: 9201246 / 1998-05-27
Spill Date: 1992-04-30
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True

NEWSDAY, LLC (Continued) **1000378809**

SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1992-04-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-04
Spill Record Last Update:	2016-10-12
Spiller Name:	JOHN TILLATSON
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	300411
DEC Memo:	"TANK ALONE PASSED 5/15/92. SYSTEMS TEST PASSED 5/15/92. FILL BOX REPLACED. LEAKAGE FROM COMPRESSION PIPE. CLEANUP JUST BELOW THE SURFACE MOUNTED FILL CAP, ~ 2YDS OF CONTAMINATED SOIL REMOVED"
Remarks:	"25K FAILED AT -.493, DRY AS A BONE TESTER, SCDH NOTIFIED, TYREE TO DO CLEANUP"

Material:

Site ID:	276627
Operable Unit ID:	968626
Operable Unit:	01
Material ID:	412574
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	276627
Spill Tank Test:	1539939
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

NEWSDAY, LLC (Continued) **1000378809**

Site ID:	276630
Spill Number/Closed Date:	9709711 / 2009-12-11
Spill Date:	1997-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1997-11-20
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-11-20
Spill Record Last Update:	2016-10-12
Spiller Name:	DAVE KRUEGER
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, ZZ
Spiller County:	001
Spiller Contact:	DAVE KRUEGER
Spiller Phone:	(516) 843-5437
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	300411
DEC Memo:	"HISTORY OF PROBLEMS WITH INTERFERENCE WHEN TESTING, LATER TESTS PASSED"
Remarks:	"gross failure on system test "

Material:

Tank Test:

Site ID:	276630
Spill Tank Test:	1545479
Tank Number:	south
Tank Size:	25000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Site ID:	465817
Spill Number/Closed Date:	1203029 / 2014-04-07
Spill Date:	2012-06-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

NEWSDAY, LLC (Continued) **1000378809**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	5226
Investigator:	hmcirrit
Referred To:	Not reported
Reported to Dept:	2012-06-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-26
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	NEWSDAY INC
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	999
Spiller Contact:	DJ OCONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	300411
DEC Memo:	"TANK ABANDONED IN PLACE"
Remarks:	"Tank test failure. underground 25000g"

Material:

Site ID:	465817
Operable Unit ID:	1215830
Operable Unit:	01
Material ID:	2213978
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1402877
Facility Type:	ER
DER Facility ID:	300411
Site ID:	496217
DEC Region:	1
Spill Date:	2014-06-17
Spill Number/Closed Date:	1402877 / 2014-08-12

NEWSDAY, LLC (Continued) **1000378809**

Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	hmcirrit
Referred To:	Not reported
Reported to Dept:	2014-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-06-17
Spill Record Last Update:	2014-10-03
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	JOE MARINO
Contact Phone:	(631) 843-2044
DEC Memo:	"06/17/14 1210 Hrs: Left message for Libuser. DR 06/17/14 1250 Hrs (A): Libuser called- apparently, a test of some sort was performed overnight on the day tank for this generator. The solenoid which opens and closes the line failed and caused the spill. 06/17/14 1250 Hrs (B): At this time, Miller believes only a few gallons of oil spilled. THE CATCH BASIN IS INSIDE THE BUILDING, AND MILLER DOES NOT BELIEVE IT HAS ANY OUTLETS. 06/17/14 1250 Hrs (C): Miller is cleaning up the floor with speedi dri, and is bringing a guzzler truck to clean out the basin. 06/17/14 1250 Hrs (D): DEC directed Miller to keep this office updated. DR DRAIN CLEANED OUT, ENDPOINT SAMPLES ARE CLEAN, NO FURTHER ACTION REQUIRED"
Remarks:	"lost from generator, c/u in progress. loss to catch basin, unknown where that releases"

Material:

Site ID:	496217
Operable Unit ID:	1245709
Operable Unit:	01
Material ID:	2246746
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	496217
Operable Unit ID:	1245709
Operable Unit:	01
Material ID:	2246745

NEWSDAY, LLC (Continued) **1000378809**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	1205313
Facility Type:	ER
DER Facility ID:	380703
Site ID:	468240
DEC Region:	1
Spill Date:	2012-08-26
Spill Number/Closed Date:	1205313 / 2012-10-03
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	wxprzylo
Referred To:	Not reported
Reported to Dept:	2012-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-08-26
Spill Record Last Update:	2016-10-12
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	JOE MARINO
Contact Phone:	(516) 509-0495
DEC Memo:	"08/26/12 @13:20 t/c to notifier, by Mr Marino there was broken ink feeding tube on printing machine. MEG is working on cleanup. All is contained to the printing shop, no floor drains affected or odors outside of the building. (VP)"
Remarks:	"on concrete to inside bld. c/u in progrss, ,Miller Enviro on site"

Material:

Site ID:	468240
Operable Unit ID:	1218171
Operable Unit:	01

NEWSDAY, LLC (Continued) **1000378809**

Material ID:	2216544
Material Code:	9999
Material Name:	other - ink
Case No.:	Not reported
Material FA:	Other
Quantity:	2000.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	1200716
Facility Type:	ER
DER Facility ID:	300411
Site ID:	463369
DEC Region:	1
Spill Date:	2012-04-23
Spill Number/Closed Date:	1200716 / 2012-10-22
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2012-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-23
Spill Record Last Update:	2016-10-12
Spiller Name:	JOSEPH MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	JOSEPH MARINO
Contact Phone:	(631) 843-2044
DEC Memo:	"04/23/12 1330 Hrs (A): Called Marino- this was a spill of combined industrial/sanitary sewage from THEIR plant. 04/23/12 1330 Hrs (B): The waste spilled onto gravel, and the plant operator (SEVERIN TRENT) is cleaning up the spillage. 04/23/12 1330 Hrs (C): Spills informed Marino we would notify DEC Div of Water. DR 04/23/12 1535 Hrs: Copy of this report emailed to Tony Leung (DEC Div of Water). DR"
Remarks:	"system had loss due to weather, no waterways, c/u in progress"

Material:

NEWSDAY, LLC (Continued) **1000378809**

Site ID:	463369
Operable Unit ID:	1213465
Operable Unit:	01
Material ID:	2211426
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	500.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	1108374
Facility Type:	ER
DER Facility ID:	300411
Site ID:	456103
DEC Region:	1
Spill Date:	2011-10-01
Spill Number/Closed Date:	1108374 / 2011-10-03
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-10-01
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	PRE PRINT LOGISTICS
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	JOSEPH MARINO
Contact Phone:	(631) 843-2044
DEC Memo:	"10/3/2011 11:30 t/c to JOSEPH MARINO, NEWSDAY -Truck from Pre Print Logistics Management, INC. (800-596-2335) was making a delivery to Newsday. -When the truck was leaving, it was noticed that it was leaking diesel fuel. -The driver of the truck drove off. -Aprox 5 to 6 gallons spilled at the loading dock. -No drains affected, Miller completed the cleanup. (BD) "
Remarks:	"SPEEDY DRY HAS BEEN LAID ON THE SPILL CELL - 516-509-0495"

NEWSDAY, LLC (Continued) **1000378809**

Material:

Site ID:	456103
Operable Unit ID:	1206248
Operable Unit:	01
Material ID:	2203291
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	1000551
Facility Type:	ER
DER Facility ID:	300411
Site ID:	431720
DEC Region:	1
Spill Date:	2010-04-13
Spill Number/Closed Date:	1000551 / 2011-03-30
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2010-04-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-14
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	NEWSDAY
Spiller Address:	235 pinelawn rd
Spiller City,St,Zip:	melville, NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"3/28/11 TJD File review. All required documentation has been provided in support of spill closure. A total of 166.83 tons of petroleum impacted soils were excavated and properly disposed of during remedial process. Laboratory analysis reveals all target compounds are within acceptable concentrations. No further action is

NEWSDAY, LLC (Continued) **1000378809**

required."

Remarks: "WOERNER IS PREPARING TO REMOVE 3 20,000GAL DIESEL TANKS, AND FOUND CONTAMINATION UNDER THE DISPENSER. HE IS NOT CERTAIN WHEN THE TANKS WILL ACTUALLY BE REMOVED BECAUSE HE MUST HAVE SHORING INSTALLED, BUT HOPES THEY WILL BE REMOVED THIS WEEK OR NEXT. (DR)"

Material:

Site ID:	431720
Operable Unit ID:	1183191
Operable Unit:	01
Material ID:	2177394
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0507524
Facility Type:	ER
DER Facility ID:	300411
Site ID:	352993
DEC Region:	1
Spill Date:	2005-09-22
Spill Number/Closed Date:	0507524 / 2006-03-14
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2005-09-22
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2008-06-30
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	JOE MARINO
Contact Phone:	(516) 509-0495

NEWSDAY, LLC (Continued) **1000378809**

DEC Memo: "9/13/05 9:22 TELECON MARINO, INK RECLAIM MACHINE, FILTERED AND RECYCLED, AREA IS BERMED AND FLOOR IS SEALED. ESTIMATE ABOUT 100 GALS PUMPED INTO DRUMS. MACHINE WILL BE REPAIRED"
Remarks: "BERMED AREA, CONTAINED, AND CLEANED UP. DUE TO AN O RING ON A FILTER BREAKING."

Material:
Site ID: 352993
Operable Unit ID: 1110463
Operable Unit: 01
Material ID: 2100493
Material Code: 0582A
Material Name: ink
Case No.: Not reported
Material FA: Other
Quantity: 100.00
Units: Gallons
Recovered: 100.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0203990
Facility Type: ER
DER Facility ID: 224903
Site ID: 276625
DEC Region: 1
Spill Date: 2002-07-17
Spill Number/Closed Date: 0203990 / 2002-08-21
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5200
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 2002-07-17
CID: 204
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-07-17
Spill Record Last Update: 2002-09-09
Spiller Name: Not reported
Spiller Company: JAMAICA ASH
Spiller Address: UNKNOWN
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: STEPHEN CLUFF
Contact Phone: (631) 843-3631

NEWSDAY, LLC (Continued) **1000378809**

DEC Memo: ""
Remarks: "HYDROLIC LINE ON TRUCK BROKE *** 877-382-1737 - BEEPER ***"

Material:
Site ID: 276625
Operable Unit ID: 856785
Operable Unit: 01
Material ID: 518251
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: Gallons
Recovered: 20.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0125175
Facility Type: ER
DER Facility ID: 300411
Site ID: 276624
DEC Region: 1
Spill Date: 2001-08-27
Spill Number/Closed Date: 0125175 / 2004-09-16
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5226
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 2001-08-27
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-08-27
Spill Record Last Update: 2009-12-10
Spiller Name: STEPHEN CLUFF
Spiller Company: NEWSDAY
Spiller Address: 235 PINELAWN ROAD
Spiller City,St,Zip: MELVILLE, NY
Spiller Company: 001
Contact Name: SAME
Contact Phone: (516) 657-7012
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was UNASSIGNED 01-090 "
Remarks: "FAILURE OF HYDRAULIC HOSE ON DUMPSTER TRUCK. SPEEDY DRY APPLIED.

NEWSDAY, LLC (Continued) **1000378809**

TRUCK WAS OPERATED BY JAMAICA ASH. WILL USE ESI TO COMPLETE CLEANUP."

Material:

Site ID:	276624
Operable Unit ID:	849426
Operable Unit:	01
Material ID:	526504
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	20.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0008603
Facility Type:	ER
DER Facility ID:	300411
Site ID:	276623
DEC Region:	1
Spill Date:	2000-10-23
Spill Number/Closed Date:	0008603 / 2000-12-14
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	NJACAMPO
Referred To:	Not reported
Reported to Dept:	2000-10-23
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-23
Spill Record Last Update:	2011-12-27
Spiller Name:	STEPHEN CLUFF
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	STEPHEN CLUFF
Contact Phone:	(631) 843-3631
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ACAMPORA 10/24/00 STEVE CLUFF (NEWSDAY) CALLED, ACTUALLY 1000-1500 GAL SPILL, TRYING TO DETERMINE EXACT AMT, ESI ON SITE, VACCING DRAIN"
Remarks:	"spill of 100-200 gal of disel occ at the main building - spill to

NEWSDAY, LLC (Continued) **1000378809**

blacktop and a storm drain is also effected - unk cause at this time, still being investigated. Security noticed the oil coming from a vent pipe - clean up contractor fenley & nicol has been paged "

Material:

Site ID:	276623
Operable Unit ID:	831066
Operable Unit:	01
Material ID:	546108
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1600.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9706042
Facility Type:	ER
DER Facility ID:	300411
Site ID:	276629
DEC Region:	1
Spill Date:	1997-08-18
Spill Number/Closed Date:	9706042 / 1997-12-01
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1997-08-18
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-18
Spill Record Last Update:	2009-08-25
Spiller Name:	DAVE KRUEGER
Spiller Company:	NEWSDAY NEWSPAPER
Spiller Address:	235 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY 11747-
Spiller Company:	001
Contact Name:	DAVE KRUEGER
Contact Phone:	(516) 436-1381
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA 20-35 GALS SPILLED ONTO PAVEMENT, NO DRAINAGE BUT PADS

NEWSDAY, LLC (Continued) **1000378809**

DEPLOYED AS PRECAUTION, SPILL OCCURRED WHEN 1 HOSE FAILED DUE TO CONTINUAL CONTACT WITH COMPACTOR BODY. SPILL ONTO PAVEMENT ONLY, 10 BAGS USED AND WILL BE PICKED UP TOMORROW. NEWSDAY THEN WILL PUT WASTE INTO DRUMS FOR PROPER DISPOSAL CLEANUP BY NEWSDAY, DISPOSAL RECVD"

Remarks: "A HYDRAULIC LINE FROM A TRASH COMPACTOR RUPTURED FROM RUBBING AGAINST A SHARP OBJECT - SPILL HAS BEEN CONTAINED WITH SPEEDY DRY"

Material:

Site ID:	276629
Operable Unit ID:	1049277
Operable Unit:	01
Material ID:	331649
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

ICIS:

Enforcement Action ID:	NY-ETP1502
FRS ID:	110000807761
Action Name:	NEWSDAY INC - MAINTENANCE
Facility Name:	NEWSDAY, LLC
Facility Address:	235 PINELAWN ROAD MELVILLE, NY 11747-4250
Enforcement Action Type:	State Administrative Order of Consent
Facility County:	SUFFOLK
Program System Acronym:	NPDES
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	STAOCO
Facility SIC Code:	2711
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.764028
Longitude in Decimal Degrees:	-73.40625
Permit Type Desc:	Individual State Issued Permit (Non-NPDES)
Program System Acronym:	NY0136751
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

US AIRS (AFS):

Envid:	1000378809
Region Code:	02
County Code:	NY103
Programmatic ID:	AIR NY0000001472600157
Facility Registry ID:	110000807761

NEWSDAY, LLC (Continued) **1000378809**

D and B Number: Not reported
Facility Site Name: NEWSDAY
Primary SIC Code: 2711
NAICS Code: 511110
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

NEWSDAY, LLC (Continued) **1000378809**

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-12-19 00:00:00
Activity Status Date: 2016-05-02 12:51:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-24 00:00:00
Activity Status Date: 2016-05-02 12:51:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-09-29 00:00:00
Activity Status Date: 2016-10-09 08:02:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-09-29 00:00:00
Activity Status Date: 2016-10-09 08:02:07
Activity Group: Compliance Monitoring

NEWSDAY, LLC (Continued) **1000378809**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-09-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NEWSDAY, LLC (Continued) **1000378809**

Activity Date: 2007-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-01-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761

NEWSDAY, LLC (Continued) **1000378809**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-02-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-04-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NEWSDAY, LLC (Continued) **1000378809**

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110000807761

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of

NEWSDAY, LLC (Continued) **1000378809**

Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000378809
Registry ID:	110000807761
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000807761

NY MANIFEST:

Country:	USA
EPA ID:	NYD052782497
Facility Status:	Not reported
Location Address 1:	235 PINELAWN ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD052782497

NEWSDAY, LLC (Continued) **1000378809**

Mailing Name:	NEWSDAY INC
Mailing Contact:	ATTN DAVE KRUEGER
Mailing Address 1:	235 PINELAWN RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	4250
Mailing Country:	USA
Mailing Phone:	5164542025

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	01/05/2015
Trans1 Recv Date:	01/05/2015
Trans2 Recv Date:	01/15/2015
TSD Site Recv Date:	01/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	004460656SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/16/2015
Trans1 Recv Date:	03/16/2015
Trans2 Recv Date:	03/27/2015
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	004460657SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD986607380

NEWSDAY, LLC (Continued) **1000378809**

Generator Ship Date:	01/12/2015
Trans1 Recv Date:	01/12/2015
Trans2 Recv Date:	01/21/2015
TSD Site Recv Date:	01/22/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	004692639SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD986607380
Generator Ship Date:	12/11/2015
Trans1 Recv Date:	12/11/2015
Trans2 Recv Date:	12/18/2015
TSD Site Recv Date:	12/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	005008334SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	U151
Waste Code 1_2:	D009
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	NYC7461652
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	11/24/2004
Trans1 Recv Date:	11/24/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00015
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Document ID:	NYC7462980
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NY79919JN
Trans2 State ID:	Not reported
Generator Ship Date:	11/05/2004
Trans1 Recv Date:	11/05/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00015
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels

NEWSDAY, LLC (Continued) **1000378809**

Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Document ID:	NYC7561348
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NY74914JN
Trans2 State ID:	Not reported
Generator Ship Date:	12/08/2004
Trans1 Recv Date:	12/08/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00015
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Document ID:	NJA5061553
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	06993
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2004
Trans1 Recv Date:	02/17/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/17/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Generator EPA ID:	NYD052782497
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NYC7572014
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NY74914JN
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2004
Trans1 Recv Date:	12/20/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/20/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00015
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Document ID:	NJD4126778
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	S6993
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2004
Trans1 Recv Date:	09/14/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00770
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	014
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

NEWSDAY, LLC (Continued) **1000378809**

Click this hyperlink while viewing on your computer to access
1124 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYD052782497
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	D
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA4126782
EPA ID:	NYD052782497
Date Shipped:	01/24/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/24/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/24/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03150521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5229182
EPA ID:	NYD052782497
Date Shipped:	03/21/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/21/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/21/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05090522
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5249293
EPA ID:	NYD052782497
Date Shipped:	05/02/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/02/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/02/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140525
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5318585
EPA ID:	NYD052782497
Date Shipped:	06/12/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/12/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/12/2006

NEWSDAY, LLC (Continued) **1000378809**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08010625
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5314811
EPA ID:	NYD052782497
Date Shipped:	07/24/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/24/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/24/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Manifest Number:	NJA4129799
EPA ID:	NYD052782497
Date Shipped:	04/27/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/27/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/27/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05180421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126795
EPA ID:	NYD052782497
Date Shipped:	05/11/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/11/2004
Date Trans2 Transported Waste:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/11/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05210422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5318254
EPA ID:	NYD052782497
Date Shipped:	04/13/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/13/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06160625
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126777
EPA ID:	NYD052782497
Date Shipped:	08/31/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/31/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10070422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126778
EPA ID:	NYD052782497
Date Shipped:	09/14/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/14/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/14/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10190422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126780
EPA ID:	NYD052782497
Date Shipped:	10/12/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/12/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/12/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12230421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126787
EPA ID:	NYD052782497
Date Shipped:	06/22/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/22/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/22/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	07130421
Was Load Rejected:	No

NEWSDAY, LLC (Continued) **1000378809**

Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126796
EPA ID:	NYD052782497
Date Shipped:	05/21/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/21/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/21/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06170421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126788
EPA ID:	NYD052782497
Date Shipped:	07/06/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Date Trans1 Transported Waste:	07/06/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/06/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08030421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126784
EPA ID:	NYD052782497
Date Shipped:	07/14/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/14/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/14/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08230425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4129798
EPA ID:	NYD052782497
Date Shipped:	04/13/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/13/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05170421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126775
EPA ID:	NYD052782497
Date Shipped:	10/26/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768

NEWSDAY, LLC (Continued) **1000378809**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/26/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/26/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12060425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126776
EPA ID:	NYD052782497
Date Shipped:	12/07/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01190521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126786
EPA ID:	NYD052782497
Date Shipped:	08/17/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/17/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/17/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

NEWSDAY, LLC (Continued) **1000378809**

Data Entry Number:	09160421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126774
EPA ID:	NYD052782497
Date Shipped:	11/23/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	NJD980772768
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/23/2004
Date Trans2 Transported Waste:	11/23/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/23/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01100525
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

SPDES:

Permit Number:	NY0136751
State-Region:	01
Expiration Date:	11/30/2021
Current Major Minor Status:	Minor
Primary Facility SIC Code:	2711
State Water Body Name:	GW
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	0.045
Total App Design Flow(MGD):	Not reported

NEWSDAY, LLC (Continued) **1000378809**

UDF1:	DMR
Lat/Long:	40.764028 / -73.40625
DMR Cognizant Official:	JOSEPH MARINO, MGR FAC ENG
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	NEWSDAY, LLC
Non-Gov Permit Supplemental Location:	235 PINELAWN ROAD
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	NEWSDAY, LLC
Non-Gov Permit Supplemental Location:	235 PINELAWN ROAD
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	235 PINELAWN ROAD
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC

NEWSDAY, LLC (Continued) **1000378809**

Non-Gov Facility Supplemental Location: 235 PINELAWN ROAD
Non-Gov Facility City: MELVILLE
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11747-4250
State Water Body: 02030202070

UDF2: 001702
UDF3: GA
FIPS County Code: NY103

Non-Gov Permit Affiliation Type Desc: Permittee
Non-Gov Permit Org Formal Name: NEWSDAY, LLC
Non-Gov Permit Street Address: 235 PINELAWN ROAD
Non-Gov Permit Supplemental Location: Not reported
Non-Gov Permit City: MELVILLE
Non-Gov Permit State Code: NY
Non-Gov Permit Zip Code: 11747-4250
Non-Gov Facility Affiliation Type Desc: Owner
Non-Gov Facility Org Formal Name: NEWSDAY, LLC
Non-Gov Facility Street Address: NEWSDAY, LLC
Non-Gov Facility Supplemental Location: 235 PINELAWN ROAD
Non-Gov Facility City: MELVILLE
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11747-4250
State Water Body: 02030202070

A5 **NEWSDAY INC** **NY UST** **U004219660**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 5 of 8 in cluster A

Actual: 105 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 07934
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 07934
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: NEWSDAY INC ATTN:J MARINO
Storage Owner Address: 235 PINELAWN RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 07934
Facility Reference #: 02037
Official Use: Removed Tank. 86
Township: HUNTINGTON
Tax Map No: 0400 270.00 002 001.000

NEWSDAY INC (Continued) **U004219660**

Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	23068
Installed:	78
Capacity:	0000025000
Substance:	DIESEL
Date Removed:	010186
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000025000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010186
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013
Tank ID:	2
Tank Key:	23069
Installed:	78
Capacity:	0000025000
Substance:	DIESEL
Date Removed:	010186
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000025000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

NEWSDAY INC (Continued) **U004219660**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010186
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	23070
Installed:	78
Capacity:	0000025000
Substance:	DIESEL
Date Removed:	010186
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000025000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010186
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	4
Tank Key:	23071
Installed:	78
Capacity:	0000012000
Substance:	GASOLINE
Date Removed:	010186
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000012000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

NEWSDAY INC (Continued) **U004219660**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	010186
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	5
Tank Key:	23072
Installed:	78
Capacity:	0000002000
Substance:	SPILL CONTAINMENT
Date Removed:	062888
Construction:	STEEL
Dispenser:	SUBMERSIBLE
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	062888
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	6
Tank Key:	23073
Installed:	78
Capacity:	0000025000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION

NEWSDAY INC (Continued) **U004219660**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000025000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	7
Tank Key:	23074
Installed:	78
Capacity:	0000025000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000025000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	8

NEWSDAY INC (Continued) **U004219660**

Tank Key:	23075
Installed:	78
Capacity:	0000004000
Substance:	INDUSTRIAL WASTE
Date Removed:	010187
Construction:	FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	010187
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	14
Tank Key:	23081
Installed:	85
Capacity:	0000020000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000020000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

NEWSDAY INC (Continued) **U004219660**

Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	15
Tank Key:	23082
Installed:	85
Capacity:	0000020000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000020000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	16
Tank Key:	23083
Installed:	85
Capacity:	0000020000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000020000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

NEWSDAY INC (Continued) **U004219660**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	18
Tank Key:	23085
Installed:	87
Capacity:	0000002500
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	87
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	19
Tank Key:	23086
Installed:	87
Capacity:	0000004000
Substance:	INDUSTRIAL WASTE
Date Removed:	Not reported
Construction:	STEEL / STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000

NEWSDAY INC (Continued) **U004219660**

Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	87
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	20
Tank Key:	23087
Installed:	Not reported
Capacity:	0000010000
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000010000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

A6 **NEWSDAY LLC** **NY AST** **A100385242**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 6 of 8 in cluster A

Actual:
105 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	02037
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	12/31/2016
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	02037
Billing Contact:	CABLEVISION
Billing Address:	1111 STEWART AVE
Billing Address:	BETHPAGE
Billing State:	NY
Billing Zip:	11714
Storage Owner:	CABLEVISION
Storage Owner Address:	1111 STEWART AVE
Storage Owner City:	BETHPAGE
Storage Owner State:	NY
Storage Owner Zip:	11714

Tank Info:

Facility ID:	02037
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	17
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	100 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported

NEWSDAY LLC (Continued) **A100385242**

Fill:	Not reported
Date Removed:	Not reported

Tank ID:	38
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	125 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	PAINTED / COATED
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	40
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	25 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	VISUAL MONITORING

NEWSDAY LLC (Continued) **A100385242**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	55
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	REMOVED
Total Capacity:	1250 gallons
Date Permitted:	Not reported
Date Closed:	02/23/2006
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	56
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	REMOVED
Total Capacity:	1250 gallons
Date Permitted:	Not reported
Date Closed:	02/23/2006
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

NEWSDAY LLC (Continued) **A100385242**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	70
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	101 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	Not reported
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	PLAIN STEEL/IRON
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	71
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	81 gallons
Date Permitted:	Not reported
Date Closed:	06/19/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	Not reported
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE

NEWSDAY LLC (Continued) **A100385242**

Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	86
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1100 gallons
Date Permitted:	02/27/2006
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	87
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1100 gallons
Date Permitted:	02/27/2006
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE

NEWSDAY LLC (Continued) **A100385242**

Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	9
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	EXEMPT
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	COPPER
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	EXEMPT
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	97
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	15000 gallons
Date Permitted:	12/06/2013
Date Closed:	Not reported
Internal Protection:	EPOXY LINER
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm - Fill Limiter - Sight/Level Gauge
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	ABOVEGROUND OUT & INDOORS

NEWSDAY LLC (Continued) **A100385242**

Pipe Type:	BLACK STEEL
Pipe External Protection:	PAINT/COATED
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE ONLY
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

A7 **NEWSDAY LLC** **NY UST** **U003537273**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 7 of 8 in cluster A

Actual:
105 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	02037
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	12/31/2016
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	02037
Billing Contact:	CABLEVISION
Billing Address:	1111 STEWART AVE
Billing Address:	BETHPAGE
Billing State:	NY
Billing Zip:	11714
Storage Owner:	CABLEVISION
Storage Owner Address:	1111 STEWART AVE
Storage Owner City:	BETHPAGE
Storage Owner State:	NY
Storage Owner Zip:	11714

Tank Info:

Facility ID:	02037
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Tank ID:	6
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	ABANDONED IN PLACE
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	03/20/2014
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	TIGHTNESS TESTING
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	ABANDONED IN PLACE
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	03/20/2014
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	TIGHTNESS TESTING
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING

NEWSDAY LLC (Continued) **U003537273**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	14
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons
Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	15
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons
Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	16
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons
Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	18
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE

NEWSDAY LLC (Continued) **U003537273**

Total Capacity:	2500 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	93
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	94
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons

NEWSDAY LLC (Continued) **U003537273**

Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	95
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Description of drop records: Not reported

A8 Target Property **NALCO CHEMICAL**
235 PINELAWN RD - BOILER HOUSE
MELVILLE, NY 11747

RCRA NonGen / NLR **1001113472**
FINDS **NYR000024620**
ECHO
NY MANIFEST

Site 8 of 8 in cluster A

Actual: 105 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NALCO CHEMICAL
Facility address:	235 PINELAWN RD - BOILER HOUSE MELVILLE, NY 11747
EPA ID:	NYR000024620
Mailing address:	NALCO CENTER NAPERVILLE, NY 605631198
Contact:	Not reported
Contact address:	NALCO CENTER NAPERVILLE, NY 605631198
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 843-2038
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 843-2038
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

NALCO CHEMICAL (Continued) **1001113472**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NALCO CHEMICAL
Classification: Not a generator, verified

Date form received by agency: 07/15/1996
Site name: NALCO CHEMICAL
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 05/29/1996
Site name: NALCO CHEMICAL
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004525443

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001113472
Registry ID: 110004525443
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004525443

NY MANIFEST:
Country: USA
EPA ID: NYR000024620
Facility Status: Not reported
Location Address 1: 235 PINELAWN ROAD BOILER
Code: BP

NALCO CHEMICAL (Continued) **1001113472**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000024620
Mailing Name:	NALCO CHEMICAL
Mailing Contact:	EVERETTE GAUTHIER
Mailing Address 1:	1 NALCO CENTER
Mailing Address 2:	Not reported
Mailing City:	NAPERVILLE
Mailing State:	IL
Mailing Zip:	60563
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7083051134

NY MANIFEST:

Document ID:	NJA2188993
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	06/05/1996
Trans1 Recv Date:	06/12/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/12/1996
Part A Recv Date:	/ /
Part B Recv Date:	06/21/1996
Generator EPA ID:	NYR000024620
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055

NALCO CHEMICAL (Continued) **1001113472**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

B9 **IMPERIAL NEWS CO** **NY Spills** **1000552853**
ESE **255 PINELAWN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.003 mi.
15 ft. **Site 1 of 5 in cluster B**

Relative:
Lower

Actual:
103 ft.

SPILLS:

Facility ID:	0906309
Facility Type:	ER
DER Facility ID:	300660
Site ID:	418639
DEC Region:	1
Spill Date:	2009-08-31
Spill Number/Closed Date:	0906309 / 2010-03-22
Spill Cause:	Vandalism
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2009-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2009-08-31
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Company:	Not reported
Contact Name:	PAT COSTANZO
Contact Phone:	(631) 454-2337
DEC Memo:	""
Remarks:	"Caller states that overnight, the meter on the diesel fuel pump for fueling vehicles was broken. (There is a labor stike in progrees). A driver went to fuel a vehicle, and diesel sprayed out from around broken meter. Spill was to asphalt, and a small amount may have entered a catch basin on the property. The spill to the asphalt was cleaned up. -KY"

Material:

Site ID:	418639
Operable Unit ID:	1174804

IMPERIAL NEWS CO (Continued) **1000552853**

Operable Unit:	01
Material ID:	2167188
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9308159
Facility Type:	ER
DER Facility ID:	456664
Site ID:	202110
DEC Region:	1
Spill Date:	1993-10-05
Spill Number/Closed Date:	9308159 / 2004-06-02
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1993-10-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-10-06
Spill Record Last Update:	2014-11-10
Spiller Name:	Not reported
Spiller Company:	ABAND BLDG
Spiller Address:	255 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA SOIL EXCAVATED"
Remarks:	"FIRST BLDG SOUTH OF NEWSDAY BLDG, SCDH PETE SCHRAMEL ON SITE, LONG TERM LEAKAGE, 3-4 HOLES ON BOTTOM OF TANK, 1/2 DIAMETER, NEEDS DEC TO RESPOND"

Material:

Site ID:	202110
Operable Unit ID:	986833

IMPERIAL NEWS CO (Continued) **1000552853**

Operable Unit:	01
Material ID:	394398
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	8603300
Facility Type:	ER
DER Facility ID:	300660
Site ID:	202109
DEC Region:	1
Spill Date:	1986-08-18
Spill Number/Closed Date:	8603300 / 1986-10-01
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS:	5226
Investigator:	CXONEILL
Referred To:	Not reported
Reported to Dept:	1986-08-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	1986-10-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1986-08-25
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	IMPERIAL NEWS CO
Spiller Address:	255 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'NEILL FD / / : DEC INVEST- 3OPTION LETTER TO BE SENT?TANKS PASSED RETEST 9/9/86 AFTER BREAKING SYPHON. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	"2 12K SIPHONED TOGETHER. -.566GPH FOR SYSTEM ONE FILL LINE HAS POSSIBLE AIR POCKET."

Material:

IMPERIAL NEWS CO (Continued) **1000552853**

Site ID:	202109
Operable Unit ID:	900588
Operable Unit:	01
Material ID:	476129
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B10 **CLARE ROSE** **NY Spills** **S109208314**
ESE **255 PINELAWN RD/MARCUS** **N/A**
< 1/8 **MELVILLE, NY**
0.003 mi.
15 ft. **Site 2 of 5 in cluster B**

Relative:
Lower

Actual:
103 ft.

SPILLS:

Facility ID:	0890480
Facility Type:	ER
DER Facility ID:	348940
Site ID:	399610
DEC Region:	1
Spill Date:	2008-06-12
Spill Number/Closed Date:	0890480 / 2009-04-30
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2008-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-06-12
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	CLARE ROSE
Spiller Address:	255 PINELAWN RD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported

CLARE ROSE (Continued) **S109208314**

DEC Memo: "***THIS SITE IS JUST NORTH OF THE HUNTINGTON/BABYLON TOWN LINE. WHEN PINELAWN CROSSES INTO BABYLON, IT BECOMES WELLWOOD AVE.*** DEC INFORMED HIM WE MUST INSPECT THE TANK AND EXCAVATION, THAT WE DID NOT HAVE AN INSPECTOR AVAILABLE TODAY, AND THAT HE SHOULD CALL THIS OFFICE TOMORROW TO DISCUSS THE SCHEDULING OF THE INSPECTION. DEC FURTHER INFORMED HIM THAT HE COULD HAVE THE TANK EMPTIED, REMOVE THE TANK, AND LEAVE THE TANK ON SITE AND THE EXCAVATION OPEN PENDING INSPECTION IF HE FELT IT WAS SAFE TO DO SO. 6/18/08 TJD 1400-1500 Site inspection. Excavation contractor (Tully Drainage) onsite completing installation of sanitary system (cesspool rings). Upon initial notification, DEC Dave Raymond required contractor to schedule inspection with DEC prior to closure of tank grave. Contractor did not follow DEC directive and installed sanitary system in area of tank grave. Site supervisor for Tully (Mike Lucia) refused to provide specific information regarding former tank location stating that no spill occurred and DEC was wasting its time. DeMeo contacted Claire Rose representative (Patrick Costanzo) who provided contact information to Nelson & Pope surveyor (Tom Lembo) who was onsite for removal. Nelson & Pope was contacted and provided additional information required to access reported spill event including: SCDOH inspector visited site following tank removal, ESI was contractor who pumped tank & site plan was updated to include former tank location. A copy of updated site plan was requested. DEC contacted SCDOH Bob Seafarth stated his inspector (Zachary Baldwin) was onsite for removal and he would forward a copy of tank removal report. 6/19/08 TJD T/C with Joe Parisi @ ESI. Joe states he was hired to pump liquid contents from tank upon its discovery. He further states tank was filled to capacity with water following pump out he remained onsite for tank removal. Tank reported to be in good condition with no reported holes. 4/30/09 TJD File review. Updated survey depicting tank location received from Nelson & Pope. Tank removal checklist received from SCDOH no contamination noted. Based upon review of available information no further action is required. TOM LEMBO NELSON & POPE 631-427-5665 C 516-524-3535 JANET 854-2513 BOB 854-2518 PATRICK CONSTANZO SAFETY 631-454-2337 X155 MIKE LUCION ZACHARY BALDWIN "

Remarks: "THEY WERE EXCAVATING FOR A NEW CESSPOOL AND ENCOUNTERED A PREVIOUSLY ABANDONED TANK. HE BELIEVES IT MAY BE 1000 GAL IN SIZE. THE TANK CONTAINED WATER AND HAD A GASOLINE ODOR, AND SOME OF THE WATER INSIDE THE TANK SPILLED INTO THE EXCAVATION. HE HAD INITIALLY CALLED JOE PARISI OF ESI, WHO ADVISED HIM TO CALL DEC."

Material:

Site ID:	399610
Operable Unit ID:	1156474
Operable Unit:	01
Material ID:	2147404
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CLARE ROSE (Continued) **S109208314**

Tank Test:

B11
ESE
< 1/8
0.003 mi.
15 ft.

Relative:
Lower

Actual:
103 ft.

CLARE ROSE **NY Spills** **S103566566**
255 PINE LAWN ROAD **N/A**
MELVILLE, NY

Site 3 of 5 in cluster B

SPILLS:

Facility ID:	9402856
Facility Type:	ER
DER Facility ID:	265498
Site ID:	329995
DEC Region:	1
Spill Date:	1994-05-26
Spill Number/Closed Date:	9402856 / 1994-11-09
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	GIBBONS
Referred To:	Not reported
Reported to Dept:	1994-05-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	1994-11-09
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-31
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	CLARE ROSE
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"DISPOSAL RECPTS REC'VD, NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"10K #2 F/O TANK, TANK REMOVAL, 10-20 YDS CLEANED UP, REMOVED 2-10K, 8K TURNED OUT TO BE 10K ALSO, 1-3K, NO HOLES, TANKS WERE OK, SPILLAGE CAME FROM TOP OF TANK,SOIL CLEANED OUT & STOCKPILED ON SITE"

Material:

Site ID:	329995
Operable Unit ID:	999881
Operable Unit:	01
Material ID:	383026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

CLARE ROSE (Continued) **S103566566**

Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

B12 **IMPERIAL NEWS** **RCRA NonGen / NLR** **1004757764**
ESE **255 PINELAWN RD** **FINDS** **NYD986952588**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.003 mi. **NY MANIFEST**
15 ft. **Site 4 of 5 in cluster B**

Relative:
Lower

Actual:
103 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: IMPERIAL NEWS
Facility address: 255 PINELAWN RD
MELVILLE, NY 11747
EPA ID: NYD986952588
Mailing address: SMITH ST
FARMINGDALE, NY 11735
Contact: OLGA RAY
Contact address: SMITH ST
FARMINGDALE, NY 11735
Contact country: US
Contact telephone: (516) 752-2255
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DALE NEWS CO
Owner/operator address: 303 SMITH ST
FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: (516) 752-2255
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DALE NEWS CO
Owner/operator address: 303 SMITH ST
FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: (516) 752-2255
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

IMPERIAL NEWS (Continued) **1004757764**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: IMPERIAL NEWS
Classification: Not a generator, verified

Date form received by agency: 05/17/1991
Site name: IMPERIAL NEWS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004466809

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1004757764
Registry ID: 110004466809
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004466809

NY MANIFEST:

Country: USA
EPA ID: NYD986952588
Facility Status: Not reported
Location Address 1: 255 PINELAWN ROAD
Code: BP
Location Address 2: Not reported

IMPERIAL NEWS (Continued) **1004757764**

Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986952588
Mailing Name:	IMPERIAL NEWS
Mailing Contact:	IMPERIAL NEWS
Mailing Address 1:	255 PINELAWN ROAD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0007528502

NY MANIFEST:

Document ID:	NJA1400696
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	MK8837
Trans2 State ID:	NJDEPS727
Generator Ship Date:	09/16/1992
Trans1 Recv Date:	09/17/1992
Trans2 Recv Date:	09/17/1992
TSD Site Recv Date:	09/17/1992
Part A Recv Date:	/ /
Part B Recv Date:	10/01/1992
Generator EPA ID:	NYD986952588
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	NJD986609949
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)

IMPERIAL NEWS (Continued) **1004757764**

Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

B13 **CLARE ROSE** **NY UST U003842808**
ESE **255 CNTY RD 3 PINELAWN RD** **NY AST N/A**
< 1/8 **MELVILLE, NY 11747**
0.003 mi.
15 ft. **Site 5 of 5 in cluster B**

Relative:
Lower

Actual:
103 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 07581
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 07581
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: CLARE ROSE
Storage Owner Address: 255 PINELAWN RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 07581
Facility Reference #: 01373
Official Use: Removed Tank. 94
Township: HUNTINGTON
Tax Map No: 0400 270.00 001 014.000
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 21839
Installed: 72
Capacity: 0000010000
Substance: #2 FUEL OIL
Date Removed: 052694
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 0000010000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported

CLARE ROSE (Continued) **U003842808**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	052694
Year Installed:	72
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	21840
Installed:	79
Capacity:	0000010000
Substance:	#2 FUEL OIL
Date Removed:	052694
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000010000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	052694
Year Installed:	79
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	21841
Installed:	78
Capacity:	0000003000
Substance:	#2 FUEL OIL
Date Removed:	052694
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED

CLARE ROSE (Continued) **U003842808**

Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	052694
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	4
Tank Key:	21842
Installed:	78
Capacity:	0000000500
Substance:	WASTE OIL
Date Removed:	050791
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	050791
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	5
Tank Key:	21843

CLARE ROSE (Continued) **U003842808**

Installed:	79
Capacity:	0000012000
Substance:	DIESEL
Date Removed:	050691
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000012000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	050691
Year Installed:	79
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	6
Tank Key:	21844
Installed:	79
Capacity:	0000002000
Substance:	GASOLINE
Date Removed:	050691
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY

CLARE ROSE (Continued) **U003842808**

Date Removed:	050691
Year Installed:	79
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	7
Tank Key:	21845
Installed:	78
Capacity:	0000012000
Substance:	DIESEL
Date Removed:	050691
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000012000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	050691
Year Installed:	78
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	8
Tank Key:	21846
Installed:	79
Capacity:	0000008000
Substance:	GASOLINE
Date Removed:	050691
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

CLARE ROSE (Continued) **U003842808**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	050691
Year Installed:	79
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	9
Tank Key:	21847
Installed:	Not reported
Capacity:	0000000550
Substance:	OIL/WATER SEPARATOR
Date Removed:	100593
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	100593
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	10
Tank Key:	21848
Installed:	Not reported
Capacity:	0000000550
Substance:	OIL/WATER SEPARATOR
Date Removed:	100593
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported

CLARE ROSE (Continued) **U003842808**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	100593
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07581
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07581
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	CLARE ROSE
Storage Owner Address:	255 PINELAWN RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	07581
Facility Reference #:	01373
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	11
Tank Key:	21849
Year Installed:	Not reported
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported

CLARE ROSE (Continued) **U003842808**

Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	12
Tank Key:	48463
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	13
Tank Key:	48464
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE

CLARE ROSE (Continued) **U003842808**

Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	14
Tank Key:	48465
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	15
Tank Key:	48466
Year Installed:	Not reported
Substance:	DIESEL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported

CLARE ROSE (Continued) **U003842808**

Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000651
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

C14 **TRIBUNE COMPANY** **RCRA NonGen / NLR** **1000436935**
WNW **25 DESHON DR** **FINDS** **NYD002052504**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.017 mi. **NY MANIFEST**
88 ft. **Site 1 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BELWIN MILLS
Facility address:	25 DESHON DR MELVILLE, NY 117474207
EPA ID:	NYD002052504
Mailing address:	NW 48TH AVE MIAMI, NY 33014
Contact:	Not reported
Contact address:	NW 48TH AVE MIAMI, NY 33014
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NET REALTY HOLDING TR
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

TRIBUNE COMPANY (Continued) **1000436935**

Owner/operator name: NET REALTY HOLDING TR
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BELWIN MILLS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BELWIN MILLS
Classification: Not a generator, verified

Date form received by agency: 12/22/1986
Site name: BELWIN MILLS
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

TRIBUNE COMPANY (Continued) **1000436935**

MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/16/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004337511

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019617887

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000436935
Registry ID: 110004337511
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004337511

NY MANIFEST:
Country: USA
EPA ID: NYD002052504
Facility Status: Not reported
Location Address 1: 25 DESHON DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

TRIBUNE COMPANY (Continued) **1000436935**

Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD002052504
Mailing Name:	BELWIN MILLS
Mailing Contact:	JOHN KING
Mailing Address 1:	25 DESHON DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162933400

NY MANIFEST:

Document ID:	NYA3027598
Manifest Status:	K
seq:	Not reported
Year:	1987
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/1987
Trans1 Recv Date:	01/06/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/07/1987
Part A Recv Date:	02/19/1987
Part B Recv Date:	01/14/1987
Generator EPA ID:	NYD002052504
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

TRIBUNE COMPANY (Continued) **1000436935**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	092
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00085
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	082

Document ID:	NYA3025045
Manifest Status:	K
seq:	Not reported
Year:	1987
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/1987
Trans1 Recv Date:	01/06/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/07/1987
Part A Recv Date:	02/19/1987
Part B Recv Date:	01/14/1987
Generator EPA ID:	NYD002052504
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported

TRIBUNE COMPANY (Continued) **1000436935**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00013
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	110

C15 **NEWSDAY** **NY UST** **U004219691**
WNW **25 DESHON DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.017 mi.
88 ft. **Site 2 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

NEWSDAY (Continued) **U004219691**

Facility Info:

Site Ref#:	08596
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	NEWSDAY ATTN: JOE MARINO
Storage Owner Address:	25 DESHON DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08596
Facility Reference #:	08656
Official Use:	Removed Tank. 89
Township:	HUNTINGTON
Tax Map No:	0400 267.00 001 012.001
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	2
Tank Key:	24285
Installed:	Not reported
Capacity:	0000015000
Substance:	#2 FUEL OIL
Date Removed:	072689
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000015000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	072689
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013
Tank ID:	3
Tank Key:	24286

NEWSDAY (Continued) **U004219691**

Installed:	Not reported
Capacity:	0000020000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000020000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	4
Tank Key:	24287
Installed:	Not reported
Capacity:	0000020000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000020000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED

NEWSDAY (Continued) **U004219691**

Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	5
Tank Key:	24288
Installed:	91
Capacity:	0000006000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000006000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	91
Description of drop records:	RECORDS AS OF 09/10/2013

C16 **NEWSDAY** **NY AST** **A100385594**
WNW **25 DESHON DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.017 mi.
88 ft. **Site 3 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	08596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	08596
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported

NEWSDAY (Continued) **A100385594**

Storage Owner: NEWSDAY ATTN: JOE MARINO
Storage Owner Address: 25 DESHON DR
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 08596
Facility Reference #: 08656
Township: HUNTINGTON
Tax Map No: 0400
Region: SUFFOLK

Tank ID: 1
Tank Key: 24284
Year Installed: 83
Substance: INDUSTRIAL WASTE
Construction: STEEL
Dispenser: SUCTION
Official Use: Removed Tank. 92
Permit to Operate: Not reported
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 0000000550
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: OTHER
Date Removed: 010192

Tank ID: 10
Tank Key: 42357
Year Installed: Not reported
Substance: BOILER CHEM
Construction: Not reported
Dispenser: SUCTION
Official Use: Permitted Tank. Permit Runs Out. 10
Permit to Operate: 042605
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 0000000080
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported

NEWSDAY (Continued) **A100385594**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	11
Tank Key:	42358
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	12
Tank Key:	42359
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

NEWSDAY (Continued) **A100385594**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	13
Tank Key:	42360
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	6
Tank Key:	42353
Year Installed:	1991
Substance:	#2 FUEL OIL
Construction:	STEEL / STEEL
Dispenser:	SUCTION
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000100
Date Permitted:	Not reported
Date Closed:	Not reported

NEWSDAY (Continued) **A100385594**

Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	7
Tank Key:	42354
Year Installed:	Not reported
Substance:	BOILER ADDITIVE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	8
Tank Key:	42355
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported

NEWSDAY (Continued) **A100385594**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	9
Tank Key:	42356
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	042605
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000080
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

C17 **TRIBUNE LLC** **NY AST** **A100264938**
WNW **25 DESHON DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.017 mi.
88 ft. **Site 4 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	08656
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported

TRIBUNE LLC (Continued) **A100264938**

Owner/Storage Information: AVAILABLE

Facility Info:
Site Ref#: 08656
Billing Contact: TRIBUNE LLC
Billing Address: 25 DESHON DR
Billing Address: MELVILLE
Billing State: NY
Billing Zip: 11747
Storage Owner: TRIBUNE LLC
Storage Owner Address: 25 DESHON DR
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 08656
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 14
Tank Key: Not reported
Year Installed: Not reported
Substance: MOTOR OIL
Construction: REFER TO PAPER FILE
Dispenser: GRAVITY
Official Use: Not reported
Permit to Operate: Not reported
Tank Location: ABOVE - IN
Tabk Status: REMOVED
Total Capacity: 60 gallons
Date Permitted: Not reported
Date Closed: 11/08/2013
Internal Protection: NONE
Secondary Containment: NONE
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

Tank ID: 15
Tank Key: Not reported
Year Installed: Not reported
Substance: MOTOR OIL
Construction: REFER TO PAPER FILE
Dispenser: GRAVITY

TRIBUNE LLC (Continued) **A100264938**

Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	60 gallons
Date Permitted:	Not reported
Date Closed:	11/08/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	100 gallons
Date Permitted:	Not reported
Date Closed:	11/08/2013
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

C18 **J.M ALBRIZZIO** **NY Spills** **S102139203**
WNW **25 DESCHON DRIVE** **N/A**
< 1/8 **MELVILLE, NY**
0.017 mi.
88 ft. **Site 5 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

SPILLS:

Facility ID:	9309731
Facility Type:	ER
DER Facility ID:	115665
Site ID:	134618
DEC Region:	1
Spill Date:	1993-11-11
Spill Number/Closed Date:	9309731 / 1993-12-24
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	KAKISPER
Referred To:	Not reported
Reported to Dept:	1993-11-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	1993-12-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-12
Spill Record Last Update:	2013-01-15
Spiller Name:	Not reported
Spiller Company:	J.M ALBRIZZIO
Spiller Address:	100 HARTWELL ST
Spiller City,St,Zip:	WEST BOUSTON, MA
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KISPERT 12/24/93: NO RESPONSE NEEDED. "
Remarks:	"DRIVER HIT CURB, SPILL ON ROAD & PARKING LOT, WORKING ON LEAK, CLEANING UP WITH SPEEDI DRI"

Material:

Site ID:	134618
Operable Unit ID:	991250
Operable Unit:	01
Material ID:	392383
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

J.M ALBRIZZIO (Continued) **S102139203**

Tank Test:

C19
WNW
< 1/8
0.017 mi.
88 ft.

Relative:
Higher

Actual:
108 ft.

TRIBUNE LLC **NY UST** **U003537405**
25 DESHON DR **N/A**
MELVILLE, NY 11747

Site 6 of 7 in cluster C

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08656
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	08656
Billing Contact:	TRIBUNE LLC
Billing Address:	25 DESHON DR
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	TRIBUNE LLC
Storage Owner Address:	25 DESHON DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08656
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	15000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	15000 gallons
Date Permitted:	Not reported
Date Closed:	07/26/1989
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported

TRIBUNE LLC (Continued) **U003537405**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	6000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	6000 gallons
Date Permitted:	05/14/1991
Date Closed:	11/08/2013
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

C20 **NEWSDAY** **NY Spills** **S107408321**
WNW **25 DESHON DRIVE** **N/A**
< 1/8 **MELVILLE, NY**
0.017 mi.
88 ft. **Site 7 of 7 in cluster C**

Relative:
Higher

Actual:
108 ft.

SPILLS:

Facility ID:	0550849
Facility Type:	ER
DER Facility ID:	298602
Site ID:	351331
DEC Region:	1

NEWSDAY (Continued) **S107408321**

Spill Date:	2005-08-19
Spill Number/Closed Date:	0550849 / 2005-09-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2005-08-19
CID:	Not reported
Water Affected:	NO
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-19
Spill Record Last Update:	2008-09-05
Spiller Name:	Not reported
Spiller Company:	NEWSDAY
Spiller Address:	25 DESHON RD
Spiller City,St,Zip:	MELLVILLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	(631)369-4900 218
DEC Memo:	"#2 oil spilled in the boiler room CLEANUP COMPLETED BY MEG 8/24 16:15 SHANAHAN CALLED, SPILLED IN BOILER ROOM, PRODUCT ENTERED DRAIN LEADING TO SEPTIC SYSTEM, CLEANED FLOOR, FLUSHED DRAIN AND SKIMMED PRODUCT OUT OF POOL, SUGGESTED HE SEND REPORT TO REGIONAL SPILL ENGINEER (DR)"
Remarks:	""

Material:

Site ID:	351331
Operable Unit ID:	1108851
Operable Unit:	01
Material ID:	2098823
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	50.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

D21 **EASTERN ATHLETIC CLUB** **NY Spills** **S110139171**
NNE **100 RULAND ROAD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.032 mi.
168 ft. **Site 1 of 5 in cluster D**

Relative:
Lower

Actual:
99 ft.

SPILLS:

Facility ID:	0910535
Facility Type:	ER
DER Facility ID:	372191
Site ID:	423296
DEC Region:	1
Spill Date:	2009-12-26
Spill Number/Closed Date:	0910535 / 2009-12-28
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2009-12-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-26
Spill Record Last Update:	2010-01-28
Spiller Name:	GARY ZANAZZI
Spiller Company:	EASTERN ATHLETIC CLUB
Spiller Address:	100 RULAND RD
Spiller City,St,Zip:	MELVILLE, NY 11747
Spiller Company:	999
Contact Name:	GARY ZANAZZI
Contact Phone:	(631) 475-0270
DEC Memo:	"12/26/09 @ 3:00 PM WG spoke to John Durbin. Per John, Miller Environmental was retained the same night by the RP (Eastern Athletic Club) to perform cleanup at the site. -Cleanup has been completed. No add'l action required. (WG)"
Remarks:	"unsure of what caused leak - possible plow hit fill pipe - cleanup pending - contractor enroute."

Material:

Site ID:	423296
Operable Unit ID:	1179109
Operable Unit:	01
Material ID:	2172679
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

EASTERN ATHLETIC CLUB (Continued) **S110139171**

Oxygenate: Not reported

Tank Test:

D22
NNE
< 1/8
0.032 mi.
168 ft.

Relative:
Lower

Actual:
99 ft.

EASTERN ATHLETIC **NY UST** **U004067323**
100 RULAND RD **N/A**
MELVILLE, NY 11747

Site 2 of 5 in cluster D

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	17467
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	17467
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	HALF HOLLOW HILLS RACQUET CLUB
Storage Owner Address:	100 RULAND RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	17467
Facility Reference #:	17726
Official Use:	Not in Compliance (Date - 81)
Township:	HUNTINGTON
Tax Map No:	0400 270.00 001 008.003
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	48205
Installed:	1984
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported

EASTERN ATHLETIC (Continued) **U004067323**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	1984
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	48206
Installed:	1984
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	1984
Description of drop records:	RECORDS AS OF 09/10/2013

D23 **COSTCO** **RCRA NonGen / NLR** **1004761913**
NNE **625 RULAND RD** **NYR000091660**
< 1/8 **MELVILLE, NY 11747**
0.048 mi.
252 ft. **Site 3 of 5 in cluster D**

Relative:
Lower

Actual:
98 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	COSTCO
Facility address:	625 RULAND RD MELVILLE, NY 11747
EPA ID:	NYR000091660
Mailing address:	RULAND RD MELVILLE, NY 11747
Contact:	ANTHONY GIULIANI
Contact address:	RULAND RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(516) 872-2000
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	COSTCO WHOLESALE
Owner/operator address:	999 LAKE DR ISSAQUAH, WA 98027
Owner/operator country:	US
Owner/operator telephone:	(425) 313-8100
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	COSTCO WHOLESALE
Owner/operator address:	999 LAKE DR ISSAQUAH, WA 98027
Owner/operator country:	US
Owner/operator telephone:	(425) 313-8100
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

COSTCO (Continued) **1004761913**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: COSTCO
Classification: Not a generator, verified

Date form received by agency: 11/22/2000
Site name: COSTCO
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

E24 **BUSINESS** **NY Spills** **S113818829**
SE **255 PINELAWN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.050 mi.
266 ft. **Site 1 of 3 in cluster E**

Relative:
Lower

Actual:
103 ft.

SPILLS:
Facility ID: 1303748
Facility Type: ER
DER Facility ID: 300660
Site ID: 484245
DEC Region: 1
Spill Date: 2013-07-08
Spill Number/Closed Date: 1303748 / 2013-12-16
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5226
Investigator: Unassigned
Referred To: Not reported
Reported to Dept: 2013-07-08
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-07-08
Spill Record Last Update: 2016-10-12
Spiller Name: JOSEPH BARBERA
Spiller Company: NATIONAL GRID/LIPA
Spiller Address: Not reported
Spiller City,St,Zip: NY

BUSINESS (Continued) **S113818829**

Spiller Company:	999
Contact Name:	JOSEPH BARBERA
Contact Phone:	(516) 790-5726
DEC Memo:	"07/08/2013-Per National Grid Incident Description: LIPA pad mount transformer released approximately 3 gallons of transformer oil onto cement bottom and surrounding soil. Contractor WRS"
Remarks:	"clean up will commence in 2 hours"

Material:

Site ID:	484245
Operable Unit ID:	1233929
Operable Unit:	01
Material ID:	2232875
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

E25 **CLARE ROSE INC** **NY UST** **U004199756**
SE **255 PINELAWN RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.050 mi.
266 ft. **Site 2 of 3 in cluster E**

Relative:
Lower

Actual:
103 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	01373
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	10/31/2019
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	01373
Billing Contact:	CLARE ROSE INC
Billing Address:	255 PINELAWN RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CLARE ROSE INC
Storage Owner Address:	255 PINELAWN RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	01373
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported

CLARE ROSE INC (Continued) **U004199756**

Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/26/1994
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/26/1994
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported

CLARE ROSE INC (Continued) **U004199756**

Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/26/1994
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	500 gallons
Substance:	WASTE OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	500 gallons
Date Permitted:	Not reported
Date Closed:	05/07/1991

CLARE ROSE INC (Continued) **U004199756**

Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	6
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON

CLARE ROSE INC (Continued) **U004199756**

Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	2000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

CLARE ROSE INC (Continued) **U004199756**

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	8000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	8000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

E26
SE
< 1/8
0.050 mi.
266 ft.

CLARE ROSE INC **NY AST** **A100383150**
255 PINELAWN RD **N/A**
MELVILLE, NY 11747

Site 3 of 3 in cluster E

Relative:
Lower

Actual:
103 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	01373
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	10/31/2019
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	01373
Billing Contact:	CLARE ROSE INC
Billing Address:	255 PINELAWN RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CLARE ROSE INC
Storage Owner Address:	255 PINELAWN RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

CLARE ROSE INC (Continued) **A100383150**

Tank Info:

Facility ID:	01373
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	12
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	13
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	250 gallons
Date Permitted:	06/29/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

CLARE ROSE INC (Continued) **A100383150**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	14
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	250 gallons
Date Permitted:	06/29/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	15
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	OTHER - PLEASE LIST
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	670 gallons
Date Permitted:	06/29/2010
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported

CLARE ROSE INC (Continued) **A100383150**

Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	17
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	OTHER - PLEASE LIST
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	1000 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	18
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUBMERSIBLE
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2000 gallons
Date Permitted:	03/12/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	OTHER
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

CLARE ROSE INC (Continued) **A100383150**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

D27 **UNKNOWN** **NY Spills** **S106015354**
NNE **PINELAWN ROAD/RULAND ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.070 mi.
368 ft. **Site 4 of 5 in cluster D**

Relative:
Lower

Actual:
98 ft.

SPILLS:

Facility ID:	0303103
Facility Type:	ER
DER Facility ID:	96945
Site ID:	110727
DEC Region:	1
Spill Date:	2003-06-24
Spill Number/Closed Date:	0303103 / 2003-07-02
Spill Cause:	Traffic Accident
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	2003-06-24
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-24
Spill Record Last Update:	2009-06-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MELVILLE FIRE DEPT
Contact Phone:	(631) 423-2635
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was YAGER SPOKE WITH TUCKER-SAYS ONE SADDLE TANK IS BEGINNING TO LEAK, OIL ON ROADWAY, HE HAS NO ADDITIONAL INFORMATION TELECON WITH BOB WARREN-MELVILLE FIRE CHIEF, TOW TRUCK IS THERE, BUT IS AFRAID THAT SADDLE TANK WILL LEAK SO IT WON'T BE MOVED UNTIL TANK PUMPED OUT, TOWN OF HUNTINGTON IS ENROUTE AND WILL COORDINATE CLEANUP OF ROADWAY 7/1/03 FILE REASSIGNED 10:50 SPOKE WITH MATT GROSS, CLEANUP CREW ENROUTE, SPILL WAS ABOUT 20-25 GALLONS 15:30 SPOKE WITH MATT,COMPANY

UNKNOWN (Continued) **S106015354**

IS COMPLETING CLEANUP ON THEIR OWN"
Remarks: "Traffic accident at above location. Fire dept on scene and attempting to contain material. Fire dept is requesting callback from regional office in reference to the situation."

Material:
Site ID: 110727
Operable Unit ID: 870842
Operable Unit: 01
Material ID: 503980
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 40.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

D28 **UNKNOWN** **NY Spills** **S102567861**
NNE **PINE LAWN & RULAN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.070 mi.
368 ft. **Site 5 of 5 in cluster D**

Relative:
Lower

Actual:
98 ft.

SPILLS:
Facility ID: 8600899
Facility Type: ER
DER Facility ID: 239693
Site ID: 296193
DEC Region: 1
Spill Date: 1986-05-06
Spill Number/Closed Date: 8600899 / 1987-04-22
Spill Cause: Traffic Accident
Spill Class: Not reported
SWIS: 5226
Investigator: PAREJA
Referred To: Not reported
Reported to Dept: 1986-05-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: 1987-04-22
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1986-06-05
Spill Record Last Update: 2006-02-27
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported

UNKNOWN (Continued) **S102567861**

Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was PAREJA FD / / : F.D. FLUSHED INTO DRAINAGE. 5/6/86 SITE CHECKED.SPILLER REMOVED LESS THAN 1 YD. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"TRACTOR TRAILER"

Material:

Site ID:	296193
Operable Unit ID:	898574
Operable Unit:	01
Material ID:	477466
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

29
WSW
< 1/8
0.071 mi.
374 ft.

PATTERSON BUILDING
25 DESHON DR/MARCUS
HUNTINGTON, NY

NY Spills **S105142322**
N/A

Relative:
Higher

Actual:
105 ft.

SPILLS:

Facility ID:	0106454
Facility Type:	ER
DER Facility ID:	258870
Site ID:	321344
DEC Region:	1
Spill Date:	2001-09-20
Spill Number/Closed Date:	0106454 / 2001-09-27
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	HMCIRRIT
Referred To:	Not reported
Reported to Dept:	2001-09-20
CID:	323
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False

PATTERSON BUILDING (Continued) **S105142322**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-20
Spill Record Last Update:	2009-11-10
Spiller Name:	Not reported
Spiller Company:	INDEPENDENT COURIER
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	STEVEN CLUFF
Contact Phone:	(631) 643-3631
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CIRRITO 9/20 CLUFF CALLED, INDEPENDENT COURIER IS LISTED ON THE TRUCK, BUT THE NAME OF ACTUAL OWNER IS UNKNOWN, ESTIMATE 5-10 GALS, POSSIBLY SOME IN DRAIN IN ENTRANCE TO PARKING LOT, HAVE HIRED ESI, ASKED FOR UPDATE 9/20 11:15 JOE PARISI, ESI, CALLED, HAVE FINISHED CLEANING UP, TOOK PRODUCT, WATER AND IMPACTED SEDIMENT OUT OF DRAIN, WILL TAKE ENDPOINT, ARE WE RESPONDING, PERHAPS LATER 9/20 11:20 HC RETURNING FROM HICKSVILLE, WILL CHECK OILY WATER VAC FROM DRAIN, CONT SOIL GUZZLED FROM DRAIN, CLEAN ENDPOINT SAMPLE (CONFIRMATORY) DISPOSAL MANIFESTS FOR WATER AND SOIL REC'VD"
Remarks:	"line failure on the truck. spill being cleaned up."

Material:

Site ID:	321344
Operable Unit ID:	844709
Operable Unit:	01
Material ID:	531309
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

F30 **WOODBOURNE CULTURAL NSYS INC** **NY AST** **A100385672**
NNE **301 COLONIAL SPRING RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.082 mi.
435 ft. **Site 1 of 4 in cluster F**

Relative:
Lower

Actual:
97 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	12333
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	01/31/2018
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	12333
Billing Contact:	CAROLE PITTLEMAN

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Billing Address:	301 COLONIAL SPRINGS RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CAROLE PITTLEMAN
Storage Owner Address:	301 COLONIAL SPRINGS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	12333
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	14
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Tank ID:	15
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	16
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Total Capacity:	275 gallons
Date Permitted:	12/11/2002
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	200 gallons
Date Permitted:	Not reported
Date Closed:	11/19/2002
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

F31 **WOODBOURNE CULTURAL NSYS INC** **NY UST U003537562**
NNE **301 COLONIAL SPRING RD** **NY AST N/A**
< 1/8 **MELVILLE, NY 11747**
0.082 mi.
435 ft. **Site 2 of 4 in cluster F**

Relative:
Lower

Actual:
97 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	12333
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	01/31/2018
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	12333
Billing Contact:	CAROLE PITTLEMAN
Billing Address:	301 COLONIAL SPRINGS RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CAROLE PITTLEMAN
Storage Owner Address:	301 COLONIAL SPRINGS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	12333
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/27/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	1000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	1000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	4000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	4000 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2001
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	03/08/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07529
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07529
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	CAROLE PITTLEMAN
Storage Owner Address:	301 COLONIAL SPRINGS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	07529
Facility Reference #:	12333
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	6
Tank Key:	44353
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL / STEEL
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	121102
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Tank ID:	7
Tank Key:	44354
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	STEEL / STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	111902

F32 **WOODBOURNE CULTURAL** **NY Spills** **S109063004**
NNE **301 COLONIAL SPRINGS ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.082 mi.
435 ft. **Site 3 of 4 in cluster F**

Relative:
Lower

Actual:
97 ft.

SPILLS:

Facility ID:	0801935
Facility Type:	ER
DER Facility ID:	347368
Site ID:	397985
DEC Region:	1
Spill Date:	2008-05-19
Spill Number/Closed Date:	0801935 / 2008-10-30
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-05-19
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-19
Spill Record Last Update:	2010-03-23
Spiller Name:	ROGER
Spiller Company:	WOODBOURNE CULTURAL
Spiller Address:	301 COLONIAL SPRINGS RD
Spiller City,St,Zip:	MELVILLE, NY 11747
Spiller Company:	001
Contact Name:	ROGER
Contact Phone:	(631) 249-2329
DEC Memo:	""
Remarks:	"ABOUT 1 CUP OF MATERIAL WAS SPILLED; POROUS TANK; CUSTOMER IS

WOODBOURNE CULTURAL (Continued) **S109063004**

CLEANING IT UP;"

Material:
Site ID: 397985
Operable Unit ID: 1154901
Operable Unit: 01
Material ID: 2145735
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

F33 **WOODBOURNE CULTURAL NSYS INC** **NY UST** **U004219638**
NNE **301 COLONIAL SPRING RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.082 mi.
435 ft. **Site 4 of 4 in cluster F**

Relative:
Lower

Actual:
97 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 07529
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 07529
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: CAROLE PITTLEMAN
Storage Owner Address: 301 COLONIAL SPRINGS RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 07529
Facility Reference #: 12333
Official Use: Removed Tank. 92
Township: HUNTINGTON
Tax Map No: 0400 270.00 002 016.000
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 21758

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Installed:	82
Capacity:	0000003000
Substance:	GASOLINE
Date Removed:	052792
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	052792
Year Installed:	82
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	21759
Installed:	82
Capacity:	0000003000
Substance:	GASOLINE
Date Removed:	052892
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Date Removed:	052892
Year Installed:	82
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	21760
Installed:	82
Capacity:	0000001000
Substance:	DIESEL
Date Removed:	052892
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	052892
Year Installed:	82
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	4
Tank Key:	21761
Installed:	92
Capacity:	0000004000
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	5
Tank Key:	21762
Installed:	92
Capacity:	0000002500
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	8
Tank Key:	44454
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	010101
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	010101
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	9
Tank Key:	44455
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	10
Tank Key:	44456
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	11
Tank Key:	44457
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Tank ID:	12
Tank Key:	44458
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	13
Tank Key:	44459
Installed:	Not reported
Capacity:	0000000275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U004219638**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

G34 **HEIDELBERG PUBLISHING SERVICES** **RCRA NonGen / NLR** **1000274264**
WNW **80 RULAND RD** **FINDS** **NYD986885457**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.083 mi. **NY MANIFEST**
437 ft. **Site 1 of 3 in cluster G**

Relative: Higher

Actual: 108 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	HEIDELBERG PUBLISHING SERVICES
Facility address:	80 RULAND RD MELVILLE, NY 11747
EPA ID:	NYD986885457
Mailing address:	RULAND RD MELVILLE, NY 11747
Contact:	RICHARD LUHRS
Contact address:	RULAND RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(516) 753-4888
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HEIDELBERG PUBLISHING SERVICES
Owner/operator address:	80 RULAND RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 753-4800
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	HEIDELBERG PUBLISHING SERVICES
Owner/operator address:	80 RULAND RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 753-4800
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: HEIDELBERG PUBLISHING SERVICES
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: HEIDELBERG PUBLISHING
Classification: Large Quantity Generator

Date form received by agency: 12/11/1998
Site name: HEIDELBERG PUBLISHING SERVICES
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004440123

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019811220

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000274264
Registry ID:	110004440123
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004440123

NY MANIFEST:

Country:	USA
EPA ID:	NYD986885457
Facility Status:	Not reported
Location Address 1:	80 RULAND RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986885457
Mailing Name:	LINOTYPE-HELL CO
Mailing Contact:	JAMES MALLILO
Mailing Address 1:	80 RULAND RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164843000

NY MANIFEST:

Document ID:	NJA3089658
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2000
Trans1 Recv Date:	04/19/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJR000022442
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Document ID:	NJA3089848
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2000
Trans1 Recv Date:	03/28/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJR000022442
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Document ID:	NJA3089874
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2000
Trans1 Recv Date:	03/20/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/20/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJR000022442
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Document ID:	NJA3089941
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2000
Trans1 Recv Date:	03/06/2000

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJR000022442
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Document ID:	NYG0109467
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	PW2414
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/1997
Trans1 Recv Date:	06/03/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/03/1997
Part A Recv Date:	06/18/1997
Part B Recv Date:	07/03/1997
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NYG0396207
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	14467AK
Trans2 State ID:	Not reported
Generator Ship Date:	11/12/1997
Trans1 Recv Date:	11/12/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/12/1997
Part A Recv Date:	12/01/1997
Part B Recv Date:	11/26/1997
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NYG0057897
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PW6590
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/1997
Trans1 Recv Date:	03/24/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/24/1997
Part A Recv Date:	04/02/1997
Part B Recv Date:	04/11/1997
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00120
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYG0921033
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	PW6590
Trans2 State ID:	Not reported
Generator Ship Date:	07/11/1997
Trans1 Recv Date:	07/11/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/11/1997
Part A Recv Date:	07/30/1997
Part B Recv Date:	08/15/1997
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB6935418
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/1995
Trans1 Recv Date:	03/31/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/31/1995
Part A Recv Date:	04/07/1995
Part B Recv Date:	04/14/1995
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB7478613
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/1995
Trans1 Recv Date:	10/24/1995

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/24/1995
Part A Recv Date:	/ /
Part B Recv Date:	11/14/1995
Generator EPA ID:	NYD986885457
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
157 additional NY_MANIFEST: record(s) in the EDR Site Report.

G35 **LINOTYPE-HELL CO** **NY AST** **1006305092**
WNW **80 RULAND RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.083 mi.
437 ft. **Site 2 of 3 in cluster G**

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07760
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07760
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported

LINOTYPE-HELL CO (Continued) **1006305092**

Billing Zip: Not reported
Storage Owner: LINOTYPE-HELL CO
Storage Owner Address: 80 RULAND RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 07760
Facility Reference #: 14659
Township: HUNTINGTON
Tax Map No: 0400
Region: SUFFOLK

Tank ID: 1
Tank Key: 22405
Year Installed: Not reported
Substance: DRUM STORAGE
Construction: Not reported
Dispenser: Not reported
Official Use: Plans have been approved and awaiting construction
Permit to Operate: Not reported
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 0000001000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

Tank ID: 2
Tank Key: 22406
Year Installed: Not reported
Substance: PHOTO WASTEWATER
Construction: Not reported
Dispenser: SUBMERSIBLE
Official Use: Plans have been approved and awaiting construction
Permit to Operate: Not reported
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 0000000100
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported

LINOTYPE-HELL CO (Continued) **1006305092**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

H36 **PERGAMENT** **NY Spills** **S104951564**
South **101 MARCUS DRIVE** **NY MANIFEST** **N/A**
< 1/8 **MELVILLE, NY**
0.104 mi.
547 ft. **Site 1 of 7 in cluster H**

Relative:
Lower

Actual:
102 ft.

SPILLS:

Facility ID:	0013423
Facility Type:	ER
DER Facility ID:	417281
Site ID:	328273
DEC Region:	1
Spill Date:	2001-03-23
Spill Number/Closed Date:	0013423 / 2001-10-03
Spill Cause:	Human Error
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	DONOVAN
Referred To:	Not reported
Reported to Dept:	2001-03-23
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-23
Spill Record Last Update:	2012-04-11
Spiller Name:	BRIAN RAMOS
Spiller Company:	IMPACT ENVIROMENTAL
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	KINGS PARK, NY
Spiller Company:	001
Contact Name:	DAVE LORTHIOIR
Contact Phone:	(631) 586-4900
DEC Memo:	"3/23 SPOKE TO DAN PERKOWSKI, F&N, WILL GET INFO AND CALL BACK 13:28 TELECON DAVE LORTHIOIR, SOMEONE DOING LINE TEST, SOMEWHERE THERE AS LINE THAT WAS CUT BUT NOT CAPPED,LEAK IN BOILER ROOM AND INTO PARKING

PERGAMENT (Continued) **S104951564**

LOT, NO DRAINS AFFECTED SAME AS 00-13428 F&N CLEANING WITH SPEEDI DRI, F&N REPORTED THAT THEY ARE SENDING GUZZLER INSTEAD OF DRUMMING SOLIDS SPILL CONTAINED ON PAVED SURFACE. NO SOIL AFFECTED, SPEEDI DRI PLACED, SWEPT AND DISPOSED OF BY F&N, NO FURTHER ACTION"

Remarks: "DURING A LINE TEST AT ABOVE LOCATION EMPLOYEE FAILED TO CAP OFF A VALVE IN BOILER ROOM CAUSING ABOVE MATERIAL TO BE SPILLED. CREW ENROUTE FOR CLEANUP AND ALL MATERIAL IS EXPECTED TO BE RECOVERED. ***SAME AS 0013428***"

Material:

Site ID:	328273
Operable Unit ID:	834913
Operable Unit:	01
Material ID:	540135
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0013428
Facility Type:	ER
DER Facility ID:	417281
Site ID:	328274
DEC Region:	1
Spill Date:	2001-03-23
Spill Number/Closed Date:	0013428 / 2001-03-23
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2001-03-23
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-23
Spill Record Last Update:	2012-04-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -

PERGAMENT (Continued) **S104951564**

Spiller Company:	001
Contact Name:	RUSS
Contact Phone:	(631) 269-8800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE ***SAME AS 0013423***"
Remarks:	"caller was on site doing tank test and pipe leading to boiler failed causing spill - clean up in progress. ***SAME AS 0013423***"

Material:

Site ID:	328274
Operable Unit ID:	835371
Operable Unit:	01
Material ID:	540139
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

NY MANIFEST:

Country:	USA
EPA ID:	NYP000736259
Facility Status:	Not reported
Location Address 1:	101 MARCUS DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000736259
Mailing Name:	PERGAMENT HOME CENTER
Mailing Contact:	PERGAMENT HOME CENTER
Mailing Address 1:	101 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	NYA6292845
Manifest Status:	K
seq:	Not reported
Year:	1987

PERGAMENT (Continued) **S104951564**

Trans1 State ID:	39363GV
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1987
Trans1 Recv Date:	07/14/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/14/1987
Part A Recv Date:	09/10/1987
Part B Recv Date:	07/22/1987
Generator EPA ID:	NYP000736259
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00247
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	101

H37 **MRP FAMILY HOLDINGS LLC** **NY UST** **U003961357**
South **101 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.104 mi.
547 ft. **Site 2 of 7 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	16483
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	16483
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported

MRP FAMILY HOLDINGS LLC (Continued) **U003961357**

Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	MRP FAMILY HOLDINGS LLC
Storage Owner Address:	1500 OLD NORTHERN BLVD
Storage Owner City:	ROSLYN
Storage Owner State:	NY
Storage Owner Zip:	11576

Tank Info:

Facility ID:	16483
Facility Reference #:	16754
Official Use:	Removed Tank. 03
Township:	HUNTINGTON
Tax Map No:	0400 270.00 001 013.000
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	45061
Installed:	Not reported
Capacity:	0000015000
Substance:	#2 FUEL OIL
Date Removed:	091703
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000015000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	091703
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

G38
WNW
< 1/8
0.104 mi.
548 ft.

OTTO KEIL FLORIST
107 RULAND RD
MELVILLE, NY 11747

Site 3 of 3 in cluster G

NY AST **A100197467**
N/A

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07769
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07769
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	MARRATOOKA PROPERTIES LLC
Storage Owner Address:	107 RULAND RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	07769
Facility Reference #:	14697
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	1
Tank Key:	22425
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000005000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

OTTO KEIL Fflorist (Continued) **A100197467**

Fill: PUMPED
Date Removed: Not reported

H39 **RACANELLI COMMERCIAL BUILDING** **NY UST** **U003844038**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.119 mi.
628 ft. **Site 3 of 7 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 11311
Status: INACTIVE
Site Type: PBS
Operating Permit Expires: Not reported
Owner/Storage Information: AVAILABLE

Facility Info:
Site Ref#: 11311
Billing Contact: FONAR CORP
Billing Address: 110 MARCUS DR
Billing Address: MELVILLE
Billing State: NY
Billing Zip: 11747
Storage Owner: FONAR CORP
Storage Owner Address: 110 MARCUS DR
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 11311
Facility Reference #: Not reported
Official Use: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: Not reported
Installed: Not reported
Capacity: 3000 gallons
Substance: #2 FUEL OIL
Date Removed: Not reported
Construction: STEEL/ IRON
Dispenser: SUCTION
Fill Type: Not reported
Tank Location: UNDER - OUT
Tabk Status: REMOVED
Total Capacity: 3000 gallons
Date Permitted: Not reported
Date Closed: 10/27/2014
Internal Protection: NONE
Secondary Containment: NONE
Extrenal Protection: NONE
Leak Detection: NONE (NON-EXEMPT)

RACANELLI COMMERCIAL BUILDING (Continued) **U003844038**

Overfill Prevention:	- Vent Whistle
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	OTHER
Pipe External Protection:	NONE
Pipe Containment:	OTHER
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

H40 **FONAR TRAVEL** **NY UST** **U004219542**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.119 mi.
628 ft. **Site 4 of 7 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	07114
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07114
Billing Contact:	RAND INTERNATIONAL
Billing Address:	51 EXECUTIVE BLVD
Billing Address:	FARMINGDALE
Billing State:	NY
Billing Zip:	11735
Storage Owner:	RAND INTERNATIONAL
Storage Owner Address:	51 EXECUTIVE BLVD
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	07114
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	URETHANE CLAD STEEL
Dispenser:	SUCTION

FONAR TRAVEL (Continued) **U004219542**

Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	URETHANE
Leak Detection:	U-TUBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	COPPER
Pipe External Protection:	NONE
Pipe Containment:	PVC
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

H41 **DON JAGODA INC** **NY UST** **U004219566**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.119 mi.
628 ft. **Site 5 of 7 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	07203
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07203
Billing Contact:	MELVILLE FIRE DISTRICT
Billing Address:	531 SWEET HOLLOW RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	MELVILLE FIRE DISTRICT
Storage Owner Address:	531 SWEET HOLLOW RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	07203
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK

DON JAGODA INC (Continued) **U004219566**

Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	2000 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported
Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	2000 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

DON JAGODA INC (Continued) **U004219566**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	2000 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	250 gallons
Substance:	WASTE OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	250 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE

DON JAGODA INC (Continued) **U004219566**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	250 gallons
Substance:	WASTE OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	250 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	6
Tank Key:	Not reported
Installed:	Not reported
Capacity:	6000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported

DON JAGODA INC (Continued) **U004219566**

Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	6000 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	07/13/1993
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	Not reported

DON JAGODA INC (Continued) **U004219566**

Installed:	Not reported
Capacity:	2500 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	07/13/1993
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	WASTE OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	06/07/1993
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported

DON JAGODA INC (Continued) **U004219566**

Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	NONE (NON-EXEMPT)
Overfill Prevention:	Not reported
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	PLAIN STEEL/IRON
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

H42 **RACANELLI ASSOCIATES** **NY LTANKS** **S100147328**
South **100 MARCUS DRIVE** **N/A**
1/8-1/4 **MELVILLE, NY**
0.127 mi.
673 ft. **Site 6 of 7 in cluster H**

Relative:
Lower

Actual:
101 ft.

LTANKS:

Site ID:	99721
Spill Number/Closed Date:	8805457 / 1988-09-30
Spill Date:	1988-09-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-09-30
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-09-27
CID:	Not reported
Water Affected:	Not reported

RACANELLI ASSOCIATES (Continued) **S100147328**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-30
Spill Record Last Update:	2006-06-07
Spiller Name:	Not reported
Spiller Company:	RACANELLI ASSOCIATES
Spiller Address:	200 MOTOR PARKWAY
Spiller City,St,Zip:	HAUPPAUGE, NY 11787
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	88586
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 09/30/88: TANK REMOVED BY F&N FOR SPILLER ON 9/30/88.TANK HAD LITTLE SURFACE RUST, NO PITTING, NO HOLES,2 OIL STAINS NEAR BUNGS. NO CONTAMINATED SOIL ENCOUNTERED. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"5K FAILED AT -.131 GPH. FIRST TEST ON 9/23,FAILED RETEST ON 9/26 TANK ALONE AT -.091 GPH. F&N TESTER"

Material:

Site ID:	99721
Operable Unit ID:	920615
Operable Unit:	01
Material ID:	457359
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	99721
Spill Tank Test:	1534681
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

H43 **ESPRIT BLDG** **NY UST** **U003537687**
South **100 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.127 mi.
673 ft. **Site 7 of 7 in cluster H**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	07104
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07104
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	N RACANELLI ASSOC
Storage Owner Address:	200 MOTOR PARKWAY, SUITE C-20
Storage Owner City:	HAUPPAUGE
Storage Owner State:	NY
Storage Owner Zip:	11788

Tank Info:

Facility ID:	07104
Facility Reference #:	10918
Official Use:	Removed Tank. 88
Township:	HUNTINGTON
Tax Map No:	0400 270.00 001 015.002
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	20072
Installed:	Not reported
Capacity:	0000005000
Substance:	#2 FUEL OIL
Date Removed:	093088
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000005000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

ESPRIT BLDG (Continued) **U003537687**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	093088
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	20073
Installed:	89
Capacity:	0000004000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	89
Description of drop records:	RECORDS AS OF 09/10/2013

I44 **NEW YORK STATE DRUG ENFORCEMENT ADMINIST** **NY MANIFEST** **1009233484**
North **175 PINELAWN RD SUITE 205** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.138 mi.
731 ft. **Site 1 of 2 in cluster I**

Relative:
Lower

Actual:
100 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP000916015
Facility Status:	Not reported
Location Address 1:	175 PINELAWN RD SUITE 205
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747

NEW YORK STATE DRUG ENFORCEMENT ADMINIST (Continued) **1009233484**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000916015
Mailing Name: NEW YORK STATE DRUG ENFORCEMENT ADMINIST
Mailing Contact: DIRK H LUEDERS
Mailing Address 1: 175 PINELAWN RD SUITE 205
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5164204520

NY MANIFEST:
Document ID: MDC0409838
Manifest Status: C
seq: Not reported
Year: 1994
Trans1 State ID: HWH15
Trans2 State ID: Not reported
Generator Ship Date: 07/19/1994
Trans1 Recv Date: 07/19/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 07/22/1994
Part A Recv Date: / /
Part B Recv Date: 08/01/1994
Generator EPA ID: NYP000916015
Trans1 EPA ID: MDD980554653
Trans2 EPA ID: Not reported
TSDF ID 1: MDD980554653
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F005 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

I45 **HONEYWELL INC** **NY Spills** **1000990521**
North **175 PINELAWN RD** **RCRA NonGen / NLR** **NYR000004804**
1/8-1/4 **MELVILLE, NY 11747** **FINDS**
0.138 mi. **ECHO**
731 ft. **Site 2 of 2 in cluster I** **NY MANIFEST**

Relative:
Lower

Actual:
100 ft.

SPILLS:

Facility ID:	0800679
Facility Type:	ER
DER Facility ID:	345960
Site ID:	396476
DEC Region:	1
Spill Date:	2008-04-16
Spill Number/Closed Date:	0800679 / 2008-10-30
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-04-16
CID:	404
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-16
Spill Record Last Update:	2008-11-13
Spiller Name:	SEAN DAVIS
Spiller Company:	COMMERICAL BUILDING
Spiller Address:	175 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	SEAN DAVIS
Contact Phone:	(646) 235-0406
DEC Memo:	""
Remarks:	"equipment failure with a padmount transformer; contained; clean up in progress"

Material:

Site ID:	396476
Operable Unit ID:	1153442
Operable Unit:	01
Material ID:	2144203
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

HONEYWELL INC (Continued) **1000990521**

Tank Test:

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	HONEYWELL INC
Facility address:	175 PINELAWN RD MELVILLE, NY 11747
EPA ID:	NYR000004804
Mailing address:	PINELAWN RD MELVILLE, NY 11747
Contact:	Not reported
Contact address:	PINELAWN RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HONEYWELL INC
Owner/operator address:	75-20 ASTORIA BLVD JACKSON HEIGHTS, NY 11370
Owner/operator country:	US
Owner/operator telephone:	(718) 651-4100
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	HONEYWELL INC
Owner/operator address:	75-20 ASTORIA BLVD JACKSON HEIGHTS, NY 11370
Owner/operator country:	US
Owner/operator telephone:	(718) 651-4100
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

HONEYWELL INC (Continued) **1000990521**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 05/12/1995
Site name: HONEYWELL INC
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

FINDS:

Registry ID: 110006448692

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110058270115

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000990521
Registry ID: 110006448692

HONEYWELL INC (Continued) **1000990521**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110006448692

NY MANIFEST:

Country:	USA
EPA ID:	NYR000004804
Facility Status:	Not reported
Location Address 1:	175 PINELAWN RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000004804
Mailing Name:	HONEYWELL CORP
Mailing Contact:	JIMMY MORALES
Mailing Address 1:	175 PINELAWN RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5165594048

NY MANIFEST:

Document ID:	NYB6913575
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	XR4643
Trans2 State ID:	Not reported
Generator Ship Date:	05/18/1995
Trans1 Recv Date:	05/18/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/18/1995
Part A Recv Date:	/ /
Part B Recv Date:	05/30/1995
Generator EPA ID:	NYR000004804
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

HONEYWELL INC (Continued) **1000990521**

MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	103
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	109

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	TXR000050930
Trans2 State ID:	OKD981588791
Generator Ship Date:	07/24/2008
Trans1 Recv Date:	07/24/2008
Trans2 Recv Date:	08/07/2008
TSD Site Recv Date:	08/09/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000004804
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	001306901SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

HONEYWELL INC (Continued) **1000990521**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	D011
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

46 **85 MARCUS DR** **RCRA-CESQG** **1000215971**
SW **85 MARCUS DR** **FINDS** **NYD980766349**
1/8-1/4 **MELVILLE, NY 11747** **ECHO**
0.141 mi. **NY MANIFEST**
745 ft.

Relative:
Lower

Actual:
102 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	INTERLOGIC INDUSTRIES
Facility address:	85 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYD980766349
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	Not reported
Contact address:	MARCUS DR MELVILLE, NY 11747
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

85 MARCUS DR (Continued) **1000215971**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	INTERLOGIC INDUSTRIES
Classification:	Not a generator, verified

Date form received by agency:	07/14/1999
Site name:	INTERLOGIC INDUSTRIES
Classification:	Small Quantity Generator

Date form received by agency:	02/07/1984
Site name:	INTERLOGIC INDUSTRIES

85 MARCUS DR (Continued) **1000215971**

Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

Violation Status: No violations found

FINDS:

Registry ID: 110004390631

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019770666

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000215971
Registry ID:	110004390631
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004390631

NY MANIFEST:

Country:	USA
EPA ID:	NYD980766349
Facility Status:	Not reported
Location Address 1:	85 MARCUS DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD980766349
Mailing Name:	INTERLOGIC INDUSTRIES INCORPORATED
Mailing Contact:	DONALD GREENE
Mailing Address 1:	85 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747

85 MARCUS DR (Continued) **1000215971**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164208111

NY MANIFEST:

Document ID:	NJA3057820
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	06/29/2000
Trans1 Recv Date:	06/29/2000
Trans2 Recv Date:	06/30/2000
TSD Site Recv Date:	07/06/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	MDD980554653
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00447
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Document ID:	NJA2652576
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/1997
Trans1 Recv Date:	05/07/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1997

85 MARCUS DR (Continued) **1000215971**

Part A Recv Date:	05/16/1997
Part B Recv Date:	05/20/1997
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00447
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0124826
Manifest Status:	K
seq:	Not reported
Year:	1986
Trans1 State ID:	JA-195NJD
Trans2 State ID:	NJDEPNOS0
Generator Ship Date:	01/09/1986
Trans1 Recv Date:	01/09/1986
Trans2 Recv Date:	01/10/1986
TSD Site Recv Date:	01/10/1986
Part A Recv Date:	02/07/1986
Part B Recv Date:	01/22/1986
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	NJD981138324
Trans2 EPA ID:	NJD981138324
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

85 MARCUS DR (Continued) **1000215971**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00053
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NJA2683723
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	11/10/1997
Trans1 Recv Date:	11/10/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/17/1997
Part A Recv Date:	11/26/1997
Part B Recv Date:	12/11/1997
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00448
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

85 MARCUS DR (Continued) **1000215971**

Specific Gravity:	100
Document ID:	NJA1501223
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	NJDEPS280
Trans2 State ID:	Not reported
Generator Ship Date:	08/11/1992
Trans1 Recv Date:	08/11/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/11/1992
Part A Recv Date:	/ /
Part B Recv Date:	08/24/1992
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NJA0954155
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	S8158
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/1990
Trans1 Recv Date:	10/22/1990
Trans2 Recv Date:	10/23/1990
TSD Site Recv Date:	10/23/1990
Part A Recv Date:	11/01/1990
Part B Recv Date:	11/06/1990
Generator EPA ID:	NYD980766349

85 MARCUS DR (Continued) **1000215971**

Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NJA1766109
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	NJDEPE280
Trans2 State ID:	Not reported
Generator Ship Date:	02/15/1994
Trans1 Recv Date:	02/15/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/15/1994
Part A Recv Date:	02/28/1994
Part B Recv Date:	02/28/1994
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

85 MARCUS DR (Continued) **1000215971**

MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NJA2554361
Manifest Status:	K
seq:	Not reported
Year:	1996
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/1996
Trans1 Recv Date:	10/23/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/25/1996
Part A Recv Date:	11/07/1996
Part B Recv Date:	11/19/1996
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00447
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0735162

85 MARCUS DR (Continued) **1000215971**

Manifest Status:	C
seq:	Not reported
Year:	1989
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	08/10/1989
Trans1 Recv Date:	08/10/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/11/1989
Part A Recv Date:	08/16/1989
Part B Recv Date:	08/17/1989
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	NJD982528168
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NJA0009491
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	JA-195NJS
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/1985
Trans1 Recv Date:	06/03/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/03/1985
Part A Recv Date:	06/10/1985
Part B Recv Date:	06/10/1985
Generator EPA ID:	NYD980766349
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD048810279

85 MARCUS DR (Continued) **1000215971**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
13 additional NY_MANIFEST: record(s) in the EDR Site Report.

J47 **COMAX FLAVORS** **RCRA-LQG** **1000141185**
NNW **130 BAYLISS RD** **NJ MANIFEST** **NYD016914376**
1/8-1/4 **MELVILLE, NY 11747** **NY MANIFEST**
0.142 mi.
750 ft. **Site 1 of 2 in cluster J**

Relative:
Higher

Actual:
107 ft.

RCRA-LQG:

Date form received by agency:	02/28/2008
Facility name:	COMAX FLAVORS
Facility address:	130 BAYLISS RD MELVILLE, NY 11747
EPA ID:	NYD016914376
Mailing address:	BAYLISS RD MELVILLE, NY 11747
Contact:	JOE PIAZZA
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(631) 249-0505
Contact email:	JPIAZZA@COMAXFLAUORS.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous

COMAX FLAVORS (Continued) **1000141185**

waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CALABRETTA FAMILY LLC
Owner/operator address:	BAYLISS RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2000
Owner/Op end date:	Not reported

Owner/operator name:	CALABRETTA FAMILY LLC
Owner/operator address:	BAYLISS RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

. Waste code:	D007
. Waste name:	CHROMIUM

. Waste code:	D009
. Waste name:	MERCURY

. Waste code:	P022

COMAX FLAVORS (Continued) **1000141185**

. Waste name: CARBON DISULFIDE

. Waste code: U135
. Waste name: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

. Waste code: U151
. Waste name: MERCURY

. Waste code: U153
. Waste name: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Historical Generators:
Date form received by agency: 01/01/2007
Site name: COMAX FLAVORS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/28/2006
Site name: COMAX FLAVORS
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Date form received by agency: 08/27/2006
Site name: COMAX FLAVORS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/04/2002
Site name: COMAX MFG CORP
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Date form received by agency: 07/08/1999
Site name: COMAX MFG CORP
Classification: Not a generator, verified

Date form received by agency: 06/04/1987
Site name: COMAX MFG CORP
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 05/30/2008
Date achieved compliance: 06/19/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

COMAX FLAVORS (Continued) **1000141185**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 05/30/2008
Date achieved compliance: 06/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

COMAX FLAVORS (Continued) **1000141185**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 05/30/2008
Date achieved compliance: 06/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 06/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 06/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 06/19/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

NJ MANIFEST:
EPA Id: NYD016914376
Mail Address: 130 BAYLIS ROAD

COMAX FLAVORS (Continued) **1000141185**

Mail City/State/Zip:	MELVILLE 11747
Facility Phone:	6312490505
Emergency Phone:	Not reported
Contact:	MARTON CUNNINGHAM
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006651224JJK
EPA ID:	NYD016914376
Date Shipped:	7/21/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

COMAX FLAVORS (Continued) **1000141185**

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	2,150.00 Pounds

Manifest Number:	008760495JJK
EPA ID:	NYD016914376
Date Shipped:	9/24/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	800.00 Pounds

Manifest Number:	008758547JJK
EPA ID:	NYD016914376
Date Shipped:	11/30/2012
TSDF EPA ID:	NJD980536593

COMAX FLAVORS (Continued) **1000141185**

Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	800.00 Pounds

Manifest Number:	008760193JJK
EPA ID:	NYD016914376
Date Shipped:	12/10/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,010.00 Pounds

Manifest Number:	004718520JJK
EPA ID:	NYD016914376
Date Shipped:	12/08/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/08/2008
Date Trans2 Transported Waste:	12/12/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date TSDF Received Waste:	12/12/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	1800 P

Manifest Number:	011643378JJK
EPA ID:	NYD016914376
Date Shipped:	7/29/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	COMAX FLAVORS
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	7/29/2015
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	7/31/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001033697JJK
EPA ID:	NYD016914376
Date Shipped:	08/24/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/24/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/24/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	5 P
Manifest Year:	Not reported
Waste Code:	D001

COMAX FLAVORS (Continued) **1000141185**

Hand Code:	H14
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H14
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	385 G
Manifest Year:	Not reported
Waste Code:	U151
Hand Code:	H14
Quantity:	5 G
Manifest Number:	NJA5030969
EPA ID:	NYD016914376
Date Shipped:	01/25/2005
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD002454544
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/25/2005
Date Trans2 Transported Waste:	01/25/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/25/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04110521

COMAX FLAVORS (Continued) **1000141185**

Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	008758668JJK
EPA ID:	NYD016914376
Date Shipped:	2/7/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	004718678JJK
EPA ID:	NYD016914376
Date Shipped:	03/20/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/20/2009
Date Trans2 Transported Waste:	03/24/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/27/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	900 P

Manifest Number:	004718324JJK
EPA ID:	NYD016914376
Date Shipped:	03/09/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/09/2010
Date Trans2 Transported Waste:	03/10/2010
Date Trans3 Transported Waste:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/11/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	900 P

Manifest Number:	006657627JJK
EPA ID:	NYD016914376
Date Shipped:	07/06/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/06/2010
Date Trans2 Transported Waste:	07/06/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/07/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	2000 P

Manifest Number:	006657837JJK
EPA ID:	NYD016914376
Date Shipped:	10/08/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/08/2010
Date Trans2 Transported Waste:	10/11/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/13/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Data Entry Number: Not reported
Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 2150 P

Manifest Number: 006657985JJK
EPA ID: NYD016914376
Date Shipped: 2/9/2011
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 800.00 Pounds

COMAX FLAVORS (Continued) **1000141185**

Manifest Number:	008760454JJK
EPA ID:	NYD016914376
Date Shipped:	8/8/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	400.00 Pounds

Manifest Number:	008757717JJK
EPA ID:	NYD016914376
Date Shipped:	5/31/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	011643092JJK
EPA ID:	NYD016914376
Date Shipped:	5/11/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	COMAX FLAVORS
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	5/11/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	5/12/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	008760387JJK
EPA ID:	NYD016914376
Date Shipped:	6/20/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	006657904JJK
EPA ID:	NYD016914376
Date Shipped:	11/18/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/18/2010
Date Trans2 Transported Waste:	11/19/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/24/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001

COMAX FLAVORS (Continued) **1000141185**

Hand Code:	H141
Quantity:	2150 P
Manifest Number:	008758589JJK
EPA ID:	NYD016914376
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	400.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYD016914376
Facility Status:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Location Address 1:	130 BAYLISS RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD016914376
Mailing Name:	COMAX FLAVORS
Mailing Contact:	MARION CUNNINGHAM
Mailing Address 1:	130 BAYLIS ROAD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6312490505

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	04/09/2008
Trans1 Recv Date:	04/09/2008
Trans2 Recv Date:	04/15/2008
TSD Site Recv Date:	04/15/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072479JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Code:	Not reported
Quantity:	450.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	12/08/2008
Trans1 Recv Date:	12/08/2008
Trans2 Recv Date:	12/12/2008
TSD Site Recv Date:	12/12/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004718520JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1800.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	09/03/2008
Trans1 Recv Date:	09/03/2008
Trans2 Recv Date:	09/05/2008
TSD Site Recv Date:	09/05/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072003JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1570.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008

COMAX FLAVORS (Continued) **1000141185**

Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	10/27/2008
Trans1 Recv Date:	10/27/2008
Trans2 Recv Date:	10/31/2008
TSD Site Recv Date:	10/31/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072104JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	10/27/2008
Trans1 Recv Date:	10/27/2008
Trans2 Recv Date:	10/31/2008
TSD Site Recv Date:	10/31/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376

COMAX FLAVORS (Continued) **1000141185**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072104JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	04/09/2008
Trans1 Recv Date:	04/09/2008
Trans2 Recv Date:	04/15/2008
TSD Site Recv Date:	04/15/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072479JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

COMAX FLAVORS (Continued) **1000141185**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	06/18/2008
Trans1 Recv Date:	06/18/2008
Trans2 Recv Date:	06/27/2008
TSD Site Recv Date:	06/27/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072331JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	10/23/2015
Trans1 Recv Date:	10/23/2015
Trans2 Recv Date:	10/23/2015
TSD Site Recv Date:	10/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	008933452FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.

COMAX FLAVORS (Continued) **1000141185**

Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	12/29/2015
Trans1 Recv Date:	12/29/2015
Trans2 Recv Date:	12/29/2015
TSD Site Recv Date:	01/05/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	008933581FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1600
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	05/11/2015
Trans1 Recv Date:	05/11/2015
Trans2 Recv Date:	05/11/2015
TSD Site Recv Date:	05/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	011643092JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
82 additional NY_MANIFEST: record(s) in the EDR Site Report.

J48 **COMAX MANUFACTURING CORP** **NY AST** **A100281108**
NNW **130 BAYLIS RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.142 mi.
750 ft. **Site 2 of 2 in cluster J**

Relative:
Higher

Actual:
107 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	08369
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	08369
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	PAUL CALABRETTA
Storage Owner Address:	130 BAYLIS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08369
Facility Reference #:	05634
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	1
Tank Key:	46697
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000016500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Fill:	Not reported
Date Removed:	Not reported

Tank ID:	10
Tank Key:	48457
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	CONCRETE
Dispenser:	Not reported
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000004675
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	2
Tank Key:	46698
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	3
Tank Key:	46699
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	4
Tank Key:	46700
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	5
Tank Key:	46701
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	46702
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	46703
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	8
Tank Key:	46704
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	9
Tank Key:	46706
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

K49 **MEDISYS HEALTH NETWORK** **NY UST** **U003537372**
SSW **80 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.148 mi.
779 ft. **Site 1 of 2 in cluster K**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	07596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07596
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported

MEDISYS HEALTH NETWORK (Continued) **U003537372**

Storage Owner: MEDISYS HEALTH NETWORK
Storage Owner Address: 8906 135TH STREET
Storage Owner City: RICHMOND HILL
Storage Owner State: NY
Storage Owner Zip: 11418

Tank Info:
Facility ID: 07596
Facility Reference #: 13804
Official Use: Removed Tank. 92
Township: HUNTINGTON
Tax Map No: 0400 270.00 001 016.000
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 21937
Installed: 61
Capacity: 0000007500
Substance: #2 FUEL OIL
Date Removed: 032492
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 0000007500
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: PUMPED
Date Removed: 032492
Year Installed: 61
Description of drop records: RECORDS AS OF 09/10/2013

Tank ID: 2
Tank Key: 21938
Installed: 82
Capacity: 0000006000
Substance: #2 FUEL OIL
Date Removed: Not reported
Construction: FRP
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER

MEDISYS HEALTH NETWORK (Continued) **U003537372**

Tabk Status:	Not reported
Total Capacity:	0000006000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	82
Description of drop records:	RECORDS AS OF 09/10/2013

K50 **GENOVESE DRUG STORES HQ** **NY LTANKS** **1000343746**
SSW **80 MARCUS DR** **RCRA NonGen / NLR** **NYD012364949**
1/8-1/4 **MELVILLE, NY 11747** **FINDS**
0.148 mi. **ECHO**
779 ft. **Site 2 of 2 in cluster K** **NY MANIFEST**

Relative:
Lower

Actual:
102 ft.

LTANKS:

Site ID:	249892
Spill Number/Closed Date:	9110046 / 1999-09-08
Spill Date:	1991-12-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1991-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-23
Spill Record Last Update:	1999-09-13
Spiller Name:	Not reported
Spiller Company:	GENOVESE DRUG STORE
Spiller Address:	80 MARCUS DRIVE
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 204843
DEC Memo: ""
Remarks: "5K FAILED AT -0.334, TYREE TESTER"

Material:
Site ID: 249892
Operable Unit ID: 963718
Operable Unit: 01
Material ID: 418620
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 249892
Spill Tank Test: 1539454
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: GENOVESE DRUG STORES HQ
Facility address: 80 MARCUS DR
MELVILLE, NY 117474230
EPA ID: NYD012364949
Mailing address: MARCUS DR
MELVILLE, NY 11747
Contact: HERNAN GUTIERREZ
Contact address: MARCUS DR
MELVILLE, NY 11747
Contact country: US
Contact telephone: (631) 845-8645
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ECKERD CORP - C/O GENOVESE
Owner/operator address: 80 MARCUS DR

GENOVESE DRUG STORES HQ (Continued) **1000343746**

MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (631) 845-8645
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: ECKERD CORP - C/O GENOVESE
Owner/operator address: 80 MARCUS DR
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (631) 845-8645
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: EMIL DILOILO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/30/2000
Owner/Op end date: Not reported

Owner/operator name: EMIL DILOILO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/30/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Date form received by agency: 01/01/2006
Site name: GENOVESE DRUG STORES HQ
Classification: Not a generator, verified

Date form received by agency: 10/30/2000
Site name: GENOVESE DRUG STORES HQ
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 07/08/1999
Site name: GENOVESE DRUG STORES HQ
Classification: Not a generator, verified

Date form received by agency: 11/14/1988
Site name: GENOVESE DRUG STORES HQ
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004344246

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019180358

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000343746
Registry ID: 110004344246
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004344246

NY MANIFEST:
Country: USA
EPA ID: NYD012364949
Facility Status: Not reported
Location Address 1: 80 MARCUS DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012364949
Mailing Name:	GENOVESE DRUG STORES INCORPORATED
Mailing Contact:	GENOVESE DRUG STORES INCORPORATED
Mailing Address 1:	80 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164201900

NY MANIFEST:

Document ID:	NYB5798898
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/1992
Trans1 Recv Date:	09/30/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/30/1992
Part A Recv Date:	/ /
Part B Recv Date:	10/19/1992
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NYB5871528
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/1991
Trans1 Recv Date:	12/31/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/31/1991
Part A Recv Date:	/ /
Part B Recv Date:	01/14/1992
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NYB2942883
Manifest Status:	K
seq:	Not reported
Year:	1991
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/1991
Trans1 Recv Date:	06/25/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/25/1991
Part A Recv Date:	08/09/1991

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Part B Recv Date:	07/23/1991
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB5386977
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	06/24/1993
Trans1 Recv Date:	06/24/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/24/1993
Part A Recv Date:	/ /
Part B Recv Date:	07/09/1993
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB1245510
Manifest Status:	K
seq:	Not reported
Year:	1991
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/1991
Trans1 Recv Date:	02/12/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/12/1991
Part A Recv Date:	05/22/1991
Part B Recv Date:	03/04/1991
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00026
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Document ID:	NYA7178967
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	05/31/1989
Trans1 Recv Date:	05/31/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/31/1989
Part A Recv Date:	07/12/1989
Part B Recv Date:	06/07/1989
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	MAM9230730
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	NYAT8756
Trans2 State ID:	P227659IL
Generator Ship Date:	01/29/2001
Trans1 Recv Date:	01/29/2001
Trans2 Recv Date:	02/02/2001
TSD Site Recv Date:	02/08/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012364949
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

GENOVESE DRUG STORES HQ (Continued) **1000343746**

TSDF ID 1:	MAD982755639
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00440
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

L51 **110 MARCUS DR** **RCRA NonGen / NLR** **1000446533**
SSE **110 MARCUS DR** **FINDS** **NYD986908853**
1/8-1/4 **MELVILLE, NY 11747** **ECHO**
0.150 mi. **NY MANIFEST**
791 ft. **Site 1 of 2 in cluster L** **NJ MANIFEST**

Relative:
Lower

Actual:
102 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FONAR CORP INC
Facility address:	110 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYD986908853
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	Not reported
Contact address:	MARCUS DR MELVILLE, NY 11747
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DR RAYMOND DAMADIAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999

110 MARCUS DR (Continued) **1000446533**

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DR RAYMOND DAMADIAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FONAR CORP INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: FONAR CORP INC
Classification: Small Quantity Generator

Date form received by agency: 08/03/1990
Site name: FONAR CORP INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

110 MARCUS DR (Continued) **1000446533**

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/01/2000
Date achieved compliance: 03/05/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/27/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/22/1991
Date achieved compliance: 04/24/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/22/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/01/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/05/2001
Evaluation lead agency: State

Evaluation date: 02/22/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/22/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/24/1991
Evaluation lead agency: State

FINDS:

Registry ID: 110004450969

110 MARCUS DR (Continued) **1000446533**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019835749

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000446533
Registry ID: 110004450969
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004450969

NY MANIFEST:
Country: USA
EPA ID: NYD986908853
Facility Status: Not reported
Location Address 1: 110 MARCUS DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986908853
Mailing Name: FONAR CORPORATION
Mailing Contact: FONAR CORPORATION
Mailing Address 1: 110 MARCUS DRIVE
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5166982929

NY MANIFEST:
Document ID: NYH0133722
Manifest Status: Not reported
seq: 01
Year: 2000
Trans1 State ID: 6058PB

110 MARCUS DR (Continued) **1000446533**

Trans2 State ID:	Not reported
Generator Ship Date:	05/25/2000
Trans1 Recv Date:	05/25/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/25/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Document ID:	NYH0139581
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	PW8913
Trans2 State ID:	Not reported
Generator Ship Date:	10/04/2000
Trans1 Recv Date:	10/04/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/04/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

110 MARCUS DR (Continued) **1000446533**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Document ID:	NYG0023184
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	XR4643
Trans2 State ID:	Not reported
Generator Ship Date:	04/11/1997
Trans1 Recv Date:	04/11/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/11/1997
Part A Recv Date:	04/22/1997
Part B Recv Date:	04/25/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

110 MARCUS DR (Continued) **1000446533**

Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	NYB2105388
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	HL4120
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/1990
Trans1 Recv Date:	08/27/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/27/1990
Part A Recv Date:	09/07/1990
Part B Recv Date:	09/07/1990
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	NYH0094419
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	14467AK
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2000
Trans1 Recv Date:	01/31/2000

110 MARCUS DR (Continued) **1000446533**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00160
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Document ID:	NJA2108419
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1997
Trans1 Recv Date:	07/22/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/22/1997
Part A Recv Date:	/ /
Part B Recv Date:	08/11/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

110 MARCUS DR (Continued) **1000446533**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYG0923391
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PX3640
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/1997
Trans1 Recv Date:	07/21/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/21/1997
Part A Recv Date:	08/06/1997
Part B Recv Date:	08/08/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003

110 MARCUS DR (Continued) **1000446533**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	108
Document ID:	NYG0829755
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PW8913
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/1997
Trans1 Recv Date:	10/13/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/13/1997
Part A Recv Date:	10/29/1997
Part B Recv Date:	10/29/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	104
Document ID:	NYB8541324
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/1997
Trans1 Recv Date:	01/17/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/17/1997
Part A Recv Date:	02/06/1997

110 MARCUS DR (Continued) **1000446533**

Part B Recv Date:	01/30/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	108

Document ID:	ALA0044033
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	PA250
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1997
Trans1 Recv Date:	01/08/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/13/1997
Part A Recv Date:	/ /
Part B Recv Date:	02/11/1997
Generator EPA ID:	NYD986908853
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD981020894
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

110 MARCUS DR (Continued) **1000446533**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
23 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYD986908853
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	5166942929
Emergency Phone:	9084695100
Contact:	LOU CORRADONE
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5077013
EPA ID:	NYD986908853
Date Shipped:	05/07/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

110 MARCUS DR (Continued) **1000446533**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06080425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

L52 **M & W RECKSON ASSOCIATES** **NY UST** **U003537823**
SSE **110 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.150 mi.
791 ft. **Site 2 of 2 in cluster L**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08229
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	08229
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	RECKSON ASSOCIATES
Storage Owner Address:	225 BROADHOLLOW RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08229
Facility Reference #:	04094
Official Use:	Abandoned, approved by plan review, awaiting construction for compliance inspection. 01
Township:	HUNTINGTON
Tax Map No:	0400 270.00 001 015.001

M & W RECKSON ASSOCIATES (Continued) **U003537823**

Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	23818
Installed:	83
Capacity:	0000008000
Substance:	#2 FUEL OIL
Date Removed:	110501
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	110501
Year Installed:	83
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	23819
Installed:	83
Capacity:	0000008000
Substance:	#2 FUEL OIL
Date Removed:	110501
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

M & W RECKSON ASSOCIATES (Continued) **U003537823**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	110501
Year Installed:	83
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	23820
Installed:	83
Capacity:	0000008000
Substance:	#2 FUEL OIL
Date Removed:	110501
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000008000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	110501
Year Installed:	83
Description of drop records:	RECORDS AS OF 09/10/2013

M53 **RULAND ROAD LLC** **NY UST** **U003961171**
WNW **95 RULAND RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.173 mi.
914 ft. **Site 1 of 2 in cluster M**

Relative:
Lower

Actual:
104 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	07153
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07153

RULAND ROAD LLC (Continued) **U003961171**

Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	RULAND ROAD LLC
Storage Owner Address:	337 OAK ST
Storage Owner City:	GARDEN CITY
Storage Owner State:	NY
Storage Owner Zip:	11530

Tank Info:

Facility ID:	07153
Facility Reference #:	10977
Official Use:	Removed Tank. 02
Township:	HUNTINGTON
Tax Map No:	0400 267.00 001 031.000
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	8
Tank Key:	43422
Installed:	Not reported
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	061102
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061102
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	9
Tank Key:	43423
Installed:	Not reported
Capacity:	0000001000
Substance:	FERTILIZER MIXER

RULAND ROAD LLC (Continued) **U003961171**

Date Removed:	061002
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	10
Tank Key:	43424
Installed:	Not reported
Capacity:	0000000550
Substance:	GASOLINE
Date Removed:	060702
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

RULAND ROAD LLC (Continued) **U003961171**

Tank ID:	11
Tank Key:	43425
Installed:	Not reported
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	061102
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061102
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	12
Tank Key:	43426
Installed:	Not reported
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	061002
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	13
Tank Key:	43427
Installed:	Not reported
Capacity:	0000001000
Substance:	#2 FUEL OIL
Date Removed:	061002
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	14
Tank Key:	43428
Installed:	Not reported
Capacity:	0000004000
Substance:	#2 FUEL OIL
Date Removed:	061002
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	15
Tank Key:	43429
Installed:	Not reported
Capacity:	0000002000
Substance:	#2 FUEL OIL
Date Removed:	061002
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	16
Tank Key:	43430
Installed:	Not reported
Capacity:	0000000550
Substance:	#2 FUEL OIL
Date Removed:	061102
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061102
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	23
Tank Key:	43437
Installed:	Not reported
Capacity:	0000002000
Substance:	KEROSENE
Date Removed:	060702
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

M54 **RULAND ROAD LLC** **NY AST** **A100265046**
WNW **95 RULAND RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.173 mi.
914 ft. **Site 2 of 2 in cluster M**

Relative:
Lower

Actual:
104 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	07153
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	07153
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	RULAND ROAD LLC
Storage Owner Address:	337 OAK ST
Storage Owner City:	GARDEN CITY
Storage Owner State:	NY
Storage Owner Zip:	11530

Tank Info:

Facility ID:	07153
Facility Reference #:	10977
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	1
Tank Key:	20328
Year Installed:	60
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Fill:	PUMPED
Date Removed:	061102
Tank ID:	17
Tank Key:	43431
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702
Tank ID:	18
Tank Key:	43432
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000012000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061002

Tank ID:	19
Tank Key:	43433
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	2
Tank Key:	20329
Year Installed:	60
Substance:	#4 FUEL OIL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000010000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	061202

Tank ID:	20
Tank Key:	43434
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	21
Tank Key:	43435
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	22
Tank Key:	43436
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	24
Tank Key:	43602
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	011702

Tank ID:	25
Tank Key:	43919
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	26
Tank Key:	43920
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	061302

Tank ID:	3
Tank Key:	43417
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	4
Tank Key:	43418
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	5
Tank Key:	43419
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	6
Tank Key:	43420
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

Tank ID:	7
Tank Key:	43421
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	060702

---

55 **CANADA DRY BOTTLING CO** **NY LTANKS** **U003537593**
NNW **135 BAYLIS RD** **NY UST** **N/A**
1/8-1/4 **MELVILLE, NY 11747** **NY AST**
0.174 mi.
918 ft.

Relative:
Lower

Actual:
103 ft.

LTANKS:

Site ID:	159315
Spill Number/Closed Date:	9700559 / 1999-04-14
Spill Date:	1997-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F

CANADA DRY BOTTLING CO (Continued) **U003537593**

Referred To:	Not reported
Reported to Dept:	1997-04-11
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-11
Spill Record Last Update:	1999-04-16
Spiller Name:	FRANK DAY
Spiller Company:	CANADA DRY CO
Spiller Address:	135 BAYLIS ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	999
Spiller Contact:	FRANK DAY
Spiller Phone:	(914) 636-5033
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	134569
DEC Memo:	""
Remarks:	""

Material:

Site ID:	159315
Operable Unit ID:	1046856
Operable Unit:	01
Material ID:	337153
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	159315
Spill Tank Test:	1545075
Tank Number:	1
Tank Size:	1500
Test Method:	01
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Petro-Tite/Petro Comp

Site ID:	203799
Spill Number/Closed Date:	9304069 / 1994-02-10
Spill Date:	1993-06-30
Spill Cause:	Tank Test Failure

CANADA DRY BOTTLING CO (Continued) **U003537593**

Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-02-10
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1993-06-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-02
Spill Record Last Update:	2014-08-19
Spiller Name:	ROBERT NOBLE
Spiller Company:	CANADA DRY BOTTLING
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	134569
DEC Memo:	"WILL EIR PER STEWART PASTOR 7/6/93 PATCH FOUND ON TOP OF TANK. TANK BEING PUMPED WILL BE REMOVED TOMORROW, TANK REMOVED 7/7/93 < 1/4 YD OF CONTAMINATION FOUND DISPOSED OF WITH TANK SLUDGE. NO FURTHER CONTAMINATION DETECTED PERMISSION GIVEN TO BACKFILL NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"3K FAILED GROSS LEAK, LEWIS TESTER"

Material:

Site ID:	203799
Operable Unit ID:	985798
Operable Unit:	01
Material ID:	397599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	203799
Spill Tank Test:	1541718
Tank Number:	Not reported
Tank Size:	0
Test Method:	00

CANADA DRY BOTTLING CO (Continued) **U003537593**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 06840
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 06840
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: MELVILLE BEVERAGE PARTNERS
Storage Owner Address: 135 BAYLIS RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 06840
Facility Reference #: 00092
Official Use: Removed Tank. 93
Township: HUNTINGTON
Tax Map No: 0400 268.00 002 015.001
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 19244
Installed: 65
Capacity: 0000003000
Substance: #2 FUEL OIL
Date Removed: 070793
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 0000003000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported

CANADA DRY BOTTLING CO (Continued) **U003537593**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	070793
Year Installed:	65
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	19246
Installed:	85
Capacity:	0000001500
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000001500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	RECORDS AS OF 09/10/2013

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	06840
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	06840
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported

CANADA DRY BOTTLING CO (Continued) **U003537593**

Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	MELVILLE BEVERAGE PARTNERS
Storage Owner Address:	135 BAYLIS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	06840
Facility Reference #:	00092
Township:	HUNTINGTON
Tax Map No:	0400
Region:	SUFFOLK
Tank ID:	2
Tank Key:	19245
Year Installed:	87
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 92
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

N56 **PARAGON ENTERPRISES** **NY UST** **U003537826**
NNW **125 BAYLIS RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.200 mi.
1056 ft. **Site 1 of 2 in cluster N**

Relative:
Higher

Actual:
108 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08235
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

PARAGON ENTERPRISES (Continued) **U003537826**

Facility Info:

Site Ref#:	08235
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	PARAGON ENTERPRISES
Storage Owner Address:	300 EXECUTIVE DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08235
Facility Reference #:	04122
Official Use:	Exempt from Suffolk County Art 12 Regulation
Township:	HUNTINGTON
Tax Map No:	0400 268.00 002 017.002
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	23826
Installed:	83
Capacity:	0000000550
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	83
Description of drop records:	RECORDS AS OF 09/10/2013

N57 **OFFICE BUILDING** **NY LTANKS** **S105135247**
NNW **125 BAYLIS ROAD** **N/A**
1/8-1/4 **MELVILLE, NY**
0.200 mi.
1056 ft. **Site 2 of 2 in cluster N**

Relative:
Higher

Actual:
108 ft.

LTANKS:

Site ID:	127634
Spill Number/Closed Date:	0104376 / 2001-09-07
Spill Date:	2001-07-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	2001-07-24
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-24
Spill Record Last Update:	2009-11-03
Spiller Name:	JIM DONELAN
Spiller Company:	OFFICE BUILDING
Spiller Address:	125 BAYLIS ROAD
Spiller City,St,Zip:	MELVILLE, NY -
Spiller County:	001
Spiller Contact:	JIM DONELAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	110188
DEC Memo:	"7/24/01 16:15 TELECON WG TO MR DONELAN FROM PROTEST ENT, AN UNUSED SUPPLY LINE CAUSED THE TANK FAILURE, NO CLEANUP HAS BEEN SCHEDULED YET AT THIS TIME, PER MIKE FLYNN, EASTERN ENV SOLUTIONS, 631-325-2700, REPAIRS MADE TANK PASSED RETEST TANK REMOVED, NO CONTAMINATED SOIL FOUND"
Remarks:	"tank failed the test 550gal diesel fuel tank"

Material:

Tank Test:

Site ID:	127634
Spill Tank Test:	1526479
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported

OFFICE BUILDING (Continued) **S105135247**

Test Method: Horner EZ Check I or II

58
NW
1/8-1/4
0.220 mi.
1160 ft.

NY TEL CO **NY LTANKS** **S100177468**
84 DURYEA ROAD **N/A**
MELVILLE, NY

Relative:
Lower

Actual:
104 ft.

LTANKS:

Site ID:	198367
Spill Number/Closed Date:	9109715 / 1992-01-10
Spill Date:	1991-12-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-01-10
Cleanup Meets Standard:	True
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1991-12-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-13
Spill Record Last Update:	1992-01-10
Spiller Name:	Not reported
Spiller Company:	NY TEL CO
Spiller Address:	100 GARDEN CITY PLAZA
Spiller City,St,Zip:	GARDEN CITYKNY, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	165093
DEC Memo:	""
Remarks:	"2K FAILED AT -0.417, GASOLINE INSTALLATIONS TESTER"

Material:

Site ID:	198367
Operable Unit ID:	963478
Operable Unit:	01
Material ID:	418309
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

NY TEL CO (Continued) **S100177468**

Oxygenate: Not reported

Tank Test:
Site ID: 198367
Spill Tank Test: 1539412
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

O59 **LABORATORY CORP OF AMERICA** **NY UST** **U003960936**
SSE **170 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.221 mi.
1166 ft. **Site 1 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 00450
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 00450
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: LCS REALTY C/O FINKELSTEIN REALTY
Storage Owner Address: 450 JERICHO TNPK SUITE 207
Storage Owner City: MINEOLA
Storage Owner State: NY
Storage Owner Zip: 11501

Tank Info:
Facility ID: 00450
Facility Reference #: 10343
Official Use: Removed Tank. 02
Township: BABYLON
Tax Map No: 0100 006.00 001 002.000
Region: SUFFOLK
Permit to Operate: 112091

Tank ID: 1
Tank Key: 1559
Installed: 91
Capacity: 0000000250
Substance: INDUSTRIAL WASTE
Date Removed: 011102

LABORATORY CORP OF AMERICA (Continued) **U003960936**

Construction:	Not reported
Dispenser:	OTHER
Fill Type:	OTHER
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000000250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	011102
Year Installed:	91
Description of drop records:	RECORDS AS OF 09/10/2013

O60 **ROCHE BIOMEDICAL LABS INC** **RCRA NonGen / NLR** **1000994425**
SSE **170 FINN CT** **FINDS** **NYD986899219**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.221 mi. **NY MANIFEST**
1166 ft. **Site 2 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROCHE BIOMEDICAL LABS INC
Facility address:	170 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYD986899219
Mailing address:	NORTHERN BLVD GREAT NECK, NY 11021
Contact:	Not reported
Contact address:	NORTHERN BLVD GREAT NECK, NY 11021
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROCHE BIOMEDICAL
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ROCHE BIOMEDICAL
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 04/18/1995
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 04/05/1990
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U122
. Waste name: FORMALDEHYDE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/04/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004356740

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000994425
Registry ID: 110004356740
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004356740

NY MANIFEST:
Country: USA
EPA ID: NYD986899219
Facility Status: Not reported
Location Address 1: 560 NORTHERN BOULEVARD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: GREAT NECK
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

NY MANIFEST:

EPAID:	NYD986899219
Mailing Name:	ROCHE LABS
Mailing Contact:	BETTY DECKER
Mailing Address 1:	560 NORTHERN BOULEVARD
Mailing Address 2:	Not reported
Mailing City:	GREAT NECK
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164878600

NY MANIFEST:

Document ID:	NYB2204145
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	MM5929
Trans2 State ID:	Not reported
Generator Ship Date:	07/18/1990
Trans1 Recv Date:	07/18/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/18/1990
Part A Recv Date:	08/31/1990
Part B Recv Date:	08/31/1990
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NYB2136015
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	NL6934
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/1990
Trans1 Recv Date:	09/12/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/12/1990
Part A Recv Date:	09/27/1990
Part B Recv Date:	10/23/1990
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Quantity:	00060
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0754976
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/1991
Trans1 Recv Date:	10/24/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/24/1991
Part A Recv Date:	/ /
Part B Recv Date:	11/12/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00280
Units:	P - Pounds
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00345
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NYB7650783
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	HM3506
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/1996
Trans1 Recv Date:	04/15/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/15/1996
Part A Recv Date:	04/24/1996
Part B Recv Date:	04/24/1996
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	U239 - XYLENE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00041
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	090
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	NJA1164140
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	08/13/1991
Trans1 Recv Date:	08/13/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/13/1991
Part A Recv Date:	08/30/1991
Part B Recv Date:	08/26/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00230

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0754957
Manifest Status:	K
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/1991
Trans1 Recv Date:	05/10/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/10/1991
Part A Recv Date:	06/26/1991
Part B Recv Date:	06/06/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00240
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00230
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Specific Gravity:	100
Document ID:	NJA0980990
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/1991
Trans1 Recv Date:	07/24/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/24/1991
Part A Recv Date:	08/01/1991
Part B Recv Date:	08/09/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA1164291
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/1991
Trans1 Recv Date:	06/12/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/12/1991
Part A Recv Date:	06/21/1991
Part B Recv Date:	06/29/1991
Generator EPA ID:	NYD986899219

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00160
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA1040991
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/1991
Trans1 Recv Date:	02/20/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/20/1991
Part A Recv Date:	03/04/1991
Part B Recv Date:	03/08/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00240
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00230
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0755013
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	11/25/1991
Trans1 Recv Date:	11/25/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/25/1991
Part A Recv Date:	/ /
Part B Recv Date:	12/06/1991
Generator EPA ID:	NYD986899219
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00320
Units:	P - Pounds
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Click this hyperlink while viewing on your computer to access
5 additional NY_MANIFEST: record(s) in the EDR Site Report.

O61 **ROCHE BIOMEDICAL LABS INC** **RCRA NonGen / NLR** **1000203200**
SSE **170 FINN CT** **NY MANIFEST** **NYD047645700**
1/8-1/4 **FARMINGDALE, NY 11735**
0.221 mi.
1166 ft. **Site 3 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROCHE BIOMEDICAL LABS INC
Facility address:	170 FINN CT FARMINGDALE, NY 117351107
EPA ID:	NYD047645700
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	Not reported
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROCHE BIOMEDICAL LABS INC
Owner/operator address:	231 MAPLE AVE BURLINGTON, NC 27215
Owner/operator country:	US
Owner/operator telephone:	(800) 334-5161
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ROCHE BIOMEDICAL LABS INC
Owner/operator address:	231 MAPLE AVE BURLINGTON, NC 27215
Owner/operator country:	US
Owner/operator telephone:	(800) 334-5161
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 12/09/1991
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD047645700
Facility Status: Not reported
Location Address 1: 170 FINN COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD047645700
Mailing Name:	ROCHE BIOMEDICAL
Mailing Contact:	DANILO VELASCO
Mailing Address 1:	170 FINN COURT
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5167528311

NY MANIFEST:

Document ID:	NJA0981187
Manifest Status:	K
seq:	Not reported
Year:	1992
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	05/11/1992
Trans1 Recv Date:	05/11/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/11/1992
Part A Recv Date:	/ /
Part B Recv Date:	06/10/1992
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0981263
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/1992
Trans1 Recv Date:	08/18/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/18/1992
Part A Recv Date:	09/09/1992
Part B Recv Date:	09/03/1992
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0755047
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	03/02/1992
Trans1 Recv Date:	03/02/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/02/1992
Part A Recv Date:	03/20/1992

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Part B Recv Date:	03/25/1992
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	U122 - FORMALDEHYDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00230
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0145091
Manifest Status:	C
seq:	Not reported
Year:	1986
Trans1 State ID:	S-10340DE
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1986
Trans1 Recv Date:	12/30/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1986
Part A Recv Date:	01/13/1987
Part B Recv Date:	01/14/1987
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD980773006
Trans2 EPA ID:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NJA0755317
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	03/01/1994
Trans1 Recv Date:	03/01/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/01/1994
Part A Recv Date:	/ /
Part B Recv Date:	03/16/1994
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00080
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0981410
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/1993
Trans1 Recv Date:	03/11/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/11/1993
Part A Recv Date:	04/05/1993
Part B Recv Date:	03/26/1993
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0981370
Manifest Status:	C
seq:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Year:	1993
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1993
Trans1 Recv Date:	01/22/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/22/1993
Part A Recv Date:	02/01/1993
Part B Recv Date:	02/10/1993
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0981427
Manifest Status:	K
seq:	Not reported
Year:	1993
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/1993
Trans1 Recv Date:	04/22/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/22/1993
Part A Recv Date:	05/04/1993
Part B Recv Date:	05/18/1993
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0755103
Manifest Status:	K
seq:	Not reported
Year:	1993
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	07/01/1993
Trans1 Recv Date:	07/01/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/01/1993
Part A Recv Date:	07/21/1993
Part B Recv Date:	07/29/1993
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA1663545
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	09/08/1993
Trans1 Recv Date:	09/08/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/09/1993
Part A Recv Date:	10/25/1993
Part B Recv Date:	10/01/1993
Generator EPA ID:	NYD047645700
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

O62 **ARTEK** **NY UST** **U003843265**
SSE **170 FINN CT** **N/A**
1/8-1/4 **BABYLON, NY 11702**
0.221 mi.
1166 ft. **Site 4 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	02248
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	02248
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	Not reported
Storage Owner Address:	Not reported
Storage Owner City:	Not reported
Storage Owner State:	Not reported
Storage Owner Zip:	Not reported

Tank Info:

Facility ID:	02248
Facility Reference #:	06071
Official Use:	Removed Tank. 88
Township:	BABYLON
Tax Map No:	0100 006.00 001 002.000
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	5509
Installed:	Not reported
Capacity:	0000003000
Substance:	#2 FUEL OIL
Date Removed:	010188
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

ARTEK (Continued) **U003843265**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010188
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

63
SSW
1/8-1/4
0.222 mi.
1170 ft.

FALA INC **NY UST** **U003537830**
70 MARCUS DR **N/A**
MELVILLE, NY 11747

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08240
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	08240
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	S L J R ASSOCIATES
Storage Owner Address:	70 MARCUS DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08240
Facility Reference #:	04146
Official Use:	Removed Tank. 95
Township:	HUNTINGTON
Tax Map No:	0400 267.00 002 014.000
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	23830
Installed:	77
Capacity:	0000004000
Substance:	#2 FUEL OIL
Date Removed:	092695
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported

FALA INC (Continued) **U003537830**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	092695
Year Installed:	77
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	23831
Installed:	Not reported
Capacity:	0000005000
Substance:	#2 FUEL OIL
Date Removed:	031797
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000005000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	031797
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

64
West
1/8-1/4
0.228 mi.
1202 ft.

WALAEL RESIDENCE
95 RULAND PLACE
MELVILLE, NY

NY LTANKS **S118953863**
N/A

Relative:
Lower

Actual:
100 ft.

LTANKS:

Site ID:	240480
Spill Number/Closed Date:	9903643 / 1999-09-28
Spill Date:	1999-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1999-06-29
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-29
Spill Record Last Update:	2010-06-22
Spiller Name:	RICHARD WALAEL
Spiller Company:	WALAEL RESIDENCE
Spiller Address:	95 RULAND PLACE
Spiller City,St,Zip:	MELVILLE, NY 11747-
Spiller County:	001
Spiller Contact:	RICHARD WALAEL
Spiller Phone:	(516) 694-3851
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	197767
DEC Memo:	"6/29/99 17:23 TELECON WITH RICHARD WALAEL, SYSTEM TEST FAILURE, IS LOOKING TO SELL PROPERTY, WILL EXCAVATE TANK HIMSELF, UNSURE IF REPAIR OR REMOVE TANK REMOVED, NO CONTAMINATION FOUND"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. TANK TO BE EXPOSED AND RETESTED. NO CALL BACK REQUESTED."

Material:

Site ID:	240480
Operable Unit ID:	1082569
Operable Unit:	01
Material ID:	563504
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

WALAEL RESIDENCE (Continued) **S118953863**

Tank Test:
- Site ID: 240480
- Spill Tank Test: 1547324
- Tank Number: 1
- Tank Size: 1000
- Test Method: 03
- Leak Rate: .07
- Gross Fail: Not reported
- Modified By: Spills
- Last Modified: Not reported
- Test Method: Horner EZ Check I or II

O65 **NATIONAL ENVIRONMENTAL CONTROL N E** **NY UST** **U003842869**
SSE **150 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.228 mi.
1206 ft. **Site 5 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:
- Region: SUFFOLK
- Site Ref#: 01116
- Status: Not reported
- Site Type: Not reported
- Operating Permit Expires: Not reported
- Owner/Storage Information: Not reported

Facility Info:
- Site Ref#: 01116
- Billing Contact: Not reported
- Billing Address: Not reported
- Billing Address: Not reported
- Billing State: Not reported
- Billing Zip: Not reported
- Storage Owner: SUTTON & EDWARDS
- Storage Owner Address: 1983 MARCUS AVE
- Storage Owner City: LAKE SUCCESS
- Storage Owner State: NY
- Storage Owner Zip: 11042

Tank Info:
- Facility ID: 01116
- Facility Reference #: 01989
- Official Use: Removed Tank. 00
- Township: BABYLON
- Tax Map No: 0100 006.00 001 003.000
- Region: SUFFOLK
- Permit to Operate: Not reported

- Tank ID: 1
- Tank Key: 3154
- Installed: 75
- Capacity: 0000003000
- Substance: #2 FUEL OIL
- Date Removed: 032400
- Construction: STEEL
- Dispenser: SUCTION

NATIONAL ENVIRONMENTAL CONTROL N E (Continued) **U003842869**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	032400
Year Installed:	75
Description of drop records:	RECORDS AS OF 09/10/2013

O66 **PRECIPART CORPORATION** **RCRA-SQG** **1004761475**
SSE **150 FINN COURT** **FINDS** **NYR000087247**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.228 mi. **NY MANIFEST**
1206 ft. **Site 6 of 11 in cluster O** **RI MANIFEST**

Relative:
Lower

Actual:
101 ft.

RCRA-SQG:

Date form received by agency:	12/30/2014
Facility name:	PRECIPART CORPORATION
Facility address:	150 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYR000087247
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	DANIEL RUDOLF
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	(631) 694-3100
Contact email:	DRUDOLF@PRECIPART.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DAVID I ROSENBERG
Owner/operator address:	LEXINGTON AVE11TH FL NEW YORK, NY 10022

PRECIPART CORPORATION (Continued) **1004761475**

Owner/operator country: US
Owner/operator telephone: (212) 409-2222
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/01/2013
Owner/Op end date: Not reported

Owner/operator name: PRECIPART CORPORATION
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

PRECIPART CORPORATION (Continued) **1004761475**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 02/18/2014
Site name: PRECIPART CORPORATION
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

PRECIPART CORPORATION (Continued) **1004761475**

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: PRECIPART CORP
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: PRECIPART CORP
Classification: Small Quantity Generator

Date form received by agency: 02/26/2003
Site name: PRECIPART CORP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 06/12/2000
Site name: SUTTON & EDWARDS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

PRECIPART CORPORATION (Continued) **1004761475**

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	Generators - Manifest
Date violation determined:	10/23/2008
Date achieved compliance:	01/29/2009
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/25/2008
Enf. disposition status:	Action Satisfied (Case Closed)
Enf. disp. status date:	01/29/2009
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	Generators - Pre-transport
Date violation determined:	10/23/2008
Date achieved compliance:	01/23/2009
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/25/2008
Enf. disposition status:	Action Satisfied (Case Closed)
Enf. disp. status date:	01/29/2009
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	State Statute or Regulation
Date violation determined:	10/23/2008
Date achieved compliance:	10/31/2008
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/25/2008
Enf. disposition status:	Action Satisfied (Case Closed)
Enf. disp. status date:	01/29/2009
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	Generators - Pre-transport
Date violation determined:	10/23/2008
Date achieved compliance:	10/31/2008
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/25/2008
Enf. disposition status:	Action Satisfied (Case Closed)
Enf. disp. status date:	01/29/2009
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 10/23/2008
Date achieved compliance: 10/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 01/23/2009
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 10/30/2008
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 10/31/2008
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 01/29/2009
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 10/31/2008
Evaluation lead agency: State

FINDS:

Registry ID: 110004562875

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the

PRECIPART CORPORATION (Continued) **1004761475**

discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004761475
Registry ID:	110004562875
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004562875

NY MANIFEST:

Country:	USA
EPA ID:	NYR000087247
Facility Status:	Not reported
Location Address 1:	150 FINN COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000087247
Mailing Name:	PRECIPART CORP
Mailing Contact:	MICHAEL MANUELLA
Mailing Address 1:	150 FINN COURT
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6314723400

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/09/2011
Trans1 Recv Date:	05/09/2011
Trans2 Recv Date:	05/12/2011

PRECIPART CORPORATION (Continued) **1004761475**

TSD Site Recv Date:	05/14/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	002593683SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	440.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/10/2011
Trans1 Recv Date:	10/10/2011
Trans2 Recv Date:	10/14/2011
TSD Site Recv Date:	10/15/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	002593983SKS

PRECIPART CORPORATION (Continued) **1004761475**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2250.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/22/2011
Trans1 Recv Date:	03/22/2011
Trans2 Recv Date:	03/29/2011
TSD Site Recv Date:	04/01/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	003856377FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1320.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2011
Trans1 Recv Date:	10/10/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID084802842
TSDF ID 2:	Not reported
Manifest Tracking Number:	002592246SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	900.0

PRECIPART CORPORATION (Continued) **1004761475**

Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Waste Code:	D040
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	09/05/2008
Trans1 Recv Date:	09/05/2008
Trans2 Recv Date:	09/11/2008
TSD Site Recv Date:	09/12/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	001307137SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2008
Trans1 Recv Date:	08/26/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	003535740JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976

PRECIPART CORPORATION (Continued) **1004761475**

Generator Ship Date:	06/25/2008
Trans1 Recv Date:	06/25/2008
Trans2 Recv Date:	07/14/2008
TSD Site Recv Date:	07/15/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	000125167SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	912.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2008
Trans1 Recv Date:	08/26/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	003535740JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/21/2008
Trans1 Recv Date:	03/21/2008
Trans2 Recv Date:	04/01/2008
TSD Site Recv Date:	04/02/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	000088707SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

PRECIPART CORPORATION (Continued) **1004761475**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	04/10/2012
Trans1 Recv Date:	04/10/2012
Trans2 Recv Date:	04/17/2012
TSD Site Recv Date:	04/18/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	002595096SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1400.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	F005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
127 additional NY_MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

EPA Id:	NYR000087247
Manifest Document Number:	002592282SKS
GEN Cert Date:	12/27/2011
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
TSDF Date:	1/4/2012
Transporter 2 Id:	NJD071629976
Transporter 2 Name:	1/4/2012
Transporter Receipt Date:	12/27/2011
Number Of Containers:	2
Container Type:	DM
Waste Code1:	D040
Waste Code2:	F002
Waste Code3:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported

Details:

EPA ID:	NYR000087247
Manifest Docket Number:	002592282SKS
Waste Description:	TRICHLOROETHYLENE
Quantity:	500
WT/Vol Units:	P
Item Number:	1
Transporter Name:	SAFETY KLEEN
Transporter EPA ID:	TXR000050930
GEN Cert Date:	12/27/2011
Transporter Receipt Date:	12/27/2011
Transporter 2 Receipt Date:	1/4/2012
TSDF Receipt Date:	1/4/2012
Transporter 2 ID:	NJD071629976

O67 **MORRIS BROTHERS AUTO & TRUCK PARTS** **NY Spills** **S104646291**
SSE **150 FINN COURT** **NY MANIFEST** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.228 mi.
1206 ft. **Site 7 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

SPILLS:

Facility ID:	9706548
Facility Type:	ER
DER Facility ID:	248999
Site ID:	308312
DEC Region:	1
Spill Date:	1997-09-01
Spill Number/Closed Date:	9706548 / 1997-09-03
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. (Highly Improbable)
SWIS:	3024
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1997-09-01
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-01
Spill Record Last Update:	2011-09-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	150 FINN COURT
Spiller City,St,Zip:	FARMINGDALE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE NO RESPONSE BY SPILL UNIT. ECO'S NOTIFIED."
Remarks:	"INVESTIGATOR RICHARD J MAGGIO FROM TARRYTOWN TOLD CALLER TO CALL ANYTIME HE NOTICED SUSPICIOUS ACTIVITY. SUBJECTS ARE CURRENTLY TRANSFERRING BAGS LABELED ASBESTOS - DANGEROUS FROM WAREHOUSE TO TRUCKS. WAREHOUSE IS OVERFLOWING WITH ASBESTOS. IT'S HANGING OUT OF DOORS. OFFICES ARE CLOSED FOR THE DAY. CALLER REQUEST A CALL BACK. SUFFOLK COUNTY POLICE NOTIFIED ALSO."

Material:

Site ID:	308312
Operable Unit ID:	1052766
Operable Unit:	01
Material ID:	332127
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	.00
Units:	Gallons

MORRIS BROTHERS AUTO & TRUCK PARTS (Continued) **S104646291**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

NY MANIFEST:
Country: USA
EPA ID: NYP000786608
Facility Status: Not reported
Location Address 1: 150 FINN COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000786608
Mailing Name: MORRIS BROTHERS AUTO & TRUCK PARTS
Mailing Contact: MORTIMER ROSENBERG
Mailing Address 1: 150 FINN COURT
Mailing Address 2: Not reported
Mailing City: FARMINGDALE
Mailing State: NY
Mailing Zip: 11735
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5166949161

NY MANIFEST:
Document ID: NYO4066011
Manifest Status: C
seq: Not reported
Year: 1984
Trans1 State ID: 1A-042
Trans2 State ID: Not reported
Generator Ship Date: 06/20/1984
Trans1 Recv Date: 06/20/1984
Trans2 Recv Date: / /
TSD Site Recv Date: 06/20/1984
Part A Recv Date: 06/27/1984
Part B Recv Date: 07/03/1984
Generator EPA ID: NYP000786608
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported

MORRIS BROTHERS AUTO & TRUCK PARTS (Continued) **S104646291**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	Not reported
Specific Gravity:	100

Document ID:	NYO4066119
Manifest Status:	C
seq:	Not reported
Year:	1984
Trans1 State ID:	1A-042
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/1984
Trans1 Recv Date:	06/20/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/21/1984
Part A Recv Date:	06/27/1984
Part B Recv Date:	07/03/1984
Generator EPA ID:	NYP000786608
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00650
Units:	G - Gallons (liquids only)* (8.3 pounds)

MORRIS BROTHERS AUTO & TRUCK PARTS (Continued) **S104646291**

Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Document ID:	NYO4147452
Manifest Status:	C
seq:	Not reported
Year:	1984
Trans1 State ID:	1A-042
Trans2 State ID:	Not reported
Generator Ship Date:	09/04/1984
Trans1 Recv Date:	09/04/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/04/1984
Part A Recv Date:	09/07/1984
Part B Recv Date:	09/17/1984
Generator EPA ID:	NYP000786608
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100

O68 **PRECIPART CORP** **PA MANIFEST** **S110049509**
SSE **150 FINN COURT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.228 mi.
1206 ft. **Site 8 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

Manifest Details:

Year:	2008
Manifest Number:	003535740JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000087247
Generator Date:	08/26/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	631-694-3100
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	003535740JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000087247
Generator Date:	08/26/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	631-694-3100
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported

PRECIPART CORP (Continued) **S110049509**

Date TSP Sig: Not reported

P69 **MIP INC** **NY AST** **A100196428**
SSE **130 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.229 mi.
1211 ft. **Site 1 of 4 in cluster P**

Relative:
Lower

Actual:
101 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	00431
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00431
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	CWB REALTY CO
Storage Owner Address:	130 FINN CT
Storage Owner City:	EAST FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00431
Facility Reference #:	10319
Township:	BABYLON
Tax Map No:	0100
Region:	SUFFOLK
Tank ID:	1
Tank Key:	1461
Year Installed:	85
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 86
Permit to Operate:	032685
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000023760
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

MIP INC (Continued) **A100196428**

Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: GRAVITY
Date Removed: 010186

P70 **MANUFACTURERS INDEXING PRODUCT** **RCRA NonGen / NLR** **1001090306**
SSE **130 FINN CT** **NY MANIFEST** **NYR000021436**
1/8-1/4 **EAST FARMINGDALE, NY 11735**
0.229 mi.
1211 ft. **Site 2 of 4 in cluster P**

Relative:
Lower

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MANUFACTURERS INDEXING PRODUCT
Facility address: 130 FINN CT
EAST FARMINGDALE, NY 11735
EPA ID: NYR000021436
Mailing address: FINN CT
EAST FARMINGDALE, NY 11735
Contact: Not reported
Contact address: FINN CT
EAST FARMINGDALE, NY 11735
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MANUFACTURERS INDEXING PRODUCT
Owner/operator address: 130 FINN CT
EAST FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: (516) 249-1272
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MANUFACTURERS INDEXING PRODUCT
Owner/operator address: 130 FINN CT
EAST FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: (516) 249-1272
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

MANUFACTURERS INDEXING PRODUCT (Continued) **1001090306**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Not a generator, verified

Date form received by agency: 03/25/1996
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000021436
Facility Status: Not reported
Location Address 1: 130 FINN CT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: E FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000021436
Mailing Name: MIP MANUFACTURES
Mailing Contact: MIP MANUFACTURES
Mailing Address 1: 130 FINN CT
Mailing Address 2: Not reported
Mailing City: E FARMINGDALE
Mailing State: NY

MANUFACTURERS INDEXING PRODUCT (Continued) **1001090306**

Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162491272

NY MANIFEST:

Document ID:	NJA2239851
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	04/04/1996
Trans1 Recv Date:	04/04/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/09/1996
Part A Recv Date:	04/11/1996
Part B Recv Date:	04/24/1996
Generator EPA ID:	NYR000021436
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00455
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

P71 **PRECIPART CORP** **RCRA-SQG** **1004762133**
SSE **100 FINN CT** **FINDS** **NYR000093864**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.230 mi. **NY MANIFEST**
1216 ft. **Site 3 of 4 in cluster P**

Relative:
Lower

Actual:
101 ft.

RCRA-SQG:

Date form received by agency:	06/25/2014
Facility name:	PRECIPART CORP
Facility address:	100 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYR000093864
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	DANIEL RUDOLF
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	(631) 694-3100
Contact email:	DRUDOLF@PRECIPART.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MCS REALTY CO-FINKELSTEIN REALTY
Owner/operator address:	450 JERICHO TNPK MINEOLA, NY 11504
Owner/operator country:	US
Owner/operator telephone:	(516) 747-5544
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	MCS REALTY LLC/CUSHMAN & WAKEFIELD INC
Owner/operator address:	OLD COUNTY RD 4TH FL MINEOLA, NY 11501
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/21/2002
Owner/Op end date:	Not reported

Owner/operator name:	MCS REALTY CO-FINKELSTEIN REALTY
Owner/operator address:	450 JERICHO TNPK MINEOLA, NY 11504
Owner/operator country:	US
Owner/operator telephone:	(516) 747-5544
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

PRECIPART CORP (Continued) **1004762133**

Owner/operator name: PRECIPART CORPORATION
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

Historical Generators:
Date form received by agency: 01/01/2007
Site name: PRECIPART CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: PRECIPART CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/05/2001
Site name: PRECIPART CORP

PRECIPART CORP (Continued) **1004762133**

Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 10/06/2008
Date achieved compliance: 10/23/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 11/25/2008
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/06/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 10/23/2008
Evaluation lead agency: State

FINDS:

Registry ID: 110004566979

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource

PRECIPART CORP (Continued) **1004762133**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762133
Registry ID:	110004566979
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004566979

NY MANIFEST:

Country:	USA
EPA ID:	NYR000093864
Facility Status:	Not reported
Location Address 1:	100 FINN CT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000093864
Mailing Name:	PRECIPART - NORTH
Mailing Contact:	DANIEL RUDOLF
Mailing Address 1:	100 FINN CT
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6316943100

NY MANIFEST:

Document ID:	NYC7127728
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	NY13717AT
Trans2 State ID:	NJ044
Generator Ship Date:	06/20/2003
Trans1 Recv Date:	06/20/2003
Trans2 Recv Date:	06/25/2003
TSD Site Recv Date:	06/27/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930

PRECIPART CORP (Continued) **1004762133**

Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00394
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	TXA0662837
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	87109
Trans2 State ID:	41038
Generator Ship Date:	05/13/2003
Trans1 Recv Date:	05/13/2003
Trans2 Recv Date:	05/23/2003
TSD Site Recv Date:	05/28/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	OKD981588791
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported

PRECIPART CORP (Continued) **1004762133**

Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00511
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	TXA0662840
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	87109
Trans2 State ID:	40349
Generator Ship Date:	06/20/2003
Trans1 Recv Date:	06/20/2003
Trans2 Recv Date:	07/01/2003
TSD Site Recv Date:	07/03/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00513
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NYC6712525
Manifest Status:	Not reported

PRECIPART CORP (Continued) **1004762133**

seq:	01
Year:	2003
Trans1 State ID:	NYES9459
Trans2 State ID:	T365DANJ
Generator Ship Date:	02/21/2003
Trans1 Recv Date:	02/21/2003
Trans2 Recv Date:	03/03/2003
TSD Site Recv Date:	03/05/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00788
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Document ID:	NYC6847830
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	NYES9459
Trans2 State ID:	T365DANJ
Generator Ship Date:	02/21/2003
Trans1 Recv Date:	02/21/2003
Trans2 Recv Date:	03/03/2003
TSD Site Recv Date:	03/05/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported

PRECIPART CORP (Continued) **1004762133**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00916
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Document ID:	NYC6847874
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	NY13717AT
Trans2 State ID:	T474GLNJ
Generator Ship Date:	05/13/2003
Trans1 Recv Date:	05/13/2003
Trans2 Recv Date:	05/20/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported

PRECIPART CORP (Continued) **1004762133**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01320
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NYC6847907
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	NY13717AT
Trans2 State ID:	T474GLNJ
Generator Ship Date:	05/13/2003
Trans1 Recv Date:	05/13/2003
Trans2 Recv Date:	05/20/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01182
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA4065128
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	S5811

PRECIPART CORP (Continued) **1004762133**

Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2002
Trans1 Recv Date:	08/12/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA4065801
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	10/18/2002
Trans1 Recv Date:	10/18/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/18/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

PRECIPART CORP (Continued) **1004762133**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA4031238
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	S2265
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/2002
Trans1 Recv Date:	01/22/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/22/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093864
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

PRECIPART CORP (Continued) **1004762133**

Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
7 additional NY_MANIFEST: record(s) in the EDR Site Report.

P72 **MAYTAG BLDG** **NY UST** **U003960871**
SSE **100 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.230 mi.
1216 ft. **Site 4 of 4 in cluster P**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	00363
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00363
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	MAYTAG BLDG
Storage Owner Address:	100 FINN CT
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00363
Facility Reference #:	10154
Official Use:	Abandoned, approved by plan review, awaiting construction for compliance inspection. 86
Township:	BABYLON
Tax Map No:	0100 006.00 001 006.000
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	1122
Installed:	60
Capacity:	0000003000
Substance:	GASOLINE
Date Removed:	010186
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported

MAYTAG BLDG (Continued) **U003960871**

Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	010186
Year Installed:	60
Description of drop records:	RECORDS AS OF 09/10/2013

Q73 **FALA DIRECT MARKETING** **NY UST** **U003537613**
SW **75 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.230 mi.
1216 ft. **Site 1 of 2 in cluster Q**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08603
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	08603
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	FALA DIRECT MARKETING
Storage Owner Address:	75 MARCUS DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08603
Facility Reference #:	08695
Official Use:	Removed Tank. 88
Township:	HUNTINGTON
Tax Map No:	0400 267.00 002 021.000
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1

FALA DIRECT MARKETING (Continued) **U003537613**

Tank Key:	24290
Installed:	Not reported
Capacity:	0000005000
Substance:	#2 FUEL OIL
Date Removed:	010188
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000005000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010188
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	2
Tank Key:	24291
Installed:	88
Capacity:	0000004000
Substance:	#2 FUEL OIL
Date Removed:	021500
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000004000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

FALA DIRECT MARKETING (Continued) **U003537613**

Fill:	PUMPED
Date Removed:	021500
Year Installed:	88
Description of drop records:	RECORDS AS OF 09/10/2013

Q74 **FALA CCG INC** **RCRA-SQG** **1001460264**
SW **75 MARCUS DR** **NY LTANKS** **NYR000067322**
1/8-1/4 **MELVILLE, NY 11747** **FINDS**
0.230 mi. **ECHO**
1216 ft. **Site 2 of 2 in cluster Q** **NJ MANIFEST**
NY MANIFEST

Relative:
Lower

Actual:
102 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	FALA CCG INC
Facility address:	75 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYR000067322
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	HARRY BELECHTO
Contact address:	MARCUS DR MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(631) 391-0203
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	75 MARCUS CORP
Owner/operator address:	75 MARCUS DR MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 391-0604
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	75 MARCUS CORP
Owner/operator address:	75 MARCUS DR MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	(516) 391-0604
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

FALA CCG INC (Continued) **1001460264**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FALA CCG INC
Classification: Small Quantity Generator

Date form received by agency: 02/26/2002
Site name: FALA CCG INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: FALA CCG INC
Classification: Large Quantity Generator

Date form received by agency: 10/06/1999
Site name: FALA GRAPHICS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: SR - 373-3.3(g)(1)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

FALA CCG INC (Continued) **1001460264**

Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(iii)(d)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-1.1(d)(1)(iv)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(i)(a)(2)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.9(d)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

FALA CCG INC (Continued) **1001460264**

Regulation violated: SR - 372.2(b)(2)(ii)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(c)(1)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various
Area of violation: Generators - General
Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/19/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various
Area of violation: Generators - General
Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/22/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various

FALA CCG INC (Continued) **1001460264**

Area of violation: Generators - General
Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/20/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/07/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/05/2003
Evaluation lead agency: State

Evaluation date: 03/21/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/22/2001
Evaluation lead agency: EPA

LTANKS:
Site ID: 288842
Spill Number/Closed Date: 8706743 / 1988-02-09
Spill Date: 1987-11-06
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 1988-02-09
Cleanup Meets Standard: True
SWIS: 5226
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1987-11-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1987-11-13
Spill Record Last Update: 2015-05-12
Spiller Name: Not reported
Spiller Company: SEDCO

FALA CCG INC (Continued) **1001460264**

Spiller Address:	75 MARCUS DRIVE
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	233955
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD / / : F&N TESTER.TANK HAS NO HOLES. EXCAVATION CLEAN. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	"5K FAILED AT -.203"

Material:

Site ID:	288842
Operable Unit ID:	912622
Operable Unit:	01
Material ID:	465738
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	288842
Spill Tank Test:	1532205
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

FINDS:

Registry ID: 110004551173

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

FALA CCG INC (Continued) **1001460264**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001460264
Registry ID:	110004551173
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004551173

NJ MANIFEST:

EPA Id:	NYR000067322
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	5166941919
Emergency Phone:	Not reported
Contact:	DAVID F. SCHENK
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000111823SKS
EPA ID:	NYR000067322
Date Shipped:	01/22/2008
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	NJD071629976
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/22/2008
Date Trans2 Transported Waste:	01/29/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

FALA CCG INC (Continued) **1001460264**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	488 P

Manifest Number:	001327524SKS
EPA ID:	NYR000067322
Date Shipped:	11/14/2008
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	NJD071629976
Transporter 3 EPA ID:	TXR000050930
Transporter 4 EPA ID:	NJD071629976
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/14/2008
Date Trans2 Transported Waste:	11/18/2008
Date Trans3 Transported Waste:	11/19/2008
Date Trans4 Transported Waste:	11/21/2008
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/21/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No

FALA CCG INC (Continued) **1001460264**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H061
Quantity: 400 P

Manifest Number: NJA4006080
EPA ID: NYR000067322
Date Shipped: 03/23/2004
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: MOR000505347
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 03/23/2004
Date Trans2 Transported Waste: 03/30/2004
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 03/31/2004
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 04280421
Was Load Rejected: No
Reason Load Was Rejected: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYR000067322
Facility Status: Not reported
Location Address 1: 75 MARCUS DR

FALA CCG INC (Continued) **1001460264**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	4278

NY MANIFEST:

EPAID:	NYR000067322
Mailing Name:	FALA CCG INC
Mailing Contact:	HARRY BELECHTO
Mailing Address 1:	75 MARCUS DR
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	4278
Mailing Country:	USA
Mailing Phone:	6313910223

NY MANIFEST:

Document ID:	NJA3057759
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	06/01/2000
Trans1 Recv Date:	06/01/2000
Trans2 Recv Date:	06/02/2000
TSD Site Recv Date:	06/02/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

FALA CCG INC (Continued) **1001460264**

Quantity:	00770
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA3057793
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	06/19/2000
Trans1 Recv Date:	06/19/2000
Trans2 Recv Date:	06/21/2000
TSD Site Recv Date:	06/23/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01152
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA3057825
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	06/29/2000
Trans1 Recv Date:	06/29/2000

FALA CCG INC (Continued) **1001460264**

Trans2 Recv Date:	06/30/2000
TSD Site Recv Date:	07/06/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00768
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA3057845
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	07/14/2000
Trans1 Recv Date:	07/14/2000
Trans2 Recv Date:	07/18/2000
TSD Site Recv Date:	07/24/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

FALA CCG INC (Continued) **1001460264**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00768
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NYH0137943
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	PW8913
Trans2 State ID:	Not reported
Generator Ship Date:	08/25/2000
Trans1 Recv Date:	08/25/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/25/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

FALA CCG INC (Continued) **1001460264**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA3084207
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	03/21/2000
Trans1 Recv Date:	03/21/2000
Trans2 Recv Date:	03/22/2000
TSD Site Recv Date:	03/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01305
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Document ID:	NJA3084239
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	04/06/2000
Trans1 Recv Date:	04/06/2000
Trans2 Recv Date:	04/07/2000
TSD Site Recv Date:	04/07/2000
Part A Recv Date:	Not reported

FALA CCG INC (Continued) **1001460264**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	02175
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA3084293
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	01/21/2000
Trans1 Recv Date:	01/21/2000
Trans2 Recv Date:	01/26/2000
TSD Site Recv Date:	02/01/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

FALA CCG INC (Continued) **1001460264**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01305
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA3084315
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	02/04/2000
Trans1 Recv Date:	02/04/2000
Trans2 Recv Date:	02/09/2000
TSD Site Recv Date:	02/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00870
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

FALA CCG INC (Continued) **1001460264**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01305
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA3084325
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	02/15/2000
Trans1 Recv Date:	02/15/2000
Trans2 Recv Date:	02/16/2000
TSD Site Recv Date:	02/25/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000067322
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01740
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
83 additional NY_MANIFEST: record(s) in the EDR Site Report.

O75 **AIRCRAFT PARTS INC** **RCRA-SQG** **1000180713**
SSE **160 FINN CT** **NY LTANKS** **NYD013561139**
1/8-1/4 **FARMINGDALE, NY 11735** **NJ MANIFEST**
0.239 mi. **NY MANIFEST**
1261 ft. **Site 9 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	AIRCRAFT PARTS INC
Facility address:	160 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYD013561139
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	WILLIAM PADEN
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	(516) 249-3053
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	S. SHERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	S. SHERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

AIRCRAFT PARTS INC (Continued) **1000180713**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AIRCRAFT PARTS INC
Classification: Small Quantity Generator

Date form received by agency: 06/09/1989
Site name: AIRCRAFT PARTS INC
Classification: Small Quantity Generator

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/23/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

LTANKS:
Site ID: 144446
Spill Number/Closed Date: 9304294 / 2003-09-30
Spill Date: 1993-07-06
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

Cleanup Meets Standard:	True
SWIS:	5220
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1993-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-07
Spill Record Last Update:	2014-08-19
Spiller Name:	BILL PADEN
Spiller Company:	AIRCRAFT PARTS CORP
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	123130
DEC Memo:	"SYSTEM FAILED RETEST 7/29/93 SYSTEM PASSED RETEST 8/3/93 AFTER TANK WAS BLED"
Remarks:	"DUE TO AIR POCKET WILL SPEAK TO BILL PADEN & INVESTIGATE AIR POCKET AND RETEST, 3K FAILED AT -.156, TYREE TESTER"

Material:

Site ID:	144446
Operable Unit ID:	982742
Operable Unit:	01
Material ID:	397812
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	144446
Spill Tank Test:	1541738
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AIRCRAFT PARTS INC (Continued) **1000180713**

NJ MANIFEST:

EPA Id:	NYD013561139
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	5162493053
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Manifest:

Manifest Number:	NJA5213753
EPA ID:	NYD013561139
Date Shipped:	07/26/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD980525786
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2005
Date Trans2 Transported Waste:	08/03/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/03/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12050521

AIRCRAFT PARTS INC (Continued) **1000180713**

Was Load Rejected: No
Reason Load Was Rejected: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYD013561139
Facility Status: Not reported
Location Address 1: 160 FINN COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD013561139
Mailing Name: AIRCRAFT PARTS
Mailing Contact: AIRCRAFT PARTS
Mailing Address 1: 100 CORPERATE DR
Mailing Address 2: Not reported
Mailing City: HOLTSVILLE
Mailing State: NY
Mailing Zip: 11742
Mailing Zip 4: 2004
Mailing Country: USA
Mailing Phone: 5162483053

NY MANIFEST:
Document ID: NJA0713517
Manifest Status: C
seq: Not reported
Year: 1990
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 01/03/1990
Trans1 Recv Date: 01/03/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 01/04/1990
Part A Recv Date: 01/08/1990
Part B Recv Date: 01/16/1990
Generator EPA ID: NYD013561139
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NJA0804383
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	05/04/1990
Trans1 Recv Date:	05/04/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1990
Part A Recv Date:	06/20/1990
Part B Recv Date:	05/14/1990
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01500
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.

AIRCRAFT PARTS INC (Continued) **1000180713**

Specific Gravity:	100
Document ID:	NJA1457999
Manifest Status:	K
seq:	Not reported
Year:	1992
Trans1 State ID:	ET4217
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/1992
Trans1 Recv Date:	06/12/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/17/1992
Part A Recv Date:	/ /
Part B Recv Date:	07/22/1992
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00092
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0926085
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	08/01/1990
Trans1 Recv Date:	08/01/1990
Trans2 Recv Date:	08/01/1990
TSD Site Recv Date:	08/02/1990
Part A Recv Date:	09/06/1990
Part B Recv Date:	08/20/1990
Generator EPA ID:	NYD013561139

AIRCRAFT PARTS INC (Continued) **1000180713**

Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA3160256
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	08/16/2000
Trans1 Recv Date:	08/16/2000
Trans2 Recv Date:	08/17/2000
TSD Site Recv Date:	08/22/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01945
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Document ID:	NJA2581226
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	07/03/1997
Trans1 Recv Date:	07/03/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/09/1997
Part A Recv Date:	08/01/1997
Part B Recv Date:	08/04/1997
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01167
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA2683672

AIRCRAFT PARTS INC (Continued) **1000180713**

Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	12/12/1997
Trans1 Recv Date:	12/12/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/12/1997
Part A Recv Date:	01/05/1998
Part B Recv Date:	01/06/1998
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01556
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA1918990
Manifest Status:	K
seq:	Not reported
Year:	1994
Trans1 State ID:	08690
Trans2 State ID:	NJDEPE086
Generator Ship Date:	08/19/1994
Trans1 Recv Date:	08/19/1994
Trans2 Recv Date:	08/21/1994
TSD Site Recv Date:	08/22/1994
Part A Recv Date:	09/09/1994
Part B Recv Date:	09/14/1994
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ILD984908202
TSDF ID 1:	NJD002182897

AIRCRAFT PARTS INC (Continued) **1000180713**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01168
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA2236688
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/1997
Trans1 Recv Date:	01/10/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/14/1997
Part A Recv Date:	01/30/1997
Part B Recv Date:	02/03/1997
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01945
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NYC3475877
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	ET4217
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/1996
Trans1 Recv Date:	07/08/1996
Trans2 Recv Date:	07/12/1996
TSD Site Recv Date:	07/13/1996
Part A Recv Date:	07/18/1996
Part B Recv Date:	07/29/1996
Generator EPA ID:	NYD013561139
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01932
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
17 additional NY_MANIFEST: record(s) in the EDR Site Report.

O76 **AIRCRAFT PARTS CORP** **NY UST** **U003960604**
SSE **160 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.239 mi.
1261 ft. **Site 10 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	00100
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00100
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	AIRCRAFT PARTS CORP
Storage Owner Address:	160 FINN CT
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00100
Facility Reference #:	00258
Official Use:	Removed Tank. 04
Township:	BABYLON
Tax Map No:	0100 006.00 001 009.000
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	487
Installed:	Not reported
Capacity:	0000003000
Substance:	#2 FUEL OIL
Date Removed:	091504
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

AIRCRAFT PARTS CORP (Continued) **U003960604**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	091504
Year Installed:	Not reported
Description of drop records:	RECORDS AS OF 09/10/2013

O77 **AIRCRAFT PARTS INC** **NY AST** **1001079634**
SSE **160 FINN COURT** **RCRA NonGen / NLR** **NYN008001331**
1/8-1/4 **FARMINGDALE, NY 11735** **FINDS**
0.239 mi. **ECHO**
1261 ft. **Site 11 of 11 in cluster O**

Relative:
Lower

Actual:
101 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	00100
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00100
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	AIRCRAFT PARTS CORP
Storage Owner Address:	160 FINN CT
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00100
Facility Reference #:	00258
Township:	BABYLON
Tax Map No:	0100
Region:	SUFFOLK
Tank ID:	2
Tank Key:	488
Year Installed:	90
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 04
Permit to Operate:	090490
Tank Location:	Not reported
Tabk Status:	Not reported
Total Capacity:	0000001440
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported

AIRCRAFT PARTS INC (Continued) **1001079634**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	091504

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AIRCRAFT PARTS CORP
Facility address:	160 FINN CT FARMINGDALE, NY 117351107
EPA ID:	NYN008001331
Mailing address:	FINN CT FARMINGDALE, NY 117351107
Contact:	Not reported
Contact address:	FINN CT FARMINGDALE, NY 117351107
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	UNK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No

AIRCRAFT PARTS INC (Continued) **1001079634**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AIRCRAFT PARTS CORP
Classification: Not a generator, verified

Date form received by agency: 09/29/1995
Site name: AIRCRAFT PARTS CORP
Classification: Unverified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/23/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004349232

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AIRCRAFT PARTS INC (Continued) **1001079634**

ECHO:
Envid: 1001079634
Registry ID: 110004349232
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004349232

78
SW
1/4-1/2
0.256 mi.
1351 ft.

NORTHROP GRUMMAN
65 MARCUS DRIVE
MELVILLE, NY

NY LTANKS **S100149169**
NY Spills **N/A**

Relative:
Lower

Actual:
102 ft.

LTANKS:
Site ID: 145270
Spill Number/Closed Date: 8706384 / 1988-02-12
Spill Date: 1987-10-27
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 1988-02-12
Cleanup Meets Standard: True
SWIS: 5226
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1987-10-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1987-10-29
Spill Record Last Update: 2014-03-28
Spiller Name: Not reported
Spiller Company: SEDCO SYSTEMS
Spiller Address: 65 MARCUS DRIVE
Spiller City,St,Zip: MELVILLE, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 294934
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD / / : F&N TESTER.AS PER SCOTT SCHUCK,ORIGINAL TEST FAILED DUE TO POOR CIRCULATION.ON 1/21/88,F&N RETESTED SYSTEM & PASSED. DEC NOT PRESENT. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks: "10K FAILED AT -.373"

Material:
Site ID: 145270
Operable Unit ID: 910098
Operable Unit: 01
Material ID: 465399
Material Code: 0002A

NORTHROP GRUMMAN (Continued) **S100149169**

Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 145270
Spill Tank Test: 1532072
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

SPILLS:
Facility ID: 0302056
Facility Type: ER
DER Facility ID: 294934
Site ID: 145269
DEC Region: 1
Spill Date: 2003-05-28
Spill Number/Closed Date: 0302056 / 2008-07-16
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5226
Investigator: NJACAMPO
Referred To: Not reported
Reported to Dept: 2003-05-28
CID: 297
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-28
Spill Record Last Update: 2014-03-28
Spiller Name: Not reported
Spiller Company: JET SANITATION SERVICE
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: BILL GOING
Contact Phone: (631) 719-4721

NORTHROP GRUMMAN (Continued) **S100149169**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ACAMPORA TELECON CALLER-NO SOIL OR DRAINS AFFECTED, HAS BEEN CLEANED UP WITH ABSORBANTS CLEANUP COMPLETED"
Remarks: "A HYDRAULIC LINE RUPTURED ON THE LIFT ARM OF THE TRUCK WHEN IT WAS PICKING UP A DUMPSTER - JET SANITATION CLEANED UP THE SPILL"

Material:
Site ID: 145269
Operable Unit ID: 868605
Operable Unit: 01
Material ID: 506541
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 12.00
Units: Gallons
Recovered: 12.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

79
NW
1/4-1/2
0.281 mi.
1483 ft.

Relative: Higher

Actual: 107 ft.

WE'RE ASSOCIATES **NY LTANKS** **S104513962**
100 BAYLIS ROAD **N/A**
MELVILLE, NY

LTANKS:
Site ID: 224161
Spill Number/Closed Date: 8803165 / 1988-08-25
Spill Date: 1988-07-12
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-08-25
Cleanup Meets Standard: True
SWIS: 5226
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1988-07-12
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-07-14
Spill Record Last Update: 2006-06-15
Spiller Name: Not reported
Spiller Company: WERE ASSOCIATES
Spiller Address: 100 JERICHO QUADRANGLE
Spiller City,St,Zip: JERICHO, NY
Spiller County: 001
Spiller Contact: Not reported

WE'RE ASSOCIATES (Continued) **S104513962**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	290926
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 08/25/88: F&N RETESTED SYSTEM AFTER NO REPAIRS & SYSTEM PASSED.F&N USED 2 CIRCULATORS ON RETEST INSTEAD OF 1. DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"7500 FAILED AT -.151 GPH. ISOLATE TANK TEST FAILURE-INITIAL PETROTITE TEST 2 TANKS AS SITE. NORTH TANK FAILED. WILL EITHER RETEST OR PULL TANK. F&N TESTER."

Material:

Site ID:	224161
Operable Unit ID:	920329
Operable Unit:	01
Material ID:	458726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	224161
Spill Tank Test:	1534273
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	224162
Spill Number/Closed Date:	9003860 / 1995-04-05
Spill Date:	1990-07-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-04-05
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1990-07-06
CID:	Not reported
Water Affected:	Not reported

WE'RE ASSOCIATES (Continued) **S104513962**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	2009-07-08
Spiller Name:	HERB HANSON
Spiller Company:	WE'RE ASSOCIATES
Spiller Address:	JERICHO QUAD SUITE 106
Spiller City,St,Zip:	JERICHO, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	290926
DEC Memo:	"RETEST PASSED, AWAITING FOR RESULTS PER SCHD TANK SYS #2 PASSED 7/12/90, SEE SAME FOR DOCUMENTATION, NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"7500 FAILED AT -0.147 GPH. F&N TESTER. TROUBLE WITH CIRCULATION. RETEST BEFORE DIGGING"

Material:

Site ID:	224162
Operable Unit ID:	941680
Operable Unit:	01
Material ID:	434989
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	224162
Spill Tank Test:	1537273
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

R80 **FIRST VEHICLE SERVICES** **NY LTANKS** **S108651007**
WSW **55 MARCUS DR** **NY Spills** **N/A**
1/4-1/2 **MELVILLE, NY 11747** **NY MANIFEST**
0.327 mi.
1729 ft. **Site 1 of 2 in cluster R**

Relative:
Lower

Actual:
100 ft.

LTANKS:

Site ID:	274806
Spill Number/Closed Date:	8805536 / 1988-10-31
Spill Date:	1988-09-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-10-31
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-09-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-30
Spill Record Last Update:	2014-03-28
Spiller Name:	Not reported
Spiller Company:	GABAR CO
Spiller Address:	55 MARCUS DRIVE
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	223522
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 10/31/88: BAIN RETESTED SYSTEM ON 10/5 AFTER MANWAYS WAS BLED & OEM VENT ALARM WAS REPAIRED & SYSTEM PASSED.DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"BAINE CORP TESTER. 7500 FAILED AT -.164 GPH. PETROTITE TEST"

Material:

Site ID:	274806
Operable Unit ID:	922517
Operable Unit:	01
Material ID:	457439
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

FIRST VEHICLE SERVICES (Continued) **S108651007**

Oxygenate: Not reported

Tank Test:
Site ID: 274806
Spill Tank Test: 1534697
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

SPILLS:
Facility ID: 0508683
Facility Type: ER
DER Facility ID: 223522
Site ID: 354316
DEC Region: 1
Spill Date: 2005-10-19
Spill Number/Closed Date: 0508683 / 2006-01-17
Spill Cause: Traffic Accident
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5226
Investigator: WXPRZYLO
Referred To: Not reported
Reported to Dept: 2005-10-19
CID: 73
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-10-20
Spill Record Last Update: 2008-06-30
Spiller Name: MARVIN COLEMAN
Spiller Company: COVENANT TRANSPORT
Spiller Address: 400 BURMINGHAM HWY
Spiller City,St,Zip: CHATTANOOGA, TN 37419
Spiller Company: 001
Contact Name: ANN WORTMAN
Contact Phone: (863) 581-4124
DEC Memo: "11/19/05 24:00 VALDI TELECON TO ANN WORTMAN, SPILL ON THE SURFACE, NO DRAINS AFFECTED. CLEANUP WAS ONGOING, 2-55 GAL OF STREET SWEEPER, HMHTTC COMPANY CLEANUP HAS BEEN COMPLETED, NO FURTHER ACTION REQUIRED" Not reported
Remarks: "DRIVER OF TRACTOR TRAILER RAN OVER A CURB CAUSING DAMAGE TO THE OIL PAN. CLEAN UP IN PROGRESS BY HMHTTC. ALTERNATE CONTACT FOR ANN WORTMAN IS 800-226-0911 (OFFICE NUMBER)."

FIRST VEHICLE SERVICES (Continued) **S108651007**

Material:
Site ID: 354316
Operable Unit ID: 1111735
Operable Unit: 01
Material ID: 2101782
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

NY MANIFEST:
Country: USA
EPA ID: NY5168473960
Facility Status: Not reported
Location Address 1: 55 MARCUS DR
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY5168473960
Mailing Name: FIRST VEHICLE SERVICES
Mailing Contact: FIRST VEHICLE SERVICES
Mailing Address 1: 55 MARCUS DR
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5168473960

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2007
Trans1 State ID: MAD039322250
Trans2 State ID: OHD009865825
Generator Ship Date: 10/26/2007
Trans1 Recv Date: 10/26/2007
Trans2 Recv Date: 10/30/2007
TSD Site Recv Date: 11/12/2007
Part A Recv Date: Not reported

FIRST VEHICLE SERVICES (Continued) **S108651007**

Part B Recv Date:	Not reported
Generator EPA ID:	NY5168473960
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	000540492FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D006
Waste Code 1_3:	D018
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	04/20/2012
Trans1 Recv Date:	04/20/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/27/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY5168473960
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	002751194SKS
Import Indicator:	N
Export Indicator:	N

FIRST VEHICLE SERVICES (Continued) **S108651007**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

81
West
1/4-1/2
0.336 mi.
1772 ft.

SPILL NUMBER 9713313 **NY LTANKS** **S104619472**
98 REPUBLIC ROAD **N/A**
MELVILLE, NY

Relative:
Lower

Actual:
98 ft.

LTANKS:

Site ID:	182849
Spill Number/Closed Date:	9713313 / 1998-08-26
Spill Date:	1998-03-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5200
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1998-03-02
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-02
Spill Record Last Update:	1998-08-27

SPILL NUMBER 9713313 (Continued) **S104619472**

Spiller Name:	ROGER SCHMIDT
Spiller Company:	Not reported
Spiller Address:	98 REPUBLIC ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	ROGER SCHMIDT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	153189
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA PER DEAN ANSON, CLIENT HAD PHASE II DONE BY ANOTHER FIRM IN 9/97. FOUND CONTAMINATION IN EXCEEDENCE OF STARS. CLIENT IS A SOD FARM, 2-275 GAL GASOLINE TANKS REMOVED WITH AN OVERSIGHT DURING THE 80'S. CLIENT INTERESTED IN PROPERTY TRANSFER. ANSON HAS COMPILED REPORT AND WILL SEND IT TO THE OFFICE RECENT SOIL BORING SHOWED NO SOIL OR GW CONTAMINATION "
Remarks:	"CALLER REPORTED SITE SURVEY AND FOUND CONTAMINATED SOIL AT SITE OF FORMER TANK."

Material:

Site ID:	182849
Operable Unit ID:	1059322
Operable Unit:	01
Material ID:	324332
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

82 South 1/4-1/2 0.343 mi. 1809 ft.

Relative: Lower

Actual: 100 ft.

KALMAR DESIGNS **NY LTANKS S101856411**
485 SMITH STREET **NY Spills N/A**
FARMINGDALE, NY

LTANKS:

Site ID:	70689
Spill Number/Closed Date:	9209410 / 1992-11-13
Spill Date:	1992-09-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-11-13
Cleanup Meets Standard:	True
SWIS:	5200
Investigator:	UNASSIGNED
Referred To:	Not reported

KALMAR DESIGNS (Continued) **S101856411**

Reported to Dept:	1992-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-11-13
Spill Record Last Update:	1992-11-13
Spiller Name:	Not reported
Spiller Company:	KALMAR DESIGNS
Spiller Address:	485 SMITH ST
Spiller City,St,Zip:	FARMINGDALE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	67029
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE 11/13/92: NO RESPONSE. "
Remarks:	"1-5K FUEL OIL TANK REMOVED, DETERIORATED, LEAKAGE FROM SUPPLY LINE CONT SOIL REMOVED. SCDH ON SITE DURING REMOVAL"

Material:

Site ID:	70689
Operable Unit ID:	976001
Operable Unit:	01
Material ID:	406461
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1111958
Facility Type:	ER
DER Facility ID:	414346
Site ID:	459878
DEC Region:	1
Spill Date:	2012-01-12
Spill Number/Closed Date:	1111958 / 2012-09-13
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5220
Investigator:	Unassigned

KALMAR DESIGNS (Continued) **S101856411**

Referred To:	Not reported
Reported to Dept:	2012-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-01-12
Spill Record Last Update:	2012-09-17
Spiller Name:	Not reported
Spiller Company:	ALP LIGHTING COMPONENTS
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	JEFF GOLDSTEIN
Contact Phone:	(631) 777-7700
DEC Memo:	"01/12/12 1225 Hrs (A): GOLDSTEIN CALLED- HE SAID THIS HAD JUST OCCURRED AND WANTED TO KNOW WHAT NEEDED TO BE DONE. 01/12/12 1225 Hrs (B): He said ALP LIGHTING COMPONENTS was delivering to his company when the TRUCK FUEL FILTER leaked. 01/12/12 1225 Hrs (C): He said 'PERHAPS 5GAL TOTAL LEAKED; THEY PLACED A BUCKET UNDER THE LEAK AND CAUGHT MOST OF THE PRODUCT BUT PERHAPS 1-2GAL ENTERED A DRAIN'. 01/12/12 1225 Hrs (D): Goldstein also said his maintenance company had already cleaned up the pavement with speedi dri. DEC informed him that if there was only a few gallons of fuel in the drain it could be removed with sorbent pads, and that if the maintenance company did not have any Tyree Environmental was located nearby. 01/12/12 1225 Hrs (E): DEC also asked Goldstein to call the Hotline to report the incident. DR"
Remarks:	"during delivery loss occured into catch basin and pavement, speedy dry applied."

Material:

Site ID:	459878
Operable Unit ID:	1209971
Operable Unit:	01
Material ID:	2207546
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

S83 **VENUS SCIENTIFIC INC** **NY LTANKS** **1000427538**
SSW **399 SMITH ST** **NY UST** **NYD002411866**
1/4-1/2 **FARMINGDALE, NY 11735** **NY AST**
0.353 mi. **RCRA NonGen / NLR**
1862 ft. **Site 1 of 2 in cluster S** **FINDS**
ECHO
Relative: **NY MANIFEST**
Lower

Actual: **100 ft.**

LTANKS:

Site ID:	287908
Spill Number/Closed Date:	8803558 / 1988-09-29
Spill Date:	1988-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-09-29
Cleanup Meets Standard:	True
SWIS:	3024
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-25
Spill Record Last Update:	2006-06-12
Spiller Name:	Not reported
Spiller Company:	VENUS SCIENTIFIC
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	233207
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 09/29/88: TANK WAS REMOVED BY TYREE ON 9/22. THERE WAS NO CONTAMINATION FOUND. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	"2K TANK FAILED AT -.455 GPH. ALL COUNTY TANK TESTING TESTER. NO ACTION YET. NEEDS 3 OPTION TO TANK OWNER,NOTIFICATION TO TANK TESTER."
	Not reported

Material:

Site ID:	287908
Operable Unit ID:	920738
Operable Unit:	01
Material ID:	459107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

VENUS SCIENTIFIC INC (Continued) **1000427538**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 287908
Spill Tank Test: 1534330
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 01492
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 01492
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: VENUS SCIENTIFIC
Storage Owner Address: 399 SMITH ST
Storage Owner City: FARMINGDALE
Storage Owner State: NY
Storage Owner Zip: 11735

Tank Info:
Facility ID: 01492
Facility Reference #: 03284
Official Use: Removed Tank. 86
Township: BABYLON
Tax Map No: 0100 005.00 001 006.000
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 2
Tank Key: 4193
Installed: 1960
Capacity: 0000003000
Substance: GASOLINE
Date Removed: 010186
Construction: STEEL
Dispenser: SUCTION
Fill Type: GRAVITY

VENUS SCIENTIFIC INC (Continued) **1000427538**

Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000003000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	010186
Year Installed:	1960
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	3
Tank Key:	4194
Installed:	68
Capacity:	0000002000
Substance:	#2 FUEL OIL
Date Removed:	092288
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	092288
Year Installed:	68
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	4
Tank Key:	4195

VENUS SCIENTIFIC INC (Continued) **1000427538**

Installed:	68
Capacity:	0000002000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000002000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	68
Description of drop records:	RECORDS AS OF 09/10/2013

Tank ID:	5
Tank Key:	4196
Installed:	Not reported
Capacity:	0000005000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	0000005000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED

VENUS SCIENTIFIC INC (Continued) **1000427538**

Date Removed: Not reported
Year Installed: Not reported
Description of drop records: RECORDS AS OF 09/10/2013

AST_SUFFOLK:
Region: SUFFOLK
Site Ref#: 01492
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported

Facility Info:
Site Ref#: 01492
Billing Contact: Not reported
Billing Address: Not reported
Billing Address: Not reported
Billing State: Not reported
Billing Zip: Not reported
Storage Owner: VENUS SCIENTIFIC
Storage Owner Address: 399 SMITH ST
Storage Owner City: FARMINGDALE
Storage Owner State: NY
Storage Owner Zip: 11735

Tank Info:
Facility ID: 01492
Facility Reference #: 03284
Township: BABYLON
Tax Map No: 0100
Region: SUFFOLK

Tank ID: 1
Tank Key: 4192
Year Installed: 84
Substance: DRUM STORAGE
Construction: Not reported
Dispenser: OTHER
Official Use: Removed Tank. 92
Permit to Operate: Not reported
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 0000001500
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	073192

Tank ID:	6
Tank Key:	4197
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001925
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	4198
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000220
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: VENUS SCIENTIFIC INC
Facility address: 399 SMITH ST
FARMINGDALE, NY 117351106
EPA ID: NYD002411866
Mailing address: SMITH ST
FARMINGDALE, NY 11735
Contact: Not reported
Contact address: SMITH ST
FARMINGDALE, NY 11735
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

VENUS SCIENTIFIC INC (Continued) **1000427538**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: VENUS SCIENTIFIC INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: VENUS SCIENTIFIC INC
Classification: Not a generator, verified

Date form received by agency: 04/29/1982
Site name: VENUS SCIENTIFIC INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

VENUS SCIENTIFIC INC (Continued) **1000427538**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/21/1986
Date achieved compliance: 11/06/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/26/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/21/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/06/1986
Evaluation lead agency: State

FINDS:

Registry ID: 110004341285

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000427538
Registry ID: 110004341285
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004341285

NY MANIFEST:
Country: USA
EPA ID: NYD002411866
Facility Status: Not reported
Location Address 1: 399 SMITH STREET

VENUS SCIENTIFIC INC (Continued) **1000427538**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	1106

NY MANIFEST:

EPAID:	NYD002411866
Mailing Name:	VENUS SCIENTIFIC INC.
Mailing Contact:	RAPLPH STAELGRAEVE
Mailing Address 1:	11878 HUBBARD ST.
Mailing Address 2:	Not reported
Mailing City:	LIVONIA
Mailing State:	MI
Mailing Zip:	48150
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162934100

NY MANIFEST:

Document ID:	NJA0527381
Manifest Status:	C
seq:	Not reported
Year:	1988
Trans1 State ID:	NJDEPS063
Trans2 State ID:	Not reported
Generator Ship Date:	09/07/1988
Trans1 Recv Date:	09/07/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/09/1988
Part A Recv Date:	09/16/1988
Part B Recv Date:	09/14/1988
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD982528168
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NJA0523287
Manifest Status:	C
seq:	Not reported
Year:	1988
Trans1 State ID:	NJDEPS847
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/1988
Trans1 Recv Date:	09/01/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/01/1988
Part A Recv Date:	09/13/1988
Part B Recv Date:	09/20/1988
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD065825341
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD065825341
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels

VENUS SCIENTIFIC INC (Continued) **1000427538**

Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA0938360
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	NJDEPS-81
Trans2 State ID:	Not reported
Generator Ship Date:	08/23/1990
Trans1 Recv Date:	08/23/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/23/1990
Part A Recv Date:	09/05/1990
Part B Recv Date:	09/04/1990
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Document ID:	NJA0735227

VENUS SCIENTIFIC INC (Continued) **1000427538**

Manifest Status:	C
seq:	Not reported
Year:	1989
Trans1 State ID:	NJDEPS-81
Trans2 State ID:	Not reported
Generator Ship Date:	11/07/1989
Trans1 Recv Date:	11/07/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/07/1989
Part A Recv Date:	11/21/1989
Part B Recv Date:	11/21/1989
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD980525844
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB2979585
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	LISC#XM67
Trans2 State ID:	LISC#8374
Generator Ship Date:	01/12/1990
Trans1 Recv Date:	01/12/1990
Trans2 Recv Date:	01/16/1990
TSD Site Recv Date:	01/17/1990
Part A Recv Date:	02/01/1990
Part B Recv Date:	01/26/1990
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD982744054
Trans2 EPA ID:	NYD046765574
TSDF ID 1:	NYD043815703

VENUS SCIENTIFIC INC (Continued) **1000427538**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NJA0841545
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	NJDEPS-81
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/1990
Trans1 Recv Date:	03/26/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/26/1990
Part A Recv Date:	04/18/1990
Part B Recv Date:	04/19/1990
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	MIA0692325
Manifest Status:	K
seq:	Not reported
Year:	1986
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	01/23/1986
Trans1 Recv Date:	01/23/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/24/1986
Part A Recv Date:	01/27/1986
Part B Recv Date:	03/04/1986
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD099287484
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID096963194
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00600
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	011
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NJA0175168
Manifest Status:	C
seq:	Not reported
Year:	1986

VENUS SCIENTIFIC INC (Continued) **1000427538**

Trans1 State ID:	NJDEPS847
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/1986
Trans1 Recv Date:	03/11/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/12/1986
Part A Recv Date:	03/19/1986
Part B Recv Date:	03/18/1986
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD065825341
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels

VENUS SCIENTIFIC INC (Continued) **1000427538**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NYA3265694
Manifest Status:	C
seq:	Not reported
Year:	1986
Trans1 State ID:	9A025
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/1986
Trans1 Recv Date:	11/21/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/22/1986
Part A Recv Date:	11/28/1986
Part B Recv Date:	12/02/1986
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049178296
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04000
Units:	P - Pounds
Number of Containers:	008
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NJA0175094

VENUS SCIENTIFIC INC (Continued) **1000427538**

Manifest Status:	C
seq:	Not reported
Year:	1986
Trans1 State ID:	NJDEPS847
Trans2 State ID:	Not reported
Generator Ship Date:	01/21/1986
Trans1 Recv Date:	01/21/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/22/1986
Part A Recv Date:	02/12/1986
Part B Recv Date:	01/31/1986
Generator EPA ID:	NYD002411866
Trans1 EPA ID:	NJD065825341
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110

VENUS SCIENTIFIC INC (Continued) **1000427538**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
44 additional NY_MANIFEST: record(s) in the EDR Site Report.

S84 **HT STEEL** **NY LTANKS** **S109827048**
SSW **375 SMITH STREET** **NY Spills** **N/A**
1/4-1/2 **FARMINGDALE, NY**
0.358 mi.
1889 ft. **Site 2 of 2 in cluster S**

Relative:
Lower

Actual:
100 ft.

LTANKS:

Site ID:	84738
Spill Number/Closed Date:	9311399 / 1994-02-15
Spill Date:	1993-12-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	No spill occured. (Not Possible)
Cleanup Ceased:	1994-02-15
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1993-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-24
Spill Record Last Update:	2001-11-27
Spiller Name:	Not reported
Spiller Company:	ROBERTS REALTY
Spiller Address:	20 SEAVIEW BLVD
Spiller City,St,Zip:	PORT WASHINGTON, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	77900
DEC Memo:	""
Remarks:	"5K FAILED AT -.109, VOLINO & SONS TESTER, LANDLORD WAS NOTIFIED"

Material:

Site ID:	84738
Operable Unit ID:	990023
Operable Unit:	01
Material ID:	390438
Material Code:	0001A

HT STEEL (Continued) **S109827048**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	84738
Spill Tank Test:	1542322
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0903613
Facility Type:	ER
DER Facility ID:	364816
Site ID:	415731
DEC Region:	1
Spill Date:	2009-06-27
Spill Number/Closed Date:	0903613 / 2010-01-06
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5220
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2009-06-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-27
Spill Record Last Update:	2010-02-12
Spiller Name:	JOE BARBERA
Spiller Company:	NATIONAL GRID
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	JOSEPH BARBERA
Contact Phone:	(516) 790-5726

HT STEEL (Continued) **S109827048**

DEC Memo: "0903613, National Grid, no calls (BD)"
Remarks: "1124 The caller advised dispatch a transformer failed causing the spill. No water ways affected. The sustance leaked into dirt area. The clean up will be conducted by waste recycling solutions."

Material:
Site ID: 415731
Operable Unit ID: 1172061
Operable Unit: 01
Material ID: 2163913
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 9909028
Facility Type: ER
DER Facility ID: 391854
Site ID: 296440
DEC Region: 1
Spill Date: 1999-10-25
Spill Number/Closed Date: 9909028 / 2000-02-11
Spill Cause: Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5220
Investigator: RDDECAND
Referred To: Not reported
Reported to Dept: 1999-10-25
CID: 205
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-10-25
Spill Record Last Update: 2010-07-07
Spiller Name: OWNER
Spiller Company: HT STEEL CO
Spiller Address: 375 SMITH STREET
Spiller City,St,Zip: FARMINGDALE, NY 11735-
Spiller Company: 001
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

HT STEEL (Continued) **S109827048**

DECANDIA ***SAME AS 9925362*** SOIL EXCAVATED AND DISPOSED, END POINTS ARE CLEAN"

Remarks: "CONTAMINATION FOUND DURING ROUTINE REMOVAL OF 1 5,000GAL FUEL OIL TANK. ***SAME AS 9925362***"

Material:

Site ID:	296440
Operable Unit ID:	1087707
Operable Unit:	01
Material ID:	298125
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

85 South 1/4-1/2 0.364 mi. 1924 ft.

MINMILT REALTY (HYGRADE METAL MOULDING) **NY SHWS** **S106780916**
540 SMITH STREET **NY VAPOR REOPENED** **N/A**
FARMINGDALE, NY 11735 **NY VCP**

Relative: Lower

Actual: 100 ft.

SHWS:

Program:	HW
Site Code:	55887
Classification:	Site is properly closed - requires continued management.
Region:	1
Acres:	2.28
HW Code:	152147
Record Add:	11/18/1999
Record Upd:	11/30/2015
Updated By:	JBSWARTO

Site Description: Location: This site is a former metal forming facility consisting of a one-story industrial building on a 2.28 acre parcel. The Building is located on Smith Street in the unincorporated Hamlet of East Farmingdale, Suffolk County.Site Features: The Minmilt site is located on the glacial outwash plain of southern-central Long Island. The geology consists mailnly of unconsoliated sand deposits intermixed with smaller, generally non-continuous lower permiability clay and/or silt mix confining units. The upper aquifer is the Upper Glacial aquifer that overlays the Magothy aquifer.Current Zoning and Land Use: The area surrounding the Minmilt Realty site has been zoned entirely commercial/industrial. All the surrounding structures are commercial/industrial as well. Past Use of The Site: Industrial activities at this site included the use of vapor degreasers containing tetrachloroethylene or perchlorethene(PCE). The spent degreasers were disposed into a leaching pool on-site without a SPDES permit. Nature and Extent of Contamination: Minmilt Realty signed an original order with Suffolk County to clean out the dry well. Subsequently, a Consent Order (CO) was signed on November 7, 1994 between the NYSDEC and the current owner to conduct a RI/FS and an

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

Interim Remedial Action (IRM). The RI found that soils and groundwater on the east side of the building were highly contaminated with PCE. An IRM consisting of soil vapor extraction (SVE) and groundwater pump and treat were installed in February 1997 and have run continuously, since that time. The remedial systems continue to operate and perform successfully.The Suffolk County Department of Health Services, in July 1997, installed a monitoring well and took hydro-punch samples on Central Avenue, about 1500 feet downgradient of the site to supplement the Minmilt offsite remedial investigation. The PRP investigation of the off-site groundwater plume commenced in December 1998.In summary the off-site RI/FS was approved and a ROD calling for the continued operation of the SVE system to address the soil contamination and the extraction and treatment of the groundwater to address the groundwater contamination was signed on March 3, 2002. The potential responsible party (PRP) signed the remedial design and remedial action order on consent with DEC shortly thereafter. The groundwater pump and treat system contains the plume and continues to contain and remove PCE from the Upper Glacial and Magothy aquifers. Operation, maintenance and monitoring. The shallow monitoring wells on site and downgradient of the source area have cleaned by orders of magnitude and are now below, or are approaching, groundwater standards. Vapor phase activated carbon treatment was removed from the SVE off gas in April 1999 as it was no longer required based on Air Guide 1 stack emission review. The PRPs investigated the potential for soil vapor intrusion into buildings in the area to the satisfaction of NYSDEC/NYSDOH. Results indicated that mitigation for vapor intrusion would not be required. Current Status: All the program elements are in place that allowed the site to be reclassified to class 4. This means the remedial program specified in the ROD is in place and operating and performing successfully. The continued operation, maintenance and monitoring (O,M&M) will be required. Once the remedial system is finished, and additional vapor intrusion testing completed per DEC and DOH requirements, the Minmilt Realty site will be delisted.

Env Problem: Soils and groundwater at the site have been contaminated. The PRP implemented an SVE and near offsite groundwater pump and treat IRM. The O&M data shows that the SVE is nearly complete in removing PCE from soils. To date, more than 5,200 pounds of PCE has been removed via the soil vapor extraction system. The system continues to operate to remove any resiual vapors to prevent the potential for soil vapor intrusion. To date, more than 30,000 pounds of solvent have been removed via the groundwater extraction and treatment system. Vertical profiling verified that the clay layers inhibited the vertical migration of the Minmilt Plume to the deeper part of the Magothy aquifer in the vicinity of the source area.

Health Problem: Persons who dig below the ground surface may come into contact with contaminants in subsurface soil. People are not coming into contact site related contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The soil vapor extraction system in operation at the site has been successful in preventing the indoor air quality of the on-site building and an adjacent off-site building from being

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

affected by the contamination in soil vapor.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Oct. 1982
Disp Term:	May 1990
Lat/Long:	40:45:24:0 / 73:24:20:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MINMILT REALTY
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MINMILT REALTY
Owner Address:	540 SMITH STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	HALF HOLLOW HILLS LIBRARY
Owner Company:	MINMILT REALTY
Owner Address:	55 VANDERBILT PARKWAY
Owner Addr2:	Not reported
Owner City,St,Zip:	DIX HILLS, NY 11746
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	RICHARD COLE
Owner Company:	NA
Owner Address:	352 CARNATION DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Hygrade Metal Moulding Corporation
Owner Address:	540 Smith Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	152147
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

HW Code: 152147
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152147
Waste Type: TETRACHLOROETHYLENE {(PCE OR "PERC.") (F001)}
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD001489269
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

VAPOR REOPENED:
Site Code: 152147
Facility Status: Underway

VCP:
Program Type: VCP
Site Code: 56903
HW Code: V00247
Site Class: N
SWIS: 5222
Region: 1
Town: Brookhaven
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 01/05/2005
Updated By: JBSWARTO
Site Description: This is now Registry site # 152147.This site is a metal forming facility consisting of a one-story industrial building on a 2.28 acre parcel. Industrial activities at this site included the use of vapor degreasers containing tetrachloroethylene (PCE). The spent degreasers were disposed into a leaching pool on-site without a SPDES permit. A Consent Order (CO) was signed on November 7, 1994 between the NYSDEC and the current owner to conduct a RI/FS and an IRM. The RI found that soils on the east side of the building were highly contaminated with PCE at levels up to 820 ppm, and groundwater contained PCE at levels up to 140,000 ppb. An Interim Remedial Measure (IRM) consisting of soil vapor extraction (SVE) and groundwater pump and treat were installed in February 1997 and are now operating. The Suffolk County Department of Health Services installed a monitoring well and took hydro punch samples on Central Avenue, about 1500 feet downgradient of the site, in July 1997. This sampling revealed an extensive PCE plume migrating from the site. An investigation of the off-site groundwater plume commenced in December 1998. Vapor phase activated carbon treatment was removed from the SVE off gas in April 1999 as it was no longer required. The groundwater component is containing the plume and is presently removing a significant mass of PCE from the Upper Glacial and Magothy aquifers. The off-site RI/FS was approved and a ROD calling for the continued operation of the SVE system to address the soil contamination and the extraction and treatment of the groundwater to address the groundwater contamination was signed on March 3, 2002. Operation, maintenance and monitoring

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

	continues and shallow monitoring wells on site and downgradient of the source area are beginning to clean up.
Env Problem:	Minmilt used a vapor degreaser with Tetrachloroethlyene (PCE) that discharged directly to a drywell on the east side of the building. The PRP implemented an SVE and near offsite groundwater pump and treat IRM. The O&M data shows that the SVE is nearly complete in removing PCE from soils. To date, more than 5,200 pounds of PCE has been removed from the soils and 20,000 pounds from the groundwater. Vertical Profiling verified that the clay layers inhibiting the vertical migration of the Minmilt Plume in the vicinity of the source were continuous.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Applicant/Requestor
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	J. D'Addario & Company, Inc.
Owner Address:	595 SMITH STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	C/O RICHARD COLE
Owner Company:	MINMILT REALTY
Owner Address:	40 SANTA BARBARA DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	PLAINVIEW, NY 11803
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

R86 **EAGLE FUEL TRANSPORT** **NY LTANKS** **S102668276**
SW **50 REPUBLIC ROAD** **NY Spills** **N/A**
1/4-1/2 **MELVILLE, NY**
0.368 mi.
1943 ft. **Site 2 of 2 in cluster R**

Relative:
Lower

Actual:
100 ft.

LTANKS:

Site ID:	243590
Spill Number/Closed Date:	9201913 / 1992-09-28
Spill Date:	1992-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-09-28
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1992-05-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-19
Spill Record Last Update:	2016-07-14
Spiller Name:	Not reported
Spiller Company:	RAYTHEONE ELECTRONICS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	294936
DEC Memo:	"10K #4 FUEL OIL TANK REMOVED ON 9/25/92,CAMPBELL ON SITE, NO CONTAMINATION WAS FOUND BENEATH OR AROUND THE 10K TANK OR LINES, NO FURTHER ACTION IS REQUIRED AT THIS TIME"
Remarks:	"10K FAILED AT -0.170, F&N TESTER"

Material:

Site ID:	243590
Operable Unit ID:	969306
Operable Unit:	01
Material ID:	413199
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

EAGLE FUEL TRANSPORT (Continued) **S102668276**

Tank Test:

Site ID:	243590
Spill Tank Test:	1540006
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	8706348
Facility Type:	ER
DER Facility ID:	294936
Site ID:	243589
DEC Region:	1
Spill Date:	1987-10-27
Spill Number/Closed Date:	8706348 / 1990-08-24
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	MIRZA
Referred To:	Not reported
Reported to Dept:	1987-10-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1990-08-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-29
Spill Record Last Update:	2016-07-14
Spiller Name:	Not reported
Spiller Company:	EAGLE FUEL TRANSPORT
Spiller Address:	744 BROADWAY
Spiller City,St,Zip:	NORTH MASSAPEQUA, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MIRZA FD / / : SCDH NOTIFIED.ABSORBENT MAT'L & SAND PLACED ON SPILL. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"OIL SHOT OUT OF AIR PIPE ONTO PARKING LOT."

Material:

Site ID:	243589
Operable Unit ID:	910064
Operable Unit:	01

EAGLE FUEL TRANSPORT (Continued) **S102668276**

Material ID:	465361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

87 **RECKSON ASSOCIATES** **NY VCP** **1001961566**
SSW **333 SMITH ST** **RCRA NonGen / NLR** **NYR000083600**
1/4-1/2 **FARMINGDALE, NY 11735** **FINDS**
0.389 mi. **ECHO**
2056 ft. **NY MANIFEST**

Relative:
Lower

Actual:
100 ft.

VCP:

Program Type:	VCP
Site Code:	58757
HW Code:	V00152
Site Class:	A
SWIS:	5220
Region:	1
Town:	Babylon
Acres:	13
Date Record Added:	11/30/2000
Date Record Updated:	10/06/2015
Updated By:	WJPARISH
Site Description:	Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area.Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools

RECKSON ASSOCIATES (Continued) **1001961566**

along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP.Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality.The building is currently vacant and the system is not operational and in need of repair.The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by an excavation plan work plan that will be incorporated into the projects site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water system that obtains water from a source not affected by this contamination. Since contaminated soils may remain at the site below the existing building, people will not come into contact with contaminated soils unless the building foundation is removed or they dig below the surface material. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A combination of positive pressure within the on-site building, an epoxied floor, and an active sub-slab depressurization system (a system that ventilates/removes the air beneath the building) are operating to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 7/27/2012 11:51:00 AM
Record Upd: 10/24/2012 4:34:00 PM
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: 06
Owner Name: Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

Owner Company:	Reckson Operating Partnership, L.P.
Owner Address:	225 BROADHOLLOW RD
Owner Addr2:	Not reported
Owner City,St,Zip:	MELVILLE, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	Reckson Operating Partnership, LP
Owner Address:	SEE LAST RECORD
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Farmingdale Public Library
Owner Address:	116 Merritts Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	V00152
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	TETRACHLOROETHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W1-0819-98-07(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	W1-0819-99-08(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RECKSON ASSOCIATES
Facility address:	333 SMITH ST FARMINGDALE, NY 117351106
EPA ID:	NYR000083600
Mailing address:	BROAD HOLLOW RD

RECKSON ASSOCIATES (Continued) **1001961566**

MELVILLE, NY 117470983
Contact: PHILLIP FALLON
Contact address: BROAD HOLLOW RD
MELVILLE, NY 117470983
Contact country: US
Contact telephone: (631) 662-6678
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: RECKSON OPER PARTNERSHIP LP
Owner/operator address: 225 BROAD HOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (631) 694-6900
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RECKSON OPER PARTNERSHIP LP
Owner/operator address: 225 BROAD HOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (631) 694-6900
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RECKSON ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 01/12/2000
Site name: RECKSON ASSOCIATES

RECKSON ASSOCIATES (Continued) **1001961566**

Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004560582

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001961566
Registry ID: 110004560582
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004560582

NY MANIFEST:
Country: USA
EPA ID: NYR000083600
Facility Status: Not reported
Location Address 1: 333 SMITH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000083600
Mailing Name: ROCKSON ASSC
Mailing Contact: MARIE K RANGEL
Mailing Address 1: 225 BROADHOLLOW RD

RECKSON ASSOCIATES (Continued) **1001961566**

Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6316226678

NY MANIFEST:

Document ID:	NYB2039310
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	TLA7668OH
Trans2 State ID:	Not reported
Generator Ship Date:	08/03/2000
Trans1 Recv Date:	08/03/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/04/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD005009923
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	13200
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Document ID:	CTF0901138
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	RG11135QC
Trans2 State ID:	Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

Generator Ship Date:	08/14/2000
Trans1 Recv Date:	08/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/14/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NY0000260828
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	T - Tons
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Document ID:	CTF0906018
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	QBCRM7309
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2000
Trans1 Recv Date:	08/10/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00

Document ID:	CTF0906020
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	QBCRM7314
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2000
Trans1 Recv Date:	08/10/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020

RECKSON ASSOCIATES (Continued) **1001961566**

Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Document ID:	CTF0906022
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	QBCRL3739
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2000
Trans1 Recv Date:	08/10/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Document ID:	CTF0906023
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	QBCRL3739
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2000
Trans1 Recv Date:	08/10/2000
Trans2 Recv Date:	Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

TSD Site Recv Date:	08/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00

Document ID:	CTF0906135
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	RR38550
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2000
Trans1 Recv Date:	08/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NY0000360829
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00

Document ID:	CTF0906136
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	QBLRL3739
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2000
Trans1 Recv Date:	08/10/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs

RECKSON ASSOCIATES (Continued) **1001961566**

Handling Method:	L Landfill.
Specific Gravity:	01.00
Document ID:	CTF0906137
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	RP42330
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2000
Trans1 Recv Date:	08/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NY0000260828
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Document ID:	CTF0906138
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	RR38549
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2000
Trans1 Recv Date:	08/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

RECKSON ASSOCIATES (Continued) **1001961566**

Generator EPA ID:	NYR000083600
Trans1 EPA ID:	NYD000260828
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00028
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
8 additional NY_MANIFEST: record(s) in the EDR Site Report.

88
NW
1/4-1/2
0.391 mi.
2064 ft.

WERE ASSOCIATES **NY LTANKS** **S104513868**
80 BAYLIS ROAD **N/A**
MELVILLE, NY

Relative:
Higher

Actual:
109 ft.

LTANKS:

Site ID:	220411
Spill Number/Closed Date:	8801432 / 1989-03-08
Spill Date:	1988-05-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-03-08
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-05-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

WERE ASSOCIATES (Continued) **S104513868**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-23
Spill Record Last Update:	2005-05-10
Spiller Name:	Not reported
Spiller Company:	WERE ASSOCIATES
Spiller Address:	100 JERICHO QUAD
Spiller City,St,Zip:	JERICHO, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	182316
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 03/08/89: F&N RETESTED SOUTH TANK AFTER AIR WAS BLED & SYS PASSED.DEC NOT PRESENT DURING RETEST.NORTH TANK REMOVED 7/1/88.APPROX 20 YDS OF CONT SOIL STOCKPILED & DISPOSED OF. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"2 TANKS 7500 EACH LEAKAGE RATE: -.231 GPH & -.236 GPH.F&N TESTER TO ISOLATE AND RETEST."

Material:

Site ID:	220411
Operable Unit ID:	918585
Operable Unit:	01
Material ID:	460578
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	220411
Spill Tank Test:	1533909
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

89
WNW
1/4-1/2
0.425 mi.
2242 ft.

CITICORP CREDIT SERVICE
135 DURYEA ROAD
MELVILLE, NY

NY LTANKS
NY Spills

S100491449
N/A

Relative:
Lower

Actual:
104 ft.

LTANKS:

Site ID:	247914
Spill Number/Closed Date:	9007825 / 1990-12-12
Spill Date:	1990-10-17
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1990-12-12
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	1990-10-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-19
Spill Record Last Update:	2009-07-20
Spiller Name:	RICHARD SCHALLE
Spiller Company:	CITICORP CREDIT SERVICE
Spiller Address:	135 DURYEA ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	331955
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 12/12/90: PASSED TANK ONLY TEST 11/9/90, SYSTEM RETEST 11/26. NO FURTHER ACTION. REMOVED MANWAY, REPLACED GASKETS, ALL PIPING REWORKED. "
Remarks:	"2-7500 TANKS FAILED. F&N TESTER"

Material:

Site ID:	247914
Operable Unit ID:	948480
Operable Unit:	01
Material ID:	431662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CITICORP CREDIT SERVICE (Continued) **S100491449**

Tank Test:

Site ID:	247914
Spill Tank Test:	1537722
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	247915
Spill Number/Closed Date:	9204935 / 1995-04-05
Spill Date:	1992-07-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	No spill occured. (Not Possible)
Cleanup Ceased:	1995-04-05
Cleanup Meets Standard:	True
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1992-07-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-03
Spill Record Last Update:	1995-04-06
Spiller Name:	Not reported
Spiller Company:	WE'RE ASSOC
Spiller Address:	100 JERICHO QUAD
Spiller City,St,Zip:	JERICHO, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	203555
DEC Memo:	""
Remarks:	"7500 FAILED PETROTITE, F&N TESTER,2-7500 EAST -.388, WEST -.250, PLAN TO INVESTIGATE & RETEST"

Material:

Site ID:	247915
Operable Unit ID:	968597
Operable Unit:	01
Material ID:	409178
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

CITICORP CREDIT SERVICE (Continued) **S100491449**

Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	247915
Spill Tank Test:	1540314
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0709659
Facility Type:	ER
DER Facility ID:	331955
Site ID:	390769
DEC Region:	1
Spill Date:	2007-12-07
Spill Number/Closed Date:	0709659 / 2008-07-11
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	dhraymon
Referred To:	Not reported
Reported to Dept:	2007-12-07
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-12-07
Spill Record Last Update:	2016-07-26
Spiller Name:	Not reported
Spiller Company:	HENRY SCHEIN CO
Spiller Address:	135 DURYEA ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	999
Contact Name:	STEVEN UCELLINI
Contact Phone:	(631) 234-2220
DEC Memo:	"ROUTINE REMOVAL OF 2-7500 GAL TANKS 12/07/07: CALLED JR HOLZMACHER-THE TANKS WERE OK. LESS THAN 1 GAL OF OIL LEAKED OUT OF A LINE DURING

CITICORP CREDIT SERVICE (Continued) **S100491449**

THE REMOVAL. APPROXIMATELY 8CY OF SOIL WAS REMOVED AND ENDPOINT SAMPLES WERE TAKEN. THE SUFFOLK COUNTY HEALTH DEPARTMENT(ZACH BALDWIN) WAS ON SITE. 12/13/07: Left message for Baldwin- requested copy of his report. 12/26/07: Again left message for Baldwin. 01/16/08: Baldwin left message- looking for the report. 01/31/08 (A): Received Holzmacher's report. ACCORDING TO THE REPORT, MIKE SEAMAN OF SCHD WAS ON SITE TO INSPECT THE FIRST TANK, AND BALDWIN REPLACED HIM TO INSPECT THE SECOND TANK. 01/31/08 (B): It said the tanks were 8,000gal each, not 7,500gal and were laying adjacent to each other. Both were reportedly intact, and endpoint samples were taken from the tank bed. The endpoint data was acceptable. 01/31/08 (C): The report also said an unused fill line was removed FROM ALONGSIDE THE TANKS, and it was from this line that the oil spilled."

Remarks: "while removing tank there was oil left in a line and it spilled out"

Material:

Site ID:	390769
Operable Unit ID:	1147864
Operable Unit:	01
Material ID:	2138338
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0308763
Facility Type:	ER
DER Facility ID:	331955
Site ID:	247913
DEC Region:	1
Spill Date:	2003-11-17
Spill Number/Closed Date:	0308763 / 2004-02-18
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	BXDONOVA
Referred To:	Not reported
Reported to Dept:	2003-11-17
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CITICORP CREDIT SERVICE (Continued) **S100491449**

Date Entered In Computer:	2003-11-17
Spill Record Last Update:	2011-06-03
Spiller Name:	CALLER
Spiller Company:	LIPA
Spiller Address:	333 EARLE OVINGTON BLVD
Spiller City,St,Zip:	UNIONDALE, NY -
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BRIAN D 11/18/03 TELECON TO SHAWN DAVIS, 300 GALLON TRANSFORMER 215 GALLONS RECOVERED, ESTIMATED 85 GALLONS SPILLED, SPILL CONTAINED IN PIT BELOW THE TRANSFORMER, 2 YARDS OF SOIL EXCAVATED, BOTTOMS SAMPLES TAKEN SPILL INTO CONTAINED PIT CLEANED BY TRADEWINDS. SAMPLES TAKEN, PCB AND ENDPOINT"
Remarks:	"pad mount transformerdeveloped leak at wire connection no pcb"

Material:

Site ID:	247913
Operable Unit ID:	874972
Operable Unit:	01
Material ID:	498684
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	85.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

90
North
1/4-1/2
0.433 mi.
2286 ft.

Relative:
Lower

Actual:
102 ft.

ESTEE LAUDER INC RESEARCH PARK **RCRA-SQG** **1000552223**
125 PINELAWN RD **NY LTANKS** **NYD986946184**
MELVILLE, NY 11747 **NY UST**
NY Spills
NY MANIFEST
NJ MANIFEST

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	ESTEE LAUDER INC RESEARCH PARK
Facility address:	125 PINELAWN RD MELVILLE, NY 11747
EPA ID:	NYD986946184
Mailing address:	S SERVICE RD MELVILLE, NY 11747
Contact:	JAMES MEYERS
Contact address:	S SERVICE RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(516) 454-5333
Contact email:	Not reported
EPA Region:	02
Land type:	Private

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: ESTEE LAUDER INC
Owner/operator address: 125 PINELAWN RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (516) 531-1173
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ESTEE LAUDER INC
Owner/operator address: 125 PINELAWN RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: (516) 531-1716
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ESTEE LAUDER INC RESEARCH PARK
Classification: Small Quantity Generator

Date form received by agency: 04/25/1994
Site name: ESTEE LAUDER INC RESEARCH PARK
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/10/2001
Date achieved compliance: 01/13/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/24/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 07/02/1992
Date achieved compliance: 08/10/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/02/1992
Date achieved compliance: 08/10/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Evaluation date: 01/10/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/13/2001
Evaluation lead agency: EPA

Evaluation date: 05/15/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/10/1992
Evaluation lead agency: State

Evaluation date: 05/15/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 08/10/1992
Evaluation lead agency: State

LTANKS:
Site ID: 160346
Spill Number/Closed Date: 9212267 / 1993-02-03
Spill Date: 1993-01-28
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 1993-02-03
Cleanup Meets Standard: True
SWIS: 5200
Investigator: RICE
Referred To: Not reported
Reported to Dept: 1993-01-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-01-29
Spill Record Last Update: 2002-09-17
Spiller Name: Not reported
Spiller Company: MEENAN OIL
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 135416
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RICE 02/03/93: DEC ON SITE, NO DRAINAGE AFFECTED, CLEANUP SATISFACTORY, MEENAN CLEANING UP SPILL. "
Remarks: "AT ESTEE LAUDER INC."

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Material:

Site ID:	160346
Operable Unit ID:	979252
Operable Unit:	01
Material ID:	402120
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	05089
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	11/30/2015
Owner/Storage Information:	AVAILABLE

Facility Info:

Site Ref#:	05089
Billing Contact:	ESTEE LAUDER INC ATTN S TAIANI
Billing Address:	350 SOUTH SERVICE RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	ESTEE LAUDER INC ATTN S TAIANI
Storage Owner Address:	350 SOUTH SERVICE RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	05089
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/20/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	1000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1000 gallons
Date Permitted:	06/12/1991
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	ABOVEGROUND/UNDERGROUND COMBINATION
Pipe Type:	COPPER
Pipe External Protection:	FIBERGLASS (FRP)
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE ONLY
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/20/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

SPILLS:

Facility ID:	9700756
Facility Type:	ER
DER Facility ID:	263498
Site ID:	327342
DEC Region:	1
Spill Date:	1997-04-16
Spill Number/Closed Date:	9700756 / 1998-06-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5200
Investigator:	BPAUSTIN
Referred To:	Not reported
Reported to Dept:	1997-04-17
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-17

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Spill Record Last Update:	1998-06-10
Spiller Name:	TOM MUCCIO
Spiller Company:	LILCO
Spiller Address:	100 OLD COUNTRY ROAD
Spiller City,St,Zip:	HICKVILLE, NY 11714-
Spiller Company:	001
Contact Name:	TOM MUCCIO
Contact Phone:	(516) 391-6406
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN CLEANUP BY LILCO"
Remarks:	"LEAKING BUSHING"

Material:

Site ID:	327342
Operable Unit ID:	1043405
Operable Unit:	01
Material ID:	337336
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

NY MANIFEST:

Country:	USA
EPA ID:	NYD986946184
Facility Status:	Not reported
Location Address 1:	125 PINE LAWN RD RESEARCH LAB
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	HUNTINGTON
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986946184
Mailing Name:	ESTEE LAUDER INC RESEARCH PARK
Mailing Contact:	DEBORAH LASKE
Mailing Address 1:	350 SOUTH SERVICE ROAD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164547033

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000718515VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1240
Units:	P - Pounds
Number of Containers:	31
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000718515VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	280
Units:	P - Pounds
Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	F005
Waste Code 1_3:	D022
Waste Code 1_4:	F003
Waste Code 1_5:	D001
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Tracking Number:	000718515VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2160
Units:	P - Pounds
Number of Containers:	54
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	F005
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000718515VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	5
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D001
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2015
Trans1 Recv Date:	08/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000845215VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Quantity:	80
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	F005
Waste Code 1_3:	D022
Waste Code 1_4:	F003
Waste Code 1_5:	D001
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2015
Trans1 Recv Date:	08/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000845216VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	240
Units:	P - Pounds
Number of Containers:	6
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	F005
Waste Code 1_3:	D022

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Waste Code 1_4:	F003
Waste Code 1_5:	D001
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2015
Trans1 Recv Date:	08/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000845216VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D001
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2015
Trans1 Recv Date:	08/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000845216VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2040
Units:	P - Pounds
Number of Containers:	51
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	F005
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2015
Trans1 Recv Date:	08/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000845216VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2120
Units:	P - Pounds
Number of Containers:	53
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	U134
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D002
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/2015
Trans1 Recv Date:	05/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000847258VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
478 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYD986946184
Mail Address:	S SERVICE RD
Mail City/State/Zip:	MELVILLE, NY 11747
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JAMES MEYERS
Comments:	Not reported
SIC Code:	Not reported
County:	NY103
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	4
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	11
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000847258VES
EPA ID:	NYD986946184
Date Shipped:	5/21/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	5/21/2015
Waste SEQ ID:	3
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Accepted:	5/21/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000346889VES
EPA ID:	NYD986946184
Date Shipped:	04/27/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	10 P
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	120 P

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Year: Not reported
Waste Code: U134
Hand Code: H141
Quantity: 8 P

Manifest Year: Not reported
Waste Code: D003
Hand Code: H141
Quantity: 1 P

Manifest Year: Not reported
Waste Code: U044
Hand Code: H141
Quantity: 16 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 18 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 1 P

Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 120 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 34 P

Manifest Year: Not reported
Waste Code: F003
Hand Code: H141
Quantity: 1840 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 80 P

Manifest Year: Not reported
Waste Code: D011
Hand Code: H141
Quantity: 9 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 68 P

Manifest Year: Not reported
Waste Code: D009

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Hand Code:	H141
Quantity:	3 P
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	420 P
Manifest Year:	Not reported
Waste Code:	D003
Hand Code:	H141
Quantity:	28 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	30 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	160 P
Manifest Year:	Not reported
Waste Code:	D003
Hand Code:	H141
Quantity:	6 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	20 P
Manifest Number:	000969575VES
EPA ID:	NYD986946184
Date Shipped:	2/13/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/13/2015
Waste SEQ ID:	6
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/19/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000969575VES
EPA ID:	NYD986946184
Date Shipped:	2/13/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/13/2015
Waste SEQ ID:	8
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Accepted:	2/19/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	7
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	9
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000972658VES
EPA ID:	NYD986946184
Date Shipped:	3/20/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/20/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/20/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000847258VES
EPA ID:	NYD986946184
Date Shipped:	5/21/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	5/21/2015
Waste SEQ ID:	5
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Waste Type Code 6:	Not reported
Date Accepted:	5/21/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000845216VES
EPA ID:	NYD986946184
Date Shipped:	8/24/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	8/24/2015
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	8/24/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000845216VES
EPA ID:	NYD986946184
Date Shipped:	8/24/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	8/24/2015
Waste SEQ ID:	3
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	8/24/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000530677VES
EPA ID:	NYD986946184
Date Shipped:	10/28/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	U151
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	30.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	920.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	200.00 Pounds
Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	240.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Hand Code:	H141
Quantity:	400.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	40.00 Pounds
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000972871VES
EPA ID:	NYD986946184
Date Shipped:	3/20/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/20/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/20/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000718515VES
EPA ID:	NYD986946184
Date Shipped:	5/12/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	5/12/2015
Waste SEQ ID:	2
Waste Type Code 2:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	5/12/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000845216VES
EPA ID:	NYD986946184
Date Shipped:	8/24/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	8/24/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	8/24/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	11/10/2015
Waste SEQ ID:	8
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/10/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000718515VES
EPA ID:	NYD986946184
Date Shipped:	5/12/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	5/12/2015
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	5/12/2015
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

91
South
1/4-1/2
0.463 mi.
2446 ft.

CANTOR BROTHERS **NY SHWS** **S104541575**
50 ENGINEERS LANE **NY VAPOR REOPENED** **N/A**
EAST FARMINGDALE, NY 11735 **NY VCP**
NY Spills

Relative:
Lower

Actual:
99 ft.

SHWS:

Program:	HW
Site Code:	57868
Classification:	Site is properly closed - requires continued management.
Region:	1
Acres:	3.2
HW Code:	152021
Record Add:	11/18/1999
Record Upd:	05/20/2016
Updated By:	JBSWARTO

Site Description: Location: The former Cantor Brothers Site is located at 55 Engineers Lane in Suffolk County, the Town of Babylon in the unincorporated Hamlet of East Farmingdale. Site Features: The former Cantor Brothers Site (site) was a chemical repackaging and handling facility that had been in operation since 1964. The facility building is located in a flat, industrial park setting.Current Zoning/Use: The zoning for this site is commercial/industrial and residential use in this area is prohibited by the Town of Babylon. The former Cantor Building is surrounded by manufacturing and commercial facilities. The current use of the property is warehousing.Past Use(s) of the Site: Substances including organic solvents, creosote and fuel oils were previously observed on the ground surface as a result of leaks from drums and storage tanks. Site inspections by the Suffolk County Department of Health Services (SCDHS) documented numerous spills, illegal discharges and improper storage conditions beginning in 1980. SCDHS arranged to have five monitoring wells installed near the

CANTOR BROTHERS (Continued) **S104541575**

southern boundary of the site. Phase I and Phase II Investigations were completed. Operations at the facility ceased in 1990 and the Responsible Party filed for bankruptcy in 1993.An Interim Remedial Measure (IRM) Investigation was completed in 1997, after the NYS Attorney General's Office represented the NYSDEC in Bankruptcy Court seeking funding for the investigation. The final IRM Summary Report lead to a final agreement and a Stipulated Order for final site remediation. Money totaling $200,000 from the bankruptcy proceedings was set aside in escrow to cover the storm drain cleaning and soil vapor extraction (SVE) remediation programs at the site. These activities were completed using escrow monies under the SSF program. The SVE system operated from 1998 until 2001. The storm drain cleaning was completed in 1998. A Record of Decision was signed in March of 2000. Remedial work involved the removal of soils contaminated with semi-volatile organic compounds from discrete locations on the south side of the building. Installation of a sub-slab depressurization system was completed in 2005. This system ran for eight years and was subsequently removed by new tenants in 2013. All the adjacent buildings have been investigated for the potential for soil vapor intrusion (VI) under the adjacent Minmilt Realty Site (DEC Site No. 152147). There are no VI impacts to these buildings. A Voluntary Cleanup Agreement (VCA), signed by the current owner, is the mechanism currently being utilized to manage the site (i.e., long-term site management). Site Geology and Hydrogeology: The site is located on the glacial outwash plain of the south shore of Long Island. The underlying formation consists mainly of fine sands intermixed, at varying depths of low permeability units, mainly of clay, that exist in continuous and non-continuous segments. The shallow groundwater aquifer is known as the Upper Glacial Aquifer. This overlies the next significant hydro-geologic unit known as the Magothy Aquifer. General groundwater flow is to the south southeast.

Env Problem: Remediation at the site is complete and there are no environmental concerns associated with this site. Prior to remediation, the primary contaminants of concern were non-chlorinated volatile organic compounds.A Site Management Plan has been developed and approved and is implemented under the Voluntary Cleanup Program (ref. Site ID No. V00193).

Health Problem: Soil vapor intrusion is a process by which contaminants in the soil vapor (air spaces within the soil), may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Given the levels of volatile organic compounds detected beneath the on-site building, there is a potential for people to inhale site-related contaminants in indoor air through soil vapor intrusion. However, sampling results indicate the levels detected in indoor air are commonly found in similar structures and do not represent a current health concern. Monitoring of the on-site structure will continue to ensure that the indoor air quality is not impacted. Sampling indicates that soil vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1975
Disp Term: 1990

CANTOR BROTHERS (Continued) **S104541575**

Lat/Long:	40:45:20:0 / 73:24:17:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	5/11/2015 10:40:00 AM
Updated By:	SXSCHARF
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CANTOR BROTHERS, INC.
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	DOCUMENT REPOSITORY
Owner Address:	HALF HOLLOW HILLS LIBRARY
Owner Addr2:	55 VANDERBILT PARKWAY
Owner City,St,Zip:	DIX HILLS, NY 11746
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	LJM Associates
Owner Address:	50 Engineers Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	MATTHEW MILLER
Owner Company:	CANTOR BROTHERS, INC.
Owner Address:	ENGINEERS LANE, P.O. BOX 126
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Cantor Brothers, Inc.
Owner Address:	50 Engineers Lane / PO Box 126
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	152021
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	ORGANIC SOLVENTS, FUEL OILS, CREOSOTE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	CREOSOTE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

CANTOR BROTHERS (Continued) **S104541575**

HW Code: 152021
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152021
Waste Type: TETRACHLOROETHYLENE (PCE OR "PERC.")
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152021
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152021
Waste Type: TRICHLOROETHYLENE {(TCE) (U228- FOO1)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152021
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD001367150
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

VAPOR REOPENED:
Site Code: 152021
Facility Status: Complete (Mitigate)

VCP:
Program Type: VCP
Site Code: 57869
HW Code: V00193
Site Class: A
SWIS: 5220
Region: 1
Town: Babylon
Acres: 3.2
Date Record Added: 11/30/2000
Date Record Updated: 05/20/2016
Updated By: JBSWARTO
Site Description: This site was a Class 2 Registry site (#152021) at the time of the Volunteer's (LJM Associates) application. Cantor Brothers was a chemical repackaging and handling facility until 1990. The PRP filed for Bankruptcy in 1993. The site is surrounded by manufacturing and commercial facilities. It consisted of a building with drum storage areas, and 16 underground tanks. Organic solvents, creosote, and fuel oils have been observed leaking from drums and storage tanks at the facility. Numerous spills, illegal discharges, and improper storage conditions have been documented since 1980. Investigation showed the presence of VOC soil contamination. The NYSDEC obtained $200,000 in contractual funds from Bankruptcy Court settlement to to cover storm drain cleaning and soil vapor extraction (SVE) remediation. LJM Associates, the new owner, entered the Voluntary Program to take over

CANTOR BROTHERS (Continued) **S104541575**

O&M of the SVE system upon depletion of the contractual escrow funds.The SVE system operated since its construction in 1998 until 2001. The storm drain cleaning was completed in 1998. A Record of Decision was signed in March of 2000. Remedial work since that time has involved the removal of soils contaminated with semivolatile organic compounds from discrete locations on the south side of the building. Installation of a sub-slab depressurization system was completed in 2005. The volunteer submitted a revised work plan to test whether the SSD system is still required. The consultant hired by the volunteer completed the soil Vapor Investigation (SVI) and the SVI report was approved by the DEC (11/2014). The subsequent Voluntary Cleanup Agreement (VCA) sampling included the necessary confirmatory sampling of the sub-slab depressurization (SSD) system to allow for the site reclassification determination. The Minmilt Realty site is adjacent to the former Canotor Brothers building. Monitoring for soil vapor and tersting adjacent buildings for soil vapor intrusion fell under the Minmilt Realty site. Therefore, this has been addressed.

Env Problem: Organic solvents, fuel oil and creosote leaked from drums and tanks and contaminated soils and drywells on site. The contaminated storm drains were addressed by excavation and removal of contaminated sediments. Contaminated soils beneath and near the site building were addressed by a soil vapor extraction (SVE) system. A sub-slab depressurization (SSD) system was installed in the building to prevent soil vapor intrusion. The system ran its course and was dismantled by a recent tenant. A site monitoring plan is being put in place by the volunteer.

Health Problem: Soil vapor intrusion is a process by which contaminants in the soil vapor (air spaces within the soil), may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Given the levels of volatile organic compounds detected beneath the on-site building, there is a potential for people to inhale site-related contaminants in indoor air through soil vapor intrusion. However, sampling results indicate the levels detected in indoor air are commonly found in similar structures and do not represent a current health concern. Monitoring of the on-site structure will continue to ensure that the indoor air quality is not impacted. Sampling indicates that soil vapor intrusion is not a concern for off-site structures.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: ZZZ
Owner Name: BRUCE ZABARAUSKAS
Owner Company: APPLE BANK FOR SAVINGS
Owner Address: 805 THIRD AVE.

CANTOR BROTHERS (Continued) **S104541575**

Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10022
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 01
Owner Name: Not reported
Owner Company: LJM Associates, Inc.
Owner Address: 139 Carmen Avenue
Owner Addr2: Not reported
Owner City,St,Zip: East Rockaway, NY 11510-1302
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Not reported
Owner Company: LJM Associates
Owner Address: 139 Carmen Avenue
Owner Addr2: Not reported
Owner City,St,Zip: East Rockaway, NY 11510-1302
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Linda Montgomery
Owner Company: LJM Associates
Owner Address: 139 Carmen Avenue
Owner Addr2: Not reported
Owner City,St,Zip: East Rockaway, NY 11510-1302
Owner Country: United States of America
HW Code: V00193
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0830-98-10(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS

SPILLS:
Facility ID: 8605691
Facility Type: ER
DER Facility ID: 96642
Site ID: 110231
DEC Region: 1
Spill Date: 1985-12-09
Spill Number/Closed Date: 8605691 / 1987-01-20
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 5220
Investigator: CXONEILL
Referred To: Not reported
Reported to Dept: 1986-12-09
CID: Not reported
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Fire Department
Cleanup Ceased: 1987-01-20

CANTOR BROTHERS (Continued) **S104541575**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-17
Spill Record Last Update:	2005-08-29
Spiller Name:	Not reported
Spiller Company:	HETEM TRUCKING
Spiller Address:	601 COMMERCE ROAD
Spiller City,St,Zip:	LINDEN, NJ 07036
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'NEILL FD / / : FD REQUESTS DEC TO RESPOND. MPC HIRED BY SPILLER,473 GALS LIQ RECOVERED. 1/2 YDS SPEEDI DRY. SCDH NOTIFIED.12/9/86 SATISFACTORILY CLEANED. 10/10/95: This is additional information about material spilled from the translation of the old spill file: MINERAL SPIRITS. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	""

Material:

Tank Test:

92
SSW
1/4-1/2
0.480 mi.
2534 ft.

Relative:
Lower

Actual:
97 ft.

FORMERLY EMBASSY INDUSTRIES INC **1000158277**
300 SMITH ST
FARMINGDALE, NY 11735

NY LTANKS
NY AST **NYD001217520**
NY Spills
RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

LTANKS:

Site ID:	144684
Spill Number/Closed Date:	9100457 / 1991-07-22
Spill Date:	1991-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1991-07-22
Cleanup Meets Standard:	True
SWIS:	5220
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	1991-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-04-15

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Spill Record Last Update:	2015-09-10
Spiller Name:	LEON FELDMAN
Spiller Company:	EMBASSY INDUSTRIES
Spiller Address:	300 SMITH STREET
Spiller City,St,Zip:	FARMINGDALE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	371075
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 06/25/91: PIPING REPLACED. SYSTEM RETESTED, PASSED AT -.007 ON 6/3/91. NO FURTHER ACTION."
Remarks:	"10K FAILED AT -.159. PETROTITE SYSTEM TEST. BONAFIDE TESTER"

Material:

Site ID:	144684
Operable Unit ID:	953999
Operable Unit:	01
Material ID:	426653
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	144684
Spill Tank Test:	1538444
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	00591
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00591
Billing Contact:	Not reported
Billing Address:	Not reported

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	EMBASSY INDUSTRIES INC
Storage Owner Address:	300 SMITH ST
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00591
Facility Reference #:	01120
Township:	BABYLON
Tax Map No:	0100
Region:	SUFFOLK

Tank ID:	4
Tank Key:	2095
Year Installed:	Not reported
Substance:	VANISHING OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	022702
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	5
Tank Key:	2096
Year Installed:	2002
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	022702
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000000660
Date Permitted:	Not reported

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

SPILLS:

Facility ID:	0308038
Facility Type:	ER
DER Facility ID:	273097
Site ID:	144683
DEC Region:	1
Spill Date:	2003-10-30
Spill Number/Closed Date:	0308038 / 2005-02-16
Spill Cause:	Traffic Accident
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-10-30
CID:	201
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2015-09-05
Spiller Name:	SEAN DAVIS
Spiller Company:	LIPA
Spiller Address:	333 EARLR OVINGTON BLVD
Spiller City,St,Zip:	UNIONDALE, NY -
Spiller Company:	001
Contact Name:	SEAN DAVIS
Contact Phone:	(516) 545-5589
DEC Memo:	"TRADEWINDS HIRED, NON PCB, TRADEWINDS ON SITE, NO STORM DRAINS, CONTAINED IN 10' X 12' CEMENT BLOCK BLDG"
Remarks:	"PASSANGER VEH STRUCK VAULT CAUSING SPILL. SPILL CONTAINED AND CLEAN UP SHOULD BEGIN AROUND 0900. "

Material:

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Site ID:	144683
Operable Unit ID:	874369
Operable Unit:	01
Material ID:	562807
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0110146
Facility Type:	ER
DER Facility ID:	371075
Site ID:	144682
DEC Region:	1
Spill Date:	2002-01-22
Spill Number/Closed Date:	0110146 / 2003-01-17
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5220
Investigator:	BXDONOVA
Referred To:	Not reported
Reported to Dept:	2002-01-22
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-22
Spill Record Last Update:	2015-09-05
Spiller Name:	GEORGE DEMOTT
Spiller Company:	EMBASSY INDUSTRIES
Spiller Address:	300 SMITH STREET
Spiller City,St,Zip:	FARMINGDALE, ZZ
Spiller Company:	001
Contact Name:	GEORGE DEMOTT
Contact Phone:	(631) 694-1800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BRIAN D PER SELINGER-SURFACE SPILL TO BE EXCAVATED TOMORROW, NCDH WILL BE ON SITE FOR THE INSTALLATION OF A NEW TANK. SELINGER TO CALL ON 1/22/02 WITH UPDATE CONTAMINATED SOIL ASSOCIATED WITH FILL PIPE EXCAVATED BY WINDMILL, 10K FUEL OIL TANK REMOVED, EXCAVATION APPEARED TO BE CLEAN BY SCHD WHO WAS ON SITE 1/23/02"
Remarks:	"fill pipe broke at the tank - unk amount spilled"

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Material:

Site ID:	144682
Operable Unit ID:	848629
Operable Unit:	01
Material ID:	527778
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

RCRA NonGen / NLR:

Date form received by agency:	03/10/2008
Facility name:	FORMERLY EMBASSY INDUSTRIES INC
Facility address:	300 SMITH ST FARMINGDALE, NY 117351175
EPA ID:	NYD001217520
Mailing address:	BROADHOLLOW RD - SUITE 100 MELVILLE, NY 11747
Contact:	BRYAN A DEVAUX
Contact address:	BROADHOLLOW RD - SUITE 100 MELVILLE, NY 11747
Contact country:	US
Contact telephone:	(631) 878-9242
Contact email:	BRYAND@PWGROSSE.COM
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	P & F INDUSTRIES
Owner/operator address:	BROADHOLLOW RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	09/01/1964
Owner/Op end date:	Not reported

Owner/operator name:	P & F INDUSTRIES
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Owner/Op start date: 09/01/1964
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Historical Generators:
Date form received by agency: 03/09/2008
Site name: FORMERLY EMBASSY INDUSTRIES INC
Classification: Small Quantity Generator

Date form received by agency: 05/25/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Date form received by agency: 05/24/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 04/14/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Large Quantity Generator

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Date form received by agency: 07/08/1999

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 06/23/1986
Site name: EMBASSY INDUSTRIES INC
Classification: Large Quantity Generator

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/27/1995
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 09/27/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004332623

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000158277
Registry ID: 110004332623
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004332623

NY MANIFEST:
Country: USA
EPA ID: NYD001217520
Facility Status: Not reported
Location Address 1: 300 SMITH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001217520
Mailing Name:	EMBASSY INDUSTRIES INCORPORATED
Mailing Contact:	EMBASSY INDUSTRIES INCORPORATED
Mailing Address 1:	315 OSER AVE
Mailing Address 2:	Not reported
Mailing City:	HAUPPAUGE
Mailing State:	NY
Mailing Zip:	11788
Mailing Zip 4:	3607
Mailing Country:	USA
Mailing Phone:	5166941800

NY MANIFEST:

Document ID:	NYC7127381
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	NYJE5256
Trans2 State ID:	7474GLNJ
Generator Ship Date:	05/13/2003
Trans1 Recv Date:	05/13/2003
Trans2 Recv Date:	05/20/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001217520
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00440
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Specific Gravity:	01.00
Document ID:	NYA3073127
Manifest Status:	K
seq:	Not reported
Year:	1986
Trans1 State ID:	25391-GTN
Trans2 State ID:	Not reported
Generator Ship Date:	08/13/1986
Trans1 Recv Date:	08/13/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/13/1986
Part A Recv Date:	09/15/1986
Part B Recv Date:	08/22/1986
Generator EPA ID:	NYD001217520
Trans1 EPA ID:	NYD980526024
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980526024
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00495
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	078
Document ID:	NYG4265541
Manifest Status:	Not reported
seq:	01
Year:	2006
Trans1 State ID:	NYF006000053
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/2006
Trans1 Recv Date:	05/10/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001217520

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Trans1 EPA ID:	RP52906PQ
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDD980756415
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D027 - 1,4-DICHLOROBENZENE 7.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	17838
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

93
South
1/2-1
0.510 mi.
2692 ft.

Relative:
Lower

Actual:
98 ft.

TRONIC PLATING CO., INC.
168 CENTRAL AVENUE
FARMINGDALE, NY 11735

Delisted NPL **1009968611**
SEMS **NYD002059517**
CORRACTS
US ENG CONTROLS
RCRA NonGen / NLR
ROD
ICIS

Delisted NPL:

EPA ID:	NYD002059517
Site ID:	201346
EPA Region:	2
Federal:	No
Deleted Date:	2001-10-14 00:00:00
Latitude:	40.753799999999998
Longitude:	-73.407700000000006

Category Details:

NPL Status:	Deleted from the Final NPL
Category Description:	Depth To Aquifer-> 25 And <= 50 Feet
Category Value:	31

NPL Status:	Deleted from the Final NPL
Category Description:	Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value:	10

TRONIC PLATING CO., INC. (Continued) **1009968611**

Site Details:
Site Name: TRONIC PLATING CO., INC.
Site Status: Deleted
Site Zip: 11735
Site City: FARMINGDALE
Site State: NY
Federal Site: No
Site County: SUFFOLK
EPA Region: 02
Date Proposed: 10/15/84
Date Deleted: 10/15/2001
Date Finalized: 06/10/86

Substance Details:
NPL Status: Deleted from the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Deleted from the Final NPL
Substance ID: C151
Substance: IRON AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: C178
Substance: COPPER AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: C247
Substance: ZINC AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: D006
Substance: CADMIUM (CD)
CAS #: 7440-43-9
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: D008
Substance: LEAD (PB)
CAS #: 7439-92-1
Pathway: GROUND WATER PATHWAY
Scoring: 3

TRONIC PLATING CO., INC. (Continued) **1009968611**

NPL Status: Deleted from the Final NPL
Substance ID: D011
Substance: SILVER
CAS #: 7440-22-4
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: P030
Substance: CYANIDES (SOLUBLE SALTS)
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: W001
Substance: HEAVY METALS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

Summary Details:

Conditions at proposal October 15, 1984): Tronic Plating Co., Inc. occupies 0.5 acre in Farmingdale, New York. The site is in southwestern Suffolk County, approximately l.5 miles east of the Nassau County line. Tronic occupies the southeast corner of a long building in an industrial park area. The site consists of the building, two inside above-ground storage tanks, four underground leaching pools, and a storm drain in the paved area to the northeast of the building. Tronic hasprovided electroplating and anodi ing services to the electronics industry since July 1968. State and county authorities have determined that ha ardous wastes, consisting primarily of heavy metals, were discharged from storage tanks and leaching pools on the site. The State issued a Pollutant Discharge Elimination System permit to Tronic on April l, l980. In June l980, the State issued a Consent Order to Tronic for discharging industrial wastes to ground water from leaching pools. Tronic agreed to obtain a permit and clean out the leaching pools. Tests conducted by the State on one of the leaching pools detected copper, silver, iron, inc, lead, and cadmium. Heavy metals also were detected in the storm drain. The site is in a generally flat area with an average slope of less than 3 percent. There is no surface water in the vicinity. The surrounding area is paved, and run-off flows to existing storm drains. The site is surrounded by manufacturing and commercial facilities. Large cemeteries are located to the south and east. Wells within 3 miles of the site provide drinking water to about l6,000 people and are the only water supply in the area. Status June 10, 1986): EPA is considering various alternatives for this site.

Site Status Details:
NPL Status: Deleted
Proposed Date: 10/15/1984
Final Date: 06/10/1986
Deleted Date: 10/15/2001

Narratives Details:
NPL Name: TRONIC PLATING CO., INC.
City: FARMINGDALE
State: NY

TRONIC PLATING CO., INC. (Continued) **1009968611**

SEMS:
Site ID: 201346
EPA ID: NYD002059517
Federal Facility: N
NPL: Deleted from the Final NPL
Non NPL Status: Not reported

Following information was gathered from the prior CERCLIS update completed in 10/2013:
Site ID: 0201346
EPA ID: NYD002059517
Facility County: SUFFOLK
Short Name: TRONIC PLATING CO., INC
Congressional District: 02
IFMS ID: 02R6
SMSA Number: 5380
USGC Hydro Unit: 02030202
Federal Facility: Not a Federal Facility
DMNSN Number: 0.50000
Site Orphan Flag: N
RCRA ID: Not reported
USGS Quadrangle: Not reported
Site Init By Prog: Not reported
NFRAP Flag: Not reported
Parent ID: Not reported
RST Code: Not reported
EPA Region: 02
Classification: Manufacturing Plant
Site Settings Code: SU
NPL Status: Deleted from the Final NPL
DMNSN Unit Code: ACRE
RBRAC Code: Not reported
RResp Fed Agency Code: Not reported
Non NPL Status: Not reported
Non NPL Status Date: / /
Site Fips Code: 36103
CC Concurrence Date: 09/27/93
CC Concurrence FY: 1993
Alias EPA ID: Not reported
Site FUDS Flag: Not reported

CERCLIS Site Contact Name(s):
Contact ID: 2000172.00000
Contact Name: GLORIA SOSA
Contact Tel: (212) 637-4283
Contact Title: Remedial Project Manager (RPM)
Contact Email: SOSA.GLORIA@EPA.OGV

CERCLIS Site Alias Name(s):
Alias ID: 101
Alias Name: TRONIC PLATING COMPANY, INC
Alias Address: Not reported
SUFFOLK, NY
Alias ID: 102
Alias Name: TRONIC PLATING CO., INC
Alias Address: Not reported
NY

TRONIC PLATING CO., INC. (Continued) **1009968611**

Alias ID: 103
Alias Name: TRONIC PLATING CO., INC.
Alias Address: 168 CENTRAL AVENUE
FARMINGDALE, NY 11735
Alias Comments: Not reported
Site Description: The Tronic Plating Company Site (Site) is located at 168 Central Avenue in Farmingdale, Town of Babylon, Suffolk County, Long Island, New York. The Site occupies the southeast portion of a building owned by Commerce Holding Company, Inc. situated on Commerce Drive and the surrounding property, an area of approximately 7,200 square feet within a 117,000 square-foot lot. This Site is a rectangular, flat, commercially developed property. With the exception of a 50 by 75 foot landscaped front lawn, the area surrounding the building at the Site is paved for parking and shipping access. The southern boundary of the Site is the southern edge of the front lawn adjacent to Central Avenue. The Site surroundings consist of light industrial businesses to the north, west, and northeast. The Pinelawn Cemetery is located to the south and southeast. A wooded area owned by the Pinelawn Cemetery and separated from the Site by Central Avenue and an industrial lot, is located approximately 500 feet to the south. The area north of the Site, lower Melville, has no municipal sewer service and virtually all industries discharge their wastewater to ground-water infiltration systems, thereby impacting the ground-water quality in the area. The relatively level surface of the Site slopes gently to the south-southeast at a grade of approximately 3 percent. Except for the lawn, the Site surface is primarily impermeable given the presence of the building and paved areas. Surface water from precipitation drains from the building and the paved areas into a system of 12 storm drains located along the parking area (Commerce Drive). There are 3 major aquifers underlying the Site. These are: the unconfined Upper Glacial aquifer; the semi-confined Magothy aquifer; and, the confined Lloyd Sand aquifer. The total thickness of these three aquifers beneath the Site is approximately 1,200 feet. The two aquifers of environmental concern for this Site are the Upper Glacial and the Magothy, since the Lloyd Sand is a deep aquifer (1000 feet) and not hydrogeologically connected to the above aquifers. Studies have indicated that the Upper Glacial and Magothy aquifers may be hydrogeologically connected under the Site. The Magothy aquifer is totally dependent upon downward percolating rainfall and recharge from the overlying Upper Glacial deposits for its surface replenishment. The Raritan Formation of Late Cretaceous age is the deepest geologic formation of unconsolidated deposits beneath the Site. It rests directly on the crystalline bedrock and is overlain by the Magothy Formation. The Raritan Formation occurs beneath the entire area of Long Island but does not outcrop near the Site or within Suffolk County. Formation thickness ranges from 300 to 600 feet. The Raritan Formation is divided into a lower unit, the Lloyd Sand aquifer, and the upper unit, the Raritan Clay. The Raritan Clay functions as an aquiclude, separating the groundwater within the Lloyd Sand from the groundwater within the overlying Magothy Formation. Beneath the Site, the Lloyd Sand is approximately 200 to 300 feet thick and the relatively impermeable Raritan Clay is approximately 175 feet thick. The direction and relatively rapid rate of shallow (near the water table) ground-water flow beneath the Site is southerly at approximately 2 feet per day. This information was developed from a series of water level measurements collected from piezometers installed on-site and agrees with literature describing the hydrologic conditions for the area. The water table at the Site was found to be between 28 to 35 feet below the surface. Groundwater supplies the public and private needs of the entire population of Suffolk County. The two most commonly tapped aquifers for water supply purposes are the Upper Glacial and the Magothy. The Magothy aquifer is the primary source of potable drinking water in the area of the Site. Two water companies purvey water pumped from municipal wells to the homes and businesses

TRONIC PLATING CO., INC. (Continued) **1009968611**

in the vicinity of the Site. The East Farmingdale Water District supplies the businesses at the Site as well as areas to the south. The Suffolk County Water Authority also supplies some areas to the south of the Site. Each municipal supply well generally supplies one million gallons or more per day when in full-scale operation. All of the local public supply wells are advanced to and completed within the Magothy aquifer. The nearest municipal well field is located partially downgradient at 0.9 miles southwest of the Site. The ground-water flow is to the south. Another municipal supply well is located 2.4 miles south (downgradient) of the Site and a third municipal well field is located partially downgradient at 2.8 miles south-southeast of the Site. Private wells exist in the Site vicinity; these are completed within either the upper Magothy or the Upper Glacial aquifer. Some are used to supply drinking water to businesses, but most are used for irrigation or for process and cooling water. The nearest private well used for drinking water supply services an office at the St. Charles Cemetery and is located partially downgradient at 0.9 miles south-southwest of the Site. Wells located downgradient closer to the Site are solely used for irrigation. The Tronic Plating Company, Inc. operated an electroplating and metal anodizing facility at the Site from July 1968 to March 1984. The facility was serviced by 4 industrial leaching pools, 1 sanitary leaching pool and 1 drywell. The 4 industrial pools are located below the front lawn of the building, and the sanitary pool is located under the driveway adjacent to the front lawn. The dry well (a former sanitary leaching pool that was disconnected from the building) is located in the rear of the former Tronic facility. There are 3 on-site storm drains, with 2 overflow drains, located in the driveway adjacent to the building and the front lawn. The Suffolk County Department of Health Services (SCDHS) records indicate that in November 1983, the Tronic Plating Company arranged to pump out, clean, and backfill the industrial leaching pools. There was no indication that the Tronic Plating Company removed the contents of the storm drains, sanitary leaching pool, or drywell. Also, during 1983 the building on the Site was connected to the Suffolk County municipal sewer system. In March and April of 1984, the Tronic Plating Company ceased operating at the Site and moved its facility to Nassau County. Approximately 1.25 million gallons of waste water were produced by the Tronic Plating Company each year. The sources of these wastes were rinse waters from the electroplating, anodizing and etching processes. Between 1972 and 1982, the SCDHS collected and performed chemical analyses of fluid samples collected from the Tronic Plating Company's industrial discharges, as well as from the on-site leaching pools and an on-site storm drain. The analyses indicated the presence of metals (cadmium, chromium, copper, cyanide, iron, lead, nickel, silver, zinc) with concentrations characteristic of waste streams generated by a typical electroplating facility. Under the supervision of EPA, Commerce Holding Company Inc.'s consultant, C.A. Rich Consultants, performed the RI in two consecutive phases. The Phase I RI included: 1) a geophysical survey; 2) soil sampling associated with monitoring well installation; 3) groundwater sampling; 4) sampling of sediments and water from storm drains; 5) permeability testing; 6) a topographic survey; and, 7) numerical modeling of groundwater. The Phase II RI included: 1) soil and sediment sampling from storm drains; 2) soil sampling adjacent to storm drains; 3) an installation of additional monitoring wells; 4) sampling of groundwater; and, 5) an additional topographic survey. The samples collected during these studies were analyzed for organic and metal contaminants on EPA's Target Compound List. The results of the two phases of the RI indicated that groundwater, soils and storm-drain sediments at the Site were contaminated with volatile organic compounds (VOCs) and metals. The following summary presents the RI results for site soils and the groundwater directly below and in the vicinity of the Site. However, these data represent conditions at the Site prior to the removal action that was

TRONIC PLATING CO., INC. (Continued) **1009968611**

recently conducted. Levels of contaminants in the storm drains and associated overflow drains, the sanitary leaching pool and the drywell are now much lower. Table G in Appendix II contains the post removal sampling results for soils in the above-mentioned areas. A Record of Decision (ROD) addressing operable unit 1 (OU 1) was prepared in September 1993.

CERCLIS Assessment History:

Action Code: 001
Action: DISCOVERY
Date Started: / /
Date Completed: 09/01/84
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/01/84
Priority Level: Low priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PROPOSAL TO NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 10/15/84
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: SITE INSPECTION
Date Started: 05/01/85
Date Completed: 05/31/85
Priority Level: Higher priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: FINAL LISTING ON NATIONAL PRIORITIES LIST

TRONIC PLATING CO., INC. (Continued) **1009968611**

Date Started: / /
Date Completed: 06/10/86
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: NATIONAL PRIORITIES LIST RESPONSIBLE PARTY SEARCH
Date Started: / /
Date Completed: 01/01/87
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: Notice Letters Issued
Date Started: / /
Date Completed: 06/26/87
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: Special Notice Issued
Date Started: / /
Date Completed: 01/29/88
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY NEGOTIATIONS
Date Started: 01/29/88
Date Completed: 05/20/88
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY WORKPLAN APPROVAL BY HQ
Date Started: 07/10/87
Date Completed: 06/07/88
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 07/10/87
Date Completed: 06/07/88
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Original Action Take Over

Action Code: 001
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 06/07/88
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMOVAL ASSESSMENT
Date Started: 03/21/90
Date Completed: 08/28/90
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: REMOVAL ASSESSMENT
Date Started: 12/01/92
Date Completed: 12/21/92
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Action Code: 001
Action: RISK/HEALTH ASSESSMENT
Date Started: 03/26/91
Date Completed: 12/31/92
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: ECOLOGICAL RISK ASSESSMENT
Date Started: / /
Date Completed: 12/31/92
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 05/07/93
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 06/07/88
Date Completed: 09/27/93
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: New Action Resulting from Take Over

Action Code: 001
Action: PRELIMINARY CLOSE-OUT REPORT PREPARED
Date Started: / /
Date Completed: 09/27/93
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Action Anomaly: Not reported

Action Code: 001
Action: RECORD OF DECISION
Date Started: / /
Date Completed: 09/27/93
Priority Level: Final Remedy Selected at Site
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMOVAL
Date Started: 06/17/93
Date Completed: 09/30/93
Priority Level: Cleaned up
Operable Unit: SITEWIDE
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

Action Code: 001
Action: Lodged By DOJ
Date Started: / /
Date Completed: 07/31/01
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: SECTION 107 LITIGATION
Date Started: 07/27/99
Date Completed: 10/12/01
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: STATE SUPPORT AGENCY COOPERATIVE AGREEMENT
Date Started: 06/26/87
Date Completed: 10/15/01
Priority Level: Not reported
Operable Unit: OU01

TRONIC PLATING CO., INC. (Continued) **1009968611**

Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: COMMUNITY INVOLVEMENT
Date Started: 07/10/87
Date Completed: 10/15/01
Priority Level: Not reported
Operable Unit: OU01
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: CONSENT DECREE
Date Started: / /
Date Completed: 10/15/01
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: DELETION FROM NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 10/15/01
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Federal Register Details:
Fed Register Date: 10/15/01
Fed Register Volume: 66
Page Number: 42610

Fed Register Date: 06/10/86
Fed Register Volume: 51
Page Number: 21054

Fed Register Date: 10/15/84
Fed Register Volume: 49
Page Number: 40320

CORRACTS:

TRONIC PLATING CO., INC. (Continued) **1009968611**

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19960905
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19880907
Action: CA050 - RFA Completed
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930630
Action: CA610
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA500 - CMI Workplan Approved
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA550 - Certification Of Remedy Completion Or Construction Completion
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA650 - Stabilization Construction Completed

TRONIC PLATING CO., INC. (Continued) **1009968611**

NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA350 - CMS Approved
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA200 - RFI Approved
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 2
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

US ENG CONTROLS:
EPA ID: NYD002059517
Site ID: 0201346
Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
FARMINGDALE, NY 11735
EPA Region: 02
County: SUFFOLK
Event Code: Not reported
Actual Date: 06/30/1993
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: COMMERCE HOLDING CO INC
Facility address: CENTRAL AVE UNIT 162-168
FARMINGDALE, NY 11735
EPA ID: NYD002059517
Mailing address: PO BOX 672
HICKSVILLE, NY 11802
Contact: Not reported
Contact address: PO BOX 672
HICKSVILLE, NY 11802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: TRONIC PLATING CO, INC
Owner/operator address: 168 CENTRAL AVE
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (516) 293-7883
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COMMERCE HOLDING CO INC
Owner/operator address: PO BOX 672
HICKSVILLE, NY 11802

TRONIC PLATING CO., INC. (Continued) **1009968611**

Owner/operator country: US
Owner/operator telephone: (516) 681-6000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

Date form received by agency: 02/28/1994
Site name: TRONIC PLATING CO./COMMERCE HOLDING CO.
Classification: Large Quantity Generator

Date form received by agency: 02/25/1994
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 07/23/1993
Site name: COMMERCE HOLDING CO INC
Classification: Large Quantity Generator

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM

TRONIC PLATING CO., INC. (Continued) **1009968611**

PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P099
. Waste name: ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE

. Waste code: P104
. Waste name: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Date form received by agency: 11/19/1980
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Corrective Action Summary:
Event date: 09/07/1988
Event: RFA Completed

Event date: 06/30/1993
Event: CA610

Event date: 09/30/1993
Event: Stabilization Construction Completed

TRONIC PLATING CO., INC. (Continued) **1009968611**

Event date: 09/30/1993
Event: CMI Workplan Approved

Event date: 09/30/1993
Event: Certification Of Remedy Completion Or Construction Completion

Event date: 09/30/1993
Event: CMS Approved

Event date: 09/30/1993
Event: RFI Approved

Event date: 09/30/1993
Event: Date For Remedy Selection (CM Imposed)

Event date: 09/05/1996
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/20/1985
Date achieved compliance: 08/03/1987
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/29/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 03/20/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/03/1987
Evaluation lead agency: State

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

ICIS:
Enforcement Action ID: 02-1999-0006
FRS ID: 110009302352
Action Name: COMMERCE HOLDING COMPANY INC
Facility Name: TRONIC PLATING CO., INC.
Facility Address: 168 CENTRAL AVENUE

TRONIC PLATING CO., INC. (Continued) **1009968611**

	FARMINGDALE, NY 11735
Enforcement Action Type:	Civil Judicial Action
Facility County:	SUFFOLK
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Judicial
EA Type Code:	CIV
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7538
Longitude in Decimal Degrees:	-73.4077
Permit Type Desc:	Not reported
Program System Acronym:	8112
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-1993-0077
FRS ID:	110009302352
Action Name:	COMMERCE HOLDING COMPANY, INC.
Facility Name:	TRONIC PLATING CO., INC.
Facility Address:	168 CENTRAL AVENUE FARMINGDALE, NY 11735
Enforcement Action Type:	CERCLA 106 AO For Resp Action/Imm Haz
Facility County:	SUFFOLK
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	106
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7538
Longitude in Decimal Degrees:	-73.4077
Permit Type Desc:	Not reported
Program System Acronym:	8112
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-1988-0849
FRS ID:	110009302352
Action Name:	COMMERCE HOLDING CO (TRONIC PLATING)
Facility Name:	TRONIC PLATING CO., INC.
Facility Address:	168 CENTRAL AVENUE FARMINGDALE, NY 11735
Enforcement Action Type:	CERCLA 122A/104A Agrmt For RI/FS
Facility County:	SUFFOLK
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	122/104
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7538
Longitude in Decimal Degrees:	-73.4077
Permit Type Desc:	Not reported
Program System Acronym:	8112
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	TRONIC PLATING CO., INC.

TRONIC PLATING CO., INC. (Continued) **1009968611**

Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE

TRONIC PLATING CO., INC. (Continued) **1009968611**

Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

T94 **ASTRO ELECTROPLATING, INC.** **NY SHWS S108131276**
South **170 CENTRAL AVENUE** **NY Spills N/A**
1/2-1 **EAST FARMINGDALE, NY 11735**
0.599 mi.
3162 ft. **Site 1 of 2 in cluster T**

Relative:
Lower

Actual:
96 ft.

SHWS:
Program: HW
Site Code: 58178
Classification: Significant threat to the public health or environment - action required.
Region: 1
Acres: 2.9
HW Code: 152036
Record Add: 11/18/1999
Record Upd: 02/02/2016
Updated By: GTBOBERS
Site Description: Location: The Astro Electroplating site is located in an urban portion of Suffolk County, NY. The Astro Electroplating site is located at 170 Central Avenue in the Town of Babylon, Suffolk County, New York. The 2.9-acre site is located on the north side of Central Avenue in a commercial/industrial area. Site Features: The site contains one multi-tenant industrial building. A paved parking lot surrounds the building. Astro Electroplating is an inactive electroplating facility that occupied 9,700 square feet of space at the north end of the industrial building. Current Zoning and Land Use: The site has been decommisioned and the surrounding parcels are currently used for a combination of commercial and light industrial processes.Past Use of the Site: Astro Electroplating specialized in plating nickel, chromium and copper to pre-molded plastic components. Contamination was due to wastewater being discharged to five subsurface leaching pools. Operable Units: The site was divided into

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

two operable units in 2007. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1)is the site soils. OU2 consists of site related groundwater.Site Geology and Hydrogeology: The upper glacial deposits are located directly below the surface and extend to a depth of 144 feet bgs. The soil consists primarily of coarse grained sand and is characteristic of outwash plain deposits. The water table is located atapproximately 37 feet bgs, and flows south-southeast.

Env Problem:	Nature and Extent of Contamination: The primary contaminants of concern at the site known at this time include plating metals such as nickel, zinc, chromium and copper. These are the contaminants that exceed Standards, Criteria and Guidance values. OU1 & OU2:Groundwater & Soil - Investigations indicate contamination in saturated and unsaturated soils and a plume of groundwater contamination that extends south to the property border. Groundwater and soil contamination is due to wastewater discharged to leaching pools. Significant Threat: The site presents a significant environmental threat due to the ongoing releases from source areas of contaminants into groundwater.
Health Problem:	The Astro Electroplating facility's past practice of subsurface wastewater disposal has contaminated groundwater and soil with heavy metals. In 1986, contaminated liquids and sludges were removed from the former leaching pools on-site. The remedial investigation indicated soil contamination with heavy metals in the leaching pool area below 15 feet. Exposures are unlikely due to the depth of contamination. Since homes and businesses near the site are connected to public drinking water, exposure to site-related contaminants in groundwater is not expected.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1970
Disp Term:	1986
Lat/Long:	40:45:14:0 / 73:24:25:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	10/24/2012 11:33:00 AM
Updated By:	ldennist
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Annette G. Nowak Marital Trust c/o Finch Realty
Owner Address:	55 Central Avenue
Owner Addr2:	Not reported

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Farmingdale Library
Owner Address:	116 Merritt Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Astro Electroplating, Inc.
Owner Address:	170 Central Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	NEIL WEINSTEIN, PRES.
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	170 CENTRAL AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	C/O FINCH REALTY 55 CENTRAL AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
HW Code:	152036
Waste Type:	PLATING WASTES
Waste Quantity:	400,000 GALLONS/YEAR
Waste Code:	Not reported
HW Code:	152036
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152036
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152036
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	9112811
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2/20/2007 2:50:00 PM
Record Updated:	2/20/2007 2:50:00 PM
Updated By:	TLDiaz
Crossref ID:	8605806

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/20/2007 2:50:00 PM
Record Updated: 2/20/2007 2:50:00 PM
Updated By: TLDiaz
Crossref ID: 0605861
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/20/2007 2:49:00 PM
Record Updated: 2/20/2007 2:49:00 PM
Updated By: TLDiaz
Crossref ID: 0504521
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/20/2007 2:50:00 PM
Record Updated: 2/20/2007 2:50:00 PM
Updated By: TLDiaz
Crossref ID: 982273971
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: INITIAL
Crossref ID: NYD982273971
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 12/8/2008 1:37:00 PM
Updated By: EMZUK

SPILLS:
Facility ID: 9112811
Facility Type: ER
DER Facility ID: 448623
Site ID: 311503
DEC Region: 1
Spill Date: 1992-03-17
Spill Number/Closed Date: 9112811 / 1992-03-18
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS: 5220
Investigator: KMYAGER
Referred To: Not reported
Reported to Dept: 1992-03-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: 1992-03-18
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-03-17
Spill Record Last Update: 2015-01-22

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Spiller Name:	Not reported
Spiller Company:	ASTRO ELECTRIC PLATTING
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 10/10/95: This is additional information about material spilled from the translation of the old spill file: POSS SULFURIC ACID."
Remarks:	"FUMES, VISIBLE PLUME COMING FROM STACK,EMPLOYEES AFFECTED, ONGOING PROBLEM, REFERRED TO BOB CAPP POSSIBLY SENDING EMPLOYEES HOME"

Material:

Tank Test:

Facility ID:	8605806
Facility Type:	ER
DER Facility ID:	448623
Site ID:	311502
DEC Region:	1
Spill Date:	1986-12-13
Spill Number/Closed Date:	8605806 / 1991-02-04
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
SWIS:	5220
Investigator:	WJPARISH
Referred To:	Not reported
Reported to Dept:	1986-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1991-02-04
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-17
Spill Record Last Update:	2014-04-14
Spiller Name:	Not reported
Spiller Company:	ASTRO ELECTO PLATING
Spiller Address:	170 CENTRAL AVENUE
Spiller City,St,Zip:	EAST FARMINGDALE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was PARISH / / : WATER BEING CHANNELED INTO DIKE. 02/04/91: WATER BEING CHANNELED INTO DIKE. CHEMICAL MGT HIRED BY SPILLER TO CLEANUP.SCDH TO FOLLOWUP ON CLEANUP OF DRYWELLS. 10/10/95: This is additional information about material spilled from the translation of the old

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

spill file: ACID."
Remarks: "WATER AND ACID MIXED"

Material:

Tank Test:

T95 **TRONIC PLATING CO., INC.** **NY DEL SHWS** **S108667330**
South **168 CENTRAL AVENUE** **NY Spills** **N/A**
1/2-1 **EAST FARMINGDALE, NY 11735**
0.602 mi.
3178 ft. **Site 2 of 2 in cluster T**

Relative:
Lower

Actual:
96 ft.

DEL SHWS:

Year:	Not reported
Site Code Id:	Not reported
Site Classification:	Not reported
Region:	1
Epa Id Number:	Not reported
Site Type - Dump:	No
Site Type - Structure:	No
Site Type - Lagoon:	No
Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	Not reported
Hazardous Waste Code:	152028
Hazard Waste Disposed:	Not reported
Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No
Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported

TRONIC PLATING CO., INC. (Continued) **S108667330**

Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Site-related contamination was removed from on-site leaching pits and storm drains to reduce the potential for contamination of the groundwater and exposure to contaminated soil during routine maintenance of the storm drains. The remediated areaswere backfilled with 10 to 30 feet of clean soil and subsequently paved over. Exposure to the site-related contaminants, copper,chromium, and cyanide, in groundwater is not expected since homes and businesses in the vicinity of this site are connected topublic water.
Description:	The Tronic Plating Co. operated a metal electroplating and anodizing facility at 168 Central Avenue from July 1968 to March 1984. The

TRONIC PLATING CO., INC. (Continued) **S108667330**

facility was served by four industrial leaching pools, one sanitary septic leaching pool, and one drywell. It is possible that some of the on-site storm drains may have also received discharges from the site. Contamination levels documented in the RI include sediments from storm drains and a septic system at a maximum of: cadmium at 1130 ppm; cyanide at 92 ppm; chromium at 1580 ppm; and, lead at 2,290 ppm. Borings conducted during the RI indicated that high levels of contamination were not widespread, and the groundwater investigation showed only a limited impact from the site. A soils removal action was completed in August 1993 and all known disposal areas have been cleaned to USEPA and NYSDEC approved levels. A Record Of Decision (ROD) was issued in September 1993, calling for no further action at this site. Site related groundwater contamination was limited to one shallow monitoring well. Post-remedy Groundwater monitoring was conducted by the Responsible Party following the completion of remedial activities, and all results were forwarded to the NYSDEC. The results confirmed that the remedial action was effective, and a delisting package was prepared in 1996 and finalized in 1997.

Record Added Date: 11/18/1999
Record Updated Date: 01/31/2008
Env Assessment: Not reported
HW Disposed/Quantity: Not reported
Assess/Env Prog: Not reported
Assess/Health Prob: Not reported
Site Description: Not reported

SPILLS:
Facility ID: 1212903
Facility Type: ER
DER Facility ID: 431380
Site ID: 476061
DEC Region: 1
Spill Date: 2012-12-01
Spill Number/Closed Date: 1212903 / 2013-08-29
Spill Cause: Traffic Accident
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 5220
Investigator: Unassigned
Referred To: Not reported
Reported to Dept: 2012-12-01
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-12-01
Spill Record Last Update: 2013-09-23
Spiller Name: Not reported
Spiller Company: LIPA
Spiller Address: Not reported
Spiller City,St,Zip: NY

TRONIC PLATING CO., INC. (Continued) **S108667330**

Spiller Company: 999
Contact Name: FRANK NAGLIERI
Contact Phone: (917) 578-0161
DEC Memo: "POLE 14 PER NATIONAL GRID INCIDENT DESCRIPTION: MVA, WYE BANK CAME DOWN ONTO THE ROADWAY AFTER A VEHICLE STRUCK A UTILITY, WRS CONTRACTOR"
Remarks: "on street - cleanup crew enr @1855 - Frank called back to advise 20 gallon total"

Material:
Site ID: 476061
Operable Unit ID: 1225900
Operable Unit: 01
Material ID: 2223231
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

96
North
1/2-1
0.614 mi.
3240 ft.

Relative: Higher

Actual: 117 ft.

MCGOVERN SOD FARM **NY SHWS** **S105973013**
PINELAWN ROAD & OLD SOD FARM ROAD **N/A**
MELVILLE, NY 11747

SHWS:
Program: HW
Site Code: 57636
Classification: C
Region: 1
Acres: 7.9
HW Code: 152120
Record Add: 11/18/1999
Record Upd: 01/31/2008
Updated By: JBSWARTO
Site Description: A former sod farm which used a buried 550 gallon tank to store waste motor oil from equipment used in their farming operation. Also pesticides were stored on site. In August 1985, Hewlett-Packard had the tank removed. During excavation, visible discoloration of surface and subsurface soil was observed. Soil samples were collected and analyzed indicating hydrocarbons, pesticides and metals. Remediation of site has been completed. Hewlett-Packard has performed 4 soil excavations, taking a total of 590 cubic yards, and 5 soil sampling events. The final soil sampling results indicate that the site has been remediated. Site has been delisted 12/89.
Env Problem: This site has been remediated.
Health Problem: All contamination at the site has been remediated or removed. There are no known exposures, and therefore no known health concerns
Dump: False
Structure: True

MCGOVERN SOD FARM (Continued) **S105973013**

Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Aug. 1985
Lat/Long:	00:00:00:0 / 00:00:00:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	PALO-ALTO, CA 94303
Owner Country:	United States of America
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Hewlett-Packard
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	PALO-ALTO, CA 94303
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	McGovern Sod Farm
Owner Address:	Pinelawn Road & Old Sod Farm Road
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	PINELAWN RD. & OLD SOD FARM RD.
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
HW Code:	152120
Waste Type:	HYDROCARBONS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152120
Waste Type:	METALS
Waste Quantity:	UNKNOWN

MCGOVERN SOD FARM (Continued) **S105973013**

Waste Code:	Not reported
HW Code:	152120
Waste Type:	PESTICIDES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

97
NNW
1/2-1
0.758 mi.
4004 ft.

Relative:
Higher

Actual:
119 ft.

I.W. INDUSTRIES, INC.
35 MELVILLE PARK ROAD
MELVILLE, NY 11747

NY SHWS **S105054992**
NY LTANKS **N/A**
NY ENG CONTROLS
NY INST CONTROL
NY Spills
NY MANIFEST

SHWS:

Program:	HW
Site Code:	55868
Classification:	Site is properly closed - requires continued management.
Region:	1
Acres:	6
HW Code:	152102
Record Add:	11/18/1999
Record Upd:	11/09/2016
Updated By:	JBSWARTO

Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the

I.W. INDUSTRIES, INC. (Continued) **S105054992**

depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Company:	Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address:	35 Melville Park Road, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	152102
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIBENZOFURAN
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code:	152102
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MANGANESE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	N-DECANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NONANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TETRAMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

LTANKS:
Site ID: 260833
Spill Number/Closed Date: 0102354 / 2001-06-01
Spill Date: 2001-06-01
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 5226
Investigator: T/T/F
Referred To: Not reported
Reported to Dept: 2001-06-01
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-01
Spill Record Last Update: 2012-08-08

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Spiller Name:	SAME
Spiller Company:	IW INDUSTRIES
Spiller Address:	35 MELVILLE PARK ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller County:	001
Spiller Contact:	MARK WARSHAWSKI
Spiller Phone:	(631) 293-9494
Spiller Extention:	252
DEC Region:	1
DER Facility ID:	318823
DEC Memo:	"SAME AS 01-25079"
Remarks:	"tank failed the test. ***SAME AS 0125079***"

Material:

Site ID:	260833
Operable Unit ID:	839131
Operable Unit:	01
Material ID:	534469
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	260833
Spill Tank Test:	1526346
Tank Number:	1
Tank Size:	8000
Test Method:	20
Leak Rate:	1.11
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	USTest 2000/P/LL plus USTest 2000/U

Site ID:	260834
Spill Number/Closed Date:	0125079 / 2003-11-03
Spill Date:	2001-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	2001-06-01
CID:	Not reported
Water Affected:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-01
Spill Record Last Update:	2009-12-09
Spiller Name:	Not reported
Spiller Company:	IW INDUSTRIES
Spiller Address:	35 MELVILLE PARK ROAD
Spiller City,St,Zip:	MELVILLE, NY 11747-
Spiller County:	001
Spiller Contact:	ED WIGUTOFF
Spiller Phone:	(631) 293-9494
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	318823
DEC Memo:	"THEY HAVE SCHEDULED UNCOVERING PIPING, TANK ALONE TEST AND RETEST FOR 6/7 & 6/8, SAME AS 01-2354"
Remarks:	"THEY WILL ISOLATE TANK AND LINES AND RETEST NEXT WEEK. ***SAME AS 0102354*** "

Material:

Site ID:	260834
Operable Unit ID:	849347
Operable Unit:	01
Material ID:	526400
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

ENG CONTROLS:

Site Code:	55868
HW Code:	152102
Control Code:	15
Control Type:	ENG
Date Record Added:	07/14/2004
Date Rec Updated:	11/04/2016
Updated By:	BFJANKAU
Site Description:	Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a

I.W. INDUSTRIES, INC. (Continued) **S105054992**

combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.
Health Problem:	It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1972
Disp Term:	1986
Lat/Long:	40:46:35:0 / 73:25:02:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Record Upd:	10/19/2011 9:29:00 AM
Updated By:	BFJANKAU
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	BNEI IZHAK HOLDING CORPORATION
Owner Address:	35 MELVILLE PARK ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	MELVILLE, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	HUNTINGTON PUBLIC LIBRARY
Owner Address:	338 MAIN STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	HUNTINGTON, NY 11743
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Mr. Perry Youngwell
Owner Company:	Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address:	35 Melville Park Road, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	152102
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIBENZOFURAN
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MANGANESE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

INST CONTROL:
Site Code: 55868

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Control Name: IC/EC Plan
HW Code: 152102
Control Code: 34
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Health Problem:	It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1972
Disp Term:	1986
Lat/Long:	40:46:35:0 / 73:25:02:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	10/19/2011 9:29:00 AM
Updated By:	BFJANKAU
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	BNEI IZHAK HOLDING CORPORATION
Owner Address:	35 MELVILLE PARK ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	MELVILLE, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	HUNTINGTON PUBLIC LIBRARY
Owner Address:	338 MAIN STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	HUNTINGTON, NY 11743
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Mr. Perry Youngwell
Owner Company:	Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address:	35 Melville Park Road, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	152102
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: Landuse Restriction
HW Code: 152102
Control Code: 25
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with

I.W. INDUSTRIES, INC. (Continued) **S105054992**

interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: Soil Management Plan
HW Code: 152102
Control Code: 14
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980’s under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site

I.W. INDUSTRIES, INC. (Continued) **S105054992**

investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: Ground Water Use Restriction
HW Code: 152102
Control Code: 08
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots

I.W. INDUSTRIES, INC. (Continued) **S105054992**

are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Updated By: BFJANKAU

Site Code: 55868
Control Name: Monitoring Plan
HW Code: 152102
Control Code: 31
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868

Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is

I.W. INDUSTRIES, INC. (Continued) **S105054992**

reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.
Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: O&M Plan
HW Code: 152102
Control Code: 33
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980’s under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits

I.W. INDUSTRIES, INC. (Continued) **S105054992**

consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: Site Management Plan
HW Code: 152102
Control Code: 32
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site

I.W. INDUSTRIES, INC. (Continued) **S105054992**

disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

Site Code: 55868
Control Name: Environmental Easement
HW Code: 152102
Control Code: J
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/04/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area.Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west.Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property.Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 is reducing infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/19/2011 9:29:00 AM
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 6/23/2011 9:14:00 AM
Record Updated: 6/23/2011 9:14:00 AM
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:23:00 PM
Record Updated: 10/27/2011 4:30:00 PM
Updated By: BFJANKAU

SPILLS:

Facility ID:	0605685
Facility Type:	ER
DER Facility ID:	318823
Site ID:	368898
DEC Region:	1
Spill Date:	2006-08-16
Spill Number/Closed Date:	0605685 / 2007-10-24
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	5226
Investigator:	WXPRZYLO
Referred To:	Not reported
Reported to Dept:	2006-08-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-16
Spill Record Last Update:	2012-08-08
Spiller Name:	TRANS ARROW
Spiller Company:	TRANS ARROW
Spiller Address:	35 MELVILLE PARK ROAD
Spiller City,St,Zip:	MELVILLE, NY
Spiller Company:	001
Contact Name:	TRANS ARROW
Contact Phone:	(516) 490-2301
DEC Memo:	"8/16/06 12:29 TANK REMOVAL CONDUCTED BY CONSULTING CO, FUEL OIL CONTAMINATED SOIL WAS UNDER THE SPILL BUCKET ONLY, 5 YDS WAS REMOVED. HD ON SITE OBSERVED REMOVAL, ENDPOINT SAMPLES TAKEN, ND WITH THE PID EQ, WILL SEND RESULTS WITH MANIFESTS RECPTS 11/2/06 FILE REASSIGNED SCHD DID OVERSEE THE REMOVAL, APPROX 10 CU YARDS OF CONTAMINATED SOIL HAS BEEN REMOVED, NO FURTHER ACTION REQUIRED"
Remarks:	"8000 GALLON TANK, SMALL RELEASE NEAR SUPPLY AND RETURN, NOT CONTAINED IN SPILL BUCKET : TANK IS IN GOOD SHAPE; health dept on scene- 5 cubic yards of soil removed:"

Material:

Site ID:	368898
Operable Unit ID:	1126753
Operable Unit:	01
Material ID:	2116309
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

NY MANIFEST:
Country: USA
EPA ID: NYD001486968
Facility Status: Not reported
Location Address 1: 35 MELVILLE PARK ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001486968
Mailing Name: TRANSAREO - I W INDUSTRIES
Mailing Contact: I W INDUSTRIES
Mailing Address 1: 35 MELVILLE PARK RD
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162939495

NY MANIFEST:
Document ID: NYB8561835
Manifest Status: C
seq: Not reported
Year: 1997
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 06/17/1997
Trans1 Recv Date: 06/17/1997
Trans2 Recv Date: 06/18/1997
TSD Site Recv Date: 06/18/1997
Part A Recv Date: 07/01/1997
Part B Recv Date: 07/08/1997
Generator EPA ID: NYD001486968
Trans1 EPA ID: NYD050592807
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	08400
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NYB8561061
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/1997
Trans1 Recv Date:	06/12/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/12/1997
Part A Recv Date:	06/26/1997
Part B Recv Date:	07/01/1997
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	NYB8427852
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	31124MA
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/1997
Trans1 Recv Date:	04/30/1997
Trans2 Recv Date:	05/02/1997
TSD Site Recv Date:	05/06/1997
Part A Recv Date:	05/09/1997
Part B Recv Date:	06/02/1997
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD055522429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00900
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	INA1118435
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	31124MA
Trans2 State ID:	0027401
Generator Ship Date:	08/28/1997

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	09/03/1997
TSD Site Recv Date:	09/03/1997
Part A Recv Date:	09/11/1997
Part B Recv Date:	11/26/1997
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	CTD982191942
TSDF ID 1:	IND000646943
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NYB8561826
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/1997
Trans1 Recv Date:	06/17/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/18/1997
Part A Recv Date:	07/01/1997
Part B Recv Date:	07/10/1997
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	CTF0184734
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	CTHW76
Trans2 State ID:	Not reported
Generator Ship Date:	03/01/1995
Trans1 Recv Date:	03/01/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/02/1995
Part A Recv Date:	03/08/1995
Part B Recv Date:	03/24/1995
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	03050
Units:	G - Gallons (liquids only)* (8.3 pounds)

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Document ID:	NJA1300998
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	NJDEPS667
Trans2 State ID:	Not reported
Generator Ship Date:	03/15/1995
Trans1 Recv Date:	03/15/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/15/1995
Part A Recv Date:	03/29/1995
Part B Recv Date:	04/06/1995
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	05000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Document ID:	NYC1700752
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	AT8011
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/1992
Trans1 Recv Date:	07/16/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/16/1992

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Part A Recv Date:	07/27/1992
Part B Recv Date:	07/24/1992
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708198
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00720
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Document ID:	NYB2023587
Manifest Status:	C
seq:	Not reported
Year:	1990
Trans1 State ID:	NY729894
Trans2 State ID:	Not reported
Generator Ship Date:	09/17/1990
Trans1 Recv Date:	09/17/1990
Trans2 Recv Date:	09/17/1990
TSD Site Recv Date:	09/17/1990
Part A Recv Date:	10/01/1990
Part B Recv Date:	10/10/1990
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000691949
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	06000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Document ID:	NYB2165922
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	72989YNY
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/1990
Trans1 Recv Date:	06/19/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/19/1990
Part A Recv Date:	09/10/1990
Part B Recv Date:	08/20/1990
Generator EPA ID:	NYD001486968
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000691949
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	05000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Specific Gravity: 100

Click this hyperlink while viewing on your computer to access
81 additional NY_MANIFEST: record(s) in the EDR Site Report.

98
NNW
1/2-1
0.791 mi.
4174 ft.

ARCHON GROUP
25 MELVILLE PARK RD
MELVILLE, NY 11746

NY SHWS **1009234856**
NY ENG CONTROLS **N/A**
NY INST CONTROL
NY VCP
NY MANIFEST

Relative:
Higher

Actual:
117 ft.

SHWS:
Program: HW
Site Code: 57693
Classification: Significant threat to the public health or environment - action required.
Region: 1
Acres: 0.19
HW Code: 152169
Record Add: 11/18/1999
Record Upd: 01/16/2015
Updated By: JBSWARTO
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this class 2 site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is

ARCHON GROUP (Continued) **1009234856**

approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern for OU 02 include tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. Groundwater - Based on the groundwater monitoring results from 2012, PCE and its associated degradation products TCE and DCE are considered the primary contaminants, which were detected above the groundwater standard of 5 parts per billion. The leading edge of the PCE contamination was detected approximately 4,600 feet downgradient of the site along Ruland Road at a concentration of 180 parts per billion (ppb). However, a subsequent sample detected PCE at 23 ppb. The depth of contamination is approximately 50 feet below ground surface (bgs) at the site and descends to approximately 300 feet bgs downgradient of the site south of Bayliss Road. The width of the groundwater contamination plume is approximately 400 feet near Bayliss Road where the highest detections of PCE (211 ppb) and DCE (286 ppb) were located. The detection of DCE within the plume at a greater concentration than PCE indicates that natural degradation of PCE is occurring, since PCE is the primary contaminant detected on-site and DCE is a known degradation product of PCE. On-site remedial activities conducted since 2003 have significantly reduced site impacts to off-site groundwater, as a result groundwater conditions near the site have improved and reduced the length of the plume to 4,300 feet. Groundwater contamination is attenuating further down-gradient of the site based on low levels detected at the furthest monitoring well from the site located along Ruland Road, the decreasing trend of site related contamination detected at MW-09 from 2008 to 2012 and the detection of the final degradation product of PCE, known as ethane/ethene, within the plume. Vapor Intrusion - One structure down-gradient of the site has been evaluated for vapor intrusion. Sampling has detected elevated PCE, TCE and DCE concentrations beneath the building, but has not detected PCE, TCE or DCE within the indoor air. In 2007, sub-slab soil vapor concentrations of PCE, TCE and DCE were detected at 1,010 micrograms per cubic meter (ug/m3), 67 ug/m3 and 14.6 ug/m3, respectively. Subsequent sub-slab soil vapor sampling in 2014 detected PCE up to 74 ug/m3, but TCE and DCE were not detected. Clean groundwater is located above the zone of contaminated groundwater further downgradient of the site, therefore, soil vapor will not be impacted from this sites groundwater contamination.

Health Problem: Exposures associated with contamination on Operable Unit 1 (on-site) have been assessed as part of remedial activities for Site #V00128. Exposures to off-site contamination are being assessed as part of Operable Unit 2. People will not come into contact with groundwater contamination unless they dig or drill below the surface. Contaminated groundwater in the area is not used for drinking and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, the potential for exposures via soil vapor intrusion should

ARCHON GROUP (Continued) **1009234856**

	be monitored.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1985
Lat/Long:	40:46:35:0 / 73:25:05:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	10/24/2012 11:36:00 AM
Updated By:	ldennist
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	WHCS Melville LLC
Owner Address:	600 East Lascolinas Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Irving, TX 75039
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	New York Twist Drill
Owner Address:	25 Melville Park Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	WHCS Melville LLC
Owner Address:	600 East Lascolinas Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Irving, TX 75039
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Twist Drill
Owner Address:	25 Melville Park Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
HW Code:	152169
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

ARCHON GROUP (Continued) **1009234856**

HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

ENG CONTROLS:
Site Code: 56832
HW Code: V00128
Control Code: 15
Control Type: ENG
Date Record Added: 10/27/2011
Date Rec Updated: 10/29/2015
Updated By: SRHEIGEL
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is

ARCHON GROUP (Continued) **1009234856**

presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the

ARCHON GROUP (Continued) **1009234856**

site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/27/2011 4:15:00 PM
Record Upd:	10/24/2012 11:42:00 AM
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Lawrence A. Levine
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Mark Condon
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Phillips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Philips INternational Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America

ARCHON GROUP (Continued) **1009234856**

HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	10/27/2011 4:17:00 PM
Record Updated:	10/27/2011 4:31:00 PM
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	9/29/2008 12:07:00 PM
Record Updated:	9/29/2008 12:07:00 PM
Updated By:	MOBARRIE

Site Code:	56832
HW Code:	V00128
Control Code:	13
Control Type:	ENG
Date Record Added:	10/27/2011
Date Rec Updated:	10/29/2015
Updated By:	SRHEIGEL
Site Description:	Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or

ARCHON GROUP (Continued) **1009234856**

exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM

ARCHON GROUP (Continued) **1009234856**

Record Upd:	10/24/2012 11:42:00 AM
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Lawrence A. Levine
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Mark Condon
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Phillips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Philips INternational Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	10/27/2011 4:17:00 PM
Record Updated:	10/27/2011 4:31:00 PM
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM

ARCHON GROUP (Continued) **1009234856**

Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	9/29/2008 12:07:00 PM
Record Updated:	9/29/2008 12:07:00 PM
Updated By:	MOBARRIE
Site Code:	56832
HW Code:	V00128
Control Code:	12
Control Type:	ENG
Date Record Added:	10/27/2011
Date Rec Updated:	10/29/2015
Updated By:	SRHEIGEL
Site Description:	Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and

ARCHON GROUP (Continued) **1009234856**

consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430

ARCHON GROUP (Continued) **1009234856**

Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Mark Condon
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Phillips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Philips INternational Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	10/27/2011 4:17:00 PM
Record Updated:	10/27/2011 4:31:00 PM
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	9/29/2008 12:07:00 PM
Record Updated:	9/29/2008 12:07:00 PM
Updated By:	MOBARRIE

ARCHON GROUP (Continued) **1009234856**

INST CONTROL:
Site Code: 56832
Control Name: IC/EC Plan
HW Code: V00128
Control Code: 34
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern

ARCHON GROUP (Continued) **1009234856**

side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America

ARCHON GROUP (Continued) **1009234856**

Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Environmental Easement
HW Code: V00128
Control Code: J
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The

ARCHON GROUP (Continued) **1009234856**

main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of

ARCHON GROUP (Continued) **1009234856**

buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.

ARCHON GROUP (Continued) **1009234856**

Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Building Use Restriction
HW Code: V00128
Control Code: 26
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985,

ARCHON GROUP (Continued) **1009234856**

the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False

ARCHON GROUP (Continued) **1009234856**

Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU

ARCHON GROUP (Continued) **1009234856**

Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Monitoring Plan
HW Code: V00128
Control Code: 31
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent

ARCHON GROUP (Continued) **1009234856**

soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported

ARCHON GROUP (Continued) **1009234856**

Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169

ARCHON GROUP (Continued) **1009234856**

Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: O&M Plan
HW Code: V00128
Control Code: 33
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products

ARCHON GROUP (Continued) **1009234856**

trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon

ARCHON GROUP (Continued) **1009234856**

Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Site Management Plan
HW Code: V00128
Control Code: 32
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015

ARCHON GROUP (Continued) **1009234856**

Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.
Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that

ARCHON GROUP (Continued) **1009234856**

is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America

ARCHON GROUP (Continued) **1009234856**

Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Ground Water Use Restriction
HW Code: V00128
Control Code: 08
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and

ARCHON GROUP (Continued) **1009234856**

vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

ARCHON GROUP (Continued) **1009234856**

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746

ARCHON GROUP (Continued) **1009234856**

Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Landuse Restriction
HW Code: V00128
Control Code: 25
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property

ARCHON GROUP (Continued) **1009234856**

owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository

ARCHON GROUP (Continued) **1009234856**

Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20

ARCHON GROUP (Continued) **1009234856**

Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 56832
Control Name: Soil Management Plan
HW Code: V00128
Control Code: 14
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 10/29/2015
Updated By: SRHEIGEL
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand,

ARCHON GROUP (Continued) **1009234856**

silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/27/2011 4:15:00 PM
Record Upd: 10/24/2012 11:42:00 AM
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Lawrence A. Levine
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported

ARCHON GROUP (Continued) **1009234856**

Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Mr. Mark Condon
Owner Company: 25 MPR, LLC
Owner Address: 445 Broadhollow Road, Suite 430
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Phillips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Linda Greenfield
Owner Company: BP Moby Holdings, LLC
Owner Address: c/o Philips INternational Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 10/27/2011 4:17:00 PM
Record Updated: 10/27/2011 4:31:00 PM
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 11/30/2000 4:07:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: VCPTRANS
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 57693
Control Name: Decision Document

ARCHON GROUP (Continued) **1009234856**

HW Code: 152169
Control Code: D
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 02/03/2016
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this class 2 site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern for OU 02 include tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. Groundwater - Based on the groundwater monitoring results from 2012, PCE and its associated degradation products TCE and DCE are considered the primary contaminants, which were detected above the groundwater standard of 5 parts per billion. The leading edge of the PCE contamination was detected approximately 4,600 feet downgradient of the site along Ruland Road at a concentration of 180 parts per billion (ppb). However, a subsequent sample detected PCE at 23 ppb. The depth of contamination is approximately 50 feet below ground surface (bgs) at the site and descends to approximately 300 feet bgs downgradient of

ARCHON GROUP (Continued) **1009234856**

the site south of Bayliss Road. The width of the groundwater contamination plume is approximately 400 feet near Bayliss Road where the highest detections of PCE (211 ppb) and DCE (286 ppb) were located. The detection of DCE within the plume at a greater concentration than PCE indicates that natural degradation of PCE is occurring, since PCE is the primary contaminant detected on-site and DCE is a known degradation product of PCE. On-site remedial activities conducted since 2003 have significantly reduced site impacts to off-site groundwater, as a result groundwater conditions near the site have improved and reduced the length of the plume to 4,300 feet. Groundwater contamination is attenuating further down-gradient of the site based on low levels detected at the furthest monitoring well from the site located along Ruland Road, the decreasing trend of site related contamination detected at MW-09 from 2008 to 2012 and the detection of the final degradation product of PCE, known as ethane/ethene, within the plume. Vapor Intrusion - One structure down-gradient of the site has been evaluated for vapor intrusion. Sampling has detected elevated PCE, TCE and DCE concentrations beneath the building, but has not detected PCE, TCE or DCE within the indoor air. In 2007, sub-slab soil vapor concentrations of PCE, TCE and DCE were detected at 1,010 micrograms per cubic meter (ug/m3), 67 ug/m3 and 14.6 ug/m3, respectively. Subsequent sub-slab soil vapor sampling in 2014 detected PCE up to 74 ug/m3, but TCE and DCE were not detected. Clean groundwater is located above the zone of contaminated groundwater further downgradient of the site, therefore, soil vapor will not be impacted from this sites groundwater contamination.

Health Problem: Exposures associated with contamination on Operable Unit 1 (on-site) have been assessed as part of remedial activities for Site #V00128. Exposures to off-site contamination are being assessed as part of Operable Unit 2. People will not come into contact with groundwater contamination unless they dig or drill below the surface. Contaminated groundwater in the area is not used for drinking and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, the potential for exposures via soil vapor intrusion should be monitored.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/24/2012 11:36:00 AM
Updated By: ldennist
Own Op: Owner
Sub Type: E

ARCHON GROUP (Continued) **1009234856**

Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN

ARCHON GROUP (Continued) **1009234856**

Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

Site Code: 57693
Control Name: Monitoring Plan
HW Code: 152169
Control Code: 31
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 02/03/2016
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can

ARCHON GROUP (Continued) **1009234856**

be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this class 2 site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern for OU 02 include tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. Groundwater - Based on the groundwater monitoring results from 2012, PCE and its associated degradation products TCE and DCE are considered the primary contaminants, which were detected above the groundwater standard of 5 parts per billion. The leading edge of the PCE contamination was detected approximately 4,600 feet downgradient of the site along Ruland Road at a concentration of 180 parts per billion (ppb). However, a subsequent sample detected PCE at 23 ppb. The depth of contamination is approximately 50 feet below ground surface (bgs) at the site and descends to approximately 300 feet bgs downgradient of the site south of Bayliss Road. The width of the groundwater contamination plume is approximately 400 feet near Bayliss Road where the highest detections of PCE (211 ppb) and DCE (286 ppb) were located. The detection of DCE within the plume at a greater concentration than PCE indicates that natural degradation of PCE is occurring, since PCE is the primary contaminant detected on-site and DCE is a known degradation product of PCE. On-site remedial activities conducted since 2003 have significantly reduced site impacts to off-site groundwater, as a result groundwater conditions near the site have improved and reduced the length of the plume to 4,300 feet. Groundwater contamination is attenuating further down-gradient of the site based on low levels detected at the furthest monitoring well from the site located along Ruland Road, the decreasing trend of site related contamination detected at MW-09 from 2008 to 2012 and the detection of the final degradation product of PCE, known as ethane/ethene, within the plume. Vapor Intrusion - One structure down-gradient of the site has been evaluated for vapor intrusion. Sampling has detected elevated PCE, TCE and DCE concentrations beneath the building, but has not detected PCE, TCE or DCE within the indoor air. In 2007, sub-slab soil vapor concentrations of PCE, TCE and DCE were detected at 1,010 micrograms per cubic meter (ug/m3), 67 ug/m3 and 14.6 ug/m3, respectively. Subsequent sub-slab soil vapor sampling in 2014 detected PCE up to 74 ug/m3, but TCE and DCE were not detected. Clean groundwater is located above the zone of contaminated groundwater further downgradient of the site, therefore, soil vapor will not be impacted from this sites groundwater contamination.

ARCHON GROUP (Continued) **1009234856**

Health Problem: Exposures associated with contamination on Operable Unit 1 (on-site) have been assessed as part of remedial activities for Site #V00128. Exposures to off-site contamination are being assessed as part of Operable Unit 2. People will not come into contact with groundwater contamination unless they dig or drill below the surface. Contaminated groundwater in the area is not used for drinking and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, the potential for exposures via soil vapor intrusion should be monitored.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/24/2012 11:36:00 AM
Updated By: ldennist
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard

ARCHON GROUP (Continued) **1009234856**

Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

ARCHON GROUP (Continued) **1009234856**

Site Code: 57693
Control Name: Site Management Plan
HW Code: 152169
Control Code: 32
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 02/03/2016
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this class 2 site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern for OU 02 include tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. Groundwater - Based on the groundwater monitoring results from 2012, PCE and its associated degradation products TCE and DCE are considered the primary contaminants, which were detected above the groundwater standard of 5 parts per billion. The leading edge of the PCE contamination was detected approximately 4,600 feet downgradient of the site along Ruland Road at a concentration of 180 parts per billion (ppb). However, a subsequent sample detected PCE at 23 ppb. The depth of

ARCHON GROUP (Continued) **1009234856**

contamination is approximately 50 feet below ground surface (bgs) at the site and descends to approximately 300 feet bgs downgradient of the site south of Bayliss Road. The width of the groundwater contamination plume is approximately 400 feet near Bayliss Road where the highest detections of PCE (211 ppb) and DCE (286 ppb) were located. The detection of DCE within the plume at a greater concentration than PCE indicates that natural degradation of PCE is occurring, since PCE is the primary contaminant detected on-site and DCE is a known degradation product of PCE. On-site remedial activities conducted since 2003 have significantly reduced site impacts to off-site groundwater, as a result groundwater conditions near the site have improved and reduced the length of the plume to 4,300 feet. Groundwater contamination is attenuating further down-gradient of the site based on low levels detected at the furthest monitoring well from the site located along Ruland Road, the decreasing trend of site related contamination detected at MW-09 from 2008 to 2012 and the detection of the final degradation product of PCE, known as ethane/ethene, within the plume. Vapor Intrusion - One structure down-gradient of the site has been evaluated for vapor intrusion. Sampling has detected elevated PCE, TCE and DCE concentrations beneath the building, but has not detected PCE, TCE or DCE within the indoor air. In 2007, sub-slab soil vapor concentrations of PCE, TCE and DCE were detected at 1,010 micrograms per cubic meter (ug/m3), 67 ug/m3 and 14.6 ug/m3, respectively. Subsequent sub-slab soil vapor sampling in 2014 detected PCE up to 74 ug/m3, but TCE and DCE were not detected. Clean groundwater is located above the zone of contaminated groundwater further downgradient of the site, therefore, soil vapor will not be impacted from this sites groundwater contamination.

Health Problem: Exposures associated with contamination on Operable Unit 1 (on-site) have been assessed as part of remedial activities for Site #V00128. Exposures to off-site contamination are being assessed as part of Operable Unit 2. People will not come into contact with groundwater contamination unless they dig or drill below the surface. Contaminated groundwater in the area is not used for drinking and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, the potential for exposures via soil vapor intrusion should be monitored.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/24/2012 11:36:00 AM
Updated By: ldennist

ARCHON GROUP (Continued) **1009234856**

Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: WHCS Melville LLC
Owner Address: 600 East Lascolinas Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Irving, TX 75039
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169

ARCHON GROUP (Continued) **1009234856**

Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 9/29/2008 12:07:00 PM
Record Updated: 9/29/2008 12:07:00 PM
Updated By: MOBARRIE

VCP:
Program Type: VCP
Site Code: 56832
HW Code: V00128
Site Class: C
SWIS: 5226
Region: 1
Town: Huntington
Acres: 6
Date Record Added: 11/30/2000
Date Record Updated: 12/02/2015
Updated By: JBSWARTO
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES

ARCHON GROUP (Continued) **1009234856**

violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False

ARCHON GROUP (Continued) **1009234856**

Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/27/2011 4:15:00 PM
Record Upd:	10/24/2012 11:42:00 AM
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Lawrence A. Levine
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Mr. Mark Condon
Owner Company:	25 MPR, LLC
Owner Address:	445 Broadhollow Road, Suite 430
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Phillips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Linda Greenfield
Owner Company:	BP Moby Holdings, LLC
Owner Address:	c/o Philips INternational Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	10/27/2011 4:17:00 PM
Record Updated:	10/27/2011 4:31:00 PM

ARCHON GROUP (Continued) **1009234856**

Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	11/30/2000 4:07:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	VCPTRANS
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	9/29/2008 12:07:00 PM
Record Updated:	9/29/2008 12:07:00 PM
Updated By:	MOBARRIE

NY MANIFEST:

Country:	USA
EPA ID:	NYP000946558
Facility Status:	Not reported
Location Address 1:	25 MELVILLE PARK RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11746
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000946558
Mailing Name:	ARCHON GROUP
Mailing Contact:	PETER JURGS
Mailing Address 1:	25 MELVILLE PARK RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6318436179

NY MANIFEST:

Document ID:	NYG2454903
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	0440464ME
Trans2 State ID:	Not reported
Generator Ship Date:	12/15/2000
Trans1 Recv Date:	12/15/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/03/2001

ARCHON GROUP (Continued) **1009234856**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000946558
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

U99 **CIRCUITRON CORPORATION** **NY VAPOR REOPENED** **1000181928**
SW **82 MILBAR BOULEVARD** **NY AST** **NYD003995651**
1/2-1 **FARMINGDALE, NY 11735** **RCRA NonGen / NLR**
0.967 mi. **ICIS**
5106 ft. **Site 1 of 3 in cluster U** **FINDS**
ECHO
Relative: **NY MANIFEST**
Lower

Actual: **86 ft.**

VAPOR REOPENED:

Site Code:	152082
Facility Status:	Complete

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	00261
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported

Facility Info:

Site Ref#:	00261
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	CIRCUITRON CORP
Storage Owner Address:	82 MILBAR BLVD
Storage Owner City:	FARMINGDALE
Storage Owner State:	NY
Storage Owner Zip:	11735

Tank Info:

Facility ID:	00261
Facility Reference #:	00769
Township:	BABYLON
Tax Map No:	0100
Region:	SUFFOLK

Tank ID:	1
Tank Key:	857
Year Installed:	82
Substance:	ORGANIC SOLVENT
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 84
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010184

Tank ID:	2
Tank Key:	858
Year Installed:	82
Substance:	ORGANIC SOLVENT
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 84
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	0000001000
Date Permitted:	Not reported
Date Closed:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	010184

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CIRCUITRON CORP
Facility address:	82 MILBAR BLVD FARMINGDALE, NY 117351406
EPA ID:	NYD003995651
Mailing address:	MILBAR BLVD FARMINGDALE, NY 11735
Contact:	Not reported
Contact address:	MILBAR BLVD FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LOMBARDO MARIO C PRESIDENT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	LOMBARDO MARIO C PRESIDENT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CIRCUITRON CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: CIRCUITRON CORP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: CIRCUITRON CORP
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

CIRCUITRON CORPORATION (Continued) **1000181928**

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/25/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

CIRCUITRON CORPORATION (Continued) **1000181928**

ICIS:

Enforcement Action ID:	02-2005-2018
FRS ID:	110000876099
Action Name:	Joseph Z. Gazza, et al
Facility Name:	CIRCUITRON CORPORATION
Facility Address:	82 MILBAR BOULEVARD FARMINGDALE, NY 11735-1406
Enforcement Action Type:	CERCLA 104E5A AO For Access And/Or Info
Facility County:	SUFFOLK
Program System Acronym:	CERCLIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	104E5A
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7495
Longitude in Decimal Degrees:	-73.4195
Permit Type Desc:	Not reported
Program System Acronym:	NYD981184229
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-2005-2002
FRS ID:	110000876099
Action Name:	Circuitron Corporation SF Site
Facility Name:	CIRCUITRON CORPORATION
Facility Address:	82 MILBAR BOULEVARD FARMINGDALE, NY 11735-1406
Enforcement Action Type:	Prospective Purchaser Agreement
Facility County:	SUFFOLK
Program System Acronym:	CERCLIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	PPA
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7495
Longitude in Decimal Degrees:	-73.4195
Permit Type Desc:	Not reported
Program System Acronym:	NYD981184229
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-1988-0001
FRS ID:	110000876099
Action Name:	ADI ELECTRONICS
Facility Name:	CIRCUITRON CORPORATION
Facility Address:	82 MILBAR BOULEVARD FARMINGDALE, NY 117351406
Enforcement Action Type:	Bankruptcy
Facility County:	SUFFOLK
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Judicial
EA Type Code:	BNK
Facility SIC Code:	3679
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.7495
Longitude in Decimal Degrees:	-73.4195
Permit Type Desc:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Program System Acronym: 28693
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N

CIRCUITRON CORPORATION (Continued) **1000181928**

Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3679

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3679

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3679

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No

CIRCUITRON CORPORATION (Continued) **1000181928**

NAIC Code: Not reported
SIC Code: 3679

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3679

Facility Name: CIRCUITRON CORP
Address: 82 MILBAR BOULEVARD
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3679

FINDS:

Registry ID: 110000876099

Environmental Interest/Information System
SUPERFUND NPL

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000181928
Registry ID: 110000876099
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000876099

CIRCUITRON CORPORATION (Continued) **1000181928**

NY MANIFEST:

Country:	USA
EPA ID:	NYD003995651
Facility Status:	Not reported
Location Address 1:	82 MILBAR BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD003995651
Mailing Name:	CIRCUITRON CORP
Mailing Contact:	THOMAS MUSCHEZIO
Mailing Address 1:	82 MILBAR BLVD
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5167371800

NY MANIFEST:

Document ID:	NYA1384101
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	03/14/1985
Part B Recv Date:	03/06/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP

CIRCUITRON CORPORATION (Continued) **1000181928**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	110
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	112
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Document ID:	NYA1384119
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	03/14/1985
Part B Recv Date:	03/06/1985

CIRCUITRON CORPORATION (Continued) **1000181928**

Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	120
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	133
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	112
Waste Code:	D010 - SELENIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055

CIRCUITRON CORPORATION (Continued) **1000181928**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102
Document ID:	NYA1384128
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	03/14/1985
Part B Recv Date:	03/07/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	132
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.

CIRCUITRON CORPORATION (Continued) **1000181928**

Specific Gravity:	132
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	121
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102

Document ID:	NYA1384137
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	03/14/1985
Part B Recv Date:	03/06/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	104

Document ID:	NYA2451267
Manifest Status:	C
seq:	Not reported
Year:	1986
Trans1 State ID:	NY8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	01/02/1986
Trans1 Recv Date:	01/02/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/03/1986
Part A Recv Date:	01/06/1986
Part B Recv Date:	01/06/1986
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)

CIRCUITRON CORPORATION (Continued) **1000181928**

Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00605
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	011
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	133
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	110
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	109

Document ID:	NYA2637801
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	06/06/1985
Trans1 Recv Date:	06/06/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/07/1985
Part A Recv Date:	06/14/1985
Part B Recv Date:	06/11/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D010 - SELENIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	088
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	109
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	110
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Document ID: NYA1463607

CIRCUITRON CORPORATION (Continued) **1000181928**

Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/1985
Trans1 Recv Date:	05/06/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1985
Part A Recv Date:	05/28/1985
Part B Recv Date:	05/14/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D010 - SELENIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	088
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050

CIRCUITRON CORPORATION (Continued) **1000181928**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	112
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	110

Document ID:	NYA1463616
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/1985
Trans1 Recv Date:	05/06/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1985
Part A Recv Date:	05/28/1985
Part B Recv Date:	05/14/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.

CIRCUITRON CORPORATION (Continued) **1000181928**

Specific Gravity:	133
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	120
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	104

Document ID:	NYA1463625
Manifest Status:	C
seq:	Not reported
Year:	1985
Trans1 State ID:	7901-NF
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/1985
Trans1 Recv Date:	05/06/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1985
Part A Recv Date:	05/28/1985
Part B Recv Date:	05/14/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

CIRCUITRON CORPORATION (Continued) **1000181928**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00350
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	123
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	101
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	132
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	125
Document ID:	NYA1463337
Manifest Status:	K
seq:	Not reported
Year:	1985

CIRCUITRON CORPORATION (Continued) **1000181928**

Trans1 State ID:	8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/1985
Trans1 Recv Date:	04/15/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/17/1985
Part A Recv Date:	10/15/1985
Part B Recv Date:	04/19/1985
Generator EPA ID:	NYD003995651
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	133
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	123
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)

CIRCUITRON CORPORATION (Continued) **1000181928**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	102
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	108

Click this hyperlink while viewing on your computer to access
67 additional NY_MANIFEST: record(s) in the EDR Site Report.

U100 **UNITED STATES DEPT OF ENVIRONEMNTAL** **NY SHWS** **1007204997**
SW **PROTECTION-SITE:82 MILBAR AVE** **NY ENG CONTROLS** **NYP000789883**
1/2-1 **EAST FARMINGDALE, NY 11735** **NY INST CONTROL**
0.967 mi. **RCRA NonGen / NLR**
5106 ft. **Site 2 of 3 in cluster U**

Relative:
Lower

Actual:
86 ft.

SHWS:

Program:	HW
Site Code:	55856
Classification:	Site is properly closed - requires continued management.
Region:	1
Acres:	0.95
HW Code:	152082
Record Add:	11/18/1999
Record Upd:	04/29/2016
Updated By:	GWBURKE

Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1961
Disp Term:	present
Lat/Long:	40:44:58:0 / 73:25:07:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	5/13/2011 6:26:00 PM
Updated By:	jetrad
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082
Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	PLATING WASTES
Waste Quantity:	UNKNOWN

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

ENG CONTROLS:
Site Code: 55856
HW Code: 152082
Control Code: 13
Control Type: ENG
Date Record Added: 04/07/2011
Date Rec Updated: 04/07/2011
Updated By: jetrad
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Updated By:	jetrad
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082
Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	PLATING WASTES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD981184229
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	6/14/2006 8:08:00 AM
Record Updated:	6/14/2006 8:08:00 AM
Updated By:	rmdenyse
Site Code:	55856
HW Code:	152082
Control Code:	12
Control Type:	ENG
Date Record Added:	04/07/2011
Date Rec Updated:	04/07/2011
Updated By:	jetrad
Site Description:	Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

	groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.
Health Problem:	Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1961
Disp Term:	present
Lat/Long:	40:44:58:0 / 73:25:07:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	5/13/2011 6:26:00 PM
Updated By:	jetrad
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	PLATING WASTES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD981184229
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	6/14/2006 8:08:00 AM
Record Updated:	6/14/2006 8:08:00 AM
Updated By:	rmdenyse

Site Code:	55856
HW Code:	152082
Control Code:	16
Control Type:	ENG
Date Record Added:	04/07/2011
Date Rec Updated:	04/07/2011
Updated By:	jetrad
Site Description:	Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools.

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1961
Disp Term:	present
Lat/Long:	40:44:58:0 / 73:25:07:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	5/13/2011 6:26:00 PM
Updated By:	jetrad
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082
Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

INST CONTROL:
Site Code: 55856
Control Name: Site Management Plan
HW Code: 152082
Control Code: 32
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments.

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: O&M Plan
HW Code: 152082

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Control Code: 33
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.
Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics.

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: Monitoring Plan
HW Code: 152082
Control Code: 31
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: Ground Water Use Restriction
HW Code: 152082
Control Code: 08
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: Soil Management Plan
HW Code: 152082
Control Code: 14
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: Landuse Restriction
HW Code: 152082
Control Code: 25
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

Site Code: 55856
Control Name: Environmental Easement
HW Code: 152082
Control Code: J
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 04/07/2011
Updated By: jetrad
Site Code: 55856
Site Description: Location:The Circuitron Site is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is .95 acres and is flat with commercial properties on all sides.Current Zoning/Use(s): The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity.Historical Use(s): Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron engaged in photographic, riston, and silk screen

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt.Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination.Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The Site is located on the outwash plain of Long Island. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site.

Env Problem: Samples were taken from the SPDES discharge pools, two leach pools found in the plating room, storm drains on the west side of the building and from another abandoned SPDES discharge pool at the site. The results conformed the presence of heavy metals and organics. Based on these findings, the site was found to represent a significant threat to the environment and was placed on the National Priorities List in March 1989 with USEPA as the lead agency. A Phase I Investigation and a RI/FS was completed at this site. The March 1991 ROD for Operable unit 1 (OU1) is the on-site source area removal of soil and sediments. The September 1994 ROD for Operable unit 2 (OU2) OU2 consists of the extraction, treatment and reinjection of the on-site and off-site groundwater.In September of 1996, the groundwater 100% design was approved. The source removal portion of the OU-1 soil remediation program was completed in January of 1997. The building was demolished and the contaminated sediments were removed. Construction of the groundwater treatment system was completed on June 28, 2000. A single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE) was installed and completed 2/2008 and began operation 3/2008. This system addresses the contaminated subsurface soils and groundwater located in the southwest corner of the site. The GCW/IVS/SVE system achieve the OU2 remedy goals sooner and replaces the groundwater extraction and treatment facility, which was treating only the groundwater. The groundwater extraction and treatment system is being removed.The overall project is currently in the site management phase.

Health Problem: Direct contact with contaminants in soil is unlikely because the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/13/2011 6:26:00 PM
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 6/14/2006 8:08:00 AM
Record Updated: 6/14/2006 8:08:00 AM
Updated By: rmdenyse

RCRA NonGen / NLR:
Date form received by agency: 03/03/1990
Facility name: UNITED STATES DEPT OF ENVIRONEMNTAL
Facility address: PROTECTION-SITE:82 MILBAR AVE
EAST FARMINGDALE, NY 117351406
EPA ID: NYP000789883
Mailing address: PROTECTION-REGION2-WOODBRIDGE
AVENUE - EDISON, NY 08837
Contact: UNKNOWN UNKNOWN
Contact address: PROTECTION-REGION2-WOODBRIDGE
AVENUE - EDISON, NY 08837
Contact country: US
Contact telephone: (201) 906-6827
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/02/1990
Site name: UNITED STATES DEPT OF ENVIRONEMNTAL
Classification: Not a generator, verified

Date form received by agency: 03/01/1990

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Site name: UNITED STATES DEPT OF ENVIRONEMNTAL
Classification: Large Quantity Generator

Violation Status: No violations found

U101 **CIRCUITRON CORP.** **NPL** **1009968701**
SW **82 MILBAR BOULEVARD** **SEMS** **NYD981184229**
1/2-1 **EAST FARMINGDALE, NY 11735** **US ENG CONTROLS**
0.967 mi. **LIENS 2**
5106 ft. **Site 3 of 3 in cluster U** **RCRA NonGen / NLR**
ROD
Relative: **PRP**
Lower

Actual: **86 ft.**

NPL:
EPA ID: NYD981184229
Cerclis ID: 202301
EPA Region: 2
Federal: N
Final Date: 1989-03-30 00:00:00
Site Score: 54.270000000000003
Latitude: 40.749499999999998
Longitude: -73.419499999999999

Category Details:
NPL Status: Currently on the Final NPL
Category Description: Depth To Aquifer-> 25 And <= 50 Feet
Category Value: 26

NPL Status: Currently on the Final NPL
Category Description: Distance To Nearest Population-> 1/4 And <= 1/2 Mile
Category Value: 2640

Site Details:
Site Name: CIRCUITRON CORP.
Site Status: Final
Site Zip: 11735
Site City: EAST FARMINGDALE
Site State: NY
Federal Site: No
Site County: SUFFOLK
EPA Region: 02
Date Proposed: 06/24/88
Date Deleted: Not reported
Date Finalized: 03/31/89

Substance Details:
NPL Status: Currently on the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: C178
Substance: COPPER AND COMPOUNDS
CAS #: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: D008
Substance: LEAD (PB)
CAS #: 7439-92-1
Pathway: GROUND WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U044
Substance: CHLOROFORM
CAS #: 67-66-3
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U226
Substance: TRICHLOROETHANE, 1,1,1-
CAS #: 71-55-6
Pathway: GROUND WATER PATHWAY
Scoring: 2

Summary Details:

Conditions at proposal June 24, 1988): Circuitron Corp. manufactured circuit boards during 1961-86 on about 1 acre at 82 Milbar Boulevard, East Farmingdale, Suffolk County, New York. The site is in a densely populated industrial/commercialarea of Long Island east of Route 110 and the State University of New York Farmingdale Campus. The property is owned by 82 Milbar Boulevard Corp. Circuitron was a subsidiary of FEE Industries, which ADI Electronics, Inc., bought in 1984.The facility discharged thousands of gallons of metal-containing plating wastes to an underground leaching pool permitted under the State Pollutant Discharge Elimination System SPDES), to unauthori ed leaching pools beneath the floor of the plating room, and to a storm drain. After ADI Electronics purchased the facility, the Suffolk County Department of Health Services SCDHS) identified the discharge to the SPDES pool and the storm drain. Since 1984, SCDHS has issued Circuitron numerous notices of violations. On June 12, 1984, Circuitron agreed to an Order on Consent from SCDHS requiring removal of all ha ardous substances from the site. On March 7, 1985, SCDHS issued a Stipulated Agreement in which Circuitron agreed to install three monitoring wells, analy e ground water, and clean out one of the unauthori ed leaching pools. In mid-1986, the company vacated the facility without complying with all SCDHS requirements. In addition, Circuitron received one of the largest fines ever in the State for environmental pollution. The original owner has been convicted of a felony as a result of illegal waste discharges. Extensive sampling of the site by SCDHS detected heavy metals and chlorinated organic solvents in the SPDES leaching pool, the unauthori ed leaching pools, and the storm drains. Analyses of the monitoring wells installed as part of the Stipulated Agreement detected 1,1,1-trichloroethane in on-site wells downgradient of themanufacturing building. In May 1987, EPA found potentially explosive conditions at the site. From 125 to 150 drums, most unmarked and one bulging, were left hapha ardly throughout the building when it was vacated. Incompatible andreactive wastes were not segregated. Some drums were marked sulfuric acid, hydrochloric acid, sodium hydroxide, and caustic soda. Other smaller containers were strewn outside. Six concrete holding tanks

CIRCUITRON CORP. (Continued) **1009968701**

containing unknown materials were belowthe floor and three aboveground storage tanks were behind the building. The aquifers underlying Long Island have been designated as Sole Source Aquifers under the Safe Drinking Water Act. At least 15 municipal wells serving over 215,000people are within 3 miles of the site, the nearest 1,000 feet in the direction ground water flows. The shallow well has been closed since 1978 due to volatile organic chemical contamination from an unknown source. The building is not fenced or guarded. Employees of other businesses in the area use the site for parking. Status March 31, 1989): EPA is preparing a workplan for a remedial investigation/feasibility study to determine the type and extent of contamination atthe site and identify alternatives for remedial action.

Site Status Details:

NPL Status:	Final
Proposed Date:	06/24/1988
Final Date:	03/31/1989
Deleted Date:	Not reported

Narratives Details:

NPL Name:	CIRCUITRON CORP.
City:	EAST FARMINGDALE
State:	NY

SEMS:

Site ID:	202301
EPA ID:	NYD981184229
Federal Facility:	N
NPL:	Currently on the Final NPL
Non NPL Status:	Not reported

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0202301
EPA ID:	NYD981184229
Facility County:	SUFFOLK
Short Name:	CIRCUITRON CORP.
Congressional District:	02
IFMS ID:	021E
SMSA Number:	5380
USGC Hydro Unit:	02030202
Federal Facility:	Not a Federal Facility
DMNSN Number:	1.00000
Site Orphan Flag:	Y
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	Not reported
NFRAP Flag:	Not reported
Parent ID:	Not reported
RST Code:	Not reported
EPA Region:	02
Classification:	Manufacturing Plant
Site Settings Code:	UR
NPL Status:	Currently on the Final NPL
DMNSN Unit Code:	ACRE
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Non NPL Status Date: / /
Site Fips Code: 36103
CC Concurrence Date: 09/22/00
CC Concurrence FY: 2000
Alias EPA ID: Not reported
Site FUDS Flag: Not reported

CERCLIS Site Contact Name(s):
Contact ID: 2000184.00000
Contact Name: SHARON TROCHER
Contact Tel: (212) 637-4261
Contact Title: Remedial Project Manager (RPM)
Contact Email: Not reported

CERCLIS Site Alias Name(s):
Alias ID: 101
Alias Name: CIRCUITRON CORP
Alias Address: Not reported
NY
Alias ID: 102
Alias Name: CIRCUITRON CORP.
Alias Address: 82 MILBAR BOULEVARD
FARMINGDALE, NY 11735
Alias ID: 103
Alias Name: CIRCUITRON CORP.
Alias Address: 82 MILBAR BOULEVARD
EAST FARMINGDALE, NY 11735
Alias Comments: Not reported
Site Description: In 1984, an owner of Circuitron Corporation, Mario Lombardo, was charged for discharging organic solvents to unpermitted "hidden" leaching pools between March 1, 1982 and March 22, 1984. In 1985, Mr. Lombardo pleaded guilty to unlawful dumping of hazardous wastes, under New York State Environmental Conservation Law Section 27, Subsection 09-14. An Order of Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the Site including drums, tanks, and piping; and a groundwater quality study be performed. To comply with the order, Circuitron Corporation cleaned out and backfilled the unpermitted leaching pool in the southern part of the plating room and installed and sampled 5 on-Site monitoring wells. There are no records available regarding the amount of waste removed from this leaching pool or the existence and the extent of contaminated soil in and around the leaching pool. In 1987, EPA initiated an emergency removal of some of the more than 100 chemical containers and storage tanks on-Site. In 1988, EPA conducted another emegency cleanup action and removed approximately 20 waste drums from inside the building, 3 aboveground tanks from the rear of ther building, the contents of 7 undergground storage tanks, 2 below-surface treatment basins, and several leaching basins. The Site was proposed for teh National Priorities List in June 1988 and was listed on thr NPL in March 1989. The first RI/FS of the Site was initiated by EPA in september 1988 and was completed in January 1991. In 1984, an owner of Circuitron Corporation, Mario Lombardo, was charged for discharging organic solvents to unpermitted "hidden" leaching pools between March 1, 1982 and March 22, 1984. In 1985, Mr. Lombardo pleaded guilty to unlawful dumping of hazardous wastes, under New York State Environmental Conservation Law Section 27, Subsection 09-14. An Order of Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively,

CIRCUITRON CORP. (Continued) **1009968701**

required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the Site including drums, tanks, and piping; and a groundwater quality study be performed. To date, only the unpermitted leaching pool in the southern part of the plating room has been cleaned out and backfilled. This work was performed by Circuitron Corporation. There are no records available regarding the amount of waste removed from this leaching pool or the existence and the extent of contaminated soil in and around the leaching pool. In 1987, EPA initiated an emergency removal of some of the more than 100 chemical containers and storage tanks on-Site. In 1988, EPA conducted another emegency cleanup action and removed approximately 20 waste drums from inside the building, 3 aboveground tanks from the rear of ther building, the contents of 7 undergground storage tanks, 2 below-surface treatment basins, and several leaching basins. The Site was proposed for teh National Priorities List in June 1988 and was listed on thr NPL in March 1989. The first RI/FS of the Site was initiated by EPA in september 1988 and was completed in January 1991. The Circuitron Corporation site is located at 82 Milbar Boulevard, East Farmingdale, Suffolk County, New York. The site is situated near the Nassau County-Suffolk County border in central Long Island. The site encompasses approximately 1 acre in an industrial/commercial area just east of Route 110 and the State University of New York, Agricultural and Technical College campus in Farmingdale. The site is generally flat and has a slight slope up to the southeast of less than 1 percent. The site elevation is approximately 85 to 90 feet above mean sea level. The Circuitron Corporation site consists of an abandoned 23,500 square foot building that was used between 1961 and 1986 for the manufacture of electronic circuit boards. Aside from the building, the site is primarily asphalt paved, with the exception of a small area in the rear of the building. The paved area in front of the building was used in the past as a parking lot for the employees of Circuitron Corporation and is presently used for parking by employees of nearby companies. Approximately 95% of the site is paved or covered by the building.
At least two unauthorized leaching pools exist below the concrete floor in the plating room inside the building. A circular depression in the concrete floor towards the front of this room indicates the presence of other unauthorized leaching pools. A series of leaching pools lies beneath the parking lot in the front of the building. These leaching pools include an authorized wastewater discharge pool below a manhole located on the north side of the property in front of the laboratory, and two old abandoned leaching pools located in the northeast corner of the site. At least two sanitary cesspools have been documented to exist below the parking lot in front of the northwest corner of the building. A line of interconnected storm drains exists on the western portion of the site. The storm drains range from 10 feet to approximately 13 feet in depth. Circuitron Corporation is located in an industrial area surrounded by similar small manufacturers and is several miles away from any residential area. There are no schools or any recreational facilities in the immediate vicinity. Approximately 15 municipal wells serving over 215,000 people are within 3 miles of the site, the nearest being approximately 1500 feet to the southeast of the site in the direction of groundwater flow. One shallow well in this field has been closed since 1978 due to organic chemical contamination from an unknown source. Circuitron Corporation was incorporated in New York State in 1961 and operated a manufacturing facility at the site between 1961 and 1986. Circuitron Corporation ceased operations and vacated the site some time between May and June 1986. During this time period, Circuitron Corporation removed all equipment of value and left the facility in its present condition. The current owner of the site is 82 Milbar Blvd., Inc., a New York corporation incorporated in 1968. Circuitron Corporation filed for bankruptcy in 1986. 82 Milbar Blvd., Inc. filed for bankruptcy in 1987. Both of these bankruptcy proceedings were

CIRCUITRON CORP. (Continued) **1009968701**

dismissed or closed in 1988. At the request of the New York State Department of Environmental Conservation (NYSDEC), an emergency response action was performed by the EPA at the site in mid-1989, prior to the Remedial Investigation/Feasibility Study (RI/FS) investigation. This action included removal of 20 waste drums from inside the building, the emptying of 2 underground tanks containing various volatile organic and inorganic compounds, cleaning and removing of 3 aboveground tanks from the rear of the building and general clean-up of the suspected contaminated debris from inside the building. The facility had an approved New York State Pollutant Discharge Elimination System (SPDES) permit, No. NY-007 5655, to discharge industrial wastewater to a leaching pool located below the parking lot in front of the building. This SPDES permit expired on September 12, 1986, based on a July 1, 1986 inspection by NYSDEC, indicating that the discharge had ceased. Circuitron Corporation had received numerous warnings from both the Suffolk County Department of Health Services (SCDHS) and NYSDEC concerning SPDES permit violations and unauthorized discharges. An Order of Consent and the Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. Circuitron Corporation installed 5 monitoring wells at the site; however, there are no engineering or well installation reports available concerning the construction of these wells. In addition, the analytical results from the Circuitron Corporation and the SCDHS groundwater sampling of these wells are in conflict with each other. To date, only the unauthorized leaching pool in the southern part of the plating room has been cleaned out and backfilled. This work was performed by Circuitron Corporation. There are no records available regarding the amount of waste removed from the unauthorized leaching pool or the existence and the extent of contaminated soil in and around the leaching pool. In 1984, a former owner of Circuitron Corporation, Mario Lombardo, was charged for discharging organic solvents to unauthorized, "hidden" leaching pools between March 1, 1982 and March 22, 1984. He was indicted on 6 felony counts of unlawful dumping of hazardous wastes, under New York State (NYS) Environmental Conservation Law (ECL) Section 27, Subsection 09-14; 19 felony counts of offering a false instrument for filing, under Suffolk County Penal Law Section 175, Subsection 135; and 20 misdemeanor counts of violating NYS ECL Section 17, Subsection 03-01 and 05-01. On May 9, 1985, Mario Lombardo pleaded guilty to unlawful dumping of hazardous wastes, NYS ECL Section 27, Subsection 09-14. He was fined $50,000 and sentenced to 700 hours of community service. When Circuitron Corporation informed SCDHS that it would be vacating the facility, SCDHS informed Circuitron Corporation that a cleanup of toxic and hazardous materials and a groundwater study would be required. SCDHS also required further off-site groundwater monitoring. Circuitron Corporation refused to comply with the off-site groundwater monitoring requirement. EPA sent a general notice letter and a request for information to the identified potentially responsible parties (PRPs) on July 24, 1987. EPA sent another general notice letter to the PRPs on August 15, 1988 inviting them to conduct a RI/FS. The site was proposed for the National Priorities List in June, 1988 and finalized in March, 1989. The RI/FS was initiated in September, 1988 and the field work started in May, 1989. A Record of Decision addressing Operable Unit 1 was completed in March 1991.

CERCLIS Assessment History:

Action Code:	001
Action:	DISCOVERY
Date Started:	/ /
Date Completed:	03/25/86
Priority Level:	Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 03/28/86
Priority Level: Low priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: SITE INSPECTION
Date Started: 06/26/87
Date Completed: 06/29/87
Priority Level: Higher priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/23/87
Priority Level: Low priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PROPOSAL TO NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 06/24/88
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: NATIONAL PRIORITIES LIST RESPONSIBLE PARTY SEARCH

CIRCUITRON CORP. (Continued) **1009968701**

Date Started: 10/01/87
Date Completed: 06/30/88
Priority Level: No PRPs Identified
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: Notice Letters Issued
Date Started: / /
Date Completed: 08/15/88
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: CLAIM IN BANKRUPTCY PROCEEDING
Date Started: 11/30/87
Date Completed: 11/09/88
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY NEGOTIATIONS
Date Started: 08/15/88
Date Completed: 11/10/88
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY WORKPLAN APPROVAL BY HQ
Date Started: 09/27/88
Date Completed: 02/15/89
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 001
Action: LIEN ON POTENTIALLY RESPONSIBLE PARTY PROPERTY
Date Started: / /
Date Completed: 03/02/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: FINAL LISTING ON NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 03/31/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: Public Notice Published
Date Started: / /
Date Completed: 04/17/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMOVAL
Date Started: 09/15/88
Date Completed: 09/28/89
Priority Level: Cleaned up
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: RISK/HEALTH ASSESSMENT
Date Started: / /
Date Completed: 08/15/90
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 001
Action: REMOVAL ASSESSMENT
Date Started: 03/21/90
Date Completed: 09/08/90
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: NATIONAL PRIORITIES LIST RESPONSIBLE PARTY SEARCH
Date Started: 01/17/90
Date Completed: 11/07/90
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 09/27/88
Date Completed: 03/29/91
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: Notice Letters Issued
Date Started: / /
Date Completed: 03/29/91
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: RECORD OF DECISION
Date Started: / /
Date Completed: 03/29/91
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 001
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 03/29/91
Date Completed: 06/24/91
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: REMOVAL ASSESSMENT
Date Started: 02/08/93
Date Completed: 02/09/93
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 003
Action: REMEDIAL DESIGN
Date Started: 06/21/91
Date Completed: 09/30/94
Priority Level: Not reported
Operable Unit: EXCAVATION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 004
Action: REMEDIAL DESIGN
Date Started: 06/24/91
Date Completed: 09/30/94
Priority Level: Not reported
Operable Unit: SVE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMEDIAL DESIGN
Date Started: 06/24/91
Date Completed: 09/30/94
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 002
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 01/27/92
Date Completed: 09/30/94
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: RECORD OF DECISION
Date Started: / /
Date Completed: 09/30/94
Priority Level: Final Remedy Selected at Site
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMEDIAL ACTION
Date Started: 09/30/94
Date Completed: 09/30/96
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: REMEDIAL DESIGN
Date Started: 02/01/95
Date Completed: 09/30/96
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 003
Action: REMEDIAL ACTION
Date Started: 09/30/94
Date Completed: 03/31/97
Priority Level: Not reported
Operable Unit: EXCAVATION
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001

CIRCUITRON CORP. (Continued) **1009968701**

Action: PRELIMINARY CLOSE-OUT REPORT PREPARED
Date Started: / /
Date Completed: 09/22/00
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: REMEDIAL ACTION
Date Started: 09/10/97
Date Completed: 05/15/01
Priority Level: Interim RA Report
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 05/18/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PROSPECTIVE PURCHASER AGREEMENT ASSESSMENT
Date Started: 04/23/01
Date Completed: 07/18/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: CONSENT AGREEMENT (ADMINISTRATIVE)
Date Started: / /
Date Completed: 07/18/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 001
Action: COST RECOVERY NEGOTIATIONS
Date Started: / /
Date Completed: 07/18/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: FIVE-YEAR REVIEW
Date Started: / /
Date Completed: 08/05/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: STATE SUPPORT AGENCY COOPERATIVE AGREEMENT
Date Started: 04/28/89
Date Completed: 03/01/06
Priority Level: Not reported
Operable Unit: ON-SITE BUILDING DEMOLITION
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 002
Action: FIVE-YEAR REVIEW
Date Started: / /
Date Completed: 04/05/10
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: LONG TERM RESPONSE ACTION
Date Started: 05/15/01
Date Completed: 05/16/11
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action Code: 001
Action: TECHNICAL ASSISTANCE
Date Started: 07/16/05
Date Completed: 06/29/12
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: OPERATIONS AND MAINTENANCE
Date Started: 06/01/11
Date Completed: / /
Priority Level: Not reported
Operable Unit: GROUNDWATER
Primary Responsibility: State, No Fund Money
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Federal Register Details:
Fed Register Date: 03/31/89
Fed Register Volume: 54
Page Number: 13296

Fed Register Date: 06/24/88
Fed Register Volume: 53
Page Number: 23988

US ENG CONTROLS:
EPA ID: NYD981184229
Site ID: 0202301
Name: CIRCUITRON CORP.
Address: 82 MILBAR BOULEVARD
EAST FARMINGDALE, NY 11735
EPA Region: 02
County: SUFFOLK
Event Code: Not reported
Actual Date: 09/30/1994
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Buildings/Structures
Engineering Control: Decontamination
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Buildings/Structures
Engineering Control: Disposal
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Excavation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Treatment, (N.O.S.)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Soil Vapor Extraction (in-situ)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Aeration
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Air Stripping
Contact Name: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Carbon Adsorption
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Coagulation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Discharge
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Extraction
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Flocculation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02

CIRCUITRON CORP. (Continued) **1009968701**

Contaminated Media : Groundwater
Engineering Control: Operations & Maintenance (O&M)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Reinjection
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Residuals Discharge
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Sedimentation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

LIENS 2:
Facility name: CIRCUITRON CORP.
Facility address: 82 MILBAR BOULEVARD
EAST FARMINGDALE, NY 11735
EPA ID: NYD981184229
Effective date: Not reported
Lien: LP001
Party name: Not reported
Reg: 02
Release date: Not reported
Start date: Not reported
Complete date: 03/02/1989

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: CIRCUITRON SITE
Facility address: 82 MILBAR AVE
EAST FARMINGDALE, NY 11735
EPA ID: NYD981184229

CIRCUITRON CORP. (Continued) **1009968701**

Mailing address: US ARMY CORPS OF ENGINEERS
1900 HEMPSTEAD TPK STE 316
EAST MEADOW, NY 115540000
Contact: SHEWEN BIAN
Contact address: US ARMY CORPS OF ENGINEERS
EAST MEADOW, NY 115540000
Contact country: US
Contact telephone: (516) 794-2913
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CIRCUITRON SITE
Classification: Not a generator, verified

Date form received by agency: 06/29/1998
Site name: CIRCUITRON SITE
Classification: Large Quantity Generator

Violation Status: No violations found

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

PRP:
PRP name: ADI CIRCUITS, INC.
ADI CIRCUITS, INC.
ADI ELECTRONICS, INC.
ADI ELECTRONICS, INC.
CIRCUITRON CORP.
CIRCUITRON CORP.
CIRCUITRON CORP.
F.E.E. INDUSTRIES, INC.
F.E.E. INDUSTRIES, INC.
F.E.E./CHRIONICS, INC.
FEE CHRIONICS, INC.

CIRCUITRON CORP. (Continued) **1009968701**

JOSEPH Z. GAZZA
JULIUS J. D'AMATO
MR. JULIUS D'AMATO
MR. MARIO LOMBARDO
THOMAS J. LOVE

Count: 3 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
EAST FARMINGDALE	S113916706	PINELAWN/FARMINGDALE - HORTONSPHER	E/S BROADHOLLOW ROAD	11735	NY SHWS
FARMINGDALE	S105841217	RJN ASSOCIATES; LTD	NEW HIGHWAY	11735	NY SWF/LF
MELVILLE	S113916744	MELVILLE PLUME TRACKDOWN	SOUTH SERVICE ROAD	11747	NY SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/07/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/07/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 02/07/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 01/04/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 93

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 101

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 101

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/26/2016
Date Data Arrived at EDR: 09/29/2016
Date Made Active in Reports: 11/11/2016
Number of Days to Update: 43

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/29/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 06/01/2016
Date Data Arrived at EDR: 08/19/2016
Date Made Active in Reports: 01/05/2017
Number of Days to Update: 139

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/04/2017
Date Data Arrived at EDR: 01/10/2017
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/06/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/17/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 09/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/07/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/06/2017
Date Data Arrived at EDR: 02/06/2017
Date Made Active in Reports: 02/08/2017
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/11/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/07/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/06/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/17/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 01/14/2017
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/31/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/24/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 11/23/2016
Date Data Arrived at EDR: 12/21/2016
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 54

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/23/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/27/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/05/2017
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/02/2017
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/02/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Annually

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 01/04/2017
Date Data Arrived at EDR: 01/10/2017
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/24/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 02/09/2017
Date Data Arrived at EDR: 03/08/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 93

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/28/2017
Next Scheduled EDR Contact: 06/12/2017
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 11/16/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Annually

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/09/2017
Date Data Arrived at EDR: 03/08/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 93

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 12/29/2016
Date Data Arrived at EDR: 12/30/2016
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 45
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 37
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/29/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/06/2017
Date Data Arrived at EDR: 02/06/2017
Date Made Active in Reports: 02/08/2017
Number of Days to Update: 2
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/18/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Varies

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/24/2017
Next Scheduled EDR Contact: 06/05/2017
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/14/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/14/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/15/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/17/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/24/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 133

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/26/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/26/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 02/01/2017
Date Data Arrived at EDR: 02/09/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 57
Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/21/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3
Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 06/06/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 04/28/2016
Date Made Active in Reports: 09/02/2016
Number of Days to Update: 127
Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/10/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 04/10/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/04/2017
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/06/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2016
Date Data Arrived at EDR: 11/18/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 77

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/27/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/24/2015
Date Made Active in Reports: 09/30/2015
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/26/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/14/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 12/23/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/17/2017
Number of Days to Update: 52

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/22/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/05/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/07/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/07/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Annually

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/08/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 38

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 06/02/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines
An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/14/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 21

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/04/2017
Date Data Arrived at EDR: 04/07/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 35

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 06/07/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/03/2016
Date Made Active in Reports: 09/02/2016
Number of Days to Update: 91

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/24/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 10/25/2015
Date Data Arrived at EDR: 01/29/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 67

Source: Department of Defense
Telephone: 571-373-0407
Last EDR Contact: 05/22/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/19/2017
Date Data Arrived at EDR: 03/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/07/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/22/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 79

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/24/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 11/09/2016
Date Data Arrived at EDR: 11/18/2016
Date Made Active in Reports: 01/04/2017
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/24/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 01/04/2017
Date Data Arrived at EDR: 01/10/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 31

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 10/27/2016
Date Data Arrived at EDR: 01/10/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 31

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2047
Data Release Frequency: Varies

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 11/08/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 48

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/20/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 01/03/2017
Date Data Arrived at EDR: 01/04/2017
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/01/2015
Date Data Arrived at EDR: 12/29/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/12/2017
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/30/2017
Date Data Arrived at EDR: 02/01/2017
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 12

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/03/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Annually

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 01/30/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 02/22/2017
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/24/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 12/05/2016
Date Data Arrived at EDR: 12/08/2016
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 11/25/2016
Date Data Arrived at EDR: 12/02/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 70

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 11/25/2016
Date Data Arrived at EDR: 12/02/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 70

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/03/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 12/20/2016
Date Data Arrived at EDR: 12/21/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 51
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 12/20/2016
Date Data Arrived at EDR: 12/21/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 51
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/13/2017
Date Data Arrived at EDR: 01/20/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 26
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/13/2017
Date Data Arrived at EDR: 01/20/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 26
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 09/29/2016
Date Made Active in Reports: 01/03/2017
Number of Days to Update: 96

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/11/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 07/22/2016
Date Made Active in Reports: 11/22/2016
Number of Days to Update: 123

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/18/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/22/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 11/18/2016
Date Made Active in Reports: 01/06/2017
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 04/14/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 50

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

NEWSDAY
235 PINELAWN ROAD
MELVILLE, NY 11747

TARGET PROPERTY COORDINATES

Latitude (North):	40.763451 - 40° 45' 48.42''
Longitude (West):	73.406648 - 73° 24' 23.93''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	634487.5
UTM Y (Meters):	4513508.0
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940609 HUNTINGTON, NY
Version Date:	2013
South Map:	5940593 AMITYVILLE, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General ENE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36103C0620G	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
36103C0835G	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
HUNTINGTON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile South
Site Name:	Tronic Plating Co., Inc
Site EPA ID Number:	NYD002059517
Groundwater Flow Direction:	South-Southeast
Measured Depth to Water:	not available.
Hydraulic Connection:	Information is not available about the hydraulic connection between aquifers underlying the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Pleistocene
Code:	Qp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 4977850.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Newsday	CLIENT:	Gaiatech Real Estate Division
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Grace Riordan
LAT/LONG:	40.763451 / 73.406648	INQUIRY #:	4977850.2s
		DATE:	June 27, 2017 9:28 am

Copyright © 2017 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Haven

Soil Surface Texture: highly decomposed plant material

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	highly decomposed plant material	A-8	Highly organic soils, Peat.	Max: 42 Min: 1.4	Max: 5.5 Min: 4.5
2	5 inches	18 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 6 Min: 4.5
3	1 inches	5 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 6 Min: 4.5
4	18 inches	27 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 14 Min: 4	Max: 6 Min: 4.5

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
5	27 inches	59 inches	stratified gravelly sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 6 Min: 4.5

Soil Map ID: 2

Soil Component Name: Plymouth

Soil Surface Texture: loamy sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6
2	3 inches	27 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	27 inches	59 inches	gravelly coarse sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 5.5 Min: 3.6

Soil Map ID: 3

Soil Component Name: Plymouth

Soil Surface Texture: loamy sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6
2	3 inches	27 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	27 inches	59 inches	gravelly coarse sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 5.5 Min: 3.6

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000832018	1/8 - 1/4 Mile WNW
A2	USGS40000832101	1/4 - 1/2 Mile NNE
3	USGS40000832056	1/4 - 1/2 Mile ENE
A4	USGS40000832122	1/4 - 1/2 Mile NNE
5	USGS40000832149	1/4 - 1/2 Mile North
B6	USGS40000831804	1/4 - 1/2 Mile SSE
7	USGS40000832121	1/4 - 1/2 Mile NE
B8	USGS40000831758	1/4 - 1/2 Mile SSE
9	USGS40000831759	1/2 - 1 Mile SW
10	USGS40000832176	1/2 - 1 Mile NNW
11	USGS40000832113	1/2 - 1 Mile WNW
C12	USGS40000831627	1/2 - 1 Mile SW
C13	USGS40000831628	1/2 - 1 Mile SW
14	USGS40000832219	1/2 - 1 Mile NW
15	USGS40000832187	1/2 - 1 Mile ENE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found


Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 4977850.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Newsday	CLIENT:	Gaiatech Real Estate Division
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Grace Riordan
		INQUIRY #:	4977850.2s
LAT/LONG:	40.763451 / 73.406648	DATE:	June 27, 2017 9:25 am

Copyright © 2017 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
WNW **FED USGS** **USGS40000832018**
1/8 - 1/4 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404550073243501		
Monloc name:	S 65546. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.763988
Longitude:	-73.4092883	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	54
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1994-03-02		62.91

A2
NNE **FED USGS** **USGS40000832101**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404602073241501		
Monloc name:	S 7271. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7673213
Longitude:	-73.4037325	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	406
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

3
ENE **FED USGS** **USGS40000832056**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404555073240501		
Monloc name:	S112871. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7653768
Longitude:	-73.4009547	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	40
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4
NNE **FED USGS** **USGS40000832122**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404605073241701		
Monloc name:	S 66132. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7681546
Longitude:	-73.4042881	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	140
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-09-13		66.56	1982-06-30		67.39
1982-03-12		67.24	1981-12-14		66.00
1981-06-15		68.07	1980-12-19		69.51
1980-09-15		70.97	1980-06-27		72.06
1980-03-06		69.84	1980-01-17		70.64

5
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000832149**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404608073242101		
Monloc name:	S 42680. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7689879
Longitude:	-73.4053992	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.7
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 66

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-12-29					
Note: The well was destroyed (no water level is recorded).					
1982-09-27		66.48	1982-09-13		66.78
1982-06-30		67.56	1982-06-14		67.58
1982-03-16		67.13	1982-03-12		67.25
1981-12-14		65.98	1981-09-15		66.97
1981-06-16		68.03	1981-06-12		68.03
1981-03-26		69.58	1981-01-05		69.22
1980-12-11		69.79	1980-09-26		70.91
1980-06-25		72.30	1980-03-25		70.94
1979-12-27		70.85	1979-09-21		71.80

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1979-06-20		72.90	1979-04-12		72.66
1979-03-26		70.78	1979-03-20		72.77
1979-01-22		71.13	1978-12-22		68.94
1978-12-21		69.10	1978-11-20		69.06
1978-10-23		69.62	1978-10-04		69.87
1978-09-25		70.04	1978-08-22		70.65
1978-07-25		70.53	1978-06-27		70.85
1978-06-17		70.99	1978-06-01		71.05
1978-04-20		70.94	1978-03-28		71.01
1977-12-27		68.49	1977-09-26		66.03
1977-07-27		66.46	1977-06-22		66.94
1977-04-05		67.98	1976-12-21		67.79
1976-09-21		68.85	1976-06-22		69.35
1976-03-22		69.96	1975-12-30		68.43
1975-09-29		68.31	1975-09-04		68.31
1975-06-24		68.20	1975-06-18		68.07
1975-03-26		66.73	1975-02-20		66.43
1974-12-16		65.73	1974-10-09		66.57
1974-09-20		66.82	1974-08-05		67.00
1974-07-18		67.39	1974-06-03		68.24
1973-07-09		68.73	1973-04-03		62.77
1973-01-23		63.65	1972-10-02		62.40
1972-07-12		62.99	1972-03-27		62.60
1972-01-20		62.23			

B6
SSE **FED USGS** **USGS40000831804**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404530073241101		
Monloc name:	S 43811. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7584324
Longitude:	-73.4026215	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	102.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	197206	Welldepth:	90
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 48

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1994-03-23		61.83	1990-03-01		65.10
1983-03-04		60.61	1982-12-08		61.27
1982-09-07		62.82	1982-06-16		63.58
1982-03-02		63.08	1981-12-04		61.77
1981-09-08		62.55	1981-06-12		63.48
1981-03-03		64.08	1980-12-02		65.21
1980-09-04		66.60	1979-06-25		68.44
1979-04-17		68.26	1979-03-20		68.32
1979-01-22		65.03	1978-12-21		64.23
1978-11-20		64.49	1978-10-23		64.86
1978-09-25		65.34	1978-09-22		65.88
1978-08-22		65.88	1978-07-25		66.11
1978-06-27		66.42	1978-06-01		66.42
1978-04-12		66.38	1978-03-23		66.76
1977-12-08		63.29	1977-10-03		61.63
1977-06-09		64.66	1977-03-22		62.99
1976-12-23		63.75	1976-10-13		65.08
1976-06-21		64.74	1976-04-12		65.43
1975-12-15		63.73	1975-10-02		63.90
1975-06-18		63.88	1975-02-15		61.93
1974-12-04		61.27	1974-08-05		62.64
1974-07-08		63.46	1974-05-24		64.11
1974-04-12		63.88	1974-03-11		63.17
1974-02-11		63.12	1974-01-17		62.88

7
NE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000832121**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404605073240801		
Monloc name:	S 4656. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7681546
Longitude:	-73.401788	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	141
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B8
SSE **FED USGS** **USGS40000831758**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404527073241201		
Monloc name:	S 23059. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7575991
Longitude:	-73.4028993	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	105.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	204
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

9
SW **FED USGS** **USGS40000831759**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404527073244601		
Monloc name:	S 31023. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7575992
Longitude:	-73.412344	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	384
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

10
NNW **FED USGS** **USGS40000832176**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404612073244501		
Monloc name:	S 10830. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7700991
Longitude:	-73.412066	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	110.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	80
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

11
WNW **FED USGS** **USGS40000832113**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404604073245801		
Monloc name:	S 57666. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7678769
Longitude:	-73.4156773	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	105.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	270
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

C12
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831627**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404518073250201		
Monloc name:	S 19538. 1		
Monloc type:	Well		
Monloc desc:	NEW: S 80573. 1 19850913		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7550992
Longitude:	-73.4167887	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19610322	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

C13
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831628**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404518073250202		
Monloc name:	S 80573. 1		
Monloc type:	Well		
Monloc desc:	OLD: S 19538. 1 19850913		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7550992
Longitude:	-73.4167887	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	19850913	Welldepth:	200
Welldepth units:	ft	Wellholedepth:	202
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

14
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000832219**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404617073250701		
Monloc name:	S 11262. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.771488
Longitude:	-73.4181774	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	110.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	175
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

15
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000832187**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404613073233601		
Monloc name:	S 5869. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7703767
Longitude:	-73.3928988	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	200.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	191
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
SUFFOLK	BABYLON	49	1.07	0.76	5.5
SUFFOLK	BROOKHAVEN	117	1.61	1.22	7.5
SUFFOLK	E. HAMPTON	19	1.55	1.16	4.7
SUFFOLK	HUNTINGTON	146	2.13	1.47	22.2
SUFFOLK	ISLIP	61	1.19	0.74	10.4
SUFFOLK	NORTHPORT	4	1.43	1.12	2.5
SUFFOLK	RIVERHEAD	9	2.18	1.26	8.9
SUFFOLK	SHELTER ISLAND	1	1.1	1.1	1.1
SUFFOLK	SMITHTOWN	60	3.02	1.48	42.6
SUFFOLK	SOUTHAMPTON	24	0.99	0.8	2.8
SUFFOLK	SOUTHOLD	7	2.47	1.58	8.6

Federal EPA Radon Zone for SUFFOLK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SUFFOLK COUNTY, NY

Number of sites tested: 183

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.670 pCi/L	100%	0%	0%
Basement	1.010 pCi/L	98%	2%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix E

Resumes



ROBERT B. ANDERSON
SENIOR ENVIRONMENTAL CONSULTANT -
TRANSACTION ADVISORY SERVICES GROUP
DENVER, COLORADO

SUMMARY

- Completed Phase I ESAs for commercial, residential, and industrial sites
- Conducted compliance audits at industrial facilities
- Performed Phase II ESAs
- Prepared regulatory reporting leading to site closures
- Conducted remedial activities at contaminated sites
- Prepared SPCC and SWPPP Plans
- Prepared annual Tier II reports

EDUCATION

Bachelor of Arts in Physics, Amherst College, Amherst, Massachusetts, 2006

ADDITIONAL TRAINING

OSHA 40 Hour HAZWOPER

OSHA 8 Hour Annual HAZWOPER Refreshers

Environmental Professional as defined by ASTM standards

PROFILE

Mr. Anderson is a Senior Environmental Consultant and a member of the Transactional Services group in RPS GaiaTech's west region. In this role, he is responsible for conducting Phase I Environmental Site Assessments (ESAs) and compliance audits of commercial and industrial facilities. Mr. Anderson has performed Phase II subsurface investigations and prepared regulatory reports leading to site closures. He has performed site remediation activities including the design and installation of remediation systems, subsurface chemical injection, UST removals with closure sampling, and soil and groundwater monitoring activities. Mr. Anderson has conducted facility inspections and prepared reports for SPCC and SWPPP plans for quarries. He has also prepared annual Tier II reports for a client with locations across several different states.

EXAMPLE PROJECT EXPERIENCE

Phase I ESAs

- Performed and managed 150+ Phase I ESAs for commercial, residential, and industrial sites.

Compliance Audits

- Performed 80+ compliance audits of industrial facilities.

Deal Coordination

- Coordinated environmental due diligence for deals including 37 automotive maintenance facilities, five industrial sites, and several smaller portfolios.

Subsurface Investigations

- Managed and performed Phase II subsurface investigations based on RECs identified in Phase I ESAs.
- Prepared regulatory reports leading to site closures with the environmental regulatory agencies.
- Prepared Baseline Environmental Assessments based on subsurface sampling for due diligence protection with the Michigan Department of Natural Resources and Environment.

Remedial Activities

- Assisted in the design and installation of air sparge and soil vapor extraction remediation systems.
- Planned and conducted subsurface chemical injection activities.
- Perform UST removals, excavation of contaminated soil, and closure sampling.
- Conducted soil and groundwater sampling to monitor the progress of remediation systems.

Environmental Compliance

- Conducted inspections and prepared reports for SPCC and SWPPP plans for quarries.
- Prepared annual Tier II reports for a client with locations across several different states.

GRACE RIORDAN
ENVIRONMENTAL CONSULTANT -
DUE DILIGENCE GROUP
CHICAGO, ILLINOIS

SUMMARY

- Completed and reviewed Phase I ESAs for commercial, and residential sites
- Assisted in the research and investigation of multiple Phase I ESAs

EDUCATION

Bachelors of Arts in Geography: Sustainable Systems, Minor in Public and Environmental Affairs from Indiana University, 2014

PROFILE

Ms. Riordan is an Associate Environmental Consultant and a member of the Due Diligence group in RPS GaiaTech's Chicago office. In this role, she is responsible for conducting Phase I Environmental Site Assessments (ESAs) for stock purchase, asset purchase, refinancing, and foreclosure transactions. She has performed radon surveys as a non-ASTM part of Phase I ESAs, as requested by clients. She has also been responsible for creating scopes of work, budgets, and tracking the status of various types of environmental reports.

EXAMPLE PROJECT EXPERIENCE

Corporate Reviews and Desktop Audits

- Reviewed environmental policies, procedures, and compliance obligations.
- Researched environmental claims or enforcement actions formerly or currently filed against the company or its facilities.
- Reviewed State and Federal environmental databases for former and current facilities to identify environmental impact or compliance concerns.
- Evaluated the potential of future liability associated with off-site disposal facilities and Potentially Responsible Party (PRP) claims.
- Conducted environmental due-diligence and quantified potential environmental liabilities associated with site operations.

Phase I ESAs

- Performed and managed Phase I ESAs
- Assisted with Phase I ESAs and environmental compliance audits for facilities in North America.
- She has performed radon surveys as a non-ASTM part of Phase I ESAs, as requested by clients.

135 S LaSalle Street, Suite 3500, Chicago, Illinois 60603
T 312 541 4200 W rpsgroup.com/usa

Privileged and Confidential

March 8, 2018

Mr. Robert F. Lawrence
Orrick, Herrington & Sutcliffe LLP
Columbia Center
1152 15th Street, N.W.
Washington, D.C. 20005-1706

Re: Limited Phase II Site Investigation Report - DRAFT
Newsday Media Group
235 Pinelawn Road
Melville, New York 11747

Dear Mr. Lawrence:

GaiaTech Incorporated dba RPS performed a limited Phase II Site Investigation (Phase II) at the Newsday Media Group facility located at 235 Pinelawn Road, Melville, New York, Suffolk County, New York (the "Site"). The Site location is identified on the attached Figure 1 located in Appendix A. The investigation was conducted in accordance with the approved proposal dated November 29, 2017. This investigation was completed to assess potential impacts identified in the Phase I Environmental Site Assessment (ESA) completed at the site by RPS in July 2017. A summary of the sampling activities and findings of the limited Phase II investigation are summarized below.

BACKGROUND

The roughly 50-acre site is developed with an approximately 539,000 square foot production building, which is divided between an office area, production areas and a wastewater treatment plant. The production areas contain a packaging and bundling area, a reel room where paper reels are fed to the printing lines, two levels of printing presses, boiler rooms, emergency generator rooms, a cooling tower room, various chemical storage areas, mechanical rooms, electrical rooms and maintenance shops. Chemical storage areas include three bermed areas (containing fountain solution aboveground storage tanks [ASTs], press oil and degreasers) and ink ASTs. Based on the available historical records, the Phase I report identified 15 underground storage tanks (USTs), including three 20,000-gallon diesel USTs, one 2,500-gallon fuel oil UST, and 11 historical USTs operated at the site. The four active USTs were reported to be in good working condition and in compliance with current UST regulations.

The Phase I site assessment conducted by RPS in July 2017 and including additional follow-up research revealed the following potential concerns in connection with the Site:

Potential Subsurface Concerns

- **Historical Site Operations and Former USTs**: Newsday has operated as a newspaper printing facility since the late 1970s. Printing operations have included the use of petroleum-

based inks, washes, oils and chlorinated solvents. The facility has also generated hazardous waste including silver and spent solvents. While limited soil and groundwater investigations have been performed in the vicinity of a two former fuel oil USTs (indicating no actionable impacts), a few other former USTs were present in agency records for which no post-removal sampling was conducted, and the exact locations of these former tanks was uncertain.

- Twelve current or historical USTs were identified as follows:

UST System(s) Summary					
Tank ID	*Contents*	*Capacity (gallons)*	*Installation Date*	*Removal Date*	*Comment*
1	Diesel	25,000	1978	1986	Former location believed to be in the paved parking area near the wastewater treatment plant; No historical sampling performed.
2	Diesel	25,000	1978	1986	Same as above
3	Diesel	25,000	1978	1986	Same as above
4	Gasoline	12,000	1978	1986	Same as above
5	Spill containment	2,000	1978	1988	Location unknown; believed to be near the wastewater treatment building; No historical sampling is known to have occurred.
6	No. 6 fuel oil	25,000	1978	Abandoned 2010	SE corner of building; **No concerns; previous sampling conducted.**
7	No. 2 fuel oil	25,000	1978	Abandoned 2010	SE corner of building; **No concerns; previous sampling conducted.**
8	Industrial Waste	4,000	1978	1987	Location unknown; No historical sampling is known to have occurred.
14	Diesel	20,000	1985	2010	South side of property, replaced in 2010 with new USTs; **No concerns; previous sampling conducted during UST upgrade activities.**

15	Diesel	20,000	1985	2010	Same as above; **No concerns; previous sampling conducted during UST upgrade activities.**
16	Diesel	20,000	1985	2010	Same as above; **No concerns; previous sampling conducted during UST upgrade activities.**
18	Diesel	2,500	NA	NA	Double wall fiberglass tank; Active tank with leak/over fill detectors. **No concerns noted.**

Of the 12 current and historical USTs, the exact former locations of tanks #1 through #5, and #8 were unknown, and no previous sampling was performed. The other USTs are either currently in operation and/or proper sampling and closure/abandonment has been performed. Due to the nature of the on-site operations, Tanks #1 through 4 were likely used for vehicle refueling services at the site. Based upon RPS' review of aerial photo from 1980, the refueling is believed to have been conducted in the western parking lot area (in the general vicinity off the wastewater treatment plant). It appears that these refueling services were relocated to the southwestern portion of the site where tanks #14 through 16 were installed in 1985.

COMPLETED SCOPE OF WORK

As a result of the Phase I findings, RPS conducted a Limited Phase II Investigation to assess potential concerns identified in the July 2017 Phase I ESA. This included the potential for impacts to soil, groundwater and/or soil-gas from historical on-site operations (including solvent use) and the former removed or abandoned on-site USTs for which no previous sampling was performed.

As described in the November 29, 2017 proposal, RPS completed six soil borings, five sub-slab soil vapor sampling points, three additional soil-gas sampling points and two temporary wells at the Site. Additional groundwater sampling points were planned, however, due to the presence of hard, compacted sand, gravel and cobbles, the Geoprobe unit was unable to reach groundwater in most locations. As such, soil gas sampling was substituted for groundwater sampling in 3 locations.

Per the approved proposal, the property was subdivided into a northern portion and southern portion. As the northern portion had not historically contained industrial operations, the investigation was focused on the southern portion only. The borings/wells were advanced to evaluate potential impacts to the subsurface related to the potential concerns identified in the Phase I, including:

- Historic use of inks, washes, oils and chlorinated solvents throughout the production area:
  - two soil borings
  - five soil-gas sampling points
- Wastewater Treatment Plant Area (also the general vicinity of Tanks 1through 5) :

  - one soil boring
  - one temporary well
- Presumed Location of former Tanks 1 through 4 (10K & 20K-gallon gasoline & diesel USTs):
  - one soil boring
  - one soil-gas point
- Along Northern Boundary of Southern Portion
  - two soil borings
  - two soil-gas points (with one of the two samples analyzed)

All soil and groundwater samples were analyzed for volatile organic compounds (VOCs) by USEPA Method 5035/8260C, polycyclic aromatic hydrocarbons (PAHs) by US EPA 8270D-SIM, and total or dissolved Resource Conservation and Recovery Act (RCRA) metals by US EPA 6010C & 7471A . The soil-gas and sub-slab vapor point samples were analyzed for VOCs by US EPA Method TO-15. The approximate sample locations are shown in Figure 2.

Field Activities

RPS cleared public subsurface utilities through the Dig Safely New York one call locating system. For safety purposes and prior to installing any soil borings, RPS also retained a private utility locating company (Ground Penetrating Radar Systems, LLC, GPRS) to verify that the proposed soil boring and temporary monitoring well locations were clear of underground utilities. The GPRS used a combination of radio-frequency locators, magnetometers and ground penetrating radar to clear each boring location. On January 17 to 19, 2018, RPS installed a total of six borings at the Site, with a few driven down to the water table and converted to temporary monitoring wells. Five sub-slab vapor samples and three soil-gas samples were also collected. The locations of the borings and temporary monitoring wells are shown on Figure 2 (Appendix A).

Soil Sampling

Borings were advanced around the Site to investigate the potential subsurface impacts from the reported historical operations. Two of the borings (GP-1 and GP-2) were completed inside the building. In most cases, soil samples were collected on a continuous basis using the direct-push probe. Each soil interval was field screened for VOC vapors using a photoionization detector (PID). Where field screening results suggested impact in soil, soil samples were selected for possible analysis. In the event field screening results do not indicate contamination, soil samples will be selected from a depth interval most likely to be impacted or at a location under an identified structure or UST.

The boring locations and sampling rationale are provided in the table below.

Boring Name	Depth (feet)	Rationale
GP-1	15	Historic use of inks, washes, oils and chlorinated solvents
GP-2	20	Historic use of inks, washes, oils and chlorinated solvents
GP-3	26	Former UST location (Tanks 1-4)
GP-4	25	Wastewater treatment area & Vicinity of tanks 1 through 4
GP-5	25	Northern parking lot area/boundary between northern and southern parcels
GP-6	25	Northern parking lot area/ boundary between northern and southern parcels

Soil borings were advanced to depths ranging from 15 and 26 feet below ground surface (bgs) using a Geoprobe® rig. Generally, continuous soil samples were collected from ground surface the bottom of each borehole using 5-foot stainless steel sampling tubes lined with plastic sample liners. In some cases, a spilt spoon sampler was used due to borehole caving and rocky soils. Due to the difficult drilling conditions the Duel Tube, Macrocore and discreet sampler were used with varying success. Upon retrieval from the sampling tube, each soil sample was visually inspected for evidence of contamination and logged in accordance with the Unified Soil Classification System. Portions of each soil sample were collected in separate sample bags for field-screening with a handheld, MiniRAE 3000 PID. The PID was equipped with a 10.6eV lamp and was calibrated to a 100 volumetric parts per million (Vppm) isobutylene standard. The field screening was used to provide an indication of the potential presence of volatile organic vapors to aid in the selection of samples for laboratory analysis. Soil boring logs, which include the PID readings, are included in Appendix B.

One soil sample from each location was submitted to the laboratory for analysis. Soil samples were collected directly into appropriate laboratory-supplied bottles, secured in a sample cooler and preserved with ice. The selected soil samples were analyzed for VOCs, PAHs, and total RCRA metals (arsenic, barium, cadmium, chromium, lead, mercury, selenium and silver). These analytical parameters were selected based on known materials used at the Site. The sample interval from each boring was selected for analysis based on the following criteria:

- The soil sample that exhibited the highest headspace concentration and/or visual evidence of impact; or

- A depth likely to display the presence of impact or corresponding to the base of a sub-grade structure or UST.

Under standard sample chain-of-custody procedures, all soil samples were delivered via FedEx to ESC Lab Sciences (ESC) in Mount Juliet, Tennessee, a New York accredited chemical analytical laboratory. The soil samples were analyzed using U.S. Environmental Protection Agency (USEPA) Methods 5035/8260C (VOCs), 8270D-SIM (PAHs), and 6010B/7470A (RCRA metals).

Groundwater Sampling

RPS proposed to collect groundwater samples from each of the six borings at the Site. However, since groundwater was not encountered above 26 feet bgs, the maximum depth explored using the Geoprobe rig, Temporary well points were installed and groundwater samples were collected from two borings (GP-4 and GP-6), advanced to depths of 50 and 60 feet bgs, respectively. These locations were selected for overall site coverage. Due to the difficulty in advancing the boreholes with caving dry soils, cobbles and rocky materials, a temporary well point was installed via drive casing. The wells were constructed of one inch diameter, 0.010 inch slotted polyvinyl chloride (PVC) screen and one inch diameter PVC riser casing. The well screens were placed at the base of the boring to intercept groundwater present within the unconsolidated zone.

Temporary well GP-4 was installed at a depth of 50 feet bgs with a 10 foot long screen in the sewage treatment area. Well GT-6 was installed in the northern parking lot area at a depth of 60 feet bgs and also constructed with a 10 foot long screen. Groundwater was encountered at depths of 40-42 feet at GP-4 and 52 feet at GP-6. The difference in water levels between the two wells is attributed to the variation in surface elevation between the two well points.

Following well installation, the wells were purged of sediment with a check valve with the assistance of a peristaltic pump. The wells were developed by removing enough water (approximately 3-gallons) until the groundwater was relatively free of turbidity. A groundwater sample from each temporary well was then collected shortly after development. Under standard sample chain-of-custody procedures, the collected groundwater samples were delivered via FedEx to ESC. The groundwater samples were analyzed using USEPA Methods 8260C (VOCs), 8270D (PAHs), and 6010B/7470A (dissolved RCRA metals – lab filtered).

Sub-slab and Soil-gas Sampling

Sub-slab Vapor Points - To evaluate the potential for interior soil vapor intrusion, five sub-slab vapor points (SS-1 through SS-5) were installed in the building. One sub-slab soil vapor point sample (SS-1) was located in a utility area in the middle of the office area, while another sample (SS-2)was installed in the newsprint paper storage area/near the printing area and the final three samples (SS-3, SS-4 and SS-5) were installed in the general printing area of the plant. The vapor point locations were selected for overall building coverage (Figure 2). Installation of the points, connection testing and sampling were consistent with the 2006 New York State Department of Heath Final Guidance for Evaluating Soil Vapor Intrusion in the State of New York.

All interior sub-slab vapor points were installed by drilling a 3/8 inch whole through the floor slab and installing a vapor pin sealed with a silicone rubber outer seal set within the drill hole. The vapor pin was further sealed with clay on the concrete top surface to ensure a good seal. Teflon hosting was connected to the pin and by swage lock nut to a 30-minute flow regulator attached to a laboratory supplied 6-liter Summa canister and a peristaltic pump. The peristaltic pump was used to purge the air under the slab and to test the various sampling train connections by inducing a vacuum to test the floor connection. The entire sampling train assembly and vapor pin floor seal was next tested by releasing helium into a plastic enclosure sealed to the floor surface. Within this enclosure the sampling train was inserted to test all of the connections. The pump air output was then tested via a helium meter to ensure all seals were acceptable for sampling. The testing at all vapor pin locations determined that the seals were found to be acceptable and sampling could be completed.

The sub-slab vapor testing began by removing the peristaltic pump/hose from the assembly and subsequently turning on the valve to the Summa canister. The starting time and initial vacuum pressure were noted on the canister label. The flow regulator was allowed to run for approximately 30-minues at each location. The final time and canister vacuum was noted on the label and the 30-minute period was complete and the summa valve was shutoff. Following valve shutoff, the flow regulator was removed and the canister sealed above the valve with the supplied nut. The canister was then placed in a box for transport to the laboratory. The samples were then, shipped to ESC laboratory under standard chain-of-custody protocol and analyzed for VOCs using USEPA Method TO-15.

Soil-gas Sampling

Due to the time and difficulty of obtaining deep groundwater samples at the site, soil-gas samples were collected to evaluate three of the exterior boring locations in lieu of a groundwater sample. Samples were collected generally to look for any high concentration anomalous readings that could indicate groundwater impact. Three soil-gas samples were collected near (6 feet away) from soil borings GP-3, GP-5 and GP-6. GP-6 was not analyzed since a groundwater sample was later collected from this location.

Soil-gas points were installed at a depth of between 5 and 6 feet below the ground surface. A macrocore Geoprobe boring was initially advanced to the stated depth and a soil-gas screen was installed at the base of the boring and attached to a Teflon hose. Clean sand was placed around the soil-gas inlet screen and also several inches above the screen. Above the sand, granulated bentonite was hydrated up and above the ground surface to provide a good seal. The seal and sampling assembly was tested as previously described above. All seals in the sampling train were found to be acceptable and testing began with the Teflon hose connected directly to the flow regulator and 6-liter summa canister. Testing was also completed similar to the sub-slab samples with a 30-minute testing period. The samples were then, shipped to ESC laboratory under standard chain-of-custody protocol and analyzed for VOCs using USEPA Method TO-15.

Site Restoration

Upon completion of sampling activities, and between uses to avoid cross contamination, all down-hole soil boring and non-dedicated sampling equipment was decontaminated. The decontamination train included an Alconox®/water wash and scrubbing, followed by a potable water rinse. Once the samples were collected, the boreholes were back-filled with soil cuttings and bentonite chips. The surface was then restored (to the extent feasible) to its original condition.

FINDINGS AND RESULTS

The following section summarizes the findings of the limited Phase II investigation conducted by RPS on January 17 to 19, 2018.

Geology, Hydrogeology and Field Screening Results

Soil borings were advanced in both the interior and exterior areas of the Site. Concrete and asphalt pavement were present at four of the six soil boring locations. Crushed stone, sand or sand and gravel fill were present under the pavement to a depth of approximately 1to 4 feet bgs. Native sand and gravel with cobbles were encountered between from base of the fill materials to a depth of 26 feet, the deepest level reached via the Geoprobe rig. No obvious visual, olfactory or elevated PID readings were found at any boring location.
The soil boring logs are presented in Appendix B.

Onsite Newsday personnel stated that when the wastewater plant was constructed, groundwater was present at approximately 45 feet below ground surface in geotechnical borings completed in the area Groundwater was not encountered in the upper 26 feet (the maximum depth explored) during the standard soil borings activities. In order to sample the groundwater, in two locations near the former Tanks 1 through 4, drive casing was pushed by the Geoprobe rig to a depth of 50 feet and a temporary well was installed with a reported water level of approximately 40-42 feet bgs. The second temporary well was installed at boring GP-6 by pushing the drive casing to a

depth of 60 feet. The water level in this temporary well was measured at approximately 52 feet bgs

Topography in the area varies considerably across the site, with the northern parking lot area as the highest point, with the ground surface generally sloping to the south. The lowest point on the property is in the area of the sewage treatment plant that appears to be around 10 to12 feet lower in elevation than the northern parking lot. The area topography and likely groundwater flow is to the south and towards Oster Bay of the Atlantic Ocean around 7.5 miles from the Site.

Soil Analytical Results

RPS compared all soil analytical results to the New York State Department of Environmental Conservation (NYDEC) Soil Cleanup Objectives for Unrestricted Use and Restricted Use, Protection of Public Health for Restricted Residential, Commercial, Industrial, Protection of Ecological Resources and Protection of Groundwater. The results of the soil analysis are summarized in Table 1 (in Appendix C) and are discussed below. The laboratory analytical report is provided in Appendix D.

VOCs

The soil analysis detected acetone in soil samples collected from two borings (GP-5 and GP-6). Although NYSDEP does not have soil cleanup standards for acetone, the detected concentrations are generally low and are not believed to pose a concern. The soil analysis did not detect other VOCs at concentrations in excess of laboratory detection limits or NYSDEC soil cleanup objectives.

PAHs

Several PAHs were detected in soil samples collected from four borings (GP-1, GP-2, GP-3 and GP-5); however, none of the PAHs were present at concentrations in excess of NYSDEC soil cleanup objectivities.

Total Metals

Several metals (arsenic, barium, chromium, lead, mercury and/or cadmium) were detected in soil collected from all six borings (GP-1 through GP-6). All concentrations, however, were below the NYSDEC soil cleanup objectives.

Groundwater Analytical Results

RPS compared all groundwater sample results to the NYDEC Section 701.15 Class GA – Fresh Groundwater Quality Standards (GAs) within the New York State Technical and Operational Guidance Series (TOGS) for ambient water quality values. The laboratory analytical results are summarized in Table 2 (included in Appendix C) and are discussed below. The laboratory analytical report is provided in Appendix D.

VOCs

The groundwater analysis detected one VOC (dichlorodifluoromethane) in samples collected from the two temporary wells (GP-4 and GP-6). The concentrations (1.51 and 0.749 micrograms per liter [ug/L], respectively) did not exceed the GA (5 ug/L). The groundwater analysis did not detect other VOCs at concentrations in excess of laboratory detection limits or GAs.

PAHs

The groundwater analysis detected several PAHs in samples collected from the two temporary wells (GP-4 and GP-6). Benzo(b)flouranthene was present in samples collected from both temporary (GP-4 and GP-6) at concentrations of 0.00424 ug/L and 0.00255 ug/L, respectively, which exceed the GA (0.002 ug/L). The two exceedances were noted in the qualifiers in the lab report as being found in the method blank (B qualifier) and the value was estimated (J qualifier). With the Exception of B(b)P, no other PAHs exceeded the NYSDEC GAs.

Dissolved Metals

The groundwater analysis detected two RCRA metals, (barium and mercury) in samples collected from the temporary wells (GP-4 and GP-6). The concentrations of barium (24.7 ug/L and 85.6 ug/L, respectively) did not exceed the NYSDEC GA (1,000 ug/L). Similarly, the concentration of mercury detected in the sample collected from GP-4 (0.0514 mg/L) did not exceed its GA (0.7 ug/L).

Sub-slab Soil Vapor and Soil-gas Sampling Results

The sub-slab soil vapor and soil-gas samples were compared to both the September 2006 New York State Brownfield Cleanup Program Technical Support Document's Inhalation Toxicity Values for Priority Contaminants and to the 2002 US EPA Office of Solid Waste and Emergency Response (OSWER) shallow soil-gas vapor intrusion guidance values as no New York values have been established for outside soil gas. The OSWER levels were used for a qualitative review of the soil gas sample results. The 2006 New York State Department of Heath Final Guidance for Evaluating Soil Vapor Intrusion in the State of New York was also used to evaluate the significance of any exceedance to the toxicity values.

The results of the sub-slab vapor and exterior soil-gas analysis are summarized in Table 3 (included in Appendix C) and are discussed below. The laboratory analytical report is provided in Appendix D.

Interior Sub-slab VOC Results

Several VOC compounds were detected in the five interior sub-slab vapor points (SS-1 through SS-5). The vapor analysis detected two compounds (carbon tetrachloride and 1,2,4-trimethylbenzene) at concentrations that exceed the Toxicity Values for Priority Contaminants (TVPC). The 1,2,4-trimethylbenzene (1,2,4-TMB) concentration (11 micrograms per cubic meter (ug/m^3)) exceeded the TVPC guidance level of 6 ug/m^3 in sample location SS-2 (located in the newsprint paper warehouse). The carbon tetrachloride concentration (6.67 ug/m^3) also exceeded the TVPC concentration of 2 ug/m^3 collected at sample location SS-3 (located in the middle of the plant).

Exterior Soil-gas VOC Results

The soil-gas analysis detected several VOCs in the two exterior soil-gas samples (SG-1 and SG-2). New York State does not have regulatory limits for exterior soil-gas concentrations; therefore,

RPS used the US EPA OSWER vapor intrusion guidance as a qualitative tool to evaluate the exterior soil-gas concentrations. The soil-gas analysis detected two compounds, 1,2,4-TMB (63.8 ug/m^3) and 1,3-butadiene (8.8 ug/m^3) in sample SG-2 at concentrations that slightly exceeds US EPA OSWER concentrations of 60 ug/m^3 and 8.7 ug/m^3, respectively. RPS does not consider these slight exceedances of the US EPA OSWER to be significant that would be indicative of any groundwater impact.

CONCLUSIONS AND RECOMMENDATIONS

Based upon the above findings, RPS provides the following conclusions and recommendations:

Conclusions

During the completion of the limited Phase II investigation six soil, two groundwater, five sub-slab vapor points and two soil-gas samples were collected and analyzed during the investigation. All soil and groundwater samples were analyzed for VOCs, PAHs and RCRA metals. The sub-slab and soil-gas samples were analyzed for VOCs. Based on the sampling results the following conclusions were drawn:

Soils

- Soils at the site were found to consist of 1 to 4 feet of sandy fill or topsoil underlain by sand and gravel with cobbles to a depth of 26 feet. Area geology information indicates that the sandy units extend into the groundwater. Groundwater was found to be present at approximately 42 to 52 feet bgs.

- The soil analysis did not detect VOCs, PAHs, or RCRA metals at concentrations in excess of any NYSDEC soil cleanup objectives.

Groundwater

- The groundwater sampling identified no VOCs or RCRA metals at concentrations in excess of GAs. With the exception of benzo(b)flouranthene, the groundwater analyses did not detect PAHs at concentrations in excess of GAs. RPS notes that due to the presence of benzo(b)flouranthene (B(b)F) in the lab-produced blank sample, it appears likely that the B(b)F detection is a laboratory artifact, rather than an actual constituent of the groundwater sample. Additionally, even if present, groundwater at the Site is not used as a potable supply source, and as such, low-level detections such as these are not believed to pose ingestion or other significant exposure concerns or any likely threat of off-site migration. According to agency records, the nearest down-gradient (south) potable well is present at a distance of greater than ½ mile from the boundary of the property. Due to the relative distance from the site and the low B(b)F concentration detected, the B(b)F, if present in the groundwater beneath the Newsday site, appears to pose no significant risk to the any down gradient sources

Soil-Gas and Sub-slab Vapor

- Analysis of sub-slab vapor samples detected VOCs at concentrations in excess of TVPCs in

two of five samples. The analysis detected 1,2,4-TMB in one sample and carbon tetrachloride in another sample at concentrations in excess TVPCs. The compound exceedances were generally isolated to one sample out of five and "hit and miss" detections.

- Based upon these results, RPS concludes that the analysis did not detect severe or wide-spread presence of VOCs below the floor slab.

- Analysis of two soil-gas samples collected in outdoor areas detected several VOCs. New York State does not have regulatory limits for exterior soil-gas concentrations; therefore, RPS used the US EPA OSWER vapor intrusion guidance as a qualitative tool to evaluate the exterior soil-gas concentrations. The soil-gas analysis detected low levels of two petroleum compounds (1,2,4-TMB and 1,3-butadiene) in one sample at concentrations that slightly exceeds US EPA OSWER concentrations. Due to the relatively low concentrations and the exterior location, RPS does not consider these slightly elevated detections to be significant.

The soil, groundwater and soil gas/vapor sampling performed by RPS to investigate potential spills and releases from historical site operations did not identify any significant subsurface impacts. While minor detections of VOCs were present in the vapors beneath the building in isolated locations, their "hit or miss" dispersion suggests that no widespread impacts are present. Additionally, the potential for vapor intrusion into the building is low. The building slab is 8 to 10 inches thick, which serves to retard vapor migration into the plant, and the plant generally has high (15 to 20 ft.) ceilings throughout, which serves to dissipate and dilute any vapors that might migrate into the building. Based on these findings, no further investigation is warranted.

LIMITATIONS

This report is prepared for the sole benefit of Orrick, Herrington & Sutcliffe LLP, approved parties or any of its affiliates and their respective successors and assigns who may each rely on this report. This report and the findings shall not, in whole or in part, be relied upon by any other party, nor used by any other party, without the prior written consent of RPS and an authorized representative of Orrick, Herrington & Sutcliffe LLP.

RPS has conducted these professional services in accordance with current scientific principles and industrial standards of practices in the fields of environmental science and engineering on the date the work was conducted and in the same geographical area of the subject Site for similar studies. RPS's findings must be considered as professional opinions based upon the limited data collected during the course of the environmental Site investigation, which is limited in time and scope.

Independent laboratories qualified to perform analyses have performed analytical laboratory analyses. RPS has derived the findings, in part, from the analytical reports. These findings are contingent upon the validity of the analytical reports, provided RPS exercised the applicable standard of care in reviewing and assessing the analytical reports.

CLOSING

We appreciate the opportunity to be of service on this project.

Sincerely,

RPS | Environmental Risk

Completed By:



Larry Bertsch, PG
Senior Geologist II – Project Manager

Technical Review and Concurrence by:



Steve Kline, PE
President

CC: Matthew Weisberg - Tribune Real Estate Holdings, LLC
Rita DeBoer - Tribune Media


Appendices
A - Figures
B - RPS Soil Boring and Well Construction Logs
C - Analytical Summary Tables
D - Laboratory Analytical Reports and Chain-of-Custody Documentation

Appendix A

Figures

- **Figure 1 - Site Location Map**
- **Figure 2 - Site Layout and Sample Location Map**





Scale 1:24 000
Contour Interval 20 Feet

1 0 1 MILE
1000 0 1000 2000 3000 4000 5000 6000 7000 FEET
1 .5 0 1 KILOMETER

NEW YORK

Quadrangle Location

UNITED STATES GEOLOGICAL SURVEY
DEPARTMENT OF THE INTERIOR/USGS
HUNTINGTON QUADRANGLE
NEW YORK – SUFFOLK COUNTY
7.5 MINUTE SERIES (TOPOGRAPHIC)


2016

Newsday
235 Pinelawn Road
Melville, New York
Project No. 167855.420.00

Figure 1

Site Location Map

RPS


NORTH
RULAND ROAD
PINELAWN ROAD
DESHON DRIVE
BASEBALL FIELD AND BASKETBALL COURT
2x EMERGENCY GENERATORS (EACH WITH ONE 1,100-GALLON DIESEL ASTs) AND 2x PAD-MOUNTED TRANSFORMERS
2,500-GALLON #2 DIESEL UST
APARTMENT COMPLEX
FORMER 25,000-GALLON NO.6 AND NO.2 FUEL OIL USTs
15,000-GALLON #2 FUEL OIL AST
DIESEL DAY TANKS
WASTEWATER TREATMENT PLANT (LAB BUILDING, SLUDGE TANKS, AERATORS AND MEMBRANES)
FIRE PREVENTION BASIN
3x 20,000-GALLON DIESEL USTs AND FUEL PUMPS
GP-1
GP-2
GP-3
GP-4
GP-5
GP-6
SG-1
SG-2
SG-3
SS-1
SS-2
SS-3
SS-4
SS-5
LEGEND
SITE BOUNDARY
GEOPROBE SOIL BORING LOCATION
SUB-SLAB VAPOR POINT
SOIL GAS POINT
SAMPLE COLLECTED BUT NOT ANALYZED DUE TO SUBSEQUENT COLLECTION OF GROUNDWATER SAMPLE
DESCRIPTION:
NEWSDAY
235 PINELAWN ROAD
MELVILLE, NEW YORK
DRAWN: JB
SCALE: 1"=300'
DATE: 3/9/18
FILE: 167855.420.00
FIGURE: 2
SITE LAYOUT & SAMPLE LOCATIONS
RPS

Appendix B

RPS Soil Boring and Well Construction Logs



BORING LOG GP-1

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
RPS Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 1/17/18	Logged By	: L. Bertsch
Date/Time Completed	: 1/17/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 15 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	:	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Hand Auger/Dual Tube/Mac

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0					FB		Concrete
1	1		90	0	AR		Fill - Yellow Brown Fine Grained Sand, dry, no odor.
2							
3	2			0			
4							
5	3		60	0.8	SW-GW		Light Brown Sand and Gravel, Cobbles, Very Compact, Dry, No Odor
6	4			1.5			
7							
8							
9							
10	5		70	1.6			
11							
12							
13	6			1.8			
14							
15							Refusal on a Rock - End of Boring at 15 Feet

02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-1 Newsday NY.bor

BORING LOG GP-2

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
RPS Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 1/17/18	Logged By	: L Bertsch
Date/Time Completed	: 1/17/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 20 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	:	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Hand Auger, Macrocore

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0					FB		Concrete
1	1		100%	3.1	AR		Fill - Yellow Brown Fine Grained Sand
2					FB		Concrete
3	2			3.9	SW-GW		Light Brown Sand and Gravel, Cobbles, Compact, Dry, No Odor
4							
5	3		80	4.6			
6							
7	4			4.5			
8							
9							
10	5		75	2.6			
11							
12							
13	6			1.9			
14							
15							
16	7		90	2			
17							
18							
19	8			1.6			
20							Refusal on a rock - End of Boring at 20 Feet

02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-2 Newsday NY.bor

BORING LOG GP-3

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
RPS Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 1/18/18	Logged By	: L Bertsch
Date/Time Completed	: 1/18/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 25 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	:	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Macrocore, Split Spoon

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0					FB		Asphalt
1	1		75%	3.1	AR		Fill - Sand and Gravel, No Odor, Dry
2							Light Brown Sand and Gravel, Very Compact, Cobbles, No Odor, Dry
3	2			4.8			
4							
5	3		90%	3			
6							
7	4			3.8			
8							
9	5		60	3.6			
10							
11	6			4.2	SW/GW		
12							
13							
14	7		60	5.9			
15							
16	8		NS	NS			
17							
18	9		75	0.9			
19							
20	10		NS	NS			
21							
22							
23	11		75	1.0			
24							
25							End of Boring at 26 Feet
26							
27							
28							
29							
30							

02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-3 Newsday NY.bor


RPS BORING LOG GP-4

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
GaiaTech Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 01/18/18	Logged By	: Larry Bertsch
Date/Time Completed	: 01/18/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 25 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	: 50 ft bgs	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Duel Tube or Macro core

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0	1		40	0.9	SM		Dark Brown Silty Sand with Organics, Topsoil
	2			1.3			Brown to Light Brown Sand and Gravel, Compact, Dry, No Odor
5	3		30	1.3			
	4						
10	5		30	1.2			
	6				SW-GW		
15	7		25	1.8			
	8						
20	9		25	0.9			
	10						
25							End of Boring at 25 Feet
30							
35							
40							
45							
50							



02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-4 Newsday NY.bor

BORING LOG GP-5

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
RPS Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 1/19/18	Logged By	: L Bertsch
Date/Time Completed	: 1/19/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 25 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	:	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Dual Tube

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0					FB		Asphalt
1	1		80	1	AR		Fill - Sand and Gravel, No Odor, Dry
2							
3	2			1.9	ML		Brown Silt, Trace of Clay, Moist, Firm, No Odor
4					SW-GW		Light Brown Sand and Gravel, Dry, No Odor, Compact
5	3		75	1.6			
6							
7	4			1.1			
8							
9	5		50	1.3			
10							
11	6			1.2			
12							
13							
14	7		50	0.9			
15							
16							
17	8			0.8			
18							
19							
20	9		50	0.6			
21							
22							
23	10			0.5			
24							
25							End of Boring at 25 Feet
26							
27							
28							
29							
30							

02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-5 Newsday NY.bor


RPS BORING LOG GP-6

(PAGE 1 TO 1)

Newsday
235 Pinelawn Road
Melville, New York
GaiaTech Project #167855.420.00

FUNCTION INFORMATION			
Date/Time Started	: 01/19/18	Logged By	: Larry Bertsch
Date/Time Completed	: 01/19/18	Drilling Method	: Geoprobe (Track)
Total Depth of Boring	: 25 ft bgs	Hole Diameter	: 2 inches
Total Depth of Well	: 60 ft bgs	Drilling Company	: Eastern Env Solutions
		Sampling Method	: Dual Tube

Depth In	Sample	Blow Count	% Recovery	PID (ppm)	USCS	GRAPHIC	Description
0	1		90	0.7	AR		Topsoil, No Odor
	2			0.9			Brown to Light Brown Sand and Gravel, occasional cobble, Compact, Dry, No Odor
5	3		60	0.2			
	4			0.5			
10	5		60	0.6			
	6			0.3	SW-GW		
15	7		70	0.5			
	8			0.5			
20	9		80	0.3			
	10			0.1			
25							End of Boring at 25 Feet
30							
35							
40							
45							
50							
55							
60							



02-01-2018 H:\Active Projects\167855.420.00 Limited Phase II Investigation with ACM\Technical\GP-6 Newsday NY updated.bor

Appendix C

Tables

1 – Soil Sample Analytical Results Summary
2 – Groundwater Analytical Results Summary
3 – Soil Gas & Sub-slab Analytical Results Summary



Project No. 167855.420.00

Table 1
Soil Analytical Data
(detected parameters)

Newsday
235 Pinelawn Rd.
Melville, NY

Sample Identification	Unrestricted Use Soil Cleanup Objectives	Restricted Use Soil Cleanup Objectives - Residential	Restricted Use Soil Cleanup Objectives - Commercial	Restricted Use Soil Cleanup Objectives - Industrial	Protection of Ecological Resources	Protection of Groundwater	**GP-1**	**GP-2**	**GP-3**	**GP-4**	**GP-5**	**GP-6**
Sample Depth (feet)							13-15'	5-7'	15-17'	15-17'	3.5-5'	3.5'
Sample Date							1/19/2018	1/19/2018	1/19/2018	1/19/2018	1/19/2018	1/19/2018
VOCs - USEPA Method 8260C	***mg/kg***											
Acetone	NE	NE	NE	NE	NE	NE	BDL	BDL	BDL	BDL	0.0124* J	0.0101* J
All Other VOCs	Varies	Varies	Varies	Varies	Varies	Varies	BDL	BDL	BDL	BDL	BDL	BDL
Polynuclear Aromatic Hydrocarbons - Method 8270D-SIM	***mg/kg***											
Anthracene	100	100	500	1,000	NE	1,000	BDL	0.000658 J	BDL	BDL	BDL	BDL
Benzo(a)anthracene	1	1	5.6	1.1	NE	1	0.00116 J	0.000945 J	BDL	BDL	BDL	BDL
Benzo(a)pyrene	1	1	1	1.1	2.6	22	0.00106 J	BDL	BDL	BDL	BDL	BDL
Benzo(b)fluoranthene	1	1	5.6	11	NE	1.7	0.00106 J	0.000649 J	BDL	BDL	BDL	BDL
Benzo(g,h,i)perylene	100	100	500	1,000	NE	1,000	0.00116 J	0.00101 J	BDL	BDL	BDL	BDL
Benzo(k)fluoranthene	0.8	3.9	56	110	NE	1.7	0.000767 J	BDL	BDL	BDL	BDL	BDL
Chrysene	1	3.9	56	110	NE	1	0.0011 J	0.000834 J	BDL	BDL	BDL	BDL
Fluoranthene	100	100	500	1,000	NE	1,000	0.00225 J	0.00168 J	BDL	BDL	BDL	BDL
Fluorene	30	100	500	1,000	30	386	BDL	BDL	BDL	BDL	BDL	BDL
Indeno(1,2,3-cd)pyrene	0.5	0.5	5.6	11	NE	8.2	0.000931 J	0.000709 J	BDL	BDL	BDL	BDL
Naphthalene	12	100	500	1,000	NE	12	0.00282 BJ	0.00256 BJ	0.00276 BJ	BDL	0.00273 BJ	BDL
Phenanthrene	100	100	500	1,000	NE	1,000	0.00158 J	0.0025 J	0.000742 J	BDL	BDL	BDL
Pyrene	100	100	500	1,000	NE	1,000	0.00175 J	0.00221 J	BDL	BDL	BDL	BDL
All Other PAHs	Varies	Varies	Varies	Varies	Varies	Varies	BDL	BDL	BDL	BDL	BDL	BDL
RCRA Metals - USEPA Method 6010C & 7471A	***mg/kg***											
Arsenic	13	16	16	16	13	16	1.61 J	1.95 J	0.695 J	0.904 J	4.33	3.22
Barium	350	400	400	10,000	433	820	13.5	13.6	3.26	7.34	27.8	12.5
Cadmium	2.5	4.3	9.3	60	4	7.5	BDL	0.184 J	BDL	BDL	BDL	BDL
Chromium	30	180	1,500	6,800	41	NE	16.9	16.7	1.51	2.82	16	4.23
Lead	63	400	1,000	3,900	63	450	2.87	3.14	1.2	1.25	7.33	3.82
Mercury	0.18	0.81	2.8	5.7	0.18	0.73	0.00915 BJ	0.0118 BJ	0.00593 BJ	0.00763 BJ	0.0451	0.00923 BJ
All other metals	Varies	Varies	Varies	Varies	Varies	Varies	BDL	BDL	BDL	BDL	BDL	BDL

Notes:
Samples analyzed by ESC Lab Sciences, Mt. Juliet, TN
Only detected analytes shown
NE = Not Established, NA= Not Applicable, BDL= Below Laboratory Detection Limi
Standards obtained from New York State Dept. of Env Conservation:
Table 375-6.8(a): Unrestircted Use Soil Cleanup Objectives
Table 375-6.8(b): Restricted Use Soil Cleanup Objectives
Shaded and bolded values exceed Soil Cleanup Objectives
*Acetone can be a laboratory artifact
B= The same analyte found in the associated method blank
J= The identification of the analyte is acceptable; the reported value is an estimate

Table 2
Groundwater Analytical Data

Sample Identification	Water Quality Standards Surface Waters and Groundwaters "GA"	GP-4	GP-6
Sample Date		1/19/2018	1/19/2018
VOCs - USEPA Method 8260	***ug/L***	***ug/L***	
Dichlorodifluoromethane	5	1.51 J	0.749 J
All Other VOC Analytes	Varies	BDL	BDL
Polynuclear Aromatic Hydrocarbons - Method 8270	***ug/L***	***ug/L***	
Acenaphthene	20	0.0164 J	BDL
Benzo(b)fluoranthene	0.002	**0.00424** BJ	**0.00255** BJ
Benzo(g,h,i)perylene	NE	0.00391 BJ	BDL
Fluorene	50	0.0306 J	BDL
Naphthalene	10	0.103 BJ	0.0816 BJ
Phenanthrene	50	0.0562	0.028 J
1-Methylnaphthalene	NE	0.0285 J	0.00872 J
2-Methylnaphthalene	NE	0.0373 J	0.0109 J
All other PAHs	Varies	BDL	BDL
RCRA Metals - USEPA Method 6010B & 7471A	***ug/L***	***ug/L***	
Barium	1,000	24.7	85.6
Mercury	0.7	0.0514 J	BDL
All other Metals	Varies	BDL	BDL

Notes:
Lab Analysis by ESC Lab Sciences, Mt. Juliet, TN
Only detected analytes are shown
NE = Not Established, NA=Not Applicable, BDL= Below Laboratory Detection Limits, NS=Not Sampled
Source of Drinking Water (groundwater) GA Standards obtained from New York State Dept. of Env Conservation Table 1 (cf. section 703.5)
TOGs NEW YORK STATE AMBIENT WATER QUALITY STANDARDS AND GUIDANCE VALUES June 1998
Bolded values exceed GA Water Quality Standards
B= The same analyte found in the associated method blank
J= The identification of the analyte is acceptable; the reported value is an estimate

Table 3
Soil Gas Analysis

Sample Identification	Toxicity Values for Priority Contaminants	EPA OSWER Subsurface Vapor Intrusion Guidance Shallow Soil Gas	SG-1	SG-2	SS-1	SS-2	SS-3	SS-4	SS-5
Gas Sample Type			Exterior Soil Gas		Interior Sub-Slab Vapor Samples				
Sample Date			1/18/2018	1/19/2018	1/18/2018	1/18/2018	1/19/2018	1/19/2018	1/19/2018
VOCs - USEPA Method TO-15	*ug/m³*								
Acetone	30,000	35,000	57.9	97.5	55.5	113	1,120	180	302
Benzene	30	310	4.11	5.63	1.44	BDL	16.3	3.32	2.75
Benzylchloride	NE	50	BDL	3.13	BDL	BDL	BDL	BDL	BDL
1,3-Butadiene	NE	8.7	6.01	**8.8**	BDL	BDL	BDL	BDL	BDL
Carbon Disulfide	NE	7,000	7.88	4.48	BDL	BDL	BDL	4.11	BDL
Carbon Tetrachloride	2	160	BDL	BDL	BDL	BDL	**6.67**	BDL	BDL
Chloroform	50	110	2.98	BDL	BDL	BDL	19.4	6.68	24.6
Cloromethane	NE	NE	0.538	BDL	BDL	BDL	0.945	0.479	0.726
2-Chlorotoluene	NE	NE	BDL	2.12	BDL	BDL	BDL	BDL	BDL
Cyclohexane	NE	NE	17	1	1.26	BDL	BDL	BDL	BDL
1,3-Dichlorobenzene	10	1,100	BDL	BDL	1.21	BDL	5.72	BDL	BDL
1,1-Dichloroethene	200	2,000	BDL	BDL	BDL	BDL	BDL	BDL	BDL
1,4-Dioxane	3,600	NE	BDL	BDL	BDL	BDL	2.28	BDL	BDL
Ethanol	NE	NE	11.4	7.61	110	78.2	548	247	380
Ethylbenzene	2,000	2,200	18.1	3.79	13.2	14.2	2.88	3.18	1.85
4-Ethyltoluene	NE	NE	29.6	19.3	1.56	BDL	3.96	3.34	5.06
Trichlorofluoromethane	NE	7,000	5.89	1.38	2.61	BDL	21.3	15.7	140
Dichlorodifluromethane	NE	2,000	92.7	36.6	6.16	BDL	75	13.5	118
Heptane	NE	NE	27	4.86	1.37	BDL	1.92	2.44	5.78
n-Hexane	NE	NE	13.3	4.97	1.3	BDL	2.6	1.31	2.54
Isopropylbenzene	NE	NE	11.4	2.3	BDL	BDL	BDL	BDL	BDL
Methylene Chloide	400	900	BDL	BDL	BDL	BDL	BDL	1.06	BDL
Methyl Butyl Ketone	NE	NE	BDL	BDL	BDL	BDL	10.2	BDL	11.2
2-Butanone (MEK)	5,000	10,000	56.1	33.1	9.77	BDL	47.3	19	30.5
4-Methyl-2-pentanone (MIBK)	NE	NE	BDL	BDL	BDL	BDL	7.3	BDL	8.71
Naphthalene	9.00	30	BDL	BDL	BDL	BDL	3.51	BDL	BDL
2-Propanol	NE	NE	3.74	BDL	1,620	147	669	27.4	184
Propene	NE	NE	49.3	45.6	BDL	BDL	56.7	5.09	8.6
Styrene	NE	10,000	BDL	0.947	BDL	BDL	6.98	1.06	0.984
1,1,2,2-Tetrachloroethane	NE	42	18.1	BDL	BDL	BDL	BDL	BDL	BDL
Tetrachloroethylene	100	810	4.87	1.53	3.04	BDL	10.6	3.67	16.2
Tertrahydrofuran	NE	NE	91.5	37.9	2.42	BDL	BDL	BDL	BDL
Toluene	300	4,000	18.9	7.76	41	10.9	53.1	4.08	9.27
1,1,1-Trichloroethane	2,200	22,000	BDL	BDL	BDL	BDL	11.8	BDL	BDL
Trichloethylene	40	22	2.38	BDL	BDL	BDL	2.91	BDL	BDL
1,2,4-Trimethylbenzene	6	60	24.5	**63.8**	1.75	**11**	5.36	3.9	5.96
1,3,5-Trimethylbenzene	6	60	18.4	21.2	BDL	BDL	1.39	1.08	1.3
2,2,4-Trimethylpentane	NE	NE	112	BDL	BDL	BDL	BDL	BDL	BDL
m&p xylene	100	70,000	63.7	14.8	46.5	59.2	11.5	12.3	7.45
o-Xylene	100	70,000	49.2	6.46	13	34.2	3.7	6.39	2.95
All other VOCs	NA	NA	BDL	BDL	BDL	BDL	BDL	BDL	BDL

Notes:

Samples analyzed by ESC Lab Sciences, Mt. Juliet, TN

Only detected analytes shown

NE = Not Established, NA= Not Applicable, BDL= Below Laboratory Detection Limits

SG=Soil Gas, SS=Sub-Slab

Standards obtained from: 2006 New York State Dept. of Env Conservation: Table 5.1.1-2 Toxicity Values for Priority Contaminants

Standards obtained from: EPA OSWER Subsurface Vapor Intrusion Guideance November 2002

Bolded values exceed EPA Values

Shaded & bolded values exceed NY Toxicity Values

Appendix D

Laboratory Analytical Reports and Chain-of-Custody Documentation



ANALYTICAL REPORT

January 29, 2018

GAIA Tech - Chicago, IL

Sample Delivery Group:	L964604
Samples Received:	01/20/2018
Project Number:	16785542000
Description:	Melville, NY
Site:	NY
Report To:	Larry Bertsch 135 S. LaSalle St, Ste 3500 Chicago, IL 60603

Entire Report Reviewed By:

Jason Romer
Technical Service Representative

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approval of the laboratory. Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures: 060302, 060303, and 060304.



TABLE OF CONTENTS

Cp: Cover Page 1

Tc: Table of Contents 2

Ss: Sample Summary 3

Cn: Case Narrative 5

Sr: Sample Results 6

GP-1 L964604-01 6

GP-2 L964604-02 9

GP-3 L964604-03 12

GP-4 L964604-04 15

GP-5 L964604-05 18

GP-6 L964604-06 21

GP-4 L964604-08 24

GP-6 L964604-09 26

Qc: Quality Control Summary 28

Total Solids by Method 2540 G-2011 28

Mercury by Method 7470A 30

Mercury by Method 7471B 31

Metals (ICP) by Method 6010C 32

Volatile Organic Compounds (GC/MS) by Method 8260C 34

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM 44

Gl: Glossary of Terms 48

Al: Accreditations & Locations 49

Sc: Sample Chain of Custody 50

GP-1 L964604-01 Solid

Collected by: Larry P Bertsch | Collected date/time: 01/17/18 13:30 | Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065860	1	01/25/18 07:40	01/25/18 07:50	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 17:04	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:12	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/17/18 13:30	01/22/18 19:11	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 17:04	ADF

GP-2 L964604-02 Solid

Collected by: Larry P Bertsch | Collected date/time: 01/17/18 18:00 | Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065855	1	01/25/18 07:52	01/25/18 08:04	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 18:01	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:15	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/17/18 18:00	01/22/18 19:31	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 17:26	ADF

GP-3 L964604-03 Solid

Collected by: Larry P Bertsch | Collected date/time: 01/18/18 09:00 | Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065860	1	01/25/18 07:40	01/25/18 07:50	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 18:03	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:27	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/18/18 09:00	01/22/18 19:51	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 17:48	ADF

GP-4 L964604-04 Solid

Collected by: Larry P Bertsch | Collected date/time: 01/19/18 08:50 | Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065860	1	01/25/18 07:40	01/25/18 07:50	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 18:06	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:30	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/19/18 08:50	01/22/18 20:11	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 18:10	ADF

GP-5 L964604-05 Solid

Collected by: Larry P Bertsch | Collected date/time: 01/19/18 11:08 | Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065860	1	01/25/18 07:40	01/25/18 07:50	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 18:08	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:34	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/19/18 11:08	01/22/18 23:26	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 18:32	ADF

GP-6 L964604-06 Solid

Collected by: Larry P Bertsch
Collected date/time: 01/19/18 12:05
Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Total Solids by Method 2540 G-2011	WG1065860	1	01/25/18 07:40	01/25/18 07:50	KDW
Mercury by Method 7471B	WG1064970	1	01/22/18 00:39	01/23/18 18:11	EL
Metals (ICP) by Method 6010C	WG1066494	1	01/26/18 11:31	01/28/18 23:37	ST
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065171	1	01/19/18 12:05	01/22/18 23:46	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064936	1	01/22/18 08:23	01/23/18 18:54	ADF

GP-4 L964604-08 GW

Collected by: Larry P Bertsch
Collected date/time: 01/19/18 09:10
Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Mercury by Method 7470A	WG1064955	1	01/22/18 01:26	01/22/18 17:10	EL
Metals (ICP) by Method 6010C	WG1064590	1	01/20/18 17:02	01/22/18 03:15	JDG
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065128	1	01/22/18 15:35	01/22/18 15:35	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064934	1	01/22/18 01:44	01/23/18 18:43	DMG

GP-6 L964604-09 GW

Collected by: Larry P Bertsch
Collected date/time: 01/19/18 15:15
Received date/time: 01/20/18 09:00

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Mercury by Method 7470A	WG1064955	1	01/22/18 01:26	01/22/18 17:12	EL
Metals (ICP) by Method 6010C	WG1064590	1	01/20/18 17:02	01/22/18 03:18	JDG
Volatile Organic Compounds (GC/MS) by Method 8260C	WG1065128	1	01/22/18 15:52	01/22/18 15:52	GLN
Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM	WG1064934	1	01/22/18 01:44	01/23/18 19:08	DMG

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times, unless qualified or notated within the report. Where applicable, all MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All radiochemical sample results for solids are reported on a dry weight basis with the exception of tritium, carbon-14 and radon, unless wet weight was requested by the client. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.



Jason Romer
Technical Service Representative

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	99.8		1	01/25/2018 07:50	WG1065860

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.00915	B J	0.00280	0.0200	1	01/23/2018 17:04	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	1.61	J	0.650	2.00	1	01/28/2018 23:12	WG1066494
Barium	13.5		0.170	0.500	1	01/28/2018 23:12	WG1066494
Cadmium	U		0.0700	0.500	1	01/28/2018 23:12	WG1066494
Chromium	16.9		0.140	1.00	1	01/28/2018 23:12	WG1066494
Lead	2.87		0.190	0.500	1	01/28/2018 23:12	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:12	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:12	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	U		0.0100	0.0500	1	01/22/2018 19:11	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 19:11	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 19:11	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 19:11	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 19:11	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 19:11	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 19:11	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 19:11	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 19:11	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 19:11	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 19:11	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 19:11	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 19:11	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 19:11	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 19:11	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 19:11	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 19:11	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 19:11	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 19:11	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 19:11	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 19:11	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 19:11	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 19:11	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 19:11	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 19:11	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 19:11	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 19:11	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 19:11	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 19:11	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 19:11	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 19:11	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 19:11	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 19:11	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 19:11	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 19:11	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 19:11	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 19:11	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 19:11	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 19:11	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 19:11	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 19:11	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 19:11	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 19:11	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 19:11	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 19:11	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 19:11	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 19:11	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 19:11	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 19:11	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 19:11	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 19:11	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 19:11	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 19:11	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 19:11	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 19:11	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 19:11	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 19:11	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 19:11	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 19:11	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 19:11	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 19:11	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 19:11	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 19:11	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 19:11	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 19:11	WG1065171
(S) Toluene-d8	*97.5*			*80.0-120*		*01/22/2018 19:11*	WG1065171
(S) Dibromofluoromethane	*103*			*74.0-131*		*01/22/2018 19:11*	WG1065171
(S) 4-Bromofluorobenzene	*95.8*			*64.0-132*		*01/22/2018 19:11*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	U		0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Benzo(a)anthracene	0.00116	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Benzo(a)pyrene	0.00106	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Benzo(b)fluoranthene	0.00106	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Benzo(g,h,i)perylene	0.00116	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Benzo(k)fluoranthene	0.000767	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Chrysene	0.00110	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Fluoranthene	0.00225	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Indeno(1,2,3-cd)pyrene	0.000931	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Naphthalene	0.00282	B J	0.00200	0.0200	1	01/23/2018 17:04	WG1064936
Phenanthrene	0.00158	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
Pyrene	0.00175	J	0.000600	0.00600	1	01/23/2018 17:04	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:04	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:04	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 17:04	WG1064936
(S) Nitrobenzene-d5	*74.0*			*14.0-149*		*01/23/2018 17:04*	WG1064936
(S) 2-Fluorobiphenyl	*78.7*			*34.0-125*		*01/23/2018 17:04*	WG1064936
(S) p-Terphenyl-d14	*71.5*			*23.0-120*		*01/23/2018 17:04*	WG1064936

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	99.0		1	01/25/2018 08:04	WG1065855

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.0118	B J	0.00280	0.0200	1	01/23/2018 18:01	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	1.95	J	0.650	2.00	1	01/28/2018 23:15	WG1066494
Barium	13.6		0.170	0.500	1	01/28/2018 23:15	WG1066494
Cadmium	0.184	J	0.0700	0.500	1	01/28/2018 23:15	WG1066494
Chromium	16.7		0.140	1.00	1	01/28/2018 23:15	WG1066494
Lead	3.14		0.190	0.500	1	01/28/2018 23:15	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:15	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:15	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	U		0.0100	0.0500	1	01/22/2018 19:31	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 19:31	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 19:31	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 19:31	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 19:31	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 19:31	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 19:31	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 19:31	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 19:31	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 19:31	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 19:31	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 19:31	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 19:31	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 19:31	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 19:31	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 19:31	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 19:31	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 19:31	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 19:31	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 19:31	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 19:31	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 19:31	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 19:31	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 19:31	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 19:31	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 19:31	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 19:31	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 19:31	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 19:31	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 19:31	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 19:31	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 19:31	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 19:31	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 19:31	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 19:31	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 19:31	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 19:31	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 19:31	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 19:31	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 19:31	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 19:31	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 19:31	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 19:31	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 19:31	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 19:31	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 19:31	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 19:31	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 19:31	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 19:31	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 19:31	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 19:31	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 19:31	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 19:31	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 19:31	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 19:31	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 19:31	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 19:31	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 19:31	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 19:31	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 19:31	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 19:31	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 19:31	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 19:31	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 19:31	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 19:31	WG1065171
(S) Toluene-d8	*96.6*			*80.0-120*		*01/22/2018 19:31*	WG1065171
(S) Dibromofluoromethane	*103*			*74.0-131*		*01/22/2018 19:31*	WG1065171
(S) 4-Bromofluorobenzene	*97.0*			*64.0-132*		*01/22/2018 19:31*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	0.000658	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Benzo(a)anthracene	0.000945	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Benzo(a)pyrene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Benzo(b)fluoranthene	0.000649	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Benzo(g,h,i)perylene	0.00101	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Benzo(k)fluoranthene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Chrysene	0.000834	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Fluoranthene	0.00168	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Indeno(1,2,3-cd)pyrene	0.000709	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Naphthalene	0.00256	B J	0.00200	0.0200	1	01/23/2018 17:26	WG1064936
Phenanthrene	0.00250	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
Pyrene	0.00221	J	0.000600	0.00600	1	01/23/2018 17:26	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:26	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:26	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 17:26	WG1064936
(S) Nitrobenzene-d5	*71.5*			*14.0-149*		*01/23/2018 17:26*	WG1064936
(S) 2-Fluorobiphenyl	*75.2*			*34.0-125*		*01/23/2018 17:26*	WG1064936
(S) p-Terphenyl-d14	*94.1*			*23.0-120*		*01/23/2018 17:26*	WG1064936

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	98.5		1	01/25/2018 07:50	WG1065860

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.00593	B J	0.00280	0.0200	1	01/23/2018 18:03	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	0.695	J	0.650	2.00	1	01/28/2018 23:27	WG1066494
Barium	3.26		0.170	0.500	1	01/28/2018 23:27	WG1066494
Cadmium	U		0.0700	0.500	1	01/28/2018 23:27	WG1066494
Chromium	1.51		0.140	1.00	1	01/28/2018 23:27	WG1066494
Lead	1.20		0.190	0.500	1	01/28/2018 23:27	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:27	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:27	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	U		0.0100	0.0500	1	01/22/2018 19:51	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 19:51	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 19:51	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 19:51	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 19:51	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 19:51	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 19:51	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 19:51	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 19:51	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 19:51	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 19:51	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 19:51	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 19:51	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 19:51	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 19:51	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 19:51	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 19:51	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 19:51	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 19:51	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 19:51	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 19:51	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 19:51	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 19:51	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 19:51	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 19:51	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 19:51	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 19:51	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 19:51	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 19:51	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 19:51	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 19:51	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 19:51	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 19:51	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 19:51	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 19:51	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 19:51	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 19:51	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 19:51	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 19:51	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 19:51	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 19:51	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 19:51	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 19:51	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 19:51	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 19:51	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 19:51	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 19:51	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 19:51	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 19:51	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 19:51	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 19:51	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 19:51	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 19:51	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 19:51	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 19:51	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 19:51	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 19:51	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 19:51	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 19:51	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 19:51	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 19:51	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 19:51	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 19:51	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 19:51	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 19:51	WG1065171
(S) Toluene-d8	*98.7*			*80.0-120*		*01/22/2018 19:51*	WG1065171
(S) Dibromofluoromethane	*103*			*74.0-131*		*01/22/2018 19:51*	WG1065171
(S) 4-Bromofluorobenzene	*96.2*			*64.0-132*		*01/22/2018 19:51*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Benzo(a)anthracene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Benzo(a)pyrene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Benzo(b)fluoranthene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Benzo(g,h,i)perylene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Benzo(k)fluoranthene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Chrysene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Fluoranthene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Indeno(1,2,3-cd)pyrene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Naphthalene	0.00276	B J	0.00200	0.0200	1	01/23/2018 17:48	WG1064936
Phenanthrene	0.000742	J	0.000600	0.00600	1	01/23/2018 17:48	WG1064936
Pyrene	U		0.000600	0.00600	1	01/23/2018 17:48	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:48	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 17:48	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 17:48	WG1064936
(S) Nitrobenzene-d5	*98.0*			*14.0-149*		*01/23/2018 17:48*	WG1064936
(S) 2-Fluorobiphenyl	*99.8*			*34.0-125*		*01/23/2018 17:48*	WG1064936
(S) p-Terphenyl-d14	*94.1*			*23.0-120*		*01/23/2018 17:48*	WG1064936

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	98.0		1	01/25/2018 07:50	WG1065860

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.00763	B J	0.00280	0.0200	1	01/23/2018 18:06	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	0.904	J	0.650	2.00	1	01/28/2018 23:30	WG1066494
Barium	7.34		0.170	0.500	1	01/28/2018 23:30	WG1066494
Cadmium	U		0.0700	0.500	1	01/28/2018 23:30	WG1066494
Chromium	2.82		0.140	1.00	1	01/28/2018 23:30	WG1066494
Lead	1.25		0.190	0.500	1	01/28/2018 23:30	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:30	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:30	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	U		0.0100	0.0500	1	01/22/2018 20:11	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 20:11	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 20:11	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 20:11	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 20:11	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 20:11	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 20:11	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 20:11	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 20:11	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 20:11	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 20:11	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 20:11	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 20:11	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 20:11	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 20:11	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 20:11	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 20:11	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 20:11	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 20:11	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 20:11	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 20:11	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 20:11	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 20:11	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 20:11	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 20:11	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 20:11	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 20:11	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 20:11	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 20:11	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 20:11	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 20:11	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 20:11	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 20:11	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 20:11	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 20:11	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 20:11	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 20:11	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 20:11	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 20:11	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 20:11	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 20:11	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 20:11	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 20:11	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 20:11	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 20:11	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 20:11	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 20:11	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 20:11	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 20:11	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 20:11	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 20:11	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 20:11	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 20:11	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 20:11	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 20:11	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 20:11	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 20:11	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 20:11	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 20:11	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 20:11	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 20:11	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 20:11	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 20:11	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 20:11	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 20:11	WG1065171
(S) Toluene-d8	*97.8*			*80.0-120*		*01/22/2018 20:11*	WG1065171
(S) Dibromofluoromethane	*102*			*74.0-131*		*01/22/2018 20:11*	WG1065171
(S) 4-Bromofluorobenzene	*100*			*64.0-132*		*01/22/2018 20:11*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Benzo(a)anthracene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Benzo(a)pyrene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Benzo(b)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Benzo(g,h,i)perylene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Benzo(k)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Chrysene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Indeno(1,2,3-cd)pyrene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Naphthalene	U		0.00200	0.0200	1	01/23/2018 18:10	WG1064936
Phenanthrene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
Pyrene	U		0.000600	0.00600	1	01/23/2018 18:10	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:10	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:10	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 18:10	WG1064936
(S) Nitrobenzene-d5	*73.0*			*14.0-149*		*01/23/2018 18:10*	WG1064936
(S) 2-Fluorobiphenyl	*77.8*			*34.0-125*		*01/23/2018 18:10*	WG1064936
(S) p-Terphenyl-d14	*69.4*			*23.0-120*		*01/23/2018 18:10*	WG1064936

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	89.1		1	01/25/2018 07:50	WG1065860

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.0451		0.00280	0.0200	1	01/23/2018 18:08	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	4.33		0.650	2.00	1	01/28/2018 23:34	WG1066494
Barium	27.8		0.170	0.500	1	01/28/2018 23:34	WG1066494
Cadmium	U		0.0700	0.500	1	01/28/2018 23:34	WG1066494
Chromium	16.0		0.140	1.00	1	01/28/2018 23:34	WG1066494
Lead	7.33		0.190	0.500	1	01/28/2018 23:34	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:34	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:34	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	0.0124	J	0.0100	0.0500	1	01/22/2018 23:26	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 23:26	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 23:26	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 23:26	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 23:26	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 23:26	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 23:26	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 23:26	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 23:26	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 23:26	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 23:26	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 23:26	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 23:26	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 23:26	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 23:26	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 23:26	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 23:26	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 23:26	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 23:26	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 23:26	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 23:26	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 23:26	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 23:26	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 23:26	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 23:26	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 23:26	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 23:26	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 23:26	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 23:26	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 23:26	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 23:26	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 23:26	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 23:26	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 23:26	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 23:26	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 23:26	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 23:26	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 23:26	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 23:26	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 23:26	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 23:26	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 23:26	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 23:26	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 23:26	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 23:26	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 23:26	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 23:26	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 23:26	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 23:26	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 23:26	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 23:26	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 23:26	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 23:26	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 23:26	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 23:26	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 23:26	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 23:26	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 23:26	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 23:26	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 23:26	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 23:26	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 23:26	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 23:26	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 23:26	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 23:26	WG1065171
(S) Toluene-d8	*95.7*			*80.0-120*		*01/22/2018 23:26*	WG1065171
(S) Dibromofluoromethane	*100*			*74.0-131*		*01/22/2018 23:26*	WG1065171
(S) 4-Bromofluorobenzene	*96.9*			*64.0-132*		*01/22/2018 23:26*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Benzo(a)anthracene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Benzo(a)pyrene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Benzo(b)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Benzo(g,h,i)perylene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Benzo(k)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Chrysene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Indeno(1,2,3-cd)pyrene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Naphthalene	0.00273	B J	0.00200	0.0200	1	01/23/2018 18:32	WG1064936
Phenanthrene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
Pyrene	U		0.000600	0.00600	1	01/23/2018 18:32	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:32	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:32	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 18:32	WG1064936
(S) Nitrobenzene-d5	*76.5*			*14.0-149*		*01/23/2018 18:32*	WG1064936
(S) 2-Fluorobiphenyl	*79.0*			*34.0-125*		*01/23/2018 18:32*	WG1064936
(S) p-Terphenyl-d14	*73.2*			*23.0-120*		*01/23/2018 18:32*	WG1064936

Total Solids by Method 2540 G-2011

Analyte	Result	Qualifier	Dilution	Analysis	Batch
	%			date / time	
Total Solids	92.8		1	01/25/2018 07:50	WG1065860

Mercury by Method 7471B

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Mercury	0.00923	B J	0.00280	0.0200	1	01/23/2018 18:11	WG1064970

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Arsenic	3.22		0.650	2.00	1	01/28/2018 23:37	WG1066494
Barium	12.5		0.170	0.500	1	01/28/2018 23:37	WG1066494
Cadmium	U		0.0700	0.500	1	01/28/2018 23:37	WG1066494
Chromium	4.23		0.140	1.00	1	01/28/2018 23:37	WG1066494
Lead	3.82		0.190	0.500	1	01/28/2018 23:37	WG1066494
Selenium	U		0.740	2.00	1	01/28/2018 23:37	WG1066494
Silver	U		0.280	1.00	1	01/28/2018 23:37	WG1066494

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	mg/kg		mg/kg	mg/kg		date / time	
Acetone	0.0101	J	0.0100	0.0500	1	01/22/2018 23:46	WG1065171
Acrylonitrile	U		0.00179	0.0100	1	01/22/2018 23:46	WG1065171
Benzene	U		0.000270	0.00100	1	01/22/2018 23:46	WG1065171
Bromobenzene	U		0.000284	0.00100	1	01/22/2018 23:46	WG1065171
Bromodichloromethane	U		0.000254	0.00100	1	01/22/2018 23:46	WG1065171
Bromoform	U		0.000424	0.00100	1	01/22/2018 23:46	WG1065171
Bromomethane	U		0.00134	0.00500	1	01/22/2018 23:46	WG1065171
n-Butylbenzene	U		0.000258	0.00100	1	01/22/2018 23:46	WG1065171
sec-Butylbenzene	U		0.000201	0.00100	1	01/22/2018 23:46	WG1065171
tert-Butylbenzene	U		0.000206	0.00100	1	01/22/2018 23:46	WG1065171
Carbon tetrachloride	U		0.000328	0.00100	1	01/22/2018 23:46	WG1065171
Chlorobenzene	U		0.000212	0.00100	1	01/22/2018 23:46	WG1065171
Chlorodibromomethane	U		0.000373	0.00100	1	01/22/2018 23:46	WG1065171
Chloroethane	U		0.000946	0.00500	1	01/22/2018 23:46	WG1065171
Chloroform	U		0.000229	0.00500	1	01/22/2018 23:46	WG1065171
Chloromethane	U		0.000375	0.00250	1	01/22/2018 23:46	WG1065171
2-Chlorotoluene	U		0.000301	0.00100	1	01/22/2018 23:46	WG1065171
4-Chlorotoluene	U		0.000240	0.00100	1	01/22/2018 23:46	WG1065171
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500	1	01/22/2018 23:46	WG1065171
1,2-Dibromoethane	U		0.000343	0.00100	1	01/22/2018 23:46	WG1065171
Dibromomethane	U		0.000382	0.00100	1	01/22/2018 23:46	WG1065171
1,2-Dichlorobenzene	U		0.000305	0.00100	1	01/22/2018 23:46	WG1065171
1,3-Dichlorobenzene	U		0.000239	0.00100	1	01/22/2018 23:46	WG1065171
1,4-Dichlorobenzene	U		0.000226	0.00100	1	01/22/2018 23:46	WG1065171
Dichlorodifluoromethane	U		0.000713	0.00500	1	01/22/2018 23:46	WG1065171
1,1-Dichloroethane	U		0.000199	0.00100	1	01/22/2018 23:46	WG1065171
1,2-Dichloroethane	U		0.000265	0.00100	1	01/22/2018 23:46	WG1065171
1,1-Dichloroethene	U		0.000303	0.00100	1	01/22/2018 23:46	WG1065171
cis-1,2-Dichloroethene	U		0.000235	0.00100	1	01/22/2018 23:46	WG1065171
trans-1,2-Dichloroethene	U		0.000264	0.00100	1	01/22/2018 23:46	WG1065171
1,2-Dichloropropane	U		0.000358	0.00100	1	01/22/2018 23:46	WG1065171
1,1-Dichloropropene	U		0.000317	0.00100	1	01/22/2018 23:46	WG1065171
1,3-Dichloropropane	U		0.000207	0.00100	1	01/22/2018 23:46	WG1065171

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
cis-1,3-Dichloropropene	U		0.000262	0.00100	1	01/22/2018 23:46	WG1065171
trans-1,3-Dichloropropene	U		0.000267	0.00100	1	01/22/2018 23:46	WG1065171
2,2-Dichloropropane	U		0.000279	0.00100	1	01/22/2018 23:46	WG1065171
Di-isopropyl ether	U		0.000248	0.00100	1	01/22/2018 23:46	WG1065171
Ethylbenzene	U		0.000297	0.00100	1	01/22/2018 23:46	WG1065171
Hexachloro-1,3-butadiene	U		0.000342	0.00100	1	01/22/2018 23:46	WG1065171
Isopropylbenzene	U		0.000243	0.00100	1	01/22/2018 23:46	WG1065171
p-Isopropyltoluene	U		0.000204	0.00100	1	01/22/2018 23:46	WG1065171
2-Butanone (MEK)	U		0.00468	0.0100	1	01/22/2018 23:46	WG1065171
Methylene Chloride	U		0.00100	0.00500	1	01/22/2018 23:46	WG1065171
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100	1	01/22/2018 23:46	WG1065171
Methyl tert-butyl ether	U		0.000212	0.00100	1	01/22/2018 23:46	WG1065171
Naphthalene	U		0.00100	0.00500	1	01/22/2018 23:46	WG1065171
n-Propylbenzene	U		0.000206	0.00100	1	01/22/2018 23:46	WG1065171
Styrene	U		0.000234	0.00100	1	01/22/2018 23:46	WG1065171
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100	1	01/22/2018 23:46	WG1065171
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100	1	01/22/2018 23:46	WG1065171
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100	1	01/22/2018 23:46	WG1065171
Tetrachloroethene	U		0.000276	0.00100	1	01/22/2018 23:46	WG1065171
Toluene	U		0.000434	0.00500	1	01/22/2018 23:46	WG1065171
1,2,3-Trichlorobenzene	U		0.000306	0.00100	1	01/22/2018 23:46	WG1065171
1,2,4-Trichlorobenzene	U		0.000388	0.00100	1	01/22/2018 23:46	WG1065171
1,1,1-Trichloroethane	U		0.000286	0.00100	1	01/22/2018 23:46	WG1065171
1,1,2-Trichloroethane	U		0.000277	0.00100	1	01/22/2018 23:46	WG1065171
Trichloroethene	U		0.000279	0.00100	1	01/22/2018 23:46	WG1065171
Trichlorofluoromethane	U		0.000382	0.00500	1	01/22/2018 23:46	WG1065171
1,2,3-Trichloropropane	U		0.000741	0.00250	1	01/22/2018 23:46	WG1065171
1,2,4-Trimethylbenzene	U		0.000211	0.00100	1	01/22/2018 23:46	WG1065171
1,2,3-Trimethylbenzene	U		0.000287	0.00100	1	01/22/2018 23:46	WG1065171
Vinyl chloride	U		0.000291	0.00100	1	01/22/2018 23:46	WG1065171
1,3,5-Trimethylbenzene	U		0.000266	0.00100	1	01/22/2018 23:46	WG1065171
Xylenes, Total	U		0.000698	0.00300	1	01/22/2018 23:46	WG1065171
(S) Toluene-d8	*97.4*			*80.0-120*		*01/22/2018 23:46*	WG1065171
(S) Dibromofluoromethane	*101*			*74.0-131*		*01/22/2018 23:46*	WG1065171
(S) 4-Bromofluorobenzene	*97.6*			*64.0-132*		*01/22/2018 23:46*	WG1065171

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
Anthracene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Acenaphthene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Acenaphthylene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Benzo(a)anthracene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Benzo(a)pyrene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Benzo(b)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Benzo(g,h,i)perylene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Benzo(k)fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Chrysene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Dibenz(a,h)anthracene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Fluoranthene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Fluorene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Indeno(1,2,3-cd)pyrene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Naphthalene	U		0.00200	0.0200	1	01/23/2018 18:54	WG1064936
Phenanthrene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
Pyrene	U		0.000600	0.00600	1	01/23/2018 18:54	WG1064936
1-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:54	WG1064936

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result mg/kg	Qualifier	MDL mg/kg	RDL mg/kg	Dilution	Analysis date / time	Batch
2-Methylnaphthalene	U		0.00200	0.0200	1	01/23/2018 18:54	WG1064936
2-Chloronaphthalene	U		0.00200	0.0200	1	01/23/2018 18:54	WG1064936
(S) Nitrobenzene-d5	*73.1*			*14.0-149*		*01/23/2018 18:54*	WG1064936
(S) 2-Fluorobiphenyl	*79.2*			*34.0-125*		*01/23/2018 18:54*	WG1064936
(S) p-Terphenyl-d14	*74.8*			*23.0-120*		*01/23/2018 18:54*	WG1064936

Mercury by Method 7470A

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Mercury,Dissolved	0.0514	J	0.0490	0.200	1	01/22/2018 17:10	WG1064955

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Arsenic,Dissolved	U		6.50	10.0	1	01/22/2018 03:15	WG1064590
Barium,Dissolved	24.7		1.70	5.00	1	01/22/2018 03:15	WG1064590
Cadmium,Dissolved	U		0.700	2.00	1	01/22/2018 03:15	WG1064590
Chromium,Dissolved	U		1.40	10.0	1	01/22/2018 03:15	WG1064590
Lead,Dissolved	U		1.90	5.00	1	01/22/2018 03:15	WG1064590
Selenium,Dissolved	U		7.40	10.0	1	01/22/2018 03:15	WG1064590
Silver,Dissolved	U		2.80	5.00	1	01/22/2018 03:15	WG1064590

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Acetone	U		10.0	50.0	1	01/22/2018 15:35	WG1065128
Acrolein	U	J3	8.87	50.0	1	01/22/2018 15:35	WG1065128
Acrylonitrile	U		1.87	10.0	1	01/22/2018 15:35	WG1065128
Benzene	U		0.331	1.00	1	01/22/2018 15:35	WG1065128
Bromobenzene	U		0.352	1.00	1	01/22/2018 15:35	WG1065128
Bromodichloromethane	U		0.380	1.00	1	01/22/2018 15:35	WG1065128
Bromoform	U		0.469	1.00	1	01/22/2018 15:35	WG1065128
Bromomethane	U		0.866	5.00	1	01/22/2018 15:35	WG1065128
n-Butylbenzene	U		0.361	1.00	1	01/22/2018 15:35	WG1065128
sec-Butylbenzene	U		0.365	1.00	1	01/22/2018 15:35	WG1065128
tert-Butylbenzene	U		0.399	1.00	1	01/22/2018 15:35	WG1065128
Carbon tetrachloride	U		0.379	1.00	1	01/22/2018 15:35	WG1065128
Chlorobenzene	U		0.348	1.00	1	01/22/2018 15:35	WG1065128
Chlorodibromomethane	U		0.327	1.00	1	01/22/2018 15:35	WG1065128
Chloroethane	U		0.453	5.00	1	01/22/2018 15:35	WG1065128
Chloroform	U		0.324	5.00	1	01/22/2018 15:35	WG1065128
Chloromethane	U		0.276	2.50	1	01/22/2018 15:35	WG1065128
2-Chlorotoluene	U		0.375	1.00	1	01/22/2018 15:35	WG1065128
4-Chlorotoluene	U		0.351	1.00	1	01/22/2018 15:35	WG1065128
1,2-Dibromo-3-Chloropropane	U		1.33	5.00	1	01/22/2018 15:35	WG1065128
1,2-Dibromoethane	U		0.381	1.00	1	01/22/2018 15:35	WG1065128
Dibromomethane	U		0.346	1.00	1	01/22/2018 15:35	WG1065128
1,2-Dichlorobenzene	U		0.349	1.00	1	01/22/2018 15:35	WG1065128
1,3-Dichlorobenzene	U		0.220	1.00	1	01/22/2018 15:35	WG1065128
1,4-Dichlorobenzene	U		0.274	1.00	1	01/22/2018 15:35	WG1065128
Dichlorodifluoromethane	1.51	J	0.551	5.00	1	01/22/2018 15:35	WG1065128
1,1-Dichloroethane	U		0.259	1.00	1	01/22/2018 15:35	WG1065128
1,2-Dichloroethane	U		0.361	1.00	1	01/22/2018 15:35	WG1065128
1,1-Dichloroethene	U		0.398	1.00	1	01/22/2018 15:35	WG1065128
cis-1,2-Dichloroethene	U		0.260	1.00	1	01/22/2018 15:35	WG1065128
trans-1,2-Dichloroethene	U		0.396	1.00	1	01/22/2018 15:35	WG1065128
1,2-Dichloropropane	U		0.306	1.00	1	01/22/2018 15:35	WG1065128
1,1-Dichloropropene	U		0.352	1.00	1	01/22/2018 15:35	WG1065128
1,3-Dichloropropane	U		0.366	1.00	1	01/22/2018 15:35	WG1065128
cis-1,3-Dichloropropene	U		0.418	1.00	1	01/22/2018 15:35	WG1065128
trans-1,3-Dichloropropene	U		0.419	1.00	1	01/22/2018 15:35	WG1065128
2,2-Dichloropropane	U		0.321	1.00	1	01/22/2018 15:35	WG1065128
Di-isopropyl ether	U		0.320	1.00	1	01/22/2018 15:35	WG1065128
Ethylbenzene	U		0.384	1.00	1	01/22/2018 15:35	WG1065128

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Hexachloro-1,3-butadiene	U		0.256	1.00	1	01/22/2018 15:35	WG1065128
Isopropylbenzene	U		0.326	1.00	1	01/22/2018 15:35	WG1065128
p-Isopropyltoluene	U		0.350	1.00	1	01/22/2018 15:35	WG1065128
2-Butanone (MEK)	U		3.93	10.0	1	01/22/2018 15:35	WG1065128
Methylene Chloride	U		1.00	5.00	1	01/22/2018 15:35	WG1065128
4-Methyl-2-pentanone (MIBK)	U		2.14	10.0	1	01/22/2018 15:35	WG1065128
Methyl tert-butyl ether	U		0.367	1.00	1	01/22/2018 15:35	WG1065128
Naphthalene	U		1.00	5.00	1	01/22/2018 15:35	WG1065128
n-Propylbenzene	U		0.349	1.00	1	01/22/2018 15:35	WG1065128
Styrene	U		0.307	1.00	1	01/22/2018 15:35	WG1065128
1,1,1,2-Tetrachloroethane	U		0.385	1.00	1	01/22/2018 15:35	WG1065128
1,1,2,2-Tetrachloroethane	U		0.130	1.00	1	01/22/2018 15:35	WG1065128
1,1,2-Trichlorotrifluoroethane	U		0.303	1.00	1	01/22/2018 15:35	WG1065128
Tetrachloroethene	U		0.372	1.00	1	01/22/2018 15:35	WG1065128
Toluene	U		0.412	1.00	1	01/22/2018 15:35	WG1065128
1,2,3-Trichlorobenzene	U		0.230	1.00	1	01/22/2018 15:35	WG1065128
1,2,4-Trichlorobenzene	U		0.355	1.00	1	01/22/2018 15:35	WG1065128
1,1,1-Trichloroethane	U		0.319	1.00	1	01/22/2018 15:35	WG1065128
1,1,2-Trichloroethane	U		0.383	1.00	1	01/22/2018 15:35	WG1065128
Trichloroethene	U		0.398	1.00	1	01/22/2018 15:35	WG1065128
Trichlorofluoromethane	U		1.20	5.00	1	01/22/2018 15:35	WG1065128
1,2,3-Trichloropropane	U		0.807	2.50	1	01/22/2018 15:35	WG1065128
1,2,4-Trimethylbenzene	U		0.373	1.00	1	01/22/2018 15:35	WG1065128
1,2,3-Trimethylbenzene	U		0.321	1.00	1	01/22/2018 15:35	WG1065128
1,3,5-Trimethylbenzene	U		0.387	1.00	1	01/22/2018 15:35	WG1065128
Vinyl chloride	U		0.259	1.00	1	01/22/2018 15:35	WG1065128
Xylenes, Total	U		1.06	3.00	1	01/22/2018 15:35	WG1065128
(S) Toluene-d8	*101*			*80.0-120*		*01/22/2018 15:35*	WG1065128
(S) Dibromofluoromethane	*103*			*76.0-123*		*01/22/2018 15:35*	WG1065128
(S) 4-Bromofluorobenzene	*102*			*80.0-120*		*01/22/2018 15:35*	WG1065128

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Anthracene	U		0.0140	0.0500	1	01/23/2018 18:43	WG1064934
Acenaphthene	0.0164	J	0.0100	0.0500	1	01/23/2018 18:43	WG1064934
Acenaphthylene	U		0.0120	0.0500	1	01/23/2018 18:43	WG1064934
Benzo(a)anthracene	U		0.00410	0.0500	1	01/23/2018 18:43	WG1064934
Benzo(a)pyrene	U		0.0116	0.0500	1	01/23/2018 18:43	WG1064934
Benzo(b)fluoranthene	0.00424	B J	0.00212	0.0500	1	01/23/2018 18:43	WG1064934
Benzo(g,h,i)perylene	0.00391	B J	0.00227	0.0500	1	01/23/2018 18:43	WG1064934
Benzo(k)fluoranthene	U		0.0136	0.0500	1	01/23/2018 18:43	WG1064934
Chrysene	U		0.0108	0.0500	1	01/23/2018 18:43	WG1064934
Dibenz(a,h)anthracene	U		0.00396	0.0500	1	01/23/2018 18:43	WG1064934
Fluoranthene	U		0.0157	0.0500	1	01/23/2018 18:43	WG1064934
Fluorene	0.0306	J	0.00850	0.0500	1	01/23/2018 18:43	WG1064934
Indeno(1,2,3-cd)pyrene	U		0.0148	0.0500	1	01/23/2018 18:43	WG1064934
Naphthalene	0.103	B J	0.0198	0.250	1	01/23/2018 18:43	WG1064934
Phenanthrene	0.0562		0.00820	0.0500	1	01/23/2018 18:43	WG1064934
Pyrene	U		0.0117	0.0500	1	01/23/2018 18:43	WG1064934
1-Methylnaphthalene	0.0285	J	0.00821	0.250	1	01/23/2018 18:43	WG1064934
2-Methylnaphthalene	0.0373	J	0.00902	0.250	1	01/23/2018 18:43	WG1064934
2-Chloronaphthalene	U		0.00647	0.250	1	01/23/2018 18:43	WG1064934
(S) Nitrobenzene-d5	*93.0*			*31.0-160*		*01/23/2018 18:43*	WG1064934
(S) 2-Fluorobiphenyl	*105*			*48.0-148*		*01/23/2018 18:43*	WG1064934
(S) p-Terphenyl-d14	*103*			*37.0-146*		*01/23/2018 18:43*	WG1064934

Mercury by Method 7470A

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Mercury,Dissolved	U		0.0490	0.200	1	01/22/2018 17:12	WG1064955

Metals (ICP) by Method 6010C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Arsenic,Dissolved	U		6.50	10.0	1	01/22/2018 03:18	WG1064590
Barium,Dissolved	85.6		1.70	5.00	1	01/22/2018 03:18	WG1064590
Cadmium,Dissolved	U		0.700	2.00	1	01/22/2018 03:18	WG1064590
Chromium,Dissolved	U		1.40	10.0	1	01/22/2018 03:18	WG1064590
Lead,Dissolved	U		1.90	5.00	1	01/22/2018 03:18	WG1064590
Selenium,Dissolved	U		7.40	10.0	1	01/22/2018 03:18	WG1064590
Silver,Dissolved	U		2.80	5.00	1	01/22/2018 03:18	WG1064590

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Acetone	U		10.0	50.0	1	01/22/2018 15:52	WG1065128
Acrolein	U	J3	8.87	50.0	1	01/22/2018 15:52	WG1065128
Acrylonitrile	U		1.87	10.0	1	01/22/2018 15:52	WG1065128
Benzene	U		0.331	1.00	1	01/22/2018 15:52	WG1065128
Bromobenzene	U		0.352	1.00	1	01/22/2018 15:52	WG1065128
Bromodichloromethane	U		0.380	1.00	1	01/22/2018 15:52	WG1065128
Bromoform	U		0.469	1.00	1	01/22/2018 15:52	WG1065128
Bromomethane	U		0.866	5.00	1	01/22/2018 15:52	WG1065128
n-Butylbenzene	U		0.361	1.00	1	01/22/2018 15:52	WG1065128
sec-Butylbenzene	U		0.365	1.00	1	01/22/2018 15:52	WG1065128
tert-Butylbenzene	U		0.399	1.00	1	01/22/2018 15:52	WG1065128
Carbon tetrachloride	U		0.379	1.00	1	01/22/2018 15:52	WG1065128
Chlorobenzene	U		0.348	1.00	1	01/22/2018 15:52	WG1065128
Chlorodibromomethane	U		0.327	1.00	1	01/22/2018 15:52	WG1065128
Chloroethane	U		0.453	5.00	1	01/22/2018 15:52	WG1065128
Chloroform	U		0.324	5.00	1	01/22/2018 15:52	WG1065128
Chloromethane	U		0.276	2.50	1	01/22/2018 15:52	WG1065128
2-Chlorotoluene	U		0.375	1.00	1	01/22/2018 15:52	WG1065128
4-Chlorotoluene	U		0.351	1.00	1	01/22/2018 15:52	WG1065128
1,2-Dibromo-3-Chloropropane	U		1.33	5.00	1	01/22/2018 15:52	WG1065128
1,2-Dibromoethane	U		0.381	1.00	1	01/22/2018 15:52	WG1065128
Dibromomethane	U		0.346	1.00	1	01/22/2018 15:52	WG1065128
1,2-Dichlorobenzene	U		0.349	1.00	1	01/22/2018 15:52	WG1065128
1,3-Dichlorobenzene	U		0.220	1.00	1	01/22/2018 15:52	WG1065128
1,4-Dichlorobenzene	U		0.274	1.00	1	01/22/2018 15:52	WG1065128
Dichlorodifluoromethane	0.749	J	0.551	5.00	1	01/22/2018 15:52	WG1065128
1,1-Dichloroethane	U		0.259	1.00	1	01/22/2018 15:52	WG1065128
1,2-Dichloroethane	U		0.361	1.00	1	01/22/2018 15:52	WG1065128
1,1-Dichloroethene	U		0.398	1.00	1	01/22/2018 15:52	WG1065128
cis-1,2-Dichloroethene	U		0.260	1.00	1	01/22/2018 15:52	WG1065128
trans-1,2-Dichloroethene	U		0.396	1.00	1	01/22/2018 15:52	WG1065128
1,2-Dichloropropane	U		0.306	1.00	1	01/22/2018 15:52	WG1065128
1,1-Dichloropropene	U		0.352	1.00	1	01/22/2018 15:52	WG1065128
1,3-Dichloropropane	U		0.366	1.00	1	01/22/2018 15:52	WG1065128
cis-1,3-Dichloropropene	U		0.418	1.00	1	01/22/2018 15:52	WG1065128
trans-1,3-Dichloropropene	U		0.419	1.00	1	01/22/2018 15:52	WG1065128
2,2-Dichloropropane	U		0.321	1.00	1	01/22/2018 15:52	WG1065128
Di-isopropyl ether	U		0.320	1.00	1	01/22/2018 15:52	WG1065128
Ethylbenzene	U		0.384	1.00	1	01/22/2018 15:52	WG1065128

Volatile Organic Compounds (GC/MS) by Method 8260C

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Hexachloro-1,3-butadiene	U		0.256	1.00	1	01/22/2018 15:52	WG1065128
Isopropylbenzene	U		0.326	1.00	1	01/22/2018 15:52	WG1065128
p-Isopropyltoluene	U		0.350	1.00	1	01/22/2018 15:52	WG1065128
2-Butanone (MEK)	U		3.93	10.0	1	01/22/2018 15:52	WG1065128
Methylene Chloride	U		1.00	5.00	1	01/22/2018 15:52	WG1065128
4-Methyl-2-pentanone (MIBK)	U		2.14	10.0	1	01/22/2018 15:52	WG1065128
Methyl tert-butyl ether	U		0.367	1.00	1	01/22/2018 15:52	WG1065128
Naphthalene	U		1.00	5.00	1	01/22/2018 15:52	WG1065128
n-Propylbenzene	U		0.349	1.00	1	01/22/2018 15:52	WG1065128
Styrene	U		0.307	1.00	1	01/22/2018 15:52	WG1065128
1,1,1,2-Tetrachloroethane	U		0.385	1.00	1	01/22/2018 15:52	WG1065128
1,1,2,2-Tetrachloroethane	U		0.130	1.00	1	01/22/2018 15:52	WG1065128
1,1,2-Trichlorotrifluoroethane	U		0.303	1.00	1	01/22/2018 15:52	WG1065128
Tetrachloroethene	U		0.372	1.00	1	01/22/2018 15:52	WG1065128
Toluene	U		0.412	1.00	1	01/22/2018 15:52	WG1065128
1,2,3-Trichlorobenzene	U		0.230	1.00	1	01/22/2018 15:52	WG1065128
1,2,4-Trichlorobenzene	U		0.355	1.00	1	01/22/2018 15:52	WG1065128
1,1,1-Trichloroethane	U		0.319	1.00	1	01/22/2018 15:52	WG1065128
1,1,2-Trichloroethane	U		0.383	1.00	1	01/22/2018 15:52	WG1065128
Trichloroethene	U		0.398	1.00	1	01/22/2018 15:52	WG1065128
Trichlorofluoromethane	U		1.20	5.00	1	01/22/2018 15:52	WG1065128
1,2,3-Trichloropropane	U		0.807	2.50	1	01/22/2018 15:52	WG1065128
1,2,4-Trimethylbenzene	U		0.373	1.00	1	01/22/2018 15:52	WG1065128
1,2,3-Trimethylbenzene	U		0.321	1.00	1	01/22/2018 15:52	WG1065128
1,3,5-Trimethylbenzene	U		0.387	1.00	1	01/22/2018 15:52	WG1065128
Vinyl chloride	U		0.259	1.00	1	01/22/2018 15:52	WG1065128
Xylenes, Total	U		1.06	3.00	1	01/22/2018 15:52	WG1065128
(S) Toluene-d8	*103*			*80.0-120*		*01/22/2018 15:52*	WG1065128
(S) Dibromofluoromethane	*103*			*76.0-123*		*01/22/2018 15:52*	WG1065128
(S) 4-Bromofluorobenzene	*101*			*80.0-120*		*01/22/2018 15:52*	WG1065128

Semi Volatile Organic Compounds (GC/MS) by Method 8270D-SIM

Analyte	Result	Qualifier	MDL	RDL	Dilution	Analysis	Batch
	ug/l		ug/l	ug/l		date / time	
Anthracene	U		0.0140	0.0500	1	01/23/2018 19:08	WG1064934
Acenaphthene	U		0.0100	0.0500	1	01/23/2018 19:08	WG1064934
Acenaphthylene	U		0.0120	0.0500	1	01/23/2018 19:08	WG1064934
Benzo(a)anthracene	U		0.00410	0.0500	1	01/23/2018 19:08	WG1064934
Benzo(a)pyrene	U		0.0116	0.0500	1	01/23/2018 19:08	WG1064934
Benzo(b)fluoranthene	0.00255	B J	0.00212	0.0500	1	01/23/2018 19:08	WG1064934
Benzo(g,h,i)perylene	U		0.00227	0.0500	1	01/23/2018 19:08	WG1064934
Benzo(k)fluoranthene	U		0.0136	0.0500	1	01/23/2018 19:08	WG1064934
Chrysene	U		0.0108	0.0500	1	01/23/2018 19:08	WG1064934
Dibenz(a,h)anthracene	U		0.00396	0.0500	1	01/23/2018 19:08	WG1064934
Fluoranthene	U		0.0157	0.0500	1	01/23/2018 19:08	WG1064934
Fluorene	U		0.00850	0.0500	1	01/23/2018 19:08	WG1064934
Indeno(1,2,3-cd)pyrene	U		0.0148	0.0500	1	01/23/2018 19:08	WG1064934
Naphthalene	0.0816	B J	0.0198	0.250	1	01/23/2018 19:08	WG1064934
Phenanthrene	0.0280	J	0.00820	0.0500	1	01/23/2018 19:08	WG1064934
Pyrene	U		0.0117	0.0500	1	01/23/2018 19:08	WG1064934
1-Methylnaphthalene	0.00872	J	0.00821	0.250	1	01/23/2018 19:08	WG1064934
2-Methylnaphthalene	0.0109	J	0.00902	0.250	1	01/23/2018 19:08	WG1064934
2-Chloronaphthalene	U		0.00647	0.250	1	01/23/2018 19:08	WG1064934
(S) Nitrobenzene-d5	*94.3*			*31.0-160*		*01/23/2018 19:08*	WG1064934
(S) 2-Fluorobiphenyl	*107*			*48.0-148*		*01/23/2018 19:08*	WG1064934
(S) p-Terphenyl-d14	*105*			*37.0-146*		*01/23/2018 19:08*	WG1064934

Method Blank (MB)

(MB) R3281893-1 01/25/18 08:04

Analyte	MB Result %	MB Qualifier	MB MDL %	MB RDL %
Total Solids	0			

L964573-21 Original Sample (OS) • Duplicate (DUP)

(OS) L964573-21 01/25/18 08:04 • (DUP) R3281893-3 01/25/18 08:04

Analyte	Original Result %	DUP Result %	Dilution	DUP RPD %	DUP Qualifier	DUP RPD Limits %
Total Solids	75.1	75.2	1	0		5

Laboratory Control Sample (LCS)

(LCS) R3281893-2 01/25/18 08:04

Analyte	Spike Amount %	LCS Result %	LCS Rec. %	Rec. Limits %	LCS Qualifier
Total Solids	50.0	50.0	100	85-115	

Method Blank (MB)

(MB) R3281892-1 01/25/18 07:50

Analyte	MB Result %	MB Qualifier	MB MDL %	MB RDL %
Total Solids	0			

L964573-19 Original Sample (OS) • Duplicate (DUP)

(OS) L964573-19 01/25/18 07:50 • (DUP) R3281892-3 01/25/18 07:50

Analyte	Original Result %	DUP Result %	Dilution	DUP RPD %	DUP Qualifier	DUP RPD Limits %
Total Solids	82.9	83.3	1	0		5

Laboratory Control Sample (LCS)

(LCS) R3281892-2 01/25/18 07:50

Analyte	Spike Amount %	LCS Result %	LCS Rec. %	Rec. Limits %	LCS Qualifier
Total Solids	50.0	50.0	100	85-115	

Method Blank (MB)

(MB) R3280979-1 01/22/18 16:36

Analyte	MB Result	MB Qualifier	MB MDL	MB RDL
	ug/l		ug/l	ug/l
Mercury,Dissolved	U		0.0490	0.200

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280979-4 01/22/18 19:28 • (LCSD) R3280979-5 01/22/18 19:30

Analyte	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits
	ug/l	ug/l	ug/l	%	%	%			%	%
Mercury,Dissolved	3.00	3.35	3.35	112	112	80-120			0.218	20

L964587-02 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964587-02 01/22/18 16:44 • (MS) R3280979-2 01/22/18 16:47 • (MSD) R3280979-3 01/22/18 16:49

Analyte	Spike Amount	Original Result	MS Result	MSD Result	MS Rec.	MSD Rec.	Dilution	Rec. Limits	MS Qualifier	MSD Qualifier	RPD	RPD Limits
	ug/l	ug/l	ug/l	ug/l	%	%		%			%	%
Mercury,Dissolved	3.00	U	3.35	3.15	112	105	1	75-125			6.12	20

Method Blank (MB)

(MB) R3281329-1 01/23/18 16:57

Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Mercury	0.00413	J	0.0028	0.0200

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281329-2 01/23/18 16:59 • (LCSD) R3281329-3 01/23/18 17:02

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Mercury	0.300	0.294	0.295	98	98.2	80-120			0.211	20

L964604-01 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964604-01 01/23/18 17:04 • (MS) R3281329-4 01/23/18 17:07 • (MSD) R3281329-5 01/23/18 17:09

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Mercury	0.300	0.00915	0.340	0.345	110	112	1	75-125			1.37	20

Method Blank (MB)

(MB) R3280756-1 01/22/18 02:31

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Arsenic,Dissolved	U		6.50	10.0
Barium,Dissolved	U		1.70	5.00
Cadmium,Dissolved	U		0.700	2.00
Chromium,Dissolved	1.49	J	1.40	10.0
Lead,Dissolved	5.72		1.90	5.00
Selenium,Dissolved	U		7.40	10.0
Silver,Dissolved	U		2.80	5.00

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280756-2 01/22/18 02:33 • (LCSD) R3280756-3 01/22/18 02:36

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Arsenic,Dissolved	1000	995	1010	99.5	101	80-120			1.16	20
Barium,Dissolved	1000	1040	1050	104	105	80-120			0.94	20
Cadmium,Dissolved	1000	1010	1020	101	102	80-120			1.17	20
Chromium,Dissolved	1000	1030	1040	103	104	80-120			0.686	20
Lead,Dissolved	1000	1010	1020	101	102	80-120			0.801	20
Selenium,Dissolved	1000	985	1010	98.5	101	80-120			2.15	20
Silver,Dissolved	200	197	199	98.3	99.6	80-120			1.24	20

L963861-02 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L963861-02 01/22/18 02:38 • (MS) R3280756-5 01/22/18 02:44 • (MSD) R3280756-6 01/22/18 02:46

Analyte	Spike Amount ug/l	Original Result ug/l	MS Result ug/l	MSD Result ug/l	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Arsenic,Dissolved	1000	10.8	1040	1040	103	103	1	75-125			0.669	20
Barium,Dissolved	1000	49.8	1080	1100	103	105	1	75-125			1.25	20
Cadmium,Dissolved	1000	ND	1030	1040	103	104	1	75-125			1.25	20
Chromium,Dissolved	1000	ND	1030	1050	103	105	1	75-125			1.19	20
Lead,Dissolved	1000	ND	1020	1040	102	104	1	75-125			1.61	20
Selenium,Dissolved	1000	ND	1020	1040	102	104	1	75-125			2.07	20
Silver,Dissolved	200	ND	201	205	100	103	1	75-125			2.32	20

Method Blank (MB)

(MB) R3282309-1 01/28/18 22:47

Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Arsenic	U		0.65	2.00
Barium	0.229	J	0.17	0.500
Cadmium	U		0.07	0.500
Chromium	U		0.14	1.00
Lead	U		0.19	0.500
Selenium	U		0.74	2.00
Silver	U		0.28	1.00

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3282309-2 01/28/18 22:50 • (LCSD) R3282309-3 01/28/18 22:53

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Arsenic	100	101	99.6	101	99.6	80-120			1.28	20
Barium	100	107	106	107	106	80-120			0.953	20
Cadmium	100	101	100	101	100	80-120			0.784	20
Chromium	100	103	103	103	103	80-120			0.0585	20
Lead	100	102	101	102	101	80-120			0.64	20
Selenium	100	102	99.6	102	99.6	80-120			2.2	20
Silver	20.0	18.8	18.6	94.1	92.8	80-120			1.42	20

L965494-03 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L965494-03 01/28/18 22:56 • (MS) R3282309-6 01/28/18 23:06 • (MSD) R3282309-7 01/28/18 23:09

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Arsenic	100	ND	99.8	97.4	99	96.6	1	75-125			2.42	20
Barium	100	49.5	147	152	98	102	1	75-125			2.93	20
Cadmium	100	ND	98.9	97.2	98.8	97.1	1	75-125			1.8	20
Chromium	100	10.2	109	109	99.1	98.9	1	75-125			0.155	20
Lead	100	52.8	150	165	96.8	112	1	75-125			9.79	20
Selenium	100	ND	97.7	96.4	97.7	96.4	1	75-125			1.35	20
Silver	20.0	ND	18.2	18.0	91.2	90	1	75-125			1.36	20

Method Blank (MB)

(MB) R3280954-3 01/22/18 12:49

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Acetone	U		10.0	50.0
Acrolein	U		8.87	50.0
Acrylonitrile	U		1.87	10.0
Benzene	U		0.331	1.00
Bromobenzene	U		0.352	1.00
Bromodichloromethane	U		0.380	1.00
Bromoform	U		0.469	1.00
Bromomethane	U		0.866	5.00
n-Butylbenzene	U		0.361	1.00
sec-Butylbenzene	U		0.365	1.00
tert-Butylbenzene	U		0.399	1.00
Carbon tetrachloride	U		0.379	1.00
Chlorobenzene	U		0.348	1.00
Chlorodibromomethane	U		0.327	1.00
Chloroethane	U		0.453	5.00
Chloroform	U		0.324	5.00
Chloromethane	U		0.276	2.50
2-Chlorotoluene	U		0.375	1.00
4-Chlorotoluene	U		0.351	1.00
1,2-Dibromo-3-Chloropropane	U		1.33	5.00
1,2-Dibromoethane	U		0.381	1.00
Dibromomethane	U		0.346	1.00
1,2-Dichlorobenzene	U		0.349	1.00
1,3-Dichlorobenzene	U		0.220	1.00
1,4-Dichlorobenzene	U		0.274	1.00
Dichlorodifluoromethane	U		0.551	5.00
1,1-Dichloroethane	U		0.259	1.00
1,2-Dichloroethane	U		0.361	1.00
1,1-Dichloroethene	U		0.398	1.00
cis-1,2-Dichloroethene	U		0.260	1.00
trans-1,2-Dichloroethene	U		0.396	1.00
1,2-Dichloropropane	U		0.306	1.00
1,1-Dichloropropene	U		0.352	1.00
1,3-Dichloropropane	U		0.366	1.00
cis-1,3-Dichloropropene	U		0.418	1.00
trans-1,3-Dichloropropene	U		0.419	1.00
2,2-Dichloropropane	U		0.321	1.00
Di-isopropyl ether	U		0.320	1.00
Ethylbenzene	U		0.384	1.00
Hexachloro-1,3-butadiene	U		0.256	1.00

Method Blank (MB)

(MB) R3280954-3 01/22/18 12:49

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Isopropylbenzene	U		0.326	1.00
p-Isopropyltoluene	U		0.350	1.00
2-Butanone (MEK)	U		3.93	10.0
Methylene Chloride	U		1.00	5.00
4-Methyl-2-pentanone (MIBK)	U		2.14	10.0
Methyl tert-butyl ether	U		0.367	1.00
Naphthalene	U		1.00	5.00
n-Propylbenzene	U		0.349	1.00
Styrene	U		0.307	1.00
1,1,1,2-Tetrachloroethane	U		0.385	1.00
1,1,2,2-Tetrachloroethane	U		0.130	1.00
Tetrachloroethene	U		0.372	1.00
Toluene	U		0.412	1.00
1,1,2-Trichlorotrifluoroethane	U		0.303	1.00
1,2,3-Trichlorobenzene	U		0.230	1.00
1,2,4-Trichlorobenzene	U		0.355	1.00
1,1,1-Trichloroethane	U		0.319	1.00
1,1,2-Trichloroethane	U		0.383	1.00
Trichloroethene	U		0.398	1.00
Trichlorofluoromethane	U		1.20	5.00
1,2,3-Trichloropropane	U		0.807	2.50
1,2,3-Trimethylbenzene	U		0.321	1.00
1,2,4-Trimethylbenzene	U		0.373	1.00
1,3,5-Trimethylbenzene	U		0.387	1.00
Vinyl chloride	U		0.259	1.00
Xylenes, Total	U		1.06	3.00
(S) Toluene-d8	*102*			*80.0-120*
(S) Dibromofluoromethane	*98.6*			*76.0-123*
(S) 4-Bromofluorobenzene	*101*			*80.0-120*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280954-1 01/22/18 11:42 • (LCSD) R3280954-2 01/22/18 11:58

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Acetone	125	124	128	99.5	103	10.0-160			3.25	23
Acrolein	125	116	142	93.0	114	10.0-160		J3	20.1	20
Acrylonitrile	125	128	117	102	93.5	60.0-142			8.78	20
Benzene	25.0	24.8	24.6	99.4	98.4	69.0-123			0.927	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280954-1 01/22/18 11:42 • (LCSD) R3280954-2 01/22/18 11:58

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Bromobenzene	25.0	24.9	25.3	99.5	101	79.0-120			1.83	20
Bromodichloromethane	25.0	25.1	25.0	101	99.8	76.0-120			0.772	20
Bromoform	25.0	26.2	26.4	105	106	67.0-132			0.943	20
Bromomethane	25.0	25.0	25.4	99.8	101	18.0-160			1.58	20
n-Butylbenzene	25.0	24.8	25.8	99.1	103	72.0-126			3.84	20
sec-Butylbenzene	25.0	25.7	26.2	103	105	74.0-121			1.84	20
tert-Butylbenzene	25.0	25.8	26.0	103	104	75.0-122			0.898	20
Carbon tetrachloride	25.0	26.2	25.5	105	102	63.0-122			2.48	20
Chlorobenzene	25.0	26.1	26.0	104	104	79.0-121			0.315	20
Chlorodibromomethane	25.0	25.7	25.4	103	102	75.0-125			1.05	20
Chloroethane	25.0	26.3	26.4	105	105	47.0-152			0.249	20
Chloroform	25.0	24.9	25.0	99.7	99.9	72.0-121			0.210	20
Chloromethane	25.0	24.9	25.4	99.6	102	48.0-139			2.06	20
2-Chlorotoluene	25.0	25.2	25.6	101	103	74.0-122			1.68	20
4-Chlorotoluene	25.0	25.5	25.7	102	103	79.0-120			0.579	20
1,2-Dibromo-3-Chloropropane	25.0	24.5	25.4	98.1	102	64.0-127			3.51	20
1,2-Dibromoethane	25.0	25.7	25.4	103	101	77.0-123			1.43	20
Dibromomethane	25.0	24.6	24.7	98.6	98.8	78.0-120			0.265	20
1,2-Dichlorobenzene	25.0	25.3	25.6	101	102	80.0-120			1.02	20
1,3-Dichlorobenzene	25.0	24.9	25.6	99.6	102	72.0-123			2.79	20
1,4-Dichlorobenzene	25.0	24.2	24.7	96.7	98.9	77.0-120			2.16	20
Dichlorodifluoromethane	25.0	25.4	26.5	102	106	49.0-155			4.29	20
1,1-Dichloroethane	25.0	25.2	25.3	101	101	70.0-126			0.470	20
1,2-Dichloroethane	25.0	24.8	24.9	99.0	99.5	67.0-126			0.442	20
1,1-Dichloroethene	25.0	26.2	26.3	105	105	64.0-129			0.561	20
cis-1,2-Dichloroethene	25.0	23.9	24.3	95.5	97.3	73.0-120			1.81	20
trans-1,2-Dichloroethene	25.0	25.7	25.8	103	103	71.0-121			0.431	20
1,2-Dichloropropane	25.0	24.2	24.1	96.7	96.2	75.0-125			0.445	20
1,1-Dichloropropene	25.0	26.2	26.1	105	104	71.0-129			0.445	20
1,3-Dichloropropane	25.0	25.2	25.1	101	100	80.0-121			0.374	20
cis-1,3-Dichloropropene	25.0	25.9	25.8	104	103	79.0-123			0.486	20
trans-1,3-Dichloropropene	25.0	25.7	25.4	103	102	74.0-127			0.971	20
2,2-Dichloropropane	25.0	26.0	25.8	104	103	60.0-125			0.733	20
Di-isopropyl ether	25.0	25.2	24.8	101	99.1	59.0-133			1.69	20
Ethylbenzene	25.0	26.5	26.1	106	104	77.0-120			1.57	20
Hexachloro-1,3-butadiene	25.0	24.4	25.2	97.4	101	64.0-131			3.50	20
Isopropylbenzene	25.0	26.2	26.4	105	106	75.0-120			0.892	20
p-Isopropyltoluene	25.0	26.0	26.6	104	106	74.0-126			2.35	20
2-Butanone (MEK)	125	145	147	116	117	37.0-158			1.36	20
Methylene Chloride	25.0	24.1	24.5	96.3	98.1	66.0-121			1.81	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280954-1 01/22/18 11:42 • (LCSD) R3280954-2 01/22/18 11:58

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
4-Methyl-2-pentanone (MIBK)	125	131	129	105	104	59.0-143			1.38	20
Methyl tert-butyl ether	25.0	24.4	23.5	97.7	93.9	64.0-123			3.93	20
Naphthalene	25.0	23.6	24.4	94.6	97.7	62.0-128			3.23	20
n-Propylbenzene	25.0	26.0	26.3	104	105	79.0-120			0.878	20
Styrene	25.0	26.6	26.8	106	107	78.0-124			0.763	20
1,1,1,2-Tetrachloroethane	25.0	25.8	25.5	103	102	75.0-122			1.09	20
1,1,2,2-Tetrachloroethane	25.0	24.5	24.5	97.9	98.0	71.0-122			0.170	20
Tetrachloroethene	25.0	25.8	25.8	103	103	70.0-127			0.0563	20
Toluene	25.0	25.1	24.8	100	99.3	77.0-120			1.08	20
1,1,2-Trichlorotrifluoroethane	25.0	26.5	26.8	106	107	61.0-136			0.993	20
1,2,3-Trichlorobenzene	25.0	23.9	25.6	95.6	102	61.0-133			6.81	20
1,2,4-Trichlorobenzene	25.0	22.0	23.7	88.1	94.8	69.0-129			7.34	20
1,1,1-Trichloroethane	25.0	26.1	25.7	105	103	68.0-122			1.54	20
1,1,2-Trichloroethane	25.0	24.5	24.5	98.1	98.1	78.0-120			0.00702	20
Trichloroethene	25.0	25.0	25.8	100	103	78.0-120			2.97	20
Trichlorofluoromethane	25.0	27.7	27.8	111	111	56.0-137			0.249	20
1,2,3-Trichloropropane	25.0	24.6	24.8	98.5	99.1	72.0-124			0.595	20
1,2,3-Trimethylbenzene	25.0	24.9	25.2	99.4	101	75.0-120			1.24	20
1,2,4-Trimethylbenzene	25.0	25.3	25.8	101	103	75.0-120			1.94	20
1,3,5-Trimethylbenzene	25.0	25.8	25.8	103	103	75.0-120			0.0799	20
Vinyl chloride	25.0	27.4	27.1	110	108	64.0-133			1.36	20
Xylenes, Total	75.0	77.7	77.7	104	104	77.0-120			0.000	20
(S) Toluene-d8				*102*	*102*	*80.0-120*				
(S) Dibromofluoromethane				*99.8*	*97.6*	*76.0-123*				
(S) 4-Bromofluorobenzene				*102*	*102*	*80.0-120*				

Method Blank (MB)

(MB) R3281130-3 01/22/18 11:20

Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Acetone	U		0.0100	0.0500
Acrylonitrile	U		0.00179	0.0100
Benzene	U		0.000270	0.00100
Bromobenzene	U		0.000284	0.00100
Bromodichloromethane	U		0.000254	0.00100
Bromoform	U		0.000424	0.00100
Bromomethane	U		0.00134	0.00500
n-Butylbenzene	U		0.000258	0.00100
sec-Butylbenzene	U		0.000201	0.00100
tert-Butylbenzene	U		0.000206	0.00100
Carbon tetrachloride	U		0.000328	0.00100
Chlorobenzene	U		0.000212	0.00100
Chlorodibromomethane	U		0.000373	0.00100
Chloroethane	U		0.000946	0.00500
Chloroform	U		0.000229	0.00500
Chloromethane	U		0.000375	0.00250
2-Chlorotoluene	U		0.000301	0.00100
4-Chlorotoluene	U		0.000240	0.00100
1,2-Dibromo-3-Chloropropane	U		0.00105	0.00500
1,2-Dibromoethane	U		0.000343	0.00100
Dibromomethane	U		0.000382	0.00100
1,2-Dichlorobenzene	U		0.000305	0.00100
1,3-Dichlorobenzene	U		0.000239	0.00100
1,4-Dichlorobenzene	U		0.000226	0.00100
Dichlorodifluoromethane	U		0.000713	0.00500
1,1-Dichloroethane	U		0.000199	0.00100
1,2-Dichloroethane	U		0.000265	0.00100
1,1-Dichloroethene	U		0.000303	0.00100
cis-1,2-Dichloroethene	U		0.000235	0.00100
trans-1,2-Dichloroethene	U		0.000264	0.00100
1,2-Dichloropropane	U		0.000358	0.00100
1,1-Dichloropropene	U		0.000317	0.00100
1,3-Dichloropropane	U		0.000207	0.00100
cis-1,3-Dichloropropene	U		0.000262	0.00100
trans-1,3-Dichloropropene	U		0.000267	0.00100
2,2-Dichloropropane	U		0.000279	0.00100
Di-isopropyl ether	U		0.000248	0.00100
Ethylbenzene	U		0.000297	0.00100
Hexachloro-1,3-butadiene	U		0.000342	0.00100
Isopropylbenzene	U		0.000243	0.00100

Method Blank (MB)

(MB) R3281130-3 01/22/18 11:20

Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
p-Isopropyltoluene	U		0.000204	0.00100
2-Butanone (MEK)	U		0.00468	0.0100
Methylene Chloride	U		0.00100	0.00500
4-Methyl-2-pentanone (MIBK)	U		0.00188	0.0100
Methyl tert-butyl ether	U		0.000212	0.00100
Naphthalene	U		0.00100	0.00500
n-Propylbenzene	U		0.000206	0.00100
Styrene	U		0.000234	0.00100
1,1,1,2-Tetrachloroethane	U		0.000264	0.00100
1,1,2,2-Tetrachloroethane	U		0.000365	0.00100
Tetrachloroethene	U		0.000276	0.00100
Toluene	U		0.000434	0.00500
1,1,2-Trichlorotrifluoroethane	U		0.000365	0.00100
1,2,3-Trichlorobenzene	U		0.000306	0.00100
1,2,4-Trichlorobenzene	U		0.000388	0.00100
1,1,1-Trichloroethane	U		0.000286	0.00100
1,1,2-Trichloroethane	U		0.000277	0.00100
Trichloroethene	U		0.000279	0.00100
Trichlorofluoromethane	U		0.000382	0.00500
1,2,3-Trichloropropane	U		0.000741	0.00250
1,2,3-Trimethylbenzene	U		0.000287	0.00100
1,2,4-Trimethylbenzene	U		0.000211	0.00100
1,3,5-Trimethylbenzene	U		0.000266	0.00100
Vinyl chloride	U		0.000291	0.00100
Xylenes, Total	U		0.000698	0.00300
(S) Toluene-d8	*99.4*			*80.0-120*
(S) Dibromofluoromethane	*97.3*			*74.0-131*
(S) 4-Bromofluorobenzene	*98.3*			*64.0-132*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281130-1 01/22/18 09:41 • (LCSD) R3281130-2 01/22/18 10:01

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Acetone	0.125	0.122	0.120	97.9	96.3	11.0-160			1.70	23
Acrylonitrile	0.125	0.125	0.121	99.9	96.7	61.0-143			3.33	20
Benzene	0.0250	0.0241	0.0243	96.2	97.0	71.0-124			0.840	20
Bromobenzene	0.0250	0.0243	0.0239	97.2	95.8	78.0-120			1.44	20
Bromodichloromethane	0.0250	0.0249	0.0243	99.7	97.0	75.0-120			2.68	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281130-1 01/22/18 09:41 • (LCSD) R3281130-2 01/22/18 10:01

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Bromoform	0.0250	0.0267	0.0256	107	103	65.0-133			3.84	20
Bromomethane	0.0250	0.0258	0.0260	103	104	26.0-160			0.934	20
n-Butylbenzene	0.0250	0.0284	0.0281	114	112	73.0-126			1.29	20
sec-Butylbenzene	0.0250	0.0262	0.0259	105	104	75.0-121			1.22	20
tert-Butylbenzene	0.0250	0.0253	0.0256	101	102	74.0-122			1.42	20
Carbon tetrachloride	0.0250	0.0253	0.0259	101	104	66.0-123			2.49	20
Chlorobenzene	0.0250	0.0262	0.0258	105	103	79.0-121			1.37	20
Chlorodibromomethane	0.0250	0.0256	0.0250	102	100	74.0-128			2.33	20
Chloroethane	0.0250	0.0244	0.0253	97.7	101	51.0-147			3.58	20
Chloroform	0.0250	0.0252	0.0249	101	99.7	73.0-123			1.18	20
Chloromethane	0.0250	0.0237	0.0247	94.7	98.8	51.0-138			4.27	20
2-Chlorotoluene	0.0250	0.0254	0.0251	102	100	72.0-124			1.14	20
4-Chlorotoluene	0.0250	0.0260	0.0254	104	102	78.0-120			2.58	20
1,2-Dibromo-3-Chloropropane	0.0250	0.0277	0.0255	111	102	65.0-126			8.38	20
1,2-Dibromoethane	0.0250	0.0250	0.0245	100	98.1	78.0-122			1.87	20
Dibromomethane	0.0250	0.0259	0.0261	104	104	79.0-120			0.585	20
1,2-Dichlorobenzene	0.0250	0.0258	0.0254	103	102	80.0-120			1.51	20
1,3-Dichlorobenzene	0.0250	0.0262	0.0258	105	103	72.0-123			1.80	20
1,4-Dichlorobenzene	0.0250	0.0246	0.0244	98.2	97.5	77.0-120			0.697	20
Dichlorodifluoromethane	0.0250	0.0252	0.0253	101	101	49.0-155			0.375	20
1,1-Dichloroethane	0.0250	0.0244	0.0249	97.5	99.7	70.0-128			2.21	20
1,2-Dichloroethane	0.0250	0.0245	0.0245	98.0	98.0	69.0-128			0.0154	20
1,1-Dichloroethene	0.0250	0.0236	0.0247	94.3	98.6	63.0-131			4.48	20
cis-1,2-Dichloroethene	0.0250	0.0245	0.0254	98.0	102	74.0-123			3.62	20
trans-1,2-Dichloroethene	0.0250	0.0247	0.0247	98.8	98.6	72.0-122			0.157	20
1,2-Dichloropropane	0.0250	0.0254	0.0259	102	103	75.0-126			1.74	20
1,1-Dichloropropene	0.0250	0.0249	0.0252	99.7	101	72.0-130			1.02	20
1,3-Dichloropropane	0.0250	0.0240	0.0235	96.0	94.1	80.0-121			2.04	20
cis-1,3-Dichloropropene	0.0250	0.0256	0.0255	103	102	80.0-125			0.356	20
trans-1,3-Dichloropropene	0.0250	0.0267	0.0260	107	104	75.0-129			2.80	20
2,2-Dichloropropane	0.0250	0.0309	0.0295	123	118	60.0-129			4.65	20
Di-isopropyl ether	0.0250	0.0240	0.0241	95.9	96.5	62.0-133			0.592	20
Ethylbenzene	0.0250	0.0261	0.0260	104	104	77.0-120			0.523	20
Hexachloro-1,3-butadiene	0.0250	0.0269	0.0276	107	110	68.0-128			2.67	20
Isopropylbenzene	0.0250	0.0248	0.0252	99.2	101	75.0-120			1.63	20
p-Isopropyltoluene	0.0250	0.0270	0.0268	108	107	74.0-125			0.680	20
2-Butanone (MEK)	0.125	0.129	0.123	103	98.4	37.0-159			4.90	20
Methylene Chloride	0.0250	0.0232	0.0235	93.0	94.0	67.0-123			1.09	20
4-Methyl-2-pentanone (MIBK)	0.125	0.128	0.122	103	97.7	60.0-144			4.86	20
Methyl tert-butyl ether	0.0250	0.0239	0.0236	95.7	94.3	66.0-125			1.50	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281130-1 01/22/18 09:41 • (LCSD) R3281130-2 01/22/18 10:01

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Naphthalene	0.0250	0.0246	0.0246	98.4	98.6	64.0-125			0.194	20
n-Propylbenzene	0.0250	0.0255	0.0254	102	102	78.0-120			0.539	20
Styrene	0.0250	0.0272	0.0260	109	104	78.0-124			4.63	20
1,1,1,2-Tetrachloroethane	0.0250	0.0270	0.0264	108	106	74.0-124			2.13	20
1,1,2,2-Tetrachloroethane	0.0250	0.0248	0.0240	99.3	96.0	73.0-120			3.37	20
Tetrachloroethene	0.0250	0.0269	0.0269	107	108	70.0-127			0.285	20
Toluene	0.0250	0.0241	0.0238	96.5	95.1	77.0-120			1.37	20
1,1,2-Trichlorotrifluoroethane	0.0250	0.0240	0.0240	96.1	96.1	64.0-135			0.0479	20
1,2,3-Trichlorobenzene	0.0250	0.0266	0.0266	106	107	68.0-126			0.0918	20
1,2,4-Trichlorobenzene	0.0250	0.0288	0.0292	115	117	70.0-127			1.33	20
1,1,1-Trichloroethane	0.0250	0.0254	0.0256	102	102	69.0-125			0.650	20
1,1,2-Trichloroethane	0.0250	0.0243	0.0240	97.0	96.0	78.0-120			1.05	20
Trichloroethene	0.0250	0.0253	0.0257	101	103	79.0-120			1.87	20
Trichlorofluoromethane	0.0250	0.0254	0.0258	102	103	59.0-136			1.54	20
1,2,3-Trichloropropane	0.0250	0.0255	0.0240	102	96.2	73.0-124			6.01	20
1,2,3-Trimethylbenzene	0.0250	0.0254	0.0254	101	101	76.0-120			0.00446	20
1,2,4-Trimethylbenzene	0.0250	0.0258	0.0257	103	103	75.0-120			0.617	20
1,3,5-Trimethylbenzene	0.0250	0.0255	0.0254	102	102	75.0-120			0.491	20
Vinyl chloride	0.0250	0.0265	0.0271	106	108	63.0-134			2.25	20
Xylenes, Total	0.0750	0.0787	0.0782	105	104	77.0-120			0.637	20
(S) Toluene-d8				*99.3*	*99.3*	*80.0-120*				
(S) Dibromofluoromethane				*96.3*	*98.3*	*74.0-131*				
(S) 4-Bromofluorobenzene				*98.1*	*93.4*	*64.0-132*				

L964604-04 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964604-04 01/22/18 20:11 • (MS) R3281130-5 01/23/18 00:06 • (MSD) R3281130-6 01/23/18 00:26

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Acetone	0.125	U	0.0894	0.0857	71.5	68.6	1	10.0-160			4.25	36
Acrylonitrile	0.125	U	0.145	0.130	116	104	1	14.0-160			11.1	33
Benzene	0.0250	U	0.0238	0.0221	95.3	88.2	1	13.0-146			7.73	27
Bromobenzene	0.0250	U	0.0207	0.0190	82.8	76.1	1	10.0-149			8.41	33
Bromodichloromethane	0.0250	U	0.0230	0.0213	91.8	85.2	1	15.0-142			7.51	28
Bromoform	0.0250	U	0.0247	0.0225	99.0	90.0	1	10.0-147			9.48	31
Bromomethane	0.0250	U	0.0240	0.0221	96.0	88.4	1	10.0-160			8.31	32
n-Butylbenzene	0.0250	U	0.0217	0.0212	87.0	84.6	1	10.0-154			2.73	37
sec-Butylbenzene	0.0250	U	0.0227	0.0219	90.6	87.7	1	10.0-151			3.27	36
tert-Butylbenzene	0.0250	U	0.0232	0.0217	92.8	86.8	1	10.0-152			6.61	35

L964604-04 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964604-04 01/22/18 20:11 • (MS) R3281130-5 01/23/18 00:06 • (MSD) R3281130-6 01/23/18 00:26

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Carbon tetrachloride	0.0250	U	0.0258	0.0244	103	97.6	1	13.0-140			5.62	30
Chlorobenzene	0.0250	U	0.0221	0.0212	88.4	84.9	1	10.0-149			4.04	31
Chlorodibromomethane	0.0250	U	0.0230	0.0214	92.1	85.7	1	12.0-147			7.26	29
Chloroethane	0.0250	U	0.0234	0.0216	93.8	86.5	1	10.0-159			8.08	33
Chloroform	0.0250	U	0.0250	0.0226	100	90.4	1	18.0-148			10.2	28
Chloromethane	0.0250	U	0.0232	0.0225	92.7	90.1	1	10.0-146			2.91	29
2-Chlorotoluene	0.0250	U	0.0211	0.0198	84.6	79.2	1	10.0-151			6.62	35
4-Chlorotoluene	0.0250	U	0.0202	0.0189	80.7	75.7	1	10.0-150			6.39	35
1,2-Dibromo-3-Chloropropane	0.0250	U	0.0325	0.0287	130	115	1	10.0-149			12.3	34
1,2-Dibromoethane	0.0250	U	0.0247	0.0225	98.6	89.9	1	14.0-145			9.30	28
Dibromomethane	0.0250	U	0.0264	0.0233	105	93.2	1	18.0-144			12.3	27
1,2-Dichlorobenzene	0.0250	U	0.0208	0.0188	83.2	75.3	1	10.0-153			9.95	34
1,3-Dichlorobenzene	0.0250	U	0.0196	0.0186	78.4	74.3	1	10.0-150			5.37	35
1,4-Dichlorobenzene	0.0250	U	0.0180	0.0173	72.1	69.2	1	10.0-148			4.16	34
Dichlorodifluoromethane	0.0250	U	0.0244	0.0246	97.6	98.4	1	10.0-160			0.759	30
1,1-Dichloroethane	0.0250	U	0.0251	0.0234	101	93.7	1	19.0-148			7.05	28
1,2-Dichloroethane	0.0250	U	0.0251	0.0227	100	90.7	1	17.0-147			9.98	27
1,1-Dichloroethene	0.0250	U	0.0240	0.0230	96.0	92.2	1	10.0-150			4.06	31
cis-1,2-Dichloroethene	0.0250	U	0.0249	0.0220	99.5	87.8	1	16.0-145			12.4	28
trans-1,2-Dichloroethene	0.0250	U	0.0241	0.0224	96.4	89.7	1	11.0-142			7.22	29
1,2-Dichloropropane	0.0250	U	0.0254	0.0233	102	93.0	1	17.0-148			8.74	28
1,1-Dichloropropene	0.0250	U	0.0239	0.0228	95.5	91.3	1	10.0-150			4.57	30
1,3-Dichloropropane	0.0250	U	0.0232	0.0222	92.8	88.7	1	16.0-148			4.49	27
cis-1,3-Dichloropropene	0.0250	U	0.0218	0.0204	87.1	81.7	1	13.0-150			6.37	28
trans-1,3-Dichloropropene	0.0250	U	0.0232	0.0216	92.8	86.4	1	10.0-152			7.23	29
2,2-Dichloropropane	0.0250	U	0.0306	0.0302	122	121	1	16.0-143			1.40	30
Di-isopropyl ether	0.0250	U	0.0248	0.0225	99.1	89.8	1	16.0-149			9.80	28
Ethylbenzene	0.0250	U	0.0221	0.0219	88.2	87.6	1	10.0-147			0.692	31
Hexachloro-1,3-butadiene	0.0250	U	0.0218	0.0222	87.4	88.9	1	10.0-154			1.68	40
Isopropylbenzene	0.0250	U	0.0221	0.0210	88.3	83.9	1	10.0-147			5.10	33
p-Isopropyltoluene	0.0250	U	0.0223	0.0219	89.2	87.5	1	10.0-156			1.97	37
2-Butanone (MEK)	0.125	U	0.112	0.104	89.4	82.9	1	10.0-160			7.47	33
Methylene Chloride	0.0250	U	0.0227	0.0209	90.7	83.8	1	16.0-139			7.91	29
4-Methyl-2-pentanone (MIBK)	0.125	U	0.156	0.147	125	118	1	12.0-160			5.66	32
Methyl tert-butyl ether	0.0250	U	0.0265	0.0235	106	94.0	1	21.0-145			12.1	29
Naphthalene	0.0250	U	0.0224	0.0213	89.4	85.0	1	10.0-153			5.05	36
n-Propylbenzene	0.0250	U	0.0212	0.0206	84.9	82.3	1	10.0-151			3.22	34
Styrene	0.0250	U	0.0222	0.0208	89.0	83.0	1	10.0-155			6.91	34
1,1,1,2-Tetrachloroethane	0.0250	U	0.0243	0.0226	97.3	90.4	1	10.0-147			7.32	30
1,1,2,2-Tetrachloroethane	0.0250	U	0.0276	0.0253	110	101	1	10.0-155			8.60	31

L964604-04 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964604-04 01/22/18 20:11 • (MS) R3281130-5 01/23/18 00:06 • (MSD) R3281130-6 01/23/18 00:26

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Tetrachloroethene	0.0250	U	0.0218	0.0224	87.4	89.5	1	10.0-144			2.38	32
Toluene	0.0250	U	0.0211	0.0201	84.2	80.5	1	10.0-144			4.54	28
1,1,2-Trichlorotrifluoroethane	0.0250	U	0.0235	0.0235	94.0	93.9	1	10.0-153			0.0752	33
1,2,3-Trichlorobenzene	0.0250	U	0.0180	0.0177	72.0	70.7	1	10.0-153			1.80	40
1,2,4-Trichlorobenzene	0.0250	U	0.0164	0.0162	65.8	64.8	1	10.0-156			1.54	40
1,1,1-Trichloroethane	0.0250	U	0.0264	0.0243	106	97.4	1	18.0-145			8.06	29
1,1,2-Trichloroethane	0.0250	U	0.0235	0.0221	93.9	88.4	1	12.0-151			6.10	28
Trichloroethene	0.0250	U	0.0235	0.0223	94.0	89.3	1	11.0-148			5.21	29
Trichlorofluoromethane	0.0250	U	0.0253	0.0244	101	97.5	1	10.0-157			3.55	34
1,2,3-Trichloropropane	0.0250	U	0.0289	0.0263	116	105	1	10.0-154			9.58	32
1,2,3-Trimethylbenzene	0.0250	U	0.0218	0.0203	87.3	81.0	1	10.0-150			7.44	33
1,2,4-Trimethylbenzene	0.0250	U	0.0212	0.0202	84.9	80.9	1	10.0-151			4.88	34
1,3,5-Trimethylbenzene	0.0250	U	0.0215	0.0205	86.1	81.9	1	10.0-150			5.00	33
Vinyl chloride	0.0250	U	0.0257	0.0234	103	93.8	1	10.0-150			9.21	29
Xylenes, Total	0.0750	U	0.0666	0.0649	88.8	86.5	1	10.0-150			2.59	31
(S) Toluene-d8					*93.3*	*94.6*		*80.0-120*				
(S) Dibromofluoromethane					*102*	*102*		*74.0-131*				
(S) 4-Bromofluorobenzene					*93.9*	*94.5*		*64.0-132*				

Method Blank (MB)

(MB) R3281439-3 01/23/18 10:26

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Anthracene	U		0.0140	0.0500
Acenaphthene	U		0.0100	0.0500
Acenaphthylene	U		0.0120	0.0500
Benzo(a)anthracene	U		0.00410	0.0500
Benzo(a)pyrene	U		0.0116	0.0500
Benzo(b)fluoranthene	0.00294	J	0.00212	0.0500
Benzo(g,h,i)perylene	0.00260	J	0.00227	0.0500
Benzo(k)fluoranthene	U		0.0136	0.0500
Chrysene	U		0.0108	0.0500
Dibenz(a,h)anthracene	U		0.00396	0.0500
Fluoranthene	U		0.0157	0.0500
Fluorene	U		0.00850	0.0500
Indeno(1,2,3-cd)pyrene	U		0.0148	0.0500
Naphthalene	0.0720	J	0.0198	0.250
Phenanthrene	U		0.00820	0.0500
Pyrene	U		0.0117	0.0500
1-Methylnaphthalene	U		0.00821	0.250
2-Methylnaphthalene	U		0.00902	0.250
2-Chloronaphthalene	U		0.00647	0.250
(S) Nitrobenzene-d5	*92.3*			*31.0-160*
(S) 2-Fluorobiphenyl	*106*			*48.0-148*
(S) p-Terphenyl-d14	*102*			*37.0-146*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281439-1 01/23/18 09:36 • (LCSD) R3281439-2 01/23/18 10:01

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Anthracene	2.00	2.20	2.12	110	106	64.0-142			3.34	20
Acenaphthene	2.00	1.99	1.91	99.4	95.6	66.0-132			3.89	20
Acenaphthylene	2.00	2.02	1.94	101	97.1	65.0-132			3.75	20
Benzo(a)anthracene	2.00	2.00	1.95	99.9	97.3	59.0-134			2.63	20
Benzo(a)pyrene	2.00	2.08	1.97	104	98.4	61.0-145			5.42	20
Benzo(b)fluoranthene	2.00	2.05	1.86	102	92.8	57.0-136			9.82	20
Benzo(g,h,i)perylene	2.00	2.21	2.13	110	107	54.0-140			3.49	20
Benzo(k)fluoranthene	2.00	1.96	1.96	97.8	97.8	57.0-141			0.0557	20
Chrysene	2.00	2.07	1.99	104	99.5	63.0-140			4.11	20
Dibenz(a,h)anthracene	2.00	2.33	2.24	116	112	49.0-141			4.05	20
Fluoranthene	2.00	2.28	2.22	114	111	65.0-143			2.46	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281439-1 01/23/18 09:36 • (LCSD) R3281439-2 01/23/18 10:01

Analyte	Spike Amount ug/l	LCS Result ug/l	LCSD Result ug/l	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Fluorene	2.00	1.99	1.93	99.5	96.4	64.0-129			3.20	20
Indeno(1,2,3-cd)pyrene	2.00	2.24	2.15	112	108	53.0-141			4.05	20
Naphthalene	2.00	2.01	1.92	101	96.2	68.0-129			4.40	20
Phenanthrene	2.00	1.97	1.86	98.4	93.1	62.0-132			5.60	20
Pyrene	2.00	1.89	1.83	94.7	91.7	58.0-156			3.25	20
1-Methylnaphthalene	2.00	2.11	2.04	106	102	68.0-137			3.63	20
2-Methylnaphthalene	2.00	2.02	1.93	101	96.6	68.0-134			4.51	20
2-Chloronaphthalene	2.00	2.10	2.03	105	101	65.0-129			3.46	20
(S) Nitrobenzene-d5				*99.1*	*93.6*	*31.0-160*				
(S) 2-Fluorobiphenyl				*110*	*105*	*48.0-148*				
(S) p-Terphenyl-d14				*105*	*103*	*37.0-146*				

Method Blank (MB)

(MB) R3281389-3 01/23/18 10:53

Analyte	MB Result mg/kg	MB Qualifier	MB MDL mg/kg	MB RDL mg/kg
Anthracene	U		0.000600	0.00600
Acenaphthene	U		0.000600	0.00600
Acenaphthylene	U		0.000600	0.00600
Benzo(a)anthracene	U		0.000600	0.00600
Benzo(a)pyrene	U		0.000600	0.00600
Benzo(b)fluoranthene	U		0.000600	0.00600
Benzo(g,h,i)perylene	U		0.000600	0.00600
Benzo(k)fluoranthene	U		0.000600	0.00600
Chrysene	U		0.000600	0.00600
Dibenz(a,h)anthracene	U		0.000600	0.00600
Fluoranthene	U		0.000600	0.00600
Fluorene	U		0.000600	0.00600
Indeno(1,2,3-cd)pyrene	U		0.000600	0.00600
Naphthalene	0.00238	J	0.00200	0.0200
Phenanthrene	U		0.000600	0.00600
Pyrene	U		0.000600	0.00600
1-Methylnaphthalene	U		0.00200	0.0200
2-Methylnaphthalene	U		0.00200	0.0200
2-Chloronaphthalene	U		0.00200	0.0200
(S) Nitrobenzene-d5	*64.9*			*14.0-149*
(S) 2-Fluorobiphenyl	*69.8*			*34.0-125*
(S) p-Terphenyl-d14	*55.4*			*23.0-120*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281389-1 01/23/18 10:09 • (LCSD) R3281389-2 01/23/18 10:31

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Anthracene	0.0800	0.0662	0.0618	82.7	77.2	50.0-125			6.85	20
Acenaphthene	0.0800	0.0627	0.0561	78.4	70.1	52.0-120			11.2	20
Acenaphthylene	0.0800	0.0603	0.0529	75.4	66.1	51.0-120			13.1	20
Benzo(a)anthracene	0.0800	0.0538	0.0476	67.3	59.6	46.0-121			12.2	20
Benzo(a)pyrene	0.0800	0.0537	0.0482	67.1	60.3	42.0-121			10.7	20
Benzo(b)fluoranthene	0.0800	0.0499	0.0423	62.4	52.9	42.0-123			16.5	20
Benzo(g,h,i)perylene	0.0800	0.0592	0.0534	74.0	66.8	43.0-128			10.2	20
Benzo(k)fluoranthene	0.0800	0.0592	0.0565	74.0	70.6	45.0-128			4.63	20
Chrysene	0.0800	0.0608	0.0570	76.0	71.3	48.0-127			6.32	20
Dibenz(a,h)anthracene	0.0800	0.0598	0.0536	74.8	67.0	43.0-132			11.0	20
Fluoranthene	0.0800	0.0617	0.0532	77.1	66.5	49.0-129			14.8	20

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281389-1 01/23/18 10:09 • (LCSD) R3281389-2 01/23/18 10:31

Analyte	Spike Amount mg/kg	LCS Result mg/kg	LCSD Result mg/kg	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Fluorene	0.0800	0.0616	0.0600	77.0	75.0	50.0-120			2.53	20
Indeno(1,2,3-cd)pyrene	0.0800	0.0601	0.0539	75.2	67.4	44.0-131			10.9	20
Naphthalene	0.0800	0.0610	0.0537	76.2	67.2	50.0-120			12.6	20
Phenanthrene	0.0800	0.0578	0.0517	72.2	64.6	48.0-120			11.1	20
Pyrene	0.0800	0.0485	0.0518	60.6	64.8	48.0-135			6.72	20
1-Methylnaphthalene	0.0800	0.0550	0.0462	68.8	57.7	52.0-122			17.5	20
2-Methylnaphthalene	0.0800	0.0538	0.0447	67.3	55.9	52.0-120			18.4	20
2-Chloronaphthalene	0.0800	0.0614	0.0527	76.7	65.8	50.0-120			15.3	20
(S) Nitrobenzene-d5				*87.3*	*55.2*	*14.0-149*				
(S) 2-Fluorobiphenyl				*70.2*	*62.1*	*34.0-125*				
(S) p-Terphenyl-d14				*53.5*	*57.3*	*23.0-120*				

L964604-06 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L964604-06 01/23/18 18:54 • (MS) R3281389-4 01/23/18 16:21 • (MSD) R3281389-5 01/23/18 16:42

Analyte	Spike Amount mg/kg	Original Result mg/kg	MS Result mg/kg	MSD Result mg/kg	MS Rec. %	MSD Rec. %	Dilution	Rec. Limits %	MS Qualifier	MSD Qualifier	RPD %	RPD Limits %
Anthracene	0.0800	U	0.0730	0.0708	91.2	88.5	1	20.0-136			2.99	24
Acenaphthene	0.0800	U	0.0632	0.0610	79.0	76.2	1	29.0-124			3.63	20
Acenaphthylene	0.0800	U	0.0627	0.0601	78.4	75.2	1	35.0-120			4.21	20
Benzo(a)anthracene	0.0800	U	0.0543	0.0527	67.9	65.9	1	13.0-132			3.06	27
Benzo(a)pyrene	0.0800	U	0.0613	0.0573	76.6	71.7	1	14.0-138			6.63	27
Benzo(b)fluoranthene	0.0800	U	0.0534	0.0478	66.7	59.7	1	10.0-129			11.1	31
Benzo(g,h,i)perylene	0.0800	U	0.0634	0.0585	79.3	73.1	1	10.0-133			8.10	30
Benzo(k)fluoranthene	0.0800	U	0.0620	0.0606	77.4	75.7	1	15.0-131			2.25	27
Chrysene	0.0800	U	0.0657	0.0655	82.1	81.8	1	15.0-137			0.380	25
Dibenz(a,h)anthracene	0.0800	U	0.0653	0.0597	81.6	74.6	1	15.0-132			8.96	27
Fluoranthene	0.0800	U	0.0612	0.0587	76.4	73.4	1	13.0-139			4.11	28
Fluorene	0.0800	U	0.0615	0.0591	76.9	73.9	1	27.0-122			3.98	22
Indeno(1,2,3-cd)pyrene	0.0800	U	0.0645	0.0594	80.6	74.3	1	11.0-133			8.12	29
Naphthalene	0.0800	U	0.0638	0.0609	79.8	76.2	1	18.0-136			4.58	21
Phenanthrene	0.0800	U	0.0590	0.0568	73.8	71.0	1	15.0-133			3.89	25
Pyrene	0.0800	U	0.0606	0.0573	75.7	71.6	1	11.0-146			5.56	29
1-Methylnaphthalene	0.0800	U	0.0586	0.0560	73.3	70.1	1	24.0-137			4.53	22
2-Methylnaphthalene	0.0800	U	0.0552	0.0549	69.0	68.6	1	23.0-136			0.650	22
2-Chloronaphthalene	0.0800	U	0.0632	0.0605	78.9	75.6	1	36.0-120			4.36	20
(S) Nitrobenzene-d5					*77.4*	*67.4*		*14.0-149*				
(S) 2-Fluorobiphenyl					*76.7*	*74.0*		*34.0-125*				
(S) p-Terphenyl-d14					*70.7*	*67.5*		*23.0-120*				

Guide to Reading and Understanding Your Laboratory Report

The information below is designed to better explain the various terms used in your report of analytical results from the Laboratory. This is not intended as a comprehensive explanation, and if you have additional questions please contact your project representative.

Abbreviations and Definitions

MDL	Method Detection Limit.
RDL	Reported Detection Limit.
Rec.	Recovery.
RPD	Relative Percent Difference.
SDG	Sample Delivery Group.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
U	Not detected at the Reporting Limit (or MDL where applicable).
Analyte	The name of the particular compound or analysis performed. Some Analyses and Methods will have multiple analytes reported.
Dilution	If the sample matrix contains an interfering material, or if concentrations of analytes in the sample are higher than the highest limit of concentration that the laboratory can accurately report, the sample may be diluted for analysis. If a value different than 1 is used in this field, the result reported has already been corrected for this factor.
Limits	These are the target % recovery ranges or % difference value that the laboratory has historically determined as normal for the method and analyte being reported. Successful QC Sample analysis will target all analytes recovered or duplicated within these ranges.
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
Qualifier	This column provides a letter and/or number designation that corresponds to additional information concerning the result reported. If a Qualifier is present, a definition per Qualifier is provided within the Glossary and Definitions page and potentially a discussion of possible implications of the Qualifier in the Case Narrative if applicable.
Result	The actual analytical final result (corrected for any sample specific characteristics) reported for your sample. If there was no measurable result returned for a specific analyte, the result in this column may state “ND” (Not Detected) or “BDL” (Below Detectable Levels). The information in the results column should always be accompanied by either an MDL (Method Detection Limit) or RDL (Reporting Detection Limit) that defines the lowest value that the laboratory could detect or report for this analyte.
Case Narrative (Cn)	A brief discussion about the included sample results, including a discussion of any non-conformances to protocol observed either at sample receipt by the laboratory from the field or during the analytical process. If present, there will be a section in the Case Narrative to discuss the meaning of any data qualifiers used in the report.
Quality Control Summary (Qc)	This section of the report includes the results of the laboratory quality control analyses required by procedure or analytical methods to assist in evaluating the validity of the results reported for your samples. These analyses are not being performed on your samples typically, but on laboratory generated material.
Sample Chain of Custody (Sc)	This is the document created in the field when your samples were initially collected. This is used to verify the time and date of collection, the person collecting the samples, and the analyses that the laboratory is requested to perform. This chain of custody also documents all persons (excluding commercial shippers) that have had control or possession of the samples from the time of collection until delivery to the laboratory for analysis.
Sample Results (Sr)	This section of your report will provide the results of all testing performed on your samples. These results are provided by sample ID and are separated by the analyses performed on each sample. The header line of each analysis section for each sample will provide the name and method number for the analysis reported.
Sample Summary (Ss)	This section of the Analytical Report defines the specific analyses performed for each sample ID, including the dates and times of preparation and/or analysis.

Qualifier	Description
B	The same analyte is found in the associated blank.
J	The identification of the analyte is acceptable; the reported value is an estimate.
J3	The associated batch QC was outside the established quality control range for precision.

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our one location design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be YOUR LAB OF CHOICE.
* Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey–NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Connecticut	PH-0197	North Carolina [1]	DW21704
Florida	E87487	North Carolina [2]	41
Georgia	NELAP	North Dakota	R-140
Georgia [1]	923	Ohio–VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
Iowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky [1]	90010	South Dakota	n/a
Kentucky [2]	16	Tennessee [1 4]	2006
Louisiana	AI30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas [5]	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		


Third Party Federal Accreditations

A2LA – ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA – ISO 17025 [5]	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
EPA–Crypto	TN00003		

[1] Drinking Water [2] Underground Storage Tanks [3] Aquatic Toxicity [4] Chemical/Microbiological [5] Mold n/a Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.



GAIA Tech - Chicago, IL
135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Billing Information:
Accounts Payable and PM
135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Pres Chk

Report to: Larry Bertsch
Email To: larry.bertsch@rpsgroup.com

Project Description: Melville, NY
City/State Collected: melville NY

Phone: 312-541-4200
Fax: 312-541-0340

Client Project # 16785542000
Lab Project # GAICIL-MELVILLE

Collected by (print): Larry P. Bertsch
Site/Facility ID # NY
P.O. #

Collected by (signature):
Immediately Packed on Ice N ___ Y X

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day
Date Results Needed
Quote #

Analysis / Container / Preservative

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	Metals (Lab Filter) 250mlHDPE-NoPres	PAHSIMLVID 40mlAmb-NoPres-WT	RCRA8 Metals 2ozClr-NoPres	SV8270PAHSIMD,TS 4ozClr-NoPres	TO-15 Summa	V8260C 2ozClr-NoPres	V8260C 40ml/NaHSO4/Syr/MeOH	V8260C 40mlAmb-HCl	V8260C 40mlAmb-HCl-Blk	Remarks	Sample # (lab only)
GP-1	Comp	SS	13-15'	~~1/17/18~~ 1330	1330	6			X	X		X	X				01
GP-2		SS	5-7'	~~1/17/18~~ 1800	1800	6			X	X		X	X				02
GP-3		SS	15-17'	1/18/18	900	6			X	X		X	X				03
GP-4		SS	15-17'	1/19/18	850	6			X	X		X	X				04
GP-5		SS	3.5-5		1108	6			X	X		X	X				05
GP-6		SS	3-5'		1205	6			X	X		X	X				06
		SS				~~6~~			X	X		X	X				
		SS				~~6~~			X	X		X	X				
TRIP Blank		~~Water~~ SS				~~6~~			~~X~~	~~X~~		~~X~~	~~X~~		X		
		GW				5	X	X						X			

Chain of Custody Page ___ of ___

ESC LAB SCIENCES a subsidiary of Pace Analytical
12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# 964604
H242
Acctnum: GAICIL
Template: T131605
Prelogin: P635243
TSR: 104 - Jason Romer
PB: 1-12-18 CM
Shipped Via: FedEX Ground

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other ___

Remarks: * MUST meet HOLD time on soil samples - 5-6 DAYS

pH ___ Temp ___
Flow ___ Other ___

Samples returned via: ___ UPS X FedEx ___ Courier ___
Tracking # 4142 5232 3834

Sample Receipt Checklist
COC Seal Present/Intact: ___NP ___Y ___N
COC Signed/Accurate: ___Y ___N
Bottles arrive intact: ___Y ___N
Correct bottles used: ___Y ___N
Sufficient volume sent: ___Y ___N
If Applicable
VOA Zero Headspace: ___Y ___N
Preservation Correct/Checked: ___Y ___N

	Date:	Time:		
Relinquished by: (Signature)	1/18/18	1730	Received by: (Signature)	Trip Blank Received: Yes / No HCL / MeoH TBR
Relinquished by: (Signature)	Date:	Time:	Received by: (Signature)	Temp: 1.5 °C Bottles Received: 47 — If preservation required by Login: Date/Time
Relinquished by: (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1/20/18 Time: 0900 — Hold: — Condition: NCF / OK

GAIA Tech - Chicago, IL
135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Billing Information:
Accounts Payable and PM
135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Pres Chk

Report to: Larry Bertsch
Email To: larry.bertsch@rpsgroup.com

Project Description: Melville, NY
City/State Collected:

Phone: 312-541-4200
Fax: 312-541-0340

Client Project # 16785542000
Lab Project # GAICIL-MELVILLE

Collected by (print): Larry P. Bertsch
Site/Facility ID # NY
P.O. #

Collected by (signature):
Immediately Packed on Ice N ___ Y X

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day
Date Results Needed
Quote #

Analysis / Container / Preservative

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	Metals (Lab Filter) 250mlHDPE-NoPres	PAHSIMLVID 40mlAmb-NoPres-WT	RCRA8 Metals 2ozClr-NoPres	SV8270PAHSIMD,TS 4ozClr-NoPres	TO-15 Summa	V8260C 2ozClr-NoPres	V8260C 40ml/NaHSO4/Syr/MeOH	V8260C 40mlAmb-HCl	V8260C 40mlAmb-HCl-Blk			Remarks	Sample # (lab only)
GP-4	Grab	GW	—	1/19/18	910	5	X	X						X					08
GP-6	↓	GW	—	"	1515	5	X	X						X					09
		GW				~~5~~	X	X						X					
		GW				~~5~~	X	X						X					
		GW				~~5~~	X	X						X					
		GW				~~5~~	X	X						X					
		GW				~~5~~	X	X						X					
		GW				~~5~~	X	X						X					
TRIP BLANK		GW				~~2~~									X				
		Air				~~1~~					X								

Chain of Custody Page ___ of ___

ESC LABORATORIES
a subsidiary of Pace Analytical
12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# 961604
Table #
Acctnum: GAIACIL
Template: T131605
Prelogin: P635243
TSR: 104 - Jason Romer
PB: 1-12-18 CM
Shipped Via: FedEX Ground

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other_____

Remarks:

pH _____ Temp _____
Flow _____ Other _____

Samples returned via:
__ UPS X FedEx __ Courier __ _____
Tracking # 4142 5232 3834

Sample Receipt Checklist
COC Seal Present/Intact: NP Y N
COC Signed/Accurate: Y N
Bottles arrive intact: Y N
Correct bottles used: Y N
Sufficient volume sent: Y N
If Applicable
VOA Zero Headspace: Y N
Preservation Correct/Checked: Y N

Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Trip Blank Received: Yes / No HCL / MeoH TBR
	1/19/18	1730		
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Temp: 1.2 °C Bottles Received: 47 — If preservation required by Login: Date/Time
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1/20/18 Time: 0900 — Hold: — Condition: NCF / OK

ANALYTICAL REPORT

January 24, 2018

GAIA Tech - Chicago, IL

Sample Delivery Group:	L964491
Samples Received:	01/20/2018
Project Number:	16785542000
Description:	Melville, NY
Site:	NY
Report To:	Larry Bertsch 135 S. LaSalle St, Ste 3500 Chicago, IL 60603

Entire Report Reviewed By:

Jason Romer
Technical Service Representative

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approval of the laboratory. Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures: 060302, 060303, and 060304.



Cp: Cover Page 1

Tc: Table of Contents 2

Ss: Sample Summary 3

Cn: Case Narrative 4

Sr: Sample Results 5

SS-1 L964491-01 5

SS-3 L964491-03 7

SS-4 L964491-04 9

SS-5 L964491-05 11

SG-1 L964491-06 13

SG-2 L964491-07 15

SS-2 L964491-08 17

Qc: Quality Control Summary 19

Volatile Organic Compounds (MS) by Method TO-15 19

Gl: Glossary of Terms 33

Al: Accreditations & Locations 34

Sc: Sample Chain of Custody 35

SS-1 L964491-01 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/18/18 16:19	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1064707	1	01/20/18 22:44	01/20/18 22:44	MBF
Volatile Organic Compounds (MS) by Method TO-15	WG1065114	25	01/22/18 19:16	01/22/18 19:16	MBF

SS-3 L964491-03 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/19/18 08:32	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1064707	1	01/20/18 23:31	01/20/18 23:31	MBF
Volatile Organic Compounds (MS) by Method TO-15	WG1065114	25	01/22/18 19:54	01/22/18 19:54	MBF

SS-4 L964491-04 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/19/18 10:14	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1064707	1	01/21/18 00:17	01/21/18 00:17	MBF
Volatile Organic Compounds (MS) by Method TO-15	WG1065114	10	01/22/18 20:32	01/22/18 20:32	MBF

SS-5 L964491-05 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/18/18 15:54	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1064707	1	01/21/18 01:16	01/21/18 01:16	MBF
Volatile Organic Compounds (MS) by Method TO-15	WG1065114	20	01/22/18 21:12	01/22/18 21:12	MBF

SG-1 L964491-06 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/18/18 15:07	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1065099	1	01/22/18 14:13	01/22/18 14:13	AMC
Volatile Organic Compounds (MS) by Method TO-15	WG1065339	10	01/23/18 13:56	01/23/18 13:56	AMC

SG-2 L964491-07 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/19/18 12:11	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1065099	1	01/22/18 15:00	01/22/18 15:00	AMC

SS-2 L964491-08 Air

Collected by	Collected date/time	Received date/time
Larry Bertsch	01/18/18 17:25	01/20/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (MS) by Method TO-15	WG1065114	10	01/22/18 21:50	01/22/18 21:50	MBF

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times, unless qualified or notated within the report. Where applicable, all MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All radiochemical sample results for solids are reported on a dry weight basis with the exception of tritium, carbon-14 and radon, unless wet weight was requested by the client. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.



Jason Romer
Technical Service Representative

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	1.25	2.97	23.4	55.5		1	WG1064707
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1064707
Benzene	71-43-2	78.10	0.200	0.639	0.452	1.44		1	WG1064707
Benzyl Chloride	100-44-7	127	0.200	1.04	ND	ND		1	WG1064707
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1064707
Bromoform	75-25-2	253	0.600	6.21	ND	ND		1	WG1064707
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1064707
1,3-Butadiene	106-99-0	54.10	2.00	4.43	ND	ND		1	WG1064707
Carbon disulfide	75-15-0	76.10	0.200	0.622	ND	ND		1	WG1064707
Carbon tetrachloride	56-23-5	154	0.200	1.26	ND	ND		1	WG1064707
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1064707
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1064707
Chloroform	67-66-3	119	0.200	0.973	ND	ND		1	WG1064707
Chloromethane	74-87-3	50.50	0.200	0.413	ND	ND		1	WG1064707
2-Chlorotoluene	95-49-8	126	0.200	1.03	ND	ND		1	WG1064707
Cyclohexane	110-82-7	84.20	0.200	0.689	0.367	1.26		1	WG1064707
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1064707
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1064707
1,2-Dichlorobenzene	95-50-1	147	0.200	1.20	ND	ND		1	WG1064707
1,3-Dichlorobenzene	541-73-1	147	0.200	1.20	0.201	1.21		1	WG1064707
1,4-Dichlorobenzene	106-46-7	147	0.200	1.20	ND	ND		1	WG1064707
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1064707
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1064707
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1064707
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1064707
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1064707
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1064707
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1064707
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1064707
1,4-Dioxane	123-91-1	88.10	0.200	0.721	ND	ND		1	WG1064707
Ethanol	64-17-5	46.10	15.8	29.8	58.4	110		25	WG1065114
Ethylbenzene	100-41-4	106	0.200	0.867	3.04	13.2		1	WG1064707
4-Ethyltoluene	622-96-8	120	0.200	0.982	0.318	1.56		1	WG1064707
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	0.465	2.61		1	WG1064707
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	1.24	6.16		1	WG1064707
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	ND	ND		1	WG1064707
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1064707
Heptane	142-82-5	100	0.200	0.818	0.336	1.37		1	WG1064707
Hexachloro-1,3-butadiene	87-68-3	261	0.630	6.73	ND	ND		1	WG1064707
n-Hexane	110-54-3	86.20	0.200	0.705	0.369	1.30		1	WG1064707
Isopropylbenzene	98-82-8	120.20	0.200	0.983	ND	ND		1	WG1064707
Methylene Chloride	75-09-2	84.90	0.200	0.694	ND	ND		1	WG1064707
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	ND	ND		1	WG1064707
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	3.31	9.77		1	WG1064707
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	ND	ND		1	WG1064707
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1064707
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1064707
Naphthalene	91-20-3	128	0.630	3.30	ND	ND		1	WG1064707
2-Propanol	67-63-0	60.10	31.2	76.7	657	1620		25	WG1065114
Propene	115-07-1	42.10	0.400	0.689	ND	ND		1	WG1064707
Styrene	100-42-5	104	0.200	0.851	ND	ND		1	WG1064707
1,1,2,2-Tetrachloroethane	79-34-5	168	0.200	1.37	ND	ND		1	WG1064707
Tetrachloroethylene	127-18-4	166	0.200	1.36	0.447	3.04		1	WG1064707
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	0.822	2.42		1	WG1064707
Toluene	108-88-3	92.10	0.200	0.753	10.9	41.0		1	WG1064707
1,2,4-Trichlorobenzene	120-82-1	181	0.630	4.66	ND	ND		1	WG1064707

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	ND	ND		1	WG1064707
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1064707
Trichloroethylene	79-01-6	131	0.200	1.07	ND	ND		1	WG1064707
1,2,4-Trimethylbenzene	95-63-6	120	0.200	0.982	0.357	1.75		1	WG1064707
1,3,5-Trimethylbenzene	108-67-8	120	0.200	0.982	ND	ND		1	WG1064707
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	ND	ND		1	WG1064707
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1064707
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1064707
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1064707
m&p-Xylene	1330-20-7	106	0.400	1.73	10.7	46.5		1	WG1064707
o-Xylene	95-47-6	106	0.200	0.867	3.00	13.0		1	WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*99.3*				WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*95.5*				WG1065114

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	31.2	74.1	472	1120		25	WG1065114
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1064707
Benzene	71-43-2	78.10	0.200	0.639	5.11	16.3		1	WG1064707
Benzyl Chloride	100-44-7	127	0.200	1.04	ND	ND		1	WG1064707
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1064707
Bromoform	75-25-2	253	0.600	6.21	ND	ND		1	WG1064707
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1064707
1,3-Butadiene	106-99-0	54.10	2.00	4.43	ND	ND		1	WG1064707
Carbon disulfide	75-15-0	76.10	0.200	0.622	ND	ND		1	WG1064707
Carbon tetrachloride	56-23-5	154	0.200	1.26	1.06	6.67		1	WG1064707
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1064707
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1064707
Chloroform	67-66-3	119	0.200	0.973	3.98	19.4		1	WG1064707
Chloromethane	74-87-3	50.50	0.200	0.413	0.457	0.945		1	WG1064707
2-Chlorotoluene	95-49-8	126	0.200	1.03	ND	ND		1	WG1064707
Cyclohexane	110-82-7	84.20	0.200	0.689	ND	ND		1	WG1064707
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1064707
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1064707
1,2-Dichlorobenzene	95-50-1	147	0.200	1.20	ND	ND		1	WG1064707
1,3-Dichlorobenzene	541-73-1	147	0.200	1.20	0.952	5.72		1	WG1064707
1,4-Dichlorobenzene	106-46-7	147	0.200	1.20	ND	ND		1	WG1064707
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1064707
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1064707
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1064707
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1064707
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1064707
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1064707
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1064707
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1064707
1,4-Dioxane	123-91-1	88.10	0.200	0.721	0.632	2.28		1	WG1064707
Ethanol	64-17-5	46.10	15.8	29.8	291	548		25	WG1065114
Ethylbenzene	100-41-4	106	0.200	0.867	0.665	2.88		1	WG1064707
4-Ethyltoluene	622-96-8	120	0.200	0.982	0.807	3.96		1	WG1064707
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	3.80	21.3		1	WG1064707
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	15.2	75.0		1	WG1064707
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	0.374	2.86		1	WG1064707
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1064707
Heptane	142-82-5	100	0.200	0.818	0.468	1.92		1	WG1064707
Hexachloro-1,3-butadiene	87-68-3	261	0.630	6.73	ND	ND		1	WG1064707
n-Hexane	110-54-3	86.20	0.200	0.705	0.737	2.60		1	WG1064707
Isopropylbenzene	98-82-8	120.20	0.200	0.983	ND	ND		1	WG1064707
Methylene Chloride	75-09-2	84.90	0.200	0.694	ND	ND		1	WG1064707
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	2.49	10.2		1	WG1064707
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	16.0	47.3		1	WG1064707
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	1.78	7.30		1	WG1064707
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1064707
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1064707
Naphthalene	91-20-3	128	0.630	3.30	0.671	3.51		1	WG1064707
2-Propanol	67-63-0	60.10	31.2	76.7	272	669		25	WG1065114
Propene	115-07-1	42.10	0.400	0.689	33.0	56.7		1	WG1064707
Styrene	100-42-5	104	0.200	0.851	1.64	6.98		1	WG1064707
1,1,2,2-Tetrachloroethane	79-34-5	168	0.200	1.37	ND	ND		1	WG1064707
Tetrachloroethylene	127-18-4	166	0.200	1.36	1.55	10.6		1	WG1064707
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	ND	ND		1	WG1064707
Toluene	108-88-3	92.10	0.200	0.753	14.1	53.1		1	WG1064707
1,2,4-Trichlorobenzene	120-82-1	181	0.630	4.66	ND	ND		1	WG1064707

1 Cp
2 Tc
3 Ss
4 Cn
5 Sr
6 Qc
7 Gl
8 Al
9 Sc

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	2.16	11.8		1	WG1064707
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1064707
Trichloroethylene	79-01-6	131	0.200	1.07	0.543	2.91		1	WG1064707
1,2,4-Trimethylbenzene	95-63-6	120	0.200	0.982	1.09	5.36		1	WG1064707
1,3,5-Trimethylbenzene	108-67-8	120	0.200	0.982	0.284	1.39		1	WG1064707
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	ND	ND		1	WG1064707
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1064707
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1064707
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1064707
m&p-Xylene	1330-20-7	106	0.400	1.73	2.66	11.5		1	WG1064707
o-Xylene	95-47-6	106	0.200	0.867	0.854	3.70		1	WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*95.5*				WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*95.7*				WG1065114

1 Cp
2 Tc
3 Ss
4 Cn
5 Sr
6 Qc
7 Gl
8 Al
9 Sc

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	12.5	29.7	75.7	180		10	WG1065114
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1064707
Benzene	71-43-2	78.10	0.200	0.639	1.04	3.32		1	WG1064707
Benzyl Chloride	100-44-7	127	0.200	1.04	ND	ND		1	WG1064707
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1064707
Bromoform	75-25-2	253	0.600	6.21	ND	ND		1	WG1064707
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1064707
1,3-Butadiene	106-99-0	54.10	2.00	4.43	ND	ND		1	WG1064707
Carbon disulfide	75-15-0	76.10	0.200	0.622	1.32	4.11		1	WG1064707
Carbon tetrachloride	56-23-5	154	0.200	1.26	ND	ND		1	WG1064707
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1064707
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1064707
Chloroform	67-66-3	119	0.200	0.973	1.37	6.68		1	WG1064707
Chloromethane	74-87-3	50.50	0.200	0.413	0.232	0.479		1	WG1064707
2-Chlorotoluene	95-49-8	126	0.200	1.03	ND	ND		1	WG1064707
Cyclohexane	110-82-7	84.20	0.200	0.689	ND	ND		1	WG1064707
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1064707
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1064707
1,2-Dichlorobenzene	95-50-1	147	0.200	1.20	ND	ND		1	WG1064707
1,3-Dichlorobenzene	541-73-1	147	0.200	1.20	ND	ND		1	WG1064707
1,4-Dichlorobenzene	106-46-7	147	0.200	1.20	ND	ND		1	WG1064707
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1064707
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1064707
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1064707
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1064707
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1064707
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1064707
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1064707
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1064707
1,4-Dioxane	123-91-1	88.10	0.200	0.721	ND	ND		1	WG1064707
Ethanol	64-17-5	46.10	6.30	11.9	131	247		10	WG1065114
Ethylbenzene	100-41-4	106	0.200	0.867	0.733	3.18		1	WG1064707
4-Ethyltoluene	622-96-8	120	0.200	0.982	0.680	3.34		1	WG1064707
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	2.79	15.7		1	WG1064707
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	2.74	13.5		1	WG1064707
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	ND	ND		1	WG1064707
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1064707
Heptane	142-82-5	100	0.200	0.818	0.598	2.44		1	WG1064707
Hexachloro-1,3-butadiene	87-68-3	261	0.630	6.73	ND	ND		1	WG1064707
n-Hexane	110-54-3	86.20	0.200	0.705	0.373	1.31		1	WG1064707
Isopropylbenzene	98-82-8	120.20	0.200	0.983	ND	ND		1	WG1064707
Methylene Chloride	75-09-2	84.90	0.200	0.694	0.305	1.06		1	WG1064707
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	ND	ND		1	WG1064707
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	6.43	19.0		1	WG1064707
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	ND	ND		1	WG1064707
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1064707
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1064707
Naphthalene	91-20-3	128	0.630	3.30	ND	ND		1	WG1064707
2-Propanol	67-63-0	60.10	1.25	3.07	11.2	27.4		1	WG1064707
Propene	115-07-1	42.10	0.400	0.689	2.96	5.09		1	WG1064707
Styrene	100-42-5	104	0.200	0.851	0.248	1.06		1	WG1064707
1,1,2,2-Tetrachloroethane	79-34-5	168	0.200	1.37	ND	ND		1	WG1064707
Tetrachloroethylene	127-18-4	166	0.200	1.36	0.541	3.67		1	WG1064707
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	ND	ND		1	WG1064707
Toluene	108-88-3	92.10	0.200	0.753	1.08	4.08		1	WG1064707
1,2,4-Trichlorobenzene	120-82-1	181	0.630	4.66	ND	ND		1	WG1064707

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	ND	ND		1	WG1064707
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1064707
Trichloroethylene	79-01-6	131	0.200	1.07	ND	ND		1	WG1064707
1,2,4-Trimethylbenzene	95-63-6	120	0.200	0.982	0.795	3.90		1	WG1064707
1,3,5-Trimethylbenzene	108-67-8	120	0.200	0.982	0.221	1.08		1	WG1064707
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	ND	ND		1	WG1064707
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1064707
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1064707
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1064707
m&p-Xylene	1330-20-7	106	0.400	1.73	2.84	12.3		1	WG1064707
o-Xylene	95-47-6	106	0.200	0.867	1.47	6.39		1	WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*97.6*				WG1065114
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*97.7*				WG1064707

1 Cp
2 Tc
3 Ss
4 Cn
5 Sr
6 Qc
7 Gl
8 Al
9 Sc

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	25.0	59.4	127	302		20	WG1065114
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1064707
Benzene	71-43-2	78.10	0.200	0.639	0.862	2.75		1	WG1064707
Benzyl Chloride	100-44-7	127	0.200	1.04	ND	ND		1	WG1064707
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1064707
Bromoform	75-25-2	253	0.600	6.21	ND	ND		1	WG1064707
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1064707
1,3-Butadiene	106-99-0	54.10	2.00	4.43	ND	ND		1	WG1064707
Carbon disulfide	75-15-0	76.10	0.200	0.622	ND	ND		1	WG1064707
Carbon tetrachloride	56-23-5	154	0.200	1.26	ND	ND		1	WG1064707
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1064707
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1064707
Chloroform	67-66-3	119	0.200	0.973	5.06	24.6		1	WG1064707
Chloromethane	74-87-3	50.50	0.200	0.413	0.351	0.726		1	WG1064707
2-Chlorotoluene	95-49-8	126	0.200	1.03	ND	ND		1	WG1064707
Cyclohexane	110-82-7	84.20	0.200	0.689	ND	ND		1	WG1064707
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1064707
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1064707
1,2-Dichlorobenzene	95-50-1	147	0.200	1.20	ND	ND		1	WG1064707
1,3-Dichlorobenzene	541-73-1	147	0.200	1.20	ND	ND		1	WG1064707
1,4-Dichlorobenzene	106-46-7	147	0.200	1.20	ND	ND		1	WG1064707
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1064707
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1064707
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1064707
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1064707
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1064707
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1064707
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1064707
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1064707
1,4-Dioxane	123-91-1	88.10	0.200	0.721	ND	ND		1	WG1064707
Ethanol	64-17-5	46.10	12.6	23.8	202	380		20	WG1065114
Ethylbenzene	100-41-4	106	0.200	0.867	0.427	1.85		1	WG1064707
4-Ethyltoluene	622-96-8	120	0.200	0.982	1.03	5.06		1	WG1064707
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	24.8	140		1	WG1064707
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	23.9	118		1	WG1064707
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	ND	ND		1	WG1064707
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1064707
Heptane	142-82-5	100	0.200	0.818	1.41	5.78		1	WG1064707
Hexachloro-1,3-butadiene	87-68-3	261	0.630	6.73	ND	ND		1	WG1064707
n-Hexane	110-54-3	86.20	0.200	0.705	0.722	2.54		1	WG1064707
Isopropylbenzene	98-82-8	120.20	0.200	0.983	ND	ND		1	WG1064707
Methylene Chloride	75-09-2	84.90	0.200	0.694	ND	ND		1	WG1064707
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	2.73	11.2		1	WG1064707
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	10.4	30.5		1	WG1064707
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	2.13	8.71		1	WG1064707
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1064707
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1064707
Naphthalene	91-20-3	128	0.630	3.30	ND	ND		1	WG1064707
2-Propanol	67-63-0	60.10	25.0	61.5	74.9	184		20	WG1065114
Propene	115-07-1	42.10	0.400	0.689	5.00	8.60		1	WG1064707
Styrene	100-42-5	104	0.200	0.851	0.231	0.984		1	WG1064707
1,1,2,2-Tetrachloroethane	79-34-5	168	0.200	1.37	ND	ND		1	WG1064707
Tetrachloroethylene	127-18-4	166	0.200	1.36	2.39	16.2		1	WG1064707
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	ND	ND		1	WG1064707
Toluene	108-88-3	92.10	0.200	0.753	2.46	9.27		1	WG1064707
1,2,4-Trichlorobenzene	120-82-1	181	0.630	4.66	ND	ND		1	WG1064707

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	ND	ND		1	WG1064707
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1064707
Trichloroethylene	79-01-6	131	0.200	1.07	ND	ND		1	WG1064707
1,2,4-Trimethylbenzene	95-63-6	120	0.200	0.982	1.21	5.96		1	WG1064707
1,3,5-Trimethylbenzene	108-67-8	120	0.200	0.982	0.264	1.30		1	WG1064707
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	ND	ND		1	WG1064707
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1064707
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1064707
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1064707
m&p-Xylene	1330-20-7	106	0.400	1.73	1.72	7.45		1	WG1064707
o-Xylene	95-47-6	106	0.200	0.867	0.680	2.95		1	WG1064707
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*95.3*				WG1065114
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*98.9*				WG1064707

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	1.25	2.97	24.4	57.9		1	WG1065099
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1065099
Benzene	71-43-2	78.10	0.200	0.639	1.29	4.11		1	WG1065099
Benzyl Chloride	100-44-7	127	2.00	10.4	ND	ND		10	WG1065339
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1065099
Bromoform	75-25-2	253	6.00	62.1	ND	ND		10	WG1065339
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1065099
1,3-Butadiene	106-99-0	54.10	2.00	4.43	2.72	6.01		1	WG1065099
Carbon disulfide	75-15-0	76.10	0.200	0.622	2.53	7.88		1	WG1065099
Carbon tetrachloride	56-23-5	154	0.200	1.26	ND	ND		1	WG1065099
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1065099
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1065099
Chloroform	67-66-3	119	0.200	0.973	0.611	2.98		1	WG1065099
Chloromethane	74-87-3	50.50	0.200	0.413	0.260	0.538		1	WG1065099
2-Chlorotoluene	95-49-8	126	2.00	10.3	ND	ND		10	WG1065339
Cyclohexane	110-82-7	84.20	0.200	0.689	4.94	17.0		1	WG1065099
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1065099
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1065099
1,2-Dichlorobenzene	95-50-1	147	2.00	12.0	ND	ND		10	WG1065339
1,3-Dichlorobenzene	541-73-1	147	2.00	12.0	ND	ND		10	WG1065339
1,4-Dichlorobenzene	106-46-7	147	2.00	12.0	ND	ND	J4	10	WG1065339
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1065099
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1065099
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1065099
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1065099
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1065099
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1065099
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1065099
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1065099
1,4-Dioxane	123-91-1	88.10	0.200	0.721	ND	ND		1	WG1065099
Ethanol	64-17-5	46.10	0.630	1.19	6.05	11.4		1	WG1065099
Ethylbenzene	100-41-4	106	2.00	8.67	4.17	18.1		10	WG1065339
4-Ethyltoluene	622-96-8	120	2.00	9.82	6.03	29.6		10	WG1065339
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	1.05	5.89		1	WG1065099
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	18.7	92.7		1	WG1065099
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	ND	ND		1	WG1065099
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1065099
Heptane	142-82-5	100	0.200	0.818	6.61	27.0		1	WG1065099
Hexachloro-1,3-butadiene	87-68-3	261	6.30	67.3	ND	ND		10	WG1065339
n-Hexane	110-54-3	86.20	0.200	0.705	3.76	13.3		1	WG1065099
Isopropylbenzene	98-82-8	120.20	2.00	9.83	2.33	11.4		10	WG1065339
Methylene Chloride	75-09-2	84.90	0.200	0.694	ND	ND		1	WG1065099
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	ND	ND		1	WG1065099
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	19.0	56.1		1	WG1065099
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	ND	ND		1	WG1065099
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1065099
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1065099
Naphthalene	91-20-3	128	6.30	33.0	ND	ND		10	WG1065339
2-Propanol	67-63-0	60.10	1.25	3.07	1.52	3.74		1	WG1065099
Propene	115-07-1	42.10	0.400	0.689	28.6	49.3		1	WG1065099
Styrene	100-42-5	104	2.00	8.51	ND	ND		10	WG1065339
1,1,2,2-Tetrachloroethane	79-34-5	168	2.00	13.7	2.64	18.1		10	WG1065339
Tetrachloroethylene	127-18-4	166	0.200	1.36	0.717	4.87		1	WG1065099
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	31.0	91.5		1	WG1065099
Toluene	108-88-3	92.10	0.200	0.753	5.01	18.9		1	WG1065099
1,2,4-Trichlorobenzene	120-82-1	181	6.30	46.6	ND	ND		10	WG1065339

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	ND	ND		1	WG1065099
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1065099
Trichloroethylene	79-01-6	131	0.200	1.07	0.444	2.38		1	WG1065099
1,2,4-Trimethylbenzene	95-63-6	120	2.00	9.82	5.00	24.5		10	WG1065339
1,3,5-Trimethylbenzene	108-67-8	120	2.00	9.82	3.74	18.4		10	WG1065339
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	24.0	112		1	WG1065099
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1065099
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1065099
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1065099
m&p-Xylene	1330-20-7	106	4.00	17.3	14.7	63.7		10	WG1065339
o-Xylene	95-47-6	106	2.00	8.67	11.4	49.2		10	WG1065339
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*102*				WG1065339
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*226*		J1		WG1065099

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	1.25	2.97	41.0	97.5		1	WG1065099
Allyl chloride	107-05-1	76.53	0.200	0.626	ND	ND		1	WG1065099
Benzene	71-43-2	78.10	0.200	0.639	1.76	5.63		1	WG1065099
Benzyl Chloride	100-44-7	127	0.200	1.04	0.603	3.13		1	WG1065099
Bromodichloromethane	75-27-4	164	0.200	1.34	ND	ND		1	WG1065099
Bromoform	75-25-2	253	0.600	6.21	ND	ND		1	WG1065099
Bromomethane	74-83-9	94.90	0.200	0.776	ND	ND		1	WG1065099
1,3-Butadiene	106-99-0	54.10	2.00	4.43	3.98	8.80		1	WG1065099
Carbon disulfide	75-15-0	76.10	0.200	0.622	1.44	4.48		1	WG1065099
Carbon tetrachloride	56-23-5	154	0.200	1.26	ND	ND		1	WG1065099
Chlorobenzene	108-90-7	113	0.200	0.924	ND	ND		1	WG1065099
Chloroethane	75-00-3	64.50	0.200	0.528	ND	ND		1	WG1065099
Chloroform	67-66-3	119	0.200	0.973	ND	ND		1	WG1065099
Chloromethane	74-87-3	50.50	0.200	0.413	ND	ND		1	WG1065099
2-Chlorotoluene	95-49-8	126	0.200	1.03	0.410	2.12		1	WG1065099
Cyclohexane	110-82-7	84.20	0.200	0.689	0.290	1.00		1	WG1065099
Dibromochloromethane	124-48-1	208	0.200	1.70	ND	ND		1	WG1065099
1,2-Dibromoethane	106-93-4	188	0.200	1.54	ND	ND		1	WG1065099
1,2-Dichlorobenzene	95-50-1	147	0.200	1.20	ND	ND		1	WG1065099
1,3-Dichlorobenzene	541-73-1	147	0.200	1.20	ND	ND		1	WG1065099
1,4-Dichlorobenzene	106-46-7	147	0.200	1.20	ND	ND		1	WG1065099
1,2-Dichloroethane	107-06-2	99	0.200	0.810	ND	ND		1	WG1065099
1,1-Dichloroethane	75-34-3	98	0.200	0.802	ND	ND		1	WG1065099
1,1-Dichloroethene	75-35-4	96.90	0.200	0.793	ND	ND		1	WG1065099
cis-1,2-Dichloroethene	156-59-2	96.90	0.200	0.793	ND	ND		1	WG1065099
trans-1,2-Dichloroethene	156-60-5	96.90	0.200	0.793	ND	ND		1	WG1065099
1,2-Dichloropropane	78-87-5	113	0.200	0.924	ND	ND		1	WG1065099
cis-1,3-Dichloropropene	10061-01-5	111	0.200	0.908	ND	ND		1	WG1065099
trans-1,3-Dichloropropene	10061-02-6	111	0.200	0.908	ND	ND		1	WG1065099
1,4-Dioxane	123-91-1	88.10	0.200	0.721	ND	ND		1	WG1065099
Ethanol	64-17-5	46.10	0.630	1.19	4.03	7.61		1	WG1065099
Ethylbenzene	100-41-4	106	0.200	0.867	0.874	3.79		1	WG1065099
4-Ethyltoluene	622-96-8	120	0.200	0.982	3.93	19.3		1	WG1065099
Trichlorofluoromethane	75-69-4	137.40	0.200	1.12	0.246	1.38		1	WG1065099
Dichlorodifluoromethane	75-71-8	120.92	0.200	0.989	7.40	36.6		1	WG1065099
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	0.200	1.53	ND	ND		1	WG1065099
1,2-Dichlorotetrafluoroethane	76-14-2	171	0.200	1.40	ND	ND		1	WG1065099
Heptane	142-82-5	100	0.200	0.818	1.19	4.86		1	WG1065099
Hexachloro-1,3-butadiene	87-68-3	261	0.630	6.73	ND	ND		1	WG1065099
n-Hexane	110-54-3	86.20	0.200	0.705	1.41	4.97		1	WG1065099
Isopropylbenzene	98-82-8	120.20	0.200	0.983	0.468	2.30		1	WG1065099
Methylene Chloride	75-09-2	84.90	0.200	0.694	ND	ND		1	WG1065099
Methyl Butyl Ketone	591-78-6	100	1.25	5.11	ND	ND		1	WG1065099
2-Butanone (MEK)	78-93-3	72.10	1.25	3.69	11.2	33.1		1	WG1065099
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	1.25	5.12	ND	ND		1	WG1065099
Methyl methacrylate	80-62-6	100.12	0.200	0.819	ND	ND		1	WG1065099
MTBE	1634-04-4	88.10	0.200	0.721	ND	ND		1	WG1065099
Naphthalene	91-20-3	128	0.630	3.30	ND	ND		1	WG1065099
2-Propanol	67-63-0	60.10	1.25	3.07	ND	ND		1	WG1065099
Propene	115-07-1	42.10	0.400	0.689	26.5	45.6		1	WG1065099
Styrene	100-42-5	104	0.200	0.851	0.223	0.947		1	WG1065099
1,1,2,2-Tetrachloroethane	79-34-5	168	0.200	1.37	ND	ND		1	WG1065099
Tetrachloroethylene	127-18-4	166	0.200	1.36	0.226	1.53		1	WG1065099
Tetrahydrofuran	109-99-9	72.10	0.200	0.590	12.8	37.9		1	WG1065099
Toluene	108-88-3	92.10	0.200	0.753	2.06	7.76		1	WG1065099
1,2,4-Trichlorobenzene	120-82-1	181	0.630	4.66	ND	ND		1	WG1065099

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	0.200	1.09	ND	ND		1	WG1065099
1,1,2-Trichloroethane	79-00-5	133	0.200	1.09	ND	ND		1	WG1065099
Trichloroethylene	79-01-6	131	0.200	1.07	ND	ND		1	WG1065099
1,2,4-Trimethylbenzene	95-63-6	120	0.200	0.982	13.0	63.8		1	WG1065099
1,3,5-Trimethylbenzene	108-67-8	120	0.200	0.982	4.31	21.2		1	WG1065099
2,2,4-Trimethylpentane	540-84-1	114.22	0.200	0.934	ND	ND		1	WG1065099
Vinyl chloride	75-01-4	62.50	0.200	0.511	ND	ND		1	WG1065099
Vinyl Bromide	593-60-2	106.95	0.200	0.875	ND	ND		1	WG1065099
Vinyl acetate	108-05-4	86.10	0.200	0.704	ND	ND		1	WG1065099
m&p-Xylene	1330-20-7	106	0.400	1.73	3.42	14.8		1	WG1065099
o-Xylene	95-47-6	106	0.200	0.867	1.49	6.46		1	WG1065099
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*100*				WG1065099

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
Acetone	67-64-1	58.10	12.5	29.7	47.4	113		10	WG1065114
Allyl chloride	107-05-1	76.53	2.00	6.26	ND	ND		10	WG1065114
Benzene	71-43-2	78.10	2.00	6.39	ND	ND		10	WG1065114
Benzyl Chloride	100-44-7	127	2.00	10.4	ND	ND		10	WG1065114
Bromodichloromethane	75-27-4	164	2.00	13.4	ND	ND		10	WG1065114
Bromoform	75-25-2	253	6.00	62.1	ND	ND		10	WG1065114
Bromomethane	74-83-9	94.90	2.00	7.76	ND	ND		10	WG1065114
1,3-Butadiene	106-99-0	54.10	20.0	44.3	ND	ND		10	WG1065114
Carbon disulfide	75-15-0	76.10	2.00	6.22	ND	ND		10	WG1065114
Carbon tetrachloride	56-23-5	154	2.00	12.6	ND	ND		10	WG1065114
Chlorobenzene	108-90-7	113	2.00	9.24	ND	ND		10	WG1065114
Chloroethane	75-00-3	64.50	2.00	5.28	ND	ND		10	WG1065114
Chloroform	67-66-3	119	2.00	9.73	ND	ND		10	WG1065114
Chloromethane	74-87-3	50.50	2.00	4.13	ND	ND		10	WG1065114
2-Chlorotoluene	95-49-8	126	2.00	10.3	ND	ND		10	WG1065114
Cyclohexane	110-82-7	84.20	2.00	6.89	ND	ND		10	WG1065114
Dibromochloromethane	124-48-1	208	2.00	17.0	ND	ND		10	WG1065114
1,2-Dibromoethane	106-93-4	188	2.00	15.4	ND	ND		10	WG1065114
1,2-Dichlorobenzene	95-50-1	147	2.00	12.0	ND	ND		10	WG1065114
1,3-Dichlorobenzene	541-73-1	147	2.00	12.0	ND	ND		10	WG1065114
1,4-Dichlorobenzene	106-46-7	147	2.00	12.0	ND	ND		10	WG1065114
1,2-Dichloroethane	107-06-2	99	2.00	8.10	ND	ND		10	WG1065114
1,1-Dichloroethane	75-34-3	98	2.00	8.02	ND	ND		10	WG1065114
1,1-Dichloroethene	75-35-4	96.90	2.00	7.93	ND	ND		10	WG1065114
cis-1,2-Dichloroethene	156-59-2	96.90	2.00	7.93	ND	ND		10	WG1065114
trans-1,2-Dichloroethene	156-60-5	96.90	2.00	7.93	ND	ND		10	WG1065114
1,2-Dichloropropane	78-87-5	113	2.00	9.24	ND	ND		10	WG1065114
cis-1,3-Dichloropropene	10061-01-5	111	2.00	9.08	ND	ND		10	WG1065114
trans-1,3-Dichloropropene	10061-02-6	111	2.00	9.08	ND	ND		10	WG1065114
1,4-Dioxane	123-91-1	88.10	2.00	7.21	ND	ND		10	WG1065114
Ethanol	64-17-5	46.10	6.30	11.9	41.5	78.2		10	WG1065114
Ethylbenzene	100-41-4	106	2.00	8.67	3.27	14.2		10	WG1065114
4-Ethyltoluene	622-96-8	120	2.00	9.82	ND	ND		10	WG1065114
Trichlorofluoromethane	75-69-4	137.40	2.00	11.2	ND	ND		10	WG1065114
Dichlorodifluoromethane	75-71-8	120.92	2.00	9.89	ND	ND		10	WG1065114
1,1,2-Trichlorotrifluoroethane	76-13-1	187.40	2.00	15.3	ND	ND		10	WG1065114
1,2-Dichlorotetrafluoroethane	76-14-2	171	2.00	14.0	ND	ND		10	WG1065114
Heptane	142-82-5	100	2.00	8.18	ND	ND		10	WG1065114
Hexachloro-1,3-butadiene	87-68-3	261	6.30	67.3	ND	ND		10	WG1065114
n-Hexane	110-54-3	86.20	2.00	7.05	ND	ND		10	WG1065114
Isopropylbenzene	98-82-8	120.20	2.00	9.83	ND	ND		10	WG1065114
Methylene Chloride	75-09-2	84.90	2.00	6.94	ND	ND		10	WG1065114
Methyl Butyl Ketone	591-78-6	100	12.5	51.1	ND	ND		10	WG1065114
2-Butanone (MEK)	78-93-3	72.10	12.5	36.9	ND	ND		10	WG1065114
4-Methyl-2-pentanone (MIBK)	108-10-1	100.10	12.5	51.2	ND	ND		10	WG1065114
Methyl methacrylate	80-62-6	100.12	2.00	8.19	ND	ND		10	WG1065114
MTBE	1634-04-4	88.10	2.00	7.21	ND	ND		10	WG1065114
Naphthalene	91-20-3	128	6.30	33.0	ND	ND		10	WG1065114
2-Propanol	67-63-0	60.10	12.5	30.7	60.0	147		10	WG1065114
Propene	115-07-1	42.10	4.00	6.89	ND	ND		10	WG1065114
Styrene	100-42-5	104	2.00	8.51	ND	ND		10	WG1065114
1,1,2,2-Tetrachloroethane	79-34-5	168	2.00	13.7	ND	ND		10	WG1065114
Tetrachloroethylene	127-18-4	166	2.00	13.6	ND	ND		10	WG1065114
Tetrahydrofuran	109-99-9	72.10	2.00	5.90	ND	ND		10	WG1065114
Toluene	108-88-3	92.10	2.00	7.53	2.89	10.9		10	WG1065114
1,2,4-Trichlorobenzene	120-82-1	181	6.30	46.6	ND	ND		10	WG1065114

Volatile Organic Compounds (MS) by Method TO-15

Analyte	CAS #	Mol. Wt.	RDL1 ppbv	RDL2 ug/m3	Result ppbv	Result ug/m3	Qualifier	Dilution	Batch
1,1,1-Trichloroethane	71-55-6	133	2.00	10.9	ND	ND		10	WG1065114
1,1,2-Trichloroethane	79-00-5	133	2.00	10.9	ND	ND		10	WG1065114
Trichloroethylene	79-01-6	131	2.00	10.7	ND	ND		10	WG1065114
1,2,4-Trimethylbenzene	95-63-6	120	2.00	9.82	2.25	11.0		10	WG1065114
1,3,5-Trimethylbenzene	108-67-8	120	2.00	9.82	ND	ND		10	WG1065114
2,2,4-Trimethylpentane	540-84-1	114.22	2.00	9.34	ND	ND		10	WG1065114
Vinyl chloride	75-01-4	62.50	2.00	5.11	ND	ND		10	WG1065114
Vinyl Bromide	593-60-2	106.95	2.00	8.75	ND	ND		10	WG1065114
Vinyl acetate	108-05-4	86.10	2.00	7.04	ND	ND		10	WG1065114
m&p-Xylene	1330-20-7	106	4.00	17.3	13.7	59.2		10	WG1065114
o-Xylene	95-47-6	106	2.00	8.67	7.89	34.2		10	WG1065114
(S) 1,4-Bromofluorobenzene	*460-00-4*	*175*	*60.0-140*		*96.1*				WG1065114

Method Blank (MB)

(MB) R3280857-3 01/20/18 10:23

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Acetone	U		0.0569	1.25
Allyl Chloride	U		0.0546	0.200
Benzene	U		0.0460	0.200
Benzyl Chloride	U		0.0598	0.200
Bromodichloromethane	U		0.0436	0.200
Bromoform	U		0.0786	0.600
Bromomethane	U		0.0609	0.200
1,3-Butadiene	U		0.0563	2.00
Carbon disulfide	U		0.0544	0.200
Carbon tetrachloride	U		0.0585	0.200
Chlorobenzene	U		0.0601	0.200
Chloroethane	U		0.0489	0.200
Chloroform	U		0.0574	0.200
Chloromethane	U		0.0544	0.200
2-Chlorotoluene	U		0.0605	0.200
Cyclohexane	U		0.0534	0.200
Dibromochloromethane	U		0.0494	0.200
1,2-Dibromoethane	U		0.0185	0.200
1,2-Dichlorobenzene	U		0.0603	0.200
1,3-Dichlorobenzene	U		0.0597	0.200
1,4-Dichlorobenzene	U		0.0557	0.200
1,2-Dichloroethane	U		0.0616	0.200
1,1-Dichloroethane	U		0.0514	0.200
1,1-Dichloroethene	U		0.0490	0.200
cis-1,2-Dichloroethene	U		0.0389	0.200
trans-1,2-Dichloroethene	U		0.0464	0.200
1,2-Dichloropropane	U		0.0599	0.200
cis-1,3-Dichloropropene	U		0.0588	0.200
trans-1,3-Dichloropropene	U		0.0435	0.200
1,4-Dioxane	U		0.0554	0.200
Ethylbenzene	U		0.0506	0.200
4-Ethyltoluene	U		0.0666	0.200
Trichlorofluoromethane	U		0.0673	0.200
Dichlorodifluoromethane	U		0.0601	0.200
1,1,2-Trichlorotrifluoroethane	U		0.0687	0.200
1,2-Dichlorotetrafluoroethane	U		0.0458	0.200
Heptane	U		0.0626	0.200
Hexachloro-1,3-butadiene	U		0.0656	0.630
n-Hexane	U		0.0457	0.200
Isopropylbenzene	U		0.0563	0.200

Method Blank (MB)

(MB) R3280857-3 01/20/18 10:23

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Methylene Chloride	U		0.0465	0.200
Methyl Butyl Ketone	U		0.0682	1.25
2-Butanone (MEK)	U		0.0493	1.25
4-Methyl-2-pentanone (MIBK)	U		0.0650	1.25
Methyl Methacrylate	U		0.0773	0.200
MTBE	U		0.0505	0.200
Naphthalene	U		0.154	0.630
2-Propanol	U		0.0882	1.25
Propene	U		0.0932	0.400
Styrene	U		0.0465	0.200
1,1,2,2-Tetrachloroethane	U		0.0576	0.200
Tetrachloroethylene	U		0.0497	0.200
Tetrahydrofuran	U		0.0508	0.200
Toluene	U		0.0499	0.200
1,2,4-Trichlorobenzene	U		0.148	0.630
1,1,1-Trichloroethane	U		0.0665	0.200
1,1,2-Trichloroethane	U		0.0287	0.200
Trichloroethylene	U		0.0545	0.200
1,2,4-Trimethylbenzene	U		0.0483	0.200
1,3,5-Trimethylbenzene	U		0.0631	0.200
2,2,4-Trimethylpentane	U		0.0456	0.200
Vinyl chloride	U		0.0457	0.200
Vinyl Bromide	U		0.0727	0.200
Vinyl acetate	U		0.0639	0.200
m&p-Xylene	U		0.0946	0.400
o-Xylene	U		0.0633	0.200
(S) 1,4-Bromofluorobenzene	*97.7*			*60.0-140*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280857-1 01/20/18 08:53 • (LCSD) R3280857-2 01/20/18 09:38

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Propene	3.75	3.92	3.94	105	105	54.0-155			0.509	25
Dichlorodifluoromethane	3.75	4.12	4.14	110	111	69.0-143			0.518	25
1,2-Dichlorotetrafluoroethane	3.75	4.00	4.02	107	107	70.0-130			0.489	25
Chloromethane	3.75	3.44	3.80	91.7	101	70.0-130			9.99	25
Vinyl chloride	3.75	3.68	3.81	98.3	101	70.0-130			3.22	25
1,3-Butadiene	3.75	3.67	3.74	98.0	99.7	70.0-130			1.75	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280857-1 01/20/18 08:53 • (LCSD) R3280857-2 01/20/18 09:38

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Bromomethane	3.75	4.38	4.48	117	120	70.0-130			2.40	25
Chloroethane	3.75	4.12	4.17	110	111	70.0-130			1.35	25
Trichlorofluoromethane	3.75	4.11	4.18	110	111	70.0-130			1.65	25
1,1,2-Trichlorotrifluoroethane	3.75	4.19	4.22	112	112	70.0-130			0.628	25
1,1-Dichloroethene	3.75	3.99	4.04	106	108	70.0-130			1.21	25
1,1-Dichloroethane	3.75	3.94	4.02	105	107	70.0-130			1.92	25
Acetone	3.75	3.79	3.95	101	105	70.0-130			4.04	25
2-Propanol	3.75	3.97	4.06	106	108	66.0-150			2.23	25
Carbon disulfide	3.75	4.02	4.07	107	109	70.0-130			1.44	25
Methylene Chloride	3.75	3.78	3.85	101	103	70.0-130			1.89	25
MTBE	3.75	4.02	4.07	107	109	70.0-130			1.32	25
trans-1,2-Dichloroethene	3.75	3.95	4.05	105	108	70.0-130			2.53	25
n-Hexane	3.75	3.97	4.03	106	107	70.0-130			1.41	25
Vinyl acetate	3.75	3.83	3.95	102	105	70.0-130			3.05	25
Methyl Ethyl Ketone	3.75	4.16	4.17	111	111	70.0-130			0.284	25
cis-1,2-Dichloroethene	3.75	3.99	4.05	107	108	70.0-130			1.52	25
Chloroform	3.75	3.97	4.01	106	107	70.0-130			0.965	25
Cyclohexane	3.75	4.07	4.13	108	110	70.0-130			1.59	25
1,1,1-Trichloroethane	3.75	4.02	4.04	107	108	70.0-130			0.430	25
Carbon tetrachloride	3.75	4.05	4.09	108	109	70.0-130			1.05	25
Benzene	3.75	4.05	4.07	108	108	70.0-130			0.469	25
1,2-Dichloroethane	3.75	3.87	3.93	103	105	70.0-130			1.42	25
Heptane	3.75	3.92	3.95	105	105	70.0-130			0.711	25
Trichloroethylene	3.75	4.05	4.04	108	108	70.0-130			0.273	25
1,2-Dichloropropane	3.75	3.92	4.10	104	109	70.0-130			4.48	25
1,4-Dioxane	3.75	4.06	4.28	108	114	70.0-152			5.10	25
Bromodichloromethane	3.75	4.00	4.02	107	107	70.0-130			0.440	25
cis-1,3-Dichloropropene	3.75	4.13	4.17	110	111	70.0-130			0.765	25
4-Methyl-2-pentanone (MIBK)	3.75	4.04	4.12	108	110	70.0-142			1.85	25
Toluene	3.75	4.13	4.17	110	111	70.0-130			0.947	25
trans-1,3-Dichloropropene	3.75	4.12	4.18	110	112	70.0-130			1.52	25
1,1,2-Trichloroethane	3.75	4.04	4.08	108	109	70.0-130			1.07	25
Tetrachloroethylene	3.75	4.16	4.18	111	111	70.0-130			0.512	25
Methyl Butyl Ketone	3.75	4.06	4.23	108	113	70.0-150			4.18	25
Dibromochloromethane	3.75	4.01	4.07	107	108	70.0-130			1.42	25
1,2-Dibromoethane	3.75	4.00	4.06	107	108	70.0-130			1.46	25
Chlorobenzene	3.75	3.95	3.99	105	106	70.0-130			1.04	25
Ethylbenzene	3.75	4.28	4.28	114	114	70.0-130			0.0360	25
m&p-Xylene	7.50	8.57	8.55	114	114	70.0-130			0.230	25
o-Xylene	3.75	4.31	4.30	115	115	70.0-130			0.280	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3280857-1 01/20/18 08:53 • (LCSD) R3280857-2 01/20/18 09:38

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Styrene	3.75	4.50	4.49	120	120	70.0-130			0.101	25
Bromoform	3.75	4.42	4.42	118	118	70.0-130			0.0596	25
1,1,2,2-Tetrachloroethane	3.75	4.20	4.23	112	113	70.0-130			0.687	25
4-Ethyltoluene	3.75	4.48	4.47	119	119	70.0-130			0.186	25
1,3,5-Trimethylbenzene	3.75	4.45	4.44	119	118	70.0-130			0.0860	25
1,2,4-Trimethylbenzene	3.75	4.45	4.43	119	118	70.0-130			0.327	25
1,3-Dichlorobenzene	3.75	4.54	4.53	121	121	70.0-130			0.166	25
1,4-Dichlorobenzene	3.75	4.63	4.63	124	124	70.0-130			0.0159	25
Benzyl Chloride	3.75	4.76	4.79	127	128	70.0-144			0.623	25
1,2-Dichlorobenzene	3.75	4.46	4.45	119	119	70.0-130			0.0555	25
1,2,4-Trichlorobenzene	3.75	4.55	4.59	121	122	70.0-155			0.869	25
Hexachloro-1,3-butadiene	3.75	4.62	4.65	123	124	70.0-145			0.717	25
Naphthalene	3.75	4.66	4.68	124	125	70.0-155			0.445	25
Allyl Chloride	3.75	3.97	4.06	106	108	70.0-130			2.19	25
2-Chlorotoluene	3.75	4.36	4.37	116	116	70.0-130			0.171	25
Methyl Methacrylate	3.75	3.97	4.03	106	107	70.0-130			1.63	25
Tetrahydrofuran	3.75	3.89	3.94	104	105	70.0-140			1.21	25
2,2,4-Trimethylpentane	3.75	4.04	4.08	108	109	70.0-130			1.04	25
Vinyl Bromide	3.75	4.15	4.22	111	112	70.0-130			1.49	25
Isopropylbenzene	3.75	4.34	4.32	116	115	70.0-130			0.511	25
(S) 1,4-Bromofluorobenzene				*101*	*101*	*60.0-140*				

Method Blank (MB)

(MB) R3281018-3 01/22/18 10:34

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Acetone	U		0.0569	1.25
Allyl Chloride	U		0.0546	0.200
Benzene	U		0.0460	0.200
Benzyl Chloride	U		0.0598	0.200
Bromodichloromethane	U		0.0436	0.200
Bromoform	U		0.0786	0.600
Bromomethane	U		0.0609	0.200
1,3-Butadiene	U		0.0563	2.00
Carbon disulfide	U		0.0544	0.200
Carbon tetrachloride	U		0.0585	0.200
Chlorobenzene	U		0.0601	0.200
Chloroethane	U		0.0489	0.200
Chloroform	U		0.0574	0.200
Chloromethane	U		0.0544	0.200
2-Chlorotoluene	U		0.0605	0.200
Cyclohexane	U		0.0534	0.200
Dibromochloromethane	U		0.0494	0.200
1,2-Dibromoethane	U		0.0185	0.200
1,2-Dichlorobenzene	U		0.0603	0.200
1,3-Dichlorobenzene	U		0.0597	0.200
1,4-Dichlorobenzene	U		0.0557	0.200
1,2-Dichloroethane	U		0.0616	0.200
1,1-Dichloroethane	U		0.0514	0.200
1,1-Dichloroethene	U		0.0490	0.200
cis-1,2-Dichloroethene	U		0.0389	0.200
trans-1,2-Dichloroethene	U		0.0464	0.200
1,2-Dichloropropane	U		0.0599	0.200
cis-1,3-Dichloropropene	U		0.0588	0.200
trans-1,3-Dichloropropene	U		0.0435	0.200
1,4-Dioxane	U		0.0554	0.200
Ethylbenzene	U		0.0506	0.200
4-Ethyltoluene	U		0.0666	0.200
Trichlorofluoromethane	U		0.0673	0.200
Dichlorodifluoromethane	U		0.0601	0.200
1,1,2-Trichlorotrifluoroethane	U		0.0687	0.200
1,2-Dichlorotetrafluoroethane	U		0.0458	0.200
Heptane	U		0.0626	0.200
Hexachloro-1,3-butadiene	U		0.0656	0.630
n-Hexane	U		0.0457	0.200
Isopropylbenzene	U		0.0563	0.200

Method Blank (MB)

(MB) R3281018-3 01/22/18 10:34

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Methylene Chloride	U		0.0465	0.200
Methyl Butyl Ketone	U		0.0682	1.25
2-Butanone (MEK)	U		0.0493	1.25
4-Methyl-2-pentanone (MIBK)	U		0.0650	1.25
Methyl Methacrylate	U		0.0773	0.200
MTBE	U		0.0505	0.200
Naphthalene	U		0.154	0.630
2-Propanol	U		0.0882	1.25
Propene	U		0.0932	0.400
Styrene	U		0.0465	0.200
1,1,2,2-Tetrachloroethane	U		0.0576	0.200
Tetrachloroethylene	U		0.0497	0.200
Tetrahydrofuran	U		0.0508	0.200
Toluene	U		0.0499	0.200
1,2,4-Trichlorobenzene	U		0.148	0.630
1,1,1-Trichloroethane	U		0.0665	0.200
1,1,2-Trichloroethane	U		0.0287	0.200
Trichloroethylene	U		0.0545	0.200
1,2,4-Trimethylbenzene	U		0.0483	0.200
1,3,5-Trimethylbenzene	U		0.0631	0.200
2,2,4-Trimethylpentane	U		0.0456	0.200
Vinyl chloride	U		0.0457	0.200
Vinyl Bromide	U		0.0727	0.200
Vinyl acetate	U		0.0639	0.200
m&p-Xylene	U		0.0946	0.400
o-Xylene	U		0.0633	0.200
Ethanol	U		0.0832	0.630
(S) 1,4-Bromofluorobenzene	*97.8*			*60.0-140*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281018-1 01/22/18 09:02 • (LCSD) R3281018-2 01/22/18 09:47

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Ethanol	3.75	3.66	3.67	97.6	97.9	52.0-158			0.345	25
Propene	3.75	4.14	4.16	110	111	54.0-155			0.505	25
Dichlorodifluoromethane	3.75	4.24	4.32	113	115	69.0-143			1.96	25
1,2-Dichlorotetrafluoroethane	3.75	4.15	4.23	111	113	70.0-130			1.95	25
Chloromethane	3.75	4.21	4.24	112	113	70.0-130			0.558	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281018-1 01/22/18 09:02 • (LCSD) R3281018-2 01/22/18 09:47

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Vinyl chloride	3.75	4.04	4.10	108	109	70.0-130			1.38	25
1,3-Butadiene	3.75	3.73	3.70	99.5	98.7	70.0-130			0.764	25
Bromomethane	3.75	4.54	4.60	121	123	70.0-130			1.40	25
Chloroethane	3.75	4.24	4.30	113	115	70.0-130			1.48	25
Trichlorofluoromethane	3.75	4.26	4.34	114	116	70.0-130			1.83	25
1,1,2-Trichlorotrifluoroethane	3.75	4.34	4.38	116	117	70.0-130			0.988	25
1,1-Dichloroethene	3.75	4.16	4.20	111	112	70.0-130			1.08	25
1,1-Dichloroethane	3.75	4.12	4.18	110	111	70.0-130			1.48	25
Acetone	3.75	4.09	4.07	109	109	70.0-130			0.365	25
2-Propanol	3.75	4.14	4.19	110	112	66.0-150			1.18	25
Carbon disulfide	3.75	4.19	4.25	112	113	70.0-130			1.38	25
Methylene Chloride	3.75	3.94	4.01	105	107	70.0-130			1.88	25
MTBE	3.75	4.15	4.22	111	112	70.0-130			1.53	25
trans-1,2-Dichloroethene	3.75	4.15	4.18	111	112	70.0-130			0.731	25
n-Hexane	3.75	4.10	4.16	109	111	70.0-130			1.33	25
Vinyl acetate	3.75	4.37	4.42	116	118	70.0-130			1.32	25
Methyl Ethyl Ketone	3.75	4.29	4.33	114	115	70.0-130			0.930	25
cis-1,2-Dichloroethene	3.75	4.13	4.20	110	112	70.0-130			1.58	25
Chloroform	3.75	4.10	4.15	109	111	70.0-130			1.20	25
Cyclohexane	3.75	4.19	4.27	112	114	70.0-130			1.90	25
1,1,1-Trichloroethane	3.75	4.16	4.22	111	113	70.0-130			1.48	25
Carbon tetrachloride	3.75	4.21	4.27	112	114	70.0-130			1.44	25
Benzene	3.75	4.13	4.19	110	112	70.0-130			1.58	25
1,2-Dichloroethane	3.75	4.03	4.08	107	109	70.0-130			1.34	25
Heptane	3.75	4.09	4.16	109	111	70.0-130			1.54	25
Trichloroethylene	3.75	4.13	4.20	110	112	70.0-130			1.66	25
1,2-Dichloropropane	3.75	4.06	4.24	108	113	70.0-130			4.38	25
1,4-Dioxane	3.75	4.38	4.42	117	118	70.0-152			1.11	25
Bromodichloromethane	3.75	4.13	4.19	110	112	70.0-130			1.53	25
cis-1,3-Dichloropropene	3.75	4.25	4.32	113	115	70.0-130			1.61	25
4-Methyl-2-pentanone (MIBK)	3.75	4.17	4.25	111	113	70.0-142			1.70	25
Toluene	3.75	4.23	4.30	113	115	70.0-130			1.55	25
trans-1,3-Dichloropropene	3.75	4.28	4.33	114	116	70.0-130			1.21	25
1,1,2-Trichloroethane	3.75	4.16	4.23	111	113	70.0-130			1.64	25
Tetrachloroethylene	3.75	4.30	4.34	115	116	70.0-130			1.06	25
Methyl Butyl Ketone	3.75	4.24	4.35	113	116	70.0-150			2.42	25
Dibromochloromethane	3.75	4.19	4.27	112	114	70.0-130			1.76	25
1,2-Dibromoethane	3.75	4.12	4.20	110	112	70.0-130			2.04	25
Chlorobenzene	3.75	4.04	4.12	108	110	70.0-130			1.96	25
Ethylbenzene	3.75	4.36	4.44	116	118	70.0-130			1.62	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281018-1 01/22/18 09:02 • (LCSD) R3281018-2 01/22/18 09:47

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
m&p-Xylene	7.50	8.72	8.86	116	118	70.0-130			1.51	25
o-Xylene	3.75	4.39	4.45	117	119	70.0-130			1.37	25
Styrene	3.75	4.62	4.70	123	125	70.0-130			1.63	25
Bromoform	3.75	4.62	4.70	123	125	70.0-130			1.76	25
1,1,2,2-Tetrachloroethane	3.75	4.32	4.35	115	116	70.0-130			0.802	25
4-Ethyltoluene	3.75	4.58	4.65	122	124	70.0-130			1.57	25
1,3,5-Trimethylbenzene	3.75	4.53	4.62	121	123	70.0-130			2.06	25
1,2,4-Trimethylbenzene	3.75	4.53	4.60	121	123	70.0-130			1.59	25
1,3-Dichlorobenzene	3.75	4.69	4.78	125	127	70.0-130			1.96	25
1,4-Dichlorobenzene	3.75	4.78	4.88	127	130	70.0-130			2.11	25
Benzyl Chloride	3.75	4.87	4.97	130	133	70.0-144			2.09	25
1,2-Dichlorobenzene	3.75	4.61	4.70	123	125	70.0-130			1.93	25
1,2,4-Trichlorobenzene	3.75	4.79	4.92	128	131	70.0-155			2.63	25
Hexachloro-1,3-butadiene	3.75	4.86	4.94	130	132	70.0-145			1.61	25
Naphthalene	3.75	4.86	5.01	130	134	70.0-155			3.13	25
Allyl Chloride	3.75	4.17	4.21	111	112	70.0-130			0.952	25
2-Chlorotoluene	3.75	4.46	4.53	119	121	70.0-130			1.58	25
Methyl Methacrylate	3.75	4.10	4.17	109	111	70.0-130			1.75	25
Tetrahydrofuran	3.75	4.03	4.09	108	109	70.0-140			1.39	25
2,2,4-Trimethylpentane	3.75	4.18	4.22	111	113	70.0-130			1.02	25
Vinyl Bromide	3.75	4.33	4.39	115	117	70.0-130			1.46	25
Isopropylbenzene	3.75	4.43	4.49	118	120	70.0-130			1.41	25
(S) 1,4-Bromofluorobenzene				*100*	*101*	*60.0-140*				

Method Blank (MB)

(MB) R3281017-2 01/22/18 10:16

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Acetone	U		0.0569	1.25
Allyl Chloride	U		0.0546	0.200
Benzene	U		0.0460	0.200
Benzyl Chloride	U		0.0598	0.200
Bromodichloromethane	U		0.0436	0.200
Bromoform	U		0.0786	0.600
Bromomethane	U		0.0609	0.200
1,3-Butadiene	U		0.0563	2.00
Carbon disulfide	U		0.0544	0.200
Carbon tetrachloride	U		0.0585	0.200
Chlorobenzene	U		0.0601	0.200
Chloroethane	U		0.0489	0.200
Chloroform	U		0.0574	0.200
Chloromethane	U		0.0544	0.200
2-Chlorotoluene	U		0.0605	0.200
Cyclohexane	U		0.0534	0.200
Dibromochloromethane	U		0.0494	0.200
1,2-Dibromoethane	U		0.0185	0.200
1,2-Dichlorobenzene	U		0.0603	0.200
1,3-Dichlorobenzene	U		0.0597	0.200
1,4-Dichlorobenzene	U		0.0557	0.200
1,2-Dichloroethane	U		0.0616	0.200
1,1-Dichloroethane	U		0.0514	0.200
1,1-Dichloroethene	U		0.0490	0.200
cis-1,2-Dichloroethene	U		0.0389	0.200
trans-1,2-Dichloroethene	U		0.0464	0.200
1,2-Dichloropropane	U		0.0599	0.200
cis-1,3-Dichloropropene	U		0.0588	0.200
trans-1,3-Dichloropropene	U		0.0435	0.200
1,4-Dioxane	U		0.0554	0.200
Ethylbenzene	U		0.0506	0.200
4-Ethyltoluene	U		0.0666	0.200
Trichlorofluoromethane	U		0.0673	0.200
Dichlorodifluoromethane	U		0.0601	0.200
1,1,2-Trichlorotrifluoroethane	U		0.0687	0.200
1,2-Dichlorotetrafluoroethane	U		0.0458	0.200
Heptane	U		0.0626	0.200
Hexachloro-1,3-butadiene	U		0.0656	0.630
n-Hexane	U		0.0457	0.200
Isopropylbenzene	U		0.0563	0.200

Method Blank (MB)

(MB) R3281017-2 01/22/18 10:16

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Methylene Chloride	U		0.0465	0.200
Methyl Butyl Ketone	U		0.0682	1.25
2-Butanone (MEK)	U		0.0493	1.25
4-Methyl-2-pentanone (MIBK)	U		0.0650	1.25
Methyl Methacrylate	U		0.0773	0.200
MTBE	U		0.0505	0.200
Naphthalene	U		0.154	0.630
2-Propanol	0.0973	J	0.0882	1.25
Propene	U		0.0932	0.400
Styrene	U		0.0465	0.200
1,1,2,2-Tetrachloroethane	U		0.0576	0.200
Tetrachloroethylene	U		0.0497	0.200
Tetrahydrofuran	U		0.0508	0.200
Toluene	U		0.0499	0.200
1,2,4-Trichlorobenzene	U		0.148	0.630
1,1,1-Trichloroethane	U		0.0665	0.200
1,1,2-Trichloroethane	U		0.0287	0.200
Trichloroethylene	U		0.0545	0.200
1,2,4-Trimethylbenzene	U		0.0483	0.200
1,3,5-Trimethylbenzene	U		0.0631	0.200
2,2,4-Trimethylpentane	U		0.0456	0.200
Vinyl chloride	U		0.0457	0.200
Vinyl Bromide	U		0.0727	0.200
Vinyl acetate	U		0.0639	0.200
m&p-Xylene	U		0.0946	0.400
o-Xylene	U		0.0633	0.200
Ethanol	U		0.0832	0.630
(S) 1,4-Bromofluorobenzene	*96.1*			*60.0-140*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281017-1 01/22/18 09:34 • (LCSD) R3281017-3 01/22/18 11:14

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Ethanol	3.75	3.90	3.87	104	103	52.0-158			0.739	25
Propene	3.75	3.72	3.61	99.2	96.2	54.0-155			3.06	25
Dichlorodifluoromethane	3.75	4.45	4.11	119	110	69.0-143			7.79	25
1,2-Dichlorotetrafluoroethane	3.75	4.24	4.17	113	111	70.0-130			1.74	25
Chloromethane	3.75	3.87	3.82	103	102	70.0-130			1.17	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281017-1 01/22/18 09:34 • (LCSD) R3281017-3 01/22/18 11:14

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Vinyl chloride	3.75	3.97	3.98	106	106	70.0-130			0.112	25
1,3-Butadiene	3.75	3.86	3.74	103	99.8	70.0-130			2.97	25
Bromomethane	3.75	4.05	4.55	108	121	70.0-130			11.7	25
Chloroethane	3.75	3.74	4.40	99.7	117	70.0-130			16.2	25
Trichlorofluoromethane	3.75	4.10	4.28	109	114	70.0-130			4.42	25
1,1,2-Trichlorotrifluoroethane	3.75	4.21	4.21	112	112	70.0-130			0.0109	25
1,1-Dichloroethene	3.75	4.00	3.93	107	105	70.0-130			1.77	25
1,1-Dichloroethane	3.75	3.92	3.91	105	104	70.0-130			0.254	25
Acetone	3.75	3.80	3.77	101	100	70.0-130			0.900	25
2-Propanol	3.75	3.81	3.77	101	100	66.0-150			1.03	25
Carbon disulfide	3.75	4.05	4.01	108	107	70.0-130			0.991	25
Methylene Chloride	3.75	3.71	3.65	99.0	97.2	70.0-130			1.77	25
MTBE	3.75	4.03	4.01	107	107	70.0-130			0.468	25
trans-1,2-Dichloroethene	3.75	3.96	3.94	106	105	70.0-130			0.376	25
n-Hexane	3.75	4.03	4.05	107	108	70.0-130			0.504	25
Vinyl acetate	3.75	3.89	3.82	104	102	70.0-130			1.95	25
Methyl Ethyl Ketone	3.75	4.04	4.07	108	109	70.0-130			0.830	25
cis-1,2-Dichloroethene	3.75	4.10	4.10	109	109	70.0-130			0.103	25
Chloroform	3.75	4.04	4.06	108	108	70.0-130			0.511	25
Cyclohexane	3.75	4.18	4.14	112	110	70.0-130			1.05	25
1,1,1-Trichloroethane	3.75	4.15	4.18	111	112	70.0-130			0.711	25
Carbon tetrachloride	3.75	4.16	4.21	111	112	70.0-130			1.17	25
Benzene	3.75	4.11	4.10	110	109	70.0-130			0.144	25
1,2-Dichloroethane	3.75	4.02	4.00	107	107	70.0-130			0.341	25
Heptane	3.75	4.00	3.96	107	105	70.0-130			1.12	25
Trichloroethylene	3.75	4.18	4.20	111	112	70.0-130			0.606	25
1,2-Dichloropropane	3.75	4.03	4.07	108	109	70.0-130			0.927	25
1,4-Dioxane	3.75	4.21	4.18	112	112	70.0-152			0.560	25
Bromodichloromethane	3.75	4.11	4.19	110	112	70.0-130			1.85	25
cis-1,3-Dichloropropene	3.75	4.14	4.12	110	110	70.0-130			0.527	25
4-Methyl-2-pentanone (MIBK)	3.75	3.88	3.80	103	101	70.0-142			2.01	25
Toluene	3.75	4.32	4.34	115	116	70.0-130			0.613	25
trans-1,3-Dichloropropene	3.75	4.15	4.21	111	112	70.0-130			1.30	25
1,1,2-Trichloroethane	3.75	4.25	4.25	113	113	70.0-130			0.0724	25
Tetrachloroethylene	3.75	4.45	4.53	119	121	70.0-130			1.93	25
Methyl Butyl Ketone	3.75	4.05	3.94	108	105	70.0-150			2.56	25
Dibromochloromethane	3.75	4.40	4.43	117	118	70.0-130			0.740	25
1,2-Dibromoethane	3.75	4.33	4.37	116	117	70.0-130			0.895	25
Chlorobenzene	3.75	4.42	4.39	118	117	70.0-130			0.671	25
Ethylbenzene	3.75	4.41	4.47	117	119	70.0-130			1.38	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281017-1 01/22/18 09:34 • (LCSD) R3281017-3 01/22/18 11:14

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
m&p-Xylene	7.50	8.93	9.03	119	120	70.0-130			1.07	25
o-Xylene	3.75	4.38	4.50	117	120	70.0-130			2.59	25
Styrene	3.75	4.59	4.67	122	124	70.0-130			1.73	25
Bromoform	3.75	4.58	4.66	122	124	70.0-130			1.86	25
1,1,2,2-Tetrachloroethane	3.75	4.24	4.34	113	116	70.0-130			2.31	25
4-Ethyltoluene	3.75	4.50	4.58	120	122	70.0-130			1.67	25
1,3,5-Trimethylbenzene	3.75	4.43	4.50	118	120	70.0-130			1.46	25
1,2,4-Trimethylbenzene	3.75	4.39	4.54	117	121	70.0-130			3.43	25
1,3-Dichlorobenzene	3.75	4.53	4.67	121	124	70.0-130			2.87	25
1,4-Dichlorobenzene	3.75	4.60	4.81	123	128	70.0-130			4.46	25
Benzyl Chloride	3.75	4.39	4.55	117	121	70.0-144			3.58	25
1,2-Dichlorobenzene	3.75	4.50	4.65	120	124	70.0-130			3.35	25
1,2,4-Trichlorobenzene	3.75	4.75	5.01	127	134	70.0-155			5.42	25
Hexachloro-1,3-butadiene	3.75	4.62	4.93	123	132	70.0-145			6.59	25
Naphthalene	3.75	4.72	4.92	126	131	70.0-155			4.18	25
Allyl Chloride	3.75	3.72	3.73	99.3	99.3	70.0-130			0.0352	25
2-Chlorotoluene	3.75	4.57	4.60	122	123	70.0-130			0.649	25
Methyl Methacrylate	3.75	4.21	4.13	112	110	70.0-130			1.96	25
Tetrahydrofuran	3.75	3.75	3.71	100	99.0	70.0-140			0.926	25
2,2,4-Trimethylpentane	3.75	4.17	4.10	111	109	70.0-130			1.64	25
Vinyl Bromide	3.75	3.98	4.54	106	121	70.0-130			13.3	25
Isopropylbenzene	3.75	4.48	4.56	119	121	70.0-130			1.65	25
(S) 1,4-Bromofluorobenzene				*97.7*	*98.0*	*60.0-140*				

Method Blank (MB)

(MB) R3281374-3 01/23/18 09:54

Analyte	MB Result ppbv	MB Qualifier	MB MDL ppbv	MB RDL ppbv
Benzyl Chloride	U		0.0598	0.200
Bromoform	U		0.0786	0.600
2-Chlorotoluene	U		0.0605	0.200
1,2-Dichlorobenzene	U		0.0603	0.200
1,3-Dichlorobenzene	U		0.0597	0.200
1,4-Dichlorobenzene	U		0.0557	0.200
Ethylbenzene	U		0.0506	0.200
4-Ethyltoluene	U		0.0666	0.200
Hexachloro-1,3-butadiene	U		0.0656	0.630
Isopropylbenzene	U		0.0563	0.200
Naphthalene	U		0.154	0.630
Styrene	U		0.0465	0.200
1,1,2,2-Tetrachloroethane	U		0.0576	0.200
1,2,4-Trichlorobenzene	U		0.148	0.630
1,2,4-Trimethylbenzene	U		0.0483	0.200
1,3,5-Trimethylbenzene	U		0.0631	0.200
m&p-Xylene	U		0.0946	0.400
o-Xylene	U		0.0633	0.200
(S) 1,4-Bromofluorobenzene	*95.9*			*60.0-140*

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281374-1 01/23/18 08:32 • (LCSD) R3281374-2 01/23/18 09:13

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Ethylbenzene	3.75	4.59	4.54	122	121	70.0-130			1.03	25
m&p-Xylene	7.50	9.38	9.19	125	122	70.0-130			2.05	25
o-Xylene	3.75	4.67	4.56	125	122	70.0-130			2.38	25
Styrene	3.75	4.79	4.72	128	126	70.0-130			1.29	25
Bromoform	3.75	4.78	4.70	128	125	70.0-130			1.75	25
1,1,2,2-Tetrachloroethane	3.75	4.45	4.40	119	117	70.0-130			1.18	25
4-Ethyltoluene	3.75	4.73	4.64	126	124	70.0-130			1.89	25
1,3,5-Trimethylbenzene	3.75	4.72	4.60	126	123	70.0-130			2.54	25
1,2,4-Trimethylbenzene	3.75	4.71	4.57	126	122	70.0-130			3.18	25
1,3-Dichlorobenzene	3.75	4.81	4.70	128	125	70.0-130			2.34	25
1,4-Dichlorobenzene	3.75	4.91	4.81	131	128	70.0-130	J4		2.09	25
Benzyl Chloride	3.75	4.73	4.59	126	122	70.0-144			3.01	25
1,2-Dichlorobenzene	3.75	4.78	4.68	127	125	70.0-130			2.04	25
1,2,4-Trichlorobenzene	3.75	5.05	4.96	135	132	70.0-155			1.69	25

Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3281374-1 01/23/18 08:32 • (LCSD) R3281374-2 01/23/18 09:13

Analyte	Spike Amount ppbv	LCS Result ppbv	LCSD Result ppbv	LCS Rec. %	LCSD Rec. %	Rec. Limits %	LCS Qualifier	LCSD Qualifier	RPD %	RPD Limits %
Hexachloro-1,3-butadiene	3.75	4.93	4.83	132	129	70.0-145			2.11	25
Naphthalene	3.75	4.98	4.90	133	131	70.0-155			1.54	25
2-Chlorotoluene	3.75	4.83	4.70	129	125	70.0-130			2.58	25
Isopropylbenzene	3.75	4.71	4.63	126	124	70.0-130			1.61	25
(S) 1,4-Bromofluorobenzene				*99.5*	*99.6*	*60.0-140*				

Guide to Reading and Understanding Your Laboratory Report

The information below is designed to better explain the various terms used in your report of analytical results from the Laboratory. This is not intended as a comprehensive explanation, and if you have additional questions please contact your project representative.

Abbreviations and Definitions

MDL	Method Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
RDL	Reported Detection Limit.
Rec.	Recovery.
RPD	Relative Percent Difference.
SDG	Sample Delivery Group.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
U	Not detected at the Reporting Limit (or MDL where applicable).
Analyte	The name of the particular compound or analysis performed. Some Analyses and Methods will have multiple analytes reported.
Dilution	If the sample matrix contains an interfering material, or if concentrations of analytes in the sample are higher than the highest limit of concentration that the laboratory can accurately report, the sample may be diluted for analysis. If a value different than 1 is used in this field, the result reported has already been corrected for this factor.
Limits	These are the target % recovery ranges or % difference value that the laboratory has historically determined as normal for the method and analyte being reported. Successful QC Sample analysis will target all analytes recovered or duplicated within these ranges.
Qualifier	This column provides a letter and/or number designation that corresponds to additional information concerning the result reported. If a Qualifier is present, a definition per Qualifier is provided within the Glossary and Definitions page and potentially a discussion of possible implications of the Qualifier in the Case Narrative if applicable.
Result	The actual analytical final result (corrected for any sample specific characteristics) reported for your sample. If there was no measurable result returned for a specific analyte, the result in this column may state “ND” (Not Detected) or “BDL” (Below Detectable Levels). The information in the results column should always be accompanied by either an MDL (Method Detection Limit) or RDL (Reporting Detection Limit) that defines the lowest value that the laboratory could detect or report for this analyte.
Case Narrative (Cn)	A brief discussion about the included sample results, including a discussion of any non-conformances to protocol observed either at sample receipt by the laboratory from the field or during the analytical process. If present, there will be a section in the Case Narrative to discuss the meaning of any data qualifiers used in the report.
Quality Control Summary (Qc)	This section of the report includes the results of the laboratory quality control analyses required by procedure or analytical methods to assist in evaluating the validity of the results reported for your samples. These analyses are not being performed on your samples typically, but on laboratory generated material.
Sample Chain of Custody (Sc)	This is the document created in the field when your samples were initially collected. This is used to verify the time and date of collection, the person collecting the samples, and the analyses that the laboratory is requested to perform. This chain of custody also documents all persons (excluding commercial shippers) that have had control or possession of the samples from the time of collection until delivery to the laboratory for analysis.
Sample Results (Sr)	This section of your report will provide the results of all testing performed on your samples. These results are provided by sample ID and are separated by the analyses performed on each sample. The header line of each analysis section for each sample will provide the name and method number for the analysis reported.
Sample Summary (Ss)	This section of the Analytical Report defines the specific analyses performed for each sample ID, including the dates and times of preparation and/or analysis.

Qualifier	Description
J	The identification of the analyte is acceptable; the reported value is an estimate.
J1	Surrogate recovery limits have been exceeded; values are outside upper control limits.
J4	The associated batch QC was outside the established quality control range for accuracy.

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our one location design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be YOUR LAB OF CHOICE.
* Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey–NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Connecticut	PH-0197	North Carolina [1]	DW21704
Florida	E87487	North Carolina [2]	41
Georgia	NELAP	North Dakota	R-140
Georgia [1]	923	Ohio–VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
Iowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky [1]	90010	South Dakota	n/a
Kentucky [2]	16	Tennessee [1 4]	2006
Louisiana	AI30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas [5]	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		


Third Party Federal Accreditations

A2LA – ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA – ISO 17025 [5]	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
EPA–Crypto	TN00003		

[1] Drinking Water [2] Underground Storage Tanks [3] Aquatic Toxicity [4] Chemical/Microbiological [5] Mold n/a Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. ESC Lab Sciences performs all testing at our central laboratory.



GAIA Tech - Chicago, IL

135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Billing Information:
Accounts Payable and PM
135 S. LaSalle St, Ste 3500
Chicago, IL 60603

Pres Chk

Report to: Larry Bertsch

Email To: larry.bertsch@rpsgroup.com

Project Description: Melville, NY

City/State Collected:

Phone: 312-541-4200
Fax: 312-541-0340

Client Project # 16785542000

Lab Project # GAICIL-MELVILLE

Collected by (print): Larry Bertsch

Site/Facility ID # NY

P.O. #

Collected by (signature):

Immediately Packed on Ice N ___ Y A

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day

Quote #

Date Results Needed

Analysis / Container / Preservative

Chain of Custody Page ___ of ___

ESC LABORATORY SCIENCES
a subsidiary of Pace Analytical
12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# 564491
M190

Acctnum: GAIACIL
Template: T131605
Prelogin: P635243
TSR: 104 - Jason Romer
PB: 1-12-18 CM

Shipped Via: FedEX Ground

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	Metals (Lab Filter) 250mlHDPE-NoPres	PAHSIMLVID 40mlAmb-NoPres-WT	RCRA8 Metals 2ozClr-NoPres	SV8270PAHSIMD,TS 4ozClr-NoPres	TO-15 Summa	V8260C 2ozClr-NoPres	V8260C 40ml/NaHSO4/Syr/MeOH	V8260C 40mlAmb-HCl	V8260C 40mlAmb-HCl-Blk	Remarks	Sample # (lab only)
SS-1 (sub-slab)	Grab	Air	—	1/18/18	1549-1619	1					X						01
SS-2	"	Air	—	1/18/18	1658-1728	1					X						-08
SS-3	"	Air	—	1/19/18	802-832	1					X						03
SS-4	"	Air	—	↓	1013-1044	1					X						04
SS-5	"	Air	—	↓	1924-1954	1					X						05
SG-1 (soil gas)	Grab	Air	5'	1/18/18	1437-1507	1					X						06
SG-2	"	Air	—	1/19/18	1137-1211	1					X						07
SG-3	"	Air	—	↓	1254-1324	1					~~X~~					HOLD	

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other_____

Remarks:

pH _____ Temp _____
Flow _____ Other _____

Samples returned via:
__ UPS ✓ FedEx __ Courier __ _____

Tracking # 4442 5232 3856

Sample Receipt Checklist
COC Seal Present/Intact: __NP __Y __N
COC Signed/Accurate: __Y __N
Bottles arrive intact: __Y __N
Correct bottles used: __Y __N
Sufficient volume sent: __Y __N
If Applicable
VOA Zero Headspace: __Y __N
Preservation Correct/Checked: __Y __N

	Date:	Time:			
Relinquished by : (Signature)	1/19/18	1730	Received by: (Signature)	Trip Blank Received: Yes / No HCL / MeoH TBR	
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Temp: AMB °C Bottles Received: 8	If preservation required by Login: Date/Time
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1/20/18 Time: 845	Hold: Condition: NCF / OK

RPS

135 S LaSalle Street, Suite 3500, Chicago, Illinois 60603
T 312 541 4200 W rpsgroup.com/usa

Privileged and Confidential

May 22, 2018

Mr. Robert F. Lawrence
Orrick, Herrington & Sutcliffe LLP
Columbia Center
1152 15th Street, N.W.
Washington, D.C. 20005-1706

RE: Summary of Environmental Conditions
Newsday Media Group Facility
235 Pinelawn Road
Melville, New York 11747

Dear Mr. Lawrence:

Tribune Media Company (Tribune) retained GaiaTech Incorporated (dba RPS) to conduct environmental studies at its Newsday facility located at 235 Pinelawn Road in Melville, New York (the Site). This work included a Phase I Environmental Site Assessment (Phase I ESA) and a limited Phase II Environmental Site Assessment (Phase II). The following is an overview of environmental conditions at the Site.

Phase I Environmental Site Assessment – Summary of Findings

The Phase I ESA was completed at the Site in July 2017 in preparation for the sale of the Site. The Phase I ESA identified two Recognized Environmental Conditions (RECs) and one Controlled RECs (CRECs). The first REC RPS identified in the ESA related to historical facility operations, which included the use of inks, oils, solvents (including chlorinated solvents), generation of hazardous waste and wastewater treatment operations. The second REC was identified as an open release incident for the release of 4-gallons of compressor oil to the concrete floor and in-plant containment system. The CREC related to several recently closed underground storage tank (UST) systems. In addition to the REC findings, RPS identified concerns related to prior spill events on or near the Site that have been "closed" by relevant regulatory authorities. Refer to RPS's Phase I ESA report dated January 2017 for additional Information regarding the findings of the Phase I assessment.

Based on the REC and CREC findings, and other concerns identified in the Phase I, Tribune engaged RPS to conduct additional investigations with respect to the potential concerns associated with the RECs, CREC and historical spills and releases.

To further evaluate potential residual impacts associated with the items identified in the Phase I ESA and to confirm the closure of selected releases, RPS completed a Phase II ESA at the Site.

Phase II Environmental Site Assessment – Summary of Findings

The Phase II ESA included collection of soil samples from six borings, collection of groundwater from two borings/temporary wells, and collection of seven soil-vapor samples. Groundwater was encountered in two of the six borings. [1]

Field screening of soil samples did not identify any evidence of staining, odors or volatile emissions (measured using a photoionization detector). Since indications of soil impacts were not encountered throughout the entire depth of the soil boring, a representative soil sample was collected from each boring for confirmatory analysis.

Each soil and groundwater sample was analyzed for volatile organic compounds (VOCs), polynuclear aromatic hydrocarbons (PAHs), and Resource Conservation and Recovery Act (RCRA) metals[2]. The soil-vapor samples were analyzed for VOCs. The sample locations are shown in the attached figure.

The results of the soil analysis were compared to New York State Department of Environmental Conservation (NYDEC) Soil Cleanup Objectives (SCOs) for unrestricted (residential) use, restricted (generally considered commercial and industrial) use and for the protection of groundwater and ecological resources. VOCs, PAHs and/or total RCRA metals were not detected in any of the soil samples at concentrations exceeding the most restrictive of the SCOs.

The results of groundwater analysis were compared to NYDEC Ambient Water Quality Standards and Guidance Values (WQS). The two groundwater samples did not contain VOCs or dissolved RCRA metals at concentrations exceeding WQSs. The groundwater analysis detected one PAH compound, benzo(b)fluoranthene (BbF), at concentrations that slightly exceed GQS as summarized below:

Compound	Concentrations in micrograms per Liter			
	GP-4	GP-6	Lab Method Blank	GQS
benzo(b)fluoranthene	0.00424	0.00255	0.00294	0.002

[1] Groundwater was encountered in two borings (GP-4 and GP-6), at depths of 42 and 52 feet below ground surface (bgs), respectively. Probe refusal was encountered in four borings at depths less than 26 feet bgs.
[2] Arsenic, Barium, Cadmium, Chromium, Lead, Mercury, Selenium and Silver

Due to the presence of BbF in the laboratory method blank, pursuant to the National Functional Guidelines for Organic Data Review, this data should be qualified as non-detect at the noted concentrations. The presence of BbF in the laboratory method blank at concentrations similar to those in the groundwater samples indicates that the BbF detections are due to laboratory contamination/error and are not present in Site groundwater.

Results of Soil-Vapor Analysis

In October 2006, the New York State Department of Health (NYSDOH) issued the Guidance for Evaluation of Soil Vapor Intrusion in New York State (as updated through May 2017). This guidance establishes a recommended action levels for sub slab vapor and indoor air concentrations of eight selected chlorinated solvents. One sub slab vapor sample contained carbon tetrachloride (CT) at a concentration slightly above the sub slab guidance contained in Matrix A of the NYSDOH guidance. There are no records that indicate that the facility historically utilized CT in routine operations. Soil and groundwater samples did not contain CT. As a result, the CT detection is considered an isolated occurrence and not indicative of widespread impacts.

For constituents that were not part of the NYSDOH guidance, RPS compared the results of the soil-vapor analysis to the US EPA Office of Solid Waste and Emergency Response (OSWER) shallow soil-gas vapor intrusion guidance values (OSWER values). Analysis of sub-slab vapor samples collected inside the building (SS-1 through SS-5) did not detect VOCs at concentrations exceeding OSWER values.

Analysis of soil-gas (vapor) samples collected from outdoor areas (SG-1 and SG-2) did not detect VOCs at concentrations exceeding OSWER values, except for two VOCs that slightly exceeded the OWSER values in one sample. These VOCs were not detected in any of the other site soil or groundwater samples collected at the Site. As a result, these detections are considered an isolated occurrence and not indicative of widespread impacts. Refer to RPS's report dated July 2017 for additional Information regarding the results of the Phase II subsurface assessment.

OPEN SPILL REPORT

Subsequent to the Phase I, RPS initiated closure activities associated with the open spill incident REC. These activities included a reinspection of the spill area by the NYSDEC. Based on the remedial activities completed by the facility and the reinspection of the spill area, on November 9, 2017, NYSDEC closed the spill incident.

SUMMARY AND CONCLUSIONS

The Phase II investigation did not identify impacts in Site soil and groundwater at concentrations above the NYSDEC's most restrictive environmental screening levels. Selected constituents were identified in soil vapor that exceeded certain environmental screening criteria. These data were not consistent across the Site and none of these constituents were detected in site soil or groundwater. The data therefore do not appear to represent significant site contamination conditions that require further investigation or remediation.

Based on the Phase II results, the conditions identified in the Phase I ESA have been addressed and/or adequately characterized, and additional assessment or mitigation is not required. Prior to the closing of any transfer of the Site to a new owner, we recommend that the Phase I ESA be updated and/or performed again, in order to meet the 6-month validity criteria generally applicable to Phase I ESAs.

If you have any questions or require further information, please feel free to contact us.

Sincerely,
RPS Group

Steven D. Kline, PE
President – Environmental Risk Group

Stephen G. Torres, P.G.
Director, Site Investigation and Remediation

cc: Matthew Weisberg - Tribune Real Estate Holdings, LLC
Rita DeBoer - Tribune Media

Enclosure – Site Plan Showing Sample Locations

RPS

Privileged and Confidential

Asbestos-Containing Material Survey

Newsday

235 Pinelawn Road | Melville, New York 11747

June 2018 | RPS Project No. 169142.540.00



Energy | Environmental Risk | Infrastructure | Ocean Science

TABLE OF CONTENTS

EXECUTIVE SUMMARY ..... **i**

1.0 INTRODUCTION **1**

1.1 Purpose 1

1.2 Scope of Work 1

1.3 Sampling Protocol 2

1.4 Laboratory Analysis 2

1.5 Special Terms and Conditions 4

1.6 Limitations and Exceptions of Survey 4

2.0 SITE DESCRIPTION **5**

2.1 Site Location and Description 5

2.2 Building Description 5

2.3 Prior Environmental Documentation 5

3.0 RESULTS **6**

3.1 Survey Methods and Results 6

3.2 Inspector Comments 23

4.0 FINDINGS AND CONCLUSIONS **24**

5.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS **26**

List of Attachments

Tables
Sample Collection Summary Table

Figures
Figure 1: Sample Location Map
Figure 2: Confirmed ACM Location Map

Appendices
Appendix A: Laboratory Chain of Custody and Analytical Report
Appendix B: Photographic Documentation
Appendix C: Certifications

EXECUTIVE SUMMARY

Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. (Client) retained RPS to conduct a limited Asbestos-Containing Material Survey (ACM Survey) of the Newsday facility located at 235 Pinelawn Road in Melville, Suffolk County, New York (the site).

RPS performed this ACM Survey as described in the authorized Agreement between the Client and RPS dated March 29, 2018 and in general accordance with applicable sections of ASTM E 2356-10 "*Standard Practice for Comprehensive Building Asbestos Surveys",* as it relates to a commercial real estate transaction.

The ACM Survey was conducted to categorize the different homogeneous materials within the interior of the Newsday facility's production and office structure, to assess the condition of suspect asbestos-containing materials (ACMs), to develop and implement an asbestos sampling plan, and identify or negate the presence of asbestos through laboratory analysis.

The site is owned by Tribune ND, Inc. (successor-in-interest to Tribune Company). Newsday leases the site from Tribune ND, Inc. Newsday operates a newspaper publishing and distribution company producing approximately 350,000 newspapers per day. Operations consist of the printing, plate development, digital photographic development, ink mixing, and newspaper sorting, bundling, and distribution.

The approximately 50-acre site is developed with an approximately 539,000-square-foot production building, which is divided between an office area and production areas, and a wastewater treatment plant. The production areas contain a packaging and bundling area, a reel room (where paper reels are fed to the printing lines), two levels of printing presses (including the printing presses, photo developing lines, and plate developing lines discussed above), boiler rooms, emergency generator rooms, a cooling tower room, various chemical storage areas, mechanical rooms, electrical rooms, maintenance shops, and a paper reel storage warehouse.

The survey of the structure's interior was conducted on April 18-21, 2018 by Mr. Aaron Paik, New York State Department of Labor (NYSDOL) Certified Asbestos Inspector (12-04000). RPS collected a total of 238 bulk samples of suspect ACMs from 65 homogeneous materials at the Newsday facility. In consultation with the Client, 50 samples from the 238 collected were withheld from analysis, resulting in a total of 188 samples submitted. All samples withheld represented extraneous samples collected in excess of regulatory requirements. No homogenous material identified during the survey was excluded from analysis by the omission of the withheld samples. In addition, it is important to note that additional material layers (i.e. mastics/glues/adhesives/layers) associated with the 188 bulk samples submitted were also analyzed where applicable.

Asbestos includes chrysotile, amosite, crocidolite, anthophyllite, tremolite and actinolite (fibrous minerals). The analytical report relates only to the samples tested. Samples were analyzed using polarized light microscopy (PLM) and transmission electron microscopy (TEM) via New York State Environmental Laboratory Approval Program (NYS ELAP) methods for bulk asbestos materials 198.1, 198.4 and 198.6. In addition, where vermiculite was noted in spray-applied

coatings and surfacing materials, further analysis by NYS ELAP method 198.8 was utilized. The reliable limit of detection of these methods is one percent (1%) asbestos content. If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*. When no asbestos is detected in the sample submitted, the results are reported as *None Detected.* If a sample contains greater than 1% asbestos, it is considered to be ACM by United States Environmental Protection Agency-National Emissions Standards for Hazardous Air Pollutants (EPA-NESHAPs), the United States Occupational Safety and Health Administration (OSHA), New York State Department of Health (NYSDOH), and NYSDOL.

The following building materials were identified as containing greater than 1% asbestos; therefore, they are required to be treated as regulated ACMs:

NEWSDAY – MELVILLE, NY – SUMMARY OF CONFIRMED ACMS					
Sample Number(s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
25, 26	12"x12" black w/multi-color streaks + assoc. adhesive - Mastic	1st Fl. Below raised floor @ ramp outside IDF	2.30% Chrysotile	Not friable/good condition	30 SF
28, 29	Black mastic to 12"x12" mottled red VFT	1st Fl. Cafeteria – closet	1.90% Chrysotile	Not friable/good condition	25 SF

IDF = Intermediate Distribution Frame (IT/Server Room)
SF = Square Feet
VFT = Vinyl Floor Tile
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected.*
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.

The following building materials were identified as containing less than 1% or trace amounts of asbestos; therefore, certain work practice requirements and prohibitions of the OSHA Asbestos in Construction Standard (29 CFR 1926.1101) must be followed:

NEWSDAY – MELVILLE, NY – SUMMARY OF <1% (TRACE) AMOUNTS OF ASBESTOS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
73, 74	Black mastic to 12"x12" mottled brown VFT	Throughout	<1% Chrysotile	Not friable/good condition	15,000 SF
209-217	Tan spray-on fireproofing (SF-2)	Throughout; west portion of structure (c. 1986-1989 construction), containing portions of reel room, production floor and west penthouse MER**	0.016% Amphibole/ Trace	Friable/good condition	45,000 SF

NEWSDAY – MELVILLE, NY – SUMMARY OF <1% (TRACE) AMOUNTS OF ASBESTOS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
218-226	Tan spray-on fireproofing (SF-3)	Throughout; south portion of structure (unknown construction date), containing portions of the collating/receiving floor, south office wing, and basement mechanical spaces **	0.055% Amphibole/ Trace	Friable/good condition	37,500 SF

SF = Square Feet
VFT = Vinyl Floor Tile
MER = Mechanical Equipment Room
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.
** In the execution of the survey, homogenous types were identified on the basis of appearance, color and texture in accordance with applicable regulations and industry standards. In assessing spray-on fireproofing, information provided by Newsday staff with regards to construction history was further utilized to subdivide the "Tan spray-on fireproofing" into sub-types (SF1 through SF3).

Vermiculite was detected in the initial analysis of some of the spray-on fireproofing (SFP) samples collected at the site. In consultation with the Client, representative samples were selected from the homogenous materials identified as containing vermiculite, and re-analyzed in accordance with the New York State Department of Health Environmental Laboratory Accreditation Program (NYSDOH ELAP) requirements. A total of ten (10) samples from the four (4) homogenous types/sub-types of spray-on fireproofing identified as containing vermiculite were submitted for further analysis via method 198.8. Reanalysis indicated that three (3) samples contained trace amounts of asbestos (<1%).

In accordance with the Agreement and the Client's instructions, this ACM Survey focused on accessible interior building systems and components within the production/office structure with the potential to contain asbestos, and did not include the assessment or sampling of any suspect exterior building materials or systems, including (but not limited to) roofing and all other suspect ACMs on the roof level. WJE Engineers and Architects separately contracted with the Client to obtain roof core samples and submit them for laboratory analysis. The laboratory analysis data associated with these roof samples has been provided to RPS and is presented alongside RPS's findings in the body of this report. The data provided by WJE Engineers and Architects was not obtained through conventional protocols, and cannot be relied upon in connection with renovation and demolition, because an insufficient number of samples were collected to characterize the roofing system. These samples were non-detect for ACM, but roofing and other exterior materials may require additional sampling to confirm the non-detect finding prior to renovation or demolition involving exterior materials.

It is possible that additional suspect or assumed ACMs may be present within inaccessible areas of the building, such as above fixed ceilings, within wall systems, behind walls, beneath layers of flooring, within pipe chases, in mechanical equipment insulation, in electrical components, and

within HVAC equipment; therefore, these materials may not have been observed or sampled during this ACM Survey. Any suspect materials that may not have been sampled as part of this ACM Survey should be assumed to be ACM until proven otherwise prior to future renovation or demolition activities.

1.0 INTRODUCTION

1.1 Purpose

The purpose of this Asbestos-Containing Material Survey (ACM Survey) was to satisfy the authorized Agreement between Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. (Client) and RPS and dated March 29, 2018 and to substantially satisfy the requirements of ASTM E 2356-10 "*Standard Practice for Comprehensive Building Asbestos Surveys",* as it relates to a commercial real estate transaction.

1.2 Scope of Work

There are several types of asbestos surveys depending upon the ultimate disposition of the site and the local/state regulatory environments. Currently, ASTM Standard E 2356-10 "Standard Practice for Comprehensive Building Asbestos Surveys" codifies and effectively differentiates hazard assessment, pre-demolition, and pre-asbestos abatement design surveys that have historically been described independently in:

- Asbestos Hazard Emergency Response Act (AHERA; 40 CFR Part 763), EPA's governing regulations asbestos management in schools;
- National Emission Standards for Hazardous Air Pollutants (NESHAPS; 40 CFR Part 61), EPA regulations for demolition and renovation;
- OSHA Asbestos in Construction Standard (29 CFR 1926.1101), OSHA's regulations requiring building survey to control asbestos exposure to construction personnel; and
- "Guidance for Controlling Asbestos-Containing Materials in Buildings", (EPA 560/5-85-024,), EPA's guidelines prescribing minimal sampling and hazard assessment protocols.

The scope of purpose of this ACM Survey was to adequately identify and sample suspect ACMs in substantial accordance with applicable sections of ASTM 2356-10 and appropriate Federal, State and/or local requirements, as it relates to a commercial real estate transaction. This type of survey involves both the employment of visual and slightly invasive sampling methods which may be necessary to collect material samples that may be hidden beneath multiple layers of flooring and/or other finishes; to assess the condition of suspect ACMs, PACMs, and/or other assumed ACMs; to implement a strategic asbestos sampling plan, and to confirm or negate the presence of ACMs through laboratory analysis.

RPS's field activities were conducted on April 18-21, 2018 utilizing modified EPA Asbestos Hazard Emergency Response Act (AHERA), and New York State Department of Labor (NYSDOL) requirements by NYSDOL Certified Asbestos Inspector Mr. Aaron Paik (12-04000).

Site access was provided by Mr. Joseph Marino, and Mr. Stephen Zimmerman of Newsday. RPS conducted the scope of work in accordance with the authorized Agreement between Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. (Client) and RPS dated March 29, 2018.

RPS collected a total of 238 bulk samples of suspect ACMs from 65 homogeneous materials at the Newsday facility. In consultation with the Client, 50 samples from the 238 collected were withheld from analysis, resulting in a total of 188 samples submitted. All samples withheld represented extraneous samples collected in excess of regulatory requirements. No homogenous material identified during the survey was excluded from analysis by the omission of the withheld samples. In addition, it is important to note that additional material layers (i.e. mastics/glues/adhesives/layers) associated with the 188 bulk samples submitted were also analyzed where applicable.

1.3 Sampling Protocol

The ACM Survey was conducted to satisfy the authorized Agreement between the Client and RPS dated March 29, 2018.

Bulk samples of each material suspected to contain asbestos were collected utilizing a modified Asbestos Hazard Emergency Response Act (AHERA) sampling protocol (AHERA, 40 CFR 763.86), in accordance with OSHA General Industry Standard 29 CFR 1910.1001, OSHA Asbestos Construction Standard 29 CFR 1926.1101, and State of New York requirements.

Suspect ACMs were identified and bulk samples were collected from the interior of the structure by Mr. Aaron Paik, NYSDOL Certified Asbestos Inspector (12-04000) and submitted for laboratory analysis. The EPA, OSHA, and State of New York define ACM as a material that contains greater than one percent (1%) asbestos.

Bulk samples of suspect ACM were collected as per the EPA definition of "homogenous area" (similarity of suspect material as indicated by age, type, color, and/or use). Samples were submitted to the analytical laboratory under chain of custody, and analyzed for the presence of asbestos via Polarized Light Microscopy (PLM) with dispersion staining in accordance with NYSDOH ELAP approved methodologies. In accordance with NYSDOH ELAP, non-friable organically bound samples that tested negative for asbestos via PLM were further analyzed via Transmission Electron Microscopy (TEM). Additionally, spray-on fireproofing was analyzed for the presence of vermiculite. Due to the potential for low level asbestos contamination in vermiculite, NYSDOH regulatory notices stipulate specific vermiculite analysis as summarized below.

1.4 Laboratory Analysis

Asbestos includes chrysotile, amosite, crocidolite, anthophyllite, tremolite and actinolite (fibrous minerals). The analytical report relates only to the samples tested. Samples were analyzed using polarized light microscopy (PLM) and Transmission Electron Microscopy (TEM) via New York State Environmental Laboratory Approval Program (NYS ELAP) methods for bulk asbestos materials 198.1, 198.4 and 198.6. In addition, where vermiculite was noted in spray-applied coatings and surfacing materials, further analysis by NYS ELAP method 198.8 was utilized. The reliable limit of detection of these methods is one percent (1%) asbestos content. If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*. When no

asbestos is detected in the sample submitted, the results are reported as *None Detected.* If a sample contains greater than 1% asbestos, it is considered to be ACM by EPA-NESHAPs, OSHA, NYSDOH, and NYSDOL.

Polarized Light Microscopy (PLM) via NY State ELAP 198.1 Method: The standard analytical protocol for bulk sample analysis as described above utilizes optical properties of the sampled material to provide an estimate of asbestos content as well as other minerals such as vermiculite. In New York State, only friable materials can be analyzed using the PLM method. Where thermal systems insulation (TSI), surfacing material, presumed ACM (PACM), or miscellaneous suspect ACM contain greater than 10% vermiculite, NYSDOH requires additional analysis via Environmental Laboratory Accreditation Program (ELAP) Method 198.6 (PLM-NOB) as described below.

PLM for Non-Friable Organically-Bound Materials (PLM-NOB) via NYS ELAP 198.6 Method: Certain types of building materials, such as vinyl asbestos floor tile (VAT), roofing materials, mastics, caulking, and glazing contain inherent interferences for accurate identification via standard PLM Method 198.1. These materials are classified as non-friable organically bound (NOB) materials, and require special preparation before analysis via PLM ELAP Method 198.6. The method has subsequently been permitted for vermiculite (when encountered) and other specified materials. Method 198.6 prescribes a more detailed examination of samples under what is termed "point counting" than what is employed in normal "area estimation" technique under ELAP 198.1. If results for materials analyzed via ELAP 198.6 are deemed to be inconclusive, samples are required to be analyzed using TEM methodology per NYS ELAP 198.4 as described below.

Transmission Electron Microscopy (TEM) via NYS ELAP 198.4 Method: Due to limitations of PLM to detect asbestos fibers of very small sizes (0.2 micrometers in diameter), NOB samples that are inconclusive or reveal trace amounts of asbestos via PLM methods require confirmation by a secondary analysis through Transmission Electron Microscopy (TEM) via ELAP 198.4. TEM is state-of-the-art analysis for asbestos determination due to its very high magnification (i.e., 20,000X) and its ability to positively identify the elemental composition of material being tested.

Vermiculite in Spray-Applied Coatings and Surfacing Materials: In the event that vermiculite is detected in these materials via 198.1 or 198.6 analysis, the sample must then be submitted for analysis via Method 198.8 or RJ Lee method 055 in order to provide valid results for New York State regulatory purposes. If vermiculite is not detected, no disclaimer is needed for Surfacing Material Containing Vermiculite (SM-V), defined as spray-on, troweled-on, or otherwise applied-to surfaces, if approved methods are followed. Disclaimers are still required for all other vermiculite-containing materials tested that are reported as non-ACM. These requirements are currently specific to New York State in connection with renovation, demolition and compliance requirements applicable to ACM.

1.5 Special Terms and Conditions

RPS performed this ACM Survey on behalf of and exclusively for Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. (Client). This ACM Survey and the findings contained herein shall not be relied upon, in whole or part, by any other party, except by or with the express written consent of a responsible official of RPS or the Client.

1.6 Limitations and Exceptions of Survey

During the preparation of this ACM Survey, RPS relied upon building construction information and diagrams provided by the Client. RPS has assumed, where reasonable, that the information reviewed is true and accurate but assumes no responsibility or liability for its accuracy or completeness. Site observations are of the conditions observed at the time of the site reconnaissance.

The ACM Survey was conducted to categorize the different homogeneous materials within the building, to assess the condition of suspect asbestos-containing materials (ACMs), to develop and implement an asbestos sampling plan, and identify or negate the presence of asbestos through laboratory analysis. The scope of the survey conducted was limited to the primary (production & office) structure, and did not include an assessment of any outbuilding, garage, or shed associated with the facility.

It shall be noted that where possible, RPS collected samples in inconspicuous and/or unoccupied locations of the building in coordination with Newsday administrative staff. Furthermore, RPS is not responsible for damage and/or repairs to slightly damaged materials resulting from the collection of bulk samples.

The ACM Survey executed by RPS focused on interior building systems and components with potential to contain asbestos. The scope of work associated with this survey did not include the assessment or sampling of any suspect exterior building materials or systems, including (but not limited to) roofing and all suspect ACM on the roof level.

Limited probing of interior finishes was conducted as part of this survey to identify and sample readily accessible concealed ACM. Any concealed ACM accessible only through extensive structural or mechanical demolition was not evaluated as part of this survey. No disassembly of installed equipment was conducted as part of this survey. This survey did not include probes of the perimeter masonry.

It is possible that additional suspect or assumed ACMs may be present within inaccessible areas of the building, such as above fixed ceilings, within wall systems, behind walls, beneath layers of flooring, within pipe chases, in mechanical equipment insulation, in electrical components, and within HVAC equipment; therefore, these materials may not have been observed or sampled during this ACM Survey. Any suspect materials that may not have been sampled as part of this ACM Survey should be assumed to be ACM until proven otherwise prior to future renovation or demolition activities.

2.0 SITE DESCRIPTION

2.1 Site Location and Description

The approximately 50-acre site is located southwest of the intersection of Ruland Road and Pinelawn Road at 235 Pinelawn Road in Melville, Suffolk County, New York. The site area is characterized as developed with a mix of industrial, commercial, and residential properties.

2.2 Building Description

The approximately 50-acre site is developed with an approximately 539,000-square-foot production building, which is divided between an office area and production areas, and a wastewater treatment plant. The production areas contain a packaging and bundling area, a reel room (where paper reels are fed to the printing lines), two levels of printing presses (including the printing presses, photo developing lines, and plate developing lines discussed above), boiler rooms, emergency generator rooms, a cooling tower room, various chemical storage areas, mechanical rooms, electrical rooms, maintenance shops, and a paper reel storage warehouse.

The site was redeveloped circa 1977 with the original portion of the current production building, the fire suppression water pond, the chemical storage shed, and the wastewater treatment plant. By the early 1990s, the production building was expanded to the south and west and the fuel pump island was constructed on the southern portion of the site. By the mid-2000s, a baseball field was constructed on the northwest corner of the site, bringing the site into its current configuration.

2.3 Prior Environmental Documentation

No prior environmental documentation was provided to RPS.

3.0 RESULTS

3.1 Survey Methods and Results

Bulk sampling of homogeneous areas containing suspect ACMs was conducted at the site. A homogeneous area is defined as an area of surfacing material, thermal system insulation material or miscellaneous material that is uniform in appearance, color and texture, and was applied at the same time.

Prior to collection of suspect materials, the sample location was sprayed with amended water to minimize fiber release and to soften the building material being sampled. Bulk materials were sampled from the center of the wetted area. After the sample was taken, the bulk material was placed in a sample bag which was sealed to prevent escape or contamination of outside sources. A unique sample number was assigned to each sample and the sample bag was labeled with that number.

Respiratory protection and Tyvek suits were available but not used during collection of suspect non-friable ACMs. Background fiber concentrations were not determined at the time of this ACM Survey. Potential exposures were based upon previous similar surveys indicated the permissible exposure limit (PEL) for asbestos would not be exceeded.

The survey of the facility's interior was conducted on April 18-21, 2018 by Mr. Aaron Paik, New York State Department of Labor (NYSDOL) Certified Asbestos Inspector (12-04000). RPS collected a total of 238 bulk samples of suspect ACMs from 65 homogeneous materials at the Newsday facility. In consultation with the Client, 50 samples from the 238 collected were withheld from analysis, resulting in a total of 188 samples submitted. All samples withheld represented extraneous samples collected in excess of regulatory requirements. No homogenous material identified during the survey was excluded from analysis by the omission of the withheld samples. In addition, it is important to note that additional material layers (i.e. mastics/glues/adhesives/layers) associated with the 188 bulk samples submitted were also analyzed where applicable.

Asbestos includes chrysotile, amosite, crocidolite, anthophyllite, tremolite and actinolite (fibrous minerals). The analytical report relates only to the samples tested. Samples were analyzed using polarized light microscopy (PLM) and Transmission Electron Microscopy (TEM) via New York State Environmental Laboratory Approval Program (NYS ELAP) methods for bulk asbestos materials 198.1, 198.4 and 198.6. In addition, where vermiculite was noted in spray-applied coatings and surfacing materials, further analysis by NYS ELAP method 198.8 was utilized. The reliable limit of detection of these methods is one percent (1%) asbestos content. If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*. When no asbestos is detected in the sample submitted, the results are reported as *None Detected*. If a sample contains greater than 1% asbestos, it is considered to be ACM by EPA-NESHAPs, OSHA, NYSDOH, and NYSDOL.

The following table describes materials sampled, locations, analytical results, friability, condition, and quantity estimates of materials sampled.

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
1	Yellow mastic to 12"x12" white w/black streaks VFT	2nd Fl. Executive pantry	None Detected	Non-Friable/ Good	N/A
2	Yellow mastic to 12"x12" white w/black streaks VFT	2nd Fl. Executive pantry	None Detected	Non-Friable/ Good	N/A
4	12"x12" white w/black streaks VFT	2nd Fl. Executive pantry	None Detected	Non-Friable/ Good	N/A
6	12"x12" white w/black streaks VFT	1st Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
7	Yellow/green mastic to 12"x12" bright blue VFT	2nd Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
8	Yellow/green mastic to 12"x12" bright blue VFT	2nd Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
10	12"x12" bright blue VFT	2nd Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
11	12"x12" bright blue VFT	2nd Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
13	Black mastic to 12"x12" mottled blue VFT	2nd Fl. Pantry @ southeast (near circulation)	None Detected	Non-Friable/ Good	N/A
15	Black mastic to 12"x12" mottled blue VFT	1st Fl. Production floor (collating office)	None Detected	Non-Friable/ Good	N/A
16	12"x12" mottled blue VFT	2nd Fl. Pantry @ southeast (near circulation)	None Detected	Non-Friable/ Good	N/A
18	12"x12" mottled blue VFT	1st Fl. Production floor (collating office)	None Detected	Non-Friable/ Good	N/A
19	Yellow/green mastic to 12"x12" white w/black streaks VFT	1st Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
20	Yellow/green mastic to 12"x12" white w/black streaks VFT	1st Fl. Pantry @ east	None Detected	Non-Friable/ Good	N/A
23	Black pedestal mastic assoc. w/raised floor	1st Fl. IDF/server room @ core	None Detected	Non-Friable/ Good	N/A
24	Black pedestal mastic assoc. w/raised floor	2nd Fl. IDF/server room (near compressing)	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
25	12"x12" black w/multi-color streaks + assoc. adhesive	1st Fl. Below raised floor @ ramp outside IDF	None Detected	Non-Friable/ Good	30 SF
25-Mastic	12"x12" black w/multi-color streaks + assoc. adhesive	1st Fl. Below raised floor @ ramp outside IDF	<1.00% Chrysotile	Non-Friable/ Good	30 SF
26	12"x12" black w/multi-color streaks + assoc. adhesive	1st Fl. Below raised floor @ ramp outside IDF	None Detected	Non-Friable/ Good	30 SF
26-Mastic	12"x12" black w/multi-color streaks + assoc. adhesive	1st Fl. Below raised floor @ ramp outside IDF	2.30% Chrysotile	Non-Friable/ Good	30 SF
28	Black mastic to 12"x12" mottled red VFT	1st Fl. Cafeteria – closet	1.9% Chrysotile	Non-Friable/ Good	25 SF
29	Black mastic to 12"x12" mottled red VFT	1st Fl. Cafeteria – closet	Positive Stop	Non-Friable/ Good	25 SF
31	12"x12" mottled red VFT	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	25 SF
32	12"x12" mottled red VFT	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	25 SF
34	Yellow mastic to black taupe linoleum	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	N/A
35	Yellow mastic to black taupe linoleum	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	N/A
37	Black/taupe linoleum	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	N/A
38	Black/taupe linoleum	1st Fl. Cafeteria – closet	None Detected	Non-Friable/ Good	N/A
40	Black mastic to black VFT (bottom layer)	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
41	Black mastic to black VFT (bottom layer)	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
43	Black VFT (bottom layer)	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
44	Black VFT (bottom layer)	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
46	Yellow mastic to 12"x12" black VFT w/tan mottling	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
47	Yellow mastic to 12"x12" black VFT w/tan mottling	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
49	12"x12" black VFT w/tan mottling	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
50	12"x12" black VFT w/tan mottling	1st Fl. Mailroom	None Detected	Non-Friable/ Good	N/A
53	Yellow mastic to 12"x12" black VFT w/white streaks	1st Fl. Reel room office near paper warehouse	None Detected	Non-Friable/ Good	N/A
54	Yellow mastic to 12"x12" black VFT w/white streaks	2nd Fl. Engineer's shop – closet	None Detected	Non-Friable/ Good	N/A
56	12"x12" black VFT w/white streaks	1st Fl. Reel room office near paper warehouse	None Detected	Non-Friable/ Good	N/A
57	12"x12" black VFT w/white streaks	2nd Fl. Engineer's shop – closet	None Detected	Non-Friable/ Good	N/A
58	12"x12" white VFT w/rainbow speckles + assoc. mastic (bottom layer)	Basement – Break room	None Detected	Non-Friable/ Good	N/A
59	12"x12" white VFT w/rainbow speckles + assoc. mastic (bottom layer)	Basement – Break room	None Detected	Non-Friable/ Good	N/A
61	White mastic to 12"x12" blue VFT (orange peel texture)	Basement – Break room	None Detected	Non-Friable/ Good	N/A
62	White mastic to 12"x12" blue VFT (orange peel texture)	Basement – Break room	None Detected	Non-Friable/ Good	N/A
64	12"x12" blue VFT (orange peel texture)	Basement – Break room	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
65	12"x12" blue VFT (orange peel texture)	Basement – Break room	None Detected	Non-Friable/ Good	N/A
67	Black mastic to 12"x12" beige VFT w/white + black speckles (textured)	Basement locker room	None Detected	Non-Friable/ Good	N/A
68	Black mastic to 12"x12" beige VFT w/white + black speckles (textured)	Basement locker room	None Detected	Non-Friable/ Good	N/A
70	12"x12" beige VFT w/white + black speckles	Basement locker room	None Detected	Non-Friable/ Good	N/A
71	12"x12" beige VFT w/white + black speckles	Basement locker room	None Detected	Non-Friable/ Good	N/A
73	Black mastic to 12"x12" mottled brown VFT	2nd Fl. Collating offices – hall	<1.00% Chrysotile	Non-Friable/ Good	15,000 SF
74	Black mastic to 12"x12" mottled brown VFT	1st Fl. Closet under staircase	None Detected	Non-Friable/ Good	15,000 SF
76	12"x12" mottled brown VFT	2nd Fl. Collating offices – hall	None Detected	Non-Friable/ Good	15,000 SF
77	12"x12" mottled brown VFT	1st Fl. Closet under staircase	None Detected	Non-Friable/ Good	15,000 SF
79	Mastic to parquet wood flooring	1st Fl. South wing - studio	None Detected	Non-Friable/ Good	N/A
80	Mastic to parquet wood flooring	1st Fl. South wing - studio	None Detected	Non-Friable/ Good	N/A
82	Yellow pedestal mastic	2nd Fl. Office adjacent IDF/server room (near composing)	None Detected	Non-Friable/ Good	N/A
83	Yellow pedestal mastic	2nd Fl. Office adjacent IDF/server room (near composing)	None Detected	Non-Friable/ Good	N/A
85	Yellow/green carpet panel mastic	2nd Fl. Office south wing	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
86	Yellow/green carpet panel mastic	1st Fl. Northeast office space	None Detected	Non-Friable/ Good	N/A
88	Yellow mastic to rubber impact panels	2nd Fl. Closet adjacent freight	None Detected	Non-Friable/ Good	N/A
89	Yellow mastic to rubber impact panels	1st Fl. Electrical closet @ office core corridor	None Detected	Non-Friable/ Good	N/A
91	Mudded pipe fittings	1st Fl. Reel room @ north/center	None Detected	Friable/ Good	N/A
92	Mudded pipe fittings	1st Fl. Reel room @ north/center	None Detected	Friable/ Good	N/A
93	Mudded pipe fittings	1st Fl. Reel room @ north/center	None Detected	Friable/ Good	N/A
94	Textured epoxy coating	1st Fl. Reel room @ west	None Detected	Non-Friable/ Good	N/A
95	Textured epoxy coating	1st Fl. Reel room @ east	None Detected	Non-Friable/ Good	N/A
96	Textured epoxy coating	1st Fl. Reel room – stairwell @ northeast	None Detected	Non-Friable/ Good	N/A
97	Textured epoxy coating	2nd Fl. Production floor @ west	None Detected	Non-Friable/ Good	N/A
98	Textured epoxy coating	2nd Fl. Production floor @ center	None Detected	Non-Friable/ Good	N/A
99	Textured epoxy coating	2nd Fl. Production floor @ east	None Detected	Non-Friable/ Good	N/A
100	Textured epoxy coating	2nd Fl. Production floor @ east	None Detected	Non-Friable/ Good	N/A
101	Beige cove base mastic	1st Fl. Office area @ northeast	None Detected	Non-Friable/ Good	N/A
102	Beige cove base mastic	2nd Fl. South wing office	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
104	Brown cove base mastic	2nd Fl. Production floor office – Janitor's closet	None Detected	Non-Friable/ Good	N/A
105	Brown cove base mastic	2nd Fl. Slop sink, men's bathroom	None Detected	Non-Friable/ Good	N/A
107	3" vinyl cove base	1st Fl. Closet under stairwell @ northwest	None Detected	Non-Friable/ Good	N/A
108	3" vinyl cove base	2nd Fl. Janitor's closet – production floor office	None Detected	Non-Friable/ Good	N/A
110	6" vinyl cove base	2nd Fl. Production floor @ north	None Detected	Non-Friable/ Good	N/A
111	6" vinyl cove base	2nd Fl. Production floor @ south	None Detected	Non-Friable/ Good	N/A
113	Grey duct caulk	1st Fl. Collating area – catwalk	None Detected	Non-Friable/ Good	N/A
114	Grey duct caulk	3rd Fl. West penthouse MER	None Detected	Non-Friable/ Good	N/A
116	Grey caulk/sealant on duct batting insulation pins	1st Fl. East MER	None Detected	Non-Friable/ Good	N/A
118	Grey caulk/sealant on duct batting insulation pins	3rd Fl. East penthouse MER	None Detected	Non-Friable/ Good	N/A
119	Quarry tile mortar	1st Fl. Paper warehouse	None Detected	Friable/ Good	N/A
120	Quarry tile mortar	1st Fl. Kitchen	None Detected	Friable/ Good	N/A
122	Quarry tile grout	1st Fl. paper warehouse	None Detected	Friable/ Good	N/A
123	Quarry tile grout	1st Fl. Kitchen	None Detected	Friable/ Good	N/A
125	Yellow mastic to quarry tile cove	1st Fl. Paper warehouse @ east	None Detected	Non-Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
126	Yellow mastic to quarry tile cove	1st Fl. Paper warehouse @ east	None Detected	Non-Friable/ Good	N/A
128	Mortar to ceramic tile systems	1st Fl. Men's bathroom @ slop sink	None Detected	Friable/ Good	N/A
130	Mortar to ceramic tile systems	2nd Fl. Men's bathroom	None Detected	Friable/ Good	N/A
131	White grout to ceramic tile systems	1st Fl. Women's bathroom @ shower	None Detected	Friable/ Good	N/A
132	White grout to ceramic tile systems	1st Fl. Women's bathroom @ shower	None Detected	Friable/ Good	N/A
134	Dark grout to ceramic tile systems	1st Fl. Women's bathroom under sink	None Detected	Friable/ Good	N/A
135	Dark grout to ceramic tile systems	1st Fl. Men's bathroom	None Detected	Friable/ Good	N/A
137	Yellow mastic to ceramic wall tile	1st Fl. Women's bathroom @ shower	None Detected	Non-Friable/ Good	N/A
139	Yellow mastic to ceramic wall tile	1st Fl. Women's bathroom under sink	None Detected	Non-Friable/ Good	N/A
140	12"x12" spine ACT white	2ndFl. @ east	None Detected	Friable/ Good	N/A
141	12"x12" spine ACT white	1st Fl. Office @ northeast	None Detected	Friable/ Good	N/A
143	12"x12" spine ACT grey	2nd Fl. Production office hallway	None Detected	Friable/ Good	N/A
144	12"x12" spine ACT grey	2nd Fl. Production office hallway	None Detected	Friable/ Good	N/A
146	Gypsum panel ACT	Basement Janitor's closet across from freight elevator	None Detected	Friable/ Good	N/A
148	Gypsum panel ACT	2nd Fl. @ east	None Detected	Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
149	Rough textured ACT	1st Fl. Hallway	None Detected	Friable/ Good	N/A
150	Rough textured ACT	1st Fl. Hallway	None Detected	Friable/ Good	N/A
152	Smooth textured ACT	Basement stock pile – storage area	None Detected	Friable/ Good	N/A
153	Smooth textured ACT	Basement stock pile – storage area	None Detected	Friable/ Good	N/A
155	24"x48" ribbed ACT	1st Fl. Auditorium	None Detected	Friable/ Good	N/A
156	24"x48" ribbed ACT	1st Fl. Auditorium	None Detected	Friable/ Good	N/A
158	Wormhole ACT	2nd Fl. Storage room adjacent to freight	None Detected	Friable/ Good	N/A
159	Wormhole ACT	1st Fl. Storage room, production floor @ west	None Detected	Friable/ Good	N/A
161	Boiler gaskets (woven fabric like material)	Boiler L 65133	None Detected	Friable/ Good	N/A
162	Boiler gaskets (woven fabric like material)	Boiler L 65134	None Detected	Friable/ Good	N/A
163	Boiler gaskets (woven fabric like material)	Boiler L 89899	None Detected	Friable/ Good	N/A
164	Boiler flue/breeching insulation	Boiler L 65133	None Detected	Friable/ Good	N/A
165	Boiler flue/breeching insulation	Boiler L 65134	None Detected	Friable/ Good	N/A
166	Boiler flue/breeching insulation	Boiler L 65134	None Detected	Friable/ Good	N/A
167	Exhaust/breeching insulation	2nd Fl. Generator, northwest electrical room	None Detected	Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
168	Exhaust/breeching insulation	2nd Fl. Generator, northwest electrical room	None Detected	Friable/ Good	N/A
169	Exhaust/breeching insulation	2nd Fl. Generator, northwest electrical room	None Detected	Friable/ Good	N/A
170	Generator exhaust/breeching insulation (white block)	Basement generator @ north	None Detected	Friable/ Good	N/A
171	Generator exhaust/breeching insulation (white block)	Basement generator @ north	None Detected	Friable/ Good	N/A
172	Generator exhaust/breeching insulation (white block)	Basement generator @ north	None Detected	Friable/ Good	N/A
173	Generator exhaust/breeching insulation (grey mudding)	Basement generator @ north	None Detected	Friable/ Good	N/A
174	Generator exhaust/breeching insulation (grey mudding)	Basement generator @ north	None Detected	Friable/ Good	N/A
175	Generator exhaust/breeching insulation (grey mudding)	Basement generator @ north	None Detected	Friable/ Good	N/A
176	Sheetrock	2nd Fl. Office adjacent IDF/server room (near composing)	None Detected	Friable/ Good	N/A
177	Sheetrock	1st Fl. Office area @ northeast	None Detected	Friable/ Good	N/A
178	Sheetrock	2nd Fl. Storage room adjacent freight	None Detected	Friable/ Good	N/A
179	Sheetrock	2nd Fl. Production floor office @ west	None Detected	Friable/ Good	N/A
180	Sheetrock	2nd Fl. Men's bathroom	None Detected	Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
181	Sheetrock	2nd Fl. South wing – conference room	None Detected	Friable/ Good	N/A
182	Sheetrock	2nd Fl. Closet adjacent freight	None Detected	Friable/ Good	N/A
183	Sheetrock	2nd Fl. Production floor office janitor closet	None Detected	Friable/ Good	N/A
184	Sheetrock	1st Fl. Storage room under stairs @ northeast	None Detected	Friable/ Good	N/A
185	Joint compound	2nd Fl. Office adjacent IDF/server room (near composing)	None Detected	Friable/ Good	N/A
186	Joint compound	1st Fl. Office area @ northeast	None Detected	Friable/ Good	N/A
187	Joint compound	2nd Fl. Storage room adjacent freight	None Detected	Friable/ Good	N/A
188	Joint compound	2nd Fl. Production floor office @ west	None Detected	Friable/ Good	N/A
189	Joint compound	2nd Fl. Men's bathroom	None Detected	Friable/ Good	N/A
190	Joint compound	2nd Fl. South wing – conference room	None Detected	Friable/ Good	N/A
191	Joint compound	2nd Fl. Closet adjacent freight	None Detected	Friable/ Good	N/A
192	Joint compound	2nd Fl. Production floor office – janitors closet	None Detected	Friable/ Good	N/A
193	Joint compound	1st Fl. Storage room under stairs @ northeast	None Detected	Friable/ Good	N/A
194	CMU mortar	1st Fl. Storage room under stairs @ northeast	None Detected	Friable/ Good	N/A
195	CMU mortar	Basement @ center	None Detected	Friable/ Good	N/A

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
196	CMU mortar	1st Fl. Collating area	None Detected	Friable/ Good	N/A
197	Brown epoxy floor	1st Fl. Freight lobby	None Detected	Non-Friable/ Good	N/A
198	Brown epoxy floor	1st Fl. Freight lobby	None Detected	Non-Friable/ Good	N/A
199	Brown epoxy floor	1st Fl. Freight lobby	None Detected	Non-Friable/ Good	N/A
200	Grey spray-on fireproofing	Basement South generator room	None Detected	Friable/ Good	N/A
201	Grey spray-on fireproofing	Basement South generator room	None Detected	Friable/ Good	N/A
202	Grey spray-on fireproofing	Basement South generator room	None Detected	Friable/ Good	N/A
203	Grey spray-on fireproofing	1st Fl. Loading dock @ south	None Detected	Friable/ Good	N/A
204	Grey spray-on fireproofing	1st Fl. Loading dock @ south	None Detected	Friable/ Good	N/A
205	Grey spray-on fireproofing	1st Fl. Loading dock @ south	None Detected	Friable/ Good	N/A
206	Grey spray-on fireproofing	2nd Fl. South wing – facilities office conference room	None Detected	Friable/ Good	N/A
207	Grey spray-on fireproofing	2nd Fl. South wing – facilities office conference room	None Detected	Friable/ Good	N/A
208	Grey spray-on fireproofing	2nd Fl. South wing – facilities office conference room	None Detected	Friable/ Good	N/A
209	Tan spray-on fireproofing (SF-2)	1st Fl. Reel storage @ west	Trace Amphibole	Friable/ Good	45,000 SF
210	Tan spray-on fireproofing (SF-2)	1st Fl. Reel storage @ west	Trace Amphibole	Friable/ Good	45,000 SF

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
211	Tan spray-on fireproofing (SF-2)	1st Fl. Reel storage @ west	Trace Amphibole	Friable/ Good	45,000 SF
212	Tan spray-on fireproofing (SF-2)	2nd Fl. Storage room @ west	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
213	Tan spray-on fireproofing (SF-2)	2nd Fl. Generator room @ northwest	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
214	Tan spray-on fireproofing (SF-2)	2nd Fl. Generator room @ northwest	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
215	Tan spray-on fireproofing (SF-2)	3rd Fl. West penthouse MER	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
216	Tan spray-on fireproofing (SF-2)	3rd Fl. West penthouse MER	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
217	Tan spray-on fireproofing (SF-2)	3rd Fl. West penthouse MER	Not Analyzed/ Contains Vermiculite	Friable/ Good	45,000 SF
218	Tan spray-on fireproofing (SF-3)	1st Fl. Collating receiving @ east	0.016% Amphibole	Friable/ Good	37,500 SF
219	Tan spray-on fireproofing (SF-3)	1st Fl. Collating receiving @ east	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF
220	Tan spray-on fireproofing (SF-3)	1st Fl. Collating receiving @ east	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF
221	Tan spray-on fireproofing (SF-3)	1st Fl. Collating receiving @ east	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
222	Tan spray-on fireproofing (SF-3)	1st Fl. Collating receiving @ east	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF
223	Tan spray-on fireproofing (SF-3)	2nd Fl. Conference room – south wing	0.025% Amphibole	Friable/ Good	37,500 SF
224	Tan spray-on fireproofing (SF-3)	2nd Fl. Conference room – south wing	Trace Amphibole	Friable/ Good	37,500 SF
225	Tan spray-on fireproofing (SF-3)	2nd Fl. Conference room – south wing	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF
226	Tan spray-on fireproofing (SF-3)	2nd Fl. Conference room – south wing	Not Analyzed/ Contains Vermiculite	Friable/ Good	37,500 SF
227	Tan spray-on fireproofing (SF-1)	1st Fl. Cafeteria closet – column	None Detected	Friable/ Good	175,000 SF
228	Tan spray-on fireproofing (SF-1)	1st Fl. Reel room @ center	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF
229	Tan spray-on fireproofing (SF-1)	2nd Fl. Office adjacent IDF/server room	None Detected	Friable/ Good	175,000 SF
230	Tan spray-on fireproofing (SF-1)	1st Fl. Paper warehouse, C22	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF
231	Tan spray-on fireproofing (SF-1)	3rd Fl. East penthouse MER	None Detected	Friable/ Good	175,000 SF
232	Tan spray-on fireproofing (SF-1)	1st Fl. East MER	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF
233	Tan spray-on fireproofing (SF-1)	1st Fl. Office @ northeast	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF

NEWSDAY – MELVILLE, NY – RPS SAMPLE COLLECTION SUMMARY TABLE					
Sample Number	**Sample Description**	**Material Location**	**Laboratory Results**	**Friability/ Condition**	**Estimated Quantity**
234	Tan spray-on fireproofing (SF-1)	2nd Fl. Storage room adjacent freight	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF
235	Tan spray-on fireproofing (SF-1)	2nd Fl. Collating office hallway	Not Analyzed/ Contains Vermiculite	Friable/ Good	175,000 SF
236	Tan trowel applied fireproofing	1st Fl. Paper warehouse, C19	Not Analyzed/ Contains Vermiculite	Friable/ Good	N/A
237	Tan trowel applied fireproofing	1st Fl. Paper warehouse, C19	Not Analyzed/ Contains Vermiculite	Friable/ Good	N/A
238	Tan trowel applied fireproofing	1st Fl. Paper warehouse, C22	None Detected	Friable/ Good	N/A

ACT = Acoustical Ceiling Tile
CMU = Concrete Masonry Unit
IDF = Intermediate Distribution Frame
MER = Mechanical Equipment Room
N/A = Not Applicable
SF = Square Feet
VFT = Vinyl Floor Tile
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.

The scope of the survey executed by RPS included no assessment of suspect ACM on the exterior or roof level of the inspected properties. The table below presents sampling and analysis performed by WJE Engineers and Architects on behalf of the Client with respect to roofing materials at the site. The laboratory analysis data associated with these roof samples has been provided to RPS and is presented here in this table. Although the results are favorable (non-detect for all samples), the number of samples and methodology of collection did not comply with regulations and protocols applicable to sampling performed in connection with demolition or renovation, and therefore cannot be relied upon for such purposes. Additional sampling and analysis would be required prior to any renovation or demolition of such exterior materials.

NEWSDAY – MELVILLE, NY – WJE ENGINEERS & ARCHITECTS ROOF CORE DATA					
Sample Number	**Sample Description**	**Material Locations**	**Laboratory Results**	**Friability**	**Estimated Quantity**
Core #1	Roof field	Roof 1	None Detected	Non-Friable	N/A

NEWSDAY – MELVILLE, NY – WJE ENGINEERS & ARCHITECTS ROOF CORE DATA					
Sample Number	**Sample Description**	**Material Locations**	**Laboratory Results**	**Friability**	**Estimated Quantity**
Core #2	Roof field	Roof 2	None Detected	Non-Friable	N/A
Core #3	Roof field	Roof 3	None Detected	Non-Friable	N/A
Core #4	Roof field	Roof 4	None Detected	Non-Friable	N/A
Core #5	Roof field	Roof 5	None Detected	Non-Friable	N/A
Core #6	Roof field	Roof 6	None Detected	Non-Friable	N/A
Core #7	Roof field	Roof 7	None Detected	Non-Friable	N/A
Core #8	Roof field	Roof 8	None Detected	Non-Friable	N/A
Core #9	Roof field	Roof 9	None Detected	Non-Friable	N/A
Core #10	Roof field	Roof 10	None Detected	Non-Friable	N/A
Core #11	Roof field	Roof 11	None Detected	Non-Friable	N/A

SF = Square Feet
N/A = Not Applicable
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.

The following building materials were identified as containing greater than 1% asbestos; therefore, they are required to be treated as regulated ACMs:

NEWSDAY – MELVILLE, NY – SUMMARY OF CONFIRMED ACMS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
25, 26	12"x12" black w/multi-color streaks + assoc. adhesive - Mastic	1st Fl. Below raised floor @ ramp outside IDF	2.30% Chrysotile	Not friable/good condition	30 SF
28, 29	Black mastic to 12"x12" mottled red VFT	1st Fl. Cafeteria – closet	1.90% Chrysotile	Not friable/good condition	25 SF

IDF = Intermediate Distribution Frame (IT/Server Room)
SF = Square Feet
VFT = Vinyl Floor Tile
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.

If a material contains 1% or less asbestos, certain work practice requirements and prohibitions of the OSHA Asbestos in Construction Standard (29 CFR 1926.1101) must be followed. Standard 29 CFR 1926.1101 regulates asbestos exposure in all work as defined in 29 CFR 1910.12(b), including (but not limited to) demolition, construction, alteration, repair, maintenance, or renovation in structures that contain asbestos. The regulation also regulates transportation, disposal, storage, containment of and housekeeping activities involving asbestos or products

containing asbestos. Among other requirements, the regulation outlines employer responsibilities in monitoring and ensuring that employee exposure asbestos fall below acceptable thresholds. These thresholds are defined by a permissible exposure limit (PEL) of 0.1 fibers per cubic centimeter of air, calculated as an eight (8) hour time-weighted average (TWA), and an excursion limit defined as an airborne concentration of asbestos in excess of 1.0 fiber per cubic centimeter of air as averaged over a thirty (30) minute period. Other requirements include (but are not limited to): training, hazard communication, notification, medical surveillance, appropriate work practices, required personal protective equipment (PPE), and engineering controls.

The following materials were identified to contain asbestos in amounts of 1% or less (trace):

NEWSDAY – MELVILLE, NY – SUMMARY OF <1% (TRACE) AMOUNTS OF ASBESTOS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
73, 74	Black mastic to 12"x12" mottled brown VFT	Throughout	<1% Chrysotile	Not friable/good condition	15,000 SF
209-217	Tan Spray-on fireproofing (SF-2)	Throughout; west portion of structure (c. 1986-1989 construction), containing portions of reel room, production floor and west penthouse MER**	0.016% Amphibole/ Trace	Friable/good condition	45,000 SF
218-226	Tan Spray-on fireproofing (SF-3)	Throughout; south portion of structure (unknown construction date), containing portions of the collating/receiving floor, south office wing, and basement mechanical spaces**	0.055% Amphibole/ Trace	Friable/good condition	37,500 SF

SF = Square Feet
VFT = Vinyl Floor Tile
MER = Mechanical Equipment Room
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.
** In the execution of the survey, homogenous types were identified on the basis of appearance, color and texture in accordance with applicable regulations and industry standards. In assessing spray-on fireproofing, information provided by Newsday staff with regards to construction history was further utilized to subdivide the "Tan spray-on fireproofing" into sub-types (SF1 through SF3).

Vermiculite was detected in the initial analysis of some of the spray-on fireproofing (SFP) samples collected at the site. In consultation with the Client, representative samples were selected from the homogenous materials identified as containing vermiculite, and re-analyzed in accordance with the New York State Department of Health Environmental Laboratory Accreditation Program (NYSDOH ELAP) requirements. A total of ten (10) samples from the four (4) homogenous types/sub-types of spray-on fireproofing identified as containing vermiculite were

submitted for further analysis via method 198.8. Reanalysis indicated that three (3) samples contained trace amounts of asbestos (<1%).

3.2 Inspector Comments

In the event of building renovation or demolition activities, EPA-NESHAP and OSHA requirements for the management of identified ACMs or untested materials assumed to be ACM will apply. Therefore, a licensed asbestos abatement contractor should be retained to repair, remove, encapsulate, or encase the materials in accordance with applicable EPA-NESHAP, OSHA, and NYSDOL rules and regulations for proper asbestos management activities.

It should be noted that the EPA has not prohibited the manufacture of non-friable ACMs, such as vinyl floorings, mastics, joint compounds, and roofing materials as well as materials imported from other countries.

4.0 FINDINGS AND CONCLUSIONS

Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. (Client) retained RPS to conduct an ACM Survey of the Newsday facility, located at 235 Pinelawn Road in Melville, Suffolk County, New York (the facility or building).

RPS conducted this ACM Survey as described in the authorized Agreement between the Client and RPS dated March 29, 2018 and in general accordance with applicable sections of ASTM E 2356-10 "*Standard Practice for Comprehensive Building Asbestos Surveys",* as it relates to a commercial real estate transaction.

The following building materials were identified as containing greater than 1% asbestos; therefore, they are required to be treated as regulated ACMs:

NEWSDAY – MELVILLE, NY - SUMMARY OF CONFIRMED ACMS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
25, 26	12"x12" black w/multi-color streaks + assoc. adhesive - Mastic	1st Fl. Below raised floor @ ramp outside IDF	2.30% Chrysotile	Not friable/good condition	30 SF
28, 29	Black mastic to 12"x12" mottled red VFT	1st Fl. Cafeteria – closet	1.90% Chrysotile	Not friable/good condition	25 SF

IDF = Intermediate Distribution Frame (IT/Server Room)
SF = Square Feet
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.

The following materials were identified to contain asbestos in amounts of 1% or less (trace):

NEWSDAY – MELVILLE, NY – SUMMARY OF <1% (TRACE) AMOUNTS OF ASBESTOS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
73, 74	Black mastic to 12"x12" mottled brown VFT	Throughout	<1% Chrysotile	Not friable/good condition	15,000 SF
209-217	Tan Spray-on fireproofing (SF-2)	Throughout; west portion of structure (c. 1986-1989 construction), containing portions of reel room, production floor and west penthouse MER**	0.016% Amphibole/ Trace	Friable/good condition	45,000 SF

NEWSDAY – MELVILLE, NY – SUMMARY OF <1% (TRACE) AMOUNTS OF ASBESTOS					
Sample Number (s)	**Sample Description**	**Material Location**	**Laboratory Results***	**Friability/ Condition**	**Estimated Quantity**
218-226	Tan Spray-on fireproofing (SF-3)	Throughout; south portion of structure (unknown construction date), containing portions of the collating/receiving floor, south office wing, and basement mechanical spaces**	0.055% Amphibole/ Trace	Friable/good condition	37,500 SF

SF = Square Feet
VFT = Vinyl Floor Tile
MER = Mechanical Equipment Room
None Detected = When no asbestos is detected in the sample submitted, the results are reported as *None Detected*.
Trace = If less than 1% asbestos is present in the sample submitted, the results are reported as <1% or *Trace*.
* Highest result for samples of the identified material reported.
** In the execution of the survey, homogenous types were identified on the basis of appearance, color and texture in accordance with applicable regulations and industry standards. In assessing spray-on fireproofing, information provided by Newsday staff with regards to construction history was further utilized to subdivide the "Tan spray-on fireproofing" into sub-types (SF1 through SF3).

Vermiculite was detected in the initial analysis of some of the spray-on fireproofing (SFP) samples collected at the site. In consultation with the Client, representative samples were selected from the homogenous materials identified as containing vermiculite, and re-analyzed in accordance with the New York State Department of Health Environmental Laboratory Accreditation Program (NYSDOH ELAP) requirements. A total of ten (10) samples from the four (4) homogenous types/sub-types of spray-on fireproofing identified as containing vermiculite were submitted for further analysis via method 198.8. Reanalysis indicated that three (3) samples contained trace amounts of asbestos (<1%).

In the event of building renovation or demolition activities, EPA-NESHAP and OSHA requirements for the management of identified ACMs or untested materials assumed to be ACM will apply. Therefore, a licensed asbestos abatement contractor should be retained to repair, remove, encapsulate, or encase the materials in accordance with applicable EPA-NESHAP, OSHA, and NYSDOL rules and regulations for proper asbestos management activities.

5.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS

This ACM Survey was performed as described in the authorized Agreement between Orrick, Harrington & Sutcliffe LLP, as attorneys for Tribune ND, Inc. and RPS dated March 29, 2018 and documents the sampling methodology used by qualified environmental professionals of RPS to obtain, identify, and summarize information pertaining to ACMs located at the Newsday facility, located at 235 Pinelawn Road in Melville, Suffolk County, New York.

Report By:

RPS – Environmental Risk

Jeffrey D. Menter
Director

Steven D. Kline, P.E.
President



United States | Canada | Brazil | UK | Ireland | Netherlands | Australia Asia Pacific | Russia | Middle East | Africa

135 South LaSalle Street, Suite 3500 | Chicago, IL | 60603 | (312) 541-4200

RCRA CLOSURE PLAN

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK 11747

USEPA ID# NYD052782497

JULY 18, 2018, REV 1

Prepared for:

Newsday LLC
235 Pinelawn Road
Melville, New York 11747

Prepared by:

H2M architects + engineers
290 Broad Hollow Road, Suite 400E
Melville, New York 11747

H2M Project No.: NEWD1803

H 2 M architects + engineers

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

RCRA CLOSURE PLAN

JULY 18, 2018, REV 1

TABLE OF CONTENTS

Page

1.0 GENERAL INFORMATION 1

1.1 Location and Facility Description 1

1.2 Scope 2

1.3 Process Operations – Hazardous Waste Streams 2

2.0 CLOSURE 4

2.1 Closure Description 4

2.2 Closure Performance Standard 4

2.3 Maximum Waste Inventory 5

2.4 Closure Requirements 6

2.4.1 Former Silver Recovery Underground Storage Tank 6

2.4.2 Former Silver Recovery Room & Photo Waste Room 6

2.4.3 Ink Recovery Room 7

2.4.4 Fixer, Developer, and Industrial Waste Piping 8

3.0 CLOSURE CERTIFICATION 9

4.0 CLOSURE SCHEDULE 9

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

RCRA CLOSURE PLAN

JULY 18, 2018, REV 1

LIST OF FIGURES

FIGURE 1	SITE LOCATION MAP
FIGURE 2	FACILITY SITE PLAN
FIGURE 3	LOCATION OF FORMER 4,000-GAL. SILVER RECOVERY UST
FIGURE 4	BASEMENT BOILER EXPANSION FLOOR PLAN AND WALL SECTION
FIGURE 5	LOCATIONS OF FORMER SILVER RECOVERY & PHOTO WASTE ROOMS
FIGURE 6	PROPOSED SAMPLING OF FORMER SILVER RECOVERY ROOM
FIGURE 7A	FIRST LAYOUT OF FORMER PHOTO WASTE ROOM (PLAN VIEW)
FIGURE 7B	FIRST LAYOUT OF FORMER PHOTO WASTE ROOM (SECTION VIEW)
FIGURE 8	SECOND LAYOUT OF FORMER PHOTO WASTE ROOM & PROPOSED SAMPLING
FIGURE 9	PROPOSED SAMPLING OF INK RECOVERY ROOM
FIGURES 10.1 – 10.5	FIXER, DEVELOPER AND INDUSTRIAL WASTE PIPING

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

RCRA CLOSURE PLAN

JULY 18, 2018, REV 1

LIST OF TABLES

TABLE 1	TANKS ASSOCIATED WITH FIXER AND DEVELOPER WASTE
TABLE 2	MAXIMUM WASTE INVENTORY OF ON-SITE HAZARDOUS WASTES
TABLE 3.1	FIXER PIPING SAMPLING RESULTS FOR METALS – APRIL 24, 2018
TABLE 3.2	FIXER PIPING SAMPLING RESULTS FOR VOCS – APRIL 24, 2018

APPENDICES

APPENDIX A	QUALITY ASSURANCE PROJECT PLAN
APPENDIX B	SCDHS TANK LISTING, APRIL 10, 2014
APPENDIX C	FORMER SILVER RECOVERY UST REMOVAL DOCUMENTATION
APPENDIX D	LABORATORY ANALYTICAL REPORT – FIXER PIPING, APRIL 24, 2018

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

RCRA CLOSURE PLAN

JULY 18, 2018, REV 1

1.0 GENERAL INFORMATION

Facility Name:	Newsday LLC
Address:	235 Pinelawn Road Melville, New York 11747
Facility Contact:	Stephen Zimmerman Director of Engineering Services
Telephone No.:	(631) 843-2032
Facility Owner:	Tribune ND, LLC 435 N. Michigan Avenue Chicago, Illinois 60611
Facility Operator:	Newsday LLC 235 Pinelawn Road Melville, New York 11747
RCRA Status:	Large Quantity Generator (LQG)

1.1 Location and Facility Description

The Newsday facility occupies a 50-acre site located at 235 Pinelawn Road in Melville, Long Island, within the Town of Huntington, County of Suffolk, New York. The facility is bounded to the east by Pinelawn Road, to the north by Ruland Road, to the west by Deshon Drive, and to the South by a private service road. Properties surrounding the facility include undeveloped land to the north, Clare Rose Distributor to the south, Pinelawn Cemetery to the east, and Town Apartments to the west. A site location map is provided as **Figure 1**. The facility is improved with one (1) two-story building with a partial basement which was built in 1979 and some later additions.

Operations at the facility include printing, publishing, preparing and distributing a daily newspaper edition. Most recent activities have included, but are not limited to the following: photo platemaking, collating, printing press operation, press maintenance, facility maintenance, housekeeping, wastewater treatment, boiler treatment, cooling tower treatment, and fleet vehicle fueling. Past activities included photographic film development. The facility was historically a Large Quantity Generator (LQG) of hazardous waste, but operated as a Small Quantity Generator (SQG) since approximately 2012. Wastes predominantly include

flammable and corrosive press wastes from printing operations. Other wastes that were historically generated at the facility primarily included ink waste, spent photographic developer and spent photographic fixer. The USEPA Hazardous Waste ID is NYD052782497 and the SCDHS Hazardous Material Storage Permit ID is 02037.

1.2 Scope

This Closure Plan has been prepared by H2M architects + engineers (H2M) on behalf of Newsday LLC in accordance with the requirements outlined in 6 NYCRR Part 373-3.7, Closure and Post-Closure. This Closure Plan shall be implemented to formally cease and document completion of regulated waste activities. The purpose of completing the closure is to eliminate post-closure maintenance of hazardous waste generation sources and hazardous waste storage areas at the subject property and to minimize the potential for a post-closure release of hazardous waste to the environment. The Newsday facility location is shown in **Figure 1**, Site Location Map. The facility site plan is shown in **Figure 2**.

1.3 Process Operations – Hazardous Waste Streams

The Newsday facility generated three hazardous waste streams in its daily operations. The hazardous waste streams included ink waste, spent photographic developer and spent photographic fixer. A brief description of the processes and the wastes generated is provided below:

Ink Waste: The ink waste stream is generated from the cleaning of the printing presses at the end of each day's press run. The presses are washed with a solution of detergent, water and a naphtha solvent. The spent solution is containerized into 55-gallon drums, and then processed in an ink recycler unit. Wastes generated from the recycler unit include the ink waste, the water and naphtha with some residual ink, and a sludge byproduct consisting primarily of paper fibers. The ink that is recovered is re-used for printing. The resulting wastes are drummed and stored in the Ink Recovery Room. Due to the flashpoint and trace amounts of methylene chloride detected in the wastes, the drums were historically listed as D001 and F001 hazardous waste. Most recently these wastes have been non-hazardous. The drums are properly disposed of on a weekly basis by a licensed hauler to a permitted disposal facility.

Spent Photographic Developer and Fixer: Photographic developing was performed in a series of compartments or sinks located in five areas on the second floor of the facility. The compartments or sinks consisted of water rinses, developer and fixer solutions, each with separate drainage systems. The water rinses drained into the industrial waste system that led to the on-site Sewage Treatment Plant. The developer drainage system consisted of glass and polyethylene piping, which drained directly into a 4,000-gallon fiberglass underground storage tank (UST, SCDHS Tank No. 8). The spent fixer solution, which contained silver, also drained through glass and polyethylene piping. The fixer drainage system led to a former 100-gallon polyethylene holding

tank (SCDHS Tank No. 13) located in the Former Silver Recovery Room in the basement. The layout of the Former Silver Recovery Room is shown on **Figure 6**. The spent fixer solution was then circulated through a cathode/anode type electroplating unit to separate the entrained silver before being pumped into the 4,000-gallon UST, mixing with the developer waste. The silver was sold to a reclaimer on a monthly basis.

The 4,000-gallon UST was subsequently removed in June 1989, and the waste stream was subsequently redirected to two 2,000-gallon polyethylene aboveground storage tanks (ASTs, SCDHS Tank Nos. 26 and 27) located in a Former Photo Waste Room that was constructed circa 1989, shown in **Figures 7a and 7b**. One of the two 2,000-gallon ASTs was for emergency use only. The Former Photo Waste Room also consisted of a 100-gallon holding tank (SCDHS Tank No. 43) which held fixer solution that processed through silver reclamation equipment prior to being pumped into the 2,000-gallon ASTs. The developer solution drained directly into the ASTs. When the Former Photo Waste Room was first set up, the fixer/developer waste was pumped out two or three times a month and disposed of at a permitted disposal facility. The fixer/developer mixture that was stored in the ASTs contained elevated levels of cadmium and silver with traces of mercury and selenium. This waste was considered hazardous due to EP Toxicity; however, exact concentrations depended upon composition and silver recovery efficiency. Eventually, in an effort to reduce the volume of wastes, the waste solutions from the two 2,000-gallon ASTs were pumped into a 250-gallon holding tank (SCDHS Tank No. 28) which was then processed through wastewater treatment equipment and discharged through the industrial drain to the on-site wastewater treatment plant (WWTP).

The Former Photo Waste Room was subsequently modified circa 2002, and is shown in **Figure 8**. The two 2,000-gallon ASTs were removed. The fixer solution after running through silver recovery equipment along with the developer solution were pumped into the existing 250-gallon holding tank and a 500-gallon holding tank. From the two holding tanks, the waste mixture was discharged to the on-site WWTP. The Former Photo Waste Room was decommissioned in late 2008. A copy of the

All tanks associated with the fixer and developer wastes have been removed from the facility. Table 1 below shows the year removed for each of the aforementioned tanks. A copy of a SCDHS tank listing, dated April 10, 2014, highlighting the tanks below is provided in **Appendix B**.

Table 1. Tanks Associated with Fixer and Developer Waste.

SCDHS Tank No.	Location	Tank Capacity (gallons)	Year Removed
8	Underground, Outdoor	4,000	1989 (Tyree)
13	Aboveground, Former Silver Recovery Room	100	2001
26	Aboveground, Former Photo Waste Room	2,000	2002
27	Aboveground, Former Photo Waste Room	2,000	2002
28	Aboveground, Former Photo Waste Room	250	2003
43	Aboveground, Former Photo Waste Room	100	2002
83	Aboveground, Former Photo Waste Room	500	2009

2.0 CLOSURE

The closure of Newsday facility will include the removal of all hazardous wastes, decontamination of the hazardous waste storage areas, confirmatory rinsate and subsurface soil sampling, and removal of all wastes generated during closure.

2.1 Closure Description

Facility closure will initiate with the discontinuation of all routine process operations that generate hazardous wastes. Upon shutting down the process operations, all inventories of hazardous wastes will be disposed of in accordance with all applicable federal, state, and local regulations. Wastewaters that are generated during decontamination activities will be collected, containerized, and disposed of in accordance with federal, state and local regulations.

2.2 Closure Performance Standard

This Closure Plan is designed to ensure that the Newsday facility will require no further maintenance or controls following closure of its hazardous waste activities. The contents of the plan are structured to prevent threats to human health and the environment.

Confirmatory sampling will be conducted as part of the closure activities to document that no hazardous materials remain that can adversely impact public health or the environment. Sampling shall include floor surface rinsate sampling and subsurface soil sampling in the areas where hazardous wastes were handled and stored including the Former Silver Recovery Room and the Ink Recovery Room. In addition, rinsate sampling will be performed as necessary for the spent photographic developer, spent photographic fixer waste, and industrial waste piping to confirm that no hazardous materials remain within the piping.

When available, applicable, federal, state, and local environmental quality standards are to be used to determine the adequacy of closure. For rinsate sampling of floors and piping conducted as part of Newsday facility's RCRA Closure, the closure performance standard shall be the NYS Groundwater Effluent Limitations (Class GA), as identified in NYSDEC TOGS 1.1.1 or 6 NYCRR Part 703.6. If any rinsate sample exceeds the groundwater effluent limitations, then the corresponding area shall be re-cleaned and subsequently re-sampled. This procedure shall be repeated until all parameters are within the closure performance standards. Rinsate samples will be collected following the completion of cleaning activities and analyzed for the target analyte list (TAL) of metals, including mercury (Hg), and target compound list (TCL) of volatile organic compounds (VOCs) plus tentatively identified compounds (TICs).

For soil sampling, the closure performance standard shall be the 6 NYCRR Part 375-6.8(a) Unrestricted Use Soil Cleanup Objectives. All soil samples will be analyzed for TAL metals/Hg, and TCL VOCs + TICs.

In order to determine whether the waste piping is characterized as non-hazardous or hazardous, sampling results from the interior deposits of the piping will be compared with the 6 NYCRR Part 371.1(e) Table 1 Maximum Concentration of Contaminants for the Toxicity Characteristic (TCLP Limits). Piping deposit samples will be analyzed for TCLP metals, should sufficient material be collected.

2.3 Maximum Waste Inventory

During the closure of the Newsday facility, any existing hazardous wastes will be properly disposed of off-site. A RCRA regulated facility must identify the maximum inventory of hazardous waste stored on-site over the active life of the facility. Implementation of this closure plan may create additional wastes requiring off-site disposal such as decontamination rinse waters, analytical equipment and contaminated structures, if any. However, the maximum inventory determination excludes wastes generated as a result of facility closure. Based upon the fact that Newsday actively maintains the facility and a licensed hazardous waste transporter routinely hauls hazardous material on a regular basis, the maximum waste inventory that is expected to be on-site at any time is based on the storage capacity of the hazardous storage areas or tanks, and is shown in the following table:

Table 2. Maximum Waste Inventory of On-Site Hazardous Wastes.

Process Generating Waste	Type of Waste	Max. Quantity On-Site
Ink Waste	EPA Waste Codes: D001 & F001 (e.g., Naptha, Methylene Chloride)	1,380 Gallons[1]

(1) Maximum storage capacity of solvent storage area. Most recent ink wastes have been non-hazardous.

2.4 Closure Requirements

The activities to be performed as part of the RCRA Closure at the Newsday facility are described in the following sections:

2.4.1 Former Silver Recovery Underground Storage Tank

As described in Section 1.3, a former 4,000-gallon fiberglass underground storage tank (UST) was utilized to store spent photographic developer and spent photographic fixer waste. The UST was located outdoors near the southeast portion of the building, as shown on **Figure 3**. Following decommissioning of the 4,000-gallon UST in January 1989, the two photographic waste streams were subsequently directed into the two 2,000-gallon polyethylene aboveground storage tanks (ASTs) located in the basement of the facility. The 4,000-gallon UST was removed by Tyree Bros. Environmental Services, Inc. (Tyree) on June 12, 1989 and disposed of at Gershow Recycling in Medford, New York. The UST was removed as part of a basement boiler room expansion project. **Figure 4** shows the basement boiler expansion area and a section view of one of the basement walls. As shown on Figure 4, the basement foundation slab extended 18.5 feet below the first floor slab. The 4,000-gallon UST had a diameter of 7 feet and the bottom of the tank was situated at approximately 12.5 feet below grade. Therefore, at the time of the basement expansion project, the area with the former silver recovery UST was over-excavated to a minimum depth of 18.5 feet below grade. Copies of a request for proposal (Newsday to Tyree, dated April 17, 1989), proposal from Tyree (dated April 25, 1989), a purchase order issued by Newsday to Tyree (dated May 5, 1989), a tank removal confirmation letter (Tyree, dated June 15, 1989), and invoice (Tyree, dated June 15, 1989) are provided in **Appendix C**. As shown on Tyree's invoice, no contaminated soil was identified during the tank excavation.

2.4.2 Former Silver Recovery Room & Photo Waste Room

Hazardous wastes derived from spent photographic developer and fixer solutions generated at the Newsday facility were handled or stored within the Former Silver Recovery Room and Former Photo Waste Room. The locations of the two rooms are shown on **Figure 5**. **Figure 6** shows the layout of the Former Silver Recovery Room. **Figures 7a, 7b and 8** show the two layouts of the Former Photo Waste Room. All silver recovery and waste processing equipment, including the holding tanks, had previously been removed from the two rooms. The Former Silver Recovery Room is currently occupied by a large air compressor, while the Former Photo Waste Room is utilized for the storage of fire extinguishers. Closure of the two rooms shall include decontamination and power washing of the floors, rinsate sampling, and subsurface soil sampling. Specific tasks include the following:

1. Remove and/or properly dispose of all equipment and wastes.
2. Decontaminate and power wash the floors. Contain and collect all decontamination rinse waters and fluids for characterization and proper disposal.

3. Collect one (1) rinsate sample from each room. The proposed rinsate sampling locations in the Former Silver Recovery Room and Former Photo Waste Room are shown on **Figures 6 and 8**, respectively. The rinsate sample shall be collected and analyzed according to the Rinsate Sample Collection Protocol, the Closure Performance Standards as detailed in Section 2.2, and the site-specific Quality Assurance Project Plan (QAPP) provided in **Appendix A**. Should the sampling results exceed the Closure Performance Standards, decontamination of the floors will be repeated until subsequent confirmatory rinsate samples meet the standard.

4. Following completion of the rinsate sampling, one (1) soil boring will be advanced in each of the three former holding tank locations to sample and characterize subsurface soils below the floor slab. Since the tanks are no longer present, the soil boring locations will be approximated. The proposed soil boring locations are shown on **Figures 6 and 8**, and may be adjusted at the discretion of the NYSDEC representative on-site at the time of the closure investigation. The concrete floor shall be core drilled. Using a remote access Geoprobe® 420, or equivalent, direct-push drill rig, the soil borings will be advanced to a total depth of 8 feet below the floor slab. Representative soil samples shall be collected from depth intervals of 0-2, 2-4. 4-6 and 6-8 feet. Soils will be screened for lithology and screened with a portable photo-ionization detector (PID, MiniRAE 3000 or equivalent with a 10.6 eV lamp). The core holes will be backfilled and repaired with cement upon completion of the boring activity. Analytical sampling details are provided in the site-specific QAPP.

2.4.3 Ink Recovery Room

Ink waste is derived from the cleaning of the presses at the end of each day's press run. The waste is collected in pails and transferred to 55-gallon drums stored in the Ink Recovery Room. The location of the Ink Recovery Room on the second floor of the facility is shown in **Figure 9**. Closure of The Ink Recovery Room shall include decontamination and power washing of the floors, and collecting rinsate samples. Specific tasks include the following:

1. Remove and/or properly dispose of all equipment and wastes.

2. Decontaminate and power wash the floors. Contain and collect all decontamination rinse waters and fluids for characterization and proper disposal.

3. Collect two (2) rinsate samples from the recovery equipment area and two (2) rinsate samples from the drum storage area. The proposed rinsate sampling locations are shown on **Figure 9**. The rinsate sample shall be collected and analyzed according to the Rinsate Sample Collection Protocol, the Closure Performance Standards as detailed in Section 2.2, and the site-specific QAPP provided in **Appendix A**. Should the sampling results exceed the

Closure Performance Standards, decontamination of the floors will be repeated until subsequent confirmatory rinsate samples meet the standard.

2.4.4 Fixer, Developer, and Industrial Waste Piping

Waste piping throughout the facility included photographic fixer piping, photographic developer piping, and industrial waste piping. **Figures 10.1 to 10.5** highlight the fixer, developer and industrial waste piping throughout the entire facility. The photographic fixer waste stream contained entrained silver, while the photographic developer waste stream contained little or no entrained silver. The industrial waste stream includes the rinses from photographic developing operations and leads into the on-site sewage treatment plant. It is estimated that the fixer, developer and industrial waste piping each total approximately 1,000 feet of piping.

On April 24, 2018, three (3) 4- to 5-foot sections of the fixer piping were sampled in general accordance with the Rinsate Sample Collection Protocol. The piping was removed from three representative areas of the building, including the mail center, MER-1 room and the basement. Silty deposits were observed along the inside of the piping. In order to collect the rinsate samples, one end of each section of piping was capped utilizing a 3-inch rubber cap (i.e., Fernco). While situated in an empty 55-gallon drum, approximately 0.75 gallons of deionized water was then poured into the piping. Following a contact time of 10 minutes, the samples were transferred from the piping into laboratory-supplied sample bottles. An equipment blank was also collected by pouring the deionized water into the rubber cap. The rinsate samples were analyzed for TAL metals and VOCs. The sampling results are tabulated in **Tables 3.1 and 3.2** and compared with the NYSDEC 6 NYCRR Part 703.6 and TOGS 1.1.1 Groundwater Effluent Limitations (Class GA). The laboratory analytical report is provided as **Appendix D**. As shown in the tables, no VOCs were detected at concentrations above the Class GA Standards. Aluminum was detected in the Fixer Basement sample at a concentration of 3.21 mg/l, exceeding the Class GA Standard of 2 mg/l. Iron was detected in the Fixer MER-1 sample at a concentration of 11.7 mg/l, exceeding the Class GA Standard of 0.6 mg/l. Based on these sampling results, decontamination of the sections of piping in the basement and MER-1 room is necessary. Subsequent rinsate sampling will also be performed.

An additional seventeen (17) representative sections of piping throughout the building will be removed and sampled, as necessary. Visual inspections of the interior of the piping will be conducted in order to determine whether additional rinsate sampling is necessary. If the interior of the piping is observed to show significant differences in comparison to the three sections of fixer piping that were sampled, such as quantity, texture, odor, or discoloration of the silty deposits, the piping will be sampled and analyzed. If the silty deposits are observed to be similar, a sample will not be collected. Sampling and analysis will be performed in general accordance with the Rinsate Sample Collection Protocol, the Closure Performance Standards as detailed in Section 2.2, and the site-specific QAPP provided in **Appendix A**. Should the

sampling results exceed the Closure Performance Standards, decontamination of the piping will be repeated until subsequent confirmatory rinsate samples meet the standard.

In addition, the seventeen sections of piping will also be inspected to determine if sufficient material can be scraped from the interior deposits to analyze for TCLP metals. Should there be sufficient material, a sample will be collected from the piping section. If there is not sufficient material, then no sample will be collected. The samples will be analyzed for TCLP metals via EPA Method 1131/6010. The sampling results will be compared with the TCLP Limits identified in 6 NYCRR Part 371.3(e) in order to determine whether the piping is characterized as non-hazardous or hazardous. Should the sampling results exceed the TCLP Limits, the hazardous sections of piping will be removed and properly disposed of in accordance with federal, state and local regulations. If the sampling results indicate that the piping is non-hazardous, the piping will be left in place and handled as C&D debris during future building demolition or renovation**.**

3.0 CLOSURE CERTIFICATION

Following completion of the closure activities identified herein, a Closure Certification Report will be prepared to document all procedures and the results of sampling and analysis. The Closure Certification Report will be signed by the owner or operator and an independent licensed Professional Engineer, and submitted to the NYSDEC for approval. The proposed outline for the Closure Certification Report is provided below:

1.0 GENERAL INFORMATION
- 1.1 Location and Facility Description
- 1.2 Scope
- 1.3 Process Operations

2.0 CLOSURE ACTIVITIES

3.0 CLOSURE PROCEDURES

4.0 SAMPLING PROGRAM
- 4.1 Sampling Objective
- 4.2 Sampling Methodology
- 4.3 Sampling Results
- 4.4 Quality Assurance/Data Validation

4.0 CLOSURE PERFORMANCE GUIDELINES


6.0 ENGINEER'S CERTIFICATION

7.0 FACILITY OWNER'S CERTIFICATION

4.0 CLOSURE SCHEDULE


Closure of the Newsday facility is expected to require approximately eight weeks for completion. This includes two weeks for closure activity, four weeks for confirmatory sample analysis, and two weeks for reporting. If the confirmatory sampling results indicate that additional closure activities are required (i.e., additional decontamination, piping removal, etc.), then the closure schedule will be revised at that time.

FIGURES



CLIENT **NEWSDAY** **235 PINELAWN ROAD** **MELVILLE, NY 11747**	**Figure 1: Site Location Map** SCALE: **1" = 3280'** N	PROJECT NEWD1□03 DATE: **MAY 2018**	H2M architects + engineers Melville, NY · Albany, NY New City, NY · Parsippany, NJ

X:\NEWD (Newsday) - 44530\2018\NEWD1803 - (RCRA Closure)\02-BIM-CADD\env\Fig 1.Site Location Map_LW.dwg Last Modified: May 25, 2018 - 4:30pm Plotted on: May 25, 2018 - 4:31pm By lwu



REFERENCE: NEWSDAY SITE PLAN 04/19/08

Client

Newsday

235 Pinelawn Road, Melville, NY 11747
RCRA Closure


SHEET #
Figure 2


DATE:
MAY 2018

Facility Site Plan


NEWD1803

H2M architects + engineers


Overhead Transmission Lines
N85°52'15"E 985.10'
E.M.H.#2
T.M.H.#2
T.M.H.#3
E.M.H.#3
E.M.H.#4
L.B.#27-15'-10"Φ
R=108.5
L.B.#26-15'-10"Φ
R=108.5
1/8 Bend
10" D.I.
L.B.# 15-8'-10"Φ
R=109.3
L.B.# 16-15'-10"Φ
R=109.3
L.B.#11-15'
L.B.#7-15'
L.B.#8-15'
L.B.#9-15'-10"Φ
L.B.#10-15'
L.B.#6-8'-10"Φ
R=107.6
62.5'
22.5'
52.5'
50'
27.5'
32.5'
Areaway Drain
For Details See Dwg C-3
For Location See Dwg
3011-4-S17 & Dwg 3011-4-M52
Trea-Way
New 4-5" electrical conduit
in 18"x18" concrete envelope
For details see electrical dwgs.
L.B.#17-8'-10"Φ
R=109.1
L.B.#18-8'-10"Φ
R=109.1
L.B.#12-15'
L.B.#19-15'
L.B.#25-8'-10"Φ
R=109.3
L.B.# 43-15'
R=105.2
L.B.#42-15'
L.B.# 41-15'
R=105.2
L.B.# 40-15'
1/8" Bends
1/16' min. (typ.)
Concrete Slab
Cleanout
See Dwg C-3
Gate Valves
L.B.# 39-15'
R=105.4
L.B.# 38-15'
R=105.4
6" CT SSP
Underground
Solvent Storage Tank
See Dwg. C-4.
L.B.# 36-15'
R=105.6
Gate Valves
L.B.# 35-15'
R=105.7
L.B.# 34-15'
R=106.4
L.B.#33-8'-10"Φ
R=106.5
Fixer and Developer
Underground Waste
Storage Tank
The minimum distance between all pipes where they cross shall be 18".
Encase the Sewer and Industrial Lines with 6" of concrete for a distance of 12' feet where the Waste Lines cross over the Fire Protection Water
See Dwg C-5
For piping continuation and location, see mechanical drawings
L.B.#3-15'
L.B.#29-15'
R=106.5
L.B.#5-15'
L.B.#4-15'
L.B.#30-15'
R=106.5
TWLB#2-10'
R=106.6
TWLB#1-10'
R=106.5
L.B.#32-15-10Φ
R=106.1
L.B.#31-15-10Φ
Drop Inlet #1
R=106.1
Drop Inlet #2
R=106.1
Drop Inlet #3
R=105.7
12" RCP
8" Bends
1/4" Bend
L.B.#20-15'
L.B.#21-8'-10"Φ
R=108.0
L.B.#22-8-10'Φ
R=107.7
L.B.#23-15'
R=108.6
L.B.#1-15'
R=106.8
L.B.#2-15'
R=106.8
L.B.#
R=105-15'
Gate Valve
10" CI
8" DI
6" DI
6" AC
8" VC
6" CI SSP
Vent (SSP)
F.P.
DW
S
I=104.0
I=101.0
I=107.0
I=104.8
I=98.9
I=102.6
I=100.1
I=103.5
I=107.0
I=104.8
I=101.8
I=102.7
I=104.3
I=109.5
I=108.5
I=103.5
I=104.3
I=104.1
I=104.1
I=104.1



REFERENCE: A-4 "BASEMENT AND SECOND FLOOR PLAN" PREPARED HENRY LOHEAC 07/02/91



REFERENCE: A-8 "STAIR DETAILS AND FLOOR SCHEDULES" PREPARED HENRY LOHEAC 07/02/91

ISSUED FOR CONSTRUCTION DATE 5-23-91

Client


Newsday
235 Pinelawn Road, Melville, NY 11747
RCRA Closure

SHEET # Figure 4

DATE: MAY 2018

Basement Boiler Expansion Floor Plan and Wall Section
NEWD1803

H2M architects + engineers



Former Photo Waste Room

Former Silver Recovery Room

REFERENCE: NEWSDAY MELVILLE BUILDING BASEMENT 04/19/08

Client

Newsday

235 Pinelawn Road, Melville, NY 11747
RCRA Closure


SHEET #
Figure 5

DATE:
MAY 2018

Locations of Former Silver Recovery & Photo Waste


NEWD1803

H2M architects + engineers




*NOT TO SCALE
REFERENCE: HAZARDOUS WASTE GENERATION, STORAGE FACILITY AND OPERATION CONTINGENCY DETAIL 2 PAGE 15

Client	SHEET #		
Newsday **235 Pinelawn Road, Melville, NY 11747** **RCRA Closure**	**Figure 6**	**PROPOSED SAMPLING OF FORMER SILVER RECOVERY ROOM**	H2M architects + engineers
	DATE: **MAY 2018**	**NEWD1803**	




REFERENCE: NEWSDAY "PHOTOGRAPHIC WASTEWATER STORAGE TANKS" SHEET 1, DATED JULY 1988

Client **Newsday** **235 Pinelawn Road, Melville, NY 11747** **RCRA Closure**	**SHEET #** **Figure 7a** **DATE:** **MAY 2018**	**FIRST LAYOUT OF FORMER PHOTO WASTE ROOM (PLAN VIEW)** **NEWD1803**	H2M architects + engineers



REFERENCE: SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES APPROVAL TO CONSTRUCT, DATED DECEMBER 1988, APPROVED AUGUST 1989

Client	SHEET #		
Newsday 235 Pinelawn Road, Melville, NY 11747 RCRA Closure	Figure 7b DATE: MAY 2018	**FIRST LAYOUT OF FORMER PHOTO WASTE ROOM (SECTION VIEW)** NEWD1803	H2M architects + engineers



(2) 55 GAL DEVELOPER CANISTERS = 110 GALS
(4) 25 GAL STEEL WOOL CANISTERS = 100 GALS
(2) 60 GAL LIQUID METERING STATIONS (LMS) = 120 GALS
(1) 50 GAL PUMPING STATION = 50 GALS
(1) 50 GAL FIXER TANK = 50 GALS
(1) 250 GAL PHOTO WASTE TANKS = 250 GALS
(1) 500 GAL PHOTO WASTE TANKS = 500 GALS
(3) 15 GAL SILVER PROCESSORS = 45 GALS
TOTAL TANK CAPACITY = 1225 GALS

SCDHS BERM COMPLIANCE

11.5 FT X 13 FT X 1.5 FT = 224.25 cuFT
224.25 cuFT X 7.48 GAL/cuFT = 1677 GAL
1225 X 1.10 = 1347.5 GALS
1677GAL(BERM) > 1347.5 GAL(TANKS & 110%)

*NOT TO SCALE
REFERENCE: NEWSDAY ENGINEERING "PHOTO WASTE TX TANK PLAN" SHEET 3, DATED NOVEMBER 2001

Client

Newsday

235 Pinelawn Road, Melville, NY 11747
RCRA Closure


SHEET #
Figure 8


DATE:
MAY 2018

SECOND LAYOUT OF FORMER PHOTO WASTE ROOM & PROPOSED SAMPLING

NEWD1803

H2M architects + engineers





REFERENCE: NEWSDAY "MELVILLE BUILDING SECOND FLOOR" 04/19/08

Client


Newsday
235 Pinelawn Road, Melville, NY 11747
RCRA Closure

SHEET #
Figure 9

DATE:
MAY 2018

Proposed Sampling of Ink Recovery Room
NEWD1803

H2M architects + engineers



Client

Newsday
235 Pinelawn Road, Melville, NY 11747
RCRA Closure


SHEET #
Figure 10.1

DATE:
MAY 2018


BASEMENT OFFICE PIPING

NEWD1803

H2M architects + engineers



Client **Newsday** 235 Pinelawn Road, Melville, NY 11747 RCRA Closure	SHEET # **Figure 10.2**	**FIRST FLOOR (UNDER FLOOR) OFFICE PIPING** NEWD1803	H2M architects + engineers
	DATE: **MAY 2018**		



19	7/11	PTS DEMOLITION	DL
18	4/10	DEP INSTALL / CAPTAIN TYP	DL
17	4/10	ROSMATIC TO INSTALL	DL
16	10/09	ADDED SCANLE PROPOSE LINE	
15	7/09	CONSTR. REVISION EN #51	
14		CONSTRUCTION REVISION EN #	
13	8/08	CONSTRUCTION REV. EN # 71	
12	8/08	CONSTRUCTION REV EN # 59	
11	8/08	CONSTRUCTION REV. EN # 55	
10	9/07	CONSTRUCTION REVISION EN # 45	
9	4/07	CONSTRUCTION REVISION EN # 40	
8	8/06	CONSTRUCTION REV. EN # 41	
7	4/06	CONSTRUCTION REV EN # 32	
6	8/05	CONSTRUCTION REV. EN # 36	
5	7/05	CONSTRUCTION REV EN-30	
4	8/04	CONSTRUCTION REVISION E.N. # 24	
3	12/11/03	BSD DEPT REVIEW	
2	11/10/03	ISSUED FOR CONSTRUCTION (& HVAC RADIATION) EN # 20	
1	12/5/03	ISSUED FOR BIDS EN # 18	

NO. DATE DESCRIPTION

DRAWN BY J. LOTTERO | CHECKED BY
DESIGN SUPV. H. GILMAN | RESP. ENGR.
SUPV. DISC. ENGR. J. JACOBS | CH. DISC. ENGR.
PROJECT ENG. MGR.
PROJECT MGR. G.F. GROGAN
IN CHARGE D.W. LEWIS

MAIN Engineers
CHAS. T. MAIN of NEW YORK, INC.
BOSTON · CHARLOTTE · DENVER · PORTLAND


CLIENT/PROJECT TITLE
NEWSDAY, INC.
NEWSPAPER PLANT
MELVILLE, NEW YORK

DEPT. NO.

DRAWING DESCRIPTION
MECHANICAL
FIRST FLOOR
OFFICE PIPING
& RADIATION SHEET 1

SCALE 1/8"=1'-0"
MAIN'S DWG. NO. 3011-4-M 14 REV. 19
CLIENT'S DWG. NO.

Client	**Newsday** 235 Pinelawn Road, Melville, NY 11747 RCRA Closure
SHEET #	**Figure 10.3**
DATE:	**MAY 2018**
	FIRST FLOOR OFFICE PIPING (SHEET 1 OF 2) NEWD1803
	H 2 M architects + engineers



Client

Newsday

235 Pinelawn Road, Melville, NY 11747
RCRA Closure


SHEET #
Figure 10.4

DATE:
MAY 2018

FIRST FLOOR OFFICE PIPING (SHEET 2 OF 2)

NEWD1803

H2M architects + engineers


SECOND FLOOR PLAN
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
SECTION
DETAIL
DIAGRAM
NO SCALE
G
A
F
E
SINK N.I.C.
LAVA
DISHWASHER N.I.C.
WC'B'
LAV 'B'
SHOCK ABSORBER
TEMPERING VALVE
TYPE 'J' SINK
RELOCATE EYEWASH-TYPE 'B'
EXIST. SINK FROM PHOTO DEPT.
GENERAL WORK AREA - PROVIDE DRILLING TO SUIT SERVICES INDICATED
WASHER (BY OWNER)
SIMPLEX PROCESSOR
PROVIDE HUBS FLUSH WITH FL.
TRAP PRIMER VALVE PRECISION PLUMBING PRODUCTS MODEL P-2, 2 REQ'D, MOUNT ABOVE TRAP LEVEL
FISCHER & PORTER 10F1020 SERIES (IMPACT TUBE FLOW RATE INDICATOR)
HOSE CONNECTION
PLUG VALVE
FLOOR
KEY PLAN
NO SCALE
LASER VALVE CONTROL STATION
EXISTING MIXING VALVE (4-UNITS ONLY) NEW MIXING VALVE (1-UNIT)
EXISTING WATER FILTERS (4-UNITS ONLY) NEW WATER FILTER (1-UNIT)
TO FIX TANK (PAKONO LITH ONLY) TO WASH TANK (PAKOQUICK ONLY)
TO DEVELOPER TANK (PAKONOLITH ONLY)
PAKOQUICK/ PAKONOLITH
PAKONOLITH ONLY
3"- DRAINS
MATCH LINE SEE DWG M20
CEILING
INSIDE FACE OF WALL
ESCUTCHEON PLATES @ CEILING
EXISTING SINK FROM PHOTO DEPT. SEE DETAIL 'B'
TYPE 'B' EYEWASH (NOT TYPICAL)
PAKOQUICK
NEWSPAGER
1284
1289
1273
1272
1279
1283
1255
1268
1271
1247
1287
1210
1211
1212
1213
1214
1215
1216
1217
1218
1219
1220
1221
1222
1223
1224
1225
1226
1227
1228
1229
1230
1231
1232
1233
1234
1235
1236
1237
1238
1239
1240
1241
1242
1243
1244
1245
1246
1247
1248
1249

TABLES

Newsday - 235 Pinelawn Road, Melvile, NY

Table 3.1 - Fixer Piping Sampling Results for Metals - April 24, 2018

Sample ID:	6 NYCRR Part 703.6[1] & TOGS 1.1.1[2] Class GA Standards	Fixer Mail Center		Fixer MER-1		Fixer Basement		Equip Blank	
Sample Date:		4/24/2018		4/24/2018		4/24/2018		4/24/2018	
Lab Sample ID:		1804167-002		1804167-003		1804167-004		1804167-001	
Units:	(mg/l)	(mg/l)		(mg/l)		(mg/l)		(mg/l)	
Metals									
Mercury	0.0014	0.00021	J	0.00019	J	0.00017	J	0.00023	J
Aluminum	2	0.0759		0.266		3.21		0.0262	
Antimony	0.006	0.005	U	0.005	U	0.005	U	0.005	U
Arsenic	0.05	0.01	U	0.01	U	0.01	U	0.01	U
Barium	2	0.0265		0.0241		0.0278		0.0261	
Beryllium	0.003	0.005	U	0.005	U	0.005	U	0.005	U
Cadmium	0.01	0.005	U	0.005	U	0.005	U	0.005	U
Calcium	-	2.67		2.04		2.61		2.57	
Chromium	0.1	0.005	U	0.005	U	0.005	U	0.005	U
Cobalt	-	0.005	U	0.005	U	0.005	U	0.005	U
Copper	0.4	0.0346		0.0296		0.00631	J	0.028	
Iron	0.6	0.273		11.7		0.145		0.107	
Lead	0.05	0.005	U	0.005	U	0.005	U	0.0122	J
Magnesium	35	0.574		0.598		0.528		0.617	
Manganese	0.6	0.00537	J	0.031		0.00813	J	0.00594	J
Nickel	0.2	0.005	U	0.00408	J	0.00427	J	0.005	U
Potassium	-	0.0771	J	0.895		0.296		0.0741	J
Selenium	0.02	0.01	U	0.01	U	0.01	U	0.01	U
Silver	0.1	0.005	U	0.0221		0.005	U	0.005	U
Sodium	-	0.28		5.01		4.5		0.457	
Thallium	0.0005	0.01	U	0.01	U	0.01	U	0.01	U
Vanadium	-	0.005	U	0.005	U	0.005	U	0.005	U
Zinc	5	0.101		0.0321		0.13		0.0764	

Notes:

(1) 6 NYCRR Part 703.6 Groundwater effluent limitations for discharges to Class GA waters, Table 3 Groundwater Effluent Limitations Class GA.

(2) TOGS 1.1.1 Ambient Water Quality Standards and Guidance Values and Groundwater Effluent Limitations, Table 5 NYS Groundwater Effluent Limitations (Class GA).

Qualifiers:

J: The reported value was obtained from a reading that was less than the Limit of Quantitation but greater than or equal to the Limit of Detection Limit (LOD).

U: The analyte was analyzed for but not detected at or above the LOD.

Newsday - 235 Pinelawn Road, Melvile, NY

Table 3.2 - Fixer Piping Sampling Results for VOCs - April 24, 2018

Sample ID:	6 NYCRR Part 703.6[1] & TOGS 1.1.1[2] Class GA Standards	Fixer Mail Center		Fixer MER-1		Fixer Basement		Equip Blank	
Sample Date:		4/24/2018		4/24/2018		4/24/2018		4/24/2018	
Lab Sample ID:		1804167-002		1804167-003		1804167-004		1804167-001	
Units:	(ug/l)	(ug/l)		(ug/l)		(ug/l)		(ug/l)	
Volatile Organic Compounds									
1,1,1,2-Tetrachloroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1,1-Trichloroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1,2,2-Tetrachloroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1,2-Trichloro-1,2,2-trifluoroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1,2-Trichloroethane	1	0.25	U	0.25	U	0.25	U	0.25	U
1,1-Dichloroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1-Dichloroethene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,1-Dichloropropene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,2,3-Trichlorobenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,2,3-Trichloropropane	0.04	0.25	U	0.25	U	0.25	U	0.25	U
1,2,4,5-Tetramethylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,2,4-Trichlorobenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,2,4-Trimethylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,2-Dibromo-3-chloropropane	0.04	0.03	U	0.03	U	0.03	U	0.03	U
1,2-Dibromoethane	0.0006	0.25	U	0.25	U	0.25	U	0.25	U
1,2-Dichlorobenzene	3	0.25	U	0.25	U	0.25	U	0.25	U
1,2-Dichloroethane	0.6	0.25	U	0.25	U	0.25	U	0.25	U
1,2-Dichloropropane	1	0.25	U	0.25	U	0.25	U	0.25	U
1,3,5-Trimethylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
1,3-Dichlorobenzene	3	0.25	U	0.25	U	0.25	U	0.25	U
1,3-dichloropropane	5	0.25	U	0.25	U	0.25	U	0.25	U
1,4-Dichlorobenzene	3	0.25	U	0.25	U	0.25	U	0.25	U
1,4-Dioxane	-	0.25	U	0.25	U	0.25	U	0.25	U
2,2-Dichloropropane	5	0.25	U	0.25	U	0.25	U	0.25	U
2-Butanone	50	0.5	U	0.5	U	0.5	U	0.5	U
2-Chloroethyl vinyl ether	-	0.25	U	0.25	U	0.25	U	0.25	U
2-Chlorotoluene	5	0.25	U	0.25	U	0.25	U	0.25	U
2-Hexanone	50	0.5	U	0.5	U	0.5	U	0.5	U
2-Propanol	-	0.25	U	0.25	U	0.25	U	0.25	U
4-Chlorotoluene	5	0.25	U	0.25	U	0.25	U	0.25	U
4-Isopropyltoluene	5	0.25	U	0.25	U	0.25	U	0.25	U
4-Methyl-2-pentanone	-	0.5	U	0.5	U	0.5	U	0.5	U
Acetone	50	5	U	5	U	5	U	5	U
Benzene	1	0.25	U	0.25	U	0.25	U	0.25	U
Bromobenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Bromochloromethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Bromodichloromethane	50	0.25	U	0.25	U	0.25	U	0.25	U
Bromoform	50	0.25	U	0.25	U	0.25	U	0.25	U
Bromomethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Carbon disulfide	60	0.25	U	0.25	U	0.25	U	0.25	U
Carbon tetrachloride	5	0.25	U	0.25	U	0.25	U	0.25	U
Chlorobenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Chlorodifluoromethane	-	0.25	U	0.25	U	0.25	U	0.25	U
Chloroethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Chloroform	7	0.25	U	0.25	U	0.25	U	0.25	U
Chloromethane	5	0.25	U	0.25	U	0.25	U	0.25	U
cis-1,2-Dichloroethene	5	0.25	U	0.25	U	0.25	U	0.25	U
cis-1,3-Dichloropropene	0.4	0.25	U	0.25	U	0.25	U	0.25	U
Cyclohexane	-	0.25	U	0.25	U	0.25	U	0.25	U
Dibromochloromethane	50	0.25	U	0.25	U	0.25	U	0.25	U
Dibromomethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Dichlorodifluoromethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Diisopropyl ether	-	0.5	U	0.5	U	0.5	U	0.5	U
Ethanol	-	2.5	U	2.5	U	2.5	U	2.5	U
Ethylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Freon-114	-	0.25	U	0.25	U	0.25	U	0.25	U
Hexachlorobutadiene	0.5	0.25	U	0.25	U	0.25	U	0.25	U
Isopropylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
m,p-Xylene	5	0.5	U	0.5	U	0.5	U	0.5	U
Methyl Acetate	-	0.25	U	0.25	U	0.25	U	0.25	U
Methyl tert-butyl ether	10	0.25	U	0.25	U	0.25	U	0.25	U
Methylene chloride	5	5	U	5	U	5	U	5	U
n-Butylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
n-Propylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Naphthalene	10	0.25	U	0.25	U	0.25	U	0.25	U
o-Xylene	5	0.25	U	0.25	U	0.25	U	0.25	U
p-Diethylbenzene	-	0.25	U	0.25	U	0.25	U	0.25	U
p-Ethyltoluene	-	0.25	U	0.25	U	0.25	U	0.25	U
sec-Butylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Styrene	5	0.25	U	0.25	U	0.25	U	0.25	U
t-Butyl alcohol	-	2.5	U	2.5	U	2.5	U	2.5	U
tert-Butylbenzene	5	0.25	U	0.25	U	0.25	U	0.25	U
Tetrachloroethene	5	0.25	U	0.25	U	0.25	U	0.25	U
Toluene	5	0.28	J	0.3	J	0.25	U	0.25	U
trans-1,2-Dichloroethene	5	0.25	U	0.25	U	0.25	U	0.25	U
trans-1,3-Dichloropropene	0.4	0.25	U	0.25	U	0.25	U	0.25	U
Trichloroethene	5	0.25	U	0.25	U	0.25	U	0.25	U
Trichlorofluoromethane	5	0.25	U	0.25	U	0.25	U	0.25	U
Vinyl acetate	-	0.25	U	0.25	U	0.25	U	0.25	U
Vinyl chloride	2	0.25	U	0.25	U	0.25	U	0.25	U
Xylenes, Total	5	0.75	U	0.75	U	0.75	U	0.75	U
Acrolein	5	1	U	1	U	1	U	1	U
Acrylonitrile	5	0.25	U	0.25	U	0.25	U	0.25	U

Notes:

(1) 6 NYCRR Part 703.6 Groundwater effluent limitations for discharges to Class GA waters, Table 3 Groundwater Effluent Limitations Class GA.

(2) TOGS 1.1.1 Ambient Water Quality Standards and Guidance Values and Groundwater Effluent Limitations, Table 5 NYS Groundwater Effluent Limitations (Class GA).

Qualifiers:

J: The reported value was obtained from a reading that was less than the Limit of Quantitation but greater than or equal to the Limit of Detection Limit (LOD).

U: The analyte was analyzed for but not detected at or above the LOD.

APPENDIX A

QUALITY ASSURANCE PROJECT PLAN (QAPP)

QUALITY ASSURANCE PROJECT PLAN (QAPP)

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK 11747

JULY 18, 2018, REV 1

Prepared for:

Newsday LLC
235 Pinelawn Road
Melville, New York 11747

Prepared by:

H2M architects + engineers
290 Broad Hollow Road, Suite 400E
Melville, New York 11747

H2M Project No.: NEWD1803

H 2 M architects + engineers

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

QUALITY ASSURANCE PROJECT PLAN (QAPP)

JULY 18, 2018, REV 1

TABLE OF CONTENTS

Page

1.0 PROJECT DESCRIPTION 1

2.0 PROJECT ORGANIZATION AND RESPONSIBILITY 2

3.0 QA OBJECTIVES FOR DATA MEASUREMENT 3

4.0 FIELD SAMPLING 3

4.1 Sampling Methodology 3
4.1.1 Floor Rinsate Sampling 3
4.1.2 Soil Sampling 4
4.1.3 Piping Rinsate Sampling 4
4.1.4 Sampling Equipment Decontamination and Waste Characterization 5
4.2 Sampling Plan 5
4.2.1 Floor Rinsate Sampling 5
4.2.2 Soil Sampling 6
4.2.3 Piping Rinsate Sampling 6

5.0 DOCUMENTATION AND CUSTODY 7

5.1 Sample Containers 7
5.2 Sample Preservation 8
5.3 Preparation of Sample Bottles and Coolers 8
5.4 Custody Transfer to Field Personnel 8
5.5 Custody Transfer to Laboratory 9

6.0 QUALITY ASSURANCE/QUALITY CONTROL (QA/QC) SAMPLES 9

6.1 Blanks 10
6.2 Duplicate Samples 10
6.3 Matrix Spiked Samples 11

7.0 ANALYTICAL PROCEDURES AND LABORATORY TESTING 11

7.1 Analytical Laboratory 11

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

QUALITY ASSURANCE PROJECT PLAN (QAPP)

JULY 18, 2018, REV 1

TABLE OF CONTENTS

Page

7.2 Sample Analysis 11

8.0 CALIBRATION PROCEDURES 12

8.1 Calibration Practices 12
8.2 Calibration Frequency 12
8.3 Calibration Reference Standards 12
8.4 Calibration Failure 13
8.5 Calibration Records 13

9.0 DATA REDUCTION, VALIDATION AND REPORTING 13

9.1 Data Reduction 13
9.2 Data Validation 14
9.3 Data Reporting 14

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

QUALITY ASSURANCE PROJECT PLAN (QAPP)

JULY 18, 2018, REV 1

LIST OF FIGURES

FIGURE 1 SITE LOCATION MAP

FIGURE 2 FACILITY SITE PLAN

FIGURE 3 ORGANIZATION CHART FOR FIELD SAMPLING AND ANALYSIS PROGRAM

LIST OF TABLES

TABLE 7.2.1 ANALYTICAL METHODS/QUALITY ASSURANCE SUMMARY

TABLE 7.2.2 SOIL MATRIX ANALYSIS REQUIREMENTS AND METHODS

TABLE 7.2.3 ANALYTICAL METHODS/QUALITY ASSURANCE SUMMARY

APPENDICES

APPENDIX A RINSATE SAMPLE COLLECTION PROTOCOL

APPENDIX B QC LIMITS FOR SPIKING AND SURROGATE COMPOUNDS

APPENDIX C RESUME OF MS. NANCY POTAK (THIRD PARTY DATA VALIDATOR)

NEWSDAY LLC
235 PINELAWN ROAD
MELVILLE, NEW YORK

QUALITY ASSURANCE PROJECT PLAN (QAPP)

JULY 18, 2018, REV 1

1.0 PROJECT DESCRIPTION

H2M architects + engineers (H2M) has prepared this Quality Assurance Project Plan (QAPP) to address sampling activities to be performed as part of the RCRA Closure of the Newsday LLC facility located at 235 Pinelawn Road in Melville, New York.

This QAPP presents procedures to be followed during the sampling and analysis program as well as project organization and personnel responsibilities necessary to carry out these practices. Quality Assurance / Quality Control (QA/QC) and data validation requirements are also summarized in this plan. The closure of the facility will be performed in accordance with a New York State Department of Environmental Conservation (NYSDEC)-approved RCRA Closure Plan.

Operations at the Newsday facility include printing, publishing, preparing and distributing a daily newspaper edition and limited contract printing. The facility is bounded to the east by Pinelawn Road, to the north by Ruland Road, to the west by Deshon Drive, and to the South by a private service road. Properties surrounding the facility include undeveloped land to the north, Clare Rose Distributor to the south, Pinelawn Cemetery to the east, and Town Apartments to the west. A site location map is provided as **Figure 1** and facility site plan is provided as **Figure 2.**

Regulated wastes were generated at the Newsday facility as part of routine printing operations. All hazardous wastes were stored and disposed of in accordance with local, state and federal regulations. Hazardous wastes primarily included ink waste, spent photographic developer and spent photographic fixer. The ink waste is containerized in 55-gallon drums stored in the Ink Recovery Room. Spent photographic developer and fixer solutions drained into holding tanks located in the Former Silver Recovery and Photo Waste Rooms where they were processed through silver recovery equipment. The processed developer and fixer mixture was then pumped into a 4,000-gallon fiberglass underground storage tank, which was subsequently replaced by two (2) 2,000-gallon polyethylene aboveground storage tanks. Following decommissioning of the storage tanks, the developer and fixer waste was eventually discharged to the on-site wastewater treatment plant.

2.0 PROJECT ORGANIZATION AND RESPONSIBILITY

H2M, a professional engineering corporation, has been retained by Newsday for the oversight of the RCRA Closure of the Newsday facility including providing for all sampling services. An organizational chart for the closure activities and field investigation program is provided as **Figure 3**.

For projects involving a field investigation program, a project team is assembled with each team member responsible for specific elements of the work. To ensure that every project is completed with the highest degree of quality, each member of the project team must be aware of the quality assurance objectives for his/her specific element of the work.

As indicated in **Figure 3**, the Principal-in-Charge is the direct contact between the consultant and the client. The Principal-in-Charge is responsible for overall project technical direction and quality assurance, including:

- Defining project objectives;
- Allocation of resources;
- Establishing chains of command; and
- Periodic evaluation of project.

The consultant's Project Manager is responsible for directing and overseeing all technical and administrative elements of the project. This includes:

- Day to day direction, communication and coordination with the project team;
- Review of all project documents;
- Monitoring overall work progress, schedules, project costs; and
- Day to day direction of QA/QC activities.

Reporting directly to the Project Manager is the Field Team Supervisor, who is responsible for directing all field investigation activities. Depending upon the specific project requirements, the field investigation/sampling work is carried out by staff engineers, geologists, hydrogeologists, wetlands specialists, wildlife specialists and/or field technicians.

The Field Team Supervisor is responsible for ensuring that the work performed by the field investigation staff is carried out in a manner consistent with the project QA requirements. Project QA requirements are specified by the NYSDEC and/or the approved closure plan. The Field Team Supervisor is also responsible for direction and coordination of subcontractors, which may be utilized for surveying, drilling and geophysical investigations, and acts as an intermediary between the field staff and the analytical laboratory.

The Quality Assurance Officer (QAO) operates independently of the Project Manager, reporting directly to the Principal-in-Charge. The primary responsibilities of the QAO are as follows:

- Assist in the development of the work plan and evaluate its effectiveness;
- Monitor work to ensure conformance with the requirements of the work plan;
- Evaluate the need for and, if necessary, conduct field and laboratory QA audits;
- Supervise data validation and review all report deliverables.

3.0 QA OBJECTIVES FOR DATA MEASUREMENT

The primary aim of this plan is to establish the procedures to be followed by project personnel when conducting field sampling and analysis. Quality assurance requires careful planning, organization and the dedication of every member of the firm to the concepts of QA/QC. This must be accompanied by the understanding and coordination of the roles of all personnel involved in a particular project, if this quality objective is to be met. The overall QA objective for the closure sampling and analysis associated with the Newsday buildings is to produce data at the highest level to provide direct support for determining the environmental quality of the areas in question.

4.0 FIELD SAMPLING

The field sampling plan associated with the closure of the Newsday facility is anticipated to include the collection and analysis of rinsate samples and subsurface soil samples in the areas where hazardous wastes were handled and stored including the Former Silvery Recovery Room, Former Photo Waste Room and the Ink Recovery Room. Waste piping throughout the facility, including the photographic fixer piping, photographic developer piping and industrial waste piping, will also be visually inspected and sampled, as necessary. The purpose of sampling is to document that no hazardous materials remain following facility closure.

4.1 Sampling Methodology

4.1.1 Floor Rinsate Sampling

Following decontamination of the floors, rinsate sampling will be conducted. The rinsate sampling will be performed in accordance with the Rinsate Sample Collection Protocol provided in **Appendix A**. Rinsate samples will be collected by placing deionized water in contact with the subject surface. A temporary containment area will be created on the surface at the designated sampling area using an inert, pre-cleaned sampling container. Deionized water will then be poured into this temporary collection area. The volume of deionized water will be sufficient to collect all the sample and QC parameters. If the designated sampling area is sloped, the deionized water will be poured starting at the highest elevation. Following a contact time of 10 minutes, the samples will be collected from the temporary collection area using a peristaltic pump

and new dedicated sample tubing, or by an equivalent method. Field personnel will transfer the samples directly into dedicated containers provided by the analytical laboratory. The samples will be transferred to the sample containers with minimal mixing and disruption since the laboratory analysis will include volatile organic compounds (VOCs). The sample containers required for VOC analysis will be filled so that there is no headspace in the sample container. Water sample containers for VOCs will be sealed with Teflon lined septum caps.

4.1.2 Soil Sampling

Soil borings and subsurface soil sampling will be conducted utilizing direct-push sampling methods in accordance with American Society for Testing and Materials (ASTM) D6282-98, Standard Guide for Direct Push Soil Sampling for Environmental Site Characterizations. A remote access Geoprobe® 420, or equivalent, unit will be employed in conjunction with 2-inch outside diameter (OD) cylindrical "macro-core" barrels. The core barrels, fitted with a cutting shoe, will be advanced with a hydraulic drive hammer into the ground to the desired sampling depth. The macro-core sampler will extract samples into the barrel fitted with an acetate liner. As the barrels are removed from the ground, the acetate liner will be removed to permit field screening, fill or soil classification and sample collection. Field screening will include an inspection for visual and olfactory evidence of contamination and field testing with a portable photoionization detector (PID, MiniRAE 3000 or equivalent with a 10.6 eV lamp).

Borings will be recorded by the on-site field personnel. Physical characteristics will be documented using preprinted boring log forms and will include the following:

- Project name, location and job number,
- Date of boring (start, finish),
- Boring number and driller,
- Sample number and depth,
- Method of advancing sampler,
- Type and size of sampler,
- Description of soil or fill,
- Thickness of observed layers,
- Type and make of equipment (i.e., drill rig, etc.) used, and
- Identification of any samples collected and submitted for laboratory analysis.

Subsurface boring descriptions will be made in accordance with the Unified Soil Classification System (USCS).

4.1.3 Piping Rinsate Sampling

Representative sections of the waste piping throughout the building will be removed and visually inspected. Based upon visual inspections, rinsate sampling of the piping will be conducted as necessary. If the interior of the piping is observed to show significant differences in comparison to the three sections of fixer piping that were sampled on April 24, 2018, the piping will be sampled. If the piping interior is observed to be

similar, a sample will not be collected. The rinsate sampling will be performed in general accordance with the Rinsate Sample Collection Protocol. One end of each section of piping will be capped utilizing an inert, pre-cleaned rubber cap (i.e., Fernco). Deionized water will then be poured into the piping. The volume of deionized water will be sufficient to collect all the sample and QC parameters. Following a contact time of 10 minutes, the samples will be transferred directly from the piping into laboratory-supplied bottleware.

In addition to rinsate sampling, the sections of piping will also be inspected to determine if sufficient material can be scraped from the interior deposits to analyze for TCLP metals. Should there be sufficient material, a sample will be collected from the piping section. If there is not sufficient material, then no sample will be collected.

4.1.4 Sampling Equipment Decontamination and Waste Characterization

All non-dedicated sampling equipment that requires re-use will be cleaned and decontaminated using the following procedure:

1) Detergent wash (e.g., Alconox®) and potable tap water rinse,
2) Double rinse with distilled deionized water.

All contaminated disposable field sampling equipment, decontamination fluids and rinse water will be collected and characterized for proper disposal.

4.2 Sampling Plan

All samples will be submitted to the analytical laboratory for analysis in accordance with NYSDEC ASP Category B protocols. As stated, hazardous wastes generated at the Newsday facility were handled or stored within the building in the Former Silver Recovery Room, Former Photo Waste Room, the Ink Recovery Room, and within the fixer, developer, and industrial waste piping. Closure of these areas shall include decontamination of the hazardous waste storage areas, rinsate sampling and subsurface soil sampling.

4.2.1 Floor Rinsate Sampling

Following sweeping, power washing and decontamination of the floor surfaces in these areas, a total of six rinsate samples will be collected, including one from the Former Silver Recovery Room, one from the Former Photo Waste Room, two from the recovery equipment area in the Ink Recovery Room and two from the drum storage area in the Ink Recovery Room. The exact locations of the rinsate samples will be determined in the field in coordination with the NYSDEC. Additional QA/QC samples, i.e., blank, duplicate and spike samples, will also be collected to satisfy the NYSDEC Category B standards for Data Quality Assessments. Rinsate samples will be analyzed for TAL metals/Hg and TCL VOCs + TICs. Sampling

results will be compared with the NYS Groundwater Effluent Limitations (Class GA), as identified in NYSDEC TOGS 1.1.1 or 6 NYCRR Part 703.6. Should the sampling results exceed the Class GA standards, decontamination of the floors will be repeated until subsequent confirmatory rinsate samples meet the Class GA standards.

4.2.2 Soil Sampling

Three (3) subsurface borings will be advanced in the three former holding tank locations in these areas to sample and characterize subsurface soils from below the floor slab to a depth of 8 feet. The former holding tanks included a 100-gallon polyethylene tank in the Former Silver Recovery Room, a 500-gallon HDPE and a 250-gallon HDPE tank in the Former Photo Waste Room. It is anticipated that the precise sampling location will be dictated by a NYSDEC representative on-site at the time of the closure investigation. The concrete floor, estimated to be 4-6 inches thick, shall be core drilled. As discussed in Section 4.1.2, a remote access direct-push drilling unit will be used to advance the subsurface borings to a total depth of 8 feet below the floor slab. Representative soil samples shall be collected from depth intervals of 0-2, 2-4, 4-6 and 6-8 feet. Additional QA/QC samples, i.e., blank, duplicate and spike samples, will be collected to satisfy the NYSDEC Analytical Services Protocol (ASP) standards for Data Quality Assessments. As the fill media is expected to have low sample recovery due to an anticipated low moisture content, additional borings immediately adjacent may be used for the same collection depths. All samples submitted to the analytical laboratory will be tested for TAL metals/Hg and TCL VOCs + TICs. Soil sampling results will be compared with the 6 NYCRR Part 375-6.8(a) Unrestricted Use Soil Cleanup Objectives. The soil VOC samples shall be collected in conformance with EPA Method 5035 – Terra Core Sampling.

Once all samples are collected, initially only the 0-2 and 2-4 feet samples from each soil boring location will be analyzed by the analytical laboratory. These samples will be analyzed on an accelerated turnaround time, while ensuring compliance with analytical holding times. Should no contamination be identified, then the 4-6 and 6-8 feet samples will not be analyzed.

4.2.3 Piping Rinsate Sampling

Seventeen (17) representative sections of the waste piping throughout the building will be removed and visually inspected. As stated in Section 4.1.3, rinsate sampling of the piping will be conducted as necessary based on visual inspections of the piping. Additional QA/QC samples, i.e., blank, duplicate and spike samples, will also be collected to satisfy the NYSDEC Category B standards for Data Quality Assessments. The piping rinsate samples will be analyzed for TAL metals/Hg and TCL VOCs + TICs. Sampling results will be compared with the NYS Groundwater Effluent Limitations (Class GA), as identified in NYSDEC TOGS 1.1.1 or 6 NYCRR Part 703.6. Should the sampling results exceed the Class GA standards, decontamination of the piping will be repeated until subsequent confirmatory rinsate samples meet the Class GA standards.

5.0 DOCUMENTATION AND CUSTODY

Sample preparation, documentation and custody are important elements of any QA/QC program. Without proper sample preparation and accurate documentation and tracking of sample custody, even well planned and properly implemented field sampling programs can generate data open to interpretation. For the purposes of this QA Plan, sample preparation and custody include containerization, preservation, container transfer to field personnel, field handling and sample custody, sample transfer to the laboratory, and internal laboratory custody during sample analysis.

Sample custody is initiated at the designated laboratory where appropriate sample containers and preservatives, if required, are compiled for use by field personnel.

5.1 Sample Containers

Sample containers are provided by the designated laboratory. Generally, the wide scopes of analyses performed during field and sampling investigations necessitate the use of several different types of sample containers. Container materials are selected so that there will be no interference with the analysis to be performed on the given sample. Each sample container will have a label that contains the information necessary to identify the sample. Care must be taken to ensure that the sample locations identified on the Sample Request Form precisely match those on the container and the Chain of Custody. The information to be provided on the container label will include the following, at a minimum:

- A unique laboratory identification number,
- Sample identification,
- Sample location (and depth, if appropriate),
- Sampler's name,
- Date and time of collection, and
- Identification of any preservatives, if applicable.

CLP bottles, as used during this closure sampling effort, are prepared using only CLP approved cleaning techniques with quality control certified by the vendor. The bottles used will be verified as non-contaminated by filling representative bottles with distilled water and analyzing the bottles for the parameters that would be analyzed using the specific bottle type. If any analytes are detected, the entire affected lot will be discarded and not used until the source of contamination is identified and remedied. Verification data is maintained on file at the laboratory.

5.2 Sample Preservation

Sample preservation is dependent upon the specific type or suite of analyses to be performed. A summary of sample container types and preservation methods is presented in Tables 7.2.1 and 7.2.2. Sample preservatives will be added in the laboratory prior to shipment and identified on the sample bottle labels. Field personnel are responsible for verifying the addition of preservatives by visually examining the sample bottles, sample bottle labels, and the chain of custody. Any discrepancies will be reported immediately to the laboratory and field personnel will not use the bottles in question.

After samples are collected and transferred into their respective sample bottles by field personnel, the samples are packed on ice, maintained at 4°C, and delivered to the laboratory within twenty-four hours of collection. Samples will be maintained in a refrigerator (4°C) in the laboratory prior to analysis.

5.3 Preparation of Sample Bottles and Coolers

Coolers used for sample transport will be scrubbed clean prior to use with a non-contaminating detergent followed by a thorough rinse with organic-free distilled water. Coolers will then be dried before packing and use. All sample bottles are purchased new and specially cleaned and certified by the vendor. As per CLP requirements, the sample bottles for this sampling program will be used once for the specific job intended. Non-CLP projects permit the sample bottles to be re-used after thorough cleaning and verification of non-contamination as discussed earlier. All glass containers to be used will be individually packaged in “bubble-wrap” to prevent breakage during transport.

5.4 Custody Transfer to Field Personnel

A standard chain of custody form is utilized for documenting the receipt, tracking and compilation of sample data. The chain of custody (COC) procedure begins with the preparation of the sample bottles. After the sample bottles have been prepared, the cooler to be used will be sealed with custody tape and an external chain of custody form prepared. At a minimum, the following information will be included on the COC at the time of shipment to field personnel:

- Container types including preservatives, if required;
- Number of containers required at each sample location for each analysis, including matrix spike/matrix spike duplicates (MS/MSD), trip blanks and field blanks;
- Any distinctive sample identification requirements;
- Sample custodian's signature with a date and time of relinquishment;
- Receiver's signature with a date and time of receipt.

Sample coolers will be picked up by field personnel at the laboratory. At this point, field personnel are in custody of the sample bottles.

5.5 Custody Transfer to Laboratory

Upon completion of field sampling, field personnel pack sample bottles, including any blank or duplicate samples, and seal the cooler with custody tape. Any breakage of bottles must be noted on the comment section of the COC. If lab prepared glassware is not to be submitted back to the laboratory for analysis, the line designating the unused sample bottles must be crossed-out with a single line through the entry, and the correction initialed by the person in custody of the samples. All corrections to the COC must be made with a single line through the incorrect entry and must be accompanied by the initials of the person in custody of the samples.

Field personnel must verify that the identification labels on the sample bottles and the COC are identical, and that all sample bottles are accounted. Any discrepancies must be resolved before relinquishing custody of the samples. Once the field personnel are satisfied that the samples are ready for submittal to the lab, the cooler will be returned to the laboratory.

Upon receipt of the sample cooler at the laboratory, the sample custodian examines the exterior of the cooler to ensure that sample integrity has not been impacted. Once the laboratory is satisfied that the sample integrity has not been compromised, a lab sample custodian signs and dates the COC to acknowledge receipt of the samples. The field personnel, when hand delivering samples, shall also sign and date the COC acknowledging that they have transferred custody of the samples to the laboratory.

6.0 QUALITY ASSURANCE/QUALITY CONTROL (QA/QC) SAMPLES

There are generally three types of QA/QC samples collected during field sampling programs: blank samples, duplicate samples, and spiked samples. Each of these types of samples serves a specific purpose. Blank samples provide a measure of contamination that may have been introduced into a sample set in either of two ways:

- in the field while the samples were being collected or transported, or
- in the laboratory during sample preparation or analysis.

Duplicate samples provide a quantitative measurement of the reproducibility of sample results and as such, provide a mechanism for measuring the accuracy of sample collection and laboratory analysis procedures. Spiked samples can be used in several ways; the most common of which are the determination of parameter recoveries and reproducibility of results. Parameter recoveries are important in discussing data usability and the possible use of pseudo-correction factors for site sample results.

6.1 Blanks

There are four basic types of blank samples: trip blanks, field blanks, equipment blanks, laboratory calibration blanks, and laboratory reagent (or method) blanks. Only trip blanks and equipment blanks are utilized by field sampling personnel.

Trip blanks are used to indicate potential contamination due to migration of volatile organic compounds (VOCs) from the air on the site or in the sample shipping containers into the sample. A trip blank consists of laboratory distilled and deionized water in a 40 ml glass vial sealed with a Teflon septum. The blank accompanies the empty sample bottles to the field as well as the samples returning to the laboratory for analysis.

Equipment blanks are used to determine if certain field sampling or cleaning procedures (e.g., decontamination of field equipment) result in cross-contamination of site samples. Like the trip blank, the equipment blank is a sample of distilled and deionized water taken to the field with empty sample bottles and analyzed with the site samples. However, unlike the trip blank, the equipment blank sample is prepared in the field. The equipment blank will be poured through or over the sampling equipment after the equipment has been decontaminated. The equipment blank is collected after cleaning the equipment and before next use. The equipment blank will be containerized and labeled in the same manner as other site samples. One (1) equipment blank per 20 field samples will be collected for each matrix type and submitted to the laboratory for the same analysis parameters as the field samples.

6.2 Duplicate Samples

Duplicate samples are used to assess the accuracy and repeatability of field procedures and laboratory analytical procedures. Duplicate site samples are generally collected so that the laboratory is “blind” to the source of the duplicate. Duplicate samples should be collected by sampling the given matrix in accordance with the procedures established for the project, except that approximately double the quantity of sample should be collected. Since sample recoveries are often a limiting factor as to which samples can be collected as duplicates, initial planning is important to ensure that sufficient sample volume is available for an accurate duplicate.

After collection of the sample, the sample will be divided evenly so that each 'half' sample is representative of the whole (i.e., the two samples should be as close to identical as possible). Each sample will then be labeled. The first sample will be labeled with the actual sample location and description. The second sample will be labeled with a fictitious sample identifier known only to the sampler and those responsible for data interpretation. The laboratory should not be informed of the presence of a duplicate sample. Both samples will then submitted in an identical manner and documented on the COC. Analysis should include

all parameters required for the original site sample. One (1) duplicate sample per 20 field samples will be collected over the course of the field sampling program.

6.3 Matrix Spiked Samples

Spiked samples are utilized to potentially improve combined sampling and analytical accuracy. The two spiked samples are identified as matrix spike and matrix spike duplicate (MS/MSD). For matrix spiked samples, a selected field sample is collected in triplicate following the same procedure as used for duplicate samples, discussed in Section 6.2. In the laboratory, two of the field samples are spiked with a known concentration of a contaminant of interest. The recovery of the spiked compound is determined after laboratory analysis. The recovery serves as an indicator of the efficiency of the laboratory analysis, and more importantly from the standpoint of the field sampling personnel; the percent recovery can be used as a pseudo-correction factor for other sample results. Sample recoveries outside of a pre-determined control limit can also be used by the personnel responsible for data interpretation to assess the usability of site data. One (1) set of MS/MSD samples will be collected per 20 field samples as part of the field sampling program.

A summary of spiking compounds, method, low and high QC limits for spike recovery and relative percent difference values (RPD) for all matrices are included in **Appendix B**. Tables listing surrogate compounds, method, and acceptability QC limits for all samples matrices are also included.

7.0 ANALYTICAL PROCEDURES AND LABORATORY TESTING

7.1 Analytical Laboratory

Environmental samples will be analyzed by American Analytical Laboratories LLC in Farmingdale, New York, a New York State ELAP-accredited laboratory.

7.2 Sample Analysis

All rinsate and soil samples will include a NYSDEC ASP category B data package that documents the quality of the analytical work. A summary of the desired parameters, methods of analyses, required sample container, preservative and maximum holding time is shown in Table 7.2.1 for water matrices and Table 7.2.2 for soil and solid matrices. An Analytical Methods/Quality Assurance summary including information pertaining to all environmental, performance evaluation and quality control samples is provided in Table 7.2.3.

8.0 CALIBRATION PROCEDURES

8.1 Calibration Practices

Instruments and equipment to be used in the analytical laboratory are controlled by a formal calibration program. The program verifies that equipment is of the proper type, range, accuracy and precision to provide data compatible with the desired requirements. All instruments and equipment that measure a quantity with performance expected at a stated level are subject to calibration. Calibration may be performed by lab personnel using reference standards or externally by calibration agencies or equipment manufacturers.

Implementation of the laboratory calibration program is the responsibility of the Laboratory Manager and Analysts. The Laboratory QA Manager shall review the implementation of the program.

There are two types of calibration pertinent to the laboratory procedures to be utilized during the analysis of samples from the Newsday Facility closure. These are operational and periodic.

1.) Operational calibration which is routinely performed as part of the instrument usage, such as the development of a standard curve for use with an Atomic Absorption (AA) Spectrophotometer or Inductively Coupled Plasma (ICP) Spectrophotometer. Operation calibration is generally performed for instrument systems.

2.) Periodic calibration is performed at prescribed intervals for equipment such as balances and controlled ovens. In general, equipment that can be calibrated periodically is considered a distinct single purpose unit and is relatively stable in performance.

Whenever possible recognized procedures, such as those published by ASTM, USEPA, or the equipment manufacturers shall be utilized.

8.2 Calibration Frequency

Instruments and equipment shall be calibrated at prescribed intervals and/or as part of the operational use of the equipment. Frequency shall be based on the type of equipment, inherent stability, manufacturer's recommendations, values provided in recognized standards, intended use, effect of error upon the measurement process, and prior experience.

8.3 Calibration Reference Standards

Two (2) types of reference standards are used by American Analytical for calibration. These are physical and chemical.

1.) Physical Standards, such as weights for calibrating balances and certified thermometers for calibrating working thermometers and ovens, are generally used for periodic calibration.

2.) Chemical Standards are primarily used for operational calibration.

Whenever possible, physical and chemical reference standards shall have known relationships to nationally recognized standards (e.g., National Bureau of Standards) or accepted values of natural physical constants. If national standards do not exist, the basis for the reference standard shall be documented.

8.4 Calibration Failure

Equipment that fails calibration or becomes inoperable during use shall be removed from service and segregated to prevent inadvertent use, or shall be tagged to indicate it is out of calibration. Such equipment shall be repaired and satisfactorily recalibrated before reuse.

8.5 Calibration Records

Records shall be prepared and maintained for each piece of equipment subject to calibration. Records demonstrating accuracy of reference standards shall also be maintained.

For instruments and equipment that are calibrated on an operational basis, calibration generally consists of determining instrumental response against compounds of known composition and concentration or the preparation of a standard response curve of the same compound at different concentrations. Records of these calibrations can be maintained in several ways:

1.) The calibration data can be kept with analytical sample data.

2.) A logbook can be prepared for each instrument that contains all calibration data.

Method 1 provides response factor information, etc., directly with the analytical data so that the data can be readily processed and verified. Also, the raw data package is completed as a unit.

Method 2 provides an on-going record of calibration undertaken for a specific instrument. However, to process and verify the analytical data, the log must be used in conjunction with the raw data.

For operational calibration of instrumentation used for this project, calibration data will be included with the raw analytical data and maintained in project files.

9.0 DATA REDUCTION, VALIDATION AND REPORTING

9.1 Data Reduction

Laboratory data reduction and analysis for organic analyses involves relating a "peak area" to the mass of a constituent. This is accomplished by digital computers. The computer hardware and software is designed

to allow the analyst to create libraries or files of calibration standards, and then compare raw sample data against these libraries to produce a report that contains the identification and qualification of constituents present in the sample. The analysts manually check the computer-reduced data.

Inorganic analyses are performed with instruments of varying electronic sophistication, but in all instances, data reduction and analysis involves essentially the generation of a standard calibration curve, and then comparing the instrument readout against the calibration curve to obtain a "Quantity" of constituent. The concentration is then manually calculated. The calculated results are manually entered into the computer system.

9.2 Data Validation

Data validation is a process in which field and analytical data quality is assessed relative to the data quality objectives. The validation process examines the acceptability or validity of data, and assesses data usability. Although data validation usually refers to analytical laboratory data, the same review process is applied to all field-generated data.

In order to ensure that data collected in the field is consistent and accurate, standard reporting forms are utilized. These forms are then checked by the Field Team Supervisor to confirm that the information is complete and that any calculations are correct. A minimum of 20% of the field data reports is checked in this manner. If, during the initial review process, errors are identified, the remaining 80% of the data set are reviewed. Items to be checked by the reviewer will be dependent on the type of data being reported, but in general include the following:

- Proper sampling methods and equipment were employed
- Proper sample preservation methods were followed
- Chain of custody information is complete
- Proper QA/QC samples were utilized.
- Equipment decontamination procedures were followed, and
- Instruments were properly calibrated.

The final analytical laboratory category B data package generated as part of the planned closure activities at Newsday will be evaluated for data validation by a third party. For this project, outside validation services will be provided by Nancy Potak. A copy of Ms. Nancy Potak's resume is provided as **Appendix C**.

9.3 Data Reporting

The following are applicable to data presentation:

1.) The final presentation shall be checked in accordance with data verification requirements and approved by the Laboratory QA Manager.

2.) Data presentation will include:

a) Sample identification number used by American Analytical and/or the sample identification provided to the laboratory (if different).

b) Chemical parameters analyzed reported values, and units of measurements.

c) Detection limit of the analytical procedure, if the reported value is less than the reporting limit.


d) Reporting limit for non-detects flagged with the “U” qualifier.

e) Data for a chemical parameter are reported with consistent significant figures for all samples.

f) Results of QA/QC sample analysis, if appropriate.


g) Footnotes referenced to specific data, if required to explain reported values.

The format for reporting will follow the NYSDEC ASP category B data package. All data will be made available in EQuIS Electronic Data Deliverable (EDD) Format.



CLIENT **NEWSDAY** **235 PINELAWN ROAD** **MELVILLE, NY 11747**	**Figure 1: Site Location Map** SCALE: **1" = 3280'** N	PROJECT NEWD1□03 DATE: **MAY 2018**	H2M architects + engineers Melville, NY · Albany, NY New City, NY · Parsippany, NJ

X:\NEWD (Newsday) - 44530\2018\NEWD1803 - (RCRA Closure)\02-BIM-CADD\env\Fig 1.Site Location Map_LW.dwg Last Modified: May 25, 2018 - 4:30pm Plotted on: May 25, 2018 - 4:31pm By lwu



REFERENCE: NEWSDAY SITE PLAN 04/19/08

Client

Newsday

235 Pinelawn Road, Melville, NY 11747
RCRA Closure

SHEET #
Figure 2

DATE:
MAY 2018

Facility Site Plan

NEWD1803

H2M architects + engineers




Figure 3. Organization Chart for Field Sampling and Analysis Program

Table 7.2.1. Water Matrix Analysis Requirements and Methods

Parameter	Method	Container	Preservative	Max. Holding Time*
VOCs	ASP 2005 8260C	40 ml vial	Cool, 4°C; HCl to pH<2	7 days unpreserved; 14 days preserved.
Metals / Hg	ASP 2005 6010C / 7470A	500 ml plastic	Cool, 4°C; HNO_3 to pH<2	6 months / 28 days.

*All holding times from verified time of sample receipt (VTSR) as per NYSDEC ASP Category B.

Table 7.2.2. Soil and Solid Matrix Analysis Requirements and Methods

Parameter	Method	Container	Preservative	Max. Holding Time*
VOCs (High Level)	ASP 2005 8260C / 5035	40 ml vial	Cool, 4°C; Methanol	14 days preserved.
VOCs (Low Level)	ASP 2005 8260C / 5035	40 ml vial	Cool, 4°C (48 hours) or Freeze, < -7°C; DI Water	14 days preserved.
Metals / Hg	ASP 2005 6010C / 7471B	8 oz jar	Cool, 4°C	6 months / 28 days.

* All holding times from VTSR as per NYSDEC ASP Category B.

Table 7.2.3. Analytical Methods/Quality Assurance Summary

Sampling Location	Matrix	No. of Samples	Analysis	Methods
1. Closure Sampling				
a. Floor Rinsate Sampling	Liquid	6	Metals	6010/7470
			VOCs	8260
b. Soil Sampling	Soil	12 [1]	Metals	6010/7471
			VOCs	8260
c. Piping Rinsate Sampling	Liquid	As Necessary	Metals	6010/7470
			VOCs	8260
2. QA/QC Sampling				
a. Trip Blank	Liquid	1 [2]	VOCs	8260
b1. Equipment Blank - Floor Rinsate	Liquid	1 [3]	Metals	6010/7470
			VOCs	8260
b2. Equipment Blank - Soil	Liquid	1 [3]	Metals	6010/7470
			VOCs	8260
b3. Equipment Blank - Piping Rinsate	Liquid	1 [3]	Metals	6010/7470
			VOCs	8260
c. Duplicate	Soil	1 [3]	Metals	6010/7471
			VOCs	8260
	Liquid	1 [3]	Metals	6010/7470
			VOCs	8260
d. MS/MSD	Soil	1 [3]	Metals	6010/7471
			VOCs	8260
	Liquid	1 [3]	Metals	6010/7470
			VOCs	8260

[1] Soil samples collected using EPA Method 5035 will be collected in duplicate.

[2] One trip blank per day.

[3] Minimum of one set of QA samples per sample delivery group (SDG), i.e., 1 per 20.

QAPP APPENDIX A

RINSATE SAMPLE COLLECTION PROTOCOL

Attachment A

Rinsate Sample Collection Protocol

This procedure is intended to be used to collect samples for analysis of concrete floors, secondary containment areas and sumps, including surfaces that have been coated, to establish whether or not there is any contamination on the concrete surfaces. This procedure is to be performed after the surfaces have been cleaned and decontaminated pursuant to the approved closure plan. This procedure may also be suitable for use on other surfaces on a case-by-case basis.

1. Mark areas to be sampled on a facility floor plan for the area(s) to be closed. Sketches should include locations of building columns, walls, fixed equipment, and the rinsate sampling locations themselves to accurately locate the rinsate sampling points within the buildings.

2. Assemble and clean all equipment necessary for sample collection. Equipment needs to be cleaned, if not already pre-cleaned by the laboratory.

3. Create a temporary containment area on the floor using an inert, pre-cleaned, flexible boom.

4. Label the sample containers with a unique sample code, information on the site, sample location and date/time sample was collected. Affix appropriate labels for test parameters on the sample containers. Put on a new pair of disposable nitrile gloves.

5. At each sampling location, slowly pour the minimum quantity of de-ionized water (start with one gallon for metals analysis, much less for only volatiles) needed to collect all sample parameters, including QC samples, onto the concrete area. If the individual area is sloped, start pouring at the highest elevation. The de-ionized water may be provided by the analytical laboratory, purchased, or generated on-site.

6. Allow de-ionized water to collect and remain in the sample location for 10 minutes.

7. Collect the number of samples as specified in the closure plan along with appropriate QA/QC samples. Samples may be collected using dedicated, sterile glass pipettes provided by the laboratory, or any other suitable device approved in the closure plan. The pipettes are used to transfer the sample fluids into the appropriate laboratory supplied containers. Volatile sample containers shall be filled first to minimize loss of volatiles.

8. Samples must not be composited.

9. Cap the sample container and place sample containers in a cooler with ice to maintain a temperature of 4 °C.

10. Remove and discard the gloves. Place all disposable gloves into a plastic bag designated

for proper disposal.

11. Fill out sampling details in field log book. Photographs of the sample locations, wetted areas, equipment, and actual sampling events may be taken by the facility or Department staff and a list of the photographs shall be recorded in the field book.

12. Fill out the chain-of-custody and any other sample forms. Prepare the samples for storage and shipping in the cooler with ice to maintain a temperature of 4 $\pm$ 2°C. Ship overnight to the laboratory for analysis.

13. Follow the chain-of custody procedures as detailed in the Quality Assurance Project Plan.

QAPP APPENDIX B

QC LIMITS FOR SPIKING AND SURROGATE COMPOUNDS

Volatile Organic Compounds (VOCs), Method 8260B - Water (ug/l)

Lab Fortified Blank (LFB)		QC Limits (%R)	
Analyte	Spike Concentration	Low	High
1,1,1-Trichloroethane	50	66	126
1,1,2,2-Tetrachloroethane	50	77	120
1,1,2-Trichloroethane	50	82	116
1,1-Dichloroethane	50	77	114
1,1-Dichloroethene	50	67	120
1,2-Dichloroethane	50	76	120
1,2-Dichloroethene (total)	100	78	128
1,2-Dichloropropane	50	81	115
2-Butanone	50	74	121
2-Hexanone	50	76	119
4-Methyl-2-pentanone	50	79	121
Acetone	50	71	125
Benzene	50	77	116
Bromodichloromethane	50	78	118
Bromoform	50	75	121
Bromomethane	50	50	136
Carbon disulfide	50	61	126
Carbon tetrachloride	50	64	126
Chlorobenzene	50	72	124
Chloroethane	50	71	116
Chloroform	50	75	119
Chloromethane	50	70	114
cis-1,3-Dichloropropene	50	79	116
Dibromochloromethane	50	75	125
Ethylbenzene	50	68	128
Methylene chloride	50	80	112
Styrene	50	72	124
Tetrachloroethene	50	59	133
Toluene	50	70	125
trans-1,3-Dichloropropene	50	77	120
Trichloroethene	50	72	121
Vinyl chloride	50	66	117
Xylene (total)	150	78	133

VOCs (continued), Method 8260B - Water (ug/l)

MS/MSD		QC Limits (%R)		RPD
Analyte	Spike Concentration	Low	High	
1,1-Dichloroethene	50	61	145	14
Benzene	50	76	127	11
Chlorobenzene	50	75	130	13
Toluene	50	76	125	13
Trichloroethene	50	71	120	14

Surrogates		QC Limits (%R)	
Analyte	Spike Concentration	Low	High
1,2-Dichloroethane-d4	50	76	114
4-Bromofluorobenzene	50	86	115
Toluene-d8	50	88	110

Volatile Organic Compounds (VOCs), Method 8260B - Soil (ug/kg)

Lab Fortified Blank (LFB)		QC Limits (%R)	
Analyte	**Spike Concentration**	**Low**	**High**
1,1,1-Trichloroethane	50	78	127
1,1,2,2-Tetrachloroethane	50	72	152
1,1,2-Trichloroethane	50	80	139
1,1-Dichloroethane	50	67	141
1,1-Dichloroethene	50	65	142
1,2-Dichloroethane	50	65	147
1,2-Dichloroethene (total)	100	57	150
1,2-Dichloropropane	50	81	132
2-Butanone	50	30	226
2-Hexanone	50	59	163
4-Methyl-2-pentanone	50	64	170
Acetone	50	50	187
Benzene	50	71	142
Bromodichloromethane	50	78	137
Bromoform	50	81	142
Bromomethane	50	58	144
Carbon disulfide	50	52	143
Carbon tetrachloride	50	70	136
Chlorobenzene	50	85	128
Chloroethane	50	33	153
Chloroform	50	68	140
Chloromethane	50	33	149
cis-1,3-Dichloropropene	50	78	131
Dibromochloromethane	50	82	136
Ethylbenzene	50	80	129
Methylene chloride	50	46	157
Styrene	50	85	126
Tetrachloroethene	50	67	144
Toluene	50	83	129
trans-1,3-Dichloropropene	50	59	147
Trichloroethene	50	72	145
Vinyl chloride	50	20	164
Xylene (total)	150	79	133

VOCs (continued), Method 8260B - Soil (ug/kg)

MS/MSD		QC Limits (%R)		RPD
Analyte	Spike Concentration	Low	High	
1,1-Dichloroethene	50	59	172	22
Benzene	50	66	142	21
Chlorobenzene	50	60	133	21
Toluene	50	59	139	21
Trichloroethene	50	62	137	24

Surrogates		QC Limits (%R)	
Analyte	Spike Concentration	Low	High
1,2-Dichloroethane-d4	50	70	121
4-Bromofluorobenzene	50	59	113
Toluene-d8	50	84	138

Metals, Method 6010/7471 - Soil (mg/kg)

LCS		QC Limits	
Analyte	Spike Concentration	Low	High
Aluminum	10600	52.36	147.2
Antimony	103	0	207.8
Arsenic	107	79.5	119.6
Barium	331	79.2	120.8
Beryllium	74.1	73.9	118.5
Cadmium	244	73.4	118
Calcium	9690	75.4	117.6
Chromium	80.6	79.5	120.3
Cobalt	85.8	81.9	117.7
Copper	65.3	80.4	119.6
Iron	18400	50.6	149.5
Lead	107	80.3	119.6
Magnesium	4100	74.6	125.1
Manganese	452	76.3	119.2
Mercury	3	71.7	128.4
Nickel	96.8	79.8	119.8
Potassium	4490	72.2	127.8
Selenium	177	78.5	122
Silver	46.2	66.2	133.8
Sodium	1060	73.8	126.4
Thallium	272	80.9	119.5
Vanadium	115	79.6	120
Zinc	378	78.3	122

Metals (continued), Method 6010/7471 - Soil (mg/kg)

Matrix Spike (MS)		QC Limits (%R)	
Analyte	**Spike Concentration**	**Low**	**High**
Antimony	50	75	125
Arsenic	4	75	125
Barium	200	75	125
Beryllium	5	75	125
Cadmium	5	75	125
Chromium	20	75	125
Cobalt	50	75	125
Copper	25	75	125
Lead	2	75	125
Manganese	50	75	125
Mercury	0.167	75	125
Nickel	50	75	125
Selenium	1	75	125
Silver	5	75	125
Thallium	5	75	125
Vanadium	50	75	125
Zinc	50	75	125

Sample Duplicate – 20% RPD

QAPP APPENDIX C

RESUME OF MS. NANCY POTAK (THIRD PARTY DATA VALIDATOR)

Nancy J. Potak
1796 Craftsbury Road
Greensboro, Vermont 05841

Phone (802) 533-9206
Fax (802) 533-9206
email: npotak@vtlink.net

PROFESSIONAL EXPERIENCE

Data Validation / Client List – NYS DEC

First Project 2007	Earth Tech
First Project 2007	OP-TECH Environmental Sciences
First Project 2007	Camp Dresser McKee (CDM)
First Project 2006	EA Science & Technology
First Project 2005	H2M, Inc.
First Project 2004	GEI Consultants
First Project 2003	Vanasse Hangen Brustlin, Inc
First Project 2000	O'Brien & Gere, Syracuse, NY
First Project 2000	EPM, Lake Success, NY
First Project 1998	IT International Technology Corporation / Shaw Environmental, New Jersey
First Project 1997	Cluogh Harbour and Associates
First Project 1997	Roux Associates, Islandia, New York
First Project 1996	Lawler, Matusky and Skelly Enngineers, Pearl River, NY
First Project 1996	ABB, Portland Maine
First Project 1996	Malcolm Pirnie, Buffalo, Albany, New York
First Project 1995	AKRF Associates, New York, New York
First Project 1992	Dvirka & Bartilucci, Woodbury, New York
First Project 1992	Eckenfelder, Inc., Mahwah, New Jersey
First Project 1991	C&S Engineering, Liverpool, New York

1989 - 1993 **EDER ASSOCIATES**, Locust Valley, New York

- Perform independent third party data validations for NY CLP projects.
- Review analytical data from projects in several states for appropriate methodology, detection limits, and quality assurance practices.
- Compose laboratory analytical contracts detailing methods, deliverables and laboratory quality assurance requirements.
- Advise on potential analytical problems which may be encountered at specific sites.

1988 -1993 **WOODWARD CLYDE CONSULTANTS,** Wayne, New Jersey

- Perform independent third party data validation for CLP analyses of all samples collected for the Pelham Bay Landfill.
- Design data validation documentation for dioxin and furan analyses.

1989 - 1990 **SMC MARTIN**, Valley Forge, PA

- Perform independent data validations for the New Jersey CLP program.

1987 - 1988 **KILLAM ASSOCIATES**, Millburn, New Jersey
Laboratory Director
Supervise a staff of 14 chemists and technicians in methodologies for GC/MS, GC, and inorganic analyses.
Responsible for the quality of all data and the final review of all analytical reports produced by the laboratory.
Developed the laboratory quality assurance program
Responsible for the hiring of all technical and administrative personnel.

1982 - 1987 **GENERAL TESTING CORPORATION**, Hackensack, NJ
Laboratory Director, 1986 through 1987
Coordinate all analytical and field projects originating in the New York metropolitan area involving water quality analyses, site investigation, and industrial monitoring.

Laboratory Manager, 1983 - 1986
Hired, trained, and evaluated all technical personnel.
Directly responsible for all data originating at the New Jersey laboratory.
Extensive experience in all aspects of large scale water quality monitoring studies.

1982 **HUDSONIA**, Annandale, NY
Consultant
Assisted in a study to determine the feasibility of the use of apple cider wastes as a soil amendment and fuel.

HUDSON RIVER SLOOP CLEARWATER, Poughkeepsie, NY
Consultant
Studied the effectiveness of the NY SPDES program. Examined the engineering files of the major dischargers in the Hudson River valley to determine the reasons for permit violations.

1981 **LAWLER, MATUSKY, AND SKELLY ENGINEERS**, Pearl River, NY
Analyst: Performed wet chemical analyses for environmental monitoring.

1977 - 1979 **UNIVERSITY OF GEORGIA**, Athens, GA
Research assistant in several projects involving soil and water chemistry. Extensive experience in inorganic analyses.

1972 - 1976 **UNIVERSITY OF MASSACHUSETTS**, Amherst, MA
Assisted in experiments designed to study the effects of sludge on plant growth and heavy metal uptake. Performed all of the inorganics analyses for the project.

EDUCATION

University of Massachusetts, Amherst, MA
B.S. - Plant and Soil Sciences, Honors Program, 1976

University of Georgia, Athens, GA
Graduate work in environmental chemistry and ecology

APPENDIX B

SCDHS TANK LISTING, APRIL 10, 2014

STATUS KEY:
REM = removed
NI = never installed
#P = permitted
EX = exempt
ABD = abandoned
81, 82, 85 = non-compliant tank

Facility Info: NEWSDAY LLC
235 PINELAWN RD
MELVILLE, NY 11747

Reg. No.: 4-0094
Ref. No.: 02037
Tax Lot: 0400 270.00 002 001.000

Tank Listing as of 04/10/2014

SIC Code: 2711
Rank: D03
EPA: Y
X Coord.: 2164274
Y Coord.: 196590

No.	Location	Vol	Status	Job No	Contents	Constr / Contain	Rem/Abd	Permit (registered)
1	UNDER OUT UNKNOWN	25000	86REM		DIESEL NONE	STEEL/ IRON	01/01/86	
2	UNDER OUT UNKNOWN	25000	86REM		DIESEL NONE	STEEL/ IRON	01/01/86	
3	UNDER OUT UNKNOWN	25000	86REM		DIESEL NONE	STEEL/ IRON	01/01/86	
4	UNDER OUT UNKNOWN	12000	86REM		GASOLINE NONE	STEEL/ IRON	01/01/86	
5	UNDER OUT UNKNOWN	2000	88ABD		SPILL CONT NONE	STEEL/ IRON	06/28/88	
6	UNDER OUT UNDERGROUND	25000	14ABD		#2 FUEL OI NONE	STEEL/ IRON	03/20/14	
7	UNDER OUT UNDERGROUND	25000	14ABD		#2 FUEL OI NONE	STEEL/ IRON	03/20/14	
8	UNDER OUT UNKNOWN	4000	87REM		INDUSTRIAL NONE	FIBER REINFORCED PLA	01/01/87	
9	ABOVE IN ABOVEGROUND	275	EX		DIESEL - IN CONTACT WITH IMPERVI NONE	STEEL/ IRON		
10	ABOVE IN ABOVEGROUND	7900	11P	HM02-049R3	BLACK INK - IN CONTACT WITH IMPERVI DIKE - CONCRETE	STEEL/ IRON		02/27/06
11	ABOVE IN ABOVEGROUND	7900	11P	HM02-049R3	BLACK INK - IN CONTACT WITH IMPERVI DIKE - CONCRETE	STEEL/ IRON		02/27/06
12	ABOVE IN ABOVEGROUND	7900	11P	HM02-049R3	BLACK INK - IN CONTACT WITH IMPERVI DIKE - CONCRETE	STEEL/ IRON		02/27/06
13	ABOVE IN UNKNOWN	100	01REM		INDUSTRIAL NONE	REFER TO PAPER FILE	02/06/01	
14	UNDER OUT UNKNOWN	20000	10REM	HU-052R	DIESEL NONE	FIBER REINFORCED PLA	04/28/10	
15	UNDER OUT UNKNOWN	20000	10REM	HU-052R	DIESEL NONE	FIBER REINFORCED PLA	04/28/10	
16	UNDER OUT UNKNOWN	20000	10REM	HU-052R	DIESEL NONE	FIBER REINFORCED PLA	04/28/10	
17	ABOVE IN ABOVEGROUND	100	EX		DIESEL - IN CONTACT WITH IMPERVI DIKE - STEEL	STEEL/ IRON		
18	UNDER OUT UNDERGROUND	2500	92P	HU-052	#2 FUEL OI SECONDARY WALL - FIBERGLASS	FIBER REINFORCED PLA		
19	UNDER OUT UNKNOWN	4000	NI	HM86-068R3	INDUSTRIAL SECONDARY WALL - STI-P3 PROTECTED	STEEL/ IRON STEEL		
20	UNDER OUT UNKNOWN	10000	NI	HU-052	GASOLINE NONE	FIBER REINFORCED PLA		
21	ABOVE IN UNKNOWN	4675	NI	HM88-141	DRUM STORA UNKNOWN	UNKNOWN		
22	ABOVE IN ABOVEGROUND	1380	96P	HM88-141R1	DRUM STORA - IN CONTACT WITH IMPERVI DIKE - CONCRETE	STEEL/ IRON		04/19/91
23	ABOVE IN ABOVEGROUND	200	96P	HM88-141R1	INDUSTRIAL - IN CONTACT WITH IMPERVI DIKE - CONCRETE	STEEL/ IRON		04/19/91
24	ABOVE IN	200	96P	HM88-141R1	INDUSTRIAL	STEEL/ IRON		04/19/91

	ABOVEGROUND - IN CONTACT WITH IMPERVI			DIKE - CONCRETE			
25	ABOVE IN	500	96P	HM88-141R1	INDUSTRIAL STEEL/ IRON		04/19/91
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
26	ABOVE IN	2000	02REM	HM89-038	INDUSTRIAL POLYETHYLENE	12/16/02	
	UNKNOWN				NONE		
27	ABOVE IN	2000	02REM	HM89-038	INDUSTRIAL POLYETHYLENE	12/16/02	
	UNKNOWN				NONE		
28	ABOVE IN	250	03REM	HM89-038	INDUSTRIAL REFER TO PAPER FILE	07/29/03	
	UNKNOWN				NONE		
29	ABOVE IN	2640	03REM	HM91-442R2	DRUM STORA UNKNOWN	07/29/03	02/06/01
	UNKNOWN				UNKNOWN		
30	ABOVE IN	1500	06REM	HM93-159R2	CAUSTIC (N STEEL/ IRON	02/23/06	02/06/01
	UNKNOWN				NONE		
31	ABOVE IN	7900	13P	HM02-048R3	BLACK INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
32	ABOVE IN	7900	13P	HM02-048R3	BLACK INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
33	ABOVE IN	7900	13P	HM02-048R3	BLACK INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
34	ABOVE IN	1900	13P	HM02-048R3	CYAN INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
35	ABOVE IN	1900	13P	HM02-048R3	YELLOW INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
36	ABOVE IN	1900	13P	HM02-048R3	RED INK STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
37	ABOVE IN	1900	13P	HM02-048R3	MAGENTA IN STEEL/ IRON		12/22/08
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
38	ABOVE IN	125	EX		DIESEL STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL		
39	ABOVE IN	300	03REM		COOLING TO REFER TO PAPER FILE	07/29/03	
	UNKNOWN				NONE		
40	ABOVE IN	25	EX		#2 FUEL OI STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE		
41	ABOVE IN	550	13REM		COOLING WA POLYETHYLENE	06/19/13	
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE		
42	ABOVE IN	50	13REM	HM01-278R1	INDUSTRIAL POLYETHYLENE	06/19/13	07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE		
43	ABOVE IN	100	02REM	HM01-137	INDUSTRIAL REFER TO PAPER FILE	12/16/02	
	UNKNOWN				REFER TO PAPER FILE		
44	ABOVE IN	55	08REM	HM01-137,H	DEVELOPER REFER TO PAPER FILE	09/10/08	02/27/06
	UNKNOWN				REFER TO PAPER FILE		
45	ABOVE IN	100	08REM	HM01-137,H	DEVELOPER UNKNOWN	09/10/08	02/27/06
	UNKNOWN				UNKNOWN		
46	ABOVE IN	100	08REM	HM01-137,H	FIXER REFER TO PAPER FILE	09/10/08	02/27/06
	UNKNOWN				NONE		
47	ABOVE IN	100	08REM	HM01-137,H	FIXER REFER TO PAPER FILE	09/10/08	02/27/06
	UNKNOWN				NONE		
48	ABOVE IN	66	08REM	HM01-137,H	PHOTO CHEM UNKNOWN	09/10/08	02/27/06
	UNKNOWN				UNKNOWN		
49	ABOVE IN	200	08REM	HM01-137	DRY PHOTO UNKNOWN	09/10/08	02/27/06
	UNKNOWN				UNKNOWN		
50	ABOVE IN	200	82	HM01-137	SOLVENT PA STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE		
51	ABOVE IN	330	02REM	HM01-137	FOUNTAIN S UNKNOWN	12/16/02	
	UNKNOWN				UNKNOWN		
52	ABOVE IN	330	02REM	HM01-137	FOUNTAIN S UNKNOWN	12/16/02	
	UNKNOWN				UNKNOWN		
53	ABOVE IN	330	02REM		FOUNTAIN S UNKNOWN	12/16/02	
	UNKNOWN				UNKNOWN		
54	ABOVE IN	330	02REM		FOUNTAIN S UNKNOWN	12/16/02	

	UNKNOWN				UNKNOWN			
55	ABOVE OUT	1250	06REM		DIESEL	STEEL/ IRON	02/23/06	
	UNKNOWN				NONE			
56	ABOVE OUT	1250	06REM		DIESEL	STEEL/ IRON	02/23/06	
	UNKNOWN				NONE			
57	ABOVE IN	80	08P	HM02-100R1	BOILER CHE	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
58	ABOVE IN	80	08P	HM02-100R1	BOILER CHE	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
59	ABOVE IN	80	08P	HM02-100R1	BOILER CHE	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
60	ABOVE IN	80	08P	HM02-100R1	BOILER CHE	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
61	ABOVE IN	80	08P	HM02-100R1	COOLING TO	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
62	ABOVE IN	140	08P	HM02-100R1	COOLING TO	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
63	ABOVE IN	80	08P	HM02-100R1	COOLING TO	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
64	ABOVE IN	140	08P	HM02-100R1	COOLING TO	POLYETHYLENE		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
65	ABOVE IN	220	EX		DRUM STORA	STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE			
66	ABOVE IN	595	08P	HM02-179R1	DRUM STORA	STEEL/ IRON		07/29/03
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - STEEL			
67	ABOVE IN	440	03REM		DRUM STORA	UNKNOWN	07/29/03	
	UNKNOWN				UNKNOWN			
68	ABOVE IN	5280	08P	HM01-291R2	DRUM STORA	STEEL/ IRON		07/29/03
	UNKNOWN				DIKE - CONCRETE			
69	ABOVE OUT	10	01REM		SALT STORA	UNKNOWN	10/16/02	
	UNKNOWN				UNKNOWN			
70	ABOVE IN	101	EX		OTHER OIL	STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE			
71	ABOVE IN	81	13REM		OTHER OIL	STEEL/ IRON	06/19/13	
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE			
72	ABOVE IN	600	01REM		HYDRAULIC	STEEL/ IRON	10/16/02	
	UNKNOWN				NONE			
73	ABOVE IN	120	EX		HYDRAULIC	STEEL/ IRON		
	ABOVEGROUND - IN CONTACT WITH IMPERVI				NONE			
74	ABOVE IN	275	01REM		DRUM STORA	UNKNOWN	10/16/02	
	UNKNOWN				UNKNOWN			
75	ABOVE IN	500	07P	HM01-277R1	FOUNTAIN S	POLYETHYLENE		12/16/02
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE			
76	ABOVE IN	500	07P	HM01-277R1	FOUNTAIN S	POLYETHYLENE		12/16/02
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE			
77	ABOVE IN	500	07P	HM01-277R1	FOUNTAIN S	POLYETHYLENE		12/16/02
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE			
78	ABOVE IN	500	07P	HM01-277R1	FOUNTAIN S	POLYETHYLENE		12/16/02
	ABOVEGROUND - IN CONTACT WITH IMPERVI				DIKE - CONCRETE			
79	ABOVE IN	660	07P	HM01-277R1	TRANSFER F	POLYETHYLENE		12/16/02
	ABOVEGROUND - IN CONTACT WITH IMPERVI				SECONDARY WALL - FIBERGLASS			
80	ABOVE IN	60	09REM	HM01-278R1	INDUSTRIAL	REFER TO PAPER FILE	12/14/09	07/29/03
	UNKNOWN				REFER TO PAPER FILE			
81	ABOVE IN	60	09REM	HM01-278R1	INDUSTRIAL	REFER TO PAPER FILE	12/14/09	07/29/03
	UNKNOWN				REFER TO PAPER FILE			
82	ABOVE IN	50	09REM	HM01-278R1	INDUSTRIAL	REFER TO PAPER FILE	12/14/09	07/29/03
	UNKNOWN				REFER TO PAPER FILE			
83	ABOVE IN	500	09REM	HM01-278R1	INDUSTRIAL	REFER TO PAPER FILE	12/14/09	07/29/03
	UNKNOWN				REFER TO PAPER FILE			
84	ABOVE OUT	2860	07P	HM01-288R1	DRUM STORA	STEEL/ IRON		12/16/02

	ABOVEGROUND - IN CONTACT WITH IMPERVI			DIKE - CONCRETE			
85	ABOVE IN	200 10P	HM01-289R2	DEGREASER	STEEL/ IRON		01/06/05
	ABOVEGROUND - IN CONTACT WITH IMPERVI			DIKE - CONCRETE			
86	ABOVE OUT	1100 11P	HM03-122R4	DIESEL	STEEL/ IRON		02/27/06
	ABOVEGROUND - IN CONTACT WITH IMPERVI			SECONDARY WALL - EPOXY COATED STEEL			
87	ABOVE OUT	1100 11P	HM03-122R4	DIESEL	STEEL/ IRON		02/27/06
	ABOVEGROUND - IN CONTACT WITH IMPERVI			SECONDARY WALL - EPOXY COATED STEEL			
88	ABOVE IN	210 82		O/W SEPARA	POLYETHYLENE		
	ABOVEGROUND - IN CONTACT WITH IMPERVI			NONE			
89	ABOVE IN	210 82		O/W SEPARA	POLYETHYLENE		
	ABOVEGROUND - IN CONTACT WITH IMPERVI			NONE			
90	ABOVE IN	210 82		O/W SEPARA	POLYETHYLENE		
	ABOVEGROUND - IN CONTACT WITH IMPERVI			NONE			
91	ABOVE IN	120 13REM		ENZYMATIC	POLYETHYLENE	06/19/13	
	ABOVEGROUND - IN CONTACT WITH IMPERVI			NONE			
92	ABOVE IN	50 13REM		INDUSTRIAL	POLYETHYLENE	06/19/13	
	ABOVEGROUND - IN CONTACT WITH IMPERVI			NONE			
93	UNDER OUT	20000 15P	HM08-301	DIESEL	FIBER REINFORCED PLA		07/23/10
	UNDERGROUND			SECONDARY WALL - FIBERGLASS			
94	UNDER OUT	20000 15P	HM08-301	DIESEL	FIBER REINFORCED PLA		07/23/10
	UNDERGROUND			SECONDARY WALL - FIBERGLASS			
95	UNDER OUT	20000 15P	HM08-301	DIESEL	FIBER REINFORCED PLA		07/23/10
	UNDERGROUND			SECONDARY WALL - FIBERGLASS			
96	ABOVE OUT	300 14REMUR		CHLORINE (	POLYETHYLENE	03/20/14	
	ABOVEGROUND - IN CONTACT WITH SOIL			NONE			
97	ABOVE OUT	15000 18P	HM13-105	#2 FUEL OI	STEEL/ IRON		12/06/13
	ABOVEGROUND - ON CRIB, RACK OR CRADLE			SECONDARY WALL - EPOXY COATED STEEL			

APPENDIX C

FORMER SILVER RECOVERY UST REMOVAL DOCUMENTATION

Newsday

Long Island, NY 11747

April 17, 1989

Mr. Larry Lucks
Tyree Environmental Services
208 Route 109
Farmingdale, NY 11735

Dear Mr. Lucks:

Please provide a price quotation for the removal of the following underground storage tanks:

1) 4000 Gallon Single Wall Fiberglass Tank
Installed 1980
Contained Photographic Wastewater
7' Diameter, 14' Length
12'- 6" Inverted Elevation

2) 550 Gallon Steel Tank
Installed 1980
Contained Methanol Solution
4' Diameter, 6' Length
5'- 6" Inverted Elevation

Work is to be performed in accordance with all applicable regulations of the New York State Department of Environmental Conservation, Suffolk County Department of Health, and the Town of Huntington. Notifications and permits are to be the responsibility of Tyree Environmental Services.

The proposal is to include:

- Excavation
- Tank Removal and Disposal
- Tank Cleaning
- Remove vent pipes to grade
- Seal connecting piping
- Permits
- Backfill and compact to grade
- Waste Disposal (Waste generated from Tank number one is to be removed by Newsday's present waste hauler. Waste generated from Tank number two is to be disposed of into Newday's Sewage Treatment Plant is directed).
- Opening repair to be completed by others.

A Times Mirror
Newspaper

Please provide two price quotations: one for the removal of Tank number one and a second for the removal of Tank number two. Contact me at 756-3833 for a site visit.

Sincerely,

John Tillotson
Environmental Coordinator

/ra

(516) 249-3130

ESTIMATE

4/25/89

TB 89-154

Tyree Bros. Environmental Services Inc.

208 ROUTE 109 • FARMINGDALE, NY 11735

- EMERGENCY SPILL RESPONSE
- RECOVERY OPERATIONS
- SOLID WASTE TRANSPORTATION
- LIQUID WASTE TRANSPORTATION
- PETRO-TITE TESTING
- DRILLING & WELL INSTALLATION

Newsday
Pinelawn Road
Melville, NY

Attn: John Tillotson

Re: Premises

We propose to make the following installation at the above location:

Excavate, remove and properly dispose of one (1) - 4,000 gallon tank: cut open and clean tank of up to one (1) D.O.T. drum of bottom sludge; properly dispose of tank steel and bottom sludge; backfill excavation to grade with clean fill material; lay bluestone base over excavation:

TOTAL: $2,600.00
Plus all applicable taxes

NOTE: (1) Pumping and disposal of oil/gas/contaminated water, add $76.00 per hour trucking and .85 per gallon disposal.

(2) Removal and disposal of tank bottom sludge in excess of drum in base bid, add $475.00 per drum

(3) Excavation and disposal of contaminated soil, if required by N.Y.S. Dept. of Environmental Conservation, add
1-5 cubic yards $1,500.00
over 5 cubic yards-add $125.00 per yard

(4) TERMS: 50% down prior to commencement of job, balance due upon completion of all work

PLEASE NOTE
THIS ESTIMATE MAY BE SUBJECT
TO ADDITIONAL COSTS DUE TO
ENVIRONMENTAL REGULATIONS
BOARD CONTROL

All the above work to be completed in a first class workmanlike manner. Any unforseen conditions encountered such as rock or water will be billed as an extra on a time and material basis.

ACCEPTED:

DATE

TYREE BROS. ENVIRONMENTAL SERVICES INC.

By:

Newsday

Long Island, NY 11747

PURCHASE ORDER NO. 54477

INVOICE TO ABOVE - ATT: ACCOUNTS PAYABLE

SHIP TO: [X] Newsday, Inc. 235 Pinelawn Road Melville, L.I., N.Y. 11747

SHIP TO: [ ]

Deliveries will be accepted **only** between 9:00 A.M. & 4:30 P.M. Mon. - Fri.

TYREE BROS. ENVIRONMENTAL SERVICES, INC.
208 ROUTE 109
FARMINGDALE, NY 11735

DATE	SHIP VIA	TERMS	F.O.B.
5-5-89	YOUR SERVICE	NET 30	[X] DELIVERED [ ] SHIPPING POINT (PPD & ADD)

DELIVERY DATE	TAX EXEMPT	CERTIFICATE NUMBER	INTERNAL DISTRIBUTION (NAME, ROOM NO., LOCATION, ETC.)
6-12-89	N		JOHN TILLOTSON - ADMIN SVC

ITEM NO.	QUANTITY	DESCRIPTION	ACCOUNT NUMBER	UNIT PRICE
1		THIS PURCHASE ORDER IS ISSUED TO HAVE TYREE BROS. ENVIRONMENTAL SERVICES EXCAVATE & REMOVE ONE - 4000 GALLON FIBERGLASS TANK . SURFACE REPAIR BY OTHERS. EXCAVATE TANKS IN ACCORDANCE WITH TOWN OF HUNTINGTON, SUFFOLK COUNTY AND NEW YORK STATE REGULATIONS. PERMITS TO BE OBTAINED BY TYREE. LIQUID DISPOSAL TO BE ARRANGED BY NEWSDAY, SEE ATTACHED QUOTATION TS 89-154 CONFIRMED TO: CARI FIORE ON: 5-5-89	CAPITAL AUTH. 88-78	2,600.00 TOTAL

RECEIVING REPORT MUST BE SIGNED BY JOHN TILLOTSON

THIS ORDER IS PLACED BY NEWSDAY (THE "BUYER") SUBJECT TO THE TERMS AND CONDITIONS APPEARING HEREON AND ON THE REVERSE SIDE HEREOF, AND BY ACCEPTING THIS ORDER SELLER AGREES TO BE BOUND THEREBY.

PURCHASE ORDER NUMBER must appear on all invoices, packages, packing slips, bills of lading and correspondence pertaining to this order. COMPLETE PACKING SLIP must accompany each shipment, and indicate whether "complete" or "partial" shipment. INVOICE IN DUPLICATE together with bills of lading to the attention of Accounts Payable.

Newsday, Inc.

BY M. Lustig

MIKE LUSTIG - PURCHASING MANAGER

SELLER ACCEPTS THIS ORDER SUBJECT TO THE TERMS AND CONDITIONS ENUMERATED ON THE FACE AND BACK OF THE ORIGINAL COPY AND WILL SHIP ON THE SPECIFIED DATES SHOWN.

A Times Mirror Newspaper

12/88

REQUISITIONER

(516) 249-3150

TYREE BROS.
ENVIRONMENTAL SERVICES, INC.

208 ROUTE 109 • FARMINGDALE, NEW YORK 11735

DATE June 15, 1989

Suffolk County Dept. of Health
15 Horseblock Place
Farmingville, New York 11738

Attention: Mr. John Gladys

Re: Thursday
235 Pinelawn Rd.
Melville

Dear Mr. Gladys:

This letter is to confirm that on 6-12-89 at the above mentioned location, TYREE BROTHERS ENVIRONMENTAL SERVICES, INC. removed 1-550 and 1-4000 and disposed of same at Gershow Recycling, Medford, New York.

Very truly yours,

Matthew C. Milne

Matthew C. Milne
T.B.E.S., Inc.

MCM:dls

(516) 249-3150

INVOICE

Tyree Bros.
Environmental Services, Inc.

208 ROUTE 109 • FARMINGDALE, N.Y. 11735

- EMERGENCY SPILL RESPONSE
- RECOVERY OPERATIONS
- SOLID WASTE TRANSPORTATION
- LIQUID WASTE TRANSPORTATION
- PETRO-TITE TESTING
- *DRILLING & WELL INSTALLATION

SOLD TO
N00070
NEWSDAY
PINELAWN ROAD
MELVILLE, NY 11747

ATTN: JOHN TILLOTSON

NO. 792092
DATE 6/15/89
WORKSITE ADDRESS
235 PINELAWN RD.
MELVILLE, NY

DESCRIPTION	AMOUNT
6-12-89	
REMOVED AND PROPERLY DISPOSED OF 1-550 AND 1-4000 GAL TANK ABOVE LOCATION.	
1-550	1,700.00
1-4000	2,600.00
EXTRA IN EXCESS OF BASE BID	
DOT DRUM @ 475.00	475.00
NET AMOUNT	4,775.00
TAX	358.13
INVOICE TOTAL	5,133.13

NEWSDAY, INC.
ACCOUNTS PAYABLE VOUCHER

VOUCHER NUMBER	SPECIAL INSTRUCTIONS

APPROVALS	ACCOUNT DISTRIBUTION				DISTRIBUTION AMOUNTS
	CODE	ACCOUNT	SUB ACC'T	COST CENTER	
JT 6/19/89		CAPITAL AUTH	88.78		$5,133.13

DESCRIPTION: TANK REMOVAL

APPENDIX D

LABORATORY ANALYTICAL REPORT – FIXER PIPING, APRIL 24, 2018

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

April 30, 2018

Joseph Spinelli
H2M Architects & Engineers
538 Broadhollow Road, 4th Floor East
Melville, NY 11747
TEL: (631) 756-8000
FAX

RE: Fixer Pipe Sampling, RCRA Closure, Melvi Order No.: 1804167

Dear Joseph Spinelli:

American Analytical Laboratories, LLC. received 4 sample(s) on 4/24/2018 for the analyses presented in the following report.

Samples were analyzed in accordance with the test procedures documented on the chain of custody and detailed throughout the text of this report. The results reported herein relate only to the items tested or to the samples as received by the laboratory. This report may not be reproduced, except in full, without the approval of American Analytical Laboratories, LLC and is not considered complete without a cover page and chain of custody documentation. The limits (LOQ) provided in the data package are analytical reporting limits and not Federal or Local mandated values to which the sample results should be compared.

There were no problems with the analyses and all data for associated QC met laboratory specifications. If there are any exceptions a Case Narrative is provided in the report or the data is qualified either on the sample results or in the QC section of the report. This package has been reviewed by American Analytical Laboratories' QA Department/Laboratory Director to comply with NELAC standards prior to report submittal.

If you have any questions regarding these tests results, please do not hesitate to call (631) 454-6100 or email me directly at lbeyer@american-analytical.com.

Sincerely,

Lori Beyer

Lori Beyer
Lab Director
American Analytical Laboratories, LLC.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Workorder Sample Summary

WO#: **1804167**

30-Apr-18

CLIENT: H2M Architects & Engineers

Project: Fixer Pipe Sampling, RCRA Closure, Melville,

Lab SampleID	Client Sample ID	Tag No	Date Collected	Date Received	Matrix
1804167-001A	Equip Blank		4/24/2018 10:30:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-001B	Equip Blank		4/24/2018 10:30:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-002A	Fixer Mail Center		4/24/2018 10:50:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-002B	Fixer Mail Center		4/24/2018 10:50:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-003A	Fixer MER-1		4/24/2018 11:04:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-003B	Fixer MER-1		4/24/2018 11:04:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-004A	Fixer Basement		4/24/2018 11:18:00 AM	4/24/2018 12:30:51 PM	Liquid
1804167-004B	Fixer Basement		4/24/2018 11:18:00 AM	4/24/2018 12:30:51 PM	Liquid

CHAIN OF CUSTODY

AMERICAN ANALYTICAL LABORATORIES

56 Toledo Street, Farmingdale NY 11735
(T) 631-454-6100 (F) 631-454-8027
www.american-analytical.com

CERTIFICATIONS
NY ELAP - 11418 PA DEP - 68-00573
NJ DEP - NY050 CT DOH - PH-0205

Client Information

Company Name: H2M architects + engineers
Address: 290 Broadhollow Rd, Suite 400E
City: Melville State: NY Zip: 11747
Project Contact: Joseph Spinelli
Phone #: (631) 756-8000 x1640
E-mail: JSpinelli@h2m.com

Project Information

Project Name: Fixer Pipe Sampling for RCRA Closure
Street:
City: Melville State: NY Zip: 11747
Project # / Purchase Order #: NEWD18
Sampler's Name / Company: Joseph Spinelli (H2M)
Sampler's Signature: Joseph Spinelli

Analytical Test / Information

LAB SAMPLE # (LAB USE ONLY)	Client Sample ID	Sample Type	Matrix Code	Date	Time	Glass / Plastic	Total # of bottles	Number of Each Preserved Bottle: NONE	HCl	NaOH	HNO_3	H_2SO_4	DI Water (5035A)	MeOH	OTHER	TAL Metals	VOCs
1804167-001A,B	Equip Blank	G	L	4/24/18	10:30	G/P	3		2		1					X	X
002 MW2	Fixer Mail Center	G	L		10:50		3		2		1					X	X
003 MW3	Fixer MER-1	G	L		11:04		3		2		1					X	X
004 MW1	Fixer Basement	G	L	↓	11:18	↓	3		2		1					X	X

Turnaround Time (Business Days)

Standard
[ ] 7-10 Business Days
[ ] 3 Day *RUSH*
[X] 5 Day *RUSH* One Week
[ ] 2 Day *RUSH*
[ ] 4 Day *RUSH*
[ ] 1 Day *RUSH*

Please contact laboratory for rush service availability

SAMPLE TYPE

G = Grab
C = Composite
B = Blank

MATRIX CODE

L = Liquid **PC** = Paint Chip
S = Soil **SL** = Sludge
O = Oil **SD** = Solid
W = Wipe **M** = Misc

ELECTRONIC DELIVERABLES

NYCRR Part 375 - please circle
Unres/ Comm/ Industrial/ Residential/ Res Residential/ PGW
NJ Soil Clean Up Criteria **SCDOH Action Levels**
CP 51 - Gas / Fuel **TCLP Hazardous Waste**
TOGS **NYSDEC EQUIS**

Comments / Remarks

Cooler Temp: 4°C

Sample custody must be documented below, each time samples change possession, with a signature, date, and time.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
Joseph Spinelli	4/24/18 1220	Joseph Spinelli		4/24/2018 1220	JMULLADY
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Sample Log-In Check List

Client Name: **H2M ARCHITECTS** Work Order Number: **1804167** RcptNo: **1**

Logged by:	**Jenny Mullady**	**4/24/2018 12:30:51 PM**	Jenny Mullady
Completed By:	**Jenny Mullady**	**4/24/2018**	Jenny Mullady
Reviewed By:	**Lori Beyer**	**4/24/2018 12:39:13 PM**	Lori Beyer

Chain of Custody

1.	Is Chain of Custody complete?	Yes ☑	No ☐	Not Present ☐
2.	How was the sample delivered?	Client		

Log In

3.	Coolers are present?	Yes ☑	No ☐	NA ☐
4.	Shipping container/cooler in good condition?	Yes ☑	No ☐	
	Custody seals intact on shipping container/cooler?	Yes ☐	No ☐	Not Present ☑
	No. Seal Date:	Signed By:		
5.	Was an attempt made to cool the samples?	Yes ☑	No ☐	NA ☐
6.	Were all samples received at a temperature of >0° C to 6.0°C	Yes ☑	No ☐	NA ☐
7.	Sample(s) in proper container(s)?	Yes ☑	No ☐	
8.	Sufficient sample volume for indicated test(s)?	Yes ☑	No ☐	
9.	Are samples (except VOA and ONG) properly preserved?	Yes ☑	No ☐	
10.	Was preservative added to bottles?	Yes ☐	No ☑	NA ☐
11.	Is the headspace in the VOA vials less than 1/4 inch or 6 mm?	Yes ☑	No ☐	No VOA Vials ☐
12.	Were any sample containers received broken?	Yes ☐	No ☑	
13.	Does paperwork match bottle labels? (Note discrepancies on chain of custody)	Yes ☑	No ☐	
14.	Are matrices correctly identified on Chain of Custody?	Yes ☑	No ☐	
15.	Is it clear what analyses were requested?	Yes ☑	No ☐	
16.	Were all holding times able to be met? (If no, notify customer for authorization.)	Yes ☑	No ☐	

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☑

Person Notified: Date

By Whom: Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person

Regarding:

Client Instructions:

18. Additional remarks:

Cooler Information

Cooler No	Temp ºC	Condition	Seal Intact	Seal No	Seal Date	Signed By

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Case Narrative

WO#: **1804167**
Date: **4/30/2018**

CLIENT: H2M Architects & Engineers
Project: Fixer Pipe Sampling, RCRA Closure, Melville,

Samples were analyzed using the methods outlined in the following references:

Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW846 and additional methods as detailed throughout the text of the report. All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objectives with exceptions notated in this Narrative discussion of this report.

Volatile LCS are analyzed with preservatives - HCL/NaHSO4/Methanol depending on level of analysis (high/low) similar to sample analysis. Outliers can be attributed to the presence of chemical preservatives. 2-Chloroethyl vinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

The test results meet the requirements of the NYSDOH and NELAC standards, except where noted. The information contained in this analytical report is the sole property of American Analytical Laboratories, LLC. or the client for which this report was issued. The results contained in this report are only representative of the samples received. The sample receipt checklist is included as part of this lab report. Conditions can vary at different times and at different sampling conditions. American Analytical is not responsible for the use or interpretation of the data included herein.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Definition Only

WO#: **1804167**
Date: **4/30/2018**

Definitions:

Sample Result and QC Summary Qualifiers - Level I and Level II Reports
ND - Not detected at the reporting limit/Limit of Quantitation

B - The analyte was detected in the associated method blank. For volatiles, methylene chloride and acetone are common lab contaminants. Data users should consider anything <5x the blank value as artifact.

E - The value is above the quantitation range

D - Analyte concentration was obtained from diluted analysis or from analysis using reduced sample volume.

J - The analyte was detected below the limit of quantitation but greater than the established Limit of Detection (LOD). There is greater uncertainty associated with these results and data should be considered as estimated.

U - The compound was analyzed for but not detected.

H - Holding time for preparation or analysis has been exceeded.

S - Spike recovery is outside accepted recovery limits.

R - RPD is outside accepted recovery range.

P - Secondary column exceeds 40% difference for GC test.

* - Calibration exceeds method requirement. Due to the large number of analytes for organic testing, the method allows 10% of analytes to have %RSD and/or %D to be >20%.
LOD - Limit of Detection; the lowest level the analyte can be determined to be statistically different from a blank.
LOQ - Limit of Quantitation; the lowest amount of analyte in a sample that can be quantitatively determined with suitable precision and accuracy.
PQL - Practical Quantitation Limit; the lowest level that can be reliably achieved within the specific limits of Precision and accuracy. Listed on the QC Summary Forms.
m - Analyte was manually integrated for GC/MS.
+ - Concentration exceeds regulatory level for TCLP

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Equip Blank
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:30:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
1,1,1,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1,1-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1,2,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1,2-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,1-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2,3-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2,3-Trichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2,4,5-Tetramethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2,4-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2,4-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2-Dibromo-3-chloropropane	ND	0.030	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2-Dibromoethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,3,5-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,3-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,3-dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,4-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
1,4-Dioxane	ND	0.25	1.0	U	µg/L	1	4/24/2018 4:06:00 PM
2,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
2-Butanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:06:00 PM
2-Chloroethyl vinyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
2-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
2-Hexanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:06:00 PM
2-Propanol	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
4-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
4-Isopropyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
4-Methyl-2-pentanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:06:00 PM
Acetone	ND	5.0	5.0	U	µg/L	1	4/24/2018 4:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Equip Blank
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:30:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
Benzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Bromobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Bromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Bromodichloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Bromoform	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Bromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Carbon disulfide	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Carbon tetrachloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Chlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Chlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Chloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Chloroform	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Chloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
cis-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
cis-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Cyclohexane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Dibromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Dibromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Dichlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Diisopropyl ether	ND	0.50	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Ethanol	ND	2.5	10	U	µg/L	1	4/24/2018 4:06:00 PM
Ethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Freon-114	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Hexachlorobutadiene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Isopropylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
m,p-Xylene	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:06:00 PM
Methyl Acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Methyl tert-butyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Methylene chloride	ND	5.0	5.0	U	µg/L	1	4/24/2018 4:06:00 PM
n-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
n-Propylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Naphthalene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
o-Xylene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Equip Blank
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:30:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
p-Diethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
p-Ethyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
sec-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Styrene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
t-Butyl alcohol	ND	2.5	10	U	µg/L	1	4/24/2018 4:06:00 PM
tert-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Tetrachloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Toluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
trans-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
trans-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Trichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Trichlorofluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Vinyl acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Vinyl chloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM
Xylenes, Total	ND	0.75	6.0	U	µg/L	1	4/24/2018 4:06:00 PM
Acrolein	ND	1.0	10	U	µg/L	1	4/24/2018 4:06:00 PM
Acrylonitrile	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Equip Blank
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:30:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-001B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
MERCURY, TOTAL			**E245.1 REV3.0 1994**		**E245.1 REV3.0**		Analyst: **JP**
Mercury	0.000230	0.000150	0.000300	J	mg/L	1	4/30/2018 11:13:26 AM
TOTAL METALS			**E200.7 REV4.4 1994**		**E200.7 REV4.4**		Analyst: **JP**
Aluminum	0.0262	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM
Antimony	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Arsenic	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:13:48 AM
Barium	0.0261	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM
Beryllium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Cadmium	ND	0.00500	0.0100	U	mg/L	1	4/30/2018 10:13:48 AM
Calcium	2.57	0.00500	0.0250		mg/L	1	4/30/2018 10:13:48 AM
Chromium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Cobalt	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Copper	0.0280	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM
Iron	0.107	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM
Lead	0.0122	0.00500	0.0150	J	mg/L	1	4/30/2018 10:13:48 AM
Magnesium	0.617	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM
Manganese	0.00594	0.00500	0.0200	J	mg/L	1	4/30/2018 10:13:48 AM
Nickel	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Potassium	0.0741	0.0500	0.200	J	mg/L	1	4/30/2018 10:13:48 AM
Selenium	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:13:48 AM
Silver	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Sodium	0.457	0.0100	0.0300		mg/L	1	4/30/2018 10:13:48 AM
Thallium	ND	0.0100	0.0150	U	mg/L	1	4/30/2018 10:13:48 AM
Vanadium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:13:48 AM
Zinc	0.0764	0.00500	0.0200		mg/L	1	4/30/2018 10:13:48 AM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Mail Center
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:50:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
1,1,1,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1,1-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1,2,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1,2-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,1-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2,3-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2,3-Trichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2,4,5-Tetramethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2,4-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2,4-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2-Dibromo-3-chloropropane	ND	0.030	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2-Dibromoethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,3,5-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,3-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,3-dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,4-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
1,4-Dioxane	ND	0.25	1.0	U	µg/L	1	4/24/2018 4:36:00 PM
2,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
2-Butanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:36:00 PM
2-Chloroethyl vinyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
2-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
2-Hexanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:36:00 PM
2-Propanol	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
4-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
4-Isopropyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
4-Methyl-2-pentanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:36:00 PM
Acetone	ND	5.0	5.0	U	µg/L	1	4/24/2018 4:36:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Mail Center
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:50:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
Benzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Bromobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Bromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Bromodichloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Bromoform	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Bromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Carbon disulfide	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Carbon tetrachloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Chlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Chlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Chloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Chloroform	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Chloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
cis-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
cis-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Cyclohexane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Dibromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Dibromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Dichlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Diisopropyl ether	ND	0.50	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Ethanol	ND	2.5	10	U	µg/L	1	4/24/2018 4:36:00 PM
Ethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Freon-114	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Hexachlorobutadiene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Isopropylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
m,p-Xylene	ND	0.50	4.0	U	µg/L	1	4/24/2018 4:36:00 PM
Methyl Acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Methyl tert-butyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Methylene chloride	ND	5.0	5.0	U	µg/L	1	4/24/2018 4:36:00 PM
n-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
n-Propylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Naphthalene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
o-Xylene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Mail Center
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:50:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
p-Diethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
p-Ethyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
sec-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Styrene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
t-Butyl alcohol	ND	2.5	10	U	µg/L	1	4/24/2018 4:36:00 PM
tert-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Tetrachloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Toluene	0.28	0.25	2.0	J	µg/L	1	4/24/2018 4:36:00 PM
trans-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
trans-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Trichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Trichlorofluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Vinyl acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Vinyl chloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM
Xylenes, Total	ND	0.75	6.0	U	µg/L	1	4/24/2018 4:36:00 PM
Acrolein	ND	1.0	10	U	µg/L	1	4/24/2018 4:36:00 PM
Acrylonitrile	ND	0.25	2.0	U	µg/L	1	4/24/2018 4:36:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Mail Center
Lab Order:	1804167	**Collection Date:**	4/24/2018 10:50:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-002B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
MERCURY, TOTAL			**E245.1 REV3.0 1994**		**E245.1 REV3.0**		Analyst: **JP**
Mercury	0.000210	0.000150	0.000300	J	mg/L	1	4/30/2018 11:15:33 AM
TOTAL METALS			**E200.7 REV4.4 1994**		**E200.7 REV4.4**		Analyst: **JP**
Aluminum	0.0759	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM
Antimony	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Arsenic	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:15:53 AM
Barium	0.0265	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM
Beryllium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Cadmium	ND	0.00500	0.0100	U	mg/L	1	4/30/2018 10:15:53 AM
Calcium	2.67	0.00500	0.0250		mg/L	1	4/30/2018 10:15:53 AM
Chromium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Cobalt	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Copper	0.0346	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM
Iron	0.273	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM
Lead	ND	0.00500	0.0150	U	mg/L	1	4/30/2018 10:15:53 AM
Magnesium	0.574	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM
Manganese	0.00537	0.00500	0.0200	J	mg/L	1	4/30/2018 10:15:53 AM
Nickel	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Potassium	0.0771	0.0500	0.200	J	mg/L	1	4/30/2018 10:15:53 AM
Selenium	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:15:53 AM
Silver	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Sodium	0.280	0.0100	0.0300		mg/L	1	4/30/2018 10:15:53 AM
Thallium	ND	0.0100	0.0150	U	mg/L	1	4/30/2018 10:15:53 AM
Vanadium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:15:53 AM
Zinc	0.101	0.00500	0.0200		mg/L	1	4/30/2018 10:15:53 AM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer MER-1
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:04:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-003A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
1,1,1,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1,1-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1,2,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1,2-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,1-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2,3-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2,3-Trichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2,4,5-Tetramethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2,4-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2,4-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2-Dibromo-3-chloropropane	ND	0.030	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2-Dibromoethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,3,5-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,3-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,3-dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,4-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
1,4-Dioxane	ND	0.25	1.0	U	µg/L	1	4/24/2018 5:06:00 PM
2,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
2-Butanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:06:00 PM
2-Chloroethyl vinyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
2-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
2-Hexanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:06:00 PM
2-Propanol	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
4-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
4-Isopropyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
4-Methyl-2-pentanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:06:00 PM
Acetone	ND	5.0	5.0	U	µg/L	1	4/24/2018 5:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer MER-1
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:04:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-003A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
Benzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Bromobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Bromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Bromodichloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Bromoform	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Bromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Carbon disulfide	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Carbon tetrachloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Chlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Chlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Chloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Chloroform	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Chloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
cis-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
cis-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Cyclohexane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Dibromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Dibromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Dichlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Diisopropyl ether	ND	0.50	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Ethanol	ND	2.5	10	U	µg/L	1	4/24/2018 5:06:00 PM
Ethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Freon-114	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Hexachlorobutadiene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Isopropylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
m,p-Xylene	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:06:00 PM
Methyl Acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Methyl tert-butyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Methylene chloride	ND	5.0	5.0	U	µg/L	1	4/24/2018 5:06:00 PM
n-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
n-Propylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Naphthalene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
o-Xylene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer MER-1
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:04:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-003A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
p-Diethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
p-Ethyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
sec-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Styrene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
t-Butyl alcohol	ND	2.5	10	U	µg/L	1	4/24/2018 5:06:00 PM
tert-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Tetrachloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Toluene	0.30	0.25	2.0	J	µg/L	1	4/24/2018 5:06:00 PM
trans-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
trans-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Trichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Trichlorofluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Vinyl acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Vinyl chloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM
Xylenes, Total	ND	0.75	6.0	U	µg/L	1	4/24/2018 5:06:00 PM
Acrolein	ND	1.0	10	U	µg/L	1	4/24/2018 5:06:00 PM
Acrylonitrile	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:06:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer MER-1
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:04:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-003B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
MERCURY, TOTAL			**E245.1 REV3.0 1994**		**E245.1 REV3.0**		Analyst: **JP**
Mercury	0.000190	0.000150	0.000300	J	mg/L	1	4/30/2018 11:17:41 AM
TOTAL METALS			**E200.7 REV4.4 1994**		**E200.7 REV4.4**		Analyst: **JP**
Aluminum	0.266	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Antimony	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:17:59 AM
Arsenic	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:17:59 AM
Barium	0.0241	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Beryllium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:17:59 AM
Cadmium	ND	0.00500	0.0100	U	mg/L	1	4/30/2018 10:17:59 AM
Calcium	2.04	0.00500	0.0250		mg/L	1	4/30/2018 10:17:59 AM
Chromium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:17:59 AM
Cobalt	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:17:59 AM
Copper	0.0296	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Iron	11.7	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Lead	ND	0.00500	0.0150	U	mg/L	1	4/30/2018 10:17:59 AM
Magnesium	0.598	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Manganese	0.0310	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Nickel	0.00408	0.00500	0.0200	J	mg/L	1	4/30/2018 10:17:59 AM
Potassium	0.895	0.0500	0.200		mg/L	1	4/30/2018 10:17:59 AM
Selenium	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:17:59 AM
Silver	0.0221	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM
Sodium	5.01	0.0100	0.0300		mg/L	1	4/30/2018 10:17:59 AM
Thallium	ND	0.0100	0.0150	U	mg/L	1	4/30/2018 10:17:59 AM
Vanadium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:17:59 AM
Zinc	0.0321	0.00500	0.0200		mg/L	1	4/30/2018 10:17:59 AM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Basement
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:18:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-004A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
1,1,1,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1,1-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1,2,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1,2-Trichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,1-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2,3-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2,3-Trichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2,4,5-Tetramethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2,4-Trichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2,4-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2-Dibromo-3-chloropropane	ND	0.030	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2-Dibromoethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2-Dichloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,3,5-Trimethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,3-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,3-dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,4-Dichlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
1,4-Dioxane	ND	0.25	1.0	U	µg/L	1	4/24/2018 5:36:00 PM
2,2-Dichloropropane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
2-Butanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:36:00 PM
2-Chloroethyl vinyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
2-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
2-Hexanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:36:00 PM
2-Propanol	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
4-Chlorotoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
4-Isopropyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
4-Methyl-2-pentanone	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:36:00 PM
Acetone	ND	5.0	5.0	U	µg/L	1	4/24/2018 5:36:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Basement
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:18:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-004A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
Benzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Bromobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Bromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Bromodichloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Bromoform	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Bromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Carbon disulfide	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Carbon tetrachloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Chlorobenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Chlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Chloroethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Chloroform	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Chloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
cis-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
cis-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Cyclohexane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Dibromochloromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Dibromomethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Dichlorodifluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Diisopropyl ether	ND	0.50	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Ethanol	ND	2.5	10	U	µg/L	1	4/24/2018 5:36:00 PM
Ethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Freon-114	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Hexachlorobutadiene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Isopropylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
m,p-Xylene	ND	0.50	4.0	U	µg/L	1	4/24/2018 5:36:00 PM
Methyl Acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Methyl tert-butyl ether	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Methylene chloride	ND	5.0	5.0	U	µg/L	1	4/24/2018 5:36:00 PM
n-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
n-Propylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Naphthalene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
o-Xylene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Basement
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:18:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-004A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260			**SW8260C**		**SW5030C**		Analyst: **LA**
p-Diethylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
p-Ethyltoluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
sec-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Styrene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
t-Butyl alcohol	ND	2.5	10	U	µg/L	1	4/24/2018 5:36:00 PM
tert-Butylbenzene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Tetrachloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Toluene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
trans-1,2-Dichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
trans-1,3-Dichloropropene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Trichloroethene	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Trichlorofluoromethane	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Vinyl acetate	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Vinyl chloride	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM
Xylenes, Total	ND	0.75	6.0	U	µg/L	1	4/24/2018 5:36:00 PM
Acrolein	ND	1.0	10	U	µg/L	1	4/24/2018 5:36:00 PM
Acrylonitrile	ND	0.25	2.0	U	µg/L	1	4/24/2018 5:36:00 PM

American Analytical Laboratories, LLC.

Date: *30-Apr-18*

ELAP ID : 11418

CLIENT:	H2M Architects & Engineers	**Client Sample ID:**	Fixer Basement
Lab Order:	1804167	**Collection Date:**	4/24/2018 11:18:00 AM
Project:	Fixer Pipe Sampling, RCRA Closure, Melville,	**Matrix:**	LIQUID
Lab ID:	1804167-004B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
MERCURY, TOTAL			**E245.1 REV3.0 1994**		**E245.1 REV3.0**		Analyst: **JP**
Mercury	0.000170	0.000150	0.000300	J	mg/L	1	4/30/2018 11:19:49 AM
TOTAL METALS			**E200.7 REV4.4 1994**		**E200.7 REV4.4**		Analyst: **JP**
Aluminum	3.21	0.00500	0.0200		mg/L	1	4/30/2018 10:20:04 AM
Antimony	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Arsenic	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:20:04 AM
Barium	0.0278	0.00500	0.0200		mg/L	1	4/30/2018 10:20:04 AM
Beryllium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Cadmium	ND	0.00500	0.0100	U	mg/L	1	4/30/2018 10:20:04 AM
Calcium	2.61	0.00500	0.0250		mg/L	1	4/30/2018 10:20:04 AM
Chromium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Cobalt	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Copper	0.00631	0.00500	0.0200	J	mg/L	1	4/30/2018 10:20:04 AM
Iron	0.145	0.00500	0.0200		mg/L	1	4/30/2018 10:20:04 AM
Lead	ND	0.00500	0.0150	U	mg/L	1	4/30/2018 10:20:04 AM
Magnesium	0.528	0.00500	0.0200		mg/L	1	4/30/2018 10:20:04 AM
Manganese	0.00813	0.00500	0.0200	J	mg/L	1	4/30/2018 10:20:04 AM
Nickel	0.00427	0.00500	0.0200	J	mg/L	1	4/30/2018 10:20:04 AM
Potassium	0.296	0.0500	0.200		mg/L	1	4/30/2018 10:20:04 AM
Selenium	ND	0.0100	0.0250	U	mg/L	1	4/30/2018 10:20:04 AM
Silver	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Sodium	4.50	0.0100	0.0300		mg/L	1	4/30/2018 10:20:04 AM
Thallium	ND	0.0100	0.0150	U	mg/L	1	4/30/2018 10:20:04 AM
Vanadium	ND	0.00500	0.0200	U	mg/L	1	4/30/2018 10:20:04 AM
Zinc	0.130	0.00500	0.0200		mg/L	1	4/30/2018 10:20:04 AM

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Materials Management, Region 1
SUNY @ Stony Brook, 50 Circle Road, Stony Brook, NY 11790
P: (631) 444-0375 I F: (631) 444-0231
www.dec.ny.gov

Sent by email to steve.zimmerman@newsday.com

August 10, 2018

Mr. Stephen Zimmerman
Director of Engineering Services
235 Pinelawn Road
Melville, NY 11747

Re: Closure of Facility: Newsday LLC
235 Pinelawn Road
Melville, NY
EPA Identification Number: NYD052782497

Dear Mr. Zimmerman:

The revised Closure Plan/QAPP for this facility dated July 18, 2018 is acceptable.

Under the provisions of the New York State regulations, 6NYCRR Part 373-3.7, when the owner or operator of a facility submits a closure plan, opportunity must be provided through a newspaper notice for the affected public to comment prior to Departmental approval.

Therefore, to satisfy the aforementioned regulatory requirements in conjunction with closure of the facility, the enclosed Public Notice must be published unedited in its entirety for one day, either in the official newspaper for the town in which the facility is located, or in Newsday.

The notice should not be revised or edited unless you have been authorized to do so by this office. Minor revisions may be authorized by telephone if necessary.

Please instruct the newspaper publisher to provide this office with an affidavit of publication. You are responsible for the cost of publication.

Once the 30-day comment period has expired and, if no comments are received, a letter approving your closure plan will be sent.

If you have any questions, please contact me at 631-444-0233.

Sincerely,

Tatiana Klappas, P.E.
Professional Engineer 1

Eclosure
ec: C. Engelhardt, DMM, R1
P. Lageraaen, H2M
L. Wu, H2M
File/eDocs

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	1,1,1-Trichloroethane	Effluent Gross	11/30/1996	10	Non Report	ug/L	DAILY MX	
001M	1,1,1-Trichloroethane	Effluent Gross	12/31/1996	10	Non Report	ug/L	DAILY MX	
001M	1,1,1-Trichloroethane	Effluent Gross	01/31/1997	10	Non Report	ug/L	DAILY MX	
001M	1,1,1-Trichloroethane	Effluent Gross	02/28/1997	10	Non Report	ug/L	DAILY MX	
001M	1,2,4,5-Tetramethylbenzene	Effluent Gross	07/31/1999	5	Non Report	ug/L	DAILY MX	
001M	1,3,5-Trimethylbenzene	Effluent Gross	07/31/1999	5	Non Report	ug/L	DAILY MX	
001M	Benzene	Effluent Gross	11/30/1996	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	12/31/1996	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	01/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	02/28/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	03/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	04/30/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	05/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	06/30/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	07/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	08/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	09/30/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	10/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	11/30/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	12/31/1997	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	01/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	02/28/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	03/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	04/30/1998	.7	<1	ug/L	DAILY MX	43

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Benzene	Effluent Gross	05/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	06/30/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	07/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	08/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	09/30/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	10/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	11/30/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	12/31/1998	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	01/31/1999	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	02/28/1999	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	03/31/1999	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	06/30/1999	.7	<1	ug/L	DAILY MX	43
001M	Benzene	Effluent Gross	07/31/1999	.7	<1	ug/L	DAILY MX	43
001M	Cyanide, total [as CN]	Effluent Gross	06/30/1997	.4	<3	mg/L	DAILY MX	650
001M	Cyanide, total [as CN]	Effluent Gross	01/31/2004	.4	Non Report	mg/L	DAILY MX	
001M	Flow rate	Effluent Gross	10/31/2001		Non Report	gal/d	DAILY MX	
001M	Flow rate	Effluent Gross	04/30/2006		Non Report	gal/d	DAILY AV	
001M	Flow rate	Effluent Gross	04/30/2006		Non Report	gal/d	DAILY MX	
001M	Nitrogen, total [as N]	Effluent Gross	12/31/1997	10	10.2	mg/L	DAILY MX	2
001M	Nitrogen, total [as N]	Effluent Gross	01/31/1998	10	12.7	mg/L	DAILY MX	27
001M	Nitrogen, total [as N]	Effluent Gross	03/31/1998	10	14.1	mg/L	DAILY MX	41
001M	Nitrogen, total [as N]	Effluent Gross	06/30/1998	10	16.1	mg/L	DAILY MX	61
001M	Nitrogen, total [as N]	Effluent Gross	01/31/1999	10	38.5	mg/L	DAILY MX	285
001M	Nitrogen, total [as N]	Effluent Gross	02/28/1999	10	11.56	mg/L	DAILY MX	16
001M	Nitrogen, total [as N]	Effluent Gross	04/30/1999	10	10.37	mg/L	DAILY MX	4

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Nitrogen, total [as N]	Effluent Gross	09/30/1999	10	14.26	mg/L	DAILY MX	43
001M	Nitrogen, total [as N]	Effluent Gross	10/31/1999	10	18.2	mg/L	DAILY MX	82
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2000	10	10.78	mg/L	DAILY MX	8
001M	Nitrogen, total [as N]	Effluent Gross	05/31/2000	10	12.1	mg/L	DAILY MX	21
001M	Nitrogen, total [as N]	Effluent Gross	06/30/2000	10	40	mg/L	DAILY MX	300
001M	Nitrogen, total [as N]	Effluent Gross	08/31/2000	10	22	mg/L	DAILY MX	120
001M	Nitrogen, total [as N]	Effluent Gross	11/30/2000	10	64	mg/L	DAILY MX	540
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2001	10	21	mg/L	DAILY MX	110
001M	Nitrogen, total [as N]	Effluent Gross	02/28/2001	10	12	mg/L	DAILY MX	20
001M	Nitrogen, total [as N]	Effluent Gross	12/31/2001	10	12	mg/L	DAILY MX	20
001M	Nitrogen, total [as N]	Effluent Gross	04/30/2002	10	12	mg/L	DAILY MX	20
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2003	10	16	mg/L	DAILY MX	60
001M	Nitrogen, total [as N]	Effluent Gross	03/31/2003	10	11	mg/L	DAILY MX	10
001M	Nitrogen, total [as N]	Effluent Gross	10/31/2003	10	12	mg/L	DAILY MX	20
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2004	10	Non Report	mg/L	DAILY MX	
001M	Nitrogen, total [as N]	Effluent Gross	03/31/2004	10	38	mg/L	DAILY MX	280
001M	Nitrogen, total [as N]	Effluent Gross	05/31/2004	10	21	mg/L	DAILY MX	110
001M	Nitrogen, total [as N]	Effluent Gross	09/30/2004	10	15	mg/L	DAILY MX	50
001M	Nitrogen, total [as N]	Effluent Gross	11/30/2004	10	16	mg/L	DAILY MX	60
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2005	10	28	mg/L	DAILY MX	180
001M	Nitrogen, total [as N]	Effluent Gross	03/31/2005	10	22	mg/L	DAILY MX	120
001M	Nitrogen, total [as N]	Effluent Gross	06/30/2005	10	21	mg/L	DAILY MX	110
001M	Nitrogen, total [as N]	Effluent Gross	10/31/2005	10	13	mg/L	DAILY MX	30
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2006	10	18	mg/L	DAILY MX	80
001M	Nitrogen, total [as N]	Effluent Gross	02/28/2006	10	14	mg/L	DAILY MX	40

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Nitrogen, total [as N]	Effluent Gross	03/31/2006	10	14	mg/L	DAILY MX	40
001M	Nitrogen, total [as N]	Effluent Gross	06/30/2006	10	16	mg/L	DAILY MX	60
001M	Nitrogen, total [as N]	Effluent Gross	07/31/2006	10	=11	mg/L	DAILY MX	10
001M	Nitrogen, total [as N]	Effluent Gross	10/31/2006	10	=12	mg/L	DAILY MX	20
001M	Nitrogen, total [as N]	Effluent Gross	11/30/2006	10	=11	mg/L	DAILY MX	10
001M	Nitrogen, total [as N]	Effluent Gross	12/31/2006	10	=11	mg/L	DAILY MX	10
001M	Nitrogen, total [as N]	Effluent Gross	01/31/2007	10	=31	mg/L	DAILY MX	210
001M	Nitrogen, total [as N]	Effluent Gross	02/28/2007	10	=41	mg/L	DAILY MX	310
001M	Nitrogen, total [as N]	Effluent Gross	03/31/2007	10	=48	mg/L	DAILY MX	380
001M	Nitrogen, total [as N]	Effluent Gross	04/30/2007	10	=14	mg/L	DAILY MX	40
001M	Nitrogen, total [as N]	Effluent Gross	05/31/2007	10	=20	mg/L	DAILY MX	100
001M	Oil & Grease	Effluent Gross	12/31/1996	15	20	mg/L	DAILY MX	33
001M	Oil & Grease	Effluent Gross	03/31/1997	15	119	mg/L	DAILY MX	693
001M	Oil & Grease	Effluent Gross	04/30/1997	15	18	mg/L	DAILY MX	20
001M	Oil & Grease	Effluent Gross	07/31/1997	15	50.4	mg/L	DAILY MX	236
001M	Oil & Grease	Effluent Gross	09/30/1997	15	32	mg/L	DAILY MX	113
001M	Oil & Grease	Effluent Gross	10/31/1997	15	18	mg/L	DAILY MX	20
001M	Oil & Grease	Effluent Gross	01/31/1998	15	17	mg/L	DAILY MX	13
001M	Oil & Grease	Effluent Gross	06/30/1998	15	24.4	mg/L	DAILY MX	63
001M	Oil & Grease	Effluent Gross	02/28/1999	15	31.7	mg/L	DAILY MX	111
001M	Oil & Grease	Effluent Gross	09/30/1999	15	15.2	mg/L	DAILY MX	1
001M	Oil & Grease	Effluent Gross	10/31/1999	15	23.8	mg/L	DAILY MX	59
001M	Oil & Grease	Effluent Gross	09/30/2003	15	31	mg/L	DAILY MX	107
001M	Oil & Grease	Effluent Gross	01/31/2004	15	Non Report	mg/L	DAILY MX	
001M	Oil & Grease	Effluent Gross	03/31/2004	15	18	mg/L	DAILY MX	20

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	p-Ethyltoluene	Effluent Gross	07/31/1999	5	Non Report	ug/L	DAILY MX	
001M	pH	Effluent Gross	03/31/1997	6.5	5.8	SU	MINIMUM	
001M	pH	Effluent Gross	05/31/1997	6.5	6.2	SU	MINIMUM	
001M	pH	Effluent Gross	06/30/1997	8.5	8.8	SU	MAXIMUM	
001M	pH	Effluent Gross	07/31/1997	8.5	8.7	SU	MAXIMUM	
001M	pH	Effluent Gross	10/31/1997	8.5	Non Report	SU	MAXIMUM	
001M	pH	Effluent Gross	11/30/1997	6.5	6.4	SU	MINIMUM	
001M	pH	Effluent Gross	11/30/1997	8.5	9	SU	MAXIMUM	
001M	pH	Effluent Gross	12/31/1997	8.5	8.9	SU	MAXIMUM	
001M	pH	Effluent Gross	03/31/1998	6.5	6.3	SU	MINIMUM	
001M	pH	Effluent Gross	03/31/1998	8.5	9.2	SU	MAXIMUM	
001M	pH	Effluent Gross	04/30/1998	6.5	6.3	SU	MINIMUM	
001M	pH	Effluent Gross	04/30/1998	8.5	9.9	SU	MAXIMUM	
001M	pH	Effluent Gross	05/31/1998	8.5	9	SU	MAXIMUM	
001M	pH	Effluent Gross	11/30/1998	6.5	6.3	SU	MINIMUM	
001M	pH	Effluent Gross	06/30/1999	6.5	6	SU	MINIMUM	
001M	pH	Effluent Gross	07/31/1999	6.5	6.2	SU	MINIMUM	
001M	pH	Effluent Gross	09/30/1999	8.5	9	SU	MAXIMUM	
001M	pH	Effluent Gross	11/30/1999	8.5	9.2	SU	MAXIMUM	
001M	pH	Effluent Gross	06/30/2000	6.5	6.1	SU	MINIMUM	
001M	pH	Effluent Gross	09/30/2000	6.5	6.1	SU	MINIMUM	
001M	pH	Effluent Gross	10/31/2000	6.5	6.3	SU	MINIMUM	
001M	pH	Effluent Gross	12/31/2000	6.5	6.4	SU	MINIMUM	
001M	pH	Effluent Gross	12/31/2000	8.5	8.7	SU	MAXIMUM	
001M	pH	Effluent Gross	01/31/2001	6.5	6.4	SU	MINIMUM	

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	pH	Effluent Gross	04/30/2001	8.5	9.4	SU	MAXIMUM	
001M	pH	Effluent Gross	05/31/2001	8.5	8.9	SU	MAXIMUM	
001M	pH	Effluent Gross	08/31/2001	6.5	5.6	SU	MINIMUM	
001M	pH	Effluent Gross	10/31/2001	6.5	6.4	SU	MINIMUM	
001M	pH	Effluent Gross	01/31/2002	8.5	8.6	SU	MAXIMUM	
001M	pH	Effluent Gross	03/31/2002	8.5	9	SU	MAXIMUM	
001M	pH	Effluent Gross	04/30/2002	8.5	8.6	SU	MAXIMUM	
001M	pH	Effluent Gross	08/31/2002	8.5	8.6	SU	MAXIMUM	
001M	pH	Effluent Gross	09/30/2002	8.5	8.6	SU	MAXIMUM	
001M	pH	Effluent Gross	04/30/2003	8.5	8.8	SU	MAXIMUM	
001M	pH	Effluent Gross	03/31/2005	8.5	8.7	SU	MAXIMUM	
001M	pH	Effluent Gross	07/31/2006	6.5	=6.25	SU	MINIMUM	
001M	pH	Effluent Gross	09/30/2006	6.5	=6.23	SU	MINIMUM	
001M	pH	Effluent Gross	10/31/2006	6.5	=6	SU	MINIMUM	
001M	pH	Effluent Gross	11/30/2006	6.5	=6.2	SU	MINIMUM	
001M	pH	Effluent Gross	12/31/2007	6.5	=6.1	SU	MINIMUM	
001M	Phenolics, total recoverable	Effluent Gross	12/31/1996	.008	.14	mg/L	DAILY MX	1,650
001M	Phenolics, total recoverable	Effluent Gross	02/28/1997	.008	.049	mg/L	DAILY MX	512
001M	Phenolics, total recoverable	Effluent Gross	03/31/1997	.008	.04	mg/L	DAILY MX	400
001M	Phenolics, total recoverable	Effluent Gross	04/30/1997	.008	.01	mg/L	DAILY MX	25
001M	Phenolics, total recoverable	Effluent Gross	05/31/1997	.008	.02	mg/L	DAILY MX	150
001M	Phenolics, total recoverable	Effluent Gross	06/30/1997	.008	.02	mg/L	DAILY MX	150
001M	Phenolics, total recoverable	Effluent Gross	08/31/1997	.008	.02	mg/L	DAILY MX	150
001M	Phenolics, total recoverable	Effluent Gross	09/30/1997	.008	.03	mg/L	DAILY MX	275
001M	Phenolics, total recoverable	Effluent Gross	10/31/1997	.008	.02	mg/L	DAILY MX	150

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Phenolics, total recoverable	Effluent Gross	11/30/1997	.008	.02	mg/L	DAILY MX	150
001M	Phenolics, total recoverable	Effluent Gross	12/31/1997	.008	.03	mg/L	DAILY MX	275
001M	Phenolics, total recoverable	Effluent Gross	03/31/1998	.008	.03	mg/L	DAILY MX	275
001M	Phenolics, total recoverable	Effluent Gross	04/30/1998	.008	.51	mg/L	DAILY MX	6,275
001M	Phenolics, total recoverable	Effluent Gross	05/31/1998	.008	.202	mg/L	DAILY MX	2,425
001M	Phenolics, total recoverable	Effluent Gross	06/30/1998	.008	.06	mg/L	DAILY MX	650
001M	Phenolics, total recoverable	Effluent Gross	07/31/1998	.008	.11	mg/L	DAILY MX	1,275
001M	Phenolics, total recoverable	Effluent Gross	08/31/1998	.008	.05	mg/L	DAILY MX	525
001M	Phenolics, total recoverable	Effluent Gross	09/30/1998	.008	<.1	mg/L	DAILY MX	1,150
001M	Phenolics, total recoverable	Effluent Gross	10/31/1998	.008	.259	mg/L	DAILY MX	3,137
001M	Phenolics, total recoverable	Effluent Gross	11/30/1998	.008	<.1	mg/L	DAILY MX	1,150
001M	Phenolics, total recoverable	Effluent Gross	12/31/1998	.008	.03	mg/L	DAILY MX	275
001M	Phenolics, total recoverable	Effluent Gross	01/31/1999	.008	<.1	mg/L	DAILY MX	1,150
001M	Phenolics, total recoverable	Effluent Gross	02/28/1999	.008	<.1	mg/L	DAILY MX	1,150
001M	Phenolics, total recoverable	Effluent Gross	03/31/1999	.008	<.1	mg/L	DAILY MX	1,150
001M	Phenolics, total recoverable	Effluent Gross	10/31/1999	.008	.04	mg/L	DAILY MX	400
001M	Phenolics, total recoverable	Effluent Gross	11/30/1999	.008	.01	mg/L	DAILY MX	25
001M	Phenolics, total recoverable	Effluent Gross	12/31/1999	.008	.054	mg/L	DAILY MX	575
001M	Phenolics, total recoverable	Effluent Gross	01/31/2000	.008	.017	mg/L	DAILY MX	113
001M	Phenolics, total recoverable	Effluent Gross	02/29/2000	.008	.015	mg/L	DAILY MX	88
001M	Phenolics, total recoverable	Effluent Gross	03/31/2000	.008	.031	mg/L	DAILY MX	287
001M	Phenolics, total recoverable	Effluent Gross	04/30/2000	.008	.014	mg/L	DAILY MX	75
001M	Phenolics, total recoverable	Effluent Gross	05/31/2000	.008	.021	mg/L	DAILY MX	162
001M	Phenolics, total recoverable	Effluent Gross	06/30/2000	.008	.038	mg/L	DAILY MX	375
001M	Phenolics, total recoverable	Effluent Gross	07/31/2000	.008	.01	mg/L	DAILY MX	25

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Phenolics, total recoverable	Effluent Gross	08/31/2000	.008	.034	mg/L	DAILY MX	325
001M	Phenolics, total recoverable	Effluent Gross	09/30/2000	.008	.012	mg/L	DAILY MX	50
001M	Phenolics, total recoverable	Effluent Gross	10/31/2000	.008	.012	mg/L	DAILY MX	50
001M	Phenolics, total recoverable	Effluent Gross	11/30/2000	.008	.041	mg/L	DAILY MX	412
001M	Phenolics, total recoverable	Effluent Gross	01/31/2001	.008	.01	mg/L	DAILY MX	25
001M	Phenolics, total recoverable	Effluent Gross	02/28/2001	.008	.024	mg/L	DAILY MX	200
001M	Phenolics, total recoverable	Effluent Gross	03/31/2001	.008	.012	mg/L	DAILY MX	50
001M	Phenolics, total recoverable	Effluent Gross	04/30/2001	.008	.016	mg/L	DAILY MX	100
001M	Phenolics, total recoverable	Effluent Gross	08/31/2001	.008	.011	mg/L	DAILY MX	38
001M	Phenolics, total recoverable	Effluent Gross	01/31/2004	.008	Non Report	mg/L	DAILY MX	
001M	Phenolics, total recoverable	Effluent Gross	10/31/2005	.008	.016	mg/L	DAILY MX	100
001M	Phenolics, total recoverable	Effluent Gross	10/31/2012	.008	<5	mg/L	DAILY MX	62,400
001M	Silver, total [as Ag]	Effluent Gross	01/31/1999	.1	.15	mg/L	DAILY MX	50
001M	Silver, total [as Ag]	Effluent Gross	05/31/1999	.1	.24	mg/L	DAILY MX	140
001M	Silver, total [as Ag]	Effluent Gross	06/30/1999	.1	.22	mg/L	DAILY MX	120
001M	Silver, total [as Ag]	Effluent Gross	07/31/1999	.1	.13	mg/L	DAILY MX	30
001M	Silver, total [as Ag]	Effluent Gross	09/30/1999	.1	.15	mg/L	DAILY MX	50
001M	Silver, total [as Ag]	Effluent Gross	12/31/1999	.1	.21	mg/L	DAILY MX	110
001M	Silver, total [as Ag]	Effluent Gross	01/31/2000	.1	19.5	mg/L	DAILY MX	19,400
001M	Silver, total [as Ag]	Effluent Gross	03/31/2000	.1	.11	mg/L	DAILY MX	10
001M	Silver, total [as Ag]	Effluent Gross	11/30/2000	.1	.14	mg/L	DAILY MX	40
001M	Silver, total [as Ag]	Effluent Gross	02/28/2001	.1	.13	mg/L	DAILY MX	30
001M	Silver, total [as Ag]	Effluent Gross	12/31/2001	.1	.23	mg/L	DAILY MX	130
001M	Silver, total [as Ag]	Effluent Gross	01/31/2004	.1	Non Report	mg/L	DAILY MX	
001M	Silver, total [as Ag]	Effluent Gross	05/31/2006	.1	.23	mg/L	DAILY MX	130

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	Silver, total [as Ag]	Effluent Gross	06/30/2006	.1	.11	mg/L	DAILY MX	10
001M	Solids, total dissolved	Effluent Gross	11/30/1996	1000	Non Report	mg/L	DAILY MX	
001M	Solids, total dissolved	Effluent Gross	12/31/1996	1000	Non Report	mg/L	DAILY MX	
001M	Solids, total dissolved	Effluent Gross	01/31/1997	1000	Non Report	mg/L	DAILY MX	
001M	Solids, total dissolved	Effluent Gross	02/28/1997	1000	Non Report	mg/L	DAILY MX	
001M	Solids, total dissolved	Effluent Gross	05/31/1997	1000	2011	mg/L	DAILY MX	101
001M	Solids, total dissolved	Effluent Gross	08/31/1997	1000	1680	mg/L	DAILY MX	68
001M	Solids, total dissolved	Effluent Gross	10/31/1997	1000	1300	mg/L	DAILY MX	30
001M	Solids, total dissolved	Effluent Gross	12/31/1997	1000	1064	mg/L	DAILY MX	6
001M	Solids, total dissolved	Effluent Gross	01/31/1998	1000	1290	mg/L	DAILY MX	29
001M	Solids, total dissolved	Effluent Gross	02/28/1998	1000	1132	mg/L	DAILY MX	13
001M	Solids, total dissolved	Effluent Gross	02/28/1999	1000	1050	mg/L	DAILY MX	5
001M	Solids, total dissolved	Effluent Gross	07/31/1999	1000	Non Report	mg/L	DAILY MX	
001M	Solids, total dissolved	Effluent Gross	09/30/1999	1000	1264	mg/L	DAILY MX	26
001M	Solids, total dissolved	Effluent Gross	11/30/1999	1000	1160	mg/L	DAILY MX	16
001M	Solids, total dissolved	Effluent Gross	04/30/2003	1000	1100	mg/L	DAILY MX	10
001M	Solids, total dissolved	Effluent Gross	01/31/2004	1000	Non Report	mg/L	DAILY MX	
001M	Toluene	Effluent Gross	04/30/1999	5	12	ug/L	DAILY MX	140
001M	Toluene	Effluent Gross	04/30/2002	5	<7	ug/L	DAILY MX	40
001M	Toluene	Effluent Gross	05/31/2002	5	<7	ug/L	DAILY MX	40
001M	Toluene	Effluent Gross	04/30/2003	5	6	ug/L	DAILY MX	20
001M	Toluene	Effluent Gross	05/31/2003	5	5.8	ug/L	DAILY MX	16
001M	Toluene	Effluent Gross	01/31/2004	5	Non Report	ug/L	DAILY MX	
001M	Toluene	Effluent Gross	04/30/2004	5	6	ug/L	DAILY MX	20
001M	Toluene	Effluent Gross	03/31/2005	5	8	ug/L	DAILY MX	60

***** NOT ICIS CERTIFIED*****

NY0136751 NEWSDAY, LLC

		Monitoring Location	Mon. Period	Limit Value	DMR Value	Units	Stat Base	% Exceedence
001M	**Toluene**	**Effluent Gross**	**11/30/2005**	**.005**	**<1**	**mg/L**	**DAILY MX**	**19,900**
001M	**Toluene**	**Effluent Gross**	**12/31/2005**	**.005**	**<1**	**mg/L**	**DAILY MX**	**19,900**
001M	**Toluene**	**Effluent Gross**	**04/30/2006**	**.005**	**<1**	**mg/L**	**DAILY MX**	**19,900**
001M	**Toluene**	**Effluent Gross**	**06/30/2006**	**.005**	**<.5**	**mg/L**	**DAILY MX**	**9,900**
001M	**Toluene**	**Effluent Gross**	**09/30/2006**	**.005**	**<7**	**mg/L**	**DAILY MX**	**139,900**
001M	**Toluene**	**Effluent Gross**	**11/30/2006**	**.005**	**<7**	**mg/L**	**DAILY MX**	**139,900**
001M	**Toluene**	**Effluent Gross**	**03/31/2011**	**.005**	**<.007**	**mg/L**	**DAILY MX**	**40**
001M	**Total toxic organics [TTO] [40 CFR413]**	**Effluent Gross**	**07/31/1999**	**100**	**Non Report**	**ug/L**	**DAILY MX**	
001M	**Xylene [mix of m+o+p]**	**Effluent Gross**	**07/31/1999**	**5**	**Non Report**	**ug/L**	**DAILY MX**	

91-20-2 (1/89)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)

DISCHARGE PERMIT

Special Conditions (Part l)

Industrial Code: 2711
Discharge Class (CL): 01
Toxic Class (TX): T
Major Drainage Basin: 17
Sub Drainage Basin: 02
Water Index Number: Groundwater
Compact Area:

SPDES Number: NY - 0136751
DEC Number: 1-4726-00157/00001-0
Effective Date (EDP): 10/16/ 1996
Expiration Date (ExDP): 10/15/ 2001
Modification Date(s):
Attachment(s): General Conditions (Part ll) Date: 11/90

This SPDES permit is issued in compliance with Title 8 of Article 17 of the Environmental Conservation Law of New York State and in compliance with the Clean Water Act as amended, (33 U.S.C. Section 1251 et. seq.)(hereafter referred to as "the Act").

PERMITTEE NAME AND ADDRESS

Attention: John Tillotson, Envir. Coord.

Name: Newsday, Inc.
Street: 235 Pinelawn Road
City: Melville State: NY Zip Code: 11747
is authorized to discharge from the facility described below:

FACILITY NAME AND ADDRESS

Name: Newsday, Inc.
Location (C,T,V): Huntington (T) County: Suffolk
Facility Address: 235 Pinelawn Road
City: Melville State: NY Zip Code: 11747
NYTM - E: . NYTM - N: 4 .
From Outfall No.: 001 at Latitude: 40° 15′ 14" & Longitude: 73° 22′ 34"
into receiving waters known as: Groundwater Class: GA
and; (list other Outfalls, Receiving Waters & Water Classifications)

Outfall 002:
Groundwater - GA

Suffolk County Tax Map #'s:

District: 0400 Section: 20
Block: 2 Lot: 1

in accordance with the effluent limitations, monitoring requirements and other conditions set forth in Special Conditions (Part l) and General Conditions (Part ll) of this permit.

DISCHARGE MONITORING REPORT (DMR) MAILING ADDRESS

Mailing Name: Newsday, Inc.
Street: 235 Pinelawn Road
City: Melville State: NY Zip Code: 11747
Responsible Official or Agent: Mr. Dave Krueger, Engineer Phone: (516)843-5437

This permit and the authorization to discharge shall expire on midnight of the expiration date shown and the permittee shall not discharge after the expiration date unless this permit has been renewed, or extended pursuant to law. To be authorized to discharge beyond the expiration date, the permittee shall apply for a permit renewal no less than 180 days prior to the expiration date shown above.

DISTRIBUTION: R. Hannaford
R. Schneck
J. Myslinski
J. Maloney/R. Seyfarth

Permit Administrator: Roger Evans, Deputy RPA	
Address: Building 40 - SUNY Stony Brook, New York 11790-2356	
Signature: Roger Evans	Date: 9/27/96

EFFLUENT LIMITATIONS AND MONITORING REQUIREMENTS

During the period beginning EDP 10/16/1996

and lasting until EDP + 5 YEARS 10/15/2001

the discharges from the permitted facility shall be limited and monitored by the permittee as specified below:

Outfall Number & Effluent Parameter	Discharge Limitations Daily Avg.	Daily Max.	Units	Minimum Monitoring Requirements Measurement Frequency	Sample Type
Outfall 001: Industrial and Sanitary Wastewater					
Flow	0.045	NA	MGD	Continuous	Record
Oil & Grease	NA	15	mg/l	Monthly	Grab
Ph (Range)	NA	6.5 - 8.5	SU	Monthly	Grab
Solids, Total Dissolved (TDS)	NA	1000	mg/l	Monthly	Grab
Cyanide	NA	0.4	mg/l	Monthly	Grab
Nitrogen, total (expressed as N)	NA	10	mg/l	Monthly	Grab
Phenols, Total	NA	0.008	mg/l	Monthly	Grab
Silver, Total	NA	0.1	mg/l	Monthly	Grab
Benzene*	NA	0.7	µg/l	Monthly	Grab
Chloroform*	NA	7	µg/l	Monthly	Grab
P-Ethyltoluene*	NA	5	µg/l	Monthly	Grab
Methylene Chloride*	NA	5	µg/l	Monthly	Grab
1,2,4,5-Tetramethylbenzene*	NA	5	µg/l	Monthly	Grab
Toluene*	NA	5	µg/l	Monthly	Grab
1,1,1-Trichloroethylene*	NA	10	µg/l	Monthly	Grab
1,1,2-Trichloroethane*	NA	5	µg/l	Monthly	Grab
1,3,5-Trimethylbenzene*	NA	5	µg/l	Monthly	Grab
Xylene*	NA	5	µg/l	Monthly	Grab
Total Organic Chemicals(1)	NA	100	µg/l	Monthly	Grab
Outfall 002: Storm Water - No Process Wastes Allowed					
No monitoring required.					

Footnotes:

(1) The value reported for Total Organic Chemicals shall be the sum of the reported values for those substances indicated by asterisks (*) above.

SCHEDULE OF COMPLIANCE

a) The permittee shall comply with the following schedule.

Action Code	Outfall Number(s)	Compliance Action	Due Date
	All	Submit Best Management Practices (BMP) Plan as outlined on Special Conditions on page 4 of 6.	EDPM + 3 mos.
		Implement non-structural measures specified by the BMP Plan.	EDPM + 6 mos.
		Complete construction of structural measures specified by the BMP Plan.	EDP + 12 mos
	001	Submit a complete response to the Department's October 19, 1995 Request for Information under the Environmental Benefit Permit Strategy (EBPS) (copy attached), to the following locations: NYSDEC Bureau of Water Permits 50 Wolf Rd, Room 338 Albany, New York 12233-3505 and Regional Permit Administrator, DCS NYSDEC Region 1 Building 40, SUNY @ Stony Brook Stony Brook, New York 11790 NOTE: The due dates for the implementation of non-structural measures and completion of the structural measures specified by the BMP Plan may be modified at the discretion of the Department to allow the permittee reasonable time to design and construct these measures.	EDPM + 60 days

b) The permittee shall submit a written notice of compliance or non-compliance with each of the above schedule dates no later than 14 days following each elapsed date, unless conditions require more immediate notice under terms of the General Conditions (Part II), Section 5. All such compliance or non-compliance notification shall be sent to the locations listed under the section of this permit entitled RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS. Each notice of non-compliance shall include the following information:

1. A short description of the non-compliance;
2. A description of any actions taken or proposed by the permittee to comply with the elapsed schedule requirements without further delay and to limit environmental impact associated with the non-compliance;
3. A description or any factors which tend to explain or mitigate the non-compliance; and
4. An estimate of the date the permittee will comply with the elapsed schedule requirement and an assessment of the probability that the permittee will meet the next scheduled requirement on time.

c) The permittee shall submit copies of any document required by the above schedule of compliance to NYSDEC Regional Water Engineer at the location listed under the section of this permit entitled RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS, unless otherwise specified in this permit or in writing by the Department.

SPECIAL CONDITIONS - BEST MANAGEMENT PRACTICES

1. The permittee shall develop and implement a Best Management Practices (BMP) plan, within one year of EDP to prevent, or minimize the potential for, release of significant amounts of toxic or hazardous pollutants to the waters of the State through plant site runoff; spillage and leaks; sludge or waste disposal; and storm water discharges including, but not limited to, drainage from raw material storage. Completed BMP plans shall be submitted to the Regional Water Engineer within six months of EDP.

2. The permittee shall review all facility components or systems (including material storage areas; in-plant transfer, process and material handling areas; loading and unloading operations; storm water, erosion, and sediment control measures; process emergency control systems; and sludge and waste disposal areas) where toxic or hazardous pollutants are used, manufactured, stored or handled to evaluate the potential for the release of significant amounts of such pollutants to the waters of the State. In performing such an evaluation, the permittee shall consider such factors as the probability of equipment failure or improper operation, cross-contamination of storm water by process materials, settlement of facility air emissions, the effects of natural phenomena such as freezing temperatures and precipitation, fires, and the facility's history of spills and leaks. For hazardous pollutants, the list of reportable quantities as defined in 40 CFR, Part 117 may be used as a guide in determining significant amounts of releases. For toxic pollutants, the relative toxicity of the pollutant shall be considered in determining the significance of potential releases.

   The review shall address all substances present at the facility that are listed as toxic pollutants under Section 307(a)(1) of the Clean Water Act or as hazardous pollutants under Section 311 of the Act or that are identified as Chemicals of Concern by the Industrial Chemical Survey.

3. Whenever the potential for a significant release of toxic or hazardous pollutants to State waters is determined to be present, the permittee shall identify Best Management Practices that have been established to minimize such potential releases. Where BMPs are inadequate or absent, appropriate BMPs shall be established. In selecting appropriate BMPs, the permittee shall consider typical industry practices such as spill reporting procedures, risk identification and assessment, employee training, inspections and records, preventive maintenance, good housekeeping, materials compatibility and security. In addition, the permittee may consider structural measures (such as secondary containment and erosion/sediment control devices and practices) where appropriate.

4. Development of the BMP plan shall include sampling of waste stream segments for the purpose of toxic "hot spot"* identification. The economic achievability of technology-based end-of-pipe treatment will not be considered until plant site "hot spot" sources have been identified, contained, removed or minimized through the imposition of site specific BMPs or application of internal facility treatment technology.

5. The BMP plan shall be documented in narrative form and shall include any necessary plot plans, drawings or maps. Other documents already prepared for the facility such as a Safety Manual or a Spill Prevention, Control and Countermeasure (SPCC) plan may be used as part of the plan and may be incorporated by reference. USEPA guidance for development of storm water elements of the BMP is available in the September 1992 manual "Storm Water Management for Industrial Activities," USEPA Office of Water Publication EPA 832-R-92-006 (available from NTIS, (703)487-4650, order number PB 92235969). A copy of the BMP plan shall be maintained at the facility and shall be available to authorized Department representatives upon request. As a minimum, the plan shall include the following BMP's:

a.	BMP Committee	e.	Inspections and Records	i.	Security
b.	Reporting of BMP Incidents	f.	Preventive Maintenance	j.	Spill prevention & response
c.	Risk Identification & Assessment	g.	Good Housekeeping	k.	Erosion & sediment control
d.	Employee Training	h.	Materials Compatibility	l.	Management of runoff

6. The BMP plan shall be modified whenever changes at the facility materially increase the potential for significant releases of toxic or hazardous pollutants or where actual releases indicate the plan is inadequate.

* A "hot spot" is a segment of an industrial facility; including but not limited to soil, equipment, material storage areas, sewer lines etc.; which contributes elevated levels of problem pollutants to the wastewater and/or storm water collection system of that facility. For the purposes of this definition, problem pollutants are substances for which end of pipe treatment to meet a water quality or technology requirement may, considering the results of wastestream segment sampling, be deemed unreasonable. For the purposes of this definition, an elevated level is a concentration or mass loading of the pollutant in question which is sufficiently higher than the end of pipe concentration of that same pollutant so as to allow for an economically justifiable removal and/or isolation of the segment and/or B.A.T. treatment of wastewaters emanating from the segment.


DEFINITIONS OF DAILY AVERAGE AND DAILY MAXIMUM


The daily average discharge is the total discharge by weight or in other appropriate units as specified herein, during a calendar month divided by the number of days in the month that the production or commercial facility was operating. Where less than daily sampling is required by this permit, the daily average discharge shall be determined by the summation of all the measured daily discharges in appropriate units as specified herein divided by the number of days during the calendar month when measurements were made.

The daily maximum discharge means the total discharge by weight or in other appropriate units as specified herein, during any calendar day.

MONITORING LOCATIONS

The permittee shall take samples and measurements, to comply with the monitoring requirements specified in this permit, at the location(s) indicated below:





Water flow and sampling location diagram, Newsday, 235 Pinelawn Rd., Melville NY 11747

Note: All flow values shown are approximate averages.

RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS

a) The permittee shall also refer to the General Conditions (Part II) of this permit for additional information concerning monitoring and reporting requirements and conditions.

b) The monitoring information required by this permit shall be summarized, signed and retained for a period of three years from the date of the sampling for subsequent inspection by the Department or its designated agent. **Also**;

[X] (if box is checked) monitoring information required by this permit shall be summarized and reported by submitting completed and signed Discharge Monitoring Report (DMR) forms for each one month reporting period to the locations specified below. Blank forms are available at the Department's Albany office listed below. The first reporting period begins on the effective date of this permit and the reports will be due no later than the 28th day of the month following the end of each reporting period.

Send the **original** (top sheet) of each DMR page to:

Department of Environmental Conservation
Division of Water
Bureau of Water Compliance Programs
50 Wolf Road
Albany, New York 12233-3506

Phone: (518) 457-3790

Send the **second copy** (third sheet) of each DMR page to:

Suffolk County Department of Health Services
15 Horseblock Place
Farmingville, New York 11738
Attn: Mr. Jim Maloney, P.E.

Include a copy of the laboratory analysis with the NYSDEC - Region 1 and SCDHS copies.

Send the **first copy** (second sheet) of each DMR page to:

Department of Environmental Conservation
Regional Water Engineer - Region 1
Building 40 - SUNY @ Stony Brook
Stony Brook, New York 11790-2356

c) A monthly "Wastewater Facility Operation Report..." (form 92-15-7) shall be submitted (if box is checked) to the [ ] Regional Water Engineer and/or [ ] County Health Department or Environmental Control Agency listed above.

d) **Noncompliance** with the provisions of this permit shall be reported to the Department as prescribed in the attached General Conditions (Part II)

e) Monitoring must be conducted according to test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit.

f) If the permittee monitors any pollutant more frequently than required by the permit, using test procedures approved under 40 CFR Part 136 or as specified in this permit, the results of this monitoring shall be included in the calculations and recording of the data on the Discharge Monitoring Reports.

g) Calculation for all limitations which require averaging of measurements shall utilize an arithmetic mean unless otherwise specified in this permit.

h) Unless otherwise specified, all information recorded on the Discharge Monitoring Report shall be based upon measurements and sampling carried out during the most recently completed reporting period.

i) Any laboratory test or sample analysis required by this permit for which the State Commissioner of Health issues certificates of approval pursuant to section five hundred two of the Public Health Law shall be conducted by a laboratory which has been issued a certificate of approval. Inquiries regarding laboratory certification should be sent to the Environmental Laboratory Accreditation Program, New York State Health Department Center for Laboratories and Research, Division of Environmental Sciences , The Nelson A. Rockefeller Empire State Plaza, Albany, New York 12201.

RLJ

New York State Department of Environmental Conservation
Division of Environmental Permits, 4th Floor
625 Broadway, Albany, New York 12233-1750
Phone: (518) 402-9167 • **FAX:** (518) 402-9168
Website: www.dec.state.ny.us

Erin M. Crotty
Commissioner

September 07, 2001

STEPHEN CLUFF
NEWSDAY INC
235 PINELAWN RD.
MELVILLE, NY 11747

FACILITY INFORMATION

NEWSDAY
LOCATION : HUNTINGTON (T)
COUNTY : SUFFOLK
DEC NO : 1-4726-00157-00001-
SPDES NO : NY 013 6751

Dear SPDES Permittee:

Enclosed please find your renewed State Pollutant Discharge Elimination System (SPDES) permit. This renewal permit together with the previously issued valid permit constitute authorization to discharge wastewater in accordance with all terms, conditions and limitations specified in your previously issued permit, including any valid modifications.

The instructions and other information that you received with the NOTICE/RENEWAL APPLICATION/PERMIT package fully described procedures for renewal and modification of your SPDES permit under the Environmental Benefit Permit Strategy (EBPS). As a reminder, SPDES permits are renewed at a central location in Albany in order to make the process more efficient. All other concerns with your permit such as applications for permit modifications, permit transfers to a new owner, name changes, and other questions should be directed to the Regional Permit Administrator at the following address:

John Pavacic
NYSDEC REGION 1
Bldg 40 SUNY @ Stony Brook
Stony Brook, NY 11790-2356
(516) 444-0355

If you have already filed an application for modification of your permit, it will be processed separately through our regional office. If you have questions concerning this permit renewal, please contact Erin L. Burns at (518) 402-9170.

Sincerely,

Barbara B. Rinaldi

Barbara B. Rinaldi
Deputy Chief Permit Administrator

Enclosure
cc: RPA
RWE SUFFOLK COUNTY
BWP

91-20-5 (5/97)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)

NOTICE / RENEWAL APPLICATION / PERMIT

Please read **ALL** instructions on the back before completing this application form. Please **TYPE** or **PRINT** clearly in ink.

PART 1 - NOTICE 12/18/2000

Permittee Contact Name, Title, Address

NEWSDAY INC
STEPHEN CLUFF
235 PINELAWN RD.
MELVILLE NY 11747

Facility and SPDES Permit Information

Name: NEWSDAY INC
Ind. Code: 2711 County: SUFFOLK
DEC No.: 1-4726-00157/00001
SPDES No.: NY 013 6751
Expiration Date: 10/15/2001
Application Due By: 04/18/2001

Are these name(s) & address(es) correct? if not, please write corrections above.

The State Pollutant Discharge Elimination System Permit for the facility referenced above expires on the date indicated. You are required by law to file a complete renewal application **at least 180 days prior to expiration of your current permit. Note the "Application Due By" date above.**

CAUTION: This short application form and attached questionnaire are the only forms acceptable for permit renewal. Sign Part 2 below and mail only this form and the completed questionnaire using the enclosed envelope. *Effective April 1, 1994 the Department no longer assesses SPDES application fees.*

If there are changes to your discharge, or to operations affecting the discharge, then in addition to this renewal application, you must also submit a separate permit modification application to the Regional Permit Administrator for the DEC region in which the facility is located, as required by your current permit. See the reverse side of this page for instructions on filing a modification request.

PART 2 - RENEWAL APPLICATION

CERTIFICATION: I hereby affirm that under penalty of perjury that the information provided on this form and all attachments submitted herewith is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to section 210.45 of the Penal Law.

JOHN TILLOTSON — DIRECTOR OF ENGINEERING SERVICES

Name of person signing application (see instructions on back) — Title

J Q Tillotson — JUNE 29, 2001

Signature — Date

RECEIVED JUL -3 PM 2:11 NYSDEC ENVIRONMENTAL PERMITS

PART 3 - PERMIT (Below this line - Official Use Only)

Effective Date: 10/1/01 Expiration Date: 10/1/06

Barbara B. Rinaldi

Permit Administrator

Address: NYSDEC - Division of Environmental Permits
Bureau of Environmental Analysis
50 Wolf Road, Albany, NY 12233-1760

Barbara B. Rinaldi — 9/7/01

Signature — Date

This permit together with the previous valid permit for this facility issued 09/27/96 and subsequent modifications constitute authorization to discharge wastewater in accordance with all terms, conditions and limitations specified in the previously issued valid permit, modifications thereof or issued as part of this permit, including any special or general conditions attached hereto. Nothing in this permit shall be deemed to waive the Department's authority to initiate a modification of this permit on the grounds specified in 6NYCRR §621.14, 6NYCRR §754.4 or 6NYCRR §757.1 existing at the time this permit is issued or which arise thereafter.

Attachments: General Conditions dated 11/90

91-20-5a (7/99)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Please enter the numbers from your current permit:

DEC Number: 1 - 4726 - 00157 / 0000 - 1

SPDES Number: NY 013 6751

SPDES RENEWAL APPLICATION
QUESTIONNAIRE

THIS PAGE MUST BE COMPLETED AND RETURNED WITH YOUR COMPLETED APPLICATION

Please **TYPE** or **PRINT** neatly using adequate pressure to make ALL copies legible. Keep the GOLD copy for your records.

1. Has the SPDES permit for your facility been modified in the past 5 years ☒ YES ☐ NO

2. Dischargers who use, manufacture, store, handle or discharge toxic or hazardous pollutants are subject to Industrial Best Management Practices (BMP) plan requirements for toxic or hazardous substances. A BMP plan prevents or minimizes the potential for release of pollutants to receiving waters from such ancillary industrial activities, including material storage areas; plant site runoff; in-plant transfer; process and material storage areas; loading and unloading operations, and sludge and waste disposal areas.

   Does your facility conduct ancillary activities as described above, which are not covered by BMP requirements in your current permit? ☐ YES ☒ NO

Please indicate which of the following best describes the situation at your facility:

☐ None of the concerns on the "Self Evaluation List" seem to apply to my facility at this time and I will not be applying for a modification of the SPDES permit in the foreseeable future.

☒ Yes, some of the items on the "Self Evaluation List" have led me to believe my permit needs to be modified. I already have a complete modification application pending with the Department.

☐ Yes, some of the items on the "Self Evaluation List" have led me to believe that the SPDES permit for this facility may need to be Modified. I have requested the appropriate forms by phone OR I have completed and attached the "Request For SPDES Application Forms" (included in this renewal package) to allow me to submit a permittee-initiated Modification application.

☐ The items on the "Self Evaluation List" have left me unable to conclude whether my permit needs to be modified at this time. I am reporting the following general concerns about my permit:

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

_____

DISTRIBUTION:

Regional Water Engineer -- WHITE
Central Office (BWP) -- YELLOW
Regional Permit Administrator -- PINK
Applicant -- GOLD

State Pollutant Discharge Elimination System (SPDES)

Application Supplement B
DISCHARGES WITHIN SOLE SOURCE AQUIFERS

Facility Name:	SPDES Number:
NEWSDAY, INC.	NY 0136751

Your facility may be located in a sole source aquifer area, which is an area designated by Federal or State statutes. Maps showing the designated sole source areas can be found on the internet at: www.epa.gov/region02/water/ssamap.htm.

Chapter 663 of the Laws of 1983 added Section 17-0828 to the Environmental Conservation Law which requires that any person seeking a SPDES permit or a renewal hereunder, within an area designated pursuant to any federal or state statute as a sole source aquifer, shall include as a part of the required information, the name and address of all public water purveyors with a service area or portion thereof located within a three mile radius of the applicant's facility.

For purposes of this section "public water purveyor" shall mean any person, partnership, public or private corporation, municipality, or public authority which sells water derived from a sole source aquifer to at least five service connections or at least twenty-five individuals.

---

1. Water Purveyors within a three mile radius of your facility:

Please complete the following information to the best of your knowledge and attach it to your application. Attach additional copies of this sheet as necessary.

	Name	Address
1.	SOUTH HUNTINGTON WATER DISTRICT	5TH AVENUE SOUTH & W 13TH STREET HUNTINGTON STATION, NY 11746-0302
2.	SUFFOLK COUNTY WATER AUTHORITY (BABYLON)	179 LITTLE EAST NECK ROAD BABYLON, NEW YORK 11702
3.	DIX HILLS WATER DISTRICT	683 CALEDONIA ROAD DIX HILLS, NEW YORK 11746
4.	VILLAGE OF FARMINGDALE WATER DISTRICT	KETCHUM LANE & RIDGE ROAD FARMINGDALE, NEW YORK 11735
5.	EAST FARMINGDALE WATER DISTRICT	1919 BROAD HOLLOW ROAD FARMINGDALE, NEW YORK 11735
6.	PLAINVIEW WATER DISTRICT	10 MANETTO HILL ROAD PLAINVIEW, NEW YORK 11803
7.		
8.		
9.		
10.		
11.		

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747
tel: 631/843-3631
fax: 631/843-3444
stephen.cluff@newsday.com

Stephen Cluff
Environmental Engineer

June 29, 2001

New York State Department of Environmental Conservation
Division of Environmental Permits
Bureau of Environmental Analysis
50 Wolf Road
Albany, NY 12233-1750

SUBJECT: **SPDES #NY0136751**

To Bureau of Environmental Analysis:

I am sending you a completed SPDES renewal application for your review. If you have any questions or comments, please feel free to contact me at (631)-843-3631.

Sincerely,


Stephen Cluff
Environmental Engineer

CC: DEC/Stony Brook - Robert Sorrentino
John Tillotson, Newsday Director of Engineering

Attachments: (1) Notice/Renewal Aplication Permit
(2) Application Supplement B "Discharges within Sole Source Aquifers"
(3) SPDES Renewal Application Questionaire

RECEIVED NYSDEC
ENVIRONMENTAL PERMITS
01 JUL -3 PM 2:11

New York State Department of Environmental Conservation
Division of Environmental Permits
625 Broadway, Albany, New York 12233-1750
Phone: (518) 402-9167 • **FAX:** (518) 402-9168
Website: www.dec.state.ny.us



Erin M. Crotty
Commissioner

MEMORANDUM

TO: John Pavacic, Regional Permit Administrator, Region 1

FROM: Erin Burns, Agency Program Aide Erin

SUBJ: **SPDES Renewal Application**
Permittee: Newsday Inc.
Facility: Newsday
SPDES #: NY-013-6751
DEC #: 1-4726-00157/00001

DATE: August 14, 2001

On July 3, 2001, I received an EBPS SPDES renewal application for the above-referenced facility. It appears from the comments on their questionnaire that they might be considering a modification to their existing SPDES permit.

Attached is a copy of the renewal application and questionnaire for your review. I will continue processing the renewal of this permit.

Attach.

cc: Robert Schneck, RWE, Region 1

(fold #2)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL PERMITS
NYSDEC HEADQUARTERS
625 BROADWAY
ALBANY NY 12233

NEWSDAY INC
PINELAWN RD
MELVILLE NY 11746

(fold #1) -- staple here

NOTICE OF RECEIPT OF APPLICATION

The Division of Environmental Permits has received the application referenced below. The material submitted is being reviewed by staff, and you will be advised in writing regarding the department's findings. In all future communications, please refer to the Application ID number.

Application ID: 1-4726-00157/00001

Date Received: July 03, 2001

Applicant: NEWSDAY INC

Facility: NEWSDAY

Description: SPDES Fast-Track Renewal NY 013 6751

DEC Contact: ERIN L. BURNS

Permit Application Process Sheet

Class 1 type 1

Tracked DEC ID	Batch ID	Processing Office	DEP Analyst
1-4726-00157/00001	896004	NYSDEC HEADQUARTERS	ERIN L. BURNS

Application Type: Renewal **Public ID:** 6800

Project Description: SPDES Fast-Track Renewal NY 013 6751

General Permit: N Pre-Appl: N Emergency: N Special Attn Type:

DEC ID#	TI	Permit applied for:
1-4726-00157/00001	T	PD1 Industrial SPDES

Legally Responsible Party - ( )___-___	Facility	Geographic Location
NEWSDAY INC PINELAWN RD MELVILLE, NY 11746	NEWSDAY 235 PINELAWN RD MELVILLE, NY 11746	County: SUFFOLK Municipality: HUNTINGTON NYTM-E 634.517 NYTM-N 4513.785

Application Contact	Phone #	Facility Contact	Phone #
_____	( ) ___ - _____	_____	( ) ___ - _____
_____	FAX #	_____	FAX #
_____	( ) ___ - _____	_____	( ) ___ - _____
_____		_____	

SEQR INFORMATION: SEQR Class Type I / Unlisted / Type II

SEQR Determination Neg Dec / Pos Dec / Conditioned Neg Dec / N/A

Coordinated Review Y / N Lead Agency _____

Critical Env. Area Y / N Significant Habitat Y / N

COMPLETENESS INFO: **UPA Status:** Minor / Major SHPA Status CZM Review Y / N

APA 809 Jurisdiction Y / N Newspaper Name _____

ENB Date ___/___/___ Newspaper Date ___/___/___ Radio Date ___/___/___

SUSPENSION INFORMATION:

Suspension during Pre-completeness: Reason

Date Suspended ___/___/___ **Date Unsuspended** ___/___/___ **New Completeness Due Date** ___/___/___

Suspension during Post-completeness: Reason

Date Suspended ___/___/___ **Date Unsuspended** ___/___/___ **New Final Disposition Due Date** ___/___/___

CIRCULATION / COORDINATION:

Distribution List	Date Sent	Resp Due Date	Resp Recvd Date
_____	___/___/___	___/___/___	___/___/___
_____	___/___/___	___/___/___	___/___/___
_____	___/___/___	___/___/___	___/___/___
_____	___/___/___	___/___/___	___/___/___
_____	___/___/___	___/___/___	___/___/___
_____	___/___/___	___/___/___	___/___/___

The applicant has submitted information identified as confidential: Y / N

Date Received **July 03, 2001**
Incomplete/Complete Due **September 04, 2001**
Incomplete Sent
Resubmission Recvd
Incomplete/Complete Due
Incomplete Sent
Resubmission Recvd
Incomplete/Complete Due
Complete Sent
Written Comments Deadline
Proof of Publication Recvd Date
Hearing Decision Due
Hearing Decision Sent
Final Decision Due
Final Decision
Final Decision Sent
Effective Date
Expiration Date
Date Logged off DART

New York State Department of Environmental Conservation
Division of Environmental Permits, Region One
Building 40 - SUNY, Stony Brook, New York 11790-2356
Phone: (631) 444-0365 • **FAX:** (631) 444-0360
Website: www.dec.state.ny.us

John P. Cahill
Commissioner

November 2, 2001

RECEIVED
NOV 05 2001
WATER UNIT
DEC REGION 1

Newsday, Inc.
235 Pinelawn Road
Melville, NY 11747-4250
Attn.: Stephen Cluff, Environmental Engineer

Re: NYSDEC Permit # 1-4726-00157/00001
SPDES Facility # NY-0136751

Dear Permittee:

The Department has reviewed your request to modify this permit. A determination has been made to modify your permit as requested. Please conform your copy of the permit by replacing the appropriate page(s) with the enclosed.

Please direct any inquiries you may have to this office to my attention at the number listed above.

Sincerely,

Roger Evans

Roger Evans
Permit Administrator

RE/ls
enclosure

cc: R. Hannaford
R. Schneck
A. Santino
File

NEW YORK STATE CENSUS 2000
BE PART OF THE COUNT
¡SEA PARTE DE LA CUENTA!

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)
DISCHARGE PERMIT

Special Conditions (Part 1)

First3.99

Industrial Code:	2711	SPDES Number:	NY- 013 6751
Discharge Class (CL):	01	DEC Number:	1-4726-00157/00001
Toxic Class (TX):	T	Effective Date (EDP):	October 16, 1996
Major Drainage Basin:	17	Expiration Date (ExPD):	October 1, 2006
Sub Drainage Basin:	02	Modification Dates:	9/1/99; 12/1/01
Water Index Number:	Groundwater	Attachment(s):	General Conditions (Part II) Date: 11/90
Compact Area:			

This SPDES permit is issued in compliance with Title 8 of Article 17 of the Environmental Conservation Law of New York State and in compliance with the Clean Water Act, as amended, (33 U.S.C. §1251 et.seq.)(hereinafter referred to as "the Act").

PERMITTEE NAME AND ADDRESS

Name: Newsday, Inc. Attention: Stephen Cluff, Environmental Engineer

Street: 235 Pinelawn Road

City: Melville State: NY Zip Code: 11747-4250

is authorized to discharge from the facility described below:

FACILITY NAME AND ADDRESS

Name: Newsday, Inc.

Location (C,T,V): Huntington (T) County: Suffolk

Facility Address: 235 Pinelawn Road

City: Melville State: NY Zip Code: 11747-4250

NYTM -E: NYTM - N:

Suffolk County Tax Map Numbers: District: 0400 Section: 20 Block: 2 Lot: 1

From Outfall No.: 001 at Latitude: 40 ° 15 ′ 14 ″ & Longitude: 73 ° 22 ′ 34 ″

into receiving waters known as: Groundwater Class: GA

and; (list other Outfalls, Receiving Waters & Water Classifications)

Outfall 002: Groundwater - GA

Outfall 003: Groundwater - GA

in accordance with the effluent limitations, monitoring requirements and other conditions set forth in Special Conditions (Part I) and General Conditions (Part II) of this permit.

DISCHARGE MONITORING REPORT (DMR) MAILING ADDRESS

Mailing Name: Newsday, Inc.

Street: 235 Pinelawn Road

City: Melville State: NY Zip Code: 11747-4250

Responsible Official or Agent: Mr. Stephen Cluff, Environmental Engineer Phone: (516)843-3631

This permit and the authorization to discharge shall expire on midnight of the expiration date shown above and the permittee shall not discharge after the expiration date unless this permit has been renewed, or extended pursuant to law. To be authorized to discharge beyond the expiration date, the permittee shall apply for permit renewal not less than 180 days prior to the expiration date shown above.

DISTRIBUTION:
R. Hannaford, DOW; R. Schneck, Region 1;
A. Santino, SCDHS

Permit Administrator:	Roger Evans , Deputy RPA
Address:	Building 40 - SUNY Stony Brook, New York 11790-2356
Signature: Roger Evans	Date: 10/31/01

PERMIT LIMITS, LEVELS AND MONITORING DEFINITIONS

C:\FacilityFiles\Newsday\0136751P.BB.wpd

OUTFALL	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
	This cell describes the type of wastewater authorized for discharge. Examples include process wastewater, storm water, non-contact cooling water.	This cell lists classified waters of the state to which the listed outfall discharges.	The date this page starts in effect.	The date this page is no longer in effect

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQ.	SAMPLE TYPE
	The minimum level that must be maintained at all times.	The maximum level that may not be exceeded at any time.			

PARAMETER	COMPLIANCE LIMIT	ACTION LEVEL	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE
	Daily Max. and Daily Avg. are defined below. All determinations of compliance with substance specific discharge limits are made by comparing monitoring results to the compliance level.	Type I or Type II Action Levels are monitoring requirements, as defined below, that trigger additional monitoring and permit review when exceeded.	This can include units of flow, pH, Temperature, mass or concentration. Examples include SU, °F, µg/l, lbs/d, etc.	Examples include Daily, 3/week, weekly, 2/month, monthly, quarterly, 2/yr and yearly.	Examples include grab, 24 hour composite and 3 grab samples collected over a 6 hour period.

DAILY DISCHARGE.: The discharge of a pollutant measured during a calendar day or any 24-hour period that reasonably represents the calendar day for the purposes of sampling. For pollutants expressed in units of mass, the 'daily discharge' is calculated as the total mass of the pollutant discharged over the day. For pollutants with limitations expressed in other units of measurement, the 'daily discharge' is calculated as the average measurement of the pollutant over the day.

DAILY MAX.: The highest allowable daily discharge.

DAILY AVG.: The highest allowable average of daily discharges over a calendar month, calculated as the sum of all daily discharges measured during a calendar month divided by the number of daily discharges measured during that month.

ACTION LEVELS: Routine Action Level monitoring results, if not provided for on the Discharge Monitoring Report (DMR) form, shall be appended to the DMR for the period during which the sampling was conducted. If the additional monitoring requirement is triggered as noted below, the permittee shall undertake a short-term, high-intensity monitoring program for the parameter(s). Samples identical to those required for routine monitoring purposes shall be taken on each of at least three consecutive operating and discharging days and analyzed. Results shall be expressed in terms of both concentration and mass, and shall be submitted no later than the end of the third month following the month when the additional monitoring requirement was triggered. Results may be appended to the DMR or transmitted under separate cover to the same address. If levels higher than the Action Levels are confirmed, the permit may be reopened by the Department for consideration of revised Action Levels or effluent limits. The permittee is not authorized to discharge any of the listed parameters at levels which may cause or contribute to a violation of water quality standards.

TYPE I : The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results in excess of the stated Action Level.

TYPE II: The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results that show the stated action level exceeded for four of six consecutive samples, or for two of six consecutive samples by 20 % or more, or for any one sample by 50 % or more

FINAL PERMIT LIMITS, LEVELS AND MONITORING

C:\FacilityFiles\Newsday\0136751P BB.wpd

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
001	Industrial and Sanitary Wastewater	Groundwater	12/1/01	10/1/06

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FOOTNOTES (FN)
pH	5.5	8.5	SU	Monthly	Grab	

PARAMETER	ENFORCEABLE LIMIT		MONITORING ACTION LEVEL		UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FN
	Daily Avg.	Daily Max.	TYPE I	TYPE II				
Flow	Monitor	Monitor			gal/day	Continuous	Recorder	
Oil and Grease	NA	15			mg/l	Monthly	Grab	
Solids, Total Dissolved	NA	1000			mg/l	Monthly	Grab	
Cyanide	NA	0.4			mg/l	Monthly	Grab	
Nitrogen, Total (expressed as N)	NA	10			mg/l	Monthly	Grab	
Phenols, Total	NA	0.008			mg/l	Monthly	Grab	
Silver, Total	NA	0.1			mg/l	Monthly	Grab	
Toluene	NA	0.005			mg/l	Monthly	Grab	

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
002	Storm Water - No Process Wastes Allowed	Groundwater	09/01/99	10/15/01
No monitoring required.				

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
003	Non contact Compressor Cooling Water	Groundwater	09/01/99	10/15/01
No monitoring required.				


Notes:


1. BMP Plan: The completed Best Management Practices (BMP) plan submitted to this Department on August 29, 1997 shall be reviewed by the permittee on an annual basis. The BMP Plan shall be modified whenever changes at the facility materially increase the potential for significant releases of toxic or hazardous pollutants or where actual releases indicate that the plan is inadequate.

C:\FacilityFiles\Newsday\0136751P.BB.wpd

MONITORING LOCATIONS

The permittee shall take samples and measurements, to comply with the monitoring requirements specified in this permit, at the location(s) specified below:





RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS

a) The permittee shall also refer to the General Conditions (Part II) of this permit for additional information concerning monitoring and reporting requirements and conditions.

b) The monitoring information required by this permit shall be summarized, signed and retained for a period of three years from the date of the sampling for subsequent inspection by the Department or its designated agent. **Also, monitoring information required by this permit shall be summarized and reported by submitting;**

[X] (if box is checked) completed and signed Discharge Monitoring Report (DMR) forms for each 1 month reporting period to the locations specified below. Blank forms are available at the Department's Albany office listed below. The first reporting period begins on the effective date of this permit and the reports will be due no later than the 28th day of the month following the end of each reporting period.

[ ] (if box is checked) an annual report to the Regional Water Engineer at the address specified below. The annual report is due by February 1 and must summarize information for January to December of the previous year in a format acceptable to the Department.

[ ] (if box is checked) a monthly "Wastewater Facility Operation Report..." (form 92-15-7) to the [ ] Regional Water Engineer and/or [ ] County Health Department or Environmental Control Agency specified below.

Send the **original** (top sheet) of each DMR page to:

Department of Environmental Conservation
Division of Water, Bureau of Watershed Compliance Programs
50 Wolf Road
Albany, New York 12233-3506

Phone: (518) 457-8954

Send the **second copy** (third sheet) of each DMR page to:

Suffolk County Department of Health Services
15 Horseblock Place
Farmingville, New York 11738
Attn: Mr.A.Santino, P.E.

Send the **first copy** (second sheet) of each DMR page to:

Department of Environmental Conservation
Regional Water Engineer
Building 40 - SUNY @ Stony Brook
Stony Brook, NY 11790-2356

NOTE: Include a copy of the laboratory analysis with the NYSDEC - Region 1 and SCDHS copies.

c) Noncompliance with the provisions of this permit shall be reported to the Department as prescribed in the attached General Conditions (Part II).

d) Monitoring must be conducted according to test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit.

e) If the permittee monitors any pollutant more frequently than required by the permit, using test procedures approved under 40 CFR Part 136 or as specified in this permit, the results of this monitoring shall be included in the calculations and recording of the data on the Discharge Monitoring Reports.

f) Calculation for all limitations which require averaging of measurements shall utilize an arithmetic mean unless otherwise specified in this permit.

g) Unless otherwise specified, all information recorded on the Discharge Monitoring Report shall be based upon measurements and sampling carried out during the most recently completed reporting period.

h) Any laboratory test or sample analysis required by this permit for which the State Commissioner of Health issues certificates of approval pursuant to section five hundred two of the Public Health Law shall be conducted by a laboratory which has been issued a certificate of approval. Inquiries regarding laboratory certification should be sent to the Environmental Laboratory Accreditation Program, New York State Health Department Center for Laboratories and Research, Division of Environmental Sciences , The Nelson A. Rockefeller Empire State Plaza, Albany, New York 12201.

New York State Department of Environmental Conservation
Division of Environmental Permits, Region One
Building 40 - SUNY, Stony Brook, New York 11790-2356
Phone: (631) 444-0361 • **FAX:** (631) 444-0360
Website: www.dec.state.ny.us

Denise M. Sheehan
Acting Commissioner

September 14, 2005

Newsday, Inc.
235 Pinelawn Road
Melville, NY 11747
Attn.: Mr. Joseph Marino, Manager

Re: NYSDEC Permit # 1-4726-00157/00001
SPDES Facility # NY-0136751

Dear Permittee:

The Department has reviewed your request to modify this permit. A determination has been made to modify your permit as requested. Please conform your copy of the permit by replacing the appropriate page(s) with the enclosed.

Please direct any inquiries you may have to this office to my attention at the number listed above.

Sincerely,

Roger Evans

Roger Evans
Permit Administrator

RE/ls
enclosure

cc: W. Spitz/R. Sorrentino
BWP Permit Coordinator
A. Santino
File

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)
DISCHARGE PERMIT

Special Conditions (Part 1)

Industrial Code:	2711	SPDES Number:	NY- 013 6751
Discharge Class (CL):	01	DEC Number:	1-4726-00157/00001
Toxic Class (TX):	T	Effective Date (EDP):	10/01/01 3/14/06
Major Drainage Basin:	17	Expiration Date (ExPD):	10/01/06 9/30/11
Sub Drainage Basin:	01	Modification Dates:	12/01/01;11/01/05
Water Index Number:	Groundwater	Attachment(s):	
Compact Area:			

This SPDES permit is issued in compliance with Title 8 of Article 17 of the Environmental Conservation Law of New York State and in compliance with the Clean Water Act, as amended, (33 U.S.C. §1251 et.seq.)(hereinafter referred to as "the Act").

PERMITTEE NAME AND ADDRESS

Name: Newsday, Inc. Attention: Joseph Marino, Mgr. Facilities Engrg.
Street: 235 Pinelawn Road
City: Melville State: NY Zip Code: 11747-4250

is authorized to discharge from the facility described below:

FACILITY NAME AND ADDRESS

Name: Newsday, Inc.
Location (C,T,V): Huntington (T) County: Suffolk
Facility Address: 235 Pinelawn Road
City: Melville State: NY ZipCode: 11747-4250
NYTM -E: NYTM - N:
Suffolk County Tax Map Numbers: District: 0400 Section: 20 Block: 2 Lot: 1
From Outfall No.: 001 at Latitude: 40 ° 15 ′ 14 ″ & Longitude: 73 ° 22 ′ 34 ″
into receiving waters known as: Groundwater Class: GA
and Outfalls 002, 003, 004 & 005 to Groundwater Class GA

in accordance with the effluent limitations, monitoring requirements and other conditions set forth in Special Conditions (Part I) of this permit and 6NYCRR Part 750-1.2(a) & 750-2.

DISCHARGE MONITORING REPORT (DMR) MAILING ADDRESS

Mailing Name: Newsday, Inc.
Street: 235 Pinelawn Road Fax 631.843.3444
City: Melville State: NY Zip Code: 11747-4250
Responsible Official : Mr. Joseph Marino,Manager Facilities Engrg. Phone: 631.843.2044

This permit and the authorization to discharge shall expire on midnight of the expiration date shown above and the permittee shall not discharge after the expiration date unless this permit has been renewed, or extended pursuant to law. To be authorized to discharge beyond the expiration date, the permittee shall apply for permit renewal not less than 180 days prior to the expiration date shown above.

DISTRIBUTION:
BWP Permit Coordinator ;
W. H. Spitz, Region 1;
A. Santino, SCDHS

Permit Administrator:	Roger Evans, DPA
Address:	Building 40 - SUNY @ Stony Brook Stony Brook, NY 11790-2356
Signature: Roger Evans	Date: 9/13/05

D:\MyFiles\FacilityFiles\Newsday\Permit\SanMod05.wpd

PERMIT LIMITS, LEVELS AND MONITORING DEFINITIONS

H:\My Files\Elliott\Bellport\Brookhaven\Permit\SanMod05.wpd

OUTFALL	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
	This cell describes the type of wastewater authorized for discharge. Examples include process wastewater, storm water, non-contact cooling water.	This cell lists classified waters of the state to which the listed outfall discharges.	The date this page starts in effect.	The date this page is no longer in effect

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQ.	SAMPLE TYPE
	The minimum level that must be maintained at all times.	The maximum level that may not be exceeded at any time.			

PARAMETER	COMPLIANCE LIMIT	ACTION LEVEL	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE
	Daily Max. and Daily Avg. are defined below. All determinations of compliance with substance specific discharge limits are made by comparing monitoring results to the compliance level.	Type I or Type II Action Levels are monitoring requirements, as defined below, that trigger additional monitoring and permit review when exceeded.	This can include units of flow, pH, Temperature, mass or concentration. Examples include SU, °F, µg/l, lbs/d, etc.	Examples include Daily, 3/week, weekly, 2/month, monthly, quarterly, 2/yr and yearly.	Examples include grab, 24 hour composite and 3 grab samples collected over a 6 hour period.

DAILY DISCHARGE.: The discharge of a pollutant measured during a calendar day or any 24-hour period that reasonably represents the calendar day for the purposes of sampling. For pollutants expressed in units of mass, the 'daily discharge' is calculated as the total mass of the pollutant discharged over the day. For pollutants with limitations expressed in other units of measurement, the 'daily discharge' is calculated as the average measurement of the pollutant over the day.

DAILY MAX.: The highest allowable daily discharge.

DAILY AVG.: The highest allowable average of daily discharges over a calendar month, calculated as the sum of all daily discharges measured during a calendar month divided by the number of daily discharges measured during that month.

ACTION LEVELS: Routine Action Level monitoring results, if not provided for on the Discharge Monitoring Report (DMR) form, shall be appended to the DMR for the period during which the sampling was conducted. If the additional monitoring requirement is triggered as noted below, the permittee shall undertake a short-term, high-intensity monitoring program for the parameter(s). Samples identical to those required for routine monitoring purposes shall be taken on each of at least three consecutive operating and discharging days and analyzed. Results shall be expressed in terms of both concentration and mass, and shall be submitted no later than the end of the third month following the month when the additional monitoring requirement was triggered. Results may be appended to the DMR or transmitted under separate cover to the same address. If levels higher than the Action Levels are confirmed, the permit may be reopened by the Department for consideration of revised Action Levels or effluent limits. The permittee is not authorized to discharge any of the listed parameters at levels which may cause or contribute to a violation of water quality standards.

TYPE I : The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results in excess of the stated Action Level.

TYPE II: The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results that show the stated action level exceeded for four of six consecutive samples, or for two of six consecutive samples by 20 % or more, or for any one sample by 50 % or more

FINAL PERMIT LIMITS, LEVELS AND MONITORING

...Files\FacilityFiles\Newsday\Permit\SanMod05.wpd

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
001	Industrial and Sanitary Wastewater	Groundwater	11/01/05	10/01/06

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FOOTNOTES (FN)
pH	6.5	8.5	SU	Monthly	Grab	

PARAMETER	ENFORCEABLE LIMIT		MONITORING ACTION LEVEL		UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FN
	Daily Avg.	Daily Max.	TYPE I	TYPE II				
Flow	Monitor	Monitor			gal/day	Continuous	Recorder	
Oil and Grease	NA	15			mg/l	Monthly	Grab	
Solids, Total Dissolved	NA	1000			mg/l	Monthly	Grab	
Cyanide	NA	0.4			mg/l	Monthly	Grab	
Nitrogen, Total (expressed as N)	NA	10			mg/l	Monthly	Grab	
Phenols, Total	NA	0.008			mg/l	Monthly	Grab	
Silver, Total	NA	0.1			mg/l	Monthly	Grab	
Toluene	NA	0.005			mg/l	Monthly	Grab	

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
002	Storm Water - No Process Wastes Allowed	Groundwater	11/01/05	10/01/06
No monitoring required.				

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
003	Non contact Compressor Cooling Water	Groundwater	11/01/05	10/01/06
No monitoring required.				


OUTFALLS No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
004 & 005	Sanitary Wastewater from Security Booths	Groundwater	11/01/05	10/01/06
No monitoring required.				

Notes:

1. BMP Plan: The completed Best Management Practices (BMP) plan submitted to this Department on August 29, 1997 shall be reviewed by the permittee on an annual basis. The BMP Plan shall be modified whenever changes at the facility materially increase the potential for significant releases of toxic or hazardous pollutants or where actual releases indicate that the plan is inadequate
2. Outfalls 004 & 005 Discharge via Septic Tanks and Leaching Pools.

MONITORING LOCATIONS

The permittee shall take samples and measurements, to comply with the monitoring requirements specified in this permit, at the location(s) specified below:






Figure 2

RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS

a) The permittee shall also refer to 6NYCRR Part 750-1.2(a) & 750-2 for additional information concerning monitoring and reporting requirements and conditions.

b) The monitoring information required by this permit shall be summarized, signed and retained for a period of three years from the date of the sampling for subsequent inspection by the Department or its designated agent. **Also, monitoring information required by this permit shall be summarized and reported by submitting;**

☒ (if box is checked) completed and signed Discharge Monitoring Report (DMR) forms for each 1 month reporting period to the locations specified below. Blank forms are available at the Department's Albany office listed below. The first reporting period begins on the effective date of this permit and the reports will be due no later than the 28th day of the month following the end of each reporting period.

☐ (if box is checked) an annual report to the Regional Water Manager at the address specified below. The annual report is due by February 1 and must summarize information for January to December of the previous year in a format acceptable to the Department.

☐ (if box is checked) a monthly "Wastewater Facility Operation Report..." (form 92-15-7) to the ☐ Regional Water Manager and/or ☐ County Health Department or Environmental Control Agency specified below.

Send the **original** (top sheet) of each DMR page to:

Department of Environmental Conservation
Division of Water, Bureau of Watershed Compliance Programs
625 Broadway
Albany, New York 12233-3506

Phone: (518) 402-8177

Send the **second copy** (third sheet) of each DMR page to:

Suffolk County Department of Health Services
15 Horseblock Place
Farmingville, New York 11738
Attn: Mr. Alex Santino P.E.

Send the **first copy** (second sheet) of each DMR page to:

Department of Environmental Conservation
Regional Water Manager
Building 40 - SUNY @ Stony Brook
Stony Brook, NY 11790-2356

NOTE: Include a copy of the laboratory analysis with the NYSDEC - Region 1 and SCDHS copies.

c) Noncompliance with the provisions of this permit shall be reported to the Department as prescribed in 6NYCRR Part 750-1.2(a) & 750-2.

d) Monitoring must be conducted according to test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit.

e) If the permittee monitors any pollutant more frequently than required by the permit, using test procedures approved under 40 CFR Part 136 or as specified in this permit, the results of this monitoring shall be included in the calculations and recording of the data on the Discharge Monitoring Reports.

f) Calculation for all limitations which require averaging of measurements shall utilize an arithmetic mean unless otherwise specified in this permit.

g) Unless otherwise specified, all information recorded on the Discharge Monitoring Report shall be based upon measurements and sampling carried out during the most recently completed reporting period.

h) Any laboratory test or sample analysis required by this permit for which the State Commissioner of Health issues certificates of approval pursuant to section five hundred two of the Public Health Law shall be conducted by a laboratory which has been issued a certificate of approval. Inquiries regarding laboratory certification should be sent to the Environmental Laboratory Accreditation Program, New York State Health Department Center for Laboratories and Research, Division of Environmental Sciences, The Nelson A. Rockefeller Empire State Plaza, Albany, New York 12201.

New York State Department of Environmental Conservation
Division of Environmental Permits, 4th Floor
625 Broadway, Albany, New York 12233-1750
Phone: (518) 402-9167 • **FAX:** (518) 402-9168
Website: www.dec.state.ny.us

Denise M. Sheehan
Commissioner

MAR 1 4 2006

FACILITY INFORMATION

NEWSDAY, INC
JOSEPH MARINO MGR
235 PINELAWN RD
MELVILLE NY 11747-4250

NAME: NEWSDAY INC
LOCATION: (T) HUNTINGTON
COUNTY: SUFFOLK
SPDES NO: NY 013 6751
DEC ID NO. 1-4726-00157-00001

Dear SPDES Permittee:

Enclosed please find a validated NOTICE/RENEWAL APPLICATION/PERMIT form renewing your State Pollutant Discharge Elimination System (SPDES) permit for the referenced facility. This validated form, together with the previously issued permit (see issuance date of this permit in Part 3 of the NOTICE/RENEWAL APPLICATION/PERMIT form), and any subsequent permit modifications constitute authorization to discharge wastewater in accordance with all terms, conditions and limitations specified therein.

The instructions and other information that you received with the NOTICE/RENEWAL APPLICATION/PERMIT package fully described procedures for renewal and modification of your SPDES permit under the Environmental Benefit Permit Strategy (EBPS). As a reminder, SPDES permits are renewed at a central location in Albany in order to make the process more efficient. All other concerns with your permit such as applications for permit modifications, permit transfers to a new owner, name changes, and other questions should be directed to the Regional Permit Administrator at the following address:

John Pavacic
NYSDEC REGION 1
Building 40, Room 121
SUNY at Stony Brook
Stony Brook, NY 11790-2356
(631) 444-0365

If you have already filed an application for modification of your permit, it will be processed separately through our regional office. If you have questions concerning this permit renewal, please contact Lynn Kaplan at (518) 402-9165.

Sincerely,

William R. Adriance

Chief Permit Administrator

Enclosure
cc: RPA
RWE
BWP
SUFFOLK COUNTY

81-20-5 (5/97)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)

NOTICE / RENEWAL APPLICATION / PERMIT

RECEIVED NYSDEC

Please read **ALL** instructions on the back before completing this application form. Please **TYPE** or **PRINT** clearly in ink.

PART 1 - NOTICE

12/19/2005

Permittee Contact Name, Title, Address

NEWSDAY, INC.
JOSEPH MARINO MGR
235 PINELAWN RD.
MELVILLE NY 11747-4250

Facility and SPDES Permit Information

Name: NEWSDAY INC
Ind. Code: 2711 County: SUFFOLK
DEC No.: 1-4726-00157/00001
SPDES No.: NY 013 6751
Expiration Date: 10/01/2006
Application Due By: 04/04/2006

plumbing tbm

Are these name(s) & address(es) correct? if not, please write corrections above.

The State Pollutant Discharge Elimination System Permit for the facility referenced above expires on the date indicated. You are required by law to file a complete renewal application **at least 180 days prior to expiration of your current permit Note the "Application Due By" date above**

CAUTION: This short application form and attached questionnaire are the only forms acceptable for permit renewal. Sign Part 2 below and mail only this form and the completed questionnaire using the enclosed envelope. *Effective April 1, 1994 the Department no longer assesses SPDES application fees.*

If there are changes to your discharge, or to operations affecting the discharge, then in addition to this renewal application, you must also submit a separate permit modification application to the Regional Permit Administrator for the DEC region in which the facility is located, as required by your current permit. See the reverse side of this page for instructions on filing a modification request.

PART 2 - RENEWAL APPLICATION

CERTIFICATION: *I hereby affirm that under penalty of perjury that the information provided on this form and all attachments submitted herewith is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to section 210.45 of the Penal Law.*

Frank Toner, Sr. V.P. Operations and Engineering Services

Name of person signing application (see instructions on back) — Title

Frank Toner — January 19, 2005

Signature — Date

PART 3 - PERMIT (Below this line - Official Use Only)

Effective Date: 10/1/06 Expiration Date: 9/30/11

William R Adriance

Permit Administrator

Address: NYSDEC - Division of Environmental Permits
Bureau of Environmental Analysis
625 Broadway, Albany, NY 12233-1750

William R. Adriance — MAR 14 2006

Signature — Date

This permit together with the previous valid permit for this facility issued 10/1/01 and subsequent modifications constitute authorization to discharge wastewater in accordance with all terms, conditions and limitations specified in the previously issued valid permit, modifications thereof or issued as part of this permit, including any special or general conditions attached hereto. Nothing in this permit shall be deemed to waive the Department's authority to initiate a modification of this permit on the grounds specified in 6NYCRR §621.14, 6NYCRR §754.4 or 6NYCRR §757.1 existing at the time this permit is issued or which arise thereafter.

~~Attachments: General Conditions dated ___~~

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Please enter the numbers from your current permit:	DEC Number: 1-4726-00571/00001-__
	SPDES Number: NY 013 6751

SPDES RENEWAL APPLICATION
QUESTIONNAIRE

THIS PAGE MUST BE COMPLETED AND RETURNED WITH YOUR COMPLETED APPLICATION

Please **TYPE** or **PRINT** neatly using adequate pressure to make ALL copies legible. Keep the GOLD copy for your records.

1 Has the SPDES permit for your facility been modified in the past 5 years ☒ YES ☐ NO

2. Dischargers who use, manufacture, store, handle or discharge toxic or hazardous pollutants are subject to Industrial Best Management Practices (BMP) plan requirements for toxic or hazardous substances. A BMP plan prevents or minimizes the potential for release of pollutants to receiving waters from such ancillary industrial activities, including material storage areas; plant site runoff; in-plant transfer; process and material storage areas; loading and unloading operations, and sludge and waste disposal areas.

Does your facility conduct ancillary activities as described above, which are not covered by BMP requirements in your current permit? ☐ YES ☒ NO

Please indicate which of the following best describes the situation at your facility:

☐ None of the concerns on the "Self Evaluation List" seem to apply to my facility at this time and I will not be applying for a modification of the SPDES permit in the foreseeable future.

☐ Yes, some of the items on the "Self Evaluation List" have led me to believe my permit needs to be modified. I already have a complete modification application pending with the Department.

☐ Yes, some of the items on the "Self Evaluation List" have led me to believe that the SPDES permit for this facility may need to be Modified. I have requested the appropriate forms by phone OR I have completed and attached the "Request For SPDES Application Forms" (included in this renewal package) to allow me to submit a permittee-initiated Modification application.

☒ The items on the "Self Evaluation List" have left me unable to conclude whether my permit needs to be modified at this time. I am reporting the following general concerns about my permit:

- On site waste water treatment plant is undergoing modification. The new design is complete and has been approved by Suffolk County Department of Health Services. The local NYSDEC Region 1 Engineer is aware of the new design. Upgrade is scheduled for completion in 2007.

- Industrial photo chemistry process will be eliminated within the next few years. The Region 1 Engineer will be notified at that time.

- SPDES permit modified by DEC Department initiated modification (amendment of 6NYCRR 750-2) dated 23February, 2004.

DISTRIBUTION: Regional Water Engineer
Central Office (BWP)
Regional Permit Administrator
Applicant

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

State Pollutant Discharge Elimination System (SPDES)
DISCHARGE PERMIT

Special Conditions (Part 1)

Industrial Code:	2711	SPDES Number:	**NY- 013 6751**
Discharge Class (CL):	01	DEC Number:	1-4726-00157/00001
Toxic Class (TX):	T	Effective Date (EDP):	10/01/2006
Major Drainage Basin:	17	Expiration Date (ExPD):	09/30/2011
Sub Drainage Basin:	01	Modification Dates:	05/30/2008
Water Index Number:	Groundwater		
Compact Area:			

This SPDES permit is issued in compliance with Title 8 of Article 17 of the Environmental Conservation Law of New York State and in compliance with the Clean Water Act, as amended, (33 U.S.C. §1251 et.seq.)(hereinafter referred to as "the Act").

PERMITTEE NAME AND ADDRESS

Name: Newsday, Inc. Attention: Joseph Marino, Mgr. Facilities Engrg.
Street: 235 Pinelawn Road
City: Melville State: NY Zip Code: 11747-4250

is authorized to discharge from the facility described below:

FACILITY NAME AND ADDRESS

Name: Newsday, Inc.
Location (C,T,V): Huntington (T) County: Suffolk
Facility Address: 235 Pinelawn Road
City: Melville State: NY ZipCode: 11747-4250
NYTM -E: NYTM - N:
Suffolk County Tax Map Numbers: District: 0400 Section: 20 Block: 2 Lot: 1
From Outfall No.: 001 at Latitude: 40 ° 15 ′ 14 ″ & Longitude: 73 ° 22 ′ 34 ″
into receiving waters known as: Groundwater Class: GA
and Outfalls 002, 003, 004 & 005 to Groundwater Class GA

in accordance with the effluent limitations, monitoring requirements and other conditions set forth in Special Conditions (Part I) of this permit and 6NYCRR Part 750-1.2(a) & 750-2.

DISCHARGE MONITORING REPORT (DMR) MAILING ADDRESS

Mailing Name: Newsday, Inc.
Street: 235 Pinelawn Road Fax 631.843.3444
City: Melville State: NY Zip Code: 11747-4250
Responsible Official : Mr. Joseph Marino,Manager Facilities Engrg. Phone: 631.843.2044

This permit and the authorization to discharge shall expire on midnight of the expiration date shown above and the permittee shall not discharge after the expiration date unless this permit has been renewed, or extended pursuant to law. To be authorized to discharge beyond the expiration date, the permittee shall apply for permit renewal not less than 180 days prior to the expiration date shown above.

DISTRIBUTION:
BWP Permit Coordinator ;
W. H. Spitz, Region 1;
J. Meyers , SCDHS

Permit Administrator:	Roger Evans, Regional Permit Admiistrator
Address:	50 Circle Road - SUNY @ Stony Brook Stony Brook, NY 11790-3409
Signature:	Roger Evans — Date: 6/4/08

H:\MyFiles\FacilityFiles\Newsday\Permit\AerotorMod08.wpd

PERMIT LIMITS, LEVELS AND MONITORING DEFINITIONS

OUTFALL	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
	This cell describes the type of wastewater authorized for discharge. Examples include process wastewater, storm water, non-contact cooling water.	This cell lists classified waters of the state to which the listed outfall discharges.	The date this page starts in effect.	The date this page is no longer in effect

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQ.	SAMPLE TYPE
	The minimum level that must be maintained at all times.	The maximum level that may not be exceeded at any time.			

PARAMETER	COMPLIANCE LIMIT	ACTION LEVEL	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE
	Daily Max. and Daily Avg. are defined below. All determinations of compliance with substance specific discharge limits are made by comparing monitoring results to the compliance level.	Type I or Type II Action Levels are monitoring requirements, as defined below, that trigger additional monitoring and permit review when exceeded.	This can include units of flow, pH, Temperature, mass or concentration. Examples include SU, °F, µg/l, lbs/d, etc.	Examples include Daily, 3/week, weekly, 2/month, monthly, quarterly, 2/yr and yearly.	Examples include grab, 24 hour composite and 3 grab samples collected over a 6 hour period.

DAILY DISCHARGE.: The discharge of a pollutant measured during a calendar day or any 24-hour period that reasonably represents the calendar day for the purposes of sampling. For pollutants expressed in units of mass, the 'daily discharge' is calculated as the total mass of the pollutant discharged over the day. For pollutants with limitations expressed in other units of measurement, the 'daily discharge' is calculated as the average measurement of the pollutant over the day.

DAILY MAX.: The highest allowable daily discharge.

DAILY AVG.: The highest allowable average of daily discharges over a calendar month, calculated as the sum of all daily discharges measured during a calendar month divided by the number of daily discharges measured during that month.

ACTION LEVELS: Routine Action Level monitoring results, if not provided for on the Discharge Monitoring Report (DMR) form, shall be appended to the DMR for the period during which the sampling was conducted. If the additional monitoring requirement is triggered as noted below, the permittee shall undertake a short-term, high-intensity monitoring program for the parameter(s). Samples identical to those required for routine monitoring purposes shall be taken on each of at least three consecutive operating and discharging days and analyzed. Results shall be expressed in terms of both concentration and mass, and shall be submitted no later than the end of the third month following the month when the additional monitoring requirement was triggered. Results may be appended to the DMR or transmitted under separate cover to the same address. If levels higher than the Action Levels are confirmed, the permit may be reopened by the Department for consideration of revised Action Levels or effluent limits. The permittee is not authorized to discharge any of the listed parameters at levels which may cause or contribute to a violation of water quality standards.

TYPE I : The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results in excess of the stated Action Level.

TYPE II: The additional monitoring requirement is triggered upon receipt by the permittee of any monitoring results that show the stated action level exceeded for four of six consecutive samples, or for two of six consecutive samples by 20 % or more, or for any one sample by 50 % or more

FINAL PERMIT LIMITS, LEVELS AND MONITORING

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
001	Industrial and Sanitary Wastewater	Groundwater	10/01/06	9/30/11

PARAMETER	MINIMUM	MAXIMUM	UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FOOTNOTES (FN)
pH	6.5	8.5	SU	Monthly	Grab	

PARAMETER	ENFORCEABLE LIMIT		MONITORING ACTION LEVEL		UNITS	SAMPLE FREQUENCY	SAMPLE TYPE	FN
	Daily Avg.	Daily Max.	TYPE I	TYPE II				
Flow	Monitor	Monitor			gal/day	Continuous	Recorder	
Oil and Grease	NA	15			mg/l	Monthly	Grab	
Solids, Total Dissolved	NA	1000			mg/l	Monthly	Grab	
Cyanide	NA	0.4			mg/l	Monthly	Grab	
Nitrogen, Total (expressed as N)	NA	10			mg/l	Monthly	Grab	
Phenols, Total	NA	0.008			mg/l	Monthly	Grab	
Silver, Total	NA	0.1			mg/l	Monthly	Grab	
Toluene	NA	0.005			mg/l	Monthly	Grab	

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
002	Storm Water - No Process Wastes Allowed	Groundwater	10/01/06	9/30/11
No monitoring required.				

OUTFALL No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
003	Non contact Compressor Cooling Water	Groundwater	10/01/06	9/30/11
No monitoring required.				


OUTFALLS No.	WASTEWATER TYPE	RECEIVING WATER	EFFECTIVE	EXPIRING
004 & 005	Sanitary Wastewater from Security Booths	Groundwater	10/01/06	9/30/11
No monitoring required.				


Notes:

1. BMP Plan: The completed Best Management Practices (BMP) plan submitted to this Department on August 29, 1997 shall be reviewed by the permittee on an annual basis. The BMP Plan shall be modified whenever changes at the facility materially increase the potential for significant releases of toxic or hazardous pollutants or where actual releases indicate that the plan is inadequate
2. Outfalls 004 & 005 Discharge via Septic Tanks and Leaching Pools.

MONITORING LOCATIONS

The permittee shall take samples and measurements, to comply with the monitoring requirements specified in this permit, at the location(s) specified below:





RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS

a) The permittee shall also refer to 6NYCRR Part 750-1.2(a) & 750-2 for additional information concerning monitoring and reporting requirements and conditions.

b) The monitoring information required by this permit shall be summarized, signed and retained for a period of three years from the date of the sampling for subsequent inspection by the Department or its designated agent. **Also, monitoring information required by this permit shall be summarized and reported by submitting;**

☒ (if box is checked) completed and signed Discharge Monitoring Report (DMR) forms for each 1 month reporting period to the locations specified below. Blank forms are available at the Department's Albany office listed below. The first reporting period begins on the effective date of this permit and the reports will be due no later than the 28th day of the month following the end of each reporting period.

☐ (if box is checked) an annual report to the Regional Water Manager at the address specified below. The annual report is due by February 1 and must summarize information for January to December of the previous year in a format acceptable to the Department.

☐ (if box is checked) a monthly "Wastewater Facility Operation Report..." (form 92-15-7) to the ☐ Regional Water Manager and/or ☐ County Health Department or Environmental Control Agency specified below.

Send the **original** (top sheet) of each DMR page to:

Department of Environmental Conservation
Division of Water, Bureau of Watershed Compliance Programs
625 Broadway
Albany, New York 12233-3506

Phone: (518) 402-8177

Send the **second copy** (third sheet) of each DMR page to:

Suffolk County Department of Health Services
15 Horseblock Place
Farmingville, New York 11738
Attn: Mr. James Meyers P.E.

Send the **first copy** (second sheet) of each DMR page to:

Department of Environmental Conservation
Regional Water Manager
50 Circle Road SUNY @ Stony Brook
Stony Brook, NY 11790-3409

c) Noncompliance with the provisions of this permit shall be reported to the Department as prescribed in 6NYCRR Part 750-1.2(a) & 750-2.

d) Monitoring must be conducted according to test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit.

e) If the permittee monitors any pollutant more frequently than required by the permit, using test procedures approved under 40 CFR Part 136 or as specified in this permit, the results of this monitoring shall be included in the calculations and recording of the data on the Discharge Monitoring Reports.

f) Calculation for all limitations which require averaging of measurements shall utilize an arithmetic mean unless otherwise specified in this permit.

g) Unless otherwise specified, all information recorded on the Discharge Monitoring Report shall be based upon measurements and sampling carried out during the most recently completed reporting period.

h) Any laboratory test or sample analysis required by this permit for which the State Commissioner of Health issues certificates of approval pursuant to section five hundred two of the Public Health Law shall be conducted by a laboratory which has been issued a certificate of approval. Inquiries regarding laboratory certification should be sent to the Environmental Laboratory Accreditation Program, New York State Health Department Center for Laboratories and Research, Division of Environmental Sciences , The Nelson A. Rockefeller Empire State Plaza, Albany, New York 12201.

91-20-5 (5/97)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
State Pollutant Discharge Elimination System (SPDES)
NOTICE / RENEWAL APPLICATION / PERMIT

Please read **ALL** instructions on the back before completing this application form. Please **TYPE** or **PRINT** clearly in ink.

PART 1 - NOTICE

11/15/2010

Permittee Contact Name, Title, Address

NEWSDAY ~~INC.~~ LLC (name change completed 7/15/2008)
JOSEPH MARINO MGR
235 PINELAWN RD.
MELVILLE NY 11747-4250

FEE updated 8/22/11

Facility and SPDES Permit Information

Name: NEWSDAY ~~INC~~ LLC
Ind. Code: 2711 County: SUFFOLK
DEC No.: 1-4726-00157/00001
SPDES No.: NY 013 6751
Expiration Date: 09/30/2011
Application Due By: 04/03/2011

Are these name(s) & address(es) correct? if not, please write corrections above.

The State Pollutant Discharge Elimination System Permit for the facility referenced above expires on the date indicated. You are required by law to file a complete renewal application **at least 180 days prior to expiration of your current permit**. **Note the "Application Due By" date above.**

CAUTION: This short application form and attached questionnaire are the only forms acceptable for permit renewal. Sign Part 2 below and mail only this form and the completed questionnaire using the enclosed envelope. *Effective April 1, 1994 the Department no longer assesses SPDES application fees.*

If there are changes to your discharge, or to operations affecting the discharge, then in addition to this renewal application, you must also submit a separate permit modification application to the Regional Permit Administrator for the DEC region in which the facility is located, as required by your current permit. See the reverse side of this page for instructions on filing a modification request.

PART 2 - RENEWAL APPLICATION

CERTIFICATION: I hereby affirm that under penalty of perjury that the information provided on this form and all attachments submitted herewith is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to section 210.45 of the Penal Law.

JOSEPH MARINO — MANAGER, FACILITIES ENGINEERING
Name of person signing application (see instructions on back) — Title

Joseph Marino — 8/15/2011
Signature — Date

PART 3 - PERMIT (Below this line - Official Use Only)

Effective Date: 12/1/11 Expiration Date: 11/30/21

Stuart Fox
Permit Administrator

Address: NYSDEC - Division of Environmental Permits
Bureau of Environmental Analysis
625 Broadway, Albany, NY 12233-1750

Stuart M Fox
Signature

NOV 15 2011
Date

This permit together with the previous valid permit for this facility issued 10/1/06 and subsequent modifications constitute authorization to discharge wastewater in accordance with all terms, conditions and limitations specified in the previously issued valid permit, modifications thereof or issued as part of this permit, including any special or general conditions attached hereto. Nothing in this permit shall be deemed to waive the Department's authority to initiate a modification of this permit on the grounds specified in 6NYCRR §621.14, 6NYCRR §754.4 or 6NYCRR §757.1 existing at the time this permit is issued or which arise thereafter.

~~Attachments: General Conditions dated ___/___~~

91-20-5a (5/97)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Please enter the numbers from your current permit:

DEC Number: 1-4726-00157/0000-1

SPDES Number: NY 013 6751

SPDES RENEWAL APPLICATION
QUESTIONNAIRE

THIS PAGE MUST BE COMPLETED AND RETURNED WITH YOUR COMPLETED APPLICATION

Please **TYPE** or **PRINT** neatly using adequate pressure to make ALL copies legible. Keep a copy for your records.

1. Has the SPDES permit for your facility been modified in the past 5 years ☒ YES ☐ NO

2. Dischargers who use, manufacture, store, handle or discharge toxic or hazardous pollutants are subject to Industrial Best Management Practices (BMP) plan requirements for toxic or hazardous substances. A BMP plan prevents or minimizes the potential for release of pollutants to receiving waters from such ancillary industrial activities, including material storage areas; plant site runoff; in-plant transfer; process and material storage areas; loading and unloading operations, and sludge and waste disposal areas.

   Does your facility conduct ancillary activities as described above, which are not covered by BMP requirements in your current permit? ☐ YES ☒ NO

Please indicate which of the following best describes the situation at your facility:

☐ None of the concerns on the "Self Evaluation List" seem to apply to my facility at this time and I will not be applying for a modification of the SPDES permit in the foreseeable future.

☐ Yes, some of the items on the "Self Evaluation List" have led me to believe that the permit for this facility needs to be modified. I already have a complete modification application pending with the Department.

☐ Yes, some of the items on the "Self Evaluation List" have led me to believe that the SPDES permit for this facility may need to be Modified. I have requested the appropriate forms by phone OR I have completed and attached the "Request For SPDES Application Forms" (included in this renewal package) to allow me to submit a permittee-initiated Modification application. See The "Request For SPDES Application Forms" page for a toll-free 800 number.

☒ The items on the "Self Evaluation List" have left me unable to conclude whether my permit needs to be modified at this time. I am reporting the following general concerns about my permit:

NEWSDAY LLC HAS ELIMINATED MANY CHEMICALS ASSOCIATED WITH PHOTO WET CHEMISTRY DUE TO DIGITAL PRINTING EQUIPMENT. SUBSQUENTLY, THE EFFLUENT FROM THE WASTEWATER TREATMENT PLANT HAS BEEN IN CONSISTENT COMPLIANCE WITH SOME OF THE PERMIT PARAMETERS THAT WERE ASSOCIATED WITH THE OLDER PHOTO WET CHEMISTRY AND OTHER MISCELLANEOUS CHEMICALS THROUGHOUT THE FACILITY SUCH AS PHENOL, SILVER, TOLUENE AND CYANIDE. WE REQUEST THAT THESE BE REMOVED FROM THE PERMIT.

DISTRIBUTION: Regional Water Engineer
Regional Permit Administrator
Central Office (BWP)

State Pollutant Discharge Elimination System (SPDES)

Application Supplement B
DISCHARGES WITHIN SOLE SOURCE AQUIFERS

Facility Name: Newsday LLC	SPDES Number: NY 0136751

Your facility may be located in a sole source aquifer area, which is an area designated by Federal or State statutes. Maps showing the designated sole source areas can be found on the internet at: www.epa.gov/Region02/water/aquifer/index.html.

Chapter 663 of the Laws of 1983 added Section 17-0828 to the Environmental Conservation Law which requires that any person seeking a SPDES permit or a renewal hereunder, within an area designated pursuant to any federal or state statute as a sole source aquifer, shall include as a part of the required information, the name and address of all public water purveyors with a service area or portion thereof located within a three mile radius of the applicant's facility.

For purposes of this section "public water purveyor" shall mean any person, partnership, public or private corporation, municipality, or public authority which sells water derived from a sole source aquifer to at least five service connections or at least twenty-five individuals.

---

1. Water Purveyors within a three mile radius of your facility:

Please complete the following information to the best of your knowledge and attach it to your application. Attach additional copies of this sheet as necessary.

	Name	Address
1.	South Huntington Water District	75 Fifth Avenue South P.O. Box 370 Huntington Station, NY 11746
2.		
3.		
4.		
5.		
6.		
7.		
8.		
9.		
10.		
11.		

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **December 2007** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **PH (6.1)**

Due to a drop in alkalinity due to the nitrification process.

Has event ceased? (**Yes**) (No) If so, when? **unknown** Was event due to plant upset? (Yes) (**No**) SPDES limits violated? (**Yes**) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

Add Soda Ash to the process to raise the alkalinity as well as raise the pH back into compliance.

Preventive (long term) corrective actions:

To continue monitoring the process and supplement with an alkalinity source, (Soda Ash).

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joseph Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** 1/22/08

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph V. Marino

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **December 2006** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **Nitrogen (11 mg/l)**

High Nitrogen due to incomplete nitrification in filter.

Has event ceased? (**Yes**) (No) If so, when? **unknown** Was event due to plant upset? (Yes) (**No**) SPDES limits violated? (**Yes**) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

Frequent backwash and scour

Preventive (long term) corrective actions:

Newsday's WWTP upgrade and subsequent implementation of anoxic tank and MBR clarifier will commence February 8th.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Stephen Cluff** **TITLE:** **Sr. Facilities Engineer** **DATE:** **1/29/06**

Phone #: **631-843-3631** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact Robert Schneck Regional Water Engineer DEC Region: 1

Report Type ___ 5 Day ___ Permit Violation X Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: 0136751 Facility: **Newsday, Inc.**

Date of noncompliance: _____ Location (Outfall, Treatment Unit, or Pump Station): OUTFALL

Description of noncompliance(s) and cause(s):

NITROGEN 11 mg/L

Has event ceased? (Yes) (No) If so, when? _____ Was event due to plant upset? (Yes) (No) SPDES limits violated? **(Yes)** (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: _____

Immediate corrective actions: UPSET DUE TO CONSTRUCTION ACTIVITIES AND TRANSFER BETWEEN PROCESS TANKS LED TO INCOMPLETE DENITRIFICATION

Preventive (long term) corrective actions: COMPLETE WWTP UPGRADE EXPECTED END OF JANUARY

SECTION 3

Complete this section if event was a bypass:

Bypass amount: _____ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: _____ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLUFF **TITLE:** SC FACILITIES ENG **DATE:** 21 DEC 06

Phone #: (631) 843-3631 **FAX #:** (631) 843-3444

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

_____

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact — Robert Schneck, Regional Water Engineer — DEC Region: 1

Report Type: 5 Day ___ Permit Violation X Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: 0136751 Facility: **Newsday, Inc.**

Date of noncompliance: 10/2/06 Location (Outfall, Treatment Unit, or Pump Station): OUTFALL

Description of noncompliance(s) and cause(s):

NITROGEN EXCEEDANCE (12 mg/l) DUE TO EXCESSIVE SOLIDS BULLOUP & INCOMPLETE DENITRIFICATION

Has event ceased? (Yes) (No) If so, when? ___ Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

NEW AERATOR PROBE INSTALLED; FILTERS BACKWASHED MORE FREQUENTLY

Preventive (long term) corrective actions: COMPLETE FACILITY UPGRADE NEAR COMPLETION & MORE FILTERS TO REPLACE CLOTHS & DENITE FILTER

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLIFF **TITLE:** SR. ENGINEER **DATE:** 27 NOV 06

Phone #: (631) 843-3631 **FAX #:** (631) 843-3444

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact Robert Schneck Regional Water Engineer DEC Region: 1

Report Type ___ 5 Day ___ Permit Violation X Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: 0136751 Facility: **Newsday, Inc.**

Date of noncompliance: 7/27 - 7/31 Location (Outfall, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s):
LOW PH (6.25, 6.39, 6.48, 6.49) DUE DUE PLANT UPSET AND ALKALINITY ADDITIONS

Has event ceased? (Yes) (No) If so, when? ___ Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:
PLANT UPSET CLEARED AFTER SEVERAL DAYS BY PUMPING OUT POOLS TANKING LOAD OF PLANT.

Preventive (long term) corrective actions: COMPLETE FACILITY UPGRADE IN PROGRESS

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLUFF **TITLE:** SR. FACILITIES ENG **DATE:** 28/AUG/06

Phone #: (631)843-3613 **FAX #:** (631)843-3444

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact Robert Schneck Regional Water Engineer DEC Region: 1

Report Type ___ 5 Day ___ Permit Violation X Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: 0136751 Facility: **Newsday, Inc.**

Date of noncompliance: 7/17/06 Location (Outfall, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s):

NITRATES EXCEEDANCE 11 mg/l DUE TO PLANT UPSET

Has event ceased? (Yes) (No) If so, when? ___ Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

PLANT UPSET DUE TO EXCESSIVE COOLING WATER / LEACHING POOLS BACKED UP LEADING TO INCOMPLETE DENITRIFICATION AND LOW MLSS CONCENTRATION

Preventive (long term) corrective actions: COOLING WATER WAS DIVERTED IMMEDIATELY TO PERMITTED POOLS FOR THIS DISCHARGE. COMPLETE FACILITY UPGRADE IN PROGRESS.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLIFF **TITLE:** SR. FACILITIES ENGR. **DATE:** 28 JULY 06

Phone #: (631) 843-3631 **FAX #:** (631) 843-3644

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Stephen Cliff

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact — Robert Schneck, Regional Water Engineer — DEC Region: 1

Report Type: ___ 5 Day ___ Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other

SECTION 2

SPDES #: **0136751** Facility: **Newsday, Inc.**

Date of noncompliance: JUNE 19, 06 Location (Outfall, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s):

NITROGEN EXCEEDANCE (16 mg/l) DUE TO ERROR IN OXYGENATION FROM AERATOR IN NIGHT MODE/DO PROBE ERROR

Has event ceased? (Yes) (No) If so, when? UKN Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

MANUFACTURER EVALUATED PANEL MADE CORRECTIVE ACTIONS TO PANEL CONTROLLERS/OVERHEAT CONDITIONS.

Preventive (long term) corrective actions: NEW AERATOR PANEL INSTALLED INSIDE; NEW DO PROBE TO BE INSTALLED. 2ND AERATOR TO BE INSTALLED WITHIN A MONTH

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLIFF **TITLE:** SLF FACILITIES ENG **DATE:** JUL 26, 06

Phone #: (631) 843-3631 **FAX #:** (631) 843-3444

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact Robert Schneck Regional Water Engineer DEC Region: 1

Report Type ___ 5 Day ___ Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other

SECTION 2

SPDES #: 0136751 Facility: Newsday, Inc.

Date of noncompliance: JUNE 19, 06 Location (Outfall, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s):

SILVER EXCEEDANCE (0.11 mg/l) DUE TO CLOGGED INDUSTRIAL PIPE & SUBSEQUENT OVERFLOW THROUGH SILVER RECOVERY.

Has event ceased? (Yes) (No) If so, when? ___ Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: JUNE 19 06. ___ : ___ (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions: INDUSTRIAL DRAIN LINE CLEANED.

Preventive (long term) corrective actions: NEWSDAY IS ELIMINATING PHOTO/COMPOSING CHEMISTRY WITHIN NEXT 6 MONTHS WHICH INCLUDES SILVER.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /


Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLUFF **TITLE:** SR. FACILITIES ENG **DATE:** JUL 26, 06

Phone #: (631) 843-3631 **FAX #:** (631) 843-3444

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations



Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **3/2006** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **Nitrogen (14 mg/l)**

Due to cold temperatures, total nitrogen exceeded the permitted value with a reported value of 14 mg/l. Extensive BOD loading in influent flow stream process was unable to completely oxidize the BOD.

Has event ceased? (**Yes**) (No) If so, when? **unknown** Was event due to plant upset? (Yes) (**No**) SPDES limits violated? (**Yes**) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

We shall increase recycle flow rate to increase process detention time.

Preventive (long term) corrective actions:

We shall increase Aerotor process detention time for complete nitrification.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **4/18/06**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph Marino

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **2/2006** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **Nitrogen (14 mg/l)**

Due to cold temperatures, total nitrogen exceeded the permitted value with a reported value of 14 mg/l. Extensive BOD loading in influent flow stream process was unable to completely oxidize the BOD.

Has event ceased? (**Yes**) (No) If so, when? **unknown** Was event due to plant upset? (Yes) (**No**) SPDES limits violated? (**Yes**) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

We shall increase recycle flow rate to increase process detention time.

Preventive (long term) corrective actions:

We shall increase Aerotor process detention time for complete nitrification.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **3/7/06**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph Marino

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **January 2006** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **Nitrogen (18 mg/l)**

Due to cold temperatures, total nitrogen was exceeded with a reported value of 18 mg/l. Extensive BOD loading in influent flow stream, process was unable to completely oxidize the BOD, which resulted in total nitrogen exceeding the limit.

Has event ceased? **(Yes)** (No) If so, when? **unknown** Was event due to plant upset? (Yes) **(No)** SPDES limits violated? **(Yes)** (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions:

Increase recycle flow rate to increase process detention time.

Preventive (long term) corrective actions:

Increase Aerotor process detention time for complete nitrification.

SECTION 3

~~Complete this section if event was a bypass:~~

~~Bypass~~ amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates ~~and times~~ in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **2/24/06**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph Marino

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **09/27/04** Location (**Outfall**, Treatment Unit, or Pump Station):

Description of noncompliance(s) and cause(s): **Nitrogen (15 mg/l) One process unit (aerotor) is currently under re-construction. the other process unit (extended aeration basin) is experiencing hydraulic overload due to decreased detention time.**

Has event ceased? (**Yes**) (No) If so, when? **unknown** Was event due to plant upset? (Yes) (**No**) SPDES limits violated? (**Yes**) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted:

Immediate corrective actions: **Sludge removal rate will be increased. The Aerotor process unit is under re-construction and is scheduled to be back in service within the next 45 days.**

Preventive (long term) corrective actions:

SECTION 3

Complete this section if event was a bypass:

Bypass amount: Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **10/15/04**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph V. Martin

Signature of Principal Executive Officer or Authorize Agent

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **5/24/04** Location (**Outfall**, Treatment Unit, or Pump Station): ___

Description of noncompliance(s) and cause(s): **Nitrogen (21 mg/l). Unknown cause. Due to the new pilot aerator experiment the elevated level of nitrogen was caused by the carry-over of solids from the clarifiers.**

Has event ceased? **(Yes)** (No) If so, when? **unknown** Was event due to plant upset? (Yes) **(No)** SPDES limits violated? **(Yes)** (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted: ___

Immediate corrective actions: **Investigating cause believed to be associated with the new pilot project.**

Preventive (long term) corrective actions: **A full-scale pilot project is being proven.**

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **5/26/04**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph V. Marino

Signature of Principal Executive Officer or Authorize Agent

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747
tel: 631/843-2616
fax: 631/843-3444
tom.perrotta@newsday.com
Tom Perrotta
Assistant Manager,
Building Services/Security

June 25, 2004

New York State Department of Environmental Conservation
Division of Water
Bureau of Watershed Compliance Programs
625 Broadway 4th Floor
Albany, New York 12233-3506

SUBJECT: **SPDES #NY0136751**

To Bureau of Wastewater Facilities Operations:

Attached is the Discharge Monitoring Report for May 2004. Also, attached is a "Report of Noncompliance Event" form. A full-scale pilot project is underway and possibly resulted in the noncompliance.



Sincerely,

Tom Perrotta

Tom Perrotta
Assistant Manager,
Building Services/Security

CC: DEC - Stony Brook
SCOWM

Attachments: (1) Discharge Monitoring Report 4/04
(1) Report of Noncompliance Event

File: DMR(5-04).doc

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other ___

SECTION 2

SPDES #: **0136751** Facility: **Newsday**

Date of noncompliance: **4/28/04** Location (**Outfall**, Treatment Unit, or Pump Station):

Description of noncompliance(s) and cause(s): **Toluene (6 ug/l). Unknown cause. New Aerotor project is currently running simultaneously with current process.**

Has event ceased? **(Yes)** (No) If so, when? **unknown** Was event due to plant upset? (Yes) **(No)** SPDES limits violated? **(Yes)** (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted:

Immediate corrective actions: **Investigating cause believed to be associated with the new pilot project.**

Preventive (long term) corrective actions: **A full-scale pilot project is being proven.**

SECTION 3

Complete this section if event was a bypass:

Bypass amount: Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joe Marino** **TITLE:** **Manager, Facilities Engineering** **DATE:** **5/26/04**

Phone #: **631-843-2044** **FAX #:** **631-843-3444**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph U. Marino

Signature of Principal Executive Officer or Authorize Agent

CAMERON ENGINEERING & ASSOCIATES, LLP

Three Aerial Way, Suite 100
Syosset, NY 11791-5598
Tel 516-827-4900 Fax 516-827-4920

April 26, 2004

Active Member of
ACEC New York
American Council of Engineering Companies

Partners
John D. Cameron, Jr., P.E.
Joseph R. Amato, P.E.

Associates
Mark Wagner
Janice Jijina, AICP
Glenn DeSimone, P.E., CPE
Nicholas A. Kumbatovic, P.E.
Kevin M. McAndrew, RLA
Thomas W. Broderick, P.E.

Mr. Joseph Marino, Manager Facilities Engineering
Newsday
235 Pinelawn Road
Melville, NY 11747-4250

Re: March DMR
Nitrogen Exceedance
CE 761C

Dear Mr. Marino:

Cameron Engineering & Associates, LLP has reviewed the operating data for the Newsday Wastewater Treatment Plant and has noted the maximum nitrogen discharge concentration of 38 mg/l in the month of March. In discussions with the plant operations firm, Severn Trent Environmental Services, we are in agreement that a number of factors may have caused this exceedance.

Potential and most likely cause of the nitrogen exceedance is the recent start-up of the pilot BNR system (funded by NYSERDA) located in one of the aeration tanks. Coupled with extremely low wastewater temperatures, the start-up of the innovative technology was severely hampered. STES fed all wastewater for the first few weeks only into the aeration tank having diffused air. The aeration tank with the aerator was filled with raw sewage and put into "idle" status while awaiting growth of biomass. Once the biomass began to appear, forward flow was put into the Aerotor tank with the effluent from the tank directed back into the other aeration tank to ensure that no untreated waste left the system.

Under these operating conditions, the detention time in the diffused air aeration tank was reduced significantly and total nitrogen loading to that reactor was greater than the loading to the Aerotor reactor. This imbalance of loading is believed to have impacted the nitrification process. The downstream denitrification process in the deep bed filter was most likely impacted by the low temperatures as well.

At this time, the Aerotor has continued to advance biologically and is showing almost total nitrification. In the coming weeks, the system will be adjusted to determine its denitrification capabilities within the Aerotor reactor.

It would be advisable to attach this letter to the Non-Compliance Report and DMR for March as it would apprise the regulatory agencies of the current situation. We will continue to coordinate the pilot operations with STES and your office. The data being collected will be shared with the Suffolk County Department of Health Services as well.

Should you have any questions or require further information, please do not hesitate to contact our office.

Very truly yours,

Mark Wagner
Associate

MW/es

cc: Joseph Covati, STES

K:\C750-799\ce761c\Corres 2004\L-042604DMR.doc

New York State Department of Environmental Conservation

Division of Water

Report of Noncompliance Event

To: DEC Water Contact **Robert Schneck, RWE** DEC Region: **1**

Report Type ___ 5 Day **X** Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow ___ Other

SECTION 2

SPDES #: **NY 0136751** Facility: **Newsday**

Date of noncompliance: **3-31-04** Location (Outfall, Treatment Unit, or Pump Station):

Description of noncompliance(s) and cause(s): **Total nitrogen was exceeded with a reported value of 38 mg/L. Cold weather conditions inhibited the denitrification project. Also a full scale pilot project is being proven. All influent flow is being directed into one aeration basin, thus reducing the detention time by an order of magnitude**

Has event ceased? (Yes) (No) If so, when? ___ Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: / / , : (AM) (PM) End date, time of event: / / , : (AM) (PM)

Date, time oral notification made to DEC? / / , : (AM) (PM) DEC Official contacted:

Immediate corrective actions: **The pilot project is now nitrifying almost completely, thus reducing the impact upon the aeration basin.**

Preventive (long term) corrective actions: **The pilot project must be able to completely nitrify for the facility to meet total nitrogen. With warmer temperatures arriving, the nitrification process will be increased to effluent standards**

SECTION 3

Complete this section if event was a bypass:

Bypass amount: ___ Was prior DEC approval received for this event? (Yes) (No)

DEC Official contacted: ___ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: **Joseph M. Covati, Jr.** **TITLE:** **Area Manager** **DATE:** **2004-04-26**

Phone #: **(516) 674 - 6032** **FAX #:** **(516) 674 - 0151**

I Certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations

Joseph M. Covati Jr.

Signature of Principal Executive Officer or Authorize Agent

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747
tel: 631/843-2044
fax: 631/843-3444
joe.marino@newsday.com
Joseph Marino
Manager,
Facilities Engineering

April 26, 2004

New York State Department of Environmental Conservation
Division of Water
Bureau of Watershed Compliance Programs
625 Broadway 4th Floor
Albany, New York 12233-3506

SUBJECT: **SPDES #NY0136751**

To Bureau of Wastewater Facilities Operations:

Attached is the Discharge Monitoring Report for March 2004. See attached letter from Cameron Engineering and attached "Report of Noncompliance Event."



Sincerely,

Joseph Marino
Manager,
Facilities Engineering

CC: DEC - Stony Brook
SCDHS

Attachments: (1) Discharge Monitoring Report 3/04

File: DMR(2-04).doc

SECTION 1

New York State Department of Environmental Conservation
Division of Water

Report of Noncompliance Event

To: DEC Water Contact WILLIAM SPITZ **DEC Region:** 1

Report Type: ___ 5 Day X Permit Violation ___ Order Violation ___ Anticipated Noncompliance ___ Bypass/Overflow

SECTION 2

SPDES #: NY- 0136751 **Facility:** NEWSDAY, INC.

Date of noncompliance: JANUARY **Location (Outfall, Treatment Unit, or Pump Station):** OUTFALL

Description of noncompliance(s) and cause(s): DUE TO MISCOMMUNICATION WITH OUR CONTRACT OPERATOR, SEVERNTRENT, MONTHLY SAMPLES FOR JANUARY WERE NOT COLLECTED.

Has event ceased? (Yes) (No) **If so, when?** _____ **Was event due to plant upset?** (Yes) (No) **SPDES limits violated?** (Yes) (No)

Start date, time of event: ___/___/___, ___:___ (AM) (PM) **End date, time of event:** ___/___/___, ___:___ (AM) (PM)

Date, time oral notification made to DEC? ___/___/___, ___:___ (AM) (PM) **DEC Official contacted:** _____

Immediate corrective actions: WRITTEN VERBAL WARNING ISSUED TO CONTRACT OPERATOR.

Preventive (long term) corrective actions: CONTRACT OPERATOR REVIEWING SAMPLING PROCEDURES

SECTION 3

Complete this section if event was a bypass:

Bypass amount: _____ Was prior DEC authorization received for this event? (Yes) (No)

DEC Official contacted: _____ Date of DEC approval: ___/___/___

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: STEPHEN CLAFF, P.E. **Title:** SR. FACILITIES ENG. **Date:** 02/27/04

Phone #: (631) 843-3631 **Fax #:** (631) 843-3444

NYSDEC SPILL REPORT FORM

DEC REGION:	1	**SPILL NUMBER:**	0008603
SPILL NAME:	NEWSDAY	**DEC LEAD:**	NJACAMPO
SPILL DATE:	10/23/2000	**SPILL TIME:**	8:30 pm
CALL RECEIVED DATE:	10/23/2000	**RECEIVED TIME:**	9:39 pm

SPILL LOCATION

PLACE:	NEWSDAY	**COUNTY:**	Suffolk
STREET:	235 PINELAWN ROAD	**TOWN/CITY:**	Huntington
		COMMUNITY:	MELVILLE
CONTACT:	STEPHEN CLUFF	**CONTACT PHONE:**	(631) 843-3631

CONT. FACTOR:	Unknown	**SPILL REPORTED BY:**	Responsible Party
FACILITY TYPE:	Commercial/Industrial	**WATERBODY:**	

CALLER REMARKS:

spill of 100-200 gal of disel occ at the main building - spill to blacktop and a storm drain is also effected - unk cause at this time, still being investigated. Security noticed the oil coming from a vent pipe - clean up contractor fenley & nicol has been paged

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	1,600 G	0 G	Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE NY	STEPHEN CLUFF (631) 843-3631

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ACAMPORA"
10/24/00 STEVE CLUFF (NEWSDAY) CALLED, ACTUALLY 1000-1500 GAL SPILL, TRYING TO DETERMINE EXACT AMT ESI ON SITE, VACCING DRAIN

PIN	T & A	COST CENTER

CLASS: B3 **CLOSE DATE:** 12/14/2000 **MEETS STANDARDS:** True

Created On: 10/23/2000
Date Printed: 8/7/2018 Last Updated: 12/27/2011

10/24 0840 Joe Parisi (EST) called

- has already taken a full 5000gal tanker to disposal facility
  - 3000gal was product
- beginning to clean out bottom of drain
- Newsday has 2 25k tanks
  - both were "full"
  - tanks were serviced, due to too much pressure in one line
    - suspects serviceman may have turned off valve returning unused product to tank being used, causing oil to enter full tank & spray out vent

10/24 0845 Spoke to Bruce
- ETA before 11

10/24 0845 updated Joe

00-08603
TWLP #117
PHOTOS BY
STEVE CLUFF/NEWSDAY.













NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☒ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 00-08603

Location	Representatives on site	time in	time out
Name NEWSDAY BLDG.	DEC DCAMPORA		
Address PINELAWN ROAD			
Town MELVILLE			



00-08603
10/24/00
(1)



00-08603
10/24/00
(2)



00-08603
10/24/00.
(3)

Continued Page ____ Of ____

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747-4250
tel: 631/843-3631
fax: 631/843-3444
beeper: 516/657-7012
stephen.cluff@newsday.com

Stephen Cluff
Environmental Engineer

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747-4250
tel: 631/843-2044
fax: 631/843-3444
beeper: 631/554-0340
joe.marino@newsday.com

Joseph Marino
Manager
Facilities Engineering &
Maintenance

Steve Cluff

pager 5166577012

Joe Parisi

cell 5168054686

New York State Department of Environmental Conservation
Building 40 - SUNY, Stony Brook, New York 11790-2356

TEL # (516) 444-0320
FAX # (516) 444-0373

REQUEST FOR CLEANUP NOTIFICATION FORM - FIELD ISSUE

Date OCT. 24, 2000

✓ **IMMEDIATE CLEANUP REQUIRED**

___ **WITHIN 10-DAY PERIOD (Unless otherwise specified, the 10-day period will begin with the above date.)**

SPILL #: 00-08603 **SPILL LOCATION:** NEWSDAY BLDG./MELVILLE

RESPONSIBLE PARTY INFORMATION:

Address: NEWSDAY/235 PINELAWN ROAD/MELVILLE, NY 11747-4250

Telephone: 631-843-3631

Contact Person(s): STEPHEN CLUFF

FINDINGS: OVERFILL OF 1X25,000 TANK DUE TO HUMAN ERROR CAUSING PRODUCT TO ENTER ON SITE DRAINAGE.

WORK TO BE PERFORMED: REMOVE ALL FREE PRODUCT; REMOVE CONTAMINATED SEDIMENT FROM DRAINS LB-31; SD-01; TWLB-116, TWLB-117 & CB 114 - POST EXCAVATION SOIL SAMPLING MUST BE COMPLETED FOR ALL DRAINS & TWLB #115. UTILIZING 8021 & 8270 TOTALS. PROVIDE DISPOSAL RECEIPTS FOR ALL.

This letter serves as notice that the Department is directing you or your company to proceed with a cleanup of the above-referenced site within the time frame indicated. You may either hire a contractor or do the work yourself. However, you must use a contractor with a 364 Transporter Permit to transport the contaminated material to a proper disposal facility.

If you do not proceed with the required cleanup within the time frame noted above, this office will proceed with the cleanup of the site, and the New York State Department of Law will seek reimbursement along with an assessment of penalties from you in accordance with Article 12 of the New York State Navigation Law.

Stephen Cluff — Responsible Party/Agent — 10/24/00 — Date — (Signature acknowledges receipt only)

Scott Rosenbusch — Spill Response Investigator — 10/24/00. — Date — (Original to RP, Copy to DEC)

(CNF rev 10/96)

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☒ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 00 08603

Location	Representatives on site	time in	time out
Name NEWSDAY BLDG.	DEC ACAMPORA	0959	1145
Address 235 PINELAWN ROAD	STEPHEN CLUFF/NEWSDAY		
Town MELVILLE, NY 11747-4250	JOSEPH MARINO/NEWSDAY		
Phone 631-843-3631	VIC PARISI/ ESI		
	PRP		

Weather	Temperature	General conditions
humidity	Cold	Sunny
~~Dry~~	~~Rain~~	~~Partly Cloudy~~
Humid	~~Warm~~	Cloudy
Very humid	Hot	Rain / Snow

Date	Time	Inspection Narrative

10/24/00 0959 - ACAMPORA ON SITE
- MET W/ THE ABOVE REFERENCED REPS.
- CLEANUP IN PROGRESS UPON ARRIVAL
- RELEASE RESTRICTED TO NEWSDAY PROPERTY
- RELEASE OCCURRED DUE TO FOLLOWING (AS PER MR. CLUFF)
- ON 10/23/00 REPAIR CONTRACTOR WAS ON SITE ATTEMPTING TO DETERMINE CAUSE OF FAULTY EQUIPMENT INCLUDING AUTOMATIC VALVING & TANK GAUGES. - DURING THIS WORK AN EMPLOYEE OF THE REPAIR CONTRACTOR OPENED MANUAL VALVE ON RETURN LINE FOR NORTH TANK. THERE ARE 2 x 25,000 DIESEL TANK DESIGNATED AS NORTH & SOUTH.
- BOTH TANKS HAD BEEN "TOPPED" OFF LAST FRIDAY. HOWEVER, WHEN THE BOILER WENT ON-LINE, PRODUCT WAS RETURNED TO TANK (NORTH) CAUSING AN OVERFILL CONDITION. PRODUCT CAME OUT VENT LINE & FLOWED ON SURFACE OF PARKING LOT & IMPACTED SEVERAL DRAINAGE BASINS.
ROUTINE SECURITY CHECK BY SECURITY GROUP NOTICED SPILL & REPORTED SAME TO NEWSDAY'S

Continued ✓ ON BACK → Page ____ Of ____

Contractor's Equipment	Contractor's Work Force	time in	time out

Site Sketch (Include North Arrow)

10/24/00
CW.T

- MAINT. CREW WHO DIEN RESPONDED & HIRED E.S.I. TO CLEAN UP.
- SPILL OCCURRED APPROX. 2000 pm ~~[illegible]~~ 10/23/00. - NEWSDAY IS INVESTIGATING

- INSPECTED DRAINAGE SYSTEM.
- SEVERAL DRAINS IMPACTED. - SEE ATTACHED MAP FOR LOCATIONS + DESIGNATIONS.

- MAJORITY OF PRODUCT ENTERED DRAIN LB #114 ALL LIQUID REMOVED PRIOR TO MY ARRIVAL. STRONG ODOR EVIDENT IN SEDIMENTS
- ALL WATER BASINS HAVE CONTAMINATED SEDIMENT
- TWLB #117 HAS WATER W/ FLOATING PRODUCT. E.S.I. TO REMOVE PRODUCT & DISPLAY PROS.

- REQUIRED ALL BOTTOM SEDIMENT BE SAMPLED AFTER REMOVAL OF CONTAMINATION TO EXTENTS POSSIBLE. 8021+8270 TOTALS.

- ISSUED "FIELD CLEAN-UP LETTER".
- SEE MAP FOR LOCATIONS.

- CLEAN-UP TO CONTINUE.
- WILL MAKE FOLLOW-UP INSPECTION ON 10/25/00

11:45 - LEFT SITE.

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☒ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 00-08603

Location	Representatives on site	time in	time out
Name NEWSDAY BLDG.	DEC ACAMPORA	1416	1505
Address 235 PINELAWN ROAD	STEVE CLUFF/NEWSDAY		
Town MELVILLE	E.S.I. CREW.		
Phone	TOWN OF HUNTINGTON F.M. OFFICE		
	PRP		

Weather	Temperature	General conditions
humidity	Cold	Sunny
Dry	Fair	Partly Cloudy
Humid	Warm	Cloudy
Very humid	Hot	Rain / Snow

Date	Time	Inspection Narrative
10/25/00	14:16	- ACAMPORA ON SITE:
		- MET W/ ABOVE REFERENCED REPS.
		- CLEAN-UP STILL IN PROGRESS.
		- DRAIN CB-114 HAS BEEN CLEANED TO EXTENT PRACTICAL.
		SOIL REMOVED AT LEAST FIVE FEET BELOW BOTTOM
		PRECAST RING. TOTAL DEPTH APPROX 30' B.L.S.
		- ANY ADD'L SOIL REMOVAL WITHIN TIME MAY
		CAUSE RINGS TO COLLAPSE.
		- BOTTOM SOIL SAMPLE IS REQ'D.
		- DEPLOYED BARS IN TWLB 117
		- CREWS TO BEGIN ON LB-31
		- ADVISED ITEM AGAIN THAT BOTTOM SAMPLES WILL
		BE REQ'D. FAST TURNAROUND DUE TO FORCASTED
		RAIN EVENT THIS WEEKEND.
		- SURFACE SPILLAGE CLEANED UP STAIN REMAINS IN
		ASPHALT.
		- CAUSE OF INCIDENT: ADD'L INFO.:
		BOILER WAS DRAWING PRODUCT FROM SOUTH TANK BUT
		DUE TO HUMAN ERROR, PRODUCT WAS DIRECTED THRU
		NORTH TANK RETURN LINE, AS RESULT NORTH TANK
		WAS OVERFILLED.
		- ALSO CHECKED MANWAY ACCESS FOR NORTH TANK. →

Continued ✓ Page ____ Of ____
ON BACK

Contractor's Equipment	Contractor's Work Force	time in	time out

Site Sketch (Include North Arrow)

10/25/00 -
(Cont'd)
- SOIL CONTAMINATION NOTED IN THIS AREA AS WELL.
- WILL REQUIRE SOIL REMOVAL.
1505 - LEFT SITE.

10/30/00 -
0926 - ACAMPORA HAD TELECON W/ STEVE CLUFF @ KLEINFELDER.
- CLEAN UP APPEARS COMPLETE. AWAITING SAMPLE RESULTS.
-

CERTIFIED METER READING BEFORE AND AFTER DELIVERY

0 2 7 2 3 2 9 . A 3 9 6

NY0003795-

RAD ENERGY CORP. US EPA # 3039

287 Bowman Avenue, Purchase, NY 10577-2540
(914) 701-2700 (516) 622-7000

☐ GASOLINE 3 UN 1203 PGII/MIN OCTANE (R & M) / 2

(87) ☐ UNLEADED	(89) ☐ MID UNLEADED	(91) ☐ SUPER UNLEADED
(92) ☐ SUPER UNLEADED	(93) ☐ SUPER UNLEADED	☐ OTHER
☐ DIESEL FUEL NO. 1	3 NA 1993 PGIII	
☐ DIESEL FUEL NO. 2	3 NA 1993 PGIII	
☐ FUEL OIL NO. 2	3 NA 1993 PGIII	
☐ KEROSENE	3 UN 1223 PGIII	
☐ AV JET A	3 UN 1863 PGIII	☐ OTHER

THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION.

SOLD TO NEWSDAY INC.

ADDRESS 235 PINELAWN ROAD

CITY, STATE, ZIP MELVILLE NY

DELIVERY DATE	DELIVERY TIME	TICKET NUMBER
10-18-00	1100 AM/PM	016946
PURCHASE ORDER NUMBER	PRODUCT CODE	ORDERED AMOUNT
	H-2	1000
BOL / MANIFEST NUMBER 3870 99888933R		DELIVERED AMOUNT 824
PAYMENT AMOUNT	CHECK NUMBER	

TRANSPORTER NAME METCALF TRANSPORT CORP TRUCK NUMBER

ADDRESS DRIVER EDDIE

2/9208

CUSTOMER SIGNATURE
X Kendall Lousart

SIGNING THIS INVOICE BY CUSTOMER OR CUSTOMER'S REPRESENTATIVE MEANS SIGNER PERSONALLY GUARANTEES PAYMENT AND CUSTOMER HAS READ AND AGREES TO TERMS AND CONDITIONS OF SECURITY AGREEMENT ON REVERSE SIDE.

☐ DYED DIESEL FUEL IS FOR NONTAXABLE USE ONLY, PENALTY FOR TAXABLE USE.

THIS DIESEL FUEL MEETS THE REQUIREMENTS OF 40CFR 80.29 AND IS SUITABLE FOR USE BY *ON-HIGHWAY VEHICLES*.
MIN CETANE: 40, MAX. MAX. CLOUD: 15 DEGREES F°

THE GRADE OF GASOLINE INDICATED ABOVE IS ONE OF THE FOLLOWING AS NOTED BY THE BOXES CHECKED.

☐ CONVENTIONAL
☐ OXYGENATED
} THIS PRODUCT DOES NOT MEET THE REQUIREMENTS FOR REFORMULATED GASOLINE AND MAY NOT BE USED IN ANY REFORMULATED GASOLINE COVERED AREA.

☐ REFORMULATED GASOLINE - CERTIFIED UNDER SIMPLE MODEL STANDARDS
BENZENE CONTENT 1.3 VOLUME PERCENT MAXIMUM. CONTAINS MTBE

☐ OPRG OXYGENATED FUELS PROGRAM REFORMULATED GASOLINE
NOT VOC CONTROLLED. N.Y.S. 2.7% - 2.9%
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
3.5% PER GALLON MAXIMUM
☐ NOPRG NOT OXYGENATED FUELS PROGRAM REFORMULATED GASOLINE,
NOT VOC CONTROLLED
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
3.5% PER GALLON MAXIMUM,
☐ RFG VOC-CONTROLLED REGION 2 U.S.E.P.A.
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
2.7% PER GALLON MAXIMUM,
RVP (PSI PER GAL) 8.3 MAXIMUM

MAXIMUM RVP PSI PER GALLON PER N.Y.S.
MAY 1 TO SEPT. 15 – 9.0 SEPT. 16 TO OCTOBER 31 – 13.5
NOV. 1 TO MARCH 31 – 15.0 APRIL 1 TO APRIL 30 – 13.5
DETERGENT ADDITIZED GASOLINE

CERTIFIED METER READING BEFORE AND AFTER DELIVERY

0 2 7 2 3 3 0 . A 3 9 6

NY0003795-

RAD ENERGY CORP. US EPA # 303

287 Bowman Avenue, Purchase, NY 10577-2540
(914) 701-2700 (516) 622-7000

☐ GASOLINE 3 UN 1203 PGII/MIN OCTANE (R & M) / 2

(87) ☐ UNLEADED (89) ☐ MID UNLEADED (91) ☐ SUPER UNLEADED
(92) ☐ SUPER UNLEADED (93) ☐ SUPER UNLEADED ☐ OTHER
☐ DIESEL FUEL NO. 1 3 NA 1993 PGIII
☐ DIESEL FUEL NO. 2 3 NA 1993 PGIII
☐ FUEL OIL NO. 2 3 NA 1993 PGIII
☐ KEROSENE 3 UN 1223 PGIII
☐ AV JET A 3 UN 1863 PGIII ☐ OTHER

THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION.

SOLD TO NEWSDAY INC.

ADDRESS 235 PINELAWN ROAD

CITY, STATE, ZIP MELVILLE NY

DELIVERY DATE 10-18-00 | DELIVERY TIME 1130 AM/PM | TICKET NUMBER 016945
PURCHASE ORDER NUMBER | PRODUCT CODE H-2 | ORDERED AMOUNT 8400
BOL / MANIFEST NUMBER 3870 99888933R | DELIVERED AMOUNT 8006
PAYMENT AMOUNT | CHECK NUMBER

TRANSPORTER NAME METCALF TRANSPORT CORP TRUCK NUMBER

ADDRESS DRIVER EDDIE

2/9208

CUSTOMER SIGNATURE
X Kendall Lousart

SIGNING THIS INVOICE BY CUSTOMER OR CUSTOMER'S REPRESENTATIVE MEANS SIGNER PERSONALLY GUARANTEES PAYMENT AND CUSTOMER HAS READ AND AGREES TO TERMS AND CONDITIONS OF SECURITY AGREEMENT ON REVERSE SIDE.

☐ DYED DIESEL FUEL IS FOR NONTAXABLE USE ONLY, PENALTY FOR TAXABLE USE.

THIS DIESEL FUEL MEETS THE REQUIREMENTS OF 40CFR 80.29 AND IS SUITABLE FOR USE BY *ON-HIGHWAY VEHICLES*.
MIN CETANE: 40, MAX. MAX. CLOUD: 15 DEGREES F°

THE GRADE OF GASOLINE INDICATED ABOVE IS ONE OF THE FOLLOWING AS NOTED BY THE BOXES CHECKED.

☐ CONVENTIONAL
☐ OXYGENATED
} THIS PRODUCT DOES NOT MEET THE REQUIREMENTS FOR REFORMULATED GASOLINE AND MAY NOT BE USED IN ANY REFORMULATED GASOLINE COVERED AREA.

☐ REFORMULATED GASOLINE - CERTIFIED UNDER SIMPLE MODEL STANDARDS
BENZENE CONTENT 1.3 VOLUME PERCENT MAXIMUM. CONTAINS MTBE

☐ OPRG OXYGENATED FUELS PROGRAM REFORMULATED GASOLINE
NOT VOC CONTROLLED. N.Y.S. 2.7% - 2.9%
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
3.5% PER GALLON MAXIMUM
☐ NOPRG NOT OXYGENATED FUELS PROGRAM REFORMULATED GASOLINE,
NOT VOC CONTROLLED
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
3.5% PER GALLON MAXIMUM,
☐ RFG VOC-CONTROLLED REGION 2 U.S.E.P.A.
OXYGEN WEIGHT 1.5% PER GALLON MINIMUM
2.7% PER GALLON MAXIMUM,
RVP (PSI PER GAL) 8.3 MAXIMUM

MAXIMUM RVP PSI PER GALLON PER N.Y.S.
MAY 1 TO SEPT. 15 – 9.0 SEPT. 16 TO OCTOBER 31 – 13.5
NOV. 1 TO MARCH 31 – 15.0 APRIL 1 TO APRIL 30 – 13.5
DETERGENT ADDITIZED GASOLINE

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☒ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 00 08603

Location	Representatives on site	time in	time out
Name NEWSDAY BLDG.	DEC RAMPOAD	0959	1145
Address PINELAWN RD.	SEE PAGE 1		
Town MELVILLE			
Phone			
	PRP		

Weather	Temperature	General conditions
humidity	Cold	Sunny
Dry	Fair	Partly Cloudy
Humid	Warm	Cloudy
Very humid	Hot	Rain / Snow

Date	Time	Inspection Narrative
10/24/00 (CONT'D)		INFO. SHEET
		- LAST DELIVERY TO TANKS : 10/18/00
		TANKS "TOPPED-OFF".
		- TANK LEVELS CHECKED THIS MORNING.
		NORTH TANK: 25,000. ALARM SYSTEM ACTIVATED.
		SOUTH TANK: 23,350
		- ASSUMING BOTH TANKS FILLED = 50,000.
		TOTAL AMT. IN TANKS = 48,350
		TOTAL AMT. LOST = 1650 W
		- E.S.I. HAD ONE TANKER OFF SITE: 5500 GALLONS.
		27% OIL - 1650 OIL. W RECOVERED.
		70% WATER - 3850 GALLONS
		3% SOLIDS
		- ALL AMTS. ESTIMATES.

Continued Page ____ Of ____

Newsday
Engineering Services
235 Pinelawn Road
Melville, NY 11747-4250
FAX (631)-843-3444

facsimile transmittal

To: DEC/Nick Acampora Fax: 631-444-0373

From: Stephen Cluff Date: October 31, 2000

Re: Spill # 00-08603 End Point Sample Pages: 11

Analysis

CC:

Urgent For Review X Please Comment Please Reply Please Recycle

Mr. Acampora,

I am faxing you EPA 8021 and 8270 analysis completed for endpoint samples after evacuating contaminated pools CB#114, TWLB#115, TWLB#116 and TWLB#117 "DRY WELL W/PUMP" and LB-31; note, SD-01 is a dry well that was completely evacuated leaving no contaminated soil remaining. I will be out Wednesday, November 1, 2000. Should you need to get a hold of someone to visit the site, please contact Timothy McGarry at 843-2036; otherwise, I will be back on Thursday to go over the analysis and clean-up.

Regards,

Stephen Cluff
Environmental Engineer

(631)-843-3631

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100436 SAMPLE ID#: 00100435-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : CB114 END POINT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00 7:38:35 PM	10/26/00	10/26/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	34	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100435 SAMPLE ID#: 00100435-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : CB114 END POINT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00 7:38:35 PM	10/26/00	10/26/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<5.0	µg/kg
Anthracene	<5.0	µg/kg
Benzo(a)anthracene	<5.0	µg/kg
Benzo(a)pyrene	<5.0	µg/kg
Benzo(b)fluoranthene	<5.0	µg/kg
Benzo(g,h,i)perylene	<5.0	µg/kg
Benzo(k)fluoranthene	<5.0	µg/kg
Chrysene	<5.0	µg/kg
Dibenzo(a,h)anthracene	<5.0	µg/kg
Fluoranthene	<5.0	µg/kg
Fluorene	<5.0	µg/kg
Indeno(1,2,3-cd)pyrene	<5.0	µg/kg
Napnthalene	<5.0	µg/kg
Phenanthrene	<5.0	µg/kg
Pyrene	<5.0	µg/kg
	<5.0	µg/kg

John Pedneault
Lab Director

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:	*PEDNEAULT ASSOCIATES, INC.*
ENVIRONMENTAL SERVICES	*1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716*
133 COMMACK ROAD	LAB#: 00100474 SAMPLE ID#: 00100474-001
MASTIC BEACH , NY 11951-0000	PROJECT ID : NEWSDAY
(516)587-8282	SAMPLE ORIGIN : TWLB 115
	MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE. BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA N.Y. 11716
LAB#: 00100474 SAMPLE ID#: 00100474-001
PROJECT ID: NEWSDAY
SAMPLE ORIGIN: TWLB 115
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

10-30-2000 3 14PM FROM PEDNEAULT TEST LABS 516 467 6905 P.1

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:	PEDNEAULT ASSOCIATES, INC.
ENVIRONMENTAL SERVICES	1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
133 COMMACK ROAD	LAB#: 00100474 SAMPLE ID#: 00100474-002
MASTIC BEACH , NY 11951-0000	PROJECT ID : NEWSDAY
(516)587-8282	SAMPLE ORIGIN : TWLB 116
	MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS — METHOD: EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100474 SAMPLE ID#: 00100474-002
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : TWLB 116
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

P.2
10-30-2000 3:14PM FROM PEDNEAULT TEST LABS 516 467 6905

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905
AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100477 SAMPLE ID#: 00100477-001
PROJECT ID: NEWSDAY
SAMPLE ORIGIN: DRY WELL W/PUMP
MATRIX: NON-POTABLE WATER

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/27/00	10/27/00 5:09:06 PM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8021

PARAMETER	RESULT	UNITS
Benzene	<1.0	µg/L
n-Butylbenzene	<1.0	µg/L
sec-Butylbenzene	<1.0	µg/L
tert-Butylbenzene	<1.0	µg/L
Ethylbenzene	<1.0	µg/L
Isopropylbenzene	<1.0	µg/L
p-Isopropyltoluene	<1.0	µg/L
Methyl-tert-butyl ether	20	µg/L
Napthalene	<1.0	µg/L
n-Propylbenzene	<1.0	µg/L
Toluene	<1.0	µg/L
1,2,4-Trimethylbenzene	5.5	µg/L
1,3,5-Trimethylbenzene	<1.0	µg/L
o-Xylene	<1.0	µg/L
m,p-Xylene	<1.0	µg/L
Mix Xylenes	<1.0	µg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100477 SAMPLE ID#: 00100477-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : DRY WELL W/PUMP
MATRIX: NON-POTABLE WATER

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/27/00	10/27/00 5:09:06 PM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<1.0	µg/L
Anthracene	<1.0	µg/L
Benzo(a)anthracene	<1.0	µg/L
Benzo(a)pyrene	<1.0	µg/L
Benzo(b)fluoranthene	<1.0	µg/L
Benzo(g,h,i)perylene	<1.0	µg/L
Benzo(k)fluoranthene	<1.0	µg/L
Chrysene	<1.0	µg/L
Dibenzo(a,h)anthracene	<1.0	µg/L
Fluoranthene	1.1	µg/L
Fluorene	<1.0	µg/L
Indeno(1,2,3-cd)pyrene	2.4	µg/L
Naphthalene	1.1	µg/L
Phenanthrene	<1.0	µg/L
Pyrene		

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100474 **SAMPLE ID#:** 00100474-003
PROJECT ID: NEWSDAY
SAMPLE ORIGIN: LB-31
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

FILE No.475 10/31 '00 PM 01:03 ID:ENVIRONMENTAL SERVICES FAX:631 595 9695

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH . NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 00100474 SAMPLE ID#: 00100474-003
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : LB-31
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS METHOD: EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

New York State Department of Environmental Conservation
Building 40 - SUNY, Stony Brook, New York 11790-2356

COVER SHEET

FAX

To: Mr. Steve Cluff, Environmental Engineer, Newsday
Fax #: (631) 843-3444
Re: Spill #00-08603, Newsday Building, Melville.
Date: 1, November, 2000
Pages: 1 of 1

COMMENTS:

This office is in receipt of the end point sample results for the clean-up at the above referenced site. Based on review of the, this office has the following comments:

1. Was all floating product and water removed from TWLB #117 prior to sampling? If this was the case, was any bottom sediment removed as well?

2. Was the contaminated soil in the man way access for the north tank removed. If so, was the work completed and/or was it sampled?

3. Approximately how much soil was removed for disposal?

If you have any questions or comments regarding this matter, please call me at the number listed below.

Nick Acampora
NYSDEC
(631) 444-0322 Voice
(631) 444-0373 Fax

000803
NEWSDAY BLDG
MELVILLE

11/8/00 -
0845 - REDMOND HAD TELECON W/ STEVE @ NEWSDAY.
- CLEAN-UP COMPLETED, WITH EXCEPTION OF TRUCK MANWAY.
- DID NOT TAKE SOIL OR SW SAMPLE FROM TANK #117. - REMOVED FLOATING PRODUCT & DEPLOYED PADS. TOOK WATER SAMPLE.
- APPROX 60 YARDS SOIL REMOVED.
- WILL CONTACT ME WHEN READY FOR RE-INSPECTION.

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of 1
Exempt	11.03.00	

GENERATOR

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd, Melville NY

4. Generator's Phone ( )

5. Transporter 1 Company Name: Environmental Services Inc
6. US EPA ID Number:
A. Transporter's Phone: (631) 395-9888

7. Transporter 2 Company Name:
8. US EPA ID Number:
B. Transporter's Phone:

9. Designated Facility Name and Site Address
Bluewater Environmental
1610 New Highway
Farmingdale NY
10. US EPA ID Number:
C. Facility's Phone: (631) 395-9888

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. N816 Contaminated Soil	001	TK	19.43	TNS
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
PBA 00342

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Emergencies Call ESI (631) 395-9888
or
Chemtrec (800) 424-9300

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Frank Abbate Agent for Newsday
Signature:
Month Day Year: 11/03/00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Frank Abbate
Signature:
Month Day Year: 11/03/00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space
Meets EPA Regs For Non-Haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: M. Reynolds
Signature: M. Reynolds
Month Day Year: 11/03/00

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: Exempt
Manifest Doc. No.: 11380
2. Page 1 of 1

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd, Melville NY

4. Generator's Phone ( )

5. Transporter 1 Company Name: Environmental Services Inc
6. US EPA ID Number:
A. Transporter's Phone: (631) 395-9888

7. Transporter 2 Company Name
8. US EPA ID Number:
B. Transporter's Phone:

9. Designated Facility Name and Site Address
Bluewater Environmental
1610 New Highway
Farmingdale NY
10. US EPA ID Number:
C. Facility's Phone: (631) 752-2145

GENERATOR

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. N816 Contaminatated Soil	001	TK	21.53	TNS
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
PBA 00342

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Emergencies Call ESI (631) 395-9888
or
Chemtrec (800) 424-9300

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Frank Abbruzzese Agent for Newsday
Signature: Frank Abbruzzese
Month Day Year: 11 03 00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Frank Abbruzzese
Signature: Frank Abbruzzese
Month Day Year: 11 03

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space
Meets EPA Regs For Non-Haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: M. Reynolds
Signature: M. Reynolds
Month Day Year: 11 03 00

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: Exempt
Manifest Doc. No.: 10300
2. Page 1 of 1

GENERATOR

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd Melville NY
4. Generator's Phone ( )

5. Transporter 1 Company Name: Environmental Services Inc
6. US EPA ID Number:
A. Transporter's Phone: (631) 395-9888

7. Transporter 2 Company Name:
8. US EPA ID Number:
B. Transporter's Phone:

9. Designated Facility Name and Site Address
Bluewater Environmental
1610 New Highway
Farmingdale NY
10. US EPA ID Number:
C. Facility's Phone: (631) 752-2145

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. N816 Contaminated Soil	001	TK	30.77	TNS
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
PBA 00342

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Emergencies Call: ESI (631) 395-9888
or
Chemtrec (800) 424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Frank Abbruzzese Agent for Newsday
Signature:
Month Day Year: 11 03 00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Frank Abbruzzese
Signature:
Month Day Year: 11 03 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space
Meets EPA Regs For Non-Haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: M. Reynolds
Signature:
Month Day Year: 11 03 00

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of
EXEMPT	1024.00	

GENERATOR

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd. Melville, N.Y.

4. Generator's Phone ( )

5. Transporter 1 Company Name	6. US EPA ID Number	A. Transporter's Phone
Environmental Services Inc.	EXEMPT	(631) 395-9888
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter's Phone

9. Designated Facility Name and Site Address	10. US EPA ID Number	C. Facility's Phone
Clean Water of New York 3249 Richmond Terrace Staten Island, N.Y.		(718) 981-4600

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. NO18 - Oily Water Mixture			5500	Gal
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
N.Y. S.D.E.C. #

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Spills Please Call E.S.I at (631) 395-9888
or Chemtrec at 1-800 424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name	Signature	Month	Day	Year
Stephen Cluff		10	24	00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Scott Sindt		10	24	00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
D. Kaminski		10	24	00

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: Exempt
Manifest Doc. No.: 102700
2. Page 1 of 1

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd, Melville NY

4. Generator's Phone ( )

5. Transporter 1 Company Name
Environmental Services Inc

6. US EPA ID Number

A. Transporter's Phone (631) 395-9888

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
Clean Water of New York
3249 Richmond Terrace
Staten Island NY

10. US EPA ID Number

C. Facility's Phone (718) 981-4600

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. N018 Oil/Water Mixtures	001	TK	2750	G
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Emergenicies Call: ESI (631) 395-9888
or
Chemtrec (800) 424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Joseph Parisi Agent For Newsday
Signature:
Month Day Year: 10 27 00

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Kenneth Enright
Signature:
Month Day Year: 10 25 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space
Meets EPA Regs For Non-haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Month Day Year: 10 27 00

GENERATOR
TRANSPORTER
FACILITY

ORIGINAL – RETURN TO GENERATOR

SAMPLE COLLECTION / CHAIN OF CUSTODY RECORD

Pedneault Associates, Inc.
1615 NINTH AVENUE
BOHEMIA, NEW YORK 11716
PHONE: (631) 467-0477 / FAX: (631) 467-0666

CLIENT: ENVIRONMENTAL SERVICES INC.
ADDRESS: 133 COMMACK RD
CITY, STATE, ZIP: MASTIC BEACH NY 11951
PHONE / FAX: (631) 395-9888 – (631) 395-9893

PAGE 1 OF 1
P.O. #:
JOB #:

PROJECT NAME AND/OR LOCATION: NEWSDAY - DISPOSAL

LAB NUMBER: 00100404

#	DATE	TIME	SAMPLE: COMP	SAMPLE: GRAB	MATRIX: S	MATRIX: L	MATRIX: G	SAMPLE ORIGIN	SAMPLE CONTAINERS	ANALYSIS	#
1	10/25/00	10:15 AM	X		X			Roll-off	(1)	R3 / BLUEWATER	1
2											2
3											3
4											4
5											5
6											6
7											7
8											8
9											9
10									change to	24 HR	10

48 HR. T.A.T.

SAMPLED BY: DAVID PARISI
RELINQUISHED BY: [signature]
DATE: 10/26 TIME: 10:30 AM

SPECIAL INSTRUCTIONS: 48 HOUR TAT
RECEIVED BY:
DATE: TIME:

RECEIVED AT LAB BY: K. Bustin
DATE: 10/25/00 TIME: 11:05

REMARKS:

SHIPPING CONTAINER CONDITION | PACKED IN ICE?

PAGE 1
FILE NO. 4020 W HI AV-CO AV-ENVIRONMENTAL SERVICES PHX:631 395 9893

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

LAB#: 00100404 **SAMPLE ID#:** 00100404-001

PROJECT ID : NEWSDAY DISPOSAL

SAMPLE ORIGIN : ROLL-OFF

MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00	10/27/00	10/27/00

PARAMETER	METHOD	RESULT	UNITS
Arsenic (As)	SW-846 3050/6010	0.87	mg/Kg
Barium (Ba)	SW-846 3050/6010	6.23	mg/Kg
Cadmium (Cd)	SW-846 3050/6010	0.42	mg/Kg
Chromium (Cr)	SW-846 3050/6010	2.13	mg/Kg
Copper (Cu)	SW-846 3050/6010	3.50	mg/Kg
Lead (Pb)	SW-846 3050/6010	4.10	mg/Kg
Nickel (Ni)	SW-846 3050/6010	1.21	mg/Kg
Selenium (Se)	SW-846 3050/6010	<0.01	mg/Kg
Silver (Ag)	SW-846 3050/6010	3.04	mg/Kg
Zinc (Zn)	SW-846 3050/6010	21.2	mg/Kg
Mercury (Hg)	EPA 245.5	0.01	mg/Kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100404 **SAMPLE ID#:** 00100404-001
PROJECT ID : NEWSDAY DISPOSAL
SAMPLE ORIGIN : ROLL-OFF
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00 11:25:36 AM	10/27/00	10/27/00

TEST: SEMI-VOLATILE EXTRACTABLE ORGANIC **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<5.0	µg/kg
Acenaphthylene	<5.0	µg/kg
Anthracene	<5.0	µg/kg
Benzidine	<5.0	µg/kg
Benzo(a)anthracene	12	µg/kg
Benzo(b)fluoranthene	<5.0	µg/kg
Benzo(k)fluoranthene	<5.0	µg/kg
Benzo(a)pyrene	<5.0	µg/kg
Benzo(g,h,i)perylene	<5.0	µg/kg
Butylbenzylphthalate	<5.0	µg/kg
Bis(2-chloroethyl)ether	<5.0	µg/kg
Bis(2-chloroethoxy)methane	<5.0	µg/kg
Bis(2-ethylhexyl) phthalate	<5.0	µg/kg
Bis (2-chloroisopropyl) ether	<5.0	µg/kg
4-Bromophenyl phenyl ether	<5.0	µg/kg
2-Chloronaphthalene	<5.0	µg/kg
4-Chlorophenyl phenyl ether	<5.0	µg/kg
Chrysene	<5.0	µg/kg
Dibenzo(a,h)anthracene	<5.0	µg/kg
Di-n-butylphthalate	<5.0	µg/kg
1,3-Dichlorobenzene	<5.0	µg/kg
1,2-Dichlorobenzene	<5.0	µg/kg
1,4-Dichlorobenzene	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100404 **SAMPLE ID#:** 00100404-001
PROJECT ID : NEWSDAY DISPOSAL
SAMPLE ORIGIN : ROLL-OFF
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00 11:25:36 AM	10/27/00	10/27/00

TEST: SEMI-VOLATILE EXTRACTABLE ORGANIC **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
3,3'-Dichlorobenzidine	<5.0	µg/kg
Diethylphthalate	<5.0	µg/kg
Dimethylphthalate	<5.0	µg/kg
2,4-Dinitrotoluene	<5.0	µg/kg
2,6-Dinitrotoluene	<5.0	µg/kg
Di-n-octylphthalate	<5.0	µg/kg
Fluoranthene	14	µg/kg
Fluorene	<5.0	µg/kg
Hexachlorobenzene	<5.0	µg/kg
Hexachlorobutadiene	<5.0	µg/kg
Hexachlorocyclopentadiene	<5.0	µg/kg
Hexachloroethane	<5.0	µg/kg
Indeno(1,2,3-cd)pyrene	<5.0	µg/kg
Isophorone	<5.0	µg/kg
n-Nitrosodimethylamine	<5.0	µg/kg
n-Nitrosodiphenylamine	<5.0	µg/kg
n-Nitrosodi-N-propylamine	<5.0	µg/kg
Phenanthrene	11	µg/kg
Pyrene	11	µg/kg
1,2,4-Trichlorobenzene	<5.0	µg/kg
Naphthalene	6.0	µg/kg
Nitrobenzene	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

LAB#: 00100404 **SAMPLE ID#:** 00100404-001

PROJECT ID : NEWSDAY DISPOSAL

SAMPLE ORIGIN : ROLL-OFF

MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00	10/27/00	10/27/00

PARAMETER	METHOD	RESULT	UNITS
Diesel Range Organics (DROs)	OSW8015B	5.6	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

LAB#: 00100404 **SAMPLE ID#:** 00100404-001

PROJECT ID : NEWSDAY DISPOSAL

SAMPLE ORIGIN : ROLL-OFF

MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00	10/27/00	10/27/00

PARAMETER	METHOD	RESULT	UNITS
Corrosivity	EPA SW-1110	Negative	
Flashpoint	EPA 1020	>100	°C
Reactive Cyanide	ASTM9010	<0.4	mg/kg
Reactive Sulfide	ASTM9310	<0.4	mg/kg
Reactivity	EPA SW-846 Chap. 7	Negative	
Total Petroleum Hydrocarbons	EPA 418.1	960	mg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

TCLP ANALYSIS

Prepared Exclusively For:

ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100404 **SAMPLE ID#:** 00100404-001
PROJECT ID : NEWSDAY DISPOSAL
SAMPLE ORIGIN : ROLL-OFF
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00	10/27/00	10/27/00

TCLP Lead	RESULTS	UNITS	REGULATORY LIMITS
TCLP Lead	0.05	mg/L	5.00

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100404 **SAMPLE ID#:** 00100404-001
PROJECT ID : NEWSDAY DISPOSAL
SAMPLE ORIGIN : ROLL-OFF
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/25/00	10/25/00 11:25:36 AM	10/27/00	10/27/00

TEST: PCBS (POLYCHLORINATED BIPHENYL) **METHOD:** EPA 8082A

PARAMETER	RESULT	UNITS
Aroclor 1016 (PCB-1016)	<7.0	µg/kg
Aroclor 1221 (PCB-1221)	<16	µg/kg
Aroclor 1232 (PCB-1232)	<4.0	µg/kg
Aroclor 1242 (PCB-1242)	<4.0	µg/kg
Aroclor 1248 (PCB-1248)	<2.0	µg/kg
Aroclor 1254 (PCB-1254)	<2.0	µg/kg
Aroclor 1260 (PCB-1260)	<2.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

SAMPLE COLLECTION / CHAIN OF CUSTODY RECORD

Pedneault Associates, Inc.
1615 NINTH AVENUE
BOHEMIA, NEW YORK 11716
PHONE: (631) 467-84[illegible] / FAX: (631) 467-6905

CLIENT: ENVIRONMENTAL SERVICES INC
ADDRESS: 133 COMMACK Rd
CITY, STATE, ZIP: MASTIC Beach NY
PHONE / FAX:

PAGE ___ OF ___
P.O. #:
JOB #:

PROJECT NAME AND/OR LOCATION: NEWSDAY

LAB NUMBER: 00100474

#	DATE	TIME	SAMPLE COMP	SAMPLE GRAB	MATRIX S	MATRIX L	MATRIX G	SAMPLE ORIGIN	SAMPLE CONTAINERS	ANALYSIS	#
1	10 26 00	4 pm		X	X			TWLB 115	1-16 oz MASON	8021 8270 STARS.	1
2	10 26 00	4 pm		X	X			TWLB 116	1-16 oz MASON	8021 8270 STARS	2
3	10 26 00	4 pm		X	X			LB-31	1-16-02 MASON	8021 8270 STARS	3
4											4
5											5
6											6
7											7
8											8
9											9
10											10

24 HR. T.A.T.

24 HR. T.A.T.

SAMPLED BY: DAVID PARISI
RELINQUISHED BY:
DATE: TIME:

SPECIAL INSTRUCTIONS: 24 HR TAT
RECEIVED BY:
DATE: TIME:

RECEIVED AT LAB BY: K. Bustria
DATE: 10/27/00 TIME: 9:15

SHIPPING CONTAINER CONDITION: GOOD ___ FAIR ___ POOR ___
PACKED IN ICE? YES ___ NO ___

REMARKS:

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100474 **SAMPLE ID#:** 00100474-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : TWLB 115
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100474 **SAMPLE ID#:** 00100474-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : TWLB 115
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100474 **SAMPLE ID#:** 00100474-002
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : TWLB 116
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100474 **SAMPLE ID#:** 00100474-002
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : TWLB 116
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene.	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100474 **SAMPLE ID#:** 00100474-003
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : LB-31
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<33	µg/kg
Anthracene	<33	µg/kg
Benzo(a)anthracene	<33	µg/kg
Benzo(a)pyrene	<33	µg/kg
Benzo(b)fluoranthene	<33	µg/kg
Benzo(g,h,i)perylene	<33	µg/kg
Benzo(k)fluoranthene	<33	µg/kg
Chrysene	<33	µg/kg
Dibenzo(a,h)anthracene	<33	µg/kg
Fluoranthene	<33	µg/kg
Fluorene.	<33	µg/kg
Indeno(1,2,3-cd)pyrene	<33	µg/kg
Naphthalene	<33	µg/kg
Phenanthrene	<33	µg/kg
Pyrene	<33	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:	***PEDNEAULT ASSOCIATES, INC.***
ENVIRONMENTAL SERVICES	*1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716*
133 COMMACK ROAD	**LAB#:** 00100474 **SAMPLE ID#:** 00100474-003
MASTIC BEACH , NY 11951-0000	**PROJECT ID :** NEWSDAY
(516)587-8282	**SAMPLE ORIGIN :** LB-31
	MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/26/00	10/27/00 10:35:54 AM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

SAMPLE COLLECTION / CHAIN OF CUSTODY RECORD

Pedneault Associates, Inc.
1615 NINTH AVENUE
BOHEMIA, NEW YORK 11716
PHONE: (631) 467-8477 / FAX: (631) 467-8905

CLIENT: ENVIRONMENTAL SERV INC
ADDRESS: 133 commack Rd.
CITY, STATE, ZIP: Commack Beach NY
PHONE / FAX:

PAGE ___ OF ___
P.O. #:
JOB #:

PROJECT NAME AND/OR LOCATION: NEWSDAY

RUSH

LAB NUMBER: 00100477

#	DATE	TIME	SAMPLE COMP	SAMPLE GRAB	MATRIX S	MATRIX L	MATRIX G	SAMPLE ORIGIN	SAMPLE CONTAINERS	ANALYSIS	#
1	10/27/00										1
2	10/27/00	13:00 pm		X		X		DRYWELL w/ pump	3 950 AMBERS	8021 → STARS	2
3										8270 → STARS	3
4											4
5											5
6											6
7											7
8											8
9											9
10											10

24 HR. T.A.T.

SAMPLED BY: [illegible]
RELINQUISHED BY:
DATE: TIME:
REMARKS:

SPECIAL INSTRUCTIONS: 24 HR TAT
RECEIVED BY:
DATE: TIME:

RECEIVED AT LAB BY:
DATE: 10.27.00 TIME: 2:20

SHIPPING CONTAINER CONDITION: GOOD ___ FAIR ___ POOR
PACKED IN ICE? YES NO

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100477 **SAMPLE ID#:** 00100477-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : DRY WELL W/PUMP
MATRIX: NON-POTABLE WATER

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/27/00	10/27/00 5:09:06 PM	10/31/00	10/31/00

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021

PARAMETER	RESULT	UNITS
Benzene	<1.0	µg/L
n-Butylbenzene	<1.0	µg/L
sec-Butylbenzene	<1.0	µg/L
tert-Butylbenzene	<1.0	µg/L
Ethylbenzene	<1.0	µg/L
Isopropylbenzene	<1.0	µg/L
p-Isopropyltoluene	<1.0	µg/L
Methyl-tert-butyl ether	20	µg/L
Napthalene	<1.0	µg/L
n-Propylbenzene	<1.0	µg/L
Toluene	<1.0	µg/L
1,2,4-Trimethylbenzene	6.5	µg/L
1,3,5-Trimethylbenzene	<1.0	µg/L
o-Xylene	<1.0	µg/L
m,p-Xylene	<1.0	µg/L
Mix Xylenes	<1.0	µg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (631) 467-8477 Fax: (631) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
ENVIRONMENTAL SERVICES
133 COMMACK ROAD
MASTIC BEACH , NY 11951-0000
(516)587-8282

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 00100477 **SAMPLE ID#:** 00100477-001
PROJECT ID : NEWSDAY
SAMPLE ORIGIN : DRY WELL W/PUMP
MATRIX: NON-POTABLE WATER

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
10/27/00	10/27/00 5:09:06 PM	10/30/00	10/30/00

TEST: STARS SEMI-VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270

PARAMETER	RESULT	UNITS
Acenaphthene	<1.0	µg/L
Anthracene	<1.0	µg/L
Benzo(a)anthracene	<1.0	µg/L
Benzo(a)pyrene	<1.0	µg/L
Benzo(b)fluoranthene	<1.0	µg/L
Benzo(g,h,i)perylene	<1.0	µg/L
Benzo(k)fluoranthene	<1.0	µg/L
Chrysene	<1.0	µg/L
Dibenzo(a,h)anthracene	<1.0	µg/L
Fluoranthene	<1.0	µg/L
Fluorene	1.1	µg/L
Indeno(1,2,3-cd)pyrene	<1.0	µg/L
Naphthalene	2.4	µg/L
Phenanthrene	1.1	µg/L
Pyrene	<1.0	µg/L

John Pedneault
Lab Director

NYS ELAP #10224

Newsday
Engineering Services
235 Pinelawn Road
Melville, NY 11747-4250
FAX (631)-843-3444

facsimile transmittal

To: DEC/Nick Acampora Fax: 631-~~444-0373~~ 0328

From: Stephen Cluff Date: November 22, 2000

Re: Spill # 00-08603 Pages: 9

CC:

Urgent For Review X Please Comment Please Reply Please Recycle

Mr. Acampora,

I am faxing you remaining Non-Hazardous Waste Manifests for Spill # 00-08603 and will send a hardcopy of originals once I receive them in the mail. The (4) ESI Manifests should read:

1. Contaminated Soil: 10.76 Tons
2. Oil Soaked Debris: 600 Pounds
3. Oily Water Mixture: 2005 Gallons
4. Oil/Water Mixture 3000 Gallons

Also, I'd like to follow-up with Spill #9906045 which occurred on August 20, 1999. Brian Austin was the DEC representative with whom I was corresponding; I am sending you fax/disposal Fenley & Nicol receipts for this spill as well for your reference.

Regards,

Stephen Cluff
Environmental Engineer

[redacted] ORIGINAL – RETURN TO GENERATOR [redacted]

[redacted]

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. EXEMPT | Manifest Doc No. 11700 | 2. Page 1 of

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD. MELVILLE

4. Generator's Phone ( )

5. Transporter 1 Company Name
ENVIRONMENTAL SERVICES INC.

6. US EPA ID Number
EXEMPT

A. Transporter's Phone
631-395-9888

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
CLEAN WATER
3249 RICHMOND TERRACE
STATEN ISLAND, NY

10. US EPA ID Number

C. Facility's Phone
718-981-4600

11. Waste Shipping Name and Description	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. NO11 OIL SOAKED DEBRIS	003	DM	600	P
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
NYS spill # 00-08603

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
FOR SPILL CLEAN UP CALL: E.S.I. 631-395-9888 or CHEMTREC 1-800-424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name Joseph Vassi Signature Agent for NewsDay Month 11 Day 20 Year 00

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name Kenny Cargill Signature Kenny Cargill Month 11 Day 20 Year 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name Signature Month Day Year

19. Discrepancy Indication Space
MEETS EPA REGULATIONS FOR NON HAZARDOUS WASTE:

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NEWSDAY | Manifest Doc. No. | 2. Page 1 of

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD. MELVILLE, NY
4. Generator's Phone ( )

5. Transporter 1 Company Name: ENVIRONMENTAL SERVICES INC.
6. US EPA ID Number: EXEMPT
A. Transporter's Phone: 631-395-9888

7. Transporter 2 Company Name
8. US EPA ID Number
B. Transporter's Phone

9. Designated Facility Name and Site Address
CLEAN WATER
3249 RICHMOND TERRACE
STATEN ISLAND, NY 10303
10. US EPA ID Number
C. Facility's Phone: 10303 718-981-4600

11. Waste Shipping Name and Description	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. NO18 OILY WATER MIXTURE	001	TK	2005	G
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
FOR SPILL CLEAN UP CALL: E.S.I. 631-395-9888 or CHEMTREC 1-800-424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Kenneth Englert Agent for | Signature | Month 11 Day 13 Year 00

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Kenneth Englert | Signature | Month 11 Day 13 Year 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space
MEETS EPA REGULATINS FOR NON HAZARDOUS WASTE:

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: Exempt
Manifest Doc. No.:
2. Page 1 of 1

3. Generator's Name and Mailing Address
Newedge
235 Pinelawn Rd, Melville NY
4. Generator's Phone ( )

5. Transporter 1 Company Name: Environmental Services Inc
6. US EPA ID Number:
A. Transporter's Phone: (631) 3950888

7. Transporter 2 Company Name:
8. US EPA ID Number:
B. Transporter's Phone:

9. Designated Facility Name and Site Address
Clean Water of New York
3249 Richmond Terrace
Staten Island NY 1195
10. US EPA ID Number:
C. Facility's Phone: (718) 9818 4600

	11. Waste Shipping Name and Description	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a.	NA18 011/Water Mixtures	001	TK	3000	G
b.					
c.					
d.					

D. Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Emergencies Call: ESI (631) 395-9888
or
Chemtrec (800) 424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: [illegible] Signature: [illegible] Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: [illegible] Signature: [illegible] Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Signature: Month Day Year

19. Discrepancy Indication Space
Meets EPA Regs For Non-Haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Signature: Month Day Year

GENERATOR TRANSPORTER FACILITY

COPY

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747
tel: 631/843-3631
fax: 631/843-3444
stephen.cluff@newsday.com

Stephen Cluff
Environmental Engineer

RECEIVED
DEC 11 2000
REG 1 - OIL SPILLS

December 4, 2000

Mr. Nick Acampora
New York State DEC
Spills Response Unit
Building 40 SUNY
Stony Brook, New York 11790-2356

Subject: Spill #00-08603 Waste Manifests

Mr. Acampora,

Enclosed are the remaining Non-Hazardous Waste Manifests for clean-up of TWLB #117 and manways for Diesel Fuel Tanks.

Should you need further information, feel free to call me at (631)-843-3631.

Sincerely,

Stephen Cluff
Environmental Engineer

Encl: 1. Non-Hazardous Waste Manifest 11-13-00 "3000 Gallon Oil/Water Mixtures"
2. Non-Hazardous Waste Manifest 11-13-00 "2005 Gallon Oil/Water Mixtures"
3. Non-Hazardous Waste Manifest 11-10-00 "600 Pound Oil Soaked Debris"
4. Non-Hazardous Waste Manifest 11-16-00 "10.76 Tons Contaminated Soil"

Cc: Joseph Marino, Newsday Facility Manager
Timothy McGarry, Newsday Assistant Facility Manager

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of 1
Exempt		

GENERATOR

3. Generator's Name and Mailing Address
Newsday
235 Pinelawn Rd, Melville NY
4. Generator's Phone ( )

5. Transporter 1 Company Name: Environmental Services In c
6. US EPA ID Number:
A. Transporter's Phone: (631) 39509888

7. Transporter 2 Company Name:
8. US EPA ID Number:
B. Transporter's Phone:

9. Designated Facility Name and Site Address
Clean Water of New York
3249 Richmond Terrace
Staten Island NY 1195
10. US EPA ID Number:
C. Facility's Phone: (718) 98104600

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. NA18 Oil/Water Mixtures	001	TK	3000	G
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
For Emergencies Call: ESI (631) 395-9888
or
Chemtrec (800) 424-9300

TRANSPORTER

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Vice President for Marketing
Signature:
Month 11 Day 15 Year 95

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month 11 Day 15 Year 95

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year

FACILITY

19. Discrepancy Indication Space
Meets EPA Regs For Non-Haz Waste

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Month Day Year

COPY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of
NEWSDAY		

GENERATOR

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD. MELVILLE, NY
4. Generator's Phone ( )

5. Transporter 1 Company Name
ENVIRONMENTAL SERVICES INC.

6. US EPA ID Number
EXEMPT

A. Transporter's Phone
631-395-9888

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
CLEAN WATER
3249 RICHMOND TERRACE
STATEN ISLAND, NY 10303

10. US EPA ID Number

C. Facility's Phone
~~10303~~ 718-981-4600

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. NO18 OILY WATER MIXTURE	001	TK	2005	G
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
FOR SPILL CLEAN UP CALL: E.S.I. 631-395-9888 or CHEMTREC 1-800-424-9300

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name	Signature	Month	Day	Year
Kenneth Enright Agent for	Kenneth Enright	1	1	2000

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Kenneth Enright	Kenneth Enright	1	1	2000

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
MEETS EPA REGULATINS FOR NON HAZARDOUS WASTE:

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
Tim R		1	3	00

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. EXEMPT | Manifest Doc. No. 11000 | 2. Page 1 of

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD. MELVILLE

4. Generator's Phone ( )

5. Transporter 1 Company Name: ENVIRONMENTAL SERVICES INC. | 6. US EPA ID Number: EXEMPT | A. Transporter's Phone: 631-395-9888

7. Transporter 2 Company Name | 8. US EPA ID Number | B. Transporter's Phone

9. Designated Facility Name and Site Address
CLEAN WATER
3249 RICHMOND TERRACE
STATEN ISLAND, NY

10. US EPA ID Number | C. Facility's Phone: 718-981-4600

11. Waste Shipping Name and Description	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. NO11 OIL SOAKED DEBRIS	003	DM	600	P
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
NYS spill # 00-08603

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
FOR SPILL CLEAN UP CALL: E.S.I. 631-395-9888 or CHEMTREC 1-800-424-9300

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.
Printed/Typed Name: Joseph Varisi, Agent for Newsday | Signature | Month 11 Day 20 Year 00

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Kenny Ewrulta | Signature | Month 11 Day 20 Year 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space
MEETS EPA REGULATIONS FOR NON HAZARDOUS WASTE:

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Tim | Signature | Month 11 Day 26 Year 00

GENERATOR

TRANSPORTER

FACILITY

ORIGINAL – RETURN TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of
EXEMPT		

GENERATOR

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD. MELVILLE, NY

4. Generator's Phone ( )

5. Transporter 1 Company Name	6. US EPA ID Number	A. Transporter's Phone
ENVIRONMENTAL SERVICES INC.	EXEMPT	631-395-9888
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter's Phone
9. Designated Facility Name and Site Address R-3 TECHNOLOGIES 7 STEEL RD. EAST MORRISVILLE, PA	10. US EPA ID Number	C. Facility's Phone 1-215-428-1700

11. Waste Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. N816 CONTAMINATED SOIL	001	TK	10.76	TNS
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above
ESR 00/00402

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
FOR SPILL CLEAN UP CALL: E.S.I. 631-395-9888 or CHEMTREC 1-800-424-9300

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name	Signature	Month	Day	Year
Agent for Newsday Frank A Brust	Frank A Brust	11	16	00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Frank A Brust	Frank A Brust	11	16	00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
MEETS EPA REGULATIONS FOR NON HAZARDOUS WASTE:

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
MICHAEL BROWN	M. Brown	11	16	00

ORIGINAL – RETURN TO GENERATOR

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☑ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 00-08603

Location	Representatives on site	time in	time out
Name NEWSDAY BLDG.	DEC RCAMPORA	1340	1355
Address 235 PINELAWN ROAD	STEVE CLUFF/NEWSDAY		
Town MELVILLE			
Phone	PRP		

Weather	Temperature	General conditions
humidity	Cold	Sunny
Dry	(Fair)	Partly Cloudy
(Humid)	Warm	(Cloudy)
Very humid	Hot	Rain / Snow


Date	Time	Inspection Narrative
11/10/00	1340	- RCAMPORA ON SITE.
		- MET W/ ABOVE REPS. REP.
		- DISCUSSED SITE & MADE FOLLOW-UP INSPECTION.
		- ALL DRAINS APPEAR SATISFACTORY EXCEPT FOR
		TWLB #117. ABSORBANT PADS STILL PRESENT
		IN DRAIN.
		- INSTRUCTED STEVE TO HAVE PADS REMOVED &
		FRESH ONES DEPLOYED. CONTINUE UNTIL CLEAN.
		- OTHER DRAINS APPEAR O.K.
		- STEVE PROVIDED DISPOSAL RECEIPTS.
		- WILL MAKE FOLLOW-UP NEXT WEEK.
	1355	- LEFT SITE.
11/14/00	1130	- RCAMPORA HAD TELECON W/ STEVE @ NEWSDAY.
		- TWLB #117 PUMP OF ALL LIQUID, &
		REMOVED APPROX 3 YDS OF BOTTOM SEDIMENTS.
		ALSO SAMPLED.
		- WILL RE-INSPECT THURSDAY TO CONFIRM.

Continued Page ____ Of ____

Contractor's Equipment	Contractor's Work Force	time in	time out

Site Sketch (Include North Arrow)


11/20/00
1457 - ARRIVED ON SITE
- MET W/ S. CLUFF.
- WORKED ON WELLS INC. TWLP #117-
- ALL APPEAR CLOSED
- AWAITING FINAL DISPOSAL RECEIPTS & SAMPLE RESULTS.
- UPON RECEIPT OF THIS DATA & BASED ON REVIEW, CAN CLOSE
1510 - LEFT SITE.





KEY MAP

SCALE: 1" = 1000'

DELIVERY DOCKS




DESHON (SL
SITE PLAN "A"
MARCUS DR.
HUNTINGTON
BABYLON
TOWN OF
TOWN OF
PINELAWN ROAD
39C
KEY MAP
SCALE: 1" = 1000'
SAN
107
SAN MH
MH
DROP INLET #1
S
LB #29
FP
LB #30
TWMH #1
DROP INLET #2
TWMH #2
120'
10
FP
LB #31
DROP INLET #3
W
31.17'
100'
8"
8"
100.00
106.77
107.22
106.63
12"
12"
10"
106.32
106.32
106.5
MH-123
MH-122
MH-170
TWLB #119
TWLB #118
TW LB #117
LB #86
TWLB #120
TWLB #116
TWLB #121
TWLB #115
FP
106
105
LB #83
LB #84
LB #85
LB #87
LB #88
LB #89
CB 114
8


TWMH #2
DROP INLET #3
LB# 31
FP
120'
10
31.17'
W
106.7
107.08
107.22
106.63
8"
8"
12"
12"
106.54
MH 123
106.32
MH 122
106.32
MH 120
TWLB #119
TWLB #118
TW LB #117
LB# 86
TWLB #120
TWLB #116
10"
106
FP
TWLB #121
TWLB #115
106'
105
LB# 83
LB# 87
LB# 84
LB# 88
CB 114
LB# 85
LB# 89

New York State Department of Environmental Conservation
Division of Environmental Remediation, Region One
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
Phone: (631) 444-0320 • **FAX:** (631) 444-0328
Website: www.dec.state.ny.us

John P. Cahill
Commissioner

December 14, 2000

Newsday
235 Pinelawn Road
Melville, NY 11747-4250

Attn: Stephen Cluff, Environmental Engineer

RE: Spill #00-08603, Diesel Fuel Release, Newsday Building, 235 Pinelawn Road, Melville.

Dear Mr. Cluff :

Based upon a review of the file, you have completed the investigation/remediation for the referenced site.

This office has no further requirements for the referenced spill at this time. Should additional environmental problems be discovered at this site, this office will require further action at that time. The spill file has been removed from our active spill list.

If you have any questions please call me at (631) 444-0322.

Sincerely,

Nick Acampora
Environmental Program Specialist I

cc: K. Gomez

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 0125175

SPILL NAME: NEWSDAY **DEC LEAD:** UNASSIGNED

SPILL DATE: 08/27/2001 **SPILL TIME:** 11:05 am

CALL RECEIVED DATE: 08/27/2001 **RECEIVED TIME:** 11:49 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: SAME **CONTACT PHONE:** (516) 657-7012

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

FAILURE OF HYDRAULIC HOSE ON DUMPSTER TRUCK. SPEEDY DRY APPLIED. TRUCK WAS OPERATED BY JAMAICA ASH. WILL USE ESI TO COMPLETE CLEANUP.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	20 G	20 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE NY	STEPHEN CLUFF (631) 843-3631

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "UNASSIGNED 01-090"

PIN **T & A** **COST CENTER**

CLASS: C4 **CLOSE DATE:** 09/16/2004 **MEETS STANDARDS:** True

Created On: 08/27/2001

Date Printed: 8/7/2018 Last Updated: 12/10/2009

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 0203990

SPILL NAME: NEWSDAY **DEC LEAD:** UNASSIGNED

SPILL DATE: 07/17/2002 **SPILL TIME:** 6:00 am

CALL RECEIVED DATE: 07/17/2002 **RECEIVED TIME:** 9:11 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: STEPHEN CLUFF **CONTACT PHONE:** (631) 843-3631

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Local Agency

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
HYDROLIC LINE ON TRUCK BROKE *** 877-382-1737 - BEEPER ***

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	20 G	20 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
JAMAICA ASH	UNKNOWN ZZ	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

7/17 CLUFF CALLED, LINE ON GARBAGE TRUCK RUPTURED WHILE PICKING UP DUMPSTER
~4'X20' AREA ON ASPHALT, NO DRAINS, PRP CLEANING WITH SPEEDI DRI, BROOMS, SWEEPER

PIN **T & A** **COST CENTER**

CLASS: C4 **CLOSE DATE:** 08/21/2002 **MEETS STANDARDS:** True

Created On: 07/17/2002

Date Printed: 8/7/2018 Last Updated: 08/07/2018

RECEIVED
JUL 3 1 2002
REG 1 - OIL SPILLS

Newsday

A TRIBUNE PUBLISHING COMPANY

235 Pinelawn Road
Melville, New York 11747
tel: 631/843-3631
fax: 631/843-3444
stephen.cluff@newsday.com

Stephen Cluff, P.E.
Environmental Engineer

July 26, 2002

Ms. Karen Gomez
NY State Department of Environmental Conservation
Division of Environmental Remediation, Region 1
Spill Prevention and Response
Stony Brook, New York 11790-2356

Subject: Spill #020-3990 Waste Manifests

Ms. Gomez,

On July 17th, 2002 at approximately 6:00 AM, a hydraulic hose on a Waste Contractor (Jamaica Ash) vehicle let loose under pressure dispensing 15-20 gallons of hydraulic fluid to pavement in Newsday's Truck Parking Lot. The hydraulic fluid was immediately contained posing no threat to groundwater, the nearest storm drain over 100' from the spill. Jamaica Ash immediately cleaned up and discarded the spill contents into (1) 55 gallon drum through the use of absorbent material, deck brooms and a street cleaner by 2:00 PM on the same day as instructed by Dave Remy from the Department of Environmental Conservation. (1) drum of speedy dry/hydraulic fluid was removed for disposal. Enclosed is the Non-Hazardous Waste Manifest.

Should you need further information, feel free to call me at (631)-843-3631.

Sincerely,

Stephen Cluff, P.E.
Environmental Engineer

Encl: 1. Non-Hazardous Waste Manifest #5994 7-19-02 "150 lbs."

cc: Stephen Zimmerman, Newsday Director of Engineering
Joseph Marino, Newsday Manager of Facilities and Maintenance
Matt Gross, Town of Huntington Environmental Waste Management

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

NON-HAZARDOUS MANIFEST

1. Generator's US EPA ID No.	Manifest Document No. 0 3 9 3 4	2. Page 1 of 4 of 1

3. Generator's Name and Mailing Address
NEWSDAY
235 PINELAWN RD.
MELVILLE, NY 11747
4. Generator's Phone (631) 843-2038

5. Transporter 1 Company Name	6. US EPA ID Number	A. Transporter's Phone
ABLE ENVIRONMENTAL SERVICE	N Y R 0 0 0 0 0 3 5 8 2	1A-392 631 567-6545
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter's Phone
9. Designated Facility Name and Site Address	10. US EPA ID Number	C. Facility's Phone
A B OIL SERVICE LTD. 1599 Ocean Avenue Bohemia, NY 11716	N Y D 9 8 7 0 2 3 3 7 1	516 567-6545

11. Shipping Name and Description	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol
a. OIL SOAKED DEBRIS D M	1	DM	N011 P 150	4
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above

E. Handling Codes Listed Above
S14

15. Special Handling Instructions and Additional Information
24 HOUR EMERGENCY # (516) 567-6545

16. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name	Signature	Month	Day	Year
X Stephen Cluff		07	19	02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jerry NoGueras		07	19	02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
TIM MAHONEY		7	22	02

GENERATOR

TRANSPORTER

FACILITY

Published by J.J. KELLER & ASSOCIATES, INC. Neenah, WI • USA • (800) 327-6868 • Printed in the United States

ORIGINAL - RETURN TO GENERATOR

New York State Department of Environmental Conservation
Division of Environmental Remediation, Region One
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
Phone: (631) 444-0320 • **FAX:** (631) 444-0328
Website: www.dec.state.ny.us



Erin M. Crottyl
Commissioner

August 27, 2002

Stephen Cluff
Newsday
235 Pinelawn Road
Melville, NY 11747

Re: Spill # 02-03990, 235 Pinelawn Road, Melville

Dear Mr. Cluff:

Based upon a review of the file, you have completed the investigation/remediation for the referenced site.

This office has no further requirements for the referenced spill at this time. Should additional environmental problems be discovered at this site, this office will require further action at that time. The spill file has been removed from our active spill list.

Please call me if you have any questions.

Sincerely,

FOR

Karen J. Gomez, P.E.
Regional Spill Engineer

KJG:rl

NYSDEC SPILL REPORT FORM

DEC REGION: 1
SPILL NUMBER: 0507524
SPILL NAME: NEWSDAY
DEC LEAD: Unassigned
SPILL DATE: 09/22/2005
SPILL TIME: 4:00 pm
CALL RECEIVED DATE: 09/22/2005
RECEIVED TIME: 5:23 pm

SPILL LOCATION

PLACE: NEWSDAY
COUNTY: Suffolk
STREET: 235 PINELAWN ROAD
TOWN/CITY: Huntington
COMMUNITY: MELVILLE
CONTACT: JOE MARINO
CONTACT PHONE: (516) 509-0495

CONT. FACTOR: Equipment Failure
SPILL REPORTED BY: Responsible Party
FACILITY TYPE: Commercial/Industrial
WATERBODY:

CALLER REMARKS:
BERMED AREA, CONTAINED, AND CLEANED UP. DUE TO AN O RING ON A FILTER BREAKING.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
ink	Other	100 G	100 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE NY	JOE MARINO
		(516) 509-0495 CELL

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:
9/13/05 9:22 TELECON MARINO, INK RECLAIM MACHINE, FILTERED AND RECYCLED, AREA IS BERMED AND FLOOR SEALED. ESTIMATE ABOUT 100 GALS PUMPED INTO DRUMS. MACHINE WILL BE REPAIRED

PIN
T & A
COST CENTER

CLASS: C4
CLOSE DATE: 03/14/2006
MEETS STANDARDS: False

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES
DIVISION OF ENVIRONMENTAL QUALITY
OFFICE OF POLLUTION CONTROL

TANK REMOVAL CHECKLIST

FILE REF NO: 02037 REG NO: 4-0094 DATE: 4-28-11
FACILITY NAME: Newsday
FACILITY ADDRESS: 235 Pinelawn Rd Melville
SCTM# 400-270-2-1
400-270-1-24.001 SITE GPS

TANK #	LOCATION	CAPACITY	CONTENTS	MATERIAL
14	Underlout	20000 gal	Diesel	FRP
15	Underlout	20000 gal	Diesel	FRP
16	Underlout	20000 gal	Diesel	FRP


1. CONDITION OF TANK AND PIPING: (Note any holes) No holes or stains noted
Tanks appear to be in good condition.

2. WAS CONTAMINATION NOTED WITHIN EXCAVATION? (Y) / N
All Material Removed Under SCDHS Supervision: Y / (N)
Approximate Amount Of Contaminated Soil Removed: 25-30 (cu yds) / tons / drums DEC To oversee cleanup (possible event)
Was Ground Water Impacted: Y / (N)
DEC Notified: (Y) / N *(1-800-457-7362)* DEC Spill Number: 10-96551

3. WERE ALL ASSOCIATED PIPES AND VENT LINES REMOVED? Y / (N) (If No, explain)
To be removed (near electrical)

4. NAME OF CONTRACTOR: Jones Warner

Site Sketch: Private Rd.



A Copy of This Document Was Given to: [signature]
(Owner's Representative)

Inspector: Jeff Green Inspector's Signature: Jeff Green

OFFICE USE:	
SCDHS Spill Number:	Spills Key:

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1000551

SPILL NAME: NEWSDAY **DEC LEAD:** TJDEMEO

SPILL DATE: 04/13/2010 **SPILL TIME:** 4:00 pm

CALL RECEIVED DATE: 04/13/2010 **RECEIVED TIME:** 4:30 pm

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Other **SPILL REPORTED BY:** Other

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

WOERNER IS PREPARING TO REMOVE 3 20,000GAL DIESEL TANKS, AND FOUND CONTAMINATION UNDER THE DISPENSER. HE IS NOT CERTAIN WHEN THE TANKS WILL ACTUALLY BE REMOVED BECAUSE HE MUST HAVE SHORING INSTALLED, BUT HOPES THEY WILL BE REMOVED THIS WEEK OR NEXT. (DR)

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	0 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 pinelawn rd melville NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

3/28/11 TJD
File review. All required documentation has been provided in support of spill closure. A total of 166.83 tons of petroleum impacted soils were excavated and properly disposed of during remedial process. Laboratory analysis reveals all target compounds are within acceptable concentrations. No further action is required.

PIN **T & A** **COST CENTER**

CLASS: B3 **CLOSE DATE:** 03/30/2011 **MEETS STANDARDS:** False

Created On: 04/14/2010

Date Printed: 10/12/2016 Last Updated: 04/02/2011

Multiple files are bound together in this PDF Package.

Adobe recommends using Adobe Reader or Adobe Acrobat version 8 or later to work with documents contained within a PDF Package. By updating to the latest version, you'll enjoy the following benefits:

- Efficient, integrated PDF viewing
- Easy printing
- Quick searches

Don't have the latest version of Adobe Reader?

Click here to download the latest version of Adobe Reader

If you already have Adobe Reader 8, click a file in this PDF Package to view it.

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1108374

SPILL NAME: NEWSDAY OFFICE **DEC LEAD:** Unassigned

SPILL DATE: 10/01/2011 **SPILL TIME:** 9:30 pm

CALL RECEIVED DATE: 10/01/2011 **RECEIVED TIME:** 1:35 am

SPILL LOCATION

PLACE: NEWSDAY OFFICE **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOSEPH MARINO **CONTACT PHONE:** (631) 843-2044

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Affected Persons

FACILITY TYPE: Commercial Vehicle **WATERBODY:**

CALLER REMARKS:

SPEEDY DRY HAS BEEN LAID ON THE SPILL

CELL - 516-509-0495

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	6 G		Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
PRE PRINT LOGISTICS	NY	(800) 596-2335

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

10/3/2011 11:30 t/c to JOSEPH MARINO, NEWSDAY

-Truck from Pre Print Logistics Management, INC. (800-596-2335) was making a delivery to Newsday.
-When the truck was leaving, it was noticed that it was leaking diesel fuel.
-The driver of the truck drove off.
-Aprox 5 to 6 gallons spilled at the loading dock.
-No drains affected, Miller completed the cleanup. (BD)

PIN **T & A** **COST CENTER**

CLASS: C4 **CLOSE DATE:** 10/03/2011 **MEETS STANDARDS:** False

From: Dave Raymond
To: Anthony Leung
Date: 4/23/2012 3:33 PM
Subject: NEWSDAY SEWAGE SPILL- MELVILLE
Attachments: 1200716.pdf

Attached is a copy of Spill report 1200716 that we received today. The plant operator (Severin Trent) is handling any cleanup.

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1200716

SPILL NAME: NEWSDAY **DEC LEAD:** Unassigned

SPILL DATE: 04/23/2012 **SPILL TIME:** 8:30 am

CALL RECEIVED DATE: 04/23/2012 **RECEIVED TIME:** 1:12 pm

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOSEPH MARINO **CONTACT PHONE:** (631) 843-2044

CONT. FACTOR: Other **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
system had loss due to weather, no waterways, c/u in progress

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
wastewater	Other	500 G		Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE NY	JOSEPH MARINO (631) 843-2044

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

04/23/12 1330 Hrs (A): Called Marino- this was a spill of combined industrial/sanitary sewage from THEIR plant.

04/23/12 1330 Hrs (B): The waste spilled onto gravel, and the plant operator (SEVERIN TRENT) is cleaning up the spillage.

04/23/12 1330 Hrs (C): Spills informed Marino we would notify DEC Div of Water. DR

04/23/12 1535 Hrs: Copy of this report emailed to Tony Leung (DEC Div of Water). DR

PIN **T & A** **COST CENTER**

CLASS: D5 **CLOSE DATE:** 10/22/2012 **MEETS STANDARDS:** False

Created On: 04/23/2012

Date Printed: 10/12/2016 Last Updated: 11/30/2012

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1203029

SPILL NAME: NEWSDAY INC **DEC LEAD:** hmcirrit

SPILL DATE: 06/26/2012 **SPILL TIME:** 8:15 pm

CALL RECEIVED DATE: 06/26/2012 **RECEIVED TIME:** 10:02 pm

SPILL LOCATION

PLACE: NEWSDAY INC **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: DJ OCONNOR **CONTACT PHONE:** (516) 678-5115

CONT. FACTOR: Tank Test Failure **SPILL REPORTED BY:** Tank Tester

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
Tank test failure. underground 25000g

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
#2 fuel oil	Petroleum			Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY INC	235 PINELAWN ROAD MELVILLE NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

TANK ABANDONED IN PLACE

PIN **T & A** **COST CENTER**

CLASS: B3 **CLOSE DATE:** 04/07/2014 **MEETS STANDARDS:** False

Created On: 06/26/2012

Date Printed: 10/12/2016 Last Updated: 06/25/2014

Environmental Resources Management

105 Maxess Road
Suite 316
Melville, NY 11747
(631) 756-8900
(631) 756-8901 (fax)
http://www.erm.com

4 April 2014

Mr. Hugh Cirrito
NYSDEC
50 Circle Road
Stony Brook, NY 12561

Re: Spill Case No. 1203029
Spill Closure Report
235 Pinelawn Road, Melville, NY

Dear Mr. Cirrito:

On behalf of Tribune Company (Tribune), ERM Consulting & Engineering, Inc. (ERM) has prepared this summary letter report to document the investigation, and abandonment of two (2) 25,000-gallon fuel oil underground storage tanks (USTs) located at 235 Pinelawn Road, Melville, NY (the Property).

PROJECT BACKGROUND

On 15 November 2011, tightness testing was performed on adjacent Tank Nos. 6 & 7 located in a loading dock area south of the main building. A site plan showing the tank locations is provided as Figure 1. Both USTs were registered with the New York State Department of Environmental Conservation (NYSDEC) through the Suffolk County Department of Health Services (SCDOHS).

Tank No. 6 tested "tight" while Tank No. 7 failed the tightness test and was immediately pumped out. The NYSDEC was notified and NYSDEC Spill No. 1203029 was assigned. Subsequently, Tank No. 7 was cleaned and 4 soil samples were collected from beneath the tank invert and analyzed for Volatile Organic Compounds (VOCs) and Semi-VOCs (SVOC) on 25 October 2012. The analytical results were provided to the NYSDEC and authorization was given to abandon Tank No. 7 on 14 November 2012 (Appendix A). The sampling locations are identified in Figure 1 and a summary of the analytical results from the 25 October 2012 sampling event are provided as Table 1. A complete analytical data report is provided as Appendix B.

Although Tank No. 6 had tested tight, Tribune elected to preemptively abandon this tank and replace it with an above ground storage tank (AST). On 26 June 2013, an abandonment request for both tanks was submitted to SCDOHS which was subsequently approved by the SCDOHS on 13 September 2013. Copies of the abandonment request and approval letters are provided as Appendix C.

ABANDONMENT ACTIVITIES

Tank No. 6 remained in service for emergency generator fuel storage until early 2014 when it was replaced by an AST. Tank No. 6 was emptied on 7 March 2014 so that it could be abandoned along with Tank No. 7.

On 17 March 2014, ERM and its UST contractor, Metro Environmental Contracting Corporation (Metro) mobilized to the Site to abandon the two tanks. Metro Environmental vacuumed out the residual product and cleaned the interior of Tank No. 6. Three equidistant saw cuts were then made in the concrete above each tank and the soil was excavated to expose the tank tops. The tanks were then cut at each location to expose their interiors, and the vent pipes, fill ports and tank alarms were removed.

On 20 March 2014, Mr. Mike Seaman from SCDOHS inspected the tanks prior to backfilling to confirm that their interiors were clean and ready for abandonment. The SCDOHS was satisfied with the condition of the tanks and authorized the abandonment. The tanks were subsequently abandoned with 296-tons of clean sand. The bills of lading for the sand from 110 Sand Company is provided in Appendix D.

On 21 March 2014, Mr. Seaman (SCDOHS) returned to the Site to observe the backfilled tanks and issued the completed Tank Removal Checklist, which is provided in Appendix E. The open excavations were then backfilled using clean sand installed in compacted lifts, and finished to grade with 6-inches of 4,000 psi-rated concrete. The concrete patches were keyed into the existing pad/reinforced with rebar and steel mesh. The vent line for each tank was cut flush to grade and filled with concrete. The fill ports were directly atop each UST and were removed when the tanks were cut open and accessed. Pictures documenting the tank closure and restoration work are provided in Appendix F.

Waste Disposal

A total of 10 cubic yards of un-impacted concrete and soil from above the tanks was excavated and transported to Con Strux in Lindenhurst, NY, for recycling. Approximately 300 gallons of combined tank sludge and wash water were collected in the vacuum truck and transported to Advanced Waste and Water Technology in Farmingdale, NY. The adsorbant (SpeedyDry) used to clean the residual fuel oil in Tank No. 6 was collected in one (1) 55-gallon drum and transported to Republic Environmental Systems in Hatfield, PA, for disposal. The associated waste manifests are provided in Appendix G.

CONCLUSIONS AND RECOMMENDATIONS

The tank abandonment activities were completed under the supervision of SCDOHS and in accordance with all NYSDEC and SCDOHS regulations. On behalf of Tribune, ERM respectfully requests that NYSDEC Spill Case No. 1203029 be closed as soon as possible.

We look forward to your expeditious approval of this closure request. If you have any additional questions or comments, please do not hesitate to contact me at (631) 756-8900.

Sincerely,



Eugene Gabay
Senior Consultant

Attachments

cc: Chris Wong, SCDOH
Rita DeBoer, Tribune
Mark Bilut, McDermott Will & Emery LLP

FIGURE



Legend

- Tank Excavation
- Soil Sample Location

0 20 40

GRAPHIC SCALE IN FEET

N

TITLE

SITE PLAN
235 PINELAWN ROAD
MELVILLE, NY 11747

PREPARED FOR

TRIBUNE COMPANY

Environmental Resources Management

FIGURE 1

DRAWN BY	SCALE	DATE	JOB NO.
EMF	GRAPHIC	04/01/2014	0177133

R:\Scout\Projects\Tribune Company\CAD\2014-03 - Tribune - Site Plan.dwg (04/01/2014 - 2:27pm Melville)

TABLE

TABLE 1
Tank No. 6 Soil Sampling Results Summary
Spill No. 1203029
235 Pinelawn Road
Melville, New York

Client Sample ID:		NY CP-51 Table 2 - Gasoline Contaminated	NY CP-51 Table 3 - Fuel Oil Contaminated	TRIB-A	TRIB-B	TRIB-C	TRIB-D
Lab Sample ID:				JB20289-1	JB20289-2	JB20289-3	JB20289-4
Date Sampled:		Soil (NYDEC CP-51 10/10)	Soil (NYDEC CP-51 10/10)	10/25/2012	10/25/2012	10/25/2012	10/25/2012
Matrix:				Soil	Soil	Soil	Soil
GC/MS Volatiles (SW846 8260B)							
Benzene	ug/kg	60	60	ND (0.11)	ND (0.11)	0.42 J	ND (0.13)
n-Butylbenzene	ug/kg	12000	12000	ND (0.11)	ND (0.11)	ND (0.17)	ND (0.12)
sec-Butylbenzene	ug/kg	11000	11000	ND (0.11)	ND (0.11)	ND (0.18)	ND (0.12)
tert-Butylbenzene	ug/kg	5900	5900	ND (0.28)	ND (0.28)	ND (0.45)	ND (0.32)
Ethylbenzene	ug/kg	1000	1000	ND (0.25)	ND (0.25)	ND (0.41)	ND (0.28)
Isopropylbenzene	ug/kg	2300	2300	ND (0.072)	ND (0.070)	ND (0.11)	ND (0.080)
p-Isopropyltoluene	ug/kg	10000	10000	ND (0.10)	ND (0.098)	ND (0.16)	ND (0.11)
Methyl Tert Butyl Ether	ug/kg	930	-	ND (0.23)	ND (0.22)	ND (0.36)	ND (0.25)
Naphthalene	ug/kg	12000	12000	ND (0.12)	ND (0.11)	ND (0.19)	ND (0.13)
n-Propylbenzene	ug/kg	3900	3900	ND (0.11)	ND (0.11)	ND (0.18)	ND (0.13)
Toluene	ug/kg	700	700	ND (0.10)	ND (0.099)	ND (0.16)	ND (0.11)
1,2,4-Trimethylbenzene	ug/kg	3600	3600	ND (0.20)	ND (0.20)	ND (0.32)	ND (0.23)
1,3,5-Trimethylbenzene	ug/kg	8400	8400	ND (0.15)	ND (0.15)	ND (0.25)	ND (0.17)
m,p-Xylene	ug/kg	260	260	ND (0.17)	ND (0.16)	ND (0.27)	ND (0.19)
o-Xylene	ug/kg	260	260	ND (0.13)	ND (0.13)	ND (0.21)	ND (0.15)
Xylene (total)	ug/kg	260	260	ND (0.13)	ND (0.13)	ND (0.21)	ND (0.15)
GC/MS Semi-volatiles (SW846 8270D)							
Acenaphthene	ug/kg	-	20000	ND (8.7)	22.7 J	22.3 J	ND (11)
Acenaphthylene	ug/kg	-	100000	ND (9.6)	ND (11)	ND (11)	ND (12)
Anthracene	ug/kg	-	100000	ND (11)	490	503	ND (13)
Benzo(a)anthracene	ug/kg	-	1000	ND (9.8)	**1060**	**1400**	41
Benzo(a)pyrene	ug/kg	-	1000	ND (9.2)	497	615	18.1 J
Benzo(b)fluoranthene	ug/kg	-	1000	ND (10)	965	806	21.3 J
Benzo(g,h,i)perylene	ug/kg	-	100000	ND (11)	284	281	ND (14)
Benzo(k)fluoranthene	ug/kg	-	800	ND (11)	512	489	ND (14)
Chrysene	ug/kg	-	1000	ND (10)	**1070**	**1260**	33.4 J
Dibenzo(a,h)anthracene	ug/kg	-	330	ND (10)	118	116	ND (13)
Fluoranthene	ug/kg	-	100000	22.6 J	3210	3910	106
Fluorene	ug/kg	-	30000	ND (9.8)	35.5	35.5	ND (12)
Indeno(1,2,3-cd)pyrene	ug/kg	-	500	ND (10)	302	278	ND (13)
Naphthalene	ug/kg	12000	12000	ND (8.2)	ND (9.1)	ND (9.4)	ND (10)
Phenanthrene	ug/kg	-	100000	17.5 J	1340	1340	26.2 J
Pyrene	ug/kg	-	100000	13.8 J	2150	2920	75.7
General Chemistry							
Solids, Percent	%	-	-	98	93.5	85.1	85.9

Compound Detected
Compound Exceeds Criteria

APPENDIX A
NYSDEC ABANDONMENT APPROVAL

Eugene Gabay

From: Hugh Cirrito <hmcirrit@gw.dec.state.ny.us>
Sent: Wednesday, November 14, 2012 11:25 AM
To: Eugene Gabay
Subject: Re: Spill No. 1203029_ Sample Results

Gene,

I have reviewed the submitted sample results. You may abandon the tank in place. Please inform me when the work is completed.

Hugh Cirrito, PE
Environmental Engineer 2
NYSDEC Spill Response
(631) 444-0324
(631) 444-0328 fax

>>> Eugene Gabay <Eugene.Gabay@erm.com> 11/14/2012 11:11 AM >>>
Hello Hugh,

As discussed, ERM drilled core holes at 4 locations in the spine of the tank in order to obtain soil samples. The soil samples were collected from the soil just below the tank and analyzed for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) via EPA methods 8260 and 8270 by a New York State Department of Health-certified laboratory. The laboratory results are attached for your review. ERM's intention is to abandon the tank in place. Once you have had a chance to review the data could you please call me to discuss? My number is listed at the bottom of this email.

Thanks,
Gene

Eugene Gabay
Environmental Resources Management (ERM)
40 Marcus Drive
Suite 200
Melville, New York 11747

T: +1 631 756-8900 (Main)
T: +1 631 756-8954(Direct)
F: +1 631 756-8901
C: +1 516 250-6155

eugene.gabay@erm.com

www.erm.com

This electronic mail message may contain information which is (a) LEGALLY PRIVILEGED, PROPRIETARY IN NATURE, OR OTHERWISE PROTECTED BY LAW FROM DISCLOSURE, and (b) intended only for the use of the Addressee (s) names herein. If you are not the Addressee(s), or the person responsible for delivering this to the Addressee (s), you are hereby notified that reading, copying, or distributing this message is prohibited. If you have received this electronic mail message in error, please contact us immediately at (617) 646-7800 and take the steps necessary to delete the message completely from your computer

system. Thank you,

Please visit ERM's web site: http://www.erm.com

APPENDIX B
LAB DATA

New Jersey ACCUTEST LABORATORIES

03/27/14



Technical Report for

ERM, Inc.

Tribune, Pinelawn Avenue, Melville, NY

0177133

Accutest Job Number: JB20289

Sampling Date: 10/25/12

Report to:

ERM, Inc.

eugene.gabay@erm.com

ATTN: Eugene Gabay

Total number of pages in report: **20**

NELAP ACCREDITED TNI LABORATORY

Test results contained within this data package meet the requirements of the National Environmental Laboratory Accreditation Program and/or state specific certification programs as applicable.

Nancy Cole
Laboratory Director

Client Service contact: Tammy McCloskey 732-329-0200

Certifications: NJ(12129), NY(10983), CA, CT, DE, FL, IL, IN, KS, KY, LA, MA, MD, MI, MT, NC, OH VAP (CL0056), PA, RI, SC, TN, VA, WV, DoD ELAP (L-A-B L2248)

This report shall not be reproduced, except in its entirety, without the written approval of Accutest Laboratories. Test results relate only to samples analyzed.

Accutest Laboratories is the sole authority for authorizing edits or modifications to this document. Unauthorized modification of this report is strictly prohibited.

Sections: 1 2 3 4 5

Table of Contents

Section 1: Sample Summary **3**
Section 2: Case Narrative/Conformance Summary **4**
Section 3: Summary of Hits **6**
Section 4: Sample Results **8**
4.1: JB20289-1: TRIB-A 9
4.2: JB20289-2: TRIB-B 11
4.3: JB20289-3: TRIB-C 13
4.4: JB20289-4: TRIB-D 15
Section 5: Misc. Forms **17**
5.1: Chain of Custody 18

Sample Summary

ERM, Inc.

Job No: JB20289

Tribune, Pinelawn Avenue, Melville, NY
Project No: 0177133

Sample Number	Collected Date	Time	By	Received	Matrix Code	Type	Client Sample ID
JB20289-1	10/25/12	13:20	JM	10/26/12	SO	Soil	TRIB-A
JB20289-2	10/25/12	13:28	JM	10/26/12	SO	Soil	TRIB-B
JB20289-3	10/25/12	13:34	JM	10/26/12	SO	Soil	TRIB-C
JB20289-4	10/25/12	13:40	JM	10/26/12	SO	Soil	TRIB-D

Soil samples reported on a dry weight basis unless otherwise indicated on result page.

CASE NARRATIVE / CONFORMANCE SUMMARY

Client:	ERM, Inc.	**Job No**	JB20289
Site:	Tribune, Pinelawn Avenue, Melville, NY	**Report Date**	11/12/2012 4:09:42 P

On 10/26/2012, 4 Sample(s), 0 Trip Blank(s) and 0 Field Blank(s) were received at Accutest Laboratories at a temperature of 3 C. Samples were intact and chemically preserved, unless noted below. An Accutest Job Number of JB20289 was assigned to the project. Laboratory sample ID, client sample ID and dates of sample collection are detailed in the report's Results Summary Section.

Specified quality control criteria were achieved for this job except as noted below. For more information, please refer to the analytical results and QC summary pages.

Volatiles by GCMS By Method SW846 8260B

Matrix: SO **Batch ID:** VO5784

- All samples were analyzed within the recommended method holding time.
- All method blanks for this batch meet method specific criteria.
- Sample(s) JB20133-2MS, JB20133-2MSD were used as the QC samples indicated.

Extractables by GCMS By Method SW846 8270D

Matrix: SO **Batch ID:** OP61052

- All samples were extracted within the recommended method holding time.
- All method blanks for this batch meet method specific criteria.
- Sample(s) JB20508-1MS, JB20508-1MSD were used as the QC samples indicated.
- Matrix Spike Recovery(s) for Acenaphthylene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- Matrix Spike Duplicate Recovery(s) for Acenaphthylene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- Matrix Spike Recovery(s) for Acenaphthene, Anthracene, Benzo(a)anthracene, Benzo(a)pyrene, Benzo(b)fluoranthene, Benzo(g,h,i)perylene, Benzo(k)fluoranthene, Chrysene, Dibenzo(a,h)anthracene, Fluoranthene, Fluorene, Indeno(1,2,3-cd)pyrene, Naphthalene, Phenanthrene, Pyrene are outside control limits. Outside control limits due to high level in sample relative to spike amount.
- JB20289-4: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-3: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-3: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-2: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
- JB20289-1: Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

Wet Chemistry By Method SM2540 G-97

Matrix: SO **Batch ID:** GN74854

- The data for SM2540 G-97 meets quality control requirements.

Accutest certifies that data reported for samples received, listed on the associated custody chain or analytical task order, were produced to specifications meeting Accutest's Quality System precision, accuracy and completeness objectives except as noted.

Estimated non-standard method measurement uncertainty data is available on request, based on quality control bias and implicit for standard methods. Acceptable uncertainty requires tested parameter quality control data to meet method criteria.

Accutest Laboratories is not responsible for data quality assumptions if partial reports are used and recommends that this report be used in its entirety. Data release is authorized by Accutest Laboratories indicated via signature on the report cover

Summary of Hits

Job Number: JB20289
Account: ERM, Inc.
Project: Tribune, Pinelawn Avenue, Melville, NY
Collected: 10/25/12

Lab Sample ID / Analyte	Client Sample ID	Result/ Qual	RL	MDL	Units	Method
JB20289-1	**TRIB-A**					
Fluoranthene [a]		22.6 J	30	13	ug/kg	SW846 8270D
Phenanthrene [a]		17.5 J	30	14	ug/kg	SW846 8270D
Pyrene [a]		13.8 J	30	12	ug/kg	SW846 8270D
JB20289-2	**TRIB-B**					
Acenaphthene [a]		22.7 J	33	9.7	ug/kg	SW846 8270D
Anthracene [a]		490	33	12	ug/kg	SW846 8270D
Benzo(a)anthracene [a]		1060	33	11	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		497	33	10	ug/kg	SW846 8270D
Benzo(b)fluoranthene [a]		965	33	11	ug/kg	SW846 8270D
Benzo(g,h,i)perylene [a]		284	33	12	ug/kg	SW846 8270D
Benzo(k)fluoranthene [a]		512	33	13	ug/kg	SW846 8270D
Chrysene [a]		1070	33	11	ug/kg	SW846 8270D
Dibenzo(a,h)anthracene [a]		118	33	11	ug/kg	SW846 8270D
Fluoranthene [a]		3210	33	15	ug/kg	SW846 8270D
Fluorene [a]		35.5	33	11	ug/kg	SW846 8270D
Indeno(1,2,3-cd)pyrene [a]		302	33	12	ug/kg	SW846 8270D
Phenanthrene [a]		1340	33	15	ug/kg	SW846 8270D
Pyrene [a]		2150	33	13	ug/kg	SW846 8270D
JB20289-3	**TRIB-C**					
Benzene		0.42 J	1.5	0.18	ug/kg	SW846 8260B
Acenaphthene [a]		22.3 J	34	10	ug/kg	SW846 8270D
Anthracene [a]		503	34	12	ug/kg	SW846 8270D
Benzo(a)anthracene [a]		1400	34	11	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		615	34	10	ug/kg	SW846 8270D
Benzo(b)fluoranthene [a]		806	34	11	ug/kg	SW846 8270D
Benzo(g,h,i)perylene [a]		281	34	13	ug/kg	SW846 8270D
Benzo(k)fluoranthene [a]		489	34	13	ug/kg	SW846 8270D
Chrysene [a]		1260	34	12	ug/kg	SW846 8270D
Dibenzo(a,h)anthracene [a]		116	34	12	ug/kg	SW846 8270D
Fluoranthene [a]		3910	69	30	ug/kg	SW846 8270D
Fluorene [a]		35.5	34	11	ug/kg	SW846 8270D
Indeno(1,2,3-cd)pyrene [a]		278	34	12	ug/kg	SW846 8270D
Phenanthrene [a]		1340	34	16	ug/kg	SW846 8270D
Pyrene [a]		2920	34	13	ug/kg	SW846 8270D
JB20289-4	**TRIB-D**					
Benzo(a)anthracene [a]		41.0	37	12	ug/kg	SW846 8270D
Benzo(a)pyrene [a]		18.1 J	37	11	ug/kg	SW846 8270D

Summary of Hits

Job Number: JB20289
Account: ERM, Inc.
Project: Tribune, Pinelawn Avenue, Melville, NY
Collected: 10/25/12

Lab Sample ID / Analyte	Client Sample ID	Result/ Qual	RL	MDL	Units	Method
Benzo(b)fluoranthene [a]		21.3 J	37	12	ug/kg	SW846 8270D
Chrysene [a]		33.4 J	37	13	ug/kg	SW846 8270D
Fluoranthene [a]		106	37	16	ug/kg	SW846 8270D
Phenanthrene [a]		26.2 J	37	17	ug/kg	SW846 8270D
Pyrene [a]		75.7	37	14	ug/kg	SW846 8270D

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

New Jersey ACCUTEST LABORATORIES

Sample Results

Report of Analysis

Report of Analysis

Client Sample ID: TRIB-A
Lab Sample ID: JB20289-1
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 98.0

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131253.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.3 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	0.96	0.11	ug/kg	
104-51-8	n-Butylbenzene	ND	4.8	0.11	ug/kg	
135-98-8	sec-Butylbenzene	ND	4.8	0.11	ug/kg	
98-06-6	tert-Butylbenzene	ND	4.8	0.28	ug/kg	
100-41-4	Ethylbenzene	ND	0.96	0.25	ug/kg	
98-82-8	Isopropylbenzene	ND	4.8	0.072	ug/kg	
99-87-6	p-Isopropyltoluene	ND	4.8	0.10	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	0.96	0.23	ug/kg	
91-20-3	Naphthalene	ND	4.8	0.12	ug/kg	
103-65-1	n-Propylbenzene	ND	4.8	0.11	ug/kg	
108-88-3	Toluene	ND	0.96	0.10	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	4.8	0.20	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	4.8	0.15	ug/kg	
	m,p-Xylene	ND	0.96	0.17	ug/kg	
95-47-6	o-Xylene	ND	0.96	0.13	ug/kg	
1330-20-7	Xylene (total)	ND	0.96	0.13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	104%		70-130%
17060-07-0	1,2-Dichloroethane-D4	91%		70-122%
2037-26-5	Toluene-D8	110%		81-127%
460-00-4	4-Bromofluorobenzene	103%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-A
Lab Sample ID: JB20289-1
Matrix: SO - Soil
Method: SW846 8270D SW846 3550C
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 98.0

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45391.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	34.0 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	ND	30	8.7	ug/kg	
208-96-8	Acenaphthylene	ND	30	9.6	ug/kg	
120-12-7	Anthracene	ND	30	11	ug/kg	
56-55-3	Benzo(a)anthracene	ND	30	9.8	ug/kg	
50-32-8	Benzo(a)pyrene	ND	30	9.2	ug/kg	
205-99-2	Benzo(b)fluoranthene	ND	30	10	ug/kg	
191-24-2	Benzo(g,h,i)perylene	ND	30	11	ug/kg	
207-08-9	Benzo(k)fluoranthene	ND	30	11	ug/kg	
218-01-9	Chrysene	ND	30	10	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	ND	30	10	ug/kg	
206-44-0	Fluoranthene	22.6	30	13	ug/kg	J
86-73-7	Fluorene	ND	30	9.8	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	ND	30	10	ug/kg	
91-20-3	Naphthalene	ND	30	8.2	ug/kg	
85-01-8	Phenanthrene	17.5	30	14	ug/kg	J
129-00-0	Pyrene	13.8	30	12	ug/kg	J

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	67%		21-122%
321-60-8	2-Fluorobiphenyl	58%		30-117%
1718-51-0	Terphenyl-d14	74%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-B
Lab Sample ID: JB20289-2
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 93.5

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131254.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.7 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	0.94	0.11	ug/kg	
104-51-8	n-Butylbenzene	ND	4.7	0.11	ug/kg	
135-98-8	sec-Butylbenzene	ND	4.7	0.11	ug/kg	
98-06-6	tert-Butylbenzene	ND	4.7	0.28	ug/kg	
100-41-4	Ethylbenzene	ND	0.94	0.25	ug/kg	
98-82-8	Isopropylbenzene	ND	4.7	0.070	ug/kg	
99-87-6	p-Isopropyltoluene	ND	4.7	0.098	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	0.94	0.22	ug/kg	
91-20-3	Naphthalene	ND	4.7	0.11	ug/kg	
103-65-1	n-Propylbenzene	ND	4.7	0.11	ug/kg	
108-88-3	Toluene	ND	0.94	0.099	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	4.7	0.20	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	4.7	0.15	ug/kg	
	m,p-Xylene	ND	0.94	0.16	ug/kg	
95-47-6	o-Xylene	ND	0.94	0.13	ug/kg	
1330-20-7	Xylene (total)	ND	0.94	0.13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	105%		70-130%
17060-07-0	1,2-Dichloroethane-D4	92%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	103%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-B
Lab Sample ID: JB20289-2
Matrix: SO - Soil
Method: SW846 8270D SW846 3550C
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 93.5

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45392.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	32.1 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	22.7	33	9.7	ug/kg	J
208-96-8	Acenaphthylene	ND	33	11	ug/kg	
120-12-7	Anthracene	490	33	12	ug/kg	
56-55-3	Benzo(a)anthracene	1060	33	11	ug/kg	
50-32-8	Benzo(a)pyrene	497	33	10	ug/kg	
205-99-2	Benzo(b)fluoranthene	965	33	11	ug/kg	
191-24-2	Benzo(g,h,i)perylene	284	33	12	ug/kg	
207-08-9	Benzo(k)fluoranthene	512	33	13	ug/kg	
218-01-9	Chrysene	1070	33	11	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	118	33	11	ug/kg	
206-44-0	Fluoranthene	3210	33	15	ug/kg	
86-73-7	Fluorene	35.5	33	11	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	302	33	12	ug/kg	
91-20-3	Naphthalene	ND	33	9.1	ug/kg	
85-01-8	Phenanthrene	1340	33	15	ug/kg	
129-00-0	Pyrene	2150	33	13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	70%		21-122%
321-60-8	2-Fluorobiphenyl	64%		30-117%
1718-51-0	Terphenyl-d14	77%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-C
Lab Sample ID: JB20289-3
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 85.1

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131255.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	3.8 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	0.42	1.5	0.18	ug/kg	J
104-51-8	n-Butylbenzene	ND	7.7	0.17	ug/kg	
135-98-8	sec-Butylbenzene	ND	7.7	0.18	ug/kg	
98-06-6	tert-Butylbenzene	ND	7.7	0.45	ug/kg	
100-41-4	Ethylbenzene	ND	1.5	0.41	ug/kg	
98-82-8	Isopropylbenzene	ND	7.7	0.11	ug/kg	
99-87-6	p-Isopropyltoluene	ND	7.7	0.16	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	1.5	0.36	ug/kg	
91-20-3	Naphthalene	ND	7.7	0.19	ug/kg	
103-65-1	n-Propylbenzene	ND	7.7	0.18	ug/kg	
108-88-3	Toluene	ND	1.5	0.16	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	7.7	0.32	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	7.7	0.25	ug/kg	
	m,p-Xylene	ND	1.5	0.27	ug/kg	
95-47-6	o-Xylene	ND	1.5	0.21	ug/kg	
1330-20-7	Xylene (total)	ND	1.5	0.21	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	106%		70-130%
17060-07-0	1,2-Dichloroethane-D4	96%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	104%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range

J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-C		
Lab Sample ID:	JB20289-3	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8270D SW846 3550C	**Percent Solids:**	85.1
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45393.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2 [a]	3E45398.D	2	11/08/12	OYA	11/07/12	OP61052	E3E1976

	Initial Weight	Final Volume
Run #1	34.2 g	1.0 ml
Run #2	34.2 g	1.0 ml

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	22.3	34	10	ug/kg	J
208-96-8	Acenaphthylene	ND	34	11	ug/kg	
120-12-7	Anthracene	503	34	12	ug/kg	
56-55-3	Benzo(a)anthracene	1400	34	11	ug/kg	
50-32-8	Benzo(a)pyrene	615	34	10	ug/kg	
205-99-2	Benzo(b)fluoranthene	806	34	11	ug/kg	
191-24-2	Benzo(g,h,i)perylene	281	34	13	ug/kg	
207-08-9	Benzo(k)fluoranthene	489	34	13	ug/kg	
218-01-9	Chrysene	1260	34	12	ug/kg	
53-70-3	Dibenzo(a,h)anthracene	116	34	12	ug/kg	
206-44-0	Fluoranthene	3910 [b]	69	30	ug/kg	
86-73-7	Fluorene	35.5	34	11	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	278	34	12	ug/kg	
91-20-3	Naphthalene	ND	34	9.4	ug/kg	
85-01-8	Phenanthrene	1340	34	16	ug/kg	
129-00-0	Pyrene	2920	34	13	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	61%	59%	21-122%
321-60-8	2-Fluorobiphenyl	56%	60%	30-117%
1718-51-0	Terphenyl-d14	73%	84%	31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.
(b) Result is from Run# 2

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID: TRIB-D
Lab Sample ID: JB20289-4
Matrix: SO - Soil
Method: SW846 8260B SW846 5035
Project: Tribune, Pinelawn Avenue, Melville, NY

Date Sampled: 10/25/12
Date Received: 10/26/12
Percent Solids: 85.9

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1	O131256.D	1	11/06/12	DPP	10/27/12 11:00	n/a	VO5784
Run #2							

	Initial Weight
Run #1	5.4 g
Run #2	

VOA STARS List

CAS No.	Compound	Result	RL	MDL	Units	Q
71-43-2	Benzene	ND	1.1	0.13	ug/kg	
104-51-8	n-Butylbenzene	ND	5.4	0.12	ug/kg	
135-98-8	sec-Butylbenzene	ND	5.4	0.12	ug/kg	
98-06-6	tert-Butylbenzene	ND	5.4	0.32	ug/kg	
100-41-4	Ethylbenzene	ND	1.1	0.28	ug/kg	
98-82-8	Isopropylbenzene	ND	5.4	0.080	ug/kg	
99-87-6	p-Isopropyltoluene	ND	5.4	0.11	ug/kg	
1634-04-4	Methyl Tert Butyl Ether	ND	1.1	0.25	ug/kg	
91-20-3	Naphthalene	ND	5.4	0.13	ug/kg	
103-65-1	n-Propylbenzene	ND	5.4	0.13	ug/kg	
108-88-3	Toluene	ND	1.1	0.11	ug/kg	
95-63-6	1,2,4-Trimethylbenzene	ND	5.4	0.23	ug/kg	
108-67-8	1,3,5-Trimethylbenzene	ND	5.4	0.17	ug/kg	
	m,p-Xylene	ND	1.1	0.19	ug/kg	
95-47-6	o-Xylene	ND	1.1	0.15	ug/kg	
1330-20-7	Xylene (total)	ND	1.1	0.15	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
1868-53-7	Dibromofluoromethane	105%		70-130%
17060-07-0	1,2-Dichloroethane-D4	93%		70-122%
2037-26-5	Toluene-D8	112%		81-127%
460-00-4	4-Bromofluorobenzene	104%		66-132%

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range

J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

Report of Analysis

Client Sample ID:	TRIB-D		
Lab Sample ID:	JB20289-4	**Date Sampled:**	10/25/12
Matrix:	SO - Soil	**Date Received:**	10/26/12
Method:	SW846 8270D SW846 3550C	**Percent Solids:**	85.9
Project:	Tribune, Pinelawn Avenue, Melville, NY		

	File ID	DF	Analyzed	By	Prep Date	Prep Batch	Analytical Batch
Run #1 [a]	3E45394.D	1	11/08/12	OYA	11/07/12	OP61052	E3E1976
Run #2							

	Initial Weight	Final Volume
Run #1	31.2 g	1.0 ml
Run #2		

BN PAH List

CAS No.	Compound	Result	RL	MDL	Units	Q
83-32-9	Acenaphthene	ND	37	11	ug/kg	
208-96-8	Acenaphthylene	ND	37	12	ug/kg	
120-12-7	Anthracene	ND	37	13	ug/kg	
56-55-3	Benzo(a)anthracene	41.0	37	12	ug/kg	
50-32-8	Benzo(a)pyrene	18.1	37	11	ug/kg	J
205-99-2	Benzo(b)fluoranthene	21.3	37	12	ug/kg	J
191-24-2	Benzo(g,h,i)perylene	ND	37	14	ug/kg	
207-08-9	Benzo(k)fluoranthene	ND	37	14	ug/kg	
218-01-9	Chrysene	33.4	37	13	ug/kg	J
53-70-3	Dibenzo(a,h)anthracene	ND	37	13	ug/kg	
206-44-0	Fluoranthene	106	37	16	ug/kg	
86-73-7	Fluorene	ND	37	12	ug/kg	
193-39-5	Indeno(1,2,3-cd)pyrene	ND	37	13	ug/kg	
91-20-3	Naphthalene	ND	37	10	ug/kg	
85-01-8	Phenanthrene	26.2	37	17	ug/kg	J
129-00-0	Pyrene	75.7	37	14	ug/kg	

CAS No.	Surrogate Recoveries	Run# 1	Run# 2	Limits
4165-60-0	Nitrobenzene-d5	71%		21-122%
321-60-8	2-Fluorobiphenyl	66%		30-117%
1718-51-0	Terphenyl-d14	90%		31-129%

(a) Storage temperature exceeded 6 degrees C due to power outage from the tropical cyclone of Oct. 29th and 30th, 2012.

ND = Not detected MDL = Method Detection Limit
RL = Reporting Limit
E = Indicates value exceeds calibration range
J = Indicates an estimated value
B = Indicates analyte found in associated method blank
N = Indicates presumptive evidence of a compound

New Jersey ACCUTEST LABORATORIES

Misc. Forms

Custody Documents and Other Forms

Includes the following where applicable:

- Chain of Custody

ACCUTEST LABORATORIES

CHAIN OF CUSTODY

2235 Route 130, Dayton, NJ 08810
Tel: 732-329-0200 FAX: 732-329-3499/3480
www.accutest.com

PAGE ___ OF ___

FED-EX Tracking #: | Bottle Order Control #:
Accutest Quote #: | Accutest Job #: JB20289

Client / Reporting Information

Company Name: ERM
Street Address: 40 MARCUS DR STE 200
City: MELVILLE State: NY Zip: 11747
Project Contact: EUGENE.GABAY@ERM.COM E-mail:
Phone #: 631 756 8900 Fax #: 8901
Sampler(s) Name(s): MADDOX Phone #:

Project Information

Project Name: TRIBUNE
Street: 235 PINELAWN
City: MELVILLE State: NY
Project #: 0177133
Client Purchase Order #:
Project Manager: GENE GABAY

Billing Information (if different from Report to)

Company Name:
Street Address:
City: State: Zip:
Attention:

Requested Analysis (see TEST CODE sheet)

Matrix Codes
DW - Drinking Water
GW - Ground Water
WW - Water
SW - Surface Water
SO - Soil
SL- Sludge
SED-Sediment
OI - Oil
LIQ - Other Liquid
AIR - Air
SOL - Other Solid
WP - Wipe
FB-Field Blank
EB-Equipment Blank
RB- Rinse Blank
TB-Trip Blank

Accutest Sample #	Field ID / Point of Collection	MEOH/DI Vial #	Collection Date	Collection Time	Sampled by	Matrix	# of bottles	Preserved: HCl	NaOH	HNO3	H2SO4	NONE	DI Water	MEOH	ENCORE	8260	8270	% Solids	LAB USE ONLY
-1	TRIB-A		10/25/12	1320	JMX	S	5					5				3	1	1	
-2	TRIB-B			1328			5					5				3	1	1	
-3	TRIB-C			1334			5					5				3	1	1	UPC16
-4	TRIB-D			1340			5					5				3	1	1	0068
																			1401
																			4074

Turnaround Time (Business days)

- [X] Std. 15 Business Days
- [ ] Std. 10 Business Days (by Contract only)
- [ ] 10 Day *RUSH*
- [ ] 5 Day *RUSH*
- [ ] 3 Day *EMERGENCY*
- [ ] 2 Day *EMERGENCY*
- [ ] 1 Day *EMERGENCY*

Emergency & Rush T/A data available VIA Lablink

Approved By (Accutest PM): / Date:

Data Deliverable Information

- [ ] Commercial "A" (Level 1)
- [ ] Commercial "B" (Level 2)
- [ ] FULLT1 (Level 3+4)
- [ ] NJ Reduced
- [ ] Commercial "C"
- [ ] NYASP Category A
- [X] NYASP Category B
- [ ] State Forms
- [ ] EDD Format
- [ ] Other

Commercial "A" = Results Only
Commercial "B" = Results + QC Summary
NJ Reduced = Results + QC Summary + Partial Raw data

Comments / Special Instructions

3 ENCORES @ 10/26/12

Sample Custody must be documented below each time samples change possession, including courier delivery.

Relinquished by Sampler: 1	Date Time: 10/26/12 1030	Received By: 1	Relinquished By: 2	Date Time: 1745 10/26/12	Received By: 2
Relinquished by Sampler: 3	Date Time:	Received By: 3	Relinquished By: 4	Date Time:	Received By: 4
Relinquished by: 5	Date Time:	Received By: 5	Custody Seal # 372 [X] Intact [ ] Not intact	Preserved where applicable [ ]	On Ice [X] Cooler Temp. 3°C

5.1 5

JB20289: Chain of Custody
Page 1 of 3

Accutest Laboratories Sample Receipt Summary

Accutest Job Number: JB20289 **Client:** **Project:**

Date / Time Received: 10/26/2012 **Delivery Method:** **Airbill #'s:**

Cooler Temps (Initial/Adjusted): #1: (3/3); 0

Cooler Security	Y	or	N		Y	or	N
1. Custody Seals Present:	☑		☐	3. COC Present:	☑		☐
2. Custody Seals Intact:	☑		☐	4. Smpl Dates/Time OK	☑		☐

Cooler Temperature	Y	or	N
1. Temp criteria achieved:	☑		☐
2. Cooler temp verification:	Bar Therm		
3. Cooler media:	Ice (Bag)		
4. No. Coolers:	1		

Quality Control Preservation	Y	or	N	N/A
1. Trip Blank present / cooler:	☐		☑	☐
2. Trip Blank listed on COC:	☐		☑	☐
3. Samples preserved properly:	☑		☐	
4. VOCs headspace free:	☐		☐	☑

Sample Integrity - Documentation	Y	or	N
1. Sample labels present on bottles:	☑		☐
2. Container labeling complete:	☑		☐
3. Sample container label / COC agree:	☑		☐

Sample Integrity - Condition	Y	or	N
1. Sample recvd within HT:	☑		☐
2. All containers accounted for:	☑		☐
3. Condition of sample:	Intact		

Sample Integrity - Instructions	Y	or	N	N/A
1. Analysis requested is clear:	☑		☐	
2. Bottles received for unspecified tests	☐		☑	
3. Sufficient volume recvd for analysis:	☑		☐	
4. Compositing instructions clear:	☐		☐	☑
5. Filtering instructions clear:	☐		☐	☑

Comments

ACCUTEST LABORATORIES

Subject: Sample Storage – Tropical Storm

Date: November 2, 2012

To: Valued Clients

From: Phillip M. Worby
Director, Corporate Quality Assurance

As a result of the extraordinary damage from the Tropical Storm that hit the East Coast late Monday evening October 29, 2012, Accutest Laboratories Dayton, New Jersey had to temporarily suspend analytical operations until power could be restored.

While the laboratory did not sustain any physical damage, it was left without power as utility companies assessed the overall damage caused by the storm and as they continue restore power throughout the state.

Accutest Laboratories has endeavored to minimize the impact of the storm on lab operations. To that end, extra staff was brought in before the storm to work ahead and secure the building. After the storm, as soon as it was possible to safely bring staff in, external generators were put in place on storage refrigeration units to help maintain sample integrity in accordance with preservation requirements set by either the regulatory program or method specification.

Despite our efforts and planning, a storage temperature excursion above 6 degrees C. has been noted and documented. The affected analyte and/or test method is qualified in accordance with our quality system procedures and is indicated in the report.

To our valued clients, we appreciate your patience and understanding during this difficult period, and hope that your recovery efforts are also moving forward. We stand ready to help you with any and all sample needs as a result of this powerful storm.

JB20289: Chain of Custody
Page 3 of 3

APPENDIX C
SCDOHS ABANDONMENT
REQUEST AND APPLICATION

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES
APPLICATION FOR
CLOSURE OF UNDERGROUND STORAGE TANKS

Check #0a3095 $200.00

OFFICIAL USE ONLY	File Reference Number	Facility Id. Number
	0 2 , 0 3 7	4 6 0 9 4

Fac. Code	Rank	Sic Code	Hydro Zone	Article 7 Restricted	M U N	A # # #	Insp. Zone	Multi-Occupied Building

Latitude Deg Min Sec	Longitude Deg Min Sec	PBS Reg	EPA Reg	Type of Petroleum Facility	Owner Type

Property Tax Map Number District 0400 Section 270 Block 100 Lot 241

Facility Name: Newsday Inc.

Physical Address	Community	State	Zip
235 Pinelawn Road	Melville	NY	11747

Property Owner's Name	Phone Number	Fax Number
Tribune Company	626-808-5728	

Mailing Address	Community	State	Zip
435 N. Michigan Avenue	Chicago	IL	60611

Contact Person	E-mail Address
Mark Anderson	manderson@tribune.com

Consultant/Agent (if applicable)	Phone Number	Fax Number
ERM	631-756-8900	

Mailing Address	Community	State	Zip
105 Maxess Road- Suite 316	Melville	NY	11747

Contact Person	E-mail Address
Eugene Gabay	eugene.gabay@erm.com

For **Abandonment Requests**, describe why that the tank(s) **cannot** be removed and provide supporting documentation (List **all** tanks to be removed and abandoned on the back of this form)

RECEIVED
JUL 5 2013
SUFFOLK COUNTY HEALTH SERVICES
Office of Pollution Control

I Certify that all information supplied hereon and in all attachments is true to the best of my knowledge.

Applicant Signature: _____ Print Name: Eugene Gabay Date: 6/26/13

☑ Abd. Request Approved ☐ Abd. Request Denied Date: 9/13/2013 Processed By: _____

See reverse side for required additional information.

Tank Information

Enter Information for all tank(s) to be removed or abandoned, below*:

SCDHS Tank #	Volume	Contents	Disposition (circle one)
SCDHS-6	25,000 gal	No. 2 Fuel Oil	Rem / Abd
SCDHS-7	25,000 gal	No. 2 Fuel Oil	Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd
			Rem / Abd

*if additional space is needed, attach addendum.

Instructions

For All Requests, submit the following:

1. A site plan showing the location of the tank(s) as well as utilities and other structures that may interfere with removal. A sketch is acceptable with the initial application but a more detailed site plan may be required by the Department.

2. A check, per SCHDS Fee Schedule. $100/tank
3. Return the application to the address listed below. You will be contacted to schedule an appointment

For Abandonment Requests, in addition to the above, provide a submittal that includes the following:

1. For requests based upon Utility Infringement, provide diagram and photographs of the mark outs. Photos must indicate tank location.
2. For requests based upon Building Infringement, provide:
   (a) Burial depth of tank. Measure from grade to top of tank.
   (b) Distance of tank center line to any adjacent structure.
   (c) Diameter of tank.
   (d) Depth below grade of footings supporting the adjacent structure(s)
3. Diagrams and Photographic evidence of any other item(s) that are claimed to prevent removal of any tank.

If you have questions, call 854-2536

Submit all Information to:
Suffolk County Department of Health Services
15 Horseblock Pl.
Farmingville, NY 11738

COUNTY OF SUFFOLK

STEVEN BELLONE
SUFFOLK COUNTY EXECUTIVE

DEPARTMENT OF HEALTH SERVICES

JAMES L. TOMARKEN, MD
MSW, MPH, MBA, FRCPC, FACP
Commissioner

September 6, 2013

ERM
105 Maxess Road, Suite 316
Melville, NY 11747

Attn: Eugene Gabay

Re: **Application for In Place - Permanent Closure of Underground Storage Tank**
Facility Name: Newsday Inc.
File Reference No. 02037
Facility I.D. No. 4-0094

Dear Mr. Gabay:

Your application for in place permanent closure of underground storage tank is under review process and you are required to submit following information:

1. Provide a site plan to indicate the location and depth of any underground structures, such as septic tanks, leaching pools, storm drains, and dry wells, within 50' radius of the tank.
2. You are required to perform site assessment as pre NYS DEC S.P.O.T.S. 14 which pump out, clean and vapor free the Tank #7. You need to take 8 soil samples through the bottom of the Tank #7, 4' and 8' below tank bottom respectively and each sample must pass STARS 8620/8270 analysis in approved laboratory.

If you have any questions, please feel free to contact our office.

Sincerely,

Chris Wong
Assistant Public Health Engineer
Bureau of Environmental Engineering

Public Health
Prevent. Promote. Protect.

DIVISION OF ENVIRONMENTAL QUALITY
Office of Pollution Control, 15 Horseblock Place, Farmingville, NY 11738
Phone (631) 854-2502 Fax (631) 854-2505

COUNTY OF SUFFOLK

STEVEN BELLONE
SUFFOLK COUNTY EXECUTIVE

DEPARTMENT OF HEALTH SERVICES

JAMES L. TOMARKEN, MD
MSW, MPH, MBA, FRCPC, FACP
Commissioner

September 13, 2013

ERM
105 Maxes Road, Suite 316
Melville, NY 11747

Attn: Eugene Gabay

Re: **Application for In Place - Permanent Closure of Underground Storage Tank**
Facility Name: Newsday Inc.
File Reference No. 02037
Facility I.D. No. 4-0094

Dear Mr. Gabay:

Your application for in place permanent closure of underground storage tank is approved for following tank(s)

Tank #	Volume	Contents	Disposition
6	25,000 Gals.	#2 Fuel Oil	Abandonment
7	25,000 Gals.	#2 Fuel Oil	Abandonment

The Office of Pollution Control must be contacted at (631)854-2523 at least 2 business days prior to commencement of any work to arrange for the required inspections.

Contact the local building department and/or fire safety enforcement office for any additional requirements that may apply to your project.

The Office of Pollution Control reserves the right to revoke this permit as allowable by law.

Special Condition(s): Tanks must be filled with concrete slurry or clean sand.

If you have any questions, please feel free to contact our office.

Sincerely,

Chris Wong
Assistant Public Health Engineer
Bureau of Environmental Engineering

Public Health
Prevent. Promote. Protect.

DIVISION OF ENVIRONMENTAL QUALITY
Office of Pollution Control, 15 Horseblock Place, Farmingville, NY 11738
Phone (631) 854-2502 Fax (631) 854-2505

APPENDIX D
BILLS OF LADING

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542307

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
58.02	19.19	39.03	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	7:09		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 39.03
LOADS THIS ORDER TODAY 1

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542313

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
58.02	19.19	39.83	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	7:09		AE47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 78.86
LOADS THIS ORDER TODAY 2

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

110 Sand Company

170 Cabot Street
West Babylon, New York 11704

CUSTOMER COPY

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542323

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
59.13	19.19	39.94	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	13:54	AE	47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 118.80
LOADS THIS ORDER TODAY 3

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

170 Cabot Street
West Babylon, New York 11704

CUSTOMER COPY

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3319	SHIPPING		010021	542326

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED B
59.02	19.19	39.83	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/20/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	14:31	AE	47774211

MATERIAL DESCRIPTION:
PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 158.63
LOADS THIS ORDER TODAY 4

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#19

CUSTOMER SIGNATURE

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542349

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
69.80	19.42	40.38	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

MATERIAL DESCRIPTION: PROCESSED FILL (A)

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	8:42		

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY	
QUANTITY THIS ORDER TODAY	40.38
LOADS THIS ORDER TODAY	1

OFFICE USE ONLY

RECEIVED BY:
BROMAN#26

CARRIER SIGNATURE _____

CUSTOMER SIGNATURE _____

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542358

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
60.32	19.42	40.90	TONS	JDW

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	9:28		

MATERIAL DESCRIPTION: PROCESSED FILL (A)

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 81.20
LOADS THIS ORDER TODAY 2

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#26

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
12650		3326	SHIPPING		010021	542360

CUSTOMER NAME:
BROMAN & SON, INC.

GROSS	TARE	NET	UNIT	WEIGHED BY
59.77	19.42	40.35	TONS	CAR

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14			140

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	10:04		

MATERIAL DESCRIPTION: PROCESSED FILL (A)

119540 1.8

DELIVERY ADDRESS
TANK SAND

TOTAL TODAY
QUANTITY THIS ORDER TODAY 121.63
LOADS THIS ORDER TODAY 3

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE BROMAN#26

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

110 Sand Company

CUSTOMER COPY

170 Cabot Street
West Babylon, New York 11704

TELEPHONES
Office - 631-249-4108
Scalehouse - 631-694-2822
Landfill - 631-694-2848

CUSTOMER NO.	P.O. NUMBER	TRUCK NO.	TYPE OF SALE	JOB NO.	OUR ORDER NUMBER	TICKET NO.
010001		8674	SHIPPING		012130	542375

CUSTOMER NAME: ENV-14Y

MATERIAL SALE - CHECK

GROSS	TARE	NET	UNIT	WEIGHED BY
27.27	11.02	16.25	TONS	CAK

DATE	TAX PERCENTAGE	TRUCK CODE	MATERIAL CODE
3/21/14	Y		13

IN	OUT	CHECK NO./CHARGE TYPE	LICENSE NO.
	11:53		8674JU

MATERIAL DESCRIPTION: SAND (A) 10-34F

DELIVERY ADDRESS

TOTAL TODAY

QUANTITY THIS ORDER TODAY

LOADS THIS ORDER TODAY

OFFICE USE ONLY

RECEIVED BY:

CARRIER SIGNATURE

CUSTOMER SIGNATURE

SEE REVERSE SIDE FOR COLLECTION TERMS

SEVILLE CENTRAL MIX, CORP.

SEVILLE CENTRAL MIX CORP.

MAILING ADDRESS:
157 ALBANY AVENUE
FREEPORT, N.Y. 11520

OLD BETHPAGE 293-6190 | HOLTSVILLE 293-6190 | CEDARHURST 239-8333

AUTHORIZATION TO ADD WATER
BY: _____
_____ GAL. WATER ADDED
The seller will not assume any responsibility for strength of concrete if water is added to the concrete on the job by the purchaser.

PLANT CODE	CENTRAL MIX	TRUCK MIX	PICK-UP	DELIVERY	SLUMP	TICKET REF. NO.
W1-20168					3.5	63370

ORDER # 600

DATE	DRIVER	TRUCK NO.	JOB NO.	ACCOUNT NO.
3/25/2014	Daniel16 D.	48		CODE

_____ HRS.
_____ MINS

SOLD TO
METRO ENVIRONMENTAL

GARY 516-216-0025
DASHON DR. TO GOLD BOOTH

SHIPPED TO
JOB #
NEWSDAY-MELVILLE/PINELAWN RD

PRODUCT NO.	DESCRIPTION	UNIT	QUANTITY	UNIT PRICE	AMOU
40A61	4000# STONE COMMERCIAL	CY	5.00		
W/C	WINTER CONCRETE	/Y	5.00		
PLC	PART LOAD CHARGE	/1	1.00		

CONTROLLED CONCRETE
WEIGHTS PER YD.

CEMENT _____ LBS.
COARSE AGG _____ LBS.
_____ LBS.
FINE AGG _____ LBS.
_____ GALS WATER/YD

ADMIXTURE

TO PRODUCE _____ LB. CONCRETE

TOTAL ORDERED	YARDS TO DAY	COLLECT GRAND TOTAL	SUB TOTAL
5.00	5.00		TAX
REC'D BY		ALLOWABLE TIME	TOTAL

SLIP NO
W 33

NOT RESPONSIBLE FOR VARIANCE IN COLOR
SUBJECT TO CONDITIONS ON REVERSE SIDE

CAUTION!—FRESHLY MIXED CEMENT, MORTAR, GROUT OR CONCRETE MAY CAUSE A SEVERE SKIN IRRITATION AND BURNS ON INDIVIDUALS WITH SENSITIVE SKIN. AVOID DIRECT CONTACT WITH SKIN IF POSSIBLE AND WASH EXPOSED SKIN AREAS PROMPTLY WITH WATER. IF ANY OF THESE MATERIALS GET INTO THE EYE, RINSE IMMEDIATELY AND REPEATEDLY WITH WATER AND GET PROMPT MEDICAL ATTENTION. KEEP CEMENT AND FRESHLY MIXED CEMENT PRODUCTS OUT OF THE REACH OF CHILDREN.

APPENDIX E
SCDOHS TANK REMOVAL CHECKLIST

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES
DIVISION OF ENVIRONMENTAL QUALITY
OFFICE OF POLLUTION CONTROL

TANK REMOVAL CHECKLIST

FILE REF NO: 02637 REG NO: 4-0094 DATE: 2/20/2014
FACILITY NAME: NEWSDAY
FACILITY ADDRESS: 235 PINELAWN RD MELVILLE
SCTM# 400-270-2-1 SITE GPS
400-270-1-24.1

TANK #	LOCATION	CAPACITY	CONTENTS	MATERIAL
6	UPRIGHT	25000	#2 FUEL OIL	PLW STL
7	INSIDE OUT	25000	#2 FUEL OIL	PLW STL


1. CONDITION OF TANK AND PIPING: (Note any holes) CLEAN W/L LIQUIDS AND SLUDGES REMOVED

2. WAS CONTAMINATION NOTED WITHIN EXCAVATION? ~~Y~~ / N
   All Material Removed Under SCDHS Supervision: ~~Y~~ / N
   Approximate Amount Of Contaminated Soil Removed: X cu yds / tons / drums
   Was Ground Water Impacted: Y / (N)
   DEC Notified: (Y) / N *(1-800-457-7362)* DEC Spill Number: 1203029

3. WERE ALL ASSOCIATED PIPES AND VENT LINES REMOVED? (Y) / N (If No, explain)

4. NAME OF CONTRACTOR: ERM SUB: METRO

Site Sketch:



A Copy of This Document Was Given to: Bill Smith
(Owner's Representative)

Inspector: MICHAEL SEAMAN Inspector's Signature:

OFFICE USE:	
SCDHS Spill Number:	Spills Key:

APPENDIX F
PHOTOLOG



Photograph: *1*	*Saw cuts and jack hammered concrete on top of UST #6 and #7*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *2*	*Excavated debris from the saw cut holes on top of UST #6 and #7*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *3*	*UST #6 center hole after it was cleaned out*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *4*	*UST #6 eastern hole prior to backfilling with sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *5*	*UST #7 western hole prior to backfilling with sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *6*	*UST #7 eastern hole prior to backfilling with sand*	
Tribune Company	***ERM***	*285 Pinelawn Road* *Melville, NY*



Photograph: 7	End of work day all of the holes were secured with plywood, 2x4s and caution tape	
Tribune Company	**ERM**	235 Pinelawn Road Melville, NY



Photograph: 8	UST #6 being backfilled with clean sand	
Tribune Company	**ERM**	235 Pinelawn Road Melville, NY



Photograph: *9*	*UST #7 being backfilled with clean sand*	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *10*	Vent lines filled with concrete	
Tribune Company	***ERM***	*235 Pinelawn Road* *Melville, NY*



Photograph: *11*	*Tank excavations ready for concrete*	
Tribune Company	***ERM***	*235 Pinelawn Melville, NY*



Photograph: *12*	*Excavations restored to original condition*	
Tribune Company	***ERM***	*235 Pinelawn Melville, NY*

APPENDIX G
WASTE MANIFESTS

13-946 ✓

Con Strux - Lindenhurst
690 Muncy Avenue
Lindenhurst, NY 11757
Phone: (631) 669-3133

Customer: METR01
METRO ENVIRONMENTAL
690 A. NORTH QUEENS AVE
N.Y. NY 11757
631-884-1880
P/O:

Ship To:

Drw # 1
54889
Sls #
User SML
03/19/14
09:36

ITEM#	QTY	PRICE
D2	10	
CLEAN CONCRETE	CU	

Cash	*0.00*	Sub-Total	
Ccd		Disc	0.00
Check	*0.00*	Freight	0.00
Gft/Cpns/Fst	*0.00*	Tax (SUFF)	0.00
Store Credit	*0.00*	**TOTAL**	
Bill To A/R	*0.00*	Change Due	0.00

Auth# 04191G

METRO ENVIRONMENTAL

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N / A

Manifest Document No.: 3 8 9 2 1

2. Page 1 of 1

3. Generator's Name and Mailing Address
Tribune
435 N. Michigan Avenue
Chicago, IL 60611

Newsday-235 Pinelawn Road
Melville, NY 11747

4. Generator's Phone (631) 843-2000

5. Transporter 1 Company Name: Metro Environmental Contracting

6. US EPA ID Number: N Y R 0 0 0 1 3 4 9 5 7

A. State Transporter's ID

B. Transporter 1 Phone: (631)884-1880

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Advanced Waste & Water Technology,
208 Route 109
Farmingdale, NY 11735

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone: (631)249-3774

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oily Water Non-DOT Regulated Material	1	TT	100	G
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Stephen Zimmerman | Signature | Date: Month 3 Day 17 Year 14

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Keith Boncke | Signature | Date: Month 3 Day 17 Year 14

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Chris Brown | Signature | Date: Month 3 Day 18 Year 14

NON-HAZARDOUS WASTE

F-14 © 2002 LABELMASTER® (800) 621-5808 www.labelmaster.com

PRINTED WITH SOY INK

Rev. 3/95

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N/A

Manifest Document No.: 032014-01

2. Page 1 of 1

3. Generator's Name and Mailing Address
Tribune
435 N. Michigan Ave
Chicago, IL 60611
4. Generator's Phone (631) 843-2000

Newsday - 235 Pinelawn Rd
Melville, NY 11747

5. Transporter 1 Company Name: Metro Environmental Contracting
6. US EPA ID Number: NYR000134957
A. State Transporter's ID
B. Transporter 1 Phone: 631-884-1880

7. Transporter 2 Company Name
8. US EPA ID Number
C. State Transporter's ID
D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Advanced Waste Water Technology
208 Route 109
Farmingdale NY 11735
10. US EPA ID Number
E. State Facility's ID
F. Facility's Phone: 631-249-3774

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oily Water Non-DOT Regulated Material	1	TT	200	G
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Steve Ammerman
Signature:
Date: Month 3 Day 21 Year 14

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Keith Baucke
Signature:
Date: Month 3 Day 21 Year 14

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Jim Kidney
Signature: Jim Kidney
Date: Month 3 Day 21 Year 14

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: N / A

Manifest Document No.: 38922

2. Page 1 of 1

3. Generator's Name and Mailing Address
Tribune
435 N. Michigan Avenue
Chicago, IL 60611

4. Generator's Phone (631) 843-2000

Newsday-235 Pinelawn Road
Melville, NY 11747

5. Transporter 1 Company Name: Metro Environmental Contracting

6. US EPA ID Number: NYR000134957

A. State Transporter's ID

B. Transporter 1 Phone: (631)884-1880

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Republic Environmental Systems
2869 Sandstone Drive
Hatfield, PA 19440

10. US EPA ID Number: PAD085690592

E. State Facility's ID

F. Facility's Phone: (215)822-8995

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Oil Tank Bottoms Non-DOT Regulated Material	1	DM	100	~~LBS~~ (P) RQ
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
11a) 635017
Doc#

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Stephen Zimmerman
Signature:
Date: Month 3 Day 17 Year 14

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Matthew S. Copeland
Signature:
Date: Month 03 Day 17 Year 14

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.
Printed/Typed Name
Signature
Date: Month Day Year

NON-HAZARDOUS WASTE

New York State Department of Environmental Conservation
Spill Prevention and Response, Region One Headquarters
50 Circle Road - SUNY
Stony Brook, NY 11790-3409
Phone: (631) 444-0323 • FAX: (631) 444-0328
Website: http://www.dec.ny.gov

Joe Martens
Commissioner

April 7, 2014

Rita DeBoer
Assistant General Counsel
Tribune Company
435 N. Michigan Avenue, 6th Floor
Chicago, IL 60611

Re: Spill #12-03029, Newsday, 235 Pinelawn Rd., Melville, NY

Dear Ms. DeBoer:

The Department has reviewed the records and data submitted by you regarding the tank test failure at the above referenced site. Based on such review, the Department determined that you have completed all necessary actions, and no further activities are necessary.

Nothing contained herein shall be construed as barring, diminishing, or in any way limiting Department's authority under the Navigation Law or the Environmental Conservation Law, including the authority to require additional remedial work, if necessary.

Should you have any questions concerning this matter, you may call me at (631) 444-0324 or e-mail me at hmcirrit@gw.dec.state.ny.us.

Sincerely,
Hugh Cirrito

Hugh Cirrito, PE
Environmental Engineer 2

cc: K. Gomez, NYSDEC

Multiple files are bound together in this PDF Package.

Adobe recommends using Adobe Reader or Adobe Acrobat version 8 or later to work with documents contained within a PDF Package. By updating to the latest version, you'll enjoy the following benefits:

- Efficient, integrated PDF viewing
- Easy printing
- Quick searches

Don't have the latest version of Adobe Reader?

Click here to download the latest version of Adobe Reader

If you already have Adobe Reader 8, click a file in this PDF Package to view it.

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1205313

SPILL NAME: NEWSDAY **DEC LEAD:** wxprzylo

SPILL DATE: 08/26/2012 **SPILL TIME:** 1:30 am

CALL RECEIVED DATE: 08/26/2012 **RECEIVED TIME:** 1:13 pm

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN RD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOE MARINO **CONTACT PHONE:** (516) 509-0495

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

on concrete to inside bld. c/u in progrss, ,Miller Enviro on site

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
other	Other	2,000 G		Imp Surf

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN RD MELVILLE NY	JOE MARINO (516) 509-0495

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

08/26/12 @13:20 t/c to notifier, by Mr Marino there was broken ink feeding tube on printing machine. MEG is working on cleanup. All is contained to the printing shop, no floor drains affected or odors outside of the building. (VP)

PIN **T & A** **COST CENTER**

CLASS: D4 **CLOSE DATE:** 10/03/2012 **MEETS STANDARDS:** False

NYSDEC Region 1, SUNY at Stony Brook, 50 Circle Rd., Stony Brook, NY 11790-3409

Site Notes

Spill Number: 14-02877

Representatives:

Steve Zimmerman - Newsday
Hugh Cirrito - DEC

Date	Time	Narrative
8/5/14	11:26	HC on site: met with Zimmerman. Apparently, solenoid that stops the transfer from the main tank to the day tank did not stop the flow. The day tank overflowed and once the secondary containment filled, the oil went into a drywell located about 20 feet from the day tank. MEG was hired to clean drain and once completed, an end point sample was taken. Zimmerman was verbally told the sample results met standards, however he has not received the report yet. Once he gets the report, he will forward it to my attention. The cleanup appears satisfactory. As long as the sample results meet standards, the file can be closed.   

MILLER ENVIRONMENTAL GROUP INC.

June 30, 2014

Newsday
235 Pinelawn Rd.
Melville, NY 11747
Attn: Joseph Marino

Re: Emergency Spill Response
Generator: Newsday
Date of Incident: June 17, 2014
Product Involved: Diesel
Location: 235 Pinelawn Rd., Melville, NY 11747
NYSDEC Spill No.: 1402877

Dear Mr. Marino:

On June 17, 2014, Miller Environmental Group, Inc. (MEG) received a phone call from Newsday regarding a diesel spill at the above referenced facility.

MEG immediately dispatched an Operations Supervisor, an Equipment Operator and two (2) Haz-Mat Technicians along with a guzzler truck, rack truck and response truck to the Newsday facility located at 235 Pinelawn Road, Melville, NY.

Apparently the spill originated from a generator fuel tank that had a faulty shut off switch which caused it to overflow into the secondary containment and eventually into an outside below grade storm sewer adjacent to the generator room.

Prior to arrival on site Newsday recovered the standing product from within the secondary containment. The product (approximately 90-gallons) was containerized within NYSDOT approved 55-gallon drums.

MEG entered the storm drain utilizing proper confined space entry procedures and Level C PPE. Impacted soil was recovered from the storm drain via a guzzler truck. Additionally, MEG applied speedy dry to the impacted asphalt areas between the generator tank and the storm drain. The speedy dry was worked into the spill and then recovered. The recovered speedy dry was containerized within NYSDOT approved 55-gallon drums along with petroleum impacted debris and spent PPE. Photos are attached.

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer

On June 23, 2014 MEG disposed of the soil within the guzzler at Tradebe Treatment Recycling (Bridgeport, CT) under non-hazardous waste manifest (52279)

On June, 26, 2014 MEG brought the soil and liquid drums for disposal to Tradebe Treatment Recycling (Bridgeport, CT) under non-hazardous waste manifest (52281 and 52280 respectively). A copy of the waste manifests are attached.

Upon completion of the remediation MEG collected two (2) confirmatory endpoint samples from within the storm sewer. The samples were containerized within laboratory issued glassware, placed in a cooler filled with ice and transported to a NYSDOH accredited laboratory for analysis. The samples were analyzed for the presence of volatile organic compounds (VOCs) via USEPA Method 8260 (NYSDEC CP-51 analyte list) and semi-volatile organic compounds (SVOCs) via USEPA Method 8270 (NYSDEC CP-51 analyte list).

A review of the laboratory analysis indicated that all targeted compounds were below the laboratory's method detection limit and their respective NYSDEC guidance values (see Tables 1 and 2). The complete laboratory analysis report is attached.

Based upon a review of the laboratory analysis it appears that the impacted soil within the storm drain has been successfully removed. Accordingly, MEG recommends that the NYSDEC be petitioned for closure of the assigned spill and that a "No Further Action" letter be issued for the site.

Sincerely,

Robert J. Ferguson

Project Manager / Sr. Hydrogeologist

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer

TABLES

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer

TABLE 1
Newsaday
235 Pinelawn Road
Melville, NY
June 17, 2014
Soil Samples - Volatile Organic Compounds

Compound	EP-1 (µg/Kg)	EP-2 (µg/Kg)	NYSDEC Levels (µg/Kg)
1,2,4-Trimethylbenzene	ND	650	3,600
1,3,5-Trimethylbenzene	ND	170	8,400
Benzene	ND	ND	6,000
Ethylbenzene	ND	ND	1,000
Isopropylbenzene	ND	ND	2,300
m&p Xylenes	ND	140	260
MTBE	ND	ND	930
Naphthalene	2.3	520	12,000
n-Butylbenzene	ND	91	1,200
n-Propylbenzene	ND	65.0	3,900
o-Xylene	ND	ND	260
p-Isopropyltoluene	ND	ND	10,000
sec-Butylbenzene	ND	59	11,000
tert-Butylbenzene	ND	ND	5,900
Toluene	ND	ND	700
Total Xylenes	ND	140	260

Notes:
Bold - Values in bold exceed NYSDEC Guidance Values as set forth within NYSDEC CP-51 Table 3
ND - Not Detected above laboratory's Reportable Limit

TABLE 2
Newsaday
235 Pinelawn Road
Melville, NY
June 17, 2014
Soil Samples - Semi-Volatile Organic Compounds

Compound	EP-1 (µg/Kg)	EP-2 (µg/Kg)	NYSDEC Levels (µg/Kg)
Acenaphthylene	ND	ND	100,000
Anthracene	ND	ND	100,000
Benzo-a-anthracene	ND	ND	1,000
Benzo-a-pyrene	ND	ND	1,000
Benzo-b-fluoroanthene	ND	ND	1,000
Benzo-g,h,i-perylene	ND	ND	100,000
Benzo-k-fluoroanthene	ND	ND	800
Chrysene	ND	ND	1,000
Dibenzo-a,h-anthracene	ND	ND	330
Fluoranthene	ND	ND	100,000
Fluorene	ND	ND	30,000
Indeno(1,2,3-c,d)pyrene	ND	ND	500
Naphthalene	ND	450	12,000
Phenanthrene	ND	420	100,000
Pyrene	ND	ND	100,000

Notes:
Bold - Values in bold exceed NYSDEC Guidance Values as set forth within NYSDEC CP-51 Table 3
ND - Not Detected above laboratory's Reportable Limit

PHOTOLOG

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer


DE-SW-0460
DE-HW-0460
PA-WH3763
GABRIELLI
TRUCK SALES
gabriellitruck.com
MILLER
ENVIRONMENTAL
GROUP
06/17/2014 14:06


06/17/2014 14:07


06/17/2014 14:49


06/17/2014 14:49


06/17/2014 17:33


06/17/2014 18:51


06/17/2014 14:08


06/17/2014 18:52


06/17/2014 17:33

06/17/2014 18:08

MANIFEST

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer

PRIVATE
NON-HAZARDOUS
DOCUMENT OF CARGO

№ 52279

N.Y. State 364 Permit No. 1A-041

#1 MEG ID # #521

#1 Truck License Number 13845PC

#2 MEG ID #

#2 Truck License Number

IDENTIFICATION M14-0532

Generator: NEWSDAY
235 PINELAWN ROAD
MELVILLE, NY 11747

Company name, mailing address and telephone number (631) 843-2044

DEC SPILL# 1402877

Transporter: **Miller Environmental Group, Inc.**
538 Edwards Avenue
Calverton, New York 11933

EPA ID # NYD986908085

TSDF Treatment Storage or Disposal Facility: TRADEBE TREATMENT RECYCLING OF BRIDGEPORT, LLC
50 CROSS STREET
BRIDGEPORT, CT. 06610

WASTE INFORMATION

NON-HAZARDOUS WASTE SHIPPING DESCRIPTION	Containers No.	Containers Type	Total Quantity Gals./Lbs./Yds./Bgs.	NYSDEC Code	TSDF Code
NON RCRA/DOT REGULATED SOLID (OIL SOAKED SOLID/ DEBRIS) NONE, NONE	1	DT	5 YDS		3812 EPT-4RL
			.86 tons		4141 CRF

I hereby certify that the above waste description is complete and accurate, and that no component exist in the wastes which render it hazardous as defined by 6 NY CRR Section 371 and 372.

Generator's Signature — Date 6/17/14

Transporter's Signature #1 — Date 6-17-14

Transporter's Signature #2 — Date 6/23/14

TSDF Signature — Date 6-23-14

PRIVATE
NON-HAZARDOUS
DOCUMENT OF CARGO

52281

N.Y. State 364 Permit No. 1A-041

#1 MEG ID # #605 SO5

#1 Truck License Number 27145MA

#2 MEG ID # _____

#2 Truck License Number _____

IDENTIFICATION M14-0532

Dec Spill # 1402577

Generator: NEWSDAY
235 PINELAWN ROAD (631) 843-2044
MELVILLE, NY 11747

Company name, mailing address and telephone number

Transporter: **Miller Environmental Group, Inc.**
538 Edwards Avenue
Calverton, New York 11933
EPA ID# NYD986906085

TSDF Treatment Storage or Disposal Facility: TRADEBE TREATMENT RECYCLING OF BRIDGEPORT, LLC
50 CROSS STREET
BRIDGEPORT, CT. 06610

WASTE INFORMATION

NON-HAZARDOUS WASTE SHIPPING DESCRIPTION	Containers No.	Containers Type	Total Quantity Gals./Lbs./Yds./Bgs.	NYSDEC Code	TSDF Code
NON RCRA/DOT REGULATED SOLID (OIL SOAKED SOLID/ DEBRIS) NONE, NONE	3	DM	150 LBS		38 REPT-4RL

I hereby certify that the above waste description is complete and accurate, and that no component exist in the wastes which render it hazardous as defined by 6 NY CRR Section 371 and 372.

Generator's Signature _____ Date _____

Transporter's Signature #1 _____ Date _____

Transporter's Signature #2 _____ Date _____

TSDF Signature _____ Date _____

PRIVATE
NON-HAZARDOUS
DOCUMENT OF CARGO

52280

N.Y. State 364 Permit No. 1A-041

#1 MEG ID # ~~#695~~ 805

#1 Truck License Number 27145 MA

#2 MEG ID # _____

#2 Truck License Number _____

IDENTIFICATION M14-0532

DEC SPILL # 1402577

Company name, mailing address and telephone number

Generator: NEWSDAY
235 PINELAWN ROAD
MELVILLE, NY 11747
(631) 843-2044

Transporter: **Miller Environmental Group, Inc.**
538 Edwards Avenue
Calverton, New York 11933
EPA ID # NY0986908085

TSDF Treatment Storage or Disposal Facility: TRADEBE TREATMENT RECYCLING OF BRIDGEPORT, LLC
50 CROSS STREET
BRIDGEPORT, CT. 06610

WASTE INFORMATION

NON-HAZARDOUS WASTE SHIPPING DESCRIPTION	Containers No.	Containers Type	Total Quantity Gals./Lbs./Yds./Bgs.	NYSDEC Code	TSDF Code
NON RCRA / DOT REGULATED LIQUIDS (OIL/WATER) NONE, NONE	2	DM	90 GALS		6136LIKLM

I hereby certify that the above waste description is complete and accurate, and that no component exist in the wastes which render it hazardous as defined by 6 NY CRR Section 371 and 372.

Generator's Signature _____ Date _____

Transporter's Signature #1 _____ Date _____

Transporter's Signature #2 _____ Date _____

TSDF Signature _____ Date _____

MILLER ENVIRONMENTAL GROUP INC.

LABORATORY ANALYTICAL REPORT

1300 Shames Drive, Westbury, NY 11590

(516) 876-7940 · (516) 876-7946

www.millerenv.com

An Equal Opportunity Employer

PHOENIX
Environmental Laboratories, Inc.

Thursday, June 26, 2014

Attn: Mr Robert Ferguson
Miller Environmental Group, Inc.
1300 Shames Drive
Westbury, NY 11590

Project ID: NEWS DAY
Sample ID#s: BG62179, BG62189

This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.


This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,



Phyllis Shiller
Laboratory Director

NELAC - #NY11301
CT Lab Registration #PH-0618
MA Lab Registration #MA-CT-007
ME Lab Registration #CT-007
NH Lab Registration #213693-A,B
NJ Lab Registration #CT-003
NY Lab Registration #11301
PA Lab Registration #68-03530
RI Lab Registration #63
VT Lab Registration #VT11301

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

SDG Comments

June 26, 2014

SDG I.D.: GBG62179

BG62179 - Client provided soil jar for volatile analysis. Phoenix prepared sample per method 5035.

BG62189 - Client provided soil jar for volatile analysis. Phoenix prepared sample per method 5035.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

June 26, 2014

FOR: Attn: Mr Robert Ferguson
Miller Environmental Group, Inc.
1300 Shames Drive
Westbury, NY 11590

Sample Information		Custody Information		Date	Time
Matrix:	SOLID	Collected by:		06/17/14	20:23
Location Code:	MILLERWE	Received by:	SW	06/18/14	17:12
Rush Request:	Standard	Analyzed by:	see "By" below		
P.O.#:	M14-0522				

Laboratory Data

SDG ID: GBG62179
Phoenix ID: BG62179

Project ID: NEWS DAY
Client ID: EP-1

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	96		%	06/18/14	I	E160.3
Soil Extraction SVOA PAH	Completed			06/18/14	BJ/FV	SW3545
Volatiles- STARS/CP-51						
1,2,4-Trimethylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
1,3,5-Trimethylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
Benzene	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
Ethylbenzene	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
Isopropylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
m&p-Xylene	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
Methyl t-Butyl Ether (MTBE)	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
Naphthalene	2.3	1.0	ug/Kg	06/25/14	JLI	SW8260
n-Butylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
n-Propylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
o-Xylene	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
p-Isopropyltoluene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
sec-Butylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
tert-Butylbenzene	ND	1.0	ug/Kg	06/25/14	JLI	SW8260
Toluene	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
Total Xylenes	ND	2.1	ug/Kg	06/25/14	JLI	SW8260
QA/QC Surrogates						
% 1,2-Dichlorobenzene-d4	97		%	06/25/14	JLI	70 - 130 %
% Bromofluorobenzene	98		%	06/25/14	JLI	70 - 130 %
% Dibromofluoromethane	94		%	06/25/14	JLI	70 - 130 %
% Toluene-d8	94		%	06/25/14	JLI	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	240	ug/Kg	06/19/14	DD	SW 8270

Project ID: NEWS DAY
Client ID: EP-1

Phoenix I.D.: BG62179

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acenaphthylene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Benz(a)anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Benzo(a)pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Benzo(b)fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Benzo(ghi)perylene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Benzo(k)fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Chrysene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Dibenz(a,h)anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Fluorene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Indeno(1,2,3-cd)pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Naphthalene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Phenanthrene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
Pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270	
QA/QC Surrogates							
% 2-Fluorobiphenyl	103		%	06/19/14	DD	30 - 130 %	
% Nitrobenzene-d5	96		%	06/19/14	DD	30 - 130 %	
% Terphenyl-d14	132		%	06/19/14	DD	30 - 130 %	3

3 = This parameter exceeds laboratory specified limits.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected
BRL=Below Reporting Level

Comments:

This sample was not collected in accordance with EPA method 5035. NELAC requires the laboratory to qualify the volatile soil data as biased low.

Semi-Volatile Comment:
One of the surrogate recoveries was above the upper range due to sample matrix interference. The other surrogates associated with this sample were within QA/QC criteria. No significant bias is suspected.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director
June 26, 2014
Reviewed and Released by: Bobbi Aloisa, Vice President

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

Analysis Report

June 26, 2014

FOR: Attn:
Miller Environmental Group, Inc.
1300 Shames Drive
Westbury, NY 11590

Sample Information		Custody Information		Date	Time
Matrix:	SOLID	Collected by:		06/17/14	20:25
Location Code:	MILLERWE	Received by:	LB	06/18/14	17:12
Rush Request:	Standard	Analyzed by:	see "By" below		
P.O.#:	M14-0522				

Laboratory Data

SDG ID: GBG62179
Phoenix ID: BG62189

Project ID: NEWS DAY
Client ID: EP-2

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	96		%	06/18/14	I	E160.3
Soil Extraction SVOA PAH	Completed			06/18/14	BJ/FV	SW3545
Volatiles- STARS/CP-51						
1,2,4-Trimethylbenzene	650	52	ug/Kg	06/21/14	JLI	SW8260
1,3,5-Trimethylbenzene	170	52	ug/Kg	06/21/14	JLI	SW8260
Benzene	ND	100	ug/Kg	06/21/14	JLI	SW8260
Ethylbenzene	ND	100	ug/Kg	06/21/14	JLI	SW8260
Isopropylbenzene	ND	52	ug/Kg	06/21/14	JLI	SW8260
m&p-Xylene	140	100	ug/Kg	06/21/14	JLI	SW8260
Methyl t-Butyl Ether (MTBE)	ND	52	ug/Kg	06/21/14	JLI	SW8260
Naphthalene	520	52	ug/Kg	06/21/14	JLI	SW8260
n-Butylbenzene	91	52	ug/Kg	06/21/14	JLI	SW8260
n-Propylbenzene	65	52	ug/Kg	06/21/14	JLI	SW8260
o-Xylene	ND	100	ug/Kg	06/21/14	JLI	SW8260
p-Isopropyltoluene	ND	52	ug/Kg	06/21/14	JLI	SW8260
sec-Butylbenzene	59	52	ug/Kg	06/21/14	JLI	SW8260
tert-Butylbenzene	ND	52	ug/Kg	06/21/14	JLI	SW8260
Toluene	ND	100	ug/Kg	06/21/14	JLI	SW8260
Total Xylenes	140	100	ug/Kg	06/21/14	JLI	SW8260
QA/QC Surrogates						
% 1,2-Dichlorobenzene-d4	97		%	06/21/14	JLI	70 - 130 %
% Bromofluorobenzene	99		%	06/21/14	JLI	70 - 130 %
% Dibromofluoromethane	90		%	06/21/14	JLI	70 - 130 %
% Toluene-d8	103		%	06/21/14	JLI	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	240	ug/Kg	06/19/14	DD	SW 8270

Project ID: NEWS DAY
Client ID: EP-2

Phoenix I.D.: BG62189

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Acenaphthylene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Benz(a)anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Benzo(a)pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Benzo(b)fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Benzo(ghi)perylene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Benzo(k)fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Chrysene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Dibenz(a,h)anthracene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Fluoranthene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Fluorene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270
Naphthalene	450	240	ug/Kg	06/19/14	DD	SW 8270
Phenanthrene	420	240	ug/Kg	06/19/14	DD	SW 8270
Pyrene	ND	240	ug/Kg	06/19/14	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	100		%	06/19/14	DD	30 - 130 %
% Nitrobenzene-d5	93		%	06/19/14	DD	30 - 130 %
% Terphenyl-d14	116		%	06/19/14	DD	30 - 130 %

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected
BRL=Below Reporting Level

Comments:

This sample was not collected in accordance with EPA method 5035. NELAC requires the laboratory to qualify the volatile soil data as biased low.

Volatile Comment:
Elevated reporting limits for volatiles due to the presence of target and/or non-target compounds.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director
June 26, 2014
Reviewed and Released by: Bobbi Aloisa, Vice President

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

QA/QC Report

June 26, 2014

QA/QC Data

SDG I.D.: GBG62179

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
QA/QC Batch 278146, QC Sample No: BG60510 (BG62179)										
Volatiles - Solid										
1,2,4-Trimethylbenzene	ND	97	96	1.0	93	103	10.2	70 - 130	30	
1,3,5-Trimethylbenzene	ND	100	102	2.0	93	103	10.2	70 - 130	30	
Benzene	ND	106	98	7.8	89	100	11.6	70 - 130	30	
Ethylbenzene	ND	102	101	1.0	87	97	10.9	70 - 130	30	
Isopropylbenzene	ND	96	99	3.1	89	95	6.5	70 - 130	30	
m&p-Xylene	ND	98	99	1.0	86	97	12.0	70 - 130	30	
Methyl t-butyl ether (MTBE)	ND	105	98	6.9	84	94	11.2	70 - 130	30	
Naphthalene	ND	105	103	1.9	87	98	11.9	70 - 130	30	
n-Butylbenzene	ND	98	96	2.1	94	105	11.1	70 - 130	30	
n-Propylbenzene	ND	91	93	2.2	88	98	10.8	70 - 130	30	
o-Xylene	ND	104	102	1.9	89	98	9.6	70 - 130	30	
p-Isopropyltoluene	ND	100	98	2.0	90	100	10.5	70 - 130	30	
sec-Butylbenzene	ND	103	101	2.0	92	102	10.3	70 - 130	30	
tert-Butylbenzene	ND	101	100	1.0	90	101	11.5	70 - 130	30	
Toluene	ND	103	99	4.0	88	99	11.8	70 - 130	30	
% 1,2-dichlorobenzene-d4	99	102	100	2.0	98	100	2.0	70 - 130	30	
% Bromofluorobenzene	95	104	97	7.0	103	103	0.0	70 - 130	30	
% Dibromofluoromethane	100	97	106	8.9	95	86	9.9	70 - 130	30	
% Toluene-d8	89	99	97	2.0	100	101	1.0	70 - 130	30	
Comment:										
Additional 8260 criteria: 10% of LCS/LCSD compounds can be outside of acceptance criteria as long as recovery is 40-160%.										
QA/QC Batch 277769, QC Sample No: BG62020 (BG62189 (50X))										
Volatiles - Solid										
1,2,4-Trimethylbenzene	ND	100	103	3.0	78	82	5.0	70 - 130	30	
1,3,5-Trimethylbenzene	ND	104	106	1.9	78	84	7.4	70 - 130	30	
Benzene	ND	109	110	0.9	95	97	2.1	70 - 130	30	
Ethylbenzene	ND	107	111	3.7	87	90	3.4	70 - 130	30	
Isopropylbenzene	ND	100	104	3.9	75	83	10.1	70 - 130	30	
m&p-Xylene	ND	105	108	2.8	85	87	2.3	70 - 130	30	
Methyl t-butyl ether (MTBE)	ND	105	110	4.7	101	99	2.0	70 - 130	30	
Naphthalene	ND	109	112	2.7	84	104	21.3	70 - 130	30	
n-Butylbenzene	ND	105	107	1.9	43	55	24.5	70 - 130	30	m
n-Propylbenzene	ND	96	99	3.1	67	76	12.6	70 - 130	30	m
o-Xylene	ND	105	107	1.9	87	89	2.3	70 - 130	30	
p-Isopropyltoluene	ND	105	107	1.9	68	77	12.4	70 - 130	30	m
sec-Butylbenzene	ND	106	109	2.8	52	63	19.1	70 - 130	30	m
tert-Butylbenzene	ND	101	104	2.9	73	82	11.6	70 - 130	30	
Toluene	ND	109	111	1.8	93	95	2.1	70 - 130	30	
% 1,2-dichlorobenzene-d4	97	96	97	1.0	100	99	1.0	70 - 130	30	
% Bromofluorobenzene	97	99	99	0.0	104	105	1.0	70 - 130	30	

QA/QC Data

SDG I.D.: GBG62179

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits
% Dibromofluoromethane	97	98	101	3.0	101	98	3.0	70 - 130	30
% Toluene-d8	102	101	100	1.0	101	100	1.0	70 - 130	30

Comment:

Additional 8260 criteria: 10% of LCS/LCSD compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 277411, QC Sample No: BG62115 (BG62179, BG62189)

Polynuclear Aromatic HC - Solid

Acenaphthene	ND	85	85	0.0	95	96	1.0	30 - 130	30
Acenaphthylene	ND	87	86	1.2	97	96	1.0	30 - 130	30
Anthracene	ND	91	92	1.1	104	105	1.0	30 - 130	30
Benz(a)anthracene	ND	90	88	2.2	103	103	0.0	30 - 130	30
Benzo(a)pyrene	ND	79	78	1.3	88	86	2.3	30 - 130	30
Benzo(b)fluoranthene	ND	85	86	1.2	99	101	2.0	30 - 130	30
Benzo(ghi)perylene	ND	80	77	3.8	80	74	7.8	30 - 130	30
Benzo(k)fluoranthene	ND	93	86	7.8	98	94	4.2	30 - 130	30
Chrysene	ND	100	99	1.0	114	115	0.9	30 - 130	30
Dibenz(a,h)anthracene	ND	85	84	1.2	89	84	5.8	30 - 130	30
Fluoranthene	ND	92	91	1.1	106	109	2.8	30 - 130	30
Fluorene	ND	107	110	2.8	126	125	0.8	30 - 130	30
Indeno(1,2,3-cd)pyrene	ND	84	82	2.4	87	83	4.7	30 - 130	30
Naphthalene	ND	82	83	1.2	93	94	1.1	30 - 130	30
Phenanthrene	ND	92	93	1.1	107	108	0.9	30 - 130	30
Pyrene	ND	95	92	3.2	108	111	2.7	30 - 130	30
% 2-Fluorobiphenyl	79	76	76	0.0	82	84	2.4	30 - 130	30
% Nitrobenzene-d5	83	77	78	1.3	85	85	0.0	30 - 130	30
% Terphenyl-d14	98	91	88	3.4	98	103	5.0	30 - 130	30

m = This parameter is outside laboratory ms/msd specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference

Phyllis Shiller, Laboratory Director
June 26, 2014

Sample Criteria Exceedences Report

GBG62179 - MILLERWE

Criteria: None

State: NY

SampNo	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL Criteria	Analysis Units

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

NY Temperature Narration

June 26, 2014

SDG I.D.: GBG62179

The samples in this delivery group were received at 4°C.
(Note acceptance criteria is above freezing up to 6°C)

NY/NJ CHAIN OF CUSTODY RECORD

Temp Yam ICE

Pg 1 of 1

PHOENIX
Environmental Laboratories, Inc.

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
Client Services (860) 645-8726

Data Delivery:
☐ Fax #:
☒ Email: RFerguson@millerenv.com

Customer: MEE
Address: 1300 Starnes Rd Mastic NY

Project: News day
Report to: Ferguson
Invoice to:

Project P.O: M14-0522
Phone #:
Fax #:

Client Sample - Information - Identification

Sampler's Signature

Date: 6/17/14

Matrix Code:
DW=drinking water **WW**=wastewater **S**=soil/solid **O**=oil
GW=groundwater **SL**=sludge **A**=air **X**=other

Phoenix Sample #	Customer Sample Identification	Sample Matrix	Date Sampled	Time Sampled	Analysis Request: 8260 CP-51	8270 CP-51	Soil VOA [ ] Methanol [ ] S. Bisulfate [ ] H2O	GL Soil container (8) oz	GL Soil container ( ) oz	40 ml VOA Vial [ ] As is [ ] HCl	GL Amber 1000ml [ ] As is [ ] H2SO4	PL As is [ ] 250ml [ ] As is [ ] HCl	PL H2SO4 [ ] 500ml [ ] 1000ml	PL HNO3 250ml [ ] 250ml [ ] 500ml	PL NaOH 250ml	Bacteria Bottle
62179	EP-1	S	6/17	2023	✓	✓		1								
62189	EP-2	S	6/17	2025	✓	✓		1								

Relinquished by:	Accepted by:	Date:	Time:
		6-18-14	1538
		6-18-14	1712

Comments, Special Requirements or Regulations:

Turnaround:
☐ 1 Day*
☐ 2 Days*
☐ 3 Days*
☒ 5 Days
☐ 10 Days
☐ Other
* SURCHARGE APPLIES

NJ
☐ Res. Criteria
☐ Non-Res. Criteria
☐ Impact to GW Soil Cleanup Criteria
☐ GW Criteria

NY
☐ TOGS GA GW
☐ CP-51 Soil
☐ NY375 Unrestricted Soil
☐ NY375 Residential Soil
☐ NY375 Restricted Non-Residential Soil

Data Format
☐ Phoenix Std Report
☐ Excel
☐ PDF
☐ GIS/Key
☐ EQuIS
☐ NJ Hazsite EDD
☐ NY EZ EDD (ASP)
☐ Other

Data Package
☐ NJ Reduced Deliv. *
☐ NY Enhanced (ASP B) *
☐ Other

State where samples were collected: _____

New York State Department of Environmental Conservation
Spill Prevention and Response, Region One Headquarters
50 Circle Road - SUNY
Stony Brook, NY 11790-3409
Phone: (631) 444-0323 • FAX: (631) 444-0328
Website: http://www.dec.ny.gov

Joe Martens
Commissioner

August 12, 2014

Joe Marino
Newsday
235 Pinelawn Rd.
Melville, NY 11747

Re: Spill # 14-02877, Newsday, 235 Pinelawn Rd., Melville, NY

Dear Mr. Marino:

The Department has reviewed the records and data submitted by you regarding cleanup actions at the above referenced petroleum spill site. Based on such review, the Department determined that you have completed the necessary cleanup and removal actions, and no further remedial activities are necessary.

Nothing contained herein shall be construed as barring, diminishing, or in any way limiting Department's authority under the Navigation Law or the Environmental Conservation Law, including the authority to require additional remedial work, if necessary.

Should you have any questions concerning this matter, you may call me at (631) 444-0324 or e-mail me at hmcirrit@gw.dec.state.ny.us.

Sincerely,

Hugh Cirrito, PE
Environmental Engineer 2

cc: K. Gomez, NYSDEC

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1402877

SPILL NAME: NEWSDAY **DEC LEAD:** hmcirrit

SPILL DATE: 06/17/2014 **SPILL TIME:** 10:00 am

CALL RECEIVED DATE: 06/17/2014 **RECEIVED TIME:** 12:01 pm

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOE MARINO **CONTACT PHONE:** (631) 843-2044

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Other

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

lost from generator, c/u in progress. loss to catch basin, unknown where that releases

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	5 G		Soil,
diesel	Petroleum	5 G		Sewer,
diesel	Petroleum	5 G		Soil,
diesel	Petroleum	5 G		Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN RD MELVILLE NY	JOE MARINO (631) 843-2044

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

06/17/14 1210 Hrs: Left message for Libuser. DR

06/17/14 1250 Hrs (A): Libuser called- apparently, a "test" of some sort was performed overnight on the day tank for this generator. The solenoid which opens and closes the line failed and caused the spill.

06/17/14 1250 Hrs (B): At this time, Miller believes only a few gallons of oil spilled. THE CATCH BASIN IS INSIDE THE BUILDING, AND MILLER DOES NOT BELIEVE IT HAS ANY OUTLETS.

06/17/14 1250 Hrs (C): Miller is cleaning up the floor with speedi dri, and is bringing a "guzzler" truck to clean out the basin.

06/17/14 1250 Hrs (D): DEC directed Miller to keep this office updated. DR

DRAIN CLEANED OUT, ENDPOINT SAMPLES ARE CLEAN, NO FURTHER ACTION REQUIRED

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1402877

SPILL NAME: NEWSDAY **DEC LEAD:** hmcirrit

PIN **T & A** **COST CENTER**

CLASS: C3 **CLOSE DATE:** 08/12/2014 **MEETS STANDARDS:** False

Houghton Chemical Corporation

52 Cambridge Street • Allston (Boston) • MA 02134
Phone: (800) 777-2466 • Fax: (617) 254-2713
www.houghton.com

MacGuard® 2792 Heavy Duty Product Data Sheet

Inhibited Ethylene Glycol Antifreeze/Coolant

MacGuard® 2792 Heavy Duty Antifreeze/Coolant is a fully formulated heavy duty antifreeze/coolant requiring no additive (SCA) precharge. It provides corrosion protection for all heavy duty cooling systems and is formulated to be compatible with antifreeze/coolants of all major producers.

For health and safety information for this product, contact Houghton for a Material Safety Data Sheet (MSDS).

MacGuard® 2792 Heavy Duty (MAC)

Typical Properties by Concentration

Typical Properties	Conc. (~volume of EG) Item #0001	50%(~v/v of MAC) Item #0809
Ethylene Glycol	95	48
Performance Additives and Water	5	52
Color	Green	Green
Clarity	Clear	Clear
Specific Gravity (15/15^{0}C 60/60^{0}F)	1.12-1.14	1.06-1.09
pH 50%	7.5-11.0	7.5-11.0
Reserve Alkalinity (min)	6	3
Freeze Point (^{0}F) Max @ 50%	-34	-34

Typical properties, not to be construed as specifications. As use conditions are not within its control, Houghton does not guarantee results from use of the information or products herein; and gives no warranty, express or implied.

Use Recommendation: MacGuard® 2792 HD meets or exceeds performance requirements for both automotive and Heavy Duty cooling systems, including those with aluminum heat-rejecting components such as aluminum cylinder heads, water pumps and radiators. It provides corrosion protection for all cooling system metals and is formulated to be compatible with antifreeze/coolants of all major producers. It is SCA pre-charged with nitrite to protect heavy duty truck engine cooling components such as wet sleeve liners.

MacGuard® 2792 HD antifreeze/coolant should not be used in concentrated form in your vehicle. A 50% dilution is generally recommended for best balanced protection against corrosion and summer boiling. Do not dilute to less than 33-1/3%. (Maximum freeze protection is at 70% if required.) Water quality can be an important factor affecting the long-term corrosion protection of any antifreeze. Use only water of good quality (see ASTM D3306, General Requirements for water quality). Test coolant annually or at maintenance intervals, replace when depleted or, if testing is not done, replace every two years. For HVAC systems, recreational vehicles, and protection of other Hydronic systems, please consult the heat transfer fluids section of our website or call us for suggestions.

Formulated to Satisfy: ASTM D5216 and the corrosion limits in ASTM D3306, ASTM D4985, and ASTM D6210, SAE/J1034, SAE/J1941, and Federal Specification OA548D; satisfying both Hot Surface Aluminum protection requirements of ASTM test D4340 and Cummins Heavy Duty Low Silicate requirements, and is designed to meet the requirements of TMC RP-329, GM1825M, GM1899M, Chrysler MS7170, Ford ESEM97B44A, Cummins CES 14603.

Cautionary Information: Ethylene glycol, the major component of MacGuard® 2792 Heavy Duty, is poisonous to humans and animals when ingested. Store only in closed containers with complete cautionary information thereon, in a cool, secure place, out of reach of children. Do not use in any system connected with potable water. Ask us about other Houghton Chemical products specifically designed for this purpose.

NOTICE: No freedom from any patent owned by Seller or others is to be inferred. Because use conditions and applicable laws may differ from one location to another and may change with time, Customer is responsible for determining whether products and the information in this document are appropriate for Customer's use and for ensuring that Customer's workplace and disposal practices are in compliance with applicable laws and other governmental enactments. Seller assumes no obligation or liability for the information in this document. NO WARRANTIES ARE GIVEN; ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE ARE EXPRESSLY EXCLUDED.

Date Revised: September 10, 2012
W:\Administration\MSDS, Test Reports, Product Data Sheets\Product Data Sheets\Antifreeze\MacGuard HD Product Data.docx

Houghton Chemical Corporation

Safety Data Sheet

MACGUARD® 2792 Antifreeze

Section 1 - Identification	
Manufacturer Address	Houghton Chemical Corporation 52 Cambridge Street, Allston, MA 02134 1-617-254-1010 or 1-800-777-2466
Emergency Telephone	**CHEMTREC: 1-800-424-9300**
Chemical Name & Synonyms	Antifreeze/Inhibited Ethylene Glycol
Chemical Family	Ethylene Glycol Mixture
Recommended Use	Antifreeze Fluid
Restrictions on Use	Dilution to 50% is generally recommended: dilute to meet local condition.
Section 2 – Hazard(s) Identification	
Hazard Classification	OSHA: Acute Toxicity, Oral, Category 4 Skin Corrosion / Irritation, Category 2 Serious Eye Damage / Eye Irritation, Category 2A Sensitization – Skin, Category 1 Toxic to Reproduction, Category 2 Specific Target Organ Toxicity (Single Exposure), Category 1 Specific Target Organ Toxicity (Repeated Exposure), Category 2
Signal Word	DANGER
Hazard Statement	Harmful if swallowed. Causes skin irritation. Causes serious eye irritation. May cause an allergic skin reaction. Suspected of damaging fertility of the unborn child. Caused damage to the central nervous system (CNS) and kidneys if swallowed. May cause damage to kidneys through prolonged or repeated exposure if swallowed.
Pictogram Description	GHS: Health Hazard, Exclamation Point
Precautionary Statement	Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wash hands and any other contaminated skin after handling. Do not eat, drink or smoke when using this product. Wear eye protection (splash goggles or full face shield), protective gloves and protective clothing (chemically impervious). Do not breathe mist or spray. Contaminated work clothing must not be allowed out of the workplace. Response: If swallowed: Call a poison control center or doctor. Rinse mouth. If on skin: Wash with plenty of water. If skin irritation or rash occurs: Get medical attention. Take off contaminated clothing and wash it before reuse. If in eyes: Rinse eyes cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention. If exposed or concerned: Get medical advice. Get medical attention if you feel unwell. Storage: Store locked up. Disposal: Contact local sewer, municipal, state and/or federal agencies to determine appropriate disposal options for the product. Dispose of this container with a registered reconditioner or as otherwise appropriate.
Any other Hazard not otherwise classified	Not Applicable

Section 3 – Composition and Information on Ingredients			
Chemical Name	Common name and synonyms	CAS #	% by weight
Ethylene Glycol	Monoethylene Glycol	107-21-1	95%
Water	N/A	7732-18-5	2.5%
Inhibitors & Dye	N/A	Proprietary	3%

Section 4 – First aid Measures	
Symptoms of Exposure	
Acute	Irritation of affected area with symptoms of reddening, itching, swelling, burning, possible permanent damage, nausea, vomiting, weakness, and death

Delayed	Irritation of affected area with symptoms of reddening, itching, swelling, burning, possible permanent damage, nausea, vomiting, weakness, abdominal pain, muscle tenderness, repiratory failure, severe metabolic acidosis, hypocalcemictetany and death
Inhalation	Vapors and mists cause respiratory irritation and may be harmful if inhaled.
Skin	Irritation may result. May be harmful if absorbed through skin.
Eye Contact	Irritation may cause transitory stinging and tearing.
Ingestion	Toxic: may be harmful or fatal if swallowed.
First Aid Instructions	
Inhalation	Remove to fresh air. Administer oxygen if breathing is difficult. Give artificial respiration if victim is not breathing. Seek medical attention.
Skin	Wash skin with soap and water for at least 20 minutes. Remove any contaminated clothing. Seek medical attention immediately if symptoms or irritation develops.
Eye Contact	Flush with water for at least 20 minutes. Seek medical attention if irritation develops or persists.
Ingestion	DO NOT induce vomiting, seek medical attention immediately. If swallowed give 2 to 3 glasses of water if victim is conscious and alert. Do not give anything by mouth to an unconscious person. To prevent aspiration of swallowed product, lay victim on side with head lower than waist. Vomiting may occur spontaneously. If vomiting occurs and the victim is conscious, give water to victim to further dilute the chemical.
Other	Consult a physician. Show safety data sheet to the doctor in attendance.
Section 5 – Fire Fighting Measures	
Suitable Extinguishing Material	**Water, water fog, water spray, alcohol foam, dry chemical or carbon dioxide.**
Unsuitable Extinguishing Material	No Data Available
Hazards from Combustion	Smoke may contain the original material in addition to but not limited to: Carbon Monoxide, Carbon Dioxide.
Special Protective Equipment for Firefighters	Wear self-contained breathing apparatus and protective suit. Evacuate personnel to safe areas and keep upwind of fire.
Section 6 – Accidental Release Measures	
Use of personal precautions	Ventilate area of leak or spill. Remove all sources of ignition. Wear appropriate personal protective equipment.
Protective equipment to prevent the contamination of skin, eyes, and clothing.	Usage of safety glasses or googles is recommended. Chemical resistant gloves, chemical resistant apron, boots, and full suit will be necessary depending on the extent of clean up task. If ventilation does not control airborne concentration then respiratory protection equipment that meets OSHA's 29 CFR 1910.134 and ANSI Z88.2 requirements should be used.
Methods and materials used for containment	Collect liquid in an appropriate container or absorb with inert material and place in chemical waste container.
Cleanup procedures	Do not flush to sewer. Comply with all federal, state, and local regulations.
Section 7 – Handling and Storage	
Precautions for safe handling	Protect container from physical damage. Wear appropriate personal protection equipment. Do not expose containers to open flame, excessive heat, or direct sunlight. Use local exhaust over processing area. Do not eat, drink or smoke around products.
Recommendations on the conditions for safe storage, Storage/handling incompatibilities.	Store in a cool, dry and ventilated area away from sources of heat, moisture and incompatible materials. Observe all warnings and precautions listed for the product. Keep container closed to prevent contamination.
Section 8 – Exposure Controls/Personal Protection	
OSHA Permissible Exposure Limits (PELs)	Not Applicable
American Conference of Governmental Industrial Hygienists (ACGIH) Threshold Limit Values	ACGIH TLV: 100 mg/m3
Other Exposure Limits	OSHA - Table Z-1 Limits for air contaminants - 1910.1000: 50 ppm 125 mg/m3 .
Engineering Control	Use mechanical (general) ventilation to control airborne levels below exposure guidelines.

Individual Protection Measures	Wear protective safety glasses or goggles, gloves, apron, vapor respirator.

Section 9 – Physical and Chemical and Chemical Properties

Appearance (physical state, color, etc.)	Liquid, Clear,Green
Upper/lower flammability or explosive limits	Not Explosive; LOWER: 3.2% (v) UPPER: 15.3% (v)
Odor	Slight to no odor
Vapor pressure	134 Pa / 0.1 mmHg
Odor threshold	No data available
Vapor density (air = 1)	2.14
pH	7.5 - 11.0
Relative density	1.120 - 1.140
Freezing point (as 50%)	-34°F / -37°C
Solubility(ies)	Miscible in water
Initial boiling point and boiling range	385°F / 196°C
Flash point	232°F / 111°C
Evaporation rate (Butyl Acetate = 1)	<1
Flammability (solid, gas)	This material is Not Flammable but can burn if heated
Partition coefficient: n-octanol/water	Log Pow: -1.36
Auto-ignition temperature	> 700°F / > 370°C
Decomposition temperature; and	Not Applicable
Viscosity	~16 cps at 60°F

Section 10 – Stability and Reactivity

Reactivity	Product is stable under typical use temperatures.
Chemical Stability	Product is stable under typical use temperatures.
Hazardous Reactions	Avoid contact with oxidizing materials strong bases and strong acids.
Conditions to Avoid	Heat, flames, ignition sources and incompatibles.
Incompatible Materials	Avoid contact with oxidizing agents, strong bases and strong acids.
Decomposition Products	Carbon dioxide and carbon monoxide may form when heated to decomposition.

Section 11 – Toxicological Information

Likely Routes of Exposure	Eyes / Skin / Ingestion / Inhalation

	Effects from Short Term Exposure	Effects from Long Term Exposure
Delayed Effects	Irritation of affected area	Irritation of affected area
Immediate Effects	Irritation of affected area	Irritation of affected area
Chronic Effects	Not Applicable	Teratogenic effects
The numerical measures of toxicity (e.g., acute toxicity estimates such as the LD50 (median lethal dose)) - the estimated amount [of a substance] expected to kill 50% of test animals in a single dose.		Skin: LD50 - Rabbits - >10600 mg/kg Ingestion: LD50 - Rats - 7712 mg/kg; Lethal Dose Human Adult - 90mL
Description of the symptoms. This description includes the symptoms associated with exposure to the chemical including symptoms from the lowest to the most severe exposure.		Irritation, nausea, vomiting, abdominal pain, weakness, muscle tenderness, respiratory failure, convulsions, cardiovascular collapse, pulmonary edema, hypocalcemictetany, metabolic acidosis, death.

Listed in the National Toxicology Program (NTP) Report on Carcinogens?	No	**Found to be a potential carcinogen in the International Agency for Research on Cancer (IARC) Monographs?**	No	**Found to be a potential carcinogen by OSHA?**	No

Section 12 – Ecological Information

Ecotoxicity	Low Ecotoxicity
Persistence and Degradability	Biodegradable
Bioaccumulation	Does not bioaccumulate significantly
Mobility in Soil	Dissolves in water. If product enters soil, it will be highly mobile and may contaminate ground water

Other Adverse Effects	No Data Available

Section 13 – Disposal Considerations

Do not dump into sewers, on ground or into any bodies of water. Contact local sewer, municipal, state and/or federal agencies to determine appropriate disposal options

Section 14 – Transport Information

Is product DOT regulated in Non-Bulk packaging?	No

DOT BULK

UN number	UN3082
UN proper shipping name	Environmentally hazardous substances, liquid, n.o.s.
Transport hazard class(es)	9
Packing group number	III
Environmental hazards (e.g., identify if it is a marine pollutant according to the International Maritime Dangerous Goods Code (IMDG Code))	Not Regulated
Guidance on transport in bulk (according to Annex II of MARPOL 73/783 and the International Code for the Construction and Equipment of Ships Carrying Dangerous Chemicals in Bulk (International Bulk Chemical Code (IBC Code))	Not Regulated
Any special precautions which an employee should be aware of or needs to comply with, in connection with transport or conveyance either within or outside their premises	Reportable Quantity (RQ): 5000 lbs Ethylene Glycol

Section 15 – Regulatory Information (Not indicated anywhere else on this SDS)

Safety Regulations	OSHA Hazard Communication Standard: This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication Standard, 29 CFR 1910.1200.	
Health Regulations	Not Available	
Environmental Regulations	Not Available	
SARA 311/312	Based upon available information, this material is classified as the following health and/or physical hazards according to Section 311 & 312	Superfund Amendments and Reauthorization Act of 1986 Title III (SARA) Sections 311 and 312: Immediate (Acute) Health Hazard - Yes; Delayed (Chronic) Health Hazard - Yes; Fire Hazard - No; Reactive Hazard - No; Sudden Release of Pressure Hazard - No. Section 313: Product contains the following substances which are subject to reporting requirements and are listed in 40 CFR 372 - Component: Ethylene Glycol CAS#: 107-21-1 Amount: >=99.0%.
HMIS	Blue/Health	2
	Red/Flammability	1
	Orange/Physical Hazard	0
	White/Personal Protection	x
NFPA 0(no hazard) to 4(severe risk)	Health (Blue)	2
	Flammability (Red)	1
	Instability/Reactivity (Yellow)	N/A
	Special (White)	0
US Toxic Substance Control Act	All components of this product are on the TSCA Inventory or are exempt from TSCA Inventory requirements under 40 CFR 720.30	
CEPA – Domestic Substances List (DSL)	All substances contained in this product are listed on the Canadian Domestic Substances List (DSL) or are not required to be listed.	

Section 16 – Other Information

This SDS is applicable for all dilutions and containers for this brand of product. The information herein is provided in good faith and believed to be accurate as of the effective revision date shown. However, no warranty, express or implied, is given. Regulatory requirements are subject to change and may differ between various locations. It is the buyer's/ user's responsibility to ensure that activities comply with all federal, state, provincial or local law.

Product Dilutions Differentials

Properties[1]	60%	50%	40%	35%	30%	25%
MACGUARD® 2792 Antifreeze		48%				
Performance Additives and Water		52%				
Specific Gravity ($15/15^0$C $60/60^0$F)		1.060 - 1.090				
Reserve Alkalinity (min)		3				
Freeze Point Max		-34°F / -37°C				
Revision Date: September 4, 2015						

61001 - H01 - 010116

HOUGHTON CHEMICAL CORPORATION
MATERIAL SAFETY DATA SHEET

"MACGUARD 2792 ANTIFREEZE/COOLANT CONCENTRATE"

SECTION 1
IDENTIFICATION

MANUFACTURER:	Houghton Chemical Corporation
ADDRESS:	52 Cambridge Street, Allston, MA 02134
EMERGENCY TELEPHONE:	(617) 254-1010, 1-800-777-2466 or Chemtrec 1-800-424-9300
CHEMICAL NAME & SYNONYMS:	Permanent Antifreeze and Summer Coolant
CHEMICAL FAMILY:	Ethylene Glycol Based
FORMULA:	Trade Secret
CAS REGISTRY NUMBER:	Not applicable for blended product
DOT SHIPPING CLASSIFICATION:	Not regulated in quantities containing less than 5,000 pounds of ethylene glycol
PRODUCT NUMBER:	61001, 62001

SECTION 2
HAZARDOUS INGREDIENTS

MATERIAL	CAS #	%	TLV (Units)
Ethylene Glycol	107-21-1	90-95	50 ppm
Diethylene Glycol	111-46-6	≤ 5	50 ppm
Sodium Tetraborate	1303964	<1	1 mg/m^3
Sodium Nitrite	7632000	<1	Not applicable
Sodium Toiytriazole	64665572	<1	Not applicable
Sodium Hydroxide	1310732	<1	2 mg/m^3

SECTION 3
PHYSICAL DATA

BOILING POINT:	@760 mm Hg. 325°F
FREEZING POINT:	-4° F
SPECIFIC GRAVITY:	1.12
VAPOR PRESSURE AT 20°C:	0.1
VAPOR DENSITY (air = 1):	2.1
SOLUBILITY IN WATER:	Complete

% VOLATILE BY VOLUME:	Greater than 95%
EVAPORATION RATE:	Less than 1
APPEARANCE AND ODOR:	Fluorescent green; mild odor

SECTION 4
FIRE AND EXPLOSION HAZARD DATA

FLASH POINT:	250°F - TOC 225°F - TCC
AUTO IGNITION TEMPERATURE:	Not applicable
FLAMMABLE LIMITS IN AIR:	LEL = 3.0 UEL = 16 (calculated)
EXTINGUISHING MEDIA:	Water, fog, alcohol foam, dry chemical or CO_2 for small fires
SPECIAL FIRE FIGHTING PROCEDURES:	A solid stream of water directed into hot burning liquid can cause frothing.
UNUSUAL FIRE AND EXPLOSION HAZARDS:	None

SECTION 5
REACTIVITY DATA

STABILITY:	This material is stable.
INCOMPATIBILITY:	Keep away from strong oxidizing agents.
HAZARDOUS DECOMPOSITION PRODUCTS:	Burning can produce carbon dioxide or carbon monoxide.
HAZARDOUS POLYMERIZATION:	Will not occur.

SECTION 6
HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE:	50 ppm (vapor or mist)
EFFECTS OF OVEREXPOSURE:	Irritating to eyes and skin. Inhalation irritates nose and throat. High vapor concentration causes nausea, vomiting and headaches.
Eye Contact:	Irritation may result.
Skin:	May be mildly irritating to skin. Slightly toxic on prolonged or repeated contact.
Inhalation:	Exposure to high vapor concentration from heated antifreeze coolant or exposure to mists may produce

nausea, vomiting, headache, dizziness and irregular eye movements.

Ingestion: *Swallowing causes abdominal discomfort or pain, dizziness, lumbar pain, oliguria, uremia and central nervous system depression. Large volumes cause kidney damage and can be fatal.*

EMERGENCY AND FIRST AID PROCEDURES:

Eyes: Flush with plenty of water for at least 15 minutes.

Skin: Flush with plenty of water, wash with mild soap if available.

Inhalation: Remove to fresh air and give artificial respiration if breathing has stopped.

Ingestion: If swallowed, IMMEDIATELY contact a poison control center, emergency treatment center, or physician.

SECTION 7
SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE THE MATERIAL IS SPILLED OR RELEASED:

Wear suitable protective equipment. Large spills should be contained and collected. Small spills can be collected or may be absorbed with appropriate liquid absorbing materials. All spill response and disposal should be carried out in accordance with federal, state and local requirements.

WASTE DISPOSAL METHOD: Consult with local sewer, municipal, state and/or federal agencies to determine appropriate current disposal options.

SECTION 8
SPECIAL PROTECTIVE INFORMATION

RESPIRATORY PROTECTION: Provide adequate ventilation with local exhaust system.

VENTILATION: Mechanical or other

PROTECTIVE GLOVES: Rubber gloves recommended.

EYE PROTECTION: Safety glasses or goggles.

OTHER PROTECTIVE EQUIPMENT: Normally not required

SECTION 9
SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:

Do not breathe mist or spray. Follow good work/hygiene practices. Provide safety shower and wash in immediate area. Workers should wash with soap and water before eating, smoking or using toilet facilities. Launder contaminated clothing before re-use.


Site Notes

Spill Number: 1508951


Representatives:

Robert Poczkalski, Pat Mclaughlan-MEG, Joseph Marino- Newsday

Date	Time	Narrative
12/2/15	1135	RJP on location. Release of 50-60 gallons of coolant from generator. Hose fitting failed during routine maintenance, system was powered down immediately. Impact to floor drain. Spill location is approx 15' below grade, and is open to air. Removable grates allow access of large equipment to mechanical room. Coolant is 50% concentration of MacGuard 2792 ethylene glycol mixture. SDS states water-miscible solution is biodegradable and has low ecotoxicity. No recoverable product remaining on location, liquid drained through sand base of floor drain. Surface spill was cleaned with absorbents. USGS DTW 42'. No DEC action, SDS and product information available on D2. RJP.
	1200	RJP off location.



Site Notes Continued

Date	Time	Narrative
		 

Site Notes Continued

Date	Time	Narrative
		 

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1508951

SPILL NAME: NEWSDAY **DEC LEAD:** RJPOCZKA

SPILL DATE: 12/02/2015 **SPILL TIME:** 8:00 am

CALL RECEIVED DATE: 12/02/2015 **RECEIVED TIME:** 10:40 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOSEPH MARINO **CONTACT PHONE:** (631) 843-2044

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
Spill contained to drive well, Miller environmental enroute for pump out of fluid.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
antifreeze	Other	60 G	0 G	Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN RD MELVILLE NY	JOSEPH MARINO (631) 843-2044

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

12/02/15 1050 Hrs (A): Called Marino- he said a hose burst on a generator INSIDE their facility, but the fluid spilled outside to a drywell. He confirmed that the drywell has no outlets and a sand bottom, and that MEG is responding.

12/02/15 1050 Hrs (B): DEC informed him that this office might have RJP (currently in Farmingdale) respond when finished there. DR

12/02/15 1052 Hrs: RJP called- he just finished in Farmingdale and saw this report, so he will respond at this time. DR

12/02/15 approx noon: As per RJP- ALL the product appears to have soaked into the sand at the bottom of the drywell. He will obtain a copy of the MSDS sheet from Newsday. DR

12/2/15 1135 Hrs: RJP on location w/ MEG. No recoverable liquid, no DEC action. Documents on D2. RJP

PIN **T & A** **COST CENTER**

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1508951

SPILL NAME: NEWSDAY **DEC LEAD:** RJPOCZKA

CLASS: C3 **CLOSE DATE:** 12/09/2015 **MEETS STANDARDS:** False

New York State Department of Environmental Conservation
Division of Environmental Remediation, Region One
Bureau of Spill Prevention and Response

REFERRAL MEMORANDUM

To:
- ❑ Air Unit
- ❑ Hazardous Waste Remediation
- ❑ Solid Waste
- ❑ Pesticides
- X Water Unit
- ❑ Natural Resources
- ❑ Marine Habitat Protection
- ❑ Law Enforcement
- ❑ Wildlife

From: Bureau of Spill Prevention and Response

Referred By: Willie Gabin

Date: October 11, 2016

Re: Spill #16-06790

Attached, please find a copy of our Spill Report and any pertinent information. This incident is being referred to your unit for any appropriate actions and/or follow-up that you deem necessary.

If you have any questions regarding this matter, please contact the above referenced inspector at (631) 444-0335.

Note: Copy of Spill Report must be attached to original Memo and submitted to the appropriate unit. Copy of this memo must be attached to the original Spill Report to document referral.

refmem (rev. 5/00)

NYSDEC Region 1, SUNY at Stony Brook, 50 Circle Rd., Stony Brook, NY 11790-3409

Site Notes

Spill Number: 1606790

Representatives:

Robert Poczkalski,

Date	Time	Narrative
10/11/16	1250	RJP on location. Marino did not answer phone, RJP requested him at reception desk. Electric air compressor, 12 gal capacity of synthetic compressor oil, SAE 30 non-detergent. Failure of weld at joint, release of approx. 4 gallons. 4 gallons remains in equipment, 4 gallons recovered in buckets. Release to base of compressor, concrete floor, and floor drain. Absorbent pads placed, compressor out of service pending repairs. Drain connected to on-site wastewater collection and treatment facility. Facility operates oil/water separator and utilizes mechanical, chemical, and bacteriological treatment prior to discharge. No further action required. RJP.
	1330	RJP off location.



Site Notes Continued

Date	Time	Narrative
		

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1606790

SPILL NAME: INDUSTRIAL **DEC LEAD:** RJPOCZKA

SPILL DATE: 10/11/2016 **SPILL TIME:** 6:35 am

CALL RECEIVED DATE: 10/11/2016 **RECEIVED TIME:** 9:52 am

SPILL LOCATION

PLACE: INDUSTRIAL **COUNTY:** Suffolk

STREET: 235 PINELAWN RD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOSEPH MARINO **CONTACT PHONE:** (631) 843-2044

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

the spill went into the waste treatment plant that will go into underground pools. The cleanup is pending. It would be process or clean in the treatment plant.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
compressor oil	Petroleum	4 G	0 G	Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY LLC	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

10/11/16 @ 1130 AM -WG called Mr. Marino (Newsday LLC)
-No answer. Left message.

10/11/16 @ 1230 PM--Rob was dispatched to the site.

10/11/16 1250 Hrs: RJP on location. Marino did not answer phone, RJP requested him at reception desk. Electric air compressor, 12 gal capacity of synthetic compressor oil, SAE 30 non-detergent. Failure of weld at joint, release of approx. 4 gallons. 4 gallons remains in equipment, 4 gallons recovered in buckets. Release to base of compressor, concrete floor, and floor drain. Absorbent pads placed, compressor out of service pending repairs. Drain connected to on-site wastewater collecti and treatment facility. Facility operates oil/water separator and utilizes mechanical, chemical, and bacteriological treatment prior to discharge.

Incident was also referred to the Water Unit.

10/13/17 1130 Hrs: RJP made call to Marino. Surface spill cleaned up, equipment repaired and returned to service, no issues noted with water treatment facility. No Further Action. RJP.

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1606790

SPILL NAME: INDUSTRIAL **DEC LEAD:** RJPOCZKA

PIN **T & A** **COST CENTER**

CLASS: C3 **CLOSE DATE:** 11/09/2017 **MEETS STANDARDS:** False


Site Notes

Spill Number: 1610337

Representatives:

Robert Poczkalski, Joe Marino- Newsday		
Date	Time	Narrative
3/9/17	1045	RJP on location with Joe Marino of Newsday. Failure of valve on pump associated with 2000 gal holding tank, now repaired and back in operation. Release of non-toxic majenta ink to concrete containment. Room constructed to contain product, no drains or cracks. Material collected, filtered, and replaced into tank. No release of ink out of containment, no materials sent for disposal. No further Action. RJP off location. RJP.
	1115	

Site Notes Continued

Date	Time	Narrative
		 

Poczkalski, Robert J (DEC)

From: Joseph Marino <Joe.Marino@newsday.com>
Sent: Tuesday, March 21, 2017 8:49 AM
To: Poczkalski, Robert J (DEC)
Cc: Stephen Zimmerman; Frank Fazio Jr.; Al Motis
Subject: Newsday Spill No. 1610337

ATTENTION: This email came from an external source. Do not open attachments or click on links from unknown senders or unexpected emails.

Hello Robert,

Follow-up to the magenta ink spill (on 2/14/2017) inside secondary containment (Spill Number 1610337). The Newsday Operations Department captured all the ink and put in drums and labeled. All ink will be recycled - filtered via our on-site ink reclaim equipment (no ink will be sent off site for disposal) and pumped back into ink tanks. You may close out the spill, please call me should you have any questions, or require anything else.

Regards.

Joseph Marino
Newsday
Senior Manager
Facilities and Engineering
235 Pinelawn Road
Melville, NY 11747
O: 631-843-2044
M: 516-509-0495
F: 631-843-3444

LEED Green Associate
Building Operator Certification

-----Original Message-----
From: Frank Fazio Jr.
Sent: Monday, March 13, 2017 10:44 AM
To: Joseph Marino <Joe.Marino@newsday.com>
Cc: Richard Lizzi <Rich.Lizzi@newsday.com>; Al Motis <Al.Motis@newsday.com>; Bill Parrish <Bill.Parrish@newsday.com>; William Mallon <Bill.Mallon@newsday.com>
Subject: Magenta ink spill

Joe

All magenta ink from spill was captured put in drums and labeled.
All ink will be recycled filtered back to ink tanks.

Thanks

Frank Fazio Jr.
Sent from my IPhone

The information transmitted in this email and any of its attachments is intended only for the person or entity to which it is addressed and may contain information concerning Altice USA and/or its affiliates and subsidiaries that is proprietary, privileged, confidential and/or subject to copyright. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient(s) is prohibited and may be unlawful. If you received this in error, please contact the sender immediately and delete and destroy the communication and all of the attachments you have received and all copies thereof.

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1610337

SPILL NAME: NEWSDAY **DEC LEAD:** RJPOCZKA

SPILL DATE: 02/14/2017 **SPILL TIME:** 11:15 pm

CALL RECEIVED DATE: 02/15/2017 **RECEIVED TIME:** 3:00 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOE MARINO **CONTACT PHONE:** (516) 509-0495

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Other

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
Spill contained inside secondary containment. Clean up being completed in-house.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
other	Other	1,000 G		

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN RD MELVILLE NY	JOE MARINO (516) 509-0495

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

02/15/17 0905 Hrs: Marino called- he said they have multiple tanks in a containment area that provides 110% containment. A fitting on one tank failed and resulted in the release of an estimated 1000gal of ink, but ONLY the containment area was impacted. They are cleaning up the spillage themselves, and hope to reuse the ink. DR

3/9/17 1045 Hrs: RJP on location. No release from containment, no remaining impacts, non-hazardous ink being recycled on-site and reused. No further action. RJP.

PIN **T & A** **COST CENTER**

CLASS: C4 **CLOSE DATE:** 11/09/2017 **MEETS STANDARDS:** False

Created On: 02/15/2017

Date Printed: 8/7/2018 Last Updated: 12/18/2017

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 1703192

SPILL NAME: NEWSDAY **DEC LEAD:** Unassigned

SPILL DATE: 07/01/2017 **SPILL TIME:** 6:00 am

CALL RECEIVED DATE: 07/01/2017 **RECEIVED TIME:** 9:43 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: JOSEPH MARINO **CONTACT PHONE:** (516) 509-0495

CONT. FACTOR: Human Error **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
spill impacted storm drain, clean up is pending

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
wastewater	Other	10 G		Soil,
wastewater	Other	10 G		Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	NN	JOSEPH MARINO
		(516) 509-0495 cell?

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

OUTSIDE WASTE TREATMENT FACILITY

07/01/17 -10:00 Nh spoke with Joe Marino..operator failed to close valve causing waste water to spill out.. some went into dra which an individual drain. Drain was pumped out. NH will refer to water unit via e-mail.


PIN **T & A** **COST CENTER**

CLASS: D5 **CLOSE DATE:** 07/03/2017 **MEETS STANDARDS:** False

Created On: 07/01/2017

Date Printed: 8/7/2018 Last Updated: 11/03/2017





Newsday

Long Island, NY 11747

John Tillotson
Environmental Coordinator
Administrative Services
(516) 756-3833


A Times Mirror Newspaper

89-07176
235 PINELAWN RD., MELVILLE
NEWSDAY PLANT / OFFICE BLDG.

10-20-89
1405 - FROM OFFICE
- RESPONSE REQ'D
- EN-ROUTE
14:30 - ON SITE. (ACAMPORA.)
- TYREE HIRED BY SPILLER
& ON SITE @ TIME OF MY ARRIVAL.
- CONCRETE PAVEMENT & LEACHING BASIN AFFECTED.
- NEWSDAY PERSONNEL CLEANED-UP SURFACE AREA
W/ SPEEDI-DRY.

- CAUSE OF INCIDENT:
- EMERGENCY GENERATOR WAS BEING TESTED
& TESTING CREW FILLED BOTH "DAY-TANKS"
(100 GALLON & 25 GALLON)
- A FLOAT IN THE 100 GALLON TANK FAILED
AND CAUSED AN OVERFLOW - FUEL OIL FILLED
TANK & VENT LINE, SPILLED FROM VENT ONTO
CONCRETE FLOORING, ALONG FLOOR INTO DRAIN.
DRAIN IS A LEACHING BASIN & HAD LARGE
AMOUNT OF WATER.
- APPROX. 2½" PRODUCT FLOATING ON WATER.
(ASSUMING 8' DIAMETER RING. = 1" = 30 GALLONS =
70 GALLONS)
16:00 - A+B WASTE OIL SUB-CO OUT BY TYREE.
16:10 - ON BOARD VAC TRUCK - 60 GALLONS #2 F/O
590 " H_2O
- PADDED DRAIN FOR WEEKEND.
- NO FURTHER ACTION REQ'D. CAN CLOSE PENDING
DISPOSAL OF ±5 DRUMS SOLIDS.
16:20 - LEFT SITE
17:30 - OUT OF SERVICE. H.Q. STONY BROOK.

→ →


NORTH
GROUND FLOOR
CHIMINEY
EMERGENCY GENERATOR ROOM
DAY TANKS 100
25
STAIRS UP
GROUND-LEVEL
BASEMENT LEVEL
BOILER RM.
LEACHING BASIN
OPEN AREA/AIR INTAKE
GROUND FLOOR (CAFETERIA/LUNCH AREA)
CHIMNEY
1ST FLOOR
GROUND LEVEL
GRATING
STORAGE-FRESH AIR INTAKES
BOILER RM.
CONCRETE FLOOR
AFFECTED LEACHING BASIN

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 8907176

SPILL NAME: NEWSDAY PLANT **DEC LEAD:** NJACAMPO

SPILL DATE: 10/20/1989 **SPILL TIME:** 1:30 pm

CALL RECEIVED DATE: 10/20/1989 **RECEIVED TIME:** 2:00 pm

SPILL LOCATION

PLACE: NEWSDAY PLANT **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Affected Persons

FACILITY TYPE: Institutional, Educational, Gov., Other **WATERBODY:**

CALLER REMARKS:

PUMP OVERRAN NEAR AN EMERGENCY GENERATOR & SPILLED OUT. CONFINED IN BLDG & DRAINED INTO A DRYWELL. NEWSDAY HIRED TYREE

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
#2 fuel oil	Petroleum	40 G	0 G	Sewer,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY PLANT	235 PINELAWN ROAD MELVILLE NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ACAMPORA"

PIN **T & A** **COST CENTER**

CLASS: C1 **CLOSE DATE:** 08/23/1990 **MEETS STANDARDS:** True

Created On: 10/23/1989

Date Printed: 8/7/2018 Last Updated: 05/21/2009

92-012,46
+H+
melvee 11:22
5/18
BC

Cathy,

John Tillotson
Newsday
756-5458

Re: he wants to forward the results of the 'Tank Only' retest to you

P/c/b

92-01246
5.11.92

Spoke to John Tillotson
Tyree hired to pressure
test lines. Will
excavate vent + fill.
Dry As a Bone To
T/A 5.15.92 and
retest if tank passes.

C.G.

NEWSDAY

235 PINELAWN ROAD, MELVILLE, NY 11747-4250

FAX COVER SHEET

DATE: 5/21/98

TOTAL PAGES: 3
(INCLUDING THIS PAGE)

TO: Mary Hennigan
NYSDEC

FAX #: 444-0373

FROM:
DAVE KRUEGER
ENGINEERING SERVICES
(516) 843-5437
(516) 843-3444 FAX #

SUBJECT: '92 spill # 92-01246 manifest

Mary, I've contacted Tyrell Records Dept at least 4 times since you contacted me about the missing manifest for spill # 92-01246. Please let me know what our next step is.

Thnx

New York State Department of Environmental Conservation
Building 40--SUNY, Stony Brook, New York 11790-2356
(516)751-7725 or 751-7900
FAX 751-3839



Thomas C. Jorling
Commissioner

May 26, 1992

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. John Tillotson
Manager of Environmental Services
Newsday
235 Pinelawn Road
Melville, NY 11747

Re: Oil Spill Number 92-01246, Contaminated Soil Stockpile at Newsday, 235 Pinelawn Road, Melville

Dear Mr. Mr. Tillotson:

On May 15, approximately two (2) cubic yards of #2 fuel oil contaminated soil were excavated and stockpiled at the above referenced site.

In accordance with Article 12 of the New York State Navigation Law, the contaminated soil must be expeditiously removed in order to effect a prompt and complete cleanup. A contractor with a Part 364 (waste transporter) Permit is required for such removal. You may contact our Division of Solid and Hazardous Waste at (516) 751-7900 for further information concerning the legal transport and disposal of the contaminated soil.

The soil may be temporarily stored on site while final transport and disposal is arranged. An impermeable liner must remain both above and below the soil to prevent further contamination to the site.

This site has been placed on the Department's active petroleum spill site list. It has been assigned the above referenced spill number. The site will remain on the active list until copies of the disposal receipts are received and, if necessary, all additional clean-up/remedial work is performed.

If you have any questions or comments regarding this matter, please call me at (516)751-7725 or 751-7900.

Sincerely,

Cathy A. Gibbons

Cathy A. Gibbons
Environmental Engineer

CAG:jf
cc: D. Rice, File

printed on recycled paper

Rec'd 6/1/92 JT

Newsday

Long Island, NY 11747

John Tillotson
Manager of Environmental Service
Administrative Services
516 756-5458

September 28, 1992

Mr. Larry Tyree
Larry E. Tyree Company, Inc.
208 Route 109
Farmingdale, New York 11735

Re: Oil Spill No: 92-01246

Dear Mr. Tyree:

I am writing to you to remind you that as of today, I have not received confirmation of the disposition of the debris removed from Newsday. As you recall, after the new fill pipes were installed onto our two fuel oil tanks, there was a minimal amount of soil. The project was completed on May 22, 1992.

It was not until June 4 that a crew removed the old concrete, piping, fittings, and some of the dirt removed from the opening. The remaining soil, approximately three cubic feet, was covered with plastic. A follow-up visit was made by an individual from your lab, on June 17, to take a sample from the pile. By the time a second person from your lab showed up to take another sample, the soil had been removed.

According to the New York State Department of Environmental Conservation, this project is still on their active petroleum spill site list. They are awaiting confirmation from you as to the disposition of the material. I would appreciate your attention and a rapid conclusion to this project.

Sincerely,

John Tillotson

92-01246
4/1/+

New York State Department of Environmental Conservation
Building 40—SUNY, Stony Brook, New York 11790-2356
(516)751-7725 or 751-7900
FAX 751-3839



Thomas C. Jorling
Commissioner

May 26, 1992

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. John Tillotson
Manager of Environmental Services
Newsday
235 Pinelawn Road
Melville, NY 11747

Re: Oil Spill Number 92-01246, Contaminated Soil Stockpile at Newsday, 235 Pinelawn Road, Melville

Dear Mr. Mr. Tillotson:

On May 15, approximately two (2) cubic yards of #2 fuel oil contaminated soil were excavated and stockpiled at the above referenced site.

In accordance with Article 12 of the New York State Navigation Law, the contaminated soil must be expeditiously removed in order to effect a prompt and complete cleanup. A contractor with a Part 364 (waste transporter) Permit is required for such removal. You may contact our Division of Solid and Hazardous Waste at (516) 751-7900 for further information concerning the legal transport and disposal of the contaminated soil.

The soil may be temporarily stored on site while final transport and disposal is arranged. An impermeable liner must remain both above and below the soil to prevent further contamination to the site.

This site has been placed on the Department's active petroleum spill site list. It has been assigned the above referenced spill number. The site will remain on the active list until copies of the disposal receipts are received and, if necessary, all additional clean-up/remedial work is performed.

If you have any questions or comments regarding this matter, please call me at (516)751-7725 or 751-7900.

Sincerely,

Cathy A. Gibbons

Cathy A. Gibbons
Environmental Engineer

CAG:jf
cc: D. Rice, File

printed on recycled paper

CERTIFIED #P 061 497 548

New York State Department of Environmental Conservation
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
TEL # (516) 444-0320
FAX # (516) 444-0373

John P. Cahill
Commissioner

May 26, 1998

CERTIFIED LETTER - RETURN RECEIPT REQUESTED

Mr. Dave Krueger
Engineering Services
Newsday
235 Pinelawn Road
Melville, New York 11747

Re: Spill #92-01246, Newsday, 235 Pinelawn Road, Melville, N.Y.

Dear Mr. Krueger:

This letter if to confirm our telephone conversation of May 22, 1998, regarding the above referenced site. Based on this conversation, you have advised this office that you and/or your contractor have not been able to provide documentation pursuant to Cathy Gibbon's letter of May 26, 1992, to prove disposal of approximately 2 yards of contaminated soil stockpiled during this cleanup.

Please be advised that you may be subject to future liability if you do not have adequate documentation verifying proper disposal. Should additional environmental problems be discovered at this site, this office will require future action at that time. At this time, the spill file has been removed from our active spill list.

Sincerely,


Mary M. Henning

Mary M. Henning
Engineering Aide

MMH:ap
cc: N. Acampora, NYSDEC

92-01246
H+H

New York State Department of Environmental Conservation
Building 40—SUNY, Stony Brook, New York 11790-2356
(516) 751-7900
FAX # 516-751-3839



Thomas C. Jorling
Commissioner

May 6, 1992

CERTIFIED LETTER - RETURN RECEIPT REQUESTED

Mr. John Tillotson
Newsday
235 Pinelawn Road
Melville, NY 11747

Re: Spill #92-01246, Newsday, 235 Pinelawn Road, Melville, NY

Dear Mr. Tillotson:

This office has been informed by Dry-As-A-Bone that one (1) 25,000 gallon #26 fuel oil tank failed a Horner EZY Check systems test on April 30, 1992. In accordance with Article 12 of the New York State Navigation law, I must determine if there has been any harm to the groundwaters of the State. In order for me to make this determination, you have three options:

1. Prove that it was not a leaking tank by removing all the piping from the tank and separately Horner test the tank. If the tank passes the Horner test, it is a piping leak. The tank may then be abandoned or the piping can be repaired, attached to the tank, and the system Horner E-Zy check tested. If at any time contaminated soil is found, this office must be notified immediately and the contaminated soil removed and stockpiled on site.

2. Excavate and remove the tank in the presence of a representative from this office so that an inspection of the tank and the soil can be made. If the tank is sound, and there is no evidence of product loss, nothing further need be done. If there is a problem, proceed as in 3 below.

3. Abandon the tank in-place and install several four(4) inch diameter PVC site wells extending ten(10) feet into the groundwater with a screen length of twenty(20) feet, with slot size of .020 inches. The exact location and number of wells will be determined by a representative from this office. These wells must be checked by you or your contractor, with the monitoring data submitted to this office. If no floating/dissolved product appears in the wells for twelve consecutive months, then this office will review the case for possible removal from our active list. If floating/dissolved product appears, recovery must begin immediately.

printed on recycled paper

Please be advised that the in-place abandonment of underground tanks may be prohibited in some areas. You should check with the appropriate local or county authority (health department, fire marshal, environmental control unit) regarding local laws governing the storage of petroleum products.

Please call Karen DeRosa at 516-751-7900 ext. 269 or me at ext. 365, to let us know which option you will select to resolve this problem. If no response is received from you by May 15, 1992, this office will proceed with the installation of observation wells and will seek reimbursement from you in accordance with Article 12 of the New York State Navigation Law.

Sincerely,

Cathy A. Gibbons

Cathy A. Gibbons
Environmental Engineer

CAG:ic
cc: J. Pim, SCDHS
W. Parish, NYSDEC

SUFFOLK COUNTY DEPARTMENT OF HEALTH SERVICES

RECEIVED

TANK TEST COVER SHEET

MAY 04 1992

REG. 1
OIL SPILLS

FACILITY INFORMATION:

Facility Name: Newsday

Address: 235 Pinelawn
Melville

Facility ID #*: 4-00094

*If not available provide Tax Map # (Dist-Sect-Blk-Lot)

TANK TESTING COMPANY INFORMATION:

Dry As A Bone Inc.
69 Capitolian Blvd.
Rockville Centre
New York 11570

Company Name:

Technician Name: Jerry Curtin

Technician License #: Company #32 Oper. #95

TANK INFORMATION:

Spill # 9201246

Tank #	Size	Type	Age	Contents	Test Date	Results	I/R
6	25000	Steel	14	#2 oil	4/30/92	Failed -.493	I
7	25000	Steel	14	#2 oil	4/30/92	Passed -.053	I

Size - volume in gallons
Type - steel, FRP, DWFRP, etc.
Age - approximate age in years
Contents - gasoline, #2 heating oil, waste oil, caustic, etc.
I/R - initial test / retest

HORNER EZY CHEK II 9201246

OWNER OR DEALER Newsday Jan IO 4-00 94

ADDRESS (NO. & STREET) 235 Pinelawn Rd Tank #6

CITY AND STATE Melville

TANK INFORMATION

Tank 2 South

CAPACITY (NOMINAL) 25000

CAPACITY (CHART) 25098

NUMBER OF GALLONS ADDED 30

TOTAL CAPACITY 25128


CONTENTS (PRODUCT) #2 oil

CALIBRATION NUMBER 305

MONITOR MODE RESULTS

TANK LAYOUT

TIME	RESULT	CI
15 54	-.214	015
1612	-.413	011
1613 Test Mode Started		



COEFFICIENT CALCULATIONS

MEASURED API GRAVITY 33.2

PRODUCT TEMPERATURE 60°

API SPECIFIC GRAVITY @ 60 F. 33.0 + .2 = 33.2 (FROM TABLE A)

COEFFICIENT OF EXPANSION 455 (FROM TABLE B)

HORNER EZY CHEK II TEST LOG

SITE ARRIVAL TIME 645 am,pm

CONTACT PERSON John Tillison

TIME OF PRODUCT DELIVERY 4/20 am,pm

AMOUNT OF PRODUCT TO TOP OFF _____

TIME OF EQUIPMENT SET UP 730 am,pm

CHANGES TO TANK SYSTEM _____

ESTIMATED AMOUNT OF PRODUCT TO MAINTAIN TEST LEVEL 135.9

TIME TEST LEVEL WAS MAINTAINED 1000 am,pm

TIME OF .4 PSI DROP 1000 am,pm

TIME OF CALIBRATION 12 am (pm)


TIME OF TEST COMPLETION _____ am,pm

DEPTH OF WATER TABLE _____

REMARKS _____

OPERATOR _____

Vent & Lines 84
Tank Prod 49
Equipment 29
135.9



A.	Tank Ect. to Grade	154"
B.	Tank Top to Grade	27"
C.	Tank Diameter	126"
D.	Test Level above grade	57.30"
E.	Depth of water in tank	0"
F.	Depth for taking sample	80"
G.	Temp. Probe depth (connector)	29"
H.	Test level to Tank Ect.	184"
I.	Groundwater above tank bottom	0
J.	Product Pressure per 1" height	.031 PSI

Test Pressure Formula

184 (H) × .031 (J) − (____ (I) × .036) = 5.7 NET TEST PRESSURE

NEWSDAY FAC ID 4-0094
235 PINELAWN RD.
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: TANK# 6 #2 OIL
CAPACITY TANK 1: 25128 GALLONS
TEMPERATURE COEFFICIENT: 455 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

04/30/92 TEST TIME FROM 16:13 TO 17:20
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: -0.494 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.049 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.493 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.002 GPH
(-0.492 TO -0.495 GPH)

TESTER.....

CUSTOMER.....

NEWSDAY FAC ID 4-0094
235 PINELAWN RD.
MELVILLE
DATE: 04/30/92 TIME: 15:37
FUEL TYPE: TANK# 6 #2 OIL
CAPACITY TANK 1: 25128 GALLONS
TEST CRITERIA: +0.00 GPH TO +0.00 GPH
TEMPERATURE COEFFICIENT: 455 ppm/deg F
RELATIVE FUEL TEMPERATURE 51.50 deg F
VOLUME CHANGE PER DEG F: 11.43 GALLONS

TANK TESTER VER 2.01

	TANK 1 CAPACITY CHANGE GALLONS				TANK 2 CAPACITY CHANGE GALLONS			
TIME	VOLUME	TEMP.	NET	RATE GPH	VOLUME	TEMP.	NET	RATE GPH
15:38	+0.0000	+0.0000	+0.0000	+0.000				
15:38	-0.0003	-0.0001	-0.0002	-0.017				
15:39	-0.0004	-0.0000	-0.0004	-0.028				
15:39	-0.0006	-0.0000	-0.0006	-0.039				
15:40	-0.0007	-0.0000	-0.0006	-0.047				
15:40	-0.0008	+0.0000	-0.0008	-0.055				
15:41	-0.0009	+0.0000	-0.0009	-0.062				
15:41	-0.0010	+0.0001	-0.0012	-0.071				
15:42	-0.0012	+0.0002	-0.0014	-0.080				
15:43	-0.0013	+0.0002	-0.0015	-0.089				
15:43	-0.0014	+0.0002	-0.0016	-0.098				
15:44	-0.0015	+0.0002	-0.0017	-0.106				
15:44	-0.0016	+0.0002	-0.0018	-0.114				
15:45	-0.0017	+0.0002	-0.0019	-0.121				
15:45	-0.0018	+0.0002	-0.0020	-0.129				
15:46	-0.0019	+0.0002	-0.0021	-0.135				
15:47	-0.0020	+0.0002	-0.0022	-0.142				
15:47	-0.0021	+0.0002	-0.0023	-0.149				
15:48	-0.0021	+0.0002	-0.0023	-0.155				
15:48	-0.0022	+0.0002	-0.0024	-0.161				
15:49	-0.0023	+0.0002	-0.0024	-0.167				
15:49	-0.0024	+0.0002	-0.0026	-0.172				
15:50	-0.0024	+0.0002	-0.0026	-0.178				
15:50	-0.0025	+0.0002	-0.0026	-0.183				
15:51	-0.0025	+0.0002	-0.0027	-0.188				
15:52	-0.0026	+0.0002	-0.0027	-0.193				
15:52	-0.0026	+0.0001	-0.0027	-0.197				
15:53	-0.0027	+0.0002	-0.0028	-0.202				
15:53	-0.0027	+0.0001	-0.0029	-0.206				
15:54	-0.0028	+0.0001	-0.0029	-0.210				
15:54	-0.0028	+0.0001	-0.0029	-0.214				
15:55	+0.0000	+0.0000	+0.0000	+0.000				
15:55	-0.0029	+0.0002	-0.0031	-0.336				
15:56	-0.0031	+0.0002	-0.0032	-0.339				
15:57	-0.0029	+0.0002	-0.0031	-0.337				
15:57	-0.0030	+0.0002	-0.0032	-0.340				
15:58	-0.0031	+0.0002	-0.0033	-0.342				
15:58	-0.0031	+0.0002	-0.0033	-0.344				
15:59	-0.0032	+0.0002	-0.0034	-0.347				
15:59	-0.0032	+0.0002	-0.0035	-0.350				
16:00	-0.0032	+0.0002	-0.0035	-0.353				

16:01	-0.0033	+0.0002	-0.0035	-0.355
16:01	-0.0033	+0.0002	-0.0035	-0.358
16:02	-0.0033	+0.0002	-0.0036	-0.360
16:02	-0.0034	+0.0003	-0.0036	-0.362
16:03	-0.0034	+0.0003	-0.0037	-0.365
16:03	-0.0034	+0.0003	-0.0036	-0.367
16:04	-0.0034	+0.0003	-0.0037	-0.369
16:04	-0.0035	+0.0003	-0.0037	-0.371
16:05	-0.0035	+0.0003	-0.0038	-0.373
16:06	-0.0035	+0.0003	-0.0038	-0.374
16:06	-0.0036	+0.0003	-0.0039	-0.376
16:07	-0.0036	+0.0003	-0.0039	-0.378
16:07	-0.0036	+0.0003	-0.0039	-0.380
16:08	-0.0036	+0.0013	-0.0049	-0.383
16:08	-0.0037	+0.0014	-0.0051	-0.387
16:09	-0.0037	+0.0014	-0.0051	-0.391
16:09	-0.0037	+0.0014	-0.0051	-0.396
16:10	-0.0037	+0.0013	-0.0050	-0.400
16:11	-0.0037	+0.0013	-0.0050	-0.405
16:11	-0.0038	+0.0003	-0.0041	-0.409
16:12	-0.0038	+0.0003	-0.0041	-0.413
16:12	+0.0000	+0.0000	+0.0000	+0.000
16:13	-0.0038	+0.0003	-0.0041	-0.434
16:13	+0.0000	+0.0000	+0.0000	+0.000*
16:14	-0.0039	+0.0003	-0.0042	-0.457
16:15	-0.0040	+0.0003	-0.0043	-0.455
16:15	-0.0039	+0.0003	-0.0042	-0.455
16:16	-0.0039	+0.0003	-0.0042	-0.454
16:16	-0.0039	+0.0003	-0.0042	-0.455
16:17	-0.0040	+0.0003	-0.0042	-0.455
16:17	-0.0040	+0.0003	-0.0043	-0.454
16:18	-0.0040	+0.0003	-0.0043	-0.454
16:18	-0.0040	+0.0003	-0.0043	-0.455
16:19	-0.0040	+0.0003	-0.0043	-0.455
16:20	-0.0041	+0.0003	-0.0043	-0.456
16:20	-0.0040	+0.0003	-0.0043	-0.457
16:21	-0.0040	+0.0003	-0.0043	-0.458
16:21	-0.0041	+0.0003	-0.0043	-0.458
16:22	-0.0040	+0.0003	-0.0043	-0.459
16:22	-0.0041	+0.0003	-0.0043	-0.459
16:23	-0.0041	+0.0003	-0.0043	-0.460
16:23	-0.0041	+0.0003	-0.0044	-0.460
16:24	-0.0041	+0.0003	-0.0044	-0.460
16:25	-0.0041	+0.0003	-0.0044	-0.461
16:25	-0.0041	+0.0003	-0.0044	-0.461
16:26	-0.0041	+0.0003	-0.0044	-0.461
16:26	-0.0041	+0.0003	-0.0043	-0.462
16:27	-0.0041	+0.0003	-0.0044	-0.462
16:27	-0.0041	+0.0003	-0.0044	-0.462
16:28	-0.0041	+0.0002	-0.0043	-0.463
16:29	-0.0041	+0.0002	-0.0043	-0.463
16:29	-0.0041	+0.0002	-0.0043	-0.463
16:30	-0.0041	+0.0002	-0.0044	-0.463
16:30	-0.0042	+0.0002	-0.0044	-0.463
16:31	-0.0041	+0.0002	-0.0043	-0.464
16:31	-0.0041	+0.0003	-0.0043	-0.464
16:32	-0.0040	+0.0002	-0.0043	-0.464
16:32	-0.0040	+0.0003	-0.0043	-0.464
16:33	-0.0041	+0.0003	-0.0043	-0.464
16:34	-0.0040	+0.0003	-0.0043	-0.464

```
16:34   -0.0040  +0.0003 -0.0043 -0.464
16:35   -0.0040  +0.0003 -0.0043 -0.464
16:35   -0.0040  +0.0003 -0.0043 -0.464
16:36   -0.0040  +0.0003 -0.0043 -0.464
16:36   -0.0040  +0.0003 -0.0042 -0.464
16:37   -0.0040  +0.0003 -0.0043 -0.464
16:37   -0.0040  +0.0003 -0.0043 -0.463
16:38   -0.0040  +0.0003 -0.0043 -0.463
16:39   -0.0040  +0.0003 -0.0043 -0.463
16:39   -0.0040  +0.0013 -0.0053 -0.463
16:40   -0.0040  +0.0003 -0.0043 -0.464
16:40   -0.0040  +0.0014 -0.0054 -0.464
16:41   -0.0040  +0.0014 -0.0054 -0.465
16:41   -0.0040  +0.0014 -0.0054 -0.465
16:42   -0.0040  +0.0013 -0.0054 -0.466
16:43   -0.0040  +0.0013 -0.0053 -0.467
16:43   -0.0041  +0.0013 -0.0053 -0.469
16:44   -0.0041  +0.0003 -0.0044 -0.470
16:44   -0.0041  +0.0003 -0.0044 -0.471
16:45   -0.0041  +0.0003 -0.0044 -0.471
16:45   -0.0041  +0.0003 -0.0044 -0.472
16:46   -0.0041  +0.0003 -0.0044 -0.473
16:46   -0.0041  +0.0003 -0.0044 -0.474
VOLUME RATE OF CHANGE          -0.474 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.003 GPH
RELATIVE FUEL TEMPERATURE: 51.50 deg F

16:47   -0.0041  +0.0003 -0.0044 -0.474
16:48   -0.0041  +0.0003 -0.0044 -0.475
16:48   -0.0041  +0.0013 -0.0054 -0.475
16:49   -0.0042  +0.0014 -0.0056 -0.476
16:49   -0.0042  +0.0014 -0.0056 -0.477
16:50   -0.0042  +0.0014 -0.0056 -0.478
16:50   -0.0042  +0.0013 -0.0055 -0.479
16:51   -0.0042  +0.0013 -0.0055 -0.480
16:51   -0.0042  +0.0003 -0.0045 -0.481
16:52   -0.0042  +0.0003 -0.0045 -0.482
16:53   -0.0043  +0.0003 -0.0046 -0.482
16:53   -0.0042  +0.0003 -0.0045 -0.483
16:54   -0.0042  +0.0003 -0.0045 -0.484
16:54   -0.0043  +0.0003 -0.0045 -0.485
16:55   -0.0043  +0.0003 -0.0045 -0.485
16:55   -0.0043  +0.0003 -0.0046 -0.486
16:56   -0.0043  +0.0003 -0.0045 -0.486
16:57   -0.0043  +0.0003 -0.0045 -0.487
16:57   -0.0043  +0.0003 -0.0046 -0.487
16:58   -0.0043  +0.0003 -0.0046 -0.488
16:58   -0.0043  +0.0003 -0.0046 -0.488
16:59   -0.0043  +0.0003 -0.0046 -0.488
16:59   -0.0043  +0.0003 -0.0046 -0.489
17:00   -0.0043  +0.0003 -0.0046 -0.489
17:00   -0.0043  +0.0003 -0.0046 -0.489
17:01   -0.0043  +0.0003 -0.0046 -0.489
17:02   -0.0043  +0.0003 -0.0046 -0.490
17:02   -0.0044  +0.0003 -0.0046 -0.490
17:03   -0.0043  +0.0003 -0.0046 -0.490
17:03   -0.0043  +0.0003 -0.0046 -0.490
VOLUME RATE OF CHANGE          -0.490 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.003 GPH
RELATIVE FUEL TEMPERATURE: 51.50 deg F
```

17:04	-0.0043	+0.0003	-0.0046	-0.491
17:04	-0.0043	+0.0003	-0.0045	-0.491
17:05	-0.0043	+0.0003	-0.0046	-0.491
17:05	-0.0043	+0.0003	-0.0046	-0.491
17:06	-0.0043	+0.0003	-0.0046	-0.491
17:07	-0.0043	+0.0003	-0.0046	-0.491
17:07	-0.0043	+0.0003	-0.0046	-0.491
17:08	-0.0043	+0.0003	-0.0046	-0.492
17:08	-0.0043	+0.0003	-0.0046	-0.492
17:09	-0.0043	+0.0003	-0.0046	-0.492
17:09	-0.0043	+0.0003	-0.0046	-0.492
17:10	-0.0043	+0.0003	-0.0046	-0.492
17:11	-0.0043	+0.0003	-0.0046	-0.492
17:11	-0.0043	+0.0003	-0.0046	-0.492
17:12	-0.0043	+0.0003	-0.0046	-0.492
17:12	-0.0043	+0.0003	-0.0046	-0.492
17:13	-0.0043	+0.0003	-0.0046	-0.492
17:13	-0.0043	+0.0003	-0.0046	-0.492
17:14	-0.0043	+0.0013	-0.0055	-0.493
17:14	-0.0043	+0.0003	-0.0046	-0.493
17:15	-0.0043	+0.0003	-0.0046	-0.493
17:16	-0.0043	+0.0003	-0.0046	-0.493
17:16	-0.0043	+0.0003	-0.0046	-0.493
17:17	-0.0043	+0.0003	-0.0045	-0.493
17:17	-0.0043	+0.0003	-0.0046	-0.493
17:18	-0.0042	+0.0003	-0.0045	-0.493
17:18	-0.0043	+0.0003	-0.0046	-0.493
17:19	-0.0042	+0.0003	-0.0045	-0.493
17:19	-0.0043	+0.0003	-0.0046	-0.493
17:20	-0.0043	+0.0013	-0.0056	-0.493

VOLUME RATE OF CHANGE -0.493 GPH
95 % CONFIDENCE INTERVAL: +/-0.002 GPH
RELATIVE FUEL TEMPERATURE: 51.50 deg F

Newsday

Long Island, NY 11747

92-01246

+++ melvels

John Tillotson
Manager of Environmental Services
Administrative Services
516 756-5458

May 11, 1992

RECEIVED
MAY 12 1992
REG. 1
OIL SPILLS

Ms. Cathy A. Gibbons
New York State Department of
Environmental Conservation
Building 40 - SUNY
Stony Brook, New York 11790-2356

Re: Spill No: 92-01246 .....CERTIFIED, RETURN RECEIPT REQUESTED

Dear Ms. Gibbons:

I am responding to your correspondence of May 6 that was received at Newsday on May 11. Newsday has contracted with Tyree Environmental to expose all tank penetrations and disconnect all piping from the tank. The excavations were performed on Friday May 8 and Monday May 11.

The testing company of Dry-As-A-Bone, Inc. has scheduled a tank-only test for Friday, May 15. After completion of the tank-only test, each leg of the piping will be reconnected and tested independently. The final test will be a full system test with all piping attached. Through this procedure, we will be able to identify which of the components may have caused the previous test results.

As we had discussed during our telephone conversation of May 11, I will notify you as to the results of the above tests that will be performed on May 15.

Sincerely,

John Tillotson

92-01246

Newsday

Long Island, NY 11747

John Tillotson
Manager of Environmental Services
Administrative Services
516 756-5458

May 18, 1992

Ms. Cathy Gibbons
New York State Department of
Environmental Conservation
Building 40 - SUNY
Stony Brook, New York 11790-2356

RECEIVED
MAY 1992
REG. 1
OIL SPILLS

Re: Spill No: 92-01246... CERTIFIED, RETURN RECEIPT REQUESTED

Dear Ms. Gibbons:

As we had discussed, and as described in my correspondence of May 11, a tank-only and systems test was performed on Newsday's 25,000 gallon No: 2 fuel oil storage tank (Tank No: 6) on Friday May 15.

Excavations were made at each of the tank penetrations. The piping was disconnected and a tank-only tightness test was performed. The tank passed this test, see attached results.

All piping was reconnected and a system tightness test was performed. The system passed this test, see attached results.

During excavation at the fill line, there was an indication of oil leakage at a compression pipe clamp located immediately below the surface mounted fill cap. Prior to the system test, this connection was replaced with a pipe-pipe joint from the tank to the surface. It is believed that this compression joint may have been the cause of the original test failure. The compression joint would have been leaking only during the tightness test since it is above the top of the tank, i.e., the tank's operating level.

The amount of contaminated soil is estimated at less than two cubic yards and will be properly removed by Tyree Environmental as part of their contract responsibilities.

Sincerely,

John Tillotson

NEWSDAY FAC ID 4-0094
235 PINELAWN RD.
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: TANK ONLY TANK#6 #2OIL
CAPACITY TANK 1: 25106 GALLONS
TEMPERATURE COEFFICIENT: 457 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

05/15/92 TEST TIME FROM 10:22 TO 11:29
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: +0.000 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.049 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.045 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.001 GPH
(-0.044 TO -0.045 GPH)

TESTER.....

CUSTOMER.....

NEWSDAY FAC ID 4-0094
235 PINELAWN
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: SYSTEM TEST TANK#6 #2 OIL
CAPACITY TANK 1: 25133 GALLONS
TEMPERATURE COEFFICIENT: 457 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

05/15/92 TEST TIME FROM 16:43 TO 17:49
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: +0.060 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.075 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.014 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.002 GPH
(-0.012 TO -0.016 GPH)

NEWSDAY FAC ID 4-0094
235 PINELAWN
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: SYSTEM TEST TANK#6 #2 OIL
CAPACITY TANK 1: 25133 GALLONS
TEMPERATURE COEFFICIENT: 457 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

05/15/92 TEST TIME FROM 16:43 TO 17:49
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: +0.060 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.075 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.014 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.002 GPH
(-0.012 TO -0.016 GPH)

TESTER. .....

CUSTOMER .....

DRY AS A BONE, INC.

PRECISION TANK TESTING

PHONE:
516 678 5115
800 427 2454

69 Capitolian Boulevard
Rockville Centre, N.Y. 11570

May 16, 1992

RECEIVED
MAY 21 1992
REG. 1
OIL SPILLS

Mr. Ken Clunie
Suffolk County Dept. of Health Services
15 Horseblock Road
Farmingville, N.Y. 11738

RE: NEWSDAY TANK TEST RESULTS
SPILL #9201246

Enclosed is the data regarding the two (2) tank tests performed at the above site .

On 5/15/92, a tank only test was performed. Since the problem was the fill box, prior to testing, Tyree Brothers excavated to tank top and replaced fill box. The tank passed test criteria with a -.045 GPH at which time all piping was reconnected (feed return and vent). A systems test was performed passing test criteria with a -.014 GPH.

There is approximately one to two yards of contaminated soil from old fill box leakage which will be disposed of by Tyree Brothers.

If you have any questions regarding the above, please do not hesitate to call.

Very truly yours,

Jerry Curtin

JC/kc

cc: Ms. Kathy Gibbons
NYS DEC

Tank Only

HORNER ECY CHEK II Well # 92012

OWNER OR DEALER Newsday Inc ID 4-0094

ADDRESS (NO. & STREET) 235 Pinelawn Rd Tank #6

CITY AND STATE Melville

TANK INFORMATION

CAPACITY (NOMINAL) 25,000

CAPACITY (CHART) 25098

NUMBER OF GALLONS ADDED 8

TOTAL CAPACITY 25,106


CONTENTS (PRODUCT) #2 oil

CALIBRATION NUMBER 368

MONITOR MODE RESULTS

TIME	RESULT	CI
10:02	+030	003
10:19	-007	002
10:21	Test Mode Started	

TANK LAYOUT



COEFFICIENT CALCULATIONS

MEASURED API GRAVITY 34

PRODUCT TEMPERATURE 63

API SPECIFIC GRAVITY @ 60 F. 33.8 (FROM TABLE A)

COEFFICIENT OF EXPANSION 457 (FROM TABLE B)

HORNER ECV CHEK II TEST LOG

SITE ARRIVAL TIME 6:00 (am), pm

CONTACT PERSON John Tillerson

TIME OF PRODUCT DELIVERY 4/20 am, pm

AMOUNT OF PRODUCT TO TOP OFF _____

TIME OF EQUIPMENT SET UP 6:15 (am), pm

CHANGES TO TANK SYSTEM Tank On Ln Test

ESTIMATED AMOUNT OF PRODUCT TO MAINTAIN TEST LEVEL 49 00

TIME TEST LEVEL WAS MAINTAINED 6:45 am, pm

TIME OF .4 PSI DROP 6:45 am, pm Tank Ref - 49 00


TIME OF CALIBRATION 9:45 am, pm

TIME OF TEST COMPLETION _____ am, pm

DEPTH OF WATER TABLE _____

REMARKS Tank only

OPERATOR Jerry Cutter



A.	Tank Ect. to Grade	154
B.	Tank Top to Grade	27
C.	Tank Diameter	126
D.	Test Level above grade	5.7 30
E.	Depth of water in tank	0
F.	Depth for taking sample	80
G.	Temp. Probe depth (connector)	29
H.	Test level to Tank Ect.	184
I.	Groundwater above tank bottom	0
J.	Product Pressure per 1" height	031 PS

Test Pressure Formula

184 (H) × 031 (J) − (____ (I) × .036) = 5.7 NET TEST PRESSURE

Sec. 5/Pg. 2

Dry As A Bone Inc.
69 Capitolian Blvd.
Rockville Centre
New York 11570

NEWSDAY FAC ID 4-0094
235 PINELAWN RD.
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: TANK ONLY TANK#6 #2OIL
CAPACITY TANK 1: 25106 GALLONS
TEMPERATURE COEFFICIENT: 457 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

05/15/92 TEST TIME FROM 10:22 TO 11:29
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: +0.000 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.049 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.045 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.001 GPH
(-0.044 TO -0.045 GPH)

TESTER.....

CUSTOMER.....

NEWSDAY FAC ID 4-0094
235 PINELAWN RD.
MELVILLE
DATE: 05/15/92 TIME: 09:44
FUEL TYPE: TANK ONLY TANK#6 #2OIL
CAPACITY TANK 1: 25106 GALLONS
TEST CRITERIA: +0.00 GPH TO +0.00 GPH
TEMPERATURE COEFFICIENT: 457 ppm/deg F
RELATIVE FUEL TEMPERATURE 68.00 deg F
VOLUME CHANGE PER DEG F: 11.47 GALLONS

TANK TESTER VER 2.01

	TANK 1 CAPACITY CHANGE GALLONS				TANK 2 CAPACITY CHANGE GALLONS			
TIME	VOLUME	TEMP.	NET	RATE GPH	VOLUME	TEMP.	NET	RATE GPH
09:45	+0.0000	+0.0000	+0.0000	+0.000				
09:46	+0.0000	-0.0001	+0.0001	+0.008				
09:46	-0.0000	+0.0001	-0.0001	-0.001				
09:47	+0.0000	+0.0000	+0.0000	-0.000				
09:47	+0.0000	+0.0000	+0.0000	+0.001				
09:48	-0.0000	-0.0001	+0.0001	+0.002				
09:48	+0.0000	-0.0001	+0.0001	+0.003				
09:49	-0.0000	-0.0001	+0.0001	+0.003				
09:49	+0.0001	+0.0000	+0.0000	+0.004				
09:50	+0.0001	-0.0002	+0.0002	+0.005				
09:51	+0.0001	-0.0002	+0.0002	+0.007				
09:51	+0.0000	-0.0002	+0.0002	+0.008				
09:52	+0.0001	-0.0002	+0.0003	+0.010				
09:52	+0.0000	-0.0002	+0.0003	+0.012				
09:53	+0.0001	-0.0003	+0.0004	+0.013				
09:53	+0.0001	-0.0003	+0.0004	+0.015				
09:54	+0.0001	-0.0002	+0.0003	+0.017				
09:55	+0.0001	-0.0004	+0.0004	+0.018				
09:55	+0.0001	-0.0003	+0.0004	+0.020				
09:56	+0.0001	-0.0002	+0.0003	+0.021				
09:56	+0.0001	-0.0002	+0.0003	+0.022				
09:57	+0.0001	-0.0003	+0.0004	+0.023				
09:57	+0.0001	-0.0002	+0.0003	+0.024				
09:58	+0.0001	-0.0003	+0.0004	+0.025				
09:58	+0.0002	-0.0003	+0.0005	+0.026				
09:59	+0.0001	-0.0003	+0.0004	+0.027				
10:00	+0.0001	-0.0002	+0.0003	+0.028				
10:00	+0.0001	-0.0003	+0.0003	+0.028				
10:01	+0.0001	-0.0003	+0.0004	+0.029				
10:01	+0.0001	-0.0001	+0.0003	+0.030				
10:02	+0.0002	-0.0002	+0.0004	+0.030				
10:02	+0.0000	+0.0000	+0.0000	+0.000				
10:03	+0.0001	-0.0001	+0.0002	+0.026				
10:03	+0.0001	-0.0001	+0.0003	+0.027				
10:04	+0.0001	+0.0000	+0.0001	+0.021				
10:05	+0.0001	+0.0001	+0.0001	+0.017				
10:05	+0.0002	+0.0001	+0.0001	+0.014				
10:06	+0.0001	+0.0001	+0.0001	+0.013				
10:06	+0.0002	+0.0001	+0.0000	+0.011				
10:07	+0.0001	+0.0001	+0.0000	+0.010				
10:07	+0.0001	+0.0001	+0.0000	+0.009				

10:08	+0.0002	+0.0002	+0.0000	+0.008
10:09	+0.0001	+0.0002	-0.0001	+0.007
10:09	+0.0002	+0.0002	+0.0000	+0.006
10:10	+0.0001	+0.0002	-0.0001	+0.005
10:10	+0.0001	+0.0001	-0.0000	+0.004
10:11	+0.0001	+0.0003	-0.0001	+0.003
10:11	+0.0002	+0.0002	-0.0001	+0.002
10:12	+0.0002	+0.0002	-0.0001	+0.002
10:12	+0.0002	+0.0003	-0.0002	+0.001
10:13	+0.0002	+0.0003	-0.0002	-0.000
10:14	+0.0001	+0.0003	-0.0001	-0.001
10:14	+0.0002	+0.0003	-0.0002	-0.002
10:15	+0.0002	+0.0003	-0.0001	-0.003
10:15	+0.0001	+0.0002	-0.0001	-0.003
10:16	+0.0002	+0.0003	-0.0001	-0.004
10:16	+0.0001	+0.0003	-0.0002	-0.004
10:17	+0.0001	+0.0004	-0.0002	-0.005
10:17	+0.0001	+0.0003	-0.0002	-0.006
10:18	+0.0001	+0.0003	-0.0001	-0.006
10:19	+0.0002	+0.0003	-0.0001	-0.007
10:19	+0.0000	+0.0003	-0.0003	-0.007
10:20	+0.0000	+0.0000	+0.0000	+0.000
10:20	+0.0002	+0.0003	-0.0002	-0.017
10:21	+0.0002	+0.0003	-0.0002	-0.018
10:21	+0.0002	+0.0004	-0.0001	-0.018
10:22	+0.0000	+0.0000	+0.0000	+0.000*
10:23	+0.0001	+0.0003	-0.0002	-0.023
10:23	+0.0001	+0.0004	-0.0002	-0.022
10:24	+0.0002	+0.0004	-0.0002	-0.021
10:24	+0.0002	+0.0004	-0.0002	-0.021
10:25	+0.0001	+0.0004	-0.0002	-0.022
10:25	+0.0001	+0.0004	-0.0003	-0.023
10:26	+0.0000	+0.0004	-0.0003	-0.025
10:26	+0.0000	+0.0004	-0.0003	-0.026
10:27	+0.0001	+0.0004	-0.0002	-0.027
10:28	+0.0001	+0.0004	-0.0003	-0.027
10:28	+0.0001	+0.0004	-0.0003	-0.028
10:29	+0.0002	+0.0004	-0.0002	-0.028
10:29	+0.0001	+0.0004	-0.0002	-0.028
10:30	+0.0001	+0.0004	-0.0003	-0.028
10:30	+0.0000	+0.0004	-0.0003	-0.028
10:31	+0.0001	+0.0004	-0.0003	-0.029
10:31	+0.0001	+0.0004	-0.0003	-0.029
10:32	+0.0001	+0.0004	-0.0003	-0.029
10:33	+0.0000	+0.0004	-0.0003	-0.029
10:33	+0.0000	+0.0004	-0.0004	-0.030
10:34	+0.0000	+0.0004	-0.0004	-0.030
10:34	+0.0000	+0.0004	-0.0004	-0.030
10:35	+0.0000	+0.0004	-0.0004	-0.031
10:35	+0.0001	+0.0004	-0.0004	-0.031
10:36	+0.0000	+0.0004	-0.0004	-0.032
10:37	-0.0000	+0.0004	-0.0004	-0.032
10:37	-0.0000	+0.0004	-0.0004	-0.032
10:38	-0.0000	+0.0004	-0.0004	-0.033
10:38	-0.0000	+0.0004	-0.0004	-0.033
10:39	-0.0000	+0.0004	-0.0004	-0.034
10:39	-0.0001	+0.0004	-0.0004	-0.034
10:40	-0.0000	+0.0004	-0.0004	-0.034
10:40	-0.0001	+0.0004	-0.0005	-0.035
10:41	-0.0000	+0.0004	-0.0004	-0.035

```
10:42   -0.0001  +0.0004 -0.0005 -0.036
10:42   -0.0000  +0.0004 -0.0004 -0.036
10:43   +0.0000  +0.0004 -0.0004 -0.036
10:43   -0.0000  +0.0004 -0.0005 -0.037
10:44   +0.0000  +0.0004 -0.0004 -0.037
10:44   -0.0000  +0.0004 -0.0004 -0.037
10:45   +0.0000  +0.0004 -0.0004 -0.038
10:45   +0.0001  +0.0004 -0.0003 -0.038
10:46   +0.0001  +0.0004 -0.0003 -0.038
10:47   +0.0001  +0.0004 -0.0004 -0.038
10:47   -0.0000  +0.0004 -0.0004 -0.039
10:48   +0.0000  +0.0004 -0.0004 -0.039
10:48   +0.0000  +0.0004 -0.0003 -0.039
10:49   +0.0000  +0.0004 -0.0004 -0.039
10:49   -0.0000  +0.0004 -0.0004 -0.039
10:50   +0.0000  +0.0004 -0.0003 -0.039
10:51   -0.0000  +0.0004 -0.0004 -0.039
10:51   -0.0000  +0.0004 -0.0004 -0.039
10:52   -0.0000  +0.0004 -0.0004 -0.040
10:52   -0.0000  +0.0004 -0.0004 -0.040
10:53   -0.0000  +0.0004 -0.0004 -0.040
10:53   -0.0000  +0.0004 -0.0004 -0.040
10:54   +0.0000  +0.0004 -0.0003 -0.040
10:54   +0.0002  +0.0004 -0.0002 -0.040
10:55   +0.0000  +0.0004 -0.0003 -0.040
VOLUME RATE OF CHANGE          -0.040 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.001 GPH
RELATIVE FUEL TEMPERATURE: 68.00 deg F

10:56   +0.0001  +0.0004 -0.0003 -0.040
10:56   +0.0000  +0.0004 -0.0004 -0.040
10:57   -0.0000  +0.0004 -0.0004 -0.040
10:57   -0.0000  +0.0004 -0.0004 -0.040
10:58   +0.0000  +0.0004 -0.0004 -0.040
10:58   -0.0000  +0.0004 -0.0004 -0.040
10:59   +0.0000  +0.0004 -0.0004 -0.040
10:59   -0.0001  +0.0004 -0.0004 -0.040
11:00   -0.0001  +0.0004 -0.0005 -0.040
11:01   -0.0001  +0.0004 -0.0004 -0.040
11:01   -0.0001  +0.0004 -0.0005 -0.040
11:02   -0.0001  +0.0004 -0.0004 -0.040
11:02   -0.0001  +0.0004 -0.0005 -0.040
11:03   -0.0001  +0.0004 -0.0005 -0.040
11:03   -0.0001  +0.0004 -0.0005 -0.040
11:04   -0.0000  +0.0004 -0.0004 -0.040
11:05   +0.0000  +0.0004 -0.0004 -0.040
11:05   -0.0000  +0.0004 -0.0005 -0.040
11:06   -0.0001  +0.0004 -0.0005 -0.041
11:06   -0.0001  +0.0004 -0.0005 -0.041
11:07   -0.0000  +0.0004 -0.0005 -0.041
11:07   +0.0000  +0.0004 -0.0004 -0.041
11:08   -0.0001  +0.0004 -0.0005 -0.041
11:08   -0.0000  +0.0005 -0.0005 -0.041
11:09   +0.0000  +0.0005 -0.0004 -0.041
11:10   -0.0000  +0.0005 -0.0005 -0.041
11:10   -0.0000  +0.0005 -0.0005 -0.041
11:11   -0.0000  +0.0005 -0.0005 -0.041
11:11   -0.0000  +0.0005 -0.0005 -0.041
11:12   -0.0001  +0.0005 -0.0006 -0.042
VOLUME RATE OF CHANGE          -0.042 GPH
```

95 % CONFIDENCE INTERVAL: +/-0.000 GPH
RELATIVE FUEL TEMPERATURE: 68.01 deg F

11:12	-0.0000	+0.0005	-0.0005	-0.042
11:13	-0.0000	+0.0005	-0.0005	-0.042
11:13	-0.0000	+0.0005	-0.0005	-0.042
11:14	-0.0001	+0.0004	-0.0005	-0.042
11:15	-0.0000	+0.0005	-0.0005	-0.042
11:15	-0.0001	+0.0004	-0.0006	-0.042
11:16	-0.0000	+0.0004	-0.0005	-0.042
11:16	-0.0000	+0.0004	-0.0005	-0.042
11:17	-0.0000	+0.0004	-0.0005	-0.043
11:17	-0.0001	+0.0004	-0.0005	-0.043
11:18	-0.0000	+0.0004	-0.0005	-0.043
11:19	-0.0000	+0.0005	-0.0005	-0.043
11:19	-0.0001	+0.0005	-0.0006	-0.043
11:20	-0.0000	+0.0005	-0.0005	-0.043
11:20	-0.0000	+0.0005	-0.0005	-0.043
11:21	-0.0000	+0.0005	-0.0005	-0.043
11:21	-0.0000	+0.0005	-0.0005	-0.043
11:22	-0.0001	+0.0005	-0.0005	-0.044
11:22	-0.0000	+0.0005	-0.0005	-0.044
11:23	-0.0000	+0.0005	-0.0005	-0.044
11:24	-0.0000	+0.0005	-0.0005	-0.044
11:24	+0.0000	+0.0005	-0.0004	-0.044
11:25	+0.0000	+0.0005	-0.0005	-0.044
11:25	+0.0000	+0.0005	-0.0005	-0.044
11:26	+0.0001	+0.0005	-0.0004	-0.044
11:26	+0.0000	+0.0005	-0.0004	-0.044
11:27	+0.0000	+0.0005	-0.0004	-0.044
11:27	+0.0000	+0.0005	-0.0004	-0.044
11:28	+0.0000	+0.0005	-0.0004	-0.045
11:29	+0.0000	+0.0005	-0.0004	-0.045

VOLUME RATE OF CHANGE -0.045 GPH
95 % CONFIDENCE INTERVAL: +/-0.001 GPH
RELATIVE FUEL TEMPERATURE: 68.01 deg F

HORNER ECV CHEK II TEST LOG

SITE ARRIVAL TIME 6 00 am, pm

CONTACT PERSON John Tolliver

TIME OF PRODUCT DELIVERY 4 20 am, pm

AMOUNT OF PRODUCT TO TOP OFF _____

TIME OF EQUIPMENT SET UP 6'5 am, pm

CHANGES TO TANK SYSTEM Connect all piping for System Test

ESTIMATED AMOUNT OF PRODUCT TO MAINTAIN TEST LEVEL _____

TIME TEST LEVEL WAS MAINTAINED 13 00 am, pm

TIME OF .4 PSI DROP 13 00 am, pm


TIME OF CALIBRATION 16 00 am, pm

TIME OF TEST COMPLETION _____ am, pm

DEPTH OF WATER TABLE 0

REMARKS System Test

OPERATOR Jerry Cutts



A. Tank Ect. to Grade	154
E. Tank Top to Grade	27
C. Tank Diameter	126
D. Test Level above grade	57 30
E. Depth of water in tank	0
F. Depth for taking sample	80
G. Temp. Probe depth (connector)	29
H. Test level to Tank Ect.	184
I. Groundwater above tank bottom	0
J. Product Pressure per 1" height	031 PS

Test Pressure Formula

184 (H) × 031 (J) − (____ (I) × .036) = 5.7 NET TEST PRESSURE

Sec. 5/23. 2

Dry As A Bone Inc.
69 Capitolian Blvd.
Rockville Centre
New York 11570

NEWSDAY FAC ID 4-0094
235 PINELAWN
MELVILLE
TANK TESTER VER 2.01
FUEL TYPE: SYSTEM TEST TANK#6 #2 OIL
CAPACITY TANK 1: 25133 GALLONS
TEMPERATURE COEFFICIENT: 457 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

05/15/92 TEST TIME FROM 16:43 TO 17:49
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: +0.060 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.075 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.014 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.002 GPH
(-0.012 TO -0.016 GPH)

TESTER .....

CUSTOMER .....

NEWSDAY FAC ID 4-0094
235 PINELAWN
MELVILLE
DATE: 05/15/92 TIME: 16:03
FUEL TYPE: SYSTEM TEST TANK#6 #2 OIL
CAPACITY TANK 1: 25133 GALLONS
TEST CRITERIA: +0.00 GPH TO +0.00 GPH
TEMPERATURE COEFFICIENT: 457 ppm/deg F
RELATIVE FUEL TEMPERATURE 68.03 deg F
VOLUME CHANGE PER DEG F: 11.49 GALLONS

TANK TESTER VER 2.01

	TANK 1 CAPACITY CHANGE GALLONS				TANK 2 CAPACITY CHANGE GALLONS			
TIME	VOLUME	TEMP.	NET	RATE GPH	VOLUME	TEMP.	NET	RATE GPH
16:03	+0.0000	+0.0000	+0.0000	+0.000				
16:04	+0.0001	+0.0000	+0.0001	+0.009				
16:05	+0.0004	+0.0001	+0.0003	+0.023				
16:05	+0.0001	+0.0001	+0.0000	+0.017				
16:06	+0.0001	+0.0001	-0.0000	+0.013				
16:06	+0.0001	+0.0003	-0.0002	+0.007				
16:07	+0.0001	+0.0003	-0.0002	+0.002				
16:07	+0.0002	+0.0002	-0.0000	-0.001				
16:08	+0.0001	+0.0003	-0.0002	-0.003				
16:08	+0.0001	+0.0003	-0.0002	-0.005				
16:09	+0.0001	+0.0002	-0.0001	-0.007				
16:10	+0.0001	+0.0003	-0.0002	-0.008				
16:10	+0.0002	+0.0003	-0.0001	-0.009				
16:11	+0.0002	+0.0003	-0.0002	-0.010				
16:11	+0.0003	+0.0004	-0.0001	-0.011				
16:12	+0.0002	+0.0004	-0.0002	-0.011				
16:12	+0.0002	+0.0004	-0.0002	-0.012				
16:13	+0.0002	+0.0004	-0.0002	-0.012				
16:13	+0.0002	+0.0004	-0.0002	-0.013				
16:14	+0.0003	+0.0004	-0.0001	-0.013				
16:15	+0.0001	+0.0004	-0.0002	-0.014				
16:15	+0.0001	+0.0004	-0.0002	-0.014				
16:16	+0.0002	+0.0004	-0.0002	-0.014				
16:16	+0.0003	+0.0004	-0.0001	-0.015				
16:17	+0.0003	+0.0004	-0.0000	-0.015				
16:17	+0.0002	+0.0004	-0.0002	-0.015				
16:18	+0.0003	+0.0004	-0.0001	-0.015				
16:19	+0.0002	+0.0004	-0.0001	-0.015				
16:19	+0.0002	+0.0004	-0.0002	-0.015				
16:20	+0.0002	+0.0004	-0.0002	-0.015				
16:20	+0.0002	+0.0004	-0.0002	-0.015				
16:21	+0.0000	+0.0000	+0.0000	+0.000				
16:21	+0.0002	+0.0004	-0.0001	-0.014				
16:22	+0.0003	+0.0004	-0.0001	-0.013				
16:22	+0.0004	+0.0004	-0.0000	-0.010				
16:23	+0.0005	+0.0004	+0.0001	-0.005				
16:24	+0.0001	+0.0004	-0.0003	-0.008				
16:24	+0.0003	+0.0004	-0.0002	-0.009				
16:25	+0.0003	+0.0004	-0.0001	-0.010				
16:25	+0.0003	+0.0004	-0.0001	-0.011				
16:26	+0.0002	+0.0004	-0.0002	-0.012				

16:26	+0.0005	+0.0004	+0.0001	-0.011
16:27	+0.0003	+0.0004	-0.0001	-0.011
16:28	+0.0004	+0.0004	-0.0001	-0.010
16:28	+0.0004	+0.0004	-0.0000	-0.010
16:29	+0.0003	+0.0004	-0.0001	-0.010
16:29	+0.0003	+0.0004	-0.0001	-0.010
16:30	+0.0005	+0.0004	+0.0001	-0.009
16:30	+0.0005	+0.0004	+0.0000	-0.009
16:31	+0.0004	+0.0004	-0.0001	-0.008
16:31	+0.0004	+0.0004	-0.0001	-0.008
16:32	+0.0004	+0.0004	-0.0000	-0.008
16:33	+0.0004	+0.0004	+0.0000	-0.008
16:33	+0.0004	+0.0004	-0.0000	-0.007
16:34	+0.0005	+0.0004	+0.0000	-0.007
16:34	+0.0004	+0.0004	-0.0000	-0.007
16:35	+0.0005	+0.0004	+0.0000	-0.007
16:35	+0.0005	+0.0004	+0.0000	-0.006
16:36	+0.0005	+0.0004	+0.0000	-0.006
16:36	+0.0005	+0.0004	+0.0001	-0.006
16:37	+0.0005	+0.0004	+0.0000	-0.005
16:38	+0.0006	+0.0004	+0.0002	-0.005
16:38	+0.0000	+0.0000	+0.0000	+0.000
16:39	+0.0005	+0.0004	+0.0001	+0.007
16:39	+0.0007	+0.0004	+0.0002	+0.017
16:40	+0.0005	+0.0004	+0.0001	+0.014
16:40	+0.0005	+0.0004	+0.0000	+0.012
16:41	+0.0005	+0.0004	+0.0000	+0.010
16:42	+0.0004	+0.0004	-0.0001	+0.007
16:42	+0.0005	+0.0004	+0.0000	+0.006
16:43	+0.0000	+0.0000	+0.0000	+0.000*
16:43	+0.0005	+0.0004	+0.0001	+0.007
16:44	+0.0005	+0.0004	+0.0001	+0.007
16:44	+0.0005	+0.0004	+0.0000	+0.007
16:45	+0.0005	+0.0004	+0.0000	+0.006
16:45	+0.0005	+0.0005	+0.0001	+0.006
16:46	+0.0005	+0.0004	+0.0000	+0.006
16:47	+0.0005	+0.0004	+0.0000	+0.006
16:47	+0.0005	+0.0005	+0.0001	+0.006
16:48	+0.0005	+0.0005	+0.0000	+0.006
16:48	+0.0005	+0.0005	+0.0001	+0.006
16:49	+0.0005	+0.0005	+0.0000	+0.006
16:49	+0.0005	+0.0004	+0.0001	+0.006
16:50	+0.0006	+0.0004	+0.0002	+0.006
16:50	+0.0006	+0.0004	+0.0001	+0.007
16:51	+0.0007	+0.0005	+0.0002	+0.007
16:52	+0.0006	+0.0005	+0.0001	+0.008
16:52	+0.0006	+0.0005	+0.0001	+0.008
16:53	+0.0006	+0.0004	+0.0001	+0.009
16:53	+0.0005	+0.0005	+0.0001	+0.009
16:54	+0.0006	+0.0005	+0.0001	+0.009
16:54	+0.0006	+0.0005	+0.0002	+0.010
16:55	+0.0006	+0.0005	+0.0002	+0.010
16:56	+0.0006	+0.0005	+0.0001	+0.010
16:56	+0.0005	+0.0005	+0.0001	+0.010
16:57	+0.0006	+0.0005	+0.0002	+0.011
16:57	+0.0006	+0.0005	+0.0001	+0.011
16:58	+0.0007	+0.0005	+0.0003	+0.011
16:58	+0.0006	+0.0005	+0.0001	+0.011
16:59	+0.0006	+0.0005	+0.0002	+0.011
16:59	+0.0006	+0.0005	+0.0001	+0.012

17:00	+0.0006	+0.0005	+0.0002	+0.012
17:01	+0.0006	+0.0005	+0.0001	+0.012
17:01	+0.0006	+0.0005	+0.0002	+0.012
17:02	+0.0006	+0.0005	+0.0002	+0.012
17:02	+0.0007	+0.0005	+0.0002	+0.013
17:03	+0.0006	+0.0005	+0.0001	+0.013
17:03	+0.0006	+0.0005	+0.0001	+0.013
17:04	+0.0005	+0.0005	+0.0000	+0.013
17:04	+0.0006	+0.0021	-0.0015	+0.012
17:05	+0.0006	+0.0005	+0.0002	+0.012
17:06	+0.0006	+0.0005	+0.0001	+0.011
17:06	+0.0006	+0.0005	+0.0001	+0.011
17:07	+0.0006	+0.0021	-0.0015	+0.010
17:07	+0.0006	+0.0005	+0.0002	+0.010
17:08	+0.0006	+0.0005	+0.0001	+0.009
17:08	+0.0006	+0.0005	+0.0001	+0.008
17:09	+0.0006	+0.0005	+0.0001	+0.008
17:10	+0.0006	+0.0005	+0.0001	+0.008
17:10	+0.0006	+0.0005	+0.0001	+0.007
17:11	+0.0006	+0.0005	+0.0002	+0.007
17:11	+0.0006	+0.0005	+0.0001	+0.007
17:12	+0.0005	+0.0005	+0.0000	+0.006
17:12	+0.0005	+0.0005	+0.0000	+0.006
17:13	+0.0005	+0.0005	+0.0000	+0.006
17:13	+0.0005	+0.0005	+0.0000	+0.006
17:14	+0.0006	+0.0005	+0.0001	+0.006
17:15	+0.0006	+0.0005	+0.0001	+0.006
17:15	+0.0005	+0.0005	+0.0000	+0.006
17:16	+0.0005	+0.0005	+0.0001	+0.005

VOLUME RATE OF CHANGE 0.005 GPH
95 % CONFIDENCE INTERVAL: +/-0.001 GPH
RELATIVE FUEL TEMPERATURE: 68.03 deg F

17:16	+0.0005	+0.0005	+0.0000	+0.005
17:17	+0.0005	+0.0005	+0.0000	+0.005
17:17	+0.0005	+0.0005	+0.0000	+0.005
17:18	+0.0005	+0.0005	-0.0000	+0.005
17:18	+0.0005	+0.0005	+0.0000	+0.005
17:19	+0.0005	+0.0005	+0.0000	+0.005
17:20	+0.0005	+0.0021	-0.0016	+0.005
17:20	+0.0005	+0.0005	+0.0000	+0.004
17:21	+0.0004	+0.0005	-0.0000	+0.004
17:21	+0.0005	+0.0005	+0.0000	+0.004
17:22	+0.0004	+0.0005	-0.0000	+0.004
17:22	+0.0005	+0.0005	+0.0000	+0.003
17:23	+0.0005	+0.0005	+0.0000	+0.003
17:24	+0.0004	+0.0005	-0.0001	+0.003
17:24	+0.0005	+0.0021	-0.0016	+0.003
17:25	+0.0005	+0.0005	+0.0001	+0.002
17:25	+0.0004	+0.0005	-0.0001	+0.002
17:26	+0.0005	+0.0005	-0.0000	+0.002
17:26	+0.0005	+0.0005	-0.0000	+0.001
17:27	+0.0004	+0.0005	-0.0000	+0.001
17:27	+0.0005	+0.0005	+0.0000	+0.001
17:28	+0.0004	+0.0005	-0.0001	+0.001
17:29	+0.0005	+0.0005	-0.0000	+0.000
17:29	+0.0005	+0.0005	+0.0000	+0.000
17:30	+0.0005	+0.0005	-0.0000	+0.000
17:30	+0.0004	+0.0005	-0.0001	-0.000
17:31	+0.0005	+0.0021	-0.0016	-0.000

```
17:31   +0.0005  +0.0021 -0.0016 -0.001
17:32   +0.0004  +0.0021 -0.0017 -0.001
17:32   +0.0003  +0.0005 -0.0001 -0.002
VOLUME RATE OF CHANGE          -0.002 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.002 GPH
RELATIVE FUEL TEMPERATURE: 68.04 deg F

17:33   +0.0006  +0.0005 +0.0001 -0.002
17:34   +0.0005  +0.0005 -0.0000 -0.003
17:34   +0.0004  +0.0005 -0.0001 -0.003
17:35   +0.0004  +0.0021 -0.0016 -0.004
17:35   +0.0004  +0.0005 -0.0001 -0.004
17:36   +0.0008  +0.0005 +0.0004 -0.005
17:36   +0.0003  +0.0005 -0.0002 -0.005
17:37   +0.0004  +0.0021 -0.0017 -0.005
17:38   +0.0003  +0.0005 -0.0001 -0.006
17:38   +0.0003  +0.0005 -0.0002 -0.006
17:39   +0.0003  +0.0021 -0.0017 -0.007
17:39   +0.0003  +0.0005 -0.0002 -0.007
17:40   +0.0003  +0.0005 -0.0001 -0.008
17:40   +0.0003  +0.0005 -0.0002 -0.008
17:41   +0.0003  +0.0005 -0.0002 -0.009
17:41   +0.0004  +0.0005 -0.0001 -0.009
17:42   +0.0003  +0.0005 -0.0001 -0.009
17:43   +0.0004  +0.0005 -0.0001 -0.010
17:43   +0.0004  +0.0005 -0.0001 -0.010
17:44   +0.0003  +0.0005 -0.0001 -0.011
17:44   +0.0003  +0.0005 -0.0002 -0.011
17:45   +0.0005  +0.0005 +0.0000 -0.011
17:45   +0.0005  +0.0005 -0.0000 -0.011
17:46   +0.0004  +0.0021 -0.0017 -0.012
17:46   +0.0004  +0.0005 -0.0000 -0.012
17:47   +0.0004  +0.0005 -0.0001 -0.012
17:48   +0.0004  +0.0021 -0.0017 -0.013
17:48   +0.0005  +0.0005 -0.0000 -0.013
17:49   +0.0004  +0.0005 -0.0000 -0.013
17:49   +0.0005  +0.0005 -0.0000 -0.014
VOLUME RATE OF CHANGE          -0.014 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.002 GPH
RELATIVE FUEL TEMPERATURE: 68.04 deg F
```

10:37:21 23 MAR 1995 Tank Registration Inquiry Screen

Facility — Owner

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
400 270.0 2 1.0

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
Reg No 4-0094 File Ref No 4-203

Tanks

No	Location	Volume	Contents	Constr	Offuse	Job No	PO	Date Remov
1	UNDER	OUT	25,000	DIESEL	PLNSTL	86REM			01/01
2	UNDER	OUT	25,000	DIESEL	PLNSTL	86REM			01/01
3	UNDER	OUT	25,000	DIESEL	PLNSTL	86REM			01/01
4	UNDER	OUT	12,000	GASOLINE	PLNSTL	86REM			01/01
5	UNDER	OUT	2,000	OTHER	PLNSTL	88ABD			06/28
6	UNDER	OUT	25,000	#2 FUEL OIL	PLNSTL	97HO			
7	UNDER	OUT	25,000	#2 FUEL OIL	PLNSTL	97HO			

Plans — Tank Test

Job No	Rcvd	Disaprvd	Apprvd	No	1st Test	Result	Retest	Nex
HM86-068	07/28/86			6	05/15/92		05/15/92	12/31
HM86-068R1	04/07/87			6	04/30/92	- .493		
HM86-068R3	10/27/87		10/27/87	7	04/30/92	- .053		12/31
HM87-306	10/14/87	12/03/87		8	02/02/86	- 0.01		12/31

.014

Enter T, L or TT to scroll Tanks, Logs or Tank Test (E = End)

10:37:21 23 MAR 1995 Tank Registration Inquiry Screen

Facility — Owner

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
400 270.0 2 1.0

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
Reg No 4-0094 File Ref No 4-203

Tanks

No	Location	Volume	Contents	Constr	Offuse	Job No	PO	Date Remov
8	UNDER	OUT	4,000	INDUSTRIAL WERP		87REM			01/01
9	ABOVE	IN	275	DIESEL	PLNSTL	EX			
10	ABOVE	IN	8,000	OTHER	PLNSTL	85			
11	ABOVE	IN	8,000	OTHER	PLNSTL	85			
12	ABOVE	IN	8,000	OTHER	PLNSTL	85			
13	ABOVE	IN	100	INDUSTRIAL WOTHER		82			
14	UNDER	OUT	20,000	DIESEL	FRP	90P	HU-052R		

Plans — Tank Test

Job No	Rcvd	Disaprvd	Apprvd	No	1st Test	Result	Retest	Nex
HM86-068	07/28/86			6	05/15/92		05/15/92	12/31
HM86-068R1	04/07/87			6	04/30/92	- .493		
HM86-068R3	10/27/87		10/27/87	7	04/30/92	- .053		12/31
HM87-306	10/14/87	12/03/87		8	02/02/86	- 0.01		12/31

Enter T, L or TT to scroll Tanks, Logs or Tank Test (E = End)

10:37:21 23 MAR 1995 Tank Registration Inquiry Screen

Facility — Owner

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
400 270.0 2 1.0

NEWSDAY INC
235 PINELAWN RD
MELVILLE NY 11747
Reg No 4-0094 File Ref No 4-203

Tanks

No	Location	Volume	Contents	Constr	Offuse	Job No	PO	Date Remov
15	UNDER	OUT	20,000	DIESEL	FRP	90P	HU-052R		
16	UNDER	OUT	20,000	DIESEL	FRP	90P	HU-052R		
17	ABOVE	IN	100	DIESEL	PLNSTL	EX			

```
 18 UNDER OUT    2,500 #2 FUEL OIL DWFRP      92P     HU-052
 19 UNDER OUT    4,000 INDUSTRIAL WDWSTIP-3 92P     HM86-068R3
 20 UNDER OUT   10,000 GASOLINE    FRP       NI      HU-052
 21 ABOVE IN     4,675 DRUM STORAGE           NI      HM88-141
------------------ Plans ------------------------------Tank Test----------
Job No          Rcvd   Disaprvd  Apprvd  | No 1st Test  Result Retest     Next
HM86-068      07/28/86                   | 6  05/15/92        05/15/92  12/31/97
HM86-068R1    04/07/87                   | 6  04/30/92 - .493
HM86-068R3    10/27/87          10/27/87 | 7  04/30/92 - .053            12/31/97
HM87-306      10/14/87  12/03/87         | 8  02/02/86 - 0.01            12/31/89
-------------------------------------------------------------------------------
Enter <Return> = forward, "B"ack or "E"nd


10:37:21 23 MAR 1995      Tank Registration Inquiry Screen
------------Facility-------------------------------------Owner---------------
NEWSDAY INC                                  NEWSDAY INC
235 PINELAWN RD                              235 PINELAWN RD
MELVILLE NY 11747                            MELVILLE NY 11747
400 270.0 2 1.0                              Reg No 4-0094      File Ref No 4-2037
------------------------------------ Tanks ------------------------------------
No  Location  Volume  Contents     Constr   Offuse    Job No     PO Date Removed
22 ABOVE IN    1,380 DRUM STORAGE           96P     HM88-141R1   04/19/91
23 ABOVE IN      200 INDUSTRIAL WPLNSTL     96P     HM88-141R1   04/19/91
24 ABOVE IN      165 INDUSTRIAL WPLNSTL     96P     HM88-141R1   04/19/91
25 ABOVE IN      500 INDUSTRIAL WPLNSTL     96P     HM88-141R1   04/19/91
26 ABOVE IN    2,000 INDUSTRIAL WOTHERPLY   94P     HM89-038
27 ABOVE IN    2,000 INDUSTRIAL WOTHERPLY   94P     HM89-038
28 ABOVE IN      250 INDUSTRIAL WOTHER      94P     HM89-038
------------------ Plans ------------------------------Tank Test----------
Job No          Rcvd   Disaprvd  Apprvd  | No 1st Test  Result Retest     Next
HM86-068      07/28/86                   | 6  05/15/92        05/15/92  12/31/97
HM86-068R1    04/07/87                   | 6  04/30/92 - .493
HM86-068R3    10/27/87          10/27/87 | 7  04/30/92 - .053            12/31/97
HM87-306      10/14/87  12/03/87         | 8  02/02/86 - 0.01            12/31/89
-------------------------------------------------------------------------------
Enter <Return> = forward, "B"ack or "E"nd


10:37:21 23 MAR 1995      Tank Registration Inquiry Screen
------------Facility-------------------------------------Owner---------------
NEWSDAY INC                                  NEWSDAY INC
235 PINELAWN RD                              235 PINELAWN RD
MELVILLE NY 11747                            MELVILLE NY 11747
400 270.0 2 1.0                              Reg No 4-0094      File Ref No 4-2037
------------------------------------ Tanks ------------------------------------
No  Location  Volume  Contents     Constr   Offuse    Job No     PO Date Removed
29 ABOVE IN    2,640 DRUM STORAGE           AP      HM91-442R2
30 ABOVE IN    1,500 CAUSTIC     PLNSTL     AP      HM93-159R2
------------------ Plans ------------------------------Tank Test----------
Job No          Rcvd   Disaprvd  Apprvd  | No 1st Test  Result Retest     Next
HM86-068      07/28/86                   | 6  05/15/92        05/15/92  12/31/97
HM86-068R1    04/07/87                   | 6  04/30/92 - .493
HM86-068R3    10/27/87          10/27/87 | 7  04/30/92 - .053            12/31/97
HM87-306      10/14/87  12/03/87         | 8  02/02/86 - 0.01            12/31/89
-------------------------------------------------------------------------------
Enter <Return> = forward, "B"ack or "E"nd
```

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 9201246

SPILL NAME: NEWSDAY **DEC LEAD:** T/T/F

SPILL DATE: 04/30/1992 **SPILL TIME:** 5:30 pm

CALL RECEIVED DATE: 04/30/1992 **RECEIVED TIME:** 9:01 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Tank Test Failure **SPILL REPORTED BY:** Tank Tester

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

25K FAILED AT -.493, DRY AS A BONE TESTER, SCDH NOTIFIED, TYREE TO DO CLEANUP

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
kerosene	Petroleum	0 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE NY	JOHN TILLATSON 516-454-2020 5458

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
	0	kerosene [#1 fuel oil]	(on-site consumption)		00	0.00	

DEC REMARKS:

TANK ALONE PASSED 5/15/92. SYSTEMS TEST PASSED 5/15/92. FILL BOX REPLACED. LEAKAGE FROM COMPRESSION PIPE. CLEANUP JUST BELOW THE SURFACE MOUNTED FILL CAP, ~ 2YDS OF CONTAMINATED SOIL REMOVED

PIN **T & A** **COST CENTER**

CLASS: B3 **CLOSE DATE:** 05/27/1998 **MEETS STANDARDS:** True

11/20/94 9:50

Tel con John Tillotsen
- spill contained + covered with speedi-dry.
- no drainage affected -
- 3 droms. being loaded.
- told to send Disposal Reciepts.

T/C 3/1/94

T/C John Tillotsen
DRUMS STILL ON SITE
- Disposal expected this Friday. will send receipts

SPILL OCCURRED ON South parking Lot Trucks lot South East side of that lot.

As per
- Spill was contained on ice with aid of socks and speedy dry
Nowhere near any drainage.

93-12349

Anthony,

for Newsday Spill

John Tillotsen

843-5458

235 Pinelawn Rd
Melville

266-0299


3/1/94

TA 1352 AUSTIN ON SITE.

- Met with John Tilotsen. Showed me area where spill had taken place
- Incident had been photographed.
- Photos showed incident occurred in location indicated in sketch
- Photos showed that containment actions (speedydry/socks) had protected drains
- No odor or sheen found in drains
- 3 ~~drums of~~ speedydry/ice on site
- Will dispose of drums and forward receipt

TL 1420 Left site

No further action required at this time.



Newsday

235 Pinelawn Rd., Melville, NY 11747-4250

John Tillotson
Manager of Environmental Services
(516) 843-5458

March 14, 1994

Mr Brian Austin
New York State Department of
Environmental Conservation
Spill Control Section
SUNY - Bldg 40
Stony Brook, New York 11794

RECEIVED
MAR 18 1994
REG 1
OIL SPILLS

Re: Spill Report No: 93-12349
Spill Date: January 21, 1994

Dear Mr Austin:

As requested, I am enclosing a copy of the completed New Jersey Hazardous Waste Manifest (NJA 1854425) used to dispose of waste generated from the diesel fuel spill from one of Newsday's trucks on January 21, 1994. As we had discussed,

Newsday's policy is to respond quickly and thoroughly in the event of any type of accident. If there is any other information required to close out this episode, please contact me as soon as possible. Thank you for your time and cooperation.

Yours truly,

John Tillotson

A Times Mirror
Newspaper

State of New Jersey
Department of Environmental Protection and Energy
Hazardous Waste Regulation Program
Manifest Section
CN 421, Trenton, NJ 08625-0421

Please type or print in block letters. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-94

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NYD052782497 — Manifest Document No. 000110

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
NEWSDAY, INC
235 PINELAWN RD MELVILLE, NY 11747-4250

4. Generator's Phone (516-843-5458 (24 HR: 516-843-2255)

A. State Manifest Document Number: NJA 1854425

B. State Generator's ID-(Gen, Site Address): SAME

5. Transporter 1 Company Name: AUCHTER INDUSTRIAL VAC SER — 6. US EPA ID Number: NJD980772768

C. State Trans. ID-NJDEPE: S6993
Decal No.: 57448

7. Transporter 2 Company Name — 8. US EPA ID Number

D. Transporter's Phone: 201 562-2277

E. State Trans. ID-NJDEPE

Decal No.

9. Designated Facility Name and Site Address
S & W WASTE, INC
105 JACOBUS AVE
S. KEARNY, NJ 07032 — 10. US EPA ID Number: NJD991129105

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (201 344-4004

11. US DOT Description (Including Proper Shipping Name, Hazard Class or Division, ID Number and Packing Group)	HM	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. HAZARDOUS WASTE SOLID, NOS PKG GROUP III NA 3077 DOT CLASS 9	X	XX	6DM	X3900	P	X725
b.						
c.						
d.						

J. Additional Descriptions for Materials Listed Above
a. VIRGIN DIESEL FUEL SPILL CONTAMINATED ABSORBENT T/S
b.
c.
d.

K. Handling Codes for Wastes Listed Above
a. T&Y Stabilization
b.
c.
d.

15. Special Handling Instructions and Additional Information
APPROVAL NO: 002
NJ HAZARD CODE: X725
NY - NJ - 197
DECAL NO:
TRAILER PLATE NO: T181WP NJ
NY=L

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
JOHN TILLOTSON	J T Tillotson	03	04	94

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
BILL MERSIL/PR	Bill Mersil	03	04	94

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

19. Discrepancy Indication Space

RECEIVED PENDING MANIFEST REVIEW & QUALITY CONTROL

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
TOM RUSSELL	Tom Russell	03	04	94

GENERATOR — TRANSPORTER — FACILITY

In case of an emergency or spill immediately call the state the emergency occurred in and the N.J. Dept. of Environmental Protection and Energy. (609) 292-7172

EPA Form 8700-22 (Rev. 9/88) Previous editions are obsolete.

SIGNATURE AND INFORMATION *MUST* BE LEGIBLE ON ALL COPIES

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 9312349

SPILL NAME: NEWSDAY **DEC LEAD:** BPAUSTIN

SPILL DATE: 01/21/1994 **SPILL TIME:** 2:50 am

CALL RECEIVED DATE: 01/21/1994 **RECEIVED TIME:** 3:08 am

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial Vehicle **WATERBODY:**

CALLER REMARKS:
FUEL LINE ON TRUCK BROKE, SPILL DIKED, WILL CLEANUP TODAY,

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	50 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	MELVILLE NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN"
03/28/94: AUSTIN ON SITE, CLEANUP COMPLETE, DISPOSAL RECPTS RECEIVED.

PIN **T & A** **COST CENTER**

CLASS: C3 **CLOSE DATE:** 03/28/1994 **MEETS STANDARDS:** True

Created On: 01/21/1994

Date Printed: 8/7/2018 Last Updated: 08/07/2018

Newsday

235 Pinelawn Road, Melville, NY 11747-4250

Administrative Services

November 21, 1997

RECEIVED

NOV 24 1997

REG 1 - OIL SPILLS

Robert DeCandia
Environmental Engineer 1
NYSDEC - Region 1
SUNY Building 40
Stony Brook, New York 11790-2356

SUBJECT: NYSDEC Spill #9706042

Dear Mr. DeCandia:

As per your request, enclosed are copies of:

1) Newsday Material Release Log
2) Manifest for spill material removal.

Please contact me for any questions and/or comments.

Sincerely,

David Krueger
Engineering Services
(516) 843-5437
(516) 843-3444 fax

CC: Tim McGarry

Attachments: (1) 1) Newsday Hazardous Material Release Log, 8/18/97
2) Manifest for spill material removal, NJA2777001, 9/24/97

file: DNK(97spilll.DOC)

SUBJECT: SECTION 6

HAZARDOUS MATERIAL RELEASE LOG

PAGE OF

EFFECTIVE DATE:

1) ADDRESS OR LOCATION OF LEAK:

NAME: Newsday
ADDRESS: 235 Pinelawn Rd / Melville, NY 11747
TELEPHONE: (516) 843-5437 attn David Krueger
-DIAGRAM ON BACK-

2) DATE OF RELEASE DISCOVERY: 8/18/97

3) TIME OF RELEASE DISCOVERY: 12:30

4) DURATION OF RELEASE: approximately 5 minutes

5) MATERIAL RELEASED: SOLID (LIQUID) GAS
DESCRIPTION: Hydraulic Fluid Oil

HAZARD CLASS: Flammable

PRECAUTIONS: used absorbant clay to contain & clean. spill

6) QUANTITY OF RELEASE: GALLONS. approximately 25 gallons
POUNDS.
FLOOR AREA.

7) CAUSE OF RELEASE: Hydraulic line Ruptured caused by abrasion

8) IMMEDIATE INJURIES: none

9) CORRECTIVE ACTION: Absorbant clay used to clean up spill. Ruptured hydraulic line was Replaced & secured. to prevent abrasion

10) AGENCY NOTIFIED: AGENCY: NYSDEC - Albany
CONTACT/TITLE: Patric O'conner - Environmental Engineer.
PHONE NO.: (800) 457-7362
TIME/DATE: 8/18/97 15:40
DEC spill # 9706042

11) REPORTER: David Krueger
TITLE: Engineer
SIGNATURE:
DATE: 8/19/97

→ 8/18/97 16:30, Nick Scampoco called from NYSDEC - stonybrook. Dave K Reiterated above information

→ 9/1-9/10/97, Robert DeCandia, Environmental Engineer I - NYSDEC - Stony Brook Contacted Dave K for copy of waste manifest. 444-0337

State of New Jersey
Department of Environmental Protection
Hazardous Waste Regulation Program
Manifest Section
CN 421, Trenton, NJ 08625-0421

Please type or print in block letters. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039. Expires 9-30-97

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NYD052782497 | Manifest Document No. 000031 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
NEWSDAY, INC.
235 PINELAWN ROAD / MELVILLE, NEW YORK 11747

4. Generator's Phone (516) 843-5437 (516) 843-2255 24hrs.

A. State Manifest Document Number: NJA 2777001

B. State Generator's ID (Gen. Site Address): SAME

5. Transporter 1 Company Name: AUCHTER INDUSTRIAL VAC SERVICE

6. US EPA ID Number: NJD080772768

C. State Trans. ID-NJDEP: 869937 Decal No.: X83227

7. Transporter 2 Company Name

8. US EPA ID Number

D. Transporter's Phone (908) 862-2277

E. State Trans. ID-NJDEP / Decal No.

9. Designated Facility Name and Site Address
S&W WASTE, INC.
105 JACOBUS AVENUE
SOUTH KEARNY, NJ 07032

10. US EPA ID Number: NJD991291105

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (201) 344-4004

11. US DOT Description (Including Proper Shipping Name, Hazard Class or Division, ID Number and Packing Group)	HM	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. X HAZARDOUS WASTE SOLID, NOS 9 NA3077 PKG GRP III	X	xx3	DM	01000	P	X 910
b. 97-06042						
c.						
d.						

J. Additional Descriptions for Materials Listed Above
a. S/T 1-3% OIL, 27-99% SPEEDI-DRY/SOLIDS
c. S&W APP.010748 (A) 002

K. Handling Codes for Wastes Listed Above
a. T04 Stabilization
c.
b.
d.

15. Special Handling Instructions and Additional Information
NJSA197

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Dave Krugger | Signature | Month Day Year: 09 24 97

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Roy Klebowicz | Signature | Month Day Year: 09 24 97

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space
Sec11a c & Non-regulated Material
RECEIVED PENDING MANIFEST REVIEW & QUALITY CONTROL

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Michael Szpyhulsky | Signature | Month Day Year: 09 24 97

NJA2777001

GENERATOR

In case of an emergency or spill immediately call the state the emergency occurred in and the N.J. Dept. of Environmental Protection and Energy: (609) 292-7172

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 9706042

SPILL NAME: NEWSDAY NEWSPAPER **DEC LEAD:** RDDECAND

SPILL DATE: 08/18/1997 **SPILL TIME:** 12:30 pm

CALL RECEIVED DATE: 08/18/1997 **RECEIVED TIME:** 3:38 pm

SPILL LOCATION

PLACE: NEWSDAY NEWSPAPER **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: DAVE KRUEGER **CONTACT PHONE:** (516) 436-1381

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Responsible Party

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

A HYDRAULIC LINE FROM A TRASH COMPACTOR RUPTURED FROM RUBBING AGAINST A SHARP OBJECT
SPILL HAS BEEN CONTAINED WITH SPEEDY DRY

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	20 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY NEWSPAPER	235 PINELAWN ROAD MELVILLE NY 11747-	DAVE KRUEGER (516) 436-1381

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DECANDIA"
20-35 GALS SPILLED ONTO PAVEMENT, NO DRAINAGE BUT PADS DEPLOYED AS PRECAUTION,
SPILL OCCURRED WHEN 1" HOSE FAILED DUE TO CONTINUAL CONTACT WITH COMPACTOR BODY.
SPILL ONTO PAVEMENT ONLY, 10 BAGS USED AND WILL BE PICKED UP TOMORROW. NEWSDAY THEN
WILL PUT WASTE INTO DRUMS FOR PROPER DISPOSAL

CLEANUP BY NEWSDAY, DISPOSAL RECVD

PIN **T & A** **COST CENTER**

CLASS: C3 **CLOSE DATE:** 12/01/1997 **MEETS STANDARDS:** True

Created On: 08/18/1997

Date Printed: 8/7/2018 Last Updated: 08/07/2018

11/20 1530 : Spoke to Tom McGlennon (FTN)

- level in tank is "going down very slowly"
- may be vent or some other problem
  + not the tank itself
- will monitor level overnight
- will disconnect
- tank-only test planned for Tue 11/25

CERTIFIED #P 061 496 846

97-09711
+1+L

New York State Department of Environmental Conservation
Building 40 - SUNY, Stony Brook, New York 11790-2356

TEL # (516) 444-0320
FAX # (516) 444-0373

John P. Cahill
Commissioner

December 8, 1997

CERTIFIED LETTER - RETURN RECEIPT REQUESTED

Mr. Dave Krueger
Newsday
235 Pinelawn Road
Melville, New York 11747

Re: Spill #97-09711, Newsday
235 Pinelawn Road, Melville, N.Y.

Dear Mr. Krueger:

This office has been informed by Fenley & Nicol that one (1) 25,000 gallon #2 fuel oil tank failed a Horner Ezy Check systems test on November 20, 1997. In accordance with Article 12 of the New York State Navigation Law, I must determine if there has been any harm to the groundwaters of the State. In order for me to make this determination, you have three options:

1. Prove that the tank is not leaking by removing all of the piping from the tank and separately testing the tank alone using a state and county approved test method. If the tank fails this test you must notify this office within two hours of the failure. The tank must then be emptied immediately and you will have to proceed as in 2 or 3 below. If the tank passes this test, it may then be abandoned and the piping further investigated or the piping can be repaired, reattached to the tank, and the system retested. If at any time contaminated soil is found, this office must be notified immediately and the soil must be removed and stockpiled properly on site until proper disposal. The excavation cannot be backfilled until authorization to do so is given by the NYSDEC. Be advised that the soil can only be removed from site by a hauler possessing a Part 364 Permit.

2. Excavate and remove the tank in the presence of a representative from this office so that an inspection of the tank and the surrounding soil can be made. The removal must be scheduled with this department at least 48 hours prior to the date of removal and is on a first come first served availability basis. If evidence of contamination is found, you will be required by this office to remediate the said contamination.

TTF - file 97-09711
Melville

2/3

TL

Dave Krueger

Newsday

843 5437

Petro Tite
tank passed
suction line problem

9709711

3. Abandon the tank in-place in accordance with county procedures, and install several four (4) inch diameter PVC site wells extending at least ten (10) feet into the groundwater with a minimum screen length of twenty (20) feet, and a recommended slot size of .020 inches. The location, number of wells and monitoring schedule will be determined by a representative from this office. These wells must be checked by you or your contractor, and the monitoring data submitted to this office periodically. If floating/dissolved product appears, recovery must begin immediately.

Please be advised that the above work must be done by a county fire marshall and/or health department approved tester and/or contractor. The in-place abandonment of underground tanks may be prohibited in some areas. Check with the appropriate local or county authority regarding their laws governing the storage of petroleum products. All documentation, including all test results (failing and passing) and descriptions of repairs and soil condition (in regard to contamination), must be forwarded to this office.

Please call me at (516) 444-0333 to advise me of how you will proceed to resolve this problem. If no response is received from you by December 19, 1997 this office will have no choice but to proceed with further investigation of your site and will then seek reimbursement from you for all costs associated with the investigation/remediation in accordance with Article 12 of the New York State Navigation Law.

Should you have any questions or comments, please contact me at the above telephone number.

Sincerely,

Mary M. Henning

Mary M. Henning
Engineering Aide

MMH:ap
cc: J. Maloney, SCDHS
A. Leung, NYSDEC

TF 97-09711

COUNTY OF SUFFOLK

ROBERT J. GAFFNEY
SUFFOLK COUNTY EXECUTIVE

DEPARTMENT OF HEALTH SERVICES

CLARE B. BRADLEY, M.D., M.P.H.
ACTING COMMISSIONER

RECEIVED
DEC 15 1997
REG 1 - OIL SPILLS

Certified Mail - RRR

December 11, 1997

Mr. Dave Krueger
Newsday
235 Pinelawn Road
Melville, NY 11747

Re: Tank Failure
Newsday, 235 Pinelawn Rd, Meville NY
Spill #97-09711, SCDHS Fac.ID#4-0094

Dear Sir/Madam:

This office has been informed by Fenley & Nicol. that the following tank system(s) failed the tank system tightness test on November 20, 1997:

Tank#1 - 25,000 gallon #2 fuel oil tank

Section 1210F of Article 12 of the Suffolk County Sanitary Code requires that any underground storage facility, or part thereof, which is found to be leaking, must immediately be emptied of all contents and removed from service. It is unlawful to permit a leaking underground storage facility or part thereof to remain in service or to continue to retain its toxic or hazardous contents after it has been found to be leaking.

Your storage tank system has failed the initial tank system tightness test. You have **ten days** from receipt of this letter to make the necessary repairs to any piping associated with the particular line and retest the line and the piping as a system to show that the underground storage facility is tight. **Repairs to metal tank(s) are prohibited by code.**

If all associated piping has been disconnected from the tank, and a subsequent tank tightness test proves that the tank is leaking, you must immediately remove the contents of the tank.

The tank must then be removed from service per the enclosed guidance document "Removal of Underground Storage Facilities from Service" within **ninety days** from the date of this notice.

Prior to removing any underground storage facility from service, all remaining liquid and residue must be cleaned and hauled away for proper disposal by a New York State licensed industrial hauler. A list of such haulers may be obtained from the New York State Department of Environmental Conservation (NYSDEC) at (516)444-0230.

Tank removal must be coordinated with this office. You must notify this office within **ten days** of receipt of this letter advising of your intention to remove the tank and then again at least 48 hours prior to the removal, as a department representative **must be present** during the procedure. Please contact John Gladysz at 854-2524 for this purpose.

Failure to comply with the above requirements constitutes a violation of Article 12 and may subject you to fines and penalties of up to $500 per day per violation for each day the violation(s) exists.

Very truly yours,

Kenneth A Clunie

Kenneth A. Clunie
Assistant Public Health Engineer
Bureau of Environmental Engineering

KAC:ar
Enc. - cc: Mary M. Henning, Engineering Aide, NYSDEC

Newsday

235 Pinelawn Road, Melville, NY 11747-4250

December 16, 1997

CERTIFIED MAIL RRR - Z 341 086 252

Mary Henning
Engineering Aide
NYSDEC – Region 1
Building 40 – SUNY
Stony Brook, New York 11790

RECEIVED
DEC 22 1997
REG 1 - OIL SPILLS

SUBJECT: **Spill #97-09711 Tank System Tightness Testing**

Dear Mrs. Henning:

Newsday's UST testing contractor, Fenley & Nicol Environmental, was unable to stabilize their testing equipment in our 25,000 gallon UST. The testing equipment, Horner EZY-Check II, requires an acceptable Confidence Interval Number (standard of deviation) obtained from the testing data for the results to be considered valid. During testing, the tank temperature probe would fluctuate significantly causing an out of specification CIN. Since the CIN was out of specification, Fenley & Nicol was unable to perform a valid system tank tightness test.

Fenley & Nicol attempted testing the tank on several occasions. The following actions have been taken to eliminate known interference with the testing equipment:

1. Product Stabilization -- the product has been left undisturbed in the 100% full tank for over 4 weeks;
2. FM Interference -- all above-ground testing cable, data gathering panels and associated hardware have been shielded with foil to resist FM interference;
3. Stray Current – the testing equipment was grounded to eliminate effects of stray current;
4. Ground Vibration – testing was scheduled on a Saturday to eliminate vehicles from driving on or near the tank.

Fenley & Nicol has attempted three system tests with their EZY-Check II equipment. As the next step, a new UST testing contractor, Dry As A Bone Inc., is scheduled to test on Saturday, January 3, 1998. Dry As A Bone will test the tank system with their Horner EZY-Check II testing equipment to eliminate the possibility of equipment malfunction.

Currently, 1) there is no evidence of tank leakage or ground contamination in the areas associated with the tank/piping and 2) the volume of the tank's product has maintained its level in the fill port since monitoring commenced two weeks ago.

Newsday will contact you after the January 3rd testing. Please contact me for any questions and/or comments.

Sincerely,

David Krueger
Engineering Services
(516) 843-5437
(516) 843-3444 fax

CC: Tim McGarry
John Tillotson
Ken Clunie – SCDHS (Certified Mail RRR - Z 341 086 253)

Attachments: (0)
file: DNK(97ust673.DOC)

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☐ Field Notes ☑ Phone Conversation ☐ Meeting Notes **Spill No.**_____

Location	**Representatives on site**	time in	time out
Name	DEC		
Address			
Town			
Phone			
Weather / Temperature / General conditions	PRP		
humidity / Cold / Sunny			
Dry / Fair / Partly Cloudy			
Humid / Warm / Cloudy			
Very humid / Hot / Rain / Snow			
°C___°F___ / Other_____			

Date	Time	Entries
1/7/18	09:45	Phone Conv. w/ Amy de A Bone - They performed E24 chels II as well and have encountered the same problem - We believe it's Radio inference as temp readings were just fluctuating too much. We would like to get approval for Petro Tite II test. TC
	10:00	Lenny Spoke to Russ in Albany, He said that is an acceptable alternative but if it still fails (as Petro Tite II is still susceptible to Radio interference but not as much as the ~~fate~~ current tests) should then move toward a non-volumetric type test. TC

Revised 10-22-97

☐ Continued Page ____ Of ____

97-09711

RECEIVED
JAN 09 1998
REG 1 - OIL SPILLS

DRY AS A BONE, INC.
INSTALLATION, REMOVALS & UPGRADING
D.A.A.B .INC.

933 Northern Blvd.	153-44 So. Conduit Ave.	69 Capitolian Blvd
Clarks Summit, PA 18411	Jamaica, NY 11434	Rockville Centre, NY 11570
PH: (717)586-3105	PH: (718)949-3849	PH: (516)678-5115
FAX: (717)586-3118	FAX:(718)527-6688	FAX:(516)678-9140

Suffolk Co. Dept. of Health
15 Horseblock Rd.
Farmingville, NY. 11738

January 7,1998

Attn: Ken Clunie

Subject: 25,000 gallon #2 oil tank; #002

Ken,

As per our conversation enclosed is the tank tightness test performed at; Newsday, 235 Pine Lawn Rd., Melville, NY.11747.

As you can see be the enclosed data there is no loss of product, however, the temperature is very erratic. These erratic temperature readings could possibly be caused by radio interference, disrupting the Horner II temperature probe.

According to Dave Krueger at Newsday the stick readings do not show any loss of product. Therefore, it is the writers opinion that this tank is tight. I also agree with you to confirm that this tank is tight, therefore a Petro-tite Systems test should be performed in the near future.

Any further questions please do not hesitate to call our office.

Sincerely,

Jerry Curtin

cc: Mary Henning
Dave Krueger

DRY AS A BONE, INC.
INSTALLATION, REMOVALS & UPGRADING
D.A.A.B .INC.

933 Northern Bvld.	**153-44 So. Conduit Ave.**	**69 Capitolian Blvd**
Clarks Summit, PA 18411	**Jamaica, NY 11434**	**Rockville Centre, NY 11570**
PH: (717)586-3105	**PH: (718)949-3849**	**PH: (516)678-5115**
FAX: (717)586-3118	**FAX:(718)527-6688**	**FAX:(516)678-9140**

TANK TEST CERTIFICATE

TANK OWNER: Newsday

PURCHASE ORDER# _____

CONTACT ADDRESS: _____

PHONE NUMBER: _____

SITE ADDRESS: 235 Pine Lawn Rd. Melville, NY. 11747

TEST METHOD: Horner Ezy Chek II

TEST DATE: January 3,1997

TANK	CAPACITY	PRODUCT	TANK RESULT
#001	25,000 gallon	#2 fuel oil	-0.087gph

REMARKS: Passed

APPROVAL: T.J. O'Connor #254

SIGNATURE: TJOC

HORNER EZY CHEK II

OWNER OR DEALER Newsday

ADDRESS (NO. & STREET) 235 Pinelawn Rd

CITY AND STATE Melville, NY

TANK INFORMATION TANK 002

CAPACITY (NOMINAL) 25000

CAPACITY (CHART) 25400

NUMBER OF GALLONS ADDED 25


TOTAL CAPACITY 25368 (-57, ALS = 1.5 IN. WATER)

CONTENTS (PRODUCT) ~~Water~~ Diesel CALIBRATION NUMBER 385

MONITOR MODE RESULTS

TIME	RESULT	CI
10:56	-.014	+/-.001
11:13	-.040	+/-.002
11:31	-.071	+/-.001
11:48	+.141	+/-.017
12:06	+.043	+/-.026
12:23	-.070	+/-.007
12:26	Test Started	

TANK LAYOUT



COEFFICIENT CALCULATIONS

MEASURED API GRAVITY 33

PRODUCT TEMPERATURE 48

API SPECIFIC GRAVITY @ 60 F, 339 (FROM TABLE A)

COEFFICIENT OF EXPANSION 456 (FROM TABLE B)

HORNER EZY CHEK II TEST LOG

SITE ARRIVAL TIME 600 am, pm

CONTACT PERSON Dave

TIME OF PRODUCT DELIVERY _____ am, pm

AMOUNT OF PRODUCT TO TOP OFF _____

TIME OF EQUIPMENT SET UP 615 am, pm

CHANGES TO TANK SYSTEM None

ESTIMATED AMOUNT OF PRODUCT TO MAINTAIN TEST LEVEL 25 gal

TIME TEST LEVEL WAS MAINTAINED 7:35 am, pm

TIME OF .4 PSI DROP 7:35 am, pm


TIME OF CALIBRATION 10:35 am, pm

TIME OF TEST COMPLETION 1:33 am, pm

DEPTH OF WATER TABLE 0

REMARKS _____

OPERATOR TJ O'CONNOR



A. Tank Ect. to Grade
B. Tank Top to Grade
C. Tank Diameter
D. Test Level above grade
E. Depth of water in tank
F. Depth for taking sample
G. Temp. Probe depth (connector)
H. Test level to Tank Ect.
I. Groundwater above tank bottom
J. Product Pressure per 1" height

Test Pressure Formula
183 × .031 (____ × .036) = 5

NEWSDAY
235 PINELAWN RD.
MELVILLE NY
TANK TESTER VER 2.01
FUEL TYPE: TANK #002 FUEL OIL SYS TEST
CAPACITY TANK 1: 25368 GALLONS
TEMPERATURE COEFFICIENT: 458 ppm/deg F
TEST CRITERIA: +0.000 GPH TO +0.000 GPH

01/03/97 TEST TIME FROM 12:26 TO 13:33
DATA ANALYSIS INDICATES:

A GROSS VOLUME CHANGE OF: -0.000 GALLONS
A VOLUME CHANGE DUE TO TEMPERATURE OF: +0.073 GALLONS

A LIQUID VOLUME RATE OF CHANGE OF: -0.087 GPH
WITH A 95 % CONFIDENCE INTERVAL OF: +/-0.016 GPH
(-0.070 TO -0.103 GPH)

TESTER.....

CUSTOMER.....

NEWSDAY
235 PINELAWN RD.
MELVILLE NY
DATE: 01/03/97 TIME: 10:39
FUEL TYPE: TANK #002 FUEL OIL SYS TEST
CAPACITY TANK 1: 25368 GALLONS
TEST CRITERIA: +0.00 GPH TO +0.00 GPH
TEMPERATURE COEFFICIENT: 458 ppm/deg F
RELATIVE FUEL TEMPERATURE 47.89 deg F
VOLUME CHANGE PER DEG F: 11.62 GALLONS

TANK TESTER VER 2.01

	TANK 1 CAPACITY CHANGE GALLONS				TANK 2 CAPACITY CHANGE GALLONS			
TIME	VOLUME	TEMP.	NET	RATE GPH	VOLUME	TEMP.	NET	RATE GPH
10:39	+0.0000	+0.0000	+0.0000	+0.000				
10:40	-0.0001	-0.0004	+0.0003	+0.035				
10:40	-0.0001	+0.0000	-0.0001	+0.012				
10:41	-0.0002	+0.0002	-0.0003	-0.005				
10:42	-0.0000	-0.0001	+0.0001	-0.004				
10:42	-0.0001	-0.0000	-0.0001	-0.004				
10:43	-0.0001	-0.0001	+0.0001	-0.003				
10:43	-0.0001	+0.0001	-0.0002	-0.004				
10:44	-0.0001	+0.0001	-0.0002	-0.006				
10:44	-0.0001	+0.0001	-0.0002	-0.008				
10:45	+0.0000	+0.0001	-0.0001	-0.009				
10:45	-0.0001	+0.0001	-0.0001	-0.009				
10:46	-0.0001	+0.0002	-0.0002	-0.010				
10:47	-0.0001	+0.0001	-0.0002	-0.011				
10:47	-0.0000	+0.0001	-0.0001	-0.012				
10:48	-0.0000	-0.0001	+0.0000	-0.012				
10:48	-0.0001	+0.0001	-0.0002	-0.012				
10:49	+0.0001	+0.0001	-0.0000	-0.012				
10:49	+0.0001	+0.0002	-0.0000	-0.012				
10:50	+0.0001	+0.0002	-0.0001	-0.012				
10:50	+0.0000	+0.0000	+0.0000	-0.011				
10:51	-0.0000	+0.0002	-0.0002	-0.011				
10:52	-0.0001	+0.0002	-0.0003	-0.011				
10:52	-0.0002	-0.0001	-0.0001	-0.011				
10:53	-0.0001	+0.0001	-0.0001	-0.012				
10:53	-0.0001	+0.0002	-0.0002	-0.012				
10:54	-0.0001	+0.0002	-0.0003	-0.012				
10:54	-0.0001	+0.0001	-0.0002	-0.012				
10:55	-0.0003	+0.0002	-0.0005	-0.013				
10:56	-0.0002	-0.0001	-0.0001	-0.013				
10:56	-0.0001	+0.0002	-0.0003	-0.014				
10:57	+0.0000	+0.0000	+0.0000	+0.000				
10:57	-0.0001	+0.0002	-0.0002	-0.027				
10:58	+0.0000	+0.0002	-0.0002	-0.024				
10:58	-0.0000	+0.0002	-0.0002	-0.023				
10:59	-0.0001	+0.0001	-0.0002	-0.023				
10:59	-0.0002	+0.0002	-0.0004	-0.026				
11:00	-0.0000	+0.0001	-0.0002	-0.026				
11:01	-0.0001	+0.0001	-0.0002	-0.025				
11:01	-0.0002	+0.0002	-0.0004	-0.026				
11:02	-0.0002	+0.0002	-0.0004	-0.027				

11:02	-0.0000	+0.0002	-0.0002	-0.028
11:03	+0.0000	+0.0001	-0.0001	-0.028
11:03	-0.0001	+0.0002	-0.0003	-0.028
11:04	-0.0001	+0.0002	-0.0004	-0.028
11:04	-0.0002	+0.0002	-0.0004	-0.028
11:05	-0.0003	+0.0002	-0.0005	-0.029
11:06	-0.0001	+0.0002	-0.0003	-0.030
11:06	-0.0001	+0.0002	-0.0003	-0.031
11:07	-0.0002	+0.0002	-0.0004	-0.031
11:07	-0.0003	+0.0003	-0.0005	-0.032
11:08	-0.0003	+0.0002	-0.0005	-0.033
11:08	-0.0003	+0.0002	-0.0006	-0.034
11:09	-0.0004	+0.0002	-0.0006	-0.035
11:10	-0.0004	+0.0001	-0.0005	-0.036
11:10	-0.0001	+0.0002	-0.0003	-0.037
11:11	-0.0002	+0.0002	-0.0003	-0.038
11:11	-0.0003	+0.0002	-0.0005	-0.038
11:12	-0.0003	+0.0001	-0.0004	-0.039
11:12	-0.0004	+0.0001	-0.0004	-0.039
11:13	-0.0004	+0.0001	-0.0006	-0.040
11:13	-0.0004	+0.0002	-0.0006	-0.040
11:14	+0.0000	+0.0000	+0.0000	+0.000
11:15	-0.0005	+0.0002	-0.0006	-0.067
11:15	-0.0005	+0.0001	-0.0006	-0.064
11:16	-0.0005	+0.0001	-0.0006	-0.064
11:16	-0.0006	+0.0000	-0.0006	-0.063
11:17	-0.0005	+0.0002	-0.0007	-0.064
11:17	-0.0006	+0.0001	-0.0006	-0.065
11:18	-0.0006	-0.0001	-0.0005	-0.064
11:18	-0.0006	+0.0002	-0.0008	-0.066
11:19	-0.0006	+0.0000	-0.0006	-0.067
11:20	-0.0006	-0.0002	-0.0005	-0.066
11:20	-0.0008	+0.0002	-0.0010	-0.067
11:21	-0.0005	+0.0002	-0.0008	-0.068
11:21	-0.0006	+0.0002	-0.0008	-0.070
11:22	-0.0007	+0.0001	-0.0008	-0.071
11:22	-0.0006	+0.0000	-0.0006	-0.072
11:23	-0.0006	+0.0001	-0.0007	-0.072
11:24	-0.0006	+0.0000	-0.0006	-0.072
11:24	-0.0006	+0.0001	-0.0007	-0.073
11:25	-0.0006	+0.0002	-0.0008	-0.073
11:25	-0.0006	-0.0000	-0.0005	-0.073
11:26	-0.0005	+0.0001	-0.0006	-0.073
11:26	-0.0005	+0.0002	-0.0007	-0.073
11:27	-0.0005	+0.0002	-0.0007	-0.073
11:27	-0.0005	+0.0002	-0.0007	-0.073
11:28	-0.0005	+0.0001	-0.0006	-0.073
11:29	-0.0005	+0.0001	-0.0005	-0.072
11:29	-0.0004	+0.0002	-0.0006	-0.072
11:30	-0.0004	+0.0001	-0.0006	-0.072
11:30	-0.0004	+0.0002	-0.0006	-0.072
11:31	-0.0004	+0.0002	-0.0006	-0.071
11:31	+0.0000	+0.0000	+0.0000	+0.000
11:32	-0.0004	+0.0002	-0.0006	-0.058
11:33	-0.0003	+0.0002	-0.0005	-0.056
11:33	-0.0003	+0.0002	-0.0005	-0.054
11:34	-0.0004	+0.0001	-0.0005	-0.053
11:34	-0.0003	-0.0001	-0.0002	-0.048
11:35	-0.0003	-0.0001	-0.0002	-0.044
11:35	-0.0003	+0.0000	-0.0003	-0.041

11:36	-0.0003	-0.0002	-0.0001	-0.038
11:36	-0.0003	-0.0001	-0.0002	-0.035
11:37	-0.0003	-0.0002	-0.0001	-0.032
11:38	-0.0003	-0.0003	-0.0000	-0.029
11:38	-0.0003	-0.0002	-0.0000	-0.027
11:39	-0.0002	-0.0057	+0.0054	-0.008
11:39	-0.0002	-0.0002	+0.0000	+0.005
11:40	-0.0002	-0.0025	+0.0022	+0.018
11:40	-0.0002	-0.0002	-0.0000	+0.027
11:41	-0.0002	-0.0142	+0.0139	+0.059
11:41	-0.0002	-0.0003	+0.0001	+0.081
11:42	-0.0002	-0.0003	+0.0001	+0.096
11:43	-0.0002	+0.0000	-0.0002	+0.106
11:43	-0.0002	-0.0001	-0.0001	+0.112
11:44	-0.0002	+0.0000	-0.0002	+0.115
11:44	-0.0002	-0.0031	+0.0029	+0.119
11:45	-0.0002	-0.0002	+0.0000	+0.121
11:45	-0.0002	-0.0002	-0.0000	+0.122
11:46	-0.0002	-0.0001	-0.0001	+0.121
11:46	-0.0004	-0.0052	+0.0048	+0.124
11:47	-0.0005	-0.0050	+0.0045	+0.128
11:48	-0.0005	-0.0049	+0.0045	+0.134
11:48	-0.0005	-0.0057	+0.0052	+0.141
11:49	+0.0000	+0.0000	+0.0000	+0.000
11:49	-0.0004	-0.0111	+0.0107	+1.131
11:50	-0.0004	-0.0041	+0.0037	+0.773
11:50	-0.0005	-0.0048	+0.0042	+0.637
11:51	-0.0005	-0.0036	+0.0030	+0.546
11:52	-0.0005	-0.0033	+0.0028	+0.487
11:52	-0.0008	-0.0031	+0.0024	+0.440
11:53	-0.0011	-0.0031	+0.0020	+0.402
11:53	-0.0017	-0.0029	+0.0011	+0.365
11:54	-0.0015	-0.0029	+0.0014	+0.335
11:54	-0.0028	-0.0048	+0.0020	+0.313
11:55	-0.0024	-0.0021	-0.0003	+0.287
11:55	-0.0021	-0.0017	-0.0004	+0.261
11:56	-0.0017	-0.0017	+0.0000	+0.237
11:57	-0.0015	-0.0014	-0.0001	+0.215
11:57	-0.0012	-0.0013	+0.0000	+0.196
11:58	-0.0011	-0.0003	-0.0008	+0.177
11:58	-0.0009	-0.0003	-0.0007	+0.159
11:59	-0.0009	-0.0002	-0.0006	+0.143
11:59	-0.0006	-0.0002	-0.0004	+0.129
12:00	-0.0005	-0.0003	-0.0002	+0.116
12:01	-0.0007	-0.0002	-0.0005	+0.105
12:01	-0.0004	-0.0003	-0.0002	+0.095
12:02	-0.0002	-0.0002	-0.0000	+0.086
12:02	-0.0004	+0.0001	-0.0005	+0.078
12:03	-0.0003	-0.0001	-0.0001	+0.071
12:03	-0.0003	-0.0001	-0.0002	+0.064
12:04	-0.0001	+0.0002	-0.0003	+0.059
12:04	-0.0002	+0.0002	-0.0004	+0.053
12:05	-0.0003	+0.0002	-0.0005	+0.048
12:06	-0.0002	+0.0002	-0.0005	+0.043
12:06	+0.0000	+0.0000	+0.0000	+0.000
12:07	-0.0000	+0.0002	-0.0003	-0.029
12:07	-0.0000	+0.0003	-0.0003	-0.029
12:08	-0.0000	+0.0003	-0.0003	-0.030
12:08	-0.0000	+0.0003	-0.0003	-0.030
12:09	+0.0000	+0.0003	-0.0002	-0.029

12:09	+0.0003	+0.0003	+0.0000	-0.026
12:10	+0.0003	+0.0003	+0.0000	-0.022
12:11	+0.0003	+0.0003	-0.0000	-0.019
12:11	+0.0003	+0.0003	-0.0000	-0.017
12:12	+0.0002	+0.0003	-0.0001	-0.015
12:12	+0.0002	+0.0013	-0.0011	-0.018
12:13	+0.0001	+0.0013	-0.0012	-0.023
12:13	+0.0002	+0.0015	-0.0013	-0.029
12:14	+0.0002	+0.0013	-0.0011	-0.036
12:14	+0.0002	+0.0003	-0.0000	-0.039
12:15	+0.0002	+0.0003	-0.0001	-0.041
12:16	+0.0001	+0.0003	-0.0002	-0.042
12:16	+0.0001	+0.0013	-0.0012	-0.044
12:17	+0.0002	+0.0003	-0.0001	-0.045
12:17	+0.0001	+0.0014	-0.0013	-0.047
12:18	+0.0001	+0.0003	-0.0002	-0.048
12:18	+0.0001	+0.0015	-0.0013	-0.050
12:19	+0.0002	+0.0016	-0.0014	-0.052
12:20	+0.0001	+0.0015	-0.0014	-0.055
12:20	+0.0001	+0.0003	-0.0002	-0.057
12:21	+0.0001	+0.0016	-0.0015	-0.060
12:21	+0.0001	+0.0014	-0.0013	-0.062
12:22	+0.0000	+0.0013	-0.0012	-0.065
12:22	+0.0000	+0.0014	-0.0013	-0.067
12:23	+0.0001	+0.0014	-0.0013	-0.070
12:23	+0.0000	+0.0000	+0.0000	+0.000
12:24	+0.0001	+0.0003	-0.0002	-0.021
12:25	+0.0000	+0.0003	-0.0003	-0.026
12:25	+0.0001	+0.0003	-0.0002	-0.025
12:26	+0.0000	+0.0013	-0.0013	-0.047
12:26	+0.0000	+0.0000	+0.0000	+0.000
12:27	+0.0000	+0.0013	-0.0013	-0.134
12:27	+0.0001	+0.0015	-0.0015	-0.146
12:28	+0.0001	+0.0015	-0.0014	-0.149
12:29	+0.0001	+0.0015	-0.0014	-0.151
12:29	+0.0001	+0.0015	-0.0014	-0.151
12:30	+0.0000	+0.0003	-0.0003	-0.138
12:30	-0.0000	+0.0002	-0.0002	-0.124
12:31	+0.0000	+0.0003	-0.0003	-0.110
12:31	+0.0000	-0.0019	+0.0019	-0.086
12:32	-0.0000	+0.0021	-0.0021	-0.079
12:32	+0.0001	-0.0022	+0.0023	-0.063
12:33	+0.0000	+0.0003	-0.0003	-0.052
12:34	+0.0000	+0.0003	-0.0003	-0.044
12:34	+0.0001	-0.0091	+0.0092	-0.014
12:35	+0.0000	-0.0030	+0.0031	+0.014
12:35	+0.0000	-0.0134	+0.0134	+0.062
12:36	-0.0000	-0.0126	+0.0126	+0.117
12:36	+0.0000	-0.0121	+0.0121	+0.176
12:37	-0.0000	-0.0120	+0.0120	+0.235
12:37	-0.0000	-0.0113	+0.0113	+0.291
12:38	+0.0000	-0.0110	+0.0111	+0.344
12:39	+0.0000	+0.0046	-0.0046	+0.375
12:39	-0.0000	+0.0045	-0.0045	+0.390
12:40	-0.0000	+0.0043	-0.0044	+0.394
12:40	+0.0000	+0.0038	-0.0038	+0.390
12:41	-0.0000	+0.0035	-0.0035	+0.381
12:41	+0.0000	+0.0036	-0.0036	+0.368
12:42	+0.0000	+0.0030	-0.0029	+0.353
12:42	+0.0000	+0.0031	-0.0031	+0.336

12:43	-0.0000	+0.0002	-0.0002	+0.320
12:44	+0.0000	+0.0026	-0.0026	+0.304
12:44	+0.0000	+0.0024	-0.0024	+0.287
12:45	-0.0000	+0.0020	-0.0020	+0.271
12:45	-0.0000	+0.0019	-0.0020	+0.255
12:46	+0.0000	+0.0013	-0.0013	+0.240
12:46	-0.0000	-0.0021	+0.0021	+0.227
12:47	-0.0000	+0.0015	-0.0015	+0.214
12:48	-0.0000	-0.0013	+0.0013	+0.203
12:48	-0.0000	+0.0003	-0.0003	+0.193
12:49	-0.0000	-0.0063	+0.0063	+0.185
12:49	+0.0000	-0.0002	+0.0002	+0.179
12:50	-0.0000	+0.0002	-0.0003	+0.172
12:50	+0.0001	-0.0014	+0.0015	+0.166
12:51	-0.0000	+0.0020	-0.0020	+0.160
12:51	-0.0000	+0.0017	-0.0017	+0.154
12:52	+0.0001	+0.0019	-0.0019	+0.147
12:53	-0.0000	+0.0003	-0.0003	+0.141
12:53	-0.0000	+0.0019	-0.0019	+0.135
12:54	-0.0001	+0.0003	-0.0004	+0.129
12:54	+0.0000	+0.0015	-0.0014	+0.123
12:55	-0.0000	+0.0014	-0.0014	+0.117
12:55	-0.0000	+0.0022	-0.0022	+0.111
12:56	+0.0000	+0.0019	-0.0019	+0.105
12:57	-0.0000	-0.0096	+0.0096	+0.102
12:57	+0.0000	+0.0018	-0.0018	+0.098
12:58	-0.0000	+0.0023	-0.0023	+0.094
12:58	-0.0000	+0.0022	-0.0022	+0.090
12:59	-0.0000	-0.0093	+0.0092	+0.088
12:59	-0.0000	+0.0003	-0.0003	+0.086

VOLUME RATE OF CHANGE 0.086 GPH

95 % CONFIDENCE INTERVAL: +/-0.033 GPH

RELATIVE FUEL TEMPERATURE: 47.66 deg F

13:00	+0.0000	+0.0029	-0.0028	+0.083
13:00	+0.0001	+0.0030	-0.0029	+0.080
13:01	+0.0000	+0.0028	-0.0028	+0.077
13:02	+0.0000	+0.0031	-0.0031	+0.073
13:02	-0.0000	+0.0028	-0.0028	+0.070
13:03	-0.0000	+0.0026	-0.0026	+0.066
13:03	-0.0001	+0.0025	-0.0026	+0.062
13:04	-0.0000	+0.0022	-0.0022	+0.058
13:04	-0.0000	+0.0026	-0.0026	+0.053
13:05	-0.0000	+0.0026	-0.0026	+0.049
13:05	-0.0000	+0.0023	-0.0023	+0.045
13:06	-0.0000	+0.0020	-0.0020	+0.041
13:07	-0.0000	+0.0020	-0.0021	+0.037
13:07	-0.0001	+0.0020	-0.0021	+0.033
13:08	+0.0000	+0.0021	-0.0021	+0.029
13:08	+0.0000	+0.0022	-0.0022	+0.025
13:09	-0.0000	+0.0015	-0.0016	+0.021
13:09	+0.0000	+0.0028	-0.0028	+0.017
13:10	+0.0000	+0.0021	-0.0021	+0.013
13:11	-0.0000	+0.0018	-0.0018	+0.010
13:11	-0.0000	+0.0018	-0.0018	+0.006
13:12	+0.0000	+0.0018	-0.0018	+0.002
13:12	-0.0000	+0.0018	-0.0019	-0.001
13:13	-0.0000	+0.0020	-0.0021	-0.005
13:13	-0.0000	+0.0000	-0.0001	-0.008
13:14	+0.0000	-0.0003	+0.0003	-0.011

```
13:14   +0.0000  -0.0002 +0.0002 -0.013
13:15   +0.0000  -0.0002 +0.0002 -0.016
13:16   -0.0000  -0.0002 +0.0002 -0.018
13:16   -0.0000  +0.0002 -0.0003 -0.020
VOLUME RATE OF CHANGE          -0.020 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.022 GPH
RELATIVE FUEL TEMPERATURE: 47.88 deg F

13:17   -0.0000  +0.0024 -0.0025 -0.023
13:17   +0.0000  +0.0019 -0.0018 -0.025
13:18   +0.0000  +0.0024 -0.0024 -0.027
13:18   +0.0000  +0.0041 -0.0041 -0.029
13:19   +0.0000  +0.0037 -0.0037 -0.032
13:19   -0.0000  +0.0032 -0.0032 -0.034
13:20   +0.0000  +0.0030 -0.0030 -0.037
13:21   -0.0000  +0.0026 -0.0026 -0.039
13:21   +0.0000  +0.0027 -0.0026 -0.042
13:22   +0.0000  +0.0025 -0.0025 -0.044
13:22   -0.0000  +0.0035 -0.0035 -0.047
13:23   +0.0000  +0.0025 -0.0025 -0.049
13:23   +0.0000  +0.0020 -0.0020 -0.052
13:24   -0.0000  +0.0024 -0.0024 -0.054
13:25   -0.0000  +0.0022 -0.0022 -0.057
13:25   +0.0000  +0.0050 -0.0049 -0.059
13:26   -0.0000  +0.0025 -0.0026 -0.062
13:26   +0.0000  +0.0021 -0.0021 -0.064
13:27   -0.0000  +0.0003 -0.0003 -0.066
13:27   -0.0000  +0.0016 -0.0016 -0.069
13:28   +0.0000  +0.0014 -0.0014 -0.071
13:28   -0.0000  +0.0019 -0.0019 -0.073
13:29   -0.0000  +0.0022 -0.0023 -0.075
13:30   -0.0000  +0.0003 -0.0003 -0.077
13:30   -0.0000  +0.0003 -0.0003 -0.079
13:31   -0.0000  +0.0014 -0.0014 -0.080
13:31   -0.0000  +0.0016 -0.0017 -0.082
13:32   +0.0000  +0.0003 -0.0003 -0.084
13:32   -0.0000  +0.0003 -0.0003 -0.085
13:33   -0.0001  +0.0002 -0.0003 -0.087
VOLUME RATE OF CHANGE          -0.087 GPH
 95 % CONFIDENCE INTERVAL:  +/-0.016 GPH
RELATIVE FUEL TEMPERATURE: 47.89 deg F
```

Newsday

235 Pinelawn Road, Melville, NY 11747-4250

RECEIVED

JAN 0 9 1998

REG 1 - OIL SPILLS

January 8, 1998

CERTIFIED MAIL RRR - Z 115 996 787

Mary Henning
Engineering Aide
NYSDEC – Region 1
Building 40 – SUNY
Stony Brook, New York 11790

SUBJECT: **Spill #97-09711 Tank System Tightness Retest With Petro-Tight II**


Dear Mrs. Henning:

As per today's conversations with Mr. Tony Leung of your office and Mr. Ken Clunie of SCDHS, both NYSDEC and SCDHS are allowing Newsday to replace the Horner EZY-Check II with the Petro-Tight II for Spill #97-09711 tank testing. The premise of this decision was based on the inability to test the tank system with the Horner EZY-Check II due to electrical interference.

Fenley and Nicol Environmental is scheduled to test the tank system on Saturday, January 17th, 1998 with the Petro-Tight II.

Thank you for your help with this matter and please contact me for any questions and/or comments.

Sincerely,



David Krueger
Engineering Services
(516) 843-5437
(516) 843-3444 fax

CC: Tim McGarry
John Tillotson
Ken Clunie – SCDHS (Certified Mail RRR - Z 115 996 788)
Tony Leung – NYSDEC (Certified Mail RRR - Z 115 996 789)

Attachments: (0)
file: DNK(97ust674.DOC)

TTF

Newsday 97-09711

235 Pinelawn Road, Melville, NY 11747-4250

February 23, 1998

CERTIFIED MAIL RRR - Z 341 086 255

RECEIVED
FEB 27 1998
REG 1 - OIL SPILLS

Mary Henning
Engineering Aide
NYSDEC – Region 1
Building 40 – SUNY
Stony Brook, New York 11790

SUBJECT: **Spill #97-09711 Tank Testing Status**

Dear Mrs. Henning:

The tank associated with Spill #97-09711 passed a "tank only" test on January 31, 1998. Fenley and Nicol Environmental will be sending their results to your office and to Mr. Ken Clunie of SCDHS within the next week.

The tank will remain out of service while the condition of the suction line is being investigated. Currently, the suction line is empty of all liquid and isolated from the tank.

Again, thank you for your assistance with this matter. Please contact me for any questions and/or comments.

Sincerely, DK

David Krueger
Engineering Services
(516) 843-5437
(516) 843-3444 fax

11/3/03 - T/C TO KRUEGER - NO LONGER WORKS AT NEWSDAY

CC: Tom McGlennon – Fenley & Nicol Environmental
Tim McGarry
John Tillotson
Ken Clunie – SCDHS (Certified Mail RRR - Z 341 086 256)

Attachments: (0)
file: DNK(97ust675.DOC)

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 9709711

SPILL NAME: NEWSDAY **DEC LEAD:** T/T/F

SPILL DATE: 11/20/1997 **SPILL TIME:** 2:00 pm

CALL RECEIVED DATE: 11/20/1997 **RECEIVED TIME:** 2:24 pm

SPILL LOCATION

PLACE: NEWSDAY **COUNTY:** Suffolk

STREET: 235 PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: DAVE KRUEGER **CONTACT PHONE:** (516) 843-5437

CONT. FACTOR: Tank Test Failure **SPILL REPORTED BY:** Tank Tester

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:
gross failure on system test

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY	235 PINELAWN ROAD MELVILLE ZZ	DAVE KRUEGER (516) 843-5437

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
south	25,000				03	0.00	

DEC REMARKS:

HISTORY OF PROBLEMS WITH INTERFERENCE WHEN TESTING, LATER TESTS PASSED

PIN **T & A** **COST CENTER**

CLASS: B3 **CLOSE DATE:** 12/11/2009 **MEETS STANDARDS:** False

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☐ Field Notes ■ Phone Conversation ☐ Meeting Notes **Spill No.** 98-25125

Location		Representatives on site	time in	time out
Name	Newsday	DEC Mr. M. Discenzo		
Address	Pinelawn Rd			
Town	Melville			
Phone				
Weather	**Temperature** / **General conditions**	PRP		
humidity: Dry, Humid, Very humid	Cold, Fair, Warm, Hot	Sunny, Partly Cloudy, Cloudy, Rain / Snow		

Date	Time	Inspection Narrative
11/16/98	11:53	Left Message for Joe Demauro
11/24/98	10:10	Left Message for Joe Demauro
11/25/98	15:15	Telcon with Joe Demauro - Removed 4 Drums of soil while replacing sump on top of tank - Collected End point sample will Analyze for 8021 and 8270 - Will send in disposal recieipts when recieved
1/14/99	10:30	Telcon with Stan Suchanski - Upgrading diesel dispensers as a continuation of earlier project - Contamination Encountered below old dispensers removed all contaminated soil possible - Unable to excavate all - Collected End point Samples and continued with upgrade - Previous contamination was found in vacinity of tanks while installing spill boxes

Continued Page ____ Of ____

98-25125(M.A.)

New York State Department of Environmental Conservation
Division of Environmental Remediation, Region One
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356

John P. Cahill
Commissioner

COVER SHEET FAX

To: Mr. Stan Sucharski, Fenley & Nicol Environmental
Fax #: 586-4920
RE: Spill# 98-25125, Newsday, 235 Pilelawn Rd, Melville
Date: January 12, 1999
Pages: 1, including this cover sheet.

Comments:

During a telephone conversation earlier today, you informed this Department of diesel soil contamination in the dispenser area which was discovered during upgrade work at the above referenced location.

You had stated that all of the contamination could not be removed. Therefore, end point soil samples must be retrieved and analyzed; the samples must be analyzed by a NYS Certified Laboratory for EPA Methods 8021 and 8270(B.N.).

Please arrange to have the sample analysis and soil disposal documentation submitted to the NYSDEC investigator for the above referenced spill, Matthew Darcangelo, who can be reached at (516) 444-0336.

(O.D.) **From the desk of:**
Brian Campbell
Environmental Engineer I
TEL.(516) 444-0325

Fenley & Nicol Environmental

"SOLUTIONS AT WORK"™

445 Brook Avenue, Deer Park, New York 11729 (516) 586-4900 • NYC (718) 204-1998 FAX (516) 586-4920

FENLEY & NICOL ENVIRONMENTAL, INC. FAX NUMBERS:
General: (516) 536-4920
Purchasing: (516) 254-6145
Accounting: (516) 242-6452

FAX TRANSMITTAL COVER SHEET

DATE: 3/23/99

COMPANY: NYS DEC

ATTENTION: MATT Decarogelo

FAX NUMBER: 444 0373

NUMBER OF PAGES (INCLUDING COVER SHEET): 4

FAXED TO YOU BY: Joe DeMauro EXTENSION: 150

HARD COPY TO FOLLOW: _____ YES ✓ NO

SUBJECT: Disposal Doc Newsday

J. DeMauro

CONFIDENTIALITY NOTE

The documents accompanying this telecopy transmission contain information which is confidential or privileged. The information is intended for the use of the individual or entity named on this transmission sheet. If you are not the intended recipient, be aware that disclosure, copying, distribution, or use of the contents of this telecopied information is prohibited.

PLEASE TYPE OR PRINT CLEARLY

JOB # 980984

DATE 1/25/99

MANIFEST # No. 05650

1. **GENERATOR OF WASTE**

NAME NEWSDAY

ADDRESS 235 PINELAWN RD MELVILLE NY

PHONE NUMBER

SITE LOCATION SAME

2. **IDENTIFICATION OF WASTE**

PROPER U.S. D.O.T. SHIPPING NAME	STATE CODE	CONTAINER TYPE	QTY.
DIESEL CONTAMINATED SOIL	NO 11	55 GALLON DOT DRUM	1
Spill # (if applicable)	ERG #		

3. **GENERATOR'S CLASSIFICATION**

This is to certify that the herein named materials are properly described, classified and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, Environmental Protection Administration and Local State regulations. The wastes are described herein were consigned to the transporter named. The TSD Facility can and will accept the shipment of waste, and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S OR GENERATOR'S SUPERVISOR M SEPE AGENT FOR
and/or (Authorized Agent) please print or type

SUPERVISOR'S SIGNATURE M. C TITLE TECH

4. **TRANSPORTER NAME AND ADDRESS** (#1) (#2)

(#1)	(#2)
NAME FENLEY & NICOL ENVIRONMENTAL INC.	NAME
ADDRESS 445 BROOK AVENUE, DEER PARK, NY 11729	ADDRESS
PHONE NUMBER 24 Hour Emergency# (516) 586-4900	PHONE NUMBER
DRIVER'S NAME M SEPE SIGNATURE	DRIVER'S NAME SIGNATURE
INDUSTRIAL WASTE HAULER PERMIT # 1A-036 VEHICLE PLATE # 14807 AD	INDUSTRIAL WASTE HAULER PERMIT # VEHICLE PLATE #

5. **DISPOSAL SITE** (Must be filled in by disposal site)

NAME OF FACILITY

ADDRESS OF FACILITY

PHONE NUMBER

This load was received as stated by generator YES ☐ NO ☐

DISPOSAL SITE IDENTIFICATION NUMBER (if applicable)

DISPOSAL SITE INSPECTOR NAME

SIGNATURE DATE

GENERATOR-White TRANSPORTER-Yellow DISPOSAL-Pink ORANGE-File

1 14 99	UTICA T OI CH #1396	5572	6	G/W
1 14 99	ENG CO 225	5560	2	DRILL
1 14 99	SCHRIEBER	5600	2	O/B
1 14 99	RAINBO N PRIME PROD	5597	1	C/B
1 18 99	MASS HOSP	5596	1	O/B
1 18 99	DEC 138 BRUCKNER	7124	2	DRILL
1 18 99	MASS GENERAL	5596	1	O/B
1 18 99	LEVER CO	5649	1	O/B
1 25 99	NEWSDAY	5650	1	S/O
1 25 99	BETH ABRAHAM	5836	16	DRILL
2 2 99	SR QUARTERS	5737	2	O/B
2 2 99				

2 4 99 SHIPPED CHAMBERS MAN # FOOO14

NON-HAZARDOUS WASTE MANIFEST

If waste is asbestos waste, complete all Sections.
If waste is NOT asbestos waste, complete only Sections 1, 2, 3, 4 and 5.

Manifest No. [illegible]

GENERATOR INFORMATION (generator to complete)

a) Generator's Name: [illegible] Industrial Environmental
b) Generating Location (Name): [illegible]
Generator's Address: Brock Court Deer Pk 11749
c) Address: Same
d) Generator's Representative: Joe DeMauro
e) Telephone Number: ( ) [illegible]
f) Telephone Number: (516) 586-4900
g) USA WASTE APPROVAL CODE: NY 013 930928 552
h) Common Name of Waste: Industrial Solid
i) Asbestos ONLY - Friable; Non-friable; Solid; N/A; % friable; % non-friable
j) Description of Waste: Solid
k) Disposal Volume: 20
Tons; Cubic Yards; Other
l) Number of Containers:
m) Type of Containers: TR

TYPE OF CONTAINER
TR - TRUCK
DM - METAL DRUM
DP - PLASTIC DRUM
BA - BAG
SS - 6 M...
SC - 12 M...

n) I hereby warrant that the above named material is the same material as represented on the Special Waste Disposal Application certified by the above USA Waste Code and such material was delivered to the transporter on the shipment date referenced below.

Joseph DeMauro — Generator's Authorized Agent Name (print/type)
Joseph DeMauro — Signature of Generator's Authorized Agent
2/4/99 — Shipment Date

SECTION 2 TRANSPORTER 1

a) Transporter's Name: Hewitt Trucking
b) Transporter's Address: P.O. Box 7178 Southampton, NY
c) Telephone Number: (516) 728-5507
d) Vehicle License No./State: #511 - AD-01665
e) Trailer or Container No.: #169 - XC58822
f) Name of Driver (print/type): Bruce E. Sulp
g) I hereby warrant that the above named and described material was received from the generator on the date of receipt referenced below.
Bruce E. Sulp — Signature of Driver
2/4/99 — Date of Receipt
h) I hereby warrant that the above named and described material was delivered without incident or contamination on the date of delivery referenced below.
Earl Hewitt — Signature of Driver
2-5-99 — Date of Delivery

SECTION 3 TRANSFER FACILITY - (Complete if applicable)

a) Transfer Facility's Name:
b) Transfer Facility's Address:
c) Telephone Number: ( )
d) Vehicle License No./State:
e) Trailer or Container No.:
f) Name of Transfer Facility's Authorized Agent (print/type)
g) I hereby warrant that the above [illegible] from the transporter on the date of [illegible]
Signature of Transfer Facility's Authorized Agent
h) I hereby warrant that the above named and described material was delivered to the transporter without incident or contamination on the date of delivery referenced below.
Signature of Transfer Facility's Authorized Agent

SECTION 4 TRANSPORTER 2 - (Complete if applicable)

a) Transporter's Name:
b) Transporter's Address:
c) Telephone Number: ( )
d) Vehicle License No./State:
e) Trailer or Container No.:
f) Name of Driver (print/type)
g) I hereby warrant that the above named and described material was received on the date of receipt referenced below.
Signature of Driver — Date of Receipt
h) I hereby warrant that the above named and described material was delivered on the delivery date referenced below.
Signature of Driver — Date of Delivery

SECTION 5 DESTINATION (Disposal Facility)

a) Disposal Facility's Name: Chambers Inc
b) Physical Address: Fredonia, NY
c) Telephone Number: (607) [illegible]
d) Mailing Address:
e) Name of Disposal Facility's Authorized Agent (print/type)
f) The material delivered by the Transporter has been received at the Disposal Facility.
Signature of Disposal Facility's Authorized Agent — 2-5-99 Date of Receipt
g) The material delivered by the Transporter has been rejected for disposal at the Disposal Facility.
Signature of Disposal Facility's Authorized Agent — Date of Rejection
Signature of Driver — Date of Return

SECTION 6 ASBESTOS (operator to complete)

"Operator" is defined as the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both.

a) Operator's Name:
c) Telephone Number: ( )
d) Operator's Address:
f) Recommended special handling instructions and additional information:
g) Operator's Certification: I hereby warrant and declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and domestic law, regulations, ordinances, orders, rules and/or standards.

Operator's Name (print/type) — Signature of Operator's Authorized Agent — Date

Responsible Agency Name and Address:

Fenley & Nicol Environmental Inc.

445 Brook Avenue, Deer Park, NY 11729 (516) 586-4900 • NYC (718) 204-4993 FAX (516) 586-4920

RECEIVED
APR 30 1999
REG 1 - OIL SPILLS

"SOLUTIONS AT WORK" ®

April 28, 1999

Matt Darcangelo
NYS DEC
Division of Environmental Remediation, Region One
Spill Prevention and Response
Building 40 – SUNY
Stony Brook NY 11790-2356

Re: Spill# 98-25125
Newsday
235 Pinelawn Rd
Melville NY

Dear Mr. Darcangelo

Attached please find copies of the analytical report for the end point samples collected under the three-diesel fuel dispensers at above referenced site.

Sincerely yours

Stan Sucharski
Project Manager

SS/kb

cc: Tim McGarry

attachments

c:\mydocuments\letters\newsday

Analab Inc.

FACSIMILE TRANSMITTAL

DATE: 2/9/99 NUMBER OF PAGES: 17

PLEASE HAND DELIVER THE FOLLOWING TO:

NAME: Stan S. FAX #516 586-4920

COMPANY: Ferley Nicol RE:

SENT BY:

OMAYRA PENAS

COMMENTS:

PROJECT # L1537-

IF YOU DO NOT RECEIVE ALL PAGES, PLEASE CALL US AT (732) 225-4111 AS SOON AS POSSIBLE.

205 CAMPUS PLAZA 1, RARITAN CENTER, EDISON, NJ. 08837

IN BUSINESS FOR THE ENVIRONMENT

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ 08837 Tel(732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID: ENDPOINT EAST DISPENSER
LAB ID: L1537-3 1.0 GM PPB
FILENAME: D:\DATA1\U012711.RAW

MATRIX: SOIL
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		5.9
74-87-3	CHLOROMETHANE	U		5.9
75-01-4	VINYL CHLORIDE	U		5.9
74-97-5	BROMOMETHANE	U		5.9
75-00-3	CHLOROETHANE	U		5.9
75-69-4	TRICHLOROFLOUROMETHANE	U		5.9
75-35-4	1,1 DICHLOROETHENE	U		5.9
75-09-2	METHYLENE CHLORIDE	U		5.9
156-60-5	TRANS-1,2-DICHLOROETHENE	U		5.9
75-34-3	1,1 DICHLOROETHANE	U		12
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		5.9
67-66-3	CHLOROFORM	U		5.9
74-97-5	BROMOCHLOROMETHANE	U		5.9
71-55-6	1,1,1 TRICHLOROETHANE	U		5.9
563-58-6	1,1 DICHLOROPROPENE	U		5.9
56-23-5	CARBON TETRACHLORIDE	U		5.9
107-06-2	1,2 DICHLOROETHANE	U		5.9
79-01-6	TRICHLOROETHENE	U		5.9
78-87-5	1,2 DICHLOROPROPANE	U		5.9
75-27-4	BROMODICHLOROMETHANE	U		5.9
74-95-3	DIBROMOMETHANE	U		5.9
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		5.9
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		5.9
630-20-6	1,1,2-TRICHLOROETHANE	U		5.9
142-28-9	1,3 DICHLOROPROPANE	U		5.9
127-18-4	TETRACHLOROETHENE	U		5.9
75-27-4	DIBROMOCHLOROMETHANE	U		5.9
106-93-4	1,2 DIBROMOETHANE	U		5.9
108-90-7	CHLOROBENZENE	U		5.9
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		5.9
75-25-2	BROMOFORM	U		5.9
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		5.9
96-18-4	1,2,3 TRICHLOROPROPANE	U		5.9
108-86-1	BROMOBENZENE	U		5.9
95-49-8	2, CHLOROTOLUENE	U		5.9
106-34-4	4, CHLOROTOLUENE	U		5.9
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		5.9
87-68-3	HEXACHLOROBUTADIENE	U		5.9
87-61-6	1,2,3 TRICHLOROBENZENE	U		5.9

% SOLIDS 85%

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ, 08837, Tel (732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID: ENDPOINT EAST DISPENSER
LAB ID: L1537-3 1.0 GM PPB
FILENAME: D:\DATA1\V012711.RAW

MATRIX: SOLID
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		5.9
	METHYL TERT BUTYL ETHER (MTBE)	U		5.9
71-43-2	BENZENE	U		5.9
108-88-3	TOLUENE	12		5.9
100-41-4	ETHYLBENZENE	320		5.9
	M&P XYLENES	27		12
95-47-6	O-XYLENE	230		5.9
100-42-5	STYRENE	U		5.9
98-82-8	ISOPROPYLBENZENE	140		5.9
103-65-1	n-PROPYLBENZENE	760		5.9
	2-CHLORTOLUENE+P-ETHYLTOLUENE	580		12
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	700		12
98-06-6	TERT-BUTYLBENZENE	230		5.9
95-63-6	1,2,4-TRIMETHYLBENZENE	U		5.9
135-98-8	SEC-BUTYLBENZENE	190		5.9
541-73-1	1,3 DICHLOROBENZENE	320		5.9
99-87-6	ISOPROPYLTOLUENE	150		5.9
106-46-7	1,4 DICHLOROBENZENE	U		5.9
104-51-8	n-BUTYLBENZENE	810		5.9
95-50-1	1,2 DICHLOROBENZENE	U		5.9
120-82-1	1,2,4 TRICHLOROBENZENE	140		5.9
87-68-3	HEXACHLOROBUTADIENE	25		5.9
91-20-3	NAPHTHALENE	31		5.9

% SOLIDS 85%

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT EAST DIS.
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 30
DATA FILE : >F9818
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-3
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
62-75-9	N-NITROSODIMETHYLAMINE	U		3900
62-53-3	ANILINE	U		3900
111-44-4	BIS (2-CHLOROETHYL) ETHER	U		3900
541-73-1	1,3-DICHLOROBENZENE	U		3900
106-46-7	1,4-DICHLOROBENZENE	U		3900
95-50-1	1,2-DICHLOROBENZENE	U		3900
100-51-6	BENZYL ALCOHOL	U		3900
108-60-1	2,2'-OXY BIS(1-CHLOROPROPANE)	U		3900
67-72-1	HEXACHLOROETHANE	U		3900
621-64-7	N-NITROSODIPROPYL AMINE	U		3900
98-95-3	NITROBENZENE	U		3900
78-59-1	ISOPHORONE	U		3900
111-91-1	BIS (2-CHLOROETHOXY) METHANE	U		3900
120-82-1	1,2,4-TRICHLOROBENZENE	U		3900
91-20-3	NAPHTHALENE	U		19000
65-85-0	BENZOIC ACID	U		3900
106-47-8	4-CHLOROANILINE	U		3900
87-68-3	HEXACHLOROBUTADIENE	18000		3900
91-57-6	2-METHYLNAPHTHALENE	U		3900
77-47-4	HEXACHLOROCYCLOPENTADIENE	U		3900
91-58-7	2-CHLORONAPHTHALENE	U		19000
88-74-4	2-NITROANILINE	U		3900
208-96-8	ACENAPHTHYLENE	U		3900
131-11-3	DIMETHYL PHTHALATE	U		3900
606-20-2	2,6-DINITROTOLUENE	5400		3900
83-32-9	ACENAPHTHENE	U		19000
99-09-2	3-NITROANILINE	U		3900
132-64-9	DIBENZOFURAN	U		3900
121-14-2	2,4-DINITROTOLUENE	11000		3900
86-73-7	FLUORENE	U		3900
84-66-2	DIETHYL PHTHALATE			

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT EAST DIS.
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 3G
DATA FILE : >F9818
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-3
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
7005-72-3	4-CHLOROPHENYL PHENYL ETHER	U		3900
100-01-6	4-NITROANILINE	U		20000
86-30-6	N-NITROSODIPHENYL AMINE	6100		3900
101-55-3	4-BROMOPHENYL PHENYL ETHER	U		3900
118-74-1	HEXACHLOROBENZENE	U		3900
85-01-8	PHENANTHRENE	15000		3900
120-12-7	ANTHRACENE	U		3900
86-74-8	CARBAZOLE	U		3900
84-74-2	DI-N-BUTYL PHTHALATE	U		3900
206-44-0	FLUORANTHENE	U		3900
92-87-5	BENZIDINE	U		20000
129-00-0	PYRENE	U		3900
85-68-7	BUTYLBENZYL PHTHALATE	U		3900
56-55-3	BENZO (A) ANTHRACENE	U		3900
91-94-1	3,3'-DICHLOROBENZIDINE	U		20000
218-01-9	CHRYSENE	U		3900
117-81-7	BIS (2-ETHYLHEXYL) PHTHALATE	U		3900
117-84-0	DI-N-OCTYL PHTHALATE	U		3900
205-99-2	BENZO (B) FLUORANTHENE	U		3900
207-08-9	BENZO (K) FLUORANTHENE	U		3900
50-32-8	BENZO (A) PYRENE	U		3900
193-39-5	INDENO (1,2,3-CD) PYRENE	U		3900
53-70-3	DIBENZO (A,H) ANTHRACENE	U		3900
191-24-2	BENZO (GHI) PERYLENE	U		3900

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

ANAlab Inc,205 Campus Plaza I,Edison,NJ,08837:Phone(732)225-4111Fax(732)225-4110

TABULATED ANALYTICAL REPORT

CLIENT : FENNICOL
CLIENT ID : ENDPOINT EAST DISPEN
PROJECT : NEWSDAY - MELLVILLE
SAMPLE VOLUME : NA
DATA FILE : NA
EXTRACTION DATE : NA
NJDEP ID : 12531

LABSAMPLE ID : L1537-3
DATE SAMPLED : 21-JAN-99
DATE RECEIVED : 26-JAN-99
DATE ANALYZED : 27-JAN-99
DILUTION FACTOR : NA
ANALYST : MZ

CASNO	Analyte	Result %	MDL %	PQL %
NA	TOTAL SOLIDS	85		

MDL = Method Detection Limit (Statistical, 40CFR136 APXB)
PQL = Practical Quantitation Limit
J = Estimated Value, < MDL, > Zero
U = Not Detected
B = Compund Also Present In Blank
E = Concentration Exceeds Calibration Range
D = Result Quantified From Secondary Dilution
NA = Not Applicable / Not Available

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ 08837 Tel(732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID; ENDPOINT MIDDLE DISPENSER
LAB ID: L1537-2 1.0 GM PPB
FILENAME: D:\DATA1\U012710.RAW

MATRIX: SOIL
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		6.0
74-87-3	CHLOROMETHANE	U		6.0
75-01-4	VINYL CHLORIDE	U		6.0
74-97-5	BROMOMETHANE	U		6.0
75-00-3	CHLOROETHANE	U		6.0
75-69-4	TRICHLOROFLOUROMETHANE	U		6.0
75-35-4	1,1 DICHLOROETHENE	U		6.0
75-09-2	METHYLENE CHLORIDE	U		6.0
156-60-5	TRANS-1,2-DICHLOROETHENE	U		6.0
75-34-3	1,1 DICHLOROETHANE	U		6.0
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		12
67-66-3	CHLOROFORM	U		6.0
74-97-5	BROMOCHLOROMETHANE	U		6.0
71-55-6	1,1,1 TRICHLOROETHANE	U		6.0
563-58-6	1,1 DICHLOROPROPENE	U		6.0
56-23-5	CARBON TETRACHLORIDE	U		6.0
107-06-2	1,2 DICHLOROETHANE	U		6.0
79-01-6	TRICHLOROETHENE	U		6.0
78-87-5	1,2 DICHLOROPROPANE	U		6.0
75-27-4	BROMODICHLOROMETHANE	U		6.0
74-95-3	DIBROMOMETHANE	U		6.0
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		6.0
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		6.0
630-20-6	1,1,2-TRICHLOROETHANE	U		6.0
142-28-9	1,3 DICHLOROPROPANE	U		6.0
127-18-4	TETRACHLOROETHENE	U		6.0
75-27-4	DIBROMOCHLOROMETHANE	U		6.0
106-93-4	1,2 DIBROMOETHANE	U		6.0
108-90-7	CHLOROBENZENE	U		6.0
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		6.0
75-25-2	BROMOFORM	U		6.0
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		6.0
96-18-4	1,2,3 TRICHLOROPROPANE	U		6.0
108-86-1	BROMOBENZENE	U		6.0
95-49-8	2, CHLOROTOLUENE	U		6.0
106-34-4	4, CHLOROTOLUENE	U		6.0
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		6.0
87-68-3	HEXACHLOROBUTADIENE	U		6.0
87-61-6	1,2,3 TRICHLOROBENZENE	U		6.0

% SOLIDS 84%

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ, 08837, Tel (732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID: ENDPOINT MIDDLE DISPENSER
LAB ID: L1537-2 1.0 GM PPB
FILENAME: D:\DATA1\V012710.RAW

MATRIX: SOLID
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		6.0
	METHYL TERT BUTYL ETHER (MTBE)	U		6.0
71-43-2	BENZENE	U		6.0
108-88-3	TOLUENE	24		6.0
100-41-4	ETHYLBENZENE	250		6.0
	M&P XYLENES	22		12
95-47-6	O-XYLENE	170		6.0
100-42-5	STYRENE	190		6.0
98-82-8	ISOPROPYLBENZENE	100		6.0
103-65-1	n-PROPYLBENZENE	600		6.0
	2-CHLORTOLUENE+P-ETHYLTOLUENE	460		12
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	450		12
98-06-6	TERT-BUTYLBENZENE	300		6.0
95-63-6	1,2,4-TRIMETHYLBENZENE	U		6.0
135-98-8	SEC-BUTYLBENZENE	120		6.0
541-73-1	1,3 DICHLOROBENZENE	170		6.0
99-87-6	ISOPROPYLTOLUENE	180		6.0
106-46-7	1,4 DICHLOROBENZENE	U		6.0
104-51-8	n-BUTYLBENZENE	610		6.0
95-50-1	1,2 DICHLOROBENZENE	U		6.0
120-82-1	1,2,4 TRICHLOROBENZENE	100		6.0
87-68-3	HEXACHLOROBUTADIENE	U		6.0
91-20-3	NAPHTHALENE	130		6.0

% SOLIDS 84%

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT MIDDLE
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 30
DATA FILE : >F9817
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-2
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
62-75-9	N-NITROSODIMETHYLAMINE	U		4000
62-53-3	ANILINE	U		4000
111-44-4	BIS (2-CHLOROETHYL) ETHER	U		4000
541-73-1	1,3-DICHLOROBENZENE	U		4000
106-46-7	1,4-DICHLOROBENZENE	U		4000
95-50-1	1,2-DICHLOROBENZENE	U		4000
100-51-6	BENZYL ALCOHOL	U		4000
108-60-1	2,2'-OXY BIS(1-CHLOROPROPANE)	U		4000
67-72-1	HEXACHLOROETHANE	U		4000
621-64-7	N-NITROSODIPROPYL AMINE	U		4000
98-95-3	NITROBENZENE	U		4000
78-59-1	ISOPHORONE	U		4000
111-91-1	BIS (2-CHLOROETHOXY) METHANE	U		4000
120-82-1	1,2,4-TRICHLOROBENZENE	U		4000
91-20-3	NAPHTHALENE	U		20000
65-85-0	BENZOIC ACID	U		4000
106-47-8	4-CHLOROANILINE	U		4000
87-68-3	HEXACHLOROBUTADIENE	26000		4000
91-57-6	2-METHYLNAPHTHALENE	U		4000
77-47-4	HEXACHLOROCYCLOPENTADIENE	U		4000
91-58-7	2-CHLORONAPHTHALENE	U		20000
88-74-4	2-NITROANILINE	U		4000
208-96-8	ACENAPHTHYLENE	U		4000
131-11-3	DIMETHYL PHTHALATE	U		4000
606-20-2	2,6-DINITROTOLUENE	6400		4000
83-32-9	ACENAPHTHENE	U		20000
99-09-2	3-NITROANILINE	U		4000
132-64-9	DIBENZOFURAN	U		4000
121-14-2	2,4-DINITROTOLUENE	13000		4000
86-73-7	FLUORENE	U		4000
84-66-2	DIETHYL PHTHALATE			

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT MIDDLE
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 30
DATA FILE : >F9817
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-2
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
7005-72-3	4-CHLOROPHENYL PHENYL ETHER	U		4000
100-01-6	4-NITROANILINE	U		20000
86-30-6	N-NITROSODIPHENYL AMINE	6700		4000
101-55-3	4-BROMOPHENYL PHENYL ETHER	U		4000
118-74-1	HEXACHLOROBENZENE	U		4000
85-01-8	PHENANTHRENE	15000		4000
120-12-7	ANTHRACENE	U		4000
86-74-8	CARBAZOLE	U		4000
84-74-2	DI-N-BUTYL PHTHALATE	U		4000
206-44-0	FLUORANTHENE	U		4000
92-87-5	BENZIDINE	U		20000
129-00-0	PYRENE	U		4000
85-68-7	BUTYLBENZYL PHTHALATE	U		4000
56-55-3	BENZO (A) ANTHRACENE	U		4000
91-94-1	3,3'-DICHLOROBENZIDINE	U		20000
218-01-9	CHRYSENE	U		4000
117-81-7	BIS (2-ETHYLHEXYL) PHTHALATE	U		4000
117-84-0	DI-N-OCTYL PHTHALATE	U		4000
205-99-2	BENZO (B) FLUORANTHENE	U		4000
207-08-9	BENZO (K) FLUORANTHENE	U		4000
50-32-8	BENZO (A) PYRENE	U		4000
193-39-5	INDENO (1,2,3-CD) PYRENE	U		4000
53-70-3	DIBENZO (A,H) ANTHRACENE	U		4000
191-24-2	BENZO (GHI) PERYLENE	U		4000

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

ANAlab Inc,205 Campus Plaza I,Edison,NJ,08837:Phone(732)225-4111Fax(732)225-4110

TABULATED ANALYTICAL REPORT

CLIENT	: FENNICOL	LABSAMPLE ID	: L1537-2
CLIENT ID	: ENDPOINT MIDDLE DISP	DATE SAMPLED	: 21-JAN-99
PROJECT	: NEWSDAY - MELLVILLE	DATE RECEIVED	: 26-JAN-99
SAMPLE VOLUME	: NA	DATE ANALYZED	: 27-JAN-99
DATA FILE	: NA	DILUTION FACTOR	: NA
EXTRACTION DATE	: NA	ANALYST	: MZ
NJDEP ID	: 12531		

CASNO	Analyte	Result %	MDL %	PQL %
NA	TOTAL SOLIDS	84		

MDL = Method Detection Limit (Statistical, 40CFR136 APXB)
PQL = Practical Quantitation Limit
J = Estimated Value, < MDL, > Zero
U = Not Detected
B = Compund Also Present In Blank
E = Concentration Exceeds Calibration Range
D = Result Quantified From Secondary Dilution
NA = Not Applicable / Not Available

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ 08837 Tel(732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID: ENDPOINT WEST DISPENSER
LAB ID: L1537-1 1.0 GM PPB
FILENAME: D:\DATA1\U012709.RAW

MATRIX: SOIL
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		5.6
74-87-3	CHLOROMETHANE	U		5.6
75-01-4	VINYL CHLORIDE	U		5.6
74-97-5	BROMOMETHANE	U		5.6
75-00-3	CHLOROETHANE	U		5.6
75-69-4	TRICHLOROFLOUROMETHANE	U		5.6
75-35-4	1,1 DICHLOROETHENE	U		5.6
75-09-2	METHYLENE CHLORIDE	U		5.6
156-60-5	TRANS-1,2-DICHLOROETHENE	U		5.6
75-34-3	1,1 DICHLOROETHANE	U		11
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		5.6
67-66-3	CHLOROFORM	U		5.6
74-97-5	BROMOCHLOROMETHANE	U		5.6
71-55-6	1,1,1 TRICHLOROETHANE	U		5.6
563-58-6	1,1 DICHLOROPROPENE	U		5.6
56-23-5	CARBON TETRACHLORIDE	U		5.6
107-06-2	1,2 DICHLOROETHANE	U		5.6
79-01-6	TRICHLOROETHENE	U		5.6
78-87-5	1,2 DICHLOROPROPANE	U		5.6
75-27-4	BROMODICHLOROMETHANE	U		5.6
74-95-3	DIBROMOMETHANE	U		5.6
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		5.6
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		5.6
630-20-6	1,1,2-TRICHLOROETHANE	U		5.6
142-28-9	1,3 DICHLOROPROPANE	U		5.6
127-18-4	TETRACHLOROETHENE	U		5.6
75-27-4	DIBROMOCHLOROMETHANE	U		5.6
106-93-4	1,2 DIBROMOETHANE	U		5.6
108-90-7	CHLOROBENZENE	U		5.6
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		5.6
75-25-2	BROMOFORM	U		5.6
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		5.6
96-18-4	1,2,3 TRICHLOROPROPANE	U		5.6
108-86-1	BROMOBENZENE	U		5.6
95-49-8	2, CHLOROTOLUENE	U		5.6
106-34-4	4, CHLOROTOLUENE	U		5.6
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		5.6
87-68-3	HEXACHLOROBUTADIENE	U		5.6
87-61-6	1,2,3 TRICHLOROBENZENE	U		5.6

% SOLIDS 90%

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

ANAlab Inc., 205 Campus Plaza 1, Edison, NJ, 08837, Tel (732)225-4111 Fax (732)225-4110

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
SW846 8021

PROJECT: NEWSDAY-MELVILLE
SAMPLE ID: ENDPOINT WEST DISPENSER
LAB ID: L1537-1 1.0 GM PPB
FILENAME: D:\DATA1\V012709.RAW

MATRIX: SOLID
DATE ANALYZED: 1/27/99
ANALYST: RW
DILUTION 5

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		5.6
	METHYL TERT BUTYL ETHER (MTBE)	U		5.6
71-43-2	BENZENE	U		5.6
108-88-3	TOLUENE	6.3		5.6
100-41-4	ETHYLBENZENE	150		11
	M&P XYLENES	U		5.6
95-47-6	O-XYLENE	170		5.6
100-42-5	STYRENE	100		5.6
98-82-8	ISOPROPYLBENZENE	68		5.6
103-65-1	n-PROPYLBENZENE	410		11
	2-CHLORTOLUENE+P-ETHYLTOLUENE	220		11
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	390		5.6
98-06-6	TERT-BUTYLBENZENE	95		5.6
95-63-6	1,2,4-TRIMETHYLBENZENE	U		5.6
135-98-8	SEC-BUTYLBENZENE	100		5.6
541-73-1	1,3 DICHLOROBENZENE	U		5.6
99-87-6	ISOPROPYLTOLUENE	270		5.6
106-46-7	1,4 DICHLOROBENZENE	U		5.6
104-51-8	n-BUTYLBENZENE	610		5.6
95-50-1	1,2 DICHLOROBENZENE	U		5.6
120-82-1	1,2,4 TRICHLOROBENZENE	62		5.6
87-68-3	HEXACHLOROBUTADIENE	U		5.6
91-20-3	NARHTHALENE	160		5.6

% SOLIDS 90%

MDL = METHOD DETECTION LIMIT
U = UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT WEST DIS.
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 30
DATA FILE : >F9816
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-1
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
62-75-9	N-NITROSODIMETHYLAMINE	U		3700
62-53-3	ANILINE	U		3700
111-44-4	BIS (2-CHLOROETHYL) ETHER	U		3700
541-73-1	1,3-DICHLOROBENZENE	U		3700
106-46-7	1,4-DICHLOROBENZENE	U		3700
95-50-1	1,2-DICHLOROBENZENE	U		3700
100-51-6	BENZYL ALCOHOL	U		3700
108-60-1	2,2'-OXY BIS(1-CHLOROPROPANE)	U		3700
67-72-1	HEXACHLOROETHANE	U		3700
621-64-7	N-NITROSODIPROPYL AMINE	U		3700
98-95-3	NITROBENZENE	U		3700
78-59-1	ISOPHORONE	U		3700
111-91-1	BIS (2-CHLOROETHOXY) METHANE	U		3700
120-82-1	1,2,4-TRICHLOROBENZENE	U		3700
91-20-3	NAPHTHALENE	U		18000
65-85-0	BENZOIC ACID	U		3700
106-47-8	4-CHLOROANILINE	U		3700
87-68-3	HEXACHLOROBUTADIENE	U		3700
91-57-6	2-METHYLNAPHTHALENE	U		3700
77-47-4	HEXACHLOROCYCLOPENTADIENE	U		3700
91-58-7	2-CHLORONAPHTHALENE	U		18000
88-74-4	2-NITROANILINE	U		3700
208-96-8	ACENAPHTHYLENE	U		3700
131-11-3	DIMETHYL PHTHALATE	U		3700
606-20-2	2,6-DINITROTOLUENE	U		3700
83-32-9	ACENAPHTHENE	U		18000
99-09-2	3-NITROANILINE	U		3700
132-64-9	DIBENZOFURAN	U		3700
121-14-2	2,4-DINITROTOLUENE	U		3700
86-73-7	FLUORENE	U		3700
84-66-2	DIETHYL PHTHALATE	U		3700

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

TCL/HSL Base/Neutral Extractable Organics - Non-Aqueous Matrix

CLIENT : FENLY & NICOL
SAMPLE ID: ENDPOINT WEST DIS.
PROJECT : NEWSDAY/MELVILLE
SAMPLE VOL. : 3G
DATA FILE : >F9816
EXTRACT/DATE : 01/27/99
NJDEP LAB ID : 12531

LAB SAMPLE ID : L1537-1
DATE SAMPLED: 1/22/99
DATE RECEIVED: 1/26/99
DATE ANALYZED: 02/01/99
DIL. FACT : .003
ANALYST: RB

CAS #	COMPOUND	UG/KG	Q	MDL
7005-72-3	4-CHLOROPHENYL PHENYL ETHER	U		3700
100-01-6	4-NITROANILINE	U		18000
86-30-6	N-NITROSODIPHENYL AMINE	U		3700
101-55-3	4-BROMOPHENYL PHENYL ETHER	U		3700
118-74-1	HEXACHLOROBENZENE	U		3700
85-01-8	PHENANTHRENE	U		3700
120-12-7	ANTHRACENE	U		3700
86-74-8	CARBAZOLE	U		3700
84-74-2	DI-N-BUTYL PHTHALATE	U		3700
206-44-0	FLUORANTHENE	U		3700
92-87-5	BENZIDINE	U		18000
129-00-0	PYRENE	U		3700
85-68-7	BUTYLBENZYL PHTHALATE	U		3700
56-55-3	BENZO (A) ANTHRACENE	U		3700
91-94-1	3,3'-DICHLOROBENZIDINE	U		18000
218-01-9	CHRYSENE	U		3700
117-81-7	BIS (2-ETHYLHEXYL) PHTHALATE	U		3700
117-84-0	DI-N-OCTYL PHTHALATE	U		3700
205-99-2	BENZO (B) FLUORANTHENE	U		3700
207-08-9	BENZO (K) FLUORANTHENE	U		3700
50-32-8	BENZO (A) PYRENE	U		3700
193-39-5	INDENO (1,2,3-CD) PYRENE	U		3700
53-70-3	DIBENZO (A,H) ANTHRACENE	U		3700
191-24-2	BENZO (GHI) PERYLENE	U		3700

QUALIFIERS

J Indicates detected below MDL, Estimated Value
U Indicates compound not detected
B Indicates compound also present in blank
E Exceeds Calibration Range, Estimated Value

ANALab INC.

205 Campus Plaza I, Raritan Center, Edison, New Jersey 08837 (908) 225-4111
ENVIRONMENTAL ANALYTICAL LABORATORY SERVICES FAX (908) 225-4110

CHAIN-OF-CUSTODY RECORD and Work Authorization

LAB SDG NO - (FOR LAB USE ONLY) 21537

Company: Fenley + Nicol
Address: 445 Broad Ave
City: Deer Park
State: New York ZIP: 11729 Phone: 516 586-4400
Project Manager: Stan Sucharski Fax: 516 586-4926
Project name: Navy-Melville Purchase Order No: 1990037

ANALYSIS REQUESTED

PRINT ANALYSIS REQUESTS CLEARLY, LEGIBLY AND COMPLETELY

Page 1 of 1

	SAMPLE DESCRIPTION	TYPE GRAB	TYPE COMP	MATRIX TYPE	DATE SAMPLED	TIME	PRES	NO. CONT	8021	8021 (BV)	REMARKS
1	Endpoint West Disposal		X	S	1/23/99	10:45		2	X	X	2-8oz
2	Endpoint Middle Disposal		X	S	1/23/99	11:15		2	X	X	11
3	Endpoint East Disposal		X	S	1/23/99	11:40		2	X	X	11

FAILURE TO PRINT CLEARLY, LEGIBLY AND COMPLETELY MAY RESULT IN DELAYS. ANY ANALYSIS REQUEST NOT ENTERED COMPLETELY, CLEARLY AND LEGIBLY OR WHICH IS CONFUSING OR AMBIGUOUS MAY RESULT IN DELAYS. SAMPLES CAN NOT BE LOGGED IN AND THE TURNAROUND TIME CLOCK WILL NOT START UNTIL ANY AMBIGUITIES ARE RESOLVED. TO AVOID THIS, PRINT CLEARLY, LEGIBLY AND COMPLETELY.

SAMPLER/SUBMITTER'S STATEMENT: I attest that the proper field sampling procedures were used during the collection of these samples and that the information on the Chain of Custody and the analysis(es) requested are true and correct. Name (print): Signature:

RELINQUISHED BY:	RECEIVED BY:	DATE:	TIME:	RELINQUISHED TO LABORATORY BY:	ACCEPTED FOR LAB BY	DATE	TIME
		1-26-99	1415			1-26-99	1645

Turnaround Time (Faxables)

24Hour____ 5 Day____
48 Hour____ 10 Day____
72 Hour____ 14 Day____

If other than 14 day contact your project manager for authorization number.

Auth No: _____

Laboratory Comments:

Data Deliverables (Standard T.A.T. Hard Copy)

Results only____
Results with QC____
RTD-4____
FTD-2____

If other than standard turnaround time for hard copy, please indicate in client remarks.

Client Remarks:

All Samples Received
Temp 2.7 °C Cool (Yes) No
Samples Intact (Yes) No
Properly Preserved (Yes) No

© 1991 ANALAB Inc.

White: Lab Yellow: Accounting Pink: Customer/Client

Form 0401 Rev. 9/94

FEB. 9.1999 5:11PM ANALAB INC NO.684 P.2/17

TO: Curtis From: Carolyn 2/1-/99

FENLEY & NICOL ENVIRONMENTAL, INC.
WORK ORDERS NEEDED OR INCREASES OF NTE
DATE Feb 9, 99

DATE	WO#	S/S #	ADDRESS	JOB DESCRIPTION	AMOUNT	WORK TYPE
1/11	9679	MIH		Problem with Nozzle Dealer was informed & SAID OK.	125.00	
1/14	9722	MID		V/R 0/0	125.00	
1/29	9595	AOB		Hit pump	400.00	
1/28	9714	MLM		V/R 0/0	200.00	
1/28	9780	JTG		V/R 0/0	200.00	
1/28	9651	LME		VAC motor only	1000.00	
1/27	9588	MQO		V/R 0/0	200.00	
1/29	9738	KYE		Drive-off	200.00	

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☑ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 98-25125


Location	Representatives on site	time in	time out
Name Newsday	DEC Matt Darcangelo	12:40	12:43
Address Pinelawn Rd			
Town Melville			
Phone			
	PRP		

Weather	Temperature	General conditions
humidity	Cold	(Sunny)
(Dry)	Fair	Partly Cloudy
~~Humid~~	(Warm)	Cloudy
Very humid	Hot	Rain / Snow

Date	Time	Inspection Narrative
5/12/98	12:40	onsite
		Drive by to observe location and setup of Diesel Dispensers
	12:43	offsite - Gate Locked no one at check Booth
5/14/98	10:54	Left Message for Tim McGarry

Continued Page ____ Of ____

New York State Department of Environmental Conservation
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
(516) 444-0336
FAX (516) 444-0373



John P. Cahill
Commissioner

May 14, 1999

Newsday
Attn: Tim McGarry
235 Pinelawn Road
Melville, NY 11747

Re: Spill # 98-25125, Pinelawn Road, Melville, NY 11747

Dear Mr. McGarry:

I have reviewed the laboratory data for the soil samples collected after the excavation of soil, which occured during upgrade operations of your fuel dispenser area. The results indicate that several volatile and semi-volatile organic compounds are present above levels listed in STARS Memo #1 for groundwater quality protection. It was also reported that soil contamination was found in the area around the diesel tanks during upgrade operations, however no data from endpoint soil samples has been received by this office.

New York State Department of Environmental Conservation (NYSDEC) is directing you to perform a subsurface investigation in the vacinity of the dispensers and tank area. This investigation should identify the complete horizontal and vertical extent of the contamination. Soil samples should be collected, field screened and certain samples should be selected for laboratory analysis via EPA method 8021 and method 8270 with TCLP extraction. Based on the findings during the subsurface investigation in may be necessary to collect and analyze groundwater samples via EPA methods 8021 and 8270. Please advise me at least two days prior to conducting the investigation so that I may arrange to be present.

If you do not contact this office within ten days of receipt of this letter, this office may proceed with the investigation of the site; and the New York State Department of Law will seek reimbursement and an assessment of penalties from you according to Article 12 of the New York State Navigation Law.


Please contact me at (516) 444-0336 if you have any questions.

Sincerely,

Matthew J. Darcangelo
Environmental Engineer I

cc: file
W. Parish
J. Demauro, Fenly and Nicol

New York State Department of Environmental Conservation
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
(516) 444-0336
FAX (516) 444-0373



John P. Cahill
Commissioner

May 14, 1999

Newsday
Attn: Tim McGarry
235 Pinelawn Road
Melville, NY 11747

Re: Spill # 98-25125, Pinelawn Road, Melville, NY 11747

Dear Mr. McGarry:

I have reviewed the laboratory data for the soil samples collected after the excavation of soil, which occured during upgrade operations of your fuel dispenser area. The results indicate that several volatile and semi-volatile organic compounds are present above levels listed in STARS Memo #1 for groundwater quality protection. It was also reported that soil contamination was found in the area around the diesel tanks during upgrade operations, however no data from endpoint soil samples has been received by this office.

New York State Department of Environmental Conservation (NYSDEC) is directing you to perform a subsurface investigation in the vacinity of the dispensers and tank area. This investigation should identify the complete horizontal and vertical extent of the contamination. Soil samples should be collected, field screened and certain samples should be selected for laboratory analysis via EPA method 8021 and method 8270 with TCLP extraction. Based on the findings during the subsurface investigation in may be necessary to collect and analyze groundwater samples via EPA methods 8021 and 8270. Please advise me at least two days prior to conducting the investigation so that I may arrange to be present.

If you do not contact this office within ten days of receipt of this letter, this office may proceed with the investigation of the site; and the New York State Department of Law will seek reimbursement and an assessment of penalties from you according to Article 12 of the New York State Navigation Law.

Please contact me at (516) 444-0336 if you have any questions.

Sincerely,

Matthew J. Darcangelo
Environmental Engineer I

cc: file
W. Parish
J. Demauro, Fenly and Nicol

Fenley & Nicol Environmental

445 Brook Avenue
Deer Park, New York 11729
(516) 586-4900 • Fax (516) 586-4920

TRANSMITTAL SHEET

Date: 6/23/99

To: Matt Durcanglo

Company: NYSDEC I

FAX #: 444-0373

COMMENTS:

Is there a spill #?
If there is, please let me
know what it is.

FROM:

____ Mostafa El Sehamy,P.G. (ext. 141)
Director, Professional Services

____ Albert Giuliano (ext. 133)
Draftsman

____ Janice Kowalski (ext. 137)
Staff Geologist

____ Dave Lorthioir (ext. 159)
Senior Geologist

____ Brian McCabe (ext. 144)
Senior Geologist

____ Krista Morisen (ext. 102)
Project Geologist

____ Cheryl Neary (ext. 190)
Marketing Representative/Field Coordinator

____ David Oloke (ext. 154)
Staff Geologist

____ Angel Ramirez (ext. 134)
Environmental Scientist/ Project Manager

____ Tara Riley (ext. 162)
Professional Service Coordinator

Total number of pages, including cover sheet 2 X
If you do not receive all pages, please call (516) 586 – 4900

X Mark Robbins (ext. 167)
Senior Geologist

____ Stephanie Salvemini (ext. 191)
Staff Geologist

Confidentiality Note

The documents accompanying this telecopy transmission contain information which is confidential or privileged. The information is intended to be for the use of the individual or entity named on this transmission sheet. If you are not the intended recipient, be aware that any disclosure, copying or distribution or use of the contents of this telecopied information is prohibited.

Fenley & Nicol Environmental

"SOLUTIONS AT WORK"SM

445 Brook Avenue, Deer Park, New York 11729 (516) 586-4900 • NYC (718) 204-4993 FAX (516) 586-4920

To: Matt Darcangelo

From: Mark E. Robbins

Date: June 23, 1999

Re: Newsday, 235 Pinelawn Road, Melville, NY


Matt:

As requested, enclosed please find a diagram depicting the location of the proposed locations of the soil borings at the above-referenced site. The borings will be installed in the vicinity of the fuel dispensing island area. The borings are scheduled to be installed on Wednesday, June 30, 1999, commencing at approximately 8:00 a.m.

An estimated four (4) soil borings will be installed. Split spoon samples will be obtained in each boring at five (5) foot intervals from ground surface until three (3) consecutive "clean" samples are obtained. I will be prepared to obtain soil samples where necessary.

Please call me should you have any questions or comments.

Mark



NEWSDAY, INC. — PINELAWN F
SCDHS FACILITY ENVIRONMENTAL AU

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☑ Field Notes ☐ Phone Conversation ☐ Meeting Notes **Spill No.** 98-25125

Location		Representatives on site	time in	time out
Name	Newsday	DEC Matt Dalcangelo	8:20	10:33
Address	Pinelawn RD	Mark Robbins F+N	—	—
Town	Melville	~~Steve~~		
Phone				
		PRP Steve Cluff 843-8631	—	—

Weather	Temperature	General conditions
humidity	Cold	Sunny
(Dry)	Fair	(Partly Cloudy)
Humid	(Warm)	Cloudy
Very humid	Hot	Rain / Snow

Date	Time	Inspection Narrative
6/~~30~~/98	8:20	Onsite

- F+N getting set to perform borings using drill rig
- First boring location chosen North of Tank pad Between dispensers
- 0-4' yellow orange well sorted medium grain tank sand no odor
- 4-12' yellow orange ~~SILT~~ sand with cobbles no odor
- Split spoons Intervals

Soil Description	PID Reading
10-12' - yellow orange sand + gravel with some cobble	0.0 ppm
14'-16' - white/yellow sand + gravel with cobbles	0.3 ppm
19'-21' white/yellow sand + gravel with cobbles	0.4 ppm
24-26' white/red sand + gravel with cobbles	2.5 ppm
29-31' Same	no PID
34-36' Same	
41.5-43.5 red/yellow mixed gravel no odor wet	0.2 ppm

no standing water in Augers.

To Lab 8021 8270 TCLP ✗


- Tanks are 20,000 gal USTs
- Depth to Bottom 15' 4"
- Marked out boring locations #2 + #3
- Will spoon 14-16', 19-21 and 24'-26'
- If nothing found (ie no odors, staining, high PID sample will be submitted from 14'-16' (tank bottom) and borings discontinued


10:33 offsite

Continued

Page ____ Of ____

98-25125


Newsday Bldg
Waste Water Treatment Facility
Leaching Pools
Fire Suppression Water storage


Asphalt Parking
96'
38'
32'
B2
B1
Manways
Concrete Tank
Fill
Fill
36'
Dispenser Island
Operator Booth
Fill
B3
25'
Asphalt
Fence
Gate
Guard Booth
Landscape + grass
Newsday Private Rd.
To Pinelawn
To Deer Park Rd
N
MSD 6/26/98

NYSDEC Region 1, SUNY, Bldg. 40, Stony Brook, NY 11790-2356

☐ Field Notes ☑ Phone Conversation ☐ Meeting Notes **Spill No.** 98-25125

Location	Representatives on site	time in	time out
Name Newsday	DEC Matt Darcangelo		
Address Pinelawn Rd			
Town Melville			
Phone			
Weather / Temperature / General conditions	PRP		
humidity / Cold / Sunny			
Dry / Fair / Partly Cloudy			
Humid / Warm / Cloudy			
Very humid / Hot / Rain / Snow			

Date	Time	Inspection Narrative
7/1/98	9:00	Telcon with Mark Robbins e F+N - Borings #2 and #3 Finished 6/30 - Similar soil characteristics and PID readings as Boring #1 - Both Borings 14'-16' interval to lab for 8021 + 8270 TCLP - Will prepare report and submit.

Continued Page ____ Of ____

Fenley & Nicol Environmental

"SOLUTIONS AT WORK"SM

445 Brook Avenue, Deer Park, New York 11729 (516) 586-4900 • NYC (718) 204-4993 FAX (516) 586-4920

July 19, 1999

Mr. Stephen Cluff
Newsday
235 Pinelawn Road
Melville, New York 11747

RECEIVED
JUL 21 1999
REG 1 - OIL SPILLS

Re: Newsday Facility
235 Pinelawn Road, Melville, New York

Dear Stephen:

Enclosed please find F&N's Subsurface Investigation Report for the above referenced property. This report provides the findings and conclusions of the soil borings installed in the vicinity of the underground storage tanks on June 30, 1999.

If you have any questions or comments, do not hesitate to contact me at extension 167.

Very truly yours,
Fenley and Nicol Environmental, Inc.

Mark E. Robbins
Senior Geologist

MER /tr
Enc.
cc: Mostafa El Sehamy, F&N w/enc.
F&N File No. 9904777 w/enc.
Matt Darcangelo, NYSDEC w/enc.

PEDNEAULT ASSOCIATES, INC.
COMMERCIAL TESTING LABORATORIES
1615 NINTH AVENUE, P.O. BOX 205
BOHEMIA, NEW YORK 11716
PHONE: (516) 467-8477 / FAX: (516) 467-6905

FAX TRANSMITTAL

DATE OF TRANSMISSION: July 15th 1999

NUMBER OF PAGES: 7 (INCLUDING COVER SHEET)

ATTENTION: Matt / NYS DEC I

MESSAGE: Lab Results
Revised Detection Limits

FROM: Stephanie / as per Brian's permission

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-001
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-01 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<1.0	µg/kg
n-Butylbenzene	<1.0	µg/kg
sec-Butylbenzene	<1.0	µg/kg
tert-Butylbenzene	<1.0	µg/kg
Ethylbenzene	<1.0	µg/kg
Isopropylbenzene	<1.0	µg/kg
p-Isopropyltoluene	<1.0	µg/kg
Methyl-tert-butyl ether	<1.0	µg/kg
Napthalene	<1.0	µg/kg
n-Propylbenzene	<1.0	µg/kg
Toluene	<1.0	µg/kg
1,2,4-Trimethylbenzene	<1.0	µg/kg
1,3,5-Trimethylbenzene	<1.0	µg/kg
o-Xylene	<1.0	µg/kg
m,p-Xylene	<1.0	µg/kg
Mix Xylenes	<1.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-002
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-02 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<1.0	µg/kg
n-Butylbenzene	<1.0	µg/kg
sec-Butylbenzene	<1.0	µg/kg
tert-Butylbenzene	<1.0	µg/kg
Ethylbenzene	<1.0	µg/kg
Isopropylbenzene	<1.0	µg/kg
p-Isopropyltoluene	<1.0	µg/kg
Methyl-tert-butyl ether	<1.0	µg/kg
Napthalene	<1.0	µg/kg
n-Propylbenzene	<1.0	µg/kg
Toluene	<1.0	µg/kg
1,2,4-Trimethylbenzene	<1.0	µg/kg
1,3,5-Trimethylbenzene	<1.0	µg/kg
o-Xylene	<1.0	µg/kg
m,p-Xylene	<1.0	µg/kg
Mix Xylenes	<1.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-003
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-03 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<1.0	µg/kg
n-Butylbenzene	<1.0	µg/kg
sec-Butylbenzene	<1.0	µg/kg
tert-Butylbenzene	<1.0	µg/kg
Ethylbenzene	<1.0	µg/kg
Isopropylbenzene	<1.0	µg/kg
p-Isopropyltoluene	<1.0	µg/kg
Methyl-tert-butyl ether	<1.0	µg/kg
Napthalene	<1.0	µg/kg
n-Propylbenzene	<1.0	µg/kg
Toluene	<1.0	µg/kg
1,2,4-Trimethylbenzene	<1.0	µg/kg
1,3,5-Trimethylbenzene	<1.0	µg/kg
o-Xylene	<1.0	µg/kg
m,p-Xylene	<1.0	µg/kg
Mix Xylenes	<1.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-001
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-01 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.01	mg/L
Anthracene	<0.01	mg/L
Benzo(a)anthracene	<0.01	mg/L
Benzo(a)pyrene	<0.01	mg/L
Benzo(b)fluoranthene	<0.01	mg/L
Benzo(g,h,i)perylene	<0.01	mg/L
Benzo(k)fluoranthene	<0.01	mg/L
Chrysene	<0.01	mg/L
Dibenzo(a,h)anthracene	<0.01	mg/L
Fluoranthene	<0.01	mg/L
Fluorene	<0.01	mg/L
Indeno(1,2,3-cd)pyrene	<0.01	mg/L
Naphthalene	<0.01	mg/L
Phenanthrene	<0.01	mg/L
Pyrene	<0.01	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 99070031 **SAMPLE ID#:** 99070031-002
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-02 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.01	mg/L
Anthracene	<0.01	mg/L
Benzo(a)anthracene	<0.01	mg/L
Benzo(a)pyrene	<0.01	mg/L
Benzo(b)fluoranthene	<0.01	mg/L
Benzo(g,h,i)perylene	<0.01	mg/L
Benzo(k)fluoranthene	<0.01	mg/L
Chrysene	<0.01	mg/L
Dibenzo(a,h)anthracene	<0.01	mg/L
Fluoranthene	<0.01	mg/L
Fluorene	<0.01	mg/L
Indeno(1,2,3-cd)pyrene	<0.01	mg/L
Naphthalene	<0.01	mg/L
Phenanthrene	<0.01	mg/L
Pyrene	<0.01	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 99070031 **SAMPLE ID#:** 99070031-003
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-03 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.01	mg/L
Anthracene	<0.01	mg/L
Benzo(a)anthracene	<0.01	mg/L
Benzo(a)pyrene	<0.01	mg/L
Benzo(b)fluoranthene	<0.01	mg/L
Benzo(g,h,i)perylene	<0.01	mg/L
Benzo(k)fluoranthene	<0.01	mg/L
Chrysene	<0.01	mg/L
Dibenzo(a,h)anthracene	<0.01	mg/L
Fluoranthene	<0.01	mg/L
Fluorene	<0.01	mg/L
Indeno(1,2,3-cd)pyrene	<0.01	mg/L
Naphthalene	<0.01	mg/L
Phenanthrene	<0.01	mg/L
Pyrene	<0.01	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

New York State Department of Environmental Conservation
Spill Prevention and Response
Building 40 - SUNY, Stony Brook, New York 11790-2356
(516) 444-0320
FAX (516) 444-0373



John P. Cahill
Commissioner

August 17, 1999

Steve Cluff
Newsday
235 Pinelawn Road
Melville, NY 11747

RE: Spill # 98-25125, Newsady Fueling Facility, Pinelawn Road, Melville, NY 11747

Dear Mr. Cluff:

Based upon a review of the file, site inspections, and the information supplied on your behalf, including laboratory data and disposal documents for contaminated soil, you have completed the cleanup for the above referenced site.

This office has no further requirements for the referenced spill at this time. Should future environmental problems be discovered at this site, this office will require further action at that time. The spill file has been removed from our active spill list.

Please contact me at (516) 444-0336 if you have any questions.

Sincerely,

Matthew Darcangelo
Environmental Engineer I

cc: W. Parish
Mark. Robbins, Fenly and Nicol
File

Fenley & Nicol Environmental

"SOLUTIONS AT WORK"SM

445 Brook Avenue, Deer Park, New York 11729 (516) 586-4900 • NYC (718) 204-4993 FAX (516) 586-4920

RECEIVED
JUL 21 1999
REG 1 - OIL SPILLS

Subsurface Investigation
Newsday Facility
235 Pinelawn Road
Melville, New York

Prepared For:	Newsday 235 Pinelawn Road Melville, New York
Attention:	Mr. Steven Cluff
Prepared By:	Fenley & Nicol Environmental 445 Brook Avenue Deer Park, New York 11729
Project Geologist:	Mark E. Robbins
Date:	July 16, 1999
Job #:	9904447

TABLE OF CONTENTS

		Page Number
1.0	INTRODUCTION	1
2.0	FIELD WORK	1
3.0	SOIL BORINGS	2
4.0	CONCLUSIONS	4
5.0	RECOMMENDATIONS	4

FIGURES

1. Site Plan

TABLES

1. PID Screening Results

APPENDICES

A. Laboratory Results

Fenley & Nicol Environmental Inc.

1.0 INTRODUCTION

Fenley & Nicol Environmental (F&N) has been retained by Newsday to install and sample soil borings at the property located at 235 Pinelawn Road in Melville, New York (herein after referred to as *"the site"*). The site consists of the Newsday facility and is located along the west side of Pinelawn Road. The area surrounding the site is utilized for commercial and industrial purposes. Pinelawn Cemetery is located to the east of the subject site.

The topographic elevation of the site is approximately 90 feet above sea level (USGS 7.5 Minute Topographic Map, Amityville Quadrangle). The depth to ground water beneath the site is estimated to be approximately 42 feet. The regional ground water flow is toward the south-southeast.

The scope of work for the field portion of the assessment consisted of the installation and sampling of soil borings associated with a recent spill. The spill consisted of the identification of petroleum-contaminated soil on top of underground storage tanks during the installation of spill prevention equipment.

2.0 FIELD WORK

The installation of soil borings was performed on June 30, 1999. The fieldwork was performed under the guidance of Mr. Matthew Darcangelo, Case Manager for the NYSDEC. Figure 1 provides a Site Plan indicating the locations of each soil boring. All soil samples were obtained utilizing a hollow stem auger and a split spoon.

Soil boring B-01 was installed immediately to the northeast of the concrete tank pad. Soil samples were collected in boring B-01 at 5-foot intervals from 10 feet to 44 feet. The water table was encountered at approximately 43 feet. Soil boring B-02 was installed to the northwest of the concrete tank pad and soil-boring B-03 was installed to the southeast of the concrete tank pad. Soil samples were collected in borings B-02 and B-03 at 5-foot intervals from 14 feet to 26 feet.

3.0 SOIL BORINGS

The soils encountered during the installation of the borings consisted of a fine to medium, yellow to light brown sand with traces of pebbles, cobbles, and gravel. Each soil sample was inspected for evidence of petroleum contamination. None of the soil samples exhibited visual or olfactory evidence of contamination.

In addition to visual observations, each soil sample was screened in the field for volatile organic compounds (VOCs) utilizing a Photoionization Detector (PID). The PID has a detection limit of 0.1 parts per million (ppm). The results of the field screening are presented in **Table 1**. As Table 1 indicates, trace levels of VOCs were identified in the soil samples from 14 feet to 26 feet in soil boring B-01. No other detectable levels of VOCs were identified in the remaining soil samples. These trace levels can be attributed to background levels and should not be of any concern.

Table 1
PID Screening Results
235 Pinelawn Road, Melville, NY

Boring #	Sampling Depth (feet)	VOC Reading (ppm)
B-01	10 – 12	0.0
	14 – 16	0.3
	19 – 21	0.4
	24 – 26	2.5
	29 – 31	0.0
	34 – 36	0.0
	42 – 44	0.0
B-02	14 – 16	0.2
	19 – 21	0.0
	24 – 26	0.0
B-03	14 – 16	0.0
	19 – 21	0.0
	24 – 26	0.0

The 14 to 16 foot sample from each boring was transmitted to an outside laboratory and analyzed for VOCs in accordance with NYSDEC STARS 8021 and semi-

VOCs in accordance with NYSDEC STARS TCLP 8270. The results of these analyses indicate that no detectable levels of VOCs or semi-VOCs were identified in any soil sample. The laboratory reports from the analyses are provided as **Appendix A**.


The results of the soil borings indicate that the soils in the immediate vicinity of the underground storage tanks has not been impacted by the petroleum-contaminated soil identified on top of the underground storage tanks. Furthermore, the results of soil boring B-01 indicate that the petroleum-contaminated soil has not impacted the ground water beneath the site.

4.0 CONCLUSIONS

The results of the soil borings indicate that the petroleum contamination identified during the construction work associated with the underground storage tanks has not migrated to the soils in the immediate vicinity of the underground storage tanks or to the ground water beneath the site.

5.0 RECOMMENDATIONS

F&N recommends that the spill file be closed pertaining to the site and documentation to that effect be provided to site representatives. At the time that additional construction work is performed associated with the underground storage tanks, a new spill file should be opened and the petroleum-contaminated soil should be excavated and disposed of at that time.



B-01 SOIL BORING

UNDERGROUND TANK MANHOLE

Fanley & Nicol
Professional Services Division
445 BROOK AVENUE, DEER PARK,
NEW YORK 11729 (516)586-4900

SCALE: 1"=15'	GEOLOGIST: M.R.	JOB # 9904447
DATE: 7/99	DRAWN BY: A.G.	CUSTOMER: PRIVATE

SITE PLAN

NEWSDAY
MELVILLE, NEW YORK

Appendix A
Laboratory Reports

Fenley & Nicol Environmental Inc.

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-001
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-01 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-002
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-02 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 99070031 **SAMPLE ID#:** 99070031-003
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-03 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/13/99	7/13/99

TEST: STARS VOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8021/8260

PARAMETER	RESULT	UNITS
Benzene	<5.0	µg/kg
n-Butylbenzene	<5.0	µg/kg
sec-Butylbenzene	<5.0	µg/kg
tert-Butylbenzene	<5.0	µg/kg
Ethylbenzene	<5.0	µg/kg
Isopropylbenzene	<5.0	µg/kg
p-Isopropyltoluene	<5.0	µg/kg
Methyl-tert-butyl ether	<5.0	µg/kg
Napthalene	<5.0	µg/kg
n-Propylbenzene	<5.0	µg/kg
Toluene	<5.0	µg/kg
1,2,4-Trimethylbenzene	<5.0	µg/kg
1,3,5-Trimethylbenzene	<5.0	µg/kg
o-Xylene	<5.0	µg/kg
m,p-Xylene	<5.0	µg/kg
Mix Xylenes	<5.0	µg/kg

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-001
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-01 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.05	mg/L
Anthracene	<0.05	mg/L
Benzo(a)anthracene	<0.05	mg/L
Benzo(a)pyrene	<0.05	mg/L
Benzo(b)fluoranthene	<0.05	mg/L
Benzo(g,h,i)perylene	<0.05	mg/L
Benzo(k)fluoranthene	<0.05	mg/L
Chrysene	<0.05	mg/L
Dibenzo(a,h)anthracene	<0.05	mg/L
Fluoranthene	<0.05	mg/L
Fluorene	<0.05	mg/L
Indeno(1,2,3-cd)pyrene	<0.05	mg/L
Naphthalene	<0.05	mg/L
Phenanthrene	<0.05	mg/L
Pyrene	<0.05	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716

LAB#: 99070031 **SAMPLE ID#:** 99070031-002
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-02 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.05	mg/L
Anthracene	<0.05	mg/L
Benzo(a)anthracene	<0.05	mg/L
Benzo(a)pyrene	<0.05	mg/L
Benzo(b)fluoranthene	<0.05	mg/L
Benzo(g,h,i)perylene	<0.05	mg/L
Benzo(k)fluoranthene	<0.05	mg/L
Chrysene	<0.05	mg/L
Dibenzo(a,h)anthracene	<0.05	mg/L
Fluoranthene	<0.05	mg/L
Fluorene	<0.05	mg/L
Indeno(1,2,3-cd)pyrene	<0.05	mg/L
Naphthalene	<0.05	mg/L
Phenanthrene	<0.05	mg/L
Pyrene	<0.05	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

PEDNEAULT ASSOCIATES, INC.

1615 NINTH AVENUE, BOX 205
BOHEMIA, N.Y. 11716
Phone: (516) 467-8477 Fax: (516) 467-6905

AMERICA'S TEST LAB!

Prepared Exclusively For:
NEWSDAY
235 PINELAWN ROAD
MELVILLE , NY 11747-0000
(516)843-2020

PEDNEAULT ASSOCIATES, INC.
1615 NINTH AVENUE, BOX 205, BOHEMIA, N.Y. 11716
LAB#: 99070031 **SAMPLE ID#:** 99070031-003
PROJECT ID : CONTRACT# 11101-753207-70205
SAMPLE ORIGIN : B-03 14-16 FT
MATRIX: SOLID

COLLECT DATE	DATE RECEIVED	RELEASE DATE	REPORT DATE
6/30/99	7/1/99 6:39:35 PM	7/8/99	7/8/99

TEST: TCLP/STARS-SEMIVOLATILE ORGANIC COMPOUNDS **METHOD:** EPA 8270BN

PARAMETER	RESULT	UNITS
Acenaphthene	<0.05	mg/L
Anthracene	<0.05	mg/L
Benzo(a)anthracene	<0.05	mg/L
Benzo(a)pyrene	<0.05	mg/L
Benzo(b)fluoranthene	<0.05	mg/L
Benzo(g,h,i)perylene	<0.05	mg/L
Benzo(k)fluoranthene	<0.05	mg/L
Chrysene	<0.05	mg/L
Dibenzo(a,h)anthracene	<0.05	mg/L
Fluoranthene	<0.05	mg/L
Fluorene	<0.05	mg/L
Indeno(1,2,3-cd)pyrene	<0.05	mg/L
Naphthalene	<0.05	mg/L
Phenanthrene	<0.05	mg/L
Pyrene	<0.05	mg/L

John Pedneault
Lab Director

NYS ELAP #10224

SAMPLE COLLECTION / CHAIN OF CUSTODY RECORD *Entered by*

Pedneault Associates, Inc.
1615 NINTH AVENUE
BOHEMIA, NEW YORK 11716
PHONE: (516) 467-0477 / FAX: (516) 467-6905

CLIENT: Newsday
ADDRESS: 235 Pinelawn Rd
CITY, STATE, ZIP: Melville NY
PHONE / FAX: (516) 843-3631 Stephen Cluff

PAGE ___ OF ___
P.O. #:
JOB #:

PROJECT NAME AND/OR LOCATION:

Contract # : 1101-753207-70205

LAB NUMBER: 9907003/

#	DATE	TIME	SAMPLE COMP	SAMPLE GRAB	MATRIX S	MATRIX L	MATRIX G	SAMPLE ORIGIN	SAMPLE CONTAINERS	ANALYSIS	#
1	6/32			✓	✓			B-01 14-16 ft	8 oz	STARS 8021 Totals	1
2	6/32			✓	✓			B-02 14-16 ft	8 oz	"	2
3	6/30			✓	✓			B-03 14-16 ft	8 oz	STARS 8270 TCLP	3
4											4
5											5
6											6
7											7
8											8
9											9
10											10

SAMPLED BY: M. Lobbins

SPECIAL INSTRUCTIONS: Copy to Fenley + Nicol - Mark Robbins

RELINQUISHED BY: C. Neary
DATE: 7/1/99 TIME: 5:15pm

RECEIVED BY:
DATE: TIME:

RECEIVED AT LAB BY: C. Wright
DATE: 7-1-99 TIME: 5:15

REMARKS:

SHIPPING CONTAINER CONDITION: GOOD ___ FAIR ___ POOR ___

PACKED IN ICE? YES ___ NO ___

NYSDEC SPILL REPORT FORM

DEC REGION: 1 **SPILL NUMBER:** 9825125

SPILL NAME: NEWSDAY PUBLICATIONS **DEC LEAD:** MJDARCAN

SPILL DATE: 11/12/1998 **SPILL TIME:** 12:30 pm

CALL RECEIVED DATE: 11/12/1998 **RECEIVED TIME:** 1:00 pm

SPILL LOCATION

PLACE: NEWSDAY PUBLICATIONS **COUNTY:** Suffolk

STREET: PINELAWN ROAD **TOWN/CITY:** Huntington

COMMUNITY: MELVILLE

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Other **SPILL REPORTED BY:** Other

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

WHILE WORKING ON STATION UPGRADE DIESEL OIL WAS OBSERVED IN SOIL. CONTAMINATED SOIL TO BE EXCAVATED AND PLACED INTO DRUMS. BOTTOM SAMPLES TO BE TAKEN FOR ANALYSIS.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	0 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NEWSDAY PUBLICATIONS	235 PINELAWN ROAD MELVILLE NY 11747-	TIM MCGARRY (516) 843-5437

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DARCANGELO 98-144"
NO FURTHER ACTION AT THIS TIME. CONT SOIL BELOW DISPENSER AND ABOVE TANK UNABLE TO EXCAVATE AL
CONT SOIL BORINGS AROUND PERIMETER TANK AREA DID NOT IDENTIFY ANY SOIL CONTAMINATION, VISUAL AN
OF FACTORY OBSERVATIONS OF GW DID NOT IDENTIFY ANY CONAMINATION, DTW 41'

PIN **T & A** **COST CENTER**

CLASS: C3 **CLOSE DATE:** 08/17/1999 **MEETS STANDARDS:** True

APPENDIX C:

CITY DIRECTORIES

Newsday
235 Pinelawn Road
Melville, NY 11747

Inquiry Number: 5337044.5
June 21, 2018

The EDR-City Directory Image Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2014	☑	☐	EDR Digital Archive
2010	☑	☐	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1987	☑	☐	Cole Criss-Cross Directory
1982	☑	☐	Cole Criss-Cross Directory
1977	☑	☐	Cole Criss-Cross Directory
1972	☑	☐	Cole Criss-Cross Directory

FINDINGS

TARGET PROPERTY STREET

235 Pinelawn Road
Melville, NY 11747

Year	*CD Image*	*Source*
PINELAWN RD		
2014	pg A1	EDR Digital Archive
2010	pg A2	EDR Digital Archive
2005	pg A3	EDR Digital Archive
2000	pg A4	EDR Digital Archive
1995	pg A5	EDR Digital Archive
1992	pg A6	EDR Digital Archive
1987	pg A7	Cole Criss-Cross Directory
1982	pg A8	Cole Criss-Cross Directory
1977	pg A9	Cole Criss-Cross Directory
1972	pg A10	Cole Criss-Cross Directory

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 2014

235	DISTINCTION MAGAZINE INC
	NEWSDAY LLC
	STAR COMMUNITY PUBG GROUP LLC
255	CLARE ROSE INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 2010

235	DISTINCTION MAGAZINE INC
	LONG ISLAND PARENTS & CHILDREN
	NEWSDAY COMMUNITY SERVICE FUND
	NEWSDAY EMPLYEE RCREATION FUND
	NEWSDAY LLC
	STAR COMMUNITY PUBG GROUP LLC
	TRIBUNE NM INC
255	CLARE ROSE INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 2005

235	DISTINCTION MAGAZINE INC
	LONG ISLAND PARENTS & CHILDREN
	NEW YORK CITY OF
	NEWSDAY COMMUNITY SERVICE FUND
	NEWSDAY INC
	STAR COMMUNITY PUBLISHING GROU
	THIS WEEK/PENNYSAVER
255	CLARE ROSE OF NASSAU INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 2000

235 CORPORATE TRAVEL CONSULTANTS
DISTINCTION MAGAZINE INC
DISTRIBUTION SYSTEMS OF AMER
NEWSDAY COMMUNITY SERVICE FUND
NEWSDAY INC
THIS WEEK/PENNYSAVER

255 CLARE ROSE OF NASSAU INC
DEE GEE EXPRESS INC
NEWS AMERICA PUBLICATIONS INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 1995

235	CORPORATE TRAVEL CONSULTANTS
	DISTRIBUTION SYSTEMS OF AMER
	NEWSDAY COMMUNITY SERVICE FUND
	NEWSDAY INC
	TIMES MIRROR COMPANY THE
255	CLARE ROSE OF NASSAU INC
	TV GUIDE


Target Street	Cross Street	Source
✓	-	EDR Digital Archive

PINELAWN RD 1992

235 NEWSDAY INC
255 TV GUIDE

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

PINELAWN RD 1987



PINELAWN RD

				11747
35	★	A J Savasta Inc	.82	694-1330
	★	Standard Register	.81	752-1844
	★	US Sml Bus Admnstr	.81	454-0750
41	★	Eltrcn 25 Fd CD Un	.77	420-8094
50	★	McGovern Sod Farms		249-3610
77	★	Salad Barn	.81	752-8007
86		Ronald Kolbe	.84	420-0152
105			NP	
130	★	John Gozo Jr	.79	752-8946
	★	J Gozo Jr Tennis	.82	420-0700
		George E Hoffman	.86	752-0342
	★	Pinelwn Suply Co	.84	752-8946
133			NP	
135	★	Charles Schwab&Co	¤	694-1660
	★	Chase Manhtn Bank	.86	753-9600
	★	Greenway Plaza Ofc	¤	249-1080
	★	Metrpltn Lif Brkr	¤	752-1305
	★	Nrthrn Telecm Inc	-	694-8070
	★	R K&L Enterprises	¤	756-0300
	★	C Schwab&Co Inc	¤	694-1660
		Samuel Walton	¤	752-1120
146			NP	
235	★	Newsday Inc	.79	736-0800
	★	Newsday Inc	.79	454-3000
	★	Newsday Inc	.79	360-0647
	★	Newsday Inc	.79	454-2470
	★	Newsday Inc	.79	454-2600
	★	Newsday Inc	.79	454-2500
	★	Newsday Inc	.79	454-2629
	★	Newsday Inc	.79	454-2565
	★	Newsday Inc	.79	454-2550
	★	Newsday Inc	.79	454-2000
	★	Newsday Inc	.79	360-0888
	★	Newsday Inc	.79	454-2121
	★	Newsday Inc	.79	454-2150
	★	Newsday Inc	.79	454-2710
	★	Newsday Inc	.79	454-2700
	★	Newsday Inc	.79	454-2785
	★	Newsday Inc	.79	454-2775
	★	Newsday Inc	.79	454-2950
	★	Newsday Inc	.79	454-2900
	★	Newsday Inc	.83	454-2120
	★	Newsday Inc		454-2000
	★	Newsday Inc	.83	454-2030
	★	Newsday Inc	.83	454-2020
255	★	Cable News	.79	752-7135
	★	Imperial News Co	.77	226-9039
	★	Imperial News Co	.78	752-9330
	★	NAPA Imports	.73	293-0590
	★	Select Magazine	.79	752-9749
	★	Warner Publisher	¤	752-7517
NO	# ★	HHH Racquet Club	.73	427-4343
NO	# ★	Half Hollow Racqut	.73	420-1310
NO	# ★	Half Hlw Hls Racqt	.73	531-8032
NO	# ★	Internatl Brothrhd		694-0200
NO	#	Alfred E Moore	.84	249-9386
NO	#	Richard Newton	.74	423-8897
NO	# ★	Pinelawn Constr	.85	752-8571
NO	# ★	Pinelawn Mmrl Prk	.85	249-8075
NO	# ★	Wellwd Cemtry Assn	.82	694-8444

11 RESIDENCE 75 BUSINESS

PINELAWN RD 11789

RR 3 Sound Bch P O

1- END CT1583 05 $D A10

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

PINELAWN RD 1982



PINE LAWN RD 11747
Melville
Huntington Sta P O
1- END TZ112201 SA..C 6
151520
2 Mrs Norma Stallard 67 249-5798
25 Henry Klein 77 249-4830
26 F H Schmitt Jr 70 423-5693
35★Glowill Corp .....¤ 249-8543
★Lcs Assocs Inc .....¤ 694-7400
★Mass Mutual Life .....- 249-5588
★Ring Commtns Inc .....¤ 293-6700
★Ring Commtns Inc .....¤ 293-6705
41★Eltrcn 25 Fd Cd Un 420-8094
50★McGovern Sod Farms ... 249-3610
Gasper V Messina .....¤ 694-2840
★VIP Messenger Sv .....¤ 752-7788
77 Joseph Kowalski Jr 249-5359
★Manetto Vy Sod Frm ... 249-5359
105 .....NP
130★John Gozo Jr 752-8946
Albert P Herget .....¤ 454-7652
Albert Petrucci .....¤ 454-7652
G Wells 79 249-7495
146 E Reckner 69 249-8053
225★Imperial News Co 752-9330
235★Newsday Inc 454-3000
★Newsday Inc E Suff 736-0800
★Newsday Inc 454-2470
★Newsday Incorportd 360-0647
★Newsday Inc ..... 454-2600 P
★Newsday Inc 454-2500
★Newsday Inc 454-2550
★Newsday Inc 454-2565
★Newsday Inc 454-2000
★Newsday Incorportd 360-3434
★Newsday Inc 454-2150
★Newsday Inc 454-2121
★Newsday Incorportd 360-0888
★Newsday Inc 454-2700
★Newsday Inc 454-2710
★Newsday Inc 454-2785
★Newsday Inc 454-2775
★Newsday Inc 454-2309
★Newsday Inc 454-2950
★Newsday Inc 454-2900
★Newsday Inc 454-2100
★Newsday Inc 454-2030
★Newsday Inc 454-2020
255★Cable News 752-7135
★Imperial News Co 226-9039
★NAPA Imports 293-0590
★Select Magazine 752-9749
No # Anthony Donatello 71 249-8150
No #★Half Hollow Hl Clb 427-4343
No #★Half Hlw Hls Club 249-8032
No #★Internatl Brothrhd 694-0200
No # Richard Newton 423-8897
12 Residence 41 Business

PINELAWN RD 11789

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

PINELAWN RD 1977

PINE LAWN RD 11746

Melville

Huntington Sta P O

1 - END TZ 112201 $A..C 6

144370

2 Mrs Norma Stallard..... 249-5798

25 Henry Klein..... □ 423-3582

26 F H Schmitt Jr..... 0 423-5693

41 ★ Eltrcn 25 Fd Cd Un.. □ 420-8094

50 ★ McGovern Sod Farms. 249-3610

77 Joseph Kowalski Jr..... CH9-5359

★ Manetto Vy Sod Frm. CH9-5359

105 ..... NP

125 ★ Hydrosystems Inc.... □ 293-8116

130 Ward Reilly..... 6 752-0032

146 E Reckner..... 9 CH9-8053

255 ★ Imperial News Co.... □ 249-8130

★ NAPA Imports..... 293-0590

No # Anthony Donatello..... 1 CH9-8150

No # ★ Half Hollow Hl Clb.... 427-4343

No # ★ Half Hlw Hls Club..... 249-8032

No # ★ Internatl Brothrhd..... 694-0200

No # Richard Newton..... HA3-8897


No # ★ Pinelawn Meml Pk... □ 249-6100

9 RESIDENCE 10 BUSINESS

PINELAWN RD 11789

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

PINELAWN RD 1972



```
PINELAWN AVE                                11798
WYANDANCH P O
NO  #*BAB SEWAGE DISPSAL                    6437910
                                  1 BUSINESS

PINE LAWN RD                                11746
MELVILLE
HUNTINGTON STA P O
...    1-  END T 112201                     $A..C 6
   2 MRS NORMA STALLARD
                                  7         2495798
  25 HENRY KLEIN                            4233582
  26 F H SCHMITT JR                0        4235693
  77*MANETTO VLY SD FRM                     CH95359
 105 STEVE RYPKA                   0        6946076
 130 HERMAN HEINLEIN               9        2495615
 146 E RECKNER                     9        CH98053
 255*BRITANNIC&ERPN AUTO                    ¤2931400
     *UNEX PRODS CORP                       ¤2931400
NO  #  EUGENE CARR                          2497225
NO  #  ANTHONY DONATELLO1                   CH98150
NO  #*INTERNATL BROTHRHD                    6940200
NO  #*INTRNTL BRTHHD ELC                    2663444
NO  #  JOSPEH KOWALSKI JR                   CH95359
NO  #  M MALLOY                             2493519
NO  #*MCGOVERN SOD FARMS                    2493610
NO  #*MIRROR ROOFINGS                       2498035
NO  #  RICHARD NEWTON                       HA38897
   11 RESIDENCE                  7 BUSINESS

PINELAWN RD                                 11789
SOUND BEACH P O
```

APPENDIX D:

AERIAL PHOTOGRAPHS

Newsday

235 Pinelawn Road

Melville, NY 11747

Inquiry Number: 5337044.8

June 19, 2018

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

06/19/18

Site Name:

Newsday
235 Pinelawn Road
Melville, NY 11747
EDR Inquiry # 5337044.8

Client Name:

The Vertex Companies, Inc.
400 Libbey Parkway
Weymouth, MA 02189-0000
Contact: Stephen Mccarthy

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2008	1"=500'	Flight Year: 2008	USDA/NAIP
1994	1"=500'	Acquisition Date: April 08, 1994	USGS/DOQQ
1985	1"=500'	Flight Date: March 16, 1985	USGS
1980	1"=500'	Flight Date: September 08, 1980	USDA
1976	1"=500'	Flight Date: April 06, 1976	Aero
1970	1"=500'	Flight Date: May 30, 1970	USDA
1966	1"=500'	Flight Date: March 29, 1966	USGS
1962	1"=500'	Flight Date: March 18, 1962	EDR Proprietary Aerial Viewpoint
1957	1"=500'	Flight Date: March 24, 1957	Jack
1953	1"=500'	Flight Date: December 02, 1953	USGS
1947	1"=500'	Flight Date: October 20, 1947	USDA
1938	1"=500'	Flight Date: July 13, 1938	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 5337044.8

YEAR: 2015

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 2011

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 2008

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1994

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1985

= 500'

N

EDR


INQUIRY #: 5337044.8
YEAR: 1980
= 500'
N
EDR



INQUIRY #: 5337044.8

YEAR: 1976

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1970

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1966

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1962

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1957

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1953

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1947

= 500'

N

EDR



INQUIRY #: 5337044.8

YEAR: 1938

= 500'

N

EDR

APPENDIX E:

TOPOGRAPHIC MAPS

Newsday
235 Pinelawn Road
Melville, NY 11747

Inquiry Number: 5337044.4
June 19, 2018

EDR Historical Topo Map Report
with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

06/19/18

Site Name:

Newsday
235 Pinelawn Road
Melville, NY 11747
EDR Inquiry # 5337044.4

Client Name:

The Vertex Companies, Inc.
400 Libbey Parkway
Weymouth, MA 02189-0000
Contact: Stephen Mccarthy

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by The Vertex Companies, Inc. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: Newsday

Coordinates:

Latitude:	40.763451 40° 45' 48" North
Longitude:	-73.406648 -73° 24' 24" West
UTM Zone:	Zone 18 North
UTM X Meters:	634483.87
UTM Y Meters:	4513719.55
Elevation:	105.00' above sea level

Maps Provided:

2013
1979
1967, 1969
1954
1947
1942
1904
1903
1901

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2013 Source Sheets



Huntington
2013
7.5-minute, 24000



Amityville
2013
7.5-minute, 24000

1979 Source Sheets




Huntington
1979
7.5-minute, 24000
Aerial Photo Revised 1977



Amityville
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1967, 1969 Source Sheets



Huntington
1967
7.5-minute, 24000
Aerial Photo Revised 1940



Amityville
1969
7.5-minute, 24000
Aerial Photo Revised 1966

1954 Source Sheets



Amityville
1954
7.5-minute, 24000
Aerial Photo Revised 1940



Huntington
1954
7.5-minute, 24000
Aerial Photo Revised 1940

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1947 Source Sheets



Huntington
1947
7.5-minute, 24000
Aerial Photo Revised 1940



Amityville
1947
7.5-minute, 24000
Aerial Photo Revised 1940

1942 Source Sheets



Islip
1942
30-minute, 125000

1904 Source Sheets



Islip
1904
30-minute, 125000

1903 Source Sheets



Babylon
1903
15-minute, 62500



Northport
1903
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1901 Source Sheets




Northport
1901
15-minute, 62500



Babylon
1901
15-minute, 62500

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Huntington, 2013, 7.5-minute
S, Amityville, 2013, 7.5-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N

Historical Topo Map

1979



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Huntington, 1979, 7.5-minute
S, Amityville, 1979, 7.5-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Huntington, 1967, 7.5-minute
S, Amityville, 1969, 7.5-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N

Historical Topo Map

1954



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Huntington, 1954, 7.5-minute
S, Amityville, 1954, 7.5-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Huntington, 1947, 7.5-minute
S, Amityville, 1947, 7.5-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Islip, 1942, 30-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Islip, 1904, 30-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Northport, 1903, 15-minute
S, Babylon, 1903, 15-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Northport, 1901, 15-minute
S, Babylon, 1901, 15-minute

SITE NAME: Newsday
ADDRESS: 235 Pinelawn Road
Melville, NY 11747
CLIENT: The Vertex Companies, Inc.

N

APPENDIX F:

SANBORN FIRE INSURANCE MAPS

Newsday

235 Pinelawn Road

Melville, NY 11747

Inquiry Number: 5337044.3

June 19, 2018

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

06/19/18

Site Name:

Newsday
235 Pinelawn Road
Melville, NY 11747
EDR Inquiry # 5337044.3

Client Name:

The Vertex Companies, Inc.
400 Libbey Parkway
Weymouth, MA 02189-0000
Contact: Stephen Mccarthy

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by The Vertex Companies, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 04B2-4B46-8081

PO # NA

Project Newsday

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 04B2-4B46-8081

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

The Vertex Companies, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

APPENDIX G:

REGULATORY DATABASE REPORT

Newsday
235 Pinelawn Road
Melville, NY 11747

Inquiry Number: 5337044.2s
June 19, 2018

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	635
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

235 PINELAWN ROAD
MELVILLE, NY 11747

COORDINATES

Latitude (North):	40.7634510 - 40° 45' 48.42''
Longitude (West):	73.4066480 - 73° 24' 23.93''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	634487.5
UTM Y (Meters):	4513508.0
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940609 HUNTINGTON, NY
Version Date:	2013
South Map:	5940593 AMITYVILLE, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	NEWSDAY INC	235 PINELAWN RD	NY UST		TP
A2	NEWSDAY LLC	235 PINELAWN RD	NY UST		TP
A3	NEWSDAY LLC	235 PINELAWN RD	NY AST		TP
A4	NEWSDAY	235 PINELAWN ROAD	NY Spills		TP
A5	NALCO CHEMICAL	235 PINELAWN RD - BO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST		TP
A6	NEWSDAY INC	235 PINELAWN RD	NY AST		TP
A7	NEWSDAY INC	235 PINELAWN ROAD	NY Spills, NY MANIFEST		TP
A8	NEWSDAY INC	235 PINELAWN ROAD	SEMS-ARCHIVE, RCRA-LQG, NY LTANKS, NY Spills,...		TP
B9	TRIBUNE COMPANY	25 DESHON DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	77, 0.015, WNW
B10	NEWSDAY	25 DESHON DR	NY AST	Higher	77, 0.015, WNW
B11	NEWSDAY	25 DESHON DR	NY UST	Higher	77, 0.015, WNW
B12	J.M ALBRIZZIO	25 DESCHON DRIVE	NY Spills	Higher	77, 0.015, WNW
B13	NEWSDAY	25 DESHON DRIVE	NY Spills	Higher	77, 0.015, WNW
B14	TRIBUNE LLC	25 DESHON DR	NY AST	Higher	77, 0.015, WNW
B15	TRIBUNE LLC	25 DESHON DR	NY UST	Higher	77, 0.015, WNW
C16	EASTERN ATHLETIC	100 RULAND RD	NY UST	Lower	187, 0.035, NNE
C17	EASTERN ATHLETIC CLU	100 RULAND ROAD	NY Spills	Lower	187, 0.035, NNE
D18	BUSINESS	255 PINELAWN ROAD	NY Spills	Lower	273, 0.052, SE
D19	IMPERIAL NEWS CO	255 PINELAWN ROAD	NY Spills	Lower	273, 0.052, SE
D20	CLARE ROSE	255 PINELAWN RD/MARC	NY Spills	Lower	273, 0.052, SE
D21	CLARE ROSE	255 CNTY RD 3 PINELA	NY UST, NY AST	Lower	273, 0.052, SE
D22	CLARE ROSE INC	255 PINELAWN RD	NY AST	Lower	273, 0.052, SE
D23	IMPERIAL NEWS	255 PINELAWN RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	273, 0.052, SE
D24	CLARE ROSE	255 PINE LAWN ROAD	NY Spills	Lower	273, 0.052, SE
D25	CLARE ROSE INC	255 PINELAWN RD	NY UST	Lower	273, 0.052, SE
26	PATTERSON BUILDING	25 DESHON DR/MARCUS	NY Spills	Higher	375, 0.071, WSW
C27	UNKNOWN	PINE LAWN & RULAN RO	NY Spills	Lower	383, 0.073, NNE
C28	UNKNOWN	PINELAWN ROAD/RULAND	NY Spills	Lower	383, 0.073, NNE
E29	LINOTYPE-HELL CO	80 RULAND RD	NY AST	Higher	440, 0.083, WNW
E30	HEIDELBERG PUBLISHIN	80 RULAND RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	440, 0.083, WNW
F31	WOODBOURNE CULTURAL	301 COLONIAL SPRING	NY UST, NY AST	Lower	441, 0.084, NNE
F32	WOODBOURNE CULTURAL	301 COLONIAL SPRING	NY AST	Lower	441, 0.084, NNE
F33	WOODBOURNE CULTURAL	301 COLONIAL SPRINGS	NY Spills	Lower	441, 0.084, NNE
E34	OTTO KEIL FLORIST	107 RULAND RD	NY AST	Higher	551, 0.104, WNW
G35	MRP FAMILY HOLDINGS	101 MARCUS DR	NY UST	Lower	553, 0.105, South
G36	PERGAMENT HOME CENTE	101 MARCUS DRIVE	NY Spills, NY MANIFEST	Lower	553, 0.105, South
G37	RACANELLI COMMERCIAL	102 MARCUS DR	NY UST	Lower	634, 0.120, SSE
G38	RACANELLI COMMERCIAL	102 MARCUS DR	NY AST	Lower	634, 0.120, SSE
G39	DON JAGODA INC	102 MARCUS DR	NY UST	Lower	634, 0.120, SSE

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G40	RACANELLI ASSOCIATES	100 MARCUS DRIVE	NY LTANKS	Lower	679, 0.129, South
G41	ESPRIT BLDG	100 MARCUS DR	NY UST	Lower	679, 0.129, South
H42	FONAR TRAVEL	102 MARCUS DR	NY UST	Lower	707, 0.134, SSE
I43	HONEYWELL INC	175 PINELAWN RD	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	743, 0.141, North
I44	NEW YORK STATE DRUG	175 PINELAWN RD SUIT	NY MANIFEST	Lower	743, 0.141, North
45	INTERLOGIC INDUSTRIE	85 MARCUS DR	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	750, 0.142, SW
J46	COMAX MANUFACTURING	130 BAYLIS RD	NY AST	Higher	758, 0.144, NNW
J47	COMAX FLAVORS	130 BAYLISS RD	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Higher	758, 0.144, NNW
K48	MEDISYS HEALTH NETWO	80 MARCUS DR	NY UST	Lower	784, 0.148, SSW
K49	GENOVESE DRUG STORES	80 MARCUS DR	NY LTANKS, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	784, 0.148, SSW
H50	M & W RECKSON ASSOCI	110 MARCUS DR	NY UST	Lower	797, 0.151, SSE
H51	FONAR CORP INC	110 MARCUS DR	RCRA NonGen / NLR, FINDS, ECHO, NJ MANIFEST, NY...	Lower	797, 0.151, SSE
L52	RULAND ROAD LLC	95 RULAND RD	NY AST	Lower	917, 0.174, WNW
L53	RULAND ROAD LLC	95 RULAND RD	NY UST	Lower	917, 0.174, WNW
54	CANADA DRY BOTTLING	135 BAYLIS RD	NY LTANKS, NY UST, NY AST	Lower	931, 0.176, NNW
M55	COMMERCIAL	125 BAYLIS ROAD	NY LTANKS, NY Spills	Higher	1062, 0.201, NNW
M56	PARAGON ENTERPRISES	125 BAYLIS RD	NY UST	Higher	1062, 0.201, NNW
57	NY TEL CO	84 DURYEA ROAD	NY LTANKS	Lower	1166, 0.221, NW
N58	ROCHE BIOMEDICAL LAB	170 FINN CT	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1172, 0.222, SSE
N59	ROCHE BIOMEDICAL LAB	170 FINN CT	RCRA NonGen / NLR, NY MANIFEST	Lower	1172, 0.222, SSE
N60	LABORATORY CORP OF A	170 FINN CT	NY UST	Lower	1172, 0.222, SSE
N61	ARTEK	170 FINN CT	NY UST	Lower	1172, 0.222, SSE
62	FALA INC	70 MARCUS DR	NY UST	Lower	1175, 0.223, SSW
63	WALAEL RESIDENCE	95 RULAND PLACE	NY LTANKS	Lower	1201, 0.227, West
N64	MORRIS BROTHERS AUTO	150 FINN COURT	NY Spills, NY MANIFEST	Lower	1213, 0.230, SSE
N65	NATIONAL ENVIRONMENT	150 FINN CT	NY UST	Lower	1213, 0.230, SSE
N66	PRECIPART CORPORATIO	150 FINN CT	NJ MANIFEST	Lower	1213, 0.230, SSE
N67	PRECIPART CORPORATIO	150 FINN CT	RCRA-SQG, FINDS, ECHO, RI MANIFEST, NY MANIFEST	Lower	1213, 0.230, SSE
N68	PRECIPART CORP	150 FINN COURT	PA MANIFEST	Lower	1213, 0.230, SSE
O69	MANUFACTURERS INDEXI	130 FINN CT	RCRA NonGen / NLR, NY MANIFEST	Lower	1218, 0.231, SSE
O70	MIP INC	130 FINN CT	NY AST	Lower	1218, 0.231, SSE
P71	FALA CCG INC	75 MARCUS DR	RCRA-SQG, NY LTANKS, FINDS, ECHO, NY MANIFEST, NJ...	Lower	1221, 0.231, SW
P72	FALA DIRECT MARKETIN	75 MARCUS DR	NY UST	Lower	1221, 0.231, SW
O73	MAYTAG BLDG	100 FINN CT	NY UST	Lower	1222, 0.231, SSE
O74	PRECIPART CORP	100 FINN CT	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	1222, 0.231, SSE
N75	AIRCRAFT PARTS INC	160 FINN COURT	NY AST, RCRA NonGen / NLR, FINDS, ECHO	Lower	1267, 0.240, SSE
N76	AIRCRAFT PARTS CORP	160 FINN CT	NY UST	Lower	1267, 0.240, SSE
N77	AIRCRAFT PARTS INC	160 FINN CT	RCRA-SQG, NY LTANKS, NY MANIFEST, NJ MANIFEST	Lower	1267, 0.240, SSE
N78	ULTIMATE PRECISION M	200 FINN CT	NY AST	Lower	1297, 0.246, SSE

MAPPED SITES SUMMARY

Target Property Address:
235 PINELAWN ROAD
MELVILLE, NY 11747

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
79	NORTHROP GRUMMAN	65 MARCUS DRIVE	NY LTANKS, NY Spills	Lower	1355, 0.257, SW
80	WE'RE ASSOCIATES	100 BAYLIS ROAD	NY LTANKS	Higher	1489, 0.282, NW
Q81	FIRST VEHICLE SERVIC	55 MARCUS DR	NY LTANKS, NY Spills, NY MANIFEST	Lower	1733, 0.328, WSW
82	SPILL NUMBER 9713313	98 REPUBLIC ROAD	NY LTANKS	Lower	1772, 0.336, West
83	KALMAR DESIGNS	485 SMITH STREET	NY LTANKS, NY Spills	Lower	1814, 0.344, South
R84	VENUS SCIENTIFIC INC	399 SMITH ST	NY LTANKS, NY UST, NY AST, RCRA NonGen / NLR,...	Lower	1867, 0.354, SSW
R85	HT STEEL	375 SMITH STREET	NY LTANKS, NY Spills	Lower	1894, 0.359, SSW
86	MINMILT REALTY (HYGR	540 SMITH STREET	NY SHWS, NY VCP, NY VAPOR REOPENED	Lower	1930, 0.366, South
Q87	EAGLE FUEL TRANSPORT	50 REPUBLIC ROAD	NY LTANKS, NY Spills	Lower	1947, 0.369, SW
88	STELLAE INTERNATIONA	333 SMITH ST	NY ENG CONTROLS, NY INST CONTROL, NY VCP, RCRA...	Lower	2061, 0.390, SSW
89	WERE ASSOCIATES	80 BAYLIS ROAD	NY LTANKS	Higher	2070, 0.392, NW
90	HENRY SCHEIN CO	135 DURYEA ROAD	NY LTANKS, NY Spills	Lower	2247, 0.426, WNW
91	ESTEE LAUDER INC RES	125 PINELAWN RD	RCRA-SQG, NY LTANKS, NY UST, NY Spills, NJ...	Lower	2296, 0.435, North
92	CANTOR BROTHERS	50 ENGINEERS LANE	NY SHWS, NY VCP, NY Spills, NY VAPOR REOPENED	Lower	2452, 0.464, South
93	FORMERLY EMBASSY IND	300 SMITH ST	NY LTANKS, NY AST, NY Spills, RCRA NonGen / NLR,...	Lower	2539, 0.481, SSW
S94	ASTRO ELECTROPLATING	170 CENTRAL AVENUE	NY SHWS, NY Spills	Lower	3168, 0.600, South
S95	TRONIC PLATING CO.,	168 CENTRAL AVENUE	Delisted NPL, SEMS, CORRACTS, US ENG CONTROLS,...	Lower	3211, 0.608, South
S96	UNKNOWN	168 CENTRAL AVE	NY DEL SHWS, NY Spills	Lower	3211, 0.608, South
97	MCGOVERN SOD FARM	PINELAWN ROAD & OLD	NY SHWS	Higher	3250, 0.616, North
98	I.W. INDUSTRIES, INC	35 MELVILLE PARK ROA	NY SHWS, NY LTANKS, NY ENG CONTROLS, NY INST...	Higher	4011, 0.760, NNW
99	25 MELVILLE PARK ROA	25 MELVILLE PARK ROA	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY VCP,...	Higher	4181, 0.792, NNW
T100	CIRCUITRON CORP.	82 MILBAR BOULEVARD	NPL, SEMS, US ENG CONTROLS, LIENS 2, RCRA NonGen /...	Lower	5111, 0.968, SW
T101	UNITED STATES DEPT O	PROTECTION-SITE:82 M	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, RCRA...	Lower	5111, 0.968, SW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
NEWSDAY INC 235 PINELAWN RD MELVILLE, NY 11747	NY UST Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7934 Facility ID: 7934	N/A
NEWSDAY LLC 235 PINELAWN RD MELVILLE, NY 11747	NY UST Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 02037 Status: ACTIVE Facility ID: 02037	N/A
NEWSDAY LLC 235 PINELAWN RD MELVILLE, NY 11747	NY AST Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 02037 Status: ACTIVE Facility Id: 02037	N/A
NEWSDAY 235 PINELAWN ROAD MELVILLE, NY	NY Spills Date Closed: 2015-12-09 Spill Number: 1508951 Site ID: 517549	N/A
NALCO CHEMICAL 235 PINELAWN RD - BO MELVILLE, NY 11747	RCRA NonGen / NLR EPA ID:: NYR000024620 FINDS Registry ID:: 110004525443 ECHO Registry ID: 110004525443 NY MANIFEST EPA ID: NYR000024620	NYR000024620
NEWSDAY INC 235 PINELAWN RD MELVILLE, NY 11747	NY AST Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 7934 Facility Id: 7934	N/A
NEWSDAY INC 235 PINELAWN ROAD MELVILLE LONG ISLAND, NY 11747	NY Spills	N/A

Date Closed: 2017-11-09
Date Closed: 2017-07-03
Spill Number: 1606790
Spill Number: 1703192
Site ID: 533430
Site ID: 554358

NY MANIFEST
EPA ID: NYD052782497

NEWSDAY INC
235 PINELAWN ROAD
MELVILLE, NY 11747

SEMS-ARCHIVE NYD052782497
Site ID: 0202958
EPA Id: NYD052782497

RCRA-LQG
EPA ID:: NYD052782497

NY LTANKS
Date Closed: 1998-05-27
Date Closed: 2009-12-11
Date Closed: 2014-04-07
Site ID: 276627
Site ID: 276630
Site ID: 465817
Program Number: 9201246
Program Number: 9709711
Program Number: 1203029

NY Spills
Date Closed: 2011-03-30
Date Closed: 2006-03-14
Date Closed: 2000-12-14
Date Closed: 2004-09-16
Date Closed: 2002-08-21
**Additional key fields are available in the Map Findings section*
Spill Number: 1000551
Spill Number: 0507524
Spill Number: 0008603
Spill Number: 0125175
Spill Number: 0203990
**Additional key fields are available in the Map Findings section*
Site ID: 431720
Site ID: 352993
Site ID: 276623
Site ID: 276624
Site ID: 276625
**Additional key fields are available in the Map Findings section*

ICIS
FRS ID:: 110000807761

US AIRS
Database: US AIRS (AFS), Date of Government Version: 10/12/2016
EPA plant ID:: 110000807761

FINDS
Registry ID:: 110000807761

ECHO

EXECUTIVE SUMMARY

Registry ID: 110000807761

NY AIRS
DEC Id: 1472600157

NJ MANIFEST
EPA Id: NYD052782497

NY SPDES
Limit Set Status Flag: A
Permit Number: NY0136751

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF ---------- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF UST ---- Major Oil Storage Facilities Database
NY CBS ---- Chemical Bulk Storage Site Listing
NY MOSF ---- Major Oil Storage Facility Site Listing
NY CBS AST ---- Chemical Bulk Storage Database
NY MOSF AST ---- Major Oil Storage Facilities Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY BROWNFIELDS ---- Brownfields Site List
NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---- Registered Recycling Facility List
NY SWTIRE ---- Registered Waste Tire Storage & Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---- Open Dump Inventory
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System

NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PADS ---- PCB Activity Database System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY DRYCLEANERS ---- Registered Drycleaners
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY UIC ---- Underground Injection Control Wells

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---- EDR Proprietary Manufactured Gas Plants
EDR Hist Auto ---- EDR Exclusive Historical Auto Stations
EDR Hist Cleaner ---- EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CIRCUITRON CORP.	***82 MILBAR BOULEVARD***	***SW 1/2 - 1 (0.968 mi.)***	***T100***	***592***

Federal Delisted NPL site list

Delisted NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may deleted from the NPL where no further response is appropriate.

A review of the Delisted NPL list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 Delisted NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	***168 CENTRAL AVENUE***	***S 1/2 - 1 (0.608 mi.)***	***S95***	***472***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1

CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	*168 CENTRAL AVENUE*	*S 1/2 - 1 (0.608 mi.)*	*S95*	*472*

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMAX FLAVORS	*130 BAYLISS RD*	*NNW 1/8 - 1/4 (0.144 mi.)*	*J47*	*235*

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORPORATIO	*150 FINN CT*	*SSE 1/8 - 1/4 (0.230 mi.)*	*N67*	*323*
FALA CCG INC	*75 MARCUS DR*	*SW 1/8 - 1/4 (0.231 mi.)*	*P71*	*338*
PRECIPART CORP	*100 FINN CT*	*SSE 1/8 - 1/4 (0.231 mi.)*	*O74*	*350*
AIRCRAFT PARTS INC	*160 FINN CT*	*SSE 1/8 - 1/4 (0.240 mi.)*	*N77*	*358*

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INTERLOGIC INDUSTRIE	*85 MARCUS DR*	*SW 1/8 - 1/4 (0.142 mi.)*	*45*	*227*

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/14/2018 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCGOVERN SOD FARM Site Code: 57636	PINELAWN ROAD & OLD	N 1/2 - 1 (0.616 mi.)	97	497
I.W. INDUSTRIES, INC Site Code: 55868	***35 MELVILLE PARK ROA***	***NNW 1/2 - 1 (0.760 mi.)***	***98***	***498***
25 MELVILLE PARK ROA Site Code: 57693	***25 MELVILLE PARK ROA***	***NNW 1/2 - 1 (0.792 mi.)***	***99***	***546***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR Site Code: 55887	***540 SMITH STREET***	***S 1/4 - 1/2 (0.366 mi.)***	***86***	***388***
CANTOR BROTHERS Site Code: 57868	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.464 mi.)***	***92***	***454***
ASTRO ELECTROPLATING Site Code: 58178	***170 CENTRAL AVENUE***	***S 1/2 - 1 (0.600 mi.)***	***S94***	***468***
UNITED STATES DEPT O Site Code: 55856	***PROTECTION-SITE:82 M***	***SW 1/2 - 1 (0.968 mi.)***	***T101***	***608***

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/14/2018 has revealed that there are 20 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMMERCIAL Date Closed: 2001-09-07 Site ID: 127634 Program Number: 0104376	***125 BAYLIS ROAD***	***NNW 1/8 - 1/4 (0.201 mi.)***	***M55***	***290***
WE'RE ASSOCIATES Date Closed: 1988-08-25 Date Closed: 1995-04-05 Site ID: 224161	100 BAYLIS ROAD	NW 1/4 - 1/2 (0.282 mi.)	80	367

Site ID: 224162 Program Number: 8803165 Program Number: 9003860				
WERE ASSOCIATES Date Closed: 1989-03-08 Site ID: 220411 Program Number: 8801432	80 BAYLIS ROAD	NW 1/4 - 1/2 (0.392 mi.)	89	422

Lower Elevation	Address	Direction / Distance	Map ID	Page
RACANELLI ASSOCIATES Date Closed: 1988-09-30 Site ID: 99721 Program Number: 8805457	100 MARCUS DRIVE	S 1/8 - 1/4 (0.129 mi.)	G40	219
GENOVESE DRUG STORES Date Closed: 1999-09-08 Site ID: 249892 Program Number: 9110046	***80 MARCUS DR***	***SSW 1/8 - 1/4 (0.148 mi.)***	***K49***	***260***
CANADA DRY BOTTLING Date Closed: 1999-04-14 Date Closed: 1994-02-10 Site ID: 159315 Site ID: 203799 Program Number: 9700559 Program Number: 9304069	***135 BAYLIS RD***	***NNW 1/8 - 1/4 (0.176 mi.)***	***54***	***286***
NY TEL CO Date Closed: 1992-01-10 Site ID: 198367 Program Number: 9109715	84 DURYEA ROAD	NW 1/8 - 1/4 (0.221 mi.)	57	294
WALAEL RESIDENCE Date Closed: 1999-09-28 Site ID: 240480 Program Number: 9903643	95 RULAND PLACE	W 1/8 - 1/4 (0.227 mi.)	63	304
FALA CCG INC	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.231 mi.)***	***P71***	***338***
AIRCRAFT PARTS INC	***160 FINN CT***	***SSE 1/8 - 1/4 (0.240 mi.)***	***N77***	***358***
NORTHROP GRUMMAN Date Closed: 1988-02-12 Site ID: 145270 Program Number: 8706384	***65 MARCUS DRIVE***	***SW 1/4 - 1/2 (0.257 mi.)***	***79***	***365***
FIRST VEHICLE SERVIC Date Closed: 1988-10-31 Site ID: 274806 Program Number: 8805536	***55 MARCUS DR***	***WSW 1/4 - 1/2 (0.328 mi.)***	***Q81***	***370***
SPILL NUMBER 9713313 Date Closed: 1998-08-26 Site ID: 182849 Program Number: 9713313	98 REPUBLIC ROAD	W 1/4 - 1/2 (0.336 mi.)	82	372
KALMAR DESIGNS Date Closed: 1992-11-13 Site ID: 70689 Program Number: 9209410	***485 SMITH STREET***	***S 1/4 - 1/2 (0.344 mi.)***	***83***	***374***
VENUS SCIENTIFIC INC	***399 SMITH ST***	***SSW 1/4 - 1/2 (0.354 mi.)***	***R84***	***376***

Date Closed: 1988-09-29
Site ID: 287908
Program Number: 8803558

HT STEEL	***375 SMITH STREET***	***SSW 1/4 - 1/2 (0.359 mi.)***	***R85***	***385***
Date Closed: 1994-02-15 Site ID: 84738 Program Number: 9311399				
EAGLE FUEL TRANSPORT	***50 REPUBLIC ROAD***	***SW 1/4 - 1/2 (0.369 mi.)***	***Q87***	***392***
Date Closed: 1992-09-28 Site ID: 243590 Program Number: 9201913				
HENRY SCHEIN CO	***135 DURYEA ROAD***	***WNW 1/4 - 1/2 (0.426 mi.)***	***90***	***423***
Date Closed: 1990-12-12 Date Closed: 1995-04-05 Site ID: 247914 Site ID: 247915 Program Number: 9007825 Program Number: 9204935				
ESTEE LAUDER INC RES	***125 PINELAWN RD***	***N 1/4 - 1/2 (0.435 mi.)***	***91***	***428***
Date Closed: 1993-02-03 Site ID: 160346 Program Number: 9212267				
FORMERLY EMBASSY IND	***300 SMITH ST***	***SSW 1/4 - 1/2 (0.481 mi.)***	***93***	***460***
Date Closed: 1991-07-22 Site ID: 144684 Program Number: 9100457				

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 23 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWSDAY Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 8596 Facility ID: 8596	25 DESHON DR	WNW 0 - 1/8 (0.015 mi.)	B11	136
TRIBUNE LLC Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 08656 Status: INACTIVE Facility ID: 08656	25 DESHON DR	WNW 0 - 1/8 (0.015 mi.)	B15	142
PARAGON ENTERPRISES Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 8235	125 BAYLIS RD	NNW 1/8 - 1/4 (0.201 mi.)	M56	293

Facility ID: 8235

Lower Elevation	Address	Direction / Distance	Map ID	Page
EASTERN ATHLETIC	100 RULAND RD	NNE 0 - 1/8 (0.035 mi.)	C16	144
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 17467 Facility ID: 17467				
CLARE ROSE	***255 CNTY RD 3 PINELA***	***SE 0 - 1/8 (0.052 mi.)***	***D21***	***152***
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7581 Facility ID: 7581				
CLARE ROSE INC	255 PINELAWN RD	SE 0 - 1/8 (0.052 mi.)	D25	168
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 01373 Status: ACTIVE Facility ID: 01373				
WOODBOURNE CULTURAL	***301 COLONIAL SPRING***	***NNE 0 - 1/8 (0.084 mi.)***	***F31***	***181***
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7529 Site Ref#: 12333 Status: ACTIVE Facility ID: 12333				
MRP FAMILY HOLDINGS	101 MARCUS DR	S 0 - 1/8 (0.105 mi.)	G35	213
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 16483 Facility ID: 16483				
RACANELLI COMMERCIAL	102 MARCUS DR	SSE 0 - 1/8 (0.120 mi.)	G37	216
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 11311 Status: INACTIVE Facility ID: 11311				
DON JAGODA INC	102 MARCUS DR	SSE 0 - 1/8 (0.120 mi.)	G39	218
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7203 Facility ID: 7203				
ESPRIT BLDG	100 MARCUS DR	S 1/8 - 1/4 (0.129 mi.)	G41	221
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7104 Facility ID: 7104				
FONAR TRAVEL	102 MARCUS DR	SSE 1/8 - 1/4 (0.134 mi.)	H42	222
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7114 Facility ID: 7114				
MEDISYS HEALTH NETWO	80 MARCUS DR	SSW 1/8 - 1/4 (0.148 mi.)	K48	259
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 7596 Facility ID: 7596				
M & W RECKSON ASSOCI	110 MARCUS DR	SSE 1/8 - 1/4 (0.151 mi.)	H50	264
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015 Site Ref#: 8229				

Facility ID: 8229

RULAND ROAD LLC — 95 RULAND RD — WNW 1/8 - 1/4 (0.174 mi.) — L53 — 280
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 7153
Facility ID: 7153

CANADA DRY BOTTLING — 135 BAYLIS RD — NNW 1/8 - 1/4 (0.176 mi.) — 54 — 286
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 6840
Facility ID: 6840

LABORATORY CORP OF A — 170 FINN CT — SSE 1/8 - 1/4 (0.222 mi.) — N60 — 300
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 450
Facility ID: 450

ARTEK — 170 FINN CT — SSE 1/8 - 1/4 (0.222 mi.) — N61 — 301
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 2248
Facility ID: 2248

FALA INC — 70 MARCUS DR — SSW 1/8 - 1/4 (0.223 mi.) — 62 — 302
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 8240
Facility ID: 8240

NATIONAL ENVIRONMENT — 150 FINN CT — SSE 1/8 - 1/4 (0.230 mi.) — N65 — 307
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 1116
Facility ID: 1116

FALA DIRECT MARKETIN — 75 MARCUS DR — SW 1/8 - 1/4 (0.231 mi.) — P72 — 347
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 8603
Facility ID: 8603

MAYTAG BLDG — 100 FINN CT — SSE 1/8 - 1/4 (0.231 mi.) — O73 — 349
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 363
Facility ID: 363

AIRCRAFT PARTS CORP — 160 FINN CT — SSE 1/8 - 1/4 (0.240 mi.) — N76 — 357
Database: SUFFOLK CO. UST, Date of Government Version: 03/03/2015
Site Ref#: 100
Facility ID: 100

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 15 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWSDAY	25 DESHON DR	WNW 0 - 1/8 (0.015 mi.)	B10	131
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 8596 Facility Id: 8596				
TRIBUNE LLC	25 DESHON DR	WNW 0 - 1/8 (0.015 mi.)	B14	140
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015				

Site Ref#: 08656
Status: INACTIVE
Facility Id: 08656

LINOTYPE-HELL CO 80 RULAND RD WNW 0 - 1/8 (0.083 mi.) E29 177
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 7760
Facility Id: 7760

OTTO KEIL FLORIST 107 RULAND RD WNW 0 - 1/8 (0.104 mi.) E34 212
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 7769
Facility Id: 7769

COMAX MANUFACTURING 130 BAYLIS RD NNW 1/8 - 1/4 (0.144 mi.) J46 230
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 8369
Facility Id: 8369

Lower Elevation	Address	Direction / Distance	Map ID	Page

CLARE ROSE ***255 CNTY RD 3 PINELA*** ***SE 0 - 1/8 (0.052 mi.)*** ***D21*** ***152***
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 7581
Facility Id: 7581

CLARE ROSE INC 255 PINELAWN RD SE 0 - 1/8 (0.052 mi.) D22 161
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 01373
Status: ACTIVE
Facility Id: 01373

WOODBOURNE CULTURAL ***301 COLONIAL SPRING*** ***NNE 0 - 1/8 (0.084 mi.)*** ***F31*** ***181***
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 7529
Facility Id: 7529

WOODBOURNE CULTURAL 301 COLONIAL SPRING NNE 0 - 1/8 (0.084 mi.) F32 208
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 12333
Status: ACTIVE
Facility Id: 12333

RACANELLI COMMERCIAL 102 MARCUS DR SSE 0 - 1/8 (0.120 mi.) G38 218
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 11311
Status: INACTIVE

RULAND ROAD LLC 95 RULAND RD WNW 1/8 - 1/4 (0.174 mi.) L52 271
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 7153
Facility Id: 7153

CANADA DRY BOTTLING ***135 BAYLIS RD*** ***NNW 1/8 - 1/4 (0.176 mi.)*** ***54*** ***286***
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 6840
Facility Id: 6840

MIP INC 130 FINN CT SSE 1/8 - 1/4 (0.231 mi.) O70 337
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015
Site Ref#: 431

Facility Id: 431

AIRCRAFT PARTS INC	***160 FINN COURT***	***SSE 1/8 - 1/4 (0.240 mi.)***	***N75***	***354***
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 100 Facility Id: 100				
ULTIMATE PRECISION M	200 FINN CT	SSE 1/8 - 1/4 (0.246 mi.)	N78	363
Database: SUFFOLK CO. AST, Date of Government Version: 03/03/2015 Site Ref#: 1073 Facility Id: 1073				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/14/2018 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
STELLAE INTERNATIONA	***333 SMITH ST***	***SSW 1/4 - 1/2 (0.390 mi.)***	***88***	***395***
Site Code: 58757				

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 05/14/2018 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
STELLAE INTERNATIONA	***333 SMITH ST***	***SSW 1/4 - 1/2 (0.390 mi.)***	***88***	***395***
Site Code: 58757				

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 3 NY VCP sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR	***540 SMITH STREET***	***S 1/4 - 1/2 (0.366 mi.)***	***86***	***388***
Database: VCP, Date of Government Version: 05/14/2018 Site Code: 56903				
STELLAE INTERNATIONA	***333 SMITH ST***	***SSW 1/4 - 1/2 (0.390 mi.)***	***88***	***395***
Database: VCP, Date of Government Version: 05/14/2018 Site Code: 58757				
CANTOR BROTHERS	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.464 mi.)***	***92***	***454***
Database: VCP, Date of Government Version: 05/14/2018				

EXECUTIVE SUMMARY

Site Code: 57869

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 05/14/2018 has revealed that there is 1 NY DEL SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN	***168 CENTRAL AVE***	***S 1/2 - 1 (0.608 mi.)***	***S96***	***493***

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/14/2018 has revealed that there are 12 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J.M ALBRIZZIO Date Closed: 1993-12-24 Spill Number: 9309731 Site ID: 134618	25 DESCHON DRIVE	WNW 0 - 1/8 (0.015 mi.)	B12	138
NEWSDAY Date Closed: 2005-09-09 Spill Number: 0550849 Site ID: 351331	25 DESHON DRIVE	WNW 0 - 1/8 (0.015 mi.)	B13	139
PATTERSON BUILDING Date Closed: 2001-09-27 Spill Number: 0106454 Site ID: 321344	25 DESHON DR/MARCUS	WSW 0 - 1/8 (0.071 mi.)	26	173

Lower Elevation	Address	Direction / Distance	Map ID	Page
EASTERN ATHLETIC CLU Date Closed: 2009-12-28 Spill Number: 0910535 Site ID: 423296	100 RULAND ROAD	NNE 0 - 1/8 (0.035 mi.)	C17	146
BUSINESS Date Closed: 2013-12-16 Spill Number: 1303748	255 PINELAWN ROAD	SE 0 - 1/8 (0.052 mi.)	D18	147

Site ID: 484245				
IMPERIAL NEWS CO Date Closed: 2010-03-22 Date Closed: 1986-10-01 Date Closed: 2004-06-02 Spill Number: 0906309 Spill Number: 8603300 Spill Number: 9308159 Site ID: 418639 Site ID: 202109 Site ID: 202110	255 PINELAWN ROAD	SE 0 - 1/8 (0.052 mi.)	D19	148
CLARE ROSE Date Closed: 2009-04-30 Spill Number: 0890480 Site ID: 399610	255 PINELAWN RD/MARC	SE 0 - 1/8 (0.052 mi.)	D20	151
CLARE ROSE Date Closed: 1994-11-09 Spill Number: 9402856 Site ID: 329995	255 PINE LAWN ROAD	SE 0 - 1/8 (0.052 mi.)	D24	167
UNKNOWN Date Closed: 1987-04-22 Spill Number: 8600899 Site ID: 296193	PINE LAWN & RULAN RO	NNE 0 - 1/8 (0.073 mi.)	C27	174
UNKNOWN Date Closed: 2003-07-02 Spill Number: 0303103 Site ID: 110727	PINELAWN ROAD/RULAND	NNE 0 - 1/8 (0.073 mi.)	C28	175
WOODBOURNE CULTURAL Date Closed: 2008-10-30 Spill Number: 0801935 Site ID: 397985	301 COLONIAL SPRINGS	NNE 0 - 1/8 (0.084 mi.)	F33	211
PERGAMENT HOME CENTE Date Closed: 2001-10-03 Date Closed: 2001-03-23 Spill Number: 0013423 Spill Number: 0013428 Site ID: 328273 Site ID: 328274	***101 MARCUS DRIVE***	***S 0 - 1/8 (0.105 mi.)***	***G36***	***214***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/11/2017 has revealed that there are 10 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TRIBUNE COMPANY	*25 DESHON DR*	*WNW 0 - 1/8 (0.015 mi.)*	*B9*	*128*
HEIDELBERG PUBLISHIN	*80 RULAND RD*	*WNW 0 - 1/8 (0.083 mi.)*	*E30*	*178*

Lower Elevation	Address	Direction / Distance	Map ID	Page
IMPERIAL NEWS	*255 PINELAWN RD*	*SE 0 - 1/8 (0.052 mi.)*	*D23*	*165*
HONEYWELL INC	*175 PINELAWN RD*	*N 1/8 - 1/4 (0.141 mi.)*	*I43*	*223*
GENOVESE DRUG STORES	*80 MARCUS DR*	*SSW 1/8 - 1/4 (0.148 mi.)*	*K49*	*260*
FONAR CORP INC	*110 MARCUS DR*	*SSE 1/8 - 1/4 (0.151 mi.)*	*H51*	*266*
ROCHE BIOMEDICAL LAB	*170 FINN CT*	*SSE 1/8 - 1/4 (0.222 mi.)*	*N58*	*295*
ROCHE BIOMEDICAL LAB	*170 FINN CT*	*SSE 1/8 - 1/4 (0.222 mi.)*	*N59*	*298*
MANUFACTURERS INDEXI	*130 FINN CT*	*SSE 1/8 - 1/4 (0.231 mi.)*	*O69*	*335*
AIRCRAFT PARTS INC	*160 FINN COURT*	*SSE 1/8 - 1/4 (0.240 mi.)*	*N75*	*354*

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 01/09/2018 has revealed that there are 2 ROD sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRONIC PLATING CO.,	*168 CENTRAL AVENUE*	*S 1/2 - 1 (0.608 mi.)*	*S95*	*472*
CIRCUITRON CORP.	*82 MILBAR BOULEVARD*	*SW 1/2 - 1 (0.968 mi.)*	*T100*	*592*

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 04/30/2018 has revealed that there are 18 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TRIBUNE COMPANY EPA ID: NYD002052504	*25 DESHON DR*	*WNW 0 - 1/8 (0.015 mi.)*	*B9*	*128*
HEIDELBERG PUBLISHIN EPA ID: NYD986885457	*80 RULAND RD*	*WNW 0 - 1/8 (0.083 mi.)*	*E30*	*178*
COMAX FLAVORS EPA Id: NYD016914376	*130 BAYLISS RD*	*NNW 1/8 - 1/4 (0.144 mi.)*	*J47*	*235*

Lower Elevation	Address	Direction / Distance	Map ID	Page
IMPERIAL NEWS EPA ID: NYD986952588	*255 PINELAWN RD*	*SE 0 - 1/8 (0.052 mi.)*	*D23*	*165*
PERGAMENT HOME CENTE EPA ID: NYP000736259	*101 MARCUS DRIVE*	*S 0 - 1/8 (0.105 mi.)*	*G36*	*214*
HONEYWELL INC EPA ID: NYR000004804	*175 PINELAWN RD*	*N 1/8 - 1/4 (0.141 mi.)*	*I43*	*223*
NEW YORK STATE DRUG EPA ID: NYP000916015	175 PINELAWN RD SUIT	N 1/8 - 1/4 (0.141 mi.)	I44	227
INTERLOGIC INDUSTRIE	*85 MARCUS DR*	*SW 1/8 - 1/4 (0.142 mi.)*	*45*	*227*

EPA ID: NYD980766349

GENOVESE DRUG STORES EPA ID: NYD012364949	***80 MARCUS DR***	***SSW 1/8 - 1/4 (0.148 mi.)***	***K49***	***260***
FONAR CORP INC EPA ID: NYD986908853	***110 MARCUS DR***	***SSE 1/8 - 1/4 (0.151 mi.)***	***H51***	***266***
ROCHE BIOMEDICAL LAB EPA ID: NYD986899219	***170 FINN CT***	***SSE 1/8 - 1/4 (0.222 mi.)***	***N58***	***295***
ROCHE BIOMEDICAL LAB EPA ID: NYD047645700	***170 FINN CT***	***SSE 1/8 - 1/4 (0.222 mi.)***	***N59***	***298***
MORRIS BROTHERS AUTO EPA ID: NYP000786608	***150 FINN COURT***	***SSE 1/8 - 1/4 (0.230 mi.)***	***N64***	***305***
PRECIPART CORPORATIO EPA ID: NYR000087247	***150 FINN CT***	***SSE 1/8 - 1/4 (0.230 mi.)***	***N67***	***323***
MANUFACTURERS INDEXI EPA ID: NYR000021436	***130 FINN CT***	***SSE 1/8 - 1/4 (0.231 mi.)***	***O69***	***335***
FALA CCG INC EPA Id: NYR000067322	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.231 mi.)***	***P71***	***338***
PRECIPART CORP EPA ID: NYR000093864	***100 FINN CT***	***SSE 1/8 - 1/4 (0.231 mi.)***	***O74***	***350***
AIRCRAFT PARTS INC EPA Id: NYD013561139	***160 FINN CT***	***SSE 1/8 - 1/4 (0.240 mi.)***	***N77***	***358***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORP Generator EPA Id: NYR000087247	150 FINN COURT	SSE 1/8 - 1/4 (0.230 mi.)	N68	334

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRECIPART CORPORATIO EPA ID: NYR000087247	***150 FINN CT***	***SSE 1/8 - 1/4 (0.230 mi.)***	***N67***	***323***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there are 5 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMAX FLAVORS	***130 BAYLISS RD***	***NNW 1/8 - 1/4 (0.144 mi.)***	***J47***	***235***

EXECUTIVE SUMMARY

EPA Id: NYD016914376

Lower Elevation	Address	Direction / Distance	Map ID	Page
FONAR CORP INC EPA ID: NYD986908853	***110 MARCUS DR***	***SSE 1/8 - 1/4 (0.151 mi.)***	***H51***	***266***
PRECIPART CORPORATIO EPA Id: NYR000087247	150 FINN CT	SSE 1/8 - 1/4 (0.230 mi.)	N66	308
FALA CCG INC EPA Id: NYR000067322	***75 MARCUS DR***	***SW 1/8 - 1/4 (0.231 mi.)***	***P71***	***338***
AIRCRAFT PARTS INC EPA Id: NYD013561139	***160 FINN CT***	***SSE 1/8 - 1/4 (0.240 mi.)***	***N77***	***358***

NY VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 01/01/2018 has revealed that there are 2 NY VAPOR REOPENED sites within approximately 0.5 miles of the target property.


Lower Elevation	Address	Direction / Distance	Map ID	Page
MINMILT REALTY (HYGR Facility Status: Underway Site Code: 152147	***540 SMITH STREET***	***S 1/4 - 1/2 (0.366 mi.)***	***86***	***388***
CANTOR BROTHERS Facility Status: Complete (Mitigate) Site Code: 152021	***50 ENGINEERS LANE***	***S 1/4 - 1/2 (0.464 mi.)***	***92***	***454***

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
PINELAWN/FARMINGDALE - HORTONSPHER	NY SHWS
MELVILLE PLUME TRACKDOWN	NY SHWS
RJN ASSOCIATES; LTD	NY SWF/LF

OVERVIEW MAP - 5337044.2S



0 1/4 1/2 1 Miles


- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- National Wetland Inventory
- State Wetlands
- Upgradient Area

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Newsday ADDRESS: 235 Pinelawn Road Melville NY 11747 LAT/LONG: 40.763451 / 73.406648	CLIENT: The Vertex Companies, Inc. CONTACT: Stephen Mccarthy INQUIRY #: 5337044.2s DATE: June 19, 2018 12:59 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5337044.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Newsday	CLIENT: The Vertex Companies, Inc.
ADDRESS: 235 Pinelawn Road Melville NY 11747	CONTACT: Stephen Mccarthy
LAT/LONG: 40.763451 / 73.406648	INQUIRY #: 5337044.2s DATE: June 19, 2018 1:00 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	1	NR	1
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500	1	0	0	0	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	1	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250	1	0	1	NR	NR	NR	2
RCRA-SQG	0.250		0	4	NR	NR	NR	4
RCRA-CESQG	0.250		0	1	NR	NR	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	2	5	NR	7
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500	1	0	8	12	NR	NR	21
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250	2	9	14	NR	NR	NR	25
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	0	NR	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250	2	9	6	NR	NR	NR	17
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	1	NR	NR	1
NY INST CONTROL	0.500		0	0	1	NR	NR	1
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	3	NR	NR	3
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	0	0	NR	NR	0
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	1	NR	1
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	3	12	NR	NR	NR	NR	15
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	3	7	NR	NR	NR	11
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	2	NR	2
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	1	NR	NR	NR	NR	NR	1
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP	1	NR	NR	NR	NR	NR	1
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250	2	4	14	NR	NR	NR	20
PA MANIFEST	0.250		0	1	NR	NR	NR	1
RI MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250	1	0	5	NR	NR	NR	6
NY SPDES	TP	1	NR	NR	NR	NR	NR	1
NY VAPOR REOPENED	0.500		0	0	2	NR	NR	2
NY UIC	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		22	37	62	21	11	0	153

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 Target Property **NEWSDAY INC**
235 PINELAWN RD
MELVILLE, NY 11747

NY UST **U004219660**
N/A

Site 1 of 8 in cluster A

Actual: 105 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7934
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7934
Facility Reference #:	Not reported
Official Use:	Removed Tank. 86
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	23068
Installed:	78
Capacity:	25000
Substance:	DIESEL
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	25000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/20/1927
Year Installed:	78
Description of drop records:	Not reported
Tank ID:	2
Tank Key:	23069
Installed:	78
Capacity:	25000

NEWSDAY INC (Continued) **U004219660**

Substance:	DIESEL
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	25000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/20/1927
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	23070
Installed:	78
Capacity:	25000
Substance:	DIESEL
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	25000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/20/1927
Year Installed:	78

NEWSDAY INC (Continued) **U004219660**

Description of drop records:	Not reported

Tank ID:	4
Tank Key:	23071
Installed:	78
Capacity:	12000
Substance:	GASOLINE
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	12000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	11/20/1927
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	23072
Installed:	78
Capacity:	2000
Substance:	SPILL CONTAINMENT
Date Removed:	3/5/2072
Construction:	STEEL
Dispenser:	SUBMERSIBLE
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

NEWSDAY INC (Continued) **U004219660**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	3/5/2072
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	6
Tank Key:	23073
Installed:	78
Capacity:	25000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	25000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	23074
Installed:	78
Capacity:	25000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	25000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

NEWSDAY INC (Continued) **U004219660**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	23075
Installed:	78
Capacity:	4000
Substance:	INDUSTRIAL WASTE
Date Removed:	11/21/1927
Construction:	FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	11/21/1927
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	14
Tank Key:	23081
Installed:	85
Capacity:	20000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE

NEWSDAY INC (Continued) **U004219660**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	20000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	Not reported

Tank ID:	15
Tank Key:	23082
Installed:	85
Capacity:	20000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	20000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	Not reported

Tank ID:	16

NEWSDAY INC (Continued) **U004219660**

Tank Key:	23083
Installed:	85
Capacity:	20000
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	20000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	Not reported

Tank ID:	18
Tank Key:	23085
Installed:	87
Capacity:	2500
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

NEWSDAY INC (Continued) **U004219660**

Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	87
Description of drop records:	Not reported

Tank ID:	19
Tank Key:	23086
Installed:	87
Capacity:	4000
Substance:	INDUSTRIAL WASTE
Date Removed:	Not reported
Construction:	STEEL / STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	87
Description of drop records:	Not reported

Tank ID:	20
Tank Key:	23087
Installed:	Not reported
Capacity:	10000
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUBMERSIBLE
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	10000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

NEWSDAY INC (Continued) **U004219660**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

A2 Target Property **NEWSDAY LLC** **NY UST** **U003537273**
235 PINELAWN RD **N/A**
MELVILLE, NY 11747

Site 2 of 8 in cluster A

Actual: 105 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	02037
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	12/31/2016
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	02037
Billing Contact:	CABLEVISION
Billing Address:	1111 STEWART AVE
Billing Address:	BETHPAGE
Billing State:	NY
Billing Zip:	11714
Storage Owner:	CABLEVISION
Storage Owner Address:	1111 STEWART AVE
Storage Owner City:	BETHPAGE
Storage Owner State:	NY
Storage Owner Zip:	11714

Tank Info:

Facility ID:	02037
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION

NEWSDAY LLC (Continued) **U003537273**

Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3

NEWSDAY LLC (Continued) **U003537273**

Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	01/01/1986
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	6
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	ABANDONED IN PLACE
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	03/20/2014
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	TIGHTNESS TESTING
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	Not reported
Installed:	Not reported
Capacity:	25000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	ABANDONED IN PLACE
Total Capacity:	25000 gallons
Date Permitted:	Not reported
Date Closed:	03/20/2014
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	TIGHTNESS TESTING
Overfill Prevention:	- Electronic Leak Alarm

NEWSDAY LLC (Continued) **U003537273**

Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	14
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons
Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	15
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons

NEWSDAY LLC (Continued) **U003537273**

Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	16
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	20000 gallons
Date Permitted:	Not reported
Date Closed:	04/28/2010
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	18
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	#2 FUEL OIL

NEWSDAY LLC (Continued) **U003537273**

Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	93
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

NEWSDAY LLC (Continued) **U003537273**

Tank ID:	94
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	95
Tank Key:	Not reported
Installed:	Not reported
Capacity:	20000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUBMERSIBLE
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	20000 gallons
Date Permitted:	07/23/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	FIBERGLASS (FRP)
Pipe External Protection:	NONE
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE & AUTO LINE LEAK DETECTOR

NEWSDAY LLC (Continued) **U003537273**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

A3 **NEWSDAY LLC** **NY AST** **A100385242**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 3 of 8 in cluster A

Actual:
105 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	02037
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	12/31/2016
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	02037
Billing Contact:	CABLEVISION
Billing Address:	1111 STEWART AVE
Billing Address:	BETHPAGE
Billing State:	NY
Billing Zip:	11714
Storage Owner:	CABLEVISION
Storage Owner Address:	1111 STEWART AVE
Storage Owner City:	BETHPAGE
Storage Owner State:	NY
Storage Owner Zip:	11714

Tank Info:

Facility ID:	02037
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	17
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	100 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	NONE

NEWSDAY LLC (Continued) **A100385242**

Leak Detection:	EXEMPT
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	38
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	125 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	PAINTED / COATED
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	40
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	25 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE

NEWSDAY LLC (Continued) **A100385242**

Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	BLACK STEEL
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	VISUAL MONITORING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	55
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	REMOVED
Total Capacity:	1250 gallons
Date Permitted:	Not reported
Date Closed:	02/23/2006
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	56
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	REMOVED
Total Capacity:	1250 gallons
Date Permitted:	Not reported
Date Closed:	02/23/2006
Internal Protection:	NONE

NEWSDAY LLC (Continued) **A100385242**

Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	70
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	101 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	Not reported
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	PLAIN STEEL/IRON
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	71
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	81 gallons
Date Permitted:	Not reported
Date Closed:	06/19/2013

NEWSDAY LLC (Continued) **A100385242**

Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	Not reported
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	86
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1100 gallons
Date Permitted:	02/27/2006
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	87
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1100 gallons
Date Permitted:	02/27/2006

NEWSDAY LLC (Continued) **A100385242**

Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	VISUAL MONITORING (ABOVEGROUND TANK)
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SECONDARY CONTAINMENT
Pipe Location:	NO PIPING
Pipe Type:	NONE
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	NONE (NON-EXEMPT)
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	9
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	EXEMPT
Overfill Prevention:	- Sight/Level Gauge
Spill Prevention:	EXEMPT
Pipe Location:	ABOVEGROUND INDOORS ONLY
Pipe Type:	COPPER
Pipe External Protection:	NONE
Pipe Containment:	NONE
Pipe Leak Detection:	EXEMPT
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	97
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	15000 gallons

NEWSDAY LLC (Continued) **A100385242**

Date Permitted:	12/06/2013
Date Closed:	Not reported
Internal Protection:	EPOXY LINER
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm - Fill Limiter - Sight/Level Gauge
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	ABOVEGROUND OUT & INDOORS
Pipe Type:	BLACK STEEL
Pipe External Protection:	PAINT/COATED
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE ONLY
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

A4 **NEWSDAY** **NY Spills** **S118460063**
Target **235 PINELAWN ROAD** **N/A**
Property **MELVILLE, NY**

Site 4 of 8 in cluster A

Actual: **105 ft.**

SPILLS:

Facility ID:	1508951
Facility Type:	ER
Spill Number:	1508951
DER Facility ID:	300411
Site ID:	517549
DEC Region:	1
Closed Date:	2015-12-09
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2015-12-02
Investigator:	RJPOCZKA
Referred To:	Not reported
Reported to Dept:	2015-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-02
Spill Record Last Update:	2016-03-07
Spiller Name:	JOSEPH MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller Company:	999
Contact Name:	JOSEPH MARINO
DEC Memo:	"12/02/15 1050 Hrs (A): Called Marino- he said a hose burst on a generator INSIDE their facility, but the fluid spilled outside to a

NEWSDAY (Continued) **S118460063**

drywell. He confirmed that the drywell has no outlets and a sand bottom, and that MEG is responding. 12/02/15 1050 Hrs (B): DEC informed him that this office might have RJP (currently in Farmingdale) respond when finished there. DR 12/02/15 1052 Hrs: RJP called- he just finished in Farmingdale and saw this report, so he will respond at this time. DR 12/02/15 approx noon: As per RJP- ALL the product appears to have soaked into the sand at the bottom of the drywell. He will obtain a copy of the MSDS sheet from Newsday. DR 12/2/15 1135 Hrs: RJP on location w/ MEG. No recoverable liquid, no DEC action. Documents on D2. RJP"

Remarks: "Spill contained to drive well, Miller environmental enroute for pump out of fluid."

All Materials:

Site ID:	517549
Operable Unit ID:	1266624
Operable Unit:	01
Material ID:	2270570
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A5 **NALCO CHEMICAL** **RCRA NonGen / NLR** **1001113472**
Target **235 PINELAWN RD - BOILER HOUSE** **FINDS** **NYR000024620**
Property **MELVILLE, NY 11747** **ECHO**
NY MANIFEST

Site 5 of 8 in cluster A

Actual: 105 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NALCO CHEMICAL
Facility address:	235 PINELAWN RD - BOILER HOUSE MELVILLE, NY 11747
EPA ID:	NYR000024620
Mailing address:	NALCO CENTER NAPERVILLE, NY 60563-1198
Contact:	Not reported
Contact address:	NALCO CENTER NAPERVILLE, NY 60563-1198
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-843-2038

NALCO CHEMICAL (Continued) **1001113472**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEWSDAY INC
Owner/operator address: 235 PINELAWN RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 516-843-2038
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NALCO CHEMICAL
Classification: Not a generator, verified

Date form received by agency: 07/15/1996
Site name: NALCO CHEMICAL
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 05/29/1996
Site name: NALCO CHEMICAL
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

NALCO CHEMICAL (Continued) **1001113472**

Violation Status: No violations found

FINDS:

Registry ID: 110004525443

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001113472
Registry ID:	110004525443
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004525443

NY MANIFEST:

Country:	USA
EPA ID:	NYR000024620
Facility Status:	Not reported
Location Address 1:	235 PINELAWN ROAD BOILER
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000024620
Mailing Name:	NALCO CHEMICAL
Mailing Contact:	EVERETTE GAUTHIER
Mailing Address 1:	1 NALCO CENTER
Mailing Address 2:	Not reported
Mailing City:	NAPERVILLE
Mailing State:	IL
Mailing Zip:	60563
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7083051134

A6 **NEWSDAY INC** **NY AST** **1006305114**
Target **235 PINELAWN RD** **N/A**
Property **MELVILLE, NY 11747**

Site 6 of 8 in cluster A

Actual:
105 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	7934
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7934
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	10
Tank Key:	23077
Year Installed:	79
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Tank ID:	11
Tank Key:	23078
Year Installed:	78
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE

NEWSDAY INC (Continued) **1006305114**

Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	12
Tank Key:	23079
Year Installed:	78
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	13
Tank Key:	23080
Year Installed:	78
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	5/26/1956

Tank ID:	17
Tank Key:	23084
Year Installed:	78
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	21
Tank Key:	23088
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Never Installed

NEWSDAY INC (Continued) **1006305114**

Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	4675
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	22
Tank Key:	23089
Year Installed:	91
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	12/18/2014
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1380
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	23
Tank Key:	23090
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	OTHER

NEWSDAY INC (Continued) **1006305114**

Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	12/18/2014
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	24
Tank Key:	23091
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	12/18/2014
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	165
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	25
Tank Key:	23092
Year Installed:	91
Substance:	INDUSTRIAL WASTE
Construction:	STEEL

NEWSDAY INC (Continued) **1006305114**

Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 96
Permit to Operate:	12/18/2014
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	26
Tank Key:	23093
Year Installed:	89
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	12/6/2232

Tank ID:	27
Tank Key:	23094
Year Installed:	89
Substance:	INDUSTRIAL WASTE

NEWSDAY INC (Continued) **1006305114**

Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	12/6/2232

Tank ID:	28
Tank Key:	23095
Year Installed:	89
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	8/6/2099

Tank ID:	29
Tank Key:	23096
Year Installed:	92

NEWSDAY INC (Continued) **1006305114**

Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 03
Permit to Operate:	5/26/1956
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2640
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	8/6/2099

Tank ID:	30
Tank Key:	23097
Year Installed:	Not reported
Substance:	CAUSTIC
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 06
Permit to Operate:	5/26/1956
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	1/25/1961

Tank ID:	31
Tank Key:	23098

NEWSDAY INC (Continued) **1006305114**

Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	32
Tank Key:	23099
Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	33

NEWSDAY INC (Continued) **1006305114**

Tank Key:	23100
Year Installed:	86
Substance:	BLACK INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	34
Tank Key:	23101
Year Installed:	86
Substance:	CYAN INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	35
Tank Key:	23102
Year Installed:	86
Substance:	YELLOW INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	36
Tank Key:	23103
Year Installed:	86
Substance:	RED INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	37
Tank Key:	23104
Year Installed:	86
Substance:	MAGENTA INK
Construction:	STEEL / CONCRETE
Dispenser:	SUCTION
Official Use:	Approved Plan for Upgrade of existing non-complying tank, awaiting construction for compliance insp
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	38
Tank Key:	23105
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	125
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	39
Tank Key:	23106
Year Installed:	Not reported
Substance:	COOLING TOWER BLOW D
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	8/6/2099

Tank ID:	40
Tank Key:	23107
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	25
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	41
Tank Key:	23108
Year Installed:	Not reported
Substance:	COLLING WATER BLOW D
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	42
Tank Key:	43056
Year Installed:	1998
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	50
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	43
Tank Key:	43057
Year Installed:	1998
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	12/6/2232

Tank ID:	44
Tank Key:	43058
Year Installed:	2000
Substance:	DEVELOPER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	55
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	45
Tank Key:	43059
Year Installed:	Not reported
Substance:	DEVELOPER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	46
Tank Key:	43060
Year Installed:	Not reported
Substance:	FIXER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	47
Tank Key:	43061
Year Installed:	Not reported
Substance:	FIXER
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	48
Tank Key:	43062
Year Installed:	Not reported
Substance:	PHOTO CHEMS
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	66
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	49
Tank Key:	43063
Year Installed:	Not reported
Substance:	DRY PHOTO CHEMS
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	50
Tank Key:	43064
Year Installed:	Not reported
Substance:	SOLVENT PARTS WASHER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 05
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/12/1929

NEWSDAY INC (Continued) **1006305114**

Tank ID:	51
Tank Key:	43065
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	12/6/2232

Tank ID:	52
Tank Key:	43066
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	12/6/2232

NEWSDAY INC (Continued) **1006305114**

Tank ID:	53
Tank Key:	43067
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	12/6/2232

Tank ID:	54
Tank Key:	43068
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	330
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	12/6/2232

NEWSDAY INC (Continued) **1006305114**

Tank ID:	55
Tank Key:	43069
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 06
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/25/1961

Tank ID:	56
Tank Key:	43070
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 06
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/25/1961

NEWSDAY INC (Continued) **1006305114**

Tank ID:	57
Tank Key:	43071
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	58
Tank Key:	43072
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	59
Tank Key:	43073
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	60
Tank Key:	43074
Year Installed:	Not reported
Substance:	BOILER CHEMICAL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	61
Tank Key:	43075
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	62
Tank Key:	43076
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	63
Tank Key:	43077
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	64
Tank Key:	43078
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	65
Tank Key:	43079
Year Installed:	Not reported
Substance:	METHANOL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	225
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	66
Tank Key:	43080
Year Installed:	2
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	OTHER
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	660
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	67
Tank Key:	43081
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 03
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	440
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	8/6/2099

Tank ID:	68
Tank Key:	43082
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	5280
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	69
Tank Key:	43083
Year Installed:	Not reported
Substance:	SALT/SAND STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	10
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/4/2178

Tank ID:	70
Tank Key:	43084
Year Installed:	Not reported
Substance:	OTHER OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	101
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	71
Tank Key:	43085
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	81
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	72
Tank Key:	43086
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	600
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/4/2178

NEWSDAY INC (Continued) **1006305114**

Tank ID:	73
Tank Key:	43087
Year Installed:	Not reported
Substance:	HYDRAULIC OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	120
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	74
Tank Key:	43088
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Removed Tank. 01
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/4/2178

NEWSDAY INC (Continued) **1006305114**

Tank ID:	75
Tank Key:	44155
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	76
Tank Key:	44156
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	77
Tank Key:	44157
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	78
Tank Key:	44158
Year Installed:	Not reported
Substance:	FOUNTAIN SOLUTION
Construction:	POLYETHYLENE / CONCR
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	79
Tank Key:	44159
Year Installed:	Not reported
Substance:	TRANSFER FACILITY
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	660
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	Not reported

Tank ID:	80
Tank Key:	44160
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	60
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	81
Tank Key:	44161
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	60
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

Tank ID:	82
Tank Key:	44162
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	50
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	83
Tank Key:	44163
Year Installed:	Not reported
Substance:	INDUSTRIAL WASTE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 08
Permit to Operate:	8/6/2099
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	84
Tank Key:	44543
Year Installed:	Not reported
Substance:	Not reported
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	12/6/2232
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2860
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	85
Tank Key:	47001
Year Installed:	Not reported
Substance:	DEGREASER
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	1/12/1929
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	86
Tank Key:	47927
Year Installed:	2006
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

NEWSDAY INC (Continued) **1006305114**

Tank ID:	87
Tank Key:	47928
Year Installed:	2006
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 11
Permit to Operate:	3/1/1962
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	9
Tank Key:	23076
Year Installed:	78
Substance:	DIESEL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Exempt from Suffolk County Art 12 Regulation
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

A7 **NEWSDAY INC** **NY Spills** **S118952427**
Target **235 PINELAWN ROAD** **NY MANIFEST** **N/A**
Property **MELVILLE LONG ISLAND, NY 11747**

Site 7 of 8 in cluster A

Actual:
105 ft.

SPILLS:

Facility ID:	1606790
Facility Type:	ER
Spill Number:	1606790
DER Facility ID:	422538
Site ID:	533430
DEC Region:	1
Closed Date:	2017-11-09
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2016-10-11
Investigator:	RJPOCZKA
Referred To:	Not reported
Reported to Dept:	2016-10-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-10-11
Spill Record Last Update:	2017-12-18
Spiller Name:	Not reported
Spiller Company:	NEWSDAY LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSEPH MARINO
DEC Memo:	"10/11/16 @ 1130 AM -WG called Mr. Marino (Newsday LLC) -No answer. Left message. 10/11/16 @ 1230 PM--Rob was dispatched to the site. 10/11/16 1250 Hrs: RJP on location. Marino did not answer phone, RJP requested him at reception desk. Electric air compressor, 12 gal capacity of synthetic compressor oil, SAE 30 non-detergent. Failure of weld at joint, release of approx. 4 gallons. 4 gallons remains in equipment, 4 gallons recovered in buckets. Release to base of compressor, concrete floor, and floor drain. Absorbent pads placed, compressor out of service pending repairs. Drain connected to on-site wastewater collection and treatment facility. Facility operates oil/water separator and utilizes mechanical, chemical, and bacteriological treatment prior to discharge. Incident was also referred to the Water Unit. 10/13/17 1130 Hrs: RJP made call to Marino. Surface spill cleaned up, equipment repaired and returned to service, no issues noted with water treatment facility. No Further Action. RJP. "
Remarks:	"the spill went into the waste treatment plant that will go into underground pools. The cleanup is pending. It would be process or clean in the treatment plant."

All Materials:

Site ID:	533430

NEWSDAY INC (Continued) **S118952427**

Operable Unit ID:	1282150
Operable Unit:	01
Material ID:	2287488
Material Code:	0811A
Material Name:	compressor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1703192
Facility Type:	ER
Spill Number:	1703192
DER Facility ID:	300411
Site ID:	554358
DEC Region:	1
Closed Date:	2017-07-03
Spill Cause:	Human Error
Spill Class:	D5
SWIS:	5226
Spill Date:	2017-07-01
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2017-07-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-01
Spill Record Last Update:	2017-11-03
Spiller Name:	JOSEPH MARINO
Spiller Company:	NEWSDAY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSEPH MARINO
DEC Memo:	"OUTSIDE WASTE TREATMENT FACILITY 07/01/17 -10:00 Nh spoke with Joe Marino..operator failed to close valve causing waste water to spill out.. some went into drain which an individual drain. Drain was pumped out. NH will refer to water unit via e-mail."
Remarks:	"spill impacted storm drain, clean up is pending"

All Materials:

Site ID:	554358
Operable Unit ID:	1302434
Operable Unit:	01
Material ID:	2308818
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported

NEWSDAY INC (Continued) **S118952427**

Material FA:	Other
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYD052782497
Facility Status:	Not reported
Location Address 1:	235 PINELAWN ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD052782497
Mailing Name:	NEWSDAY INC
Mailing Contact:	ATTN DAVE KRUEGER
Mailing Address 1:	235 PINELAWN RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	4250
Mailing Country:	USA
Mailing Phone:	5164542025

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	TXR000081205
Trans2 State ID:	MAD039322250
Generator Ship Date:	09/26/2017
Trans1 Recv Date:	09/26/2017
Trans2 Recv Date:	09/29/2017
TSD Site Recv Date:	10/05/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052782497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	006125684SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

NEWSDAY INC (Continued) **S118952427**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A8
Target Property

NEWSDAY INC
235 PINELAWN ROAD
MELVILLE, NY 11747

Site 8 of 8 in cluster A

Actual:
105 ft.

SEMS-ARCHIVE **1000378809**
RCRA-LQG **NYD052782497**
NY LTANKS
NY Spills
ICIS
US AIRS
FINDS
ECHO
NY AIRS
NJ MANIFEST
NY SPDES

SEMS Archive:

Site ID:	202958
EPA ID:	NYD052782497
Cong District:	2
FIPS Code:	36103
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	2
Site ID:	202958
EPA ID:	NYD052782497
Site Name:	NEWSDAY INC
NPL:	N
FF:	N
OU:	0

NEWSDAY INC (Continued) **1000378809**

Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1998-10-21 00:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 2
Site ID: 202958
EPA ID: NYD052782497
Site Name: NEWSDAY INC
NPL: N
FF: N
OU: 0
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1989-02-28 00:00:00
Finish Date: 1989-03-31 00:00:00
Qual: H
Current Action Lead: EPA Perf

Region: 2
Site ID: 202958
EPA ID: NYD052782497
Site Name: NEWSDAY INC
NPL: N
FF: N
OU: 0
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1989-02-28 00:00:00
Finish Date: 1989-02-28 00:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202958
EPA ID: NYD052782497
Site Name: NEWSDAY INC
NPL: N
FF: N
OU: 0
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: Not reported
Finish Date: 1998-09-28 00:00:00
Qual: N
Current Action Lead: EPA Perf

RCRA-LQG:
Date form received by agency: 03/06/2014
Facility name: NEWSDAY LLC

NEWSDAY INC (Continued) **1000378809**

Facility address:	235 PINELAWN ROAD MELVILLE, NY 11747
EPA ID:	NYD052782497
Mailing address:	PINELAWN ROAD MELVILLE, NY 11747
Contact:	JOSEPH MARINO
Contact address:	PINELAWN ROAD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	631-843-2044
Contact email:	JOE.MARINO@NEWSDAY.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	Not reported
Owner/operator telephone:	516-454-2020
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	TRIBUNE ND INC
Owner/operator address:	N MICHIGAN AVENUE CHICAGO, IL 60611
Owner/operator country:	US
Owner/operator telephone:	312-222-9100
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/26/2008
Owner/Op end date:	Not reported
Owner/operator name:	NEWSDAY INC
Owner/operator address:	235 PINELAWN ROAD OPERCITY, NY 99999

NEWSDAY INC (Continued) **1000378809**

Owner/operator country: Not reported
Owner/operator telephone: 516-454-2020
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEWSDAY LLC
Owner/operator address: N MICHIGAN AVENUE
CHICAGO, IL 60611
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1979
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

NEWSDAY INC (Continued) **1000378809**

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/01/2007
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 01/16/2006
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/15/2006
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 02/18/2004
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

NEWSDAY INC (Continued) **1000378809**

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 11/19/2002
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 02/27/1998
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 06/10/1996
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/18/1994
Site name: NEWSDAY, INC.
Classification: Large Quantity Generator

Date form received by agency: 02/14/1992
Site name: NEWSDAY, INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1981
Site name: NEWSDAY INC
Classification: Large Quantity Generator

Date form received by agency: 03/01/1981
Site name: NEWSDAY INC
Classification: Not a generator, verified

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT

NEWSDAY INC (Continued) **1000378809**

MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K086
. Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U227
. Waste name: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 10/29/1980
Site name: NEWSDAY INC
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

NEWSDAY INC (Continued) **1000378809**

SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K086
. Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U227
. Waste name: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

NEWSDAY INC (Continued) **1000378809**

Area of violation: Generators - Records/Reporting
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 09/29/2015
Date achieved compliance: 10/05/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 09/29/2015
Date achieved compliance: 09/30/2015
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/05/2015
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 10/06/2015
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/25/2012
Date achieved compliance: 09/11/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2012
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/13/2012
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers

NEWSDAY INC (Continued) **1000378809**

Date violation determined: 07/25/2012
Date achieved compliance: 07/25/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2012
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/13/2012
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 12/07/2005
Date achieved compliance: 12/07/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Contingency Plan and Emergency Procedures
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 12/07/2005

NEWSDAY INC (Continued) **1000378809**

Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 12/07/2005
Date achieved compliance: 12/07/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/2005
Date achieved compliance: 07/24/2006

NEWSDAY INC (Continued) **1000378809**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/31/1997
Date achieved compliance: 06/11/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/23/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/31/1997
Date achieved compliance: 06/11/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/31/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/29/1988
Date achieved compliance: 06/16/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/03/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/1986
Date achieved compliance: 10/24/1986
Violation lead agency: State

NEWSDAY INC (Continued) **1000378809**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Records/Reporting
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 09/30/2015
Evaluation lead agency: State

Evaluation date: 09/29/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 10/05/2015
Evaluation lead agency: State

Evaluation date: 07/25/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 09/11/2012
Evaluation lead agency: State

Evaluation date: 07/25/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 07/25/2012
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

NEWSDAY INC (Continued) **1000378809**

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Records/Reporting
Date achieved compliance: 12/07/2005
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Contingency Plan and Emergency Procedures
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-General Facility Standards
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 07/24/2006
Evaluation lead agency: State

Evaluation date: 12/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 12/07/2005
Evaluation lead agency: State

Evaluation date: 03/07/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/11/1997
Evaluation lead agency: State

Evaluation date: 08/29/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 11/29/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/16/1989
Evaluation lead agency: State

Evaluation date: 05/20/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General

NEWSDAY INC (Continued) **1000378809**

Date achieved compliance: 10/24/1986
Evaluation lead agency: State

LTANKS:
Facility ID: 9201246
Site ID: 276627
Closed Date: 1998-05-27
Spill Number: 9201246
Spill Date: 1992-04-30
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 5226
Investigator: T/T/F
Referred To: Not reported
Reported to Dept: 1992-04-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1992-05-04
Spill Record Last Update: 2016-10-12
Spiller Name: JOHN TILLATSON
Spiller Company: NEWSDAY
Spiller Address: 235 PINELAWN ROAD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 300411
DEC Memo: "TANK ALONE PASSED 5/15/92. SYSTEMS TEST PASSED 5/15/92. FILL BOX REPLACED. LEAKAGE FROM COMPRESSION PIPE. CLEANUP JUST BELOW THE SURFACE MOUNTED FILL CAP, ~ 2YDS OF CONTAMINATED SOIL REMOVED"
Remarks: "25K FAILED AT -.493, DRY AS A BONE TESTER, SCDH NOTIFIED, TYREE TO DO CLEANUP"

All TTF:
Facility ID: 9201246
Spill Number: 9201246
Spill Tank Test: 1539939
Site ID: 276627
Tank Number: Not reported
Tank Size: 0
Material: 0012
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported

NEWSDAY INC (Continued) **1000378809**

Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	276627
Operable Unit ID:	968626
Operable Unit:	01
Material ID:	412574
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9709711
Site ID:	276630
Closed Date:	2009-12-11
Spill Number:	9709711
Spill Date:	1997-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1997-11-20
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-11-20
Spill Record Last Update:	2016-10-12
Spiller Name:	DAVE KRUEGER
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller County:	001
Spiller Contact:	DAVE KRUEGER
Spiller Phone:	(516) 843-5437
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	300411
DEC Memo:	"HISTORY OF PROBLEMS WITH INTERFERENCE WHEN TESTING, LATER TESTS PASSED"
Remarks:	"gross failure on system test "

All TTF:

Facility ID:	9709711
Spill Number:	9709711

NEWSDAY INC (Continued) **1000378809**

Spill Tank Test:	1545479
Site ID:	276630
Tank Number:	south
Tank Size:	25000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	1203029
Site ID:	465817
Closed Date:	2014-04-07
Spill Number:	1203029
Spill Date:	2012-06-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	hmcirrit
Referred To:	Not reported
Reported to Dept:	2012-06-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-26
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	NEWSDAY INC
Spiller Address:	235 PINELAWN ROAD
Spiller County:	999
Spiller Contact:	DJ OCONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	300411
DEC Memo:	"TANK ABANDONED IN PLACE"
Remarks:	"Tank test failure. underground 25000g"

All Materials:

Site ID:	465817
Operable Unit ID:	1215830
Operable Unit:	01
Material ID:	2213978
Material Code:	0001A

NEWSDAY INC (Continued) **1000378809**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	1000551
Facility Type:	ER
Spill Number:	1000551
DER Facility ID:	300411
Site ID:	431720
DEC Region:	1
Closed Date:	2011-03-30
Spill Cause:	Other
Spill Class:	B3
SWIS:	5226
Spill Date:	2010-04-13
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2010-04-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-14
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	NEWSDAY
Spiller Address:	235 pinelawn rd
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"3/28/11 TJD File review. All required documentation has been provided in support of spill closure. A total of 166.83 tons of petroleum impacted soils were excavated and properly disposed of during remedial process. Laboratory analysis reveals all target compounds are within acceptable concentrations. No further action is required."
Remarks:	"WOERNER IS PREPARING TO REMOVE 3 20,000GAL DIESEL TANKS, AND FOUND CONTAMINATION UNDER THE DISPENSER. HE IS NOT CERTAIN WHEN THE TANKS WILL ACTUALLY BE REMOVED BECAUSE HE MUST HAVE SHORING INSTALLED, BUT HOPES THEY WILL BE REMOVED THIS WEEK OR NEXT. (DR)"

All Materials:

Site ID:	431720
Operable Unit ID:	1183191
Operable Unit:	01
Material ID:	2177394

NEWSDAY INC (Continued) **1000378809**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0507524
Facility Type:	ER
Spill Number:	0507524
DER Facility ID:	300411
Site ID:	352993
DEC Region:	1
Closed Date:	2006-03-14
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2005-09-22
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2005-09-22
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2008-06-30
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	001
Contact Name:	JOE MARINO
DEC Memo:	"9/13/05 9:22 TELECON MARINO, INK RECLAIM MACHINE, FILTERED AND RECYCLED, AREA IS BERMED AND FLOOR IS SEALED. ESTIMATE ABOUT 100 GALS PUMPED INTO DRUMS. MACHINE WILL BE REPAIRED"
Remarks:	"BERMED AREA, CONTAINED, AND CLEANED UP. DUE TO AN O RING ON A FILTER BREAKING."

All Materials:

Site ID:	352993
Operable Unit ID:	1110463
Operable Unit:	01
Material ID:	2100493
Material Code:	0582A
Material Name:	ink
Case No.:	Not reported
Material FA:	Other
Quantity:	100.00
Units:	G

NEWSDAY INC (Continued) **1000378809**

Recovered:	100.00
Oxygenate:	Not reported
Facility ID:	0008603
Facility Type:	ER
Spill Number:	0008603
DER Facility ID:	300411
Site ID:	276623
DEC Region:	1
Closed Date:	2000-12-14
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	5226
Spill Date:	2000-10-23
Investigator:	NJACAMPO
Referred To:	Not reported
Reported to Dept:	2000-10-23
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-23
Spill Record Last Update:	2011-12-27
Spiller Name:	STEPHEN CLUFF
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	001
Contact Name:	STEPHEN CLUFF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ACAMPORA 10/24/00 STEVE CLUFF (NEWSDAY) CALLED, ACTUALLY 1000-1500 GAL SPILL, TRYING TO DETERMINE EXACT AMT, ESI ON SITE, VACCING DRAIN"
Remarks:	"spill of 100-200 gal of disel occ at the main building - spill to blacktop and a storm drain is also effected - unk cause at this time, still being investigated. Security noticed the oil coming from a vent pipe - clean up contractor fenley & nicol has been paged "

All Materials:

Site ID:	276623
Operable Unit ID:	831066
Operable Unit:	01
Material ID:	546108
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1600.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NEWSDAY INC (Continued) **1000378809**

Facility ID:	0125175
Facility Type:	ER
Spill Number:	0125175
DER Facility ID:	300411
Site ID:	276624
DEC Region:	1
Closed Date:	2004-09-16
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2001-08-27
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2001-08-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-27
Spill Record Last Update:	2009-12-10
Spiller Name:	STEPHEN CLUFF
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	001
Contact Name:	SAME
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was UNASSIGNED 01-090 "
Remarks:	"FAILURE OF HYDRAULIC HOSE ON DUMPSTER TRUCK. SPEEDY DRY APPLIED. TRUCK WAS OPERATED BY JAMAICA ASH. WILL USE ESI TO COMPLETE CLEANUP."

All Materials:

Site ID:	276624
Operable Unit ID:	849426
Operable Unit:	01
Material ID:	526504
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Facility ID:	0203990
Facility Type:	ER
Spill Number:	0203990
DER Facility ID:	224903
Site ID:	276625
DEC Region:	1
Closed Date:	2002-08-21

NEWSDAY INC (Continued) **1000378809**

Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5200
Spill Date:	2002-07-17
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2002-07-17
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-17
Spill Record Last Update:	2002-09-09
Spiller Name:	Not reported
Spiller Company:	JAMAICA ASH
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	STEPHEN CLUFF
DEC Memo:	""
Remarks:	"HYDROLIC LINE ON TRUCK BROKE *** 877-382-1737 - BEEPER ***"

All Materials:

Site ID:	276625
Operable Unit ID:	856785
Operable Unit:	01
Material ID:	518251
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Facility ID:	8907176
Facility Type:	ER
Spill Number:	8907176
DER Facility ID:	300411
Site ID:	276626
DEC Region:	1
Closed Date:	1990-08-23
Spill Cause:	Equipment Failure
Spill Class:	C1
SWIS:	5226
Spill Date:	1989-10-20
Investigator:	NJACAMPO
Referred To:	Not reported
Reported to Dept:	1989-10-20
CID:	Not reported
Water Affected:	Not reported

NEWSDAY INC (Continued) **1000378809**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1990-08-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-10-23
Spill Record Last Update:	2009-05-21
Spiller Name:	Not reported
Spiller Company:	NEWSDAY PLANT
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ACAMPORA "
Remarks:	"PUMP OVERRAN NEAR AN EMERGENCY GENERATOR & SPILLED OUT. CONFINED IN BLDG & DRAINED INTO A DRYWELL. NEWSDAY HIRED TYREE"

All Materials:

Site ID:	276626
Operable Unit ID:	932255
Operable Unit:	01
Material ID:	443973
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9312349
Facility Type:	ER
Spill Number:	9312349
DER Facility ID:	224903
Site ID:	276628
DEC Region:	1
Closed Date:	1994-03-28
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5200
Spill Date:	1994-01-21
Investigator:	BPAUSTIN
Referred To:	Not reported
Reported to Dept:	1994-01-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-03-28
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

NEWSDAY INC (Continued) **1000378809**

Remediation Phase:	0
Date Entered In Computer:	1994-01-21
Spill Record Last Update:	1994-03-29
Spiller Name:	Not reported
Spiller Company:	NEWSDAY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 03/28/94: AUSTIN ON SITE, CLEANUP COMPLETE, DISPOSAL RECPTS RECEIVED. "
Remarks:	"FUEL LINE ON TRUCK BROKE, SPILL DIKED, WILL CLEANUP TODAY,"

All Materials:

Site ID:	276628
Operable Unit ID:	990970
Operable Unit:	01
Material ID:	391330
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9706042
Facility Type:	ER
Spill Number:	9706042
DER Facility ID:	300411
Site ID:	276629
DEC Region:	1
Closed Date:	1997-12-01
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	1997-08-18
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1997-08-18
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-18
Spill Record Last Update:	2009-08-25
Spiller Name:	DAVE KRUEGER
Spiller Company:	NEWSDAY NEWSPAPER
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	001

NEWSDAY INC (Continued) **1000378809**

Contact Name:	DAVE KRUEGER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA 20-35 GALS SPILLED ONTO PAVEMENT, NO DRAINAGE BUT PADS DEPLOYED AS PRECAUTION, SPILL OCCURRED WHEN 1 HOSE FAILED DUE TO CONTINUAL CONTACT WITH COMPACTOR BODY. SPILL ONTO PAVEMENT ONLY, 10 BAGS USED AND WILL BE PICKED UP TOMORROW. NEWSDAY THEN WILL PUT WASTE INTO DRUMS FOR PROPER DISPOSAL CLEANUP BY NEWSDAY, DISPOSAL RECVD"
Remarks:	"A HYDRAULIC LINE FROM A TRASH COMPACTOR RUPTURED FROM RUBBING AGAINST A SHARP OBJECT - SPILL HAS BEEN CONTAINED WITH SPEEDY DRY"

All Materials:

Site ID:	276629
Operable Unit ID:	1049277
Operable Unit:	01
Material ID:	331649
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1610337
Facility Type:	ER
Spill Number:	1610337
DER Facility ID:	300411
Site ID:	541155
DEC Region:	1
Closed Date:	2017-11-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2017-02-14
Investigator:	RJPOCZKA
Referred To:	Not reported
Reported to Dept:	2017-02-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-02-15
Spill Record Last Update:	2017-12-18
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller Company:	999
Contact Name:	JOE MARINO
DEC Memo:	"02/15/17 0905 Hrs: Marino called- he said they have multiple tanks in a containment area that provides 110% containment. A fitting on

NEWSDAY INC (Continued) **1000378809**

one tank failed and resulted in the release of an estimated 1000gal of ink, but ONLY the containment area was impacted. They are cleaning up the spillage themselves, and hope to reuse the ink. DR 3/9/17 1045 Hrs: RJP on location. No release from containment, no remaining impacts, non-hazardous ink being recycled on-site and reused. No further action. RJP. "

Remarks: "Spill contained inside secondary containment. Clean up being completed in-house."

All Materials:

Site ID:	541155
Operable Unit ID:	1289724
Operable Unit:	01
Material ID:	2295487
Material Code:	9999
Material Name:	other - printing ink
Case No.:	Not reported
Material FA:	Other
Quantity:	1000.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	1108374
Facility Type:	ER
Spill Number:	1108374
DER Facility ID:	300411
Site ID:	456103
DEC Region:	1
Closed Date:	2011-10-03
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2011-10-01
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-10-01
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	PRE PRINT LOGISTICS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSEPH MARINO
DEC Memo:	"10/3/2011 11:30 t/c to JOSEPH MARINO, NEWSDAY -Truck from Pre Print Logistics Management, INC. (800-596-2335) was making a delivery to Newsday. -When the truck was leaving, it was noticed that it was

NEWSDAY INC (Continued) **1000378809**

leaking diesel fuel. -The driver of the truck drove off. -Aprox 5 to 6 gallons spilled at the loading dock. -No drains affected, Miller completed the cleanup. (BD) "

Remarks: "SPEEDY DRY HAS BEEN LAID ON THE SPILL CELL - 516-509-0495"

All Materials:

Site ID:	456103
Operable Unit ID:	1206248
Operable Unit:	01
Material ID:	2203291
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	1205313
Facility Type:	ER
Spill Number:	1205313
DER Facility ID:	380703
Site ID:	468240
DEC Region:	1
Closed Date:	2012-10-03
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	5226
Spill Date:	2012-08-26
Investigator:	wxprzylo
Referred To:	Not reported
Reported to Dept:	2012-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-08-26
Spill Record Last Update:	2016-10-12
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller Company:	999
Contact Name:	JOE MARINO
DEC Memo:	"08/26/12 @13:20 t/c to notifier, by Mr Marino there was broken ink feeding tube on printing machine. MEG is working on cleanup. All is contained to the printing shop, no floor drains affected or odors outside of the building. (VP)"
Remarks:	"on concrete to inside bld. c/u in progrss, ,Miller Enviro on site"

All Materials:

NEWSDAY INC (Continued) **1000378809**

Site ID:	468240
Operable Unit ID:	1218171
Operable Unit:	01
Material ID:	2216544
Material Code:	9999
Material Name:	other - ink
Case No.:	Not reported
Material FA:	Other
Quantity:	2000.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	1200716
Facility Type:	ER
Spill Number:	1200716
DER Facility ID:	300411
Site ID:	463369
DEC Region:	1
Closed Date:	2012-10-22
Spill Cause:	Other
Spill Class:	D5
SWIS:	5226
Spill Date:	2012-04-23
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2012-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-23
Spill Record Last Update:	2016-10-12
Spiller Name:	JOSEPH MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN ROAD
Spiller Company:	999
Contact Name:	JOSEPH MARINO
DEC Memo:	"04/23/12 1330 Hrs (A): Called Marino- this was a spill of combined industrial/sanitary sewage from THEIR plant. 04/23/12 1330 Hrs (B): The waste spilled onto gravel, and the plant operator (SEVERIN TRENT) is cleaning up the spillage. 04/23/12 1330 Hrs (C): Spills informed Marino we would notify DEC Div of Water. DR 04/23/12 1535 Hrs: Copy of this report emailed to Tony Leung (DEC Div of Water). DR"
Remarks:	"system had loss due to weather, no waterways, c/u in progress"

All Materials:

Site ID:	463369
Operable Unit ID:	1213465
Operable Unit:	01
Material ID:	2211426

NEWSDAY INC (Continued) **1000378809**

Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	500.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	1402877
Facility Type:	ER
Spill Number:	1402877
DER Facility ID:	300411
Site ID:	496217
DEC Region:	1
Closed Date:	2014-08-12
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2014-06-17
Investigator:	hmcirrit
Referred To:	Not reported
Reported to Dept:	2014-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-06-17
Spill Record Last Update:	2014-10-03
Spiller Name:	JOE MARINO
Spiller Company:	NEWSDAY
Spiller Address:	235 PINELAWN RD
Spiller Company:	999
Contact Name:	JOE MARINO
DEC Memo:	"06/17/14 1210 Hrs: Left message for Libuser. DR 06/17/14 1250 Hrs (A): Libuser called- apparently, a test of some sort was performed overnight on the day tank for this generator. The solenoid which opens and closes the line failed and caused the spill. 06/17/14 1250 Hrs (B): At this time, Miller believes only a few gallons of oil spilled. THE CATCH BASIN IS INSIDE THE BUILDING, AND MILLER DOES NOT BELIEVE IT HAS ANY OUTLETS. 06/17/14 1250 Hrs (C): Miller is cleaning up the floor with speedi dri, and is bringing a guzzler truck to clean out the basin. 06/17/14 1250 Hrs (D): DEC directed Miller to keep this office updated. DR DRAIN CLEANED OUT, ENDPOINT SAMPLES ARE CLEAN, NO FURTHER ACTION REQUIRED"
Remarks:	"lost from generator, c/u in progress. loss to catch basin, unknown where that releases"

All Materials:

Site ID:	496217
Operable Unit ID:	1245709

NEWSDAY INC (Continued) **1000378809**

Operable Unit: 01
Material ID: 2246745
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Site ID: 496217
Operable Unit ID: 1245709
Operable Unit: 01
Material ID: 2246746
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

ICIS:
Enforcement Action ID: NY-ETP1502
FRS ID: 110000807761
Action Name: NEWSDAY INC - MAINTENANCE
Facility Name: NEWSDAY, LLC
Facility Address: 235 PINELAWN ROAD
MELVILLE, NY 11747-4250
Enforcement Action Type: State Administrative Order of Consent
Facility County: SUFFOLK
Program System Acronym: NPDES
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: STAOCO
Facility SIC Code: 2711
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.764028
Longitude in Decimal Degrees: -73.40625
Permit Type Desc: Individual State Issued Permit (Non-NPDES)
Program System Acronym: NY0136751
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

US AIRS (AFS):
Envid: 1000378809
Region Code: 02
County Code: NY103
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
D and B Number: Not reported
Facility Site Name: NEWSDAY
Primary SIC Code: 2711

NEWSDAY INC (Continued) **1000378809**

NAICS Code: 511110
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761

NEWSDAY INC (Continued) **1000378809**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-12-19 00:00:00
Activity Status Date: 2016-05-02 12:51:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-24 00:00:00
Activity Status Date: 2016-05-02 12:51:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-09-29 00:00:00
Activity Status Date: 2016-10-09 08:02:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-09-29 00:00:00
Activity Status Date: 2016-10-09 08:02:07
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NEWSDAY INC (Continued) **1000378809**

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-09-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NEWSDAY INC (Continued) **1000378809**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-01-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NEWSDAY INC (Continued) **1000378809**

Activity Date: 2010-02-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-04-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761

NEWSDAY INC (Continued) **1000378809**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-31 00:00:00
Activity Status Date: 2007-06-04 10:27:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000001472600157
Facility Registry ID: 110000807761
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110000807761

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants.

NEWSDAY INC (Continued) **1000378809**

AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000378809
Registry ID:	110000807761
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000807761

AIRS:

Permit Type:	ASF
Permit Status:	Issued
Issue Date:	01/19/2001
Expiration Date:	Not reported
County Fips:	Not reported
DEC Id:	1472600157
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	73.406241544
Longitude:	40.764034981

NEWSDAY INC (Continued) **1000378809**

Permit Type: ASF
Permit Status: Issued
Issue Date: 07/15/2008
Expiration Date: Not reported
County Fips: Not reported
DEC Id: 1472600157
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported
Auth Type Code: 2
Latitude: 73.406241544
Longitude: 40.764034981

Permit Type: ASF
Permit Status: Issued
Issue Date: 04/05/2012
Expiration Date: Not reported
County Fips: Not reported
DEC Id: 1472600157
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported
Auth Type Code: 2
Latitude: 73.406241544
Longitude: 40.764034981

NJ MANIFEST:
EPA Id: NYD052782497
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: D
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: NJA5318585
EPA ID: NYD052782497
Date Shipped: 06/12/2006
TSDF EPA ID: NJD991291105

NEWSDAY INC (Continued) **1000378809**

Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/12/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/12/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08010625
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5314811
EPA ID:	NYD052782497
Date Shipped:	07/24/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/24/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

NEWSDAY INC (Continued) **1000378809**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/24/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126782
EPA ID:	NYD052782497
Date Shipped:	01/24/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/24/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/24/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

NEWSDAY INC (Continued) **1000378809**

Manifest Discrepancy Type:	Not reported
Data Entry Number:	03150521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5229182
EPA ID:	NYD052782497
Date Shipped:	03/21/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/21/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/21/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05090522
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5249293
EPA ID:	NYD052782497
Date Shipped:	05/02/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

NEWSDAY INC (Continued) **1000378809**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/02/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/02/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140525
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126787
EPA ID:	NYD052782497
Date Shipped:	06/22/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/22/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/22/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

NEWSDAY INC (Continued) **1000378809**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	07130421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5318254
EPA ID:	NYD052782497
Date Shipped:	04/13/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/13/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06160625
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126778
EPA ID:	NYD052782497

NEWSDAY INC (Continued) **1000378809**

Date Shipped:	09/14/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/14/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/14/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10190422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126780
EPA ID:	NYD052782497
Date Shipped:	10/12/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/12/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

NEWSDAY INC (Continued) **1000378809**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/12/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12230421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126777
EPA ID:	NYD052782497
Date Shipped:	08/31/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/31/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

NEWSDAY INC (Continued) **1000378809**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10070422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4129799
EPA ID:	NYD052782497
Date Shipped:	04/27/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/27/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/27/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05180421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126795
EPA ID:	NYD052782497
Date Shipped:	05/11/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

NEWSDAY INC (Continued) **1000378809**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/11/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/11/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05210422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126796
EPA ID:	NYD052782497
Date Shipped:	05/21/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/21/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/21/2004

NEWSDAY INC (Continued) **1000378809**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06170421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5228961
EPA ID:	NYD052782497
Date Shipped:	02/22/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/22/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/22/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04280521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NEWSDAY INC (Continued) **1000378809**

Manifest Number:	NJA4129798
EPA ID:	NYD052782497
Date Shipped:	04/13/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/13/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05170421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126775
EPA ID:	NYD052782497
Date Shipped:	10/26/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/26/2004
Date Trans2 Transported Waste:	Not reported

NEWSDAY INC (Continued) **1000378809**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/26/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12060425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126776
EPA ID:	NYD052782497
Date Shipped:	12/07/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

NEWSDAY INC (Continued) **1000378809**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01190521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126786
EPA ID:	NYD052782497
Date Shipped:	08/17/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/17/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/17/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09160421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA4126774
EPA ID:	NYD052782497
Date Shipped:	11/23/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	NJD980772768
Transporter 3 EPA ID:	Not reported

NEWSDAY INC (Continued) **1000378809**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/23/2004
Date Trans2 Transported Waste:	11/23/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/23/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01100525
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4126788
EPA ID:	NYD052782497
Date Shipped:	07/06/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/06/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NEWSDAY INC (Continued) **1000378809**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/06/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08030421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

SPDES:

Permit Number:	NY0136751
State-Region:	01
Expiration Date:	11/30/2021
Current Major Minor Status:	Minor
Primary Facility SIC Code:	Not reported
State Water Body Name:	GW
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	0.045
Total App Design Flow(MGD):	Not reported
UDF1:	DMR
Lat/Long:	40.764028 / -73.40625
DMR Cognizant Official:	JOSEPH MARINO, MGR FAC ENG
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	NEWSDAY, LLC
Non-Gov Permit Supplemental Location:	235 PINELAWN ROAD
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070

UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103

NEWSDAY INC (Continued) **1000378809**

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	NEWSDAY, LLC
Non-Gov Permit Supplemental Location:	235 PINELAWN ROAD
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	235 PINELAWN ROAD
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070
UDF2:	001702
UDF3:	GA
FIPS County Code:	NY103
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NEWSDAY, LLC
Non-Gov Permit Street Address:	235 PINELAWN ROAD
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	MELVILLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11747-4250
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEWSDAY, LLC
Non-Gov Facility Street Address:	NEWSDAY, LLC
Non-Gov Facility Supplemental Location:	235 PINELAWN ROAD
Non-Gov Facility City:	MELVILLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11747-4250
State Water Body:	02030202070

B9 **TRIBUNE COMPANY** **RCRA NonGen / NLR** **1000436935**
WNW **25 DESHON DR** **FINDS** **NYD002052504**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.015 mi. **NY MANIFEST**
77 ft. **Site 1 of 7 in cluster B**

Relative:
Higher

Actual:
108 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BELWIN MILLS
Facility address:	25 DESHON DR MELVILLE, NY 11747-4207
EPA ID:	NYD002052504
Mailing address:	NW 48TH AVE MIAMI, NY 33014
Contact:	Not reported
Contact address:	NW 48TH AVE MIAMI, NY 33014
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NET REALTY HOLDING TR
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NET REALTY HOLDING TR
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

TRIBUNE COMPANY (Continued) **1000436935**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BELWIN MILLS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BELWIN MILLS
Classification: Not a generator, verified

Date form received by agency: 12/22/1986
Site name: BELWIN MILLS
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/16/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

TRIBUNE COMPANY (Continued) **1000436935**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004337511

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019617887

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000436935
Registry ID: 110004337511
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004337511

NY MANIFEST:
Country: USA
EPA ID: NYD002052504
Facility Status: Not reported
Location Address 1: 25 DESHON DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD002052504
Mailing Name: BELWIN MILLS
Mailing Contact: JOHN KING
Mailing Address 1: 25 DESHON DRIVE
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162933400

B10
WNW
< 1/8
0.015 mi.
77 ft.

NEWSDAY
25 DESHON DR
MELVILLE, NY 11747

Site 2 of 7 in cluster B

NY AST **A100385594**
N/A

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	8596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8596
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	24284
Year Installed:	83
Substance:	INDUSTRIAL WASTE
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 92
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	11/26/1927
Tank ID:	10
Tank Key:	42357
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE

NEWSDAY (Continued) **A100385594**

Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	11
Tank Key:	42358
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	12
Tank Key:	42359
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016

NEWSDAY (Continued) **A100385594**

Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	13
Tank Key:	42360
Year Installed:	Not reported
Substance:	COOLING TOWER CHEMIC
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	6
Tank Key:	42353
Year Installed:	1991
Substance:	#2 FUEL OIL
Construction:	STEEL / STEEL
Dispenser:	SUCTION
Official Use:	Not in Compliance (Date - 82)

NEWSDAY (Continued) **A100385594**

Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	7
Tank Key:	42354
Year Installed:	Not reported
Substance:	BOILER ADDITIVE
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	140
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	8
Tank Key:	42355
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION

NEWSDAY (Continued) **A100385594**

Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

Tank ID:	9
Tank Key:	42356
Year Installed:	Not reported
Substance:	BOILER CHEM
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Permitted Tank. Permit Runs Out. 10
Permit to Operate:	8/23/2016
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	80
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

B11
WNW
< 1/8
0.015 mi.
77 ft.

NEWSDAY
25 DESHON DR
MELVILLE, NY 11747

Site 3 of 7 in cluster B

NY UST **U004219691**
N/A

Relative:
Higher

Actual:
108 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	8596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8596
Facility Reference #:	Not reported
Official Use:	Removed Tank. 89
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	2
Tank Key:	24285
Installed:	Not reported
Capacity:	15000
Substance:	#2 FUEL OIL
Date Removed:	1/4/2099
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	15000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	1/4/2099
Year Installed:	Not reported
Description of drop records:	Not reported
Tank ID:	3
Tank Key:	24286
Installed:	Not reported
Capacity:	20000

NEWSDAY (Continued) **U004219691**

Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	20000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	24287
Installed:	Not reported
Capacity:	20000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	20000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	Not reported

NEWSDAY (Continued) **U004219691**

Description of drop records:	Not reported
Tank ID:	5
Tank Key:	24288
Installed:	91
Capacity:	6000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	6000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	91
Description of drop records:	Not reported

B12 **J.M ALBRIZZIO** **NY Spills** **S102139203**
WNW **25 DESCHON DRIVE** **N/A**
< 1/8 **MELVILLE, NY**
0.015 mi.
77 ft. **Site 4 of 7 in cluster B**

Relative: **Higher**
Actual: **108 ft.**

SPILLS:

Facility ID:	9309731
Facility Type:	ER
Spill Number:	9309731
DER Facility ID:	115665
Site ID:	134618
DEC Region:	1
Closed Date:	1993-12-24
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	5226
Spill Date:	1993-11-11
Investigator:	KAKISPER
Referred To:	Not reported
Reported to Dept:	1993-11-11
CID:	Not reported
Water Affected:	Not reported

J.M ALBRIZZIO (Continued) **S102139203**

Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	1993-12-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-12
Spill Record Last Update:	2013-01-15
Spiller Name:	Not reported
Spiller Company:	J.M ALBRIZZIO
Spiller Address:	100 HARTWELL ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KISPERT 12/24/93: NO RESPONSE NEEDED. "
Remarks:	"DRIVER HIT CURB, SPILL ON ROAD & PARKING LOT, WORKING ON LEAK, CLEANING UP WITH SPEEDI DRI"

All Materials:

Site ID:	134618
Operable Unit ID:	991250
Operable Unit:	01
Material ID:	392383
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B13 **NEWSDAY** **NY Spills** **S107408321**
WNW **25 DESHON DRIVE** **N/A**
< 1/8 **MELVILLE, NY**
0.015 mi.
77 ft. **Site 5 of 7 in cluster B**

Relative: **Higher**
Actual: **108 ft.**

SPILLS:

Facility ID:	0550849
Facility Type:	ER
Spill Number:	0550849
DER Facility ID:	298602
Site ID:	351331
DEC Region:	1
Closed Date:	2005-09-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2005-08-19
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2005-08-19
CID:	Not reported
Water Affected:	NO

NEWSDAY (Continued) **S107408321**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-19
Spill Record Last Update:	2008-09-05
Spiller Name:	Not reported
Spiller Company:	NEWSDAY
Spiller Address:	25 DESHON RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"#2 oil spilled in the boiler room CLEANUP COMPLETED BY MEG 8/24 16:15 SHANAHAN CALLED, SPILLED IN BOILER ROOM, PRODUCT ENTERED DRAIN LEADING TO SEPTIC SYSTEM, CLEANED FLOOR, FLUSHED DRAIN AND SKIMMED PRODUCT OUT OF POOL, SUGGESTED HE SEND REPORT TO REGIONAL SPILL ENGINEER (DR)"
Remarks:	""

All Materials:

Site ID:	351331
Operable Unit ID:	1108851
Operable Unit:	01
Material ID:	2098823
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

B14 **TRIBUNE LLC** **NY AST** **A100264938**
WNW **25 DESHON DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.015 mi.
77 ft. **Site 6 of 7 in cluster B**

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	08656
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	08656
Billing Contact:	TRIBUNE LLC
Billing Address:	25 DESHON DR
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747

TRIBUNE LLC (Continued) **A100264938**

Storage Owner: TRIBUNE LLC
Storage Owner Address: 25 DESHON DR
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 08656
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 14
Tank Key: Not reported
Year Installed: Not reported
Substance: MOTOR OIL
Construction: REFER TO PAPER FILE
Dispenser: GRAVITY
Official Use: Not reported
Permit to Operate: Not reported
Tank Location: ABOVE - IN
Tabk Status: REMOVED
Total Capacity: 60 gallons
Date Permitted: Not reported
Date Closed: 11/08/2013
Internal Protection: NONE
Secondary Containment: NONE
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

Tank ID: 15
Tank Key: Not reported
Year Installed: Not reported
Substance: MOTOR OIL
Construction: REFER TO PAPER FILE
Dispenser: GRAVITY
Official Use: Not reported
Permit to Operate: Not reported
Tank Location: ABOVE - IN
Tabk Status: REMOVED
Total Capacity: 60 gallons
Date Permitted: Not reported
Date Closed: 11/08/2013
Internal Protection: NONE
Secondary Containment: NONE

TRIBUNE LLC (Continued) **A100264938**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	100 gallons
Date Permitted:	Not reported
Date Closed:	11/08/2013
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

B15 **TRIBUNE LLC** **NY UST** **U003537405**
WNW **25 DESHON DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.015 mi.
77 ft. **Site 7 of 7 in cluster B**

Relative: **Higher**
Actual: **108 ft.**

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	08656
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported
Owner/Storage Information:	AVAILABLE
Year:	2015

TRIBUNE LLC (Continued) **U003537405**

Facility Info:

Site Ref#:	08656
Billing Contact:	TRIBUNE LLC
Billing Address:	25 DESHON DR
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	TRIBUNE LLC
Storage Owner Address:	25 DESHON DR
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	08656
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	15000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	15000 gallons
Date Permitted:	Not reported
Date Closed:	07/26/1989
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported

TRIBUNE LLC (Continued) **U003537405**

Installed:	Not reported
Capacity:	6000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	6000 gallons
Date Permitted:	05/14/1991
Date Closed:	11/08/2013
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

C16 **EASTERN athletic** **NY UST** **U004067323**
NNE **100 RULAND RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.035 mi.
187 ft. **Site 1 of 4 in cluster C**

Relative:
Lower

Actual:
99 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	17467
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Facility Info:

Site Ref#:	17467
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	HALF HOLLOW HILLS RACQUET CLUB
Storage Owner Address:	100 RULAND RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

EASTERN ATHLETIC (Continued) **U004067323**

Tank Info:

Facility ID:	17467
Facility Reference #:	Not reported
Official Use:	Not in Compliance (Date - 81)
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	48205
Installed:	1984
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	1984
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	48206
Installed:	1984
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported

EASTERN ATHLETIC (Continued) **U004067323**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	1984
Description of drop records:	Not reported

C17 **EASTERN ATHLETIC CLUB** **NY Spills** **S110139171**
NNE **100 RULAND ROAD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.035 mi.
187 ft. **Site 2 of 4 in cluster C**

Relative: **Lower**
Actual: **99 ft.**

SPILLS:

Facility ID:	0910535
Facility Type:	ER
Spill Number:	0910535
DER Facility ID:	372191
Site ID:	423296
DEC Region:	1
Closed Date:	2009-12-28
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	5226
Spill Date:	2009-12-26
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2009-12-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-26
Spill Record Last Update:	2010-01-28
Spiller Name:	GARY ZANAZZI
Spiller Company:	EASTERN ATHLETIC CLUB
Spiller Address:	100 RULAND RD
Spiller Company:	999
Contact Name:	GARY ZANAZZI
DEC Memo:	"12/26/09 @ 3:00 PM WG spoke to John Durbin. Per John, Miller Environmental was retained the same night by the RP (Eastern Athletic Club) to perform cleanup at the site. -Cleanup has been completed. No add'l action required. (WG)"

EASTERN ATHLETIC CLUB (Continued) **S110139171**

Remarks: "unsure of what caused leak - possible plow hit fill pipe - cleanup pending - contractor enroute."

All Materials:

Site ID:	423296
Operable Unit ID:	1179109
Operable Unit:	01
Material ID:	2172679
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D18 **BUSINESS** **NY Spills** **S113818829**
SE **255 PINELAWN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.052 mi.
273 ft. **Site 1 of 8 in cluster D**

Relative: **Lower**
Actual: **103 ft.**

SPILLS:

Facility ID:	1303748
Facility Type:	ER
Spill Number:	1303748
DER Facility ID:	300660
Site ID:	484245
DEC Region:	1
Closed Date:	2013-12-16
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2013-07-08
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2013-07-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-07-08
Spill Record Last Update:	2016-10-12
Spiller Name:	JOSEPH BARBERA
Spiller Company:	NATIONAL GRID/LIPA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSEPH BARBERA
DEC Memo:	"07/08/2013-Per National Grid Incident Description: LIPA pad mount transformer released approximately 3 gallons of transformer oil onto

BUSINESS (Continued) **S113818829**

cement bottom and surrounding soil. Contractor WRS"
Remarks: "clean up will commence in 2 hours"

All Materials:
Site ID: 484245
Operable Unit ID: 1233929
Operable Unit: 01
Material ID: 2232875
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

D19 **IMPERIAL NEWS CO** **NY Spills** **1000552853**
SE **255 PINELAWN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.052 mi.
273 ft. **Site 2 of 8 in cluster D**

Relative: **Lower**
Actual: **103 ft.**

SPILLS:
Facility ID: 0906309
Facility Type: ER
Spill Number: 0906309
DER Facility ID: 300660
Site ID: 418639
DEC Region: 1
Closed Date: 2010-03-22
Spill Cause: Vandalism
Spill Class: C4
SWIS: 5226
Spill Date: 2009-08-31
Investigator: Unassigned
Referred To: Not reported
Reported to Dept: 2009-08-31
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2009-08-31
Spill Record Last Update: 2016-10-12
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: Not reported
Contact Name: PAT COSTANZO
DEC Memo: ""
Remarks: "Caller states that overnight, the meter on the diesel fuel pump for

IMPERIAL NEWS CO (Continued) **1000552853**

fueling vehicles was broken. (There is a labor stike in progrees). A driver went to fuel a vehicle, and diesel sprayed out from around broken meter. Spill was to asphalt, and a small amount may have entered a catch basin on the property. The spill to the asphalt was cleaned up. -KY"

All Materials:

Site ID:	418639
Operable Unit ID:	1174804
Operable Unit:	01
Material ID:	2167188
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	False

Facility ID:	8603300
Facility Type:	ER
Spill Number:	8603300
DER Facility ID:	300660
Site ID:	202109
DEC Region:	1
Closed Date:	1986-10-01
Spill Cause:	Other
Spill Class:	C2
SWIS:	5226
Spill Date:	1986-08-18
Investigator:	CXONEILL
Referred To:	Not reported
Reported to Dept:	1986-08-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	1986-10-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1986-08-25
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	IMPERIAL NEWS CO
Spiller Address:	255 PINELAWN ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'NEILL FD / / : DEC INVEST- 3OPTION LETTER TO BE SENT?TANKS PASSED RETEST 9/9/86 AFTER BREAKING SYPHON. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	"2 12K SIPHONED TOGETHER. -.566GPH FOR SYSTEM ONE FILL LINE HAS

IMPERIAL NEWS CO (Continued) **1000552853**

POSSIBLE AIR POCKET."

All Materials:

Site ID:	202109
Operable Unit ID:	900588
Operable Unit:	01
Material ID:	476129
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9308159
Facility Type:	ER
Spill Number:	9308159
DER Facility ID:	456664
Site ID:	202110
DEC Region:	1
Closed Date:	2004-06-02
Spill Cause:	Other
Spill Class:	B3
SWIS:	5226
Spill Date:	1993-10-05
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1993-10-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-10-06
Spill Record Last Update:	2014-11-10
Spiller Name:	Not reported
Spiller Company:	ABAND BLDG
Spiller Address:	255 PINELAWN ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA SOIL EXCAVATED"
Remarks:	"FIRST BLDG SOUTH OF NEWSDAY BLDG, SCDH PETE SCHRAMEL ON SITE, LONG TERM LEAKAGE, 3-4 HOLES ON BOTTOM OF TANK, 1/2 DIAMETER, NEEDS DEC TO RESPOND"

All Materials:

Site ID:	202110
Operable Unit ID:	986833
Operable Unit:	01

IMPERIAL NEWS CO (Continued) **1000552853**

Material ID:	394398
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D20 **CLARE ROSE** **NY Spills** **S109208314**
SE **255 PINELAWN RD/MARCUS** **N/A**
< 1/8 **MELVILLE, NY**
0.052 mi.
273 ft. **Site 3 of 8 in cluster D**

Relative: **Lower**
Actual: **103 ft.**

SPILLS:

Facility ID:	0890480
Facility Type:	ER
Spill Number:	0890480
DER Facility ID:	348940
Site ID:	399610
DEC Region:	1
Closed Date:	2009-04-30
Spill Cause:	Other
Spill Class:	B3
SWIS:	5226
Spill Date:	2008-06-12
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2008-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-06-12
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	CLARE ROSE
Spiller Address:	255 PINELAWN RD
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"***THIS SITE IS JUST NORTH OF THE HUNTINGTON/BABYLON TOWN LINE. WHEN PINELAWN CROSSES INTO BABYLON, IT BECOMES WELLWOOD AVE.*** DEC INFORMED HIM WE MUST INSPECT THE TANK AND EXCAVATION, THAT WE DID NOT HAVE AN INSPECTOR AVAILABLE TODAY, AND THAT HE SHOULD CALL THIS OFFICE TOMORROW TO DISCUSS THE SCHEDULING OF THE INSPECTION. DEC FURTHER INFORMED HIM THAT HE COULD HAVE THE TANK EMPTIED, REMOVE THE TANK, AND LEAVE THE TANK ON SITE AND THE EXCAVATION OPEN PENDING INSPECTION IF HE FELT IT WAS SAFE TO DO SO. 6/18/08 TJD 1400-1500 Site inspection. Excavation contractor (Tully Drainage) onsite

CLARE ROSE (Continued) **S109208314**

completing installation of sanitary system (cesspool rings). Upon initial notification, DEC Dave Raymond required contractor to schedule inspection with DEC prior to closure of tank grave. Contractor did not follow DEC directive and installed sanitary system in area of tank grave. Site supervisor for Tully (Mike Lucia) refused to provide specific information regarding former tank location stating that no spill occurred and DEC was wasting its time. DeMeo contacted Claire Rose representative (Patrick Costanzo) who provided contact information to Nelson & Pope surveyor (Tom Lembo) who was onsite for removal. Nelson & Pope was contacted and provided additional information required to access reported spill event including: SCDOH inspector visited site following tank removal, ESI was contractor who pumped tank & site plan was updated to include former tank location. A copy of updated site plan was requested. DEC contacted SCDOH Bob Seafarth stated his inspector (Zachary Baldwin) was onsite for removal and he would forward a copy of tank removal report. 6/19/08 TJD T/C with Joe Parisi @ ESI. Joe states he was hired to pump liquid contents from tank upon its discovery. He further states tank was filled to capacity with water following pump out he remained onsite for tank removal. Tank reported to be in good condition with no reported holes. 4/30/09 TJD File review. Updated survey depicting tank location received from Nelson & Pope. Tank removal checklist received from SCDOH no contamination noted. Based upon review of available information no further action is required.
TOM LEMBO NELSON & POPE 631-427-5665 C 516-524-3535 JANET 854-2513 BOB 854-2518 PATRICK CONSTANZO SAFETY 631-454-2337 X155 MIKE LUCION ZACHARY BALDWIN "

Remarks: "THEY WERE EXCAVATING FOR A NEW CESSPOOL AND ENCOUNTERED A PREVIOUSLY ABANDONED TANK. HE BELIEVES IT MAY BE 1000 GAL IN SIZE. THE TANK CONTAINED WATER AND HAD A GASOLINE ODOR, AND SOME OF THE WATER INSIDE THE TANK SPILLED INTO THE EXCAVATION. HE HAD INITIALLY CALLED JOE PARISI OF ESI, WHO ADVISED HIM TO CALL DEC."

All Materials:

Site ID:	399610
Operable Unit ID:	1156474
Operable Unit:	01
Material ID:	2147404
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D21 **CLARE ROSE** **NY UST U003842808**
SE **255 CNTY RD 3 PINELAWN RD** **NY AST N/A**
< 1/8 **MELVILLE, NY 11747**
0.052 mi.
273 ft. **Site 4 of 8 in cluster D**

Relative: SUFFOLK CO. UST:
Lower

Region:	SUFFOLK
Site Ref#:	7581
Status:	Not reported

Actual:
103 ft.

CLARE ROSE (Continued) **U003842808**

Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 7581
Facility Reference #: Not reported
Official Use: Removed Tank. 94
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 21839
Installed: 72
Capacity: 10000
Substance: #2 FUEL OIL
Date Removed: 4/7/2044
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 10000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: PUMPED
Date Removed: 4/7/2044
Year Installed: 72
Description of drop records: Not reported

Tank ID: 2
Tank Key: 21840
Installed: 79
Capacity: 10000
Substance: #2 FUEL OIL
Date Removed: 4/7/2044
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 10000

CLARE ROSE (Continued) **U003842808**

Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	4/7/2044
Year Installed:	79
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	21841
Installed:	78
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	4/7/2044
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	4/7/2044
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	21842
Installed:	78
Capacity:	500
Substance:	WASTE OIL

CLARE ROSE (Continued) **U003842808**

Date Removed:	1/21/2039
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	1/21/2039
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	21843
Installed:	79
Capacity:	12000
Substance:	DIESEL
Date Removed:	10/13/2038
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	12000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/13/2038
Year Installed:	79
Description of drop records:	Not reported

CLARE ROSE (Continued) **U003842808**

Tank ID:	6
Tank Key:	21844
Installed:	79
Capacity:	2000
Substance:	GASOLINE
Date Removed:	10/13/2038
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/13/2038
Year Installed:	79
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	21845
Installed:	78
Capacity:	12000
Substance:	DIESEL
Date Removed:	10/13/2038
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	12000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

CLARE ROSE (Continued) **U003842808**

Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/13/2038
Year Installed:	78
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	21846
Installed:	79
Capacity:	8000
Substance:	GASOLINE
Date Removed:	10/13/2038
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/13/2038
Year Installed:	79
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	21847
Installed:	Not reported
Capacity:	550
Substance:	OIL/WATER SEPARATOR
Date Removed:	5/30/2175
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported

CLARE ROSE (Continued) **U003842808**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	5/30/2175
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	21848
Installed:	Not reported
Capacity:	550
Substance:	OIL/WATER SEPARATOR
Date Removed:	5/30/2175
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	5/30/2175
Year Installed:	Not reported
Description of drop records:	Not reported

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	7581
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7581

CLARE ROSE (Continued) **U003842808**

Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	11
Tank Key:	21849
Year Installed:	Not reported
Substance:	DIESEL
Construction:	Not reported
Dispenser:	SUCTION
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Tank ID:	12
Tank Key:	48463
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

CLARE ROSE (Continued) **U003842808**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	13
Tank Key:	48464
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	14
Tank Key:	48465
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

CLARE ROSE (Continued) **U003842808**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	15
Tank Key:	48466
Year Installed:	Not reported
Substance:	DIESEL
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	651
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

D22 **CLARE ROSE INC** **NY AST** **A100383150**
SE **255 PINELAWN RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.052 mi.
273 ft. **Site 5 of 8 in cluster D**

Relative: **Lower**

Actual: **103 ft.**

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	01373
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	10/31/2019
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	01373
Billing Contact:	CLARE ROSE INC
Billing Address:	255 PINELAWN RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747

CLARE ROSE INC (Continued) **A100383150**

Storage Owner: CLARE ROSE INC
Storage Owner Address: 255 PINELAWN RD
Storage Owner City: MELVILLE
Storage Owner State: NY
Storage Owner Zip: 11747

Tank Info:
Facility ID: 01373
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 12
Tank Key: Not reported
Year Installed: Not reported
Substance: #2 FUEL OIL
Construction: STEEL/ IRON
Dispenser: SUCTION
Official Use: Not reported
Permit to Operate: Not reported
Tank Location: ABOVE - IN
Tabk Status: IN SERVICE
Total Capacity: 275 gallons
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: NONE
Secondary Containment: NONE
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

Tank ID: 13
Tank Key: Not reported
Year Installed: Not reported
Substance: MOTOR OIL
Construction: STEEL/ IRON
Dispenser: Not reported
Official Use: Not reported
Permit to Operate: Not reported
Tank Location: ABOVE - IN
Tabk Status: IN SERVICE
Total Capacity: 250 gallons
Date Permitted: 06/29/2010
Date Closed: Not reported
Internal Protection: NONE
Secondary Containment: DIKE - STEEL

CLARE ROSE INC (Continued) **A100383150**

Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	14
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	IN SERVICE
Total Capacity:	250 gallons
Date Permitted:	06/29/2010
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	DIKE - STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	15
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	OTHER - PLEASE LIST
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	670 gallons
Date Permitted:	06/29/2010
Date Closed:	Not reported
Internal Protection:	Not reported

CLARE ROSE INC (Continued) **A100383150**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	17
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	OTHER - PLEASE LIST
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	1000 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	18
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	SUBMERSIBLE
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2000 gallons
Date Permitted:	03/12/2010
Date Closed:	Not reported

CLARE ROSE INC (Continued) **A100383150**

Internal Protection:	NONE
Secondary Containment:	OTHER
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

D23 **IMPERIAL NEWS** **RCRA NonGen / NLR** **1004757764**
SE **255 PINELAWN RD** **FINDS** **NYD986952588**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.052 mi. **NY MANIFEST**
273 ft. **Site 6 of 8 in cluster D**

Relative: **Lower**

Actual: **103 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	IMPERIAL NEWS
Facility address:	255 PINELAWN RD MELVILLE, NY 11747
EPA ID:	NYD986952588
Mailing address:	SMITH ST FARMINGDALE, NY 11735
Contact:	OLGA RAY
Contact address:	SMITH ST FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	516-752-2255
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DALE NEWS CO
Owner/operator address:	303 SMITH ST FARMINGDALE, NY 11735
Owner/operator country:	US
Owner/operator telephone:	516-752-2255
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DALE NEWS CO
Owner/operator address:	303 SMITH ST FARMINGDALE, NY 11735

IMPERIAL NEWS (Continued) **1004757764**

Owner/operator country: US
Owner/operator telephone: 516-752-2255
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: IMPERIAL NEWS
Classification: Not a generator, verified

Date form received by agency: 05/17/1991
Site name: IMPERIAL NEWS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004466809

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

IMPERIAL NEWS (Continued) **1004757764**

ECHO:
- Envid: 1004757764
- Registry ID: 110004466809
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004466809

NY MANIFEST:
- Country: USA
- EPA ID: NYD986952588
- Facility Status: Not reported
- Location Address 1: 255 PINELAWN ROAD
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: MELVILLE
- Location State: NY
- Location Zip: 11747
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYD986952588
- Mailing Name: IMPERIAL NEWS
- Mailing Contact: IMPERIAL NEWS
- Mailing Address 1: 255 PINELAWN ROAD
- Mailing Address 2: Not reported
- Mailing City: MELVILLE
- Mailing State: NY
- Mailing Zip: 11747
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 0007528502

D24 **CLARE ROSE** **NY Spills** **S103566566**
SE **255 PINE LAWN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.052 mi.
273 ft. **Site 7 of 8 in cluster D**

Relative: **Lower**
Actual: **103 ft.**

SPILLS:
- Facility ID: 9402856
- Facility Type: ER
- Spill Number: 9402856
- DER Facility ID: 265498
- Site ID: 329995
- DEC Region: 1
- Closed Date: 1994-11-09
- Spill Cause: Other
- Spill Class: C3
- SWIS: 5226
- Spill Date: 1994-05-26
- Investigator: GIBBONS
- Referred To: Not reported
- Reported to Dept: 1994-05-27
- CID: Not reported
- Water Affected: Not reported
- Spill Source: Commercial/Industrial
- Spill Notifier: Health Department

CLARE ROSE (Continued) **S103566566**

Cleanup Ceased:	1994-11-09
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-31
Spill Record Last Update:	2016-10-12
Spiller Name:	Not reported
Spiller Company:	CLARE ROSE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"DISPOSAL RECPTS REC'VD, NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"10K #2 F/O TANK, TANK REMOVAL, 10-20 YDS CLEANED UP, REMOVED 2-10K, 8K TURNED OUT TO BE 10K ALSO, 1-3K, NO HOLES, TANKS WERE OK, SPILLAGE CAME FROM TOP OF TANK,SOIL CLEANED OUT & STOCKPILED ON SITE"

All Materials:

Site ID:	329995
Operable Unit ID:	999881
Operable Unit:	01
Material ID:	383026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D25 **CLARE ROSE INC** **NY UST** **U004199756**
SE **255 PINELAWN RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.052 mi.
273 ft. **Site 8 of 8 in cluster D**

Relative: **Lower**

Actual: **103 ft.**

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	01373
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	10/31/2019
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	01373
Billing Contact:	CLARE ROSE INC
Billing Address:	255 PINELAWN RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CLARE ROSE INC
Storage Owner Address:	255 PINELAWN RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY

CLARE ROSE INC (Continued) **U004199756**

Storage Owner Zip: 11747

Tank Info:
Facility ID: 01373
Facility Reference #: Not reported
Official Use: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: Not reported
Installed: Not reported
Capacity: 10000 gallons
Substance: #2 FUEL OIL
Date Removed: Not reported
Construction: STEEL/ IRON
Dispenser: SUCTION
Fill Type: Not reported
Tank Location: UNDER - OUT
Tabk Status: REMOVED
Total Capacity: 10000 gallons
Date Permitted: Not reported
Date Closed: 05/26/1994
Internal Protection: NONE
Secondary Containment: NONE
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported
Year Installed: Not reported
Description of drop records: Not reported

Tank ID: 2
Tank Key: Not reported
Installed: Not reported
Capacity: 10000 gallons
Substance: #2 FUEL OIL
Date Removed: Not reported
Construction: STEEL/ IRON
Dispenser: SUCTION
Fill Type: Not reported
Tank Location: UNDER - OUT
Tabk Status: REMOVED
Total Capacity: 10000 gallons
Date Permitted: Not reported
Date Closed: 05/26/1994

CLARE ROSE INC (Continued) **U004199756**

Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/26/1994
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	500 gallons
Substance:	WASTE OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON

CLARE ROSE INC (Continued) **U004199756**

Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	500 gallons
Date Permitted:	Not reported
Date Closed:	05/07/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

CLARE ROSE INC (Continued) **U004199756**

Tank ID:	6
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	2000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	7
Tank Key:	Not reported
Installed:	Not reported
Capacity:	12000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	12000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

CLARE ROSE INC (Continued) **U004199756**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	8000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	8000 gallons
Date Permitted:	Not reported
Date Closed:	05/06/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

26
WSW
< 1/8
0.071 mi.
375 ft.

PATTERSON BUILDING
25 DESHON DR/MARCUS
HUNTINGTON, NY

NY Spills **S105142322**
N/A

Relative:
Higher

Actual:
105 ft.

SPILLS:

Facility ID:	0106454
Facility Type:	ER
Spill Number:	0106454
DER Facility ID:	258870
Site ID:	321344
DEC Region:	1
Closed Date:	2001-09-27
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2001-09-20
Investigator:	HMCIRRIT

PATTERSON BUILDING (Continued) **S105142322**

Referred To:	Not reported
Reported to Dept:	2001-09-20
CID:	323
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-20
Spill Record Last Update:	2009-11-10
Spiller Name:	Not reported
Spiller Company:	INDEPENDENT COURIER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	STEVEN CLUFF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CIRRITO 9/20 CLUFF CALLED, INDEPENDENT COURIER IS LISTED ON THE TRUCK, BUT THE NAME OF ACTUAL OWNER IS UNKNOWN, ESTIMATE 5-10 GALS, POSSIBLY SOME IN DRAIN IN ENTRANCE TO PARKING LOT, HAVE HIRED ESI, ASKED FOR UPDATE 9/20 11:15 JOE PARISI, ESI, CALLED, HAVE FINISHED CLEANING UP, TOOK PRODUCT, WATER AND IMPACTED SEDIMENT OUT OF DRAIN, WILL TAKE ENDPOINT, ARE WE RESPONDING, PERHAPS LATER 9/20 11:20 HC RETURNING FROM HICKSVILLE, WILL CHECK OILY WATER VAC FROM DRAIN, CONT SOIL GUZZLED FROM DRAIN, CLEAN ENDPOINT SAMPLE (CONFIRMATORY) DISPOSAL MANIFESTS FOR WATER AND SOIL REC'VD"
Remarks:	"line failure on the truck. spill being cleaned up."

All Materials:

Site ID:	321344
Operable Unit ID:	844709
Operable Unit:	01
Material ID:	531309
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C27 **UNKNOWN** **NY Spills** **S102567861**
NNE **PINE LAWN & RULAN ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.073 mi.
383 ft. **Site 3 of 4 in cluster C**

Relative: **Lower**

Actual: **98 ft.**

SPILLS:

Facility ID:	8600899
Facility Type:	ER
Spill Number:	8600899
DER Facility ID:	239693
Site ID:	296193

UNKNOWN (Continued) **S102567861**

DEC Region:	1
Closed Date:	1987-04-22
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	5226
Spill Date:	1986-05-06
Investigator:	PAREJA
Referred To:	Not reported
Reported to Dept:	1986-05-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1987-04-22
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-06-05
Spill Record Last Update:	2006-02-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was PAREJA FD / / : F.D. FLUSHED INTO DRAINAGE. 5/6/86 SITE CHECKED.SPILLER REMOVED LESS THAN 1 YD. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"TRACTOR TRAILER"

All Materials:

Site ID:	296193
Operable Unit ID:	898574
Operable Unit:	01
Material ID:	477466
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C28 **UNKNOWN** **NY Spills** **S106015354**
NNE **PINELAWN ROAD/RULAND ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.073 mi.
383 ft. **Site 4 of 4 in cluster C**

Relative: SPILLS:
Lower

Facility ID:	0303103
Facility Type:	ER
Spill Number:	0303103

Actual:
98 ft.

UNKNOWN (Continued) **S106015354**

DER Facility ID:	96945
Site ID:	110727
DEC Region:	1
Closed Date:	2003-07-02
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	5226
Spill Date:	2003-06-24
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	2003-06-24
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-24
Spill Record Last Update:	2009-06-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MELVILLE FIRE DEPT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was YAGER SPOKE WITH TUCKER-SAYS ONE SADDLE TANK IS BEGINNING TO LEAK, OIL ON ROADWAY, HE HAS NO ADDITIONAL INFORMATION TELECON WITH BOB WARREN-MELVILLE FIRE CHIEF, TOW TRUCK IS THERE, BUT IS AFRAID THAT SADDLE TANK WILL LEAK SO IT WON'T BE MOVED UNTIL TANK PUMPED OUT, TOWN OF HUNTINGTON IS ENROUTE AND WILL COORDINATE CLEANUP OF ROADWAY 7/1/03 FILE REASSIGNED 10:50 SPOKE WITH MATT GROSS, CLEANUP CREW ENROUTE, SPILL WAS ABOUT 20-25 GALLONS 15:30 SPOKE WITH MATT,COMPANY IS COMPLETING CLEANUP ON THEIR OWN"
Remarks:	"Traffic accident at above location. Fire dept on scene and attempting to contain material. Fire dept is requesting callback from regional office in reference to the situation."

All Materials:

Site ID:	110727
Operable Unit ID:	870842
Operable Unit:	01
Material ID:	503980
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E29
WNW
< 1/8
0.083 mi.
440 ft.

LINOTYPE-HELL CO
80 RULAND RD
MELVILLE, NY 11747

Site 1 of 3 in cluster E

NY AST **1006305092**
N/A

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	7760
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7760
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	22405
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Tank ID:	2
Tank Key:	22406
Year Installed:	Not reported
Substance:	PHOTO WASTEWATER
Construction:	Not reported
Dispenser:	SUBMERSIBLE
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE

LINOTYPE-HELL CO (Continued) **1006305092**

Tabk Status:	Not reported
Total Capacity:	100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported

E30 **HEIDELBERG PUBLISHING SERVICES** **RCRA NonGen / NLR** **1000274264**
WNW **80 RULAND RD** **FINDS** **NYD986885457**
< 1/8 **MELVILLE, NY 11747** **ECHO**
0.083 mi. **NY MANIFEST**
440 ft. **Site 2 of 3 in cluster E**

Relative:
Higher

Actual:
108 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	HEIDELBERG PUBLISHING SERVICES
Facility address:	80 RULAND RD MELVILLE, NY 11747
EPA ID:	NYD986885457
Mailing address:	RULAND RD MELVILLE, NY 11747
Contact:	RICHARD LUHRS
Contact address:	RULAND RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	516-753-4888
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HEIDELBERG PUBLISHING SERVICES
Owner/operator address:	80 RULAND RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-753-4800
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Owner/operator name: HEIDELBERG PUBLISHING SERVICES
Owner/operator address: 80 RULAND RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 516-753-4800
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: HEIDELBERG PUBLISHING SERVICES
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: HEIDELBERG PUBLISHING
Classification: Large Quantity Generator

Date form received by agency: 12/11/1998
Site name: HEIDELBERG PUBLISHING SERVICES
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004440123

HEIDELBERG PUBLISHING SERVICES (Continued) **1000274264**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019811220

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000274264
Registry ID: 110004440123
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004440123

NY MANIFEST:
Country: USA
EPA ID: NYD986885457
Facility Status: Not reported
Location Address 1: 80 RULAND RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986885457
Mailing Name: LINOTYPE-HELL CO
Mailing Contact: JAMES MALLILO
Mailing Address 1: 80 RULAND RD
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5164843000

F31 **WOODBOURNE CULTURAL NSYS INC** **NY UST U003537562**
NNE **301 COLONIAL SPRING RD** **NY AST N/A**
< 1/8 **MELVILLE, NY 11747**
0.084 mi.
441 ft. **Site 1 of 3 in cluster F**

Relative:
Lower

Actual:
97 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7529
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7529
Facility Reference #:	Not reported
Official Use:	Removed Tank. 92
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	21758
Installed:	82
Capacity:	3000
Substance:	GASOLINE
Date Removed:	7/14/2044
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	7/14/2044
Year Installed:	82
Description of drop records:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/27/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Description of drop records:	Not reported

Tank ID:	2
Tank Key:	21759
Installed:	82
Capacity:	3000
Substance:	GASOLINE
Date Removed:	10/22/2044
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/22/2044
Year Installed:	82
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	1000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	1000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	21760
Installed:	82
Capacity:	1000
Substance:	DIESEL
Date Removed:	10/22/2044
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	10/22/2044
Year Installed:	82
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	4000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	4000 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	21761
Installed:	92
Capacity:	4000
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	21762
Installed:	92
Capacity:	2500
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Tank Key:	44454
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	8/27/1927
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	8/27/1927
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2001
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	44455
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	44456
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	44457
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	44458
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Tank ID:	12
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	03/08/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13
Tank Key:	44459
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Region:	SUFFOLK
Site Ref#:	12333
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	01/31/2018
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	12333
Billing Contact:	CAROLE PITTLEMAN
Billing Address:	301 COLONIAL SPRINGS RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CAROLE PITTLEMAN
Storage Owner Address:	301 COLONIAL SPRINGS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Storage Owner Zip: 11747

Tank Info:
Facility ID: 7529
Facility Reference #: Not reported
Official Use: Removed Tank. 92
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 21758
Installed: 82
Capacity: 3000
Substance: GASOLINE
Date Removed: 7/14/2044
Construction: STEEL
Dispenser: SUCTION
Fill Type: GRAVITY
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 3000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: GRAVITY
Date Removed: 7/14/2044
Year Installed: 82
Description of drop records: Not reported

Tank ID: 1
Tank Key: Not reported
Installed: Not reported
Capacity: 3000 gallons
Substance: GASOLINE
Date Removed: Not reported
Construction: STI-P3 PROTECTED STEEL
Dispenser: SUCTION
Fill Type: Not reported
Tank Location: UNDER - OUT
Tabk Status: REMOVED
Total Capacity: 3000 gallons
Date Permitted: Not reported
Date Closed: 05/27/1992

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	21759
Installed:	82
Capacity:	3000
Substance:	GASOLINE
Date Removed:	10/22/2044
Construction:	STEEL

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/22/2044
Year Installed:	82
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	1000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	STI-P3 PROTECTED STEEL
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	1000 gallons
Date Permitted:	Not reported
Date Closed:	05/28/1992
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Tank ID:	3
Tank Key:	21760
Installed:	82
Capacity:	1000
Substance:	DIESEL
Date Removed:	10/22/2044
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	10/22/2044
Year Installed:	82
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	Not reported
Installed:	Not reported
Capacity:	4000 gallons
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	4000 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	4
Tank Key:	21761
Installed:	92
Capacity:	4000
Substance:	GASOLINE
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	21762
Installed:	92
Capacity:	2500
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported
Year Installed:	92
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	Not reported
Installed:	Not reported
Capacity:	2500 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	2500 gallons
Date Permitted:	07/30/1992
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	Not reported
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	44454
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	8/27/1927
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	8/27/1927
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	8
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2001
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	9
Tank Key:	44455
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Description of drop records:	Not reported

Tank ID:	10
Tank Key:	44456
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	11
Tank Key:	44457
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	44458
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	01/01/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13
Tank Key:	Not reported
Installed:	Not reported
Capacity:	275 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	275 gallons
Date Permitted:	Not reported
Date Closed:	03/08/2013
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Tank Key:	44459
Installed:	Not reported
Capacity:	275
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	7529
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7529
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	6
Tank Key:	44353
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL / STEEL
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 07
Permit to Operate:	7/25/2231
Tank Location:	ABOVE
Tabk Status:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **U003537562**

Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	44354
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	STEEL / STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	5/17/2206

F32
NNE
< 1/8
0.084 mi.
441 ft.

WOODBOURNE CULTURAL NSYS INC
301 COLONIAL SPRING RD
MELVILLE, NY 11747

Site 2 of 3 in cluster F

NY AST **A100385672**
N/A

Relative:
Lower

Actual:
97 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	12333
Status:	ACTIVE
Site Type:	PBS
Operating Permit Expires:	01/31/2018
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	12333
Billing Contact:	CAROLE PITTLEMAN
Billing Address:	301 COLONIAL SPRINGS RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	CAROLE PITTLEMAN
Storage Owner Address:	301 COLONIAL SPRINGS RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	12333
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	14
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	15
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	16
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	DIESEL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	UNREGISTERED
Total Capacity:	550 gallons
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	WASTE OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - OUT
Tabk Status:	IN SERVICE
Total Capacity:	275 gallons
Date Permitted:	12/11/2002
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	Not reported
Year Installed:	Not reported
Substance:	MOTOR OIL
Construction:	STEEL/ IRON
Dispenser:	Not reported
Official Use:	Not reported
Permit to Operate:	Not reported
Tank Location:	ABOVE - IN
Tabk Status:	REMOVED
Total Capacity:	200 gallons
Date Permitted:	Not reported
Date Closed:	11/19/2002
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - EPOXY COATED STEEL
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

WOODBOURNE CULTURAL NSYS INC (Continued) **A100385672**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

F33 **WOODBOURNE CULTURAL** **NY Spills** **S109063004**
NNE **301 COLONIAL SPRINGS ROAD** **N/A**
< 1/8 **MELVILLE, NY**
0.084 mi.
441 ft. **Site 3 of 3 in cluster F**

Relative: **Lower**

Actual: **97 ft.**

SPILLS:

Facility ID:	0801935
Facility Type:	ER
Spill Number:	0801935
DER Facility ID:	347368
Site ID:	397985
DEC Region:	1
Closed Date:	2008-10-30
Spill Cause:	Other
Spill Class:	C4
SWIS:	5226
Spill Date:	2008-05-19
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-05-19
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-19
Spill Record Last Update:	2010-03-23
Spiller Name:	ROGER
Spiller Company:	WOODBOURNE CULTURAL
Spiller Address:	301 COLONIAL SPRINGS RD
Spiller Company:	001
Contact Name:	ROGER
DEC Memo:	""
Remarks:	"ABOUT 1 CUP OF MATERIAL WAS SPILLED; POROUS TANK; CUSTOMER IS CLEANING IT UP;"

All Materials:

Site ID:	397985
Operable Unit ID:	1154901
Operable Unit:	01
Material ID:	2145735
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

WOODBOURNE CULTURAL (Continued) **S109063004**

Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

E34 **OTTO KEIL FLORIST** **NY AST** **A100197467**
WNW **107 RULAND RD** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.104 mi.
551 ft. **Site 3 of 3 in cluster E**

Relative:
Higher

Actual:
108 ft.

AST_SUFFOLK:
Region: SUFFOLK
Site Ref#: 7769
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 7769
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 1
Tank Key: 22425
Year Installed: Not reported
Substance: #2 FUEL OIL
Construction: Not reported
Dispenser: SUCTION
Official Use: Plans have been approved and awaiting construction
Permit to Operate: Not reported
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 5000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: PUMPED
Date Removed: Not reported

G35 **MRP FAMILY HOLDINGS LLC** **NY UST** **U003961357**
South **101 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.105 mi.
553 ft. **Site 1 of 7 in cluster G**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	16483
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Facility Info:

Site Ref#:	16483
Billing Contact:	Not reported
Billing Address:	Not reported
Billing Address:	Not reported
Billing State:	Not reported
Billing Zip:	Not reported
Storage Owner:	MRP FAMILY HOLDINGS LLC
Storage Owner Address:	1500 OLD NORTHERN BLVD
Storage Owner City:	ROSLYN
Storage Owner State:	NY
Storage Owner Zip:	11576

Tank Info:

Facility ID:	16483
Facility Reference #:	Not reported
Official Use:	Removed Tank. 03
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	45061
Installed:	Not reported
Capacity:	15000
Substance:	#2 FUEL OIL
Date Removed:	1/26/2151
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	15000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

MRP FAMILY HOLDINGS LLC (Continued) **U003961357**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	1/26/2151
Year Installed:	Not reported
Description of drop records:	Not reported

G36 **PERGAMENT HOME CENTER** **NY Spills S104951564**
South **101 MARCUS DRIVE** **NY MANIFEST N/A**
< 1/8 **MELVILLE, NY**
0.105 mi.
553 ft. **Site 2 of 7 in cluster G**

Relative: **Lower**

Actual: **102 ft.**

SPILLS:

Facility ID:	0013423
Facility Type:	ER
Spill Number:	0013423
DER Facility ID:	417281
Site ID:	328273
DEC Region:	1
Closed Date:	2001-10-03
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	5226
Spill Date:	2001-03-23
Investigator:	DONOVAN
Referred To:	Not reported
Reported to Dept:	2001-03-23
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-23
Spill Record Last Update:	2012-04-11
Spiller Name:	BRIAN RAMOS
Spiller Company:	IMPACT ENVIROMENTAL
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	DAVE LORTHIOIR
DEC Memo:	"3/23 SPOKE TO DAN PERKOWSKI, F&N, WILL GET INFO AND CALL BACK 13:28 TELECON DAVE LORTHIOIR, SOMEONE DOING LINE TEST, SOMEWHERE THERE AS LINE THAT WAS CUT BUT NOT CAPPED,LEAK IN BOILER ROOM AND INTO PARKING LOT, NO DRAINS AFFECTED SAME AS 00-13428 F&N CLEANING WITH SPEEDI DRI, F&N REPORTED THAT THEY ARE SENDING GUZZLER INSTEAD OF DRUMMING SOLIDS SPILL CONTAINED ON PAVED SURFACE. NO SOIL AFFECTED, SPEEDI DRI PLACED, SWEPT AND DISPOSED OF BY F&N, NO FURTHER ACTION"
Remarks:	"DURING A LINE TEST AT ABOVE LOCATION EMPLOYEE FAILED TO CAP OFF A VALVE IN BOILER ROOM CAUSING ABOVE MATERIAL TO BE SPILLED. CREW ENROUTE FOR CLEANUP AND ALL MATERIAL IS EXPECTED TO BE RECOVERED.

PERGAMENT HOME CENTER (Continued) **S104951564**

SAME AS 0013428"

All Materials:

Site ID:	328273
Operable Unit ID:	834913
Operable Unit:	01
Material ID:	540135
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0013428
Facility Type:	ER
Spill Number:	0013428
DER Facility ID:	417281
Site ID:	328274
DEC Region:	1
Closed Date:	2001-03-23
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	5226
Spill Date:	2001-03-23
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2001-03-23
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-23
Spill Record Last Update:	2012-04-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RUSS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE ***SAME AS 0013423***"
Remarks:	"caller was on site doing tank test and pipe leading to boiler failed causing spill - clean up in progress. ***SAME AS 0013423***"

All Materials:

Site ID:	328274
Operable Unit ID:	835371
Operable Unit:	01
Material ID:	540139

PERGAMENT HOME CENTER (Continued) **S104951564**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP000736259
Facility Status:	Not reported
Location Address 1:	101 MARCUS DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000736259
Mailing Name:	PERGAMENT HOME CENTER
Mailing Contact:	PERGAMENT HOME CENTER
Mailing Address 1:	101 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

G37 **RACANELLI COMMERCIAL BUILDING** **NY UST** **U003844038**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.120 mi.
634 ft. **Site 3 of 7 in cluster G**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	11311
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	11311
Billing Contact:	N RACANELLI ASSOC
Billing Address:	200 MOTOR PKY STE C20
Billing Address:	HAUPPAUGE
Billing State:	NY

RACANELLI COMMERCIAL BUILDING (Continued) **U003844038**

Billing Zip:	11788
Storage Owner:	N RACANELLI ASSOC
Storage Owner Address:	200 MOTOR PKY STE C20
Storage Owner City:	HAUPPAUGE
Storage Owner State:	NY
Storage Owner Zip:	11788

Tank Info:

Facility ID:	11311
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	3000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	3000 gallons
Date Permitted:	Not reported
Date Closed:	10/27/2014
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	NONE
Leak Detection:	NONE (NON-EXEMPT)
Overfill Prevention:	- Vent Whistle
Spill Prevention:	NONE (NON-EXEMPT)
Pipe Location:	UNDERGROUND ONLY
Pipe Type:	OTHER
Pipe External Protection:	NONE
Pipe Containment:	OTHER
Pipe Leak Detection:	TIGHTNESS TESTING
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

G38 **RACANELLI COMMERCIAL BUILDING** **NY AST** **A100456216**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.120 mi.
634 ft. **Site 4 of 7 in cluster G**

Relative:
Lower

Actual:
102 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	11311
Status:	INACTIVE
Site Type:	PBS
Operating Permit Expires:	Not reported
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	11311
Billing Contact:	N RACANELLI ASSOC
Billing Address:	200 MOTOR PKY STE C20
Billing Address:	HAUPPAUGE
Billing State:	NY
Billing Zip:	11788
Storage Owner:	N RACANELLI ASSOC
Storage Owner Address:	200 MOTOR PKY STE C20
Storage Owner City:	HAUPPAUGE
Storage Owner State:	NY
Storage Owner Zip:	11788

G39 **DON JAGODA INC** **NY UST** **U004219566**
SSE **102 MARCUS DR** **N/A**
< 1/8 **MELVILLE, NY 11747**
0.120 mi.
634 ft. **Site 5 of 7 in cluster G**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7203
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7203
Facility Reference #:	Not reported
Official Use:	Heating Oil Tanks Greater Than 1100 Gallons. Next test. 04
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	20534
Installed:	Not reported
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION

DON JAGODA INC (Continued) **U004219566**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

G40 **RACANELLI ASSOCIATES** **NY LTANKS** **S100147328**
South **100 MARCUS DRIVE** **N/A**
1/8-1/4 **MELVILLE, NY**
0.129 mi.
679 ft. **Site 6 of 7 in cluster G**

Relative: LTANKS:
Lower

Actual:
101 ft.

Facility ID:	8805457
Site ID:	99721
Closed Date:	1988-09-30
Spill Number:	8805457
Spill Date:	1988-09-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-09-30
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-09-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-30
Spill Record Last Update:	2006-06-07
Spiller Name:	Not reported
Spiller Company:	RACANELLI ASSOCIATES
Spiller Address:	200 MOTOR PARKWAY
Spiller County:	001

RACANELLI ASSOCIATES (Continued) **S100147328**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	88586
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 09/30/88: TANK REMOVED BY F&N FOR SPILLER ON 9/30/88.TANK HAD LITTLE SURFACE RUST, NO PITTING, NO HOLES,2 OIL STAINS NEAR BUNGS. NO CONTAMINATED SOIL ENCOUNTERED. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"5K FAILED AT -.131 GPH. FIRST TEST ON 9/23,FAILED RETEST ON 9/26 TANK ALONE AT -.091 GPH. F&N TESTER"

All TTF:

Facility ID:	8805457
Spill Number:	8805457
Spill Tank Test:	1534681
Site ID:	99721
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	99721
Operable Unit ID:	920615
Operable Unit:	01
Material ID:	457359
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G41 **ESPRIT BLDG** **NY UST** **U003537687**
South **100 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.129 mi.
679 ft. **Site 7 of 7 in cluster G**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7104
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7104
Facility Reference #:	Not reported
Official Use:	Removed Tank. 88
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	20072
Installed:	Not reported
Capacity:	5000
Substance:	#2 FUEL OIL
Date Removed:	11/11/2154
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	5000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/11/2154
Year Installed:	Not reported
Description of drop records:	Not reported
Tank ID:	2
Tank Key:	20073
Installed:	89
Capacity:	4000

ESPRIT BLDG (Continued) **U003537687**

Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	89
Description of drop records:	Not reported

H42 **FONAR TRAVEL** **NY UST** **U004219542**
SSE **102 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.134 mi.
707 ft. **Site 1 of 3 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7114
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7114
Facility Reference #:	Not reported
Official Use:	Removed Tank. 92
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	20134
Installed:	Not reported
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	11/26/1927

FONAR TRAVEL (Continued) **U004219542**

Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/26/1927
Year Installed:	Not reported
Description of drop records:	Not reported

I43 **HONEYWELL INC** **NY Spills** **1000990521**
North **175 PINELAWN RD** **RCRA NonGen / NLR** **NYR000004804**
1/8-1/4 **MELVILLE, NY 11747** **FINDS**
0.141 mi. **ECHO**
743 ft. **Site 1 of 2 in cluster I** **NY MANIFEST**

Relative: **Lower**

Actual: **100 ft.**

SPILLS:

Facility ID:	0800679
Facility Type:	ER
Spill Number:	0800679
DER Facility ID:	345960
Site ID:	396476
DEC Region:	1
Closed Date:	2008-10-30
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5226
Spill Date:	2008-04-16
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-04-16
CID:	404
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-16

HONEYWELL INC (Continued) **1000990521**

Spill Record Last Update:	2008-11-13
Spiller Name:	SEAN DAVIS
Spiller Company:	COMMERICAL BUILDING
Spiller Address:	175 PINELAWN ROAD
Spiller Company:	001
Contact Name:	SEAN DAVIS
DEC Memo:	""
Remarks:	"equipment failure with a padmount transformer; contained; clean up in progress"

All Materials:

Site ID:	396476
Operable Unit ID:	1153442
Operable Unit:	01
Material ID:	2144203
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	HONEYWELL INC
Facility address:	175 PINELAWN RD MELVILLE, NY 11747
EPA ID:	NYR000004804
Mailing address:	PINELAWN RD MELVILLE, NY 11747
Contact:	Not reported
Contact address:	PINELAWN RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HONEYWELL INC
Owner/operator address:	75-20 ASTORIA BLVD JACKSON HEIGHTS, NY 11370
Owner/operator country:	US
Owner/operator telephone:	718-651-4100
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

HONEYWELL INC (Continued) **1000990521**

Owner/operator name: HONEYWELL INC
Owner/operator address: 75-20 ASTORIA BLVD
JACKSON HEIGHTS, NY 11370
Owner/operator country: US
Owner/operator telephone: 718-651-4100
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 05/12/1995
Site name: HONEYWELL INC
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

HONEYWELL INC (Continued) **1000990521**

FINDS:

Registry ID: 110058270115

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Registry ID: 110006448692

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000990521
Registry ID:	110006448692
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006448692

NY MANIFEST:

Country:	USA
EPA ID:	NYR000004804
Facility Status:	Not reported
Location Address 1:	175 PINELAWN RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000004804
Mailing Name:	HONEYWELL CORP
Mailing Contact:	JIMMY MORALES
Mailing Address 1:	175 PINELAWN RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5165594048

I44 **NEW YORK STATE DRUG ENFORCEMENT ADMINIST** **NY MANIFEST** **1009233484**
North **175 PINELAWN RD SUITE 205** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.141 mi.
743 ft. **Site 2 of 2 in cluster I**

Relative:
Lower

Actual:
100 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP000916015
Facility Status:	Not reported
Location Address 1:	175 PINELAWN RD SUITE 205
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000916015
Mailing Name:	NEW YORK STATE DRUG ENFORCEMENT ADMINIST
Mailing Contact:	DIRK H LUEDERS
Mailing Address 1:	175 PINELAWN RD SUITE 205
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164204520

---

45 **INTERLOGIC INDUSTRIES** **RCRA-CESQG** **1000215971**
SW **85 MARCUS DR** **FINDS** **NYD980766349**
1/8-1/4 **MELVILLE, NY 11747** **ECHO**
0.142 mi. **NY MANIFEST**
750 ft.

Relative:
Lower

Actual:
102 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	INTERLOGIC INDUSTRIES
Facility address:	85 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYD980766349
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	Not reported
Contact address:	MARCUS DR MELVILLE, NY 11747
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

INTERLOGIC INDUSTRIES (Continued) **1000215971**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006

INTERLOGIC INDUSTRIES (Continued) **1000215971**

Site name: INTERLOGIC INDUSTRIES
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: INTERLOGIC INDUSTRIES
Classification: Small Quantity Generator

Date form received by agency: 02/07/1984
Site name: INTERLOGIC INDUSTRIES
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

Violation Status: No violations found

FINDS:

Registry ID: 110019770666

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Registry ID: 110004390631

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000215971
Registry ID: 110004390631
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004390631

NY MANIFEST:
Country: USA
EPA ID: NYD980766349
Facility Status: Not reported
Location Address 1: 85 MARCUS DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

INTERLOGIC INDUSTRIES (Continued) **1000215971**

NY MANIFEST:

EPAID:	NYD980766349
Mailing Name:	INTERLOGIC INDUSTRIES INCORPORATED
Mailing Contact:	DONALD GREENE
Mailing Address 1:	85 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164208111

J46 **COMAX MANUFACTURING CORP** **NY AST** **A100281108**
NNW **130 BAYLIS RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.144 mi.
758 ft. **Site 1 of 2 in cluster J**

Relative:
Higher

Actual:
107 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	8369
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8369
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	46697
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	16500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	10
Tank Key:	48457
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	CONCRETE
Dispenser:	Not reported
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	4675
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	2
Tank Key:	46698
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	3
Tank Key:	46699
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	4
Tank Key:	46700
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	5
Tank Key:	46701
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	6
Tank Key:	46702
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	200
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	46703
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	8
Tank Key:	46704
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

COMAX MANUFACTURING CORP (Continued) **A100281108**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	9
Tank Key:	46706
Year Installed:	Not reported
Substance:	MIXING
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Unregistered Tank discovered through routine industrial inspection
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	300
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

J47 **COMAX FLAVORS** **RCRA-LQG** **1000141185**
NNW **130 BAYLISS RD** **NY MANIFEST** **NYD016914376**
1/8-1/4 **MELVILLE, NY 11747** **NJ MANIFEST**
0.144 mi.
758 ft. **Site 2 of 2 in cluster J**

Relative: **Higher**
Actual: **107 ft.**

RCRA-LQG:

Date form received by agency:	02/28/2008
Facility name:	COMAX FLAVORS
Facility address:	130 BAYLISS RD MELVILLE, NY 11747
EPA ID:	NYD016914376
Mailing address:	BAYLISS RD MELVILLE, NY 11747
Contact:	JOE PIAZZA
Contact address:	Not reported Not reported
Contact country:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Contact telephone: 631-249-0505
Contact email: JPIAZZA@COMAXFLAUORS.COM
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CALABRETTA FAMILY LLC
Owner/operator address: BAYLISS RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Owner/operator name: CALABRETTA FAMILY LLC
Owner/operator address: BAYLISS RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

COMAX FLAVORS (Continued) **1000141185**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: U135
. Waste name: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

. Waste code: U151
. Waste name: MERCURY

. Waste code: U153
. Waste name: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Historical Generators:
Date form received by agency: 01/01/2007
Site name: COMAX FLAVORS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/28/2006
Site name: COMAX FLAVORS
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Date form received by agency: 08/27/2006
Site name: COMAX FLAVORS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/04/2002
Site name: COMAX MFG CORP
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Date form received by agency: 07/08/1999
Site name: COMAX MFG CORP
Classification: Not a generator, verified

COMAX FLAVORS (Continued) **1000141185**

Date form received by agency: 06/04/1987
Site name: COMAX MFG CORP
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 03/29/2017
Date achieved compliance: 03/29/2017
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 05/30/2008
Date achieved compliance: 06/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

COMAX FLAVORS (Continued) **1000141185**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 05/30/2008
Date achieved compliance: 05/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 05/30/2008
Date achieved compliance: 06/19/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 05/30/2008
Date achieved compliance: 06/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/13/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/29/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 03/29/2017
Evaluation lead agency: EPA

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 06/30/2008

COMAX FLAVORS (Continued) **1000141185**

Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 06/19/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 06/30/2008
Evaluation lead agency: State

Evaluation date: 05/30/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 05/30/2008
Evaluation lead agency: State

NY MANIFEST:
Country: USA
EPA ID: NYD016914376
Facility Status: Not reported
Location Address 1: 130 BAYLISS RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD016914376
Mailing Name: COMAX FLAVORS
Mailing Contact: MARION CUNNINGHAM
Mailing Address 1: 130 BAYLIS ROAD
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6312490505

COMAX FLAVORS (Continued) **1000141185**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	02/07/2018
Trans1 Recv Date:	02/07/2018
Trans2 Recv Date:	02/09/2018
TSD Site Recv Date:	02/13/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD016914376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	009419609FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
10 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYD016914376
Mail Address:	130 BAYLIS ROAD

COMAX FLAVORS (Continued) **1000141185**

Mail City/State/Zip:	MELVILLE 11747
Facility Phone:	6312490505
Emergency Phone:	Not reported
Contact:	MARTON CUNNINGHAM
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	004718520JJK
EPA ID:	NYD016914376
Date Shipped:	12/08/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/08/2008
Date Trans2 Transported Waste:	12/12/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/12/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

COMAX FLAVORS (Continued) **1000141185**

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	1800 P

Manifest Number:	006651224JJK
EPA ID:	NYD016914376
Date Shipped:	7/21/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	2,150.00 Pounds

Manifest Number:	008760495JJK
EPA ID:	NYD016914376
Date Shipped:	9/24/2013
TSDF EPA ID:	NJD980536593

COMAX FLAVORS (Continued) **1000141185**

Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	800.00 Pounds

Manifest Number:	008758547JJK
EPA ID:	NYD016914376
Date Shipped:	11/30/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	800.00 Pounds

Manifest Number:	008760193JJK
EPA ID:	NYD016914376
Date Shipped:	12/10/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,010.00 Pounds

Manifest Number:	008757717JJK
EPA ID:	NYD016914376
Date Shipped:	5/31/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 1,200.00 Pounds

Manifest Number: 001033697JJK
EPA ID: NYD016914376
Date Shipped: 08/24/2007
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/24/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/24/2007
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001

COMAX FLAVORS (Continued) **1000141185**

Hand Code:	H14
Quantity:	5 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H14
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	385 G
Manifest Year:	Not reported
Waste Code:	U151
Hand Code:	H14
Quantity:	5 G
Manifest Number:	008758668JJK
EPA ID:	NYD016914376
Date Shipped:	2/7/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	006657627JJK
EPA ID:	NYD016914376
Date Shipped:	07/06/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/06/2010
Date Trans2 Transported Waste:	07/06/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/07/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste Code:	D001
Hand Code:	H141
Quantity:	2000 P

Manifest Number:	004718324JJK
EPA ID:	NYD016914376
Date Shipped:	03/09/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/09/2010
Date Trans2 Transported Waste:	03/10/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/11/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	900 P

Manifest Number:	008760454JJK
EPA ID:	NYD016914376
Date Shipped:	8/8/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304

COMAX FLAVORS (Continued) **1000141185**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	400.00 Pounds

Manifest Number:	006657837JJK
EPA ID:	NYD016914376
Date Shipped:	10/08/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/08/2010

COMAX FLAVORS (Continued) **1000141185**

Date Trans2 Transported Waste:	10/11/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/13/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	2150 P

Manifest Number:	NJA5030969
EPA ID:	NYD016914376
Date Shipped:	01/25/2005
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD002454544
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/25/2005
Date Trans2 Transported Waste:	01/25/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/25/2005

COMAX FLAVORS (Continued) **1000141185**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04110521
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	006657985JJK
EPA ID:	NYD016914376
Date Shipped:	2/9/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	800.00 Pounds
Manifest Number:	004718678JJK
EPA ID:	NYD016914376
Date Shipped:	03/20/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/20/2009
Date Trans2 Transported Waste:	03/24/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/27/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	900 P
Manifest Number:	006657904JJK
EPA ID:	NYD016914376

COMAX FLAVORS (Continued) **1000141185**

Date Shipped:	11/18/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/18/2010
Date Trans2 Transported Waste:	11/19/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/24/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	2150 P

Manifest Number:	008760387JJK
EPA ID:	NYD016914376
Date Shipped:	6/20/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	011643092JJK
EPA ID:	NYD016914376
Date Shipped:	5/11/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	008758589JJK
EPA ID:	NYD016914376
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

COMAX FLAVORS (Continued) **1000141185**

Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 400.00 Pounds

Manifest Number: 006651382JJK
EPA ID: NYD016914376
Date Shipped: 10/5/2011
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: MELVILLE 11747
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 2,150.00 Pounds

K48 **MEDISYS HEALTH NETWORK** **NY UST** **U003537372**
SSW **80 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.148 mi.
784 ft. **Site 1 of 2 in cluster K**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7596
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7596
Facility Reference #:	Not reported
Official Use:	Removed Tank. 92
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	21937
Installed:	61
Capacity:	7500
Substance:	#2 FUEL OIL
Date Removed:	12/15/1988
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	7500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	12/15/1988
Year Installed:	61
Description of drop records:	Not reported
Tank ID:	2
Tank Key:	21938
Installed:	82
Capacity:	6000

MEDISYS HEALTH NETWORK (Continued) **U003537372**

Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	6000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	82
Description of drop records:	Not reported

K49 **GENOVESE DRUG STORES HQ** **NY LTANKS** **1000343746**
SSW **80 MARCUS DR** **RCRA NonGen / NLR** **NYD012364949**
1/8-1/4 **MELVILLE, NY 11747** **FINDS**
0.148 mi. **ECHO**
784 ft. **Site 2 of 2 in cluster K** **NY MANIFEST**

Relative: **Lower**
Actual: **102 ft.**

LTANKS:

Facility ID:	9110046
Site ID:	249892
Closed Date:	1999-09-08
Spill Number:	9110046
Spill Date:	1991-12-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1991-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-23
Spill Record Last Update:	1999-09-13

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Spiller Name:	Not reported
Spiller Company:	GENOVESE DRUG STORE
Spiller Address:	80 MARCUS DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	204843
DEC Memo:	""
Remarks:	"5K FAILED AT -0.334, TYREE TESTER"

All TTF:

Facility ID:	9110046
Spill Number:	9110046
Spill Tank Test:	1539454
Site ID:	249892
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	249892
Operable Unit ID:	963718
Operable Unit:	01
Material ID:	418620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GENOVESE DRUG STORES HQ
Facility address:	80 MARCUS DR MELVILLE, NY 11747-4230
EPA ID:	NYD012364949
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	HERNAN GUTIERREZ
Contact address:	MARCUS DR MELVILLE, NY 11747

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Contact country: US
Contact telephone: 631-845-8645
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EMIL DILOILO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/30/2000
Owner/Op end date: Not reported

Owner/operator name: EMIL DILOILO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/30/2000
Owner/Op end date: Not reported

Owner/operator name: ECKERD CORP - C/O GENOVESE
Owner/operator address: 80 MARCUS DR
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-845-8645
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: ECKERD CORP - C/O GENOVESE
Owner/operator address: 80 MARCUS DR
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-845-8645
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator

GENOVESE DRUG STORES HQ (Continued) **1000343746**

Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GENOVESE DRUG STORES HQ
Classification: Not a generator, verified

Date form received by agency: 10/30/2000
Site name: GENOVESE DRUG STORES HQ
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 07/08/1999
Site name: GENOVESE DRUG STORES HQ
Classification: Not a generator, verified

Date form received by agency: 11/14/1988
Site name: GENOVESE DRUG STORES HQ
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004344246

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019180358

Environmental Interest/Information System

GENOVESE DRUG STORES HQ (Continued) **1000343746**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000343746
Registry ID:	110004344246
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004344246

NY MANIFEST:

Country:	USA
EPA ID:	NYD012364949
Facility Status:	Not reported
Location Address 1:	80 MARCUS DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012364949
Mailing Name:	GENOVESE DRUG STORES INCORPORATED
Mailing Contact:	GENOVESE DRUG STORES INCORPORATED
Mailing Address 1:	80 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164201900

H50 **M & W RECKSON ASSOCIATES** **NY UST** **U003537823**
SSE **110 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.151 mi.
797 ft. **Site 2 of 3 in cluster H**

Relative:
Lower

Actual:
102 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	8229
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8229
Facility Reference #:	Not reported

M & W RECKSON ASSOCIATES (Continued) **U003537823**

Official Use:	Abandoned, approved by plan review, awaiting construction for compliance inspection. 01
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	23818
Installed:	83
Capacity:	8000
Substance:	#2 FUEL OIL
Date Removed:	7/16/2202
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	7/16/2202
Year Installed:	83
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	23819
Installed:	83
Capacity:	8000
Substance:	#2 FUEL OIL
Date Removed:	7/16/2202
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported

M & W RECKSON ASSOCIATES (Continued) **U003537823**

Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	7/16/2202
Year Installed:	83
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	23820
Installed:	83
Capacity:	8000
Substance:	#2 FUEL OIL
Date Removed:	7/16/2202
Construction:	STEEL
Dispenser:	GRAVITY
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	8000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	7/16/2202
Year Installed:	83
Description of drop records:	Not reported

H51 **FONAR CORP INC** **RCRA NonGen / NLR** **1000446533**
SSE **110 MARCUS DR** **FINDS** **NYD986908853**
1/8-1/4 **MELVILLE, NY 11747** **ECHO**
0.151 mi. **NJ MANIFEST**
797 ft. **Site 3 of 3 in cluster H** **NY MANIFEST**

Relative: **Lower**
Actual: **102 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FONAR CORP INC
Facility address:	110 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYD986908853
Mailing address:	MARCUS DR

FONAR CORP INC (Continued) **1000446533**

MELVILLE, NY 11747
Contact: Not reported
Contact address: MARCUS DR
MELVILLE, NY 11747
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DR RAYMOND DAMADIAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DR RAYMOND DAMADIAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

FONAR CORP INC (Continued) **1000446533**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FONAR CORP INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: FONAR CORP INC
Classification: Small Quantity Generator

Date form received by agency: 08/03/1990
Site name: FONAR CORP INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/01/2000
Date achieved compliance: 03/05/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/27/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/22/1991
Date achieved compliance: 04/24/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/22/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

FONAR CORP INC (Continued) **1000446533**

Evaluation Action Summary:
Evaluation date: 12/01/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/05/2001
Evaluation lead agency: State

Evaluation date: 02/22/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/22/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/24/1991
Evaluation lead agency: State

FINDS:

Registry ID: 110004450969

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019835749

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000446533
Registry ID: 110004450969
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004450969

NJ MANIFEST:
EPA Id: NYD986908853
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: 5166942929
Emergency Phone: 9084695100
Contact: LOU CORRADONE
Comments: Not reported
SIC Code: Not reported

FONAR CORP INC (Continued) **1000446533**

County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5077013
EPA ID:	NYD986908853
Date Shipped:	05/07/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06080425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYD986908853
Facility Status:	Not reported

FONAR CORP INC (Continued) **1000446533**

Location Address 1:	110 MARCUS DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986908853
Mailing Name:	FONAR CORPORATION
Mailing Contact:	FONAR CORPORATION
Mailing Address 1:	110 MARCUS DRIVE
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5166982929

L52 **RULAND ROAD LLC** **NY AST** **A100265046**
WNW **95 RULAND RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.174 mi.
917 ft. **Site 1 of 2 in cluster L**

Relative:
Lower

Actual:
104 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	7153
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7153
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	20328
Year Installed:	60
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	4/15/2067

Tank ID:	17
Tank Key:	43431
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	18
Tank Key:	43432
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	12000
Date Permitted:	Not reported
Date Closed:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067

Tank ID:	19
Tank Key:	43433
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	2
Tank Key:	20329
Year Installed:	60
Substance:	#4 FUEL OIL
Construction:	STEEL
Dispenser:	SUCTION
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	10000
Date Permitted:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	7/24/2067

Tank ID:	20
Tank Key:	43434
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	21
Tank Key:	43435
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275

RULAND ROAD LLC (Continued) **A100265046**

Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	22
Tank Key:	43436
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	24
Tank Key:	43602
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/14/1932

Tank ID:	25
Tank Key:	43919
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	26
Tank Key:	43920
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE

RULAND ROAD LLC (Continued) **A100265046**

Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	11/1/2067

Tank ID:	3
Tank Key:	43417
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	4
Tank Key:	43418
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported

RULAND ROAD LLC (Continued) **A100265046**

Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	5
Tank Key:	43419
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	6
Tank Key:	43420
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02

RULAND ROAD LLC (Continued) **A100265046**

Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

Tank ID:	7
Tank Key:	43421
Year Installed:	Not reported
Substance:	#2 FUEL OIL
Construction:	STEEL
Dispenser:	Not reported
Official Use:	Removed Tank. 02
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	275
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066

L53 **RULAND ROAD LLC** **NY UST** **U003961171**
WNW **95 RULAND RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.174 mi.
917 ft. **Site 2 of 2 in cluster L**

Relative:
Lower

Actual:
104 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	7153
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	7153
Facility Reference #:	Not reported
Official Use:	Removed Tank. 02
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	8
Tank Key:	43422
Installed:	Not reported
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	4/15/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	4/15/2067
Year Installed:	Not reported
Description of drop records:	Not reported
Tank ID:	9
Tank Key:	43423
Installed:	Not reported
Capacity:	1000

RULAND ROAD LLC (Continued) **U003961171**

Substance:	FERTILIZER MIXER
Date Removed:	1/5/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	10
Tank Key:	43424
Installed:	Not reported
Capacity:	550
Substance:	GASOLINE
Date Removed:	3/11/2066
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066
Year Installed:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Description of drop records:	Not reported

Tank ID:	11
Tank Key:	43425
Installed:	Not reported
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	4/15/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	4/15/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	12
Tank Key:	43426
Installed:	Not reported
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	1/5/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	13
Tank Key:	43427
Installed:	Not reported
Capacity:	1000
Substance:	#2 FUEL OIL
Date Removed:	1/5/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	14
Tank Key:	43428
Installed:	Not reported
Capacity:	4000
Substance:	#2 FUEL OIL
Date Removed:	1/5/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	15
Tank Key:	43429
Installed:	Not reported
Capacity:	2000
Substance:	#2 FUEL OIL
Date Removed:	1/5/2067
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/5/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	16
Tank Key:	43430
Installed:	Not reported
Capacity:	550
Substance:	#2 FUEL OIL
Date Removed:	4/15/2067
Construction:	STEEL
Dispenser:	Not reported

RULAND ROAD LLC (Continued) **U003961171**

Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	550
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	4/15/2067
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	23
Tank Key:	43437
Installed:	Not reported
Capacity:	2000
Substance:	KEROSENE
Date Removed:	3/11/2066
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	3/11/2066
Year Installed:	Not reported
Description of drop records:	Not reported

54
NNW
1/8-1/4
0.176 mi.
931 ft.

CANADA DRY BOTTLING CO
135 BAYLIS RD
MELVILLE, NY 11747

NY LTANKS
NY UST
NY AST

U003537593
N/A

Relative:
Lower

Actual:
103 ft.

LTANKS:

Facility ID:	9700559
Site ID:	159315
Closed Date:	1999-04-14
Spill Number:	9700559
Spill Date:	1997-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1997-04-11
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-11
Spill Record Last Update:	1999-04-16
Spiller Name:	FRANK DAY
Spiller Company:	CANADA DRY CO
Spiller Address:	135 BAYLIS ROAD
Spiller County:	999
Spiller Contact:	FRANK DAY
Spiller Phone:	(914) 636-5033
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	134569
DEC Memo:	""
Remarks:	""

All TTF:

Facility ID:	9700559
Spill Number:	9700559
Spill Tank Test:	1545075
Site ID:	159315
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

CANADA DRY BOTTLING CO (Continued) **U003537593**

All Materials:

Site ID:	159315
Operable Unit ID:	1046856
Operable Unit:	01
Material ID:	337153
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9304069
Site ID:	203799
Closed Date:	1994-02-10
Spill Number:	9304069
Spill Date:	1993-06-30
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1994-02-10
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1993-06-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-02
Spill Record Last Update:	2014-08-19
Spiller Name:	ROBERT NOBLE
Spiller Company:	CANADA DRY BOTTLING
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	134569
DEC Memo:	"WILL EIR PER STEWART PASTOR 7/6/93 PATCH FOUND ON TOP OF TANK. TANK BEING PUMPED WILL BE REMOVED TOMORROW, TANK REMOVED 7/7/93 < 1/4 YD OF CONTAMINATION FOUND DISPOSED OF WITH TANK SLUDGE. NO FURTHER CONTAMINATION DETECTED PERMISSION GIVEN TO BACKFILL NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"3K FAILED GROSS LEAK, LEWIS TESTER"

All TTF:

Facility ID:	9304069
Spill Number:	9304069

CANADA DRY BOTTLING CO (Continued) **U003537593**

Spill Tank Test:	1541718
Site ID:	203799
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	203799
Operable Unit ID:	985798
Operable Unit:	01
Material ID:	397599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	6840
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	6840
Facility Reference #:	Not reported
Official Use:	Removed Tank. 93
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	19244
Installed:	65
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	10/26/2093
Construction:	STEEL
Dispenser:	SUCTION

CANADA DRY BOTTLING CO (Continued) **U003537593**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	10/26/2093
Year Installed:	65
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	19246
Installed:	85
Capacity:	1500
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	1500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	85
Description of drop records:	Not reported

CANADA DRY BOTTLING CO (Continued) **U003537593**

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	6840
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	6840
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	2
Tank Key:	19245
Year Installed:	87
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Permitted Tank. Permit Runs Out. 92
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1100
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

M55 **COMMERCIAL** **NY LTANKS** **S105135247**
NNW **125 BAYLIS ROAD** **NY Spills** **N/A**
1/8-1/4 **MELVILLE, NY**
0.201 mi.
1062 ft. **Site 1 of 2 in cluster M**

Relative:
Higher

Actual:
108 ft.

LTANKS:

Facility ID:	0104376
Site ID:	127634
Closed Date:	2001-09-07
Spill Number:	0104376
Spill Date:	2001-07-24
Spill Cause:	Tank Test Failure

COMMERCIAL (Continued) **S105135247**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	2001-07-24
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-24
Spill Record Last Update:	2009-11-03
Spiller Name:	JIM DONELAN
Spiller Company:	OFFICE BUILDING
Spiller Address:	125 BAYLIS ROAD
Spiller County:	001
Spiller Contact:	JIM DONELAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	110188
DEC Memo:	"7/24/01 16:15 TELECON WG TO MR DONELAN FROM PROTEST ENT, AN UNUSED SUPPLY LINE CAUSED THE TANK FAILURE, NO CLEANUP HAS BEEN SCHEDULED YET AT THIS TIME, PER MIKE FLYNN, EASTERN ENV SOLUTIONS, 631-325-2700, REPAIRS MADE TANK PASSED RETEST TANK REMOVED, NO CONTAMINATED SOIL FOUND"
Remarks:	"tank failed the test 550gal diesel fuel tank"

All TTF:

Facility ID:	0104376
Spill Number:	0104376
Spill Tank Test:	1526479
Site ID:	127634
Tank Number:	1
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

SPILLS:

Facility ID:	1703782
Facility Type:	ER
Spill Number:	1703782

COMMERCIAL (Continued) **S105135247**

DER Facility ID:	110188
Site ID:	554971
DEC Region:	1
Closed Date:	2017-09-22
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2017-07-05
Investigator:	JAFRADUA
Referred To:	Not reported
Reported to Dept:	2017-07-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-18
Spill Record Last Update:	2017-10-30
Spiller Name:	KALNETTA
Spiller Company:	125 BAYLIS LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KALNETTA
DEC Memo:	"07/18/17 1300 Hrs: Checked Google Earth and the internet- this appears to be a commercial/office building (apparently medical). DR 07/18/17 1305 Hrs: Left message for Schlageter. DR 07/18/17 1305 Hrs (A): Schlageter called- he pointed out that this occurred 7/5, and said he just found out that the incident was reported to the local officials but not to DEC. 07/18/17 1305 Hrs (B): There was an out-of-service diesel tank ('capacity perhaps 15-20gal?') and generator on the roof. The tank leaked, and some fuel stayed on the roof but some entered a drywell. 07/18/17 1305 Hrs (C): 'There were some odors inside at that time, and AARCO etc cleaned the roof, but he was just informed that the drywell had been impacted.' 07/18/17 1305 Hrs (D): Schlageter is also notifying the Suffolk County Health Department, and does not know when the cleanup of the drywell will be performed. 07/18/17 1305 Hrs (E): DEC directed him to call back tomorrow to determine who had been assigned to the case. DR CONTAMINATED SOIL EXCAVATED, CLEANUP COMPLETE, NO FURTHER ACTION REQUIRED"
Remarks:	"roof top generator leaked fuel to gutter and into dry well/clean up pending"

All Materials:

Site ID:	554971
Operable Unit ID:	1303036
Operable Unit:	01
Material ID:	2309496
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00

COMMERCIAL (Continued) **S105135247**

Units: G
Recovered: .00
Oxygenate: Not reported

M56 **PARAGON ENTERPRISES** **NY UST** **U003537826**
NNW **125 BAYLIS RD** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.201 mi.
1062 ft. **Site 2 of 2 in cluster M**

Relative:
Higher

Actual:
108 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 8235
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 8235
Facility Reference #: Not reported
Official Use: Exempt from Suffolk County Art 12 Regulation
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 23826
Installed: 83
Capacity: 550
Substance: DIESEL
Date Removed: Not reported
Construction: STEEL
Dispenser: SUCTION
Fill Type: GRAVITY
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 550
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: GRAVITY
Date Removed: Not reported
Year Installed: 83

PARAGON ENTERPRISES (Continued) **U003537826**

Description of drop records: Not reported

57
NW
1/8-1/4
0.221 mi.
1166 ft.

NY TEL CO
84 DURYEA ROAD
MELVILLE, NY

NY LTANKS **S100177468**
N/A

Relative:
Lower

Actual:
104 ft.

LTANKS:

Facility ID:	9109715
Site ID:	198367
Closed Date:	1992-01-10
Spill Number:	9109715
Spill Date:	1991-12-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-01-10
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1991-12-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-13
Spill Record Last Update:	1992-01-10
Spiller Name:	Not reported
Spiller Company:	NY TEL CO
Spiller Address:	100 GARDEN CITY PLAZA
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	165093
DEC Memo:	""
Remarks:	"2K FAILED AT -0.417, GASOLINE INSTALLATIONS TESTER"

All TTF:

Facility ID:	9109715
Spill Number:	9109715
Spill Tank Test:	1539412
Site ID:	198367
Tank Number:	Not reported
Tank Size:	0
Material:	0012
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

NY TEL CO (Continued) **S100177468**

Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 198367
Operable Unit ID: 963478
Operable Unit: 01
Material ID: 418309
Material Code: 0012A
Material Name: kerosene
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

N58 **ROCHE BIOMEDICAL LABS INC** **RCRA NonGen / NLR** **1000994425**
SSE **170 FINN CT** **FINDS** **NYD986899219**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.222 mi. **NY MANIFEST**
1172 ft. **Site 1 of 13 in cluster N**

Relative: **Lower**
Actual: **101 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ROCHE BIOMEDICAL LABS INC
Facility address: 170 FINN CT
FARMINGDALE, NY 11735
EPA ID: NYD986899219
Mailing address: NORTHERN BLVD
GREAT NECK, NY 11021
Contact: Not reported
Contact address: NORTHERN BLVD
GREAT NECK, NY 11021
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ROCHE BIOMEDICAL
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ROCHE BIOMEDICAL
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 04/18/1995
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 04/05/1990
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F003

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U122
. Waste name: FORMALDEHYDE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/04/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004356740

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000994425
Registry ID: 110004356740
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004356740

NY MANIFEST:
Country: USA
EPA ID: NYD986899219
Facility Status: Not reported
Location Address 1: 560 NORTHERN BOULEVARD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: GREAT NECK
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

ROCHE BIOMEDICAL LABS INC (Continued) **1000994425**

NY MANIFEST:

EPAID:	NYD986899219
Mailing Name:	ROCHE LABS
Mailing Contact:	BETTY DECKER
Mailing Address 1:	560 NORTHERN BOULEVARD
Mailing Address 2:	Not reported
Mailing City:	GREAT NECK
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5164878600

N59 **ROCHE BIOMEDICAL LABS INC** **RCRA NonGen / NLR** **1000203200**
SSE **170 FINN CT** **NY MANIFEST** **NYD047645700**
1/8-1/4 **FARMINGDALE, NY 11735**
0.222 mi.
1172 ft. **Site 2 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROCHE BIOMEDICAL LABS INC
Facility address:	170 FINN CT FARMINGDALE, NY 11735-1107
EPA ID:	NYD047645700
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	Not reported
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROCHE BIOMEDICAL LABS INC
Owner/operator address:	231 MAPLE AVE BURLINGTON, NC 27215
Owner/operator country:	US
Owner/operator telephone:	800-334-5161
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ROCHE BIOMEDICAL LABS INC
Owner/operator address:	231 MAPLE AVE BURLINGTON, NC 27215
Owner/operator country:	US
Owner/operator telephone:	800-334-5161

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Not a generator, verified

Date form received by agency: 12/09/1991
Site name: ROCHE BIOMEDICAL LABS INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT

ROCHE BIOMEDICAL LABS INC (Continued) **1000203200**

NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD047645700
Facility Status: Not reported
Location Address 1: 170 FINN COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD047645700
Mailing Name: ROCHE BIOMEDICAL
Mailing Contact: DANILO VELASCO
Mailing Address 1: 170 FINN COURT
Mailing Address 2: Not reported
Mailing City: FARMINGDALE
Mailing State: NY
Mailing Zip: 11735
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5167528311

N60 **LABORATORY CORP OF AMERICA** **NY UST** **U003960936**
SSE **170 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.222 mi.
1172 ft. **Site 3 of 13 in cluster N**

Relative: **Lower**
Actual: **101 ft.**

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 450
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 450
Facility Reference #: Not reported
Official Use: Removed Tank. 02
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: 11/22/2206

LABORATORY CORP OF AMERICA (Continued) **U003960936**

Tank ID:	1
Tank Key:	1559
Installed:	91
Capacity:	250
Substance:	INDUSTRIAL WASTE
Date Removed:	5/24/1930
Construction:	Not reported
Dispenser:	OTHER
Fill Type:	OTHER
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	250
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	OTHER
Date Removed:	5/24/1930
Year Installed:	91
Description of drop records:	Not reported

N61 **ARTEK** **NY UST** **U003843265**
SSE **170 FINN CT** **N/A**
1/8-1/4 **BABYLON, NY 11702**
0.222 mi.
1172 ft. **Site 4 of 13 in cluster N**

Relative: **Lower**
Actual: **101 ft.**

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	2248
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	2248
Facility Reference #:	Not reported
Official Use:	Removed Tank. 88
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	5509

ARTEK (Continued) **U003843265**

Installed:	Not reported
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	11/22/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/22/1927
Year Installed:	Not reported
Description of drop records:	Not reported

62
SSW
1/8-1/4
0.223 mi.
1175 ft.

FALA INC **NY UST** **U003537830**
70 MARCUS DR **N/A**
MELVILLE, NY 11747

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	8240
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8240
Facility Reference #:	Not reported
Official Use:	Removed Tank. 95
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	23830
Installed:	77
Capacity:	4000

FALA INC (Continued) **U003537830**

Substance:	#2 FUEL OIL
Date Removed:	10/14/2153
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	10/14/2153
Year Installed:	77
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	23831
Installed:	Not reported
Capacity:	5000
Substance:	#2 FUEL OIL
Date Removed:	1/20/1987
Construction:	STEEL
Dispenser:	Not reported
Fill Type:	Not reported
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	5000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	1/20/1987
Year Installed:	Not reported

FALA INC (Continued) **U003537830**

Description of drop records: Not reported

63
West
1/8-1/4
0.227 mi.
1201 ft.

WALAEL RESIDENCE
95 RULAND PLACE
MELVILLE, NY

NY LTANKS **S118953863**
N/A

Relative:
Lower

Actual:
100 ft.

LTANKS:

Facility ID:	9903643
Site ID:	240480
Closed Date:	1999-09-28
Spill Number:	9903643
Spill Date:	1999-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1999-06-29
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-29
Spill Record Last Update:	2010-06-22
Spiller Name:	RICHARD WALAEL
Spiller Company:	WALAEL RESIDENCE
Spiller Address:	95 RULAND PLACE
Spiller County:	001
Spiller Contact:	RICHARD WALAEL
Spiller Phone:	(516) 694-3851
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	197767
DEC Memo:	"6/29/99 17:23 TELECON WITH RICHARD WALAEL, SYSTEM TEST FAILURE, IS LOOKING TO SELL PROPERTY, WILL EXCAVATE TANK HIMSELF, UNSURE IF REPAIR OR REMOVE TANK REMOVED, NO CONTAMINATION FOUND"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. TANK TO BE EXPOSED AND RETESTED. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	9903643
Spill Number:	9903643
Spill Tank Test:	1547324
Site ID:	240480
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported

WALAEL RESIDENCE (Continued) **S118953863**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.07
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	240480
Operable Unit ID:	1082569
Operable Unit:	01
Material ID:	563504
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N64 **MORRIS BROTHERS AUTO & TRUCK PARTS** **NY Spills** **S104646291**
SSE **150 FINN COURT** **NY MANIFEST** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.230 mi.
1213 ft. **Site 5 of 13 in cluster N**

Relative: **Lower**
Actual: **101 ft.**

SPILLS:

Facility ID:	9706548
Facility Type:	ER
Spill Number:	9706548
DER Facility ID:	248999
Site ID:	308312
DEC Region:	1
Closed Date:	1997-09-03
Spill Cause:	Other
Spill Class:	D1
SWIS:	3024
Spill Date:	1997-09-01
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1997-09-01
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-01
Spill Record Last Update:	2011-09-12

MORRIS BROTHERS AUTO & TRUCK PARTS (Continued) **S104646291**

Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	150 FINN COURT
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE NO RESPONSE BY SPILL UNIT. ECO'S NOTIFIED."
Remarks:	"INVESTIGATOR RICHARD J MAGGIO FROM TARRYTOWN TOLD CALLER TO CALL ANYTIME HE NOTICED SUSPICIOUS ACTIVITY. SUBJECTS ARE CURRENTLY TRANSFERRING BAGS LABELED ASBESTOS - DANGEROUS FROM WAREHOUSE TO TRUCKS. WAREHOUSE IS OVERFLOWING WITH ASBESTOS. IT'S HANGING OUT OF DOORS. OFFICES ARE CLOSED FOR THE DAY. CALLER REQUEST A CALL BACK. SUFFOLK COUNTY POLICE NOTIFIED ALSO."

All Materials:

Site ID:	308312
Operable Unit ID:	1052766
Operable Unit:	01
Material ID:	332127
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP000786608
Facility Status:	Not reported
Location Address 1:	150 FINN COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000786608
Mailing Name:	MORRIS BROTHERS AUTO & TRUCK PARTS
Mailing Contact:	MORTIMER ROSENBERG
Mailing Address 1:	150 FINN COURT
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5166949161

N65 **NATIONAL ENVIRONMENTAL CONTROL N E** **NY UST** **U003842869**
SSE **150 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.230 mi.
1213 ft. **Site 6 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	1116
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	1116
Facility Reference #:	Not reported
Official Use:	Removed Tank. 00
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	3154
Installed:	75
Capacity:	3000
Substance:	#2 FUEL OIL
Date Removed:	9/14/1988
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	9/14/1988
Year Installed:	75
Description of drop records:	Not reported

N66 **PRECIPART CORPORATION** **NJ MANIFEST** **S120678726**
SSE **150 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.230 mi.
1213 ft. **Site 7 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

NJ MANIFEST:

EPA Id:	NYR000087247
Mail Address:	FINN CT
Mail City/State/Zip:	FARMINGDALE, NY 11735
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ALAN ROSENBERG
Comments:	Not reported
SIC Code:	Not reported
County:	NY103
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	005008138SKS
EPA ID:	NYR000087247
Date Shipped:	1/11/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/11/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/15/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004942610SKS
EPA ID:	NYR000087247
Date Shipped:	6/23/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004816574SKS
EPA ID:	NYR000087247
Date Shipped:	4/29/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004924092SKS
EPA ID:	NYR000087247
Date Shipped:	6/3/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005008617SKS
EPA ID:	NYR000087247
Date Shipped:	9/17/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Manifest Number:	004606232SKS
EPA ID:	NYR000087247
Date Shipped:	1/19/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005008773SKS
EPA ID:	NYR000087247
Date Shipped:	8/18/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005193594SKS
EPA ID:	NYR000087247
Date Shipped:	2/1/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/1/2016
Waste SEQ ID:	1

PRECIPART CORPORATION (Continued) **S120678726**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/5/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004947091SKS
EPA ID:	NYR000087247
Date Shipped:	7/30/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004980115SKS
EPA ID:	NYR000087247
Date Shipped:	10/13/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205

PRECIPART CORPORATION (Continued) **S120678726**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005167079SKS
EPA ID:	NYR000087247
Date Shipped:	12/22/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004894061SKS
EPA ID:	NYR000087247
Date Shipped:	2/16/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/16/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date Accepted:	2/19/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported
Manifest Number:	004816974SKS
EPA ID:	NYR000087247
Date Shipped:	10/28/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported
Manifest Number:	005406585SKS
EPA ID:	NYR000087247
Date Shipped:	3/15/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/15/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/18/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004636599SKS
EPA ID:	NYR000087247
Date Shipped:	2/23/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005008379SKS
EPA ID:	NYR000087247
Date Shipped:	11/12/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Manifest Number:	005415089SKS
EPA ID:	NYR000087247
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	4/1/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005188082SKS
EPA ID:	NYR000087247
Date Shipped:	1/18/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	PRECIPART INC NORTH
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	gallons
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/18/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/22/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	004646600SKS
EPA ID:	NYR000087247
Date Shipped:	3/23/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

PRECIPART CORPORATION (Continued) **S120678726**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

Manifest Number:	005153043SKS
EPA ID:	NYR000087247
Date Shipped:	11/23/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FARMINGDALE, NY 11735
Reason Load Was Rejected:	Not reported

N67 **PRECIPART CORPORATION** **RCRA-SQG** **1004761475**
SSE **150 FINN CT** **FINDS** **NYR000087247**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.230 mi. **RI MANIFEST**
1213 ft. **Site 8 of 13 in cluster N** **NY MANIFEST**

Relative: Lower

Actual: 101 ft.

RCRA-SQG:

Date form received by agency:	12/30/2014
Facility name:	PRECIPART CORPORATION
Facility address:	150 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYR000087247
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	DANIEL RUDOLF
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	631-694-3100
Contact email:	DRUDOLF@PRECIPART.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DAVID I ROSENBERG
Owner/operator address:	LEXINGTON AVE11TH FL NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	212-409-2222
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/01/2013
Owner/Op end date:	Not reported

Owner/operator name:	PRECIPART CORPORATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

PRECIPART CORPORATION (Continued) **1004761475**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

PRECIPART CORPORATION (Continued) **1004761475**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 02/18/2014
Site name: PRECIPART CORPORATION
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: PRECIPART CORP
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: PRECIPART CORP

PRECIPART CORPORATION (Continued) **1004761475**

Classification: Small Quantity Generator

Date form received by agency: 02/26/2003
Site name: PRECIPART CORP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 06/12/2000
Site name: SUTTON & EDWARDS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 02/14/2017
Date achieved compliance: 02/14/2017
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 02/14/2017
Date achieved compliance: 02/27/2017

PRECIPART CORPORATION (Continued) **1004761475**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 02/14/2017
Date achieved compliance: 02/16/2017
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 02/14/2017
Date achieved compliance: 03/01/2017
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/14/2017
Date achieved compliance: 03/20/2017
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 02/14/2017
Date achieved compliance: 03/02/2017
Violation lead agency: State

PRECIPART CORPORATION (Continued) **1004761475**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 10/23/2008
Date achieved compliance: 10/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 10/23/2008
Date achieved compliance: 01/23/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 10/23/2008
Date achieved compliance: 10/31/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 10/23/2008
Date achieved compliance: 10/31/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

PRECIPART CORPORATION (Continued) **1004761475**

Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 10/23/2008
Date achieved compliance: 01/29/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/29/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/27/2017
Evaluation lead agency: State

Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 02/14/2017
Evaluation lead agency: State

Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/16/2017
Evaluation lead agency: State

Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 03/02/2017
Evaluation lead agency: State

Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/20/2017
Evaluation lead agency: State

Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 03/01/2017

PRECIPART CORPORATION (Continued) **1004761475**

Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 01/29/2009
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 10/31/2008
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 10/30/2008
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 10/31/2008
Evaluation lead agency: State

Evaluation date: 10/23/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 01/23/2009
Evaluation lead agency: State

FINDS:

Registry ID: 110004562875

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

PRECIPART CORPORATION (Continued) **1004761475**

ECHO:

Envid:	1004761475
Registry ID:	110004562875
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004562875

RI MANIFEST:

EPA Id:	NYR000087247
GEN Cert Date:	12/27/2011
Manifest Document Number:	002592282SKS
Waste Description:	TRICHLOROETHYLENE
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	500
WT/Vol Units:	P
TSDF Date:	1/4/2012
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	1/4/2012
Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	12/27/2011
Number Of Containers:	2
Container Type:	DM
Waste Code1:	D040
Waste Code2:	F002
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	12/27/2011
Number Of Containers:	2
Container Type:	DM
Waste Code1:	D040
Waste Code2:	F002
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported

PRECIPART CORPORATION (Continued) **1004761475**

Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000087247
Manifest Docket Number:	002592282SKS
Quarter:	Not reported
Waste Description:	TRICHLOROETHYLENE
Transporter Contact Name:	Not reported
Quantity:	500
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/27/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/4/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/4/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYR000087247
Facility Status:	Not reported
Location Address 1:	150 FINN COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000087247
Mailing Name:	PRECIPART CORP
Mailing Contact:	MICHAEL MANUELLA
Mailing Address 1:	150 FINN COURT
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA

PRECIPART CORPORATION (Continued) **1004761475**

Mailing Phone: 6314723400

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000081205
Trans2 State ID:	MAD039322250
Generator Ship Date:	03/12/2018
Trans1 Recv Date:	03/12/2018
Trans2 Recv Date:	03/16/2018
TSD Site Recv Date:	03/16/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	006589561SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
66 additional NY_MANIFEST: record(s) in the EDR Site Report.

N68 **PRECIPART CORP** **PA MANIFEST** **S110049509**
SSE **150 FINN COURT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.230 mi.
1213 ft. **Site 9 of 13 in cluster N**

Relative: **Lower**

Actual: **101 ft.**

Manifest Details:

Year:	2008
Manifest Number:	003535740JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000087247
Generator Date:	08/26/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	631-694-3100
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	003535740JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000087247
Generator Date:	08/26/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	631-694-3100
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported

PRECIPART CORP (Continued) **S110049509**

Date TSP Sig: Not reported

O69 **MANUFACTURERS INDEXING PRODUCT** **RCRA NonGen / NLR** **1001090306**
SSE **130 FINN CT** **NY MANIFEST** **NYR000021436**
1/8-1/4 **EAST FARMINGDALE, NY 11735**
0.231 mi.
1218 ft. **Site 1 of 4 in cluster O**

Relative:
Lower

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MANUFACTURERS INDEXING PRODUCT
Facility address: 130 FINN CT
EAST FARMINGDALE, NY 11735
EPA ID: NYR000021436
Mailing address: FINN CT
EAST FARMINGDALE, NY 11735
Contact: Not reported
Contact address: FINN CT
EAST FARMINGDALE, NY 11735
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MANUFACTURERS INDEXING PRODUCT
Owner/operator address: 130 FINN CT
EAST FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: 516-249-1272
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MANUFACTURERS INDEXING PRODUCT
Owner/operator address: 130 FINN CT
EAST FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: 516-249-1272
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

MANUFACTURERS INDEXING PRODUCT (Continued) **1001090306**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Not a generator, verified

Date form received by agency: 03/25/1996
Site name: MANUFACTURERS INDEXING PRODUCT
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000021436
Facility Status: Not reported
Location Address 1: 130 FINN CT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: E FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000021436
Mailing Name: MIP MANUFACTURES
Mailing Contact: MIP MANUFACTURES
Mailing Address 1: 130 FINN CT
Mailing Address 2: Not reported
Mailing City: E FARMINGDALE

MANUFACTURERS INDEXING PRODUCT (Continued) **1001090306**

Mailing State: NY
Mailing Zip: 11735
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162491272

O70 **MIP INC** **NY AST** **A100196428**
SSE **130 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.231 mi.
1218 ft. **Site 2 of 4 in cluster O**

Relative:
Lower

Actual:
101 ft.

AST_SUFFOLK:
Region: SUFFOLK
Site Ref#: 431
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 431
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 1
Tank Key: 1461
Year Installed: 85
Substance: DRUM STORAGE
Construction: Not reported
Dispenser: Not reported
Official Use: Removed Tank. 86
Permit to Operate: 6/26/1989
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 23760
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: GRAVITY
Date Removed: 11/20/1927

P71
SW
1/8-1/4
0.231 mi.
1221 ft.

Relative:
Lower

Actual:
102 ft.

FALA CCG INC
75 MARCUS DR
MELVILLE, NY 11747

Site 1 of 2 in cluster P

Database(s): RCRA-SQG, NY LTANKS, FINDS, ECHO, NY MANIFEST, NJ MANIFEST

EDR ID Number: 1001460264
EPA ID Number: NYR000067322

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	FALA CCG INC
Facility address:	75 MARCUS DR MELVILLE, NY 11747
EPA ID:	NYR000067322
Mailing address:	MARCUS DR MELVILLE, NY 11747
Contact:	HARRY BELECHTO
Contact address:	MARCUS DR MELVILLE, NY 11747
Contact country:	US
Contact telephone:	631-391-0203
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	75 MARCUS CORP
Owner/operator address:	75 MARCUS DR MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-391-0604
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	75 MARCUS CORP
Owner/operator address:	75 MARCUS DR MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-391-0604
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

FALA CCG INC (Continued) **1001460264**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FALA CCG INC
Classification: Small Quantity Generator

Date form received by agency: 02/26/2002
Site name: FALA CCG INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: FALA CCG INC
Classification: Large Quantity Generator

Date form received by agency: 10/06/1999
Site name: FALA GRAPHICS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: SR - 373-3.3(g)(1)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

FALA CCG INC (Continued) **1001460264**

Regulation violated: SR - 372.2(a)(8)(iii)(d)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-1.1(d)(1)(iv)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(i)(a)(2)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.9(d)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(b)(2)(ii)

FALA CCG INC (Continued) **1001460264**

Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(c)(1)
Area of violation: Generators - General
Date violation determined: 07/07/2003
Date achieved compliance: 09/05/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/05/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various
Area of violation: Generators - General
Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/19/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various
Area of violation: Generators - General
Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/22/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - various
Area of violation: Generators - General

FALA CCG INC (Continued) **1001460264**

Date violation determined: 03/21/2001
Date achieved compliance: 08/22/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/20/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/07/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/05/2003
Evaluation lead agency: State

Evaluation date: 03/21/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/22/2001
Evaluation lead agency: EPA

LTANKS:
Facility ID: 8706743
Site ID: 288842
Closed Date: 1988-02-09
Spill Number: 8706743
Spill Date: 1987-11-06
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C2
Cleanup Ceased: 1988-02-09
SWIS: 5226
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1987-11-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1987-11-13
Spill Record Last Update: 2015-05-12
Spiller Name: Not reported
Spiller Company: SEDCO

FALA CCG INC (Continued) **1001460264**

Spiller Address: 75 MARCUS DRIVE
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 233955
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD / / : F&N TESTER.TANK HAS NO HOLES. EXCAVATION CLEAN. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks: "5K FAILED AT -.203"

All TTF:
Facility ID: 8706743
Spill Number: 8706743
Spill Tank Test: 1532205
Site ID: 288842
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 288842
Operable Unit ID: 912622
Operable Unit: 01
Material ID: 465738
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

FINDS:

Registry ID: 110004551173

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

FALA CCG INC (Continued) **1001460264**

corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001460264
Registry ID:	110004551173
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004551173

NY MANIFEST:

Country:	USA
EPA ID:	NYR000067322
Facility Status:	Not reported
Location Address 1:	75 MARCUS DR
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	4278

NY MANIFEST:

EPAID:	NYR000067322
Mailing Name:	FALA CCG INC
Mailing Contact:	HARRY BELECHTO
Mailing Address 1:	75 MARCUS DR
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	4278
Mailing Country:	USA
Mailing Phone:	6313910223

NJ MANIFEST:

EPA Id:	NYR000067322
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	5166941919
Emergency Phone:	Not reported
Contact:	DAVID F. SCHENK
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

FALA CCG INC (Continued) **1001460264**

Date Change: Not reported

Manifest:
Manifest Number: 000111823SKS
EPA ID: NYR000067322
Date Shipped: 01/22/2008
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/22/2008
Date Trans2 Transported Waste: 01/29/2008
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/29/2008
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H061
Quantity: 488 P

Manifest Number: 001327524SKS
EPA ID: NYR000067322
Date Shipped: 11/14/2008
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: TXR000050930

FALA CCG INC (Continued) **1001460264**

Transporter 4 EPA ID:	NJD071629976
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/14/2008
Date Trans2 Transported Waste:	11/18/2008
Date Trans3 Transported Waste:	11/19/2008
Date Trans4 Transported Waste:	11/21/2008
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/21/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	400 P

Manifest Number:	NJA4006080
EPA ID:	NYR000067322
Date Shipped:	03/23/2004
TSDF EPA ID:	NJR000022442
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	MOR000505347
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/23/2004
Date Trans2 Transported Waste:	03/30/2004
Date Trans3 Transported Waste:	Not reported

FALA CCG INC (Continued) **1001460264**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/31/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04280421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

P72 **FALA DIRECT MARKETING** **NY UST** **U003537613**
SW **75 MARCUS DR** **N/A**
1/8-1/4 **MELVILLE, NY 11747**
0.231 mi.
1221 ft. **Site 2 of 2 in cluster P**

Relative: **Lower**
Actual: **102 ft.**

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	8603
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	8603
Facility Reference #:	Not reported
Official Use:	Removed Tank. 88
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	24290
Installed:	Not reported
Capacity:	5000
Substance:	#2 FUEL OIL
Date Removed:	11/22/1927
Construction:	STEEL
Dispenser:	SUCTION

FALA DIRECT MARKETING (Continued) **U003537613**

Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	5000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/22/1927
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	2
Tank Key:	24291
Installed:	88
Capacity:	4000
Substance:	#2 FUEL OIL
Date Removed:	11/11/1958
Construction:	FRP / FRP
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	4000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	11/11/1958
Year Installed:	88
Description of drop records:	Not reported

O73 **MAYTAG BLDG** **NY UST** **U003960871**
SSE **100 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.231 mi.
1222 ft. **Site 3 of 4 in cluster O**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	363
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	363
Facility Reference #:	Not reported
Official Use:	Abandoned, approved by plan review, awaiting construction for compliance inspection. 86
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported
Tank ID:	1
Tank Key:	1122
Installed:	60
Capacity:	3000
Substance:	GASOLINE
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	11/20/1927
Year Installed:	60
Description of drop records:	Not reported

O74 **PRECIPART CORP** **RCRA-SQG** **1004762133**
SSE **100 FINN CT** **FINDS** **NYR000093864**
1/8-1/4 **FARMINGDALE, NY 11735** **ECHO**
0.231 mi. **NY MANIFEST**
1222 ft. **Site 4 of 4 in cluster O**

Relative:
Lower

Actual:
101 ft.

RCRA-SQG:

Date form received by agency:	06/25/2014
Facility name:	PRECIPART CORP
Facility address:	100 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYR000093864
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	DANIEL RUDOLF
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	631-694-3100
Contact email:	DRUDOLF@PRECIPART.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	PRECIPART CORPORATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1997
Owner/Op end date:	Not reported

Owner/operator name:	MCS REALTY CO-FINKELSTEIN REALTY
Owner/operator address:	450 JERICHO TNPK MINEOLA, NY 11504
Owner/operator country:	US
Owner/operator telephone:	516-747-5544
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	MCS REALTY LLC/CUSHMAN & WAKEFIELD INC
Owner/operator address:	OLD COUNTY RD 4TH FL MINEOLA, NY 11501

PRECIPART CORP (Continued) **1004762133**

Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/21/2002
Owner/Op end date: Not reported

Owner/operator name: MCS REALTY CO-FINKELSTEIN REALTY
Owner/operator address: 450 JERICHO TNPK
MINEOLA, NY 11504
Owner/operator country: US
Owner/operator telephone: 516-747-5544
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

PRECIPART CORP (Continued) **1004762133**

Historical Generators:
Date form received by agency: 01/01/2007
Site name: PRECIPART CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: PRECIPART CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/05/2001
Site name: PRECIPART CORP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 02/14/2017
Date achieved compliance: 03/02/2017
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/2017
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/22/2017
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 10/06/2008
Date achieved compliance: 10/23/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/25/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 11/25/2008
Enforcement lead agency: State

PRECIPART CORP (Continued) **1004762133**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/14/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 03/02/2017
Evaluation lead agency: State

Evaluation date: 10/06/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 10/23/2008
Evaluation lead agency: State

FINDS:

Registry ID: 110004566979

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004762133
Registry ID: 110004566979
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004566979

NY MANIFEST:
Country: USA
EPA ID: NYR000093864
Facility Status: Not reported
Location Address 1: 100 FINN CT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE

PRECIPART CORP (Continued) **1004762133**

Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000093864
Mailing Name: PRECIPART - NORTH
Mailing Contact: DANIEL RUDOLF
Mailing Address 1: 100 FINN CT
Mailing Address 2: Not reported
Mailing City: FARMINGDALE
Mailing State: NY
Mailing Zip: 11735
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6316943100

N75 **AIRCRAFT PARTS INC** **NY AST** **1001079634**
SSE **160 FINN COURT** **RCRA NonGen / NLR** **NYN008001331**
1/8-1/4 **FARMINGDALE, NY 11735** **FINDS**
0.240 mi. **ECHO**
1267 ft. **Site 10 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

AST_SUFFOLK:
Region: SUFFOLK
Site Ref#: 100
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 100
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 2
Tank Key: 488
Year Installed: 90
Substance: DRUM STORAGE
Construction: Not reported
Dispenser: Not reported
Official Use: Removed Tank. 04
Permit to Operate: 10/1/2147
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 1440
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported

AIRCRAFT PARTS INC (Continued) **1001079634**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	7/11/2150

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AIRCRAFT PARTS CORP
Facility address:	160 FINN CT FARMINGDALE, NY 11735-1107
EPA ID:	NYN008001331
Mailing address:	FINN CT FARMINGDALE, NY 11735-1107
Contact:	Not reported
Contact address:	FINN CT FARMINGDALE, NY 11735-1107
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	UNK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

AIRCRAFT PARTS INC (Continued) **1001079634**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AIRCRAFT PARTS CORP
Classification: Not a generator, verified

Date form received by agency: 09/29/1995
Site name: AIRCRAFT PARTS CORP
Classification: Unverified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/23/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004349232

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIRCRAFT PARTS INC (Continued) **1001079634**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079634
Registry ID: 110004349232
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004349232

N76 **AIRCRAFT PARTS CORP** **NY UST** **U003960604**
SSE **160 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.240 mi.
1267 ft. **Site 11 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

SUFFOLK CO. UST:
Region: SUFFOLK
Site Ref#: 100
Status: Not reported
Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 100
Facility Reference #: Not reported
Official Use: Removed Tank. 04
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK
Permit to Operate: Not reported

Tank ID: 1
Tank Key: 487
Installed: Not reported
Capacity: 3000
Substance: #2 FUEL OIL
Date Removed: 7/11/2150
Construction: STEEL
Dispenser: SUCTION
Fill Type: PUMPED
Tank Location: UNDER
Tabk Status: Not reported
Total Capacity: 3000
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported

AIRCRAFT PARTS CORP (Continued) **U003960604**

Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	7/11/2150
Year Installed:	Not reported
Description of drop records:	Not reported

N77 **AIRCRAFT PARTS INC** **RCRA-SQG 1000180713**
SSE **160 FINN CT** **NY LTANKS NYD013561139**
1/8-1/4 **FARMINGDALE, NY 11735** **NY MANIFEST**
0.240 mi. **NJ MANIFEST**
1267 ft. **Site 12 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	AIRCRAFT PARTS INC
Facility address:	160 FINN CT FARMINGDALE, NY 11735
EPA ID:	NYD013561139
Mailing address:	FINN CT FARMINGDALE, NY 11735
Contact:	WILLIAM PADEN
Contact address:	FINN CT FARMINGDALE, NY 11735
Contact country:	US
Contact telephone:	516-249-3053
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	S. SHERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	S. SHERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AIRCRAFT PARTS INC
Classification: Small Quantity Generator

Date form received by agency: 06/09/1989
Site name: AIRCRAFT PARTS INC
Classification: Small Quantity Generator

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

AIRCRAFT PARTS INC (Continued) **1000180713**

Evaluation Action Summary:
- Evaluation date: 02/23/1995
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA

LTANKS:
- Facility ID: 9304294
- Site ID: 144446
- Closed Date: 2003-09-30
- Spill Number: 9304294
- Spill Date: 1993-07-06
- Spill Cause: Tank Test Failure
- Spill Source: Commercial/Industrial
- Spill Class: B3
- Cleanup Ceased: Not reported
- SWIS: 5220
- Investigator: T/T/F
- Referred To: Not reported
- Reported to Dept: 1993-07-06
- CID: Not reported
- Water Affected: Not reported
- Spill Notifier: Tank Tester
- Last Inspection: Not reported
- Recommended Penalty: False
- Meets Standard: True
- UST Involvement: False
- Remediation Phase: 0
- Date Entered In Computer: 1993-07-07
- Spill Record Last Update: 2014-08-19
- Spiller Name: BILL PADEN
- Spiller Company: AIRCRAFT PARTS CORP
- Spiller Address: Not reported
- Spiller County: 001
- Spiller Contact: Not reported
- Spiller Phone: Not reported
- Spiller Extention: Not reported
- DEC Region: 1
- DER Facility ID: 123130
- DEC Memo: "SYSTEM FAILED RETEST 7/29/93 SYSTEM PASSED RETEST 8/3/93 AFTER TANK WAS BLED"
- Remarks: "DUE TO AIR POCKET WILL SPEAK TO BILL PADEN & INVESTIGATE AIR POCKET AND RETEST, 3K FAILED AT -.156, TYREE TESTER"

All TTF:
- Facility ID: 9304294
- Spill Number: 9304294
- Spill Tank Test: 1541738
- Site ID: 144446
- Tank Number: Not reported
- Tank Size: 0
- Material: 0001
- EPA UST: Not reported
- UST: Not reported
- Cause: Not reported
- Source: Not reported
- Test Method: 00

AIRCRAFT PARTS INC (Continued) **1000180713**

Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 144446
Operable Unit ID: 982742
Operable Unit: 01
Material ID: 397812
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYD013561139
Facility Status: Not reported
Location Address 1: 160 FINN COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD013561139
Mailing Name: AIRCRAFT PARTS
Mailing Contact: AIRCRAFT PARTS
Mailing Address 1: 100 CORPERATE DR
Mailing Address 2: Not reported
Mailing City: HOLTSVILLE
Mailing State: NY
Mailing Zip: 11742
Mailing Zip 4: 2004
Mailing Country: USA
Mailing Phone: 5162483053

NJ MANIFEST:
EPA Id: NYD013561139
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: 5162493053
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported

AIRCRAFT PARTS INC (Continued) **1000180713**

SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Manifest:

Manifest Number:	NJA5213753
EPA ID:	NYD013561139
Date Shipped:	07/26/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD980525786
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2005
Date Trans2 Transported Waste:	08/03/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/03/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12050521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

N78 **ULTIMATE PRECISION METAL PRODUCTS** **NY AST** **A100264688**
SSE **200 FINN CT** **N/A**
1/8-1/4 **FARMINGDALE, NY 11735**
0.246 mi.
1297 ft. **Site 13 of 13 in cluster N**

Relative:
Lower

Actual:
101 ft.

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	1073
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	1073
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	3068
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	819
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Tank ID:	2
Tank Key:	47071
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Not in Compliance (Date - 82)
Permit to Operate:	Not reported
Tank Location:	ABOVE

ULTIMATE PRECISION METAL PRODUCTS (Continued) **A100264688**

Tabk Status:	Not reported
Total Capacity:	1815
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	3
Tank Key:	47673
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	GRAVITY
Official Use:	Plans have been approved and awaiting construction
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	220
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	Not reported

79
SW
1/4-1/2
0.257 mi.
1355 ft.

NORTHROP GRUMMAN
65 MARCUS DRIVE
MELVILLE, NY

NY LTANKS
NY Spills

S100149169
N/A

Relative:
Lower

Actual:
102 ft.

LTANKS:

Facility ID:	8706384
Site ID:	145270
Closed Date:	1988-02-12
Spill Number:	8706384
Spill Date:	1987-10-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1988-02-12
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1987-10-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-29
Spill Record Last Update:	2014-03-28
Spiller Name:	Not reported
Spiller Company:	SEDCO SYSTEMS
Spiller Address:	65 MARCUS DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	294934
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD / / : F&N TESTER.AS PER SCOTT SCHUCK,ORIGINAL TEST FAILED DUE TO POOR CIRCULATION.ON 1/21/88,F&N RETESTED SYSTEM & PASSED. DEC NOT PRESENT. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	"10K FAILED AT -.373"

All TTF:

Facility ID:	8706384
Spill Number:	8706384
Spill Tank Test:	1532072
Site ID:	145270
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

NORTHROP GRUMMAN (Continued) **S100149169**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	145270
Operable Unit ID:	910098
Operable Unit:	01
Material ID:	465399
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0302056
Facility Type:	ER
Spill Number:	0302056
DER Facility ID:	294934
Site ID:	145269
DEC Region:	1
Closed Date:	2008-07-16
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2003-05-28
Investigator:	NJACAMPO
Referred To:	Not reported
Reported to Dept:	2003-05-28
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-28
Spill Record Last Update:	2014-03-28
Spiller Name:	Not reported
Spiller Company:	JET SANITATION SERVICE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BILL GOING
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ACAMPORA TELECON CALLER-NO SOIL OR DRAINS AFFECTED, HAS BEEN CLEANED UP WITH ABSORBANTS CLEANUP COMPLETED"
Remarks:	"A HYDRAULIC LINE RUPTURED ON THE LIFT ARM OF THE TRUCK WHEN IT WAS

NORTHROP GRUMMAN (Continued) **S100149169**

PICKING UP A DUMPSTER - JET SANITATION CLEANED UP THE SPILL"

All Materials:

Site ID:	145269
Operable Unit ID:	868605
Operable Unit:	01
Material ID:	506541
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00
Units:	G
Recovered:	12.00
Oxygenate:	Not reported

80
NW
1/4-1/2
0.282 mi.
1489 ft.

WE'RE ASSOCIATES
100 BAYLIS ROAD
MELVILLE, NY

NY LTANKS **S104513962**
N/A

Relative:
Higher

Actual:
107 ft.

LTANKS:

Facility ID:	8803165
Site ID:	224161
Closed Date:	1988-08-25
Spill Number:	8803165
Spill Date:	1988-07-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-08-25
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-07-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-14
Spill Record Last Update:	2006-06-15
Spiller Name:	Not reported
Spiller Company:	WERE ASSOCIATES
Spiller Address:	100 JERICHO QUADRANGLE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	290926
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 08/25/88: F&N RETESTED SYSTEM AFTER NO REPAIRS & SYSTEM

WE'RE ASSOCIATES (Continued) **S104513962**

Remarks:	PASSED.F&N USED 2 CIRCULATORS ON RETEST INSTEAD OF 1. DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES " "7500 FAILED AT -.151 GPH. ISOLATE TANK TEST FAILURE-INITIAL PETROTITE TEST 2 TANKS AS SITE. NORTH TANK FAILED. WILL EITHER RETEST OR PULL TANK. F&N TESTER."

All TTF:

Facility ID:	8803165
Spill Number:	8803165
Spill Tank Test:	1534273
Site ID:	224161
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	224161
Operable Unit ID:	920329
Operable Unit:	01
Material ID:	458726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9003860
Site ID:	224162
Closed Date:	1995-04-05
Spill Number:	9003860
Spill Date:	1990-07-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1995-04-05
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1990-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

WE'RE ASSOCIATES (Continued) **S104513962**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	2009-07-08
Spiller Name:	HERB HANSON
Spiller Company:	WE'RE ASSOCIATES
Spiller Address:	JERICHO QUAD SUITE 106
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	290926
DEC Memo:	"RETEST PASSED, AWAITING FOR RESULTS PER SCHD TANK SYS #2 PASSED 7/12/90, SEE SAME FOR DOCUMENTATION, NO FURTHER ACTION NEEDED AT THIS TIME"
Remarks:	"7500 FAILED AT -0.147 GPH. F&N TESTER. TROUBLE WITH CIRCULATION. RETEST BEFORE DIGGING"

All TTF:

Facility ID:	9003860
Spill Number:	9003860
Spill Tank Test:	1537273
Site ID:	224162
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	224162
Operable Unit ID:	941680
Operable Unit:	01
Material ID:	434989
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q81
WSW
1/4-1/2
0.328 mi.
1733 ft.

FIRST VEHICLE SERVICES
55 MARCUS DR
MELVILLE, NY 11747

Site 1 of 2 in cluster Q

NY LTANKS **S108651007**
NY Spills **N/A**
NY MANIFEST

Relative:
Lower

Actual:
100 ft.

LTANKS:

Facility ID:	8805536
Site ID:	274806
Closed Date:	1988-10-31
Spill Number:	8805536
Spill Date:	1988-09-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1988-10-31
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-09-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-30
Spill Record Last Update:	2014-03-28
Spiller Name:	Not reported
Spiller Company:	GABAR CO
Spiller Address:	55 MARCUS DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	223522
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 10/31/88: BAIN RETESTED SYSTEM ON 10/5 AFTER MANWAYS WAS BLED & OEM VENT ALARM WAS REPAIRED & SYSTEM PASSED.DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"BAINE CORP TESTER. 7500 FAILED AT -.164 GPH. PETROTITE TEST"

All TTF:

Facility ID:	8805536
Spill Number:	8805536
Spill Tank Test:	1534697
Site ID:	274806
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

FIRST VEHICLE SERVICES (Continued) **S108651007**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 274806
Operable Unit ID: 922517
Operable Unit: 01
Material ID: 457439
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 0508683
Facility Type: ER
Spill Number: 0508683
DER Facility ID: 223522
Site ID: 354316
DEC Region: 1
Closed Date: 2006-01-17
Spill Cause: Traffic Accident
Spill Class: C3
SWIS: 5226
Spill Date: 2005-10-19
Investigator: WXPRZYLO
Referred To: Not reported
Reported to Dept: 2005-10-19
CID: 73
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-10-20
Spill Record Last Update: 2008-06-30
Spiller Name: MARVIN COLEMAN
Spiller Company: COVENANT TRANSPORT
Spiller Address: 400 BURMINGHAM HWY
Spiller Company: 001
Contact Name: ANN WORTMAN
DEC Memo: "11/19/05 24:00 VALDI TELECON TO ANN WORTMAN, SPILL ON THE SURFACE, NO DRAINS AFFECTED. CLEANUP WAS ONGOING, 2-55 GAL OF STREET SWEEPER, HMHTTC COMPANY CLEANUP HAS BEEN COMPLETED, NO FURTHER ACTION REQUIRED"
Not reported

FIRST VEHICLE SERVICES (Continued) **S108651007**

Remarks: "DRIVER OF TRACTOR TRAILER RAN OVER A CURB CAUSING DAMAGE TO THE OIL PAN. CLEAN UP IN PROGRESS BY HMHTTC. ALTERNATE CONTACT FOR ANN WORTMAN IS 800-226-0911 (OFFICE NUMBER)."

All Materials:

Site ID:	354316
Operable Unit ID:	1111735
Operable Unit:	01
Material ID:	2101782
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NY5168473960
Facility Status:	Not reported
Location Address 1:	55 MARCUS DR
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY5168473960
Mailing Name:	FIRST VEHICLE SERVICES
Mailing Contact:	FIRST VEHICLE SERVICES
Mailing Address 1:	55 MARCUS DR
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5168473960

---

82 **SPILL NUMBER 9713313** **NY LTANKS** **S104619472**
West **98 REPUBLIC ROAD** **N/A**
1/4-1/2 **MELVILLE, NY**
0.336 mi.
1772 ft.

Relative: **Lower**

Actual: **98 ft.**

LTANKS:

Facility ID:	9713313
Site ID:	182849
Closed Date:	1998-08-26
Spill Number:	9713313
Spill Date:	1998-03-02

SPILL NUMBER 9713313 (Continued) **S104619472**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5200
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1998-03-02
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-02
Spill Record Last Update:	1998-08-27
Spiller Name:	ROGER SCHMIDT
Spiller Company:	Not reported
Spiller Address:	98 REPUBLIC ROAD
Spiller County:	001
Spiller Contact:	ROGER SCHMIDT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	153189
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA PER DEAN ANSON, CLIENT HAD PHASE II DONE BY ANOTHER FIRM IN 9/97. FOUND CONTAMINATION IN EXCEEDENCE OF STARS. CLIENT IS A SOD FARM, 2-275 GAL GASOLINE TANKS REMOVED WITH AN OVERSIGHT DURING THE 80'S. CLIENT INTERESTED IN PROPERTY TRANSFER. ANSON HAS COMPILED REPORT AND WILL SEND IT TO THE OFFICE RECENT SOIL BORING SHOWED NO SOIL OR GW CONTAMINATION "
Remarks:	"CALLER REPORTED SITE SURVEY AND FOUND CONTAMINATED SOIL AT SITE OF FORMER TANK."

All Materials:

Site ID:	182849
Operable Unit ID:	1059322
Operable Unit:	01
Material ID:	324332
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

83
South
1/4-1/2
0.344 mi.
1814 ft.

KALMAR DESIGNS
485 SMITH STREET
FARMINGDALE, NY

NY LTANKS
NY Spills

S101856411
N/A

Relative:
Lower

Actual:
100 ft.

LTANKS:

Facility ID:	9209410
Site ID:	70689
Closed Date:	1992-11-13
Spill Number:	9209410
Spill Date:	1992-09-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-11-13
SWIS:	5200
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1992-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-11-13
Spill Record Last Update:	1992-11-13
Spiller Name:	Not reported
Spiller Company:	KALMAR DESIGNS
Spiller Address:	485 SMITH ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	67029
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was NONE 11/13/92: NO RESPONSE. "
Remarks:	"1-5K FUEL OIL TANK REMOVED, DETERIORATED, LEAKAGE FROM SUPPLY LINE CONT SOIL REMOVED. SCDH ON SITE DURING REMOVAL"

All Materials:

Site ID:	70689
Operable Unit ID:	976001
Operable Unit:	01
Material ID:	406461
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

KALMAR DESIGNS (Continued) **S101856411**

SPILLS:

Facility ID:	1111958
Facility Type:	ER
Spill Number:	1111958
DER Facility ID:	414346
Site ID:	459878
DEC Region:	1
Closed Date:	2012-09-13
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5220
Spill Date:	2012-01-12
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2012-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-01-12
Spill Record Last Update:	2012-09-17
Spiller Name:	Not reported
Spiller Company:	ALP LIGHTING COMPONENTS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JEFF GOLDSTEIN
DEC Memo:	"01/12/12 1225 Hrs (A): GOLDSTEIN CALLED- HE SAID THIS HAD JUST OCCURRED AND WANTED TO KNOW WHAT NEEDED TO BE DONE. 01/12/12 1225 Hrs (B): He said ALP LIGHTING COMPONENTS was delivering to his company when the TRUCK FUEL FILTER leaked. 01/12/12 1225 Hrs (C): He said 'PERHAPS 5GAL TOTAL LEAKED; THEY PLACED A BUCKET UNDER THE LEAK AND CAUGHT MOST OF THE PRODUCT BUT PERHAPS 1-2GAL ENTERED A DRAIN'. 01/12/12 1225 Hrs (D): Goldstein also said his maintenance company had already cleaned up the pavement with speedi dri. DEC informed him that if there was only a few gallons of fuel in the drain it could be removed with sorbent pads, and that if the maintenance company did not have any Tyree Environmental was located nearby. 01/12/12 1225 Hrs (E): DEC also asked Goldstein to call the Hotline to report the incident. DR"
Remarks:	"during delivery loss occured into catch basin and pavement, speedy dry applied."

All Materials:

Site ID:	459878
Operable Unit ID:	1209971
Operable Unit:	01
Material ID:	2207546
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum

KALMAR DESIGNS (Continued) **S101856411**

Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

R84 **VENUS SCIENTIFIC INC** **NY LTANKS** **1000427538**
SSW **399 SMITH ST** **NY UST** **NYD002411866**
1/4-1/2 **FARMINGDALE, NY 11735** **NY AST**
0.354 mi. **RCRA NonGen / NLR**
1867 ft. **Site 1 of 2 in cluster R** **FINDS**
ECHO
Relative: Lower **NY MANIFEST**

Actual: 100 ft.

LTANKS:
Facility ID: 8803558
Site ID: 287908
Closed Date: 1988-09-29
Spill Number: 8803558
Spill Date: 1988-07-23
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-09-29
SWIS: 3024
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1988-07-25
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-07-25
Spill Record Last Update: 2006-06-12
Spiller Name: Not reported
Spiller Company: VENUS SCIENTIFIC
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 233207
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 09/29/88: TANK WAS REMOVED BY TYREE ON 9/22. THERE WAS NO CONTAMINATION FOUND. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks: "2K TANK FAILED AT -.455 GPH. ALL COUNTY TANK TESTING TESTER. NO ACTION YET. NEEDS 3 OPTION TO TANK OWNER,NOTIFICATION TO TANK TESTER."
Not reported

All TTF:
Facility ID: 8803558
Spill Number: 8803558

VENUS SCIENTIFIC INC (Continued) **1000427538**

Spill Tank Test:	1534330
Site ID:	287908
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	287908
Operable Unit ID:	920738
Operable Unit:	01
Material ID:	459107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	1492
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	1492
Facility Reference #:	Not reported
Official Use:	Removed Tank. 86
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	2
Tank Key:	4193
Installed:	1960
Capacity:	3000
Substance:	GASOLINE
Date Removed:	11/20/1927
Construction:	STEEL
Dispenser:	SUCTION

VENUS SCIENTIFIC INC (Continued) **1000427538**

Fill Type:	GRAVITY
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	3000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	11/20/1927
Year Installed:	1960
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	4194
Installed:	68
Capacity:	2000
Substance:	#2 FUEL OIL
Date Removed:	9/2/2152
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	9/2/2152
Year Installed:	68
Description of drop records:	Not reported

Tank ID:	4

VENUS SCIENTIFIC INC (Continued) **1000427538**

Tank Key:	4195
Installed:	68
Capacity:	2000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	2000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	68
Description of drop records:	Not reported

Tank ID:	5
Tank Key:	4196
Installed:	Not reported
Capacity:	5000
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	PUMPED
Tank Location:	UNDER
Tabk Status:	Not reported
Total Capacity:	5000
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Fill:	PUMPED
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	1492
Status:	Not reported
Site Type:	Not reported
Operating Permit Expires:	Not reported
Owner/Storage Information:	Not reported
Year:	2006

Tank Info:

Facility ID:	1492
Facility Reference #:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Tank ID:	1
Tank Key:	4192
Year Installed:	84
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	OTHER
Official Use:	Removed Tank. 92
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1500
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	GRAVITY
Date Removed:	5/22/2100
Tank ID:	6
Tank Key:	4197
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported

VENUS SCIENTIFIC INC (Continued) **1000427538**

Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	1925
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

Tank ID:	7
Tank Key:	4198
Year Installed:	Not reported
Substance:	DRUM STORAGE
Construction:	Not reported
Dispenser:	Not reported
Official Use:	Never Installed
Permit to Operate:	Not reported
Tank Location:	ABOVE
Tabk Status:	Not reported
Total Capacity:	220
Date Permitted:	Not reported
Date Closed:	Not reported
Internal Protection:	Not reported
Secondary Containment:	Not reported
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	VENUS SCIENTIFIC INC
Facility address:	399 SMITH ST FARMINGDALE, NY 11735-1106

VENUS SCIENTIFIC INC (Continued) **1000427538**

EPA ID: NYD002411866
Mailing address: SMITH ST
FARMINGDALE, NY 11735
Contact: Not reported
Contact address: SMITH ST
FARMINGDALE, NY 11735
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

VENUS SCIENTIFIC INC (Continued) **1000427538**

Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: VENUS SCIENTIFIC INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: VENUS SCIENTIFIC INC
Classification: Not a generator, verified

Date form received by agency: 04/29/1982
Site name: VENUS SCIENTIFIC INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS

VENUS SCIENTIFIC INC (Continued) **1000427538**

LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - General
- Date violation determined: 08/21/1986
- Date achieved compliance: 11/06/1986
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 09/26/1986
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 08/21/1986
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Generators - General
- Date achieved compliance: 11/06/1986
- Evaluation lead agency: State

FINDS:

Registry ID: 110004341285

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1000427538
- Registry ID: 110004341285
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004341285

NY MANIFEST:
- Country: USA
- EPA ID: NYD002411866
- Facility Status: Not reported
- Location Address 1: 399 SMITH STREET
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: FARMINGDALE
- Location State: NY

VENUS SCIENTIFIC INC (Continued) **1000427538**

Location Zip: 11735
Location Zip 4: 1106

NY MANIFEST:
EPAID: NYD002411866
Mailing Name: VENUS SCIENTIFIC INC.
Mailing Contact: RAPLPH STAELGRAEVE
Mailing Address 1: 11878 HUBBARD ST.
Mailing Address 2: Not reported
Mailing City: LIVONIA
Mailing State: MI
Mailing Zip: 48150
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162934100

R85 **HT STEEL** **NY LTANKS S109827048**
SSW **375 SMITH STREET** **NY Spills N/A**
1/4-1/2 **FARMINGDALE, NY**
0.359 mi.
1894 ft. **Site 2 of 2 in cluster R**

Relative: **Lower**
Actual: **100 ft.**

LTANKS:
Facility ID: 9311399
Site ID: 84738
Closed Date: 1994-02-15
Spill Number: 9311399
Spill Date: 1993-12-21
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: E4
Cleanup Ceased: 1994-02-15
SWIS: 3000
Investigator: T/T/F
Referred To: Not reported
Reported to Dept: 1993-12-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-12-24
Spill Record Last Update: 2001-11-27
Spiller Name: Not reported
Spiller Company: ROBERTS REALTY
Spiller Address: 20 SEAVIEW BLVD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 77900
DEC Memo: ""
Remarks: "5K FAILED AT -.109, VOLINO & SONS TESTER, LANDLORD WAS NOTIFIED"

HT STEEL (Continued) **S109827048**

All TTF:

Facility ID:	9311399
Spill Number:	9311399
Spill Tank Test:	1542322
Site ID:	84738
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84738
Operable Unit ID:	990023
Operable Unit:	01
Material ID:	390438
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9909028
Facility Type:	ER
Spill Number:	9909028
DER Facility ID:	391854
Site ID:	296440
DEC Region:	1
Closed Date:	2000-02-11
Spill Cause:	Other
Spill Class:	B3
SWIS:	5220
Spill Date:	1999-10-25
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	1999-10-25
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

HT STEEL (Continued) **S109827048**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-25
Spill Record Last Update:	2010-07-07
Spiller Name:	OWNER
Spiller Company:	HT STEEL CO
Spiller Address:	375 SMITH STREET
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA ***SAME AS 9925362*** SOIL EXCAVATED AND DISPOSED, END POINTS ARE CLEAN"
Remarks:	"CONTAMINATION FOUND DURING ROUTINE REMOVAL OF 1 5,000GAL FUEL OIL TANK. ***SAME AS 9925362***"

All Materials:

Site ID:	296440
Operable Unit ID:	1087707
Operable Unit:	01
Material ID:	298125
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0903613
Facility Type:	ER
Spill Number:	0903613
DER Facility ID:	364816
Site ID:	415731
DEC Region:	1
Closed Date:	2010-01-06
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5220
Spill Date:	2009-06-27
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2009-06-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-27
Spill Record Last Update:	2010-02-12
Spiller Name:	JOE BARBERA

HT STEEL (Continued) **S109827048**

Spiller Company: NATIONAL GRID
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOSEPH BARBERA
DEC Memo: "0903613, National Grid, no calls (BD)"
Remarks: "1124 The caller advised dispatch a transformer failed causing the spill. No water ways affected. The sustance leaked into dirt area. The clean up will be conducted by waste recycling solutions."

All Materials:
Site ID: 415731
Operable Unit ID: 1172061
Operable Unit: 01
Material ID: 2163913
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

---

86 **MINMILT REALTY (HYGRADE METAL MOULDING)** **NY SHWS** **S106780916**
South **540 SMITH STREET** **NY VCP** **N/A**
1/4-1/2 **EAST FARMINGDALE, NY 11735** **NY VAPOR REOPENED**
0.366 mi.
1930 ft.

Relative:
Lower

Actual:
100 ft.

SHWS:
Program: HW
Site Code: 55887
Classification: 4
Region: 1
Acres: 2.28
HW Code: 152147
Record Add: 11/18/1999
Record Upd: 03/13/2018
Updated By: JBSWARTO
Site Description: Location: This site is a former metal forming facility consisting of a one-story industrial building on a 2.28 acre parcel. The Building is located on Smith Street in the unincorporated Hamlet of East Farmingdale, Suffolk County. Site Features: The Minmilt site is located on the glacial outwash plain of southern-central Long Island. The geology consists mailnly of unconsoliated sand deposits intermixed with smaller, generally non-continuous lower permiability clay and/or silt mix confining units. The upper aquifer is the Upper Glacial aquifer that overlays the Magothy aquifer. Current Zoning and Land Use: The area surrounding the Minmilt Realty site has been zoned entirely commercial/industrial. All the surrounding structures are commercial/industrial as well. Past Use of The Site: Industrial activities at this site included the use of vapor degreasers containing tetrachloroethylene or perchlorethene(PCE). The spent degreaser solvent was disposed into a leaching pool on-site without a SPDES permit. Nature and Extent of Contamination: Minmilt Realty signed an original order with Suffolk County to clean out the dry well. Subsequently, a Consent Order (CO) was signed on November 7,

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

1994 between the NYSDEC and the current owner to conduct a RI/FS and an Interim Remedial Action (IRM). The RI found that soils and groundwater on the east side of the building were highly contaminated with PCE. An IRM consisting of soil vapor extraction (SVE) and groundwater pump and treat were installed in February 1997 and have run continuously, since that time. The PRP investigation of the off-site groundwater plume commenced in December 1998. The remedial systems continue to operate and perform successfully with periodic routine maintenance. In summary, the off-site RI/FS reports were approved. The ROD calling for the continued operation of the SVE system to for soil contamination and the extraction and treatment of the groundwater to for groundwater contamination was signed on March 3, 2002. The potential responsible party (PRP) signed the remedial design and remedial action (RD/RA) order on consent with DEC shortly thereafter. The groundwater pump and treat system contains the plume and continues to contain and remove PCE from the Upper Glacial and Magothy aquifers. Operation, maintenance and monitoring. The shallow monitoring wells on site and downgradient of the source area have cleaned by orders of magnitude and are now below, or are approaching, groundwater standards. Vapor phase activated carbon treatment was removed from the SVE off gas in April 1999 as it was no longer required based on Air Guide 1 stack emission review. The PRPs investigated the potential for soil vapor intrusion into buildings in the area to the satisfaction of NYSDEC/NYSDOH. Results indicated that mitigation for vapor intrusion would not be required. Current Status: All the program elements are in place that allowed the site to be reclassified to class 4. This means the remedial program specified in the ROD is in place and operating and performing successfully. The continued operation, maintenance and monitoring (O,M&M) will be required. Once the remedial system is finished, and additional vapor intrusion testing completed per DEC and DOH requirements, the Minmilt Realty site will be delisted.

Env Problem: Soils and groundwater at the site have been contaminated. The PRP implemented an SVE and near offsite groundwater pump and treat IRM. The O&M data shows that the SVE is nearly complete in removing PCE from soils. As of December 2016, more than 5,500 pounds of PCE has been removed via the soil vapor extraction system. The system continues to operate to remove any resiual vapors to prevent the potential for soil vapor intrusion. As of December 2016, more than 80,000 pounds of solvent have been removed via the groundwater extraction and treatment system. Vertical profiling verified that the clay layers inhibited the vertical migration of the Minmilt Plume to the deeper part of the Magothy aquifer in the vicinity of the source area.

Health Problem: Persons who dig below the ground surface may come into contact with contaminants in subsurface soil. People are not coming into contact site related contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The soil vapor extraction system in operation at the site has been successful in preventing the indoor air quality of the on-site building and an adjacent off-site building from being affected by the contamination in soil vapor.

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Oct. 1982
Disp Term:	May 1990
Lat/Long:	40:45:24:0 / 73:24:20:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MINMILT REALTY
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	HALF HOLLOW HILLS LIBRARY
Owner Company:	MINMILT REALTY
Owner Address:	55 VANDERBILT PARKWAY
Owner Addr2:	Not reported
Owner City,St,Zip:	DIX HILLS, NY 11746
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MINMILT REALTY
Owner Address:	540 SMITH STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Hygrade Metal Moulding Corporation
Owner Address:	540 Smith Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	152147
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152147
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152147
Waste Type:	TETRACHLOROETHYLENE {(PCE OR "PERC.") (F001)}
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD001489269

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS

VCP:
Program Type: VCP
Site Code: 56903
HW Code: V00247
Site Class: N
SWIS: 5222
Region: 1
Town: Brookhaven
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 01/05/2005
Updated By: JBSWARTO
Site Description: This is now Registry site # 152147. This site is a metal forming facility consisting of a one-story industrial building on a 2.28 acre parcel. Industrial activities at this site included the use of vapor degreasers containing tetrachloroethylene (PCE). The spent degreasers were disposed into a leaching pool on-site without a SPDES permit. A Consent Order (CO) was signed on November 7, 1994 between the NYSDEC and the current owner to conduct a RI/FS and an IRM. The RI found that soils on the east side of the building were highly contaminated with PCE at levels up to 820 ppm, and groundwater contained PCE at levels up to 140,000 ppb. An Interim Remedial Measure (IRM) consisting of soil vapor extraction (SVE) and groundwater pump and treat were installed in February 1997 and are now operating. The Suffolk County Department of Health Services installed a monitoring well and took hydro punch samples on Central Avenue, about 1500 feet downgradient of the site, in July 1997. This sampling revealed an extensive PCE plume migrating from the site. An investigation of the off-site groundwater plume commenced in December 1998. Vapor phase activated carbon treatment was removed from the SVE off gas in April 1999 as it was no longer required. The groundwater component is containing the plume and is presently removing a significant mass of PCE from the Upper Glacial and Magothy aquifers. The off-site RI/FS was approved and a ROD calling for the continued operation of the SVE system to address the soil contamination and the extraction and treatment of the groundwater to address the groundwater contamination was signed on March 3, 2002. Operation, maintenance and monitoring continues and shallow monitoring wells on site and downgradient of the source area are beginning to clean up.
Env Problem: Minmilt used a vapor degreaser with Tetrachloroethlyene (PCE) that discharged directly to a drywell on the east side of the building. The PRP implemented an SVE and near offsite groundwater pump and treat IRM. The O&M data shows that the SVE is nearly complete in removing PCE from soils. To date, more than 5,200 pounds of PCE has been removed from the soils and 20,000 pounds from the groundwater. Vertical Profiling verified that the clay layers inhibiting the vertical migration of the Minmilt Plume in the vicinity of the source were continuous.
Health Problem: Not reported
Dump: Not reported
Structure: Not reported

MINMILT REALTY (HYGRADE METAL MOULDING) (Continued) **S106780916**

Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	C/O RICHARD COLE
Owner Company:	MINMILT REALTY
Owner Address:	40 SANTA BARBARA DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	PLAINVIEW, NY 11803
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	J. D'Addario & Company, Inc.
Owner Address:	595 SMITH STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

VAPOR REOPENED:

Site Code:	152147
Facility Status:	Underway

Q87 **EAGLE FUEL TRANSPORT** **NY LTANKS** **S102668276**
SW **50 REPUBLIC ROAD** **NY Spills** **N/A**
1/4-1/2 **MELVILLE, NY**
0.369 mi.
1947 ft. **Site 2 of 2 in cluster Q**

Relative:
Lower

Actual:
100 ft.

LTANKS:

Facility ID:	9201913
Site ID:	243590
Closed Date:	1992-09-28
Spill Number:	9201913
Spill Date:	1992-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-09-28

EAGLE FUEL TRANSPORT (Continued) **S102668276**

SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1992-05-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-19
Spill Record Last Update:	2016-07-14
Spiller Name:	Not reported
Spiller Company:	RAYTHEONE ELECTRONICS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	294936
DEC Memo:	"10K #4 FUEL OIL TANK REMOVED ON 9/25/92,CAMPBELL ON SITE, NO CONTAMINATION WAS FOUND BENEATH OR AROUND THE 10K TANK OR LINES, NO FURTHER ACTION IS REQUIRED AT THIS TIME"
Remarks:	"10K FAILED AT -0.170, F&N TESTER"

All TTF:

Facility ID:	9201913
Spill Number:	9201913
Spill Tank Test:	1540006
Site ID:	243590
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	243590
Operable Unit ID:	969306
Operable Unit:	01
Material ID:	413199
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

EAGLE FUEL TRANSPORT (Continued) **S102668276**

Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	8706348
Facility Type:	ER
Spill Number:	8706348
DER Facility ID:	294936
Site ID:	243589
DEC Region:	1
Closed Date:	1990-08-24
Spill Cause:	Other
Spill Class:	C3
SWIS:	5226
Spill Date:	1987-10-27
Investigator:	MIRZA
Referred To:	Not reported
Reported to Dept:	1987-10-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1990-08-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-29
Spill Record Last Update:	2016-07-14
Spiller Name:	Not reported
Spiller Company:	EAGLE FUEL TRANSPORT
Spiller Address:	744 BROADWAY
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MIRZA FD / / : SCDH NOTIFIED.ABSORBENT MAT'L & SAND PLACED ON SPILL. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"OIL SHOT OUT OF AIR PIPE ONTO PARKING LOT."

All Materials:

Site ID:	243589
Operable Unit ID:	910064
Operable Unit:	01
Material ID:	465361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

88
SSW
1/4-1/2
0.390 mi.
2061 ft.

Relative:
Lower

Actual:
100 ft.

STELLAE INTERNATIONAL
333 SMITH ST
FARMINGDALE, NY 11735

NY ENG CONTROLS **1001961566**
NY INST CONTROL **NYR000083600**
NY VCP
RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

ENG CONTROLS:

Site Code:	58757
HW Code:	V00152
Control Code:	13
Control Type:	ENG
Date Record Added:	11/07/2017
Date Rec Updated:	11/07/2017
Updated By:	TLRIDNER
Site Description:	Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.
Env Problem:	Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab

STELLAE INTERNATIONAL (Continued) **1001961566**

	of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.
Health Problem:	People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-07-27 11:51:00
Record Upd:	2012-10-24 16:34:00
Updated By:	ldennist
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Carl Daguillard
Owner Company:	CG Realty Associates LLC
Owner Address:	c/o Stellae International Inc.
Owner Addr2:	50 Marcus Drive
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Mr. Carl Daguillard
Owner Company:	Stellae International Inc.
Owner Address:	1111Marcus Avenue
Owner Addr2:	Unit 5A
Owner City,St,Zip:	Lake Success, NY 11042
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN

STELLAE INTERNATIONAL (Continued) **1001961566**

Owner Name:	Not reported
Owner Company:	Farmingdale Public Library
Owner Address:	116 Merritts Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	V00152
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	TETRACHLOROETHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W1-0819-98-07(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	W1-0819-99-08(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

INST CONTROL:

Site Code:	58757
Control Name:	Site Management Plan
HW Code:	V00152
Control Code:	32
Control Type:	INST
Dt record added:	11/07/2017
Dt rec updated:	11/07/2017
Updated By:	TLRIDNER
Site Code:	58757
Site Description:	Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is

STELLAE INTERNATIONAL (Continued) **1001961566**

zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is

STELLAE INTERNATIONAL (Continued) **1001961566**

not a concern for off-site structures.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00

STELLAE INTERNATIONAL (Continued) **1001961566**

Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: Monitoring Plan
HW Code: V00152
Control Code: 31
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.
Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab

STELLAE INTERNATIONAL (Continued) **1001961566**

depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A

STELLAE INTERNATIONAL (Continued) **1001961566**

Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: Soil Management Plan
HW Code: V00152
Control Code: 14
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the

STELLAE INTERNATIONAL (Continued) **1001961566**

vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the

STELLAE INTERNATIONAL (Continued) **1001961566**

indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I

STELLAE INTERNATIONAL (Continued) **1001961566**

Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: Landuse Restriction
HW Code: V00152
Control Code: 25
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.
Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site

STELLAE INTERNATIONAL (Continued) **1001961566**

building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard

STELLAE INTERNATIONAL (Continued) **1001961566**

Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: Ground Water Use Restriction
HW Code: V00152
Control Code: 08
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site

STELLAE INTERNATIONAL (Continued) **1001961566**

is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at

STELLAE INTERNATIONAL (Continued) **1001961566**

this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances

STELLAE INTERNATIONAL (Continued) **1001961566**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: Deed Restriction
HW Code: V00152
Control Code: A
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site

STELLAE INTERNATIONAL (Continued) **1001961566**

Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America

STELLAE INTERNATIONAL (Continued) **1001961566**

Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 58757
Control Name: IC/EC Plan
HW Code: V00152
Control Code: 34
Control Type: INST
Dt record added: 11/07/2017
Dt rec updated: 11/07/2017
Updated By: TLRIDNER
Site Code: 58757
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington,

STELLAE INTERNATIONAL (Continued) **1001961566**

Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the

STELLAE INTERNATIONAL (Continued) **1001961566**

subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Carl Daguillard
Owner Company: CG Realty Associates LLC
Owner Address: c/o Stellae International Inc.
Owner Addr2: 50 Marcus Drive
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Mr. Carl Daguillard
Owner Company: Stellae International Inc.
Owner Address: 1111Marcus Avenue
Owner Addr2: Unit 5A
Owner City,St,Zip: Lake Success, NY 11042
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Farmingdale Public Library
Owner Address: 116 Merritts Road
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735
Owner Country: United States of America
HW Code: V00152
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00152
Waste Type: TETRACHLOROETHENE
Waste Quantity: UNKNOWN

STELLAE INTERNATIONAL (Continued) **1001961566**

Waste Code: Not reported
HW Code: V00152
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0819-98-07(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: W1-0819-99-08(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

VCP:
Program Type: VCP
Site Code: 58757
HW Code: V00152
Site Class: A
SWIS: 5220
Region: 1
Town: Babylon
Acres: 13
Date Record Added: 11/30/2000
Date Record Updated: 03/28/2017
Updated By: WJPARISH
Site Description: Site Location: The site is located in both Melville, in the Town of Huntington and Farmingdale within the Town of Babylon, Suffolk County. The current site address is 50 Marcus drive, Huntington, Suffolk County. Prior to the site being redeveloped by the volunteer, the site's address was 333 Smith Street, Farmingdale, Suffolk County. Site Features: The site is approximately 13.0 acres in size. The site is bordered to the north by Marcus Drive and to the south by Smith Street. The property is occupied by a two-story 164,000 square foot building. The volunteer purchased the property and converted the vacated manufacturing building into an office building. The remainder of the site consists of asphalt and concrete paved parking area with limited area of grass cover. Current Zoning/Use: The property is zoned for commercial use and is occupied by an office building in a primarily commercial urban area. Past Use of the site: The site was used by a textile manufacturer (Fairfield Noble) that apparently did some dry cleaning in their operations until 1969. The site was then by Gould Electronics for the manufacture of circuit boards. In the northwest corner of the former building, the soils underlying the former dry cleaning area were contaminated by tetrachloroethylene (PCE). The separator wastes were apparently discharged next to the dry cleaning machines in small hand-dug dry wells inside the building. Some PCE wastes were also discharged to outdoor dry wells. Additionally, run-off from the parking lots entered into various dry wells that resulted in petroleum and metals contamination. Finally, both former operations discharged wastewater to a network of pools along the western side of the site. Discharge was managed via a State Pollutant Discharge Elimination System (SPDES) permit. Some of the

STELLAE INTERNATIONAL (Continued) **1001961566**

pools had antimony and cadmium contamination from dyes. The areas identified as impacted have been remediated as part of the VCP. Site Geology/Hydrogeology: The site is primarily flat and soils consist of fine and medium sands. Depth to groundwater is approximately 45 feet below grade and flows south/southeast, consistent with regional groundwater flow. The project is currently entering into the Site Management Phase. The FER and SMP were approved on April 20, 2016.

Env Problem: Nature and Extent of Contamination: Soil contamination in dry wells, leaching pools and in soils by the northwestern portion of the site building have been remediated. Periodic on-site groundwater monitoring has been terminated due to very minimal contributions from this site. In the fall of 2009, the existing sub-slab depressurization system was modified from passive to active mode of operation in order to improve the amount of sub-slab vapors being captured by the system. The system was installed to address the elevated concentrations of tetrachloroethene present beneath the slab of the building. Based on the Indoor Air Quality (IAQ) sampling conducted in March 2010, when operating, the system is effectively preventing any residual sub-slab vapors from entering the occupied building and adversely effecting indoor air quality. The building is currently vacant. Prior to occupancy the system, which was recently repaired, will be tested and evaluated for mitigation effectiveness. The potential exist for residual soil contamination to remain under the building. Any residual soil that may exist will be addressed by the excavation plan work plan which is part of the approved site management plan.

Health Problem: People are not drinking contaminated water because the area is served by a public water supply that is not affected by this contamination. People will not contact contaminated soils unless they dig below the surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a concern at this time. Furthermore, a sub-slab depressurization system (systems that ventilate/remove the sir beneath the building), and an epoxy sealant on the concrete building slab are in place to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building should the building become re-occupied in the future. Environmental sampling indicates that vapor intrusion is not a concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-27 11:51:00
Record Upd: 2012-10-24 16:34:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN

STELLAE INTERNATIONAL (Continued) **1001961566**

Owner Name:	Carl Daguillard
Owner Company:	CG Realty Associates LLC
Owner Address:	c/o Stellae International Inc.
Owner Addr2:	50 Marcus Drive
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Mr. Carl Daguillard
Owner Company:	Stellae International Inc.
Owner Address:	1111Marcus Avenue
Owner Addr2:	Unit 5A
Owner City,St,Zip:	Lake Success, NY 11042
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Farmingdale Public Library
Owner Address:	116 Merritts Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
HW Code:	V00152
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	TETRACHLOROETHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00152
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W1-0819-98-07(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	W1-0819-99-08(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

RCRA NonGen / NLR:

Date form received by agency:	06/16/2017
Facility name:	STELLAE INTERNATIONAL
Facility address:	333 SMITH ST FARMINGDALE, NY 11735
EPA ID:	NYR000083600

STELLAE INTERNATIONAL (Continued) **1001961566**

Mailing address: SMITH ST
FARMINGDALE, NY 11735
Contact: CARL DAGUILLARD
Contact address: SMITH ST
FARMINGDALE, NY 11735
Contact country: US
Contact telephone: 516-472-6200
Contact email: C_DAGUILLARD@STELLAE.NET
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: RECKSON OPER PARTNERSHIP LP
Owner/operator address: 225 BROAD HOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-694-6900
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RECKSON OPER PARTNERSHIP LP
Owner/operator address: 225 BROAD HOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-694-6900
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CARL DAGUILLARD
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/01/2016
Owner/Op end date: Not reported

Owner/operator name: STELLAE INTERNATIONAL
Owner/operator address: SMITH ST
FARMINGDALE, NY 11735
Owner/operator country: US
Owner/operator telephone: 516-472-6200

STELLAE INTERNATIONAL (Continued) **1001961566**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/01/2016
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Historical Generators:
Date form received by agency: 05/12/2017
Site name: STELLAE INTERNATIONAL
Classification: Large Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 01/01/2007
Site name: RECKSON ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: RECKSON ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 01/12/2000
Site name: RECKSON ASSOCIATES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

STELLAE INTERNATIONAL (Continued) **1001961566**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004560582

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001961566
Registry ID:	110004560582
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004560582

NY MANIFEST:

Country:	USA
EPA ID:	NYR000083600
Facility Status:	Not reported
Location Address 1:	333 SMITH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	FARMINGDALE
Location State:	NY
Location Zip:	11735
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000083600
Mailing Name:	STELLAE INTERNATIONAL
Mailing Contact:	STELLAE INTERNATIONAL
Mailing Address 1:	333 SMITH ST
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6316226678

NY MANIFEST:

Document ID:	Not reported

STELLAE INTERNATIONAL (Continued) **1001961566**

Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	07/06/2017
Trans1 Recv Date:	07/06/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000083600
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX168000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	014985461JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10270
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
4 additional NY_MANIFEST: record(s) in the EDR Site Report.

89
NW
1/4-1/2
0.392 mi.
2070 ft.

WERE ASSOCIATES
80 BAYLIS ROAD
MELVILLE, NY

NY LTANKS **S104513868**
N/A

Relative:
Higher

Actual:
109 ft.

LTANKS:

Facility ID:	8801432
Site ID:	220411
Closed Date:	1989-03-08
Spill Number:	8801432
Spill Date:	1988-05-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-03-08
SWIS:	5226
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	1988-05-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-23
Spill Record Last Update:	2005-05-10
Spiller Name:	Not reported
Spiller Company:	WERE ASSOCIATES
Spiller Address:	100 JERICHO QUAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	182316
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GOERTZ FD 03/08/89: F&N RETESTED SOUTH TANK AFTER AIR WAS BLED & SYS PASSED.DEC NOT PRESENT DURING RETEST.NORTH TANK REMOVED 7/1/88.APPROX 20 YDS OF CONT SOIL STOCKPILED & DISPOSED OF. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES "
Remarks:	"2 TANKS 7500 EACH LEAKAGE RATE: -.231 GPH & -.236 GPH.F&N TESTER TO ISOLATE AND RETEST."

All TTF:

Facility ID:	8801432
Spill Number:	8801432
Spill Tank Test:	1533909
Site ID:	220411
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

WERE ASSOCIATES (Continued) **S104513868**

Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 220411
Operable Unit ID: 918585
Operable Unit: 01
Material ID: 460578
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

90 WNW 1/4-1/2 0.426 mi. 2247 ft. **HENRY SCHEIN CO**
135 DURYEA ROAD
MELVILLE, NY

NY LTANKS S100491449
NY Spills N/A

Relative: Lower
Actual: 104 ft.

LTANKS:
Facility ID: 9007825
Site ID: 247914
Closed Date: 1990-12-12
Spill Number: 9007825
Spill Date: 1990-10-17
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: 1990-12-12
SWIS: 5226
Investigator: KMYAGER
Referred To: Not reported
Reported to Dept: 1990-10-17
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1990-10-19
Spill Record Last Update: 2009-07-20
Spiller Name: RICHARD SCHALLE
Spiller Company: CITICORP CREDIT SERVICE
Spiller Address: 135 DURYEA ROAD
Spiller County: 001
Spiller Contact: Not reported

HENRY SCHEIN CO (Continued) **S100491449**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	331955
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 12/12/90: PASSED TANK ONLY TEST 11/9/90, SYSTEM RETEST 11/26. NO FURTHER ACTION. REMOVED MANWAY, REPLACED GASKETS, ALL PIPING REWORKED. "
Remarks:	"2-7500 TANKS FAILED. F&N TESTER"

All TTF:

Facility ID:	9007825
Spill Number:	9007825
Spill Tank Test:	1537722
Site ID:	247914
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	247914
Operable Unit ID:	948480
Operable Unit:	01
Material ID:	431662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9204935
Site ID:	247915
Closed Date:	1995-04-05
Spill Number:	9204935
Spill Date:	1992-07-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	E4
Cleanup Ceased:	1995-04-05
SWIS:	5200
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	1992-07-29

HENRY SCHEIN CO (Continued) **S100491449**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-03
Spill Record Last Update:	1995-04-06
Spiller Name:	Not reported
Spiller Company:	WE'RE ASSOC
Spiller Address:	100 JERICHO QUAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	203555
DEC Memo:	""
Remarks:	"7500 FAILED PETROTITE, F&N TESTER,2-7500 EAST -.388, WEST -.250, PLAN TO INVESTIGATE & RETEST"

All TTF:

Facility ID:	9204935
Spill Number:	9204935
Spill Tank Test:	1540314
Site ID:	247915
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	247915
Operable Unit ID:	968597
Operable Unit:	01
Material ID:	409178
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

HENRY SCHEIN CO (Continued) **S100491449**

SPILLS:

Facility ID:	0308763
Facility Type:	ER
Spill Number:	0308763
DER Facility ID:	331955
Site ID:	247913
DEC Region:	1
Closed Date:	2004-02-18
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2003-11-17
Investigator:	BXDONOVA
Referred To:	Not reported
Reported to Dept:	2003-11-17
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-17
Spill Record Last Update:	2011-06-03
Spiller Name:	CALLER
Spiller Company:	LIPA
Spiller Address:	333 EARLE OVINGTON BLVD
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BRIAN D 11/18/03 TELECON TO SHAWN DAVIS, 300 GALLON TRANSFORMER 215 GALLONS RECOVERED, ESTIMATED 85 GALLONS SPILLED, SPILL CONTAINED IN PIT BELOW THE TRANSFORMER, 2 YARDS OF SOIL EXCAVATED, BOTTOMS SAMPLES TAKEN SPILL INTO CONTAINED PIT CLEANED BY TRADEWINDS. SAMPLES TAKEN, PCB AND ENDPOINT"
Remarks:	"pad mount transformerdeveloped leak at wire connection no pcb"

All Materials:

Site ID:	247913
Operable Unit ID:	874972
Operable Unit:	01
Material ID:	498684
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	85.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0709659
Facility Type:	ER

HENRY SCHEIN CO (Continued) **S100491449**

Spill Number:	0709659
DER Facility ID:	331955
Site ID:	390769
DEC Region:	1
Closed Date:	2008-07-11
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5226
Spill Date:	2007-12-07
Investigator:	dhraymon
Referred To:	Not reported
Reported to Dept:	2007-12-07
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-12-07
Spill Record Last Update:	2016-07-26
Spiller Name:	Not reported
Spiller Company:	HENRY SCHEIN CO
Spiller Address:	135 DURYEA ROAD
Spiller Company:	999
Contact Name:	STEVEN UCELLINI
DEC Memo:	"ROUTINE REMOVAL OF 2-7500 GAL TANKS 12/07/07: CALLED JR HOLZMACHER- THE TANKS WERE OK. LESS THAN 1 GAL OF OIL LEAKED OUT OF A LINE DURING THE REMOVAL. APPROXIMATELY 8CY OF SOIL WAS REMOVED AND ENDPOINT SAMPLES WERE TAKEN. THE SUFFOLK COUNTY HEALTH DEPARTMENT(ZACH BALDWIN) WAS ON SITE. 12/13/07: Left message for Baldwin- requested copy of his report. 12/26/07: Again left message for Baldwin. 01/16/08: Baldwin left message- looking for the report. 01/31/08 (A): Received Holzmacher's report. ACCORDING TO THE REPORT, MIKE SEAMAN OF SCHD WAS ON SITE TO INSPECT THE FIRST TANK, AND BALDWIN REPLACED HIM TO INSPECT THE SECOND TANK. 01/31/08 (B): It said the tanks were 8,000gal each, not 7,500gal and were laying adjacent to each other. Both were reportedly intact, and endpoint samples were taken from the tank bed. The endpoint data was acceptable. 01/31/08 (C): The report also said an unused fill line was removed FROM ALONGSIDE THE TANKS, and it was from this line that the oil spilled."
Remarks:	"while removing tank there was oil left in a line and it spilled out"

All Materials:

Site ID:	390769
Operable Unit ID:	1147864
Operable Unit:	01
Material ID:	2138338
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

HENRY SCHEIN CO (Continued) **S100491449**

Oxygenate: Not reported

91
North
1/4-1/2
0.435 mi.
2296 ft.

Relative:
Lower

Actual:
102 ft.

ESTEE LAUDER INC RESEARCH PARK
125 PINELAWN RD
MELVILLE, NY 11747

RCRA-SQG **1000552223**
NY LTANKS **NYD986946184**
NY UST
NY Spills
NJ MANIFEST
NY MANIFEST

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	ESTEE LAUDER INC RESEARCH PARK
Facility address:	125 PINELAWN RD MELVILLE, NY 11747
EPA ID:	NYD986946184
Mailing address:	S SERVICE RD MELVILLE, NY 11747
Contact:	JAMES MEYERS
Contact address:	S SERVICE RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	516-454-5333
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	ESTEE LAUDER INC
Owner/operator address:	125 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-531-1173
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ESTEE LAUDER INC
Owner/operator address:	125 PINELAWN RD MELVILLE, NY 11747
Owner/operator country:	US
Owner/operator telephone:	516-531-1716
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ESTEE LAUDER INC RESEARCH PARK
Classification: Small Quantity Generator

Date form received by agency: 04/25/1994
Site name: ESTEE LAUDER INC RESEARCH PARK
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/10/2001
Date achieved compliance: 01/13/2001
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/24/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 07/02/1992
Date achieved compliance: 08/10/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/02/1992
Date achieved compliance: 08/10/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 03/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/07/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/10/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/13/2001
Evaluation lead agency: EPA

Evaluation date: 05/15/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 08/10/1992
Evaluation lead agency: State

Evaluation date: 05/15/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/10/1992
Evaluation lead agency: State

LTANKS:

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Facility ID:	9212267
Site ID:	160346
Closed Date:	1993-02-03
Spill Number:	9212267
Spill Date:	1993-01-28
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	D3
Cleanup Ceased:	1993-02-03
SWIS:	5200
Investigator:	RICE
Referred To:	Not reported
Reported to Dept:	1993-01-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-29
Spill Record Last Update:	2002-09-17
Spiller Name:	Not reported
Spiller Company:	MEENAN OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	135416
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RICE 02/03/93: DEC ON SITE, NO DRAINAGE AFFECTED, CLEANUP SATISFACTORY, MEENAN CLEANING UP SPILL. "
Remarks:	"AT ESTEE LAUDER INC."

All Materials:

Site ID:	160346
Operable Unit ID:	979252
Operable Unit:	01
Material ID:	402120
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUFFOLK CO. UST:

Region:	SUFFOLK
Site Ref#:	05089
Status:	ACTIVE
Site Type:	PBS

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Operating Permit Expires:	11/30/2015
Owner/Storage Information:	AVAILABLE
Year:	2015

Facility Info:

Site Ref#:	05089
Billing Contact:	ESTEE LAUDER INC ATTN S TAIANI
Billing Address:	350 SOUTH SERVICE RD
Billing Address:	MELVILLE
Billing State:	NY
Billing Zip:	11747
Storage Owner:	ESTEE LAUDER INC ATTN S TAIANI
Storage Owner Address:	350 SOUTH SERVICE RD
Storage Owner City:	MELVILLE
Storage Owner State:	NY
Storage Owner Zip:	11747

Tank Info:

Facility ID:	05089
Facility Reference #:	Not reported
Official Use:	Not reported
Township:	Not reported
Tax Map No:	Not reported
Region:	SUFFOLK
Permit to Operate:	Not reported

Tank ID:	1
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/20/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Tank ID:	2
Tank Key:	Not reported
Installed:	Not reported
Capacity:	1000 gallons
Substance:	DIESEL
Date Removed:	Not reported
Construction:	FIBER REINFORCED PLASTIC
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	IN SERVICE
Total Capacity:	1000 gallons
Date Permitted:	06/12/1991
Date Closed:	Not reported
Internal Protection:	NONE
Secondary Containment:	SECONDARY WALL - FIBERGLASS
Extrenal Protection:	NONE
Leak Detection:	(DWP) ELECTRONIC LEAK PROBES
Overfill Prevention:	- Electronic Leak Alarm
Spill Prevention:	SPILL/FILL BOX AND/OR SUMP
Pipe Location:	ABOVEGROUND/UNDERGROUND COMBINATION
Pipe Type:	COPPER
Pipe External Protection:	FIBERGLASS (FRP)
Pipe Containment:	FIBERGLASS (FRP)
Pipe Leak Detection:	ELECTRONIC LEAK PROBE ONLY
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

Tank ID:	3
Tank Key:	Not reported
Installed:	Not reported
Capacity:	10000 gallons
Substance:	#2 FUEL OIL
Date Removed:	Not reported
Construction:	STEEL/ IRON
Dispenser:	SUCTION
Fill Type:	Not reported
Tank Location:	UNDER - OUT
Tabk Status:	REMOVED
Total Capacity:	10000 gallons
Date Permitted:	Not reported
Date Closed:	05/20/1991
Internal Protection:	NONE
Secondary Containment:	NONE
Extrenal Protection:	Not reported
Leak Detection:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported
Year Installed:	Not reported
Description of drop records:	Not reported

SPILLS:

Facility ID:	9700756
Facility Type:	ER
Spill Number:	9700756
DER Facility ID:	263498
Site ID:	327342
DEC Region:	1
Closed Date:	1998-06-09
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5200
Spill Date:	1997-04-16
Investigator:	BPAUSTIN
Referred To:	Not reported
Reported to Dept:	1997-04-17
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-17
Spill Record Last Update:	1998-06-10
Spiller Name:	TOM MUCCIO
Spiller Company:	LILCO
Spiller Address:	100 OLD COUNTRY ROAD
Spiller Company:	001
Contact Name:	TOM MUCCIO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN CLEANUP BY LILCO"
Remarks:	"LEAKING BUSHING"

All Materials:

Site ID:	327342
Operable Unit ID:	1043405
Operable Unit:	01
Material ID:	337336
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

NJ MANIFEST:

EPA Id:	NYD986946184
Mail Address:	S SERVICE RD
Mail City/State/Zip:	MELVILLE, NY 11747
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JAMES MEYERS
Comments:	Not reported
SIC Code:	Not reported
County:	NY103
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	5
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000346889VES
EPA ID:	NYD986946184
Date Shipped:	04/27/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D003
Hand Code:	H141
Quantity:	6 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	160 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	10 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	20 P
Manifest Year:	Not reported
Waste Code:	U134
Hand Code:	H141
Quantity:	8 P

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Year: Not reported
Waste Code: D003
Hand Code: H141
Quantity: 1 P

Manifest Year: Not reported
Waste Code: U044
Hand Code: H141
Quantity: 16 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 18 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 1 P

Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 120 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 34 P

Manifest Year: Not reported
Waste Code: F003
Hand Code: H141
Quantity: 1840 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 80 P

Manifest Year: Not reported
Waste Code: D011
Hand Code: H141
Quantity: 9 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 68 P

Manifest Year: Not reported
Waste Code: D009
Hand Code: H141
Quantity: 3 P

Manifest Year: Not reported
Waste Code: F003

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Hand Code:	H141
Quantity:	420 P
Manifest Year:	Not reported
Waste Code:	D003
Hand Code:	H141
Quantity:	28 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	30 P
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	120 P
Manifest Number:	001011744VES
EPA ID:	NYD986946184
Date Shipped:	11/10/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001096524VES
EPA ID:	NYD986946184
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	3
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/29/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000718515VES
EPA ID:	NYD986946184
Date Shipped:	5/12/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000847258VES
EPA ID:	NYD986946184
Date Shipped:	5/21/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Number:	001096524VES
EPA ID:	NYD986946184
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	7
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/29/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000530677VES
EPA ID:	NYD986946184
Date Shipped:	10/28/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	U151
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	30.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	920.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	200.00 Pounds

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	240.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	400.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	40.00 Pounds
Manifest Number:	000972871VES
EPA ID:	NYD986946184
Date Shipped:	3/20/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	4
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	8
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	001062094VES
EPA ID:	NYD986946184
Date Shipped:	1/12/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2016
Waste SEQ ID:	9
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/12/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	001096524VES
EPA ID:	NYD986946184
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	6
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/29/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Number:	001096556VES
EPA ID:	NYD986946184
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/29/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000845216VES
EPA ID:	NYD986946184
Date Shipped:	8/24/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Manifest Number:	000969575VES
EPA ID:	NYD986946184
Date Shipped:	2/13/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	001096524VES
EPA ID:	NYD986946184
Date Shipped:	3/29/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ESTEE LAUDER CO INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/29/2016
Waste SEQ ID:	8
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/29/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported
Manifest Number:	000531269VES
EPA ID:	NYD986946184
Date Shipped:	4/19/2012

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	MELVILLE, NY 11747
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	2.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003 D001 F005
Hand Code:	Not reported
Quantity:	440.00 Pounds
Manifest Year:	Not reported
Waste Code:	F003 D001
Hand Code:	Not reported
Quantity:	40.00 Pounds
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	45.00 Pounds

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Manifest Year: Not reported
Waste Code: F003 D001 F005
Hand Code: Not reported
Quantity: 40.00 Pounds

Manifest Year: Not reported
Waste Code: F002 F005 D022 F003 D001
Hand Code: Not reported
Quantity: 200.00 Pounds

Manifest Year: Not reported
Waste Code: D003 D001
Hand Code: Not reported
Quantity: 1.00 Pounds

Manifest Year: Not reported
Waste Code: F003 D001 F005
Hand Code: Not reported
Quantity: 680.00 Pounds

NY MANIFEST:
Country: USA
EPA ID: NYD986946184
Facility Status: Not reported
Location Address 1: 125 PINE LAWN RD RESEARCH LAB
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: HUNTINGTON
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986946184
Mailing Name: ESTEE LAUDER INC RESEARCH PARK
Mailing Contact: DEBORAH LASKE
Mailing Address 1: 350 SOUTH SERVICE ROAD
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5164547033

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 02/13/2018
Trans1 Recv Date: 02/13/2018

ESTEE LAUDER INC RESEARCH PARK (Continued) **1000552223**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986946184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000968993VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	F005
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
93 additional NY_MANIFEST: record(s) in the EDR Site Report.

---

92 **CANTOR BROTHERS** **NY SHWS** **S104541575**
South **50 ENGINEERS LANE** **NY VCP** **N/A**
1/4-1/2 **EAST FARMINGDALE, NY 11735** **NY Spills**
0.464 mi. **NY VAPOR REOPENED**
2452 ft.

Relative:
Lower

Actual:
99 ft.

SHWS:

Program:	HW
Site Code:	57868
Classification:	4
Region:	1
Acres:	3.2
HW Code:	152021
Record Add:	11/18/1999

CANTOR BROTHERS (Continued) **S104541575**

Record Upd: 05/17/2017
Updated By: JBSWARTO
Site Description: Location: The former Cantor Brothers Site is located at 55 Engineers Lane in Suffolk County, the Town of Babylon in the unincorporated Hamlet of East Farmingdale. Site Features: The former Cantor Brothers Site (site) was a chemical repackaging and handling facility that had been in operation since 1964. The facility building is located in a flat, industrial park setting. Current Zoning/Use: The zoning for this site is commercial/industrial and residential use in this area is prohibited by the Town of Babylon. The former Cantor Building is surrounded by manufacturing and commercial facilities. The current use of the property is warehousing. Past Use(s) of the Site: Substances including organic solvents, creosote and fuel oils were previously observed on the ground surface as a result of leaks from drums and storage tanks. Site inspections by the Suffolk County Department of Health Services (SCDHS) documented numerous spills, illegal discharges and improper storage conditions beginning in 1980. SCDHS arranged to have five monitoring wells installed near the southern boundary of the site. Phase I and Phase II Investigations were completed. Operations at the facility ceased in 1990 and the Responsible Party filed for bankruptcy in 1993. An Interim Remedial Measure (IRM) Investigation was completed in 1997, after the NYS Attorney General's Office represented the NYSDEC in Bankruptcy Court seeking funding for the investigation. The final IRM Summary Report lead to a final agreement and a Stipulated Order for final site remediation. Money totaling $200,000 from the bankruptcy proceedings was set aside in escrow to cover the storm drain cleaning and soil vapor extraction (SVE) remediation programs at the site. These activities were completed using escrow monies under the SSF program. The SVE system operated from 1998 until 2001. The storm drain cleaning was completed in 1998. A Record of Decision was signed in March of 2000. Remedial work involved the removal of soils contaminated with semi-volatile organic compounds from discrete locations on the south side of the building. Installation of a sub-slab depressurization system was completed in 2005. This system ran for eight years and was subsequently removed by new tenants in 2013. A Voluntary Cleanup Agreement (VCA), signed by the current owner, was the mechanism utilized to complete the site remedial work and issue a release to the volunteer. Site Geology and Hydrogeology: The site is located on the glacial outwash plain of the south shore of Long Island. The underlying formation consists mainly of fine sands intermixed, at varying depths of low permeability units, mainly of clay, that exist in continuous and non-continuous segments. The shallow groundwater aquifer is known as the Upper Glacial Aquifer. This overlies the next significant hydro-geologic unit known as the Magothy Aquifer. General groundwater flow is to the south southeast.
Env Problem: Remediation at the site is complete and there are no environmental concerns associated with this site. Prior to remediation, the primary contaminants of concern were non-chlorinated volatile organic compounds.
Health Problem: Soil vapor intrusion is a process by which contaminants in the soil vapor (air spaces within the soil), may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Given the levels of volatile organic compounds detected beneath the on-site building, there is a potential for people to inhale site-related contaminants

CANTOR BROTHERS (Continued) **S104541575**

in indoor air through soil vapor intrusion. However, sampling results indicate the levels detected in indoor air are commonly found in similar structures and do not represent a current health concern. Monitoring of the on-site structure will continue to ensure that the indoor air quality is not impacted. Sampling indicates that soil vapor intrusion is not a concern for off-site structures.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1975
Disp Term:	1990
Lat/Long:	40:45:20:0 / 73:24:17:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2015-05-11 10:40:00
Updated By:	SXSCHARF
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CANTOR BROTHERS, INC.
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	LJM Associates
Owner Address:	50 Engineers Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Cantor Brothers, Inc.
Owner Address:	50 Engineers Lane / PO Box 126
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	MATTHEW MILLER
Owner Company:	CANTOR BROTHERS, INC.
Owner Address:	ENGINEERS LANE, P.O. BOX 126
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	DOCUMENT REPOSITORY
Owner Address:	HALF HOLLOW HILLS LIBRARY
Owner Addr2:	55 VANDERBILT PARKWAY
Owner City,St,Zip:	DIX HILLS, NY 11746

CANTOR BROTHERS (Continued) **S104541575**

Owner Country:	United States of America
HW Code:	152021
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	ORGANIC SOLVENTS, FUEL OILS, CREOSOTE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	CREOSOTE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	TETRACHLOROETHYLENE (PCE OR "PERC.")
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	TRICHLOROETHYLENE {(TCE) (U228- FOO1)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152021
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD001367150
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS

VCP:

Program Type:	VCP
Site Code:	57869
HW Code:	V00193
Site Class:	C
SWIS:	5220
Region:	1
Town:	Babylon
Acres:	3.2
Date Record Added:	11/30/2000
Date Record Updated:	06/01/2017
Updated By:	BXANDERS
Site Description:	This site was a Class 2 Registry site (#152021) at the time of the Volunteer's (LJM Associates) application. Cantor Brothers was a chemical repackaging and handling facility until 1990. The PRP filed for Bankruptcy in 1993. The site is surrounded by manufacturing and commercial facilities. It consisted of a building with drum storage

CANTOR BROTHERS (Continued) **S104541575**

areas, and 16 underground tanks. Organic solvents, creosote, and fuel oils have been observed leaking from drums and storage tanks at the facility. Numerous spills, illegal discharges, and improper storage conditions have been documented since 1980. Investigation showed the presence of VOC soil contamination. The NYSDEC obtained $200,000 in contractual funds from Bankruptcy Court settlement to to cover storm drain cleaning and soil vapor extraction (SVE) remediation. LJM Associates, the new owner, entered the Voluntary Program to take over O&M of the SVE system upon depletion of the contractual escrow funds. The SVE system operated since its construction in 1998 until 2001. The storm drain cleaning was completed in 1998. A Record of Decision was signed in March of 2000. Remedial work since that time has involved the removal of soils contaminated with semivolatile organic compounds from discrete locations on the south side of the building. Installation of a sub-slab depressurization system was completed in 2005. The volunteer submitted a revised work plan to test whether the SSD system is still required. The consultant hired by the volunteer completed the soil Vapor Investigation (SVI) and the SVI report was approved by the DEC (11/2014). The subsequent Voluntary Cleanup Agreement (VCA) sampling included the necessary confirmatory sampling of the sub-slab depressurization (SSD) system to allow for the site reclassification determination. The Minmilt Realty site is adjacent to the former Cantor Brothers building. Monitoring for soil vapor and testing adjacent buildings for soil vapor intrusion fell under the Minmilt Realty site. Therefore, this concern has been addressed.

Env Problem: Historically Organic solvents, fuel oil and creosote leaked from drums and tanks and contaminated soils and drywells on site. The contaminated storm drains were addressed by excavation and removal of contaminated sediments. Contaminated soils beneath and near the site building were addressed by a soil vapor extraction (SVE) system.

Health Problem: Soil vapor intrusion is a process by which contaminants in the soil vapor (air spaces within the soil), may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Given the levels of volatile organic compounds detected beneath the on-site building, there is a potential for people to inhale site-related contaminants in indoor air through soil vapor intrusion. However, sampling results indicate the levels detected in indoor air are commonly found in similar structures and do not represent a current health concern. Monitoring of the on-site structure will continue to ensure that the indoor air quality is not impacted. Sampling indicates that soil vapor intrusion is not a concern for off-site structures.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner

CANTOR BROTHERS (Continued) **S104541575**

Sub Type:	ZZZ
Owner Name:	BRUCE ZABARAUSKAS
Owner Company:	APPLE BANK FOR SAVINGS
Owner Address:	805 THIRD AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10022
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	01
Owner Name:	Not reported
Owner Company:	LJM Associates, Inc.
Owner Address:	139 Carmen Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	East Rockaway, NY 11510-1302
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Linda Montgomery
Owner Company:	LJM Associates
Owner Address:	139 Carmen Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	East Rockaway, NY 11510-1302
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Linda Montgomery
Owner Company:	LJM Associates
Owner Address:	139 Carmen Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	East Rockaway, NY 11510-1302
Owner Country:	United States of America
HW Code:	V00193
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W1-0830-98-10(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

SPILLS:

Facility ID:	8605691
Facility Type:	ER
Spill Number:	8605691
DER Facility ID:	96642
Site ID:	110231
DEC Region:	1
Closed Date:	1987-01-20
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	5220
Spill Date:	1985-12-09
Investigator:	CXONEILL
Referred To:	Not reported
Reported to Dept:	1986-12-09

CANTOR BROTHERS (Continued) **S104541575**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Fire Department
Cleanup Ceased:	1987-01-20
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-17
Spill Record Last Update:	2005-08-29
Spiller Name:	Not reported
Spiller Company:	HETEM TRUCKING
Spiller Address:	601 COMMERCE ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'NEILL FD / / : FD REQUESTS DEC TO RESPOND. MPC HIRED BY SPILLER,473 GALS LIQ RECOVERED. 1/2 YDS SPEEDI DRY. SCDH NOTIFIED.12/9/86 SATISFACTORILY CLEANED. 10/10/95: This is additional information about material spilled from the translation of the old spill file: MINERAL SPIRITS. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES"
Remarks:	""

VAPOR REOPENED:

Site Code:	152021
Facility Status:	Complete (Mitigate)

93
SSW
1/4-1/2
0.481 mi.
2539 ft.

Relative:
Lower

Actual:
97 ft.

FORMERLY EMBASSY INDUSTRIES INC **NY LTANKS** **1000158277**
300 SMITH ST **NY AST** **NYD001217520**
FARMINGDALE, NY 11735 **NY Spills**
RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

LTANKS:

Facility ID:	9100457
Site ID:	144684
Closed Date:	1991-07-22
Spill Number:	9100457
Spill Date:	1991-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1991-07-22
SWIS:	5220
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	1991-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-04-15
Spill Record Last Update:	2015-09-10
Spiller Name:	LEON FELDMAN
Spiller Company:	EMBASSY INDUSTRIES
Spiller Address:	300 SMITH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	371075
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 06/25/91: PIPING REPLACED. SYSTEM RETESTED, PASSED AT -.007 ON 6/3/91. NO FURTHER ACTION."
Remarks:	"10K FAILED AT -.159. PETROTITE SYSTEM TEST. BONAFIDE TESTER"

All TTF:

Facility ID:	9100457
Spill Number:	9100457
Spill Tank Test:	1538444
Site ID:	144684
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	144684
Operable Unit ID:	953999
Operable Unit:	01
Material ID:	426653
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AST_SUFFOLK:

Region:	SUFFOLK
Site Ref#:	591
Status:	Not reported

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Site Type: Not reported
Operating Permit Expires: Not reported
Owner/Storage Information: Not reported
Year: 2006

Tank Info:
Facility ID: 591
Facility Reference #: Not reported
Township: Not reported
Tax Map No: Not reported
Region: SUFFOLK

Tank ID: 4
Tank Key: 2095
Year Installed: Not reported
Substance: VANISHING OIL
Construction: STEEL
Dispenser: Not reported
Official Use: Permitted Tank. Permit Runs Out. 07
Permit to Operate: 2/25/1962
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 330
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe External Protection: Not reported
Pipe Containment: Not reported
Pipe Leak Detection: Not reported
Date Next Tank Test: Not reported
Fill: Not reported
Date Removed: Not reported

Tank ID: 5
Tank Key: 2096
Year Installed: 2002
Substance: DRUM STORAGE
Construction: Not reported
Dispenser: Not reported
Official Use: Permitted Tank. Permit Runs Out. 07
Permit to Operate: 2/25/1962
Tank Location: ABOVE
Tabk Status: Not reported
Total Capacity: 660
Date Permitted: Not reported
Date Closed: Not reported
Internal Protection: Not reported
Secondary Containment: Not reported
Extrenal Protection: Not reported
Leak Detection: Not reported

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe External Protection:	Not reported
Pipe Containment:	Not reported
Pipe Leak Detection:	Not reported
Date Next Tank Test:	Not reported
Fill:	Not reported
Date Removed:	Not reported

SPILLS:

Facility ID:	0110146
Facility Type:	ER
Spill Number:	0110146
DER Facility ID:	371075
Site ID:	144682
DEC Region:	1
Closed Date:	2003-01-17
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	5220
Spill Date:	2002-01-22
Investigator:	BXDONOVA
Referred To:	Not reported
Reported to Dept:	2002-01-22
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-22
Spill Record Last Update:	2015-09-05
Spiller Name:	GEORGE DEMOTT
Spiller Company:	EMBASSY INDUSTRIES
Spiller Address:	300 SMITH STREET
Spiller Company:	001
Contact Name:	GEORGE DEMOTT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BRIAN D PER SELINGER-SURFACE SPILL TO BE EXCAVATED TOMORROW, NCDH WILL BE ON SITE FOR THE INSTALLATION OF A NEW TANK. SELINGER TO CALL ON 1/22/02 WITH UPDATE CONTAMINATED SOIL ASSOCIATED WITH FILL PIPE EXCAVATED BY WINDMILL, 10K FUEL OIL TANK REMOVED, EXCAVATION APPEARED TO BE CLEAN BY SCHD WHO WAS ON SITE 1/23/02"
Remarks:	"fill pipe broke at the tank - unk amount spilled"

All Materials:

Site ID:	144682
Operable Unit ID:	848629
Operable Unit:	01
Material ID:	527778

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0308038
Facility Type:	ER
Spill Number:	0308038
DER Facility ID:	273097
Site ID:	144683
DEC Region:	1
Closed Date:	2005-02-16
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	5226
Spill Date:	2003-10-30
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-10-30
CID:	201
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2015-09-05
Spiller Name:	SEAN DAVIS
Spiller Company:	LIPA
Spiller Address:	333 EARLR OVINGTON BLVD
Spiller Company:	001
Contact Name:	SEAN DAVIS
DEC Memo:	"TRADEWINDS HIRED, NON PCB, TRADEWINDS ON SITE, NO STORM DRAINS, CONTAINED IN 10' X 12' CEMENT BLOCK BLDG"
Remarks:	"PASSANGER VEH STRUCK VAULT CAUSING SPILL. SPILL CONTAINED AND CLEAN UP SHOULD BEGIN AROUND 0900. "

All Materials:

Site ID:	144683
Operable Unit ID:	874369
Operable Unit:	01
Material ID:	562807
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Oxygenate: Not reported

RCRA NonGen / NLR:
Date form received by agency: 03/10/2008
Facility name: FORMERLY EMBASSY INDUSTRIES INC
Facility address: 300 SMITH ST
FARMINGDALE, NY 11735-1175
EPA ID: NYD001217520
Mailing address: BROADHOLLOW RD - SUITE 100
MELVILLE, NY 11747
Contact: BRYAN A DEVAUX
Contact address: BROADHOLLOW RD - SUITE 100
MELVILLE, NY 11747
Contact country: US
Contact telephone: 631-878-9242
Contact email: BRYAND@PWGROSSE.COM
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: P & F INDUSTRIES
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/01/1964
Owner/Op end date: Not reported

Owner/operator name: P & F INDUSTRIES
Owner/operator address: BROADHOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/01/1964
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Historical Generators:
Date form received by agency: 03/09/2008
Site name: FORMERLY EMBASSY INDUSTRIES INC
Classification: Small Quantity Generator

Date form received by agency: 05/25/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Date form received by agency: 05/24/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 04/14/2006
Site name: EMBASSY INDUSTRIES INC
Classification: Large Quantity Generator

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Date form received by agency: 07/08/1999
Site name: EMBASSY INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 06/23/1986
Site name: EMBASSY INDUSTRIES INC
Classification: Large Quantity Generator

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Evaluation Action Summary:
Evaluation date: 09/27/1995
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 09/27/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004332623

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000158277
Registry ID: 110004332623
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004332623

NY MANIFEST:
Country: USA
EPA ID: NYD001217520
Facility Status: Not reported
Location Address 1: 300 SMITH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: FARMINGDALE
Location State: NY
Location Zip: 11735
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001217520
Mailing Name: EMBASSY INDUSTRIES INCORPORATED
Mailing Contact: EMBASSY INDUSTRIES INCORPORATED
Mailing Address 1: 315 OSER AVE
Mailing Address 2: Not reported
Mailing City: HAUPPAUGE
Mailing State: NY
Mailing Zip: 11788
Mailing Zip 4: 3607

FORMERLY EMBASSY INDUSTRIES INC (Continued) **1000158277**

Mailing Country: USA
Mailing Phone: 5166941800

S94 **ASTRO ELECTROPLATING, INC.** **NY SHWS** **S108131276**
South **170 CENTRAL AVENUE** **NY Spills** **N/A**
1/2-1 **EAST FARMINGDALE, NY 11735**
0.600 mi.
3168 ft. **Site 1 of 3 in cluster S**

Relative:
Lower

Actual:
96 ft.

SHWS:
Program: HW
Site Code: 58178
Classification: 2
Region: 1
Acres: 2.9
HW Code: 152036
Record Add: 11/18/1999
Record Upd: 03/06/2018
Updated By: GTBOBERS
Site Description: Location: The Astro Electroplating site is located in an urban portion of Suffolk County, NY. The Astro Electroplating site is located at 170 Central Avenue in the Town of Babylon, Suffolk County, New York. The 2.9-acre site is located on the north side of Central Avenue in a commercial/industrial area. Site Features: The site contains one multi-tenant industrial building. A paved parking lot surrounds the building. Astro Electroplating is an inactive electroplating facility that occupied 9,700 square feet of space at the north end of the industrial building. Current Zoning and Land Use: The site and the surrounding parcels are currently used for a combination of commercial and light industrial processes. Past Use of the Site: Astro Electroplating specialized in plating nickel, chromium and copper to pre-molded plastic components. Contamination was due to wastewater being discharged to five subsurface leaching pools. Operable Units: The site was divided into two operable units in 2007. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1)is the site soils. OU2 consists of site related groundwater. Site Geology and Hydrogeology: The upper glacial deposits are located directly below the surface and extend to a depth of 144 feet below ground surface (bgs). The soil consists primarily of coarse grained sand and is characteristic of outwash plain deposits. The water table is located at about 37 feet bgs, and flows south-southeast.
Env Problem: Nature and Extent of Contamination: The primary contaminants of concern at the site known at this time include plating metals such as nickel, zinc, chromium and copper. These are the contaminants that exceed Standards, Criteria and Guidance values. OU1 & OU2: Groundwater & Soil - Investigations indicate contamination in saturated and unsaturated soils and a plume of groundwater contamination that extends south to the property border. Groundwater and soil contamination is due to wastewater discharged to leaching pools.
Health Problem: The Astro Electroplating facility’s past practice of subsurface wastewater disposal has contaminated groundwater and soil with heavy metals. In 1986, contaminated liquids and sludges were removed from

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

the former leaching pools on-site. The remedial investigation indicated soil contamination with heavy metals in the leaching pool area below 15 feet. Exposures are unlikely due to the depth of contamination. Since homes and businesses near the site are connected to public drinking water, exposure to site-related contaminants in groundwater is not expected.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1970
Disp Term:	1986
Lat/Long:	40:45:14:0 / 73:24:25:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2012-10-24 11:33:00
Updated By:	ldennist
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Farmingdale Library
Owner Address:	116 Merritt Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Astro Electroplating, Inc.
Owner Address:	170 Central Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Annette G. Nowak Marital Trust c/o Finch Realty
Owner Address:	55 Central Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	NEIL WEINSTEIN, PRES.
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	170 CENTRAL AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	ANNETTE G. NOWAK MARITAL TRUST C/O
Owner Address:	C/O FINCH REALTY 55 CENTRAL AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
HW Code:	152036
Waste Type:	PLATING WASTES
Waste Quantity:	400,000 GALLONS/YEAR
Waste Code:	Not reported
HW Code:	152036
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152036
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152036
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD982273971
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2008-12-08 13:37:00
Updated By:	EMZUK
Crossref ID:	982273971
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2005-02-24 15:54:00
Updated By:	INITIAL
Crossref ID:	9112811
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2007-02-20 14:50:00
Record Updated:	2007-02-20 14:50:00
Updated By:	TLDiaz
Crossref ID:	8605806
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2007-02-20 14:50:00
Record Updated:	2007-02-20 14:50:00
Updated By:	TLDiaz
Crossref ID:	0605861
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2007-02-20 14:49:00
Record Updated:	2007-02-20 14:49:00
Updated By:	TLDiaz
Crossref ID:	0504521
Cross Ref Type Code:	01

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Cross Ref Type: Spill No.
Record Added Date: 2007-02-20 14:50:00
Record Updated: 2007-02-20 14:50:00
Updated By: TLDiaz

SPILLS:

Facility ID:	8605806
Facility Type:	ER
Spill Number:	8605806
DER Facility ID:	448623
Site ID:	311502
DEC Region:	1
Closed Date:	1991-02-04
Spill Cause:	Other
Spill Class:	B4
SWIS:	5220
Spill Date:	1986-12-13
Investigator:	WJPARISH
Referred To:	Not reported
Reported to Dept:	1986-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1991-02-04
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-17
Spill Record Last Update:	2014-04-14
Spiller Name:	Not reported
Spiller Company:	ASTRO ELECTO PLATING
Spiller Address:	170 CENTRAL AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was PARISH / / : WATER BEING CHANNELED INTO DIKE. 02/04/91: WATER BEING CHANNELED INTO DIKE. CHEMICAL MGT HIRED BY SPILLER TO CLEANUP.SCDH TO FOLLOWUP ON CLEANUP OF DRYWELLS. 10/10/95: This is additional information about material spilled from the translation of the old spill file: ACID."
Remarks:	"WATER AND ACID MIXED"

Facility ID:	9112811
Facility Type:	ER
Spill Number:	9112811
DER Facility ID:	448623
Site ID:	311503
DEC Region:	1
Closed Date:	1992-03-18
Spill Cause:	Unknown
Spill Class:	C2
SWIS:	5220
Spill Date:	1992-03-17
Investigator:	KMYAGER

ASTRO ELECTROPLATING, INC. (Continued) **S108131276**

Referred To:	Not reported
Reported to Dept:	1992-03-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-03-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-03-17
Spill Record Last Update:	2015-01-22
Spiller Name:	Not reported
Spiller Company:	ASTRO ELECTRIC PLATTING
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEROSA 10/10/95: This is additional information about material spilled from the translation of the old spill file: POSS SULFURIC ACID."
Remarks:	"FUMES, VISIBLE PLUME COMING FROM STACK,EMPLOYEES AFFECTED, ONGOING PROBLEM, REFERRED TO BOB CAPP POSSIBLY SENDING EMPLOYEES HOME"

S95 **TRONIC PLATING CO., INC.** **Delisted NPL** **1009968611**
South **168 CENTRAL AVENUE** **SEMS** **NYD002059517**
1/2-1 **FARMINGDALE, NY 11735** **CORRACTS**
0.608 mi. **US ENG CONTROLS**
3211 ft. **Site 2 of 3 in cluster S** **RCRA NonGen / NLR**
ROD
Relative: **ICIS**
Lower **RI MANIFEST**

Actual:
95 ft.

Delisted NPL:

EPA ID:	NYD002059517
Site ID:	201346
EPA Region:	2
Federal:	No
Deleted Date:	2001-10-15 00:00:00
Latitude:	40.753799999999998
Longitude:	-73.407700000000006

Category Details:

NPL Status:	Deleted from the Final NPL
Category Description:	Depth To Aquifer-> 25 And <= 50 Feet
Category Value:	31

NPL Status:	Deleted from the Final NPL
Category Description:	Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value:	10

Site Details:

Site Name:	TRONIC PLATING CO., INC.
Site Status:	Deleted
Site Zip:	11735

TRONIC PLATING CO., INC. (Continued) **1009968611**

Site City: FARMINGDALE
Site State: NY
Federal Site: No
Site County: SUFFOLK
EPA Region: 02
Date Proposed: 10/15/84
Date Deleted: 10/15/2001
Date Finalized: 06/10/86

Substance Details:

NPL Status: Deleted from the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Deleted from the Final NPL
Substance ID: C151
Substance: IRON AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: C178
Substance: COPPER AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: C247
Substance: ZINC AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: D006
Substance: CADMIUM (CD)
CAS #: 7440-43-9
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: D008
Substance: LEAD (PB)
CAS #: 7439-92-1
Pathway: GROUND WATER PATHWAY
Scoring: 3

NPL Status: Deleted from the Final NPL
Substance ID: D011
Substance: SILVER
CAS #: 7440-22-4
Pathway: NO PATHWAY INDICATED

TRONIC PLATING CO., INC. (Continued) **1009968611**

Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: P030
Substance: CYANIDES (SOLUBLE SALTS)
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Deleted from the Final NPL
Substance ID: W001
Substance: HEAVY METALS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

Summary Details:

Conditions at proposal October 15, 1984): Tronic Plating Co., Inc. occupies 0.5 acre in Farmingdale, New York. The site is in southwestern Suffolk County, approximately l.5 miles east of the Nassau County line. Tronic occupies the southeast corner of a long building in an industrial park area. The site consists of the building, two inside above-ground storage tanks, four underground leaching pools, and a storm drain in the paved area to the northeast of the building. Tronic hasprovided electroplating and anodi ing services to the electronics industry since July 1968. State and county authorities have determined that ha ardous wastes, consisting primarily of heavy metals, were discharged from storage tanks and leaching pools on the site. The State issued a Pollutant Discharge Elimination System permit to Tronic on April l, l980. In June l980, the State issued a Consent Order to Tronic for discharging industrial wastes to ground water from leaching pools. Tronic agreed to obtain a permit and clean out the leaching pools. Tests conducted by the State on one of the leaching pools detected copper, silver, iron, inc, lead, and cadmium. Heavy metals also were detected in the storm drain. The site is in a generally flat area with an average slope of less than 3 percent. There is no surface water in the vicinity. The surrounding area is paved, and run-off flows to existing storm drains. The site is surrounded by manufacturing and commercial facilities. Large cemeteries are located to the south and east. Wells within 3 miles of the site provide drinking water to about l6,000 people and are the only water supply in the area. Status June 10, 1986): EPA is considering various alternatives for this site.

Site Status Details:

NPL Status: Deleted
Proposed Date: 10/15/1984
Final Date: 06/10/1986
Deleted Date: 10/15/2001

Narratives Details:

NPL Name: TRONIC PLATING CO., INC.
City: FARMINGDALE
State: NY

SEMS:

Site ID: 201346

TRONIC PLATING CO., INC. (Continued) **1009968611**

EPA ID: NYD002059517
Cong District: 2
FIPS Code: 36103
Latitude: 40.753799999999998
Longitude: -73.407700000000006
FF: N
NPL: Deleted from the Final NPL
Non NPL Status: Not reported

SEMS Detail:

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 0
Action Code: NP
Action Name: PROPOSED
SEQ: 1
Start Date: 1984-10-15 00:00:00
Finish Date: 10/15/1984
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 0
Action Code: CR
Action Name: CI
SEQ: 1
Start Date: 1987-07-10 00:00:00
Finish Date: 10/15/2001
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 1
Action Code: JF
Action Name: ECO RISK
SEQ: 1
Start Date: 1992-12-31 00:00:00
Finish Date: 12/31/1992
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 201346
EPA ID: NYD002059517

TRONIC PLATING CO., INC. (Continued) **1009968611**

Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	1
Action Code:	RO
Action Name:	ROD
SEQ:	1
Start Date:	1993-09-27 00:00:00
Finish Date:	9/27/1993
Qual:	R
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	2
Start Date:	1992-12-01 00:00:00
Finish Date:	12/21/1992
Qual:	S
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	NF
Action Name:	NPL FINL
SEQ:	1
Start Date:	1986-06-10 00:00:00
Finish Date:	6/10/1986
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	1
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	1987-07-10 00:00:00
Finish Date:	6/7/1988
Qual:	Not reported
Current Action Lead:	EPA Perf

TRONIC PLATING CO., INC. (Continued) **1009968611**

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	CM
Action Name:	PCOR
SEQ:	1
Start Date:	1993-09-27 00:00:00
Finish Date:	9/27/1993
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	ND
Action Name:	DELETION
SEQ:	1
Start Date:	2001-10-15 00:00:00
Finish Date:	10/15/2001
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	TU
Action Name:	NOID
SEQ:	1
Start Date:	2001-08-14 00:00:00
Finish Date:	8/14/2001
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	1990-03-21 00:00:00
Finish Date:	8/28/1990

TRONIC PLATING CO., INC. (Continued) **1009968611**

Qual: S
Current Action Lead: EPA Perf

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 1
Action Code: BD
Action Name: PRP RI/FS
SEQ: 1
Start Date: 1988-06-07 00:00:00
Finish Date: 9/27/1993
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 1
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1993-08-25 00:00:00
Finish Date: Not reported
Qual: E
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 0
Action Code: BB
Action Name: PRP RV
SEQ: 1
Start Date: 1993-06-17 00:00:00
Finish Date: 9/30/1993
Qual: C
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 201346
EPA ID: NYD002059517
Site Name: TRONIC PLATING CO., INC.
NPL: D
FF: N
OU: 1
Action Code: ED
Action Name: R/H ASMT

TRONIC PLATING CO., INC. (Continued) **1009968611**

SEQ:	1
Start Date:	1991-03-26 00:00:00
Finish Date:	12/31/1992
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	MA
Action Name:	ST COOP
SEQ:	1
Start Date:	1987-06-26 00:00:00
Finish Date:	10/15/2001
Qual:	Not reported
Current Action Lead:	St Perf
Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1984-09-01 00:00:00
Finish Date:	9/1/1984
Qual:	Not reported
Current Action Lead:	St Perf
Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N
OU:	0
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1985-05-01 00:00:00
Finish Date:	5/31/1985
Qual:	H
Current Action Lead:	St Perf
Region:	2
Site ID:	201346
EPA ID:	NYD002059517
Site Name:	TRONIC PLATING CO., INC.
NPL:	D
FF:	N

TRONIC PLATING CO., INC. (Continued) **1009968611**

OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1984-09-01 00:00:00
Finish Date:	9/1/1984
Qual:	L
Current Action Lead:	St Perf

CORRACTS:

EPA ID:	NYD002059517
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19960905
Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	332813 Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD002059517
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19880907
Action:	CA050 - RFA Completed
NAICS Code(s):	332813 Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD002059517
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19930630
Action:	CA610
NAICS Code(s):	332813 Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD002059517
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19930930
Action:	CA500 - CMI Workplan Approved
NAICS Code(s):	332813 Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD002059517
EPA Region:	02
Area Name:	SITEWIDE

TRONIC PLATING CO., INC. (Continued) **1009968611**

Actual Date: 19930930
Action: CA550 - Certification Of Remedy Completion Or Construction Completion
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA650 - Stabilization Construction Completed
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA200 - RFI Approved
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002059517
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19930930
Action: CA350 - CMS Approved
NAICS Code(s): 332813
Electroplating, Plating, Polishing, Anodizing, and Coloring
Original schedule date: Not reported
Schedule end date: Not reported

US ENG CONTROLS:
EPA ID: NYD002059517
Site ID: 0201346
Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
FARMINGDALE, NY 11735
EPA Region: 02
County: SUFFOLK
Event Code: Not reported
Actual Date: 06/30/1993

TRONIC PLATING CO., INC. (Continued) **1009968611**

Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/27/1993
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: No Further Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: COMMERCE HOLDING CO INC
Facility address: CENTRAL AVE UNIT 162-168
FARMINGDALE, NY 11735
EPA ID: NYD002059517
Mailing address: PO BOX 672
HICKSVILLE, NY 11802
Contact: Not reported
Contact address: PO BOX 672
HICKSVILLE, NY 11802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: TRONIC PLATING CO, INC

TRONIC PLATING CO., INC. (Continued) **1009968611**

Owner/operator address: 168 CENTRAL AVE
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: 516-293-7883
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COMMERCE HOLDING CO INC
Owner/operator address: PO BOX 672
HICKSVILLE, NY 11802
Owner/operator country: US
Owner/operator telephone: 516-681-6000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

Date form received by agency: 02/28/1994
Site name: TRONIC PLATING CO./COMMERCE HOLDING CO.
Classification: Large Quantity Generator

Date form received by agency: 02/25/1994
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

. Waste code: NONE

TRONIC PLATING CO., INC. (Continued) **1009968611**

. Waste name: None

Date form received by agency: 07/23/1993
Site name: COMMERCE HOLDING CO INC
Classification: Large Quantity Generator

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P099
. Waste name: ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE

. Waste code: P104
. Waste name: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Date form received by agency: 11/19/1980
Site name: COMMERCE HOLDING CO INC
Classification: Not a generator, verified

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

TRONIC PLATING CO., INC. (Continued) **1009968611**

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Corrective Action Summary:
Event date: 09/07/1988
Event: RFA COMPLETED

Event date: 06/30/1993
Event: INTERIM MEASURES PLAN APPROVED

Event date: 09/30/1993
Event: STABILIZATION CONSTRUCTION COMPLETED

Event date: 09/30/1993
Event: CMI WORKPLAN APPROVED

Event date: 09/30/1993
Event: REMEDY CONSTRUCTION

Event date: 09/30/1993
Event: CMS COMPLETE

Event date: 09/30/1993
Event: INVESTIGATION COMPLETE

Event date: 09/30/1993
Event: REMEDY DECISION

Event date: 09/05/1996
Event: CA PRIORITIZATION-LOW CA PRIORITY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/20/1985
Date achieved compliance: 08/03/1987
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/29/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Evaluation lead agency: EPA

Evaluation date: 03/20/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/03/1987
Evaluation lead agency: State

ROD:

Full-text of USEPA Record of Decision(s) is available from EDR.

ICIS:

Enforcement Action ID: 02-1999-0006
FRS ID: 110009302352
Action Name: COMMERCE HOLDING COMPANY INC
Facility Name: TRONIC PLATING CO., INC.
Facility Address: 168 CENTRAL AVENUE
FARMINGDALE, NY 11735
Enforcement Action Type: Civil Judicial Action
Facility County: SUFFOLK
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial
EA Type Code: CIV
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.7538
Longitude in Decimal Degrees: -73.4077
Permit Type Desc: Not reported
Program System Acronym: 8112
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-1993-0077
FRS ID: 110009302352
Action Name: COMMERCE HOLDING COMPANY, INC.
Facility Name: TRONIC PLATING CO., INC.
Facility Address: 168 CENTRAL AVENUE
FARMINGDALE, NY 11735
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: SUFFOLK
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.7538
Longitude in Decimal Degrees: -73.4077
Permit Type Desc: Not reported
Program System Acronym: 8112
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-1988-0849
FRS ID: 110009302352
Action Name: COMMERCE HOLDING CO (TRONIC PLATING)
Facility Name: TRONIC PLATING CO., INC.
Facility Address: 168 CENTRAL AVENUE

TRONIC PLATING CO., INC. (Continued) **1009968611**

FARMINGDALE, NY 11735
Enforcement Action Type: CERCLA 122A/104A Agrmt For RI/FS
Facility County: SUFFOLK
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 122/104
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.7538
Longitude in Decimal Degrees: -73.4077
Permit Type Desc: Not reported
Program System Acronym: 8112
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: TRONIC PLATING CO., INC.
Address: 168 CENTRAL AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

RI MANIFEST:
EPA Id: NYD002059517
GEN Cert Date: 8/25/1993
Manifest Document Number: RIC0027315
Waste Description: CHROMIUM
TSDF Id: RID040098352
TSDF Name: NORTHLAND ENVIRONMENTAL INC
Qty: 1080
WT/Vol Units: G
TSDF Date: Not reported
Transporter 2 Id: Not reported
Item Number: 1
Transporter 2 Name: Not reported
Transporter Name 2: BECHEM TRANSPORT INC
Transporter EPAID: CTD982191942

TRONIC PLATING CO., INC. (Continued) **1009968611**

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0027315
Quarter:	Not reported
Waste Description:	CHROMIUM
Transporter Contact Name:	Not reported
Quantity:	1080
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942

TRONIC PLATING CO., INC. (Continued) **1009968611**

Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/25/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D006
Waste Code2:	D011
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0024547
Quarter:	Not reported
Waste Description:	SILVER
Transporter Contact Name:	Not reported
Quantity:	9000
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/19/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D003
Waste Code2:	Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0024547
Quarter:	Not reported
Waste Description:	CYANIDE
Transporter Contact Name:	Not reported
Quantity:	600
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/19/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0027315
Quarter:	Not reported
Waste Description:	CHROMIUM
Transporter Contact Name:	Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

Quantity:	1080
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/25/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D006
Waste Code2:	D011
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0024547
Quarter:	Not reported
Waste Description:	SILVER
Transporter Contact Name:	Not reported
Quantity:	9000
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/19/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported

TRONIC PLATING CO., INC. (Continued) **1009968611**

TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	NORTHLAND ENVIRONMENTAL INC
TSDF Id:	RID040098352
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD002059517
Manifest Docket Number:	RIC0024547
Quarter:	Not reported
Waste Description:	CYANIDE
Transporter Contact Name:	Not reported
Quantity:	600
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	BECHEM TRANSPORT INC
Billing Name:	Not reported
Transporter EPA ID:	CTD982191942
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/19/1993
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

S96 **UNKNOWN** **NY DEL SHWS S108667330**
South **168 CENTRAL AVE** **NY Spills N/A**
1/2-1 **FARMINGDALE, NY 11735**
0.608 mi.
3211 ft. **Site 3 of 3 in cluster S**

Relative: DEL SHWS:
Lower

Year:	Not reported
Site Code Id:	Not reported
Site Classification:	Not reported
Region:	1
Epa Id Number:	Not reported

Actual:
95 ft.

UNKNOWN (Continued) **S108667330**

Site Type - Dump:	No
Site Type - Structure:	No
Site Type - Lagoon:	No
Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	Not reported
Hazardous Waste Code:	152028
Hazard Waste Disposed:	Not reported
Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No
Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported

UNKNOWN (Continued) **S108667330**

Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Site-related contamination was removed from on-site leaching pits and storm drains to reduce the potential for contamination of the groundwater and exposure to contaminated soil during routine maintenance of the storm drains. The remediated areaswere backfilled with 10 to 30 feet of clean soil and subsequently paved over. Exposure to the site-related contaminants, copper,chromium, and cyanide, in groundwater is not expected since homes and businesses in the vicinity of this site are connected topublic water.
Description:	The Tronic Plating Co. operated a metal electroplating and anodizing facility at 168 Central Avenue from July 1968 to March 1984. The facility was served by four industrial leaching pools, one sanitary septic leaching pool, and one drywell. It is possible that some of the on-site storm drains may have also received discharges from the site. Contamination levels documented in the RI include sediments from storm drains and a septic system at a maximum of: cadmium at 1130 ppm; cyanide at 92 ppm; chromium at 1580 ppm; and, lead at 2,290 ppm. Borings conducted during the RI indicated that high levels of contamination were not widespread, and the groundwater investigation showed only a limited impact from the site. A soils removal action was completed in August 1993 and all known disposal areas have been cleaned to USEPA and NYSDEC approved levels. A Record Of Decision (ROD) was issued in September 1993, calling for no further action at this site. Site related groundwater contamination was limited to one shallow monitoring well. Post-remedy Groundwater monitoring was conducted by the Responsible Party following the completion of remedial activities, and all results were forwarded to the NYSDEC. The results confirmed that the remedial action was effective, and a delisting package was prepared in 1996 and finalized in 1997.
Record Added Date:	11/18/1999

UNKNOWN (Continued) **S108667330**

Record Updated Date:	01/31/2008
Env Assessment:	Not reported
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

SPILLS:

Facility ID:	1212903
Facility Type:	ER
Spill Number:	1212903
DER Facility ID:	431380
Site ID:	476061
DEC Region:	1
Closed Date:	2013-08-29
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	5220
Spill Date:	2012-12-01
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2012-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-01
Spill Record Last Update:	2013-09-23
Spiller Name:	Not reported
Spiller Company:	LIPA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK NAGLIERI
DEC Memo:	"POLE 14 PER NATIONAL GRID INCIDENT DESCRIPTION: MVA, WYE BANK CAME DOWN ONTO THE ROADWAY AFTER A VEHICLE STRUCK A UTILITY, WRS CONTRACTOR"
Remarks:	"on street - cleanup crew enr @1855 - Frank called back to advise 20 gallon total"

All Materials:

Site ID:	476061
Operable Unit ID:	1225900
Operable Unit:	01
Material ID:	2223231
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported

UNKNOWN (Continued) **S108667330**

Oxygenate: Not reported

97
North
1/2-1
0.616 mi.
3250 ft.

MCGOVERN SOD FARM **NY SHWS** **S105973013**
PINELAWN ROAD & OLD SOD FARM ROAD **N/A**
MELVILLE, NY 11747

Relative: Higher

Actual: 117 ft.

SHWS:

Program:	HW
Site Code:	57636
Classification:	C
Region:	1
Acres:	7.9
HW Code:	152120
Record Add:	11/18/1999
Record Upd:	01/31/2008
Updated By:	JBSWARTO
Site Description:	A former sod farm which used a buried 550 gallon tank to store waste motor oil from equipment used in their farming operation. Also pesticides were stored on site. In August 1985, Hewlett-Packard had the tank removed. During excavation, visible discoloration of surface and subsurface soil was observed. Soil samples were collected and analyzed indicating hydrocarbons, pesticides and metals. Remediation of site has been completed. Hewlett-Packard has performed 4 soil excavations, taking a total of 590 cubic yards, and 5 soil sampling events. The final soil sampling results indicate that the site has been remediated. Site has been delisted 12/89.
Env Problem:	This site has been remediated.
Health Problem:	All contamination at the site has been remediated or removed. There are no known exposures, and therefore no known health concerns
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Aug. 1985
Lat/Long:	00:00:00:0 / 00:00:00:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	PALO-ALTO, CA 94303
Owner Country:	United States of America
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	Not reported
Owner Addr2:	Not reported

MCGOVERN SOD FARM (Continued) **S105973013**

Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	MCGOVERN SOD FARM
Owner Address:	PINELAWN RD. & OLD SOD FARM RD.
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	McGovern Sod Farm
Owner Address:	Pinelawn Road & Old Sod Farm Road
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Hewlett-Packard
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	PALO-ALTO, CA 94303
Owner Country:	United States of America
HW Code:	152120
Waste Type:	HYDROCARBONS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152120
Waste Type:	METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152120
Waste Type:	PESTICIDES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

98
NNW
1/2-1
0.760 mi.
4011 ft.

Relative:
Higher

Actual:
119 ft.

I.W. INDUSTRIES, INC.
35 MELVILLE PARK ROAD
MELVILLE, NY 11747

NY SHWS **S105054992**
NY LTANKS **N/A**
NY ENG CONTROLS
NY INST CONTROL
NY Spills
NY MANIFEST

SHWS:

Program:	HW
Site Code:	55868
Classification:	4
Region:	1
Acres:	6

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Record Add: 11/18/1999
Record Upd: 03/13/2018
Updated By: JBSWARTO
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.
Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is

I.W. INDUSTRIES, INC. (Continued) **S105054992**

	served by a public water supply that is not affected by this contamination.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1972
Disp Term:	1986
Lat/Long:	40:46:35:0 / 73:25:02:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2011-10-19 09:29:00
Updated By:	BFJANKAU
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	BNEI IZHAK HOLDING CORPORATION
Owner Address:	35 MELVILLE PARK ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	MELVILLE, NY 11747
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	John O'Connor
Owner Company:	Transaero Inc
Owner Address:	35 Melville Park Road
Owner Addr2:	Suite 100
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Mr. Perry Youngwell
Owner Company:	Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address:	35 Melville Park Road, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	HUNTINGTON PUBLIC LIBRARY
Owner Address:	338 MAIN STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	HUNTINGTON, NY 11743
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	152102
Waste Type:	N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity:	UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code:	Not reported
HW Code:	152102
Waste Type:	N-DECANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NONANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TETRAMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ETHYL TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code:	152102
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIBENZOFURAN
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MANGANESE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W1-0725-04-09

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

LTANKS:
Facility ID: 0102354
Site ID: 260833
Closed Date: 2001-06-01
Spill Number: 0102354
Spill Date: 2001-06-01
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 5226
Investigator: T/T/F
Referred To: Not reported
Reported to Dept: 2001-06-01
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-01
Spill Record Last Update: 2012-08-08
Spiller Name: SAME
Spiller Company: IW INDUSTRIES
Spiller Address: 35 MELVILLE PARK ROAD
Spiller County: 001
Spiller Contact: MARK WARSHAWSKI
Spiller Phone: (631) 293-9494
Spiller Extention: 252
DEC Region: 1
DER Facility ID: 318823
DEC Memo: "SAME AS 01-25079"
Remarks: "tank failed the test. ***SAME AS 0125079***"

All TTF:
Facility ID: 0102354
Spill Number: 0102354

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Spill Tank Test:	1526346
Site ID:	260833
Tank Number:	1
Tank Size:	8000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	1.11
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	260833
Operable Unit ID:	839131
Operable Unit:	01
Material ID:	534469
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0125079
Site ID:	260834
Closed Date:	2003-11-03
Spill Number:	0125079
Spill Date:	2001-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	5226
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	2001-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-01
Spill Record Last Update:	2009-12-09
Spiller Name:	Not reported
Spiller Company:	IW INDUSTRIES
Spiller Address:	35 MELVILLE PARK ROAD

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Spiller County:	001
Spiller Contact:	ED WIGUTOFF
Spiller Phone:	(631) 293-9494
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	318823
DEC Memo:	"THEY HAVE SCHEDULED UNCOVERING PIPING, TANK ALONE TEST AND RETEST FOR 6/7 & 6/8, SAME AS 01-2354"
Remarks:	"THEY WILL ISOLATE TANK AND LINES AND RETEST NEXT WEEK. ***SAME AS 0102354*** "

All Materials:

Site ID:	260834
Operable Unit ID:	849347
Operable Unit:	01
Material ID:	526400
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

ENG CONTROLS:

Site Code:	55868
HW Code:	152102
Control Code:	15
Control Type:	ENG
Date Record Added:	07/14/2004
Date Rec Updated:	11/29/2016
Updated By:	BFJANKAU
Site Description:	Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table,

I.W. INDUSTRIES, INC. (Continued) **S105054992**

and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.
Health Problem:	It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1972
Disp Term:	1986
Lat/Long:	40:46:35:0 / 73:25:02:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2011-10-19 09:29:00
Updated By:	BFJANKAU
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	BNEI IZHAK HOLDING CORPORATION
Owner Address:	35 MELVILLE PARK ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	MELVILLE, NY 11747
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	John O'Connor
Owner Company:	Transaero Inc
Owner Address:	35 Melville Park Road

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Addr2:	Suite 100
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Mr. Perry Youngwell
Owner Company:	Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address:	35 Melville Park Road, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	HUNTINGTON PUBLIC LIBRARY
Owner Address:	338 MAIN STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	HUNTINGTON, NY 11743
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	152102
Waste Type:	N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	N-DECANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NONANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TETRAMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	COPPER

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	ETHYL TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	DIBENZOFURAN
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152102
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

INST CONTROL:
Site Code: 55868
Control Name: Ground Water Use Restriction
HW Code: 152102
Control Code: 08
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Site Code: 55868

Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: Monitoring Plan
HW Code: 152102
Control Code: 31
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies

I.W. INDUSTRIES, INC. (Continued) **S105054992**

the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: Site Management Plan
HW Code: 152102
Control Code: 32
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: O&M Plan
HW Code: 152102
Control Code: 33
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in

I.W. INDUSTRIES, INC. (Continued) **S105054992**

groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: Environmental Easement
HW Code: 152102
Control Code: J
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued

I.W. INDUSTRIES, INC. (Continued) **S105054992**

in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O’Connor

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: IC/EC Plan
HW Code: 152102
Control Code: 34
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.
Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: Landuse Restriction
HW Code: 152102
Control Code: 25
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface

I.W. INDUSTRIES, INC. (Continued) **S105054992**

to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00
Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

Site Code: 55868
Control Name: Soil Management Plan
HW Code: 152102
Control Code: 14
Control Type: INST
Dt record added: 07/14/2004
Dt rec updated: 11/29/2016
Updated By: BFJANKAU
Site Code: 55868
Site Description: Location: The I.W. Industries, Inc. site is located at 35 Melville Park Road in the Hamlet of Melville. The 6 acre site is situated in a suburban area. Site Features: The main site feature is a one-story masonry structure that covers 97,000 square feet. Paved parking lots are located to the east and west of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for industrial use and currently used for offices and warehousing. The surrounding parcels are currently used for a combination of commercial and industrial uses. The nearest

I.W. INDUSTRIES, INC. (Continued) **S105054992**

residential area is approximately 0.5 miles to the west. Historic Use(s): The site was initially developed in 1966 and occupied by I.W. Industries, which manufactured threaded metal parts until 2005. Industrial wastewater (i.e. cutting oils and degreasing solvents) from site operations was discharged to on-site leaching pools until 1980's under a State Pollutant Discharge Elimination System (SPDES) permit. In 1986 site operations contained wastewater for off-site disposal. Suffolk County Department of Health Services conducted inspections at the site, which resulted in the cleaning of leaching pools in 1983 and 1984. I.W. Industries conducted initial site investigations between 1981 and 1994 and a Focused Remedial Investigation between 1994 and 1997. A Record of Decision was issued in March 2000, which selected removal of source soils from leaching pools, removal of free phase product from the top of the water table, and groundwater monitoring. In July 2000, material was removed from the selected leaching pools. As part of facility closure equipment was removed from the building, samples were collected, and contaminated material was removed from an interior trench and select leaching pools. Three leaching pools, identified as LP-1, LP-2, and LP-3, were abandoned in place and covered in January 2010 due to the depth of contamination. In 2011, an environmental easement was placed on the property. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soils were volatile organic compounds (xylene and toluene), semi-volatile organic compounds (benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3)perylene, fluoranthene, phenanthrene, phenol, dibenzofuran and pyrene) and metals (arsenic, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel and zinc) and in groundwater were metals (chromium, iron, lead and manganese). The abandonment and capping of leaching pools LP-1, LP-2, and LP-3 stopped the infiltration of free phase product into the groundwater. Monitoring wells at the site do not contain measurable amounts of free phase product.

Health Problem: It is unlikely that people will come in contact with the contaminated soils unless they remove the concrete caps covering the leaching pools and dig through the backfill soil in the leaching pools. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1972
Disp Term: 1986
Lat/Long: 40:46:35:0 / 73:25:02:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-10-19 09:29:00

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Updated By: BFJANKAU
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BNEI IZHAK HOLDING CORPORATION
Owner Address: 35 MELVILLE PARK ROAD
Owner Addr2: Not reported
Owner City,St,Zip: MELVILLE, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: John O'Connor
Owner Company: Transaero Inc
Owner Address: 35 Melville Park Road
Owner Addr2: Suite 100
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: 05
Owner Name: Mr. Perry Youngwell
Owner Company: Kailyn Realty I, LLC care of Transaero, Inc.
Owner Address: 35 Melville Park Road, Suite 100
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: HUNTINGTON PUBLIC LIBRARY
Owner Address: 338 MAIN STREET
Owner Addr2: Not reported
Owner City,St,Zip: HUNTINGTON, NY 11743
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
HW Code: 152102
Waste Type: N-UNDECANE CIS-DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: N-DECANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NONANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

HW Code: 152102
Waste Type: TETRAMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ETHYL TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: DIBENZOFURAN
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MANGANESE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152102
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0725-04-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: W1-0725-00-06
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-06-23 09:14:00
Record Updated: 2011-06-23 09:14:00
Updated By: BFJANKAU
Crossref ID: Liber D00012667 page 051
Cross Ref Type Code: 25

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:23:00
Record Updated: 2011-10-27 16:30:00
Updated By: BFJANKAU

SPILLS:

Facility ID:	0605685
Facility Type:	ER
Spill Number:	0605685
DER Facility ID:	318823
Site ID:	368898
DEC Region:	1
Closed Date:	2007-10-24
Spill Cause:	Other
Spill Class:	C3
SWIS:	5226
Spill Date:	2006-08-16
Investigator:	WXPRZYLO
Referred To:	Not reported
Reported to Dept:	2006-08-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-16
Spill Record Last Update:	2012-08-08
Spiller Name:	TRANS ARROW
Spiller Company:	TRANS ARROW
Spiller Address:	35 MELVILLE PARK ROAD
Spiller Company:	001
Contact Name:	TRANS ARROW
DEC Memo:	"8/16/06 12:29 TANK REMOVAL CONDUCTED BY CONSULTING CO, FUEL OIL CONTAMINATED SOIL WAS UNDER THE SPILL BUCKET ONLY, 5 YDS WAS REMOVED. HD ON SITE OBSERVED REMOVAL, ENDPOINT SAMPLES TAKEN, ND WITH THE PID EQ, WILL SEND RESULTS WITH MANIFESTS RECPTS 11/2/06 FILE REASSIGNED SCHD DID OVERSEE THE REMOVAL, APPROX 10 CU YARDS OF CONTAMINATED SOIL HAS BEEN REMOVED, NO FURTHER ACTION REQUIRED"
Remarks:	"8000 GALLON TANK, SMALL RELEASE NEAR SUPPLY AND RETURN, NOT CONTAINED IN SPILL BUCKET : TANK IS IN GOOD SHAPE; health dept on scene- 5 cubic yards of soil removed:"

All Materials:

Site ID:	368898
Operable Unit ID:	1126753
Operable Unit:	01
Material ID:	2116309
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

I.W. INDUSTRIES, INC. (Continued) **S105054992**

Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYD001486968
Facility Status: Not reported
Location Address 1: 35 MELVILLE PARK ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MELVILLE
Location State: NY
Location Zip: 11747
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001486968
Mailing Name: TRANSAREO - I W INDUSTRIES
Mailing Contact: I W INDUSTRIES
Mailing Address 1: 35 MELVILLE PARK RD
Mailing Address 2: Not reported
Mailing City: MELVILLE
Mailing State: NY
Mailing Zip: 11747
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162939495

99
NNW
1/2-1
0.792 mi.
4181 ft.

25 MELVILLE PARK ROAD
25 MELVILLE PARK ROAD
MELVILLE, NY 11747

NY SHWS **1009234856**
NY ENG CONTROLS **N/A**
NY INST CONTROL
NY VCP
NY MANIFEST

Relative: Higher

Actual: 117 ft.

SHWS:
Program: HW
Site Code: 57693
Classification: 4
Region: 1
Acres: 0.19
HW Code: 152169
Record Add: 11/18/1999
Record Upd: 05/16/2017
Updated By: JBSWARTO
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist

25 MELVILLE PARK ROAD (Continued) **1009234856**

drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature of Contamination: Based upon investigations conducted to date, the off-site groundwater contamination (OU02) primarily includes tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. This site is in the site management phase and no longer presents a significant threat to the environment. Site remediation continues on-site (OU01) and groundwater monitoring continues off-site (OU02).

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, continued monitoring of this building will determine if additional actions are needed to address future potential exposures.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2012-10-24 11:36:00
Updated By: ldennist

25 MELVILLE PARK ROAD (Continued) **1009234856**

Own Op:	Owner
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Half Hollow Hills Community Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	New York Twist Drill
Owner Address:	25 Melville Park Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Karakoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue, 2nd Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	152169
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169
Waste Type:	Dichloroethene (trans-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169
Waste Type:	Dichloroethene (1,1-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152169

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0998-04-04
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-02-03 15:39:00
Record Updated: 2016-02-03 15:39:00
Updated By: BFJANKAU
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE

ENG CONTROLS:
Site Code: 56832
HW Code: V00128
Control Code: 15
Control Type: ENG
Date Record Added: 10/27/2011
Date Rec Updated: 11/28/2016
Updated By: LSZINOMA
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid

25 MELVILLE PARK ROAD (Continued) **1009234856**

1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False

Structure: True

25 MELVILLE PARK ROAD (Continued) **1009234856**

Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-09-29 12:07:00
Record Updated:	2008-09-29 12:07:00
Updated By:	MOBARRIE
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-10-27 16:17:00
Record Updated:	2011-10-27 16:31:00
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R

25 MELVILLE PARK ROAD (Continued) **1009234856**

Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Site Code:	56832
HW Code:	V00128
Control Code:	13
Control Type:	ENG
Date Record Added:	10/27/2011
Date Rec Updated:	11/28/2016
Updated By:	LSZINOMA
Site Description:	Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem:	Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting

25 MELVILLE PARK ROAD (Continued) **1009234856**

	mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.
Health Problem:	People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.

25 MELVILLE PARK ROAD (Continued) **1009234856**

Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-09-29 12:07:00
Record Updated:	2008-09-29 12:07:00
Updated By:	MOBARRIE
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-10-27 16:17:00
Record Updated:	2011-10-27 16:31:00
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

Site Code:	56832
HW Code:	V00128
Control Code:	12
Control Type:	ENG
Date Record Added:	10/27/2011
Date Rec Updated:	11/28/2016
Updated By:	LSZINOMA
Site Description:	Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit

25 MELVILLE PARK ROAD (Continued) **1009234856**

represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984

25 MELVILLE PARK ROAD (Continued) **1009234856**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-09-29 12:07:00
Record Updated:	2008-09-29 12:07:00
Updated By:	MOBARRIE
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-10-27 16:17:00
Record Updated:	2011-10-27 16:31:00
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

25 MELVILLE PARK ROAD (Continued) **1009234856**

INST CONTROL:
Site Code: 56832
Control Name: Soil Management Plan
HW Code: V00128
Control Code: 14
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern

25 MELVILLE PARK ROAD (Continued) **1009234856**

side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-10-27 16:15:00
Record Upd: 2012-10-24 11:42:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Vim Goyal
Owner Company: Omega Melville LLC
Owner Address: 18 Winthrop Drive
Owner Addr2: Not reported
Owner City,St,Zip: Woodbury, NY 11797
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC & Karahoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America

25 MELVILLE PARK ROAD (Continued) **1009234856**

HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: Ground Water Use Restriction
HW Code: V00128
Control Code: 08
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for

25 MELVILLE PARK ROAD (Continued) **1009234856**

technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported

25 MELVILLE PARK ROAD (Continued) **1009234856**

Dell: Not reported
Record Add: 2011-10-27 16:15:00
Record Upd: 2012-10-24 11:42:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Vim Goyal
Owner Company: Omega Melville LLC
Owner Address: 18 Winthrop Drive
Owner Addr2: Not reported
Owner City,St,Zip: Woodbury, NY 11797
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC & Karahoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

25 MELVILLE PARK ROAD (Continued) **1009234856**

Site Code: 56832
Control Name: Site Management Plan
HW Code: V00128
Control Code: 32
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated

25 MELVILLE PARK ROAD (Continued) **1009234856**

	concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.
Health Problem:	People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: Monitoring Plan
HW Code: V00128
Control Code: 31
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to

25 MELVILLE PARK ROAD (Continued) **1009234856**

investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported

25 MELVILLE PARK ROAD (Continued) **1009234856**

Record Add: 2011-10-27 16:15:00
Record Upd: 2012-10-24 11:42:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Vim Goyal
Owner Company: Omega Melville LLC
Owner Address: 18 Winthrop Drive
Owner Addr2: Not reported
Owner City,St,Zip: Woodbury, NY 11797
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC & Karahoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832

25 MELVILLE PARK ROAD (Continued) **1009234856**

Control Name: Building Use Restriction
HW Code: V00128
Control Code: 26
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site.

25 MELVILLE PARK ROAD (Continued) **1009234856**

	The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.
Health Problem:	People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: IC/EC Plan
HW Code: V00128
Control Code: 34
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or

25 MELVILLE PARK ROAD (Continued) **1009234856**

exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-10-27 16:15:00

25 MELVILLE PARK ROAD (Continued) **1009234856**

Record Upd: 2012-10-24 11:42:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Vim Goyal
Owner Company: Omega Melville LLC
Owner Address: 18 Winthrop Drive
Owner Addr2: Not reported
Owner City,St,Zip: Woodbury, NY 11797
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC & Karahoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: Environmental Easement

25 MELVILLE PARK ROAD (Continued) **1009234856**

HW Code: V00128
Control Code: J
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to

25 MELVILLE PARK ROAD (Continued) **1009234856**

	be applied at the site to reduce groundwater contamination on-site.
Health Problem:	People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: O&M Plan
HW Code: V00128
Control Code: 33
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit

25 MELVILLE PARK ROAD (Continued) **1009234856**

#1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-10-27 16:15:00
Record Upd: 2012-10-24 11:42:00

25 MELVILLE PARK ROAD (Continued) **1009234856**

Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Half Hollow Hills Public Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Vim Goyal
Owner Company: Omega Melville LLC
Owner Address: 18 Winthrop Drive
Owner Addr2: Not reported
Owner City,St,Zip: Woodbury, NY 11797
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC & Karahoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: V00128
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 56832
Control Name: Landuse Restriction
HW Code: V00128

25 MELVILLE PARK ROAD (Continued) **1009234856**

Control Code: 25
Control Type: INST
Dt record added: 10/27/2011
Dt rec updated: 11/28/2016
Updated By: LSZINOMA
Site Code: 56832
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.
Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

25 MELVILLE PARK ROAD (Continued) **1009234856**

Health Problem:	People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1966
Disp Term:	1984
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-10-27 16:15:00
Record Upd:	2012-10-24 11:42:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

25 MELVILLE PARK ROAD (Continued) **1009234856**

Crossref ID: 152169
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE
Crossref ID: Liber D00012643 page 746
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-10-27 16:17:00
Record Updated: 2011-10-27 16:31:00
Updated By: BFJANKAU
Crossref ID: W1-0778-96-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: w1-0778-96-11(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Site Code: 57693
Control Name: Decision Document
HW Code: 152169
Control Code: D
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 12/01/2017
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this site

25 MELVILLE PARK ROAD (Continued) **1009234856**

which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature of Contamination: Based upon investigations conducted to date, the off-site groundwater contamination (OU02) primarily includes tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. This site is in the site management phase and no longer presents a significant threat to the environment. Site remediation continues on-site (OU01) and groundwater monitoring continues off-site (OU02).

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, continued monitoring of this building will determine if additional actions are needed to address future potential exposures.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2012-10-24 11:36:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road

25 MELVILLE PARK ROAD (Continued) **1009234856**

Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Karakoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0998-04-04
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-02-03 15:39:00
Record Updated: 2016-02-03 15:39:00
Updated By: BFJANKAU
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE

Site Code: 57693
Control Name: Site Management Plan
HW Code: 152169
Control Code: 32
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 12/01/2017
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address

25 MELVILLE PARK ROAD (Continued) **1009234856**

contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature of Contamination: Based upon investigations conducted to date, the off-site groundwater contamination (OU02) primarily includes tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. This site is in the site management phase and no longer presents a significant threat to the environment. Site remediation continues on-site (OU01) and groundwater monitoring continues off-site (OU02).

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, continued monitoring of this building will determine if additional actions are needed to address future potential exposures.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2012-10-24 11:36:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747

25 MELVILLE PARK ROAD (Continued) **1009234856**

Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Karakoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

25 MELVILLE PARK ROAD (Continued) **1009234856**

HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0998-04-04
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-02-03 15:39:00
Record Updated: 2016-02-03 15:39:00
Updated By: BFJANKAU
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE

Site Code: 57693
Control Name: Monitoring Plan
HW Code: 152169
Control Code: 31
Control Type: INST
Dt record added: 04/23/2007
Dt rec updated: 12/01/2017
Updated By: BFJANKAU
Site Code: 57693
Site Description: Location: The New York Twist Drill Loading Dock Area is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main facility feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Past Use of the Site: The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permitted discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units (OU): The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU 01 covers on-site activities for this site which are undertaken under the Voluntary Cleanup Program (Site number V00128). Remedial actions are being performed on-site to address contamination and prevent the migration of contamination off-site in accordance with the Record of Decision, dated March 2004. Site

25 MELVILLE PARK ROAD (Continued) **1009234856**

remedial actions include reductive dechlorination, free-phase product removal and a vapor control system. OU 02 covers off-site activities, which are being conducted under the State Superfund Program. Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 100 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature of Contamination: Based upon investigations conducted to date, the off-site groundwater contamination (OU02) primarily includes tetrachlorethene (PCE), trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), trans-1,2-dichloroethene, 1,1 dichloroethene, 1,1,1-trichloroethane and 1,1-dichloroethane. This site is in the site management phase and no longer presents a significant threat to the environment. Site remediation continues on-site (OU01) and groundwater monitoring continues off-site (OU02).

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion does not appear to be currently occurring off-site; however, continued monitoring of this building will determine if additional actions are needed to address future potential exposures.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1985
Lat/Long: 40:46:35:0 / 73:25:05:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2012-10-24 11:36:00
Updated By: ldennist
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Melville Opportunity LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Half Hollow Hills Community Library
Owner Address: 510 Sweet Hollow Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: On-Site Operator

25 MELVILLE PARK ROAD (Continued) **1009234856**

Sub Type: E
Owner Name: Not reported
Owner Company: New York Twist Drill
Owner Address: 25 Melville Park Road
Owner Addr2: Not reported
Owner City,St,Zip: Melville, NY 11747
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Raymond Sohmer
Owner Company: Karakoram LLC
Owner Address: c/o Philips International Holding Corp.
Owner Addr2: 295 Madison Avenue, 2nd Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: Dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TETRACHLOROETHENE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: TRICHLOROETHENE (F001 & F002 WASTE)

25 MELVILLE PARK ROAD (Continued) **1009234856**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152169
Waste Type: 1,1,1-TRICHLOROETHANE (F001 & F002 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W1-0998-04-04
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-02-03 15:39:00
Record Updated: 2016-02-03 15:39:00
Updated By: BFJANKAU
Crossref ID: V00128
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-09-29 12:07:00
Record Updated: 2008-09-29 12:07:00
Updated By: MOBARRIE

VCP:
Program Type: VCP
Site Code: 56832
HW Code: V00128
Site Class: C
SWIS: 5226
Region: 1
Town: Huntington
Acres: 6
Date Record Added: 11/30/2000
Date Record Updated: 03/13/2018
Updated By: JBSWARTO
Site Description: Location: The 25 Melville Park Road site is located at 25 Melville Park Road in a large commercial/industrial area immediately south of the Long Island Expressway in Melville, New York. Site Features: The main site feature is a two-story office building. Paved parking lots are located to the east and north of the building and a grass lawn is located to the south. Current Zoning/Use(s): The property is presently zoned for commercial use and currently used for offices. Historical Use(s): The site was initially developed in 1966 and occupied by the New York Twist Drill Company (NYTD) until 1984. NYTD manufactured carbon steel and other hardened metal twist drills. Operations included heat treatment with salt baths, nitriding, and vapor degreasing with chlorinated solvents. A State Pollutant Discharge Elimination System (SPDES) permit was in place from the mid 1960's to early 1980's, which permited discharging industrial wastewater from site operations to the environment. Several SPDES violations were issued to NYTD for unacceptable discharges. In 1985, the building was converted into a two-story office complex. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit #1 covers the on-site investigation and remediation being performed under a Voluntary Cleanup Agreement (Site #V00128) with a property owner not involved in the disposal. A Record of Decision (ROD) dated March 2004 selected enhanced reductive dechlorination with recovery

25 MELVILLE PARK ROAD (Continued) **1009234856**

of nonaqueous phased liquids (NAPL) as the primary components of the on-site remedy. A sub-slab depressurization system was installed and currently operational under the former manufacturing area to prevent soil vapor migration into the site building. A Site Management Plan and Environmental Easement define current site activities. Operable Unit #2 covers off-site activities, which are presented under the State Superfund Program (Site #152169). Site Geology and Hydrogeology: Glacial deposits consisting of stratified sand and gravel are present from the surface to a depth of approximately 50 feet. The Magothy formation underlies the glacial deposits and consists of fine grained sand with interbedded layers of clayey sand, silty sand, and clay. Groundwater is approximately 45 feet below ground surface and flows southeast.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern include tetrachlorethene (PCE) and associated breakdown products trichloroethene (TCE), cis-1,2 Dichloroethene (DCE), and vinyl chloride (VC). Dense non-aqueous phase liquid (DNAPL) consisting mostly of PCE and light non-aqueous phase liquid (LNAPL) consisting of waste oils are being recovered by hand bailing groundwater monitoring wells located beneath the loading dock area on the eastern side of the building. Due to the DNAPL on-site, elevated concentrations of PCE have been detected in the groundwater on-site. The selected remedy, enhanced reductive dechlorination, continues to be applied at the site to reduce groundwater contamination on-site.

Health Problem: People will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilates/removes air from beneath the building) was installed in northeastern corner of the site building. Positive indoor air pressure serves to prevent soil vapor intrusion from occurring in the western portion of the site building. Vapor intrusion concerns are limited to this one building. Off-site contaminated groundwater and associated potential exposures are assessed as part of activities for Operable Unit 2, Site #152169.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1966
Disp Term: 1984
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-10-27 16:15:00
Record Upd: 2012-10-24 11:42:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: NNN
Owner Name: Reference Librarian

25 MELVILLE PARK ROAD (Continued) **1009234856**

Owner Company:	Half Hollow Hills Public Library
Owner Address:	510 Sweet Hollow Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Melville, NY 11747
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Vim Goyal
Owner Company:	Omega Melville LLC
Owner Address:	18 Winthrop Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbury, NY 11797
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Raymond Sohmer
Owner Company:	Melville Opportunity LLC & Karahoram LLC
Owner Address:	c/o Philips International Holding Corp.
Owner Addr2:	295 Madison Avenue
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	V00128
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	152169
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-09-29 12:07:00
Record Updated:	2008-09-29 12:07:00
Updated By:	MOBARRIE
Crossref ID:	Liber D00012643 page 746
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-10-27 16:17:00
Record Updated:	2011-10-27 16:31:00
Updated By:	BFJANKAU
Crossref ID:	W1-0778-96-11(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	w1-0778-96-11(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

NY MANIFEST:

Country:	USA
EPA ID:	NYD012758322
Facility Status:	Not reported
Location Address 1:	25 MELVILLE PARK ROAD
Code:	BP
Location Address 2:	Not reported

25 MELVILLE PARK ROAD (Continued) **1009234856**

Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11747
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012758322
Mailing Name:	25 MPR LLC
Mailing Contact:	MARK CONDON
Mailing Address 1:	445 BROADHOLLOW RD SUITE 430
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6312937800

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	11/13/2017
Trans1 Recv Date:	11/13/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/13/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012758322
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	001335198VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds

25 MELVILLE PARK ROAD (Continued) **1009234856**

Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D043
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP000946558
Facility Status:	Not reported
Location Address 1:	25 MELVILLE PARK RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MELVILLE
Location State:	NY
Location Zip:	11746
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000946558
Mailing Name:	ARCHON GROUP
Mailing Contact:	PETER JURGS
Mailing Address 1:	25 MELVILLE PARK RD
Mailing Address 2:	Not reported
Mailing City:	MELVILLE
Mailing State:	NY
Mailing Zip:	11747
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6318436179

T100 **CIRCUITRON CORP.** **NPL 1009968701**
SW **82 MILBAR BOULEVARD** **SEMS NYD981184229**
1/2-1 **EAST FARMINGDALE, NY 11735** **US ENG CONTROLS**
0.968 mi. **LIENS 2**
5111 ft. **Site 1 of 2 in cluster T** **RCRA NonGen / NLR**
ROD
Relative: **PRP**
Lower

Actual: **86 ft.**

NPL:

EPA ID:	NYD981184229
Cerclis ID:	202301
EPA Region:	2
Federal:	N
Final Date:	1989-03-31 00:00:00
Site Score:	54.270000000000003
Latitude:	40.749499999999998
Longitude:	-73.419499999999999

CIRCUITRON CORP. (Continued) **1009968701**

Category Details:
NPL Status: Currently on the Final NPL
Category Description: Depth To Aquifer-> 25 And <= 50 Feet
Category Value: 26

NPL Status: Currently on the Final NPL
Category Description: Distance To Nearest Population-> 1/4 And <= 1/2 Mile
Category Value: 2640

Site Details:
Site Name: CIRCUITRON CORP.
Site Status: Final
Site Zip: 11735
Site City: EAST FARMINGDALE
Site State: NY
Federal Site: No
Site County: SUFFOLK
EPA Region: 02
Date Proposed: 06/24/88
Date Deleted: Not reported
Date Finalized: 03/31/89

Substance Details:
NPL Status: Currently on the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: C178
Substance: COPPER AND COMPOUNDS
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: D008
Substance: LEAD (PB)
CAS #: 7439-92-1
Pathway: GROUND WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U044
Substance: CHLOROFORM
CAS #: 67-66-3
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U226
Substance: TRICHLOROETHANE, 1,1,1-
CAS #: 71-55-6
Pathway: GROUND WATER PATHWAY

CIRCUITRON CORP. (Continued) **1009968701**

Scoring: 2

Summary Details:

Conditions at proposal June 24, 1988): Circuitron Corp. manufactured circuit boards during 1961-86 on about 1 acre at 82 Milbar Boulevard, East Farmingdale, Suffolk County, New York. The site is in a densely populated industrial/commercialarea of Long Island east of Route 110 and the State University of New York Farmingdale Campus. The property is owned by 82 Milbar Boulevard Corp. Circuitron was a subsidiary of FEE Industries, which ADI Electronics, Inc., bought in 1984.The facility discharged thousands of gallons of metal-containing plating wastes to an underground leaching pool permitted under the State Pollutant Discharge Elimination System SPDES), to unauthori ed leaching pools beneath the floor of the plating room, and to a storm drain. After ADI Electronics purchased the facility, the Suffolk County Department of Health Services SCDHS) identified the discharge to the SPDES pool and the storm drain. Since 1984, SCDHS has issued Circuitron numerous notices of violations. On June 12, 1984, Circuitron agreed to an Order on Consent from SCDHS requiring removal of all ha ardous substances from the site. On March 7, 1985, SCDHS issued a Stipulated Agreement in which Circuitron agreed to install three monitoring wells, analy e ground water, and clean out one of the unauthori ed leaching pools. In mid-1986, the company vacated the facility without complying with all SCDHS requirements. In addition, Circuitron received one of the largest fines ever in the State for environmental pollution. The original owner has been convicted of a felony as a result of illegal waste discharges. Extensive sampling of the site by SCDHS detected heavy metals and chlorinated organic solvents in the SPDES leaching pool, the unauthori ed leaching pools, and the storm drains. Analyses of the monitoring wells installed as part of the Stipulated Agreement detected 1,1,1-trichloroethane in on-site wells downgradient of themanufacturing building. In May 1987, EPA found potentially explosive conditions at the site. From 125 to 150 drums, most unmarked and one bulging, were left hapha ardly throughout the building when it was vacated. Incompatible andreactive wastes were not segregated. Some drums were marked sulfuric acid, hydrochloric acid, sodium hydroxide, and caustic soda. Other smaller containers were strewn outside. Six concrete holding tanks containing unknown materials were belowthe floor and three aboveground storage tanks were behind the building. The aquifers underlying Long Island have been designated as Sole Source Aquifers under the Safe Drinking Water Act. At least 15 municipal wells serving over 215,000people are within 3 miles of the site, the nearest 1,000 feet in the direction ground water flows. The shallow well has been closed since 1978 due to volatile organic chemical contamination from an unknown source. The building is not fenced or guarded. Employees of other businesses in the area use the site for parking. Status March 31, 1989): EPA is preparing a workplan for a remedial investigation/feasibility study to determine the type and extent of contamination atthe site and identify alternatives for remedial action.

Site Status Details:

NPL Status:	Final
Proposed Date:	06/24/1988
Final Date:	03/31/1989
Deleted Date:	Not reported

Narratives Details:

NPL Name:	CIRCUITRON CORP.
City:	EAST FARMINGDALE
State:	NY

CIRCUITRON CORP. (Continued) **1009968701**

SEMS:
Site ID: 202301
EPA ID: NYD981184229
Cong District: 2
FIPS Code: 36103
Latitude: 40.749499999999998
Longitude: -73.419499999999999
FF: N
NPL: Currently on the Final NPL
Non NPL Status: Not reported

SEMS Detail:
Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 4
Action Code: RD
Action Name: RD
SEQ: 4
Start Date: 1991-06-24 00:00:00
Finish Date: 9/30/1994
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 3
Action Code: RD
Action Name: RD
SEQ: 3
Start Date: 1991-06-21 00:00:00
Finish Date: 9/30/1994
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 3
Action Code: RA
Action Name: RA
SEQ: 3
Start Date: 1994-09-30 00:00:00
Finish Date: 3/31/1997
Qual: Not reported
Current Action Lead: EPA Perf

CIRCUITRON CORP. (Continued) **1009968701**

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	2
Action Code:	RA
Action Name:	RA
SEQ:	2
Start Date:	1997-09-10 00:00:00
Finish Date:	5/15/2001
Qual:	IR
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	1
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	1988-09-27 00:00:00
Finish Date:	3/29/1991
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	1
Action Code:	RA
Action Name:	RA
SEQ:	1
Start Date:	1994-09-30 00:00:00
Finish Date:	9/30/1996
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	0
Action Code:	MA
Action Name:	ST COOP
SEQ:	1
Start Date:	1989-04-28 00:00:00
Finish Date:	3/1/2006

CIRCUITRON CORP. (Continued) **1009968701**

Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: NF
Action Name: NPL FINL
SEQ: 1
Start Date: 1989-03-31 00:00:00
Finish Date: 3/31/1989
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 2
Action Code: RD
Action Name: RD
SEQ: 2
Start Date: 1995-02-01 00:00:00
Finish Date: 9/30/1996
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 1
Action Code: RO
Action Name: ROD
SEQ: 1
Start Date: 1991-03-29 00:00:00
Finish Date: 3/29/1991
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 1
Action Code: RD
Action Name: RD

CIRCUITRON CORP. (Continued) **1009968701**

SEQ: 1
Start Date: 1991-06-24 00:00:00
Finish Date: 9/30/1994
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: NP
Action Name: PROPOSED
SEQ: 1
Start Date: 1988-06-24 00:00:00
Finish Date: 6/24/1988
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1989-04-17 00:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: 1990-03-21 00:00:00
Finish Date: 9/8/1990
Qual: S
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N

CIRCUITRON CORP. (Continued) **1009968701**

OU: 2
Action Code: RO
Action Name: ROD
SEQ: 2
Start Date: 1994-09-30 00:00:00
Finish Date: 9/30/1994
Qual: R
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: PA
Action Name: PA
SEQ: 2
Start Date: 1987-09-23 00:00:00
Finish Date: 9/23/1987
Qual: L
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: FE
Action Name: 5 YEAR
SEQ: 3
Start Date: 2015-01-12 00:00:00
Finish Date: 1/12/2015
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: TA
Action Name: TECH ASSIST
SEQ: 1
Start Date: 2005-07-16 00:00:00
Finish Date: 6/29/2012
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229

CIRCUITRON CORP. (Continued) **1009968701**

Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	2
Action Code:	CO
Action Name:	RI/FS
SEQ:	2
Start Date:	1992-01-27 00:00:00
Finish Date:	9/30/1994
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	0
Action Code:	FE
Action Name:	5 YEAR
SEQ:	2
Start Date:	2010-04-05 00:00:00
Finish Date:	4/5/2010
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	2
Action Code:	LR
Action Name:	LT RESP
SEQ:	1
Start Date:	2001-05-15 00:00:00
Finish Date:	5/16/2011
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202301
EPA ID:	NYD981184229
Site Name:	CIRCUITRON CORP.
NPL:	F
FF:	N
OU:	0
Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	1988-09-15 00:00:00
Finish Date:	9/28/1989
Qual:	C
Current Action Lead:	EPA Perf

CIRCUITRON CORP. (Continued) **1009968701**

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: RS
Action Name: RV ASSESS
SEQ: 2
Start Date: 1993-02-08 00:00:00
Finish Date: 2/9/1993
Qual: S
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1987-06-26 00:00:00
Finish Date: 6/29/1987
Qual: H
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: FE
Action Name: 5 YEAR
SEQ: 1
Start Date: 2005-08-05 00:00:00
Finish Date: 8/5/2005
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 1
Action Code: AR
Action Name: ADMIN REC
SEQ: 2
Start Date: 1991-03-28 00:00:00
Finish Date: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Qual: E
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: CM
Action Name: PCOR
SEQ: 1
Start Date: 2000-09-22 00:00:00
Finish Date: 9/22/2000
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 1
Action Code: ED
Action Name: R/H ASMT
SEQ: 1
Start Date: 1990-08-15 00:00:00
Finish Date: 8/15/1990
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1986-03-25 00:00:00
Finish Date: 3/25/1986
Qual: Not reported
Current Action Lead: St Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 0
Action Code: PA
Action Name: PA

CIRCUITRON CORP. (Continued) **1009968701**

SEQ: 1
Start Date: 1986-03-28 00:00:00
Finish Date: 3/28/1986
Qual: L
Current Action Lead: St Perf

Region: 2
Site ID: 202301
EPA ID: NYD981184229
Site Name: CIRCUITRON CORP.
NPL: F
FF: N
OU: 2
Action Code: OM
Action Name: OM
SEQ: 1
Start Date: 2011-06-01 00:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: St Perf

US ENG CONTROLS:
EPA ID: NYD981184229
Site ID: 0202301
Name: CIRCUITRON CORP.
Address: 82 MILBAR BOULEVARD
EAST FARMINGDALE, NY 11735
EPA Region: 02
County: SUFFOLK
Event Code: Not reported
Actual Date: 09/30/1994
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Buildings/Structures
Engineering Control: Decontamination
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Buildings/Structures
Engineering Control: Disposal
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001

CIRCUITRON CORP. (Continued) **1009968701**

Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Excavation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Treatment, (N.O.S.)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 03/29/1991
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Soil Vapor Extraction (in-situ)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Aeration
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Air Stripping
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Carbon Adsorption
Contact Name: Not reported
Contact Phone and Ext: Not reported

CIRCUITRON CORP. (Continued) **1009968701**

Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Coagulation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Discharge
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Extraction
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Flocculation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Operations & Maintenance (O&M)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater

CIRCUITRON CORP. (Continued) **1009968701**

Engineering Control: Reinjection
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Residuals Discharge
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 09/30/1994
Operable Unit: 02
Contaminated Media : Groundwater
Engineering Control: Sedimentation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

LIENS 2:
Facility name: CIRCUITRON CORP.
Facility address: 82 MILBAR BOULEVARD
EAST FARMINGDALE, NY 11735
EPA ID: NYD981184229
Effective date: Not reported
Lien: LP-1
Party name: Not reported
Reg: 2
Release date: Not reported
Start date: 03/02/1989
Complete date: 03/02/1989

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: CIRCUITRON SITE
Facility address: 82 MILBAR AVE
EAST FARMINGDALE, NY 11735
EPA ID: NYD981184229
Mailing address: US ARMY CORPS OF ENGINEERS
1900 HEMPSTEAD TPK STE 316
EAST MEADOW, NY 11554-0000
Contact: SHEWEN BIAN
Contact address: US ARMY CORPS OF ENGINEERS
EAST MEADOW, NY 11554-0000
Contact country: US
Contact telephone: 516-794-2913
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator

CIRCUITRON CORP. (Continued) **1009968701**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CIRCUITRON SITE
Classification: Not a generator, verified

Date form received by agency: 06/29/1998
Site name: CIRCUITRON SITE
Classification: Large Quantity Generator

Violation Status: No violations found

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

PRP:
PRP name:
ADI CIRCUITS, INC.
ADI CIRCUITS, INC.
ADI ELECTRONICS, INC.
ADI ELECTRONICS, INC.
CIRCUITRON CORP.
CIRCUITRON CORP.
CIRCUITRON CORP.
F.E.E. INDUSTRIES, INC.
F.E.E. INDUSTRIES, INC.
F.E.E./CHRIONICS, INC.
FEE CHRIONICS, INC.
JOSEPH Z. GAZZA
JULIUS J. D'AMATO
MR. JULIUS D'AMATO
MR. MARIO LOMBARDO
THOMAS J. LOVE

T101
SW
1/2-1
0.968 mi.
5111 ft.

UNITED STATES DEPT OF ENVIRONEMNTAL PROTECTION-SITE:82 MILBAR AVE
EAST FARMINGDALE, NY 11735

Site 2 of 2 in cluster T

NY SHWS **1007204997**
NY ENG CONTROLS **NYP000789883**
NY INST CONTROL
RCRA NonGen / NLR

Relative: Lower

Actual: 86 ft.

SHWS:

Program:	HW
Site Code:	55856
Classification:	4
Region:	1
Acres:	0.95
HW Code:	152082
Record Add:	11/18/1999
Record Upd:	03/30/2018
Updated By:	JLDYBER

Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

ENG CONTROLS:
Site Code: 55856
HW Code: 152082
Control Code: 13
Control Type: ENG
Date Record Added: 04/07/2011
Date Rec Updated: 11/16/2017
Updated By: TLRIDNER
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

(SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082
Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	PLATING WASTES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD981184229
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	2006-06-14 08:08:00
Record Updated:	2006-06-14 08:08:00
Updated By:	rmdenyse
Site Code:	55856
HW Code:	152082
Control Code:	12
Control Type:	ENG
Date Record Added:	04/07/2011
Date Rec Updated:	11/16/2017
Updated By:	TLRIDNER
Site Description:	Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1961
Disp Term:	present
Lat/Long:	40:44:58:0 / 73:25:07:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2011-05-13 18:26:00
Updated By:	jetrad
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MARIO LOMBARDO
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	08
Owner Name:	Bob Geier
Owner Company:	Mid-Island Bindery Inc.
Owner Address:	77 Schmitt Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-1406
Owner Country:	United States of America
HW Code:	152082
Waste Type:	HEAVY METALS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	1,1,2-TRICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	152082
Waste Type:	PLATING WASTES
Waste Quantity:	UNKNOWN

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
HW Code: 152082
Control Code: 16
Control Type: ENG
Date Record Added: 04/07/2011
Date Rec Updated: 11/16/2017
Updated By: TLRIDNER
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

INST CONTROL:
Site Code: 55856
Control Name: Site Management Plan
HW Code: 152082
Control Code: 32
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: Monitoring Plan
HW Code: 152082
Control Code: 31
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Site Code: 55856

Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: Ground Water Use Restriction
HW Code: 152082
Control Code: 08
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: Soil Management Plan
HW Code: 152082
Control Code: 14
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: Landuse Restriction

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

HW Code: 152082
Control Code: 25
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.
Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: Environmental Easement
HW Code: 152082
Control Code: J
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

Site Code: 55856
Control Name: O&M Plan
HW Code: 152082
Control Code: 33
Control Type: INST
Dt record added: 04/07/2011
Dt rec updated: 11/16/2017
Updated By: TLRIDNER
Site Code: 55856
Site Description: Location: The Circuitron Site a 0.95-acre site and is located at 82 Milbar Boulevard in Farmingdale, Long Island, in an urban, industrial park. Site Features: The main site features include one treatment building housing the extraction and treatment system and one treatment trailer for the single integrated groundwater circulating well with an in-well vapor stripping and SVE (GCW/IVS/SVE)system. The rest of the site consists of paved, stoned or grassed areas. The site is flat with commercial properties on all sides. Current Zoning and

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Land Use: The site is currently inactive, and is zoned for industrial/commercial use. The surrounding parcels are currently used for a combination of commercial, industrial, and manufacturing. The nearest residential area is 0.56 miles north on Cinnamon Court. Except for the State University, there are no schools or any recreational facilities in the immediate vicinity. Past Use of the Site: Circuitron Corporation, a circuit board manufacturing facility operating from 1961 to 1986 and occupied a single building at this site. Circuitron employed photographic and dry film photoresist process, silk screen processes as well as some plating and etching operations. Process wastes associated with facility operations contained heavy metals and solvents and were discharged to the ground through leaching pools. Circuitron had received numerous warnings from both the Suffolk County Deaprtment of Health Services (SCDHS) and NYSDEC concerning State Pollution Discharge Elimination System (SPDES) permit violations and unauthorized discharges. An Order on Consent and a Stipulated Agreement, issued by the SCDHS in 1984 and 1985, respectively, required that all leaching pools and storm drains be remediated; all toxic and hazardous materials be removed from the site including drums, tanks, and piping; and a groundwater quality study be performed. In 1986 Circuitron abandoned the property leaving behind various storage tanks and drums and went bankrupt. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area, which includes soil and sediments. Operable unit 2 (OU2) OU2 consists of the on-site and off-site groundwater. Site Geology and Hydrogeology: The Site is generally flat and has a slight slope up to the southeast of less than 1 percent. The Site elevation is approximately 85 to 90 feet above mean sea level. The uppermost aquifer, the Upper Glacial, is estimated to be 80 feet thick beneath the Site. The depth to the water table is approximately 30 feet below grade. The saturated portion of the Upper Glacial aquifer, with a thickness of 50 feet, begins at the water table and extends down to 80 feet below grade. The Upper Glacial aquifer is underlain by the Magothy aquifer which is approximately 700 feet thick in the vicinity of the Site. Groundwater flow in both aquifers is toward the southeast.

Env Problem: Remediation at the site is complete but requires continued management. Prior to remediation, the primary contaminants of concern were heavy metals and organics in groundwater and soil. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in soil is unlikely because the majority of the site is covered with paved, stoned or grassed areas and is fenced to restrict access. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. An evaluation

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

of the potential for soil vapor intrusion to occur will be completed should the current use of the site change.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1961
Disp Term: present
Lat/Long: 40:44:58:0 / 73:25:07:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2011-05-13 18:26:00
Updated By: jetrad
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: MARIO LOMBARDO
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: 08
Owner Name: Bob Geier
Owner Company: Mid-Island Bindery Inc.
Owner Address: 77 Schmitt Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-1406
Owner Country: United States of America
HW Code: 152082
Waste Type: HEAVY METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,1-TRICHLOROETHANE (TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: METHYL ETHYL KETONE (A.K.A. 2-BUTANONE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: 1,1,2-TRICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152082
Waste Type: PLATING WASTES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981184229
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID

UNITED STATES DEPT OF ENVIRONEMNTAL (Continued) **1007204997**

Record Added Date: 2006-06-14 08:08:00
Record Updated: 2006-06-14 08:08:00
Updated By: rmdenyse

RCRA NonGen / NLR:
Date form received by agency: 03/03/1990
Facility name: UNITED STATES DEPT OF ENVIRONEMNTAL
Facility address: PROTECTION-SITE:82 MILBAR AVE
EAST FARMINGDALE, NY 11735-1406
EPA ID: NYP000789883
Mailing address: PROTECTION-REGION2-WOODBRIDGE
AVENUE - EDISON, NY 08837
Contact: UNKNOWN UNKNOWN
Contact address: PROTECTION-REGION2-WOODBRIDGE
AVENUE - EDISON, NY 08837
Contact country: US
Contact telephone: 201-906-6827
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/02/1990
Site name: UNITED STATES DEPT OF ENVIRONEMNTAL
Classification: Not a generator, verified

Date form received by agency: 03/01/1990
Site name: UNITED STATES DEPT OF ENVIRONEMNTAL
Classification: Large Quantity Generator

Violation Status: No violations found

Count: 3 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
EAST FARMINGDALE	S113916706	PINELAWN/FARMINGDALE - HORTONSPHER	E/S BROADHOLLOW ROAD	11735	NY SHWS
FARMINGDALE	S105841217	RJN ASSOCIATES; LTD	NEW HIGHWAY	11735	NY SWF/LF
MELVILLE	S113916744	MELVILLE PLUME TRACKDOWN	SOUTH SERVICE ROAD	11747	NY SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/06/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 66

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 66

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/16/2018
Date Data Arrived at EDR: 02/22/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 78

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/09/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/27/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/29/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/27/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/29/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/19/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 73

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/24/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/16/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 01/06/2018
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/12/2018
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/27/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/27/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/16/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/24/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/13/2018
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/24/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 134

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/30/2018
Number of Days to Update: 33
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 06/27/2017
Date Data Arrived at EDR: 09/21/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 1
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/29/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 46

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 06/15/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Semi-Annually

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/19/2018
Date Data Arrived at EDR: 03/21/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 06/07/2018
Next Scheduled EDR Contact: 09/24/2018
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/30/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 05/04/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 02/22/2018
Date Data Arrived at EDR: 03/01/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/22/2018
Date Data Arrived at EDR: 03/01/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 05/07/2018
Date Data Arrived at EDR: 05/09/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 27
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 94
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 73
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/16/2018
Date Made Active in Reports: 06/12/2018
Number of Days to Update: 27
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/11/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/15/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 01/11/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/07/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/08/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/09/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 94

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 11/02/2017
Date Data Arrived at EDR: 11/17/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/20/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2017
Date Data Arrived at EDR: 06/09/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 126

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 04/09/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/07/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/04/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/03/2018
Date Data Arrived at EDR: 01/04/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 99

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/05/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 79

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 04/06/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/11/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 12/23/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/17/2017
Number of Days to Update: 52

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/07/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 24

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 01/25/2018
Date Data Arrived at EDR: 02/28/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 72

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/31/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/08/2018
Date Data Arrived at EDR: 03/13/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 87

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/06/2018
Next Scheduled EDR Contact: 09/24/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/21/2018
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 28

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 06/06/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2016
Date Data Arrived at EDR: 10/31/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 73

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 01/04/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 06/01/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 02/25/2018
Date Data Arrived at EDR: 03/17/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/06/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/20/2018
Date Data Arrived at EDR: 02/21/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 30

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/23/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 02/07/2018
Date Data Arrived at EDR: 02/13/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/20/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 09/25/2017
Date Data Arrived at EDR: 09/26/2017
Date Made Active in Reports: 10/12/2017
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 03/07/2018
Date Data Arrived at EDR: 03/30/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/07/2018
Next Scheduled EDR Contact: 09/24/2018
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/14/2018
Date Data Arrived at EDR: 03/23/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 52

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 12/01/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/29/2017
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 60

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 06/07/2018
Next Scheduled EDR Contact: 09/24/2018
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 04/30/2018
Date Data Arrived at EDR: 05/03/2018
Date Made Active in Reports: 06/07/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/25/2017
Date Data Arrived at EDR: 10/27/2017
Date Made Active in Reports: 11/28/2017
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2018
Date Data Arrived at EDR: 02/15/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/04/2018
Date Data Arrived at EDR: 03/08/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 06/07/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/01/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/01/2018
Next Scheduled EDR Contact: 09/17/2018
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 04/26/2018
Date Data Arrived at EDR: 05/11/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 25
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Semi-Annually

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 04/26/2018
Date Data Arrived at EDR: 05/11/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 25

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 01/03/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/22/2018
Number of Days to Update: 36

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/11/2017
Date Made Active in Reports: 07/27/2017
Number of Days to Update: 107

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/23/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 07/25/2017
Date Made Active in Reports: 09/25/2017
Number of Days to Update: 62

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/12/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/21/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 01/12/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 02/13/2018
Number of Days to Update: 25

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/16/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/13/2017
Date Made Active in Reports: 07/14/2017
Number of Days to Update: 92

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/11/2018
Next Scheduled EDR Contact: 09/24/2018
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

NEWSDAY
235 PINELAWN ROAD
MELVILLE, NY 11747

TARGET PROPERTY COORDINATES

Latitude (North):	40.763451 - 40° 45' 48.42''
Longitude (West):	73.406648 - 73° 24' 23.93''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	634487.5
UTM Y (Meters):	4513508.0
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940609 HUNTINGTON, NY
Version Date:	2013
South Map:	5940593 AMITYVILLE, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General ENE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36103C0620G	FEMA Q3 Flood data
Additional Panels in search area:	**FEMA Source Type**
36103C0835G	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
HUNTINGTON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile South
Site Name:	Tronic Plating Co., Inc
Site EPA ID Number:	NYD002059517
Groundwater Flow Direction:	South-Southeast
Measured Depth to Water:	not available.
Hydraulic Connection:	Information is not available about the hydraulic connection between aquifers underlying the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Pleistocene
Code:	Qp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 5337044.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Newsday	CLIENT:	The Vertex Companies, Inc.
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Stephen Mccarthy
LAT/LONG:	40.763451 / 73.406648	INQUIRY #:	5337044.2s
		DATE:	June 19, 2018 1:00 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Haven

Soil Surface Texture: highly decomposed plant material

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	highly decomposed plant material	A-8	Highly organic soils, Peat.	Max: 42 Min: 1.4	Max: 5.5 Min: 4.5
2	5 inches	18 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 6 Min: 4.5
3	1 inches	5 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 6 Min: 4.5
4	18 inches	27 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 14 Min: 4	Max: 6 Min: 4.5

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
5	27 inches	59 inches	stratified gravelly sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 6 Min: 4.5

Soil Map ID: 2

Soil Component Name: Plymouth

Soil Surface Texture: loamy sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6
2	3 inches	27 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	27 inches	59 inches	gravelly coarse sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 5.5 Min: 3.6

Soil Map ID: 3

Soil Component Name: Plymouth

Soil Surface Texture: loamy sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6
2	3 inches	27 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 5.5 Min: 3.6

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	27 inches	59 inches	gravelly coarse sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand.	Max: 141 Min: 141	Max: 5.5 Min: 3.6

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000832018	1/8 - 1/4 Mile WNW
A2	USGS40000832101	1/4 - 1/2 Mile NNE
3	USGS40000832056	1/4 - 1/2 Mile ENE
A4	USGS40000832122	1/4 - 1/2 Mile NNE
5	USGS40000832149	1/4 - 1/2 Mile North
B6	USGS40000831804	1/4 - 1/2 Mile SSE
7	USGS40000832121	1/4 - 1/2 Mile NE
B8	USGS40000831758	1/4 - 1/2 Mile SSE
9	USGS40000831759	1/2 - 1 Mile SW
10	USGS40000832176	1/2 - 1 Mile NNW
11	USGS40000832113	1/2 - 1 Mile WNW
C12	USGS40000831627	1/2 - 1 Mile SW
C13	USGS40000831628	1/2 - 1 Mile SW
14	USGS40000832219	1/2 - 1 Mile NW
15	USGS40000832187	1/2 - 1 Mile ENE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found


Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 5337044.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Newsday	CLIENT:	The Vertex Companies, Inc.
ADDRESS:	235 Pinelawn Road Melville NY 11747	CONTACT:	Stephen Mccarthy
		INQUIRY #:	5337044.2s
LAT/LONG:	40.763451 / 73.406648	DATE:	June 19, 2018 1:00 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
WNW **FED USGS** **USGS40000832018**
1/8 - 1/4 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404550073243501		
Monloc name:	S 65546. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.763988
Longitude:	-73.4092883	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	54
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1994-03-02		62.91

A2
NNE **FED USGS** **USGS40000832101**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404602073241501		
Monloc name:	S 7271. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7673213
Longitude:	-73.4037325	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	406
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

3
ENE **FED USGS** **USGS40000832056**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404555073240501		
Monloc name:	S112871. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7653768
Longitude:	-73.4009547	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	40
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4
NNE **FED USGS** **USGS40000832122**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404605073241701		
Monloc name:	S 66132. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7681546
Longitude:	-73.4042881	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	140
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-09-13		66.56	1982-06-30		67.39
1982-03-12		67.24	1981-12-14		66.00
1981-06-15		68.07	1980-12-19		69.51
1980-09-15		70.97	1980-06-27		72.06
1980-03-06		69.84	1980-01-17		70.64

5
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000832149**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404608073242101		
Monloc name:	S 42680. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7689879
Longitude:	-73.4053992	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.7
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 66

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-12-29					
Note: The well was destroyed (no water level is recorded).					
1982-09-27		66.48	1982-09-13		66.78
1982-06-30		67.56	1982-06-14		67.58
1982-03-16		67.13	1982-03-12		67.25
1981-12-14		65.98	1981-09-15		66.97
1981-06-16		68.03	1981-06-12		68.03
1981-03-26		69.58	1981-01-05		69.22
1980-12-11		69.79	1980-09-26		70.91
1980-06-25		72.30	1980-03-25		70.94
1979-12-27		70.85	1979-09-21		71.80

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1979-06-20		72.90	1979-04-12		72.66
1979-03-26		70.78	1979-03-20		72.77
1979-01-22		71.13	1978-12-22		68.94
1978-12-21		69.10	1978-11-20		69.06
1978-10-23		69.62	1978-10-04		69.87
1978-09-25		70.04	1978-08-22		70.65
1978-07-25		70.53	1978-06-27		70.85
1978-06-17		70.99	1978-06-01		71.05
1978-04-20		70.94	1978-03-28		71.01
1977-12-27		68.49	1977-09-26		66.03
1977-07-27		66.46	1977-06-22		66.94
1977-04-05		67.98	1976-12-21		67.79
1976-09-21		68.85	1976-06-22		69.35
1976-03-22		69.96	1975-12-30		68.43
1975-09-29		68.31	1975-09-04		68.31
1975-06-24		68.20	1975-06-18		68.07
1975-03-26		66.73	1975-02-20		66.43
1974-12-16		65.73	1974-10-09		66.57
1974-09-20		66.82	1974-08-05		67.00
1974-07-18		67.39	1974-06-03		68.24
1973-07-09		68.73	1973-04-03		62.77
1973-01-23		63.65	1972-10-02		62.40
1972-07-12		62.99	1972-03-27		62.60
1972-01-20		62.23			

B6
SSE **FED USGS** **USGS40000831804**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404530073241101		
Monloc name:	S 43811. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7584324
Longitude:	-73.4026215	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	102.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	197206	Welldepth:	90
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 48

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1994-03-23		61.83	1990-03-01		65.10
1983-03-04		60.61	1982-12-08		61.27
1982-09-07		62.82	1982-06-16		63.58
1982-03-02		63.08	1981-12-04		61.77
1981-09-08		62.55	1981-06-12		63.48
1981-03-03		64.08	1980-12-02		65.21
1980-09-04		66.60	1979-06-25		68.44
1979-04-17		68.26	1979-03-20		68.32
1979-01-22		65.03	1978-12-21		64.23
1978-11-20		64.49	1978-10-23		64.86
1978-09-25		65.34	1978-09-22		65.88
1978-08-22		65.88	1978-07-25		66.11
1978-06-27		66.42	1978-06-01		66.42
1978-04-12		66.38	1978-03-23		66.76
1977-12-08		63.29	1977-10-03		61.63
1977-06-09		64.66	1977-03-22		62.99
1976-12-23		63.75	1976-10-13		65.08
1976-06-21		64.74	1976-04-12		65.43
1975-12-15		63.73	1975-10-02		63.90
1975-06-18		63.88	1975-02-15		61.93
1974-12-04		61.27	1974-08-05		62.64
1974-07-08		63.46	1974-05-24		64.11
1974-04-12		63.88	1974-03-11		63.17
1974-02-11		63.12	1974-01-17		62.88

7
NE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000832121**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404605073240801		
Monloc name:	S 4656. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7681546
Longitude:	-73.401788	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	100.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	141
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B8
SSE **FED USGS** **USGS40000831758**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404527073241201		
Monloc name:	S 23059. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7575991
Longitude:	-73.4028993	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	105.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	204
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

9
SW **FED USGS** **USGS40000831759**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404527073244601		
Monloc name:	S 31023. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7575992
Longitude:	-73.412344	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	384
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

10
NNW **FED USGS** **USGS40000832176**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404612073244501		
Monloc name:	S 10830. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7700991
Longitude:	-73.412066	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	110.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	80
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

11
WNW **FED USGS** **USGS40000832113**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404604073245801		
Monloc name:	S 57666. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7678769
Longitude:	-73.4156773	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	105.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	270
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

C12
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831627**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404518073250201		
Monloc name:	S 19538. 1		
Monloc type:	Well		
Monloc desc:	NEW: S 80573. 1 19850913		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7550992
Longitude:	-73.4167887	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19610322	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

C13
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831628**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404518073250202		
Monloc name:	S 80573. 1		
Monloc type:	Well		
Monloc desc:	OLD: S 19538. 1 19850913		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7550992
Longitude:	-73.4167887	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	96.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	19850913	Welldepth:	200
Welldepth units:	ft	Wellholedepth:	202
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

14
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000832219**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404617073250701		
Monloc name:	S 11262. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.771488
Longitude:	-73.4181774	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	110.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	175
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

15
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000832187**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404613073233601		
Monloc name:	S 5869. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030202	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7703767
Longitude:	-73.3928988	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	200.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Magothy Aquifer		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	191
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
SUFFOLK	BABYLON	49	1.07	0.76	5.5
SUFFOLK	BROOKHAVEN	117	1.61	1.22	7.5
SUFFOLK	E. HAMPTON	19	1.55	1.16	4.7
SUFFOLK	HUNTINGTON	146	2.13	1.47	22.2
SUFFOLK	ISLIP	61	1.19	0.74	10.4
SUFFOLK	NORTHPORT	4	1.43	1.12	2.5
SUFFOLK	RIVERHEAD	9	2.18	1.26	8.9
SUFFOLK	SHELTER ISLAND	1	1.1	1.1	1.1
SUFFOLK	SMITHTOWN	60	3.02	1.48	42.6
SUFFOLK	SOUTHAMPTON	24	0.99	0.8	2.8
SUFFOLK	SOUTHOLD	7	2.47	1.58	8.6

Federal EPA Radon Zone for SUFFOLK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SUFFOLK COUNTY, NY

Number of sites tested: 183

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.670 pCi/L	100%	0%	0%
Basement	1.010 pCi/L	98%	2%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX H:

RESUMES OF ENVIRONMENTAL PROFESSIONALS

Christopher Cook
Project Manager

[ccook@vertexeng.com / 908-333-4303]

Highlights:

Subsurface Investigation Expertise
Nationwide Due Diligence Experience
Project Management Experience Nationwide

Expertise:

Mold
Compliance Audits
Database Review
Environmental Portfolio Reviews
Letter of Reliance
Peer Review
Phase I ESAs
Phase II LSI
Transaction Screen
Pollution Claim Management
Environmental Health & Safety
Groundwater & Soil Characterization
Hazardous Materials/Waste
PCB
Remediation & Construction Management
Site Characterization
UST Removal

Education/Training:

B.S., Environmental Health Science, University of Georgia, 2002

Biography:

Mr. Cook has 12 years experience working in the environmental consulting field. Mr. Cook's experience includes extensive work in due diligence including: Phase I Environmental Site Assessments (ESAs), Phase II Limited Subsurface Investigations, compliance audits, desktop reviews, and peer reviews. In addition, Mr. Cook has performed and completed site investigations and remedial investigations per strict United States Environmental Protection Agency (USEPA) and New Jersey Department of Environmental Protection (NJDEP) guidelines. Mr. Cook has also completed numerous water intrusion assessments, asbestos-containing material (ACM) assessments, and environmental insurance audits.

As Project Manager, Mr. Cook offers both organizational and technical support to the strategic environmental management team at VERTEX. Specific duties include: conducting site visitations and environmental investigations, project oversight, technical writing, report preparation, and client consultation. Organizational responsibilities include: scheduling, subcontractor management, and subcontractor oversight.

Licenses/Certifications:

IATA Dangerous Goods
First Aid/CPR
OSHA HAZWOPER 40 hour course
EPA/AHERA/ASHARA (TSCA Title II) Building Inspector and Assessor, 3108
OSHA 30-Hour Construction Safety Trained, May 2010
OSHA Excavation Competent Person, May 2010
Environmental Professional as defined by the USEPA in §312.10 of 40 CFR 312
OSHA Hazardous Waste Supervisor, May 2010
OSHA Confined Space Entry Supervisor, May 2010

Relevant Experience:

[PHASE I ENVIRONMENTAL SITE ASSESSMENTS] -

Mr. Cook has completed hundreds of Phase I Environmental Site Assessments for various clients including lending institutions, large corporations, and private clients on sites including filling stations, dry cleaning establishments, large industrial facilities, commercial shopping centers, and multi-family residential properties throughout the United States.

[PHASE II LIMITED SUBSURFACE INVESTIGATIONS] -

Mr. Cook has completed multiple Phase II Limited Subsurface Investigations for various clients including lending institutions, large corporations, and private clients on sites including filling stations, dry cleaning establishments, large industrial properties, commercial properties, and multi-family residential properties throughout the United States.

[SOIL/GROUNDWATER] -

Mr. Cook has field experience including oversight of installation of soil borings and groundwater monitoring wells; and sampling of soil, soil gas, groundwater, sediment, and surface water. Mr. Cook has performed and field managed sampling events at several military installations and at industrial, commercial, and residential properties.

[PROJECT MANAGEMENT] -

Mr. Cook has served as the Project Manager for various Environmental Investigation and Remediation projects. Projects included Phase I ESAs, Phase II Limited Subsurface Investigations, Asbestos Building Inspections, NJDEP Known Contaminated Sites, UST Closures/Compliance, and additional property assessments.

[COMPLIANCE AUDITING/HEALTH & SAFETY] -

Mr. Cook has experience with health and safety planning, and compliance auditing at sites including major industrial facilities.

[DUE DILIGENCE/REMEDIATION] *Walgreens, Northeast and Mid-Atlantic United States.*

Ms. Cook conducted numerous Phase I ESAs, Phase II Limited Subsurface Investigations, remedial investigations, and regulatory correspondence and compliance of numerous Walgreen pre-development sites between 2006 and 2009. Mr. Cook worked with Walgreens and associated developers to provide correspondence throughout the due diligence process.

[FEDERAL ENVIRONMENTAL SITES] -

Mr. Cook has performed environmental investigations at several Federally-regulated environmental sites. This has included the performance of regulatory audits at Federal Emergency Management Agency (FEMA) sites, investigation of soil and groundwater at Superfund sites, and multi-phase investigations at military installations.

[ENVIRONMENTAL INSURANCE AUDITS] -

Mr. Cook has performed environmental insurance-based audits for a major environmental insurance carrier including site inspections, thorough site interviews, and detailed reports to assist the client in making risk-based insurance decisions.

[INDUSTRIAL HYGIENE] -

Mr. Cook has performed several industrial hygiene evaluations included asbestos inspections, lead-based paint inspections, and water intrusion/mold inspections.

[SAFETY] -

As the Certified Site Safety Officer for the local company office, Mr. Cook was responsible for the oversight of sampling, excavation, trenching, and drilling. In addition, responsibilities included preparation of health and safety plans, job safety analyses, and maintaining safety documentation and certifications for office personnel.

[STATE REGULATED PETROLEUM SITES] -

Mr. Cook performed soil and groundwater investigations at several state regulated petroleum release sites in Georgia and Alabama.

[PHASE I BUSINESS DEVELOPMENT] -

Mr. Cook has experience in marketing, sales, management, and billing of due

diligence investigations.

[DUE DILIGENCE/SITE INVESTIGATION] *Extra Space Storage, Mahwah, New Jersey.*

Extra Space Storage, Mahwah, New Jersey. Mr. Cook performed a Phase I ESA, Phase II Limited Subsurface Investigation, and subsequent NJDEP-required investigations under the NJDEP Site Remediation Program at a historic fill site. A Response Action Outcome (RAO) was achieved for the site which brought it to regulatory closure with limited groundwater-use restrictions.

[DUE DILIGENCE/REMEDIATION] *Former Landscaping Company, Somerset, New Jersey.*

Former Landscaping Company, Somerset, New Jersey. Mr. Cook performed a Phase I ESA, Phase II Limited Subsurface Investigation, and subsequent NJDEP-required investigations under the NJDEP Site Remediation Program at a former landscaping company property. Investigation activities led to remedial activities which included removal and disposal of petroleum-impacted soil. The site received an unrestricted-use RAO in 2014.

[DUE DILIGENCE/SITE INVESTIGATION] *Flomatic, Glens Falls, New York.*

Mr. Cook performed a Phase I ESA at a large industrial facility which resulted in a Phase II Limited Subsurface Investigation and frequent Client interaction. Based on the results and regulatory discussions, the Client was able to secure a loan to purchase the property.

[PHASE 1 ESA] *Morristown Municipal Airport, Morristown, New Jersey.*

Mr. Cook a Phase I ESA on a large airport property which included inspection of greater than ten structures, review and summary of hundreds of regulatory documents, and frequent interaction with the Client. The project was completed and the Client was able to secure a loan for additional development projects.

[SOIL/GROUNDWATER INVESTIGATION AND REMEDIATION] *GE Fairfield, Fairfield, NJ*

Mr. Cook performed soil and groundwater investigation activities in an attempt to identify "hot-spot" areas for future remedial activities. Impacted source areas were identified and subsequently remediated via excavation and removal activities.

Stephen McCarthy
Vice President, Due Diligence

[smccarthy@vertexeng.com / 781-952-6067]

Highlights:

Nationwide Due Diligence Experience
Project Management Experience Nationwide

Expertise:

Asbestos
Mold
Compliance Audits
PCA
Environmental Health & Safety
Remediation & Construction Management

Education/Training:

B.A., History, Providence College, 1986

Biography:

Mr. McCarthy has over 25 years of experience in Environmental Consulting. He has routinely managed several hundred environmental assessment due diligence projects per year for financial, commercial and institutional clients. These projects included Phase I and Phase II Environmental Site Assessments, asbestos surveys and abatement, mold assessments, removal of underground storage tanks and site investigations.

As Vice President, Mr. McCarthy is responsible for project and staff management, document review, quality control and client management. He is responsible for sales, client interaction, proposal preparation and quality assurance of product. In addition, Mr. McCarthy is also responsible for managing the set up and timely completion of due diligence services including Phase I ESAs, planning and management of Phase II subsurface investigations and remediation projects. Specifically this work includes observation of properties and operations, historic site research, delineation of contaminated media, coordinating UST removals, oversight of excavation activities, development of remediation strategies and serving as the liaison between clients, contractors and regulatory agencies.

Licenses/Certifications:

OSHA 40 Hour HAZWOPER

Relevant Experience:

[PHASE I ESAS] *Wisconsin*

Prepared Phase I Environmental Site Assessmets to assess seven gasoline stations located in Wisconsin. Project included review of the site history and regulatory records to evaluate the potential for recognized environmental conditions in connection with the sites.

[PHASE I ESA AND PCA] *12-Story Multi-Tenant Office Building, Philadelphia, PA.*

Mr. McCarthy managed and oversaw all aspects of a Phase I ESA and Property Condition Assessment (PCA) performed at an 12-story multi-tenant office building located in Philadelphia. The site had a long history of industrial operations dating back to the 1890s. Responsibilities included staff/project management, document review and quality control and client interface on all aspects of the project.

[PHASE I ESAS] *35 Site Gasoline Portfolio*

Prepared Phase I Environmental Site Assessmets to assess 35 gasoline stations located in four states. Project included review of the site history and regulatory records to evaluate the potential for recognized environmental conditions and any obvious regulatory compliance issues in connection with the sites.

[PORTFOLIO EVALUATION] *New Jersey Gas Station Portfolio*

As part of a plan acquistion of 17 gasoline stations in New Jersey, VERTEX was retained to review the environmental reports for each of the gasoline stations to evaluate known release cases as well as potential unknown issues and provide a risk quantification based on review of the avaialble documentation. In addition, VERTEX conducted a review and evaluation of remedial cost estimates that were prepared for each of the facilites. Managed the team of Engineers and Scientists who performed the document review and prepared an evaluation of the portfolio and potential liabilities.

[ENVIRONMENTAL DUE DILIGENCE] *Nationwide Experience*

[PHASE I & II ESAs] *Nationwide Due Diligence Program, Confidential Client.* Developed and managed a nationwide due diligence program which included conducting Phase I Environmental Site Assessments (ESAs) at over 400 company owned properties to assess environmental risk. Developed a risk rating matrix, which summarized key findings from the ESAs and provided a risk quantification estimate for each property. Follow-up activities at select properties included subsurface investigations, tank closures, and removal/repair of damaged asbestos-containing materials. Responsibilities included staff/project management, document review and quality control and client interface on all aspects of the project.

[PHASE I ESAs] *Phase I ESAs of 350 properties, Confidential Client.* Coordinated and oversaw all aspects of environmental assessments of a 350-site portfolio of commercial properties nationwide. Responsibilities included staff/project management, document review and quality control and client interface on all aspects of the project.

[PHASE I ESAs/ENVIRONMETAL CHECKLIST] *Nationwide, Confidential Client.* Coordinated and oversaw all aspects of environmental assessments, including Phase I ESAs and Environmental Checklists, of over 400 commercial and residential properties nationwide. Responsibilities included staff/project management, document review and quality control and client interface on all aspects of the project.

[PHASE I ESA] *15,000 acres in Georgia, Confidential Client.* Coordinated and oversaw all aspects of a Phase I ESA completed on 15,000 acres in southern Georgia in support of a real estate transaction. Responsibilities included develop of the assessment strategy, staff/project management, document review and quality control and client interface on all aspects of the project.

[UST CLOSURE] *Pittsburgh, PA, Confidential Client.* Coordinated and oversaw all aspects of the removal of six underground storage tanks (USTs) associated with a former gasoline station and subsequent remediation of releases associated with the USTs. Responsibilities included staff/project management, document review and quality control and client interface on all aspects of the project.

[ASBESTOS ABATEMENT] *Dallas, TX.* Managed a $2 million dollar asbestos abatement project at an occupied high rise office building. Responsibilities included project design, specification preparation, conducting pre-bid conferences, collection and analysis of air samples, daily inspections of abatement contractor's work practices and consultation with owner's representative on all aspects of the abatement project.

[ASBESTOS SURVEYS] *Bank and Office Buildings, TX.* Performed asbestos-containing material surveys of a 110 building portfolio containing over 8 million square feet of space located throughout the State of Texas. Responsibilities included design of the survey strategy, on-site inspection and collection of bulk material samples, assessment of asbestos-containing materials,

interpretation of data, and preparation of final reports. Project included recommendations for further action at each facility, if warranted, development of associated cost estimates and development and implementation of an asbestos management program.

[PORTFOLIO REVIEW] *California Gas Station Portfolio*

As part of a plan acquistion of 52 gasoline stations in California, VERTEX was retained to review the environmental reports for each of the gasoline stations to evaluate known release cases as well as potential unknown issues and provide a risk quantification based on review of the avaialble documentaiton. Managed the team of Engineers and Scientists who performed the document review and prepared an evaluation of the portfolio and potential liabilities.