Phase I Environmental Site Assessment

824 Metropolitan Avenue
Brooklyn, New York

EBI Project No. 1115005479

July 28, 2015

Prepared for:

Mr. Zois Sachtouris
116 East 83rd Street
New York, NY

Prepared by:

EBI Consulting
environmental | engineering | due diligence

DRAFT

EBI Consulting
environmental | engineering | due diligence

21 B Street
Burlington, MA 01803
Tel: (781) 273-2500
Fax: (781) 273-3311
www.ebiconsulting.com

July 28, 2015

Mr. Zois Sachtouris
116 East 83rd Street
New York, NY

Subject: Phase I Environmental Site Assessment
824 Metropolitan Avenue, Brooklyn, New York
EBI Project No. 1115005479

Dear Mr. Sachtouris:

Attached please find our *Phase I Environmental Site Assessment* (the report) for the above-mentioned asset (the Subject Property). During the survey and research, our surveyor met with agents representing the Subject Property, or agents of the owner, and reviewed the Subject Property and its history. The report was completed according to the terms and conditions authorized by you. This report has been completed in general conformance with the ASTM Standard E 1527-13.

The purpose of this report is to acquire environmental information, observe the general condition and maintenance status of the Subject Property, to suggest remediation and/or maintenance practices considered customary for the Subject Property to continue in its current operation, compared to properties of similar age and condition, and to identify recognized environmental conditions in connection with the Subject Property described in this report.

Reliance on the report and the information contained herein shall mean (i) the report may be relied upon by a lender to be selected by *Mr. Zois Sachtouris*, in determining whether to make a loan evidenced by a note secured by the Subject Property ("the Mortgage Loan"); (ii) the report may be relied upon by any purchaser in determining whether to purchase the Mortgage Loan (but not the Subject Property) from that lender, or an interest in the Mortgage Loan or securities backed or secured by the Mortgage Loan, and any rating agency rating securities representing an interest in the Mortgage Loan or backed or secured by the Mortgage Loan; (iii) the report may be referred to in and included, in whole or in part, with materials offering for sale the Mortgage Loan or an interest in the Mortgage Loan or securities backed or secured by the Mortgage Loan; (iv) the report speaks only as of its date in the absence of a specific written update of the report signed and delivered by EBI Consulting.

There are no intended or unintended third party beneficiaries to this report, except as expressly stated herein.

EBI is an independent contractor, not an employee of either the issuer or the borrower, and its compensation was not based on the findings or recommendations made in the report or on the closing of any business transaction.

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Thank you very much for the opportunity to provide environmental consulting services to *Mr. Zois Sachtouris*. Should you have any questions or require additional information, please do not hesitate to contact the undersigned.

Respectfully submitted,
EBI CONSULTING

Jon Hickey
Author / Program Manager

Jennifer Callaghan
Reviewer / Program Manager
jcallaghan@ebiconsulting.com
484.680.2757

DRAFT

TABLE OF CONTENTS

EXECUTIVE SUMMARY **1**
1.0 INTRODUCTION **3**
1.1 Purpose 3
1.2 Scope-of-Services 3
1.3 Assumptions, Limitations and Exceptions 3
1.4 Special Terms and Conditions 5
1.5 Data Gaps 6
2.0 SUBJECT PROPERTY DESCRIPTION **7**
2.1 Ownership and Location 7
2.2 Subject Property Improvements 7
2.3 Current Use of the Subject Property 7
2.4 Municipal Services & Utilities 7
2.5 Adjoining Properties 8
3.0 USER PROVIDED INFORMATION **9**
3.1 Title Records 9
3.2 Environmental Liens and Activity and Use Limitations 9
3.3 Specialized Knowledge 9
3.4 Commonly Known or Reasonably Ascertainable Information 9
3.5 Valuation Reduction for Environmental Issues 9
3.6 Owner, Property Manager, and Occupant Information 9
3.7 Reason for Performing Phase I ESA 9
4.0 RECORDS REVIEW **10**
4.1 Standard Environmental Records 10
4.1.1 Federal Agency Database Records 11
4.1.2 State and Tribal Agency Database Records 13
4.1.3 Local Regulatory Agency Records 18
4.2 Physical Setting 19
4.2.1 Topography 19
4.2.2 Geology and Soils 19
4.2.3 Hydrogeology and Hydrology 19
4.3 Historical Use of the Subject Property and Adjoining Properties 19
4.3.1 Aerial Photographs 20
4.3.2 Fire Insurance Maps 21
4.3.3 Topographic Maps 22
4.3.4 Street Directories 23
4.3.5 Recorded Land Title Records 23
4.3.6 Property Tax Records 23
4.3.7 Environmental Liens and Activity and Use Limitations 23
4.3.8 Previous Environmental Reports 23
4.3.9 Other Historical Records and Interviews 23
5.0 SUBJECT PROPERTY RECONNAISSANCE **24**
5.1 Methodology and Limiting Conditions 24
5.2 Hazardous Substances and Petroleum Products 24
5.2.1 Hazardous Substances and Petroleum Products (Identified Uses) 24
5.2.2 Hazardous Substances and Petroleum Products (Unidentified Uses) 24
5.2.3 Unidentified Substances Containers 24
5.3 Waste Generation, Storage, and Disposal 25

DRAFT

5.4 Underground Storage Tanks (USTs) & Aboveground Storage Tanks (ASTs) 25
5.4.1 Existing Storage Tanks 25
5.4.2 Former Storage Tanks 25
5.5 Oil-Containing Equipment and Polychlorinated Biphenyls (PCBs) 25
5.6 Additional Site Conditions 25
6.0 INTERVIEWS 27
7.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM PRACTICE E 1527-13 28
7.1 Asbestos-Containing Material (ACM) 28
7.2 Radon 28
7.3 Lead-Based Paint (LBP) 28
7.4 Lead in Drinking Water 29
7.5 Vapor Migration 29
8.0 FINDINGS AND OPINIONS 30
9.0 RECOMMENDATIONS 32
10.0 REFERENCES 33

APPENDIX A PHOTOGRAPHS
APPENDIX B FIGURES
APPENDIX C PRE-SURVEY QUESTIONNAIRE AND OTHER RELEVANT DOCUMENTATION
APPENDIX D PROFESSIONAL QUALIFICATIONS
APPENDIX E REGULATORY DATABASE REPORT
APPENDIX F HISTORICAL DOCUMENTATION
APPENDIX G TERMINOLOGY

DRAFT

EXECUTIVE SUMMARY

At the request of Mr. Zois Sachtouris, EBI has performed a Phase I Environmental Site Assessment (ESA) of the property located at 824 Metropolitan Avenue in Brooklyn, New York, herein referred to as the Subject Property. The main objective of this ESA was to identify *recognized environmental conditions* in connection with the Subject Property, defined in ASTM Practice E 1527-13 as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: 1) due to any release to the environment, 2) under conditions indicative of a release to the environment, or 3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions. This ESA also includes a preliminary evaluation of certain potential environmental conditions that are outside the scope of ASTM Practice E 1527-13.

The Subject Property includes one rectangular-shaped parcel, totaling approximately 0.12 acres (5,000 square feet). The Subject Property consists of an asphalt-paved lot, with no existing structures or other improvements. At the time of assessment, the paved lot was unoccupied with overgrown vegetation and storage of construction debris, tires, and drums scattered throughout the lot. There are currently no operations conducted at the Subject Property.

Below is the Assessment Summary Table presenting our recommended actions for the Subject Property. EBI's Findings and Opinions are presented in Section 8.0, and recommendations for further action or investigation are presented in Section 9.0.

DRAFT

ASSESSMENT SUMMARY TABLE			
Assessment Component	**Section(s)**	**Recommended Actions**	**Estimated Cost**
Historical Review	4.3	No Further Action	
Current Occupants / Operations	2.3, 5.0	No Further Action	
Hazardous Substances / Petroleum Products	5.2	EBI recommends that the contents of the unlabeled and discarded 30-gallon and 55-gallon drums located on the northern and western portions of the Subject Property be characterized and properly disposed of in accordance with applicable state and local requirements.	$2,500
Waste Generation	5.3	EBI recommends the discarded debris, trash, and other solid waste, including concrete, plywood, toilets, bathtubs, tires, various objects, empty drums, and 5-gallon containers located on the eastern, southern, and western portions of the Subject Property, be disposed of by a licensed waste hauler.	Action Item
Storage Tanks	5.4	No Further Action	
PCBs	5.5	No Further Action	
Potential Off-site Sources	2.5, 4.1	No Further Action	
Regulatory Agency / Database Review	4.1	No Further Action	
Asbestos Containing Materials	7.1	No Further Action	
Radon	7.2	No Further Action	
Lead-Based Paint	7.3	No Further Action	
Lead in Drinking Water	7.4	No Further Action	
Vapor Migration	7.5	No Further Action	

DRAFT

1.0 INTRODUCTION

This report documents the findings, opinions, and conclusions of a Phase I Environmental Site Assessment (ESA) of the property located at 824 Metropolitan Avenue in Brooklyn, New York.

1.1 PURPOSE

The purpose of this ESA was to identify *recognized environmental conditions* and certain environmental conditions outside the scope of ASTM Practice E 1527-13 in connection with the property at the time of the property reconnaissance.

1.2 SCOPE-OF-SERVICES

This ESA was conducted utilizing a standard of good commercial and customary practice that was consistent with the ASTM Practice E 1527-13. Any significant scope-of-work additions, deletions or deviations to ASTM Practice E 1527-13 are noted below or in the corresponding sections of this report. The scope-of-work for this assessment included an evaluation of the following:

- Physical characteristics of the Subject Property through a review of referenced sources for topographic, geologic, soils and hydrologic data.
- Subject Property history through a review of referenced sources such as land deeds, fire insurance maps, city directories, aerial photographs, prior reports, and interviews.
- Current Subject Property conditions, including observations and interviews regarding the following: the presence or absence of hazardous substances or petroleum products; generation, treatment, storage, or disposal of hazardous, regulated, or biomedical waste; equipment that utilizes oils which potentially contain PCBs; and storage tanks (aboveground and underground).
- Usage of surrounding area properties and the likelihood for releases of hazardous substances and petroleum products (if known and/or suspected) to migrate onto the Subject Property.
- Information in referenced environmental agency databases and local environmental records, within specified minimum search distances.
- Past ownership through a review of available prior reports and local municipal file review.

The scope-of-work also included consideration of the following potential environmental conditions that are outside the scope of ASTM Practice E 1527-13: asbestos-containing materials (ACM), lead-based paint (LBP), lead in drinking water, and radon.

1.3 ASSUMPTIONS, LIMITATIONS AND EXCEPTIONS

This Phase I Environmental Site Assessment (the report) has been prepared for the use of Mr. Zois Sachtouris, in accordance with our Standard Conditions for Engagement and Authorization Letter and Agreement for Environmental Services approved and signed by Mr. Zois Sachtouris, and with the limitations described below, all of which are integral parts of this report. A copy of the signed Standard Conditions For Engagement and Authorization Letter and Agreement for Environmental Services is maintained at the EBI Consulting office in Burlington, Massachusetts.

DRAFT

EBI has performed this Phase I Environmental Site Assessment in conformance with the scope and limitations of *ASTM Standard E 1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process*. This report was prepared with no exceptions or deletions from ASTM Standard E 1527-13.

This Phase I Environmental Site Assessment has been prepared to assess a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) and petroleum products. As such, this practice is intended to permit Mr. Zois Sachtouris to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability: that is, the practices that constitute "all appropriate inquiry into the previous ownership and uses of the Subject Property consistent with good commercial or customary practice" as defined in 42 U.S.C. § 9601(35)(B).

In defining a standard of good commercial and customary practice for conducting an environmental site assessment of a parcel of property, the goal of the processes established by this practice is to identify *recognized environmental conditions*. The term recognized environmental conditions means the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: 1) due to any release to the environment, 2) under conditions indicative of a release to the environment, or 3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include *de minimis conditions* that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions.

The information reported was obtained through sources deemed reasonably ascertainable, as defined in ASTM Standard E 1527-13; a visual site survey of areas readily observable, easily accessible or made accessible by the Subject Property contact and interviews with owners, agents, occupants, or other appropriate persons involved with the Subject Property. Municipal information was obtained through review of reasonably ascertainable standard government record sources and interviews with the authorities having jurisdiction over the Subject Property. Findings, conclusions, and recommendations included in the report are based on our visual observations in the field, the municipal information reasonably obtained, information provided by the Client, and/or a review of readily available and supplied documents and drawings. EBI relies completely on the information, whether written, graphic, or verbal, provided by the Subject Property contact or as shown on any documents reviewed or received from the Subject Property contact, owner or agent, or municipal source, and assumes that information to be true and correct. Although there may have been some degree of overlap in the information provided by these various sources, EBI did not attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of these environmental services.

The observations in this report are valid on the date of the investigation. Where access to portions of the Subject Property or to structures on the Subject Property was unavailable or limited, EBI renders no opinion as to the presence of hazardous substances or petroleum products in that portion of the Subject Property or structure. Inaccessible portions of the Subject Property are described below. In addition, EBI renders no opinion as to the presence of, or indirect evidence relating to, hazardous substances or petroleum products where direct observation of the interior walls, floor, or ceiling of a structure was obstructed by objects or coverings on or over these surfaces.

DRAFT

It is acknowledged that EBI judgments shall not be based on scientific or technical tests or procedures beyond the scope of the Services or beyond the time and budgetary constraints imposed by the Client. It is acknowledged further that EBI conclusions shall not rest on pure science but on such considerations as economic feasibility and available alternatives. Client also acknowledges that, because geologic and soil formations are inherently random, variable, and indeterminate in nature, the Services and opinions provided under this Agreement with respect to such Services are not guaranteed to be a representation of actual conditions on the Subject Property, which are also subject to change with time as a result of natural or man-made processes, including water permeation. In performing the Services, EBI shall use that degree of care and skill ordinarily exercised by environmental consultants or engineers performing similar services in the same or similar locality. The standard of care shall be determined solely at the time the Services are rendered and not according to standards utilized at a later date. The Services shall be rendered without any other warranty, expressed or implied, including, without limitation, the warranty of merchantability and the warranty of fitness for a particular purpose.

Client and EBI agree that to the fullest extent permitted by law, EBI shall not be liable to Client for any special, indirect or consequential damages whatsoever, whether caused by EBI's negligence, errors, omissions, strict liability, breach of contract, breach of warranty or other cause or causes whatsoever.

The ASTM Standard E 1527-13 does not encompass analytical testing to evaluate asbestos containing materials, radon, lead-based paint, drinking water quality, indoor air quality, stored chemicals, debris, fill materials, surface water, or subsurface samples (soil and groundwater) as part of a Phase I ESA. Any analytical testing performed at the Subject Property has been conducted in accordance with the Standard Conditions for Engagement and Authorization Letter and Agreement for Environmental Services and the client-specific Scope of Work. Unless otherwise specified herein, such testing involves screening methods intended to provide a broad and approximate evaluation of conditions at readily accessible portions of the Subject Property, limited by project constraints, and should not be construed as a comprehensive program designed to comply with a specific regulatory program. If a thorough and regulatory-compliant study is warranted based on the findings of the Phase I ESA, EBI will recommend the appropriate further investigation. In certain cases, quantitative laboratory testing is performed as part of the assessment and analyses have been conducted by an outside laboratory. EBI relies upon the data provided by the outside laboratory, and has not conducted an independent evaluation of the reliability of this data.

The assessment was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession, and in accordance with generally accepted practices of other consultants currently practicing in the same locality under similar conditions. No other representation, expressed or implied, and no warranty or guarantee is included or intended. The report speaks only as of its date, in the absence of a specific written update of the report, signed and delivered by EBI.

Additional information that becomes available after our survey and draft submission concerning the Subject Property should be provided to EBI so that our conclusions may be revised and modified if necessary, at additional cost. This report has been prepared in accordance with our Standard Conditions for Engagement, which is an integral part of this report.

1.4 SPECIAL TERMS AND CONDITIONS

This Phase I Environmental Site Assessment (the report) has been prepared to assist Mr. Zois Sachtouris in its underwriting of a proposed mortgage loan on the Subject Property. This report can be relied upon by only the parties stated in the transmittal letter at the front of this report. EBI's liability to a purchaser wishing to use this report is limited to the cost of the report. Amendments to EBI's

limitations as stated herein that may occur after issuance of the report are considered to be included in this report. Payment for the report is made by, and EBI's contract and report extends to Mr. Zois Sachtouris only, in accordance with our Standard Conditions For Engagement and, Authorization Letter and Agreement for Environmental Services.

1.5 DATA GAPS

Any data gaps identified herein, as defined by ASTM Practice E 1527-13 § 3.2.20, are not considered to have significantly affected the ability to identify recognized environmental conditions in connection with the Subject Property and do not alter the conclusions of this report.

DRAFT

2.0 SUBJECT PROPERTY DESCRIPTION

2.1 OWNERSHIP AND LOCATION

According to the New York City Department of Finance, the Subject Property is currently owned by Zois Sachtouris.

The Subject Property is located at 824 Metropolitan Avenue in the New York City Borough of Brooklyn, Kings County, New York. The Subject Property includes one rectangular-shaped parcel, identified by the New York City Department of Finance as Block 2916, Lot 14, totaling approximately 0.12 acres (5,000 square feet). The Subject Property is located approximately 140 feet east of the intersection of Metropolitan Avenue and Bushwick Avenue. Figure 1 - Location Map depicts the location of the Subject Property on a street map of Brooklyn, New York. Figure 2 - Locus Map depicts the location of the Subject Property on the Brooklyn, New York United States Geological Survey (USGS) 7.5 Minute Topographic Quadrangle. Figure 3 - Site Plan depicts the configuration of the Subject Property and adjoining properties.

2.2 SUBJECT PROPERTY IMPROVEMENTS

The Subject Property consists of an asphalt-paved lot, with no existing structures or other improvements. The paved lot is enclosed with chain-link fencing and corrugated metal paneling. A gate located on the north side of the property, fronting Metropolitan Avenue, provides access to the Subject Property. Several trees are present along the perimeter of the property.

2.3 CURRENT USE OF THE SUBJECT PROPERTY

At the time of assessment, the Subject Property was unoccupied with overgrown vegetation and storage of construction debris, tires, and drums scattered throughout the lot. There are currently no operations conducted at the Subject Property. Please refer to Section 5.2 for further discussion regarding hazardous substances and petroleum products at the Subject Property.

2.4 MUNICIPAL SERVICES & UTILITIES

The Subject Property is serviced by the following municipal services and utilities:

MUNICIPAL SERVICES AND UTILITIES	
Utility	**Provider/Source**
Potable Water Supply	Not provided
Sewage Disposal System	Not provided
Electrical Service	Not provided
Natural Gas Service	Not provided
Oil Service	Not provided
Heating/Cooling Systems	Not provided
Emergency Power	Not provided

DRAFT

2.5 ADJOINING PROPERTIES

Property use in the vicinity of the Subject Property is primarily characterized by residential and retail/commercial development.

ADJOINING PROPERTIES	
North	The Subject Property is bound to the north by Metropolitan Avenue, beyond which are two- to three-story single and multi-family residential buildings (819-821 Metropolitan Avenue and 3 Orient Avenue). The intersection of Metropolitan Avenue and Orient Avenue is present to the northeast.
South	The Subject Property is bound to the south by multi-family residential apartment buildings to the southwest (15 and 15 ½ Bushwick Avenue) and a single-family residential dwelling to the southeast (217 Devoe Street). Farther south is Devoe Street.
East	The Subject Property is bound to the east by a multi-family residential apartment building (832 Metropolitan Avenue).
West	The Subject Property is bound to the west by a gasoline station occupied by Speedway Gas (810 Metropolitan Avenue). Farther west is Bushwick Avenue.

No visual evidence of adverse environmental conditions was observed during the survey of the adjoining properties, with the exception of the western adjoining Speedway gasoline station, which is identified as a Registered Storage Tank, Leaking Storage Tank, and Spills site, and is further discussed in Section 4.1.2 of this report.

DRAFT

3.0 USER PROVIDED INFORMATION

The following section summarizes information provided by Mr. Zois Sachtouris with regard to this Phase I Environmental Site Assessment. Additionally, a User Questionnaire was forwarded to the designated Client contact. The User Questionnaire has been completed and returned to our offices. The information requested in the User Questionnaire is intended to assist in gathering information that may be material to identifying recognized environmental conditions in connection with the Subject Property. The User Questionnaire and any additional documentation referenced below is presented in Appendix C.

3.1 TITLE RECORDS

Title record information associated with the Subject Property has not been provided to EBI by Mr. Zois Sachtouris. A detailed discussion regarding review of information obtained from other sources is presented in Section 4.3.5 of this report.

3.2 ENVIRONMENTAL LIENS AND ACTIVITY AND USE LIMITATIONS

Mr. Zois Sachtouris has provided no information regarding environmental liens or activity and use limitations in connection with the Subject Property. A detailed discussion regarding environmental liens is presented in Section 4.3.7 of this report. A detailed discussion regarding activity and use limitations is presented in Sections 4.1.1 and 4.1.2 of this report.

3.3 SPECIALIZED KNOWLEDGE

Mr. Zois Sachtouris provided no specialized knowledge that is material to recognized environmental conditions in connection with the Subject Property. EBI was not provided with or made aware of previous environmental assessments or other documentation that is material to recognized environmental conditions in connection with the Subject Property, except as presented in Section 4.3.8 of this report.

3.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION

Mr. Zois Sachtouris has provided no commonly known or reasonably ascertainable information within the local community about the Subject Property that is material to recognized environmental conditions in connection with the Subject Property.

3.5 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES

Mr. Zois Sachtouris has provided no information regarding valuation reduction for environmental issues in connection with the Subject Property.

3.6 OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION

Mr. Zois Sachtouris provided contact information for the Subject Property owner, manager and/or occupants.

3.7 REASON FOR PERFORMING PHASE I ESA

Mr. Zois Sachtouris retained EBI to complete this Phase I Environmental Site Assessment in connection with a real estate transaction.

DRAFT

4.0 RECORDS REVIEW

4.1 STANDARD ENVIRONMENTAL RECORDS

A review of standard environmental databases maintained by Federal, state, and tribal offices was completed through Environmental Data Resources, Inc. (EDR) of Shelton, Connecticut. The databases were searched for properties with reported environmental conditions located within approximate minimum search distances as specified by ASTM Standard E 1527-13, by using geocoding information that identified the coordinates of the properties in the databases or by checking the street addresses of practically reviewable non-geocoded "orphan" properties within the same zip code. The database report is presented in Appendix E.

The database report identified 18 "orphan sites." Orphan sites are those sites that could not be accurately mapped or geocoded due to inadequate location information. EBI attempted to locate these sites via vehicular reconnaissance and interviews with personnel familiar with the area. Based on this research, EBI did not identify listed orphan sites within the approximate minimum search distances that may be considered likely to have impacted conditions at the Subject Property.

It should be noted that plotted locations of listed sites are not always accurate. With regard to listings that are determined or suspected to be inaccurate, based on information from other sources such as direct observation or consultation with individuals familiar with the property, EBI uses the best available data when evaluating the location of listed sites discussed below. The following table provides a summary of the findings of the environmental database report. Specific properties identified within the database report are further discussed below.

SUMMARY OF FEDERAL, STATE, AND TRIBAL AGENCY DATABASE FINDINGS			
Regulatory Database	**Approximate Minimum Search Distance**	**Subject Property Listed**	**Off-site Listings Within Search Distance**
Federal NPL Sites	1.0 mile	No	**1**
Federal Delisted NPL Sites	0.5 mile	No	0
Federal CERCLIS Sites	0.5 mile	No	0
Federal CERCLIS NFRAP Sites	0.5 mile	No	**1**
Federal RCRA CORRACTS Sites	1.0 mile	No	0
Federal RCRA non-CORRACTS TSD Sites	0.5 mile	No	0
Federal RCRA Generators Sites	Property & Adjoining	No	0
Federal Engineering / Institutional Control Sites	0.5 mile	No	0
Federal ERNS Sites	Property	No	NA
State and Tribal equivalent NPL / CERCLIS Sites	1.0 / 0.5 mile	No	**11**
State and Tribal Spills Sites	Property	No	NA
State and Tribal Landfill or Solid Waste Disposal Sites	0.5 mile	No	**8**
State and Tribal Leaking Storage Tank Sites	0.5 mile	No	**33**
State and Tribal Registered Storage Tank Sites	Property & Adjoining	No	**1**
State and Tribal Engineering / Institutional Control Sites	0.5 mile	No	**1**
State and Tribal Voluntary Cleanup Sites	0.5 mile	No	0
State and Tribal Brownfield Sites	0.5 mile	No	**4**
New York Dry Cleaners Sites	Property & Adjoining	No	0
EDR Manufactured Gas Plant Sites	Property & Adjoining	No	0
EDR US Historical Auto Station Sites	Property & Adjoining	No	**1**
EDR US Historical Dry Cleaner Sites	Property & Adjoining	No	0

DRAFT

4.1.1 Federal Agency Database Records

National Priority List (NPL)
The NPL database, also known as the Superfund List, is a subset of CERCLIS and identifies sites that are ranked as high priority for remedial action under the Federal Superfund Act. The Subject Property was not identified on the NPL. However, one site located within 1.0 mile of the Subject Property was identified on the NPL. Information regarding the listed site is presented in the following table:

NPL			
Site	**Distance / Direction / Gradient***	**EPA ID No.**	**Regulatory Status**
Newtown Creek South End of Ivy Hill Road Brooklyn/Queens, NY	0.545 miles / East / Downgradient	NYN000206282	Discovery: 08/15/2008 Proposed: 09/23/2009 Final Listing on NPL: 09/29/2010 Contaminants: Not reported Media Impacted: Not reported

* Presumed hydrogeologic gradient based upon regional topography

Based upon the separating distance and presumed hydrogeologic gradient relative to the Subject Property, it is considered unlikely that conditions associated with the identified NPL facility represent an environmental concern to the Subject Property.

Delisted National Priority List (NPL)
The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate. Neither the Subject Property nor any sites located within 0.5 mile of the Subject Property were identified on the Delisted NPL database.

Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS)
CERCLIS contains data regarding potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies, and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability ACT (CERCLA). CERCLIS contains sites that are included on the National Priority List (NPL), as well as sites which are in the screening and assessment phase for possible inclusion on the NPL. Neither the Subject Property nor any sites located within 0.5 mile of the Subject Property were identified on the CERCLIS database.

CERCLIS – No Further Remedial Action Planned (CERCLIS-NFRAP)
As of February 1995, CERCLIS sites designated as No Further Remedial Action Planned (NFRAP) have been removed from the CERCLIS list. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed without the need for the site to be placed on the NPL, or the contamination was not considered sufficient to warrant Federal Superfund action or NPL consideration. The Subject Property was not identified on the CERCLIS-NFRAP database. However, one site located within 0.5 mile of the Subject Property was identified on the CERCLIS-NFRAP database. Information regarding the listed site is presented in the following table:

DRAFT

CERCLIS-NFRAP			
Site	**Distance / Direction / Gradient***	**EPA ID No.**	**Regulatory Status**
City Barrel & Drum Co. Inc. 421 Meeker Avenue Brooklyn, NY	0.415 miles / Northwest / Crossgradient	NYD068298835	Discovery: 04/25/1980 Preliminary Assessment: 09/02/1987 Archive Site: 09/02/1987 Status: NFRAP

* Presumed hydrogeologic gradient based upon regional topography

Based upon the current regulatory status, separating distance, and presumed hydrogeologic gradient relative to the Subject Property, it is considered unlikely that conditions associated with the identified CERCLIS-NFRAP facility represent an environmental concern to the Subject Property.

Resource Conservation and Recovery Act (RCRA) – Corrective Action Tracking System (CORRACTS)
RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS). The database includes selective information regarding sites that generate, transport, store, treat, and/or dispose of hazardous waste as defined by RCRA. The RCRA-CORRACTS database identifies TSD facilities that have conducted, or are currently conducting, corrective action(s) as regulated under RCRA. Neither the Subject Property nor any sites located within 1.0 mile of the Subject Property were identified on the RCRA CORRACTS database.

RCRA non-CORRACTS Treatment, Storage and/or Disposal (TSD) Facilities
RCRA non-CORRACTS Treatment, Storage and/or Disposal (TSD) facilities are required to register hazardous waste activity under the Resource Conservation and Recovery Act (RCRA). Neither the Subject Property nor any sites located within 0.5 mile of the Subject Property were identified on the RCRA non-CORRACTS TSD database.

RCRA Hazardous Waste Generators
Hazardous waste generators tracked under the Resource Conservation and Recovery Act (RCRA) are classified as either Large Quantity Generators (LQGs), Small Quantity Generators (SQGs), or Conditionally Exempt Small Quantity Generators (CESQG). A RCRA-LQG is defined as a facility that generates over 1,000 kilograms (Kg) of hazardous waste, or over 1 Kg of acutely hazardous waste per month. A RCRA-SQG is defined as a facility that generates between 100 Kg and 1,000 Kg of hazardous waste per month. A RCRA-CESQG is defined as a facility that generates less than 100 Kg of hazardous waste, or less than 1 Kg of acutely hazardous waste per month. Neither the Subject Property nor any adjoining properties were identified on the RCRA Generator database.

Federal Engineering Control / Institutional Control Registries
The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. Neither the Subject Property nor any sites located within 0.5 mile of the Subject Property were identified on Federal Engineering Control or Institutional Control Registries.

DRAFT

Emergency Response Notification System (ERNS)
ERNS is a national database used to collect information regarding reported releases of petroleum products and/or hazardous substances. The database contains information from spill reports submitted to Federal agencies, including the EPA, the U.S. Coast Guard, the National Response Center, and the U.S. Department of Transportation. A review of this database was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property was not identified on the ERNS database.

4.1.2 State and Tribal Agency Database Records

State and Tribal equivalent NPL Sites and CERCLIS Sites
State and tribal equivalent NPL and CERCLIS databases were searched for sites located within 1.0 mile and 0.5 mile of the Subject Property, respectively. The Subject Property was not identified on state and/or tribal databases. However, according to the State Hazardous Waste Site (SHWS) database, 11 SHWS sites are located within 1.0 mile of the Subject Property. All of the listed sites are located greater than 0.40 mile from the Subject Property and/or at a crossgradient location relative to the Subject Property. Based upon the distance and/or hydrogeologic separation from the Subject Property, these 11 sites are considered unlikely to represent an existing release, past release, or material threat of release of hazardous substances or petroleum products on the Subject Property.

State and Tribal Spills Sites (Spills)
A review of available Spills databases was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property was not identified on the Spills database.

However, the western adjoining gasoline station, identified as Merit Metropolitan located at 810 Metropolitan Avenue, was listed on the Spills database. According to the database listing, petroleum odors were encountered during the removal of several gasoline and diesel underground storage tanks (USTs) in 1995. The spill case was reported to the New York State Department of Environmental Conservation (NYSDEC) on June 5, 1995 under Case No. 9502757. Preliminary groundwater monitoring in 2005 revealed elevated levels of benzene, toluene, ethylbenzene, and xylenes (BTEX) and methyl tertiary-butyl ether (MTBE). A soil vapor extraction and air sparging (SVE/AS) system was installed in 2006 to pump and treat the contaminated groundwater. Oxygen Release Compound (ORC) socks were also installed in several monitoring wells in 2006. Multiple SVE/AS events were completed between 2006 and 2007, and subsequent groundwater monitoring revealed a significant decrease in BTEX and MTBE concentrations. A request for closure was submitted in 2007, but was denied by the NYSDEC as further soil and groundwater delineation was required. Downgradient monitoring wells were proposed to be installed in the sidewalk along Bushwick Avenue; however, delays were encountered due to the presence of the New York City subway system beneath Bushwick Avenue. Monitoring wells were eventually installed in 2012, and very low concentrations of BTEX and MTBE were detected. A second request for closure was submitted in 2012, but was denied by the NYSDEC as residual contaminated soil required further delineation and/or remediation. The release case was revisited by the NYSDEC at the Regional Spill Engineers meeting in 2013, and it was determined that soil exceedances observed were moderate and further excavation was not warranted, and that spill closure was warranted due to the following factors:

- Clean downgradient monitoring wells for numerous years;
- Age of spill and fact that monitoring wells have shown no increase in groundwater contamination for numerous years, and as such there is no likelihood for downward migration of soil contamination through the soil column to the water table;

DRAFT

- Excavation of UST systems and large amount of contaminated soil removed from site;
- Spills Database has an institutional control to account for possible future changes in site use as none reported to date; and,
- Addition of soil contamination notification in Spill Closure Letter.

The spill case (Case No. 9502757) was granted closure on May 6, 2013. Since residual contamination was left in place at the western adjoining gasoline station site at the time of case closure, EBI cannot completely dismiss the potential for impacts to the Subject Property in the absence of a subsurface investigation. However, based upon the reported remediation to the satisfaction of the NYSDEC, the recent regulatory closure, and the downgradient location relative to the Subject Property, further investigation at the Subject Property does not appear warranted at this time.

The western adjoining gasoline station, identified as Merit Metropolitan located at 810 Metropolitan Avenue, was listed on the Spills database for another release case reported on December 12, 1988 due to a spill of 100 gallons of gasoline caused by human error (Case No. 8807632). The spill was cleaned up with an absorbent material (Speedy Dry) and the case was granted closure on December 18, 1988. Based upon the current regulatory status and reported nature/extent of the release, this Spills case is not considered an environmental concern to the Subject Property.

State and Tribal Landfill Sites and Solid Waste Disposal Sites

The state and tribal landfill and solid waste disposal site databases identify active or inactive landfill and transfer station facilities, as well as open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. The Subject Property was not identified on state or tribal landfill and solid waste disposal site databases. However, eight sites located within 0.5 mile of the Subject Property were identified on state or tribal landfill and solid waste disposal site databases. All of the listed sites are located greater than 0.33 mile from the Subject Property and/or at a lower elevation relative to the Subject Property. Based upon the distance and/or hydrogeologic separation from the Subject Property, these eight sites are considered unlikely to represent an existing release, past release, or material threat of release of hazardous substances or petroleum products on the Subject Property.

State and Tribal Leaking Storage Tank Sites

Leaking Storage Tank Sites are properties where releases of hazardous substances or petroleum products from underground storage tanks (USTs) and/or aboveground storage tanks (ASTs) have been identified and reported to state, tribal, or local agencies. The Subject Property was not identified on state or tribal Leaking Storage Tank databases. However, according to the Leaking Storage Tank (LTANKS) database, 33 LTANKs sites are located within 0.5 mile of the Subject Property. Of the listed sites, 26 sites are located greater than 0.25 mile from the Subject Property and/or crossgradient/downgradient relative to the Subject Property. Based upon the distance and/or hydrogeologic separation from the Subject Property, these 26 sites are considered unlikely to represent an existing release, past release, or material threat of release of hazardous substances or petroleum products on the Subject Property. All of the seven LTANKS sites located within 0.25 mile of the Subject Property have been granted a "Closed" status by the New York State Department of Environmental Conservation (NYSDEC). The regulatory agency awards a "Closed" status only when contamination, if any, has been investigated and/or remediated in accordance with regulatory standards. Based upon the current regulatory status these sites are considered unlikely to represent an environmental concern to the Subject Property. An adjoining property was listed twice on the LTANKS database. Information regarding the adjoining LTANKS sites is presented in the following table:

DRAFT

STATE AND TRIBAL LEAKING STORAGE TANK SITES			
Site	**Distance / Direction / Gradient***	**Spill Case No.**	**Regulatory Status**
Merit Metropolitan 810 Metropolitan Avenue Brooklyn, NY	Adjacent / West / Downgradient	9404715	Notification Date: 07/06/1994 Contaminants: Gasoline Media Impacted: Not reported Status: Tank Test Failure; Isolate/Retest; Closed Date of Closure: 11/22/1994
Metropolitan Ave/Merrit Metropolitan & Bushwick Avenue Brooklyn, NY	Adjacent / West / Downgradient	8903546	Notification Date: 07/09/1989 Contaminants: Gasoline Media Impacted: Not reported Status: Tank Overfill; Closed Date of Closure: 07/10/1989

* Presumed hydrogeologic gradient based upon regional topography

According to the LTANKS database, two Leaking Storage Tank cases were identified at the western adjoining gasoline station, located at 810 Metropolitan Avenue. The first release case was reported on July 6, 1994 due to a failed tank tightness test (Case No. 9404715). The tank system was isolated and retested, and no gasoline was reportedly released. The case was granted closure on November 22, 1994. The second release case was reported on July 9, 1989 due to a tank overfill (Case No. 8903546). Approximately five gallons of gasoline was released during fuel delivery. The fire department was on scene, and cleaned up the spill with an absorbent material. No action was required by the NYSDEC due to the small size of the spill, and the case was granted closure on July 10, 1989. Based upon the current regulatory status, presumed hydrogeologic gradient relative to the Subject Property, and/or reported nature/extent of contamination, it is considered unlikely that conditions associated with the Leaking Storage Tank listings for the western adjoining property represent an environmental concern to the Subject Property. It is noted that the western adjoining gasoline station is cross-listed as a Spills site, and is further discussed in the corresponding section above.

State and Tribal Registered Storage Tanks

The Subject Property was not identified on state or tribal Registered Storage Tank databases. However, one adjoining property was identified on state or tribal Registered Storage Tank databases. Information regarding the listed site is presented in the following table:

STATE AND TRIBAL REGISTERED STORAGE TANKS				
Location	**Distance / Direction / Gradient***	**Capacity / Contents**	**Year Installed**	**Status**
Merit Metropolitan 810 Metropolitan Avenue Brooklyn, NY	Adjacent / West / Crossgradient to Downgradient	(1) 2,000-gallon UST / Gasoline	1979	Removed (1991)
		(1) 2,000-gallon UST / Gasoline	1979	Removed (1995)
		(3) 4,000-gallon USTs / Gasoline	1979	Removed (1995)
		(1) 4,000-gallon UST / Diesel	1979	Removed (1995)
		(1) 550-gallon UST / Other	1979	Removed (1995)
		(1) 600-gallon UST / Other	1995	Admin. Closed
		(1) 600-gallon UST / Other	1995	In Service
		(4) 4,000-gallon USTs / Gasoline	1995	In Service
		(1) 4,000-gallon UST / Diesel	1995	In Service

* Presumed hydrogeologic gradient based upon regional topography

DRAFT

The western adjoining gasoline station is cross-listed as a Leaking Storage Tank site and a Spills site, and is further discussed in the corresponding sections above.

State and Tribal Engineering Control / Institutional Control Registries

The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. The Subject Property was not identified on state or tribal Engineering Control or Institutional Control Registries. However, one site located within 0.5 mile of the Subject Property was identified on state or tribal Engineering Control or Institutional Control Registries. Information regarding the listed site is presented in the following table:

STATE AND TRIBAL ENGINEERING CONTROL / INSTITUTIONAL CONTROL REGISTRIES			
Site	**Distance / Direction / Gradient***	**HW Code**	**Regulatory Status**
Frito Lay 202-218 Morgan Avenue Brooklyn, NY	0.460 miles / East-southeast / Crossgradient	C224133	Site Description: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Status: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site. Engineering Controls: Asphalt/Concrete Cover Institutional Controls: Groundwater Use Restriction; Land Use Restriction; Soil Management Plan; Site Management Plan; Monitoring Plan; IC/EC Plan; O&M Plan; Environmental Easement

* Presumed hydrogeologic gradient based upon regional topography

Based upon the distance/presumed hydrogeologic gradient relative to the Subject Property, it is considered unlikely that conditions associated with the identified site represent an environmental concern to the Subject Property.

State and Tribal Voluntary Cleanup Sites

Neither the Subject Property nor any sites located within 0.5 mile of the Subject Property were identified on state or tribal Voluntary Cleanup Site databases.

State and Tribal Brownfield Sites

The Subject Property was not identified on state or tribal Brownfield Sites databases. However, four sites located within 0.5 mile of the Subject Property were identified on state or tribal Brownfield Sites databases. Information regarding the listed sites is presented in the following table:

STATE AND TRIBAL BROWNFIELD SITES			
Site	**Distance / Direction / Gradient***	**BCP ID No.**	**Regulatory Status**
Former Bennett Trucking Corp. 845 Grand Street Brooklyn, NY	0.177 miles / South-southeast / Crossgradient	485965	Contaminants: Petroleum-related VOCs Media Impacted: Soil and groundwater Status: Since the site is fenced and covered by asphalt or concrete, people will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes. Environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings
Former Scientific Fire Prevention Inc. 871 Grand Street Brooklyn, NY	0.188 miles / Southeast / Crossgradient	487645	Contaminants: Trichloroethene and Tetrachloroethene Media Impacted: Soil, groundwater, soil vapor Status: Significant Threat: It is not yet known whether there is a significant off-site environmental threat due to contamination at the BCP site. This section will be updated as data become available.
Frito Lay 202-218 Morgan Avenue Brooklyn, NY	0.460 miles / East-southeast / Crossgradient	485965	Contaminants: PCBs and metals Media Impacted: Soil and groundwater Status: Engineering and Institutional Controls in place (see corresponding section above)
555 Grand Street Brooklyn, NY	0.498 miles / West-southwest / Downgradient	489692	Contaminants: PCE, TCE, Mercury Media Impacted: Soil vapor and soil Status: Significant Threat: The site represents a significant threat due to the soil vapor contamination which may not be limited to the on-site area.

* Presumed hydrogeologic gradient based upon regional topography

Based upon the current regulatory status, distance/presumed hydrogeologic gradient relative to the Subject Property, and/or reported nature/extent of contamination, it is considered unlikely that conditions associated with the identified Brownfield Sites represent an environmental concern to the Subject Property.

New York Dry Cleaners Sites

Neither the Subject Property nor any adjoining properties were identified on the New York Dry Cleaners database.

EDR Manufactured Gas Plants (MGP) Sites

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination. Neither the Subject Property nor any adjoining properties were identified on the EDR Proprietary Manufactured Gas Plant Database.

DRAFT

EDR Historical Auto Station Sites
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, automobile repair, auto service station, service station, etc. The Subject Property was not identified on the EDR Historical Auto Stations database. However, the western adjoining property was identified on the EDR Historical Auto Stations database. According to the database listing, this property was occupied by Merit Gasoline Stations from 1999-2001; Amerada Hess Corp. from 2003-2009; and back to Merit Gasoline Stations from 2010-2012. This facility is cross-listed as a Registered Storage Tank, Leaking Storage Tank, and Spills site, and is further discussed in the corresponding section above.

EDR Historical Dry Cleaner Sites
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, laundry, laundromat, cleaning/laundry, wash and dry, etc. Neither the Subject Property nor any adjoining properties were identified on the EDR Historical Dry Cleaner site database.

Additional Regulatory Sites
Several other supplemental regulatory databases contained listings for sites within 1.0 mile of the Subject Property. However, the Subject Property was not listed on any of the databases, and the listed sites are not anticipated to have adversely impacted the environmental integrity of the Property based on factors such as the nature of their database listing, distance from the Property, topographic elevation relative to the Property, anticipated groundwater flow direction, and/or regulatory status.

4.1.3 Local Regulatory Agency Records

Local municipal offices consulted during the completion of this assessment included the City of New York Department of Buildings, Planning Department, Department of Environmental Protection, and Fire Department. EBI did not identify records of spills or releases of hazardous substances or petroleum products having occurred at the Subject Property.

City of New York Department of Buildings (NYCDOB)
EBI reviewed available online files regarding the Subject Property at the City of New York Department of Buildings website for information regarding past uses of the Subject Property. According to municipal records, the Subject Property includes the addresses 824 to 830 Metropolitan Avenue. A Certificate of Occupancy (CO) on file for the Subject Property, dated April 20, 1996, described the Subject Property as improved with a public parking lot with 100 spaces or less. No other COs were on file for the Subject Property. A demolition permit was issued for the Subject Property in 1961, presumably for the former two-story structures located on the Subject Property, as identified in historical resources discussed in Section 4.3. Copies of Building Department records are included in Appendix C of this report.

City of New York Planning Department
EBI reviewed available online files regarding the Subject Property at the City of New York Planning Department website. Review of the files revealed that the Subject Property is located within an area designated as C8-2 and R6B Commercial and Residential District. No areas of environmental concern were identified during the review of the Planning Department files.

City of New York Fire Department
EBI has submitted a written request to the Fire Department for information regarding the generation, transportation, storage, treatment, disposal, and/or spills or releases of hazardous substances or

DRAFT

petroleum products at the Subject Property, in accordance with the Freedom of Information Act (FOIA). As of the date of this report, EBI has not received a response to this inquiry. Upon receipt of the agency response, if the provided information has a material effect on the findings of this report, EBI will forward this information as an addendum to this report. If no response is received, or no material information is identified, our report will not be modified.

4.2 PHYSICAL SETTING

4.2.1 Topography

The Subject Property is located at an elevation of approximately 37 feet above mean sea level (msl). The topography of the Subject Property is relatively flat with no distinct slope. The Subject Property is located in a relatively flat area, and the general slope of the surrounding region is to the east-northeast (see Figure 2 - Locus Map, which depicts the location of the Subject Property on the Brooklyn, New York USGS 7.5 Minute Topographic Quadrangle).

4.2.2 Geology and Soils

No bedrock outcroppings were observed at the Subject Property. Near-surface geology in heavily developed areas such as the Subject Property and vicinity is considered "urban land" and is characterized by a non-homogeneous distribution of soil and fill types. Excavation and backfilling for building foundations, utility conduits, subway systems and other construction results in a varied subsurface profile. In this setting, estimation of local subsurface parameters such as permeability, moisture content, and organic fraction is not feasible without site-specific testing data.

The Subject Property is part of the Long Island Hydrogeologic System and characterized as Cretaceous and Pleistocene age unconsolidated sediments. The thickness of the unconsolidated sequence can vary greatly within the range of zero to approximately 1,300 feet below ground surface. Metamorphic bedrock beneath the unconsolidated sequence is of Precambrian and Paleozoic age. The overlying sediments make up the aquifer-bearing Raritan and Magothy Formations.

4.2.3 Hydrogeology and Hydrology

No natural surface water bodies were identified on or adjacent to the Subject Property. The nearest surface water bodies are the English Kills, located approximately 0.5 mile east of the Subject Property, and the East River, located over 1.4 miles west-southwest of the Subject Property.

Local groundwater gradient is typically expected to follow surface topography; therefore, groundwater flow near the Subject Property is expected to be to the east-northeast. However, based upon review of a regulatory database listing for the western adjoining gasoline station (as referenced in Section 4.1.2), groundwater at this property was determined to flow in a southwesterly direction toward Bushwick Avenue. Groundwater was encountered at depths ranging from 9.88 feet to 22.24 feet below grade.

4.3 HISTORICAL USE OF THE SUBJECT PROPERTY AND ADJOINING PROPERTIES

EBI attempted to determine the history of the Subject Property dating back to 1940 or first developed use. It should be noted that data failure occurred per Section 8.3.2.3 of ASTM Standard E 1527-13. The earliest available record reviewed was a Sanborn Fire Insurance Map dated 1888, which depicted the Subject Property as improved with small residential and commercial buildings fronting Metropolitan Avenue. These former structures were demolished in the early 1960s when the Subject Property was redeveloped into a parking lot. Based on the information obtained, the historical data gap identified is

DRAFT

not considered to have significantly impacted the ability to identify recognized environmental conditions and does not alter the conclusions of this report. The following table summarizes the historical use of the Subject Property and surrounding area.

HISTORICAL USE SUMMARY			
Period	**Historical Uses**		**Source(s)**
	Subject Property	**Surrounding Area**	
At least 1888 to Circa 1966	Two-story residential and commercial/retail buildings addressed as 824-830 Metropolitan Avenue	Primarily single-family and multi-family residential development, with limited commercial use	Aerial Photographs Fire Insurance Maps Topographic Maps City Directories Municipal Records
Circa 1966 to 1979	Parking lot and used car sales lot	Single-family and multi-family residential development; commercial development to the west	Aerial Photographs Fire Insurance Maps Topographic Maps City Directories Municipal Records
1979 to Present	Parking lot	Single-family and multi-family residential development; gasoline station to the west	Aerial Photographs Fire Insurance Maps Topographic Maps City Directories Municipal Records Personal Interviews

No environmentally significant conditions were identified on the Subject Property or surrounding properties during the historical review, except for the western adjoining gasoline station, which is further discussed in Section 4.1.2 of this report.

4.3.1 Aerial Photographs

Historical aerial photographs may be used to evaluate changes in land use and to identify visible areas of potential environmental concern. A search for historical aerial photographs depicting the Subject Property and vicinity was conducted by Environmental Data Resources, Inc. (EDR). Aerial photographs depicting the Subject Property were reviewed and are summarized in the following table. Copies of the aerial photographs are presented in Appendix F.

AERIAL PHOTOGRAPH SUMMARY		
Year	**Issues Noted**	**Observations**
1924, 1941, 1951, 1954, 1961	No	**Subject Property:** The Subject Property appears to be improved with several small structures on the northern and southern portions of the property. It should be noted that the scale of these aerial photographs precludes the distinct identification of structures and/or land uses on the Subject Property.
		Surrounding Area: The existing Metropolitan Avenue is visible to the north of the Subject Property. Surrounding properties to the north, south, east, and west appear to be improved with small structures, likely residential and/or commercial in use.
1966	No	**Subject Property:** The Subject Property appears to consist of vacant land. All former improvements appear to have been demolished.
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1961 photograph, with the exception of the western adjoining property, which appears to consist of vacant land, followed by a small commercial building.
1974	No	**Subject Property:** Conditions on the Subject Property appear to be similar to those depicted on the 1966 photograph. The Subject Property appears to consist of a dirt-

AERIAL PHOTOGRAPH SUMMARY		
Year	**Issues Noted**	**Observations**
		covered lot with no structures or other notable features.
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1966 photograph. The dirt-covered lot on the Subject Property appears to extend onto the west adjacent property.
1980	Yes	**Subject Property:** Conditions on the Subject Property appear to be similar to those depicted on the 1974 photograph; however, the lot appears to be utilized for parking.
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1974 photograph, with the exception of the western adjoining property. The former extension of the dirt-covered lot appears to have been combined with an additional lot to the west, and redeveloped with the existing gasoline station.
1984, 1991, 1994, 2006, 2009, 2011	Yes	**Subject Property:** Conditions on the Subject Property appear to be similar to those depicted on the 1980 photograph.
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1980 photograph.

4.3.2 Fire Insurance Maps

A search for historical fire insurance maps depicting the Subject Property and vicinity was conducted by EDR. Historical fire insurance maps depicting the Subject Property were reviewed and are summarized in the following table. Copies of the fire insurance maps are presented in Appendix F.

FIRE INSURANCE MAP SUMMARY		
Year	**Issues Noted**	**Observations**
1888	No	**Subject Property:** The Subject Property is depicted as improved with three small structures on the northern portion of the property, fronting Metropolitan Avenue. The structures are labeled as a store and two dwellings. A detached garage or shed is also depicted on the southern portion of the property.
		Surrounding Properties: Metropolitan Avenue is depicted to the north of the Subject Property. Surrounding properties to the north, east, and south are shown as residential dwellings. Stores are depicted to the west.
1907, 1933, 1951	No	**Subject Property:** Conditions on the Subject Property are similar to those as depicted on the 1888 map, with the addition of a small single-story structure on the southern portion of the property, labeled as occupied by a tailor. The structures on the Subject Property are addressed as 824, 828, 830, and 830 ½ Metropolitan Avenue.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1888 map.
1965	No	**Subject Property:** The Subject Property is depicted as a vacant parcel. All former structures appear to have been demolished.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1951 map, with the exception of the western adjoining property, which is shown as part of the vacant Subject Property parcel. Farther west of the vacant parcel is a small, single-story commercial building.
1968	No	**Subject Property:** Conditions on the Subject Property are similar to those as depicted on the 1965 map, with the addition of a small single-story office building on the southern portion of the property. The Subject Property is labeled as utilized for "Used Auto Sales", and carries over onto the western adjoining property.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1965 map. As noted above, the used auto sales on the Subject Property

DRAFT

FIRE INSURANCE MAP SUMMARY		
Year	**Issues Noted**	**Observations**
		appears to extend onto the western adjoining property.
1977, 1979	No	**Subject Property:** Conditions on the Subject Property are similar to those as depicted on the 1968 map; however, the small single-story office building is no longer shown on the southern portion of the property.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1968 map.
1980	Yes	**Subject Property:** Conditions on the Subject Property are similar to those as depicted on the 1979 map. The Subject Property is labeled as a parking lot.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1979 map, with the exception of the western adjoining property, which appears to have been divided from the Subject Property, and combined with the adjoining property farther west. This new parcel is shown as developed with the existing gasoline filling station.
1981, 1982, 1986-1995, 2001-2007	Yes	**Subject Property:** Conditions on the Subject Property are similar to those as depicted on the 1980 map.
		Surrounding Properties: Conditions on the surrounding properties are similar to those as depicted on the 1980 map.

4.3.3 Topographic Maps

Historical topographic maps provide information related to physical land configuration such as elevation, ground slope, surface water and other features. While most buildings in densely developed urban centers are not depicted, topographic maps typically show structures equal to or larger than the size of a single-family residence in rural areas. Other notable features such as woods, pipelines, municipal boundaries, and areas of filled land are often marked on topographic maps.

A search for historical topographic maps depicting the Subject Property and vicinity was conducted by EDR. Historical topographic maps depicting the Subject Property were reviewed and are summarized in the following table. Copies of the topographic maps are presented in Appendix F.

TOPOGRAPHIC MAP SUMMARY		
Year	**Issues Noted**	**Observations**
1900, 1924	No	**Subject Property:** No visible structures or other notable features are depicted on the Subject Property. The Subject Property appears to be located within an urban development.
		Surrounding Properties: No visible structures or other notable features are depicted on the surrounding properties. A roadway resembling Metropolitan Avenue is visible to the north of the Subject Property.
1947	No	**Subject Property:** The Subject Property appears to be improved; however, distinct structures are not identifiable.
		Surrounding Properties: The surrounding properties appear to be improved with structures, likely depicting commercial and residential development; however, distinct structures are not identifiable.
1956, 1967, 1979, 1995	No	**Subject Property:** The Subject Property is shaded to represent urban development; no distinct structures or other notable features are depicted.
		Surrounding Properties: The surrounding properties are shaded to represent urban development; no distinct structures or other notable features are depicted.

DRAFT

4.3.4 Street Directories

Street directories are commercial publications containing names and addresses, and in many cases, occupations of the occupants of a particular community. The directories may also contain information pertaining to business processes conducted within a community. A search for historical street directories was conducted by EDR. It is noted that the Subject Property includes municipal addresses 824-830 Metropolitan Avenue. Historical street directories were reviewed and are summarized in the following table. Copies of the street directories are presented in Appendix F.

STREET DIRECTORY SUMMARY		
Year	**Issues Noted**	**Occupants**
1928	No	Nassau Heights Hardware Co. (828 Metropolitan Ave.)
1940	No	Bry Julius candy mfr (824 Metropolitan Ave.)
1960	No	Doran Patk (826 Metropolitan Ave.)
1965-2013	No	Subject Property is not listed in research source.

4.3.5 Recorded Land Title Records

Land title records provide information on previous ownership of a property. Typically, deeds signifying transfer of a land parcel are recorded in county files and can be researched to determine the identity of past owners. A "chain of title" is a continuous record of ownership for a specific parcel. A 50-year chain of title search was not included in the scope of work for this assessment.

4.3.6 Property Tax Records

The property card for the Subject Property was obtained at the City of New York Department of Finance. The property card identifies the Subject Property as Block 2916, Lot 14, and the current owner as Zois Sachtouris, which acquired the Subject Property in 2014. Copies of the property tax records are presented in Appendix C.

4.3.7 Environmental Liens and Activity and Use Limitations

A search for Environmental Liens and Activity and Use Limitations was not included in the scope of this assessment.

4.3.8 Previous Environmental Reports

EBI was not provided with or made aware of previous environmental assessments or other documentation regarding environmental investigations performed for the Subject Property. EBI did not identify previous environmental reports for the Subject Property at local agencies or other sources contacted during this assessment.

4.3.9 Other Historical Records and Interviews

Mr. Zois Sachtouris, the Subject Property owner, was interviewed to obtain information regarding the history of the Subject Property. Mr. Sachtouris reported that he has been familiar with the Subject Property for over 10 years and that the Subject Property has been owned by his family since approximately the 1990s. Mr. Sachtouris reported that the Subject Property has been historically utilized as a parking lot and is currently unused, beyond storage purposes.

DRAFT

5.0 SUBJECT PROPERTY RECONNAISSANCE

The Subject Property reconnaissance was conducted by Mr. Jon Hickey, EBI Field Assessor, on July 27, 2015. Mr. Hickey was unaccompanied during the site reconnaissance, but interviewed Mr. Zois Sachtouris, the Subject Property owner, prior to the site reconnaissance.

5.1 METHODOLOGY AND LIMITING CONDITIONS

The Subject Property reconnaissance consisted of visual and/or physical observations of the Subject Property and improvements, adjoining properties as viewed from the Subject Property boundaries, and the surrounding area based on visual observations made from adjacent public thoroughfares. Unimproved portions of the Subject Property were observed along the perimeter and in a general grid pattern in safely accessible areas.

At the time of the survey, the weather was sunny and approximately 80° Fahrenheit. During the survey, representative site areas were observed. There were no significant portions of the Subject Property that were inaccessible or excluded from this survey.

5.2 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS

5.2.1 Hazardous Substances and Petroleum Products (Identified Uses)

EBI did not observe evidence of notable hazardous substances or petroleum products in connection with identified uses observed at the Subject Property. However, several unidentified substances containers were observed, and are further discussed in Section 5.2.3 below.

5.2.2 Hazardous Substances and Petroleum Products (Unidentified Uses)

EBI did not observe evidence of hazardous substance or petroleum products containers at the Subject Property that were not in connection with identified uses, except for several unidentified substances containers that are further discussed in Section 5.2.3 below.

5.2.3 Unidentified Substances Containers

EBI observed seven discarded 55-gallon drums and numerous 5-gallon containers located on the northern, western, and eastern portions of the vacant parking lot of the Subject Property. The drums were observed to be rusted and in fair condition. The drums and 5-gallon containers appeared to be empty. No obvious staining or other evidence of a release of hazardous substances or petroleum products was observed in the vicinity of the drums and 5-gallon containers.

EBI also observed five discarded 30-gallon drums and one 55-gallon drum located on the northern and western portions of the vacant parking lot of the Subject Property. These drums were observed to be rusted and in fair to poor condition. The drums appeared to be partially full of unknown substances. No staining or other evidence of a release of hazardous substances or petroleum products was observed in the vicinity of the drums. However, it is noted that the asphalt pavement throughout the Subject Property was noted to be in poor condition, with cracks and penetrations that may serve as potential pathways to the subsurface in the event of a release.

DRAFT

5.3 WASTE GENERATION, STORAGE, AND DISPOSAL

At the time of assessment, the Subject Property consisted of a vacant parking lot. As such, no waste streams were identified at the Subject Property. Discarded debris observed at the Subject Property is further discussed in Section 5.6.

5.4 UNDERGROUND STORAGE TANKS (USTS) & ABOVEGROUND STORAGE TANKS (ASTS)

5.4.1 Existing Storage Tanks

Based upon site reconnaissance, interviews, and a review of state and local records, EBI identified no evidence of existing USTs or ASTs located at the Subject Property.

5.4.2 Former Storage Tanks

Based upon site reconnaissance, interviews, and a review of state and local records, EBI identified no evidence of former USTs or ASTs located at the Subject Property.

5.5 OIL-CONTAINING EQUIPMENT AND POLYCHLORINATED BIPHENYLS (PCBS)

Polychlorinated biphenyls (PCBs) are a chemical component of many dielectric fluids, heat transfer fluids, hydraulic fluids, lubricating oils, paints, or coatings manufactured prior to July 2, 1979. Equipment that may potentially contain PCBs includes electrical equipment such as transformers or capacitors or hydraulically operated equipment, such as elevators, compaction equipment, or manufacturing equipment. The manufacture and distribution in commerce of PCBs was banned for use in 1979 by the United States Congress, which enacted the Toxic Substance and Control Act (TSCA). In accordance with *US Code of Federal Regulations Title 40 - Protection of Environment, Chapter I - Environmental Protection Agency, Subchapter R - Toxic Substance Control Act (TSCA), Part 761 - Polychlorinated Biphenyls (PCBs) Manufacturing, Processing, Distribution in Commerce, and Use Prohibitions*, the owner of a transformer or other PCB-containing equipment is responsible for equipment maintenance and remediation in the event of a leak or release.

Based upon the absence of transformers, hydraulic equipment or other oil-containing equipment, no potential PCB-containing equipment was identified at the Subject Property.

5.6 ADDITIONAL SITE CONDITIONS

The following is a summary of visual and/or physical observations of the Subject Property on the day of the site visit. Photographs of pertinent Subject Property features are presented in Appendix A.

ADDITIONAL SITE CONDITIONS	
Condition	**Identified**
Interior Drains, Trenches, or Sumps	No
Interior Stains or Corrosion	No
Unusual Odors	No
Interior Pools of Liquid	No
Stained Soil or Pavement	No
Stressed Vegetation	No
Indications of Solid Waste Disposal	**Yes**
Exterior Pits, Ponds, or Lagoons	No
Wastewater or Stormwater Discharge/Disposal	No

ADDITIONAL SITE CONDITIONS	
Condition	**Identified**
Oil-Water Separators or Clarifiers	No
Septic Systems or Cesspools	No
Wells (Drinking Water Wells, Monitoring Wells, Agricultural/Irrigation Wells, or Process Water Wells)	No
Petroleum or Natural Gas Pipelines/Easements	No

EBI observed several piles of discarded debris, trash, and other solid waste, including concrete, plywood, toilets, bathtubs, tires, and various objects located on the eastern, southern, and western portions of the vacant parking lot of the Subject Property. The source of this debris is unknown. As noted in Section 5.2.3, several empty 55-gallon drums and 5-gallon containers were observed through the debris piles. The presence of this discarded debris is considered a *de minimis condition.*

DRAFT

6.0 INTERVIEWS

The following persons were interviewed to obtain information regarding recognized environmental conditions in connection with the property. Additionally, a Pre-Survey Questionnaire was forwarded to the designated Subject Property contact. The Pre-Survey Questionnaire has been completed and returned to our offices. The information requested in the Pre-Survey Questionnaire is intended to assist in gathering information that may be material to identifying recognized environmental conditions in connection with the Subject Property. The Pre-Survey Questionnaire and any accompanying documentation is presented in Appendix C.

INTERVIEWS			
Contact / Affiliation	**Date of Communication**	**Years Associated with Subject Property**	**Telephone No.**
Mr. Zois Sachtouris Subject Property Owner	07/27/2015	10+	(917) 364-3872
Mr. Alex Rodriguez Project Manager A.R. Construction Management Corp.	07/27/2015	Not Reported	(917) 842-9505
New York City Department of Buildings	07/27/2015	N/A	www.nyc.gov/html/dob
New York City Department of Planning	07/27/2015	N/A	www.nyc.gov/html/dcp
New York City Department of Finance	07/27/2015	N/A	www.nyc.gov/html/dof

Pertinent information from the interviews is presented in applicable sections of this report.

DRAFT

7.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM PRACTICE E 1527-13

The following sections address environmental issues or conditions at the Subject Property that parties may wish to assess in connection with commercial real estate that are outside the scope of ASTM Practice E 1527-13 (non-scope considerations).

7.1 ASBESTOS-CONTAINING MATERIAL (ACM)

Asbestos is a term used to describe a group of six naturally occurring crystalline fiber minerals. Asbestos has excellent thermal stability, a high degree of tensile strength, and has been used extensively in the textile, insulation, and building industries, particularly as a component in fireproofing, decorative coatings, insulation materials, and as reinforcement for plaster binders in building products. Asbestos-containing building materials are generally classified as friable or non-friable. Friable materials are those which can be crumbled, pulverized, or reduced to powder by hand pressure, or by normal use or maintenance can be expected to emit asbestos fibers into the air. Non-friable ACM is a potential concern if it is damaged by maintenance work, demolition, or other activities, at which time it may be considered friable.

The Subject Property consists of an asphalt-paved surface parking lot. Based upon the absence of Subject Property improvements and in accordance with the scope of work for this assessment, EBI did not conduct a survey for the presence of ACM.

7.2 RADON

Radon is a naturally-occurring, colorless and odorless radioactive gas that is generated primarily in granitic rocks. The United States Surgeon General has published information that radon is a cause of lung cancer. Radon usually enters a building through openings in the foundation, and therefore is a potential health concern to residents of the lowest level of a building with inadequate ventilation.

The EPA Map of Radon Zones indicates that Kings County is located within a Zone 3 radon area. Zone 3 is defined as an area that has a low potential for radon gas, with a predicted average indoor radon screening level less than 2.0 picoCuries per liter (pCi/L). The EPA recommended Action Level for radon is 4.0 pCi/L.

The Subject Property consists of an asphalt-paved surface parking lot. Based upon the absence of Subject Property improvements, the low propensity radon zone, and in accordance with the scope of work for this assessment, EBI did not conduct a limited short-term radon screening at the Subject Property.

7.3 LEAD-BASED PAINT (LBP)

Use of lead in household paint was banned by the U.S. Environmental Protection Agency (EPA) effective January 1, 1978. The EPA and the U.S. Department of Housing and Urban Development (HUD) consider lead-based paint as containing a lead concentration equal to or greater than 1.0 milligram per square centimeter (mg/cm^2) or 0.5% lead by weight, as defined by Title X of the 1992 Housing and Community Development Act.

The Subject Property consists of an asphalt-paved surface parking lot. Based upon the absence of Subject Property improvements and in accordance with the scope of work of this assessment, a lead-based paint (LBP) survey was not conducted at the Subject Property.

DRAFT

7.4 LEAD IN DRINKING WATER

Lead has historically been used in pipes, solder, and brass fixtures used in water distribution systems and building plumbing systems. In 1986, EPA banned the use of lead at concentrations exceeding 0.2% lead in solder and 8% lead in other plumbing materials. Lead in drinking water results primarily from corrosion of lead containing materials in service lines or from corrosion of lead containing materials in building plumbing systems such as lead solder, brass, bronze, and other lead containing alloys. The EPA Action Level for lead in public drinking water supplies is 0.015 parts per million (ppm) or 0.015 milligrams per liter (mg/L).

Municipal water service is provided to the Subject Property by the New York City Department of Environmental Protection (NYCDEP). The source of potable water for the City includes a network of 19 surface water reservoirs and 3 lakes within a 1,972 square-mile watershed that extends approximately 125 miles north and west of New York City. According to information published on the NYCDEP website, http://www.nyc.gov/html/dep/html/wsstate.html, domestic water for the City meets the water quality standards as established by state and federal authorities. Lead in the domestic water supply is reportedly less than the method detection limit. Based upon the existing municipal water service and in accordance with the scope of work for this assessment, EBI did not conduct lead-in-drinking water sampling at the Subject Property.

7.5 VAPOR MIGRATION

EBI conducted a vapor migration screening survey of the Subject Property. EBI's site observations and review of the environmental database report (cited in Section 4.1) did not identify any conditions on the Subject Property or on adjoining properties that would indicate a REC relative to vapor migration exists at the Subject Property, with the exception of the western adjoining gasoline station. As discussed in Section 4.1.2, several USTs have been removed from this adjoining property, and soil and groundwater contamination was identified. The contamination was remediated between 1995 and 2013, and regulatory closure was granted in 2013. Some residual contamination was left in place at the western adjoining gasoline station site at the time of case closure. Although EBI cannot completely dismiss the potential for impacts to the Subject Property in the absence of a subsurface investigation, based upon the reported remediation to the satisfaction of the NYSDEC, the recent regulatory closure, and the downgradient location relative to the Subject Property, further investigation at the Subject Property does not appear warranted at this time. However, it would be prudent that a vapor barrier be installed beneath any proposed building foundation on the Subject Property at the time of construction to mitigate the potential for vapor migration in connection with the adjoining gasoline station site.

This vapor migration screening was conducted in accordance with ASTM E1527-13 and is not intended to satisfy the requirements of ASTM E2600-10. The scope of this screening was limited to visual observations of review of the environmental database report and did not include the collection and laboratory analysis of air samples to confirm the presence of airborne contaminants by vapor intrusion.

DRAFT

8.0 FINDINGS AND OPINIONS

EBI has performed this Phase I Environmental Site Assessment of the Subject Property in conformance with the scope and limitations of ASTM Standard E 1527-13. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report. This assessment has identified no evidence of *recognized environmental conditions (RECs)* in connection with the Subject Property.

However, the following notable finding and *de minimis condition* were identified:

- The Subject Property is bound to the west by a gasoline station occupied by Speedway Gas (810 Metropolitan Avenue). Historical records reviewed indicate that the gasoline station has operated at this site since 1979. This gasoline station, identified as Merit Metropolitan, was listed on the New York Spills database. According to the database listing, petroleum odors were encountered during the removal of several gasoline and diesel underground storage tanks (USTs) in 1995. The spill case was reported to the New York State Department of Environmental Conservation (NYSDEC) on June 5, 1995 under Case No. 9502757. Preliminary groundwater monitoring in 2005 revealed elevated levels of benzene, toluene, ethylbenzene, and xylenes (BTEX) and methyl tertiary-butyl ether (MTBE). A soil vapor extraction and air sparging (SVE/AS) system was installed in 2006 to pump and treat the contaminated groundwater. Oxygen Release Compound (ORC) socks were also installed in several monitoring wells in 2006. Multiple SVE/AS events were completed between 2006 and 2007, and subsequent groundwater monitoring revealed a significant decrease in BTEX and MTBE concentrations. A request for closure was submitted in 2007, but was denied by the NYSDEC as further soil and groundwater delineation was required. Downgradient monitoring wells were proposed to be installed in the sidewalk along Bushwick Avenue; however, delays were encountered due to the presence of the New York City subway system beneath Bushwick Avenue. Monitoring wells were eventually installed in 2012, and very low concentrations of BTEX and MTBE were detected. A second request for closure was submitted in 2012, but was denied by the NYSDEC as residual contaminated soil required further delineation and/or remediation. The release case was revisited by the NYSDEC at the Regional Spill Engineers meeting in 2013, and it was determined that soil exceedances observed were moderate and further excavation was not warranted, and that spill closure was warranted due to the following factors:

  - Clean downgradient monitoring wells for numerous years;
  - Age of spill and fact that monitoring wells have shown no increase in groundwater contamination for numerous years, and as such there is no likelihood for downward migration of soil contamination through the soil column to the water table;
  - Excavation of UST systems and large amount of contaminated soil removed from site;
  - Spills Database has an institutional control to account for possible future changes in site use as none reported to date; and,
  - Addition of soil contamination notification in Spill Closure Letter.

  The spill case (Case No. 9502757) was granted closure on May 6, 2013. Since residual contamination was left in place at the western adjoining gasoline station site at the time of case closure, EBI cannot completely dismiss the potential for impacts to the Subject Property in the absence of a subsurface investigation. However, based upon the reported remediation to the satisfaction of the NYSDEC, the recent regulatory closure, and the downgradient location relative to the Subject Property, further investigation at the Subject Property does not appear warranted at this time. However, in the event that impacted soil is encountered during future redevelopment activities conducted at the Subject Property, the oversight of the subsurface activities should be

DRAFT

conducted by an environmental professional and any impacted soil be handled/disposed in accordance with the applicable regulatory requirements. If dewatering is required for any future construction, testing should be performed to ensure that the groundwater would meet New York City Department of Environmental Protection (NYCDEP) sewer discharge requirements. If necessary, the water should be pretreated prior to discharge to the City's sewer system, as required by NYCDEP permit/approval requirements. EBI also notes that it would be prudent that a vapor barrier be installed beneath any proposed building foundation on the Subject Property at the time of construction to mitigate the potential for vapor migration in connection with the adjoining gasoline station site.

- EBI observed several piles of discarded debris, trash, and other solid waste, including concrete, plywood, toilets, bathtubs, tires, and various objects located on the eastern, southern, and western portions of the vacant parking lot of the Subject Property. The source of this debris is unknown. EBI also observed seven discarded 55-gallon drums and numerous 5-gallon containers located on the northern, western, and eastern portions of the vacant parking lot of the Subject Property. The drums were observed to be rusted and in fair condition. The drums and 5-gallon containers appeared to be empty. Lastly, EBI observed five discarded 30-gallon drums and one 55-gallon drum located on the northern and western portions of the vacant parking lot of the Subject Property. These drums were observed to be rusted and in fair to poor condition. The drums appeared to be partially full of unknown substances. No staining or other evidence of a release of hazardous substances or petroleum products was observed in the vicinity of the drums and 5-gallon containers. However, it is noted that the asphalt pavement throughout the Subject Property was observed to be in poor condition, with cracks and penetrations that may serve as potential pathways to the subsurface in the event of a release. The presence of the discarded debris and drums is considered a *de minimis condition*.

DRAFT

9.0 RECOMMENDATIONS

Based upon the findings of this investigation, EBI offers the following recommendations:

- EBI recommends that the contents of the six unlabeled and discarded 30-gallon and 55-gallon drums located on the northern and western portions of the Subject Property be characterized and properly disposed of in accordance with applicable state and local requirements. Estimated cost: $2,500.

- EBI recommends the discarded debris, trash, and other solid waste, including concrete, plywood, toilets, bathtubs, tires, various objects, empty drums, and 5-gallon containers located on the eastern, southern, and western portions of the Subject Property, be disposed of by a licensed waste hauler. Estimated cost: Action Item.

DRAFT

10.0 REFERENCES

PHASE I ENVIRONMENTAL SITE ASSESSMENT REFERENCES

ASTM Designation E 1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process

Department of Environmental Protection Priority Radon Map, On-line:
http://www.epa.gov/radon/zonemap/newyork.htm

Environmental Data Resources, Inc., The EDR Certified Sanborn Map Report; Inquiry Number 4357835.3, dated July 17, 2015

Environmental Data Resources, Inc., The EDR City Directory Abstract; Inquiry Number 4357835.6, dated July 17, 2015

Environmental Data Resources, Inc., The EDR Historical Aerial Photographs report; Inquiry Number 4357835.5, dated July 20, 2015

Environmental Data Resources, Inc., The EDR Historical Topographic Map report; Inquiry Number 4357835.4, dated July 17, 2015

Environmental Data Resources, Inc., The EDR Radius Report with GeoCheck®; Inquiry Number 4357835.2r, dated July 17, 2015

USGS Topographic Map, *Brooklyn, New York* Quadrangle, 7.5-Minute Series, dated 1980

Web Soil Survey, NRCS, U.S. Department of Agriculture, On-line:
http://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx

New York City Municipal Data - Refer to Section 6.0

DRAFT

APPENDIX A

PHOTOGRAPHS

DRAFT

1.	Street view of the Subject Property, looking southeast.

2.	View of the access gate on the north side of the Subject Property, along Metropolitan Avenue.

3.	Overview of the Subject Property parking lot, looking south.

4.	Overview of the Subject Property parking lot, looking north.

5.	55-gallon drum full of an unknown substance located on the northern portion of the property.

6.	30-gallon drums full of unknown substances located on the western portion of the property.

DRAFT

7.	30-gallon drums full of unknown substances located on the western portion of the property.

8.	Empty 55-gallon drum located on the northern portion of the property.

9.	Empty 55-gallon drums located on the western portion of the property.

10.	Piles of debris located on the eastern portion of the property.

11.	Piles of debris located on the southern portion of the property.

12.	Piles of debris (hot water tank) located on the western portion of the property.

DRAFT

13.	Western adjoining gasoline station, looking easterly.

14.	UST locations on the western adjoining gasoline station, looking easterly toward Subject Property.

15.	View of border between Subject Property and western adjoining gasoline station.

16.	Adjoining residential development to the north, across Metropolitan Avenue.

17.	Adjoining residential development to the east.

18.	Adjoining residential development to the south, viewed from Devoe Street.

APPENDIX B

FIGURES

DRAFT



Legend

- Project Site
- Site Radius at ¼ and ½ mile

Source: Selected data from ESRI, EBI & USGS

N

Date: 7/21/2015

Figure 1: Site Location Map

0 500 1,000 2,000 3,000 Feet

(BLOCK 2916, LOT 14) 824 METROPOLITAN AVE
824 METROPOLITAN AVE
BROOKLYN, NY 10028

PN: 1115005479

EBI Consulting
environmental | engineering | due diligence



Legend

- ★ Project Site
- Site Radius at ¼ and ½ mile

Source: Selected data from ESRI, EBI & USGS

N

USGS 24K Quad: Brooklyn, NY 1980

Date: 7/21/2015

Figure 2 - Topographic Map

0 500 1,000 2,000 3,000 Feet

(BLOCK 2916, LOT 14) 824 METROPOLITAN AVE
824 METROPOLITAN AVE
BROOKLYN, NY 10028

PN: 1115005479

EBI Consulting
environmental | engineering | due diligence



FIGURE 3 – SITE PLAN

- 55-gallon drum, unidentified contents
- 30-gallon drums, unidentified contents
- 55-gallon drums, empty

N

Not to scale



FIGURE 4 – TAX MAP

Not to scale



Surveyed: July 9, 2015

PAWEL KOPCINSKI
NEW YORK LICENSE 050881
1317 PARK AVENUE
NEW HYDE PARK, NY 11040
Tel: (516)341 8201

This is to certify that there are no visible streams or natural watercourses in the property except as shown on the survey.

Unauthorized alteration or addition to this survey is a violation of Section 7209, of the New York State Educational Law.

Copies of this survey not bearing the Land Surveyor's inked Seal or Embossed Seal shall not be considered to be a valid true copy.

Certifications indicated hereon shall run only to the person for whom the survey is prepared and on his behalf to the Title Company, Governmental Agency and lending institution listed hereon, and to the Assignees of the lending institution. Certifications are not transferable to additional institutions or subsequent owners.

AREA 5,000.00 SQ.FT.

BLOCK 2916 LOT 14

BOROUGH OF BROOKLYN COUNTY OF KINGS STATE OF NEW YORK

APPENDIX C

PRE-SURVEY QUESTIONNAIRE AND OTHER RELEVANT DOCUMENTATION

DRAFT

ESA AAI USER QUESTIONNAIRE (ASTM E1527)

Subject Property Name: 824 Metropolitan EBI Project #: TBD

Address: 824 Metropolitan Ave, Brooklyn, NY

1. Are you aware of any environmental cleanup liens against the Subject Property that are filed or recorded under federal, tribal, state or local law?

   Yes / (No) Unknown / Not Applicable

   If yes, please attach a copy.

2. Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

   Yes / (No) / Unknown / Not Applicable

   If yes, please attach a copy.

3. As the user of this ESA do you have any specialized knowledge or experience related to the Subject Property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the Subject Property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business? Or, do you have documentation (i.e., Phase I ESAs, Phase II subsurface investigations, Tank Removal reports, remedial reports, asbestos sampling and/or abatement reports, lead-based paint sampling and/or abatement reports, etc.) for the Subject Property that may be relevant to the Phase I ESA?

   Yes / (No) / Unknown / Not Applicable

   Comments: Has been empty since Mid 90's

4. Does the purchase price being paid for this Subject Property reasonably reflect the fair market value of the Subject Property?

   Yes / No / Unknown / (Not Applicable)

   If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the Subject Property?

   Yes / No

   Comments: Have owned since Mid 90's

ESA AAI USER QUESTIONNAIRE (ASTM E1527)

5. Are you aware of commonly known or reasonably ascertainable information about the Subject Property that would help the environmental professional to identify conditions indicative of release or threatened releases? For example, as user,

   a. Do you know the past uses of the Subject Property?
   b. Do you know the specific chemicals that are present or once were present at the Subject Property?
   c. Do you know of spills or other chemical releases that have taken place at the Subject Property?
   d. Do you know of any environmental cleanups that have taken place at the Subject Property?

   Comments: N/A

   Please attach copies of previous environmental reports prepared for the Subject Property.

6. As the user of this ESA, based on your knowledge and experience related to the Subject Property are there any obvious indicators that point to the presence or likely presence of contamination at the Subject Property?

   Yes / (No) / Unknown / Not Applicable

   Comments: _____

Please be sure to attach copies of documentation, as available.

Completed by:

Alex Rodriguez
Name

President
Title

AR Construction Mgmt.
Company Name

7-16-15
Date

EBI Consulting
environmental | engineering | due diligence

CORPORATE

REGIONAL OFFICE
TEL. 717-428-0401 FAX 781-425-3623
nequestionnaires@ebiconsulting.com

FACSIMILE TRANSMITTAL SHEET

To:	From:	Date:
Alex Rodriguez	Kim Holland Project Coordinator	July 27, 2015
Fax number or email address:	**Total number of pages including cover:**	
armgmtcorp@gmail.com	4	

☒ Please complete and return

Email to nequestionnaires@ebiconsulting.com
Or Fax to 781-425-3623

☒ Please Reply

☒ Urgent

Re: Environmental Site Assessment Questionnaire for property known as or located at

824 METROPOLITAN AVE

We have been requested by:	Subject:	EBI Project #:
A.R. Construction Management Corp.	To complete an Environmental survey of the above mentioned property.	1115005479

1. Please read these instructions and those on the following page carefully.
2. Please assemble this original questionnaire and one copy of pertinent property documents, and forward all information to the site or the site contact for the Engineer and/or Scientist to use during the site visit. This documentation will be included in our report.
3. Please fill out this questionnaire to the best of your knowledge and email or fax it back to us within three business days.
4. The Scientist will contact you directly to schedule the site visit.
5. This information is extremely time sensitive and necessary to provide your lender with accurate and timely report.

EBI Consulting
environmental | engineering | due diligence

Please fill out and sign this questionnaire to the best of your knowledge for the Scientist's site visit. Email to Kim Holland at nequestionnaires@ebiconsulting.com or fax to781-425-3623, for our report files, and keep the original to provide to the Scientist.

6.

Subject Property Name: 824 Metropolitan Ave EBI Project #: 1115005479

Address: 824 Metropolitan Ave Brooklyn NY

Subject Property Owner: Zois sachtouris Purchase Date: 2002

On-Site Property Contact: Zois sachtouris Telephone: 9173643872

Fax: Email: zis77@hotmail.com

Zois Sachtouris owner

Your Name and title Signature Date

Additional plans and documentation (see page 4) must be forwarded to the site for the Scientist during the survey. For questions not applicable please respond "N/A." Attach additional pages if necessary. This questionnaire and your responses will be included as an exhibit in the Environmental report. Accurate and full completion is critical to a timely completion of our reports, and timely loan closing.

LOCAL JURISDICTIONAL INFORMATION

1. What is the property ID #, Lot and Block, or Township/Range ID #? Brooklyn 2916 14
2. What is the legal Municipality or County that has jurisdiction over the property? Kings county
3. What is the assessors file ID number and tax file ID number if available?

PROPERTY INFORMATION

4. What is the size of the subject property lot or lots, in acres? 5000 ft.^{2}
5. How many buildings comprise the subject property? 0
   a. If the property is a mall or large retail center, please confirm and list ownership of each building.
6. What is the gross and net rentable square footage of the building(s)?
7. What is the date of construction of the building(s)? When was the building(s) first occupied?
8. How many tenant spaces or apartments are at the Subject Property?
9. Please list, to the best of your knowledge, any structural, water infiltration, mold, roof, plumbing, HVAC, Fire Alarm or electrical deficiencies or problems.
10. Please list any deficiencies noted during any Building, Fire or Health Department inspections in the last three years.
11. Please list the following utility providers:
    Electricity:
    Water:
    Storm Drainage:
    Sanitary Sewer:
    Natural Gas or Oil:
    Trash Hauler: and, Frequency of Pick-ups:
12. Please attach a brief history of the property.

ENVIRONMENTAL SITE ASSESSMENT PRE-SURVEY QUESTIONNAIRE

1. Describe the current uses of the property noting tenant names and oil/chemical usage. None empty lot

2. Describe the past uses of the property noting tenant names and oil/chemical usage. None empty lot

3. (Y) (N) Has a previous environmental site assessment report been prepared for the property? If yes, for what reason? Can EBI have a copy? Unknown

4. (Y) (N) Has a subsurface investigation (Phase II) ever been conducted on the property, including soil sampling, groundwater sampling, or installation of groundwater monitoring wells? If yes, for what reason? What were the results? Can EBI have a copy of the report? Are there any groundwater monitoring wells currently located on the property?

5. (Y) (N) Has contamination been identified at the Subject Property? Describe the nature of the contamination (i.e., source, media impacted, location, sampling, cleanup activities, regulatory status, etc.). Can EBI have copies of related documentation?

6. (Y) (N) Has a spill or surficial release occurred at the Subject Property? Describe the nature of the spill/surficial release (i.e., source, location, response/cleanup actions, regulatory status, etc.). Can EBI have copies of related documentation?

7. (Y) (N) Is the Subject Property listed with the USEPA and/or the state environmental regulatory agency as a contaminated site? If yes, please describe. Can EBI have copies of related documentation?

8. (Y) (N) Has there ever been previous sampling for Asbestos, Lead-Based Paint, Lead in Water, or Radon? If yes, please describe. Can EBI have copies of related documentation?

9. (Y) (N) Has there been any Asbestos or Lead-Based Paint abatement or Radon mitigation conducted at the Subject Property? Are there Asbestos and/or Lead-Based Paint Operations and Maintenance Plans for the Subject Property? If yes, please describe. Can EBI have copies of related documentation?

10. (Y) (N) Any known environmental liens, deed restrictions, or use limitations for the Property? If yes, please describe. Can EBI have copies of related documentation?

11. (Y) (N) Any permitted or regulated activities (Hazardous waste generator, air) on the Property? If yes, please describe.

12. (Y) (N) Are there any transformers or other electrical equipment, which may contain PCBs? If yes, please describe. Where are they? Who owns the transformer(s)? Who services them?

13. (Y) (N) Has an industrial or manufacturing operation, gas station, motor repair facility, commercial printing facility, dry cleaners, photo-developing laboratory, junk yard, landfill or waste, treatment, storage, disposal processing or recycling facility ever been located at or adjacent to the property? If yes, please describe.

14. (Y) (N) Are there any discarded drums, barrels or containers, construction debris, damaged or discarded automobile or industrial batteries, or pesticides, paints or other chemicals in individual containers or drums of greater than five gallons or fifty gallons in aggregate located on the property? If yes, please describe.

15. (Y) (N) Have there ever been any waste storage or treatment lagoons, pits, ponds, or surface impoundments on the property? If yes, please describe.

16. (Y) (N) Does the property have floor drains not discharging to a sewer? Septic System? If yes, please describe.

17. (Y) (N) Are there currently aboveground or underground storage tanks at the property? If yes, complete table.

Type of Tank	Size	Content	Installation Date	Spill/Leak Detection? Y or N
Above or Underground	gal			
Above or Underground	gal			
Above or Underground	gal			
Above or Underground	gal			

18. Are you aware of any information to indicate that the Subject Property was sold for substantially below its fair market value? If so, please provide an explanation: Unknown

19. Additional comments and/or pertinent information relevant to this Phase I ESA: Unknown

DOCUMENT AND INFORMATION CHECKLIST

Please provide the following information (as much as possible in electronic format) so the Scientist can proceed with the survey of the property.

A. Plans	B. Municipal Documents	C. Additional Information
▪ ALTA Survey or Site Plan ▪ Reduced scale Site and Building Plans	▪ Certificate of Occupancy ▪ Building Permit ▪ Copy of tax cards ▪ UST/AST Registrations	▪ Tenant Rent Roll ▪ Historical Uses ▪ Previous Due Diligence Reports ▪ Copy of most Recent Appraisal

EBI ACCESS REQUIREMENTS

At the time of the site visit the Consultant is required to gain access to <u>all</u> areas of the property. This includes:

- All building interiors, including as applicable, common areas, lobbies, a representative sampling of offices, retail spaces, manufacturing or assembly areas, or apartments, community rooms, exercise rooms, pool areas, storage rooms, attics and basements, garages.
- All building perimeters
- All site amenities
- All building roofs, unless pitched asphalt shingles. This may require you to obtain and provide a ladder.
- All mechanical, electric, sprinkler, HVAC, utility, service, elevator, storage and equipment rooms

NYCityMap

MASPETH AV
morial
Gore
METROPO
BUSHWICK AV
0
50
100
feet
Copyright 2015 The City of New York

BROOKLYN Block: 2916 Lot: 14

- Building & Property Information

Borough: BROOKLYN **Block:** 2916 **Lot:** 14
Police Precinct: 90
Owner: JOHN BOUZAS

Address: 824 METROPOLITAN AVENUE 11211
Lot Area: 5000 sf
Lot Frontage: 50' **Lot Depth:** 100
Year Built: unknown
Number of Buildings: 0
Number of Floors: 0
Gross Floor Area: 0 sf (estimated)
Residential Units: 0 **Total # of Units:** 0
Land Use:
Zoning: C8-2 R6B
Commercial Overlay: C2-4
Zoning Map #: 13B

Dept. of City Planning, PLUTO 14v2 © 2014 and other city agency sources

Links to More Information

Address Translator
Building Profile
Building Registration/Violation
DCP Zoning Map 13B
DOF Digital Tax Map
DOHMH Rat Information Portal
Tax and Property Records

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

824 METROPOLITAN AVENUE
METROPOLITAN AVENUE 824 - 830

BROOKLYN 11211

Health Area	: 900
Census Tract	: 481
Community Board	: 301

BIN# 3821541

Tax Block	: 2916
Tax Lot	: 14
Condo	: NO
Vacant	: YES

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	ORIENT AVENUE, OLIVE STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	3821543 3821542		
Special District:	UNKNOWN		

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: Z9-MISCELLANEOUS

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 824 METROPOLITAN AVENUE BROOKLYN **BIN: 3821541 Block: 2916 Lot: 14**

NUMBER		TYPE	FILE DATE
			00/00/0000
ALT 6057/33		ALTERATION	00/00/1933
ALT 8098EXTENSION INT PL/33		ALTERATION	00/00/1933
ALT 353/66		ALTERATION	00/00/1966
CERT 194505/66	(PDF)	CERTIFICATE OF OCCUPANCY	00/00/1966
DEM 337/61		DEMOLITION	00/00/1961
PRS 455/44		PLUMBING REPAIR SLIP	00/00/1944
UNK 5-4-1531962374HUGHES6-5-		UNKNOWN	00/00/0000
UNK 4-21-66		UNKNOWN	00/00/1921
UNK 10-25-654731-826-30LEVIN		UNKNOWN	00/00/1925

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-C (Rev. 7/64)—15M-781070(64) 114

DEPARTMENT OF BUILDINGS

ck BOROUGH OF Brooklyn, THE CITY OF NEW YORK

Date APR 20 1966 No. 194505

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No.

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at 826 Metropolitan Avenue Block 2916 Lot 14

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the south side of Metropolitan Avenue distant 140 feet east from the corner formed by the intersection of Metropolitan Avenue and Bushwick Avenue

running thence south 100 feet; thence east 50 feet;

thence north 100 feet; thence west 50 feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~N.B.~~ or Alt. No.— Alt. 353-1966 see occupancy below

Occupancy classification— const. 4-13-66 Construction classification— vacant land

Date of completion— plumb. 4-11-66 Height — stories — feet.

at time of issuance of permit. located in C8-2&C2-3 in R 6 Zoning District.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals:
and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	FLOOR AREA (Sq. Ft.)	OCCUPANT ACCOMMODATED	USE
on ground		1	public parking lot one hundred (100) spaces or less (Use Group 8)

TOTAL:- AS STATED ABOVE

Sewage Disposal:
Sanitary Drainage ..... (DOES) (DOES NOT) Discharge Into Either Sanitary or Combined Sewer

Storm Drainage ..... (DOES) (DOES NOT) Discharge Into Either Storm or Combined Sewer

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

APPENDIX D

PROFESSIONAL QUALIFICATIONS

DRAFT

EBI Consulting
environmental | engineering | due diligence

Jon Hickey
Project Engineer
344 East 87th Street, 4D
New York, NY 10128
Mobile: 917.804.5470
Fax: 617.715.6572

Summary of Experience

Jon Hickey is a Project Engineer specializing in environmental site assessments and property condition assessments for the real estate and telecommunications industries. In addition, Mr. Hickey has extensive experience overseeing subsurface investigations, remediation projects, and asbestos and lead-based paint surveys.

Relevant Project Experience

Mr. Hickey has over five years of experience conducting environmental assessments for commercial, industrial, and multi-family residential properties located nationwide and in Canada. Mr. Hickey has extensive experience conducting environmental assessments for real estate and telecommunications sites located throughout the New York metropolitan area. These assessments were performed to evaluate current and historic site conditions, potential off-site liabilities, environmental control systems, and site remediation costs in order to advise prospective buyers, operators and owners of potential and existing environmental concerns.

In addition to environmental assessments, Mr. Hickey has performed hundreds of property condition assessments for various property owners and financial institutions for portfolios and individual projects in the Northeast and Canada. Projects worked on ranged in size and complexity from small single-family residences and individual businesses, to multi-story apartment buildings and multi-building shopping centers.

Mr. Hickey has also conducted various stages of technical investigations including subsurface investigations, remediation projects, environmental compliance audits, and hazardous materials surveys. These investigations have included the management, installation, and oversight of soil borings and groundwater monitoring wells and sampling of environmental media.

Education

B.A.Sc. Environmental Engineering, University of Toronto, Toronto, Ontario, Canada

Professional Registrations

Registered Intern Engineer in the State of New York
U.S. EPA Certified Lead-Based Paint Inspector in the State of New York
New York State Department of Labor Certified Asbestos Inspector
OSHA 40-Hour Hazardous Waste Operations Certification

EBI Consulting
environmental | engineering | due diligence

Jennifer L. Callaghan
Program Manager
21 B Street
Burlington, MA 01803
Mobile: 484.680.2757

SUMMARY OF EXPERIENCE

JENNIFER L. CALLAGHAN IS A PROGRAM MANAGER WITH 13 YEARS OF EXPERIENCE SPECIALIZING IN ENVIRONMENTAL SITE ASSESSMENTS. MS. CALLAGHAN HAS CONDUCTED OVER 1,000 ENVIRONMENTAL SITE-ACQUISITION ASSESSMENTS/DUE DILIGENCE ASSIGNMENTS FOR A WIDE RANGE OF PROPERTIES THROUGHOUT THE UNITED STATES AND PUERTO RICO. THESE ASSESSMENTS HAVE BEEN PERFORMED TO EVALUATE SITE CONDITIONS AND POTENTIAL OFF-SITE LIABILITIES, INCLUDING CURRENT AND HISTORIC SITE AND OFF-SITE USES, IN ORDER TO ADVISE PROSPECTIVE BUYERS, LENDERS, OWNERS, AND OPERATORS OF POTENTIAL AND EXISTING ENVIRONMENTAL CONCERNS. MS. CALLAGHAN CURRENTLY CONDUCTS QA/QC AND TECHNICAL REVIEWS OF PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORTS. MS. CALLAGHAN HAS PERFORMED NUMEROUS SUBSURFACE INVESTIGATIONS WITHIN THE MID-ATLANTIC REGION AND HAS CONDUCTED SAMPLING SURVEYS FOR ASBESTOS, RADON, LEAD IN DRINKING WATER, AND LEAD-BASED PAINT.

RELEVANT PROJECT EXPERIENCE

ENVIRONMENTAL SITE ASSESSMENTS: MS. CALLAGHAN HAS PERFORMED, AUTHORED, MANAGED, AND REVIEWED ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENTS, TRANSACTION SCREEN ENVIRONMENTAL SITE ASSESSMENTS, PROPERTY CONDITION ASSESSMENTS, PRELIMINARY ASSESSMENTS, AND VAPOR INTRUSION ASSESSMENTS FOR VARIOUS CLIENTS AND A VARIETY OF PROPERTIES PRIMARILY WITHIN AND BORDERING THE MID-ATLANTIC REGION. THESE PROPERTIES HAVE INCLUDED HEAVY INDUSTRIAL, LIGHT INDUSTRIAL, INSTITUTIONAL, COMMERCIAL, RETAIL, AGRICULTURAL, RESIDENTIAL, AND UNDEVELOPED PROPERTIES AS WELL AS MULTI-TENANT PROPERTIES AND MULTI-SITE PROJECT PORTFOLIOS. AS PART OF THE ENVIRONMENTAL SITE ASSESSMENTS, MS. CALLAGHAN HAS PERFORMED REGULATORY FILE REVIEWS, LIMITED NEPA SCREENINGS, AND SURVEYS/SAMPLING OF SOIL, GROUNDWATER, SURFACE WATER, RADON, ASBESTOS-CONTAINING MATERIALS, LEAD-BASED PAINT, LEAD-IN-WATER, MOLD, AND WETLANDS.

NOTABLE PROJECTS INCLUDE:

- PHASE I ENVIRONMENTAL SITE ASSESSMENT AND REGULATORY FILE REVIEW OF THE FORMER CATERPILLAR TRACTOR CO. MANUFACTURING PLANT IN YORK, PENNSYLVANIA. A 106-ACRE FORMER HEAVY MANUFACTURING PLANT THAT HAD BEEN CONVERTED TO A MULTI-TENANT LIGHT INDUSTRIAL PARK WITH AN ELECTRIC CO-GENERATION PLANT. PROCESSES AND FACILITIES INCLUDED METAL MACHINING, CARBON FORGING, SPRAY PAINTING, SOLVENT DEGREASING, ELECTROPLATING, UNDERGROUND AND ABOVEGROUND STORAGE TANKS, A COAL-FIRED BOILER AND POWER PLANT, A COAL-GASIFICATION FACILITY, AND RAILROAD SPURS. ON-SITE WASTE HANDLING CONSISTED OF HAZARDOUS AND RESIDUAL WASTE STORAGE AREAS, UNDER-FLOOR AND UNDERGROUND PROCESS PIPING, AN INDUSTRIAL WASTEWATER TREATMENT PLANT, A METAL CHIP HOPPER, WASTE OIL LAGOONS, AND SLUDGE DISPOSAL, BURNING, AND LANDFARMING. THE HISTORIC USE OF THE FACILITY HAD RESULTED IN RELEASES OF REGULATED CONTAMINANTS TO THE SUBSOILS AND SHALLOW GROUNDWATER, AND THE SITE WAS INVESTIGATED AS A POTENTIAL SUPERFUND SITE. AFTER NEARLY TWO DECADES OF INVESTIGATION AND REMEDIATION, THE STATE GRANTED REGULATORY CLOSURE FOR SITE-WIDE SOILS AND GROUNDWATER IMPAIRMENT WITH PROVISIONS FOR DEED RESTRICTIONS AND ENGINEERING CONTROLS.

- PHASE I ENVIRONMENTAL SITE ASSESSMENT AND VAPOR INTRUSION ASSESSMENT OF A SOLVENT-BASED INK MANUFACTURING FACILITY IN NEW JERSEY, INCLUDING A REGULATORY FILE REVIEW FOR AN ADJACENT SUPERFUND SITE.

EBI Consulting
environmental | engineering | due diligence

Jennifer L. Callaghan
Program Manager
21 B Street
Burlington, MA 01803
Mobile: 484.680.2757

- Portfolio of 76 Phase I Environmental Site Assessments for a proposed conservation easement along the Susquehanna River in Lancaster and York Counties, Pennsylvania. Ms. Callaghan performed, authored, and managed the 76 ESAs, which were conducted on dozens of properties being acquired by a local conservancy organization from a regional electric utility provider. Ms. Callaghan discovered through historical research and inspection that the properties had housed a river coal dredging and processing operation, coal refuse basins, hydroelectric plants and dams, electrical transmission and distribution facilities, mills, an iron works, railroads, and dumping grounds.

- Technical review and project management for a 55-site Dollar General portfolio, many of which were historically operated as gasoline service stations.

- Phase I Environmental Site Assessments of heavy manufacturing facilities, automobile repair shops, gasoline stations, shopping centers, dry cleaners, tank farms, abandoned solid waste landfills, sewage treatment plants, and public school properties.

Subsurface Investigations: Ms. Callaghan has completed Phase II Site Investigations and other subsurface investigations at property types ranging from industrial to residential. Subsurface investigations have included auger, air/mud rotary and air drilling, test pit excavation, direct-push sampling methodology, the installation of soil borings and groundwater monitoring wells, and sampling of soil and groundwater. In addition, Ms. Callaghan has performed aquifer characterization tests and analysis as well as oversight of underground storage tank and underground hydraulic lift removals.

Notable projects include:

- Extensive soil and groundwater sampling, a forensics investigation, and remediation at a former pharmaceutical landfill located beneath a public school property and residential subdivision in New Jersey.

- Subsurface investigations to assess impacts from heating oil underground storage tanks at multiple public school properties in Philadelphia, Pennsylvania.

- Subsurface investigations of county maintenance facilities and automobile repair shops, to assess for impacts from underground storage tanks, underground hydraulic lifts, and floor drains.

Education

Honors Bachelor of Science, Ecology and Evolutionary Biology, *Summa Cum Laude*
University of Arizona, Tucson, Arizona
Member of *Phi Beta Kappa*

Professional Registrations

USEPA AHERA Accredited Asbestos Building Inspector
HUD Visual Assessment Course (lead-based paint) Certification

APPENDIX E

REGULATORY DATABASE REPORT

DRAFT

824 Metropolitan Ave
824 Metropolitan Ave
Brooklyn, NY 11211

Inquiry Number: 04357835.2r
July 17, 2015

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	666
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

824 METROPOLITAN AVE
BROOKLYN, NY 11211

COORDINATES

Latitude (North):	40.7146000 - 40° 42' 52.56''
Longitude (West):	73.9411000 - 73° 56' 27.96''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589441.3
UTM Y (Meters):	4507403.5
Elevation:	37 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	40073-F8 BROOKLYN, NY
Version Date:	1995

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20110710, 20110705
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	CON EDISON	13 ORIENT AVE	NY MANIFEST	Lower	94, 0.018, NE
A2	LEROS REALTY CORP	850 METROPOLITAN AVE	NY AST, NY HIST AST	Lower	194, 0.037, East
B3		810 METROPOLITAN AV	EDR US Hist Auto Stat	Higher	231, 0.044, West
B4	MERIT METROPOLITAN	810 METROPOLITAN AVE	RCRA NonGen / NLR, FINDS, NY LTANKS, NY UST, NY...	Higher	231, 0.044, West
B5	CON EDISON	813 METROPOLITAN AVE	NY MANIFEST	Higher	237, 0.045, WNW
A6	CON EDISON	35 ORIENT AV	NY MANIFEST	Lower	240, 0.045, ENE
B7	METROPOLITAN AVE/MER	METROPOLITAN&BUSHWIC	NY LTANKS	Higher	255, 0.048, West
B8	CON EDISON	807 METROPOLITAN AVE	NY MANIFEST	Higher	268, 0.051, WNW
B9		807 METROPOLITAN AV	EDR US Hist Auto Stat	Higher	268, 0.051, WNW
B10		5 BUSHWICK AVE	EDR US Hist Auto Stat	Higher	269, 0.051, West
B11	MERIT S/S / BKLN	METROPOLITAN & BUSHW	NY Spills	Higher	269, 0.051, West
12	25 BUSHWICK AVE	25 BUSHWICK AVE	NY LTANKS	Higher	273, 0.052, SW
B13	AMOCO SVCE STA	2 BUSHWICK AVE.	RCRA NonGen / NLR, FINDS, NY LTANKS, NY MANIFEST,...	Higher	274, 0.052, West
B14	SHELL SERVICE STATIO	2 BUSHWICK AVENUE	NY UST	Higher	274, 0.052, West
B15	SHELL SERVICE STATIO	2 BUSHWICK AVENUE	NY AST	Higher	274, 0.052, West
B16		2 BUSHWICK AVE	EDR US Hist Auto Stat	Higher	274, 0.052, West
C17	CON EDISON	OPP 34 MASPETH AV	NY MANIFEST	Lower	304, 0.058, NNW
C18	CON EDISON	42 MASPETH AV	NY MANIFEST	Lower	334, 0.063, North
19	CON EDISON	58-35 MASPETH AV	NY MANIFEST	Lower	411, 0.078, NNE
D20		880 METROPOLITAN AV	EDR US Hist Auto Stat	Lower	416, 0.079, East
D21	880 METROPOLITAN AVE	880 METROPOLITAN AVE	NY Spills	Lower	416, 0.079, East
E22	CON EDISON	OPP 3 MASPETH AVE	NY MANIFEST	Higher	423, 0.080, WNW
23	ST FRANCIS OF PAOLA	219 CONSELYEA STREET	NY UST, NY HIST UST	Lower	454, 0.086, NW
E24	NYS TAXI NETWORK INC	801 METROPALITAN AVE	NY AST	Higher	474, 0.090, West
D25	CON EDISON - MANHOLE	890 METROPOLITAN AVE	RCRA-LQG, NY MANIFEST	Lower	480, 0.091, East
26	SPILL NUMBER 0100018	50 BUSHWICK AVE	NY Spills	Higher	481, 0.091, South
F27	CON EDISON SERVICE B	253 DEVOE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	488, 0.092, ESE
D28	CON EDISON SERVICE B	892 METROPOLITAN AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST	Lower	496, 0.094, East
G29		383 HUMBOLDT ST	EDR US Hist Auto Stat	Higher	528, 0.100, WNW
G30	385 HUMBOLDT ST.	385 HUMBOLDT ST	NY Spills	Higher	542, 0.103, WNW
H31	S/S BREAKER LEAKED D	324 AINSLIE ST. SUBS	NY Spills	Higher	558, 0.106, SSW
I32	SPILL NUMBER 0201573	236 SKILLMAN AVE	NY Spills	Lower	600, 0.114, North
H33	CON EDISON	298 AINSLIE ST	NY MANIFEST	Higher	601, 0.114, SW
H34	CON EDISON	298 AINSLIE ST	NY MANIFEST	Higher	601, 0.114, SW
F35	CON EDISON	263 DEVOE STREET	NY MANIFEST	Lower	602, 0.114, ESE
I36	SANITATION COMPANY	244 SKILLMAN AVE	NY Spills	Lower	605, 0.115, North
I37	SKILL-MAN CONTRACTIN	244 SKILLMAN AVENUE	NY AST	Lower	605, 0.115, North
J38		193 WOODPOINT RD	EDR US Hist Auto Stat	Lower	608, 0.115, NNW
J39	TWO BROTHERS AUTO SA	193 WOODPOINT ROAD	NY AST	Lower	608, 0.115, NNW

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G40	ST. FRANCIS OF PAOLA	195-201 CONSELYEA ST	NY AST	Lower	612, 0.116, WNW
K41	CON EDISON SERVICE B	16 JUDGE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	634, 0.120, SSE
J42		221 SKILLMAN AVE	EDR US Hist Auto Stat	Lower	636, 0.120, NNW
L43	258 SKILLMAN ST	258 SKILLMAN ST	NY Spills, NY E DESIGNATION	Lower	648, 0.123, NNE
M44	CON EDISON	FRONT OF 67 OLIVE ST	NY MANIFEST	Lower	652, 0.123, East
N45	SOCCI RESIDENCE	177 DEVOE ST	NY Spills	Higher	659, 0.125, WSW
M46	CON EDISON - MANHOLE	909 METROPOLITAN AVE	RCRA-LQG, NY MANIFEST, NY MANIFEST	Lower	663, 0.126, East
47		70 BUSHWICK AVE	EDR US Hist Auto Stat	Higher	682, 0.129, South
O48	CON EDISON	FO 764 METROPOLITAN	NY MANIFEST	Higher	688, 0.130, West
K49	JENNINGS HALLL HDFC	260 POWERS STREET	NY UST	Higher	690, 0.131, SSE
L50		253 SKILLMAN AVE	EDR US Hist Auto Stat	Lower	697, 0.132, North
O51		765 METROPOLITAN AV	EDR US Hist Cleaners	Higher	734, 0.139, West
P52	CON EDISON	FRONT OF 921 METROPO	NY MANIFEST	Lower	757, 0.143, East
53	ST NICHOLAS R C CHUR	26 OLIVE ST	NY AST, NY HIST AST	Lower	762, 0.144, SE
54	CON EDISON	FO 269 POWERS ST	NY MANIFEST	Lower	770, 0.146, SE
N55	CON EDISON	180 DEVOE ST	NY MANIFEST	Higher	785, 0.149, WSW
N56	CON EDISON	180 DEVOE ST	NY MANIFEST	Higher	785, 0.149, WSW
P57	CON EDISON	925 METROPOLITAN AVE	NY MANIFEST	Lower	788, 0.149, East
Q58		334 GRAHAM AVE	EDR US Hist Cleaners	Higher	844, 0.160, West
Q59	GATTI CLEANERS	334 GRAHAM AVE	RCRA NonGen / NLR, NY MANIFEST, US AIRS	Higher	844, 0.160, West
Q60	NEW GATTI/PARK/LOUIS	334 GRAHAM AVENUE	NY DRYCLEANERS	Higher	844, 0.160, West
61	CON EDISON	231 JACKSON ST	NY MANIFEST	Lower	872, 0.165, North
R62	CON EDISON	OPP 285 DEVOE ST	NY MANIFEST	Lower	894, 0.169, ESE
S63	RESIDENCE	243 JACKSON STREET	NY LTANKS, NY Spills	Lower	900, 0.170, North
Q64	CON EDISON SERVICE B	327 GRAHAM AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	915, 0.173, WSW
65		177 SKILLMAN AVE	EDR US Hist Auto Stat	Lower	917, 0.174, NW
R66	CON EDISON	312 DEVOE ST	NY MANIFEST	Lower	919, 0.174, ESE
67	326 GRAHAM AVE	326 GRAHAM AVENUE	NY UST	Higher	921, 0.174, WSW
68	FORMER BENNETT TRUCK	845 GRAND STREET	NY Spills, NY BROWNFIELDS	Higher	935, 0.177, SSE
S69		251 JACKSON ST	EDR US Hist Cleaners	Lower	936, 0.177, NNE
T70	CON EDISON	940 METROPOLITAN AV	NY MANIFEST	Lower	940, 0.178, East
T71	CON EDISON	945 METROPOLITAN AVE	NY MANIFEST	Lower	946, 0.179, East
U72		362 GRAHAM AVE	EDR US Hist Cleaners	Lower	954, 0.181, WNW
V73	JP MORGAN CHASE AND	819 GRAND STREET	NY AST	Higher	963, 0.182, South
V74	NYNEX	BUSHWICK AVE & GRAND	NY MANIFEST	Higher	967, 0.183, South
V75	MTA NYCT - GRAND STR	GRAND ST & BUSHWICK	RCRA-SQG, FINDS	Higher	969, 0.184, South
U76		368 GRAHAM AVE	EDR US Hist Cleaners	Lower	980, 0.186, WNW
V77	CON EDISON SERVICE B	812 GRAND ST	RCRA NonGen / NLR, NY MANIFEST	Higher	982, 0.186, South
W78	FORMER SCIENTIFIC FI	871 GRAND STREET	NY BROWNFIELDS, NY E DESIGNATION	Higher	990, 0.188, SE

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
X79		802 GRAND ST	EDR US Hist Cleaners	Higher	992, 0.188, South
X80	RHEE & NURYS DRY CLE	802 GRAND ST	RCRA NonGen / NLR, FINDS, NY MANIFEST	Higher	992, 0.188, South
X81	RHEE & NURY'S/Y&Y CL	802 GRAND STREET	NY DRYCLEANERS	Higher	992, 0.188, South
W82	SCIENTIFIC FIRE PREV	871 GRAND ST	RCRA NonGen / NLR, FINDS, NY MANIFEST	Higher	992, 0.188, SE
83	FRANK LOVISI	308 GRAHAM AVE	NY AST, NY HIST AST	Higher	994, 0.188, WSW
V84		100 BUSHWICK AVE	EDR US Hist Auto Stat	Higher	1001, 0.190, South
T85	CORMEN ENTERPRISES I	953 METROPOLITAN AVE	NY AST	Lower	1008, 0.191, East
T86		948 METROPOLITAN AV	EDR US Hist Auto Stat	Lower	1020, 0.193, East
W87	885 GRAND STREET COR	881-5 GRAND ST	NY UST	Higher	1023, 0.194, SE
W88		881 GRAND ST	EDR US Hist Auto Stat	Higher	1023, 0.194, SE
W89	J & M AUTO REPAIRS	881-885 GRAND ST	RCRA NonGen / NLR, FINDS, NY LTANKS, NY MANIFEST	Higher	1023, 0.194, SE
W90		885 GRAND ST	EDR US Hist Auto Stat	Lower	1036, 0.196, SE
W91	RALPH'S AUTO CENTER	885 GRAND STREET	NY UST	Lower	1036, 0.196, SE
Y92	CON EDISON	39 KINGSLAND AVE	NY MANIFEST	Lower	1044, 0.198, NNE
93		380 GRAHAM AVE	EDR US Hist Cleaners	Lower	1066, 0.202, WNW
94	NYCHA - COOPER PARK	275 JACKSON ST	RCRA NonGen / NLR, FINDS, NY MANIFEST	Lower	1067, 0.202, NNE
Z95	CON EDISON	177 JACKSON ST	NY MANIFEST	Lower	1069, 0.202, NW
Z96	CON EDISON	FO 177 JACKSON ST	NY MANIFEST	Lower	1069, 0.202, NW
AA97		770 GRAND ST	EDR US Hist Cleaners	Higher	1082, 0.205, SSW
98	BRICKMER REALTY CORP	722 METROPOLITAN AVE	NY AST	Lower	1083, 0.205, West
AB99	900 GRAND STREET MIL	900 GRAND ST	RCRA-CESQG, FINDS, NY MANIFEST	Lower	1090, 0.206, SE
AB100	900 GRAND ST. MILK L	900 GRAND STREET	NY UST	Lower	1090, 0.206, SE
AA101	GRAND CLEANERS	765 GRAND ST	RCRA-SQG, FINDS, NY MANIFEST, NY DRYCLEANERS, US...	Higher	1091, 0.207, SSW
AA102		765 GRAND ST	EDR US Hist Cleaners	Higher	1091, 0.207, SSW
AC103	CON EDISON	143 DEVOE ST	NY MANIFEST	Higher	1091, 0.207, WSW
AB104		900 GRAND ST	EDR US Hist Auto Stat	Lower	1096, 0.208, SE
AD105	GLOVEMAN REALTY CORP	294 GRAHAM AVENUE	NY UST, NY HIST UST	Higher	1127, 0.213, SW
106	CON EDISON	251 WITHERS ST	NY MANIFEST	Lower	1137, 0.215, North
AE107	ST NICHOLAS H S BUIL	11-29 CATHERINE ST	NY AST, NY HIST AST	Lower	1141, 0.216, ESE
108	CON EDISON	267 WITHERS ST	NY MANIFEST	Lower	1143, 0.216, North
109	EASTERN DISTRICT HIG	850 GRAND ST	RCRA NonGen / NLR, NY AST, NY HIST AST, NY...	Higher	1148, 0.217, SSE
110	755 REALTY CORP.	753 GRAND STREET	NY AST	Higher	1148, 0.217, SSW
AE111	CON EDISON	12 CATHERINE ST	NY MANIFEST	Lower	1149, 0.218, ESE
Y112		47 KINGSLAND AVE	EDR US Hist Cleaners	Lower	1151, 0.218, North
113	CON EDISON	56 SHARON ST	NY MANIFEST	Lower	1164, 0.220, ENE
AD114		283 GRAHAM AVE	EDR US Hist Auto Stat	Higher	1166, 0.221, SW
AF115	AMERICAN WOOD COLUMN	913 GRAND ST	NY AST, NY HIST AST	Lower	1175, 0.223, SE
AG116	COOPER PARK HOUSES	295 JACKSON STREET	NY UST	Lower	1175, 0.223, NNE
AG117	COOPER PARK -NYCHA	295 JACKSON ST	NY LTANKS, NY Spills	Lower	1175, 0.223, NNE

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AH118	CON EDISON	FO 214 WITHERS ST	NY MANIFEST	Lower	1180, 0.223, NNW
AF119	GRAND AUTO REPAIRS C	916 GRAND ST	RCRA NonGen / NLR, FINDS, NY MANIFEST	Lower	1185, 0.224, SE
AF120		916 GRAND ST	EDR US Hist Auto Stat	Lower	1185, 0.224, SE
AF121	SAFEGUARD SELF STORA	916 GRAND STREET	NY UST, NY AST	Lower	1185, 0.224, SE
AI122	KINGSLAND SERVICE ST	51 KINGSLAND AVENUE	NY UST, NY Spills	Lower	1185, 0.224, North
AI123	MOBIL OIL CO	51 KINGSLAND AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1185, 0.224, North
AI124		51 KINGSLAND AVE	EDR US Hist Auto Stat	Lower	1185, 0.224, North
AH125	BUONOMO/GY LEE CLEAN	448 HUMBOLDT AVENUE	NY DRYCLEANERS	Lower	1201, 0.227, NNW
AH126	EVADA CLEANERS OF NY	448 HUMBOLDT ST	RCRA-CESQG, FINDS, NY MANIFEST, US AIRS	Lower	1201, 0.227, NNW
AH127		448 HUMBOLDT ST	EDR US Hist Cleaners	Lower	1201, 0.227, NNW
AJ128		972 METROPOLITAN AV	EDR US Hist Auto Stat	Lower	1208, 0.229, East
AK129	CON EDISON SERVICE B	161 JACKSON ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1209, 0.229, NW
AF130	J&G AUTO SHOP	921 GRAND STREET	NY UST	Lower	1217, 0.230, ESE
AC131	CON EDISON	FO 133 DEVOE ST	NY MANIFEST	Higher	1218, 0.231, WSW
AL132	CON EDISON	FRONT OF 137 MASPETH	NY MANIFEST	Lower	1221, 0.231, NE
AM133	CON EDISON	277 GRAHAM AV	NY MANIFEST	Higher	1230, 0.233, SW
134	231 MAUJER STREET	231 MAUJER STREET	NY AST, NY HIST AST	Higher	1243, 0.235, South
AK135		395 GRAHAM AVE	EDR US Hist Auto Stat	Lower	1253, 0.237, NW
AK136		400 GRAHAM AVE	EDR US Hist Cleaners	Lower	1256, 0.238, NW
137		145 SKILLMAN AVE	EDR US Hist Auto Stat	Lower	1261, 0.239, WNW
138	NYCHA - COOPER PARK	40 DEBEVOISE AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1263, 0.239, NE
AJ139		980 METROPOLITAN AV	EDR US Hist Auto Stat	Lower	1263, 0.239, East
140	CON EDISON SERVICE B	129 DEVOE	RCRA NonGen / NLR, NY MANIFEST	Lower	1268, 0.240, WSW
AL141	CON EDISON SERVICE B	143 MASPETH AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST	Lower	1287, 0.244, ENE
AN142	WILLIAMSBURG	200 MAUJER STREET	NY UST, NY AST	Higher	1287, 0.244, South
AO143	GCS SERVICE INC.	932 GRAND STREET	NY UST, NY HIST UST	Lower	1291, 0.245, ESE
AO144	CON EDISON	933 GRAND ST	NY MANIFEST	Lower	1300, 0.246, ESE
AN145	CON EDISON - MANHOLE	276 HUMBOLDT ST	RCRA-LQG, NY MANIFEST	Higher	1306, 0.247, SSW
AM146	LOT 43,TAXBLOCK 2783	725 GRAND STREET	NY MANIFEST, NY E DESIGNATION	Higher	1311, 0.248, SW
AP147	CHASE BANK	726 GRAND STREET	NY UST	Higher	1319, 0.250, SW
AP148	DIME SAVINGS BANK	726 GRAND STREET	NY HIST UST	Higher	1319, 0.250, SW
149	308 MAUJER ST	308 MAUJER ST	NY LTANKS	Lower	1435, 0.272, SE
150	WILLIAMSBURG HOUSES	188 TEN EYCK WALK	NY LTANKS, NY Spills	Higher	1572, 0.298, SSW
151	BUG, EQUITY WORKS	MASPETH AND MORGAN A	NY HSWDS	Lower	1636, 0.310, ENE
AQ152	WILLIAMSBURG	144 MAUJER ST & GRAH	NY LTANKS	Higher	1655, 0.313, SSW
AQ153	151 MAUJER ST	151 MAUJER STREET	NY LTANKS	Higher	1666, 0.316, SW
AR154	MAGNUM BODY SHOP INC	185A MASPETH AVE	NY RGA LF	Lower	1766, 0.334, ENE
AR155	MAGNUM BODY SHOP INC	185A MASPETH AVE	NY SWF/LF	Lower	1766, 0.334, ENE
156	WILLIAMSBURG HOUSES	128 MAUJER STREET	NY LTANKS, NY HIST UST, NY Spills	Higher	1790, 0.339, SW

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AS157	JOESEPH LOWESTEIN AN	420 MORGAN AVE	NY LTANKS, NY Spills	Lower	1799, 0.341, NE
158	WILLIAMSBURGH HOUSES	211 STAGG WALK	NY LTANKS, NY UST, NY AST, NY Spills	Higher	1802, 0.341, South
159	INTERMEDIATE SCHOOL	223 GRAHAM AVENUE	NY LTANKS, NY UST, NY AST, NY HIST AST	Higher	1822, 0.345, SSW
160	345 TENEYCK STREET	345 TENEYCK STREET	NY LTANKS	Lower	1855, 0.351, SE
161	MS POWER INC	187 MASPETH VE	NY SWF/LF	Lower	1863, 0.353, ENE
AS162	ABANDONED BLDG	430 MORGAN AVE	NY LTANKS	Lower	1871, 0.354, NE
AT163	DURITE S&V & MAINT.	250 MORGAN AVE	NY RGA LF	Lower	1941, 0.368, ESE
AT164	DURITE S&V & MAINT.	250 MORGAN AVE	NY SWF/LF	Lower	1941, 0.368, ESE
165	APARTMENT BUILDING	35 MEADOW STREET	NY LTANKS	Lower	1993, 0.377, SE
AU166	COOPER TANK AND WELD	222 MASPETH AVENUE	NY SWF/LF, NY HIST AST, NY Financial Assurance	Lower	2087, 0.395, ENE
AU167	COOPER TANK (222 MAS	222 MASPETH AVENUE	NY RGA LF	Lower	2087, 0.395, ENE
168	GREEN HILL	2 REWE ST & 300 VAND	NY LTANKS	Lower	2110, 0.400, East
169	EQUITY WORKS	MASPETH AND VANDERVO	EDR MGP	Lower	2170, 0.411, ENE
AV170	NEW TOWN AUTO SALES	1074 GRAND STREET	NY RGA LF	Lower	2186, 0.414, East
AV171	NEW TOWN AUTO SALES	1074 GRAND AVENUE	NY SWF/LF	Lower	2186, 0.414, East
AW172	CITY BARREL CO.	421-429 MEEKER STREE	NY SHWS	Lower	2186, 0.414, NW
AX173	CLEAN VENTURE	222 MORGAN AVENUE	NY RGA LF	Lower	2188, 0.414, ESE
AX174	EASTERN TRANSFER OF	222 MORGAN AVE	NY RGA LF	Lower	2188, 0.414, ESE
AX175	EASTERN TRANSFER OF	222 MORGAN AVE	NY SWF/LF, NY LTANKS	Lower	2188, 0.414, ESE
AX176	NY MATERIALS REC (NY	222 MORGAN AVENUE	NY RGA LF	Lower	2188, 0.414, ESE
AX177	EASTERN TRANSFER	222 MORGAN AVENUE	NY RGA LF	Lower	2188, 0.414, ESE
AW178	CITY BARREL	421 MEEKER STREET	NY HSWDS	Lower	2191, 0.415, NW
AW179	CITY BARREL & DRUM C	421 MEEKER AVE	CERC-NFRAP, RCRA NonGen / NLR	Lower	2191, 0.415, NW
AY180	CLOSED-LACKOF RECENT	1105 METROPOLITAN AV	NY LTANKS	Lower	2195, 0.416, East
AY181	1101 METROPOLITAN AV	1101 METROPOLITAN AV	NY LTANKS	Lower	2245, 0.425, East
182	WILLIAMSBURG HOUSES	125 STAGG WALK	NY LTANKS, NY Spills	Higher	2249, 0.426, SSW
183	MOBIL OIL CORP SS #F	550 HUMBOLDT ST	RCRA NonGen / NLR, NY LTANKS, NY UST, NY Spills	Lower	2257, 0.427, NNW
184	APT BUILDING TANK	85 MEADOW STREET	NY LTANKS	Lower	2307, 0.437, ESE
185	SPILL NUMBER 0003338	232 MESROLE ST	NY LTANKS	Higher	2321, 0.440, South
AZ186	FORMER KLINK COSMO C	364 RICHARDSON STREE	NY SHWS	Higher	2330, 0.441, NNE
AZ187	FORMER KLINK COSMO C	364 RICHARDSON STREE	NY RGA HWS	Higher	2330, 0.441, NNE
BA188	FONTANA TRANSFER STA	252 MASPETH AVENUE	NY SWF/LF	Lower	2337, 0.443, ENE
BA189	FONTANA TRANSFER STA	252 MASPETH AVENUE	NY RGA LF	Lower	2337, 0.443, ENE
190	COMMERCIAL PROPERTY	1-7 BUSHWICK PLACE	NY LTANKS, NY Spills	Higher	2370, 0.449, SSE
BB191	FRITO LAY	202-218 MORGAN AVENU	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	2427, 0.460, ESE
BB192	KARNAK (NEWTOWN META	202 MORGAN AVENUE	NY RGA LF	Lower	2427, 0.460, ESE
BB193	KARNAK (NEWTOWN META	202 MORGAN AVENUE	NY SWF/LF, NY Spills	Lower	2427, 0.460, ESE
194	GAS STATION/ 278 FUE	392 LEONARD ST	NY LTANKS, NY Spills	Lower	2438, 0.462, NW
195	ALBERTS PLATING WORK	32 BEADEL ST	RCRA NonGen / NLR, FINDS, NY LTANKS, NY MANIFEST	Higher	2439, 0.462, North

MAPPED SITES SUMMARY

Target Property Address:
824 METROPOLITAN AVE
BROOKLYN, NY 11211

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BB196	MORGAN OIL TERMINALS	200 MORGAN AVE	RCRA NonGen / NLR, FINDS, NY MOSF UST, NY MANIFEST	Lower	2451, 0.464, ESE
BB197	NYC DEP HAZ MAT	200 MORGAN AVENUE	NY LIENS, NY MANIFEST, NY Spills, NY MOSF	Lower	2451, 0.464, ESE
BC198	BAYSIDE FUEL OIL DEP	1100 GRAND STREET	NY Spills, NY SPDES, NY MOSF	Lower	2457, 0.465, East
BC199	BAYSIDE FUEL OIL DEP	1100 GRAND STREET	NY MOSF UST, NY MOSF AST	Lower	2457, 0.465, East
200	UNITED AMBULETTE	495 GRAHAM AVE	NY LTANKS	Lower	2533, 0.480, NW
201	APT COMPLEX	349 SCHOLES ST	NY LTANKS	Lower	2606, 0.494, SE
202	64 FROST ST	64 FROST STREET	NY LTANKS, NY Spills	Lower	2607, 0.494, WNW
203	555 GRAND STREET	555 GRAND STREET	NY BROWNFIELDS, NY E DESIGNATION	Lower	2630, 0.498, WSW
204	SCHOLES ST. STATION	SCHOLES ST 7 BOGART	EDR MGP	Lower	2637, 0.499, SE
205	MOST HOLY TRINITY RE	157 GRAHAM AVE	NY LTANKS, NY UST, NY HIST UST	Lower	2639, 0.500, SSW
BD206	K - GREENPOINT MGP -	287 MASPETH AVENUE	NY RGA HWS	Lower	2779, 0.526, ENE
BD207	K - GREENPOINT MGP -	287 MASPETH AVE	NY RGA HWS	Lower	2779, 0.526, ENE
208	NEWTOWN CREEK	SOUTH END OF IVY HIL	NPL, CERCLIS, NY MANIFEST	Lower	2880, 0.545, East
BE209	ACME STEEL/METAL WOR	95 LOMBARDY STREET	NY RGA HWS	Higher	3129, 0.593, NNE
BE210	95 LOMBARDY ST./ACME	95 LOMBARDY ST	NY SHWS, NY UST, NY HIST UST	Higher	3129, 0.593, NNE
211	BERKMAN BROS INC	ECKFORD ST	RCRA-CESQG, NY SHWS, NY LTANKS, NY MANIFEST, NY...	Lower	3216, 0.609, NW
BF212	GREENPOINT ENERGY FA	287 MASPETH AVENUE	NY SHWS, NY SWF/LF, NY LTANKS, NY TANKS, NY...	Lower	3356, 0.636, NE
BF213	GREENPOINT	287 MASPETH AVENUE	EDR MGP	Lower	3356, 0.636, NE
BG214	BCF OIL REFINING, IN	360 MASPETH AVENUE -	NY RGA HWS	Lower	3376, 0.639, ENE
BG215	US ENVIRONMENTAL PRO	C O BCF OIL REFINING	CERCLIS, RCRA NonGen / NLR, NY SHWS, NY MANIFEST,...	Lower	3376, 0.639, ENE
BG216	B.C.F. OIL REFINING,	360 MASPETH AVENUE,	NY RGA HWS	Lower	3376, 0.639, ENE
217	BQE/ANSBACHER COLOR	MEEKER AVENUE	NY SHWS	Lower	3390, 0.642, West
BH218	ACME STEEL PARTITION	513 PORTER AVE	RCRA NonGen / NLR, NY SHWS, NY MANIFEST	Higher	3609, 0.684, NNE
BH219	ACME STEEL/BRASS FOU	72 ANTHONY STREET	NY RGA HWS	Higher	3609, 0.684, NNE
BI220	VARICK AVENUE	165 VARICK AVENUE	NY RGA HWS	Lower	3619, 0.685, ESE
BI221	VARICK AVENUE	165 VARICK AVENUE	NY SHWS	Lower	3619, 0.685, ESE
222	CHLORAL GROUP	171 LOMBARDY ST	NY SHWS, NY CBS AST, NY CBS	Higher	3761, 0.712, NNE
BJ223	FORMER SPIC AND SPAN	315 KINGSLAND AVENUE	NY RGA HWS	Lower	4653, 0.881, North
BJ224	FORMER SPIC AND SPAN	315 KINGSLAND AVE	NY SHWS, NY Spills	Lower	4653, 0.881, North
225	WYTHE AVE. (BERRY ST	WYTHE AVE., BERRY ST	EDR MGP	Lower	5079, 0.962, WNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent CERCLIS

NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

State and tribal leaking storage tank lists

NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

INDIAN LUST - Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

NY CBS UST - Chemical Bulk Storage Database
INDIAN UST - Underground Storage Tanks on Indian Land
FEMA UST - Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

NY RES DECL - Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP - Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP - Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS - A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
ODI - Open Dump Inventory
NY SWRCY - Registered Recycling Facility List
NY SWTIRE - Registered Waste Tire Storage & Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL - Clandestine Drug Labs
NY DEL SHWS - Delisted Registry Sites
US HIST CDL - National Clandestine Laboratory Register

Local Land Records

LIENS 2 - CERCLA Lien Information

Records of Emergency Release Reports

HMIRS - Hazardous Materials Information Reporting System
NY Hist Spills - SPILLS Database

Other Ascertainable Records

DOT OPS - Incident and Accident Data
DOD - Department of Defense Sites
FUDS - Formerly Used Defense Sites

EXECUTIVE SUMMARY

CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
US MINES	Mines Master Index File
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
SSTS	Section 7 Tracking Systems
ICIS	Integrated Compliance Information System
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
RADINFO	Radiation Information Database
RAATS	RCRA Administrative Action Tracking System
RMP	Risk Management Plans
NY UIC	Underground Injection Control Wells
NY AIRS	Air Emissions Data
INDIAN RESERV	Indian Reservations
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
NY COAL ASH	Coal Ash Disposal Site Listing
PCB TRANSFORMER	PCB Transformer Registration Database
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
LEAD SMELTERS	Lead Smelter Sites
2020 COR ACTION	2020 Corrective Action Program List
COAL ASH DOE	Steam-Electric Plant Operation Data

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 03/26/2015 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK	*SOUTH END OF IVY HIL*	*E 1/2 - 1 (0.545 mi.)*	*208*	*595*

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY BARREL & DRUM C	*421 MEEKER AVE*	*NW 1/4 - 1/2 (0.415 mi.)*	*AW179*	*438*

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/10/2015 has revealed that there are 3 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE	*276 HUMBOLDT ST*	*SSW 1/8 - 1/4 (0.247 mi.)*	*AN145*	*370*

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE	*890 METROPOLITAN AVE*	*E 0 - 1/8 (0.091 mi.)*	*D25*	*80*
CON EDISON - MANHOLE	*909 METROPOLITAN AVE*	*E 1/8 - 1/4 (0.126 mi.)*	*M46*	*110*

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/10/2015 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - GRAND STR	***GRAND ST & BUSHWICK***	***S 1/8 - 1/4 (0.184 mi.)***	***V75***	***164***
GRAND CLEANERS	***765 GRAND ST***	***SSW 1/8 - 1/4 (0.207 mi.)***	***AA101***	***225***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/10/2015 has revealed that there are 2 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
900 GRAND STREET MIL	***900 GRAND ST***	***SE 1/8 - 1/4 (0.206 mi.)***	***AB99***	***217***
EVADA CLEANERS OF NY	***448 HUMBOLDT ST***	***NNW 1/8 - 1/4 (0.227 mi.)***	***AH126***	***331***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/18/2015 has revealed that there are 11 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER KLINK COSMO C	364 RICHARDSON STREE	NNE 1/4 - 1/2 (0.441 mi.)	AZ186	477
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 405851				
95 LOMBARDY ST./ACME	***95 LOMBARDY ST***	***NNE 1/2 - 1 (0.593 mi.)***	***BE210***	***599***
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 405853				
ACME STEEL PARTITION	***513 PORTER AVE***	***NNE 1/2 - 1 (0.684 mi.)***	***BH218***	***646***
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 405855				
CHLORAL GROUP	***171 LOMBARDY ST***	***NNE 1/2 - 1 (0.712 mi.)***	***222***	***656***
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 486951				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY BARREL CO.	421-429 MEEKER STREE	NW 1/4 - 1/2 (0.414 mi.)	AW172	432
Site Code: 55909				
BERKMAN BROS INC	***ECKFORD ST***	***NW 1/2 - 1 (0.609 mi.)***	***211***	***606***
Site Code: 470590				
GREENPOINT ENERGY FA	***287 MASPETH AVENUE***	***NE 1/2 - 1 (0.636 mi.)***	***BF212***	***620***
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 372971				

Lower Elevation	Address	Direction / Distance	Map ID	Page
US ENVIRONMENTAL PRO	***C O BCF OIL REFINING***	***ENE 1/2 - 1 (0.639 mi.)***	***BG215***	***631***
Site Code: 56747				
BQE/ANSBACHER COLOR	MEEKER AVENUE	W 1/2 - 1 (0.642 mi.)	217	644
Class Code: Does not present a significant threat to the public health or the environment - action may be deferred.				
Site Code: 55913				
VARICK AVENUE	165 VARICK AVENUE	ESE 1/2 - 1 (0.685 mi.)	BI221	655
Site Code: 55914				
FORMER SPIC AND SPAN	***315 KINGSLAND AVE***	***N 1/2 - 1 (0.881 mi.)***	***BJ224***	***660***
Class Code: Significant threat to the public health or environment - action required.				
Site Code: 405850				

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 04/08/2015 has revealed that there are 8 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAGNUM BODY SHOP INC	185A MASPETH AVE	ENE 1/4 - 1/2 (0.334 mi.)	AR155	387
MS POWER INC	187 MASPETH VE	ENE 1/4 - 1/2 (0.353 mi.)	161	422
DURITE S&V & MAINT.	250 MORGAN AVE	ESE 1/4 - 1/2 (0.368 mi.)	AT164	424
COOPER TANK AND WELD	***222 MASPETH AVENUE***	***ENE 1/4 - 1/2 (0.395 mi.)***	***AU166***	***427***
NEW TOWN AUTO SALES	1074 GRAND AVENUE	E 1/4 - 1/2 (0.414 mi.)	AV171	431
EASTERN TRANSFER OF	***222 MORGAN AVE***	***ESE 1/4 - 1/2 (0.414 mi.)***	***AX175***	***433***
FONTANA TRANSFER STA	252 MASPETH AVENUE	ENE 1/4 - 1/2 (0.443 mi.)	BA188	480
KARNAK (NEWTOWN META	***202 MORGAN AVENUE***	***ESE 1/4 - 1/2 (0.460 mi.)***	***BB193***	***496***

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/18/2015 has revealed that there are 33 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERIT METROPOLITAN	***810 METROPOLITAN AVE***	***W 0 - 1/8 (0.044 mi.)***	***B4***	***13***
Program Number: 9404715				
Spill Number/Closed Date: 9404715 / 11/22/1994				
Site ID: 158143				
METROPOLITAN AVE/MER	METROPOLITAN&BUSHWIC	W 0 - 1/8 (0.048 mi.)	B7	35
Program Number: 8903546				
Spill Number/Closed Date: 8903546 / 7/10/1989				
Site ID: 252968				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
25 BUSHWICK AVE	25 BUSHWICK AVE	SW 0 - 1/8 (0.052 mi.)	12	39
Program Number: 9512040				
Spill Number/Closed Date: 9512040 / 7/4/1999				
Site ID: 134902				
AMOCO SVCE STA	***2 BUSHWICK AVE.***	***W 0 - 1/8 (0.052 mi.)***	***B13***	***40***
Program Number: 8900824				
Spill Number/Closed Date: 8900824 / 4/30/1991				
Site ID: 182085				
J & M AUTO REPAIRS	***881-885 GRAND ST***	***SE 1/8 - 1/4 (0.194 mi.)***	***W89***	***202***
Program Number: 8901284				
Spill Number/Closed Date: 8901284 / 7/21/2008				
Site ID: 92038				
WILLIAMSBURG HOUSES	***188 TEN EYCK WALK***	***SSW 1/4 - 1/2 (0.298 mi.)***	***150***	***380***
Program Number: 9802239				
Spill Number/Closed Date: 9802239 / 2/12/2010				
Site ID: 77200				
WILLIAMSBURG	144 MAUJER ST & GRAH	SSW 1/4 - 1/2 (0.313 mi.)	AQ152	385
Program Number: 8809821				
Spill Number/Closed Date: 8809821 / 12/4/1992				
Site ID: 304525				
151 MAUJER ST	151 MAUJER STREET	SW 1/4 - 1/2 (0.316 mi.)	AQ153	386
Program Number: 9414176				
Spill Number/Closed Date: 9414176 / 2/28/2003				
Site ID: 233375				
WILLIAMSBURG HOUSES	***128 MAUJER STREET***	***SW 1/4 - 1/2 (0.339 mi.)***	***156***	***388***
Program Number: 9305275				
Program Number: 9314699				
Program Number: 9104201				
Spill Number/Closed Date: 9305275 / Not Reported				
Spill Number/Closed Date: 9314699 / 3/23/1994				
Spill Number/Closed Date: 9104201 / 4/27/1995				
Site ID: 121683				
Site ID: 131045				
Site ID: 128131				
WILLIAMSBURGH HOUSES	***211 STAGG WALK***	***S 1/4 - 1/2 (0.341 mi.)***	***158***	***404***
Program Number: 9110920				
Spill Number/Closed Date: 9110920 / 1/22/1992				
Site ID: 187016				
INTERMEDIATE SCHOOL	***223 GRAHAM AVENUE***	***SSW 1/4 - 1/2 (0.345 mi.)***	***159***	***412***
Program Number: 0411168				
Program Number: 9711161				
Spill Number/Closed Date: 0411168 / 12/19/2005				
Spill Number/Closed Date: 9711161 / 3/14/2005				
Site ID: 336264				
Site ID: 128139				
WILLIAMSBURG HOUSES	***125 STAGG WALK***	***SSW 1/4 - 1/2 (0.426 mi.)***	***182***	***443***
Program Number: 9810259				
Program Number: 9810261				
Program Number: 9811727				
Program Number: 9811227				
Spill Number/Closed Date: 9810259 / 1/8/2004				
Spill Number/Closed Date: 9810261 / 1/8/2004				
Spill Number/Closed Date: 9811727 / 3/29/1999				
Spill Number/Closed Date: 9811227 / 12/2/2005				
Site ID: 204507				
Site ID: 204508				
Site ID: 204509				
Site ID: 187018				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 0003338 Program Number: 0003338 Spill Number/Closed Date: 0003338 / 4/10/2003 Site ID: 202905	232 MESROLE ST	S 1/4 - 1/2 (0.440 mi.)	185	476
COMMERCIAL PROPERTY Program Number: 0300112 Spill Number/Closed Date: 0300112 / 3/24/2004 Site ID: 80495	***1-7 BUSHWICK PLACE***	***SSE 1/4 - 1/2 (0.449 mi.)***	***190***	***481***
ALBERTS PLATING WORK Program Number: 0510292 Spill Number/Closed Date: 0510292 / 1/25/2006 Site ID: 356241	***32 BEADEL ST***	***N 1/4 - 1/2 (0.462 mi.)***	***195***	***503***

Lower Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Program Number: 0409577 Spill Number/Closed Date: 0409577 / 2/4/2005 Site ID: 334346	***243 JACKSON STREET***	***N 1/8 - 1/4 (0.170 mi.)***	***S63***	***139***
COOPER PARK -NYCHA Program Number: 9414384 Program Number: 9515713 Program Number: 9515837 Program Number: 9414271 Spill Number/Closed Date: 9414384 / 3/29/1996 Spill Number/Closed Date: 9515713 / 9/14/2009 Spill Number/Closed Date: 9515837 / 6/10/2008 Spill Number/Closed Date: 9414271 / 3/29/1996 Site ID: 64539 Site ID: 250035 Site ID: 250036 Site ID: 315998	***295 JACKSON ST***	***NNE 1/8 - 1/4 (0.223 mi.)***	***AG117***	***288***
308 MAUJER ST Program Number: 0305120 Spill Number/Closed Date: 0305120 / 1/31/2006 Site ID: 144741	308 MAUJER ST	SE 1/4 - 1/2 (0.272 mi.)	149	379
JOESEPH LOWESTEIN AN Program Number: 9704885 Spill Number/Closed Date: 9704885 / 8/16/2003 Site ID: 209407	***420 MORGAN AVE***	***NE 1/4 - 1/2 (0.341 mi.)***	***AS157***	***398***
345 TENEYCK STREET Program Number: 9210082 Spill Number/Closed Date: 9210082 / 12/1/1992 Site ID: 300237	345 TENEYCK STREET	SE 1/4 - 1/2 (0.351 mi.)	160	421
ABANDONED BLDG Program Number: 0203790 Spill Number/Closed Date: 0203790 / 6/4/2003 Site ID: 331139	430 MORGAN AVE	NE 1/4 - 1/2 (0.354 mi.)	AS162	423
APARTMENT BUILDING Program Number: 0601731 Spill Number/Closed Date: 0601731 / 8/29/2006 Site ID: 364030	35 MEADOW STREET	SE 1/4 - 1/2 (0.377 mi.)	165	425

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
GREEN HILL Program Number: 0302094 Spill Number/Closed Date: 0302094 / 1/31/2006 Site ID: 191858	2 REWE ST & 300 VAND	E 1/4 - 1/2 (0.400 mi.)	168	429
EASTERN TRANSFER OF Program Number: 0009585 Program Number: 9312206 Spill Number/Closed Date: 0009585 / 8/28/2003 Spill Number/Closed Date: 9312206 / 1/17/1994 Site ID: 302888 Site ID: 302889	***222 MORGAN AVE***	***ESE 1/4 - 1/2 (0.414 mi.)***	***AX175***	***433***
CLOSED-LACKOF RECENT Program Number: 8802460 Spill Number/Closed Date: 8802460 / 3/5/2003 Site ID: 183945	1105 METROPOLITAN AV	E 1/4 - 1/2 (0.416 mi.)	AY180	440
1101 METROPOLITAN AV Program Number: 9800642 Spill Number/Closed Date: 9800642 / 5/17/2006 Site ID: 190461	1101 METROPOLITAN AV	E 1/4 - 1/2 (0.425 mi.)	AY181	441
MOBIL OIL CORP SS #F Program Number: 9007766 Spill Number/Closed Date: 9007766 / Not Reported Site ID: 59273	***550 HUMBOLDT ST***	***NNW 1/4 - 1/2 (0.427 mi.)***	***183***	***450***
APT BUILDING TANK Program Number: 0504662 Spill Number/Closed Date: 0504662 / 12/9/2005 Site ID: 349596	85 MEADOW STREET	ESE 1/4 - 1/2 (0.437 mi.)	184	475
GAS STATION/ 278 FUE Program Number: 0310672 Spill Number/Closed Date: 0310672 / 12/16/2003 Site ID: 246017	***392 LEONARD ST***	***NW 1/4 - 1/2 (0.462 mi.)***	***194***	***498***
UNITED AMBULETTE Program Number: 0410348 Spill Number/Closed Date: 0410348 / 5/3/2005 Site ID: 335249	495 GRAHAM AVE	NW 1/4 - 1/2 (0.480 mi.)	200	577
APT COMPLEX Program Number: 0300325 Spill Number/Closed Date: 0300325 / 3/24/2004 Site ID: 117954	349 SCHOLES ST	SE 1/4 - 1/2 (0.494 mi.)	201	578
64 FROST ST Program Number: 9601530 Spill Number/Closed Date: 9601530 / 8/5/2010 Site ID: 261281	***64 FROST STREET***	***WNW 1/4 - 1/2 (0.494 mi.)***	***202***	***580***
MOST HOLY TRINITY RE Program Number: 0306650 Spill Number/Closed Date: 0306650 / 8/25/2006 Site ID: 131344	***157 GRAHAM AVE***	***SSW 1/4 - 1/2 (0.500 mi.)***	***205***	***589***

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 03/30/2015 has revealed that there are 16 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERIT METROPOLITAN Id/Status:: 2-297410	***810 METROPOLITAN AVE***	***W 0 - 1/8 (0.044 mi.)***	***B4***	***13***
SHELL SERVICE STATIO Id/Status:: 2-190411	2 BUSHWICK AVENUE	W 0 - 1/8 (0.052 mi.)	B14	56
JENNINGS HALLL HDFC Id/Status:: 2-608986	260 POWERS STREET	SSE 1/8 - 1/4 (0.131 mi.)	K49	115
326 GRAHAM AVE Id/Status:: 2-608719	326 GRAHAM AVENUE	WSW 1/8 - 1/4 (0.174 mi.)	67	147
885 GRAND STREET COR Id/Status:: 2-478075	881-5 GRAND ST	SE 1/8 - 1/4 (0.194 mi.)	W87	196
GLOVEMAN REALTY CORP Id/Status:: 2-329800	***294 GRAHAM AVENUE***	***SW 1/8 - 1/4 (0.213 mi.)***	***AD105***	***246***
WILLIAMSBURG Id/Status:: 2-602348	***200 MAUJER STREET***	***S 1/8 - 1/4 (0.244 mi.)***	***AN142***	***362***
CHASE BANK Id/Status:: 2-601850	726 GRAND STREET	SW 1/8 - 1/4 (0.250 mi.)	AP147	376

Lower Elevation	Address	Direction / Distance	Map ID	Page
ST FRANCIS OF PAOLA Id/Status:: 2-316393	***219 CONSELYEA STREET***	***NW 0 - 1/8 (0.086 mi.)***	***23***	***75***
RALPH'S AUTO CENTER Id/Status:: 2-608757	885 GRAND STREET	SE 1/8 - 1/4 (0.196 mi.)	W91	206
900 GRAND ST. MILK L Id/Status:: 2-610024	900 GRAND STREET	SE 1/8 - 1/4 (0.206 mi.)	AB100	222
COOPER PARK HOUSES Id/Status:: 2-474630	295 JACKSON STREET	NNE 1/8 - 1/4 (0.223 mi.)	AG116	285
SAFEGUARD SELF STORA Id/Status:: 2-321257	***916 GRAND STREET***	***SE 1/8 - 1/4 (0.224 mi.)***	***AF121***	***298***
KINGSLAND SERVICE ST Id/Status:: 2-070270 Id/Status:: 2-157392	***51 KINGSLAND AVENUE***	***N 1/8 - 1/4 (0.224 mi.)***	***AI122***	***303***
J&G AUTO SHOP Id/Status:: 2-610457	921 GRAND STREET	ESE 1/8 - 1/4 (0.230 mi.)	AF130	345
GCS SERVICE INC. Id/Status:: 2-602621	***932 GRAND STREET***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AO143***	***366***

EXECUTIVE SUMMARY

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 2 NY MOSF UST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MORGAN OIL TERMINALS	***200 MORGAN AVE***	***ESE 1/4 - 1/2 (0.464 mi.)***	***BB196***	***507***
BAYSIDE FUEL OIL DEP	***1100 GRAND STREET***	***E 1/4 - 1/2 (0.465 mi.)***	***BC199***	***567***

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 03/30/2015 has revealed that there are 18 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SHELL SERVICE STATIO Facility Id: 2-190411	2 BUSHWICK AVENUE	W 0 - 1/8 (0.052 mi.)	B15	66
NYS TAXI NETWORK INC Facility Id: 2-611088	801 METROPALITAN AVE	W 0 - 1/8 (0.090 mi.)	E24	78
JP MORGAN CHASE AND Facility Id: 2-601809	819 GRAND STREET	S 1/8 - 1/4 (0.182 mi.)	V73	159
FRANK LOVISI Facility Id: 2-160180	***308 GRAHAM AVE***	***WSW 1/8 - 1/4 (0.188 mi.)***	***83***	***190***
EASTERN DISTRICT HIG Facility Id: 2-355623	***850 GRAND ST***	***SSE 1/8 - 1/4 (0.217 mi.)***	***109***	***255***
755 REALTY CORP. Facility Id: 2-608530	753 GRAND STREET	SSW 1/8 - 1/4 (0.217 mi.)	110	277
231 MAUJER STREET Facility Id: 2-466727	***231 MAUJER STREET***	***S 1/8 - 1/4 (0.235 mi.)***	***134***	***350***
WILLIAMSBURG Facility Id: 2-602348	***200 MAUJER STREET***	***S 1/8 - 1/4 (0.244 mi.)***	***AN142***	***362***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LEROS REALTY CORP Facility Id: 2-340804	***850 METROPOLITAN AVE***	***E 0 - 1/8 (0.037 mi.)***	***A2***	***9***
SKILL-MAN CONTRACTIN Facility Id: 2-608653	244 SKILLMAN AVENUE	N 0 - 1/8 (0.115 mi.)	I37	98
TWO BROTHERS AUTO SA Facility Id: 2-607573	193 WOODPOINT ROAD	NNW 0 - 1/8 (0.115 mi.)	J39	100
ST. FRANCIS OF PAOLA Facility Id: 2-201014	195-201 CONSELYEA ST	WNW 0 - 1/8 (0.116 mi.)	G40	102
ST NICHOLAS R C CHUR Facility Id: 2-241253	***26 OLIVE ST***	***SE 1/8 - 1/4 (0.144 mi.)***	***53***	***120***
CORMEN ENTERPRISES I Facility Id: 2-305596	953 METROPOLITAN AVE	E 1/8 - 1/4 (0.191 mi.)	T85	194

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRICKMER REALTY CORP Facility Id: 2-374431	722 METROPOLITAN AVE	W 1/8 - 1/4 (0.205 mi.)	98	215
ST NICHOLAS H S BUIL Facility Id: 2-241261	***11-29 CATHERINE ST***	***ESE 1/8 - 1/4 (0.216 mi.)***	***AE107***	***251***
AMERICAN WOOD COLUMN Facility Id: 2-325546	***913 GRAND ST***	***SE 1/8 - 1/4 (0.223 mi.)***	***AF115***	***281***
SAFEGUARD SELF STORA Facility Id: 2-321257	***916 GRAND STREET***	***SE 1/8 - 1/4 (0.224 mi.)***	***AF121***	***298***

NY MOSF AST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF AST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP Facility Status: 1 Facility Status: 4	***1100 GRAND STREET***	***E 1/4 - 1/2 (0.465 mi.)***	***BC199***	***567***

NY MOSF: These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

A review of the NY MOSF list, as provided by EDR, and dated 03/30/2015 has revealed that there are 2 NY MOSF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYC DEP HAZ MAT Tank Status: Inactive Facility Id: 2-1500	***200 MORGAN AVENUE***	***ESE 1/4 - 1/2 (0.464 mi.)***	***BB197***	***521***
BAYSIDE FUEL OIL DEP Tank Status: Active Facility Id: 2-1280	***1100 GRAND STREET***	***E 1/4 - 1/2 (0.465 mi.)***	***BC198***	***562***

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/18/2015 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY Site Code: 407689	***202-218 MORGAN AVENU***	***ESE 1/4 - 1/2 (0.460 mi.)***	***BB191***	***484***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 05/18/2015 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY Site Code: 407689	***202-218 MORGAN AVENU***	***ESE 1/4 - 1/2 (0.460 mi.)***	***BB191***	***484***

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/18/2015 has revealed that there are 4 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER BENNETT TRUCK Site Code: 485965	***845 GRAND STREET***	***SSE 1/8 - 1/4 (0.177 mi.)***	***68***	***149***
FORMER SCIENTIFIC FI Site Code: 487645 Site Code: 468207	***871 GRAND STREET***	***SE 1/8 - 1/4 (0.188 mi.)***	***W78***	***167***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY Site Code: 407689	***202-218 MORGAN AVENU***	***ESE 1/4 - 1/2 (0.460 mi.)***	***BB191***	***484***
555 GRAND STREET Site Code: 489692	***555 GRAND STREET***	***WSW 1/4 - 1/2 (0.498 mi.)***	***203***	***587***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Registered Storage Tanks

NY HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 4 NY HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GLOVEMAN REALTY CORP Facility Status: 1 PBS Number: 2-329800 Tank Status: 1	***294 GRAHAM AVENUE***	***SW 1/8 - 1/4 (0.213 mi.)***	***AD105***	***246***
DIME SAVINGS BANK Facility Status: 1 PBS Number: 2-601850 Tank Status: 1	726 GRAND STREET	SW 1/8 - 1/4 (0.250 mi.)	AP148	377

Lower Elevation	Address	Direction / Distance	Map ID	Page
ST FRANCIS OF PAOLA	***219 CONSELYEA STREET***	***NW 0 - 1/8 (0.086 mi.)***	***23***	***75***
Facility Status: 1				
PBS Number: 2-316393				
Tank Status: 1				
GCS SERVICE INC.	***932 GRAND STREET***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AO143***	***366***
Facility Status: 2				
PBS Number: 2-602621				
Tank Status: 4				

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/18/2015 has revealed that there are 11 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERIT METROPOLITAN	***810 METROPOLITAN AVE***	***W 0 - 1/8 (0.044 mi.)***	***B4***	***13***
Site ID: 158142				
Site ID: 158144				
Spill Number/Closed Date: 9502757 / 5/6/2013				
Spill Number/Closed Date: 8807632 / 12/18/1988				
spillno: 8807632				
spillno: 9502757				
MERIT S/S / BKLN	METROPOLITAN & BUSHW	W 0 - 1/8 (0.051 mi.)	B11	38
Site ID: 243418				
Spill Number/Closed Date: 8909052 / 12/14/1989				
spillno: 8909052				
AMOCO SVCE STA	***2 BUSHWICK AVE.***	***W 0 - 1/8 (0.052 mi.)***	***B13***	***40***
Site ID: 182084				
Site ID: 359980				
Site ID: 274225				
Site ID: 274226				
Spill Number/Closed Date: 8901576 / 5/17/1989				
Spill Number/Closed Date: 0513496 / 2/28/2006				
Spill Number/Closed Date: 9110815 / 6/9/2005				
Spill Number/Closed Date: 0330060 / Not Reported				
spillno: 0330060				
spillno: 0513496				
spillno: 8901576				
spillno: 9110815				
SPILL NUMBER 0100018	50 BUSHWICK AVE	S 0 - 1/8 (0.091 mi.)	26	83
Site ID: 251983				
Site ID: 251984				
Spill Number/Closed Date: 0100016 / 4/2/2001				
Spill Number/Closed Date: 0100018 / 6/1/2004				
spillno: 0100016				
spillno: 0100018				

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
385 HUMBOLDT ST. Site ID: 210114 Spill Number/Closed Date: 9302207 / 4/25/1994 spillno: 9302207	385 HUMBOLDT ST	WNW 0 - 1/8 (0.103 mi.)	G30	89
S/S BREAKER LEAKED D Site ID: 396859 Spill Number/Closed Date: 0801005 / 5/19/2008 spillno: 0801005	324 AINSLIE ST. SUBS	SSW 0 - 1/8 (0.106 mi.)	H31	91
SOCCI RESIDENCE Site ID: 418147 Spill Number/Closed Date: 0905854 / 8/19/2009 spillno: 0905854	177 DEVOE ST	WSW 0 - 1/8 (0.125 mi.)	N45	109

Lower Elevation	Address	Direction / Distance	Map ID	Page
880 METROPOLITAN AVE Site ID: 278188 Spill Number/Closed Date: 9303810 / 6/24/1993 spillno: 9303810	880 METROPOLITAN AVE	E 0 - 1/8 (0.079 mi.)	D21	73
SPILL NUMBER 0201573 Site ID: 300829 Spill Number/Closed Date: 0201573 / 2/13/2003 spillno: 0201573	236 SKILLMAN AVE	N 0 - 1/8 (0.114 mi.)	I32	92
SANITATION COMPANY Site ID: 272280 Spill Number/Closed Date: 9903762 / 7/6/1999 spillno: 9903762	244 SKILLMAN AVE	N 0 - 1/8 (0.115 mi.)	I36	97
258 SKILLMAN ST Site ID: 153371 Spill Number/Closed Date: 0302151 / 5/30/2003 spillno: 0302151	***258 SKILLMAN ST***	***NNE 0 - 1/8 (0.123 mi.)***	***L43***	***107***

Other Ascertainable Records

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are 2 NY HSWDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUG, EQUITY WORKS Facility Id: HS2009	MASPETH AND MORGAN A	ENE 1/4 - 1/2 (0.310 mi.)	151	383
CITY BARREL	421 MEEKER STREET	NW 1/4 - 1/2 (0.415 mi.)	AW178	437

EXECUTIVE SUMMARY

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 05/01/2015 has revealed that there are 63 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERIT METROPOLITAN EPA ID: NYD982185720	***810 METROPOLITAN AVE***	***W 0 - 1/8 (0.044 mi.)***	***B4***	***13***
CON EDISON EPA ID: NYP004531489	813 METROPOLITAN AVE	WNW 0 - 1/8 (0.045 mi.)	B5	33
CON EDISON EPA ID: NYP004739090	807 METROPOLITAN AVE	WNW 0 - 1/8 (0.051 mi.)	B8	36
AMOCO SVCE STA EPA ID: NYD987001849	***2 BUSHWICK AVE.***	***W 0 - 1/8 (0.052 mi.)***	***B13***	***40***
CON EDISON EPA ID: NYP004551297	OPP 3 MASPETH AVE	WNW 0 - 1/8 (0.080 mi.)	E22	74
CON EDISON EPA ID: NYP004645156	298 AINSLIE ST	SW 0 - 1/8 (0.114 mi.)	H33	93
CON EDISON EPA ID: NYP004611257	298 AINSLIE ST	SW 0 - 1/8 (0.114 mi.)	H34	95
CON EDISON SERVICE B EPA ID: NYP004452728	***16 JUDGE ST***	***SSE 0 - 1/8 (0.120 mi.)***	***K41***	***105***
CON EDISON EPA ID: NYP004584215	FO 764 METROPOLITAN	W 1/8 - 1/4 (0.130 mi.)	O48	114
CON EDISON EPA ID: NYP004639126	180 DEVOE ST	WSW 1/8 - 1/4 (0.149 mi.)	N55	124
CON EDISON EPA ID: NYP004539126	180 DEVOE ST	WSW 1/8 - 1/4 (0.149 mi.)	N56	125
GATTI CLEANERS EPA ID: NYD982743981	***334 GRAHAM AVE***	***W 1/8 - 1/4 (0.160 mi.)***	***Q59***	***127***
CON EDISON SERVICE B EPA ID: NYP004372058	***327 GRAHAM AVE***	***WSW 1/8 - 1/4 (0.173 mi.)***	***Q64***	***144***
NYNEX EPA ID: NYP000921718	BUSHWICK AVE & GRAND	S 1/8 - 1/4 (0.183 mi.)	V74	161
CON EDISON SERVICE B EPA ID: NYP004445862	***812 GRAND ST***	***S 1/8 - 1/4 (0.186 mi.)***	***V77***	***165***
RHEE & NURYS DRY CLE EPA ID: NYD982271769	***802 GRAND ST***	***S 1/8 - 1/4 (0.188 mi.)***	***X80***	***170***
SCIENTIFIC FIRE PREV EPA ID: NYR000206813	***871 GRAND ST***	***SE 1/8 - 1/4 (0.188 mi.)***	***W82***	***182***
J & M AUTO REPAIRS EPA ID: NYD986936649	***881-885 GRAND ST***	***SE 1/8 - 1/4 (0.194 mi.)***	***W89***	***202***
GRAND CLEANERS EPA ID: NYR000033357	***765 GRAND ST***	***SSW 1/8 - 1/4 (0.207 mi.)***	***AA101***	***225***
CON EDISON EPA ID: NYP004516787	143 DEVOE ST	WSW 1/8 - 1/4 (0.207 mi.)	AC103	245
EASTERN DISTRICT HIG EPA ID: NY0001039668	***850 GRAND ST***	***SSE 1/8 - 1/4 (0.217 mi.)***	***109***	***255***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004626990	FO 133 DEVOE ST	WSW 1/8 - 1/4 (0.231 mi.)	AC131	347
CON EDISON EPA ID: NYP004590865	277 GRAHAM AV	SW 1/8 - 1/4 (0.233 mi.)	AM133	349
CON EDISON - MANHOLE EPA ID: NYP004345302	***276 HUMBOLDT ST***	***SSW 1/8 - 1/4 (0.247 mi.)***	***AN145***	***370***
LOT 43,TAXBLOCK 2783 EPA ID: NYP004582771 EPA ID: NYP004704433 EPA ID: NYP004704888	***725 GRAND STREET***	***SW 1/8 - 1/4 (0.248 mi.)***	***AM146***	***373***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004514055	13 ORIENT AVE	NE 0 - 1/8 (0.018 mi.)	1	8
CON EDISON EPA ID: NYP004709739	35 ORIENT AV	ENE 0 - 1/8 (0.045 mi.)	A6	34
CON EDISON EPA ID: NYP004519666	OPP 34 MASPETH AV	NNW 0 - 1/8 (0.058 mi.)	C17	69
CON EDISON EPA ID: NYP004748315	42 MASPETH AV	N 0 - 1/8 (0.063 mi.)	C18	70
CON EDISON EPA ID: NYP004728895	58-35 MASPETH AV	NNE 0 - 1/8 (0.078 mi.)	19	71
CON EDISON - MANHOLE EPA ID: NYP004324489	***890 METROPOLITAN AVE***	***E 0 - 1/8 (0.091 mi.)***	***D25***	***80***
CON EDISON SERVICE B EPA ID: NYP004479705	***253 DEVOE ST***	***ESE 0 - 1/8 (0.092 mi.)***	***F27***	***85***
CON EDISON SERVICE B EPA ID: NYP004329462	***892 METROPOLITAN AVE***	***E 0 - 1/8 (0.094 mi.)***	***D28***	***87***
CON EDISON EPA ID: NYP004526026	263 DEVOE STREET	ESE 0 - 1/8 (0.114 mi.)	F35	96
CON EDISON EPA ID: NYP004600003	FRONT OF 67 OLIVE ST	E 0 - 1/8 (0.123 mi.)	M44	108
CON EDISON - MANHOLE EPA ID: NYP004186011	***909 METROPOLITAN AVE***	***E 1/8 - 1/4 (0.126 mi.)***	***M46***	***110***
CON EDISON EPA ID: NYP004665121	FRONT OF 921 METROPO	E 1/8 - 1/4 (0.143 mi.)	P52	118
CON EDISON EPA ID: NYP004550364	FO 269 POWERS ST	SE 1/8 - 1/4 (0.146 mi.)	54	123
CON EDISON EPA ID: NYP004516795	925 METROPOLITAN AVE	E 1/8 - 1/4 (0.149 mi.)	P57	126
CON EDISON EPA ID: NYP004514030	231 JACKSON ST	N 1/8 - 1/4 (0.165 mi.)	61	137
CON EDISON EPA ID: NYP004542270	OPP 285 DEVOE ST	ESE 1/8 - 1/4 (0.169 mi.)	R62	138
CON EDISON EPA ID: NYP004544888	312 DEVOE ST	ESE 1/8 - 1/4 (0.174 mi.)	R66	146

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004517009	940 METROPOLITAN AV	E 1/8 - 1/4 (0.178 mi.)	T70	155
CON EDISON EPA ID: NYP004560975 EPA ID: NYP004628814	945 METROPOLITAN AVE	E 1/8 - 1/4 (0.179 mi.)	T71	156
CON EDISON EPA ID: NYP004505939	39 KINGSLAND AVE	NNE 1/8 - 1/4 (0.198 mi.)	Y92	208
NYCHA - COOPER PARK EPA ID: NYR000052753	***275 JACKSON ST***	***NNE 1/8 - 1/4 (0.202 mi.)***	***94***	***210***
CON EDISON EPA ID: NYP004605523	177 JACKSON ST	NW 1/8 - 1/4 (0.202 mi.)	Z95	212
CON EDISON EPA ID: NYP004576393	FO 177 JACKSON ST	NW 1/8 - 1/4 (0.202 mi.)	Z96	213
900 GRAND STREET MIL EPA ID: NYD986987600	***900 GRAND ST***	***SE 1/8 - 1/4 (0.206 mi.)***	***AB99***	***217***
CON EDISON EPA ID: NYP004712678	251 WITHERS ST	N 1/8 - 1/4 (0.215 mi.)	106	249
CON EDISON EPA ID: NYP004508925	267 WITHERS ST	N 1/8 - 1/4 (0.216 mi.)	108	254
CON EDISON EPA ID: NYP004542254	12 CATHERINE ST	ESE 1/8 - 1/4 (0.218 mi.)	AE111	279
CON EDISON EPA ID: NYP004529996	56 SHARON ST	ENE 1/8 - 1/4 (0.220 mi.)	113	280
CON EDISON EPA ID: NYP004619029 EPA ID: NYP004551776	FO 214 WITHERS ST	NNW 1/8 - 1/4 (0.223 mi.)	AH118	293
GRAND AUTO REPAIRS C EPA ID: NYR000055566	***916 GRAND ST***	***SE 1/8 - 1/4 (0.224 mi.)***	***AF119***	***295***
MOBIL OIL CO EPA ID: NYD986890556	***51 KINGSLAND AVE***	***N 1/8 - 1/4 (0.224 mi.)***	***AI123***	***327***
EVADA CLEANERS OF NY EPA ID: NYD004225660	***448 HUMBOLDT ST***	***NNW 1/8 - 1/4 (0.227 mi.)***	***AH126***	***331***
CON EDISON SERVICE B EPA ID: NYP004471900	***161 JACKSON ST***	***NW 1/8 - 1/4 (0.229 mi.)***	***AK129***	***343***
CON EDISON EPA ID: NYP004669115	FRONT OF 137 MASPETH	NE 1/8 - 1/4 (0.231 mi.)	AL132	348
NYCHA - COOPER PARK EPA ID: NYD986887594	***40 DEBEVOISE AVE***	***NE 1/8 - 1/4 (0.239 mi.)***	***138***	***355***
CON EDISON SERVICE B EPA ID: NYP004452249	***129 DEVOE***	***WSW 1/8 - 1/4 (0.240 mi.)***	***140***	***358***
CON EDISON SERVICE B EPA ID: NYP004330213	***143 MASPETH AVE***	***ENE 1/8 - 1/4 (0.244 mi.)***	***AL141***	***360***
CON EDISON EPA ID: NYP004538948	933 GRAND ST	ESE 1/8 - 1/4 (0.246 mi.)	AO144	369

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 05/01/2015 has revealed that there is 1 NJ MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID: NYP004186011	***909 METROPOLITAN AVE***	***E 1/8 - 1/4 (0.126 mi.)***	***M46***	***110***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 03/31/2015 has revealed that there are 4 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEW GATTI/PARK/LOUIS Facility Id: 2-6101-00992	334 GRAHAM AVENUE	W 1/8 - 1/4 (0.160 mi.)	Q60	137
RHEE & NURY'S/Y&Y CL Facility Id: 2-6101-00356	802 GRAND STREET	S 1/8 - 1/4 (0.188 mi.)	X81	182
GRAND CLEANERS Facility Id: 2-6101-01147	***765 GRAND ST***	***SSW 1/8 - 1/4 (0.207 mi.)***	***AA101***	***225***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUONOMO/GY LEE CLEAN Facility Id: 2-6101-00828	448 HUMBOLDT AVENUE	NNW 1/8 - 1/4 (0.227 mi.)	AH125	330

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 4 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EQUITY WORKS	MASPETH AND VANDERVO	ENE 1/4 - 1/2 (0.411 mi.)	169	431
SCHOLES ST. STATION	SCHOLES ST 7 BOGART	SE 1/4 - 1/2 (0.499 mi.)	204	589
GREENPOINT	287 MASPETH AVENUE	NE 1/2 - 1 (0.636 mi.)	BF213	631
WYTHE AVE. (BERRY ST	WYTHE AVE., BERRY ST	WNW 1/2 - 1 (0.962 mi.)	225	665

EXECUTIVE SUMMARY

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 23 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	810 METROPOLITAN AV	W 0 - 1/8 (0.044 mi.)	B3	12
Not reported	807 METROPOLITAN AV	WNW 0 - 1/8 (0.051 mi.)	B9	37
Not reported	5 BUSHWICK AVE	W 0 - 1/8 (0.051 mi.)	B10	37
Not reported	2 BUSHWICK AVE	W 0 - 1/8 (0.052 mi.)	B16	68
Not reported	383 HUMBOLDT ST	WNW 0 - 1/8 (0.100 mi.)	G29	89
Not reported	70 BUSHWICK AVE	S 1/8 - 1/4 (0.129 mi.)	47	114
Not reported	100 BUSHWICK AVE	S 1/8 - 1/4 (0.190 mi.)	V84	194
Not reported	881 GRAND ST	SE 1/8 - 1/4 (0.194 mi.)	W88	201
Not reported	283 GRAHAM AVE	SW 1/8 - 1/4 (0.221 mi.)	AD114	281

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	880 METROPOLITAN AV	E 0 - 1/8 (0.079 mi.)	D20	72
Not reported	193 WOODPOINT RD	NNW 0 - 1/8 (0.115 mi.)	J38	100
Not reported	221 SKILLMAN AVE	NNW 0 - 1/8 (0.120 mi.)	J42	106
Not reported	253 SKILLMAN AVE	N 1/8 - 1/4 (0.132 mi.)	L50	117
Not reported	177 SKILLMAN AVE	NW 1/8 - 1/4 (0.174 mi.)	65	146
Not reported	948 METROPOLITAN AV	E 1/8 - 1/4 (0.193 mi.)	T86	196
Not reported	885 GRAND ST	SE 1/8 - 1/4 (0.196 mi.)	W90	206
Not reported	900 GRAND ST	SE 1/8 - 1/4 (0.208 mi.)	AB104	246
Not reported	916 GRAND ST	SE 1/8 - 1/4 (0.224 mi.)	AF120	298
Not reported	51 KINGSLAND AVE	N 1/8 - 1/4 (0.224 mi.)	AI124	329
Not reported	972 METROPOLITAN AV	E 1/8 - 1/4 (0.229 mi.)	AJ128	343
Not reported	395 GRAHAM AVE	NW 1/8 - 1/4 (0.237 mi.)	AK135	354
Not reported	145 SKILLMAN AVE	WNW 1/8 - 1/4 (0.239 mi.)	137	355
Not reported	980 METROPOLITAN AV	E 1/8 - 1/4 (0.239 mi.)	AJ139	358

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 12 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	765 METROPOLITAN AV	W 1/8 - 1/4 (0.139 mi.)	O51	118
Not reported	334 GRAHAM AVE	W 1/8 - 1/4 (0.160 mi.)	Q58	127

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	802 GRAND ST	S 1/8 - 1/4 (0.188 mi.)	X79	170
Not reported	770 GRAND ST	SSW 1/8 - 1/4 (0.205 mi.)	AA97	214
Not reported	765 GRAND ST	SSW 1/8 - 1/4 (0.207 mi.)	AA102	244

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	251 JACKSON ST	NNE 1/8 - 1/4 (0.177 mi.)	S69	155
Not reported	362 GRAHAM AVE	WNW 1/8 - 1/4 (0.181 mi.)	U72	158
Not reported	368 GRAHAM AVE	WNW 1/8 - 1/4 (0.186 mi.)	U76	165
Not reported	380 GRAHAM AVE	WNW 1/8 - 1/4 (0.202 mi.)	93	209
Not reported	47 KINGSLAND AVE	N 1/8 - 1/4 (0.218 mi.)	Y112	280
Not reported	448 HUMBOLDT ST	NNW 1/8 - 1/4 (0.227 mi.)	AH127	342
Not reported	400 GRAHAM AVE	NW 1/8 - 1/4 (0.238 mi.)	AK136	354

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS: The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

A review of the NY RGA HWS list, as provided by EDR, has revealed that there are 9 NY RGA HWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER KLINK COSMO C	364 RICHARDSON STREE	NNE 1/4 - 1/2 (0.441 mi.)	AZ187	480
ACME STEEL/METAL WOR	95 LOMBARDY STREET	NNE 1/2 - 1 (0.593 mi.)	BE209	599
ACME STEEL/BRASS FOU	72 ANTHONY STREET	NNE 1/2 - 1 (0.684 mi.)	BH219	654

Lower Elevation	Address	Direction / Distance	Map ID	Page
K - GREENPOINT MGP -	287 MASPETH AVENUE	ENE 1/2 - 1 (0.526 mi.)	BD206	594
K - GREENPOINT MGP -	287 MASPETH AVE	ENE 1/2 - 1 (0.526 mi.)	BD207	594
BCF OIL REFINING, IN Facility ID: 224034	360 MASPETH AVENUE -	ENE 1/2 - 1 (0.639 mi.)	BG214	631
B.C.F. OIL REFINING, Facility ID: 224034	360 MASPETH AVENUE,	ENE 1/2 - 1 (0.639 mi.)	BG216	643
VARICK AVENUE Facility ID: 224017	165 VARICK AVENUE	ESE 1/2 - 1 (0.685 mi.)	BI220	654
FORMER SPIC AND SPAN	315 KINGSLAND AVENUE	N 1/2 - 1 (0.881 mi.)	BJ223	660

EXECUTIVE SUMMARY

NY RGA LF: The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

A review of the NY RGA LF list, as provided by EDR, has revealed that there are 10 NY RGA LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAGNUM BODY SHOP INC	185A MASPETH AVE	ENE 1/4 - 1/2 (0.334 mi.)	AR154	387
DURITE S&V & MAINT.	250 MORGAN AVE	ESE 1/4 - 1/2 (0.368 mi.)	AT163	424
COOPER TANK (222 MAS	222 MASPETH AVENUE	ENE 1/4 - 1/2 (0.395 mi.)	AU167	429
NEW TOWN AUTO SALES	1074 GRAND STREET	E 1/4 - 1/2 (0.414 mi.)	AV170	431
CLEAN VENTURE Facility ID: 24T76	222 MORGAN AVENUE	ESE 1/4 - 1/2 (0.414 mi.)	AX173	433
EASTERN TRANSFER OF	222 MORGAN AVE	ESE 1/4 - 1/2 (0.414 mi.)	AX174	433
NY MATERIALS REC (NY Facility ID: 24T76	222 MORGAN AVENUE	ESE 1/4 - 1/2 (0.414 mi.)	AX176	436
EASTERN TRANSFER Facility ID: 24T76	222 MORGAN AVENUE	ESE 1/4 - 1/2 (0.414 mi.)	AX177	436
FONTANA TRANSFER STA	252 MASPETH AVENUE	ENE 1/4 - 1/2 (0.443 mi.)	BA189	480
KARNAK (NEWTOWN META	202 MORGAN AVENUE	ESE 1/4 - 1/2 (0.460 mi.)	BB192	496

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 18 records.

Site Name	Database(s)
MTA NYCT - METROPOLITAN AVE STATIO	RCRA NonGen / NLR, NY MANIFEST
NYCDOT METROPOLITAN AVE BRG #22402	RCRA-SQG, NJ MANIFEST, NY MANIFEST
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
2 INGRAHAM STREET	NY SHWS, NY VCP, NY BROWNFIELDS
INGRAHAM STREET SIDEWALK PLUME TRA	NY SHWS
NORTH OF CORNISH KNIT GOODS	NY SHWS
KENT TERMINAL	NY SHWS, NY VCP
JONES MOTORS	NY SHWS
MEEKER AVENUE PLUME TRACKDOWN	NY SHWS
MORGAN OIL TERMINAL	NY SHWS
K - SCHOLES ST. STATION	NY SHWS, NY BROWNFIELDS
LOMBARDY ST	CERC-NFRAP
JONES MOTOR SITE	CERC-NFRAP
NYCDOT METROPOLITAN AVE BRG #22402	FINDS
MTA NYCT - METROPOLITAN AVE STATIO	FINDS
NYC DOT - METROPOLITAN AVE BRIDGE	FINDS
EQUITY WORKS	NY VCP
SCHOLES ST. STATION	NY VCP

OVERVIEW MAP - 04357835.2R



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 824 Metropolitan Ave ADDRESS: 824 Metropolitan Ave Brooklyn NY 11211 LAT/LONG: 40.7146 / 73.9411	CLIENT: EnviroBusiness, Inc. CONTACT: Production Manager INQUIRY #: 04357835.2r DATE: July 17, 2015 2:52 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 04357835.2R

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Pipelines
- 100-year flood zone
- 500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	824 Metropolitan Ave	CLIENT:	EnviroBusiness, Inc.
ADDRESS:	824 Metropolitan Ave Brooklyn NY 11211	CONTACT:	Production Manager
LAT/LONG:	40.7146 / 73.9411	INQUIRY #:	04357835.2r
		DATE:	July 17, 2015 2:56 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS	0.500		0	0	0	NR	NR	0
FEDERAL FACILITY	1.000		0	0	0	0	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		1	2	NR	NR	NR	3
RCRA-SQG	0.250		0	2	NR	NR	NR	2
RCRA-CESQG	0.250		0	2	NR	NR	NR	2
Federal institutional controls / engineering controls registries								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.125		0	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	2	9	NR	11
NY VAPOR REOPENED	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	8	NR	NR	8
State and tribal leaking storage tank lists								
NY LTANKS	0.500		4	3	26	NR	NR	33
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
NY TANKS	0.250		0	0	NR	NR	NR	0
NY UST	0.250		3	13	NR	NR	NR	16
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	2	NR	NR	2
NY AST	0.250		6	12	NR	NR	NR	18
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	1	NR	NR	1
NY MOSF	0.500		0	0	2	NR	NR	2
NY CBS	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY ENG CONTROLS	0.500		0	0	1	NR	NR	1
NY INST CONTROL	0.500		0	0	1	NR	NR	1
NY RES DECL	0.180		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY ERP	0.500		0	0	0	NR	NR	0
NY BROWNFIELDS	0.500		0	2	2	NR	NR	4
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		1	3	NR	NR	NR	4
NY HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
NY LIENS	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		11	NR	NR	NR	NR	11
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	2	NR	NR	2
NY UIC	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		18	45	NR	NR	NR	63
NJ MANIFEST	0.250		0	1	NR	NR	NR	1
NY DRYCLEANERS	0.250		0	4	NR	NR	NR	4
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY E DESIGNATION	TP		NR	NR	NR	NR	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	2	2	NR	4
EDR US Hist Auto Stat	0.250		8	15	NR	NR	NR	23
EDR US Hist Cleaners	0.250		0	12	NR	NR	NR	12
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	1.000		0	0	1	8	NR	9
NY RGA LF	0.500		0	0	10	NR	NR	10
- Totals --		0	52	116	61	20	0	249

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
NE
< 1/8
0.018 mi.
94 ft.

CON EDISON
13 ORIENT AVE
BROOKLYN, NY 11201

NY MANIFEST **S117059246**
N/A

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:

EPA ID:	NYP004514055
Country:	USA
Location Address 1:	13 ORIENT AVE
Location Address 2:	SB16350
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH ST
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2014
Trans1 Recv Date:	04/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004514055
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002418188GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117059246**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

A2 **LEROS REALTY CORP** **NY AST** **U003393652**
East **850 METROPOLITAN AVE** **NY HIST AST** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.037 mi.
194 ft. **Site 1 of 2 in cluster A**

Relative:
Lower

Actual:
35 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-340804
Program Type: PBS
UTM X: 589530.96427999996
UTM Y: 4507600.0603200002
Expiration Date: 10/14/2003
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 16475
Affiliation Type: Facility Owner
Company Name: LEO GROSS
Contact Type: Not reported
Contact Name: Not reported
Address1: 850 METROPOLITAN
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-8417
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 16475
Affiliation Type: Mail Contact
Company Name: LEO GROSS
Contact Type: Not reported
Contact Name: Not reported
Address1: 850 METROPOLITAN
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-8417
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 16475
Affiliation Type: On-Site Operator
Company Name: LEROS REALTY CORP

LEROS REALTY CORP (Continued) **U003393652**

Contact Type:	Not reported
Contact Name:	LEO GROSS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-8417
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	16475
Affiliation Type:	Emergency Contact
Company Name:	LEROS REALTY CORP
Contact Type:	Not reported
Contact Name:	LEO GROSS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-8417
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	31665
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN

LEROS REALTY CORP (Continued) **U003393652**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-340804
SWIS Code:	6101
Operator:	LEO GROSS
Facility Phone:	(718) 782-8417
Facility Addr2:	850 METROPOLITAN AVE
Facility Type:	MANUFACTURING
Emergency:	LEO GROSS
Emergency Tel:	(718) 782-8417
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	LEO GROSS
Owner Address:	850 METROPOLITAN
Owner City,St,Zip:	BROOKLYN, NY 11211
Federal ID:	Not reported
Owner Tel:	(718) 782-8417
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	LEO GROSS
Mailing Address:	850 METROPOLITAN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211
Mailing Telephone:	(718) 782-8417
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	12/21/1998
Expiration:	10/14/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND

LEROS REALTY CORP (Continued) **U003393652**

Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

B3 **EDR US Hist Auto Stat** **1015643131**
West **810 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.044 mi.
231 ft. **Site 1 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:

Name:	MERIT GASOLINE STATIONS
Year:	1999
Address:	810 METROPOLITAN AVE
Name:	MERIT GASOLINE STATIONS
Year:	2000
Address:	810 METROPOLITAN AVE
Name:	MERIT GAS STATIONS
Year:	2001
Address:	810 METROPOLITAN AVE
Name:	AMERADA HESS CORP
Year:	2003
Address:	810 METROPOLITAN AVE
Name:	AMERIDA HESS GAS STATION
Year:	2006
Address:	810 METROPOLITAN AVE
Name:	AMERIDA HESS GAS STATION
Year:	2007
Address:	810 METROPOLITAN AVE
Name:	AMERIDA HESS GAS STATION
Year:	2008

(Continued) **1015643131**

Address: 810 METROPOLITAN AVE

Name: HESS CORP
Year: 2009
Address: 810 METROPOLITAN AVE

Name: MERIT GASOLINE STATIONS
Year: 2010
Address: 810 METROPOLITAN AVE

Name: MERIT GASOLINE STATIONS
Year: 2011
Address: 810 METROPOLITAN AVE

Name: MERIT GASOLINE STATIONS
Year: 2012
Address: 810 METROPOLITAN AVE

B4 **MERIT METROPOLITAN** **RCRA NonGen / NLR** **1000263777**
West **810 METROPOLITAN AVE** **FINDS** **NYD982185720**
< 1/8 **BROOKLYN, NY 11211** **NY LTANKS**
0.044 mi. **NY UST**
231 ft. **Site 2 of 12 in cluster B** **NY MANIFEST**
NY Spills
Relative: **US AIRS**
Higher

Actual: **38 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MERIT OIL CORP
Facility address: 810 METROPOLITAN AVE
BROOKLYN, NY 112112515
EPA ID: NYD982185720
Mailing address: W LANCASTER AVE
HAVERFORD, NY 19041
Contact: Not reported
Contact address: W LANCASTER AVE
HAVERFORD, NY 19041
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MERIT OIL CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MERIT OIL CORP
Owner/operator address: NOT REQUIRED

MERIT METROPOLITAN (Continued) **1000263777**

NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MERIT OIL CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MERIT OIL CORP
Classification: Not a generator, verified

Date form received by agency: 05/11/1987
Site name: MERIT OIL CORP
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004415954

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

MERIT METROPOLITAN (Continued) **1000263777**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

LTANKS:

Site ID:	158143
Spill Number/Closed Date:	9404715 / 11/22/1994
Spill Date:	7/6/1994
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	11/22/1994
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	7/6/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/5/1994
Spill Record Last Update:	3/29/1995
Spiller Name:	Not reported
Spiller Company:	MERIT SERVICE STATION
Spiller Address:	810 METROPOLITAN AVENUE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	133692
DEC Memo:	Not reported
Remarks:	ISOLATE/RETEST

Material:

Site ID:	158143
Operable Unit ID:	998987
Operable Unit:	01
Material ID:	381316
Material Code:	0009

MERIT METROPOLITAN (Continued) **1000263777**

Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 158143
Spill Tank Test: 1542924
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

UST:
Id/Status: 2-297410 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 05/23/2015
UTM X: 589406.49727000005
UTM Y: 4507604.8834600002
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 13734
Affiliation Type: Facility Owner
Company Name: HESS RETAIL STORES LLC
Contact Type: AUTHORIZED REPRESENTATIVE
Contact Name: JASON S. CETEL
Address1: ONE HESS PLAZA
Address2: Not reported
City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (732) 750-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TMMOODY
Date Last Modified: 10/8/2014

Site Id: 13734
Affiliation Type: Mail Contact
Company Name: HESS RETAIL STORES LLC
Contact Type: Not reported
Contact Name: JIM HOWARD
Address1: ONE HESS PLAZA
Address2: Not reported

MERIT METROPOLITAN (Continued) **1000263777**

City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (732) 750-6220
EMail: JJHOWARD@SPEEDWAY.COM
Fax Number: Not reported
Modified By: MAPERSSO
Date Last Modified: 2/23/2015

Site Id: 13734
Affiliation Type: On-Site Operator
Company Name: HESS 32522
Contact Type: Not reported
Contact Name: SITE MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (732) 750-6000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/31/2013

Site Id: 13734
Affiliation Type: Emergency Contact
Company Name: HESS RETAIL STORES LLC
Contact Type: Not reported
Contact Name: JIM HOWARD
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (732) 750-6220
EMail: Not reported
Fax Number: Not reported
Modified By: TMMOODY
Date Last Modified: 10/8/2014

Tank Info:

Tank Number: 008
Tank ID: 49696
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 06/01/1995
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712

MERIT METROPOLITAN (Continued) **1000263777**

Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 08/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TMMOODY
Last Modified: 10/10/2014

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 009
Tank ID: 49697
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 06/01/1995
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 08/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TMMOODY
Last Modified: 10/10/2014

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

MERIT METROPOLITAN (Continued) **1000263777**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve

Tank Number:	010
Tank ID:	49698
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	06/01/1995
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	20
Date Test:	08/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TMMOODY
Last Modified:	10/10/2014

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	011
Tank ID:	49699
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	06/01/1995
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	20
Date Test:	08/01/1997
Next Test Date:	Not reported

MERIT METROPOLITAN (Continued) **1000263777**

Pipe Model: Not reported
Modified By: TMMOODY
Last Modified: 10/10/2014

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 012
Tank ID: 49700
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 06/01/1995
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 20
Date Test: 08/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TMMOODY
Last Modified: 10/10/2014

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

MERIT METROPOLITAN (Continued) **1000263777**

Tank Number:	013
Tank ID:	49701
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	600
Install Date:	06/01/1995
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	20
Date Test:	08/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TMMOODY
Last Modified:	10/10/2014

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
L00 - Piping Leak Detection - None

Tank Number:	06
Tank ID:	15684
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1979
Date Tank Closed:	06/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	09/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	05/29/2013

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None

MERIT METROPOLITAN (Continued) **1000263777**

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

Tank Number:	0P5
Tank ID:	15683
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	06/01/1979
Date Tank Closed:	02/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	10/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	1
Tank ID:	15679
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	06/01/1979
Date Tank Closed:	06/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	09/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported

MERIT METROPOLITAN (Continued) **1000263777**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 2
Tank ID: 15680
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1979
Date Tank Closed: 06/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 09/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 3
Tank ID: 15681
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1979
Date Tank Closed: 06/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

MERIT METROPOLITAN (Continued) **1000263777**

Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 07/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 4
Tank ID: 15682
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1979
Date Tank Closed: 06/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 09/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 6
Tank ID: 248539
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 600

MERIT METROPOLITAN (Continued) **1000263777**

Install Date:	06/01/1995
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TMMOODY
Last Modified:	10/10/2014

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve

Tank Number:	7
Tank ID:	15685
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/01/1979
Date Tank Closed:	06/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	01
Date Test:	07/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I01 - Overfill - Float Vent Valve

MERIT METROPOLITAN (Continued) **1000263777**

NY MANIFEST:

EPA ID:	NYD982185720
Country:	USA
Location Address 1:	810 METROPOLITAN AVENUE
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	MERIT OIL CORPORATION
Contact:	DOM DEBENEDICTIS
Address:	551 W LANCASTER AVENUE
City/State/Zip:	HAVERFORD, PA 19041
Country:	USA
Phone:	516-731-0036

Manifest:

Document ID:	PAE5165786
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PAAH0067
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/1995
Trans1 Recv Date:	11/30/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/01/1995
Part A Recv Date:	12/15/1995
Part B Recv Date:	02/27/1996
Generator EPA ID:	NYD982185720
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	PAD067098822
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

SPILLS:

Facility ID:	9502757
Facility Type:	ER
DER Facility ID:	133692
Site ID:	158144
DEC Region:	2
Spill Date:	6/5/1995
Spill Number/Closed Date:	9502757 / 5/6/2013
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	RJFENG

MERIT METROPOLITAN (Continued) **1000263777**

Referred To:	DENIED SPILL CLOSURE, RESPONSE BY11/2012
Reported to Dept:	6/5/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/13/1995
Spill Record Last Update:	5/6/2013
Spiller Name:	Not reported
Spiller Company:	HESS/MERIT
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SUN"10/28/2005: Project reassigned from Sun to Andersen. Reviewed the triannual report dated 8/19/2005, there is local contamination around MW-4. A stip needs to be sent out to begin remediation.12/6/05: Reviewed the tri-annual report dated 11/29/05. Three MW's sampled on October 11, 2005. Max BTEX is 2,318ppb (MW4) and max MTBE is 91 (MW2). Fluctuating concentrations. Sent RAP required letter.1/3/06: Spoke with Gail Russo of Quantum. I gave verbal approval for the RAP received. Installation for SVES/AS system scheduled for January 4-5, 2006.1/4/06: Letter with RAP approval mailed. SVE/AS data sheets are required to be submitted.1/26/06: 1/25/06 meeting with Quantum, NYSDEC, and ET. SVE/AS wells have been installed. Three short term SVE/AS events will be performed.5/19/06: Sent Gail Russo an email to followup on overdue update report.6/8/06: Received update report dated June 2, 2006. Three extended-period SVE/AS events performed in first third 2006. ORM socks installed in wells MW-2 and MW-4. Wells sampled on 2/24/2006. MAX BTEX 1,662 ppb (Mw4), max MTBE 447ppb (MW-2). Decreasing BTEX trend and slight increase in MTBE. Three additional extended-period SVE/AS events will be performed in the second third 2006, and new ORM socks installed. 7/5/06: Meeting on 6/28/06 with Hess, Quantum, NYSDEC, EnviroTrac and GSC. Short term SVE/AS is effective.8/29/06: Received update report dated 8/21/06. Short term SVE/AS on wells MW4, SVE1, AS1, AS2 on June 16 and June 22 2006. Groundwater sampled on June 29 2006. Max BTEX 16 (MW4), max MTBE 1,420 (MW2). ORM socks installed in MW2 and MW4 following the SVE/AS event on June 16 2006. Large decrease in BTEX in MW4. MW2 still shows significant MTBE contamination. Report states "concentrations in MW2 will continue to be evaluated to determine if these concentrations attenuate naturally or require remedial action". This site is on a triannual sampling plan. 1/17/07: Meeting on 1/16/07 with Hess, Delta, NYSDEC.1/23/07: Received update report. Wells sampled on 10/7/06. Max BTEX 156 ppb (MW4), max MTBE 523 ppb (MW2). ORC socks in MW 2 and 4. 4/26/07: Received update report. Wells sampled on 2/23/07. Max BTEX 175 ppb (MW4), max MTBE 690 ppb (MW2). ORC socks in use. 8/17/07: Reviewed update report. Wells sampled on 6/11/07. Max BTEX 295 ppb (MW4), max MTBE 110 ppb (MW2).

MERIT METROPOLITAN (Continued) **1000263777**

Two extended period portable sve/as events were conducted in June around MW4. ORC socks were installed in MW2 and MW4. Sent email requesting that air flow rate and effluent PID be measured when conducting portable SVE/AS events, and that the total petroleum recovered then be calculated.2/11/08: Reviewed August 2007 - November 2007 Site Status Report. Wells sampled on October 5, 2007. Max BTEX 350 ppb (MW4), max MTBE 100 ppb (MW2), benzene ND in all wells. No further action requested. 5/6/08 - Carlson: Reviewed first triannual 2008 update report dated April 28, 2008. Wells sampled on 2/12/08. Maximum BTEX concentration 96 ppb in MW4. Maximum MTBE concentration 2 ppb (MW2). ORC socks in use in MW2 and MW4. Meeting scheduled for 5/7/08.9/8/08 - Carlson: Reviewed August 2008 Update Report. Wells sampled on June 13, 2008. Low dissolved concentrations. Sent email to Hess/Envirotrac - remove ORC socks from MW-2 and MW-4. 9/15/08 - Carlson: Received email notification that ORC socks removed on 9/11/08.10/22/08 - Carlson: Meeting with Hess/Envirotrac. They have recent soil data from SVE/AS well installation. They will submit a petition for closure.1/8/09 - Carlson: Reviewed closure request dated 12/12/08. Three soil borings were completed. Impacted soil present in SB3. Delineation workplan required for soil borings/monitoring wells on Bushwick Avenue. (Wolf Bushwick Avenue site is directly downgradient). Workplan due 2/8/09.1/9/09 - Carlson: Reviewed update report. Low level groundwater impact remains.1/22/09 - Carlson: Approved workplan for the installation of two sidewalk wells.2/27/09 - Carlson: Received email request from Ed Russo to delay quarterly sampling by one month in order to include new wells. Report will be submitted in April as planned. Request approved.3/18/09 - Carlson: Meeting with Hess and Envirotrac. Delineation not possible due to subway. RAP will be submitted in April 2009. Quarterly gauging requested.5/7/09 - Carlson: Reviewed April 2009 update report. RAP overdue. Emailed John Schenkewitz about overdue report.5/11/09 - Carlson: Received email from Ed Russo, RAP will be submitted in August 2009.8/7/09 - Carlson: Reviewed update report. Low dissolved concentrations. Workplan to address residual soil impact will be submitted by end of the month.8/10/09 - Carlson: Received work plan for installation of four on-site wells.8/19/09 - Carlson: Meeting with Hess and Envirotrac. 8/27/09 - Carlson: Issued approval letter for installation of four on-site monitoring wells.11/17/09 - Carlson: Reviewed update report. Low dissolved concentrations. New wells were not installed yet.12/10/09 - Carlson: Reviewed second closure petition. Four additional confirmatory borings were installed. 1/27/2010 - Carlson: Meeting with Hess. NYSDEC to review case file internally.5/20/2010 - Carlson: Meeting with Hess. NYSDEC still requires additional borings around SB3.5/28/2010 - Carlson: Reviewed update report. Low dissolved concentrations.8/15/2010 - Carlson: Reviewed July 2010 update report. Low dissolved concentrations. Report states Hess to delineate after receipt of NYCTA permits. Delineation work plan was not submitted.8/31/11 - Obligado - I reviewed the 2Q11 report. BTEX is ND. They are still trying to get permit to do the soil delineation work.11/14/11 - Carlson: Reviewed October 2011 update report. Hess still waiting for permit approval from NYCTA for delineation.4/24/2012 - email from Joe Rennie of EnviroTrac "Please be advised that we are tentatively scheduled to conduct drilling at the above referenced location on Tuesday May 1, 2012 as per the attached NYSDEC approval letter. Please note that this project has been delayed due to New York City Transit Authority permitting requirements as this location is in close proximity to the

MERIT METROPOLITAN (Continued) **1000263777**

New York City subway system. As discussed previously with NYSDEC case managers Mark Tibbe and Sarah Carlson, Hess expects that if soil and groundwater sampling data from this drilling is favorable, that closure of NYSDEC spill # 95-02757 will be granted by NYSDEC. If you have any questions, please do not hesitate to contact me at (631) 924-3001."6/19/2012 - reviewed 1Q2012, 4/30/2012, by EnviroTrac. DTW 9.88' to 22.24' bg. Flows to southwest. 5 wells were sampled. MW-4, 4.4 ug/L BTEX, 8.3 ug/L MTBE. others are ND. Proposes to abandon monitoring wells MW-1, MW-2, MW-3 and MW-5. Next sampling event will be in 5/2012. 6/20/2012 - comments to Hess/EnviroTrac. 1) need to have the newly installed wells data in order to make the call whether or not to abandon the wells; 2) the requirement on the petition for closure: site use history; show all the investigation; show all the remediation; show all the remediation results; and the sensitive receptors information. reply form Edward Russo "thanks for getting back to us. The data from the newly completed soil borings/wells indicated positive results, so we are working on the request for closure now. The request for closure will incorporate your comments/requests below. You can disregard the request to abandon MWs 1, 2, 3, and 5. The closure request will be submitted to you within the next couple of weeks."7/18/2012 - reviewed the Request for Spill Closure Letter (the Letter) dated June 29, 2012, prepared by EnviroTrac Enviromental Services (EnviroTrac) on behalf of Hess Corporation (Hess). The Letter summarizes the Site's history and requests site closure. Denies the spill closure request due to the uninvestigated and unremediated residual contamination at the Site. see the letter for details on the required additional work to be done. Response by 8/20/2012. 10/4/2012 - Reviewed the response letter dated 8/20/2012 from Hess/EnviroTrac. Basically, they responded on DEC comments. The soil contamination is either infeasible to treat and the previous investigation has delineated the extent of the mentioned soil contamination location. Hess/EnviroTrac request for spill closure. 10/15/2012 - presented the case to the Section committee. Spill closure is denied based on: see the memo in eDoc for more details.1) Residual contaminated soil was present in the former remote fills area at depth of 2 feet below ground surface. Confirmatory soil samples are required. As-built drawing and utilities mark out map shall be provided to prove infeasibility to remediate the area. 2) The confirmatory soil boring SB-3 exhibits soil contamination exceeds CP-51 SCOs at depth of 29-30 feet. Additional remediation and confirmatory sampling shall be required. email to Hess/EnviroTrac requiring a work plan to address the above concerns/requirement by November 2012. 5/3/13-Vought-During Regional Spill Engineers meeting in Albany with DEC Hale and DEC Farrar, RSE and Paul John concurrence with email dated 4/24/13 from DEC Hale was confirmed regarding this site. As per email dated 4/24/13 from DEC Hale (with attached Powerpoint presentation) with cc to DEC Farrar, Ottoway and Regional Director and RSE, soil exceedences observed were moderate and further excavation is not warranted and spill closure is warranted due to: clean downgradient monitoring wells for numerous years; age of spill and fact that wells are have shown no increase in groundwater contamination for numerous years and as such there is no likelihood for downward migration of soil contamination through the soil column to the water table; excavation of UST systems and large amount of contaminated soil removed from site; Spills Database as an institutional control to account for possible future changes in site use as none reported to date; and addition of soil contamination

MERIT METROPOLITAN (Continued) **1000263777**

notification in Spill Closure Letter. This spill to be closed by Feng or to be closed by Vought after transfer to Vought by Feng.5/6/2013 - As per DEC Jeff Vought's directives, spill is closed.

Remarks: ODOR OF GASOLINE WHEN TANKS WERE UNCOVERED

Material:

Site ID:	158144
Operable Unit ID:	1013974
Operable Unit:	01
Material ID:	367814
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	8807632
Facility Type:	ER
DER Facility ID:	133692
Site ID:	158142
DEC Region:	2
Spill Date:	12/18/1988
Spill Number/Closed Date:	8807632 / 12/18/1988
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	12/18/1988
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	12/18/1988
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/19/1989
Spill Record Last Update:	8/24/2004
Spiller Name:	Not reported
Spiller Company:	DRIVER (PHILIP HALL)
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	SPEEDY DRY CREW ON THE WAY.

MERIT METROPOLITAN (Continued) **1000263777**

Material:

Site ID:	158142
Operable Unit ID:	923117
Operable Unit:	01
Material ID:	559519
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110004415954
Plant name:	MERIT METROPOLITAN
Plant address:	810 METROPOLITAN AVE BROOKLYN, NY 11222
County:	KINGS
Region code:	02
Dunn & Bradst #:	162426795
Air quality cntrl region:	043
Sic code:	5541
Sic code desc:	GASOLINE SERVICE STATIONS
North Am. industrial classf:	Not reported
NAIC code description:	Not reported
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1403
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1401
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1303
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1302

MERIT METROPOLITAN (Continued) **1000263777**

Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1402
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1304
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

B5
WNW
< 1/8
0.045 mi.
237 ft.

CON EDISON
813 METROPOLITAN AVE
BROOKLYN, NY 11211

Site 3 of 12 in cluster B

NY MANIFEST **S117060892**
N/A

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:

EPA ID:	NYP004531489
Country:	USA
Location Address 1:	813 METROPOLITAN AVE
Location Address 2:	SB 153222
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2014
Trans1 Recv Date:	05/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004531489
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002419008GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117060892**

Mgmt Method Type Code: H110

A6 **CON EDISON** **NY MANIFEST** **S117538308**
ENE **35 ORIENT AV** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.045 mi.
240 ft. **Site 2 of 2 in cluster A**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

EPA ID:	NYP004709739
Country:	USA
Location Address 1:	35 ORIENT AV
Location Address 2:	SB16351
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	12/29/2014
TSD Site Recv Date:	12/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709739
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002620201GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

CON EDISON (Continued) **S117538308**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

B7 **METROPOLITAN AVE/MERRIT** **NY LTANKS** **S102671408**
West **METROPOLITAN&BUSHWICK AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.048 mi.
255 ft. **Site 4 of 12 in cluster B**

Relative:
Higher

Actual:
39 ft.

LTANKS:
Site ID: 252968
Spill Number/Closed Date: 8903546 / 7/10/1989
Spill Date: 7/9/1989
Spill Cause: Tank Overfill
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Not reported
Cleanup Ceased: 7/10/1989
Cleanup Meets Standard: True
SWIS: 2401
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 7/9/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 7/11/1989
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: ISLAND TRANSPORTATION
Spiller Address: 5700 47TH STREET
Spiller City,St,Zip: MASPETH, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 207227
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN"07/10/89: NO ACTION REQUIRED OF DEC DUE TO SIZE OF SPILL.
Remarks: FIRE DEPT ON SCENE, SPILL CLEANED UP WITH SPEEDY DRY, REPORT CONFIRMEDWITH FIRE DEPT DISPATCHER.

Material:
Site ID: 252968
Operable Unit ID: 931040
Operable Unit: 01
Material ID: 447631
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported

METROPOLITAN AVE/MERRIT (Continued) **S102671408**

Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B8 **CON EDISON** **NY MANIFEST** **S117740729**
WNW **807 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.051 mi.
268 ft. **Site 5 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:

EPA ID:	NYP004739090
Country:	USA
Location Address 1:	807 METROPOLITAN AVE
Location Address 2:	SB 15322
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2015
Trans1 Recv Date:	02/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004739090
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117740729**

Year:	2015
Manifest Tracking Num:	002618768GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

B9 **EDR US Hist Auto Stat** **1015641847**
WNW **807 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.051 mi.
268 ft. **Site 6 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:

Name:	BROOKLYN CITY TRANSMISSIONS
Year:	1999
Address:	807 METROPOLITAN AVE
Name:	BROOKLYN CITY TRANSMISSIONS
Year:	2000
Address:	807 METROPOLITAN AVE
Name:	BROOKLYN CITY TRANSMISSIONS
Year:	2001
Address:	807 METROPOLITAN AVE
Name:	BROOKLYN CITY TRANSMISSION INC
Year:	2002
Address:	807 METROPOLITAN AVE
Name:	APPLE AUTO GROUP
Year:	2008
Address:	807 METROPOLITAN AVE

B10 **EDR US Hist Auto Stat** **1015520556**
West **5 BUSHWICK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.051 mi.
269 ft. **Site 7 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:

Name:	STAR RITE TRANSMISSIONS INCORPORATED
Year:	2000
Address:	5 BUSHWICK AVE
Name:	STAR RITE TRANSMISSIONS INC
Year:	2003
Address:	5 BUSHWICK AVE

(Continued) **1015520556**

Name: STAR RITE TRANSMISSIONS INC
Year: 2004
Address: 5 BUSHWICK AVE

Name: STAR RITE TRANSMISSIONS INC
Year: 2005
Address: 5 BUSHWICK AVE

B11 **MERIT S/S / BKLN** **NY Spills** **S102145594**
West **METROPOLITAN & BUSHWICK** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
269 ft. **Site 8 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

SPILLS:

Facility ID:	8909052
Facility Type:	ER
DER Facility ID:	199943
Site ID:	243418
DEC Region:	2
Spill Date:	12/14/1989
Spill Number/Closed Date:	8909052 / 12/14/1989
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	12/14/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	12/14/1989
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/2/1990
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	ISL TRANS
Spiller Address:	57-00 37 ST
Spiller City,St,Zip:	MASPETH, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	MECHANICAL FAILURE - DIESEL SPURTED OUT BECAUSE OF PRESSURE. TYREE TO CLEAN.(718)4762058. NO DIESEL IMPACT TO GROUNDWATER, CATCH BASIN CLEANED OUT BY ITC.

Material:

Site ID:	243418
Operable Unit ID:	934075
Operable Unit:	01
Material ID:	442231
Material Code:	0008

MERIT S/S / BKLN (Continued) **S102145594**

Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

12
SW
< 1/8
0.052 mi.
273 ft.

25 BUSHWICK AVE
25 BUSHWICK AVE
BROOKLYN, NY

NY LTANKS **S102673149**
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:

Site ID:	134902
Spill Number/Closed Date:	9512040 / 7/4/1999
Spill Date:	12/23/1995
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	12/23/1995
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/23/1995
Spill Record Last Update:	8/5/1999
Spiller Name:	BARBARA GUNSON
Spiller Company:	BAERENKLAU FUEL OIL
Spiller Address:	740 JAMAICA AVE
Spiller City,St,Zip:	BROOKLYN, NY 11208-
Spiller County:	001
Spiller Contact:	MR GONZALEZ
Spiller Phone:	(718) 456-1874
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	115831
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"
Remarks:	tank over fill onto concrete drive way-oil co on scenefor cleanup

Material:

Site ID:	134902

25 BUSHWICK AVE (Continued) **S102673149**

Operable Unit ID:	1022718
Operable Unit:	01
Material ID:	359360
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B13
West
< 1/8
0.052 mi.
274 ft.

Relative:
Higher

Actual:
38 ft.

AMOCO SVCE STA
2 BUSHWICK AVE.
BROOKLYN, NY 11211

Site 9 of 12 in cluster B

RCRA NonGen / NLR **1000693997**
FINDS **NYD987001849**
NY LTANKS
NY MANIFEST
NY Spills
US AIRS

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	SHELL OIL CO
Facility address:	2 BUSHWICK AVE BROOKLYN, NY 112112505
EPA ID:	NYD987001849
Mailing address:	JERICHO PLZ JERICHO, NY 11753
Contact:	Not reported
Contact address:	JERICHO PLZ JERICHO, NY 11753
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	SHELL OIL CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SHELL OIL CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212

AMOCO SVCE STA (Continued) **1000693997**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SHELL OIL CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: SHELL OIL CO
Classification: Not a generator, verified

Date form received by agency: 05/15/1992
Site name: SHELL OIL CO
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110001572227

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major

AMOCO SVCE STA (Continued) **1000693997**

redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

LTANKS:

Site ID:	182085
Spill Number/Closed Date:	8900824 / 4/30/1991
Spill Date:	4/26/1989
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	4/30/1991
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	4/26/1989
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/2/1989
Spill Record Last Update:	10/18/2004
Spiller Name:	Not reported
Spiller Company:	SHELL OIL
Spiller Address:	2 BUSHWICK AVENUE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	317029
DEC Memo:	Not reported
Remarks:	550 GALLON TANK FAILED TANK AUDITOR WITH A LEAK RATE OF .10GPH, WILL EXCAVATE & REPAIR & RETEST, POSSIBLE PIPE LEAK,DEC INVESTIGATED SITE.

Material:

Site ID:	182085
Operable Unit ID:	927385

AMOCO SVCE STA (Continued) **1000693997**

Operable Unit: 01
Material ID: 452150
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 182085
Spill Tank Test: 1535388
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

NY MANIFEST:
EPA ID: NYD987001849
Country: USA
Location Address 1: 2 BUSHWICK AVE
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: SHELL OIL COMPANY
Contact: BROOKS PERLEE
Address: ONE JERICHO PLAZA
City/State/Zip: JERICHO, NY 11753
Country: USA
Phone: 000-000-0000

Manifest:

Document ID: ARA5581280
Manifest Status: Completed copy
Trans1 State ID: PC936H245
Trans2 State ID: Not reported
Generator Ship Date: 06/18/1992
Trans1 Recv Date: 06/18/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 06/22/1992
Part A Recv Date: / /
Part B Recv Date: 07/03/1992
Generator EPA ID: NYD987001849

AMOCO SVCE STA (Continued) **1000693997**

Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID:	ARD069748192
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01462
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1992

SPILLS:

Facility ID:	8901576
Facility Type:	ER
DER Facility ID:	317029
Site ID:	274225
DEC Region:	2
Spill Date:	5/16/1989
Spill Number/Closed Date:	8901576 / 5/17/1989
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	2401
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	5/17/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	5/17/1989
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/30/1989
Spill Record Last Update:	3/1/2004
Spiller Name:	Not reported
Spiller Company:	SHELL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	RAIN WASHED PRODUCT INTO SEWER.

Material:

Site ID:	274225
Operable Unit ID:	927618
Operable Unit:	01
Material ID:	559461
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum

AMOCO SVCE STA (Continued) **1000693997**

Quantity:	20
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0513496
Facility Type:	ER
DER Facility ID:	317029
Site ID:	359980
DEC Region:	2
Spill Date:	2/22/2006
Spill Number/Closed Date:	0513496 / 2/28/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2/22/2006
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2/22/2006
Spill Record Last Update:	2/28/2006
Spiller Name:	ADAM WOLFE
Spiller Company:	AMACO GAS STATION
Spiller Address:	2 BUSHWICK AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	ADAM WOLFE
Contact Phone:	(516) 997-9300
DEC Memo:	Not reported
Remarks:	FAILED LINE TEST. YESTERDAY DISPENSER WAS HIT BY A CAR AND THEN DID A LINE TEST. THE LINE TEST WAS STOPPED DO TO DRIP BUT THE GASOLINE ONLY WENT INTO THE DISPENSER PAN. REPAIRS WILL BE DONE FIRST THING IN THE MORNING AND THEN A RETEST. UPDATED @ 15:22 2/22/2006

Material:

Site ID:	359980
Operable Unit ID:	1117170
Operable Unit:	01
Material ID:	2107651
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum

AMOCO SVCE STA (Continued) **1000693997**

Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9110815
Facility Type:	ER
DER Facility ID:	317029
Site ID:	274226
DEC Region:	2
Spill Date:	1/16/1992
Spill Number/Closed Date:	9110815 / 6/9/2005
Spill Cause:	Unknown
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1/17/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/6/1992
Spill Record Last Update:	6/9/2005
Spiller Name:	Not reported
Spiller Company:	SHELL OIL
Spiller Address:	ONE JERICHO PLAZA
Spiller City,St,Zip:	JERICHO, NY 11753-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "K FOLEY"SITE IS NOW AN AMOCO, OWNED NY WOLF PETROLEUM, PBS #2-1904112.DTW:22-24': GWF:NE. PRODUCT IN MW-2 AND MW-3.8/5/99 mtg: EnviroTrac will review and submit all historical data related to this site going back to the early 1990's. EnviroTrac will also review the contamination in well #3 and propose a clean up system (possibly biological)11/03 Reassigned from Sangesland to K Foley.11/20/03 E-mail from Steve Sangesland to Rob Rule: "It requires opening up a new spill for Amoco before closing out the old Shell spill case for the site. I believe Shell has made it's case that the present problem is due to Amoco's action, but Kerry will need to take action on it." 2/4/04 Spoke to Rob Rule. Requested he send actual historic concentration data. Data from post-1999 is indicative of a new release, however Shell needs to prove their case that concentrations were decreasing toward and close to groundwater standards. Rob

AMOCO SVCE STA (Continued) **1000693997**

indicated they have previously tried to come to an agreement with Wolf Petroleum but had no response.2/6/04 Received email from P. Sherwood, Phoenix Environmental. He attached copy of 6/6/03 letter to S. Sangesland requesting closure. Shell sold property to Wolf in April 1992. A product recovery pump and SVE system were operated by Shell from 1993 to 1994 to address residual hydrocarbons. Groundwater sampling continued until January 2000. Samples were collected and analyzed for VOCs and SVOCs in February 2003.From July 1990 to Februrary 1998, MTBE concentrations in on-site wells MW-2 and MW-4 ranged from non-detect to 986ppb.From Februrary 1999 to February 2003, MTBE concentrations in wells MW-2 and MW-4 ranged from 619ppb to 34,400ppb. Highest concentrations of MTBE in wells MW-2 and MW-4 were 34,400ppb and 23,300ppb, respectively.From 1990 to 1991, MTBE concentrations in MW-3 ranged from 24,400ppb to 26,000ppb. Product was detected intermittently in MW-3 from 1991 to 2003. On March 30, 1998 product was not present and a groundwater sample was collected with MTBE conc at 3,990ppb. In the most recent groundwater sampling results of MW-3, collected in 2000, MTBE ranged from 181,000ppb to 842,000ppb.In 1990 and 1991, groundwater samples were collected from MW-1 and analyzed for MTBE. Concentrations ranged from 1,600ppb to 24,000ppb. MW-1 was destroyed in 1993. MTBE concentrations in MW-1 appear to be a minor spike, localized to the tank field area. This is supported by the fact MTBE concentrations in downgradient well MW-2 ranged from 14ppb to 986ppb until 1999, when concentrations increased significantly.6/8/04 Meeting with Shell. They agreed to keep monitoring gw until legal issues have been resolved with Wolf for spill #0330060. DEC expects resolution in 6-12 months.11/23/04 Met with P. Sherwood, B. Hoashi(Phoenix) and R. Rule(Shell). Samples collected 8/30/04 showed 0.38' free product in MW-3. BTEX ranged from 3ppb(MW-2) to 20ppb(MW-4). MTBE from 18ppb(MW-2) to 251ppb(MW-4). Requesting closure due spill under new owner.See spill #0330060.

Remarks: PRODUCT IN SITE WELL MW3. WAS SULLIVAN SPILL. RE ASSIGNED TO MULQUEEN 4/18/95. SHELL ADDRESSING PROBLEM AT SITE, SEE FILE

Material:

Site ID:	274226
Operable Unit ID:	964669
Operable Unit:	01
Material ID:	415894
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	274226
Operable Unit ID:	964669
Operable Unit:	01
Material ID:	2096641
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported

AMOCO SVCE STA (Continued) **1000693997**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0330060
Facility Type: ER
DER Facility ID: 317029
Site ID: 182084
DEC Region: 2
Spill Date: 1/1/1999
Spill Number/Closed Date: 0330060 / Not Reported
Spill Cause: Unknown
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: adzhitom
Referred To: VEFR WILL BE CONDUCTED
Reported to Dept: 2/4/2004
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: 10/15/2004
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 2/4/2004
Spill Record Last Update: 4/7/2015
Spiller Name: CARY WOLF
Spiller Company: WOLF PETROLEUM
Spiller Address: 125 JERICHO TURNPIKE
Spiller City,St,Zip: JERICHO, NY 11753-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: 2/4/04 Spill date is estimated as occuring sometime in 1999, based upon data submitted by Shell's consultant, Phoenix Environmental. Summary:DTW 20-25'bgs. Flow east to northeast.7/90-2/98 MTBE concentrations in onsite wells MW-2 and MW-4 ranged from ND to 986ppb. 2/99-2/03 MTBE concentrations in wells MW-2 and MW-4 ranged from 619ppb to 34400ppb. The highest concentrations of MTBE in wells MW-2 and MW-4 were 34400ppb and 23300ppb respectively.From 1990 to 1991, concentrations in MW-3 ranged from 24,000ppb to 26,000ppb. Product was detected intermittently in well MW-3 from 1991 to 2003. On March 30, 1998 product was not present and a groundwater sample was collected with an MTBE concentration of 3990ppb. In 2000, MTBE concentrations in MW-3 ranged from 181,000ppb to 842,000ppb.From 1990 to 1991, concentrations in MW-1 ranged from 1600ppb to 24000ppb for MTBE. MW-1 was destroyed during construction in 1993. MTBE concentrations in MW-1 appear to be a minor spike, localized to the tank field area. This is supported by the fact that down gradient

AMOCO SVCE STA (Continued) **1000693997**

MW-2 ranged from 14 to 986ppb until 1999 when MTBE concentrations throughout the site increased significantly.2/13/04 Stipulation agreement faxed(516-997-3673) and mailed to Cary Wolf, Wolf Petroleum and B. Beck, National Environmental.2/13/04 Spoke with B. Beck. He expressed concern that Shell will not be held responsible for their spill. I explained that Shell spill #9110815 remains open. He will speak to Cary Wolf on Tuesday 2/17/04 and get back to me.4/21/04 Received letter from Mr. Wolf's attorney. Reluctant to execute a stipulation because "they have info suggesting the detection of increased MTBE is related to an upgradient, off-site discharge". There is a Hess station(810 Metropolitan, spill #9702757) but downgradient. Hess is possibly being affected by Amoco as per groundwater monitoring data from Hess from 2/04.4/22/04 Spoke to B. Beck. Requested they put deadline extension request in writing with deadline for signing stip.4/28/04 Received unsigned copy of letter from B. Beck. Report can be transmitted on or before June 4, 2004 assuming sampling is completed soon. Installation of upgradient wells may require more time. Will sample and survey all wells, possibly install upgradient wells, and complete FOIL process. Wish to arrange split sampling and gauging with Shell's consultant. Does not indicate when or if stipulation will be signed.4/29/04 Referred to Legal, D. Rubinton.9/29/04 Met with Barry Cohen(Certilman Balin Attorneys), Bruce Beck(consultant National Env.) with J. Rommel and L. Oliva. Wolf is taking responsibility for spill. B. Beck to send report by 10/1/04. To sign stip in interim of consent order. Changed stip to read 2 Bushwick Ave Corp(Wolf Petroleum) as the respondent. Emailed stip to B. Cohen. STIP due 10/6/04.10/8/04 Spoke to B. Cohen. He will be bringing stip over to Wolf for signature today.10/15/04 Received signed stip. Also received passing system test results(Crompco).10/19/04 Stip fully executed by T. Kunkel. Investigation summary report due 12/19/04.1/14/05 Received letter from B. Beck of partial completion of investigation which includes sample results for three wells. Results indicate BTEX from ND(MW-2,4) to 820ppb(MW-3). MTBE from 102ppb(MW-4) to 590ppb(MW-3). MW-1 has been destroyed.6/30/05 Received quarterly report. Sampled three wells(MW-2,3,4) in 4/05. BTEX from ND(MW-4) to 3.4ppb(MW-2). MTBE from 3ppb(MW-4) to 17ppb(MW-2). Report states that construction of MW-4 was rehabilitated to avoid a nearby self-serve car wash machine run-off from entering well. MW-3 is mounted in a 2'X2' manhole pit which collects run-off and is "oily". Trace "oily" product found in MW-3(0.3").1/31/06: Case reassigned to Andersen. Recent monitoring report overdue. MW-2 and MW-4 have low contaminant concentrations. MW-3 has 0.3 inches product. Sent Bruce Beck an email saying quarterly reports are overdue. He replied saying samples were just taken and he would send a report in approximately 4 weeks.3/13/06: Received letter from Bruce Beck saying a report will be submitted.5/19/06: Consent order meeting with Wolf scheduled for June 2 at 11am.6/8/06: Meeting with NYSDEC, Barry Cohen (Wolf's attorney's) and Bruce Beck (Wolf's consultant) regarding the consent order. Barry Cohen indicated that Sunoco may also be a responsible party. 7/10/06: Emailed Bruce Beck to set up a meeting to discuss deliverables required for consent order.7/13/06: Received update report dated 3/3/06. MW-4 was repaired. Groundwater samples collected on 1/30/06. MW-3 has a sheen, heavy oil staining, and a PVC pipe that connects it to MW-4 (probably used for recovery). Benzene 6.9 ppb in MW4. MTBE 73 in MW4. NEMA proposed: 1) clean all wells with Biosolve, 2) cleanout MW3 manway casing and seal well at top, 3) install a

AMOCO SVCE STA (Continued) **1000693997**

monitoring well in the location of former MW1, 4) sample wells quarterly (starting after Biosolve use. Approved proposed remedial methods.8/2/06: Meeting with Bruce Beck on 7/25/06 to discuss deliverables. Shell is also a potential responsible party for this spill. 9/28/06: Received email from Bruce Beck: "Why was Shell released from the spill?The numbers presented by them prior to the 'MTBE spike' were not near closure. The MTBE spike was a single event and the post spike concentrations returned to pre-spike concentrations immediately afterwards."1/11/07: Received update report. MW1 redrilled. MW3 cleaned with Biosolve. Wells sampled on 11/14/06. No product detected. Max BTEX 250 ppb (MW3), max MTBE 171 ppb (MW3). Quarterly sampling.5/1/07: Emailed Bruce Beck to followup on submission date for next report. 5/10/07: Left phone message for Bruce Beck to followup on overdue quarterly report.5/16/07: Reviewed update report. Wells sampled in February 2007. Trace LNAPL in MW3. Low dissolved concentrations in all wells. 8/6/07: Consent order effective 7/27/07. Update report due 10/25/07.9/12/07: Consent order modified, RAP due 10/27/07.2/28/08: Reviewed September 2007 - November 2007 Quarterly Monitoring Report dated January 10, 2008. VEFR conducted from MW 3 on November 14, 2008. 50 gallons recovered. Wells sampled on November 14, 2007. 0.05 ft LNAPL in MW3. Relatively low concentrations in other wells. Wells were gauged but groundwater flow direction was not determined.3/20/08 - Carlson: Meeting with Bruce Beck at 10am. A letter-report, titled Final report on Remedial Action, dated March 18, 2008, was submitted at the meeting. Groundwater samples were not collected, groundwater flow direction was not determined, and VEFR recovery volume and waste disposal manifests were not included. Continuation of weekly VEFR events was recommended.3/24/08 - Carlson: Reviewed report dated March 18, 2008. Report stated that weekly VEFR events have been conducted since Novemebr 17, 2007. However, no documentation on these events was provided in the report. Sent letter requiring documentation of VEFR events, quarterly groundwater sampling and gauging, and quarterly reporting. 5/8/08 - Carlson: Reviewed December 2007 - February 2008 Quarterly Monitoring Report dated March 31, 2008, received on May 7, 2008. Gauging and VEFR events were conducted once in November and December, three times in January, and twice in February. Trace product was found in MW3 in November, December, and February. Groundwater samples were collected on February 28, 2008. Maximum BTEX concentration was 3,380 ppb (MW3). Maximum MTBE concentration was 22 ppb (MW1). VEFR events will continue.7/24/08: Reviewed Quarterly Report dated June 20, 2008. Weekly gauging of all wells. A sheen was present in all wells at some point this quarter. Weekly VEFR upgraded to all wells. Wells sampled in May 2008. MW-3 not samples because a sheen was present. Low dissolved concentrations. Review effectiveness of VEFR.8/11/08 - Carlson: Reviewed report dated 8/8/08. Weekly VEFR ongoing. Sheen present in MW3 and MW 4 in June 2008. Groundwater sampling data was not included.8/20/08 - Carlson: Meeting on 8/19/08 with Bruce Beck and Tracy Wall. The Department requests additional delineation. Workplan due by 10/08.9/24/08 - Carlson: Reviewed Final Report dated 8/8/08.10/30/80 - Carlson: Reviewed June 2008 - August 2008 Quarterly Monitoring Report. Wells sampled on August 14, 2008. Sheen present in MW3 and MW4. Maximum BTEX concentration 189 ppb (MW1), maximum MTBE concentration 17 ppb (MW1). Weekly VEFR from MW3, and MW4 if necessary. Delineation workplan was not received.11/19/08 - Carlson: Meeting with NEMA. IP due by end of year.12/18/08 - Carlson: Received FOIL request for 95-02757, IP deadline extended to

AMOCO SVCE STA (Continued) **1000693997**

1/30/09 to allow for review of FOIL request.2/20/09 - Carlson: DEC Leung returned case file because FOIL officer did not get a response from NEMA.Reviewed Quarterly Report dated January 4, 2009. Wells gauged weekly. Weekly VEFR. Sheen present in every well throughout quarter. Groundwater flow direction was not indicated on the site plan. IP overdue.Received letter dated January 25, 2009 requesting reduction in VEFR from weekly to twice-monthly.2/23/09: Received request for extension from tracy wall. Replied how long of an extension she is requesting (it is already three weeks overdue, and they have had one extension already).4/8/09 - Carlson: Reviewed December 2008 - February 2009 Quarterly Report and Investigation Workplan dated March 22, 2009. Wells sampled on March 5, 2009. Sheen present in MW1 and MW2. Maximum BTEX concentration 254 ppb (MW3), maximum MTBE concentration 611 ppb (MW3). Weekly VEFR ongoing. Discuss effectivess of VEFR at the upcoming meeting. Investigation workplan proposes installation of two downgradient wells on Humbolt Street. Is it possible to install a well in the parking lot at 358 Humbolt Street? Left voice message for Tracy Wall.4/29/09 - Carlson: Met with Bruce Beck. He will pursue access agreement with owner of parking lot. Revised workplan due 5/30/09.6/3/09 - Carlson: Received email from Bruce Beck. Access agreement in progress. Extension needed for workplan submittal.7/2/09 - Carlson: Received email from Bruce Beck - access agreement will be sent to off-site owner.7/8/09 - Carlson: Reviewed March 2009 - May 2009 Quarterly Monitoring Report. Wells sampled on May 28, 2009. Weekly VEFR ongoing. Sheen in every well throughout quarter. Low dissolved concentrations.10/7/09 - Carlson: Received update report. LNAPL in MW 2,3,4. Weekly VEFR ongoing. Revised investigation plan overdue.10/13/09 - Carlson: Received email from Bruce Beck: sidewalk wells will be installed this week. Revised IP required for well in private parking lot, they are working on access to the private parking lot.11/18/2009 - Carlson: Meeting with Bruce Beck. IP for well installation overdue. RIR for sidewalk well installation due 1/30/2010. Wolf's attorney Barry Cohen will work on access for well installation in private parking lot. 1/7/2010 - Carlson: Approved extension for investigation and quarterly report submittal to 1/31/2010.2/11/2010 - Carlson: Received RIR. Two sidewalk wells are clean, but soil samples were not collected. Received email - they can go back and do soil borings to delineate soil. IP for well in private parking lot overdue. 2/17/2010 - Carlson: Portfolio review meeting with Bruce Beck. NYSDEC to issue letter requiring delineation work plan. 3/4/2010 - Carlson: Issued letter requiring delineation work plan for soil borings adjacent to monitoring wells MW5 and 6, and a proposed mw in private parking lot to the SW of the property. Due 4/5/2010.4/7/2010 - Carlson: Received cc of access request to adjacent property owner.4/20/2010 - Carlson: Reviewed update report and investigation work plan. 4/21/2010 - Carlson: Approved work paln for installation of one off-site monitoring well (in the adjacent private parking lot), and three soil borings. RIR due in 60 days.7/16/2010 - Carlson: Reviewed RIR and QMR. Three soil borings performed adjacent to MW's 3,5,6. Low level soil impact present in boring adjacent to MW3. Sheen present in MW3. Off-site soil boring in private parking lot was not installed. Weekly VEFR ongoing.1/14/11 - Obligado - I received a letter from Impact requesting monthly instead of weekly gauging, since product has not been encountered for the past 3 months. I approved this request.4/6/11 - Obligado - I reviewed the 1Q11 update report. BTEX concentrations of 16,760 ug/L were detected in MW3. No product

AMOCO SVCE STA (Continued) **1000693997**

detected. GW is 22 feet below grade. I reviewed some historical reports to gain information related to free product and subway tunnel. According to a 1990 Handex report, there is a subway easement in the northeast corner of the site. The bottom of the tunnel is 26 feet bgs. The top of the tunnel is approximately 7 feet below grade. Therefore the tunnel cuts across the water table and probably acts as a ground water barrier. The subway contains a sump-pump system for seepage along length of the tunnel and two pump stations located within the vicinity of the site. 9/27/11 - Obligado - I reviewed the 2Q11 update report. No product detected. 6201 ug/L BTEX in MW3. They recommend returning to quarterly gauging due to continued lack of product.Meeting held on 1/30/2012 with Christine Camardella and Kevin Kleaka of Impact Environmental, Barry Cohen of Certilman Balin, and Carlson, Kolleeny and Urda of NYSDEC. IWP to be submitted in 30 days for an additional on-site well in the NE portion of the site. May not be feasible because the subway is located directly adjacent to the site.3/16/2012 - Carlson: Reviewed 4th quarter 2011 update report. MW1 not sampled - inaccessible. MW2 - MW4 sampled only. No LNAPL noted. Large decrease in VOC concentration in MW3 since last sampling. Significant VOC concentration in MW1 in 9/26/11 sampling event. IWP for on-site delineation overdue - as discussed during 1/30/12 meeting. 3/29/12 - Carlson: Reviewed IWP, delineation not accessible due to subway. MNA proposed. 9/11/12 - Carlson: Reviewed 2nd quarterly update report dated 7/17/12. The report documents groundwater gauging and sampling conducted in June 2012. Volatile organic compounds are present above the Departments standards in three wells. 9/12/12 - Carlson: Issued RAWP required letter. RAWP due 10/12/12.11/8/12 - Carlson: Received email from Christine Camardella on 9/14/12. Remediation not possible because MW-3 is located 13 feet from the subway tunnel. No intrusive work allowed within 20 feet of subway tunnel (this includes chemical injection). Replied to email - how about waterloo oxygen emitters?07/15/13 - Spill Case is transferred from Sarah Carlson (Section C) to Brevdo (Section B) as per DER Region 2 decision. VB07/30/2013 - Spill Case is re-assigned to Alex Zhitomirsky. Re-assignment of Wolf cases to Alex Zhitomirsky discussed between Alex Zhitormirsky and Vadim Brevdo on 7/29/2013 and via Brevdo’s e-mails of 7/17/2013 and 7/29/2013. VB11-15-2013 Received an e-mail from Christine Camardella dated 11-13-2013:"Alex,This is to inform you that we are proceeding with the installation of one soil boring at the above-referenced Site on Monday, November 18th. The soil data will be used to determine the effectiveness of the soil vapor extraction system that operated at the Site pursuant to our previous request for no further action in which the NYSDEC requested current soil data.If you have any questions please do not hesitate to contact me.Thank you.Christine CamardellaIMPACT ENVIRONMENTALT | 631.269.8800"I left a message requesting info regarding location of the planned boring. AZ2-10-2014 Reviewed a 2nd quarter 2013 monitoring report received on August 16, 2013. The report stated that total VOCs ranged 10 ppb to 853 ppb in MW-3. Contamination found in MW-3 is due to residual contamination from the original spill number. Impact conducted a vacuum enhanced fluid recovery (EFR)event on June 6, 2013. Approximately 84 gallons of water was removed from two wells. AZ3-30-2014 Reviewed a subsurface investigation report dated April 18, 2014. A soil boring was advanced and exhibited no contamination. Groundwater was sampled. Well MW-3 exhibited 1,305 ppb of total VOCs. Previous reading was 841 ppb (contamination increased). I have discussed the site with

AMOCO SVCE STA (Continued) **1000693997**

Christine Camardella. SVE system existed at the site, apparently installed by Tyree. No background soil sampling results exist. The system doesn't exist anymore. Apparently, no soil samples were taken after the operation of the system discontinued. Ms. Camardella will contact Tyree and try to obtain soil data. Also, ORC socks will be installed. AZ10-9-2014 Discussed the site with C. Camardella. She stated that there is a residual contamination in MW-3, ABOUT 1500 PPB of total VOC. It was decided that Impact will consider re drilling and and reinstalling this well. AZ3-27-2015 Reviewed a subsurface investigation report dated August 8, 2014. Impact conducted a vacuum enhanced fluid recovery event on June 6, 2013. Aproximately 84 gallons of water was removed from MW-3 and MW-4. In addition, as recommended by DEC, two oxygen release compund filter socks were installed in MW-3 on June 17, 2014. Groundwater was sampled. Well MW-5 exhibited 1,562 ppb of total VOCs. AZ4-6-2015 Reviewed the 1st Quarter Monitoring Report and closure request dated March 5, 2015. SVE system was operated at the site in the early 1990's. A vacuum enhanced fluid recovery was conducted on June 6, 2013. ORC socks were installed in 2014. Monitoring well M-13 was air lifted and re-developed in an effort to remove particles that may be clogging the screen. Based on the current groundwater and soil conditions, Impact requested no further action for this spill.4-7-2015 The following e-mail was sent to C. Camardello and V. Brevdo:"Dear Christine,I have reviewed the 1st Quarter Monitoring Report and Spill Closure Request dated 03/05/2015. The site has been a gasoline service station since at least the early 1930's. Spill #0330060 was opened due to a spike of MTBE in monitoring well MW-3. Soil investigation was performed in 2010. Analytical results indicated that concentrations of benzene, toluene, ethyl benzene and total xylenes and MTBE were ranging from 5 ppb to 68 ppb. Concentrations of semi-volatile organic compounds (SVOCs) were non-detect in al soil samples taken. One soil probe was advanced in 2013, and showed no exceedances of NYSDEC Recommended Soil CLeanup Guidance Values. Groundwater samples were collected in February 2015. Concentrations of total Volatile Organic Compounds (VOCs) ranged from below reporting limit to 5.4 ppb.Based upon results of the sampling, Impact recommended closure of spill #0330060. I concur with this request.All wells should be checked for the presence of free phase product prior to decommissioning. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts may need to be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence

AMOCO SVCE STA (Continued) **1000693997**

regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely,Alex Zhitomirsky | Engineering Geologist 2NYS Department of Environmental Conservation47-40 21st Street, Long Island City, NY 11101Phone: 718.482.6387 | Fax: 718.482.6390Email: alexander.zhitomirsky@dec.ny.gov"

Remarks: MTBE spike detected during groundwater monitoring for spill #9110815. Possible new release. Currently an Amoco station owned by Wolf Petroleum.

Material:

Site ID:	182084
Operable Unit ID:	880626
Operable Unit:	01
Material ID:	574723
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	182084
Operable Unit ID:	880626
Operable Unit:	01
Material ID:	574722
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	182084
Operable Unit ID:	880626
Operable Unit:	01
Material ID:	496565
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True

Tank Test:

AIRS (AFS):

Airs Minor Details:

AMOCO SVCE STA (Continued) **1000693997**

EPA plant ID:	110001572227
Plant name:	AMOCO SVCE STA
Plant address:	2 BUSHWICK AVE BROOKLYN, NY 11211
County:	KINGS
Region code:	02
Dunn & Bradst #:	Not reported
Air quality cntrl region:	043
Sic code:	5541
Sic code desc:	GASOLINE SERVICE STATIONS
North Am. industrial classf:	Not reported
NAIC code description:	Not reported
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1403
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1402
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1401
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1303
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1302
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1204
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1202
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1201
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1304
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

AMOCO SVCE STA (Continued) **1000693997**

Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

B14 **SHELL SERVICE STATION** **NY UST** **U004061890**
West **2 BUSHWICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.052 mi.
274 ft. **Site 10 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

UST:
Id/Status: 2-190411 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 09/20/2018
UTM X: 589396.13497999997
UTM Y: 4507603.2218000004
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 5875
Affiliation Type: Facility Owner
Company Name: 2 BUSHWICK AVENUE CORP
Contact Type: PRESIDENT
Contact Name: CARY WOLF
Address1: 125 JERICHO TURNPIKE SUITE 401
Address2: Not reported
City: JERICHO
State: NY
Zip Code: 11753
Country Code: 001
Phone: (516) 997-9300
EMail: Not reported

SHELL SERVICE STATION (Continued) **U004061890**

Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	8/14/2013

Site Id:	5875
Affiliation Type:	Mail Contact
Company Name:	2 BUSHWICK AVENUE CORP.
Contact Type:	Not reported
Contact Name:	CARY WOLF
Address1:	125 JERICHO TURNPIKE
Address2:	SUITE 401
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	CWOLF@BWPETROLEUM.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/30/2011

Site Id:	5875
Affiliation Type:	On-Site Operator
Company Name:	SHELL SERVICE STATION
Contact Type:	Not reported
Contact Name:	DAVID CHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-0310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	8/14/2013

Site Id:	5875
Affiliation Type:	Emergency Contact
Company Name:	2 BUSHWICK AVENUE CORP
Contact Type:	Not reported
Contact Name:	CARY WOLF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 997-9300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/30/2011

Tank Info:

SHELL SERVICE STATION (Continued) **U004061890**

Tank Number:	001
Tank ID:	81901
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	03/02/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BKFALVEY
Last Modified:	10/15/2014

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	001-A
Tank ID:	81904
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1992
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating

SHELL SERVICE STATION (Continued) **U004061890**

C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	81905
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	03/02/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BKFALVEY
Last Modified:	10/15/2014

Equipment Records:

F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	002-A
Tank ID:	81909
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1992
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

SHELL SERVICE STATION (Continued) **U004061890**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 81910
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 3000
Install Date: 07/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 03/02/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: BKFALVEY
Last Modified: 10/15/2014

Equipment Records:

F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Number: 003-A
Tank ID: 81913
Tank Status: Closed - Removed

SHELL SERVICE STATION (Continued) **U004061890**

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005-A
Tank ID: 82864
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating

SHELL SERVICE STATION (Continued) **U004061890**

H00 - Tank Leak Detection - None

Tank Number: 006
Tank ID: 6838
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number: 007
Tank ID: 6839
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

SHELL SERVICE STATION (Continued) **U004061890**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number:	008
Tank ID:	6840
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1992
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Number:	009
Tank ID:	6841
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1992
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

SHELL SERVICE STATION (Continued) **U004061890**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number: 010
Tank ID: 6842
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number: 011
Tank ID: 6843
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001

SHELL SERVICE STATION (Continued) **U004061890**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 04
Tank ID: 81914
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1992
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 07/25/2007

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

B15 **SHELL SERVICE STATION** **NY AST** **U001832999**
West **2 BUSHWICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.052 mi.
274 ft. **Site 11 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-190411
Program Type:	PBS
UTM X:	589396.13497999997
UTM Y:	4507603.2218000004
Expiration Date:	09/20/2018
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	5875
Affiliation Type:	Facility Owner
Company Name:	2 BUSHWICK AVENUE CORP
Contact Type:	PRESIDENT
Contact Name:	CARY WOLF
Address1:	125 JERICHO TURNPIKE SUITE 401
Address2:	Not reported
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	8/14/2013

Site Id:	5875
Affiliation Type:	Mail Contact
Company Name:	2 BUSHWICK AVENUE CORP.
Contact Type:	Not reported
Contact Name:	CARY WOLF
Address1:	125 JERICHO TURNPIKE
Address2:	SUITE 401
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	CWOLF@BWPETROLEUM.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/30/2011

Site Id:	5875
Affiliation Type:	On-Site Operator
Company Name:	SHELL SERVICE STATION
Contact Type:	Not reported
Contact Name:	DAVID CHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

SHELL SERVICE STATION (Continued) **U001832999**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-0310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	8/14/2013

Site Id:	5875
Affiliation Type:	Emergency Contact
Company Name:	2 BUSHWICK AVENUE CORP
Contact Type:	Not reported
Contact Name:	CARY WOLF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 997-9300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/30/2011

Tank Info:

Tank Number:	004
Tank Id:	81916
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/1993
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

SHELL SERVICE STATION (Continued) **U001832999**

Register:	True
Modified By:	KAKYER
Last Modified:	08/14/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)
Tank Number:	005
Tank Id:	82090
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/1993
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	08/14/2013
Material Name:	Waste Oil/Used Oil

B16 **EDR US Hist Auto Stat** **1015299061**
West **2 BUSHWICK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.052 mi.
274 ft. **Site 12 of 12 in cluster B**

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:

Name:	L & R SHELL AUTO SERVICE INC
Year:	2001
Address:	2 BUSHWICK AVE
Name:	L & R SHELL AUTO SERVICE INC
Year:	2002
Address:	2 BUSHWICK AVE
Name:	R & R AUTO REPAIR SHOP
Year:	2003
Address:	2 BUSHWICK AVE

(Continued) **1015299061**

Name: R & R AUTO REPAIR SHOP
Year: 2004
Address: 2 BUSHWICK AVE

Name: K & D AUTO REPAIR SHOP
Year: 2005
Address: 2 BUSHWICK AVE

C17 **CON EDISON** **NY MANIFEST** **S117059777**
NNW **OPP 34 MASPETH AV** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.058 mi.
304 ft. **Site 1 of 2 in cluster C**

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:
EPA ID: NYP004519666
Country: USA
Location Address 1: OPP 34 MASPETH AV
Location Address 2: SB31305
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 05/02/2014
Trans1 Recv Date: 05/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/02/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004519666
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002417579GBF

CON EDISON (Continued) **S117059777**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

C18 **CON EDISON** **NY MANIFEST** **S117741592**
North **42 MASPETH AV** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.063 mi.
334 ft. **Site 2 of 2 in cluster C**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

EPA ID:	NYP004748315
Country:	USA
Location Address 1:	42 MASPETH AV
Location Address 2:	SB13109
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2015
Trans1 Recv Date:	03/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004748315
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117741592**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014087091JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

---

19 **CON EDISON** **NY MANIFEST** **S117739752**
NNE **58-35 MASPETH AV** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.078 mi.
411 ft.

Relative:
Lower

Actual:
33 ft.

NY MANIFEST:

EPA ID:	NYP004728895
Country:	USA
Location Address 1:	58-35 MASPETH AV
Location Address 2:	SB25150
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/09/2015
Trans1 Recv Date:	02/09/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004728895
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported

CON EDISON (Continued) **S117739752**

Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002620996GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

D20 **EDR US Hist Auto Stat** **1015661862**
East **880 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.079 mi.
416 ft. **Site 1 of 4 in cluster D**

Relative:
Lower

Actual:
31 ft.

EDR Historical Auto Stations:

Name:	CITY TRUCK REPAIR INCORPORATED
Year:	1999
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INCORPORATED
Year:	2000
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2001
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2002
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2003
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2007
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2008
Address:	880 METROPOLITAN AVE
Name:	CITY TRUCK REPAIR INC
Year:	2009
Address:	880 METROPOLITAN AVE

D21 **880 METROPOLITAN AVE** **NY Spills** **S102146667**
East **880 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.079 mi.
416 ft. **Site 2 of 4 in cluster D**

Relative:
Lower

Actual:
31 ft.

SPILLS:

Facility ID:	9303810
Facility Type:	ER
DER Facility ID:	225874
Site ID:	278188
DEC Region:	2
Spill Date:	6/16/1993
Spill Number/Closed Date:	9303810 / 6/24/1993
Spill Cause:	Deliberate
Spill Class:	No spill occured. (Not Possible)
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	6/24/1993
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	6/24/1993
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/24/1993
Spill Record Last Update:	1/30/1998
Spiller Name:	Not reported
Spiller Company:	ALL CITY SERVICES
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	DUMPING LIQUIDS, MATERIALS GREASE - HIS DOG GOT VERY SICK - DUMPING THINGS INTO STORM DRAIN.

Material:

Site ID:	278188
Operable Unit ID:	982103
Operable Unit:	01
Material ID:	397358
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

E22
WNW
< 1/8
0.080 mi.
423 ft.

CON EDISON
OPP 3 MASPETH AVE
BROOKLYN, NY 11211

Site 1 of 2 in cluster E

NY MANIFEST **S117062748**
N/A

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:

EPA ID:	NYP004551297
Country:	USA
Location Address 1:	OPP 3 MASPETH AVE
Location Address 2:	SB 13105
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/2014
Trans1 Recv Date:	06/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004551297
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013245922JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117062748**

Mgmt Method Type Code: H110

23
NW
< 1/8
0.086 mi.
454 ft.

ST FRANCIS OF PAOLA CHURCH
219 CONSELYEA STREET
BROOKLYN, NY 11211

NY UST **U000399951**
NY HIST UST **N/A**

Relative:
Lower

Actual:
36 ft.

UST:

Id/Status:	2-316393 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/10/2012
UTM X:	589372.61938000005
UTM Y:	4507680.6580800004
Site Type:	Other

Affiliation Records:

Site Id:	14506
Affiliation Type:	Facility Owner
Company Name:	ST FRANCIS OF PAOLA CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	219 CONSELYEA ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-0256
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/11/2008

Site Id:	14506
Affiliation Type:	Mail Contact
Company Name:	ST FRANCIS OF PAOLA CHURCH
Contact Type:	Not reported
Contact Name:	LORETTA PIZZA
Address1:	219 CONSELYEA STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-0256
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/11/2008

Site Id:	14506
Affiliation Type:	On-Site Operator
Company Name:	ST FRANCIS OF PAOLA CHURCH
Contact Type:	Not reported
Contact Name:	ST FRANCIS OF PAOLA CHURCH

ST FRANCIS OF PAOLA CHURCH (Continued) **U000399951**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-0256
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	14506
Affiliation Type:	Emergency Contact
Company Name:	ST FRANCIS OF PAOLA CHURCH
Contact Type:	Not reported
Contact Name:	RC DIOCESE OF BKLYN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 638-5500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	12961
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	01/01/1940
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	01/07/2014
Next Test Date:	01/07/2019
Pipe Model:	Not reported
Modified By:	BKFALVEY
Last Modified:	02/14/2014

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

ST FRANCIS OF PAOLA CHURCH (Continued) **U000399951**

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	2-316393
SPDES Number:	Not reported
Emergency Contact:	RC DIOCESE OF BKLYN
Emergency Telephone:	(718) 638-5500
Operator:	ST FRANCIS OF PAOLA CHURCH
Operator Telephone:	(718) 387-0256
Owner Name:	ST FRANCIS OF PAOLA CHURCH
Owner Address:	219 CONSELYEA ST
Owner City,St,Zip:	BKLYN, NY 11211
Owner Telephone:	(718) 387-0256
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	ST FRANCIS OF PAOLA CHURCH
Mailing Address:	219 CONSELYEA ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BKLYN, NY 11211
Mailing Contact:	Not reported
Mailing Telephone:	(718) 387-0256
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	219 CONSELYEA ST
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	09/08/1998
Expiration Date:	07/10/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service

ST FRANCIS OF PAOLA CHURCH (Continued) **U000399951**

Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	07/01/1998
Next Test Date:	07/01/2003
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

E24 **NYS TAXI NETWORK INC** **NY AST** **A100343968**
West **801 METROPALITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.090 mi.
474 ft. **Site 2 of 2 in cluster E**

Relative:
Higher

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-611088
Program Type:	PBS
UTM X:	589290.12337000004
UTM Y:	4507628.9799100002
Expiration Date:	06/02/2014
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	413876
Affiliation Type:	Facility Owner
Company Name:	SAIF U. KAHN
Contact Type:	SECR.
Contact Name:	ARSHAD A. BAALH
Address1:	9 EAST 3RD ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 777-8757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/15/2009

NYS TAXI NETWORK INC (Continued) **A100343968**

Site Id:	413876
Affiliation Type:	Mail Contact
Company Name:	NYS TAXI NETWORK INC
Contact Type:	Not reported
Contact Name:	SAIF U. KAHN
Address1:	801 METROPALITAN AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/15/2009

Site Id:	413876
Affiliation Type:	On-Site Operator
Company Name:	NYS TAXI NETWORK INC
Contact Type:	Not reported
Contact Name:	SAIF U. KAHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/15/2009

Site Id:	413876
Affiliation Type:	Emergency Contact
Company Name:	SAIF U. KAHN
Contact Type:	Not reported
Contact Name:	SAIF U. KAHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/15/2009

Tank Info:

Tank Number:	001
Tank Id:	228461
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

NYS TAXI NETWORK INC (Continued) **A100343968**

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
A99 - Tank Internal Protection - Other
E00 - Piping Secondary Containment - None
I01 - Overfill - Float Vent Valve

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/2006
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	05/15/2009
Material Name:	Waste Oil/Used Oil

D25 **CON EDISON - MANHOLE 68734** **RCRA-LQG** **1016960461**
East **890 METROPOLITAN AVENUE** **NY MANIFEST** **NYP004324489**
< 1/8 **BROOKLYN, NY 11211**
0.091 mi.
480 ft. **Site 3 of 4 in cluster D**

Relative:
Lower

Actual:
30 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 68734
Facility address:	890 METROPOLITAN AVENUE BROOKLYN, NY 11211
EPA ID:	NYP004324489
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1

CON EDISON - MANHOLE 68734 (Continued) **1016960461**

kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/15/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/15/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D008
. Waste name:	LEAD

Historical Generators:

Date form received by agency:	08/03/2013
Site name:	CON EDISON MANHOLE: 68734
Classification:	Not a generator, verified

Date form received by agency:	07/03/2013
Site name:	CON EDISON MANHOLE: 68734
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON - MANHOLE 68734 (Continued) **1016960461**

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004324489
Country: USA
Location Address 1: 890 METROPOLITAN AVENUE
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 07/03/2013
Trans1 Recv Date: 07/03/2013
Trans2 Recv Date: 07/03/2013
TSD Site Recv Date: 07/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004324489
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 800
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 002016846GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

26
South
< 1/8
0.091 mi.
481 ft.

SPILL NUMBER 0100018
50 BUSHWICK AVE
BROOKLYN, NY

NY Spills **S104953799**
N/A

Relative:
Higher

Actual:
41 ft.

SPILLS:

Facility ID:	0100016
Facility Type:	ER
DER Facility ID:	206479
Site ID:	251983
DEC Region:	2
Spill Date:	4/2/2001
Spill Number/Closed Date:	0100016 / 4/2/2001
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	4/2/2001
CID:	403
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/2/2001
Spill Record Last Update:	5/12/2005
Spiller Name:	Not reported
Spiller Company:	CONTRACTOR
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	NONE
Contact Phone:	(000) 000-0000
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"Close and Cross reference to 0100018. FD reported twice.
Remarks:	CONTRACTOR ON SCENE WAS DUMPING OIL DOWN DRAIN.

Material:

Site ID:	251983
Operable Unit ID:	837073
Operable Unit:	01
Material ID:	539291
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

SPILL NUMBER 0100018 (Continued) **S104953799**

Tank Test:

Facility ID:	0100018
Facility Type:	ER
DER Facility ID:	206479
Site ID:	251984
DEC Region:	2
Spill Date:	4/2/2001
Spill Number/Closed Date:	0100018 / 6/1/2004
Spill Cause:	Deliberate
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	4/2/2001
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/2/2001
Spill Record Last Update:	6/1/2004
Spiller Name:	Not reported
Spiller Company:	ANGEL MENDOZA
Spiller Address:	65 BUSHWICK AVE
Spiller City,St,Zip:	BROOKLYN, NY 11211-
Spiller Company:	001
Contact Name:	FF JOHN HACK
Contact Phone:	(917) 769-0483
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"10:00 Spoke to FF Hack.Angel Mendoza (owner)was doing work on the above ground fuel oil tank in the basement of 50 Bushwick Avenue (3 story Apartment Bldg)The tank was intentionally pierced by the owner in order to clean the tank. Mr. Mendoza failed to plug the hole before his wife ordered 200 gallons of oil. The FDNY was able to plug the tank and contain 130 gallons in the tank, but 70 gallons was lost to the sump and eventually pumped into the sewer.The pump was removed from the drain by FDNY. AL Eastmond has been hired to perform the cleanup of sump and sewer (if possible). DEP has been notified that oil was pumped to their sewer. See also Spill 0100016. JMR7/20/03 letter sent requesting documentation6/1/04 A L Eastman conducted pumpout of recoverable oil and repairs on tank///nfa
Remarks:	req callback and response asap - party cut through tank to get rid of oil

Material:

Site ID:	251984
Operable Unit ID:	837077
Operable Unit:	01
Material ID:	539293

SPILL NUMBER 0100018 (Continued) **S104953799**

Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

F27 **CON EDISON SERVICE BOX: 12563** **RCRA NonGen / NLR** **1016974158**
ESE **253 DEVOE ST** **NY MANIFEST** **NYP004479705**
< 1/8 **BROOKLYN, NY 11211**
0.092 mi.
488 ft. **Site 1 of 2 in cluster F**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/26/2014
Facility name:	CON EDISON SERVICE BOX: 12563
Facility address:	253 DEVOE ST BROOKLYN, NY 11211
EPA ID:	NYP004479705
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/26/2014

CON EDISON SERVICE BOX: 12563 (Continued) **1016974158**

Site name: CON EDISON SERVICE BOX: 12563
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004479705
Country: USA
Location Address 1: F/O DEVOE AT
Location Address 2: STRUCTURE 12363
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: KMART
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2014
Trans1 Recv Date: 03/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004479705
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002406403GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

CON EDISON SERVICE BOX: 12563 (Continued) **1016974158**

Mgmt Method Type Code: H110

D28 **CON EDISON SERVICE BOX: 68734** **RCRA NonGen / NLR** **1016454575**
East **892 METROPOLITAN AVE** **FINDS** **NYP004329462**
< 1/8 **BROOKLYN, NY 11249** **NY MANIFEST**
0.094 mi.
496 ft. **Site 4 of 4 in cluster D**

Relative:
Lower

Actual:
30 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/15/2013
Facility name:	CON EDISON SERVICE BOX: 68734
Facility address:	892 METROPOLITAN AVE BROOKLYN, NY 11249
EPA ID:	NYP004329462
Mailing address:	VING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/15/2013
Site name:	CON EDISON SERVICE BOX: 68734
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110056497599

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON SERVICE BOX: 68734 (Continued) **1016454575**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYP004329462
Country:	USA
Location Address 1:	892 METROPOLITAN AVE
Location Address 2:	SB #68734
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/15/2013
Trans1 Recv Date:	07/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004329462
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	002084331GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

CON EDISON SERVICE BOX: 68734 (Continued) **1016454575**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

G29 **EDR US Hist Auto Stat** **1015460163**
WNW **383 HUMBOLDT ST** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.100 mi.
528 ft. **Site 1 of 3 in cluster G**

Relative:
Higher

Actual:
37 ft.

EDR Historical Auto Stations:

Name: NGUYEN AUTO SHOP
Year: 2003
Address: 383 HUMBOLDT ST

Name: NGUYEN AUTO SHOP
Year: 2004
Address: 383 HUMBOLDT ST

Name: NGUYEN AUTO SHOP
Year: 2005
Address: 383 HUMBOLDT ST

Name: WING AUTO SHOP
Year: 2006
Address: 383 HUMBOLDT ST

Name: WING AUTO SHOP
Year: 2007
Address: 383 HUMBOLDT ST

Name: WING AUTO SHOP
Year: 2008
Address: 383 HUMBOLDT ST

Name: WING AUTO SHOP
Year: 2009
Address: 383 HUMBOLDT ST

G30 **385 HUMBOLDT ST.** **NY Spills** **S104495484**
WNW **385 HUMBOLDT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.103 mi.
542 ft. **Site 2 of 3 in cluster G**

Relative:
Higher

Actual:
37 ft.

SPILLS:

Facility ID: 9302207
Facility Type: ER
DER Facility ID: 174187
Site ID: 210114
DEC Region: 2
Spill Date: 5/17/1993
Spill Number/Closed Date: 9302207 / 4/25/1994
Spill Cause: Housekeeping
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

385 HUMBOLDT ST. (Continued) **S104495484**

SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	5/17/1993
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	4/25/1994
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/19/1993
Spill Record Last Update:	11/26/2003
Spiller Name:	Not reported
Spiller Company:	IN BACK YARD RES.AUTO REP
Spiller Address:	AUTO REPAIR.
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	DUMP OIL ON GROUNG OIL IS SEEPING INTO NOTIFIERS HOME THRU WALL BETWEEN YARD (192 CONSELVEA ST.NOTIFIER ADDRESS.) NYC DEP HAG MAT WAS NOTIFIED.

Material:

Site ID:	210114
Operable Unit ID:	980646
Operable Unit:	01
Material ID:	399345
Material Code:	0011
Material Name:	Jet Fuel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	210114
Operable Unit ID:	980646
Operable Unit:	01
Material ID:	399346
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

H31 **S/S BREAKER LEAKED DURING REMOVAL** **NY Spills** **S109062206**
SSW **324 AINSLIE ST. SUBSTATION** **N/A**
< 1/8 **BROOKLYN, NY**
0.106 mi.
558 ft. **Site 1 of 3 in cluster H**

Relative:
Higher

Actual:
41 ft.

SPILLS:

Facility ID:	0801005
Facility Type:	ER
DER Facility ID:	346328
Site ID:	396859
DEC Region:	2
Spill Date:	4/24/2008
Spill Number/Closed Date:	0801005 / 5/19/2008
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	gdbreen
Referred To:	Not reported
Reported to Dept:	4/24/2008
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/24/2008
Spill Record Last Update:	5/19/2008
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON VEH.#60711
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	ERT DESK' MIKE DAUGHTERY
Contact Phone:	(212) 580-8383
DEC Memo:	05/19/08 - See eDocs for Con Ed report detailing cleanup and closure.211043. see eDocs
Remarks:	3 ounces of material fell onto the sidewalk from a circuit breaker. clean up is in progress. Con Ed #211043.

Material:

Site ID:	396859
Operable Unit ID:	1153826
Operable Unit:	01
Material ID:	2144599
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

S/S BREAKER LEAKED DURING REMOVAL (Continued) **S109062206**

Tank Test:

I32 **SPILL NUMBER 0201573** **NY Spills** **S106003527**
North **236 SKILLMAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.114 mi.
600 ft. **Site 1 of 3 in cluster I**

Relative:
Lower

Actual:
33 ft.

SPILLS:

Facility ID:	0201573
Facility Type:	ER
DER Facility ID:	243289
Site ID:	300829
DEC Region:	2
Spill Date:	5/12/2002
Spill Number/Closed Date:	0201573 / 2/13/2003
Spill Cause:	Abandoned Drums
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	5/12/2002
CID:	405
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/12/2002
Spill Record Last Update:	2/13/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	FF FENDELMAN
Contact Phone:	(917) 769-0483
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"2/13/2003 - Closed Due To The Nature / Extent Of The Spill Report
Remarks:	CALLER STATES THEY WERE DISPATCHED TO 3 100 LBS PROPANE CILINDARS LEAKING IN THE STREET - ONLY ONE WAS FOUND TO BE LEAKING - NYFD ON SCENE

Material:

Site ID:	300829
Operable Unit ID:	852546
Operable Unit:	01
Material ID:	522988
Material Code:	2617A
Material Name:	PROPANE GAS
Case No.:	Not reported

SPILL NUMBER 0201573 (Continued) **S106003527**

Material FA:	Other
Quantity:	50
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

H33 **CON EDISON** **NY MANIFEST** **S117317151**
SW **298 AINSLIE ST** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.114 mi.
601 ft. **Site 2 of 3 in cluster H**

Relative:
Higher

Actual:
41 ft.

NY MANIFEST:

EPA ID:	NYP004645156
Country:	USA
Location Address 1:	298 AINSLIE ST
Location Address 2:	SB13190
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2014
Trans1 Recv Date:	09/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004645156
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117317151**

Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002616584GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/2014
Trans1 Recv Date:	09/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004645156
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002359345GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

H34 **CON EDISON** **NY MANIFEST** **S117314091**
SW **298 AINSLIE ST** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.114 mi.
601 ft. **Site 3 of 3 in cluster H**

Relative:
Higher

Actual:
41 ft.

NY MANIFEST:

EPA ID:	NYP004611257
Country:	USA
Location Address 1:	298 AINSLIE ST
Location Address 2:	SB 13190
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/29/2014
Trans1 Recv Date:	07/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004611257
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002615417GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117314091**

Mgmt Method Type Code: H110

F35 **CON EDISON** **NY MANIFEST** **S117736519**
ESE **263 DEVOE STREET** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.114 mi.
602 ft. **Site 2 of 2 in cluster F**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

EPA ID:	NYP004526026
Country:	USA
Location Address 1:	263 DEVOE STREET
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH ST
City/State/Zip:	NEW YORK, NY 10001
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2014
Trans1 Recv Date:	05/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004526026
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002422235GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

CON EDISON (Continued) **S117736519**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

I36 **SANITATION COMPANY** **NY Spills** **S103939104**
North **244 SKILLMAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.115 mi.
605 ft. **Site 2 of 3 in cluster I**

Relative:
Lower

Actual:
33 ft.

SPILLS:
Facility ID: 9903762
Facility Type: ER
DER Facility ID: 221615
Site ID: 272280
DEC Region: 2
Spill Date: 7/1/1999
Spill Number/Closed Date: 9903762 / 7/6/1999
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 7/1/1999
CID: 270
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/1/1999
Spill Record Last Update: 3/3/2000
Spiller Name: Not reported
Spiller Company: SANITATION COMPANY
Spiller Address: 244 SKILLMAN AVE
Spiller City,St,Zip: BROOKLYN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"7/1- 1:30PM CALLED KAMPIL SMELLS LIKE PAINT THINNER- GARBAGE TRUCKS ARE WASHED WITH CHEMICALS, NEIGHBOR SAID IT THE SMELL IS REALLY STRONG. WOULD LIKE SOMEONE TO LOOK AT THE PROPERTY.NO ODORS, SKILLMAN CONTRACTING CLAIMED NOT TO WASH TRUCKS ONSITE. CALLER DOES NOT WANT TO PURSUE FURTHER.
Remarks: caller states that there is a strong odor comingb from property
caller would like a call back

Material:
Site ID: 272280
Operable Unit ID: 1082697

SANITATION COMPANY (Continued) **S103939104**

Operable Unit: 01
Material ID: 303665
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

I37 **SKILL-MAN CONTRACTING INC.** **NY AST** **A100296053**
North **244 SKILLMAN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.115 mi.
605 ft. **Site 3 of 3 in cluster I**

Relative:
Lower

Actual:
33 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608653
Program Type: PBS
UTM X: 589436.91798000003
UTM Y: 4507794.0428900002
Expiration Date: 03/20/2013
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 30505
Affiliation Type: Facility Owner
Company Name: VINCENZA LATEMPA
Contact Type: PRES
Contact Name: VINCENZA
Address1: 244 SKILLMAN AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 388-4600
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 2/7/2008

Site Id: 30505
Affiliation Type: Mail Contact
Company Name: SKILL-MAN CONTRACTING INC.
Contact Type: Not reported
Contact Name: VINCENZA LATEMPA
Address1: 244 SKILLMAN AVENUE
Address2: Not reported
City: BROOKLYN

SKILL-MAN CONTRACTING INC. (Continued) **A100296053**

State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 388-4600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30505
Affiliation Type: On-Site Operator
Company Name: SKILL-MAN CONTRACTING INC.
Contact Type: Not reported
Contact Name: VINCENZA LATEMPA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 388-4600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30505
Affiliation Type: Emergency Contact
Company Name: VINCENZA LATEMPA
Contact Type: Not reported
Contact Name: VINCENZA LATEMPA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 388-4600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 1
Tank Id: 65447
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

SKILL-MAN CONTRACTING INC. (Continued) **A100296053**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/20/2003
Capacity Gallons:	200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	msbaptis
Last Modified:	02/07/2008
Material Name:	Waste Oil/Used Oil

J38 **EDR US Hist Auto Stat** **1015293696**
NNW **193 WOODPOINT RD** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.115 mi.
608 ft. **Site 1 of 3 in cluster J**

Relative:
Lower

Actual:
33 ft.

EDR Historical Auto Stations:

Name:	TWO BROTHERS AUTO SVCE
Year:	1999
Address:	193 WOODPOINT RD
Name:	TWO BROTHERS AUTO SVCE
Year:	2000
Address:	193 WOODPOINT RD
Name:	TWO BROTHERS AUTO SERVICE
Year:	2001
Address:	193 WOODPOINT RD
Name:	TWO BROTHERS AUTO SALES
Year:	2002
Address:	193 WOODPOINT RD

J39 **TWO BROTHERS AUTO SALES** **NY AST** **A100296474**
NNW **193 WOODPOINT ROAD** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.115 mi.
608 ft. **Site 2 of 3 in cluster J**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607573
Program Type:	PBS
UTM X:	589358
UTM Y:	4507775

TWO BROTHERS AUTO SALES (Continued) **A100296474**

Expiration Date: 04/08/2007
Site Type: Unknown

Affiliation Records:

Site Id: 29425
Affiliation Type: Facility Owner
Company Name: JOSEPH & STEVEN SANTORA
Contact Type: Not reported
Contact Name: Not reported
Address1: 84-06 DORAN AVE
Address2: Not reported
City: GLENDALE
State: NY
Zip Code: 11785
Country Code: 001
Phone: (718) 894-4636
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 12/12/2013

Site Id: 29425
Affiliation Type: Mail Contact
Company Name: TWO BROTHERS AUTO SALES
Contact Type: Not reported
Contact Name: JOSEPH & STEVEN SANTORA
Address1: 193 WOODPOINT ROAD
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 387-1285
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29425
Affiliation Type: On-Site Operator
Company Name: TWO BROTHERS AUTO SALES
Contact Type: Not reported
Contact Name: JOSEPH SANTORA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 387-1285
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29425
Affiliation Type: Emergency Contact
Company Name: JOSEPH & STEVEN SANTORA

TWO BROTHERS AUTO SALES (Continued) **A100296474**

Contact Type:	Not reported
Contact Name:	JOSEPH SANTORA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-1285
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	63205
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Waste Oil/Used Oil

G40 **ST. FRANCIS OF PAOLA SCHOOL** **NY AST** **A100182922**
WNW **195-201 CONSELYEA STREET** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.116 mi.
612 ft. **Site 3 of 3 in cluster G**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-201014

ST. FRANCIS OF PAOLA SCHOOL (Continued) **A100182922**

Program Type: PBS
UTM X: 589315.44421999995
UTM Y: 4507673.7250300003
Expiration Date: 08/14/2011
Site Type: School

Affiliation Records:

Site Id: 6804
Affiliation Type: Facility Owner
Company Name: REV. ANDREW VARANO PASTOR
Contact Type: PASTOR
Contact Name: REV. ANDREW R. VARANO
Address1: 219 CONSELYEA STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 387-0256
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/21/2006

Site Id: 6804
Affiliation Type: Mail Contact
Company Name: ST. FRANCIS OF PAOLA SCHOOL
Contact Type: Not reported
Contact Name: ROSEMARIE MILAZZO
Address1: 201 CONSELYEA STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-1462
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/21/2006

Site Id: 6804
Affiliation Type: On-Site Operator
Company Name: ST. FRANCIS OF PAOLA SCHOOL
Contact Type: Not reported
Contact Name: JOSE REYES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 782-1462
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/21/2006

ST. FRANCIS OF PAOLA SCHOOL (Continued) **A100182922**

Site Id:	6804
Affiliation Type:	Emergency Contact
Company Name:	REV. ANDREW VARANO PASTOR
Contact Type:	Not reported
Contact Name:	REV. ANDREW VARANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-0256
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	11418
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

K41 **CON EDISON SERVICE BOX: 12572** **RCRA NonGen / NLR** **1016971529**
SSE **16 JUDGE ST** **NY MANIFEST** **NYP004452728**
< 1/8 **BROOKLYN, NY 11211**
0.120 mi.
634 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/26/2014
Facility name:	CON EDISON SERVICE BOX: 12572
Facility address:	16 JUDGE ST BROOKLYN, NY 11211
EPA ID:	NYP004452728
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/26/2014
Site name:	CON EDISON SERVICE BOX: 12572
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004452728
Country:	USA
Location Address 1:	FRONT OF 16 JUDGE ST
Location Address 2:	SB12572
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

CON EDISON SERVICE BOX: 12572 (Continued) **1016971529**

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING ST
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2014
Trans1 Recv Date:	02/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004452728
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002359015GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

J42 **EDR US Hist Auto Stat** **1015334893**
NNW **221 SKILLMAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.120 mi.
636 ft. **Site 3 of 3 in cluster J**

Relative:
Lower

Actual:
33 ft.

EDR Historical Auto Stations:

Name:	HI TECH AUTO REPAIR CORP
Year:	2006
Address:	221 SKILLMAN AVE
Name:	HI TECH AUTO REPAIR CORP

(Continued) **1015334893**

Year: 2007
Address: 221 SKILLMAN AVE

Name: HI TECH AUTO REPAIR CORP
Year: 2008
Address: 221 SKILLMAN AVE

L43 **258 SKILLMAN ST** **NY Spills** **S109942436**
NNE **258 SKILLMAN ST** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY**
0.123 mi.
648 ft. **Site 1 of 2 in cluster L**

Relative:
Lower

Actual:
32 ft.

SPILLS:

Facility ID:	0302151
Facility Type:	ER
DER Facility ID:	130141
Site ID:	153371
DEC Region:	2
Spill Date:	5/30/2003
Spill Number/Closed Date:	0302151 / 5/30/2003
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	5/30/2003
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/30/2003
Spill Record Last Update:	5/30/2003
Spiller Name:	UNK
Spiller Company:	258 SKILLMAN AV
Spiller Address:	258 SKILLMAN AV
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller Company:	001
Contact Name:	UNK
Contact Phone:	(000) 000-0000
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"Sangesland DDOMinor spill from a 275 gal tank. NYCFD secured the tank.Area was cleaned.Closed
Remarks:	caller states that there is a diesel tank on site that is used for filling machines and it was uncapped and some product spilled out

Material:

Site ID:	153371
Operable Unit ID:	868716
Operable Unit:	01
Material ID:	555333

258 SKILLMAN ST (Continued) **S109942436**

Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	10
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

E DESIGNATION:

Tax Lot(s):	30
Tax Block:	2893
Borough Code:	Not reported
E-No:	E-232
Effective Date:	7/29/2009
Satisfaction Date:	Not reported
Ceqr Number:	09DCP056K
Ulurp Number:	090334ZMK
Zoning Map No:	12c 13a 13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

M44 **CON EDISON** **NY MANIFEST** **S117067244**
East **FRONT OF 67 OLIVE ST** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.123 mi.
652 ft. **Site 1 of 2 in cluster M**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:

EPA ID:	NYP004600003
Country:	USA
Location Address 1:	FRONT OF 67 OLIVE ST
Location Address 2:	SB68313
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

CON EDISON (Continued) **S117067244**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/2014
Trans1 Recv Date:	07/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004600003
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002504128GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

N45 **SOCCI RESIDENCE** **NY Spills** **S109828858**
WSW **177 DEVOE ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.125 mi.
659 ft. **Site 1 of 3 in cluster N**

Relative:
Higher

Actual:
39 ft.

SPILLS:

Facility ID:	0905854
Facility Type:	ER
DER Facility ID:	367265
Site ID:	418147
DEC Region:	2
Spill Date:	8/19/2009
Spill Number/Closed Date:	0905854 / 8/19/2009
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	8/19/2009
CID:	Not reported
Water Affected:	Not reported

SOCCI RESIDENCE (Continued) **S109828858**

Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/19/2009
Spill Record Last Update:	8/19/2009
Spiller Name:	ROSEANNE SOCCI
Spiller Company:	ROSEANNE SOCCI
Spiller Address:	177 DEVOE ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	LAURA DOVIDO
Contact Phone:	(718) 628-3321
DEC Memo:	Gasket on the line filter leaked to the basement floor. Petro had a crew in to fix the gasket and clean the floor and sump pit. Petro Manager Mike Passi called Sangesland from the house to confirm that all of the cleanup was complete and no additional problems were visible.
Remarks:	LEAKING PART IN THE BASEMENT ABOUT 3 GALLONS SPILLED TO THE SUMP PUMP WHICH THEN ENTERED THE SEWER.

Material:

Site ID:	418147
Operable Unit ID:	1174335
Operable Unit:	01
Material ID:	2166667
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

M46 **CON EDISON - MANHOLE 4964** **RCRA-LQG** **1014396337**
East **909 METROPOLITAN AVE** **NJ MANIFEST** **NYP004186011**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.126 mi.
663 ft. **Site 2 of 2 in cluster M**

Relative:
Lower

Actual:
28 ft.

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - MANHOLE 4964
Facility address:	909 METROPOLITAN AVE BROOKLYN, NY 11211
EPA ID:	NYP004186011
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY

CON EDISON - MANHOLE 4964 (Continued) **1014396337**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/23/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/23/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

CON EDISON - MANHOLE 4964 (Continued) **1014396337**

Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 07/23/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004186011
Mail Address: 4 IRVING PLACE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: FRANKLYN MURRAY
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 000894673GBF
EPA ID: NYP004186011
Date Shipped: 08/05/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/05/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/06/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

CON EDISON - MANHOLE 4964 (Continued) **1014396337**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	400 G

NY MANIFEST:

EPA ID:	NYP004186011
Country:	USA
Location Address 1:	909 METROPOLITAN AVE
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON
Contact:	FRANKLYN MURRAY
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-2808

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2009
Trans1 Recv Date:	08/05/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/06/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004186011
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported

CON EDISON - MANHOLE 4964 (Continued) **1014396337**

Quantity:	400.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000894673GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

---

47 **EDR US Hist Auto Stat** **1015604146**
South **70 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.129 mi.
682 ft.

Relative:
Higher

Actual:
43 ft.

EDR Historical Auto Stations:

Name:	D & L TIRE SHOP
Year:	2001
Address:	70 BUSHWICK AVE
Name:	D & L TIRE SHOP
Year:	2002
Address:	70 BUSHWICK AVE
Name:	D & L TIRE SHOP
Year:	2005
Address:	70 BUSHWICK AVE

O48 **CON EDISON** **NY MANIFEST** **S117065826**
West **FO 764 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.130 mi.
688 ft. **Site 1 of 2 in cluster O**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:

EPA ID:	NYP004584215
Country:	USA
Location Address 1:	FO 764 METROPOLITAN AVE
Location Address 2:	STRUCTURE 15318
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON

CON EDISON (Continued) **S117065826**

Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/02/2014
Trans1 Recv Date: 07/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004584215
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 80
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002503903GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

K49 **JENNINGS HALLL HDFC** **NY UST** **U004047255**
SSE **260 POWERS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.131 mi.
690 ft. **Site 2 of 2 in cluster K**

Relative:
Higher

Actual:
42 ft.

UST:
Id/Status: 2-608986 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 06/25/2014
UTM X: 589491.69299999997
UTM Y: 4507406.0120000001

JENNINGS HALLL HDFC (Continued) **U004047255**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30833
Affiliation Type: Mail Contact
Company Name: CA RICH CONSULTANTS, INC.
Contact Type: Not reported
Contact Name: JESSICA PROSCIA
Address1: 17 DUPONT STREET
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 576-8844
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/17/2010

Site Id: 30833
Affiliation Type: On-Site Operator
Company Name: JENNINGS HALLL HDFC
Contact Type: Not reported
Contact Name: JOSE ECHAVARRIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 782-3390
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30833
Affiliation Type: Emergency Contact
Company Name: JENNINGS HALL HDFC
Contact Type: Not reported
Contact Name: MARIE IEANZA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 782-3390
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30833
Affiliation Type: Facility Owner
Company Name: JENNINGS HALL, LP
Contact Type: VP

JENNINGS HALLL HDFC (Continued) **U004047255**

Contact Name:	JOSE ECHAVARRIA
Address1:	260 POWERS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 782-3390
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2/17/2010

Tank Info:

Tank Number:	001
Tank ID:	66089
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	20000
Install Date:	01/01/1930
Date Tank Closed:	11/23/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	01/03/2008
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	02/17/2010

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None

L50 **EDR US Hist Auto Stat** **1015366575**
North **253 SKILLMAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.132 mi.
697 ft. **Site 2 of 2 in cluster L**

Relative:
Lower

Actual:
32 ft.

EDR Historical Auto Stations:

Name:	TWO BROTHERS AUTO SALES
Year:	2006
Address:	253 SKILLMAN AVE
Name:	TWO BROTHERS AUTO SALES

(Continued) **1015366575**

Year: 2007
Address: 253 SKILLMAN AVE

O51 **EDR US Hist Cleaners** **1015094499**
West **765 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.139 mi.
734 ft. **Site 2 of 2 in cluster O**

Relative:
Higher

Actual:
38 ft.

EDR Historical Cleaners:

Name: COURTSIDE CLEANERS
Year: 2001
Address: 765 METROPOLITAN AVE

Name: COURTSIDE CLEANERS
Year: 2002
Address: 765 METROPOLITAN AVE

Name: RAFAEL S CLEANERS
Year: 2005
Address: 765 METROPOLITAN AVE

Name: RAFAEL S CLEANERS
Year: 2006
Address: 765 METROPOLITAN AVE

Name: RAFAELS CLEANERS CORP
Year: 2007
Address: 765 METROPOLITAN AVE

Name: RAFAELS CLEANERS CORP
Year: 2010
Address: 765 METROPOLITAN AVE

Name: RAFAELS CLEANERS CORP
Year: 2011
Address: 765 METROPOLITAN AVE

Name: RAFAELS CLEANERS CORP
Year: 2012
Address: 765 METROPOLITAN AVE

P52 **CON EDISON** **NY MANIFEST** **S117318914**
East **FRONT OF 921 METROPOLITAN AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.143 mi.
757 ft. **Site 1 of 2 in cluster P**

Relative:
Lower

Actual:
27 ft.

NY MANIFEST:

EPA ID: NYP004665121
Country: USA
Location Address 1: FRONT OF 921 METROPOLITAN AV
Location Address 2: SB15331
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211

CON EDISON (Continued) **S117318914**

Location Zip Code 4: Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/24/2014
Trans1 Recv Date:	09/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004665121
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	90
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002617589GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

53
SE
1/8-1/4
0.144 mi.
762 ft.

ST NICHOLAS R C CHURCH
26 OLIVE ST
BROOKLYN, NY 11211

NY AST **U003386427**
NY HIST AST **N/A**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-241253
Program Type:	PBS
UTM X:	589681.77517000004
UTM Y:	4507453.8023800002
Expiration Date:	06/30/2007
Site Type:	School

Affiliation Records:

Site Id:	9181
Affiliation Type:	Facility Owner
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	26 OLIVE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9181
Affiliation Type:	Mail Contact
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	REV. KENNETH J. GRANDE
Address1:	26 OLIVE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9181
Affiliation Type:	On-Site Operator
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	MARIO A. CASRTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported

ST NICHOLAS R C CHURCH (Continued) **U003386427**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9181
Affiliation Type:	Emergency Contact
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	KENNETH J. GRANDE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	9924
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
H04 - Tank Leak Detection - Groundwater Well

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT

ST NICHOLAS R C CHURCH (Continued) **U003386427**

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:
PBS Number: 2-241253
SWIS Code: 6101
Operator: LUIS CORREA
Facility Phone: (718) 388-1420
Facility Addr2: 26 OLIVE ST
Facility Type: OTHER
Emergency: PEDRO N. OSSA
Emergency Tel: (718) 388-1420
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: ST NICHOLAS R C CHURCH
Owner Address: 26 OLIVE ST
Owner City,St,Zip: BROOKLYN, NY 11211
Federal ID: Not reported
Owner Tel: (718) 388-1420
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: REV. PEDRO N. OSSA
Mailing Name: ST NICHOLAS R C CHURCH
Mailing Address: 26 OLIVE ST
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11211
Mailing Telephone: (718) 388-1420
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 06/23/1997
Expiration: 06/30/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 4000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 4000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

ST NICHOLAS R C CHURCH (Continued) **U003386427**

Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	3
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

---

54 **CON EDISON** **NY MANIFEST** **S117062666**
SE **FO 269 POWERS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.146 mi.
770 ft.

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:

EPA ID:	NYP004550364
Country:	USA
Location Address 1:	FO 269 POWERS ST
Location Address 2:	STRUCTURE 16523
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004550364
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117062666**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002423374GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

N55 **CON EDISON** **NY MANIFEST** **S117316628**
WSW **180 DEVOE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.149 mi.
785 ft. **Site 2 of 3 in cluster N**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:

EPA ID:	NYP004639126
Country:	USA
Location Address 1:	180 DEVOE ST
Location Address 2:	SB12353
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2014
Trans1 Recv Date:	08/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/2014

CON EDISON (Continued) **S117316628**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004639126
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002504261GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

N56 **CON EDISON** **NY MANIFEST** **S117313402**
WSW **180 DEVOE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.149 mi.
785 ft. **Site 3 of 3 in cluster N**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:

EPA ID:	NYP004539126
Country:	USA
Location Address 1:	180 DEVOE ST
Location Address 2:	SB12353
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

P57 **CON EDISON** **NY MANIFEST** **S117059507**
East **925 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.149 mi.
788 ft. **Site 2 of 2 in cluster P**

Relative:
Lower

Actual:
27 ft.

NY MANIFEST:

EPA ID:	NYP004516795
Country:	USA
Location Address 1:	925 METROPOLITAN AVE
Location Address 2:	SB 15331
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004516795
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002417603GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117059507**

Mgmt Method Type Code: H110

Q58 **EDR US Hist Cleaners** **1015045329**
West **334 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.160 mi.
844 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
37 ft.

EDR Historical Cleaners:

Name:	GATTI LOUIS DRY CLEANERS
Year:	2001
Address:	334 GRAHAM AVE
Name:	GATTI LOUIS DRY CLEANERS
Year:	2003
Address:	334 GRAHAM AVE
Name:	PARK GATTI CLEANER
Year:	2009
Address:	334 GRAHAM AVE
Name:	GATTI CLEANERS
Year:	2010
Address:	334 GRAHAM AVE

Q59 **GATTI CLEANERS** **RCRA NonGen / NLR** **1000411242**
West **334 GRAHAM AVE** **NY MANIFEST** **NYD982743981**
1/8-1/4 **BROOKLYN, NY 11211** **US AIRS**
0.160 mi.
844 ft. **Site 2 of 4 in cluster Q**

Relative:
Higher

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GATTI CLEANERS
Facility address:	334 GRAHAM AVE BROOKLYN, NY 112113736
EPA ID:	NYD982743981
Mailing address:	GRAHAM AVE BROOKLYN, NY 11211
Contact:	Not reported
Contact address:	GRAHAM AVE BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNKNOWN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private

GATTI CLEANERS (Continued) **1000411242**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: UNKNOWN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GATTI CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: GATTI CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/17/1989
Site name: GATTI CLEANERS
Classification: Large Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

GATTI CLEANERS (Continued) **1000411242**

NY MANIFEST:

EPA ID:	NYD982743981
Country:	USA
Location Address 1:	334 GRAHAM AVE
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	GATTI CLNRS
Contact:	GATTI CLNRS
Address:	334 GRAHAM AVENUE
City/State/Zip:	BROOKLYN, NY 11211
Country:	USA
Phone:	718-388-6776

Manifest:

Document ID:	NYC4762528
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	HQ80784
Generator Ship Date:	06/16/1997
Trans1 Recv Date:	06/16/1997
Trans2 Recv Date:	06/23/1997
TSD Site Recv Date:	06/25/1997
Part A Recv Date:	07/08/1997
Part B Recv Date:	07/18/1997
Generator EPA ID:	NYD982743981
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4412430
Manifest Status:	Completed copy
Trans1 State ID:	NYGF2859
Trans2 State ID:	M0001
Generator Ship Date:	01/03/1997
Trans1 Recv Date:	01/03/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/09/1997
Part A Recv Date:	01/17/1997
Part B Recv Date:	01/24/1997
Generator EPA ID:	NYD982743981
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998

GATTI CLEANERS (Continued) **1000411242**

TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

Document ID: NYC3955296
Manifest Status: Completed copy
Trans1 State ID: GE2859NY
Trans2 State ID: Not reported
Generator Ship Date: 01/24/1996
Trans1 Recv Date: 01/24/1996
Trans2 Recv Date: / /
TSD Site Recv Date: 01/31/1996
Part A Recv Date: 02/01/1996
Part B Recv Date: 02/15/1996
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1996

Document ID: NYC4191761
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GF2859NY
Trans2 State ID: 1643BCOK
Generator Ship Date: 07/17/1996
Trans1 Recv Date: 07/17/1996
Trans2 Recv Date: 07/19/1996
TSD Site Recv Date: 07/20/1996
Part A Recv Date: 07/29/1996
Part B Recv Date: 08/12/1996
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ARD981908551
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1996

GATTI CLEANERS (Continued) **1000411242**

Document ID:	NYA9542913
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	12/29/1989
Trans1 Recv Date:	12/29/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/29/1989
Part A Recv Date:	01/03/1990
Part B Recv Date:	01/05/1990
Generator EPA ID:	NYD982743981
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1989

Document ID:	NYC1313302
Manifest Status:	Completed copy
Trans1 State ID:	HW8207NY
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1992
Trans1 Recv Date:	02/28/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1992
Part A Recv Date:	03/10/1992
Part B Recv Date:	03/09/1992
Generator EPA ID:	NYD982743981
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1992

Document ID:	NYC0759508
Manifest Status:	Completed copy
Trans1 State ID:	AM6252
Trans2 State ID:	Not reported
Generator Ship Date:	05/02/1991
Trans1 Recv Date:	05/02/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/02/1991
Part A Recv Date:	05/20/1991

GATTI CLEANERS (Continued) **1000411242**

Part B Recv Date: 05/14/1991
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1991

Document ID: NYA9542463
Manifest Status: Completed copy
Trans1 State ID: EU1132NY
Trans2 State ID: Not reported
Generator Ship Date: 02/23/1990
Trans1 Recv Date: 02/23/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 02/23/1990
Part A Recv Date: 03/14/1990
Part B Recv Date: 03/15/1990
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1990

Document ID: NYC0550405
Manifest Status: Completed copy
Trans1 State ID: EU1732NY
Trans2 State ID: Not reported
Generator Ship Date: 10/26/1990
Trans1 Recv Date: 10/26/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 10/26/1990
Part A Recv Date: 11/07/1990
Part B Recv Date: 11/09/1990
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001

GATTI CLEANERS (Continued) **1000411242**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

Document ID: NYC2081935
Manifest Status: Completed copy
Trans1 State ID: JE4550NY
Trans2 State ID: Not reported
Generator Ship Date: 08/23/1993
Trans1 Recv Date: 08/23/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 08/23/1993
Part A Recv Date: 08/31/1993
Part B Recv Date: 09/01/1993
Generator EPA ID: NYD982743981
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

AIRS (AFS):

Airs Minor Details:
EPA plant ID: 110004424141
Plant name: NEW GATTI CLEANERS
Plant address: 334 GRAHAM AVE
BROOKLYN, NY 112113736
County: KINGS
Region code: 02
Dunn & Bradst #: Not reported
Air quality cntrl region: 043
Sic code: 7216
Sic code desc: DRYCLEANING PLANTS, EXCEPT RUG
North Am. industrial classf: 812320
NAIC code description: Drycleaning and Laundry Services (except Coin-Operated)
Default compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV: Not reported

Compliance and Enforcement Major Issues:
Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

GATTI CLEANERS (Continued) **1000411242**

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00660
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00660
Penalty amount: Not reported

Air program: Not reported
National action type: Not reported
Date achieved: Not reported
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1402
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1304
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

GATTI CLEANERS (Continued) **1000411242**

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1403
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1402
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1401
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1304
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

GATTI CLEANERS (Continued) **1000411242**

Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1403
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1401
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: MACT (SECTION 63 NESHAPS)

Compliance & Violation Data by Minor Sources:
Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: UNCLASSIFIED

GATTI CLEANERS (Continued) **1000411242**

Repeat violator date: Not reported
Turnover compliance: Not reported

Q60
West
1/8-1/4
0.160 mi.
844 ft.

NEW GATTI/PARK/LOUIS CLEANERS **NY DRYCLEANERS** **S110247428**
334 GRAHAM AVENUE **N/A**
BROOKLYN, NY 11211

Site 3 of 4 in cluster Q

Relative:
Higher

Actual:
37 ft.

DRYCLEANERS:
Facility ID: 2-6101-00992
Phone Number: 718-388-6776
Region: Not reported
Registration Effective Date: 9/5/2002 10:54:27:38
Inspection Date: 07APR18
Install Date: 94
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

61
North
1/8-1/4
0.165 mi.
872 ft.

CON EDISON **NY MANIFEST** **S117059244**
231 JACKSON ST **N/A**
BROOKLYN, NY 11201

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:
EPA ID: NYP004514030
Country: USA
Location Address 1: 231 JACKSON ST
Location Address 2: SB12570
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/28/2014
Trans1 Recv Date: 04/28/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/29/2014

CON EDISON (Continued) **S117059244**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004514030
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002417918GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

R62
ESE
1/8-1/4
0.169 mi.
894 ft.

Relative:
Lower

Actual:
28 ft.

CON EDISON **NY MANIFEST** **S117061900**
OPP 285 DEVOE ST **N/A**
BROOKLYN, NY 11211

Site 1 of 2 in cluster R

NY MANIFEST:

EPA ID:	NYP004542270
Country:	USA
Location Address 1:	OPP 285 DEVOE ST
Location Address 2:	SB 63869
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/23/2014

CON EDISON (Continued) **S117061900**

Trans1 Recv Date:	05/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004542270
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002423684GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

S63 **RESIDENCE** **NY LTANKS S106971706**
North **243 JACKSON STREET** **NY Spills N/A**
1/8-1/4 **BROOKLYN, NY**
0.170 mi.
900 ft. **Site 1 of 2 in cluster S**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	334346
Spill Number/Closed Date:	0409577 / 2/4/2005
Spill Date:	11/26/2004
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	11/26/2004
CID:	409
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/29/2004

RESIDENCE (Continued) **S106971706**

Spill Record Last Update:	4/20/2005
Spiller Name:	ALBERT LONG
Spiller Company:	RESIDENCE
Spiller Address:	243 JACKSON STREET
Spiller City,St,Zip:	BROOKLYN, NY 11237
Spiller County:	001
Spiller Contact:	ALBERT LONG
Spiller Phone:	(718) 349-6697
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	269562
DEC Memo:	2/4/05 TJDDemeo was contacted by the property owner. He has completed the removal of his 275 AST and converted to gas. According to the property owner the floor beneath the tank is in good shape, no holes or cracks in the concrete. Petro completed the cleanup immediately following the reported spill using absorbents. No lingering petroleum vapors inside residence. Based upon the property owners statements spill is closed. No further action required.
Remarks:	two thirty five tanks leakng closer to the wall. in the basement. crews not on the way :not cleaned up

Material:

Site ID:	334346
Operable Unit ID:	1096485
Operable Unit:	01
Material ID:	576423
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPILLS:

Facility ID:	1113750
Facility Type:	ER
DER Facility ID:	269562
Site ID:	461762
DEC Region:	2
Spill Date:	3/9/2012
Spill Number/Closed Date:	1113750 / 3/26/2012
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	3/9/2012
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown

RESIDENCE (Continued) **S106971706**

Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	3/9/2012
Spill Record Last Update:	3/26/2012
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ANDREW KELLY
Contact Phone:	(718) 595-4761
DEC Memo:	03/09/12-Hiralkumar Patel.2:56 PM:- spoke with Andrew at DEP. he mentioned that owner of 243 Jackson Street reported an oil seepage into his basement. Andrew inspected site and found few ounces of oil seeping through basement wall. there is a gas heating system at impacted site. he tried to inspect next door building at 31 Kingsland Ave, but no success.3:03 PM:- spoke with Albert Long, owner of 243 Jackson Street. he owns 243 Jackson street (property at the northwest corner of Jackson Street and Kingsland Ave). he mentioned that oil found in basement of his building. he has gas heating system, but building at 31 Kingsland Ave has oil heating system.Albert Long **owner of building 243**1417 Jefferson AvenueBrooklyn, NY 11237Ph. (347) 247-9543email: cienlada@aol.comMellys LongPh. (347) 987-9541as per DOB application approved on 12/28/04, oil burner was replaced with gas burner at Mr. Long's property. <----------alternate address for 243 Jackson Street: 243-251 Jackson Street, 31A Kingsland Aveno PBS record found for 243 Jackson Street.old spill # 0409577 found for 243 Jackson Street. the spill was reported on 11/26/04 due to a petroleum release from a 275 gal tank located closer to the wall. the case was closed based on property owner's statement, but no cleanup report submitted.alternate address for 31 Kingsland Ave: noneno PBS or spill record found for 31 Kingsland Ave.4:00 PM:- visited site. met Teresa, building super for 243 Jackson St. its four story buiding with basement. building 243 runs east-west along the north side of Jackson Street. ground floor of the buiding 243 is occupied by: a grocery store (Neighborhood Grocery) at the eastern end of the property (at the northwest corner of the intersection of Jackson St and Kingsland Ave), apartment building entrance in middle and a restaurant (718-349-2400) on the western end of the property. inspected basements under the apartment building and grocery store. found oil on water in the northwest corner of the grocery store basement. oil/water mix also found in the northeast corner of the apartment basement, at the end of the basement stairs. the boiler room is located in the eastern part of the apartment basement. there is a small open area behind the boiler room, between the subject site and the adjacent building at 31 Kingsland Ave. found oil/water in this open area. during inspection, minor odors noticed in basements.inspected basement at building 31 Kingsland Ave. suspected site has two 275 gal ASTs on legs. no sign of oil spill found under the tanks. fill and vent lines runs aboveground. the two tanks are located along the southern foundation wall in the eastern part of the basement. tank location is along the grocery store basement at

RESIDENCE (Continued) **S106971706**

building 243. boiler at building 31 is located in the northwestern corner of the basement and supply line between the tank and boiler runs underground. basement at building 31 is about 4 ft higher than basement at building 243.based on location of tanks at building 31 and most impact in the grocery basement at building 243, oil may have spilled from an underground supply line at building 31.03/12/12-Hiralkumar Patel.12:54 PM:- left message for Mr. Long.1:15 PM:- visited site. met Mr. Long. inspected basement under the restaurant, the apartment and the grocery store.its a finished basement under the restaurant. no sign of any water or oil seepage found in the basement.during site inspection, Mr. Long showed location of his old tanks. the tanks at building 243 were located along the southern foundation wall in center of the basement and just right of the basement entrance (which is left of the restaurant entrance) from sidewalk. Mr. Long mentioned that fill port and a vent line for old tanks in his building were located just left of the apartment building entrance (in area between the apartment entrance and restaurant entrance). no sign of oil/water seepage found where the old tanks were located. inspected other parts of basement where oily water observed during site visit on 03/09/12. no oil found at the end of the basement stairs or boiler room or an open area behind the boiler room. during today's inspection, found a drain in the open area and a drain pipe going towards the grocery basement. its looks like whatever oil found in open area and in the northeast corner of the apartment basement, might have came through the drain pipe from the grocery basement.during inspection of the grocery basement, found a sump like structure in the northwest corner and oil/water in the corner. asked Mr. Long to remove oily water and seal the corner which will prevent further seepage.Mr. Long mentioned that they had changed a main sewer line about 8 months ago, but they never so oil seepage before. oil spill found by grocery store person when they noticed petroleum odors in grocery basement about two weeks ago.during inspection, met Lorenzo Ayala, president of co-op board for building 31. there are six co-op units in the building. discussed about possible leak from an underground supply line at building 31. asked him to perform a tightness test of the line and submit result by the end of 03/14/12.31 Kingsland Ave Housing Development Fund Corporation **owner of building 31**c/o Lorenzo Ayala **co-op president**31 Kingsland Avenue, Unit 1RBrooklyn, NY 11211Ph. (347) 251-4123Erica Erazo **co-op unit owner at building 31**31 Kingsland Avenue, Apt. 2RBrooklyn, NY 11211Diana Hodge **co-op unit owner at building 31**31 Kingsland Avenue, Apt. 2LBrooklyn, NY 112113:28 PM:- spoke with Dennis at Ferrentino Fuel and requested a copy of delivery record for building 31 from Jan. 2011 to Mar. 2012. he asked to send email.Dennis GoldsteinFerrentino Fuel **oil delivery company for building 31**Ph. (718) 832-6700email: dennis@ffcenergy.com3:30 PM:- sent email to Dennis and asked to send delivery record from Jan. 2011 to Mar. 2012.based on available information, chagned following information in the original spill report (see copy on e-docs):- spill name: "intersection" to "apartment building"- site address: "Jackson St & Kingsland Ave" to " 243 Jackson Street"3:54 PM:- left message from Mr. Long.03/13/12-Hiralkumar Patel.10:16 AM:- spoke with Mr. Long. they are going to pump out oil/water today. asked him to call for inspection after pump out and prior to sealing the sump.10:32 AM:- received call from Mr. Ayala. he mentioned that about two weeks ago, building 39 Kingsland Ave changed from oil to gas heating system and Mr. Ayala suspects that owner of building 39 has dumped excess

RESIDENCE (Continued) **S106971706**

oil into sewer system. he asked to meet at the site and will provide evidence. informed him that regardless of findings at building 39, the department still requires tightness test of the supply line in his building. informed him about possible site visit tomorrow morning. he will try to have line test done during the site inspection tomorrow morning.10:40 AM:- received email from Ferrantino Fuel including delivery record for bldg 31 from Oct. 2011 to Mar. 2012. based on delivery record, occupants of bldg 31 used average of about 17-19 gal per day since Oct. 2011 and there is no sudden increase in oil use.03/15/12-Hiralkumar Patel.10:00 AM:- visited site. inspected grocery store basement. oily water was removed from basement, but some more oil came into sump. asked cleanup guy to remove the product from sump.spoke with Mr. Ayala. he mentioned that a technician from his own company checked the system and confirms no leak. informed him that a tightness test of the supply line must be performed and a certified result must be submitted to the Department. Mr. Ayala mentioned that his sister lives in building 39 and will call back with landlord's number for building 39.10:32 AM:- received message from Mr. Ayala with contact info for property owner for building 39.Zev Zafir Inc. **owner of 39 Kingsland Ave**Shloma StuhlPresident543 Bedford Avenue #239Brooklyn, NY 11211Ph. (718) 387-75841:10 PM:- spoke with Mr. Long. suggest him to continue cleanup. asked him to call for site inspection before he seal the sump.2:43 PM:- left message at Zev Zafir Inc.3:00 PM:- received call from Shloma Stuhl from Zev Zafir Inc. he mentioned that they have gas heating system for more than six months. they only modified gas line on 03/01/12. scheduled a site inspection at 10 AM tomorrow morning. George (917-721-2470) will provide access to building 39.03/16/12-Hiralkumar Patel. called George multiple times, but no answer. did not visited building 39.03/19/12-Hiralkumar Patel.3:45 PM:- visited site. inspected grocery basement. oil hasn't cleaned up yet. no increase in the amount.03/21/12-Hiralkumar Patel.9:27 AM:- left message for Mr. Long. informed him that spill in grocery store basement must be cleaned up immediately.03/22/12-Hiralkumar Patel.03/23/12-Hiralkumar Patel.2:04 PM:- spoke with Mr. Long. he mentioned that contractor pumped out oily water from sump until it cleared out.2:09 PM:- spoke with Elizabeth at 95 Inc., contractor who pumped out oil/water. she mentioned that they pumped out about 50 gal of oily water. she will ask driver to call back, who responded to the site.Elizabeth95 Inc.Ph. (631) 842-98172:23 PM:- received call from Dino, driver from 95 Inc. he mentioned that after pumping about 50 gal, he found mostly clear water.03/26/12-Hiralkumar Patel.9:15 AM:- visited site. inspected grocery store basement. found mostly muddy water, with some oily water (less than 1 ft by 1 ft area) away from sump area.received fax from Elizabeth including a disposal manifest.3:35 PM:- spoke with Mr. Long. asked him to remove the last spot of oily water. informed him that as no more oil coming into the basement, case can be closed. suggested him to seal the basement.after discussing with DEC Austin, case closed.

Remarks: Oil suspected to be coming from 33 Kingsland Ave. DEP unable to gain access to bldg. Unknown owner at this time. Further is pending.

Material:
Site ID: 461762
Operable Unit ID: 1211843
Operable Unit: 01
Material ID: 2209666
Material Code: 0001A

RESIDENCE (Continued) **S106971706**

Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0.01
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Q64 **CON EDISON SERVICE BOX: 12945** **RCRA NonGen / NLR 1016964271**
WSW **327 GRAHAM AVE** **NY MANIFEST NYP004372058**
1/8-1/4 **BROOKLYN, NY 11211**
0.173 mi.
915 ft. **Site 4 of 4 in cluster Q**

Relative:
Higher

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/09/2013
Facility name:	CON EDISON SERVICE BOX: 12945
Facility address:	327 GRAHAM AVE BROOKLYN, NY 11211
EPA ID:	NYP004372058
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/09/2013
Site name:	CON EDISON SERVICE BOX: 12945

CON EDISON SERVICE BOX: 12945 (Continued) **1016964271**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004372058
Country: USA
Location Address 1: 327 GRAHAM AVE
Location Address 2: SB12945
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 10/09/2013
Trans1 Recv Date: 10/09/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/10/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004372058
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 30
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 002291296GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

65
NW
1/8-1/4
0.174 mi.
917 ft.

177 SKILLMAN AVE
BROOKLYN, NY 11211

EDR US Hist Auto Stat **1015274609**
N/A

Relative:
Lower

Actual:
31 ft.

EDR Historical Auto Stations:

Name:	ERROL AUTO REPAIR
Year:	2001
Address:	177 SKILLMAN AVE
Name:	ERROL AUTO REPAIR
Year:	2003
Address:	177 SKILLMAN AVE

R66
ESE
1/8-1/4
0.174 mi.
919 ft.

CON EDISON
312 DEVOE ST
BROOKLYN, NY 11211

Site 2 of 2 in cluster R

NY MANIFEST **S117062156**
N/A

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:

EPA ID:	NYP004544888
Country:	USA
Location Address 1:	312 DEVOE ST
Location Address 2:	SB 63869
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/28/2014
Trans1 Recv Date:	05/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004544888
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117062156**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013245748JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

67
WSW
1/8-1/4
0.174 mi.
921 ft.

326 GRAHAM AVE **NY UST** **U004045416**
326 GRAHAM AVENUE **N/A**
BROOKLYN, NY 11211

Relative:
Higher

Actual:
38 ft.

UST:

Id/Status:	2-608719 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/31/2008
UTM X:	589177.27231000003
UTM Y:	4507531.3454099996
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30571
Affiliation Type:	Facility Owner
Company Name:	HARVEY S. ROSENBLUM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	326 GRAHAM AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 291-5510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/8/2008

Site Id:	30571
Affiliation Type:	Mail Contact
Company Name:	HARVEY S. ROSENBLUM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	326 GRAHAM AVENUE
Address2:	Not reported
City:	BROOKLYN

326 GRAHAM AVE (Continued) **U004045416**

State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 291-5510
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/8/2008

Site Id: 30571
Affiliation Type: On-Site Operator
Company Name: 326 GRAHAM AVE
Contact Type: Not reported
Contact Name: HARVEY S. ROSENBLUM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 291-5510
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30571
Affiliation Type: Emergency Contact
Company Name: HARVEY S. ROSENBLUM
Contact Type: Not reported
Contact Name: HARVEY S. ROSENBLUM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 291-5510
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 101000
Tank ID: 65562
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1500
Install Date: 01/01/1950
Date Tank Closed: 03/28/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

326 GRAHAM AVE (Continued) **U004045416**

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/08/2008

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

68
SSE
1/8-1/4
0.177 mi.
935 ft.

Relative:
Higher

Actual:
43 ft.

FORMER BENNETT TRUCKING CORP. **NY Spills** **S113818149**
845 GRAND STREET **NY BROWNFIELDS** **N/A**
BROOKLYN, NY 11211

SPILLS:

Facility ID:	1303007
Facility Type:	ER
DER Facility ID:	438674
Site ID:	483468
DEC Region:	2
Spill Date:	6/19/2013
Spill Number/Closed Date:	1303007 / Not Reported
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Investigator:	ljalden
Referred To:	Not reported
Reported to Dept:	6/19/2013
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	6/19/2013
Spill Record Last Update:	8/29/2014
Spiller Name:	Not reported
Spiller Company:	COMMERCIAL PROPERTY/OLD LAUNDRY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CHARLES
Contact Phone:	Not reported

FORMER BENNETT TRUCKING CORP. (Continued) **S113818149**

DEC Memo: Vacant lot, previously used as laundromat and auto repair shop.Gasoline compound in soil samples detected. Phase I and Phase II report will be sent to Kumar Patel.(sr)06/24/13-Hiralkumar Patel.alternate address: noneno PBS or other spill record found.10:13 AM:- spoke with Charles. he mentioned that current owner baught this property recently and did Phase I and limited Phase II investigation. Charles mentioned that gasoline tank found on old sanborn maps and site was auto repair shop in past. sometime in past, front part of onsite building was demolished to create parking lot. recently the site was used as laundromat and dry cleaning drop-off. currently, site is vacant. asked Charles to submit available environmental reports for review. also asked to provide property owner's contact information. Charles mentioned that property owner is planning to meet DEC Jane to discuss enrollment in BCP.06/26/13-Hiralkumar Patel.1:34 PM:- left message for Charles and asked to submit environmental reports/data.07/03/13-Hiralkumar Patel.11:06 AM:- left message for Charles.Charles SosikEBCPh. (631) 504-6000 (O) (631) 357-4927 (C)email: csosik@ebcincny.com07/08/13-Hiralkumar Patel.10:51 AM:- received email from Charles including summary of Phase I, Phase II boring logs, sample results and site map. Charles mentioned that property owner had meeting with DEC Jane (and central office) last week and will submit BCP application.email did not included complete Phase I or Phase II reports.two borings were installed near suspected gasoline UST, to a depth of 15 ft bg. in both borings, 10 ppm recorded on PID in 10 to 15 ft interval only. no odors or PID readings noted above 10 ft depth. found VOC compounds in soil samples.soil analyticals:----------B1----------B2
10-13 ft 13-15
ftEthylbenzene----------230----------1,
300Xylene----------690----------6,9001,2,
4-Trimethylbenzene--1,400----------5,5001,3,
5-Trimethylbenzene----450----------1,
400Naphthalene----------290----------1,20007/11/13-Hiralkumar Patel.12:30 PM:- spoke with Charles. asked him to submit complete Phase I report. asked him about Phase II report. he mentioned that borings were installed around tank to find any contamination or not. they received sample results and discussed with DEC Jane and DEC Cozzy regarding enrollment into BCP. they haven't prepared any Phase II report. asked Charles to submit written investigation report with all details. currently, they are preparing BCP application. informed Charles that the department may require further delineation before even BCP application reviewed.12:43 PM:- received Phase I report from Charles. abstract:- block #: 2922 / lot #: 47- site was an undeveloped portion of a larger residential property from at least 1888 through 1907. by 1928, the site was developed with a garage, later occupied by a motor freight company. by 1977, the building was occupied by a warehouse and non-specific commercial uses, with tenants including a sanitation company and a coffee distributor. circa 2009, the building was converted to its current use as a laundromat, dry cleaning drop off facility, and a retail store- one gasoline tank on sanborn maps for the years 1933 through 1967- gasoline tank presumed to be an UST located at the south-central portion of the building ---------- E designation (E-232) for hazmat and noise ---------- depth to groundwater at the site is approx. 37 ft bg ---------- based on regional groundwater contour maps, groundwater flow is expected to be east-southeast toward English Kills ---------- property is currently developed

FORMER BENNETT TRUCKING CORP. (Continued) **S113818149**

with a one-story commercial building with a partial basement- building is divided into two commercial/retail units: western unit is occupied by Grand Central Laundromat, a retail laundromat and dry cleaner; eastern unit is currently vacant, but was most recently occupied by Interstate Laundry Parts and Equipment- small asphalt-paved parking lot area is located in front of the building along Grand St- parking lot was formerly covered by the site building, until site renovations conducted circa 2009 reduced the building footprint to create customer parking- majority of the building basement extends beneath the far western section of the parking lot- building heated and supplied hot water by natural gas-fired equipment ---------- properties across Grand street to the south have been developed with the existing school, identified as the Northeast Brooklyn High School and reportedly constructed between 1975 and 1980 ---------- no evidence of ASTs or USTs (e.g., vent or fill lines) was observed on the property- no exterior storm drains were identified on the property and no interior floor drains were observed at the time of inspection- potential buyer: Joel Braver of Express Builders JB, Inc. ----------2:20 PM:- sent email to Charles. asked him to submit detailed report of recent Phase II investigation and contact information of property owner/buyer.07/23/13-Hiralkumar Patel.12:42 PM:- spoke with Charles. asked him to submit property owner's information. regarding Phase II, Charles mentioned that Phase II report will be preapred after further investigation required under BCP, if application approved.08/13/13-Hiralkumar Patel. discussed with DEC Jane regarding BCP application. she mentioned that property owner has to conduct required investigation/remediation, even BCP application is rejected.spoke with Charles from Jane's office. Charles submitted BCP application today including investigation work plan. asked Charles to submit property owner's contact information.2:45 PM:- received email from Charles including property owner's information.845 Grand Development LLC. **property owner**11 Hayes Avenue, Suite 201Monroe, NY 10950Attn.: Yidal Hirsch09/10/13-Hiralkumar Patel. discussed with DEC Jane. a BCP application (C224181) has been received and currently it is under review. she mentioned that it will take couple of months (probably end of Dec. 2013) prior to having a signed agreement, if accepted by the department and property owner.sent email to Larry Alden, BCP project manager in Albany.reviewed RIWP submitted in BCP application. abstract:- redevelopment plans for the site include demolishing the existing commercial building and replacing it with a new multi-family residential apartment building with a full basement level- based upon results of previous investigations, subsurface soils at the site consist of a silty non-native fill with bricks, wood and other rubble to approx. 5 to 15 ft bg. a native fine brown silty-sand is present immediately below the fill material- based upon regional groundwater contour maps, and measurements made at adjacent properties, the depth to groundwater beneath the site is approx. 35 ft bg and flows west-northwest toward the East River- according to USGS topographic map, the elevation of the property is 39 ft above the National Geodetic Vertical Datum- propose to conduct geophysical survey of the southern portion of the property in the vicinity of the former US-propose to install total nine soil borings (four around former UST and five in other parts of the site), four groundwater wells and six soil-gas probes- four borings (SB6 through SB9) will be installed in vicinity of former UST. these borings will continue to the extent of contamination (based on visual or olfactory) or to the

FORMER BENNETT TRUCKING CORP. (Continued) **S113818149**

water table interface, whichever comes last. if contamination is not present above the water, borings will be advanced to a minimum depth of 5 ft below water table interface- five borings (SB1 through SB5) will be installed to the extent of contamination or to a depth of 15 ft bg, whichever comes last- from borings SB6 through SB9, soil samples will be collected as: one sample at grounwater interface, one from 12 to 14 ft interval and one from highest indication of contamination (if present). samples will be analyzed for VOCs and SVOCs only- one soil sample will be collected from boring SB1 through SB5 for SVOCs, metals, pesticides and PCBs. these samples will be collected from just below the planned excavation level of 12 ft bg- four (4) 1-inch monitoring wells will be installed to a depth of 7 ft below water table, with 10 ft of screen- groundwater samples will be analyzed for VOCs, SVOCs, pesticides, PCBs and metals- soil vapor samples will be taken from 6 soil-gas locations, and analyzed via method TO-15- soil-gas implants at each location will be set at the proposed basement level of the new building which is approx. 12 ft bgthe proposed RIWP needs to be revised for following reason, if site is not accepted in BCP and requires work under spills:- the plan proposes not to analyze samples from SB1 through SB5 for VOCs. the department requires all soil and groundwater samples analyzed for VOCs and SVOCs09/19/13-Hiralkumar Patel.11:47 AM:- spoke with DEC Larry. he mentioned that more data is needed to make determination of the eligibility of the application. DEC Cozzy sent letter to property owner and asked to conduct proposed Phase II.reviewed letter.12:44 PM:- spoke with Larry. informed him that all soil and groundwater samples should be analyzed for VOCs and SVOCs. Larry stated that as site was only drop-off facility for dry cleaning business, there is no need for full list analyses. Larry will inform property owner to analyze all samples for VOCs also.11/26/13-Hiralkumar Patel.5:56 PM:- sent email to Larry inquiring update.11/27/13-Hiralkumar Patel.9:21 AM:- received email from Larry. he mentioned that water sample was collected beneath the area of the former UST, which shows BTEX. Larry mentioned that the site was accepted into the BCP on 11/18/13.12/06/13-Hiralkumar Patel.10:14 AM:- spoke with DEC Larry. as site has been accepted in BCP, case assigned to Larry.**little 'E' designation for Hazmat/Noise.*** ----------8/26/14 - Larry AldenRI work completed at this site and draft RI report and RAWP have been submitted for review. Draft RAWP calls for excavation of soil in vicinity of UST to 15 feet below grade, installation of an SVE system, and treatment of residual groundwater contamination via injection of chemical oxidants and oxygen release compounds.

Remarks: contamination based on lab results/clean up pending

Material:

Site ID:	483468
Operable Unit ID:	1233176
Operable Unit:	01
Material ID:	2232054
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

FORMER BENNETT TRUCKING CORP. (Continued) **S113818149**

Tank Test:

BROWNFIELDS:

Program:	BCP
Site Code:	485965
Acres:	.190
HW Code:	C224181
SWIS:	2401
Town:	New York City
Update By:	MJKOMORO
Site Description:	Location: The site is located on the north side of Grand Street, between Bushwick Avenue and Olive Street, in the East Williamsburg section of Brooklyn. The site is approximately 0.19 acres in size, at an elevation of 39 feet above sea level. The neighborhood includes multi-use units with first floor retail use and residential units. Progress High School (K474) is located directly across Grand Street from the site.Site Features: The site was developed with a one-story commercial building with a partial basement. The original building took up the entire parcel. When the building was converted to a laundromat, the front quarter (ten feet) of the building was removed and a parking lot put in its place. The above-ground portion of the building was razed in June 2014, leaving the slab.Current Zoning/Use: The property is currently vacant but was used for commercial purposes. The site is zoned R-7A residential with a C2-4 commercial overlay. The intended use of the site is restricted-residential.Historic Use: The site was an undeveloped portion of a larger residential property from at least 1888 through 1907. By 1928 the site was developed with a garage, later occupied by a motor freight company. Sanborn maps of the original building identify a buried gas tank located toward the front part of the building. By 1977 the building was occupied by a warehouse and non-specific commercial uses, with tenants including a sanitation company and a coffee distributor. Circa 2009 the building was converted to its final use as a laundromat/dry cleaner drop-off and a retail store.Site Geology and Hydrogeology: Subsurface soils at the site consist of a silty non-native fill with bricks, wood, and rubble to a depth of up to 6 feet below grade. Below that is native material consisting of brown silty sand. Groundwater is present under water table conditions at a depth of approximately 30 feet below the surface and flows southwest, possibly under the influence of dewatering activities associated with the subway line along Bushwick Avenue.
Env Problem:	Nature and Extent of Contamination: The Remedial Investigation for this site consisted of soil samples collected from nine subsurface borings, groundwater from three monitoring wells, and six soil vapor samples from beneath the building slab. Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics, and pesticides/PCBs.Soil: Soil samples were collected from 12-14 feet below grade at all nine borings, and additional deeper samples, up to a maximum depth of 27 feet, were collected from three of the borings.Based on the investigations conducted to date, soil beneath the site in the vicinity of the historic underground storage tank identified on Sanborn maps is contaminated with petroleum-related VOCs, mostly above the unrestricted use soil cleanup objectives (UUSCOs) but below

FORMER BENNETT TRUCKING CORP. (Continued) **S113818149**

the restricted-residential SCOs. Contaminated soil in that area is assumed to be present from a depth of at least 15 feet down to the water table at approximately 30 feet below ground.Historic fill (soil mixed with bricks, concrete, and rubble) was found beneath the building slab at one boring location to a depth of six feet, although samples were not collected for analysis. The investigation identified petroleum-related VOCs at concentrations above UUSCOs in soil samples obtained from borings around the reported underground gasoline storage tank. The VOCs driving the remedy are 1,2,4-trimethylbenzene (maximum concentration 56 parts per million [ppm]) and mixed xylenes (maximum concentration 115 ppm). There were no SVOCs or pesticides/PCBs detected above UUSCOs. Manganese was found above the UUSCOs in one sample. Contaminated soil related to the site does not extend off-site.Groundwater: Based on the investigations conducted to date, groundwater across much of the site is contaminated above standards with petroleum-related VOCs, although no significant groundwater contamination extends off-site. Contaminated groundwater is present both to the northeast and southwest of the contaminated soil, perhaps as a result of dewatering operations at the nearby subway line and station, which may have reversed the natural (to the northeast) groundwater flow gradient.Groundwater had concentrations of petroleum-related VOCs above the drinking water standards. These VOCs were the same as those found in the soil samples. 1,2,4-trimethylbenzene (maximum concentration 490 parts per billion [ppb]; drinking water standard 5 ppb) and mixed xylenes (maximum concentration 2,190 ppb; drinking water standard 5 ppb) were found. A few SVOCs were detected in the low part per trillion range in the samples. Multiple VOCs, including petroleum-related compounds, were detected in the soil vapor samples at low concentrations across the site with totals ranging from 226.9 micrograms per cubic meter (ug/m3) to 1,960.6 ug/m3. The highest concentrations of petroleum-related compounds were detected in the southeast corner of the property.

Health Problem: Since the site is fenced and covered by asphalt or concrete, people will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern because the site is vacant. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings.

S69
NNE
1/8-1/4
0.177 mi.
936 ft.

251 JACKSON ST
BROOKLYN, NY 11211

Site 2 of 2 in cluster S

EDR US Hist Cleaners **1015028195**
N/A

Relative:
Lower

Actual:
32 ft.

EDR Historical Cleaners:

Name:	LONGS LAUNDROMAT
Year:	2002
Address:	251 JACKSON ST
Name:	LONGS LAUNDROMAT
Year:	2003
Address:	251 JACKSON ST
Name:	NIEGHBORHOOD LAUNDROMAT INC
Year:	2004
Address:	251 JACKSON ST
Name:	NEIGHBORHOOD LAUNDROMAT INC
Year:	2004
Address:	251 JACKSON ST
Name:	LONGS LAUNDROMAT
Year:	2005
Address:	251 JACKSON ST

T70
East
1/8-1/4
0.178 mi.
940 ft.

CON EDISON
940 METROPOLITAN AV
BROOKLYN, NY 11201

Site 1 of 4 in cluster T

NY MANIFEST **S117059526**
N/A

Relative:
Lower

Actual:
26 ft.

NY MANIFEST:

EPA ID:	NYP004517009
Country:	USA
Location Address 1:	940 METROPOLITAN AV
Location Address 2:	SB15333
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014

CON EDISON (Continued) **S117059526**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004517009
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002417576GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

T71 **CON EDISON** **NY MANIFEST** **S117063662**
East **945 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.179 mi.
946 ft. **Site 2 of 4 in cluster T**

Relative:
Lower

Actual:
25 ft.

NY MANIFEST:

EPA ID:	NYP004628814
Country:	USA
Location Address 1:	945 METROPOLITAN AVE
Location Address 2:	SB 15332
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S117063662**

Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2014
Trans1 Recv Date:	08/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004628814
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	75
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002616420GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

EPA ID:	NYP004560975
Country:	USA
Location Address 1:	945 METROPOLITAN AVE
Location Address 2:	SB 15332
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014

CON EDISON (Continued) **S117063662**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004560975
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013255320JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

U72 **EDR US Hist Cleaners** **1015049537**
WNW **362 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.181 mi.
954 ft. **Site 1 of 2 in cluster U**

Relative:
Lower

Actual:
34 ft.

EDR Historical Cleaners:

Name:	ECONO WASH LAUNDRY
Year:	1999
Address:	362 GRAHAM AVE
Name:	ECONO WASH LAUNDRY
Year:	2000
Address:	362 GRAHAM AVE
Name:	ECONO WASH LAUNDRY
Year:	2001
Address:	362 GRAHAM AVE
Name:	ECONO WASH LAUNDRY
Year:	2002
Address:	362 GRAHAM AVE
Name:	ECONO WASH LAUNDRY
Year:	2003
Address:	362 GRAHAM AVE
Name:	ECONO WASH LAUNDRY
Year:	2004

(Continued) **1015049537**

Address: 362 GRAHAM AVE

Name: ECONO WASH LAUNDRY
Year: 2005
Address: 362 GRAHAM AVE

Name: ECONO WASH LAUNDRY
Year: 2006
Address: 362 GRAHAM AVE

Name: ECONO WASH LAUNDRY
Year: 2007
Address: 362 GRAHAM AVE

Name: ECONO WASH LAUNDRY
Year: 2008
Address: 362 GRAHAM AVE

Name: ECONO WASH LAUNDRY
Year: 2009
Address: 362 GRAHAM AVE

V73 **JP MORGAN CHASE AND COMPANY** **NY AST** **A100300930**
South **819 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.182 mi.
963 ft. **Site 1 of 5 in cluster V**

Relative:
Higher

Actual:
46 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-601809
Program Type: PBS
UTM X: 589521.54278999998
UTM Y: 4507291.4689499997
Expiration Date: 09/30/2007
Site Type: Other

Affiliation Records:
Site Id: 23771
Affiliation Type: Facility Owner
Company Name: JP MORGAN CHASE AND COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 575 WASHINGTON BOULEVARD, FOURTH FLOOR
Address2: Not reported
City: JERSEY CITY
State: NJ
Zip Code: 07310-1680
Country Code: 001
Phone: (201) 595-5851
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23771

JP MORGAN CHASE AND COMPANY (Continued) **A100300930**

Affiliation Type:	Mail Contact
Company Name:	JP MORGAN CHASE AND COMPANY
Contact Type:	Not reported
Contact Name:	JAMES S. LISCIOTTO
Address1:	575 WASHINGTON BOULEVARD
Address2:	FOURTH FLOOR
City:	JERSEY CITY
State:	NJ
Zip Code:	07310-1680
Country Code:	001
Phone:	(201) 595-5851
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23771
Affiliation Type:	On-Site Operator
Company Name:	JP MORGAN CHASE AND COMPANY
Contact Type:	Not reported
Contact Name:	JAMES S. LISCIOTTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(201) 595-5851
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23771
Affiliation Type:	Emergency Contact
Company Name:	JP MORGAN CHASE AND COMPANY
Contact Type:	Not reported
Contact Name:	JAMES S. LISCIOTTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(201) 595-5851
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	47898
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

JP MORGAN CHASE AND COMPANY (Continued) **A100300930**

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2002
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/23/2002
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

V74 **NYNEX** **NY MANIFEST** **1009233840**
South **BUSHWICK AVE & GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.183 mi.
967 ft. **Site 2 of 5 in cluster V**

Relative:
Higher

Actual:
46 ft.

NY MANIFEST:

EPA ID:	NYP000921718
Country:	USA
Location Address 1:	BUSHWICK AVE & GRAND ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11201
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NYNEX
Contact:	SUSHMITA BISWAS
Address:	221 EAST 37TH STREET
City/State/Zip:	NEW YORK, NY 10016
Country:	USA
Phone:	212-338-7126

Manifest:

Document ID:	MIA4133825
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/1995
Trans1 Recv Date:	08/29/1995

NYNEX (Continued) **1009233840**

Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/06/1995
Part A Recv Date:	/ /
Part B Recv Date:	09/25/1995
Generator EPA ID:	NYP000921718
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574
TSDF ID:	MID096963194
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	MOA0926950
Manifest Status:	Completed copy
Trans1 State ID:	H1144
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/1995
Trans1 Recv Date:	09/26/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/29/1995
Part A Recv Date:	/ /
Part B Recv Date:	10/19/1995
Generator EPA ID:	NYP000921718
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	MOD980962849
Waste Code:	D016 - 2,4-D 10.0 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	MOA0926950

NYNEX (Continued) **1009233840**

Manifest Status:	Completed copy
Trans1 State ID:	H1144
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/1995
Trans1 Recv Date:	09/26/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/29/1995
Part A Recv Date:	/ /
Part B Recv Date:	10/19/1995
Generator EPA ID:	NYP000921718
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	MOD980962849
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F003 - UNKNOWN
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00350
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

V75 **MTA NYCT - GRAND STREET STATION - L LINE** **RCRA-SQG** **1016455589**
South **GRAND ST & BUSHWICK AVE** **FINDS** **NYR000206920**
1/8-1/4 **BROOKLYN, NY 11211**
0.184 mi.
969 ft. **Site 3 of 5 in cluster V**

Relative:
Higher

Actual:
46 ft.

RCRA-SQG:

Date form received by agency:	01/23/2014
Facility name:	MTA NYCT - GRAND STREET STATION - L LINE
Facility address:	GRAND ST & BUSHWICK AVE BROOKLYN, NY 11211
EPA ID:	NYR000206920
Mailing address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Contact:	GERALD LEZEAU
Contact address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3535
Contact email:	GERALD.LEZEAU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3535
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	MTA NYCT
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

MTA NYCT - GRAND STREET STATION - L LINE (Continued) **1016455589**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110057070315

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

U76 **EDR US Hist Cleaners** **1015050142**
WNW **368 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.186 mi.
980 ft. **Site 2 of 2 in cluster U**

Relative:
Lower

Actual:
33 ft.

EDR Historical Cleaners:
Name: GS CLEANING STORE
Year: 2004
Address: 368 GRAHAM AVE

Name: G S CLEANING STORE
Year: 2005
Address: 368 GRAHAM AVE

Name: G & S CLEANER
Year: 2006
Address: 368 GRAHAM AVE

V77 **CON EDISON SERVICE BOX: 68622** **RCRA NonGen / NLR** **1016970857**
South **812 GRAND ST** **NY MANIFEST** **NYP004445862**
1/8-1/4 **BROOKLYN, NY 11212**
0.186 mi.
982 ft. **Site 4 of 5 in cluster V**

Relative:
Higher

Actual:
47 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/19/2014
Facility name: CON EDISON SERVICE BOX: 68622
Facility address: 812 GRAND ST
BROOKLYN, NY 11212
EPA ID: NYP004445862

CON EDISON SERVICE BOX: 68622 (Continued) **1016970857**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/19/2014
Site name: CON EDISON SERVICE BOX: 68622
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004445862
Country: USA
Location Address 1: FRONT OF 812 GRAND ST
Location Address 2: SB68622
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

CON EDISON SERVICE BOX: 68622 (Continued) **1016970857**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2014
Trans1 Recv Date:	02/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004445862
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002219892GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

W78 **FORMER SCIENTIFIC FIRE PREVENTION INC** **NY BROWNFIELDS** **S109942567**
SE **871 GRAND STREET** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.188 mi.
990 ft. **Site 1 of 7 in cluster W**

Relative:
Higher

Actual:
38 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	487645
Acres:	Not reported
HW Code:	C224165A
SWIS:	2401
Town:	New York City
Update By:	JEBROWN
Site Description:	Location: This site is the off-site portion of the Former Scientific Fire Prevention BCP site# C224165. This site is located on the eastern half of the block between Powers and Grand Streets, in the Williamsburg section of Brooklyn, NY. Site Features: Multiple lots with a mix of commercial and residential land uses. Approximately 70% of the site is covered with pavement or buildings.Current Zoning and Land Uses: The BCP site is zoned R7A. These districts typically produce high-lot coverage, seven- and eight-story apartment buildings, blending with existing buildings in many established

FORMER SCIENTIFIC FIRE PREVENTION INC (Continued) **S109942567**

neighborhoods. The neighborhood is currently a mix of commercial and residential land uses. Progress High School is across Grand Street from the site.Past Uses of the Site: The immediate off-site study area is residential with some commercial. Previously, the area was a mix of residential, industrial and commercial. Past uses in the general site vicinity included auto body shops, a bakery, manufacturing and a commercial laundry.Site Geology and Hydrogeology: Groundwater at the BCP site is present at a depth of approximately 35 feet below grade. Groundwater flows to the southwest. Groundwater depth and flow direction are expected to be similar in the adjacent off-site study area. Subsurface soils at the BCP site consist of a silty non-native fill with bricks, wood and other rubble to approximately 2 feet below grade. At the BCP site, a native fine brown silty-sand is present immediately below the fill material to a depth of approximately 15 feet below grade. As the off-site investigation progresses, this information will be updated as appropriate.

Env Problem: Nature and Extent of Contamination: Based upon the remedial investigation at the BCP site, the primary contaminants of concern are expected to be trichloroethene (TCE) and tetrachloroethene (PCE) which were found in the BCP site soil, groundwater and soil vapor. Some pesticides, such as chlordane and dieldrin were also found in site soils and groundwater, and 4,4,4-DDD found in site soil. The BCP site soils also contained some semi-volatile organic compounds (SVOCs), such as benzo(a)pyrene, benzo(a) anthracene and benzo(b)fluoranthene.The off-site investigation has not begun, therefore this section will be updated to reflect the investigation results as data become available.Significant Threat: It is not yet known whether there is a signficant off-site environmental threat due to contamination at the BCP site. This section will be updated as data become available.

Health Problem: Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that soil vapor intrusion may represent a concern for off-site buildings.

Program: BCP
Site Code: 468207
Acres: .057
HW Code: C224165
SWIS: 2401
Town: New York City
Update By: JEBROWN

Site Description: Location: The site is located at 871 Grand Street in the Williamsburg section of Brooklyn, NY. The site is comprised of a single tax parcel, Section 3, Block 2922, lot 41 and occupies 0.06 acres.Site Features: The lot is currently developed with a one-story slab-on-grade concrete block building which occupies the entire lot. The building was constructed in 1981 according to the NYC Department of Buildings.Current Zoning and Land Uses: The site is currently vacant. The building was commercial, but is currently unoccupied. The intended use of the site is residential. The site is zoned R7A. These districts typically produce high-lot coverage, seven- and eight-story apartment buildings, blending with existing buildings in many

FORMER SCIENTIFIC FIRE PREVENTION INC (Continued) **S109942567**

established neighborhoods. The neighborhood is currently a mix of commercial and residential land uses. Progress High School is across Grand Street from the site.Past Use of the Site: Historical records show the subject site as being developed prior to 1887 with a two-story wheelwright located at the street front, and detached one-story shed located in the rear yard. By 1907, the two- story building was converted for use by a horseshoer, which included two horse stables in the rear yard. In the 1930's through the 1950's, the subject site building was used for paper storage and tile storage. The building was then used in the 1960's and 1970's by a metal products manufacturer, Scientific Fire Prevention Inc., until it was demolished in 1981. The subject site lot was then redeveloped in 1981 with the one-story concrete block commercial building that currently remains at the site. Site Geology and Hydrogeology: Groundwater at the site is present at a depth of approximately 35 feet below grade. Groundwater flows to the southwest. Subsurface soils at the site consist of a silty non-native fill with bricks, wood and other rubble to approximately 2 feet below grade. A native fine brown silty-sand is present immediately below the fill material to a depth of approximately 15 feet below grade.

Env Problem: Nature and Extent of Contamination: Based upon the remedial investigation, the primary contaminants of concern at the site are trichloroethene (TCE) and tetrachloroethene (PCE) found in site soil, groundwater and soil vapor, as well as some pesticides, such as chlordane and dieldrin in site soils and groundwater, and 4,4,4-DDD in site soil. Site soils also contained some semi-volatile organic compounds (SVOCs), such as benzo(a)pyrene, benzo(a) anthracene and benzo(b)fluoranthene.Soil: TCE and PCE were encountered in shallow (3-5 feet) soil samples with the highest levels at 350 parts per million (ppm), and 36 ppm, respectively compared to the unrestricted use soil cleanup objectives (UUSCO) of 0.47 ppm and 1.3 ppm, respectively. A TCE/PCE hot spot was identified near the south end of the property. One sample from 12-14 feet showed elevated levels of pesticides such as chlordane at 0.76 ppm versus the UUSCO of 0.094 ppm and 4,4-DDT at 0.16 ppm vs the UUSCO of 0.0033 ppm. The top two feet of site soils are historic fill. Sampling in shallow soils showed elevated levels of other VOCs, such as 1,3 and 1,4 dichlorobenzene, as well as SVOCs and pesticides as noted above. No metals exceeding UUSCOs were encountered.Groundwater: TCE and PCE were found in groundwater throughout the site. The levels of TCE marginally exceeded the groundwater standards at a maximum of 9.4 parts per billion (ppb) versus a standard of 5 ppb, while PCE was detected at a slightly higher concentration, at a maximum of 24 ppb versus a standard of 5 ppb. Dieldrin was detected at 0.033 ppb versus a standard of 0.004 ppb. The metals detected in groundwater (i.e., magnesium, manganese and sodium) are naturally occurring and/or not site-related. Groundwater is 35 feet below grade.Soil Vapor: Soil vapor samples were collected at 12 feet below ground surface. TCE was detected in every soil vapor sample collected. The highest TCE soil gas concentration was 3,620 micrograms per cubic meter (ug/m3), while the highest PCE soil gas concentration was 214 ug/m3. Significant Threat: The site presents a significant threat to human health due to the ongoing releases of contaminants from source areas to soil vapor.

Health Problem: Direct contact with contamination in the soil and groundwater are not expected because the site is covered by a building. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor

FORMER SCIENTIFIC FIRE PREVENTION INC (Continued) **S109942567**

air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants in indoor air for any future on-site redevelopment and occupancy. Furthermore, environmental sampling indicates that soil vapor intrusion may represent a concern for off-site buildings.

E DESIGNATION:

Tax Lot(s):	41
Tax Block:	2922
Borough Code:	Not reported
E-No:	E-232
Effective Date:	7/29/2009
Satisfaction Date:	Not reported
Ceqr Number:	09DCP056K
Ulurp Number:	090334ZMK
Zoning Map No:	12c 13a 13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

X79 **EDR US Hist Cleaners** **1015097137**
South **802 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.188 mi.
992 ft. **Site 1 of 3 in cluster X**

Relative:
Higher

Actual:
46 ft.

EDR Historical Cleaners:

Name:	Y & Y CLEANERS
Year:	2001
Address:	802 GRAND ST
Name:	Y & Y CLEANERS
Year:	2002
Address:	802 GRAND ST

X80 **RHEE & NURYS DRY CLEANERS** **RCRA NonGen / NLR** **1004756817**
South **802 GRAND ST** **FINDS** **NYD982271769**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.188 mi.
992 ft. **Site 2 of 3 in cluster X**

Relative:
Higher

Actual:
46 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RHEE & NURYS DRY CLEANERS
Facility address:	802 GRAND ST BROOKLYN, NY 11211
EPA ID:	NYD982271769
Mailing address:	GRAND ST BROOKLYN, NY 11211
Contact:	WARN SEUP RHEE
Contact address:	GRAND ST BROOKLYN, NY 11211

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Contact country: US
Contact telephone: (718) 387-6033
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SABATINO NAPOLITANO
Owner/operator address: 84-27 149TH AVE
HOWARD BEACH, NY 11414
Owner/operator country: US
Owner/operator telephone: (718) 738-5690
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: SABATINO NAPOLITANO
Owner/operator address: 84-27 149TH AVE
HOWARD BEACH, NY 11414
Owner/operator country: US
Owner/operator telephone: (718) 738-5690
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: SABATINO NAPOLITANO
Owner/operator address: 84-27 149TH AVE
HOWARD BEACH, NY 11414
Owner/operator country: Not reported
Owner/operator telephone: (718) 738-5690
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RHEE & NURYS DRY CLEANERS
Classification: Not a generator, verified

Date form received by agency: 01/29/2002
Site name: RHEE & NURYS DRY CLEANERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 06/06/2000
Site name: RHEE & NURYS DRY CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004417596

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD982271769
Country:	USA
Location Address 1:	802 GRAND ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	Y & Y CLNRS
Contact:	Y & Y CLNRS
Address:	802 GRAND STREET
City/State/Zip:	BROOKLYN, NY 11211
Country:	USA
Phone:	718-387-6033

Manifest:

Document ID:	NYC6590711
Manifest Status:	Not reported
Trans1 State ID:	AP62777
Trans2 State ID:	DEP03217
Generator Ship Date:	01/18/2002
Trans1 Recv Date:	01/18/2002
Trans2 Recv Date:	01/28/2002
TSD Site Recv Date:	01/29/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00540
Units:	P - Pounds
Number of Containers:	009
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYC6536968
Manifest Status:	Not reported

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Trans1 State ID: NYCGF1411
Trans2 State ID: 321783385
Generator Ship Date: 06/15/2001
Trans1 Recv Date: 06/15/2001
Trans2 Recv Date: 06/25/2001
TSD Site Recv Date: 06/26/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982271769
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC6331858
Manifest Status: Not reported
Trans1 State ID: NYCGF1411
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2001
Trans1 Recv Date: 02/20/2001
Trans2 Recv Date: 02/27/2001
TSD Site Recv Date: 02/27/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982271769
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD076621976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC6264202
Manifest Status: Not reported
Trans1 State ID: NYCGF1411
Trans2 State ID: MEW37720

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Generator Ship Date:	10/25/2000
Trans1 Recv Date:	10/25/2000
Trans2 Recv Date:	10/27/2000
TSD Site Recv Date:	10/31/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6208020
Manifest Status:	Not reported
Trans1 State ID:	NYCGF1411
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2000
Trans1 Recv Date:	06/13/2000
Trans2 Recv Date:	06/20/2000
TSD Site Recv Date:	06/23/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6053354
Manifest Status:	Not reported
Trans1 State ID:	NYEH2705
Trans2 State ID:	T748NY
Generator Ship Date:	02/24/2000
Trans1 Recv Date:	02/24/2000
Trans2 Recv Date:	03/01/2000
TSD Site Recv Date:	03/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC5669335
Manifest Status:	Not reported
Trans1 State ID:	NYLP3931
Trans2 State ID:	T748NY
Generator Ship Date:	06/18/1999
Trans1 Recv Date:	06/18/1999
Trans2 Recv Date:	06/23/1999
TSD Site Recv Date:	06/24/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5288117
Manifest Status:	Not reported
Trans1 State ID:	NYAP4503
Trans2 State ID:	Not reported
Generator Ship Date:	06/18/1998
Trans1 Recv Date:	06/18/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Document ID:	NYC5466418
Manifest Status:	Not reported
Trans1 State ID:	NYAP4503
Trans2 State ID:	506T4JNJ
Generator Ship Date:	12/03/1998
Trans1 Recv Date:	12/03/1998
Trans2 Recv Date:	12/08/1998
TSD Site Recv Date:	12/11/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC4762462
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	HQ80784
Generator Ship Date:	06/17/1997
Trans1 Recv Date:	06/17/1997
Trans2 Recv Date:	06/23/1997
TSD Site Recv Date:	06/25/1997
Part A Recv Date:	06/26/1997
Part B Recv Date:	07/18/1997
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NJA2650622
Manifest Status:	Completed copy
Trans1 State ID:	XZ90GR501
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/1997
Trans1 Recv Date:	01/09/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/13/1997
Part A Recv Date:	02/20/1997

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Part B Recv Date:	01/30/1997
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00180
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4441217
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	1FS147OK
Generator Ship Date:	03/27/1997
Trans1 Recv Date:	03/27/1997
Trans2 Recv Date:	04/03/1997
TSD Site Recv Date:	04/04/1997
Part A Recv Date:	04/08/1997
Part B Recv Date:	04/23/1997
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4908407
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYAP4503
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/1997
Trans1 Recv Date:	12/03/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/10/1997
Part A Recv Date:	12/16/1997
Part B Recv Date:	01/15/1998
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYB8529165
Manifest Status:	Completed copy
Trans1 State ID:	XZ90GR501
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1997
Trans1 Recv Date:	05/14/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/19/1997
Part A Recv Date:	06/02/1997
Part B Recv Date:	05/29/1997
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00250
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYG0160614
Manifest Status:	Completed copy
Trans1 State ID:	XZ90GR501
Trans2 State ID:	Not reported
Generator Ship Date:	11/05/1997
Trans1 Recv Date:	11/05/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/12/1997
Part A Recv Date:	01/20/1998
Part B Recv Date:	11/26/1997
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYB7192656
Manifest Status:	Completed copy
Trans1 State ID:	XZ90GR501

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Trans2 State ID:	Not reported
Generator Ship Date:	11/21/1996
Trans1 Recv Date:	11/21/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/22/1996
Part A Recv Date:	12/16/1996
Part B Recv Date:	12/12/1996
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00200
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4152903
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	AM6252NY
Trans2 State ID:	4672AZ
Generator Ship Date:	06/18/1996
Trans1 Recv Date:	06/18/1996
Trans2 Recv Date:	06/21/1996
TSD Site Recv Date:	06/22/1996
Part A Recv Date:	07/03/1996
Part B Recv Date:	07/17/1996
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4393798
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	MO001
Generator Ship Date:	11/27/1996
Trans1 Recv Date:	11/27/1996
Trans2 Recv Date:	12/03/1996
TSD Site Recv Date:	12/04/1996
Part A Recv Date:	12/18/1996
Part B Recv Date:	12/26/1996
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4008892
Manifest Status:	Completed copy
Trans1 State ID:	GF2859NY
Trans2 State ID:	4190AZOK
Generator Ship Date:	03/25/1996
Trans1 Recv Date:	03/25/1996
Trans2 Recv Date:	03/28/1996
TSD Site Recv Date:	03/29/1996
Part A Recv Date:	04/02/1996
Part B Recv Date:	04/11/1996
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4272660
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/1996
Trans1 Recv Date:	09/11/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/19/1996
Part A Recv Date:	09/20/1996
Part B Recv Date:	10/15/1996
Generator EPA ID:	NYD982271769
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

RHEE & NURYS DRY CLEANERS (Continued) **1004756817**

Year: 1996

X81 **RHEE & NURY'S/Y&Y CLEANERS** **NY DRYCLEANERS** **S110247774**
South **802 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.188 mi.
992 ft. **Site 3 of 3 in cluster X**

Relative:
Higher

Actual:
46 ft.

DRYCLEANERS:

Facility ID:	2-6101-00356
Phone Number:	718-387-6033
Region:	Not reported
Registration Effective Date:	10/5/2001 14:56:57:076
Inspection Date:	04JUN3
Install Date:	91
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

W82 **SCIENTIFIC FIRE PREVENTION SITE FORMER** **RCRA NonGen / NLR** **1016455578**
SE **871 GRAND ST** **FINDS** **NYR000206813**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.188 mi.
992 ft. **Site 2 of 7 in cluster W**

Relative:
Higher

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/05/2014
Facility name:	SCIENTIFIC FIRE PREVENTION SITE FORMER
Facility address:	871 GRAND ST BROOKLYN, NY 11211
EPA ID:	NYR000206813
Mailing address:	LEE AVE NO 693 BROOKLYN, NY 11211
Contact:	JOEL GREENFIELD
Contact address:	LEE AVE NO 693 BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	(718) 623-6430
Contact email:	JIG@SYGREALTIES.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JOEL GREENFIELD
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/13/2012
Owner/Op end date:	Not reported
Owner/operator name:	871 GRAND LLC

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

Owner/operator address: LEE AVE NO 693
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/13/2012
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Historical Generators:
Date form received by agency: 11/26/2013
Site name: SCIENTIFIC FIRE PREVENTION SITE FORMER
Classification: Large Quantity Generator

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110057070208

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

NY MANIFEST:

EPA ID:	NYR000206813
Country:	USA
Location Address 1:	871 GRAND ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SCIENTIFIC FIRE PREVENTION SITE FORMER
Contact:	SCIENTIFIC FIRE PREVENTION SITE FORMER
Address:	871 GRAND ST
City/State/Zip:	BROOKLYN, NY 11211
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	42900
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133210JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	46320
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133214JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	42980
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

Manifest Tracking Num:	013133215JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	48880
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133216JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	44960
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133222JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	44980
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133218JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	45340
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133219JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50640
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133220JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	52280
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133221JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

SCIENTIFIC FIRE PREVENTION SITE FORMER (Continued) **1016455578**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000206813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	46960
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133217JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

83
WSW
1/8-1/4
0.188 mi.
994 ft.

FRANK LOVISI **NY AST** **U003387635**
308 GRAHAM AVE **NY HIST AST** **N/A**
BROOKLYN, NY 11211

Relative:
Higher

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-160180
Program Type:	PBS
UTM X:	589221.57314999995
UTM Y:	4507417.1775599997
Expiration Date:	02/20/2009
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5453
Affiliation Type:	Facility Owner
Company Name:	TANM IRREVOCABLE TRUST
Contact Type:	Not reported
Contact Name:	Not reported

FRANK LOVISI (Continued) **U003387635**

Address1:	260 AINSLIE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	5453
Affiliation Type:	Mail Contact
Company Name:	AS TRUSTEE
Contact Type:	Not reported
Contact Name:	ANTHONY J. SARRO
Address1:	TANM IRREVOCABLE TRUST
Address2:	260 AINSLIE STREET
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	5453
Affiliation Type:	On-Site Operator
Company Name:	TANM IRREVOCABLE TRUST
Contact Type:	Not reported
Contact Name:	ANTHONY SARRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/26/2008

Site Id:	5453
Affiliation Type:	Emergency Contact
Company Name:	TANM IRREVOCABLE TRUST
Contact Type:	Not reported
Contact Name:	ANTHONY SARRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

FRANK LOVISI (Continued) **U003387635**

Phone:	(718) 388-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/26/2008

Tank Info:

Tank Number:	1
Tank Id:	12317
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
B05 - Tank External Protection - Jacketed

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/09/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	01/27/2009
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-160180
SWIS Code:	6101
Operator:	FRANK LOVISI
Facility Phone:	(516) 741-4873
Facility Addr2:	308 GRAHAM AVE
Facility Type:	Not reported
Emergency:	FRANK LOVISI
Emergency Tel:	(516) 741-4873
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	FRANK LOVISI
Owner Address:	701 FOCH BLV

FRANK LOVISI (Continued) **U003387635**

Owner City,St,Zip:	WILLISTON PARK, NY 11596
Federal ID:	Not reported
Owner Tel:	(516) 741-4873
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Contact:	FRANK LOVISI
Mailing Name:	FRANK LOVISI
Mailing Address:	701 FOCH BLV
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WILLISTON PARK, NY 11596
Mailing Telephone:	(516) 741-4873
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	07/08/1997
Expiration:	07/10/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	1500
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Other
Leak Detection:	9
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported

FRANK LOVISI (Continued) **U003387635**

Lat/Long: Not reported

V84 **EDR US Hist Auto Stat** **1015117706**
South **100 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.190 mi.
1001 ft. **Site 5 of 5 in cluster V**

Relative:
Higher

EDR Historical Auto Stations:
Name: NEW EASTERN CAR & LIMO SERVICE
Year: 2000
Actual: Address: 100 BUSHWICK AVE
47 ft.

T85 **CORMEN ENTERPRISES INC.** **NY AST** **U003393564**
East **953 METROPOLITAN AVENUE** **N/A**
1/8-1/4 **WILLIAMSBURG, NY 11211**
0.191 mi.
1008 ft. **Site 3 of 4 in cluster T**

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Actual: Site Status: Active
25 ft. Facility Id: 2-305596
Program Type: PBS
UTM X: 589789.35976000002
UTM Y: 4507587.2312200004
Expiration Date: 11/18/2017
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 13970
Affiliation Type: Facility Owner
Company Name: CORMEN ENTERPRISES INC.
Contact Type: AGENT
Contact Name: JOHN FAY
Address1: 245 WILSON AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 574-6266
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 12/18/2012

Site Id: 13970
Affiliation Type: Mail Contact
Company Name: CORMEN ENTERPRISES INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 245 WILSON AVENUE
Address2: Not reported
City: BROOKLYN
State: NY

CORMEN ENTERPRISES INC. (Continued) **U003393564**

Zip Code:	11237
Country Code:	001
Phone:	(718) 573-7911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13970
Affiliation Type:	On-Site Operator
Company Name:	CORMEN ENTERPRISES INC.
Contact Type:	Not reported
Contact Name:	ANASTASIC HANDRINOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 573-7911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13970
Affiliation Type:	Emergency Contact
Company Name:	CORMEN ENTERPRISES INC.
Contact Type:	Not reported
Contact Name:	ANASTASIC HANDRINOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 573-7911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	30727
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

CORMEN ENTERPRISES INC. (Continued) **U003393564**

H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1957
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	12/18/2012
Material Name:	#2 Fuel Oil (On-Site Consumption)

T86 **EDR US Hist Auto Stat** **1015682027**
East **948 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.193 mi.
1020 ft. **Site 4 of 4 in cluster T**

Relative:
Lower

Actual:
25 ft.

EDR Historical Auto Stations:

Name:	RULA AUTO REPAIR INC
Year:	2001
Address:	948 METROPOLITAN AVE
Name:	DIAGNOSTIC AUTO CLINIC INC
Year:	2002
Address:	948 METROPOLITAN AVE

W87 **885 GRAND STREET CORP** **NY UST** **U000411056**
SE **881-5 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.194 mi.
1023 ft. **Site 3 of 7 in cluster W**

Relative:
Higher

Actual:
37 ft.

UST:

Id/Status:	2-478075 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/05/2004
UTM X:	589685.68521000003
UTM Y:	4507349.6892299997
Site Type:	Other

Affiliation Records:

Site Id:	21233
Affiliation Type:	Mail Contact
Company Name:	885 GRAND STREET CORP
Contact Type:	Not reported

885 GRAND STREET CORP (Continued) **U000411056**

Contact Name:	ALPHONSE MILO
Address1:	600 WATERVIEW ROAD
Address2:	Not reported
City:	OCEANSIDE
State:	NY
Zip Code:	11572
Country Code:	001
Phone:	(718) 388-7575
EMail:	AMILODUNWELL@AOL.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/24/2007

Site Id:	21233
Affiliation Type:	On-Site Operator
Company Name:	885 GRAND STREET CORP
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/24/2007

Site Id:	21233
Affiliation Type:	Emergency Contact
Company Name:	885 GRAND STREET CORP
Contact Type:	Not reported
Contact Name:	ALPHONSE MILO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-7575
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/24/2007

Site Id:	21233
Affiliation Type:	Facility Owner
Company Name:	885 GRAND STREET CORP
Contact Type:	PRESIDENT
Contact Name:	ALPHONSE MILO
Address1:	881-885 GRAND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211

885 GRAND STREET CORP (Continued) **U000411056**

Country Code:	001
Phone:	(516) 766-2353
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/24/2007

Tank Info:

Tank Number:	001
Tank ID:	41065
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	06/01/1957
Date Tank Closed:	11/25/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	10/24/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	41066
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	06/01/1957
Date Tank Closed:	11/25/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

885 GRAND STREET CORP (Continued) **U000411056**

Modified By: KXTANG
Last Modified: 10/24/2007

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 41067
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 06/01/1957
Date Tank Closed: 11/25/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 10/24/2007

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 41068
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 06/01/1957
Date Tank Closed: 11/25/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

885 GRAND STREET CORP (Continued) **U000411056**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 10/24/2007

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 41069
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 06/01/1957
Date Tank Closed: 11/25/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 10/24/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 006
Tank ID: 41070
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 06/01/1957
Date Tank Closed: 11/25/1990
Registered: True
Tank Location: Underground

885 GRAND STREET CORP (Continued) **U000411056**

Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	10/24/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

W88 **EDR US Hist Auto Stat** **1015662234**
SE **881 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.194 mi.
1023 ft. **Site 4 of 7 in cluster W**

Relative:
Higher

Actual:
37 ft.

EDR Historical Auto Stations:

Name:	RALPHS AUTO CENTER
Year:	1999
Address:	881 GRAND ST
Name:	RALPHS AUTO CENTER
Year:	2000
Address:	881 GRAND ST
Name:	RALPHS AUTO CTR
Year:	2002
Address:	881 GRAND ST
Name:	RALPHS AUTO CENTER
Year:	2006
Address:	881 GRAND ST
Name:	RALPHS AUTO CENTER
Year:	2007
Address:	881 GRAND ST
Name:	RALPHS AUTO CENTER
Year:	2008
Address:	881 GRAND ST
Name:	RALPHS AUTO CTR
Year:	2010
Address:	881 GRAND ST
Name:	RALPHS AUTO CENTER
Year:	2011

(Continued) **1015662234**

Address: 881 GRAND ST

Name: RALPHS AUTO CENTER
Year: 2012
Address: 881 GRAND ST

W89 **J & M AUTO REPAIRS** **RCRA NonGen / NLR** **1000458276**
SE **881-885 GRAND ST** **FINDS** **NYD986936649**
1/8-1/4 **BROOKLYN, NY 11211** **NY LTANKS**
0.194 mi. **NY MANIFEST**
1023 ft. **Site 5 of 7 in cluster W**

Relative:
Higher

Actual:
37 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: J & M AUTO REPAIRS
Facility address: 881-885 GRAND ST
BROOKLYN, NY 112115001
EPA ID: NYD986936649
Mailing address: METROPOLITAN AVE
QUEENS, NY 11385
Contact: Not reported
Contact address: METROPOLITAN AVE
QUEENS, NY 11385
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: GEORGE ADOMAITES
Owner/operator address: 56-29 METROPOLITAN AVE
QUEENS, NY 11385
Owner/operator country: US
Owner/operator telephone: (718) 366-1881
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: GEORGE ADOMAITES
Owner/operator address: 56-29 METROPOLITAN AVE
QUEENS, NY 11385
Owner/operator country: US
Owner/operator telephone: (718) 366-1881
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No

J & M AUTO REPAIRS (Continued) **1000458276**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	J & M AUTO REPAIRS
Classification:	Not a generator, verified

Date form received by agency:	07/08/1999
Site name:	J & M AUTO REPAIRS
Classification:	Not a generator, verified

Date form received by agency:	01/11/1991
Site name:	J & M AUTO REPAIRS
Classification:	Small Quantity Generator

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004458827

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:

Site ID:	92038
Spill Number/Closed Date:	8901284 / 7/21/2008
Spill Date:	5/9/1989
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	5/9/1989
CID:	Not reported

J & M AUTO REPAIRS (Continued) **1000458276**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/9/1989
Spill Record Last Update:	7/22/2008
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	30485
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"SEE SPILL NUMBER 8908532.4/12/04-Vought-Spill transferred from Sullivan to Rommel as per Rommel.2/2/07 - Haggerty - Alphonse Milo (718-388-7575) brought the property shortly after the tank test failures and is still owner today. He states he is will be building a parking lot on the subject property and all soil will be excavated for the foundation. I instructed Mr. Milo to contact the DEC as soon as possible because there is a good chance contamination is present. Spill to remain open10/4/07 - Haggerty - received Phase II subsurface Investigation report from Al Milo. Phase II completed to satisfy the bank requirement. Report states that all soil samples and groundwater samples are below standards. MW's in the area surrounding the former tank field. No groundwater contamination was detected. PM stated that all tanks must be properly closed out in PBS wether tanks are registered or previously unknown and this spill will remain open until this is resolved.07/21/08 - Haggerty: Spoke with Mrs. Milo. She stated that the PBS issue has been resovled. I checked the PBS records to confirm. PBS# 2-478075. Spill closed
Remarks:	THREE 550 GALLON TANKS FAIL HORNER-EZY CHEK - LR = -0.11982 GPH. NO DECISION ON ACTION TO BE TAKEN..

Material:

Site ID:	92038
Operable Unit ID:	927414
Operable Unit:	01
Material ID:	449034
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	92038
Operable Unit ID:	927414
Operable Unit:	01
Material ID:	2135635

J & M AUTO REPAIRS (Continued) **1000458276**

Material Code: 1213A
Material Name: MTBE (METHYL-TERT-BUTYL ETHER)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True

Tank Test:
Site ID: 92038
Spill Tank Test: 1535443
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

NY MANIFEST:
EPA ID: NYD986936649
Country: USA
Location Address 1: 881-885 GRAND ST
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: 5001

Mailing Info:
Name: KALCO PUMP & TANK
Contact: KALCO PUMP & TANK
Address: 45-01 20TH AVE
City/State/Zip: LONG ISLAND CITY, NY 11106
Country: USA
Phone: 718-626-8083

Manifest:

Document ID: NYB2043576
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: VH6911
Trans2 State ID: Not reported
Generator Ship Date: 02/08/1991
Trans1 Recv Date: 02/08/1991
Trans2 Recv Date: / /
TSD Site Recv Date: 02/08/1991
Part A Recv Date: 02/28/1991
Part B Recv Date: 03/08/1991
Generator EPA ID: NYD986936649
Trans1 EPA ID: NYD980592570
Trans2 EPA ID: Not reported

J & M AUTO REPAIRS (Continued) **1000458276**

TSDF ID: NYD082785429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1991

W90 **EDR US Hist Auto Stat** **1015662934**
SE **885 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.196 mi.
1036 ft. **Site 6 of 7 in cluster W**

Relative:
Lower

Actual:
36 ft.

EDR Historical Auto Stations:
Name: RALPHS AUTO CENTER INC
Year: 2005
Address: 885 GRAND ST

Name: HECTORS AUTO BODY
Year: 2007
Address: 885 GRAND ST

Name: MIDTOWN AUTOMOTIVE CTR
Year: 2010
Address: 885 GRAND ST

W91 **RALPH'S AUTO CENTER INC.** **NY UST** **U004048086**
SE **885 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.196 mi.
1036 ft. **Site 7 of 7 in cluster W**

Relative:
Lower

Actual:
36 ft.

UST:
Id/Status: 2-608757 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 04/02/2018
UTM X: 589668.60630999994
UTM Y: 4507391.0506499996
Site Type: Other

Affiliation Records:
Site Id: 30608
Affiliation Type: Facility Owner
Company Name: 885 GRAND ST CORP
Contact Type: PRESIDENT/OWNER
Contact Name: ALPHONSE MILO
Address1: 600 WATERVIEW RD
Address2: Not reported
City: OCEANSIDE
State: NY
Zip Code: 11572
Country Code: 001

RALPH'S AUTO CENTER INC. (Continued) **U004048086**

Phone:	(917) 577-1414
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/22/2013

Site Id:	30608
Affiliation Type:	Mail Contact
Company Name:	OWNER
Contact Type:	Not reported
Contact Name:	ALPHONSE MILO
Address1:	600 WATERVIEW ROAD
Address2:	Not reported
City:	OCEANSIDE
State:	NY
Zip Code:	11572
Country Code:	001
Phone:	(516) 766-2353
EMail:	AMILODUNWELL@AOL.COM
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/22/2013

Site Id:	30608
Affiliation Type:	On-Site Operator
Company Name:	RALPHS AUTO CENTER INC.
Contact Type:	Not reported
Contact Name:	RALPH GONZALEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-2310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/25/2009

Site Id:	30608
Affiliation Type:	Emergency Contact
Company Name:	885 GRAND ST CORP
Contact Type:	Not reported
Contact Name:	RALPH GONZALEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 450-4344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/22/2013

RALPH'S AUTO CENTER INC. (Continued) **U004048086**

Tank Info:

Tank Number:	001
Tank ID:	65605
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	275
Install Date:	03/01/1997
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DMMOLOUG
Last Modified:	03/22/2013

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Y92 **CON EDISON** **NY MANIFEST** **S117058475**
NNE **39 KINGSLAND AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.198 mi.
1044 ft. **Site 1 of 2 in cluster Y**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

EPA ID:	NYP004505939
Country:	USA
Location Address 1:	39 KINGSLAND AVE
Location Address 2:	SERVICE BOX # 12708
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TELLING
Address:	4 IRVING PLACE-15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA

CON EDISON (Continued) **S117058475**

Phone: 212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004505939
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002417939GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

93
WNW
1/8-1/4
0.202 mi.
1066 ft.

380 GRAHAM AVE
BROOKLYN, NY 11211

EDR US Hist Cleaners **1015051616**
N/A

Relative:
Lower

Actual:
31 ft.

EDR Historical Cleaners:

Name:	GS CLEANING STORE
Year:	2007
Address:	380 GRAHAM AVE
Name:	GS CLEANING STORE
Year:	2008
Address:	380 GRAHAM AVE
Name:	GS CLEANING STORE
Year:	2009
Address:	380 GRAHAM AVE

(Continued) **1015051616**

Name: G S CLEANING STORE
Year: 2010
Address: 380 GRAHAM AVE

Name: G S CLEANING STORE
Year: 2011
Address: 380 GRAHAM AVE

Name: G S CLEANING STORE
Year: 2012
Address: 380 GRAHAM AVE

94
NNE
1/8-1/4
0.202 mi.
1067 ft.

NYCHA - COOPER PARK
275 JACKSON ST
BROOKLYN, NY 11211

RCRA NonGen / NLR **1001224059**
FINDS **NYR000052753**
NY MANIFEST

Relative:
Lower

Actual:
31 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYCHA - COOPER PARK
Facility address: 275 JACKSON ST
BROOKLYN, NY 11211
EPA ID: NYR000052753
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: FRANK OCELLO
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: (212) 306-3229
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

NYCHA - COOPER PARK (Continued) **1001224059**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCHA - COOPER PARK
Classification: Not a generator, verified

Date form received by agency: 03/30/1998
Site name: NYCHA - COOPER PARK
Classification: Small Quantity Generator

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Violation Status: No violations found

FINDS:

Registry ID: 110004541719

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000052753
Country: USA
Location Address 1: 275 JACKSON AVE
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: NYCHA - COOPER PARK HOUSES

NYCHA - COOPER PARK (Continued) **1001224059**

Contact:	RAFAEL VELEZ
Address:	250 BROADWAY 16TH FLR
City/State/Zip:	NEW YORK, NY 10007
Country:	USA
Phone:	212-306-3142

Manifest:

Document ID:	NJA2787631
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	05/05/1998
Trans1 Recv Date:	05/05/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/05/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000052753
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	U240 - 2,4 D,SALTS + ESTERS
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	CW - Wooden boxes
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	U240 - 2,4 D,SALTS + ESTERS
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Z95 **CON EDISON** **NY MANIFEST** **S117067565**
NW **177 JACKSON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.202 mi.
1069 ft. **Site 1 of 2 in cluster Z**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:

EPA ID:	NYP004605523
Country:	USA
Location Address 1:	177 JACKSON ST
Location Address 2:	SB 12565
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR

CON EDISON (Continued) **S117067565**

City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/23/2014
Trans1 Recv Date: 07/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004605523
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002615017GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Z96 **CON EDISON** **NY MANIFEST** **S117065107**
NW **FO 177 JACKSON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.202 mi.
1069 ft. **Site 2 of 2 in cluster Z**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:
EPA ID: NYP004576393
Country: USA
Location Address 1: FO 177 JACKSON ST
Location Address 2: SB 12565
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

CON EDISON (Continued) **S117065107**

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/2014
Trans1 Recv Date:	06/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004576393
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002424347GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AA97 **EDR US Hist Cleaners** **1015094723**
SSW **770 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.205 mi.
1082 ft. **Site 1 of 3 in cluster AA**

Relative:
Higher

Actual:
43 ft.

EDR Historical Cleaners:

Name:	770 GRAND LAUNDRY INC
Year:	2002
Address:	770 GRAND ST
Name:	BENSON LAUNDROMAT INC

(Continued) **1015094723**

Year: 2007
Address: 770 GRAND ST

Name: BENSON LAUNDROMAT INC
Year: 2008
Address: 770 GRAND ST

Name: BENSON LAUNDROMAT INC
Year: 2009
Address: 770 GRAND ST

Name: BENSON LAUNDROMAT INC
Year: 2010
Address: 770 GRAND ST

Name: ERIC & NANA LAUNDROMAT
Year: 2010
Address: 770 GRAND ST

Name: BENSON LAUNDROMAT INC
Year: 2011
Address: 770 GRAND ST

Name: BENSON LAUNDROMAT INC
Year: 2012
Address: 770 GRAND ST

98
West
1/8-1/4
0.205 mi.
1083 ft.

BRICKMER REALTY CORP
722 METROPOLITAN AVE
BROOKLYN, NY 11211

NY AST **U004078037**
N/A

Relative:
Lower

Actual:
35 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-374431
Program Type: PBS
UTM X: 589139.42845999997
UTM Y: 4507573.7996800002
Expiration Date: 10/02/2007
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 18836
Affiliation Type: Facility Owner
Company Name: BRICKMER REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 722 METROPOLITAN AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 387-4843
EMail: Not reported

BRICKMER REALTY CORP (Continued) **U004078037**

Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/16/2004

Site Id:	18836
Affiliation Type:	Mail Contact
Company Name:	BRICKMER REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	722 METROPOLITAN AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-4843
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/16/2004

Site Id:	18836
Affiliation Type:	On-Site Operator
Company Name:	BRICKMER REALTY CORP
Contact Type:	Not reported
Contact Name:	BRICKMER REALTY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-4843
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	18836
Affiliation Type:	Emergency Contact
Company Name:	BRICKMER REALTY CORP
Contact Type:	Not reported
Contact Name:	BARMETT BRICKMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-4843
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

BRICKMER REALTY CORP (Continued) **U004078037**

Tank Number: 001
Tank Id: 21139
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AB99 **900 GRAND STREET MILK LLC** **RCRA-CESQG** **1000556201**
SE **900 GRAND ST** **FINDS** **NYD986987600**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.206 mi.
1090 ft. **Site 1 of 3 in cluster AB**

Relative:
Lower

Actual:
35 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: 900 GRAND STREET MILK LLC
Facility address: 900 GRAND ST
BROOKLYN, NY 11211
EPA ID: NYD986987600
Mailing address: NORFOLK ST
NEW YORK, NY 10002
Contact: ROMEO L SANTOS JR
Contact address: NORFOLK ST
NEW YORK, NY 10002
Contact country: US
Contact telephone: (718) 857-3100
Contact email: DONCARLO@AOL.COM
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

900 GRAND STREET MILK LLC (Continued) **1000556201**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	900 GRAND ST MILK LLC
Owner/operator address:	NORFOLK ST
	NEW YORK, NY 10002
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/15/2005
Owner/Op end date:	Not reported

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/15/2005
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	900 GRAND STREET MILK LLC
Classification:	Not a generator, verified

Date form received by agency:	11/23/2005
Site name:	900 GRAND STREET MILK LLC
Classification:	Not a generator, verified

900 GRAND STREET MILK LLC (Continued) **1000556201**

Date form received by agency: 11/09/2005
Site name: 900 GRAND STREET MILK LLC
Classification: Small Quantity Generator

Date form received by agency: 08/22/2005
Site name: VON DAM INC
Classification: Small Quantity Generator

Date form received by agency: 02/03/1992
Site name: F H VON DAMM INC
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/03/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110032990743

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986987600
Country: USA
Location Address 1: 900 GRAND STREET
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: 900 GRAND STREET MILK LLC
Contact: DAN SINGH/DON CARLO ENVIR
Address: 900 GRAND STREET
City/State/Zip: BROOKLYN, NY 11211
Country: USA
Phone: 718-641-4000

Manifest:

Document ID: NYG5224239
Manifest Status: Not reported
Trans1 State ID: NYD049178296

900 GRAND STREET MILK LLC (Continued) **1000556201**

Trans2 State ID:	Not reported
Generator Ship Date:	10/06/2005
Trans1 Recv Date:	10/06/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986987600
Trans1 EPA ID:	70491PANY
Trans2 EPA ID:	Not reported
TSDF ID:	CDX480000000
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	Not reported
Year:	2005

Document ID:	NYG5224248
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/2005
Trans1 Recv Date:	10/06/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2005

900 GRAND STREET MILK LLC (Continued) **1000556201**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986987600
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX109000000
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	U036 - CHLORDANE, TECHNICAL
Quantity:	00400
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	01.00
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	Not reported
Year:	2005

Document ID:	NYG5224239
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/2005
Trans1 Recv Date:	10/06/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986987600
Trans1 EPA ID:	70491PANY
Trans2 EPA ID:	Not reported
TSDF ID:	CDX480000000
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00600
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported

900 GRAND STREET MILK LLC (Continued) **1000556201**

Specific Gravity:	01.00
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	Not reported
Year:	2005

AB100 **900 GRAND ST. MILK LLC** **NY UST** **U004045804**
SE **900 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.206 mi.
1090 ft. **Site 2 of 3 in cluster AB**

Relative:
Lower

Actual:
35 ft.

UST:

Id/Status:	2-610024 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/07/2010
UTM X:	589690.64315000002
UTM Y:	4507385.0997400004
Site Type:	Other

Affiliation Records:

Site Id:	353653
Affiliation Type:	Facility Owner
Company Name:	900 GRAND ST. MILK LLC
Contact Type:	AGENT
Contact Name:	ROMEO SUWTOS
Address1:	133 NORFOLK STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(212) 677-8603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/7/2005

Site Id:	353653
Affiliation Type:	Mail Contact
Company Name:	ATKINS & BRESKIN, CO.
Contact Type:	Not reported
Contact Name:	MR. JERRY ATKINS
Address1:	133 NORFOLK STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(212) 677-8603
EMail:	Not reported
Fax Number:	Not reported

900 GRAND ST. MILK LLC (Continued) **U004045804**

Modified By:	KXTANG
Date Last Modified:	10/7/2005

Site Id:	353653
Affiliation Type:	On-Site Operator
Company Name:	900 GRAND ST. MILK LLC
Contact Type:	Not reported
Contact Name:	JERRY ATKINS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 677-8603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/7/2005

Site Id:	353653
Affiliation Type:	Emergency Contact
Company Name:	900 GRAND ST. MILK LLC
Contact Type:	Not reported
Contact Name:	JERRY ATKINS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 677-8603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	10/7/2005

Tank Info:

Tank Number:	01
Tank ID:	208228
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	08/31/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG

900 GRAND ST. MILK LLC (Continued) **U004045804**

Last Modified: 10/07/2005

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 02
Tank ID: 208229
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 08/31/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 10/07/2005

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 03
Tank ID: 208230
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported

900 GRAND ST. MILK LLC (Continued) **U004045804**

Date Tank Closed:	08/31/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	10/07/2005

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

AA101 **GRAND CLEANERS** **RCRA-SQG 1004760137**
SSW **765 GRAND ST** **FINDS NYR000033357**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.207 mi. **NY DRYCLEANERS**
1091 ft. **Site 2 of 3 in cluster AA** **US AIRS**

Relative: Higher

Actual: 42 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	GRAND CLEANERS
Facility address:	765 GRAND ST BROOKLYN, NY 11211
EPA ID:	NYR000033357
Mailing address:	GRAND ST BROOKLYN, NY 11211
Contact:	LUIS ALCANTARA
Contact address:	GRAND ST BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	(718) 599-3758
Contact email:	Not reported
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	LUIS E ALCANTARA

GRAND CLEANERS (Continued) **1004760137**

Owner/operator address: NOT REQUIRED
QUEENS, NY 11377
Owner/operator country: US
Owner/operator telephone: (718) 565-7195
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LUIS E ALCANTARA
Owner/operator address: NOT REQUIRED
QUEENS, NY 11377
Owner/operator country: US
Owner/operator telephone: (718) 565-7195
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GRAND CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/19/1996
Site name: GRAND CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

GRAND CLEANERS (Continued) **1004760137**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004530954

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

NY MANIFEST:

EPA ID:	NYR000033357
Country:	USA
Location Address 1:	765 GRAND ST
Location Address 2:	Not reported
Location City:	KINGS
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	GRAND CLEANER
Contact:	LUIS ALCANTARA
Address:	765 GRAND ST
City/State/Zip:	KINGS, NY 11211
Country:	USA
Phone:	718-599-3758

GRAND CLEANERS (Continued) **1004760137**

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014
Trans2 Recv Date:	06/03/2014
TSD Site Recv Date:	06/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	60
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012906900JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014
Trans2 Recv Date:	06/03/2014
TSD Site Recv Date:	06/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	260
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels

GRAND CLEANERS (Continued) **1004760137**

Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012906900JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NYD980769947
Generator Ship Date:	01/08/2009
Trans1 Recv Date:	01/08/2009
Trans2 Recv Date:	01/20/2009
TSD Site Recv Date:	01/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001030536SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NYD980769947

GRAND CLEANERS (Continued) **1004760137**

Generator Ship Date:	01/08/2009
Trans1 Recv Date:	01/08/2009
Trans2 Recv Date:	01/20/2009
TSD Site Recv Date:	01/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	133.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001030536SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/11/2009
Trans1 Recv Date:	11/11/2009
Trans2 Recv Date:	11/19/2009
TSD Site Recv Date:	12/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	195.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002316122SKS
Import Ind:	N
Export Ind:	N

GRAND CLEANERS (Continued) **1004760137**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/11/2009
Trans1 Recv Date:	11/11/2009
Trans2 Recv Date:	11/19/2009
TSD Site Recv Date:	12/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	60.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002316122SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NYD980769947
Generator Ship Date:	01/08/2009
Trans1 Recv Date:	01/08/2009
Trans2 Recv Date:	01/20/2009
TSD Site Recv Date:	01/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

GRAND CLEANERS (Continued) **1004760137**

Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	195.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001030536SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/11/2009
Trans1 Recv Date:	11/11/2009
Trans2 Recv Date:	11/19/2009
TSD Site Recv Date:	12/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	133.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002316122SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

GRAND CLEANERS (Continued) **1004760137**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	06/28/2011
Trans1 Recv Date:	06/28/2011
Trans2 Recv Date:	07/14/2011
TSD Site Recv Date:	07/15/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002595669SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	06/28/2011
Trans1 Recv Date:	06/28/2011
Trans2 Recv Date:	07/14/2011
TSD Site Recv Date:	07/15/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	100.0

GRAND CLEANERS (Continued) **1004760137**

Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002595669SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	06/28/2011
Trans1 Recv Date:	06/28/2011
Trans2 Recv Date:	07/14/2011
TSD Site Recv Date:	07/15/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002595669SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported

GRAND CLEANERS (Continued) **1004760137**

Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/28/2008
Trans1 Recv Date:	05/28/2008
Trans2 Recv Date:	06/05/2008
TSD Site Recv Date:	06/06/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	133.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000141928SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/28/2008
Trans1 Recv Date:	05/28/2008
Trans2 Recv Date:	06/05/2008
TSD Site Recv Date:	06/06/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	60.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008

GRAND CLEANERS (Continued) **1004760137**

Manifest Tracking Num:	000141928SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814252374
Generator Ship Date:	07/22/2013
Trans1 Recv Date:	07/22/2013
Trans2 Recv Date:	07/29/2013
TSD Site Recv Date:	07/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	80
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011176417JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814252374
Generator Ship Date:	07/22/2013
Trans1 Recv Date:	07/22/2013
Trans2 Recv Date:	07/29/2013

GRAND CLEANERS (Continued) **1004760137**

TSD Site Recv Date:	07/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	60
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011176417JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814252374
Generator Ship Date:	07/22/2013
Trans1 Recv Date:	07/22/2013
Trans2 Recv Date:	07/29/2013
TSD Site Recv Date:	07/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	260
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011176417JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N

GRAND CLEANERS (Continued) **1004760137**

Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: OKD981588791
Generator Ship Date: 10/11/2007
Trans1 Recv Date: 10/11/2007
Trans2 Recv Date: 10/19/2007
TSD Site Recv Date: 10/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000033357
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD980587364
Waste Code: Not reported
Quantity: 60
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000074197SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: OKD981588791
Generator Ship Date: 10/11/2007
Trans1 Recv Date: 10/11/2007
Trans2 Recv Date: 10/19/2007
TSD Site Recv Date: 10/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000033357
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

GRAND CLEANERS (Continued) **1004760137**

TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	133
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000074197SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/09/2007
Trans1 Recv Date:	03/09/2007
Trans2 Recv Date:	03/16/2007
TSD Site Recv Date:	03/19/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	133
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000021213SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

GRAND CLEANERS (Continued) **1004760137**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/09/2007
Trans1 Recv Date:	03/09/2007
Trans2 Recv Date:	03/16/2007
TSD Site Recv Date:	03/19/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	193
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000021213SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

DRYCLEANERS:

Facility ID:	2-6101-01147
Phone Number:	718-599-3758
Region:	Not reported
Registration Effective Date:	10/2/2003
Inspection Date:	07MAY21
Install Date:	98
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110015655334
Plant name:	PAULINO'S CLEANERS
Plant address:	765 GRAND ST BROOKLYN, NY 112114950
County:	KINGS
Region code:	02

GRAND CLEANERS (Continued) **1004760137**

Dunn & Bradst #:	Not reported
Air quality cntrl region:	043
Sic code:	7216
Sic code desc:	DRYCLEANING PLANTS, EXCEPT RUG
North Am. industrial classf:	812320
NAIC code description:	Drycleaning and Laundry Services (except Coin-Operated)
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	SIP SOURCE
National action type:	Not reported
Date achieved:	00900
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	Not reported
Date achieved:	00900
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported
Air program:	Not reported
National action type:	Not reported
Date achieved:	Not reported
Penalty amount:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

GRAND CLEANERS (Continued) **1004760137**

Hist compliance date: 1403
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1402
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1304
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1402
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1304
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104

GRAND CLEANERS (Continued) **1004760137**

Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1401
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1403
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1401
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported

GRAND CLEANERS (Continued) **1004760137**

Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: UNCLASSIFIED
Repeat violator date: Not reported
Turnover compliance: Not reported

AA102 **EDR US Hist Cleaners** **1015094494**
SSW **765 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.207 mi.
1091 ft. **Site 3 of 3 in cluster AA**

Relative:
Higher

Actual:
42 ft.

EDR Historical Cleaners:

Name: GRAND DRY CLEANERS
Year: 2005
Address: 765 GRAND ST

Name: GRAND DRY CLEANERS
Year: 2006
Address: 765 GRAND ST

Name: GRAND DRY CLEANERS
Year: 2007
Address: 765 GRAND ST

Name: GRAND DRY CLEANERS
Year: 2008
Address: 765 GRAND ST

Name: GRAND DRY CLEANERS
Year: 2010
Address: 765 GRAND ST

Name: PAULINO CLEANING INC
Year: 2011
Address: 765 GRAND ST

Name: PAULINO CLEANING INC
Year: 2012
Address: 765 GRAND ST

AC103 **CON EDISON** **NY MANIFEST** **S117059506**
WSW **143 DEVOE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.207 mi.
1091 ft. **Site 1 of 2 in cluster AC**

Relative:
Higher

Actual:
37 ft.

NY MANIFEST:

EPA ID:	NYP004516787
Country:	USA
Location Address 1:	143 DEVOE ST
Location Address 2:	STRUCTURE 12352
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004516787
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002417604GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117059506**

Mgmt Method Type Code: H110

AB104 **EDR US Hist Auto Stat** **1015666589**
SE **900 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.208 mi.
1096 ft. **Site 3 of 3 in cluster AB**

Relative:
Lower

Actual:
34 ft.

EDR Historical Auto Stations:

Name:	GOOD WILL AUTO CORP
Year:	2009
Address:	900 GRAND ST
Name:	GOOD WILL AUTO CORP
Year:	2010
Address:	900 GRAND ST
Name:	GOOD WILL AUTO CORP
Year:	2011
Address:	900 GRAND ST
Name:	GOOD WILL AUTO CORP
Year:	2012
Address:	900 GRAND ST

AD105 **GLOVEMAN REALTY CORP** **NY UST** **U000403889**
SW **294 GRAHAM AVENUE** **NY HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.213 mi.
1127 ft. **Site 1 of 2 in cluster AD**

Relative:
Higher

Actual:
39 ft.

UST:

Id/Status:	2-329800 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	02/03/2008
UTM X:	589232.60352
UTM Y:	4507340.8432400003
Site Type:	Other

Affiliation Records:

Site Id:	15506
Affiliation Type:	Facility Owner
Company Name:	GLOVEMAN REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	294 GRAHAM AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-3740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

GLOVEMAN REALTY CORP (Continued) **U000403889**

Date Last Modified: 3/4/2004

Site Id: 15506
Affiliation Type: Mail Contact
Company Name: GLOVEMAN REALTY CORP
Contact Type: Not reported
Contact Name: C. GERBER
Address1: 294 GRAHAM AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 387-3740
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15506
Affiliation Type: On-Site Operator
Company Name: GLOVEMAN REALTY CORP
Contact Type: Not reported
Contact Name: ALLAN GERBER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 387-3740
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15506
Affiliation Type: Emergency Contact
Company Name: GLOVEMAN REALTY CORP
Contact Type: Not reported
Contact Name: CHESTER GERBER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 482-8745
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 20185

GLOVEMAN REALTY CORP (Continued) **U000403889**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	09/21/2004
Next Test Date:	09/21/2009
Pipe Model:	Not reported
Modified By:	EXROSSAN
Last Modified:	10/18/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	2-329800
SPDES Number:	Not reported
Emergency Contact:	CHESTER GERBER
Emergency Telephone:	(516) 482-8745
Operator:	ALLAN GERBER
Operator Telephone:	(718) 387-3740
Owner Name:	GLOVEMAN REALTY CORP
Owner Address:	294 GRAHAM AVE
Owner City,St,Zip:	BKLYN, NY 11211
Owner Telephone:	(718) 387-3740
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	GLOVEMAN REALTY CORP
Mailing Address:	294 GRAHAM AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BKLYN, NY 11211
Mailing Contact:	C. GERBER
Mailing Telephone:	(718) 387-3740
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	294 GRAHAM AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING

GLOVEMAN REALTY CORP (Continued) **U000403889**

Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/12/2000
Expiration Date:	02/03/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	11/01/1999
Next Test Date:	11/01/2004
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

106
North
1/8-1/4
0.215 mi.
1137 ft.

CON EDISON
251 WITHERS ST
BROOKLYN, NY 11211

NY MANIFEST **S117738252**
N/A

Relative:
Lower

Actual:
30 ft.

NY MANIFEST:

EPA ID:	NYP004712678
Country:	USA
Location Address 1:	251 WITHERS ST
Location Address 2:	SB53398

CON EDISON (Continued) **S117738252**

Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 01/07/2015
Trans1 Recv Date: 01/07/2015
Trans2 Recv Date: 01/13/2015
TSD Site Recv Date: 01/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004712678
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 80
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 002620135GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AE107 **ST NICHOLAS H S BUILDING** **NY AST** **U003386428**
ESE **11-29 CATHERINE ST** **NY HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.216 mi.
1141 ft. **Site 1 of 2 in cluster AE**

Relative:
Lower

Actual:
28 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-241261
Program Type:	PBS
UTM X:	589802.76139
UTM Y:	4507441.6317299996
Expiration Date:	06/30/2007
Site Type:	School

Affiliation Records:

Site Id:	9182
Affiliation Type:	Facility Owner
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	26 OLIVE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9182
Affiliation Type:	Mail Contact
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	REV. KENNETH J. GRANDE
Address1:	26 OLIVE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9182
Affiliation Type:	On-Site Operator
Company Name:	ST NICHOLAS H S BUILDING
Contact Type:	Not reported
Contact Name:	LISA ARMBAND
Address1:	Not reported
Address2:	Not reported
City:	Not reported

ST NICHOLAS H S BUILDING (Continued) **U003386428**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	9182
Affiliation Type:	Emergency Contact
Company Name:	ST NICHOLAS R C CHURCH
Contact Type:	Not reported
Contact Name:	KENNETH J. GRANDE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	9925
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT

ST NICHOLAS H S BUILDING (Continued) **U003386428**

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:
PBS Number: 2-241261
SWIS Code: 6101
Operator: ROGER MAZZOLA
Facility Phone: (718) 388-5900
Facility Addr2: 11 CATHERINE ST
Facility Type: OTHER
Emergency: REV PEDRO N OSSA
Emergency Tel: (718) 388-1420
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: ST NICHOLAS R C CHURCH
Owner Address: 26 OLIVE ST
Owner City,St,Zip: NEW YORK, NY 11211
Federal ID: Not reported
Owner Tel: (718) 388-1420
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: REV PEDRO N OSSA
Mailing Name: ST NICHOLAS R C CHURCH
Mailing Address: 26 OLIVE ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 11211
Mailing Telephone: (718) 388-1420
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 06/23/1997
Expiration: 06/30/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

ST NICHOLAS H S BUILDING (Continued) **U003386428**

Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	3
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

108
North
1/8-1/4
0.216 mi.
1143 ft.

CON EDISON **NY MANIFEST** **S117058758**
267 WITHERS ST **N/A**
BROOKLYN, NY 11211

Relative:
Lower

Actual:
31 ft.

NY MANIFEST:

EPA ID:	NYP004508925
Country:	USA
Location Address 1:	267 WITHERS ST
Location Address 2:	SB 53396
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2014
Trans1 Recv Date:	04/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508925
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117058758**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002418071GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

---

109 **EASTERN DISTRICT HIGH SCHOOL** **RCRA NonGen / NLR** **1000990675**
SSE **850 GRAND ST** **NY AST** **NY0001039668**
1/8-1/4 **BROOKLYN, NY 11211** **NY HIST AST**
0.217 mi. **NY MANIFEST**
1148 ft. **NY Spills**

Relative: Higher

Actual: 41 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	EASTERN DISTRICT HIGH SCHOOL
Facility address:	850 GRAND ST BROOKLYN, NY 11211
EPA ID:	NY0001039668
Mailing address:	GRAND ST BROOKLYN, NY 11211
Contact:	Not reported
Contact address:	GRAND ST BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Municipal
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CITY OF NEW YORK
Owner/operator address:	1 CENTRE ST NEW YORK, NY 11211
Owner/operator country:	US
Owner/operator telephone:	(212) 669-8710
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW YORK
Owner/operator address: 1 CENTRE ST
NEW YORK, NY 11211
Owner/operator country: US
Owner/operator telephone: (212) 669-8710
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: EASTERN DISTRICT HIGH SCHOOL
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 10/11/1996
Site name: EASTERN DISTRICT H.S.
Classification: Large Quantity Generator

Date form received by agency: 01/29/1996
Site name: EASTERN DISTRICT HIGH SCHOOL
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 02/17/1995
Site name: EASTERN DISTRICT HIGH SCHOOL
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

. Waste code: D009

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

. Waste name: MERCURY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 10/07/1996
Date achieved compliance: 11/01/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/09/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/01/1996
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 11/01/1996
Evaluation lead agency: State

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-355623
Program Type: PBS
UTM X: 589594.69625000004
UTM Y: 4507317.4160200004
Expiration Date: 06/28/2018
Site Type: School

Affiliation Records:
Site Id: 17731
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: MUNENDRA SHARMA
Address1: 44-36 VERNON BOULEVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Date Last Modified: 3/4/2015

Site Id: 17731
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: MUNENDRA SHARMA
Address1: FIELD OPERATIONS-FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: MSHARMA@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/26/2015

Site Id: 17731
Affiliation Type: On-Site Operator
Company Name: EASTERN DISTRICT HS - BROOKLYN K450
Contact Type: Not reported
Contact Name: PLANT OPERATIONS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 349-5400
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/10/2013

Site Id: 17731
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: SCHOOL SAFETY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 935-3300
EMail: Not reported
Fax Number: Not reported
Modified By: GDBREEN
Date Last Modified: 9/10/2014

Tank Info:

Tank Number: 001
Tank Id: 34701

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/11/1980
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 07/08/2013
Material Name: #4 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 34702
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/11/1980
Capacity Gallons: 20000

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	07/08/2013
Material Name:	#4 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-355623
SWIS Code:	6101
Operator:	PLANT OPERATION
Facility Phone:	(718) 391-6000
Facility Addr2:	850 GRAND STREET
Facility Type:	SCHOOL
Emergency:	SCHOOL SAFETY
Emergency Tel:	(212) 979-3300
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CITY OF NEW YORK C/O BOARD OF EDUCATION
Owner Address:	28-11 QUEENS PLAZA NORTH
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 391-6832
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	FRANK CARDELLO NTROL
Mailing Name:	BOARD OF EDUCATION
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	5TH FLOOR
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 391-6832
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	09/02/1998
Expiration:	06/28/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	40000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 20000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 002
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 20000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

NY MANIFEST:
EPA ID: NY0001039668
Country: USA

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Location Address 1: 850 GRAND ST
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: NYC BOE - EASTERN DISTRICT HIGH SCHOOL
Contact: KENNETH SHELLY
Address: 850 GRAND ST
City/State/Zip: BROOKLYN, NY 11211
Country: USA
Phone: 914-287-3407

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/23/2009
Trans1 Recv Date: 04/23/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/30/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0001039668
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 10.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716671JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Generator Ship Date:	04/23/2009
Trans1 Recv Date:	04/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004716671JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2009
Trans1 Recv Date:	04/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004716671JJK
Import Ind:	N
Export Ind:	N

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2009
Trans1 Recv Date:	04/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	13.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004716671JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2009
Trans1 Recv Date:	04/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	6.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004716671JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	07/06/2012
TSD Site Recv Date:	07/07/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD048415665
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162843FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H040

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	4.0

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	23.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	16.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2012
Trans1 Recv Date:	06/27/2012
Trans2 Recv Date:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

TSD Site Recv Date:	06/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	181.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004162842FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	PAE4160833
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0346
Trans2 State ID:	Not reported
Generator Ship Date:	04/12/1995
Trans1 Recv Date:	04/12/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/13/1995
Part A Recv Date:	05/11/1995
Part B Recv Date:	05/01/1995
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987367216
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	02470
Units:	P - Pounds
Number of Containers:	019
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	PAE4162620
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0346
Trans2 State ID:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Generator Ship Date:	06/14/1995
Trans1 Recv Date:	06/14/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/16/1995
Part A Recv Date:	06/27/1995
Part B Recv Date:	07/03/1995
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987367216
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	01100
Units:	P - Pounds
Number of Containers:	011
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00060
Units:	P - Pounds
Number of Containers:	003
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	PAE4164856
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PAAH0346
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/1995
Trans1 Recv Date:	09/14/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/15/1995
Part A Recv Date:	09/22/1995
Part B Recv Date:	10/11/1995
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987367216
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Document ID:	PAE4161625
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0346
Trans2 State ID:	Not reported
Generator Ship Date:	04/26/1995
Trans1 Recv Date:	04/26/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/28/1995
Part A Recv Date:	05/05/1995
Part B Recv Date:	05/15/1995
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987367216
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00840
Units:	P - Pounds
Number of Containers:	007
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	PAE1782443
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0346
Trans2 State ID:	Not reported
Generator Ship Date:	03/23/1995
Trans1 Recv Date:	03/23/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/24/1995
Part A Recv Date:	04/12/1995
Part B Recv Date:	04/11/1995
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987367216
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	03100
Units:	P - Pounds
Number of Containers:	028
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	NYG2501046
Manifest Status:	Not reported
Trans1 State ID:	PD8070
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2000
Trans1 Recv Date:	06/01/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2000
Part A Recv Date:	Not reported

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049178296
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	00005
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYG2501046
Manifest Status:	Not reported
Trans1 State ID:	PD8070
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2000
Trans1 Recv Date:	06/01/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001039668
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049178296
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

SPILLS:

Facility ID:	0301522
Facility Type:	ER
DER Facility ID:	118026
Site ID:	138021
DEC Region:	2
Spill Date:	5/12/2003
Spill Number/Closed Date:	0301522 / 11/14/2003
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	5/12/2003
CID:	204
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/12/2003
Spill Record Last Update:	11/17/2003
Spiller Name:	Not reported
Spiller Company:	GRAND STREET CAMPUS H.S
Spiller Address:	850 GRAND STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	MICHAEL WHITE
Contact Phone:	(516) 746-8000 250

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"5/12/2003 - Zhao/DO: Some material discovered with petroluem vapor during excavation (3'deep 10' wide and 600' long) at this location. About 300 yard this dark soil/material stock piled. Demeo responded to scene.5/29/2003 - Mr. Janice Lalli (attorney for athletic field contractor) (212-644-1010). He called to find out what work needs to be done to close the site out. He says that lab results have come back and he would like to know what these results say and what work will be needed.6/2/03 TJDDemeo spoke with Ram (YU associates) regarding site. Analytical data reveals contamination above TAGM. Contractor has been directed to excavate and properly dispose of contaminated soils. Upon completion of excavation contractor is directed to collect end-point samples and provide laboratory data when analysis has been completed. Disposal manifests are required prior to spill closure.11/17/03 TJDTotal of 450 cu yds of contaminated soils excavated for off-site treatment and disposal. Endpoint samples taken revealing elevated concentrations of SVOC's and metals. Elevated chemical concentrations are attributed to historical urban fill. Health and safety plan submitted with closure documents to manage soils during future excavation. Site does not meet standards. Spill closed.

Remarks: CALLERS CLIENT WAS DOING WORK IN THE ATHLETIC FIELD AT THE SCHOOLHE CAME ACROSS SOME STAINED PETROLEUM SMELLING DIRT - HE TOLD THECONTRACTOR WHO WAS SUPPOSED TO FIX IT - THEN HE WAS LET GO FROM THE JOB

Material:

Site ID:	138021
Operable Unit ID:	867923
Operable Unit:	01
Material ID:	506013
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	1410814
Facility Type:	ER
DER Facility ID:	17703
Site ID:	504525
DEC Region:	2
Spill Date:	2/10/2015
Spill Number/Closed Date:	1410814 / Not Reported
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2/10/2015

EASTERN DISTRICT HIGH SCHOOL (Continued) **1000990675**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2/10/2015
Spill Record Last Update:	2/12/2015
Spiller Name:	MUNUNDRA
Spiller Company:	NYC DEPT OF EDUCATION
Spiller Address:	850 GRAND ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	MUNUNDRA UNKNOWN
Contact Phone:	(718) 349-5752
DEC Memo:	2/11/15-Vought-Duty desk officer. Looked up PBS and site has two (20,000-gallon) #4 fuel oil ASTs. Vought called PTC Lara (Ph:718-624-4842) for more information and spoke to Marisol at PTC who noted that Lara was out of office but she did have knowledge of site and noted that they were waiting for approval from school to excavate out old fill box and once that permission was obtained they would then get sidewalk permits to do the work. She also confirmed that there was no spill inside school. Vought noted to Marisol that DEC would be requiring collection of endpoint samples and that Vought would be sending out letter. Spill assigned to DEC piper as daytime runner.2/12/14-Vought-Sent out contaminated soil letter with endpoint sampling requirement and one month report deadline with cc to PTC and DEC Piper and Vought also added letter to D2. Letter sent to:Mr. Munendra SharmaNYC Department of EducationField Operations - Fuel Division44-36 Vernon Blvd.Long Island City, NY 11101DEC requires:1)collection of soil endpoint samples at fill box (once it and contaminated soil are removed).
Remarks:	loss to soil while changing the fill box, c/u pending

Material:

Site ID:	504525
Operable Unit ID:	1253877
Operable Unit:	01
Material ID:	2256233
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

110
SSW
1/8-1/4
0.217 mi.
1148 ft.

755 REALTY CORP.
753 GRAND STREET
BROOKLYN, NY 11211

NY AST **A100292721**
N/A

Relative:
Higher

Actual:
41 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608530
Program Type:	PBS
UTM X:	589288.93634000001
UTM Y:	4507301.0948299998
Expiration Date:	03/10/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30382
Affiliation Type:	Facility Owner
Company Name:	755 REALTY CORP
Contact Type:	PRES
Contact Name:	755 REALTY CORP
Address1:	753 GRAND ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-8287
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/13/2014

Site Id:	30382
Affiliation Type:	Mail Contact
Company Name:	ROSARIO GANGI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	753 GRAND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-8287
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/13/2014

Site Id:	30382
Affiliation Type:	On-Site Operator
Company Name:	755 REALTY CORP.
Contact Type:	Not reported
Contact Name:	ROSARIO GANGI
Address1:	Not reported
Address2:	Not reported
City:	Not reported

755 REALTY CORP. (Continued) **A100292721**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 387-8287
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30382
Affiliation Type: Emergency Contact
Company Name: ROSARIO GANGI
Contact Type: Not reported
Contact Name: ROSARIO GANGI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 813-5556
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 65285
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B05 - Tank External Protection - Jacketed
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
I03 - Overfill - Automatic Shut-Off

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 1101
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS

755 REALTY CORP. (Continued) **A100292721**

Last Modified: 05/13/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

AE111 **CON EDISON** **NY MANIFEST** **S117061898**
ESE **12 CATHERINE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.218 mi.
1149 ft. **Site 2 of 2 in cluster AE**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:
EPA ID: NYP004542254
Country: USA
Location Address 1: 12 CATHERINE ST
Location Address 2: SB 58595
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 05/23/2014
Trans1 Recv Date: 05/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004542254
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002423685GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

CON EDISON (Continued) **S117061898**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Y112 **EDR US Hist Cleaners** **1015064794**
North **47 KINGSLAND AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.218 mi.
1151 ft. **Site 2 of 2 in cluster Y**

Relative:
Lower

Actual:
32 ft.

EDR Historical Cleaners:
Name: 47 LAUNDROMAT CORP
Year: 2004
Address: 47 KINGSLAND AVE

Name: 47 LAUNDROMAT CORP
Year: 2005
Address: 47 KINGSLAND AVE

---

113 **CON EDISON** **NY MANIFEST** **S117060757**
ENE **56 SHARON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.220 mi.
1164 ft.

Relative:
Lower

Actual:
22 ft.

NY MANIFEST:
EPA ID: NYP004529996
Country: USA
Location Address 1: 56 SHARON ST
Location Address 2: SB6455
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 05/15/2014
Trans1 Recv Date: 05/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2014

CON EDISON (Continued) **S117060757**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004529996
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002422266GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AD114 **EDR US Hist Auto Stat** **1015388503**
SW **283 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.221 mi.
1166 ft. **Site 2 of 2 in cluster AD**

Relative:
Higher

Actual:
39 ft.

EDR Historical Auto Stations:

Name:	BRAKE THE RULES INC
Year:	2003
Address:	283 GRAHAM AVE
Name:	BRAKE THE RULES INC
Year:	2004
Address:	283 GRAHAM AVE

AF115 **AMERICAN WOOD COLUMN CORP** **NY AST** **U003393224**
SE **913 GRAND ST** **NY HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.223 mi.
1175 ft. **Site 1 of 5 in cluster AF**

Relative:
Lower

Actual:
32 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-325546
Program Type:	PBS
UTM X:	589773.54584000004
UTM Y:	4507387.4487399999

AMERICAN WOOD COLUMN CORP (Continued) **U003393224**

Expiration Date: 10/23/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 15127
Affiliation Type: Facility Owner
Company Name: AMERICAN WOOD COLUMN CORP
Contact Type: PRESIDENT
Contact Name: THOMAS P. LUPO
Address1: 913 GRAND ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-3163
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 9/7/2007

Site Id: 15127
Affiliation Type: Mail Contact
Company Name: AMERICAN WOOD COLUMN CORP
Contact Type: Not reported
Contact Name: THOMAS LUPO
Address1: 913 GRAND ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-3163
EMail: TPL913@VERIZON.NET
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 11/16/2012

Site Id: 15127
Affiliation Type: On-Site Operator
Company Name: AMERICAN WOOD COLUMN CORP
Contact Type: Not reported
Contact Name: AMERICAN WOOD COLUMN CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 782-3163
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15127
Affiliation Type: Emergency Contact
Company Name: AMERICAN WOOD COLUMN CORP

AMERICAN WOOD COLUMN CORP (Continued) **U003393224**

Contact Type:	Not reported
Contact Name:	THOMAS LUPO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 621-3292
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	26334
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/15/1960
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	11/16/2012
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-325546
SWIS Code:	6101
Operator:	AMERICAN WOOD COLUMN CORP
Facility Phone:	(718) 782-3163
Facility Addr2:	913 GRAND ST
Facility Type:	Not reported
Emergency:	THOMAS LUPO

AMERICAN WOOD COLUMN CORP (Continued) **U003393224**

Emergency Tel:	(516) 488-2065
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	AMERICAN WOOD COLUMN CORP
Owner Address:	913 GRAND ST
Owner City,St,Zip:	BROOKLYN, NY 11211
Federal ID:	Not reported
Owner Tel:	(718) 782-3163
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	THOMAS LUPO
Mailing Name:	AMERICAN WOOD COLUMN CORP
Mailing Address:	913 GRAND ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211
Mailing Telephone:	(718) 782-3163
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	10/01/1997
Expiration:	10/23/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	1500
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported

AMERICAN WOOD COLUMN CORP (Continued) **U003393224**

Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

AG116 **COOPER PARK HOUSES** **NY UST** **U000410820**
NNE **295 JACKSON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.223 mi.
1175 ft. **Site 1 of 2 in cluster AG**

Relative:
Lower

Actual:
31 ft.

UST:
Id/Status: 2-474630 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/28/2019
UTM X: 589603.91353999998
UTM Y: 4507900.8643300002
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 20929
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5806
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/13/2015

Site Id: 20929
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Y.TKACH@NYCHA.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR

COOPER PARK HOUSES (Continued) **U000410820**

Date Last Modified: 12/24/2014

Site Id: 20929
Affiliation Type: On-Site Operator
Company Name: COOPER PARK HOUSES
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/25/2014

Site Id: 20929
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPARTMENT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 707-5900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/30/2014

Tank Info:

Tank Number: 1
Tank ID: 37786
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 20000
Install Date: 10/01/1953
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 06/19/2012
Next Test Date: 06/19/2017
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/13/2012

COOPER PARK HOUSES (Continued) **U000410820**

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number:	2
Tank ID:	37787
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	20000
Install Date:	10/01/1953
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	06/19/2012
Next Test Date:	06/19/2017
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	09/13/2012

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

AG117 **COOPER PARK -NYCHA** **NY LTANKS** **S106722316**
NNE **295 JACKSON ST** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.223 mi.
1175 ft. **Site 2 of 2 in cluster AG**

Relative:
Lower

Actual:
31 ft.

LTANKS:

Site ID:	64539
Spill Number/Closed Date:	9414384 / 3/29/1996
Spill Date:	1/31/1995
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1/31/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/2/1995
Spill Record Last Update:	12/16/2005
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204947
DEC Memo:	Not reported
Remarks:	TANK TEST-GROSS FAILURE

Material:

Site ID:	64539
Operable Unit ID:	1007967
Operable Unit:	01
Material ID:	373126
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

COOPER PARK -NYCHA (Continued) **S106722316**

Site ID:	64539
Spill Tank Test:	1543587
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	250035
Spill Number/Closed Date:	9515713 / 9/14/2009
Spill Date:	3/7/1996
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	3/7/1996
CID:	297
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/7/1996
Spill Record Last Update:	9/14/2009
Spiller Name:	PAUL GOLDSTEIN
Spiller Company:	NEW YORK CITY
Spiller Address:	295 JACKSON ST
Spiller City,St,Zip:	BROOKLYN, NY 11211-
Spiller County:	001
Spiller Contact:	PAUL GOLSTEIN
Spiller Phone:	(212) 306-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204947
DEC Memo:	12/16/05: This spill transferred from J.Kolleeny to S.Kraszewski.07/28/06: See DEc remarks for spill #9515837. - SK5/21/08: J.Kann - site reassigned to J.Kann. Investigative work Plan received.6/10/08: Spill 9515837 closed and consolidated with this spill.8/18/09: J.Kann - Site Assessment report submitted in June 2009. Report indicates sheen of product in one well (MW-1). Two other groundwater monitoring wells sampled and results indicate no exceedances. Follow up observations performed by the consultant indicate that the sheen was no longer present in August 2009. A site visit is planned for August 21 to observe groundwater sampling of the well.9/14/09: J.Kann - Site visit made on 8/21. No oil sheen present in the well (MW-1). Malcolm Pirnie sampled well. Summary of analysis submitted on 9/11. Information provided indicated all concentrations

COOPER PARK -NYCHA (Continued) **S106722316**

below guidance. Based on information received, spill closed.
Remarks: Not reported

Material:
Site ID: 250035
Operable Unit ID: 1026766
Operable Unit: 01
Material ID: 355831
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 250036
Spill Number/Closed Date: 9515837 / 6/10/2008
Spill Date: 3/11/1996
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: jkkann
Referred To: CONSOLIDATED WITH 9515713
Reported to Dept: 3/11/1996
CID: 312
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/11/1996
Spill Record Last Update: 6/10/2008
Spiller Name: CALLER
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: MANHATTAN, NY 10007-
Spiller County: 001
Spiller Contact: FRANK OCELLO
Spiller Phone: (212) 306-3233
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 204947
DEC Memo: 12/16/05: This spill transferred from J.Kolleeny to S.Kraszewski.07/28/06: NYCHA update summary states that two 20K USTs installed in 1953 and store #2 oil are currently in service. Both

COOPER PARK -NYCHA (Continued) **S106722316**

spills due to TTFs caused by leaking man way gasket. Both repaired and retested. The tanks are rescheduled for testing in 2007. No site assessment available. NYCHA recommends a site assessment be performed during tank replacement. - SK09/26/06:Site status summary provided to DEC by NYCHA indicates that two monitoring wells are on site and that water/oil mixture is being bailed. Site was therefore identified as a high priority. Site transferred from S. Kraszewski to J. Kann - JK6/10/08: J.Kann - spill closed and consolidated with 9515713.

Remarks: no apparent leak - tank failed

Material:

Tank Test:

Site ID:	250036
Spill Tank Test:	1544431
Tank Number:	1
Tank Size:	20000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

Site ID:	315998
Spill Number/Closed Date:	9414271 / 3/29/1996
Spill Date:	1/27/1995
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1/27/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/27/1995
Spill Record Last Update:	12/16/2005
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

COOPER PARK -NYCHA (Continued) **S106722316**

DER Facility ID: 204947
DEC Memo: Not reported
Remarks: TANK TEST FAILURE - COULD NOT MAINTAIN LEVEL

Material:
Site ID: 315998
Operable Unit ID: 1007841
Operable Unit: 01
Material ID: 373014
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 315998
Spill Tank Test: 1543579
Tank Number: 001
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

SPILLS:
Facility ID: 0408049
Facility Type: ER
DER Facility ID: 267879
Site ID: 332666
DEC Region: 2
Spill Date: 10/20/2004
Spill Number/Closed Date: 0408049 / 10/25/2004
Spill Cause: Abandoned Drums
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 10/20/2004
CID: 407
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False

COOPER PARK -NYCHA (Continued) **S106722316**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/20/2004
Spill Record Last Update:	10/25/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	2 PETTICOAT LA
Spiller City,St,Zip:	TOWN OF BRUNSWICK, NY
Spiller Company:	001
Contact Name:	ALEX LUGO
Contact Phone:	(718) 389-9230
DEC Memo:	Sangesland confirmed that Housing Authority drained and removed both the 2- 55 gal drums and the 275 gal tank from the site.Spill Closed
Remarks:	Caller states someone broke into their compound and left a 275 gallon tank and 2 55 gallon drums there. They pumped out the rest of the tank and the 2 drums, they are in process of cleaning the spilled oil out of the drum.

Material:

Site ID:	332666
Operable Unit ID:	1094885
Operable Unit:	01
Material ID:	575018
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AH118 **CON EDISON** **NY MANIFEST** **S117062794**
NNW **FO 214 WITHERS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.223 mi.
1180 ft. **Site 1 of 4 in cluster AH**

Relative:
Lower

Actual:
27 ft.

NY MANIFEST:

EPA ID:	NYP004551776
Country:	USA
Location Address 1:	FO 214 WITHERS ST
Location Address 2:	STRUCTURE 53397
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA

CON EDISON (Continued) **S117062794**

Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 06/03/2014
Trans1 Recv Date: 06/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/04/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004551776
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002424217GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

EPA ID: NYP004619029
Country: USA
Location Address 1: FO 214 WITHERS ST
Location Address 2: STRUCTURE 53397
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

CON EDISON (Continued) **S117062794**

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2014
Trans1 Recv Date:	08/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004619029
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002615659GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AF119 **GRAND AUTO REPAIRS CORP** **RCRA NonGen / NLR** **1001224339**
SE **916 GRAND ST** **FINDS** **NYR000055566**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.224 mi.
1185 ft. **Site 2 of 5 in cluster AF**

Relative:
Lower

Actual:
32 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GRAND AUTO REPAIRS CORP
Facility address:	916 GRAND ST BROOKLYN, NY 11211
EPA ID:	NYR000055566
Mailing address:	GRAND ST BROOKLYN, NY 11211
Contact:	EDGER SANCHEZ
Contact address:	GRAND ST BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	(718) 384-0705
Contact email:	Not reported

GRAND AUTO REPAIRS CORP (Continued) **1001224339**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EDGAR SANCHEZ
Owner/operator address: 916-930 GRAND ST
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: (718) 384-0705
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EDGAR SANCHEZ
Owner/operator address: 916-930 GRAND ST
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: (718) 384-0705
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GRAND AUTO REPAIRS CORP
Classification: Not a generator, verified

Date form received by agency: 05/29/1998
Site name: GRAND AUTO REPAIRS CORP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

GRAND AUTO REPAIRS CORP (Continued) **1001224339**

Violation Status: No violations found

FINDS:

Registry ID: 110004543646

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000055566
Country:	USA
Location Address 1:	916 GRAND ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	GRAND AUTO REPAIRS CORP
Contact:	SANTO NADAL
Address:	916 GRAND ST
City/State/Zip:	BROOKLYN, NY 11211
Country:	USA
Phone:	718-384-0705

Manifest:

Document ID:	NYG0586899
Manifest Status:	Not reported
Trans1 State ID:	PD1011NY
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/1998
Trans1 Recv Date:	06/19/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/22/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000055566
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

AF120 **EDR US Hist Auto Stat** **1015673865**
SE **916 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1185 ft. **Site 3 of 5 in cluster AF**

Relative:
Lower

Actual:
32 ft.

EDR Historical Auto Stations:

Name:	GRAND AUTO REPAIRS
Year:	1999
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2000
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2001
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2002
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2003
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2004
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2005
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2006
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2007
Address:	916 GRAND ST
Name:	GRAND AUTO REPAIRS
Year:	2008
Address:	916 GRAND ST

AF121 **SAFEGUARD SELF STORAGE** **NY UST** **U004107519**
SE **916 GRAND STREET** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1185 ft. **Site 4 of 5 in cluster AF**

Relative:
Lower

Actual:
32 ft.

UST:

Id/Status:	2-321257 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/31/2013
UTM X:	589769.22666000004

SAFEGUARD SELF STORAGE (Continued) **U004107519**

UTM Y: 4507385.4557999996
Site Type: Other

Affiliation Records:

Site Id: 14921
Affiliation Type: Mail Contact
Company Name: SAFEGUARD SELF STORAGE
Contact Type: Not reported
Contact Name: LAURA FAULKNER
Address1: 105 MAXESS ROAD
Address2: SUITE 125
City: MELVILLE
State: NY
Zip Code: 11747
Country Code: 001
Phone: (631) 539-0200 4
EMail: IFAULKNER@SAFEGUARDIT.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/11/2010

Site Id: 14921
Affiliation Type: On-Site Operator
Company Name: SAFEGUARD SELF STORAGE
Contact Type: Not reported
Contact Name: LAURA FAULKNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (631) 539-0200
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/11/2010

Site Id: 14921
Affiliation Type: Emergency Contact
Company Name: SAFEGUARD E. WILLIAMSBURG, LLC
Contact Type: Not reported
Contact Name: LAURA FAULKNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (631) 539-0200
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/11/2010

Site Id: 14921
Affiliation Type: Facility Owner
Company Name: SAFEGUARD E. WILLIAMSBURG, LLC

SAFEGUARD SELF STORAGE (Continued) **U004107519**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3350 PEACHTREE ROAD, SUITE 1700
Address2:	Not reported
City:	ATLANTA
State:	GA
Zip Code:	30326
Country Code:	001
Phone:	(404) 231-4000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	7/31/2008

Tank Info:

Tank Number:	001
Tank ID:	18407
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1100
Install Date:	12/01/1982
Date Tank Closed:	07/24/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	07/31/2008

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode

Tank Number:	002
Tank ID:	18408
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	12/01/1966

SAFEGUARD SELF STORAGE (Continued) **U004107519**

Date Tank Closed:	08/08/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	06/11/2010

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-321257
Program Type:	PBS
UTM X:	589769.22666000004
UTM Y:	4507385.4557999996
Expiration Date:	07/31/2013
Site Type:	Other

Affiliation Records:

Site Id:	14921
Affiliation Type:	Mail Contact
Company Name:	SAFEGUARD SELF STORAGE
Contact Type:	Not reported
Contact Name:	LAURA FAULKNER
Address1:	105 MAXESS ROAD
Address2:	SUITE 125
City:	MELVILLE
State:	NY
Zip Code:	11747
Country Code:	001
Phone:	(631) 539-0200 4
EMail:	IFAULKNER@SAFEGUARDIT.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/11/2010
Site Id:	14921

SAFEGUARD SELF STORAGE (Continued) **U004107519**

Affiliation Type:	On-Site Operator
Company Name:	SAFEGUARD SELF STORAGE
Contact Type:	Not reported
Contact Name:	LAURA FAULKNER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(631) 539-0200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/11/2010

Site Id:	14921
Affiliation Type:	Emergency Contact
Company Name:	SAFEGUARD E. WILLIAMSBURG, LLC
Contact Type:	Not reported
Contact Name:	LAURA FAULKNER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 539-0200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/11/2010

Site Id:	14921
Affiliation Type:	Facility Owner
Company Name:	SAFEGUARD E. WILLIAMSBURG, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3350 PEACHTREE ROAD, SUITE 1700
Address2:	Not reported
City:	ATLANTA
State:	GA
Zip Code:	30326
Country Code:	001
Phone:	(404) 231-4000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	7/31/2008

Tank Info:

Tank Number:	003
Tank Id:	216982
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

SAFEGUARD SELF STORAGE (Continued) **U004107519**

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2001
Capacity Gallons:	100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/24/2008
Register:	True
Modified By:	NRLOMBAR
Last Modified:	07/31/2008
Material Name:	Waste Oil/Used Oil

AI122 **KINGSLAND SERVICE STATION INC** **NY UST** **1000788767**
North **51 KINGSLAND AVENUE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1185 ft. **Site 1 of 3 in cluster AI**

Relative:
Lower

Actual:
31 ft.

UST:

Id/Status:	2-070270 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	09/15/2016
UTM X:	589538.70869999996
UTM Y:	4507957.3062500004
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	1546
Affiliation Type:	Mail Contact
Company Name:	KINGSLAND SERVICE STATION INC.
Contact Type:	Not reported
Contact Name:	JOHN PASSARELLA
Address1:	51 KINGSLAND AVENLUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 389-6133
EMail:	JONSUNOIL@ME.COM
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2/27/2012

Site Id:	1546

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Affiliation Type:	On-Site Operator
Company Name:	KINGSLAND SERVICE STATION INC
Contact Type:	Not reported
Contact Name:	DONATO PASSARELLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 389-6133
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/25/2011

Site Id:	1546
Affiliation Type:	Emergency Contact
Company Name:	JOHN PASSARELLA
Contact Type:	Not reported
Contact Name:	JOHN PASSERELLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 610-3088
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2/27/2012

Site Id:	1546
Affiliation Type:	Facility Owner
Company Name:	JOHN PASSARELLA
Contact Type:	PRES
Contact Name:	JOHN PASSARELLA
Address1:	159-59 78TH ST
Address2:	Not reported
City:	QUEENS
State:	NY
Zip Code:	11414
Country Code:	001
Phone:	(718) 389-6133
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2/27/2012

Tank Info:

Tank Number:	001
Tank ID:	29954
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number:	001
Tank ID:	70
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B02 - Tank External Protection - Original Sacrificial Anode

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	001-A
Tank ID:	71
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number:	002
Tank ID:	29955
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	72
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	002-A
Tank ID:	73
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number: 003
Tank ID: 29956
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 12/01/1966
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 74
Tank Status: In Service

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	003-A
Tank ID:	75
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number:	004
Tank ID:	29957
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number:	004
Tank ID:	2619
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number: 005
Tank ID: 2620
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 02/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number: 005
Tank ID: 29958
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 12/01/1966
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number: 006
Tank ID: 29959
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1971
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 2621
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1965
Date Tank Closed: 02/01/1990
Registered: True
Tank Location: Underground

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Affiliation Records:

Site Id: 5208
Affiliation Type: Facility Owner
Company Name: MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type: Not reported
Contact Name: Not reported
Address1: 3225 GALLOWS RD.; ENV.ENGINEER
Address2: Not reported
City: FAIRFAX
State: VA
Zip Code: 22037
Country Code: 001
Phone: (703) 849-5862
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/10/2010

Site Id: 5208
Affiliation Type: Mail Contact
Company Name: MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type: Not reported
Contact Name: Not reported
Address1: 3225 GALLOWS RD.; ENV.ENGINEER
Address2: Not reported
City: FAIRFAX
State: VA
Zip Code: 22037
Country Code: 001
Phone: (703) 849-5862
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/10/2010

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Site Id:	5208
Affiliation Type:	On-Site Operator
Company Name:	MOBIL S/S 17BJ6
Contact Type:	Not reported
Contact Name:	MOBIL S/S 17BJ6
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 234-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	5208
Affiliation Type:	Emergency Contact
Company Name:	MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type:	Not reported
Contact Name:	MOBIL S/S 17BJ6
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 234-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	29954
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number:	001
Tank ID:	70
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B02 - Tank External Protection - Original Sacrificial Anode
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	001-A
Tank ID:	71
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 29955
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 12/01/1966
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 72
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	002-A
Tank ID:	73
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number:	003
Tank ID:	29956
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number:	003
Tank ID:	74
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/27/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	BVCAMPBE
Last Modified:	02/27/2012

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	003-A
Tank ID:	75
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number:	004
Tank ID:	29957
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None

Tank Number: 004
Tank ID: 2619
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 02/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number: 005
Tank ID: 2620

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	02/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

Tank Number:	005
Tank ID:	29958
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1966
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

G00 - Tank Secondary Containment - None

Tank Number: 006
Tank ID: 29959
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1971
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 2621
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1965
Date Tank Closed: 02/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None

SPILLS:

Facility ID:	1111339
Facility Type:	ER
DER Facility ID:	119415
Site ID:	459232
DEC Region:	2
Spill Date:	12/20/2011
Spill Number/Closed Date:	1111339 / 6/5/2014
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	12/21/2011
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	12/21/2011
Spill Record Last Update:	6/6/2014
Spiller Name:	Not reported
Spiller Company:	GAS STATION
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MIKE HAGGERTY
Contact Phone:	Not reported
DEC Memo:	HaggertyDecember: Spill called in during an investigation of the property in regards to long term remediation Spill 89-08110. The distribution system had to be shutdown for the investigation because we drilled between the current tanks and the dispensers. During that process, Arcadis, ExxonMobil's consultant, noticed very small leaks coming from the diesel meters. ExxonMobil will be gw sampling in January 2012 and will collect soil samples beneath the meters.February 2012: results will be included in the SIR due 3/7/12April 2012 - diesel range organics detected in sample beneath one dispenser due to a leaking O-ring. Spoke with owner and attorney and advised them to obtain a consultant so we can move forward. This could be as simple as digging out all the soil beneath the dispenser and collecting an end-point sampleMay 2012 - Station owner has yet to hire consultant to deal with deisel contamination. EM still responsible for gasoline contamination. Regional attorney, John Urda, is seeking a Consent Order with EM as the gasoline contamination is

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

severeJune 2012 - Station owner, John Passerella, hired a consultant, HRP Associates, to investigate the diesel contamination.August 2012 - Owner's consultant's, HRP, has yet to do anything regardind the diesel leak. The PM at HRP is on a vacation week. I will speak to him in early Sept. December 2012 - The station owner's consultant, HRP, removed ~1 foot of soil beneath the 2 dispensers in question and collected end-point samples. Based on the results, the Spill cannot be closed at this time. Additional soil (deeper) must be removed and properly disposed of to reach clean soil and sampledMay 2013 - Spoke with station owner, John Passerella, and he is replacing his dispensers in the next month giving us the perfect time to excavate out the diesel contamination. The consultant will submit a new work plan within 45 daysJuly 2013 - spoke with station's current owner John Passerella and his attorney, Jean Warshaw. The project has dragged on too long (~20 months) and only a reasonably small excavation is required to close the Spill. The Dept gave them 3 months to have the remediation at the Site to be implemented by the end of OctoberOctober 2013 - Contamination from beneath one dispenser has been removed. Consultant moving on to the other dispenser. PM on-site 10/24/13November 2013 - The southern dispenser proved to be more contaminated with diesel. 3 drums of soil was removed via air knife and vac-unit. Using an industrial vacuum was much more practical considering the infra-structure below dispensers and a CAMP was not required. Contamination was observed spreading to the south therefore additional soil was removed in that direction and 2 end-point samples were collected (one bottom, one south side). Results from the lab were not clean. The contamination in both samples did not comply with CP-51: Table 2 and Table 3. Additional soil removal and end-point sampling requiredDecember 2013 - received clean end-point samples from the beneath the southern dispenser. Closure report due in January 2014April 2013 - Remedial Action Report being revisedJune 5, 2014 - Haggerty: RAR approved. Owner, John Passerella, backfilled the soil removed was clean pea graval (invoice in DecDocs) and concrete to the surface himself. Spill closed.

Remarks: Two (2) leaking diesel meters one on #2 & #4. Repairs will be conducted by Finley and Nichol. Confirmatory sample below dispensers to be collected. Owners name: John Passeralla - 347-610-3088

Material:

Site ID:	459232
Operable Unit ID:	1209322
Operable Unit:	01
Material ID:	2206726
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID: 8908110

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

Facility Type:	ER
DER Facility ID:	119415
Site ID:	139794
DEC Region:	2
Spill Date:	11/15/1989
Spill Number/Closed Date:	8908110 / Not Reported
Spill Cause:	Unknown
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	MJHAGGER
Referred To:	SUBSURFACE INVESTIGATION REPORT RECEIVED
Reported to Dept:	11/15/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	4
Date Entered In Computer:	11/24/1989
Spill Record Last Update:	6/26/2014
Spiller Name:	Not reported
Spiller Company:	exxonmobil
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SUN"12/10/2003 Reassigned from Tipple to Sun.11/7/05: Project reassigned from Sun to Andersen. Sent letter saying investigation was required by 1/2/06.12/6/05: Letter returned to sender, unclaimed. USPS wrote the address 159-59 78th street on the letter, instead of the address I sent it to: Donato Passerella 159 78th Street, Queens, NY 11414.1/23/06: Resent letter to 57 Kingsland Realty Corp., 57 Kingsland Avenue, Brooklyn, NY 11211 Attn: Hussein Mustafa, as per the current owner on Property Shark.2/3/06: An attorney for Mr. Mustafa called. She said that 51-57 Kingsland is owned by Mr. Mustafa and that 61-65 Kingsland is owned by Denato Passarella, and that the gas station is on 61-65 Kingsland. She will fax me a letter confirming this from the Department of Finance. Need to resend letter to Denato Passarella at 61-65 Kingsland. Changed address on spill report to 65 Kingsland Avenue. 2/9/06: Letter was returned. Resent letter to:Donato PassarellaKingsland Service Station51 Kingsland AvenueBrooklyn, NY 112112/13/06: Spoke to John Passarella (related to Denato Passarella) (718-389-6133). He said the correct address is 51 Kingsland Avenue. Changed address on spill report back to 51 kingsland. He said that Mobil owned the tanks at that time, but that he owns the property and the gas station. All old tanks were removed and new tanks installed in 1990. John Passarella will ask the old owner if they have and documentation of the tank closures.4/5/06: ExxonMobil contact: Melissa Tacchino, 908-730-3610, melissa.w.tacchino@exxonmobil.com. Called Melissa Tacchino and left

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

her a message. She called back and said that EM has never operated or owned this property.4/13/06: Spoke with John Passarella and he confirmed that Mobil owned the tanks in 1989 and were in charge of the tank excavation. 7/26/06: Refered to NYSDEC Legal Department.4/28/08 - Carlson: Spoke to John Passarella (718-389-6133). They received a letter from the legal division. They requested a 60 day extension to investigate this spill.12/23/09 - Carlson: Received investigation work plan from ExxonMobil, dated 12/7/09. Six borings/monitoring wells proposed. Issued approval letter. Ken DrakeExxonMobil Environmental ServicesU S Retail Remediation Project Manager297 Route 72 WSuite 35, #285Manahawkin, NJ 08050-2890kenneth.j.drake@exxonmobil.com5/25/2010 - Carlson: Performed site visit. They were hand clearing boreholes. Boreholes will be completed as wells starting tomorrow (three days expected).5/27/2010 - Carlson: Spoke to Joel Adrian. Product found in one of new wells. Product will be fingerprinted and tested for ethanol. If it is new product a new spill will be called in.9/9/2010 - Carlson: Received phone call. 2 ft of product present. Product will be ID'd again. 9/15/2010 - Carlson: Spill No. 00-02006 consolidated with 89-08110. Reveiwed Subsurface Investigation Report. Six monitoring wells installed. Product present in three wells. Product ID'd as weathered gasoline. Legal Division is negotiating a consent order. Case may be referred to central office.11/2/10 - EM did foil and complained they did not receive TTT reports. Station is delinquent since January, yet TTT may not be required. I can not tell from registration, which has omissions and questionable entries. Moses found registration deficiencies during recent PBS inspection and told Donato to correct them pronto. There is even uncertainty over the correct street address for the station (see the beginning of these notes). Moses would know if the station has a Veeder-Root doing LD on dw UST and dw pipes. (Breen)3/2/11 - Haggerty: assumed project management from Andre ObligadoMarch 2011 - Spoke with EM, they agreed to perform SI. Work Plan approvedApril 2011: Kleinfelder still working on Access Agreement with property ownerMay 2011 - Owner reluctant to sign Access Agreement. He called me because he states that shutting down his station for 6 days would do irreparable financial damage. I explained that if he doesn't allow EM on the property to perform the investigation, the state will be forced to. June 2011 - no resolution between the owner and EM has been reached concerning access to perform the workAugust 2011 - according to both the station owner, John Passeralla (347-610-3088) and EM, settlement for lost business is close and access should be granted soonNovember 2011 - Access Agreement signed between owner and EM. December 2011 - 6 new MW's installed on-site February 2012 - SIR for the on-site investigation due in mid March. Product encountered on-site. EM sent out Vac truck April 2012 - reviewed and commented on SIR for on-site well installation. The Deptartments position is that EM is responsible for the gasoline contamination in soil and groundwater and the current owner is responsible for the diesel contamination in the soil beneath the dispenser. John Urda is pursuing a CO with EM June 2012 - PM required twice monthly Dual-Phase extraction events until a RAP is submitted.August 2012 - EM fingerprinting report under review. December 2012 - A RAP was submitted which includes pilot testing to determine the best method. Also spoke with Julie de la Fuente at Kleinfelder. She states that EM is considering excavation as long as the owner would agree. They asked for 30 days to submit the CAP and the extension was approved 12/26/12May 2013 - ExxonMobil

KINGSLAND SERVICE STATION INC (Continued) **1000788767**

will not sign the Consent OrderDecember 2013 - While ExxonMobil is still not willing to sign a Consent Order, they did perform a SVE/AS pilot test this month. Also, they continue to perform Dual-Phase Extraction events twice monthlyApril 2014 - According to John Urda, our R2 Spills attorney, the Consent Order should have been signed and executed by now. The oversight/penalty cost of $30,000 as well as the Consent Order language are agreed upon. John will contact PM when he hears something.June 2014 - ExxonMobil executed Consent Order 6/3/14

Remarks: DURING EXCAVATION OF TANK CONTAMINATED SOIL DISCOVERED IN PITS - PUMP-ING CONTAMINATED SOIL & WATER OUT OF PIT INTO STREETS - DEP RESPONDED & FOUND ONLY CONTAMINATED SOIL & SLIGHT SHEEN IN TRENCH.

Material:

Site ID:	139794
Operable Unit ID:	935580
Operable Unit:	01
Material ID:	444871
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	139794
Spill Tank Test:	1536405
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

AI123 **MOBIL OIL CO** **RCRA NonGen / NLR** **1000253431**
North **51 KINGSLAND AVE** **NY MANIFEST** **NYD986890556**
1/8-1/4 **BROOKLYN, NY 11227**
0.224 mi.
1185 ft. **Site 2 of 3 in cluster AI**

Relative:
Lower

Actual:
31 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MOBIL OIL CO
Facility address:	51 KINGSLAND AVE BROOKLYN, NY 11227
EPA ID:	NYD986890556
Mailing address:	DOUGHTY BLVD INWOOD, NY 11696
Contact:	Not reported
Contact address:	DOUGHTY BLVD INWOOD, NY 11696
Contact country:	US

MOBIL OIL CO (Continued) **1000253431**

Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MOBIL OIL CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MOBIL OIL CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MOBIL OIL CO
Classification: Not a generator, verified

Date form received by agency: 04/14/1995
Site name: MOBIL OIL CO
Classification: Not a generator, verified

Date form received by agency: 02/27/1990
Site name: MOBIL OIL CO
Classification: Small Quantity Generator

MOBIL OIL CO (Continued) **1000253431**

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986890556
Country: USA
Location Address 1: 51 KINGSLAND AVE
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: 1521

Mailing Info:
Name: MOBIL OIL CO SERVICE STATION
Contact: MOBIL OIL CO SERVICE STATION
Address: 464 DOUGHTY BLVD
City/State/Zip: INWOOD, NY 11696
Country: USA
Phone: 516-371-1527

Manifest:

Document ID: NYA8317989
Manifest Status: Completed copy
Trans1 State ID: MK 8837
Trans2 State ID: Not reported
Generator Ship Date: 03/08/1990
Trans1 Recv Date: 03/08/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 03/08/1990
Part A Recv Date: 03/29/1990
Part B Recv Date: 03/29/1990
Generator EPA ID: NYD986890556
Trans1 EPA ID: NYD006801245
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

AI124 **EDR US Hist Auto Stat** **1015530176**
North **51 KINGSLAND AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1185 ft. **Site 3 of 3 in cluster AI**

Relative:
Lower

Actual:
31 ft.

EDR Historical Auto Stations:
Name: KINGSLAND SVCE STATION INCORPORATED
Year: 1999
Address: 51 KINGSLAND AVE

(Continued) **1015530176**

Name: KINGSLAND SVCE STATION INCORPORATED
Year: 2000
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2001
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2002
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2003
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STA INC
Year: 2005
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STA INC
Year: 2006
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2007
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2008
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STATION INC
Year: 2009
Address: 51 KINGSLAND AVE

Name: KINGSLAND SERVICE STA INC
Year: 2010
Address: 51 KINGSLAND AVE

AH125 **BUONOMO/GY LEE CLEANERS** **NY DRYCLEANERS** **S106435460**
NNW **448 HUMBOLDT AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.227 mi.
1201 ft. **Site 2 of 4 in cluster AH**

Relative:
Lower

Actual:
27 ft.

DRYCLEANERS:
Facility ID: 2-6101-00828
Phone Number: 718-389-7936
Region: Not reported
Registration Effective Date: 3/12/2002 11:44:16:5
Inspection Date: 07MAY9
Install Date: 91/00
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

AH126 **EVADA CLEANERS OF NY** **RCRA-CESQG** **1000318342**
NNW **448 HUMBOLDT ST** **FINDS** **NYD004225660**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.227 mi. **US AIRS**
1201 ft. **Site 3 of 4 in cluster AH**

Relative:
Lower

Actual:
27 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	BUONOMO CLEANERS INC
Facility address:	448 HUMBOLDT ST BROOKLYN, NY 11211
EPA ID:	NYD004225660
Mailing address:	HUMBOLDT ST BROOKLYN, NY 11211
Contact:	Not reported
Contact address:	HUMBOLDT ST BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BUONOMO CLEANERS
Owner/operator address:	448 HUMBOLT ST BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	(718) 389-7936
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BUONOMO CLEANERS
Owner/operator address:	448 HUMBOLT ST BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	(718) 389-7936
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

EVADA CLEANERS OF NY (Continued) **1000318342**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BUONOMO CLEANERS INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/30/1995
Site name: BUONOMO CLEANERS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 01/14/1993
Site name: BUONOMO CLEANERS INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110001610524

Environmental Interest/Information System

EVADA CLEANERS OF NY (Continued) **1000318342**

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD004225660
Country:	USA
Location Address 1:	448 HUMBOLDT ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	BUONOMO CLNRS
Contact:	BUONOMO CLNRS
Address:	448 HUMBOLDT STREET
City/State/Zip:	BROOKLYN, NY 11211
Country:	USA
Phone:	718-389-7936

Manifest:

Document ID:	NYC4441252
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	1FS147OK
Generator Ship Date:	03/27/1997
Trans1 Recv Date:	03/27/1997
Trans2 Recv Date:	04/03/1997
TSD Site Recv Date:	04/04/1997
Part A Recv Date:	04/08/1997
Part B Recv Date:	04/23/1997
Generator EPA ID:	NYD004225660

EVADA CLEANERS OF NY (Continued) **1000318342**

Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4754250
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	AM6252NY
Trans2 State ID:	1GT281OK
Generator Ship Date:	07/17/1997
Trans1 Recv Date:	07/17/1997
Trans2 Recv Date:	07/22/1997
TSD Site Recv Date:	07/23/1997
Part A Recv Date:	08/04/1997
Part B Recv Date:	08/14/1997
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4412406
Manifest Status:	Completed copy
Trans1 State ID:	NYGF2859
Trans2 State ID:	M0001
Generator Ship Date:	01/03/1997
Trans1 Recv Date:	01/03/1997
Trans2 Recv Date:	01/08/1997
TSD Site Recv Date:	01/09/1997
Part A Recv Date:	01/22/1997
Part B Recv Date:	01/24/1997
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.

EVADA CLEANERS OF NY (Continued) **1000318342**

Specific Gravity: 100
Year: 1997

Document ID: NYC4941808
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NYGF2859
Trans2 State ID: Not reported
Generator Ship Date: 12/30/1997
Trans1 Recv Date: 12/30/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 01/09/1998
Part A Recv Date: 01/20/1998
Part B Recv Date: 02/09/1998
Generator EPA ID: NYD004225660
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

Document ID: NYC4854824
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NYGF2859
Trans2 State ID: MO001
Generator Ship Date: 09/10/1997
Trans1 Recv Date: 09/10/1997
Trans2 Recv Date: 09/16/1997
TSD Site Recv Date: 09/17/1997
Part A Recv Date: 09/18/1997
Part B Recv Date: 10/17/1997
Generator EPA ID: NYD004225660
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: MOD095038998
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

Document ID: NYC4699708
Manifest Status: Completed copy
Trans1 State ID: NYGF2859
Trans2 State ID: HQ42129OR
Generator Ship Date: 04/22/1997

EVADA CLEANERS OF NY (Continued) **1000318342**

Trans1 Recv Date:	04/22/1997
Trans2 Recv Date:	04/28/1997
TSD Site Recv Date:	04/29/1997
Part A Recv Date:	05/02/1997
Part B Recv Date:	05/15/1997
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC4448147
Manifest Status:	Completed copy
Trans1 State ID:	NYGF2859
Trans2 State ID:	483341
Generator Ship Date:	01/30/1997
Trans1 Recv Date:	01/30/1997
Trans2 Recv Date:	02/04/1997
TSD Site Recv Date:	02/05/1997
Part A Recv Date:	02/12/1997
Part B Recv Date:	02/21/1997
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYC3668466
Manifest Status:	Completed copy
Trans1 State ID:	GF2859NY
Trans2 State ID:	5068BGOK
Generator Ship Date:	01/10/1996
Trans1 Recv Date:	01/10/1996
Trans2 Recv Date:	01/12/1996
TSD Site Recv Date:	01/15/1996
Part A Recv Date:	01/22/1996
Part B Recv Date:	02/01/1996
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364

EVADA CLEANERS OF NY (Continued) **1000318342**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4393800
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	HQ02665OR
Generator Ship Date:	12/04/1996
Trans1 Recv Date:	12/04/1996
Trans2 Recv Date:	12/09/1996
TSD Site Recv Date:	12/10/1996
Part A Recv Date:	12/20/1996
Part B Recv Date:	01/02/1997
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC3941010
Manifest Status:	Completed copy
Trans1 State ID:	GF2859NY
Trans2 State ID:	4190AZOK
Generator Ship Date:	03/25/1996
Trans1 Recv Date:	03/25/1996
Trans2 Recv Date:	03/28/1996
TSD Site Recv Date:	03/29/1996
Part A Recv Date:	04/02/1996
Part B Recv Date:	04/11/1996
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

EVADA CLEANERS OF NY (Continued) **1000318342**

Document ID:	NYC4067638
Manifest Status:	Completed copy
Trans1 State ID:	GF2859NY
Trans2 State ID:	AR0041204
Generator Ship Date:	04/24/1996
Trans1 Recv Date:	04/24/1996
Trans2 Recv Date:	04/26/1996
TSD Site Recv Date:	04/27/1996
Part A Recv Date:	05/02/1996
Part B Recv Date:	05/16/1996
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4224778
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	2828BB
Generator Ship Date:	08/14/1996
Trans1 Recv Date:	08/14/1996
Trans2 Recv Date:	08/20/1996
TSD Site Recv Date:	08/21/1996
Part A Recv Date:	08/29/1996
Part B Recv Date:	09/13/1996
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ARD981908551
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC4299592
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGF2859
Trans2 State ID:	OK1645BC
Generator Ship Date:	10/08/1996
Trans1 Recv Date:	10/08/1996
Trans2 Recv Date:	10/11/1996
TSD Site Recv Date:	10/13/1996
Part A Recv Date:	10/22/1996

EVADA CLEANERS OF NY (Continued) **1000318342**

Part B Recv Date:	11/04/1996
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYC3785758
Manifest Status:	Completed copy
Trans1 State ID:	AM6252NY
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/1995
Trans1 Recv Date:	12/05/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/05/1995
Part A Recv Date:	12/18/1995
Part B Recv Date:	12/15/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3560567
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY
Trans2 State ID:	Not reported
Generator Ship Date:	06/22/1995
Trans1 Recv Date:	06/22/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/22/1995
Part A Recv Date:	06/30/1995
Part B Recv Date:	06/30/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001

EVADA CLEANERS OF NY (Continued) **1000318342**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3840592
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY
Trans2 State ID:	Not reported
Generator Ship Date:	04/26/1995
Trans1 Recv Date:	04/26/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/26/1995
Part A Recv Date:	05/04/1995
Part B Recv Date:	05/05/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3526457
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/1995
Trans1 Recv Date:	03/30/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/30/1995
Part A Recv Date:	04/07/1995
Part B Recv Date:	04/06/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3885434
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY

EVADA CLEANERS OF NY (Continued) **1000318342**

Trans2 State ID:	Not reported
Generator Ship Date:	05/24/1995
Trans1 Recv Date:	05/24/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/24/1995
Part A Recv Date:	06/02/1995
Part B Recv Date:	06/06/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3493091
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY
Trans2 State ID:	Not reported
Generator Ship Date:	03/03/1995
Trans1 Recv Date:	03/03/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/03/1995
Part A Recv Date:	03/09/1995
Part B Recv Date:	03/14/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC3453570
Manifest Status:	Completed copy
Trans1 State ID:	JE4550NY
Trans2 State ID:	Not reported
Generator Ship Date:	02/01/1995
Trans1 Recv Date:	02/01/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/01/1995
Part A Recv Date:	02/09/1995
Part B Recv Date:	02/10/1995
Generator EPA ID:	NYD004225660
Trans1 EPA ID:	ILD984908202

EVADA CLEANERS OF NY (Continued) **1000318342**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110001610524
Plant name:	EVADA CLEANERS OF NY
Plant address:	448 HUMBOLDT STREET BROOKLYN, NY 112112418
County:	KINGS
Region code:	02
Dunn & Bradst #:	Not reported
Air quality cntrl region:	043
Sic code:	7216
Sic code desc:	DRYCLEANING PLANTS, EXCEPT RUG
North Am. industrial classf:	812320
NAIC code description:	Drycleaning and Laundry Services (except Coin-Operated)
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL EMISSIONS ARE BELOW ALL APPLICABLE MAJOR SOURCE THRESHOLDS IF AND ONLY IF THE SOURCE COMPLIES WITH FEDERALLY ENFORCEABLE REGULATIONS OR LIMITATIONS.
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

AH127 **EDR US Hist Cleaners** **1015062522**
NNW **448 HUMBOLDT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.227 mi.
1201 ft. **Site 4 of 4 in cluster AH**

Relative:
Lower

Actual:
27 ft.

EDR Historical Cleaners:

Name:	BUONOMO CLEANERS
Year:	2001
Address:	448 HUMBOLDT ST
Name:	BUONOMO CLEANERS
Year:	2002
Address:	448 HUMBOLDT ST
Name:	BUONOMO CLEANERS
Year:	2005
Address:	448 HUMBOLDT ST
Name:	BUONOMO CLEANERS
Year:	2006
Address:	448 HUMBOLDT ST

(Continued) **1015062522**

Name: BUONOMO CLEANERS
Year: 2007
Address: 448 HUMBOLDT ST

Name: BUONOMO CLEANERS
Year: 2010
Address: 448 HUMBOLDT ST

Name: BUONOMO CLEANERS
Year: 2011
Address: 448 HUMBOLDT ST

AJ128 **EDR US Hist Auto Stat** **1015686659**
East **972 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.229 mi.
1208 ft. **Site 1 of 2 in cluster AJ**

Relative:
Lower

Actual:
22 ft.

EDR Historical Auto Stations:

Name: HRATCH AUTO BODY
Year: 1999
Address: 972 METROPOLITAN AVE

Name: HRATCH AUTO BODY
Year: 2000
Address: 972 METROPOLITAN AVE

Name: HRATCH AUTO BODY
Year: 2001
Address: 972 METROPOLITAN AVE

Name: HRATCH AUTO BODY
Year: 2002
Address: 972 METROPOLITAN AVE

AK129 **CON EDISON SERVICE BOX: 12564** **RCRA NonGen / NLR** **1016973389**
NW **161 JACKSON ST** **NY MANIFEST** **NYP004471900**
1/8-1/4 **BROOKLYN, NY 11211**
0.229 mi.
1209 ft. **Site 1 of 3 in cluster AK**

Relative:
Lower

Actual:
26 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/19/2014
Facility name: CON EDISON SERVICE BOX: 12564
Facility address: 161 JACKSON ST
BROOKLYN, NY 11211
EPA ID: NYP004471900
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02

CON EDISON SERVICE BOX: 12564 (Continued) **1016973389**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/19/2014
Site name: CON EDISON SERVICE BOX: 12564
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004471900
Country: USA
Location Address 1: FRONT OF 161 JACKSON ST
Location Address 2: SB12564
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/19/2014
Trans1 Recv Date: 03/19/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/20/2014
Part A Recv Date: Not reported

CON EDISON SERVICE BOX: 12564 (Continued) **1016973389**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004471900
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	120
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002359189GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AF130 **J&G AUTO SHOP** **NY UST** **U004078902**
ESE **921 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.230 mi.
1217 ft. **Site 5 of 5 in cluster AF**

Relative:
Lower

Actual:
31 ft.

UST:

Id/Status:	2-610457 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/26/2017
UTM X:	589750.95726000005
UTM Y:	4507418.3007199997
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	376597
Affiliation Type:	Facility Owner
Company Name:	921 GRAND LLC
Contact Type:	AGENT
Contact Name:	ULRIC GLOUDON
Address1:	210 KINGSLAND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 486-0176
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS

J&G AUTO SHOP (Continued) **U004078902**

Date Last Modified:	8/20/2014
Site Id:	376597
Affiliation Type:	Mail Contact
Company Name:	UNFLAT AND ASSOCIATES INC.
Contact Type:	Not reported
Contact Name:	ULRIC GLOUDON
Address1:	451 GRANDVIEW AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 386-6100
EMail:	UNFLAT.ASSOCIATES@VERIZON.NET
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/20/2014
Site Id:	376597
Affiliation Type:	On-Site Operator
Company Name:	BARONA & MILLAN INC.
Contact Type:	Not reported
Contact Name:	MIGUEL MILLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 218-7316
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/25/2009
Site Id:	376597
Affiliation Type:	Emergency Contact
Company Name:	921 GRAND LLC
Contact Type:	Not reported
Contact Name:	MRS. RAMA MUKHOPADHYAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 486-0176
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/20/2014

Tank Info:

Tank Number:	1
Tank ID:	215585

J&G AUTO SHOP (Continued) **U004078902**

Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	250
Install Date:	01/01/1985
Date Tank Closed:	06/06/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	08/21/2014

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

AC131 **CON EDISON** **NY MANIFEST** **S117315523**
WSW **FO 133 DEVOE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.231 mi.
1218 ft. **Site 2 of 2 in cluster AC**

Relative:
Higher

Actual:
37 ft.

NY MANIFEST:

EPA ID:	NYP004626990
Country:	USA
Location Address 1:	FO 133 DEVOE ST
Location Address 2:	STRUCTURE 12351
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

CON EDISON (Continued) **S117315523**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/13/2014
Trans1 Recv Date:	08/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004626990
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002616132GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AL132 **CON EDISON** **NY MANIFEST** **S117319223**
NE **FRONT OF 137 MASPETH AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.231 mi.
1221 ft. **Site 1 of 2 in cluster AL**

Relative:
Lower

Actual:
24 ft.

NY MANIFEST:

EPA ID:	NYP004669115
Country:	USA
Location Address 1:	FRONT OF 137 MASPETH AV
Location Address 2:	SB78543
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA

CON EDISON (Continued) **S117319223**

Phone: Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2014
Trans1 Recv Date:	09/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004669115
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002615910GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM133 **CON EDISON** **NY MANIFEST** **S117066436**
SW **277 GRAHAM AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.233 mi.
1230 ft. **Site 1 of 2 in cluster AM**

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:

EPA ID:	NYP004590865
Country:	USA
Location Address 1:	277 GRAHAM AV
Location Address 2:	SB12950
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11206
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON

CON EDISON (Continued) **S117066436**

Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/09/2014
Trans1 Recv Date: 07/09/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004590865
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002503827GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

---

134 **231 MAUJER STREET** **NY AST U003394626**
South **231 MAUJER STREET** **NY HIST AST N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.235 mi.
1243 ft.

Relative:
Higher

Actual:
48 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-466727
Program Type: PBS
UTM X: 589494.67697999999
UTM Y: 4507198.3569799997

231 MAUJER STREET (Continued) **U003394626**

Expiration Date: 10/30/2008
Site Type: Other

Affiliation Records:
Site Id: 20268
Affiliation Type: Facility Owner
Company Name: 231 MAUJER STREET HDFC
Contact Type: Not reported
Contact Name: Not reported
Address1: 75 MAIDEN LANE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 806-8565
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20268
Affiliation Type: Mail Contact
Company Name: NYC HOUSING PRESERV & DEVEL
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 231 MAUJER STREET
Address2: 231 MAUJER STREET
City: BROOKLYN
State: NY
Zip Code: 11206
Country Code: 001
Phone: (212) 806-8565
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20268
Affiliation Type: On-Site Operator
Company Name: 231 MAUJER STREET
Contact Type: Not reported
Contact Name: NYC HOUSING PRESERV & DEVEL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 806-8565
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20268
Affiliation Type: Emergency Contact
Company Name: 231 MAUJER STREET HDFC

231 MAUJER STREET (Continued) **U003394626**

Contact Type:	Not reported
Contact Name:	WANDER GONZALEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 328-0230
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	36914
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-466727
SWIS Code:	6101
Operator:	NYC HOUSING PRESERV & DEVEL
Facility Phone:	(212) 806-8565
Facility Addr2:	231 MAUJER STREET
Facility Type:	Not reported
Emergency:	WANDER GONZALEZ
Emergency Tel:	(212) 722-3931

231 MAUJER STREET (Continued) **U003394626**

Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	231 MAUJER STREET HDFC
Owner Address:	75 MAIDEN LANE
Owner City,St,Zip:	NEW YORK, NY 10038
Federal ID:	Not reported
Owner Tel:	(212) 806-8565
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Contact:	SUPER FACILITY MANAGER
Mailing Name:	NYC HOUSING PRESERV & DEVEL
Mailing Address:	231 MAUJER STREET
Mailing Address 2:	231 MAUJER STREET
Mailing City,St,Zip:	BROOKLYN, NY 11206
Mailing Telephone:	(212) 806-8565
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	05/30/2000
Expiration:	10/30/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported

231 MAUJER STREET (Continued) **U003394626**

Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AK135 **EDR US Hist Auto Stat** **1015465483**
NW **395 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.237 mi.
1253 ft. **Site 2 of 3 in cluster AK**

Relative:
Lower

Actual:
26 ft.

EDR Historical Auto Stations:

Name:	SOBE AUTO REPAIR CORP
Year:	2003
Address:	395 GRAHAM AVE

AK136 **EDR US Hist Cleaners** **1015054382**
NW **400 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.238 mi.
1256 ft. **Site 3 of 3 in cluster AK**

Relative:
Lower

Actual:
26 ft.

EDR Historical Cleaners:

Name:	BUBBLES SPA LAUNDROMAT
Year:	1999
Address:	400 GRAHAM AVE
Name:	BUBBLES SPA LAUNDROMAT
Year:	2000
Address:	400 GRAHAM AVE
Name:	BUBBLES SPA LAUNDROMAT
Year:	2001
Address:	400 GRAHAM AVE
Name:	BUBBLES SPA LAUNDROMAT
Year:	2002
Address:	400 GRAHAM AVE
Name:	BUBBLE LAUNDROMAT
Year:	2004
Address:	400 GRAHAM AVE
Name:	BUBBLE LAUNDROMAT
Year:	2005
Address:	400 GRAHAM AVE
Name:	BUBBLE LAUNDROMAT
Year:	2006
Address:	400 GRAHAM AVE
Name:	BUBBLE LAUNDROMAT
Year:	2007

(Continued) **1015054382**

Address: 400 GRAHAM AVE

Name: BUBBLE LAUNDROMAT
Year: 2008
Address: 400 GRAHAM AVE

Name: BUBBLE LAUNDROMAT
Year: 2009
Address: 400 GRAHAM AVE

Name: BUBBLE LAUNDROMAT
Year: 2010
Address: 400 GRAHAM AVE

Name: BUBBLE LAUNDROMAT
Year: 2011
Address: 400 GRAHAM AVE

Name: BUBBLE LAUNDROMAT
Year: 2012
Address: 400 GRAHAM AVE

137
WNW
1/8-1/4
0.239 mi.
1261 ft.

145 SKILLMAN AVE
BROOKLYN, NY 11211

EDR US Hist Auto Stat **1015230027**
N/A

Relative:
Lower

Actual:
29 ft.

EDR Historical Auto Stations:
Name: J & G AUTO REPR
Year: 2004
Address: 145 SKILLMAN AVE

138
NE
1/8-1/4
0.239 mi.
1263 ft.

NYCHA - COOPER PARK HOUSES
40 DEBEVOISE AVE
BROOKLYN, NY 11211

RCRA NonGen / NLR **1000238813**
NY MANIFEST **NYD986887594**

Relative:
Lower

Actual:
29 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYCHA - COOPER PARK HOUSES
Facility address: 40 DEBEVOISE AVE
BROOKLYN, NY 11211
EPA ID: NYD986887594
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: FRANK OCELLO
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: (212) 306-3229
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

NYCHA - COOPER PARK HOUSES (Continued) **1000238813**

Owner/Operator Summary:
Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCHA - COOPER PARK HOUSES
Classification: Not a generator, verified

Date form received by agency: 08/12/1999
Site name: NYCHA - COOPER PARK HOUSES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

. Waste code: X001
. Waste name: WASTE OILS

NYCHA - COOPER PARK HOUSES (Continued) **1000238813**

Date form received by agency: 04/03/1998
Site name: NYCHA - COOPER PARK HOUSES
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986887594
Country: USA
Location Address 1: 40 DEBEUIOSE ST-COOPER HOUSING
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: NYC HOUSING AUTH
Contact: RAY VALEZ
Address: 250 BROADWAY
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-306-3142

Manifest:

Document ID: NJA2987388
Manifest Status: Not reported
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 08/20/1999
Trans1 Recv Date: 08/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/23/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986887594
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00085
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CW - Wooden boxes
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 1999

AJ139
East
1/8-1/4
0.239 mi.
1263 ft.

980 METROPOLITAN AVE
BROOKLYN, NY 11211

Site 2 of 2 in cluster AJ

EDR US Hist Auto Stat **1015687929**
N/A

Relative:
Lower

Actual:
21 ft.

EDR Historical Auto Stations:

Name:	F & B TRUCK REPAIR & MAINTENANCE INC
Year:	2005
Address:	980 METROPOLITAN AVE
Name:	F & B TRUCK REPAIR & MAINTENANCE
Year:	2006
Address:	980 METROPOLITAN AVE
Name:	F & B TRUCK REPAIR & MAINTENANCE
Year:	2008
Address:	980 METROPOLITAN AVE
Name:	F & B TRUCK REPAIR & MAINTENANCE
Year:	2009
Address:	980 METROPOLITAN AVE

140
WSW
1/8-1/4
0.240 mi.
1268 ft.

CON EDISON SERVICE BOX: 12351
129 DEVOE
BROOKLYN, NY 11211

RCRA NonGen / NLR **1016971483**
NY MANIFEST **NYP004452249**

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/26/2014
Facility name:	CON EDISON SERVICE BOX: 12351
Facility address:	129 DEVOE BROOKLYN, NY 11211
EPA ID:	NYP004452249
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON SERVICE BOX: 12351 (Continued) **1016971483**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/26/2014
Site name: CON EDISON SERVICE BOX: 12351
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004452249
Country: USA
Location Address 1: FRONT OF 129 DEVOE ST
Location Address 2: SB12351
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2014
Trans1 Recv Date: 02/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/26/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004452249
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002359013GBF
Import Ind: N

CON EDISON SERVICE BOX: 12351 (Continued) **1016971483**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AL141 **CON EDISON SERVICE BOX: 56334** **RCRA NonGen / NLR** **1016454611**
ENE **143 MASPETH AVE** **FINDS** **NYP004330213**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.244 mi.
1287 ft. **Site 2 of 2 in cluster AL**

Relative:
Lower

Actual:
22 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/16/2013
Facility name:	CON EDISON SERVICE BOX: 56334
Facility address:	143 MASPETH AVE BROOKLYN, NY 11211
EPA ID:	NYP004330213
Mailing address:	VING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/16/2013
Site name:	CON EDISON SERVICE BOX: 56334
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 56334 (Continued) **1016454611**

Violation Status: No violations found

FINDS:

Registry ID: 110056498320

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYP004330213
Country:	USA
Location Address 1:	143 MASPETH AVE
Location Address 2:	SB #56334
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2013
Trans1 Recv Date:	07/16/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004330213
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013

CON EDISON SERVICE BOX: 56334 (Continued) **1016454611**

Manifest Tracking Num:	001676098GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AN142 **WILLIAMSBURG** **NY UST U002259565**
South **200 MAUJER STREET** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.244 mi.
1287 ft. **Site 1 of 2 in cluster AN**

Relative:
Higher

Actual:
45 ft.

UST:

Id/Status:	2-602348 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	08/04/2005
UTM X:	589430.34738000005
UTM Y:	4507190.8085599998
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24305
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/28/2015

Site Id:	24305
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	LUIS PONCE-REMEDIA. UNIT
Address1:	23-02 49TH AVENUE
Address2:	9TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001

WILLIAMSBURG (Continued) **U002259565**

Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24305
Affiliation Type:	On-Site Operator
Company Name:	WILLIAMSBURG
Contact Type:	Not reported
Contact Name:	FUEL OIL REM. COORD.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ajsigona
Date Last Modified:	4/15/2004

Site Id:	24305
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPARTMENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 289-3940
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ajsigona
Date Last Modified:	4/1/2004

Tank Info:

Tank Number:	001
Tank ID:	49858
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7000
Install Date:	09/01/1995
Date Tank Closed:	09/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	NN
Date Test:	Not reported

WILLIAMSBURG (Continued) **U002259565**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-602348
Program Type: PBS
UTM X: 589430.34738000005
UTM Y: 4507190.8085599998
Expiration Date: 08/04/2005
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 24305
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: \\
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/28/2015

Site Id: 24305
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: LUIS PONCE-REMEDIA. UNIT
Address1: 23-02 49TH AVENUE
Address2: 9TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported

WILLIAMSBURG (Continued) **U002259565**

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24305
Affiliation Type: On-Site Operator
Company Name: WILLIAMSBURG
Contact Type: Not reported
Contact Name: FUEL OIL REM. COORD.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: ajsigona
Date Last Modified: 4/15/2004

Site Id: 24305
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICE DEPARTMENT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 289-3940
EMail: Not reported
Fax Number: Not reported
Modified By: ajsigona
Date Last Modified: 4/1/2004

Tank Info:

Tank Number: 002
Tank Id: 49859
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 6

WILLIAMSBURG (Continued) **U002259565**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	09/01/1995
Capacity Gallons:	7000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Empty

AO143 **GCS SERVICE INC.** **NY UST** **U003065911**
ESE **932 GRAND STREET** **NY HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.245 mi.
1291 ft. **Site 1 of 2 in cluster AO**

Relative:
Lower

Actual:
30 ft.

UST:

Id/Status:	2-602621 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	02/14/2001
UTM X:	589818.28500000003
UTM Y:	4507406.4918400003
Site Type:	Other

Affiliation Records:

Site Id:	24578
Affiliation Type:	Facility Owner
Company Name:	RAYMUR REALTY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1504 SHEEPSHEAD BAY ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235
Country Code:	001
Phone:	(718) 891-6943
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24578
Affiliation Type:	Mail Contact
Company Name:	RAYMUR REALTY
Contact Type:	Not reported
Contact Name:	RAYMOND FEIDEN
Address1:	1504 SHEEPSHEAD BAY ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235

GCS SERVICE INC. (Continued) **U003065911**

Country Code:	001
Phone:	(718) 891-6943
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24578
Affiliation Type:	On-Site Operator
Company Name:	GCS SERVICE INC.
Contact Type:	Not reported
Contact Name:	HOWARD BAKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 891-6943
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24578
Affiliation Type:	Emergency Contact
Company Name:	RAYMUR REALTY
Contact Type:	Not reported
Contact Name:	HOWARD BAKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 891-6943
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	50742
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	02/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN

GCS SERVICE INC. (Continued) **U003065911**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-602621
SPDES Number: Not reported
Emergency Contact: HOWARD BAKER
Emergency Telephone: (718) 891-6943
Operator: HOWARD BAKER
Operator Telephone: (718) 891-6943
Owner Name: RAYMUR REALTY
Owner Address: 1504 SHEEPSHEAD BAY ROAD
Owner City,St,Zip: BROOKLYN, NY 11235
Owner Telephone: (718) 891-6943
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: RAYMUR REALTY
Mailing Address: 1504 SHEEPSHEAD BAY ROAD
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11235
Mailing Contact: RAYMOND FEIDEN
Mailing Telephone: (718) 891-6943
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 6101
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: Not reported
Expiration Date: 02/14/2001
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: 0
Dead Letter: False

GCS SERVICE INC. (Continued) **U003065911**

CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	02/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AO144 **CON EDISON** **NY MANIFEST** **S117061580**
ESE **933 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.246 mi.
1300 ft. **Site 2 of 2 in cluster AO**

Relative:
Lower

Actual:
30 ft.

NY MANIFEST:

EPA ID:	NYP004538948
Country:	USA
Location Address 1:	933 GRAND ST
Location Address 2:	SB 14137
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11211
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

CON EDISON (Continued) **S117061580**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/2014
Trans1 Recv Date:	05/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004538948
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	002423468GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AN145 **CON EDISON - MANHOLE 180** **RCRA-LQG** **1016961669**
SSW **276 HUMBOLDT ST** **NY MANIFEST** **NYP004345302**
1/8-1/4 **BROOKLYN, NY 11206**
0.247 mi.
1306 ft. **Site 2 of 2 in cluster AN**

Relative:
Higher

Actual:
43 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 180
Facility address:	276 HUMBOLDT ST BROOKLYN, NY 11206
EPA ID:	NYP004345302
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any

CON EDISON - MANHOLE 180 (Continued) **1016961669**

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/13/2013
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/13/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 09/13/2013
Site name: CON EDISON MANHOLE: 180

CON EDISON - MANHOLE 180 (Continued) **1016961669**

Classification: Not a generator, verified

Date form received by agency: 08/13/2013
Site name: CON EDISON MANHOLE: 180
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004345302
Country: USA
Location Address 1: 276 HUMBOLDT ST
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11206
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/13/2013
Trans1 Recv Date: 08/13/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/15/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004345302
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 002219356GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

CON EDISON - MANHOLE 180 (Continued) **1016961669**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AM146 **LOT 43,TAXBLOCK 2783** **NY MANIFEST** **S109942587**
SW **725 GRAND STREET** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.248 mi.
1311 ft. **Site 2 of 2 in cluster AM**

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:
EPA ID: NYP004582771
Country: USA
Location Address 1: 725 GRAND ST
Location Address 2: SB19920
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/01/2014
Trans1 Recv Date: 07/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/14/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004582771
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002424454GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

LOT 43,TAXBLOCK 2783 (Continued) **S109942587**

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

EPA ID: NYP004704888
Country: USA
Location Address 1: 725 GRAND ST
Location Address 2: SB 73900
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 12/10/2014
Trans1 Recv Date: 12/10/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/16/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004704888
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002618365GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

LOT 43,TAXBLOCK 2783 (Continued) **S109942587**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

EPA ID: NYP004704433
Country: USA
Location Address 1: 725 GRAND ST
Location Address 2: SB73900
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 12/09/2014
Trans1 Recv Date: 12/09/2014
Trans2 Recv Date: 12/16/2014
TSD Site Recv Date: 12/16/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004704433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002618341GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported

LOT 43,TAXBLOCK 2783 (Continued) **S109942587**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

E DESIGNATION:
Tax Lot(s): 43
Tax Block: 2783
Borough Code: BK
E-No: E-232
Effective Date: 7/29/2009
Satisfaction Date: Not reported
Ceqr Number: 09DCP056K
Ulurp Number: 090334ZMK
Zoning Map No: 12c 13a 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

AP147 **CHASE BANK** **NY UST** **U004198821**
SW **726 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.250 mi.
1319 ft. **Site 1 of 2 in cluster AP**

Relative:
Higher

Actual:
39 ft.

UST:
Id/Status: 2-601850 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 07/06/2004
UTM X: 589242.71545000002
UTM Y: 4507247.8195200004
Site Type: Utility (Other than Municipal)

Tank Info:

Tank Number: 001
Tank ID: 48070
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 03/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: 03
Date Test: 03/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/14/2010

Tank Number: 002

CHASE BANK (Continued) **U004198821**

Tank ID:	48071
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	03/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	03
Date Test:	03/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	01/14/2010

AP148 **DIME SAVINGS BANK** **NY HIST UST** **U002034198**
SW **726 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.250 mi.
1319 ft. **Site 2 of 2 in cluster AP**

Relative:
Higher

Actual:
39 ft.

HIST UST:

PBS Number:	2-601850
SPDES Number:	Not reported
Emergency Contact:	MR. LENNOX DEBRA
Emergency Telephone:	(516) 568-3886
Operator:	MR. LENNOX DEBRA
Operator Telephone:	(516) 568-3886
Owner Name:	DIME SAVINGS BANK, FSB
Owner Address:	400 SUNRISE HIGHWAY
Owner City,St,Zip:	VALLEY STREAM, NY 11582
Owner Telephone:	(516) 568-3886
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	DIME SAVINGS BANK, FSB
Mailing Address:	400 SUNRISE HIGHWAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	VALLEY STREAM, NY 11582
Mailing Contact:	MR. LENNOX DEBRA
Mailing Telephone:	(516) 568-3886
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	UTILITY
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/30/1999
Expiration Date:	07/06/2004
Renew Flag:	False
Renewal Date:	Not reported

DIME SAVINGS BANK (Continued) **U002034198**

Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	03/01/1999
Next Test Date:	03/01/2004
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	03/01/1999

DIME SAVINGS BANK (Continued) **U002034198**

Next Test Date:	03/01/2004
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

149
SE
1/4-1/2
0.272 mi.
1435 ft.

Relative:
Lower

Actual:
31 ft.

308 MAUJER ST
308 MAUJER ST
BROOKLYN, NY

NY LTANKS **S105999626**
N/A

LTANKS:

Site ID:	144741
Spill Number/Closed Date:	0305120 / 1/31/2006
Spill Date:	8/14/2003
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	JBLISTER
Referred To:	Not reported
Reported to Dept:	8/14/2003
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/14/2003
Spill Record Last Update:	1/31/2006
Spiller Name:	Not reported
Spiller Company:	FRED GELFAR
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	FRED GELFAR
Spiller Phone:	(516) 455-4775
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	123363
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"Will send a TTF as soon as RP provides a proper mailing address 8/19/2003 TTF Letter sent to:Fred Gelfar2941 Charlotte DriveMerrick, NY 115661/31/06 Received copy of 10/04/04 tightness report showing tank passed. Closed spill out based on report. J Lister
	Not reported
Remarks:	TANK TEST FAILURE THEY WILL RETEST

Material:

308 MAUJER ST (Continued) **S105999626**

Tank Test:

Site ID:	144741
Spill Tank Test:	1528589
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

---

150 SSW 1/4-1/2 0.298 mi. 1572 ft. **WILLIAMSBURG HOUSES -NYCHA** **NY LTANKS S102149362**
188 TEN EYCK WALK **NY Spills N/A**
BROOKLYN, NY

Relative: Higher

Actual: 41 ft.

LTANKS:

Site ID:	77200
Spill Number/Closed Date:	9802239 / 2/12/2010
Spill Date:	5/20/1998
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	MXAJOKU
Referred To:	SITE ASSESSMENT RCVD 6/07
Reported to Dept:	5/20/1998
CID:	198
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/20/1998
Spill Record Last Update:	2/12/2010
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	238486
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BREEN"NYCHA is no longer using this UST, but has yet to permanently close it (remove it from the ground). The tank was installed in 1978. It tested OK in 1991. It failed testing on 5/20/98. A second, identical tank was installed alongside this tank in 1978. The second

WILLIAMSBURG HOUSES -NYCHA (Continued) **S102149362**

tank consistently tests OK and is still in service. George Breen12/07/05: This spill transferred from J.Kolleeny to S.Kraszewski.02/06/06: This spill transferred from S.Kraszewski to Q.Abidi.04/04/06: This spill transferred from Q. Abidi to Koon Tang.06/19/06: SK received Email from Mohan Sharma from UTB consultants. As part of Schedule C of the NYCHA Order on Consent the tanks at this site are to be removed and replaced by the end of the month. Two 20K tanks, currently TOS will begin prep work on 06/22: cleaning, asbestos removal, piping. Once the prep work is finished, UTB will notify when the tanks will be pulled. I mentioned to Mohan that I wish to be on-site when they perform the tank removal. Waiting for second notice.Also, two tanks at 211 Stagg Walk, which are adjacent to this site are also being removed as part of Schedule C. No open spills for 211 Stagg Walk. - SK06/27/06: Recieved call from Frank Inoa, NYCHA Fuel Oil Remediation Unit. Oil recovery from the tanks is delaying the prep work. He expects to start uncovering the tanks next week and pull them the following week. Both he and Mohan Sharma from UTB will keep me updated. - SK07/07/06: Received an Email from UTB to notify of work to expose piping on July 12, 2006 in preparation for tank replacement. - SK09/08/06: Received email from Mohan Sharma at UTB informing me that the tanks will be pulled on 9/11 and 9/12 as part of Schedule C. - SK09/11/06: SK visited site to witness tank excavation. Two 20K USTs will be removed and replaced by one 20K UST. No soil or GW contamination was evident. Ivy Olberding (516-671-8440) from Gannett Fleming called asking about end-point sampling locations. I told her that I would like to be on-site when they perform the sampling. A Dorian Howard will be calling me to inform me when they will start sampling. - SK09/18/06: SK visited excavation site to instruct Gannett Fleming personnel where to collect end-point samples. UTB staff was finishing pumping out rainwater that colleted int he pit. A single tank pad that supported both tanks was present. SK instructed that soil sidewall samples be collected at two points along the length of the pit and one at each end. Also, since a bottom sample cannot be obtained two samples along the length of the pad and one a each end would suffice. Staff asked about the fill port and sampling, GF said once the site has been restored they will remove fill port piping and excavate. - SK02/08/07 : DEC lead changed from S. Kraszewski to J. Kann. J.Kann8/14/08: JK - site assessment received on 6/07.01/28/2010: Remediation and other associated clean-up activities linked to this spill number is now under the oversight of Moses Ajoku, all correspondence related this case should be addressed to me. (MA) 02/12/10: Spill number linked to this release is hereby closed follwoing the review of Closure Assessment Report. Report document is in eDocs. (MA)

Remarks: GROSS FAILURE OF TANK TEST. See Spill No. 9413630 also for this site.

Material:

Site ID:	77200
Operable Unit ID:	1060292
Operable Unit:	01
Material ID:	320577
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons

WILLIAMSBURG HOUSES -NYCHA (Continued) **S102149362**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 77200
Spill Tank Test: 1545911
Tank Number: 2
Tank Size: 20000
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 9413630
Facility Type: ER
DER Facility ID: 238486
Site ID: 294663
DEC Region: 2
Spill Date: 1/12/1995
Spill Number/Closed Date: 9413630 / 12/7/2005
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 1/12/1995
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/23/1995
Spill Record Last Update: 12/7/2005
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: 12/07/05: This spill transferred from J.Kolleeny to S.Kraszewski.This spill closed to consolidate with open spill #9802239.
Remarks: SEEPAGE NOTED THROUGH BASEMENT WALL IN BOILER ROOM-ADJACENT TO FUEL LINE. UNKNOWN IF LEAK OR PREVIOUS SPILL-REQUIRES REMEDIATION. JANE HEALY NOTIFIED-WILL MEET WITH HER TOMORROW.

WILLIAMSBURG HOUSES -NYCHA (Continued) **S102149362**

Material:

Site ID:	294663
Operable Unit ID:	1007196
Operable Unit:	01
Material ID:	372372
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

151
ENE
1/4-1/2
0.310 mi.
1636 ft.

Relative:
Lower

Actual:
18 ft.

BUG, EQUITY WORKS **NY HSWDS** **S102872851**
MASPETH AND MORGAN AVENUES **N/A**
BROOKLYN, NY 11222

HSWDS:

Facility ID:	HS2009
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	(formerly) Brooklyn Union Gas
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532048
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 43 00 N
Longitude:	73 56 15 W
Acres:	0.00
Operator Date:	1896
Close Date:	1928
Completed:	PA
Active:	No
PCB's Disposed:	Unknown
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No

BUG, EQUITY WORKS (Continued) **S102872851**

Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AQ152 **WILLIAMSBURG** **NY LTANKS** **S102671371**
SSW **144 MAUJER ST & GRAHAM ST** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.313 mi.
1655 ft. **Site 1 of 2 in cluster AQ**

Relative:
Higher

Actual:
38 ft.

LTANKS:

Site ID:	304525
Spill Number/Closed Date:	8809821 / 12/4/1992
Spill Date:	3/21/1989
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	12/4/1992
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	3/21/1989
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/23/1989
Spill Record Last Update:	9/7/1994
Spiller Name:	Not reported
Spiller Company:	NYC HSG AUTH
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	245979
DEC Memo:	Not reported
Remarks:	SPILL HAPPENED DURING A TRANSFER OF OIL FROM ONE TANK TO ANOTHER, CAP WAS NOT TIGHTENED IN FILL BOX, OIL SPILLED ON ROADWAY & 40 GALLONS IN SEWER.

Material:

Site ID:	304525
Operable Unit ID:	926081
Operable Unit:	01
Material ID:	450993
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

WILLIAMSBURG (Continued) **S102671371**

Tank Test:

AQ153 **151 MAUJER ST** **NY LTANKS** **S101508983**
SW **151 MAUJER STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.316 mi.
1666 ft. **Site 2 of 2 in cluster AQ**

Relative:
Higher

Actual:
38 ft.

LTANKS:

Site ID:	233375
Spill Number/Closed Date:	9414176 / 2/28/2003
Spill Date:	1/25/1995
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	No spill occured. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1/25/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/16/1995
Spill Record Last Update:	2/28/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	192302
DEC Memo:	Not reported
Remarks:	Not reported

Material:

Site ID:	233375
Operable Unit ID:	1007757
Operable Unit:	01
Material ID:	372923
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

151 MAUJER ST (Continued) **S101508983**

Oxygenate: False

Tank Test:
Site ID: 233375
Spill Tank Test: 1543568
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

AR154 **MAGNUM BODY SHOP INC** **NY RGA LF** **S114958856**
ENE **185A MASPETH AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.334 mi.
1766 ft. **Site 1 of 2 in cluster AR**

Relative:
Lower

Actual:
18 ft.

RGA LF:

2012	MAGNUM BODY SHOP INC	185A MASPETH AVE
2011	MAGNUM BODY SHOP INC	185A MASPETH AVE
2010	MAGNUM BODY SHOP INC	185A MASPETH AVE
2009	MAGNUM BODY SHOP INC	185A MASPETH AVE
2008	MAGNUM BODY SHOP INC	185A MASPETH AVE
2007	MAGNUM BODY SHOP INC	185A MASPETH AVE
2006	MAGNUM BODY SHOP INC	185A MASPETH AVE

AR155 **MAGNUM BODY SHOP INC** **NY SWF/LF** **S107785410**
ENE **185A MASPETH AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.334 mi.
1766 ft. **Site 2 of 2 in cluster AR**

Relative:
Lower

Actual:
18 ft.

SWF/LF:
Flag: ACTIVE
Region Code: 2
Phone Number: 7183029792
Owner Name: Bart Buchman
Owner Type: Private
Owner Address: 185A Maspeth Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Email: bartautosmart@yahoo.com
Owner Phone: 7184153315
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Vehicle Dismantling
Activity Number: [7091251]
Active: Yes
East Coordinate: 589945

MAGNUM BODY SHOP INC (Continued) **S107785410**

North Coordinate: 4507859
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

156
SW
1/4-1/2
0.339 mi.
1790 ft.

WILLIAMSBURG HOUSES
128 MAUJER STREET
BROOKLYN, NY 11206

NY LTANKS **U002034231**
NY HIST UST **N/A**
NY Spills

Relative:
Higher

Actual:
39 ft.

LTANKS:

Site ID:	121683
Spill Number/Closed Date:	9305275 / Not Reported
Spill Date:	7/28/1993
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	7/28/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	7/29/1993
Spill Record Last Update:	11/18/2014
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTH.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	105628
DEC Memo:	01/17/06: This spill transferred from J.Kolleeny to S.Kraszewski. Two TTF for tank 001 and it was replaced in 1994. No contamination evident during the removal. However, this open spill number exists and a site assessment must be performed. - SK09/01/06: DEC Lead for this spill changed from "unassigned" to S. Kraszewski. - J. Kolleeny02/09/07 - J.Kann - Spill reassigned from S.Kraszewski to J.Kann.08/04/08- J.Kann - Spill 9113231 (same address) closed and consolidated with this spill. J.kann11/18/14: J.Kann - looked through file. Need to further determine which tanks are at this location and what work was done.
Remarks:	PROB. EMPTY TANK AND CHECK FOR LEAK RATE.

WILLIAMSBURG HOUSES (Continued) **U002034231**

Material:

Site ID:	121683
Operable Unit ID:	986780
Operable Unit:	01
Material ID:	395207
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	121683
Spill Tank Test:	1541817
Tank Number:	001
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	131045
Spill Number/Closed Date:	9314699 / 3/23/1994
Spill Date:	3/15/1994
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	3/23/1994
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	3/15/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/21/1994
Spill Record Last Update:	1/17/2006
Spiller Name:	Not reported
Spiller Company:	NYC HOUS. AUTH.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported

WILLIAMSBURG HOUSES (Continued) **U002034231**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	105628
DEC Memo:	Not reported
Remarks:	CONTAINED CLEANED UP BY BAYSIDE FUEL OIL - PUT INTO DRUM - SPEEDY DRY USED. 350/PM CALLED GENTILE - SPILL ON CONCRETE & ASPHALT AT PARKING LOT - FUEL CO. & H.A. CLEANED UP QUICKLY BECAUSE IT WAS RAINI

Material:

Site ID:	131045
Operable Unit ID:	996626
Operable Unit:	01
Material ID:	386486
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	131045
Spill Tank Test:	1542497
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	128131
Spill Number/Closed Date:	9104201 / 4/27/1995
Spill Date:	7/19/1991
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/27/1995
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	7/19/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

WILLIAMSBURG HOUSES (Continued) **U002034231**

Remediation Phase: 0
Date Entered In Computer: 7/22/1991
Spill Record Last Update: 1/17/2006
Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 105628
DEC Memo: Not reported
Remarks: 8K TANK HORNER EZY CHECK; VISUAL GROSS LEAK, WILL REPAIR & RETEST. SEE SPILL # 9305275

Material:
Site ID: 128131
Operable Unit ID: 958108
Operable Unit: 01
Material ID: 423293
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 128131
Spill Tank Test: 1538781
Tank Number: 001
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST UST:
PBS Number: 2-601883
SPDES Number: Not reported
Emergency Contact: EMERGENCY SERVICE SQUAD
Emergency Telephone: (212) 289-3940
Operator: RAFAEL VELEZ
Operator Telephone: (212) 306-3142
Owner Name: NYC HOUSING AUTHORITY
Owner Address: 250 BROADWAY
Owner City,St,Zip: NEW YORK, NY 10007
Owner Telephone: (212) 306-3142

WILLIAMSBURG HOUSES (Continued) **U002034231**

Owner Type:	Local Government
Owner Subtype:	51
Mailing Name:	NYC HOUSING AUTHORITY
Mailing Address:	250 BROADWAY
Mailing Address 2:	16TH FLOOR - REMEDIATION SECTION
Mailing City,St,Zip:	NEW YORK, NY 10007
Mailing Contact:	FRANK OCELLO
Mailing Telephone:	(212) 306-3142
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	10/29/1999
Expiration Date:	06/02/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	14400
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	09/01/1994
Capacity (gals):	7000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Fiberglass
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Vault (w/access)
Leak Detection:	Electronic
Overfill Prot:	High Level Alarm, Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	09/01/2009
Missing Data for Tank:	Minor Data Missing

WILLIAMSBURG HOUSES (Continued) **U002034231**

Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

SPILLS:
Facility ID: 9506468
Facility Type: ER
DER Facility ID: 105628
Site ID: 121686
DEC Region: 2
Spill Date: 8/24/1995
Spill Number/Closed Date: 9506468 / 8/25/1995
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 8/25/1995
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons
Cleanup Ceased: 8/25/1995
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/25/1995
Spill Record Last Update: 8/28/1995
Spiller Name: Not reported
Spiller Company: B&G NATIONAL
Spiller Address: 33-59 55TH STREET
Spiller City,St,Zip: WOODSIDE, NY 11377
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: CONTRACTOR FOR BROOKLYN UNION GAS WAS CONVERTING BOILER ROOM FROM OIL TO DUAL FUEL-LEFT COVERS OFF OIL STRAINERS, CAUSED LEAK TO FLOOR DRAINS AND SUMP. NO OIL GOT INTO SEWER. CONTRACTOR TO CLEAN

Material:
Site ID: 121686
Operable Unit ID: 1017247
Operable Unit: 01
Material ID: 364434
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 40
Units: Gallons
Recovered: No

WILLIAMSBURG HOUSES (Continued) **U002034231**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9113231
Facility Type: ER
DER Facility ID: 105628
Site ID: 308874
DEC Region: 2
Spill Date: 3/27/1992
Spill Number/Closed Date: 9113231 / 8/4/2008
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: jkkann
Referred To: CONSOLIDATED WITH 9305275
Reported to Dept: 3/30/1992
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/6/1992
Spill Record Last Update: 8/4/2008
Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: 03/14/06: This spill assigned to K.Tang.8/4/08: Spill transferred to J.Kann and consolidated with spill 9305275. - J.Kann
Remarks: ILLEGALLY ABANDONED TANKS - 6 VAULTED TANKS AND 6 UNDERGROUND TANKS ABOUT 7000 GALS EACH. NYC HSG INSPECTOR GENERAL OFFICE IS INVESTIGATING FURTHER

Material:
Site ID: 308874
Operable Unit ID: 966835
Operable Unit: 01
Material ID: 414749
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No

WILLIAMSBURG HOUSES (Continued) **U002034231**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9412051
Facility Type: ER
DER Facility ID: 105628
Site ID: 121684
DEC Region: 2
Spill Date: 12/9/1994
Spill Number/Closed Date: 9412051 / 5/1/1995
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 12/9/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: 5/1/1995
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/15/1994
Spill Record Last Update: 5/1/1995
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: PUT FILL LINE TO SECONDARY CONTAINMENT-SPILL WENT ONTO LAWN AND CONCRETE-WILL RELIEVE PRESSURE AND CLEAN.

Material:
Site ID: 121684
Operable Unit ID: 1009840
Operable Unit: 01
Material ID: 374387
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 136
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

WILLIAMSBURG HOUSES (Continued) **U002034231**

Tank Test:

Site ID:	121684
Spill Tank Test:	1543436
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Facility ID:	9107819
Facility Type:	ER
DER Facility ID:	105628
Site ID:	128132
DEC Region:	2
Spill Date:	10/22/1991
Spill Number/Closed Date:	9107819 / 12/2/1994
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	10/22/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	12/2/1994
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/28/1991
Spill Record Last Update:	1/17/2006
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	7K TANK; OIL ON CONCRETE FLOOR. WINSTON CLEANING UP & DISPOSING. WILL INNVESTIGATE.

Material:

Site ID:	128132
Operable Unit ID:	961898
Operable Unit:	01
Material ID:	420004
Material Code:	0002A
Material Name:	#4 Fuel Oil

WILLIAMSBURG HOUSES (Continued) **U002034231**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	128132
Spill Tank Test:	1539201
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Facility ID:	9208264
Facility Type:	ER
DER Facility ID:	105628
Site ID:	121682
DEC Region:	2
Spill Date:	10/16/1992
Spill Number/Closed Date:	9208264 / 10/16/1992
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	10/16/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	10/16/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/20/1992
Spill Record Last Update:	9/7/1994
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	OIL FOUND IN STICKWELL AFTER DELIVERY-NYC HOUSING TO CLEANUP. CALLED JIM CAREY AT CASTLE OIL, OIL CAME OUT OF THE STICK HOLE CONTAMINATED

WILLIAMSBURG HOUSES (Continued) **U002034231**

SURROUNDING SOIL,NYCHA CALL CONTRACTOR TO PICK UP.

Material:

Site ID:	121682
Operable Unit ID:	975149
Operable Unit:	01
Material ID:	408857
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	121682
Spill Tank Test:	1540723
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

AS157 **JOESEPH LOWESTEIN AND SONS INC** **NY LTANKS S104647880**
NE **420 MORGAN AVE** **NY Spills N/A**
1/4-1/2 **BROOKLYN, NY 11222**
0.341 mi.
1799 ft. **Site 1 of 2 in cluster AS**

Relative:
Lower

Actual:
30 ft.

LTANKS:

Site ID:	209407
Spill Number/Closed Date:	9704885 / 8/16/2003
Spill Date:	7/24/1997
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	7/24/1997
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/24/1997
Spill Record Last Update:	8/18/2003
Spiller Name:	KAY STERN
Spiller Company:	JOSEPH LOWENSTEIN & SON
Spiller Address:	420 MORGAN AVE
Spiller City,St,Zip:	BROOKLYN, NY 11222-
Spiller County:	001
Spiller Contact:	KAY STERN
Spiller Phone:	(718) 388-5410
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	148750
DEC Memo:	Not reported
Remarks:	WATER LEAKING INTO A FUEL TANK AND FUEL LEAKING OUT BELIEVES SOME DID GET INTO SEWER - SPILL IS CONTAINED BUT NOT CLEANED UP YET

Material:

Site ID:	209407
Operable Unit ID:	1050744
Operable Unit:	01
Material ID:	334121
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPILLS:

Facility ID:	9807480
Facility Type:	ER
DER Facility ID:	148750
Site ID:	241702
DEC Region:	2
Spill Date:	9/17/1998
Spill Number/Closed Date:	9807480 / 3/3/2003
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	9/17/1998
CID:	201
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/17/1998
Spill Record Last Update:	5/12/2003
Spiller Name:	PHYLLIS HORATA
Spiller Company:	JOSEPH LOWENSTEIN INC
Spiller Address:	420 MORGAN AV
Spiller City,St,Zip:	BROOKLYN, NY -
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	FIRE AT LOCATION/THE DYS ARE 2 DIFFERENT TYPES/PDR AUBURN GRR #5 AND PDR DK BROWN RCC #5 - UNK AMOUNT ON THE DK BRO DYE AND THE SODIUM SILICATE/UNK AMOUNT WENT INTO STORM DRAIN DURING EXTINGUSIHMENT AND COOLING DOWN OF THE DRUMS/DEP WAS ON SCEEN REP WONG ON SCENE

Material:

Site ID:	241702
Operable Unit ID:	1065046
Operable Unit:	01
Material ID:	318564
Material Code:	0392A
Material Name:	SODIUM SILICATE
Case No.:	01344098
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	241702
Operable Unit ID:	1065046
Operable Unit:	01
Material ID:	318563
Material Code:	0048A
Material Name:	DYE
Case No.:	Not reported
Material FA:	Other
Quantity:	525
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	1005972
Facility Type:	ER
DER Facility ID:	394306
Site ID:	439308
DEC Region:	2
Spill Date:	8/30/2010

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

Spill Number/Closed Date:	1005972 / 9/13/2010
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	2401
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	8/30/2010
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/30/2010
Spill Record Last Update:	9/13/2010
Spiller Name:	HASSAN HUSSEIN
Spiller Company:	JOESEPH LOWESTEIN AND SONS INC
Spiller Address:	420 MORGAN AVE
Spiller City,St,Zip:	BROOKLYN, NY 11222
Spiller Company:	999
Contact Name:	HASSAN HUSSEIN
Contact Phone:	(917) 371-4064
DEC Memo:	Material spilled is Lanolin (yellow waxy substance secreted by the sebaceous glands of wool-bearing animals. Most lanolin used by humans comes from domestic sheep)Not regulated by DEC
Remarks:	Spill is a mixture of water and lanoline. It is in a secondary containment area.

Material:

Site ID:	439308
Operable Unit ID:	1189953
Operable Unit:	01
Material ID:	2184914
Material Code:	9999
Material Name:	Other - Lanoline
Case No.:	Not reported
Material FA:	Other
Quantity:	10
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9704884
Facility Type:	ER
DER Facility ID:	148750
Site ID:	177007
DEC Region:	2

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

Spill Date:	7/24/1997
Spill Number/Closed Date:	9704884 / 8/16/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	7/24/1997
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/24/1997
Spill Record Last Update:	8/18/2003
Spiller Name:	JOSEPH LOWENSTEIN
Spiller Company:	JOSEPH H LOWENSTEIN,INC.
Spiller Address:	420 MORGAN AVENUE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	JOSEPH LOWENSTEIN
Contact Phone:	(718) 388-5410
DEC Memo:	Not reported
Remarks:	broken line in system.

Material:

Site ID:	177007
Operable Unit ID:	1048278
Operable Unit:	01
Material ID:	334120
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9911878
Facility Type:	ER
DER Facility ID:	148750
Site ID:	209408
DEC Region:	2
Spill Date:	1/12/2000
Spill Number/Closed Date:	9911878 / 3/6/2007
Spill Cause:	Unknown

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	HRPATEL
Referred To:	MOORE
Reported to Dept:	1/12/2000
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/12/2000
Spill Record Last Update:	3/6/2007
Spiller Name:	SAME
Spiller Company:	JOSEPH LOWENSTEIN & SONS
Spiller Address:	420 MORGAN AVE
Spiller City,St,Zip:	BROOKLYN, NY 11222-
Spiller Company:	001
Contact Name:	BILL MIKULA
Contact Phone:	(908) 686-5959
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M TIBBE"12/05 - Additional groundwater and soil samples should be taken to determine if remediation needs to be performed. Samples taken as part of the UST Closure Report in 2000 indicate some exceedences. ~MaloneyAlbany review (above) - kamalone1/29/07 - Austin - Transferred from Albany assignment to Patel in R-2 office for further work - end03/06/07-Hiralkumar Patel.owner of property:Joe Lowe RealtyAttn.: Kay SternHS&E Manager420 Morgan AvenueBrooklyn, NY 11222PH. (718) 388-5140Fax (718) 387-3806email: kay@jhlowenstein.comabstract of Site Assessment report, submitted by Hudson environmental dated 02/14/00:- closure of two USTs: 1. 3000 gal Paraffin 105 oil, 2. 2800 gal Paraffin 240 oil- USTs abandoned (11/1999) in place after one year of tightness test (11/1998)- site is used by Lowenstein to manufacture hair and fur preparatory agents (i.e. dyes, soaps, tanning oils, etc.)- Lowenstein expanded into the adjacent buildings that were formerly occupied by AN AUTOMOBILE GARAGE, paint factory and foundry.- another spill reported on 07/24/97, fuel oil release from the fill piping associated with 3000 gal #2 oil UST (spill closed)- local groundwater flow direction is assumed to be towards the southwest toward the Newtown Creek and the English Kills- groundwater was not encountered to a depth of 19 ft below the concrete floor of the facility- interior visual inspection of the tanks revealed no evidence of corrosion or breach of the bottom, top, side or end walls of the tanks- three access holes were cut along the bottom centerline fo the cleaned tanks for soil samples (T1.1, T1.2 and T1.3 from under 3000 gal UST and T2.1, T2.2 and T2.3 from under 2800 gal UST)- soil samples were collected 0.5 ft below the tanks- three soil borings (B1 through B3) were adavanced on 11/12/1999- boring depths ranged from 8 ft bg in B1 to 19 ft bg in B3- temporary well point was placed into the deepest soil boring B3- no measurable groundwater was detected in the temporary well point- no floating product was observed in teh temporary well

JOESEPH LOWESTEIN AND SONS INC (Continued) **S104647880**

point----------T1.1-------T1.2-------T1.3-----limit
(TCLP)
ppbBenzene----------63---------52----------14Acen
aphthene----------2,100--------830--------410----------400Benzo(a)
anthracene----------100----------0.04Benzo(b)
fluoranthene----------130----------0.
04Fluorene----------2,900------1,300----------1,
000Naphthalene----------8,400------3,
200--------810----------200Phenanthrene----------6,100------2,
500----------1,000Pyrene----------1,
400----------1,000----------Total Petroleum
Hydrocarbon (TPHC)
ppbT1.1----------55,000,000T1.2----------63,000,000T1.
3----------22,000,000T2.1----------2,400,000T2.2----------4,
200,000T2.3----------6,500,000Note from report: Paraffin oil is
not a petroleum product as defined under NYS PBS regulations parts
612 through 614 and are exempt under NYS CBS regulations from parts
595 through 598.report mentioned of three soil borings (B1 through
B3), but no indication of any soil samples from these borings.PBS #:
2-010790discussed with DEC Austin. he mentioned that Paraffin oil is
residual of petroleum product and is not regulated by PBS. he asked
to compare TCLP values to "Soil cleanup objectoves to protect
groundwater quality" in TAGM. if values below limit, he asked to
close this case.comared all above TCLP values to groundwater quality
standards. no exceedance found.case closed.

Remarks: THEY WERE DOING A IN PLACE CLOSURE ON THE SITE AND TOOK SAMPLESIN EARLY DECMEMBER AND GOT THE RESULTS BACK THIS WEEK.THE SAMPLES VOLATAILES AND SEMI VOLATAILES IN THE DIRT.

Material:

Site ID:	209408
Operable Unit ID:	1090576
Operable Unit:	01
Material ID:	297317
Material Code:	0063A
Material Name:	UNKNOWN HAZARDOUS MATERIAL
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

---

158 South 1/4-1/2 0.341 mi. 1802 ft.

WILLIAMSBURGH HOUSES
211 STAGG WALK
BROOKLYN, NY 11206

NY LTANKS **U002034232**
NY UST **N/A**
NY AST
NY Spills

Relative: Higher

Actual: 40 ft.

LTANKS:

Site ID:	187016
Spill Number/Closed Date:	9110920 / 1/22/1992
Spill Date:	1/22/1992
Spill Cause:	Tank Overfill

WILLIAMSBURGH HOUSES (Continued) **U002034232**

Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1/22/1992
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1/22/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/6/1992
Spill Record Last Update:	6/28/2006
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	156295
DEC Memo:	Not reported
Remarks:	CONTAINED ON DRIVEWAY. WINSTON TO CLEAN. NO DRAINS AFFECTED.

Material:

Site ID:	187016
Operable Unit ID:	964729
Operable Unit:	01
Material ID:	415992
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	187016
Spill Tank Test:	1539531
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

WILLIAMSBURGH HOUSES (Continued) **U002034232**

UST:

Id/Status:	2-601884 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/02/2019
UTM X:	589456.09647999995
UTM Y:	4507038.3996599996
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23846
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/3/2014

Site Id:	23846
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Y.TKACH@NYCHA.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/24/2014

Site Id:	23846
Affiliation Type:	On-Site Operator
Company Name:	WILLIAMSBURGH HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725

WILLIAMSBURGH HOUSES (Continued) **U002034232**

EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/24/2014

Site Id: 23846
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: 718-707-5900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/31/2008

Tank Info:

Tank Number: 1
Tank ID: 215666
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 20000
Install Date: 01/09/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: 0
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: E
Modified By: NRLOMBAR
Last Modified: 12/31/2008

Equipment Records:

C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
A00 - Tank Internal Protection - None
D11 - Pipe Type - Flexible Piping
F05 - Pipe External Protection - Jacketed
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B09 - Tank External Protection - Urethane

WILLIAMSBURGH HOUSES (Continued) **U002034232**

G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None

Tank Number:	OLD 1
Tank ID:	48201
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	20000
Install Date:	12/01/1978
Date Tank Closed:	01/03/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	05/13/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	01/18/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	OLD 2
Tank ID:	48202
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	20000
Install Date:	12/01/1978
Date Tank Closed:	01/03/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	01/18/2007

WILLIAMSBURGH HOUSES (Continued) **U002034232**

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601884
Program Type:	PBS
UTM X:	589456.09647999995
UTM Y:	4507038.3996599996
Expiration Date:	06/02/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23846
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/3/2014

Site Id:	23846
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Y.TKACH@NYCHA.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/24/2014

WILLIAMSBURGH HOUSES (Continued) **U002034232**

Site Id:	23846
Affiliation Type:	On-Site Operator
Company Name:	WILLIAMSBURGH HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/24/2014

Site Id:	23846
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	718-707-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008

Tank Info:

Tank Number:	T-1
Tank Id:	209300
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

E01 - Piping Secondary Containment - Diking (Aboveground)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B09 - Tank External Protection - Urethane
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)
H00 - Tank Leak Detection - None
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None

Tank Location: 3

WILLIAMSBURGH HOUSES (Continued) **U002034232**

Tank Type:	Urethane Clad Steel
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/09/2005
Capacity Gallons:	20000
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/19/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/28/2006
Material Name:	Empty

SPILLS:

Facility ID:	9506548
Facility Type:	ER
DER Facility ID:	156295
Site ID:	187017
DEC Region:	2
Spill Date:	8/28/1995
Spill Number/Closed Date:	9506548 / 8/29/1995
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	8/28/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	8/29/1995
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/29/1995
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	SMALL LEAK IN BOILER STRAINER - WAS REPAIRED.

Material:

Site ID:	187017
Operable Unit ID:	1017296
Operable Unit:	01
Material ID:	364510
Material Code:	0001A

WILLIAMSBURGH HOUSES (Continued) **U002034232**

Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

---

159 SSW 1/4-1/2 0.345 mi. 1822 ft. **INTERMEDIATE SCHOOL 49 - BROOKLYN K049** **NY LTANKS U001839975**
223 GRAHAM AVENUE **NY UST N/A**
BROOKLYN, NY 11206 **NY AST**
NY HIST AST

Relative: Higher

Actual: 38 ft.

LTANKS:

Site ID:	336264
Spill Number/Closed Date:	0411168 / 12/19/2005
Spill Date:	1/14/2005
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	AJWHITE
Referred To:	Not reported
Reported to Dept:	1/14/2005
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/14/2005
Spill Record Last Update:	12/19/2005
Spiller Name:	JEFF DEVERTEUIO
Spiller Company:	SCHOOL
Spiller Address:	223 GRAHM AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	JEFF DEVERTEUIO
Spiller Phone:	(718) 349-5752
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	110563
DEC Memo:	send ttf letterSee also spill #9711161. Spill 971116 was closed and merged with this spill no. This is a NYTC school, will track down the NYC school coordinator.Spoke to Phil Frazin of A-1 Crown Leak. this is a NYC School. I will check to see if Spill response will take this over as part of the whole NYC School project.- S. Scharf August 30, 2005.11/15/2005: Lead transferred to Joe White as part of the Spill

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Initiative Project.12/08/2005: Mr. James Merlo, the coordinator for NYC School spills, called Joe White to indicate that the tank has been emptied and taken out of service. a certificate of abandonment will be forwarded to document this.12/19/2005: Joe White received the "Certificate of Affidavit" for abandonment of the the tank at this location. The certificate date was 2/1/2005. This abandonment is sufficient for closure of this spill report due to tanks test failure.
Not reported
Remarks: PBS No: 2-356220

Material:
Site ID: 336264
Operable Unit ID: 1098301
Operable Unit: 01
Material ID: 578471
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 336264
Spill Tank Test: 1548488
Tank Number: 2
Tank Size: 7500
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 1/14/2005
Test Method: Horner EZ Check I or II
Site ID: 336264
Spill Tank Test: 1548491
Tank Number: 1
Tank Size: 7500
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 1/14/2005
Test Method: Horner EZ Check I or II

Site ID: 128139
Spill Number/Closed Date: 9711161 / 3/14/2005
Spill Date: 1/5/1998
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1/5/1998
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/5/1998
Spill Record Last Update:	3/14/2005
Spiller Name:	KWAME FOSU
Spiller Company:	NY CITY SCHOOL DISTRICT
Spiller Address:	30-30 THOMSON AVE
Spiller City,St,Zip:	LONG ISLAND, NY 11101-
Spiller County:	001
Spiller Contact:	KWAME FOSU
Spiller Phone:	(718) 472-8501
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	110563
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN"5/12/04 - ORIG. ASIGNED TO HALE3/14/05 - Austin - closed and consolidated with spill #0411168 - end
Remarks:	SOIL TEST AT ABOVE LOCATION IDICATE A POSSIBLE LEAK AT ABOVELOCATION. ADDITIONAL TESTING WILL BE DONE TO DETERMINE AMOUNTAND NATURE OF SPILL. CALLER REQUEST CALL DURING BUSINESS HOURS.

Material:

Site ID:	128139
Operable Unit ID:	1054046
Operable Unit:	01
Material ID:	325865
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

UST:

Id/Status:	2-356220 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/28/2018
UTM X:	589279.37416999997

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

UTM Y:	4506973.4511599997
Site Type:	School

Affiliation Records:

Site Id:	17785
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	3/4/2015

Site Id:	17785
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/14/2015

Site Id:	17785
Affiliation Type:	On-Site Operator
Company Name:	INTERMEDIATE SCHOOL 49 - BROOKLYN K049
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/26/2013

Site Id:	17785
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	GDBREEN
Date Last Modified:	9/10/2014

Tank Info:

Tank Number:	001
Tank ID:	34798
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	02/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	ZZ
Date Test:	09/11/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	06/25/2008

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	34799
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	11/09/2006

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 08/26/2005
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 06/25/2008

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-356220
Program Type: PBS
UTM X: 589279.37416999997
UTM Y: 4506973.4511599997
Expiration Date: 06/28/2018
Site Type: School

Affiliation Records:
Site Id: 17785
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: MUNENDRA SHARMA
Address1: 44-36 VERNON BOULEVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 3/4/2015

Site Id: 17785
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF EDUCATION

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/14/2015

Site Id:	17785
Affiliation Type:	On-Site Operator
Company Name:	INTERMEDIATE SCHOOL 49 - BROOKLYN K049
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/26/2013

Site Id:	17785
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	GDBREEN
Date Last Modified:	9/10/2014

Tank Info:

Tank Number:	003
Tank Id:	223811
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/18/2007
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	07/01/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-356220
SWIS Code:	6101
Operator:	PLANT OPERATION
Facility Phone:	(718) 391-6000
Facility Addr2:	223 GRAHAM AVE
Facility Type:	SCHOOL
Emergency:	SCHOOL SAFETY
Emergency Tel:	(212) 979-3300
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	N.Y.C. BOARD OF EDUCATION
Owner Address:	28-11 QUEENS PLAZA NORTH
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 391-6832
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	FRANK CARDELLO NTROL
Mailing Name:	OFFICE OF BUILDING SERVICES
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	5TH FLOOR
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 391-6832
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

or not at the facility.
Certification Flag: False
Certification Date: 05/15/2000
Expiration: 06/28/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 15000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 7500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: 01
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 01
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 002
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 7500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: 01
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON

INTERMEDIATE SCHOOL 49 - BROOKLYN K049 (Continued) **U001839975**

Pipe Internal:	None
Pipe External:	01
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

160
SE
1/4-1/2
0.351 mi.
1855 ft.

345 TENEYCK STREET **NY LTANKS** **S102672003**
345 TENEYCK STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
19 ft.

LTANKS:

Site ID:	300237
Spill Number/Closed Date:	9210082 / 12/1/1992
Spill Date:	12/1/1992
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	12/1/1992
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	12/1/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/2/1992
Spill Record Last Update:	12/2/1992
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	242863
DEC Memo:	Not reported
Remarks:	FAULTY PETROMETER-OIL OUT FILL PIPE TO CONCRETE SIDEWALK-SPEEDI-DRI APPLIED-SPILL TEAM ENROUTE TO P/U AND DISPOSE

345 TENEYCK STREET (Continued) **S102672003**

Material:

Site ID:	300237
Operable Unit ID:	974178
Operable Unit:	01
Material ID:	407093
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

161
ENE
1/4-1/2
0.353 mi.
1863 ft.

MS POWER INC **NY SWF/LF** **S108146009**
187 MASPETH VE **N/A**
BROOKLYN, NY 11211

Relative:
Lower

Actual:
16 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling
Activity Number:	Not reported
Active:	No
East Coordinate:	589950
North Coordinate:	4507862
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported

AS162 **ABANDONED BLDG** **NY LTANKS** **S105996244**
NE **430 MORGAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.354 mi.
1871 ft. **Site 2 of 2 in cluster AS**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	331139
Spill Number/Closed Date:	0203790 / 6/4/2003
Spill Date:	7/10/2002
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	7/10/2002
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/10/2002
Spill Record Last Update:	6/4/2003
Spiller Name:	MATT
Spiller Company:	ABANDONED BLDG .,.,
Spiller Address:	430 MORGAN AV
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller County:	001
Spiller Contact:	MATT
Spiller Phone:	(631) 851-1600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266314
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"GCI Inc. submitted a report dated May 16, 2003 which details the removal of the subject tank. According to this report there was no sign of oil leakage and the only holes were in the vent line. Soil end point samples were taken from the bottom of the excavation and were Non Detect for 8021 and 8270. Excavation was back filled with packed sand.Spill closed
Remarks:	TANK FAILED TEST - NO PRODUCT SPILLAGE

Material:

Site ID:	331139
Operable Unit ID:	854918
Operable Unit:	01
Material ID:	521602
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons

ABANDONED BLDG (Continued) **S105996244**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 331139
Spill Tank Test: 1527269
Tank Number: 001
Tank Size: 1080
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

AT163 **DURITE S&V & MAINT. CORP.** **NY RGA LF** **S114956448**
ESE **250 MORGAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.368 mi.
1941 ft. **Site 1 of 2 in cluster AT**

Relative:
Lower

Actual:
16 ft.

RGA LF:

2012	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2011	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2010	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2009	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2008	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2007	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2006	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2005	DURITE S&V & MAINT. CORP.	250 MORGAN AVE
2004	DURITE S&V & MAINT. CORP.	250 MORGAN AVE

AT164 **DURITE S&V & MAINT. CORP.** **NY SWF/LF** **S105841904**
ESE **250 MORGAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.368 mi.
1941 ft. **Site 2 of 2 in cluster AT**

Relative:
Lower

Actual:
16 ft.

SWF/LF:
Flag: INACTIVE
Region Code: 2
Phone Number: 7184177271
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: STEVE RUSSEL; OWNER
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported

DURITE S&V & MAINT. CORP. (Continued) **S105841904**

Activity Desc:	C&D processing - registration
Activity Number:	[24W67]
Active:	No
East Coordinate:	589000
North Coordinate:	4507200
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6104-00016
Authorization Date:	05/21/1991
Expiration Date:	05/31/1996

---

165 SE 1/4-1/2 0.377 mi. 1993 ft.

APARTMENT BUILDING
35 MEADOW STREET
BROOKLYN, NY

NY LTANKS **S107789405**
N/A

Relative: Lower

Actual: 20 ft.

LTANKS:

Site ID:	364030
Spill Number/Closed Date:	0601731 / 8/29/2006
Spill Date:	5/16/2006
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	5/16/2006
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/16/2006
Spill Record Last Update:	8/29/2006
Spiller Name:	DEREK DENCKLA
Spiller Company:	APARTMENT BUILDING
Spiller Address:	35 MEADOW STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	DEREK DENCKLA
Spiller Phone:	(917) 674-9040
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	314232
DEC Memo:	05/17/06-Hiralkumar Patel. Spoke to Jim at Protest. it was 1500 gal AST. tank was cleaned in past and doesn't have manhole. and Jim found dry leak and thinks it is from patch on top of tank. he hasn't find any oil stains on floor. he has send proposal to owner and planning to clean tank and to put manhole on tank. haven't found PBS number.Spoke to Derek. he is process of buying this property and gave current owner's name and number.Joseph Heimlich(718) 381-2405As per

APARTMENT BUILDING (Continued) **S107789405**

Derek, he has closing of this property on Jun 30 2006. once he will get property on his name, he will remove tank and system. owner is not using tank currently. asked him to send tank test results and letter signed by current owner and purchaser stating that they will remove tank after closing and tank is not in use currently by end of tomorrow. told Derek that as this tank is more than 1100 gal capacity, it has to be registered with PBS eventhought they are planning to remove it after Jun.Spoke to Joseph. as per him, he has turn off boiler and tank is not in use currently. tank has oil less than half of the volume. told Joseph that if Department receive letter from him and Derek, Department can wait till they remove tank. but tank has to registered with PBS now. send out letter with tank registration requirement. faxed to Joseph and Derek.Joseph Heimlich35 Meadow StreetBrooklyn, NY 11206FAX (718) 381-287505/19/06-Hiralkumar Patel. Received letter from Joseph and Derek. abstract:- owner is selling property and property is set to close on or about July 30, 2006.- heating season is over and boiler is currently turned off and will remain turned off through contract closing date- based on tank test, owner has cancelled all scheduled oil deliveries and suspended oil delivery service until further notice.08/01/06-Hiralkumar Patel. spoke with Derek. he is no longer in process of buying this property. spoke with Joseph. owner has removed oil, clean tank and sealed it back. he didn't do any isolation test or system test after tank cleaning. asked Joseph to do system test again. he will call ABC tank for further testing.08/02/06-Hiralkumar Patel. received call from Robert from ABC Tank. they will do system test probably next week. Robert will call once he gets test result.08/29/06-Hiralkumar Patel. spoke with Donna at ABC Tank. they have changed rubber gasket on tank. she doesn't have any information about system test. she will check and call back. received call from Donna. she got test result and will fax it. got passing system test in fax. tank is registered now. PBS#: 2-610289based on available informations, case closed.

Remarks: Not reported

Material:

Site ID:	364030
Operable Unit ID:	1122083
Operable Unit:	01
Material ID:	2111568
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AU166 **COOPER TANK AND WELDING CORP.** **NY SWF/LF** **S107783541**
ENE **222 MASPETH AVENUE** **NY HIST AST** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY Financial Assurance**
0.395 mi.
2087 ft. **Site 1 of 2 in cluster AU**

Relative:
Lower

Actual:
15 ft.

SWF/LF:

Flag:	ACTIVE
Region Code:	2
Phone Number:	7183847727
Owner Name:	Adrienne Cooper
Owner Type:	Private
Owner Address:	215 Moore Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Email:	Not reported
Owner Phone:	7184974431
Contact Name:	Ray Kvedaras
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	rkvedaras@coopertank.com
Contact Phone:	7183847727
Activity Desc:	C&D processing - permit
Activity Number:	[24W21]
Active:	Yes
East Coordinate:	590021
North Coordinate:	4507910
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Construction & Demolition Debris;Metals (Ferrous);Metals (Non-Ferrous);Plastics;Paper / Cardboard;Wood (Chips);Concrete
Authorization #:	2-6101-00061/00001
Authorization Date:	02/17/2011
Expiration Date:	02/17/2016

HIST AST:

PBS Number:	2-604500
SWIS Code:	6101
Operator:	RAY KVEDARAS
Facility Phone:	(718) 384-7727
Facility Addr2:	Not reported
Facility Type:	OTHER
Emergency:	MICHAEL LITTWIN
Emergency Tel:	(718) 497-4431
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	COOPER TANK & WELDING CORP.
Owner Address:	222 MASPETH AVE.
Owner City,St,Zip:	BROOKLYN, NY 11211
Federal ID:	Not reported
Owner Tel:	(718) 384-7727
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	RAY KVEDARAS
Mailing Name:	COOPER TANK & WELDING CORP.
Mailing Address:	222 MASPETH AVE.

COOPER TANK AND WELDING CORP. (Continued) **S107783541**

Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211
Mailing Telephone:	(718) 384-7727
Owner Mark:	First Owner
Facility Status:	4 - Subpart 360-14 only (active)
Certification Flag:	False
Certification Date:	05/15/2000
Expiration:	05/08/2005
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	275
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	275
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	1
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	1
Tank Containment:	Excavation/Tranch Liner
Leak Detection:	0
Overfill Protection:	5
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

NY Financial Assurance 1:

Owner Name:	Adrienne Cooper
Region:	2
Estimate Type:	Closure Estimate
Estimate Amount:	$355,000.0
Estimate Date:	03/01/2001
Mechanism:	Surety bond - Performance
Mechanism Amount:	$355,000.0

COOPER TANK AND WELDING CORP. (Continued) **S107783541**

Issue Date: 03/01/2001
Expiration Date: Not reported
Activity Number: 24W21
Activity Description: C&D processing - permit

AU167 **COOPER TANK (222 MASPETH)** **NY RGA LF** **S114955937**
ENE **222 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.395 mi.
2087 ft. **Site 2 of 2 in cluster AU**

Relative:
Lower

Actual:
15 ft.

RGA LF:

2012	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2011	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2010	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2009	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2008	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2007	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2006	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2005	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE
2004	COOPER TANK (222 MASPETH)	222 MASPETH AVENUE

---

168 **GREEN HILL** **NY LTANKS** **S105999093**
East **2 REWE ST & 300 VANDERVOO** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.400 mi.
2110 ft.

Relative:
Lower

Actual:
9 ft.

LTANKS:

Site ID:	191858
Spill Number/Closed Date:	0302094 / 1/31/2006
Spill Date:	5/29/2003
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	5/29/2003
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/29/2003
Spill Record Last Update:	1/31/2006
Spiller Name:	ALBERT CHAN
Spiller Company:	Not reported
Spiller Address:	2 REWE ST & 300 VANDERVOO
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	ALBERT CHAN

GREEN HILL (Continued) **S105999093**

Spiller Phone:	(718) 963-2800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	160009
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHAO"Sangesland DDO Zhao is assigned because consultant dealt with her on this site. Contaminated soil letter was sent to:Consultant is: Andrew Drotleff of TRC Raviv Assoc (973-564-6006 x285) 57 East Willow St., Millburn, NJ 07041 Site is a corner lot with 2 addresses: (2 Rewe St & 300 Vandervoort) PBS 2-608764Two tanks are being abandoned in place (3,000 gal and 2,000)One tank had pin holes in it and water poured in from raised water table. The second tank appeared OK, but had some oil odor from the soil in the piping area.10/31/2005 - JZ: Zhao spoke with Andrew Drotleff, TRC. Recently took GW samples from 3 wells. Sesults are favorable and look clean. Report will be send in end November.1/31/2006 - JZ: Report was submitted and reviewed. spill is closed.
Remarks:	CALLERS COMPANY PERFORMING A TANK CLOSURE AND CONTAMINATED SOIL WAS DISCOVERED AROUND 2 TANKS

Material:

Site ID:	191858
Operable Unit ID:	870003
Operable Unit:	01
Material ID:	506580
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	191858
Operable Unit ID:	870003
Operable Unit:	01
Material ID:	506579
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

169
ENE
1/4-1/2
0.411 mi.
2170 ft.

EQUITY WORKS
MASPETH AND VANDERVORT AVES.
BROOKLYN, NY 11211

EDR MGP **1008407885**
N/A

Relative:
Lower

Actual:
15 ft.

Manufactured Gas Plants:
No additional information available

AV170
East
1/4-1/2
0.414 mi.
2186 ft.

NEW TOWN AUTO SALES & AUTO PARTS INC
1074 GRAND STREET
BROOKLYN, NY

NY RGA LF **S114959465**
N/A

Site 1 of 2 in cluster AV

Relative:
Lower

Actual:
13 ft.

RGA LF:

2012	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2011	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2010	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2009	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2008	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2007	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET
2006	NEW TOWN AUTO SALES & AUTO PARTS INC	1074 GRAND STREET

AV171
East
1/4-1/2
0.414 mi.
2186 ft.

NEW TOWN AUTO SALES & AUTO PARTS INC
1074 GRAND AVENUE
BROOKLYN, NY 11211

NY SWF/LF **S108146024**
N/A

Site 2 of 2 in cluster AV

Relative:
Lower

Actual:
13 ft.

SWF/LF:

Flag:	ACTIVE
Region Code:	2
Phone Number:	7185992300
Owner Name:	New Town Used Auto Sales & Auto Parts Inc
Owner Type:	Private
Owner Address:	1074 Grand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	Not reported
Owner Phone:	7185992300
Contact Name:	Frederick Kirschbaum
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	NY
Contact Email:	Not reported
Contact Phone:	7185992300
Activity Desc:	Vehicle Dismantling
Activity Number:	[7096848]
Active:	Yes
East Coordinate:	590144
North Coordinate:	4507507
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported

NEW TOWN AUTO SALES & AUTO PARTS INC (Continued) **S108146024**

Expiration Date: Not reported

AW172 **CITY BARREL CO.** **NY SHWS** **S105972440**
NW **421-429 MEEKER STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11378**
0.414 mi.
2186 ft. **Site 1 of 3 in cluster AW**

Relative:
Lower

Actual:
17 ft.

SHWS:

Program:	HW
Site Code:	55909
Classification:	N
Region:	2
Acres:	Not reported
HW Code:	224005
Record Add:	11/18/1999
Record Upd:	12/16/2003
Updated By:	kstang
Site Description:	The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. This site was listed in the Eckhardt subcommittee report as a disposal site. Investigation by the NYSDEC Regional offices indicate that this is an industrial operation to recycle, recover and refurbish drums and that no apparent disposal of hazardous or toxic waste have occurred here.
Env Problem:	None known. No apparent disposal of significant quantities of any hazardous waste.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AX173 **CLEAN VENTURE** **NY RGA LF** **S114955762**
ESE **222 MORGAN AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.414 mi.
2188 ft. **Site 1 of 5 in cluster AX**

Relative:
Lower

Actual:
14 ft.

RGA LF:

1998	CLEAN VENTURE	222 MORGAN AVENUE

AX174 **EASTERN TRANSFER OF NY; INC (N.Y. MATER** **NY RGA LF** **S114956530**
ESE **222 MORGAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.414 mi.
2188 ft. **Site 2 of 5 in cluster AX**

Relative:
Lower

Actual:
14 ft.

RGA LF:

2012	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2011	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2010	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2009	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2008	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2007	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2006	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2005	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE
2004	EASTERN TRANSFER OF NY; INC (N.Y. MATER	222 MORGAN AVE

AX175 **EASTERN TRANSFER OF NY; INC (N.Y. MATER** **NY SWF/LF** **S103592538**
ESE **222 MORGAN AVE** **NY LTANKS** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.414 mi.
2188 ft. **Site 3 of 5 in cluster AX**

Relative:
Lower

Actual:
14 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	7184973100
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	LOUIS D'AMBROSIO
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W76]
Active:	No
East Coordinate:	590116
North Coordinate:	4507117
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Authorization #: 2-6104-00097
Authorization Date: Not reported
Expiration Date: Not reported

Flag: INACTIVE
Region Code: 2
Phone Number: 7184973100
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: LOUIS D'AMBROSIO
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Transfer station - permit
Activity Number: [24T76]
Active: No
East Coordinate: 590116
North Coordinate: 4507117
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2-6104-00097
Authorization Date: Not reported
Expiration Date: Not reported

LTANKS:
Site ID: 302888
Spill Number/Closed Date: 0009585 / 8/28/2003
Spill Date: 11/21/2000
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 11/21/2000
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/21/2000
Spill Record Last Update: 8/28/2003
Spiller Name: JAMES JULIANO, PROP MGR
Spiller Company: QUATTRO PROPERTIES, LLC

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Spiller Address:	213-19 99TH AVENUE
Spiller City,St,Zip:	QUEENS VILLAGE, NY 11429-
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244717
DEC Memo:	Not reported
Remarks:	CALLER PULLED TANK AND FOUND CONTAMINATED SOIL.WOULD LIKE A CALL FROM DEC 11-21-00 TIS STRANGE BUT R. SPADALIK IS NO LONGER AT F&N WHEN I CALLED THE TEL#AND EXT,THATS WHAT THE PERSON AT THAT TEL#SAID ROBERT.L
	Not reported

Material:

Site ID:	302888
Operable Unit ID:	830684
Operable Unit:	01
Material ID:	543525
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	302889
Spill Number/Closed Date:	9312206 / 1/17/1994
Spill Date:	1/17/1994
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1/17/1994
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1/17/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/20/1994
Spill Record Last Update:	8/28/2003
Spiller Name:	Not reported
Spiller Company:	222 MORGAN AVENUE

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Spiller Address:	222 MORGAN AVENUE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244717
DEC Memo:	Not reported
Remarks:	FIRE @ PLANT NOTIFIED DEP, UNK. ACTIONS. 11/18 UPDATE ROBERT KEPICH / DEP 595-6777 / 50-60 GAL DIESSEL HYDRAULIC NO CALL BACK. 100PM SPOKE TO ENZO HE SAID FIRE DIESSEL HYDRAULIC OIL P/U DISPOSE INDRUM

Material:

Site ID:	302889
Operable Unit ID:	990817
Operable Unit:	01
Material ID:	391198
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AX176 **NY MATERIALS REC (NY CART** **NY RGA LF** **S114959734**
ESE **222 MORGAN AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.414 mi.
2188 ft. **Site 4 of 5 in cluster AX**

Relative: RGA LF:
Lower

1997	NY MATERIALS REC (NY CART	222 MORGAN AVENUE	

Actual:
14 ft.

AX177 **EASTERN TRANSFER** **NY RGA LF** **S114956531**
ESE **222 MORGAN AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.414 mi.
2188 ft. **Site 5 of 5 in cluster AX**

Relative: RGA LF:
Lower

2000	EASTERN TRANSFER	222 MORGAN AVENUE	

Actual:
14 ft.

AW178 **CITY BARREL** **NY HSWDS** **S108146441**
NW **421 MEEKER STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11222**
0.415 mi.
2191 ft. **Site 2 of 3 in cluster AW**

Relative:
Lower

Actual:
17 ft.

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	None
Owner Type:	Puplic
Owner:	Harry Goldstein
Owner Address:	421 Meeker St.
Owner Phone:	(212)388-9227
Operator Type:	Same
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD068298835
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	None
RCRA Permitted:	Unknown
Site Code:	Industrial Site
Owner City State:	Brooklyn, NY 11222
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 43’15"N
Longitude:	73 56’30"W
Acres:	0.00
Operator Date:	1940
Close Date:	Unknown
Completed:	PA
Active:	Unknown
PCB’s Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	None
Surface Water Contamination:	No
Surface Water Body Class:	Unknown
Groundwater Contamination:	No
Groundwater Classification:	Unknown
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	No
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown

CITY BARREL (Continued) **S108146441**

Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AW179 **CITY BARREL & DRUM CO INC** **CERC-NFRAP** **1015735637**
NW **421 MEEKER AVE** **RCRA NonGen / NLR** **NYD068298835**
1/4-1/2 **BROOKLYN, NY 11222**
0.415 mi.
2191 ft. **Site 3 of 3 in cluster AW**

Relative:
Lower

Actual:
17 ft.

CERC-NFRAP:

Site ID:	0201593
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assessment History:

Action:	PRELIMINARY ASSESSMENT
Date Started:	/ /
Date Completed:	09/02/87
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information
Action:	ARCHIVE SITE
Date Started:	/ /
Date Completed:	09/02/87
Priority Level:	Not reported
Action:	DISCOVERY
Date Started:	/ /
Date Completed:	04/25/80

CITY BARREL & DRUM CO INC (Continued) **1015735637**

Priority Level: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: CITY BARREL & DRUM CO INC
Facility address: 421 MEEKER AVE
BROOKLYN, NY 11222
EPA ID: NYD068298835
Mailing address: MEEKER AVE
BROOKLYN, NY 11222
Contact: HARRY GOLDSTEIN
Contact address: MEEKER AVE
BROOKLYN, NY 11222
Contact country: US
Contact telephone: (201) 388-9227
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HARRY GOLDSTEIN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: HARRY GOLDSTEIN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

CITY BARREL & DRUM CO INC (Continued) **1015735637**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CITY BARREL & DRUM CO INC
Classification: Not a generator, verified

Date form received by agency: 11/28/1980
Site name: CITY BARREL & DRUM CO INC
Classification: Unverified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/15/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

AY180 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100346426**
East **1105 METROPOLITAN AV** **N/A**
1/4-1/2 **NYC, NY**
0.416 mi.
2195 ft. **Site 1 of 2 in cluster AY**

Relative:
Lower

Actual:
11 ft.

LTANKS:
Site ID: 183945
Spill Number/Closed Date: 8802460 / 3/5/2003
Spill Date: 6/17/1988
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 6/17/1988
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 6/24/1988
Spill Record Last Update: 3/18/2003
Spiller Name: CONTACT JOE
Spiller Company: STERLING OPTICAL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001

CLOSED-LACKOF RECENT INFO (Continued) **S100346426**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	153958
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ADMIN.CLOSED" / / : Replace Vent Line, Empty Tank & Retest. 03/05/2003- Closed Due To The Nature / Extent Of The Spill Report
Remarks:	L R =-20 GPH. NEVER STABILIZED 7.5K TANK.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS.

Material:

Site ID:	183945
Operable Unit ID:	919680
Operable Unit:	01
Material ID:	458025
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	183945
Spill Tank Test:	1534139
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

AY181 **1101 METROPOLITAN AVE** **NY LTANKS** **S103238306**
East **1101 METROPOLITAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.425 mi.
2245 ft. **Site 2 of 2 in cluster AY**

Relative:
Lower

Actual:
8 ft.

LTANKS:

Site ID:	190461
Spill Number/Closed Date:	9800642 / 5/17/2006
Spill Date:	4/15/1998
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	SIGONA

1101 METROPOLITAN AVE (Continued) **S103238306**

Referred To:	Not reported
Reported to Dept:	4/15/1998
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/15/1998
Spill Record Last Update:	5/17/2006
Spiller Name:	USA TANKS
Spiller Company:	1101 METROPOLITIAN AVE
Spiller Address:	1101 METROPOLITIAN AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	USA TANKS
Spiller Phone:	(718) 384-9151
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	158882
DEC Memo:	5/17/06 - Mike - PBS# 2-109932 Tank was closed in place. Only one tank exsisted at site, Spill Report suggests tank #2 failed but there is no #2 tank. Occupant has documentation for proper closing and of no contamination. March 20, 2006 - have not worked on this spill to date - Jones Next Step - establish contact with site owner as per spill report.
Remarks:	TESTED TANK.TANK FAILED.

Material:

Site ID:	190461
Operable Unit ID:	1061125
Operable Unit:	01
Material ID:	322598
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	190461
Spill Tank Test:	1545783
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

182
SSW
1/4-1/2
0.426 mi.
2249 ft.

WILLIAMSBURG HOUSES
125 STAGG WALK
BROOKLYN, NY

NY LTANKS
NY Spills

S102672842
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:

Site ID:	204507
Spill Number/Closed Date:	9810259 / 1/8/2004
Spill Date:	11/13/1998
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	11/13/1998
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/13/1998
Spill Record Last Update:	3/4/2005
Spiller Name:	PAUL GOLDSTEIN
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller County:	001
Spiller Contact:	PAUL GOLDSTEIN
Spiller Phone:	(212) 306-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	170013
DEC Memo:	Not reported
Remarks:	TANKS TO BE EMPTIED AND INVESTIGATED

Material:

Site ID:	204507
Operable Unit ID:	1071172
Operable Unit:	01
Material ID:	314127
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

WILLIAMSBURG HOUSES (Continued) **S102672842**

Site ID:	204507
Spill Tank Test:	1546531
Tank Number:	1
Tank Size:	20000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

Site ID:	204508
Spill Number/Closed Date:	9810261 / 1/8/2004
Spill Date:	11/13/1998
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	11/13/1998
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/13/1998
Spill Record Last Update:	3/14/2005
Spiller Name:	PAUL GOLDSTEIN
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller County:	001
Spiller Contact:	PAUL GOLDSTEIN
Spiller Phone:	(212) 306-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	170013
DEC Memo:	Not reported
Remarks:	TANK TO BE EMPTIED AND INVESTIGATED.

Material:

Site ID:	204508
Operable Unit ID:	1071175
Operable Unit:	01
Material ID:	314128
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0

WILLIAMSBURG HOUSES (Continued) **S102672842**

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 204508
Spill Tank Test: 1546532
Tank Number: 2
Tank Size: 20000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

Site ID: 204509
Spill Number/Closed Date: 9811727 / 3/29/1999
Spill Date: 12/17/1998
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SACCACIO
Referred To: Not reported
Reported to Dept: 12/17/1998
CID: 366
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/17/1998
Spill Record Last Update: 3/29/1999
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY 10007-
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 170013
DEC Memo: Not reported
Remarks: ISOLATE AND RETEST.

Material:
Site ID: 204509
Operable Unit ID: 1072529

WILLIAMSBURG HOUSES (Continued) **S102672842**

Operable Unit: 01
Material ID: 312013
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 204509
Spill Tank Test: 1546664
Tank Number: 1
Tank Size: 20000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

Site ID: 187018
Spill Number/Closed Date: 9811227 / 12/2/2005
Spill Date: 12/7/1998
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 12/7/1998
CID: 312
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/7/1998
Spill Record Last Update: 12/2/2005
Spiller Name: SEBASTIAN LOREFICE
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 170013

WILLIAMSBURG HOUSES (Continued) **S102672842**

DEC Memo: 12/02/05: This spill transferred from J.Kolleeny to S.Kraszewski.Closed to consolidate with open spill #0102133.
Remarks: ISOLATE AND RETEST

Material:
Site ID: 187018
Operable Unit ID: 1072088
Operable Unit: 01
Material ID: 315074
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 187018
Spill Tank Test: 1546605
Tank Number: 002
Tank Size: 20000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 0102133
Facility Type: ER
DER Facility ID: 170013
Site ID: 313516
DEC Region: 2
Spill Date: 5/25/2001
Spill Number/Closed Date: 0102133 / 11/18/2014
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: jkkann
Referred To: Not reported
Reported to Dept: 5/25/2001
CID: 211
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

WILLIAMSBURG HOUSES (Continued) **S102672842**

Remediation Phase:	0
Date Entered In Computer:	5/25/2001
Spill Record Last Update:	11/18/2014
Spiller Name:	JOHN TOMKIN
Spiller Company:	NEW YORK CITY HOUSING AUT
Spiller Address:	123 WILLIAMS
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller Company:	001
Contact Name:	JOHN TOMKIN
Contact Phone:	(718) 566-8960
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BREEN"11/09/05: Joel Rogers, P.E. from Gannett Fleming sent request letter dated June 23, 2005 for elvaluation of Site Investigation Work Plan dated Jan. 13, 2004. Jon sent approval for Site Investigation Work Plan on Feb. 4 2005 to NYCHA. I spoke with Joel, he never recieved approval letter possibly because Steve Saccacio from NYCHA transferred from his position around the time Jon submitted his approval. I spoke with Ralph Trocchio at NYCHA, he said he would look into it. - SKThis spill transferred from J.Kolleeny to S.Kraszewski.11/22/05: Message from Joel Rogers, says he still hasn't recieved approval for work plan. Faxed him copy of approval. - SK02/06/07 - J.Kann - site reassigned from S. Kraszewski to J.Kann.11/18/14: J.Kann - Reviewed original tank closure report prepared by UTB. SVOC and VOC constituents in the endpoints samples are all below CP-51 Fuel Oil Guidance. NFA. NYCHA will be informed of spill closure.
Remarks:	CALLER DID TANK REMOVAL AND SOIL SAMPLE TAKEN SHOWED CONTAMINATION. See 9811727, 9810261, 9810259 and 9415279.

Material:

Site ID:	313516
Operable Unit ID:	840958
Operable Unit:	01
Material ID:	534258
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9415279
Facility Type:	ER
DER Facility ID:	170013
Site ID:	204506
DEC Region:	2
Spill Date:	2/22/1995
Spill Number/Closed Date:	9415279 / 4/3/1995
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

WILLIAMSBURG HOUSES (Continued) **S102672842**

SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	2/22/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	4/3/1995
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/22/1995
Spill Record Last Update:	4/3/1995
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	STEAM PRE-HEATER LEAKING FROM BROKEN VALVE. WINSTON TO CLEAN UP.

Material:

Site ID:	204506
Operable Unit ID:	1012595
Operable Unit:	01
Material ID:	370459
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75
Units:	Gallons
Recovered:	75
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	204506
Operable Unit ID:	1012595
Operable Unit:	01
Material ID:	370460
Material Code:	0012A
Material Name:	Kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

183 NNW 1/4-1/2 0.427 mi. 2257 ft.

MOBIL OIL CORP SS #FX9
550 HUMBOLDT ST
BROOKLYN, NY 11222

RCRA NonGen / NLR
NY LTANKS
NY UST
NY Spills

1000553844
NYD986962785

Relative: Lower

Actual: 23 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MOBIL OIL CORP SS #FX9
Facility address:	550 HUMBOLDT ST BROOKLYN, NY 112224902
EPA ID:	NYD986962785
Mailing address:	GALLOWS RD - MKTG ENVIRON FAIRFAX, NY 220370001
Contact:	Not reported
Contact address:	GALLOWS RD - MKTG ENVIRON FAIRFAX, NY 220370001
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	(703) 849-3330
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	(703) 849-3330
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MOBIL OIL CORP SS #FX9
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MOBIL OIL CORP SS #FX9
Classification: Not a generator, verified

Date form received by agency: 04/10/1991
Site name: MOBIL OIL CORP SS #FX9
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

LTANKS:
Site ID: 59273
Spill Number/Closed Date: 9007766 / Not Reported
Spill Date: 10/16/1990
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: MJHAGGER
Referred To: Not reported
Reported to Dept: 10/16/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 4
Date Entered In Computer: 10/31/1990
Spill Record Last Update: 5/23/2014
Spiller Name: MELISSA TACCHINO
Spiller Company: EXXONMOBIL OIL CORP
Spiller Address: 1545 ROUTE 22 EAST
Spiller City,St,Zip: ANNANDALE, NJ 08801
Spiller County: 001
Spiller Contact: Not reported

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 301050
DEC Memo: Spill remediation is being tracked under spill no. 90-07766. See also spill nos. 05-08671 and 07-10898.11/6/2000: Reassigned from Sullivan to Sigona. PBS records indicate that 14 x 550-gallon, 1 x 4,000-gallon and 1 x 1,000-gallon USTs were either closed in-place or removed from this site. (Sigona)12/12/2003: Reassigned from Roberts to Harrington (central office) for management. (Rommel)5/6/2005: Sent letter to Exxon Mobil approving off-site RI work plan. (Harrington)7/18/2005: Sent letter to Exxon Mobil approving revised RAP. EFR events @ MW-3 and MW-4 will be conducted semi-annually. FS to address dissolved BTEX @ MW-3 will be submitted along with off-site RI report. (Harrington)10/7/2005: Sent e-mail to Exxon Mobil approving the sensitive receptor survey. (Harrington)11/28/2005: Sent Exxon Mobil letters approving the SI report and the supplemental SI work plan for the off-site plume delineation. Additional work was required due to the discovery of free product west of McGuinness Boulevard. (Harrington)7/31/2006: Approved supplemental SI report. Monthly EFR events will now be conducted at wells MW-3, MW-4, MW-11, MW-12, and MW-15A. Work plan for recovery well installation near MW-15 is expected in October. (Harrington)10/14/2006: Sent an e-mail to Exxon Mobil approving the SI work plan. Plan calls for the installation of six (6) monitoring wells along the west side of McGuinness Boulevard between Bayard and Newton Streets in order to fully delineate and recover the free product observed in this area. (Harrington)3/2/2007: Sent e-mail to Exxon Mobil approving the UST divestiture and excavation work plan. EM will be removing all USTs, distribution lines, vent lines, hydraulic lifts, and contaminated soil identified during this effort. (Harrington)4/20/2007: Sent e-mail to Exxon Mobil approving the SI report which documented the off-site work completed along McGuiness Boulevard in support of LPH recovery efforts. (Harrington)6/22/2007: PM visited the site along with Kleinfelder personnel. Excavation work has been completed. Report expected in the Fall. (Harrington)10/29/2007: Sent e-mail to Exxon Mobil approving the Tank Excavation Assessment Report. The revised RAP will be submitted in mid-December. (Harrington)12/4/2007: PM approved the feasibility testing work plan during a site visit with Kleinfelder personnel. SVE/AS and chem-ox injection technologies will be evaluated. (Harrington)12/13/2007: PM conducted a site visit during monitoring well installation as part of the recently-approved FS work plan. Field work began on December 10th. (Harrington)1/15/2008: Kleinfelder encountered LPH in a newly-installed monitoring well on-site during pilot testing efforts. Kleinfelder personnel contacted the PM, who instructed them to call it in as a spill. The spill number (07-10898) was administratively closed by Region 2 personnel. (Harrington)5/1/2008: PM sent an e-mail to Exxon Mobil approving the off-site subsurface investigation work plan. This effort will begin to fully delineate the free-product plume west of McGuinness Boulevard. (Harrington)5/6/2008: PM conducted a site meeting with Exxon Mobil's consultant (Kleinfelder East, Inc.). During the meeting, the PM approved the IRM work plan, which calls for excavation of soils in the area of the former dispenser islands. Given that this area is adjacent to McGuinness Boulevard, sheeting and shoring will be required. (Harrington)6/24/2008: PM conducted a site visit with Exxon Mobil

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

personnel (Drake) and their consultant (Kleinfelder) in order to discuss recent developments. Apparently, Exxon Mobil has been denied further access to the site by the owner thus delaying implementation of the IRM. Additional off-site investigation will be required due to the continued presence of LPH along McGuinness Boulevard. This will involve well installation further west along Newton Street. (Harrington)9/7/2008: PM sent an e-mail to Exxon Mobil approving the updated version of the IRM work plan. Work plan calls for additional excavation of petroleum-contaminated soils on-site and post-excavation sampling. Work is scheduled to begin on September 15th. (Harrington)4/3/09 - Haggerty: approved Excavation Report. With this excavation, over 7000 tons of contaminated soil has been removed from the site. My comments were as follows:1. A "No Further Action" letter can not be granted for just the on-site soils. If the replacement monitoring wells are installed and groundwater meets with DEC approval, a "No Further Action" letter will be issued for the spill 90-07766 and I will re-open spill 05-08671 for the off-site contamination.2. Resend the Off-Site Investigation Work Plan under a separate cover. Dave Harrington disregarded the 8/29/08 RRAP and therefore I have not been able to review the work plan contained therein. After I have approved it, I will forward the DOT sidewalk permit letter.3. I have spoken with the Developer's consultant. The Developer's consultant, George Kavrakis, states the layout of the station has been approved and is not subject to change. Therefore, proceed with the installation of the on-site replacement wells within the next 60 days. I also informed him that if the monitoring wells are damaged during the construction of the new station, it will be their responsibility to re-install them. I have attached the site plan for the new station which appears to match the layout provided in your report. 4. I spoke with the BEST Squad Demolition Supervisor who was holding up the redevelopment at the property and wrote him a letter (attached) requesting he allow redevelopment to begin. Once he receives the letter, he states construction can proceed. According to George Kavrakis, once they receive permission from the BEST Squad, construction will begin. Please coordinate with Mr. Kavrakis (516 298 2355)6/19/09 - Haggerty: had conference call with Ken Drake (ExxonMobil) and Kleinfelder. New station under construction and will not be completed for the next month. Installation of on-site and off-site MW's will be completed at the same time once construction of the new station is complete.June 2010 - required additional delineation of MTBE plumeAugust 2010 - received Supplemental Subsurface Investigation Work Plan. Under review11-4-10 - Austin - Had a discussion with Sally Dewes of DEC/Albany - Sampling at this site recently yielded the discovery of ethanol, indicating that there may be a new release on this site - we agreed that this would be called in as a new spill report, for investigation by Region 2 Spills - endMarch 2011 - reviewed SIR and sent comment email requiring work plan to remediate off-site LPH. EFR events over the past 3 years have not reduced LPH thicknessMay 2011 - Work plan overdueJune 2011 - approved plan to increase efficiency of LPH removal using HIT events. Also, the new owner had a Spill called in under the his name due to ethanol detectionsNovember 2011 - Feasibility Report due in DecemberDecember 2011 - Feasibility Report under reviewJanuary 2012 - using VER events. percent level vapors were being collected. Considering this is ~200ft for the site, it appears a plume of product has broken off for the source. Remedial alternatives being evaluatedMarch 2012 - met with new Project Manager, Heather Cloud,

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

from GES and discussed project. A plume of free product has broken off from the site and is slowly moving across Humboldt. We discussed the fact that the plume will be persistant for years. She requested 2 months to meet internally as to the next step. I told to look for a possible locations for a SVE system shed in the adjacent propertiesMay 2012 - nothing substantive regarding a solution has been proposed. Conference call required June 2012 - approved EMs soil boring/sampling work plan along McGuiness where the product has been consistant for yearsDecember 2012 - GES proposed excavating the sidewalk on McGuiness Blvd into the groundwater to remove the product beneath it. EM fully excavated the station and the remaining contamination has detached from the original site. This site requires more thought. Even if they did excavate the sidewalk which a don't believe the DOT would allow, more product will migrate below the sidewalk due to the groundwater flow directionOctober 2013 - approved EM work plan to perform 2 Dual-Phase Extraction events to determine the vapor mass in the subsurface. Groundwater is only 10fbg and free product is present near buildings with basementsApril 25, 2014: Haggerty - Conference call including: EM territory manager Laurie McCarthy, EM legal Counsel Andrew Torrent, EM consultant GES, OGC Scott Caruso, Jim Moras and PM. We discussed the fact that EM was not in compliance with the Consent Order over the past seven months. PM approved a work plan to perform 2 Dual-Phase Extraction events 9/24/13 to determine the vapor mass in the subsurface as well as to estimate how fast the vapor mass is rebounding. Only one DPE event was conducted and it took seven months to receive the report. As this point, it may be necessary to involve the DOH. EM scheduled another conference for a week later (5/2/14) with proposals to deal with the vapor mass as well as remediation of the Spill.May 2, 2014 - Haggerty - EM agreed to install SVE/AS system across McGuiness Blvd. at 179 Bayard Street. May 13, 2014 - Haggerty - approved revised CAP with supersedes the original CAP with the Consent Order. RAP due 7/2/14

Remarks: LINE TEST ONLY, PETRO TITE, LEAK RATE -.011GPH, WILL EXCAVATE, REPAIR & RETEST (REPAIRS BY ALVIN PETROLEUM).

Material:

Site ID:	59273
Operable Unit ID:	945056
Operable Unit:	01
Material ID:	431609
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	59273
Operable Unit ID:	945056
Operable Unit:	01
Material ID:	2106619
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True

Tank Test:
Site ID: 59273
Spill Tank Test: 1537714
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

UST:
Id/Status: 2-157295 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/01/2017
UTM X: 589161.48621
UTM Y: 4508307.6923900004
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 5199
Affiliation Type: Mail Contact
Company Name: BOLLA OPERATING CORP.
Contact Type: Not reported
Contact Name: CMS: MAILSTOP F-76
Address1: % GILBARCO VEEDER-ROOT
Address2: 7300 W. FRIENDLY AVE, MS F-76
City: GREENSBORO
State: NC
Zip Code: 27420
Country Code: 001
Phone: (800) 253-8054
EMail: CMS@GILBARCO.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/10/2013

Site Id: 5199
Affiliation Type: On-Site Operator
Company Name: BOLLA OPERATING CORP.
Contact Type: Not reported
Contact Name: STATION MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Country Code:	001
Phone:	(718) 389-2729
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/10/2013

Site Id:	5199
Affiliation Type:	Emergency Contact
Company Name:	BOLLA OPERATING CORP
Contact Type:	Not reported
Contact Name:	FMS SPILL RESPONSE HOTLINE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(800) 997-7725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/22/2012

Site Id:	5199
Affiliation Type:	Facility Owner
Company Name:	BOLLA OPERATING CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	809 STEWART AVE
Address2:	Not reported
City:	GARDEN CITY
State:	NY
Zip Code:	11530
Country Code:	001
Phone:	(516) 512-6125
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/10/2013

Tank Info:

Tank Number:	001
Tank ID:	29854
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1975
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 29855
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 29856
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 29857
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 005
Tank ID: 29858

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	006
Tank ID:	29859
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	007
Tank ID:	29860
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	008
Tank ID:	29861
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 009
Tank ID: 29862
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 010
Tank ID: 29863
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 011
Tank ID: 29864
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 012
Tank ID: 29865
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 013
Tank ID: 29866
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 12/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 014
Tank ID: 29867
Tank Status: Closed - Removed
Material Name: Closed - Removed

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	015
Tank ID:	29868
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	12/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank Number:	016
Tank ID:	227975
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	04/01/2009
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/10/2013

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	017
Tank ID:	227976
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	04/01/2009
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/10/2013

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	018
Tank ID:	227977
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	04/01/2009
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/10/2013

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	019

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank ID:	227978
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	04/01/2009
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/10/2013

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	100
Tank ID:	41992
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1988
Date Tank Closed:	04/24/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	10/22/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/16/2007

Equipment Records:

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 200
Tank ID: 41993
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1988
Date Tank Closed: 04/24/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 10/22/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/16/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 300
Tank ID: 41994
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1988
Date Tank Closed: 04/24/2007
Registered: True
Tank Location: Underground

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 10/06/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/16/2007

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 400
Tank ID: 41995
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1988
Date Tank Closed: 04/24/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 03/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/16/2007

Equipment Records:

B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 500
Tank ID: 41996
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1988
Date Tank Closed: 04/24/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/16/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 600
Tank ID: 41997
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 06/01/1988
Date Tank Closed: 04/24/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 01
Date Test: 03/01/1992
Next Test Date: Not reported
Pipe Model: F
Modified By: NRLOMBAR
Last Modified: 10/16/2007

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Equipment Records:

B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	600A
Tank ID:	56134
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	01/01/1988
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	05/21/2007

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G10 - Tank Secondary Containment - Impervious Underlayment (AG)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve

Tank Number:	700
Tank ID:	50672
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	06/01/1988
Date Tank Closed:	04/24/2007

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/16/2007

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

SPILLS:

Facility ID:	1011266
Facility Type:	ER
DER Facility ID:	399959
Site ID:	444909
DEC Region:	2
Spill Date:	2/9/2011
Spill Number/Closed Date:	1011266 / Not Reported
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Investigator:	AXDORONO
Referred To:	DATA IS DUE
Reported to Dept:	2/9/2011
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2/9/2011
Spill Record Last Update:	9/22/2014
Spiller Name:	Not reported
Spiller Company:	SUNOCO SERVICE STATION
Spiller Address:	Not reported
Spiller City,St,Zip:	NN

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Spiller Company: 001
Contact Name: VIKI CRETEUR
Contact Phone: Not reported
DEC Memo: This is a new spill at the site of an old ongoing spill case. A newly called in spill number usually means there is a new owner/operator. The old owner is cleaning up the old case and does not want to be held responsible for the new spill.Cross Ref Spill #9007766. Call Kleinfelder to determine why this is a new spill and what is being done to clean it up.3/11/11-Called Kleinfelder and left a message to the operator to call back.Case Manager: Viki Creteur (631 281 0612 Ext 220)10/27/11 - Austin - Transferring this case from Ahmed to Ketani - end07/11/2013 - Case is transferred from Ketani (Section C) to Feng (Section of Spill Prevention and Response) as per DER Region 2 decision. V. Brevdo06/27/2014: This spill case was transferred to A. Doronova. - AD08/05/2014: Sent the following e-mail to Sunoco contact - Russell Hammond (e-mail: rhammond@sunocoinc.com) and copied to Anthony Fiorentine (afiorentine@cg-env.com):"Dear Mr. Hammond: My name is Ainura Doronova. I am a NYSDEC project manager for the following spill cases, which were recently transferred to me: 1. Spill No. 1011266, 550 Humbolt Street, Brooklyn;2. Spill No. 0913725, 1626 Steelwell Avenue, Brooklyn;3. Spill No. 0809869, 42-02 21st Streeet, Queens;4. Spill No. 0708451, 972 Remsen Avenue, Brooklyn;5. Spill No. 0502868, 1781 Bay Ridge Parkway, Brooklyn;6. Spill No. 0407558, 5 Flatbush Avenue, Brooklyn;7. Spill No. 0304033, 805 65th Street, Brooklyn;8. Spill No. 9909665, 175-33, Horace Harding Expressway, Queens;9. Spill No. 9900619, 1650 Forest Avenue, Staten Island;10. Spill No. 9808686, 188-06 Hillside Avenue, Queens;11. Spill No. 9711173, 2310 Tillotson Avenue, Bronx;12. Spill No. 9609282, 1781 Arthur Kill Rd., Staten Island;13. Spill No. 9501327, 2701 Knapp Stret, Brooklyn;14. Spill No. 8905358, 32-32 Queens Boulevard, New York;15. Spill No. 8904831, 38-15 Queens Boulevard, Queens;16. Spill No. 8904151, 161-15 46th Avenue, New York;17. Spill No. 8808987, 135-45 Cross Bay Boulevard, Queens;18. Spill No. 8706272. 2052 Victory Boulevard, Staten Island. From now on, please submit all your future documentation (letters, reports, work plans, RAPs) related to these spill cases to my attention. Please note, that you should submit one hard copy of the document (report/work plan) and e-copy on a CD by regular mail. Please, do not submit large size documents via e-mail, since we have limited storage capacity, so it should be used only for correspondence. Feel free to contact me if you have any questions. Thank you. Sincerely, Ainura DoronovaEnvironmental Engineer 1Division of Environmental RemediationNYS Department of Environmental ConservationRegion 2(718) 482-6453"AD
Remarks: test data show NEW release/9007766

Material:
Site ID: 444909
Operable Unit ID: 1195345
Operable Unit: 01
Material ID: 2191417
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0508671
Facility Type:	ER
DER Facility ID:	301050
Site ID:	354303
DEC Region:	2
Spill Date:	10/19/2005
Spill Number/Closed Date:	0508671 / 12/22/2006
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	DKHARRIN
Referred To:	Not reported
Reported to Dept:	10/19/2005
CID:	407
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/19/2005
Spill Record Last Update:	12/22/2006
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CHRISTINE CAMARDELLA
Contact Phone:	(631) 218-0612
DEC Memo:	12/22/2006: Consolidated under spill no. 90-07766. (Harrington)
Remarks:	notified dave harrington of this spill, sampling shows contamination.

Material:

Site ID:	354303
Operable Unit ID:	1111723
Operable Unit:	01
Material ID:	2101771
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

MOBIL OIL CORP SS #FX9 (Continued) **1000553844**

Tank Test:

184
ESE
1/4-1/2
0.437 mi.
2307 ft.

APT BUILDING TANK **NY LTANKS** **S106972250**
85 MEADOW STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
14 ft.

LTANKS:

Site ID:	349596
Spill Number/Closed Date:	0504662 / 12/9/2005
Spill Date:	7/19/2005
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	7/19/2005
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/20/2005
Spill Record Last Update:	12/9/2005
Spiller Name:	MR FRIEDMAN
Spiller Company:	GARAGE
Spiller Address:	84 MEADOW STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	MR FRIEDMAN
Spiller Phone:	(718) 614-1896
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	296031
DEC Memo:	Sangesland spoke to Vicky at Island Tank.This is a heating oil tank in the garage area of an apartment building.Island Tank is already doing the dig out and knows to take the end point samples. No Tank Test Failure or Contaminated Soil letter was sent.09.22.05 SR// Sharif spoke with Mr. Friedman . He informed me Island Tank took care of the problem. I tried to hold Vicky but not able. 12/09/05-Sharif// I rec'd report prepared by Island Tank.The UST was 3000 gallons and was removed from the property as clean scrap metal.Six end point samples were taken from the UST cavity. Approx. 26 yards of contaminated soil was removed from the hole.Soil analytical result came back almost clean with no significant contaminants left at the site.Disposal manifests are provided. NFA action required.
Remarks:	LINES ON 3000 GALLON TANK ARE ROTTED AND THEY NEED TO REMOVE SOME CONTAMINATED SOIL

APT BUILDING TANK (Continued) **S106972250**

Material:

Site ID:	349596
Operable Unit ID:	1107185
Operable Unit:	01
Material ID:	2097080
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

185
South
1/4-1/2
0.440 mi.
2321 ft.

Relative:
Higher

Actual:
42 ft.

SPILL NUMBER 0003338 **NY LTANKS** **S104621153**
232 MESROLE ST **N/A**
BROOKLYN, NY

LTANKS:

Site ID:	202905
Spill Number/Closed Date:	0003338 / 4/10/2003
Spill Date:	6/17/2000
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	6/17/2000
CID:	281
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/17/2000
Spill Record Last Update:	4/10/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	ZOLA BAILEY
Spiller Phone:	(718) 595-6700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	168762

SPILL NUMBER 0003338 (Continued) **S104621153**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"HANDLED BY DEP AND FDNY.
Remarks: TANK OVERFILL AT ABOVE LOCATION. FIRE DEPT ON SCENE. ATTEMPTSARE BEING MADE TO DETERMINE THE OIL COMPANY RESPONSIBLE. NO CALL BACK BEING REQUESTED AT TIME OF CALL.

Material:
Site ID: 202905
Operable Unit ID: 824732
Operable Unit: 01
Material ID: 551660
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AZ186 **FORMER KLINK COSMO CLEANERS** **NY SHWS** **S109416412**
NNE **364 RICHARDSON STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11222**
0.441 mi.
2330 ft. **Site 1 of 2 in cluster AZ**

Relative:
Higher

Actual:
38 ft.

SHWS:
Program: HW
Site Code: 405851
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 1.080
HW Code: 224130
Record Add: 10/28/2008
Record Upd: 03/02/2015
Updated By: JAMORAS
Site Description: Location:The site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the southwest corner of the intersection of Vandervoort Avenue and Richardson Street. Site Features:The site is completely covered by a one-story brick building. Numerous other commercial and industrial properties are located to the north, south, and west of the site. The Greenpoint Little League fields and a National Grid energy facility are east of the site across Vandervoort Avenue. A small residential area is located 1-2 blocks north of the site. An eastbound on-ramp to the Brooklyn-Queens Expressway (I-278) is located 4 blocks to the north.Current Zoning/Use(s):The site is zoned for manufacturing. The site is currently used for sheet metal fabrication.Historical Use(s):The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This

FORMER KLINK COSMO CLEANERS (Continued) **S109416412**

particular location was specifically targeted for investigation based on interviews with multiple residents indicating the sites former usage as a commercial dry cleaner from the 1950's to the mid 1990's (including one former employee), and a Department database which lists the cleaners as a generator of F002 waste (spent halogenated solvents). This investigation was conducted in several phases, and was completed in the Summer of 2009.Site Geology and Hydrogeology:The site is underlain by a fill unit (0.5-8' thick), a sand/silty sand unit (~100' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit, a sand and gravel unit (~1-3' thick), and the Raritan Formation (located 108-113' below ground surface).Groundwater is approximately 24-50' below ground surface in the vicinity of the site. Groundwater flows north to northeast toward Newtown Creek, which lies approximately 3,000' northeast of the site.

Env Problem:	Nature and Extent of Contamination:- GroundwaterThe primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been found in shallow groundwater at concentrations up to 46,000 ppb, which is well above the Part 703.5 class GA standard of 5 ppb. PCE has also been found in very deep groundwater (atop the Raritan clay) at 4,500 ppb. The plume of PCE-contaminated groundwater has migrated at least 1,200' downgradient of the site. - Soil VaporPCE has been found in soil vapor beneath the site at concentrations up to 48,200,000 ug/m^3. TCE has been found at concentrations up to 230,000 ug/m^3.Significant Threat:The site poses a significant environmental threat due to ongoing releases of PCE from source areas into soil and groundwater.
Health Problem:	Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area anddata evaluated as they become available.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/28/2008 12:21:00 PM
Record Upd:	10/29/2013 11:18:00 AM
Updated By:	ldennist
Own Op:	Owner
Sub Type:	01
Owner Name:	PAVLOVICH & COMPANY
Owner Company:	PAVLOVICH & COMPANY
Owner Address:	460 MORGAN AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222-5706
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	08
Owner Name:	Not reported
Owner Company:	AWL Industries
Owner Address:	364 Richardson Street

FORMER KLINK COSMO CLEANERS (Continued) **S109416412**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Greenpoint Branch
Owner Address:	107 Norman Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
HW Code:	224130
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224121
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	8/26/2009 4:51:00 PM
Record Updated:	8/26/2009 4:51:00 PM
Updated By:	dkharrin
Crossref ID:	224129
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	10/31/2008 2:34:00 PM
Record Updated:	10/31/2008 2:34:00 PM
Updated By:	MOBARRIE
Crossref ID:	224131
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	10/31/2008 2:41:00 PM
Record Updated:	10/31/2008 2:41:00 PM
Updated By:	MOBARRIE
Crossref ID:	224132
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	10/31/2008 2:41:00 PM
Record Updated:	10/31/2008 2:41:00 PM
Updated By:	MOBARRIE

AZ187 **FORMER KLINK COSMO CLEANERS** **NY RGA HWS** **S114963909**
NNE **364 RICHARDSON STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.441 mi.
2330 ft. **Site 2 of 2 in cluster AZ**

Relative: **Higher**

Actual: **38 ft.**

RGA HWS:

2012	FORMER KLINK COSMO CLEANERS	364 RICHARDSON STREET
2011	FORMER KLINK COSMO CLEANERS	364 RICHARDSON STREET
2010	FORMER KLINK COSMO CLEANERS	364 RICHARDSON STREET
2009	FORMER KLINK COSMO CLEANERS	364 RICHARDSON STREET

BA188 **FONTANA TRANSFER STATION** **NY SWF/LF** **S105841907**
ENE **252 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.443 mi.
2337 ft. **Site 1 of 2 in cluster BA**

Relative: **Lower**

Actual: **13 ft.**

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	7183847727
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	JACK BORDORE; OWNER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W52]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6101-00067
Authorization Date:	Not reported
Expiration Date:	Not reported

BA189 **FONTANA TRANSFER STATION** **NY RGA LF** **S114956927**
ENE **252 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.443 mi.
2337 ft. **Site 2 of 2 in cluster BA**

Relative: **Lower**

Actual: **13 ft.**

RGA LF:

2012	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2011	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2010	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2009	FONTANA TRANSFER STATION	252 MASPETH AVENUE

FONTANA TRANSFER STATION (Continued) **S114956927**

2008	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2007	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2006	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2005	FONTANA TRANSFER STATION	252 MASPETH AVENUE
2004	FONTANA TRANSFER STATION	252 MASPETH AVENUE

---

190 **COMMERCIAL PROPERTY** **NY LTANKS** **S105998592**
SSE **1-7 BUSHWICK PLACE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.449 mi.
2370 ft.

Relative:
Higher

Actual:
38 ft.

LTANKS:

Site ID:	80495
Spill Number/Closed Date:	0300112 / 3/24/2004
Spill Date:	4/2/2003
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	4/3/2003
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/3/2003
Spill Record Last Update:	3/24/2004
Spiller Name:	BRUCE FIFFER
Spiller Company:	1-7 BUSHWICK PL
Spiller Address:	1-7 BUSHWICK PL
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	172718
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"Cross Ref Spill #0311991CALLED BRUCE FEFFER, WHO CONFIRMED TANK TEST FAILURE. REQUEST TANK TEST FAILURE LETTER BE ADDRESSED TO HIM, AT 61 BROADWAY SUITE # 1050 NEW YORK, NY 10006Called Marc Ricciardi, who confirm tank test failure. However could not say whether tank is registered. Did give on- site contact person as Steffen, # (516) 790-5535.Tank Test failure letter was sent to BRUCE FEFFER, ON 4/3/2003.PSThis tank is UNREGISTERED,Application Form was sent, so that tank can be REGISTERED. E.R.10/15/2003 Charlie Schmidgall of Aggressive Envir.5,000 gal Tank will be pulled within 60 days and DEC asked for 4 sidewall and 2 bottom samples.3/24/2004 Sangesland spoke to Carla Weinpahl of ERM (212-447-1900) She said the client dropped Aggressive Environmental and switched over to ERM in late January 2004. Ms. Weinpahl stated that Aggressive had pulled the

COMMERCIAL PROPERTY (Continued) **S105998592**

tank, did one round of samples, pulled more soil and did another round of samples. Results show some exceedences of PAH (SVOCs), but the argument is made that this is consistant with industrial fill in this part of Brooklyn. The DEC reviewed these numbers and compared them to the RSCO values on TAGM 4046. Based on this information and the present site use, the spill number 0300112 associated with the petroleum spill from the tank is closed out.Spill number 0311991 was associated with contamination found in another portion of the property. Organic Compounds identified as Chlorinated Solvents and Pesticides were found in sample R3656.Based on DEC Policy, the property owner and/or their consultant is directed to the state Brownfield Program."Not a spill report - property owner and/or consultant is referred to the Brownfield Cleanup Program website for futher information in having the DEC review the results from this site investigation"See www.dec.state.ny.us/website/der/bcp/

Remarks: Not reported

Material:

Site ID:	80495
Operable Unit ID:	868416
Operable Unit:	01
Material ID:	508188
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	80495
Spill Tank Test:	1528229
Tank Number:	1
Tank Size:	5000
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

SPILLS:

Facility ID:	0311991
Facility Type:	ER
DER Facility ID:	172718
Site ID:	208165
DEC Region:	2
Spill Date:	1/26/2004
Spill Number/Closed Date:	0311991 / 3/24/2004
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party.

COMMERCIAL PROPERTY (Continued) **S105998592**

	Corrective action taken.
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1/26/2004
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/26/2004
Spill Record Last Update:	3/24/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	BRUCE FEFFER
Contact Phone:	(212) 269-7343
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"1/26/2004 Sangesland spoke to Charlie Schmidgall of Agressive Environmental. There was a tank on one side of the property that failed a tank test (see spill #0300112). This tank was registered and then pulled.After tank pull, minor oil contamination was found and removed.New problem appears to be heavy pesticides & solvents found in endpoints. 253 tons of soil have been pulled.PERC is present along with a hit for Dichlorobenzene (28,000ppb)There is no history of dry cleaners at/near the site, also no history of solvents.Sangesland spoke to Austin who said that there may have been a lab mixup. He suggested that another round of samples may be appropriate. This message was left on Agressive Environmental's answering machine. 3/24/2004 Sangesland spoke to Carla Weinpahl of ERM (212-447-1900) She said the client dropped Aggressive Environmental and switched over to ERM in late January 2004. Ms. Weinpahl stated that Aggressive had pulled the tank, did one round of samples, pulled more soil and did another round of samples. Results show some exceedences of PAH (SVOCs), but the argument is made that this is consistant with industrial fill in this part of Brooklyn. The DEC reviewed these numbers and compared them to the RSCO values on TAGM 4046. Based on this information and the present site use, the spill number 0300112 associated with the petroleum spill from the tank is closed out.Spill number 0311991 was associated with contamination found in another portion of the property. Organic Compounds identified as Chlorinated Solvents and Pesticides were found in sample R3656.Based on DEC Policy, the property owner and/or their consultant is directed to the state Brownfield Program:"Not a spill report - property owner and/or consultant is referred to the Brownfield Cleanup Program website for further information in having the DEC review the results from this site investigation"See: www.dec.state.ny.us/website/der/bcp/
Remarks:	an unknow amount of pseticides and solents spilled. none of it has been cleaned up. it was detected in the stars soil sample labrotory

COMMERCIAL PROPERTY (Continued) **S105998592**

narrative.

Material:

Site ID:	208165
Operable Unit ID:	877222
Operable Unit:	01
Material ID:	497228
Material Code:	0057A
Material Name:	PESTICIDES
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	208165
Operable Unit ID:	877222
Operable Unit:	01
Material ID:	497229
Material Code:	0059A
Material Name:	SOLVENTS
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

BB191 **FRITO LAY** **NY ENG CONTROLS** **S109416391**
ESE **202-218 MORGAN AVENUE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY BROWNFIELDS**
0.460 mi.
2427 ft. **Site 1 of 5 in cluster BB**

Relative:
Lower

Actual:
14 ft.

ENG CONTROLS:

Site Code:	407689
HW Code:	C224133
Control Code:	22
Control Type:	ENG
Date Record Added:	10/22/2013
Date Rec Updated:	03/30/2015
Updated By:	CHPOST
Site Description:	Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal

FRITO LAY (Continued) **S109416391**

yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
HW Code: C224133
Control Code: 18
Control Type: ENG
Date Record Added: 10/22/2013
Date Rec Updated: 03/30/2015
Updated By: CHPOST
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site.

FRITO LAY (Continued) **S109416391**

Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
HW Code: C224133
Control Code: 13
Control Type: ENG
Date Record Added: 10/22/2013
Date Rec Updated: 03/30/2015
Updated By: CHPOST

Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

FRITO LAY (Continued) **S109416391**

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
HW Code: C224133
Control Code: 15
Control Type: ENG
Date Record Added: 10/22/2013
Date Rec Updated: 03/30/2015
Updated By: CHPOST
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.
Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.
Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and

FRITO LAY (Continued) **S109416391**

affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

INST CONTROL:
Site Code: 407689
Control Name: Ground Water Use Restriction
HW Code: C224133
Control Code: 08
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.
Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.
Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and

FRITO LAY (Continued) **S109416391**

occupied.

Site Code: 407689
Control Name: Landuse Restriction
HW Code: C224133
Control Code: 25
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.
Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.
Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: Soil Management Plan
HW Code: C224133
Control Code: 14

FRITO LAY (Continued) **S109416391**

Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.
Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.
Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: Site Management Plan
HW Code: C224133
Control Code: 32
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban

FRITO LAY (Continued) **S109416391**

area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: Monitoring Plan
HW Code: C224133
Control Code: 31
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing

FRITO LAY (Continued) **S109416391**

structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: IC/EC Plan
HW Code: C224133
Control Code: 34
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and

FRITO LAY (Continued) **S109416391**

the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: O&M Plan
HW Code: C224133
Control Code: 33
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689

Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site.

FRITO LAY (Continued) **S109416391**

Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

Site Code: 407689
Control Name: Environmental Easement
HW Code: C224133
Control Code: J
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 03/30/2015
Updated By: CHPOST
Site Code: 407689

Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to

FRITO LAY (Continued) **S109416391**

groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

BROWNFIELDS:

Program: BCP
Site Code: 407689
Acres: 2.760
HW Code: C224133
SWIS: 2401
Town: New York City
Update By: JEBROWN
Site Description: Location:The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features:The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures.Current Zoning and Land Use:The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site:The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination.Site Geology and Hydrogeology:The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel.

Env Problem: The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site.

Health Problem: The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that

FRITO LAY (Continued) **S109416391**

is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied.

BB192 **KARNAK (NEWTOWN METAL CORP.)** **NY RGA LF** **S114958241**
ESE **202 MORGAN AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.460 mi.
2427 ft. **Site 2 of 5 in cluster BB**

Relative:
Lower

Actual:
14 ft.

RGA LF:

2012	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2011	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2010	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2009	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2008	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2007	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2006	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2005	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE
2004	KARNAK (NEWTOWN METAL CORP.)	202 MORGAN AVENUE

BB193 **KARNAK (NEWTOWN METAL CORP.)** **NY SWF/LF** **S108635814**
ESE **202 MORGAN AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.460 mi.
2427 ft. **Site 3 of 5 in cluster BB**

Relative:
Lower

Actual:
14 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	7183660717
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	STANLEY K. HORNG
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T60]
Active:	No
East Coordinate:	589900
North Coordinate:	4507500
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported

KARNAK (NEWTOWN METAL CORP.) (Continued) **S108635814**

Authorization #: 2-6101-00015
Authorization Date: Not reported
Expiration Date: Not reported

SPILLS:

Facility ID:	0700119
Facility Type:	ER
DER Facility ID:	328885
Site ID:	379402
DEC Region:	2
Spill Date:	4/4/2007
Spill Number/Closed Date:	0700119 / 5/23/2007
Spill Cause:	Abandoned Drums
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	4/4/2007
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/4/2007
Spill Record Last Update:	5/23/2007
Spiller Name:	VICTOR LEE
Spiller Company:	ON SIDEWALK
Spiller Address:	202 MORGAN AV
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	VICTOR LEE
Contact Phone:	(646) 584-3544
DEC Memo:	add to next drum run05/23/07 Drum was not found on 05/22/07.
Remarks:	DRUM ON SIDEWALK NEEDS TO BE PICKED UP

Material:

Site ID:	379402
Operable Unit ID:	1136884
Operable Unit:	01
Material ID:	2126828
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

KARNAK (NEWTOWN METAL CORP.) (Continued) **S108635814**

Tank Test:

194
NW
1/4-1/2
0.462 mi.
2438 ft.

GAS STATION/ 278 FUEL STOP
392 LEONARD ST
BROOKLYN, NY 11211

NY LTANKS **S104648903**
NY Spills **N/A**

Relative:
Lower

Actual:
15 ft.

LTANKS:

Site ID:	246017
Spill Number/Closed Date:	0310672 / 12/16/2003
Spill Date:	12/16/2003
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	12/16/2003
CID:	444
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/16/2003
Spill Record Last Update:	12/16/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	ANNY
Spiller Phone:	(203) 876-7430
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	202028
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"
Remarks:	CALLER DOES NOT WISH TO GIVE HIS NAME, BUT STATES THAT THE GAS STAION IS POLLUTING THE SEWER BY A BROKEN HOSE OR OTHER, THEY ARE SWEEPING INTO THE SEWER SYSTEM. CALLER VERY CONCERNED.UNKNOWN AMOUNTS. WOULD LIKE SOMEONE TO COME CHECK OUT.

Material:

Site ID:	246017
Operable Unit ID:	878333
Operable Unit:	01
Material ID:	499520
Material Code:	0008
Material Name:	Diesel

GAS STATION/ 278 FUEL STOP (Continued) **S104648903**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPILLS:

Facility ID:	9900802
Facility Type:	ER
DER Facility ID:	202028
Site ID:	169686
DEC Region:	2
Spill Date:	4/21/1999
Spill Number/Closed Date:	9900802 / 8/10/1999
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	4/21/1999
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/21/1999
Spill Record Last Update:	12/16/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	392 LEONARD ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	UNKNOWN
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"5/19/99 SPOKE TO REED TUROFF (TRINITY CONSULTING - 718-257-8470) HE SAID THE OLD TANKS WERE PULLED IN APRIL. SINCE A PROBLEM WAS FOUND, NO NEW TANKS HAVE BEEN INSTALLED AND THE OWNER & OPERATOR ARE IN DISCUSSIONS AS TO WHO IS RESPONSIBLE AND WHAT WILL BE DONE. ACCORDING TO MR. TUROFF, THE OPERATORS ARE: KAY SINGH AND K. JANGI (718-388-3329). OWNERS ARE: DIMITRI (DAVID) SHTAIRMAN AND WALTER ROMANSKY (718-388-3464)7/28/99 SPOKE WITH DIMITRI SHTAIRMAN - HE SAYS A NEW LEASE WAS SIGNED WITH KAY SINGH FOR THE STATION AND MR. SINGH AS OPERATOR IS RESPONSIBLE FOR ALL ENVIRONMENTAL WORK ON THE SITE. DIMITRI SAYS THAT ALL CONTAMINATED SOIL HAS BEEN DUG OUT AND

GAS STATION/ 278 FUEL STOP (Continued) **S104648903**

REMOVED. HE SAYS END POINT SAMPLES OF THE OPEN HOLE WERE TAKEN BY ASTEM LAB INC (DR. NORMAN MUNROE 718-459-3770). RIGHT NOW THE SITE HAS A LARGE OPEN HOLE AND THEY ARE NOW WAITING FOR THE CONTRACTOR TO INSTALL THE NEW TANK & SYSTEM, BACKFILL AND REPAVE THE SITE.8/10/99 - ASTEM LABORATORIES, INC. SUBMITTED A REPORT SHOWING 6 END POINT SAMPLES (1 EACH SIDE, 2 BOTTOM) TAKEN FROM PIT WHERE 550 TANKS WERE. ALL SAMPLES WERE TESTED FOR 8021 + MTBE. ALL RESULTS INDICATE BTEX AND MTBE WERE <50 PPB.CLOSE OUT (CPT SAYS OK)

Remarks: CALLER STATES THAT DURING REMOVAL OF 550 GAL TANKS CONTAMINATED SOIL WAS FOUND.

Material:

Site ID:	169686
Operable Unit ID:	1075577
Operable Unit:	01
Material ID:	307921
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0610686
Facility Type:	ER
DER Facility ID:	202028
Site ID:	375177
DEC Region:	2
Spill Date:	12/20/2006
Spill Number/Closed Date:	0610686 / 8/26/2010
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	12/20/2006
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	12/21/2006
Spill Record Last Update:	8/26/2010
Spiller Name:	GABRIEL KAPUR
Spiller Company:	CONSTUCTION SITE

GAS STATION/ 278 FUEL STOP (Continued) **S104648903**

Spiller Address:	392 LEONARD ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	GABRIEL KAPUR
Contact Phone:	(917) 682-3753 CELL
DEC Memo:	Vought was on off hours8/16/10 - Raphael Ketani. The spill was called in on 12/20/06 by the NYPD and Gabriel Kapur of the NYCDEP (917) 682-3753. The spill was large gas puddles on the surface of the site.The site is block and lot 2733 and 7. It was sold on 7/28/87 by Lawrence Sievers of 5 Mt. Logan Court, Farmingville, NY to Walter Romansky and Dimitri Shtairman of 2421 East 74 Street, Brklyn, NY.There are two PBS registrations. PBS #2-510793 is for the 278 Fuel Stop, Inc. It lists four 4,000 gal. USTs and one 550 UST as still active with gasoline and diesel. The 4,000 gal. tanks were installed in either 1972 or 1999. The 550 UST was installed in 1939. There were 4 USTs that were closed and removed in 1939. The owner of the site is 278 Fuel Stop, Inc. (718) 388-3329. The contact is Kuldeep S. Sakota (718) 388-3329/(201) 548-1658.PBS #2-611136 is for A-1 Auto Repairs, Inc. It lists just a 275 gal. waste oil tank as being in service that was installed in 6/1/08. The owner of the site is Avtar Singh, 126 Berwood Drive, Linden, NJ 07036 (908) 486-0412. Mr. Singh is also at (718) 388-3464.There is no paper file and there are no E-docs.There are two other spill cases, both of which were closed by Steve Sangesland of Spills. They are #9900802 and #0310672. Case #9900802 was opened on 4/21/99 and closed on 8/10/99. It was based upon the discovery of oil contaminated soil when they pulled the 550 gal. UST. The soil was dug out and the end point samples were below 50 ppb.Case #0310672 was opened on 12/16/03 and closed on 12/16/03. There was an annonymous call regarding someone sweeping gas into the sewers.8/25/10 - Raphael Ketani. I made an unannounced site visit today. It was raining moderately, but I felt that it would still be possible to determine the site conditions. The site fronts on Leonard Street and on Meeker Avenue, where it parallels the Brooklyn Queens Expressway. There wasn't much to see from the Leonard Street side. There is a corrugated still building that opens onto Leonard Street. It has a sloping roof (see E-docs). The building was being used as a metal fabrication shop. The floor was clean. Next, I went to the Meeker Avenue side of "278 Fuel Stop." Even though it was raining, I didn't see any sheen on the pavement in the fueling area (see E-docs). There appeared to be some small (about 6" diameter) stains on the, but nothing else. Next, the gas station manager showed me the repair area. The area was largely try as it was mostly covered by a roof. There were several trucks in and next to the garage. I didn't see any free product on the pavement, but there were some old stains. I told the station manager to make sure that any spills that occur are cleaned up quickly. After this, I left the site.As the spills mentioned in the original spill report are no longer present, and as there appeared to be no new spills, I have determined that there is no threat to the environment or the public. Therefore, I am closing the spill case.
Remarks:	CALLER REPORTS A CALL REGARDING LARGE PUDDLES OF GASOLINE AT THIS SITE: SERVICE NUMBER 1516668

Material:

Site ID:	375177
Operable Unit ID:	1132823
Operable Unit:	01
Material ID:	2122608

GAS STATION/ 278 FUEL STOP (Continued) **S104648903**

Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	1407383
Facility Type:	ER
DER Facility ID:	455892
Site ID:	500893
DEC Region:	2
Spill Date:	10/16/2014
Spill Number/Closed Date:	1407383 / 11/3/2014
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	10/16/2014
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/16/2014
Spill Record Last Update:	11/3/2014
Spiller Name:	ROBERT ARCARO
Spiller Company:	GAS STATION
Spiller Address:	392 LEONARD ST
Spiller City,St,Zip:	BROOKLYN, NY 11211
Spiller Company:	999
Contact Name:	KULDIT SAHOTA
Contact Phone:	(718) 388-4163
DEC Memo:	10/27/14-Hiralkumar Patel.alternate address: 98 Richardson StreetPBS #: 2-510793, 2-611136as per PBS # 2-510793, the site has/had following tanks:- four (4) 550 gal gasoline USTs, removed in Apr. 1999- one (1) 550 gal waste oil UST, removed in Jun. 2009- one (1) 4,000 gal gasoline UST, in-service, installed in Aug. 1972- one (1) 4,000 gal gasoline UST, in-service, installed in Apr. 1999- two (2) 4,000 gal diesel USTs, in-service, installed in Apr. 1999as per PBS # 2-611136, the site has one (1) 250 gal waste oil AST on saddles, in-service, installed in Jun. 2008. PBS registration expired.other spills #: 9900802, 0310672, 0610686spill # 9900802 was reported on 04/21/1999 due to findings of soil contamination during removal of 550 gal tanks. case closed.spill # 0310672 was reported on 12/16/2003

GAS STATION/ 278 FUEL STOP (Continued) **S104648903**

anonymously. caller stated that gas station is polluting sewer system by a broken hose. case closed.spill # 0610686 was reported on 12/20/2006 due to findings of oil puddles on surface. case closed.12:42 PM:- spoke with Robert. he went to conduct a tank system test, as required by FDNY. during inspection, he noted that a sensor in intertitial space of the double wall diesel tank went off. he found about 2 gal diesel mixed water. site has two manifolded diesel tanks. currently the tank in question is empty and isolated from the other tank. fill box has been locked. further testing will be conducted and repairs will be made. FDNY has been informed about possible leak in diesel tank.Walter Romansky / Dimitri Shtairman **property owners**278 Fuel Stop Inc.Attn.: Kuldeep Singh **station operator**Ph. (718) 388-3329 (917) 755-8900email: 278fuelstop@gmail.comRobert ArcaroAmerican Res. Tech. Inc.Ph. (347) 204-1279email: arcarora@aol.comdiscussed with DEC Austin. as no indication of spill outside the secondary wall, further investigation may not be needed. he asked to discuss with DEC Leszek regarding PBS issues.11/03/14-Hiralkumar Patel. discussed with DEC Leszek. he will inspect the site.case closed based on discussions with DEC Austin and DEC Leszek.**PBS 2-611136 for waste oil tank has expired.**

Remarks: outer wall of double tank 4000 gal. tank - (contained) mixture of diesel & water tank will be emptied - repaired - clean up pending

Material:

Site ID:	500893
Operable Unit ID:	1250298
Operable Unit:	01
Material ID:	2251986
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

---

195 North 1/4-1/2 0.462 mi. 2439 ft.

ALBERTS PLATING WORKS BEADEL SITE
32 BEADEL ST
BROOKLYN, NY 11222

RCRA NonGen / NLR **1001127924**
FINDS **NYR000035345**
NY LTANKS
NY MANIFEST

Relative: Higher

Actual: 39 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ALBERTS PLATING WORKS BEADEL SITE
Facility address:	32 BEADEL ST BROOKLYN, NY 112225112
EPA ID:	NYR000035345
Mailing address:	DIVISION PL BROOKLYN, NY 11222
Contact:	Not reported
Contact address:	DIVISION PL BROOKLYN, NY 11222

ALBERTS PLATING WORKS BEADEL SITE (Continued) **1001127924**

Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: 42 DIVISION PLACE REALTY CO INC
Owner/operator address: 50 DIVISION PL
BROOKLYN, NY 11222
Owner/operator country: US
Owner/operator telephone: (718) 387-8460
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: 42 DIVISION PLACE REALTY CO INC
Owner/operator address: 50 DIVISION PL
BROOKLYN, NY 11222
Owner/operator country: US
Owner/operator telephone: (718) 387-8460
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ALBERTS PLATING WORKS BEADEL SITE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: ALBERTS PLATING WORKS BEADEL SITE
Classification: Not a generator, verified

Date form received by agency: 05/11/1998

ALBERTS PLATING WORKS BEADEL SITE (Continued) **1001127924**

Site name: ALBERTS PLATING WORKS IN DIP
Classification: Large Quantity Generator

Date form received by agency: 02/07/1997
Site name: ALBERTS PLATING WORKS BEADEL SITE
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/01/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004532186

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:
Site ID: 356241
Spill Number/Closed Date: 0510292 / 1/25/2006
Spill Date: 11/30/2005
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

ALBERTS PLATING WORKS BEADEL SITE (Continued) **1001127924**

SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	11/30/2005
CID:	408
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/30/2005
Spill Record Last Update:	1/25/2006
Spiller Name:	MARLON JOSEPH
Spiller Company:	BUSINESS
Spiller Address:	32 BEADEL STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	MARLON JOSEPH
Spiller Phone:	(646) 772-7949
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	306301
DEC Memo:	TTF Ltr sent to:Alberts Plating Works Inc.32 Beadel StBrooklyn, NY 11222Attn: Super/Facility Manager 1/12/06. J.Krimgold reviewd the letter-report dated January 9, 2006 and submitted by Middleton Environmental, Inc (631-321-4349). The report stats that the tank (UST) failed the test due to the leak in the ullage and that three soil samples taken beneath the tank do not show contaminant concentration above NYSDEC TAGM levels. It also suggests that the spill case can be closed once documentation for UST closure submitted to the Department. This report was not approved by the Department due to the lack of the following information:Soil samples location (lateral and vertical).Soil sampling at the fill port and along the fill line.Boring logs.Scaled site map.1/25/06. J.Krimgold reviewed a letter report dated January 25, 2006 and submitted by PTC,Ltd.According to the report, the perforations of the tank shell was found at the top of the tank. Samples were taken through the tank bottom and did not show contaminant above TAGM levels. NFA letter.
Remarks:	ABOVE LIQUID LEAK.

Material:

Site ID:	356241
Operable Unit ID:	1113553
Operable Unit:	01
Material ID:	2103617
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

ALBERTS PLATING WORKS BEADEL SITE (Continued) **1001127924**

Tank Test:

NY MANIFEST:

EPA ID:	NYR000035345
Country:	USA
Location Address 1:	32 BEADEL ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11222
Location Zip Code 4:	Not reported

Mailing Info:

Name:	ALBERTS PLATING WORKS BEADEL
Contact:	ALFRED DAGOSTINO
Address:	50 DIVISION PL
City/State/Zip:	BROOKLYN, NY 11222
Country:	USA
Phone:	718-387-8460

Manifest:

Document ID:	NYG0121401
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/1997
Trans1 Recv Date:	02/21/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/21/1997
Part A Recv Date:	/ /
Part B Recv Date:	03/17/1997
Generator EPA ID:	NYR000035345
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	05600
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

BB196 **MORGAN OIL TERMINALS CORP** **RCRA NonGen / NLR** **1000889835**
ESE **200 MORGAN AVE** **FINDS** **NYD074359472**
1/4-1/2 **BROOKLYN, NY 11237** **NY MOSF UST**
0.464 mi. **NY MANIFEST**
2451 ft. **Site 4 of 5 in cluster BB**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MORGAN OIL TERMINALS CORP
Facility address:	200 MORGAN AVE BROOKLYN, NY 112371014

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

EPA ID: NYD074359472
Mailing address: 21ST ST NYSDEC
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 21ST ST NYSDEC
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: UNKNOWN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: UNKNOWN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MORGAN OIL TERMINALS CORP
Classification: Not a generator, verified

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Date form received by agency: 07/08/1999
Site name: MORGAN OIL TERMINALS CORP
Classification: Not a generator, verified

Date form received by agency: 07/01/1996
Site name: NYSDEC - MORGAN TERMINAL SITE
Classification: Large Quantity Generator

Date form received by agency: 04/12/1994
Site name: MORGAN OIL TERMINALS CORP
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

Violation Status: No violations found

FINDS:

Registry ID: 110009468290

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MOSF UST:
Id/Status: 2-1500 / INACTIVE FACILITY
SWIS Code: 61
Facility Town: NEW YORK CITY
Contact Phone: (718) 366-5108
Emergency Contact: HENRY FOSTER
Emergency Telephone: (718) 857-6472
CBS Number: Not reported
SPDES Num: 0-032824
Total Tanks: 7
Total Capacity: 1925000
Avg Throughput: 0
License Stat: 3
Facility Type: STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options: AC
Expiration Date: 03/31/1991
Applic Rcvd: 01/14/1991
Operator: HENRY FOSTER
Owner Name: MORGAN OIL TERMINALS CORP.
Owner Address: 200 MORGAN AVENUE
Owner City,St,Zip: BROOKLYN, NY 11337-
Owner Telephone: (718) 366-5108
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mail To Name: MORGAN OIL TERMINALS CORP.
Mail To Address: C/O SHATZKIN & FURMAN, P.C.

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Mail To Address 2:	60 CUTTER MILL RD., SUITE 206
Mail City,St,Zip:	GREAT NECK, NY 11021-
Mail To Contact:	SCOTT E. FURMAN
Mail To Telephone:	(516) 487-3703
Legal Agent Name:	SCOTT FURMAN
Legal Agent Address:	60 CUTTERMILL ROAD
Legal Agent City,St,Zip:	GREAT NECK, NY 11021-
Date Filed:	00/82
Latitude:	40|42|40
Longitude:	73|56|00

Tank ID:	1
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	645000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	2
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	7000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	3
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	55000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	4
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	67000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	5
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	507000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Tank ID: 6
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 400000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 02/22/1994
Inspector Initials: Not reported
Inspector Status: Not reported
Pipe Flag: False
License Issued: 03/28/1990
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/23/1993
Federal Id No: Not reported
COI Date: / /

Tank ID: 7
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 244000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 02/22/1994
Inspector Initials: Not reported
Inspector Status: Not reported
Pipe Flag: False
License Issued: 03/28/1990

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/23/1993
Federal Id No: Not reported
COI Date: / /

NY MANIFEST:
EPA ID: NYD074359472
Country: USA
Location Address 1: 47-40 21ST STREET
Location Address 2: Not reported
Location City: LONG ISLAND CITY
Location State: NY
Location Zip Code: 11101
Location Zip Code 4: Not reported

Mailing Info:
Name: NYSDEC
Contact: JOSEPH SCEPPA
Address: 47-40 21ST STREET
City/State/Zip: LONG ISLAND CITY, NY 11101
Country: USA
Phone: 718-482-4933

Manifest:

Document ID: CTF0379437
Manifest Status: Completed copy
Trans1 State ID: TAF8660NJ
Trans2 State ID: Not reported
Generator Ship Date: 01/12/1995
Trans1 Recv Date: 01/12/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 01/12/1995
Part A Recv Date: 01/24/1995
Part B Recv Date: 01/27/1995
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 04700
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: NYB2125575
Manifest Status: Completed copy
Trans1 State ID: T448SMNJ
Trans2 State ID: Not reported
Generator Ship Date: 11/09/1994
Trans1 Recv Date: 11/09/1994
Trans2 Recv Date: / /

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

TSD Site Recv Date: 11/09/1994
Part A Recv Date: 11/18/1994
Part B Recv Date: 11/18/1994
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00015
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1994

Document ID: CTF0379414
Manifest Status: Completed copy
Trans1 State ID: T891GCNJ
Trans2 State ID: Not reported
Generator Ship Date: 09/29/1994
Trans1 Recv Date: 09/29/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 09/30/1994
Part A Recv Date: 10/11/1994
Part B Recv Date: 10/18/1994
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 05130
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYB6706683
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: T448SMNJ
Trans2 State ID: Not reported
Generator Ship Date: 10/11/1994
Trans1 Recv Date: 10/11/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 10/11/1994
Part A Recv Date: 10/26/1994
Part B Recv Date: 11/30/1994
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 39000

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

Document ID:	CTB0032187
Manifest Status:	Completed copy
Trans1 State ID:	HW307
Trans2 State ID:	Not reported
Generator Ship Date:	08/30/1994
Trans1 Recv Date:	08/30/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/30/1994
Part A Recv Date:	09/13/1994
Part B Recv Date:	09/14/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	04671
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	CTF0379413
Manifest Status:	Completed copy
Trans1 State ID:	T891GCNJ
Trans2 State ID:	Not reported
Generator Ship Date:	09/28/1994
Trans1 Recv Date:	09/28/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/28/1994
Part A Recv Date:	10/06/1994
Part B Recv Date:	10/14/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	04544
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	NYB2125260

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Manifest Status:	Completed copy
Trans1 State ID:	T448SMNJ
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/1994
Trans1 Recv Date:	11/01/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/01/1994
Part A Recv Date:	11/15/1994
Part B Recv Date:	11/18/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity:	00015
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

Document ID:	NYB2125233
Manifest Status:	Completed copy
Trans1 State ID:	T448SMNJ
Trans2 State ID:	Not reported
Generator Ship Date:	10/28/1994
Trans1 Recv Date:	10/28/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/28/1994
Part A Recv Date:	11/07/1994
Part B Recv Date:	11/09/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity:	00015
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

Document ID:	CTB0032193
Manifest Status:	Completed copy
Trans1 State ID:	780TWUNJ
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/1994
Trans1 Recv Date:	09/01/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/01/1994
Part A Recv Date:	09/13/1994
Part B Recv Date:	09/22/1994

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 03834
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: CTB0032188
Manifest Status: Completed copy
Trans1 State ID: 780TWUNJ
Trans2 State ID: Not reported
Generator Ship Date: 08/31/1994
Trans1 Recv Date: 08/31/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 08/31/1994
Part A Recv Date: 09/13/1994
Part B Recv Date: 09/14/1994
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 04671
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: CTB0032189
Manifest Status: Completed copy
Trans1 State ID: CTHW307
Trans2 State ID: Not reported
Generator Ship Date: 07/19/1994
Trans1 Recv Date: 07/19/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 07/19/1994
Part A Recv Date: 08/15/1994
Part B Recv Date: 08/04/1994
Generator EPA ID: NYD074359472
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 04950
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	CTB0032190
Manifest Status:	Completed copy
Trans1 State ID:	CTHW30
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/1994
Trans1 Recv Date:	07/20/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/20/1994
Part A Recv Date:	08/15/1994
Part B Recv Date:	08/04/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	04800
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	CTB0032191
Manifest Status:	Completed copy
Trans1 State ID:	CTHW307
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/1994
Trans1 Recv Date:	07/21/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/21/1994
Part A Recv Date:	08/15/1994
Part B Recv Date:	08/04/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	04635
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	NYB2125566
Manifest Status:	Completed copy
Trans1 State ID:	T448SMNJ
Trans2 State ID:	Not reported

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Generator Ship Date:	11/15/1994
Trans1 Recv Date:	11/15/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/15/1994
Part A Recv Date:	11/28/1994
Part B Recv Date:	11/25/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity:	00015
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

Document ID:	NYB2125251
Manifest Status:	Completed copy
Trans1 State ID:	T448SMNJ
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/1994
Trans1 Recv Date:	11/21/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/21/1994
Part A Recv Date:	12/02/1994
Part B Recv Date:	12/02/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity:	00015
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

Document ID:	NYB2125584
Manifest Status:	Completed copy
Trans1 State ID:	T448SMNJ
Trans2 State ID:	Not reported
Generator Ship Date:	11/07/1994
Trans1 Recv Date:	11/07/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/07/1994
Part A Recv Date:	11/18/1994
Part B Recv Date:	11/18/1994
Generator EPA ID:	NYD074359472
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

TSDF ID:	NYD082785429
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity:	00015
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

BB197 **NYC DEP HAZ MAT** **NY LIENS** **S102143390**
ESE **200 MORGAN AVENUE** **NY MANIFEST** **N/A**
1/4-1/2 **BROOKLYN, NY 11201** **NY Spills**
0.464 mi. **NY MOSF**
2451 ft. **Site 5 of 5 in cluster BB**

Relative:
Lower

Actual:
13 ft.

LIENS:

Region:	2
PIN:	92402
Spill No:	92-09135
Tax Map Id:	2942-101, 157, 160, 207, 220
Lien Request Received:	03/22/1994
Request Sent To APA Or Vendor:	12/05/1994
Draft Lien Received From Vendor:	05/31/1995
Approved Lien To Administrator:	Not reported
Signed By Administrator:	Not reported
Received From Administrator:	Not reported
Sent For Filing:	Not reported
Resent For Filing:	Not reported
Proof Of Service Received:	Not reported
Sent To OAG:	06/05/1995
Amount:	$71,828.17
Release Required:	Not reported
Sent To Administrator:	Not reported
Signed By Adminstrator:	Not reported
Received From Adminsitrator:	Not reported
Release Sent To OAG:	Not reported
Complete:	Yes
Release:	No

Region:	2
PIN:	92402
Spill No:	92-09135
Tax Map Id:	2942-101, 157, 160, 207, 220
Lien Request Received:	06/17/1996
Request Sent To APA Or Vendor:	07/18/1996
Draft Lien Received From Vendor:	11/19/1996
Approved Lien To Administrator:	Not reported
Signed By Administrator:	Not reported
Received From Administrator:	Not reported
Sent For Filing:	Not reported
Resent For Filing:	Not reported
Proof Of Service Received:	Not reported
Sent To OAG:	11/25/1996
Amount:	$561,620.28
Release Required:	Not reported
Sent To Administrator:	Not reported
Signed By Adminstrator:	Not reported

NYC DEP HAZ MAT (Continued) **S102143390**

Received From Adminsitrator: Not reported
Release Sent To OAG: Not reported
Complete: Yes
Release: No

NY MANIFEST:
EPA ID: NYP003662657
Country: USA
Location Address 1: 200 MORGAN AVENUE
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11201
Location Zip Code 4: Not reported

Mailing Info:
Name: NYC DEP HAZ MAT
Contact: JOANNE NURSE
Address: 59 17 JUNCTION BLVD
City/State/Zip: FLUSHING, NY 11373
Country: USA
Phone: 718-595-4675

NY MANIFEST:
No Manifest Records Available

SPILLS:
Facility ID: 9105949
Facility Type: ER
DER Facility ID: 57235
Site ID: 251343
DEC Region: 2
Spill Date: 9/3/1991
Spill Number/Closed Date: 9105949 / 9/19/1991
Spill Cause: Abandoned Drums
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: SJMILLER
Referred To: Not reported
Reported to Dept: 9/3/1991
CID: Not reported
Water Affected: NEWTOWN CREEK
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Other
Cleanup Ceased: 9/19/1991
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/3/1991
Spill Record Last Update: 4/7/2004
Spiller Name: Not reported
Spiller Company: MORGAN OIL CORP
Spiller Address: Not reported

NYC DEP HAZ MAT (Continued) **S102143390**

Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MILLER"10/10/95: This is additional information about material spilled from the translation of the old spill file: SHEEN, GLOBS.
Remarks:	APPEARS TO BE COMING FROM A 55 GAL ABANDONED DRUM IN CREEK. OR MAY BE DUE TO A BULKHEAD (LOW TIDE)

Material:

Site ID:	251343
Operable Unit ID:	956456
Operable Unit:	01
Material ID:	421709
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	1202045
Facility Type:	ER
DER Facility ID:	419184
Site ID:	464793
DEC Region:	2
Spill Date:	5/30/2012
Spill Number/Closed Date:	1202045 / 5/31/2012
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	5/31/2012
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/31/2012
Spill Record Last Update:	8/7/2012
Spiller Name:	BRIAN CISKOWITZ
Spiller Company:	UNKNOWN
Spiller Address:	200 MORGAN AVE

NYC DEP HAZ MAT (Continued) **S102143390**

Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	BRIAN CISKOWITZ
Contact Phone:	(516) 364-4140
DEC Memo:	05/31/12-Hiralkumar Patel.9:30 AM:- visited site. no oil or sheen observed.after discussing with DEC Austin, case closed.
Remarks:	Not reported

Material:

Site ID:	464793
Operable Unit ID:	1214830
Operable Unit:	01
Material ID:	2212900
Material Code:	9999
Material Name:	Other - brown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9112693
Facility Type:	ER
DER Facility ID:	57235
Site ID:	251344
DEC Region:	2
Spill Date:	3/12/1992
Spill Number/Closed Date:	9112693 / 3/13/1992
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	3/12/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	3/13/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	3/20/1992
Spill Record Last Update:	9/23/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported

NYC DEP HAZ MAT (Continued) **S102143390**

Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"
Remarks:	FD ON SCENE. SPEEDY-DRY APPLIED

Material:

Site ID:	251344
Operable Unit ID:	963025
Operable Unit:	01
Material ID:	414255
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9211657
Facility Type:	ER
DER Facility ID:	57235
Site ID:	59303
DEC Region:	2
Spill Date:	12/23/1992
Spill Number/Closed Date:	9211657 / 11/19/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	12/23/1992
CID:	Not reported
Water Affected:	ENGLISH KILL
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1/14/1993
Spill Record Last Update:	4/19/2012
Spiller Name:	Not reported
Spiller Company:	MORGAN OIL CORP.
Spiller Address:	200 MORGAN AVENUE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	4/19/12-Vought-Project manager for PIN project at Morgan Terminal

NYC DEP HAZ MAT (Continued) **S102143390**

(Open spill 9209135). Located box in file room with notes and reports from DEC Sigona PBS Inspection and Case. This file added to PIN drawer as PBS data may be needed for further cost recovery by NYSOAG if applicable.

Remarks: 19 WELLS PUT ON SITE 15 WELLS SHOWS CONTAMINATION/REMEDIAL INVESTIGATION REPORT PREPARED BY FENLY AND NICOL. SITE SHOWS FREE PRODUCT MIGRATING OFF-SITE. DEC TO CLEAN/INSPECT MOUNDED TANKS/LEAKS.

Material:

Site ID:	59303
Operable Unit ID:	976105
Operable Unit:	01
Material ID:	405044
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9209135
Facility Type:	ER
DER Facility ID:	57235
Site ID:	59302
DEC Region:	2
Spill Date:	11/6/1992
Spill Number/Closed Date:	9209135 / Not Reported
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	11/6/1992
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Federal Government
Cleanup Ceased:	2/28/1995
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	11/10/1992
Spill Record Last Update:	1/28/2015
Spiller Name:	Not reported
Spiller Company:	CITIFUEL INC.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001

NYC DEP HAZ MAT (Continued) **S102143390**

Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"This spill site remediation has been consolidated under Spill No. 9209135.1. Current Site Activity- All electricity to site and recovery system has been shut down. There are a total of 45 wells at the site some of which are equipped with recovery pumps which require major modifications to recover the remaining product. The site is being monitored on a monthly basis. All tanks and sources of additional spills have been cleaned and emptied. There is a locked fence around the site which is controlled by DEC. 2. DEC State Funded Cleanup- The DEC has spent over 1.7 Million dollars which should include all costs for the cleaning and removal of petroleum and hazardous waste from the tanks and investigation and partial remediation of the groundwater. There is a lien on the property which should be settled with Office of the State Comptroller, New York Environmental Protection and Spill Compensation Fund, Alfred E. Smith State Office Building, 8th Floor, Albany, New York 12236 - ATT: Ann Hohenstein, Esq.3. Legal IssuesThere are two Consent Orders Under R2-3721-06 & R2-3885-91-09 and subsequent judgements against the owners and past operators of the site:Morgan Oil Terminal Corp, Citifuel Corp, Premium Pipeline, Inc., Samual Festinger, Henry Foster & Alexander Weisz. There was a judgement order in 1993/94 by the DEC's commissioner after an administrative hearing against several of the above parties confirmed violations of the previous consent orders. 4. Site HistoryThe Site had 7 tanks capable of holding 1.9 million gallons and 2 barge slips, a loading rack for tanker trucks and 1 oil water separator. The tanks, piping and oil-water separator was cleaned of sludge and waste which was found to be hazardous. The heat exchanges for the loading rack were checked for asbestos and secured.The groundwater was contaminated from leaks in tank nos. 4 & 5. In February 1994, the owner's attorney provided written access to DEC to take over control and cleanup of the site.4/21/04 - Spill manager's name is switched to Tipple from Sigona.6/10/04//TIPPLE UPDATING///COMMUNITY LIASON ---SGT. LOCHTER 516-644-77381/18/05 Albany required transfer to the low bid contractor National Environmental///Upon arrival at the location, the back half of the site had been leveled, obliterating many of the wells,the back fence was missing, the shed had been burnt down and much of the front fence had been damaged.4/5/05 12:30 pm ///mt updating/// DEC notified of active leak from overhead line, Arron Abraham was contacted and given the opportunity to retain an emergency response contractor. Mr Abraham (718-390-8811 ex.1)declined and requested the DEC conduct this emergency remedial work, Milro was retained and will be on site 3:30 this afternoon///// Bill Buss AAG informed of the situation////8/23/05 - Raphael Ketani. Case transferred to Jeff Vought.8/24/05-Vought-Spoke to Marc Casslar (GeoQuest 860-243-1757). Michelle was sent RAP and offer to resolve lein. Michelle was going to review letter and resolve lein with AG's office.10/7/05-Vought-Spoke with Aaron Abraham (RCC Associates 718-514-3782) who is current property manager for owner. RCC took over property during public auction. RCC hired Casslar. Large amount of taxes owed on property. Vought will call Buss prior to sending review letter. Site may be self storage or parking lot. 10/20/05-Vought-File review by Vought: See also closed spill #'s-8808176, 9105949, 9112693, 9208755, 9211657.Tank Inventory Records (English Kills Oil Company)-January 1947Tank Inventory

NYC DEP HAZ MAT (Continued) **S102143390**

Records (English Kills Oil Company)-November 1954PBS Registration-12/26/90. One 645,000-gallon #6 fuel oil UST, One 7,000-gallon #1,2,4 fuel oil UST, one 55,000-gallon #1,2,4 fuel oil UST, one 67,000-gallon #1,2,4 fuel oil UST, one 507,000-gallon #6 fuel oil UST, one 400,000-gallon #1,2,4 fuel oil UST and one 244,000-gallon #1,2,4 fuel oil UST.SPDES Permit (DEC)-7/30/87 thru 7/30/92.Morgan Oil Advertisement Brochures (Morgan Oil Company).Morgan Oil Terminal Operations Manual (Morgan Oil Company). Products transferred at facililty include #2 and #6 fuel oil. Site plan shows 400,000-gallon UST for #2 fuel oil, 243,000-gallon UST for #2 fuel oil, 647,000-gallon UST for #6 fuel oil, 70,000-gallon UST for #2 fuel oil, 54,000-gallon UST for #4 fuel oil, one 67,000-gallon UST for #4 fuel oil, and one 307,000-gallon fuel oil for #4 fuel oil.Letter from DEC Chakrabarti to Morgan Oil (David Braun)-3/9/90. "Please be advised that we have received the application for Major Petroleum Facility License of your company." Letter states that tank internal and external protection sections not filled out properly.Letter from DEC Bureau of Wastewater(Cronin)-10/30/90. "This is to advise you that your Discharge Monitoring Report for the reproting period which ended August 31, 1990 has not been received in our Bureau of Wastewater Facilities Operations, Albany office."Lease Agreement between Morgan Oil (owner) and Citifuel Inc (tenant)-lease from 3/25/91 to 3/31/95.DEC Major Petroleum Facility Annual Inspection Report (DEC Sigona)-5/28/91. Inspection performed on 2/22/91. Facility must correct following defeciences: submission of new spill prevention, control and countermeasures plan 2)installation of monitoring wells and groundwater sampling 3)submission of groundwater contingency plan 4)testing and monitoring of UST and mounded petroleum tanks.DEC Case Initiation Form (DEC Sigona)-5/28/91. Facility owner failed to comply with special license conditions for at least two years by not having any Spill prevention, control and countermeasures plan. Facility failed to inspect or test the USTs by 12/27/87.DEC Major Petroleum Facility License Fee Report-10/28/91. FDNY Inspection Report-9/11/91. Contains product/water levels in USTs. Up to 12'2" of oil in USTs. Three violations written by DEC: 1)operating bulk storage terminal with out permit 2)failure to comply with commissioners order D09612 3)failure to comply with commissioner order D09609. Letter from DEC Barrell to Morgan Oil-9/26/91. "Since you have failed to submit your July 1001 Major Petroleum Facility Fee Report as requested in our previous letter, we have estimated your license fee and surcharge as follows...." Letter has cerfied mail receipts of attempted delivery on 7/8/91, 9/4/91 and 11/1/91.Notes from DEC Sigona-10/7/91. Sampling of USTs by Pedneault Labs. Also contains product and sludge levels in USTs.Letter from Pedneault Associates to Citifuel Corp-10/22/91. "As per your request we sampled seven oil storage tanks on October 7, 1991..." "Our tests show most, if not all, of the stored oil in the tanks to be usable diesel oil..." No PCBs found in results.Letter from DEC Sigona to Morgan Oil (Henry Foster)-10/24/91. "...recent MOSF inspections have found that your facility is being occupied by a company called Citi Fuel Oil, Inc. This arrangement was never formally identified by you, the authorized facility representative." Letter requires Morgan Oil to immediately file application to update MOSF license. "Until DEC received a corrected license application we will suspend the issuance, or renewal of your April 1, 1991 -March 31, 1992 MOSF license". Letter sent to Terminal was returned and letter sent to and accepted by Scott Furman PC (attorney for Morgan

NYC DEP HAZ MAT (Continued) **S102143390**

Oil).Letter from Pedneault to Citifuel Corp-11/13/91. Metal and PCB analysis of product samples.Letter from Pedneault to DEC-1/6/92. PCB and metal analysis of samples obtained from oil and water separators and storm drains. Analyticals show no PCBs or metals except for lead (highest concentrations of .111mg/l).Fax from DEP Hazmat to DEC Sullivan-1/31/92. Caller stated that tanks are cracked and leaking into the ground. Owner has sealed of stick wells into tanks. Complainant is a former employee.FDNY Violation D17149-2/4/92. Violation Order to: 1)repair or replace defective fog spray 2)pressure test repaired spray piping 3)Submission of report regarding the "oil spill atop mounded tank compartments #1 and #2" 4)cleanup of contaminated earth atop compartments #1 and #2.FDNY Violation D09639-3/12/92. Violation Order to: 1)discontinue receipt and transfer of product from all the tanks.FDNY Violation D09640-3/12/92. Violation Order to: 1)clean up all oil spill on and around the tank area #1 to #5. 2)clean up all contaminated earth as per other govt' agencies having jurisdiction.FDNY Violation D09641-3/12/92. Violation Order to: 1)submit detailed report regarding oil spill "which occurred today".FDNY Violation D09642-3/12/92. Violation Order to: 1)discontinue modification to product piping on mounded tank area of Tank #1 to Tank #5.FDNY Violation D09643-3/12/92. Violation Order to: 1)restore product piping to it's original condition.Notes from Alexander Weisz (plant manager)-3/12/92. "Spill on Feb 4, 1992 occurred when a Best Tank Co. truck was attempting to clean out oil from Tank #1 at the terminal". Approximately 100 gallons of #6 oil was spilled during transfer. Oil spilled on top of mounded tanks #1 thru #5 and some overflow occurred. Spill on 3/12/92 (#9112693)occurred when Best Tank Co. was removing product from the #6 fuel oil lines. 50 gallons of oil spilled on the north wall of the mounded tanks #1 thru #5. Letter witnessed by DEC Sigona. Notice of Hearing (NYSDEC by Morgan Oil Terminals) from DEC Gallay-6/30/92.Letter from DEC legal Keehn to Weiss Esq.-7/29/92. "...Morgan Oil Terminals are respondents in a case that is set for hearing August 6..." "I am sending you this to ensure you are aware of the pending enforcement action".NPDES Dishcarge Monitoring Report-August 1992.Letter from DEC Keehn to NYSDEC Judge Pearlstein-8/5/92. "...due to a sever accidental injury to Staff's primary witness in this case, I have been forced to ask for an adjournment".Letter from Furman to DEC Keehn-8/13/92. Furman is representing Henry Foster. Citifuel breached several of it's obligations pursuant to a lease including a provision which prohibited operating the Premises as an oil storage facility without first obtaining the required permits. Morgan commenced action to evict Citi Fuel in October 1991. Citifuel is still in possession of the premises. Enclosed is response to Citifuel's Order to Show Cause.Letter to DEC Judge Pearlstein from DEC Keehn-8/20/92. Staffs primary witness has returned to the office and hearing will be held on 9/17.Letter from DEC Keehn to DEC Pearlstein-9/9/92. "Mr Gross called me and asked for another adjournment..." Mr Gross is attorney representing Citifuel. "I do not believe it would be appropriate for me to move for another adjournment".Letter to Hayim Gross from DEC Keehn-9/9/92. "...I cannot move to adjourn again. You are, of course, free to move for such and adjournment yourself." "With respect to settlement your clients will have to submit a complete application for license, submission of a plan to test the tanks and plan for investigation and remediation.Letter from DEC Keehn to DEC Serbent-9/15/92. Attorneys for Morgan Oil (Furman) and CitiFuel

NYC DEP HAZ MAT (Continued) **S102143390**

(Gross) agreed to hearing on 10/22/92.Letter from FDNY Fire Prevention to USCG (Hodgens)-9/15/92. FDNY requested letter of Adequacy to be rescinded due to 1)lack of current FDNY permit 2)18 FDNY summons 3)facility is operating with DEC permit. Attached was USCG letter of Adequacy to Morgan Oil Terminal.Letter from DEC Keehn to Hayim Gross-10/13/92. "As you have discussed with Paul Gallay, your clients will be taking the Major Onshore Petroleum Storage Facility at 200 Morgan Avenue out of service in the near future. It is imperative that you put this committment in writing and send a fax of a letter on this to me". Letter also requires a complete site assessment and remediation.Field Notes from DEC Sigona-10/16/92. Product levels and inventory estimations in each tank.Investigation Proposal (Roux Associates)-10/18/92. Proposal for the installation of four monitoring wells and subsequent groundwater sampling and report preparation.10/21/05-Vought-Continued File Review: Letter from CitiFuel Corp to DEC Gallay-11/2/92. Four letters sent to DEC stating that CitiFuel, Premium Pipeline, Alexander Weisz and Sam Festinger have appointed Chaim Yosef Mariategui-Levi to represent them for negotiations leading to a consent order and final permitting of oil terminal.Field Notes from DEC Sigona-11/6/92. Sigona observed oil puddles on ground near mouned tanks and on top of mounded tanks #1-5.Invoice from Winston Contracting-11/7/92. "Called out by Mr. Sullivan (NYSDEC) at 12:30pm Saturday November 7, 1992 to 200 Morgan Avenue. Secured Hard Boom to piles. Installed 20' of boom at ends of hard boom. Installed 1 sweep between barge and dock. Installed 20' of boom near outfall pipe from oil water separator. Drained oil from oil water separator; Drained oil from catch basin in yard." Took sample from water and took sample from oil water separator.Photos of site visit on 11/10/92. Fax from US Environmental to Premium Pipeline(Festinger)-11/17/92. Estimate of cost to perform: 1)tank and pipe cleaning 2)installation of waste water treatment equipment 3)monitoring wells 4)temporary closure certification 5)coordination of temporary closure.Fax of Bankruptcy Papers for Premium Pipeline (Festinger)-11/23/92. Interim Order on Consent-signed on 12/3/92. 10/24/05-Vought-Contract Payment Package (National)-Biweekly well monitoring, searching for missing wells, replace manhole covers, photos, report preparation, groundwater sampling. (4/1/05-7/31/05).11/2/05-Vought-Received call from Ted Yen(917-584-6299) and his client is looking to buy property. Yen looking for further guidance on property as future location as cement factory. Vought received second call from Aaron Abraham (property manager for owner) regarding site status. Site visit scheduled for 11/9/05 at 1pm. Morgan Oil sold property on 3/04 to RCC during foreclosure at city.11/2/05-Vought-Continued File Review by Vought:Fingerprinting Results (Pedneault)-1/4/93. Fingerprinting results from samples collected from USTs showed samples to contain "gasoline contaminated fuel oil". Three 55-gallon drums sampled on 1/5/93.Tank Testing Results (Fenley & Nicol)-1/13/93. Passing test results of one (550-gallon) diesel UST and three (550-gallon) gasoline USTs.Fingerprinting Results (Pedneault)-1/15/93. Fingerprinting results from tanks #1 thru tank #7 showing "fuel oil" in tanks #1-#6 and "contaminated fuel oil" in tank #7. No PCBs in sample.Soil Boring Results (Pedneault)-1/22/93. Soil sample results for twenty monitoring wells.Letter from DEC Keehn to Furman-2/1/93. "The most recent Discharge Monitoring Reports for the subject facility have been returned as not deliverable. This is to let you know that from now on they will be mailed to the 200 Morgan Avenue

NYC DEP HAZ MAT (Continued) **S102143390**

address....".Subsurface Investigation Report (Fenley & Nicol)-3/6/93. F&N hired by NYSDEC. Installation of twenty monitoring wells. "At twelve feet a peat layer consisting of very soft to medium compacted peat and/or organic silt with trace plant fibers and fine sand was encountered". Groundwater from 2-6' below grade. Surrounding property is commercial and industrial. Air rotary and hollow stem augers were drilling method. Product samples were also collected from: tank ST-7, two soil water separators (ST-1 and ST-2), storm drain ST-3 and ST-6, composite of 55-gallon drums (three drums), tank #1 and tank #5. Collection and analysis of 65 soil samples. Groundwater flow to the northeast. Report recommends installation of additional monitoring wells, performance of a pump test, cleaning of all USTs, cleaning of barge off-loading sumps, cleaning of loading dock drains, cleaning of storm drains. Gasoline contamination detected in soil samples from wells FN2, FN3 and FN5. Fuel oil contamination detected in FN11, FN12, FN15 and FN17. Report from USCG-3/6/93. Approximately 200 gallons of waste oil spilled into English Kills due to a bulkhead collapse on the property adjacent to Morgan Oil. Morgan oil was contacted to clean up spill but it was stated that no funds were available. ISR-3/18/93. Letter from DEC Keehn to Judge Serbent-3/18/93. "Per our discussion of today, this is to advise all parties that the date through which Closing Arguments in this case will be accepted has been extended to March 31, 1993."Order from FDNY-3/18/93. Order to gas free all bulk oil and vehicle storage tank, associated piping and submit marine chemist gas free certificates.MOSF Application-3/28/03.Draft Consent Order-4/14/93.Fax from Shatzkin & Furman to DEC Keehn-4/15/93. "Enclosed herewith are an executed original and two copies of the Partial Order on Consent...".ISR (DEC Sigona)-4/29/93.Report from USCG-8/5/93. "All oil removed from English Kills and Morgan oil Corp's Bulkhead...". Oil removed from English Kills on 3/7/93, 3/8/93 and 6/24/03.11/3/05-Vought-File review continued by Vought:Letter from DEC Gallay to Furman-10/5/93. "My field inspectors advise me that Morgan Oil Terminals had not complied with its most significant cosnent order requirements, since Morgan executed the order on April 6, 1993". "If we cannot determine a mutually satsifactory resolution of the current situation I will reopen the adjudicatory hearing agains Morgan and seek penalties...".Fax from FDNY to DEC Sigona-10/2/93. Copy of correspondence from JLE General Contracting to FDNY. "We are submitting to you a preliminary list of items which we understand need to be done before your department will consider issuing the permits necessary to restore the terminal to operation". Letter from Furman to DEC Gallay-10/13/93. "As we discussed our client Morgan Oil Terminals Corp entered into a lease agreement with JLE Industries with respect to the above referenced properties.." Consent Order was incorporated into lease agreement. JLE will submit items including cleaning and testing of all tanks and sumbission of a remedial action plan addressing groundwater. JLE was granted permission by FDNY to clean tanks.Letter from JLE (LaBate) to DEC Vitale-12/7/93. "The objective of the work described herein is to maintain a system for tank entry and cleaning for the buried tanks located at the above site".Letter from DEC Sigona to JLE Labate-12/8/93. "JLE must submit written procedures to DEC for written approval before you proceed with tank inspection work".Letter from DEC Gallay to Furman-12/30/93. "...we have not had any substantive progress on several issues which the Department cannot overlook". Issues include new facility operators failed to maintain

NYC DEP HAZ MAT (Continued) **S102143390**

round-the-clock coverage, product removal from tanks without notification to DEC, facilty is not properly secured with a fence, lack of committment from JLE to commence tank cleaning. "Please send me a letter or facsimile response by COB Friday January 7, 1993 to advise me of a schedule when DEC an expect the operators to secure the site and begin cleaning the tanks".Letter from DEC Vitale to Furman-2/9/94. Advisment that JLE is in violation of the consent order. To date JLE had not performed any remedial tasks. "DEC hereby gives notice to Morgan Oil and JLE that if within 48 hours, proof that the Premises has been secured and that remedial work has begun is not forwarded to this office, DEC will resume a state funded contract..."Letter from DEC Atwater to Furman-2/15/94. "The New York State Department of Environmental Conservation will be undertaking the investigation and/or cleanup of a petroleum spill on the project referred to above". "Please sign below to indicate that you consent to the Departments and/or its contractors entrance onto and use of your property...". Letter signed by Scott Furman.Letter from DEC Sigona to Winston Contracting (Sceppa)-2/10/94. "I would like your organization to provide to this Department with the estimated cost to clean and secure mounded tanks and above ground piping, and install a security fence and gate....". Letter from Fenley & Nicol (El Sehamy) to DEC Tomasello-2/27/94. "Fenley & Nicol Environmental understands that thte remediation proposal that was sumbitted to your office on February 15, 1995 regarding the above referenced site has been approved. F&N will begin construction of the system in the mid month of March 1995." Estimate from Miller Environmental-3/7/94.Estimate from Tyree Bros Environmental-3/11/94.Estimate from Milro-3/22/94.Estimate from Winston-3/22/94.Letter from DEC Sigona to Winston (Sceppa)-3/30/94. "I would like to confirm that your company has been selected to provide this Department with the work outline in the request for proposal dated February 10, 1994". Proposal to install fence and clean tanks.Letter from DEC Gallay to Furman-4/5/94. "..DEC is now proceeding with a state funded contract to remediate site contamination at the above facility". "DEC has selected Winston Contracting to execute the following surface remediation work to begin on Thursday April 7, 1994:". "Once work begins at the site, access must be restricted to DEC and Winston Contracting. DEC must receive written assurance from you in this mattter".CommonWealth of Pennsylvania-Request for Process or Dispose of Residual Waste-4/8/94.Letter from DEC Sigona to NYS Department of Labor (Gibney)-4/8/94. "...the DEC would like your assistance in evaluating a potential asbestos contamination problem ..."Letter from Department of Labor (Khelem)-4/11/94. "The analysis indicated that the insulation on a steam pipe and on a heat exchanger contains asbestos".USEPA Acknowledgment of Notification Of hazardous Waste Activity-4/18/94.Laboratory Analyticals (Pedneault)-6/22/94. Liquid Tank #5(85575ppb tetrachlorethene, 7845ppb trichlorethylene).Letter from Chemical Pollution Control-6/30/94. "Chemical Pollution Control having reviewed your analysis, MSDS and information submitted to us had determined that we have the capabilities to dispose of this material in accordance with all federal, state and local regulations".Laboratory Analyticals (Pedneault)-7/5/05. Solids (Tank #1-750ppb tetrachloroethene), (Tank #2-330ppb 1,1,2-trichlorethane), (Tank #3-350ppb tetrachloroethene), (Tank #4-500ppb tetrachloroethene).Letter from Winston Contractors to Environmental Chemical Associates-7/7/94. Request to submit estimate for cost of disposal of haz waste from tanks (oil with perc and TCE).Hazardous

NYC DEP HAZ MAT (Continued) **S102143390**

Waste Manifests-Various.Letter from Winston (Sceppa) to DEC Sigona-9/14/94. "The enclosed price quote from Chemical Pollution Control is for the remvoal of Hazardous Waste from Tank #1".Letter from Hogan, Jones and Parisi to DEC Sigona-11/14/94. "I am the attorney representing Zunno Rag Corp., 184 Morgan Avenue...." Property is adjacent to Morgan Terminal. Zunno is in process of selling property. Request for FOIL information.Haz Waste Manifest (Chemical Pollution Control)-11/15/94. Letter from Fenley & Nicol (Ash)-1/20/95. "The purpose of this letter is to provide you with an update on the status of the above referenced site". Four upgradient monitoring wells were installed in January 1994." "As per our discussions we are scheduling the following: periodic site monitoring, vacuuming of all wells containing floating product and redevelopment of all wells." "F&N requests your permission to bring our recovery trailer on-site".Fax from Fenley & Nicol-1/30/95. Map of floating product.Monitoring Report (F&N)-January 1995. Recovery system "under construction". Total amount of free product recovered to date is 22 gallons.Remediation Proposal (F&N)-2/14/95. Proposal to install a groundwater pump and treat system. Free product in FN11, FN15, FN16 and FN17. "The floating product plume is migrating in a southerly direction. "Floating product and contaminated groundwater will be removed from the subsurface by the Total Fluids Ejectors and pumped into the oil/water separator. Floating product will be removed from the separator through periodic vacuum truck visits. Contaminated water will be passed through the carbon units for decontamination and discharged to an existing on-site storm drain".11/7/05-Vought-Continued File Review:Opening Report (Winston Contracting)-2/25/95. English Kills borders property to north and east and commercial properties to the west. Onsite USTs consist of:one (54957-gallon) USTone (647068-gallon) #6 fuel oil USTone (70991-gallon) #2 fuel oil USTone (67001-gallon) USTone (507940-gallon) USTone (416122-gallon) #2 fuel oil USTone (243778-gallon) #2 fuel oil USTone (550-gallon) diesel USTone (5000-gallon) waste oil USTFour (550-gallon) gasoline USTWinston Contracting installed perimeter fence, staffing of an onsite security guard, removal of sludge from tanks, cleaning of pipelines, capping of all open pipelines, tank cleaning, encapsulation of all exposed asbestos in aboveground pipes, removal of perc contaminated sludge from tanks #1 and #5, well monitoring, product removal from wells. Results of tank investigations after cleaning showed: Tank #1, #2, #3, #4, #5, #6, #7 were "found to be sound with no visible defects". Oil water separator was vacuumed and cleaned and UST by boiler room was also emptied. Trench drains were also vacuumed and cleaned. Four gasoline tanks by garage were also vacuumed and cleaned. Diesel UST by office was also vacuumed and cleaned. "All contractual work at 200 Morgan Avenue was terminated on 1/31/95." Report recommends bimonthly well monitoring and installation of several recovery systems.Letter from DEC Tomasello to Zunno Rag Corp-3/8/95. "Our investigation has determined that the oil does not extend onto the Zunno Rag Corp property".Notice of Enviromental Lien-3/24/95. Lien in the amount of $71,828.17 is attached to property.Monthly Monitoring Report (F&N) February thru December 1995. Weekly well monitoring, recovery system is total fluid ejector system with 1000-gallon oil water separator/550-gallon product holding tank/carbon treatment for effluent, 415 gallons total product bailed from wells via vacuum truck.Non-hazardous Waste Manifests-8/7/95Monthly Monitoring Reports (F&N)-Jan 1996 thru August 1996. Weekly well monitoring, recovery

NYC DEP HAZ MAT (Continued) **S102143390**

system is total fluid ejector system with 1000-gallon oil water separator/550-gallon product holding tank/carbon treatment for effluent, 417 gallons total product bailed from wells via vacuum truck. Wells #28 and 28A contained free product.Status Report (F&N) Nov 1995 thru April 1996. Gasoline constituents found in wells FN2, FN3 and FN5 adjacent to 550-gallon gasoline USTs. Recovery system became operational in June 1995. Total of 23 monitoring wells and five ejector wells onsite. Groundwater table mounding in areas of Tanks #2 thru 5. "Groundwater flow is directed away from the mounds in a radial fashion toward English Kills to the north and east, and towards Morgan Avenue to the west". Report recommends installation of an ejector well and three monitoring wells adjacent to FN28, beginning of VEFR at site, a round of sampling for dissolved product and a closure plan for onsite tanks.Notice of Environmental Lien-9/23/96. Lien in the amount of 305416.30 attached to property.Notice of Environmental Lien-9/23/96. Lien in the amount of 561620.28 attached to property.Monthly Monitoring Reports (F&N)-Jan 1996 thru August 1996. Weekly well monitoring, recovery system is total fluid ejector system with 1000-gallon oil water separator/550-gallon product holding tank/carbon treatment for effluent, 429.75 gallons total product bailed from wells via vacuum truck. Semi-Annual Monitoring Report (F&N)-December 1996. There are a total of 39 monitoring wells and six ejector wells onsite. VEFR occurring on as-needed basis. "Groundwater flow is directed toward English Kills and Morgan Avenue". Groundwater at 12' below grade. Free product detected in 12 wells. Free product plume map indicated two separate plumes. A total of 435.25 gallons of free product was recovered from site to date. Report recommends solicitation of bids to install horizontal recovery wells and and EFR pilot test. Letter from F&N (Dunn)-5/8/97. F&N inspected site to monitor wells and overall condition of site. F&N feels two separate plumes onsite. F&N recommends collection of free product samples, additional Geoprobe delineation, performance of an EFR pilot test and if applicable installation of a permanent vacuum enhanced recovery system.Letter from F&N (Lorthior) to DEC Tomasello-10/31/97. Product from several wells was sampled for the proposed viscosity test. Numerous cars found onsite and fence was removed. Oil was observed seeping from the bulkhead and into the English Kills. Boom was placed and the fence was secured on 10/31/97. "Please respond to this letter regarding the fence repair and the status of the abandoned cars."Letter from F&N (Lorthior) to DEC Tomasello-11/20/97. "The purpose of this letter is to provide you with the results of the title search performed by F&N in an attempt to identify the current owner..." Search indicated that the current owner is the Morgan Oil Terminals Corporation. No current mortgage on property. No record of city seizing property for unpaid taxes.Monthly Monitoring Reports (F&N)-Jan 1997 thru December 1997. Bi-weekly well monitoring, recovery system is total fluid ejector system with 1000-gallon oil water separator/550-gallon product holding tank/carbon treatment for effluent, 781.63 gallons total product bailed from wells via vacuum truck.Meeting notes-2/24/98. Abandoned cars still onsite. "The EFR pilot test was performed on wells FN-11a and FN-15a. The results of the test indicated poor results. The testing has been dicontinued." "An intercept trench or well should be installed along the bulkhead to catch and remove the oil which is migrating towards the canal". Status Report (F&N)-April 1998. A total of 45 monitoring and recovery wells onsite including ten ejector wells. VEFR on as-needed basis. Monthly site visits by

NYC DEP HAZ MAT (Continued) **S102143390**

F&N. "The total mass of contaminant removed from the subsurface by EFR to date was 179.1 pounds. 23 gallons of free product was removed during this period". EFR was discontinued on 12/2/97. Investigation into utilizing bacteria to reduce viscosity of free product was initiated. Test results still pending. General groundwater flow direction is towards the English Kills and radially from storage tanks. Three separate plumes onsite. Report recommends: 1)installation of an ejector into FN33 2)installation of a well along bulkhead.Hazardous Waste Manifests (State of Conneticut)-10/7/98. Letter from F&N (Lorthior) to DEC Tomasello-10/30/98. Investigation to reduce viscosity with bacteria. "Therefore it is suggested that we simply use Bio-solve to begin the process while we investigate whether steam or hot water is a possibility". F&N wants to test bio-solve in one or two wells as pilot test.Letter from F&N (Morisen) to DEC Tomasello-11/2/98. Request for approval to use Bio-solve in selected wells. Proposal to inject and remove Bio-solve with vacuum truck.Status Report (F&N)-3/2/99. 45 monitoring and recovery wells onsite including ten ejector wells. Monthly site visits. Work including reinforcing bulkhead, jackhammering on one area to prevent cars from coming onto site, pumping of oil/water separator, repair of fence, trenching to install new ejectors, installation of one 4" well. Test results of bacterial reduction of viscosity still pending. Groundwater flow towards the English Kills and radially outward from storage tanks. Three free product plumes onsite. Report recommends continuing to investigate viscosity reducing products.Letter from F&N (Lorthior) to DEC Tomasello-10/8/99. "The purpose of this letter is to inform you of F&N's planned use of EFR in conjunction with Biosolve...". "F&N has decided to perform the initial EFR event on the plume of #6 fuel oil located in the northwest corner of the site".Status Report (F&N)-3/2/99. 47 monitoring and recovery wells onsite including ten ejector wells. MBi-weekly site visits. Work included pressure washing of ejectors, pump/surging of wells. Test results of bacterial reduction of viscosity still pending. Groundwater flow towards the English Kills and radially outward from storage tanks. Three free product plumes onsite. Report recommends continuing to investigate viscosity reducing products such as Biosolve.Site Status Report (Miller)-Jan 2001 thru June 2001. A total of 45 monitoring wells and ejector wells onsite. Monthly site visits by Miller. Work included replacing heat tape and insluation on product tanks, checked all ejectors, vaccumed product out of tank and wells, serviced compressor, VEFR on wells with free product. Report recommends cleaning bio-fouled wells with peroxide, installation of new holding tanks and new carbon units.Site Status Monitoring Report (Miller)-July 2002 thru Nov 2002. A total of 45 monitoring wells and ejector wells onsite. Work included well monitoring and VEFR, bi-weekly well monitoring, collection of groundwater samples. Miller (aka MEG) in process of submitting a proposal to removal all USTs and contaminated soils onsite. Report recommends monthly VEFR events, monthly monitoring and quarterly sampling, and replacement of the burnt out ejector panel to make the remediation system operational. Well monitoring shows: .02' FP(FN-11a), oil too thick to measure in wells FN15a, FN17a, FN28a, FN32, FN33a and FN34. Groundwater samples show: 19ppb MTBE(MW24), 15ppb xylene(MW22), 20ppb MTBE(MW23), 51ppb MTBE(MW40), 5ppb toluene(MW20), 15ppb ethylbenzene(MW20), 69ppb xylene(MW20).Memo fromn DEC Sigona to DEC Nagi-12/12/03. Memo of site status. Recovery system not operational, monthly site monitoring, all tanks have been cleaned, hazardous waste cleanup cost incurred in

NYC DEP HAZ MAT (Continued) **S102143390**

addition to Oil Spill Fund recovery effort, lien still on property, two consent orders onsite, owner and operator have failed to comply with consent order.Remediation System Evaluation (EPA)-6/11/04. Report recommends: 1)analysis of chlorinated solvents and PAHs to monitoring program for at least two quarters 2)removal of storage tanks and loading docks and possible removal of underlying soil contamination 3)updating of site conceptual model 4)location of the discharge permit. EPA agrees with termination of VEFR events and reduction in well monitoring frequency. Report also recommends remedial approach based on institutional controls and installation of a passive skimmer to remove free product. Additions of biosolve "were not effective". Majority of ejector pumps are not operating as they are in need of repair (only four pumps are operating). "The ejector pumps require frequent servicing and parts are difficult to obtain". Report proposes three options for addressing soil contamination: 1)delineation of soil contamination 2)removal of contamination within one foot of surface as a temporary solution 3)excavation of impacted soils to a depth of 5' below grade (depth to groundwater). Report also suggests that removed soils can be reused for asphalt, brick or construction material pending analysis of chlorinated solvents. Report recommends removal of structures first. Report recommends monthly monitoring as opposed to bi-weekly, and after four quarters of sampling for the first year, reduction to semi-annual monitoring. Current system not effective at product removal of containment of product. "The only active remediation that would have a good chance of removing a substantial percentage of the petroleum mass at the site is excavation to below the water table". "Excavation at the site does not appear to be warranted at the site due to the apparent lack of exposure pathways and the relatively low toxicity of the fuel oil". Site team should consider passive skimming and perodic bailing and institutional controls for long term remediation. If benzene concentrations persist at FN26 then VEFR should be implemented for one year to decrease the concentrations. Approach to implementation:1)sampling of all wells for chlorinated hydrocarbons2)removal of site structures and tanks3)investigation and/or excavation of soils beneath the structures to facilitate sale of property (vapor toxicity is low and potential vapor intrusion could be addressed by design/construction methods).4)development of a site conceptual model.Fax from AG (Buss) to DEC Tipple-10/21/04. Property sold to:RCC and York Associates350 Jericho TurnpikeSuite 101Jericho, NY 11753Ph: (516-942-3600)11/8/05-Vought-File review continued by Vought:Site Status Monitoring Report (Miller)-March 2003 thru October 2004. 45 monitoring wells onsite including ten ejector wells. Remediation system was removed from the site in February 2004. Bi-weekly groundwater monitoring and quarterly groundwater sampling. Free product has been indentified since March 2003 in wells: 11a, 15a, 16a, 17a, 18, 26, 28a, 31a, 32, 33, 33a, 34 and 36. Report recommends continuation of current monitoring and sampling schedule. Groundwater analyticals show: 6ppb xylene(MW1), 110ppb benzene(MW2), 15ppb xylene(MW2), 200ppb MTBE(MW2), 31ppb MTBE(MW4), 14ppb toluene(MW5), 490ppb ethylbenzene(MW5), 1400ppb xylene(MW5), 8ppb xylene(MW7), 12ppb xylene(MW10), 21ppb toluene(MW16a), 120ppb ethylbenzene(MW16a), 340ppb xylene(MW16a), 10ppb benzene(MW19), 480ppb toluene(MW19), 3400ppb ethylbenzene(MW19), 11000ppb xylene(MW19), 5900ppb MTBE(MW19), 14ppb toluene(MW20), 94ppb ethylbenzene(MW20), 310ppb xylene(MW20), 28ppb MTBE(MW22), 5ppb toluene(MW24), 57ppb ethylbenzene(MW24), 220ppb xylene(MW24), 25ppb

NYC DEP HAZ MAT (Continued) **S102143390**

MTBE(MW24), 39ppb ethylbenzene(MW25), 120ppb xylene(MW25), 20ppb MTBE(MW25), 12ppb toluene(MW26), 130ppb ethylbenzene(MW26), 350ppb xylene(MW26), 26ppb ethylbenzene(MW27), 73ppb xylene(MW27), 7ppb xylene(MW28A), 12ppb ethylbenzene(MW29), 40ppb xylene(MW29), 12ppb MTBE(MW29), 39ppb ethylbenzene(MW30A), 120ppb xylene(MW30A), 12ppb toluene(MW35), 73ppb ethylbenzene(MW35), 240ppb xylene(MW35), 8ppb toluene(MW36), 130ppb ethylbenzene(MW36), 400ppb xylene(MW36), 6ppb xylene(MW38), 11ppb MTBE(MW40). Waste Characterization Report (Philip Services)-4/20/05. Disposal for oil.Letter from Foreht Last Landau & Katz to DEC Tipple-4/29/05. "Further to our discussion of several weeks back you advised you were going to send me a breakdown of the damage caused and approximate repair costs or a bill if available. We would also appreciate it if you have any documents as to the cause of the accident".Letter from Foreht Last Landau & Katz to DEC Tipple-5/11/05. "...we are still awaiting a breakdown of the charges and repair costs for th damage to the above property".Letter from GeoQuest (Casslar) to DEC Tipple-7/11/05. GeoQuest hired by RCC & York "Complete site remediation would appear to be neither practical or cost effective". "If NYSDEC can agree in concept to the attached program and in consideration of the significant expense that will be expended by our client in effecting this program, our client would be willing to offer 25,000 to NYSDEC to waive all of their existing liens and or penalties against the property". "Consequently excavation and removal of all petroluem contaminated soil at this site may be unfeasible and cost-prohibitive". "Partial removal, possibly in combination with an engineering control or an engineered control with no removal is expected to be protective of human health". Proposal to: 1)excavate and remove tanks and piping 2)prepare a site investigation plan to determine the depth and lateral extent of petroleum contamination.Site Status Monitoring Report (National Environmental)- (Nov 2004 thru June 2005). Biweekly monitoring and quarterly groundwater sampling. 45 monitoring wells onsite. "On April 4, 2005 a spillage of petroleum was noted on the property by NEMA. A pipe associated with the overhead filling station of the operations terminal appeared to have leaked onto the ground and into a solid bottom drain on the property. The NYSDEC manager (Michelle Tipple) was notified of the spill. As per Ms. Tipple's request Milro Inc was contracted to clean up the spill. Report recommends continuation of biweekly monitoring and quarterly sampling. Free product in ten wells.11/8/05-Vought-Questions for AG Buss: 1)is DEC willing to waive existing liens and penalties 2)should we have STIP or consent order? Vought called Buss and left message to return call. Vought confirmed meetign time with GeoQuest Casslar (cell 860-841-4851).DEC requires: 1)addition of chlorinated solvents to monitoring parameters 2)surrounding area site plan due to possible offsite impacts to MW19 3)removal of all tanks and structures and collection of endpoint samples from excavation and analysis for total list VOCs. 4)investigation of soils under storage tanks via submission of a Investigation Workplan 5)excavation of all areas with free product 6)continuation of monthly monitoring and quarterly groundwater sampling 7)DEC notification of tank and structure removal so site visit may be performed 8)determination of groundwater flow directions 9)submission of a detailed demolition plan including health and safety, dust control, vapor monitoring and confined space entry 10)notification to Mayors Office of Environmental Coordination (as per DEC Austin) 10)current round of groundwater samples and well locations 11)documentation of end use.11/9/05-Vought-Received message

NYC DEP HAZ MAT (Continued) **S102143390**

from AG Buss. Vought returned call and left message to return call. Vought spoke to Buss and property was acquired with liens. Buss suggested that a meeting be held simultaneously with AG and Mayors Office so that both agencies could be included in discussion. After site meeting scheduled for today, Vought will schedule teleconference with AG Buss, DEC Austin, DEC Vought, Mark Casslar (GeoQuest) and rep for current owner. AG Buss also suggested Stipulation Agreement be signed for future work. Site visit by Vought with DEC Austin, DEC Piper and DEC Ketani. Onsite were GeoQuest (Marc Casslar aand Mike Susca) and RCC(Arthur Schwartz 732-905-1008). Result of meeting was that DEC will send approval of conceptual remedial action plan and require demolition plan and health and safety plan. Vought received call from Buss and returned call and he approved of sending letter approving of conceptual site plan pending the inclusion of a specific RAP and signing of Stipulation. 11/14/05-Vought-Recevied call from Ted Yen (Don Carlo). His client was looking to buy site from RCC. Vought explained that this was not mentioned during the 11/9/05 site visit and that he should contact RCC. Once RCC informs DEC of intent to sell than remedial options may be discussed with Don Carlo. Vought received call from Aaron Abraham (RCC 718-514-3782) and informed him of pending DEC letter. Contact info for RCC is:Mr. Aaron AbrahamRCC & York Associates, LLC46 Main StreetSuite 225Monsey, NY 10952Fax: (718) 732-4549Vought received approved letter from DEC Austin and sent letter to Abraham and cc'd McIntyre (Mayors Office of Enviro. Coord.) and AG Buss. Vought received call from Cindy Swain (Broadway Concrete 718-218-9700) and she is working with New York Industrial Development Association. Vought gave Swain number of Abraham and told her to call him and send in letter documenting such.1/3/06-Vought-Contract Payment Package (Miller)-Well monitoring, monthly electric bill (01/23/04-02/05/04). Payment approved as per DEC Karwiel due to paid invoice not in file and check not cut as per FMIS.1/03/06-Vought-Contract Payment Package (Miller)-Liquid disposal, well monitoring, monthly electric bill, well VEFR (11/07/02-01/29/03). Payment approved as per DEC Karwiel due to paid invoice not in file and check not cut as per FMIS.1/3/06-Vought-Contract Payment Package (Miller)-System check and maintenance, well monitoring, entering well data, well sampling (05/13/03-06/12/03). Payment approved as per DEC Karwiel due to paid invoice not in file and check not cut as per FMIS.03/07/06- Thomas-Contract Payment Package- National Env. Mgmt- Preparation of hydrographs and tables for report, review of site figures, report preparation, fluid level monitoring and recording (08/01/05-09/30/05).03/16/06-Thomas- Contract Payment Package-(National)- reviewed groundwater results, prepared table, prepared report, monitored fluid level (10/01/05-11/30/05).06/13/06-Vought-Received Monthly Report for May 2006 from the Oil Spill Unit in the Civil Recoveries Bureau of NYSOAG. Report shows settlement dated 5/15/06. 06/19/06-Vought-Received call and spoke to Mike Pinehas (Sahmip Holdings 917-771-6434) who is interested in buying property.10/13/06-Vought-Spoke with DEC Austin who was contacted by NYSOAG Buss. Robert Feller (Attorney for RCC York 518-533-3000) sent in copy of agreement between RCC and NYSOAG/Comptroller. RCC will pay fines and environmental lien will be removed from property and BCP Program will be considered. Vought forwarded copy of agreement to DEC Lesser as per DEC Austin for review to see if BCP application will be considered in light of settlement with

NYC DEP HAZ MAT (Continued) **S102143390**

NYSOAG.11/15/06-Vought-Received call from Josh Kaplan (GeoQuest 860-243-1757) and returned call and left message. Vought spoke to Kaplan who is requesting most recent National report and is currently working for RCC.12/18/07-Vought-Received call from DEC Central Office Drew Willette showing that RCC is not owner and Corpus Christi Resources does own property. 07/25/08-Vought-Spill reassigned from DEC Vought to DEC Ketani as per DEC Austin. 1/15/09 - Raphael Ketani. William Buss of the OAG (518) 474-8012 sent Randy Austin, Chief of the Spills Unit in Region 2, a copy of a Texas Findings of Fact document regarding a bankruptcy proceeding which was handled by the Corpus Cristi Division of the Southern District of Texas. The document is dated 11/13/08. The document was forwarded to me and I was told to contact the new owners of the property, English Kills Ventures, LLC, and to find out whether they intend to continue the remediation of the site.I contacted Mr. Campbell (713) 654-8111, but he said that Mr. Hancock (713) 951-5880 was the one who knows who the contact person at English Kills is. I tried to contact Mr. Hancock, but could only leave a message.Mr. Hancock's secretary called me back. She said that English Kills' attorney was Hillel Kurzmann at (845) 835-6300. She said that his e-mail is hkurzmann@kurzmannlaw.com.I tried calling the number, but it was always busy. So I e-mailed Mr. Kurzmann and asked him whether his client was going to continue the remediation of the site.1/16/09 - Raphael Ketani. Marc Casslar of GeoQuest (860) 243-1757 called to say that he has been retained by English Kills Ventures, LLC to perform the remediation work at the site. Mr. Casslar said that the first steps will be to demolish the buildings and remove the tanks before the investigative work takes place. He added that asbestos removal will also take place. Mr. Casslar said that DEC will receive an investigation plan. 2/3/09 - Raphael Ketani. I tried to contact Mr. Casslar, but found out he wont be back until tomorrow. I was put in touch with Jay Soltis, Senior Associate at the same number. He said that he works with Mr. Casslar on the case, but he hasn't heard of any progress regarding demolishing the buildings and removing the tanks.I spoke to Mr. Soltis again. He said that the asbestos survey started about 1/25/09 and the tanks are being inspected to see what is in them and how much. I told him to keep me informed about progress at the site and to let me know when the tanks are going to be pulled. He said he will.I had a meeting with Randall Austin, Chief of the Spills Unit, regarding the product tanks. He said that the tanks should not be moved, nor any disturbance of the piping or ground until DEC receives and approves a site demolition and remediation plan, and the owners send back a signed STIP agreement regarding the plan. Mr. Austin told me to keep him, John Urda and Bill Buss informed as regards progress at the site.I tried to contact Mr. Soltis (860) 243-1757 to let him know that a plan has to be submitted, but could only leave a message. 2/5/09 - Raphael Ketani. I made an unannounced site visit. There was no activity at the site, nor did I see that any demolition had taken place. The site was filled with many thousands of pieces of dismantled construction scaffolding. I walked along the west and south sides of the property and looked inside where I could. All I could see were piles of scaffolding. 2/24/09 - Raphael Ketani. I made an unannounced site visit. There was no activity at the site, nor did I see that any demolition had taken place.2/25/09 - Raphael Ketani. I tried contacting Mr. Soltis and Mr. Casslar at (860) 243-1757, but they weren't in. So I contacted Mr. Casslar at his cell (860) 841-4851. I

NYC DEP HAZ MAT (Continued) **S102143390**

asked him for the owner's name and phone number. I told him that the project needs to get started. However, I told him that no work should take place regarding the tanks and piping until DEC has approved the work plan and English Kills Ventures, LLC has signed and returned a STIP agreement. Mr. Casslar felt that the STIP was uncalled for as he explained that the tanks and piping had been cleaned out and because his client has owned the property for only 60 days. I told him that the STIP is not a legal judgement, but only a contract that specific work will be performed and on a set schedule. He asked me to send him an e-mail describing what DEC wanted at this time regarding the project. I sent him an e-mail (mcasslar@geoquestinc.com) regarding the need for an owner's name and phone number, and that DEC is asking for a work plan and that DEC will send a STIP to the owner. 2/27/09 - Raphael Ketani. Bob Feller of Bond Schoeneck & King (518) 533-3222 called. He said that his law firm has been retained by English Kills Ventures, LLC. Mr. Feller's e-mail is: rfeller@bsk.com. I sent Mr. Feller an e-mail requesting English Kills Ventures' mailing address.Mr. Feller e-mailed me back that the client is in Israel and wants all correspondences to go through his lawyer, Mr. Feller. So Mr. Feller wrote that the mailing address should be:English Kills Ventures, LLCc/o Bond, Schoeneck & King, PLLC111 Washington AvenueAlbany, New York 12210Attn: Robert H. Feller3/10/09 - Raphael Ketani. I contacted Mr. Soltis of GeoQuest at (860) 243-1757. He said that no work is taking place at the site. He said that they are putting together the environmental aspects of the proposed work plan for the site. These parts of the document will be added to the demolition aspects of the plan. The demolition aspects will be written by the demolition company. I asked him whether any work has taken place. He said that staff from his company only inspected the tanks and nothing else. I reminded him that no work at all is to take place at the site until DEC has an approved plan in hand. He said that Mr. Casslar had told him this. With that, the conversation ended.3/11/09 - Raphael Ketani. I contacted Mr. Soltis again. I gave him a verbal outline of the revised STIP CAP. He said that it sounded alright. I asked him when he can get the Remedial Investigation Work Plan to DEC. He said that he is still waiting for the asbestos contractor to write and submit their part. I suggested to Mr. Soltis that he simply include a few paragraphs describing how the asbestos work will be done, as a separate section in the plan, rather than waiting any longer for the asbestos removal plan itself. He said that he will do this. I asked him again how quickly he can get the environmental RIWP to the client who is in Israel. He said that the client is usually quick with his e-mail responses. He will send the RIWP this week by e-mail. Mr. Soltis believes that the client will respond sometime next week.3/18/09 - Raphael Ketani. I sent a STIP package to Mr. Feller with a deadline of 4/18/09. 3/25/09 - Raphael Ketani. I visited the site today. It is still full of dismantled scaffolding. 4/15/09 - Raphael Ketani. I received the following e-mail today from Mr. Feller:Mr. Ketani - I wanted to update you on the review of DEC's proposedstipulation for the captioned site. As I'm sure you know, the file onthis site is very extensive. My clients just purchased the site a fewmonths ago and they are still in the process of reviewing it with theirtechnical consultant. They are also awaiting additional documents fromDEC as a result of a FOIL request made around 6 weeks ago. It is my clients' intent to work cooperatively with DEC. Our review ofthese documents is intended to inform our decision either to apply underthe Brownfields Cleanup

NYC DEP HAZ MAT (Continued) **S102143390**

Program or to tailor the stipuluaton to betterreflect the specifics of this site, both in terms of site conditions andthe studies and investigatory work already performed. It is my intentto provide you a further update in a few weeks as our review processprogresses. If you have any questions, pls call me at your convenience. BobFeller4/22/09 - Raphael Ketani. I had a meeting with Randall Austin, Chief of the Spills Unit, regarding the site and whether the owners have sent in the signed STIP. I told Mr. Austin that the STIP submission deadline had passed on 4/18/09, but Mr. Feller had e-mailed me on 4/15/09 that he wanted to tailor the STIP that he received so that it better reflects the site conditions and the work that had been done. Mr. Austin told me to contact Mr. Feller (518) 533-3222 and arrange a meeting with him and the owners at DEC. I tried to contact Mr. Feller, but could only leave a message with his secretary. Mr. Feller called me back. He said that he will talk with his client and let me know several dates for a meeting that are acceptable to them. I told him to choose dates that are as close to or in the first week of May as possible.5/18/09 - Raphael Ketani. I spoke to Mr. Feller. I asked him why he hadn't set up a meeting date for here at DEC with his client. I reminded him that we last talked on 4/22/09 and he had told me then that the meeting would be set up for either the end of April or the beginning of May. I told him that it's almost the end of May! He said that his client was a new owner and they had to review the documents they had received via the FOIL request. I told him that they have had a month to review everything. I asked him whether there was a problem. He said that he will contact his client and get back to me. I had a meeting with Randall Austin, Chief of the Spills Unit, to discuss the lack of progress on the case. Mr. Austin mentioned that the bankruptcy settlement put money in escrow for the cleanup of the site. Mr. Austin asked me to draft a letter to English Kills Ventures, LLC.5/21/09 - Raphael Ketani. Mr. Feller sent me an e-mail today:Mr. Ketani - I communicated with my client to discuss scheduling ameeting in your office. Due to the volume of material in the FOILresponse, the review is taking longer than first estimated. Both myclient and their technical consultant are actively going through thesematerials.We are anxious to meet with DEC to determine the direction for theproperty but we believe that the meeting will be most productive ifeveryone on our side is up to speed. I will be in touch with you in acouple of weeks to update you on our progress and let you know if we arein a position to schedule a meeting. Thx. Bob Feller5/27/09 - Raphael Ketani. A Case Initiation Form was sent up to Region 2 Office of General Counsel.6/5/09 - Raphael Ketani. Mr. Feller sent me an e-mail today. In his e-mail, he stated that they are almost done with the document review and will be able to meet with DEC in a week or two. 6/12/09 - Raphael Ketani. I sent Mr. Feller an e-mail requesting an update regarding the writing of a plan for investigating the site, and the setting up of a meeting with DEC.6/25/09 - Raphael Ketani. Mr. Feller sent me an e-mail that had suggested days for a meeting with DEC. We conversed back and forth via e-mail and I also e-mailed DEC staff to see what days they were available. Mr. Feller and I agreed upon 7/15/09 at 10:30AM as the date for the meeting between Morgan Oil owners and DEC staff.7/21/09 - Raphael Ketani. Marc Casslar of GeoQuest (860) 243-1757 sent me a Proposed Conceptual Approach to Site Remediation. This document was a remediation plan to be used in discussions during a planned meeting with the client's representatives tomorrow at DEC. In the document, they essentially state that it is not economically feasible to fully

NYC DEP HAZ MAT (Continued) **S102143390**

remediate the site. They do not describe the removal of the tanks and piping. They do, however, present information which shows where they discovered very viscous free product during a 2006 investigation. They state that the product is not recoverable to the extent practical. Though, the most contaminated soil will be removed. The end of use of the site is not set. The site may have a building erected on it or just a cap. 7/22/09 - Raphael Ketani. A meeting was held at the DEC today to discuss the status of the Morgan Oil Terminal and a possible remediation plan. The meeting was held today as the owners and their representatives couldn't attend a meeting on 7/15/09. In attendance were Marc Casslar (president) and Jay Soltis (senior associate) of GeoQuest, Ryan Karben of IGR (attorney), Robert Feller (attorney) of BSK, and John Urda (DEC Assistant Regional Attorney), Randall Austin (Chief of the Spills Unit), myself, and Brandon Harrell (DEC legal intern).Mr. Casslar stated that it is unknown what will be done with the site after the remediation. It all depends on the economy. Also, he stated that even though the Proposed Conceptual Approach didn't state so, the tanks, infrastructure, pipes and buildings will all be removed from the site. Once the tanks are removed, then remediation will take place. The free product is too viscous to recover except by excavation. Contaminated soil that is found to have free product will be removed. However, Mr. Austin commented that the State requires all oil contamination that is above TAGM to be removed. He went on to ask what data indicated the presence of free product. Mr. Casslar responded that this was based on the work done in 2006 and work done by other clients. They will remove 1200 cu. yds. of soil. However, Mr. Casslar stated that he didn't believe it was possible to remove all of the contaminated soil that was above TAGM. He said that it wasn't financially possible to do so. Mr. Austin stated that the tanks are leaking. Though Mr. Casslar remarked that there is no evidence that the tanks are leaking. Mr. Casslar added that there will be additional investigating at the site. He believed that 75% of the soil will be clean. Remediation will take place in less than 2 years. GeoQuest will be the supervising contractor. Mr. Casslar stated that he believed it wasn't possible to remove all of the contaminated soil. The site is tidally influenced and the contamination is below the tide. The site would be capped. Mr. Feller commented that there are cases where the site is closed above the standards. Mr. Austin stated that it is premature to discuss this. Mr. Casslar stated that the bulkheading will be repaired. Mr. Austin suggested that they start by gauging the wells and submit the 2006 data. Then we should reconvene and decide what can be done. Mr. Urda stated that the project can be performed under a STIP or a Consent Order. A Consent Order involves penalties, but a STIP doesn't.Mr. Casslar wanted to know whether it was possible to enter the brownfield program. Mr. Austin described what needed to be done in order to apply to the brownfield program. He also described what the brownfield program entailed regarding tax rebates, the owner is considered free of liability, the goal of the project (i.e. commercial or residential development). Mr. Casslar was given the name of the head of the brownfield/superfund program, Jane O'Connell. Mr. Austin finished by stating that the owner can explore the possibilities, but he can't hold off doing the remediation for the site. Mr. Austin stated that the City and the community are very interested and concerned about the site and wish that the cleanup move forward quickly, given that the site was the location of extensive previous criminal activity. He asked that if the owner

NYC DEP HAZ MAT (Continued) **S102143390**

wishes to enter the brownfield program, then he should let DEC know as quickly as possible. Mr.Casslar stated that work will start in the next week or two.8/6/09 - Raphael Ketani. Today I received the Summary of the 2006 Subsurface Investigation report by e-mail from Jay Soltis of GeoQuest, Inc. (860) 243-1757. I reviewed the report. The soil sample results from the seven borings were below the detection limit or far below TAGM. The groundwater sample results were below the detection limit or below TAGM, except for the sample from B-7. The results for B-7 greatly exceeded TAGM (i.e. 1120 ppb 2-methylnaphthalene). Mr. Solits wrote that they expect to finish the current round of groundwater sampling and gauging next week.9/2/09 - Raphael Ketani. I made an unannounced site visit. There were people loading scaffolding material onto trucks. The parking area was crowded with trucks. I walked into the site as far as I could. The walkway appeared to dead end at a pile of scaffolding material. The sides of the walkway were piled high with scaffolding. I could not determine how the staff from GeoQuest had made their way into the site to access the wells and collect groundwater samples. Otherwise, no work appeared to be taking place. 9/4/09 - Raphael Ketani. I spoke to Mr. Soltis. He said that the groundwater was sampled on 8/12/09. There was product in some of the wells, but the wells without product were sampled. The analytical report is with the client. As soon as he is done and the report is finalized, then Mr. Soltis will send it to DEC. 9/23/09 - Raphael Ketani. Today I received the 9/18/09 2009 Groundwater Investigation report from GeoQuest. I began my review.9/24/09 - Raphael Ketani. The report states that the historical plans indicated that 34 monitoring wells were previously installed at the site. During GeoQuest's December 2006 visit, the location of 24 wells were identified. Five wells were destroyed or unuseable. Fourteen wells were gauged and five had product. A limited subsurface investigation was performed on 12/6/06 and seven borings were installed.During the limited investigation, groundwater was encountered at 7.5 feet below grade. Temporary 1" wells were installed at B-3, B-4 and B-7. Groundwater samples were collected from six of the earlier wells.GeoQuest visited the site on 8/12/09 and located nine of the wells. The depth to groundwater was measured and was found to be from 3' to 9' below grade. Viscous, black oil was encountered in four wells (FN-11, FN-15A, FN-16A, FN-34). The report states that, based upon the laboratory analytical results, there is minimal groundwater contamination at the site. GeoQuest doesn't believe that there are many soluble components in the oil. They also believe that the oil is not a continuing source of contamination.I reviewed the analytical results. Soil samples from B-2 and B-7 were the most contaminated of the December 2006 boring samples. VOCs were almost entirely below the method detection limits for all of the samples. The analytes with the highest measurements and the most TAGM exceedences were the benzo series SVOCs and their combustion product associates. Exceedences were ten to 100 times the TAGM limit. Regarding the groundwater samples, most of them were entirely below the detection limits for both VOCs and SVOCs. The sample from B-7 had the most hits and these were only SVOCs. The exceedences were 24 to 646 ppb.The groundwater elevation results were highly variable. The depth to groundwater was from 3.19' to 8.46' below grade. It is not clear why the results vary so much. 10/7/09 - Raphael Ketani. Mr. Soltis called today. He said that they plan to knock down the buildings as the next step. I asked him why. He said that this will give them enough room to move around and do other work. I asked him

NYC DEP HAZ MAT (Continued) **S102143390**

whether there is any more asbestos insulation. He said he didn't know. 10/29/09 - Raphael Ketani. I spoke to Mr. Soltis (860) 243-1757. He said that staff at GeoQuest, Inc. have been discussing how to go about demolishing the buildings and abating the asbestos. He said that they have a licensed asbestos abatement company to do the abatement. This company will provide documentation that they are licensed and other documentation showing where the asbestos will be disposed of and that this site is approved to receive asbestos. I told Mr. Soltis that the DEC wanted copies of these documents. He said that he will send them. He added that they are also working with the tenant, the scaffolding contractor, to get him to move his material over so that the demolition can take place. 11/13/09 - Raphael Ketani. Today I received a letter by e-mail from Mr. Casslar of GeoQuest (860) 243-1757 dated 11/13/09. The letter indicated that, as part of the first phase of work, the asbestos will be removed. T.C.L. Environmental, Inc. will perform this work. The work shall begin on about 11/30/09. 12/3/09 - Raphael Ketani. I spoke to Mr. Soltis. He said that he wasn't sure whether the asbestos abatement work had started. He said that the work was being handled by T.C.L. Environmental. So GeoQuest was not very involved in this aspect of the remediation. He will find out what's happening and let me know.12/4/09 - Raphael Ketani. Mr. Soltis sent me an e-mail stating that the application to do the asbestos abatement work was filed earlier this week. So he expects the work to start either next week or the week of the twenty first of December.12/23/09 - Raphael Ketani. I spoke to Mr. Soltis (860) 243-1757. He said that the contractor was supposed to keep him informed regarding when the work will start and when they are finished. However, he hasn't heard anything from them. I asked him to call them up and see what is happening, and then to send me an e-mail or a phone message. Mr. Soltis said that he will do this. 12/29/09 - Raphael Ketani. Mr. Soltis sent me an e-mail stating that the contractor has set up at the site for the asbestos abatement work. However, they are waiting for the cold weather to end before they commence the actual physical removal of the asbestos.2/9/10 - Raphael Ketani. I tried to contact Jay Soltis (860) 243-1757, but could only leave a message.2/10/10 - Raphael Ketani. I received the following e-mail from Mr. Soltis today:The asbestos job is fully complete, and our client has an ACP-7 indicatingthat all abatement has been completed. We are hoping to begin theadditional soil/groundwater investigation once the structures have beenremoved and this Winter weather clears out.4/1/10 - Raphael Ketani. I contacted Jay Soltis (860) 243-1757. He said that the contractor told him that the asbestos removal had been completed. However, he hasn't heard anything from them in a long time. He will call them and try to find out what is going on.4/19/10 - Raphael Ketani. I tried to contact Mr. Soltis, but could only leave a message regarding progress at the site.Mr. Soltis sent me an e-mail today. He wrote that a contractor has been selected to remove the surface structures. However, they are waiting on the permits from the NYC DOB so that they can begin the work.5/25/10 - Raphael Ketani. I tried to contact Mr. Soltis regarding progress at the site, but could only leave a voice message.Mr. Soltis sent me an e-mail stating that they are working on obtaining the permits for performing demolition at the site.7/12/10 - Raphael Ketani. I contacted Jay Soltis (860) 243-1757. He said the last he had heard from the owners was about a month ago. He said that their last e-mail to him stated that they had 5 or 6 people working on obtaining the necessary demolition permits from the

NYC DEP HAZ MAT (Continued) **S102143390**

NYC DOB. He added that the owners usually don't contact him during this stage of the project. I told Mr. Soltis to call them and to find out where the project stands. He said that he will.I received the following e-mail today from Mr. Soltis:I spoke with our client and the only thing left prior to obtaining the demopermit is utility cut-offs for electricity, water, etc. They have an"expediter" that is currently working on this.Once the cut-off documentation is completed, the paperwork will be ready forsubmission to the Building Dept. I have asked them to let me know as soonas the paperwork has been submitted so I can keep you updated. Regards,-Jay9/23/10 - Raphael Ketani. I spoke to Jay Soltis (860) 243-1757. He said that they did all of the demolition work. So the buildings are gone. They dug some test pits. They are waiting for the test results to come back. He will keep me posted regarding progress at the site.11/10/10 - Raphael Ketani. I spoke to Mr. Soltis. He said that he had the test pit soil results. He said that he will send the DEC a table containing the results. The results showed that the analyte concentrations didn't exceed TAGM, but there is light residual contamination. So the soil will be used as fill material on site. I asked Mr. Soltis why the test pits had been performed in the first place. He said that there were some berms next to the tanks and they wanted to see whether they needed to dispose of the soil off site or whether it could be re-used. He added that the next step is to expose the tanks and remove them, but the owners haven't given the go ahead yet to do this work.12/16/10 - Raphael Ketani. I spoke to Jay Soltis (860) 243-1757. He said that no work is taking place now. The big issue is the lack of room to manuver the excavator. So the owners have evicted the scaffolding supply tenant. The tenant hasn't finished removing his material, but should complete this work soon. Once the tenant is out, then they will contact the owners and see whether the excavation and tank removal work can proceed.Mr. Soltis sent me the soil analytical data from the test pit samples along with a cover memo. The memo described the test pitting. The data consisted of only SVOCs and the results were almost entirely below the TAGM limits, except for some of the benzo series analytes and chrysene.12/29/10 - Raphael Ketani. William Hughes of GeoQuest called me today. He said that he is the project engineer for the site. He asked whether the contractor can leave the tank bottom in place for a very large tank of 100 feet long by 80 feet wide (600,000 gal. capacity). I told him that would be fine, but the DEC will want the soil sampled underneath the tank bottom. He said that this will be done. I told him that Part 375 has guidance regarding how many borings are necessary per linear or square footage. He said that he will follow the guidance. I asked him why the contractor wanted to leave the tank bottom in place. Mr. Hughes said that the contractor had removed a lot of soil and the scaffolding company owner still had some of his materail on site. This resulted in not much room for the excavated soil that came from the sides and top of the tank. So the contractor wants to backfill the tank bottom as he goes. I said that this sounded alright, but if contaminated soil is found below the tank bottom, then the backfill and the tank bottom will have to come out. Mr. Hughes said that he understood. With this the conversation ended.1/14/11 - Raphael Ketani. I contacted Mr. Hughes. He said that they were working on the 600,000 gal. tank (actually divided into 400,000 gals. and 200,000 gals.). However, given the snow and the crowded conditions, work had stopped. He is expecting to start again soon.Later, Mr. Hughes sent me pictures showing the internal

NYC DEP HAZ MAT (Continued) **S102143390**

structure of the tank.4/28/11 - Raphael Ketani. I contacted Mr. Hughes (860) 243-1757. He told me that the demolition welder is working on the 400,000 gal tank. All piping over the road and across the top of tank is gone. The welder cut out part of the top of tank. There is a concrete slab beneath tank. He has cut the tank down to the ground level in one location. Mr. Hughes said that he did an elevation survey in March. The bottom of the tank is above the water table, which is at 7 feet below grade. The tank is very clean inside. Most of the tank has been removed. I asked Mr. Hughes whether it was possible to do a round of groundwater sampling, as none have been done since late 2009. He said that it was impossible. Only two wells were accessible now. He was aware that there is a pool of #4 or #6 oil below ground. He said that he thought there was a gasoline plume entering from the east (Morgan Avenue side), also. The tenant has brought in more scaffolding and he has covered almost all of the wells and has made the site so congested that there are only walkways through which to pass. I asked Mr. Hughes whether someone can get the tenant to move his material. He said that the tenant was given an eviction notice back in January 2011, but it may be 3 or 4 months until he moves. The problem with the scaffolding overcrowding started back in 2009 and has gotten much worse. I told Mr. Hughes to talk to the owners and to see what can be done to get the tenant to move his scaffoling. Still, the tank dismantling work will continue.Later, Mr. Hughes sent me two photos showing the dismantling of the 400,000 gal. tank.5/4/11 - Raphael Ketani. Today, I visited the site. The scaffolding parts were stacked about 20 feet high in places. There was a worker operating a forklift and moving scaffolding. The site was very crowded. I met Jaques Gallet, the welder at the site. He was working on a piece of metal from the 400,000 gal. tank and was loading his pickup truck. He had finished dismantling everything except the back wall of the 400,000 gal. tank.Once back at my desk, I called Mr. Hughes (860) 243-1757. I told him that Mr. Gallet was almost finished dismantling the 400,000 gal. tank. Mr. Hughes said that Mr. Gallet will work on the 200,000 gal. tank next, which abuts the 400,000 gal. tank. I added that the DEC wanted the soil tested below the tank, even though it looked clean. Mr. Hughes said that it will be tested, but, first, the area needed to be backfilled. Then there will be a flat, stable platform for the drill rig to work on. I told Mr. Hughes that sounded fine. I added that he should submit a work plan to the DEC describing what will happen regarding the tank grave and how the soil below the grave will be investigated. Mr. Hughes said that he will put together a quick plan next week. 6/3/11 - Raphael Ketani. Mr. Hughes sent me an e-mail. He stated that work was continuing on the demolition of the 400,000 gal. tank. It turned out that there was an 18 inch thick concrete wall separating the 200,000 gal. tank and the 400,000 gal. tank. It has been calculated that groundwater is about 1.5 feet below the bottom of the tank. Also, the tank sits on a 12 inch concrete slab. No oil odors have been detected during the excavation. Mr. Hughes also sent pictures of the work as of 5/31/11.6/14/11 - Raphael Ketani. Mr. Hughes sent me an e-mail. He stated that Mr. Guillet had completed the demolition of the 400,000 gal. tank and is in the process of dismantling the concrete structures that held the north and south berms back. No contaminated soil was found. The location will be backfilled with clean soil. He said that the property owner wants to cover the area with asphalt and rent it to another tenant.I wrote back that the owner already has one tenant who is making it difficult for the work

NYC DEP HAZ MAT (Continued) **S102143390**

to progress with all of his material. I suggested that, once the neighboring 200,000 gal. tank is dismantled, this tenant should move his belongings over to the new paved areas.7/8/11 - Raphael Ketani. I tried to call Mr. Hughes (860) 243-1757 regarding progress at the site, but I could only leave a message.7/22/11 - Raphael Ketani. I spoke to Mr. Hughes. He said that he didn't know what was happening at the site. He hadn't been there in a while. Last he knew, Mr. Gallet had found a buyer for the grade A lumber that was recovered as a result of the tank demolition. So this material will be moved out. However, the scaffolding tenant is still there and is supposed to move out at the end of August. Mr. Hughes will make a site visit soon and let me know what the status of the site is. 8/23/11 - Raphael Ketani. I called Mr. William (Bill) Hughes (860) 243-1757 regarding progress at the site. He said that Mr. Gallet is now taking apart the oil piping that is associated with the tanks. The pipes still have a little oil in them and some has spilled onto the ground. I asked Mr. Hughes whether Mr. Gallet is picking up the oil. He said that it's being cleaned up and Mr. Gallet is very aware that GeoQuest is monitoring the work and wants the place to remain clean. Mr. Hughes said that all of the piping is going into a roll off container. Also, the tenant is slowly moving his scaffolding out. So this is allowing Mr. Gallet access to the building on the site for demolition purposes. I asked Mr. Hughes to keep me updated. He said that he will.8/24/11 - Raphael Ketani. I made an unannounced site visit at 11AM. I saw that the tenant was moving his scaffolding out of the site. You can now walk all over the site. At one end of the site, there was a large pile of uncovered soil. This soil was the same type of soil that had been used to fill in the area where the 400,000 gal. and 200,000 gal. tanks used to be. It appeared to be a sandy soil with cobbles of natural rock, burned wood and historical fill. The soil had an apron that reached the edge of the property where the bulkheading was. It seemed reasonable to assume that some of the soil had entered the English Kills. There was a large boat moored at the site. I met the owner. His name is Jonathan Yaney. Mr. Yaney said that he is a real estate agent and works in Manhattan. He said that he had a short term lease with English Kills Ventures, LLC for mooring the boat. He said that it is 180 feet long and that it was difficult to find a long place to put the boat. So that's why it is here. He added that he had a crew doing repairs to the boat, but mechanically, the boat was in good shape. He said that the engines had been refurbished before he had bought it. It was a Martha's Vineyard ferry. I didn't notice any sheens around the boat. So I left the area. Next, I met one of Mr. Gallet's workers. He was transfering oil from one drum to another. I noticed some oily soil near one of the drums. I told him to put the soil in the drum. He said that he has been doing this all along. He then walked me to the Morgan Avenue part of the site. There, he showed me the oil pipes that had been dismantled and more drums full of oil. He also showed me some boiler internal pipes that had been cut up and where boiler dismantling which was taking place inside the old building on the site. Everything looked like things were being done right without any oil spills. So I left the site. While walking out, I noticed that the well which is about 60 feet from Morgan Avenue was missing a steel plate and a plastic cap. Later, I tried to contact Mr. Hughes (860) 243-1757, but I could only leave a message. I let him know that he needed to put up silt fencing and hay bales in order to keep sediment from washing into the English Kills. I also sent an e-mail to the DEC

NYC DEP HAZ MAT (Continued) **S102143390**

Division of Marine Resources letting them know the potential wetlands violations.Mr. Hughes called me back later. He said that he will have Mr. Gallet install silt fencing in the backfilled area and anchor the silt fencing with double staked hay bales. I told him that the DEC Division of Marine Resources was notified about the potential for sediment to enter the English Kills. Mr. Hughes said that he will let his wetlands people know that they may get a call. I added that he needed to get someone to the site to replace the plastic cap to the well and the steel plate. He said that this will be done.8/25/11 - Raphael Ketani. George Stadnick of the Division of Marine Resources called me. He said that he will send letters to English Kills Ventures, LLC and to Mr. Feller regarding the violations of the marine wetlands regulations.English Kills Ventures, LLC, 10103 Fondren Road, Ste 425, Houston, TX, 77096; b&l = 2942/101; Robert Feller (518) 533-3222Later, Mr. Stadnick sent me an e-mail stating that he had contacted Mr. Hughes and told him to put silt fencing and hay bales along the bulkhead perimeter, not just around the soil pile. He asked him to do this immediately. Mr. Stadnick will make an inspection of the site sometime next week after hurricane Irene passes. Also, Imadadul Islam of the Division of Water sent me an e-mail stating that he had contacted the owner and had told him to install sediment and erosion control measures around the soil stock pile and along the bulkhead perimeter.10/3/11 - Raphael Ketani. Matt Cavas of Anchor QEA (518) 792-3709 ext 14 called. He said that his company was tasked by the EPA with putting together a database of sites that may affect the water quality of the Newtown Creek. He added that the Newtown Creek was a super fund site (CERCLA) and that he needed to see the files for the former Morgan Oil terminal. I told him that most of the documents were not electronically stored and that there were a lot of documents in the file cabinet. He asked about the status of the site. I told him that tank, piping and building demolition were presently taking place. He asked whether the oil was leaking into the creek. I told him that, off the top of my head, I thought that all of the oil was contained about 20 feet or so below the site. Mr. Cavas said that he would like to see the file and make copies. I told him to contact our FOIL staff to arrange this. He said that he was told by his DEC contact in Albany that he didn't need to go through the normal process. I told him that since Anchor QEA is not a DEC contractor, then his company is an outside organization, and all outside organizations have to go through the FOIL process. Mr. Cavas said that he will talk to his contact and see whether the file viewing and copying can be expedited.10/13/11 - Raphael Ketani. I called Mr. William (Bill) Hughes (860) 243-1757 regarding progress at the site. He said that he hadn't been to the site in awhile, but his understanding from Mr. Gallet was that the tenant was still removing his scaffolding from the site. I asked Mr. Hughes whether the oil transmission pipes were still there. He said that the pipes had been removed some time ago. Mr. Hughes added that Mr. Gallet had removed some oil contaminated soil from on top of one of the tanks that he hasn't touched. I told Mr. Hughes to give me a progress update when he visits the site. He said that he expected to visit the site soon. 10/27/11 - Raphael Ketani. As part of the caseload realignment order by Randall Austin, Chief of the Spills Unit, I am transfering this case to Jeffrey Vought in the Spills Unit. The synopsis of the case is as follows:The spill was received by the DEC on 11/6/92. The cause of the spill was the leaking of tanks #4 and #5. The tanks also had contained solvents at one time.

NYC DEP HAZ MAT (Continued) **S102143390**

This was a major oil storage facility. The site was owned and leased by several entities. Consent Orders were drawn up for the owners. However, they did not comply with them. Hence, State contractors were hired to cleanup the site and install monitoring wells. The State spent over 1.7 million dollars for cleaning the site, installing 45 wells (some with recovery pumps) and emptying and cleaning out the tanks. On 1/15/09, the DEC was notified that English Kills Ventures, LLC has bought the property. On 3/18/09, a STIP package was sent out to English Kills Ventures. A site visit was made on 3/25/09 and I noted that the site was full of scaffolding. On 5/27/09, a Case Initiation form was submitted to the Office of General Counsel. A meeting with the consultants for the owners and their lawyers took place at the DEC on 7/22/09. On 8/6/09, the DEC received a Summary of the 2006 SIR. The Summary stated that the soil contamination was below the method detection limits. Groundwater analyticals were also below the method detection limits, except for the sample from B-7. On 9/18/09, 2009 Groundwater Investigation Report was received. Twenty four wells were found. Five were unuseable or had been destroyed. Fourteen wells were gauged and five had product in them. A limited site investigation was performed on 12/6/06 and 5 borings were installed. As part of the equipment dismantling, asbestos abatement started during January 2010. Tank demolition started during December 2010. My 5/4/11 site visit revealed that the place was still full of scaffolding. The owner of the scaffolding started removing it during August 2011. Meanwhile, two large tanks and their associated piping had been removed and work was continuing on the other tanks. John Urda is involved in this case. NOTIFY IMMADADUL AND GEORGE WHEN DEVELOPMENT CONSTRUCTION TAKES PLACE2/7/12-Vought-Project transferred from Ketani to Vought as per Austin.4/19/12-Vought-Project manager for PIN project at Morgan Terminal. Located box in file room with notes and reports from DEC Sigona closed spill #9211657 at Morgan Terminal for former PBS Inspection and Case. This file added to PIN drawer as PBS data may be needed for further cost recovery by NYSOAG if applicable. Vought, RSE and NYCOER Mark McIntyre held teleconference on applicability of this site to have site assessment performed via Federal Grant monies that NYCOER received for assessment on petroleum contaminated sites.DEC possibly requires:1)File review for current status and continuation of investigation/remedial/IRM activities2)submission of current status of monitoring wells and initiation of monitoring/IRM if applicable3)E-docing of file (and separate spill as per 4/19/12 notes above)4)Possible call back to NYCOER McIntyre by RSE and/or DEC Patel5)Call to NYSOAG for status of cost recovery and any possible liens on-siteafter discussing with DEC Austin, case transferred to DEC Patel.04/20/12-Hiralkumar Patel. DEC Vought forwarded email from DEC Ketani who received email from Bill Hughes from GeoQuest, Inc. dated 02/07/12. Bill mentioned that scaffolding company has left the site and left mess behind. they are currently cleaning up the site.Bill HughesGeoQuest, Inc.Ph. (860) 243-1757 Ext. 103 (860) 402-9592 (C)email: williamhughes01@gmail.com1:00 PM:- left message for Bill at GeoQuest.2:00 PM:- visited site with DEC Vought. site contains lots of junk left behind by scaffolding company. no environmental work in progress. found multiple wells (some destroyed and some in bad condition) on and around the property. Vought showed a large aboveground tank in concrete vault along south side of the property. some rainbow and silver sheen (could be mixed of biological and petroleum) observed on water in creek along north of the

NYC DEP HAZ MAT (Continued) **S102143390**

site.04/27/12-Hiralkumar Patel.10:16 AM:- received message from Bill.11:43 AM:- spoke with Bill. he mentioned that due to access issue with the previous tenant (scaffolding company) for couple of years and large piles of junk left behind after tenant left, no environmental work is in progress at the site. once all the scaffolding junk removed, they are planning to conduct additional soil/gw investigation for additional data. asked him to send summary of work done till now and future plan. also asked him to submit property owner's contact information.5/8/12-Vought-Vought and Patel held teleconference with NYSOAG Judith Karpen and State will only release lien upon cleanup of site to satisfaction of NYSDEC. Karpen noted that new owner was English Kills and former owner was Corpus Christi and that Corpus Christi declared bankruptcy and as a result State will receive minor settlement amount in lieu of total monies spent. Karpen noted that Corpus Christi may have secured eight million dollar loan for cleanup (as per former OAG Buss) but not sure if monies are being used for cleanup and also not sure whether Corpus Christi or English Kills is supervising cleanup. Karpen will begin file research upon completion of file review by DEC Patel and subsequent call to NYSOAG Karpen. Spill transferred to DEC Patel as per RSE.05/18/12-Hiralkumar Patel. completed review of available documents and found following:1) 10/12/2006: Robert Feller from Bond, Schoeneck & King, PLLC sent fax including a singed copy of Agreement for Discharge of Environmental Liens. RCC & York Associates, Inc. signed the agreement. RCC agreed on following terms:- payment of $ 25,000 upon execution of this agreement- upon completion of cleanup of environmental contamination to the satisfaction of NYS DEC, RCC or its assigns, heirs, or successors of interest, shall pay $ 100,000- upon receipt of the final payment, DEC shall issue a release of its said environmental liens against the said property2) 05/27/2009: DEC Ketani referred case to legal as no response to the STIP letter (dated 03/18/09).05/23/12-Hiralkumar Patel.2:40 PM:- received email from Bill including summary of work done by GeoQuest and disposal manifests for soil removed during removal of eastern tanks (400,000 gal and 200,000 gal). GeoQuest is planning to remove southern tanks (total five tanks). once the tank complex has been removed and extent of the sub-surface structure is known, a proposed plan of action for determining the extent of the subsurface contamination will be submitted. Bill will visit the site on 05/30/12. 05/24/12-Hiralkumar Patel.alternate address: 198-200 Morgan AveMOSF #: 2-1500. MOSF registration showing tanks still in-service. registration expired on 03/31/1991.other spill #: 8808176, 9105949, 9112693, 9208755 and 9211657spill # 8808176 was reported on 01/13/1989 as 100 gal #2 oil dumped into creek. case closed on 08/07/1995. no documents on e-docs.spill # 9105949 was reported on 09/03/1991 as #6 oil found in creek which might be coming from a 55 gal abandoned drum or from bulkhead. case closed 09/19/1991.spill # 9112693 was reported on 03/12/1992 as 50 gal #6 oil spilled. case closed on 03/13/1992.spill # 9208755 was reported on 10/29/1992 as 50 gal #6 oil sludge spilled during tank cleaning operation. spill cleaned up by Citi Fuel. case closed on 02/05/1998.spill # 9211657 was reported on 12/23/1992 by DEC Mitchell due to contamination found in wells as part of PIN job.05/25/12-Hiarlkumar Patel.12:43 PM:- spoke with DEC legal regarding case initiation and confirmed no legal action from region 2 office as owner was doing work.05/30/12-Hiralkumar Patel.1:30 PM:- visited site. met Bill. found tank removal operation at the site. crew already removed more than 70% of the tank #1 (which is closest

NYC DEP HAZ MAT (Continued) **S102143390**

to the Morgan Ave - 647,000 gal tank). found about 12 inches thick concrete pad under the tank metal. water found on the side of the tank pad and oil found on water. no petroleum odors noticed. Bill mentioned that tank removal operation begun probably at the beginning of the month. informed him that the department has not received any work plans or notification to MOSF regarding removal of the tanks. after discussing with DEC Austin, asked Bill to stop tank removal work immediately and informed him that work should only be resumed after getting approval from the Department. Bill spoke with property owner and requested a meeting in DEC office. informed Bill that meeting can be scheduled once required work plan/documents submitted to the Department.during visit, met with Jacques Guillet (914-309-4317), contractor who is removing tank metals. informed him about no more work without the department's approval.2:30 PM:- spoke with Ms. Karpen. she found the Agreement for Discharge of Environmental Liens (dated 10/12/2006) in her file. she will review available documents to see if any consent order or STIP signed for cleanup work. informed her about a meeting requested by RP. she mentioned that she needs to review the entire file and the work plan/documents, that will be submitted by RP, before any meeting with RP. she requested copy of work plan/documents, once submitted.05/31/12-Hiralkumar Patel. discussed with DEC Austin and DEC Vought. Austin required submission of following documents:- work plan for tanks removal including community air monitoring plan and health and safety plan- submission of MOSF application for tanks closure- copy of NYC DOB's work permit for tanks removal- documentation about notification to FDNY1:52 PM:- received email from Bill. he mentioned that the site owner has a prospective tenant who would rent part of the space (starting in two weeks), but currently, access to the area being rented is blocked by physical obstacles on the ground. Bill asked if they can move stockpiled soil to other part of the site and remove already cut-up steel off-site.discussed with DEC Austin. Austin approved to move soil and metal to other part of the site, but no off-site disposal without approval of the work plan.2:25 PM:- spoke with Bill and informed him that the department approves moving of stockpiled soil and cut-up steel to other part of the site, but does not approve off-site disposal of any material until all required documents submitted and approved. asked him to send property owner's contact info. asked Bill about well monitoring. Bill mentioned that wells were lastly checked in 2009 before scaffolding removed. after removing scaffolding, most of the wells are covered under dirt/metal and are not accessible. asked Bill about DOB work permit. he believes that permit is not needed for tank removal. asked him to check with NYC DOB regarding required work permit.06/01/12-Hiralkumar Patel.2:01 PM:- received email from Bill including property owner's contact info.English Kills Ventures LLCc/o Asher Zwebner, Trustee5014 16th Avenue, Suite 110Brooklyn, NY 112196:15 PM:- sent email to Bill and asked to provide owner's phone number and email address.06/05/12-Hiralkumar Patel.11:08 AM:- received email from Bill. he mentioned that property owner asked to send documents to their attorney.Robert H. Feller, Esq. **property owner's attorney**Bond, Schoeneck & King, PLLC.111 Washington AvenueAlbany, NY 12210-2211Ph. (518) 533-3222Fax (518) 533-3299email: rfeller@bsk.com1:44 PM:- received email from Bill. due to open tank excavation pit, he requested to backfill it using on-site stockpiled soil.2:33 PM:- forwarded Bill's email to DEC Austin for review.6/6/12-Vought-DEC Patel received email from GeoQuest (Bill

NYC DEP HAZ MAT (Continued) **S102143390**

Hughes Ph:860-243-1757 Cell:860-402-5292) that "When you closed down the site on Wednesday (5-30-12) you may not have realized that a dangerous condition resulted - an open pit. Granted, the work area is theoretically closed to any and all persons and/or vehicles, but we all know that stuff happens. In addition, the open pit is subject to flooding which could result in a multitude of unforeseeable problems including exacerbating the danger of this site condition.We propose the following solution: 1) Continue the removal of the steel bottom of the tank (at the very least) and store the steel on-site. The next level of action would be to also remove the steel back wall (south wall), remaining steel west wall (only about 30% still remains), and remove the remainder of the north wall (storing all removed steel on-site, of course). 2) Back-fill the open pit with the on-site soil as you and I discussed. The on-site soil is fill removed from the tank top and walls which exhibits no sign of any contamination. The backfilling of this area would eliminate a very dangerous situation. 3) Consider allowing the stored steel to be removed from the site. It could be used to pay for the rental equipment. Steel is steel- it is not a source of contamination. 4) Consider the power of inertia- the longer a project remains stalled, the harder it is to get it moving again. Regards." DEC Patel forwarded email to RSE with request for advisement and RSE forwarded mail to DEC Vought asking to look into matter. Vought called and spoke to Geoquest who noted that tanks bottoms were approximately 5-6'below grade on concrete and close to groundwater. Geoquest also noted that the concrete under the tanks was at groundwater level. Vought after concurring with DEC Farrar called back Geoquest and noted that backfilled soils must meet STARS Memo #1 parameters. Vought also called and spoke to NYCOEM McIntyre who noted that site is not in a NYC Program and as such there are to date no institutional or engineering controls for site but that if applicants are interested in alternate SCOs associated with a different program then they should call NYCOER Chawla. Vought spoke to DEC Patel who noted that when he was onsite last week he also noted to contractor that wells will need to be installed at the tank locations through the concrete. Vought to meet Hughes on site at 1pm today and required that: 1)samples be collected from the soil pile analyzied for Full List 8260/8270 (due to history of chlorinated solvents) 2)note that wells will be required in the future in the backfilled areas 3)Submission of analyticals to DEC for review prior to use as backfill. Vought received callback from Hughes who noted that site was zoned M-1(manufacturing). Vought performed site visit and received call from Hughes who noted that his car broke down in Brooklyn and he will not be able to make it to site but will arrange to have sampling company come to site and collect sam[ple. Vought repeated that sample must be collected for 8260/8270 Full List and compared to STARS Memo#1 values. Vought observed approximately 2O' high by 70' long pile of soil up against large MOSF tank but noted no petroleum odors or staining in pile. Vought also observed standing water in open tank pit and water was connected to soil as west wall of UST removed down to tank bottom. No sheen or product in water in tank pit. Bottom of tank pit composed of concrete pad and steel(of which is scheduled to be removed). Vought met English Kills (Arthur Schwartz Ph:732-309-2063) onsite and discussed tank removal and future use of site (which may be parking lot for buses) as well as need for installation of wells at tank location through concrete pad as per DEC Patel. Vought also observed approximately 6' width of soil between steel tank and outer support wall with no staining as well.

NYC DEP HAZ MAT (Continued) **S102143390**

Note soil pile covering many monitoring wells. Rush turnaround time will be requested for soil samples as well. Vought sent email update to Kumar.6/7/12-Vought-Received message from Hughes and returned call and left message to return call with confirmation of sample collection. Vought received callback from Hughes who was enroute to site to perform soil sampling of proposed soils for backfill (EPA 8260/8270 Full List) due to former presence of chlorinated solvents as well as petroleum in tank. Results to be compared to STARS Alternative Guidance values and examined for possible Haz Waste contaminants as well. Results should be received and Hughes will follow up with Vought on Friday.06/12/12-Hiralkumar Patel.11:58 AM:- received email from Bill including sample results. three samples were collected. some SVOCs found in samples. found maximum 460 ppb of Naphthalene in one sample. Bill requested approval to backfill the excavation.DEC Austin and DEC Vought inspected site. based on observations during the site inspection, Austin mentioned that the department does not approve backfilling of the tank excavation. he asked for a meeting in DEC office, with property owner.2:36 PM:- spoke with Bill and informed him about the discussion with DEC Austin. asked him to set up meeting with property owner.4:25 PM:- sent email to Bill. informed him that the department does not approve backfilling of the excavation. informed him that the department requests a meeting with property owner. asked him to provide timing for the meeting. email copied to DEC Vought, DEC Austin, Judy Karpen, Jay Soltis (jsoltis@geoquestinc.com) and Marc Casslar (mcasslar@geoquestinc.com).06/14/12-Hiralkumar Patel.11:51 AM:- received email from Bill. he mentioned that him, Marc Casslar (GeoQuest) and Robert Feller (owner's attorney) will meet at 10 AM on 06/20/12, in DEC office.spoke with DEC Austin. he requested presence of property owner. he mentioned that if owner brings his attorney, then DEC attorney will be present in the meeting and it will be an enforcment issue.2:32 PM:- spoke with Bill and informed him about discussion with DEC Austin. Bill asked to reply by email.06/18/12-Hiralkumar Patel. discussed with DEC Vouth, DEC Austin and Judith Karpen. Ms. Karpen is still reviewing legal documents. as the legal review is pending, Austin mentioned that the meeting on 06/20/12 will be to discuss technical issues only.3:31 PM:- sent email to Bill including meeting agenda. informed him that this meeting will be for technical discussion only. email copied to DEC Austin, DEC Vought, Judy Karpen, Jay Soltis and Marc Casslar.06/20/12-Hiralkumar Patel.10:00 AM:- discussed with DEC Austin, DEC Vought, Bill, Marc Casslar, Robert Feller and Ryan Karben during meeting in DEC office and agreed upon following:- notification to NYC DOB and FDNY (if applicable)- submission of MOSF application for tanks removal- monitoring of bulkhead during low tide for possible oil seepage into the creek and installation of boom, if product seepage noted- submission of tank removal plan, including health and safety plan and CAMP, by the end of 07/16/12- subsurface soil and groundwater investigation, at and around the tanks locationduring discussion, Bill mentioned that removal of remaining tanks would take another 6-8 months and subsurface investigation will be peformed after that. informed RP that the department requires delineation under the tank pads, via installation of wells through the pads. also, the department may require replacement of wells, if existing wells are destroyed or clogged. during discussion, Austin approved to use on-site stockpiled soil to backfill the tank excavation and RP agreed that depends on future site use, backfilled

NYC DEP HAZ MAT (Continued) **S102143390**

soil may be removed during future development. asked RP to submit MOSF application for tanks removal.Ryan Scott Karben, Esq. **owner's representative**Law Office of Ryan Scott Karben11 Tara DrivePomona, NY 10970Ph. (914) 536-4402email: ryan@ryankarben.com1:01 PM:- spoke with Judy. she mentioned that due to statue of limitation, she can not enforce for money spent more than 6 years ago. also, there is no dicussion about spill remeidation in the Agreement for Discharge of Environmental Liens signed by RCC & York Associates, Inc. in 2006. she also mentioned that bankruptcy court has found environmental liens be not valid.06/29/12-Hiralkumar Patel.3:50 PM:- spoke with Bill and informed him that a STIP agreement will be mailed today.4:06 PM:- sent STIP letter to Mr. Feller. informed him that the signed STIP and a tank removal plan (including schedule) must be submitted by the end of 07/27/12. letter emailed to Mr. Feller, DEC Austin, DEC Urda, Ms. Karpen, Bill, Mr. Casslar and Mr. Karben.07/05/12-Hiralkumar Patel.12:14 PM:- received email from Bill including MOSF notification, tank removal plan and health & safety plan (including CAMP).1:02 PM:- sent email to Bill. informed him that a signed stipulation must be submitted to the Department prior to review of any work plans. email copied to DEC Austin, DEC Urda, Ms. Karpen, Mr. Felller, Mr. Casslar and Mr. Karben.07/12/12-Hiralkumar Patel. received email from Mr. Casslar (at 6:11 PM on 07/11/12) including revised STIP and CAP. Mr. Casslar noted following nine reasons for changes in STIP and CAP:- the "spill" occurred in 1992, more than 20 years ago- the oil terminal has been closed for almost 20 years- all of the tanks were emptied, cleaned, and inspected more than 18 years ago- active remediation of groundwater was conducted for about 8 years- NYSDEC concluded almost 8 years ago that no further benefit could be achieved from active groundwater remediation- all of the work was conducted under the supervision of the NYSDEC- no new spills have occurred since the facility was closed- the site has been used and occupied at various times in the last 20 years and there is no indication that a risk to human health or safety exists; and- throughout time the importance of removing the tanks has been continuously discussed07/18/12-Hiralkumar Patel. discussed with DEC Austin, DEC Vought, DEC Urda and Ms. Karpen. Ms. Karpen will discuss with Patrick Hallaway in AG's office to discuss about third party claim to the spill fund by the property owner. discussed submitted revised CAP and changed as needed. Urda will revised the CAP after gets update from Ms. Karpen.07/31/12-Hiralkumar Patel. visited site. found water in tank excavation area. some sheen observed on water.3:23 PM:- received email from Ms. Karpen inquiring if English Kills had a Phase I done prior to purchasing the property.08/01/12-Hiralkumar Patel.4:43 PM:- sent email to Ms. Karpen. informed her that the department does not have any Phase I report in file and doesn't know if English Kills ever conducted Phase I investigation.08/03/12-Hiralkumar Patel. received call from DEC Urda. he will arrange a conference call with AG's office and spill fund.08/07/12-Hiralkumar Patel. yesterday (08/06/12), DEC Austin, DEC Vought, DEC Urda, DEC Ben Conlon, Ms. Karpen (AG's office), Bonnie Riggi (AG's office), Luzette Baker (spill fund) and Patrick Halloway (spill fund) discussed the case and decided to send a consent order.spoke with DEC Urda. he has asked DEC Leszek to review available MOSF documents and waiting for his response before drafting response to the revised STIP sent by RP.3:48 PM:- spoke with DEC Ian Beilby who inquired about spill # 1202045, which was reported by BCP contractor as they noticed some sheen in water near the site.

NYC DEP HAZ MAT (Continued) **S102143390**

informed Ian that no sheen observed during the site visit on 05/31/12 and based on site observation, case 1202045 is closed. during conversation, Ian mentioned that they have meeting with EPA on 08/09/12 regarding Newtown Creek cleanup project and will discuss about possible impact to the creek from the Morgan Terminal. asked Ian to update after meeting.08/13/12-Hiralkumar Patel.3:33 PM:- received call from DEC Beilby. he mentioned that EPA and respondent's consultant (Anchor QEA) are considering sending a letter (104E request) to English Kills Ventures LLC requiring to submit all investigation/compliance documents for review.08/14/12-Hiralkumar Patel.2:47 PM:- received email from DEC Beilby. he will send CD of available documents to AnchorQEA.08/14/12-Ian BeilbyCD with edoc files sent to AnchorQEA for review and possible 104e request.08/16/12-Hiralkumar Patel.12:38 PM:- received email from DEC Michele Albert including copy of cover letter that was sent to Anchor QEA (with document CD).09/06/12-Hiralkumar Patel. reviewed tank removal plan, submitted previously on 07/05/12.abstract of tank removal plan:- fill material removed from the top and sides of the tank will be assigned to one of two piles- if soil appears normal with no dark stains or odor it will be placed onto a "clean" pile- if soil has dark stains or odor or if it registers on a PID meter it will be placed onto a "dirty" pile and be stored on and under plastic for sampling, laboratory analysis and eventually off-site disposal- when half of the bottom plate has been removed, the excavation resulting from the tank removal will be partially backfilled to allow the excavator to move into the tnak area to reach the remainder of the bottom plate and the tank back wall- upon completion of the removal of each tank section, the excavation for that tank section will be backfilled and compacted to grade- use of previously excavated "clean" fill from the on-site "clean" pile is done with the understanding that in the future, this fill may have to be sampled and/or remediatedthe tank removal plan does not discuss about endpoint sampling. 10/23/12-Hiralkumar Patel. received email from DEC Urda (at 10:39 AM on 10/17/12) including copy of email from Mr. Feller. Mr. Feller sent signed copy of the consent order. as per the Corrective Action Plan of the Consent Order, the Department must be notified two days prior to backfilling of any part of the excavation and the Department may require collection of endpoint soil and groundwater samples.waiting for copy of fully executed Consent Order.11/13/12-Hiralkumar Patel.11:46 AM:- received email from DEC Urda including fully-executed order.11/29/12-Hiralkumar Patel.4:07 PM:- spoke with Bill. they started work about 2-3 days ago.12/05/12-Hiralkumar Patel.2:55 PM:- visited site. crew was working in tank pit, cutting angle brackets to the south wall of tank. no structural supports were observed to the south wall. also noted that the tank pit was partially backfilled, without prior notification to the department as required in signed consent order.3:25 PM:- left message for Bill and asked him to ensure worker's safety.3:50 PM:- sent email to Bill regarding operation at the site. asked him to ensure safe operation. email copied to DEC Urda and Mr. Feller.12/06/12-Hiralkumar Patel.11:08 AM:- received email from Bill. he has spoke with Jacques and was informed that there is still a piece of the bottom plate attached to teh south wall as well as the eastern end wall and the angle brackets are for tank stiffness, and are not for structural integrity.2:16 PM:- spoke with Bill regarding partial backfilling of excavation without prior notice to the department. he mentioned that the excavation was partially

NYC DEP HAZ MAT (Continued) **S102143390**

backfilled so a backhoe can be used for further work. he mentioned that soil in tank excavation pit will be tested as part of investigation after tank removal and removed, if found contaminated.12/10/12-Hiralkumar Patel. received email from Bill (at 4:18 PM on 12/09/12). he mentioned that when remedial investigation work plan is submitted, the soil in the area occupied by the tanks will be addresses along with the soils on the remainder of the property.01/22/13-Hiralkumar Patel.9:00 AM:- visited site. first section of the tank is removed completely and area has been backfilled to grade. no crew was on-site.03/20/13-Hiralkumar Patel.10:45 AM:- visited site. crew was removing the tank. the site is divided in two sections: section towards Morgan Ave is occupied by buses and section towards the water is occupied by construction equipments.05/04/13-Hiralkumar Patel. another spill reported at the site (spill #: 1301162) by FDNY as fire occurred in tank pit during tank removal.1:30 PM:- visited site. FDNY had left. met with Jacques Guillet, site supervisor. he mentioned that due to very hot weather, some of the left over oil got vaporized and flash fire occurred. FDNY extinguished the fire and stopped work until they get fitness certificate. FDNY issued violation order (# A181083). Mr. Guillet mentioned that work will resume only after necessary documents submitted to FDNY.inspected tank pit. only eastern section of last tank left. found burned steel in tank pit. no odors noted. as per Mr. Guillet, no one was injured.05/06/13-Hiralkumar Patel.9:17 AM:- DEC Urda forwarded email from Mr. Feller (dated 05/02/13). Mr. Feller mentioned that tank removal report will be submitted by 05/31/13, as approved by DEC.05/24/13-Hiralkumar Patel.11:03 AM:- received call from Bill. he inquired about document from previous contractors regarding cleaning of tanks.11:10 AM:- sent email to Bill including copy of report from Winston Contracting dated 02/25/1995.05/31/13-Hiralkumar Patel.10:42 AM:- received email from Bill including tank removal report. abstract:- two tanks (# 6 and 7) in eastern tank complex- five tanks (# 1 through 5) in southern tank complex- tanks were fabricated on the site from individual steel plates with welded seams- tank structures were supported with internal steel angle brackets welded into a rigid pattern- soil was placed on the exterior of the tanks to create "bunders", and appeared to consist of the same fill-type materials underlying the property- both the eastern (with two tanks # 6 and 7) and southern (with five tanks # 1 through 5) tank complexes were constructed approx. 4 ft bg- on-site soil, including bunkering material, was utilized to backfill the excavations- during the remvoal of the tank bottom plates, small quantities of free product were occasionally observed on groundwater- when encountered, the oil was collected using oil absorbent material- total of 835.84 tons of soil, from removal of eastern tanks, transported in Mar. 2012- total of 1,696.63 tons of soil, from removal of southern tanks, transported in Aug. 20122:18 PM:- tank removal report forwarded to Ms. Karpen.2:22 PM:- sent email to Bill and asked to submit remedial investigation work plan and tank registration forms as per item # 5 and 6 of the correction action plan of the signed consent order. email copied to DEC Urda, Ms. Karpen, Mr. Casslar, Mr. Feller and Mr. Karben.05/31/13-Hiralkumar Patel.2:57 PM:- received email from Bill. he inquired if tank removal report is accepted. he mentioned that investigation work plan will be submitted within 30 days of acceptance of the tank removal report. he also mentioned that required tank registration forms will be submitted upon approval of the remedial investigation work

NYC DEP HAZ MAT (Continued) **S102143390**

plan.06/04/13-Hiralkumar Patel. discussed with DEC Leszek regarding submission of MOSF/PBS forms. he mentioned that required tank registration forms should be submitted now to correct the tank status.06/05/13-Hiralkumar Patel.3:02 PM:- sent email to Bill. informed him that the tank removal report is accepted. informed him that as per the signed consent order, a remedial investigation work plan is due within 30 days of submission of the tank removal report. asked him to submit the work plan on or before June 30, 2013. also asked him to submit required tank registration forms now instead of waiting for work plan approval. email copied to DEC Urda, Ms. Karpen, Mr. Casslar, Mr. Feller and Mr. Karben.06/20/13-Hiralkumar Patel.11:41 AM:- received email from Bill including PBS/MOSF applications.06/25/13-Hiralkumar Patel. discussed with DEC Leszek about PBS/MOSF forms. he mentioned that hard copy must be submitted with original signature.12:56 PM:- sent email to Bill and asked him to submit hard copy of required PBS/MOSF forms with original signature.06/28/13-Hiralkumar Patel. received signed hard copy of PBS/MOSF forms. gave forms to DEC Leszek for review and processing.07/01/13-Hiralkumar Patel. received email from Marc Casslar from GeoQuest including Remedial Investigation Work Plan. abstract:- total of 12 soil borings wil be advanced "to the base concrete slab" of the former southern tank complex- for the eastern tank complex, a total of 8 soil borings will be advanced "to the base concrete slab"- 2 of the borings in each complex will be advanced through the slab to a total depth of 12 ft bg- soil with the highest PID readings or the most visual or olfactory contamination will be collected for lab analysis- soil samples will be analyzed for DRO, VOCs by 8260B and PAHs by 8270- five (5) additional borings will be developed as 1 inch monitoring wells, with 5 ft of screen and sufficient riser, in the vicinity of the former tanks- work can commence within 90 to 120 days after the acceptance of this work plan- report should be completed within 180 days after commencement workthe proposed work plan is not acceptable for following reasons:- it proposes to begin work within 90 to 120 days after the acceptance of the work plan. the department requires that investigation work must begin within 45 days of work plan approval- it propose to submit report within 180 days after commencement of work. the department requires that Remedial Investigation Report must be submitted within 120 days of work plan- a "scaled" site map must be submitted including all previous boring/well locations and location of proposed borings/wells- it proposes installation of 1 inch well with 5 ft screen. work plan does not specify minimum depth of proposed wells. the proposed wells must be at least 2 inch in diameter and must be installed to minimum depth of 12 ft bg with 10 ft of screen- all existing monitoring wells must be gauged and sampled10:26 AM:- spoke with Marc at GeoQuest. asked him to submit revised work plan with following changes:- investigation work must begin within 45 days of department’s approval (instead of within 90 to 120 days)- Remedial Investigation Report must be submitted within 120 days of department’s approval (instead of 180 days after commencement of work)- revised scaled site map including all previous boring/well locations, alongwith location of proposed borings/wells- wells must be at least 2 inch in diameter and must be installed to minimum depth of 12 ft bg with 10 ft of screen- gauging/sampling of all existing monitoring wellsMarc mentioned that site access may be issue for field work. informed him that the site is being used as parking lot, occupied by buses which can be moved for field work. Marc mentioned

NYC DEP HAZ MAT (Continued) **S102143390**

that Bill is out of office till next week and will submit revised work plan upon his arrival.3:40 PM:- received message from Sam Levin, attorney for property owner.Sam LevinPh. (347) 564-359707/02/13-Hiralkumar Patel.1:16 PM:- spoke with Mr. Levin. he inquired about insurance carrier of previous property owners. informed him that no such information seen in file. suggested him to review available files. he will talk to Bill.07/19/13-Hiralkumar Patel.4:12 PM:- received email from Bill including work plan, with changes in work schedule only. but no changes about well diameter or depth.08/02/13-Hiralkumar Patel. Bill proposed to install total 20 soil borings to the base concrete slab in former two tank fields, but soil above concrete bases are basically on-site backfill soil which was removed from around the tanks during tank removal. as such there is no need to sample this soil again. instead deeper and larger diameter monitoring wells are needed at the source area.1:26 PM:- spoke with Bill. informed him that the department requires minimum 4-inch wells at former tank locations, to a minimum depth of 12 ft bg with 10 ft of screen. asked him to submit revised work plan. Bill asked to send email with comments on work plan.08/06/13-Hiralkumar Patel. discussed with DEC Vought. as stated in signed consent order, complete delineation (on- and off-site) is required. 11:12 AM:- spoke with Bill. informed him that the department requires complete delineation of contamination, which includes impact to off-site also. asked him to submit revised work plan including off-site delineation. strongly suggested him to locate previous monitoring wells and sample existing wells prior to finalizing the work plan. Bill asked for written note about the requirements.1:52 PM:- sent email to Bill. informed him that as per the signed consent order, the department requires complete delineation of contamination. asked him to submit a revised RIWP, by the end of 09/13/13, including on- and off-site delineation. suggested him to locate and sample existing wells prior to finalizing the RIWP. email copied to DEC Urda, Mr. Feller, Jay Soltis (jsoltis@geoquestinc.com) and ekvllc@gmail.com.08/20/13-Hiralkumar Patel.4:35 PM:- received message from Bill.08/21/13-Hiralkumar Patel.12:42 PM:- left message for Bill.08/22/13-Hiralkumar Patel.11:29 AM:- received message from Bill.08/26/13-Hiralkumar Patel.12:52 PM:- spoke with Bill. he inquired about reason for 4 inch well. informed him that 4 inch wells are preferred in case product recovery or other remediation needed. he mentioned that as there was not much oil found on concrete pad during tanks removal, property owner wants to install 2 inch well. informed him that its ok to install 2 inch well now, but the department may require to install larger diameter well based on investigation results. he agreed to it. Bill will submit work plan by first week of Sept. 2013.09/13/13-Hiralkumar Patel.2:05 PM:- received email from DEC Beilby. he mentioned that EPA will visit site on 09/18/13 to determine whether there are any likely on-site point source discharges to Newtown Creek.10/03/13-Hiralkumar Patel.12:19 PM:- received email from DEC Beilby. Anchor QEA indicated that the morgan oil terminal would not likely be targeted for sampling because of a lack of discharge.10/29/13-Hiralkumar Patel. received email from Bill (at 2:02 PM on 10/28/13) including a revised work plan. Bill proposes to install total of twenty (20) soil borings to the base concrete slab of the former tank complexes. two borings will be advanced to 12 ft bg. three (3) 2-inch wells will be installed to 15 ft depth, with 10 ft of screen. Bill also proposes to sample seven (7) existing wells.the submitted work plan does not include

NYC DEP HAZ MAT (Continued) **S102143390**

information about number of wells available at the site and it only proposes to investigate soils and groundwater in the footprint and vicinity of the former tank complexes.11/14/13-Hiralkumar Patel.2:55 PM:- spoke with Bill. discussed about existing wells and complete delineation. Bill mentioned that they found total 12 wells. out of 12 wells, product found in 5 of the existing wells. asked Bill to submit a revised work plan including site map with location of all existing wells and information about product in existing wells. informed him that further delineation may be requuired, based on investigation results.3:17 PM:- sent email to Bill and asked to submit a revised work plan.11/26/13-Hiralkumar Patel. received email from Bill (at 4:14 PM on 11/20/13) including work plan with revised site map including location of wells where free product found.12/20/13-Hiralkumar Patel.11:30 AM:- sent letter to property owner approving work plan, pending inclusion of immediate gauging of wells to determine product thickness, installation of absorbent socks in impacted wells and weekly monitoring/removal of product from wells. asked owner to submit monthly records of well gauging/product removal activities and investigation report by the end of 06/30/2014. letter emailed to Bill, DEC Urda and Mr. Feller.01/08/14-Hiralkumar Patel. DEC Peter Malaty (Fish, Wildlife and Marine Resources) visited site earlier today to inspect bulkhead at the site. during inspection, he noted spill of unknown amount of motor fuel onto the soil, from one of the parked bus at the site. he sent pictures taken during the site visit.11:28 AM:- left message for Bill and informed him about unreported spill, from a bus, at the site. asked him to call back with bus company's information. informed him that the department requires reporting of this spill incident and cleanup of spilled material.11:36 AM:- sent email to Bill including pictures received from DEC Peter. informed Bill that the department requires reporting of this spill incident and immediate cleanup. also asked him to provide bus company's information.01/10/14-Hiralkumar Patel.12:28 PM:- received call from Bill. discussed about unreported spill under the parked bus. he will ask bus owner/operator to report the spill. Bill mentioned that spill was cleaned up.spoke with Bill about installation of absorbent socks in well and removing product. he mentioned that no work has been done yet and they believe that installing absorbent socks in wells would not do any benefit. asked Bill to submit written reply to the requirement of well gauging/product removal as listed in letter dated 12/20/13.03/10/14-Hiralkumar Patel.10:43 AM:- received email from Bill including addendum to remedial investigation work plan dated 10/18/13. Bill proposed to install "an appropriate absorbent sock", as soon as practical, into each of the contaminated wells and weekly checking and repalcement of these socks. specific work schedule is missing in the addendum.04/23/14-Hiralkumar Patel.1:33 PM:- left message for Bill.06/02/14-Hiralkumar Patel.4:48 PM:- received email from Bill including a letter including summary of interim remedial measures. on 05/14/14, GeoQuest gauged wells previously reported to contain LNAPL (MW-14, MW-15, MW-28A, MW-34 and MW-40) and installed absorbent socks. they visited site again on 05/21/14 and replaced the absorbent socks. found product in all five wells during both visits.product thickness (in ft):---------05/14/14-----05/21/14MW-14------0.90---------0.72MW-15-----0.001--------0.001MW-28A----0.001--------0.001MW-34------6.20---------0.01MW-40------1.50---------0.45absorbent sock weight difference (in oz) on 05/21/14:---------weight

NYC DEP HAZ MAT (Continued) **S102143390**

diff.MW-14------25.8MW-15-------3.0MW-28A------1.1MW-34------11.
0MW-40------47.706/23/14-Hiralkumar Patel.3:44 PM:- received email
from Bill including a letter including summary of interim remedial
measures. on 06/11/14, GeoQuest gauged wells with the installed
absorbent socks. a previously obstructed well (MW-12) has been
available and installed absorbent sock in it.previously reported to
contain LNAPL (MW-14, MW-15, MW-28A, MW-34 and MW-40) and installed
absorbent socks. they visited site again on 05/21/14 and replaced the
absorbent socks. found product in all five wells during both
visits.product thickness (in
ft):---------06/11/14MW-12------0.001MW-14------0.001MW-15------0.
001MW-34------0.001MW-40------0.001absorbent sock weight difference
(in oz) on 06/11/14:---------weight
diff.MW-14------35.6MW-15-------5.1MW-28A------2.0MW-34-------4.
2MW-40------42.510/28/14-Hiralkumar Patel.11:24 AM:- received email
from Bill including remedial investigation report. abstract:- on
06/09/14, installed 20 soil borings in the area under and around the
former bulk storage tanks- twelve (12) soil borings (B-1 through
B-12) were advanced to a depth of 5 ft within the footprint of the
former southern tank complex, six (6) soil borings (E-1 through E-6)
were advanced to a depth of five ft within the footprint of the
former eastern tank complex, and two borings (B-13 and B-14) were
advanced to a depth of 15 ft bg along the north side of the souther
tank complex- ten soil samples were submitted for lab analysis- on
06/10/14, three (3) 2-inch monitoring wells, with ten (10) ft of
screen, were installed to a depth of fifteen (15) ft bg- total of ten
monitoring wells were sampled for analysis: seven existing wells
(FN-19, FN-20, FN-22, FN-28A, FN-31, FN-35 and FN-39) and three new
wells (GQ-41, GQ-42 and GQ-43)- boring logs shows the predominant
material encountered in the footprint of each tank complex was:
brown, dark brown or black sand with silt or sand, silt, and clay,
with a variety of crushed materials: asphalt, brick, pieces of
concrete, stone, coal, plus ceraimc, glass, metal, wood and paper-
groundwater was encountered at 3.5 ft bg in boring B-13 and B-14-
very minor VOCs detection noted in few samples- SVOCs were detected
in all soil samples (backfill material found in soil borings)- using
absorbent socks in wells with product, a total of 1.5 gal of product
has been removed to-date- there are at least two USTs still on-site
including a 3,000 to 5,000 gal UST in a vault in the northwest corner
of the site and a 1,000 gal heating oil tank on the south side of the
terminal buiding- recommends removal of remaining tanks and
continuation of interim-remedial measures (product recovery using
absorbent socks in wells with product)the report is missing site map
with location of existing tanks and well FN-28A.11/04/14-Hiralkumar
Patel.8:57 AM:- sent email to Bill. asked him to submit site map with
location of existing tanks and well FN-28A. also asked him to submit
records of interim remedial measures as per the department's letter
dated 12/20/13 (copy attached in email). email copied to Aaron
Abraham (aarbenabe@yahoo.com), Marc Casslar
(mcasslar@geoquestinc.com), Jay Soltis (jsoltis@geoquestinc.com) and
lepmanagement89@gmail.com.11/06/14-Hiralkumar Patel.2:14 PM:-
received email from Bill including site map with location of existing
tanks and well FN-28A. Bill mentioned that location of FN-28/FN-28A
is uncertain. according to well location maps available to GeoQuest,
there should be two wells close together off of the eastern end of
the office buildiing, labeled FN-28 and FN-28A, but when GeoQuest did
the well usability survey in September 2013 they could only locate

NYC DEP HAZ MAT (Continued) **S102143390**

one well. Bill will refer this well from now on as FN-28A.11/10/14-Hrialkumar Patel.9:15 AM:- received email from Bill including well monitoring data table, which was previously submitted in June.10:22 AM:- sent email to Bill and asked him to submit interim remedial measure record from June to Nov. email copied to lepmanagement89@gmail.com, Mr. Abraham, Mr. Casslar, Mr. Soltis.12/24/14-Hiralkumar Patel.12:08 PM:- received email from Bill: "My apologies, there have been no sock exchanges since our last report. We initiated the Interim Remedial Measures (IRM) and made our first report, but, while the initial levels were high, the levels dropped quickly to near zero floating product and we wanted to wait a bit to see if the levels would rebound and by how much.We just completed another round and it appears that the levels, for the most part, have remained low except for one well- FN-40, which still shows some floating product. We were unable to access FN-34 for this round of sampling." absorbent sock weight difference (in oz) on 11/11/14:---------weight diff.MW-12-------7.5MW-14------38.5MW-15------29.0MW-28A------8.8MW-40------54.801/21/15-Hiralkumar Patel.8:57 AM:- left message for Bill inquiring update about recommended tank removal.01/28/15-Hiralkumar Patel.3:03 PM:- received call from Bill. asked him about status on recommended tank removal. he mentioned that they are waiting for approval from DEC on investigation report. he also mentioned that owner is planning to use the site as it is and there is no redevelopment plan at this time.**weekly gauging and product removal from impacted wells and monthly submission of gauging recods.****MOSF documents on e-docs are only part of larger file in box located in basement storage.**

Remarks: CLEANUP BY DEC WINSTON CONTRACTING INC. SUPERVISED BY SIGONA (DEC)

Material:

Site ID:	59302
Operable Unit ID:	972795
Operable Unit:	01
Material ID:	406198
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

MOSF:

Facility ID:	2-1500
Program Type:	MOSF
Tank Status:	Inactive
Expiration Date:	03/31/1991
Dec Region:	2

NYC DEP HAZ MAT (Continued) **S102143390**

UTMX: 590073.27268000
UTMY: 4507217.0631400

BC198 **BAYSIDE FUEL OIL DEPOT CORP.** **NY Spills** **S102150611**
East **1100 GRAND STREET** **NY SPDES** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY MOSF**
0.465 mi.
2457 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
13 ft.

SPILLS:

Facility ID:	9505983
Facility Type:	ER
DER Facility ID:	119283
Site ID:	280171
DEC Region:	2
Spill Date:	8/15/1995
Spill Number/Closed Date:	9505983 / 3/25/2009
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	8/15/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/11/1995
Spill Record Last Update:	3/25/2009
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	03/25/09 - LZAccording to Anna-Marie Franzese of Bayside Fuel Oil Depot, who inquired a facility's employee, during removal of an UST, contaminated soil of unknown quantity was disposed of.The spill case is closed. Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BREEN"
Remarks:	TANK REMOVAL - FOUND SOME CONTAMINATED SOIL - ESTIMATING SOME AMOUNT - GEORGE BREEN FROM DEC ON SITE

Material:

Site ID:	280171
Operable Unit ID:	1020784
Operable Unit:	01
Material ID:	363971
Material Code:	0002A
Material Name:	#4 Fuel Oil

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102150611**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	10
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9104487
Facility Type:	ER
DER Facility ID:	119283
Site ID:	139621
DEC Region:	2
Spill Date:	7/26/1991
Spill Number/Closed Date:	9104487 / 3/25/2009
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	7/26/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/29/1991
Spill Record Last Update:	3/25/2009
Spiller Name:	Not reported
Spiller Company:	CIBRO
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	03/25/09 - LZFree product of unknown quantity has been extracted from the well. Presently, no monitoring well at the facility indicates the presence of free product (based on weekly and monthly reports on gauging of monitoring wells).The spill case is closed. . Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BREEN"11/18/94: REASSIGNED FROM SIGONA TO BREEN ON 11/18/94.10/10/95: This is additional information about material spilled from the translation of the old spill file: WEATHERED #2F.0.
Remarks:	DISCOVERED IN 4" SITE WELL #2

Material:

Site ID:	139621
Operable Unit ID:	955257

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102150611**

Operable Unit:	01
Material ID:	423551
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9007551
Facility Type:	ER
DER Facility ID:	119283
Site ID:	139620
DEC Region:	2
Spill Date:	10/10/1990
Spill Number/Closed Date:	9007551 / 3/25/2009
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	10/10/1990
CID:	Not reported
Water Affected:	KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/10/1990
Spill Record Last Update:	3/25/2009
Spiller Name:	Not reported
Spiller Company:	CIBRO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	03/25/09 - LZThe spill has been contained by employing booms and cleaned up. The spill case is closed. Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BREEN"DEC SIGONA REASSIGNED TO GEORGE BREEN ON 1/23/98
Remarks:	TANK OVERFILL, BARGE UNLOADING INTO 200K TANK, HUMAN ERROR CAUSED OVERFILL, AAA IS ON SITE TO CLEAN UP BOOMS HAVE BEEN DEPLOYED, USCG HAS BEEN NOTIFIED, NYCDEP & NYCFD ALSO NOTIFIED.

Material:

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102150611**

Site ID:	139620
Operable Unit ID:	948205
Operable Unit:	01
Material ID:	431403
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5000
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPDES:

Permit Number:	NY0007641
State-Region:	02
Expiration Date:	12/31/2015
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5171
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	DMR
Lat/Long:	40.7125 / -73.929167
DMR Cognizant Official:	ANNA MARIE FRANZESE, TER MGR
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Street Address:	BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Supplemental Location:	1776 SHORE PARKWAY, BOX 140128
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	112140002
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Street Address:	BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Supplemental Location:	1100 GRAND STREET
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11231
State Water Body:	02030201010
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102150611**

Non-Gov Permit Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Street Address: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Supplemental Location: 1776 SHORE PARKWAY, BOX 140128
Non-Gov Permit City: BROOKLYN
Non-Gov Permit State Code: NY
Non-Gov Permit Zip Code: 112140002
Non-Gov Facility Affiliation Type Desc: Owner
Non-Gov Facility Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Street Address: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Supplemental Location: 1776 SHORE PARKWAY
Non-Gov Facility City: BROOKLYN
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11214
State Water Body: 02030201010

UDF2: 001702
UDF3: SD
FIPS County Code: NY047

Non-Gov Permit Affiliation Type Desc: Permittee
Non-Gov Permit Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Street Address: 1776 SHORE PKWY
Non-Gov Permit Supplemental Location: Not reported
Non-Gov Permit City: BROOKLYN
Non-Gov Permit State Code: NY
Non-Gov Permit Zip Code: 11231
Non-Gov Facility Affiliation Type Desc: Mailing Address
Non-Gov Facility Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Street Address: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Supplemental Location: 1100 GRAND STREET
Non-Gov Facility City: BROOKLYN
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11231
State Water Body: 02030201010

UDF2: 001702
UDF3: SD
FIPS County Code: NY047

Non-Gov Permit Affiliation Type Desc: Permittee
Non-Gov Permit Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Permit Street Address: 1776 SHORE PKWY
Non-Gov Permit Supplemental Location: Not reported
Non-Gov Permit City: BROOKLYN
Non-Gov Permit State Code: NY
Non-Gov Permit Zip Code: 11231
Non-Gov Facility Affiliation Type Desc: Owner
Non-Gov Facility Org Formal Name: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Street Address: BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Supplemental Location: 1776 SHORE PARKWAY
Non-Gov Facility City: BROOKLYN
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11214
State Water Body: 02030201010

MOSF:
Facility ID: 2-1280
Program Type: MOSF

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102150611**

Tank Status: Active
Expiration Date: 03/31/2016
Dec Region: 2
UTMX: 590199.08129
UTMY: 4507510.1048100

BC199 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF UST** **S102633581**
East **1100 GRAND STREET** **NY MOSF AST** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.465 mi.
2457 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
13 ft.

MOSF UST:
Id/Status: 2-1280 / ACTIVE FACILITY
SWIS Code: 61
Facility Town: NEW YORK CITY
Contact Phone: (718) 387-6641
Emergency Contact: VINCENT ALLEGRETTI
Emergency Telephone: (718) 372-9800
CBS Number: Not reported
SPDES Num: 0-007641
Total Tanks: 8
Total Capacity: 1651241
Avg Throughput: 130000
License Stat: 1
Facility Type: STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options: AC
Expiration Date: 03/31/2002
Applic Rcvd: 01/05/2001
Operator: VINCENT ALLEGRETTI
Owner Name: BAYSIDE FUEL OIL DEPOT CORP.
Owner Address: 1776 SHORE PARKWAY
Owner City,St,Zip: BROOKLYN, NY 11214-
Owner Telephone: (718) 372-9800
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: Second Owner
Mail To Name: BAYSIDE FUEL OIL DEPOT CORP.
Mail To Address: 1776 SHORE PARKWAY
Mail To Address 2: PO BOX 140128
Mail City,St,Zip: BROOKLYN, NY 11214-0002
Mail To Contact: VINCENT ALLEGRETTI
Mail To Telephone: (718) 372-9800
Legal Agent Name: ALFRED ALLEGRETTI
Legal Agent Address: 1776 SHORE PARKWAY
Legal Agent City,St,Zip: BROOKLYN, NY 11214-
Date Filed: 03/65
Latitude: 14|42|45
Longitude: 73|55|45

Tank ID: 001
Tank Location: UNDERGROUND
Install Date: 12/37
Capacity (Gal): 99960
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	002
Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	249984
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	003

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	149982
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	004
Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	249984
Product:	DIESEL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	005
Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	249984
Product:	DIESEL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00A
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00B
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00C
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00D
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	OBF1
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	2000
Product:	EMPTY

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	OPS
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	7200
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

MOSF AST:

MOSF Number:	2-1280
SWIS Code:	61
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 387-6641
Emergency Contact Name:	VINCENT ALLEGRETTI
Emergency Contact Phone:	(718) 372-9800
Total Tanks:	8
Total Capacity:	1651241
Daily Throughput:	130000
License Status:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Product Transfer Operation:	AC
Facility Status:	IN SERVICE
Operator Name:	VINCENT ALLEGRETTI
Owner Name:	BAYSIDE FUEL OIL DEPOT CORP.
Owner Address:	1776 SHORE PARKWAY
Owner City,St,Zip:	BROOKLYN, NY 11214-
Owner Phone:	(718) 372-9800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	Second Owner
Mailing Name:	BAYSIDE FUEL OIL DEPOT CORP.
Mailing Address:	1776 SHORE PARKWAY
Mailing Address 2:	PO BOX 140128
Mailing City,St,Zip:	BROOKLYN, NY 11214-0002
Mailing Contact:	VINCENT ALLEGRETTI
Mailing Phone:	(718) 372-9800
Legal Agent Name:	ALFRED ALLEGRETTI
Legal Agent Address:	1776 SHORE PARKWAY
Legal Agent City,St,Zip:	BROOKLYN, NY 11214-
LIC Expires:	03/31/2002

Tank ID:	000
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date:	12/88
Product:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	None
Leak Detection:	Concrete Pad w/channels
Overfill Protection:	None
Dispensing Mthd:	Gravity
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Complete
Capacity (gal):	5000
Lat/Long:	14|42|45 / 73|55|45
Federal ID:	Not reported
Inspected Date:	07/13/1999
Inspector:	GN
Renew Date:	10/31/2001

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Inspected State: Not reported
Pipe Flag: False
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-007641
Date Legal Agent Filed with Secretary of State: 03/65

Tank ID: OBF
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 08/92
Product: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: 81
Leak Detection: 53
Overfill Protection: 64
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: 08/92
Status of Data: Complete
Capacity (gal): 1080
Lat/Long: 14|42|45 / 73|55|45
Federal ID: Not reported
Inspected Date: 07/13/1999
Inspector: GN
Renew Date: 10/31/2001
Inspected State: Not reported
Pipe Flag: False
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-007641
Date Legal Agent Filed with Secretary of State: 03/65

Tank ID: OBF-2
Tank Location: ABOVEGROUND
Install Date: 11/99
Product: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Impervious Underlayment
Leak Detection:	None
Overfill Protection:	Vent Whistle
Dispensing Mthd:	Gravity
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	14|42|45 / 73|55|45
Federal ID:	Not reported
Inspected Date:	07/13/1999
Inspector:	GN
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	False
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-007641
Date Legal Agent Filed with Secretary of State:	03/65

Tank ID:	006
Tank Location:	ABOVEGROUND
Install Date:	12/72
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	FIBERGLASS REINFORCED PLASTIC
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	75
Leak Detection:	53
Overfill Protection:	42
Dispensing Mthd:	Suction
Test Date:	06/01
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	649992
Lat/Long:	14|42|45 / 73|55|45
Federal ID:	Not reported
Inspected Date:	07/13/1999
Inspector:	GN
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	False
Vessel ID:	Not reported

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-007641
Date Legal Agent Filed with Secretary of State:	03/65

---

200 NW 1/4-1/2 0.480 mi. 2533 ft.

Relative: Lower

Actual: 18 ft.

UNITED AMBULETTE **NY LTANKS** **S106737607**
495 GRAHAM AVE **N/A**
BROOKLYN, NY

LTANKS:

Site ID:	335249
Spill Number/Closed Date:	0410348 / 5/3/2005
Spill Date:	12/17/2004
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	12/17/2004
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	12/17/2004
Spill Record Last Update:	5/3/2005
Spiller Name:	BOB
Spiller Company:	BUSINESS
Spiller Address:	495 GRAHAM AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	BOB
Spiller Phone:	(718) 234-0024
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	270469
DEC Memo:	12/22/2004 - Sangesland - 4,000 gal gasoline tank - PBS # 2-0691401/14/2005 TTF letter sent to:United Ambulette 2428 East 18th St, Brooklyn, NY 112222/22/05 Reassigned from Rommel to Foley. Spoke to Bob Arcaro, American. He will be submitting documentation and passing test results. No release to environment. 2/28/05 Received passing tightness test results for system. Bob Arcaro to submit affidavit.3/7/05 Received affidavit. Between 1/31/05 and 2/11/05, American Resource Technology excavated part of the tank system, isolated the tank and piping and the retested. All components tested

UNITED AMBULETTE (Continued) **S106737607**

tight but the condition of the cathodic protection isolating union on the stage 1 was worn and could have compromised the integrity of the line. There was no evidence of contamination in the excavation but the isolating unions were replaced on the stage 1 line, the suction line, the fill line and vent line as a preventative measure. On 2/15/05, a tightness test of the tank system was performed with the piping still exposed and was witnessed by FDNY who had witnessed the tightness test failure on 12/17/04. The system tested tight.

Remarks: RECOMMEND: GAS TANK HAS A WET LEAK: HAS BEEN REPORTED TO FIRE DEPT;

Material:
Site ID: 335249
Operable Unit ID: 1097320
Operable Unit: 01
Material ID: 577305
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 335249
Spill Tank Test: 1548407
Tank Number: 1
Tank Size: 4000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 12/17/2004
Test Method: Horner EZ Check I or II

---

201 SE 1/4-1/2 0.494 mi. 2606 ft.

APT COMPLEX
349 SCHOLES ST
BROOKLYN, NY

NY LTANKS **S105998649**
N/A

Relative: Lower

Actual: 16 ft.

LTANKS:
Site ID: 117954
Spill Number/Closed Date: 0300325 / 3/24/2004
Spill Date: 3/12/2003
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported

APT COMPLEX (Continued) **S105998649**

Reported to Dept:	4/9/2003
CID:	39
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/9/2003
Spill Record Last Update:	3/24/2004
Spiller Name:	Not reported
Spiller Company:	APT COMPLEX
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JOHN
Spiller Phone:	(718) 497-6044
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102538
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"Called John (718) 497-6044, left message.Allison Walsh returned call. Allison is a Lawyer, representingAPT Complex, (John). She asked that the tank test failure lettersent to her. Her address is 460 Park Avenue New York, NY 10022. # (212) 421-2150Letter was prepared and sent 4/10/03. This facility is not registered with PBS E.R. Tank test letter was returned 5/2/03.Tank test failure letter sent to John 349 Scholes Street Brooklyn, NY 11206 E.R.10/22/03. YK. Facility registered on 4/25/03 PBS # 2-608900. However, TT is overdue.2/2/2004. YK faxed an old TTF letter dated April 10, 2003 to David Yudelson (212-421-2150 X 219) attorney for this property.2/23/04. J.Krimgold talked to David Y. Tank taken out of service but not close yet. Trade-Winds did soil borings(?). He should call me back today with more info.3/24/04. J.Krimgold reviewed a letter report prepared by Trade-Winds dated 3/16/04. 3 soil samples was taken by drilling through the tank bottom of 3000 gal tank and 2 samples from 1100 gal tank. All came out negative. NFA letter on 3/24/04.
Remarks:	tank test failure

Material:

Site ID:	117954
Operable Unit ID:	866409
Operable Unit:	01
Material ID:	508406
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

APT COMPLEX (Continued) **S105998649**

Site ID:	117954
Spill Tank Test:	1528245
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

---

202 WNW 1/4-1/2 0.494 mi. 2607 ft.

64 FROST ST
64 FROST STREET
BROOKLYN, NY 11211

NY LTANKS S102232676
NY Spills N/A

Relative: Lower

Actual: 17 ft.

LTANKS:

Site ID:	261281
Spill Number/Closed Date:	9601530 / 8/5/2010
Spill Date:	4/30/1996
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	4/30/1996
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	4/30/1996
Spill Record Last Update:	8/5/2010
Spiller Name:	Not reported
Spiller Company:	MEEKER DISCOUNT MUFFLERS
Spiller Address:	64 FROST ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(718) 388-3329
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	6789
DEC Memo:	3/11/03 - SAMUEL- File available in active unassigned spill files.4/3/06 Diaz - Next Steps - February 2000 Investigation report stated further investigation & possible remedial work recommended. Verify & conduct work or close site.6/28/07. J.Krimgold reviewed and approved IWP submitted by FPM Group (631-737-6200)on June 27, 2007. The plan calls for 4 soil/gw samples around tanks excavation pit5/21/08. email from FPM's Ben Cancemi informed that excavation and

64 FROST ST (Continued) **S102232676**

sampling activities will commence on 5/22/08.02/12/09-Hiralkumar Patel. contamianted groundwater (with sheen) was discovered under basement floor at 684 Lorimer Street, site located behind subject gas station. based on location of both sites, contamination under house at 684 Lorimer street might be orinigated from subject gas station site. based on recent findings, case transferred from DEC Jacob to DEC Patel.found following documents for the subject site:- tank closure environmental site assessment, Nov. 1999- subsurface investigation report, Feb. 2000- subsurface investigation work plan, Jun. 27, 2007- subsurface investigation report and remedial action plan, Sep. 10, 2007abstract of tank closure report, Nov. 1999:- total of eight 550 gal and one 3000 gal USTs were removed including all pipings and portions of pump islands- all of the tank in very good condition and exhibited no evidence of corrosion- five of the tanks were empty, and three tanks were filled with concrete- 3000 gal tank contained approx. 1300 gal of water and petroleum products- total of eight soil and water samples were collected after tank removal- depth to groundwater ranged from 14-16 ft bg <---------- according to fire department record, in Nov. of 1984, the eight 550 gal tanks failed the official 10 year test- in sept. of 1985, three 550 gal were purged and filled with concrete- one pump was removed and all associated lines were sealed- highest PID readings were noted at an average depth of 10 to 15 ft <---------- fine to medium sized grain sand with clay lenses were found to a level of 12 to 14 ft bg- a layer of one foot in thickness of peat-like material intermixed with clay occurred at about 16 ft bg- found xylene contamination in east and north sidewall samples- found contamination in groundwater samplessoil
analyticals:--------XyleneNorth----4,600East----13,500groundwater
analyticals:----------west bottom pit------east bottom
pitBenzene----------160----------230Toluene----------200---
----------230Ethylbenzene--------97----------120Xylene-----
------1,410----------1,
520Naphthalene--------390----------640MTBE----------1,
900----------2,300abstract of subsurface investigation report,
feb. 2000:- eight borings (B1 thru B8) were advanced and collected soil and groundwater samples from borings- borings B1, B2 and B5 thru B8 were advanced in the immediate vicinity of the former tank field and borings B3 and B4 advanced near the west property line- groundwater found at 10 ft depth- soil samples collected at 8-10 ft depth from each boring except boring B4 where no sample collected; additional soil sample collected from boring B1 at 0-4 ft depth- high PID reading found during borings- contamination found in soil and groundwater samplesPID
readings:----------0-4-------4-8-------8-10B1----------1,120-----1,
160------1,
190B5----------110--------20---------55B6----------2,
010B7----------640soil
analyticals:----------B1----------B1----------B6
0-4 ft 8-10 ft 8-10
ftBenzene----------<250Xylene----------25,
000---------5,300----------1,2001,2,4-Trimethylbenzene--14,0001,3,
5-Trimethylbenzene--23,000---------3,200groundwater
analyticals:
----------GW1-----GW-3-----GW-4-----GW-5-----GW-6-----
GW-7-----GW-8Benzene----------
----------2,

64 FROST ST (Continued) **S102232676**

900Toluene----------520----------
----------540Ethylbenzene----------1
20------160------260----1,
700Xylene----------360----------640------420--
--2,000---15,
000Naphthalene----------
----140------700MTBE----------260------180------830------1
20----1,200----1,500----7,0001,2,
4-Trimethylbenzene----210----------190------750
----3,6001,3,
5-Trimethylbenzene----330----------170------300----1,
700----7,200abstract of subsurface investigation report, Sep., 2007:-
four soil boring were installed to final depth of 15 ft bg- soils
encountered at the property generally consisted of fine to medium
grained sand with gravel and trace amount of silt and clay from just
below grade to the top of blue-green clay layer- the top of the
blue-green clay layer was evident in all of the borings at depths
ranging from approx. 12.5 to 14.5 ft bg- the blue-green clay layer
showed no indications of potential contamination and was not fully
penetrated by any of the borings- staining and petroleum odors were
generally observed in the soils from all of the borings in an
interval near the water table surface, which was generally
encountered at 8 to 8.5 ft bg- interval of staining/odor was variable
in thickness and ranged from approx. one foot at boring B4 to approx.
7 ft at boring B1- PID readings in stained soils generally ranged
between 10 and 60 ppm- groundwater samples collected from each
borings- no free-phase product was observed in any borings- found
contamination in soil and groundwater samplessoil
analyticals:----------B1 (7-8 ft
depth)Benzene----------7,000Toluene----------200,
000Ethylbenzene----------110,000Xylene----------620,
000Naphthalene----------56,0001,2,4-Trimethylbenzene--510,0001,3,
5-Trimethylbenzene--150,000groundwater
analyticals:
----------B1-AQ---------B2-AQ---------B3-AQ---------
B4-AQBenzene----------1,500Toluene----------3,
700Ethylbenzene----------1,100Xylene----------4,
900Naphthalene----------470----------120MTBE--
----------3001
,2,4-Trimethylbenzene------1,500----------140----------4401,3,
5-Trimethylbenzene--------370abstract of remedial action plan, Sept.
2007:- proposed to excavate impacted soils in the vicinity of boring
B1- "based on relatively low levels of groundwater impact, its
apparently limited extent, and the apparent absence of free-phase
product, no groundwater remediation recommended"- three groundwater
wells are proposed to be installed for groundwater flow direction
determination- each well will be installed to a depth of no more than
14 ft, so as not to penetrate the clay underlying the property- each
well will be installed with 10 ft of screensummary:- groundwater
found at different depths: 14-16 ft during tank removal, 10 ft during
subsurface investigation in 2000 and at 8.5 ft during subsurface
investigation in 2007- no groundwater flow direction available- no
permanent wells installed at the site- heavy soil and groundwater
contamiantion found during each investigation- contamination found in
all sides of previous tank location- DEC Jacob issued RAP approval
letter on Oct. 4, 2007 <---------- as per email from Ben Cancemi
from FPM group, excavation according to approved RAP was scheduled on

64 FROST ST (Continued) **S102232676**

05/22/08 <--------Paul's LLC **site owner**318 Grand StreetBrooklyn, NY 11211Attn.: Paul JoffePh. (718) 486-6916 (O) (917) 693-3292 (C)email: pauljoffe@pauljoffe.comaccording to building department permit record, Mr. Joffe applied for permit to convert service station into dinning location.found another spill case reported at the gas station site. - 9806871: spill called in by citizen on 09/04/1998 about abandoned tanks; tipped over. spill closed on 02/26/2003.left message for Mr. Joffe.received call from Mr. Carter from Mr. Joffe's office. informed him about situation. Mr. Carter doesn't know much about this site but will ask Mr. Joffe to call back.Nathan CarterPh. (718) 486-680402/13/09-Hiralkumar Patel. left message for Mr. Joffe.left message for Ben Cancemi, consultant who was going to perform remedial activities.Ben T. Cancemi, CPGFPM GroupPh. (631) 737-6200Fax (631) 737-2410email: b.cancemi@fpm-group.com02/17/09-Hiralkumar Patel. received call from Ben from FPM Group. they excavated contaminated soil to water table in front of stores and installed three monitoring wells in June 2008. but haven't got authorization to sample these wells. Ben mentioned that endpoint sample analyticals were clean. asked Ben to submit sample analytical summary table and scaled site map with locations of endpoint samples and wells. also asked him to include approx. location of tank and dispenser islands.received email from Ben with sample analytical summary table with site plan showing endpoint sample and well locations. site plan shows that wells were installed in front of stores on-site. but no well observed during site visit, but found some fresh patches in concrete (which could be location of wells).received call from Mr. Joffe. asked him to submit remedial action report by the end of March 06, 2009. he mentioned that area between his property and houses along Lorimer street is a commercial property at 297 Meeker Ave which is a paint shop. 02/18/09-Hiralkumar Patel. received email from Ben. they will do well sampling on 02/20/09.02/20/09-Hiralkumar Patel. visited site. met Mr. Joffe and John (FPM group). monitoring wells found in front of store. groundwater was found around 6-7 ft bg. found sheen on water from each wells. will submit sample analyticals and groundwater flow direction.during site visit, noticed an auto repair shop at 59 Frost Street. met store manager. site has one 275 gal waste oil AST. tank is not registered. asked manager to register tank. sent email to DEC Jacob regarding un-registered waste oil tank at 59 Frost St. no parts cleaning operation at the auto repair shop.Billy AlexUnique Auto Repair59 Frost StBrooklyn, NY 11211PH. (718) 387-7537Fax (718) 384-6180email: uniqueauto59@gmail.comduring site visit, Mr. Joffe mentioned that site at 297 Meeker Ave runs from Meeker Ave to Frost Street, between the subject gas station and house at 684 Lorimer st where contaminated water was found. Mr. Joffe mentioned that there is painting business at 297 Meeker Ave.owner's address for 297 Meeker Ave, from property shark:Wanda Berry56 Frost St.Brooklyn, NY 11211Ph. (516) 627-4245owner's address for 297 Meeker Ave, from ACRIS:Wanda Berry PO Box 131 Manhasset, NY 11030-0131 02/23/09-Hiralkumar Patel. received email from Mr. Joffe. he found from NYC DOB that site across frost st was dry cleaner and had seven 1000 gal USTs.03/06/09-Hiralkumar Patel. received remedial action report from Ben. abstract:- 186.34 tons of contaminated soils were excavated from southern portion of the former UST area and in proximity to the location of a reported former fuel dispensing island- two endpoint bottom samples and four endpoint sidewall samples collected from excavation- found some contamination in endpoint bottom sample from

64 FROST ST (Continued) **S102232676**

north end of excavation- additional soil was removed from the north end and collected additional endpoint bottom sample- sidewall samples were taken at 7 ft bg and bottom samples taken at 11 ft bg (means bottom endpoint samples were taken below water table)- three monitoring wells (MW-1 through MW-3) were installed in proximity to the former soil boring locations B1 through B3 (borings that done during subsurface investigation in 2007)- well MW-2 installed at previous boring B1 and MW-3 installed at previous boring B3- wells were installed to a depth of approx. 14 ft bg and completed with ten feet of screen- groundwater was found at around 8 ft depth <---------- site-specific groundwater flow direction is to the northeast <---------- no free-phase product or other visible indications of potential contamination were observed- found MTBE contamination in all three wells---------MTBEMW-1------12MW-2-----150MW-3------50report missing scaled site map.03/13/09-Hiralkumar Patel. spoke with Ben at FPM. asked him to subimt scaled site map with all previous sampling/well locations. asked Ben about any dewatering as soil was removed from below water table also. Ben mentioned that water was coming into excavation so slowly. they were removing soil from excavation and wait till water from excavation bucket drain out before loading soil for disposal. so no dewatering happened.summary: during all previous investigations, highest contamination was found towards the west end of property, in close proximity to existing well MW-2. and MW-2 is the downgradient well at the property edge.based on results of high soil and groundwater contamination in area of MW-2 and groundwater flow direction, requires off-site groundwater investigation. requires off-site well downgradient from existing well MW-2.spoke with Mr. Joffe. explained him findings of previous investigations and asked him for one more well downgradient from well MW-2.sent letter to Mr. Joffe requiring delineation of possible soil and groundwater contamination, downgradient from well MW-2. letter emailed to Mr. Joffe and Ben.03/27/09-Hiralkumar Patel. received email from Mr. Cancemi with site map including location of proposed downgradient well.03/30/09-Hiralkumar Patel. received email from Mr. Cancemi. he is planning to install well on April 08, 2009. sent email to Mr. Cancemi approving proposed location.05/11/09-Hiralkumar Patel.1:35 PM:- received report from Mr. Cancemi. abstract:- off-site well installed (MW-4), about 20 ft downgradient from well MW-2- well installed to a depth of approx. 14 ft bg with 10 ft of screen- soil generally consisted of fine to medium-grained silty sand with gravel and trace amount of clay. brick, wood, coal, ash and concrete fragments were noted in the entire screen interval, but were more abundant in the top five ft of boring- faint petroleum odors and PID responses were noted on soils from 8 to 9 ft interval; no odor or PID noticed in other intervals- groundwater was found at approx. 7.5 ft bg <--------- one soil sample collected just above water table and one at 8-9 ft depth (below water table)- no free product observed in any wells on site- groundwater flow towards northeast <---------- 1,400 ppb of MTBE found in soil sample at 8-9 ft depth- 98 ppb of MTBE found in groundwater sample from MW-405/29/09-Hiralkumar Patel.10:46 AM:- sent letter to Mr. Joffe requiring surrounding area site map (with possible off-site source) and quarterly groundwater monitoring and sampling for a period of one year (including wells gauging during each sampling events to define site specific groundwater flow direction). letter emailed to Mr. Joffe and Mr. Cancemi.09/24/09-Hiralkumar Patel.3:20 PM:- spoke with Ben. they

64 FROST ST (Continued) **S102232676**

submitted proposal to Mr. Joffe but hasn't heard back.3:22 PM:- spoke with Mr. Joffe. he will ask Ben to conduct groundwater sampling.09/29/09-Hiralkumar Patel.12:13 PM:- received email from Ben. he will sample wells on 10/01/09. he mentioned that previous samples were analyzed for VOCs only as gasoline spill was the cause. he asked whether SVOC analysis needed for groundwater samples.12:45 PM:- sent email to Ben to analyze samples for VOCs only.12/01/09-Hiralkumar Patel.3:26 PM:- spoke with Mr. Joffe. he spoke with Ben today. Ben is preparing report. asked Mr. Joffe to submit report by the end of 12/11/09.12/02/09-Hiralkumar Patel.11:20 AM:- received quarterly groundwater sampling reprt from Ben. sampled all four wells in Oct. 2009. minor MTBE contamination found in samples. will sample all wells again in Jan. 2010.12:42 PM:- sent email to Ben asking to submit next quarterly report by end of Feb. 2010. email copied to Mr. Joffe.12/11/09-Hiralkumar Patel.11:20 AM:- received email from Ben including site map showing surrounding area use.01/25/10-Hiralkumar Patel.3:41 PM:- received message from Daniel Cole (212-341-0964) from NYC DEP. he mentioned that subject site is e-designated and currently reviewing closure report. Mr. Cole wants to know spill status.01/26/10-Hiralkumar Patel.2:40 PM:- received email from Ben. they collected second round of groundwater sampling last week and will submit second quarterly report once lab data is available.3:06 PM:- spoke with Mr. Cole. Mr. Cole asked if DEC requires anything more than quarterly monitoring. informed Mr. Cole that the department may require additional work based on quarterly groundwater sampling reports. Mr. Cole mentioned that owner did air monitoring. asked Mr. Cole to send copy of air monitoring report. he will email the report.02/11/10-Hiralkumar Patel.8:23 AM:- received second quarterly report from Ben. minor MTBE contamination found in groundwater samples (MW-3: 20 ppb, MW-4: 40 ppb). will sample wells in Apr. 2010.05/12/10-Hiralkumar Patel.1:56 PM:- received third quarterly report from Ben. minor MTBE contamination found in groundwater samples (MW-3: 23 ppb, MW-4: 57 ppb). will sample wells in July 2010.08/05/10-Hiralkumar Patel.8:57 AM:- received fourth quarterly report from Ben. minor MTBE contamination found in groundwater samples (MW-3: 20 ppb, MW-4: 25 ppb).based on submitted documents, case closed.2:50 PM:- spill closure letter emailed to Mr. Joffe. email copied to Ben.

Remarks: caller belives its a bad line - 5 - 550 gal tanks manifolded together

Material:

Site ID:	261281
Operable Unit ID:	1029178
Operable Unit:	01
Material ID:	351329
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

64 FROST ST (Continued) **S102232676**

Site ID:	261281
Spill Tank Test:	1544507
Tank Number:	1-5
Tank Size:	550
Test Method:	03
Leak Rate:	0
Gross Fail:	F
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	9806871
Facility Type:	ER
DER Facility ID:	6789
Site ID:	121571
DEC Region:	2
Spill Date:	9/3/1998
Spill Number/Closed Date:	9806871 / 2/26/2003
Spill Cause:	Abandoned Drums
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	9/4/1998
CID:	205
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/4/1998
Spill Record Last Update:	6/28/2007
Spiller Name:	Not reported
Spiller Company:	ABANDONED GASOLINE STA.
Spiller Address:	FOURTH & MEEKER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	(718) 482-6451
DEC Memo:	Not reported
Remarks:	call recv'ed from citizen. Re:abandoned tanks, tipped over.

Material:

Site ID:	121571
Operable Unit ID:	1067983
Operable Unit:	01
Material ID:	318008
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported

64 FROST ST (Continued) **S102232676**

Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

203
WSW
1/4-1/2
0.498 mi.
2630 ft.

555 GRAND STREET
555 GRAND STREET
BROOKLYN, NY 11211

NY BROWNFIELDS **S109942443**
NY E DESIGNATION **N/A**

Relative:
Lower

Actual:
29 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	489692
Acres:	.058
HW Code:	C224185
SWIS:	2401
Town:	New York City
Update By:	JAMORAS
Site Description:	Site Location: The site is located in the Williamsburg section of Brooklyn, Kings County. The site is approximately 100 feet west of the intersection of Grand Street and Lorimer Street on the north side of the Grand Street. Site Features: The site has approximately 25 feet of frontage on Grand Street and is .058 acres. The entire lot is currently developed with a three-story mixed use (residential and commercial) building; there is a basement present below approximately 65 percent of the building and the remaining 35 percent of the building is slab on grade. The structure was built in 1887.Current Zoning and Land Use: The site is currently inactive (vacant), and is zoned for R7A residential with a C2-4 commercial overlay. The surrounding parcels are currently used for a combination of commercial and residential, and utility right-of-ways. Past Use of the Site: The site was most recently used as a dry cleaner between 1999 and 2013, and also had residential tenants on the second and third floor. Various retail stores operated on the property between 1934 and 1992. According to the regulatory database, the site was listed as a RCRA SQG (small quantity generator). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of silty non-native fill, to a depth of approximately 2 feet below basement slab grade followed by sandy-silt to a depth of approximately 4 feet below basement slab grade. Groundwater depth is approximately 22.5 feet below the ground surface and is expected to flow easterly.
Env Problem:	Nature and Extent of Contamination: Based upon the investigations conducted to date, the primary contaminants of concern for this site are PCE and TCE in soil vapor, and mercury in soil. It appears that elevated concentrations of contaminants in soil vapor may not be limited to the on-site area. Soil Soil sampling was limited to on-site. Of the six soil samples collected at the site (to a depth of four feet below the basement slab) no volatile organic compounds (VOCs) were detected above the unrestricted use Soil Cleanup Objective (SCO). Very low concentrations of PCE (0.420 ppm) were

555 GRAND STREET (Continued) **S109942443**

detected in shallow soil (0-2 feet), however, the concentration is below the unrestricted use SCO (for PCE which is 1.3 ppm). Various SVOCs slightly exceeded Restricted Residential Soil Cleanup Objectives (RRSCOs) and various metals exceeded RRSCOs, with mercury being the most significant exceedance at 2.72 ppm. Site related soil contamination is not expected to extend off-site based on the available data. During January and February 2014 supplemental soil investigations were conducted at the site as a part of the RI. In January seven soil borings were advanced down to a depth of four feet below the basement slab. PCE (0.0064 ppm) was detected in only one location. Again in February 2014, during monitoring well installation, six soil samples were collected from throughout the site at varying depths (12 to 28 feet below grade). The highest concentration of PCE detected was 0.29 ppm at a depth of 12 feet below the basement slab (which is below the unrestricted use SCO of 1.3 ppm). Groundwater In February 2014 two monitoring wells were installed on-site. Groundwater samples collected from three monitoring wells (the two newly installed on-site wells and one existing off-site well located on the sidewalk in front of/upgradient of the site) detected very low concentration of PCE; the highest PCE concentration detected was 16 ppb in an on-site monitoring well (NYSDEC groundwater quality standards for PCE is 5 ppb). TCE was not detected in any samples.Soil Vapor and Indoor Air Soil vapor samples were collected in July 2013 while dry cleaning operations were still being performed at the site. Elevated concentrations of PCE and TCE have been detected in on-site sub-slab soil vapor and indoor air samples. PCE and TCE concentrations in sub-slab soil vapor ranged from 7,730 micrograms per cubic meter (ug/m3) to 228,000 ug/m3 and 84.8 ug/m3 to 623 ug/m3, respectively. PCE was detected in indoor air samples at concentrations up to 6,230 ug/m3 and TCE was detected at concentrations up to 13.7 ug/m3. Elevated levels of PCE (3,930 ug/m3) and some TCE (3.92 ug/m3) were also detected in the ambient air sample collected in front of the site. Contaminated soil vapor may be migrating off-site. Special Resources Impacted/Threatened: The site is located in the urban area and Fish and a Wildlife Impact Analysis is not warranted.Significant Threat: The site represents a significant threat due to the soil vapor contamination which may not be limited to the on-site area.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. On-site soil vapor intrusion sampling has identified impacts to indoor air quality and actions to address exposure concerns are necessary in the event the building is re-occupied. The potential for soil vapor intrusion to occur in off-site buildings will be evaluated.

E DESIGNATION:

Tax Lot(s):	31
Tax Block:	2779
Borough Code:	Not reported

555 GRAND STREET (Continued) **S109942443**

E-No: E-232
Effective Date: 7/29/2009
Satisfaction Date: Not reported
Ceqr Number: 09DCP056K
Ulurp Number: 090334ZMK
Zoning Map No: 12c 13a 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

204
SE
1/4-1/2
0.499 mi.
2637 ft.

SCHOLES ST. STATION **EDR MGP** **1008407899**
SCHOLES ST 7 BOGART STS. MESSEROLE AND MORGAN AVE. **N/A**
BROOKLYN, NY 11206

Relative:
Lower

Actual:
17 ft.

Manufactured Gas Plants:
No additional information available

205
SSW
1/4-1/2
0.500 mi.
2639 ft.

MOST HOLY TRINITY RESIDENCE **NY LTANKS** **U001839612**
157 GRAHAM AVE **NY UST** **N/A**
BROOKLYN, NY 11211 **NY HIST UST**

Relative:
Lower

Actual:
29 ft.

LTANKS:
Site ID: 131344
Spill Number/Closed Date: 0306650 / 8/25/2006
Spill Date: 9/23/2003
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: LXZIELIN
Referred To: Not reported
Reported to Dept: 9/23/2003
CID: 252
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/23/2003
Spill Record Last Update: 2/14/2007
Spiller Name: JUAN PEREZ
Spiller Company: CARING COMMUNITIES
Spiller Address: 157 GRAHAM AVE

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Spiller City,St,Zip: BROOKLYN, ZZ
Spiller County: 001
Spiller Contact: JUAN PEREZ
Spiller Phone: (718) 963-3955
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 17030
DEC Memo: 08/25/06 - ZielinskiThe drawing has been received and photos indicating filling lines and vent lines. They run in the basement above a concrete floor. Thew case is closed.8/17/06 - ZielinskiSteven Tsevdos called and said that they have only two 257-gallon tanks on the site. The drawing depicting the location of the closed tank and pipe lines would be sent to DEC. 8/17/06 - ZielinskiReceived soil samples' analyses taken 3 feet below tha tank bottom--no indication of soil contamination (eDOCs). Jim Donelan of Protest faxed a tank test report-- it had been a dry leak. Left a message for Steven Tsevdos, Caring Communities manager, asking for a layout of the failed tank and a number of tanks in service since the subject tank had been closed, and no records of registered tanks at the site.7/17/06 - ZielinskiSent a letter requesting that within three weeks of receipt of this letter, Caring Communities would submit a report, required by the department's letter of September 24, 2003. This letter provides that the Caring Communities must submit soil sample analyses, an explanation of tank failure, and remowe contaminated soil. 7/13/06 - ZielinskiTook photos of at the site. No indication of soil boring. Talked to Mr. Perez- superintendent. Left a note to Mr. Alonso requesting soil sampling results.7/6/06 - ZielinskiSpoke with Gustavo Alonso, the manager of Caring Communites. Asked him to sent all documents related to the spill. That same day, he faxed a DEC letter of 09/24/03 requesting a report and an affidavit; a proposal of work to be done, submitted by Petroleum Tank Cleaners, dated 11/21/03; an affidavit from Mercury Tank & Pump Inc., dated 4/9/04.Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHAO"9/24/03 DDO Sawyer sent tank test failure letter to:Juan Perez157 Graham Ave.Brooklyn, NY 1120610/3/05: CBNCalled Juan Perez and was told that the spill has been taken care of. Requested documentation/report for spill closure. Manager will get back to DEC on that.
Remarks: RECOMMEND TO EXCAVATE-ISOLATE- AND RE-TEST

Material:
Site ID: 131344
Operable Unit ID: 875397
Operable Unit: 01
Material ID: 503846
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Site ID:	131344
Spill Tank Test:	1528699
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

UST:

Id/Status:	2-347760 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	04/19/2008
UTM X:	589301.56730999995
UTM Y:	4506768.7647500001
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	17054
Affiliation Type:	Facility Owner
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	ASSOCIATE DIRECTOR
Contact Name:	GEORGE STATHOUDAKIS
Address1:	191 JORALEMON STREET, 8TH FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 722-6138
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/3/2005

Site Id:	17054
Affiliation Type:	Mail Contact
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	Not reported
Contact Name:	GEORGE STATHOUDAKIS
Address1:	191 JORALEMON STREET,
Address2:	8TH FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 722-6138
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/3/2005

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Site Id:	17054
Affiliation Type:	On-Site Operator
Company Name:	MOST HOLY TRINITY RESIDENCE
Contact Type:	Not reported
Contact Name:	JUAN PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-3957
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/3/2005

Site Id:	17054
Affiliation Type:	Emergency Contact
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	Not reported
Contact Name:	JUAN PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 219-4989
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/3/2005

Tank Info:

Tank Number:	001
Tank ID:	33195
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	03/25/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	10/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	03/03/2005

Equipment Records:

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

HIST UST:

PBS Number:	2-347760
SPDES Number:	Not reported
Emergency Contact:	CHARLES GANLEY
Emergency Telephone:	(917) 866-4480
Operator:	JUAN PEREZ
Operator Telephone:	(718) 963-3955
Owner Name:	CARING COMMUNITIES HDFC, INC.
Owner Address:	191 JORALEMON STREET
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Telephone:	(718) 722-6000
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	CARING COMMUNITIES HDFC, INC.
Mailing Address:	157 GRAHAM AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11206
Mailing Contact:	Not reported
Mailing Telephone:	(718) 963-3957
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	157 GRAHAM AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/21/1998
Expiration Date:	04/19/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	5000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Not reported
Dispenser: Suction
Date Tested: 10/01/1998
Next Test Date: 10/01/2003
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

BD206 **K - GREENPOINT MGP - ENERGY CENTER** **NY RGA HWS** **S114964237**
ENE **287 MASPETH AVENUE** **N/A**
1/2-1 **BROOKLYN, NY**
0.526 mi.
2779 ft. **Site 1 of 2 in cluster BD**

Relative: RGA HWS:
Lower

2012	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVENUE
2011	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVENUE
2010	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVENUE

Actual:
13 ft.

BD207 **K - GREENPOINT MGP - ENERGY CENTER** **NY RGA HWS** **S114964236**
ENE **287 MASPETH AVE** **N/A**
1/2-1 **BROOKLYN, NY**
0.526 mi.
2779 ft. **Site 2 of 2 in cluster BD**

Relative: RGA HWS:
Lower

2009	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVE
2008	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVE
2007	K - GREENPOINT MGP - ENERGY CENTER	287 MASPETH AVE

Actual:
13 ft.

208
East
1/2-1
0.545 mi.
2880 ft.

NEWTOWN CREEK
SOUTH END OF IVY HILL ROAD
BROOKLYN, QUEENS, NY 11222

NPL **1011845384**
CERCLIS **NYN000206282**
NY MANIFEST

Relative:
Lower

Actual:
-1 ft.

NPL:

EPA ID:	NYN000206282
Cerclis ID:	0206282
EPA Region:	2
Federal:	G
Final Date:	2010-09-29 00:00:00
Site Score:	50

CERCLIS:

Site ID:	0206282
EPA ID:	NYN000206282
Facility County:	KINGS, QUEENS
Short Name:	NEWTOWN CREEK
Congressional District:	12, 14
IFMS ID:	A206
SMSA Number:	5600
USGC Hydro Unit:	Not reported
Federal Facility:	Not a Federal Facility
DMNSN Number:	0.00000
Site Orphan Flag:	Not reported
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	S
NFRAP Flag:	Not reported
Parent ID:	Not reported
RST Code:	Not reported
EPA Region:	02
Classification:	Not reported
Site Settings Code:	Not reported
NPL Status:	Currently on the Final NPL
DMNSN Unit Code:	Not reported
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	Not reported
Non NPL Status Date:	/ /
Site Fips Code:	Not reported
CC Concurrence Date:	/ /
CC Concurrence FY:	Not reported
Alias EPA ID:	Not reported
Site FUDS Flag:	Not reported

CERCLIS Site Contact Name(s):

Contact ID:	2000116.00000
Contact Name:	CAROLINE KWAN
Contact Tel:	(212) 637-4275
Contact Title:	Remedial Project Manager (RPM)
Contact Email:	Not reported
Contact ID:	13003472.00000
Contact Name:	NICA KLABER
Contact Tel:	(212) 637-4309

NEWTOWN CREEK (Continued) **1011845384**

Contact Title: Remedial Project Manager (RPM)
Contact Email: KLABER.NICA@EPA.GOV

Contact ID: 2000070.00000
Contact Name: BETSY DONOVAN
Contact Tel: (212) 637-4369
Contact Title: Remedial Project Manager (RPM)
Contact Email: Not reported

CERCLIS Site Alias Name(s):
Alias ID: 13000087
Alias Name: NEWTOWN CREEK
Alias Address: SOUTH END OF IVY HILL ROAD
BROOKLYN, NY 11211
Alias Comments: Not reported
Site Description: Contaminated sediment plume resulting from numerous industrial activities along newtown Creek

CERCLIS Assessment History:

Action Code: 001
Action: DISCOVERY
Date Started: / /
Date Completed: 08/15/08
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: PROPOSAL TO NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 09/23/09
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Notice Letters Issued
Date Started: / /
Date Completed: 03/25/10
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

NEWTOWN CREEK (Continued) **1011845384**

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: FINAL LISTING ON NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 09/29/10
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 02/05/10
Date Completed: 07/07/11
Priority Level: Not reported
Operable Unit: ENTIRE SITE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Original Action Take Over

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY NEGOTIATIONS
Date Started: 03/25/10
Date Completed: 07/07/11
Priority Level: Not reported
Operable Unit: ENTIRE SITE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 07/07/11
Priority Level: Not reported
Operable Unit: ENTIRE SITE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

NEWTOWN CREEK (Continued) **1011845384**

Action:	POTENTIALLY RESPONSIBLE PARTY REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started:	07/07/11
Date Completed:	/ /
Priority Level:	Not reported
Operable Unit:	ENTIRE SITE
Primary Responsibility:	Responsible Party
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	New Action Resulting from Take Over

For detailed financial records, contact EDR for a Site Report.:

Federal Register Details:

Fed Register Date:	09/29/10
Fed Register Volume:	75
Page Number:	59983

Fed Register Date:	09/23/09
Fed Register Volume:	74
Page Number:	48511

Click this hyperlink while viewing on your computer to access
283 additional US CERCLIS Financial: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYN000206282
Country:	USA
Location Address 1:	- VERNON BLVD
Location Address 2:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip Code:	11101
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NEWTOWN CREEK SUPERFUND SITE
Contact:	C/O ANCHOR QEA LLC
Address:	TICE BLVD - SUITE
City/State/Zip:	WO0ODCLIFF LAKE, NJ 07677
Country:	USA
Phone:	201-571-0912

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2014
Trans1 Recv Date:	10/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYN000206282
Trans1 EPA ID:	Not reported

NEWTOWN CREEK (Continued) **1011845384**

Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013301186JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

BE209 **ACME STEEL/METAL WORKS** **NY RGA HWS** **S114963174**
NNE **95 LOMBARDY STREET** **N/A**
1/2-1 **BROOKLYN, NY**
0.593 mi.
3129 ft. **Site 1 of 2 in cluster BE**

Relative:
Higher

Actual:
44 ft.

RGA HWS:

2012	ACME STEEL/METAL WORKS	95 LOMBARDY STREET
2011	ACME STEEL/METAL WORKS	95 LOMBARDY STREET
2010	ACME STEEL/METAL WORKS	95 LOMBARDY STREET
2009	ACME STEEL/METAL WORKS	95 LOMBARDY STREET

BE210 **95 LOMBARDY ST./ACME ARCH. PRODS., INC.** **NY SHWS** **U003652054**
NNE **95 LOMBARDY ST** **NY UST** **N/A**
1/2-1 **BROOKLYN, NY 11222** **NY HIST UST**
0.593 mi.
3129 ft. **Site 2 of 2 in cluster BE**

Relative:
Higher

Actual:
44 ft.

SHWS:

Program:	HW
Site Code:	405853
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	1.010
HW Code:	224131
Record Add:	10/28/2008
Record Upd:	03/02/2015
Updated By:	JAMORAS

Site Description: Location:The site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the east side of Vandervoort Avenue between Anthony and Lombardy Streets. Site Features:The site

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

is completely covered by one (1) two-story and three (3) one-story brick buildings. The site is surrounded by other commercial and industrial properties. Sergeant William Dougherty Playground is located immediately north of the site across Anthony Street, and the eastbound on-ramp to the Brooklyn-Queens Expressway (I-278) is located one block to the north. A small residential area is located one block south of the site.Current Zoning/Use(s):The site is zoned for manufacturing. The site is currently used as a granite warehouse and showroom at 95 Lombardy Street, and a paper distribution office and a kitchen cabinet warehouse/showroom at 46 Anthony Street.Historical Use(s):The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was utilized as a metal fabricator and painting facility from the 1930's to the late 2000's, and a Department database which lists the site as a generator of F001 waste (spent halogenated solvents used in de-greasing). This investigation was conducted in several phases, and was completed in the Summer of 2009.Based on an extensive records search and several inspections, it was determined that waste paint, waste oil, waste degreasers, and waste water precipitate were generated at the property during site operations. Numerous floor drains with unknown outfall locations existed within the property, and were identified as potential injection wells. In addition, an underground storage tank that was used as a dip tank and for storing degreasing products was located in the northwest corner of the site. Several pipes that originated from the dip tank discharged to a floor drain in the loading dock area.Site Geology and Hydrogeology:The site is underlain by a fill unit (0.5-9' thick), a sand/silty sand unit (~100' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit at various depths within the site area, a sand and gravel unit (~5' thick), and the Raritan Formation (~120-125' below ground surface). Groundwater is approximately 35-45' below ground surface in the vicinity of the site. Groundwater flows northeast toward Newtown Creek, which lies approximately 2,500' northeast of the site.

Env Problem: Nature and Extent of Contamination:- GroundwaterThe primary contaminant of concern at the site is trichloroethene (TCE). TCE has been found on-site in shallow groundwater at concentrations up to 66,000 ppb, and in deep groundwater at concentrations up to 70,000 ppb, well above Part 703.5 class GA standards (5 ppb). Concentrations of tetrachloroethene (up to 8,000 ppb) and 1,2-dichloroethene (3,200 ppb) have also been found above their respective Part 703.5 class GA standards (5 ppb each). The plume of TCE-contaminated groundwater has migrated at least 400' off-site.- Soil Vapor and Indoor AirConcentrations of PCE in soil vapor have been found up to 3,100 ug/m^3. Concentrations of TCE in soil vapor have been found up to 4,500 ug/m^3, and in indoor air up to 13 ug/m^3. Significant Threat:The site poses a significant environmental threat due to ongoing releases of TCE from source areas into soil and groundwater.

Health Problem: Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area anddata evaluated as they become available.

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/28/2008 12:21:00 PM
Record Upd:	9/20/2013 2:01:00 PM
Updated By:	ldennist
Own Op:	Owner
Sub Type:	01
Owner Name:	MAUREEN BABIS
Owner Company:	NYC IDA
Owner Address:	110 WILLIAM STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	01
Owner Name:	PAUL BURDYN
Owner Company:	ACME ARCHITECTURAL PRODUCTS, INC.
Owner Address:	251 LOMBARDY STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Greenpoint Branch
Owner Address:	107 Norman Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
HW Code:	224131
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224129
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	10/31/2008 2:34:00 PM
Record Updated:	10/31/2008 2:34:00 PM
Updated By:	MOBARRIE
Crossref ID:	224130
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Record Added Date: 10/31/2008 2:41:00 PM
Record Updated: 10/31/2008 2:41:00 PM
Updated By: MOBARRIE
Crossref ID: 224132
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:42:00 PM
Record Updated: 10/31/2008 2:42:00 PM
Updated By: MOBARRIE
Crossref ID: 224121
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 1/30/2009 12:36:00 PM
Record Updated: 1/30/2009 12:36:00 PM
Updated By: JAAVERSA

UST:
Id/Status: 2-603942 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/25/2004
UTM X: 589801.46251999994
UTM Y: 4508492.4255999997
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 25835
Affiliation Type: Facility Owner
Company Name: WHITEHEAD COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 513 PORTER AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 384-7800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25835
Affiliation Type: Mail Contact
Company Name: ACME ARCHITECTURAL PRODUCTS, INC.
Contact Type: Not reported
Contact Name: MILDRED OLSEN
Address1: 513 PORTER AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 384-7800
EMail: Not reported

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25835
Affiliation Type:	On-Site Operator
Company Name:	95 LOMBARDY ST./ACME ARCH. PRODS., INC.
Contact Type:	Not reported
Contact Name:	ACME ARCH PRODS., INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25835
Affiliation Type:	Emergency Contact
Company Name:	WHITEHEAD COMPANY
Contact Type:	Not reported
Contact Name:	WILLIAM MCDONNELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	56116
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	8500
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
G08 - Tank Secondary Containment - Flexible Internal Linning (Bladder)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 2
Tank ID: 56117
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1080
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
G08 - Tank Secondary Containment - Flexible Internal Linning (Bladder)
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:
PBS Number: 2-603942
SPDES Number: Not reported
Emergency Contact: WILLIAM MCDONNELL
Emergency Telephone: (718) 384-7800
Operator: ACME ARCH PRODS., INC.
Operator Telephone: (718) 384-7800
Owner Name: WHITEHEAD COMPANY
Owner Address: 513 PORTER AVENUE
Owner City,St,Zip: BROOKLYN, NY 11222
Owner Telephone: (718) 384-7800
Owner Type: Corporate/Commercial

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Owner Subtype:	Not reported
Mailing Name:	ACME ARCHITECTURAL PRODUCTS, INC.
Mailing Address:	513 PORTER AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11222
Mailing Contact:	MILDRED OLSEN
Mailing Telephone:	(718) 384-7800
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	02/25/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	8500
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	B
Leak Detection:	None
Overfill Prot:	Vent Whistle
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	2
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	1080
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	B
Leak Detection:	None
Overfill Prot:	Vent Whistle
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

211
NW
1/2-1
0.609 mi.
3216 ft.

BERKMAN BROS INC
ECKFORD ST
BROOKLYN, NY 11222

RCRA-CESQG **1000271415**
NY SHWS **NYD001236017**
NY LTANKS
NY MANIFEST
NY CBS

Relative:
Lower

Actual:
17 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	BERKMAN BROS INC
Facility address:	ECKFORD ST BROOKLYN, NY 11222
EPA ID:	NYD001236017
Mailing address:	MEADOW ST BROOKLYN, NY 11206
Contact:	GERALD R BERKMAN
Contact address:	MEADOW ST BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	(718) 782-1827
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

BERKMAN BROS INC (Continued) **1000271415**

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	GERALD R BERKMAN
Owner/operator address:	LEE AVE STE 287 BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/29/1976
Owner/Op end date:	Not reported

Owner/operator name:	BLUE DIAMOND DEV CORP
Owner/operator address:	LEE AVE STE 287 BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/15/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	BERKMAN BROS INC
Classification:	Small Quantity Generator

Date form received by agency:	02/18/2004
Site name:	BERKMAN BROS INC

BERKMAN BROS INC (Continued) **1000271415**

Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: BERMAN BROS INC
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Site name: BERKMAN BROS INC
Classification: Small Quantity Generator

Date form received by agency: 07/28/1980
Site name: BERKMAN BROS INC
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/23/1989
Date achieved compliance: 08/21/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/16/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/14/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/19/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

BERKMAN BROS INC (Continued) **1000271415**

Evaluation date: 08/23/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/21/1990
Evaluation lead agency: State

Evaluation date: 12/23/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SHWS:
Program: HW
Site Code: 470590
Classification: P
Region: 2
Acres: .234
HW Code: 224168
Record Add: 10/30/2012
Record Upd: 10/30/2012
Updated By: BXANDERS
Site Description: Site was referred to DER by the NYCOER due to elevated concentrations of arsenic in on-site surficial soil. No additional information is available at this time.
Env Problem: Additional investigation will be needed in order to define the nature and extend of the contamination.
Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: Eckford - Greenpoint LLC
Owner Address: 55 Eckford Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11222
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported

BERKMAN BROS INC (Continued) **1000271415**

Record Updated: Not reported
Updated By: Not reported

LTANKS:

Site ID:	107414
Spill Number/Closed Date:	9214462 / 3/31/1993
Spill Date:	3/26/1993
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	3/31/1993
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	3/31/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/1/1993
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	MYSTIC FUEL CO.
Spiller Address:	1902 STEINWAY ST.
Spiller City,St,Zip:	L.I.C., NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	94484
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"
Remarks:	MYSTIC CLEANED SPILL WITH SPEEDI-DRI, PICK UP AND DISPOSED.

Material:

Site ID:	107414
Operable Unit ID:	981754
Operable Unit:	01
Material ID:	400668
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

BERKMAN BROS INC (Continued) **1000271415**

Tank Test:

NY MANIFEST:

EPA ID:	NYD001236017
Country:	USA
Location Address 1:	55 ECKFORD ST
Location Address 2:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip Code:	11222
Location Zip Code 4:	Not reported

Mailing Info:

Name:	BERKMAN BROS
Contact:	BERKMAN BROS
Address:	85 MEADOW STREET
City/State/Zip:	BROOKLYN, NY 11206
Country:	USA
Phone:	718-782-1827

Manifest:

Document ID:	NYG3571191
Manifest Status:	Not reported
Trans1 State ID:	RP52906PA
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2003
Trans1 Recv Date:	06/02/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity:	28047
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	NJA0724693
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	NJDEPS869
Generator Ship Date:	01/04/1990
Trans1 Recv Date:	01/04/1990
Trans2 Recv Date:	01/08/1990
TSD Site Recv Date:	01/09/1990
Part A Recv Date:	01/12/1990

BERKMAN BROS INC (Continued) **1000271415**

Part B Recv Date:	01/23/1990
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID:	NJD002182897
Waste Code:	F005 - UNKNOWN
Quantity:	00384
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1990

Document ID:	NJA4077061
Manifest Status:	Not reported
Trans1 State ID:	S2265
Trans2 State ID:	Not reported
Generator Ship Date:	12/10/2003
Trans1 Recv Date:	12/10/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002385730
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	03032
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYG3199959
Manifest Status:	Not reported
Trans1 State ID:	AA395E
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2003
Trans1 Recv Date:	12/11/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/16/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	31267
Units:	P - Pounds
Number of Containers:	001

BERKMAN BROS INC (Continued) **1000271415**

Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Document ID: NYG3199968
Manifest Status: Not reported
Trans1 State ID: 0440464ME
Trans2 State ID: Not reported
Generator Ship Date: 12/19/2003
Trans1 Recv Date: 12/19/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/05/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001236017
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: P121 - ZINC CYANIDE
Quantity: 01150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 023
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Document ID: NYG2628405
Manifest Status: Not reported
Trans1 State ID: RP52906PQ
Trans2 State ID: Not reported
Generator Ship Date: 09/23/2002
Trans1 Recv Date: 09/23/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/24/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001236017
Trans1 EPA ID: NYF006000053
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 28004
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG2628576
Manifest Status: Not reported
Trans1 State ID: RP73457QC

BERKMAN BROS INC (Continued) **1000271415**

Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2002
Trans1 Recv Date:	02/08/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/08/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG0891999
Manifest Status:	Not reported
Trans1 State ID:	RP73463PQ
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/2001
Trans1 Recv Date:	07/24/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NYF006000053
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYG0852138
Manifest Status:	Not reported
Trans1 State ID:	RM73079PQ
Trans2 State ID:	Not reported
Generator Ship Date:	03/15/2000
Trans1 Recv Date:	03/15/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/16/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	CDX0000FA094

BERKMAN BROS INC (Continued) **1000271415**

Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	P121 - ZINC CYANIDE
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	MIA7001766
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/1999
Trans1 Recv Date:	04/07/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID:	MID098011992
Waste Code:	P121 - ZINC CYANIDE
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	MIA4497247
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYJA334
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/1997
Trans1 Recv Date:	10/24/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/07/1998
Part A Recv Date:	11/14/1997
Part B Recv Date:	02/09/1998
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID:	MID098011992
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

BERKMAN BROS INC (Continued) **1000271415**

Year: 1997

Document ID: MIA2780694
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS226
Trans2 State ID: Not reported
Generator Ship Date: 07/29/1993
Trans1 Recv Date: 07/29/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 08/09/1993
Part A Recv Date: 08/10/1993
Part B Recv Date: 08/25/1993
Generator EPA ID: NYD001236017
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: MID096963194
Waste Code: D004 - ARSENIC 5.0 MG/L TCLP
Quantity: 00500
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1993

Document ID: NJA1326996
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 01/21/1992
Trans1 Recv Date: 01/21/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 01/29/1992
Part A Recv Date: 01/30/1992
Part B Recv Date: 02/10/1992
Generator EPA ID: NYD001236017
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F005 - UNKNOWN
Quantity: 00384
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1992

Document ID: MIA2579230
Manifest Status: Completed copy
Trans1 State ID: NJXK81XX
Trans2 State ID: NJXK81XX
Generator Ship Date: 02/26/1992
Trans1 Recv Date: 02/26/1992

BERKMAN BROS INC (Continued) **1000271415**

Trans2 Recv Date:	02/26/1992
TSD Site Recv Date:	02/27/1992
Part A Recv Date:	03/06/1992
Part B Recv Date:	03/16/1992
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	NJD054126164
TSDF ID:	MID098011992
Waste Code:	F008 - PLAT SLDG FM BTM PLAT BATH OPER CYANIDE.
Quantity:	00487
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D004 - ARSENIC 5.0 MG/L TCLP
Quantity:	00419
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1992

Document ID:	NJA0985680
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	NJDEPS869
Generator Ship Date:	02/19/1991
Trans1 Recv Date:	02/19/1991
Trans2 Recv Date:	02/20/1991
TSD Site Recv Date:	02/21/1991
Part A Recv Date:	03/12/1991
Part B Recv Date:	03/07/1991
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID:	NJD002182897
Waste Code:	F005 - UNKNOWN
Quantity:	00384
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1991

Document ID:	MIA1654360
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYJA-203
Trans2 State ID:	NJDEPS103
Generator Ship Date:	05/08/1990
Trans1 Recv Date:	05/09/1990
Trans2 Recv Date:	05/14/1990
TSD Site Recv Date:	05/16/1990

BERKMAN BROS INC (Continued) **1000271415**

Part A Recv Date:	06/22/1990
Part B Recv Date:	07/03/1990
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD981873664
Trans2 EPA ID:	NJD981873664
TSDF ID:	MID098011992
Waste Code:	F008 - PLAT SLDG FM BTM PLAT BATH OPER CYANIDE.
Quantity:	04500
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0818620
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	03/23/1990
Trans1 Recv Date:	03/23/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/28/1990
Part A Recv Date:	04/19/1990
Part B Recv Date:	04/11/1990
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F005 - UNKNOWN
Quantity:	00384
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0906939
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	06/27/1990
Trans1 Recv Date:	06/27/1990
Trans2 Recv Date:	06/28/1990
TSD Site Recv Date:	06/28/1990
Part A Recv Date:	08/28/1990
Part B Recv Date:	07/16/1990
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID:	NJD002182897
Waste Code:	F005 - UNKNOWN
Quantity:	00320
Units:	P - Pounds

BERKMAN BROS INC (Continued) **1000271415**

Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1990

Document ID:	MIA9026399
Manifest Status:	Not reported
Trans1 State ID:	0440465ME
Trans2 State ID:	Not reported
Generator Ship Date:	12/22/2003
Trans1 Recv Date:	12/22/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/29/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001236017
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	MID980991566
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00880
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	016
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00605
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	011
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

CBS:

CBS Number:	2-000058
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	06/14/1999
Dec Region:	2
UTMX:	588840.22131000
UTMY:	4508396.6102499

BF212 **GREENPOINT ENERGY FACILITY** **NY SHWS** **S104787368**
NE **287 MASPETH AVENUE** **NY SWF/LF** **N/A**
1/2-1 **BROOKLYN, NY 11211** **NY LTANKS**
0.636 mi. **NY TANKS**
3356 ft. **Site 1 of 2 in cluster BF** **NY Spills**
NY VCP
Relative: **NY BROWNFIELDS**
Lower **NY MOSF**

Actual:
18 ft.

SHWS:

Program:	HW
Site Code:	372971
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	117.000
HW Code:	224052
Record Add:	11/02/2006
Record Upd:	11/19/2014
Updated By:	GWCROSS

Site Description: Location:The site is a large parcel located along Newtown Creek at 287 Maspeth Avenue in Brooklyn,NY in Kings County.It is bounded ny Newtown Creek to the east, Maspeth Ave. to the south, Vandevoort Ave. to the west, and Lombardy St. to the north.Site Features:The site is currently known as the Greenpoint Energy Center, and houses a major liquefied natural gas storage facility and compressor station, an operations center for KeySpan's distribution and service units, and a warehouse facility. Current zoning and land uses:Surrounding land uses are mixed industrial, residential, and commercial.The nearest residential land use is located adjacent to the northwest corner of the site.Past use of the site:A large MGP and byproduct coking operation operated on the site from 1928 until 1952. Coal tar has been found in subsurface soils, but the full extent of contamination has not yet been established. The surrounding neighborhood also conatins a large petroleum spill, apparently unrelated to the MGP.A VCA to address the northeast corner of the property was listed under V00631. This work was undertaken to allow expansion of the existing liquefied gas facility, and included a relatively small portion of the site. A site-wide RI began in the summer of 2012. The RI will be conducted in 3 phases and is scheduled to conclude in late 2014.Site Geology/hydrogeology:The site is underlain by fill and heterogeneous glacial deposits that include outwash sands with lenticulas silt and till deposits. Bedrock is approximately 200 feet below the ground surface. Groundwater flows northeasterly, toward the Newtown Creek.

Env Problem: According to the USEPA a preliminary assessment (PA) was prepared for the site dated September 24, 1986. The PA was not submitted or reviewed. A draft preliminary site investigaiton report was submitted to the Department in June 2004 for the northeast corner of the site. This report noted MGP DNAPL found across the site in the shallow depths (0-5 feet bgs) This material caused most of the soil samples to fail standards for several SVOCs including naphthalene, benzo(a)pyrene, and benzo(a)anthracene. The area noted was addressed in an IRM, but should be representative of a best-case for the site as a whole as it was in an area which was not actually part of the MGP operations. These exceedances represent a significant threat to the environment, This material is also known to contribute to groundwater contamination and sediment contamination. The site's location, adjacent to Newtown creek, means there is a potential for DNAPL to be leaking into the creek, contaminating sediments and

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

	surface water.A RI is currently ongoing. The first phase, begun in July 2012 is focused on the eastern portion of the site, adjacent to Newtown Creek.
Health Problem:	Public exposures to wastes in soil and groundwater at the site are unlikely since access to the site is restricted. Potential impacts from soil vapors need to be evaluated. Potential exposures to seepage from the site in the adjacent Newtown Creek are unknown. Eating of fish and shellfish from Newtown Creek is restricted based on fish advisories for the East River, which apply to Newtown Creek as a tributary.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	11/6/2006 2:08:00 PM
Record Upd:	9/20/2013 2:11:00 PM
Updated By:	ldennist
Own Op:	Owner
Sub Type:	NNN
Owner Name:	N/A
Owner Company:	BROOKLYN UNION GAS COMPANY
Owner Address:	1 METROTECH CENTER
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Country:	United States of America
HW Code:	224052
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224052
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224052
Waste Type:	NAPHTHALENE
Waste Quantity:	17.00
Waste Code:	Not reported
HW Code:	224052
Waste Type:	PYRENE
Waste Quantity:	83.00
Waste Code:	Not reported
HW Code:	224052
Waste Type:	BENZENE
Waste Quantity:	3.30
Waste Code:	Not reported
HW Code:	224052
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	33.00
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

SWF/LF:
Flag: ACTIVE
Region Code: 2
Phone Number: 7182705786
Owner Name: Mattia Auriemma
Owner Type: Private
Owner Address: 84-24 Ditmas Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11236
Owner Email: Not reported
Owner Phone: 7182705786
Contact Name: Mattia Auriemma
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: mattia@nationalgrid.com
Contact Phone: 7182705786
Activity Desc: C&D processing - registration
Activity Number: [24W38]
Active: Yes
East Coordinate: 590245
North Coordinate: 4508023
Accuracy Code: 4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status: Registration
Waste Type: Asphalt;Concrete;Brick;Rock;Soil (Clean);Construction & Demolition Debris
Authorization #: 24W38
Authorization Date: Not reported
Expiration Date: Not reported

LTANKS:
Site ID: 118273
Spill Number/Closed Date: 9009058 / 3/4/2003
Spill Date: 11/16/1990
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 11/16/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/20/1990

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Spill Record Last Update:	3/4/2003
Spiller Name:	Not reported
Spiller Company:	BROOKLYN UNION GAS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102793
DEC Memo:	Not reported
Remarks:	4K TANK FAILED HORNER EZY CHECK WITH AN UNDETERMINED LEAK RATE, WILL EXCAVATE, ISOLATE,REPAIR & RETEST.CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

Material:

Site ID:	118273
Operable Unit ID:	949558
Operable Unit:	01
Material ID:	432836
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	118273
Spill Tank Test:	1537896
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	181619
Spill Number/Closed Date:	9211562 / 2/6/2007
Spill Date:	1/7/1993
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Reported to Dept:	1/7/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1/8/1993
Spill Record Last Update:	2/6/2007
Spiller Name:	FACILITY MANAGER
Spiller Company:	KEYSPAN ENERGY
Spiller Address:	ONE METROTECH CENTER
Spiller City,St,Zip:	BROOKLYN, NY 11201-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	14020
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"This spill case was reassigned from DEC (Sigona) to Rommel on01/07/2004.Per Bart Polozzitti of Keyspan(516-545-5511), major renovations have occurred at the site. The tank may have been removed, he will forward relevant information when gathered.01/02/07-Zhune got an e-mail from Bart Polozzitti requesting additional time to get the information. He said hopefully he will get it by 02/17/07. Bart Polozzitti cell # 646-235040301/09/07 Bart sent the information a tightness test report from Tanknology Corp. and a letter is included. The letter state the following:The subject underground storage tank (361A)located at 287 Maspeth Ave. Brooklyn, New York was tightness tested unsuccessfully on january 7, 1993. The other three fuel thanks on the same facility (Nos. 363, 364 &365) were tested tight on the same day. After repairing the vent connections causing the ullage leak above the level of product, the tank was retested on January 25, 1993 and passed. There was no release at any time to the surrounding environment.Spill Closed
Remarks:	EIR

Material:

Site ID:	181619
Operable Unit ID:	978534
Operable Unit:	01
Material ID:	404952
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	181619

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Spill Tank Test:	1541042
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

TANKS:

Facility Id:	2-306398
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	07/14/2017
UTM X:	590290.94556999998
UTM Y:	4507980.1856899997

SPILLS:

Facility ID:	1006581
Facility Type:	ER
DER Facility ID:	394939
Site ID:	439941
DEC Region:	2
Spill Date:	9/17/2010
Spill Number/Closed Date:	1006581 / 9/17/2010
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	9/17/2010
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/17/2010
Spill Record Last Update:	9/17/2010
Spiller Name:	Not reported
Spiller Company:	NAT GRID
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MARTIN BRUCELLA
Contact Phone:	(516) 545-2401
DEC Memo:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Remarks: APPROX 25-30 GALLONS OF GAS MAIN DRIP WATER SPILLED TO SOIL/ASPHALT AND GRAVEL. CLEANUP IN PROGRESS.

Material:

Site ID:	439941
Operable Unit ID:	1190570
Operable Unit:	01
Material ID:	2185598
Material Code:	9999
Material Name:	Other - GAS MAIN DRIP WATER
Case No.:	Not reported
Material FA:	Other
Quantity:	30
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0106270
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181617
DEC Region:	2
Spill Date:	9/13/2001
Spill Number/Closed Date:	0106270 / 2/6/2007
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	9/13/2001
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/13/2001
Spill Record Last Update:	2/6/2007
Spiller Name:	CALLER
Spiller Company:	KEYSPAN
Spiller Address:	175 EAST OLD COUNRTY RD
Spiller City,St,Zip:	HICKSVILLE, NY -
Spiller Company:	001
Contact Name:	SHAWN DAVIS
Contact Phone:	(516) 545-5589
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"9/13/01. J.Krimgold called Shawn Davis of Keyspan and left message.7/26/06 - Mike - Bart Palozzotti is now attatched to the

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

number 516-545-5511. Unsure if Shawn Davis left Keyspan. Unable to get a hold of Bart.This spill case was reassigned from Bishop to Zhune02/10/07 Bart Palozzotti sent informartion. Miller Environmental Group did the cleaned up. I received invoice, Daily job report and the waste manifest. Spill Closed

Remarks: FAULTY VALVE ON TRUCK MAY HAVE CAUSED SPILL-CONTRACTORS ENROTE FOR CLEANUP.

Material:

Site ID:	181617
Operable Unit ID:	844615
Operable Unit:	01
Material ID:	531133
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0506134
Facility Type:	ER
DER Facility ID:	102793
Site ID:	351275
DEC Region:	2
Spill Date:	8/18/2005
Spill Number/Closed Date:	0506134 / 8/18/2005
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	8/18/2005
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/18/2005
Spill Record Last Update:	8/18/2005
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	ED MILLER

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Contact Phone:	(516) 792-7302
DEC Memo:	8/18/05-Vought-Called Ed and NYFD and NYPD left scene. FDNY put sand around pooled oil. NO responsible parties seen. FDNY diked oil. Pool is near gutter and spill originated from the middle of the street. Pooled oil is 3'x3'. FDNY contact is Captain Horton (Ladder 146) and Captain Villendahl (Engine 206). No sewers or drains affected and DEP was contacted. Vought called Sanitation Operations and they were previously called and are on their way. Spill closed by Vought.
Remarks:	YOU CAN SEE THE TRAIL OF MOTOR OIL ON THE ROADWAY. CLEAN UP IS NOT IN PROCESS. NOT THEIR RESPOSIBILY. ED CELL #917-731-8543.

Material:

Site ID:	351275
Operable Unit ID:	1108800
Operable Unit:	01
Material ID:	2098772
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9606233
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181621
DEC Region:	2
Spill Date:	8/13/1996
Spill Number/Closed Date:	9606233 / 10/27/1997
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	8/14/1996
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/14/1996
Spill Record Last Update:	7/16/1999
Spiller Name:	MARY CASEY
Spiller Company:	BROOKLYN UNION

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Spiller Address:	287 MASPETH AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	MARY CASEY
Contact Phone:	(718) 403-3088
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"SEE FILE.
Remarks:	there was a lack of over fill protection on tanks which allowed spill - all material was cleaned up - mark tibbe is familiar with facility

Material:

Site ID:	181621
Operable Unit ID:	1037209
Operable Unit:	01
Material ID:	345494
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	10
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0303442
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181395
DEC Region:	2
Spill Date:	7/2/2003
Spill Number/Closed Date:	0303442 / 7/9/2003
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	7/2/2003
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/2/2003
Spill Record Last Update:	8/8/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	BART POLIZZOTTI
Contact Phone:	(516) 545-5511
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHAO"
Remarks:	contractor cleaning out drain accidentally dumped approx 2 yds of oily sludge type materal on ground at location - clean upcrew enroute

Material:

Site ID:	181395
Operable Unit ID:	870549
Operable Unit:	01
Material ID:	504309
Material Code:	0058A
Material Name:	SLUDGE
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

VCP:

Program Type:	VCP
Site Code:	57149
HW Code:	V00631
Site Class:	A
SWIS:	2401
Region:	2
Town:	New York City
Acres:	2.000
Date Record Added:	01/16/2003
Date Record Updated:	06/30/2009
Updated By:	GWCROSS
Site Description:	The Greenpoint Energy Center is located in the Greenpoint section of Brooklyn, New York. The surrounding area is dominated by industrial and commercial uses with a limited residential area northwest of the the site.
Env Problem:	The site is impacted by MGP residuals. Coal tar is present at the site. KeySpan has proposed to remediate the most accessible contamination and leave the remaining contamination in place. The proposed remedy is under review by the department.
Health Problem:	Public exposures to wastes in soil and groundwater at the site are unlikely since access to the site is restricted. Potential impacts from soil vapors need to be evaluated. Potential exposures to seepage from the site in the adjacent Newtown Creek are unknown. Eating of fish and shellfish from Newtown Creek is restricted based on fish advisories for the East River, which apply to Newtown Creek as a tributary.

GREENPOINT ENERGY FACILITY (Continued) **S104787368**

BROWNFIELDS:
Program: BCP
Site Code: 57389
Acres: 119.000
HW Code: C224052
SWIS: 2401
Town: New York City
Update By: MOBARRIE
Site Description: See Site 224052
Env Problem: Not reported
Health Problem: Not reported

MOSF:
Facility ID: 2-2340
Program Type: MOSF
Tank Status: Unregulated/Closed
Expiration Date: 03/31/1992
Dec Region: 2
UTMX: 590195.67868000
UTMY: 4507995.2537200

BF213 **GREENPOINT** **EDR MGP** **1008407892**
NE **287 MASPETH AVENUE** **N/A**
1/2-1 **BROOKLYN, NY 11211**
0.636 mi.
3356 ft. **Site 2 of 2 in cluster BF**

Relative: Lower

Manufactured Gas Plants:
No additional information available

Actual: 18 ft.

BG214 **BCF OIL REFINING, INC.** **NY RGA HWS** **S114963349**
ENE **360 MASPETH AVENUE - SOUTHSIDE** **N/A**
1/2-1 **BROOKLYN, NY**
0.639 mi.
3376 ft. **Site 1 of 3 in cluster BG**

Relative: Lower

RGA HWS:
2003 BCF OIL REFINING, INC. 360 MASPETH AVENUE - SOUTHSIDE

Actual: 13 ft.

BG215 **US ENVIRONMENTAL PROTECTION AGENCY** **CERCLIS** **1000272490**
ENE **C O BCF OIL REFINING SITE** **RCRA NonGen / NLR** **NYD068273044**
1/2-1 **BROOKLYN, NY 11211** **NY SHWS**
0.639 mi. **NY MANIFEST**
3376 ft. **Site 2 of 3 in cluster BG** **PRP**

Relative: Lower

CERCLIS:
Site ID: 0204261
EPA ID: NYD068273044
Facility County: KINGS
Short Name: BCF OIL REFINING, INC.
Congressional District: 12
IFMS ID: 02PU

Actual: 13 ft.

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

SMSA Number:	Not reported
USGC Hydro Unit:	Not reported
Federal Facility:	Not a Federal Facility
DMNSN Number:	0.00000
Site Orphan Flag:	Not reported
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	R
NFRAP Flag:	Not reported
Parent ID:	Not reported
RST Code:	Not reported
EPA Region:	02
Classification:	Not reported
Site Settings Code:	Not reported
NPL Status:	Not on the NPL
DMNSN Unit Code:	Not reported
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)
Non NPL Status Date:	07/13/00
Site Fips Code:	36047
CC Concurrence Date:	/ /
CC Concurrence FY:	Not reported
Alias EPA ID:	Not reported
Site FUDS Flag:	Not reported

CERCLIS Site Contact Name(s):

Contact ID:	2000051.00000
Contact Name:	TOM BUDROE
Contact Tel:	(732) 906-6191
Contact Title:	On-Scene Coordinator (OSC)
Contact Email:	BUDROE.THOMAS@EPA.GOV

Alias Comments: Not reported

Site Description: Oil refinery containing approximately one half million gallons of PCB contaiminated waste oil. The owner has been in negotiations with the NYSDEC, but has decided to walk away and have the government perform the cleanup. The site has been determined to be removal eligible. Richard Gardineer, from DEP informed EPA that DEP wants to wait for the removal action results before doing a PA at the site.

CERCLIS Assessment History:

Action Code:	001
Action:	REMOVAL ASSESSMENT
Date Started:	03/27/00
Date Completed:	03/29/00
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	EPA Fund-Financed
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code:	001
Action:	Notice Letters Issued

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Date Started: / /
Date Completed: 04/28/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 04/28/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/23/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: Notice Letters Issued
Date Started: / /
Date Completed: 05/23/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMOVAL NEGOTIATIONS
Date Started: 04/28/00
Date Completed: 11/06/00
Priority Level: Not reported

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 11/06/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMOVAL
Date Started: 05/25/00
Date Completed: 01/02/01
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMOVAL
Date Started: 01/03/01
Date Completed: 10/26/01
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH
Date Started: 03/27/00
Date Completed: 08/23/02
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: COST RECOVERY NEGOTIATIONS
Date Started: 08/23/02
Date Completed: 09/30/03
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: SECTION 107 LITIGATION
Date Started: 09/30/03
Date Completed: 01/09/07
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: JUDICIAL/CIVIL JUDGMENT
Date Started: / /
Date Completed: 01/09/07
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: JUDICIAL/CIVIL JUDGMENT
Date Started: / /
Date Completed: 07/08/10
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Click this hyperlink while viewing on your computer to access
111 additional US CERCLIS Financial: record(s) in the EDR Site Report.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	US ENVIRONMENTAL PROTECTION AGENCY
Facility address:	C O BCF OIL REFINING SITE 360-362 MASPETH AVE BROOKLYN, NY 11211
EPA ID:	NYD068273044
Mailing address:	WOODBRIDGE AVE 360-3 62 MASPETH AVE EDISON, NJ 08837
Contact:	THOMAS P BUDROE
Contact address:	WOODBRIDGE AVE 360-3 EDISON, NJ 08837
Contact country:	US
Contact telephone:	(732) 906-6191
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: US ENVIRONMENTAL PROTECTION AGENCY
Classification: Not a generator, verified

Date form received by agency: 02/27/2002
Site name: US ENVIRONMENTAL PROTECTION AGENCY
Classification: Large Quantity Generator

Date form received by agency: 11/14/1984
Site name: TANKS-A-LOT INC
Classification: Unverified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K049
. Waste name: SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.

. Waste code: K051
. Waste name: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

. Waste code: K052
. Waste name: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

. Waste code: X001
. Waste name: WASTE OILS

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

SHWS:
Program: HW
Site Code: 56747
Classification: N
Region: 2
Acres: 1.900
HW Code: 224034
Record Add: 07/14/2004
Record Upd: 04/13/2011
Updated By: JAQUINN
Site Description: The BCF Oil site is located within an urban, industrialized area of East Williamsburg, Brooklyn. Previously existing buildings and above ground storage tanks have been removed, and the property is being used as a Marshall's impound lot. A National Grid facility borders the site on the north, Newtown Creek on the south, a city automobile impound lot on the east and a scrap metal processing facility on the west. The total area is 1.9 acres, of which 0.3 acres is land under water.The property was used as a petroleum distribution facility for many years, starting in the early 1900?s. In 1980, the terminal was modified for use as a waste oil processing facility, and was used for waste oil recycling from 1980 to 1994. Routine sampling detected PCBs in the waste oil, and operations ceased in 1994. The property is zoned M3 (manufacturing/industrial), and it is currently used to store impounded automobiles. The site consists primarily of historic fill placed upon wetlands. Groundwater exists approximately 5 to 10 feet below grade and flows both to the north and south from the site.A remedial investigation of the site has been completed. The site was managed as a single operable unit. See also NYSDEC spill #9406807
Env Problem: Based upon investigations conducted to date, the primary contaminant of concern at the site are those associated with petroleum. Separate phase petroleum contamination has been detected in numerous locations, although mobile product may be more limited.The site was extensively assessed for PCB contamination, but no significant levels of PCBs were detected on site. PCBs were detected in the Newtown Creek sediment, but the sediment contamination appears to be part of

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

a larger problem and not related to releases from the site.A significant threat created by the potential for release of PCB-contaminated oil stored in dilapidated storage tank areas was eliminated by a removal action performed by the USEPA in 2000/2001.

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	NNN
Owner Name:	C/O SETH D. FRIEDLAND, ESQ.
Owner Company:	NEWTON DEVELOPMENT LLC
Owner Address:	62 WILLIAM STREET
Owner Addr2:	THIRD FLOOR
Owner City,St,Zip:	NEW YORK, NY 10005
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Gerald Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	Brooklyn Community Board 1
Owner Addr2:	435 Graham Ave
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Shelly Paus
Owner Company:	Brooklyn Public Library, Leonard Branch
Owner Address:	Brooklyn Public Library, Leonard Branch
Owner Addr2:	81 Devoe St.
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

EPA ID:	NYD068273044
Country:	USA
Location Address 1:	360 MASPETH AVE
Location Address 2:	Not reported

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Location City: BROOKLYN
Location State: NY
Location Zip Code: 11211
Location Zip Code 4: Not reported

Mailing Info:
Name: TANKS A LOT INC
Contact: MICHAEL CALLEIA
Address: 2890 WOODBRIDGE AVE
City/State/Zip: EDISON, NJ 08837
Country: USA
Phone: 718-387-9710

Manifest:

Document ID: TXA8258800
Manifest Status: Not reported
Trans1 State ID: 41038
Trans2 State ID: Not reported
Generator Ship Date: 02/07/2001
Trans1 Recv Date: 02/07/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/09/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD068273044
Trans1 EPA ID: OKD981588791
Trans2 EPA ID: Not reported
TSDF ID: TXD055141378
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 16419
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG1885725
Manifest Status: Not reported
Trans1 State ID: NY235541A
Trans2 State ID: Not reported
Generator Ship Date: 05/17/2001
Trans1 Recv Date: 05/17/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/18/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD068273044
Trans1 EPA ID: NYD986969947
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 22961
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG1885734
Manifest Status: Not reported
Trans1 State ID: NY53412R
Trans2 State ID: Not reported
Generator Ship Date: 05/17/2001
Trans1 Recv Date: 05/17/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/18/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD068273044
Trans1 EPA ID: PAD008781072
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 18343
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Document ID: NJA0191566
Manifest Status: Completed copy
Trans1 State ID: NJSWAS751
Trans2 State ID: Not reported
Generator Ship Date: 05/21/1986
Trans1 Recv Date: 05/21/1986
Trans2 Recv Date: / /
TSD Site Recv Date: 05/21/1986
Part A Recv Date: 06/10/1986
Part B Recv Date: 05/28/1986
Generator EPA ID: NYD068273044
Trans1 EPA ID: NJD980650196
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)
Quantity: 12180
Units: P - Pounds
Number of Containers: 022
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1986

Document ID: NYG1885869
Manifest Status: Not reported
Trans1 State ID: 236049ANY

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Trans2 State ID:	Not reported
Generator Ship Date:	06/04/2001
Trans1 Recv Date:	06/04/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD068273044
Trans1 EPA ID:	PAD008781072
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	20267
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYG1887561
Manifest Status:	Not reported
Trans1 State ID:	170732ANY
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2001
Trans1 Recv Date:	05/30/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD068273044
Trans1 EPA ID:	PAD008781072
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	18652
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYG1887588
Manifest Status:	Not reported
Trans1 State ID:	236049ANY
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2001
Trans1 Recv Date:	05/30/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD068273044
Trans1 EPA ID:	PAD008781072

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	20448
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYG1885743
Manifest Status:	Not reported
Trans1 State ID:	NY235274A
Trans2 State ID:	Not reported
Generator Ship Date:	05/17/2001
Trans1 Recv Date:	05/17/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/18/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD068273044
Trans1 EPA ID:	NYD986969947
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	19878
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2001

PRP:

PRP name:	BCF OIL REFINING INC CARY FIELDS

BG216 **B.C.F. OIL REFINING, INC.** **NY RGA HWS** **S114963316**
ENE **360 MASPETH AVENUE, SOUTHSIDE** **N/A**
1/2-1 **BROOKLYN, NY**
0.639 mi.
3376 ft. **Site 3 of 3 in cluster BG**

Relative:
Lower

Actual:
13 ft.

RGA HWS:

2010	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2009	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2008	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2007	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2006	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2005	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE
2000	B.C.F. OIL REFINING, INC.	360 MASPETH AVENUE, SOUTHSIDE

217
West
1/2-1
0.642 mi.
3390 ft.

BQE/ANSBACHER COLOR & DYE FACTORY
MEEKER AVENUE
BROOKLYN, NY

NY SHWS **S106780917**
N/A

Relative:
Lower

Actual:
15 ft.

SHWS:
Program: HW
Site Code: 55913
Classification: Does not present a significant threat to the public health or the environment - action may be deferred.
Region: 2
Acres: .600
HW Code: 224016
Record Add: 11/18/1999
Record Upd: 01/11/2008
Updated By: JAAVERSA
Site Description: This site lies underneath the elevated Brooklyn - Queens Expressway (I-278) along Meeker Avenue between Metropolitan and Union Avenues in the Williamsburg Section of Brooklyn. It is believed that during the construction of the BQE, waste material and debris from the former Ansbacher Color & Dye Factory may have been used as fill material in the project area. A Phase II - type investigation was conducted by the New York State Department of Transportation in 1988. The investigation found hazardous levels of arsenic and lead in the soil and elevated levels of arsenic, lead and cyanide in the groundwater. During the reconstruction of the BQE in the early 1990s, the NYSDOT completed an IRM (soil removal) within the project's right-of way. The remaining contaminated soil is located beneath asphalt and concrete.A Preliminary Site Assessment was completed during the summer of 1999 to evaluate the areas outside the BQE footprint. The sampling results indicate that the subsurface soils within the footprint of the former Ansbacher Plant contain elevated levels of arsenic, lead, and mercury. The groundwater in this area is also contaminated with these metals, but the contaminated groundwater has not migrated significantly beyond the footprint of the former factory.
Not reported
Env Problem: The primary contaminants of concern at this site are arsenic, lead, mercury and cyanide.Investigations indicate that the subsurface soils within the footprint of the former Ansbacher Plant contain elevated levels of arsenic, lead, and mercury. The groundwater in this area is also contaminated with these metals.The site does not constitute a significant threat to the environment as the contaminated soil is covered by existing layers of asphalt and concrete, and the contaminated groundwater has not migrated significantly beyond the footprint of the former factory.
Health Problem: Residual arsenic and lead contamination remain under the BQE and is covered with several layers of concrete and asphalt, thereby preventing direct contact. Contaminated soil also underlies several on-site buildings formerly used by Ansbacher. Groundwater in the area is not used, since public water is available. Off-site sampling of surface soils from residential yards adjacent to the site indicated the presence of metals (particularly arsenic and lead) at concentrations above the range of concentrations typically encountered in urban neighborhoods. However, the exact source of the metals in the soils could not be determined from the data collected. The NYSDOH gave the residents advice on how to minimize their exposure to these surface soil contaminants.
Dump: False

BQE/ANSBACHER COLOR & DYE FACTORY (Continued) **S106780917**

Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	unknown
Disp Term:	unknown
Lat/Long:	40:42:52:0 / 73:57:12:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	ANSBACHER COLOR & DYE FACTORY
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	NYS Department of Transportation
Owner Address:	State Campus - Building 5
Owner Addr2:	Not reported
Owner City,St,Zip:	Albany, NY 12232
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Ansbacher Color & Dye Factory
Owner Address:	Meeker Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	B99
Owner Name:	Not reported
Owner Company:	ANSBACHER COLOR & DYE FACTORY
Owner Address:	MEEKER AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	B99
Owner Name:	Not reported
Owner Company:	NYS Department of Transportation
Owner Address:	STATE CAMPUS, BUILDING 5
Owner Addr2:	Not reported
Owner City,St,Zip:	ALBANY, NY 12232
Owner Country:	United States of America
HW Code:	224016
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224016
Waste Type:	ARSENIC

BQE/ANSBACHER COLOR & DYE FACTORY (Continued) **S106780917**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BH218 **ACME STEEL PARTITION CO INC** **RCRA NonGen / NLR** **1000198707**
NNE **513 PORTER AVE** **NY SHWS** **NYD001281823**
1/2-1 **BROOKLYN, NY 11222** **NY MANIFEST**
0.684 mi.
3609 ft. **Site 1 of 2 in cluster BH**

Relative:
Higher

Actual:
50 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ACME STEEL PARTITION CO INC
Facility address:	513 PORTER AVE BROOKLYN, NY 11222
EPA ID:	NYD001281823
Mailing address:	PORTER AVE BROOKLYN, NY 11222
Contact:	HY BERSHAN
Contact address:	PORTER AVE BROOKLYN, NY 11222
Contact country:	US
Contact telephone:	(718) 384-7800
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ACME STEEL PARTITION CO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ACME STEEL PARTITION CO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ACME STEEL PARTITION CO INC
Classification: Not a generator, verified

Date form received by agency: 08/15/1980
Site name: ACME STEEL PARTITION CO INC
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/19/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SHWS:
Program: HW
Site Code: 405855
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 1.210
HW Code: 224132
Record Add: 10/28/2008
Record Upd: 03/02/2015
Updated By: JAMORAS
Site Description: Location:The site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the east side of Porter Avenue between Anthony and Lombardy Streets. Site Features:The site is covered by several two-story buildings and two (2) separate open lots. The site is surrounded by other commercial and industrial properties. A large National Grid energy facility is located one

ACME STEEL PARTITION CO INC (Continued) **1000198707**

block south of the site across Lombardy Street. Sergeant William Dougherty Playground is located one block northwest of the site across Anthony Street, and the elevated Brooklyn-Queens Expressway (I-278) is located one block to the north. A small residential area is located one block southwest of the site.Current Zoning/Use(s):The site is zoned for manufacturing. The site is currently used as a marble and granite distribution warehouse and a fruit distribution warehouse at 72 Anthony Street, and a City-Wide truck maintenance shop at 498 Porter Avenue.Historical Use(s):The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was utilized as a brass foundry from the 1960's to 1993, and a Department database which lists the site as a generator of F001 waste (spent halogenated solvents used in de-greasing). This investigation was conducted in several phases, and was completed in the Summer of 2009.Based on an extensive records search and several inspections, it was determined that waste paint, waste oil, waste degreasers, and waste water precipitate were generated at the property during site operations. Numerous floor drains with unknown outfall locations existed within the property, and were identified as potential injection wells. Several storage tanks that were used as dip tanks for degreasing products were located in the northeast corner of the site, where evidence of releases existed. In addition, the open lot adjacent to the 72 Anthony Street building was used as a drum storage area that held all chemical wastes from the surrounding ACME facilities.Site Geology and Hydrogeology:The site is underlain by a fill unit (0.5-9' thick), a sand/silty sand unit (~110' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit at various depths within the site area, a sand and gravel unit (~5' thick), and the Raritan Formation (~130-135' below ground surface). Groundwater is approximately 45-55' below ground surface in the vicinity of the site. Groundwater flows northeast toward Newtown Creek, which lies approximately 2,000' northeast of the site.

Env Problem: Nature and Extent of Contamination:- GroundwaterThe primary contaminants of concern at the site are tetrachloroethene (PCE) and trichloroethene (TCE). Both PCE (up to 6,900 ppb) and TCE (up to 12,000 ppb) have been found at concentrations well above the Part 703.5 class GA standard of 5 ppb. The plume of PCE and TCE-contaminated groundwater has migrated at least 400' off-site.- SoilPCE has been found in on-site soils at concentrations up to 220 ppm, which is above the soil cleanup objective for unrestricted use (1.3 ppm).- Soil VaporConcentrations of PCE have been found up to 19,000 ug/m^3. Concentrations of TCE have been found up to 1,300 ug/m^3.Significant Threat:The site poses a significant environmental threat due to ongoing releases of TCE from source areas into soil and groundwater.

Health Problem: Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area anddata evaluated as they become available.

Dump: False

Structure: True

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/28/2008 10:35:00 AM
Record Upd:	2/27/2015 8:53:00 AM
Updated By:	DKHARRIN
Own Op:	Owner
Sub Type:	01
Owner Name:	MAUREEN BABIS
Owner Company:	NYC IDA
Owner Address:	110 WILLILAM STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	01
Owner Name:	PAUL BURDYN
Owner Company:	ACME ARCHITECTURAL PRODUCTS, INC.
Owner Address:	251 LOMBARDY STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Greenpoint Branch
Owner Address:	107 Norman Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
HW Code:	224132
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224132
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224121
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	1/30/2009 12:36:00 PM
Record Updated:	1/30/2009 12:36:00 PM
Updated By:	JAAVERSA
Crossref ID:	224129

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:34:00 PM
Record Updated: 10/31/2008 2:34:00 PM
Updated By: MOBARRIE
Crossref ID: 224130
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:41:00 PM
Record Updated: 10/31/2008 2:41:00 PM
Updated By: MOBARRIE
Crossref ID: 224131
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:42:00 PM
Record Updated: 10/31/2008 2:42:00 PM
Updated By: MOBARRIE

NY MANIFEST:
EPA ID: NYD001281823
Country: USA
Location Address 1: 72 ANTHONY ST
Location Address 2: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip Code: 11222
Location Zip Code 4: Not reported

Mailing Info:
Name: ACME STEEL DOOR
Contact: ACME STEEL DOOR
Address: 72 ANTHONY STREET
City/State/Zip: BROOKLYN, NY 11222
Country: USA
Phone: 718-384-7800

Manifest:

Document ID: NYB5006232
Manifest Status: Completed copy
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 06/30/1992
Trans1 Recv Date: 06/30/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 07/01/1992
Part A Recv Date: 07/29/1992
Part B Recv Date: 07/17/1992
Generator EPA ID: NYD001281823
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00330
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 123
Year: 1992

Document ID: NYB5005296
Manifest Status: Completed copy
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 04/29/1992
Trans1 Recv Date: 04/29/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 04/30/1992
Part A Recv Date: / /
Part B Recv Date: 05/22/1992
Generator EPA ID: NYD001281823
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 123
Year: 1992

Document ID: NYB2094030
Manifest Status: Completed copy
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 06/17/1991
Trans1 Recv Date: 06/17/1991
Trans2 Recv Date: / /
TSD Site Recv Date: 06/19/1991
Part A Recv Date: 07/09/1991
Part B Recv Date: 06/27/1991
Generator EPA ID: NYD001281823
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 130
Year: 1991

Document ID: NYB2094786
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PA6703
Trans2 State ID: Not reported

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Generator Ship Date:	10/02/1991
Trans1 Recv Date:	10/02/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/04/1991
Part A Recv Date:	11/01/1991
Part B Recv Date:	10/31/1991
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	130
Year:	1991

Document ID:	NYA7056639
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	03/02/1989
Trans1 Recv Date:	03/02/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/03/1989
Part A Recv Date:	03/13/1989
Part B Recv Date:	03/10/1989
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYB2092086
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	IA7667
Trans2 State ID:	Not reported
Generator Ship Date:	11/13/1990
Trans1 Recv Date:	11/13/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/15/1990
Part A Recv Date:	12/14/1990
Part B Recv Date:	12/17/1990
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported

ACME STEEL PARTITION CO INC (Continued) **1000198707**

TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00054
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	130
Year:	1990

Document ID:	NYA7190739
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	05/10/1989
Trans1 Recv Date:	05/10/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/12/1989
Part A Recv Date:	05/25/1989
Part B Recv Date:	05/30/1989
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYB2079540
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	IA7667
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/1990
Trans1 Recv Date:	06/20/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/21/1990
Part A Recv Date:	08/28/1990
Part B Recv Date:	08/13/1990
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00305
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1990

ACME STEEL PARTITION CO INC (Continued) **1000198707**

Document ID:	NYB2088045
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PA6703
Trans2 State ID:	Not reported
Generator Ship Date:	11/09/1989
Trans1 Recv Date:	11/09/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/14/1989
Part A Recv Date:	01/04/1990
Part B Recv Date:	11/27/1989
Generator EPA ID:	NYD001281823
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

BH219 **ACME STEEL/BRASS FOUNDRY** **NY RGA HWS** **S114963173**
NNE **72 ANTHONY STREET** **N/A**
1/2-1 **BROOKLYN, NY**
0.684 mi.
3609 ft. **Site 2 of 2 in cluster BH**

Relative:
Higher

Actual:
50 ft.

RGA HWS:

2012	ACME STEEL/BRASS FOUNDRY	72 ANTHONY STREET
2011	ACME STEEL/BRASS FOUNDRY	72 ANTHONY STREET
2010	ACME STEEL/BRASS FOUNDRY	72 ANTHONY STREET
2009	ACME STEEL/BRASS FOUNDRY	72 ANTHONY STREET

BI220 **VARICK AVENUE** **NY RGA HWS** **S114965329**
ESE **165 VARICK AVENUE** **N/A**
1/2-1 **BROOKLYN, NY**
0.685 mi.
3619 ft. **Site 1 of 2 in cluster BI**

Relative:
Lower

Actual:
12 ft.

RGA HWS:

2006	VARICK AVENUE	165 VARICK AVENUE
2005	VARICK AVENUE	165 VARICK AVENUE

BI221 **VARICK AVENUE** **NY SHWS** **S105973022**
ESE **165 VARICK AVENUE** **N/A**
1/2-1 **BROOKLYN, NY 10013**
0.685 mi.
3619 ft. **Site 2 of 2 in cluster BI**

Relative:
Lower

Actual:
12 ft.

SHWS:

Program:	HW
Site Code:	55914
Classification:	N
Region:	2
Acres:	3.540
HW Code:	224017
Record Add:	11/18/1999
Record Upd:	04/03/2007
Updated By:	KALEWAND
Site Description:	This property is located in Brooklyn (Block #2962 - lots 1, 5, & 37), and is owned by Rhino Trust (Albert Realty Co.). The site is a vacant lot, except for two, one-story shed buildings in a state of disrepair. The site has a develop- ment history dating back to the early 1900's; site uses have included an asphalt paving company and a lumber company. As a result of an environmental survey of this site conducted in 1988 and 1989, traces of 4-chloroaniline, pentachlorophenol, butyl-ben zylpthalate; di-N-butylphthalate and flouranthene were found. Metals and total petroleum hydrocarbons were also found in the soils, surface and groundwater. Contamination of soils by metals was found to include: silver, barium, cadmium, chromium , iron, lead and copper. Concentrations of metals in the groundwater exceeded groundwater quality standards for lead and iron. Rhino Trust has carried out a supplemental site assessment under a consent order in the summer of 1992. An interpretation of the analytical results from the previous investigation has been inconclusive due to data gaps in the reports. Rhino Trust performed a Supplemental Site Assessment, and the fieldwork was completed in 1994. The PRP has removed the contaminated soils. Hazardous waste is no longer present and significant threat no longer exists.
Env Problem:	Contaminated soils have been removed but groundwater contamination evidently due to construction and demolition debris (non-hazardous), still exists.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MULTIPLE OWNERS
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY

VARICK AVENUE (Continued) **S105973022**

Owner Country: Unknown
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: Rhino Trust
Owner Address: P.O. BOX 637
Owner Addr2: Not reported
Owner City,St,Zip: ASPEN, CO 81612
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: *** MULTIPLE OWNERS ***
Owner Address: P.O. BOX 637
Owner Addr2: Not reported
Owner City,St,Zip: ASPEN, CO 81612
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

---

222 **CHLORAL GROUP** **NY SHWS** **S102637940**
NNE **171 LOMBARDY ST** **NY CBS AST** **N/A**
1/2-1 **BROOKLYN, NY 11222** **NY CBS**
0.712 mi.
3761 ft.

Relative:
Higher

Actual:
53 ft.

SHWS:
Program: HW
Site Code: 486951
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: .460
HW Code: 224182
Record Add: 09/17/2013
Record Upd: 03/02/2015
Updated By: JAMORAS
Site Description: Location:The site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the northeast corner of the intersection of Lombardy Street and Varick Avenue.Site Features:The site is completely covered by two (2) masonry block buildings. Current Zoning and Land Use(s):The site is zoned for manufacturing. The site is currently utilized as a warehouse. Numerous commercial and industrial properties are located to the north, east, and west of the site. A National Grid energy facility is located south of the site across Lombardy Street. The Brooklyn-Queens Expressway (I-278) is located 1 block north of the site. A residential area is located 2 blocks southwest of the site. Newtown Creek is located 4 blocks east of the site.Past Use(s) of the Site:The Department began a Site

CHLORAL GROUP (Continued) **S102637940**

Characterization in this area during the Summer of 2011 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular area was specifically targeted for investigation based on its previous use as a soap and lacquer manufacturer, and on data collected by the Department during investigations conducted at an adjacent site between 2007-2009 (ACME Steel - Brass Foundry) which indicated the presence of an additional source area along Varick Avenue between Anthony and Lombardy Streets. This investigation was conducted in several phases, and was completed in the Spring of 2013.Site Geology and Hydrogeology:The site is underlain by a sand unit (~110' thick) with a discontinuous clayey silt/silty sand unit within the sand unit, and the Raritan formation.Groundwater is approximately 45-50' below ground surface in the vicinity of the site. Groundwater flows north towards Newtown Creek, which lies approximately 1,600' northeast of the site.

Env Problem:	Nature and Extent of Contamination:- GroundwaterThe primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been found in shallow groundwater at concentrations up to 8,400 ppb, and in deep groundwater up to 20,000 ppb, well above the Part 703.5 class GA standard of 5 ppb.- SoilPCE has been found in soil up to 23,000 ppm @ 1-1.5' below grade adjacent to a site-related cesspool, which is well above the soil cleanup objective for unrestricted use (1.3 ppm).Significant Threat:The site poses a significant environmental threat due to the ongoing release of PCE from source areas into soil and groundwater and a significant threat to public health due to the concentrations of PCE detected in groundwater and soil, in conjunction with the proximity of occupied structures.
Health Problem:	Direct contact with contaminants in the soil is unlikely because the site is covered with buildings and pavement. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for soil vapor intrusion to occur in on-site structures should be evaluated. In addition, off-site sampling indicates soil vapor intrusion is a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	9/18/2013 11:54:00 AM
Record Upd:	9/18/2013 11:54:00 AM
Updated By:	DKHARRIN
Own Op:	Owner
Sub Type:	01
Owner Name:	Not reported
Owner Company:	20 Rewe Street Ltd.
Owner Address:	885 Conklin Street

CHLORAL GROUP (Continued) **S102637940**

Owner Addr2:	Not reported
Owner City,St,Zip:	Farmingdale, NY 11735-2400
Owner Country:	United States of America
HW Code:	224182
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

CBS AST:

CBS Number:	2-000036
ICS Number:	2-125127
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	TEMPORARILY OUT-OF-SERVICE
Facility Type:	Not reported
Telephone:	(718) 388-2056
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	04/28/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	KENNETH GOLDSTEIN
Emergency Contact:	FRANK TERRANOUA
Emergency Phone:	(516) 358-9276
Owner Name:	CHLORAL CHEMICAL CORP.
Owner Address:	171 LOMBARDY ST.
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Telephone:	(718) 388-2056
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	CHLORAL CHEMICAL CORP.
Mail Contact Addr:	171 LOMBARDY ST.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	FRANK TERRANOUA
Mail Contact City,St,Zip:	BROOKLYN, NY 11222
Mail Phone:	(718) 388-2056

Tank Id:	00002
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	Not reported
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	400
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	2

CHLORAL GROUP (Continued) **S102637940**

Date Entered:	04/28/1989
Certified Date:	04/28/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Unknown
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	02/12/91
Is It There:	False
Delinquent:	False
Date Expired:	04/28/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	02/12/1991

Tank Id:	00001
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	Not reported
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	400
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	2
Date Entered:	04/28/1989
Certified Date:	04/28/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Unknown
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported

CHLORAL GROUP (Continued) **S102637940**

Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	02/12/91
Is It There:	False
Delinquent:	False
Date Expired:	04/28/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	02/12/1991

CBS:

CBS Number:	2-000036
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	04/28/1991
Dec Region:	2
UTMX:	590028.18240000
UTMY:	4508603.6046700

BJ223 **FORMER SPIC AND SPAN CLEANERS AND DYERS, INC.** **NY RGA HWS** **S114963940**
North **315 KINGSLAND AVENUE** **N/A**
1/2-1 **BROOKLYN, NY**
0.881 mi.
4653 ft. **Site 1 of 2 in cluster BJ**

Relative:
Lower

Actual:
20 ft.

RGA HWS:

2012 FORMER SPIC AND SPAN CLEANERS AND DYERS, INC. 315 KINGSLAND AVENUE
2011 FORMER SPIC AND SPAN CLEANERS AND DYERS, INC. 315 KINGSLAND AVENUE
2010 FORMER SPIC AND SPAN CLEANERS AND DYERS, INC. 315 KINGSLAND AVENUE
2009 FORMER SPIC AND SPAN CLEANERS AND DYERS, INC. 315 KINGSLAND AVENUE

BJ224 **FORMER SPIC AND SPAN CLEANERS** **NY SHWS** **S109416408**
North **315 KINGSLAND AVE** **NY Spills** **N/A**
1/2-1 **BROOKLYN, NY 11222**
0.881 mi.
4653 ft. **Site 2 of 2 in cluster BJ**

Relative:
Lower

Actual:
20 ft.

SHWS:

Program:	HW
Site Code:	405850
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	.510
HW Code:	224129
Record Add:	10/28/2008
Record Upd:	03/02/2015
Updated By:	JAMORAS

FORMER SPIC AND SPAN CLEANERS (Continued) **S109416408**

Site Description: Location:The site is located in the Greenpoint section of Kings County (Borough of Brooklyn, New York City). The site is located on the southwest corner of the intersection of Kingsland and Norman Avenues. Site Features:The site is completely covered by multiple buildings of varying construction and height. Numerous other commercial and industrial properties are located to the north, east, and west of the site. A large residential area is located immediately south of the site, and extends south along both Kingsland Avenue and Monitor Street. A large sewage treatment plan is ~1/2 mile north of the site. Current Zoning/Use(s):The site is zoned for both residential and light manufacturing. The site is partially occupied, and is utilized for a variety of purposes (residential, warehousing, etc.). Historical Use(s):The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was operated by Spic and Span Cleaners and Dyers, Inc. (a.k.a. Eastern District Dye Works) from the early 1900's until the mid-1960's. This investigation was conducted in several phases, and was completed in the Summer of 2009.Site Geology and Hydrogeology:The site is underlain by a fill unit (0.5-10' thick), a stratified sand unit with some to no fines (over 120' thick), a discontinuous glacial till unit within the sand unit (0.5-50' thick), a discontinuous clayey silt unit within the sand unit (0.5-25' thick), and the Raritan Formation (~138.5' below ground surface).Groundwater is approximately 11-25' below ground surface in the vicinity of the site. Groundwater flows north to northeast toward Newtown Creek, which lies approximately 1,300' northeast of the site.

Env Problem: Nature and Extent of Contamination:- GroundwaterThe primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been found in shallow groundwater at concentrations up to 39,000 ppb, and in deep groundwater at concentrations up to 170,000 ppb, well above the Part 703.5 class GA standard of 5 ppb. PCE DNAPL has also been found on-site at concentrations up to 730,000 ppm (73%) in deep monitoring wells. Trichloroethene (up to 5,000 ppb), cis-1,2-dichloroethene (up to 14,000 ppb), and vinyl chloride (up to 3,200 ppb) have also been found in shallow groundwater at concentrations above their respective Part 703.5 class GA standards (5 ppb each).- SoilPCE has been found in soil up to 290,000 ppm, well above the soil cleanup objective for unrestricted use (1.3 ppm).-Soil Vapor and Indoor AirConcentrations of PCE in soil vapor have been found up to 8,200,000 ug/m^3, and in indoor air up to 170 ug/m^3. Concentrations of TCE in soil vapor have been found up to 32,000 ug/m^3, and in indoor air up to 12 ug/m^3.Significant Threat:The site poses a significant environmental threat due to ongoing release of PCE from source areas into soil and groundwater.

Health Problem: Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area anddata evaluated as they become available.

Dump: False
Structure: True
Lagoon: False
Landfill: False

FORMER SPIC AND SPAN CLEANERS (Continued) **S109416408**

Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/28/2008 12:22:00 PM
Record Upd:	9/20/2013 2:09:00 PM
Updated By:	ldennist
Own Op:	Owner
Sub Type:	01
Owner Name:	Not reported
Owner Company:	DELTA PROPERTY ASSOCIATES
Owner Address:	260 NORMAN AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Greenpoint Branch
Owner Address:	107 Norman Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Jean Chau
Owner Company:	DOUBLE STAR REALESTATE, INC.
Owner Address:	307 KINGSLAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	FRANK CHAN
Owner Company:	DOUBLE STAR REALESTATE, INC.
Owner Address:	307 KINGSLAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Sam Gee
Owner Company:	Delta Property Associates
Owner Address:	276 Grand Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10002
Owner Country:	United States of America
HW Code:	224129

FORMER SPIC AND SPAN CLEANERS (Continued) **S109416408**

Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 224132
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:34:00 PM
Record Updated: 10/31/2008 2:34:00 PM
Updated By: MOBARRIE
Crossref ID: 224131
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:34:00 PM
Record Updated: 10/31/2008 2:34:00 PM
Updated By: MOBARRIE
Crossref ID: 224130
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 10/31/2008 2:34:00 PM
Record Updated: 10/31/2008 2:34:00 PM
Updated By: MOBARRIE
Crossref ID: 224121
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 1/30/2009 12:35:00 PM
Record Updated: 1/30/2009 12:35:00 PM
Updated By: JAAVERSA

SPILLS:
Facility ID: 1402556
Facility Type: ER
DER Facility ID: 450762
Site ID: 495884
DEC Region: 2
Spill Date: 6/9/2014
Spill Number/Closed Date: 1402556 / Not Reported
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Investigator: DKHARRIN
Referred To: Not reported
Reported to Dept: 6/9/2014
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 6/9/2014
Spill Record Last Update: 3/31/2015
Spiller Name: SCOTT MCCABE
Spiller Company: FORMER SPIC AND SPAN CLEANERS
Spiller Address: 315 KINGSLAND AVE

FORMER SPIC AND SPAN CLEANERS (Continued) **S109416408**

Spiller City,St,Zip:	BROOKLYN, NY 11222
Spiller Company:	999
Contact Name:	SCOTT MCCABE
Contact Phone:	(716) 430-6405
DEC Memo:	6/9/2014: During investigation work being conducted at a State Superfund site (Former Spic and Span Cleaners, DEC Site ID No. 224129), a UST was discovered beneath the southern portion of a vacant warehouse during pre-clearing activities. DEC PM (Harrington) directed the standby consultant (URS Corporation) to call in a spill for this site. Soils surrounding the tank have been found to contain visual and olfactory evidence of petroleum contamination. (Harrington)6/9/2014: H. Patel (DEC - Region 2) received spill from dispatch. Patel contacted D. Harrington (DEC PM - Central Office) to discuss the case, and subsequently assigned it to him.6/16/2014: URS personel have uncovered a portion of the UST located inside the property (vacant warehouse located at 315 Kingsland Avenue/260 Norman Avenue). Tank appears to be oriented long-way north to south, and is approximately 10’ in length. Tank was approximately 14" below grade. Through a hole in the top of the tank, it was observed to be single-walled steel approximately 1/4" thick, and approximately 4’ in diameter. There appears to be ~6" of an unidentified liquid at the bottom of the tank. Contents smelled like a mixture of weathered petroleum and solvents such as paint thinner or wood stripper. (Harrington)6/17/2014: URS personnel collected a product sample from the UST and submitted it to the lab. Product will be analyzed for VOCs, SVOCs, PCBs, RCRA characteristics, viscosity, surface tension, and specific gravity. (Harrington)11/21/2014: PM requested URS to generate report detailing the findings of investigation surrounding the UST inside the building. Report will include sampling results from soil and product samples, and a tank removal estimate. (Harrington)12/26/2014: PM sent an e-mail to URS Corporation commenting on the draft UST data summary report for the work done inside the vacant building at 315 Kingsland Avenue. Numerous changes need to be made before the report can be finalized. (Harrington)1/24/2015: PM sent an e-mail to URS Corporation approving the revised UST data summary report on 1/9/15. This report was distributed to interested parties (including Community Board 1 and Greenpoint branch of Brooklyn Public Library) on 1/21/15. (Harrington)3/30/2015: PM sent an e-mail to URS Corp. requesting budget estimate for IRM regarding DNAPL recovery and oversight work related to the removal of the UST inside the building (which will be handled separately under response call-out with Island Pump and Tank). (Harrington)
Remarks:	Unknown UST (4’x10’) discovered during test borings and contaminated soil found. DEC Dave Harrington out of Albany Ofc is aware and project manager. Cleanup is pending. Tank still in the ground.

Material:

Site ID:	495884
Operable Unit ID:	1245379
Operable Unit:	01
Material ID:	2246387
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported

FORMER SPIC AND SPAN CLEANERS (Continued) **S109416408**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

225
WNW
1/2-1
0.962 mi.
5079 ft.

Relative:
Lower

Actual:
17 ft.

WYTHE AVE. (BERRY ST.) STATION **EDR MGP** **1008407903**
WYTHE AVE., BERRY ST., N 12TH AND 13TH ST **N/A**
BROOKLYN, NY 11211

Manufactured Gas Plants:
No additional information available

Count: 18 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S110487597	2 INGRAHAM STREET	2 INGRAHAM STREET	11206	NY SHWS, NY VCP, NY BROWNFIEL
BROOKLYN	S113916751	INGRAHAM STREET SIDEWALK PLUME TRA	INGRAHAM STREET	11237	NY SHWS
BROOKLYN	S113917078	NORTH OF CORNISH KNIT GOODS	JOHNSON AVE	11206	NY SHWS
BROOKLYN	S113916586	KENT TERMINAL	KENT AVE. BETWEEN 5TH-11TH ST.	11211	NY SHWS, NY VCP
BROOKLYN	S105972439	JONES MOTORS	LOMBARDY STREET (FOOT OF NEWTO		NY SHWS
BROOKLYN	1003863875	LOMBARDY ST	LOMBARDY ST	11222	CERC-NFRAP
BROOKLYN	1003863619	JONES MOTOR SITE	LOMBARDY ST	11222	CERC-NFRAP
BROOKLYN	S113922158	EQUITY WORKS	MASPETH AND VANDERVORT AVES.	11211	NY VCP
BROOKLYN	S113916693	MEEKER AVENUE PLUME TRACKDOWN	MEEKER AVENUE	11222	NY SHWS
BROOKLYN	1016254028	NYCDOT METROPOLITAN AVE BRG #22402	METROPOLITAN AVE BRG OVER	11211	FINDS
BROOKLYN	1001215447	MTA NYCT - METROPOLITAN AVE STATIO	METROPOLITAN & NASSAU AVE	11222	RCRA NonGen / NLR, NY MANIFEST
BROOKLYN	1016255180	MTA NYCT - METROPOLITAN AVE STATIO	METROPOLITAN & NASSAU AVE	11222	FINDS
BROOKLYN	1007811841	NYC DOT - METROPOLITAN AVE BRIDGE	METROPOLITAN AVE BRIDGE OVER E	11237	FINDS
BROOKLYN	1000791719	NYCDOT METROPOLITAN AVE BRG #22402	METROPOLITAN AVE BRG OVER	11211	RCRA-SQG, NJ MANIFEST, NY MANIFEST
BROOKLYN	S113916666	MORGAN OIL TERMINAL	224038 MORGAN OIL TERMINAL		NY SHWS
BROOKLYN	S113922100	SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY VCP
BROOKLYN	S110487592	K - SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY SHWS, NY BROWNFIELDS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/10/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/16/2015
Date Data Arrived at EDR: 03/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/01/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/16/2015
Date Data Arrived at EDR: 03/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/01/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 13

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 63

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 11/01/2014
Date Data Arrived at EDR: 11/19/2014
Date Made Active in Reports: 01/12/2015
Number of Days to Update: 54

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/22/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/08/2015
Date Data Arrived at EDR: 04/10/2015
Date Made Active in Reports: 04/30/2015
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/21/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 24

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 04/30/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 53

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/03/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 02/12/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 29

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/08/2015
Date Data Arrived at EDR: 01/08/2015
Date Made Active in Reports: 02/09/2015
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/08/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/05/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 48

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/28/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 03/17/2015
Date Data Arrived at EDR: 05/01/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 52

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/26/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 09/30/2014
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 10

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Semi-Annually

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 03/17/2015
Date Data Arrived at EDR: 05/01/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 52

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/26/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/26/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 27

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 09/30/2014
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 10

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 04/30/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 53

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/05/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 48

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/06/2015
Date Data Arrived at EDR: 05/19/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 34

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 12/14/2014
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 28

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/26/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Date Data Arrived at EDR: 11/25/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 65

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/10/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 03/06/2015
Date Data Arrived at EDR: 03/27/2015
Date Made Active in Reports: 04/23/2015
Number of Days to Update: 27
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/19/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/25/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/29/2014
Date Data Arrived at EDR: 10/01/2014
Date Made Active in Reports: 11/06/2014
Number of Days to Update: 36

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/23/2015
Date Data Arrived at EDR: 03/24/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/24/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/23/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39
Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List
A listing of recycling facilities.

Date of Government Version: 04/08/2015
Date Data Arrived at EDR: 04/10/2015
Date Made Active in Reports: 04/30/2015
Number of Days to Update: 20
Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List
A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15
Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 07/15/2015
Next Scheduled EDR Contact: 11/02/2015
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 05/01/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/25/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/20/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/25/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 05/08/2015
Date Data Arrived at EDR: 05/12/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 8

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/08/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Annually

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/21/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated
RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72
Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/05/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62
Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 06/06/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 09/18/2014
Number of Days to Update: 8
Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 46
Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74
Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/12/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/26/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 12/30/2014
Date Data Arrived at EDR: 12/31/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 29

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 06/03/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/12/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 110

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 01/29/2015
Next Scheduled EDR Contact: 06/08/2015
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/25/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/20/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/20/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/10/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 10/15/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 33

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/17/2015
Next Scheduled EDR Contact: 07/27/2015
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/31/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 63

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 06/04/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/07/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 01/18/2015
Date Data Arrived at EDR: 02/27/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 26

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 06/10/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 02/01/2015
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/09/2015
Date Data Arrived at EDR: 03/11/2015
Date Made Active in Reports: 03/20/2015
Number of Days to Update: 9

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 05/01/2015
Date Data Arrived at EDR: 05/06/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/06/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 03/31/2015
Date Data Arrived at EDR: 04/20/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/28/2015
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 05/01/2015
Date Data Arrived at EDR: 05/01/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 06/09/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 04/17/2015
Date Data Arrived at EDR: 04/23/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 03/17/2015
Date Data Arrived at EDR: 03/27/2015
Date Made Active in Reports: 04/23/2015
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/19/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing
The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 04/07/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 05/11/2015
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List
The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Date Data Arrived at EDR: 11/26/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/07/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Quarterly

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: N/A

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/09/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/01/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/01/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/12/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Varies

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 07/13/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Varies

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/16/2014
Date Data Arrived at EDR: 10/31/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 17

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/16/2014
Date Data Arrived at EDR: 10/31/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 17

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/22/2015
Data Release Frequency: Annually

EPA WATCH LIST: EPA WATCH LIST
EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/07/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Quarterly

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 04/08/2015
Date Data Arrived at EDR: 04/10/2015
Date Made Active in Reports: 05/11/2015
Number of Days to Update: 31

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/05/2015
Date Data Arrived at EDR: 06/09/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 10

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/05/2015
Date Data Arrived at EDR: 06/09/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 10

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/01/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/01/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 04/17/2015
Date Data Arrived at EDR: 04/20/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 30

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 04/17/2015
Date Data Arrived at EDR: 04/20/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 30

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 12/11/2014
Date Data Arrived at EDR: 12/12/2014
Date Made Active in Reports: 01/13/2015
Number of Days to Update: 32

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 12/11/2014
Date Data Arrived at EDR: 12/12/2014
Date Made Active in Reports: 01/13/2015
Number of Days to Update: 32

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 04/29/2015
Date Made Active in Reports: 05/29/2015
Number of Days to Update: 30

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/13/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/21/2014
Date Made Active in Reports: 08/25/2014
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/16/2015
Next Scheduled EDR Contact: 08/03/2015
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/26/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 12/22/2014
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 02/27/2015
Number of Days to Update: 21

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/17/2015
Next Scheduled EDR Contact: 08/03/2015
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 03/19/2015
Date Made Active in Reports: 04/07/2015
Number of Days to Update: 19

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/28/2015
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Telephone: 281-546-1505
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
Telephone: 800-823-6277
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.
Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.
Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

824 METROPOLITAN AVE
824 METROPOLITAN AVE
BROOKLYN, NY 11211

TARGET PROPERTY COORDINATES

Latitude (North):	40.7146 - 40° 42' 52.56''
Longitude (West):	73.9411 - 73° 56' 27.96''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589441.3
UTM Y (Meters):	4507403.5
Elevation:	37 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40073-F8 BROOKLYN, NY
Version Date:	1995

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 37 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
KINGS, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 360497 - FEMA DFIRM Flood data

Additional Panels in search area:
- 3604970048B - FEMA Q3 Flood data
- 3604970047B - FEMA Q3 Flood data
- 3604970055B - FEMA Q3 Flood data
- 3604970056B - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000829528	0 - 1/8 Mile West
A2	USGS40000829385	1/4 - 1/2 Mile South
A3	USGS40000829386	1/4 - 1/2 Mile SSW
4	USGS40000829597	1/4 - 1/2 Mile ENE
5	USGS40000829364	1/4 - 1/2 Mile SE
6	USGS40000829291	1/4 - 1/2 Mile South
7	USGS40000829707	1/4 - 1/2 Mile NW
8	USGS40000829320	1/4 - 1/2 Mile SSW
B9	USGS40000829273	1/4 - 1/2 Mile SSE
10	USGS40000829578	1/4 - 1/2 Mile WNW
B11	USGS40000829261	1/4 - 1/2 Mile SSE
C12	USGS40000829262	1/4 - 1/2 Mile SSW
13	USGS40000829655	1/4 - 1/2 Mile ENE
C14	USGS40000829242	1/2 - 1 Mile SSW
15	USGS40000829892	1/2 - 1 Mile North
D16	USGS40000829485	1/2 - 1 Mile West
E17	USGS40000829234	1/2 - 1 Mile SSE
D18	USGS40000829478	1/2 - 1 Mile West
E19	USGS40000829233	1/2 - 1 Mile SSE
20	USGS40000829232	1/2 - 1 Mile SSE
F21	USGS40000829963	1/2 - 1 Mile North
F22	USGS40000829964	1/2 - 1 Mile North
23	USGS40000829247	1/2 - 1 Mile SE
G25	USGS40000829722	1/2 - 1 Mile ENE
G26	USGS40000829706	1/2 - 1 Mile ENE
27	USGS40000829373	1/2 - 1 Mile WSW
28	USGS40000830081	1/2 - 1 Mile NNE
29	USGS40000829263	1/2 - 1 Mile WSW
H30	USGS40000829330	1/2 - 1 Mile ESE
31	USGS40000829116	1/2 - 1 Mile SE
32	USGS40000829283	1/2 - 1 Mile ESE
33	USGS40000829203	1/2 - 1 Mile SW
I34	USGS40000829805	1/2 - 1 Mile WNW
I35	USGS40000829792	1/2 - 1 Mile WNW
36	USGS40000829033	1/2 - 1 Mile SSW
H37	USGS40000829306	1/2 - 1 Mile ESE
J38	USGS40000829052	1/2 - 1 Mile SSE
I39	USGS40000829834	1/2 - 1 Mile WNW
K40	USGS40000829561	1/2 - 1 Mile West
41	USGS40000829806	1/2 - 1 Mile WNW
42	USGS40000829063	1/2 - 1 Mile SSE
J43	USGS40000829031	1/2 - 1 Mile SSE
J44	USGS40000829032	1/2 - 1 Mile SSE
L45	USGS40000829002	1/2 - 1 Mile SSE
L46	USGS40000829003	1/2 - 1 Mile SSE
47	USGS40000830095	1/2 - 1 Mile NE
48	USGS40000829064	1/2 - 1 Mile SSW
K49	USGS40000829572	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
24	NY0007257	1/2 - 1 Mile West

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG70000000029	1/2 - 1 Mile WSW

PHYSICAL SETTING SOURCE MAP - 04357835.2r

County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
Indeterminate Groundwater Flow at Location
Groundwater Flow Varies at Location
Closest Hydrogeological Data
Oil, gas or related wells

N

SITE NAME:	824 Metropolitan Ave	CLIENT:	EnviroBusiness, Inc.
ADDRESS:	824 Metropolitan Ave Brooklyn NY 11211	CONTACT:	Production Manager
		INQUIRY #:	04357835.2r
LAT/LONG:	40.7146 / 73.9411	DATE:	July 17, 2015 2:59 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
West
0 - 1/8 Mile
Higher | **FED USGS** | **USGS40000829528**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404253073563501		
Monloc name:	K 678. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7148247
Longitude:	-73.9426378	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	39.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	221
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

A2
South
1/4 - 1/2 Mile
Higher | **FED USGS** | **USGS40000829385**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404239073563201		
Monloc name:	K 1283. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7109359
Longitude:	-73.9418044	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	45.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	240
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

A3
SSW **FED USGS** **USGS40000829386**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404239073563301		
Monloc name:	K 724. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7109359
Longitude:	-73.9420822	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	48.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	137
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

4
ENE **FED USGS** **USGS40000829597**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404300073561301		
Monloc name:	K 677. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7167691
Longitude:	-73.9365265	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	19.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	215
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

5
SE **FED USGS** **USGS40000829364**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404237073561201		
Monloc name:	K 889. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7103804
Longitude:	-73.9356931	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	21.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	74
Welldepth units:	ft	Wellholedepth:	74
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 265

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-10-01		3.53	1985-05-21		4.48
1984-12-18		4.95	1984-10-05		5.16
1984-06-27		5.47	1984-03-15		5.13
1984-01-05		5.76	1983-09-29		4.96
1983-06-29		4.59	1983-03-25		3.96
1982-12-21		3.69	1982-10-06		3.86
1982-06-30		3.96	1982-04-02		4.19
1981-12-29		4.01	1981-09-23		4.10
1981-06-24		4.28	1981-03-18		5.36
1980-12-30		3.96	1980-09-23		5.06
1980-06-24		5.14	1980-03-13		4.02
1979-12-18		4.92	1979-09-17		4.57
1979-06-28		4.07	1979-03-26		5.46
1978-12-22		5.11	1978-10-02		5.94
1978-06-23		3.93	1978-04-04		4.06
1978-01-03		4.29	1977-09-22		3.81
1977-07-07		3.33	1977-03-29		2.60
1976-12-22		2.81	1976-09-23		3.25
1976-07-09		3.97	1976-06-28		3.21

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1976-03-23		3.02
1975-10-07		3.10
1975-03-26		2.67
1974-09-04		2.44
1974-03-19		2.36
1973-09-24		1.86
1973-04-03		0.97
1972-10-02		1.57
1972-03-28		0.27
1971-09-27		0.57
1970-11-02		1.02
1969-11-12		0.49
1969-04-23		-0.34
1968-04-22		0.46
1967-03-28		-0.64
1966-05-03		-0.64
1965-09-14		-2.21
1964-04-27		-0.19
1963-04-29		-0.13
1962-04-26		-0.54
1961-10-02		-2.45
1960-12-27		-3.44
1960-07-05		-4.23
1960-01-14		-4.97
1959-07-17		-4.44
1958-01-10		-4.06
1957-06-27		-3.61
1956-12-18		-3.19
1956-10-25		-3.01
1956-08-02		-3.00
1956-06-05		-3.05
1956-03-05		-3.53
1955-12-22		-3.74
1955-10-07		-4.61
1955-07-27		-4.72
1955-04-26		-4.91
1955-02-25		-5.33
1954-12-27		-5.61
1954-05-27		-6.72
1954-03-30		-6.87
1954-01-28		-7.19
1953-12-02		-7.25
1953-08-03		-7.45
1953-05-25		-7.91
1953-03-24		-8.82
1953-02-05		-9.37
1952-12-05		-10.54
1952-08-25		-12.22
1952-06-24		-13.11
1952-04-29		-14.33
1952-02-20		-15.88
1951-12-20		-16.98
1951-11-02		-17.86
1951-08-28		-18.53
1951-06-28		-19.39
1975-12-16		3.17
1975-06-30		2.80
1974-12-19		1.99
1974-06-26		2.58
1974-01-09		2.26
1973-07-02		2.22
1972-12-27		1.70
1972-07-10		1.94
1972-01-13		0.44
1971-03-08		1.08
1970-03-13		1.52
1969-09-05		0.24
1968-11-06		-3.34
1967-10-20		-0.01
1966-10-24		-2.53
1965-10-28		-1.85
1964-10-30		-1.79
1963-11-05		-1.31
1962-12-04		-0.88
1961-12-28		-1.92
1961-03-28		-3.06
1960-09-28		-4.38
1960-03-31		-4.56
1959-10-07		-5.06
1959-03-18		-4.96
1957-09-24		-4.44
1957-03-27		-3.58
1956-11-29		-3.09
1956-10-02		-3.06
1956-07-11		-2.95
1956-05-15		-3.26
1956-02-03		-3.69
1955-11-15		-4.04
1955-08-25		-4.74
1955-06-23		-4.43
1955-03-29		-5.07
1955-01-25		-5.34
1954-06-29		-6.25
1954-04-28		-6.79
1954-02-25		-7.02
1953-12-23		-7.15
1953-10-02		-7.61
1953-06-23		-7.47
1953-04-27		-8.26
1953-02-27		-9.10
1952-12-24		-10.14
1952-11-03		-11.13
1952-07-25		-12.62
1952-05-27		-13.84
1952-03-24		-15.09
1952-01-29		-16.33
1951-11-28		-17.37
1951-09-26		-18.29
1951-07-26		-18.97
1951-05-29		-19.79

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1951-05-02		-20.22
1951-02-26		-21.64
1950-12-20		-24.01
1950-10-31		-24.76
1950-08-29		-24.63
1950-06-29		-24.52
1950-04-27		-24.97
1950-03-01		-25.44
1949-12-28		-25.78
1949-10-31		-25.53
1949-08-31		-25.62
1949-06-30		-25.89
1949-04-28		-26.14
1949-02-23		-27.08
1948-12-28		-27.87
1948-11-04		-28.60
1948-08-30		-29.46
1948-06-30		-30.77
1948-04-27		-32.12
1948-03-02		-33.43
1948-01-07		-35.55
1947-11-26		-36.76
1947-10-31		-37.15
1947-10-07		-37.17
1947-09-16		-37.00
1947-08-13		-36.15
1947-07-23		-35.29
1947-07-07		-35.95
1947-07-01		-36.32
1947-06-24		-37.12
1947-06-13		-37.06
1947-05-29		-36.78
1947-05-17		-36.47
1947-05-10		-35.93
1947-04-26		-35.43
1947-04-18		-35.09
1947-03-22		-33.32
1947-03-01		-35.65
1947-02-15		-36.93
1947-02-01		-38.31
1947-01-18		-37.73
1946-10-19		-31.90
1946-10-05		-20.51
1946-09-16		-37.75
1946-08-19		-38.17
1946-07-08		-37.25
1946-05-27		-36.17
1946-05-13		-35.55
1946-04-29		-35.07
1946-04-15		-35.44
1946-04-01		-35.67
1946-03-18		-35.80
1946-03-04		-35.75
1946-02-18		-35.67
1946-01-08		-35.07
1951-03-27		-20.97
1951-01-30		-22.36
1950-11-28		-24.60
1950-09-27		-24.78
1950-07-27		-24.48
1950-06-05		-24.63
1950-03-29		-24.90
1950-01-26		-25.69
1949-11-28		-25.76
1949-09-28		-25.59
1949-07-28		-25.72
1949-06-01		-26.02
1949-04-05		-26.39
1949-01-27		-27.47
1948-12-14		-28.03
1948-10-06		-28.94
1948-07-26		-30.22
1948-06-02		-31.35
1948-03-26		-32.84
1948-02-03		-34.37
1947-12-17		-35.93
1947-11-20		-36.87
1947-10-14		-37.22
1947-09-30		-37.13
1947-08-27		-36.56
1947-07-30		-35.58
1947-07-16		-35.21
1947-07-02		-36.46
1947-06-30		-36.69
1947-06-20		-37.16
1947-06-06		-36.95
1947-05-23		-36.63
1947-05-16		-36.41
1947-05-03		-35.89
1947-04-19		-35.17
1947-03-29		-33.64
1947-03-08		-34.08
1947-02-22		-36.06
1947-02-08		-37.58
1947-01-25		-39.01
1947-01-10		-37.61
1946-10-12		-27.83
1946-09-23		-36.25
1946-08-30		-38.35
1946-07-30		-37.69
1946-06-10		-36.63
1946-05-20		-35.97
1946-05-06		-35.32
1946-04-22		-35.31
1946-04-08		-35.56
1946-03-25		-35.66
1946-03-11		-35.79
1946-02-25		-35.66
1946-02-11		-35.61
1945-12-03		-34.78

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1945-11-06		-34.30	1945-09-28		-33.23
1945-09-12		-32.54	1945-08-08		-30.12
1945-07-23		-30.27	1945-07-03		-30.41
1945-06-04		-30.46			

6
South **FED USGS** **USGS40000829291**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404231073563301		
Monloc name:	K 426. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7087137
Longitude:	-73.9420822	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	38.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	140
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

7
NW **FED USGS** **USGS40000829707**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404307073565101		
Monloc name:	K 690. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7187135
Longitude:	-73.9470823	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	194
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

8
SSW **FED USGS** **USGS40000829320**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404233073564401		
Monloc name:	K 715. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7092693
Longitude:	-73.9451378	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	36.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	120
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

B9
SSE **FED USGS** **USGS40000829273**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404229073562301		
Monloc name:	K 1490. 1		
Monloc type:	Well		
Monloc desc:	2301		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7081582
Longitude:	-73.9393043	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	135
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

10
WNW **FED USGS** **USGS40000829578**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404258073570001		
Monloc name:	K 691. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7162136
Longitude:	-73.9495824	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	195
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

B11
SSE **FED USGS** **USGS40000829261**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404228073562301		
Monloc name:	K 37. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7078804
Longitude:	-73.9393043	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	25.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	130
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

C12
SSW **FED USGS** **USGS40000829262**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404228073563901		
Monloc name:	K 2533. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7078804
Longitude:	-73.9437489	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	30.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	92
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

13
ENE **FED USGS** **USGS40000829655**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404304073560001		
Monloc name:	K 569. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7178802
Longitude:	-73.9329153	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	190
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

C14
SSW **FED USGS** **USGS40000829242**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404226073564101		
Monloc name:	K 637. 1		
Monloc type:	Well		
Monloc desc:	4101		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7073249
Longitude:	-73.9443045	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	212
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

15
North **FED USGS** **USGS40000829892**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321073562801		
Monloc name:	K 679. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7226023
Longitude:	-73.9406933	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	218
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

D16
West **FED USGS** **USGS40000829485**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404249073570801		
Monloc name:	K 673. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7137136
Longitude:	-73.9518047	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	14.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	196
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

E17
SSE **FED USGS** **USGS40000829234**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404225073561301		
Monloc name:	K 1130. 1		
Monloc type:	Well		
Monloc desc:	1301		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7070471
Longitude:	-73.9365265	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	89
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

D18
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000829478**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404248073570901		
Monloc name:	K 898. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7134358
Longitude:	-73.9520825	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	7.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	46
Welldepth units:	ft	Wellholedepth:	74
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

E19
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829233**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404225073561001		
Monloc name:	K 955. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7070471
Longitude:	-73.9356931	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	72
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

20
SSE **FED USGS** **USGS40000829232**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404225073560701		
Monloc name:	K 893. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7070471
Longitude:	-73.9348598	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	118
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

F21
North **FED USGS** **USGS40000829963**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404325073563508		
Monloc name:	K 3260. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7237134
Longitude:	-73.9426378	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	28.7
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	23
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 80

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2000-10-24		12.89	2000-09-27		12.26
2000-08-24		12.89	2000-07-27		13.11
2000-06-28		13.58	2000-05-23		13.47
2000-04-27		13.00	2000-03-22		12.58
2000-02-29		12.01	1999-12-13		12.83
1999-11-23		12.54	1999-10-19		12.73
1999-09-23		12.52	1999-08-17		11.99
1999-07-20		12.49	1999-06-24		12.86
1999-05-18		13.16	1999-04-28		13.32
1999-03-23		12.97	1999-03-02		12.05
1999-01-27		11.50	1998-11-24		11.33
1998-09-29		11.65	1998-09-01		12.13
1998-07-28		12.61	1998-05-28		13.04
1998-04-29		12.48	1998-03-24		12.86
1998-02-26		11.94	1998-01-26		10.65
1997-12-29		11.32	1997-11-26		10.69
1997-10-29		10.78	1997-09-29		11.75
1997-03-24		11.56	1996-07-12		10.24
1995-09-29		10.00	1995-06-22		9.94
1995-01-03		10.61	1994-06-28		10.89
1993-11-22		9.93	1993-08-25		10.16
1993-07-22		10.33	1993-06-22		10.58
1993-05-24		10.71	1993-04-28		11.06
1993-03-26		10.29	1993-01-19		9.89
1992-12-28		9.63	1992-11-20		9.96
1992-10-27		9.50	1992-09-18		9.70
1992-08-24		10.04	1992-07-16		11.74
1992-06-23		9.74	1992-06-15		8.22
1985-10-01		10.36	1985-05-21		10.43
1984-12-28		11.59	1984-10-05		11.26
1984-06-27		11.69	1984-03-15		11.43
1984-01-05		11.29	1983-09-29		10.77
1983-06-29		10.29	1983-03-25		10.29
1982-12-20		10.10	1982-10-06		10.29
1982-07-01		10.38	1982-03-24		10.04
1981-12-30		8.94	1981-09-22		9.59
1981-06-24		9.84	1981-03-18		9.89
1981-02-12		9.83	1980-12-22		10.02
1980-09-23		10.89	1980-06-24		11.27
1980-06-10		11.36	1980-04-11		10.86

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F22
North
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000829964**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404325073563509		
Monloc name:	K 3260. 2		
Monloc type:	Well		
Monloc desc:	MONITOR ST. AND DRIGGS AVE., GREENPOINT		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7237134
Longitude:	-73.9426378	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	29
Vert measure units:	feet	Vertacc measure val:	1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Unconfined single aquifer		
Construction date:	20010716	Welldepth:	42.6
Welldepth units:	ft	Wellholedepth:	45
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 39

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15		10.95	2005-01-21		11.05
2004-12-15		10.95	2004-11-23		10.98
2004-10-21		11.29	2004-09-21		11.21
2004-08-25		11.08	2004-07-19		10.93
2004-06-16		10.97	2004-05-25		11.13
2004-04-29		11.05	2004-02-25		10.87
2003-12-18		11.04	2003-11-25		10.91
2003-10-29		11.09	2003-09-24		11.24
2003-08-25		11.57	2003-07-21		12.54
2003-06-25		11.55	2003-05-19		11.08
2003-04-28		10.70	2003-01-28		10.66
2002-12-27		10.48	2002-11-26		10.28
2002-10-21		10.03	2002-09-25		9.74
2002-08-27		9.53	2002-07-22		9.75
2002-06-18		9.75	2002-05-29		9.71
2002-04-24		9.50	2002-02-27		9.70
2002-01-28		9.71	2001-12-28		9.87
2001-11-15		10.10	2001-10-24		10.26
2001-09-26		10.31	2001-08-29		10.43
2001-07-24		10.66			

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

23
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829247**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404227073560001		
Monloc name:	K 3111. 1		
Monloc type:	Well		
Monloc desc:	0001		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7076027
Longitude:	-73.9329153	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	95
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

24
West
1/2 - 1 Mile
Lower

FRDS PWS **NY0007257**

PWS ID: NY0007257
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: MANSFIELD BUNG COLONY
GALE ROAD, BOX 123
MONGAUP VALLEY, NY 12762

Addressee / Facility: System Owner/Responsible Party
ROSENBERG MAYER
C/O MAYER ROSENBURG
570 BEDFORD AVE
BROOKLYN, NY 11211

Facility Latitude: 40 42 51 Facility Longitude: 073 57 14
City Served: BETHEL (T)
Treatment Class Not Reported Population: Not Reported

Violations information not reported.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G25
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829722**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404308073554701		
Monloc name:	K 1977. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7189913
Longitude:	-73.929304	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	163
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

G26
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829706**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404307073554501		
Monloc name:	K 675. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7187136
Longitude:	-73.9287485	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	13.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	222
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

27
WSW **FED USGS** **USGS40000829373**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404238073571501		
Monloc name:	K 672. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7106581
Longitude:	-73.9537492	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	170
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

28
NNE **FED USGS** **USGS40000830081**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404333073560801		
Monloc name:	K 689. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7259356
Longitude:	-73.9351376	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	31.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	160
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

29
WSW **FED USGS** **USGS40000829263**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404228073571801		
Monloc name:	K 670. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7078804
Longitude:	-73.9545825	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	30.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	165
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

H30
ESE **FED USGS** **USGS40000829330**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404234073553601		
Monloc name:	K 1990. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7095471
Longitude:	-73.9262484	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	70
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

31
SE **FED USGS** **USGS40000829116**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404215073555501		
Monloc name:	K 894. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7042694
Longitude:	-73.9315263	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	30.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	282
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

32
ESE **FED USGS** **USGS40000829283**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404230073553701		
Monloc name:	K 2598. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.708436
Longitude:	-73.9265262	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	7.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

33
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829203**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404223073571601		
Monloc name:	K 717. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7064915
Longitude:	-73.954027	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	45.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	202
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

I34
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829805**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404314073572301		
Monloc name:	K 1112. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7206579
Longitude:	-73.9559715	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	7.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	55
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

I35
WNW **FED USGS** **USGS40000829792**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313073572508		
Monloc name:	K 463. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7203801
Longitude:	-73.956527	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	32
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 106

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1939-11-18		3.22	1939-11-11		3.18
1939-11-04		3.26	1939-10-28		3.28
1939-10-25		3.27	1939-10-18		3.26
1939-10-11		3.39	1939-10-04		3.76
1939-09-23		3.83	1939-09-16		3.77
1939-09-08		3.75	1939-09-01		3.85
1939-08-25		4.13	1939-08-18		4.26
1939-08-11		4.39	1939-08-04		4.52
1939-07-28		4.57	1939-07-21		4.58
1939-07-14		4.59	1939-07-07		4.59
1939-06-30		4.56	1939-06-23		4.58
1939-06-16		4.60	1939-06-09		4.61
1939-06-02		4.58	1939-05-26		4.60
1939-05-19		4.61	1939-05-12		4.62
1939-05-05		4.62	1939-04-28		4.63
1939-04-21		4.64	1939-04-15		4.64
1939-04-08		4.67	1939-03-31		4.72
1939-03-24		4.70	1939-03-17		4.69
1939-03-10		4.73	1939-03-03		4.76

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1939-02-24		4.72	1939-02-17		4.73
1939-02-10		4.74	1939-02-03		4.76
1939-01-27		4.78	1939-01-20		4.81
1939-01-13		4.83	1939-01-06		4.85
1938-12-30		4.88	1938-12-23		4.91
1938-12-16		4.91	1938-12-09		4.94
1938-12-02		4.95	1938-11-25		5.03
1938-11-18		5.01	1938-11-11		5.04
1938-11-04		5.09	1938-10-28		5.20
1938-10-21		5.30	1938-10-14		5.97
1938-10-07		5.19	1938-09-30		5.24
1938-09-23		5.27	1938-09-16		4.91
1938-09-09		4.41	1938-09-02		4.41
1938-08-26		4.42	1938-08-19		4.42
1938-08-12		4.40	1938-08-05		4.41
1938-07-29		4.41	1938-07-22		4.40
1938-07-15		4.41	1938-07-08		4.40
1938-07-01		4.42	1938-06-25		4.42
1938-06-18		4.43	1938-06-11		4.43
1938-06-04		4.46	1938-05-28		4.48
1938-05-21		4.60	1938-05-14		4.78
1938-05-07		4.79	1938-04-30		4.81
1938-04-23		4.87	1938-04-16		4.88
1938-04-09		5.12	1938-04-02		5.05
1938-03-26		4.65	1938-03-19		4.63
1938-03-12		4.63	1938-03-05		4.66
1938-02-26		4.67	1938-02-19		4.68
1938-02-04		4.72	1938-01-28		4.72
1938-01-21		4.74	1938-01-14		4.77
1938-01-07		4.81	1937-12-31		4.81
1937-12-24		4.86	1937-12-18		4.88
1937-12-11		4.87	1937-12-04		4.80
1937-11-27		4.76	1937-11-20		4.73
1937-11-13		4.40	1937-11-08		4.40

36
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829033**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404206073564601		
Monloc name:	K 3483. 1		
Monloc type:	Well		
Monloc desc:	Throop Ave and Bartleet St, Tompkins Park North		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7017694
Longitude:	-73.9456934	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	16
Vert measure units:	feet	Vertacc measure val:	1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Unconfined single aquifer		
Construction date:	20001018	Welldepth:	45.6
Welldepth units:	ft	Wellholedepth:	45.6
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

H37
ESE **FED USGS** **USGS40000829306**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404232073553201		
Monloc name:	K 1346. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7089915
Longitude:	-73.9251373	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	39.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	168
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

J38
SSE **FED USGS** **USGS40000829052**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404208073560201		
Monloc name:	K 36. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.702325
Longitude:	-73.9334708	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	115
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

I39
WNW **FED USGS** **USGS40000829834**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404317073572501		
Monloc name:	K 49. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7214912
Longitude:	-73.956527	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	333
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

K40
West **FED USGS** **USGS40000829561**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404256073573401		
Monloc name:	K 1303. 1		
Monloc type:	Well		
Monloc desc:	3401		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.715658
Longitude:	-73.9590271	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	16.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	90
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

41
WNW **FED USGS** **USGS40000829806**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404314073572801		
Monloc name:	K 50. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7206579
Longitude:	-73.9573604	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	16.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	157
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

42
SSE **FED USGS** **USGS40000829063**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404209073555701		
Monloc name:	K 87. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7026028
Longitude:	-73.9320819	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	160
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 184

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1941-05-31		-9.41	1941-05-24		-9.39
1941-05-17		-9.36	1941-05-10		-9.36
1941-05-03		-9.32	1941-04-26		-9.30
1941-04-19		-9.27	1941-04-12		-9.27
1941-04-05		-9.25	1941-03-29		-9.25
1941-03-22		-9.24	1941-03-15		-9.24
1941-03-08		-9.22	1941-03-01		-9.22
1941-02-22		-9.22	1941-02-15		-9.22
1941-02-08		-9.22	1941-02-01		-9.23
1941-01-25		-9.23	1941-01-18		-9.24
1941-01-11		-9.24	1941-01-04		-9.26
1940-12-28		-9.25	1940-12-21		-9.24
1940-12-14		-9.20	1940-12-07		-9.19
1940-11-30		-9.16	1940-11-23		-9.13
1940-11-16		-9.13	1940-11-09		-9.10
1940-11-02		-9.05	1940-10-26		-9.03
1940-10-19		-8.98	1940-10-12		-8.92
1940-10-05		-8.91	1940-09-28		-8.88
1940-09-21		-8.82	1940-09-14		-8.74
1940-09-07		-8.67	1940-08-31		-8.51
1940-08-24		-8.55	1940-08-17		-8.44
1940-08-10		-8.50	1940-08-03		-8.34
1940-07-20		-8.86	1940-07-13		-8.70
1940-07-06		-8.72	1940-06-29		-7.98
1940-06-22		-8.45	1940-06-15		-8.10
1940-06-08		-7.91	1940-06-01		-7.83
1940-05-25		-7.79	1940-05-18		-7.78
1940-05-11		-7.77	1940-05-04		-7.75
1940-04-27		-7.73	1940-04-20		-7.72
1940-04-13		-7.69	1940-04-06		-7.60
1940-03-30		-7.69	1940-03-23		-7.71
1940-03-16		-7.69	1940-03-09		-7.71
1940-03-02		-7.68	1940-02-24		-7.71
1940-02-17		-7.69	1940-02-10		-8.44
1940-02-03		-8.47	1940-01-27		-8.37
1940-01-20		-8.43	1940-01-13		-8.51
1940-01-06		-8.73	1939-12-30		-8.58
1939-12-23		-8.73	1939-12-16		-8.77
1939-12-09		-8.56	1939-12-02		-8.70
1939-11-25		-8.92	1939-11-18		-9.02
1939-11-11		-8.91	1939-11-04		-8.93

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1939-10-28		-8.98
1939-10-14		-8.98
1939-09-30		-8.87
1939-09-16		-7.92
1939-09-01		-7.82
1939-08-18		-7.70
1939-08-04		-7.60
1939-07-07		-7.33
1939-06-23		-7.33
1939-06-09		-7.38
1939-05-26		-7.41
1939-05-12		-7.48
1939-04-28		-7.48
1939-04-15		-7.50
1939-03-31		-7.61
1939-03-17		-7.69
1939-03-03		-7.92
1939-02-17		-7.72
1939-02-03		-7.79
1939-01-20		-7.86
1939-01-06		-7.93
1938-12-23		-8.00
1938-12-09		-8.07
1938-11-25		-8.13
1938-11-11		-8.16
1938-10-28		-8.22
1938-10-14		-8.27
1938-09-30		-8.33
1938-09-16		-8.38
1938-09-02		-8.34
1938-08-19		-8.26
1938-08-05		-8.18
1938-07-22		-8.08
1938-07-08		-8.00
1938-06-25		-7.93
1938-06-11		-7.83
1938-05-28		-7.77
1938-05-14		-7.74
1938-04-30		-7.72
1938-04-16		-7.68
1938-04-02		-7.67
1938-03-19		-7.69
1938-03-05		-7.73
1938-02-19		-7.79
1938-02-04		-7.84
1938-01-21		-7.91
1938-01-07		-7.99
1937-12-24		-8.04
1937-12-11		-8.13
1937-11-27		-8.18
1937-11-13		-8.23
1939-10-21		-8.92
1939-10-07		-8.82
1939-09-23		-7.99
1939-09-08		-7.87
1939-08-25		-7.76
1939-08-11		-7.63
1939-07-28		-7.53
1939-06-30		-7.33
1939-06-16		-7.36
1939-06-02		-7.39
1939-05-19		-7.45
1939-05-05		-7.46
1939-04-21		-7.48
1939-04-08		-7.52
1939-03-24		-7.69
1939-03-10		-7.63
1939-02-24		-7.70
1939-02-10		-7.74
1939-01-27		-7.85
1939-01-13		-7.89
1938-12-30		-7.95
1938-12-16		-8.03
1938-12-02		-8.13
1938-11-18		-8.17
1938-11-04		-8.21
1938-10-21		-8.24
1938-10-07		-8.29
1938-09-23		-8.36
1938-09-09		-8.36
1938-08-26		-8.28
1938-08-12		-8.22
1938-07-29		-8.13
1938-07-15		-8.08
1938-07-01		-7.96
1938-06-18		-7.86
1938-06-04		-7.82
1938-05-21		-7.76
1938-05-07		-7.74
1938-04-23		-7.71
1938-04-09		-7.66
1938-03-26		-7.67
1938-03-12		-7.71
1938-02-26		-7.76
1938-02-12		-7.83
1938-01-28		-7.89
1938-01-14		-7.93
1937-12-31		-8.02
1937-12-18		-8.06
1937-12-04		-8.13
1937-11-20		-8.23
1937-11-08		-8.25

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J43
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829031**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404206073560501		
Monloc name:	K 1153. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7017694
Longitude:	-73.9343042	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	42.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	103
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

J44
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829032**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404206073560503		
Monloc name:	K 1273. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7017694
Longitude:	-73.9343042	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	275
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

L45
SSE **FED USGS** **USGS40000829002**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404204073561001		
Monloc name:	K 2136. 1		
Monloc type:	Well		
Monloc desc:	1001		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7012139
Longitude:	-73.9356931	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	112
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

L46
SSE **FED USGS** **USGS40000829003**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404204073561008		
Monloc name:	K 236. 1		
Monloc type:	Well		
Monloc desc:	1008		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7012139
Longitude:	-73.9356931	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	130
Welldepth units:	ft	Wellholedepth:	130
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 52

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1954-12-17		-8.30	1954-06-29		-9.31
1954-05-27		-8.45	1954-04-28		-10.08
1954-03-30		-9.85	1954-02-25		-9.49
1954-01-28		-10.11	1953-12-23		-10.76
1953-12-02		-10.78	1953-10-28		-10.03
1953-10-02		-11.58	1953-08-28		-11.23
1953-08-03		-11.25	1953-06-24		-10.48
1953-05-25		-10.59	1953-04-27		-11.85
1953-03-24		-12.38	1953-02-27		-12.18
1953-02-05		-12.68	1952-12-24		-12.74
1952-12-05		-12.60	1952-11-03		-13.70
1952-09-23		-16.95	1952-08-25		-16.73
1952-07-23		-17.79	1952-06-24		-17.05
1952-05-27		-17.69	1952-04-29		-19.03
1952-03-24		-19.20	1952-02-20		-20.10
1952-01-29		-20.88	1951-12-20		-22.55
1951-11-28		-22.59	1951-09-26		-24.85
1951-08-28		-25.66	1951-07-26		-25.95
1951-06-28		-25.47	1951-05-29		-26.24
1951-05-02		-26.53	1951-03-27		-26.63
1951-02-26		-26.78	1951-01-30		-27.90
1950-12-20		-28.49	1950-11-28		-28.00
1950-10-31		-27.98	1950-09-27		-29.66
1950-08-29		-29.53	1950-07-27		-29.04
1950-06-29		-27.59	1950-06-05		-26.28
1950-04-27		-28.80	1950-03-29		-28.80

47
NE
1/2 - 1 Mile
Lower

FED USGS **USGS40000830095**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404334073555201		
Monloc name:	K 1560. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7262134
Longitude:	-73.930693	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	30.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	101
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

48
SSW **FED USGS** **USGS40000829064**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404209073570601		
Monloc name:	K 29. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7026027
Longitude:	-73.9512491	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	78
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 66

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1939-03-24		-24.57	1939-03-12		-24.72
1939-03-10		-24.62	1939-03-03		-24.59
1939-02-24		-24.54	1939-02-17		-24.52
1939-02-10		-24.50	1939-02-03		-24.54
1939-01-27		-24.80	1939-01-20		-24.78
1939-01-13		-24.68	1939-01-06		-24.70
1938-12-30		-24.76	1938-12-23		-24.88
1938-12-16		-24.94	1938-12-02		-25.00
1938-11-25		-24.97	1938-11-18		-24.89
1938-11-11		-24.69	1938-11-04		-24.89
1938-10-28		-24.88	1938-10-21		-24.85
1938-10-14		-24.85	1938-10-07		-24.77
1938-09-30		-24.67	1938-09-16		-25.10
1938-09-09		-24.94	1938-09-02		-24.96
1938-08-26		-24.86	1938-08-19		-24.93
1938-08-12		-24.89	1938-08-05		-24.83
1938-07-22		-24.84	1938-07-15		-24.79
1938-07-08		-24.61	1938-07-01		-24.63
1938-06-11		-24.41	1938-06-04		-24.43

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1938-05-28		-24.40	1938-05-21		-24.46
1938-05-07		-24.34	1938-04-30		-24.37
1938-04-23		-24.43	1938-04-16		-24.47
1938-04-09		-23.90	1938-03-26		-24.07
1938-03-19		-24.32	1938-03-12		-24.18
1938-03-05		-24.09	1938-02-26		-24.48
1938-02-19		-24.59	1938-02-12		-24.44
1938-02-04		-24.76	1938-01-28		-24.88
1938-01-21		-24.73	1938-01-14		-24.82
1938-01-07		-24.65	1937-12-31		-24.78
1937-12-24		-24.75	1937-12-18		-24.63
1937-12-11		-24.90	1937-12-04		-24.89
1937-11-27		-24.89	1937-11-20		-24.88
1937-11-13		-24.63	1937-11-08		-24.81

K49
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000829572**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404257073573701		
Monloc name:	K 2262. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7159358
Longitude:	-73.9598605	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	8.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	61
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
WSW **OIL_GAS** **NYOG70000000029**
1/2 - 1 Mile

Api wellno:	31061236030000	Cnty:	New York
Hole:	23603	Sidetrck:	0
Completion:	0		
Well nm:	MPP - 5		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	28-JAN-05	Dt spud:	28-MAR-01
Dt comp:	18-JAN-01	Well typ:	Stratigraphic
Dtd:	645		
Wl status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.95824		
Yloc:	40.70885		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Jersey City	Quadsec:	C
Deepestfor:	None Specified	Elevation:	19
Dt mod:	26-APR-06	Site id:	NYOG70000000029

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

This Report contains certain products owned by or licensed by Tele Atlas North America, Inc. ("TANA") and licensed to EDR pursuant to an agreement between EDR and TANA (the "TANA Agreement"). Such products include the Dynamap® /2000 (commencing with the most current version, nationwide coverage, ArcInfo™ format, tiled by county, with semi−annual Updates) and are referred to in this Report as the "Licensed Products".

The use of the Licensed Products with a non−TANA map may result in increased variance between the location displayed on the map and ground truth location.

The recipient of the Report (hereinafter referred to as an "End User") shall use such Report solely for its internal purposes and not for resale.

U.S. GOVERNMENT RIGHTS. If End User is an agency, department, or other entity of the United States Government, or funded in whole or in part by the United States Government, then use, duplication, reproduction, release, modification, disclosure or transfer of this commercial product and accompanying documentation, is restricted in accordance with the LIMITED or RESTRICTED rights as described in DFARS 252.227−7014(a)(1) (JUN 1995) (DOD commercial computer software definition), DFARS 227.7202−1 (DOD policy on commercial computer software), FAR 52.227−19 (JUN 1987) (commercial computer software clause for civilian agencies), DFARS 252.227−7015 (NOV 1995) (DOD technical data − commercial items clause); FAR 52.227−14 Alternates I, II, and III (JUN 1987) (civilian agency technical data and noncommercial computer software clause); and/or FAR 12.211 and FAR 12.212 (commercial item acquisitions), as applicable. In case of conflict between any of the FAR and DFARS provisions listed herein, the construction that provides greater limitations on the Government's rights shall control. Contractor/manufacturer is Tele Atlas North America, Inc., 11 Lafayette Street, Lebanon, NH 03766−1445. Phone: 603.643. 0330. The Licensed Products are ©1984−2008 by Tele Atlas North America, Inc. ALL RIGHTS RESERVED. For purpose of any public disclosure provision under any federal, state or local law, it is agreed that the Licensed Products are a trade secret and a proprietary commercial product and not subject to disclosure.

If End User is an agency, department, or other entity of any State government, the United States Government or any other public entity or funded in whole or in part by the United States Government, such End User agrees to protect the Licensed Products from public disclosure and to consider the Licensed Products exempt from any statute, law, regulation, or code, including any Sunshine Act, Public Records Act, Freedom of Information Act, or equivalent, which permits public access and/or reproduction or use of the Licensed Products. In the event that such exemption is challenged under any such laws, any and all right to retain any copies or to use of the Licensed Products shall be terminated and considered immediately null and void. Any copies of the Licensed Products held by End User shall immediately be destroyed. If any court of competent jurisdiction considers this clause void and unenforceable, in whole or in part, for any reason, then all Licensed Products previously delivered to End User will be destroyed.

APPENDIX F

HISTORICAL DOCUMENTATION

DRAFT

Aerial Photograph

Year: 1924



Aerial Photograph

Year: 1941



Aerial Photograph

Year: 1951

Aerial Photograph

Year: 1954

Aerial Photograph

Year: 1961

Aerial Photograph

Year: 1966

Aerial Photograph

Year: 1974

Aerial Photograph

Year: 1980

Aerial Photograph

Year: 1984

Aerial Photograph

Year: 1991

Aerial Photograph

Year: 1994

Aerial Photograph

Year: 2006

Aerial Photograph

Year: 2009

Aerial Photograph

Year: 2011



Historic Fire Insurance Map

Year: 1888



Historic Fire Insurance Map

Year: 1907



Historic Fire Insurance Map

Year: 1933



Historic Fire Insurance Map

Year: 1951



Historic Fire Insurance Map

Year: 1965



Historic Fire Insurance Map

Year: 1968



Historic Fire Insurance Map

Year: 1977



Historic Fire Insurance Map

Year: 1979



Historic Fire Insurance Map

Year: 1980



Historic Fire Insurance Map

Year: 1986



Historic Fire Insurance Map

Year: 1990



Historic Fire Insurance Map

Year: 1995



Historic Fire Insurance Map

Year: 2001



Historic Fire Insurance Map

Year: 2004



Historic Fire Insurance Map

Year: 2007



Historic USGS Topographic Map

Year: 1900



Historic USGS Topographic Map

Year: 1924



Historic USGS Topographic Map

Year: 1947



Historic USGS Topographic Map

Year: 1956



Historic USGS Topographic Map

Year: 1967



Historic USGS Topographic Map

Year: 1979



Historic USGS Topographic Map

Year: 1995

824 Metropolitan Ave
824 Metropolitan Ave
Brooklyn, NY 11211

Inquiry Number: 4357835.6
July 17, 2015

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2013. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 100 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2013	Cole Information Services	-	-	-	-
2008	Cole Information Services	-	X	X	-
2005	Hill-Donnelly Corporation	-	X	X	-
2000	Cole Information Services	-	X	X	-
1997	NYNEX	-	X	X	-
1992	NYNEX Informantion Resource Co.	-	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	X	X	-
1976	New York Telephone	-	X	X	-
1973	New York Telephone	-	X	X	-
1970	New York Telephone	-	X	X	-
1965	New York Telephone	-	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone Company	-	X	X	-
1949	New York Telephone Company	-	X	X	-
1945	New York Telephone	-	X	X	-
1940	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
1928	New York Telephone	-	X	X	-

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

824 Metropolitan Ave
Brooklyn, NY 11211

FINDINGS DETAIL

Target Property research detail.

METROPOLITAN AVE

824 METROPOLITAN AVE

Year	*Uses*	*Source*
1940	Bry Julius candy mfr	New York Telephone

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

METROPOLITAN AVE

820 METROPOLITAN AVE

Year	Uses	Source
1960	GANNON LILLIAN MRS	New York Telephone
	RENNI M A	New York Telephone
	FATTORE ERMINIO	New York Telephone
	BRIGGS RUTH MRS	New York Telephone
	Fattore Erminio	New York Telephone Company
	Briggs Ruth Mrs	New York Telephone Company
	Gannon Lillian Mrs	New York Telephone Company
	Renni M A	New York Telephone Company

822 METROPOLITAN AVE

Year	Uses	Source
1970	Daniel Motors	New York Telephone
1960	ZAMMINER AUGUST GROCR	New York Telephone
	ZWICK PETER	New York Telephone
	Zwick Peter	New York Telephone Company
	Zamminer August grocr	New York Telephone Company
1940	Ruoff Eugene E	New York Telephone
1928	RUOFF EUGENE E R	New York Telephone

826 METROPOLITAN AVE

Year	Uses	Source
1960	DORAN PATK	New York Telephone
	Doran Patk	New York Telephone Company

832 METROPOLITAN AVE

Year	Uses	Source
2008	RACHEL WELLS	Cole Information Services
2005	1 Castronovo H	Hill-Donnelly Corporation
	h Spiro Paula	Hill-Donnelly Corporation
	h Wells Rachel	Hill-Donnelly Corporation
2000	PETER DECURTIS	Cole Information Services
	P H SPIRO	Cole Information Services

FINDINGS

Year	Uses	Source
2000	CSTRNV HOME MNTNC	Cole Information Services
1997	Castronovo Home Maintenance	NYNEX
	SPIRO P H M	NYNEX
	WANG Doris	NYNEX
1992	SPIRO P H M	NYNEX Informantion Resource Co.
	WANG DORIS	NYNEX Informantion Resource Co.
1985	CASTRONOVO GASPARE	NYNEX Information Resources Company
	CASTRONOVO HOME MAINTENANCE	NYNEX Information Resources Company
	HOROWITZ S	NYNEX Information Resources Company
1976	FRIEDMAN L	New York Telephone
1973	Valentine G	New York Telephone
1970	Mannetta Vincent	New York Telephone
1960	CURCIO PAT	New York Telephone
	Curcio Pat	New York Telephone Company
1934	CAFFREY EDW CHAUF H	R. L. Polk & Co.
	CAFFREY EDW JR SLSMN R	R. L. Polk & Co.

834 METROPOLITAN AVE

Year	Uses	Source
2005	h Chase Edmund M AV	Hill-Donnelly Corporation
2000	APARTMENTS	Cole Information Services
	1 ANTONIO F CALISE	Cole Information Services
	EDMUND M CHASE	Cole Information Services
1997	CALISE Antonio F	NYNEX
	CHASE Edmund M	NYNEX
1992	CALISE ANTONIO F	NYNEX Informantion Resource Co.
	CHASE EDMUND M	NYNEX Informantion Resource Co.
	GREANEY K A	NYNEX Informantion Resource Co.
1985	CALISE ANTONIO F	NYNEX Information Resources Company
	CHASE EDMUND M	NYNEX Information Resources Company
	GREANEY K A	NYNEX Information Resources Company
1976	CALISE ANTONIO F	New York Telephone
	CHASE EDMUND M	New York Telephone
1973	Calise Antonio F	New York Telephone
	Chase Edmund M	New York Telephone
1970	Calise Antonio F	New York Telephone
	Chase Edmund M	New York Telephone
1965	Calise Antonio F	New York Telephone
	Chase Edmund M	New York Telephone

FINDINGS

Year	Uses	Source
1960	CALISE ANTONIO F	New York Telephone
	CHASE EDMUND M	New York Telephone
	Calise Antonio F	New York Telephone Company
	Chase Edmund M	New York Telephone Company

853 METROPOLITAN AVE

Year	Uses	Source
1976	CELESTE ROSARIO	New York Telephone

METROPOLITIAN AVE

828 METROPOLITIAN AVE

Year	Uses	Source
1928	NASSAU HTS HDWRE CO	New York Telephone

834 METROPOLITIAN AVE

Year	Uses	Source
1928	CHASE ALEXANDER A R	New York Telephone

ORIENT

15 ORIENT

Year	Uses	Source
1934	KEANE EDW L MECH H	R. L. Polk & Co.

ORIENT AVE

10 ORIENT AVE

Year	Uses	Source
2005	h Guiliano Ronald v	Hill-Donnelly Corporation
	h Santiago M	Hill-Donnelly Corporation
2000	MARYVEL SANTIAGO	Cole Information Services
	APARTMENTS	Cole Information Services
	2 RONALD GUILIANO	Cole Information Services
1997	GUILIANO Ronald	NYNEX
1992	GUILIANO RONALD	NYNEX Informantion Resource Co.
	RODRIGUEZ CHERYL A	NYNEX Informantion Resource Co.
1973	Brucato Al	New York Telephone
1970	Brucato Al	New York Telephone
1965	Cicio Anthony Sr	New York Telephone

FINDINGS

Year	Uses	Source
1960	NEWMAN HUGH	New York Telephone
	Alcuri Salvatore	New York Telephone Company
	Newman Hugh	New York Telephone Company
1949	Hinderman Harriet	New York Telephone Company
	Newman Hugh	New York Telephone Company
1945	Hinderman Harriet	New York Telephone
	Newman Hugh	New York Telephone
1940	Hinderman Harriet	New York Telephone
	NEWMAN See also Neuman	New York Telephone
	Newman Hugh	New York Telephone
1934	HARRISON MICHL F H	R. L. Polk & Co.
	HINDERMAN FRANK CHAUF H	R. L. Polk & Co.
	HINDERMAN HUGH CLK R	R. L. Polk & Co.
	HINDERMAN JOS LAB R	R. L. Polk & Co.
	NEWMAN HUGH D CARP H	R. L. Polk & Co.

11 ORIENT AVE

Year	Uses	Source
2005	No Current Listing	Hill-Donnelly Corporation
2000	JAMES F GARDINI	Cole Information Services
	J MC GINNIS	Cole Information Services
1992	MC GINNIS J	NYNEX Informantion Resource Co.
1976	GARDINI GIACOMO	New York Telephone
	LARAIA VINCENT J	New York Telephone
	ZUCCHELLI MARY	New York Telephone
1973	Gardini Giacomo	New York Telephone
	Laraia Vincent J	New York Telephone
	Zucchelli Mary	New York Telephone
1970	Catania Chas C	New York Telephone
	Gardini Giacomo	New York Telephone
	Zucchelli Mary	New York Telephone
1965	Catania Chas C	New York Telephone
	Gardini Giacomo	New York Telephone
	Zucchelli Mary	New York Telephone
1960	CATANIA CHAS C	New York Telephone
	GARDINI GIACOMO	New York Telephone
	ZUCCHELLI MARY	New York Telephone
	Catania Chas C	New York Telephone Company
	Gardini Giacomo	New York Telephone Company

FINDINGS

Year	Uses	Source
1960	Zucchelli Mary	New York Telephone Company
1949	Gardini Lena Mrs	New York Telephone Company
1945	Gardini Lena Mrs	New York Telephone
1940	Napolitano Dominick	New York Telephone
1934	ALBERTI JOS LAB H	R. L. Polk & Co.
	MARTINO ATTILLO PRSMN H	R. L. Polk & Co.
	SCHERALLI MICHL ICE DLR H	R. L. Polk & Co.

12 ORIENT AVE

Year	Uses	Source
2005	Schwarz Kurt	Hill-Donnelly Corporation
2000	S ANLLO	Cole Information Services
	CHRIS BICKNELL	Cole Information Services
	KURT SCHWARZ	Cole Information Services
1997	BAADE Jeff	NYNEX
	GRIBBLE Glenn	NYNEX
1992	CHAKO GREGORY & SUSSY	NYNEX Informantion Resource Co.
	TODA KIYOKO	NYNEX Informantion Resource Co.
1980	RUBINO MARY A	New York Telephone
1976	RUBINO MARY A	New York Telephone
1973	Macellaro L	New York Telephone
	Rubino Mary A	New York Telephone
1970	Macellaro L	New York Telephone
	Rubino Mary A	New York Telephone
1965	Macellaro Pat L	New York Telephone
	Rubino Mary A	New York Telephone
1960	RUBINO MARY A	New York Telephone
	WARGO GEO	New York Telephone
	Rubino Mary A	New York Telephone Company
	Wargo Geo	New York Telephone Company
1949	Rubino Mars A	New York Telephone Company
1945	Rubino Marv A	New York Telephone
1940	Rubino Mary A	New York Telephone
1934	MADIA ANTHONY LAB H	R. L. Polk & Co.
	MADIA ROSE R	R. L. Polk & Co.

13 ORIENT AVE

Year	Uses	Source
2005	Pinkney Wanda o	Hill-Donnelly Corporation

FINDINGS

Year	Uses	Source
2000	NOEL BILLIG	Cole Information Services
1997	NEGIN Carl	NYNEX
1992	VIGLIONE M	NYNEX Informantion Resource Co.
1985	HABERKERN M	NYNEX Information Resources Company
1976	VIGLIONE M	New York Telephone
	TUBELLO A	New York Telephone
1973	Garone Jennifer Mrs	New York Telephone
	Viglione M	New York Telephone
1970	Garone Jennifer Mrs	New York Telephone
	Viglione M	New York Telephone
1965	Viglione Vincent	New York Telephone
1960	VIGLIONE CHAS J	New York Telephone
	VIGLIONE VINCENT	New York Telephone
	Viglione Chas J	New York Telephone Company
	Viglione Vincent	New York Telephone Company
1934	HARTMANN FLORENCE PKR R	R. L. Polk & Co.
	HARTMANN FREDK LONGSHOREMN H	R. L. Polk & Co.
	HARTMANN FREDK JR HLPR R	R. L. Polk & Co.
	MCBRIDE JOSEPHINE R	R. L. Polk & Co.
	MCBRIDE WALTER R	R. L. Polk & Co.
	SEIVERS ERNEST PLSHR R	R. L. Polk & Co.
	SEIVER WM BKBNDR R	R. L. Polk & Co.
	SIEVERS JOHANNA MRS H	R. L. Polk & Co.

15 ORIENT AVE

Year	Uses	Source
2005	Marsh M	Hill-Donnelly Corporation
	1 Byme Gerard & Maureen	Hill-Donnelly Corporation
2000	GERARD BYRNE	Cole Information Services
	M MARSH	Cole Information Services
1992	GATTO JOSEPHINE	NYNEX Informantion Resource Co.
1985	GATTO JOSEPHINE	NYNEX Information Resources Company
1976	GATTO JOSEPHINE	New York Telephone
1970	De Marsico M	New York Telephone
1965	Caputo Ann Mrs	New York Telephone
	Meagher Matthew T	New York Telephone
1960	MEAGHER MATTHEW T	New York Telephone
	Caputo Ann Mrs	New York Telephone Company
	Meagher Matthew T	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Caputo Ann Mrs	New York Telephone Company
1940	Cabble Frances M Mrs	New York Telephone

16 ORIENT AVE

Year	Uses	Source
2005	n Rocco Robert	Hill-Donnelly Corporation
2000	ROCCO ROBT	Cole Information Services
1997	Rocco Robt	NYNEX
1992	ROCCO ROBT	NYNEX Informantion Resource Co.
1985	ROCCO ROBT	NYNEX Information Resources Company
1980	ROCCO R	New York Telephone
	ROCCO ROBT TUNRL DLR	New York Telephone
1976	ROCCO ROBT FUNRL DIR	New York Telephone
	ROCCO ROSALITA	New York Telephone
1973	Rocco Rosalitz	New York Telephone
1970	Res	New York Telephone
	Rocco Robt tunrl dir	New York Telephone
1965	Res	New York Telephone
	Rocco Robt funrl dir	New York Telephone
1960	ROCCO ROBT FUNRL DIR	New York Telephone
	Res	New York Telephone Company
	Rocco Robt funrl dir	New York Telephone Company
1934	ROCCO ROBT H	R. L. Polk & Co.

17 ORIENT AVE

Year	Uses	Source
1973	US Gauge Div Of Ametek Inc	New York Telephone
1970	US Gauge Div of Ametek Inc	New York Telephone

3 ORIENT AVE

Year	Uses	Source
2005	h Carreiras Raul	Hill-Donnelly Corporation
2000	PAUL W CARREIRAS	Cole Information Services
	RAUL CARREIRAS	Cole Information Services
1992	CARREIRAS RAUL	NYNEX Informantion Resource Co.
1985	CARREIRAS RAUL	NYNEX Information Resources Company
	CARREIRAS RAUL	NYNEX Information Resources Company
1976	CARREIRAS RAUL	New York Telephone
	CARREIRAS RAUL	New York Telephone

FINDINGS

Year	Uses	Source
1973	Carreiras Raul	New York Telephone
	Carreiras Raul	New York Telephone
1970	Carreiras Raul	New York Telephone
	Carreiras Raul	New York Telephone
1965	Prtti Jos	New York Telephone
	Petti Jas E	New York Telephone
1960	Petti Jas	New York Telephone Company
1949	Tizzano Anthony oil brnr & electrcl reprs	New York Telephone Company
1934	BUONAGURA AMELLO H	R. L. Polk & Co.
	BUONAGURA FRANK R	R. L. Polk & Co.
	BUONAGURA LUCO R	R. L. Polk & Co.
	BUONAGURA SANTO R	R. L. Polk & Co.
	MILLER MARGT BLPR GREENPOINT HOSP R	R. L. Polk & Co.

8 ORIENT AVE

Year	Uses	Source
2005	HLeto SAV	Hill-Donnelly Corporation
	H FOX Lou & Cynthia	Hill-Donnelly Corporation
2000	JOSEPH ZERBO	Cole Information Services
	MICHAEL LETO	Cole Information Services
	GERALD HANSEN	Cole Information Services
1992	SCHATZ ALFRED J	NYNEX Informantion Resource Co.
	LETO MICHAEL	NYNEX Informantion Resource Co.
	LETO MICHAEL	NYNEX Informantion Resource Co.
1985	LETO MICHAEL	NYNEX Information Resources Company
	LANG IRENE & RAYMOND	NYNEX Information Resources Company
1976	MALAGNINI GRAZIA	New York Telephone
	CAROPOLO J	New York Telephone
1973	Malagnini Grazia	New York Telephone
	Kost Henry	New York Telephone
1970	Accardi L	New York Telephone
1965	Grasso Michl S	New York Telephone
1960	VACCARO ROBT	New York Telephone
	Vaccaro Robt	New York Telephone Company
1949	Celentano Nettie maseus	New York Telephone Company
	Capitelli Ignatius	New York Telephone Company
1934	KRUPP ARTH CLK H	R. L. Polk & Co.
	EVANS JOHN L R	R. L. Polk & Co.

FINDINGS

ORIENT WAY

13 ORIENT WAY

Year	*Uses*	*Source*
1976	KELEKET C G R CORP	New York Telephone

ORLENT AVE

15 ORLENT AVE

Year	*Uses*	*Source*
1960	CAPUTO ANN MRS	New York Telephone
1934	MEAGHER WM FERTILLZER H	R. L. Polk & Co.

3 ORLENT AVE

Year	*Uses*	*Source*
1960	PETTI JAS	New York Telephone

ORRENT AVE

8 ORRENT AVE

Year	*Uses*	*Source*
1980	LETO MICHAEL	New York Telephone

FINDINGS

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
824 Metropolitan Ave	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
10 ORIENT AVE	2013, 2008, 1985, 1980, 1976, 1928
11 ORIENT AVE	2013, 2008, 1997, 1985, 1980, 1928
12 ORIENT AVE	2013, 2008, 1985, 1928
13 ORIENT AVE	2013, 2008, 1980, 1949, 1945, 1940, 1928
13 ORIENT WAY	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 ORIENT	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
15 ORIENT AVE	2013, 2008, 1997, 1980, 1973, 1945, 1934, 1928
15 ORLENT AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
16 ORIENT AVE	2013, 2008, 1949, 1945, 1940, 1928
17 ORIENT AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 ORIENT AVE	2013, 2008, 1997, 1980, 1945, 1940, 1928
3 ORLENT AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
8 ORIENT AVE	2013, 2008, 1997, 1980, 1945, 1940, 1928
8 ORRENT AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
820 METROPOLITAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
822 METROPOLITAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1965, 1949, 1945, 1934
826 METROPOLITAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
828 METROPOLITIAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
832 METROPOLITAN AVE	2013, 2008, 1980, 1965, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
832 METROPOLITAN AVE	2013, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
834 METROPOLITAN AVE	2013, 2008, 1980, 1949, 1945, 1940, 1934, 1928
834 METROPOLITIAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
853 METROPOLITAN AVE	2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

APPENDIX G

TERMINOLOGY

DRAFT

TERMINOLOGY

The following provides definitions and descriptions of certain terms that may be used in this report. Italics indicate terms that are defined by ASTM Standard Practice E 1527-13. The Standard Practice should be referenced for further detail related definitions or additional explanation regarding the meaning of terms.

Recognized environmental condition (REC): The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: 1) due to any release to the environment, 2) under conditions indicative of a release to the environment; or 3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions.

De minimis conditions: Conditions that generally do not present threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions or controlled recognized conditions.

Historical recognized environmental condition(s) (HREC): A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted residential use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). Before calling the past release a historical recognized environmental condition, the environmental professional must determine whether the past release is a recognized environmental condition at the time of the Phase I Environmental Site Assessment is conducted (for example, if there has been a change in the regulatory criteria). If the EP considers the past release to be a recognized environmental condition at the time of the Phase I ESA, the condition shall be included in the conclusions section of the report as a recognized environmental condition,

Controlled recognized environmental condition(s) (CREC): A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by the regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). A condition considered by the environmental professional to be a controlled recognized condition shall be listed in the findings section of the Phase I Environmental Site Assessment report, and as a recognized environmental condition in the conclusions section of the Phase I Environmental Site Assessment report. NOTE: A condition identified as a controlled recognized environmental condition does not imply that the environmental professional has evaluated or confirmed the adequacy, implementation, or continued effectiveness of the required control that has been, or is intended to be, implemented.

Material threat: A physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment. An example might include an aboveground storage tank that contains a hazardous substance and which shows evidence of damage such that it may cause or contribute to tank integrity failure with a release of contents to the environment.

Material impact to public health or environment: A substantial risk of harm to public health or the environment resulting from the presence or likely presence of an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property. An example might include a release of a hazardous substance in concentrations exceeding applicable governmental agency standards under conditions that could reasonably and foreseeably result in substantial exposure to humans or

DRAFT

substantial damage to natural resources. The risk of that exposure or damage would represent a material impact to public health or environment.

General risk of enforcement action: The likelihood that an environmental condition would be subject to enforcement action if brought to the attention of appropriate governmental agencies. If the circumstances suggest an enforcement action would be more likely than not, then the condition is considered a general risk of enforcement action.

Data failure: A failure to achieve the historical research objectives, even after reviewing the standard historical sources that are reasonably ascertainable and likely to be useful. Data failure is one type of data gap.

Data gap: A lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.).

DRAFT