Sanborn Fire Insurance Maps City Directory Search and
Toxic's Targeting Report



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1896

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 174
Volume 8N, Sheet 173
Volume 8N, Sheet 173
Volume 8N, Sheet 174

0 Feet 150 300 600

N

Certified Sanborn® Map

1911



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1911

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 74
Volume 8N, Sheet 81
Volume 8N, Sheet 72
Volume 8N, Sheet 79

0 Feet 150 300 600

N

Certified Sanborn® Map

1939



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1939

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1951



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 74
Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1968



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1968

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 74
Volume 8N, Sheet 79
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1969



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1979



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 74
Volume 8N, Sheet 72
Volume 8N, Sheet 81
Volume 8N, Sheet 79

0 Feet 150 300 600

N

Certified Sanborn® Map

1980



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

EDR

Certified Sanborn® Map

1982


MADISON
AVENUE
PARK
AVENUE
EAST
STREET
119TH
118TH
117TH
120TH
121ST
79
1745
1746
1747
1748
1745
1745
1745

Certified Sanborn® Map

1986



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72
Volume 8N, Sheet 81

0 Feet 150 300 600

N

Certified Sanborn® Map

1989



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1991



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1992



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #C1E8-4F8D-9A63

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1993



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

1994



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #C1E8-4F8D-9A63

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 74
Volume 8N, Sheet 72
Volume 8N, Sheet 79

0 Feet 150 300 600

N

Certified Sanborn® Map

1995



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #C1E8-4F8D-9A63

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 72
Volume 8N, Sheet 74

0 Feet 150 300 600

N

Certified Sanborn® Map

1996



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #C1E8-4F8D-9A63

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

2001



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #C1E8-4F8D-9A63

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

2002



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

2003



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright 2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

Certified Sanborn® Map

2004



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 74
Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 72

0 Feet 150 300 600

N

EDR

Certified Sanborn® Map

2005



Site Name: 1678 and 1700 Park Avenue
Address: 1678 and 1700 Park Avenue
City, ST, ZIP: New York, NY 10035
Client: AKRF, Inc.
EDR Inquiry: 4631025.1
Order Date: 05/26/2016
Certification #: C1E8-4F8D-9A63
Copyright: 2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8N, Sheet 81
Volume 8N, Sheet 79
Volume 8N, Sheet 74
Volume 8N, Sheet 72

0 Feet 150 300 600

N

1678 and 1700 Park Avenue
1678 and 1700 Park Avenue
New York, NY 10035

Inquiry Number: 4631025.3
May 27, 2016

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1920 through 2013. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 100 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2013	Cole Information Services	-	X	X	-
2008	Cole Information Services	-	X	X	-
2006	Hill-Donnelly Information Services	-	X	X	-
	Hill-Donnelly Information Services	X	X	X	-
1998	NYNEX Telephone	-	-	-	-
1996	NYNEX	-	-	-	-
1993	NYNEX Telephone	-	-	-	-
1973	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1963	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1958	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1956	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1950	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1942	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1938	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1931	Manhattan and Bronx Directory Publishing Company Residential Directory	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1931	Manhattan and Bronx Directory Publishing Company Residential Directory	X	X	X	-
1927	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1923	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1920	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
1678 Park Avenue	Client Entered	
1700 Park Avenue	Client Entered	X
1680 Park Avenue	Client Entered	X
1682 Park Avenue	Client Entered	X
1684 Park Avenue	Client Entered	X
1686 Park Avenue	Client Entered	X
1688 Park Avenue	Client Entered	X
1690 Park Avenue	Client Entered	X

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

1678 and 1700 Park Avenue
New York, NY 10035

FINDINGS DETAIL

Target Property research detail.

PARK AVE

1700 PARK AVE

Year	*Uses*	*Source*
2000	P EVERS	Cole Information Services
1988	EVERS P	NYNEX Telephone
	SHERR A I	NYNEX Telephone
1983	EVERS P	New York Telephone
	Matt P	New York Telephone
1978	TCHOLAKIAN KEGHAM	New York Telephone
1973	AYBAR MEAT MARKET	New York Telephone
	LOEB E	New York Telephone
1968	AYBAR MEAT MARKET	New York Telephone
1963	RAMIREZ CARLOS GROCRS	New York Telephone
1958	RAMIREZ CARLOS GROCRS	New York Telephone
1956	VALENTIN ANGEL GROCRY	New York Telephone
1950	RAMIREZ CARLOS GROCR	New York Telephone
1947	RAMIREZ CARLOS GROCR	New York Telephone
1938	HYGRADE BKNDG CO	New York Telephone
1934	Branches	R. L. Polk & Co.
	Hy Grade Bookbinding Co RTN Hyman Proskowitz	R. L. Polk & Co.
	Midinian Bros Carl and Harry gros	R. L. Polk & Co.
1927	Hygrade Bookbinding Co	New York Telephone
	PERISSI K MRS R	New York Telephone
1923	Chain Butter & Egg Co RTN Louis Rosenbaum	R. L. Polk & Co.
	Goldstein Max laundry	R. L. Polk & Co.
	Rosenbaum Louis Chain Butter & Egg Co	R. L. Polk & Co.

FINDINGS

Park Avenue

1678 Park Avenue

Year	*Uses*	*Source*

1680 Park Avenue

Year	*Uses*	*Source*
1973	SISH-AMER CROCRY	New York Telephone
1968	GONZALEZ SEBASTIAN GROCR	New York Telephone
	MARTINEZ GRCCRY	New York Telephone
1963	MARTINEZ GROCRY	New York Telephone
	SPANISH AMER GROCRY	New York Telephone
1958	GONZALEZ SEBASTIAN GROCR	New York Telephone
1934	Kupper Benj Rose gro	R. L. Polk & Co.
	Rodriguez G Milian & Rodriguez	R. L. Polk & Co.
1931	BURKE ANTHONY	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Quat Ephron	New York Telephone
	Rock Spring Dairies branch	New York Telephone
	Rosedale Dairy Co	New York Telephone
1923	Quat Arnold sec Rosedale Dairy Co	R. L. Polk & Co.
	Quat Ephron pres Rosedale Dairy Co	R. L. Polk & Co.
	Rosedale Dairy Co NY Ephron Quat pres Arnold Quat sec	R. L. Polk & Co.
1920	Rosedale Dairy Co Inc NY Ephron Quat pres Arnold Quat sec treas	R. L. Polk & Co.

1682 Park Avenue

Year	*Uses*	*Source*
1968	ORTIZ TOMAS	New York Telephone
	RIOUS M L	New York Telephone
1963	CLEMENTE ANGEL C	New York Telephone
	GADSDEN ROSE MRS	New York Telephone
	MERCADO AMILCA	New York Telephone
1958	DUEN S STATNRY	New York Telephone
	RAMOS JOSE	New York Telephone
	ROSA GRACILLANO	New York Telephone
1956	BORINQUEN GLASS CO	New York Telephone
	BRISBON MALISSA	New York Telephone
	FARRAW JOHNNIE	New York Telephone

FINDINGS

Year	Uses	Source
1956	FIGUEROA ELBA	New York Telephone
1947	GOSPEL TEMPLE INC	New York Telephone
1942	PRICE D TNSMTH	New York Telephone
1938	PRICE D TINSMITH	New York Telephone
1934	Price Bernard tinsmith Danl Price	R. L. Polk & Co.
	Price Dan1 Bertha tinsmith	R. L. Polk & Co.
1931	BROWN ELLEN	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Boyle Robt J r	New York Telephone
	PREISS D SODA FNTN RPRNG	New York Telephone
	PRICE D SODA FNTN RPRNG	New York Telephone
1923	Fishberg Max pntr	R. L. Polk & Co.
	Herbene Pharmacal Co RTN Hy S Wechsler	R. L. Polk & Co.
	Midoser Paul electn	R. L. Polk & Co.
	Wechsler Hy S Herbene Pharmacal Co	R. L. Polk & Co.
1920	Denanny Owen	R. L. Polk & Co.
	Gehn A S awnings	R. L. Polk & Co.
	Mioduser P elec contr	R. L. Polk & Co.
	Ralph Edw G prsmn The World	R. L. Polk & Co.
	Ralph Ella M clk P R R h Newark NJ	R. L. Polk & Co.
	Standard Awning Co RTN Saml Gelin Louis Weinberg	R. L. Polk & Co.
	Weinberg Louis Standard Awning Co	R. L. Polk & Co.
	Weinberg Louis Weinberg & Adelmann h Mt Vernon NY	R. L. Polk & Co.
	Yaeger Israel tailor	R. L. Polk & Co.
	Yeager Nathan	R. L. Polk & Co.

1684 Park Avenue

Year	Uses	Source
1973	JOHNSON EDITH	New York Telephone
	PARRIS GREGORY	New York Telephone
	THURMAN R	New York Telephone
1968	BROWN ANNIE	New York Telephone
	JOHNSON JOHNNIE	New York Telephone
	SUTTON W B	New York Telephone
1963	FOWLER ALBERTHA	New York Telephone
	GLOVER SARAH	New York Telephone
1958	FOWLER ALBERTHA	New York Telephone
	JACKSON JAS E	New York Telephone

FINDINGS

Year	Uses	Source
1958	TROPICANA APTS INC	New York Telephone
1956	FOWLER ALBERTHA	New York Telephone
	GREER HATTIE MRS	New York Telephone
	HILL JAS L	New York Telephone
	JACKSON DORINDA MRS	New York Telephone
	TROPICANA APTS INC	New York Telephone
	WYNN AMAUDA MRS	New York Telephone
1950	LEWIS PHILLIP	New York Telephone
1934	Cusumano Tony Mary barber	R. L. Polk & Co.
1931	FRACCIOLA DOMINICK	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hill Almira	Manhattan and Bronx Directory Publishing Company Residential Directory
	HILL FRANK	Manhattan and Bronx Directory Publishing Company Residential Directory
	Layman Martha	Manhattan and Bronx Directory Publishing Company Residential Directory
	MURRAY GEO	Manhattan and Bronx Directory Publishing Company Residential Directory
	Quinlan Geo	Manhattan and Bronx Directory Publishing Company Residential Directory
	RALPH EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ralph Geo	Manhattan and Bronx Directory Publishing Company Residential Directory
	ROACHE JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	Stynbeck Millard F	Manhattan and Bronx Directory Publishing Company Residential Directory
	Williamson George	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Fleischmann M & Son candy	New York Telephone
1920	Goebel Geo J	R. L. Polk & Co.
	Grimes Edw driver	R. L. Polk & Co.
	Higgins Hugh	R. L. Polk & Co.
	Lotill Jos	R. L. Polk & Co.
	Roache Jno	R. L. Polk & Co.
	Sottile Vincenzo barber	R. L. Polk & Co.

1686 Park Avenue

Year	Uses	Source
2006	1687 1689 No Current Listing	Hill-Donnelly Information Services
1973	MILLS ANNA M MRS	New York Telephone

FINDINGS

Year	Uses	Source
1973	NEUILDER PATRICIA	New York Telephone
	RICHARDSON VIVIAN	New York Telephone
1968	MILLS ANNA M MRS	New York Telephone
	WELLS NEOLA	New York Telephone
1963	LEVINE RUTH MRS	New York Telephone
	SHARPERSON B	New York Telephone
1958	ALLBRIGHT CLIFFORD	New York Telephone
	ATKINS MERCEDIA MISS	New York Telephone
	CRAWFORD ETHEL L	New York Telephone
	JACKSON OLLIE	New York Telephone
	LEVINE RUTH MRS	New York Telephone
	MCCLEVERTY CARL	New York Telephone
	PATRICK MATTHEW	New York Telephone
1956	ALLBRIGHT CLIFFORD	New York Telephone
	CRAWFORD ETHEL L	New York Telephone
	GIBBS ROSEMOND	New York Telephone
	JOHNSON MARY A MRS	New York Telephone
	KEISLER DRAFTS MRS	New York Telephone
	LEWIS BARBARA MRS	New York Telephone
	LEWIS JAS A	New York Telephone
	THOMAS GRACE L MRS	New York Telephone
	WATSON MAXINE MRS	New York Telephone
1950	BARBER MARION E	New York Telephone
	BROWN CLEO MRS	New York Telephone
	CRAWFORD OSCAR L	New York Telephone
	FREEMAN MARY MRS BTY PLR	New York Telephone
	LOVEHEART MARY	New York Telephone
1947	FREEMAN MARY MRS BTY PLR	New York Telephone
1938	RENU RANGE & SUPL CO	New York Telephone
	SAMUELS J B	New York Telephone
1931	BURKE BRIDGET	Manhattan and Bronx Directory Publishing Company Residential Directory
	CALLAGHAN MARGT	Manhattan and Bronx Directory Publishing Company Residential Directory
	Callaghan Wm	Manhattan and Bronx Directory Publishing Company Residential Directory
	CARLOS EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	Carlos Nora	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	FEINK ANDREW	Manhattan and Bronx Directory Publishing Company Residential Directory
	Feink Nora	Manhattan and Bronx Directory Publishing Company Residential Directory
	Higgins Clara	Manhattan and Bronx Directory Publishing Company Residential Directory
	HIGGINS HUGH	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Gray Virginia A Miss r	New York Telephone
1923	Radigan Path	R. L. Polk & Co.
1920	Carlon Edw	R. L. Polk & Co.
	Levy Isaac B	R. L. Polk & Co.

1688 Park Avenue

Year	Uses	Source
1963	AUSTIN DAISY MRS	New York Telephone
1958	CREWS BEAUTY PARLOR	New York Telephone
	ISOM LUE HAZEL	New York Telephone
	RAMOS RALPH	New York Telephone
1956	AUSTIN DAISY MRS	New York Telephone
	CREW S BEAUTY PARLOR	New York Telephone
	RODRIGUEZ ESTEBAN	New York Telephone
	ROWELL LORENZO	New York Telephone
1950	CREWS BEAUTY PARLOR	New York Telephone
	ROWELL LORENZO	New York Telephone
	WARD FRANK REV	New York Telephone
1947	COZART PAULINEE MRS STATNRY	New York Telephone
1942	LITTLE C MRS STATNRY	New York Telephone
1938	SWAGEL S STATNRY	New York Telephone
1934	Blumer Rose Mrs confr	R. L. Polk & Co.
1931	BIVONA ROSE	Manhattan and Bronx Directory Publishing Company Residential Directory
	Blumstein Harry	Manhattan and Bronx Directory Publishing Company Residential Directory
	BLUMSTEIN LILLIAN	Manhattan and Bronx Directory Publishing Company Residential Directory
	Daly Catharine	Manhattan and Bronx Directory Publishing Company Residential Directory
	FEMI THERESA	Manhattan and Bronx Directory Publishing Company Residential Directory
	Jarvis Sam	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	MORAN JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	REYNOLDS ANNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	Reynolds Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	SEXTON PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Beakes Geo W	New York Telephone
	FLAGLER FARMS BUTTER & EGGS	New York Telephone
	Janowitz I butter & eggs	New York Telephone
	WOLIN S CONFECTNY	New York Telephone
1923	Harlem Cider Co Inc NY Rose Wohn pres	R. L. Polk & Co.
1920	Callaghan Wm	R. L. Polk & Co.
	Gray Wm eng	R. L. Polk & Co.
	Reynolds Jas	R. L. Polk & Co.
	Schauffler Wm	R. L. Polk & Co.
	Wolin Saul stationer	R. L. Polk & Co.

1690 Park Avenue

Year	Uses	Source
1963	ARNETT JAS R	New York Telephone
	MARTINEZ ANNIE MRS	New York Telephone
	MCDANIEL THOS	New York Telephone
	MILLS ANNA M MRS	New York Telephone
	ROBERTS CLAUDIA	New York Telephone
	THOMAS WM	New York Telephone
1958	MILLS ANNA M MRS	New York Telephone
	REID DWIGHT	New York Telephone
	ROBERTS CLAUDIA	New York Telephone
	TENNYSON RUBY	New York Telephone
	WALKER DOROTHY C	New York Telephone
1956	CLEVELAND VERA L	New York Telephone
	MILLS ANNA M MRS	New York Telephone
	MONTANO LOUIS	New York Telephone
	REID WM	New York Telephone
	ROBERTS CLAUDIA	New York Telephone
	WALLACE W RESTRNT	New York Telephone
1950	GREEN ARTHUR L	New York Telephone
	MILLER IDA MRS	New York Telephone

FINDINGS

Year	Uses	Source
1950	REID WM	New York Telephone
	TENNYSON RUBY	New York Telephone
	WHITNEY CLEANERS	New York Telephone
1947	CORAM REYES RUPERT TLR	New York Telephone
1942	RETTNER M B RITY MNTNCE	New York Telephone
1934	Wiesemann Chas baker	R. L. Polk & Co.
1931	Angelfried Agnes	Manhattan and Bronx Directory Publishing Company Residential Directory
	ENGELFRIED CHAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	Levy Harry	Manhattan and Bronx Directory Publishing Company Residential Directory
	LEVY REBECCA	Manhattan and Bronx Directory Publishing Company Residential Directory
	Lynch Michl	Manhattan and Bronx Directory Publishing Company Residential Directory
	LYNCH MINNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	O BRIEN PETER	Manhattan and Bronx Directory Publishing Company Residential Directory
	OATES MABEL	Manhattan and Bronx Directory Publishing Company Residential Directory
	OBrien Peter	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	COESTER JESS UNDERTKR	New York Telephone
1920	Clark Michl lab	R. L. Polk & Co.
	DeHaan Michl	R. L. Polk & Co.
	McDonough Jos br mgr Jas Butler Inc	R. L. Polk & Co.
	OConnor Wm waiter	R. L. Polk & Co.
	Stoll Chas J	R. L. Polk & Co.

1700 Park Avenue

Year	Uses	Source
2000	P EVERS	Cole Information Services
1988	EVERS P	NYNEX Telephone
	SHERR A I	NYNEX Telephone
1983	EVERS P	New York Telephone
	Matt P	New York Telephone
1978	TCHOLAKIAN KEGHAM	New York Telephone
1973	AYBAR MEAT MARKET	New York Telephone
	LOEB E	New York Telephone
1968	AYBAR MEAT MARKET	New York Telephone

FINDINGS

Year	Uses	Source
1963	RAMIREZ CARLOS GROCRS	New York Telephone
1958	RAMIREZ CARLOS GROCRS	New York Telephone
1956	VALENTIN ANGEL GROCRY	New York Telephone
1950	RAMIREZ CARLOS GROCR	New York Telephone
1947	RAMIREZ CARLOS GROCR	New York Telephone
1938	HYGRADE BKNDG CO	New York Telephone
1934	Branches	R. L. Polk & Co.
	Hy Grade Bookbinding Co RTN Hyman Proskowitz	R. L. Polk & Co.
	Midinian Bros Carl and Harry gros	R. L. Polk & Co.
1927	HYGRADE BOOKBINDING CO	New York Telephone
	PERISSI K MRS R	New York Telephone
1923	Chain Butter & Egg Co RTN Louis Rosenbaum	R. L. Polk & Co.
	Goldstein Max laundry	R. L. Polk & Co.
	Rosenbaum Louis Chain Butter & Egg Co	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

E 119 ST

80 E 119 ST

Year	Uses	Source
1963	SMIKTE AUBREY R	New York Telephone
1958	CARONIA ANTONINO	New York Telephone
1950	BUTLER HAROLD A	New York Telephone

91 E 119 ST

Year	Uses	Source
1931	BURAK BETTY	Manhattan and Bronx Directory Publishing Company Residential Directory

E 119 ST N

79 E 119 ST N

Year	Uses	Source
1958	REED ROBT L	New York Telephone

E 119TH

82 E 119TH

Year	Uses	Source
1920	Haberman Bessie pres Harlem Homo of the Daugthers of Israel	R. L. Polk & Co.

91 E 119TH

Year	Uses	Source
1931	Burak Betty	Manhattan and Bronx Directory Publishing Company Residential Directory

PARK AVE

1694 PARK AVE

Year	Uses	Source
2013	SOUTH ON PARK DELI	Cole Information Services
	0 0 0 & 0 24 HOUR EMERGENCY PLUM	Cole Information Services

FINDINGS

Year	Uses	Source
2013	GOURMET DELI & GRILL	Cole Information Services
2008	CHARDY DELI & GROCERY INC	Cole Information Services
2006	Ezatm Merchant Svc 2 F	Hill-Donnelly Information Services
	Chardy Deli Grocery 7s	Hill-Donnelly Information Services
	24 Hour A Day Towing 15s	Hill-Donnelly Information Services
1963	BEN S GROCRY STORE	New York Telephone
1958	RODRIGUEZ DOMINIGO GROCRS	New York Telephone
1956	ROMAN C GROCRS	New York Telephone
	MAYAGUESANA FOOD MKT	New York Telephone
1950	SALAS EIISEO B	New York Telephone
1938	LINKS ADOLPH STOVS	New York Telephone
1934	Jomax Coatracting Co Inc cap $5 000 Jos Gill pres bild contrs	R. L. Polk & Co.
1927	MARKOVITS JOS INC ARTFCL FLWRS	New York Telephone
	CARDO DRUG CO	New York Telephone
	Markovits Jos Inc artfcl flwrs	New York Telephone
	Cardo Drug Co	New York Telephone
1923	Finkler Rubin Inc NY	R. L. Polk & Co.
1920	Otein Co RTN Morris W Monsky	R. L. Polk & Co.
	Monsky Morris W Oteen Co	R. L. Polk & Co.
	Cardo Drug Co NY Abr Rose pres Max Goodman v p Morris Kassin sec treas	R. L. Polk & Co.

1696 PARK AVE

Year	Uses	Source
1973	EVANS REGINALD	New York Telephone

1702 PARK AVE

Year	Uses	Source
1942	PUGH KAYSER	New York Telephone
	PURCELL EDWIN B	New York Telephone
	SEXTON JAS J PLMBR	New York Telephone
1938	SEXTON JAS J PLUMBER	New York Telephone
1931	CAIFFREY ANGIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAFFREY THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	JARRETT FRANK	Manhattan and Bronx Directory Publishing Company Residential Directory
	LEVY MORTIMER	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	MARNELL WM	Manhattan and Bronx Directory Publishing Company Residential Directory
	Caiffrey Angie	Manhattan and Bronx Directory Publishing Company Residential Directory
	Caffrey Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Jarrett Frank	Manhattan and Bronx Directory Publishing Company Residential Directory
	Levy Mortimer	Manhattan and Bronx Directory Publishing Company Residential Directory
	Marnell Wm	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Gisonda J r	New York Telephone
	GISONDA J R	New York Telephone
1920	Allen Jno solr	R. L. Polk & Co.
	Boss Wm	R. L. Polk & Co.
	Caffrey Thos	R. L. Polk & Co.
	Dempsey Wm	R. L. Polk & Co.
	Jarrett Frank M carrier PO	R. L. Polk & Co.
	Pike Chas W corp	R. L. Polk & Co.
	Rosenstein Chas laundry	R. L. Polk & Co.
	Stewart Robt chauf	R. L. Polk & Co.
	Wertzel Jas	R. L. Polk & Co.

FINDINGS

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
1678 and 1700 Park Avenue	2013, 2008, 1998, 1996, 1993

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1694 PARK AVE	2013, 2008, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1947, 1942, 1931
1694 PARK AVE	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
1696 PARK AVE	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
1702 PARK AVE	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1934, 1923
79 E 119 ST N	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
80 E 119 ST	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1956, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
82 E 119TH	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
91 E 119 ST	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923, 1920
91 E 119TH	2013, 2008, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923, 1920

APPENDIX D

REGULATORY RECORDS REVIEW

TOXICS TARGETING

Phase I
Environmental Database Report

1678 and 1700 Park Avenue
New York, NY 10035

May 31, 2016

Privileged and Confidential.

LIMITED WARRANTY AND DISCLAIMER OF LIABILITY

Who is Covered

This limited warranty is extended by Toxics Targeting, Inc. only to the original purchaser of the accompanying Environmental Report ("Report"). It may not be assigned to any other person.

What is Warranted

Toxics Targeting, Inc. warrants that it uses reasonable care to accurately transcribe the information contained in this Report from the sources from which it is obtained. This limited warranty is in lieu of all other express warranties which might otherwise arise with respect to the Report. No one is authorized to change or add to this limited warranty.

What We Will Do

If during the warranty period there is shown to be a material error in the transcription of the information contained in this Report from the sources from which it was obtained, Toxics Targeting, Inc. shall refund to the original purchaser the full purchase price paid for the Report. The remedy stated above is the exclusive remedy extended to the Purchaser by Toxics Targeting, Inc. for any failure of the Report to conform with this Warranty, or otherwise for breach of this Warranty or any other warranty, whether expressed or implied.

What We Won't Cover

Toxics Targeting, Inc. has not and can not verify the accuracy, correctness or completion of the information contained in this Report. Information is obtained from government agencies, site owners, and other sources, and errors are common in such information. Because Toxics Targeting, Inc. can not control the accuracy of the information contained in this Report, or the uses which may be made of the information, TOXICS TARGETING, INC. DISCLAIMS LIABILITY TO ANYONE FOR ANY EVENTS ARISING OUT OF THE USE OF THE INFORMATION. TOXICS TARGETING, INC. SHALL NOT BE LIABLE FOR ANY DAMAGE CAUSED BY THIS REPORT, WHETHER DIRECT OR INDIRECT, AND WHETHER OR NOT TOXICS TARGETING, INC. HAS BEEN ADVISED OF OR HAS KNOWLEDGE OF THE POSSIBILITY OF SUCH DAMAGES. TOXICS TARGETING, INC. EXPRESSLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE. Some jurisdictions do not allow the exclusion or limitation of incidental or consequential damages, so the above exclusion or limitation may not apply to you.

Period of Warranty

The period of warranty coverage is ninety days from the date of purchase of this Report. There shall be no warranty after the period of coverage. ANY AND ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR PARTICULAR USE SHALL HAVE NO GREATER DURATION THAN THE PERIOD OF WARRANTY STATED HERE, AND SHALL TERMINATE AUTOMATICALLY UPON THE EXPIRATION OF SUCH PERIOD. Some jurisdictions do not allow limitations on how long an implied warranty lasts, so the above exclusion or limitation may not apply to you.

PLEASE REFER TO PAGES ONE AND FIVE FOR A DESCRIPTION OF SOME OF THE LIMITATIONS OF THIS ENVIRONMENTAL REPORT.

Table of Contents

Introduction..... 1

- *The Three Sections of Your Report*
- *How to Use Your Report*
- *Toxic Site Databases Analyzed In Your Report*
- *Limitations Of the Information In Your Report*

Section One: Your Report Summary..... 7

- *Table One: Number of Identified Toxic Sites By Distance Interval*
- *Table Two: Identified Toxic Sites By Direction*
- *Table Three: Identified Toxic Sites By Category*
- *Table Four: Identified Toxic Sites By Proximity*
- *Map One: One-Mile Radius Map*
- *Map Two: Half-Mile Radius Map*
- *Map Three: Eighth-Mile Radius Map*
- *Map Four: Eighth-Mile Radius Close-up Map*
- *Map Five: Tax Parcel Map*
- *Table Five: Tax Parcel Map Information Table*

Section Two: Toxic Site Profiles

Section Three: Appendices

- *USEPA ERNS Check*
- *Unmappable Sites*
- *Hazardous Waste Codes*
- *Information Source Guide*

© Toxics Targeting, Inc. 2016

Introduction

Toxics Targeting has combined environmental database searches, extensive regulatory analysis and sophisticated mapping techniques to produce your *Environmental Report.* It checks for the presence of 25 categories of government-reported toxic sites and provides detailed, up-to-date information on each identified site. The findings of your report are presented in an easy-to-understand format that:

1. ***Maps*** the approximate locations of selected government-reported toxic sites identified on or near a specified target address.

2. ***Estimates*** the distance and direction between the target address and each identified toxic site.

3. ***Reports*** air and water permit non-compliance and other regulatory violations.

4. ***Profiles*** some aspects of the usage, manufacture, storage, handling, transport or disposal of toxic chemicals at individual sites.

5. ***Summarizes*** some potential health effect information and drinking water standards for selected chemicals reported at individual sites.

The Three Sections Of Your Report

The first section highlights your report's findings by summarizing identified sites according to: **a)** distance intervals, **b)** direction, **c)** proximity to the target address and **d)** individual site categories. In addition, the locations of all identified toxic sites are illustrated on individual maps for each radius search distance used in your report. A close-up map illustrates the locations of all identified toxic sites, at the shortest radius search distance used in your report. Finally, a map of tax parcels and a table of selected information about those parcels are included.

The second section of your report contains *Toxic Site Profiles* that provide detailed information on each identified toxic site. The information in each *Toxic Site Profile* varies according to its source. Some toxic site categories have extensive information and some have limited information. All the information is updated on a regular basis.

The third section of the report contains appendices that identify: **1)** on-site spills reported to the national Emergency Response Notification System (ERNS), **2)** various toxic sites that cannot be mapped due to incomplete or erroneous addresses or other mapping problems, **3)** codes that characterize hazardous wastes reported at various facilities, **4)** methods used to map toxic sites identified in your report and **5)** information sources used in your report.

How to Use Your Report

- Check Table One to see the number of identified sites by distance intervals.

- Check Table Two to see identified sites sorted by direction.

- Check Table Three to see identified sites ranked by proximity to the target address.

- Check Table Four to see identified sites sorted by site categories.

- Use Table Five to get info for the subject parcel and every parcel found on the Tax Parcel Map
- Refer to the various maps to see the locations of identified toxic sites. Refer to the *Toxic Site Profile* and *Appendix* sections for additional information.

Toxic Site Databases Analyzed In Your Report

Search Radius

One-Mile 

1) ***National Priority List for Federal Superfund Cleanup****:* a listing of sites known to pose environmental or health hazards that are being investigated or cleaned up under the Federal Superfund program.

Half-Mile 

2) ***Delisted National Priority List Sites****:* a listing of NPL sites that have been removed from the National Priority List.

One-Mile 

3) ***New York Inactive Hazardous Waste Disposal Site Registry****:* a state listing of sites that can pose environmental or public health hazards requiring investigation or clean up.

One-Mile 

4) ***New York Inactive Hazardous Waste Disposal Site Registry Qualifying****:* a state listing of sites that qualify for possible inclusion to the NYS DEC Inactive Haz. Waste Disposal Site Registry.

One-Mile

5) ***New York and Federal RCRA Corrective Action Activity (CORRACTS):*** waste facilities with RCRA corrective action activity reported by the USEPA and NYS DEC.

Half-Mile 

6) ***CERCLIS*** (Comprehensive Environmental Response, Compensation and Liability Information System): a federal listing of Non-NFRAP sites that can pose environmental or public health hazards requiring investigation or clean up.

Half-Mile 

7) ***CERCLIS NFRAP:*** a federal listing of CERCLIS sites that have no further remedial action planned.

Half-Mile

8) ***NYS & NYC Brownfield Program Sites****:* a listing of sites that are abandoned, idled or under-used industrial and commercial sites where expansion or redevelopment is complicated by real or perceived environmental contamination.

Half-Mile 

9) ***New York Solid Waste Facilities Registry****:* active and inactive landfills, incinerators, transfer stations or other solid waste management facilities.

Half-Mile 

10) ***New York City 1934 Solid Waste Sites****:* a listing of solid waste disposal sites operated by New York City municipal authorities circa 1934.

Half-Mile

11) ***New York and Federal Hazardous Waste Treatment, Storage or Disposal Facilities****:* sites reported by the NYS manifest system and the USEPA's Resource Conservation and Recovery Act Information System (RCRIS). Also includes the following database:

- ***RCRA violations:*** waste facilities with violations reported by the USEPA pursuant to the Resource Conservation and Recovery Act.

Half-Mile

12) ***Toxic Spills: active and inactive or closed*** spills reported to state environmental authorities, including *remediated* and *unremediated* leaking underground storage tanks. This database includes the following categories:

- Tank Failures
- Tank Test Failures
- Unknown Spill Cause or Other Spill Causes
- Miscellaneous Spill Causes

Eighth-Mile

13) ***New York State Major Oil Storage Facilities****:* sites with more than a 400,000 gallon capacity for storing petroleum products.

Eighth-Mile

14) ***New York State Petroleum Bulk Storage Facilities****:* sites with more than an 1,100 gallon capacity for storing petroleum products.

Eighth-Mile

15) ***New York City Fire Dept Tank Data****:* tank data from 1997.

Eighth-Mile

16) ***New York and Federal Hazardous Waste Generators and Transporters****:* sites reported by the NYS manifest system and the USEPA's Resource Conservation and Recovery Act Information System (RCRA). Also includes the following database:

- ***RCRA violations:*** waste facilities with violations reported by the USEPA pursuant to the Resource Conservation and Recovery Act.

Eighth-Mile 

17) ***New York Chemical Bulk Storage Facilities****:* sites storing hazardous substances listed in 6 NYCRR Part 597 in aboveground tanks with capacities of 185 gallons or more and/or underground tanks of any size

Eighth-Mile

18) ***Historic New York City Utility Sites (1890's to 1940's)****:* power generating stations, manufactured gas plants, gas storage facilities, maintenance yards and other gas and electric utility sites.

Half-Mile 

19) ***New York Hazardous Substance Disposal Site Draft Study****:* a state listing of sites contaminated with toxic substances that can pose environmental or public health hazards. These sites were not eligible for state clean up funding programs.

Eighth-Mile

20) ***Federal Toxic Release Inventory Facilities****:* discharges of selected toxic chemicals to air, land, water or treatment facilities.

Eighth-Mile

21) ***Federal Air Discharges****:* air pollution point sources monitored by U.S. EPA and/or state and local air regulatory agencies.

Eighth-Mile

22) ***Federal Permit Compliance System Toxic Wastewater Discharges:*** permitted toxic wastewater discharges.

Eighth-Mile

23) ***Federal Civil and Administrative Enforcement Docket****:* judiciary cases filed on behalf of the U. S. Environmental Protection Agency by the Department of Justice.

On-site only (250 ft)

24) ***New York City Environmental Quality Review (CEQR) – E Designation Sites****:* parcels assigned a special environmental ("E") designation under the CEQR process. E designation requires specific protocols that must be followed.

Property only

25) ***ERNS: Federal Emergency Response Notification System Spills****:* a listing of federally reported spills.

Limitations Of The Information In Your Report

The information presented in your *Environmental Report* has been obtained from various local, state and federal government agencies. Please be aware that: **1)** additional information on individual sites may be available, **2)** newly discovered sites are continually reported and **3)** all map locations are approximate. As a result, this report is intended to be the FIRST STEP in the process of identifying and evaluating possible environmental threats to specific properties and can only serve as a guide for conducting on-site visits or additional, more detailed toxic hazard research.

Toxics Targeting tries to ensure that the information in your report is presented accurately and with minimal alteration. Systematic changes are made to correct obvious address errors in order to allow sites to be mapped. Any address changes that are made are noted in the map information section at the top of each corresponding *Toxic Site Profile*. Some information that has been withheld by government authorities remains included in Toxic Site Profiles and is identified as archival information. Since the information presented in your report is not edited, please be aware that it can contain reporting errors or typographical mistakes made by the site owners/operators or government agencies that produced the information. Also please be aware of some other limitations of the information in your report:

- The digital map used by *Toxics Targeting* is the same one used by the U. S. Census or local authorities in New York City. While the map is generally accurate, no map is perfect. In addition, *Toxics Targeting's* mapping methods estimate where toxic site addresses are located if the address is not specifically designated. FOR THESE REASONS, ALL MAP LOCATIONS OF ADDRESSES AND REPORTED TOXIC SITES SHOULD BE CONSIDERED APPROXIMATE AND SHOULD BE VERIFIED BY ON-SITE VISITS;

- UNDISCOVERED, UNREPORTED OR UNMAPPABLE TOXIC SITES MIGHT NOT BE IDENTIFIED BY THIS REPORT'S CHECK OF 25 TOXIC SITE CATEGORIES. TOXIC SITES REPORTED IN OTHER GOVERNMENT DATABASES MIGHT ALSO EXIST. FOR THESE REASONS, YOUR REPORT MIGHT NOT IDENTIFY ALL THE TOXIC SITES THAT EXIST IN THE AREA IT SEARCHES;

- The appendix of your report contains a listing of sites that could not be mapped due to incomplete or erroneous address information or other mapping problems. This listing includes unmappable toxic sites in the zip codes searched for the report as well as toxic sites without zip codes reported in the same county. IF YOU WOULD LIKE INFORMATION ON ANY OF THE LISTED SITES, PLEASE CONTACT *TOXICS TARGETING AND REFER TO THE SITE ID NUMBER.*

- New York State Department of Environmental Conservation Remediation Site Borders are approximate and may not align with tax parcel boundaries mapped by local authorities or the digital map used by the US Census Bureau. As a result, Remediation Site Borders may overlap parcels that do not involve site remediation activities. Selected parcels also can involve multiple Remediation Site Borders. Refer to individual site profiles for more information. Sites without profiles include potential new sites or sites that have not yet been publicly listed by DEC.

- Some toxic sites identified in your report may be classified as **known hazards**. Most of the toxic sites identified in your report involve **potential hazards** related to the on-site use, manufacture, handling, storage, transport or disposal of toxic chemicals. Some of the toxic sites identified in your report may be the addresses of parties responsible for toxic sites located elsewhere. YOU SHOULD ONLY CONCLUDE THAT TOXIC HAZARDS ACTUALLY EXIST AT A SPECIFIC SITE WHEN GOVERNMENT AUTHORITIES MAKE THAT DETERMINATION OR WHEN THAT CONCLUSION IS FULLY DOCUMENTED BY THE FINDINGS OF AN APPROPRIATE SITE INVESTIGATION UNDERTAKEN BY LICENSED PROFESSIONALS;

- Compass directions and distances are approximate. Compass directions are calculated from the subject property address to the mapped location of each identified toxic site. The compass direction does not necessarily refer to the closest property boundary of an identified toxic site. The compass direction also can vary substantially for toxic sites that are located very close to the subject property address.

- The information presented in your report is a summary of the information that *Toxics Targeting* obtains from government agencies on reported toxic sites. YOU MAY BE ABLE TO OBTAIN ADDITIONAL INFORMATION ABOUT REPORTED SITES WITH THE FREEDOM OF INFORMATION REQUEST FORM LETTERS THAT ARE PROVIDED ON THE INSIDE OF THE BACK COVER.

Section One:

Report Summary

- *Table One: Number of Identified Toxic Sites By Distance Interval*
- *Table Two: Identified Toxic Sites By Direction*
- *Table Three: Identified Toxic Sites By Category*
- *Table Four: Identified Toxic Sites By Proximity*
- *Map One: One-Mile Radius Map*
- *Map Two: Half-Mile Radius Map*
- *Map Three: Eighth-Mile Radius Map*
- *Map Four: Eighth-Mile Radius Close up Map*
- *Map Five: Tax Parcel Map*
- *Table Five: Tax Parcel Map Information Table*

NUMBER OF IDENTIFIED SITES BY DISTANCE INTERVAL

Database Searched	0 − 100 ft	100 ft − 1/8 mi	1/8 mi − 1/4 mi	1/4 mi − 1/2 mi	1/2 mi − 1 mi	Site Category Totals
ASTM−Required 1 Mile Search						
National Priority List (NPL) Sites	0	0	0	0	0	0
NYS Inactive Hazardous Waste Disposal Site Registry	0	0	0	0	2	2
NYS Inactive Haz Waste Disposal Site Registry Qualifying	0	0	0	0	0	0
RCRA Corrective Action (CORRACTS) Sites	0	0	0	0	0	0
ASTM−Required 1/2 Mile Search						
Delisted National Priority List (NPL) Sites	0	0	0	0	Not searched	0
CERCLIS Superfund Non−NFRAP Sites	0	0	0	0	Not searched	0
CERCLIS Superfund NFRAP Sites	0	0	0	0	Not searched	0
Brownfields Sites						
Voluntary Cleanup Program	0	0	0	0	Not searched	0
Environmental Restoration Program	0	0	0	0	Not searched	0
Brownfield Cleanup Program	0	0	0	1	Not searched	1
NYC Voluntary Cleanup Program	0	0	2	10	Not searched	12
NYSDEC Solid Waste Facilities / Landfills	0	0	0	0	Not searched	0
RCRA Hazardous Waste Treatment, Storage, Disposal Sites	0	0	0	0	Not searched	0
NYS Toxic Spills						
Active Tank Failures	0	0	0	0	Not searched	0
Active Tank Test Failures	0	0	1	4	Not searched	5
Active Spills − Unknown / Other Causes	0	0	0	7	Not searched	7
Active Spills − Miscellaneous Causes	0	1	0(2)	0(6)	Not searched	1(8)
Closed Tank Failures	0	0	2	8	Not searched	10
Closed Tank Test Failures	0	0	2	26	Not searched	28
Closed Spills − Unknown / Other Causes	0	6	22	109	Not searched	137
Closed Spills − Miscellaneous Causes	0	7	2(29)	31(121)	Not searched	40(150)
ASTM−Required Property & Adjacent Property (1/8 Mile Search)						
NYS Major Oil Storage Facilities	0	0	Not searched	Not searched	Not searched	0
Local & State Petroleum Bulk Storage Sites	0	13	Not searched	Not searched	Not searched	13
RCRA Hazardous Waste Generators & Transporters	1	81	Not searched	Not searched	Not searched	82
NYS Chemical Bulk Storage Sites	0	0	Not searched	Not searched	Not searched	0
Historic Utility Facilities	0	1	Not searched	Not searched	Not searched	1
ASTM−Required On−Site Only Search						
NYC Environmental Quality Review Requirements ("E") Sites*	0	0	Not searched	Not searched	Not searched	0
Emergency Response Notification System (ERNS)	0	Not searched	Not searched	Not searched	Not searched	0
Institutional Controls / Engineering Controls (IC/EC)	See databases for NPL, CERCLIS, Inactive Hazardous Waste Disposal Site Registry and Brownfield Sites.					
ASTM−Required Databases Distance Interval Totals	**1**	**109**	**31(31)**	**196(127)**	**2**	**339(158)**

Numbers in ( ) indicate spills not mapped and profiled in this report, and are listed at the end of the active and closed spills sections. See these lists for a description of the parameters involved with identifying these spills.

* NYC Environmental Quality Review Requirements ("E") Sites were searched at 250 feet.

NOTE: Table continues on next page.

Non−ASTM Databases 1/2 Mile Search						
1934 NYC Municipal Waste Landfills	0	0	0	0	Not searched	0
Hazardous Substance Waste Disposal Sites	0	0	0	1	Not searched	1
Non−ASTM Databases 1/8 Mile Search						
Toxic Release Inventory Sites (TRI)	0	0	Not searched	Not searched	Not searched	0
Permit Compliance System (PCS) Toxic Wastewater Discharges	0	0	Not searched	Not searched	Not searched	0
Air Discharges	0	0	Not searched	Not searched	Not searched	0
Civil & Administrative Enforcement Docket Facilities	0	0	Not searched	Not searched	Not searched	0
Non−ASTM Databases Distance Interval Totals	**0**	**0**	**0**	**1**	**Not Searched**	**1**
Distance Interval Totals	***1***	***109***	***31(31)***	***197(127)***	***2***	***340(158)***

Numbers in ( ) indicate spills not mapped and profiled in this report, and are listed at the end of the active and closed spills sections. See these lists for a description of the parameters involved with identifying these spills.

Identified Toxic Sites by Direction

1678 and 1700 Park Avenue
New York, NY 10035

* Compass directions can vary substantially for sites located very close to the subject property address.

Sites less than 100 feet from subject property sorted by distance

Map Id#	Site Name	Site Street	Approximate Distance & Direction From Property	Toxic Site Category
257	GE−CEL CLEANERS	1694 PARK AVE	44 feet to the SSW*	Hazardous Waste Generator/Transporter

Sites between 100 ft and 400 ft from the subject property sorted by direction and distance

Map Id#	Site Name	Site Street	Approximate Distance & Direction From Property	Toxic Site Category
265	CON EDISON	68 E 120TH ST	200 feet to the N	Hazardous Waste Generator/Transporter
267	CON EDISON	64 E 120TH ST	219 feet to the N	Hazardous Waste Generator/Transporter
268	CONED	62 E 120TH ST	231 feet to the N	Hazardous Waste Generator/Transporter
276	CON EDISON	F/O 65 E 120TH ST	314 feet to the N	Hazardous Waste Generator/Transporter
281	CON EDISON	58 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
282	CON EDISON	68 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
283	CON EDISON	72 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
284	VEOLIA ENERGY NORTH AMERICA	80 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
285	CON EDISON	50 E 121 ST	389 feet to the N	Hazardous Waste Generator/Transporter
286	NYC BOARD OF EDUCATION − PS 79	55 EAST 120TH STREET	389 feet to the N	Hazardous Waste Generator/Transporter
258	CON EDISON SERVICE BOX: 42084	1700 PARK AVE	119 feet to the NNE*	Hazardous Waste Generator/Transporter
67	SERVICE BOX 19779	E120TH ST/PARK AVE	288 feet to the NE	Closed Status Spill (Unk/Other Cause)
204	TRUCK	NEAR EAST 120TH AND PARK	288 feet to the NE	Closed Status Spill (Misc. Spill Cause)
271	CON EDISON	E 120TH ST & PARK AVE	288 feet to the NE	Hazardous Waste Generator/Transporter
272	CONSOLIDATED EDISON	PARK AVE & EAST 120 ST	288 feet to the NE	Hazardous Waste Generator/Transporter
260	CON EDISON	F/O 1700 PARK AVE	151 feet to the ENE*	Hazardous Waste Generator/Transporter
266	CON EDISON	FO 1709 PARK AVE NO 119TH ST	208 feet to the ENE	Hazardous Waste Generator/Transporter
249	AYERS MOVERS	1721 PARK AVE	399 feet to the ENE	Petroleum Bulk Storage Site
278	CON EDISON	117 E 119TH ST	364 feet to the ESE	Hazardous Waste Generator/Transporter
279	CONSOLIDATED EDISON	FRONT OF 117 EAST 119 STREET	367 feet to the ESE	Hazardous Waste Generator/Transporter
28	25 PRECINCT NYPD −DDC	120 EAST 119TH STREET	382 feet to the SE	Active Haz Spill (Misc. Spill Cause)
205	120 EAST 119TH STREET	120 EAST 119TH STREET	382 feet to the SE	Closed Status Spill (Misc. Spill Cause)
248	25 PCT	120 EAST 119TH STREET	395 feet to the SE	Petroleum Bulk Storage Site
280	CONSOLIDATED EDISON	F/O 111 E 118TH ST	385 feet to the SSE	Hazardous Waste Generator/Transporter
262	CON EDISON	F/O 1680 PARK AVE	161 feet to the S*	Hazardous Waste Generator/Transporter
68	VAULT 6340	EAST 118TH ST/ PARK AVE	288 feet to the S	Closed Status Spill (Unk/Other Cause)

273	CON EDISON	E 118TH ST& PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
274	CON EDISON	E 118 ST & PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
275	CON EDISON	SEC E 118 ST & PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
288	CON EDISON	100 E 118 ST	398 feet to the S	Hazardous Waste Generator/Transporter
289	CON EDISON	100 E 118 ST	398 feet to the S	Hazardous Waste Generator/Transporter
261	CON EDISON SERVICE BOX: 42076	1680 PARK AVE	160 feet to the SSW*	Hazardous Waste Generator/Transporter
264	CON EDISON	FO 63 E 119TH ST	200 feet to the WNW	Hazardous Waste Generator/Transporter
245	50 EAST 119TH STREET	50 EAST 119TH STREET	305 feet to the WNW	Petroleum Bulk Storage Site
246	PROVIDENCE BAPTIST CHURCH	50 EAST 119TH STREET	305 feet to the WNW	Petroleum Bulk Storage Site
247	1829 MADISON AVE	1829 MADISON AVE	305 feet to the WNW	Petroleum Bulk Storage Site
287	CONSOLIDATED EDISON	MADISON AVE & E 119TH ST	391 feet to the WNW	Hazardous Waste Generator/Transporter
263	CON EDISON	67 W 119TH ST & LENOX AVE	177 feet to the NW*	Hazardous Waste Generator/Transporter
269	CONED	61 E 119TH ST	232 feet to the NW	Hazardous Waste Generator/Transporter
244	MADISON PARK PARTNERSHIP HOUSING	59 EAST 119TH ST.	255 feet to the NW	Petroleum Bulk Storage Site
277	CON EDISON	1835 MADISON AVE	318 feet to the NW	Hazardous Waste Generator/Transporter
259	CONED	71 E 119TH ST	143 feet to the NNW*	Hazardous Waste Generator/Transporter
270	VEOLIA ENERGY NORTH AMERICA	58 E 120TH ST	256 feet to the NNW	Hazardous Waste Generator/Transporter

Sites equal to or greater than 400 ft from subject property sorted by direction and distance

Map Id#	Site Name	Site Street	Approximate Distance & Direction From Property	Toxic Site Category
251	PUBLIC SCHOOL 79 − MANHATTAN M079	55 EAST 120TH STREET	456 feet to the N	Petroleum Bulk Storage Site
308	CON EDISON	F/O 58 E 121 ST	544 feet to the N	Hazardous Waste Generator/Transporter
73	MANHOLE 50789	MADISON AV & 121ST ST	662 feet to the N	Closed Status Spill (Unk/Other Cause)
24	MORRIS PARK HOUSES −NYCHA	17 EAST 124TH ST	1518 feet to the N	Active Haz Spill (Unknown/Other Cause)
45	MORRIS PARK SENIOR	17 EAST 124TH STREET	1518 feet to the N	Closed Status Tank Test Failure
217	MORRIS PK SENIOR CITIZENS	17 EAST 124TH STREET	1518 feet to the N	Closed Status Spill (Misc. Spill Cause)
218	MORRIS PARK SENIOR CIT.	17 EAST 124TH STREET	1518 feet to the N	Closed Status Spill (Misc. Spill Cause)
50	X	1944 MADISON AVE	1565 feet to the N	Closed Status Tank Test Failure
219	SPILL NUMBER 9810692	1944 MADISON AV	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
220	MT MORRIS PARK BATH HOUSE	1944 MADISON AVE	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
221	1944 MADISON AVENUE	1944 MADISON AVENUE	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
222	STREET SPILL	124TH ST 5TH AVE	1589 feet to the N	Closed Status Spill (Misc. Spill Cause)
120	DEMOLISHED BUILDING	2000−2002 5TH AVE	1734 feet to the N	Closed Status Spill (Unk/Other Cause)
126	2ND AVE SUBWAY −NYCT	125TH ST/5TH AVE	1828 feet to the N	Closed Status Spill (Unk/Other Cause)
13	5 WEST 125TH	5 WEST 125TH STREET	2088 feet to the N	Brownfields Site
18	ABOVE GROUND TANK − TTF	17 WEST 125TH ST	2113 feet to the N	Active Tank Test Failure
162	SB 20601	WEST 127TH ST/ 5TH AVE	2313 feet to the N	Closed Status Spill (Unk/Other Cause)
166	SPILL NUMBER 0202065	2067 5TH AVE	2352 feet to the N	Closed Status Spill (Unk/Other Cause)
170	SPILL NUMBER 0011504	20 WEST 127TH ST	2387 feet to the N	Closed Status Spill (Unk/Other Cause)
242	SPILL NUMBER 0103459	24 WEST 127TH ST	2406 feet to the N	Closed Status Spill (Misc. Spill Cause)
185	SPILL NUMBER 0105211	11 WEST 127TH ST	2480 feet to the N	Closed Status Spill (Unk/Other Cause)
309	CON EDISON	65 E 121 ST & PARK AVE	550 feet to the NNE	Hazardous Waste Generator/Transporter
312	CONSOLIDATED EDISON	1748 PARK AVE	551 feet to the NNE	Hazardous Waste Generator/Transporter

325	CON EDISON	55 E 121ST ST	641 feet to the NNE	Hazardous Waste Generator/Transporter
326	CON EDISON	73 E 121 ST	641 feet to the NNE	Hazardous Waste Generator/Transporter
327	CON EDISON	73 E 121ST ST & MADISON AVE	641 feet to the NNE	Hazardous Waste Generator/Transporter
328	CON EDISON	60 E 122 ST MADISON AV	641 feet to the NNE	Hazardous Waste Generator/Transporter
329	HENRY J CARTER SPECIALITY HOSPITAL	1879 MADISON AVE	641 feet to the NNE	Hazardous Waste Generator/Transporter
330	NYC HEALTH & HOSPITAL CORP	1752 PARK AVENUE	641 feet to the NNE	Hazardous Waste Generator/Transporter
3	1901 MADISON AVENUE	1901 MADISON AVENUE	935 feet to the NNE	Brownfields Site
212	1883 MADISON AVE	1883 MADISON AVE	955 feet to the NNE	Closed Status Spill (Misc. Spill Cause)
22	SOIL	1800 PARK AVE	1366 feet to the NNE	Active Haz Spill (Unknown/Other Cause)
23	1800 PARK AVE	1800 PARK AVE	1366 feet to the NNE	Active Haz Spill (Unknown/Other Cause)
96	79 E 124TH ST	79 E 124TH ST	1366 feet to the NNE	Closed Status Spill (Unk/Other Cause)
7	HARLEM PARK	1800−1808 PARK AVE 71 E. 124 ST., 66−70 E 125 ST.	1473 feet to the NNE	Brownfields Site
103	2ND AVE SUBWAY PROJECT − NYCT	PARK AVE/125TH ST	1594 feet to the NNE	Closed Status Spill (Unk/Other Cause)
104	125TH ST BTWN MADISON −NYCT	125TH ST PARK& MADISON SO	1595 feet to the NNE	Closed Status Spill (Unk/Other Cause)
107	208153; MADISON AVE	MADISON AVE	1637 feet to the NNE	Closed Status Spill (Unk/Other Cause)
8	81 WEST 125TH STREET	81 WEST 125TH STREET	1662 feet to the NNE	Brownfields Site
112	SPILL NUMBER 0206541	79 E 125TH ST	1693 feet to the NNE	Closed Status Spill (Unk/Other Cause)
9	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE	Brownfields Site
10	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE	Brownfields Site
52	1824 PARK AVE/SUNOCO	1824 PARK AVE	1778 feet to the NNE	Closed Status Tank Test Failure
229	METRO NORTH	126TH ST. & PARK AVE.	1874 feet to the NNE	Closed Status Spill (Misc. Spill Cause)
33	78−80 E 127TH ST/NYCHPD	78−80 E 127TH ST	2056 feet to the NNE	Closed Status Tank Failure
146	64 E 127TH ST	64 E 127TH ST	2063 feet to the NNE	Closed Status Spill (Unk/Other Cause)
149	IMPACTED SOIL FOUND IN EXCAVATION	PARK AVE & EAST 127 STREET	2133 feet to the NNE	Closed Status Spill (Unk/Other Cause)
160	2005 MADISON AV & 128TH	2005 MADISON AV	2286 feet to the NNE	Closed Status Spill (Unk/Other Cause)
172	PRIVATE HOME	12 EAST 128TH ST	2408 feet to the NNE	Closed Status Spill (Unk/Other Cause)
187	SERVICE BOX 42143	PARK AVE 128TH/129TH	2522 feet to the NNE	Closed Status Spill (Unk/Other Cause)
194	1890 PARK AVE CORP	1890 PARK AVE	2574 feet to the NNE	Closed Status Spill (Unk/Other Cause)
304	CONSOLIDATED EDISON	N/S E 121 ST 165‘ EAST OF PARK	537 feet to the NE	Hazardous Waste Generator/Transporter
305	CON EDISON	E 121ST ST & PARK AVE	537 feet to the NE	Hazardous Waste Generator/Transporter
319	CONSOLIDATED EDISON	FRONT OF 1743 PARK AVE	605 feet to the NE	Hazardous Waste Generator/Transporter
79	VACANT LOT	1761 PARK AVENUE	859 feet to the NE	Closed Status Spill (Unk/Other Cause)
41	STORE FRONT	124 EAST 124TH ST.	1321 feet to the NE	Closed Status Tank Test Failure
102	APPLE BANK	124 EAST 125TH ST	1584 feet to the NE	Closed Status Spill (Unk/Other Cause)
114	MH39246	E 125TH ST & LEXINGTON AV	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
115	SPILL NUMBER 9905454	125TH ST & LEXINGTON AV	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
116	MANHOLE 39242	125TH ST /LEXINGTON AVE	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
117	218014; E 125 ST AND LEXINGTON AVE	E 125 ST AND LEXINGTON AVE	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
118	2ND AVE SUBWAY −NYCT	LEXINGTON & 125TH ST	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
11	146 EAST 126TH STREET	146 EAST 126TH STREET	1986 feet to the NE	Brownfields Site
181	LEXINGTON AV/E 128TH ST	LEXINGTON AV/E.128TH ST	2472 feet to the NE	Closed Status Spill (Unk/Other Cause)
64	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
65	JACKIE ROBINSON HOUSING	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
66	JACKIE ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
190	JACKIE ROBINSON CONSOLID. −NYCHA	129 E.128TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
191	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
192	I PT OF UNKN SUBSTANCE IN SB 21083	105 EAST 128 STREET	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
193	ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
2	VISTA 1	2401 THIRD AVENUE	3872 feet to the NE	NYSDEC Inactive Haz Waste Disposal Site
71	PARKING LOT	1980 LEXINGTON AVE	580 feet to the ENE	Closed Status Spill (Unk/Other Cause)
336	CON EDISON	N SIDE E 121ST ST 240 FEET E	656 feet to the ENE	Hazardous Waste Generator/Transporter

337	CONSOLIDATED EDISON	E 121ST ST B/T LEXINGTON & PARK	656 feet to the ENE	Hazardous Waste Generator/Transporter
338	CON EDISON	F/O 132 E 121ST ST	656 feet to the ENE	Hazardous Waste Generator/Transporter
339	121ST ST	128−130 E 121ST ST	659 feet to the ENE	Historic Utility Site
81	MANHOLE #39219	E 122ND ST & LEXINGTON AV	1008 feet to the ENE	Closed Status Spill (Unk/Other Cause)
30	2021 LEXINGTON AVENUE	2021 LEXINGTON AVENUE	1187 feet to the ENE	Closed Status Tank Failure
99	VAULT #9153	3RD AVE / E 123 ST	1546 feet to the ENE	Closed Status Spill (Unk/Other Cause)
60	THE EAST DRIVE H.D.F.C.	205 EAST 124TH STREET	1906 feet to the ENE	Closed Status Tank Test Failure
134	CROSSWALKS	125TH / 3RD AVE	1956 feet to the ENE	Closed Status Spill (Unk/Other Cause)
12	CHURCH OF SCIENTOLOGY−SITE A	220 EAST 125TH STREET	2071 feet to the ENE	Brownfields Site
14	CHURCH OF SCIENTOLOGY−SITE B	220 EAST 125TH STREET	2153 feet to the ENE	Brownfields Site
155	BWTEEEN 2ND & 3RD AV −NYCT	125TH ST 2ND & 3RD AVE	2176 feet to the ENE	Closed Status Spill (Unk/Other Cause)
156	MANHOLE 45805	EAST 126TH ST / 3RD AVE	2189 feet to the ENE	Closed Status Spill (Unk/Other Cause)
168	LOT NEXT TO AMOCO STATION	249 EAST 125TH ST	2373 feet to the ENE	Closed Status Spill (Unk/Other Cause)
173	MAN HOLE #45816	E 127TH ST & 3RD AVE	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
174	213284; 3 AVE AND E 127 ST ST	3 AVE AND E 127 ST ST	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
175	CONED MANHOLE #20977	EAST 127/3RD AVE	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
63	AMOCO	255 EAST 125TH STREET	2421 feet to the ENE	Closed Status Tank Test Failure
243	BP AMOCO STATION #13401	255 EAST 125TH ST	2421 feet to the ENE	Closed Status Spill (Misc. Spill Cause)
178	217897; 2 AVENUE AND 125TH STREET	2 AVENUE AND 125TH STREET	2439 feet to the ENE	Closed Status Spill (Unk/Other Cause)
27	CONSTRUCTION SITE	225 EAST 126TH ST	2448 feet to the ENE	Active Haz Spill (Unknown/Other Cause)
188	2ND AVE SUBWAY −NYCT	125TH & 126TH ST	2530 feet to the ENE	Closed Status Spill (Unk/Other Cause)
303	NYCHA − ROBINSON	1940 LEXINGTON AVE	525 feet to the E	Hazardous Waste Generator/Transporter
322	CON EDISON	FO 111 E 120 ST	616 feet to the E	Hazardous Waste Generator/Transporter
83	HARLEM COURTHOUSE	170 EAST 121ST STREET	1029 feet to the E	Closed Status Spill (Unk/Other Cause)
85	DUTCH REFORM CHURCH OF HARLEM	171 EAST 121 STREET	1098 feet to the E	Closed Status Spill (Unk/Other Cause)
92	SERVICE BOX 45747	2236 3RD AVE	1248 feet to the E	Closed Status Spill (Unk/Other Cause)
93	2236 3RD AVE	2236 3RD AVE OFF OF 128 EAST ST	1248 feet to the E	Closed Status Spill (Unk/Other Cause)
94	SERVICE BOX 45748	2238 3RD AVE	1262 feet to the E	Closed Status Spill (Unk/Other Cause)
5	2211 3RD AVENUE	2211 3RD AVENUE	1322 feet to the E	Brownfields Site
21	SOIL	2211 3RD AVE	1324 feet to the E	Active Haz Spill (Unknown/Other Cause)
46	RESIDENCE	212 EAST 122ND STREET	1537 feet to the E	Closed Status Tank Test Failure
47	TAINO TOWER	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
48	TAINO TOWERS − TTF	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
49	TAINO TOWERS	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
340	ODYSSEY HOUSE	219 E. 121ST STREET	1577 feet to the E	Hazardous Substance Waste Disposal Site
110	213778; 222 E 123 ST	222 E 123 ST	1666 feet to the E	Closed Status Spill (Unk/Other Cause)
228	HARLEM DAY CHARTER SCHOOL	230 E 123RD ST	1867 feet to the E	Closed Status Spill (Misc. Spill Cause)
150	STREET SPILL	SECOND AVE & E 123 ST	2144 feet to the E	Closed Status Spill (Unk/Other Cause)
171	2365 FIRST AVENUE	2365 FIRST AVENUE	2399 feet to the E	Closed Status Spill (Unk/Other Cause)
69	VACANT LOT	127 EAST 119TH ST	454 feet to the ESE	Closed Status Spill (Unk/Other Cause)
321	CON EDISON	F OF 1934 LEXINGTON AVE & 119TH ST	613 feet to the ESE	Hazardous Waste Generator/Transporter
210	119TH ST.& LEXINGTON AVE.	119TH ST. & LEXINGTON AVE	631 feet to the ESE	Closed Status Spill (Misc. Spill Cause)
323	CON EDISON	E 119TH ST & LEXINGTON AVE	631 feet to the ESE	Hazardous Waste Generator/Transporter
324	CON EDISON	NW COR LEXINGTON AVE & 119TH ST	631 feet to the ESE	Hazardous Waste Generator/Transporter
77	SB 19623	170 E.119TH ST	801 feet to the ESE	Closed Status Spill (Unk/Other Cause)
86	MAN HOLE 45730	NORTH WEST CORNER EAST 120 ST AND 3 AVE	1168 feet to the ESE	Closed Status Spill (Unk/Other Cause)
44	UNKNOWN	222 EAST 119TH ST	1505 feet to the ESE	Closed Status Tank Test Failure
122	246 E 121 ST	246 E 121ST	1762 feet to the ESE	Closed Status Spill (Unk/Other Cause)
59	APARTMENT BLDG − TTF	120TH ST & SECOND AVE	1866 feet to the ESE	Closed Status Tank Test Failure
128	MANHOLE 55068	120TH ST & 2ND AVE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)
129	215193; E 120 ST AND 2ND AVE	E 120 ST AND 2ND AVE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)

130	MANHOLE #1864	EAST 120 STREET & 2 AVENUE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)
158	ROADWAY SURFACE	EAST 120TH STREET BW 1ST AND 2ND AVE	2222 feet to the ESE	Closed Status Spill (Unk/Other Cause)
169	VACANT LOT	346 E. 119TH ST	2384 feet to the ESE	Closed Status Spill (Unk/Other Cause)
179	IS 45M− NYSCA	2351 1ST AVE	2442 feet to the ESE	Closed Status Spill (Unk/Other Cause)
186	M AND M GROCERY	2337 1ST AVE	2510 feet to the ESE	Closed Status Spill (Unk/Other Cause)
200	MANHOLE 53875	1ST AVE/120TH ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
201	MANHOLE 53880	1ST AVE/E120TH ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
202	MANHOLE 53864	E 120TH ST / 1ST AVE	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
203	VS2027 VAULT	1RST AVE AND EAST 120ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
290	CON EDISON	130 E 119TH ST W OF LEXINGTON AVE	409 feet to the SE	Hazardous Waste Generator/Transporter
206	132 E 119TH ST	132 E 119TH ST	477 feet to the SE	Closed Status Spill (Misc. Spill Cause)
315	CON EDISON	1932 LEXINGTON AVE	573 feet to the SE	Hazardous Waste Generator/Transporter
76	SB 19622	158 E. 119TH ST	710 feet to the SE	Closed Status Spill (Unk/Other Cause)
82	177 EAST 117TH STREET	177 EAST 117TH STREET	1009 feet to the SE	Closed Status Spill (Unk/Other Cause)
87	217428; 118 ST AND 3 AVE	118 ST AND 3 AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
88	VAULT #VS−5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
89	VAULT # 5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
40	JACOB'S RESIDENCE	203 EAST 117TH ST	1312 feet to the SE	Closed Status Tank Test Failure
106	DRUM RUN	228 EAST 117 ST BTW 2ND & 3RD AVE	1623 feet to the SE	Closed Status Spill (Unk/Other Cause)
109	PRIVATE RESIDENCE	236 E 118TH ST PT 9	1658 feet to the SE	Closed Status Spill (Unk/Other Cause)
131	210473; 2ND AVE	2ND AVE	1867 feet to the SE	Closed Status Spill (Unk/Other Cause)
143	MAN HOLE #55020	116TH ST / 2ND AV	2016 feet to the SE	Closed Status Spill (Unk/Other Cause)
144	SERVICE BOX 55036	2276 2ND AVE	2016 feet to the SE	Closed Status Spill (Unk/Other Cause)
61	CORSI HOUSES (JEFFERSON) −NYCHA	306 EAST 117TH STREET	2136 feet to the SE	Closed Status Tank Test Failure
26	NYC PS 155 SCHOOL	319 E117TH ST	2240 feet to the SE	Active Haz Spill (Unknown/Other Cause)
164	SOUTHSIDE OF −NYCT	EAST 116TH STREET	2329 feet to the SE	Closed Status Spill (Unk/Other Cause)
177	APARTMENT BUILDING	332 E 116TH ST	2436 feet to the SE	Closed Status Spill (Unk/Other Cause)
199	MANHOLE 53842	EAST 118 TH ST/1ST AVE	2610 feet to the SE	Closed Status Spill (Unk/Other Cause)
1	PLEASANT AVENUE PLUME TRACKDOWN	PLEASANT AVENUE	3259 feet to the SE	NYSDEC Inactive Haz Waste Disposal Site
291	CONED	117 E 118TH ST	412 feet to the SSE	Hazardous Waste Generator/Transporter
253	ST. PAUL SCHOOL	114 EAST 118TH STREET	522 feet to the SSE	Petroleum Bulk Storage Site
254	ST.PAULS CHURCH & SCHOOL	114 E 118 ST	522 feet to the SSE	Petroleum Bulk Storage Site
310	CON EDISON	125 E 117TH ST E OF 3RD AVE	551 feet to the SSE	Hazardous Waste Generator/Transporter
311	CON EDISON	115 E 117TH ST	551 feet to the SSE	Hazardous Waste Generator/Transporter
72	SPILL NUMBER 0311320	127 EAST 117TH ST	646 feet to the SSE	Closed Status Spill (Unk/Other Cause)
101	MANHOLE 45668	3RD AVE/EAST 115TH	1577 feet to the SSE	Closed Status Spill (Unk/Other Cause)
139	JEFFERSON HOUSES	2089 3RD AVE	1999 feet to the SSE	Closed Status Spill (Unk/Other Cause)
151	217860; 2 AVE AND 115TH ST	2 AVE AND 115TH ST	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
152	208234; NWC E 115 ST 2ND AV	NWC E 115 ST 2ND AV	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
153	VAULT 5975	EAST 115TH ST AT 2ND AV	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
19	CONVENT	226 EAST 113TH STREET	2217 feet to the SSE	Active Tank Test Failure
62	CHURCH	232 EAST 113TH STREET	2267 feet to the SSE	Closed Status Tank Test Failure
180	MANHOLE #62325	2 AVENUE & 113 STREET	2451 feet to the SSE	Closed Status Spill (Unk/Other Cause)
252	CRP 1661 PARK AVENUE LLC	105 EAST 117 ST.	517 feet to the S	Petroleum Bulk Storage Site
208	113 EAST 117TH STREET	113 EAST 117TH STREET	543 feet to the S	Closed Status Spill (Misc. Spill Cause)
209	ST PAULS RECTORY	113 EAST 117TH STREET	543 feet to the S	Closed Status Spill (Misc. Spill Cause)
316	CON EDISON	F/O 104 EAST 117TH ST	579 feet to the S	Hazardous Waste Generator/Transporter
317	CON EDISON	F/O 104 E 117TH ST	579 feet to the S	Hazardous Waste Generator/Transporter
332	CON EDISON	104 E 117TH ST	649 feet to the S	Hazardous Waste Generator/Transporter
333	CON EDISON	110 E 117 ST	649 feet to the S	Hazardous Waste Generator/Transporter

211	UNKNOWN RESIDENCE	124 EAST 117TH ST	746 feet to the S	Closed Status Spill (Misc. Spill Cause)
29	APARTMENT BUILDING	123 E. 116TH STREET	838 feet to the S	Closed Status Tank Failure
80	MAN HOLE (19150)	IFO 116 E. 116TH ST	924 feet to the S	Closed Status Spill (Unk/Other Cause)
42	CLOSED−LACKOF RECENT INFO	158 E 115TH ST	1367 feet to the S	Closed Status Tank Test Failure
119	MANHOLE 39163	EAST SIDE OF LEXINGTON AV	1712 feet to the S	Closed Status Spill (Unk/Other Cause)
53	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
54	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
55	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
56	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
57	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
123	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
124	JOHNSON HOUSES	1809 LEXINGTON AV	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
125	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
226	JOHNSON HOUSES	165 EAST 165TH STREET	1792 feet to the S	Closed Status Spill (Misc. Spill Cause)
227	163 E.112TH ST. NYC./NO.2 O	163 E. 112TH ST.	1792 feet to the S	Closed Status Spill (Misc. Spill Cause)
135	SPILL NUMBER 9809080	E 112 ST & LEXINGTON AV	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
136	MANHOLE 39156	E 112TH ST/LEXINGTON AV	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
137	219438; LEXINGTON AVE AND 112TH ST	LEXINGTON AVE AND 112TH ST	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
138	LEXINGTON AVE	LEXINGTON AVE/EAST 112 ST	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
237	163 E 111TH ST	163 E 111TH ST	2177 feet to the S	Closed Status Spill (Misc. Spill Cause)
157	SITE F/NEW CONSTRUCTION	169 EAST 111 ST	2216 feet to the S	Closed Status Spill (Unk/Other Cause)
176	MANHOLE 45629	E 111TH ST & 3RD AV	2418 feet to the S	Closed Status Spill (Unk/Other Cause)
189	207627; E ST	E ST	2553 feet to the S	Closed Status Spill (Unk/Other Cause)
195	APART	212 E. 111TH ST	2581 feet to the S	Closed Status Spill (Unk/Other Cause)
196	PVT APARTMENT BLDG	214 E.111TH ST	2594 feet to the S	Closed Status Spill (Unk/Other Cause)
292	CON EDISON SERVICE BOX: 42070	1664 PARK AVE	423 feet to the SSW	Hazardous Waste Generator/Transporter
293	CON EDISON	1664 PARK AVE	423 feet to the SSW	Hazardous Waste Generator/Transporter
70	207583; SE PARK AV E 117 ST	SE PARK AV E 117 ST	538 feet to the SSW	Closed Status Spill (Unk/Other Cause)
207	MANHOLE 42069	SE CRNR 117THST/PARK AVE	538 feet to the SSW	Closed Status Spill (Misc. Spill Cause)
306	CONSOLIDATED EDISON	SEC E 117TH ST & PARK AVE	538 feet to the SSW	Hazardous Waste Generator/Transporter
307	CONSOLIDATED EDISON	S/W/C E 117TH ST 7 PARK AVE	538 feet to the SSW	Hazardous Waste Generator/Transporter
255	1652 PARK AVENUE ASSOC. LLC	1648 PARK AVENUE	584 feet to the SSW	Petroleum Bulk Storage Site
132	ROAD INTERSECTION	E. 112 TH ST AND PARK AVE	1869 feet to the SSW	Closed Status Spill (Unk/Other Cause)
141	138 EAST 112TH ST	138 EAST 112TH ST	2004 feet to the SSW	Closed Status Spill (Unk/Other Cause)
183	MANHOLE #39138	EAST 110 AND LEXINGTON AV	2477 feet to the SSW	Closed Status Spill (Unk/Other Cause)
184	MANHOLE #39138	E 110TH ST & LEXINGTON AV	2477 feet to the SSW	Closed Status Spill (Unk/Other Cause)
250	61 EAST 117 STREET	61 EAST 117 STREET	449 feet to the SW	Petroleum Bulk Storage Site
256	MADISON COURT ASSOC, LP	58 EAST 117TH STREET	610 feet to the SW	Petroleum Bulk Storage Site
74	SERVICE BOX 19135	91 EAST 116 ST	705 feet to the SW	Closed Status Spill (Unk/Other Cause)
75	OPEN EXCAVATION	91 EAST 116 ST.	705 feet to the SW	Closed Status Spill (Unk/Other Cause)
216	VAULT #5033	1695 MADISON AV	1463 feet to the SW	Closed Status Spill (Misc. Spill Cause)
17	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Active Tank Test Failure
51	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Tank Test Failure
105	HOUSING PROJECT	1740 MADISON AVE	1605 feet to the SW	Closed Status Spill (Unk/Other Cause)
223	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Spill (Misc. Spill Cause)
224	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Spill (Misc. Spill Cause)
111	ROADWAY	MADISON AVE/EAST 113 ST	1691 feet to the SW	Closed Status Spill (Unk/Other Cause)
133	VAULT 2349	MADISON/E 112TH ST	1903 feet to the SW	Closed Status Spill (Unk/Other Cause)
20	PVT DWELLING − TTF	19−21 EAST 109 ST	2639 feet to the SW	Active Tank Test Failure
302	CON EDISON	1787 MADISON AVE & 117 ST	501 feet to the WSW	Hazardous Waste Generator/Transporter

334	CONSOLIDATED EDISON	V5731−MADISON & 117TH ST	654 feet to the WSW	Hazardous Waste Generator/Transporter
335	CON EDISON	S/W/C MADISON AVE E 117 ST	654 feet to the WSW	Hazardous Waste Generator/Transporter
90	MANHOLE M56965	WEST 116 ST & 5 AVE	1210 feet to the WSW	Closed Status Spill (Unk/Other Cause)
25	KING TOWERS −NYCHA	90 LENOX AVE	2079 feet to the WSW	Active Haz Spill (Unknown/Other Cause)
234	1350 5TH AVE	1350 5TH AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
235	70 LENOX AVE	70 LENOX AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
236	KING TOWERS	90 LENOX AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
294	CON EDISON	FT OF 1815−1817 MADISON AVE & 118TH ST	426 feet to the W	Hazardous Waste Generator/Transporter
295	CON EDISON	FT OF 1816−1818 MADISON AVE & 118TH ST	446 feet to the W	Hazardous Waste Generator/Transporter
296	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W	Hazardous Waste Generator/Transporter
297	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W	Hazardous Waste Generator/Transporter
298	CON EDISON SERVICE BOX: 50772	MADISON AVE & 118TH ST	471 feet to the W	Hazardous Waste Generator/Transporter
299	CON EDISON SERVICE BOX: 50775	MADISON AVE & 118TH ST	471 feet to the W	Hazardous Waste Generator/Transporter
314	NYC DEPT OF EDUCATION − PS 149M TANDEM WITH M207	34 WEST 118TH STREET	571 feet to the W	Hazardous Waste Generator/Transporter
320	CON EDISON	FT OF 22 E 118TH ST E OF 15TH AVE	613 feet to the W	Hazardous Waste Generator/Transporter
331	CONED	20 E 118TH ST	649 feet to the W	Hazardous Waste Generator/Transporter
78	209996; E E 117 ST ST	E E 117 ST ST	834 feet to the W	Closed Status Spill (Unk/Other Cause)
4	23 W. 116 ST AND 1428 FIFTH AVE (2 SITES)	1428 5TH AVENUE	1232 feet to the W	Brownfields Site
95	OPPOSITE OF 3 WEST 116 ST	OPPOSITE OF 3 WEST 116 ST	1320 feet to the W	Closed Status Spill (Unk/Other Cause)
6	23 WEST 116TH, 1428 FIFTH AVENUE	1428 5TH AVENUE	1468 feet to the W	Brownfields Site
121	CHURCH	33 WEST 115 & 36 115TH STREET	1741 feet to the W	Closed Status Spill (Unk/Other Cause)
225	WEST 115 ST	BET 5TH AV & LENOX AV	1791 feet to the W	Closed Status Spill (Misc. Spill Cause)
142	NEW CONSTRUCTION	81 WEST 115TH ST	2004 feet to the W	Closed Status Spill (Unk/Other Cause)
148	SPILL NUMBER 0308444	W. 116TH ST & LENOX AVE	2083 feet to the W	Closed Status Spill (Unk/Other Cause)
34	105 LENOX AVE/HARLEM HOSP	105 LENOX AVENUE	2291 feet to the W	Closed Status Tank Failure
241	112−114 W 116TH ST	112−114 W 116TH ST	2384 feet to the W	Closed Status Spill (Misc. Spill Cause)
318	CON EDISON	11 E 118 ST & 5 AV	600 feet to the WNW	Hazardous Waste Generator/Transporter
213	49 WEST 119TH ST/MANH	49 WEST 119TH STREET	1393 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
43	DUNLEVY MILBANK CHILDREN	14−32 WEST 118TH STREET	1398 feet to the WNW	Closed Status Tank Test Failure
97	63 W 119TH ST	63 W 119TH ST	1508 feet to the WNW	Closed Status Spill (Unk/Other Cause)
98	SPILL NUMBER 0304253	65 W 119TH ST	1525 feet to the WNW	Closed Status Spill (Unk/Other Cause)
108	79 WEST 119 STREET	79 WEST 119 STREET	1650 feet to the WNW	Closed Status Spill (Unk/Other Cause)
58	APART	86 WEST 119TH STREET	1822 feet to the WNW	Closed Status Tank Test Failure
154	BETWEEN LENOX AND 7TH AVE	109 WEST 119TH ST	2160 feet to the WNW	Closed Status Spill (Unk/Other Cause)
159	121 WEST 119TH STREET	121 WEST 119TH STREET	2276 feet to the WNW	Closed Status Spill (Unk/Other Cause)
35	127 W 119TH ST	127 W 119TH ST	2336 feet to the WNW	Closed Status Tank Failure
239	127 WEST 119TH ST/MANH	127 WEST 119TH STREET	2336 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
240	129 WEST 119TH ST/MANH	129 WEST 119TH STREET	2356 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
313	CONSOLIDATED EDISON	1832 MADISON AVE	568 feet to the NW	Hazardous Waste Generator/Transporter
84	2 WEST 120TH STREET	2 WEST 120TH STREET	1048 feet to the NW	Closed Status Spill (Unk/Other Cause)
31	42 WEST 120TH STREET	42 WEST 120TH STREET	1404 feet to the NW	Closed Status Tank Failure
214	APARTMENT BUILDING	42 WEST 120TH ST	1404 feet to the NW	Closed Status Spill (Misc. Spill Cause)
215	42 WEST 120TH ST/CIBRO	42 WEST 120TH STREET	1404 feet to the NW	Closed Status Spill (Misc. Spill Cause)
100	MANHOLE 19753	58 WEST 120TH ST	1552 feet to the NW	Closed Status Spill (Unk/Other Cause)
113	BROWNSTONE HOUSE	12 WEST 121 STREET	1698 feet to the NW	Closed Status Spill (Unk/Other Cause)
32	24 WEST 121 STREET	24 W 121ST STREET	1814 feet to the NW	Closed Status Tank Failure
127	200 LENOX AVENUE	200 LENOX AVENUE	1836 feet to the NW	Closed Status Spill (Unk/Other Cause)
145	248 LENOX AVE/MANH	248 LENOX AVENUE	2022 feet to the NW	Closed Status Spill (Unk/Other Cause)
163	SPILL NUMBER 0104362	104 WEST 123RD ST	2323 feet to the NW	Closed Status Spill (Unk/Other Cause)
182	127 W 122ND ST	127 W 122ND ST	2477 feet to the NW	Closed Status Spill (Unk/Other Cause)

300	CONED	E120TH ST	476 feet to the NNW	Hazardous Waste Generator/Transporter
301	CON EDISON	E 120 ST S 23 E MADISON AV	476 feet to the NNW	Hazardous Waste Generator/Transporter
16	NYC PARKS	122 ND & 5TH AVE	1232 feet to the NNW	Active Tank Test Failure
39	PELHAM FRITZ RECREATION C	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW	Closed Status Tank Test Failure
91	PARKS REC SYSTEM	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW	Closed Status Spill (Unk/Other Cause)
140	BEHIND HOUSES IN AREA OF	56 WEST 124TH ST	2001 feet to the NNW	Closed Status Spill (Unk/Other Cause)
230	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
231	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
232	CON ED	32 WEST 125TH STREET	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
233	SPILL NUMBER 9811292	32 WEST 123RD STREET	2044 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
147	SPILL NUMBER 9811290	36−38 WEST 123RD ST	2078 feet to the NNW	Closed Status Spill (Unk/Other Cause)
238	APT COMPLEX W/ STORES	282 LENOX AVE	2268 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
161	NYS DEPT OF HUMAN RIGHTS	55 WEST 125TH ST	2311 feet to the NNW	Closed Status Spill (Unk/Other Cause)
165	X	52 WEST 126TH STREET	2330 feet to the NNW	Closed Status Spill (Unk/Other Cause)
167	BASEMENT	271 LENOX AVE	2354 feet to the NNW	Closed Status Spill (Unk/Other Cause)
36	275 LENOX AVE	275 LENOX AVE	2370 feet to the NNW	Closed Status Tank Failure
15	110 LENOX AT 125TH STREET	281 LENOX AVENUE	2440 feet to the NNW	Brownfields Site
37	COMMERCIAL BUILDING	310 LENOX AVE	2559 feet to the NNW	Closed Status Tank Failure
197	71 W. 126TH ST	71 W. 126TH ST	2595 feet to the NNW	Closed Status Spill (Unk/Other Cause)
38	SPILL NUMBER 9911165	75 W. 126TH ST	2608 feet to the NNW	Closed Status Tank Failure
198	75 WEST 126TH STREET	75 WEST 126TH STREET	2608 feet to the NNW	Closed Status Spill (Unk/Other Cause)

Identified Toxic Sites by Category

1678 and 1700 Park Avenue
New York, NY 10035

* Compass directions can vary substantially for sites located very close to the subject property address.

NYSDEC Inactive Haz. Waste Disposal Site Registry −− Total Sites − 2

Database searched at 1 MILE − ASTM required search distance: 1 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
1	231066	PLEASANT AVENUE PLUME TRACKDOWN	PLEASANT AVENUE	3259 feet to the SE
2	203052	VISTA 1	2401 THIRD AVENUE	3872 feet to the NE

Brownfields Sites −− Total Sites − 13

Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
3	14CVCP160M	1901 MADISON AVENUE	1901 MADISON AVENUE	935 feet to the NNE
4	12CBCP034M	23 W. 116 ST AND 1428 FIFTH AVE (2 SITES)	1428 5TH AVENUE	1232 feet to the W
5	12CBCP037M	2211 3RD AVENUE	2211 3RD AVENUE	1322 feet to the E
6	12CBCP033M	23 WEST 116TH, 1428 FIFTH AVENUE	1428 5TH AVENUE	1468 feet to the W
7	C231041	HARLEM PARK	1800−1808 PARK AVE 71 E. 124 ST., 66−70 E 125 ST.	1473 feet to the NNE
8	13CVCP120M	81 WEST 125TH STREET	81 WEST 125TH STREET	1662 feet to the NNE
9	15CVCP122K	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE
10	15CVCP122M	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE
11	15CVCP149M	146 EAST 126TH STREET	146 EAST 126TH STREET	1986 feet to the NE
12	11CBCP004M	CHURCH OF SCIENTOLOGY−SITE A	220 EAST 125TH STREET	2071 feet to the ENE
13	13CVCP115M	5 WEST 125TH	5 WEST 125TH STREET	2088 feet to the N
14	11CBCP005M	CHURCH OF SCIENTOLOGY−SITE B	220 EAST 125TH STREET	2153 feet to the ENE
15	13CVCP091M	110 LENOX AT 125TH STREET	281 LENOX AVENUE	2440 feet to the NNW

Active Tank Test Failures −− Total Sites − 5

Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
16	0515023	NYC PARKS	122 ND & 5TH AVE	1232 feet to the NNW
17	9315466	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW
18	1307857	ABOVE GROUND TANK − TTF	17 WEST 125TH ST	2113 feet to the N
19	0802029	CONVENT	226 EAST 113TH STREET	2217 feet to the SSE
20	1205657	PVT DWELLING − TTF	19−21 EAST 109 ST	2639 feet to the SW

Active Haz Spills (Unknown Causes & Other Causes) −− Total Sites − 7

Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
21	1506992	SOIL	2211 3RD AVE	1324 feet to the E
22	1501648	SOIL	1800 PARK AVE	1366 feet to the NNE
23	0402211	1800 PARK AVE	1800 PARK AVE	1366 feet to the NNE
24	9513238	MORRIS PARK HOUSES −NYCHA	17 EAST 124TH ST	1518 feet to the N
25	9102023	KING TOWERS −NYCHA	90 LENOX AVE	2079 feet to the WSW
26	1509644	NYC PS 155 SCHOOL	319 E117TH ST	2240 feet to the SE
27	1508795	CONSTRUCTION SITE	225 EAST 126TH ST	2448 feet to the ENE

Active Haz Spills (Miscellaneous Spill Causes) −− Total Sites − 1

Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
28	9515731	25 PRECINCT NYPD −DDC	120 EAST 119TH STREET	382 feet to the SE

Closed Status Tank Failures −− Total Sites − 10

Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
29	0310572	APARTMENT BUILDING	123 E. 116TH STREET	838 feet to the S
30	9410094	2021 LEXINGTON AVENUE	2021 LEXINGTON AVENUE	1187 feet to the ENE
31	9313894	42 WEST 120TH STREET	42 WEST 120TH STREET	1404 feet to the NW

32	9908095	24 WEST 121 STREET	24 W 121ST STREET	1814 feet to the NW
33	9106395	78−80 E 127TH ST/NYCHPD	78−80 E 127TH ST	2056 feet to the NNE
34	9010952	105 LENOX AVE/HARLEM HOSP	105 LENOX AVENUE	2291 feet to the W
35	9111198	127 W 119TH ST	127 W 119TH ST	2336 feet to the WNW
36	0411801	275 LENOX AVE	275 LENOX AVE	2370 feet to the NNW
37	0409042	COMMERCIAL BUILDING	310 LENOX AVE	2559 feet to the NNW
38	9911165	SPILL NUMBER 9911165	75 W. 126TH ST	2608 feet to the NNW

Closed Status Tank Test Failures −− Total Sites − 28 **Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile**

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
39	0602813	PELHAM FRITZ RECREATION C	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW
40	0203815	JACOB'S RESIDENCE	203 EAST 117TH ST	1312 feet to the SE
41	0508613	STORE FRONT	124 EAST 124TH ST.	1321 feet to the NE
42	8805777	CLOSED−LACKOF RECENT INFO	158 E 115TH ST	1367 feet to the S
43	0209842	DUNLEVY MILBANK CHILDREN	14−32 WEST 118TH STREET	1398 feet to the WNW
44	0008608	UNKNOWN	222 EAST 119TH ST	1505 feet to the ESE
45	9004771	MORRIS PARK SENIOR	17 EAST 124TH STREET	1518 feet to the N
46	0000067	RESIDENCE	212 EAST 122ND STREET	1537 feet to the E
47	0514031	TAINO TOWER	2253 3RD AVE	1543 feet to the E
48	0000963	TAINO TOWERS − TTF	2253 3RD AVE	1543 feet to the E
49	0000962	TAINO TOWERS	2253 3RD AVE	1543 feet to the E
50	0403282	X	1944 MADISON AVE	1565 feet to the N
51	9402166	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW
52	9108459	1824 PARK AVE/SUNOCO	1824 PARK AVE	1778 feet to the NNE
53	9504621	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
54	9402165	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
55	9315373	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
56	9100385	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
57	8809431	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
58	0805163	APART	86 WEST 119TH STREET	1822 feet to the WNW
59	9808968	APARTMENT BLDG − TTF	120TH ST & SECOND AVE	1866 feet to the ESE
60	9802381	THE EAST DRIVE H.D.F.C.	205 EAST 124TH STREET	1906 feet to the ENE
61	9500828	CORSI HOUSES (JEFFERSON) −NYCHA	306 EAST 117TH STREET	2136 feet to the SE
62	0601542	CHURCH	232 EAST 113TH STREET	2267 feet to the SSE
63	8809618	AMOCO	255 EAST 125TH STREET	2421 feet to the ENE
64	9812531	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE
65	9808458	JACKIE ROBINSON HOUSING	110 EAST 129TH ST	2571 feet to the NE
66	9315465	JACKIE ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE

Closed Status Spills (Unknown Causes & Other Causes) −− Total Sites − 137 **Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile**

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
67	1301722	SERVICE BOX 19779	E120TH ST/PARK AVE	288 feet to the NE
68	9908760	VAULT 6340	EAST 118TH ST/ PARK AVE	288 feet to the S
69	0813381	VACANT LOT	127 EAST 119TH ST	454 feet to the ESE
70	0890186	207583; SE PARK AV E 117 ST	SE PARK AV E 117 ST	538 feet to the SSW
71	0703216	PARKING LOT	1980 LEXINGTON AVE	580 feet to the ENE
72	0311320	SPILL NUMBER 0311320	127 EAST 117TH ST	646 feet to the SSE
73	9906696	MANHOLE 50789	MADISON AV & 121ST ST	662 feet to the N
74	1004210	SERVICE BOX 19135	91 EAST 116 ST	705 feet to the SW
75	0406279	OPEN EXCAVATION	91 EAST 116 ST.	705 feet to the SW
76	9912403	SB 19622	158 E. 119TH ST	710 feet to the SE
77	9912404	SB 19623	170 E.119TH ST	801 feet to the ESE
78	0890369	209996; E E 117 ST ST	E E 117 ST ST	834 feet to the W

79	0613636	VACANT LOT	1761 PARK AVENUE	859 feet to the NE
80	9808122	MAN HOLE (19150)	IFO 116 E. 116TH ST	924 feet to the S
81	9901217	MANHOLE #39219	E 122ND ST & LEXINGTON AV	1008 feet to the ENE
82	0650090	177 EAST 117TH STREET	177 EAST 117TH STREET	1009 feet to the SE
83	0013256	HARLEM COURTHOUSE	170 EAST 121ST STREET	1029 feet to the E
84	9208787	2 WEST 120TH STREET	2 WEST 120TH STREET	1048 feet to the NW
85	0801742	DUTCH REFORM CHURCH OF HARLEM	171 EAST 121 STREET	1098 feet to the E
86	1206234	MAN HOLE 45730	NORTH WEST CORNER EAST 120 ST AND 3 AVE	1168 feet to the ESE
87	0914301	217428; 118 ST AND 3 AVE	118 ST AND 3 AVE	1168 feet to the SE
88	0408556	VAULT #VS−5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE
89	0313016	VAULT # 5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE
90	0513522	MANHOLE M56965	WEST 116 ST & 5 AVE	1210 feet to the WSW
91	0813485	PARKS REC SYSTEM	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW
92	9812163	SERVICE BOX 45747	2236 3RD AVE	1248 feet to the E
93	0201236	2236 3RD AVE	2236 3RD AVE OFF OF 128 EAST ST	1248 feet to the E
94	9812162	SERVICE BOX 45748	2238 3RD AVE	1262 feet to the E
95	0305658	OPPOSITE OF 3 WEST 116 ST	OPPOSITE OF 3 WEST 116 ST	1320 feet to the W
96	9304099	79 E 124TH ST	79 E 124TH ST	1366 feet to the NNE
97	0107880	63 W 119TH ST	63 W 119TH ST	1508 feet to the WNW
98	0304253	SPILL NUMBER 0304253	65 W 119TH ST	1525 feet to the WNW
99	0400692	VAULT #9153	3RD AVE / E 123 ST	1546 feet to the ENE
100	0009907	MANHOLE 19753	58 WEST 120TH ST	1552 feet to the NW
101	0002184	MANHOLE 45668	3RD AVE/EAST 115TH	1577 feet to the SSE
102	9512216	APPLE BANK	124 EAST 125TH ST	1584 feet to the NE
103	0302791	2ND AVE SUBWAY PROJECT − NYCT	PARK AVE/125TH ST	1594 feet to the NNE
104	0301445	125TH ST BTWN MADISON −NYCT	125TH ST PARK& MADISON SO	1595 feet to the NNE
105	9802907	HOUSING PROJECT	1740 MADISON AVE	1605 feet to the SW
106	0806548	DRUM RUN	228 EAST 117 ST BTW 2ND & 3RD AVE	1623 feet to the SE
107	0890227	208153; MADISON AVE	MADISON AVE	1637 feet to the NNE
108	9313703	79 WEST 119 STREET	79 WEST 119 STREET	1650 feet to the WNW
109	9703960	PRIVATE RESIDENCE	236 E 118TH ST PT 9	1658 feet to the SE
110	0814485	213778; 222 E 123 ST	222 E 123 ST	1666 feet to the E
111	0800328	ROADWAY	MADISON AVE/EAST 113 ST	1691 feet to the SW
112	0206541	SPILL NUMBER 0206541	79 E 125TH ST	1693 feet to the NNE
113	0701787	BROWNSTONE HOUSE	12 WEST 121 STREET	1698 feet to the NW
114	9907360	MH39246	E 125TH ST & LEXINGTON AV	1710 feet to the NE
115	9905454	SPILL NUMBER 9905454	125TH ST & LEXINGTON AV	1710 feet to the NE
116	9809077	MANHOLE 39242	125TH ST /LEXINGTON AVE	1710 feet to the NE
117	0914388	218014; E 125 ST AND LEXINGTON AVE	E 125 ST AND LEXINGTON AVE	1710 feet to the NE
118	0300354	2ND AVE SUBWAY −NYCT	LEXINGTON & 125TH ST	1710 feet to the NE
119	9808710	MANHOLE 39163	EAST SIDE OF LEXINGTON AV	1712 feet to the S
120	0407102	DEMOLISHED BUILDING	2000−2002 5TH AVE	1734 feet to the N
121	0601808	CHURCH	33 WEST 115 & 36 115TH STREET	1741 feet to the W
122	9301099	246 E 121 ST	246 E 121ST	1762 feet to the ESE
123	0306729	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
124	0205660	JOHNSON HOUSES	1809 LEXINGTON AV	1792 feet to the S
125	0000572	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S
126	0201534	2ND AVE SUBWAY −NYCT	125TH ST/5TH AVE	1828 feet to the N
127	9608875	200 LENOX AVENUE	200 LENOX AVENUE	1836 feet to the NW
128	9906343	MANHOLE 55068	120TH ST & 2ND AVE	1866 feet to the ESE
129	0913958	215193; E 120 ST AND 2ND AVE	E 120 ST AND 2ND AVE	1866 feet to the ESE
130	0602921	MANHOLE #1864	EAST 120 STREET & 2 AVENUE	1866 feet to the ESE
131	0890388	210473; 2ND AVE	2ND AVE	1867 feet to the SE

132	0311039	ROAD INTERSECTION	E. 112 TH ST AND PARK AVE	1869 feet to the SSW
133	0105881	VAULT 2349	MADISON/E 112TH ST	1903 feet to the SW
134	1205465	CROSSWALKS	125TH / 3RD AVE	1956 feet to the ENE
135	9809080	SPILL NUMBER 9809080	E 112 ST & LEXINGTON AV	1972 feet to the S
136	9808280	MANHOLE 39156	E 112TH ST/LEXINGTON AV	1972 feet to the S
137	0914652	219438; LEXINGTON AVE AND 112TH ST	LEXINGTON AVE AND 112TH ST	1972 feet to the S
138	0800725	LEXINGTON AVE	LEXINGTON AVE/EAST 112 ST	1972 feet to the S
139	9706971	JEFFERSON HOUSES	2089 3RD AVE	1999 feet to the SSE
140	1306182	BEHIND HOUSES IN AREA OF	56 WEST 124TH ST	2001 feet to the NNW
141	0402850	138 EAST 112TH ST	138 EAST 112TH ST	2004 feet to the SSW
142	9709656	NEW CONSTRUCTION	81 WEST 115TH ST	2004 feet to the W
143	9906989	MAN HOLE #55020	116TH ST / 2ND AV	2016 feet to the SE
144	0011175	SERVICE BOX 55036	2276 2ND AVE	2016 feet to the SE
145	9010506	248 LENOX AVE/MANH	248 LENOX AVENUE	2022 feet to the NW
146	0212478	64 E 127TH ST	64 E 127TH ST	2063 feet to the NNE
147	9811290	SPILL NUMBER 9811290	36−38 WEST 123RD ST	2078 feet to the NNW
148	0308444	SPILL NUMBER 0308444	W. 116TH ST & LENOX AVE	2083 feet to the W
149	0708523	IMPACTED SOIL FOUND IN EXCAVATION	PARK AVE & EAST 127 STREET	2133 feet to the NNE
150	0513230	STREET SPILL	SECOND AVE & E 123 ST	2144 feet to the E
151	0914359	217860; 2 AVE AND 115TH ST	2 AVE AND 115TH ST	2150 feet to the SSE
152	0890451	208234; NWC E 115 ST 2ND AV	NWC E 115 ST 2ND AV	2150 feet to the SSE
153	0205599	VAULT 5975	EAST 115TH ST AT 2ND AV	2150 feet to the SSE
154	0908562	BETWEEN LENOX AND 7TH AVE	109 WEST 119TH ST	2160 feet to the WNW
155	0210753	BWTEEEN 2ND & 3RD AV −NYCT	125TH ST 2ND & 3RD AVE	2176 feet to the ENE
156	9814395	MANHOLE 45805	EAST 126TH ST / 3RD AVE	2189 feet to the ENE
157	1008098	SITE F/NEW CONSTRUCTION	169 EAST 111 ST	2216 feet to the S
158	1004567	ROADWAY SURFACE	EAST 120TH STREET BW 1ST AND 2ND AVE	2222 feet to the ESE
159	0605155	121 WEST 119TH STREET	121 WEST 119TH STREET	2276 feet to the WNW
160	9005731	2005 MADISON AV & 128TH	2005 MADISON AV	2286 feet to the NNE
161	9514120	NYS DEPT OF HUMAN RIGHTS	55 WEST 125TH ST	2311 feet to the NNW
162	0012590	SB 20601	WEST 127TH ST/ 5TH AVE	2313 feet to the N
163	0104362	SPILL NUMBER 0104362	104 WEST 123RD ST	2323 feet to the NW
164	0210651	SOUTHSIDE OF −NYCT	EAST 116TH STREET	2329 feet to the SE
165	0312854	X	52 WEST 126TH STREET	2330 feet to the NNW
166	0202065	SPILL NUMBER 0202065	2067 5TH AVE	2352 feet to the N
167	1010494	BASEMENT	271 LENOX AVE	2354 feet to the NNW
168	0411494	LOT NEXT TO AMOCO STATION	249 EAST 125TH ST	2373 feet to the ENE
169	0708201	VACANT LOT	346 E. 119TH ST	2384 feet to the ESE
170	0011504	SPILL NUMBER 0011504	20 WEST 127TH ST	2387 feet to the N
171	9310338	2365 FIRST AVENUE	2365 FIRST AVENUE	2399 feet to the E
172	0709958	PRIVATE HOME	12 EAST 128TH ST	2408 feet to the NNE
173	9814391	MAN HOLE #45816	E 127TH ST & 3RD AVE	2414 feet to the ENE
174	0814398	213284; 3 AVE AND E 127 ST ST	3 AVE AND E 127 ST ST	2414 feet to the ENE
175	0405048	CONED MANHOLE #20977	EAST 127/3RD AVE	2414 feet to the ENE
176	0412552	MANHOLE 45629	E 111TH ST & 3RD AV	2418 feet to the S
177	0103578	APARTMENT BUILDING	332 E 116TH ST	2436 feet to the SE
178	0914366	217897; 2 AVENUE AND 125TH STREET	2 AVENUE AND 125TH STREET	2439 feet to the ENE
179	0904431	IS 45M− NYSCA	2351 1ST AVE	2442 feet to the ESE
180	0602136	MANHOLE #62325	2 AVENUE & 113 STREET	2451 feet to the SSE
181	9703094	LEXINGTON AV/E 128TH ST	LEXINGTON AV/E.128TH ST	2472 feet to the NE
182	9112299	127 W 122ND ST	127 W 122ND ST	2477 feet to the NW
183	9809172	MANHOLE #39138	EAST 110 AND LEXINGTON AV	2477 feet to the SSW
184	9809081	MANHOLE #39138	E 110TH ST & LEXINGTON AV	2477 feet to the SSW

185	0105211	SPILL NUMBER 0105211	11 WEST 127TH ST	2480 feet to the N
186	0605241	M AND M GROCERY	2337 1ST AVE	2510 feet to the ESE
187	0906507	SERVICE BOX 42143	PARK AVE 128TH/129TH	2522 feet to the NNE
188	0305966	2ND AVE SUBWAY −NYCT	125TH & 126TH ST	2530 feet to the ENE
189	0890189	207627; E ST	E ST	2553 feet to the S
190	9910794	JACKIE ROBINSON CONSOLID. −NYCHA	129 E.128TH ST	2571 feet to the NE
191	9907036	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE
192	0610058	I PT OF UNKN SUBSTANCE IN SB 21083	105 EAST 128 STREET	2571 feet to the NE
193	0001625	ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE
194	9902912	1890 PARK AVE CORP	1890 PARK AVE	2574 feet to the NNE
195	0605629	APART	212 E. 111TH ST	2581 feet to the S
196	9909067	PVT APARTMENT BLDG	214 E.111TH ST	2594 feet to the S
197	9911163	71 W. 126TH ST	71 W. 126TH ST	2595 feet to the NNW
198	0104097	75 WEST 126TH STREET	75 WEST 126TH STREET	2608 feet to the NNW
199	0007704	MANHOLE 53842	EAST 118 TH ST/1ST AVE	2610 feet to the SE
200	9913838	MANHOLE 53875	1ST AVE/120TH ST	2611 feet to the ESE
201	9913836	MANHOLE 53880	1ST AVE/E120TH ST	2611 feet to the ESE
202	9900785	MANHOLE 53864	E 120TH ST / 1ST AVE	2611 feet to the ESE
203	1000204	VS2027 VAULT	1RST AVE AND EAST 120ST	2611 feet to the ESE

Closed Status Spills (Miscellaneous Spill Causes) −− Total Sites − 40 **Database searched at 1/2 MILE − ASTM required search distance: 1/2 Mile**

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
204	1301696	TRUCK	NEAR EAST 120TH AND PARK	288 feet to the NE
205	9210790	120 EAST 119TH STREET	120 EAST 119TH STREET	382 feet to the SE
206	0504233	132 E 119TH ST	132 E 119TH ST	477 feet to the SE
207	0505459	MANHOLE 42069	SE CRNR 117THST/PARK AVE	538 feet to the SSW
208	9415276	113 EAST 117TH STREET	113 EAST 117TH STREET	543 feet to the S
209	0608531	ST PAULS RECTORY	113 EAST 117TH STREET	543 feet to the S
210	8704606	119TH ST.& LEXINGTON AVE.	119TH ST. & LEXINGTON AVE	631 feet to the ESE
211	1215698	UNKNOWN RESIDENCE	124 EAST 117TH ST	746 feet to the S
212	9111042	1883 MADISON AVE	1883 MADISON AVE	955 feet to the NNE
213	8907609	49 WEST 119TH ST/MANH	49 WEST 119TH STREET	1393 feet to the WNW
214	9411587	APARTMENT BUILDING	42 WEST 120TH ST	1404 feet to the NW
215	8803777	42 WEST 120TH ST/CIBRO	42 WEST 120TH STREET	1404 feet to the NW
216	9910337	VAULT #5033	1695 MADISON AV	1463 feet to the SW
217	9313540	MORRIS PK SENIOR CITIZENS	17 EAST 124TH STREET	1518 feet to the N
218	9309711	MORRIS PARK SENIOR CIT.	17 EAST 124TH STREET	1518 feet to the N
219	9810692	SPILL NUMBER 9810692	1944 MADISON AV	1565 feet to the N
220	9810690	MT MORRIS PARK BATH HOUSE	1944 MADISON AVE	1565 feet to the N
221	9507018	1944 MADISON AVENUE	1944 MADISON AVENUE	1565 feet to the N
222	0508072	STREET SPILL	124TH ST 5TH AVE	1589 feet to the N
223	9100577	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW
224	8809818	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW
225	0010119	WEST 115 ST	BET 5TH AV & LENOX AV	1791 feet to the W
226	9303636	JOHNSON HOUSES	165 EAST 165TH STREET	1792 feet to the S
227	8606210	163 E.112TH ST. NYC./NO.2 O	163 E. 112TH ST.	1792 feet to the S
228	0810730	HARLEM DAY CHARTER SCHOOL	230 E 123RD ST	1867 feet to the E
229	8600055	METRO NORTH	126TH ST. & PARK AVE.	1874 feet to the NNE
230	0301202	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW
231	0301201	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW
232	0002517	CON ED	32 WEST 125TH STREET	2017 feet to the NNW
233	9811292	SPILL NUMBER 9811292	32 WEST 123RD STREET	2044 feet to the NNW
234	9604496	1350 5TH AVE	1350 5TH AVE	2079 feet to the WSW

235	9209724	70 LENOX AVE	70 LENOX AVE	2079 feet to the WSW
236	8708238	KING TOWERS	90 LENOX AVE	2079 feet to the WSW
237	9112852	163 E 111TH ST	163 E 111TH ST	2177 feet to the S
238	1311426	APT COMPLEX W/ STORES	282 LENOX AVE	2268 feet to the NNW
239	9008744	127 WEST 119TH ST/MANH	127 WEST 119TH STREET	2336 feet to the WNW
240	9008277	129 WEST 119TH ST/MANH	129 WEST 119TH STREET	2356 feet to the WNW
241	9104068	112−114 W 116TH ST	112−114 W 116TH ST	2384 feet to the W
242	0103459	SPILL NUMBER 0103459	24 WEST 127TH ST	2406 feet to the N
243	9711337	BP AMOCO STATION #13401	255 EAST 125TH ST	2421 feet to the ENE

Petroleum Bulk Storage Sites −− Total Sites − 13 **Database searched at 1/8 MILE − ASTM required search distance: Property & Adjacent**

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
244	2−607339	MADISON PARK PARTNERSHIP HOUSING	59 EAST 119TH ST.	255 feet to the NW
245	2−470244	50 EAST 119TH STREET	50 EAST 119TH STREET	305 feet to the WNW
246	2−471445	PROVIDENCE BAPTIST CHURCH	50 EAST 119TH STREET	305 feet to the WNW
247	2−602634	1829 MADISON AVE	1829 MADISON AVE	305 feet to the WNW
248	2−217506	25 PCT	120 EAST 119TH STREET	395 feet to the SE
249	NY01714	AYERS MOVERS	1721 PARK AVE	399 feet to the ENE
250	2−601028	61 EAST 117 STREET	61 EAST 117 STREET	449 feet to the SW
251	2−353949	PUBLIC SCHOOL 79 − MANHATTAN M079	55 EAST 120TH STREET	456 feet to the N
252	2−609820	CRP 1661 PARK AVENUE LLC	105 EAST 117 ST.	517 feet to the S
253	2−606916	ST. PAUL SCHOOL	114 EAST 118TH STREET	522 feet to the SSE
254	NY09430	ST.PAULS CHURCH & SCHOOL	114 E 118 ST	522 feet to the SSE
255	2−609983	1652 PARK AVENUE ASSOC. LLC	1648 PARK AVENUE	584 feet to the SSW
256	2−609151	MADISON COURT ASSOC, LP	58 EAST 117TH STREET	610 feet to the SW

Hazardous Waste Generators, Transporters −− Total Sites − 82 **Database searched at 1/8 MILE − ASTM required search distance: Property & Adjacent**

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
257	NYD981562283	GE−CEL CLEANERS	1694 PARK AVE	44 feet to the SSW*
258	NYP004298659	CON EDISON SERVICE BOX: 42084	1700 PARK AVE	119 feet to the NNE*
259	NYP004182044	CONED	71 E 119TH ST	143 feet to the NNW*
260	NYP004298659	CON EDISON	F/O 1700 PARK AVE	151 feet to the ENE*
261	NYP004298642	CON EDISON SERVICE BOX: 42076	1680 PARK AVE	160 feet to the SSW*
262	NYP004298642	CON EDISON	F/O 1680 PARK AVE	161 feet to the S*
263	NYP004182044	CON EDISON	67 W 119TH ST & LENOX AVE	177 feet to the NW*
264	NYP004286605	CON EDISON	FO 63 E 119TH ST	200 feet to the WNW
265	NYP004298352	CON EDISON	68 E 120TH ST	200 feet to the N
266	NYP004289765	CON EDISON	FO 1709 PARK AVE NO 119TH ST	208 feet to the ENE
267	NYP004298410	CON EDISON	64 E 120TH ST	219 feet to the N
268	NYP004182127	CONED	62 E 120TH ST	231 feet to the N
269	NYP004182051	CONED	61 E 119TH ST	232 feet to the NW
270	NYP004298402	VEOLIA ENERGY NORTH AMERICA	58 E 120TH ST	256 feet to the NNW
271	NYP004182127	CON EDISON	E 120TH ST & PARK AVE	288 feet to the NE
272	NYP004188645	CONSOLIDATED EDISON	PARK AVE & EAST 120 ST	288 feet to the NE
273	NYP004182093	CON EDISON	E 118TH ST& PARK AVE	288 feet to the S
274	NYP004761839	CON EDISON	E 118 ST & PARK AVE	288 feet to the S
275	NYP004774170	CON EDISON	SEC E 118 ST & PARK AVE	288 feet to the S
276	NYP004298345	CON EDISON	F/O 65 E 120TH ST	314 feet to the N
277	NYP004298436	CON EDISON	1835 MADISON AVE	318 feet to the NW
278	NYP004197406	CON EDISON	117 E 119TH ST	364 feet to the ESE
279	NYP004197406	CONSOLIDATED EDISON	FRONT OF 117 EAST 119 STREET	367 feet to the ESE
280	NYP004167748	CONSOLIDATED EDISON	F/O 111 E 118TH ST	385 feet to the SSE
281	NYP004298089	CON EDISON	58 E 121ST ST	389 feet to the N

282	NYP004298097	CON EDISON	68 E 121ST ST	389 feet to the N
283	NYP004298105	CON EDISON	72 E 121ST ST	389 feet to the N
284	NYP004298113	VEOLIA ENERGY NORTH AMERICA	80 E 121ST ST	389 feet to the N
285	NYP004626438	CON EDISON	50 E 121 ST	389 feet to the N
286	NYR000009597	NYC BOARD OF EDUCATION − PS 79	55 EAST 120TH STREET	389 feet to the N
287	NYP004201174	CONSOLIDATED EDISON	MADISON AVE & E 119TH ST	391 feet to the WNW
288	NYP004345849	CON EDISON	100 E 118 ST	398 feet to the S
289	NYP004740734	CON EDISON	100 E 118 ST	398 feet to the S
290	NYP004166526	CON EDISON	130 E 119TH ST W OF LEXINGTON AVE	409 feet to the SE
291	NYP004182093	CONED	117 E 118TH ST	412 feet to the SSE
292	NYP004298394	CON EDISON SERVICE BOX: 42070	1664 PARK AVE	423 feet to the SSW
293	NYP004298894	CON EDISON	1664 PARK AVE	423 feet to the SSW
294	NYP004299905	CON EDISON	FT OF 1815−1817 MADISON AVE & 118TH ST	426 feet to the W
295	NYP004299897	CON EDISON	FT OF 1816−1818 MADISON AVE & 118TH ST	446 feet to the W
296	NYP004182085	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W
297	NYP004182143	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W
298	NYP004299897	CON EDISON SERVICE BOX: 50772	MADISON AVE & 118TH ST	471 feet to the W
299	NYP004299905	CON EDISON SERVICE BOX: 50775	MADISON AVE & 118TH ST	471 feet to the W
300	NYP004182119	CONED	E120TH ST	476 feet to the NNW
301	NYP004526901	CON EDISON	E 120 ST S 23 E MADISON AV	476 feet to the NNW
302	NYP004695771	CON EDISON	1787 MADISON AVE & 117 ST	501 feet to the WSW
303	NYR000053082	NYCHA − ROBINSON	1940 LEXINGTON AVE	525 feet to the E
304	NYP004167805	CONSOLIDATED EDISON	N/S E 121 ST 165' EAST OF PARK	537 feet to the NE
305	NYP004188942	CON EDISON	E 121ST ST & PARK AVE	537 feet to the NE
306	NYP004154258	CONSOLIDATED EDISON	SEC E 117TH ST & PARK AVE	538 feet to the SSW
307	NYP004223855	CONSOLIDATED EDISON	S/W/C E 117TH ST 7 PARK AVE	538 feet to the SSW
308	NYP004423422	CON EDISON	F/O 58 E 121 ST	544 feet to the N
309	NYP004422176	CON EDISON	65 E 121 ST & PARK AVE	550 feet to the NNE
310	NYP004166872	CON EDISON	125 E 117TH ST E OF 3RD AVE	551 feet to the SSE
311	NYP004298337	CON EDISON	115 E 117TH ST	551 feet to the SSE
312	NYP004167862	CONSOLIDATED EDISON	1748 PARK AVE	551 feet to the NNE
313	NYP004166153	CONSOLIDATED EDISON	1832 MADISON AVE	568 feet to the NW
314	NYR000213579	NYC DEPT OF EDUCATION − PS 149M TANDEM WITH M207	34 WEST 118TH STREET	571 feet to the W
315	NYP004794830	CON EDISON	1932 LEXINGTON AVE	573 feet to the SE
316	NYP004428348	CON EDISON	F/O 104 EAST 117TH ST	579 feet to the S
317	NYP004474789	CON EDISON	F/O 104 E 117TH ST	579 feet to the S
318	NYP004622700	CON EDISON	11 E 118 ST & 5 AV	600 feet to the WNW
319	NYP004188942	CONSOLIDATED EDISON	FRONT OF 1743 PARK AVE	605 feet to the NE
320	NYP004299913	CON EDISON	FT OF 22 E 118TH ST E OF 15TH AVE	613 feet to the W
321	NYP004296869	CON EDISON	F OF 1934 LEXINGTON AVE & 119TH ST	613 feet to the ESE
322	NYP004315644	CON EDISON	FO 111 E 120 ST	616 feet to the E
323	NYP004188132	CON EDISON	E 119TH ST & LEXINGTON AVE	631 feet to the ESE
324	NYP004296430	CON EDISON	NW COR LEXINGTON AVE & 119TH ST	631 feet to the ESE
325	NYP004298071	CON EDISON	55 E 121ST ST	641 feet to the NNE
326	NYP004420220	CON EDISON	73 E 121 ST	641 feet to the NNE
327	NYP004677514	CON EDISON	73 E 121ST ST & MADISON AVE	641 feet to the NNE
328	NYP004688008	CON EDISON	60 E 122 ST MADISON AV	641 feet to the NNE
329	NYR000085746	HENRY J CARTER SPECIALITY HOSPITAL	1879 MADISON AVE	641 feet to the NNE
330	NYR000191049	NYC HEALTH & HOSPITAL CORP	1752 PARK AVENUE	641 feet to the NNE
331	NYP004182143	CONED	20 E 118TH ST	649 feet to the W
332	NYP004298428	CON EDISON	104 E 117TH ST	649 feet to the S
333	NYP004310819	CON EDISON	110 E 117 ST	649 feet to the S
334	NYP004065215	CONSOLIDATED EDISON	V5731−MADISON & 117TH ST	654 feet to the WSW

335	NYP004426276	CON EDISON	S/W/C MADISON AVE E 117 ST	654 feet to the WSW
336	NYP004167813	CON EDISON	N SIDE E 121ST ST 240 FEET E	656 feet to the ENE
337	NYP004188694	CONSOLIDATED EDISON	E 121ST ST B/T LEXINGTON & PARK	656 feet to the ENE
338	NYP004297453	CON EDISON	F/O 132 E 121ST ST	656 feet to the ENE

Historic Utility Sites −− Total Sites − 1

Database searched at 1/8 MILE − ASTM required search distance: Property & Adjacent

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
339	CE105	121ST ST	128−130 E 121ST ST	659 feet to the ENE

Hazardous Substance Waste Disposal Sites −− Total Sites − 1

Database searched at 1/2 MILE − Non−ASTM Database

MAP ID	FACILITY ID	FACILITY NAME	FACILITY STREET	DISTANCE & DIRECTION
340		ODYSSEY HOUSE	219 E. 121ST STREET	1577 feet to the E

Identified Toxic Sites by Proximity

1678 and 1700 Park Avenue, New York, NY 10035

* Compass directions can vary substantially for sites located very close to the subject property address.

Map Id#	Site Name	Site Street	Approximate Distance & Direction From Property	Toxic Site Category
257	GE−CEL CLEANERS	1694 PARK AVE	44 feet to the SSW*	Hazardous Waste Generator/Transporter
258	CON EDISON SERVICE BOX: 42084	1700 PARK AVE	119 feet to the NNE*	Hazardous Waste Generator/Transporter
259	CONED	71 E 119TH ST	143 feet to the NNW*	Hazardous Waste Generator/Transporter
260	CON EDISON	F/O 1700 PARK AVE	151 feet to the ENE*	Hazardous Waste Generator/Transporter
261	CON EDISON SERVICE BOX: 42076	1680 PARK AVE	160 feet to the SSW*	Hazardous Waste Generator/Transporter
262	CON EDISON	F/O 1680 PARK AVE	161 feet to the S*	Hazardous Waste Generator/Transporter
263	CON EDISON	67 W 119TH ST & LENOX AVE	177 feet to the NW*	Hazardous Waste Generator/Transporter
264	CON EDISON	FO 63 E 119TH ST	200 feet to the WNW	Hazardous Waste Generator/Transporter
265	CON EDISON	68 E 120TH ST	200 feet to the N	Hazardous Waste Generator/Transporter
266	CON EDISON	FO 1709 PARK AVE NO 119TH ST	208 feet to the ENE	Hazardous Waste Generator/Transporter
267	CON EDISON	64 E 120TH ST	219 feet to the N	Hazardous Waste Generator/Transporter
268	CONED	62 E 120TH ST	231 feet to the N	Hazardous Waste Generator/Transporter
269	CONED	61 E 119TH ST	232 feet to the NW	Hazardous Waste Generator/Transporter
244	MADISON PARK PARTNERSHIP HOUSING	59 EAST 119TH ST.	255 feet to the NW	Petroleum Bulk Storage Site
270	VEOLIA ENERGY NORTH AMERICA	58 E 120TH ST	256 feet to the NNW	Hazardous Waste Generator/Transporter
67	SERVICE BOX 19779	E120TH ST/PARK AVE	288 feet to the NE	Closed Status Spill (Unk/Other Cause)
68	VAULT 6340	EAST 118TH ST/ PARK AVE	288 feet to the S	Closed Status Spill (Unk/Other Cause)
204	TRUCK	NEAR EAST 120TH AND PARK	288 feet to the NE	Closed Status Spill (Misc. Spill Cause)
271	CON EDISON	E 120TH ST & PARK AVE	288 feet to the NE	Hazardous Waste Generator/Transporter
272	CONSOLIDATED EDISON	PARK AVE & EAST 120 ST	288 feet to the NE	Hazardous Waste Generator/Transporter
273	CON EDISON	E 118TH ST& PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
274	CON EDISON	E 118 ST & PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
275	CON EDISON	SEC E 118 ST & PARK AVE	288 feet to the S	Hazardous Waste Generator/Transporter
245	50 EAST 119TH STREET	50 EAST 119TH STREET	305 feet to the WNW	Petroleum Bulk Storage Site
246	PROVIDENCE BAPTIST CHURCH	50 EAST 119TH STREET	305 feet to the WNW	Petroleum Bulk Storage Site
247	1829 MADISON AVE	1829 MADISON AVE	305 feet to the WNW	Petroleum Bulk Storage Site
276	CON EDISON	F/O 65 E 120TH ST	314 feet to the N	Hazardous Waste Generator/Transporter
277	CON EDISON	1835 MADISON AVE	318 feet to the NW	Hazardous Waste Generator/Transporter
278	CON EDISON	117 E 119TH ST	364 feet to the ESE	Hazardous Waste Generator/Transporter
279	CONSOLIDATED EDISON	FRONT OF 117 EAST 119 STREET	367 feet to the ESE	Hazardous Waste Generator/Transporter
28	25 PRECINCT NYPD −DDC	120 EAST 119TH STREET	382 feet to the SE	Active Haz Spill (Misc. Spill Cause)
205	120 EAST 119TH STREET	120 EAST 119TH STREET	382 feet to the SE	Closed Status Spill (Misc. Spill Cause)
280	CONSOLIDATED EDISON	F/O 111 E 118TH ST	385 feet to the SSE	Hazardous Waste Generator/Transporter
281	CON EDISON	58 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
282	CON EDISON	68 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
283	CON EDISON	72 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
284	VEOLIA ENERGY NORTH AMERICA	80 E 121ST ST	389 feet to the N	Hazardous Waste Generator/Transporter
285	CON EDISON	50 E 121 ST	389 feet to the N	Hazardous Waste Generator/Transporter
286	NYC BOARD OF EDUCATION − PS 79	55 EAST 120TH STREET	389 feet to the N	Hazardous Waste Generator/Transporter
287	CONSOLIDATED EDISON	MADISON AVE & E 119TH ST	391 feet to the WNW	Hazardous Waste Generator/Transporter
248	25 PCT	120 EAST 119TH STREET	395 feet to the SE	Petroleum Bulk Storage Site
288	CON EDISON	100 E 118 ST	398 feet to the S	Hazardous Waste Generator/Transporter
289	CON EDISON	100 E 118 ST	398 feet to the S	Hazardous Waste Generator/Transporter
249	AYERS MOVERS	1721 PARK AVE	399 feet to the ENE	Petroleum Bulk Storage Site
290	CON EDISON	130 E 119TH ST W OF LEXINGTON AVE	409 feet to the SE	Hazardous Waste Generator/Transporter

291	CONED	117 E 118TH ST	412 feet to the SSE	Hazardous Waste Generator/Transporter
292	CON EDISON SERVICE BOX: 42070	1664 PARK AVE	423 feet to the SSW	Hazardous Waste Generator/Transporter
293	CON EDISON	1664 PARK AVE	423 feet to the SSW	Hazardous Waste Generator/Transporter
294	CON EDISON	FT OF 1815−1817 MADISON AVE & 118TH ST	426 feet to the W	Hazardous Waste Generator/Transporter
295	CON EDISON	FT OF 1816−1818 MADISON AVE & 118TH ST	446 feet to the W	Hazardous Waste Generator/Transporter
250	61 EAST 117 STREET	61 EAST 117 STREET	449 feet to the SW	Petroleum Bulk Storage Site
69	VACANT LOT	127 EAST 119TH ST	454 feet to the ESE	Closed Status Spill (Unk/Other Cause)
251	PUBLIC SCHOOL 79 − MANHATTAN M079	55 EAST 120TH STREET	456 feet to the N	Petroleum Bulk Storage Site
296	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W	Hazardous Waste Generator/Transporter
297	CON EDISON	E 118TH ST & MADISON AVE	471 feet to the W	Hazardous Waste Generator/Transporter
298	CON EDISON SERVICE BOX: 50772	MADISON AVE & 118TH ST	471 feet to the W	Hazardous Waste Generator/Transporter
299	CON EDISON SERVICE BOX: 50775	MADISON AVE & 118TH ST	471 feet to the W	Hazardous Waste Generator/Transporter
300	CONED	E120TH ST	476 feet to the NNW	Hazardous Waste Generator/Transporter
301	CON EDISON	E 120 ST S 23 E MADISON AV	476 feet to the NNW	Hazardous Waste Generator/Transporter
206	132 E 119TH ST	132 E 119TH ST	477 feet to the SE	Closed Status Spill (Misc. Spill Cause)
302	CON EDISON	1787 MADISON AVE & 117 ST	501 feet to the WSW	Hazardous Waste Generator/Transporter
252	CRP 1661 PARK AVENUE LLC	105 EAST 117 ST.	517 feet to the S	Petroleum Bulk Storage Site
253	ST. PAUL SCHOOL	114 EAST 118TH STREET	522 feet to the SSE	Petroleum Bulk Storage Site
254	ST.PAULS CHURCH & SCHOOL	114 E 118 ST	522 feet to the SSE	Petroleum Bulk Storage Site
303	NYCHA − ROBINSON	1940 LEXINGTON AVE	525 feet to the E	Hazardous Waste Generator/Transporter
304	CONSOLIDATED EDISON	N/S E 121 ST 165‘ EAST OF PARK	537 feet to the NE	Hazardous Waste Generator/Transporter
305	CON EDISON	E 121ST ST & PARK AVE	537 feet to the NE	Hazardous Waste Generator/Transporter
70	207583; SE PARK AV E 117 ST	SE PARK AV E 117 ST	538 feet to the SSW	Closed Status Spill (Unk/Other Cause)
207	MANHOLE 42069	SE CRNR 117THST/PARK AVE	538 feet to the SSW	Closed Status Spill (Misc. Spill Cause)
306	CONSOLIDATED EDISON	SEC E 117TH ST & PARK AVE	538 feet to the SSW	Hazardous Waste Generator/Transporter
307	CONSOLIDATED EDISON	S/W/C E 117TH ST 7 PARK AVE	538 feet to the SSW	Hazardous Waste Generator/Transporter
208	113 EAST 117TH STREET	113 EAST 117TH STREET	543 feet to the S	Closed Status Spill (Misc. Spill Cause)
209	ST PAULS RECTORY	113 EAST 117TH STREET	543 feet to the S	Closed Status Spill (Misc. Spill Cause)
308	CON EDISON	F/O 58 E 121 ST	544 feet to the N	Hazardous Waste Generator/Transporter
309	CON EDISON	65 E 121 ST & PARK AVE	550 feet to the NNE	Hazardous Waste Generator/Transporter
310	CON EDISON	125 E 117TH ST E OF 3RD AVE	551 feet to the SSE	Hazardous Waste Generator/Transporter
311	CON EDISON	115 E 117TH ST	551 feet to the SSE	Hazardous Waste Generator/Transporter
312	CONSOLIDATED EDISON	1748 PARK AVE	551 feet to the NNE	Hazardous Waste Generator/Transporter
313	CONSOLIDATED EDISON	1832 MADISON AVE	568 feet to the NW	Hazardous Waste Generator/Transporter
314	NYC DEPT OF EDUCATION − PS 149M TANDEM WITH M207	34 WEST 118TH STREET	571 feet to the W	Hazardous Waste Generator/Transporter
315	CON EDISON	1932 LEXINGTON AVE	573 feet to the SE	Hazardous Waste Generator/Transporter
316	CON EDISON	F/O 104 EAST 117TH ST	579 feet to the S	Hazardous Waste Generator/Transporter
317	CON EDISON	F/O 104 E 117TH ST	579 feet to the S	Hazardous Waste Generator/Transporter
71	PARKING LOT	1980 LEXINGTON AVE	580 feet to the ENE	Closed Status Spill (Unk/Other Cause)
255	1652 PARK AVENUE ASSOC. LLC	1648 PARK AVENUE	584 feet to the SSW	Petroleum Bulk Storage Site
318	CON EDISON	11 E 118 ST & 5 AV	600 feet to the WNW	Hazardous Waste Generator/Transporter
319	CONSOLIDATED EDISON	FRONT OF 1743 PARK AVE	605 feet to the NE	Hazardous Waste Generator/Transporter
256	MADISON COURT ASSOC, LP	58 EAST 117TH STREET	610 feet to the SW	Petroleum Bulk Storage Site
320	CON EDISON	FT OF 22 E 118TH ST E OF 15TH AVE	613 feet to the W	Hazardous Waste Generator/Transporter
321	CON EDISON	F OF 1934 LEXINGTON AVE & 119TH ST	613 feet to the ESE	Hazardous Waste Generator/Transporter
322	CON EDISON	FO 111 E 120 ST	616 feet to the E	Hazardous Waste Generator/Transporter
210	119TH ST.& LEXINGTON AVE.	119TH ST. & LEXINGTON AVE	631 feet to the ESE	Closed Status Spill (Misc. Spill Cause)
323	CON EDISON	E 119TH ST & LEXINGTON AVE	631 feet to the ESE	Hazardous Waste Generator/Transporter
324	CON EDISON	NW COR LEXINGTON AVE & 119TH ST	631 feet to the ESE	Hazardous Waste Generator/Transporter
325	CON EDISON	55 E 121ST ST	641 feet to the NNE	Hazardous Waste Generator/Transporter
326	CON EDISON	73 E 121 ST	641 feet to the NNE	Hazardous Waste Generator/Transporter
327	CON EDISON	73 E 121ST ST & MADISON AVE	641 feet to the NNE	Hazardous Waste Generator/Transporter
328	CON EDISON	60 E 122 ST MADISON AV	641 feet to the NNE	Hazardous Waste Generator/Transporter

329	HENRY J CARTER SPECIALITY HOSPITAL	1879 MADISON AVE	641 feet to the NNE	Hazardous Waste Generator/Transporter
330	NYC HEALTH & HOSPITAL CORP	1752 PARK AVENUE	641 feet to the NNE	Hazardous Waste Generator/Transporter
72	SPILL NUMBER 0311320	127 EAST 117TH ST	646 feet to the SSE	Closed Status Spill (Unk/Other Cause)
331	CONED	20 E 118TH ST	649 feet to the W	Hazardous Waste Generator/Transporter
332	CON EDISON	104 E 117TH ST	649 feet to the S	Hazardous Waste Generator/Transporter
333	CON EDISON	110 E 117 ST	649 feet to the S	Hazardous Waste Generator/Transporter
334	CONSOLIDATED EDISON	V5731−MADISON & 117TH ST	654 feet to the WSW	Hazardous Waste Generator/Transporter
335	CON EDISON	S/W/C MADISON AVE E 117 ST	654 feet to the WSW	Hazardous Waste Generator/Transporter
336	CON EDISON	N SIDE E 121ST ST 240 FEET E	656 feet to the ENE	Hazardous Waste Generator/Transporter
337	CONSOLIDATED EDISON	E 121ST ST B/T LEXINGTON & PARK	656 feet to the ENE	Hazardous Waste Generator/Transporter
338	CON EDISON	F/O 132 E 121ST ST	656 feet to the ENE	Hazardous Waste Generator/Transporter
339	121ST ST	128−130 E 121ST ST	659 feet to the ENE	Historic Utility Site
73	MANHOLE 50789	MADISON AV & 121ST ST	662 feet to the N	Closed Status Spill (Unk/Other Cause)
74	SERVICE BOX 19135	91 EAST 116 ST	705 feet to the SW	Closed Status Spill (Unk/Other Cause)
75	OPEN EXCAVATION	91 EAST 116 ST.	705 feet to the SW	Closed Status Spill (Unk/Other Cause)
76	SB 19622	158 E. 119TH ST	710 feet to the SE	Closed Status Spill (Unk/Other Cause)
211	UNKNOWN RESIDENCE	124 EAST 117TH ST	746 feet to the S	Closed Status Spill (Misc. Spill Cause)
77	SB 19623	170 E.119TH ST	801 feet to the ESE	Closed Status Spill (Unk/Other Cause)
78	209996; E E 117 ST ST	E E 117 ST ST	834 feet to the W	Closed Status Spill (Unk/Other Cause)
29	APARTMENT BUILDING	123 E. 116TH STREET	838 feet to the S	Closed Status Tank Failure
79	VACANT LOT	1761 PARK AVENUE	859 feet to the NE	Closed Status Spill (Unk/Other Cause)
80	MAN HOLE (19150)	IFO 116 E. 116TH ST	924 feet to the S	Closed Status Spill (Unk/Other Cause)
3	1901 MADISON AVENUE	1901 MADISON AVENUE	935 feet to the NNE	Brownfields Site
212	1883 MADISON AVE	1883 MADISON AVE	955 feet to the NNE	Closed Status Spill (Misc. Spill Cause)
81	MANHOLE #39219	E 122ND ST & LEXINGTON AV	1008 feet to the ENE	Closed Status Spill (Unk/Other Cause)
82	177 EAST 117TH STREET	177 EAST 117TH STREET	1009 feet to the SE	Closed Status Spill (Unk/Other Cause)
83	HARLEM COURTHOUSE	170 EAST 121ST STREET	1029 feet to the E	Closed Status Spill (Unk/Other Cause)
84	2 WEST 120TH STREET	2 WEST 120TH STREET	1048 feet to the NW	Closed Status Spill (Unk/Other Cause)
85	DUTCH REFORM CHURCH OF HARLEM	171 EAST 121 STREET	1098 feet to the E	Closed Status Spill (Unk/Other Cause)
86	MAN HOLE 45730	NORTH WEST CORNER EAST 120 ST AND 3 AVE	1168 feet to the ESE	Closed Status Spill (Unk/Other Cause)
87	217428; 118 ST AND 3 AVE	118 ST AND 3 AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
88	VAULT #VS−5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
89	VAULT # 5236	EAST 118TH ST. & 3RD AVE	1168 feet to the SE	Closed Status Spill (Unk/Other Cause)
30	2021 LEXINGTON AVENUE	2021 LEXINGTON AVENUE	1187 feet to the ENE	Closed Status Tank Failure
90	MANHOLE M56965	WEST 116 ST & 5 AVE	1210 feet to the WSW	Closed Status Spill (Unk/Other Cause)
4	23 W. 116 ST AND 1428 FIFTH AVE (2 SITES)	1428 5TH AVENUE	1232 feet to the W	Brownfields Site
16	NYC PARKS	122 ND & 5TH AVE	1232 feet to the NNW	Active Tank Test Failure
39	PELHAM FRITZ RECREATION C	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW	Closed Status Tank Test Failure
91	PARKS REC SYSTEM	18 MOUNT MORRIS PARK WEST	1232 feet to the NNW	Closed Status Spill (Unk/Other Cause)
92	SERVICE BOX 45747	2236 3RD AVE	1248 feet to the E	Closed Status Spill (Unk/Other Cause)
93	2236 3RD AVE	2236 3RD AVE OFF OF 128 EAST ST	1248 feet to the E	Closed Status Spill (Unk/Other Cause)
94	SERVICE BOX 45748	2238 3RD AVE	1262 feet to the E	Closed Status Spill (Unk/Other Cause)
40	JACOB'S RESIDENCE	203 EAST 117TH ST	1312 feet to the SE	Closed Status Tank Test Failure
95	OPPOSITE OF 3 WEST 116 ST	OPPOSITE OF 3 WEST 116 ST	1320 feet to the W	Closed Status Spill (Unk/Other Cause)
41	STORE FRONT	124 EAST 124TH ST.	1321 feet to the NE	Closed Status Tank Test Failure
5	2211 3RD AVENUE	2211 3RD AVENUE	1322 feet to the E	Brownfields Site
21	SOIL	2211 3RD AVE	1324 feet to the E	Active Haz Spill (Unknown/Other Cause)
22	SOIL	1800 PARK AVE	1366 feet to the NNE	Active Haz Spill (Unknown/Other Cause)
23	1800 PARK AVE	1800 PARK AVE	1366 feet to the NNE	Active Haz Spill (Unknown/Other Cause)
96	79 E 124TH ST	79 E 124TH ST	1366 feet to the NNE	Closed Status Spill (Unk/Other Cause)
42	CLOSED−LACKOF RECENT INFO	158 E 115TH ST	1367 feet to the S	Closed Status Tank Test Failure
213	49 WEST 119TH ST/MANH	49 WEST 119TH STREET	1393 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
43	DUNLEVY MILBANK CHILDREN	14−32 WEST 118TH STREET	1398 feet to the WNW	Closed Status Tank Test Failure

31	42 WEST 120TH STREET	42 WEST 120TH STREET	1404 feet to the NW	Closed Status Tank Failure
214	APARTMENT BUILDING	42 WEST 120TH ST	1404 feet to the NW	Closed Status Spill (Misc. Spill Cause)
215	42 WEST 120TH ST/CIBRO	42 WEST 120TH STREET	1404 feet to the NW	Closed Status Spill (Misc. Spill Cause)
216	VAULT #5033	1695 MADISON AV	1463 feet to the SW	Closed Status Spill (Misc. Spill Cause)
6	23 WEST 116TH, 1428 FIFTH AVENUE	1428 5TH AVENUE	1468 feet to the W	Brownfields Site
7	HARLEM PARK	1800−1808 PARK AVE 71 E. 124 ST., 66−70 E 125 ST.	1473 feet to the NNE	Brownfields Site
44	UNKNOWN	222 EAST 119TH ST	1505 feet to the ESE	Closed Status Tank Test Failure
97	63 W 119TH ST	63 W 119TH ST	1508 feet to the WNW	Closed Status Spill (Unk/Other Cause)
24	MORRIS PARK HOUSES −NYCHA	17 EAST 124TH ST	1518 feet to the N	Active Haz Spill (Unknown/Other Cause)
45	MORRIS PARK SENIOR	17 EAST 124TH STREET	1518 feet to the N	Closed Status Tank Test Failure
217	MORRIS PK SENIOR CITIZENS	17 EAST 124TH STREET	1518 feet to the N	Closed Status Spill (Misc. Spill Cause)
218	MORRIS PARK SENIOR CIT.	17 EAST 124TH STREET	1518 feet to the N	Closed Status Spill (Misc. Spill Cause)
98	SPILL NUMBER 0304253	65 W 119TH ST	1525 feet to the WNW	Closed Status Spill (Unk/Other Cause)
46	RESIDENCE	212 EAST 122ND STREET	1537 feet to the E	Closed Status Tank Test Failure
47	TAINO TOWER	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
48	TAINO TOWERS − TTF	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
49	TAINO TOWERS	2253 3RD AVE	1543 feet to the E	Closed Status Tank Test Failure
99	VAULT #9153	3RD AVE / E 123 ST	1546 feet to the ENE	Closed Status Spill (Unk/Other Cause)
100	MANHOLE 19753	58 WEST 120TH ST	1552 feet to the NW	Closed Status Spill (Unk/Other Cause)
50	X	1944 MADISON AVE	1565 feet to the N	Closed Status Tank Test Failure
219	SPILL NUMBER 9810692	1944 MADISON AV	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
220	MT MORRIS PARK BATH HOUSE	1944 MADISON AVE	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
221	1944 MADISON AVENUE	1944 MADISON AVENUE	1565 feet to the N	Closed Status Spill (Misc. Spill Cause)
101	MANHOLE 45668	3RD AVE/EAST 115TH	1577 feet to the SSE	Closed Status Spill (Unk/Other Cause)
340	ODYSSEY HOUSE	219 E. 121ST STREET	1577 feet to the E	Hazardous Substance Waste Disposal Site
102	APPLE BANK	124 EAST 125TH ST	1584 feet to the NE	Closed Status Spill (Unk/Other Cause)
222	STREET SPILL	124TH ST 5TH AVE	1589 feet to the N	Closed Status Spill (Misc. Spill Cause)
103	2ND AVE SUBWAY PROJECT − NYCT	PARK AVE/125TH ST	1594 feet to the NNE	Closed Status Spill (Unk/Other Cause)
104	125TH ST BTWN MADISON −NYCT	125TH ST PARK& MADISON SO	1595 feet to the NNE	Closed Status Spill (Unk/Other Cause)
17	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Active Tank Test Failure
51	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Tank Test Failure
105	HOUSING PROJECT	1740 MADISON AVE	1605 feet to the SW	Closed Status Spill (Unk/Other Cause)
223	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Spill (Misc. Spill Cause)
224	TAFT HOUSES −NYCHA	1740 MADISON AVENUE	1605 feet to the SW	Closed Status Spill (Misc. Spill Cause)
106	DRUM RUN	228 EAST 117 ST BTW 2ND & 3RD AVE	1623 feet to the SE	Closed Status Spill (Unk/Other Cause)
107	208153; MADISON AVE	MADISON AVE	1637 feet to the NNE	Closed Status Spill (Unk/Other Cause)
108	79 WEST 119 STREET	79 WEST 119 STREET	1650 feet to the WNW	Closed Status Spill (Unk/Other Cause)
109	PRIVATE RESIDENCE	236 E 118TH ST PT 9	1658 feet to the SE	Closed Status Spill (Unk/Other Cause)
8	81 WEST 125TH STREET	81 WEST 125TH STREET	1662 feet to the NNE	Brownfields Site
110	213778; 222 E 123 ST	222 E 123 ST	1666 feet to the E	Closed Status Spill (Unk/Other Cause)
111	ROADWAY	MADISON AVE/EAST 113 ST	1691 feet to the SW	Closed Status Spill (Unk/Other Cause)
112	SPILL NUMBER 0206541	79 E 125TH ST	1693 feet to the NNE	Closed Status Spill (Unk/Other Cause)
9	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE	Brownfields Site
10	69 EAST 125TH STREET	69 EAST 125TH STREET	1695 feet to the NNE	Brownfields Site
113	BROWNSTONE HOUSE	12 WEST 121 STREET	1698 feet to the NW	Closed Status Spill (Unk/Other Cause)
114	MH39246	E 125TH ST & LEXINGTON AV	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
115	SPILL NUMBER 9905454	125TH ST & LEXINGTON AV	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
116	MANHOLE 39242	125TH ST /LEXINGTON AVE	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
117	218014; E 125 ST AND LEXINGTON AVE	E 125 ST AND LEXINGTON AVE	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
118	2ND AVE SUBWAY −NYCT	LEXINGTON & 125TH ST	1710 feet to the NE	Closed Status Spill (Unk/Other Cause)
119	MANHOLE 39163	EAST SIDE OF LEXINGTON AV	1712 feet to the S	Closed Status Spill (Unk/Other Cause)
120	DEMOLISHED BUILDING	2000−2002 5TH AVE	1734 feet to the N	Closed Status Spill (Unk/Other Cause)
121	CHURCH	33 WEST 115 & 36 115TH STREET	1741 feet to the W	Closed Status Spill (Unk/Other Cause)

122	246 E 121 ST	246 E 121ST	1762 feet to the ESE	Closed Status Spill (Unk/Other Cause)
52	1824 PARK AVE/SUNOCO	1824 PARK AVE	1778 feet to the NNE	Closed Status Tank Test Failure
225	WEST 115 ST	BET 5TH AV & LENOX AV	1791 feet to the W	Closed Status Spill (Misc. Spill Cause)
53	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
54	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
55	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
56	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
57	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Tank Test Failure
123	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
124	JOHNSON HOUSES	1809 LEXINGTON AV	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
125	JOHNSON HOUSES −NYCHA	1809 LEXINGTON AVE	1792 feet to the S	Closed Status Spill (Unk/Other Cause)
226	JOHNSON HOUSES	165 EAST 165TH STREET	1792 feet to the S	Closed Status Spill (Misc. Spill Cause)
227	163 E.112TH ST. NYC./NO.2 O	163 E. 112TH ST.	1792 feet to the S	Closed Status Spill (Misc. Spill Cause)
32	24 WEST 121 STREET	24 W 121ST STREET	1814 feet to the NW	Closed Status Tank Failure
58	APART	86 WEST 119TH STREET	1822 feet to the WNW	Closed Status Tank Test Failure
126	2ND AVE SUBWAY −NYCT	125TH ST/5TH AVE	1828 feet to the N	Closed Status Spill (Unk/Other Cause)
127	200 LENOX AVENUE	200 LENOX AVENUE	1836 feet to the NW	Closed Status Spill (Unk/Other Cause)
59	APARTMENT BLDG − TTF	120TH ST & SECOND AVE	1866 feet to the ESE	Closed Status Tank Test Failure
128	MANHOLE 55068	120TH ST & 2ND AVE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)
129	215193; E 120 ST AND 2ND AVE	E 120 ST AND 2ND AVE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)
130	MANHOLE #1864	EAST 120 STREET & 2 AVENUE	1866 feet to the ESE	Closed Status Spill (Unk/Other Cause)
131	210473; 2ND AVE	2ND AVE	1867 feet to the SE	Closed Status Spill (Unk/Other Cause)
228	HARLEM DAY CHARTER SCHOOL	230 E 123RD ST	1867 feet to the E	Closed Status Spill (Misc. Spill Cause)
132	ROAD INTERSECTION	E. 112 TH ST AND PARK AVE	1869 feet to the SSW	Closed Status Spill (Unk/Other Cause)
229	METRO NORTH	126TH ST. & PARK AVE.	1874 feet to the NNE	Closed Status Spill (Misc. Spill Cause)
133	VAULT 2349	MADISON/E 112TH ST	1903 feet to the SW	Closed Status Spill (Unk/Other Cause)
60	THE EAST DRIVE H.D.F.C.	205 EAST 124TH STREET	1906 feet to the ENE	Closed Status Tank Test Failure
134	CROSSWALKS	125TH / 3RD AVE	1956 feet to the ENE	Closed Status Spill (Unk/Other Cause)
135	SPILL NUMBER 9809080	E 112 ST & LEXINGTON AV	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
136	MANHOLE 39156	E 112TH ST/LEXINGTON AV	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
137	219438; LEXINGTON AVE AND 112TH ST	LEXINGTON AVE AND 112TH ST	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
138	LEXINGTON AVE	LEXINGTON AVE/EAST 112 ST	1972 feet to the S	Closed Status Spill (Unk/Other Cause)
11	146 EAST 126TH STREET	146 EAST 126TH STREET	1986 feet to the NE	Brownfields Site
139	JEFFERSON HOUSES	2089 3RD AVE	1999 feet to the SSE	Closed Status Spill (Unk/Other Cause)
140	BEHIND HOUSES IN AREA OF	56 WEST 124TH ST	2001 feet to the NNW	Closed Status Spill (Unk/Other Cause)
141	138 EAST 112TH ST	138 EAST 112TH ST	2004 feet to the SSW	Closed Status Spill (Unk/Other Cause)
142	NEW CONSTRUCTION	81 WEST 115TH ST	2004 feet to the W	Closed Status Spill (Unk/Other Cause)
143	MAN HOLE #55020	116TH ST / 2ND AV	2016 feet to the SE	Closed Status Spill (Unk/Other Cause)
144	SERVICE BOX 55036	2276 2ND AVE	2016 feet to the SE	Closed Status Spill (Unk/Other Cause)
230	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
231	CON ED FACILITY	32 W 125TH ST	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
232	CON ED	32 WEST 125TH STREET	2017 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
145	248 LENOX AVE/MANH	248 LENOX AVENUE	2022 feet to the NW	Closed Status Spill (Unk/Other Cause)
233	SPILL NUMBER 9811292	32 WEST 123RD STREET	2044 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
33	78−80 E 127TH ST/NYCHPD	78−80 E 127TH ST	2056 feet to the NNE	Closed Status Tank Failure
146	64 E 127TH ST	64 E 127TH ST	2063 feet to the NNE	Closed Status Spill (Unk/Other Cause)
12	CHURCH OF SCIENTOLOGY−SITE A	220 EAST 125TH STREET	2071 feet to the ENE	Brownfields Site
147	SPILL NUMBER 9811290	36−38 WEST 123RD ST	2078 feet to the NNW	Closed Status Spill (Unk/Other Cause)
25	KING TOWERS −NYCHA	90 LENOX AVE	2079 feet to the WSW	Active Haz Spill (Unknown/Other Cause)
234	1350 5TH AVE	1350 5TH AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
235	70 LENOX AVE	70 LENOX AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
236	KING TOWERS	90 LENOX AVE	2079 feet to the WSW	Closed Status Spill (Misc. Spill Cause)
148	SPILL NUMBER 0308444	W. 116TH ST & LENOX AVE	2083 feet to the W	Closed Status Spill (Unk/Other Cause)

13	5 WEST 125TH	5 WEST 125TH STREET	2088 feet to the N	Brownfields Site
18	ABOVE GROUND TANK − TTF	17 WEST 125TH ST	2113 feet to the N	Active Tank Test Failure
149	IMPACTED SOIL FOUND IN EXCAVATION	PARK AVE & EAST 127 STREET	2133 feet to the NNE	Closed Status Spill (Unk/Other Cause)
61	CORSI HOUSES (JEFFERSON) −NYCHA	306 EAST 117TH STREET	2136 feet to the SE	Closed Status Tank Test Failure
150	STREET SPILL	SECOND AVE & E 123 ST	2144 feet to the E	Closed Status Spill (Unk/Other Cause)
151	217860; 2 AVE AND 115TH ST	2 AVE AND 115TH ST	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
152	208234; NWC E 115 ST 2ND AV	NWC E 115 ST 2ND AV	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
153	VAULT 5975	EAST 115TH ST AT 2ND AV	2150 feet to the SSE	Closed Status Spill (Unk/Other Cause)
14	CHURCH OF SCIENTOLOGY−SITE B	220 EAST 125TH STREET	2153 feet to the ENE	Brownfields Site
154	BETWEEN LENOX AND 7TH AVE	109 WEST 119TH ST	2160 feet to the WNW	Closed Status Spill (Unk/Other Cause)
155	BWTEEEN 2ND & 3RD AV −NYCT	125TH ST 2ND & 3RD AVE	2176 feet to the ENE	Closed Status Spill (Unk/Other Cause)
237	163 E 111TH ST	163 E 111TH ST	2177 feet to the S	Closed Status Spill (Misc. Spill Cause)
156	MANHOLE 45805	EAST 126TH ST / 3RD AVE	2189 feet to the ENE	Closed Status Spill (Unk/Other Cause)
157	SITE F/NEW CONSTRUCTION	169 EAST 111 ST	2216 feet to the S	Closed Status Spill (Unk/Other Cause)
19	CONVENT	226 EAST 113TH STREET	2217 feet to the SSE	Active Tank Test Failure
158	ROADWAY SURFACE	EAST 120TH STREET BW 1ST AND 2ND AVE	2222 feet to the ESE	Closed Status Spill (Unk/Other Cause)
26	NYC PS 155 SCHOOL	319 E117TH ST	2240 feet to the SE	Active Haz Spill (Unknown/Other Cause)
62	CHURCH	232 EAST 113TH STREET	2267 feet to the SSE	Closed Status Tank Test Failure
238	APT COMPLEX W/ STORES	282 LENOX AVE	2268 feet to the NNW	Closed Status Spill (Misc. Spill Cause)
159	121 WEST 119TH STREET	121 WEST 119TH STREET	2276 feet to the WNW	Closed Status Spill (Unk/Other Cause)
160	2005 MADISON AV & 128TH	2005 MADISON AV	2286 feet to the NNE	Closed Status Spill (Unk/Other Cause)
34	105 LENOX AVE/HARLEM HOSP	105 LENOX AVENUE	2291 feet to the W	Closed Status Tank Failure
161	NYS DEPT OF HUMAN RIGHTS	55 WEST 125TH ST	2311 feet to the NNW	Closed Status Spill (Unk/Other Cause)
162	SB 20601	WEST 127TH ST/ 5TH AVE	2313 feet to the N	Closed Status Spill (Unk/Other Cause)
163	SPILL NUMBER 0104362	104 WEST 123RD ST	2323 feet to the NW	Closed Status Spill (Unk/Other Cause)
164	SOUTHSIDE OF −NYCT	EAST 116TH STREET	2329 feet to the SE	Closed Status Spill (Unk/Other Cause)
165	X	52 WEST 126TH STREET	2330 feet to the NNW	Closed Status Spill (Unk/Other Cause)
35	127 W 119TH ST	127 W 119TH ST	2336 feet to the WNW	Closed Status Tank Failure
239	127 WEST 119TH ST/MANH	127 WEST 119TH STREET	2336 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
166	SPILL NUMBER 0202065	2067 5TH AVE	2352 feet to the N	Closed Status Spill (Unk/Other Cause)
167	BASEMENT	271 LENOX AVE	2354 feet to the NNW	Closed Status Spill (Unk/Other Cause)
240	129 WEST 119TH ST/MANH	129 WEST 119TH STREET	2356 feet to the WNW	Closed Status Spill (Misc. Spill Cause)
36	275 LENOX AVE	275 LENOX AVE	2370 feet to the NNW	Closed Status Tank Failure
168	LOT NEXT TO AMOCO STATION	249 EAST 125TH ST	2373 feet to the ENE	Closed Status Spill (Unk/Other Cause)
169	VACANT LOT	346 E. 119TH ST	2384 feet to the ESE	Closed Status Spill (Unk/Other Cause)
241	112−114 W 116TH ST	112−114 W 116TH ST	2384 feet to the W	Closed Status Spill (Misc. Spill Cause)
170	SPILL NUMBER 0011504	20 WEST 127TH ST	2387 feet to the N	Closed Status Spill (Unk/Other Cause)
171	2365 FIRST AVENUE	2365 FIRST AVENUE	2399 feet to the E	Closed Status Spill (Unk/Other Cause)
242	SPILL NUMBER 0103459	24 WEST 127TH ST	2406 feet to the N	Closed Status Spill (Misc. Spill Cause)
172	PRIVATE HOME	12 EAST 128TH ST	2408 feet to the NNE	Closed Status Spill (Unk/Other Cause)
173	MAN HOLE #45816	E 127TH ST & 3RD AVE	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
174	213284; 3 AVE AND E 127 ST ST	3 AVE AND E 127 ST ST	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
175	CONED MANHOLE #20977	EAST 127/3RD AVE	2414 feet to the ENE	Closed Status Spill (Unk/Other Cause)
176	MANHOLE 45629	E 111TH ST & 3RD AV	2418 feet to the S	Closed Status Spill (Unk/Other Cause)
63	AMOCO	255 EAST 125TH STREET	2421 feet to the ENE	Closed Status Tank Test Failure
243	BP AMOCO STATION #13401	255 EAST 125TH ST	2421 feet to the ENE	Closed Status Spill (Misc. Spill Cause)
177	APARTMENT BUILDING	332 E 116TH ST	2436 feet to the SE	Closed Status Spill (Unk/Other Cause)
178	217897; 2 AVENUE AND 125TH STREET	2 AVENUE AND 125TH STREET	2439 feet to the ENE	Closed Status Spill (Unk/Other Cause)
15	110 LENOX AT 125TH STREET	281 LENOX AVENUE	2440 feet to the NNW	Brownfields Site
179	IS 45M− NYSCA	2351 1ST AVE	2442 feet to the ESE	Closed Status Spill (Unk/Other Cause)
27	CONSTRUCTION SITE	225 EAST 126TH ST	2448 feet to the ENE	Active Haz Spill (Unknown/Other Cause)
180	MANHOLE #62325	2 AVENUE & 113 STREET	2451 feet to the SSE	Closed Status Spill (Unk/Other Cause)
181	LEXINGTON AV/E 128TH ST	LEXINGTON AV/E.128TH ST	2472 feet to the NE	Closed Status Spill (Unk/Other Cause)

182	127 W 122ND ST	127 W 122ND ST	2477 feet to the NW	Closed Status Spill (Unk/Other Cause)
183	MANHOLE #39138	EAST 110 AND LEXINGTON AV	2477 feet to the SSW	Closed Status Spill (Unk/Other Cause)
184	MANHOLE #39138	E 110TH ST & LEXINGTON AV	2477 feet to the SSW	Closed Status Spill (Unk/Other Cause)
185	SPILL NUMBER 0105211	11 WEST 127TH ST	2480 feet to the N	Closed Status Spill (Unk/Other Cause)
186	M AND M GROCERY	2337 1ST AVE	2510 feet to the ESE	Closed Status Spill (Unk/Other Cause)
187	SERVICE BOX 42143	PARK AVE 128TH/129TH	2522 feet to the NNE	Closed Status Spill (Unk/Other Cause)
188	2ND AVE SUBWAY −NYCT	125TH & 126TH ST	2530 feet to the ENE	Closed Status Spill (Unk/Other Cause)
189	207627; E ST	E ST	2553 feet to the S	Closed Status Spill (Unk/Other Cause)
37	COMMERCIAL BUILDING	310 LENOX AVE	2559 feet to the NNW	Closed Status Tank Failure
64	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
65	JACKIE ROBINSON HOUSING	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
66	JACKIE ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE	Closed Status Tank Test Failure
190	JACKIE ROBINSON CONSOLID. −NYCHA	129 E.128TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
191	JACKIE ROBINSON	110 EAST 129TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
192	I PT OF UNKN SUBSTANCE IN SB 21083	105 EAST 128 STREET	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
193	ROBINSON HOUSES −NYCHA	110 EAST 129TH ST	2571 feet to the NE	Closed Status Spill (Unk/Other Cause)
194	1890 PARK AVE CORP	1890 PARK AVE	2574 feet to the NNE	Closed Status Spill (Unk/Other Cause)
195	APART	212 E. 111TH ST	2581 feet to the S	Closed Status Spill (Unk/Other Cause)
196	PVT APARTMENT BLDG	214 E.111TH ST	2594 feet to the S	Closed Status Spill (Unk/Other Cause)
197	71 W. 126TH ST	71 W. 126TH ST	2595 feet to the NNW	Closed Status Spill (Unk/Other Cause)
38	SPILL NUMBER 9911165	75 W. 126TH ST	2608 feet to the NNW	Closed Status Tank Failure
198	75 WEST 126TH STREET	75 WEST 126TH STREET	2608 feet to the NNW	Closed Status Spill (Unk/Other Cause)
199	MANHOLE 53842	EAST 118 TH ST/1ST AVE	2610 feet to the SE	Closed Status Spill (Unk/Other Cause)
200	MANHOLE 53875	1ST AVE/120TH ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
201	MANHOLE 53880	1ST AVE/E120TH ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
202	MANHOLE 53864	E 120TH ST / 1ST AVE	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
203	VS2027 VAULT	1RST AVE AND EAST 120ST	2611 feet to the ESE	Closed Status Spill (Unk/Other Cause)
20	PVT DWELLING − TTF	19−21 EAST 109 ST	2639 feet to the SW	Active Tank Test Failure
1	PLEASANT AVENUE PLUME TRACKDOWN	PLEASANT AVENUE	3259 feet to the SE	NYSDEC Inactive Haz Waste Disposal Site
2	VISTA 1	2401 THIRD AVENUE	3872 feet to the NE	NYSDEC Inactive Haz Waste Disposal Site

Toxics Targeting
1 Mile Radius Map

1678 and 1700 Park Avenue

New York, NY 10035

N
W
E
S



New York County

National Priority List (NPL)

Inactive Hazardous Waste Disposal Registry Site

Inact. Haz Waste Disp. Registry Qualifying

RCRA Corrective Action Facility

Site Location

Waterbody

County Border

Railroad Tracks

1 Mile Radius

1/2 Mile Radius

1/4 Mile Radius

1/8 Mile Radius



Toxics Targeting
1/2 Mile Radius Map

1678 and 1700 Park Avenue

New York, NY 10035





New York County

- Delisted NPL Site
- CERCLIS Superfund Non-NFRAP Site
- CERCLIS Superfund NFRAP Site
- Hazardous Waste Treater, Storer, Disposer
- Hazardous Substance Waste Disposal Site
- Solid Waste Facility
- Brownfields Site
- Hazardous Material Spill
- MTBE Gasoline Additive Spill

- Site Location
- Waterbody
- County Border
- Railroad Tracks
- 1 Mile Radius
- 1/2 Mile Radius
- 1/4 Mile Radius
- 1/8 Mile Radius

Toxics Targeting
1/8 Mile Radius Map

1678 and 1700 Park Avenue

New York, NY 10035





New York County

- Major Oil Storage Facility
- Chemical Storage Facility
- Toxic Release
- Wastewater Discharge
- Hazardous Waste Generator, Transp.
- Enforcement Docket Facility
- Air Release
- Env Qual Review E Designation
- Petroleum Bulk Storage Facility
- Historic Utility Site

- Site Location
- County Border
- 1/8 Mile Radius
- Waterbody
- Railroad Tracks
- 250 Foot Radius

Toxics Targeting
1/8 Mile Closeup Map

1678 and 1700 Park Avenue

New York, NY 10035

N
W
E
S



New York County

- National Priority List (NPL) *
- Delisted NPL Site **
- CERCLIS Superfund Non-NFRAP Site **
- CERCLIS Superfund NFRAP Site **
- Inactive Hazardous Waste Disposal Registry Site *
- Inact. Haz Waste Disp. Registry Qualifying *
- Hazardous Waste Treater, Storer, Disposer **
- RCRA Corrective Action Facility *
- Hazardous Substance Waste Disposal Site **
- Solid Waste Facility **
- Major Oil Storage Facility ****
- Brownfields Site **
- Chemical Storage Facility ****
- Hazardous Material Spill **
- Toxic Release ****
- MTBE Gasoline Additive Spill **
- Wastewater Discharge ****
- Petroleum Bulk Storage Facility ****
- Hazardous Waste Generator, Transp. ****
- Historic Utility Site ****
- Enforcement Docket Facility ****
- Air Release ****
- Env Qual Review E Designation *****
- Remediation Site Borders
- Site Location
- Waterbody
- County Border
- Railroad Tracks
- 1/8 Mile Radius
- 250 Foot Radius

* 1 Mile Search Radius

** 1/2 Mile Search Radius

**** 1/8 Mile Search Radius

***** Onsite Search (250 Ft)

Toxics Targeting Tax Parcel Map

1678 and 1700 Park Avenue

New York, NY 10035

N

W E

S



New York County

- National Priority List (NPL)
- Delisted NPL Site
- CERCLIS Superfund Non-NFRAP Site
- CERCLIS Superfund NFRAP Site
- Inactive Hazardous Waste Disposal Registry Site
- Inact. Haz Waste Disp. Registry Qualifying
- Hazardous Waste Treater, Storer, Disposer
- RCRA Corrective Action Facility
- Hazardous Substance Waste Disposal Site
- Solid Waste Facility
- Major Oil Storage Facility
- Brownfields Site
- Chemical Storage Facility
- Hazardous Material Spill
- Toxic Release
- MTBE Gasoline Additive Spill
- Wastewater Discharge
- Petroleum Bulk Storage Facility
- Hazardous Waste Generator, Transp.
- Historic Utility Site
- Enforcement Docket Facility
- Air Release
- Env Qual Review E Designation
- Remediation Site Borders
- Site Location
- Waterbody
- County Border
- Railroad Tracks

Tax Parcel Information Table

1678 and 1700 Park Avenue
New York, NY 10035

Subject Parcel or Parcels

BBL #	Address	Owner	Zoning District(s)	Building Class	# of Buildings	Year Built	Assessment	Lot Area
	Site not located on a parcel							
	Site not located on a parcel							

Other Parcels Found On The Tax Parcel Map

BBL #	Address	Owner	Zoning District(s)	Building Class	# of Buildings	Year Built	Assessment	Lot Area
1−01746−0041	70 EAST 120 STREET	NANCY HERARD	R7−2	C0	1	2002	45506	2086
1−01745−0133	73 EAST 118 STREET	CRUZ NITCHEALL	R7−2	C0	1	2001	46688	2018
1−01746−0033	1700 PARK AVENUE	PARK AVENUE PARKING	R7−2	G6	0		598050	20183
1−01767−0072	1689 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		168750	2250
1−01768−0071	96 EAST 120 STREET	COMPASS POINT LLC	M1−4	V1	0		109350	1332
1−01745−0130	67 EAST 118 STREET	LUO SHENG FENG	R7−2	C0	1	2001	46688	2018
1−01623−0039	1672 PARK AVENUE	1672 DEVELOPMENT COMP	R7−2	C7	1	1910	391050	2237
1−01746−0047	54 EAST 120 STREET	NYC PARTNERSHIP HOUSI	R7−2	C0	1	2002	48449	2001
1−01745−0050	1829 MADISON AVENUE	50 EAST 119TH STREET	R7−2	C4	1	1900	753300	2592
1−01746−0027	67 EAST 119 STREET	MORANEY, STEPHANIE E	R7−2	C0	1	2002	27427	2001
1−01745−7501	1825 MADISON AVENUE		R7−2	RM	1	2003	4049100	17292
1−01767−0062	120 EAST 119 STREET	POLICE DEPARTMENT	R7−2	Y2	1	1970	2794950	12615
1−01768−0004	1707 PARK AVENUE	EAST HARLEM COUNCILFO	R7−2	C4	2	1900	209700	4770
1−01746−0031	75 EAST 119 STREET	CHEN, CHAO XIONG	R7−2	C0	1	2002	40746	2001
1−01745−0024	55 EAST 118 STREET	JULIO CASTANO	R7−2	C0	1	2001	40755	2018
1−01623−0042	68 EAST 118 STREET	ANTONIA MOCZO	R7−2	C0	1	2002	55334	1926
1−01767−0001	1681 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		171900	2288
1−01746−0023	59 EAST 119 STREET	HARGROW, PAUL	R7−2	C0	1	2002	48122	2086
1−01768−0001	101 EAST 119 STREET	’JAMIES”” PLACE II LLC’	R7−2	D7	1	1920	788400	6800
1−01746−0141	68 EAST 120 STREET	BLIGEN, LEON	R7−2	C0	1	2002	47484	2001
1−01767−0002	1683 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		170100	2265
1−01745−0040	1694 PARK AVENUE	ORTEGA ANGELITA	R7−2	C4	1	1900	369450	2288
1−01745−0150	56 EAST 119 STREET	LEMOINE, MARITZA	R7−2	C0	1	2001	46688	2018
1−01746−0026	65 EAST 119 STREET	SANCHEZ, JULIA	R7−2	C0	1	2002	41976	2001
1−01746−0046	56 EAST 120 STREET	MARTINEZ, VIRGINIA	R7−2	C0	1	2002	22434	2001
1−01745−0141	74 EAST 119 STREET	WAITE, STEPHEN	R7−2	C0	1	2001	46688	2018
1−01746−0042	66 EAST 120 STREET	DELGADO, JOSE	R7−2	C0	1	2002	46758	2001
1−01623−0043	62 EAST 118 STREET	ERIC FRAZIER	R7−2	C0	1	2002	55334	1926
1−01746−0045	60 EAST 120 STREET	COLON, IRMA	R7−2	C0	1	2002	32702	2001
1−01767−0068	108 EAST 119 STREET	POLICE DEPARTMENT	R7−2	V1	0		189450	2523
1−01745−0126	57 EAST 118 STREET	DEBRA L. LOWERY	R7−2	C0	1	2001	46688	2018
1−01768−0003	PARK AVENUE	D C A S	R7−2	V1	0		131	90
1−01767−0169	104 EAST 119 STREET	POLICE DEPARTMENT	R7−2	V1	0		42300	561
1−01745−0129	65 EAST 118 STREET	TRAVIS, STEVEN M	R7−2	C0	1	2001	46688	2018
1−01746−0044	62 EAST 120 STREET	THE POLYNE FAMILY LIV	R7−2	C0	1	2002	37213	2001
1−01745−0143	70 EAST 119 STREET	FRAZIER, KAREEM	R7−2	C0	1	2001	46688	2018
1−01746−0021	1831 MADISON AVENUE	NYC HOUSING PARTNERSH	R7−2	D4	1	2001	5926950	17660

BBL #	Address	Owner	Zoning District(s)	Building Class	# of Buildings	Year Built	Assessment	Lot Area
1−01767−0069	1693 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		214200	2856
1−01767−0067	110 EAST 119 STREET	POLICE DEPARTMENT	R7−2	V1	0		189450	2523
1−01768−0070	100 EAST 120 STREET	COMPASS POINT LLC	M1−4	V1	0		106200	1296
1−01767−0071	1691 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		150300	2000
1−01745−0145	66 EAST 119 STREET	DOROTHY A. WALLACE	R7−2	C0	1	2001	46688	2018
1−01746−0043	64 EAST 120 STREET	KUMAGAY, MARIA C	R7−2	C0	1	2002	46842	2001
1−01746−0030	73 EAST 119 STREET	MUNOZ, RAFAEL	R7−2	C0	1	2002	40441	2001
1−01767−0003	1685 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		168750	2250
1−01745−0132	71 EAST 118 STREET	JORGE B. PENA	R7−2	C0	1	2001	44816	2018
1−01745−0147	62 EAST 119 STREET	RODGERS DENISE	R7−2	C0	1	2001	46688	2018
1−01623−0041	70 EAST 118 STREET	WASHINGTON MICHAEL A	R7−2	C0	1	2003	54606	2548
1−01767−0168	106 EAST 119 STREET	POLICE DEPARTMENT	R7−2	V1	0		105750	1406
1−01768−0005	111 EAST 119 STREET	JAMES PLACE 1V LLC	R7−2	C5	1	1910	260550	2523
1−01746−0145	58 EAST 120 STREET	SCIPIO, RICHARDENE	R7−2	C0	1	2002	26121	2001
1−01746−0025	63 EAST 119 STREET	CORREA, MARIA C	R7−2	C0	1	2002	48122	2001
1−01623−0143	64 EAST 118 STREET	TARA D. TOLLIVER	R7−2	C0	1	2002	55334	1926
1−01746−0032	77 EAST 119 STREET	DEUTOU, ISIDORE TII	R7−2	C0	1	2002	40423	2086
1−01767−0004	1687 PARK AVENUE	POLICE DEPARTMENT	R7−2	V1	0		168750	2250
1−01745−0029	63 EAST 118 STREET	JULIAN MARIA	R7−2	C0	1	2001	46688	2018
1−01746−0048	52 EAST 120 STREET	ASSOKO, GILBERT	R7−2	C0	1	2001	30982	2086
1−01745−0149	58 EAST 119 STREET	BARRAJANOS, KIM	R7−2	C0	1	2001	46688	2018
1−01745−0144	68 EAST 119 STREET	ROSEBORO, LYDIA THOMP	R7−2	C0	1	2001	46688	2018
1−01745−0148	60 EAST 119 STREET	MONROE, BRIAN	R7−2	C0	1	2001	46688	2018
1−01623−0040	1674 PARK AVENUE	RUBYANNE DEVELOPMENT,	R7−2	V1	0		170550	2275
1−01745−0127	59 EAST 118 STREET	RIVERA ANTHONY	R7−2	C0	1	2001	46688	2018
1−01623−0142	66 EAST 118 STREET	AUGUSTINA WILLIAMS	R7−2	C0	1	2002	55334	1926
1−01746−0024	61 EAST 119 STREET	RAHMAN, MUKHLESUR	R7−2	C0	1	2002	48122	2001
1−01768−0170	98 EAST 120 STREET	COMPASS POINT LLC	M1−4	V1	0		103500	1260
1−01623−0044	60 EAST 118 STREET	WILLIAM E. WOODLON	R7−2	C0	1	2002	52663	1926
1−01747−0001	1839 MADISON AVENUE	JOINTLY OWNED PLAYGRO	R7−2	W1	1	1962	4060350	81741
1−01746−0029	71 EAST 119 STREET	CID, ALFREDO G	R7−2	C0	1	2002	27427	2001
1−01745−0128	61 EAST 118 STREET	CATHERINE PAYNE	R7−2	C0	1	2001	46688	2018
1−01745−0146	64 EAST 119 STREET	GUINDO, JOAN	R7−2	C0	1	2001	46688	2018
1−01745−0134	1678 PARK AVENUE		R7−2	G6	0		544050	17642
1−01745−0131	69 EAST 118 STREET	STREETER, MARSHA P	R7−2	C0	1	2001	46688	2018
1−01767−0005	111 EAST 118 STREET	SCHAFER HALL, L.P. C	R7−2	D9	1	1999	2166750	15138
1−01745−0142	72 EAST 119 STREET	MAN TAT NG	R7−2	C0	1	2001	46688	2018
1−01746−0028	71 EAST 119 STREET	FU, XIAO QIN	R7−2	C0	1	2002	34351	2001

Section Two: Toxic Site Profiles

The heading of each *Toxic Site Profile* refers to the site's map location and details:

- The facility name, address, city, state, and zip code.
- Any changes that were made to a site's address in order to map its location.
- The site mapping method that was used (see ***How Sites are Located***, at the end of this section for more information).

Toxic Site Profiles summarize information provided by site owners or operators and government agencies regarding various toxic chemical activities reported at each site, such as:

- Whether chemicals were stored, produced, transported, discharged or disposed of.
- The name of chemicals and their Chemical Abstract Series (CAS) numbers.
- The amount of chemicals and the units (gallons/pounds) the chemical was measured in.
- Whether the site or storage tanks at the site are currently active or inactive.
- Special codes used by government agencies to regulate hazardous waste activities at some sites, or a complete description of the codes follows the profiles section.

For selected individual chemicals reported at various toxic sites, some potential health effect summary information appears below the site profile. Each potential health effect summary identifies chemicals by name and by Chemical Abstract Series (CAS) Number. An "x" under each potential health effect heading indicates positive toxicity testing results reported by the National Institute of Occupational Safety and Health's Registry of Toxic Effects of Chemical Substances (RTECS). Some chemicals (mostly appearing in profiles of Hazardous Waste facilities), are reported as mixtures, and RTECS health effect information is only available for individual chemicals. In addition, RTECS only provides information on approximately 100,000 common chemicals. Consequently, the absence of potential health effect summary information for a particular chemical identified in a Toxic Site Profile does not necessarily mean that the chemical does not pose potential health effects.

The Maximum Contaminant Level (MCL) in drinking water allowed for selected chemicals is also noted. In most cases, the only applicable MCL has been set by the New York State Department of Health (NYSDOH). Where NYSDOH has not set an MCL, the federal standard, if one exists, is listed and is marked by an asterisk.

Presented below are column headings that describe the health effect definitions used in RTECS and applicable New York State and federal drinking water standards. Reference sources for information presented in this section are also provided.

ACUTE TOX: **Acute Toxicity**: Short-term exposure to this chemical can cause lethal and non-lethal toxicity effects not included in the following four categories.

TUMOR TOX: **Tumorigenic Toxicity**: The chemical can cause an increase in the incidence of tumors.

MUTAG TOX: **Mutagenic Toxicity**: The chemical can cause genetic alterations that are passed from one generation to the next.

REPRO TOX: **Reproductive Toxicity**: May signify one of the following effects: maternal effects, paternal effects, effects on fertility, effects on the embryo or fetus, specific developmental abnormalities, tumorigenic effects, or effects on the newborn (only positive reproductive effects data for mammalian species are referenced).

IRRIT TOX: **Primary Irritant**: The chemical can cause eye or skin irritation.

MCL: **Drinking Water Standard - Maximum Contaminant Level** (MCL) listed under Drinking Water Supplies, 10 NYCRR Part 5, Subparts 1.51(f),(g), and (h) for NYDOH MCL's and under the Safe Drinking Water Act, 40 CFR 141, Subparts B and G, (* indicates value for total trihalomethanes) for federal MCL's.

Reference Source for Toxicity Information: Registry of Toxic Effects of Chemical Substances (RTECS), NIOSH (on-line database); For further information, contact: NIOSH, 4676 Columbia Parkway, Cincinnati, OH, 45226, 800/35-NIOSH.

Reference Source for Drinking Water Standards: New York State Department of Health, Bureau of Toxic Substances Assessment, 2 University Place, Room 240, Albany, NY 12203, 518/458-6373.

U.S. Environmental Protection Agency, Office of Drinking Water, 401 M St SW, Mailstop WH-556, Washington, DC, 20460, 202/260-5700.

Inactive Hazardous Waste Disposal Site Classifications:

1 -- Causing or presenting an imminent danger of causing irreversible or irreparable damage to the public health or the environment -- immediate action required;
2 -- Significant threat to the public health or environment -- action required;
3 -- Does not Present a significant threat to the environment or public health -- action may be deferred;
4 -- Site properly closed --requires continued management;
5 -- Site properly closed, no evidence of present or potential adverse impact -- no further action required;
2a -- This temporary classification has been assigned to sites where there is inadequate data to assign them to the five classifications specified by law;
A -- Work underway and not yet complete;
P -- Potential Site;
$D_{1, 2, 3}$ -- Delisted Site (1: hazardous waste not found; 2: remediated; 3: consolidated site or site incorrectly listed);
C -- Remediation Complete (formerly D2).

NO NATIONAL PRIORITIES LIST (NPL) SITES IDENTIFIED WITHIN 1 MILE SEARCH RADIUS

INACTIVE HAZ WASTE DISPOSAL REGISTRY OR REGISTRY−QUALIFYING SITES IDENTIFIED WITHIN 1 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 1 **PLEASANT AVENUE PLUME TRACKDOWN** **Facility Id: 231066**
PLEASANT AVENUE NEW YORK CITY, NY 10029 TT−Id: 120A−0007−274

MAP LOCATION INFORMATION
Site location mapped by: MAP COORDINATE − LARGE SITE
Approximate distance from property: 3259 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: PLEASANT AVE
Revised zip code: NO CHANGE

****

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
INACTIVE HAZARDOUS WASTE DISPOSAL SITE INFORMATION

SITE CODE: 231066
CLASSIFICATION CODE: N REGION: 2 DEC ID: 418905
CLASSIFICATION CODE DESCRIPTION:
No further action

NAME OF SITE: Pleasant Avenue Plume Trackdown
STREET ADDRESS: Pleasant Avenue TOWN: New York City
CITY: New York City ZIP: 10029 COUNTY: New York

ESTIMATED SIZE:
SITE TYPE: Dump− Structure− Lagoon− Landfill− Treatment Pond−

INSTITUTIONAL/ENGINEERING CONTROLS:
None reported

CROSS REFERENCES:
None reported

SITE OWNER/OPERATOR/REPOSITORY INFORMATION:
None reported

HAZARDOUS WASTE DISPOSAL PERIOD:

SITE DESCRIPTION:
PCE contamination in groundwater and soil vapor was observer in the area of Pleasant Avenue and East 115th Street during the remedial investigation of Consolidated Edison East 115th Street MGP Site, V00540. Immediately north of the MGP site is the East River Plaza brownfield site (C231045) which is now in the site management phase. The investigation area encompassed the area from Pleasant avenue to 1st Avenue and 114th Street to 118th Street. Evidence of VOC contamination in groundwater discovered during an RI at the Consolidated Edison site prompted the identification of this P (potential) site. However, the findings of the site characterization investigation showed no evidence of a PCE plume in the investigation area. The site was reclassified as an N in July 2011, which indicates that no further action is necessary.

CONFIRMED HAZARDOUS WASTE DISPOSED:
None reported

ASSESSMENT OF ENVIRONMENTAL PROBLEMS:
Evidence of VOC contamination in groundwater was discovered during an RI at the Consolidated Edison East 115th Street MGP Site Volunteer Cleanup project (V00540). A plume track down / site characterization investigation was conducted to determine the extent of VOC contamination and identify a source or sources if they are present. The plume track down investigation was conducted in late August / early September 2010. The investigation area encompassed the area from Pleasant avenue to 1st Avenue and 114th Street to 118th Street in east Harlem. Twenty−two sampling points throughout the area of were screened with a membrane interface probe (MIP) and groundwater samples were obtained for laboratory analysis The groundwater data didn't indicate the presence of a plume. The highest PCE concentration was 57 ppb found in a data point near a monitoring well on the MGP site where PCE was first detected. PCE was detected at two of the remaining 21 up− and side−gradient sampling points below the PCE groundwater standard of 5 ppb. The findings of the site characterization investigation showed no evidence of a PCE plume in the investigation area. The site was reclassified as an N in July 2011.

ASSESSMENT OF HEALTH PROBLEMS:
None provided

PROJECT COMPLETIONS:
Operable Unit 01 − Remedial Program

PROJECT	DESCRIPTION	END DATE	STATUS
Site Characterization		06/24/2011	No Further Action

The New York State Department of Environmental Conservation has not publicly updated the following fields since 2003:

ANALYTICAL DATA AVAILABLE FOR:	Air−	Surface Water−	Groundwater−	Soil−	Sediment−
APPLICABLE STANDARDS EXCEEDED IN:	Groundwater−	Drinking Water−	Surface Water−	Air−	

GEOTECHNICAL INFORMATION:
SOIL/ROCK TYPE:
GROUNDWATER DEPTH:

LEGAL ACTION:	Type:		State−	Federal−
STATUS:	Negotiation in Progress−		Order Signed−	
REMEDIAL ACTION:	Proposed−	Under Design−	In Progress−	Completed−

NATURE OF ACTION:

Map Identification Number 2 **VISTA 1** **Facility Id: 203052**
2401 THIRD AVENUE BRONX, NY 10451 TT−Id: 120A−0007−710

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 3872 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: 2401 3RD AVE
Revised zip code: NO CHANGE

****

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
INACTIVE HAZARDOUS WASTE DISPOSAL SITE INFORMATION

SITE CODE: 203052
CLASSIFICATION CODE: N REGION: 2 DEC ID: 437428
CLASSIFICATION CODE DESCRIPTION:
No further action

NAME OF SITE: Vista 1
STREET ADDRESS: 2401 Third Avenue TOWN: New York City
CITY: Bronx ZIP: 10451 COUNTY: Bronx

ESTIMATED SIZE: 1.538 Acres

SITE TYPE: Dump− Structure− Lagoon− Landfill− Treatment Pond−

INSTITUTIONAL/ENGINEERING CONTROLS:
None reported

CROSS REFERENCES:

IDENTIFIER	SOURCE

The following cross reference(s) have been deleted from the registry. Data reflects previous information.

203050	HW Site ID
203051	HW Site ID

SITE OWNER/OPERATOR/REPOSITORY INFORMATION:
CURRENT OWNER(S):

NAME: South Bronx Overall Economic Development Corporation (SoBRO)
Lourdes Zapata
ADDRESS: 555 Bergen Avenue
Bronx, NY 14055

OWNER(S) DURING DISPOSAL:

OPERATOR(S) DURING DISPOSAL:

APPLICANT REQUESTOR(S):
NAME: South Bronx Overall Economic Development Corporation (SoBRO)
Lourdes Zapata
ADDRESS: 555 Bergen Avenue
Bronx, NY 14055

HAZARDOUS WASTE DISPOSAL PERIOD:

SITE DESCRIPTION:
Part of Port Morris Zone 1 BOA. DEC #BOA00032 DOS #10BOA002 Site Investigation could not be funded under BOA since property owner would not allow access. No environmental data available for this site.

CONFIRMED HAZARDOUS WASTE DISPOSED:
None reported

ASSESSMENT OF ENVIRONMENTAL PROBLEMS:
None provided

ASSESSMENT OF HEALTH PROBLEMS:
None provided

PROJECT COMPLETIONS:
None reported

The New York State Department of Environmental Conservation has not publicly updated the following fields since 2003:

ANALYTICAL DATA AVAILABLE FOR:	Air–	Surface Water–	Groundwater–	Soil–	Sediment–
APPLICABLE STANDARDS EXCEEDED IN:	Groundwater–	Drinking Water–	Surface Water–	Air–	

GEOTECHNICAL INFORMATION:
SOIL/ROCK TYPE:
GROUNDWATER DEPTH:

LEGAL ACTION:	Type:	State–	Federal–
STATUS:	Negotiation in Progress–	Order Signed–	

REMEDIAL ACTION: Proposed– Under Design– In Progress– Completed–
NATURE OF ACTION:

NO RCRA CORRECTIVE ACTION SITES IDENTIFIED WITHIN 1 MILE SEARCH RADIUS

NO CERCLIS SUPERFUND SITES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

BROWNFIELDS SITES (STATE & LOCAL) IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 3 **1901 MADISON AVENUE** **Facility Id: 14CVCP160M**
1901 MADISON AVENUE, MANHATTAN, NY TT−Id: 330A−0000−301
VCP Project Id: 14CVCP160M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 935 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1748 Lot(s) 1

Click here for detailed site information. Copy and paste 14CVCP160M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 4 **23 W. 116 ST AND 1428 FIFTH AVE (2 SITES)** **Facility Id: 12CBCP034M**
1428 5TH AVENUE, MANHATTAN, NY TT−Id: 330A−0000−267
VCP Project Id: 12CBCP034M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1232 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: 1428 5TH AVENUE
Revised zip code: 10026

This facility has been deleted from the reported data. Data reflects last reported information.

Brownfield Program: NYC Voluntary Cleanup Program

Class: Completed

Parcels:

Click here for detailed site information. Copy and paste 12CBCP034M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 5 **2211 3RD AVENUE** **Facility Id: 12CBCP037M**
2211 3RD AVENUE, MANHATTAN, NY TT−Id: 330A−0000−277
VCP Project Id: 12CBCP037M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1322 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1785 Lot(s) 43, 46, 146

Click here for detailed site information. Copy and paste 12CBCP037M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 6 **23 WEST 116TH, 1428 FIFTH AVENUE** **Facility Id: 12CBCP033M**
1428 5TH AVENUE, MANHATTAN, NY TT−Id: 330A−0000−266
VCP Project Id: 12CBCP033M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1468 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10026

Brownfield Program: NYC Voluntary Cleanup Program

Class: Completed

Parcel(s): Block 1600 Lot(s) 20

Click here for detailed site information. Copy and paste 12CBCP033M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 7 **HARLEM PARK** **Facility Id: C231041**
1800−1808 PARK AVE 71 E. 124 ST., 66−70 E 125 ST., NEW YORK, NY 10035−1940 TT−Id: 320A−0001−600

MAP LOCATION INFORMATION
Site location mapped by: MAP COORDINATE (1)
Approximate distance from property: 1473 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: Brownfield Cleanup Program

****

DIVISION OF ENVIRONMENTAL REMEDIATION
BROWNFIELD CLEANUP PROGRAM

SITE CODE: C231041
CLASSIFICATION CODE: A REGION: 2 DEC ID: 59177
CLASSIFICATION CODE DESCRIPTION:
Work is underway and not yet complete.

NAME OF SITE: Harlem Park
STREET ADDRESS: 1800−1808 Park Ave 71 E. 124 St., 66−70 E 125 St. TOWN: New York City
CITY: New York ZIP: 10035−1940 COUNTY: New York

ESTIMATED SIZE: 1 Acre

SITE TYPE: Dump− Structure− Lagoon− Landfill− Treatment Pond−

INSTITUTIONAL/ENGINEERING CONTROLS:
None reported

CROSS REFERENCES:

IDENTIFIER	SOURCE
0402211	Spill No.
w2−1037−04−12	Agreement/Consent Order Number

SITE OWNER/OPERATOR/REPOSITORY INFORMATION:
CURRENT OWNER(S):
NAME: Harlem Park Acquisition LLC
Michael J. Merola
ADDRESS: 30 West 21st Street, 11th Floor
New York, NY 10010

OWNER(S) DURING DISPOSAL:

OPERATOR(S) DURING DISPOSAL:

APPLICANT REQUESTOR(S):
NAME: 1800 PARK AVE., LLC
MICHAEL CARIDI
ADDRESS: 32 Cutler Road
Greenwich, CT 06831

DOCUMENT REPOSITORY(S):
NAME: New York Public Library Harlem Branch
ADDRESS: 9 West 124th Street
New York, NY 10027−5699

NAME: NYSDEC Region 2 Office
ADDRESS: 47-40 21st St.
Long Island City, NY 11101

HAZARDOUS WASTE DISPOSAL PERIOD:

SITE DESCRIPTION:
Location: The Site is located in an urban area of New York County (Manhattan) on the west side of Park Avenue bounded by 124th and 125th Streets. The addresses for the site are 1800-1808 Park Avenue, 71 East 124th Street, and 66-70 East 125th Street. Site features: The site is paved and used as a parking lot. There are no on-site buildings.

Current zoning/uses: Surrounding uses include residential buildings with first floor retail, and commercial buildings with office space to the north across 125th Street; the Metro-North Railroad tracks to the east along Park Avenue, residential buildings across Park Avenue; an asphalt-paved parking lot to the south across 124th Street; and a residential building with first floor retail and the New York College of Podiatric Medicine to the west. The Site is zoned C4-4 for commercial use. Historic use: The Site had been residential and had been the location of the former Harlem Central Hotel (later the Hotel Naomi) through the 1970s. It has been a parking lot since approximately 1980. These uses contributed to the contamination identified on-site.

Site geology and hydrogeology: The Site is underlain by man-made fill to a depth of approximately 20 feet below grade, glacial lake deposits and till, and bedrock. Published geologic data indicate that the bedrock consists of Ordovician/Cambrian age metamorphic rock. In the vicinity of the Site, bedrock consists of Manhattan Formation (schist) surrounded by a larger area underlain by the Inwood Formation (marble). The groundwater table is found at approximately 14 to 16 feet below grade and the gradient is toward the southwest.

CONFIRMED HAZARDOUS WASTE DISPOSED:

TYPE	QUANTITY
LEAD	UNKNOWN
POLYCHLORINATED BIPHENYLS (PCB)	UNKNOWN
BENZ(A)ANTHRACENE	UNKNOWN
BENZO(B)FLUORANTHENE	UNKNOWN
BENZO(A)PYRENE	UNKNOWN
benzo(a)anthracene	UNKNOWN
Petroleum Products	UNKNOWN

ASSESSMENT OF ENVIRONMENTAL PROBLEMS:
Nature and extent of contamination: The RI and subsequent supplemental investigations at the site included the collection of soil and groundwater samples the analyses of which identified the contamination of environmental media as follows. Soil: Historic fill is present on the site to a depth of approximately 20 feet below grade. A layer of petroleum contamination was identified at the water table across much of the site, varying in thickness up to approximately three feet. Fingerprint analysis of the petroleum layer identified it as #6 fuel oil. In addition to soil grossly contaminated by the petroleum layer, several hot spots were identified that exhibited exceedances of both Unrestricted Use Soil Cleanup Objectives (UUSCOs) and Restricted Residential Use (RRUSCOs) as well as the Site Specific SCOs (SSSCOs). These included exceedances for lead including hazardous levels; 1,050 parts per million (ppm) compared to the UUSCO of 63 ppm and RRUSCO of 400 ppm; and SVOCs namely carcinogenic Polycyclic Aromatic

Hydrocarbons (cPAHs) including; benzo(a)pyrene at 3.2 ppm , benzo(a)anthracene at 3.7 ppm and benzo(b)fluoranthene at 3.6 ppm compared to the UUSCO and RRUSCO of 1 ppm. Groundwater: No exceedance of groundwater standards by organic compounds was noted. Filtered groundwater samples showed exceedances of groundwater standards for aluminum, iron and manganese.

In May 2011, a trace of free−phase petroleum was identified in one well and was not sampled at that time. The well was subsequently monitored in October 2011, and no trace of petroleum was identified at that time.

The analytical results of the groundwater samples indicated no VOCs or SVOCs were detected above Class GA standards, and no dissolved lead was detected in the groundwater. Dissolved manganese was detected in five wells exceeding the Class GA standard of 300 parts per billion (300 ppb), but in only one area with a corresponding soil sample exceeding the Protection of Groundwater SCO. These results indicate a regional groundwater issue that is not Site related.

Special resources impacted/threatened: There were no significant ecological resources identified at the site during the investigation. Significant threat: NYSDEC, in consultation with NYSDOH, has determined that the site conditions do not pose a significant threat to human health or the environment.

ASSESSMENT OF HEALTH PROBLEMS:

Since the site is fenced and covered by asphalt, people will not come into contact with site−related soil and groundwater contamination unless they dig below the surface. People are not drinking the contaminated groundwater since the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there is no on−site building, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on−site development.

PROJECT COMPLETIONS:

Operable Unit 01 − Remedial Program

PROJECT	DESCRIPTION	END DATE	STATUS
Remedial Design	Harlem Park	03/31/2006	Actual
Remedial Investigation		03/31/2006	Actual
Remedial Investigation Amendment		05/28/2013	Actual

****

Map Identification Number 8 **81 WEST 125TH STREET** **Facility Id: 13CVCP120M**

81 WEST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−294

VCP Project Id: 13CVCP120M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1662 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: 81 E 125TH ST
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Completed

Parcel(s): Block 1750 Lot(s) 34

Click here for detailed site information. Copy and paste 13CVCP120M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 9 **69 EAST 125TH STREET** **Facility Id: 15CVCP122K**
69 EAST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−501
VCP Project Id: 15CVCP122K

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1695 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1750 Lot(s) 28, 29, 30

Click here for detailed site information. Copy and paste 15CVCP122K in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 10 **69 EAST 125TH STREET** **Facility Id: 15CVCP122M**
69 EAST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−336
VCP Project Id: 15CVCP122M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1695 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class:

Parcel(s): Block 1750 Lot(s) 28, 29, 30, 44

Click here for detailed site information. Copy and paste 15CVCP122M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 11 **146 EAST 126TH STREET** **Facility Id: 15CVCP149M**
146 EAST 126TH STREET, MANHATTAN, NY TT−Id: 330A−0000−340
VCP Project Id: 15CVCP149M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1986 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: UNKNOWN

Brownfield Program: NYC Voluntary Cleanup Program

Class:

Parcel(s): Block 1774 Lot(s) 30

Click here for detailed site information. Copy and paste 15CVCP149M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 12 **CHURCH OF SCIENTOLOGY−SITE A** **Facility Id: 11CBCP004M**
220 EAST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−270
VCP Project Id: 11CBCP004M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2071 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1789 Lot(s) 39

Click here for detailed site information. Copy and paste 11CBCP004M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 13 **5 WEST 125TH** **Facility Id: 13CVCP115M**
5 WEST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−293
VCP Project Id: 13CVCP115M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2088 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10027

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1723 Lot(s) 31, 45, 144

Click here for detailed site information. Copy and paste 13CVCP115M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 14 **CHURCH OF SCIENTOLOGY−SITE B** **Facility Id: 11CBCP005M**
220 EAST 125TH STREET, MANHATTAN, NY TT−Id: 330A−0000−654
VCP Project Id: 11CBCP005M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (2)
Approximate distance from property: 2153 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1789 Lot(s) 34, 35, 36

Click here for detailed site information. Copy and paste 11CBCP005M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

Map Identification Number 15 **110 LENOX AT 125TH STREET** **Facility Id: 13CVCP091M**
281 LENOX AVENUE, MANHATTAN, NY TT−Id: 330A−0000−288
VCP Project Id: 13CVCP091M

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2440 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10027

Brownfield Program: NYC Voluntary Cleanup Program

Class: Active

Parcel(s): Block 1909 Lot(s) 25, 26, 27, 28, 29, 129, 30, 31, 32, 33, 38, 39, 140

Click here for detailed site information. Copy and paste 13CVCP091M in the search box, click the green search button, then click the Project ID # to see downloadable site documents.

NO SOLID WASTE FACILITIES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

NO HAZARDOUS WASTE TREATMENT/STORAGE/DISPOSERS IDENTIFIED WITHIN THE 1/2 MILE SEARCH RADIUS

HAZARDOUS MATERIAL SPILLS INTRODUCTION

The Hazardous Material Spills in this section are divided into eight spill cause groupings. These include:

Active Spills Section: Spills with incomplete paperwork that may or may not be cleaned up (See Date Cleanup Ceased)

1) Tank Failures
2) Tank Test Failures
3) Unknown Spill Cause or Other Spill Cause Hazardous Spills
4) Miscellanous Spill Causes: Equipment Failure, Human Error, Tank Overfill, Deliberate Spill, Traffic Accidents, Housekeeping, Abandoned Drum, Vandalism and Storms.

Closed Status Spills Section: Spills with completed paperwork that may or may not be cleaned up (See Date Cleanup Ceased)

5) Tank Failures
6) Tank Test Failures
7) Unknown Spill Cause or Other Spill Cause Hazardous Spills
8) Miscellanous Spill Causes: Equipment Failure, Human Error, Tank Overfill, Deliberate Spill, Traffic Accidents, Housekeeping, Abandoned Drum, Vandalism and Storms.

All spills within each spill cause category are presented in order of proximity to the subject site address.

Please note that spills reported within 0.25 mile (or one−eighth mile in New York City) are mapped and profiled.

Between 0.25 mile (or one−eighth mile in New York City) and 0.5 mile, only the following spills are mapped and profiled:

* Tank Failures;

* Tank Test Failures;

* Unknown Spill Cause or Other Spill Cause;

* Spills greater than 100 units of quantity; and

* Spills reported in the NYSDEC Fall 1998 MTBE Survey.

A table at the end of each section presents a listing of reported Miscellanous Spills with less than 100 units located between 0.25 mile (or one−eighth mile in Manhattan) and 0.5 mile. These spills are neither mapped nor profiled.

NO ACTIVE TANK FAILURES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

ACTIVE TANK TEST FAILURES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 16 **NYC PARKS** **Spill Number: 0515023** **Close Date:**
122 ND & 5TH AVE MANHATTAN, NY TT−Id: 520A−0099−405

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 1232 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: 122ND / 5TH AVE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	GABE RAMOS − NYC PARKS	Spiller Phone:	(212) 410−8916
Notifier Type:	Tank Tester	Notifier Name:	MICHEAL SEPE	Notifier Phone:	(631) 586−4900
Caller Name:	MICHEAL SEPE	Caller Agency:	FENLEY & NICHOL	Caller Phone:	(631) 586−4900
DEC Investigator:	adzhitom	Contact for more spill info:	GABE RAMOS	Contact Person Phone:	(212) 410−8916

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/31/2006		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	5000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

DIG UP AND RETEST

DEC Investigator Remarks:

04/03/06−Hiralkumar Patel. TTF letter sent out to Mr. Ramos.

09/02/09−Hiralkumar Patel. 1:18 PM:− received email from Mr. Ramos. NYC DDC removed and replaced tank in March 2009.

Gabe Ramos Dep. Chief of Citywide Operations City of New York, Parks & Recreation 5−Boro Operations Randalls Island, NY 10035 Ph. (212) 410−8916 email: Gabriel.Ramos@parks.nyc.gov

05/24/12−Hiralkumar Patel. 2:02 PM:− sent email to Mr. Ramos inquiring updates.

10/06/14−Hiralkumar Patel. as per DEC Austin, case assigned to DEC Vadim.

DEC requries: 1) tank closure report (any contamination along any lines or under tank, which part failed)

07/29/2015 Reviewed a Request for Closure dated April 8, 2015. Discussed the site with K. Shanahan (URS). The report proposed the closure based on the results of the closure report dated April 2009. However, the post excavation samples were all taken along the centerline of the excavation. No samples were taken at the sides of the excavation. Also, no samples were taken at the fill port location and supply/return lines. It should be noted that this tank system failed two tightness tests. I contacted K. Shanahan and discussed this site. It was decided that URS will take additional soil samples at the sides of the excavation, return and fill lines, and the fill port. URS will submit a brief work plan for the site. AZ

7−30−2015 The following e−mail was sent to K. Shanahan and V. Brevdo:

Dear Kevin,

I have reviewed a report for the above site dated April 8, 2015. As we have discussed over the phone, all post excavation soil samples were taken only along the centerline of the excavation. No side samples were taken. Also, no samples were taken at associated piping and former fill port locations.

As we have agreed, Aecom will submit a work plan to sample the above mentioned locations.

Sincerely,

Alex Zhitomirsky − Engineering Geologist 2 NYS Department of Environmental Conservation 47−40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 − Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov

1−22−2016 Reviewed a Work Plan dated November 4, 2015. The Work Plan proposed installation of three groundwater monitoring wells and advancement of three soil borings in the former 5,000−gallon heating UST. The following email was sent to K. Shanahan and V. Brevdo:

Dear Kevin,

I have reviewed a Work Plan for this site. In order to examine the potential environmental impacts from the former 5,000−gallon

UST, URS proposed to advance six soil borings. Three of them will be converted to wells.

This Work Plan is approved. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on− and off−site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its contractors are solely responsible for the implementation of all appropriate health and safety measures during the performance of this work.

Sincerely,

Alex Zhitomirsky − Engineering Geologist 2 NYS Department of Environmental Conservation 47−40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 − Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov

Map Identification Number 17 **TAFT HOUSES −NYCHA** **Spill Number: 9315466** **Close Date:**
1740 MADISON AVENUE NEW YORK, NY TT−Id: 520A−0095−994

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1605 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NYCHA − JOE MONTELLA	Spiller Phone:	(212) 306−3142
Notifier Type:	DEC	Notifier Name:		Notifier Phone:	
Caller Name:	JANE HEALY	Caller Agency:	NYS DEC	Caller Phone:	(718) 482−4933
DEC Investigator:	jkkann	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/22/1991		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

LEAK RATE OF −0.08 GPH − REPORTED AS PASSED BY TESTER −

DEC Investigator Remarks:

01/05/06: This spill transferred from J.Kolleeny to S.Kraszewski. No site investigation ever performed at this site. No tank closrue report for tank 001, removed in 1998 or tank 002 which is closed in place. − SK

01/09/06: Reviewed Phase II Assessment Report from A.L. Eastmond and Sons Inc., submitted in the summer of 1998. This assessment was performed to discover the extent of the contamination found during excavation of tank #1 as well as satisfy the legal abandonment of tank #2.

During excavation, all soil recovered from the site was disposed of via trucking to a designated landfill. All old piping was also removed and clean fill replaced the contaminated soil. No GW was encountered. Five post−excavation soil samples were taken from the pit:

−one composite sample from each side of the pit

−one composite sample taken from the bottom of the pit

Lab analysis of the samples does not coincide with what is required by STARS Memo #1. Only TCLP parameters were followed, which is not a substitute for the VOC and SVOC contaminant list in STARS or TAGM 46. Soil samples analyzed under the STARS and TAGM memos in needed from this site.

No free product or GW was encountered during excavation. − SK

03/22/06: This spill transferred to K.Tang. − SK

10/9/08: Spill reassigned to J.Kann. Spill 9402166 was closed to consolidate with this spill. Met with NYCHA and their consultant (Prefferred Environmental) on October 3 to discuss requirements of the site. Proposed and agreed to the installation of 6 borings (collection of gw and soil from each). Work Plan will be submitted shortly.

11/19/08: J.Kann − Work Plan submitted on 11/19/08.

07/20/10: J.Kann − SIR received on 7/15/10 and edoced.

12/26/12 : J.Kann − comments on SIR emailed today and edoced.

7/29/13: J.Kann − revised SIR received on 4/18/13. Email approving additional delineation work sent to NYCHA on 5/17/13. Report due 11/18/13.

4/28/14: J.kann − visited the site. 4 additional wells are being installed. Gauged MW−2 and MW−3 while at the site. MW−2 has a sheen of thick oil and MW−3 had a sock placed in it with no oil stainging and no oil detected in the well. Inspected the boiler

room. Minimal staining on the east wall at the location where the wall meets the floor (no fresh oil). Some staining on the south wall/floor which appears more fresh.

11/20/14 − J.Kann − SIR received on 7/17/14. Monitoring well oil/water levels 12 week study received on 11/3/14 and under review.

Map Identification Number 18 **ABOVE GROUND TANK − TTF** **Spill Number: 1307857** **Close Date:**
17 WEST 125TH ST NYC, NY TT−Id: 520A−0293−345

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2113 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	TREE TOP DEVELOPMENT − NO ONE	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	AXDORONO	Contact for more spill info:	CHRISTOPHER STEELE	Contact Person Phone:	(718) 624−4842

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/01/2013		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	UNKNOWN	0	UNKNOWN	

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

Dry leak. repairs retest pending. Assigned to DEC Demeo for followup.

03−18−2015 − V. Brevdo This TTF Spill Case is re−assigned to Remediation Section B as per discussion with Chief of Spill Response on 03/17/2015. Case is further assigned to Ms. Ainura Doronova as Project Manager. − VB

03/18/2015: This spill case was transferred to A. Doronova. − AD

04/21/2015: Looked for the owner’s info in the PBS database. There are three different search results for the same address with

three different PBS IDs. Will look in Acris. AD

04/24/2015: Looked in Acris. The property block is 01723, lot is 0023. AD

04/29/2015: Asked advise from PBS−unit regarding the issue with three different search results for the same address with three different PBS IDs. They will look into it. AD

05/01/2015: Received the following response from PBS−unit:

There are three PBS numbers for the same tank at subject address, but only 2−612163 is active. Both 2−340464 and 2−605389 are inactive because we discovered back in January that they were duplicates (triplicates?) of 2−612163. We used to call this situation ˆAdministratively Closed˜ but now it´s just ˆInactive˜.

According to PBS database, the contact person for this site is − Peter Garsia, phone number: (646)335−0730.

Address: 17 West 125 Holdings, LLC 200 West 106th Street New York, NY 10025

Issued and sent a certified TTF Letter (# 7010 0290 0000 9758 3458) to Mr. Peter Garcia of 17 West 125 Holdings, LLC. Response is due June 1, 2015. AD

Map Identification Number 19 **CONVENT** **Spill Number: 0802029** **Close Date:**
226 EAST 113TH STREET NEW YORK, NY TT−Id: 520A−0214−868

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2217 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	MARLON JOSEPH − CONVENT	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	VXBREVDO	Contact for more spill info:	MARLON JOSEPH	Contact Person Phone:	(718) 624−4842 ext. 1

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/21/2008		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	1080	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

dry portion leak

DEC Investigator Remarks:

PBS #2−209260 TTF letter sent to: Our Lady Queen of Angels Church Attn: Fr. Gerard Mulvey 232 East 113rd Street New York, NY 10029

6/11/08 letter returned by USPS and marked Moved . bf

07/16/13 − Spill Case is transferred from Brian Falvey (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision − Tank Test Failure Spill Case. VB

Map Identification Number 20 **PVT DWELLING − TTF** **Spill Number: 1205657** **Close Date:**
19−21 EAST 109 ST NEW YORK, NY TT−Id: 520A−0275−698

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2639 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: 19−21 EAST 109TH ST
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	JOHN ROGERS	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	TJDEMEO	Contact for more spill info:	JOHN ROGERS	Contact Person Phone:	(732) 598−8920

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/06/2012		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	

Caller Remarks:

3000gal agt

DEC Investigator Remarks:

9/21/12 TJD TTF letter sent (on E−DOCS).

4/3/13 AFrischeisen intern Call with kate from Levites Realty. She referred me to Mike leon (Leon@levitesrealty.com) but also stated that the tank in question was removed in November 2012 and replaced with a new tank. I emailed Mike Leon (cc TJ DeMeo) asking him to send over all relevant documents. Email reproduced below:

Hi Mr. Leon,

I was referred to you by Kate at your office. My name is Alejandro Frischeisen, an intern for Tim DeMeo, at the NYS Department of Environmental Conservation. I'm writing in regards to the open spill case at 19−21 E 109th St in Manhattan, Spill # 1205657. We hadn't heard any updates following the tank test failure September 2012. According to your PBS registration #2−290726, the tank was closed in November 2012. Kate also stated that the old tank was removed and a new tank put in place. In order to move forward on the open spill case, I ask that you please send over the original tank test failure report, any soil samples/analyses that were taken to demonstrate no soil contamination, the documents for the installation of the new tank, and the subsequent tightness test performed on the new tank. These documents can all be emailed to Tim DeMeo at tjdemeo@gw.dec.state.ny.us.

ACTIVE UNKNOWN CAUSE SPILLS AND OTHER CAUSE SPILLS IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 21 **SOIL** **Spill Number: 1506992** **Close Date:**
2211 3RD AVE NEW YORK, NY TT−Id: 520A−0313−200

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (3)
Approximate distance from property: 1324 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: 2211 3RD AVE MAZAL LLC Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: HRPATEL Contact for more spill info: DEREK ERSBAK Contact Person Phone: (631) 589−6353

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/02/2015		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL

Caller Remarks:

Caller advised visual stain and odor from the soil. Clean up is pending.

DEC Investigator Remarks:

10/02/15−Hiralkumar Patel. alternate address: 2211−2217 3rd Ave, 200−216 East 121st St

no PBS or other spills found.

environmental restrictions for Hazmat

−−−−−−−−−−−−−−−−−−

2211 Third Avenue Mazal LLC.

property owner c/o HAP Investments LLC 3 East 54th Street, 15th Floor New York, NY 10022 Attn.: Monzer Khafagy Ph. (646) 559−5732 email: monzer@hap−ny.com

Derek Ersbak P.W. Grosser Consulting PH. (631) 589−6353 Fax (631) 589−8705 email: dereke@pwgrosser.com

William Wong NYC OER Ph. () email: wiwong@dep.nyc.gov case #: 12CVCP037M & 12EHAZ218M

Darek sent email to OER Wong stating that during excavation activities today, visually stained soil was encountered in Grid 5 at a depth of approx. 12 ft bg. the location of the visually stained soil lines up closely with the former location of the UST in Grid 5. there were no signs of a release initially during removal of the UST and the endpoint samples collected at 10 ft did not indicate a release.

downloaded RIR and RAWP from NYC OER's database.

abstract of RIR: − report dated Dec. 2011 − site includes three lots on block #: 1785: 43, 46 and 146 − proposed future use of the site will consist of a new 12 story residential building which will include affordable residential units and first floor retail space or community center space − building will also include a basement, which will require excavation to approx. 10 ft bg − each of the three lots comprising the site was developed prior to 1896 with four−story row houses. lot 46 was redeveloped prior to 1911 with a large four story building with basement which was utilized as a department store, furniture store and several other commercial uses until it was demolished in 2008. the four−story row houses on lots 146 and 43 remained in place until the late 1970's/early 1980's. the upper floors were likely utilized as residential apartments, and the first floor of both buildings as small stores − Phase I conducted in Oct. 2011 − Phase I concluded that additional work was necessary to properly close out a 3,000 gal #2 fuel oil UST which may be located beneath the sidewalk of E 121st St − a geophysical survey was performed and no UST−like anomalies were found − elevation of the property is approx. 16 ft above mean sea level − installed nine soil borings (B1 through B7, T1 and T2), to a depth of 15 ft bg and collected total of 12 soil samples − stratigraphy of the site, from the surface down, consists of urban fill, which was primarily comprised of brick, concrete, wood and other debris in a brown silty−sand matrix. the layer of urban fill extended to a depth ranging from of approx. 7 to 15 ft bg − no PID readings above background concentrations were obtained from any of the soil borings − installed five (5) 1−inch temporary monitoring wells to a depth of 19 ft bg; with 10 ft of screen − monitoring wells were installed in borings B1, B4, B5, B6 and B7 and collected 5 groundwater samples − depth to groundwater ranges from 12 to 15 ft bg − groundwater flow is generally from west to east − installed four (4) soil−vapor probes to a depth of 8 ft bg − no contamination noted in soil and groundwater samples − minor petroleum VOCs and CVOCs were detected in soil−vapor samples

10/13/15−Hiarlkumar Patel. 8:54 AM:− received message from Derek. 1:04 PM:− left message for Derek. 2:02 PM:− received call from Derek. they are removing the contaminated materials and will collect endpoint samples.

10/20/15−Hiralkumar Patel. received email from Derek (at 10:15 AM on 10/16/15). they received acceptance documentation from the disposal facility. contractor plans to remove material next week. will collect endpoint samples, once all visually stained soil is removed. Derek also included link to dropbox folder for the site which included tank closure report dated Oct. 2015.

abstract of tank closure report: − one (1) 1,000 gal #4 oil UST was removed − upon removal, the UST was found to be in good condition with no visual corrosion holes − since there was no evidence of a discharge, four endpoint bottom soil samples were collected from centerline of the excavation − no VOCs detected − minor SVOC contamination noted

01/05/16−Hiralkumar Patel. 9:01 AM:− received email from Derek including daily status report for 01/04/16. they started removing petroleum impacted soil.

01/06/16−Hiralkumar Patel. 9:19 AM:− received email from Derek including daily status report for 01/05/16.

01/07/16−Hiralkumar Patel. 8:22 AM:− received email from Derek including daily status report for 01/06/16. he mentioned that endpoint samples were collected from site. there is still little bit of impact to remove underneath the ramp which will occur at a later date.

01/08/16−Hiralkumar Patel. 3:51 PM:− received email from Derek including result summary of endpoint samples collected on 01/06/16. total eight soil (five sidewalls and three bottom) samples were analyzed. no contamination noted in samples. Derek mentioned that contamination in ramp area will be removed in future.

02/03/16−Hiralkumar Patel. 9:40 AM:− received email from Derek including daily status report for 01/28/16.

sample result summary table and site map on hard driver. waiting for final report after removal of remaining contaminated soil from underneath the ramp.

Map Identification Number 22 **SOIL** **Spill Number: 1501648** **Close Date:**
1800 PARK AVE NEW YORK, NY TT−Id: 520A−0309−004

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (3)
Approximate distance from property: 1366 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	snboller	Contact for more spill info:	RAUL RAMIREZ	Contact Person Phone:	(212) 675−3225

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/13/2015		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	

Caller Remarks:

Caller advised was doing drilling and found unknown amount of unknown petroleum in the soil. Clean up is pending. Caller was advised by DEC contact Sean Bollers.

DEC Investigator Remarks:

5/14/15 TJD Spoke with Sean Bollers − he has an active BCP project at this property and will manage the spill file.

Map Identification Number 23 **1800 PARK AVE** **Spill Number: 0402211** **Close Date:**
1800 PARK AVE NEW YORK CITY, NY TT−Id: 520A−0091−524

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1366 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Other
Caller Name: CURT SCHMIDT
DEC Investigator: snboller

Spiller: MICHAEL CARIDI
Notifier Name: CURT SCHMIDT
Caller Agency: FLEMMING−LEE SHUE
Contact for more spill info: MICHAEL CARIDI

Spiller Phone: (212) 848−0253
Notifier Phone: (212) 675−3225
Caller Phone: (212) 675−3225
Contact Person Phone: (212) 848−0253

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/28/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	SOIL

Caller Remarks:

looks like historical ground water contamination. they think it is coming from off site

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE Contaminated Soil/groundwater letter sent to:

Development Manager: Michael Caridi (212−848−0253)

Address: 1800 Park Ave LLC.

645 Fifth Ave − 8th Flr

New York, NY 10022

Site is now a vacant lot which is being developed into the the Harlem Marriot Hotel to be built on Park Ave between 124th St & 125th St.

Contamination showed up in several monitoring wells. Developer plans on extensive excavation to install foundations and sub basements. During excavation soil will be sorted for disposal. Once the excavation is complete, a determination will be made concerning which direction the contamination is coming from.

06/22/06: This spill is transferred from Mr.koon Tang to Q.Abidi. Called to Mr. Michael Caridi (212)848−0253 and left message to call me back regarding information of spill. −QA

07/19/06: Called Mr. Arnold Fleming at (212)675−3225 and left message to call me back. −QA

11/14/06: Called Mr. Michael Caridi and left message to call me back. Called Mr. Arnold fleming (Flemming −Lee Shue) he said that he will talk to client (Hospital) and he will fax me the information regarding spill. −QA

02/15/07: Called Fleming Lee Shue Company at (212)675−3225 and talk to Ms. Marry Nanso, Project Director of the Company. She said that her Company is going to do the Remediation at the site. They have not started yet the remediation work. She said Mr. Shawn Bollers (DEC) (718)482−4608, Project Manager, Brownfield Programme, DEC will take care of this spill. −QA

06/26/2008: This spill case was transferred to A. Doronova − AD

11/04/2008: Called and left a message to M. Manto of FLS and to M. Caridi (phone: 212−935−3550)of Park Avenue LLC. AD

05/07/2009: This case was transferred to S. Bollers − SB BCP Project Manager.

Map Identification Number 24 **MORRIS PARK HOUSES −NYCHA** **Spill Number: 9513238** **Close Date:**
17 EAST 124TH ST NEW YORK, NY TT−Id: 520A−0092−274

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1518 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Responsible Party
Caller Name: DAVID FORTE
DEC Investigator: jkkann
Spiller: FRANK OCELLO − NYC HOUSING
Notifier Name: SUPERINTENDENT
Caller Agency: NYC HOUSING
Contact for more spill info: SUPER
Spiller Phone: (212) 306−3229
Notifier Phone: (212) 722−7880
Caller Phone: (212) 306−3233
Contact Person Phone: (212) 722−7880

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/20/1996		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	15.00	GALLONS	15.00	GALLONS	GROUNDWATER

Caller Remarks:

GROUND SEAPAGE

DEC Investigator Remarks:

12/16/05: This spill transferred from J.Kolleeny to S.Kraszewski.

03/23/06: This spill transferred to K.Tang − SK

3/10/11: J.Kann − Investigative work plan submitted on 3/3/11.

5/29/12: J.kann − priority P0 assigned to the site

2/11/15: J.Kann − reviewed file. Appears that seapage into basement occured around 1995. Wells were installed at that time. No product noted from 1997 gauging logs. Approved plan provided that is existing wells are not found, up to 3 new wells will need to be installed. SIR is due August 12, 2015

10/29/15: J.Kann − received a call from Drew Pardus regarding the site. He indicated that it will be very difficult to advance

the borings around the tank where it is in the rear of the building (no easy access). He proposed using a jack hammer to get through the concrete and attempt to collect samples that way. He said he did not observe any wells in the basement. I looked through the files and found photos showing when the wells were installed. May need to make a site visit.

11/16/15: J.Kann − visited the site today. The boiler room was redone since the 1997 photos, and the wells are no longer present. Climbed up to see the location of the tank. It is impossible to bring a geoprobe to the tank area. The adjoining property has a narrow walkway to the back. but there is a height elevation change between the tank and the adjacent property. Need to consider options for the site. NYCHA will look through their files and determine if they have any additional information about the site. I do have some well data indicating that no product was present. After any new information is located, it will be submitted to the DEC. A discussion with Pardus will be made to determine what action is necessary.

Map Identification Number 25 **KING TOWERS −NYCHA** **Spill Number: 9102023** **Close Date:**
90 LENOX AVE NEW YORK CITY, NY TT−Id: 520A−0095−978

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 2079 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10026

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NYCHA	Spiller Phone:	(212) 876−1309
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	SUPT DABUSKY	Caller Agency:	NYCHA	Caller Phone:	(212) 289−3940
DEC Investigator:	jkkann	Contact for more spill info:		Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/20/1991		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SEWER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

POSSIBLE SEEPAGE FROM UNDERGROUND TANK,MAY BEING OVERFLOWING DUE TO FLOOD IN BOILER ROOM, EPA,NYCFD HAZ MAT NOTIFIED,WILL BE CONTRACTING TO CLEAN UP SPILL.

DEC Investigator Remarks:

01/23/06: This spill transferred from J.Kolleeny to S.Kraszewski. Two 25K tanks installed in 1954. TTF in 1989 followed by installation of some MWs. TTF in 1991 followed by Phase II Investigation. A passive recovery system was installed in the boiler room to collect fuel oil seepage. Unsure about monitoring records for wells and recovery system. Need to contact NYCHA for an update. − SK

9/22/06: Spill transferred from Kraszewski to Kann.

7/31/07: J.Kann − WP submitted 7/27/07 and is under review.

7/20/10: J.Kann − WP received on 7/15/10.

9/21/10: J.Kann − Quarterly Report Rcvd 9/1/10.

2/4/11: J.Kann − Qrtly Rpt rcvd 1/6/11 and edoced.

5/11/12: J.Kann − quarterly report recieved on 5/9/12.

9/6/12: J.kann − quarterly report received on 8/21/12.

8/27/15: J.Kann − visited site. Confirmed the Pardus diagram that oil seepage is actually occurring on the north and east side of the building. The oil mop is no longer present. Significant water flow noted in the basement traveling through a drain and discharging. Need to follow up with NYCHA on what the issues are with the excess water draining in the basement. The exterior of the building is undergoing extensive renovations and may limit drilling access (scaffolding and chain link fences present). However, NYCHA rep on site, Michael Lopez, noted that gates are present to provide access into the courtyards.

8/28/15: J.kann − sent email to Yelena Tkach and Michael Lopez of NYCHA: Yelena−

A site visit was made to the referenced site on August 27, 2015 and the diagram (attached) submitted by Pardus in your August 11 email was reviewed. Based on the site visit and the diagram, the Department has the following comments:

−The oil seepage does appear to be an issue on the north and eastern walls in the boiler room. Based on this, soil borings SB−7 and SB−8 and MW−6 should be advanced along the eastern wall of the building, not along the western wall as depicted in the diagram. An attempt should be made to locate these borings close to the areas of the observed seepage.

−Given that MW−2 had a history of product and can no longer be located, the Department concurs that a new well MW2A should be installed in the area of former MW−2.

−During the visit a steady significant flow of water was noted coming from equipment/piping along the eastern wall of the boiler room. The water was flowing in a westerly direction towards the floor drains. What is the source of this water? Is it a common occurrence? Where does the drain lead to?

Construction is on−going around the site building, however it seems as though access is possible in the area around the tank. The SIR is due to the Department by November 30, 2015.

Please let me know if you have any questions.

12/7/15: J.Kann − Drew Pardus is conducting field work on behalf of NYCHA today. He sent an email indicating that MW−4 was closer to the building than shown in the work plan drawing. I responded that I still want a boring between MW−4 and the building to get a sense of soil condition in the area given the historic seepage along that side of the building.

Map Identification Number 26 **NYC PS 155 SCHOOL** **Spill Number: 1509644** **Close Date:**
319 E117TH ST MANHATTAN, NY TT−Id: 520A−0313−308

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2240 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: 319 E 117TH ST
Revised zip code: UNKNOWN

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER Spiller: JANET − NYC PS 155 SCHOOL Spiller Phone:
Notifier Type: Local Agency Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: vszhune Contact for more spill info: JANET Contact Person Phone: (212) 689−1520

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/23/2015		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL

Caller Remarks:

Samuel Bowen janitor for school reporting oil coming through walls in the boiler room. Unknown source and no further info available via NYCDEP.

DEC Investigator Remarks:

12/23/15 − Obligado − Desk Duty − I called back the caller from DEP. She said she had no other info. I called the Site PHone liste don the PBS Registration #2−354104 212−831−5559 − not working number.

I called the NYCDOE emergency contact listed on the PBS registration, and spoke to Ken Mahadeo. Ken is the Director of Maintenance at DOE Central Office. He said he will look into it and call me right back.

According to the PBS, the site has 2 Above ground 7,500 gal tanks with #4 and #6 fuel oil.

I received a call from Tilak Ramador of DOE Fuel Division. 718−349−5779, 347−764−3949. He said he spoke to Theodore Henning at the building and he was not aware of any spill and they have not received any deliveries.

According to Theodore Henning − 914−447−3865 there is a small amount of oil and water, seeping into the boiler room. this has been going on for a long time.

12/23/15− Zhune visited the site. Met Theodore Henning (school's custodian) and Christopher Oehl (Deputy Director of Facilities). During my inspection I observed small amount of oil seeping through two walls of the boiler room. I also observed oil staining covered with spedy−dry on the floor of the tank room. As per Theodore spill happened years ago in the tank room. He also mention that the seeping oil through the walls is coming from the ground. They repair the port years ago and probably soil contaminated was left in place.

12/29/15−Tilak Ramautar from the Department of Education called to say that water is seeping throught the walls of the boiler room not oil. I told him that the Department is sending a letter requesting the following:

1. Tightness Testing of the Two 7,500−Gallon Fuel Oil Aboveground Storage Tanks and the Lines

Tilak Ramautar 44−36 Vernon Blvd Room # 300 Long Island City, NY 11101

Map Identification Number 27 **CONSTRUCTION SITE** **Spill Number: 1508795** **Close Date:**
225 EAST 126TH ST NEW YORK CITY, NY TT−Id: 520A−0313−233

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (3)
Approximate distance from property: 2448 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: ALAN FREEMAN − PRO HEALTH MEDICAL MANAGEMENT LL Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: RJFENG Contact for more spill info: NELSON ABRAMS Contact Person Phone: (212) 377−8705

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/25/2015		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	1.00	UNKNOWN	0.00	UNKNOWN	SOIL, GROUNDWATER
MOTOR OIL	PETROLEUM	1.00	UNKNOWN	0.00	UNKNOWN	SOIL, GROUNDWATER
UNKNOWN MATERIAL	OTHER	0	UNKNOWN	0	UNKNOWN	SOIL, GROUNDWATER

Caller Remarks:

3 incidents − item 1 & 2 all appr 1 qt and cleanup done − item 3 − sample to be collected on Monday and further to follow

DEC Investigator Remarks:

11/25/2015 − Feng − Duty Desk. Left Nelson Abrams (212−377−8705)a message for call back.

ACTIVE HAZARDOUS SPILLS − MISC. SPILL CAUSES − EQUIPMENT FAILURE, HUMAN ERROR, TANK OVERFILL, DELIBERATE SPILL, TRAFFIC ACCIDENT, HOUSEKEEPING, ABANDONED DRUM, VANDALISM AND STORMS − IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS.
All spills mapped and profiled within 1/8 mile. Between 1/8 mile and 1/2 mile search radius, spills reported to be greater than 100 units and spills reported in the NYSDEC Fall 1998 MTBE Survey are mapped and profiled. Spills reported to be less than 100 units are listed in a table at the end of this section.

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 28 **25 PRECINCT NYPD −DDC** **Spill Number: 9515731** **Close Date:**
120 EAST 119TH STREET HARLEM, NY TT−Id: 520A−0096−083

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 382 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	MIKE ENGLISH − NYPD 25TH PRECINCT	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	RICK MEDINA	Notifier Phone:	(718) 932−9075
Caller Name:	RICK MEDINA	Caller Agency:	MYSTIC TRANSPORTATION	Caller Phone:	(718) 932−9075
DEC Investigator:	ADZHITOM	Contact for more spill info:	MIKE ENGLISH	Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/07/1996		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	5.00	GALLONS	0.00	GALLONS	SOIL
GASOLINE	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

fuel tank in garage leaking

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY Subsurface investigation showed high levels of BTEX in groundwater.

TRANSFERRED FROM Y.KRIMGOLD.

10−12−2005 In May 2004 and January 2005, Franklin (URS) applied Permeox Plus and installed ORC socks. The latest gw data dated July 13, 2005, show that elevated concentrations of dissolved phase gw contaminants remain at the site. AZ

1−13−2006 Reviewed groundwater sampling results. According to URS elevated dissolved phase groundwater contamination remains at the site. Addtional ORC round to be performed. AZ

1−8−2007 No reports were submitted between January 2006 and October 2006. Reviewed Monitoring Report dated October 30, 2006. In June 2006, Envirotrack performed the third round of IXPER calcium peroxide injection. On June 15 and August 17, 2006, URS collected gw samples. The data showed that dissolved phase gw contamination remains at the site. Increase from 9926 ppb to 11,022 ppb in total VOC concentrations was observed in MW−07 after calcium peroxide injection. MW−7 exhibited total VOC concentration of 11,022 ppb. URS is evaluating the feasibility of excavating saturated soil and/or using chemical oxidation in the areas of MW−2, MW−02R, MW−03,MW−03R and MW−07. URS will issue a separate report recommending a future course of action. AZ

7−9−2007 Reviewed report for November 2006 through January 2007 dated March 7, 2007. The report stated that exceedances of NYSDEC Groundwater Quality Criteria were detected in each sample with total VOC ranging from 17 ppb to 7,560 ppb in MW−07. URS will inject RegenOX to expedite remediation of the remaining dissolved phase contamination. AZ

8−14−2007 Reviewed report for February 2007 through April 2007 dated May 17, 2007. Between April 17 and 20, 2007 Environtrack performed the initial RegenOx injections. On March 6 2007, gw samples were collected. The total VOC concentrations ranged from 34 ppb to 9,455 ppb. AZ

11−29−2007 Reviewed report for May 2007 through August 2007 dated September 21, 2007. Between April and July of 2007 Environtrack performed four RegenOx injections. The latest groundwater results from August 2007 showed little change from the baseline concentrations measured in March 2007. URS will continue to monitor groundwater quality and prepare bid documents for additional injections. AZ

3−6−2008 Reviewed report for September 2007 through November 2007 dated December 11, 2007. URS modified the groundwater sampling program to evaluate the effectiveness of the RegenOx injections. The latest gw results show little change from the baseline concentrations measured in March 2007. However it's believed that previously untreated pockets of sorbed petroleum contamination exist below the water table near WM−7R where strong petroleum odors were identified between 7 and 8 feet below ground surface during the recent well installation. MW−7 has total VOC concentrations of 3,469 ppb. AZ

5−1−2008 Reviewed Monitoring report for the period of December 2007 through February 2008 and dated February 29, 2008. Total VOC concentrations in MW−3 increased from 308 ppb to 520 ppb. RegenOx injections are scheduled to resume in the Spring of 2008. AZ

8−21−2008 Reviewed Monitoring report for the period of Marc 2008 through May 2008 and dated June 26, 2008. On April 29− May 1 and June 2−4, 2008 Franklin completed two rounds of PermeOX injections. The latest analytical groundwater data shows an increase in contaminant concentrations compared to the previous sampling round in January 2008. Total VOC concentrations ranged from 347 ppb in MW3R to 2,754 ppb in well MW−7R. AZ

12−29−2008 Reviewed Monitoring report for the period of June 2008 through August 2008 and dated September 22, 2008. On July 3, 2008 wells were sampled. On August 19, 2008, Franklin completed round of PermeOX injections. Total VOC concentrations ranged from 30 ppb in MW−3R to 5,454 ppb in well MW−7R. The latest analytical groundwater data shows an increase in contaminant concentrations in MW−7R compared to the previous sampling round. AZ

3−12−2009 Reviewed Monitoring report for the period of September 2008 through November 2008 and dated December 19, 2009. Envirotrack completed four rounds of RegenOx injections on April 20, May 24, June 22 and July 26, 2007 in 15 and 18 borings. Franklin completed three rounds of RegenOx injections May1, June 4 and August 21, 2008 in 18 borings. Total volatiles concentrations increased in MW−2R from 438 ppb (07/08) to 1093 ppb (09/08), MW −3R from 30 ppb(07/08) to 537 ppb (09/08), decreased in MW−7R from 5454 ppb(07/08) to 1352 ppb (09/08). AZ

1−05−2010 Reviewed Monitoring report for the period of December 2008 through February 2009 and dated April 6, 2009. Envirotrack completed four rounds of RegenOx injections on April 20, May 24, June 22 and July 26, 2007 in 15 and 18 borings. Franklin completed five rounds of RegenOx injections May 1, June 4 and August 21, October 7, 2008 and February 17, 2009 in 18 borings. Well MW−2R shows an increase in contaminant concentrations. URS belivies that the data may be skewed due to turbidity caused by RegenOx. Total VOC concentrations ranged from 169 ppb to 1139 ppb. AZ

1−14−2010 Reviewed Monitoring report for the period of March 2009 through May 2009 and dated June 12, 2009. The latest data show that that dissolved phase contamination persists.Well MW−2R has shown an increase in contaminant concentrations. URS had believed that the data may be skewed due to turbidity caused by RegenOx. Since the well did not clear up, URS will re−develop the well. AZ

2−17−2010 Reviewed Monitoring report for the period of June 2009 through august 2009 and dated September 29, 2009. The latest data show that that dissolved phase contamination persists. Well MW−2R exhibits elevated total VOC concentrations. URS had believed that the data may be skewed due to turbidity caused by RegenOx. Since the well did not clear up, URS is considering replacing this well since it goes dry after purging one gallon of water. AZ

3−18−2010 Reviewed Monitoring report for the period of September 2009 through November 2009 and dated December 8, 2009. Franlin completed five rounds of RegenOX injections. The VOC concentrations in MW−3R and MW7R increased this quarter compared to the previous quarter, however, water levels increased by approximately 1.5 feet. Contaminants sorbed in soil may dissolve into the groundwater. On November 17,2009 URS decommissioned well MW−2R and installed adjacent well MW−10. AZ

9−8−2010 Reviewed Monitoring report for the period of December 2009 through February 2010 and dated March 10, 2010. Franlin completed five rounds of RegenOX injections. In February 2010 URS collected groundwater samples. All of the wells except MW−4R exhibited VOCs at concentrations exceeding QUality Criteria. Total VOC concentrations ranged from 253 ppb to 2,837 ppb. AZ

9−27−2010 Reviewed ssytem perfromance report for March through May 2010. Groundwater contamination remains at the site. An e−mail was sent to URS/DDC/V.Brevdo: I have reviewed system status report for the above site dated July 22, 2010. The report recommended removing well MW−4R from the monitoring schedule. This well is an upgradient monitoring well for the existing plume. Therefore, this well should remain in the monitoring program. AZ

10−18−2011 Reviewed system performance report for December 2010 through February 2011. Closed−in−place tanks could be a potential on−going source of contamination. Four closed−in−place 550 gallon tanks are located in the basement near the bottom of the entrance ramp. It may not be possible to remove these tanks. URS will visit the facility to evaluate the feasibility of of

removing these tanks. Total VOC concentrations in groundwater is up to 1589 ppb. AZ

4−19−2013 Reviewed a Monitoring Report for Second and Third Quarter 2012 dated September 2012. Total VOC concentrations are to 1,175 ppb.Closed in place USTs are a potential−going source of contamination. However, the four 550−gallon USTs are located near the bottom ramp of the entrance ramp. It may not be possible to remove these tanks. AZ

6−25−2013 Reviewed report dated February 7, 2013, URS proposed a bioremediation technology. Discussed the site with K. Shenahan. Groundwater is about is 4'− 6' below the slab. URS needs to obtain as−built drawings to decide on feasibility of the tanks removal. There are no soil concentration maps included in the report. URS will submit these maps and further investigate the feasibility of the tanks' (four USTs) removal. Bioremediation (ORC Advanced) injection is planned.

The following e−mail was sent to K. Shenahan/v. Brevdo/ M. Asbagh: Dear Kevin,

I have reviewed a monitoring report dated February 7, 2013. Also, we have discussed the site over the phone. URS proposed injection of a bioremediation amendment to remediate groundwater at this site. URS needs to obtain as−built drawings to decide on the feasibility of the USTs' removal. There are no soil concentration maps included in the report. URS will submit these maps and further investigate the feasibility of the USTs' removal.

Bioremediation injection is approved. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. AZ

10−1−2013 Reviewed groundwater monitoring report and proposed remedial action plan dated June 12, 2013. The site has several tanks closed in place and a former dispenser area which could be a continuous source of contamination. The site has shallow groundwater and this could make excavation difficult. URS proposed injection of a Bioremediation amendment such as ORC Advanced or Stimulox to stimulate and promote groundwater remediation. A total of 16 injection boring locations are proposed.

10−2−2013 An email was sent to K. Shenahan/V. Brevdo/M.Asbagh:

Dear Kevin,

I have reviewed a Proposed Remedial Action Plan. The Plan calls for the injection of oxygen−releasing compounds to promote and enhance the on−going bioremediation in groundwater. This Plan is approved. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan.

Sincerely,

Alexander Zhitomirsky

09−24−2014 Reviewed groundwater monitoring report for the third and fourth quarter 2013 dated December 30, 2013. ORC Advanced injections were conducted by Clean Globe Environmental in October 2013. A total of 420 pounds of ORC Advanced were injected into 16 injection borings. AZ

09−24−2014 Reviewed groundwater monitoring report for the first and second quarters of 2014 dated June 19, 2014. A total of 420 pounds of ORC Advanced were injected into 16 injection borings. Total Voc concentrations ranged from 1,190 ppb to 2,980 ppb in

April 2014. AZ

07−10−2015 Reviewed groundwater monitoring report for the third and fourth quarters of 2014 dated December 30, 2014. According to the report a small area of the site contains dissolved phase impacts at concentrations above levels that would allow for closure of the spill number. URS implemented ORC Advanced injections in 2013. Additional ORC Advanced injections will be implemented as required to achieve spill closure. AZ

01−14−2016 Reviewed groundwater monitoring report for the first and second quarters of 2015 dated June 24, 2015. According to the report a small area of the site contains dissolved phase impacts at concentrations above levels that would allow for closure of the spill number. URS implemented ORC Advanced injections in 2013. Monitoring well MW−10 exhibited 2,271 ppb of Total VOC in April 2015. URS will implement additional ORC Advanced injections. AZ

THE FOLLOWING ACTIVE SPILLS FOR THIS CATEGORY WERE REPORTED BETWEEN 1/8 MILE AND 1/2 MILE SEARCH RADIUS FROM THE SUBJECT ADDRESS. THESE SPILLS WERE REPORTED TO BE LESS THAN 100 UNITS IN QUANTITY AND CAUSED BY: EQUIPMENT FAILURE, HUMAN ERROR, TANK OVERFILL, DELIBERATE SPILL, TRAFFIC ACCIDENT, HOUSEKEEPING, ABANDONED DRUM, VANDALISM, OR STORMS. THESE SPILLS ARE NEITHER MAPPED NOR PROFILED IN THIS REPORT.

FACILITY ID	FACILITY NAME	STREET	CITY
1310870	APT BLDG	76 E116 ST	MANHATTAN
0913803	PRIVATE RESIDENCE − HPD	152 EAST 116	MANHATTAN
9702345	ENGINE CO. 058/LADD. CO. 26 FDNY −DDC	1367 5TH AVENUE	MANHATTAN
1112103	APARTMENT BLDG	24 W 121 ST	MANHATTAN
1500042	SEWER AND BASEMENT	210 LENOX AVE	MANHATTAN
0609454	LITTLE SISITERS OF ASSUMP	310 EAST 120 TH STREET	NEW YORK
1407113	VAULTS 8910, 8993, 9037, & 9052	2 EAST 111TH ST	MANHATTAN
0909537	STEVENSON RESIDENCE	141 WEST 119TH ST	MANHATTAN

CLOSED STATUS TANK FAILURES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 29 **APARTMENT BUILDING** **Spill Number: 0310572** **Close Date: 03/05/2004**
123 E. 116TH STREET MANHATTAN, NY TT−Id: 520A−0096−086

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 838 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	JOE HAI−−MGR − BUILDING	Spiller Phone:	(516) 996−9169
Notifier Type:	Affected Persons	Notifier Name:	TENANT IN APARTMENT B	Notifier Phone:	(212) 427−0228
Caller Name:	FIREFIGHTER MULQUEEN	Caller Agency:	LPNY	Caller Phone:	(917) 923−3753
DEC Investigator:	MXTIPPLE	Contact for more spill info:	VEGA IN APT. B	Contact Person Phone:	(212) 427−0228

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/12/2003		TANK FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	30.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

caller states that the tank looks like it is leaknig. it is an above ground 1000 gallon tank in the basement that has been leaking for about a week.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 12/12/2003 Management company telephone 917−709−4887

Sangesland spoke with Vega in apt B. He said he came to visit his grandmother and the apartment building was filled with a heavy oil smell. Vega called NYFD.

Mike Mulqueen was at the site(Sangesland did NOT speak with Mike) Mulqueen reported the spill and estimated 30 gallons.

According to Vega, NYFD and City DEP were both on site and gave the management company several written orders to clean & repair the spill. Sangesland called the management company and left a message. No response yet.

Unknown who is doing the cleanup. No contact made yet with either owner or management company.

12/15/03 Tipple responded to the scene, rang all bells and was buzzed in, located boiler and tank area, found the spill, no one was to be found. It was not apparent if the spill was caused by a slow drip or asingle event. Tipple then Called Management company, Owner as per PBS registration and Tenant in apt.B , got no response. Spoke with Mulqueen, FDNY had put speedy dry and biosolve to absorb the oil and reduce the vapors. FDNY stated that a cleanup company should be in route Tipple sent letter to repair/ test/tank and clean spill.

12/15/03 Ray from Petroleum Tank Cleaners will PROBABLY do the cleanup. He will look at the site and get a signed contract.

3/5/2004 Sangesland spoke to Ray at PTC. PTC records show 4 drums & a van for 4 hours. Spill Complete

Closed

Map Identification Number 30 **2021 LEXINGTON AVENUE** **Spill Number: 9410094** **Close Date: 12/30/2003**
2021 LEXINGTON AVENUE MANHATTAN, NY TT−Id: 520A−0092−098

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1187 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	UNKNOWN−OWNER	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:		Notifier Phone:	
Caller Name:	SAL SINATRA	Caller Agency:	JETTA ASSOCIATES	Caller Phone:	(718) 828−8006
DEC Investigator:	SJMILLER	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/27/1994		TANK FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	SOIL

Caller Remarks:

TANKED LEAKED IN BASEMENT

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 11/1/94, MILLER INSPECTED SITE, OBSERVING CONCRETE ENCASED AST IN BASEMENT WITH SOME SPILLAGE FROM FITTINGS. INSTRUCTED SPILLER TO CLEAN UP AND INSTALL WEEP HOLES IN CONCRETE BASE. LARGE ABANDONED LOT FILLS BACK SIDE OF SITE. SOME UNRESOLVED DOSMESTIC ISSUES BETWEEN CALLER AND SPILLER HAVE TO BE WORKED OUT ON THEIR OWN.B

Map Identification Number 31 **42 WEST 120TH STREET** **Spill Number: 9313894** **Close Date: 12/05/1994**
42 WEST 120TH STREET MANHATTAN, NY TT−Id: 520A−0093−582

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1404 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:		Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	MR. PATRICK ANNUNZATA	Caller Agency:	DIR. EMER. SERV. BUREAU	Caller Phone:	(212) 316−8189
DEC Investigator:	O'DOWD	Contact for more spill info:		Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/22/1994	12/05/1994	TANK FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	450.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CRACKED OIL TANK? BUR. OF RENTAVATION & REPAIR WILL BID THIS OUT FOR CLEAN UP − TANK IS ABOVEGROUND, MR JOE TORRES HAS INSPECTED THE SPILL, AND DETERMINED THAT IS DUE TO OVERFILL FRON VENT PIPE.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 32 **24 WEST 121 STREET** **Spill Number: 9908095** **Close Date: 10/17/2005**
24 W 121ST STREET MANHATTAN, NY TT−Id: 520A−0092−649

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1814 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Other
Caller Name: ANTHONY LARA
DEC Investigator: JXPerezM
Spiller: AJAY PATEL, DIRECTOR − HPD
Notifier Name:
Caller Agency: PETROLEUM TANK CLEANERS
Contact for more spill info: AJAY PATEL
Spiller Phone: (212) 312−8277
Notifier Phone:
Caller Phone: (718) 624−4842
Contact Person Phone: (212) 863−7764

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/04/1999		TANK FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

Caller reports tank leak to floor approximately 15 gallons.

DEC Investigator Remarks:

Spill closed on 10/17/2005. According to the documentation submitted by the current property owner, Classic Townhouses LLC (CTL), this formerly vacant NYC owned property was transferred to CTL's ownership on June 30, 2003 and there was no oil tank on the premises. Currently CTL is in the process of renovating this property and converting it to a 2−family house with a gas boiler. Therefore, the alleged threat is not apparent. By J. Perez on 10/17/05.

Map Identification Number 33 **78−80 E 127TH ST/NYCHPD** **Spill Number: 9106395** **Close Date: 09/13/1991**
78−80 E 127TH ST NYC, NY TT−Id: 520A−0095−066

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2056 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: BILL VALLEY Caller Agency: PETRO TANK CLEANERS Caller Phone: (718) 624−4842
DEC Investigator: KSTANG Contact for more spill info: Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/13/1991	09/13/1991	TANK FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

SPILL CONTAINED IN TANK ROOM. FLOOR & TANK VACCUUMED. DRIZ−ALL APPLIED.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

/ / : WILL PICK UP & DISPOSE.

Map Identification Number 34 **105 LENOX AVE/HARLEM HOSP** **Spill Number: 9010952** **Close Date: 01/17/1991**
105 LENOX AVENUE NEW YORK CITY, NY TT−Id: 520A−0091−805

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2291 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Other
Caller Name: MARK SALAMACK
DEC Investigator: O'DOWD
Spiller: HARLEM HOSPITAL
Notifier Name:
Caller Agency: ABC TANK
Contact for more spill info:
Spiller Phone: (212) 491−8707
Notifier Phone:
Caller Phone: (718) 272−2800
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/14/1991	01/17/1991	TANK FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	SOIL

Caller Remarks:

20K TANK, ABC TANK CLEANERS CALLED TO PUMP OUT PIT,WHOLE TANK RUPTUREDIN BASEMENT,OIL IN CONTAINMENT PIT,TANK OVERFILL,TANKS−A−LOT TO CLEAN UP SPILL,ENGINEER TURNED OFF WRONG CHECK VALVE.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O,DOWD 01/17/91: TANK OVERFILL,ALL IN CONTAINMENT DIKE,NO AFFECT ON SEWERS,NYCDEP

WAS ON SCENE TO INVESTIGATE,ABC TANK TO CLEAN UP,DEC CONFIRMED

CLEAN UP & DISPOSAL OF CONTAMINATED MATERIAL.

Map Identification Number 35 **127 W 119TH ST** **Spill Number: 9111198** **Close Date: 01/31/1992**
127 W 119TH ST NYC, NY TT−Id: 520A−0091−864

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2336 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Other
Caller Name: R HOUSTON
DEC Investigator: KSTANG

Spiller:
Notifier Name:
Caller Agency: BAERENKLAU
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone: (718) 647−4200
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/29/1992	01/31/1992	TANK FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

SORBENT APPLIED. CLEANUP CONFIRMED.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

Map Identification Number 36 **275 LENOX AVE** **Spill Number: 0411801** **Close Date: 09/08/2005**
275 LENOX AVE MANHATTAN, NY TT−Id: 520A−0091−582

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2370 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	MR. WALTER EDWARDS − APARTMENT BUILDING	Spiller Phone:	(212) 864−7410 ext. 2
Notifier Type:	Other	Notifier Name:	NATSHA DANZLER	Notifier Phone:	(212) 234−5900
Caller Name:	NATSHA DANZLER	Caller Agency:	SOUTH CAROLINA HEATING	Caller Phone:	(212) 234−5900
DEC Investigator:	JMKRIMGO	Contact for more spill info:	CAROL PAYNE	Contact Person Phone:	(212) 662−4840

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/25/2004		TANK FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	10.00	GALLONS	10.00	GALLONS	SOIL, AIR

Caller Remarks:

THE TANK FELL OVER WHEN A DELIVERY WAS BEING MADE: THE LEGS WERE WEAK:

DEC Investigator Remarks:

03/23/05 transferred from T. DeMeo to J. Krimgold who was daytime duty officer when inquiring phone call came in. CS. 03/31/05. J.Krimgold spoke to Carol Payne (Pine Funeral Home) @ 212−662−4840 located 273 Lenox Ave.− affected party. She stated that about December 2004 a strong oil odor was observed in the basement. Also, oil seepage was observed coming from a wall adjacent to 275 Lenox Ave. Oil odor substantially diminished over last few months, but the oil seepage (stain) is still there.

J.Krimgold called South Carolina Heating (SCH) and spoke with Natasha Danzler @ 212−234−5900. She informed that they have been called by Funeral Home and informed about incident in about 2 weeks after it happened. No notification was made to the Department at that time. They sent a crew to check out and found that one of two 257 Gal #2 oil tanks was tipped on the side and released an unknown amount of oil to the basement's concrete floor and on the wall of the adjacent (273 Lenox Ave.) building. No paddles of oil were observed at that time. SCH was in contact with Funeral Home's insurance, but as of today they have not come to the agreement.

J.Krimgold called RP, Mr. Walter Edwards (landlord? of 275 Lenox Ave) and left a message with his assistant Ms. Santa M Johns (212−864−7410x208).

3/31/05. CSL has been sent to: Mr. W. Edwards Walter J Edwards Enterprises Inc 275 Lenox Avenue New York, NY 10027−5541 YK.

5/2/05. Talked to Mr. Edwards. He claimed that his office lost CSL letter and his consultant Ethan Elton, Inc. also lost a fax copy of this letter. Nothing has been done since. Mr. Edwards was out from country and just came back. He will come and pick up a copy of CSL tomorrow. YK.

5/2/05. Mr. Poul Franky called and asked for a copy of CSL. He is with ICS Claims, an adjuster for West Port Insurance (claim # 185540 filed by Pine Funeral Home). They can cover a part of the cleanup expenses. His phone # 914−907−5788, fax 845−778−0658. YK.

5/27/05. Aimee Petkus from Ethan C. Eldon Associates, Inc. called to discuss her letter to the Department dated May 25, 2005. Generally, the letter states that 40 gal of #2 oil was spilled and 40 gal was recovered. It is unclear then how adjacent property got oil in their basement if all oil was removed. Phone conversation revealed that the consultant was not aware about oil spillage at adjacent (273 Lenox Ave) property. Agreed that they will take soil samples from under tanks in the tank room and from the basement at 273 Lenox. If results warrant a soil excavation will be performed at both sites. YK.

6/1/05. J.Krimgold reviewed a work plan submitted by the Ethan C. Eldon Associates, Inc. dated May 27, 2005. At least 4 soil borings to be advanced in the tank room and at 273 Lenox. The work should begin on June 8, 2005.

9/8/05. J.Krimgold reviewed the Phase II Environmental investigation report prepared by Ethan C. Eldon Assoc, Inc. and submitted on June 22, 2005. Afer initial cleanup four soil borings were advanced in the spill area. The lab results show no contaminants level above TAGM in all borings. NFA letter.

Map Identification Number 37 **COMMERCIAL BUILDING** **Spill Number: 0409042** **Close Date: 11/18/2005**
310 LENOX AVE NEW YORK, NY TT−Id: 520A−0093−359

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2559 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	PHIL RUTHERFORD − APARTMENT BUILDING	Spiller Phone:	(212) 685−9680
Notifier Type:	Other	Notifier Name:	NICK EAGLE	Notifier Phone:	(845) 348−6355
Caller Name:	NICK EAGLE	Caller Agency:	RND SERVICES	Caller Phone:	(845) 348−6355
DEC Investigator:	SFRAHMAN	Contact for more spill info:	PHIL RUTHERFORD	Contact Person Phone:	(212) 685−9680

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/09/2004		TANK FAILURE	NO	NO

NO MATERIAL INFORMATION GIVEN FOR THIS SPILL

Caller Remarks:

CONTAINED IN VAULT TANKS HAVE BEEN PUMPED OUT TANK SIZE ABOUT 15OO GALLONS:

DEC Investigator Remarks:

4/20/2005 Spill case transferred from DeMeo to Rahman: Sangesland spoke to project manager working for building owner. He said the problem tank was cleaned, cut up and removed from the vault. Vault was located under the sidewalk in front of the building. Vault was cleaned and there were no cracks in the floor, therefore no oil leaked out of the vault area.

Sangesland asked the project manager to send into the DEC: 1) Letter stating that the tank was removed 2) Statement that the vault area was totally cleaned and no cracks found. 3) Detailed photos of the vault floor showing it is clean and has no cracks. 4) Request closure of open spill number. 06/14/05−SR// Received photographs, invoice and left a message for them. 10.21.05 Sharif− Reviewed the waste disposal manifest and photographs after the tank has been removed. Aparently, there is no cracks or leak on the floor. But the tank room wall looks wet with black stain at different places. Spoke with Phil Rutherford, 212−685−9680 who said they took pictures after it was power washed again since my last conversation with him. He would send me the all new photographs and check with the company whether they filed any deregistration application with DEC. 11.18.05 Sharif// Recev'd new photograph that looks pretty much clean. NFA required.

Map Identification Number 38 **SPILL NUMBER 9911165** **Spill Number: 9911165** **Close Date: 12/27/1999**

75 W. 126TH ST MANHATTAN, NY TT−Id: 520A−0093−364

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2608 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	LORRAINE HORSFORD	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:	FIRE DISPT	Notifier Phone:	
Caller Name:	FF HACK	Caller Agency:	FDNY	Caller Phone:	(917) 769−0483
DEC Investigator:	JMROMMEL	Contact for more spill info:	LORRAINE HORSFORD	Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/21/1999		TANK FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

IN BASEMENT SOME DID GET INTO DRAIN − SOME IS BEING BEING PUMPED OUT − RED CROSS IS BEING NOTIFIED 13 PEOPLE LIVE IN BUILDING NO LANDLORD LISTED

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL REFER TO 9911163.

CLOSED STATUS TANK TEST FAILURES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 39 **PELHAM FRITZ RECREATION C** **Spill Number: 0602813** **Close Date: 02/25/2015**
18 MOUNT MORRIS PARK WEST MANHATTAN, NY TT−Id: 520A−0099−406

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 1232 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: 18 W MOUNT MORRIS PARK
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: MR. WELLINGTON GREEN − PELHAM FRITZ RECREATIO Spiller Phone: (212) 410−8969
Notifier Type: Tank Tester Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: VXBREVDO Contact for more spill info: MR. WELLINGTON GREEN Contact Person Phone: (212) 410−8969

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/13/2006		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	5000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

IT MAY BE THE DIRECT FILL SITCK LINE.

DEC Investigator Remarks:

6/13/06 − Raphael Ketani. I talked to Thomas Leddy of Protest (631) 321−4670. He said that they did a normal plug off test. He said it is a UST for heating oil for their buildings in the park. The contact person is:

Wellington Green or Gabe Ramos (boss) NYC Parks Department Randalls Island, NY, 10035

(212) 410−8969

06/19/06−Hiralkumar Patel. Spoke to Tom. he is not sure but that was dry leak probably. haven't heard from parks department yet. PBS #: 2−604978

TTF sent out to Gabe Ramos at:

Gabe Ramos City of NY Parks & Recreation 5 Boro Operations Randalls Island, NY 10035

Ph. (212) 410−8916 FAX (212) 410−8319

letter faxed to Mr. Ramos.

05/24/12−Hiralkumar Patel. 2:02 PM:− sent email to Mr. Ramos inquiring updates.

10/06/14−Hiralkumar Patel. as per DEC Austin, case assigned to DEC Vadim.

02/25/2015 − V. Brevdo e−mail from Aecom (Former URS):

Hello Vadim,

I have been meeting with representatives of the New York City Department of Parks and Recreation to determine the status of the seven spills assigned to URS on November 3rd (see attached pdf file). According to Mr. Gabe Ramos of the Parks Department, it appears that the following spills were assigned as a result of failed tank tightness testing at the Pelham Fritz Recreation Building located in Marcus Garvey Park:

Spill No. 0515023 ˇ Currently assigned to Mr. Alex Zhitomirsky Spill No. 0602813 ˇ Currently assigned to Mr. Vadim Brevdo

There was a 5,000−gallon heating oil tank at the site that was replaced by LiRo in 2009. URS believes that both of these older spills should be closed based on data collected during the tank replacement project as documented in LiRo´s closure report.

Our case for spill closure is contained in a report we are ready to send to the NYSDEC. However, we would like direction from you regarding who to send the report to. It may make sense to have one NYSDEC PM managing both of these spill numbers since it appears they are related to the same UST that was replaced in 2009.

Once we have direction from you, we will issue the report for your review.

Thanks,

Kevin J. Shanahan Project Manager Direct: 716−923−1215 Cell: 716−480−7352 Note New Email: kevin.shanahan@aecom.com VB

02/25/2015 − V. Brevdo Three spill numbers 0515023, 0602813, and 0813485 (closed) are related to the same tank that was replaced in 2009. Based on the e−mail explanations from Aecom (Former URS) and the review of the closed spill case 0813485, this spill case (0602813) is closed via administrative consolidation with the spill case no. 0515023.

DEC will direct Aecom to submit report to the project manager for spill case no. 0515023 (Alex Zhitomirsky) for evaluation of the merits to close case 0515023 as well, and advise Aecom/URS of the closure of the spill case 0602813 via administrative consolidation with the spill case 0515023. VB

Map Identification Number 40 **JACOB'S RESIDENCE** **Spill Number: 0203815** **Close Date: 10/21/2005**
203 EAST 117TH ST MANHATTAN, NY TT−Id: 520A−0096−102

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1312 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING Spiller: OWNER − JACOB'S RES Spiller Phone: (212) 937−7826
Notifier Type: Responsible Party Notifier Name: Notifier Phone:
Caller Name: PHIL FAZIN Caller Agency: CROWN LEAK DETECTION Caller Phone: (516) 939−2959
DEC Investigator: JBTAMBE Contact for more spill info: CALLER Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/11/2002		TANK TEST FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	2500	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD notes:

7/12/2002: sent letter to Jacob Cohen requesting to repair or close the tank. AR

7/19/2002:He called me to clarify the letter i sent him. I told him to repair the tank or send me a letter stating what his plan of action was to repair the tank. he said he would fax it today.AR

8/28/2002: CALLED AND LEFT A MESSAGE TO JACOB TO CALL ME BACK. HE NEVER DID. AR

9/2/2002: CALLED AGAIN. JACOB FAXED THE REQUIRED INFORMATION ON 9/3/2002. ON 9/4/2002 CALLED AGAIN TO ASK IF THE EXCAVATION WAS ON CONCRETE. JACOB COHEN TOLD ME IT WAS. THEY DUG 15 FEET APPROXIMATELY. GAVE ME THE NAME OF COMPANY DOING REPAIR WORK: PETROLEUM TANK CLEANERS (7186246934).

11/18/2002: tHE FACILITY IS UNDER A CONSENT ORDER FOR NOT TESTING THE TANK. THE TANK WAS LAST TESTED IN 1987. THE ORDER IS ON FILE. THE TANK WAS LAST TESTED ON 11/15/2002. THE TANK PASSED BUT THE REPORT IS NEEDED TO CLOSE THE SPILL.

01/26/04

TRANSFERRED FROM ROMMEL TO AUSTIN 02/17/04: Reassigned from AUSTIN to KRIMGOLD.

10/21/05. J.Krimgold reviewed documentation submitted by Mr. Jacob Cohen. Based on this, the tank failed the test due to an uncapped tell−tail pipe. Pipe was ecxavated. No contamination was found. NFA letter.

Map Identification Number 41 **STORE FRONT** **Spill Number: 0508613** **Close Date: 08/03/2006**
124 EAST 124TH ST. NEW YORK, NY TT−Id: 520A−0091−646

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1321 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CHRIS GORGA − STORE FRONT	Spiller Phone:	(646) 772−1404
Notifier Type:	Tank Tester	Notifier Name:	CHRIS GORGA	Notifier Phone:	(646) 772−1404
Caller Name:	CHRIS GORGA	Caller Agency:	PETROLEUM TANK CLEANERS	Caller Phone:	(646) 772−1404
DEC Investigator:	rvketani	Contact for more spill info:	CHRIS GORGA	Contact Person Phone:	(646) 772−1404

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/18/2005		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
	15000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

Systems test failure. No product released.

DEC Investigator Remarks:

need to send ttf letter to

Property Manager: Mr. Joe Berko (212−687−0777) Berko & Associates 501 Fifth Ave − Suite 1408 New York, NY 10017

Nov. 7, 2005 A Tank Test Failure Letter was sent to:

Joe Berko Berko & Assoc. 501 Fifth Ave− Suite 1408 New York, NY 10017

11/16/05−Vought−Spoke with Maya Betesh (212−687−0777) and she will be faxing in repair invoices.

05/17/06−Vought−Spill transferred from DEC Vought to DEC Ketani as per DEC Austin.

6/14/06 − Raphael Ketani. I called up Berko & Associates and asked to speak to the case manager for the property. I spoke to Joseph Berko. He said that all of the documentation showing that the tank was abandoned in place and that everything was taken care of was sent some time ago. I told him I don't have anything to look at. He said he will send it again.

6/15/06 − Raphael Ketani. Mr. Berko called me back. He stated that the tank was abandoned in place. I looked up the PBS case #2−610163 and it showed the tank abandoned in place. I told Mr. Berko that I needed the failed tank test results, why the tank failed, and a letter report from Brookside Environmental, the company that abandoned the tank, stating that there were no impacts to drains or the environment. He said he would get these documents for me.

7/20/06 − Raphael Ketani. I left a message for Mr. Berko asking what was presently taking place at the site.

8/2/06 − Raphael Ketani. I spoke to Mr. Berko. He said he was just the mortgage broker at the time. He said that he has the information and will get me the documentation that I need.

8/4/06 − Raphael Ketani. I received the dry fail tank and system test results and the cover letter from Eastside Floors stating there was no environmental impact or impact to the sewer system or drainage system. Also the cover letter stated that no oil was spilled as it was a dry leak, that the tank was abandoned in place, and that they have converted to electric heat.

Based upon the above listed documentation, I am closing the spill case.

Map Identification Number 42 **CLOSED−LACKOF RECENT INFO** **Spill Number: 8805777** **Close Date: 03/05/2003**
158 E 115TH ST NEW YORK, NY TT−Id: 520A−0100−055

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1367 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER Spiller: INSPCTR FEUERMAN − EAST HARLEM CNTR/NYC DOH Spiller Phone: (212) 566−3268
Notifier Type: Tank Tester Notifier Name: Notifier Phone:
Caller Name: JOHN LEDDY Caller Agency: PRO−TEST Caller Phone: (516) 321−4670
DEC Investigator: ADMIN. CLOSED Contact for more spill info: Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/06/1988		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

3K TK SYSTEM FAILED HORNER EZY CHEK. GROSS LEAK IN PIPING, REMOTE

FILL, OR VENT LINE.CLOSED DUE TO LACK OF ANY RECENT INFO− DOES NOT MEET ANY CLEAN UP REQUIREMENTS.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/05/2003− Closed Due To The Nature / Extent Of The Spill Report

Map Identification Number 43 **DUNLEVY MILBANK CHILDREN** **Spill Number: 0209842** **Close Date: 06/16/2004**
14−32 WEST 118TH STREET NEW YORK CITY, NY 10026 TT−Id: 520A−0093−576

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1398 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	GARY − DUN LEVY MILBANK CHILDREN	Spiller Phone:	(212) 254−3074
Notifier Type:	Tank Tester	Notifier Name:	SAME	Notifier Phone:	
Caller Name:	DAVE FAZIN	Caller Agency:	CROWN LEAK DETECTION	Caller Phone:	(516) 939−2959
DEC Investigator:	CESAWYER	Contact for more spill info:	DAVE FAZIN	Contact Person Phone:	(516) 939−2959

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/27/2002		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001	10000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

TANK FAILED THE TEST.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 12/30/2002−Vought−Dave Fazin called and not at work.
Called Gary Dawyot at site and left message to call duty desk and that letter was in mail. Tightness test letter sent 12/30/2002.

1/7/04−Vought−Spill transferred from Vought to Austin.

1/27/04 − Sawyer − Spill transferred from Austin to Sawyer.

6/16/04 − Swayer − Tank and system was isolated and repaired no impact to surrounding soil. Gary Dwyot forwarded information.
Closed.

Map Identification Number 44 **UNKNOWN** **Spill Number: 0008608** **Close Date: 06/11/2007**
222 EAST 119TH ST MANHATTAN, NY TT−Id: 520A−0096−094

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1505 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	OWNER − 222 EAST 119TH ST	Spiller Phone:	(518) 622−0663
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	RENE LEWIS	Caller Agency:	AL EASTMAN & SON	Caller Phone:	(718) 378−7000
DEC Investigator:	JMKRIMGO	Contact for more spill info:	CALLER	Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/24/2000		TANK TEST FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	5000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

tank failed test.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND

1/19/2006 − Haggerty − spoke with Rene Lewis of Al Eastmond, he will send info (718−378−3000), Rene never returns calls. Spoke with Arthur Schwartz (718−246−7944) from Acorn Realty, he will have someone return my call. Spoke with property manager who has no knowledge of anything regarding the spill (tank test failure), Acorn acquired property 1 year ago.

06/11/07. J.Krimgold reviewed a report submitted by A.L. Eastmond. Tank was removed and soil samples taken. No soil contamination or other evidence of release has been found. NFA.

Map Identification Number 45 **MORRIS PARK SENIOR** **Spill Number: 9004771** **Close Date: 09/20/1996**
17 EAST 124TH STREET NEW YORK CITY, NY TT−Id: 520A−0091−764

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1518 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	JOHN COLLINS − NYCHA	Spiller Phone:	(212) 306−3142
Notifier Type:	Tank Tester	Notifier Name:		Notifier Phone:	
Caller Name:	ROBERT GANDOLFO	Caller Agency:	TANK TEST INC	Caller Phone:	(718) 789−3770
DEC Investigator:	SIGONA	Contact for more spill info:	JOHN COLLINS	Contact Person Phone:	(212) 306−3129

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
07/30/1990		TANK TEST FAILURE	2−475165	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001	5000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

TANK FAILED HORNER EZY CHECK WITH A VISUAL GROSS LEAK, WILL EXCAVATE, ISOLATE & RETEST.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

RECEIVED COPY OF TANK TEST REPORT. THE REPORT INDICATES THAT THE TANK TEST FAILED BECAUSE THE TANK WAS MISSING BOLTS ON MANWAY. SUBSEQUENT TANK TEST IN 1/92 PASSED TIGHTNESS TEST.

Map Identification Number 46 **RESIDENCE** **Spill Number: 0000067** **Close Date: 03/17/2008**
212 EAST 122ND STREET NEW YORK, NY 10035 TT−Id: 520A−0091−094

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1537 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Tank Tester
Caller Name: JOHN LEDDY
DEC Investigator: JMKRIMGO
Spiller: WAYNE STOCK
Notifier Name: LEWIS VALSQUEZ
Caller Agency: PROTEST ENTERPRISES
Contact for more spill info: CALLER
Spiller Phone: (917) 806−7855
Notifier Phone:
Caller Phone: (631) 321−4670
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/03/2000		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	3000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

tank test failure from an u/g tank no leak to the environment no callback necessary

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE Original ttf letter sent April 3,2000

4/10/03 letter requiring report documenting work done associated with 2000 ttf describing proper removal/abandonment/ soil testing. both letters in file.

9/1/04 property sold//made contact with purchasers attorney//sending request for documentation to Telluride Realty and attorney's office.

6/15/05: Reassigned to Benjamin 10/28/05− Letter sent Telluride realty (owner)requesting information. No response. Followup needed with owner. 3/06 − File to be sent to Region 2 for followup 02/6/08. TTF letter has been sent to July Daoy LCS P.O.Box 406, Buffalo, NY 14205 −JK−

3/17/08. J.Krimgold reviewed a letter dated 02/14/08 submitted by Associated Environmental Services, Ltd. According to the letter the most probable cause of the t/t failure was a gasket at the man−way, which was subsequently replaced. Tank was retested and passed. NFA.

Map Identification Number 47 **TAINO TOWER** **Spill Number: 0514031** **Close Date: 12/19/2006**
2253 3RD AVE NEW YORK, NY TT−Id: 520A−0096−110

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1543 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Tank Tester
Caller Name: JIM MELNICK
DEC Investigator: HRPATEL

Spiller: MANNY DIAS − TAINO TOWER
Notifier Name: JIM MELNICK
Caller Agency: PROTEST
Contact for more spill info: MANNY DIAS

Spiller Phone: (212) 369−3755
Notifier Phone: (631) 321−4670
Caller Phone: (631) 321−4670
Contact Person Phone: (212) 369−3755

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/08/2006		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	20000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

while doing product came out of another tank; clean up crew enroute

DEC Investigator Remarks:

03/08/06 Feroze, PBS case of this spill is # 2−240680. TTF is sent to:

Robert Algarin 2253 Third Ave New york, NY 10035

03/15/06. Spill is transferred from Feroze to Kumer Patel.

03/21/06−Hiralkumar Patel. Spoke with John Laddy at Protest. this site has three 20,000 gal USTs on location and they were transferring oil from one tank to another. during this transfer, tank overfilled and spill happened on concrete side walk and asphalt street (possible from vent pipe). Protest has cleaned the site. John doesn't know about concrete condition but nothing went down to sewer/drain. DEP has visited site already.

03/23/06−Hiralkumar Patel. Spoke with John at Protest. John will go on site to replace faulty valve on tank. he will call me with updates.

03/24/06−Hiralkumar Patel. called for Manny Dias (212−369−3755 Ext 11), but he will be in office on Monday Mar 27 2006.

03/28/06−Hiralkumar Patel. Spoke with Mr. Dias. as per him, oil came out from vent pipe and spilled on concrete side walk and then ran on asphlt street. there are no cracks in concrete on sidewalk. no soil/sewer/drain affected. the tank had faulty pressure gauge on it. tank is currently empty and out of service. they are working on replacing this faulty gauge. all cleaned

up. no complaints.

Spoke with Mr. Melnick at Protest and asked him to send me copy of invoice once he done changing faulty gauge. He told me that they are going to replace it soon once they find out problem with gauge.

04/21/06−Hiralkumar Patel. Spoke with Mr. Melnick. they got permission to do repair work, but they haven't got chance to do it. they will probably go in next week. he will call once he done with repair work.

05/05/06−Hiralkumar Patel. Spoke to Mr. Melnick at Protest. they will start work probably on May 15.

06/22/06−Hiralkumar Patel. visited site on 06/20/2006. spoke to William, super of building & to Maria Cruz, executive director. tank was still empty on time of visit. no work done yet. spoke with Mr. Dias and asked to call back with updates.

Maria Cruz Executive Director ARCO 2253 3rd Ave, 5th Floor New York, NY 10035 PH. (212) 369−3755 Fax (212) 369−6215 Email: taino@acromgt.com

mcruz@arcomgt.com

spoke with John at Protest. he explained that oil spill happened due to overfill of tank. they have tested all three tanks and tank system passed test. asked John to fax me test results. John suggest Mr. Dias to repair/replace valve to prevent further spill.

spoke with Mr. Dias. he explained that due to air pressure inside syphon , oil in one tank reached to top and overfilled. and piece of syphon was leaking and that why it created air pressure. Mr. Dias was planning to change that defected piece of pipe in September as winter season starts. asked him to submit work invoice once he done with such repair work. spoke with John at protest again. he explained that this site doesn't have syphon. instead these tanks are connected through valves in supply/return lines. so if they need, they can open/close valve to transfer oil from one tank to another. when John did test, he did test by isolating each tank system from another two.

06/26/06−Hiralkumar Patel. Left message for Mr. Dias. 06/29/06−Hiralkumar Patel. Spoke to John and asked to send tank test results for all three tanks. 07/05/06−Hiralkumar Patel. Spoke to John at Protest. he has misplaced tank test results, once he gets it, he will forward it to the Department. Left message for Mr. Dias. 07/10/06−Hiralkumar Patel. spoke with Mr. Dias and asked him to send tank test results for all tanks.

11/14/06−Hiralkumar Patel. left message for Mr. Dias. 12/01/06−Hiralkumar Patel. left message for Mr. Dias. 12/19/06−Hiralkumar Patel. spoke with Bob at Protest. he will check for tank test result and will fax if he finds it. spoke with Mr. Dias. they have repaired leaking valve. received tank test result from Bob from Protest. all three tanks were passed test.

spoke with DEC Jacob about PBS registration. PBS registration expired on 10/23/1997. i gave tank test results to DEC Brian to update PBS record. sent email to Jacob with site address, manager's name and address.

based on available tank test result and other informations, case closed.

12/22/06−Hiralkumar Patel. received work invoice copy, about repair of leaking valve, from Mr. Dias.

Map Identification Number 48 **TAINO TOWERS − TTF** **Spill Number: 0000963** **Close Date: 04/13/2015**
2253 3RD AVE NEW YORK, NY 10035 TT−Id: 520A−0096−109

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1543 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Tank Tester
Caller Name: JOHN LEDDY
DEC Investigator: HRPATEL
Spiller: M DIAZ − ARCO MANAGMENT
Notifier Name: A LOPEZ
Caller Agency: PROTEST ENTERPRISES
Contact for more spill info: M DIAZ
Spiller Phone: (212) 369−3755
Notifier Phone:
Caller Phone: (631) 321−4670
Contact Person Phone: (212) 369−3755

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/22/2000		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
3	20000	Horner EZ Check I or II	0.00	FAIL

Caller Remarks:

TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY MANAGER ADVISED OF THE TEST RESULTS. TANK TO BE ISOLATED AND RETESTED. NO CALL BACK BEING REQUESTED.

DEC Investigator Remarks:

spill assigned to James Drumm for SCI

9/26/05 phone conversation with owner’s rep Manny Diaz. Manny Diaz says the report was previously sent to region 2. He will re−send the report of the repairs and re−test. Still haven’t received report.

02/20/09−Hiralkumar Patel. issued notice of violation for following reasons, as part of spill # 0810730:

− failure to renew registration (registration expired on 10/23/1997) − failure to color code fill ports − failure to test tank/piping (no tank test record available from 11/01/1997 to 03/15/2006) − failure to monitor unmetered tank for leaks − failure to notify of petroleum discharge (spill # 0810730 was reported by FDNY, but not by management) − failure to contain and/or remove petroleum discharge (no reports available)

08/13/12 − LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo

10/10/14−Hiralkumar Patel. reviewed available information for DEC DeMeo. alternate addresses: 200−244 E 123rd St, 2383−2395 2nd Ave, 201−223 E 122nd St, 231−265 E 122nd St, 2243−2261 3rd Ave

PBS #: 2−240680. as per PBS record, site has three (3) 20,000 gal #2 oil USTs, in−service, installed in Jan. 1972. PBS registration expired on 10/23/2012.

other spills #: 8905085, 0000962, 0514031, 0810730, 0814485

spill # 8905085 was reported on 08/22/1989 due to 30 gal #2 oil spill. case closed. spill # 0000962 was reported on 04/24/2000 due to tank test failure of 20,000 gal #2 oil tank (tank #2). the subject spill was reported on 04/24/2000 due to tank test failure of 20,000 gal #2 oil tank (tank #3). spill # 0514031 was reported on 03/08/2006 due to #2 oil spill during transfer between two tanks. case closed. spill # 0810730 was reported on 12/26/2008 due to 1,000 gal #2 oil spill in boiler room as boiler exploded. case closed. spill #: 0814485 was reported on 12/31/2008 due to findings of 4 gal of an unknown petroleum in ConEd vaults. case closed.

Taino Towers c/o Arco Management 2253 3rd Avenue, 5th Floor New York, NY 10035 Attn.: Maria Cruz PH. (212) 369−3755 email: mcruz@multifamilymgt.com

a notice of violation was issued (PBS expired, non−reported spill etc.) and a consent order was signed in 2009, as part of spill # 0810730.

2/12/15 TJD Spill reassigned from DeMeo to Patel

04/13/15−Hiralkumar Patel. in accordance with R2 TTF closure protocol, this spill is being closed due to no indication of a current release (all three tank systems were tested tight on 03/15/2006, 01/02/2009 and 01/30/2015), no information indicating that there may have been a historical release, and no information that this tank test failure will be an issue in the future. case has been referred to PBS unit due to expired PBS registration.

Map Identification Number 49 **TAINO TOWERS** **Spill Number: 0000962** **Close Date: 11/17/2003**
2253 3RD AVE NEW YORK, NY TT−Id: 520A−0096−108

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1543 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: NON−MAJOR FACILITY (>1100 GAL) Spiller: M DIAZ − ARCO MANAGMENT Spiller Phone: (212) 369−3755
Notifier Type: Tank Tester Notifier Name: A LOPEZ Notifier Phone:
Caller Name: JOHN LEDDY Caller Agency: PROTEST ENTERPRISES Caller Phone: (631) 321−4670
DEC Investigator: SIGONA Contact for more spill info: M DIAZ Contact Person Phone: (212) 369−3755

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/21/2000		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
2	20000	Horner EZ Check I or II	0.00	FAIL

Caller Remarks:

TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY MANAGER ADVISED OF THE TEST RESULTS. TANK TO BE ISOLATED AND RETESTED. NO CALL BACK BEING REQUESTED.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 50 **X** **Spill Number: 0403282** **Close Date: 01/09/2006**
1944 MADISON AVE MANHATTAN, NY TT−Id: 520A−0091−531

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1565 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	MARK SMEAR		Spiller Phone: (212) 967−2200
Notifier Type:	Other	Notifier Name:	KRISTEN CIABURRI		Notifier Phone: (718) 981−5710
Caller Name:	KRISTEN CIABURRI	Caller Agency:	USA ENVIRONMENTAL		Caller Phone: (718) 981−5710
DEC Investigator:	rmpiper	Contact for more spill info:	MARK SMEAR		Contact Person Phone: (212) 967−2200

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/25/2004		TANK TEST FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	2500	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

tank test failed.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 12/9/05− DEC Piper spoke w/ USA Environmental. According to USA E, they had sent a proposal to the current owner though it was not accepted. Mailed ttf Letter to current managment agent. Ben Nehmadi Republic Investment Corp.630 1st Ave, NY, NY 10016. PBS Reg. expired 5/7/92. 12/30/05− DEC Piper received letter form managing agent regarding site. Letter states that old tank was removed and new tank installed. However, PBS was not notified.

1/3/06− DEC Piper− had contacted American Pipe and Tank Lining Co− Steven Silver, 212.736.6618. to obtain info. Left message

requesting call back. 1/6/06− DEC Piper spoke w/ Steven Silver of American Pipe. As per conversation, no contamiantion exists. Mr. Silver had offered his services to register the old and new tank., though owners declined. 1/9/05− Violations Exist. Spill closed and referred to Legal.

Map Identification Number 51 **TAFT HOUSES −NYCHA** **Spill Number: 9402166** **Close Date: 10/09/2008**
1740 MADISON AVENUE NEW YORK, NY TT−Id: 520A−0095−995

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1605 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NYC HOUSING AUTHORITY	Spiller Phone:	(212) 306−3142
Notifier Type:	DEC	Notifier Name:		Notifier Phone:	
Caller Name:	JANE HEALY	Caller Agency:	NYSDEC	Caller Phone:	(718) 482−4933
DEC Investigator:	jkkann	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/26/1993		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
002		Unknown	0.00	UNKNOWN

Caller Remarks:

INITIALLY REPORTED AS PASSED.

DEC Investigator Remarks:

01/05/06: This spill transferred from J.Kolleeny to S.Kraszewski. No site investigation ever performed for either tank. No tank

closure report for replacement of tank 001 or closure of tank 002. Need tank closure report. − SK

03/22/06: This spill transferred to K.Tang − SK

10/9/08: Jkann − spill transferred to J.Kann and closed to consolidate with 9315466.

Map Identification Number 52 **1824 PARK AVE/SUNOCO** **Spill Number: 9108459** **Close Date: 10/13/2006**
1824 PARK AVE MANHATTAN, NY TT−Id: 520A−0091−855

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1778 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	GASOLINE STATION OR PBS FACILITY	Spiller:	SUNOCO A	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	GUY CAPPONE	Caller Agency:	GAS INSTALLATIONS	Caller Phone:	(718) 647−7443
DEC Investigator:	SKCARLSO	Contact for more spill info:		Contact Person Phone:	

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/07/1991		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

SIX 550'S LINKED. −.661 PETROTITE. E I & R

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 04/12/04

TRANSFERRED FROM SULLIVAN TO SUN

1/6/06: Case reassigned to Andersen. Sent assessment required letter to Gary Spindler (listed on the PBS data sheet). Due back 3/2/06.

3/13/06: Resent assessment required letter.

7/25/06: Spoke to Gary Spindler (212−929−9404). He said that he is not the current owner, and was not the owner in 1991 at the time of the spill. The 550 gallon tanks were removed from the property prior to sale of the property, but he does not have documentation of this. He said he would call back with contact information for the new owner.

8/9/06: New owner address from PropertyShark.com: Notice Address: Verizon Mortgage Group, Inc. 1824 Park Avenue New York, NY 10035

Billing Address: City and Suburban Federal Savings Eab Plz E Tower 11Fl Uniondale, NY 11556

New owner information from Acris: Verizon Mortgage Group, Inc. 3333 Hyde Park Road, Suite 314 New Hyde Park, NY 11042

8/10/06: Sent John Quatrale of Verizon New York an email to see if Verizon New York is affiliated with Verizon Mortgage Group.

9/8/06: Sent letter requiring an assessment to Verizon Mortgage Group, 3333 Hyde Park Road and 1824 Park Avenue addresses. Assessment due back 11/10/06,

9/12/06: Letter addressed to 1824 Park Avenue returned to sender.

9/13/06: Received phone call from Steve Baranilo (516−775−5084).

9/14/06: Spoke to Steve Baranilo. He is a consultant for Verizon Mortgage. 18 tanks were removed from the site and supervised by a PE, report submitted to the city at the time. A closure report will be submitted to the Department.

9/18/06: Spoke to Ted Yen of Don Carlo Environmental Services. He is submitting a proposal to the owner to investigate the spill. fax: 718−857−2100.

10/13/06− DEC Piper received tank closure report. Piper delivered to DEC Andersen

10/13/06 − Andersen − Reviewed tank closure report submitted by Don Carlo Environmental Services, dated 10/12/06. Tanks removed on July 9, 2001. 12 550−gallon gasoline tanks (5 endpoint samples), 1 4,000−gallon gasoline tank (5 endpoint samples), 1 550−gallon fuel oil tank (1 endpoint sample) removed. Tanks were in good condition, showed no evidence of corrosion or pitting. All endpoint samples were ND. NFA letter issued.

Map Identification Number 53 **JOHNSON HOUSES −NYCHA** **Spill Number: 9504621** **Close Date: 10/25/2005**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−085

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: NYC HOUSING AUTHORITY
Spiller Phone: (212) 306−3142
Notifier Type: Tank Tester
Notifier Name:
Notifier Phone:
Caller Name: PAUL GOLDSTEIN
Caller Agency: NYC HOUSING AUTHORITY
Caller Phone: (212) 306−3233
DEC Investigator: SWKRASZE
Contact for more spill info:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/17/1995		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

TANK #001 − COULD NOT MAINTAIN NEGATIVE PRESSURE.

DEC Investigator Remarks:

10/25/05: This spill closed to consolidate with open spill #0306729. S.Kraszewski

Map Identification Number 54 **JOHNSON HOUSES −NYCHA** **Spill Number: 9402165** **Close Date: 07/17/1995**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−088

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: NYC HOUSING AUTHORITY
Spiller Phone: (212) 306−3142
Notifier Type: DEC
Notifier Name:
Notifier Phone:
Caller Name: JANE HEALY
Caller Agency: NYSDEC
Caller Phone: (718) 482−4933
DEC Investigator: HEALY
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
03/24/1993	07/17/1995	TANK TEST FAILURE	2−474967	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

INITIALLY REPORTED AS PASSED. CLOSED OUT−SEE SPILL #9504621 (SUBSEQUENT TANK TEST FAILURE)

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 55 **JOHNSON HOUSES −NYCHA** **Spill Number: 9315373** **Close Date: 12/23/2005**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−087

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: NYCHA − JOE MONTELLA
Spiller Phone: (212) 306−3142
Notifier Type: DEC
Notifier Name:
Notifier Phone:
Caller Name: JANE HEALY
Caller Agency: NYS DEC
Caller Phone: (718) 482−4933
DEC Investigator: SWKRASZE
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/27/1991		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
002		Unknown	0.00	UNKNOWN

Caller Remarks:

LEAK RATE OF −0.1 GPH REPORTED AS PASSED BY TESTER −

DEC Investigator Remarks:

12/23/05: This spill transferred from J.Kolleeny to S.Kraszewski.

This spill closed to consolidate with opne spill #0306729. − SK

Map Identification Number 56 **JOHNSON HOUSES −NYCHA** **Spill Number: 9100385** **Close Date: 04/20/1995**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−086

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: NYCHA
Spiller Phone: (212) 306−3142
Notifier Type: Tank Tester
Notifier Name:
Notifier Phone:
Caller Name: ROBERT GANDOLFO
Caller Agency: TANK TESTING INC
Caller Phone: (718) 789−3770
DEC Investigator: HEALY
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
04/09/1991	04/20/1995	TANK TEST FAILURE	2−474967	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

40K TANK,SYSTEM TEST,FAILED HORNER EZY CHECK WITH A GROSS LEAK,WILL EXCAVATE,ISOLATE & RETEST. SEE SPILL # 9402165

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 57 **JOHNSON HOUSES −NYCHA** **Spill Number: 8809431** **Close Date: 04/20/1995**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−083

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: NYCHA
Spiller Phone: (212) 306−3229
Notifier Type: Tank Tester
Notifier Name:
Notifier Phone:
Caller Name: JOHN LEDDY
Caller Agency: PRO−TEST
Caller Phone: (516) 321−4670
DEC Investigator: HEALY
Contact for more spill info:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
03/06/1989	04/20/1995	TANK TEST FAILURE	2−474967	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
002		Unknown	0.00	UNKNOWN

Caller Remarks:

40K TANK, HORNER−EZY CHEK, LR = −0.242GPH−MONITORING WELL HAS SIGNIF FREE PRODUCT−FENELY & NICOL TO INSTALL RECOVERY SYSTEM AND OIL−WATER SEPARATOR NEEDED AT BOILER RM. SEE SPILL # 9315373

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 58 **APART** **Spill Number: 0805163** **Close Date: 12/22/2009**
86 WEST 119TH STREET NEW YORK, NY TT−Id: 520A−0220−537

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1822 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Tank Tester
Caller Name:
DEC Investigator: MXAJOKU
Spiller: PAUL MARTINEZ − APART
Notifier Name:
Caller Agency:
Contact for more spill info: PAUL MARTINEZ
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (917) 217−3639

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/04/2008		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
	3000	Horner EZ Check I or II	0.00	UNKNOWN
		Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

DRY LEAK

DEC Investigator Remarks:

Case started out as a Tank Test Failure. Tank is 3,000 gal and no PBS was found. Tank will probably be replaced. Property Manager: Paul Martinez with Wavecrest Management 718−463−1200 Wavecrest compliance person looked up the records and confirmed the tank had never been registered. Building has an alternate address of 170 thru 178 Lenox Ave, Manhattan. Building is being sold through city HPD to be a tenant owned Co−op − Contact for this transfer is: Alan Blitz 212−479−3308 −Shuhab Housing Development Fund Corp 1780 Broadway Fl 6, New York NY 10019−1414 TTF letter sent to Mr. Blitz at Shuhab.

03/02/09: I left a voice massage for both Paul Martinez and Alan Blitz with respect to failure of the 3000 gallon tank, and non−compliance status because the facility is not registered under PBS. (MA)

12/17/09: DEC is in receipt of report document dated 10/22/09 prepared and submitted on behalf of Shuhab Housing Development Fund Corp by VTEQE LTD. The report documents investigation in connection with TTF, and PBS registration for the new AST. Based on this report document, spill number associated with the TTF is hereby closed. See eDocs for detail. (MA)

Map Identification Number 59 **APARTMENT BLDG − TTF** **Spill Number: 9808968** **Close Date: 11/28/2014**
120TH ST & SECOND AVE NEW YORK, NY TT−Id: 520A−0101−937

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1866 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 2ND AVE
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	HOWARD − BLDG MGR	Spiller Phone:	
Notifier Type:	Tank Tester	Notifier Name:		Notifier Phone:	
Caller Name:	MIKE SEPE	Caller Agency:	BENLEY & NICOL ENVIRO.	Caller Phone:	(516) 586−4900
DEC Investigator:	TJDEMEO	Contact for more spill info:	HOWARD LEAPORE	Contact Person Phone:	(212) 744−9707

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/19/1998		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	2000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

TANK WONT HOLD PRODUCT TO TEST IT − AUTOMATIC FAIL.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 − AUSTIN − TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT − END

7/27/05 − Transferred for closure review to M Johnson.

6/15/06 Transferred for closure review to T Knizek.

08/13/12 − LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo

11/28/14 TJD File review. No specific address provided. No historical information available. Spill administratively closed.

Map Identification Number 60 **THE EAST DRIVE H.D.F.C.** **Spill Number: 9802381** **Close Date: 11/26/2004**
205 EAST 124TH STREET MANHATTAN, NY TT−Id: 520A−0092−498

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1906 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	ROSE MURRAY	Spiller Phone:	(212) 722−6113
Notifier Type:	Tank Tester	Notifier Name:	ALBERTO LOPEZ	Notifier Phone:	(516) 321−4670
Caller Name:	JOHN LEDDY	Caller Agency:	PROTEST ENTERPRISES	Caller Phone:	(516) 321−4670
DEC Investigator:	SMSANGES	Contact for more spill info:		Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/22/1998		TANK TEST FAILURE	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	2000	Horner EZ Check I or II	0.00	FAIL

Caller Remarks:

APARTMENT BUILDING. CUSTOMER NOTIFIED OF RESULTS.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 5/18/04 − AUSTIN − TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT − END

9/10/04 − Sawyer − Talked to new manager for building. He will call back with as much information as he can find. The information should consist of the repair receipts and other supporting documentation for the clean up, if needed.

11/26/2004 Sangesland reviewed a submittal from ProTest. On Sept 30, 2004 ProTest isolated the tank and it passed. the problem was found to be a defective vent pipe. A partial replacement of this line was performed and the tank system then passed a tightness test. There were no visible signs of contamination.

Map Identification Number 61 **CORSI HOUSES (JEFFERSON) −NYCHA** **Spill Number: 9500828** **Close Date: 06/20/2014**
306 EAST 117TH STREET MANHATTAN, NY TT−Id: 520A−0092−181

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2136 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Tank Tester
Caller Name: SEBASTIAN LORIFICE
DEC Investigator: jkkann
Spiller: NYC HOUSING AUTHORITY
Notifier Name:
Caller Agency: NYC HOUSING AUTHORITY
Contact for more spill info:
Spiller Phone: (212) 306−3142
Notifier Phone:
Caller Phone: (212) 306−3233
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/20/1995		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

TANK #1 − GROSS FAILURE

DEC Investigator Remarks:

12/20/05: This spill transferred from J.Kolleeny to S.Kraszewski.

09/01/06: DEC Lead for this spill changed from unassigned to S. Kraszewski. − J. Kolleeny

02/09/07 − J.Kann − Spill reassigned from S.Kraszewski to J.Kann.

6/11/09: JKann − Meeting held on 5/28 with ALC Environmental and NYCHA. Investigative Work Plan submitted on June 10, 2009.

10/21/10: J.Kann − Approved work plan. Email sent.

5/8/13: J.kann− EMAIL SENT TO NYCHA ON 4/13/12, WP APPRVD 10/2010. NYCHA said site was overlooked. Due to inactivity, Stip sent on 5/6/13.

11/1/13: J.kann − SIR received on 10/31/13.

6/20/14: J.Kann − SIR reveiwed. 5 borings advanced and 3 wells installed. No SVOC or VOC exceedences of RSCOs. No product in wells and no VOCs or SVOCs above TOGS 1.1.1. NFA. Spill closed.

Map Identification Number 62 **CHURCH** **Spill Number: 0601542** **Close Date: 08/11/2006**
232 EAST 113TH STREET NEW YORK, NY TT−Id: 520A−0090−493

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2267 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	EVELYN − CHURCH	Spiller Phone:	(212) 860−7618
Notifier Type:	Tank Tester	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	HRPATEL	Contact for more spill info:	EVELYN	Contact Person Phone:	(212) 860−7618

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/11/2006		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	5000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

05/11/06−Hiralkumar Patel. Spoke to Jim at Protest. they found dry leak. no discharge. 5000 gal UST. Spoke to Evelyn at Church. she gave me following address for letter and letter should be sent to Principal. as per Evelyn they are waiting for proposal from Protest for further

Joanne Walsh Our Lady Queen of Angels 232 East 113 Street New York, NY 10029 PH. (212) 860−7618

(212) 722−9277 (school) FAX (212) 987−8837

send out TTF to principal of facility. faxed letter to principal.

06/06/06−Hiralkumar Patel. Spoke to Ted at Protest and will call back with more information. received call from Ted. they have received signed contract. will call once they decide dates about further work.

06/12/06−Hiralkumar Patel. received message from Mariam from Protest. spoke to Tom and they will go at site for tank test on next monday or tuesday.

06/16/06−Hiralkumar Patel. Received message from Maria from Protest yesterday. they were planning for further testing today. Spoke with Tom. as Church has some celebration going on today, they will reschedule testing. 07/10/06−Hiralkumar Patel. spoke with Maria. they did test and have result. but they will submit result once get paid. 08/10/06−Hiralkumar Patel. spoke with Maria and she will check and will call back. 08/11/06−Hiralkumar Patel. received call from Maria. during retesting, system passed. they have replaced vent line and vent whistle, stick line and fill box. based on available information, case closed.

Map Identification Number 63 **AMOCO** **Spill Number: 8809618** **Close Date: 03/25/2004**
255 EAST 125TH STREET NEW YORK CITY, NY TT−Id: 520A−0091−703

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2421 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	GASOLINE STATION OR PBS FACILITY	Spiller:	AMOCO GAS STATION	Spiller Phone:	(212) 996−3606
Notifier Type:	Tank Tester	Notifier Name:		Notifier Phone:	
Caller Name:	BOB MENIGKE	Caller Agency:	GASOLINE INSTALLATIONS	Caller Phone:	(718) 647−7443
DEC Investigator:	KMFOLEY	Contact for more spill info:		Contact Person Phone:	

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/14/1989		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

(2) 4K TANKS SIPHONED TOGETHER FAILED PETRO TITE WITH A LEAK RATE OF −.358GPH, WILL EXCAVATE, ISOLATE & RETEST.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 3/14/03 REASSIGNED FROM SULLIVAN TO VOUGHT. 1/8/04
Reassigned from Vought to K Foley. To be investigated and remediated under spill #9711337.

Map Identification Number 64 **JACKIE ROBINSON** **Spill Number: 9812531** **Close Date: 05/20/1999**
110 EAST 129TH ST MANHATTAN, NY TT−Id: 520A−0098−387

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	NYS HOUSING AUTHORITY	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	SEBASTIAN LOREFICE	Caller Agency:	NEW YORK CITY HOUSING AUT	Caller Phone:	(212) 306−3229
DEC Investigator:	SACCACIO	Contact for more spill info:	FRANK OCELLO	Contact Person Phone:	(212) 306−3229

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
01/11/1999		TANK TEST FAILURE	' −474959'	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	20000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

WILL ISOLATE AND RETEST.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

5/20/99 − Saccacio − Subsequent tank test failure. Previous tank test failures 9808458 on 10/8/99 closed and 9315465 on 1/16/92 open. See the latter spill for updates. Spill closed

Map Identification Number 65 **JACKIE ROBINSON HOUSING** **Spill Number: 9808458** **Close Date: 03/29/1999**
110 EAST 129TH ST MANHATTAN, NY TT−Id: 520A−0098−388

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	NYC HOUSING AUTHORITY	Spiller Phone:	
Notifier Type:	Tank Tester	Notifier Name:		Notifier Phone:	
Caller Name:	SEBASTIAN LOREFICE	Caller Agency:	NEW YORK CITY HOUSING AUT	Caller Phone:	(212) 306−3229
DEC Investigator:	SACCACIO	Contact for more spill info:	FRANK OCELLO	Contact Person Phone:	(212) 306−3229

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
10/08/1998		TANK TEST FAILURE	' −474959'	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	20000	Horner EZ Check I or II	0.00	UNKNOWN

Caller Remarks:

CALLER REPORTING TANK FAILURE.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

3/29/99 −Saccacio− Subsequent tank test failure. Previous tank test failure (9315465) on 1/16/92 will remain open. Spill closed 3/29/99.

Map Identification Number 66 **JACKIE ROBINSON HOUSES −NYCHA** **Spill Number: 9315465** **Close Date: 02/27/2004**
110 EAST 129TH ST MANHATTAN, NY TT−Id: 520A−0098−385

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NYCHA − JOE MONTELLA	Spiller Phone:	(212) 306−3142
Notifier Type:	DEC	Notifier Name:		Notifier Phone:	
Caller Name:	JANE HEALY	Caller Agency:	NYS DEC	Caller Phone:	(718) 482−4933
DEC Investigator:	JAKOLLEE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/16/1992		TANK TEST FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	−1.00	POUNDS	0.00	POUNDS	GROUNDWATER

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001		Unknown	0.00	UNKNOWN

Caller Remarks:

LEAK RATE OF −0.07 GPH − REPORTED AS PASSED BY TESTER.

See 9808458, 9812531, 9907036 and 9910794.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

3/29/99 −Saccacio− Subsequent tank test failure (9808458) on 10/8/98 and (98125310 on 1/11/99 closed and refered to this spill.

CLOSED STATUS UNKNOWN CAUSE SPILLS AND OTHER CAUSE SPILLS IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 67 **SERVICE BOX 19779** **Spill Number: 1301722** **Close Date: 07/19/2013**
E120TH ST/PARK AVE MANHATTAN, NY TT−Id: 520A−0289−155

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / PARK AVE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	UNKNOWN SOURCE	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RWAUSTIN	Contact for more spill info:	CON ED ERT	Contact Person Phone:	2125808383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/20/2013		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	0.10	GALLONS	0.00	GALLONS	

Caller Remarks:

1Pt Diesel in service Box, no resources affected. Chemical Analysis pending.

DEC Investigator Remarks:

7/19/13 − Austin − 1 pint of diesel fuel from leaking truck saddle tank impacted Con Ed vault − Con Ed contained and cleaned up the spill − See eDocs files for further information − Spill closed − See also spill # 1301696 − end

Map Identification Number 68 **VAULT 6340** **Spill Number: 9908760** **Close Date: 02/05/2004**
EAST 118TH ST/ PARK AVE NEW YORK, NY TT−Id: 520A−0091−070

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR LEE	Notifier Phone:	(212) 338−3352
Caller Name:	STEVEN CRIBBIN	Caller Agency:	CON ED	Caller Phone:	(212) 580−8576
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/19/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
TRANSFORMER OIL	PETROLEUM	4.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

no visual movement in water −− sample taken, clean up pending results. con ed 128525.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 128525:

FOUND 3.5 GAL.OF OIL AND 3.5 GAL.OF WATER IN V6340. PUMP NOT RUNNING NO OIL IN SUMP, SEWER CONNECT YES, CLEANUP PEND TEST.

PCB Results 5 ppm.

11/5/99 TRANSFORMER IN VAULT WAS REMOVED. THE VAULT WAS THEN CLEANED USING A FLUSH TRUCK. THE VAULT WAS ALSO DOUBLED WASHED USING BIOGEN.

11/8/99 THE SUMP PUMP WAS REPLACED, AN OIL MINDER WAS INSTALLED AND THE SECONDARY GAP WAS RECONNECTED.

Map Identification Number 69 **VACANT LOT** **Spill Number: 0813381** **Close Date: 08/21/2009**
127 EAST 119TH ST MANHATTAN, NY TT−Id: 520A−0226−396

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 454 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SFRAHMAN	Contact for more spill info:	JOHN GEARRITY	Contact Person Phone:	(212) 863−6539

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/11/2009		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

CALLER STATES THAT DURING AN EXCAVATION CONTAMINATED SOIL WAS FOUND CLEAN UP IS PENDING.

DEC Investigator Remarks:

03/12/09 CSL was sent to

NYC HPD 100 Gold Street, Room#9 I6 New York City, NY 10038 Attn: John Gearrity (sr)

08/21/09 Rec’d closure report from LIRO Engineers Inc.Site used to be residential in nature, reportedly had a fuel oil application from 1955 and is assumed to have used fuel oil for heating.Seven soil borings and one temp monitoring well was advanced at the site.Lab analyticals show voc/svoc levels in soil and ground water within acceptable limit.No continuing on site source.Report in edocs. Case closed.(sr)

Map Identification Number 70 **207583; SE PARK AV E 117 ST** **Spill Number: 0890186** **Close Date: 10/07/2007**
SE PARK AV E 117 ST , NY TT−Id: 520A−0220−071

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 538 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: PARK AVE / E 117TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	Unassigned	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/15/2007		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0.13	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

M42069 − SE PARK AV E 117 ST

CABLE OIL Closed: Agency Approval Not Required

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 71 **PARKING LOT** **Spill Number: 0703216** **Close Date: 06/19/2007**
1980 LEXINGTON AVE MANHATTAN, NY TT−Id: 520A−0100−053

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 580 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKOWN	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	hrpatel	Contact for more spill info:	BATTALION 12	Contact Person Phone:	(212) 570−4312

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/18/2007		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CALLER REPORTS SPILL OF HEATING OIL (UNK TYPE). BETWEEN E 121 AND E 120 ST. LEAK STOPPED AND IN PROCESS OF CLEANUP.

DEC Investigator Remarks:

06/19/07−Hiralkumar Patel. visited site on 06/18/07. met Frank Inoa, supervisor of Remediation Unit and Jasus Rojas, Emergency response personnel from NYC Housing Authority. as per Mr. Inoa, building management is installing new boiler for building and have installed temporary boiler in trailer in parking lot. temporary boiler has installed and maintained by Mobile Steam Boiler Rental. oil leaked from this temporary boiler and spilled in trailer and on asphalt parking lot. FDNY put speedy dry and did initial cleanup. no soil/groundwater affected. no vapors inside building. boiler has turned off.

Frank Inoa (718) 707−5718

Mobile Steam Boiler Rental (212) 884−1110

met Andrew Kelly from NYC DEP. Andrew checks a drain in parking lot, which is about 20 ft away from source. found speedy dry around drain and as per Andrew, he didn’t noticed any oil in drain.

received call from Mr. Inoa today. spill has been cleaned up and boiler rental company is working to fix leaking line.

all cleaned up. case closed.

Map Identification Number 72 **SPILL NUMBER 0311320** **Spill Number: 0311320** **Close Date: 01/07/2004**
127 EAST 117TH ST MANHATTAN, NY TT−Id: 520A−0096−085

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 646 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	FDNY OPERATIONS	Spiller Phone:	(718) 999−2094
Notifier Type:	Fire Department	Notifier Name:	CENTRAL COMMUNICATIONS	Notifier Phone:	(718) 999−2094
Caller Name:	DERISO	Caller Agency:	NYPD OPERATIONS	Caller Phone:	(646) 610−6039
DEC Investigator:	MXTIPPLE	Contact for more spill info:	FDNY OPERATIONS	Contact Person Phone:	(718) 999−2094

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/06/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	0	POUNDS	0	POUNDS	GROUNDWATER

Caller Remarks:

FDNY REPORTS DIESEL SPILL INTO THE WATER SYSTEM. SUBJECTS GETTING ILL.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 1/6/04 Tipple called FDNY dispatch, they were not certain of details, left # for callback. Called NYPD−− 2Times− portable boiler outside building emitting fumes, sewage in basement, foul odors from multiple directions. Called FDNY dispatch to update, FDNY field called stated FDNY had flushed the building and the problem had been resolved.

Map Identification Number 73 **MANHOLE 50789** **Spill Number: 9906696** **Close Date: 08/18/2009**
MADISON AV & 121ST ST MANHATTAN, NY TT−Id: 520A−0093−057

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 662 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: MADISON AV / E 121ST ST
Revised zip code: 10035

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Affected Persons
Caller Name: RICHARD ROACH
DEC Investigator: JMKRIMGO
Spiller:
Notifier Name: STEVE BOZE
Caller Agency: CON EDISON
Contact for more spill info: RICHARD ROACH
Spiller Phone:
Notifier Phone: (212) 580−6763
Caller Phone: (212) 580−6763
Contact Person Phone: (212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/05/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

ONE GALLON OF UNKNOWN OIL ON 200 GALS OF WATER. SAMPLE TAKEN − CLEAN UP PENDING RESULTS. CON ED 127599.

DEC Investigator Remarks:

08/18/09 − See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT

Map Identification Number 74 **SERVICE BOX 19135** **Spill Number: 1004210** **Close Date: 01/13/2011**
91 EAST 116 ST MANHATTAN, NY TT−Id: 520A−0253−057

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 705 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: 91 E 116TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RWAUSTIN	Contact for more spill info:	ERT	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/15/2010		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.13	GALLONS	0.00	GALLONS	

Caller Remarks:

spill contained to service box/clean up pending

DEC Investigator Remarks:

1/13/11 − Austin − #4 fuel oil contamination found in soil by Con Ed during service box removal − Unk. source, but contamination previously found at this location (see # 0406279) Con Ed contained and cleaned up the spill around service box − see eDocs for more information − Spill closed − end

Map Identification Number 75 **OPEN EXCAVATION** **Spill Number: 0406279** **Close Date: 10/16/2006**
91 EAST 116 ST. MANHATTAN, NY TT−Id: 520A−0093−590

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 705 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: 91 E 116TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	(212) 580−8383
Notifier Type:	Responsible Party	Notifier Name:	LARRY COSTA	Notifier Phone:	(212) 580−8383
Caller Name:	LARRY COSTA	Caller Agency:	CON ED	Caller Phone:	(212) 580−8383
DEC Investigator:	GDBREEN	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/08/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL
UNKNOWN PETROLEUM	PETROLEUM	0	POUNDS	0	POUNDS	SOIL

Caller Remarks:

SOIL SMELLS LIKE PETROLEUM OIL AND CHEM LAB HAS TAKEN SAMPLES AND WHEN THEY COME BACK CLEAN UP WILL PEND ON RESULTS. THIS IS BELIEVED TO BE A THIRD PARTY SPILL. CONTRACTOR IS FELIX ASSOCIATES. CON ED # 155275

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was BREEN

10/16/6: spill closed based on Con Ed report in eDocs. (JHO)

Map Identification Number 76 **SB 19622** **Spill Number: 9912403** **Close Date: 11/15/2004**
158 E. 119TH ST MANHATTAN, NY TT−Id: 520A−0096−089

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 710 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: UNKNOWN − Unknown Spiller Phone:
Notifier Type: Affected Persons Notifier Name: MR RUSSO Notifier Phone: (212) 338−3352
Caller Name: MARK SCHLAGEL Caller Agency: CON EDISON Caller Phone: (212) 580−6765
DEC Investigator: JHOCONNE Contact for more spill info: Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/30/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

unk oil in service box − sample taken clean up pending lab results con ed #129784

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

e2mis no. 129784:

Jan.30, 2000 10:35 hrs. Paul Reidmiller #52281 Underground Supervisor reports that on 01/30/00 @ 10:15 hrs he found approx. 1 quart of an unknown oil mixed with 2 gallons of water in sb−19622 f/o# 158 E.119 St while there responding to a secondary burnout complaint. The spill did not enter waterways or sewers and no other impact reported. There is no movement and no smoke or fire. There are no sumps or sewer connections. A P.C.B. sample was taken and tag# 10604 was installed by P. Reidmiller #52281. Cleanup is pending test results.

INCIDENT # 129784 , F/O 158 EAST 119 ST , SB.19622 , <1.PPM DATE AND TIME THE CLEANUP COMPLETED : 02/18/00 , 18:00 OPERATING SUPERVISOR : R.VELASQUEZ # 27188 CLEANUP PROCEDURE : OIL AND WATER REMOVED VIA TANKER UNDER <50.PPM,WAS DOUBLE WASHED WITH BIO−GENESIS SOLUTION (SLIX),SERVICE BOX WAS THEN RINSED BY FLUSH TRUCK. QUANTITY REMOVED FROM SITE AND TYPE OF CONTAINER'S USED : ONE PLASTIC BAG NON−HAZARDOUS WASTE (PPE & RAG'S),TRANSPORTATION TO EAST 110 ST YARD (MANHATTAN) PLACED IN A UNDER <50.PPM ACCUMULATION DRUM AT INDUSTRIAL WASTE TEMP STORAGE AREA. ASTORIA CORPORATE TRANSPORTATION TANKER UNDER <50.PPM ACCUMULATION 12 GAL'S OF OIL AND WATER MIXTURE. SPILL TAG REMOVED UPON COMPLETION

Map Identification Number 77 **SB 19623** **Spill Number: 9912404** **Close Date: 03/19/2002**
170 E.119TH ST MANHATTAN, NY TT−Id: 520A−0096−090

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 801 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN − Unknown	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR RUSSO	Notifier Phone:	(212) 338−3352
Caller Name:	MARK SCHLAGEL	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6765
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/30/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

unk oil in service box − on 2 gal of water − samples have been taken and clean up pending lab results − con ed #129785

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

Map Identification Number 78 **209996; E E 117 ST ST** **Spill Number: 0890369** **Close Date: 02/21/2008**
E E 117 ST ST , NY TT−Id: 520A−0220−069
E 117 ST 5th MADISON

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 834 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: E 117 ST / 5TH & MADISON
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	Unassigned	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/21/2008		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0.25	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

M19286 − 4−20 E 117 ST (MADISON & PARK AVES) − DIELECTRIC FLUID Closed: Agency Approval Not Required

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 79 **VACANT LOT** **Spill Number: 0613636** **Close Date: 03/27/2007**
1761 PARK AVENUE MANHATTAN, NY TT−Id: 520A−0099−418
121 ST ST.// PARK AVE

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 859 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER Spiller: BARBARA − VACANT LOT Spiller Phone:
Notifier Type: Citizen Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: SFRAHMAN Contact for more spill info: BARBARA Contact Person Phone: (212) 662−2553 ext. 3

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/21/2007		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

FROM A TRAIN, CALLER SAW A HALF SUBMERGED CONTAINER WITH A RUSTY TOP IN A LARGE PUDDLE AND BROWN SUBSTANCE ALL AROUND:

DEC Investigator Remarks:

Sangesland left a voicemail for Ms. Leiterman asking for more information.

Sharif will visit the site. 03/27/07 Sharif inspected the site on 03/22/07.This is a construction site,no oil spill/contamination was observed during my visit.Project Manager,(516)624−1979,C/O:BDG,300 Robbis Lane,Syosett, NY has been advised to make sure no oil spill occurs or if occurs,it has been cleaned up.

Map Identification Number 80 **MAN HOLE (19150)** **Spill Number: 9808122** **Close Date: 11/05/2003**
IFO 116 E. 116TH ST MANHATTAN, NY TT−Id: 520A−0100−056

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 924 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: I/F/O 116 E 116TH ST
Revised zip code: 10029

Source of Spill:	UNKNOWN	Spiller:	UNK	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	BILL MURPHY	Notifier Phone:	(212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	CAENGELH	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/01/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 pint of unk oil found in man hole clean up will be done soon clean up will done after sample test results come back provided pcb’s are with in limits

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 10/02/98 Amount spilled was 1 pint. The mamhole contained no water. The manhole did not appear to have any pathways to which the contained oil could escape. ConEd could not give me any discrption as to the purpose of the manhole.

E2MIS 120240

PT. CABLE OIL ON CONCRETE FLOOR IN MH−19150 F/O 116 E.116 ST.NO WATER IN STRUCTURE,SPILL DID NOT ENTER WATERWAY OR SEWERSYSTEM AND IS CONTAINED TO STRUCTURE.10/01/98 21:19 INCIDENT WAS REPORTED BY MR.FERRARO E.S.#06749 (R.W.) TO MR.CARROLL #71122.SAMPLE TAKEN AND TAG# 17212 INSTALLED.....CARROLL#71122−−−−−−−−−−MR MURPHY CIG NOTIFIED 10/01/98 2235 HRS BY MICHAEL CROWE #71453−−−−−−−−−−−−−−−−MC

10−5−98 09:15 Cleanup completed on 10−2−98 at 1300 hours, supervised by J.McCabe 00305. 1−pint oil removed with absorbant, mh was then double washed. 2−55 gallon drums hazardous waste generated. EPA#NYP004018313. Crew: M.Brotko 10504 and T.Robinson 50666. Tag left in place pending analysis.

10−7−98 13:15 SA98−10480 PCB 22 PPM

Tag 17212 removed 10−7−98 at 08:30 by P.Rubino 69511.

Map Identification Number 81 **MANHOLE #39219** **Spill Number: 9901217** **Close Date: 01/29/2004**
E 122ND ST & LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0091−027

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1008 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 122ND ST / LEXINGTON AV
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:	MR ROMERO	Notifier Phone:	(212) 580−6763
Caller Name:	FRANK MASSERIA	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/01/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

con ed #124577. clean up pending sample results. 1 gallon unknown oil on 500 gallons of water.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 124577:

APPROX. 1 GAL. OF UNKNOWN OIL ON APPROX. 500 GALS OF WATER. OIL IS CONTAINED TO THE MANHOLE. TOOK SAMPLE AND HUNG SIGN.

LAB SEQ#99−04534 AROCLOR 1260 PCB COUNT <1.00 PPM.

Cleanup complete on 5−4−99 at 1300 hours. 560 gallons oily water removed via tanker. MH flushed.

Map Identification Number 82 **177 EAST 117TH STREET** **Spill Number: 0650090** **Close Date: 11/13/2006**
177 EAST 117TH STREET , NY TT−Id: 520A−0097−567
APT. 4B

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1009 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	EAST 117TH STREET	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	rmpiper	Contact for more spill info:	RAPHAEL VILLANVEVA	Contact Person Phone:	(212) 427−2213

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/20/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL, AIR

Caller Remarks:

Vapors reported in basement by tenant. Tenant reported issue to NYSDOH. NYSDOH found vapors near the wall and floor at 1−2ppm and visible contamination on the basement wall. The suspected source is the adjacent building at 175 East 117th Street, New York, NY.

DEC Investigator Remarks:

NYSDOH contact: Peter Stallbohm, NYCDOH, 2 Lafayette Street, 11th floor, New York, NY, 10007. 212−676−2973. He will fax report with air quality sampling conducted at the site. 4/26/06− DEC Piper mailed CSL letter to MR. SAntana. APt 3 of bld. (owner).
11/13/06− DEC Piper has no other infomration. Caller has not called nor has NYCDOH. Closed.

Map Identification Number 83 **HARLEM COURTHOUSE** **Spill Number: 0013256** **Close Date: 12/10/2003**
170 EAST 121ST STREET MANHATTAN, NY TT−Id: 520A−0100−054

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1029 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Other
Caller Name: ISAAC MUNGRA
DEC Investigator: TJDEMEO
Spiller: UNKNOWN
Notifier Name: HENRY
Caller Agency: PETROLEUM TANK CLEANERS
Contact for more spill info:
Spiller Phone:
Notifier Phone: (718) 768−6500
Caller Phone: (718) 624−4842
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/19/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	200.00	GALLONS	200.00	GALLONS	SOIL

Caller Remarks:

CALLER'S AGENCY WAS CONTACTED FOR CLEAN UP. ALL HE KNOWS IS THAT 200 GALLONS CAME OUT OF THE VENT. UNKNOWN EXACT CAUSE. SPILLED INTO CONCRETE ALLEYWAY. BEING CLEANED UP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/10/03 TJD Product spilled to concrete. PTC responded with vac truck and absorbents. No disposal documents submitted. Spill administratively closed.

Map Identification Number 84 **2 WEST 120TH STREET** **Spill Number: 9208787** **Close Date: 03/31/1995**
2 WEST 120TH STREET MANHATTAN, NY TT−Id: 520A−0093−586

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1048 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:		Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:	COSMA ZINGAROPODI	Caller Agency:	NYCDEP	Caller Phone:	(718) 595−4653
DEC Investigator:	KSTANG	Contact for more spill info:		Contact Person Phone:	

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/28/1992	03/31/1995	UNKNOWN	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	1500	GALLONS	0	GALLONS	SOIL

Caller Remarks:

FD WENT OVER AND FOAMED BASEMENT YESTERDAY.HAZ MAT SPECIALIST ON ROUTE1 FT DEEP IN FUEL −KOON WAS ALREADY ON ROUTE WHEN I CALLED ,CALL BACK, RESPONDED W/ DEP HAZMAT, OIL IN BSMT CLEANED UP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

Map Identification Number 85 **DUTCH REFORM CHURCH OF HARLEM** **Spill Number: 0801742** **Close Date: 07/14/2009**
171 EAST 121 STREET NEW YORK, NY TT−Id: 520A−0214−966
A/K/A 169 EAST 121 STREET

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1098 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: 171 E 121ST ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ELDER SESSION − CHURCH	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RMPIPER	Contact for more spill info:	ELDER SESSION	Contact Person Phone:	(347) 351−6032

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/14/2008		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

STAIN ON WALL FROM PREVIOUS FILLS, NOT LIQUID PRODUCT: FOUND DURING BOILER INSPECTION

DEC Investigator Remarks:

Sangesland spoke to Michael Lacertosa of Coastal Combustion. He said they did an inspection of the boiler and tanks (2−275 gal) He noticed staining on the basement wall under the location where the fill line enters the building. This shows an indication that the fill line has a leak and the soil behind the basement wall in that location is saturated with oil.

CSL Letter sent to:

Louis Earl Sessoms Reform Dutch Church Of Harlem 169 E 121ST St New York NY 10035−3524

7/14/09− DECPiper spoke with Church. As per them, work was completed. I received work order from church from PTc. I spoke with PTC. Theyreplace the tanks and changed out fill and vent. no contamination noted. Based on work to date, this spill is closed.

Map Identification Number 86 **MAN HOLE 45730** **Spill Number: 1206234** **Close Date: 03/08/2013**
NORTH WEST CORNER EAST 120 ST AND 3 AVE NEW YORK, NY TT−Id: 520A−0279−309

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1168 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: EAST 120TH ST / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RWAUSTIN	Contact for more spill info:	ERT	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/24/2012		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.13	GALLONS	0.00	GALLONS	

Caller Remarks:

clean up pending

DEC Investigator Remarks:

3/8/13 − Austin − 1/2 pint of unknown oil found in vault − Con Ed contained and cleaned up the spill − See documents in eDocs file for further details − Spill closed − end

Map Identification Number 87 **217428; 118 ST AND 3 AVE** **Spill Number: 0914301** **Close Date: 07/14/2009**
118 ST AND 3 AVE MANHATTAN, NY TT−Id: 520A−0249−420

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1168 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: DMPOKRZY
Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/06/2009		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 88 **VAULT #VS−5236** **Spill Number: 0408556** **Close Date: 01/05/2005**
EAST 118TH ST. & 3RD AVE MANHATTAN, NY TT−Id: 520A−0090−844

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1168 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: EAST 118TH ST. / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Other
Caller Name: TOM MARCINEK
DEC Investigator: GDBREEN
Spiller:
Notifier Name: TOM MARCINEK
Caller Agency: CON ED
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone: (212) 580−6763
Caller Phone: (212) 580−6763
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/03/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	4.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

2 samples taken for ID and PCB content. e2MIS # 156093.

DEC Investigator Remarks:

e2mis 156093

R. Mahoney #97417 discovered 4 gal. of unknown oil, on top of 1000 gal. of water. No sewer/water affected. Substance; unknown oil. Source and cause of spill is unknown. Spilled on Concrete. No private property affected. There is oil filled equipment in the stucture. Yes, standing water. Sewer connection not verified. Concrete sump not verified. Can’t verify if sump pump is running. No visual water movement. No cracks in structure. Environmental tag # 49308; two samples were taken 1−pcb and 1 for oil id.

Nov. 03, 2004 14:24 CIG requested trap to be check for oil release. At this time there is no money in the budget to start the clean−up as per Bob. Pellgrino.

Lab Sequence Number: 04−09145−001 − PCBs < 1 ppm Lab Sequence Number: 04−09146−001 − analysis indicates the presence of a lubricating oil.

11/4 @ 17:25 Spoke to Joseph # 05658 of I&A and he reported to me that the cleanup wsx completed as of 17:10 on 11/4/2004. No solid waste was removed. Approx 1880 gallons of liquid waste was removed by the Astoria tanker. The structure was triple−washe with SLIX . Environemtnal tag # 41308 was removed.

Map Identification Number 89 **VAULT # 5236** **Spill Number: 0313016** **Close Date: 12/10/2004**
EAST 118TH ST. & 3RD AVE MANHATTAN, NY TT−Id: 520A−0090−824

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1168 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: EAST 118TH ST. / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	SEAN MCKEEVER	Notifier Phone:	(212) 580−6763
Caller Name:	SEAN MCKEEVER	Caller Agency:	CONED	Caller Phone:	(212) 580−6763
DEC Investigator:	SKARAKHA	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/25/2004		UNKNOWN	NO	NO

NO MATERIAL INFORMATION GIVEN FOR THIS SPILL

Caller Remarks:

5 Gal of Unknown OIl and 400 gal of water were spilled in an underground structure (vault) Do not have a crew available for clean up for the next 24 hrs. The CONED # 152234

DEC Investigator Remarks:

e2mis 152234

On 2/25/04 at 16:19 L. Bonapart # 24219 I&A supervisor called to report that at 16:5 B. Pagan # 13630 of the I&A found 5 gallons of an unknown oil mixed with 400 gallons of water in VS−5236 that is located at S/S E. 118 St. 25’ E/O 3 Ave. The cause & source are unknown at this time. There was no sewers or waterways affected. A tag was hung # 30906. Also 2 samples were taken 1 for pcb & 1− for ID.

Lab Seq N0 04−01422−001: Analysis indicates the presence of a substance similar to a dielectric fluid. Lab Sequence Number 04−01421−001: Aroclor 1242 < 1.0 ppm

A Vactor truck was assigned at 07:00 hrs. on 2/27/04 to assist I&A crew in cleaning this vault. See Flush Request #13258. According to the dispatcher the cleanup was completed. We are waiting for details of the cleanup in order to close this incident.

UPDATE: 03/01/04 17:15 hrs R. Biliski #04919 i&a supv reported to W. Lee #3324 mc that a partial cleanup was done on friday 27−feb−2004. Remove 800 gal of water/oil mixed from Vault, complete cleanup will be done when transformer is removed. Trans has a

double bushing leak, Put absorbent pads & granules.

07/09/04 12:02 E.Hulser#39723, cable supervisor, notified the control center on 07/09/04 at 11:05hrs. that the cleanup in V5236 was completed on 07/09/04 at 11:00hrs. There were no solids removed and no barrels or drums were used. There was approx. 50 gallons of water and oil mixed removed via vactor truck. V5236 was double washed with slixs. There was a yellow environmental tag removed from V5236. The source of the spill was a defective transformer, that has been removed. A new transformer has been installed. The cleanup was completed on 07/09/04 at 11:00hrs.

Map Identification Number 90 **MANHOLE M56965** **Spill Number: 0513522** **Close Date: 05/11/2006**
WEST 116 ST & 5 AVE MANHATTAN, NY TT−Id: 520A−0090−636

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1210 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: E 116TH ST / 5TH AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	ERT DESK MIKE DAUGHTERY − CON EDISON MANHOLES	Spiller Phone: (212) 580−8383
Notifier Type:	Responsible Party	Notifier Name:	CHRISTOPHER HAYNES	Notifier Phone: (212) 580−8383
Caller Name:	CHRISTOPHER HAYNES	Caller Agency:	CON ED	Caller Phone: (212) 580−8383
DEC Investigator:	GDBREEN	Contact for more spill info:	ERT DESK MIKE DAUGHTERY	Contact Person Phone: (212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/22/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

1 QUART ON DIRT NOT CLEANED UP PENDING TEST RESULTS. CON ED# 163052

DEC Investigator Remarks:

163052.000

Found @17:00. Called E/V desk@ 17:16. M56965 − W 116 ST 37 43 (5 AVE). Stephen Presuto14921, Trouble Shooter Hv, Was in

process of doing a manhole inspection And found unknown oil coming from duct on north wall of manhole to soil on concrete floor of manhole. He states that it is approx. 1 Qt total, mixed with soil. And also reports the following: There was or is no smoke or fire involved. No sewer or waterway affected. No injuries and weather had no affect. Account #F7160 is being used for this incident. Source and cause of spill are unknown. No private property affected. No oil filled equipment in the structure. Environmental yellow tag # 38879 was applied. No standing water. No substantial cracks. W/bound lane. 2 liquid samples were taken from the spill, 1 for id and 1 for pcb. Sample priority E . Chain of custody # EE11972. Logger F.Curtis 38078

Update: after phone conversation with T.Regan 07430,this incident is now Spill−Unknown Oil Type Due to the finder was not sure as to the source of oil. Logger F.Curtis 38078.

5/11/06 This spill is being closed on the basis of the report in eDocs. (SKA)

Map Identification Number 91 **PARKS REC SYSTEM** **Spill Number: 0813485** **Close Date: 03/18/2009**
18 MOUNT MORRIS PARK WEST MANHATTAN, NY TT−Id: 520A−0226−445

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 1232 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: 18 W MOUNT MORRIS PARK
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NONE − CITY OF NEW YORK	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RMPIPER	Contact for more spill info:	NONE	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/13/2009		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL

Caller Remarks:

Caller states they found trace lelments of petroleum compounds in soil results.

DEC Investigator Remarks:

x236 need CSL to be sent

LiRo documented the removal of one 5,000−gallon heating oil (#2 diesel) underground storage tank (UST) at the Pelham Fritz Recreation Center. The removal was conducted by Gemstar Construction Corp. of Staten Island, NY. The Pelham Fritz Recreation Center is located within the western portion of the Marcus Garvey Park at 18 Mount Morris Park West in Manhattan, New York. The tank was being replaced as part of an ongoing New York City Department of Design and Construction UST management and upgrade program. No problems had been previously reported for the heating oil tank.

A 5,000−gallon heating oil single−wall steel UST and associated piping were removed from the site. During the excavation of the tank, the top of the tank was encountered at approximately 3.5 feet below ground surface and a concrete bottom slab was encountered at approximately 10.5 feet below ground surface. Upon inspection, the exterior of the tank had surficial rust. However, the interior and exterior of the UST were free of any visual damage such as holes, pitting or degradation. No staining or discoloration was noted within the excavation. The bottom slab was removed and six excavation bottom samples were collected at a depth of 12 feet bgs along the centerline of the excavation (see attached figure).

The laboratory results (also attached) showed relatively low VOC concentrations. SVOC concentration for several PAHs exceeded TAGM 4046 criteria and therefore I called in a spill report. No water was observed in the excavation. Based on surrounding locale (there are bedrock outcrops in the Park) we expect that the depth to rock and groundwater is 25 feet or less. LiRo is preparing a UST Closure report that will be submitted to NYSDEC.

Map Identification Number 92 **SERVICE BOX 45747** **Spill Number: 9812163** **Close Date: 11/04/2003**
2236 3RD AVE MANHATTAN, NY TT−Id: 520A−0092−565

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1248 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	MR ROMANO	Notifier Phone:	(212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	BILL MURPHY	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/30/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	3.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OIL FOUND IN THE BOX. SAMPLES WERE TAKEN FOR PCB CONTENT AND CLEAN UP PENDING LAB RESULTS.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS 122183

12/30/98 23:10 T.BROWN(14932) RW REPORTS HE FOUND SPILL OF 3 GALLONS OF UNKNOWN OIL IN SB45747 LOCATED F/O 2236 3 AVE. SPILL WAS FOUND WHILE RESPONDING TO REPORTS OF A MANHOLE FIRE. SPILL IS CONTAINED. THERE WAS NO ENTRY TO ANY SEWERS OR WATERWAYS. A SAMPLE WAS TAKEN AND SPILL TAG #21881 WAS INSTALLED. THERE ARE NO CRACKS IN THE STRUCTURE AND NO SEWER CONNECTIONS. THE IS NO OIL CONTAINING EQUIPMENT IN THE HOLE. THERE ARE NO AGENCIES ON LOCATION. SPILL WAS FOUND AT 22:10 HRS ON 12/30/98 AND REPORTED TO ROMANO IN THE CONTROL CENTER AT 22:30 HRS.

If this is a Con Edison manhole it contains electrical cable and splices. Many manholes have a sealed sump in the floor which is used to allow runoff when pumping the structure. A hose is place in this sump and water on the floor will flow into the sump allowing the floor to be cleaned. If cleaned prior to analysis of the fluid, the structure will be cleaned as >50 PPM and all liquid and waste will be manifested accordingly. The structure will be double washed with a degreaser, i.e. Slix. All cleaning material and PPE will also be treated as >50. If any sludge is found within a manhole it is treated as lead contaminated and manifested accordingly. The spill identification tag will remain secured to the structure until the analysis is completed and if <500 PPM the signage will be removed. If the analysis is >499 PPM, a grid will be prepared for wipe testing the area. Until the analysis of the wipes are proven to be <10ugs/100cme2 all additional waste produced from the structure will be treated as the original analysis. If this spill occurred in a transformer vault containing a sump pump and there was a possible release, the drainpipe trap will be dismantled to determine if oil was released. Sludge found in a vault, through historical analysis, has been determined not to contain lead.

12/30/98 ROMANO NOTIFIED ROMERO(CIG) OF THE SPILL. THIS REPORT WAS ENTERED ON 12/31/98 AT 09:18 DUE TO E2MIS BEING DOWN ALL NIGHT.

12/30/98 P.MCHUGH(80285) ADVISED F.MASSERIA(CIG) OF THE INCIDENT NIMBER.

01/02/99 0137 HRS RESULTS OF LAB ANALYSIS 98−14418: AROCLOR: NONE; PCB: <1 NOTE: THE E−MAIL MESSAGE ON WHICH THIS UPDATE WAS SENT INDICATED THE STRUCTURE AS BEING MH45747. THE STRUCTURE WHERE THE SPILL WAS DISOVERED IS SB45747 AS PER E2MIS INCIDENT# 122183. LOGGER JP HEFFERNAN 74031

1−4−99 18:40 Cleanup completed on 1−4−99 at 1130 hours supervised by R.Velasquez 27188. There was no evidence of oil on arrival, SB was flushed, tag 21881 removed. 1− plastic bag non−hazardous waste generated (PPE). Crew: J.Burgos 07271, A.Tucker 16707, and A.Williams 77418.

Map Identification Number 93 **2236 3RD AVE** **Spill Number: 0201236** **Close Date: 09/18/2002**
2236 3RD AVE OFF OF 128 EAST ST MANHATTAN, NY TT−Id: 520A−0093−402

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1248 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: 2236 3RD AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR GALLIGER	Notifier Phone:	
Caller Name:	ANDREW MORRIS	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	KMFOLEY	Contact for more spill info:	ANDREW MORRIS	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/02/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 qt of possible oil in in box 45747. con ed 142626 number. nothing leaking .

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed em2is #142626:

@15:15 on 05/02/02 I.Dejesus #15889 mech A found 1 quart. Of unknown oil in sb45747 and app. five gallons of water. This structure was cleaned on 05/01/02 see E2mis report # 142603. Employee stated that S45747 is in front of an auto parts store. Employee stated that he could not see anything leaking into structure. Hung sign #18792. Took two samples one for PCB and one for oil id. Chain of custody #AA31828 Reason for entering site:repairs No smoke/fire was involved No waterway/sewer affected No private property affected No injuries related to spill No weather conditions contribute to hazard of spill No sewer connection, No substantial cracks. Source of spill: unknown oil Cause of spill: unknown Account #12007 reported to A. Morris # 85791 C.I.G. at 16:49 on 05/02/02 logger M.gallagher

reported to E.R.T. B. Pierre who stated he will look into it. loggerM.

cleanup is scheduled for 07:00 0n 05/02/02 over 50 tanker ordered. E.P.A. # N.Y.P −004−098−117 is good for 30 days at this

location as per E.R.T. B. Pierre. logger M.

Date Approved − 5/3/2002 Date received and sampled − 5/2/2002 Aroclor 1242 < 1.0 ppm EPA 608/8082 Aroclor 1254 < 1.0 ppm EPA 608/8082 Aroclor 1248 < 1.0 ppm EPA 608/8082 Aroclor 1260 < 1.0 ppm EPA 608/8082

Total PCB < 1.0 ppm

On 05/03/02 R. Velasquez # 27188 reported that at 11:00 cleanup was complete. structure was double washed with slix. 25 gallons of liquid was removed by tanker. 3 bags of ppe was removed. spill tag #18792 was removed. cleanup crew are listed in people event log. this is a open double grating cover about one foot off the curb. cleanup was called in at 11:10

Map Identification Number 94 **SERVICE BOX 45748** **Spill Number: 9812162** **Close Date: 11/04/2003**
2238 3RD AVE MANHATTAN, NY TT−Id: 520A−0092−564

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1262 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	MR ROMANO	Notifier Phone:	(212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	BILL MURPHY	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/30/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OIL WAS FOUND IN THE SERVICE BOX.SAMPLES WERE TAKEN FOR PCB CONTENT AND CONTAINED IN THE BOX.CLEAN UP PENDING LAB RESULTS.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS 122182

12/30/98 22:30 T.BROWN(14933) RW REPORTS HE FOUND SPILL OF 1 GALLON OF UNKNOWN OIL IN SB45748 F/O 2238 3 AVE. SPILL IS CONTAINED, THERE WAS NO ENTRY TO ANY SEWERS OR WATERWAYS. THERE WERE NO VISIBLE CRACKS IN THE STRUCTURE AND THERE WAS NO SEWER CONNECTION. A SAMPLE WAS TAKEN AND SPILL TAG #21880 WAS INSTALLED. THERE WERE NO AGENCIES ON LOCATION. THE REASON FOR ENTERING THE STRUCTURE WAS DUE TO A MANHOLE FIRE AND THERE IS NOT ANY OIL CONTAINING EQUIPMENT IN THE HOLE. SPILL WAS FOUND AT 22:00 HRS ON 12/30/98 AND REPORTED TO D.ROMANO IN THE CONTROL CENTER AT 22:30 ON 12/30/98.

If this is a Con Edison manhole it contains electrical cable and splices. Many manholes have a sealed sump in the floor which is used to allow runoff when pumping the structure. A hose is place in this sump and water on the floor will flow into the sump allowing the floor to be cleaned. If cleaned prior to analysis of the fluid, the structure will be cleaned as >50 PPM and all liquid and waste will be manifested accordingly. The structure will be double washed with a degreaser, i.e. Slix. All cleaning material and PPE will also be treated as >50. If any sludge is found within a manhole it is treated as lead contaminated and manifested accordingly. The spill identification tag will remain secured to the structure until the analysis is completed and if <500 PPM the signage will be removed. If the analysis is >499 PPM, a grid will be prepared for wipe testing the area. Until the analysis of the wipes are proven to be <10ugs/100cme2 all additional waste produced from the structure will be treated as the original analysis. If this spill occurred in a transformer vault containing a sump pump and there was a possible release, the drainpipe trap will be dismantled to determine if oil was released. Sludge found in a vault, through historical analysis, has been determined not to contain lead.

12/31/98 23:10 ROMANO NOTIFIED S.ROMERO(CIG) OF THE SPILL..... *** THIS JOB WAS ENTERED ON 12/31/98 AT 09:07 BECAUSE E2MIS WAS DOWN ALL NIGHT.

12/31/98 09:30 P.MCHUGH NOTIFIED F.MASSERIA(CIG) OF THE INCIDENT NUMBER.

1−12−99 09:55 Job delayed until 1−8−99 because of incorrect address on original oil sample results. Cleanup completed on 1−8−99 at 1100 hours, supervised by R.Valasquez 27881. No oil found in SB, mud and water only, SB flushed. Tag 21880 removed. Crew: J.Burgos 07271 and J.Pelzer 06470.

Map Identification Number 95 **OPPOSITE OF 3 WEST 116 ST** **Spill Number: 0305658** **Close Date: 06/02/2005**
OPPOSITE OF 3 WEST 116 ST MANHATTAN, NY TT−Id: 520A−0093−403

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 1320 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: OPPOSITE OF 3 WEST 116TH ST
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Affected Persons
Caller Name: RON ELLIOT
DEC Investigator: JHOCONNE

Spiller: SAME − UNKNOWN FOR NOW
Notifier Name: SAME
Caller Agency: CON EDISON
Contact for more spill info: RON ELLIOT

Spiller Phone:
Notifier Phone:
Caller Phone: (212) 580−6763
Contact Person Phone: (212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/27/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	15.00	GALLONS	0.00	GALLONS	SOIL
The following material(s) was dropped or revised by the NYS DEC. Call Toxics Targeting for more information						
OTHER PETROLEUM	UNKNOWN	15.00	GALLONS	0.00	GALLONS	

Caller Remarks:

CON ED HAS 25 YARDS OF CONTAMINATED SOIL SPILL IS FUEL OIL UNKNOWN TYPE FUEL OIL

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 150−081:

On 8/27 @ 14:35 K. Watts of Construction Management reported that while his Contractors were working at address Opposite 13 W116 St discovered a foul smelling dark soil that has a fuel oil smell. There is approx 25 yards of soil that is affected and approx 15 gallons of the oil in the open excavation. The excavation is approx 60'L x 10'W x 12'D. They are excavating on the sidewalk to install Transformer Vaults there. According to Watts there is a river going north/south beneath where they are excavating and they were going to support this area so our equipment does not sink. Chem Lab has been called for 8/28/2003 in the morning to take samples for PCB, ID and Flash point. No cleanup action is being taken at this time.

UPDATE

8/27 @ 16:45 the original 300 yards that was removed was clean dirt. After they reached the 12' level they (Contractor) noticed the fuel smelling dirt. The Project Manager R Diaz originally told Watts that the River water table was in the vicinity (approx 15' to 17' down.). Also the job included sinking piles to put a Pad on to support the Transformers. Watts told me that the chances were very good that the water could be affected.

12/04/03 @9:49 − The lab resutlst (03−07197−001; 03−07196−001; 03−07195−001) indictate presense of Lt. fuel oil and THC is 530 PPM. PCB <1. As per K. Watts #19705, six roll off of soil were removed and transported by Clean Harbors as oily soil to Con Edison approved site. No water was involved. The job was completed on 10/23/03 and the excavation was backfilled. Incident being closed. Updated by Bharat Mukhi #72227 M&C − EHS.

Map Identification Number 96 **79 E 124TH ST** **Spill Number: 9304099** **Close Date: 03/31/1995**
79 E 124TH ST MANHATTAN, NY TT−Id: 520A−0091−981

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1366 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN Spiller: UNK Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: RICHARD ZINGARD Caller Agency: GLASSO CONTRACT INC. Caller Phone: (718) 456−1800
DEC Investigator: MCTIBBE Contact for more spill info: Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/30/1993	03/31/1995	UNKNOWN	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL

Caller Remarks:

12−15 FEET INTO EXCAVATION FOR NEW NY TELEPHONE VAULT− DISCOVERED OIL CONTAMINATION CALLER WOUL LIKE CALL BACK ASAP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

/ / : INSTALLED AND MONITORED WELLS. NO PRODUCT RECOVERED OR SHOWED UP IN WELLS.

Map Identification Number 97 **63 W 119TH ST** **Spill Number: 0107880** **Close Date: 05/30/2014**
63 W 119TH ST NEW YORK, NY TT−Id: 520A−0093−578

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1508 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	TANK TRUCK	Spiller:	UNK	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:	FF 7461	Notifier Phone:	(917) 769−0483
Caller Name:	FF 7461	Caller Agency:	NYFD	Caller Phone:	(917) 769−0483
DEC Investigator:	RWAUSTIN	Contact for more spill info:	NYC HOUSING OP # 171	Contact Person Phone:	(212) 824−4328 ext. 0

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/01/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

delivery of fuel today mayterila is located in basement unk at this point if any contamination left the basement

fd on scene now pumping some of the material out waiting for nyc housing to respond

nyc housing comp # 1519000

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 11/02/2001 DEMEO REFERRED THE FOLLOWUP TO TIPPLE.

VERNON ROBERTS PRIOR SUPER 718−861−2480

DAUGHTER AND FORMER OWNER CHERYL ROBERTS 212−926−6274

THE PROPERTY WAS TAKEN BACK BY HPD FOR NON−PAYMENT OF TAXES AS PER CONVERSATIONS WITH BOTH VERNON AND CHERYL. THEY BOTH EITHER HAVE NO KNOWLEDGE OF OR REFUSE TO REVEAL THE NAME OF THE OIL COMPANY THAT OVERFILLED THE TANK.

JIM GALLAGHER 212−863−8638 EMERGENCY REPAIR BUREAU OF HPD WAS CALLED IN AN ATTEMPT TO FIND THE OIL COMPANY.

2/6/03 − AUSTIN, DDO − CALL FROM LORETTA METRO FUEL(718−383−1400) − SHE WANTS TO CLOSE OUT THE SPILL FOR A CLIENT − I TOLD HER TO FOIL RECORDS, PROVIDE AN UPDATE TO US FOR CLOSURE

10/10 03 TIPPLE SENT REQUEST FOR DOCUMENTATION

10/8/10 − Austin − Reassigned from Tang to Spills staff − end

** PBS: 2−611816, contact Allen Grumps,(516) 779−1033 **

5/30/14 − Austin − Spill closed out due to age of report and any further information to contradict such action − end

Map Identification Number 98 **SPILL NUMBER 0304253** **Spill Number: 0304253** **Close Date: 07/23/2003**

65 W 119TH ST MANHATTAN, NY TT−Id: 520A−0093−579

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1525 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:	DISPATCHER	Notifier Phone:	
Caller Name:	FDNY HAZMAT1	Caller Agency:		Caller Phone:	(917) 769−0485
DEC Investigator:	TJDEMEO	Contact for more spill info:	FIRE FIGHTER BARRY	Contact Person Phone:	(917) 769−0485

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/22/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CEMENT PRODUCTS	OTHER	5.00	GALLONS	0.00	GALLONS	SEWER

Caller Remarks:

fire department cleaned up what they could with absorbant pads and have left the scene however there is some material still in the sewer drain, material is a roofing cement

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Spill forwarded to NYC − DEP

Map Identification Number 99 **VAULT #9153** **Spill Number: 0400692** **Close Date: 07/27/2004**
3RD AVE / E 123 ST MANHATTAN, NY TT−Id: 520A−0093−381

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1546 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: 3RD AVE / E 123RD ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − VAULT #9153	Spiller Phone: (212) 580−8383
Notifier Type:	Local Agency	Notifier Name:	MR. CURTIS	Notifier Phone: (212) 580−6763
Caller Name:	PAUL DINONATO	Caller Agency:	CONED	Caller Phone: (212) 580−6764
DEC Investigator:	JHOCONNE	Contact for more spill info:	ERT DESK	Contact Person Phone: (212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/21/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

2 QRTS OF UNKNOWN OIL FOUND ON 1 QRT OF WATER. CALLER ANSWERED NO TO ALL 5 QUESTIONS. CON ED REF #153000.

FOUND SUMP AND OIL IN YTRAP AND SOME HAS GONE INTO SEWER: UNKNOWN AMOUNT**********

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 153000:

Found approx. 2 qt of unknown oil mixed with approx. 1 qt of water. He also reports that sump pump was found unplugged. Clean up pending crews. And transformer is to be de− energized.

09:50 A.Prazan #88744 i&a supv reported when he went to investigate v−9153 @ 0946 hrs. open trap and found oil release to sewer and waterway unknown amoumt.transformer hole 285 gal of oil. Did a presure check, transf did not hole presure.

Lab Sequence Number: 04−03032−001 PCB 44 ppm

5/31 @ 10:40 V Mirance reported to me that the cleanup completed as of 10:30 on 5/31/2004. The structure was triple−washed with

SLIX . The source was the Transformer and it was removed and replaced.

Map Identification Number 100 **MANHOLE 19753** **Spill Number: 0009907** **Close Date: 04/05/2001**
58 WEST 120TH ST MANHATTAN, NY TT−Id: 520A−0093−577

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1552 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	BRUNS	Notifier Phone:	
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	OKWUOHA	Contact for more spill info:	BILL MURPHY	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/01/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

3 TS UNK OIL ON 1 QT OF WATER CONFINED TO MANHOLE − SAMPLE TAKEN CLEAN UP PENDING RESULTS CON ED 134567

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

e2mis Notes:

3 quarts unknown oil with 1 quart water in manhole−19753. Cause and source of substance unknown. Spill is on concrete floor. 2 samples taken for ID and PCB. Analysis indicates teh substance is similar to dielectric fluid. There were problems with PCB analysis. Chem Lab had to rum analysis 3 times. As per telephone conversations with Stella Volpe, indications were that PCB analysis is over 50ppm. Double washed floor and walls with slix. 2−55gal drums were generated. PCB count is 193ppm.
KMF 4/9/01.

Map Identification Number 101 **MANHOLE 45668** **Spill Number: 0002184** **Close Date: 03/24/2004**
3RD AVE/EAST 115TH MANHATTAN, NY TT−Id: 520A−0092−735

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1577 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: 3RD AVE/EAST 115TH ST
Revised zip code: 10029

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:	MR CARROL	Notifier Phone:	(212) 580−6763
Caller Name:	TONY LOPEZ	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	TONY LOPEZ	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/21/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 GAL OF OIL ON 150 GAL WATER. CON 131516. CLEAN UP PENDING RESULTS.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 131516:

1 gal of unknown oil on 150 gals of water in manhole 45668. Conduit records indicate structure has a sump with sewer connection.
Clean up to be made as 50−499 ppm pCB.

LAB SEQ.# 00−05024 PCB <1 PPM

DATE AND TIME THE CLEANUP WAS COMPLETED: 05/22/00, 12:00 NOON. CLEANUP PROCEDURE: OIL AND WATER MIXTURE REMOVED VIA TANKER OVER 50.PPM, FLUSH TRUCK FROM FLUSH OPERATIONS USED A HIGH PRESSURE HOSE TO TRIPLE WASHED THE FLOOR AND WALLS WITH BIO−GENESIS SOLUTION−760 (SLIX), MANHOLE WAS THEN RINSED BY FLUSH TRUCK.

Map Identification Number 102 **APPLE BANK** **Spill Number: 9512216** **Close Date: 12/29/1995**
124 EAST 125TH ST MANHATTAN, NY TT−Id: 520A−0092−259

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1584 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name: JIM CAREY
DEC Investigator: SMMARTIN

Spiller: UNK AT THIS TIME
Notifier Name: KURT MELHORN
Caller Agency: CASTLE OIL CORPORATION
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone: (718) 579−3414
Contact Person Phone: (212) 360−7533

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/29/1995		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	5.00	GALLONS	5.00	GALLONS	SOIL

Caller Remarks:

possible tank overfill − still being investigated at this time spill being cleaned up

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT

Map Identification Number 103 **2ND AVE SUBWAY PROJECT − NYCT** **Spill Number: 0302791** **Close Date: 09/01/2005**
PARK AVE/125TH ST MANHATTAN, NY TT−Id: 520A−0099−401

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1594 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / PARK AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	SAME	Notifier Phone:	
Caller Name:	SIRISH MUSTHYAL	Caller Agency:	DMJM HARRIS	Caller Phone:	(212) 510−2616
DEC Investigator:	MCTIBBE	Contact for more spill info:	SIRISH MUSTHYAL	Contact Person Phone:	(212) 510−2616

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/16/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

Soil borings taken at above location havve revealed contamination.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 2nd Ave Subway Project

09/01/05: Elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil and GW sampling showed only minor hits of metals and a few SVOCs constituents.

Map Identification Number 104 **125TH ST BTWN MADISON −NYCT** **Spill Number: 0301445** **Close Date: 08/26/2005**
125TH ST PARK& MADISON SO MANHATTAN, NY TT−Id: 520A−0101−459

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 1595 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST BTWN MADISON AVE / PARK AVE
Revised zip code: 10035

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:	GARRY GUTSHTEYN	Notifier Phone:	(908) 437−7083
Caller Name:	GARRY GUTSHTEYN	Caller Agency:	DHA	Caller Phone:	(908) 437−7083
DEC Investigator:	MCTIBBE	Contact for more spill info:	KEITH RYAN	Contact Person Phone:	(908) 437−7083

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/09/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

this is historic spill from while collecting geotec samples − 13−17feet is where it was found − poss a petroluim of some sort

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 5/9/03 − ROSSAN, DDO − This spill was assigned to mark Tibbe,

but was passed on to Steve Miller for follow−up action.

END

08/26/05: Elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil and GW sampling showed only minor hits of metals and a few SVOCs constituents.

Map Identification Number 105 **HOUSING PROJECT** **Spill Number: 9802907** **Close Date: 03/03/2003**
1740 MADISON AVE MANHATTAN, NY TT−Id: 520A−0095−996

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1605 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Other
Caller Name: FRAN ARCHEY
DEC Investigator: TOMASELLO

Spiller: FRAN ARCHEY − HOUSING PROJECT
Notifier Name: FRAN ARCHEY
Caller Agency: A L EASTMOND
Contact for more spill info: UNK

Spiller Phone: (718) 378−3000
Notifier Phone: (718) 378−3000
Caller Phone: (718) 378−3000 ext.
Contact Person Phone: (000) 000−0000

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/01/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

UPON EXCAVATION SOIL WAS FOUND TO BE CONTAMINATED−WILL PROCEED TO REMOVE TANK AND CONTAMINATED SOIL.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 106 **DRUM RUN** **Spill Number: 0806548** **Close Date: 10/03/2008**
228 EAST 117 ST BTW 2ND & 3RD AVE MANHATTAN, NY TT−Id: 520A−0224−037

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1623 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: 228 E 117TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	HRAHMED	Contact for more spill info:	CHIRS YESMONT	Contact Person Phone:	(646) 265−6108

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/11/2008		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
WASTE OIL/USED OIL	PETROLEUM	0	GALLONS	0	GALLONS	

Caller Remarks:

CALLER STATES THAT A 55 GALLON DRUM WAS LEFT ON THE SIDEWALK ABOUT 3−5 QUARTS WAS SPILLED. CLEAN UP IS IN PROGRESS WITH SPEEDY DRY.

DEC Investigator Remarks:

10/03/08−HRAHMED−One 55 gallon partially filled drum was found and pumped out. Notified Dept. of Sanitation to pickup the empty drums on 10/03/2008.

This case is closed.

Map Identification Number 107 **208153; MADISON AVE** **Spill Number: 0890227** **Close Date: 12/04/2007**
MADISON AVE , NY TT−Id: 520A−0220−070
MADISON AV 125TH 124TH

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1637 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 125TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	Unassigned	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/20/2007		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0.06	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

E/S MADISON AV 50’ S 125 ST

INSULATUM Closed: Agency Approval Not Required

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 108 **79 WEST 119 STREET** **Spill Number: 9313703** **Close Date: 02/24/1994**

79 WEST 119 STREET MANHATTAN, NY TT−Id: 520A−0093−584

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1650 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: 79 WEST 119TH STREET
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:		Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:	MR WATT	Caller Agency:	NYC DEP	Caller Phone:	(718) 595−6777
DEC Investigator:	CAMMISA	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/22/1994	02/24/1994	UNKNOWN	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	−1.00	UNKNOWN	0.00	UNKNOWN	SOIL

Caller Remarks:

HPD BLDG DELIVERING − IN FRONT OF HOUSE AND HER BASEMENT IS OIL CAUSED SPILLED − DEP HAZMAT ENROUTE TO CLEAN UP − NO CALL BACK − CALLED DEP FOR INFORMATION AND REQUEST FOR DEC ASSISTENCE.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 109 **PRIVATE RESIDENCE** **Spill Number: 9703960** **Close Date: 11/07/2003**
236 E 118TH ST PT 9 MANHATTAN, NY TT−Id: 520A−0096−097

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1658 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: 236 E 118TH ST
Revised zip code: 10026

Source of Spill:	PRIVATE DWELLING	Spiller:	TIM SOILCH − CON EDISON	Spiller Phone:	(212) 580−6764
Notifier Type:	Responsible Party	Notifier Name:	STEVE ROMERO	Notifier Phone:	(212) 580−6763
Caller Name:	STEVE ROMERO	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	CAENGELH	Contact for more spill info:	JOSE MERCADO	Contact Person Phone:	(212) 876−2849

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/01/1997		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
MERCURY	HAZARDOUS MATERIAL	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

CON ED ADVISED TENANT TO REMOVE THE MANOMETER SO THAT A STOVE COULD BE INSTALLED−THE MANOMETER FELL ONTO KITCHEN FLOOR−OVER 1 OUNCE OF MERCURY WAS SPILLED−CLEAN VENTURE HAS BEEN CALLED IN FOR CLEAN UP AT SPILL LOCATION

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT E2MIS 108880

St.St.7/01/1997 MG97007720

15:45 At 236 E 118 Street, a plumber?s pressure gauge filled with Mercury spilled on the kitchen floor of apt. #9. The plumber, who was not on location, left a mercury test on the tenants house pipe. The tenant, Jose Mercado, removed gauge and spilled the mercury. Con Edison employee, GDS Mechanic A ,Clarence McDonald, # 07598, stepped over mercury, tested house pipe and restored gas service. Same employee left apartment and location and returned to his workout location at 271 Avenue C (E 16 St. yard).
17:25 McDonald reports spill to Dennis Callahan, Operating General Supervisor in the Manhattan Gas Control Center.

17:30 GDS Manager Bavuso notified of spill.

17:33 Callahan pages E.R.T. Avery Tom and left message.

17:40 E.R.T. Tom calls MCC and is informed of spill.

17:45 C.I.G. Romano is notified.

18:10 Susan Duffy of Industrial Hygiene called MCC and is informed of spill.

Con Ed employee, McDonald is isolated in room at E16 St. Yard and vehicle #23298 is also isolated.

18:31 Duffy reports Chem Lab will go to E16 St. to check employee and vehicle # 23298. D.E.P. has also been notified and is responding to 236 e 118 st.

18:35 GDS Manager Bavuso updated.

19:10 Operating Supervisor Massari on location reports DEP Jacob on location, has found mercury on mat outside door in hallway. ERT & DEP in apt #9 checking same.

19:16 Massari reports to Callahan he has been informed by ERT that if Con Ed employee told consumer to remove gauge, then Con Ed has to cleanup apt.

Tenant reports through translator (Marge Santiago) that Con Ed employee advised tenant to remove gauge and vacuum up mercury. 19:25 ERT Avery Tom informs Callahan that ConEd has to clean up apt. and replace vacuum. 19:30 Callahan calls cleanup vendor, Clean Ventures, no response, will call back. 19:35 ERT Tom wants Environmental manager notified. Mr. Fawzy, DEP, arrives on location. 19:40 Mark from Clean Ventures called, will have supervisor call back.

Massari reports as per ERT spill was over 1 oz and this is a Con Ed spill. 19:45 Callahan notifies CIG that it is a Con Ed spill. 19:47 Callahan updates Bavuso. 19:55 Callahan notifies and updates Frank Ciminiello, General Manager of MGO. 20:00 DEP chemist, Wai Man Wong, takes samples in apt. 9, results in 0.1 hg milligrams/m3 (pel level). 20:05 Callahan notifies MGO Environmental Manager Lonseth. 20:06 Poiribr of Chem Lab reports negative readings on mechanic McDonalds clothes and work boots. 20:10 Poiribr reports Con Ed vehicle # 23298 is clear of mercury. 20:15 Callahan notifies Manhattan Customer Service Environmental Manager Radkte. 20:16 Massari reports DEP is requesting to put occupants of apt #9 in hotel for night. Okayed by Ciminiello. 20:18 Clean Ventures dispatcher Jesse says crew will be dispatched from Elizabeth, NJ and E.T.A. will be about 1 − 1.5 hrs. 20:28 Duffy (IH) calls to confirm Chemical Lab negative mercury readings on mechanic. 20:35 Callahan notifies John Donuhue of Law. 20:41 ERT Avery leaves location. Translator Marge Santiago repeats that tenant under advisement from CE mechanic mcDonald removed first fitting of gauge and mechanic removed the rest. She states mechanic told tenant to wipe up the spill with a rag and vacuum up the rest. 20:55 Callahan left message with Court Monitor explaining what took place at 236 E 118 St. 21:10 Tony Pizarro from Public Affairs called and enroute. 21:42 ERT Bernice Jones calls for status of hootel accommodations for DEP.

21:43 Nieves from Health Dept on location. Fawzy departs. 21:58 P.A. Pizarro on location. 22:14 Janet Fox (IH) calls MCC (OGS McTague) on status of hotel accommodation for tenants. 22:20 Lonseth arrives on location. 22:26 Pizarro will take tenants to 250 w 77 St. (Hotel Belleclare). 22:40 Clean Ventures arrives on location (Jackson / Rushing). 23:16 Pizarro reports to McTague occupants of apartment are at hotel and have been fed. Husband requests to be driven back to 236 e 118 St. after he has bathed.

23:45 Bernice Jones on location. July 2, 1997 02:03 Clean Ventures cleanup complete. DEP samples clear .Apartment accessible

Two 55 gallon drums containing Mercury Waste taken to 110 St. hazardous Waste storage area. Pizarro took Mr. Mercado back to hotel. entered by mctague 77472

02/10/2003 12:13 − C. McCallion reviewed incident description and updated status to closed pending final review.

Map Identification Number 110 **213778; 222 E 123 ST** **Spill Number: 0814485** **Close Date: 09/30/2008**
222 E 123 ST NEW YORK, NY TT−Id: 520A−0248−748

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1666 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: 222 E 123RD ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	DMPOKRZY	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/22/2008		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	4.00	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 111 **ROADWAY** **Spill Number: 0800328** **Close Date: 04/09/2008**
MADISON AVE/EAST 113 ST MAHATTHAN, NY TT−Id: 520A−0218−306

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (5)
Approximate distance from property: 1691 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 113TH ST
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Spiller: UNKNOWN
Spiller Phone:
Notifier Type: Fire Department
Notifier Name:
Notifier Phone:
Caller Name:
Caller Agency:
Caller Phone:
DEC Investigator: vszhune
Contact for more spill info: FIREFIGHTER HANSEN
Contact Person Phone: (347) 203−6886

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/08/2008		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN NON−PETRO/NON−HAZ MATERIAL	OTHER	5.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

UN # 3139, sodium nitrate. Cargo handler is Dacar industries, Transport company New england motor frieight. Unsecured load. shifted drum leaked. Drum was repacked, spill was contained to blacktop, speedi dri used for cleanup.

DEC Investigator Remarks:

04/09/08−Zhune spoke to Hassen, FF (347) 203−6886. he said It's all cleaned up. Case closed

Map Identification Number 112 **SPILL NUMBER 0206541** **Spill Number: 0206541** **Close Date: 09/25/2002**
79 E 125TH ST MANHATTAN, NY TT−Id: 520A−0091−355

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1693 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	TANK TRUCK	Spiller:	CALLER − T AND S TRUCKING	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	DRIVER	Notifier Phone:	
Caller Name:	FLORENCE HANLEY	Caller Agency:	T AND S TRUCKING	Caller Phone:	(718) 499−2900
DEC Investigator:	TJDEMEO	Contact for more spill info:	FLORENCE HANLEY	Contact Person Phone:	(718) 499−2900

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/24/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	5.00	GALLONS	5.00	GALLONS	SOIL

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/25/02 TJD Overfill of tank caused spill. All impacts to concrete from vent pipe. Spill cleaned by Castle Oil personnel using absorbents.

7/24− AL FLASHNER − OVERFILL − 5−6 GAL IN THE STREET − CLEANED USING SPEEDY DRY − CASTLE FUEL OIL SWEPT SPEEDY − 800−734−8955− ROB

Map Identification Number 113 **BROWNSTONE HOUSE** **Spill Number: 0701787** **Close Date: 03/10/2008**
12 WEST 121 STREET NEW YORK, NY TT−Id: 520A−0090−299

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1698 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: 12 W 121ST ST
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	TIM BUNYAN − SUPER FUEL CORP	Spiller Phone:	(718) 993−4747
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	rmpiper	Contact for more spill info:	CESAR GARCIA	Contact Person Phone:	(212) 689−4520

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/14/2007		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	34.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

DELIVERED TO WRONG ADDRESS AND OILCOMPANY IN PROCESS OF CLEANING UP

DEC Investigator Remarks:

Tim Bunyan manager of oil company. Homeowner: Mr. Waterston home#212−996−8425 cell#310−770−8453 Miss delivery − House switched to gas (prior owner?)and never closed fill port. Cleanup is underway. 5/18/2007 − Sangesland spoke to Mr Bunyan with Super Fuel. He says his driver hooked up to the wrong address and started pumping oil. After 34 gallons was pumped, driver didn't hear a whistle and shutdown delivery. Homeowner came outside saying his house smelled of oil. Oil company has been doing the cleanup work on their own. They seem to be using speedie dry and lemon scent? Unknown quality of remediation work. Homeowner seems most concerned about an area under the staircase where oil has been drawing up from under the slab Also small children live in the house. 5/21/07− DEC Piper responded to site. Spill was on new concrete floor w/ sealant. There is some staining and slight odors. Super Fuel was instructed to epoxy paint floor and clean office area. 5/30/07− Spill was to solid concrete floor. Floor will be sealed. No threat to Env. Closed.

James had called back and was concerned about an odor issue. Piper inspected site along with Super Fuel. Under the staircase and behind a wall there was a small amount of soil exposed that was epoxied over that had strong odors. Piper instructed Bunyon to dig out this area and reseal. Spill reopened. 10/25/07− DEC Piper inspected site and okayed new concrete work. A five gallon bucket of soil was removed from the area. When I was leaving I noticed an area in front of the stairs that had porous areas. I instructed Bunyon to dig out this area and remove any cont' soils. Concrete patch and epoxy seal. Once this is done, then can close. 3/10/08− Case closed.

Map Identification Number 114 **MH39246** **Spill Number: 9907360** **Close Date: 02/03/2004**
E 125TH ST & LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0091−061

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1710 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / LEXINGTON AV
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON EDISON	Spiller Phone:	(212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	MR. CROWE	Notifier Phone:	
Caller Name:	FRANK MASSERIA	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	COMENALE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/19/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	1.00	GALLONS	SOIL

Caller Remarks:

MANHOLE 39246. 1/2 GALLON OF UNKNOWN OIL ON 25 GALLONS OF WATER. CONTAINED WITHIN MANHOLE. SAMPLES TAKEN. CLEAN UP PENDING TEST RESULTS. CON EDISON REFERENCE NUMBER 127900.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 115 **SPILL NUMBER 9905454** **Spill Number: 9905454** **Close Date: 08/06/1999**
125TH ST & LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0093−051

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1710 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / LEXINGTON AV
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON EDISON	Spiller Phone:	(212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	TOM RUSSO	Notifier Phone:	
Caller Name:	RICHARD ROACH	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	CAENGELH	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/05/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	1.00	GALLONS	SOIL

Caller Remarks:

MANHOLE 39242. ONE PINT ON 200 GALLONS OF WATER. SAMPLES TAKEN. CLEAN UP PENDING RESULTS. CON EDISON REFERENCE NUMBER 127062.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT con ed e2mis notes:

1 pint of an unknown oil mixed with approx 200 gallons of water. Spill did not enter waterways or sewers , no visual movement, no smoke, no fire, no visable cracks, unable to determine if there is a sump, no sewer connections as per conduit plates.

Determined that there is no oil present and only water is in the structure.

Map Identification Number 116 **MANHOLE 39242** **Spill Number: 9809077** **Close Date: 11/14/2003**
125TH ST /LEXINGTON AVE MANHATTAN, NY TT−Id: 520A−0092−969

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1710 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / LEXINGTON AV
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	DENNIS ROMANO	Notifier Phone:	(212) 338−3352
Caller Name:	RICHARD ROACH	Caller Agency:	CON ED	Caller Phone:	(212) 580−6764
DEC Investigator:	CAENGELH	Contact for more spill info:	RICHARD ROACH	Contact Person Phone:	(212) 580−6764

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/21/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	5.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

cleanup pending lab results con ed #120667

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis 120667

10/21/98 01:40 HEYMACH REPORTS: WORKING ON SCH FDR−3M67 IN M−39242 S/E/C E.125 ST. & LEXINGTON AVE. FOUND APPROX. 5 GALS OF UNKNOWN OIL ON APPROX. 100 GALS OF WATER. OIL IS CONTAINED TO THE MANHOLE DIDN'T ENTER ANY WATERWAYS OR SEWER SYSTEMS. UNABLE TO DETERMINE IF THIER IS A SUMP PIT. HAVE NO VISIBLE CRACKS IN STRUCTURE. TOOK SAMPLE HUNG SIGN # 17864

CORRECTION MADE TO REPORT RESPONSIBLE PARTY IS UNDERGROUND NORTH.

10/21/98 1025 HRS LAB RESULTS OF ANALYSIS 98−11338 @0906 HRS: PCB<1 PPM; AROCLOR 1254 LOGGER JPH 74031

10−22−98 10:35 Cleanup complete on 10−21−98 at 1530 hours, supervised by R.Velasquez 27188. 200 gallons oily water removed via tanker, 2−55 gallon drums hazardous waste generated. EPA# NYP004019790. Tag 17864 removed. Crew: J.Hinojosa 16383, L.Morales 74700, J.Burgos. R.Calderon 19847.

Map Identification Number 117 **218014; E 125 ST AND LEXINGTON AVE** **Spill Number: 0914388** **Close Date: 09/29/2009**
E 125 ST AND LEXINGTON AVE MANHATTAN, NY TT−Id: 520A−0248−709

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1710 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / LEXINGTON AVE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: DMPOKRZY
Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/14/2009		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 118 **2ND AVE SUBWAY −NYCT** **Spill Number: 0300354** **Close Date: 08/26/2005**
LEXINGTON & 125TH ST HARLEM, NY TT−Id: 520A−0093−380

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1710 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / LEXINGTON AV
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name: JERRY SWAIN
DEC Investigator: MCTIBBE
Spiller:
Notifier Name: JERRY SWAIN
Caller Agency: METCAF AND EDDY
Contact for more spill info:
Spiller Phone:
Notifier Phone: (347) 865−2659
Caller Phone: (347) 865−2659
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/10/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

found historical spill during test boring

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE This spill is related to the NYCT−2nd Avenue Project. So spill

report was passed on to Mark for follow−up action.

E.R.

08/26/05: Elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil sampling showed only minor hits of metals and a few SVOCs constituents.

Map Identification Number 119 **MANHOLE 39163** **Spill Number: 9808710** **Close Date: 11/04/2003**
EAST SIDE OF LEXINGTON AV NEW YORK, NY TT−Id: 520A−0101−504

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 1712 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Affected Persons
Caller Name: ERNIE ROWLAND
DEC Investigator: CAENGELH

Spiller: UNKNOWN
Notifier Name: SAME
Caller Agency: CON EDISON
Contact for more spill info: ERNIE ROWLAND

Spiller Phone:
Notifier Phone:
Caller Phone: (212) 580−6763
Contact Person Phone: (212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/13/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

they have a unknown oil spill in the manhole spill will be cleaned up. manhole is 277 feet north of east 112th street no contact with water ways or sewers ref con ed 120496

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT E2MIS 120496

10/13/98 17:08 o.s m.davis(80932) reports in m39163 e/s lexington ave 277’ n/o e.112th st.(on the walk) found 1 gallon of unknown oil ... contained no release.. no Mentry into sewer or waterways. sample taken and tag#10536 installed..found while doing dead work on fdr 3m67.. no sump running,no cracks observed,no sewer connection..... cleanup to commence when crew returns from astoria after dropping off sample

If this is a Con Edison manhole it contains electrical cable and splices. Many manholes have a sealed sump in the floor which is used to allow runoff when pumping the structure. A hose is place in this sump and water on the floor will flow into the sump allowing the floor to be cleaned. If cleaned prior to analysis of the fluid, the structure will be cleaned as >50 PPM and all liquid and waste will be manifested accordingly. The structure will be double washed with a degreaser, i.e. Slix. All cleaning material and PPE will also be treated as >50. If any sludge is found within a manhole it is treated as lead contaminated and manifested accordingly. The spill identification tag will remain secured to the structure until the analysis is completed and if <500 PPM the signage will be removed. If the analysis is >499 PPM, a grid will be prepared for wipe testing the area. Until the analysis of the wipes are proven to be <10ugs/100cme2 all additional waste produced from the structure will be treated as the original analysis. If this spill occurred in a transformer vault containing a sump pump and there was a possible release, the drainpipe trap will be dismantled to determine if oil was released. Sludge found in a vault, through historical analysis, has been determined not to contain lead.

10/13/98 17:50 cig(roland) advised..... pm58101

10/14/98 O.S. (UG) T. Timmons #05198 reports clean up complete in MH−39163 E/S Lexington Ave 277’ N/O E. 112 St. on 10/14/98 @ 05:45 hrs. Treated wastestream as >50 ppm PCB No Water found or removed from structure Generated 3 drums solid debris and absorbant pads 3 drums taken to Chem Waste via Corporate Transportation EPA ID# NYP004019121 Spill Tag #10536 left in place

pending lab analysis Crews: O.S. T. Timmons #05198 M. Rajacic #41976, R. Rodenheiser #11414, J.Rosati #82013

Removed Oil stain from structure using slix and absorbant pads

10/14/98 21:33 Received lab results. Lab sequence # 98−10996 AROCLOR − 1254, PCB − 4 PPM

10−16−98 Tag removed 10−015−98 at 0800 by J.Hinojosa 16383.

Map Identification Number 120 **DEMOLISHED BUILDING** **Spill Number: 0407102** **Close Date: 12/13/2004**
2000−2002 5TH AVE NEW YORK, NY TT−Id: 520A−0093−373

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1734 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	MIKE VOGUEL − DEMOLISHED BUILDING	Spiller Phone:	(516) 945−4736
Notifier Type:	Other	Notifier Name:	MATT BOECKEL	Notifier Phone:	(631) 851−1600 ext. 2
Caller Name:	MATT BOECKEL	Caller Agency:	G C I ENVIRONMENTAL	Caller Phone:	(631) 851−1600 ext. 2
DEC Investigator:	TJDEMEO	Contact for more spill info:	MIKE VOGUEL	Contact Person Phone:	(516) 945−4736

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/27/2004		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	GROUNDWATER

Caller Remarks:

HIGH LEVEL HYDRO CARBONS IN THE END POINT SAMPLES:

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/29/2004 Sangesland left a phone message for Matt at GCI Envir. Summary of DEC requirements for a report with endpoints etc. If he has any further questions asked him to call Sangesland

10/18/04 TJD Matt Boekel (GCI Environmental) returned call to NYSDEC regarding questions concerning closure report submitted 9/14/04. During DEC review of report it was identified that composite sampling of tank grave was performed, not discreet samples as was required for a #2 Oil release. As such, consultant was directed to return to location and collect new samples with a geoprobe. Samples to be analyzed for 8260/8270.

12/13/04 TJD Revised closure report submitted. GCI returned to site and excavated 10 tons of contaminated soils for disposal under manifest. New endpoint(grab) samples were collected. All analytes were below TAGM allowable concentrations. No further action required. Spill closed.

Map Identification Number 121 **CHURCH** **Spill Number: 0601808** **Close Date: 02/14/2012**
33 WEST 115 & 36 115TH STREET NEW YORK, NY TT−Id: 520A−0098−790

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1741 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: 33 W 115TH ST
Revised zip code: 10026

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	PAUL CIMNELLO − CHURCH	Spiller Phone: (845) 452−1658
Notifier Type:	Other	Notifier Name:		Notifier Phone:
Caller Name:		Caller Agency:		Caller Phone:
DEC Investigator:	rmpiper	Contact for more spill info:	PAUL CIMNELLO	Contact Person Phone: (845) 452−1658

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/15/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

DURING CONSTRUCTION ON A BUILDING YOU COULD SEE OIL COMING OUT OF GROUND: IT LOOKS LIKE IT MAY BE COMING FROM THE CHURCH AND TRAVELING UNDERGROUND TO 35 −36_ SOIL HJAS BEEN STOCK PILED AND WILL BE TAKEN AWAY

DEC Investigator Remarks:

DEC Piper responded to site to meet w./ Paul. AS per visit oil appeared out of sw corner of property. Site is contr. site. Church is adjacent to site to the east and is possible source of oil slug. No other report of oil entering site. mailed a second csl.

9/28/06− DEC Piper mailed a second csl.

10/10/06− DEC Piper spoke w. Alan from Island Tank. Alan performed tightness test on system and determined that fill and vent lines were leaking, replaced lines and fill box. They will excavate soil and collect endpoints. They will fax info when completed. 12/18/06− DEC Piper received message from Adam Lee from Eco Stratedgies requesting closure. Piper left message asking for copy of report.

1/11/07− DECP iper spoke w. Vinnie at Island Tank. He will have report shortly.

Map Identification Number 122 **246 E 121 ST** **Spill Number: 9301099** **Close Date: 04/22/1993**
246 E 121ST MANHATTAN, NY TT−Id: 520A−0093−154

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1762 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: 246 E 121ST ST
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ODYSSEY HOUSE INC	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	NAHAM KEDAM	Caller Agency:	CERTIFIED ENG & TEST CO	Caller Phone:	(212) 677−9730
DEC Investigator:	CAMMISA	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/08/1993	04/22/1993	UNKNOWN	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL

Caller Remarks:

BTEX FOUND IN SOIL SAMPLE AT SITE−SOIL TO BE STOCK PILED−& ADDITIONAL SAMPLE TO BE TAKEN TO ADVISE OF POSSIBLE FURTHER REMEDIATION.CALLER TO CONTACT REGION

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 123 **JOHNSON HOUSES −NYCHA** **Spill Number: 0306729** **Close Date: 09/26/2008**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−082

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Responsible Party
Caller Name: MARIO MANDALONE
DEC Investigator: jkkann
Spiller: CALLER − JOHNSON HOUSES
Notifier Name:
Caller Agency: NYC HOUSING
Contact for more spill info: CALLER
Spiller Phone:
Notifier Phone:
Caller Phone: (718) 707−7839
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/25/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

pulled tank and found contamination.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY

11/02/05: This spill transferred from J.Kolleeny to S.Kraszewski.

12/23/05: Remedial investigation in 1993 advanced 7 MWs. FRee product encountered in two of the wells. Two recovery systems were installed to pump out the oil/water from the wells. REcords of prduct thickness are given in tables from Feb 1994 to April 1997. Last two dates record zero product in wells. No MW data since 1997 or reports for that matter. Tanks have been removed. − SK

01/27/06: This spill transferred from S.Kraszewaski to Q.Abidi.

03/31/06: This spill transferred from Q. Abidi to Koon Tang.

09/25/08: J.Kann − Spill reassigned to J.Kann. Tank Closure work (excavation) performed in April 2008. Report dated July 2008 and prepared by PWGC (631−589−6353) indicated endpoints in northwestern wall contain minimal SVOCs above RSCOs. Groundwater sample did not indicate contamination. Regenox was applied to the excavation groundwater and northwestern wall. Structural limitations prevented further excavation along the northwestern wall. Spill closed based on this report. NFA.

Map Identification Number 124 **JOHNSON HOUSES** **Spill Number: 0205660** **Close Date: 03/24/2003**
1809 LEXINGTON AV NYC, NY TT−Id: 520A−0098−081

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	JOE MILLITANO − JOHNSON HOUSES	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	SAME	Notifier Phone:	
Caller Name:	DENNIS RIDDLE	Caller Agency:	CITIZEN	Caller Phone:	(212) 964−1863
DEC Investigator:	JBVOUGHT	Contact for more spill info:	JOE MILLITANO	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/11/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

burried tanks are leaking, caller’s cell number 646−321−3098; caller req call back.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT THIS SPILL IS ACTUALLY AN ONGOING SITUATION INVOLVING A WICKING OIL RECOVERY SYSTEM IN THE BASEMENT SUMP. OIL IN SUMP, POSSIBLY #4 OR #6, IS FROM EARLIER TANK FAILURE(S). NYCHA IS PERFORMING REMEDIATION AS PART OF COMPLIANCE WITH CONSENT ORDER.

ON DAY THIS SPILL WAS REPORTED, DENNIS RIDDLE OF NYFD WAS PERFORMING TANK INSPECTION; HE REFUSED TO PASS THE TANKS BECAUSE OF THIS ONGOING SITUATION. THERE WAS NO SPECIFIC SPILL THAT OCCURRED ON THIS OCCASION. JEFFERY VOUGHT AND LATER STEVEN SACCACIO OF DEC RESPONDED.

REFER TO OPEN SPILLS 9504621 AND 0000572.

OK TO CLOSE THIS ONE. − JK, 5/5/03.

Map Identification Number 125 **JOHNSON HOUSES −NYCHA** **Spill Number: 0000572** **Close Date: 10/25/2005**
1809 LEXINGTON AVE NEW YORK, NY TT−Id: 520A−0098−080

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	ED MALONE − JOHNSON HOUSINGS	Spiller Phone:	(212) 306−3233
Notifier Type:	Tank Tester	Notifier Name:	SEBASTIAN LOREFICE	Notifier Phone:	(212) 306−3229
Caller Name:	SEBASTIAN LOREFICE	Caller Agency:	NEW YORK CITY HOUSING AUT	Caller Phone:	(212) 306−3229
DEC Investigator:	SWKRASZE	Contact for more spill info:	ED MALONE	Contact Person Phone:	(212) 306−3233

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/14/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
2	40000	Horner EZ Check I or II	0.00	FAIL

Caller Remarks:

ISOLATE AND RETEST.

DEC Investigator Remarks:

10/25/05: This spill closed to consolidate with open spill #0306729. S.Kraszewski

Map Identification Number 126 **2ND AVE SUBWAY −NYCT** **Spill Number: 0201534** **Close Date: 08/08/2005**
125TH ST/5TH AVE MANHATTAN, NY TT−Id: 520A−0093−376

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1828 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: W 125TH ST / 5TH AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	HISTORIC SPILL	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	EMPLOYEE	Notifier Phone:	(908) 437−7083
Caller Name:	KEITH RYAN	Caller Agency:	DHA	Caller Phone:	(908) 437−7083
DEC Investigator:	MCTIBBE	Contact for more spill info:	KEITH RYAN	Contact Person Phone:	(908) 437−7083

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/10/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

old spill. doing soil borings and discovered strong oil smell. 58 ppm of pid reading. 10−14 below surface. no call back needed.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

08/08/05: Odor of petroleum and elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil and GW sampling showed only minor hits of metals and a few SVOCs constituents.

Map Identification Number 127 **200 LENOX AVENUE** **Spill Number: 9608875** **Close Date: 11/15/2005**
200 LENOX AVENUE NEW YORK, NY 10027 TT−Id: 520A−0096−043

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1836 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Federal Government
Caller Name: KAREN STEPHENSON
DEC Investigator: JEDURNIN

Spiller: 200 LENNOX AVE
Notifier Name: KAREN STEPHENSON
Caller Agency: DEP
Contact for more spill info:

Spiller Phone:
Notifier Phone: (718) 595−6777
Caller Phone: (718) 595−6777
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/17/1996		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

oil flowing from the house.

DEC Investigator Remarks:

November 15, 2005, Durnin: At the time this spill was reported, this property was owned by the City of New York. It had been vacant for some time. In June/July 2000 the property was sold to Brownstone Partners, LLC. and the building was completely gutted and remodeled. On April 27, 2005 the property was sold to Michael Williams. Based on the recorded restoration activitiy at the site since the time the spill was reported, this site is closed.

Map Identification Number 128 **MANHOLE 55068** **Spill Number: 9906343** **Close Date: 11/12/1999**
120TH ST & 2ND AVE NEW YORK, NY TT−Id: 520A−0101−938

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1866 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 2ND AVE
Revised zip code: 10035

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:		Notifier Phone:	
Caller Name:	RICHARD ROCHE	Caller Agency:	CON ED	Caller Phone:	(212) 580−6764
DEC Investigator:	JHOCONNE	Contact for more spill info:	CALLER	Contact Person Phone:	(212) 580−6764

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/27/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	4.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

caller reports unknown spill in manhole coned #127447. cleanup pending oil sample.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes:

4−gallons of unknown fluids with 4−gallons of water in M55068. Sample taken. 99−09019 AROCLOR none pcb<1.00 ppm, date and tiem the cleanup completed: 9/14/99, 13:00.

Cleanup Procedure: oil and water removed via tanker under 50 ppm, was double wash with bio−genesis solution. Manhole was then flush. Quantity removed from site and type of containers used: 1 plastic bag non−hazardous waste. Transportation to 110 st yard manhattan. Tanker accumulated 35 gal's.

1ppm

Map Identification Number 129 **215193; E 120 ST AND 2ND AVE** **Spill Number: 0913958** **Close Date: 09/16/2009**
E 120 ST AND 2ND AVE NEW YORK, NY TT−Id: 520A−0248−664

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1866 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 2ND AVE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: DMPOKRZY
Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/14/2009		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 130 **MANHOLE #1864** **Spill Number: 0602921** **Close Date: 08/15/2006**
EAST 120 STREET & 2 AVENUE MANHATTAN, NY TT−Id: 520A−0097−539

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1866 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 2ND AVE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Other
Caller Name:
DEC Investigator: GDBREEN
Spiller: UNKNOWN NAME − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK‘
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/15/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	30.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

30 gallons of material on an unknown amount of water in a manhole. Unknown what the cause and source are. Samples will be taken before any clean up will be done. ConEd#200615.

DEC Investigator Remarks:

08/15/06 − See e−docs for Con Ed report detailing cleanup and closure. 200615.

see eDocs.

Map Identification Number 131 **210473; 2ND AVE** **Spill Number: 0890388** **Close Date: 03/27/2008**
2ND AVE , NY TT−Id: 520A−0220−068
E/S 2ND AVE 25‘ N/O E 118 ST

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1867 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: 2ND AVE / E 118TH ST
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: ERT DESK − CON EDISON Spiller Phone:
Notifier Type: Responsible Party Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: Unassigned Contact for more spill info: ERT DESK Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/24/2008		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

M62336 −− E/S 2ND AVE 25’ NNC E 118 ST −− UNKNOWN OIL Closed: Agency Approval Not Required

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 132 **ROAD INTERSECTION** **Spill Number: 0311039** **Close Date: 01/05/2004**
E. 112 TH ST AND PARK AVE MANHATTAN, NY TT−Id: 520A−0093−594

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1869 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: E 112TH ST / PARK AVE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Police Department
Caller Name: SEAN DONOHUE
DEC Investigator: JMKRIMGO
Spiller:
Notifier Name: SEAN DONOHUE
Caller Agency: NY CITY DEP
Contact for more spill info:
Spiller Phone:
Notifier Phone: (212) 689−1520
Caller Phone: (212) 689−1520
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/28/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	SEWER

Caller Remarks:

Unknown amount of oil (unkn type) spilled on street. Possibly went into sewer. Industrial waste investigators enroute.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 01/05/04. DEP has found some oil (1−2 gal) in the catch basin and stains on the road. Spiller is unknown.

Map Identification Number 133 **VAULT 2349** **Spill Number: 0105881** **Close Date: 03/17/2004**
MADISON/E 112TH ST MANHATTAN, NY TT−Id: 520A−0093−593

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1903 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: MADISON AV/E 112TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR PELLIGRINO	Notifier Phone:	(212) 580−6765
Caller Name:	MARK SCHLAGEL	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6765
DEC Investigator:	JHOCONNE	Contact for more spill info:	MARK SCHLAGEL	Contact Person Phone:	(212) 580−6765

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/31/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 gal unk oil in vault...clean up pending deenigerization of transformer...ref # 139242.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis 139242

Robert Grube #11504, Senior Field Oper. F.O.D., reported at 18:13 hrs. that he found at 18:00 hrs. approx. 1 gallon of unknown oil mixed with dirt on the floor of vault V2349. The source and cause of the spill is unknown, however, the cause may be a possible bottom leak of the transformer. There is a sewer connection and a concrete sump but the oil & dirt mix did not migrate towards the sump. Two solid samples from spill taken for PCB and Oil Id. For initial cleanup action, Mr. Grube put absorbent baloneys around the sump and disconnected the sump pump.

The transformer is a G.E. 500 kV unit, serial # 546920. The fluid capacity as per the nameplate is 257 gallons. Prior PCB historical data indicates 47 ppm as per lab sequence #00−0487−001, dated 5/17/2000.

09/01/0 10:00 hrs J. Gnall # 19045 of the I&A reports that he has condemned the transformer in vault−2349 due to a bottom leak. A partial cleanup was done by W. Knipper # 05153, A. Peerrin # 18138. They bagged up 2 bags of dirt. They put down pads & pigs for further releases untill the unit can be replaced.

Lab Sequence #01−08747−001 TOTAL PCB 51 ppm.

UPDATE: 9/06/01 Vito Mannino #56899 reported at 15:10 hrs. that 200 gallons was removed (drained) from the transformer. The capacity of the unit is 230 gallons (it is a 500 kVA unit). Therefore, approx. 30 gallons spilled onto the vault floor. The defective transformer is being removed on Friday, 9/07/01. The new transformer will be installed at a later date.

UPDATE: 9/21/01 Danny Pace #13149, Supervisor−in−Training I&A North, reported at 11:00 hrs. on 9/21/01 that the cleanup of this vault was completed at 18:00 hrs. on 9/20/01.

Map Identification Number 134 **CROSSWALKS** **Spill Number: 1205465** **Close Date: 08/31/2012**
125TH / 3RD AVE MANHATTAN, NY TT−Id: 520A−0277−352

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1956 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	VICTOR − UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SMSANGES	Contact for more spill info:	VICTOR	Contact Person Phone:	(917) 769−4005

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/30/2012		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	7.00	GALLONS	0.00	GALLONS	

Caller Remarks:

Onto pavement

DEC Investigator Remarks:

Minor spill of petroleum at crosswalk. Unknown source. Small amount of sand was put down. No further cleanup

Map Identification Number 135 **SPILL NUMBER 9809080** **Spill Number: 9809080** **Close Date: 11/14/2003**
E 112 ST & LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0092−970

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1972 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 112TH ST / LEXINGTON AV
Revised zip code: 10029

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:		Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	DENNIS ROMANO	Notifier Phone:	(212) 338−3352
Caller Name:	RICHARD ROACHE	Caller Agency:	CON ED	Caller Phone:	(212) 580−6764
DEC Investigator:	CAENGELH	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/21/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	10.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CONTAINED IN MANHOLE #39156 − 120670 CON ED #

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis 120670

10/21/98 03:59 HEYMACK (FOD) REPORTS: WORKING ON SCHEDULE FDR−3M67 IN M−39156 N/E/C E.112 ST. & LEXINGTON AVE. FOUND APPROX. 10 GALS OF AN UNKNOWN FLUID ON APPROX. 250 GALS OF WATER. FLUID IS CONTAINED TO THE MANHOLE DIDN'T ENTER ANY WATERWAYS OR SEWER SYSTEMS. NO VISIBLE SUMP PIT. NO VISIBLE CRACKS IN MANHOLE. TOOK SAMPLE AND HUNG SIGN # 17863

10/21/98 04:22 C.I.G. ROACH NOTIFIED.

Analysis Received SA98−11340 = No Aroclor / PCB <1.0 PPM .. 10/21/98 .. roz

10−22−98 10:20 Cleanup complete 10−21−98 at 1800 hours, supervised by R.Veasquez 27188. 500 gallons water removed via tanker, mh was then double washed. 1−plastic bag non hazardous waste generated. Tag 17863 removed. Crew: J.Burgos 07271, A.Pizarro 14971, J.Pelzer 06470 and R.Calderon 19847.

Map Identification Number 136 **MANHOLE 39156** **Spill Number: 9808280** **Close Date: 11/04/2003**
E 112TH ST/LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0090−974

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1972 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	ROMANO	Notifier Phone:	
Caller Name:	MIKE CESARE	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	CAENGELH	Contact for more spill info:	MIKE CESARE	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/05/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	5.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FOUND ON WATER IN THE MANHOLE. 50−499 PPM.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT General Info:

Feeder 3M67, 700 Gals of water

How spill was discovered:

Crew was doing work on the above mentioned feeder.

Containment:

ConEd claims containment.

Oil containing equipment in manhole:

Information was unavailable at this time.

Cleanup Plan:

Sample already taken. Cleanup pending sample results −spsn

E2MIS 120323

10/05/98 17:00 J.BYRNES (UG) REPORTS: WHILE DOING DEAD WORK ON FDR−3M67 IN M−39156 N/E/C E.112 ST & LEXINGTON AVE. FOUND APPROX. 5 GLS OF UNKNOWN OIL ON APPROX. 700 GLS OF WATER. OIL IS CONTAINED TO THE MANHOLE. DIDN'T ENTER ANY WATERWAYS OR SEWER SYSTEMS. TOOK SAMPLE AND HUNG SIGN # 10611. UNABLE TO DETERMINE IF THERE ARE ANY CRACKS ON THE WALLS OF MANHOLE.

10/05/98 17:30 HRS.CIG M.CESARE #55121 NOTIFIED D.ROMANO.

10/08/98 OS (UG) J. Byrnes #62353 reports clean up in M39156 NEC Lexington Ave & E112 St was started on 10/05/98 @ 16:00 hrs. Treated Wastestream >50 ppm PCB Removed 700 gals. Oil/Water to >50 tanker Crews began removing sediment and debris. Environmental Detailed Incident Report Crews: J. Hinojosa # 16383, L. Morales # 74700, J. Rontondi #11602 ** This job was incomplete and relieved @ 23:00 hrs by O.S. (UG) J. Sorrenti #09296. Sorrenti reports his crews continued washing and removing debris Crews: M. Melendez # 11285, J. Quinn # 50628, R. Hill #14536 This job was incomplete and relieved 10/06/98 @ 07:00 hrs

by O.S. J. Mccabe.

10−9−98 14:25 Cleanup completed on 10−6−98 at 1330 hours, supervised by J.McCabe 00305. Total of 1250 gallons oily water removed via tanker, 11 55−gal drums hazardous waste generated. EPA#NYP004018560. CrewJ.Pelzer 06470, A.Pizarro 14791, M.Brotko 10504 aand R.Calderon 19847. Tag 10611 removed on 10−9−98 at 1300 hours by P.Rubino 69511. SA98−10700.

Map Identification Number 137 **219438; LEXINGTON AVE AND 112TH ST** **Spill Number: 0914652** **Close Date: 12/04/2009**
LEXINGTON AVE AND 112TH ST MANHATTAN, NY TT−Id: 520A−0249−497

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1972 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: LEXINGTON AVE / E 112TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	DMPOKRZY	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/01/2009		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 138 **LEXINGTON AVE** **Spill Number: 0800725** **Close Date: 04/25/2008**
LEXINGTON AVE/EAST 112 ST MANHATTAN, NY TT−Id: 520A−0214−905

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1972 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: LEXINGTON AVE / E 112TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	smsanges	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/17/2008		OTHER	NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

Construction crew digging out an oil tank and it is spilling.

DEC Investigator Remarks:

Site visit made. No problems found

Map Identification Number 139 **JEFFERSON HOUSES** **Spill Number: 9706971** **Close Date: 09/24/1997**
2089 3RD AVE MANHATTAN, NY TT−Id: 520A−0100−059

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1999 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	CALLER − NYC HOUSING AUTHORITY	Spiller Phone:	(212) 306−8480
Notifier Type:	Responsible Party	Notifier Name:	EDWARD MALONE	Notifier Phone:	(212) 306−8480
Caller Name:	EDWARD MALONE	Caller Agency:	NYC HOUSING AUTHORITY	Caller Phone:	(212) 306−8480
DEC Investigator:	SACCACIO	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/10/1997		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
MERCURY	HAZARDOUS MATERIAL	−1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FOUND UNDER A SINK

UNK SORCE

WINSON CONTRING INC ENROUTE FOR CLEAN UP

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 140 **BEHIND HOUSES IN AREA OF** **Spill Number: 1306182** **Close Date: 06/04/2014**
56 WEST 124TH ST MANHATTAN, NY TT−Id: 520A−0289−146

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2001 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	HRPATEL	Contact for more spill info:	ILA GUPTA	Contact Person Phone:	(646) 250−2100

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/12/2013		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	0	UNKNOWN	0	UNKNOWN	SOIL, GROUNDWATER

Caller Remarks:

blue substance on ground that is causing rapid corrosion on pipes − unknown where it came from − Need Callback on further guidance

DEC Investigator Remarks:

06/03/14−Hiralkumar Patel. 2:15 PM:− went to site for inspection, but no−one at home. there are row houses and no access to backyard other than through building. 2:24 PM:− left message for Ms. Gupta.

06/04/14−Hiralkumar Patel. discussed with DEC DeMeo. due to nature of complaint, case closed.

Map Identification Number 141 **138 EAST 112TH ST** **Spill Number: 0402850** **Close Date: 08/25/2005**
138 EAST 112TH ST MANHATTAN, NY TT−Id: 520A−0091−526

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2004 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:		Spiller Phone:	
Notifier Type:	Other	Notifier Name:	PATTY BADDING	Notifier Phone:	(908) 604−2291
Caller Name:	PATTY BADDING	Caller Agency:	ENVIRONMENTAL MGMT	Caller Phone:	(908) 604−2291
DEC Investigator:	ADEBONG	Contact for more spill info:	CHARLES SCHWALJE	Contact Person Phone:	(718) 994−2000

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/05/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	GROUNDWATER

Caller Remarks:

Soil tested for contamination.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 6/23/2004 Sangesland spoke with Patty Badding of Environmental Mgmt. (908−604−2291) She says she arrived on the site of the tank pull after the tank had been pulled out by the contractor. Eight soil samples were taken from the pit. At the time they all looked clean and the area was backfilled. Lab results show that 3 of the 8 samples had some hits for some SVOC's.

The area has already had a new cement slab laid down and a new building is under construction on the site.

Ms. Badding will forward a report to DEC showing the soil sample results and request closure for the spill event.

No soil contamination letter was sent. Consultant already was far along in the process and DEC is awaiting a final report.

8/25/05:The Department has recieved final report on this spill, a review of the report indicates that the spill the is no need for remediation.(akwa)

Map Identification Number 142 **NEW CONSTRUCTION** **Spill Number: 9709656** **Close Date: 07/12/2006**
81 WEST 115TH ST MANHATTAN, NY TT−Id: 520A−0092−450

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2004 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	BILL DUNN − CONTINENTAL GENERAL	Spiller Phone:	(201) 589−0832
Notifier Type:	Responsible Party	Notifier Name:	THEODORE BETANCOURT	Notifier Phone:	(212) 828−3148
Caller Name:	THEODORE BETANCOURT	Caller Agency:	CONTINENTAL GENERAL	Caller Phone:	(212) 828−3148
DEC Investigator:	SXLASDIN	Contact for more spill info:	HELEN B ATKINSON	Contact Person Phone:	(212) 366−4500 ext. 2

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/19/1997		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	AIR

Caller Remarks:

upon cutting a hole in the wall to meet the main drain in the street for domestic water−between point a and point b there is

a fuel tank−fumes coming from tank. will cause dec for info on how to remove tank.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE CFDC

Helen B. Atkinson

212−366−4500 ext. 209

12/11/97 − Teddy from Continental General contractors left message that they removed the tank and there was no contamination.
Possible gasoline tank.

7/12/06. no spill reported. close spill.

Map Identification Number 143 **MAN HOLE #55020** **Spill Number: 9906989** **Close Date: 11/23/1999**
116TH ST / 2ND AV MANHATTAN, NY TT−Id: 520A−0100−058

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2016 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: E 116TH ST / 2ND AVE
Revised zip code: 10029

Source of Spill: UNKNOWN
Notifier Type: Affected Persons
Caller Name: FRANK MASSERIA
DEC Investigator: JHOCONNE

Spiller: UNKNOWN − Unknown
Notifier Name: FRANK MASSERIA
Caller Agency: CON EDISON
Contact for more spill info:

Spiller Phone:
Notifier Phone: (212) 580−6763
Caller Phone: (212) 580−6763
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/12/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
WASTEWATER	OTHER	30.00	GALLONS	0.00	GALLONS	SOIL
UNKNOWN PETROLEUM	PETROLEUM	2.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

con ed # 127754

unk type oil on the surface of water in above man hole

sample taken clean up pending lab results

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL con ed e2mis notes:

30 gallons of water and 2 gallons of unknown oil in MH55020.

pcb − 14 ppm, cleanup completed: 9/29/99, 17:45 Oil and water removed via tanker, was double washed with bio−genesis solution, manhole was then flush.

4 bags non−hazardous waste transportation to 110 st, yard manhattan, tanker accumulated 8,885 gal's.

Map Identification Number 144 **SERVICE BOX 55036** **Spill Number: 0011175** **Close Date: 05/30/2001**
2276 2ND AVE MANHATTAN, NY TT−Id: 520A−0100−057

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2016 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR RUSSO	Notifier Phone:	(212) 338−3352
Caller Name:	JIM FOX	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	JIM FOX	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/13/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	5.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

ABOVE MATERIAL DISCOVERED AT ABOVE LOCATION ON TOP OF 25 GALLONS OF WATER. SAMPLE HAS BEEN TAKEN AND CLEANUP PENDING RESULTS. CON ED # 135080. NO CALL BACK REQUESTED.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS REPORT 1−13−01 Approx. 5gals. of unknown oil mixed with approx. 25gals. of water in SB−55036. No sump or sewer connection as per conduit plates. PCb ans oil ID samples taken

LSn 01−00379−001 Analysis indicates the sample is similar to lubricating fluid.

1−16−01 14:07hrs. There was no indication for a PCB analysis on the Chain of Custody form., no analysis was performed. Made arrangements with #9 to take a PCB sample since they were at the service box rsponding to a customer outage ticket.

1−17−01 LSn aroclor none; PCb <1.0ppm <50ppm flush truck ordered.

15:35hrs. Cleanup completed oil and water removed via tanker, high pressure hose used to double wash floor and walls with Bio Gen, SB was then rinsed by flush truck. 1 plastic bag of non hazardous material was generated and transported to E110St. yard to be placed at Industrial waste temporary storage area. Corporate Transporation tanker <50ppm transported 53gals. of oil & water . Tag removed.

Map Identification Number 145 **248 LENOX AVE/MANH** **Spill Number: 9010506** **Close Date: 10/16/1997**
248 LENOX AVENUE NEW YORK CITY, NY TT−Id: 520A−0091−798

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2022 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Other
Caller Name:
DEC Investigator: JAMES
Spiller: CHAS MITCHELL
Notifier Name:
Caller Agency:
Contact for more spill info:
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/29/1990		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 146 **64 E 127TH ST** **Spill Number: 0212478** **Close Date: 10/25/2005**
64 E 127TH ST MANHATTAN, NY TT−Id: 520A−0099−413

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2063 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Other
Caller Name: MICHAEL LACERTOSA
DEC Investigator: rvketani
Spiller: UNKNOWN
Notifier Name: MICHAEL LACERTOSA
Caller Agency: COASTAL COMBUSTION CORP
Contact for more spill info: UNKNOWN
Spiller Phone:
Notifier Phone: (516) 352−5156
Caller Phone: (516) 352−5156
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/18/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

stain on florr next to oil burner

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 3/19/2003 − JZ/DO: Do−work letter sent with a 7 day deadline.

3/24/2003−Vought−Spoke with Herbert Franklyn who is owner of property. Two (250−gallons) AST's on site. Oil line was closed and only one tank in use. Oil leaked from tank onto the floor. Tank that leaked was emptied of oil. Owner used sand and produced approximately 2 5−gallon buckets. NYSDEC will not require manifest due to minor amount of disposal material. NYSDEC still requires site photos and drawing sent to Tipple. Owner will likely replace tank but information not required for spill closure.

4/11/03 MT

Photos indicated that a site visit was necessary. The basement still had sand on an oil stained floor, and the first floor had the destinct odor of oil. The concrete floor in the basement appears to be sound as revealed by scraping it with an ice removal tool. I recommended to the homeowner that the floor be thoroughly cleaned, washed and painted with an epoxy like substance to eliminate the petroleum odors. There was no indication that any subsurface contamination had occured.

10/25/05 − Raphael Ketani. I am closing the case given the very minor nature of the spill.

Map Identification Number 147 **SPILL NUMBER 9811290** **Spill Number: 9811290** **Close Date: 12/15/1998**
36−38 WEST 123RD ST MANHATTAN, NY TT−Id: 520A−0093−394

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2078 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	CUSTOMER	Notifier Phone:	
Caller Name:	GEORGE HAMILTON	Caller Agency:	SKAGGS WALSH	Caller Phone:	(718) 353−7000
DEC Investigator:	SMSANGES	Contact for more spill info:	GEORGE HAMILTON	Contact Person Phone:	(718) 353−7000

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/08/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

CALLER WAS NOTIFIED OF AN OIL SPILL BY THE CUSTOMER − CALLER WILL SEND A REP FROM HIS COMPANY TO INVESTIGATE − ADDITIONAL INFO IS UNKNOWN

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND MISS DELIVERY CROSS REF WITH 9811292 CLEAN UP COMPLETE CLOSED

Map Identification Number 148 **SPILL NUMBER 0308444** **Spill Number: 0308444** **Close Date: 11/13/2003**
W. 116TH ST & LENOX AVE MANHATTAN, NY TT−Id: 520A−0090−819

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2083 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: W. 116TH ST / LENOX AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:		Spiller Phone:	
Notifier Type:	Other	Notifier Name:	KURA	Notifier Phone:	(212) 996−8584
Caller Name:	RACQUEL RIVERA	Caller Agency:	TRAFFIC ENFORCEMENT	Caller Phone:	(212) 996−8584
DEC Investigator:	MXTIPPLE	Contact for more spill info:	RACQUEL RIVERA	Contact Person Phone:	(212) 996−8584

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/10/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
COOKING GREASE	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

cleanup in progress

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE

Map Identification Number 149 **IMPACTED SOIL FOUND IN EXCAVATION** **Spill Number: 0708523** **Close Date: 02/20/2008**
PARK AVE & EAST 127 STREET MANHATTAN, NY TT−Id: 520A−0211−212

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2133 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: PARK AVE / E 127TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERTSDESK − CON EDISON	Spiller Phone:	(212) 580−8383
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	gdbreen	Contact for more spill info:	ERTSDESK	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/05/2007		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

FOUND AN ODOR AND DISCOLORED SOIL; CONED# 208789

DEC Investigator Remarks:

02/20/08 − See eDocs for Con Ed report detailing cleanup and closure. 208789. see eDocs

Map Identification Number 150 **STREET SPILL** **Spill Number: 0513230** **Close Date: 02/17/2006**
SECOND AVE & E 123 ST MANHATTAN, NY TT−Id: 520A−0096−106

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2144 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: 2ND AVE / E 123RD ST
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ABOVE − PROJECTS	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:	BARTON FENDELMAN	Notifier Phone:	(347) 203−6008
Caller Name:	BARTON FENDELMAN	Caller Agency:	CITY OF NY FD	Caller Phone:	(347) 203−6008
DEC Investigator:	rmpiper	Contact for more spill info:	ABOVE	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/16/2006		UNKNOWN	NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	200.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

SPILL HAS GONE INTO STORM DRAIN − CAUSE STILL TO BE DETERMINED − FD ON SCENE

DEC Investigator Remarks:

Piper notified DEP FD said it was contained No DEC reponse was required

Map Identification Number 151 **217860; 2 AVE AND 115TH ST** **Spill Number: 0914359** **Close Date: 08/11/2009**
2 AVE AND 115TH ST MANHATTAN, NY TT−Id: 520A−0249−429

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2150 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: 2ND AVE / E 115TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	DMPOKRZY	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/04/2009		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	2.00	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 152 **208234; NWC E 115 ST 2ND AV** **Spill Number: 0890451** **Close Date: 08/16/2010**
NWC E 115 ST 2ND AV , NY TT−Id: 520A−0220−207
NWC E 115 ST A2ND AV

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2150 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: EAST 115TH ST / 2ND AV
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: JMZALEWS
Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/26/2007		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

M55215 − NWC E 115 ST 2ND AV −− UNKNOWN OIL Pending: Operational Necessity for Business Units Other Than S&TO or SSO

DEC Investigator Remarks:

08/16/2010 See eDocs for Con Ed report detailing cleanup and closure DMP

Map Identification Number 153 **VAULT 5975** **Spill Number: 0205599** **Close Date: 09/29/2004**
EAST 115TH ST AT 2ND AV NEW YORK, NY TT−Id: 520A−0090−784

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2150 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: EAST 115TH ST / 2ND AV
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:	WALLY LEE	Notifier Phone:	
Caller Name:	SEAN MCKEEVER	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	KMFOLEY	Contact for more spill info:	SEAN MCKEEVER	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/28/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SEWER

Caller Remarks:

OIL AND WATER IN SUMP − 1 1/2 QUARTS − CON ED NUMER 144769

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #144769:

@11:10 hrs V.Fontanez #05121 reported while inspecting vs5975 for a water leak with DEP found 1.5 qt of unknown oil and 5 gal of water. Took two sample one for pcb and one for oil id.

8/28/02 14:50 I&A reported they took apart the piping & there was no evidence of oil. The crew then put the piping back together & recapped it with a 2 plug. They also left the sump pump unplugged.

Lab Sequence Number: 02−08043−001 PCB 12 ppm.

1−Cleanup was done on 9/27/02 and work was completed @14:30pm. 2−600 gallons of water was removed 3−Approximately 2 yards of debris was also removed 4−The Vault was double washed 5−5 gallons of Citri Kleen was used to wash the vault

Map Identification Number 154 **BETWEEN LENOX AND 7TH AVE** **Spill Number: 0908562** **Close Date: 11/03/2009**
109 WEST 119TH ST NEW YORK, NY TT−Id: 520A−0233−951

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2160 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Local Agency
Caller Name:
DEC Investigator: HRAHMED

Spiller: MARTINE MUZAC − UNKNOWN
Notifier Name:
Caller Agency:
Contact for more spill info: MARTINE MUZAC

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (646) 675−7005

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/29/2009		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	

Caller Remarks:

Caller stated that there was some kind of oil that was leaking from an underground oil pipe. Industrial Waste crew went to scene to inspect. It is unknown at this time what is being done for clean up. No other information at this time.

DEC Investigator Remarks:

10/30/09−Hiralkumar Patel. spoke with Ms. Muzac (at 10:15 PM on 10/29/09), property owner. Ms. Muzac mentioned that there is a dark oil stain on sidewalk nearby fill port and suspect leak from fill line due to vibrations from ConEd work on street. no odors inside buildign. DEC Hasan will visit site this morning.

10/30/09−HRAHMED−Responded to the site today at 11:30AM. Noticed dark oil stain on the sidewalk around the fillport. Noticed to oil stain near the vent line. Called Ms. muzac and left a message to call her oil company to powerwash the sidewalk. It was a one time release on concreted sidewalk. Took some pintures and uploaded to eDocs.

This case is closed.

Map Identification Number 155 **BWTEEEN 2ND & 3RD AV −NYCT** **Spill Number: 0210753** **Close Date: 08/26/2005**
125TH ST 2ND & 3RD AVE MANHATTAN, NY TT−Id: 520A−0101−857

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2176 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 125TH ST
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Other
Caller Name: GARY GUTSHTEWN
DEC Investigator: MCTIBBE

Spiller:
Notifier Name: CAROL DOWNEY
Caller Agency: DHA
Contact for more spill info: CAROLINE DOWNEY

Spiller Phone:
Notifier Phone: (212) 510−2100
Caller Phone: (212) 510−2100
Contact Person Phone: (212) 510−2100

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/27/2003		UNKNOWN	NO	NO

NO MATERIAL INFORMATION GIVEN FOR THIS SPILL

Caller Remarks:

part of a second avenue subway station − soil borings − historical spill − encountered elevated pid levels

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

08/26/05: Elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil and GW sampling showed only minor hits of metals and a few SVOCs constituents.

Map Identification Number 156 **MANHOLE 45805** **Spill Number: 9814395** **Close Date: 03/12/1999**
EAST 126TH ST / 3RD AVE MANHATTAN, NY TT−Id: 520A−0091−007

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2189 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	BYLACK	Notifier Phone:	
Caller Name:	FRANK MASSERIA	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/02/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CASE #123387 − 1 PINT SPILLED − SAMPLE TAKEN

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes:

Found 1 pt of cable oil in mh,

No water in manhole, no cracks, no smoke , no sewer and no sewer connection took sample for pcb and hung sign. cleanup completed on 3−3−99 at 1500 hrs, supervised by M.Davis, 5− 55 gallon drums debris removed. Treated as 50−499 no lab results available.
PCB 4 ppm.

Map Identification Number 157 **SITE F/NEW CONSTRUCTION** **Spill Number: 1008098** **Close Date: 10/04/2011**
169 EAST 111 ST MANHATTAN, NY TT−Id: 520A−0258−204

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2216 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 169 E 111TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SFRAHMAN	Contact for more spill info:	KEVIN KLEAKA	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/02/2010		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

contamination found during excavation

DEC Investigator Remarks:

12/14/10 Impact Environmental performed a site investigation.The site is currently in a construction of a 6 story residencial building with a basement.The construction activities included:foundation excavation for the basement,construction of a concrete mat slab and foundation walls.Subsurface sampling was conducted within a small excavation that was intended for installation of an injector pit.

10/04/11 Impact Environmental prepared a Engineering Control Completion Report. The Engineering Control activities included: Installation of a SSDS and installation of a water proof vapor barrier membrane in the ejector pit area of the building to limit post construction exposure to potential residual soil/ground water contamination.Report with pictures in edocs.(sr)

Map Identification Number 158 **ROADWAY SURFACE** **Spill Number: 1004567** **Close Date: 07/23/2010**
EAST 120TH STREET BW 1ST AND 2ND AVE MANHATTAN, NY TT−Id: 520A−0253−046

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2222 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	Unknown Vehicle	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RMPIPER	Contact for more spill info:	NYC DEP HAZMAT	Contact Person Phone:	

Category: Investigation indicates there was no spill.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/22/2010		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
TRANSMISSION FLUID	PETROLEUM	2.00	GALLONS	0.00	GALLONS	

Caller Remarks:

SPILL TO ROADWAY, CLEANUP PENDING.

DEC Investigator Remarks:

DEC Piper spoke with DEP Wilson. Transmission fluid was pooled at curbside and a few cars drove through it. Sanitation called to sand area. Small spill to roadway. No sewers affected. Closed.

Map Identification Number 159 **121 WEST 119TH STREET** **Spill Number: 0605155** **Close Date: 08/08/2006**
121 WEST 119TH STREET MANHATTAN, NY TT−Id: 520A−0090−520

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2276 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:		Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SMSANGES	Contact for more spill info:	HAZMAT	Contact Person Phone:	(718) 595−4646

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/03/2006		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

DURING DEMOLITION SPILLING OIL: ON GROUND AND HAZMAT CREW ENROUTE

DEC Investigator Remarks:

Case was forwarded to ECO Conway who was on patrol in Manhattan. He inspected the site and found no problem. 8/8/2006 Sangesland called DEP HAZMAT to check on the site. DEP notes say the contractors were moving oil from one tank into another tank. Based on ECO Conway's inspection, the spill is now closed

Map Identification Number 160 **2005 MADISON AV & 128TH** **Spill Number: 9005731** **Close Date: 02/04/1998**
2005 MADISON AV NEW YORK CITY, NY TT−Id: 520A−0095−067

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2286 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	NYC BOARD OF EDUCATION	Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	KSTANG	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/22/1990		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	2000	GALLONS	0	GALLONS	SOIL

Caller Remarks:

(2) 7.5K TANKS, SPILL IN TANK ROOM, DEC TO INVESTIGATE.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG PROBABLY CLEANED UP.

Map Identification Number 161 **NYS DEPT OF HUMAN RIGHTS** **Spill Number: 9514120** **Close Date: 05/06/1998**
55 WEST 125TH ST MANHATTAN, NY TT−Id: 520A−0099−432

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2311 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN Spiller: Spiller Phone:
Notifier Type: Health Department Notifier Name: NYS BUREAU OF LEASES Notifier Phone: (518) 474−8416
Caller Name: CHARLIE HUDSON Caller Agency: NYS DOH Caller Phone: (518) 458−6405
DEC Investigator: O'DOWD Contact for more spill info: CHRIS NELSON Contact Person Phone: (212) 961−8566

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/05/1996		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CALLER RECEIVED CALL FROM SOMEONE IN ALBANY REGARDING SPILL IN NYC APPARENTLY SPILL IS ON 14TH FLOOR OF THE BLDG − ATTEMPTING TO CLEAN UP WITH PAPER TOWELS

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

POKE TO JOHN BIRE − DHR ON 13TH FLOOR − OIL COMING FROM CEILING. POSSIBLE THAT HEALTHY SYSTEM IS ON 14TH FLOOR − MAY HAVE BEEN LEAKING SINCE 4:30AM − 02/05/96 ODOR IN VENTILATION SYSTEM − NEED RESPONSE CALL BACK JOHN BIRE, NELSON IS CONTACT ON SITE.
SEE K.O'DOWD FILE.

Map Identification Number 162 **SB 20601** **Spill Number: 0012590** **Close Date: 08/16/2001**
WEST 127TH ST/ 5TH AVE MANHATTAN, NY TT−Id: 520A−0090−714

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2313 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	MR PELEGRINO	Notifier Phone:	
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	BILL MURPHY	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/26/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 gal oil on 1 gal water contained in servicebox. clean up pending sample results. con ed 135−698

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

Map Identification Number 163 **SPILL NUMBER 0104362** **Spill Number: 0104362** **Close Date: 09/08/2003**
104 WEST 123RD ST MANHATTAN, NY TT−Id: 520A−0091−245

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2323 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Police Department	Notifier Name:		Notifier Phone:	
Caller Name:	OFFICER MILLIGAN	Caller Agency:	NYC PD	Caller Phone:	(212) 678−1639
DEC Investigator:	MXTIPPLE	Contact for more spill info:	UNKNOWN	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/01/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

CALLER STATES THAT APPROCX 1 MONTH HE HAS SEEN AN OILY TYPE SUBSTANCE LEAKING OUT FROM UNDER THE GARAGE AT ABOVE RESIDENCE. REQ CALLBACK.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 07/25/01 SITE VISIT REVEALED SOME STAINING 0N SIDEWALK, CARS HAD BEEN REPAIRED IN MOSTLY PAVED LOT. 9/8/03 tipple updating//nfa

Map Identification Number 164 **SOUTHSIDE OF −NYCT** **Spill Number: 0210651** **Close Date: 08/26/2005**
EAST 116TH STREET MANHATTAN, NY TT−Id: 520A−0102−378

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2329 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: E 116TH ST
Revised zip code: 10029

Source of Spill:	UNKNOWN	Spiller:	KEITH RYAN − SOUTHSIDE OF	Spiller Phone:	(908) 437−7083
Notifier Type:	Local Agency	Notifier Name:	JERRY SWAIN	Notifier Phone:	(347) 865−2659
Caller Name:	JERRY SWAIN	Caller Agency:	METCAF AND EDDY	Caller Phone:	(347) 865−2659
DEC Investigator:	MCTIBBE	Contact for more spill info:	JERRY SWAIN	Contact Person Phone:	(347) 865−2659

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/23/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

DRILLING FOR 2ND AVENUE SUBWAY AND FOUND A PETROLEUM SMELLING LEAK IN THE 300 BLOCK OF EAST 116 STREET

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

08/26/05: Odor of petroleum and elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil sampling showed only minor hits of metals and a few VOCs & SVOCs constituents.

Map Identification Number 165 **X** **Spill Number: 0312854** **Close Date: 12/16/2005**
52 WEST 126TH STREET NEW YORK, NY TT−Id: 520A−0093−360

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2330 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	TANK TRUCK	Spiller:	UNKOWN TRUCK CO.	Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:	KEITH TAYLOR	Notifier Phone:	(212) 876−6091
Caller Name:	KEITH TAYLOR	Caller Agency:		Caller Phone:	(212) 876−6091
DEC Investigator:	rmpiper	Contact for more spill info:	KEITH TAYLOR	Contact Person Phone:	(212) 876−6091

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/19/2004		OTHER	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	POUNDS	0	POUNDS	SOIL

Caller Remarks:

OIL TRUCK SPILLED OIL ON STREET IN FRONT OF APRTMENT BUILD. SMELL IS VERY STRONG, SOME SPEEDI DRI WAS PLACED DOWN, BUT NOTHING ELES HAS BEEN DONE: CALLED DEP #769459; CALLER HAS TWO ASMATIC CHILDREN AND THEY ARE ALL COMPLAINING OF HEADACHES:

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 4/12/04 − Sawyer − Called Mr. Taylor and left a message. 12/16/05− DEC Piper, small spill to road surface.

Map Identification Number 166 **SPILL NUMBER 0202065** **Spill Number: 0202065** **Close Date: 07/14/2003**
2067 5TH AVE MANHATTAN, NY TT−Id: 520A−0099−419

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2352 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN Spiller: OWNER − 2067 5TH AVE Spiller Phone: (917) 288−5609
Notifier Type: Responsible Party Notifier Name: Notifier Phone:
Caller Name: RAY LARA Caller Agency: PETROLEUM TANK Caller Phone: (718) 624−4842
DEC Investigator: SMSANGES Contact for more spill info: CALLER Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/28/2002		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#6 FUEL OIL	PETROLEUM	10.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OIL ON GROUND FROM UNK SOURCE.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND

Map Identification Number 167 **BASEMENT** **Spill Number: 1010494** **Close Date: 01/14/2011**
271 LENOX AVE MANHATTEN, NY TT−Id: 520A−0258−179

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2354 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING Spiller: ELLA BREWSTER − UNKNOWN Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: HRPATEL Contact for more spill info: ELLA BREWSTER Contact Person Phone: (212) 662−4417

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/08/2011		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	UNKNOWN	0	UNKNOWN	

Caller Remarks:

Oil Line failed vacuum test. No visible oil release

DEC Investigator Remarks:

01/12/11−Hiralkumar Patel. no alternate address. no PBS or other spill record found.

BSB Management, LLC.

property owner c/o Blythe S. Brewster 271 Lenox Ave Manhattan, NY 10027 Ph. (212) 662−4417 email: vbsb.6@juno.com

1:03 PM:− spoke with Pauline at Mr. Brewster's office. she will ask Mr. Brewster to call back.

01/14/11−Hiralkumar Patel. 10:25 AM:− visited site. inspected tank area. the old supply line running aboveground except for about 2 ft below the concrete cover. line was on concrete surface. no spill noticed.

based on observation during the site visit, case closed.

Map Identification Number 168 **LOT NEXT TO AMOCO STATION** **Spill Number: 0411494** **Close Date: 05/04/2005**
249 EAST 125TH ST HARLEM, NY TT−Id: 520A−0091−579

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2373 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	LAB	Notifier Phone:	(908) 789−8900
Caller Name:	MIKE BULLOCK	Caller Agency:	WARREN AND PANZER ENGINEE	Caller Phone:	(212) 922−0077 ext. 2
DEC Investigator:	KMFOLEY	Contact for more spill info:	MIKE BULLOCK	Contact Person Phone:	(212) 922−0077 ext. 2

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/20/2005		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0	GALLONS	0	GALLONS	GROUNDWATER

Caller Remarks:

Lot is adjacent to an Amaco gas station. Warren and Pazner were drilling in the lot and found evidence of a spill. Lab confirmer fresh gasoline in the soil and groundater. Unsure when or who will be doing the clean up.

DEC Investigator Remarks:

1/26/05 Adjacent to Amoco at 255 E 125th St (Spill #9711337). Mike Bullock, Warren & Panzer(212−922−0077), will be sending in analyticals for two Geoprobes completed for potential buyer. He indicated there was no reason to think the gasoline was from any other sources other than the Amoco. No PBS #.

Block 1790/ Lot 20

Notified Amoco's Consultant, B. Fisher of Delta Environmental.

5/4/05 Received analytical results for SB−1, GW−1 and SB−2 on 1/26/05. After review of the results, it was not clear why this spill had been reported. No exceedances were detected in soil or groundwater. Called Mike Bullock of Warren and Panzer on several occasions to try to obtain more information regarding the report. He has not returned my calls. Based upon the results submitted, no further action is warranted.

Map Identification Number 169 **VACANT LOT** **Spill Number: 0708201** **Close Date: 09/22/2008**
346 E. 119TH ST MANHATTAN, NY TT−Id: 520A−0212−633

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2384 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	RUTH ANN RICHERT − VACANT LOT	Spiller Phone:	(917) 902−2641
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	rvketani	Contact for more spill info:	RUTH ANN RICHERT	Contact Person Phone:	(917) 902−2641

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/26/2007		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

DIGGING AND CAME UPON CONTAMINATED SOIL

DEC Investigator Remarks:

Sangesland left a voice message with Martin Wodka at Team Enviro asking for the name and mailing address for the property owner.... Need to send CSL

Ask Mr. Wodka first what work has already been done on the site. Maybe they have already defined the problem and they can move directly to remediation?

10/26/07 − Raphael Ketani. I spoke to Ruthann Richert, the managing partner of the owners, 346 East 119 Street, LLC. She said her company's office is at 36 West 120 Street, apt #1, NY, 10027. She said her phone number is (646) 240−4626 and her cell is (917) 902−2641.

She said that dark soil was found while digging. Soil samples were taken and sent off to the lab for analysis today. She said the digging will continue as soon as Martin Wodka of Team Environmental (845) 692−8124 gets the lined roll−off containers. She added that groundwater is about 13 feet below grade and they plan to go down about 12 feet. Right now, they are encountering rubble consisting of bricks and concrete. I told her that I will be sending out a Contaminated Soil Letter as part of our routine communication. She said that is fine.

The letter went out today.

11/28/07 − Raphael Ketani. I spoke to Ms. Richert. She said that they have removed 250 tons of contaminated soil so far. She added that more contaminated soil will be removed as soon as the underpinning is done. I asked her whether the groundwater will be sampled. She said that RND Services will sample the groundwater. I told her that DEC needs copies of all of the manifests and the groundwater analyticals. She said that she will send me the copies.

The site is located between First and Second avenues.

1/9/08 − Raphael Ketani. I tried to contact Ms. Richert (646) 240−4626 regarding the digging and soil and groundwater sampling at the site. However, I could only leave a message.

1/16/08 − Raphael Ketani. Bob Heyman of R&D Services (845) 348−6355 called me back. He said that progress is being made on the site. It is 25' by 61', essentially the dimensions of a brownstone building. He said his company is just handling the contaminated soil and water removal, nothing else. He said that they sent about 160 tons of soil to Carteret, NJ already and may have a little more in the elevator shaft area (they have to go 8' below the water table). Groundwater is at 13' below grade. He has already collected two truck loads of water. He said he will take a sample of the groundwater when all of the construction is

finished and conditions are settled. I told him to collect another load of groundwater when everything is settled. Then, I said, wait for the water to return and take a groundwater sample. He said he will do this. I asked him whether he can get all of the contaminated soil. He said No as there are structural issues with the foundations of the buildings on either side. I told him to send DEC a letter to that effect and include it in the closure report. He said he will and that pictures and everything will be included in the closure report.

4/9/08 − Raphael Ketani. I spoke to Mr. Heyman. He said that things are at a standstill. They took some more soil out and a couple of loads of water. He said the water looks clean. However, no further work can take place at the site because they have water intrusion problems in the area where the elevator pit is supposed to go. The owners have been through 3 contractors already and nothing is moving. Unless they can get the water out of the area, construction can't take place. Mr. Heyman said that he will send me a spreadsheet with the loads of water collection and soil collection listed.

Mr. Heyman sent me a FAX with a list of the vac truck load pickups and the contaminated soil load pickups.

9/22/08 − Raphael Ketani. Today I received the April 2008 Site Assessment Report (SAR). Two composite soil samples were taken. One sample was completely non−detect and the other had some naphthalene, but it was well below TAGM. Groundwater was not collected as they said it was really from precipitation and runoff. They will install a plastic vapor barrier and a vapor recovery system.

Based upon the information in the SAR and the fact that they were installing the vapor recovery system, and that they will put in a vapor barrier, I am closing the spill case.

Map Identification Number 170 **SPILL NUMBER 0011504** **Spill Number: 0011504** **Close Date: 10/31/2003**

20 WEST 127TH ST MANHATTAN, NY TT−Id: 520A−0099−424

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2387 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:		Notifier Phone:	
Caller Name:	ROZ GRAHM	Caller Agency:	CITIZEN	Caller Phone:	(212) 426−9002
DEC Investigator:	TJDEMEO	Contact for more spill info:	ROZ GRAHM	Contact Person Phone:	(212) 426−9002

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/20/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	AIR

Caller Remarks:

caller is neighbor to the above location. states strong smell of oil from neighboring house.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 10/31/03 TJD Old odor complaint. No recent history.
Spill closed.

Map Identification Number 171 **2365 FIRST AVENUE** **Spill Number: 9310338** **Close Date: 11/24/1993**
2365 FIRST AVENUE MANHATTAN, NY TT−Id: 520A−0096−128

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (2)
Approximate distance from property: 2399 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

Source of Spill: PASSENGER VEHICLE Spiller: CLASIC FUEL OIL Spiller Phone: (718) 384−3712
Notifier Type: Citizen Notifier Name: Notifier Phone:
Caller Name: JOHN SHKRELI Caller Agency: Caller Phone: (212) 289−4810
DEC Investigator: KSTANG Contact for more spill info: Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/24/1993	11/24/1993	OTHER	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FD IS THERE − ALSO POLICE WERE CALLED. CLASIC FUEL IS CLEANING UP. CALLED MR. JOHN SHKRELI @ THE SPILL SITE, AND HE CONFIRMED THE

SPILL CLEAN UP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

Map Identification Number 172 **PRIVATE HOME** **Spill Number: 0709958** **Close Date: 08/20/2008**
12 EAST 128TH ST MANHATTAN, NY TT−Id: 520A−0211−164

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2408 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	GLORIA − MANAGER − SOUTH CAROLINA FUEL	Spiller Phone:	(212) 234−5900
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RMPIPER	Contact for more spill info:	MR. CAREY	Contact Person Phone:	(646) 739−9791

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/14/2007		OTHER	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

THIS WAS AN OVERFILL OF A STORAGE TANK MADE BU ANOTHER OIL COMPANY (NOT STUYVESANT); NO CLEAN UP AT THIS TIME; STUYVESANT APPLYING SPEEDY DRY BUT IS NOT CONDUCTING THE CLEAN UP; HOME OWNER IS MR. HOLLY #718−962−4917; MR. CAREY IS REQUESTING A CALL BACK AS SOON AS POSSIBLE.

DEC Investigator Remarks:

12/18/07−Vought−Duty desk officer. Vought called DEC Piper (off−hours responder) and DEC Piper on−site and awaiting ABC Tank Cleaning to perform cleanup. DEC Piper to send out CSL (if applicable) as per his request.

1/11/07− Donna from aBC called. waiting to collecte soil samples.

8/20/08− DEC Piper− I recieved report from ABC. 19 drums of oil soaked debris in basement was removed along with 5 drums of cont. soil from a 6' x 3' area, recemented, power washed the rest of the floor then epoxy painted. Endpoints revealed minor detections of a few VOCs and SVOCs. Based on work and analytical. This spill is closed. See e−docs if warranted.

Map Identification Number 173 **MAN HOLE #45816** **Spill Number: 9814391** **Close Date: 09/10/2009**
E 127TH ST & 3RD AVE MANHATTAN, NY TT−Id: 520A−0090−165

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2414 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 127TH ST / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR CURTIS	Notifier Phone:	(212) 338−3352
Caller Name:	STEVE CRIBBIN	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	JMKRIMGO	Contact for more spill info:	STEVE CRIBBIN	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/02/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

about 1/2 gal of unknown oil in manhole ref #123382 cleanup after tested

DEC Investigator Remarks:

09/10/09 − See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

Map Identification Number 174 **213284; 3 AVE AND E 127 ST ST** **Spill Number: 0814398** **Close Date: 06/17/2009**
3 AVE AND E 127 ST ST NEW YORK, NY TT−Id: 520A−0249−434

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2414 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: 3RD AVE / E 127TH ST
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: DMPOKRZY
Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK
Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/21/2008		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 175 **CONED MANHOLE #20977** **Spill Number: 0405048** **Close Date: 10/22/2004**
EAST 127/3RD AVE MANHATTAN, NY TT−Id: 520A−0099−402

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2414 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 127TH ST / 3RD AVE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
Notifier Type: Responsible Party
Caller Name: LARRY COSTA
DEC Investigator: SKARAKHA
Spiller: ERT DESK − CONED MANHOLE #20977
Notifier Name: LARRY COSTA
Caller Agency: CON ED
Contact for more spill info: ERT DESK
Spiller Phone: (212) 580−8383
Notifier Phone: (212) 580−6763
Caller Phone: (212) 580−6763
Contact Person Phone: (212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/09/2004		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	UNKNOWN	0	UNKNOWN	SOIL
UNKNOWN PETROLEUM	PETROLEUM	0	POUNDS	0	POUNDS	SOIL

Caller Remarks:

3QUARTS OF UNKNOWN OIL ON 50 GALLONS OF WATER: WAITING FOR SAMPLES BUT MIGHT BE 3RD PARTY SPILL DUE TO A GARAGE LOCATED NEAR BY: NO SEWERS, FIRE,SMOKE, CLEAN UP PENDING TEST RESULTS: CONED # 154777

DEC Investigator Remarks:

e2mis no 154777

Greg Sullivan found approx. 3 quarts of unknown oil and 50 gallons of water. Since the service box is in an active driveway of a vehicle garage he believes that the unknown oil is motor oil. This is a possible third party spill. There is no evidence of release to sewer or waterway. There is no sewer connection, no sump pump. Three liquid samples will be taken from the spill on a priority E basis for PCB, Oil ID and Flashpoint. No initial cleanup action was taken other than placing an absorbent pad down. Cleanup is pending lab results to determine flashpoint.

Lab Sequence Number: 04−06290−001: PCBs < 1 ppm (Insufficient oil for ID)

Lab Sequence Number: 04−06290−002: Flash Point, PMCC > 140 deg F

Update Aug 12,2004 @ 04:00 hrs O.S M.Melendez 11285 U.G Dept reports that clean up complete @ 03:30 hrs And that tanker removed 50 gallons of oil & water mix, no solids,was power washed twice with slix. Yellow tag 18715 removed.

Map Identification Number 176 **MANHOLE 45629** **Spill Number: 0412552** **Close Date: 06/20/2005**
E 111TH ST & 3RD AV MANHATTAN, NY TT−Id: 520A−0090−850

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2418 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 111TH ST / 3RD AV
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:	MR CASALTA	Notifier Phone:	(212) 580−6764
Caller Name:	MARK SCHLAGEL	Caller Agency:	CONED	Caller Phone:	(212) 580−8383
DEC Investigator:	SKARAKHA	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/26/2005		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

1 quart unkn petroleum in 200 gals water − no to five questions − 2 samples were taken − no crews avail for cleanup − ref 157387

DEC Investigator Remarks:

e2mis no 157387

02/26/05 16:10 J.Ohara#03994, of the Emergeny Dept., notified the control center on 02/26/05 at 15:50hrs. to report he found approx. 1 quart of unknown oil and 200 gallons of water in M45629. There was no fire or smoke involved and no sewers or waterways were affected. The source and cause of the spill is unknown at this time. There is oil filled equipment in M45629, the primary and secondary cables. Mr. Ohara did not have a yellow environmental tag with him, the supervisor will bring one out to him. The water is standing with no visible sign of movement. J.Ohara #03994 could not see a sump and does not see any substantial cracks in M45629. There were two samples taken, one for PCB's and one for oil ID. J.Ohara#03994 did not have a chain of custody form with him, the supervisor will bring one out to him. The only initial cleanup action taken was absorbent pads placed on the spill to try and diaper it up. Due to lack of crews, as per Feeder Control, this is being made a new spill.

02/26/05 18:30 J.Ohara#03994, notified the control center on 02/26/05 at 18:00hrs. to say that the yellow environmental tag number is #46964 and the chain of custody number is #EE00923.

2/27 @ 03:50 Lab Sequence Number: 05−01697−001 The presence of oil was not detected in the sample.

Lab Sequence Number: 05−01696−001 PCB Total <1 PPM

Notified ERT, spoke to D Pontecorvo and discussed the finding of the above results and he concurred that we can ordinarily pump out the liquid on the street and flush as regular if needed

2/27 @ 05:20 Persuant to Lab results, the structure has been pumped out and waiting for Vactor to arrive to complete is job.

02/27/05 11:05 R.Jenkins#56029, Environmental Supervisor, notified the control center on 02/27/05 at10:30hrs. to report that M45629 has been flushed and cleaned, as per above. M45629 was cleaned using a vactor truck and the yellow envirnomental tag #46964 was removed. The cleanup personnel were K.Sell#53414 and H.Goyeneche#82588. The soucre and cause is still unknown at this time. The completion time was 10:15hrs. on 02/27/05.

Map Identification Number 177 **APARTMENT BUILDING** **Spill Number: 0103578** **Close Date: 01/20/2010**
332 E 116TH ST MANHATTAN, NY 10029 TT−Id: 520A−0091−235

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2436 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	NEIL MCCUFFIN − ST. FRANCIS DESALES DEVELOPEMENT	Spiller Phone:	(212) 410−3153
Notifier Type:	Affected Persons	Notifier Name:	PATRICIA BYRON	Notifier Phone:	(212) 828−5540
Caller Name:	PATRICIA BYRON	Caller Agency:	CITIZEN	Caller Phone:	(212) 828−5540
DEC Investigator:	RVKETANI	Contact for more spill info:	PATRICIA BYRON	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/02/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL, AIR

Caller Remarks:

UNK IF IT IS AN EQUIPMENT OR TANK FAILURE − BLDG SMELLS REALLY BAD ACCORDING TO CALLER − MARK TIBBE ADVISED

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE Chris Porpoterrero 347−219−5775.

12/23/05 − Haggerty − Spoke with previous owner, Mr. Geneski (212−534−6464) who owned the property at time of spill. He states the spill was called in due to a strong petroleum odor emanating from the boiler. He states there was no release of oil, the boiler was just backed up. He hired someone to repair boiler and odor went away. He has no docs pertaining to the cleanup/boiler repair, but is willing to write a letter documenting everything. He requested a few weeks to contact the boiler repair company to reference in the letter.

10/2/09 − Austin − Spill transferred from Albany staff to Ketani, for further investigation − end

10/8/09 − Raphael Ketani. Presently, there are no E−docs and documents in the case file.

The spill was called in on 7/2/01. It was called in by a citizen who claimed that the odors were strong in the building.

There is no PBS registration. According to Property Shark, the site is a 4 story walkup, tenement style, apartment building. The block and lot are 1687 and 137. The address is 332 East 116th Street, Manhattan. There are no alternate addresses. The building was built about 1900. According to ACRIS, on 3/2/95, the building was sold by 332 East 116 Street Inc. to SFDS (St. Francis deSales Development Association), 185 E. 96 Street, Manhattan. On 5/23/05, SFDS sold the building to Adam Rosenthal, 39 West Maple Avenue, Denver, CO, 80223.

A former case manager note states that Mr. Geneski, President of SFDS Development, was contacted about the odors. He explained that it was just a back up in the boiler and that no oil had been spilled. Mr. Geneski also stated that he will hire a plumber to resolve the problem.

10/9/09 − Raphael Ketani. I made contact with Jim Janesky (212) 534−6464, ext 102, President of SFDS Development. I asked him about the nature of the sale of the property to Adam Rosenthal. He said that he remembered the sale. He added that Mr. Rosenthal had some family in New York, but no businesses. He will have his assistant look for any phone numbers for Mr. Rosenthal and get back to me if he finds anything.

10/13/09 − Raphael Ketani. Mr. Janesky left a message today. He said that he didn’t have much more additional information. Mr. Rosenthal has only a Denver, CO address. However, Mr. Rosenthal’s attorney was Gideon Schwartz at 277 Broadway, Ste 408, NY, 10007. Mr. Schwartz’ phone number is (212) 807−4901.

12/15/09 − Raphael Ketani. Today I made an unannounced site visit at about 3:00PM. I rang each of the three working buzzers, but no one came to the door. I could see that the entryway light was on and that the stairway light was on. The windows of the apartments in this four floor walkup building (see E−docs) were dark.

12/16/09 − Raphael Ketani. I made another unannounced site visit at 10:00AM. The windows of the building were all dark. No one

answered when I rang each of the three buzzers.

Later, I contacted the NYC Dept. of Finance in order to find more owner information for the building. The person answering the phone said that whatever I had found while using ACRIS was all he had. Next, I contacted the law office of Gideon Schwartz and left a message with his secretary that the DEC wanted to obtain access to the site in order to perform an odor inspection.

1/6/10 − Raphael Ketani. I sent a letter requesting access to the site to Mr. Rosenthal and to Mr. Schwartz by regular mail and certified mail.

1/14/10 − Raphael Ketani. The green return card from Mr. Schwartz was returned signed. The letter to Mr. Rosenthal was returned Not Deliverable as Addressed, Unable to Forward.

Later, Mr. Rosenthal contacted me. He said that he was willing to meet with me and show me the site. We set up an appointment for 1/20/10 at 10AM. His phone number is (303) 884−4083 and his new address is 1045 Pine Street, Boulder, CO, 80302.

1/20/10 − Raphael Ketani. I buzzed bell #4 and met Mr. Rosenthal. He said that he bought the place in 2005 and lives part of the time in New York and part of the time in Denver. He showed me the basement. Mr. Rosenthal said that the building runs on gas. He said that he hasn't gotten rid of the tank yet because it costs money (see E−docs). I saw a gauge on the tank which appeared to indicate that there was no oil. However, I asked him whether there was product inside. He said the tank was empty. I banged on the tank, but couldn't tell whether anything was inside. The vent and fill pipes were still connected. The basement floor appeared to be old, but was in good condition with few cracks. The water in the sump appeared to have some milky or waxy substance in it. The water in the center of the sump was clear. There were no odors. I was not sure what the milky or waxy substance was − perhaps a buildup of dust, or fungus. My PID meter didn't detect any odors inside the building, nor in the basement. Next, he took me to the boiler room. The boiler room was free of stains and there were no odors. After this, I left the site.

As there appears to be no evidence of an oil spill, and as there are no vapors in the entire building, I have determined that there is no threat to the public, nor the environment. Therefore, I am closing the spill case.

Map Identification Number 178 **217897; 2 AVENUE AND 125TH STREET** **Spill Number: 0914366** **Close Date: 07/08/2010**
2 AVENUE AND 125TH STREET MANHATTAN, NY TT−Id: 520A−0249−430

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2439 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: 2ND AVE / E 125TH ST
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: dmpokrzy

Spiller: ERT DESK − CON EDISON
Notifier Name:
Caller Agency:
Contact for more spill info: ERT DESK

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/07/2009		UNKNOWN	NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0	GALLONS	0	GALLONS	UTILITY

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

07/08/2010 See eDocs for Con Ed report detailing cleanup and closure DMP

Map Identification Number 179 **IS 45M− NYSCA** **Spill Number: 0904431** **Close Date: 02/28/2011**
2351 1ST AVE NEW YORK, NY TT−Id: 520A−0229−448

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2442 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: DREW PARDIS AND MICAHEL TUMULTY − UNKNOWN Spiller Phone:
Notifier Type: Local Agency Notifier Name: Notifier Phone:
Caller Name: Caller Agency: Caller Phone:
DEC Investigator: hrpatel Contact for more spill info: DREW PARDIS AND MICAHEL TUMULTY Contact Person Phone: (718) 752−5036

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/15/2009		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	19.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Temp boiler was set up behind the school some oil was discovered. The oil may be coming from the temp boiler on site. Clean up will start tomorrow.

DEC Investigator Remarks:

07/15/09−Vought−Primary off−hours responder. Called and spoke to Mike Timulty (SCA (718) 752−5036). Site is a school (IS 45M) that is changing boilers and as such has installed a temporary boiler and tempoarary 275−gallon AST in center courtyard. Shoring be installed for new boiler and during installation oil was observed where shoring comes in contact with building wall. Groundwater at 8'bg. SCA performed site visit and observed oil on the soil directly under temporary boiler which was immediately adjacent to seep. Contractor for SCA will meet with SCA tomorrow to begin soil excavation and collection of endpoint samples. School is currently closed for summer and will reopen in fall so no vapor issues to date. Work will take approximately one week. Contractor to perform work will be BG National. CSL sent to:

DEC requires CSL with one month due date and: 1)collection of endpoint samples 2)cc to NYSCA Timulty(Fax:646654−1861). Vought sent CSL to:

Mr. Drew Pardus NYSCA 30−30 Thompson Avenue Long Island City, NY 11101−3045 Fax: (718)472−8500

07/20/09−Vought−DEC Austin requested update. Vought called Pardus and left message to return call with status update.

07/27/08−Vought−Received call from and spoke to SCA Pardus (cell 646−577−8280) and area was stabilized and LIRO Engineering working for SCA who are developing plan for investigation of soils. No sheen on groundwater but there is water present as of this morning. STV still onsite. LIRO contracted Fenley and Nicol to clean oil under boilers and collect water in pit. Possible contamination under boiler and between boiler and pit. Further excavation and or soil borings will be proposed. No samples have been collected to date. Spill underground in boiler room. Vought stressed importance of completing remedial action prior to children returning to school (late August or early Sept) in order to avoid air monitoring and possible health impacts.

08/05/09−Vought−Unscheduled office visit to DEC by Pardus to deliver workplan for further investigation prepared by (STV Timulty). Temporary tank currently in use with secondary containment. Boiler being replaced in school and new boiler had to be brought in via excavation through building foundation. During excavation of entranceway for new boiler soil contamination was discovered (oil was observed seeping into excavation adjacent to foundation wall). No oil seepage into school boiler room through foundation wall. F&N recovered impacted groundwater and free product via vacuum truck from excavation. Proposal for installation of eight soil borings with collection of highest PID and deepest dry soil samples. Vought noted that if free product encountered in borings then DEC will require well installation at same locations. If free product encountered then product recovery will only occurr after school hours (along with well installation). Boiler room sump was checked and showed no impact from spill. Boiler replacement will not be completed until October and as such excavation will remain open adjacent to school when school is in session. As such Vought required that excavation be covered during school hours to ensure no vapors migrating from excavation to school windows above. Voughht also required that member of NYCDOH Environmental Health (Bernie Orlan's group) be notified of work and Vought to CC Orlan and Pardus on approval letter for workplan. As per the workplan , It is STV's opinion that the leakage of fuel oi from the temporary boiler unit is the source of the oil discovered on the groundwater in the nearby shored pit . ...an eight foot diameter puddle of fuel oil was observed under the end of the temporary boiler. Inside the boiler control

shed (located on the south side of the temporary boiler), the floor beneath the fuel oil piping was covered with oil. These spills cleaned by Fenley and Nicol. Proposal also includes collection of groundwater samples from eight boring locations and submission of a Remedial Investigation Report. Vought sent Work plan approval letter to:

Lee Gutterman NYC SCA 30−30 Thompson Avenue Long Island City, NY 11101 Fax:(718)472−8500 Ph:(718)752−5026

with cc to Pardus and NYCDOE Orlan and additional requirement that excavation be covered with plastic during school hours and that well installation and recovery efforts (if any) be restricted to non−school hours.

9/30/09− File review by Intern E.M Ibeh,

The file being reviewed is Subsurface Investigation Report and Remediation Plan, prepared by STV for New York City School Construction Authority (NYCSCA) at 2351 First Avenue, NY 10035. SP# 0904431.

On 7/15/09, STV was alerted to fuel oil release in an excavation outside the boiler room of the site and after consultation with the NYCSA, the spill hotline was called and a spill number assigned to the case. STV inspected the site the next day (7/16) with representatives from SCA, LiRo (the provider of an on−site temporary boiler system) and Bay Boiler (LiRo subcontractor and operator of the temporary boiler system). A shored excavation pit was located adjacent to the school building that was created to allow the installation of new boiler equipment in the boiler room located in the school basement; and at the time of inspection, oil sheen was observed seeping through the sheeting on groundwater near the bottom of the pit.

The temporary boiler, located 12ft south of the excavation, operates on #2 fuel oil and is connected to an adjacent 8000gallon AST. No evidence of release from AST or the lines entering into the temporary boiler. An 8ft diameter puddle of fuel oil was observed beneath the southern end of temporary boiler and inside the boiler control shed, oil was found beneath the piping. STV opined that leakage of fuel oil from temporary boiler unit is the source of the oil discovered on the groundwater in the pit. The Bay Boiler rep reported that due to sudden startups or changes in wiring, the fuel pump operated in a way that resulted in excessive pressure resulting in the blowout of a diaphragm in a pressure sensor. Oil was released to the floor and leaked through floor openings to the asphalt pavement below. He said the diaphragm and sensor switch were replaced. After discovery of the spill, measures were taken: − Groundwater from pit was temporarily pumped into pails till a vac truck arrived to remove them for disposal.

− Bay Boiler performed repairs to the temporary boiler piping and controls and no further releases were observed. Boiler inspection increased to daily. − Cleanup activities were performed on 7/16 by F&N for LiRo and the pooled oil and all saturated debris were cleaned up and Speedi−Dry and sorbent pads were used to cleanup the oil. A berm was placed underneath the temporary boiler unit as a precaution against piping failure.

Regional groundwater flow direction is generally to the east, towards the East River and local groundwater flow is south southeast. 11 soil borings (SB100−110) were taken onsite to vertically and horizontally delineate the oil release. Borings were advanced to depths between 10−16ft bgs and groundwater was encountered 8−9 ft bgs. All samples were screened with a PID for odors. No samples were collected from SB108 and SB109 since SB110 was advanced further west and served as the soil delineation boring. Duplicate samples were collected and samples were shipped to be analyzed for STARS VOCs and STARS SVOCs. Groundwater samples were collected from temporary well points at 6 of the 11 soil borings but they were not collected from SB105, 106,107,108 or 109 due to the presence of separate−phase petroleum. They were sent to be analyzed for STARS VOCs and STARS SVOCs.

Upon discovery of free product in some of the soil borings, 4 of them were converted into recovery wells and product recovery activities initiated and the wells were installed at SB105, 106,107&109. SB109 was converted into a well because it contained FP and was located far from the spill area. As of 9/9, 5 rounds of well gauging and product recovery have been conducted on recovery wells RW105, 106,107& 109 and product was collected and contained. A significant reduction in product recovery was observed in RW105 and RW106 continues to yield the highest quantity of product per pumping event. On 8/28/09, STV oversaw the application of ~120lbs of ORC into the pit. ORC was allowed to mix with the shallow layer of groundwater in the pit to facilitate the biodegradation of any residual petroleum impacts.

Soil Boring Results

Sb100 (8−9'bg)− MTBE ND, Benzene ND, T 0.23J, E ND, Mixed Xylenes ND, Naphthalene ND, Benzo(a) anthracene 3200ppb, benzo(b)fluoroanthene 4200ppb, Benzo(k)fluoroanthene 1700ppb. Sb101A(2−3'bg)− MTBE ND, Benzene ND, T 0.33J, E ND, Mixed Xylenes ND, Naphthalene ND, Benzo(a)pyrene 160J; Sb102 (8−9'bg)− MTBE ND, Benzene ND, T 0.37J, E ND, Mixed Xylenes ND, Naphthalene ND, Benzo(a) anthracene 2700ppb, benzo(b)fluoroanthene 2800ppb; Sb103A (1−2'bg)− MTBE ND, Benzene ND, T 0.26J, E ND, Mixed Xylenes ND, Naphthalene ND; Sb104A−16ft− MTBE ND, Benzene ND, T 0.25J, E ND, Mixed Xylenes ND, Naphthalene ND, Benzo(a) pyrene 81J; SB105 (5−6'bg)− MTBE ND, Benzene ND, T 0.13J, E ND, Mixed Xylenes ND, Naphthalene ND, Benzo(a) anthracene 230J, benzo(b)fluoroanthene 300J; SB106A (3−4'bg)− MTBE ND, Benzene ND, T 0.53J, E ND, X ND, Naphthalene ND, Benzo(a) anthracene 670ppb, benzo(b)fluoroanthene 770ppb, Benzo(k) fluoroanthene 270J. SB107A (1−2'bg)− MTBE ND, Benzene ND, T 0.51J, E ND, Mixed Xylenes ND: SB107B (7−8'bg)− MTBE ND, Benzene ND, T ND, E 150J, m+p Xylenes 790ppb, o Xylene 1300ppb, 1,3,5 trimethyl benzene 5100ppb,Acenaphthene 2500ppb, Phenanthrene 5900ppb, Benzo(a) anthracene 550ppb, benzo(b)fluoroanthene 550ppb; SB108 & SB109− NS SB110 (8−9'bg)− All VOCs ND, Benzo(a) anthracene 1000ppb, benzo(b)fluoroanthene 1000ppb, Fluoroanthene 2200ppb.

Groundwater Results

SB100− MTBE ND, Benzene ND, T ND, E 0.17J, Mixed X 0.77J, Acenaphthene ND, Phenanthrene 0.97J. SB101− MTBE/BTEX ND, SVOCs ND. SB102− MTBE/BTEX ND, SVOCs ND. SB103− MTBE ND, Benzene ND, T 0.63ppb, E 0.45J, Mixed X 0.77J, Naphthalene 5.7ppb, Acenaphthene 1.1J, Phenanthrene 3.7J, Anthracene 0.39J. SB104− MTBE/BTEX ND, m+p X 0.37J, o X ND, All SVOCs ND. SB105, 106, 107, 108 7 109−NS SB110− MTBE/BTEX ND, SVOCs ND

08/31/09−Vought−Received call from and spoke to Drew Pardus who wished to provide update. Eight borings installed with few additonal borings and four monitoring and recovery wells installed and product being recovered via pneumatic pump. Measurements of product and water levels prior to recovery. Two recovery events in first week and recovery amounts being used to determine recovery frequencies. For first recovery 40 gallons of free product found after allowed to settle in pump. Groundwater flow possibly to East and product is being retained by the wall of the school. Vought discussed need for groundwater flow direction. Surface spill was cleaned but temp boiler cannot be moved as they are in service. Once they are removed then soil removal will occur. As of last week boiler should be completed in October. STA's IEH group has contacted Orlan with respect to site. Investigation report with RAP will be submmitted and groundwater samples in excavation pit were below TOGS and ORC was placed into the excavation by 9/30.

11/16/09−Vought−Received message from NYSCA Pardus requesting review of Subsurface Investigation Report and RAP. Vought reviewed Subsurface Investigation and RAP received from NYSCA Lee Gutterman (Ph:718−472−8502 fax:718−472−8500) and prepared by Michael Timulty (Ph:212−777−4400 Fax:646−654−1861). Site is a four story school building with basement. On 7/15/09, fuel oil was noted in excavation located outside boiler room of site. Temporary boiler located south of excavation that is connected to temp 8000−gallon AST. An approximately eight foot diamater puddle of fuel oil was observed beneath the southern end of the temporary

boiler . Oil was found in on floor beneath piping to boiler. Oil was released to the floor and leaked through floor openings to the asphalt pavement below. Fenley and Nicol cleaned spill on concrete but temp boiler cannot be removed as was servicing building. Eleven soil borings were performed and free product events are ongoing. Groundwater at 8−9'bg. Free product was discovered in four soil borings and they were converted to monitoring wells. (RW105(1.24'), RW106(1.58'). RW107(.04') and RW109(0')). Soil analyticals show 2090ppb xylene(SB107) and 5100ppb 1,3,5 trimethylbenzene(SB107). All other soil analyticals show ND for VOCs. Groundwater samples not collected from RW105, RW106. RW107 and RW109 as these wells contained free product. Groundwater samples collected from wells with no free product show non−detect concentrations for fuel oil constituents. To date approximately 140 gallons of free product have been recovered by periodically pumping the recovery wells. Five rounds of recovery were performed Report recommends continuation of VEFR on wells with product until no sheen remains or until temporary boiler is removed and subsequent excavation of impacted soil is performed. Excavation proposed to occur to 2 feet below groundwater table or until evidence of petroleum impacts are no longer observed . Soil and groundwater endpoint samples will be collected Contractor to submit a Excavation and Shoring Plan to the school as well as a Dewatering Plan. DEP permits will be obtained for treated discharge.

Vought called IEH and spoke with Anne Charlap (acharlap@nycsca.org Ph:718−752−5384) and DEC's approval of plan pending inclusion of 1)installation of well in excavation and subsequent sampling and 2)PID monitoring 3)excavation during non school hours. Vought sent letter to above address with this requirement.

12/16/09−Vought−Received letter from NYSCA Gutterman dated 12/8/09. SCA respectfully requests that the installation of two monitoring wells and two quarters of groundwater sampling would only be required if soil endpoint samples.... ...or groundwater samples.... exceed TOGS and or TAGM. Vought sent reply approving of endpoint sample collection prior to well installation provided that excavation below groundwater as per RAP was performed and soil sidewall AND bottom groundwater samples are collected. Letter with cc to DOE Orlan.

4/27/10−Vought−Received call from NYSCA Lee Gutterman and he insurance company is looking to submit alternative RAP (other than soil excavation) and would like to discuss possibility of remedial alternative. Gutterman requested conference call with Vought and insurance rep from Chartis Insurance (Tanya Crawford). Vought agreed to call and Gutterman to send email to Vought with conference call time.

4/30/10−Vought−No email received from Gutterman to date. Vought received call from Gutterman and teleconference today with herself, DEC Vought and Tanya Crawford, Chartis Insurance, Claims Analyst (Ph:201−631−7158). Conference call with DEC Vought, NYSCA Gutterman, STV Timulty, Chartis (Larry Daniels and Tanya Crawford). Chartis proposed excavation of VOC contaminated soil only (as opposed to original proposal for excavation at all areas with free product on groundwater). Vought agreed to excavation to VOC contaminated soil only (to remove source) however since product has migrated on water table away from source then a down−gradient well will be installed. However if they elect to excavated entire area above free product then no down gradient delineation required as excavation will enable VEFR of water table. Tumulty indicated that 800 gallons of product−water mix recovered to date with reduction in recovery amounts (max product thickness is 6). Timulty also indicated that product was observed seeping into adjacent boiler room however the seepage was cleaned and wall repainted and no further seepage to date.

6/11/10−Vought−Spill transferred from DEC Vought to DEC Patel as per DEC Austin and Vought transfer to Section A.

07/02/10−Hiralkumar Patel.

alternate addresses: 2345−2363 1st Ave, 339−355 East 120th Street

07/08/10−Hiralkumar Patel. 10:03 AM:− received message from Mr. Pardus.

08/06/10−Hiralkumar Patel. 3:27 PM:− left message for Mr. Pardus inquiring updates. 4:11 PM:− received call from Mr. Pardus. he mentioned that temporary tank and boiler were removed and excavation started early July, 2010. they found free product on water which was pumped out. soil was excavated 2 ft below water table. Mr. Pardus mentioned that based on results of previous borings, they installed sheeting in clean area. so three side of excavation is sheeting and fourth side is building foundation wall. all soils between sheetings and foundation wall were removed, so no endpoint sidewall samples collected. they collected endpoint bottom groundwater samples. will wait for results before backfilling excavation. Mr. Pardus mentioned that report will be submitted by end of Oct., 2010.

08/18/10−Hiralkumar Patel. 10:09 AM:− received email from Mr. Pardus with results of groundwater samples collected at the bottom of excavation. he mentioned that remediation area was divided in three cells (1, 2 and 3) as excavation was adjacent to building foundation wall. all soil within cells has been excavated to a depth of 2 ft below groundwater table. collected groundwater sample from each cell as endpoint bottom sample. no contamination found in groundwater sample from Cell 1 and Cell 2, but found very minor VOC contamination in Cell 3 (max. O−Xylene: 24 ppb). due to some VOC contamination, additional groundwater removal has been performed in Cell 3 and another post−remediation groundwater sample was collected today. Mr. Pardus requested approval for backfilling the excavation based on results of endpoint groundwater samples. he mentioned that ORC will be applied prior to backfilling. he also requested that no permanent well should be installed in excavation (as mentioned in DEC letter dated 12/16/09). 1:11 PM:− received call from Mr. Pardus. based on results of groundwater samples and all soils in three cells have been removed to 2 ft below water table, approved Mr. Pardus's request to backfill the excavation. also approved his request not to install a permanent well in exavation. asked him to submit a complete report.

02/03/11−Hiralkumar Patel. 12:34 PM:− spoke with Mr. Pardus regarding report. he mentioned that SCA is currently reviewing the closure report and once he gets comments, he will submit the report. 12:40 PM:− sent email to Mr. Pardus and asked to submit report by end of 02/28/11.

02/28/11−Hiralkumar Patel. received remedial action report from SCA.

based on submitted information, case closed.

Map Identification Number 180 **MANHOLE #62325** **Spill Number: 0602136** **Close Date: 10/05/2006**
2 AVENUE & 113 STREET MANHATTAN, NY TT−Id: 520A−0097−415

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2451 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: 2ND AVE / E 113TH ST
Revised zip code: 10029

Source of Spill:	UNKNOWN	Spiller:	ERTS − CON EDISON	Spiller Phone:	(212) 580−8383
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	GDBREEN	Contact for more spill info:	ERTS	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/26/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

ONE OINT OF PRODUCT ON 150 GALLONS OF WATER IN THE MANHOLE, NO TO FIVE QUESTIONS, CON ED # 200258

DEC Investigator Remarks:

10/05/06 − See e−docs for Con Ed report detailing cleanup and closure. 200258. See eDocs.

Map Identification Number 181 **LEXINGTON AV/E 128TH ST** **Spill Number: 9703094** **Close Date: 10/30/2008**
LEXINGTON AV/E.128TH ST NEW YORK, NY TT−Id: 520A−0090−950

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2472 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	TIM SOILCH − CON EDISON	Spiller Phone:	(212) 580−6764
Notifier Type:	Responsible Party	Notifier Name:	LISA PRIMEGGIA	Notifier Phone:	(212) 580−6763
Caller Name:	LISA PRIMEGGIA	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	JMKRIMGO	Contact for more spill info:	LISA PRIMEGGIA	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/11/1997		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	3.00	GALLONS	3.00	GALLONS	SOIL

Caller Remarks:

while removing a natural gas line − 3 gallons of water were found water is being tested for benzene −

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT

10/30/08. J.Krimgold reviewed info presented by Con Ed. There are no historic data in Con Ed records. However, caller in his remarks indicated that while removing a natural gas line − 3 gallons of water were found. water is being tested for benzene . Unconfirmed release. Most lickely by a third party. NFA.

Map Identification Number 182 **127 W 122ND ST** **Spill Number: 9112299** **Close Date: 11/22/1994**
127 W 122ND ST MANHATTAN, NY TT−Id: 520A−0091−871

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2477 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:		Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:		Notifier Phone:	
Caller Name:	VENTER HOLLY	Caller Agency:		Caller Phone:	(212) 306−2866
DEC Investigator:	SIGONA	Contact for more spill info:		Contact Person Phone:	

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/03/1992	11/22/1994	UNKNOWN	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SURFACE WATER

Caller Remarks:

~50 GAL LEAK FROM VENT PIPE TO STREET AND STORM DRAIN DURING EVERY DELIVERY. REFERED TO LAW ENF.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 183 **MANHOLE #39138** **Spill Number: 9809172** **Close Date: 11/04/2003**
EAST 110 AND LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0092−971

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2477 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: EAST 110TH ST / LEXINGTON AV
Revised zip code: 10029

Source of Spill: UNKNOWN Spiller: UNKNOWN Spiller Phone:
Notifier Type: Other Notifier Name: MR MARCY Notifier Phone: (212) 338−3352
Caller Name: WILLIAM MURPHY Caller Agency: CON ED Caller Phone: (212) 580−6763
DEC Investigator: JHOCONNE Contact for more spill info: Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/22/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CON EDISON #120733 TOOK SAMPLE FOR PCB HANDLING AS 50−499 PPMPCB

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS 120733

10/22/98 11:27 O.S R.VELASQUEZ(27188) REPORTS WHILE WORKING ON FDR−3M67(SCHEDULED) FOUND APPROXIMATELY 2 QUARTS OF UNKNOWN OIL ONTOP OF APPROXIMATELY 80 GALLONS OF WATER... NO ENTRY INTO THE SEWER OR WATERWAY. NO SUMP,NO SEWER CONNECTION.. NO ENVIRONMENTAL IMPACT..... OIL APPEARS TO BE UNKNOWN AND IT BLACK.FINAL CLEANUP IS EXPECTED TO BE COMPLETED THIS AFTERNOON THERE ARE ADDITIONAL OIL FILLED JOINTS IN THIS STRUCTURE..... PM58101

10/22/98 11:45 UNABLE TO CONTACT CIG.... NO ANSWER..... PM58101 10/22/98 12:22 CIG ADVISED..... PM58101 TAG#294 INSTALLED AND SAMPLE TAKEN..... PM58101

10/23/98 0137 HRS RESULTS OF LAB ANALYSIS #98−11469 RECEIVED ON 10/22/98 @1806HRS: PCB <1 PPM, AROCLOR 1260 LOGGER JPH 74031

10−25−98 14:10 Cleanup completed on 10−23−98 at 1300 hours, supervised by R.Velasquez 27188. 100 gallons oily water removed via tanker, mh was then flushed, 1−55 gallon drum non−hazardous waste generated. Tag removed. Crew: E.Foley 10441 and M.McCoy 17100.

Map Identification Number 184 **MANHOLE #39138** **Spill Number: 9809081** **Close Date: 11/14/2003**
E 110TH ST & LEXINGTON AV MANHATTAN, NY TT−Id: 520A−0090−987

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2477 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: E 110TH ST / LEXINGTON AV
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:		Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:	DENNIS ROMANO	Notifier Phone:	(212) 338−3352
Caller Name:	RICHARD ROACHE	Caller Agency:	CON ED	Caller Phone:	(212) 580−6764
DEC Investigator:	CAENGELH	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/21/1998		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

1 QUART OF UNK OIL FOUND IN MANHOLE − 120671 CON ED #

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis 120671

10/21/98 04:35 PECORARO (FOD) REPORTS: WORKING ON SCHEDULE FDR−3M67 IN M−39138 S/E/C E.110 ST. & LEXINGTON AVE. FOUND APPROX. 1 QT. OF UNKNOWN OIL ON APPROX. 200 GALS OF WATER. OIL IS CONTAINED TO THE MANHOLE. DIDN'T ENTER ANY WATERWAYS OR SEWER SYSTEMS. UNABLE TO DETERMINE IF MANHOLE HAS A SUMP PIT OR CRACKS ON WALLS. TOOK SAMPLE AND HUNG SIGN # 17865

10/21/98 04:53 C.I.G. ROACH 10/21/98 1354 HRS RESULTS OF ANALYSIS 98−11341 RECEIVED @1346 HRS: PCB <1 PPM, AROCLOR 0

10−22−98 10:05 Cleanup complete on 10−21−98 at 2130 hours, supervised by R.Veasquez 27188, 300 gallons oily water removed via tanker, mh was then flushed. 1−55 gallon drum non hazardous waste generated. Taag 17865 removed. Crew: J.Burgos 07271, R.Calderon 19847, J.Pelzer 06470 and A.Pizarro 147911.

Incorrect structure number (39165) was entered on the Chain of Custody. This should have read 39138 and was changed to indicate such on the office copy.

When the lab analysis (SA98−11341) was delivered it indicated the correct strcuture (39138). This matches the incident number (120671) and the location. The only thing incorrect was the initial entry on the Chain of Custody. .... roz ... 11/12/98

Map Identification Number 185 **SPILL NUMBER 0105211** **Spill Number: 0105211** **Close Date: 12/08/2003**

11 WEST 127TH ST MANHATTAN, NY TT−Id: 520A−0093−362

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2480 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Citizen	Notifier Name:		Notifier Phone:	
Caller Name:	JAMES RICH	Caller Agency:		Caller Phone:	(212) 369−9835
DEC Investigator:	TJDEMEO	Contact for more spill info:	JAMES RICH	Contact Person Phone:	(212) 369−9835

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/14/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

caller states there is some type of spill near con ed box − unk product − caller states product smells like burnt rubber − con ed was on scene last night states problem is not there − no clean up

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/8/03 TJD Unknown source. Spilled on roadway. No further action possible. Spill closed due to lack of recent history.

Map Identification Number 186 **M AND M GROCERY** **Spill Number: 0605241** **Close Date: 08/10/2006**
2337 1ST AVE MANHATTAN, NY TT−Id: 520A−0090−522

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2510 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN − Unknown	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SFRAHMAN	Contact for more spill info:	DISPATCHER 210	Contact Person Phone:	(212) 628−2900

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/04/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
SULFURIC ACID	HAZARDOUS MATERIAL	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

CLEAN UP NOT IN PROCESS.

DEC Investigator Remarks:

08/10/06 Rahman− I called the FDNY and told them to notify DEP Hazmat. NFA required.

Map Identification Number 187 **SERVICE BOX 42143** **Spill Number: 0906507** **Close Date: 09/16/2009**
PARK AVE 128TH/129TH MANHATTAN, NY TT−Id: 520A−0233−088

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2522 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: PARK AVE
Revised zip code: 10035

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RWAUSTIN	Contact for more spill info:	ERT	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/05/2009		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	10.00	GALLONS	0.00	GALLONS	

Caller Remarks:

10 gallons of unk oil discovered in service box, cause unk, will be going for ananlysis to detirmine what oil is. Spill is contained in service box.

DEC Investigator Remarks:

9/16/09 − Austin − Spill contained and cleaned up − see EMIS in eDocs file − closed − end

Map Identification Number 188 **2ND AVE SUBWAY −NYCT** **Spill Number: 0305966** **Close Date: 10/29/2010**
125TH & 126TH ST MANHATTAN, NY TT−Id: 520A−0101−854

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2530 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: 125TH / 126TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	SIRISH MUFTHYALA	Notifier Phone:	(908) 437−7089
Caller Name:	SIRISH MUFTHYALA	Caller Agency:	METCALF & EDDIE	Caller Phone:	(908) 437−7089
DEC Investigator:	hrpatel	Contact for more spill info:	SIRISH MUFTHYALA	Contact Person Phone:	(908) 437−7089

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/05/2003		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

while doing work they came in contact with contaminted soil

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

09/01/05: Elevated PID reading discovered in a boring being performed as part of the 2nd Avenue Subway Project. Corresponding soil and GW sampling showed only minor hits of metals and a few SVOCs constituents. One VOC, Xylenes @ 1400, exceeded TAGM criteria.

10/29/10−Hiralkumar Patel. reviewed sample result and boring log from MTA: − boring H125−2 was installed to total depth of 38 ft

depth − groundwater encountered at 12 ft depth − fuel oil odor at 12−14 ft depth − PID readings found from 12 to 16 ft depth only − 1,182 ppm recorded on PID in 12−14 ft and 34.2 ppm recorded on PID in 14−16 ft range − no PID readings found in remaining boring − well installed with screen from 5.2 to 20.2 ft depth − no contamination found in groundwater sample − found Xylene (1,400 ppb) and Ethylbenzene (740 ppb) in soil sample at 12−14 − no other contamination found

after discussing with DEC Austin, case closed.

Map Identification Number 189 **207627; E ST** **Spill Number: 0890189** **Close Date: 08/21/2007**
E ST , NY TT−Id: 520A−0220−211
E 110 ST LEXINGTON AVE THIRD AV

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 2553 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 110TH ST / LEXINGTON AVE / THIRD AVE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ERT DESK − CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	Unassigned	Contact for more spill info:	ERT DESK	Contact Person Phone:	(212) 580−8383

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/17/2007		UNKNOWN		

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIELECTRIC FLUID	PETROLEUM	0.01	GALLONS	0.00	GALLONS	UTILITY

Caller Remarks:

M18238 − E 110 ST 158 − CABLE OIL Closed: Agency Approval Not Required

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 190 **JACKIE ROBINSON CONSOLID. −NYCHA** **Spill Number: 9910794** **Close Date: 01/07/2016**
129 E.128TH ST MANHATTAN, NY TT−Id: 520A−0098−389

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: JACKIE ROBINSON CONSOLID.
Spiller Phone:
Notifier Type: Other
Notifier Name: ALDO GALANTE
Notifier Phone:
Caller Name: FRANK INOE
Caller Agency: NYC HOUSING
Caller Phone: (212) 306−8894
DEC Investigator: jkkann
Contact for more spill info:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/10/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

DURING SITE ASSESSMENT PRIOR TO TANK REMOVAL CONT. SOIL FOUND

See 9315465.

DEC Investigator Remarks:

11/28/05: This spill transferred from J.Kolleeny to S.Kraszewski.

07/17/06: NYCHA update summary states that one 20K UST installed in 1973 that stored #4 and #6 fuel oil was replaced by a 10K UST that presently stores #2 oil. Contaminated soil was encountered during tank replacement. No product recovery systems of MWs. A site assessment is available and NYCHA recommends DEC review it. − SK

10/06/08: J.Kann − site reassigned from S. Kraszewski to J.Kann

3/10/11: J.Kann − Investigative work plan submitted on 3/3/11.

6/10/15: J.Kann − Reviewed file. Contamination (visible) present in January 2000 assessment by ESPL. It is not clear how much,

if any, soil was removed as a part of tank replacement. Therefore, NYCHA is required to investigate the south/southwestern portion of the tank area where previous contamination was detected. The report is due 12/10/15.

11/16/15: J.Kann − visited site today. Based on observations of boring sleeves, minor impacts noted in sandy layer in one boring just above a confining layer of clay. Clay layer is moist, but not clear if in actual groundwater. No impacts noted in the clay layer. Informed the consultant that they can collect three samples from each boring instead of a well given the presence of the confining layer. The most impacted sandy layer should be collected as well as the deepest sample and a sample in between. The clay layers had no staining, no odor.

1/7/16: J.Kann − Received an email from Tyler Goodnough PID readings in SB−11 were encountered just above and below approximately 3−4 inches of wood, which appeared to be saturated with liquid (the wood itself also returned high PID readings) and had a paint−like odor. There was no visible staining or wetness in the soils themselves. Agreed with his proposal to analyze for full VOCs (plus TICs) via EPA Method 8260 for this location back on 11/20/15.

Received the Summary Report for the subsurface investigation on 1/4/15. Based on review of this report, a total of 7 borings were extended. Groundwater was not encountered but a confining layer of clay was encountered in the deep borings around the tank. Some visual staining was noted, while in the field and on the boring logs, above the clay layer. These samples were collected for analysis as well as soils from the clay layer. All soil sample analysis showed levels below CP−51 guidance. In addition, the sample collected for full VOCs plus TICs was also found to have compounds detected, but below CP−51 guidance and NYSDEC 375−6.8(a). NFA. Spill closed. Email sent to NYCHA.

Map Identification Number 191 **JACKIE ROBINSON** **Spill Number: 9907036** **Close Date: 02/27/2004**
110 EAST 129TH ST MANHATTAN, NY TT−Id: 520A−0098−386

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	FRANK OCELLO − JACKIE ROBINSON	Spiller Phone:	(212) 306−3229
Notifier Type:	Tank Tester	Notifier Name:	SABASTIAN LOREFICE	Notifier Phone:	(212) 306−3233
Caller Name:	SABASTIAN LOREFICE	Caller Agency:	NYC HOUSING	Caller Phone:	(212) 306−3233
DEC Investigator:	SACCACIO	Contact for more spill info:	FRANK OCELLO	Contact Person Phone:	(212) 306−3229

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/13/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
1	20000	Horner EZ Check I or II	0.00	FAIL

Caller Remarks:

TANK WILL BE REPLACED SOON.

See 9315465 and 9910794. Closed based on tank replacement. George Breen.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 192 **I PT OF UNKN SUBSTANCE IN SB 21083** **Spill Number: 0610058** **Close Date: 02/16/2007**
105 EAST 128 STREET MANHATTAN, NY TT−Id: 520A−0098−390

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: 105 E 128TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	CON EDISON	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	GDBREEN	Contact for more spill info:	ERT DESK‘ MIKE DAUGHTERY	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/05/2006		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN MATERIAL	OTHER	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

1 pint. CON−ED # 203549

DEC Investigator Remarks:

02/16/07 − See e−docs for Con Ed report detailing cleanup and closure. 203549. see eDocs

Map Identification Number 193 **ROBINSON HOUSES −NYCHA** **Spill Number: 0001625** **Close Date: 12/30/2009**
110 EAST 129TH ST MANHATTAN, NY TT−Id: 520A−0098−384

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2571 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	FRANK INOA − NYC HOUSING AUTHORITY	Spiller Phone:	(212) 306−3142
Notifier Type:	Responsible Party	Notifier Name:	FRANK CASTELLI	Notifier Phone:	(212) 725−1002
Caller Name:	FRANK INOA	Caller Agency:	NYC HOUSING AUTHORITY	Caller Phone:	(212) 306−3142
DEC Investigator:	jkkann	Contact for more spill info:	FRANK INOA	Contact Person Phone:	(212) 306−3142

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/09/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

SOIL CONTAMINATION FOUND DURING TANK REMOVAL OF 20,000 GALLON TANK. CLEAN UP TAKING PLACE NOW.

DEC Investigator Remarks:

11/22/05: This spill transferred from J.Kolleeny to S.Kraszewski.

01/03/06: One 20K tank replaced with one 10K tank. Maximum mechanical stated they would perform 4 borings, one for each side of the 20K tank as part of the site assessment. No record of a site assessment recieved by DEC. No mention of boring made near the fill port.

Fascimile from Maxiumu Mechanical states that the soil around the fill port is to be drummed, but no mention of samples taken from this area.

Letter from Maximum Mechanical states contaminated soil to be stockpiled on sheeting. No record of the amount of soil removed, tare weights or destination of the material. No mention of end−point sample taken from the excavation.

Need the site assessment report mentioned in the correspondence and info about the excavation. − SK

09/01/06: DEC Lead for this spill changed from unassigned to S. Kraszewski. − J. Kolleeny

02/08/07 : DEC lead changed from S. Kraszewski to J. Kann. J.Kann

12/30/09: J.Kann − spill consolidated with 9910794

Map Identification Number 194 **1890 PARK AVE CORP** **Spill Number: 9902912** **Close Date: 10/05/2005**
1890 PARK AVE MANHATTAN, NY TT−Id: 520A−0095−064

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2574 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	GASOLINE STATION OR PBS FACILITY	Spiller:	1890 PARK AVE CORP	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	ROMEO SANTOS	Notifier Phone:	(718) 641−4000
Caller Name:	ROMEO SANTOS	Caller Agency:	DC ENVIORMENTAL SERVICES	Caller Phone:	(718) 641−4000
DEC Investigator:	JBTAMBE	Contact for more spill info:		Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/14/1999		UNKNOWN	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

WASTE OIL/USED OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

during tank removal at an old gas station contaminated soil found−

tanks appear to be sound

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 6/14/99

Spoke to Romeo Santos DC Environmental.

10/3/2005− Waiting for report from DC Environmental services.

They exposed a battery of eight 550s. Four contain gasoline and four contain waste oil/water. He noted soil contamination on top of the tanks. To date, the pipes have been emptied. They plan to pump the product out of the tanks tomorrow. He expects gw to be about 29 feet below grade. The site is on the corner of Park and E129th Street. Sammy Brahimy is the new owner. His deceased brother formerly onwed the property but they represent the same entity (Beige 1890 Park Corp). He will excavate the source material and collect endpoint samples for 8021 MTBE and 8270. He will contact DEC when the tanks are out of the hole.

Romeo Cell phone: 917−335−7742. JMR

6/16/99

Spoke to Romeo. They removed the tanks and bottom slab. They collected 6 endpoint samples from the 18’ x 45’ excavation, N,E,S,W walls and two from the bottom (approx 10’) and will run them for 8021 MTBE and 8270. Pump island on top of tanks and fills 6’ from tanks closed in place.

10/5/2005− Jacob− Closure report was received from Don Carlo Environmental Services Inc on october 5,2005. Results for the endpoint analysis are within DEC specification

Map Identification Number 195 **APART** **Spill Number: 0605629** **Close Date: 08/15/2006**
212 E. 111TH ST MANHATTAN, NY TT−Id: 520A−0090−526

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2581 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	MARCANTO − APART	Spiller Phone:	(646) 533−1649
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	HRPATEL	Contact for more spill info:	MARCANTO	Contact Person Phone:	(646) 533−1649

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/15/2006		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

coming thru walls of apartment

DEC Investigator Remarks:

08/15/06−Hiralkumar Patel. visited site. met Louis Mercado, super of building. went to building basement and found sewer problem. building receiving sewer from ground and super thinks it coming from next door property at 214 E 111th Street. asked super to talk to owner of neighbour property. no oil smell. no oil stains in wall between two property. spoke with Anat Golub (212−860−8821 Ext. 109), manager of property. asked her to contact NYC DEP and NYC DOH. case closed.

Map Identification Number 196 **PVT APARTMENT BLDG** **Spill Number: 9909067** **Close Date: 06/16/2006**
214 E.111TH ST NY, NY TT−Id: 520A−0095−633

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2594 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	DIONISIA VASQUEZ	Spiller Phone:	(212) 568−8074
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	CATHY BREEN	Caller Agency:	LITTLE SISTERS OF ASSUMPT	Caller Phone:	(212) 987−4422
DEC Investigator:	MJHAGGER	Contact for more spill info:	MS BUSSI(SPEAKS SPANISH)	Contact Person Phone:	(212) 722−8277

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Unknown RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/21/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

THERE'S A VERY BAD SMELL OF OIL IN THE APARTMENTS −− CALLER WORKD FOR A FAMILY HEALTH SERVICE AND BELIEVES IT IS HINDERING THE ASTHMA OF ONE YOUNG RESIDENT −− THE BASEMENT FLOOR IS COVERED IN SAWDUST.OWNER OF BLDG GIVES PERMISSION TO CHECK IT OUT.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND

11/2/99 − Sangesland went to site. No access to basement. Smell did not exist today.

Set up contact with landlord

6/14/06 − Haggerty − Conducted site visit with John Grathwol. Spill originally called in due to petroleum odor in the basement. We visually determined the apartment has since converted to gas heat. We spoke with Mr. Crowley from apartment 2F who stated he does his laundry in the basement and hasn't noticed a petroleum odor. No petroleum odor outside. Spill closed

Map Identification Number 197 **71 W. 126TH ST** **Spill Number: 9911163** **Close Date: 04/23/2007**
71 W. 126TH ST MANHATTAN, NY TT−Id: 520A−0093−361

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2595 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	LORRAINE GOBERN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:	CHERELLE	Caller Agency:	NYC DEP	Caller Phone:	(718) 595−6777
DEC Investigator:	jbvought	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Unknown RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/21/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL, SEWER
The following material(s) was dropped or revised by the NYS DEC. Call Toxics Targeting for more information						
UNKNOWN PETROLEUM	UNKNOWN	100.00	GALLONS	0.00	GALLONS	

Caller Remarks:

callers states oil is running into the sewer − caller did not

have any information about spill

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD see also 9911165.

01/26/04

REassigned fromRommel to Austin 02/17/04: Reassigned from AUSTIN to KRIMGOLD.

04/23/07−Vought−Reassigned from Krimgold to Vought. DEC Austin received email from Lasdin that she has received word from AG's office that the case was closed on 12/18/06. Request for further information. Vought called AG's office (Bechard) to confirm case status. Vought reviwed file and DEC's contractor removed oil contaminated speedi dry from basement and excavated impacted soil and sealed and washed floor. Cause of spill was collapsed leg on 275−gallon AST resulting in separated fill line.

Letter of Initital Demand from AG Donna Ross to owner (Lorraine Gobern) dated 12/30/21.

4/23/07−Vought−Called AG Ross to confirm status of spill and AG settled case with owner who paid outstanding costs. Spill closed by Vought as no further action required for soil and groundwater and costs have been recovered. Final ISR submitted to DEC Austin for review.

Map Identification Number 198 **75 WEST 126TH STREET** **Spill Number: 0104097** **Close Date: 04/29/2005**
75 WEST 126TH STREET MANHATTAN, NY TT−Id: 520A−0093−363

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2608 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:	JOHN HACK	Notifier Phone:	(917) 769−0483
Caller Name:	JOHN HACK	Caller Agency:	NEW YORK CITY FIRE DEPART	Caller Phone:	(917) 769−0483
DEC Investigator:	JMKRIMGO	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/17/2001		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

FIRE DEPARTMENT ON SCENE. ABOUT TWO FEET OF OIL AND WATER IN THE BASEMENT OF A MULTIPLE OCCUPANCY DWELLING. UNKNOWN CAUSE. UNABLE TO CONTACT BUILDING OWNER. CALLER IS REQUESTING A CALL BACK FROM DEC REPRESENTATIVE.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 7/17/01. J. Krimgold@ site. Spoke to FF J. Hack (Haz.Mat.). Homeowner cannot be found at this time. Basement floated with 2' of water. About 2 of oil is floating on the top of water. There are 2x275 gal tanks in the basement. Oil delivery of 150 gal was made today by Price Oil (718)824−6023, ticket # 18111, truck # 644. Probable spill cause is the tank overfill. FDNY requested to pump out water and oil from basement. J. Krimgold opened a PIN job and call Milro.

7/18/01. J. Krimgold spoke to the homeowner Ms. Lorraine Gobern (718) 231−1141, 1451 Stickney Pl, Bronx, NY 10469. She told me that she asked for the delivery of 150 gal of oil without checking the gauge. Her insurance co. Cambridge & Leach (718−756−4200, 660 Nostrand Ave, Brooklyn, NY), policy # cf3003298 denied her claim.

7/23/01. J.Krimgold spoke to Ray Gordon (Milro) via phone. Milro completed the cleanup, but basement flooded again due to a broken sewer pipes.

Map Identification Number 199 **MANHOLE 53842** **Spill Number: 0007704** **Close Date: 06/30/2004**
EAST 118 TH ST/1ST AVE MANHATTAN, NY TT−Id: 520A−0101−948

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 2610 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: EAST 118TH ST / FIRST AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN − Unknown	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MARK SCHLAGEL	Notifier Phone:	(212) 580−6763
Caller Name:	MARK SCHLAGEL	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	CALLER	Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/30/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	1.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

discovered 1 gallon of unk oil on top of 1000 gallons of water con ed 133698

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 133698:

1 gallon of unknown liquid mixed with water. He estimates a 1000 gallons of water in the manhole. As per conduit plate 50−K−3 it shows a sewer connection to the manhole.

date: 9−30−00 Time: 23:00 Cleanup Info: DOUBLE WASH FLOORS AND WALLS WITH SLIXX Spill Source: UNSEALED CABLE ENDS Leak Abatement Proc: SEAL ALL ENDS

Map Identification Number 200 **MANHOLE 53875** **Spill Number: 9913838** **Close Date: 11/16/2004**
1ST AVE/120TH ST MANHATTAN, NY TT−Id: 520A−0096−113

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2611 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 1ST AVE
Revised zip code: 10035

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	MR BOSZE	Notifier Phone:	(212) 338−3352
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/08/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	5.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

found 5 gals on 150 gals water −− sample taken − clean up pending results −− con ed 130304.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

e2mis no. 130304:

08−MAR−2000 09:15 MH.53867 E/S 1 AVE 209' N/O EAST 120 ST −− SPILL UNKNOWN OIL J. Rivera 16937, UGNo, while on location to splice feeder 3M58, found spill approx 5 gal unknown oil and 150 gal water in structure. No visual movement of liquids. No apparent impact to sewers or waterways. No smoke or fire. No visible cracks. Sump, sump pump and sewer connection not verified. Conduit plate not available to determine sewer connection. PILC oil filled cable in structure. ID sample taken by Rivera, tag # 10526 hung. Cleanup pending sample results.

03/09/00 , 10:15 AM CORRECT MANHOLE NUMBER IS #53875 AND LOCATION , E/S 1 AVE 209' N/O EAST 120 ST,WHERE THE SAMPLE WAS TAKEN FROM.

INCIDENT # 130304 , E/S 1 AVE 209' N/O EAST 120 ST , MH.53867 , 1.PPM DATE AND TIME THE CLEANUP COMPLETED : 03/09/00 , 13:00.
CLEANUP PROCEDURE : OIL AND WATER REMOVED VIA TANKER UNDER <50.PPM , WAS THEN DOUBLE WASHED WITH BIO−GENESIS SOLUTION (SLIX) , MANHOLE WAS THEN RINSED BY FLUSH TRUCK. QUANTITY REMOVED FROM SITE AND TYPE OF CONTAINER'S USED : THREE PLASTIC BAG'S NON−HAZARDOUS WASTE (PPE& ABSORBENT PAD'S,TARP,RAG'S). TRANSPORTATION TO EAST 110 ST YARD (MANHATTAN) PLACED IN A UNDER <50.PPM ACCUMULATION DRUM AT INDUSTRIAL WASTE TEMP AREA. ASTORIA CORPORATE TRANSPORTATION TANKER UNDER <50.PPM ACCUMULATION 1,400 GALLON'S OIL AND WATER MIXTURE. SPILL TAG REMOVED UPON COMPLETION.

Map Identification Number 201 **MANHOLE 53880** **Spill Number: 9913836** **Close Date: 11/16/2004**
1ST AVE/E120TH ST MANHATTAN, NY TT−Id: 520A−0096−112

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2611 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / 1ST AVE
Revised zip code: 10035

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Affected Persons	Notifier Name:	STEVE BOSZE	Notifier Phone:	(212) 338−3352
Caller Name:	RICHARD ROACH	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/08/2000		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	2.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

found 2 gals on 150 gals water −− sample taken − clean up pending results −− con ed 130303.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

e2mis no. 130303:

08−MAR−2000 09:15 −− E/S 1AV 503' N/O E.120ST L.Morales#74700 splicer underground reports spill approx 2−gallons unknown oil mixed with 150−gallons water in MH−53880....No visual movement of fluid....no smoke or fire.....unable to verify sump....unable to verify sewer connection due to no conduit plate available.... ID sample taken by L.Morales....Sign# 17693 placed.....Underground crew on location to splice fdr−3m58

LAB RESULTS Lab Seq#00−02172 Aroclor None PCB 1.00 ppm 3/8/00

03/09/00, 10:30 AM CORRECT MANHOLE NUMBER IS # 53873 AND LOCATION − E/S 1 AVE 250' N/O EAST 120 ST, WHERE SAMPLE WAS TAKEN FROM.

INCIDENT # 130303 , E/S 1 AVE 250' N/O EAST 120 ST , MH.53873 , <1.PPM DATE AND TIME THE CLEANUP COMPLETED : 03/09/00 , 13:30. CLEANUP PROCEDURE : OIL AND WATER REMOVED VIA TANKER UNDER <50.PPM , WAS THEN DOUBLE WASHED WITH BIO−GENESIS SOLUTION (SLIX) , MANHOLE WAS THEN RINSED BY FLUSH TRUCK. QUANTITY REMOVED FROM SITE AND TYPE OF CONTAINER'S USED : FOUR PLASTIC BAG'S NON−HAZARDOUS WASTE− (PPE & ABSORBENTPAD'S,TARP) TRANSPORTATION TO 110 ST YARD (MANHATTAN) PLACED IN A UNDER <50.PPM ACCUMULATION DRUM AT INDUSTRIAL WASTE TEMP AREA. ASTORIA CORPORATE TRANSPORTATION TANKER UNDER <50.PPM ACCUMULATION 575 GALLON'S OIL AND WATER MIXTURE. SPILL TAG REMOVED UPON COMPLETION.

Map Identification Number 202 **MANHOLE 53864** **Spill Number: 9900785** **Close Date: 06/11/2002**
E 120TH ST / 1ST AVE MANHATTAN, NY TT−Id: 520A−0096−111

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2611 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	MR ROMANO	Notifier Phone:	(212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	BILL MURPHY	Contact Person Phone:	(212) 580−6763

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/21/1999		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	3.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

3 GAL OF OIL FOUND ON 150 GAL OF WATER. CONTAINED IN THE MANHOLE. SAMPLE WAS TAKEN AND CLEAN UP PENDING LAB RESULTS. CON ED 124−356.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS NOTES 5−04−99

Found approx. 3 gals. of unknown oil on approx. 150 gals of water. in MH#53864 oil contained to MH. No sewers or waterways affected. Cracks and sump, or sewer connection unknown.

Aroclor #1254, PCB count <1.0ppm

Cleanup started on 4−22−99 16,220 gals. removed via 5 tankers. Additional 18,000 removed via 7 tankera NYCDEP notified there is water leak in area, job pending water main repair.

4−28−99 DEP notifies R. O'Neil water main has been repaired.

4−29−99 3500 gals. water via tanker. Water level went down 2−ft and immediately rose when pumping stopped. DEP will be notified that problem has not been corrected.

Update E−mail: Cleanup Completion information: This is the latest update I have relating to 120th and 1 Ave spill report. Attached to this e−mail is the CHEMLIMS report of the sampling done on 03/30/00. The water quality for all of the test that were run met all the DEPs requirements to discharge to a public sewer. Specifically, relating to the oil spill originally reported, the oil and grease results were non−detect. The manhole is consider clean and the spill can be closed internally.

−−−−−Original Message−−−−− From: O'Neill, Robert Sent: Thursday, April 20, 2000 9:52 AM To: Ramon, Richard; Fenner, Wendell Cc: Torres, Carlos D.; DeStefano, Joseph; Cioffi, Steve Subject: RE: By Joseph DeStefano 00−03053 Rich This job has changed direction somewhat in the last month. In order to complete the feeder work prior to the summer load period, new conduit has been diverted around the structure. The plan is still to rectify the water problem in this hole. On of the structural engineers would like to get a look at the hole with the water down. In the past, I have been able to get the water down prior to pumping 10,000 gallons. Can we pump less than 10,000 gal without a hassle. This would permit the engineers to evaluate the hole. Robert O'Neill OGS Manhattan Services 212−427−5473 −−−−−Original Message−−−−− From: Ramon, Richard Sent: Thursday, April 20, 2000 9:46 AM To: Fenner, Wendell; O'Neill, Robert Subject: FW: By Joseph DeStefano 00−03053

Sampling results were sent to Sophia Rabich on April 12 − I spoke to her today and she hadn't gotten to it yet. I'll call her next week to remind her if necessary. I soon as I get approval from Pravin Patel, I send to Quantity group. We'll probably have to meet with the quantity group as we have for the previous >10,000 gpd discharges.

Description: MH #53864 TOP ANALYZED: SAMPLE TYPE: WATER Test Test Description Result Units Description Result Units −−−−−−−−−−−− −−−−−−− −−−−− −−−−−−−−−− −−−−−− −−−−− Cadmium <0.005 mg/L Chromium <0.005 mg/L Copper 0.02 mg/L Lead <0.005 mg/L AROCLOR 1016 <0.065 ug/L Manganese AROCLOR 1221 <0.065 ug/L Mercury <0.001 mg/L AROCLOR 1232 <0.065 ug/L Molybdenum

AROCLOR 1242 <0.065 ug/L Nickel <0.01 mg/L AROCLOR 1248 <0.065 ug/L Silver AROCLOR 1254 <0.065 ug/L Vanadium AROCLOR 1260 <0.065 ug/L Zinc 0.07 mg/L Cyanide <0.02 mg/L Fluoride TRPH <0.4 mg/L Analyzed by: EcoTest Laboratories, Inc. ELAP# 10320

Flash Point >100 deg C

Cadmium <0.005 mg/L Chromium <0.005 mg/L Copper 0.01 mg/L Lead <0.005 mg/L AROCLOR 1016 <0.065 ug/L Manganese AROCLOR 1221 <0.065 ug/L Mercury <0.001 mg/L AROCLOR 1232 <0.065 ug/L Molybdenum AROCLOR 1242 <0.065 ug/L Nickel <0.01 mg/L AROCLOR 1248 <0.065 ug/L Silver AROCLOR 1254 <0.065 ug/L Vanadium AROCLOR 1260 <0.065 ug/L Zinc 0.06 mg/L Cyanide <0.02 mg/L

TRPH <0.4 mg/L Analyzed by: EcoTest Laboratories, Inc. ELAP# 10320

ANALYTE RESULTS UNITS −−−−−−− −−−−−−− −−−−− Flash Point >100 deg C

Map Identification Number 203 **VS2027 VAULT** **Spill Number: 1000204** **Close Date: 05/21/2010**
1RST AVE AND EAST 120ST NEWYORK, NY TT−Id: 520A−0249−423

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 2611 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: 1ST AVE / E 120TH ST
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RWAUSTIN	Contact for more spill info:	ERT	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Any Type of RP Including No RP − No DEC Field Response − Corrective Action by Spill Response Not Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/06/2010		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	9.00	GALLONS	0.00	GALLONS	

Caller Remarks:

nine gals. unknown oil on 500gals. water/spill and water contained to vault area

DEC Investigator Remarks:

5/21/10 − Austin − Transformer bushing leak, unit replaced − Contained and cleaned up by Con Edison − see eDocs for further info − spill closed − end

CLOSED STATUS HAZARDOUS SPILLS − MISC. SPILL CAUSES − EQUIPMENT FAILURE, HUMAN ERROR, TANK OVERFILL, DELIBERATE SPILL, TRAFFIC ACCIDENT, HOUSEKEEPING, ABANDONED DRUM, VANDALISM AND STORMS − WITHIN 1/2 MILE SEARCH RADIUS.
All spills mapped and profiled within 1/8 mile. Between 1/8 mile and 1/2 mile search radius, spills reported to be greater than 100 units and spills reported in the NYSDEC Fall 1998 MTBE Survey are mapped and profiled. Spills reported to be less than 100 units are listed in a table at the end of this section.

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 204 **TRUCK** **Spill Number: 1301696** **Close Date: 06/03/2013**
NEAR EAST 120TH AND PARK NEW YORK, NY TT−Id: 520A−0292−057

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / PARK AVE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name:
DEC Investigator: SMSANGES

Spiller: ROBERRO EXPRESS
Notifier Name:
Caller Agency:
Contact for more spill info: KEARNEY

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (347) 203−6886

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/20/2013		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	

Caller Remarks:

onto street, unk sewers, fdny is on scene, contained

DEC Investigator Remarks:

See also spill # 1301722 (Con Ed vault impacted by this spill)

Map Identification Number 205 **120 EAST 119TH STREET** **Spill Number: 9210790** **Close Date: 03/31/1995**
120 EAST 119TH STREET MANHATTAN, NY TT−Id: 520A−0096−082

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 382 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:		Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	OFFICER MCKAY	Caller Agency:	NYCPD−25TH PRECINT	Caller Phone:	(212) 860−6511
DEC Investigator:	ADZHITOM	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/07/1992	03/31/1995	HUMAN ERROR	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	10.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OVER ORDERED−SPILL INTO DRAINAGE AND ON PAVEMENT−WERE WASHED DOWN MARK TIBBE WAS NOTIFIED

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

10/31/2005 Transferred this spill report from Mark Tibbe to AZ. 25th Police Precinct remediated by URS. Permeox injected. ORC socks installed.Dissolved gw plume (report dated June 6, 2005 −reviewed). AZ

Map Identification Number 206 **132 E 119TH ST** **Spill Number: 0504233** **Close Date: 11/09/2005**
132 E 119TH ST MANHATTAN, NY TT−Id: 520A−0097−569

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 477 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	SCOTT JAFFREY	Spiller Phone:	(718) 246−0018
Notifier Type:	Fire Department	Notifier Name:	CAPT DON MURPHY	Notifier Phone:	(718) 430−4241
Caller Name:	CAPT DON MURPHY	Caller Agency:	FDNY	Caller Phone:	(718) 430−4241
DEC Investigator:	JXZHAO	Contact for more spill info:	CHIEF	Contact Person Phone:	(212) 570−4235

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/10/2005		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

550 gallon tank. Unknown how much leaked in basement. Fuel Oil went down drain in the middle of the floor. Call the Chief.

DEC Investigator Remarks:

Sangesland found owner via Property Shark No PBS on this site (tank was 550 gal)

8/10/2005 Modified Contaminated Soil/TTF letter sent to:

Scott Jaffee Metropolitan Realty Group 116 Court St. #1105 Brooklyn, NY 11241

Letter tells Mr Jaffee to identify any contamination which may have gone below the basement floor. Oil flowed into a floor drain in the basement. Unknown if this drain is a dry well or hooked up to the sewer.

Map Identification Number 207 **MANHOLE 42069** **Spill Number: 0505459** **Close Date: 01/10/2006**
SE CRNR 117THST/PARK AVE MANHATTAN, NY TT−Id: 520A−0093−591

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 538 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: E 117TH ST / PARK AVE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON EDISON 151710	Spiller Phone:	
Notifier Type:	Other	Notifier Name:	MR PAGANO	Notifier Phone:	(212) 580−6763
Caller Name:	CHRIS SHIKARIVES	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	SKARAKHA	Contact for more spill info:	ERT DESK‘	Contact Person Phone:	(212) 580−8383

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/04/2005		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CABLE OIL	PETROLEUM	0	GALLONS	0	GALLONS	SOIL

Caller Remarks:

1 pint of cable oil onto concrete floor in manhole. no to 5 question. clean pending de−energerization of feeder.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 208 **113 EAST 117TH STREET** **Spill Number: 9415276** **Close Date: 02/22/1995**
113 EAST 117TH STREET MANHATTAN, NY TT−Id: 520A−0096−084

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 543 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	INSTITUTIONAL, EDUC, GOV, OTHER	Spiller:	SAME	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	0ROCKY VENUTO	Caller Agency:	GOTHAM PEETRO	Caller Phone:	(718) 389−8100
DEC Investigator:	MMMULQUE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/22/1995	02/22/1995	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	2.00	GALLONS	2.00	GALLONS	SOIL

Caller Remarks:

VENT ALARM WASN'T WORKING− TAN K WAS FULL

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN

Map Identification Number 209 **ST PAULS RECTORY** **Spill Number: 0608531** **Close Date: 03/21/2007**
113 EAST 117TH STREET NEW YORK, NY TT−Id: 520A−0090−349

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 543 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ROBB HILL − TNS TRUCKING	Spiller Phone:	(914) 403−1690
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	SFRAHMAN	Contact for more spill info:	CLAUDIA	Contact Person Phone:	(212) 534−4422

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/25/2006		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	120.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

DURING A DELIEVERY FROM AN OUTSIDE CARRIER THERE WAS A SPILL DUE TO THE OIL CAP ON TOP OF TANK NOT BEING SECURED: ROBB HILL FROM CASTLE OIL IS ON SITE: THE MATERIAL IS CONTAINED IN BASEMENT OF RECTORY IN TANK ROOM:

DEC Investigator Remarks:

10/30/06 Rahman− I responded to the site on 10/25/06 afternoon. Approx. 100 gal came out of the top of the tank and small part out of the vent.Oil was all over the floor and travelled to a 8x10’ pit .I noticed oil was sinking to the pit. PTC was hired to do the clean up. 12/19/06 Rahman− PTC did soil borings to investigate the subsurface contamination caused by the oil spill.I spoke with Mr. Stewart of St. Paul’s Church, he indicated that there is no petroleum odor in the basement. 03/21/07 Rahman− Soil boring results are on edocs.Subsurface contamination was not found by th e investigation.Spill was cleaned by PTC and Castle Oil personnel.NFA requied.

Map Identification Number 210 **119TH ST.& LEXINGTON AVE.** **Spill Number: 8704606** **Close Date: 09/02/1987**
119TH ST. & LEXINGTON AVE NEW YORK CITY, NY TT−Id: 520A−0093−386

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 631 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 119TH ST. / LEXINGTON AVE
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Federal Government	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	UNASSIGNED	Contact for more spill info:		Contact Person Phone:	

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/02/1987	09/02/1987	EQUIPMENT FAILURE	UNKNOWN	NO

NO MATERIAL INFORMATION GIVEN FOR THIS SPILL

Caller Remarks:

LEAKY VALVE ON TANK ON CORNER

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was

10/10/95: This is additional information about material spilled from the translation of the old spill file: LIQUID NITROGEN.

Map Identification Number 211 **UNKNOWN RESIDENCE** **Spill Number: 1215698** **Close Date: 02/21/2013**
124 EAST 117TH ST MANHATTAN, NY TT−Id: 520A−1000−806

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 746 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ANTHONY LARA − STATEWIDE OIL CORP	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	vszhune	Contact for more spill info:	ANTHONY LARA	Contact Person Phone:	(917) 709−3317

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/19/2013		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	150.00	GALLONS	0.00	GALLONS	GROUNDWATER, SEWER

Caller Remarks:

loss during overfill, inside the building loss to basement drain

DEC Investigator Remarks:

02/18/13−Zhune responded to this site. Met Anthony Lara 917−709−3317 from Rite Way Tank. 150 gallons of oil #2 came by the vent pipe and it went to the drains and the pit of the elevator. An overfill caused the spill. State Wide brought the delivery today

to this site. The fill pipe is located in front of the building and the vent pipe is located in the middle of the building. Rite Way is going to vaccun the drains and clean the spill under the elvator. DEP notified.

02/18/13−Zhune spoke to Michael Savino from State Wide 718−858−9000. He said a faulty gauge caused the spill.

Owner of the building: Jura 516−510−1478 Super− Peter 917−204−4593

02/21/13−Zhune called Anthony Lara. he said spill was washed down. Everything is cleaned. There was litle of oil under the elevator but it was washed down. Spoke to Peter(super). He said everything is cleaned. Spill closed

Map Identification Number 212 **1883 MADISON AVE** **Spill Number: 9111042** **Close Date: 11/22/1994**
1883 MADISON AVE MANHATTAN, NY TT−Id: 520A−0091−863

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 955 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	SAME	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	R HOUSTON	Caller Agency:	BAERENKLAU	Caller Phone:	(718) 647−4200
DEC Investigator:	SIGONA	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/24/1992	11/22/1994	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

MILRO SERVICES TO CLEAN UP.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 213 **49 WEST 119TH ST/MANH** **Spill Number: 8907609** **Close Date: 01/12/2004**
49 WEST 119TH STREET NEW YORK CITY, NY TT−Id: 520A−0093−581

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1393 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Spiller: ALMAR FUEL OIL
Spiller Phone: (718) 438−6676
Notifier Type: Affected Persons
Notifier Name:
Notifier Phone:
Caller Name: MRS. ALEXANDER
Caller Agency: CITIZEN
Caller Phone: (718) 978−0085
DEC Investigator: RWAUSTIN
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/30/1989		TANK OVERFILL	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	250.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FUEL COMPANY DELIVERED OIL TO THE WRONG BLDG, SPILL CONTAINED IN

BASEMENT, SPEEDY DRY APPLIED.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 1/12/04 − AUSTIN − SURF. SPILL FROM 14 YRS. AGO − CLOSED − ORIG. ASSIGNED TO FINGER − END

Map Identification Number 214 **APARTMENT BUILDING** **Spill Number: 9411587** **Close Date: 10/09/2015**
42 WEST 120TH ST NEW YORK, NY TT−Id: 520A−0093−583

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1404 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Spiller: BOB DECK − APARTMENT BUILDING
Spiller Phone:
Notifier Type: Other
Notifier Name:
Notifier Phone:
Caller Name: BOB DECK
Caller Agency: PETROL TANK CLEANERS
Caller Phone: (718) 624−4842
DEC Investigator: vszhune
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/30/1994		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

SPEEDY DRY USED−WILL PUT INTO DRUMS ETC.

DEC Investigator Remarks:

Information request letter sent to Tahl−Propp Equities 11/04/05. Heitzman

Spill transferred back to R−2

3/7/08 − Austin − Assigned to Ketani for further investigation − end

7/15/08 − Raphael Ketani. The spill happened on 11/30/94. About 100 gal. of #4 oil was spilled. The oil was cleaned up and the spent absorbent was put into drums.

There is just one letter in the paper file. It is dated November 4, 2005 and is the same letter that I found in the E−docs. There were no other documents available.

There is no PBS record.

The site is block and lot 1718 and 53. Alternate addresses are 42−44 W. 120 Street. The owner of record is 40−44 West 120 Street Associates, LLC, c/o Tahl−Propp Equities, 405 Park Avenue, Ste 1103, NY, 10022−9410. I tried the alternate address and still couldn't find a PBS record.

I sent a CSL.

8/18/08 − Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The case manager should find out whether a site investigation is taking place or whether an investigation plan has been written. The owners need to submit a PBS registration for the tanks.

10/27/11 − Austin − Transferring this case from Ahmed to Zhune − end

04/03/13− Zhune called to Tahl Propp and spoke to Lona Dutan (office manager). She said Chris Spring is the main person to speak regarding this matter. He is on vacation. He will return on Monday 04/08/12. A message was left in his voice mail.

Chris Spring 212−421−1117 Ext. 122 212−996−0200 Ext. 221 cspting@tahl propp.com

10/9/15−Zhune inspected the site. Zhune met Mike the superintendent 646−210−6775. During my inspection I observed no staining, no visual or olfactory evidence of petroleum contamination. The area of the tank and the sump and the area of the boiler was cleaned. No drums at the site. As per J.Vought spill is closed.

The site is being manage by Star Cities Management Jason or Hans − property managers 508−728−0508 Jason@starcities.com

Map Identification Number 215 **42 WEST 120TH ST/CIBRO** **Spill Number: 8803777** **Close Date: 11/06/2001**
42 WEST 120TH STREET NEW YORK CITY, NY TT−Id: 520A−0093−580

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1404 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	PRIVATE DWELLING	Spiller:	CIBRO	Spiller Phone:	
Notifier Type:	Fire Department	Notifier Name:		Notifier Phone:	
Caller Name:	FIREMAN SMITH	Caller Agency:	NYCFD/HAZ MAT	Caller Phone:	(212) 847−0588
DEC Investigator:	TOMASELLO	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/29/1988	11/06/2001	TANK OVERFILL	YES	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	300.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FUEL TANK, SPILL IN BASEMENT, FOAMED SPILL, OWNER & SUPERINTENDANT NOTAVAILABLE.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

11/06/01: MF−R9 ANOTHER SPILL AT THIS SITE 9313894, CLOSED, ANOTHER SPILL 9411587 OPEN. NO FURTHER INFO ON THIS SPILL, 8803777, NOTHING IN FILE. DEAD ISSUE. NO FURTHER ACTION POSSIBLE. **********COMPUTER FILE**********

Map Identification Number 216 **VAULT #5033** **Spill Number: 9910337** **Close Date: 02/06/2004**
1695 MADISON AV MANHATTAN, NY TT−Id: 520A−0092−673

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1463 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CON ED	Spiller Phone:	(212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	MR RUSSO	Notifier Phone:	(212) 338−3352
Caller Name:	STEVEN CRIBBIN	Caller Agency:	CON ED	Caller Phone:	(212) 580−8576
DEC Investigator:	COMENALE	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/29/1999		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
TRANSFORMER OIL	PETROLEUM	150.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

LEAKING TRANSFORMER IN VAULT − UNK IF ANY SEWERS WERE EFFECTED SAMPLES WAS CLEAN UP PENDING WHEN THE FEEDER IS GROUNDED − CON ED #129120 − NO VISABLE CRACKS IN THE VAULT AND THE SUMP PUMP WAS NOT RUNNING WHEN THE SPILL WAS FOUND

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 217 **MORRIS PK SENIOR CITIZENS** **Spill Number: 9313540** **Close Date: 02/23/1994**
17 EAST 124TH STREET MANHATTAN, NY TT−Id: 520A−0092−036

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1518 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Responsible Party
Caller Name: ED MALONE
DEC Investigator: SIGONA
Spiller: NYCHA
Notifier Name:
Caller Agency: NYCHA
Contact for more spill info:
Spiller Phone: (212) 722−7880
Notifier Phone:
Caller Phone: (212) 306−8480
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
02/17/1994	02/23/1994	EQUIPMENT FAILURE	2−475165	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	292.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

DURING A FUEL DELIVERY THEY NOTICED THEY HAD A LEAKING PIPE. BRINGING IN WINSTON CONTRACTING TO CLEAN IT UP. NO OTHER AGENCIES NOTIFIED, NO CALL BACK NECESSARY.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 218 **MORRIS PARK SENIOR CIT.** **Spill Number: 9309711** **Close Date: 12/28/1993**
17 EAST 124TH STREET MANHATTAN, NY TT−Id: 520A−0092−007

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1518 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	NYCHA	Spiller Phone:	(212) 722−7880
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	FRANK OCELLO	Caller Agency:	NYCHA	Caller Phone:	(212) 306−3142
DEC Investigator:	HEALY	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

---

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
11/10/1993	12/28/1993	HUMAN ERROR	2−475165	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

GASKET ON BOILER DID NOT HOLD. HAZMAT NOTIFIED. WINSTON ON SCENE CLEANING UP SPILL. APPROX. 40 GALLONS ENTERED SUMP PIT.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 219 **SPILL NUMBER 9810692** **Spill Number: 9810692** **Close Date: 11/23/1998**
1944 MADISON AV MANHATTAN, NY TT−Id: 520A−0099−428

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1565 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: TANK TRUCK
Notifier Type: Other
Caller Name: DON MCGINNIS
DEC Investigator: TOMASELLO

Spiller: CHARLIE PUGLISI − MYSTIC TRANSPORTATION
Notifier Name: SAL
Caller Agency: ACTION ENVIROMENTAL
Contact for more spill info: DON MCGINNIS

Spiller Phone: (718) 932−9075
Notifier Phone: (718) 932−9075
Caller Phone: (800) 948−6044
Contact Person Phone: (800) 948−6044

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/23/1998		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CALLERS COMPANY CONTACTED BY MYSTIC TRANSPORTATION FOR CLEAN UP AT THE ABOVE SPILL SITE − CALLER STATED THAT A MYSTIC DRIVER EITHER DELIVERED TO THE WRONG RESIDENCE OR FILLED THE WRONG TANK OVERFILLING THE TANK AND SPILLING THE OIL TO THE GROUND − CLEAN UP CREWS ARE ENROUTE TO THE SITE AND THE FDNY IS ON SCENE / CROSS REFERENCE #9810690 SPILL WAS ALREADY REPORTED BUT THE SPILLER INFORMATION WAS DIFFERENT AND THE CALLER WAS NOT NOTIFIED OF THE REPORT

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 220 **MT MORRIS PARK BATH HOUSE** **Spill Number: 9810690** **Close Date: 11/23/1998**
1944 MADISON AVE MANHATTAN, NY TT−Id: 520A−0092−545

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1565 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name: DAVE WAGNER
DEC Investigator: TOMASELLO
Spiller: STYVESANT FUEL
Notifier Name:
Caller Agency: PETRO OIL
Contact for more spill info: MR MORRIS
Spiller Phone:
Notifier Phone:
Caller Phone: (718) 628−3323
Contact Person Phone: (212) 534−9004

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Unable or Unwilling RP − DEC Field Response − DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/23/1998		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	500.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

THE SPILLER MADE A DELIVER TO A WRONG ADDRESS CAUSING THE SPILL. HE THEN LEFT THE SCENE. APPROX 500 GALLONS BY CALCULATION,BUT CANNOT SEE THAT MUCH OIL.POSSIBLY ENTERED A SEWER. FDNY IS ON SCENE.SPILLER WAS CONTACTED AND SUPPOSEDLY THEY ARE CONTRACTING A CLEAN UP CREW.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 221 **1944 MADISON AVENUE** **Spill Number: 9507018** **Close Date: 03/08/2004**
1944 MADISON AVENUE NEW YORK, NY TT−Id: 520A−0092−207

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1565 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER | Spiller: COASTAL OIL | Spiller Phone:
Notifier Type: Affected Persons | Notifier Name: | Notifier Phone:
Caller Name: WALTER FITZER | Caller Agency: MOUNT MORRIS BATHS | Caller Phone: (212) 534−9004
DEC Investigator: SIGONA | Contact for more spill info: | Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
09/08/1995		TANK OVERFILL	2−096199	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	350.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OIL COMPANY FILLED THE WRONG TANK. OIL SPILLED AT THE BUILDING AND DAMAGED ALL THE RUGS. APPLIED DRY SORB, AND CLEANED IT UP

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 222 **STREET SPILL** **Spill Number: 0508072** **Close Date: 10/06/2005**
124TH ST 5TH AVE MANHATTAN, NY TT−Id: 520A−0092−821

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1589 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: E 124TH ST / 5TH AVE
Revised zip code: 10035

Source of Spill: COMMERCIAL VEHICLE | Spiller: MURATORE,ANTHONY − MTA BUS GARAGE | Spiller Phone: (347) 203−5477
Notifier Type: Responsible Party | Notifier Name: MURATORE, ANTHONY | Notifier Phone: (347) 203−5477
Caller Name: MURATORE, ANTHONY | Caller Agency: MTA | Caller Phone: (347) 203−5477
DEC Investigator: JBVOUGHT | Contact for more spill info: MURATORE,ANTHONY | Contact Person Phone: (347) 203−5477

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/06/2005		TRAFFIC ACCIDENT	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

diesel fuel spill as a result of a traffic accident. Actual amount was estimated to be full fuel tank. MTA has crews on scene now cleaning up spill

DEC Investigator Remarks:

10/06/05−Vought−Off hours duty responder. Performed site visit and Charles Ennis (MTA Bus) and Anna Peck (MTA Bus) also onsite. Spill amount was actually around 20 gallons. Spill on asphalt with no sewers or drains affected. Spill cleaned using adsorbent material. Spill closed by Vought.

Map Identification Number 223 **TAFT HOUSES −NYCHA** **Spill Number: 9100577** **Close Date: 04/15/1991**
1740 MADISON AVENUE NEW YORK, NY TT−Id: 520A−0095−998

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1605 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Responsible Party
Caller Name: NORMAN ZABUSKI
DEC Investigator: HEALY
Spiller: NYCHA
Notifier Name:
Caller Agency: NYCHA
Contact for more spill info:
Spiller Phone: (212) 876−4450
Notifier Phone:
Caller Phone: (212) 289−3940
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/15/1991	04/15/1991	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	300.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

BAD BYPASS VALVE, EPA NOTIFIED,WINSTON CONTRACTING TO DO CLEAN UP,DEC CONTACTED MIKE SIMONELLI,300GALS CONTAINED,SOME IN CATCH BASIN,

SITUATION UNDER CONTROL.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 224 **TAFT HOUSES −NYCHA** **Spill Number: 8809818** **Close Date: 11/17/1994**
1740 MADISON AVENUE NEW YORK, NY TT−Id: 520A−0095−997

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1605 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10029

Source of Spill:	TANK TRUCK	Spiller:	CASTLE COAL & OIL	Spiller Phone:	(212) 823−8800
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	MR. NISBETT	Caller Agency:	NYC HOUSING AUTHORITY	Caller Phone:	(212) 306−3129
DEC Investigator:	HEALY	Contact for more spill info:		Contact Person Phone:	

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
03/21/1989	11/17/1994	HUMAN ERROR	2−475025	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	1800	GALLONS	0	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

TANK OVERFILL.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 225 **WEST 115 ST** **Spill Number: 0010119** **Close Date: 05/10/2001**
BET 5TH AV & LENOX AV MANHATTAN, NY TT−Id: 520A−0101−502

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 1791 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: WEST 115TH ST
Revised zip code: NO CHANGE

Source of Spill:	UNKNOWN	Spiller:	UNKNOWN	Spiller Phone:	
Notifier Type:	Local Agency	Notifier Name:		Notifier Phone:	
Caller Name:	WAI MAN WONG	Caller Agency:	NYC DEP	Caller Phone:	(718) 595−4783
DEC Investigator:	TJDEMEO	Contact for more spill info:	WAI MAN WONG	Contact Person Phone:	(718) 595−4783

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/08/2000		ABANDONED DRUM	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
WASTE OIL/USED OIL	PETROLEUM	120.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

2 55 GALS DRUMS AND 1 5 GAL PAIL OF WASTE OIL DISCOVERED ON SIDEWALK IFO VACANT LOT

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 5/15/2001 TJD

Drum emptied 5/10/01

see spill#9930008 PIN#01036

Map Identification Number 226 **JOHNSON HOUSES** **Spill Number: 9303636** **Close Date: 06/23/1993**
165 EAST 165TH STREET NEW YORK CITY, NY TT−Id: 520A−0098−090

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 165 E 112TH ST
Revised zip code: 10029

Source of Spill: COMMERCIAL/INDUSTRIAL
Spiller: NYCHA
Spiller Phone: (212) 306−3142
Notifier Type: Local Agency
Notifier Name:
Notifier Phone:
Caller Name: MR GREENE
Caller Agency: NYC DEP
Caller Phone: (718) 595−6700
DEC Investigator: HEALY
Contact for more spill info:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
06/21/1993	06/23/1993	VANDALISM	2−474967	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	300.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

NYCDEP AND FD ON SCENE TO INVESTIGATE. VANDALS OPENED FEEDER VALVE TO DONKEY BOILER AND SPILLED 50 TO 60 GALS OF #2 OIL ON SIDEWALK AND STREET. CONTRACTER CALLED IN TO DO CLEANUP.

DEC Investigator Remarks: DEC INVESTIGATOR REMARKS NOT AVAILABLE FOR THIS SPILL ACCORDING TO THE LAST UPDATE.

The following DEC Investigator Remarks were available prior to 1/1/2002:

06/23/93: SITE INSPECTION DONE 6/22/93. CLEAN−UP BY WINSTON CONTRACTING COMPLETE. DEP HAS NO FURTHER ISSUES.

Map Identification Number 227 **163 E.112TH ST. NYC./NO.2 O** **Spill Number: 8606210** **Close Date: 08/21/1987**
163 E. 112TH ST. MANHATTAN, NY TT−Id: 520A−0098−089

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1792 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING
Notifier Type: Fire Department
Caller Name:
DEC Investigator: UNASSIGNED
Spiller: BUILDING SUPER NO. − N.Y. HOUSING ATHORITY
Notifier Name:
Caller Agency:
Contact for more spill info:
Spiller Phone: (212) 427−4808
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/05/1987	08/21/1987	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	250.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

OIL BURNER BLEW UP CAUSING TANK TO RUPTURE, OIL IN BASEMENT

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Map Identification Number 228 **HARLEM DAY CHARTER SCHOOL** **Spill Number: 0810730** **Close Date: 02/23/2009**
230 E 123RD ST MANHATTAN, NY TT−Id: 520A−0224−019

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 1867 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	BUILDING SUPER	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	hrpatel	Contact for more spill info:	JAMES MORRIS	Contact Person Phone:	(374) 203−6886

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/26/2008		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	1000	GALLONS	0	GALLONS	

Caller Remarks:

boiler exploded, ruptured supply line, spilling 1000 gallons onto floor, there was a sump pump, running that has been shut down, unsure how much that discharged into sewer, haz mat and super have been attempting to get clean up crew enrout.

DEC Investigator Remarks:

12/26/08−Hiralkumar Patel. visited site. met Mr. Diaz, property manager. found oil and water on boiler room floor. site occupies entire block between 2nd and 3rd ave and between 122nd and 123rd street. site has four boilers for entire block. boiler room is located in basement at 230 E 123rd Street. part of one of the boiler blew up and broke supply line that was ruuning adjacent to the boiler. oil started leaking from supply line. odors inside boiler room. FDNY received odor complaint from tenant. they checked each floor and confirmed no more odors. super openened some doors on floors and ventilation on roof. all boilers are turned off. as per Mr. Diaz, building has heat backup for six hours. could not inspect boiler room floor as entire room is filled with oil and water.

building super mentioned that alongwith oil supply line, natural gas line also broke in this incident, but due to automatic shut off valve, no leak inside basement. asked Mr. Diaz to pump out oil and water from boiler room and to consult with boiler company and ConEd before turning remaining three boilers on.

spoke with Eric Gruber, insurance broker. he hired Branch Services to pump out oil/water.

site also has Harlem Day Charter School on street level, close to boiler room. school was closed and will be closed for next week.

site has three 20,000 gal USTs enclosed in concrete box under a street sidewalk along E 123rd street. observed three monitoring wells at the edge of tank vault, along E 123rd st.

alternate addresses:

200−218 E 123rd St, 220−222 E 123rd St, 224−244 E 123rd St

2383−2389 2nd Ave, 2391−2395 2nd Ave

219−223 E 122nd St, 201−217 E 122nd St, 231−265 E 122nd St

2243−2261 3rd Ave

Tiano Towers

property owner Acro Management

management company 2253 3rd Avenue, 5th Floor New York, NY 10035 Attn.: Manny Diaz

property manager PH. (212) 369−3755 (O)

(917) 681−3213 (C) Fax (212) 369−6215 email: mdiaz@multifamilymgt.com

Miguel Soto

building super Ph. (917) 682−6838

Eric Gruber Ben Gruber, Inc. Public Adjuster Ph. (845) 621−4600 (O)

(917) 295−1406 (C) Fax (845) 621−4613

Branch Services

cleanup company Ms. Malony Ph. (631) 767−4428

PBS #: 2−240680. found PBS expired in 10/1997. tanks are due for tightness test.

spoke with Mr. Diaz (at 10:45 AM) regarding PBS renewal and tank test. asked him to test all three tank systems by end of next week (01/02/09). they are still waiting for vacuum truck and as per Mr. Diaz, truck will be on−site in next half hour.

found another open spill case. Spill #: 0000963.

spoke with Mr. Diaz regarding open tank test failure reported in April 2000. Mr. Diaz mentioned that during that time, they re−lined all three tanks and during that work, small amount of contamination found on top of one tank. Mr. Diaz mentioned that tanks are in concrete box, covered with sand, under sidewalk. asked Mr. Diaz to submit paper work for such work done in 2000. mentioned to him, that if no documents available for such work, then based on tank test failure complaint, the department may require soil delineation around tank system. also asked Mr. Diaz to renew PBS registration and submit tank system test result for all three tanks, by end of 01/02/09. told him that if tank test results will not be submitted by end of 01/02/09, then the department will issue notice of violation (as management was informed about expired PBS in 2006 while working on spill #: 0514031).

sent email to Mr. Diaz with above requirements alongwith PBS renewal form.

12/29/08−Hiralkumar Patel. received message from Scott Hamarich from Eastern environmental. spoke with Scott at eastern. he responded for cleanup and removed about 10,000 to 11,000 gal of oil/water mix from basement on 12/26/08. they returned to site on 12/27 and 12/28/08 for powerwashing the floor. still doing that today. Scott mentioned that these all caused by a natural gas blast in one of the boiler, which was shifted about 3 ft away from its position and damaged all lines. there is no heat or hot water in entire building since 12/26/08.

Scott Hamarich Eastern Environmental Ph. (631) 774−9821 (C)

(631) 727−2700 (O) email: scotthamarich@easternenviro.com

discussed case with DEC Susan, regional direction and DEC Vought. DEC Susan asked for PID survey inside a school building and proper ventilation.

visited site. met Mr. Diaz and Mr. Gruber. inspected boiler room floor. minor cracks found in floor. found multiple floor drains inside boiler room and all connects to sump in corner. sump was disconnected. Eastern was removing water from sump using vacuum truck.

spoke with Scott at eastern environmental. asked him to inspect each corner of boiler room for any cracks in floor and if finds major cracks, then required soil samples. also asked him for PID survey inside entire school and submission of report for such survey. asked Scott to do PID survey in school building twice; one on tomorrow (12/30/08) and second on saturday (01/03/09). Scott has scheduled tank test on wednesday (12/31/08).

spoke with Jerry Baquero (646−884−3300, building incharge) and Anne Burns (646−510−1613, head of the school) and informed them regarding current condition. informed them that contractor will do PID survey in school building.

12/31/08−Hiralkumar Patel. spoke with Scott. they have finished cleanup inside boiler room. did PID survey in school building and found nothing. will do tank test today.

01/06/09−Hiralkumar Patel. spoke with Scott. they did another PID survey in school on 01/02/09 and found nothing. all tanks passed test. will submit report by end of 01/16/09.

01/22/09−Hiralkumar Patel. spoke with Mr. Diaz. asked him to submit cleanup report for recent spill, report for work done in 2000 to correct tank system leak and PBS renewal copy by the end of 01/30/09. told him that if the department doesn’t receive these documents by 01/30/09 then may issue notice of violation.

02/03/09−Hiralkumar Patel. received tank test result for all three tank. tanks passed the test.

spoke with Manny and Scott. asked Manny to submit cleanup report for recent spill by end of 02/06/09 and copy of tank repair work done in 2000 by end of 02/13/09. Scott mentioned that PBS application is ready and will send to Albany. will send copy of PBS renewal application.

02/06/09−Hiralkumar Patel. received email from Scott with tank test results. all three tanks passed the test. tank testing result forwarded to DEC Jacob for review and PBS record.

02/20/09−Hiralkumar Patel. spoke with Manny. remind him to submit report.

PBS registration hasn't renewed yet.

issued notice of violation for following reasons:

− failure to renew registration (registration expired on 10/23/1997) − failure to color code fill ports − failure to test tank/piping (no tank test record available from 11/01/1997 to 03/15/2006) − failure to monitor unmetered tank for leaks − failure to notify of petroleum discharge (spill was reported by FDNY, but not by management) − failure to contain and/or remove petroleum discharge (property manager claims that spill was cleaned out properly, but no reports available)

sent notice of violation in mail (7005 1820 0007 9827 6042) and copy emailed to Mr. Diaz and Scott.

02/23/09−Hiralkumar Patel. received cleanup report for recent spill in boiler room. based on submitted document, no further action required in reference to recent spill on 12/26/08. the department still waiting for documents regarding previous spill #: 0000963 (tank test failure reported in 2000).

case closed.

Map Identification Number 229 **METRO NORTH** **Spill Number: 8600055** **Close Date: 04/02/1986**
126TH ST. & PARK AVE. NEW YORK CITY, NY TT−Id: 520A−0093−385

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 1874 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: E 126TH ST. / PARK AVE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	METRO NORTH	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RJSCHOWE	Contact for more spill info:		Contact Person Phone:	

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/31/1986	04/02/1986	TRAFFIC ACCIDENT	UNKNOWN	NO

NO MATERIAL INFORMATION GIVEN FOR THIS SPILL

Caller Remarks:

VIADUCT ONTO STREET−SPEEDI DRY APPLIED−REST EVAPORATED &SOAKED INTO TRACKS

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SOHOWE 10/10/95: This is additional information about material spilled from the translation of the old spill file: KEROSENE(#1 FUEL OIL

3/3/86:

CLOSED.

Map Identification Number 230 **CON ED FACILITY** **Spill Number: 0301202** **Close Date: 05/06/2003**
32 W 125TH ST MANHATTAN, NY TT−Id: 520A−0093−368

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2017 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	PAUL DIDONATO − CON EDISON	Spiller Phone: (212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	CURTIS	Notifier Phone: (212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone: (212) 580−6763
DEC Investigator:	AERODRIG	Contact for more spill info:		Contact Person Phone:

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/02/2003		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
FREON	OTHER	100.00	POUNDS	0.00	POUNDS	AIR

Caller Remarks:

r414 released to air − discovered while working on air compressor

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ e2mis 148189

32 W 125 St Cust. serv. Bldg. 02−MAY−2003 @13:00 hrs Peter Elgner #80947,Operating Supervisor,Facilities Services Reports that Matceo A.C Corp. (516) 876−9100 was seviceing unit and discoverd that 100 lbs of freon R414. HOT SHOT reason for sevice was for summer season. has leaked from AC unit #2 in basement of 32 W125 st. at this time repairs are pending freon CIG called @13:53 hrs McCarthy #06416 Logger F.Curtis . Update: 02−MAY−2003 @17:00 hrs No sewers or waterways affected by this incident. No injuries related to this incident. Weather conditions did not contribute to this incident. Source of spill is unknown. Cause of spill is unknown. No fire or smoke involved in this leak Private property not affected by this incident.

Map Identification Number 231 **CON ED FACILITY** **Spill Number: 0301201** **Close Date: 05/06/2003**
32 W 125TH ST MANHATTAN, NY TT−Id: 520A−0093−367

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2017 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	PAUL DIDONATO − CON EDISON	Spiller Phone:	(212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	CURTIS	Notifier Phone:	(212) 580−6763
Caller Name:	BILL MURPHY	Caller Agency:	CON EDISON	Caller Phone:	(212) 580−6763
DEC Investigator:	AERODRIG	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/02/2003		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
FREON	OTHER	100.00	POUNDS	0.00	POUNDS	AIR

Caller Remarks:

material released to aptmosphere − discovered while working on the compressor

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ e2mis 148188

02−MAY−2003 32 W 125 St Cust. serv. Bldg. @13:00 hrs Peter Elgner #80947,Operating Supervisor,Facilities Services Reports that Matceo A.C Corp. (516) 876−9100 was seviceing unit and discoverd that 100 lbs of freon R12. Reson for service was for summer season.

has leaked from AC unit #1 in basement of 32 W125 st. at this time repairs are pending freon . Update: 02−MAY−2003 @17:00 hrs No sewers or waterways affected by this incident. No injuries related to this incident. Weather conditions did not contribute to this incident. Source of spill is unknown. Cause of spill is unknown. No fire or smoke involved in this leak Private property not affected by this incident.

Map Identification Number 232 **CON ED** **Spill Number: 0002517** **Close Date: 05/30/2000**
32 WEST 125TH STREET MANHATTAN, NY TT−Id: 520A−0093−366

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2017 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	CALLER − CON EDISON	Spiller Phone:	(212) 580−6763
Notifier Type:	Responsible Party	Notifier Name:	SAME	Notifier Phone:	
Caller Name:	TEDD ROBICHAUD	Caller Agency:	CON ED	Caller Phone:	(212) 580−6763
DEC Investigator:	JHOCONNE	Contact for more spill info:	TEDD ROBICHAUD	Contact Person Phone:	(212) 580−6763

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/30/2000		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
FREON	OTHER	200.00	POUNDS	0.00	POUNDS	AIR

Caller Remarks:

OVER A 1 YEAR PERIOD FREON WAS RELEASED INTO THE AIR.KILLER UNITS AT THE SITE UNIT 1 AND 2 RELEASED THE FREON.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Copy to NYSDEC Division of Air.

Map Identification Number 233 **SPILL NUMBER 9811292** **Spill Number: 9811292** **Close Date: 12/15/1998**
32 WEST 123RD STREET MANHATTAN, NY TT−Id: 520A−0092−553

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2044 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: TANK TRUCK Spiller: GEORGE HAMILTON − SKAGGS WALSH OIL COMPANY Spiller Phone: (718) 353−7000
Notifier Type: Local Agency Notifier Name: GEORGE HAMILTON Notifier Phone: (718) 353−7000
Caller Name: TERRY Caller Agency: NYC DEP Caller Phone: (718) 595−6777
DEC Investigator: SMSANGES Contact for more spill info: Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/08/1998		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	500.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

DRIVER WAS MAKING A DELIVERY TO EITHER 36 OR 38 WEST 123RD STREET. DRIVER REPORTED THAT HE DELIVERED TO THE WRONG ADDRESS, BUT HE DOESN'T KNOW IF HE DELIVERED TO 32 OR 40 WEST 123RD STREET. HE ALSO DOESN'T KNOW IF THE DELIVERY WENT INTO A TANK OR INTO SOMEONE'S BASEMENT. NEW YORK CITY FIRE DEPARTMENT ENROUTE.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND CROSS REF WITH 9811290 MISS DELIVERY − SPILL FOUND AND SKAGGS & WALSH CLEANED IT UP

Map Identification Number 234 **1350 5TH AVE** **Spill Number: 9604496** **Close Date: 07/05/1996**
1350 5TH AVE MANHATTAN, NY TT−Id: 520A−0095−981

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 2079 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10026

Source of Spill: UNKNOWN
Notifier Type: Federal Government
Caller Name: SHANE QUINLAN
DEC Investigator: SMMARTIN

Spiller: UNKNOWN
Notifier Name: SHANE QUINLAN
Caller Agency: DEP
Contact for more spill info:

Spiller Phone:
Notifier Phone: (718) 337−4357
Caller Phone: (718) 337−4357
Contact Person Phone:

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non−petroleum/non−hazardous spills.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/05/1996		ABANDONED DRUM	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	220.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

caller stated that a resident called to report 4 55gal drums abandoned.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT faxed to hazmat − 07/05/96 −11:30, CALLED HAZMAT TO CONFIRM − NIO ONE − TRY NEXT WEEK

Map Identification Number 235 **70 LENOX AVE** **Spill Number: 9209724** **Close Date: 11/23/1992**
70 LENOX AVE MANHATTAN, NY TT−Id: 520A−0095−979

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 2079 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10026

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:		Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:	NYC HOUSING	Caller Agency:	FRANK OCELLO	Caller Phone:	(212) 306−3142
DEC Investigator:	KSTANG	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/20/1992	11/23/1992	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

MALFUNCTION OF VALVE−CONTAINED ON PAVED DRIVEWAY,NYC DEP REP AT SCENE WINSTON CONTRACTING CLEAN UP

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

Map Identification Number 236 **KING TOWERS** **Spill Number: 8708238** **Close Date: 08/16/1995**
90 LENOX AVE NEW YORK CITY, NY TT−Id: 520A−0095−977

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING − LARGE SITE
Approximate distance from property: 2079 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10026

Source of Spill:	PRIVATE DWELLING	Spiller:	NYC HOUSING AUTHORITY	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	HEALY	Contact for more spill info:		Contact Person Phone:	

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − No DEC Field Response − Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
12/22/1987	08/16/1995	EQUIPMENT FAILURE	2−474886	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#4 FUEL OIL	PETROLEUM	300.00	GALLONS	0.00	GALLONS	SOIL

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
		Unknown	0.00	UNKNOWN

Caller Remarks:

25K UNDERGROUND TANK WITH A BROKEN OIL LINE, THE LAWN WAS AFFECTED, DIGGING UP CONTAMINATED SOIL FOR REMOVAL, HSG AUTH. WILL CLEAN UP. SEE SPILL # 9102023

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 237 **163 E 111TH ST** **Spill Number: 9112852** **Close Date: 03/18/1992**
163 E 111TH ST NYC, NY TT−Id: 520A−0091−876

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2177 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: TANK TRUCK Spiller: EMPIRE STATE FUEL Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: D WILLIAMS Caller Agency: A L EASTMOND Caller Phone: (212) 378−3000
DEC Investigator: KSTANG Contact for more spill info: Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/18/1992	03/18/1992	TANK OVERFILL	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CONTAINED ON PAVEMENT. A L EASTMOND CLEANED UP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG

Map Identification Number 238 **APT COMPLEX W/ STORES** **Spill Number: 1311426** **Close Date: 04/11/2014**
282 LENOX AVE NEW YORK, NY TT−Id: 520A−0297−262

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2268 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ANDY JINNETT − BUILDING OWNER	Spiller Phone:	
Notifier Type:	Other	Notifier Name:		Notifier Phone:	
Caller Name:		Caller Agency:		Caller Phone:	
DEC Investigator:	RMPIPER	Contact for more spill info:	RONI NOVA	Contact Person Phone:	(212) 921−1500

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/06/2014		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	

Caller Remarks:

in fill pipe − basement − cleanup in progress

DEC Investigator Remarks:

3/7/14−Zhune spoke to Rich Clifton from Castle Oil. He said the fill line has a hole and spilled approximately 100 gallons of oil onto the concrete floor of the basement. Spill is contained and It's being cleaned up by Castle and the managment company. There is a sump in the basement but oil did not reach the sump.

3/7/14−Zhune spoke to Andy Jinnett (Supoerintendent) 917−731−3475. As per Andy there are odor at the entrance of the building.

Ryan Piper responded to thi spill (Secondary off−Hour

3/7/14− DEC Piper repsonded to site and instructed owner/ castle to continue cleanup and remove additional oil soake debris.

4−11−14 − DEC Piper received email notification from Rich Clifford at Castle that spill was cleaned.

On 3/6/14 our carrier, Express had a 30 gallon #2 oil spill. Express stopped delivery after 946 gallons #2 oil delivered when building superintendent noticed oil smell coming from metal cellar doors leading to basement. Cellar doors were opened and oil was discovered leaking from fill pipe onto steps leading to basement floor. Note that fill is located to the immediate right of the cellar doors. The Spill was due to equipment failure (hole in fill line). Express personnel contained spill. No oil leaked into any sump, drain, or impacted soil. Castle assisted Express personnel in cleaning up spill in basement. Clean−up was completed 3/7/14 by Castle personnel. The fill line was replaced on 3/17/14. There have been no issues during subsequent deliveries made on 3/20/14 and 4/8/14. Based on work to date, this spill is closed.

Map Identification Number 239 **127 WEST 119TH ST/MANH** **Spill Number: 9008744** **Close Date: 12/05/1990**
127 WEST 119TH STREET NEW YORK CITY, NY TT−Id: 520A−0091−783

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2336 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	COMMERCIAL/INDUSTRIAL	Spiller:	ELRICK WILLIAMS(OWNER)	Spiller Phone:	
Notifier Type:	Responsible Party	Notifier Name:		Notifier Phone:	
Caller Name:	R. MADISON	Caller Agency:	SUPERINTENDENT	Caller Phone:	(212) 222−5013
DEC Investigator:	O'DOWD	Contact for more spill info:		Contact Person Phone:	

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/29/1990	12/05/1990	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	100.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

FUEL LINE BROKEN IN BASEMENT, FLOOR IS PART DIRT & CONCRETE, CON ED DOING DRILLING DOWN STREET,TANKS FELL,BROKE NOZZLE,OIL SPILLED OUT, TO REPAIR TANKS (5K & 12K), TEMPORARY TANK SET UP 200GAL.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 240 **129 WEST 119TH ST/MANH** **Spill Number: 9008277** **Close Date: 03/14/1991**
129 WEST 119TH STREET NEW YORK CITY, NY TT−Id: 520A−0091−780

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2356 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING Spiller: Spiller Phone: (212) 865−6305
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: EDDIE DWYER Caller Agency: BAERENKLAU OIL CO Caller Phone: (718) 647−4200
DEC Investigator: JAMES Contact for more spill info: Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/28/1990	03/14/1991	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	500.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

SPILL IN BASEMENT,INSURANCE CO TO HANDLE CLEAN UP ON DIRT FLOOR,

BAERENKLAU CONDUCTING CLEAN UP,DEC WILL FOLLOW UP AS NECESSARY.

DEC Investigator Remarks: NO DEC INVESTIGATOR REMARKS GIVEN FOR THIS SPILL.

Map Identification Number 241 **112−114 W 116TH ST** **Spill Number: 9104068** **Close Date: 10/15/1991**
112−114 W 116TH ST NYC, NY TT−Id: 520A−0093−573

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2384 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: POSSIBLY BAERENKLAU Spiller Phone:
Notifier Type: Other Notifier Name: Notifier Phone:
Caller Name: RICH HOUSTON Caller Agency: BAERENKLAU Caller Phone: (718) 647−4200
DEC Investigator: MCTIBBE Contact for more spill info: Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/16/1991	10/15/1991	HUMAN ERROR	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
#2 FUEL OIL	PETROLEUM	236.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

CONVERTED TO GAS; LEFT FILL LINE OPEN TO BASEMENT, BAERENKLAU ENROUTE TO CONTAIN & POSSIBLY HIRE CONTRACTOR TO CLEAN UP.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE

/ / : MILROSE SERVICES ON SCENE TO DO CLEANUP.

Map Identification Number 242 **SPILL NUMBER 0103459** **Spill Number: 0103459** **Close Date: 06/30/2003**
24 WEST 127TH ST MANHATTAN, NY TT−Id: 520A−0099−426

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2406 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill: UNKNOWN | Spiller: BLANCHARD REALITY | Spiller Phone: (212) 865−8953
Notifier Type: Local Agency | Notifier Name: | Notifier Phone:
Caller Name: STANLEY BALDWIN | Caller Agency: NYC DEP | Caller Phone: (718) 595−4658
DEC Investigator: TJDEMEO | Contact for more spill info: STANLEY BLADWIN | Contact Person Phone: (718) 595−4658

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/29/2001		ABANDONED DRUM	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	220.00	GALLONS	0.00	GALLONS	SOIL
The following material(s) was dropped or revised by the NYS DEC. Call Toxics Targeting for more information						
OTHER PETROLEUM	UNKNOWN	220.00	GALLONS	0.00	GALLONS	

Caller Remarks:

4 55 gal drums w/ some type of petrol and sand in them..they are onthe side of the road...not leaking. this may be waste from boiler work done at the above address.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 6/30/03 TJD Drums removed by responsible party. No further action required.

Map Identification Number 243 **BP AMOCO STATION #13401** **Spill Number: 9711337** **Close Date: 04/11/2014**
255 EAST 125TH ST HARLEM, NY TT−Id: 520A−0092−463

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 2421 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Source of Spill:	GASOLINE STATION OR PBS FACILITY	Spiller:	RAE ADAMS − AMOCO	Spiller Phone:	(973) 331−7012
Notifier Type:	Other	Notifier Name:	JERRY KASPER	Notifier Phone:	(215) 646−3161
Caller Name:	JERRY KASPER	Caller Agency:	CROMPCO CORPORATION	Caller Phone:	(215) 646−3161
DEC Investigator:	rjfeng	Contact for more spill info:	RAE ADAMS	Contact Person Phone:	(973) 331−7012

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP − DEC Field Response − Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	PBS # Involved	Meets Cleanup Standards	Penalty Recommended
01/09/1998		EQUIPMENT FAILURE	2−205613	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0	GALLONS	0	GALLONS	SOIL
MTBE (METHYL−TERT−BUTYL ETHER)	HAZARDOUS MATERIAL	0	UNKNOWN	0	UNKNOWN	

Caller Remarks:

FAULTY EQUIPTMENT ON SILVER UN−LEADED SUBMERSIBLE SYSTEM.EQUIPTMENT HAS BEEN REPAIRED − AMOCO TO MAKE ARRANGEMENTS FOR CLEAN UP. SPILL REASSIGNED FROM O'DOWD TO ROMMEL.

DEC Investigator Remarks:

1/9/98 Faulty equipment on silver unleaded submersible system. Equipment has been repaired. Amoco to make arrangements for cleanup.

1/14/98 Spoke to Jerry, Crompco. The gauge on the silver U/L submersible pump was visibly leaking. Amoco Env. aware of problem. Will need subsurface investigation.

1/14/98 Left message for Rae Adams, Amoco (973−331−7012).

Rommel spoke to Eric Lismanis, Baltec (914−273−2626)− was aware of spill. He said that they had vacced out between 30−50gal gasoline and water from tank sump. They were planning to perform a Geoprobe investigation. Rommel requested Baltec send a brief investigation plan. He will inform the project manager to address it to K. O'Dowd's attention.

2/9/98 Received letter from Baltec, Jeffrey Anderson, summarizing investigation plan. 10/22/98 Received Baltec Investigation Report(8/25/98). 4 soil borings by Geoprobe installed 2/9/98. Samples collected just above groundwater interface at depths from 7 to 13' bgs. Highest PID reading was 665ppm from 12'bgs in B−3. On 3/8/98, Baltex collected 8 groundwater samples from existing monitoring wells, MW−A, MW−C, MW−D, MW−E, MW−F, MW−G, MW−H, and MW−I. Samples were analyzed by EPA Method 8020 for BTEX/MTBE. DTW approx 11−14'bgs. Total BTEX ranged from ND (MW−A, MW−C, MW−D, MW−E, MW−G) to 600ppb(MW−H). MTBE ranged from ND(MW−G) to 90,800ppb(MW−H). Downgradient well, MW−D, displayed ND total BTEX and 13100ppb MTBE. MW−H, adjacent to the tank

vault, showed concentrations of BTEX to be 600ppb and MTBE at 90,800ppb.

03/17/03 REASSIGNED FROM ROMMEL TO VOUGHT.

11/28/03 Reassigned from Vought to Foley. File review: Pre−2000 data taken from First and Third Quarter 2000 report. Highest MTBE readings 3/18/98 91000ppb

MW−H (source area) 9/2/98 27000ppb

MW−H 12/23/98 51000ppb

MW−F (downgradient of source) 3/12/99 7950ppb

MW−F 6/23/99 13400ppb

MW−E (downgradient of source) 9/1/99 19200ppb/19100ppb MW−H/MW−F (source and downgradient) 1/13/00 4450ppb

MW−H 7/31/00 2380ppb

MW−C (most downgradient) 12/5/00 6240ppb

MW−D (most downgradient) 2/27/01 7940ppb

MW−D 6/11/01 3520ppb

MW−C 9/28/01 11000ppb

MW−J (source area) 12/12/01 3370ppb

MW−C 3/15/02 2830ppb

MW−C 6/20/02 1050ppb

MW−D 8/26/02 1450ppb

MW−D 12/12/02 449ppb

MW−I (source area) 3/24/03 529ppb

MW−I 6/10/03 284ppb

MW−F

Highest BTEX readings have generally remained in the source area within MW−H and MW−I. Highest reading was actually from MW−J

(since destroyed) with 2790ppb total BTEX on 12/12/01. 6/10/03 BTEX highest at MW−I at 256ppb.

2/5/04 Received SHAR Addendum report. Four soil borings were installed on 10/3/03 by Geoprobe to confirm that no source of contamination exists in soil, as indicated by groudwater concentration trends. Groundwater detected at 10−14'bgs. Borings were completed to 16'bgs. Samples were collected from the soil exhibiting highest PID reading or at soil water interface. Results indicated that five VOCs were detected at concentrations above soil cleanup objectives in one of four samples collected [SB−N(11−12')]. Total BTEX ranged from ND(SB−K, SB−L, SB−M) to 103998ppb(SB−N). MTBE ranged from ND(SB−K) to 7ppb (SB−M). Total VOCs ranged from ND (SB−k) to 279568ppb(SB−N). Petroleum stains were noted in all borings at approx 15'bgs.

3/16/04 3Q and 4Q 2003 reports received. No LNAPL. Max total BTEX 184ppm(MW−1) and max MTBE 636ppm(MW−1) from 11/20/03.

On 1/25/05, Spill #0411494 was reported for gasoline contamination detected on adjacent property(empty lot) at 249 E 125th St. Consultant discovered while drilling two Geoprobes for a potential buyer. Notified B. Fisher of adjacent property issue. However, results did not indicate contamination and spill #0411494 was closed.

3/15/05 Received Line Closure and Dispenser Upgrade Report. As part of spill prevention initiative, they excavated 150' of single−walled steel piping and replaced it with flexible double−walled Geoflex piping; excavated 80' of abandoned single−walled steel piping; installed sumps around the submerged pumps of the UST system; removed existing shallow spill containment boxes beneath each dispenser and replaced with deep Environ spill boxes; and installed electronic leak detection at each product line which were tied to Veeder Root. Lab analysis of post−ex soil samples collected from beneath the product dispensers, from beneath the former and abandoned product piping, and from around the top−of−tank excavation and tank vent lines identified concentrations of VOCs in excess of soil cleanup objectives (4 of 22 samples, D−1(4.4'), PR−2(4'), PR−3(3.5'), SS−2(2.3')).

4/26/05 3Q04− sampled MW−I in 9/04. Total BTEX at 455ppb and MTBE at 12ppb. 4Q04− Sampled MW−I, MW−O, MW−P in 12/04. BTEX ranged from 2766ppb(MW−P) to 6180ppb(MW−O). MTBE from 119ppb(MW−I) to 268ppb(MW−P).

9/19/05 1Q05− DTW 10.9−12'bgs. No LNAPL. BTEX from 2086ppb(MW−O) to 5172ppb(MW−P). MTBE from 29ppb(MW−I) to 493ppb(MW−P).

2Q05− DTW 11.2−12.2'bgs. No LNAPL. BTEX from 1172ppb(MW−O) to 2957ppb(MW−P). MTBE from 52ppb(MW−I) to 231ppb(MW−O).

9/28/05 Subsurface Assessment Report received for activities completed between 11/7/04 and 12/7/04. One 2 diameter MW−O and one 4 diameter MW−P were installed to 18'bgs. GW was encountered at 12−13'bgs during installation. A soil sample was collected from MW−O at 10.5−12.5'bgs and from MW−P at 11−13'bgs, and analyzed by 8260. Soil contamination noted in MW−P at total VOC concentration of 224,640ppb.

Three groundwater samples were collected from MW−I, MW−O, MW−P on 12/23/04 and analyzed by 8260. Total BTEX ranged from 2766ppb(MW−P) to 6180ppb(MW−O). MTBE ranged from 119ppb(MW−I) to 268ppb(MW−P).

11/8/05: Reviewed the quarterly monitoring report dated 11/1/05. Three monitoring wells were sampled on 9/19/05. Many others wells with no contamination are no longer being sampled. Based on the varying lithology that comprises the screened intervals of the on site monitoring wells...the measured ground water elevations may not reflect the regional ground water flow...(to the) northeast towards the Harlem River. Total BTEX in all three wells is approximately 1000ppb and MTBE is 25−290 ppb. Contamination appears to be attenuating on its own. Delta is evaluating possible Fenton's injections in 3Q06.

3/15/06 Reassigned from Foley to Tang. (KMF)

3/20/2008 − Feng − eDoc Quarterly Monitoring Report 3Q2007. (RJF)

10/29/2008 − 2Q2008, 10/23/2008, by EnviroTrac. Active BP service station. The monitoring well network was gauged and sampled 8/13/2008. 3 wells were gauged. NO LNAPL. DTW 11.14' to 12.28' bg. Flows to northeast. 3 wells were sampled. Max benzene 7.6 ug/L (MW−I). Max BTEX 4,213 ug/L (MW−I). Max MTBE 320 ug/L (MW−O). (RJF)

8/13/2009 − Reviewed the Site History Letter, dated June 30, 2009, by Delta, pdf copy. On 1/9/1998, there was a gasoline inventory loss at the Amoco service station. During the same day, a leaking valve a the pump island was discovered during the tank testing. On 1/14/1998, appro 200 gallons of gasoline/water mix was removed from the pump sumps via a vacuum truck. During the November−December 2004 lines closure and dispensers upgrade, soil endpoint samples show elevated VOCs. PR−2 hit over a million ug/kg total VOCs at 4 feet. The letter also state that the five 4,000−gallon USTs were removed in November 2008. Checked PBS record, no record shows the removal.

Drilling Work Plan, dated June 30, 2009, by Delta, pdf copy. Delta propsed to install 2 wells MW−Q and MW−R at both site of the tanks area.

Email comments to Delta on the History letter and the DWP. Asked Delta to check whether there was tank closure and dispenser closure, and tank closure report if there is any. DEC required 2 more wells at the former elevated lines closure dispensers upgrade endpoint samples, D−1, PR−2 and PR−3 area. attached site plan. Work plan revision within 30 days, 9/2009. (RJF)

email from Igor Goldstein (Delta). No tanks were removed in November 2008 and will get back to me on the two additional wells.

11/5/2009 − 3Q4Q2009, 10/30/2009, pdf, by EnviroTrac. Active BP service station. The monitoring well network was gauged and sampled on August 31, 2009. 3 wells were gauged. NO LNAPL. DTW 10.93' to 12' bg. Flows to north. 3 wells were sampled. Max benzene 46 ug/L (MW−I). Max BTEX 1,412 ug/L (MW−I). Max MTBE 390 ug/L (MW−O). (RJF)

12/15/2009 − Reviewed Drilling Work Plan revision, dated 9/9/2009, by Delta. Delta has added 2 more wells, MW−S on the west sidewalk of 2nd Ave and MW−T on the north sidewalk of East 125th Street. Work plan is approved. SHARA due 3/2010. (RJF)

4/12/2010 − email from Delta As you are aware, Delta Consultants (Delta) arranged for the installation and sampling of additional ground water monitoring wells at the subject site. However, drilling activities took longer then expected due to the presence of underground utilities and numerous refusals which, in turn, lead to additional private mark−outs conducted at the drilling locations and several mobilization events. As such, Delta will not have all well installation and sampling data in order to complete Subsurface Hydrocarbon Assessment Report Addendum (SHARA) for the subject site by April 30, 2010.

Delta is hereby requesting an extension for the submittal of SHARA report for the subject site until May 31, 2010. Please indicate your office comments to this request in your reply.

6/10/2010 − 1H2010, 4/21/2010, by EnviroTrac. Active BP service station. The monitoring well network was gauged and sampled on 2/18/2010. 3 wells were gauged. NO LNAPL. DTW 10.99 − 12.06' bg. Flows to north. 3 wells were sampled. Max benzene 4.1J ug/L (MW−I). Max BTEX 2,257 ug/L (MW−I). Max MTBE 67 ug/L (MW−O).

7/20/2010 − Informed by Hasan Ahmed from spill about the new spill 10−04193 occured on July 4th, 2010. A customer hit the dispenser 3/4 and leaked. The containment box underneath the dispenser has collected a portion of the gasoline and some staining was visible on the pavement going to a small 18 X18 drain grate near the corner of the canopy with PID 51.9 to 436 ppm. Tyree was onsite on July 4 and pumped out 30 gallons of gasoline from the dispenser containment and from the nearby 18 X18 drain. Alvin Petroleum was onsite July 7 and repaired the dispenser, clean out the dispenser 3/4 containment box and replace the gravel that sits on the bottom of the containment box. The station operator reviewed the inventory records which show approx. 40 gallons of premium and 34 gallons of regular are unaccounted for on July 4, but with % variance in the system this may only amount to 15 gallons of premium and 10 gallons regular (or roughly 30 gallons total). The spill 10−04193 was closed and consolidated under spill 97−11337.

email David Greffenius with questions. 1) is the containment box under that leaked dispenser tight or seal well? and its size? 2) is the 18 x18 drain a dry well or connected to the sewer? If it is a dry well, then the sediment shall be removed and confirm with some soil samples. 3) please send me a map indicating which one is dispenser 3/4 that was being hit and leaked.

7/30/2010 − Subsurface Hydrocarbon Assessment Report Addendum, dated 5/28/2010, by Delta. MW−S could not be installed due to the presence of underground utilities and NO DRILL marks sprayed on the sidewalk by the NYCT. On 2/4/2010, EnviroTrac hand cleared 2 soil boring locations to 6.5 feet, but could not establish the desired depth using the onsite equipment. On 3/1−2/2010, EnviroTrac completed the hand clearing and advanced MW−Q, MW−R and MW−T using Geoprobe unit equipped with hollow stem auger and macro sampler. All 3 soil borings were drilled to 17.5 feet where refusal, most likely due to the presence of bedrock, was encountered. 5 soil samples were taken. MW−Q (9.5−10'), VOCs ND, 800 benzo(a)anthracene, 820 benzo(a)pyrene, 1,200 benzo(b)fluoranthene, 440 benzo(k)fluoranthene, 730 chrysene, 210 dibenz(a,h)anthrancene. MW−Q (14.5−15'), 6,000 n−propylbenzene, 12,630 total VOCs, 500 benzo(a)anthrancene, 500 benzo(a)pyrene, 680 benzo(b)fluoranthene, 230 benzo(k)fluoranthene, 570 chrysene. MW−R, (12−12.5'), 360 total VOCs, 4,500 benzo(a)anthracene, 3,000 benzo(a)pyrene, 3,500 benzo(b)fluoranthene, 1,800 benzo(k)fluoranthene, 3,300 chrysene, 460 dibenz(a,h)anthracene. MW−T (12.5−13'), total VOCs ND, no exceedances SVOCS.

Groundwater was collected on 4/13/2010. MW−Q, 13 benzene, 8.1 toluene, 19 ethylbenzene, 6.1J xylenes, 46 BTEX, 220 isopropylbenzene, 1,300 n−propylbenzene, 13 n−isopropylbenzene, 6.8 1,2,4−trimethylbenzene, 99 n−butylbenzene, 75 sec−buylbenzene, 78 naphthalene, 1,845.4 total VOCs, 20 benzo(a)anthracene, 15 benzo(a)pyrene, 17 benzo(b)fluoranthene, 8.5 benzo(g,h,i)perlene, 7.9 benzo(k)fluoranthene, 20 chrysene, 69 fluoranthene, 7.3 indeno(1,2,3−cd)pyrene, 240 naphthalene, 55 pyrene, 581 total SVOCs. MW−R, VOCs ND, 0.043J benzo(a)anthracene, 0.049 benzo(a)pyrene, 0.072 benzo(b)fluoranthene, 0.024J benzo(k)fluoranthene, 0.047J chrysene, 0.035J indeno(1,2,3−cd)pyrene, 0.565 total SVOCS. MW−T, 14.6 total VOCs, 0.16 benzo(a)anthracene, 0.11 benzo(a)pyrene, 0.17 benzo(b)fluoranthene, 0.066 benzo(k)fluoranthene, 0.19 chrysene, 0.029J indeno(1,2,3−cd)pyrene, 3.481 total SVOCs.

Based on the low concentration of detected compounds (total BTEX 46 ug/L), and since soil impacts appear to be limitted, Delta does not recommend any additional investigation and/or remediation activities with respect to the site at this time. Groundwater will be continued to be monitored on a biannually schedule.

As agreed during the meeting on 6/23/2010, keep monitoring at this time and see how the monitoring data look like before more investigation/RAP.

11−30−2010 This spill is reassigned to Alex Z. as per Vadim Brevdo and Mark Tibbe instructions. AZ

4/11/2011 − Spill transferred back to JFeng.

7/21/2011 − 1H2011, 5/23/2011, by Anteagroup. The wells were sampled on 2/14/2011. 5 wells were sampled. Flows to east. NO LNAPL. Low BTEX and MTBE. Max BTEX 265 ug/L (MW−I). JF

5/31/12 − Raphael Ketani. Today I received the Antea Group Remedial Action Completion Report dated 5/24/12. I reviewed the report.

The spill was initially called in on 1/9/98 due to a leaking dispenser valve. Two hundred gallons of a gasoline and water mix were recovered from a sump. An initial investigation found high soil and groundwater contamination. During October 1998 the consultant began EFRing wells I and H. By September 2000 a total of 8200 gals. of contaminated water, 559 gals. of petroleum hydrocarbons and 0.67 lbs. of LNAPL were recovered. During October 2003 an additional investigation was conducted. Soil analytical results were below the SCOs for borings K, L and M. Boring N results had 6 analyte exceedences. During November and December 2004 the station was upgraded and 250 tons of contaminated soil were removed. During November 2004, 22 soil samples were taken down to 4.5 feet under the former locations of the dispensers, the product lines, tank vent pipes, and tops of the sidewalls of the UST field. Only 4 samples exceeded the SCOs. During December 2004 two wells were installed. Well P had soil exceedences. The December 23, 2004 groundwater results for wells I, O and P indicated that BTEX and MTBE were over the limits. During March 1 and 2 of 2010, three wells were installed − Q, R and T. Q had soil BTEX exceedences and groundwater exceedences. T had SVOC exceedences. The groundwater monitoring shows impacts to the north and the east of the USTs.

Wells I, O, P, Q, R and T were sampled on 2/20/12. I had 470 ppb of ethylbenzene and 110 ppb of total xylenes. O had very low VOC hits with 74 ppb MTBE. P had low double digit VOC hits. Q had very low VOC hits and 45 ppb benzene. R and T were non−detect. Groundwater is generally at 85 feet elevation and 11.30 feet below grade. Flow is to the east.

A risk and exposure assessment and modeling were performed. This was done in part because there is a Dunkin Donuts restaurant on site.

The Historical Soil Analytical Results Map dated 4/6/12 shows that there were very high endpoint results for total VOCs. PR−2 from November 2004 at 4 feet down had 1,269,260 ppb of total VOCs. Shallow borings B−1, B−2A, B−3 and B−4 from February 1998 had up to 647,000 ppb of total VOCs. SB−N of October 2003 at 11'−12' down had 279,568 ppb total VOCs. D−1, SS−2, D−5 and PR−3 from November 2004 and at shallow depth had up to 123,773 ppb total VOCs. MW−P from December 2004 at 11'−13' down had 288,572 ppb total VOCs. MW−Q and MW−R from March 2010 at 12' to 15' down had up to 12,630 ppb total VOCs and up to 62,070 ppb total SVOCs. Despite the excavation that took place, there is still very high contamination in the soil. However, B−1, B−2A, PR−2, PR−3, D−1 and D−5 were at locations that would presently be under the existing canopy.

The extent of the remediation was found to be inadequate for the following reasons:

1) very high soil contamination was found to still exist at 13 locations depicted on the 4/6/12 Historical Soil Analytical Results Map

2) not enough borings and wells were performed in the northern half of the site and next to the tire shop and along the east side of the Dunkin Donuts in order to fully delineate the soil contamination

3) a well was not installed downgradient of MW−I in order to see what the analyte concentrations are in the groundwater that is about to leave the site

4) no end point samples were taken in the bottom of the tank graves and not enough end point samples along the sides of the tank field or within the footprint of the canopy area

5) utility locations are not indicated on the maps

6/1/12 − Raphael Ketani. I drafted a letter to Mr. Onufrak for the review of Hassan Hussein, EE III and head of the Hazardous Materials Unit. In the letter, I included the 5 points listed above and set a date of July 27, 2012 for the submission of a work plan for conducting further soil and groundwater contamination delineation.

The letter was approved by Mr. Hussein and was sent out today.

6/27/12 − Raphael Ketani. Tim Fisher, Chris Meyer and Dr. Gordon Hinshalwood of Antea Group called me in a conference call. We discussed the DEC 6/1/12 review letter for the Antea Group 5/24/12 Remedial Action Completion Report. We went over each of the five above listed items.

For item #1, Mr. Fisher explained that they had wanted to show what the concentrations used to be. He added that, by this time, the concentrations should be very low.

For item #2, I explained the DEC's rationale for requesting further investigation of the northern part of the site. This was that there is very little information for this part of the site. We can't really understand what the subsurface conditions are or what effect the groundwater flow is having. Mr. Meyer stated there was no reason to do more work in this area as the spill was associated with the tank field and the dispensers. I insisted that they more fully investigate this area as there could be old tank fields, dry wells and other things below the site. I added that I was suspicious that the area had been left so clear when the site was redeveloped. I told them that I suspected there was a building in the northern part of the site at one time. At the end of this part of the discussion, Antea Group had not stated that they would do more work in the northern part of the site.

For item #3, Mr. Fisher said that they didn't see the need to install a well further downgradient of well MW−I. He said that the analytical results from the groundwater sample from well MW−I were low, except for 470 pp of ethylbenzene and 110 ppb of total xylenes. I responded that this is why the DEC wants to see another well further downgradient. We want to be sure that elevated groundwater contaminants are not leaving the site as a plume. Again, Antea Group had not agreed to put another well further downgradient.

For item #4, Mr. Fisher stated that they could not take more endpoint samples in the tank graves or along the sides as there are too many active fuel lines. Mr. Hinshalwood said that it is Antea's health and safety policy not to drill under canopies. I told Mr. Fisher to drill borings out from under the canopy and away from the fuel lines, but to get as close as he can to the former tank graves.

For item #5, Mr. Fisher stated that they will submit a map showing all of the utilities in the next work plan. Mr. Fisher asked for an extension of the work plan submission deadline to September 28. I granted the extension.

8/8/2012 − 1H2012, 4/27/2012, by Antea Group. Groundwater was sampled on 2/20/2012. The next sampling will be in 8/2012. MW−I, 591 BTEX, 18 MTBE. MW−O, 12.8 BTEX, 74 MTBE. MW−P, 85.4 BTEX, 13 MTBE, MW−Q, 64.1 BTEX, 26 MTBE.

11/20/2012 − Reviewed Soil Groundwater Investigation Work Plan, dated 8/30/2012, by Antea Group. Antea proposed to do 6 soil borings and 1 monitoring well installation. The work plan is intended to address the comments that NYSDEC had on the spill closure request. BP/Antea is not seeking NYSDEC's approval on the work plan since these installations are within the property line. No comments.

Antea did the utility mark−out on October 18, 2012 and found 3 out of the 7 proposed boring locations are on an offsite property where an access agreement is needed. The offsite propoerty appears to be part of the BP station parking lot and access agreement may not needed. They reached out to the owner of the offsite propoerty on October 19th. Will proceed the onsite work once the effects of Hurricane Sandy have subsided and will continue for access to the offsite property.

12/7/2012 − 2H2012, 10/31/2012, by Antea Group. The groundwater was sampled August 10, 2012. The next sampling will be in February 2013. MW−I, 350 BTEX, 12 MTBE. MW−O, 29.3 BTEX, 310 MTBE. MW−P, 60.1 BTEX, 0.58J MTBE. MW−Q, 37.5 BTEX, 24 MTBE.

3/26/2014 − Discussed with J. Vought and the case is forwarded to Central Office K. Hale for review.

4/11/2014 − Discussed with J. Vought and advised by K. Hale. Spill is closed based on:

1) The residual soil contamination has been remained under the tanks, dispensers and piping. It reaches the extent of feasible for soil remediation due to the reasons of PBS system integrity and safety.

2) BTEX/MTBE concentration in groundwater has been low for years. This suggest that the residual soil contamination has discontinued contributing to groundwater contamination.

3) The soil sampling from soil borings SB−X, SB−M, SB−N2, MW−O, MW−U, MW−Y and MW−Z which located in the close proximity to the historical impact locations show minimum or low soil contamination level.

4) During the PBS system upgrade in 2004, a total of 250.3 tons of soil has been removed.

5) EFR events on MW−I and MW−H and removed 8,200 gallons of petroleum impacted groundwater, 559.36 lbs of petroleum hydrocarbon and 0.67 lbs of LNAPL.

6) Inclusion of remaining soil contamination language in the spill closure letter in case site is redeveloped.

7) NYSDEC is not aware of any change of use of the site.

Spill is closed. Spill closure letter to BP/Antea.

THE FOLLOWING CLOSED SPILLS FOR THIS CATEGORY WERE REPORTED BETWEEN 1/8 MILE AND 1/2 MILE FROM THE SUBJECT ADDRESS. THESE SPILLS WERE REPORTED TO BE LESS THAN 100 UNITS IN QUANTITY AND CAUSED BY: EQUIPMENT FAILURE, HUMAN ERROR, TANK OVERFILL, DELIBERATE SPILL, TRAFFIC ACCIDENT, HOUSEKEEPING, ABANDONED DRUM, VANDALISM OR STORMS. THESE SPILLS ARE NEITHER MAPPED NOR PROFILED IN THIS REPORT.

FACILITY ID	FACILITY NAME	STREET	CITY

9300378	118TH ST& LEX. AVE	118TH ST & LEX. AVE	MANHATTAN
0210662	SPILL NUMBER 0210662	LEXINGTON AVE & E.118TH	MANHATTAN
1101821	EAST HARLEM LEX PARTNERS	149 EAST 118TH ST	NEW YORK
9814595	RESIDENCE	1889 LEXINGTON AVE	MANHATTAN
9807244	EAST 117TH ST	E.117TH ST,LEXINGTON AVE	MANHATTAN
9507515	LEXINGTON AVE/E. 117TH ST	LEXINGTON AVE/E. 117TH ST	MANHATTAN
0508666	CONSTRUCTION SITE	1761 PARK AVE	MANHATTAN
0006564	MANHOLE 48437	SYLVAN PL	MANHATTAN
0412749	116TH ST	MADISON AVE	MANHATTAN
9312659	1760 PARK AVENUE	1760 PARK AVENUE	MANHATTAN
1203926	CONSTRUCTION SITE	1901 MADISON AVE	MANHATTAN
9907797	MANHOLE 19150	116 EAST 116TH ST	MANHATTAN
0650288	RESIDENTIAL	175 E 117TH STREET	NEW YORK
0011501	2182 3RD AVE	2182 3RD AVE	MANHATTAN
9612461	2 WEST 120TH ST	2 WEST 120TH ST	MANHATTAN
0200862	2 WEST 120TH ST	2 WEST 120TH ST	MANHATTAN
0110011	SPILL NUMBER 0110011	20 EAST 116TH ST	MANHATTAN
9903612	DENTAL CENTER	165 EAST 116TH ST	MANHATTAN
1202497	FREON RELEASE AT ASSOCIATED SUPERMARKET	2212 THIRD AVE	MANHATTAN
1110726	CONCRETE	2010 LEXINGTON AVE	NEW YORK
0890438	210069; E E 120 ST ST	E E 120 ST ST	
9801567	ENGINE CO. 35/LADD. CO. 14 FDNY −DDC	2232 3RD AVENUE	MANHATTAN
9508811	22 WEST 120TH ST	22 WEST 120TH ST	MANHATTAN
9809535	MANHOLE 34126	W 116TH / 5TH AVE	MANHATTAN
0513717	MANHOLE #56966	WEST 116 STREET & 5 AVE	MANHATTAN
9210746	159 EAST 115TH STREET	159 EAST 115TH STREET	MANHATTAN
9514542	100 E. 124TH ST	100 E. 124TH ST	NEW YORK
0311476	ON STREET	E.117TH ST/ 3RD & LEXINGTON	NEW YORK CITY
0104444	#TM2682	EAST 115TH ST/LEXINGTON	MANHATTAN
0505199	THIRD PARTY CAR WITH LEAK	2141 3 AVE	MANHATTAN
9506020	JULFINE REALTY CORP	2223 3RD AVE	MANHATTAN
9512814	27 WEST 118TH ST	27 WEST 118TH ST	MANHATTAN
0514675	MANHOLE 45676	E 116 ST & 3 AVE	MANHATTAN
0408154	BUS SPILL	3RD AVE/116TH ST	MANHATTAN
1011453	UNKNOWN BUILDING	1931 MADISON AVE	NEW YORK
9507979	120TH ST & MT MORRIS PK	120TH ST & MT MORRIS PK	MANHATTAN
0103884	SPILL NUMBER 0103884	W 115TH ST/5TH AVE	MANHATTAN
0108081	201 EAST 116TH ST	201 EAST 116TH ST	MANHATTAN
0000405	APARTMENT HOUSE	50 WEST 119TH ST	NEW YORK
0001066	SPILL NUMBER 0001066	15 WEST 115TH ST	MANHATTAN
9514121	223 EAST 120TH ST	223 EAST 120TH ST	MANHATTAN
0806631	PS 57 M	176 EAST RT 115 ST	MANHATTEN
9611020	MORRIS PARK	17 EAST 124TH STREET	MANHATTAN
0104191	SPILL NUMBER 0104191	212 EAST 122ND ST	MANHATTAN

9510482	26 EAST 125TH ST CORP	26 EAST 125TH ST	MANHATTAN
1101221	TRANSFORMER TM 2483	EAST 125TH AND PARK AVE	MANHATTAN
0314214	ON STREET	125TH ST & PARK AVE	MANHATTAN
0111487	PARK AVE VIA DUCT	125TH ST & PARK AVE	NEW YORK
9704554	ENGINE CO. 058/LADD. CO. 26 FDNY −DDC	1367 5TH AVENUE	MANHATTAN
0612219	LIFFEY ALLIED VAN LINES	234 E. 121ST ST	MANHATTAN
9100219	125TH ST &MADISON AV/MANH	125TH ST & MADISON AVE	NEW YORK CITY
1202256	ROADWAY	125TH ST & MADISON AVE	MANHATTAN
0807522	MANHOLE 50813	NE CORNER EAST 125TH ST AND MADISON AVE	MANHATTAN
1302454	IN FRONT OF	240 EAST 119TH ST	MANHATTAN
9507969	5 W. 121ST STREET	5 W. 121ST STREET	MANHATTAN
9507949	5 WEST 121ST STREET	5 WEST 121ST STREET	NYC
1004265	125TH ST AND LEXINGTON AVE	125TH ST AND LEXINGTON AVE	MANHATTAN
0706559	BUS	LEXINGTON AVE ^ 125TH STR	MANHATTEN
1206944	COMMERCIAL BUILDING	103 EAST 125 ST	MANHATTAN
9511017	233 EAST 116TH ST	233 EAST 116TH ST	NEW YORK
0330038	IFO FIREHOUSE	2282 3RD AVE	NY
9413964	2002 FIFTH AVENUE	2002 FIFTH AVE	MANHATTAN
9312897	2002 5TH AVENUE	2002 5TH AVENUE	NEW YORK
0907044	APT BLDG	2325 2ND AVE	MANHATTAN
9805724	APARTMENT BUILDING	244 EAST 117TH ST	MANHATTAN
9516002	246 E 121ST ST	246 E 121ST ST	MANHATTAN
9601565	LAGUARDIA MEMORIAL HOUSE	249 EAST 117TH ST	MANHATTAN
9106694	JOHNSON	1809 LEXINGTON AVE	NYC
8809774	JOHNSON HOUSES	163 EAST 112TH STREET	NEW YORK CITY
0800254	NYC HOUSING AUTHORITY FAC	1809 LEXINGTON AVE	NEW YORK
0312761	WHYE RESIDENCE	17 WEST 121ST ST	NEW YORK CITY
9711647	IN STREET IN FRONT OF	2018 5TH AVE	MANHATTAN
9506363	TAFT HOUSES −NYCHA	95 WEST 119TH STREET	MANHATTAN
9808616	MANHOLE 20624	21−25 E 125TH ST	MANHATTAN
0206396	MANHOLE 20624	125TH ST/5TH AVE	MANHATTAN
9704227	5 FAMILY HOUSE	21 WEST 121ST ST	MANHATTAN
8905085	230 EAST 123RD ST/MANH	230 EAST 123RD STREET	NEW YORK CITY
0913500	CAPITAL CAPTRE ELECTRICAL	2289 3RD AVE	MANHATTAN
0609087	BETWEEN 3RD & LEXINGTON AVE	153 EAST 125TH ST	MANHATTAN
0608906	ON THE ROADWAY	151 E. 125TH ST	MANHATTAN
1109973	VAULT 9402	20−27 FIFTH AVE	MANHATTAN
9414505	230 LENOX AVE	230 LENOX AVE	MANHATTAN
0703922	RESIDENTIAL BUILDING	303 E 119TH ST	MANHATTAN
1308833	ROAD WAY	LENOX AVE 118TH STREET	MANHATTAN
0507874	MANHOLE # 55077	EAST 121 ST & 2 AVE	MANHATTAN
0412815	E2MIS 157505	28 E. 112TH ST	MANHATTAN
0810512	ROADWAY	126TH AND LEXINGTON AVE	MANHATTAN
0403213	MANHOLE #39250	126 TH STREET / LEXINGTON	MANHATTAN

9815148	NW CORNER	117TH ST AND LENOX AVE	MANHATTAN
9814473	SPILL NUMBER 9814473	242 LENOX AV	MANHATTAN
9210775	11−13 WEST 123RD STREET	11−13 WEST 123RD STREET	MANHATTAN
0007099	MANHOLE #TM1599	E. 116TH ST & 2ND AVE	MANHATTAN
0604704	2 QT OIL LEAK FROM VEHICLE E13478	32 WEST 125 STREET	MANHATTAN
0308848	OFFICE BLDG	32 W 125TH ST	MANHATTAN
0308847	32 WEST 125TH STREET	CON ED FACILITY	MANHATTAN
9900859	SPILL NUMBER 9900859	64 EAST 127TH ST	NEW YORK
9503896	KING TOWERS −NYCHA	90 LENOX AVE	NEW YORK CITY
9901554	SPILL NUMBER 9901554	W 116TH ST & LENOX AVE	MANHATTAN
0910725	INTERSECTION	116TH AND MALCOLM X BVLD	MANHATTAN
9510835	MOUNT OLIZET BAPTIST CHUR	201 LENOX AV	MANHATTAN
1101889	SASSON MANAGEMENT	2407 2ND AVE	NEW YORK
1411236	APT BLD	17 WEST 125TH ST	NEW YORK
1202577	COMMERCIAL PROPERTY	228 E 125TH ST	MANHATTAN
0008395	102 W 116TH ST	102 W 116TH ST	MANHATTAN
0811653	BASEMENT	202 EAST 112TH ST	MANHATTEN
0100130	333 EAST 118TH ST	333 EAST 118TH ST	NEW YORK
9514113	123 WEST 119TH ST	123 WEST 119TH ST	MANHATTAN
9514177	NEW MARC REALITY	55 W. 125TH ST	MANHATTAN
0313130	ROAD	W 124TH ST/LENOX AV	MANHATTAN
8910155	52 PAYTON CORP − MAN	52 W 126TH ST	MANHATTAN
9710463	127 WEST 119TH ST	127 WEST 119TH ST	MANHATTAN
9710446	HPD OWNED RESIDENCE	127 W 119TH ST	MANHATTAN
0205830	ST.ANDREWS CHURCH	2067 5TH AVE	MANHATTAN
0000073	AUTOMOTIVE GARAGE	344 E 119TH STREET	MANHATTAN
0910998	TS 24	22 EAST 128 ST	NEW YORK
0103455	IN FRONT	24 WEST 127TH ST	MANHATTAN
1004193	BP STATION # 13401	255 EAST 125TH ST	MANHATTAN
0701416	BROWNSTONE ROW HOUSE	136 WEST 119TH STREET	MANHATTAN
9810765	MANHOLE 55110	2ND AVE AND WEST 125TH ST	NYC
8910219	416 2ND AVE & 125TH ST	416 2ND AVE / 125TH ST	NEW YORK CITY
0908987	INTERSECTION EAST 125TH AND 2ND	INTERSECTION EAST 125TH AND 2ND	MANHATTAN
0707934	INTERMIDATE SCHOOL 45	2351 FIRST AVENUE	NEW YORK
9814724	PS 185	20 WEST 112TH ST	MANHATTAN
9814544	PS 185	20 W 112TH ST	NEW YORK
1510370	NY PROTON CENTER	225 EAST 126 ST	NEW YORK
9700774	IFO 2012 3RD AVE	2012 3RD AVE	MANHATTAN
1100831	NYCT BUS SPILL ON ROADWAY	125TH STREET AND LENOX AVE	MANHATTAN
0210983	MTA TRANSIT AUTHORITY	125TH ST & LENNON AV	NEW YORK
0203703	SPILL NUMBER 0203703	125TH ST/LENOX AVE	MANHATTAN
0107725	SPILL NUMBER 0107725	LENOX AVE & 125TH ST	MANHATTAN
9800242	RESIDENCE	129 WEST 122ND ST	MANHATTAN
9313921	129 WEST 122ND STREET	129 WEST 122ND STREET	MANHATTAN

9212076	129 WEST 122ND ST	129 W. 122ND ST	MANHATTAN
0713071	5 GAL HEATING OIL IN SERVICE BOX 29226	124 WEST 123 STREET (NEAR 7 AVENUE)	MANHATTAN
1202658	APARTMENT BLDG	95 LENOX AVE	MANHATTAN
1311151	CONSTRUCTION SITE	100 W 125TH ST	MANHATTAN
0101324	VAULT TM2884	104 WEST 125TH ST	MANHATTAN
9310467	9 EAST 128TH STREET	9 EAST 128TH STREET	MANHATTAN
9901508	MANHOLE 19734	160 W 120TH ST	MANHATTAN
0509270	MANHOLE # 53850	EAST 119 ST & 1 AVE	MANHATTAN
9508295	15−19 WEST 110TH ST	15−19 WEST 110TH ST	MANHATTAN
9101284	2261 1ST AV/MANH/CITIBANK	2261 1ST AVENUE	NEW YORK CITY
0603703	HYDRAULIC OIL FROM VEHICLE 60787	120 STREET & 1 AVENUE	MANHATTAN
9811607	SPILL NUMBER 9811607	2009 3RD AVE	MANHATTAN
0103835	SPILL NUMBER 0103835	23−27 EAST 109TH ST	MANHATTAN
0013267	MANHATTAN CASTLE OIL	23 EAST 109TH ST	MANHATTAN
1107277	126TH ST TERMINAL	126TH ST & 2ND AVE	MANHATTAN
1206708	BASEMENT	19−21 E 109TH ST	NEW YORK
1100017	SOIL	19−21 EAST 109TH ST	NEW YORK
0410569	RESIDENTIAL BUILDING	19−21 EAST 109TH ST	MANHATTAN

NO OIL STORAGE FACILITIES LARGER THAN 400,000 GALLONS IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

PETROLEUM BULK STORAGE FACILITIES LESS THAN 400,000 GALLONS IDENTIFIED WITHIN THE 1/8 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 244 **MADISON PARK PARTNERSHIP HOUSING** **Facility Id: 2−607339** **Source: NYS DEC**
59 EAST 119TH ST. NEW YORK, 10035 TT−Id: 640A−0036−182

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 255 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Other
Site Status: Unregulated/Closed
Expiration Date of the facility's registration certificate:
Operator Name: AHMAD QUAZL
Operator Phone #: (646) 210−7605
Owner Name: −
Owner Company: VELEZ ORGANIZATION
Owner Type: Corporate or Commercial
Owner Address: 475 PARK AVE SOUTH, 16TH FL, NEW YORK, NY 10016

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
01	Closed − Removed	#6 Fuel Oil	5000	Aboveground − In Contact with Soil			01/01/2002

Map Identification Number 245 **50 EAST 119TH STREET** **Facility Id: 2−470244** **Source: NYS DEC**
50 EAST 119TH STREET MANHATTAN, NY 10026 TT−Id: 640A−0036−261

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 305 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: 10035

This facility has been deleted from the reported data. Data reflects last reported information.
Facility Type: None Given
Site Status: ACTIVE PBS;>1100 GAL PBS, REGARDLESS IF SUBPART 360−14 TANKS EXIST OR NOT
Expiration Date of the facility's registration certificate: 03/28/1994
Operator Name: PIJUSH LODH
Facility Phone #: (212) 806−8091
Owner Name: CITY OF NY HOUS. PRES. & DEV.
Owner Type:
Owner Address: 75 MAIDEN LANE, MANHATTAN, NY 10038

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	Delisted or Given New ID	#1 2 OR 4 FUEL OIL	2000	Aboveground	00/00		

Map Identification Number 246 **PROVIDENCE BAPTIST CHURCH** **Facility Id: 2−471445** **Source: NYS DEC**
50 EAST 119TH STREET NEW YORK, 10035 TT−Id: 640A−0036−262

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 305 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Active
Expiration Date of the facility's registration certificate: 03/04/2004
Operator Name: CHARLES ANDERSON
Operator Phone #: (212) 427−1981
Owner Name: −
Owner Company: PROVIDENCE BAPTIST CHURCH
Owner Type: Corporate or Commercial
Owner Address: 1829 MADISON AVE, NEW YORK, NY 10035

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#2 Fuel Oil	2000	Aboveground − In Contact with Soil			

Map Identification Number 247 **1829 MADISON AVE** **Facility Id: 2−602634** **Source: NYS DEC**
1829 MADISON AVE NEW YORK, 10035 TT−Id: 640A−0036−260

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 305 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Unregulated/Closed
Expiration Date of the facility's registration certificate:
Operator Name: REV CHAS ANDERS
Operator Phone #: (212) 427−1981
Owner Name: ADAM ENBAR − MANAGER
Owner Company: 50 EAST 119TH STREET LLC
Owner Type: Corporate or Commercial
Owner Address: 46 TRINITY PLACE, SUITE 200, NEW YORK, NY 10006

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	Tank Converted to Non−Regulated Use	#2 Fuel Oil	2000	Aboveground − In Contact with Soil	04/01/1993		02/01/2016

Map Identification Number 248 **25 PCT** **Facility Id: 2−217506** **Source: NYS DEC**
120 EAST 119TH STREET NEW YORK, 10035 TT−Id: 640A−0037−650

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 395 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Municipality (Incl. WWTPs, Utilities, Swimming Pools)
Site Status: Unregulated/Closed
Expiration Date of the facility's registration certificate:
Operator Name: NYCPD
Operator Phone #: (212) 860−6511
Owner Name: −
Owner Company: N Y C P D/ ASD
Owner Type: Local Government
Owner Address: 1 POLICE PLAZA, ROOM 800, NEW YORK, NY 10038

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	Closed − In Place	Gasoline	550	Underground	11/01/1966		03/01/1996
002	Closed − In Place	Gasoline	550	Underground	11/01/1966		03/01/1996
003	Closed − In Place	Gasoline	550	Underground	11/01/1966		03/01/1996
004	Closed − In Place	Gasoline	550	Underground	11/01/1966		03/01/1996
005	Closed − In Place	#2 Fuel Oil	5500	Abovegrnd − In Contact w/Imperv. Barrier	01/01/1968		03/15/2011
006	In Service	#2 Fuel Oil	1000	Abovegrnd − In Contact w/Imperv. Barrier	12/01/1966		

Map Identification Number 249 **AYERS MOVERS** **Facility Id: NY01714** **Source: NYC FIRE DEPT**
1721 PARK AVE NEW YORK, NY 10035 TT−Id: 660A−0005−275

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 399 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

NOTE: This is an archived database

Comments: F O NO 2 1100G

Map Identification Number 250 **61 EAST 117 STREET** **Facility Id: 2−601028** **Source: NYS DEC**
61 EAST 117 STREET NYC, 10035 TT−Id: 640A−0038−025

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 449 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: 61 EAST 117TH STREET
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Unregulated/Closed
Expiration Date of the facility's registration certificate:
Operator Name: ASST. COMMISSIONER/DPM
Operator Phone #: (212) 863−7087
Owner Name: −
Owner Company: NYC/HPD/DPM
Owner Type: Local Government
Owner Address: 100 GOLD ST #6Z1, NEW YORK, NY 10038

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
1	Closed − Removed	#2 Fuel Oil	2000	Aboveground − In Contact with Soil			01/01/2007

Map Identification Number 251 **PUBLIC SCHOOL 79 − MANHATTAN M079** **Facility Id: 2−353949** **Source: NYS DEC**
55 EAST 120TH STREET NEW YORK, 10035 TT−Id: 640A−0036−183

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 456 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: School
Site Status: Active
Expiration Date of the facility's registration certificate: 06/28/2018
Operator Name: PETER ROBERTIN
Operator Phone #: (212) 534−5037
Owner Name: −
Owner Company: NEW YORK CITY DEPARTMENT OF EDUCATION
Owner Type: Local Government
Owner Address: 44−36 VERNON BOULEVARD, LONG ISLAND CITY, NY 11101

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#4 Fuel Oil	7500	Aboveground on Crib Rack or Cradle	06/01/1963		
The following tank 001 content has been deleted or replaced: #6 Fuel Oil							
002	In Service	#4 Fuel Oil	7500	Aboveground on Crib Rack or Cradle	06/01/1963		
The following tank 002 content has been deleted or replaced: #6 Fuel Oil							

**** TANK INFO CONTINUES ON NEXT PAGE ****

Map Identification Number 252 **CRP 1661 PARK AVENUE LLC** **Facility Id: 2−609820** **Source: NYS DEC**
105 EAST 117 ST. NEW YORK, 10035 TT−Id: 640A−0037−654

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 517 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 105 E 117TH ST
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Active
Expiration Date of the facility's registration certificate: 09/13/2018
Operator Name: NORBERTO VILLA
Operator Phone #: (646) 795−7848
Owner Name: CLARA RIVERA − DIR
Owner Company: CRP 1661 PARK AVENUE LLC
Owner Type: Corporate or Commercial
Owner Address: 1841 BROADWAY, STE 400, NY, NY 10023

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#2 Fuel Oil	3000	Aboveground on Crib Rack or Cradle	09/22/2005		

Map Identification Number 253 **ST. PAUL SCHOOL** **Facility Id: 2−606916** **Source: NYS DEC**
114 EAST 118TH STREET NEW YORK, 10035 TT−Id: 640A−0035−156

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 522 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: School
Site Status: Active
Expiration Date of the facility's registration certificate: 09/10/2006
Operator Name: FATHER MALLO
Operator Phone #: (212) 534−4422
Owner Name: −
Owner Company: ST. PAUL SCHOOL
Owner Type: Corporate or Commercial
Owner Address: 114 EAST 118TH STREET, NEW YORK, NY 10035

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#2 Fuel Oil	5000	Aboveground on Crib Rack or Cradle			

Map Identification Number 254 **ST.PAULS CHURCH & SCHOOL** **Facility Id: NY09430** **Source: NYC FIRE DEPT**
114 E 118 ST NEW YORK, NY 10035 TT−Id: 660A−0006−891

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 522 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: 114 E 118TH ST
Revised zip code: NO CHANGE

NOTE: This is an archived database

Comments: FUEL OIL #2−5000 GAL.TANK
NO FEE

Map Identification Number 255 **1652 PARK AVENUE ASSOC. LLC** **Facility Id: 2−609983** **Source: NYS DEC**
1648 PARK AVENUE NEW YORK, 10035 TT−Id: 640A−0036−180

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 584 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Active
Expiration Date of the facility's registration certificate: 07/12/2020
Operator Name: TOMAS HERRERA
Operator Phone #: (914) 879−4216
Owner Name: JOEL GENDELS − MANAGING AGENT
Owner Company: 1652 PARK AVENUE ASSOCIATES L.L.C.
Owner Type: Corporate or Commercial
Owner Address: 542 MAIN STREET, 2ND FL, NEW ROCHELLE, NY 10801

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#2 Fuel Oil	3000	Aboveground on Crib Rack or Cradle	10/28/2004		

Map Identification Number 256 **MADISON COURT ASSOC, LP** **Facility Id: 2−609151** **Source: NYS DEC**
58 EAST 117TH STREET NEW YORK, 10035 TT−Id: 640A−0038−036

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 610 feet to the SW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Facility Type: Apartment Building/Office Building
Site Status: Active
Expiration Date of the facility's registration certificate: 07/25/2018
Operator Name: CATALINO GONZALEZ
Operator Phone #: (917) 418−7065

Owner Name: JOEL GENDELS − AGENT
Owner Company: MADISON COURT ASSOC, LP
Owner Address: 542 MAIN ST., 2ND FLOOR, NEW ROCHELLE, NY 10801
Owner Type:

TANK NUMBER	TANK STATUS	TANK CONTENT	CAPACITY GALLONS	TANK LOCATION	INSTALL DATE	TEST DATE	CLOSE DATE
001	In Service	#2 Fuel Oil	3500	Aboveground − In Contact with Soil	06/17/2002		

HAZARDOUS WASTE GENERATORS/TRANSPORTERS IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 257 **NYSDEC Name:** **GE−CEL CLEANERS** **Facility Id: NYD981562283**

NYSDEC Address: 1694 PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0030−367
EPA (RCRA) Name: GE−CEL CLEANERS
EPA (RCRA) Address: 1694 PARK AVE NEW YORK, NY 100353937

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 44 feet to the SSW*

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Contact Name: GEORGE BROWN Source Type: Notification

Notification date: 10/01/1986
Incinerator:
Transporter:
Contact Phone: 212−555−1212 Contact Info Date: 10/01/1986

Historically listed as the following USEPA RCRA Generator Size(s) as well:
LARGE QUANTITY GENERATOR

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
NONE	Site reported by US EPA. No hazardous waste activity reported by NYS.						

Map Identification Number 258 **EPA (RCRA) Name:** **CON EDISON SERVICE BOX: 42084** **Facility Id: NYP004298659**

EPA (RCRA) Address: 1700 PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0097−163
NYSDEC Name: CON EDISON
NYSDEC Address: F/O 1700 PARK AVE NEW YORK, NY 10035
SERV BOX 42084

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 119 feet to the NNE*

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 04/04/2013
Contact Name: BENJAMIN BAMONTE Source Type: Implementer Contact Phone: 212−894−9549 Contact Info Date: 05/04/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 259 **NYSDEC Name:** **CONED** **Facility Id: NYP004182044**
NYSDEC Address: 71 E 119TH ST NEW YORK, NY 10001 TT−Id: 740A−0066−883
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: 67 W 119TH ST & LENOX AVE NEW YORK, NY 10026

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 143 feet to the NNW*

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 260 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298659**

NYSDEC Address: F/O 1700 PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0096−922
SERV BOX 42084
EPA (RCRA) Name: CON EDISON SERVICE BOX: 42084
EPA (RCRA) Address: 1700 PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 151 feet to the ENE*

ADDRESS CHANGE INFORMATION
Revised street: IFO 1700 PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 04/04/2013
Contact Name: BENJAMIN BAMONTE Source Type: Implementer Contact Phone: 212−894−9549 Contact Info Date: 05/04/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 261 **EPA (RCRA) Name:** **CON EDISON SERVICE BOX: 42076** **Facility Id: NYP004298642**

EPA (RCRA) Address: 1680 PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0097−162
NYSDEC Name: CON EDISON
NYSDEC Address: F/O 1680 PARK AVE NEW YORK, NY 10035
SERV BOX 42076

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 160 feet to the SSW*

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 04/04/2013
Contact Name: BENJAMIN BAMONTE Source Type: Implementer Contact Phone: 212−894−9549 Contact Info Date: 05/04/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 262 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298642**
NYSDEC Address: F/O 1680 PARK AVE SERV BOX 42076 NEW YORK, NY 10035 TT−Id: 740A−0096−921
EPA (RCRA) Name: CON EDISON SERVICE BOX: 42076
EPA (RCRA) Address: 1680 PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 161 feet to the S*

ADDRESS CHANGE INFORMATION
Revised street: IFO 1680 PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 04/04/2013
Contact Name: BENJAMIN BAMONTE Source Type: Implementer Contact Phone: 212−894−9549 Contact Info Date: 05/04/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 263 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004182044**

EPA (RCRA) Address: 67 W 119TH ST & LENOX AVE NEW YORK, NY 10026 TT−Id: 740A−0074−728
NYSDEC Name: CONED
NYSDEC Address: 71 E 119TH ST NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 177 feet to the NW*

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 264 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004286605**

NYSDEC Address: FO 63 E 119TH ST NEW YORK, NY 10035 TT−Id: 740A−0086−239
SERV BOX 19605
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19605
EPA (RCRA) Address: 63 E 119TH ST FRONT OF NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 200 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: IFO 63 E 119TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 01/31/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1500	POUNDS	GENERATED	2013		

Map Identification Number 265 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298352**

NYSDEC Address: 68 E 120TH ST SERV BOX 19778 NEW YORK, NY 10029 TT−Id: 740A−0085−810
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19778
EPA (RCRA) Address: 68 E 120TH ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 200 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2013		

Map Identification Number 266 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004289765**

NYSDEC Address: FO 1709 PARK AVE NO 119TH ST SERV BOX 42088 NEW YORK, NY 10035 TT−Id: 740A−0086−245

EPA (RCRA) Name: CON EDISON SERVICE BOX: 42088

EPA (RCRA) Address: PARK AVE & E 119TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 208 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: IFO 1709 PARK AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 02/15/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 03/15/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2013		

Map Identification Number 267 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298410**

NYSDEC Address: 64 E 120TH ST SERV BOX 19777 NEW YORK, NY 10029 TT−Id: 740A−0085−812

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19777

EPA (RCRA) Address: 64 E 120TH ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 219 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2013		

Map Identification Number 268 **NYSDEC Name:** **CONED** **Facility Id: NYP004182127**

NYSDEC Address:	62 E 120TH ST	NEW YORK, NY 10001	TT−Id: 740A−0066−888
EPA (RCRA) Name:	CON EDISON		
EPA (RCRA) Address:	E 120TH ST & PARK AVE	NEW YORK, NY 10035	

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 231 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 269 **NYSDEC Name:** **CONED** **Facility Id: NYP004182051**

NYSDEC Address:	61 E 119TH ST	MANHATTAN, NY 10001	TT−Id: 740A−0066−884
EPA (RCRA) Name:	CON EDISON		
EPA (RCRA) Address:	W 119TH ST & LENOX AVE	NEW YORK, NY 10026	

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 232 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	300	POUNDS	GENERATED	2009		

Map Identification Number 270 **NYSDEC Name:** **VEOLIA ENERGY NORTH AMERICA** **Facility Id: NYP004298402**

NYSDEC Address:	58 E 120TH ST SERV BOX 19776	NEW YORK, NY 10029	TT−Id: 740A−0085−811
EPA (RCRA) Name:	CON EDISON SERVICE BOX: 19776		
EPA (RCRA) Address:	58 E 120TH ST	NEW YORK, NY 10029	

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 256 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2013		

Map Identification Number 271 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004182127**
EPA (RCRA) Address: E 120TH ST & PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0074−730
NYSDEC Name: CONED
NYSDEC Address: 62 E 120TH ST NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 272 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004188645**
NYSDEC Address: PARK AVE & EAST 120 ST NEW YORK, NY 10020 TT−Id: 740A−0067−132
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 120TH ST & PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: PARK AVE / E 120TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: DENNIS MICHAELIDES Source Type: Emergency Contact Phone: 718−204−4297 Contact Info Date: 07/29/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1500	POUNDS	GENERATED	2009		

Map Identification Number 273 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004182093**
EPA (RCRA) Address: E 118TH ST& PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0075−246
NYSDEC Name: CONED
NYSDEC Address: 117 E 118TH ST NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST/ PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2009		

Map Identification Number 274 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004761839**
NYSDEC Address: E 118 ST & PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0130−984

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST / PARK AVE
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	2000	POUNDS	GENERATED	2015		

Map Identification Number 275 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004774170**
NYSDEC Address: SEC E 118 ST & PARK AVE V 6340 NEW YORK, NY 10035 TT−Id: 740A−0137−253

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 288 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST / PARK AVE
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2015		

Map Identification Number 276 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298345**

NYSDEC Address: F/O 65 E 120TH ST SERV BOX 19773 NEW YORK, NY 10029 TT−Id: 740A−0086−653

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19773

EPA (RCRA) Address: 65 E 120TH ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 314 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: IFO 65 E 120TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 277 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298436**

NYSDEC Address: 1835 MADISON AVE SERV BOX 50784 NEW YORK, NY 10029 TT−Id: 740A−0085−813

EPA (RCRA) Name: CON EDISON SERVICE BOX: 50784

EPA (RCRA) Address: 1835 MADISON AVE NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 318 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2013		

Map Identification Number 278 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004197406**

EPA (RCRA) Address: 117 E 119TH ST NEW YORK, NY 10035 TT−Id: 740A−0074−836

NYSDEC Name: CONSOLIDATED EDISON

NYSDEC Address: FRONT OF 117 EAST 119 STREET MANHATTAN, NY 10020

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 364 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: HERMAN BAKER Source Type: Emergency Contact Phone: 718−267−3853 Contact Info Date: 10/01/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	200	POUNDS	GENERATED	2009		

Map Identification Number 279 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004197406**

NYSDEC Address: FRONT OF 117 EAST 119 STREET MANHATTAN, NY 10020 TT−Id: 740A−0067−537
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: 117 E 119TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 367 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: IFO 117 E 119TH ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: HERMAN BAKER Source Type: Emergency Contact Phone: 718−267−3853 Contact Info Date: 10/01/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	200	POUNDS	GENERATED	2009		

Map Identification Number 280 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004167748**

NYSDEC Address:	F/O 111 E 118TH ST	NEW YORK, NY	TT−Id: 740A−0068−706
EPA (RCRA) Name:	CON EDISON		
EPA (RCRA) Address:	111 118TH ST & LENOX AVE	NEW YORK, NY 10026	

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 385 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: IFO 111 E 118TH ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: MICHAEL BETO Source Type: Emergency Contact Phone: 917−337−5519 Contact Info Date: 04/20/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	750	POUNDS	GENERATED	2009		

Map Identification Number 281 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298089**

NYSDEC Address:	58 E 121ST ST SERV BOX 19930	NEW YORK, NY 10029	TT−Id: 740A−0085−806
EPA (RCRA) Name:	CON EDISON SERVICE BOX: 19930		
EPA (RCRA) Address:	58 E 121ST ST	NEW YORK, NY 10035	

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 01/21/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 02/21/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 282 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298097**

NYSDEC Address: 68 E 121ST ST, SERV BOX 19932, NEW YORK, NY 10029 TT−Id: 740A−0085−807
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19932
EPA (RCRA) Address: 68 E 121ST ST, NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/02/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/02/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 283 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298105**

NYSDEC Address: 72 E 121ST ST SERV BOX 19933 NEW YORK, NY 10029 TT−Id: 740A−0085−808

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19933

EPA (RCRA) Address: 72 E 121ST ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal:
Storer:
Receives offsite waste:
Treatment facility:
Notification date: None Given
Incinerator:
Transporter:

Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/02/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/02/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 284 **NYSDEC Name:** **VEOLIA ENERGY NORTH AMERICA** **Facility Id: NYP004298113**

NYSDEC Address: 80 E 121ST ST SERV BOX 19934 NEW YORK, NY 10029 TT−Id: 740A−0085−809

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19934

EPA (RCRA) Address: 80 E 121ST ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal:
Storer:
Receives offsite waste:
Treatment facility:
Notification date: None Given
Incinerator:
Transporter:

Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/02/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/02/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 285 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004626438**
NYSDEC Address: 50 E 121 ST NEW YORK, NY 10035 TT−Id: 740A−0120−557
SB19929

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: 50 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2014		

Map Identification Number 286 **NYSDEC Name:** **NYC BOARD OF EDUCATION − PS 79** **Facility Id: NYR000009597**
NYSDEC Address: 55 EAST 120TH STREET MANHATTAN, NY 10035 TT−Id: 740A−0029−549
EPA (RCRA) Name: NYC DEPT OF EDUCATION − PS 79M
EPA (RCRA) Address: 55 E 120TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 389 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: 55 E 120TH STREET
Revised zip code: NO CHANGE

US EPA RCRA Type: SMALL QUANTITY GENERATOR
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: 07/27/1995
Incinerator:
Transporter:
Contact Name: ROBERT GUASTA Source Type: Implementer Contact Phone: 718−349−5590 Contact Info Date: 01/01/2007
Contact Name: ALEXANDER LEMPERT Source Type: Notification Contact Phone: 718−472−8501 Contact Info Date: 10/21/2014

Historically listed as the following USEPA RCRA Generator Size(s) as well:
CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
B004	PCB Articles containing 50 ppm or greater of PCBs but less than 500 ppm PCBs.	1043	KILOGRAMS	GENERATED	2015		
B007	Other PCB Wastes including contaminated soil, solids, sludges, clothing, etc.	119	KILOGRAMS	GENERATED	2015		
D008	Lead	100	POUNDS	GENERATED	1995		

Map Identification Number 287 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004201174**
NYSDEC Address: MADISON AVE & E 119TH ST NEW YORK, NY TT−Id: 740A−0072−016
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 119TH ST & MADISON AVE NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 391 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 119TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: MICHAEL BETO Source Type: Emergency Contact Phone: 917−337−5519 Contact Info Date: 01/16/2010

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
B007	Other PCB Wastes including contaminated soil, solids, sludges, clothing, etc.	900	KILOGRAMS	GENERATED	2010		

Map Identification Number 288 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004345849**

NYSDEC Address: 100 E 118 ST VAULT #6340 NEW YORK, NY 10035 TT−Id: 740A−0094−151

EPA (RCRA) Name: CON EDISON VAULT: 6340

EPA (RCRA) Address: 100 E 118TH ST FRONT OF NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 398 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 100 E 118TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JUAN RODRIGUEZ Source Type: Emergency Contact Phone: 347−865−5931 Contact Info Date: 08/14/2013
Contact Name: JUAN RODRIGUEZ Source Type: Implementer Contact Phone: 347−865−5931 Contact Info Date: 09/14/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	800	POUNDS	GENERATED	2013		

Map Identification Number 289 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004740734**

NYSDEC Address: 100 E 118 ST MH42080 NEW YORK, NY 10035 TT−Id: 740A−0131−628

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 398 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 100 E 118TH ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2015		

Map Identification Number 290 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004166526**

EPA (RCRA) Address: 130 E 119TH ST W OF LEXINGTON AVE NEW YORK, NY 10035 TT−Id: 740A−0077−031
NYSDEC Name: CONSOLIDATED EDISON
NYSDEC Address: 112−130 E 199TH ST NEW YORK, NY

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 409 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: TIMOTHY REGAN Source Type: Emergency Contact Phone: 917−416−5436 Contact Info Date: 04/08/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1500	POUNDS	GENERATED	2009		

Map Identification Number 291 **NYSDEC Name:** **CONED** **Facility Id: NYP004182093**

NYSDEC Address: 117 E 118TH ST NEW YORK, NY 10001 TT−Id: 740A−0066−887
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 118TH ST& PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 412 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2009		

Map Identification Number 292 **NYSDEC Name:** **CON EDISON SERVICE BOX: 42070** **Facility Id: NYP004298394**
NYSDEC Address: 1664 PARK AVE NEW YORK, NY 10029 TT−Id: 740A−0092−547
EPA (RCRA) Name: CON EDISON SERVICE BOX: 42070
EPA (RCRA) Address: 1664 PARK AVE NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 423 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR

NONE Site reported by US EPA. No hazardous waste activity reported by NYS.

Map Identification Number 293 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298894**
NYSDEC Address: 1664 PARK AVE NEW YORK, NY 10029 TT−Id: 740A−0092−555
SERV BOX 42070

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 423 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 294 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004299905**
NYSDEC Address: FT OF 1815−1817 MADISON AVE & 118TH ST NEW YORK, NY 10035 TT−Id: 740A−0096−928
SERV BOX #50775
EPA (RCRA) Name: CON EDISON SERVICE BOX: 50775
EPA (RCRA) Address: MADISON AVE & 118TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 426 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: IFO 1815−1817 MADISON AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Notification date: None Given
Incinerator:
Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 04/08/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 05/08/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 295 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004299897**

NYSDEC Address: FT OF 1816−1818 MADISON AVE & 118TH ST SERV BOX 50772 NEW YORK, NY 10035 TT−Id: 740A−0096−927
EPA (RCRA) Name: CON EDISON SERVICE BOX: 50772
EPA (RCRA) Address: MADISON AVE & 118TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 446 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: IFO 1816−1818 MADISON AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 04/08/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 05/08/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 296 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004182085**

EPA (RCRA) Address: E 118TH ST & MADISON AVE NEW YORK, NY 10035 TT−Id: 740A−0075−261
SB 19441
NYSDEC Name: CONED
NYSDEC Address: 14 E 118TH ST NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 471 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST / MADISON AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 297 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004182143**

EPA (RCRA) Address: E 118TH ST & MADISON AVE NEW YORK, NY 10035 TT−Id: 740A−0075−262
SB 19442
NYSDEC Name: CONED
NYSDEC Address: 20 E 118TH ST NEW YORK, NY 10001

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 471 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: E 118TH ST / MADISON AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 298 **EPA (RCRA) Name:** **CON EDISON SERVICE BOX: 50772** **Facility Id: NYP004299897**
EPA (RCRA) Address: MADISON AVE & 118TH ST NEW YORK, NY 10035 TT−Id: 740A−0097−165
NYSDEC Name: CON EDISON
NYSDEC Address: FT OF 1816−1818 MADISON AVE & 118TH ST NEW YORK, NY 10035
SERV BOX 50772

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 471 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 118TH ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 04/08/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 05/08/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 299 **EPA (RCRA) Name:** **CON EDISON SERVICE BOX: 50775** **Facility Id: NYP004299905**

EPA (RCRA) Address: MADISON AVE & 118TH ST NEW YORK, NY 10035 TT−Id: 740A−0097−166
NYSDEC Name: CON EDISON
NYSDEC Address: FT OF 1815−1817 MADISON AVE & 118TH ST NEW YORK, NY 10035
SERV BOX #50775

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 471 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 118TH ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 04/08/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 05/08/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 300 **NYSDEC Name:** **CONED** **Facility Id: NYP004182119**

NYSDEC Address: E120TH ST MANHATTAN, NY 10001 TT−Id: 740A−0068−048
MADISON AVE
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: MADISON AVE & E 120TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 476 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / MADISON AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 301 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004526901**
NYSDEC Address: E 120 ST S 23 E MADISON AV NEW YORK, NY 10035 TT−Id: 740A−0111−739
SB0765
EPA (RCRA) Name: CON EDISON TRANSFORMER MANHOLE: 0765
EPA (RCRA) Address: E 120TH ST & MADISON AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 476 feet to the NNW

ADDRESS CHANGE INFORMATION
Revised street: E 120TH ST / MADISON AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 05/09/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 06/09/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1500	POUNDS	GENERATED	2014		

Map Identification Number 302 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004695771**
NYSDEC Address: 1787 MADISON AVE & 117 ST NEW YORK, NY 10029 TT−Id: 740A−0131−249
V6998

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 501 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: 1787 MADISON AVE
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1500	POUNDS	GENERATED	2014		

Map Identification Number 303 **NYSDEC Name:** **NYCHA − ROBINSON** **Facility Id: NYR000053082**
NYSDEC Address: 1940 LEXINGTON AVE NEW YORK, NY 10035 TT−Id: 740A−0027−928
EPA (RCRA) Name: NYCHA − ROBINSON
EPA (RCRA) Address: 1940 LEXINGTON AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 525 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste:
Storer: Treatment facility:
Contact Name: FRANK OCELLO Source Type: Notification

Notification date: 04/02/1998
Incinerator:
Transporter:
Contact Phone: 212−306−3229 Contact Info Date: 04/02/1998

Historically listed as the following USEPA RCRA Generator Size(s) as well:
SMALL QUANTITY GENERATOR

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
NONE	Site reported by US EPA. No hazardous waste activity reported by NYS.						

Map Identification Number 304 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004167805**

NYSDEC Address: N/S E 121 ST 165‘ EAST OF PARK AV NEW YORK, NY 10035 TT−Id: 740A−0068−260

EPA (RCRA) Name: CON EDISON − MANHOLE 19936

EPA (RCRA) Address: N/S E 121 ST 165‘ EAST OF PARK AV NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 537 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 121ST ST / PARK AVE
Revised zip code: UNKNOWN

US EPA RCRA Type: LARGE QUANTITY GENERATOR
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: FRANKLYN MURRAY Source Type: Annual/Biennial Report update with Notification Contact Phone: 212−460−2808 Contact Info Date: 03/23/2010
Contact Name: MICHAEL BETO Source Type: Emergency Contact Phone: 917−337−5519 Contact Info Date: 04/20/2009

Historically listed as the following USEPA RCRA Generator Size(s) as well:
CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	6500	POUNDS	GENERATED	2009		

Map Identification Number 305 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004188942**

EPA (RCRA) Address: E 121ST ST & PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0074−810
NYSDEC Name: CONSOLIDATED EDISON
NYSDEC Address: FRONT OF 1743 PARK AVE NEW YORK, NY 10020

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 537 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: E 121ST ST / PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ANTONIO DELGADO Source Type: Emergency Contact Phone: 212−580−8383 Contact Info Date: 07/30/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	600	POUNDS	GENERATED	2009		

Map Identification Number 306 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004154258**

NYSDEC Address: SEC E 117TH ST & PARK AVE NEW YORK, NY TT−Id: 740A−0062−719
MH40269

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 538 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: E 117TH ST / PARK AVE
Revised zip code: 10035

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
More than one waste code was reported for the following waste amount:		100	KILOGRAMS	GENERATED	2007		
D008	Lead						
B007	Other PCB Wastes including contaminated soil, solids, sludges, clothing, etc.						

Map Identification Number 307 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004223855**

NYSDEC Address: S/W/C E 117TH ST 7 PARK AVE NEW YORK, NY TT−Id: 740A−0076−511
EPA (RCRA) Name: CON EDISON SERVICE BOX 42066
EPA (RCRA) Address: E 117TH & PARK AVE SW COR NEW YORK, NY 10026

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 538 feet to the SSW

ADDRESS CHANGE INFORMATION
Revised street: E 117TH ST / PARK AVE
Revised zip code: UNKNOWN

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 01/13/2011
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 02/12/2011

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2011		

Map Identification Number 308 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004423422**

NYSDEC Address: F/O 58 E 121 ST NEW YORK, NY 10035 TT−Id: 740A−0105−027

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 544 feet to the N

ADDRESS CHANGE INFORMATION
Revised street: IFO 58 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	300	POUNDS	GENERATED	2014		

Map Identification Number 309 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004422176**

NYSDEC Address: 65 E 121 ST & PARK AVE NEW YORK, NY 10035 TT−Id: 740A−0105−042
EPA (RCRA) Name: CON EDISON MANHOLE: 19927
EPA (RCRA) Address: 65 E 121ST ST & PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 550 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: IFO 65−67 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 01/19/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 02/19/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	10000	POUNDS	GENERATED	2014		

Map Identification Number 310 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004166872**
EPA (RCRA) Address: 125 E 117TH ST E OF 3RD AVE NEW YORK, NY 10035 TT−Id: 740A−0074−776
NYSDEC Name: CONSOLIDATED EDISON
NYSDEC Address: 215 E 117 ST NEW YORK, NY

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 551 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: 125 E 117TH ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ANTHONY BUDA Source Type: Emergency Contact Phone: 917−440−1809 Contact Info Date: 04/13/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2009		

Map Identification Number 311 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298337**
NYSDEC Address: 115 E 117TH ST SERV BOX 19295 NEW YORK, NY 10029 TT−Id: 740A−0092−543
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19295
EPA (RCRA) Address: 115 E 117TH ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 551 feet to the SSE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 312 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004167862**

NYSDEC Address: 1748 PARK AVE NEW YORK, NY TT−Id: 740A−0066−386
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: 1748 PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (4)
Approximate distance from property: 551 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: DAVID DUKE Source Type: Emergency Contact Phone: 917−559−8971 Contact Info Date: 04/21/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	425	POUNDS	GENERATED	2009		

Map Identification Number 313 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004166153**

NYSDEC Address: 1832 MADISON AVE MANHATTAN, NY 10020 TT−Id: 740A−0066−537
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: 1832 MADISON AVE & E 85TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 568 feet to the NW

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: MICHAEL BETO Source Type: Emergency Contact Phone: 917−337−5519 Contact Info Date: 04/07/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	425	POUNDS	GENERATED	2009		

Map Identification Number 314 **NYSDEC Name:** **NYC DEPT OF EDUCATION − PS 149M TANDEM WITH M207** **Facility Id: NYR000213579**
NYSDEC Address: 34 WEST 118TH STREET MANHATTAN, NY 10026 TT−Id: 740A−0130−730
EPA (RCRA) Name: NYC DEPT OF EDUCATION − PS 149M TANDEM W
EPA (RCRA) Address: 34 E 118TH ST NEW YORK, NY 10026

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 571 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: 34 E 118TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: SMALL QUANTITY GENERATOR Notification date: 10/21/2014
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ALEXANDER LEMPERT Source Type: Notification Contact Phone: 718−472−8501 Contact Info Date: 10/21/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
B007	Other PCB Wastes including contaminated soil, solids, sludges, clothing, etc.	1781	KILOGRAMS	GENERATED	2015		

Map Identification Number 315 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004794830**
NYSDEC Address: 1932 LEXINGTON AVE NEW YORK, NY 10035 TT−Id: 740A−0137−208
SB 39191

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 573 feet to the SE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2015		

Map Identification Number 316 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004428348**
NYSDEC Address: F/O 104 EAST 117TH ST NEW YORK, NY 10035 TT−Id: 740A−0105−025
SB19297
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19297
EPA (RCRA) Address: 104 E 117TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 579 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: IFO 104 EAST 117TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 01/28/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 02/28/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2014		

Map Identification Number 317 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004474789**

NYSDEC Address: F/O 104 E 117TH ST SERVICE BOX # 19297 MANHATTAN, NY 10035 TT−Id: 740A−0113−615

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19297

EPA (RCRA) Address: 104 E 117TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 579 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: IFO 104 E 117TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 03/21/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 04/21/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2014		

Map Identification Number 318 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004622700**

NYSDEC Address: 11 E 118 ST & 5 AV SB19441 NEW YORK, NY 10035 TT−Id: 740A−0120−516

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 600 feet to the WNW

ADDRESS CHANGE INFORMATION
Revised street: 11 E 118TH ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2014		

Map Identification Number 319 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004188942**

NYSDEC Address: FRONT OF 1743 PARK AVE NEW YORK, NY 10020 TT−Id: 740A−0067−477
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 121ST ST & PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 605 feet to the NE

ADDRESS CHANGE INFORMATION
Revised street: IFO 1743 PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ANTONIO DELGADO Source Type: Emergency Contact Phone: 212−580−8383 Contact Info Date: 07/30/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	600	POUNDS	GENERATED	2009		

Map Identification Number 320 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004299913**

NYSDEC Address: FT OF 22 E 118TH ST E OF 15TH AVE SERV BOX # 19446 NEW YORK, NY 10035 TT−Id: 740A−0093−131

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19446

EPA (RCRA) Address: E 118TH ST & E OF 5TH AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 613 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: IFO 22 E 118TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 04/08/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 05/08/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 321 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004296869**

NYSDEC Address: F OF 1934 LEXINGTON AVE & 119TH ST SERV BOX 39197 NEW YORK, NY 10035 TT−Id: 740A−0085−973

EPA (RCRA) Name: CON EDISON SERVICE BOX: 39197

EPA (RCRA) Address: LEXINGTON & 119TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 613 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: IFO 1934 LEXINGTON AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 03/28/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 04/28/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	250	POUNDS	GENERATED	2013		

Map Identification Number 322 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004315644**

NYSDEC Address: FO 111 E 120 ST NEW YORK, NY 10035 TT−Id: 740A−0093−505
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19779
EPA (RCRA) Address: 111 E 120ND ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 616 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: IFO 111 E 120TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: RICARDO CARTY Source Type: Emergency Contact Phone: 646−772−3407 Contact Info Date: 05/22/2013
Contact Name: RICARDO CARTY Source Type: Implementer Contact Phone: 646−772−3407 Contact Info Date: 06/22/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	50	POUNDS	GENERATED	2013		

Map Identification Number 323 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004188132**

NYSDEC Address: E 119TH ST & LEXINGTON AVE NEW YORK, NY 10035 TT−Id: 740A−0071−993
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 119TH ST & LEXINGTON AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 631 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: E 119TH ST / LEXINGTON AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: DENNIS MICHAELIDES Source Type: Emergency Contact Phone: 718−204−4297 Contact Info Date: 07/29/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
NONE	Site reported by US EPA. No hazardous waste activity reported by NYS.						

Map Identification Number 324 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004296430**
NYSDEC Address: NW COR LEXINGTON AVE & 119TH ST SERV BOX 39195 NEW YORK, NY 10035 TT−Id: 740A−0086−761
EPA (RCRA) Name: CON EDISON SERVICE BOX: 39195
EPA (RCRA) Address: LEXINGTON AVE & 119TH ST NW COR NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 631 feet to the ESE

ADDRESS CHANGE INFORMATION
Revised street: LEXINGTON AVE / E 119TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: JOSE MONTALVO Source Type: Emergency Contact Phone: 212−427−1331 Contact Info Date: 03/27/2013
Contact Name: JOSE MONTALVO Source Type: Implementer Contact Phone: 212−427−1331 Contact Info Date: 04/27/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2013		

Map Identification Number 325 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298071**

NYSDEC Address: 55 E 121ST ST SERV BOX 19925 NEW YORK, NY 10029 TT−Id: 740A−0085−640

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19925

EPA (RCRA) Address: 55 E 121ST ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/02/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/02/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 326 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004420220**

NYSDEC Address: 73 E 121 ST SB19928 NEW YORK, NY 10035 TT−Id: 740A−0101−462

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19928

EPA (RCRA) Address: 73 E 121ST ST FRONT OF NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: 73 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 01/16/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 02/16/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2014		

Map Identification Number 327 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004677514**
NYSDEC Address: 73 E 121ST ST & MADISON AVE NEW YORK, NY 10035 TT−Id: 740A−0130−806
SB 19928

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: 73 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2014		

Map Identification Number 328 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004688008**
NYSDEC Address: 60 E 122 ST MADISON AV NEW YORK, NY 10035 TT−Id: 740A−0130−823
V2210

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (3)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: 60 E 122ND ST
Revised zip code: NO CHANGE

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	800	POUNDS	GENERATED	2014		

Map Identification Number 329 **NYSDEC Name:** **HENRY J CARTER SPECIALITY HOSPITAL** **Facility Id: NYR000085746**

NYSDEC Address: 1879 MADISON AVE NEW YORK, NY 10035 TT−Id: 740A−0024−954
EPA (RCRA) Name: NORTH GENERAL HOSPITAL
EPA (RCRA) Address: 1879 MADISON AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: SMALL QUANTITY GENERATOR
Notification date: 03/16/2000
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS LAZZARO Source Type: Implementer Contact Phone: 212−423−4365 Contact Info Date: 01/01/2007
Contact Name: THOMAS LAZZARO Source Type: Notification Contact Phone: 212−423−4365 Contact Info Date: 09/21/2001

Historically listed as the following USEPA RCRA Generator Size(s) as well:
CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR

US EPA RCRA Violations:
Violation Type: Generators − Pre−transport
Violation Number: 0001 Location: NY
Former Citation:
Responsible Agency: EPA
Violation Determination Date: 03/12/2010
Violation Return to Compliance: 03/12/2010

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D001	Solid waste that exhibits the characteristic of ignitability	35	POUNDS	GENERATED	2016	1050	2006

NYS DEC Manifested Waste Transactions for NYR000085746 continued −−−

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
More than one waste code was reported for the following waste amount:		4	POUNDS	GENERATED	2016	5	2015
P001	2H−1−Benzopyran−2−one, 4−hydroxy−3−(3−oxo−1−phenylbutyl)−, & salts, when present						
P075	Nicotine, & salts						
More than one waste code was reported for the following waste amount:		295	POUNDS	GENERATED	2016	2980	2015
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U150	Melphalan						
More than one waste code was reported for the following waste amount:		90	POUNDS	GENERATED	2016		
D001	Solid waste that exhibits the characteristic of ignitability						
D009	Mercury						
U035	Benzenebutanoic acid						
D026	Cresol						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
D002	Solid waste that exhibits the characteristic of corrosivity	25	POUNDS	GENERATED	2015	910	2006
More than one waste code was reported for the following waste amount:		20	POUNDS	GENERATED	2015		
D001	Solid waste that exhibits the characteristic of ignitability						
D002	Solid waste that exhibits the characteristic of corrosivity						
More than one waste code was reported for the following waste amount:		65	POUNDS	GENERATED	2015	2030	2007
D001	Solid waste that exhibits the characteristic of ignitability						
F003	Spent non−halogenated solvents						
More than one waste code was reported for the following waste amount:		1576	POUNDS	GENERATED	2015		
D001	Solid waste that exhibits the characteristic of ignitability						
D007	Chromium						
D009	Mercury						
D010	Selenium						
D011	Silver						
More than one waste code was reported for the following waste amount:		220	POUNDS	GENERATED	2015		
D001	Solid waste that exhibits the characteristic of ignitability						
D009	Mercury						
D024	m−Cresol						
U188	Phenol						

NYS DEC Manifested Waste Transactions for NYR000085746 continued −−− see previous page

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
U035	Benzenebutanoic acid						
More than one waste code was reported for the following waste amount:		120	POUNDS	GENERATED	2015		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U150	Melphalan						
U035	Benzenebutanoic acid						
More than one waste code was reported for the following waste amount:		460	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U150	Melphalan						
U205	Selenium sulfide SeS2 (R,T)						
More than one waste code was reported for the following waste amount:		160	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
D024	m−Cresol						
U205	Selenium sulfide SeS2 (R,T)						
U035	Benzenebutanoic acid						
More than one waste code was reported for the following waste amount:		110	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U150	Melphalan						
U188	Phenol						
More than one waste code was reported for the following waste amount:		690	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
U205	Selenium sulfide SeS2 (R,T)						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
More than one waste code was reported for the following waste amount:		315	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						

NYS DEC Manifested Waste Transactions for NYR000085746 continued −−− see previous page

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U188	Phenol						
U205	Selenium sulfide SeS2 (R,T)						
More than one waste code was reported for the following waste amount:		140	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U205	Selenium sulfide SeS2 (R,T)						
D026	Cresol						
More than one waste code was reported for the following waste amount:		380	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
U035	Benzenebutanoic acid						
U150	Melphalan						
U205	Selenium sulfide SeS2 (R,T)						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
More than one waste code was reported for the following waste amount:		355	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D007	Chromium						
D009	Mercury						
D024	m−Cresol						
U205	Selenium sulfide SeS2 (R,T)						
More than one waste code was reported for the following waste amount:		1445	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D007	Chromium						
D009	Mercury						
D026	Cresol						
U205	Selenium sulfide SeS2 (R,T)						
More than one waste code was reported for the following waste amount:		475	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D007	Chromium						
D010	Selenium						
D026	Cresol						
U205	Selenium sulfide SeS2 (R,T)						

NYS DEC Manifested Waste Transactions for NYR000085746 continued −−−

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
More than one waste code was reported for the following waste amount:		600	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
U035	Benzenebutanoic acid						
U150	Melphalan						
U205	Selenium sulfide SeS2 (R,T)						
D024	m−Cresol						
More than one waste code was reported for the following waste amount:		335	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
D007	Chromium						
U205	Selenium sulfide SeS2 (R,T)						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
More than one waste code was reported for the following waste amount:		280	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
D026	Cresol						
U035	Benzenebutanoic acid						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U205	Selenium sulfide SeS2 (R,T)						
More than one waste code was reported for the following waste amount:		60	POUNDS	GENERATED	2014		
D001	Solid waste that exhibits the characteristic of ignitability						
U150	Melphalan						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U110	1−Propanamine, N−propyl− (I)						
D009	Mercury	50	POUNDS	GENERATED	2012	150	2006
D002	Solid waste that exhibits the characteristic of corrosivity	180	GALLONS	GENERATED	2011		
D011	Silver	300	POUNDS	GENERATED	2011		
More than one waste code was reported for the following waste amount:		100	GALLONS	GENERATED	2011		
D001	Solid waste that exhibits the characteristic of ignitability						
F003	Spent non−halogenated solvents						
More than one waste code was reported for the following waste amount:		15	GALLONS	GENERATED	2011		
D002	Solid waste that exhibits the characteristic of corrosivity						
D011	Silver						

NYS DEC Manifested Waste Transactions for NYR000085746 continued −−−

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
More than one waste code was reported for the following waste amount:		35	POUNDS	GENERATED	2011		
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide						
U010	Mitomycin C						
U058	2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide	25	POUNDS	GENERATED	2010	2650	2000
U188	Phenol	20	POUNDS	GENERATED	2010	68	2009
B002	Petroleum oil or other liquid containing 50 ppm < PCBs < 500 ppm	45	POUNDS	GENERATED	2009		
U122	Formaldehyde	115	POUNDS	GENERATED	2009		
D002	Solid waste that exhibits the characteristic of corrosivity	680	KILOGRAMS	GENERATED	2008		
More than one waste code was reported for the following waste amount:		40	POUNDS	GENERATED	2008		
D002	Solid waste that exhibits the characteristic of corrosivity						
D011	Silver						
More than one waste code was reported for the following waste amount:		80	POUNDS	GENERATED	2008		
D001	Solid waste that exhibits the characteristic of ignitability						
B003	Petroleum oil or other liquid containing 500 ppm or greater of PCBs.						
D007	Chromium	6	POUNDS	GENERATED	2006		
D016	2,4−D, (2,4−Dichlorophenoxyacetic acid).	300	POUNDS	GENERATED	2006		
F003	Spent non−halogenated solvents	960	POUNDS	GENERATED	2006		
U010	Mitomycin C	195	POUNDS	GENERATED	2006		
U035	Benzenebutanoic acid	50	POUNDS	GENERATED	2006		
D001	Solid waste that exhibits the characteristic of ignitability	18	GALLONS	GENERATED	2003		
F003	Spent non−halogenated solvents	10	GALLONS	GENERATED	2003	60	2002
D003	Solid waste that exhibits the characteristic of reactivity	3	POUNDS	GENERATED	2002		
D005	Barium	20	POUNDS	GENERATED	2002		
D008	Lead	10	POUNDS	GENERATED	2002		

NOTE: 2016 waste amounts are for 1/1/2016 to 4/22/2016 only

Map Identification Number 330 **NYSDEC Name:** **NYC HEALTH & HOSPITAL CORP** **Facility Id: NYR000191049**

NYSDEC Address: 1752 PARK AVENUE NEW YORK, NY 10035 TT−Id: 740A−0080−018
EPA (RCRA) Name: HENRY J CARTER SPECIALTY HOSPITAL & NURS
EPA (RCRA) Address: 1752 PARK AVE NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 641 feet to the NNE

ADDRESS CHANGE INFORMATION
Revised street: 1752 PARK AVE
Revised zip code: NO CHANGE

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Land Disposal: Receives offsite waste: Notification date: 02/17/2016
Storer: Treatment facility: Incinerator:
Transporter:

Contact Name: JOSEPH THOMPSON Source Type: Implementer Contact Phone: 646−560−1502 Contact Info Date: 09/17/2012
Contact Name: SIMORE WARREN Source Type: Notification Contact Phone: 718−319−3948 Contact Info Date: 02/17/2016
Contact Name: JOSEPH THOMPSON Source Type: Temporary Contact Phone: 646−560−1502 Contact Info Date: 02/24/2012

Historically listed as the following USEPA RCRA Generator Size(s) as well:
LARGE QUANTITY GENERATOR

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	969720	POUNDS	GENERATED	2012		

Map Identification Number 331 **NYSDEC Name:** **CONED** **Facility Id: NYP004182143**

NYSDEC Address: 20 E 118TH ST NEW YORK, NY 10001 TT−Id: 740A−0066−889
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 118TH ST & MADISON AVE NEW YORK, NY 10035
SB 19442

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 649 feet to the W

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: STEVEN MARTIS Source Type: Emergency Contact Phone: 917−416−5423 Contact Info Date: 06/25/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	400	POUNDS	GENERATED	2009		

Map Identification Number 332 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004298428**
NYSDEC Address: 104 E 117TH ST NEW YORK, NY 10029 TT−Id: 740A−0092−548
SERV BOX 19297
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19297
EPA (RCRA) Address: 107 E 117TH ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 649 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: ROBERT LINDELOF Source Type: Emergency Contact Phone: 917−559−3860 Contact Info Date: 04/03/2013
Contact Name: ROBERT LINDELOF Source Type: Implementer Contact Phone: 917−559−3860 Contact Info Date: 05/03/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 333 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004310819**
NYSDEC Address: 110 E 117 ST NEW YORK, NY 10035 TT−Id: 740A−0093−086
EPA (RCRA) Name: CON EDISON SERVICE BOX: 19298
EPA (RCRA) Address: 110 E 117TH ST NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (1)
Approximate distance from property: 649 feet to the S

ADDRESS CHANGE INFORMATION
Revised street: 110 E 117TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Land Disposal: Receives offsite waste: Notification date: None Given
Storer: Treatment facility: Incinerator:
Transporter:
Contact Name: JUAN RODRIGUEZ Source Type: Emergency Contact Phone: 347−865−5931 Contact Info Date: 05/10/2013
Contact Name: JUAN RODRIGUEZ Source Type: Implementer Contact Phone: 347−865−5931 Contact Info Date: 06/10/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

Map Identification Number 334 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004065215**
NYSDEC Address: V5731−MADISON & 117TH ST NEW YORK, NY 10020 TT−Id: 740A−0029−546

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 654 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: MADISON AV / E 117TH ST
Revised zip code: 10035

US EPA RCRA (Resource Conservation and Recovery Act) information not reported; Site information reported by NYS DEC.

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
B002	Petroleum oil or other liquid containing 50 ppm < PCBs < 500 ppm	809	KILOGRAMS	GENERATED	2000		

Map Identification Number 335 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004426276**

NYSDEC Address:	S/W/C MADISON AVE E 117 ST	NEW YORK, NY 10035	TT−Id: 740A−0105−070
EPA (RCRA) Name:	CON EDISON SERVICE BOX: 50759		
EPA (RCRA) Address:	MADISON AVE & E 117TH ST SW COR	NEW YORK, NY 10035	

MAP LOCATION INFORMATION
Site location mapped by: ADDRESS MATCHING
Approximate distance from property: 654 feet to the WSW

ADDRESS CHANGE INFORMATION
Revised street: MADISON AVE / E 117TH ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: THOMAS TEELING Source Type: Emergency Contact Phone: 212−460−3770 Contact Info Date: 01/26/2014
Contact Name: THOMAS TEELING Source Type: Implementer Contact Phone: 212−460−3770 Contact Info Date: 02/26/2014

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	HISTORIC MAXIMUM YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2014		

Map Identification Number 336 **EPA (RCRA) Name:** **CON EDISON** **Facility Id: NYP004167813**

EPA (RCRA) Address:	N SIDE E 121ST ST 240 FEET E OF PARK AVE SRV BX 19937	NEW YORK, NY 10035	TT−Id: 740A−0074−297
NYSDEC Name:	CONSOLIDATED EDISON SB19937		
NYSDEC Address:	SB19937 1741 E 121ST ST	NEW YORK, NY 10003	

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 656 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 121ST ST / PARK AVE
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: MICHAEL BETO Source Type: Emergency Contact Phone: 917−337−5519 Contact Info Date: 04/20/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2009		

Map Identification Number 337 **NYSDEC Name:** **CONSOLIDATED EDISON** **Facility Id: NYP004188694**
NYSDEC Address: E 121ST ST B/T LEXINGTON & PARK NEW YORK, NY 10020 TT−Id: 740A−0068−532
EPA (RCRA) Name: CON EDISON
EPA (RCRA) Address: E 123RD ST & 3RD AVE SB 19947 NEW YORK, NY 10035

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 656 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: E 121ST ST
Revised zip code: NO CHANGE

Special Note(s): The New York State Department of Environmental Conservation and the U. S. Environmental Protection Agency have reported different locations for this hazardous waste identification number. Available information for both locations is summarized below.

US EPA RCRA Type: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: DENNIS MICHAELIDES Source Type: Emergency Contact Phone: 718−204−4297 Contact Info Date: 07/29/2009

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	1000	POUNDS	GENERATED	2009		

Map Identification Number 338 **NYSDEC Name:** **CON EDISON** **Facility Id: NYP004297453**

NYSDEC Address: F/O 132 E 121ST ST SERV BOX 19952 NEW YORK, NY 10029 TT−Id: 740A−0086−654

EPA (RCRA) Name: CON EDISON SERVICE BOX: 19952

EPA (RCRA) Address: 132 E 121ST ST NEW YORK, NY 10029

MAP LOCATION INFORMATION
Site location mapped by: MANUAL MAPPING (4)
Approximate distance from property: 656 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: IFO 132 E 121ST ST
Revised zip code: NO CHANGE

US EPA RCRA Type: GENERATOR TYPE NOT GIVEN
Notification date: None Given
Land Disposal: Receives offsite waste: Incinerator:
Storer: Treatment facility: Transporter:
Contact Name: BENJAMIN BAMONTE Source Type: Emergency Contact Phone: 212−894−9549 Contact Info Date: 03/31/2013
Contact Name: BENJAMIN BAMONTE Source Type: Implementer Contact Phone: 212−894−9549 Contact Info Date: 04/30/2013

NYS DEC Manifested Waste Summary:
Waste Codes, Waste Units, and Transaction Types are only shown for the most recently reported year.

WASTE CODE	WASTE DESCRIPTION	WASTE AMOUNT	WASTE UNITS	TRANSACTION TYPE	YEAR	HISTORIC MAXIMUM AMOUNT	HISTORIC MAXIMUM YEAR
D008	Lead	500	POUNDS	GENERATED	2013		

NO CHEMICAL STORAGE FACILITIES IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

HISTORIC UTILITY SITES IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 339 **121ST ST**
128−130 E 121ST ST NEW YORK, NY 10035 TT−Id: 800A−0000−217

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (4)
Approximate distance from property: 659 feet to the ENE

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

DATE ASSOCIATED WITH THIS SITE BY
REFERENCED HISTORICAL RECORDS: 1911

COMPANY NAME ASSOCIATED WITH THIS SITES: CONSOLIDATED EDISON

FACILITY TYPE(S) FOUND AT THIS LOCATION: ANNEX
GENERATING STATION

HAZARDOUS SUBSTANCE WASTE DISPOSAL SITES IDENTIFIED WITHIN 1/2 MILE SEARCH RADIUS

PLEASE NOTE: * Compass directions can vary substantially for sites located very close to the subject property address.

Map Identification Number 340 **ODYSSEY HOUSE** **Site Number Id:** **Registry Id: N**
219 E. 121ST STREET NEW YORK, NY 10035 TT−Id: 840A−0000−653

MAP LOCATION INFORMATION
Site location mapped by: PARCEL MAPPING (3)
Approximate distance from property: 1577 feet to the E

ADDRESS CHANGE INFORMATION
Revised street: NO CHANGE
Revised zip code: NO CHANGE

****

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Hazardous Waste Remediation
Hazardous Substance Waste Disposal Site Study

Inventory Status: Removed from the Hazardous Substance Inventory
Reason site did not qualify for the Inventory:
Minimal probability of significant threat

SITE INFORMATION

Site Name: ODYSSEY HOUSE
Site Street: 219 E. 121ST STREET
Site City: NEW YORK
Site Zip: 10035
Region: 2

Site Number:
Registry: No
Registry Site ID: None
RCRA: No
EPA ID:

US EPA No Further Remedial Action Planned? Unknown

Site Code: 5
Description: OTHER OR UNKNOWN

Acres: 0.10
Completed Investigation? Phase 1
Is Site Active: Unknown
Years of Operation: Unknown to Unknown

Quadrangle: MANHATTAN
HRS Score:
HRS Date:

Site Description:

It is the area of a proposed paved playground of a housing, recreation and alcohol & substance abuse services facility.

Owner:	Private	Operator:	Private
Owner Name:	ODYSSEY HOUSE	Operator Name:	SAME
Owner Street:		Operator Street:	SAME
Owner City/ZIP/State:		Operator City/ZIP/State:	
Owner Telephone:	(718)263-6575	Operator Telephone:	Same

SITE IMPACT DATA

Affected Media:

Contamination of...		Hazardous Substance Exposed?	No
		Controlled Site Access?	Yes
...Surface Water?	No	Ambient Air Contamination?	No
...Groundwater?	Unknown	Threat of Direct Contact?	Yes
...Drinking Water?	Unknown	Documented Fish or Wildlife Mortality?	No
Surface Water Class:	Unknown	Impact on Special Status Fish or Wildlife Resource?	No
Groundwater Class:	Unknown	Active Drinking Water Supply?	Unknown

Descriptions:

Surface Water:
Unknown

Groundwater:
Unknown

Drinking Water:
Unknown

Fish or Wildlife Mortality: None provided
Special Status Fish or Wildlife Resource: None provided

Building:
0 feet; north,east,west; housing,recreation,treatment

THREAT TO THE ENVIRONMENT OR PUBLIC HEALTH

Threat to the Environment or the Public Health: Environment/Public Health

Threat Posed by Disposed Hazardous Substance:

Lead contaminated soil, potentially threatening the groundwater underneath. Also, exposure pathway for direct human contact.

HAZARDOUS SUBSTANCES DISPOSED:

VOCs: No Semi−VOCs: No PCBs: No Pesticides: No Metals: Yes Asbestos: No

Hazardous Substances Disposed:
Lead (D008)

SELECTED ANALYTICAL INFORMATION:

Samples Collected:
Surface So, Subsurface, TCLP

Air: None provided
Surface Water: None provided

Surface Soil:
Lead − 14.3 ppm

Waste: None provided
EPToxicity: None provided
Groundwater: None provided
Sediment: None provided

Subsurface Soil:
Unknown

Leachate: None provided
TCLP: None provided

AGENCY INFORMATION:

Regulatory Agencies Involved:
NYSDEC, NYCDEP, NYSDOH

Preparer:
Carlos Villacres(pmb) NYSDEC Env. Engineer 1 August 1, 1994

NO TOXIC AIR, LAND AND WATER RELEASES IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

NO WASTEWATER DISCHARGES IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

NO AIR DISCHARGE FACILITIES IDENTIFIED WITHIN 1/8 MILE SEARCH RADIUS

NO CIVIL & ADMINISTRATIVE ENFORCEMENT DOCKET FACILITIES IDENTIFIED WITHIN THE 1/8 MILE SEARCH RADIUS

NO NYC ENVIRONMENTAL QUALITY REVIEW REQUIREMENTS − "E" DESIGNATION SITES IDENTIFIED WITHIN 250 FT SEARCH RADIUS

U.S. EPA EMERGENCY RESPONSE NOTIFICATION SYSTEM (ERNS) SPILLS
AT THE LOCATION OR POTENTIALLY AT THE LOCATION OF
1678 and 1700 Park Avenue
New York, NY 10035

* Any ERNS Spills listed below are NOT mapped in this report *

ONSITE ERNS (A count of these spills can be found in the distance interval table):
THIS SITE IS NOT FOUND IN THE ERNS DATABASE

POTENTIALLY ONSITE ERNS:
THIS SITE IS NOT FOUND IN THE ERNS DATABASE

Copyright 2016 Toxics Targeting, Inc. May 31, 2016 '1678 and 1700 Park Avenue'

Unmappable facilities for 'New York' County

NPL/CERCLIS/NYSDEC Inactive Haz. Waste or Reg. Qual. Sites

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
NYD980531578	LEROY SHOT & LEAD WORKS	UNKNOWN	NEW YORK	UNKNOWN

Solid Waste Facilities

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
03T22	CON EDISON HELL GATE			10454
31D01	CENTRAL PARK DEMO			UNKNOWN
31D02	PENN CENTRAL DEMO			UNKNOWN
31T06	N.Y. CARTING T.S.			UNKNOWN
		HILLSIDE AVE. & 111TH ST.	MANHATTAN	UNKNOWN
NY00000002077	PENN CENTRAL DEMO	UNKNOWN	UNKNOWN	UNKNOWN

Hazardous Spills − TANK TEST FAILURES − Active

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
1108592	500 ACE AVE − TTF	500 ACE AVE	MANHATTEN	UNKNOWN

Hazardous Spills − MISC. SPILL CAUSES − Active

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
1501141	BUILDING D	75−77 PARK WEST	MANHATTAN	UNKNOWN
1412180	CON ED TUNNEL	MANHATTAN SIDE TUNNEL	MANHATTAN	UNKNOWN
1407927	789 FEET EAST; MANHOLE 56144	1ST AVE	MANHATTAN	UNKNOWN
9930008	VARIOUS LOCATIONS DRUMS	DRUMS VARIOUS LOCATIONS	NEW YORK CITY (5 BOROS)	UNKNOWN

Hazardous Spills − TANK TEST FAILURES − Closed

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
9001811	PIER #192	PORT AUTHORITY PIER #192	NEW YORK	UNKNOWN
8802622	85−09 1ST AVENUE	85−09 1ST AVENUE	NEW YORK CITY	UNKNOWN

Hazardous Spills − UNKNOWN CAUSE OR OTHER CAUSES − Closed

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
1410483	NEW YORK COUNTY EM. RES.	ONE HUNTERS POINT PLAZA		UNKNOWN
9212360	HELLGATE	HELLGATE	BRONX	UNKNOWN
1201003	AT INTERSECTION	WEST 125TH ST AND EXTERIOR ST	BRONX	UNKNOWN
0209904	VARIOUS DEP −BWSO SITES	MISC.	BRONX/QUEENS/MANHATTAN	UNKNOWN
9909586	MANHOLE 52808	FIRST/ BRONKILL RANDALLS	MANHATTAN	10035
9909356	MANHOLE 42241	CENTER ISLAND & PARK RD	MANHATTAN	UNKNOWN
9814860	OLD CERTIFIED CONC. PLANT DCAS −DDC	BET 116TH & 122TH ST	MANHATTAN	UNKNOWN
9811288	MAN HOLE #353	EAST RIVER STATION	MANHATTAN	UNKNOWN
9704385	HUDSON RIVER AREA OF	122ND ST & HUDSON RIVER	MANHATTAN	10027
9413538	STERLING RD & UNION PK RD	STERLING RD & UNION PK RD	MANHATTAN	UNKNOWN
9408638	96TH & 110TH ST	SUWY TUNNEL− 96TH & 110TH	MANHATTAN	UNKNOWN
9307232	113TH ST & CATHEDRAL DR	113TH ST & CATHEDRAL DR	MANHATTAN	UNKNOWN
9101794	LEXINGTON AVE/MANH	LEXINGTON AVENUE	MANHATTAN	UNKNOWN
9006769	RESTAURANT/UNK ADDRESS	UNKNOWN	MANHATTAN	UNKNOWN
8504758	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
8503796	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
8503779	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
8503506	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
8503421	MANHATTAN	MANHATTAN, EAST RIVER	MANHATTAN	WHR10
8503301	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
8503107	MANHATTAN	MANHATTAN	MANHATTAN	UNKNOWN
1101432	ROADWAY	CANAL AND FRONT STREET	MANHATTAN	UNKNOWN
1012387	A LINE SUBWAY STATION	BROADWAY SUBWAY STATION	MANHATTAN	UNKNOWN
1009165	222015; ADAM	ADAM	MANHATTAN	UNKNOWN

1009163	222000; ADAM	ADAM	MANHATTAN	UNKNOWN
1009149	221851; W ST	W ST	MANHATTAN	UNKNOWN
1009030	220841; MARGINAL ST	MARGINAL ST	MANHATTAN	UNKNOWN
1009010	220632; E 118 ST ST	E 118 ST ST	MANHATTAN	10035
1008985	220219; MARGINAL ST	MARGINAL ST	MANHATTAN	UNKNOWN
1008963	220049; W 127 ST	W 127 ST	MANHATTAN	10027
1008930	219761; 5 AVE	5 AVE	MANHATTAN	UNKNOWN
0910600	MANHOLE # 5107	NORTH SIDE OF EAST NEW YORK AVE	MANHATTAN	UNKNOWN
0904911	CENTRAL PARK LAKE − ALGAL BLOOM	110TH ST	MANHATTAN	UNKNOWN
0712336	ON ROADWAY	100 110TH STREET	MANHATTAN	UNKNOWN
0609717	BLDG	123RD ST	MANHATTAN	UNKNOWN
0407163	WARDS ISLAND	EAST RIVER	MANHATTAN	UNKNOWN
0405457	SERVICE BOX 60707	MADISON AVE	MANHATTAN	UNKNOWN
0402835	UNKNOWN CON ED STRUCTURE	NORTHEAST CORNER AND EAST	MANHATTAN	UNKNOWN
0310936	VAULT 1460	ST NICHOLAS	MANHATTAN	UNKNOWN
0302630	V8770	5111−13 5TH AVE	MANHATTAN	UNKNOWN
0301650	CONSTRUCTION SITE	NW CORNER OF 125TH STREET	MANHATTAN	UNKNOWN
0211245	APARTMENT BUILDING	204 121ST ST	MANHATTAN	UNKNOWN
0007797	MANHOLE 38334	WEST SIDE MADISON AVE	MANHATTAN	UNKNOWN
1006338	RAW SEWAGE	UNKNOWN	MANHATTEN	UNKNOWN
0310326	SPILL NUMBER 0310326	1400 SOUTH PARK AVE	NEW JERSEY	UNKNOWN
9905530	VARIOUS LOCAIONS	CITY AND WESTCHESTER	NEW YORK	UNKNOWN
9808577	SPILL NUMBER 9808577	1500 HARVARD BLVD	NEW YORK	UNKNOWN
8907255	HERTZ RENT A CAR/MANH		NEW YORK	UNKNOWN
8604519	NEW YORK	NEW YORK	NEW YORK	UNKNOWN
1501950	MAN HOLE/55141	2 AVE AND MARGINAL ST	NEW YORK	UNKNOWN
1405089	PIER 25	PIER 25	NEW YORK	UNKNOWN
1308812	DRILL BLD 90	DRILL	NEW YORK	UNKNOWN
1305917	UNDERGROUND COLUMN # 143 + 50	BETWEEN 145TH AND 157TH	NEW YORK	UNKNOWN
0814541	214154; LEXINGTON AVE.	LEXINGTON AVE.	NEW YORK	UNKNOWN
0406845	SPILL NUMBER 0406845	BAYWAY TERMINAL−LINDEN NJ	NEW YORK	UNKNOWN
0302841	CENTRAL PARK	DPR MINERAL SPRINGS FACIL	NEW YORK	UNKNOWN
0210329	OSTANKINO	NEW YORK	NEW YORK	UNKNOWN
0210315	PEARLMAR	NEW YORK	NEW YORK	UNKNOWN
0110864	ON MARIA KNUTSEN VESSEL	KINDER MORGAN DOCK 4	NEW YORK	UNKNOWN
8606984	UNKNOWN ADDRESS !	UNKNOWN	NEW YORK CITY	UNKNOWN
0410928	EAST RIVER HELLGATE	EAST RIVER	NEW YORK CITY	10035
8607173	UNK	UNKNOWN	UNKNOWN	UNKNOWN

Hazardous Spills − MISC. SPILL CAUSES − Closed

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
1010037	DRILL	DRILL	DRILL	UNKNOWN
1408093	DEMOLITION AREA	666 S FRONT ST	ELIZABETH , NEW JERSERY	UNKNOWN
1400120	CONSTRUCTION SITE	125TH STREET	HARLEM	UNKNOWN
1501844	TIDAL MANHOLE 59008	MARGINAL ST & 3RD AVE	MAHATTAN	UNKNOWN
1006174	SEWAGE DRAIN	BETWEEN 125TH AND 124TH AVE	MAHATTAN	UNKNOWN
9907607	CANAL	SANITATION	MANHATTAN	UNKNOWN
9714182	125TH STREET TO	62 ND STREET	MANHATTAN	UNKNOWN
9713418	UNKNOWN	UNKNOWN	MANHATTAN	UNKNOWN
9605028	VAULT #6328	EAST 121ST ST	MANHATTAN	10035
9506730	TANGO PIER	TANGO PIER	MANHATTAN	UNKNOWN
9414330	5 MORGAN CT	5 MORGAN CT	MANHATTAN	UNKNOWN
9410330	115 LAKE ROAD	115 LAKE ROAD	MANHATTAN	UNKNOWN
9402295	LOWER LEVEL EB #12	LOWER LEVER EB #12	MANHATTAN	UNKNOWN
9312441	35 GROSS STREET	35 GROSS STREET	MANHATTAN	UNKNOWN
9304809	PLANDOMD ROAD ?	PLANDOMD ROAD?	MANHATTAN	UNKNOWN
9300493	W 123RD ST	W 123RD ST	MANHATTAN	10027
9212593	119 ZECNILYEA AVE	119 ZECNILYEA AVE	MANHATTAN	UNKNOWN
8909472	LEXINGTON & THIRD AVS	3 AV − LEXINGTON	MANHATTAN	UNKNOWN
1503339	CON EDISON FEEDER LEAK	7 RIDGE HILL LANE	MANHATTAN	UNKNOWN

1406547	EAST 179TH ST SUBSTATION	4340 THIRD AVE	MANHATTAN	UNKNOWN
1308187	TRACKBED	EAST RIVER TUNNEL 3 MM 1.14	MANHATTAN	UNKNOWN
1304633	RAILROAD TRACKS	EAST RIVER TUNNEL MILE POST 0.89	MANHATTAN	UNKNOWN
1304033	HARLEM RIVER	LINCOLN AVE	MANHATTAN	UNKNOWN
1208489	LOWER MANHATTAN	ALL STREETS IN LOWER MANHAT	MANHATTAN	UNKNOWN
1206721	ROADWAY	PIER 33 / HELLGATE BRIDGE	MANHATTAN	UNKNOWN
1206669	ROADWAY	49 NANN ST	MANHATTAN	UNKNOWN
1010306	SOIL	4340 3RD AVE	MANHATTAN	UNKNOWN
1010077	# 7 SUBWAY LINE	STEINWAY TUBE C1 C2	MANHATTAN	UNKNOWN
1009029	220831; 1 AVE AVE	1 AVE AVE	MANHATTAN	UNKNOWN
0912184	CONSTRUCTION SITE TRENCH	FOR 2ND AVE SUBWAY PROJECT	MANHATTAN	UNKNOWN
0605256	TWO PINT RELEASE AT M18196	35-43 110 STREET	MANHATTAN	UNKNOWN
0500954	FRONT OF	25 GRANITE STREET	MANHATTAN	UNKNOWN
0401661	MANHATTAN GRID CHAMBER	MAHATTAN GRID	MANHATTAN	UNKNOWN
0401520	MANHATTAN GRID CHAMBER	MANHATTAN GRID CHAMBER	MANHATTAN	UNKNOWN
0109602	WESTSIDE PLAZA	NO ADDRESS(WESTSIDE PLAZA	MANHATTAN	UNKNOWN
0107394	SPILL NUMBER 0107394	156TH ST & 3RD AVE	MANHATTAN	UNKNOWN
0013621	PIER 45	NORTH RIVER	MANHATTAN	UNKNOWN
1307669	PRIVATE DWELLING	WEST 121ST ST	MANHATTEN	10027
0708382	AMTRACK	TUNNEL #3 BETWEEN MADISON	MANHATTEN	UNKNOWN
0801763	ROADWAY	125TH STREET	MANHATTON	UNKNOWN
9500261	HELLGATE EAST RIVER	HELLGATE EAST RIVER	NEW YORK	UNKNOWN
1507519	ALLIANCE GLOBAL SITE	51 -63 ACE AVE	NEW YORK	UNKNOWN
1101338	COMMERCIAL BLD	150 BARRACK ST	NEW YORK	UNKNOWN
1010611	PRINCESS K OVERFILL	LAT 40/37.9 LONG 74/ 3.7	NEW YORK	UNKNOWN
0906551	3150 WEST 115TH	3150 WEST 115TH	NEW YORK	UNKNOWN
0814274	212413; 167 121 ST	167 121 ST	NEW YORK	UNKNOWN
0810612	LAT 40-3942.8 SEC NORTH LONG-74.343SW	PORT JERSEY CHANNEL	NEW YORK	UNKNOWN
0808382	13 TH MANHATTEN CHAMBER	13 TH MANHATTEN CHAMBER	NEW YORK	UNKNOWN
0803459	STREET	160TH ST/ 5TH AVE	NEW YORK	UNKNOWN
0409938	NEW YORK IM TTDOCK A	NEW YORK IM TT DOCK	NEW YORK	UNKNOWN
9909841	TM 6003	EAST 111 ST & ASTORIA	NEW YORK CITY	UNKNOWN
9606764	FEEDER #71	DUNWOODIE TO RAINEY	NEW YORK CITY	UNKNOWN
8603644	LEXINGTON & 3	LEXINGTON & 3	NEW YORK CITY	UNKNOWN
0402464	IN FLIGHT	AIR	NY	UNKNOWN
8803287	6 PARK AVE SOUTH	6 PARK AV SO	NYC	UNKNOWN
0901080	ROADSIDE	30 NEWPORT WALK	NYC	UNKNOWN
9501840	UNKNOWN LOCATION	UNKNOWN LOCATION	WESTCHESTER	UNKNOWN

Petroleum Bulk Storage Facilities

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
NY07443	NYC FIRE		NEW YORK	UNKNOWN
2-157856	MOBIL S/S 1 JBWBT ARDOR GARAGE	MOBIL S/S 1 (JBWBT ARDOR GARAGE)	NY	UNKNOWN

Hazardous Waste Generation or Transport Facilities

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
NYN20002A347				UNKNOWN
NYP004019766	CONSOLIDATED EDISON CO	V462 WILLIAM ST		UNKNOWN
NYP004167821	CONSOLIDATED EDISON SB19938	SB19938 1741 E 121 STREET	MANHATTAN	10035
NYP004179198	CONSOLIDATED EDISON	104 WEST END RIVERSIDE	MANHATTAN	UNKNOWN
NYP004181152	CONED	MH SV-13	MANHATTAN	UNKNOWN
NYP004407967	CONSOLIDATED EDISON	ILLEGIBLE	MANHATTAN	UNKNOWN
NY0000010363	NYCDOT	N/S	N/S	UNKNOWN
NYP004077467	CONSOLIDATED EDISON	MH37962-SAINT JOHN	N/S	UNKNOWN
NY0005000575	JOHN DOE	DELETE	NEW YORK	UNKNOWN
NYD000100073	NYCDOT MANHATTN BRIDGE	OVER EAST RIVER	NEW YORK	10000
NYD000777805	NYCDEP	NEW ADMIN BLDG - 4TH FL	NEW YORK	10035
NYD004064622	CONSOLIDATED EDISON	N/S	NEW YORK	UNKNOWN
NYD981887194	METRO-NORTH RAILROAD	FORMER DISTRIBUTION CENTER	NEW YORK	UNKNOWN
NYD982740664	METRO NORTH COMMUTER RAILROAD	PARK AVENUE VIADUCT	NEW YORK	UNKNOWN

NYP000007732	NYCTA	N/S	NEW YORK	UNKNOWN
NYP000915488	CON EDISION − WTC AREA	VARIOUS WTC LOCATIONS VARIOUS	NEW YORK	UNKNOWN
NYP000918558	NYCTA	N/S	NEW YORK	UNKNOWN
NYP000919647	NYNEX	NORTH WEST CORNER MADISON AVE	NEW YORK	10016
NYP000928267	CONSOLIDATED EDISON CO	PARK AVENUE	NEW YORK	UNKNOWN
NYP000963462	VERIZON NEW YORK INC. MANHOLE	NW 93 RD	NEW YORK	UNKNOWN
NYP004007080	CONSOLIDATED EDISON	MH20660−PARK AVE & LEXINGTON	NEW YORK	UNKNOWN
NYP004020566	CONSOLIDATED EDISON	V5715−READERS DIGEST	NEW YORK	UNKNOWN
NYP004030086	CONSOLIDATED EDISON	7363 MADISON AVE	NEW YORK	UNKNOWN
NYP004032295	CONSOLIDATED EDISON	EXCAV BTW 116TH ST & 117TH ST	NEW YORK	UNKNOWN
NYP004033411	CONSOLIDATED EDISON	V0155	NEW YORK	UNKNOWN
NYP004034013	CONSOLIDATED EDISON	V3563−E 121ST ST	NEW YORK	10035
NYP004037867	CONSOLIDATED EDISON	V2801−W 395TH ST	NEW YORK	UNKNOWN
NYP004039633	CONSOLIDATED EDISON	VS0618−N/S	NEW YORK	UNKNOWN
NYP004048708	CONSOLIDATED EDISON	614145 M E	NEW YORK	UNKNOWN
NYP004050092	CONSOLIDATED EDISON	V5105−F/O 101 WHO ST	NEW YORK	UNKNOWN
NYP004054946	CONSOLIDATED EDISON	V5971−LEXINGTON AVE	NEW YORK	UNKNOWN
NYP004055414	CONSOLIDATED EDISON	V6835−MADISON AVE	NEW YORK	10001
NYP004056701	CONSOLIDATED EDISON	N/S	NEW YORK	UNKNOWN
NYP004063392	CONSOLIDATED EDISON	496 GLEN AVE	NEW YORK	UNKNOWN
NYP004066676	CONSOLIDATED EDISON	MH61062	NEW YORK	UNKNOWN
NYP004068078	CONSOLIDATED EDISON	TM3481	NEW YORK	UNKNOWN
NYP004072153	CONSOLIDATED EDISON	MH73305	NEW YORK	UNKNOWN
NYP004072385	CONSOLIDATED EDISON	209 FLORENCE AVE	NEW YORK	UNKNOWN
NYP004076295	CONSOLIDATED EDISON	MH27243−BROWN	NEW YORK	UNKNOWN
NYP004083804	CONSOLIDATED EDISON	BER BOX 54269	NEW YORK	UNKNOWN
NYP004086781	CONSOLIDATED EDISON	MH60639−PARK AVE & LEXINGTON	NEW YORK	UNKNOWN
NYP004100384	CONSOLIDATED EDISON	136 N MAIN ST	NEW YORK	UNKNOWN
NYP004110201	CONSOLIDATED EDISON	V3480 / 92−104 CODA ST	NEW YORK	UNKNOWN
NYP004144119	CONSOLIDATED EDISON	MH11077	NEW YORK	UNKNOWN
NYP004146122	CONSOLIDATED EDISON	MANSION & MCKINLEY DUNWOODIE	NEW YORK	UNKNOWN
NYP004167813	CONSOLIDATED EDISON SB19937	SB19937 1741 E 121ST ST	NEW YORK	10035
NYP004173522	CONSOLIDATED EDISON	1000 FAIRWAY LANE	NEW YORK	UNKNOWN
NYP004179271	CONED	75 E BLD 1	NEW YORK	UNKNOWN
NYP004179297	CONSOLIDATED EDISON	F/O 281 E DROMBE AVE	NEW YORK	UNKNOWN
NYP004189023	CONSOLIDATED EDISON	F/O 1731 EAST AVE.	NEW YORK	UNKNOWN
NYP004190997	CONSOLIDATED EDISON	FRONT OF 465 MT MORRIS PARK	NEW YORK	UNKNOWN
NYP004196879	CONSOLIDATED EDISON	NORTH SIDE OF JOHN ST 75‘ EAST	NEW YORK	UNKNOWN
NYP004217703	CONSOLIDATED EDISON	MH2721 − CEDAR & PALMER	NEW YORK	UNKNOWN
NYP004224846	CONED −	NO ADDRESS INFO ON MANIFEST	NEW YORK	UNKNOWN
NYP004226710	CONED	FLO 55	NEW YORK	UNKNOWN
NYP004226751	CONED	FLO 49	NEW YORK	UNKNOWN
NYP004226769	CONED	FLO 61	NEW YORK	UNKNOWN
NYP004240123	CONED	MANHOLE 1794	NEW YORK	UNKNOWN
NYP004241378	CONED	29 SAINT ANDREWS ST AND	NEW YORK	UNKNOWN
NYP004245866	CONED	GAS DRIP 501	NEW YORK	UNKNOWN
NYP004246619	CONSOLIDATED EDISON	55‘ N/O NORTH TRESTLE #42	NEW YORK	10035
NYP004252003	CONED	35 W 1231ST STREET	NEW YORK	UNKNOWN
NYP004262077	CON EDISON	F/O PARK AVE SOUTH−SERV BOX 35085	NEW YORK	UNKNOWN
NYP004297990	CON EDISON	3034 LEXINGTON AVE	NEW YORK	10029
NYP004298808	CON EDISON	F/O EAST 117TH ST	NEW YORK	10035
NYP004594529	CON EDISON	FOT	NEW YORK	10035
NYP004703834	CONSOLIDATED EDISON	MH26764	NEW YORK	UNKNOWN
NYP004812018	CON EDISON	5299 DIAGAONAL ST & E 9TH AVE	NEW YORK	UNKNOWN
NYR000034058	NYCTA	CONTRACT #S−34505 − RM 819	NEW YORK	UNKNOWN
NYR000051904	MTA NYCT − LEXINGTON AVE 4 5 6 LINE	LEXINGTON AVE & HARLEM RIVER &	NEW YORK	10016
NYR000050625	NYCTA	606W FROST	NYC	UNKNOWN
NYP004007159	CONSOLIDATED EDISON	MH 8979 − MADISON AVE	QUEENS	UNKNOWN
NYP004009205	CONSOLIDATED EDISON	MH 9 − E 118 ST	QUEENS	10035

Wastewater Discharges

FACILITY ID	FACILITY NAME	STREET	CITY	ZIP
NY0200794				UNKNOWN
NYU200032	CONSOLIDATED EDISON COMPANY			UNKNOWN

Air Releases

FACILITY ID	FACILITY NAME		STREET	CITY	ZIP
3606100080	NYCHA–FOSTER HOUSING		NO STREET ADDRESS	NEW YORK	UNKNOWN
3606100129	NAVY DIST COMMANDER		NO STREET ADDRESS	NEW YORK	UNKNOWN
3606100132	NAVAL RECRUIT STA		NO STREET ADDRESS	NEW YORK	UNKNOWN
3606100431	CUMBERLAND FARMS INC.		777 DEDHAM STREET	NEW YORK	UNKNOWN
3606100495	FEILER BROS CORP		ROOM 1700	NEW YORK	UNKNOWN
3606100552	ACADEMY CONSTRUCTION		NO STREET ADDRESS	NEW YORK	UNKNOWN
3606180051	FEILER BROS CORP		ROOM 1700	NEW YORK	UNKNOWN
3606100558	SOS INTERNATIONAL		BOX 2976 CHURCH STAT	NEW YORK CITY	UNKNOWN
NY061X0NP	MIDTOWN HOLDING CO	NEW YORK	NO STREET ADDRESS	NO CITY NAME	UNKNOWN
NY061X2DR	UNIHAB CO	NEW YORK	NO STREET ADDRESS	NO CITY NAME	UNKNOWN

BBL #	E No.	Block & Lot			
FACILITY ID		FACILITY NAME		STREET	CITY	ZIP
1–01767–0045	E–114	BLOCK: 1767	LOT: 45			
1–01767–0046	E–114	BLOCK: 1767	LOT: 46			

Hazardous waste codes presented in individual Toxic Information Profiles are defined below.

B002 Petroleum oil or other liquid containing 50 ppm or greater of PCBs but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

B004 PCB Articles containing 50 ppm or greater of PCBs but less than 500 ppm PCBs excluding, small capacitors. This includes oil filled electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable

B007 Other PCB Wastes including contaminated soil, solids, sludges, clothing, rags, and dredge material.

D001 Solid waste that exhibits the characteristic of ignitability, but is not listed under any other hazardous waste code.

D002 Solid waste that exhibits the characteristic of corrosivity, but is not listed under any other hazardous waste code.

D003 Solid waste that exhibits the characteristic of reactivity, but is not listed under any other hazardous waste code.

D005 Barium

D007 Chromium

D008 Lead

D009 Mercury

D011 Silver

D016 2,4−D, (2,4−Dichlorophenoxyacetic acid).

F003 The following spent non−halogenated solvents: Xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n−butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent non−halogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above non−halogenated solvents, and, a total of ten percent or more (by volume) of one or more of those solvents listed in F001, F002, F004, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

U010 Mitomycin C

U035 Benzenebutanoic acid, 4−[bis(2−chloroethyl)amino]−

U058 2H−1,3,2−Oxazaphosphorin−2−amine, N,N−bis(2−chloroethyl)tetrahydro−, 2−oxide

U122 Formaldehyde

U188 Phenol

Source: U. S. Environmental Protection Agency

How Toxic Site Locations Are Mapped

Toxics Targeting maps toxic site locations on a digital version of the U. S. Census map or those used by local authorities using addresses and map coordinates provided by site owners/operators or government agencies. In order to allow site locations to be verified independently, the information used to map each site is presented in the first section of each Toxic Site Profile, along with a description of the mapping technique used and any address corrections that were made in order to locate toxic sites with incomplete or inadequate site location information. The mapping process is explained below.

Map Identification Number: 12 Site Name: Acme World Manufacturing, Inc.

Site Address: 55 Main Street Anytown, NY 11797

MAP LOCATION INFORMATION

Site location mapped by:

Address Matching

1) Most toxic sites are mapped by matching addresses provided by site owners/operators or government agencies with locations on a digital version of the street or parcel map. These site locations are identified with the method used to map them.

Note: Some sites have an address match location and a map coordinate location. Both locations are mapped because they can be equally correct.

or Map Coordinate

2) Some toxic sites are located using map coordinates provided by site owners/ operators or government agencies. These site locations are identified "map coordinate." Map coordinates for Toxic Wastewater Discharges, Toxic Release Inventory sites and Major Oil Storage Facilities should be considered suspect.

or Manual Mapping

or Site Visit

3) Incomplete addresses or map coordinates require some site locations to be determined by commercial street maps (manual mapping), site visits, map coordinates from other databases and address location services. Application of any of these methods is identified accordingly.

ADDRESS CHANGE INFORMATION

Revised Street: NO CHANGE

Revised zip code: NO CHANGE

4) Site addresses are sometimes corrected to eliminate obvious errors that prevent sites from being mapped. All address corrections are noted here.

Information Source Guide

Toxics Targeting's Environmental Reports contain government and other information compiled on 21 categories of reported known or potential toxic sites. Each toxic site database is described below with information detailing a) the source of the information, b) the date when each database is covered to and c) when *Toxics Targeting* obtained the information..

1) **National Priority List for Federal Superfund Cleanup:** Toxic sites nominated for cleanup under the Federal Superfund program. Annual compilation of special two-page detailed profiles of NPL sites. Also includes delisted NPL sites.
ASTM required.* Fannie Mae required.** Source: U. S. Environmental Protection Agency.[1]
Data attributes updated from: 9/9/2015. Data obtained by Toxics Targeting: 9/9/2015.
New Facilities updated through: 9/9/2015. Data obtained by Toxics Targeting: 9/9/2015.

2) **Inactive Hazardous Waste Disposal Site Registry:** New York State database that maintains information and aids decision making regarding the investigation and cleanup of toxic sites. The Registry's data includes two-page profiles noting site name, ID number, description, classification, cleanup status, types of cleanup, owner information, types and quantities of contaminants, and assessment of health and environmental problems. Also included are sites that qualify for possible inclusion on the Registry. These Registry Qualifying sites may or may not be on the Site Registry.
ASTM required.* Fannie Mae required.** Source: New York State Department of Environmental Conservation.[2]
Data attributes updated through: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.
New Facilities updated to: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.

3) **Federal & State Corrective Action Activity (CORRACTS):** New York State and Federal databases of hazardous facilities regulated pursuant to the Resource Conservation and Recovery Act (RCRA).
ASTM required.* Fannie Mae required.**

Federal Data Source: U. S. Environmental Protection Agency[1]
Data attributes updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.
New facilities updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.

State Data Source: New York State Department of Environmental Conservation.[2]
Data attributes updated through: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.
New facilities updated through: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.

4) **CERCLIS:** Toxic sites listed in the Federal Comprehensive Environmental Response, Compensation and Liability Information System. Includes Active and No Further Remedial Action Planned (NFRAP) sites.
ASTM required.* Fannie Mae required.** Source: U. S. Environmental Protection Agency.[1]
Data attributes updated through: 10/25/2013. Data obtained by Toxics Targeting: 1/07/2014.
New Facilities updated through: 1/11/2016. Data obtained by Toxics Targeting: 1/23/2016.

5) **Brownfield Programs:** NYS & NYC programs for sites that are abandoned, idled or under-used industrial and/or commercial sites where expansion or redevelopment is complicated by real or perceived environmental contamination.
ASTM required.*

(a) **NYS DEC Brownfield Programs**: Source: New York State Department of Environmental Conservation.[2]
includes: **Brownfield Cleanup Program (BCP), Voluntary Cleanup Program (VCP), and Environmental Restoration Program (ERP)**
Data attributes updated through: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.
New Facilities updated to: 3/09/2016. Data obtained by Toxics Targeting: 3/09/2016.

(b) **NYC Voluntary Cleanup Program:** Source: NYC Office of Environmental Remediation
Data attributes updated through: 11/30/15. Data obtained by Toxics Targeting: 12/10/2015.
New Facilities updated to: 11/30/15. Data obtained by Toxics Targeting: 12/10/2015.

6) **Solid Waste Facilities:** a compilation of the following 2 databases:

(a) **NYS Solid Waste Registry:** which includes, but is not limited to, landfills, incinerators, transfer stations, recycling centers.
ASTM required.* Fannie Mae required.** Source: New York State Dept. of Environmental Conservation.[2]
Data updated to: 4/1/2013. Data obtained by Toxics Targeting: 4/1/2013.

(b) **1934 Solid Waste Disposal Site in New York City:** which includes sites operated by municipal authorities circa 1934. Source: City of New York Department of Sanitation (1984). The Waste Disposal Problem in New York City: A Proposal For Action.

7) **RCRA Hazardous Waste Treatment, Storage or Disposal Facility Databases:**

(a) **Manifest Information:** New York State database of hazardous waste facilities and shipments regulated by the DEC's Division of Environmental Remediation pursuant to NYS Law and the Resource Conservation and Recovery Act (RCRA).
ASTM required.* Fannie Mae required.** Source: New York State Department of Environmental Conservation.[2]

New facilities updated through: 4/22/2016. New facilities obtained by Toxics Targeting: 4/22/2016.
Manifest transactions data updated to: 4/22/2016. Manifest transactions data obtained by Toxics Targeting: 4/22/2016.

(b) **RCRA Notifier & Violations Information:** U. S. Environmental Protection Agency database of hazardous facilities regulated pursuant to the Resource Conservation and Recovery Act (RCRA).
ASTM required.* Fannie Mae required.** Source: U. S. Environmental Protection Agency[1]
New facilities updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.
Data attributes updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.

8) **Spills Information Database:** Spills reported to the DEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from Petroleum Bulk Storage Regulations) or 6 NYCRR Section 595.2 (from Chemical Bulk Storage Regulations). This database includes both *active* and *closed* spills.
ASTM required.* Fannie Mae.** Source: NYS Department of Environmental Conservation.[2]

New spills through: 2/13/2016 New spills data obtained by Toxics Targeting: 2/13/2016
Spill attribute data through: 2/13/2016 Spill attribute data obtained by Toxics Targeting: 2/13/2016

Active spills: paperwork not completed. Closed spills: paperwork completed.
Both active and closed spills may or may not have been cleaned up (see Date Cleanup Ceased in spill profiles).

9) **Major Oil Storage Facilities:** NYS database of facilities licensed pursuant to Article 12 of the Navigation Law, 6NYCRR Parts 610 and 17NYCRR Part 30, such as onshore facilities or vessels, with petroleum storage capacities equal to or greater than four hundred thousand gallons. **Tank & other data withheld by NYSDEC as of 4/1/2002**.
ASTM required.* Fannie Mae required.** Source: New York State Department of Environmental Conservation.[2]

Data updated through: 3/5/2016. Data obtained by Toxics Targeting: 3/5/2016.

10) **Petroleum Bulk Storage Facilities:** a compilation of local and state databases of aboveground and underground petroleum storage tank facilities.

(a) **NYS Petroleum Bulk Storage Database:** This includes all New York State counties except Cortland, Nassau, Rockland, Suffolk, and Westchester. ASTM required.* Fannie Mae required.**
Source: NYS Department of Environmental Conservation.[2]
New facilities updated through: 3/5/2016. Data obtained by Toxics Targeting: 3/5/2016.
Tank data updated through: 3/5/2016. Data obtained by Toxics Targeting: 3/5/2016.

(b) **New York City Fire Department Tank Data:** **Data has been withheld by the NYC Fire Dept.**
Source: New York City Fire Department. Data obtained by Toxics Targeting: 2/18/1997

11) **RCRA Hazardous Waste Generators and/or Transporters Databases:**

(a) **Manifest Information:** New York State database of hazardous waste facilities and shipments regulated by the NYS Department of Environmental Conservation's Division of Environmental Remediation pursuant to New York State Law. ASTM required.* Fannie Mae required.** Source: New York State Department of Environmental Conservation.[2]

New facilities updated through: 4/22/2016. New facilities obtained by Toxics Targeting: 4/22/2016.
Manifest transactions data updated to: 4/22/2016. Manifest transactions data obtained by Toxics Targeting: 4/22/2016.

(b) **RCRA Notifier & Violations Information:** U. S. Environmental Protection Agency database of hazardous facilities regulated pursuant to the Resource Conservation and Recovery Act (RCRA).
ASTM required.* Fannie Mae required.** Source: U. S. Environmental Protection Agency[1]

New facilities updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.
Data attributes updated through: 4/11/2016. Data obtained by Toxics Targeting: 4/19/2016.

12) **Chemical Bulk Storage Facilities:** New York State database of facilities compiled pursuant to 6NYCRR Part 596 that store regulated substances listed in 6NYCRR Part 597 in aboveground tanks with capacities greater than 185 gallons and /or in underground tanks of any size. **Tank & other data withheld by NYSDEC as of 4/1/2002**.
ASTM required.* Fannie Mae required.** Source: New York State Department of Environmental Conservation.[2]
Data updated through: 3/5/2016. Data obtained by Toxics Targeting: 3/5/2016.

13) **Historic New York City Utility Facilities (1898 to 1950):** An inventory of selected power generating stations, manufactured gas plants, gas storage facilities, maintenance yards and other gas and electric utility sites identified in various historic documents, maps and annual reports of New York utility companies, including: Sanborn Fire Insurance Maps of NYC (1898-1950); Consolidated Edison Co. Annual Reports (1922-1939); Consolidated Edison Co. Map: "Boroughs of Manhattan and the Bronx Showing Distribution Mains of the New York Edison Co.," (1922); and Consolidated Edison document: "Generating and Annex Stations," (1911).

14) **Hazardous Substance Waste Disposal Site Study:** NYS database of waste disposal sites that may pose threats to public health or the environment, but could not be remediated using monies from the Hazardous Waste Remedial Fund.
Source: New York State Department of Environmental Conservation.[2]
Data updated to: 5/16/2000. Data obtained by Toxics Targeting: 5/16/2000.

15) **Toxic Release Inventory (TRI):** Federal database of manufacturing facilities required under Section 313 of the Federal Emergency Planning and Community Right-to-Know Act to report releases to the air, water and land of any specifically listed toxic chemical. See Fannie Mae requirement** below.
Source: U. S. Environmental Protection Agency.[1] / NYS Department of Environmental Conservation[2]
Data updated through: 3/8/2004. Data obtained by Toxics Targeting: 3/25/2004

16) **Toxic Wastewater Discharges (Permit Compliance System):** Federal database of discharges of wastewater to surface waters and groundwaters. See Fannie Mae requirement** below. Source: U. S. Environmental Protection Agency.[1]
Data updated through: 6/17/2004. Data obtained by Toxics Targeting: 7/19/2004.

17) **Air Discharge Facilities:** EPA AIRS database containing address information on each air emission facility and the type of air pollutant emission it is. Compliance information is also provided on each pollutant as well as the facility itself.
See Fannie Mae requirement** below. Source: U. S. Environmental Protection Agency[1]
Data updated through: 11/24/1999. Data obtained by Toxics Targeting: 1/6/2000

18) **Civil Enforcement & Administrative Docket:** This database is the U. S. EPA's system for tracking administrative and civil judiciary cases filed on behalf of the agency by the Department of Justice. Fannie Mae required.**
Source: U. S. Environmental Protection Agency.[1]
New Sites through: 10/14/1999.
Data updated through: 10/14/1999. Data obtained by Toxics Targeting: 11/18/1999.

19) **New York City Environmental Quality Review (CEQR) – E Designation Sites:** These sites are parcels assigned a special environmental ("E") designation under the CEQR process. E designation requires specific protocols that must be followed. Source: New York City Department of Planning[3]
Data updated through: 4/28/2015. Data obtained by Toxics Targeting: 5/24/2015.

20) **Emergency Response Notification System (ERNS):** Federal database of spills compiled by the Emergency Response Notification System. On-site searches only.
ASTM required.* See Fannie Mae requirement** below. Source: U. S. Environmental Protection Agency.[1]
Data updated through: 1/31/2000. Data obtained by Toxics Targeting: 2/15/2000

21) **Remediation Site Borders:** Remediation site borders reported by NYSDEC.
Source: New York State Department of Environmental Conservation.[2]
Updated through: 4/8/2009. Data obtained by Toxics Targeting: 7/21/2009.

* American Society of Testing Materials: Standard Practice on Environmental Site Assessments: Phase I Environmental Site Assessment Process (E1527-05).

** Fannie Mae's Part X Environmental Hazards Management Procedures specify 1.0 mile searches for "any state or Federal list of hazardous waste sites (e.g. CERCLIS, HWDMS etc.)." Searches for the property and adjacent properties are specified for "chemical manufacturing plants," "obvious high risk neighbors engaging in storing or transporting hazardous waste, chemicals or substances" and "...any documented or visible evidence of dangerous waste handling... (e.g. stressed vegetation, stained soil, open or leaking containers, foul fumes or smells, oily ponds, etc." Searches for property and adjacent properties can include sites up to a quarter mile away (W. Hayward, Director, Multi-Family Business Planning and Control, Fannie Mae, personal communication, 5/94).

[1]U. S. Environmental Protection Agency, 290 Broadway, NY, NY 10007-1866.

[2]NYS Department of Environmental Conservation, 625 Broadway, Albany, NY 12233.

[3]New York City Department of City Planning, 22 Reade St, New York, NY 10007-1216