PBS Number
2-452335

New York State Department of Environmental Conservation
PETROLEUM BULK STORAGE CERTIFICATE

625 Broadway, 11th Floor, Albany, NY 12233-7020 Phone: 518-402-9553

Region 2 NYSDEC - PBS Unit
One Hunters Point Plaza, 1st Floor
47-40 21st Street, L.I. City, NY 11101-6454
(718) 482-6454

TANK NUMBER	TANK LOCATION	DATE INSTALLED	TANK TYPE	CAPACITY (GALLONS)	DATE LAST TESTED	TESTING DUE DATE
101	Underground	12/01/1976	Steel/Carbon Steel/Iron	550		

*** Aboveground tanks require monthly visual inspections and may need documented internal inspections as described in 6 NYCRR Part 613**

OWNER:
KINLOCH COMPANY, INC.
27-10 HUNTERS POINT BOULEVARD
LONG ISLAND CITY, NY 11101

SITE:
BLACK BEAR COMPANY
27-10 HUNTERS POINT BOULEVARD
LONG ISLAND CITY, NY 11101

OPERATOR: BLACK BEAR
(718) 326-2465

EMERGENCY CONTACT: MR. LENNY TRUBIA
(718) 326-2465

ISSUED BY: Acting Commissioner
Denise M. Sheehan

PBS NUMBER: 2-452335

DATE ISSUED: 06/30/2003

EXPIRATION DATE: 08/23/2008

FEE PAID: $250.00

MAILING CORRESPONDENCE:

MR. DEREK CHOU
BLACK BEAR COMPANY, INC.
27-10 HUNTERS POINT BOULEVARD
LONG ISLAND CITY, NY 11101

As an authorized representative of the above named facility, I affirm under penalty of perjury that the information displayed on this form is correct to the best of my knowledge. Additionally, I recognize that I am responsible for assuring that this facility is in compliance with all sections of 6 NYCRR Parts 612, 613 and 614, and applicable sections of 6 NYCRR Subpart 360-14 (used oil tanks only), not just those cited below:

-- The facility must be re-registered if there is a transfer of ownership.
-- The Department must be notified within 30 days prior to adding, replacing, reconditioning, or permanently closing a stationary tank.
-- The facility must be operated in accordance with the code for storing petroleum, 6NYCRR Part 613.
-- Any new facility or substantially modified facility must comply with 6NYCRR Part 614.
-- **This certificate must be signed and posted on the premises at all times.** Posting must be at the tank, at the entrance of the facility, or the main office where the storage tanks are located.
-- Any person with knowledge of a spill, leak or discharge must report the incident to DEC within two hours **(1-800-457-7362)**.

Derek Chou 10/24/05
Signature of Representative/ Owner Date

Treasurer Derek Chou
Name and Title of Authorized Representative/Owner (Please Print)

Print Date: 10/21/2005

THIS REGISTRATION CERTIFICATE IS NON-TRANSFERABLE

ABC TANK REPAIR & LINING, INC.
280 EAST 88 STREET
BROOKLYN, NY 11236
(718) 272-2800
FAX# (718) 272-3147

DATE: 5-29-09

COMPANY: Black Bear Co.

NAME: Jennifer

FAX #: 718-392-8283

PAGES INC. COVER: (15)

FROM: Donna

SUBJECT: soil sample results

MESSAGE: Please keep on files with your records.

IF YOU DO NOT RECEIVE ALL PAGES TRANSMITTED, PLEASE CONTACT ME. IF YOU HAVE RECEIVED THIS FACSIMILE IN ERROR, PLEASE NOTIFY US BY TELEPHONE IMMEDIATELY.

AMERICAN ANALYTICAL LABORATORIES

NYSDOH 11418
NJDEP NY050
CTDOH PH-0205
PADEP 68-00573

Wednesday, May 20, 2009

Bob Iengo
ABC Tank Cleaning & Repairing, Inc.
280 East 88th Street
Brooklyn, New York 11236

TEL: (718) 272-2800
FAX (718) 272-3147

RE: 27-10 Hunter's Point

Order No.: 0905062

Dear Bob Iengo:

American Analytical Laboratories, LLC. received 2 sample(s) on 5/6/2009 for the analyses presented in the following report.

Samples were analyzed in accordance with the test procedures documented on the chain of custody and detailed throughout the text of this report.

The results reported herein relate only to the items tested or to the samples as received by the laboratory. This report may not be reproduced, except in full, without the approval of American Analytical Laboratories, LLC and is not considered complete without a cover page and chain of custody documentation. The limits (LOQ) provided in the data package are analytical reporting limits and not Federal or Local mandated values to which the sample results should be compared.

There were no problems with the analyses and all data for associated QC met laboratory specifications. If there are any exceptions a Case Narrative is provided in the report or the data is qualified. This package has been reviewed by American Analytical Laboratories' QA Department/Laboratory Director to comply with NELAC standards prior to report submittal. This report consists of 14 pages.

If you have any questions regarding these tests results, please do not hesitate to call (631) 454-6100 or email me directly at lbeyer@american-analytical.com.

Sincerely,

Karen Kelly for

Lori Beyer
Lab Director

American Analytical Laboratories, LLC.

Date: *20-May-09*

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Project: 27-10 Hunter's Point
Lab Order: 0905062

Work Order Sample Summary

Lab Sample ID	Client Sample ID	Date Collected	Date Received
0905062-01A	East	5/6/2009	5/6/2009
0905062-01B	East	5/6/2009	5/6/2009
0905062-02A	West	5/6/2009	5/6/2009
0905062-02B	West	5/6/2009	5/6/2009

ANALYTICAL LABORATORIES
TOLEDO STREET • FARMINGDALE, NEW YORK 11735
(631) 454-6100 • FAX (631) 454-8027
www.american-analytical.com

NYSDOH 11418
CTDOH PH-0205
NJDEP NY050
PADEP 68-573

CHAIN OF CUSTODY / REQUEST FOR ANALYSIS DOCUMENT

CLIENT NAME/ADDRESS: ABC Tank

CONTACT:

PROJECT LOCATION: 27-10 Hunter's Point

SAMPLER (SIGNATURE)

SAMPLER NAME (PRINT)

SAMPLE(S) SEALED YES / NO

CORRECT CONTAINER(S) YES / NO

LABORATORY ID# LAB USE ONLY	MATRIX/ TYPE	NO. OF CONTAINERS	SAMPLING DATE	SAMPLING TIME	SAMPLE # - LOCATION	ANALYSIS REQUIRED: STARS
0905062-01A	S	2	5/6/09		East	X
02A	S	2	11		West	X

COMMENTS / INSTRUCTIONS

Samples must be on ICE (<6° C)

MATRIX S=SOIL; W=WATER; SL=SLUDGE; A=AIR; M=MISCELLANEOUS
TYPE G=GRAB; C=COMPOSITE

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

E-MAIL ADDRESS FOR RESULTS:

RELINQUISHED BY (SIGNATURE)	DATE 5/6/09 TIME 3:45	PRINTED NAME C. Ruiz	RECEIVED BY LAB (SIGNATURE)	DATE 5/6/09 TIME 16:49	PRINTED NAME Nick Muth
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE-OFFICE / CANARY-LAB / PINK-SAMPLE CUSTODIAN / GOLDENROD-CLIENT

05/29/2009 01:57 FAX 7182723181 ABC TANK 001004

American Analytical Laboratories, LLC.

Sample Receipt Checklist

Client Name ABC TANK & REPAIR

Date and Time Receive 5/6/2009 4:04:52 PM

Work Order Numbe 0905062 RcptNo: 1

Received by NM

COC_ID: CoolerID:

Checklist completed by Signature 5/6/09 Date

Reviewed by Initials 5/6/09 Date

Matrix: Carrier name Courier

Shipping container/cooler in good condition?	Yes ☑	No ☐	Not Presen ☐
Custody seals intact on shippping container/cooler?	Yes ☐	No ☐	Not Presen ☑
Custody seals intact on sample bottles?	Yes ☐	No ☐	Not Presen ☑
Chain of custody present?	Yes ☑	No ☐	
Chain of custody signed when relinquished and received?	Yes ☑	No ☐	
Chain of custody agrees with sample labels?	Yes ☑	No ☐	
Samples in proper container/bottle?	Yes ☑	No ☐	
Sample containers intact?	Yes ☑	No ☐	
Sufficient sample volume for indicated test?	Yes ☑	No ☐	
All samples received within holding time?	Yes ☑	No ☐	
Container/Temp Blank temperature in compliance?	Yes ☑	No ☐	
Water - VOA vials have zero headspace?	No VOA vials submitted ☑	Yes ☐	No ☐
Water - pH acceptable upon receipt?	Yes ☐	No ☐	N/A ☐

Adjusted? _____ Checked b _____

Any No and/or NA (not applicable) response must be detailed in the comments section be

Client contacted _____ Date contacted: _____ Person contacted _____

Contacted by: _____ Regarding: _____

Comments: Cooler: Yes; Ice: Yes; T = 4.7 C.

Corrective Action _____

American Analytical Laboratories, LLC.

Date: *20-May-09*

ELAP ID : 11418

CLIENT:	ABC Tank Cleaning & Repairing, Inc.	**Client Sample ID:**	East
Lab Order:	0905062	**Collection Date:**	5/6/2009
Project:	27-10 Hunter's Point	**Matrix:**	SOIL
Lab ID:	0905062-01A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 8260 (STARS)			**SW8021B**				Analyst: **LA**
1,2,4-Trimethylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
1,3,5-Trimethylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
4-Isopropyltoluene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Benzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Ethylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Isopropylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
m,p-Xylene	U	0.32	11		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Methyl tert-butyl ether	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Naphthalene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
n-Butylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
n-Propylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
o-Xylene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
sec-Butylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
tert-Butylbenzene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Toluene	U	0.32	5.4		µg/Kg-dry	1	5/7/2009 7:17:00 PM
Surr: 4-Bromofluorobenzene	82.9	0	61-133		%REC	1	5/7/2009 7:17:00 PM
Surr: Toluene-d8	110	0	57-131		%REC	1	5/7/2009 7:17:00 PM

Qualifiers:

*	Value exceeds Maximum Contaminant Level
E	Value above quantitation range
J	Analyte detected below quantitation limits
LOQ	Limit of Quantitation
S	Spike Recovery outside accepted recovery limits
C	Calibration %RSD/%D exceeded for non-CCC analytes
B	Analyte detected in the associated Method Blank
H	Holding times for preparation or analysis exceeded
LOD	Limit of Detection
ND	Not Detected at the Reporting Limit
U	Indicates the compound was analyzed but not detected.

American Analytical Laboratories, LLC.

Date: *20-May-09*

ELAP ID : 11418

CLIENT:	ABC Tank Cleaning & Repairing, Inc.	**Client Sample ID:**	East
Lab Order:	0905062	**Collection Date:**	5/6/2009
Project:	27-10 Hunter's Point	**Matrix:**	SOIL
Lab ID:	0905062-01B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			DZ216				Analyst: NM
Percent Moisture	6.95	0	0		wt%	1	5/8/2009
SEMIVOLATILE SW-846 METHOD 8270 (STARS)			SW8270D		SW3550A		Analyst: PT
Acenaphthene	U	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Acenaphthylene	U	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Anthracene	48	16.0	130	J	µg/Kg-dry	1	5/11/2009 6:49:00 PM
Benzo(a)anthracene	170	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Benzo(a)pyrene	150	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Benzo(b)fluoranthene	260	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Benzo(g,h,i)perylene	100	16.0	130	J	µg/Kg-dry	1	5/11/2009 6:49:00 PM
Benzo(k)fluoranthene	90	16.0	130	J	µg/Kg-dry	1	5/11/2009 6:49:00 PM
Chrysene	200	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Dibenzo(a,h)anthracene	U	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Fluoranthene	280	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Fluorene	U	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Indeno(1,2,3-c,d)pyrene	120	16.0	130	J	µg/Kg-dry	1	5/11/2009 6:49:00 PM
Phenanthrene	120	16.0	130	J	µg/Kg-dry	1	5/11/2009 6:49:00 PM
Pyrene	260	16.0	130		µg/Kg-dry	1	5/11/2009 6:49:00 PM
Surr: 2-Fluorobiphenyl	60.3	0	22-112		%REC	1	5/11/2009 6:49:00 PM
Surr: 4-Terphenyl-d14	69.0	0	24-124		%REC	1	5/11/2009 6:49:00 PM
Surr: Nitrobenzene-d5	54.8	0	20-115		%REC	1	5/11/2009 6:49:00 PM

American Analytical Laboratories, LLC., 56 Toledo Street, Farmingdale, NY, Zip - 11735
Tel - 6314546100 Fax - 6314548027 www.American-Analytical.com

Qualifiers:

*	Value exceeds Maximum Contaminant Level	B	Analyte detected in the associated Method Blank
E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
J	Analyte detected below quantitation limits	LOD	Limit of Detection
LOQ	Limit of Quantitation	ND	Not Detected at the Reporting Limit
S	Spike Recovery outside accepted recovery limits	U	Indicates the compound was analyzed but not detected.
C	Calibration %RSD/%D exceeded for non-CCC analytes		

American Analytical Laboratories, LLC.

Date: *20-May-09*

ELAP ID : 11418

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Lab Order: 0905062
Project: 27-10 Hunter's Point
Lab ID: 0905062-02A

Client Sample ID: West
Collection Date: 5/6/2009
Matrix: SOIL

Certificate of Results

Analyses	Sample Result		LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 8260 (STARS)				**SW8021B**				Analyst: LA
1,2,4-Trimethylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
1,3,5-Trimethylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
4-Isopropyltoluene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Benzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Ethylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Isopropylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
m,p-Xylene	U		0.32	11		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Methyl tert-butyl ether	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Naphthalene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
n-Butylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
n-Propylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
o-Xylene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
sec-Butylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
tert-Butylbenzene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Toluene	U		0.32	5.4		µg/Kg-dry	1	5/7/2009 7:45:00 PM
Surr: 4-Bromofluorobenzene	83.1		0	61-133		%REC	1	5/7/2009 7:45:00 PM
Surr: Toluene-d8	101		0	57-131		%REC	1	5/7/2009 7:45:00 PM

American Analytical Laboratories, LLC., 56 Toledo Street, Farmingdale, NY, Zip - 11735
Tel - 6314546100 Fax - 6314548027 www.American-Analytical.com

Qualifiers:

- * Value exceeds Maximum Contaminant Level
- E Value above quantitation range
- J Analyte detected below quantitation limits
- LOQ Limit of Quantitation
- S Spike Recovery outside accepted recovery limits
- C Calibration %RSD/%D exceeded for non-CCC analytes
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- LOD Limit of Detection
- ND Not Detected at the Reporting Limit
- U Indicates the compound was analyzed but not detected.

American Analytical Laboratories, LLC.

Date: *20-May-09*

ELAP ID : 11418

CLIENT:	ABC Tank Cleaning & Repairing, Inc.	**Client Sample ID:**	West
Lab Order:	0905062	**Collection Date:**	5/6/2009
Project:	27-10 Hunter's Point	**Matrix:**	SOIL
Lab ID:	0905062-02B		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			D2216				Analyst: NM
Percent Moisture	7.30	0	0		wt%	1	5/8/2009
SEMIVOLATILE SW-846 METHOD 8270 (STARS)			SW8270D		SW3550A		Analyst: PT
Acenaphthene	U	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Acenaphthylene	U	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Anthracene	25	16.1	130	J	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Benzo(a)anthracene	130	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Benzo(a)pyrene	120	16.1	130	J	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Benzo(b)fluoranthene	200	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Benzo(g,h,i)perylene	75	16.1	130	JC	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Benzo(k)fluoranthene	69	16.1	130	J	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Chrysene	140	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Dibenzo(a,h)anthracene	U	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Fluoranthene	200	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Fluorene	U	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Indeno(1,2,3-c,d)pyrene	89	16.1	130	JC	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Phenanthrene	70	16.1	130	J	µg/Kg-dry	1	5/12/2009 3:03:00 PM
Pyrene	200	16.1	130		µg/Kg-dry	1	5/12/2009 3:03:00 PM
Surr: 2-Fluorobiphenyl	65.7	0	22-112		%REC	1	5/12/2009 3:03:00 PM
Surr: 4-Terphenyl-d14	67.8	0	24-124		%REC	1	5/12/2009 3:03:00 PM
Surr: Nitrobenzene-d5	50.5	0	20-115		%REC	1	5/12/2009 3:03:00 PM

American Analytical Laboratories, LLC., 56 Toledo Street, Farmingdale, NY, Zip - 11735
Tel - 6314546100 Fax - 6314548027 www.American-Analytical.com

Qualifiers:

*	Value exceeds Maximum Contaminant Level	B	Analyte detected in the associated Method Blank
E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
J	Analyte detected below quantitation limits	LOD	Limit of Detection
LOQ	Limit of Quantitation	ND	Not Detected at the Reporting Limit
S	Spike Recovery outside accepted recovery limits	U	Indicates the compound was analyzed but not detected.
C	Calibration %RSD/%D exceeded for non-CCC analytes		

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8260STARS_Soil

Sample ID: V624LCS-060709Y	SampType: LCS	TestCode: Dry8260STAR	Units: pg/Kg	Prep Date:		RunNo: 43715
Client ID: LCSS	Batch ID: R43715	TestNo: SW8021B		Analysis Date: 5/7/2009		SeqNo: 595807

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
1,2,4-Trimethylbenzene	48	5.0	50.00	0	96.4	30	130				
1,3,5-Trimethylbenzene	50	5.0	50.00	0	100	30	130				
4-Isopropyltoluene	47	5.0	50.00	0	94.1	30	130				
Benzene	42	5.0	50.00	0	83.4	30	130				
Ethylbenzene	47	5.0	50.00	0	94.0	15	130				
Isopropylbenzene	48	5.0	50.00	0	96.5	30	130				
m,p-Xylene	99	10	100.0	0	98.6	30	130				
Naphthalene	42	5.0	50.00	0	84.5	30	130				
n-Butylbenzene	38	5.0	50.00	0	75.4	30	130				
n-Propylbenzene	46	5.0	50.00	0	91.2	30	130				
o-Xylene	47	5.0	50.00	0	94.3	30	130				
sec-Butylbenzene	47	5.0	50.00	0	93.5	30	140				
tert-Butylbenzene	48	5.0	50.00	0	95.9	30	130				
Toluene	42	5.0	50.00	0	84.2	20	119				
Surr: 4-Bromofluorobenzene	49		50.00		98.1	81	133				
Surr: Toluene-d8	51		50.00		101	57	131				

Sample ID: VBLK-060709Y	SampType: MBLK	TestCode: Dry8260STAR	Units: pg/Kg	Prep Date:		RunNo: 43715
Client ID: PBS	Batch ID: R43715	TestNo: SW8021B		Analysis Date: 5/7/2009		SeqNo: 595808

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
1,2,4-Trimethylbenzene	U	5.0									
1,3,5-Trimethylbenzene	U	5.0									
4-Isopropyltoluene	U	5.0									
Benzene	U	5.0									
Ethylbenzene	U	5.0									
Isopropylbenzene	U	5.0									
m,p-Xylene	U	10									
Methyl tert-butyl ether	U	5.0									

Qualifiers:

- E Value above quantitation range
- H Holding times for preparation or analysis exceeded
- J Analyte detected below quantitation li
- LOD Limit of Detection
- LOQ Limit of Quantitation
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S Spike Recovery outside accepted recovery limits
- U Indicates the compound was analyzed

05/29/2009 01:58 FAX 7182723147 ABC LAB 010

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8260STARS_Soil

Sample ID: VBLK-050709Y	SampType: MBLK	TestCode: Dry8260STAR	Units: µg/Kg	Prep Date:		RunNo: 43715					
Client ID: PBS	Batch ID: R43715	TestNo: SW8021B		Analysis Date: 5/7/2009		SeqNo: 595808					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Naphthalene	U	5.0									
n-Butylbenzene	U	5.0									
n-Propylbenzene	U	5.0									
o-Xylene	U	5.0									
sec-Butylbenzene	U	5.0									
tert-Butylbenzene	U	5.0									
Toluene	U	5.0									
Surr: 4-Bromofluorobenzene	47		50.00		94.9	61	133				
Surr: Toluene-d8	54		50.00		109	57	131				

Sample ID: V624LCS-050709Y	SampType: LCS	TestCode: Dry8260STAR	Units: µg/Kg	Prep Date:		RunNo: 43715					
Client ID: LCSS	Batch ID: R43715A	TestNo: SW8021B		Analysis Date: 5/7/2009		SeqNo: 595816					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
1,2,4-Trimethylbenzene	48	5.0	50.00	0	96.4	30	130				
1,3,5-Trimethylbenzene	50	5.0	50.00	0	100	30	130				
4-Isopropyltoluene	47	5.0	50.00	0	94.1	30	130				
Benzene	42	5.0	50.00	0	83.4	30	130				
Ethylbenzene	47	5.0	50.00	0	94.0	15	130				
Isopropylbenzene	48	5.0	50.00	0	96.6	30	130				
m,p-Xylene	99	10	100.0	0	98.6	30	130				
Naphthalene	42	5.0	50.00	0	84.5	30	130				
n-Butylbenzene	38	5.0	50.00	0	75.4	30	130				
n-Propylbenzene	46	5.0	50.00	0	91.2	30	130				
o-Xylene	47	5.0	50.00	0	94.3	30	130				
sec-Butylbenzene	47	5.0	50.00	0	93.5	30	140				
tert-Butylbenzene	48	5.0	50.00	0	95.9	30	130				
Toluene	42	5.0	50.00	0	84.2	20	119				
Surr: 4-Bromofluorobenzene	49		50.00		98.1	61	133				
Surr: Toluene-d8	51		50.00		101	57	131				

Qualifiers:

- B Value above quantitation range
- H Holding times for preparation or analysis exceeded
- J Analyte detected below quantitation li
- LOD Limit of Detection
- LOQ Limit of Quantitation
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S Spike Recovery outside accepted recovery limits
- U Indicates the compound was analyzed

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8260STARS_Soil

Sample ID: VBLK-050709Y	**SampType:** MBLK	**TestCode:** Dry8260STAR	**Units:** µg/Kg	**Prep Date:**	**RunNo:** 43715
Client ID: PBS	**Batch ID:** R43715A	**TestNo:** SW8021B		**Analysis Date:** 5/7/2009	**SeqNo:** 696817

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
1,2,4-Trimethylbenzene	U	5.0									
1,3,5-Trimethylbenzene	U	5.0									
4-Isopropyltoluene	U	5.0									
Benzene	U	5.0									
Ethylbenzene	U	5.0									
Isopropylbenzene	U	5.0									
m,p-Xylene	U	10									
Methyl tert-butyl ether	U	5.0									
Naphthalene	U	5.0									
n-Butylbenzene	U	5.0									
n-Propylbenzene	U	5.0									
o-Xylene	U	5.0									
sec-Butylbenzene	U	5.0									
tert-Butylbenzene	U	5.0									
Toluene	U	5.0									
Surr: 4-Bromofluorobenzene	46		50.00		91.4	61	133				
Surr: Toluene-d8	51		50.00		102	57	131				

Qualifiers:

E	Value above quantitation range	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation li
LOD	Limit of Detection	LOQ	Limit of Quantitation	ND	Not Detected at the Reporting Limit
R	RPD outside accepted recovery limits	S	Spike Recovery outside accepted recovery limits	U	Indicates the compound was analyzed

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8270stars_Soil

Sample ID: 0905062-01B-MS	SampType: MS	TestCode: Dry8270stars	Units: µg/Kg-dry	Prep Date: 5/8/2009	RunNo: 43786
Client ID: East	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/12/2009	SeqNo: 697006

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Acenaphthene	2700	130	4276	0	64.0	24	124				
Acenaphthylene	U	130	0	0	0	20	130				
Anthracene	47	130	0	0	0	20	130				J
Benzo(a)anthracene	260	130	0	0	0	20	130				
Benzo(a)pyrene	210	130	0	0	0	20	130				
Benzo(b)fluoranthene	390	130	0	0	0	20	130				
Benzo(g,h,i)perylene	180	130	0	0	0	20	130				C
Benzo(k)fluoranthene	120	130	0	0	0	20	130				J
Chrysene	270	130	0	0	0	20	130				
Dibenzo(a,h)anthracene	42	130	0	0	0	20	130				J
Fluoranthene	370	130	0	0	0	20	130				
Fluorene	U	130	0	0	0	20	130				
Indeno(1,2,3-c,d)pyrene	220	130	0	0	0	20	130				C
Phenanthrene	110	130	0	0	0	20	130				J
Pyrene	2800	130	4276	0	66.5	22	126				
Surr: 2-Fluorobiphenyl	1400		2137		67.0	22	112				
Surr: 4-Terphenyl-d14	1400		2137		65.9	24	124				
Surr: Nitrobenzene-d5	1100		2137		53.8	20	116				

Sample ID: 0905062-01B-MSD	SampType: MSD	TestCode: Dry8270stars	Units: µg/Kg-dry	Prep Date: 5/8/2009	RunNo: 43786
Client ID: East	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/12/2009	SeqNo: 697007

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Acenaphthene	2700	130	4259	0	63.9	24	124	2738	0.527	20	
Acenaphthylene	U	130	0	0	0	20	130	0	0	20	
Anthracene	110	130	0	0	0	20	130	46.54	0	20	J
Benzo(a)anthracene	260	130	0	0	0	20	130	262.3	10.3	20	
Benzo(a)pyrene	250	130	0	0	0	20	130	211.8	14.9	20	
Benzo(b)fluoranthene	380	130	0	0	0	20	130	390.6	1.56	20	
Benzo(g,h,i)perylene	170	130	0	0	0	20	130	179.7	2.78	20	C
Benzo(k)fluoranthene	150	130	0	0	0	20	130	119.5	21.4	20	R

Qualifiers:

- B Value above quantitation range
- H Holding times for preparation or analysis exceeded
- J Analyte detected below quantitation li
- LOD Limit of Detection
- LOQ Limit of Quantitation
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S Spike Recovery outside accepted recovery limits
- U Indicates the compound was analyzed

05/28/2009 02:00 FAX 7182723147 ABC TANK 013

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8270stars_Soil

Sample ID: 0905062-01B-MSD	SampType: MSD	TestCode: Dry8270stars	Units: µg/Kg-dry	Prep Date: 5/8/2009	RunNo: 43796
Client ID: East	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/12/2009	SeqNo: 597007

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Chrysene	320	130	0	0	0	20	130	266.2	17.9	20	
Dibenzo(a,h)anthracene	46	130	0	0	0	20	130	42.26	0	20	J
Fluoranthene	580	130	0	0	0	20	130	372.7	43.3	20	R
Fluorene	51	130	0	0	0	20	130	0	0	20	J
Indeno(1,2,3-c,d)pyrene	210	130	0	0	0	20	130	215.7	0.501	20	C
Phenanthrene	550	130	0	0	0	20	130	108.6	134	20	R
Pyrene	3200	130	4259	0	74.3	22	126	2844	10.7	20	
Surr: 2-Fluorobiphenyl	1400		2128		64.5	22	112		0	0	
Surr: 4-Terphenyl-d14	1400		2128		67.1	24	124		0	0	
Surr: Nitrobenzene-d5	1200		2128		55.1	20	115		0	0	

Sample ID: MB-25675	SampType: MBLK	TestCode: Dry8270stars	Units: µg/Kg	Prep Date: 5/8/2009	RunNo: 43796
Client ID: PBS	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/13/2009	SeqNo: 597009

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Acenaphthene	U	120									
Acenaphthylene	U	120									
Anthracene	U	120									
Benzo(a)anthracene	U	120									
Benzo(a)pyrene	U	120									
Benzo(b)fluoranthene	U	120									
Benzo(g,h,i)perylene	U	120									
Benzo(k)fluoranthene	U	120									
Chrysene	U	120									C
Dibenzo(a,h)anthracene	U	120									
Fluoranthene	U	120									
Fluorene	U	120									
Indeno(1,2,3-c,d)pyrene	U	120									
Phenanthrene	U	120									
Pyrene	U	120									C
Surr: 2-Fluorobiphenyl	1700		1998		85.1	22	112				

Qualifiers:

- E Value above quantitation range
- H Holding times for preparation or analysis exceeded
- J Analyte detected below quantitation li
- LOD Limit of Detection
- LOQ Limit of Quantitation
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S Spike Recovery outside accepted recovery limits
- U Indicates the compound was analyzed

CLIENT: ABC Tank Cleaning & Repairing, Inc.
Work Order: 0905062
Project: 27-10 Hunter's Point

ANALYTICAL QC SUMMARY REPORT

TestCode: Dry8270stars_Soil

Sample ID: MB-25675	SampType: MBLK	TestCode: Dry8270stars	Units: µg/Kg	Prep Date: 5/8/2009	RunNo: 43796
Client ID: PBS	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/13/2009	SeqNo: 597009

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Surr: 4-Terphenyl-d14	1800		1998		90.2	24	124				
Surr: Nitrobenzene-d5	1300		1998		66.8	20	115				

Sample ID: LCS-25675	SampType: LCS	TestCode: Dry8270stars	Units: µg/Kg	Prep Date: 5/8/2009	RunNo: 43796
Client ID: LCSS	Batch ID: 25675	TestNo: SW8270D	SW3550A	Analysis Date: 5/13/2009	SeqNo: 597010

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Acenaphthene	3100	120	3999	0	78.5	24	124				
Acenaphthylene	U	120	0	0	0	20	130				
Anthracene	U	120	0	0	0	20	130				
Benzo(a)anthracene	U	120	0	0	0	20	130				
Benzo(a)pyrene	U	120	0	0	0	20	130				
Benzo(b)fluoranthene	U	120	0	0	0	20	130				
Benzo(g,h,i)perylene	U	120	0	0	0	20	130				C
Benzo(k)fluoranthene	U	120	0	0	0	20	130				
Chrysene	U	120	0	0	0	20	130				
Dibenzo(a,h)anthracene	U	120	0	0	0	20	130				
Fluoranthene	U	120	0	0	0	20	130				
Fluorene	U	120	0	0	0	20	130				
Indeno(1,2,3-c,d)pyrene	U	120	0	0	0	20	130				C
Phenanthrene	U	120	0	0	0	20	130				
Pyrene	3100	120	3999	0	77.4	22	126				
Surr: 2-Fluorobiphenyl	1500		1998		75.3	22	112				
Surr: 4-Terphenyl-d14	1700		1998		87.3	24	124				
Surr: Nitrobenzene-d5	1300		1998		63.6	20	115				

Qualifiers:

B	Value above quantitation range	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation li
LOD	Limit of Detection	LOQ	Limit of Quantitation	ND	Not Detected at the Reporting Limit
R	RPD outside accepted recovery limits	S	Spike Recovery outside accepted recovery limits	U	Indicates the compound was analyzed