

NYSDEC SPILL REPORT FORM

DEC REGION: 1 SPILL NUMBER: 0500468
 SPILL NAME: COMMERCIAL BLDG DEC LEAD: HMCIRRIT
 SPILL DATE: 04/11/2005 SPILL TIME: 12:00 pm
 CALL RECEIVED DATE: 04/11/2005 RECEIVED TIME: 1:27 pm

SPILL LOCATION

PLACE: COMMERCIAL BLDG COUNTY: Nassau
 STREET: 40 UNDERHILL BLVD TOWN/CITY: Oyster Bay
 COMMUNITY: SYOSSET
 CONTACT: MIKE CONTACT PHONE: [REDACTED]

CONT. FACTOR: Tank Test Failure SPILL REPORTED BY: Tank Tester
 FACILITY TYPE: Commercial/Industrial WATERBODY:

CALLER REMARKS:

Tank test failure. Recommend uncover and retest.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
#2 fuel oil	Petroleum		0 G	GW,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
COMMERCIAL BLDG.	40 UNDERHILL BLVD SYOSSET NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
001	2,000	#2 fuel oil (on-site)			03	0.00	

DEC REMARKS:

4/11 13:40 CALLED DRY AS A BONE, OWNER WANTED TANK TESTED FOR HIS OWN REASON, INITIAL SYSTEM TEST FAILED IN ULLAGE PORTION OF TANK, CONTACT MIKE AT GENERAL FOR MORE DETAILS

4/11 13:45 CALLED MIKE, NEIL SAVITSKY, GINDELL REALTY, 40 UNDERHILL, HE HIRED GENERAL,
 (C) [REDACTED]

TANK REMOVED, 2 CY CONTAMINATED SOIL REMOVED AT FILL PORT LOCATION, NO FURTHER ACTION

PIN T & A COST CENTER

CLASS: B3 CLOSE DATE: 08/27/2007 MEETS STANDARDS: False