

# NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation, Remedial Bureau E

625 Broadway, 12th Floor, Albany, NY 12233-7017

P: (518) 402-9813 | F: (518) 402-9819

www.dec.ny.gov

September 15, 2017

Mr. Stephen Fleming, P.E.  
Senior Remediation Manager  
Safety-Kleen Systems, Inc.  
11923 Tramway Drive  
Cincinnati, OH 45241

RE: Safety-Kleen Amityville, Site No. 152154

Dear Mr. Fleming:

The New York State Department of Environmental Conservation (the "Department") has reviewed Safety-Kleen's "Q2 2017 Groundwater Monitoring Program Report" dated July 21, 2017. The report provides the results of the June 2017 groundwater sampling event.

Upon review, the Department has the following comments:

- The Department is encouraged by the continued decreasing trend of Mineral Spirits concentrations in site groundwater wells.
- Review of the analytical results indicate favorable responses to the BOS 200 injection program with reductions in contaminant concentrations and mass in the smear and vadous zones. A reduction of sampling frequency from quarterly to semi-annual will not negatively affect the monitoring of the facility's groundwater and is approved.
- ORC filter socks are no longer necessary in monitoring wells GT-3 and GT-5.

If you have any questions on this matter, please contact me at (518) 402-9813.

Sincerely,



Kent D. Johnson  
Senior Engineering Geologist  
Remedial Bureau E  
Division of Environmental Remediation

ec: A. Everett, USEPA, Region 2  
M. Leary, NYAG  
M. Roma, NYAG  
A. Patel, Region 1  
T. Killeen, DER



Department of  
Environmental  
Conservation