



Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96

Site Name: NOW Corporation		Class: 4	Number: 3-14-008
O&M Funding Source: <input checked="" type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input type="checkbox"/> Responsible Party			
O&M Information: O&M Start: April 1999 End: unk Annual Cost: \$ 92,500 <input type="checkbox"/> Estima			
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input checked="" type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Samplin			
<input type="checkbox"/> Other:			
O&M Review Information:			
Reports: Earth Tech - Quarterly OM&M Report; latest July 2000 through February 2001. There have been no exceedenc of the discharge limits since P&T system was brought on-line.			
Inspection: Site inspection conducted by G. Momberger on August 3, 2001 with Keith Decker of Earth Tech.			
Sampling: -			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
Other:			
Recommendations:			
Continue operation of P&T.			
The new WA needs to be executed by consultant to allow for payment.			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class: as above			
Comments: P&T is generally working well, contamination levels have been falling since installation. Capacity of recharge wells is at times exceeded necessitating use of surface water discharge.			
Previous WA ended spring of 2001, a new WA was sent to Earth Tech but a work plan has was not submitted within 90 d window.			
Do we need for other units?			
Project Manager: 		Reviewer: 	
Signature		Signature	
Date		Date	
January 9, 2002		2/5/02	
George F. Momberger	BHSC	GERALD J. RIDER JR	BHSC
518 457-7308		402-9640	
Name	Region or Bureau	Name	Region or Bureau
Telephone		Telephone	