



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code:	360023	Site Name:	Baldwin Place Shopping Center (now Somers Commons)
City:	Baldwin Place	Town:	Somers
Region:	3	County:	Westchester
Current Classification:	02	Proposed Classification:	04
Estimated Size (acres):	28.00	Disposal Area:	Structure
Significant Threat:	Previously	Site Type:	Dry Cleaner
Priority ranking Score:		Project Manager:	Carl Hoffman

Summary of Approvals

Originator/Supervisor: Susan Edwards	02/18/2016
RHWRE: :	06/02/2016
BEEI of NYSDOH:	06/02/2016
CO Bureau Director: Michael Cruden, Director, Remedial Bureau E:	06/02/2016
Assistant Division Director: Michael J. Ryan, P.E.:	08/24/2016

Basis for Classification Change

Threats from the disposal of hazardous waste at this site were addressed by the implementation of the remedy identified for the site by a 1995 Record of Decision. All construction of the components of the site-wide remedy was completed no later than 1998. The Final Engineering Report (FER) confirms that the remedy has been constructed consistent with the requirements in the ROD. The FER is in DecDocs. Management of contamination remaining at the site, including any required monitoring, is and has been controlled pursuant to a Site Management Plan (SMP) (or its equivalent). A copy of the SMP is in DecDocs. Institutional controls were required to ensure the protectiveness of the site. The required controls, in the form of an deed restriction, are in place. A significant threat to public health and the environment no longer exists at the site. The site is properly remediated and requires site management, therefore, it qualifies for Class 4 status on the Registry of Inactive Hazardous Waste disposal sites.

Site Description - Last Review: 02/29/2016

Location Description: This 28 acre shopping mall is located in the Town of Somers in Westchester County. The site is bounded by U.S. Route 6 to the northwest, the North County Trailway (a former NY Central railroad rail-trail) immediately to the east, and an east-west section of Miller Road (formerly route 118) and Putnam County to the north. A large tract of undeveloped woodland borders to the south.

Site Features: A 1.6 acre parcel of the mall known as unit 6 is the main area subject to the remedial program.



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

Except for a groundwater plume, the remainder of the 28 acre parcel is unimpacted by the perchloroethylene (PCE) contamination. The encompassing mall includes three large buildings, several smaller buildings, large parking areas and access roads.

Current Zoning and Use: The property is currently zoned for commercial use and Somers Commons includes several anchor stores with numerous smaller shops and restaurants. There are commercial establishments near the site along Route 6 and Route 118 to the north and northwest of the site, and residential properties along Meadow Park Road to the east. "The Mews", a senior living community, is adjacent to the mall on the west.

Past Use of the Site: The original shopping center was the Baldwin Place Mall built in 1965, and it eventually needed renovation. The current mall, Somers Commons, was constructed in the early 2000s, after a major demolition of the former shopping center was performed. The crushed concrete was re-used on-site for fill and site grading. Concerns regarding PCE contamination surfaced in mall wells and private wells on Meadow Park Road, and was associated with releases from a dry cleaner at the original shopping center. In December, 1994, a consent order for a remedial program was signed with Big V Supermarkets, Inc. the owner of the Baldwin Place Mall. Big V subsequently filed for bankruptcy, and AIG, the surety for a 1.2 million dollar bond has been funding site-related remedial costs.

A number of investigations and studies followed the discovery of contamination, and are available for further reference:

- Groundwater Investigation, J. Robert Folchetti (May, 1989)
- Water Supply and Treatment Alternatives Study, Malcolm Pirnie (October, 1989)
- Remedial Investigation, Vincent Uhl and Associates (August, 1994)
- Feasibility Study, Lawler Matusky and Skelly (June, 1995)
- Record of Decision (November, 1995)

Site Geology and hydrogeology: Overburden at the site consists of 60 feet of sandy silt till. Depth to groundwater in the source area is approximately 12 feet. Overburden groundwater flow is to the southwest. Fractured bedrock lies underneath the overburden.

Contaminants of Concern (Including Materials Disposed)

Quantity Disposed

OU 01

PCE	0.00
TRICHLOROETHENE (F002)	0.00

Analytical Data Available for : Groundwater

Applicable Standards Exceeded for: Groundwater, Drinking Water

Site Environmental Assessment- Last Review: 02/29/2016

Prior to Remediation:

In 1979, Westchester county DOH detected perchloroethylene (PCE), a dry cleaning chemical in mall bedrock wells and off-site in Meadow Park Road private wells. A source area was identified with a dry cleaner located at Baldwin Place Mall. Residual PCE concentrations were present in both the unsaturated and saturated soil in this area. The contamination in the unsaturated soil appeared to be limited to an area of approximately 15 by 15 feet. Shallow groundwater in the source area had a concentration of 24,000 parts per billion (ppb) of PCE.



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

PCE, originating from this source area, had also been detected in the Baldwin Place Shopping Center water supply wells (PW-1, PW-2) since 1979.

Remedial Action:

A first step to prevent public health exposure was the installation of granular carbon filters on affected private homeowner wells along Meadow Park Road (1991). As part of the 1995 ROD required remedial action, in 1997, 138 cubic yards of soil was excavated from the known source area to below the cleanup level of 10 ppm. Also, as part of the remedy, Plant #1 was constructed in 1998 to pump and treat contaminated groundwater generated within the source area.

A water distribution system was subsequently installed in 1999 to supply water to the Meadow Park Road homeowners with carbon treated water from the mall's on-site wells. In late 2001, public water was connected to the distribution system and the former on-site supply wells were no longer used for drinking water. These former supply wells are instead used for remedial purposes. These wells along with the treatment system components are collectively known as Plant #2. This system operated until 2011 when it was determined that pumping these two wells was not an effective part of the remedy. In 2002 several Route 6 businesses and residences along Mahopac Avenue were connected to the new public water line.

An initial soil gas study (legacy site) was conducted in February 2007. Based upon that original study, a full SVI survey was performed in five locations in two of the on-site buildings. Based upon those results, one location closest to the original source area was identified as requiring continued soil vapor intrusion (SVI) monitoring, but not mitigation. The hydrology of the intervening terrain between the site and Meadow Brook Road is an effective barrier against shallow groundwater (the source of potential vapor intrusion) migration to Meadow Park Road.

Post Remediation:

Plant #1 continues to operate in the site management phase. High concentrations (5 ppm), but low volumes, of PCE contaminated water continue to be pumped and treated from the source area. Periodic SVI monitoring, including indoor air and sub-surface vapor monitoring, is performed in one tenant space as part of ongoing site management.

Residual contamination is being managed under a Site Management Plan.

Site Health Assessment - Last Update: 02/29/2016

Access to the site is unrestricted. However, contact with contaminated soil or groundwater is unlikely unless they dig below the ground surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion sampling did not identify any indoor air impacts in the on-site building but monitoring of tenant spaces continues due to concentrations of site related volatile organic compounds in the sub-slab soil vapor beneath the on-site building. An evaluation of the potential for soil vapor intrusion to occur will be completed for any new buildings developed on site in the future. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

	Start		End	
OU 00				
OGC Docket - Access	9/29/15	ACT	8/24/16	PLN
OGC Docket - Deed Restriction	10/15/13	ACT	8/10/15	ACT
Periodic Review	4/1/10	TRM	5/1/10	TRM
Periodic Review	12/4/14	ACT	12/23/14	ACT
Periodic Review	5/1/15	ACT	6/19/15	ACT
Periodic Review	3/16/16	ACT	4/30/16	ACT
Periodic Review	5/4/17	PLN	6/18/17	PLN
Reclass Pkg.	1/27/16	ACT	9/30/16	PLN
Remedial System Optimization - Site Management	7/28/11	ACT	9/18/14	ACT
Remedial System Optimization - Site Management	9/19/14	ACT	2/22/16	ACT
Site Management	4/1/98	ACT	4/1/28	PLN
OU 01				
Remedial Action	2/1/97	ACT	4/1/98	ACT
Remedial Design	1/1/96	ACT	8/1/97	ACT
Remedial Investigation	7/1/92	ACT	11/1/95	ACT
OU 01A				
Remedial Action	10/1/91	ACT	1/1/92	ACT
OU 02				
Remedial Investigation	5/1/00	ACT	8/27/01	TRM
OU 03				
VI Evaluation	1/3/07	ACT	8/4/09	ACT

Remedy Description and Cost

Remedy Description for Operable Unit 01

Excavate PCE source to below 10 ppm. Supply potable water and/or GAC filters. Groundwater treatment with on-site discharge.

Total Cost \$2,260,000



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

Remedy Description for Operable Unit 01A

Total Cost



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

Remedy Description for Operable Unit 02

Investigation of an off-site source of PCE contamination.

This OU can be deleted as the RI was terminated.

Total Cost



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

Remedy Description for Operable Unit 03

Total Cost

OU 00

Site Management Plan Approval: 04/01/1998

Status: ACT

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Site Management Form
9/15/2016

SITE DESCRIPTION

SITE NO. 360023

SITE NAME Baldwin Place Shopping Center (now Somers Commons)

SITE ADDRESS: 80 Route 6 **ZIP CODE:** 10505

CITY/TOWN: Baldwin Place

COUNTY: Westchester

ALLOWABLE USE: Restricted-Residential, Commercial, and Industrial

SITE MANAGEMENT DESCRIPTION

SITE MANAGEMENT PLAN INCLUDES:

IC/EC Certification Plan	YES
Monitoring Plan	YES
Operation and Maintenance (O&M) Plan	YES

Periodic Review Frequency: once a year YES

Periodic Review Report Submittal Date: 05/04/2017



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

Description of Institutional Control

UB Somer, Inc. c/o Urstadt Biddle Prop.

321 Railroad Ave

Baldwin Place, 80 Route 6

Deed Restriction

Block:

Lot:

Sublot:

Section:

Subsection:

S_B_L Image: 4.20-1-11.6

Ground Water Use Restriction

IC/EC Plan

Landuse Restriction

Monitoring Plan

O&M Plan

Site Management Plan

Soil Management Plan

UB SOMERS INC. (c/o Urstadt Biddle Prope

321 Railroad Avenue

80 Route 6

Decision Document

Block:

Lot:

Sublot:

Section:

Subsection:

S_B_L Image: 4.20-1-11

Monitoring Plan

O&M Plan

Site Management Plan

Description of Engineering Control

UB Somer, Inc. c/o Urstadt Biddle Prop.

321 Railroad Ave

Baldwin Place, 80 Route 6

Deed Restriction - Institutional Control Instrument

Block:

Lot:

Sublot:

Section:

Subsection:

S_B_L Image: 4.20-1-11.6

Groundwater Treatment System



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Site Classification Report



DATE: 9/15/2016

Site Code: 360023

Site Name: Baldwin Place Shopping Center (now
Somers Commons)

UB SOMERS INC. (c/o Urstadt Biddle Prope

321 Railroad Avenue

80 Route 6

Decision Document - Institutional Control Instrument

Block:

Lot:

Sublot:

Section:

Subsection:

S_B_L Image: 4.20-1-11

Groundwater Treatment System



PUBLIC NOTICE

State Superfund Program

Receive Site Information by Email. See next page to Learn How.

Site Name: Baldwin Place Shopping Center (now Somers Commons)

September 15, 2016

Site No.: 360023 **Tax Map No.:** 4.20-1-11 and 4.20-1-11.6

Site Location: 80 Route 6, Town of Somers, 10505

Inactive Hazardous Waste Disposal Site Classification Notice

The Inactive Hazardous Waste Disposal Site Program (the State Superfund Program) is the State's program for identifying, investigating, and cleaning up sites where the disposal of hazardous waste may present a threat to public health and/or the environment. The New York State Department of Environmental Conservation (DEC) maintains a list of these sites in the Registry of Inactive Hazardous Waste Disposal Sites (Registry). As of the date of this notice, the site identified above, and located on a map on the reverse side of this page, was reclassified on the Registry as a Class 4 site as it no longer presents a significant threat to public health and/or the environment for the following reason(s):

The following remedial actions have been completed at the site:

- Excavation and removal of contaminated soil identified as a source area.
- Municipal water is now available to all affected properties.
- Site management will continue with:
 - An activated carbon remedial system continuing to pump and treat contaminated groundwater from the source area
 - The soil vapor intrusion pathway has been investigated and monitoring of one on-site space continues
 - Monitoring wells are periodically sampled
 - A site management plan is in place to ensure that all institutional and engineering controls are maintained with periodic certification of these controls.

If you own property adjacent to this site and are renting or leasing your property to someone else, please share this information with them. If you no longer wish to be on the contact list for this site or otherwise need to correct our records, please contact DEC's Project Manager listed below.

FOR MORE SITE INFORMATION

Additional information about this site can be found using DEC's "Environmental Site Remediation Database Search" engine which is located on the internet at:

www.dec.ny.gov/cfm/externalapps/derexternal/index.cfm?pageid=3

Comments and questions are always welcome and should be directed as follows:

Project Related Questions

Carl Hoffman, Project Manager
NYS Department of Environmental Conservation
Division of Environmental Remediation – Bureau E
625 Broadway, 12th Floor
Albany, NY 12233-7017
Email: carl.hoffman@dec.ny.gov
Phone: 518-402-9813

DEC is sending you this notice in accordance with Environmental Conservation Law Article 27, Title 13 and its companion regulation (6 NYCRR 375-2.7(b)(6)(ii)) which requires DEC to notify all parties on the contact list for this site of this recent action.


Approximate Site Location

Baldwin Place Shopping Center (now Somers Commons)

Site ID: 360023

80 Route 6

Town of Somers, Westchester County



Receive Site Updates by Email

Have site information such as this public notice sent right to your email inbox. DEC invites you to sign up with one or more contaminated sites county email listservs available at the following web page:

www.dec.ny.gov/chemical/61092.html . It's *quick*, it's *free*, and it will help keep you *better informed*.



As a listserv member, you will periodically receive site-related information/announcements for all contaminated sites in the county(ies) you select.

You may continue also to receive paper copies of site information for a time after you sign up with a county listserv, until the transition to electronic distribution is complete.

Note: Please disregard if you received this notice by way of a county email listserv.

Electronic copies:

R. Schick, Director, Division of Environmental Remediation
A. English, Director, Bureau of Technical Support
K. Lewandowski, Chief, Site Control Section
M. Cruden, Director, Remedial Bureau E
E. Moore, RHWRE, Region 3
D. Whitehead, Regional Permit Administrator, Region 3
W. Rosenbach, Regional CPS, Region 3
S. Shepard, CPS, Region 3
K. Anders, NYSDOH
M. Schuck, NYSDOH Regional Chief
A. Perretta, NYSDOH Project Manager
L. Ennist, DER, Bureau of Program Management
C. Hoffman, Project Manager
B. Anderson, Site Control Section
Senator Terrence Murphy (murphy@nysenate.gov)
Assemblyman Steve Katz (katzs@assembly.state.ny.us)

Robert Astorino, County Executive
148 Martine Avenue
White Plains, NY 10601

Thomas D. Myers, Executive Vice
President
Urstadt Biddle Properties, Inc.
321 Railroad Avenue
Greenwich, CT 06830

Rick Morrissey, Supervisor
Town of Somers
335 Route 202
Somers, NY 10589

Efrem Citarella, Zoning Officer
Town of Somers
335 Route 202
Somers, NY 10589

Adam Smith, Water Superintendent
Town of Somers
335 Route 202
Somers, NY 10589

Postal Customer
93 Route 6
Somers, NY 10589

Postal Customer
51 Meadow Park Rd
Somers, NY 10589

Postal Customer
59 Meadow Park Rd
Somers, NY 10589

Postal Customer
43 State Hwy 118
Somers, NY 10589

Postal Customer
67 Meadow Park Rd
Somers, NY 10589

Postal Customer
27 Meadow Park Rd
Somers, NY 10589

Postal Customer
83 Meadow Park Rd
Somers, NY 10589

Postal Customer
81 Meadow Park Rd
Somers, NY 10589

Postal Customer
73 Meadow Park Rd
Somers, NY 10589

Postal Customer
9 State Hwy 118
Somers, NY 10589

Postal Customer
91 Route 6
Somers, NY 10589

Postal Customer
89 Route 6
Somers, NY 10589

Postal Customer
93 Route 6
Somers, NY 10589

Postal Customer
89 Route 6
Somers, NY 10589

Postal Customer
93 Route 6
Somers, NY 10589

Postal Customer
75 Meadow Park Rd
Somers, NY 10589

Postal Customer
19 State Hwy 118
Somers, NY 10589

Postal Customer
3 State Hwy 118
Somers, NY 10589

Adis Ramos
264 Mahopac Avenue
Somers, NY 10589

Sherlita Amler, MD, Commissioner
Westchester County Dept of Health
145 Huguenot St.
New Rochelle, NY 10801

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation, Bureau of Technical Support
625 Broadway, 11th Floor, Albany, NY 12233-7020
P: (518) 402-9543 | F: (518) 402-9547
www.dec.ny.gov

August 26, 2016

UB Somers Inc.
c/o Urstadt Biddle Properties
Attn: Mr. Thomas Myers
321 Railroad Ave.
Greenwich, CT 06830

Dear Mr. Myers:

As mandated by Section 27-1305 of the Environmental Conservation Law (ECL), the New York State Department of Environmental Conservation (DEC) must maintain a Registry of all inactive disposal sites suspected or known to contain hazardous waste. The ECL also mandates that DEC notify the owner of all or any part of each site or area included in the Registry of Inactive Hazardous Waste Disposal Sites as to changes in site classification.

Our records indicate that you are the owner or part owner of the site listed below. Therefore, this letter constitutes notification of change in the classification of such site in the Registry of Inactive Hazardous Waste Disposal Sites in New York State. The effective date of the classification change shall be 20 days from the date of this letter.

DEC Site No.: 360023
Site Name: Baldwin Place Shopping Center (now Somers Commons)
Site Address: 80 Route 6, Baldwin Place, Town of Somers, 10505
Classification change: Class 2 to 4

The reason for the change is as follows:

Contaminated soil identified as a source area has been excavated and removed. Municipal water is now available to all affected properties. Site management will continue with: an activated carbon remedial system continuing to pump and treat contaminated groundwater from the source area; the soil vapor intrusion pathway has been investigated and monitoring of one on-site space continues; monitoring wells are periodically sampled; and a site management plan is in place to ensure that all institutional and engineering controls are maintained with periodic certification of these controls.

Enclosed is a copy of DEC's Inactive Hazardous Waste Disposal Site Report form as it will appear in the Registry. An explanation of the site classifications is available at <http://www.dec.ny.gov/chemical/8663.html>. The Law allows the owner and/or operator of a site listed in the Registry to petition the Commissioner of DEC for deletion of such site, modification of site classification, or modification of any information regarding such site, by submitting a written statement setting forth the grounds of the petition.



Department of
Environmental
Conservation

Such petition may be addressed to:

Honorable Basil Seggos, Commissioner
NYS Department of Environmental Conservation
625 Broadway
Albany, New York 12233-1010

For additional information, please contact Carl Hoffman, the project manager at 518-402-9813.

Sincerely,

A handwritten signature in black ink, appearing to read "Kelly A. Lewandowski". The signature is fluid and cursive, with the first name "Kelly" being more prominent.

Kelly A. Lewandowski, P.E.
Chief, Site Control Section


KAL/BA/cw
Enclosure

cc w/Enc:

R. Schick
L. Zeppetelli
A. English
K. Lewandowski
C. Hoffman, Project Manager



**NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF ENVIRONMENTAL REMEDIATION
Inactive Hazardous Waste Disposal Report**



Site Code	360023		
Site Name	Baldwin Place Shopping Center (now Somers Commons)	Address	80 Route 6
Classification	04	City	Baldwin Place Zip 10505
Region	3	County	Westchester Town Somers
Latitude	41 degrees, 20 minutes, 34.42 seconds		Estimated Size 28.0000
Longitude	-73 degrees, 45 minutes, 24.50 seconds		
Site Type	Dry Cleaner	Structure	

Site Description

Location Description: This 28 acre shopping mall is located in the Town of Somers in Westchester County. The site is bounded by U.S. Route 6 to the northwest, the North County Trailway (a former NY Central railroad rail-trail) immediately to the east, and an east-west section of Miller Road (formerly route 118) and Putnam County to the north. A large tract of undeveloped woodland borders to the south.

Site Features: A 1.6 acre parcel of the mall known as unit 6 is the main area subject to the remedial program. Except for a groundwater plume, the remainder of the 28 acre parcel is unimpacted by the perchloroethylene (PCE) contamination. The encompassing mall includes three large buildings, several smaller buildings, large parking areas and access roads.

Current Zoning and Use: The property is currently zoned for commercial use and Somers Commons includes several anchor stores with numerous smaller shops and restaurants. There are commercial establishments near the site along Route 6 and Route 118 to the north and northwest of the site, and residential properties along Meadow Park Road to the east. "The Mews", a senior living community, is adjacent to the mall on the west.

Past Use of the Site: The original shopping center was the Baldwin Place Mall built in 1965, and it eventually needed renovation. The current mall, Somers Commons, was constructed in the early 2000s, after a major demolition of the former shopping center was performed. The crushed concrete was re-used on-site for fill and site grading. Concerns regarding PCE contamination surfaced in mall wells and private wells on Meadow Park Road, and was associated with releases from a dry cleaner at the original shopping center. In December, 1994, a consent order for a remedial program was signed with Big V Supermarkets, Inc. the owner of the Baldwin Place Mall. Big V subsequently filed for bankruptcy, and AIG, the surety for a 1.2 million dollar bond has been funding site-related remedial costs.

A number of investigations and studies followed the discovery of contamination, and are available for further reference:

- Groundwater Investigation, J. Robert Folchetti (May, 1989)
- Water Supply and Treatment Alternatives Study, Malcolm Pirnie (October, 1989)
- Remedial Investigation, Vincent Uhl and Associates (August, 1994)
- Feasibility Study, Lawler Matusky and Skelly (June, 1995)
- Record of Decision (November, 1995)

Site Geology and hydrogeology: Overburden at the site consists of 60 feet of sandy silt till. Depth to groundwater in the source area is approximately 12 feet. Overburden groundwater flow is to the southwest. Fractured bedrock lies underneath the overburden.

Materials Disposed at Site

OU 01

PCE

UNKNOWN

TRICHLOROETHENE (F002)

"

Analytical Data Available for : Groundwater

Applicable Standards Exceeded for: Groundwater, Drinking Water

Assessment of Environmental Problems

Prior to Remediation:

In 1979, Westchester county DOH detected perchloroethylene (PCE), a dry cleaning chemical in mall bedrock wells and off-site in Meadow Park Road private wells. A source area was identified with a dry cleaner located at Baldwin Place Mall. Residual PCE concentrations were present in both the unsaturated and saturated soil in this area. The contamination in the unsaturated soil appeared to be limited to an area of approximately 15 by 15 feet. Shallow groundwater in the source area had a concentration of 24,000 parts per billion (ppb) of PCE. PCE, originating from this source area, had also been detected in the Baldwin Place Shopping Center water supply wells (PW-1, PW-2) since 1979.

Remedial Action:

A first step to prevent public health exposure was the installation of granular carbon filters on affected private homeowner wells along Meadow Park Road (1991). As part of the 1995 ROD required remedial action, in 1997, 138 cubic yards of soil was excavated from the known source area to below the cleanup level of 10 ppm. Also, as part of the remedy, Plant #1 was constructed in 1998 to pump and treat contaminated groundwater generated within the source area.

A water distribution system was subsequently installed in 1999 to supply water to the Meadow Park Road homeowners with carbon treated water from the mall's on-site wells. In late 2001, public water was connected to the distribution system and the former on-site supply wells were no longer used for drinking water. These former supply wells are instead used for remedial purposes. These wells along with the treatment system components are collectively known as Plant #2. This system operated until 2011 when it was determined that pumping these two wells was not an effective part of the remedy. In 2002 several Route 6 businesses and residences along Mahopac Avenue were connected to the new public water line.

An initial soil gas study (legacy site) was conducted in February 2007. Based upon that original study, a full SVI survey was performed in five locations in two of the on-site buildings. Based upon those results, one location closest to the original source area was identified as requiring continued soil vapor intrusion (SVI) monitoring, but not mitigation. The hydrology of the intervening terrain between the site and Meadow Brook Road is an effective barrier against shallow groundwater (the source of potential vapor intrusion) migration to Meadow Park Road.

Post Remediation:

Plant #1 continues to operate in the site management phase. High concentrations (5 ppm), but low volumes, of PCE contaminated water continue to be pumped and treated from the source area. Periodic SVI monitoring, including indoor air and sub-surface vapor monitoring, is performed in one tenant space as part of ongoing site management.

Residual contamination is being managed under a Site Management Plan.

Assessment of Health Problems

Access to the site is unrestricted. However, contact with contaminated soil or groundwater is unlikely unless they dig below the ground surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion sampling did not identify any indoor air impacts in the on-site building but monitoring of tenant spaces continues due to concentrations of site related volatile organic compounds in the sub-slab soil vapor beneath the on-site building. An evaluation of the potential for soil vapor intrusion to occur will be completed for any new buildings developed on site in the future. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

8/26/2016

Owners

Current Owner(s)

THOMAS D. MYERS

UB SOMERS, INC (C/O URSTADT BIDDLE PROPERTIES, INC.)

321 RAILROAD AVENUE

GREENWICH

CT 06830

Previous Owner(s)

MICHAEL ARCHANGEL

COLUMBIA DEVELOPMENT COMPANY

30 CORPORATE CIRCLE, SUITE 101

ALBANY

NY 12203

CORNELIUS MEDERA

BALDWIN PLACE SHOPPING CENTER

176 NORTH MAIN ST.

FLORIDA

NY 10921

Operators

Previous Operator(s)

A & D Dry Cleaners

Baldwin Place Shpg. Ctr.

Mahopac


NY 10505

BALDWIN PLACE SHOPPING CENTER

BALDWIN PLACE SHPG. CTR.

MAHOPAC



NY 10505



AREA MAP




LEGEND:

-  Groundwater Monitoring Well
-  SVI Sample Location

BALDWIN PLACE SHOPPING CENTER
(now SOMERS COMMONS)
80 ROUTE 6 BALDWIN PLACE
WESTCHESTER COUNTY, NEW YORK
NYSDEC SPILL NO. 360023

SITE MAP

FIGURE 3



NOT TO SCALE

REMEDIATION • ENVIRONMENTAL • DRILLING



5 McCrea Hill Road
Ballston Spa, NY 12020
518.885.5383
www.aztechtech.com



Department of Health

ANDREW M. CUOMO
Governor

HOWARD A. ZUCKER, M.D., J.D.
Commissioner

SALLY DRESLIN, M.S., R.N.
Executive Deputy Commissioner

June 2, 2016

Mr. Michael Cruden, Director
Remedial Bureau E
Division of Environmental Remediation
NYS Dept. of Environmental Conservation
625 Broadway
Albany, New York 12233

Re: Site Reclassification (2 to 4)
Baldwin Place Shopping Center
Site #360023
Somers, Westchester County

Dear Mr. Cruden:

At your request, we have reviewed your Department's proposal to reclassify the referenced site from a Class 2 to a Class 4 on the New York State Department of Environmental Conservation's Registry of Inactive Hazardous Waste Disposal Sites. The purpose of our review was to determine whether the reclassification will be protective of public health.

I understand that the following remedial actions have been completed at the site: Excavation and removal of contaminated soil identified as a source area and either potable water was supplied or POET systems were installed and maintained to address private well water contamination until municipal water was supplied to all affected properties. Two groundwater pump and treat remedial systems are in place with one remaining in operation. The soil vapor intrusion pathway has been identified and monitoring of one on-site space continues. An evaluation of the potential for soil vapor intrusion to occur will be completed should the building be redeveloped for occupancy. In addition, a site management plan is place to ensure that all institutional and engineering controls are maintained and the contamination remaining at the site continues to be remediated and monitored.

Based on this information, I believe the reclassification proposal is protective of public health and concur with the Class 4 (requires continued site management) classification. If you have any questions, please contact me at (518) 402-7860.

Sincerely,

A handwritten signature in black ink that reads "Maureen E. Schuck".

Maureen E. Schuck,
Region Chief, Regions 3, 6 & 7
Bureau of Environmental Exposure Investigation

ecc: K. Anders / A. Perretta / e-File
C. Westerman – NYSDOH MARO
P. Kutsy – WCHD
K. Lewandowski/S. Edwards/C. Hoffman – NYSDEC Central
E. Moore – NYSDEC Region 3