From: Mustico, Richard X (DEC) Barraza, Alicia A (DEC) To:

Komoroske, Michael (DEC); Burke, Gerard (DEC); Utberg, Joshua D (DEC) Cc:

Subject: FW: Spill Report for Watervliet Arsenal. Date: Monday, August 06, 2018 2:21:13 PM Attachments: report.er.1804728.2018-08-06.spillsReport.pdf

> image001.png image002.png

Alicia - Please see the attached regarding chromic acid condensate leak/spill. Sounds like significant excavation ongoing. Not sure if you are aware.

R4 Spills and R4 Air will be meeting at the Arsenal at 10:00 tomorrow (August 7th). I plan on attending. Thought you may be interested.

Please let me know if you will be attending.

Thanks-Rick

Richard A. Mustico, P.E.

Regional Hazardous Waste Remediation Engineer, Division of Environmental Remediation New York State Department of Environmental Conservation – Region IV

1130 N. Westcott Rd, Schenectady, NY 12306

P: (518) 357-2273 | C: (518) 949-3132 | Richard.Mustico@dec.ny.gov

www.dec.ny.gov | f |





From: Utberg, Joshua D (DEC)

Sent: Monday, August 06, 2018 2:10 PM

To: Mustico, Richard X (DEC) < richard.mustico@dec.ny.gov>; Potter, Benjamin J (DEC)

<benjamin.potter@dec.ny.gov>

Subject: Spill Report for Watervliet Arsenal.

Josh Utberg Spill Response NYS DEC Fax (518) 357-2389 Tel (518) 357-2388



NYSDEC SPILL REPORT FORM



DEC REGION:	4	4			SPILL NUMBER:		1804728		
SPILL NAME: HART CHROM INC				DEC LEAD:		JDUTBERG			
CALLER NAME: CHARLIE COLLINS				NOTIFIER'S NAME:		CHARLIE COLLINS			
CLR'S AGENCY: HART CHROM INC				NOTIFIER'S AGENCY:		HART CHROM INC			
CALLER'S PHO		NOTIFIER'S PHONE:		(518) 421-3477					
SPILL DATE:		08/01/2018	SPILL TII	ME:	8:00 am		DISPATCH	IER:	
CALL RECEIVE	ED DATE:	08/01/2018	RECEIVE	D TIME: _	10:56 am		DABRUCE	<u> </u>	
		SP	ILL LOC	<u>ATION</u>					
PLACE:	HART CHROI	M INC		_ COUNTY:		Albany			
STREET: 25 GIBSON ST			TOWN/CITY:		Watervliet (c)				
-				COMMU		WATER	RVLIET		
CONTACT:	CHARLIE CO	DLLINS		CONTA	CT PHONE:				
CONT. FACTOR: Equipment Failure				SPILL REPORTED BY: Other					
FACILITY TYPE: Com		nmercial/Industrial		WATERBODY:					
CALLER REM spill to pave	_	an up crew en route/inve	estigation ur	nderway					
MATERIAL chromic acid		CLASS Hazardou	ıs Material	SPILLED 50.00 G	RECO	VERED	RESOURC	ES AFFECTED	
		<u> POT</u>	ENTIAL	SPILLER	<u>s</u>				
COMPANY HART CHROM II	NC	ADDRESS NY				CON	ITACT		
Tank No. Tank	Size Materia	I Cause	Sou	ırce	Test Meth	od	Leak Rate	Gross Failure	

DEC REMARKS:

Spill also called in by Arsenal staff under spill # 1804726. Spill being handled under this number. Telecom with Erik at Arsenal. There is a ventilation system over the Chromic Acid tank that is used for chrome platting. The Vent system sucks the vapors from the tank and those vapors condensed and pooled in a low area of the duck work for the vent. Eventually that condensate leaked out of the duct work and down the wall to the pit in the building. Arsenals FD checked area to make sure that air quality was ok to work in. Speedy dry was put on spill and it is contained in the building. Drains in building were not impacted but do drain to on site treatment. West Central Environmental is responding to complete cleanup and dispose of material. They are also doing some exploratory excavation outside of the wall of the building to make sure no acid migrated through the wall.

JDU also called Charlie at Hart Chrom Inc. Confirmed the same story that was given by Erik. Sent Charlie an email so that he can send closure info. Charlie will contact me if anything changes or further issues are found.

8/2 JDU telecom with Charlie. Vent system is still running until chrome tank is cooled enough to be shut down. As a

Created On: 08/01/2018

Date Printed: 8/6/2018 Last Updated: 08/06/2018 1



NYSDEC SPILL REPORT FORM



DEC REGION:	_ 4	SPILL NUMBER:	1804728
SPILL NAME:	HART CHROM INC	DEC LEAD:	JDUTBERG

result condensate has continued to leak and has now gotten down 4 floors into the pit. The material is viscos and will have to be rinsed which will increase the volume. Spill is still contained and the plan is to eventually rinse it down the chem waste pipe to the treatment plant so that it can be stored in a bulk tank there. West central is continuing cleanup at this point.

8/3/18 JDU on site. Duct work for vent system outside of building has been uncovered. Leaks in that portion of the large 4-5' diameter venting ductwork were found. Soil and concrete structures around leaking section of vent pipe were stained from leak. Soils being removed by a guzzler truck and stored in a large steal roll off type tank and then covered. Discussed with Doug from Arsenal tentatively what would be needed for end point sampling of soil and possible further investigation. Soil in area of leak is had to access with many utilities and structures around and in the subsurface. Cleaned of the spilled material in the building is continuing.

8/6/18 Telecom with Eric Marcy at the Arsenal. They have discovered that the duct work has also leaked in an area where the duct runs through the building wall and product spilled in between a double wall. Cleanup of this tacky viscos material between the walls is taking place. Explained that some metals sampling and more specifically Chromium sampling would be required for end point soil sampling. No groundwater has been encountered yet. Relayed information to Air resources as well as Hazardous Waste Remediation.

Meeting scheduled on site for 8/7. Invited Air Resources as well as Haz Remediation to meeting.

PIN T & A COST CENTER

CLASS: C5 CLOSE DATE: MEETS STANDARDS: False

Created On: 08/01/2018

Date Printed: 8/6/2018 Last Updated: 08/06/2018 2