

Phase I Environmental Site Assessment

October 27, 1997

Ms. Wendy Spears
 Vice President
 ING (U.S.) Capital Corporation
 135 East 57th Street
 New York, New York 10022-2101
 (212) 409-1854 (tel)
 (212) 758-7925 (fax)

Delivered-by-DHL

Star Plaza
 2050 Western Avenue
 Guilderland, New York

Re: IVI Project No.: E7092211
 Star Plaza
 2050 Western Avenue
 Guilderland, New York

Dear Ms. Spears:

IVI Environmental, Inc. ("IVI") is pleased to submit this draft copy of our Phase I Environmental Site Assessment on the above-referenced property. This report outlines the findings of our site reconnaissance, historical land use research, review of governmental records, interviews, and our pre-survey questionnaire.

Please call should you have any questions.

Sincerely,

IVI Environmental, Inc.

DRAFT

Reviewed by: _____
 Gregory J. Doyle
 Project Manager

DRAFT

Reviewed by: _____
 Gordon Hinshaw, CFMM
 Senior Project Manager

GJD:mr

105 Corporate Park Drive • White Plains, NY 10601 • 914-694-9600 (tel) • 914-694-1353 (fax)
 WASHINGTON • LOS ANGELES • MIAMI • SEATTLE • CHICAGO
 PARIS • LONDON

Prepared for
 ING (U.S.) Capital Corporation
 New York, New York

By
 IVI Environmental, Inc.
 White Plains, New York

IVI Project No.: E7092211
 October 27, 1997

New York	Washington, DC	Los Angeles	Miami
105 Corporate Park Drive Suite 113 White Plains, New York 10604 (914) 694-9600 (914) 694-1353	790 Woodlawn Avenue Suite 510 Bethesda, Maryland 20814 (301) 977-0153 (301) 977-3352	200 South Flower Street Suite 1100 Los Angeles, California 90017 (213) 696-0300 (213) 696-0145	1321 Brickell Avenue Suite 1062 Miami, Florida 33131 (305) 358-1776 (305) 372-1797

DRAFT

Star Plaza
 2050 Western Avenue
 Guilderland, New York

IVI Environmental, Inc. PROJECT ENVIRONMENTAL OVERVIEW

Star Plaza 2050 Western Avenue Guilderland, New York 12303

Category	No. Identified Issues	Operations and Maintenance (O&M)	Additional Investigation Recommended	Action/Remediation Recommended	Estimated Cost
Historical Review			1		\$2,000
Regulatory Review	✓				
Recognized Environmental Conditions* on Neighboring Properties	✓				
On-Site Operations			1		\$5,000
Bulk Storage Tanks	✓				
Air Emissions	✓				
Polyvinylchloride Dibenzofuran (PCBs)	3				
Asbestos-Containing Material (ACMs)		4			

- Prior to 1970, a portion of the site served as a gasoline station. Since no testing was conducted during tank removal activities, a subsurface investigation in the area of this former gasoline station is recommended to determine if contamination exists.
- A dry cleaner has operated on-site since 1970. Prior to 1994, the dry cleaner was served by a second generation transfer system that generated a liquid waste stream. Waste disposal records prior to January 1989 were unavailable. Since the subject property utilized a septic system prior to 1973-1974, no historic waste manifests were available and significant staining was observed around the dry cleaning equipment. IVI recommends that subsurface investigations be conducted in the area of the former septic system and the dry cleaning facility.
- The site's utility owned electrical transformers may contain PCBs. No leakage of dielectric fluid was observed on or around the transformers.
- The friable ceiling tiles, non-tileable resilient floor coverings, and the built-up roofing system's felt and flashing may contain asbestos. Since these materials are in good condition, the management of same in-place under an O&M program is recommended.

* Recognized Environmental Conditions are defined in the American Society for Testing and Materials (ASTM) Standard D1527-97 as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property."

DRAFT

TABLE OF CONTENTS

Cover Sheet
 Transmittal Letter
 Project Environmental Overview

	Page
1.0 Executive Summary.....	1
2.0 Introduction.....	3
2.1 General.....	3
2.2 Purpose and Scope.....	3
3.0 Project Description	6
3.1 Overview.....	6
3.2 Property Location	6
3.3 Size and Shape of Parcel	7
3.4 Topography	7
3.5 Surface Waters	7
3.6 Soils, Geology and Groundwater	7
3.7 Surrounding Land Use	9
3.8 Utilities	9
3.9 Building Descriptions	10
3.10 Current Property Use	11
3.11 Environmental Permits	12
3.12 Previous Reports	12
3.13 Plans and Specifications	13
4.0 Site History	14
4.1 Historical Use Summary	14
4.2 Historical Maps	14
4.3 Topographic Maps	15
4.4 Aerial Photographs	15
4.5 Chain-of-Ownership	17
4.6 Municipal File Review	17
4.7 City Directories	18
4.8 Interviews	21
4.9 Previous Report	21

TABLE OF CONTENTS - continued

	Page
5.0 Regulatory Review.....	22
5.1 Federal Databases.....	23
5.2 New York State Department of Environmental Conservation (NYSDEC).....	25
5.3 Local Regulatory Agency Interviews and File Review.....	26
6.0 Site Reconnaissance.....	28
6.1 Site Visit Background Information.....	28
6.2 Chemical Storage and Usage.....	28
6.3 Bulk Storage Tanks.....	28
6.4 Site Waste and Wastewater.....	30
6.5 Stained Soil, Stained Pavement, or Stressed Vegetation.....	31
6.6 Liquid Discharges.....	31
6.7 Pools of Liquid.....	31
6.8 Pits, Ponds or Lagoons.....	31
6.9 Wells.....	31
6.10 On-Site Fill.....	31
6.11 Drums and Containers for Storing Waste.....	32
6.12 Floor Drains and Sumps.....	32
6.13 Odors.....	32
6.14 Air Emissions.....	32
6.15 Polychlorinated Biphenyls (PCBs).....	32
6.16 Asbestos-Containing Material (ACM).....	32
7.0 Conclusions and Recommendations.....	33
8.0 Limiting Conditions.....	35

APPENDICES

Photographs.....	A
Pre-Survey Questionnaire.....	B
Maps and Historical Aerial Photographs.....	C
Computerized Environmental Report.....	D
Correspondence.....	E

DRAFT
ENVIRONMENTAL SITE ASSESSMENT

1.0 EXECUTIVE SUMMARY - continued

This assessment has also identified the following items of environmental concern which warrant mention:

Asbestos-Containing Material (ACM)

The site's friable ceiling tiles and non-friable resilient floor finishes and built-up roofing system's felts and flashing may contain asbestos. Since these materials are in good condition and the potential for fiber release is low, no further action is recommended at this time, other than managing the material in-place under an Operations and Maintenance (O&M) Program.

Polychlorinated Biphenyls (PCBs)

Although unlikely, the site's utility-owned pad and pole mounted electrical transformers may contain PCBs. Of importance, the transformers appeared to be in good condition, free of leakage and not likely to be damaged. In accordance with Section 761 of the Toxic Substance Control Act, the transformers' owner, Niagara Mohawk Power Corporation, is responsible for their maintenance and remediation in the event of a leak.

1.0 EXECUTIVE SUMMARY

This report documents IVT's findings from our Phase I Environmental Site Assessment on Star Plaza ("the Subject"), located at 2050 Western Avenue, Guilderland, New York. The property, which is situated in a suburban area characterized by commercial and residential development, consists of three lots improved with a 34-year old, 49,534 SF retail/office strip center, a 34-year old 3,125 SF bank, a 17-year old, 2,000 SF Dunkin' Donuts, and a 24-year old, 20,700 SF training facility for the disabled. The subject property was previously improved with a small motel, a movie theater and six residences. One of these former residences sold gasoline from the pumps located in its front yard.

The purpose of this Phase I Environmental Site Assessment (ESA) was to assess current site conditions and render an opinion as to the presence of recognized environmental conditions in connection with the property within scope and limitations of ASTM Standard Practice E1527-97. Any exceptions, or deletions from the ASTM practice are described in Section 2.2.2 of this report.

This assessment has revealed no evidence of recognized environmental conditions in connection with the Subject except for the following:

On-Site Dry Cleaner

A dry cleaner has operated on-site since 1970. Prior to 1994, the dry cleaner was served by a second generation transfer system that generated a liquid waste stream. Waste disposal records prior to January 1989 were unavailable. Since the subject property utilized a septic system prior to 1973-1974, historic waste manifests were unavailable, and significant staining was observed around the dry cleaning equipment. IVT recommends that a subsurface investigation be conducted in the area of the former septic system and the dry cleaning facility to determine whether contamination from this site usage exists.

Previously On-Site Underground Storage Tanks

The northwest corner of the Subject was formerly improved with three (3) 1,000-gallon gasoline UST systems which were reportedly removed in 1970. Although the widening of Western Avenue in the early 1970's may have encroached on the location of the UST systems, since no testing of the adjacent soils and/or groundwater was conducted in conjunction with the tank removals, no information is available with regard to potential subsurface impacts in the vicinity of these UST systems. Therefore, IVT recommends that a subsurface investigation be conducted in the area of these former UST systems to evaluate whether or not the site has been impacted.

Page 1

DRAFT
ENVIRONMENTAL SITE ASSESSMENT

Star Plaza
2050 Western Avenue
Guilderland, New York

2.0 INTRODUCTION

2.1 General

IVT was retained by ING (U.S.) Capital Corporation ("ING") to prepare a Phase I Environmental Site Assessment, in compliance with ASTM Standard Practice E1527-97, on the Subject in accordance with our agreement dated September 26, 1997. This assessment was prepared on behalf of and for the exclusive use of ING.

2.2 Purpose and Scope

2.2.1 Purpose

The purpose of this assessment is to determine whether there are "recognized environmental conditions" on the property which may have an impact on the purchase, use or future sales of the property and liability of the client from a governmental agency or private party. Evidence for recognized environmental conditions were sought through environmental and historical records searches, interviews, and a site reconnaissance.

This report is the culmination of an investigation whose purpose was to identify recognized environmental conditions on the property, using the methodology recommended by The American Society for Testing Materials (ASTM). Specifically, this methodology is referred to as ASTM Standard Practice E1527-97. There are no exceptions to the ASTM Standard Practice E1527-97, except for the following: as a result of a Data Failure, as described under Section 7.3.2.3 of ASTM Standard Practice E1527-97, IVT's historical land use was conducted back to 1927, but not to a time when the site was vacant land.

2.2.2 Scope

In general, the scope of this assessment consisted of reviewing readily available information and environmental data relating to the property; interviewing persons knowledgeable about the site; reviewing readily available historical maps and aerial photographs; reviewing readily available records maintained in federal, state, and local regulatory agencies; and conducting a site visit.

Page 3

DRAFT
ENVIRONMENTAL SITE ASSESSMENT

Page 2

2.0 INTRODUCTION - continued

The specific scope of this assignment included, the following:

- 2.2.2.1** A site reconnaissance to characterize on-site conditions and assess the site's location with respect to surrounding property uses and natural surface features. In addition, reconnaissance of the surrounding roads and readily accessible properties to identify obvious potential environmental conditions on neighboring properties was conducted. Photographs taken as part of the site reconnaissance are provided in Appendix A. IVI was provided access to the grounds, and a representative number of tenant spaces. Of importance, IVI was not provided access to the roof and accordingly, we make no representations with respect to same.
- 2.2.2.2** Interviews with persons familiar with the property to obtain information on present and previous on-site activities potentially resulting in the environmental degradation of the site or adjoining properties. A Pre-Survey Questionnaire to be filled out and returned to IVI by someone knowledgeable about the site was provided to Michael Ermides, Vice President of Star Plaza, Inc. A completed copy of the Pre-Survey Questionnaire is provided in Appendix B.

The following table presents a summary of the individuals contacted as part of IVI's assessment of the Subject:

Name	Title	Employer/Department	Telephone No.
Angela Bassini	Associate	Axiom Realty Financial Services	(518) 472-4600
Savas Ermides	President	Star Plaza, Inc.	(518) 456-1442
Michael Ermides	Vice President	Star Plaza, Inc.	(518) 456-1442
Kathy Stidler	Town Clerk	Town of Guilderland	(518) 356-1980
Steven Lukowski	Director of Environmental Services	Albany Health Department	(518) 427-4580
Eric Adams	Chief Fire Inspector	Guilderland Fire Inspector's Office	(518) 356-1980
Mrs. Kullman	Not provided	Niagara Mohawk Power Corporation	(518) 423-3369

- 2.2.2.3** A review and interpretation of readily available historical documents, historical and topographic maps, and/or aerial photographs to identify previous activities on and in the vicinity of the Subject.


3.0 PROJECT DESCRIPTION

3.1 Overview

The Subject consists of Lots 5.1, 5.2, and 7. Lots 5.1 and 5.2 (Parcel A), which are adjacent lots located along Western Avenue. These lots are improved with a 34-year old, 49,534 SF retail/office strip center, a 34-year old, 3,125 SF bank, and a 17-year old, 2,000 SF Dunkin' Donuts. Lot 7 (Parcel B) is located at 6141 State Farm Road, south of Parcel A and separated from same by a 50' wide lot improved with a residence and a garage. Parcel B is improved with a 24-year old, 20,700 SF training facility for the disabled. Surrounding properties are characterized by commercial and residential development. The subject property was previously improved with a small motel and six residences.

3.2 Property Location

As shown in the Site Location Map below, the site is located at 2050 Western Avenue and 6141 State Farm Road in Guilderland, Albany County, New York and is identified on local tax maps as Block 2, Lots 5.1, 5.2, and 7. More specifically, Parcel A is located on the southwest corner of the intersection of Western Avenue and State Farm Road. Parcel B is located on the west side of State Farm Road, 50' south of Parcel A. The approximate geographic coordinates of the property are N42° 41' 50" latitude and W73° 53' 22" longitude.



Site Location Map (not to scale)

3.0 PROJECT DESCRIPTION- continued

3.3 Size and Shape of Parcel

The property consists of three lots, 5.1, 5.2, (Parcel A) and 7 (Parcel B). Parcel A is irregular in shape and 5.4 acres in size, with approximately 500 LF of frontage along Western Avenue to the north, and approximately 552 LF of frontage along State Farm Road to the east. Parcel B is rectangular in shape and 1.7-acres in size, with 204 LF of frontage along State Farm Road to the east.

3.4 Topography

The site is located on the side of a hill and slopes gently from the northeast to the southwest. The topography of the area is characterized as gently rolling hills. According to the United States Geological Survey (USGS) Voorheesville, N.Y. 7.5 Minute Series topographic map, the Subject's elevation ranges from 260' to 250' above mean sea level (msl).

3.5 Surface Waters

There are no surface water bodies or streams on the Subject. The closest open body of water to the Subject is the Kaitkout Kill, located approximately 0.2-mile to the west.

3.6 Soils, Geology and Groundwater

Soils

According to the *Soil Survey of Albany County, New York*, dated June 1992, issued by the United States Soil Conservation Service, the soils at the site are classified as Urban Land.

The general soils of the area are referred to as urban land complex because the soil's original structure and content have been so altered by human activities as to have lost their original characteristics and are thus unidentifiable.

Geology

According to USGS Bulletin GW-20, *The Groundwater Resources of Albany County, New York*, prepared by the USGS in cooperation with the Water and Power and Control Commission in 1949, the northeastern half of Albany County, in which the Subject lies, is located within the Hudson-Mohawk Lowlands.

3.0 PROJECT DESCRIPTION- continued

The bedrock underlying the Subject consists of Middle Ordovician, intensely folded sandstone strata of the Normanskill Formation of the Trenton Group. In addition to the Normanskill Formation, the Trenton Group includes the Austin Glen Formation and the Mount Merino Formation, which contains shales. These units form bedrock ridges that overlook the western shore of the Hudson River. The Normanskill Formation is preserved in fault blocks that have been thrust over the younger Upper Ordovician Snake Hill Shale, which underlies the central part of the Hudson Lowlands subprovince.

Overlying the bedrock is a thick accumulation of Pleistocene glacial lake clay which generally obscures the Snake Hill Shale. During the last million years at least four (4) major advances of glacial ice covered Albany County. The latest was the Wisconsin Glaciation, which covered the area from 70,000 to 16,000 years ago and was more than a mile thick. Each ice sheet plowed southwestward towards the Helderberg Mountains. Ice sheets transported rock debris and deposited a mosaic of glacial till and stratified meltwater sediments. Meltwater flowing southward from the ice sheet was dammed within the proto-Hudson River basin forming a lake which covered the eastern third of the county from about 18,300 to 12,600 years ago. Deposition of sediments in this lake, called Glacial Lake Albany, consisted mostly of varved clay material. The Subject lies on the Lake Albany clay plain. There are no predominant geological surface features such as rock outcroppings on the Subject.

Groundwater

The County's water supply is obtained from both surface reservoirs and subsurface aquifers. The main surface water sources are the Alcove, Basic, Watervliet, and Vly Reservoirs. The main subsurface sources are the deep glacial aquifers in the Hudson and Catskill Valleys and the shallow glacial aquifers in the area commonly called the Pine Bush. Groundwater also has been found in wells drilled into bedrock throughout the county, although the water quality and production quantities vary widely.

Under natural, undisturbed conditions, shallow groundwater flow generally follows the topography of the land surface and on this basis, the topography suggests that groundwater flow across the site is in a southwesterly direction, toward Normans Kill. However, localized conditions can alter flow directions and thus the expected flow may not coincide with actual groundwater flow in the subject area. Based on the elevation of the nearby Kiskut Kill, shallow groundwater in the vicinity of the site is suspected to be located at a depth of about 30' bgs.


DRAFT

3.0 PROJECT DESCRIPTION- continued

Approximately 90% of the property is covered with impervious surfaces such as buildings and asphalt-surfaced parking areas and roadways. Stormwater runoff collected by catchbasins, roof drains, and yard drains is discharged into the municipal stormwater system.

Visual observation of the stormwater system did not identify any abnormal accumulation of petroleum run-off or foreign material. No oily sheens or foul odors were identified in the stormwater management system.

3.9 Building Descriptions

3.9.1 Parcel A

Retail/Office strip center

This structure is a 34-year old, 49,534 SF retail/office strip center. This building was originally a supermarket which was expanded in 1970. Two-story office space additions were added to the eastern and western ends of this building in 1977. The building is of slab-on-grade construction. The superstructure is of structural steel supporting open web joists. The front and side facades are covered with brick veneer, wood siding, and an exterior insulated finish system. The rear facade is of painted concrete masonry units (CMU). The flat roof is reportedly covered with a built-up roofing system.

Interior finishes include floor coverings of carpet, resilient floor tile, ceramic tile, and bare concrete; walls are of painted plaster board, and ceilings typically consist of a suspended system with inlaid acoustical ceiling tiles, or bare metal decking. Heating and cooling are provided by gas-fired rooftop package units.

Key Bank

This structure is a 34-year old, 3,125 SF bank building. The building's tenant, Key Bank, is currently completing a gut rehab. The building is of slab-on-grade construction. The superstructure is of concrete block supporting open web joists. The facades are covered with brick veneer and an exterior insulated finish system. The flat roof is reportedly covered with a built-up roofing system.

Interior finishes include floor coverings of carpet, resilient floor tile, and ceramic tile; walls are of painted plaster board, and ceilings typically consist of a suspended system with inlaid acoustical ceiling tiles. Heating and cooling are provided by gas-fired rooftop package units.

3.0 PROJECT DESCRIPTION- continued

3.7 Surrounding Land Use

The property is located in a suburban setting which is characterized by commercial and residential development. The Subject's two parcels are separated by a 50' wide parcel improved with a single family residence and a garage. The following is a tabulation of surrounding property usage:

Direction	Adjacent Properties	Surrounding Properties
North	Across Western Avenue are a Jiffy Lube and several single-family residences.	Single-family residences and commercial buildings. To the northeast is a Billards retail store and a Rite Aid pharmacy.
South	An apartment complex and a single-family residence.	Apartments complexes
East	Across State Farm Road are a CVS pharmacy, and single-family residences.	Single-family residences
West	A bank and a large strip center shopping mall.	Vacant land; beyond is single-family residences.

The adjacent Jiffy Lube was identified as a RUST site, inasmuch as this site was not identified on the LUST database, it is not suspected of having had a significant negative environmental impact to the subject property.

None of the surrounding properties are suspected to represent an impact to the Subject.

3.8 Utilities

The Subject is served with the following utilities:

Water:	Town of Guilderland
Sanitary Sewer:	Town of Guilderland
Storm Sewer:	Town of Guilderland
Electric:	Niagara Mohawk Power Corporation
Natural Gas:	Niagara Mohawk Power Corporation

According to Kathy Sickler of the Town of Guilderland, the local water authority, the water supplied to the Subject meets all federal and state water quality standards. According to Building Department records, the Subject has supplied natural gas since its construction in 1963.



3.0 PROJECT DESCRIPTION- continued

Dunkin' Donuts

This structure is a 17-year old, 2,000 SF commercial building. The building is of slab-on-grade construction. The superstructure is of concrete block supporting open web joists. The exterior walls are of ribbed split-face concrete masonry units. The building also has an aluminum covered mansard. The flat roof is reportedly covered with a built-up roofing system.

Interior finishes include floor coverings of ceramic tile and bare concrete; walls are of painted plaster board, and ceilings typically consist of a suspended system with inlaid acoustical ceiling tiles. Heating and cooling are provided by gas-fired rooftop package units.

3.9.2 Parcel B

6141 State Farm Road

This structure is a 24-year old, 20,700 SF training facility for the disabled. This building was originally a movie theater which was converted to office space in 1978. A 12,000 SF addition was added to this building in 1993. The building is of slab-on-grade construction. The superstructure is of structural steel supporting open web joists. The front facade is covered with brick veneer. The side facades are of painted CMU. The rear facade is of ribbed split-face concrete masonry units. The flat roof is reportedly covered with a built-up roofing system.

Interior finishes include floor coverings of carpet, resilient floor tile, and ceramic tile; walls are of painted plaster board, and ceilings typically consist of a suspended system with inlaid acoustical ceiling tiles. Heating and cooling are provided by gas-fired rooftop package units.

3.10 Current Property Use

The subject property is developed with a retail shopping center/office complex. The following is a current tenant list of the retail spaces and a short description of their operations.

DRAFT

Star Plaza
2050 Western Avenue
Guilderland, New York

3.0 PROJECT DESCRIPTION- continued

Tenant	Description of Operation
Dorito's Restaurant	Restaurant
Trustco Bank	Bank
Off Track Betting	Entertainment
Guilderland Dry Cleaners	Dry cleaning
Rite Aid Pharmacy	Currently vacant
Super D Liquors	Retail
Dunkin Donuts	Restaurant
Key Bank	Bank

The remaining spaces are either currently vacant or occupied by various offices. The Subject's tenant's primarily consist of retail stores, offices, and restaurants which do not appear to generate significant quantities of hazardous waste. However, the following tenant is generating some hazardous waste:

Guilderland Dry Cleaners

Guilderland Dry Cleaners utilizes perchloroethylene, a dry cleaning solvent. According to Jim Shannon, the store's owner, the existing dry cleaning is a 3-year old 4th generation closed loop system manufactured by ILSA. Mr. Shannon also reported that the waste filters and residual sludges are picked up by Safety Kleen on a as-needed basis. Of note, floor drains were not observed in the area of the dry cleaning equipment. For further information, refer to section 6.4 "Hazardous Waste".

3.11 Environmental Permits

Based on our research, no environmental permits such as wastewater discharge permits, State Pollutant Discharge Elimination System (SPDES), air emissions permits, or petroleum bulk storage (PBS) tank registrations are required at the Subject.

3.12 Previous Reports

IVI reviewed the following previous environmental reports provided by Axiom Realty Financial Services:

Report Title: *Phase I Environmental Site Assessment Star Plaza*
 Prepared By: Northeastern Environmental Technologies Corporation (NETC)
 Ballston Spa, New York
 Prepared For: Segal & Wegner and Star Plaza, Inc.
 Report Date: October 1996

3.0 PROJECT DESCRIPTION- continued

This report concluded "...the results of this ESA have not found the site or surrounding area to be indicative of activities that would be expected to create significant on site environmental contamination." The report also states that "the historical management of dry cleaning chemicals by the Guilderland Dry Cleaning organization and their environmental significance to the subject site is unsubstantiated at this time. The lack of written documentation identifying the methods by which dry cleaning chemicals have been disposed is the most extensible issue surrounding the subject site. NETC recommends that all public regulatory information be solicited from the DEC to substantiate the waste disposal history for the site. Based on the results of this review, additional considerations for the site may be deemed appropriate." NETC also identified resilient floor tiles located in Guilderland Dry Cleaners as suspect ACMs. Of note, 4161 State Farm Road was not within the scope of this report.

Report Title: *Appendix - Phase I ESA Star Plaza Site*
 Prepared By: Northeastern Environmental Technologies Corporation (NETC)
 Ballston Spa, New York
 Prepared For: Mr. Stanley Segal
 Report Date: November 29, 1996

For this addendum, monthly waste disposal records were reviewed from January 4, 1989 through October 28, 1996. This addendum concluded that "there appears to be sufficient information that the GDC (Guilderland Dry Cleaners) facility has (over the past 6 years) appropriately managed it's waste stream. Recent use of tetrachloroethylene should not be expected to represent a significant cause for environmental concern. This opinion is based solely on the site inspection services performed during the 1996 Phase I ESA, the use of a municipal sewer system and the site's recent (i.e. 6-year) waste disposal history. No opinions are offered or implied with respect to the methods by which the Guilderland Dry Cleaners managed it's waste prior to 1989, or the environmental significance that this activity may have on the site's present condition."

3.13 Plans and Specifications

IVI reviewed numerous site plans at the Guilderland Building Department and one provided by Star Plaza, Inc. Review of these documents identified the use of an on-site septic system prior to 1973-1974. For a description of the reviewed documents, refer to Section 4.6 "Building Department".



Page 12

DRAFT

Star Plaza
2050 Western Avenue
Guilderland, New York

4.0 HISTORICAL USE

4.1 Historical Use Summary

Based on our review, the property was improved with a small motel and six residences prior to the construction of the existing improvements. One of these former residences sold gasoline from two (2) pumps in its front yard. No surrounding properties were identified with historic recognized environmental conditions which are suspected to impact the Subject.

Of note, as a result of a Data Failure, as described under Section 7.3.2.3 of ASTM Standard E1527-97, IVI's historical land use was conducted back to 1927, but not to a time when the site was vacant land.

4.2 Historical Maps

Sanborn Fire Insurance Maps (Sanborn Maps)

Sanborn Maps constitute a database of prior site uses of real property for many cities and towns in the United States. The maps were originally created to assist insurance underwriters in understanding the potential fire risk of structures requiring insurance; however, they are also useful for determining the previous uses of a property. Sanborn Maps often contain a wealth of information, relating to uses of individual structures, location of fuel storage tanks, chemical storage tanks, or both, and storage of other potentially toxic substances. Sanborn Maps begin their coverage in 1867 and continue through the present.

IVI had a search of Sanborn Maps conducted. This search did not identify any Sanborn Maps for the Subject. Searching a database such as Sanborn Maps constitutes part of the due-diligence necessary for an Environmental Site Assessment. The lack of Sanborn Mapping suggests that there likely was no historic industrial activity on or in the immediate vicinity of the site.

Town of Guilderland Map

IVI reviewed a Town of Guilderland, County of Albany Map, dated May 1953, at the Guilderland Public Library. This map was created by the NYS Department of Commerce, Bureau of Planning, and indicates the location of structures as of February 1961.

This map identifies a small motel and five residences on Parcel A and a residence on Parcel B. This indicates that these structures were built prior to 1961.

4.0 HISTORICAL USE - continued

NYS Freshwater Wetlands Map

IVI reviewed the NYS Freshwater Wetlands, Voorheesville, NY quadrangle map of the Subject area, which is based on aerial photography taken in 1982, last revised in 1983.

This map identifies a small motel, four residences, the retail strip center with its 1970 addition, and a bank on Parcel A and a movie theater on Parcel B. This indicates the above-referenced structures were constructed prior to 1982.

4.3 Topographic Maps

IVI reviewed the USGS Voorheesville, NY 7.5 Minute Series topographic map of the Subject area, which is based on aerial photography taken in 1952 and 1978, last revised in 1980.


The topographic map identifies the retail strip center with its 1970 addition on Parcel A and the original theater building on Parcel B. These two structures are identified in purple, which indicates they were constructed between 1952 and 1978. In addition, the topographic map identifies four small residences and the motel on Parcel A. These structures are identified in black, which indicates they were constructed prior to 1952. No industrial sites, landfills or wetlands were identified on, or immediately adjacent to, the Subject.

In addition, IVI reviewed a USGS Voorheesville, NY 7.5 Minute Series historic topographic map of the subject area maintained at the Albany County Natural Resources Conservation Services, which is based on aerial photography taken in 1923, last revised in 1927.


The topographic map identifies two residences on Parcel A. One is located at the intersection of State Farm Road and Western Avenue. The other is located on the western side of the subject property, along State Farm Road. These structures are identified in black, which indicates they were constructed prior to 1923. Parcel B is identified as vacant land. No industrial sites, landfills or wetlands were identified on, or immediately adjacent to, the Subject.

4.4 Aerial Photographs

Aerial photographs provide visual documentation of site conditions at the time of the photographs. Activities such as dumping or industrial use of a site can be often discerned through the examination of historical aerial photographs. IVI reviewed photographs for the years 1940, 1952, 1969, and 1977 provided by the Albany County



Page 14



Page 15

Star Plaza
2050 Western Avenue
Guilderland, New York

4.0 HISTORICAL USE - continued

Natural Resource Conservation Service and a 1986-1987 aerial photograph provided by the Albany County Farm Services Agency. Based upon this review, the site was previously improved with a motel and six residences. The following is a synopsis of the aerial photographs reviewed. Of note, the aerial photographs for the years between 1940 and 1969 were fuzzy, making interpretation difficult.

Year	Description	Properties surrounding Properties
1940	Parcel A appears to be improved with several residences. Parcel B appears to be vacant. Of note, the photograph is too fuzzy to distinguish individual features.	The parcel located between the Subject's parcels is improved with a residence and a garage. Properties to the north, across Western Avenue, are improved with single-family residences or are vacant land. To the south, along State Farm Road, are single-family residences. There are several single-family residences to the east, across State Farm Road; beyond is vacant land. To the west is vacant land.
1952	Parcel A appears to be improved with a motel and five residences. Parcel B has been improved with a residence.	Properties to the north and east have been further improved with single-family residences. The western adjacent property has been improved with two barns.
1960	Two of the residences located on Parcel A have been razed, and the property improved with a supermarket building and a bank.	To the distant south are two apartment complexes. To the distant east is a drive-in movie theater. Properties to the northeast, across State Farm Road, have been improved with commercial buildings.
1977	The motel, and two of the residences located on Parcel A have been razed and the supermarket has a large addition to its western side. The residence located on Parcel B has been razed and the property improved with a movie theater.	The western adjacent property has been improved with a retail shopping mall. To the south is an apartment complex.
1986-1987	The last residence, located in the southeastern corner of Parcel A, has been razed and the parcel has been improved with a small commercial building located on the northwest corner.	The southern adjacent property (Parcel B) has been improved with an apartment complex.

4.0 HISTORICAL USE - continued

4.5 Chain-of-Ownership

A copy of the Subject's Chain-of-Title has not been provided for review.

4.6 Municipal File Review

Building Department

IVI reviewed building records for the Subject at the Guilderland Building Department. IVI reviewed the following historically significant documents:

- An Application for Building Permit, Permit #15-3, dated April 19, 1962, for the construction of a supermarket. The existing use of the property was identified as dwellings. This permit identifies the building will use gas heating, have a 5-ply hot tar roof, two lavatories, and two water closets.
- A Property Line Survey of Proposed Shopping Center, dated August 29, 1968. This survey identifies a bank building, a two story residence, and a motel with a residence located in front of it, on the subject property along Western Avenue.
- A Site plan entitled *Outline Description for Star Market*, dated September 13, 1968, which identifies the location of the septic tank and the leaching fields.
- A Site Plan for IGA Plaza, dated January 21, 1972. This plan shows the bank building, the shopping center, and the proposed east and west wing additions. This plan also shows the location of the existing septic tank and leach fields. It also identifies the current dry cleaner tenant space as being occupied by Martinizing Cleaning. A copy of a portion of this plan indicating the location of the septic system and the dry cleaner tenant space is provided within Appendix C.
- A letter from the New York State Department of Transportation (NYSDOT), dated March 2, 1972, indicating they were using eminent domain to take 15' to 20' of property along Western Avenue and 5' to 10' of property along State Farm Road for expansion of the intersection.
- A letter from the Albany County Department of Health, dated August 2, 1972, which states that the "...east addition to Star Plaza can use the existing sewage system until the municipal system, now being developed in the Western Avenue area, is completed."
- A letter from the Guilderland Planning Department, dated August 11, 1972, stating they have no objection to the erection of an 80' by 100' theater on State Farm Road.

4.0 HISTORICAL USE - continued

- A Map Showing Final Survey of the Premises Belonging to Star Plaza, Inc., dated December 18, 1972, revised to June 15, 1973. This map indicates the location of the bank building, the shopping plaza with its additions, the area of land taken by the NYSDOT, the theater building, and the location of the proposed 30' sanitary sewer easements.
- An Access Plan, dated July 1973, for the Jerry Lewis Cinema located on State Farm Road.
- A Planning Department variance dated February 20, 1978, to convert the theater to office space.
- A Permit to Construct a Dunkin Donuts dated 1979.

4.7 City Directories

Several historical Polk city directories for the years between 1957 and 1978 were reviewed at the Guilderland Public Library. City directories provide tenant listings by address, for every year covered by the directory service. This review yielded the following information (the subject property is identified in black/italics):

Year	Address	Tenant
1957	Neuman Ave begins	
	Voorheesville Rd begins	
2054 Western Avenue	Waters, Eug. J.	
2058 Western Avenue	Ervin, Wm.	
2062 Western Avenue	Deschenes Motel Deschenes, Albert A. Rudesheim Gas Station Rudesheim, Fred M. Rudesheim Grocery	
2072 Western Avenue	Golden, Thos.	

This city directory identifies the subject property as being improved with three residences and a motel. One of the residences is identified as the Rudesheim Gas Station.

4.0 HISTORICAL USE - continued

Year	Address	Tenant
1960	Norman Ave begins	
	Voorheesville Rd begins	
2054 Western Avenue	Vacant	
2058 Western Avenue	Ervin, Wm.	
2062 Western Avenue	Deschenes Motel Deschenes, Albert A.	
	Rudesheim Gas Station Rudesheim, Fred M.	
	Rudesheim Grocery	
2072 Western Avenue	Golden, Thos.	

With the exception of one of the residences being identified as vacant, there are no significant changes from the 1957 city directory.

Year	Address	Tenant
1963	Voorheesville Rd begins	
	State Farm Rd. begins	
	No address listed	Kissel, Arth.
	No address listed	Schinnerer, Harry
2054 Western Avenue	Joyce, Frances	
2058 Western Avenue	Murphy, Gen.	
2062 Western Avenue	Dewey, John	
	Schinnerer, Harry	
2062 Western Avenue	Deschenes Motel Deschenes, Albert A.	
	Rudy's Service Station & Grocery	
	Rudesheim, Fred M.	
2072 Western Avenue	Tracy, Geo.	

There are no significant changes from the 1960 city directory.

Year	Address	Tenant
1959	Voorheesville Rd begins	
	State Farm Rd. begins	
2054 Western Avenue	Kissel, Arth.	
2058 Western Avenue	A&P Market	
2062 Western Avenue	Star Super Markets Grocery	
2072 Western Avenue	Murphy, Gen.	
	Vacant	
	Schinnerer, Harry	
2064 Western Avenue	Rudy's Service Station & Grocery	
	Rudesheim, Fred M.	
2069 Western Avenue	Irvon, Geo.	

4.0 HISTORICAL USE - continued

This city directory identifies the subject property as being improved with a supermarket and three residences. One of the residences is identified as the Rudy's Service Station & Grocery.

Year	Address	Listing
1975	Voorheesville Rd begins	
	State Farm Rd begins	
2055 Western Avenue	Kittel, Arth.	
2044 Western Avenue	National Commercial Bank & Trust Co. Photo Hut Normandy West Coiffures Rite Aide Corp. IGA Plaza Super Mart Route 155 Dry Cleaners Guilderland Wine and Liquor Center Barkers Dept. Store	
2043 Western Avenue	Twenty Mall Shopping Center	
2061 Western Avenue	Schinnerer, Harry	

Based on review of this city directory, the three on-site residences were razed prior to 1975. The subject property is identified as being improved with a bank and a shopping center. A dry cleaner is identified on-site.

Year	Address	Listing
1978	Voorheesville Rd begins	
	State Farm Rd begins	
2055 Western Avenue	Kittel, Arth.	
2044 Western Avenue	Star Plaza, Inc. Doberman Frank, psychologist Dante Reilly Brandstein Robt. podiatrist Gold Robt. optometrist Arenstein, Mortimer optometrist School Systems Fed. Credit Union Ray Mar Recyclers (Collections Apts.) Siler, Donald land surveyor planner National Commercial Bank & Trust Co. Photo Hut Harry's Beef Bottle & Beer Rest. Normandy West Coiffures Rite Aide Corp. Guilderland Star Market Route 155 Dry Cleaners Guilderland Wine and Liquor Center Hair Shapers Radio Shack	

Page 20

IVI
ENVIRONMENTAL INC.

Page 21

5.0 REGULATORY REVIEW

A copy of regulatory databases contained within a Computerized Environmental Report (CER) supplied by Environmental Data Resources, Inc. (EDR) is provided in Appendix D. The CER is a listing of sites identified on select federal and state standard source environmental databases within the approximate search distance specified by ASTM Practice for Environmental Site Assessments E1527-97. IVI reviewed each environmental database on a site-by-site basis to determine if any of the sites identified in the CER are suspected to represent a negative impact to the Subject.

The following table lists the number of sites by database within the prescribed search radius appearing in the CER.

Database Reviewed	Search Radius	Number of Sites
Federal National Priorities List (NPL)	One-Mile Radius	0
Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS)	One-Half Mile Radius	1
Federal Resource Conservation and Recovery Act (RCRA) Treatment, Storage, and Disposal (TSD) Facilities List	One Half Mile Radius	0
Corrective Action Tracking System (CARTS)	One-Mile Radius	0
Federal RCRA Generators List	On-Site and Adjoining Properties	1
Federal Emergency Response Notification System (FERN) List	On-Site	0
NYSDEC Active Hazardous Waste Disposal Sites (AHWDS)	One-Mile Radius	0
NYSDEC Landfills or Solid Waste Facilities	One-Half Mile Radius	0
NYSDEC Registered Petroleum Bulk Storage (PBS) Facility List	On-Site and Adjoining Properties	1
NYSDEC Spills Information Database	One-Half Mile Radius	5

The CER identified 39 "Orphan Sites." These are sites which could not be mapped or "geocoded" due to inadequate address information. Refer to page 18 of the CER for a list of these Orphan Sites. IVI attempted to locate these sites via street maps and interviews with personnel familiar with the area. Based on this research, IVI identified two Orphan Sites within the specified radii. These sites are discussed in their respective databases below.

4.0 HISTORICAL USE - continued

Year	Address	Listing
1978	3044 Western Avenue (continued)	Wagner & Farina P.C. Moore D.J. Adv.
	2053 Western Avenue	Kisse, Pamela
	2058 Western Avenue	Twenty Mall Shopping Center
	2061 Western Avenue	Schindeler, Joan

In addition, IVI reviewed the listings for State Farm Road in the above listed city directories. The 1957 city directory did not identify State Farm Road. In the 1960 and 1963 city directories, several residences were identified between Western Avenue and Seward Street located across State Farm Road from Parcel B; however addresses were not provided. The 1969 and 1975 city directories identify the Guilderland Star Super Grocery on Parcel A, and a residence owned by Stanley Plocki on Parcel B. The 1978 city directory identifies the Horne Savings Bank on Parcel A, and the Plocki residence on Parcel B.

4.8 Interviews

According to Sivas Ernides, the Subject's owner and developer, Parcel A was previously improved with five residences and a small motel. Parcel B was improved with a residence. He purchased the first part of the Subject in 1963 and constructed a supermarket and a bank on the lot. He subsequently purchased the surrounding lots and razed their structures. In 1970, he constructed a large addition to the western side of the supermarket. The supermarket moved into this new addition and he converted the former space into individual tenant spaces. In 1972, he constructed two-story office space addition to the east and west side of the supermarket structure. In 1973, he purchased Parcel B, razed the previous residence, and constructed a movie theater on the site. In 1978, the movie theater was converted into office spaces. In 1980, he constructed a Dunkin' Donuts building on the northwest corner of Parcel A.

He further stated that the dry cleaner moved into its current tenant space in 1970.

4.9 Previous Report

According to a report entitled, *Phase I Environmental Site Assessment, Star Plaza*, dated October 1996, prepared by Northeastern Environmental Technologies Corporation (NETC) on behalf of Segal & Wegner and Star Plaza, Inc., "with the exception of residential and agricultural activities; no prior use of the site has been established during this ESA."

IVI
ENVIRONMENTAL INC.Star Plaza
2050 Western Avenue
Guilderland, New York

5.0 REGULATORY REVIEW - continued

A description of the databases reviewed by IVI and an analysis of sites identified within the prescribed search area are presented below:

5.1 Federal Databases

NPL

This is a list of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or "Superfund"). A site must be on the NPL to receive money from the Trust Fund for Remedial Action.

Analysis/Comment: The CER did not identify NPL sites within a one-mile radius of the Subject.

CERCLIS

CERCLIS is the USEPA's system for tracking potential hazardous waste sites within the Superfund program. A site's presence in CERCLIS does not imply a level of federal toxicity or progress at a site, nor does it indicate that hazardous conditions necessarily exist at the location. Within one year of being entered into CERCLIS, the USEPA performs a preliminary assessment of a site. Based upon the results of the preliminary assessment, the USEPA may conduct additional investigations which could lead to a site being listed on the NPL.

Analysis/Comment: The CER identified one CERCLIS-NFRAP site within the prescribed radius.

Property Name/Address	EPA ID No.	Distance/Direction	Topographic Relationship	Status
Grafin Labs State Farm Road	NYD98677173	0.4-mile southwest	Downgradient	NFRAP

The above-referenced site has a No Further Remedial Action Planned (NFRAP) status with the USEPA. A NFRAP status indicates that the site has been removed from the CERCLIS database. Often, NFRAP sites are those sites, following an initial investigation, were found not to exhibit contamination, the contamination was remediated, or the contamination was not of a level as to warrant additional action. Based on its NFRAP status with the USEPA, it is not suspected that the above-referenced site has impacted the subject property.

IVI
ENVIRONMENTAL INC.

Page 22

IVI
ENVIRONMENTAL INC.

Page 23

5.0 REGULATORY REVIEW - continued

RCRA TSD Facility Report

The RCRA TSD Facility Report contains information pertaining to those facilities that either treat, store, or dispose of hazardous waste. While these facilities represent some form of hazardous waste activity, they are most significant if determined to be out of compliance or to have violations.

Analysis/Comment: The CER did not identify RCRA TSD facilities within a one-half mile radius of the Subject.

RCRA Generators

IVI reviewed the list of sites which have filed notification with the USEPA in accordance with RCRA requirements. These sites include generators of hazardous waste regulated under RCRA. Under RCRA, Generators are classified by the weight of hazardous waste generated in a calendar month into the following categories: Large Quantity Generator (LQG), 1,000 Kilograms (kgs) or more; Small Quantity Generator (SQG), 100 to 1,000 kgs.; and Conditionally-Exempt Small Quantity Generator (CEQG), less than 100 kgs. RCRA Generators, while they represent some form of hazardous waste activity, are most significant if they are determined to have Class I Violations or to be non-compliant.

Analysis/Comment: The CER identified one RCRA Generator located on the Subject.

Property Name/Address	EPA ID No.	Distance/Direction	Type of Facility	Violations Identified?
Guilderland Dry Cleaners Star Plaza Rte. 20 & 135	NYD981141393	Subject property	LQG	No

This tenant was identified in the CER as an orphan site. According to the RCRA online database, information for this generator was first received on November 8, 1985. No recorded or outstanding violations were identified on the database. For further information on this tenant, refer to Section 6.4 "Hazardous Waste".

Corrective Action Tracking System (CORRACTS)

CORRACTS is a list of facilities that are found to have had hazardous waste releases and require RCRA corrective action activity, which can range from site investigations to remediation.

Analysis/Comment: The CER did not identify CORRACTS sites within a one mile radius of the Subject.

IVI
ENVIRONMENTAL INC

Page 24

5.0 REGULATORY REVIEW - continued

Analysis/Comment: The CER identified one RPBS facility site within the specified radius.

Property Name/Address	EPA ID No.	Distance/Direction	Upgradient Relationship	LUST Site
Jiffy Lube 2057 Western Avenue	4-IC69214	Adjacent north	Upgradient	No

This site is listed as having two 4,000-gallon USTs, one 2,000-gallon UST, one 275-gallon AST and four 110-gallon AST. The ASTs are listed as being closed in place. Inasmuch as the registered storage tank list is only an inventory of storage tanks and does not necessarily constitute a contamination condition, and none of the registered storage tank sites reviewed were identified on environmental regulatory databases signifying a contamination condition, it is not suspected that the identified registered storage tank site has had a negative environmental impact on the Subject.

Spills Information Database

The Spills list is an inventory of all spills and leaks, both active and inactive. It includes stationary and non-stationary source spills reported to state and federal agencies, including remediated and unremediated leaking USTs.

Analysis/Comment: The CER identified 5 LUST/Spill sites within the specified one half mile radius of the Subject.

All of these LUST/Spill sites within the prescribed search radius have a "Case Closed" status. A Case Closed status is granted to those sites which either do not exhibit levels of contamination requiring remediation, have been remediated to the satisfaction of the NYSDEC or are not suspected to represent a significant threat to human health or the environment. As such, none of these sites are suspected to have had a negative environmental impact on the Subject.

5.3 Local Regulatory Agency, Interviews and File Review

Fire Department

IVI has sent a request to the Guilderland Fire Department for environmental information pertaining to the subject property. As of this writing, the Fire Department has not responded to our request. Should receipt of a response from the Health Department change the conclusions of this report, ING will be notified in writing by IVI.

IVI
ENVIRONMENTAL INC

Page 26

5.0 REGULATORY REVIEW - continued

ERNS

The Emergency Response Notification System (ERNS) is a database used to store information on notifications of oil discharges and hazardous substance releases. The primary purpose of ERNS is to standardize and collect notifications made to the Federal government of releases of oil and hazardous substances. These notifications are used by "On-Scene Coordinators" to determine an emergency response and release prevention. When a call is made to the NRC or one of the ten EPA Regions, a report is created containing all of the release information that the caller provided. This report is transferred to an appropriate agency to evaluate the need for a response, and the records are electronically transferred to the ERNS database.

As such, if a reported release of oil or a hazardous substance is deemed to require a response, it should be listed in the appropriate federal or state level environmental database such as CERCLIS, state equivalent CERCLIS, or state leaking underground storage tank or spills.

Analysis/Comment: The CER did not identify the Subject on the ERNS database.

5.2 New York State Department of Environmental Conservation (NYSDEC)

Inactive Hazardous Waste Disposal Sites (IHWDS)

The IHWDS list is an inventory of dumps, landfills, and other toxic sites listed by the NYSDEC. These sites are either being actively remediated, or are currently under evaluation for further action, if necessary.

Analysis/Comment: The CER did not identify SHWS sites within a one-mile radius of the Subject.

Solid Waste Facilities (SWF)

The SWF list is an inventory of landfills, incinerators, transfer stations, and other sites that manage solid wastes.

Analysis/Comment: The CER did not identify SWF facilities within a one-half mile radius of the Subject.

State Registered Petroleum Bulk Storage (RPBS) Facility List

The RPBS facility list is an inventory of all petroleum storage facilities that have greater than 1,100 gallons and less than 400,000 gallons of capacity that are registered with the NYSDEC.

IVI
ENVIRONMENTAL INC.

Page 25

5.0 REGULATORY REVIEW - continued

Health Department

IVI has sent a request to the Albany County Health Department for environmental information pertaining to the subject property. As of this writing, the Health Department has not responded to our request. Should receipt of a response from the Health Department change the conclusions of this report, ING will be notified in writing by IVI.

IVI
ENVIRONMENTAL INC

Page 27

DRAFT

Star Plaza
2050 Western Avenue
Guilderland, New York

Star Plaza
2050 Western Avenue
Guilderland, New York

6.0 SITE RECONNAISSANCE

6.1 Site Visit Background Information

Site Visit Conducted By: Gregory J. Doyle
 Date of Site Visit: October 14, 1997
 Site Representatives: Savas Ernides, Owner and Developer; and Michael Ernides, Vice President
 Weather: 60 °F, Cloudy

Of importance, IVI was not provided access to the roof and accordingly, we make no representations with respect to same.

6.2 Chemical Storage and Usage

Dry cleaning solvents, specifically perchloroethylene (PCE), are stored in a chamber within Guilderland Dry Cleaners 4th generation closed-loop dry cleaning machine. There was significant staining observed around the dry cleaning equipment, presumably from the site's previous dry cleaning equipment. Refer to Section 6.4 "Hazardous Waste" for further information pertaining to same.

With the exception of chemicals customarily used for routine building maintenance and cleaning and the above referenced PCE, IVI did not observe significant quantities of chemicals stored on site. No floor drains or sumps were observed in the vicinity of the chemical storage areas. In addition, housekeeping was generally considered satisfactory. The chemicals, which are stored in their original containers, do not appear to represent an impact to the environmental quality of the site provided that they are used as intended, properly handled, and the regulations pertaining to their usage are followed.

6.3 Bulk Storage Tanks

Underground Storage Tanks (USTs)

No USTs were identified on the subject property and no common indicators of USTs such as vent pipes, fill ports, manways, pavement cuts, fuel gauges or dispensers were observed. In addition, according to Savas Ernides, the Subject's owner and developer, there are currently no USTs on-site. Furthermore, the subject site was not identified on the NYSDEC list of registered UST facilities.

Page 23

IVI
ENVIRONMENTAL INC.

6.0 SITE RECONNAISSANCE - continued

6.4 Site Waste and Wastewater

Solid Waste

Non-hazardous solid waste is disposed of in dumpsters and is removed from the Subject on a regular basis by Waste Management of Eastern New York, Robert Wright Disposal, or Malones. Potential sources of contamination, such as waste oil and automotive batteries, were not observed in the vicinity of the dumpsters.

No areas that were apparently filled with non-natural material, or with material of unknown origin, were observed. In addition, no mounds or depressions indicative of trash or solid waste disposal were observed.

Sanitary Sewage

Sanitary sewage disposal is currently provided by the municipality. IVI did not observe any sources of wastewater or liquid discharge into the sewer other than sanitary sewage.

Prior to 1973-1974, sanitary sewage disposal was provided by an on-site septic system. The leachfield is located in the southwest corner of Parcel A. Inasmuch as hazardous materials were used on-site on a regular basis by the on-site dry cleaner, the cleaner has been on-site since 1970, and significant staining of the floor around the dry cleaning machinery was noted, the potential exists that hazardous materials have been introduced into the former septic system.

Hazardous Waste

The current dry cleaner, Guilderland Dry Cleaners, is a RCRA Large Quantity Generator of hazardous wastes (ID No. NYD981141939). Guilderland Dry Cleaners utilizes perchloroethylene (PCE), a dry cleaning solvent.

According to the store's owner, Jim Shannon, the current dry cleaning equipment is a 3-year old fourth generation closed loop system manufactured by ILSA. PCE is stored in a chamber in the machine and is used and recycled via two carbon filters and a built-in still. As the fluid is recovered and condensed, impurities are accumulated as a sludge. The sludge is removed and placed in a small 10-gallon, plastic lined container. The PCE is added directly to the machine by Mer-White, the Subject's PCE supplier. The sludge and spent filters are picked up by Safety Kleen on an as-needed basis. IVI observed one partially-full 10-gallon plastic container on-site.

6.0 SITE RECONNAISSANCE - continued

According to Savas Ernides, the owner of the previous on-site residence located on the northwest corner of Parcel A, in front of the existing Dunkin' Donuts building, sold gasoline from two pumps located in front of his house. When Mr. Ernides purchased this property in 1970, the three 1,000-gallon USTs and pumps were removed. Mr. Ernides further stated that in the mid-1970's, Western Avenue was expanded from one lane in each direction to two lanes with turning lanes. He stated that these former USTs and pumps were located under what is now part of Western Avenue. According to IVI review of historical city directories, this facility was formerly called Rudy's Service Station and Grocery.

IVI reviewed a letter from the NYSDOT, dated March 2, 1972, on-file at the Guilderland Building Department. This letter served to inform Star Plaza that due to the expansion of the intersection of Rt. 155 and Rt. 20, 15' to 20' of property along Western Avenue would be taken under eminent domain. In addition, IVI reviewed a site plan entitled *Map Showing Final Survey of Premises Belonging to Star Plaza, Inc.*, dated December 18, 1972, revised June 15, 1973, provided by Star Plaza, Inc. This map indicates the width of land taken by the NYSDOT in the vicinity of the former residence was #10'.

Since no testing of the underlying and adjacent soils and groundwater was conducted in conjunction with the tank removal activities, no information is available with regard to potential subsurface impacts in the vicinity of these USTs.

Aboveground Storage Tanks (ASTs)

No ASTs were observed and IVI did not identify any equipment within the building which should require such tanks. Furthermore, according to Savas Ernides, there are no ASTs on-site. Visual indicators of past ASTs, such as tank cradles, secondary containment structures, pedestals, etc., were not observed.

According to a report entitled, *Phase I Environmental Site Assessment, Star Plaza*, dated October 1996, prepared by NETC, during their site reconnaissance a 275-gallon AST was observed in the rear storage area of the Guilderland Dry Cleaners. The NETC report states "...the function of this tank was not substantiated during this ESA." IVI suspects this tank previously contained either PERC for the dry cleaning equipment or fuel oil for hot water heaters/heaters in the dry cleaners. IVI did not observe this AST during our site reconnaissance.

Page 24

IVI
ENVIRONMENTAL INC.

Page 24

6.0 SITE RECONNAISSANCE - continued

No dry cleaning odors were noted in the building. At the end of the cleaning cycle, the vapors are condensed for reuse.

In November of 1996, as a follow-up to their Phase I ESA, NETC reviewed monthly waste disposal records for this dry cleaner from January 4, 1989 through October 28, 1996. Waste disposal records prior to January 1989 were not available.

According to Mr. Shannon, the previous dry cleaning machine was a second generation machine. Of importance, second generation machines produce a liquid waste. Significant staining on the floor around the dry cleaning equipment was observed.

6.5 Stained Soil, Stained Pavement, or Stressed Vegetation

There was no evidence of soil staining or stressed vegetation observed on-site.

6.6 Liquid Discharges

No visible evidence of current liquid discharges, suspected to represent an environmental concern into or from the Subject were observed during our survey.

6.7 Pools of Liquid

IVI did not observe significant standing surface water or pools containing liquids likely to be hazardous substances or petroleum products.

6.8 Pits, Ponds, or Lagoons

IVI did not observe pits, ponds, or lagoons suspected of containing hazardous substances or petroleum products on the Subject.

6.9 Wells

IVI did not identify on-site dry wells, irrigation wells, injection wells, observation wells, monitoring wells, potable water wells, recovery wells or abandoned wells.

6.10 On-Site Fill

Based on our observations, it does not appear that oil has been imported onto the subject property.

Page 30

IVI
ENVIRONMENTAL INC.

Page 31

IVI
ENVIRONMENTAL INC.

6.0 SITE RECONNAISSANCE - continued

6.11 Drums and Containers for Storing Waste

With the exception of non-hazardous solid waste containers and the above-referenced dry cleaning container, IVI did not identify containers suspected of storing waste. With respect to the non-hazardous solid waste containers, no significant environmental concerns were noted.

6.12 Floor Drains and Sumps

IVI did not observe floor drains or sumps that were stained, emitting foul odors, located adjacent to chemical storage areas, or connected to an on-site disposal system.

6.13 Odors

IVI did not identify strong, pungent, or noxious odors suspected to represent any environmental concerns.

6.14 Air Emissions

IVI did not identify processes or equipment which emit noticeable vapors or fumes.

6.15 Polychlorinated Biphenyls (PCBs)

IVI observed one utility-owned pad-mounted electrical transformer on-site. This site's utility-owned transformer may contain PCBs. According to Mrs. Kullman of the Niagara Mohawk Power Corporation, the local electric authority, this transformer may contain 50-499 ppm of PCBs, which classifies it as PCP contaminated. The transformer observed appeared to be in good condition, free of leakages and staining, and not likely to be damaged.

According to the Toxic Substances Control Act (TSCA), Section 761, the owner of the transformers, Niagara Mohawk Power Corporation is responsible for the transformer's maintenance and remediation in the event of a leak.

Interior transformers observed were "dry" units which do not contain PCBs.

6.16 Asbestos-Containing Material (ACM)

Based upon the age of the subject buildings, the site's friable ceiling tiles, non-friable resilient floor finishes, and the built-up roofing system's felts and flashing may contain asbestos. These materials are in good condition and the potential for fiber release is low.

7.0 FINDINGS AND CONCLUSIONS

IVI has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Standard Practice E1527-97 of Star Plaza, located at 2050 Western Avenue, Guilderland, New York. The Subject consists of three lots improved with a 34-year old, 49,534 SF retail/office strip center, a 34-year old, 3,125 SF bank, a 17-year old, 2,000 SF Dunkin' Donuts, and a 24-year old, 20,700 SF training facility for the disabled. Any exceptions to, or deletions from, the standard practice are described in-depth within the body of this report. This assessment has revealed no evidence of recognized environmental conditions in connection with the Subject except for the following:

On-Site Dry Cleaner

A dry cleaner has operated on-site since 1970. Prior to 1994, the dry cleaner was served by a second generation transfer system that generated a liquid waste stream. Waste disposal records prior to January 1989 were unavailable. Since the subject property utilized a septic system prior to 1973-1974, historic waste manifests were unavailable, and significant staining was observed around the dry cleaning equipment. IVI recommends that a subsurface investigation be conducted in the area of the former septic system and the dry cleaning facility to determine whether contamination from this site usage exists.

Previously On-Site Underground Storage Tanks

The northwest corner of the Subject was formerly improved with three (3) 1,000-gallon gasoline UST systems which were reportedly removed in 1970. Although the widening of Western Avenue in the early 1970's may have encroached on the location of the UST systems, since no testing of the adjacent soils and/or groundwater was conducted in conjunction with the tank removals, no information is available with regard to potential subsurface impacts in the vicinity of these UST systems. Therefore, IVI recommends that a subsurface investigation be conducted in the area of these former UST systems to evaluate whether or not the site has been impacted.

This assessment has also identified the following items of environmental concern which warrant mention:

Asbestos-Containing Material (ACM)

The site's friable ceiling tiles and non-friable resilient floor finishes and built-up roofing system's felts and flashing may contain asbestos. Since these materials are in good condition and the potential for fiber release is low, no further action is recommended at this time, other than managing the material in-place under an Operations and Maintenance (O&M) Program.


7.0 FINDINGS AND CONCLUSIONS - continued

Polychlorinated Biphenyls (PCBs)

Although unlikely, the site's utility-owned pad and pole mounted electrical transformers may contain PCBs. Of importance, the transformers appeared to be in good condition, free of leakage and not likely to be damaged. In accordance with Section 761 of the Toxic Substance Control Act, the transformers' owner, Niagara Mohawk Power Corporation, is responsible for their maintenance and remediation in the event of a leak.

8.0 LIMITING CONDITIONS


- 8.1 This report has been prepared in accordance with generally accepted practices for conducting a Phase I Environmental Site Assessment in compliance with the ASTM standard entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process". The purpose of this assessment was to determine the presence of hazardous substances or petroleum product conditions on the Subject, if any; and to render an opinion.
- 8.2 The observations described in this report were made under the conditions stated therein. The conclusions presented in the report were based solely upon the services described therein, and not on scientific tasks or procedures beyond the scope of described services in the time and budgetary constraints imposed by the client. The work described in this report was carried out in accordance with the Terms and Conditions in the contract.
- 8.3 In preparing this report, IVI has relied on certain information provided by federal, state, and local officials and other parties referenced therein, and on information contained in the files of state agencies, local agencies, or both, available to IVI at the time of this site assessment. Although there may have been some degree of overlap in the information provided by these various sources, IVI did not attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of this site assessment. Observations were made of the site and of the structures on the site as indicated in this report. Where access to portions of the site or to structures on the site was unavailable or limited, IVI renders no opinion as to the presence of indirect evidence relating to petroleum substances, hazardous substances, or both, in that portion of the site and structure. In addition, IVI renders no opinion as to the presence of indirect evidence relating to hazardous material or oil, where direct observation of the interior walls, floors, ceiling or a structure is obstructed by objects covering on or over these surfaces.
- 8.4 This report was prepared on behalf of and for the exclusive use of ING and may not be relied upon by any other person or entity. The contents of this report may not be quoted in whole or in part or distributed to any other person or entity other than ING without, in each individual case, the advanced written consent of an officer of IVI.
- 8.5 IVI does not represent that the site referred to herein contains no petroleum or hazardous or toxic substances or other conditions beyond those observed by IVI during the site assessment.
- 8.6 As part of this assessment, IVI submitted requests for information via the Freedom of Information Act (FOIA) to various governmental agencies. As of the preparation of this report, these requests may not have been fulfilled. The conclusions of this report are subject to change upon receipt of a response from these FOIA requests.



1. Front facade of the retail/offices building



3. Surrounding properties to the north



2. Front facade of the 6141 State Farm Road building



4. Surrounding properties to the east

IVI
ENVIRONMENTAL INC

IVI
ENVIRONMENTAL INC



5. Surrounding properties to the west




7. Location of the abandoned septic leach field



6. The pad-mounted utility-owned electrical transformer

8. The rear of the on-site dry cleaning machine. Note the significant staining on the floor



IVI
ENVIRONMENTAL INC

IVI
ENVIRONMENTAL INC

PROPERTY DESCRIPTION & ANALYSIS - continued

1. Does the Subject contain an oil or gas-fired boiler or furnace? Yes No If so, what is the fuel type?
2. Are there any floor drains on the site? Yes No DK
(If so, where do they discharge to?) *Private Sewer System*
3. Previous Studies
Do you have any knowledge of any previously prepared Environmental Assessment Reports or testing conducted on the site, whether it be for the owner or others? If so, who prepared such report(s) when were they prepared, and who conducted testing, if any?
*Niagara Environmental Technologies Corp. (G.I.S.) 1992
Phase I - Complete October 1992
Survey to Nuke Power Report
No Results Generated.*
 I have no knowledge of any environmental related studies or reports prepared on the Subject either for myself, the company I represent, my attorney, or others.

REGULATORY

1. Has the property ever been subject to any environmental enforcement action by the local, government, federal or state entities? Yes No DK
If so, please explain.
2. Do you have any knowledge of pending or contemplated environmental actions against the Subject or neighborhood properties? Yes No DK
If so, please state the circumstances.
3. Have there been any formal or informal citizen complaints such as residents with complaints of respiratory distress regarding the Subject? Yes No DK
If so, please explain.

Page 5 of 9

IVI

SEARCHED INDEXED SERIALIZED FILED
10/12/97 101 ENVIRONMENTAL + 518 426 3002 NO. 1073 DED

E. PCBs - continued

3. Did any on-site transformers once contain PCBs, but later had the coolant replaced? Yes No DK
4. Is there any hydraulic equipment on-site? Yes No DK

F. STORAGE TANKS

1. Are there any registered or unregistered (active or inactive) Underground Storage Tanks ("UST") or Aboveground Storage Tanks ("AST") located on the premises? Yes No DK
If so, please fill out the following schedule.

Location	Size (Gallons)	AST or UST	Product Type	Age	Date Last Tested	Registered (Y/N)	Active or Inactive

1. Do you have any knowledge of any tanks that once existed on the Subject and whether such tanks were removed or abandoned? Yes No DK
If so, by whom, and when?
*3 - 1000 Gallon Fuel Storage Tanks
Removed in 1970*
2. Have any of the existing in-use tanks been tested to determine whether any leakage has occurred? Yes No DK
If so, when?
THERE ARE NO EXISTING IN-USE TANKS
3. Are there any pipes or UST access ways protruding from the ground, retaining walls or buildings? Yes No DK

G. LEAD

1. Are you aware of any lead-based paint ("LBP") applications on the site? Yes No DK
2. Has LBP testing been conducted? Yes No DK
3. Have there been any reported incidences of children with elevated blood levels residing at the site? Yes No DK

Page 7 of 9

IVI

D. ASBESTOS

4. Is any neighboring property engaged in the storing, transporting or disposal of hazardous waste, or chemicals? Yes No DK
5. Do you have any knowledge if an inspection for asbestos was ever performed on the Subject? Yes No DK
If so, who performed the inspection and when?

6. Do you have any knowledge of any materials or substances on the site that are known or suspected to contain asbestos? Yes No DK
If so, what materials and where are they located?

7. Has any asbestos been removed from the Subject? Yes No DK
If so, by whom?

8. Does the building have:
a. Any spray-on fireproofing? Yes No DK
b. Insulation on piping, boilers, tanks, chillers, or other mechanical equipment? Yes No DK
c. Any insulation used in cooling towers, exterior walls, ceilings, fascia panels, etc.? Yes No DK
d. Vinyl asbestos floor tile? Yes No DK
e. Suspended acoustical ceiling tiles? Yes No DK
f. A built-up or rolled roofing system? Yes No DK

E. PCBs

1. Are there any on-site electrical transformers? Yes No DK
2. Do any of these transformers contain PCBs? Yes No DK
Who owns these transformers and where are they located?
*Niagara Mohawk Power Corp.
Behind Building at Loading Dock*

Page 6 of 9

TOTAL P.02

SEARCHED INDEXED SERIALIZED FILED
10/12/97 101 ENVIRONMENTAL + 518 426 3002 NO. 1073 DED

G. LEAD - continued

4. Have any LBP assessments been conducted? Yes No DK
5. Has the water been tested for lead? Yes No DK
If so, what were the results?

H. HAZARDOUS MATERIALS

1. Are any hazardous materials, chemicals, or substances stored on-site used for any manufacturing processes, automotive repair or for pest control (pesticides)? Yes No DK
If so, please provide a schedule of same (please attach separate page if more room is required).

Substance	Quantity	Location

2. Are there physical signs of any of the following on the property? *None*
- | | |
|--|---|
| <input type="checkbox"/> • UnderGround Storage Tanks | <input type="checkbox"/> • PCBs |
| <input type="checkbox"/> • Stained Soil | <input type="checkbox"/> • Oil/Gas Drums |
| <input type="checkbox"/> • Vegetation Damage | <input type="checkbox"/> • Above Ground Tanks |
| <input type="checkbox"/> • Oily Sheens on Water | <input type="checkbox"/> • Lead Paint |
| <input type="checkbox"/> • Discarded Batteries | <input type="checkbox"/> • Asbestos |
| <input type="checkbox"/> • Other _____ | <input type="checkbox"/> • Debris Piles |

Page 8 of 9

IVI

STAR PLAZA TENANT LIST

H. HAZARDOUS MATERIALS - continued

3. To the best of your knowledge, do any of the following operations take place on the Subject or have ever taken place on the Subject?

- Dry Cleaning: Yes No
- Battery Storage/Sales: Yes No
- Paint Storage/Sales: Yes No
- Perculum Storage/Sales: Yes No
- Photo or X-Ray Finishing: Yes No
- Electronic Equipment Assembly or Manufacturing: Yes No
- Solvent Storage or Sales: Yes No
- Chemical Manufacturing/Sales: Yes No
- Automobile Storage, Repair, or Disposal: Yes No
- Agriculture: Yes No
- Medical or Dental Offices: Yes No

If yes, please describe: Dry Cleaning Business Occupied 2,500 Sq Ft on Lower Level
2 floors above us time period to 1970 and beyond

4. Are, or have any, adjoining sites been used for any of the preceding operations?

Yes No DK

5. Are there any hazardous or medical waste or fluids generated or used on the site that utilized an outside service for their periodic pick-up and removal? If so, provide name, address, & telephone number of the disposal company and the facility generating the waste.

Dry Cleaners uses THERMOCLEAN INC. WHICH IS
OPERATING PERMIT FROM ROME NY SANITARY DEPT.
72 STATE ROAD, LEBANON, NY 14088 (518) 783-4420

Subcontractor Dry Clean
(518) 476-3321


6. Please provide all available information from yours or Client's records including, but not limited to, documentation in connection with any pending or threatened public or private proceedings or litigation with respect to environmental liability, environmental permits and permit applications, underground and above ground tank registration and information (including removal and testing of such tanks), spill information and ground compliance information and programs.

NONE

Page 9 of 9

\PROJECT\RESEARCH\STANDARDS\RESUR.DOC

IV



USGS Topographic Map

Source: USGS Topographic Map
7.5 Minute Quadrangle:
Brookville, NY
Revision Date: 1980
Aerial Photographs Taken: 1952 & 1978


Project Name: Star Plaza
2050 Western Avenue
Guilderland, New York

Date: 10/22/97

Project Number: E092211

Scale: 1:24,000

Contour Interval: 10'



Site Plan - IGA Plaza

Dated January 21, 1972

Project Name: Star Plaza
2050 Western Avenue
Guilderland, New York

Project Number: E092211


Date: 10/22/97



**Historical Aerial Photograph
1952**

Source: NRCS	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E7092211	


ENVIROGENE INC.



Historical USGS Topographic Map

Source: USGS 7.5' Quadrangle Voorheesville, NY Aerial Surveyed: 1925 Edition of: 1927 Reprinted: 1940	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E7092211	Scale: 1:24000 Contour Interval: 10'

ENVIROGENE INC.



Fresh Water Wetlands Map

Source: NRCS	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E7092211	

ENVIROGENE INC.



**Historical Aerial Photograph
1940**

Source: NRCS	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E7092211	

ENVIROGENE INC.



Historical Aerial Photograph
1969

Source: NRCS	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E592211	

[VI]
EDR-RADIUS INC.



Historical Aerial Photograph
1977

Source: NRCS	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E592211	

[VJ]



Historical Aerial Photograph
1986-1987

Source: FSA	Project Name: Star Plaza 2050 Western Avenue Guilderland, New York	Date: 10/22/97
	Project Number: E592211	

[VI]

The EDR-Radius Map
with GeoCheck™

Star Plaza
2050 Western Ave
Guilderland, NY 12084

Inquiry Number: 0202432.1r

October 06, 1997

The Source
For Environmental
Risk Management
Data

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

edr
e data resources, inc.

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Topographic Map	2
GeoCheck Summary	3
Overview Map	5
Detail Map	6
Map Summary - All Sites	7
Map Summary - Sites with higher or the same elevation as the Target Property	8
Map Findings	9
Orphan Summary	18

APPENDICES

GeoCheck Version 2.1	A1
Government Records Searched / Data Currency Tracking Appendix	A7

Thank you for your business.
Please contact EDR at 1-800-252-4050
with any questions or comments.

Disclaimer

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report. No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages. Copyright (c) 1997 by EDR. All rights reserved.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-97. Search distances are per ASTM standard or custom distances requested by the user.

The address of the subject property for which the search was intended is:

2050 WESTERN AVE
GUILDFIELD, NY 10804

No mapped sites were found in EDR's search of available ("geocheck ascertainable") government records either on the subject property or within the ASTM E 1527-97 search radius around the subject property for the following databases:

NPL	National Priority List
Delisted NPL	NPL Delistings
RCRIS-TSDL	Resource Conservation and Recovery Information System
SHWS	Inactive Hazardous Waste Disposal Sites in New York State
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information System
CORRACTS	Corrective Action Registry
SWIFL	Facility Register
AST	Petroleum Bulk Storage (AST)
RAATS	RCRA Administrative Action Tracking System
RCRIS-SQGL	Resource Conservation and Recovery Information System
HMIRS	Hazardous Materials Information Reporting System
PADS	PCB Activity Database System
ERNS	Emergency Response Notification System
FINDS	Facility Index System
TRIS	Toxic Chemical Release Inventory System
NPL Lien	Additional Superfund Liens
TSCA	Toxic Substances Control Act
MLIS	Material Licensing Tracking System
NY Spills	Spills Information Database
ROD	Records Of Decisions
CONSENT	Superfund (CERCLIS) Consent Decrees
Coal Gasl	Former Manufactured gas (Gas) Gasl Sites

Unmapped (orphan) sites are not considered in the foregoing analysis.

Search Results:

Search results for the subject property and the search radius are listed below:

Subject Property:

The subject property was not listed in any of the databases searched by EDR.

T00202432.IR Page 1

T00202432.IR EXECUTIVE SUMMARY 1

EXECUTIVE SUMMARY

Surrounding Properties:

Elevations have been determined from the USGS 1 degree Digital Elevation Model and should be evaluated as relative, not an absolute basis. Relative elevation information between sites of close proximity should be used verbatim. EDR's definition of a site with an elevation equal to the subject property include a tolerance of +/- 10 feet. Sites with an elevation equal to or higher than the subject property have been differentiated below from sites with an elevation lower than the subject property (by more than 10 feet). Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

CERCLIS-INFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund Action or NPL consideration. EPA has removed approximately 25,000 INFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

A review of the CERCLIS-INFRAP list, as provided by EDR, and dated 04-01-1997 has revealed that there is 1 CERCLIS-INFRAP site, within approximately 1 Mile of the subject property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GRIFIN LABS	STATE FARM RD	1/8 - 1/4SSW	5	16

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data comes from the Department of Environmental Conservation's Spills Information Database.

A review of the LUST list, as provided by EDR, and dated 12-31-1996 has revealed that there are 4 LUST sites within approximately 0.5 Miles of the subject property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
CAMPBELL PES MAIN CARE SMYTH RES PATRICIA AV	1 CORNELL AVE 4 PATRICIA AVE	1/8 - 1/4SESE	3	10
GUILDFIELD CENTRAL SCHOOL DIS	STATE FARM RD	1/4 - 1/2E	5	16

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Section of the Resource Conservation and Recovery Act (RCRA). The data comes from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS, OBS, MOSFi) Database.

A review of the UST list, as provided by EDR, and dated 12-31-1996 has revealed that there is 1 UST site, within approximately 0.25 Miles of the subject property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
JIFFY LUBE STORE #309	2057 WESTERN AVENUE	1/8 - 1/4WNW	4	17

EXECUTIVE SUMMARY

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.


A review of the RCRIS-LCG list, as provided by EDR, and dated 04-01-1997 has revealed that there is 1 RCRIS-LCG site, within approximately 0.25 Miles of the subject property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GUILDFIELD CENTRAL SCHOOL DIS	STATE FARM RD	1/8 - 1/4SSW	A1	9

T00202432.IR EXECUTIVE SUMMARY 2

T00202432.IR EXECUTIVE SUMMARY 2


OVERVIEW MAP - 0202432.1r - IVI Environmental



TARGET PROPERTY: Star Plaza
ADDRESS: 2050 Western Ave
CITY/STATE/ZIP: Rutherford NY 12084

CUSTOMER: IVI Environmental
CONTACT: John Fusco
INQUIRY #: 0202432.1r

DETAIL MAP - 0202432.1r - IVI Environmental



TARGET PROPERTY: Star Plaza
ADDRESS: 2050 Western Ave
CITY/STATE/ZIP: Rutherford NY 12084

CUSTOMER: IVI Environmental
CONTACT: John Fusco
INQUIRY #: 0202432.1r

MAP FINDINGS SUMMARY SHOWING ALL SITES

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NPL		1,000	0	0	0	0	NR	0
Delested NPL	TP	NR	NR	NR	NR	NR	NR	0
RCRIS-TSD	0.500	0	0	0	0	NR	NR	0
State Haz. Waste	1,000	0	0	0	0	NR	0	0
CERCLIS	0.500	0	0	0	0	NR	0	0
CERC-NFRAP	1,000	0	0	0	0	NR	0	0
CORPACTS	1,000	0	0	0	0	NR	0	0
State Landfill	0.500	0	0	0	NR	NR	0	0
LUST	0.500	0	0	1	NR	NR	4	4
UST	0.250	0	1	NR	NR	NR	1	1
AST	TP	NR	NR	NR	NR	NR	0	0
RAATS	TP	NR	NR	NR	NR	NR	0	0
RCRIS Sm. Cuan. Gen.	0.250	0	0	NR	NR	NR	0	0
RCRIS Lg. Cuan. Gen.	0.250	0	1	NR	NR	NR	1	1
HMRIS	TP	NR	NR	NR	NR	NR	0	0
PADS	TP	NR	NR	NR	NR	NR	0	0
ERNS	TP	NR	NR	NR	NR	NR	0	0
FINDS	TP	NR	NR	NR	NR	NR	0	0
TRIS	TP	NR	NR	NR	NR	NR	0	0
NPL Lines	TP	NR	NR	NR	NR	NR	0	0
TSCA	TP	NR	NR	NR	NR	NR	0	0
MLTS	TP	NR	NR	NR	NR	NR	0	0
NY Soils	TP	NR	NR	NR	NR	NR	0	0
RDD	1,000	0	0	0	0	NR	0	0
CONSENT	1,000	0	0	0	0	NR	0	0
Coal Gas	1,000	0	0	0	0	NR	0	0

TP = Target Property

NR = Not Requested at this Search Distance

* Sites may be listed in more than one database

MAP FINDINGS SUMMARY SHOWING ONLY SITES HIGHER THAN OR THE SAME ELEVATION AS TP

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NPL		1,000	0	0	0	0	NR	0
Delested NPL	TP	NR	NR	NR	NR	NR	NR	0
ACRIS-TSD	0.500	0	0	0	0	NR	NR	0
State Haz. Waste	1,000	0	0	0	0	0	0	0
CERCLIS	0.500	0	0	0	0	NR	NR	0
CERC-NFRAP	1,000	0	0	0	0	NR	0	0
CORPACTS	1,000	0	0	0	0	NR	0	0
State Landfill	0.500	0	0	0	0	NR	0	0
LUST	0.500	0	1	NR	NR	NR	2	2
UST	0.250	0	1	NR	NR	NR	NR	1
AST	TP	NR	NR	NR	NR	NR	NR	0
RAATS	TP	NR	NR	NR	NR	NR	NR	0
RCRIS Sm. Cuan. Gen.	0.250	0	1	NR	NR	NR	NR	0
RCRIS Lg. Cuan. Gen.	0.250	0	0	NR	NR	NR	NR	0
HMRIS	TP	NR	NR	NR	NR	NR	NR	0
PAOS	TP	NR	NR	NR	NR	NR	NR	0
ERNS	TP	NR	NR	NR	NR	NR	NR	0
FINDS	TP	NR	NR	NR	NR	NR	NR	0
TRIS	TP	NR	NR	NR	NR	NR	NR	0
NPL Lines	TP	NR	NR	NR	NR	NR	NR	0
TSCA	TP	NR	NR	NR	NR	NR	NR	0
MLTS	TP	NR	NR	NR	NR	NR	NR	0
NY Soils	TP	NR	NR	NR	NR	NR	NR	0
RDD	1,000	0	0	0	0	NR	0	0
CONSENT	1,000	0	0	0	0	NR	0	0
Coal Gas	1,000	0	0	0	0	NR	0	0

TP = Target Property

NR = Not Requested at this Search Distance

* Sites may be listed in more than one database

MAP FINDINGS					
Map ID Direction Distance Elevation	Site	Databases:	EPA ID Number	EDR ID Number	
A1 SSW 13-14 Lower	GUILDFIELD CENTRAL SCHOOL DISTRICT STATE FARM RD GUILDFIELD, NY 12084	FINDS LUST	1000273514 NYC100376151		

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

A1
GUILDFIELD CENTRAL SCHOOL DISTRICT
STATE FARM RD
GUILDFIELD, NY 12084

ACRS:
Owner: Not reported
Contact: HAROLD MCCARTHY
(518) 465-5200
Record Date: 07/01/85
Classification: Large Quantity Generator
Used Oil Recycl: N/A
Violation Status: No violations found

LUST:
Facility ID: 8708013
Facility Contact: Not reported
Investigator: SPERBER
Caller Name: Not reported
Caller Phone: Not reported
Notifer Name: Not reported
Notifer Phone: Not reported
Spiller Contact: Not reported
Spiller: GUILDFIELD SCHOOL DIST.
Address: SAME
Not reported
Split Class: Not reported
Split Closed Dt: 08/10/1993
Split Cause: Tank Test Failure
Water Affected: Not reported
Split Notif: Not reported
Split Date: 10/19/1987 17:00
Cleanup Ceased: 01/04/1988
Last Inspection: Not reported
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involved: False
Spill Record Last Update: 08/10/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/22/98
Remark: 10K TANK FAILED TEST @ .27 GPH. TANK C.R. WILL ISOLATE & REPAIR.

A2
SSW
13-14
Lower

LUST:
Facility ID: 8708035
Facility Contact: Not reported

NMC TRANSFORMER RT 155
STATE FARM RD / RT 155
GUILDFIELD, NY

PBS:
Facility ID: 8708035
Facility Type: 4
Facility Contact: Not reported

LUST
S100655398
N/A

Facility ID: 8708035
Facility Type: 4
Facility Contact: Not reported

T00202432.tr Page 3

MAP FINDINGS					
Map ID Direction Distance Elevation	Site	Databases:	EPA ID Number	EDR ID Number	

CAMPBELL RES. MAINCARE (Continued)

Investigation Complete: Not reported
UST Involved: False
Spill Record Last Update: 03/10/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/15/1998
Remark: SMALL QUANTITY ON SIDE OF HOUSE. CLEAN-UP BY MAIN CARE. NO DEC RESPONSE.

4
WW
13-14
Higher

JIFFY LUBE STORE #309
2067 WESTERN AVENUE
GUILDFIELD, NY 12084

PBS UST:
Facility ID: 4-009821
Type: Not reported
Dispenser: (518) 462-9863
Address: JIFFY LUBE
Contact: Not reported
Emergency Contact: THOMAS J. HOFFMAN, JR., 518-869-3218
Facilities Total: 1
Total Tanks: 3
Owner: HOFFMAN DEVELOPMENT CORP
157 CENTRAL AVENUE
ALBANY, NY 12205
518-669-3218
Owner Type: Corporate/Commercial
Owner Status: Not reported
Mailing Address: HOFFMAN DEVELOPMENT CORP
157 CENTRAL AVENUE
NY 12205
(518) 669-3218
ATTN: THOMAS J. HOFFMAN, JR.

Facility Status: Active
Certification: CB231944
Tank Status: In Service
Tank Location: UNDERGROUND
Tank ID: 1
Product Stored: USE-OIL
Tank Material: NONE
Size (Volume): Underground
Tank External: NONE
Pipe Status: NONE
Second Containment: NONE
User Disclaimer: NONE
Owner Print: None
Date Tested: 10/93
Date Closed: Not reported
Sample Type: Not reported

Total Capacity: 4000
Expiration: 08/15/2001

Inspection Date: 10/85
Tank Type: Steel/carbon steel
Pipe Material: NONE
Pipe Type: GALVANIZED STEEL

MAP FINDINGS					
Map ID Direction Distance Elevation	Site	Databases:	EPA ID Number	EDR ID Number	

NMC TRANSFORMER RT 155 (Continued)

Investigation: MCDOUGAL
Case Name: Not reported
Case Owner: Not reported
Notifer Name: Not reported
Notifer Phone: Not reported
Spiller Contact: Not reported
Spiller: MA2438A MOHAWK, NMC
Address: 320 ERIE BLVD
SYRACUSE, NY
Sci Class: Known release with minimal potential to life hazard. DEC Response.
Wiring Responsible Party: Corrective action taken.

Sci Closed Dt: 08/31/1987
Sci Cause: Oil
Water Affected: Not reported
Sci Source: Other Commercial/Industrial
Sci Number: PBS Number: Not reported
Sci Date: 08/31/1987 04:00
Cleaning Ceased: 08/31/1987
Last Inspection: 08/31/1987
Cleaning Meets Standard: True
Recommended Penalty: No Penalty
Sci Lar Case#: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST involvement: False
Spill Record Last Update: 02/06/1997
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/31/1987
Remark: FREE FILL ON PCIE

3
ESE
18-14
Higher

CAMPBELL RES. MAINCARE
1 CORNELL AVE
ALBANY, NY

LUST
S100132455
N/A

LUST:
Facility ID: S801424
Facility Contact: Not reported
Investigator: SLAIN
Caller Name: JACK
Caller Phone: (518) 468-7356
Notifer Name: Not reported
Notifer Phone: Not reported
Spiller Contact: Not reported
Spiller: MAIN CARE
Address: Not reported
Not reported
Sci Class: Not reported
Sci Closed Dt: 05/15/1988
Sci Cause: Tank Overfill
Water Affected: Not reported
Sci Source: Tank Truck
PBS Number: Not reported
Sci Date: 05/16/1988 15:00
Cleaning Ceased: 05/16/1988
Last Inspection: 05/16/1988
Cleaning Meets Standard: True
Recommended Penalty: No Penalty
Sci Lar Case#: Not reported
Enforcement Date: Not reported

T00202432.tr Page 10

MAP FINDINGS					
Map ID Direction Distance Elevation	Site	Databases:	EPA ID Number	EDR ID Number	

JIFFY LUBE STORE #309 (Continued)

Facility ID: 4-009821
Town: Not reported
Telephone: (518) 462-9863
Operator: JIFFY LUBE
Contact: Not reported
Emergency Contact: THOMAS J. HOFFMAN, JR., 518-869-3218
Facility Type: CL
Total Tanks: 3
Owner: HOFFMAN DEVELOPMENT CORP
157 CENTRAL AVENUE
ALBANY, NY 12205
518-669-3218
Owner Type: Corporate/Commercial
Owner Status: Not reported
Mailing Address: HOFFMAN DEVELOPMENT CORP
157 CENTRAL AVENUE
NY 12205
ATTN: THOMAS J. HOFFMAN, JR.

Facility Status: Active
Certification: CB231944
Tank Status: In Service
Tank Location: UNDERGROUND
Tank ID: 1
Product Stored: USE-OIL
Tank Material: Steel/carbon steel
Size (Volume): 1000
Tank Internal: NONE
Pipe Location: Underground
Pipe External: NONE
Pipe External: NONE
Second Containment: NONE
Leak Detection: NONE
Overfill Protection: None
Drain Valve: 10/93
Date Closed: Not reported
Database Type: Not reported

T00202432.tr Page 12

Map ID	Direction	Distance	Elevation	MAP FINDINGS			
				Site	Databases(s)	EPA ID Number	EDB ID Number

JIFFY LUBE STORE #309 (Continued)

U003630403

Facility ID: 4-C2612*
 Town: Not reported
 Telephone: (518) 452-9863
 Owner: JIFFY LUBE
 Contact: Not reported
 Emergency Contact: THOMAS J. HOFFMAN JR., (518) 669-3218
 Facility Type: 21
 Total Tanks: 3
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Owner Type: Corporate/Commercial
 Owner Subtype: Not reported
 Mailing Address: HOFFMAN DEVELOPMENT CORP,
 1757 CENTRAL AVENUE
 NY 12205
 (518) 669-3218
 ATTN: THOMAS J. HOFFMAN JR.
 Facility Status: Active
 Construction: 08/23/1995
 Tank Status: In Service
 Tank Location: UNDERGROUND
 Tank ID: 3
 Product Stored: LUBE OIL
 Tank Internal: NONE
 Pipe Location: Underground
 Tank External: NONE
 Second Containment: NONE
 Tank Containment: NCAB
 Owner Pmt: None
 Date Tested: 10/88
 Date Closed: Not reported
 Database Type: Not reported

CBS Number: Dispersed
 SWS ID: 0130
 Region: Not reported

Ed PMS Num: Not reported

Map ID	Direction	Distance	Elevation	MAP FINDINGS			
				Site	Databases(s)	EPA ID Number	EDB ID Number

JIFFY LUBE STORE #309 (Continued)

U003630405

PBS AST: 4-02621
 Facility ID: 4-02621
 Facility Status: Active
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Tank ID: 5A
 Tank Status: Aboveground On Saddles Under Static Rack Or Cribade
 Tank Location: Above Ground
 Product Stored: LUBE OIL
 Tank Internal: Not reported
 Pipe Location: Painted/Asphalt Coating
 Tank External: NONE
 Pipe Location: Aboveground
 Pipe Internal: NONE
 Pipe External: Painted/Asphalt Coating
 Leak Detection: Other
 Owner Pmt: Product Level Gauge
 Date Tested: Not reported
 Date Closed: Not reported
 Region: ST

Facility ID: 4-02621
 Facility Status: Active
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Tank ID: 5A
 Tank Status: Closed-in Place
 Tank Location: ABOVEGROUND
 Product Stored: EMPTY
 Instal Date: Not reported
 Tank External: NONE
 Tank Containment: Painted/Asphalt Coating
 Pipe Location: None
 Pipe Internal: None
 Pipe External: None
 Leak Detection: None
 Owner Pmt: None
 Date Tested: Not reported
 Date Closed: Not reported
 Region: ST

TC0202432.M Page 13

TC0202432.M Page 14

Map ID	Direction	Distance	Elevation	MAP FINDINGS			
				Site	Databases(s)	EPA ID Number	EDB ID Number

JIFFY LUBE STORE #309 (Continued)

U003630405

Facility ID: 4-02621*
 Facility Status: Active
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Tank ID: 5A
 Tank Status: Closed-in Place
 Tank Location: ABOVEGROUND
 Product Stored: EMPTY
 Instal Date: Not reported
 Tank External: Painted/Asphalt Coating
 Tank Containment: NONE
 Pipe Location: None
 Pipe Internal: NONE
 Pipe External: NONE
 Leak Detection: None
 Owner Pmt: None
 Date Tested: Not reported
 Date Closed: Not reported
 Region: ST

Facility ID: 4-02621
 Facility Status: Active
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Tank ID: 5A
 Tank Status: Closed-in Place
 Tank Location: ABOVEGROUND
 Product Stored: EMPTY
 Instal Date: Not reported
 Tank External: Painted/Asphalt Coating
 Tank Containment: NONE
 Pipe Location: None
 Pipe Internal: None
 Pipe External: None
 Leak Detection: None
 Owner Pmt: None
 Date Tested: Not reported
 Date Closed: Not reported
 Region: ST

Map ID	Direction	Distance	Elevation	MAP FINDINGS			
				Site	Databases(s)	EPA ID Number	EDB ID Number

JIFFY LUBE STORE #309 (Continued)

U003630405

Facility ID: 4-02621*
 Facility Status: Active
 Owner: HOFFMAN DEVELOPMENT CORP
 1757 CENTRAL AVENUE
 ALBANY, NY 12205
 (518) 669-3218
 Tank ID: 5A
 Tank Status: Closed-in Place
 Tank Location: ABOVEGROUND
 Product Stored: EMPTY
 Instal Date: Not reported
 Tank External: Painted/Asphalt Coating
 Tank Containment: NONE
 Pipe Location: None
 Pipe Internal: None
 Pipe External: None
 Leak Detection: None
 Owner Pmt: None
 Date Tested: Not reported
 Date Closed: Not reported
 Region: ST

GRiffin LABS
 STATE FARM RD
 GUILDFIELD, NY 12084

CERCLIS/NPL Classification Data:
 Site Listed: Not reported
 Ownership Status: UNKNOWN
 EPA NPL: Not reported
 CERCLIS/NPL Assessment History:
 Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: SITE INSPECTION
 Assessment: SCREENING
 CERCLIS/NPL Area Name/Risk:
 GRiffin LABS

6	East	SMITH RES PATRICIA AV	LUST	SI0150860
	Higher	1 PATRICIA AVE ALBANY, NY		N/A

FACILITY CONTACT: CHRIS SONGER
 Facility ID: 9416522
 Facility Name: T-CWAS SMITH
 Facility Address: 1 PATRICIA AV
 ALBANY
 Facility Class: Known Release That Requires Client or Site or Hazard: DEC Response
 involving Responsible Party, Corrective action taken.

TC0202432.M Page 15

TC0202432.M Page 16

DETAILED ORPHAN LISTING

DETAILED ORPHAN LISTING

Site	Database(s)	EDB ID Number EPA ID Number
MOBIL S/S #09-352 (Continued)		
Facility ID:	4-13232	CBS Number: Not reported
Town:	Not reported	SWIS ID: 3130
Telephone:	(518) 438-4734	Location: Not reported
Operator:	JOEL FRANK	
Contact:	Not reported	
Emergency Contact:	ENV. HELP DESK, (800) 662-4567	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	6	Old PBS Num.: Not reported
Owner:	MOBIL OIL CORP. 3225 GALLONS RD., SW307 FAIRFAX, VA 22037 (703) 849-6252	
Owner Type:	Corporate/Commercial	Owner Mark: First Owner
Owner Subtype:	Mobile Oil Company	
Mailing Address:	MOBIL OIL CO NDE ENV P.O. BOX 142667 TX 78714 (800) 800-4633 ATTN: NORMA HILL	
Facility Status:	Active	Total Capacity: 6000
Classification:	04181997	Expiration: 03/24/1992
Tank Status:	In Service	
Tank Location:	UNDERGROUND	
Tank ID:	3	Install Date: 12/89
Product Stored:	UNLEADED GASOLINE	Tank Type: Fiberglass reinforced plastic (FRP) Pipe Internal: NONE Pipe External: FIBERGLASS
Tank Internal:	NONE	Pipe Type: FIBERGLASS (FRP)
Pipe Location:	Underground	
Tank External:	FIBERGLASS	
Pipe External:	FIBERGLASS	
Second Containment:	NONE	
Leak Detection:	OTHE	
Overfill Prot:	Catch Basin	Dispenser: Submersible
Date Tested:	06/96	Next Test Date: 06/01
Date Closed:	Not reported	Test Method: GILBARCO PRECISION
Database Type:	Not reported	

Site	Database(s)	EDB ID Number EPA ID Number
MORE S/S #09-352 (Continued)		
Facility ID:	4-13232	CBS Number: Not reported
Town:	Not reported	SWIS ID: 0130
Telephone:	(518) 438-4734	Location: Not reported
Operator:	JOEL FRANK	
Contact:	Not reported	
Emergency Contact:	ENV. HELP DESK, (800) 662-4567	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	6	Old PBS Num.: Not reported
Owner:	MOBIL OIL CORP. 3225 GALLONS RD., SW307 FAIRFAX, VA 22037 (703) 849-6252	
Owner Type:	Corporate/Commercial	Owner Mark: First Owner
Owner Subtype:	Mobile Oil Company	
Mailing Address:	MOBIL OIL CO NDE ENV P.O. BOX 142667 TX 78714 (800) 800-4633 ATTN: NORMA HILL	
Facility Status:	Active	Total Capacity: 550
Classification:	04181997	Expiration: 03/24/1992
Tank Status:	Tank Converted To Non-Regulated Use	
Tank Location:	UNDERGROUND	
Tank ID:	4	Install Date: 12/88
Product Stored:	OTHER	Tank Type: Steel/carbon steel
Tank Internal:	Not reported	Pipe Internal: Not reported
Tank External:	Not reported	Pipe Type: GALVANIZED STEEL
Pipe External:	Not reported	
Second Containment:	NONE	
Leak Detection:	NONE	
Overfill Prot:	Not reported	Dispenser: Submersible
Date Tested:	Not reported	Next Test Date: Not reported
Date Closed:	06/00	Test Method: Not reported
Database Type:	Not reported	

T02202452.tr Page 21

T02202452.tr Page 12

DETAILED ORPHAN LISTING

DETAILED ORPHAN LISTING

Site	Database(s)	EDB ID Number EPA ID Number
MOBIL S/S #09-352 (Continued)		
Facility ID:	4-13232	CBS Number: Not reported
Town:	Not reported	SWIS ID: 3130
Telephone:	(518) 438-4734	Location: Not reported
Operator:	JOEL FRANK	
Contact:	Not reported	
Emergency Contact:	ENV. HELP DESK, (800) 662-4567	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	6	Old PBS Num.: Not reported
Owner:	MOBIL OIL CORP. 3225 GALLONS RD., SW307 FAIRFAX, VA 22037 (703) 849-6252	
Owner Type:	Corporate/Commercial	Owner Mark: First Owner
Owner Subtype:	Mobile Oil Company	
Mailing Address:	MOBIL OIL CO NDE ENV P.O. BOX 142667 TX 78714 (800) 800-4633 ATTN: NORMA HILL	
Facility Status:	Active	Total Capacity: 6000
Classification:	04181997	Expiration: 03/24/1992
Tank Status:	In Service	
Tank Location:	UNDERGROUND	
Tank ID:	5	Install Date: 12/89
Product Stored:	UNLEADED GASOLINE	Tank Type: Fiberglass reinforced plastic (FRP) Pipe Internal: NONE Pipe External: FIBERGLASS (FRP)
Tank Internal:	NONE	
Pipe Location:	Underground	
Tank External:	FIBERGLASS	
Pipe External:	FIBERGLASS	
Second Containment:	NONE	
Leak Detection:	OTHE	
Overfill Prot:	Catch Basin	Dispenser: Submersible
Date Tested:	06/96	Next Test Date: 06/01
Date Closed:	Not reported	Test Method: GILBARCO PRECISION
Database Type:	Not reported	

Site	Database(s)	EDB ID Number EPA ID Number
MOBIL S/S #09-352 (Continued)		
Facility ID:	4-13232	CBS Number: Not reported
Town:	Not reported	SWIS ID: 3130
Telephone:	(518) 438-4734	Location: Not reported
Operator:	JOEL FRANK	
Contact:	Not reported	
Emergency Contact:	ENV. HELP DESK, (800) 662-4567	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	6	Old PBS Num.: Not reported
Owner:	MOBIL OIL CORP. 3225 GALLONS RD., SW307 FAIRFAX, VA 22037 (703) 849-6252	
Owner Type:	Corporate/Commercial	Owner Mark: First Owner
Owner Subtype:	Mobile Oil Company	
Mailing Address:	MOBIL OIL CO NDE ENV P.O. BOX 142667 TX 78714 (800) 800-4633 ATTN: NORMA HILL	
Facility Status:	Active	Total Capacity: 6000
Classification:	04181997	Expiration: 03/24/1992
Tank Status:	In Service	
Tank Location:	UNDERGROUND	
Tank ID:	8	Install Date: 12/89
Product Stored:	UNLEADED GASOLINE	Tank Type: Fiberglass reinforced plastic (FRP) Pipe Internal: NONE Pipe External: FIBERGLASS (FRP)
Tank Internal:	NONE	
Pipe Location:	Underground	
Tank External:	FIBERGLASS	
Pipe External:	FIBERGLASS	
Second Containment:	NONE	
Leak Detection:	OTHE	
Overfill Prot:	Catch Basin	Dispenser: Submersible
Date Tested:	06/96	Next Test Date: 06/01
Date Closed:	Not reported	Test Method: GILBARCO PRECISION
Database Type:	Not reported	

MOBIL OIL CORP S/S #09-352 1181 WESTERN AVE ALBANY, NY 12203	RCRIS: Owner: MOBIL OIL CORP (703) 849-3220 Contact: ROSEANN PAYAH (703) 849-3220 Record Date: 06/10/91 Classification: Small Quantity Generator	RCRIS-SOG FINDS LUST 1000553123 NY0986953359
--	--	--

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
MOBIL OIL CORP 55-4652 (Continued)		1000033123	
Used Oil Recyc. No			
Violation Status: No violations found			
LUST:			
Facility ID: 9107351	Region of Spill: 4		
Facility Contact: Not reported	Facility Type: Not reported		
Investigator: WTD-SPERBECK	Spill Type: Facility		
Caller Name: BOB GROCK	Caller Agency: ANDERSON EQ		
Caller Phone: (518) 463-2100	Caller Extension: Not reported		
Notifier Name: Not reported	Notifier Agency: Not reported		
Notifier Phone: Not reported	Notifier Extension: Not reported		
Spiller Contact: Not reported	Spiller Phone: (518) 463-4749		
Spiller: MOBIL			
Address: SAME			
Spill Class: Known release that creates potential for fire or hazard. (Minimal Occurrence)			
Spill Closed Dt: 01/14/1993	Resource Affected: On Land		
Spill Cause: Tank Test Failure	Spill Source: Gas Station		
Water Affected: GROUNDWATER	PBS Number: Not reported		
Spill Notifier: Tank Tester	Reported to Dept: 102201991-1743		
Spill Date: 10/22/1991-1745			
Cleanup Caused: 95/3/17/1992			
Last Inspection: Not reported			
Cleanup Meets Standard: True			
Recommended Penalty: No Penalty			
Spiller Cleanup Date: Not reported			
Enforcement Date: Not reported			
Investigation Complete: Not reported			
UST Involvement: True			
Spill Record Last Update: 10/25/1993			
Corrective Action Plan Submitted: Not reported			
Date Spill Entered in Computer Data File: 10/25/1993			
Remark: 2SK UGT FAILED PETROTITE 4 - 3023PM (MANL) 10/29-PASSED RETEST, AWAITING RESULTS WTD ON SITE, PIT OPEN, NO OODH, PASSING RESULTS RECEIVED			

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GETTY 1229 WESTERN AV (Continued)			SI00343955
Resource Arrestd: On Land			
Soil Source: Other Commercial/Industrial			
PBS Number: Not reported			
Reported to Dept: 09/03/1992 14:45			
Cleanup Caused: 2/1/91-1994			
Last Inspection: Not reported			
Cleanup Meets Standard: True			
Recommended Penalty: No Penalty			
Spiller Cleanup Date: Not reported			
Enforcement Date: Not reported			
Investigation Complete: Not reported			
UST Involvement: True			
Spill Record Last Update: 07/15/1995			
Corrective Action Plan Submitted: Not reported			
Date Spill Entered in Computer Data File: 09/03/1992			
Remark: LINE TEST FAILED, SHUT DOWN LINE NO ENVIRONMENTAL PROBLEM FOUND.			

Site	Database(s)	EDR ID Number	EPA ID Number
GETTY 1229 WESTERN AV	LUST	S100433956	N/A
1229 WESTERN AVE			
ALBANY, NY			
LUST:			
Facility ID: 9226371	Region of Spill: 4		
Facility Contact: Not reported	Facility Type: Not reported		
Investigator: SPERBECK/WTC	Spill Type: LUST		
Caller Name: BOB GROCK	Caller Agency: ANDERSON EQ		
Caller Phone: (518) 463-2100	Caller Extension: Not reported		
Notifier Name: Not reported	Notifier Agency: Not reported		
Notifier Phone: Not reported	Notifier Extension: Not reported		
Spiller Contact: Not reported	Spiller Phone: (518) 463-2752		
Spiller: GETTY			
Address: Not reported			
Spill Class: Known release that creates potential for fire or hazard. DEC Response			
Spill Closed Dt: 01/26/1994	Willing Responsible Party: Corrective action taken.		

TC0202432.tr Page 25

TC0202432.tr Page 25

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
NEW YORK POWER POOL (NIMO) (Continued)		U003676372	
FSS UST:			
Facility ID: 4462470	CBS Number: Not reported		
Town: Not reported	SWIS ID: 3130		
Telephone: (518) 566-8000	Location: Not reported		
Operator: NIAGARA MCHAWK POWER CORP			
Contact: Not reported			
Emergency Contact: MIKE ABBOYIT, (518) 423-3628			
Facility Type: UTILITY			
Total Tanks: 2	Oic PBS Num: Not reported		
Owner: NEW YORK POWER POOL			
3890 CARMAN RD			
SCHEECTADY, NY 12303			
(518) 381-2201			
Owner Type: Corporate/Commercial	Owner Mkt: First Owner		
Owner Subtype: Not reported			
Mailing Address: NIAGARA MCHAWK POWER CORPORATION			
300 ERIE BOULEVARD WEST			
NY 12322			
(518) 455-3490			
Facility Status: Active	Tank Capacity: 5000		
Completion: 03/21/1994	Establish: 02/15/1994		
Tank Status: In Service			
Tank Location: UNDERGROUND			
Tank ID: EG1	Initial Date: 12/90		
Product Sized: DIESEL	Tank Type: Fiberglass reinforced plastic (FRP)		
Tank Internal: NONE	Pipe Internal: NONE		
Pipe location: Underground	Pipe Type: FIBERGLASS (FRP)		
Tank External: NONE			
Pipe External: NONE			
Second Containment: NONE			
Leak Detection: IN-TANK SYSTEM			
Overfill Prot: High Level Alarm	Dispenser: Suction		
Date Tested: Not reported	Next Test Date: N/T R		
Date Closed: Not reported	Test Method: Not reported		
Database Type: Not reported			

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
NEW YORK POWER POOL (NIMO) (Continued)		U003676372	
Facility ID: 4462473			
Town: Not reported	SWIS ID: 0130		
Telephone: (518) 356-9300	Location: Not reported		
Operator: NIAGARA MCHAWK POWER CORP.			
Contact: Not reported			
Emergency Contact: MIKE ABBOYIT, (518) 423-3628			
Facility Type: UTILITY			
Total Tanks: 2	Old PBS Num: Not reported		
Owner: NEW YORK POWER POOL			
3890 CARMAN RD			
SCHEECTADY, NY 12303			
(518) 381-2201			
Owner Type: Corporate/Commercial	Owner Mkt: First Owner		
Owner Subtype: Not reported			
Mailing Address: NIAGARA MCHAWK POWER CORPORATION			
300 ERIE BOULEVARD WEST			
NY 12322			
(518) 423-3430			
ATTN: RICHARD A. SCHULMAN			
Facility Status: Active	Total Capacity: 5000		
Completion: 03/21/1994	Expiration: 12/15/1999		
Tank Status: In Service			
Tank Location: UNDERGROUND			
Tank ID: EG2	Install Date: 10/90		
Product Sized: DIESEL	Tank Type: Fiberglass reinforced plastic (FRP)		
Tank Internal: NONE	Pipe Internal: NONE		
Pipe Location: Above ground	Pipe External: NONE		
Tank External: NONE	Pipe External: NONE		
Pipe External: NONE	Second Containment: NONE		
Leak Detection: IN-TANK SYSTEM			
Overfill Prot: High Level Alarm	Dispenser: Suction		
Date Tested: Not reported	Next Test Date: N/T R		
Date Closed: Not reported	Test Method: Not reported		
Database Type: Not reported			

TC0202432.tr Page 25

TC0202432.tr Page 25

DETAILED ORPHAN LISTING								DETAILED ORPHAN LISTING							
Site	Database(s)	SDR ID Number	EPA ID Number	Site	Database(s)	SDR ID Number	EPA ID Number								
MAIN BROTHERS OIL CO INC BULK (Continued)								MAIN BROTHERS OIL CO INC BULK (Continued)							
PBS#151								PBS#151							
Facility ID:	4-152442	OBS Number:	Not reported	Facility ID:	4-152442	OBS Number:	Not reported	Facility ID:	4-152442	OBS Number:	Not reported	Facility ID:	4-152442	OBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130	Town:	Not reported	SWIS ID:	Not reported	Town:	Not reported	SWIS ID:	Not reported	Town:	Not reported	SWIS ID:	Not reported
Telephone:	(518) 438-7856	Location:	Not reported	Telephone:	(518) 438-7856	Location:	Not reported	Telephone:	(518) 438-7856	Location:	Not reported	Telephone:	(518) 438-7856	Location:	Not reported
Operator:	MAIN BROTHERS OIL CO INC			Operator:	MAIN BROTHERS OIL CO INC			Operator:	MAIN BROTHERS OIL CO INC			Operator:	MAIN BROTHERS OIL CO INC		
Contact:	Not reported			Contact:	Not reported			Contact:	Not reported			Contact:	Not reported		
Emergency Contact:	MAIN BROTHERS OIL CO INC, (518) 438-7856			Emergency Contact:	MAIN BROTHERS OIL CO INC, (518) 438-7856			Emergency Contact:	MAIN BROTHERS OIL CO INC, (518) 438-7856			Emergency Contact:	MAIN BROTHERS OIL CO INC, (518) 438-7856		
Facility Type:	Not reported			Facility Type:	Not reported			Facility Type:	Not reported			Facility Type:	Not reported		
Total Tanks:	1	OIC PBS# Num:	Not reported	Total Tanks:	1	OIC PBS# Num:	Not reported	Total Tanks:	1	OIC PBS# Num:	Not reported	Total Tanks:	1	OIC PBS# Num:	Not reported
Owner:	MAIN BROTHERS OIL CO INC PO BOX 11029 ALBANY, NY 12211 (518) 438-7856			Owner:	MAIN BROTHERS OIL CO INC PO BOX 11029 ALBANY, NY 12211 (518) 438-7856			Owner:	MAIN BROTHERS OIL CO INC PO BOX 11029 ALBANY, NY 12211 (518) 438-7856			Owner:	MAIN BROTHERS OIL CO INC PO BOX 11029 ALBANY, NY 12211 (518) 438-7856		
Owner Type:	Not reported	Owner Mark:	First Owner	Owner Type:	Not reported	Owner Mark:	First Owner	Owner Type:	Not reported	Owner Mark:	First Owner	Owner Type:	Not reported	Owner Mark:	First Owner
Owner Subtype:	Not reported			Owner Subtype:	Not reported			Owner Subtype:	Not reported			Owner Subtype:	Not reported		
Mailing Address:	MAIN BROTHERS OIL CO INC PO BOX 11029 NY 12211 (518) 438-7856			Mailing Address:	MAIN BROTHERS OIL CO INC PO BOX 11029 NY 12211 (518) 438-7856			Mailing Address:	MAIN BROTHERS OIL CO INC PO BOX 11029 NY 12211 (518) 438-7856			Mailing Address:	MAIN BROTHERS OIL CO INC PO BOX 11029 NY 12211 (518) 438-7856		
Facility Status:	Inactive	Total Capacity:	15000	Facility Status:	Closed Before April 1, 1991	Total Capacity:	15000	Facility Status:	Closed Before April 1, 1991	Total Capacity:	15000	Facility Status:	Closed Before April 1, 1991	Total Capacity:	15000
Classification:	05070-987	Exclusion:	05-07-1992	Classification:	05070-987	Exclusion:	05-07-1992	Classification:	05070-987	Exclusion:	05-07-1992	Classification:	05070-987	Exclusion:	05-07-1992
Tank Status:	Closed Before April 1, 1991			Tank Status:	UNDERGROUND			Tank Status:	UNDERGROUND			Tank Status:	UNDERGROUND		
Tank Location:	031	Install Date:	20/09	Tank Location:	031	Install Date:	20/09	Tank Location:	031	Install Date:	20/09	Tank Location:	031	Install Date:	20/09
Tank ID:	031	Tank Type:	Steel/carbon steel	Tank ID:	031	Tank Type:	Steel/carbon steel	Tank ID:	031	Tank Type:	Steel/carbon steel	Tank ID:	031	Tank Type:	Steel/carbon steel
Product Stored:	NOS 1,2,3 & FUEL OIL	Pipe Internal:	Not reported	Product Stored:	NOS 1,2,3 & FUEL OIL	Pipe Internal:	Not reported	Product Stored:	KEROSINE	Pipe Internal:	Not reported	Product Stored:	KEROSINE	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	GALVANIZED STEEL	Pipe Location:	Not reported	Pipe Type:	GALVANIZED STEEL	Pipe Location:	Not reported	Pipe Type:	GALVANIZED STEEL	Pipe Location:	Not reported	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported	Pipe External:	Not reported	Tank External:	Not reported	Pipe External:	Not reported	Tank External:	Not reported	Pipe External:	Not reported	Tank External:	Not reported	Pipe External:	Not reported
Pipe External:	Not reported			Pipe External:	Not reported			Pipe External:	Not reported			Pipe External:	Not reported		
Second Containment:	None			Second Containment:	None			Second Containment:	None			Second Containment:	None		
Leak Detection:	None			Leak Detection:	None			Leak Detection:	None			Leak Detection:	None		
Overfill Prot:	Product Level Gauge	Dispenser:	Not reported	Overfill Prot:	Product Level Gauge	Dispenser:	Not reported	Overfill Prot:	Product Level Gauge	Dispenser:	Not reported	Overfill Prot:	Product Level Gauge	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported	Date Tested:	Not reported	Next Test Date:	Not reported	Date Closed:	06-09	Test Method:	Not reported	Date Closed:	06-09	Test Method:	Not reported
Date Closed:	06-09			Date Closed:	06-09			Date Closed:	06-09			Date Closed:	06-09		
Database Type:	Not reported			Database Type:	Not reported			Database Type:	Not reported			Database Type:	Not reported		
GUIDERLAND ELEMENTARY SCH RT 20 ELEMENTARY SCHOOL GUILDFIELD, NY								GUIDERLAND ELEMENTARY SCH RT 20 ELEMENTARY SCHOOL GUILDFIELD, NY							
LUST:				LUST:				LUST:				LUST:			
Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4
Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported
Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN
Caller Name:	CAR 5 MUNIC	Caller Agency:	Not reported	Caller Name:	CAR 5 MUNIC	Caller Agency:	Not reported	Caller Name:	CAR 5 MUNIC	Caller Agency:	Not reported	Caller Name:	CAR 5 MUNIC	Caller Agency:	Not reported
Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700
Address:	RT 20			Address:	RT 20			Address:	RT 20			Address:	RT 20		
Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.		
Spill Closed Dt:	06-09-1993			Spill Closed Dt:	06-09-1993			Spill Closed Dt:	06-09-1993			Spill Closed Dt:	06-09-1993		
Last Inspection:	Not reported			Last Inspection:	Not reported			Last Inspection:	Not reported			Last Inspection:	Not reported		
Cleanup Meets Standard:	True			Cleanup Meets Standard:	True			Cleanup Meets Standard:	True			Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported			Enforcement Date:	Not reported			Enforcement Date:	Not reported			Enforcement Date:	Not reported		
Investigation Complete:	Not reported			Investigation Complete:	Not reported			Investigation Complete:	Not reported			Investigation Complete:	Not reported		
UST involvement:	True			UST involvement:	True			UST involvement:	True			UST involvement:	True		
Spill Record Last Update:	11-10-1994			Spill Record Last Update:	11-10-1994			Spill Record Last Update:	11-10-1994			Spill Record Last Update:	11-10-1994		
Corrective Action Plan Submitted:	Not reported			Corrective Action Plan Submitted:	Not reported			Corrective Action Plan Submitted:	Not reported			Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	09-12-1986			Date Spill Entered in Computer Data File:	09-12-1986			Date Spill Entered in Computer Data File:	09-12-1986			Date Spill Entered in Computer Data File:	09-12-1986		
Remark:	OTHER SPILL LOCATION RT 20 QUANTITY SPILLED 1,205 GA - PER UPWILL RETEST IN SPRINGS CULDNT GET CIRCULATION SEE 9003805,9003710,3117833 ,9003712,90034620,90034560,9004709,9004700,9005125,9009361,PL			Remark:	OTHER SPILL LOCATION RT 20 QUANTITY SPILLED 1,205 GA - PER UPWILL RETEST IN SPRINGS CULDNT GET CIRCULATION SEE 9003805,9003710,3117833 ,9003712,90034620,90034560,9004709,9004700,9005125,9009361,PL			Remark:	OTHER SPILL LOCATION RT 20 QUANTITY SPILLED 1,205 GA - PER UPWILL RETEST IN SPRINGS CULDNT GET CIRCULATION SEE 9003805,9003710,3117833 ,9003712,90034620,90034560,9004709,9004700,9005125,9009361,PL			Remark:	OTHER SPILL LOCATION RT 20 QUANTITY SPILLED 1,205 GA - PER UPWILL RETEST IN SPRINGS CULDNT GET CIRCULATION SEE 9003805,9003710,3117833 ,9003712,90034620,90034560,9004709,9004700,9005125,9009361,PL		
STEWARTS RT 20 & 146 (Continued)								STEWARTS RT 20 & 146 (Continued)							
LUST:				LUST:				LUST:				LUST:			
Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4	Facility ID:	800493	Region of Spill:	4
Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported	Facility Contact:	Not reported	Facility Type:	Not reported
Investigation:	MICCLLOUCH	Investigator:	BLAN	Investigation:	MICCLLOUCH	Investigator:	BLAN	Investigation:	MICCLLOUCH	Investigator:	BLAN	Investigation:	MICCLLOUCH	Investigator:	BLAN
Caller Name:	ED DEMARCO	Caller Agency:	Not reported	Caller Name:	ED DEMARCO	Caller Agency:	Not reported	Caller Name:	ED DEMARCO	Caller Agency:	Not reported	Caller Name:	ED DEMARCO	Caller Agency:	Not reported
Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported	Caller Phone:	(518) 587-5356	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700	Spiller Contact:	Not reported	Spiller Phone:	(518) 587-5700
Address:	RT 20 & RT 146			Address:	RT 20 & RT 146			Address:	RT 20 & RT 146			Address:	RT 20 & RT 146		
Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.			Spill Class:	Known release that creates potential for fire or hazard.		
Spill Closed Dt:	09-27-92*			Spill Closed Dt:	09-27-92*			Spill Closed Dt:	09-27-92*			Spill Closed Dt:	09-27-92*		
Last Inspection:	Not reported			Last Inspection:	Not reported			Last Inspection:	Not reported			Last Inspection:	Not reported		
Cleanup Meets Standard:	True			Cleanup Meets Standard:	True			Cleanup Meets Standard:	True			Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty			Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported			Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported			Enforcement Date:	Not reported			Enforcement Date:	Not reported			Enforcement Date:	Not reported		
Investigation Complete:	Not reported			Investigation Complete:	Not reported			Investigation Complete:	Not reported			Investigation Complete:	Not reported		
UST involvement:	True			UST involvement:	True			UST involvement:	True			UST involvement:	True		
Spill Record Last Update:	10-21-1992			Spill Record Last Update:	10-21-1992			Spill Record Last Update:	10-21-1992			Spill Record Last Update:	10-21-1992		
STEWARTS RT 20 & 146								STEWARTS RT 20 & 146							
LUST:				LUST:				LUST:				LUST:			
Facility ID:	810041	Region of Spill:	4	Facility ID:	810041	Region of Spill:	4	Facility ID:	810041	Region of Spill:	4	Facility ID:	810041	Region of Spill:	4
Facility Contact:	Not reported	Facility Type:	Facility	Facility Contact:	Not reported	Facility Type:	Facility	Facility Contact:	Not reported	Facility Type:	Facility	Facility Contact:	Not reported	Facility Type:	Facility
Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN	Investigation:	BLAN	Investigator:	BLAN
Caller Name:	NOTIFICATION	Caller Agency:	Not reported	Caller Name:	NOTIFICATION	Caller Agency:	Not reported	Caller Name:	NOTIFICATION	Caller Agency:	Not reported	Caller Name:	NOTIFICATION	Caller Agency:	Not reported
Caller Phone:	(518) 438-7856	Caller Extension:	Not reported	Caller Phone:	(518) 438-7856	Caller Extension:	Not reported	Caller Phone:	(518) 438-7856	Caller Extension:	Not reported	Caller Phone:	(518) 438-7856	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported	Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported	Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(518) 438-78												

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
STEWARTS RT 20 & RT 4 (Continued)		S100134817	

Spiller: CARMAN TRUCKING & STEWART
Address: 1 ALBANY DR.
ALBANY, NY
Spill Class: Not reported
Spill Closed Dt: 10/17/1987
Spill Cause: Tank Overfill
Water Affected: Not reported
Water Notifier: Respirable Party
Spill Date: 10/17/1987 18:00
Cleanup Ceased: 10/17/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/30/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered in Computer Data File: 10/22/1987
Remark: TRUCK OVERFILLED TANK @ STEWARTS. ED ON SCENE. FOAMED SPILL. CLEANED COMPLETE BY 2300 HRS.

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
WESTMERE ELEMENTARY RT 20 (Continued)		S100560512	

Spiller: LUST
Address: 25 RENDEZ RO
COLONIE, NY
Soil Class: Not reported
Soil Closed Dt: 1/1/19/1987
Soil Cause: Tank Failure
Water Affected: DEC
PBS Number: Not reported
Spill Date: 1/1/19/1987 12:00
Cleanup Ceased: 1/1/19/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 03/21/1985
Corrective Action Plan Submitted: Not reported
Date Spill Entered in Computer Data File: 11/29/1987
Remark: MCDONALD TALKED TO WORKER ON SCENE - WILL HAUL SOIL TO ALBANY (C) LANDFILL. WASTE HAULERS PERMIT ISSUED TO CEDAR HILLS (ONE LOAD). NO FINAL INSPECTION.

WESTMERE ELEMENTARY RT 20 LUST S100560512 N/A

Spiller:	Facility ID:	Region of Spill:	Facility Name:	Facility Type:	Spill Type:	Resource Affected:	Spill Source:	PBS Number:	Spill Date:	Reported to Dept:
CEDAR HILL	9304653	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987
GUILDERLAND, NY										
LUST										
CEDAR HILL	9307157	4	CHRISTENSEN	NOT REPORTED	UST	On Land	Other Non Commercial/Industrial	Not reported	1/1/19/1987	1/1/19/1987

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
GUILDFIELD SERVICE AREA (Continued)		
Facility ID:	A-141305	CBS Number: Not reported
Town:	Not reported	SWIS ID: 0130
Telephone:	(518) 456-0220	Location: Not reported
Operator:	KING FUELS	
Contact:	Not reported	
Emergency Contact:	SENIOR DISPATCH, (800) 342-2213	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	11	Old PBS Num.: Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700	
Owner Type:	State Government	Owner Mark: First Owner
Owner Subtype:	NYS Thruway Authority	
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3008	
Facility Status:	Active	Total Capacity: 10000
Certification:	03/05/1997	Expiration: 03/10/1992
Tank Status:	Closed/Removed	
Tank Location:	UNDERGROUND	
Tank ID:	5	Install Date: 12/54
Product Stored:	UNLEADED GASOLINE	Tank Type: Steel/carbon steel
Tank Internal:	EPOXY LINER	Pipe Internal: Not reported
Pipe Location:	Not reported	Pipe Type: GALVANIZED STEEL
Tank External:	Not reported	
Pipe External:	Not reported	
Second Containment:	NONE	
Leak Detection:	GROUNDWATER WELL	
Overfill Prot:	Not reported	
Date Tested:	03/05	Dispenser: Submersible
Date Closed:	04/22	Next Test Date: Not reported
Database Type:	Not reported	Test Method: TANKTOLOGY (VACUTEC)

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
GUILDFIELD SERVICE AREA (Continued)		
Facility ID:	A-141305	CBS Number: Not reported
Town:	Not reported	SWIS ID: 0130
Telephone:	(518) 356-3220	Location: Not reported
Operator:	KING FUELS	
Contact:	Not reported	
Emergency Contact:	SENIOR DISPATCH, (800) 342-2213	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	11	Old PBS Num.: Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700	
Owner Type:	State Government	Owner Mark: First Owner
Owner Subtype:	NYS Thruway Authority	
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3008	
Facility Status:	Active	Total Capacity: 10000
Certification:	03/05/1997	Expiration: 03/10/1992
Tank Status:	Closed/Removed	
Tank Location:	UNDERGROUND	
Tank ID:	4	Install Date: 12/54
Product Stored:	UNLEADED GASOLINE	Tank Type: Steel/carbon steel
Tank Internal:	EPOXY LINER	Pipe Internal: Not reported
Pipe Location:	Not reported	Pipe Type: Not reported
Tank External:	Not reported	Pipe External: Not reported
Second Containment:	NONE	
Leak Detection:	GROUNDWATER WELL	
Overfill Prot:	Not reported	
Date Tested:	03/05	Dispenser: Submersible
Date Closed:	04/22	Next Test Date: Not reported
Database Type:	Not reported	Test Method: TANKTOLOGY (VACUTEC)

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
GUILDFIELD SERVICE AREA (Continued)		
Facility ID:	A-141305	CBS Number: Not reported
Town:	Not reported	SWIS ID: 0130
Telephone:	(518) 356-0220	Location: Not reported
Operator:	KING FUELS	
Contact:	Not reported	
Emergency Contact:	SENIOR DISPATCH, (800) 342-2213	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	11	Old PBS Num.: Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700	
Owner Type:	State Government	Owner Mark: First Owner
Owner Subtype:	NYS Thruway Authority	
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3008	
Facility Status:	Active	Total Capacity: 10000
Certification:	03/05/1997	Expiration: 03/10/1992
Tank Status:	Closed/Removed	
Tank Location:	UNDERGROUND	
Tank ID:	5	Install Date: 12/54
Product Stored:	UNLEADED GASOLINE	Tank Type: Steel/carbon steel
Tank Internal:	EPOXY LINER	Pipe Internal: Not reported
Appl. Information:	Not reported	Pipe Type: GALVANIZED STEEL
Tank External:	Not reported	
Pipe External:	Not reported	
Second Containment:	NONE	
Leak Detection:	GROUNDWATER WELL	
Overfill Prot:	Not reported	
Date Tested:	Not reported	Dispenser: Submersible
Date Closed:	04/22	Next Test Date: Not reported
Database Type:	Not reported	Test Method: TANKTOLOGY (VACUTEC)

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
GUILDFIELD SERVICE AREA (Continued)		
Facility ID:	A-141305	CBS Number: Not reported
Town:	Not reported	SWIS ID: 0130
Telephone:	(518) 356-3220	Location: Not reported
Operator:	KING FUELS	
Contact:	Not reported	
Emergency Contact:	SENIOR DISPATCH, (800) 342-2213	
Facility Type:	RETAIL GASOLINE SALES	
Total Tanks:	11	Old PBS Num.: Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700	
Owner Type:	State Government	Owner Mark: First Owner
Owner Subtype:	NYS Thruway Authority	
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3008	
Facility Status:	Active	Total Capacity: 550
Certification:	03/05/1997	Expiration: 03/10/1992
Tank Status:	Closed/Removed	
Tank Location:	UNDERGROUND	
Tank ID:	5	Install Date: 12/54
Product Stored:	OTHER	Tank Type: Steel/carbon steel
Tank Internal:	Not reported	Pipe Internal: Not reported
Pipe Location:	Not reported	Pipe Type: GALVANIZED STEEL
Tank External:	Not reported	
Pipe External:	Not reported	
Second Containment:	NONE	
Leak Detection:	GROUNDWATER WELL	
Overfill Prot:	Not reported	
Date Tested:	03/05	Dispenser: Gravity
Date Closed:	04/22	Next Test Date: Not reported
Database Type:	Not reported	Test Method: TANKTOLOGY (VACUTEC)

DETAILED ORPHAN LISTING

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GUILDFIELD SERVICE AREA (Continued)			
Facility ID:	4-141305	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-2220	Location:	Not reported
Operator:	KING FUELS		
Contact:	Not reported		
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	11		
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700	Old PBS Num:	Not reported
Owner Type:	State Government	Owner Mark:	First Owner
Owner Subtype:	NYS Thruway Authority		
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055		
Facility Status:	Active	Total Capacity:	10000
Classification:	03/05/1997	Expiration:	03/10/2002
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	1	Install Date:	04/92
Product Stored:	UNLEADED GASOLINE	Tank Type:	FIBERGLASS reinforced plastic (FRP)
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overall Prot.	Automatic Shut-Off	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	N.T.R.
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

Site	Database(s)
GUILDFIELD SERVICE AREA (Continued)	
Facility ID:	4-141305
Town:	Not reported
Telephone:	(518) 356-2220
Operator:	KING FUELS
Contact:	Not reported
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233
Facility Type:	RETAIL GASOLINE SALES
Total Tanks:	11
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700
Owner Type:	State Government
Owner Subtype:	NYS Thruway Authority
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055
Facility Status:	Active
Classification:	03/05/1997
Tank Status:	In Service
Tank Location:	UNDERGROUND
Tank ID:	2
Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE
Pipe Location:	Underground
Tank External:	NONE
Pipe External:	NONE
Second Containment:	DOUBLED-WALLED TANK
Leak Detection:	INTERSTITIAL MONITORING
Overall Prot.	Automatic Shut-Off
Date Tested:	Not reported
Date Closed:	Not reported
Database Type:	Not reported

EDR ID Number
EPA ID Number

UO93178687

Site	Database(s)	EDR ID Number	EPA ID Number
GUILDFIELD SERVICE AREA (Continued)			
Facility ID:	4-141305	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-2220	Location:	Not reported
Operator:	KING FUELS		
Contact:	Not reported		
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	11	Old PBS Num:	Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700		
Owner Type:	State Government	Owner Mark:	First Owner
Owner Subtype:	NYS Thruway Authority		
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055		
Facility Status:	Active	Total Capacity:	10000
Classification:	03/05/1997	Expiration:	03/27/2002
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	3	Install Date:	04/92
Product Stored:	UNLEADED GASOLINE	Tank Type:	FIBERGLASS reinforced plastic (FRP)
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overall Prot.	Automatic Shut-Off	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	N.T.R.
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

EDR ID Number
EPA ID Number

UO93178687

DETAILED ORPHAN LISTING

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GUILDFIELD SERVICE AREA (Continued)			
Facility ID:	4-141305	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-2220	Location:	Not reported
Operator:	KING FUELS		
Contact:	Not reported		
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	11	Old PBS Num:	Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700		
Owner Type:	State Government	Owner Mark:	First Owner
Owner Subtype:	NYS Thruway Authority		
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055		
Facility Status:	Active	Total Capacity:	10000
Classification:	03/05/1997	Expiration:	03/10/2002
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	4	Install Date:	04/92
Product Stored:	UNLEADED GASOLINE	Tank Type:	FIBERGLASS reinforced plastic (FRP)
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overall Prot.	Automatic Shut-Off	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	N.T.R.
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

Site	Database(s)
GUILDFIELD SERVICE AREA (Continued)	
Facility ID:	4-141305
Town:	Not reported
Telephone:	(518) 356-2220
Operator:	KING FUELS
Contact:	Not reported
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233
Facility Type:	RETAIL GASOLINE SALES
Total Tanks:	11
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700
Owner Type:	State Government
Owner Subtype:	NYS Thruway Authority
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055
Facility Status:	Active
Classification:	03/05/1997
Tank Status:	In Service
Tank Location:	UNDERGROUND
Tank ID:	4
Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE
Pipe Location:	Underground
Tank External:	NONE
Pipe External:	NONE
Second Containment:	DOUBLED-WALLED TANK
Leak Detection:	INTERSTITIAL MONITORING
Overall Prot.	Automatic Shut-Off
Date Tested:	Not reported
Date Closed:	Not reported
Database Type:	Not reported

EDR ID Number
EPA ID Number

UO93178687

Site	Database(s)	EDR ID Number	EPA ID Number
GUILDFIELD SERVICE AREA (Continued)			
Facility ID:	4-141305	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-2220	Location:	Not reported
Operator:	KING FUELS		
Contact:	Not reported		
Emergency Contact:	SENIOR DISPATCH, (500) 842-2233		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	11	Old PBS Num:	Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 426-2700		
Owner Type:	State Government	Owner Mark:	First Owner
Owner Subtype:	NYS Thruway Authority		
Mailing Address:	NYS THRUWAY AUTHORITY PO BOX 189 NY 12209 (518) 426-3055		
Facility Status:	Active	Total Capacity:	10000
Classification:	03/05/1997	Expiration:	03/27/2002
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	5	Install Date:	04/92
Product Stored:	UNLEADED GASOLINE	Tank Type:	FIBERGLASS reinforced plastic (FRP)
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overall Prot.	Automatic Shut-Off	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	N.T.R.
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

EDR ID Number
EPA ID Number

UO93178687

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GUILDERLAND SERVICE AREA - (Continued)			
JCS0178597			
Facility ID:	4-141325	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-0295	Location:	Not reported
Operator:	KING FUELS		
Contact:	Not reported		
Emergency Contact:	SENIOR DISPATCH, (302) 842-2733		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	13	Old PBS Num:	Not reported
Owner:	NYS THRUWAY AUTHORITY PO BOX 189 ALBANY, NY 12209 (518) 436-0720		
Owner Type:	State Government	Owner Mark:	First Owner
Owner Subtype:	NYS Thruway Authority		
Mailing Address:	NYS THRUWAY AUTH-OP NY PO BOX 189 NY 12209 (518) 436-2003		
ATTN: ENVIRONMENTAL SPECIALIST			
Facility Status:	Active	Total Capacity:	10000
Certification:	03051597	Expiration:	03/10/2002
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	5	Install Date:	04-92
Product Stored:	DIESEL	Tank Type:	Fiberglass reinforced plastic (FRP)
Tank Internal:	None	Pipe Internal:	NON-E
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	None		
Pipe External:	None		
Second Containment:	COUPLED/WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overall Pict:	Automated Shut-Off	Dispenser:	Swingable
Date Tested:	Not reported	Next Test Date:	Not F/T
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

GUILDERLAND SERV AREA 152
NEW YORK STATE THRUWAY
GUILDERLAND, NY

LUST

S10094801

NA

FINDS
RCRIS-LQG NY0981141333GUILDERLAND DRY CLEANERS
STAR PLAZA RTE 20 & 155
GUILDERLAND, NY 12084

RCRIS:	
Owner:	ROUTE 158 CPY CLEANING CORP 212-555-1212
Contact:	LARRY DOMINICK (518) 455-3321
Record Date:	11-08-95
Classification:	Large Quantity Generator
Used Oil Pict:	No
Violation Status:	No violations found

FINDS
RCRIS-LQG NY0000094672NMPC - LINE 15
STATE RD - S SIDE OF
GUILDERLAND, NY 12084

RCRIS:	
Owner:	NIAGARA MOHAWK POWER CORP (315) 429-6670
Contact:	MICHAEL ABBOTT (518) 433-3655
Record Date:	07-13-94
Classification:	Large Quantity Generator

TC0202432.1r Page 57

TC0202432.1r Page 58

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
NMPC - LINE 15 (Continued)			
100087143			
Used Oil Pict:	No		
Violation Status:	No violations found		
TOWN OF GUILDERLAND			
TOWN HALL, RT. 20		UST	U000083493
GUILDERLAND, NY 12084			
PBS UST:			
Facility ID:	4-443124	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-1950	Location:	Not reported
Operator:	TOWN OF GUILDERLAND		
Contact:	Not reported		
Emergency Contact:	CHIEF JAMES R. MURLEY, (518) 356-1980		
Facility Type:	OTHER (SPECIFY)		
Total Tanks:	4	Old PBS Num:	Not reported
Owner:	TOWN OF GUILDERLAND TOWN HALL, RT. 20 GUILDERLAND, NY 12084 (518) 356-1950		
Owner Type:	Local Government	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF GUILDERLAND TOWN HALL, RT. 20 NY 12084 (518) 356-1950		
Facility Status:	Active	Total Capacity:	4000
Certification:	06/06/1993	Expiration:	07-29-1998
Line Status:	Closed/Removed		
Tank Location:	UNDERGROUND		
Tank ID:	1	Install Date:	06-72
Product Stored:	UNLEADED GASOLINE	Tank Type:	Steel carbon steel
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overall Pict:	Not reported	Dispenser:	Swing
Date Tested:	07-87	Next Test Date:	Not reported
Date Closed:	05-89	Test Method:	PETRO-TITE
Database Type:	Not reported		

TOWN OF GUILDERLAND (Continued)

Site	Database(s)	EDR ID Number	EPA ID Number
TOWN OF GUILDERLAND (Continued)			
JCS0083693			
TOWN OF GUILDERLAND			
Facility ID:	4-443174	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	0130
Telephone:	(518) 356-1980	Location:	Not reported
Operator:	TOWN OF GUILDERLAND		
Contact:	Not reported		
Emergency Contact:	CHIEF JAMES R. MURLEY, (518) 356-1980		
Facility Type:	OTHER (SPECIFY)		
Total Tanks:	4	Old PBS Num:	Not reported
Owner:	TOWN OF GUILDERLAND TOWN HALL, RT. 20 GUILDERLAND, NY 12084 (518) 356-1950		
Owner Type:	Local Government	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF GUILDERLAND TOWN HALL, RT. 20 NY 12084 (518) 356-1950		
Facility Status:	Active	Total Capacity:	4000
Certification:	06/06/1993	Expiration:	07-29-1998
Line Status:	Closed/Removed		
Tank Location:	UNDERGROUND		
Tank ID:	2	Install Date:	12-89
Product Stored:	UNLEADED GASOLINE	Tank Type:	Steel carbon steel
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overall Pict:	Not reported	Dispenser:	Burton
Date Tested:	07-87	Next Test Date:	Not reported
Date Closed:	05-89	Test Method:	PETRO-TITE
Database Type:	Not reported		

TC0202432.1r Page 59

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
TOWN OF GUILDERLAND (Continued)		U000383493	
Facility ID:	4-443174	CBS Number:	Not reported
Term:	Not reported	SWS ID:	0130
Telephone:	(518) 356-1980	Location:	Not reported
Operator:	TOWN OF GUILDERLAND		
Contact:	Not reported		
Emergency Contact:	CHIEF JAMES R. MURLEY, (518) 356-1980		
Facility Type:	OTHER (SPECIFY)		
Total Tanks:	4	Old PBS Num.:	Not reported
Owner:	TOWN OF GUILDERLAND TOWN HALL RT. 20 GUILDERLAND, NY 12084 (518) 356-1980		
Owner Type:	Local Government	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF GUILDERLAND TOWN HALL RT. 20 NY 12084 (518) 356-1980		
Facility Status:	Active	Total Capacity:	4000
Certification:	08/29/1992	Expiration:	07/28/1996
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	1	Install Date:	05-89
Product Stored:	UNLEADED GASOLINE	Tank Type:	Fiberglass reinforced plastic (FRP)
Tank Internal:	NCNE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	NOT DEFINED
Tank External:	FIBERGLASS		
Pipe External:	FIBERGLASS/JACKETED		
Second Containment:	DOUBLE-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/INT-TANK SYSTEM		
Overfill Prot:	High level alarm	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	N/A
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
TOWN OF GUILDERLAND (Continued)		U000383493	
Facility ID:	4-443174	CBS Number:	Not reported
Term:	Not reported	SWS ID:	0130
Telephone:	(518) 356-1980	Location:	Not reported
Operator:	TOWN OF GUILDERLAND		
Contact:	Not reported		
Emergency Contact:	CHIEF JAMES R. MURLEY, (518) 356-1980		
Facility Type:	OTHER (SPECIFY)		
Total Tanks:	4	Old PBS Num.:	Not reported
Owner:	TOWN OF GUILDERLAND TOWN HALL RT. 20 GUILDERLAND, NY 12084 (518) 356-1980		
Owner Type:	Local Government	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF GUILDERLAND TOWN HALL RT. 20 NY 12084 (518) 356-1980		
Facility Status:	Active	Total Capacity:	4000
Certification:	08/09/1992	Expiration:	07/23/1998
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	2	Install Date:	05-99
Product Stored:	UNLEADED GASOLINE	Tank Type:	Fiberglass reinforced plastic (FRP)
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	NOT DEFINED
Tank External:	FIBERGLASS		
Pipe External:	FIBERGLASS/JACKETED		
Second Containment:	DOUBLE-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/INT-TANK SYSTEM		
Overfill Prot:	High level alarm	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	N/A
Date Closed:	Not reported	Test Method:	Not reported
Database Type:	Not reported		

UST N/A U000382463

GETTY 58218
1229 WESTERN AVE
GUILDERLAND, NY 12203

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GETTY 58218 (Continued)		U000382463	
PBS UST:			
Facility ID:	4-088285	CBS Number:	Not reported
Term:	Not reported	SWS ID:	0130
Telephone:	(518) 482-2935	Location:	Not reported
Operator:	THOMAS CANALE		
Contact:	Not reported		
Emergency Contact:	JOSEPH F KELLEY, REGIONAL ENGR., (518) 465-2752		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	4	Old PBS Num.:	Not reported
Owner:	POWER TEST REALTY COMPANY 125 JERICHO TURNPIKE JERICHO, NY 11753 (518) 338-8000		
Owner Type:	Corporate/Commercial	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	GETTY PETROLEUM CORP. 49 RIVERSIDE DRIVE NY 12144 (518) 465-2752		
Facility Status:	Active	Total Capacity:	10000
Certification:	05/20/1992	Expiration:	05/07/1997
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	1	Install Date:	05-81
Product Stored:	UNLEADED GASOLINE	Tank Type:	Fiberglass reinforced plastic (FRP)
Tank Internal:	NCNE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FRIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	NONE		
Leak Detection:	None		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	07/94	Next Test Date:	05/95
Date Closed:	Not reported	Test Method:	UNKNOWN
Database Type:	Not reported		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
GETTY 58218 (Continued)		U000382463	
Facility ID:	4-088285	CBS Number:	Not reported
Term:	Not reported	SWS ID:	0130
Telephone:	(518) 482-2935	Location:	Not reported
Operator:	THOMAS CANALE		
Contact:	Not reported		
Emergency Contact:	JOSEPH F KELLEY, REGIONAL ENGR., (518) 465-2752		
Facility Type:	RETAIL GASOLINE SALES		
Total Tanks:	4	Old PBS Num.:	Not reported
Owner:	POWER TEST REALTY COMPANY 125 JERICHO TURNPIKE JERICHO, NY 11753 (518) 338-8000		
Owner Type:	Corporate/Commercial	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	GETTY PETROLEUM CORP. 49 RIVERSIDE DRIVE NY 12144 (518) 465-2752		
Facility Status:	Active	Total Capacity:	10000
Certification:	05/20/1992	Expiration:	05/07/1997
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	2	Install Date:	05-81
Product Stored:	UNLEADED GASOLINE	Tank Type:	Fiberglass reinforced plastic (FRP)
Tank Internal:	NCNE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS (FRP)
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	NONE		
Leak Detection:	None		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	07/94	Next Test Date:	05/95
Date Closed:	Not reported	Test Method:	UNKNOWN
Database Type:	Not reported		

DETAILED ORPHAN LISTING			
			EDR ID Number EPA ID Number
Site		Database#	
ORPHAN 38218 (Continued)			U000002463
Facility ID:	4-084255	CBS Number:	Not reported
Town:	Not reported	SWIS ID:	6730
Telephone:	(516) 482-2935	Location:	Not reported
Operator:	THOMAS CANALE		
Contact:	Not reported		
Emergency Contact:	JOSEPH F KELLEY, REGIONAL ENGR., (516) 465-2752		
Farm Type:	RETAIL GASOLINE SALES		
Total Tanks:	4	Old PBS Num:	Not reported
Owner:	POWER TEST REALTY COMPANY 125 JERICHO TURNPIKE JERICHO, NY 11750 (516) 338-6000		
Owner Type:	Corporate/Commercial	Owner Mark:	First Owner
Owner Subtype:	Not reported		
Mailing Address:	GETTY PETROLEUM CORP. 49 RIVERSIDE DRIVE NY 12144 (516) 465-2752		
Facility Status:	Active	Total Capacity:	10000
Construction:	05/20/1992	Expiration:	05/07/1997
Tank Status:	In Service		
Tank Location:	UNDERGROUND		
Tank ID:	3	Install Date:	05/81
Product Stored:	UNLEADED GASOLINE	Container Type:	Fiberglass reinforced plastic [FRP]
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	NONE		
Pipe External:	NONE		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	NONE	Dispenser:	Submersible
Date Tested:	07/84	Next Test Date:	05/95
Date Closed:	Not reported	Test Method:	UNKNOWN
Database Type:	Not required		

DETAILED CHAPMAN LISTING			
		Database(s)	
		EDR, G Number EPA ID Number	
<u>Site</u>			
GETTY 52218 (Continued)			UD00332463
Facility ID:	4-086745	CBS Number	Not reported
Town:	Not reported	SWIS ID:	0132
Telephone:	(518) 462-2315	Location:	Not reported
Operator:	THOMAS CANALE		
Contact:	Not reported		
Emergency Contact:	JOSEPH F KELLEY, REGIONAL ENGR., (518) 465-2752		
Facility Type:	PETROLEUM GASOLINE SALES		
Total Tanks:	4	O-4 PBS Num:	Not reported
Owner:	POWER TEST REALTY COMPANY 125 JERICHO TURNPIKE JERICHO, NY 11753 (516) 338-5000	Owner: Mark	First Owner
Owner Type:	Corporate/Commercial		
Owner Subtype:	Not reported		
Mailing Address:	GETTY PETROLEUM CORP 49 RIVERSIDE DRIVE NY 12144 (518) 465-2752		
Facility Status:	ATTN: JOSEPH F KELLEY REG ENGR. Active	Total Capacity	550
Classification:	057201-992	Expiration:	05-07-'99
Tank Status:	In Service		
Tank Location:	UNDERGROUND	Install Date	08/73
Tank ID:	4	Tank Type:	Storage; Steel
Product Stored:	OTHER	Pipe Interna-	NONE
Tank Internal:	NCNE	Pipe Extern-	
Pipe Location:	Underground	al Type:	GALVANIZED STEEL
Tank External:	None		
Pipe External:	None		
Saint Containment:	NCNE		
Leak Detection:	NCNE		
Overall Plan:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	N.T.R.
Date Closed:	Not reported	Test Methods:	Not reported
Database Type:	Not reported		

100202432.ir Page 63

-00202432.12 Page 55

DETAILED ORPHAN LISTING

Site		Databases:	EDR ID Number
FIREHOUSE WESTERN AV RT20 (Consumed)		-	EP4 Number
Soul Number:	Responsible Party	PBS Number:	Not reported
Date Built:	08/21/1994	Reported to:	09/21/1994 4:12
Cleanup Ceased:	11/08/1994		
Last Inspected:	11/08/1994		
Cleanup Meta Standard:	True		
Recommended Penalty:	No Penalty		
Soil/Clean Date:	Not reported		
Enforcement Date:	Not reported		
Investigator Compute:	Not reported		
UST Involved:	False		
Soil Record Last Update:	12/01/1994		
Corrective Action Plan Submitted:	Not reported		
Date Soil Entered in Computer Data File:	09/22/1994		
Remark:	FOUND OLD UGL & CONT. SOIL WHILE DOING NEW CONSTRUCTION, WTC # SITE 25- SGL X - CW X D. ON SW GSW SEE RPT. REMOVED CONT SOIL TO CLAY LAYER. DISPOSED OF LF.		

DETAILED ORPHAN LISTING		EDB ID Number EPA ID Number
Site	Databases	
REGENCY APARTMENTS WESTERN AVE GUILDFORD, NY	LUST	\$102233768 NRA
LUST:		
Facility ID: 960074- Facility Contact: TIM OWENS Investigator: CH-BENSTENSEN Caller Name: JEFF WINK Caller Phone: (518) 899-3654 Wells Known: None Nodular Phone: (518) 899-3664 Spiller Contact: TIM OWENS Spiller Contact: TIM OWENS Address: REGENCY APARTS Address: WESTERN AVE Address: GUILDFORD, NY	Region of Spill: 4 Facility Tele: (518) 458-8500 Soil Type: UST State Agency: NORTHEAST ENVIR Caller Extension: Not reported Notifier Agency: NORTHEAST ENVIR Notifier Extension: Not reported Spiller Phone: (518) 458-6500	
Spill Class: Known release that creates potential for fire or hazard; DEC Response Willing Responsible Party; Corrective action taken.		
Spill Closed Dt: Not reported	Resource Affected: On Land	
Spill Cause: Tank Failure	Soil Source: Other Commercial/Industrial	
Water Affected: Not reported	PBS Number: Not reported	
Spill No/Ref: Other	Reported to Dept.: 06/18/1995 15:24	
Spill Date: 06/18/1995 15:10		
Cleanup Status: not reported		
Last Inspection: Not reported		
Cleanup Meets Standards: False		
Recommended Penalty: No Penalty		
Spill Response Order: Not reported		
Rec-Completion Date: Not reported		
Investigation Complete: Not reported		
UST Inventory: True		
Spill Record Last Update: 06/19/1995		
Corrective Action Plan Submitted: Not reported		
Date Spill Entered in Computer Data File: 06/18/1995		

WESTERN AV / STATE FARM R
GUILDFIELD, NY

LUST		Report of SLE	#
Facility ID:	9606851	Facility Tel:	Not reported
Facility Contact:	Not reported	SP/Type:	UST
Investigator:	CARL H. BENN	Call Agency:	NIAGARA MOHAWK
Caller Name:	SCOTT LALOCZOWSKI	Caller Extension:	Not reported
Caller Number:	518-356-6471	Notifier Agency:	NIAGARA MOHAWK
Notif. Name:	MI BOLGONNO	Notifier Extension:	Not reported
Notif. Phone:	Not reported	Spiller Phone:	Not reported
Spiller Contact:	Not reported		
Spiller:	NIAGARA MOHAWK		
Acknowledges:	300 ERIE BOULEVARD WEST SYRACUSE, NY		
Spill Class:	Known release with minimal potential for fire or hazard. O&G Response.		
	Spill response initiated by facility or emergency service agency.		

HOLIDAY INN WESTERN AV
1442 WESTERN AV KRUMKILL
GUIDERLND, NY

LUST **S102235631**
NIA

Facility ID: 6904160 **Region of Spill:** 4
Facility Name: MARK MYKES **Facility Tele:** (518) 487-0312
Investigator: BENTEN **Spill Size:** US
Caller Name: MARK WYKES **Caller Agency:** ALBANY COUNTY HEALTH DEPT
Caller Phone: (518) 447-4620 **Caller Extension:** Not Applicable
Notifier Name: CAROL LAFAY **Another Agency:** DEC REG CN-4
Notifier Phone: Not 1800# **Notifier Extension:** Not Applicable
Spiller Contact: KATHY TABORA **Spiller Phone:** (518) 488-3001
Spiller: HLY DAY INN EXPRESS
Address: 1442 WESTERN AV
Address 2: GUIDERLND NY 12233
Spill Class: Possible hazard with minimal potential for fire or hazard or Known
 Spills with no damage. No DEC Response. No corrective action required.
Spill Class ID: 56251195 **Resource Affected:** Surface Water
Spill Sub-Category: OIL/GAS **Spill Source:** Other Commercial/Industrial
Water Affected: KRUMKILL CREEK **Spill Number:** Not reported
Spill Author: Health Department **Reported To Spill:** 56251195 12-57
Spill Date: 08/25/1996 **Spill Month:** August

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
HOLIDAY INN WESTERN AV (Continued)		S10223563	

Cleanup Ceased: Not reported
 Last Inspection: Not reported
 Cleanup Meets Standard: False
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Completed: 06/28/1996
 UST Involvement: False
 Spill Record Last Update: 01/12/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered in Computer Data File: 06/28/1996
 Remark: Owner was asked by dec region 4 to investigate a milky white substance in the kitchen sink - he did find a substance coming from an evaporator or from the holiday inns cooling system coming from a blow off valve - according to the call there isdefinitely a problem there - the subject mark spoke to stated that the substance could be a watercolor mixture

UNIVERSITY-GETTY
1229 WESTERN AVE,
GUILDFORD, NY

LUST	S10013432	N/A
Facility ID:	8100021	Region of Spill: 4
Facility Contact:	Not reported	Facility Type: Facility
Investigator:	SLAIN	Spill Type: Other
Caller Name:	Not reported	Caller Agency: Not reported
Caller Phone:	Not reported	Caller Extension: Not reported
Owner Name:	Not reported	Notifier Agency: Not reported
Owner Phone:	Not reported	Notifier Extension: Not reported
Spiller Contact:	Not reported	Spiller Phone: Not reported
Spiller:	Not reported	
Address:	Not reported	
Spill Class:	Not reported	
Spill Closed Dt:	04/01/1987	
Spill Cause:	Tank Failure	Resource Affected: In Sewer
Water Affected:	Not reported	Spill Source: Other Commercial/Industrial
Spill Hauler:	Citizen	PBS Number: Not reported
Spill Date:	03/26/1987 12:00	Reported to Dept: 03/26/1987 15:05
Cleanup Ceased:	04/01/1987	
Last Inspection:	04/01/1987	
Cleanup Meets Standard:	True	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Completed:	Not reported	
UST Involvement:	False	
Spill Record Last Update:	05/07/1995	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered in Computer Data File:	04/12/1987	
Remark:	MET W SPURGE BROWN/GETTY & GUILDFORD SEWER DEPT. v30 OIL N CATCH-BASIN, POSS. COMING FROM A WASTE OIL TANK ON A FUEL OIL TRUCK	

T0002432.1r Page 59

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
HESS RT 20 @ JOHNSTON RD (Continued)		S10017762	

Spiller/Hauler: Other
 Spill Date: 12/02/1991 10:10
 Cleanup Ceased: Not reported
 Last Inspection: Not reported
 Cleanup Meets Standard: False
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Completed: Not reported
 UST Involvement: True
 Spill Record Last Update: 08/25/1994
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered in Computer Data File: 12/01/1991
 Remark: STOCKPILEING CONT SOIL SEE FILE #710158 UNDER CONSENT ORDER.

NORTHWAY MOTOR CAR CORP
727 NEW LONDON RD
LATHAM, NY 12103

RCRIS:	Owner:	Not reported
Contact:	John Toennes	(315) 474-1511
Record Date:	10/24/95	
Classification:	Large Quantity Generator	
Used Oil Recycl: No		
Violation Status: No violations found		

FINDS 100041038
RCRIS-LGG NY0004981023

MCKOWNVILLE SUBSTATION
ROUTE 23
MCKOWNVILLE, NY 12003

RCRIS:	Owner:	Not reported
Contact:	JOHN TOENNES	(315) 474-1511
Record Date:	14/15/95	
Classification:	Large Quantity Generator	
Used Oil Recycl: No		
Violation Status: No violations found		

FINDS 1000344108
RCRIS-LGG NY0991076805

PINEBRUSH SUBSTATION
ROUTE 155
TOWN OF GUILDFORD, NY 12064

FINDS 1000200511
RCRIS-LGG NY068-075883

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
STEWART PROP RT 20 WESTERN AVE, RT 20 GUILDFORD, NY		LUST	S100177022 N/A

LUST:
 Facility ID: 9108751
 Facility Contact: Not reported
 Investigator: CH-RISTER/GENETIK
 Caller Name: OFF: DANIEL MCNAUL Y
 Caller Phone: (518) 356-1950
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: FREDERICK STEWART
 Address: 1 BRUCE DR,
 ALPLAUS

Split Class: Known release with minimal potential for fire or hazard. DEC Response
 Willing Responsible Party: Corrective action taken.

Resource Affected: On Land
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 11/15/1991 14:25

Cleanup Ceased: 01/16/1992
 Last inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Completed: Not reported
 UST Involvement: False
 Spill Record Last Update: 01/16/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered in Computer Data File: 11/15/1991
 Remark: DO NOT PROBLEMS EN SITE. OWNER FORMERLY IN JAIL. NOW LIVING IN ALPLAUS, NY. HOUSEKEEPING PROBLEMS COMPOUNDED BY FIRE. TK ATTEMPTED SEVERAL TIMES TO REACH OFF, NOVALLY NO CONTACT, CLOSED.

Site	Database(s)	EDR ID Number	EPA ID Number
HESS RT 20 @ JOHNSTON RD WESTERN @ JOHNSTON RT 20 GUILDFORD, NY		LUST	S100177675 N/A

LUST:
 Facility ID: 91002956
 Facility Contact: Not reported
 Investigator: CHRISTENSEN
 Caller Name: MARY PASSARETTI
 Caller Phone: (518) 531-3991
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: BOB HOWARD PEALT/
 Address: WESTERN AVE,
 GUILDFORD
 Spill Class: Known release that poses potential for fire or hazard. DEC Response.
 Willing Responsible Party: Corrective action taken.

Spill Closed Dt: Not reported
 Spill Cause: Tank Failure
 Water Affected: Not reported

Resource Affected: On Land
 Spill Source: Gas Station

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number	EPA ID Number
PINEBRUSH SUBSTATION (Continued)			1000200511

RCRIS:
 Owner: Not reported
 Contact: JOHN TOENNES
 Record Date: 04/15/95
 Classification: Large Quantity Generator
 Used Oil Recycl: No
 Violation Status: No violations found

T0002432.1r Page 70

T0002432.1r Page 70

GEOCHECK VERSION 2.1 ADDENDUM
FEDERAL DATABASE WELL INFORMATION

Well Closest to Target Property (Northern Quadrant)

BASIC WELL DATA	
Site ID:	42423007350201*
Site Type:	Single well, other than collector or Rarney type
Year Constructed:	Not Reported
Altitude:	237.00 ft.
Well Depth:	Not Reported
Depth to Water Table:	Not Reported
Date Measured:	Not Reported
Distance from TP:	1/2 - 1 Mile

LITHOLOGIC DATA	
Geologic Age ID (Era/System/Series):	Cenozoic-Cuaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	GR, SM, SI

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

Well Closest to Target Property (Eastern Quadrant)

BASIC WELL DATA	
Site ID:	42-12107352201*
Site Type:	Single well, other than collector or Rarney type
Year Constructed:	1946
Altitude:	250.00 ft.
Well Depth:	21.00 ft.
Depth to Water Table:	14.00 ft.
Date Measured:	01/01/1946
Distance from TP:	1/2 - 1 Mile

LITHOLOGIC DATA	
Geologic Age ID (Era/System/Series):	Cenozoic-Cuaternary-Pleistocene
Principal Lithology of Unit:	Not Reported
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

Well Closest to Target Property (Southern Quadrant)

BASIC WELL DATA	
Site ID:	42424407355101*
Site Type:	Single well, other than collector or Rarney type
Year Constructed:	1979
Altitude:	220.00 ft.
Well Depth:	198.00 ft.
Depth to Water Table:	116.32 ft.
Date Measured:	09/02/1979
Distance from TP:	1 - 2 Miles

LITHOLOGIC DATA	
Geologic Age ID (Era/System/Series):	Cenozoic-Cuaternary-Pleistocene
Principal Lithology of Unit:	Gravel
Further Description:	CLAYEY

WATER LEVEL VARIABILITY

Water Level:	116.32 ft.	Water Level:	116.47 ft.	Water Level:	116.47 ft.	Water Level:	116.47 ft.
Date Measured:	09/20/79	Date Measured:	09/23/79	Date Measured:	09/27/79	Date Measured:	10/19/79
Water Level:	116.39 ft.	Water Level:	116.52 ft.	Water Level:	117.20 ft.	Water Level:	117.20 ft.
Date Measured:	11/05/79	Date Measured:	11/12/79	Date Measured:	12/15/79	Date Measured:	1/1/80
Water Level:	116.60 ft.	Water Level:	116.70 ft.	Water Level:	117.25 ft.	Water Level:	117.25 ft.
Date Measured:	02/09/77	Date Measured:	03/11/77	Date Measured:	04/05/77	Date Measured:	05/19/77
Water Level:	119.39 ft.	Water Level:	120.02 ft.	Water Level:	120.04 ft.	Water Level:	120.29 ft.
Date Measured:	06/12/77	Date Measured:	07/05/77	Date Measured:	09/05/77	Date Measured:	1/4/77
Water Level:	116.48 ft.	Water Level:	119.10 ft.	Water Level:	120.71 ft.	Water Level:	119.31 ft.
Date Measured:	11/04/77	Date Measured:	01/12/78	Date Measured:	02/21/78	Date Measured:	02/24/78
Water Level:	120.41 ft.	Water Level:	121.15 ft.	Water Level:	121.45 ft.	Water Level:	121.70 ft.
Date Measured:	03/23/79	Date Measured:	04/18/78	Date Measured:	05/16/78	Date Measured:	06/12/78
Water Level:	120.38 ft.	Water Level:	122.35 ft.	Water Level:	124.30 ft.	Water Level:	126.33 ft.
Date Measured:	07/14/78	Date Measured:	08/02/78	Date Measured:	08/30/78	Date Measured:	09/12/78
Water Level:	126.35 ft.	Water Level:	125.88 ft.	Water Level:	124.87 ft.	Water Level:	121.25 ft.
Date Measured:	11/25/78	Date Measured:	11/25/78	Date Measured:	12/15/78	Date Measured:	01/31/79
Water Level:	119.30 ft.	Water Level:	119.55 ft.	Water Level:	114.69 ft.	Water Level:	121.75 ft.
Date Measured:	03/26/79	Date Measured:	04/03/79	Date Measured:	05/01/79	Date Measured:	05/21/79
Water Level:	119.22 ft.	Water Level:	119.58 ft.	Water Level:	119.23 ft.	Water Level:	118.43 ft.
Date Measured:	05/31/79	Date Measured:	06/05/79	Date Measured:	06/07/79	Date Measured:	06/17/79
Water Level:	118.88 ft.	Water Level:	119.86 ft.	Water Level:	119.87 ft.	Water Level:	120.15 ft.
Date Measured:	06/20/79	Date Measured:	06/25/79	Date Measured:	06/30/79	Date Measured:	07/05/79
Water Level:	120.31 ft.	Water Level:	121.39 ft.	Water Level:	120.78 ft.	Water Level:	119.86 ft.
Date Measured:	07/10/79	Date Measured:	07/15/79	Date Measured:	07/20/79	Date Measured:	07/25/79
Water Level:	119.32 ft.	Water Level:	119.57 ft.	Water Level:	119.85 ft.	Water Level:	120.14 ft.
Date Measured:	07/14/79	Date Measured:	08/05/79	Date Measured:	08/19/79	Date Measured:	08/27/79
Water Level:	118.32 ft.	Water Level:	118.75 ft.	Water Level:	119.31 ft.	Water Level:	118.39 ft.
Date Measured:	08/20/79	Date Measured:	08/25/79	Date Measured:	08/31/79	Date Measured:	09/05/79
Water Level:	118.12 ft.	Water Level:	117.74 ft.	Water Level:	118.28 ft.	Water Level:	118.46 ft.
Date Measured:	09/10/79	Date Measured:	09/15/79	Date Measured:	09/20/79	Date Measured:	09/25/79

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

Well Closest to Target Property (Western Quadrant)

BASIC WELL DATA	
Site ID:	42422407354130*
Site Type:	Single well, other than collector or Rarney type
Year Constructed:	Not Reported
Altitude:	not Reported
Well Depth:	70.00 ft.
Depth to Water Table:	Not Reported
Date Measured:	Not Reported
Distance from TP:	1/2 - 1 Miles

LITHOLOGIC DATA	
Geologic Age ID (Era/System/Series):	Cenozoic-Cuaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
STATE DATABASE WELL INFORMATION

Water Well Information:

Well Within 1 - 2 Miles of Target Property (Northern Quadrant):

Public Water Supply #	PWS ID	Source ID	001
PW Supply Name:	0109197	Source Name:	GUILDFIELD WATER DISTRICT
Source Name:	WELL #60 FT	Source Description:	Groundwater
Available Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	424308	Longitude:	.725402
Source Prod Capacity:	0	Fed ID of Seller:	Not Reported
Watershed Basin:	13	Watershed Sub-basin:	00
Treatment Plant ID:	004	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Not Reported

Well Within 1 - 2 Miles of Target Property (Southern Quadrant):

Public Water Supply #	PWS ID	Source ID	002
PW Supply Name:	0100295	Source Name:	GUILDFIELD WD (WESTMERE WD)
Source Name:	WATER TOWER RESERVOIR	Source Description:	Surface
Available Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	424108	Longitude:	.725400
Source Prod Capacity:	0	Fed ID of Seller:	Not Reported
Watershed Basin:	13	Watershed Sub-basin:	00
Treatment Plant ID:	005	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Not Reported

Well Within 1/2 - 1 Mile of Target Property (Western Quadrant):

Public Water Supply #	PWS ID	Source ID	004
PW Supply Name:	0100295	Source Name:	GUILDFIELD WD (WESTMERE WD)
Source Name:	WELL #2	Source Description:	Groundwater
Available Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	424107	Longitude:	.725402
Source Prod Capacity:	0	Fed ID of Seller:	Not Reported
Watershed Basin:	13	Watershed Sub-basin:	00
Treatment Plant ID:	005	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Not Reported

TQ0202432.11 Page A6

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

* To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM RECORDS:

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-415-0223

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 100 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/01/97

Date Made Active in EDR: 06/03/97

Database Release Frequency: Monthly

ERNS: Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/01/97

Date Made Active in EDR: 06/24/97

Database Release Frequency: Quarterly

NPL: National Priority List

Source: EPA

Telephone: 703-505-6855

NPL: National Priority List (Superfund). The NPL is a subset of CERCLIS and contains over 1,100 sites for priority cleanup under the Superfund Program. NPL sites may encompass entire large areas. As of 1/1/97, EDR provides coverage for over 1,000 NPL and contains information from EPA's Environmental Photographic Interpretation Center (EPIC).

Date of Government Version: 04/01/97

Date Made Active in EDR: 06/29/97

Database Release Frequency: Semi-Annually

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 800-421-3045

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes corrective information on sites with radioactive, irritant, toxic, treat, store or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 04/01/97

Date Made Active in EDR: 06/03/97

Database Release Frequency: Semi-Annually

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 800-421-9345

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action history.

Date of Government Version: 12/01/96

Date Made Active in EDR: 06/03/97

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 04/10/97

Elapsed ASTM Days: 40

Date of Last EDR Contact: 08/29/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

Date of Data Arrival at EDR: 04/26/97

Elapsed ASTM Days: 38

Date of Last EDR Contact: 07/01/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PADS: PCB Activity Database System

Source: EPA
Telephone: 202-560-3938
PADS: PCB Activity Database. PADS describes generators, transporters, commercial stores and/or brokers and dislosers of PCBs who are required to notify the EPA of such activities.

Date of Government Version: 01/17/97
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/19/97
Date of Next Scheduled EDR Contact: 11/17/97

RAATS: RCRA Administrative Action Tracking System

Source: EPA
Telephone: 202-561-4704
RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administrative actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 07/27/97
Date of Next Scheduled EDR Contact: 09/15/97

RCO: Records Of Decision

Source: EPA/NTIS
Telephone: 703-416-0223
Record of Decision: RCO documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95
Database Release Frequency: Annually

Date of Last EDR Contact: 09/03/97
Date of Next Scheduled EDR Contact: 12/01/97

TRIS: Toxic Chemical Release Inventory System

Source: EPANTS
Telephone: 202-260-5311
TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water, and land in reportable quantities under SARA Title IV Section 313.

Date of Government Version: 12/31/90
Database Release Frequency: Annually

Date of Last EDR Contact: 07/27/97
Date of Next Scheduled EDR Contact: 08/29/97

TSCA: Toxic Substances Control Act

Source: EPANTS
Telephone: 202-260-1444
TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95
Database Release Frequency: Annually

Date of Last EDR Contact: 08/16/97
Date of Next Scheduled EDR Contact: 09/15/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF NEW YORK ASTM RECORDS:

LUST: Soils Information Database
Source: Department of Environmental Conservation
Telephone: 518-457-2662
LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all sites in New York have these records, and the information stored varies by state.
Date of Government Version: 02/03/98
Date Made Active at EDR: 04/21/97
Database Release Frequency: Quarterly
Elapsed ASTM days: 88
Date of Last EDR Contact: 07/28/97

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Source: Department of Environmental Conservation
Telephone: 518-457-0747
SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are denoted along with sites where cleanup will be paid for by privately responsible parties. Available information varies by state.

Date of Government Version: 04/06/96
Date Made Active at EDR: 08/06/96
Database Release Frequency: Annually

SWFLP: Facility Register

Source: Department of Environmental Conservation
Telephone: 518-457-2051
SWFLP: Solid Waste Facilities/Landfill Sites. SWFLP site records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive (closed or open dumps) that failed to meet RCRA Subtitle C Section 1004 criteria for solid waste landfill or disposal units.
Date of Government Version: 12/03/96
Date Made Active at EDR: 04/21/97
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 08/06/96
Elapsed ASTM days: 60
Date of Last EDR Contact: 05/11/97

UST: Petroleum Bulk Storage (PBS) CBS, MUSP Database (LUST)

Source: Department of Environmental Conservation
Telephone: 518-457-3551
UST: Registered Underground Storage Tanks. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for each including the UST program. Available information varies by state program.
Date of Government Version: 12/03/96
Date Made Active at EDR: 04/07/97
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 02/20/97
Elapsed ASTM days: 60
Date of Last EDR Contact: 05/11/97

STATE OF NEW YORK NON-ASTM RECORDS:

AST: Petroleum Bulk Storage (AST)

Source: Department of Environmental Conservation
Telephone: 518-457-4235
AST: Registered Aboveground Storage Tanks.
Date of Government Version: 09/06/96
Database Release Frequency: Quarterly
Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 11/05/97

SPILLS: Spills Information Database

Source: Department of Environmental Conservation
Telephone: 518-457-3482
SPILLS: Data collected on spills reported to NYSDC as required by one or more of the following: Article 12 of the Navigation Law & NYCCR Section 813.8 (inc. PBS reg), or 8 NYCCR Section 865.2 (from OSS reg). It includes spills active as of April 1, 1988, as well as spills occurring since this date.
Date of Government Version: 12/03/96
Database Release Frequency: Quarterly
Date of Last EDR Contact: 07/28/97
Date of Next Scheduled EDR Contact: 10/27/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NEW YORK COUNTY RECORDS

CORTLAND COUNTY:

Cortland County UST Listing (AST)
Source: Cortland County Health Department
Telephone: 607-753-6035
Date of Government Version: 03/25/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 12/06/97

CORTLAND COUNTY UST LISTING (UST)

Source: Cortland County Health Department
Telephone: 607-753-6035
Date of Government Version: 08/06/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 12/06/97

NASSAU COUNTY:

NCPHO Article XI Database (AST)
Source: Nassau County Health Department
Telephone: 516-371-3314
Date of Government Version: 12/01/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 10/05/97

NCPHO Article XI Database (UST)

Source: Nassau County Health Department
Telephone: 516-371-3314
Date of Government Version: 02/04/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 07/06/97
Date of Next Scheduled EDR Contact: 10/06/97

ROCKLAND COUNTY:

Petroleum Bulk Storage Database (AST)
Source: Rockland County Health Department
Telephone: 914-364-2605
Date of Government Version: 03/28/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 12/06/97

PETROLEUM BULK STORAGE DATABASE (UST)

Source: Rockland County Health Department
Telephone: 914-364-2605
Date of Government Version: 03/28/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 08/06/97
Date of Next Scheduled EDR Contact: 12/06/97

SUFFOLK COUNTY:

Underground Storage Tank Database (AST)
Source: Suffolk County Department of Health Services
Telephone: 516-454-2521
Date of Government Version: 03/01/98
Database Release Frequency: Annually

Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 12/06/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UNDERGROUND STORAGE TANK DATABASE (UST)

Source: Suffolk County Department of Health Services
Telephone: 516-861-2521
Date of Government Version: 02/21/97
Database Release Frequency: Annually
Date of Last EDR Contact: 09/06/97
Date of Next Scheduled EDR Contact: 12/06/97

Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific record does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to former Real Property Scan, Inc. ©Copyright 1995 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to the amount paid. No claim is made for the actual existence or non-existence of any site. This report does not constitute a legal opinion.

DISCLOSED NPL: Drafted NPL Sites

Source: EPA
Telephone: 103-403-8759
DISCLOSED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) discloses the criteria that the EPA uses to determine sites from the NPL in accordance with 40 CFR 300.425 et seq. sites may be deleted from the NPL where no further response is anticipated.

NFRAP: No Further Remedial Action Planned

Source: EPA/NTIS
Telephone: 703-415-0223
NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation no contamination was found, or removed due to the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or EPA intervention. EPA has removed approximately 25 NCP sites from the NPL to the extent that the remediation of these properties and thus protection of the public health is no longer necessary. This policy change is part of EPA's Brownfields Redevelopment Program to reuse sites, states, private investors and affected citizens to promote economic reuse of unproductive industrial sites.

FEDERAL REPORTING DATA SYSTEM (FRDS)

Source: EPA/Office of Drinking Water
Telephone: 202-260-2805
FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCLs), and other requirements of the Safe Drinking Water Act of 1986.

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a combination of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The USEPA has a combination of the residential radon survey and the national residential radon survey study covers the years 1988 - 1992, where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the Transportation category, including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special care they need to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers and nursing homes - where individuals who are sensitive receptors are likely to be located.

USGS Water Wells: In November 1997 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 300,000 wells, springs, and other sources of groundwater.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

Epicenters: World earthquake epicenters, Richter 5 or greater.
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Water Dams: National Inventory of Dams
Source: Federal Emergency Management Agency
Telephone: 202-546-2801
WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

Town of Guilderland

ALBANY COUNTY, ROUTE 29

P.O. BOX 339

GUILDERLAND, N.Y. 12084-0339

(518) 256-3980

FAX (518) 256-3995

WILLIAM F. AYWARD
SUPERVISOR

KATHY SICKLER
TOWN CLERK

October 9, 1997

Mr. Michael Colombo
Project Manager
IVI Environmental, Inc.
105 Corporate Park Drive
Suite 115
White Plains, NY 10604

Dear Mr. Colombo:

Thank you for your Freedom of Information request dated October 7, 1997.

We have found the following information regarding the Phase I Environmental Site Assessment on:

Carman Plaza
3770 Carman Rd.
Guilderland, New York

- Q. Does your utility provide potable water to the above referenced site?
A. Yes
- Q. What is the source of the drinking water supply for the above referenced site?
A. Groundwater?
- A. Yes
- Q. Surface water?
A. Yes, 95%-100%, City of Albany interconnect
- Q. Does your utility provide drinking water that meets the current state or federal drinking water quality standards?
A. Yes
- Q. Can we obtain a copy of the latest round of drinking water quality testing results including lead and copper?
A. Yes, available for review at the Water Department

TO02204303r Page A1

- Q. Are there any lead pipes within the water distribution system?
A. Yes
- Q. What is being done to limit the lead concentration in the water supply?
A. N/A
- Q. Does your utility conduct at-the-tap lead testing?
A. Yes
- Q. Name of aquifer?
A. Offshoot of Colonie channel
- Q. Where is the nearest well to the Subject?
A. 8 miles approximately
- Q. Are the wells active?
A. Yes
- Q. How deep are the wells?
A. 118 ft.
- Q. If the wells are in close proximity to the Subject, ask the following:
a. Can you provide me with the latest analytical results from the well?
A. Yes
- Q. b. Is the Subject within a Zone of Contribution?
A. No?
- Q. c. Is the Subject within a Wellhead Protection Zone?
A. No
- Q. Are there any known potential sources of groundwater contamination which might impact these wells or the Subject?
A. No

In addition, we have found the following information regarding the Phase I Environmental Site Assessment on:
Star Plaza
2050 Western Ave.
Guilderland, New York

- Q. Does your utility provide potable water to the above referenced site?
A. Yes
- Q. What is the source of the drinking water supply for the above referenced site?
A. Groundwater?
- A. Yes

- Q. Surface water?
A. Yes, mixture, City of Albany Interconnect
- Q. Does your utility provide drinking water that meets the current state or federal drinking water quality standards?
A. Yes
- Q. Can we obtain a copy of the latest round of drinking water quality testing results including lead and copper?
A. Yes, available for review at the Water Department
- Q. Are there any lead pipes within the water distribution system?
A. Yes
- Q. What is being done to limit the lead concentration in the water supply?
A. N/A
- Q. Does your utility conduct at-the-tap lead testing?
A. Yes
- Q. Name of aquifer?
A. Offshoot of Colonie channel
- Q. Where is the nearest well to the Subject?
A. 1 mile approximately
- Q. Are the wells active?
A. Yes
- Q. How deep are the wells?
A. 118 ft.
- Q. If the wells are in close proximity to the Subject, ask the following:
a. Can you provide me with the latest analytical results from the well?
A. Yes
- Q. b. Is the Subject within a Zone of Contribution?
A. Yes?
- Q. c. Is the Subject within a Wellhead Protection Zone?
A. No
- Q. Are there any known potential sources of groundwater contamination which might impact these wells or the Subject?
A. No

Please note some of the information is on file at the Water Department. Please contact them at (518) 456-6474 and schedule

an appointment to review these files. At that time, copies can be obtained at \$0.25 per page.

If you have any questions, please contact our office at (518) 356-1930.

Sincerely,

Kathy Sickler, CMO
Town Clerk

KS:mu

Distribution: William West, Superintendent of Water & Wastewater
Kathy Sickler, Town Clerk

Facsimile Transmission

IVI Environmental, Inc.
105 Corporate Park Drive Suite 115
White Plains, New York 10604

Date: 22 October 1997
IVI Project No.: E7092211

To: Steven Lukowski - Director of Env. Services (518) 447-4580(tel)
Albany Health Department - Environmental Health (518) 447-4573(fax)

From: Michael Colombo (914) 694-9600 (tel)
Project Manager (914) 694-8549 (fax)

<input type="checkbox"/> New York (914) 694-9600 (tel)	<input type="checkbox"/> Washington, D.C. (201) 907-0163 (tel)	<input type="checkbox"/> Los Angeles (213) 896-0300 (tel)	<input type="checkbox"/> Miami (305) 358-1776 (tel)	<input type="checkbox"/> Paris 33.1.30.12.85.00 (tel)
(914) 694-8549 (fax)	(201) 907-3352 (fax)	(213) 896-0149 (fax)	(305) 372-0189 (fax)	33.1.30.12.86.66 (fax)

FAXED

Freedom of Information Act Request

IVI Environmental, Inc. (IVI) has been retained to conduct a Phase I Environmental Site Assessment on:

Star Plaza
2050 Western Ave.
Guilderland, New York 12084

In accordance with the Freedom of Information Act, IVI is requesting information with respect to the above referenced site. Specifically, IVI is requesting the following information:

- Are there any environmental health related problems at the Subject or in the area? Yes No
- Do any general environmental conditions, such as soil or groundwater contamination, exist on or around the above referenced property? Yes No If yes, please explain.
- Are there any solid or hazardous waste landfills in the vicinity of the above referenced property? Yes No
- Is there any chemical storage on the property? Yes No If yes, what kind?
- Are there any drinking water wells on or around the above referenced property? Yes No If so, are any known to be contaminated?

Please let me know if there are any costs associated with processing this request prior to processing. Your response can either be faxed or mailed to us at the location and/or fax number identified above. In addition, please indicate IVI's project number on all correspondence. Thank you in advance for your cooperation.

Michael Colombo
E:PROJECTS/E7092211@HOTCOM.POL

Facsimile Transmission

IVI Environmental, Inc.
105 Corporate Park Drive Suite 115
White Plains, New York 10604

Date: 22 October 1997
IVI Project No.: E7092211

FAXED

(518) 356-1980(tel)

(518) 356-1990(fax)

To: Eric Adams - Chief Fire Inspector
Guilderland Fire Inspectors Office - Town Hall

<input type="checkbox"/> New York (914) 694-9600 (tel)	<input type="checkbox"/> Washington, D.C. (201) 907-0163 (tel)	<input type="checkbox"/> Los Angeles (213) 896-0300 (tel)	<input type="checkbox"/> Miami (305) 358-1776 (tel)	<input type="checkbox"/> Paris 33.1.30.12.85.00 (tel)
(914) 694-8549 (fax)	(201) 907-3352 (fax)	(213) 896-0149 (fax)	(305) 372-0189 (fax)	33.1.30.12.86.66 (fax)

Freedom of Information Act Request

IVI Environmental, Inc. (IVI) has been retained to conduct a Phase I Environmental Site Assessment on:

Star Plaza
2050 Western Ave.
Guilderland, New York 12084

In accordance with the Freedom of Information Act, IVI is requesting information with respect to the above referenced property. Specifically, IVI is requesting the following information:

- Does your department have records of any active or inactive above or underground storage tanks at the above referenced property? Yes No If yes, please fill out the table below:

Above or Underground	Tank Size	Tank Contents	Tank Age	Active/Inactive

- Are you aware of any leaking above or underground storage tanks on or around the above referenced property? Yes No
- Do you have any records of hazardous, toxic, or flammable materials or wastes used or stored at the above referenced property? Yes No If yes, please list:
- Have you responded to hazardous materials spills on or around the above referenced property? Yes No If so, please explain:

• Are you aware of the property's historic usage? Yes No If yes, please indicate if it was residential, commercial, industrial, etc.
Please let me know if there are any costs associated with this request prior to processing same. Your response can either be faxed or mailed to us at the fax number and/or location identified above. In addition, please indicate IVI's project number on all correspondence. Thank you in advance for your cooperation.

Michael Colombo

Facsimile Transmission

IVI Environmental, Inc.
105 Corporate Park Drive Suite 115
White Plains, New York 10604

Date: 7 October 1997
IVI Project No.: E7992211

7 Oct 1997 (518) 433-3369(tel)

To: Mrs. Kullman
Niagra Mohawk Power Company - Guilderland Area (518) 433 3512(fax)

From: Michael Colombo (914) 694-9600(tel)
Project Manager (914) 694-3724(fax)

<input type="checkbox"/> New York	<input checked="" type="checkbox"/> Washington, D.C.	<input type="checkbox"/> Los Angeles	<input type="checkbox"/> Miami	<input type="checkbox"/> Paris
(914) 694-9600 (tel)	(301) 907-0163 (tel)	(212) 896-0300 (tel)	(305) 355-1776 (tel)	33.1.30.12.85.09 (tel)
(914) 694-8549 (fax)	(301) 907-3152 (fax)	(212) 896-0149 (fax)	(305) 373-0189 (fax)	33.1.30.11.86.86 (fax)

Information Request Form

IVI Environmental, Inc. (IVI) has been retained to conduct a Phase I Environmental Site Assessment

on: Star Plaza
2850 Western Ave.

Guilderland, New York
IVI is requesting information as it pertains to your company owned transformers on or adjacent to the above referenced site. Specifically, IVI is requesting the following information:

- Are there any of your company-owned transformers on the above referenced site? Yes No
If yes, please complete the following table (attach additional sheets if required).

Transformer No.	Non-PCB	PCB-Containing	PCB Contaminated	PCB Content Unknown

- Have there been any reported spills of transformer fluids on or around the above referenced site?
Yes No
- Is your company responsible for the maintenance of their transformers and remediation in the event of a leak? Yes No
- Will your company test the on-site transformers for PCB content? Yes No If so, what is the cost, if any?

Please let me know if there are any costs associated with processing this request prior to processing. Your response can either be faxed or mailed to us at the location and/or fax number identified above. In addition, please indicate IVI's project number on all correspondence. Thank you in advance for your cooperation.

Michael Colombo
K-PROJECTS-RESEARCHER FOR A GENERAL ELECTRIC POL