NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Primoshield Plating	Class: 4 Number: 633027			
O&M Funding Source: X State Superfund □ Fed	eral Superfund Municipal Responsible Party			
O&M Information: O&M Start: 12/98 End:	Annual Cost: \$ ☐ Estimated			
Interim Remedial Measures/Operable Units in O&M Phase □ Drum Removal X Soil Removal □ Cap/Cover □ Containment S X Groundwater Recovery/Treatment □ Leachate Colle □ Air Sparging/Stripper System □ Treatment/Filte X Other: Hazardous Material Removal	□ Tank Removal tructure X Fence/Security			
Institutional Controls: Deed Restriction Other: O&M Review Information:	scharge Permit Department of Health Sampling			
Reports: Semi-annual Groundwater Permit Reports: 5/31/99				
Quarterly Groundwater Monitoring Reports: quarterly Inspection: 4/13/99, 7/27/99, 10/28/99, 2/7/00 and 11/30/00	s ending 4/30/99, 7/30/99, 10/30/99, 2/7/00 and 11/30/00			
Sampling: 4/13/99, 7/27/99, 10/28/99, 2/7/00 and 11/30/00 Other:				
Conclusions:				
Remedy Effective? X Yes No:				
ROD Compliance? X Yes No:				
Consent Order Compliance? ☐ Yes ☐ No: there is no o	onsent order			
Other:				
Recommendations: The groundwater sampling regimen sho	Ild be reviewed and possibly changed to 5/4 sampling.			
ROD/Consent Order Modifications? X No	· · · · · · · · · · · · · · · · · · ·			
ability to reconnect them in the future if possible. Then the POTW sampling can resume. There is also a note in the files that says that once the drums are removed that we should consider disconnecting the phone because the drums failing is the biggest cause of high level alarms, but does the sump pump failure also cause high level alarms? When we consider shutting down the pump, we will need to consider possible impacts that the pumping has had on lowering gw levels, i.e., will basements get flooded when pump is off.				
Project Manager: 03/30/01 Signature Date Susan M. Lasdin, P.E. BHSC 518-457-0927 Name Region or Bureau Telephone	Reviewer: 03/30/01 Signature Date Gerald J. Rider, Jr., P.E., BHSC 518-457-0927 Name Region or Bureau Telephone			