


Figure 8

Primoshield, Inc.  
Site # 633027  
VOC Concentrations in MW 104



\*Note: For all sampling dates in question, individual VOC compounds were undetected in this well. Therefore, VOC levels in this well may exist below the detection limit of the instrument. It is important to note that the New York State Groundwater Standard for each individual VOC of concern is less than this detection limit. No samples were collected from MW 104 on 8/1/02.