

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96 10 01

Site Name: Endicott Village Landfill and Wellfield		Class: 2	Number: 7-04-008
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
O&M Information: O&M Start: 9701		End:	Annual Cost: \$ <input type="checkbox"/> Estimated
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover (Op Unit 2)	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input checked="" type="checkbox"/> Stripper System (Op Unit 1)	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input checked="" type="checkbox"/> Other: Operating a Supplemental Purge Well (Op Unit 3)			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input checked="" type="checkbox"/> Other: Record Of Decision (the third and final one) was signed 9/30/92 - calls for the capping of the landfill (Op Unit 2)			
O&M Review Information:			
Reports: <u>EPA is lead agency on this NPL Site. DEC received the 1997 monthly data reports for Supplemental Purge Well (Op Unit 3).</u>			
Inspection: <u>Region last inspected the site on January 25, 1997.</u>			
Sampling: <u>Supplemental Purge Well is sampled monthly. Ranney Well is sampled twice a month.</u>			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>The analytical results from the Supplemental Purge well have remained constant from 1996 to 1997.</u>			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>Any subsidence of the landfill cap has been acted on by Village of Endicott.</u>			
Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>Consent Order for construction of the Supplemental Purge Well was Signed by EPA, the Village of Endicott and two industrial RPs.</u>			
Other: <u>NPL Site.</u>			
Recommendations:			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes → Class: 4			
Comments:			
<u>OP Unit 1: Ranney Well - has Air Stripper. Levels of contamination at the Ranney Well are below the MCLs. Endicott asked EPA for permission to shut off air stripper (cost is \$30,000/yr). DEC studied analytical data and gave EPA its concurrence (01/08/97). EPA approved discontinuation of stripper on 2/18/97. Village is to still sample Ranney Well.</u>			
<u>OP Unit 2: Landfill - completed in the Fall of 1996.</u>			
<u>OP Unit 3: Supplemental Purge Well - this well was put in upgradient of the Ranney Well to reduce the amount of contaminated gw entering the Ranney Well. Receive monthly analytical reports on the water pulled from this well.</u>			
Project Manager:		Reviewer:	
<u>John R. Strang</u> 3/13/98		<u>Gerald J. Rider, Jr.</u> 3/13/98	
Signature Date		Signature Date	
John R. Strang Haz. Site Control (518) 457-0927		Gerald J. Rider, Jr. Haz. Site Control (518) 457-0927	
Name Region or Bureau Telephone		Name Region or Bureau Telephone	

Dickson Torrey