

**Inactive Hazardous Waste Site Operations and Maintenance Review Report**

Form Date 96.10.01

Site Name: Endicott Village Landfill and Wellfield		Class: 2	Number: 7-04-008
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
<b>O&amp;M Information:</b> O&M Start: 9701    End:    Annual Cost: \$ <input type="checkbox"/> Estimated			
Interim Remedial <b>Measures/Operable</b> Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover (Op Unit 2)	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input checked="" type="checkbox"/> Stripper System (Op Unit 1)	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input checked="" type="checkbox"/> Other: Operating a Supplemental Purge Well (Op Unit 3)			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input checked="" type="checkbox"/> Other: Record Of Decision #3 was signed 9130192 - calls for the capping of the landfill (Op Unit 2)			
<b>O&amp;M Review Information:</b> EPA is the Lead Agency for this NPL Site.			
Reports: <u>Receive quarterly Inspection Reports for the Landfill from the Village of Endicott (up to date).</u>			
The Village of Endicott is 9 months behind on reporting the Supplemental Purge Well (Op Unit 3) sampling data.			
Inspection: <u>Region last inspected the site on March 17, 1998.</u>			
Sampling: <u>None by DEC. Supplemental Purge Well is sampled quarterly. The Ranney Well continues to be operated.</u>			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>Supplemental Purge Well results have remained constant from 1996 thru 05199.</u>			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>Landfill Cap is being maintained by Village.</u>			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>Consent Order for construction of the Supplemental Purge Well was Signed by EPA, the Village of Endicott and two industrial RPs.</u>			
Other: <u>NPL Site.</u>			
Recommendations: <u>Sent letter to Village of Endicott Industrial Pretreatment Coordinator to ask whereabouts of missing Supplemental Purge Well data (attached). Have Region inspect site in calendar year 2000.</u>			
Next Review Report due <b>04/2001</b>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes → <b>Class: 4</b>			
Comments:			
<u>OP Unit 1: Ranney Well - has Air Stripper. DEC and EPA gave its approval to shutdown the air stripper in February 1997. The Village still operates the Ranney Well air stripper.</u>			
<u>OP Unit 2: Landfill - completed in the Fall of 1996.</u>			
<u>OP Unit 3: Supplemental Purge Well - this well was located upgradient of the Ranney Well to reduce the amount of contaminated GW that enters the Ranney Well. The Village sends quarterly analytical reports from the well to the EPA. The NYSDEC is to receive a copy of this report.</u>			
<b>Project Manager:</b>		<b>Reviewer:</b>	
<u>John R. Strang</u> <u>4/28/00</u>		<u>Gerald J. Rider, Jr.</u> <u>7/28/00</u>	
Signature    Date		Signature    Date	
John R. Strang    Haz. Site Control    (518) 457-0927		Gerald J. Rider, Jr.    Haz. Site Control    (518) 457-0927	
Name    Region or Bureau    Telephone		Name    Region or Bureau    Telephone	