

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Site Name: Conklin Dumps		Class: 4	Number: 704013
O&M Funding Source:	<input type="checkbox"/> State Superfund	<input type="checkbox"/> Federal Superfund	X Municipal <input type="checkbox"/> Responsible Party
O&M Information:	O&M Start: 1/96	End:	Annual Cost: \$ <input type="checkbox"/> Estimated
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
X Cap/Cover	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/treatment	X Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls:	<input type="checkbox"/> Deed Restriction	<input type="checkbox"/> Discharge Permit	<input type="checkbox"/> Department of Health Sampling
<input type="checkbox"/> Other:			
O&M Review Information:			
Reports: 1,2,3 & 4 Quarter Conklin Landfill MW sampling & analysis reports receive by this office.			
Inspection: Inspection made by this office 5/27/99.			
Sampling:			
Other:			
Conclusions:			
Remedy Effective? X Yes <input type="checkbox"/> No:			
ROD Compliance? X Yes <input type="checkbox"/> No:			
Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No:			
Other:			
Recommendations: Continue to monitor wells and collect & treat leachate. Continue to maintain landfill cap.			
ROD/Consent Order Modifications? <input type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: Total leachate collected in 1998 was 14,000 Gal. It was sent to the Binghamton - Johnson City Sewage Treatment Plant. Leachate samples were collected by the B.J.C. STP as part of their pretreatment program. The tank is half full now. No leachate seeps observed during my inspection. The sod cover appears to well maintained. No erosion noted. Fences and gates in tact and locked.			
Project Manager: <i>John A. May</i> Signature <i>John A. May / Env. Rem</i> Name Region or Bureau Telephone		Reviewer: Signature Date	