

2013 PERIODIC REVIEW REPORT (PRR) FORMER SCM – CORTLANDVILLE 839 NYS ROUTE 13 CORTLANDVILLE, NEW YORK 13045 SITE NO.: 712006

Prepared For:
New York State Department of Environmental Conservation
625 Broadway, BURE
Albany, New York 12233

Owner:
Cortland Commerce Center, LLC.
Attn: Mr. David Yaman
839 NYS Route 13
Cortland, New York 13045

Prepared By: GeoLogic NY, Inc. 37 Copeland Avenue P.O. Box 350 Homer, New York 13077

January 2014

GeoLogic Project No. 210087



TABLE OF CONTENTS

1	INTR	ODUCT	ΓΙΟΝ	1
	1.1	Summ	nary of Site	1
2	SITE	OVER\	VIEW	1
	2.1	Site Lo	ocation and Description	1
	2.2	Site H	listory	2
	2.3	Nature	e and Extent of Contamination	2
	2.4	Chron	ology of Site Remediation Activities	2
	2.5	Clean	up and Site Closure Criteria	4
3	INST	ITUTIOI	NAL AND ENGINEERING CONTROLS	4
	3.1	Summ	nary of Institutional Controls (IC's)	4
	3.2	Summ	nary of Engineering Controls (EC's)	4
		3.2.1	Summary of EC Operations During Reporting Period	5
4	MON	ITORIN	IG PLAN	6
	4.1	Monito	oring Plan Components	6
	4.2	Summ	nary of Monitoring Completed During Reporting Period	6
		4.2.1	Summary of Monthly Remediation System Sampling	6
		4.2.2	Summary of Annual Sampling Event	7
	4.3	Monito	oring Deficiencies	7
5	DATA	A TREN	IDS AND REMEDIAL EFFECTIVENESS	7
	5.1	Data S	Summary	7
	5.2	Reme	diation System Data Trends	8
	5.3	Groun	ndwater Quality Data Trends	8
	5.4	Perfor	rmance and Effectiveness of the IC's/EC's	9
	5.5	Conta	minant Mass Removal	10
6	REC	OMMEN	NDATIONS	10
7	REF	ERENC	ES	11
8	CER	TIFICAT	TION	12



APPENDICES:

APPENDIX A: Institutional and Engineering Controls Certification Forms

APPENDIX B: Drawings

Drawing 1: Site Location Plan;

Drawing 2: Monitoring Well Locations Plan;

Drawing 3: November 2013 Shallow Wells Groundwater Contours;

Drawing 4: November 2013 Deep Wells Groundwater Contours.

APPENDIX C: Tables

Table 1: Field Observations: 2013 Annual Groundwater Sampling Event;

Table 2: Summary of Groundwater Analytical Results;

Table 3: Monthly Analytical Results May 2001 – December 2013.

APPENDIX D: Charts

Charts 1 through 4: Remediation System TCE Concentrations;

Charts 5 & 6: TCE Concentrations in Perimeter Shallow Wells;

Charts 7 & 8: TCE Concentrations in Perimeter Deep Wells;

Charts 9 &10: TCE Concentrations in Interior Shallow Wells;

Charts 11 & 12: TCE Concentrations in Interior Deep Wells;

Chart 13: TCE Concentrations in Monitoring Well MW-L16;

Charts 14 & 15: 2011, 2012 & 2013 Recovery Well Pumping Rates & Groundwater Elevations

APPENDIX E: Analytical Results from 2013 Annual Sampling Event

APPENDIX F: SSD/SVE Data



2013 PERIODIC REVIEW REPORT FORMER SCM - CORTLANDVILLE 839 NYS ROUTE 13 CORTLANDVILLE, NEW YORK 13045 SITE NO.: 712006

1 INTRODUCTION

This report provides the basis for review and certification of the groundwater treatment system and the institutional and engineering controls (IC's/EC's) implemented at Site No. 712006. Signed Institutional and Engineering Controls Certification Forms are included in Appendix A.

The site is currently owned by Cortland Commerce Center, LLC (CCC) and this report is prepared and submitted at the direction of CCC, consistent with the Site's remedial program as approved by the New York State Department of Environmental Conservation (NYSDEC) and the New York State Department of Health (NYSDOH). The reporting period addressed in this report is January 1, 2013 to December 31, 2013.

1.1 Summary of Site

Former manufacturing activities at the site resulted in contamination of soil and groundwater with chlorinated organic solvents, primarily trichloroethylene (TCE) and its decomposition products. In 1986, the contaminant plume was found to extend approximately 1.5 miles downgradient (north) of the facility. The potential contaminant sources identified included a 3,000-gallon aboveground storage tank (AST) that formerly contained TCE, a 20,000-gallon underground storage tank (UST) that formerly contained tramp oil and four areas of stained surface soil associated with past material handling practices. Additionally, a former tumbling area was identified within the building footprint (adjacent to monitoring well MW-L16).

Remedial measures implemented at the site have included installing a soil vapor extraction (SVE) system and a groundwater pump and treat system. The SVE system was activated in 1990 and subsequently dismantled at an unknown date between 1996 through 1998. The groundwater remediation system is currently in operation. In June 1994, the Classification of the site was changed from 2 to 4 (site properly closed – required continued management).

2 SITE OVERVIEW

2.1 Site Location and Description

The site is located at 839 NYS Route 13, Town of Cortlandville, County of Cortland and State of New York (Appendix B, Drawing No. 1).

The site is approximately 47.4 acres in size and is developed with a one-story building occupying approximately 415,000 square feet. The building is utilized for office space, warehouse storage and manufacturing. The remainder of the site consists of employee

Page 2



parking areas, several small outbuildings, treated water infiltration lagoons and vacant undeveloped land.

The site is bordered on the north by Lime Hollow Road and a predominately residential area. It is bordered on the east by NYS Route 13 and a predominately commercial area. It is bordered on the south by a cemetery and the JM Murray Center (formerly part of the Smith Corona complex). It is bordered on the west by a mixture of undeveloped land, agricultural land and some residential properties.

2.2 Site History

The site was formerly owned and operated by Smith Corona Corporation (SCC), previously known as SCM Corporation (SCM). SCC utilized the site for the purposes of manufacturing typewriters. Trichloroethylene was used on the site by SCC during manufacturing processes.

In 1999, S. C. W. P., LLC (SCWP) purchased land and buildings from SCC and assumed operational responsibilities for the groundwater remediation system.

Cortland Commerce Center, LLC (CCC) purchased the site in May of 2010 from SCWP and assumed operational responsibilities for the groundwater remediation system.

2.3 Nature and Extent of Contamination

The site overlies the Otter Creek/Dry Creek aquifer. Town of Cortlandville municipal water wells are located approximately 2,300 feet west of the site and the City of Cortland municipal water wells are located approximately 1.5 miles north-northeast of the site.

In or around 1986 a plume of contaminated groundwater was detected during the investigation of an unrelated petroleum spill. This plume extended from the SCM site approximately 1.5 miles downgradient (generally north) toward the City of Cortland municipal well field. The contaminants in this plume were identified as (TCE) and related decomposition products.

In accordance with the 1989 Settlement Agreement, monitoring of off-site groundwater contamination has been conducted periodically by the NYSDEC, Cortland County Soil and Water Conservation District and the Cortland County Health Department.

2.4 Chronology of Site Remediation Activities

The remediation system, consisting of a recovery well, aeration tower, pipeline, rock cascade and an infiltration lagoon system, remains in place and has not been modified since its original construction.

A brief summary of the site remediation activities undertaken over the past 25 years is presented below¹:

Page 3



 October 1986 - March 1987: Use of TCE was discontinued. Various aboveground storage tanks (AST's) and underground storage tanks (UST's) containing TCE, tramp oil, fuel oil and muriatic acid were removed. Visibly contaminated soil encountered during the tank work was also removed. In addition, four areas of stained soil related to past material handling practices were excavated and disposed of off-site.

- January 1989: The Settlement Agreement for remediation of the site was signed between the NYSDEC, other parties, and SCC on January 12, 1989.
- September December 1989: Approval of the remediation Phase I design was obtained from the NYSDEC on September 22, 1989. Phase I consisted of investigation, design, construction and installation of a groundwater recovery well. The groundwater recovery well came on-line on December 29, 1989. The water from the recovery well was utilized for non-contact cooling purposes and discharged into an existing sewer line until the Phase II system could be completed.
- May 1990: Approval of the remediation Phase II design was obtained from the NYSDEC on May 29, 1990. Phase II included installation of a (SVE) System and groundwater remediation system. The groundwater remediation system consisted of an air stripping column (aeration tower), distribution piping (water from recovery well to the air stripper and from the air stripper to an infiltration lagoon) and an engineered infiltration lagoon.
- August 1990: The SVE system came on-line.
- October 1990: The groundwater remediation system came on-line.
- 1996-1998: At an unknown date, the SVE system was shutdown and decommissioned. GeoLogic has not located or reviewed documentation related to the shutdown of the SVE system.
- 1997-1998: At an unknown date, the well monitoring frequency was reduced to annual. GeoLogic has not located or reviewed documentation related to the modification of the sampling frequency.
- April 1999: SCWP purchased the SCC land and buildings and assumed operational responsibilities for the groundwater remediation system.
- May 2001: With the permission of the NYSDEC, the stripping tower blower was turned off. The influent TCE concentration had reduced to the point that the tower was able to reduce TCE levels adequately to meet discharge limits without forced airflow. Sampling frequency of the tower influent, tower discharge and outfall cascade was increased from quarterly to monthly.

Page 4



 May 2010: CCC purchased the SCWP land and buildings and assumed operational responsibilities for the groundwater remediation system.

2.5 Cleanup and Site Closure Criteria

The site-wide groundwater cleanup criteria for the site are the New York State Class GA groundwater quality standards. Currently, the standard for TCE is 5 µg/L.

All site wells are required to be monitored a minimum of annually until all wells meet the clean-up criteria. When all wells meet the clean-up criteria, the remediation system may be shut down.

Groundwater monitoring will continue for a period of five years after the remedial system is shut down. If at any time during the post-remediation monitoring period any of the samples exceed the site-wide clean-up criteria, the system will be restarted. For the first two years, post remediation monitoring will occur quarterly, then semi-annual for the next two years and finally once in the fifth year. If the remedial system must be restarted for any reason, the five year post shut-down monitoring program will be restarted once the site-wide cleanup criteria has been re-achieved.

3 INSTITUTIONAL AND ENGINEERING CONTROLS

Signed Institutional and Engineering Controls Certification Forms are included in Appendix A.

3.1 Summary of Institutional Controls (IC's)

No IC's are identified in the Settlement Agreement or Record of Decision.

3.2 Summary of Engineering Controls (EC's)

The EC's implemented at the site are described below:

 A groundwater remediation system consisting of an air stripping column (aeration tower), distribution piping (water from recovery well to the aeration tower and from the aeration tower to the infiltration lagoons) and engineered infiltration lagoons has been operating at the site since 1990.

Periodic monitoring of system performance is performed. The system must continue to operate until groundwater quality meets the clean-up criteria for the site. It should also be noted that although not required to be operated at present, the blowers (primary and back up) for the air stripper must remain in place and in good working order.



3.2.1 Summary of EC Operations During Reporting Period

Site Monitoring & Groundwater Treatment System

The groundwater remediation system has operated without major breakdown during this reporting period. The pump rate was checked during monthly sampling events and the average flow rate for the year was 717 gallons per minute (gpm), which meets the design standard of 700 to 1,000 gpm². Routine maintenance has been performed on system components on an as-needed basis. It is noted that all monthly average flow rates were within the design standard. Charts 14 and 15, located in Appendix D, depict a comparison of recovery well groundwater elevations and pumping rates for 2011, 2012 and 2013.

Both the primary and back-up blowers were energized and determined to be operational in December 2013.

During the annual sampling event, all wells (except MW-2D), were in good working order and able to be sampled. MW-2D remains blocked at a depth of 50 feet. It is likely that large gravel entered the well when it was originally damaged and that the gravel has become lodged in the well casing. Quarterly monitoring of well MW-10D continues to supplement the monitoring of conditions at the down gradient property boundary.

Sub-Slab Depressurization (SSD)/Soil Vapor Extraction (SVE) System

The sub-slab depressurization/soil vapor extraction system, installed in the vicinity of the former tumbling pit, has operated without major breakdown during this reporting period. The system consists of a single extraction point (well MW-L16) connected at a Gast Model R6P350A regenerative blower that extracts 218 cfm of vapor from under and around the former tumbling pit. Routine maintenance has been performed on system components on an as-needed basis.

A sample of the system emissions was obtained on November 26, 2013. The TCE concentration was reported at 10,000 μ g/m³. This is a 55.6% decline from the initial concentration of 18,000 μ g/m³ detected in the sample collected on January 10, 2012. The analytical results demonstrate that the system has been and remains effective in removing residual contamination from under and around the former tumbling pit. The SSD/SVE analytical results are included in Appendix F.



4 MONITORING PLAN

4.1 Monitoring Plan Components

Monitoring at the site consists of monthly sampling of the groundwater remediation system, quarterly monitoring of MW-10D and annual sampling of seventeen (17) groundwater monitoring wells (locations depicted on Drawing No. 2, Appendix B). Sampling events data trends and supporting charts are discussed in Section 5.

4.2 Summary of Monitoring Completed During Reporting Period

The following sampling events have taken place during this reporting period:

- Annual Sampling of Groundwater Monitoring Wells (11/25/2013 11/26/2013):
 - Interior Shallow Wells: MW-6, MW-7, MW-8, MW-11 and MW-12S;
 - Interior Deep Wells: MW-9 and MW-12D:
 - Perimeter Shallow Wells: MW-5S, MW-1S, MW-10S, MW-2S and MW-4S;
 - Perimeter Deep Wells: MW-4D, MW-5D, MW-1D and MW-10D;
 - Facility Well: MW-L16 (installed in 2008);
 - Quarterly Monitoring of MW-10D (February 2013, May 2013 and August 2013, plus annual sampling).
- Monthly Groundwater Remediation System (36 total samples in 2013):
 - Treatment System Influent (12 samples in 2013);
 - Tower Discharge (12 samples in 2013);
 - Cascade Outfall (12 samples in 2013).

All groundwater samples were submitted for analysis to Life Science Laboratories, Inc., LSL Central Lab located at 5854 Butternut Drive, East Syracuse, New York. The groundwater samples were analyzed for specific Volatile Organic Compounds (VOC's) (1,1,1-Trichloroethane, 1,1-Dichloroethene, 1,2-Dichloroethene, Trichloroethene, Tetrachloroethene and Vinyl Chloride) utilizing EPA Method 8260B.

4.2.1 Summary of Monthly Remediation System Sampling

Each month samples are collected at the Tower Influent, Tower Discharge and Cascade Outfall. The pumping rate is also recorded during each monthly sampling event. Samples are submitted for laboratory analysis, results are reviewed and monitoring reports are submitted to the NYSDEC and NYSDOH after each monthly sampling event.

Periodic Review Report - 2013 Former SCM - Cortlandville, Site No.: 712006

January 2014

Page 7



4.2.2 Summary of Annual Sampling Event

The depth to groundwater was measured in each of the seventeen (17) monitoring wells prior to collecting groundwater samples during the November 25, 2013 through November 26, 2013 annual sampling event. Based on recorded water levels, shallow and deep groundwater contour maps were prepared (Drawing No. 3 and No. 4, Appendix B). Generally, the groundwater flow under pumping conditions for the site was to the north-northwest; and was consistent with the previously reported flow direction. The recovery well continues to depress the water table sufficiently to influence groundwater flow at the site.

The field observations, including water levels, for the 2013 annual sampling event are summarized in Table 1, located in Appendix C.

Groundwater samples are submitted for laboratory analysis, results are reviewed and the results are detailed in the annual PRR for the site. The laboratory reports for the 2013 Annual Sampling event and the monthly monitoring results (for November and December 2013) are included in Appendix E.

The results for the annual sampling event have been up-loaded to the NYSDEC EQuIS database.

4.3 Monitoring Deficiencies

During the annual sampling event (November 25, 2013 through November 26, 2013) the following deficiencies were noted:

 Monitoring well MW-2D was unable to be sampled due to blockage within the well at a depth of about 50 feet.

5 DATA TRENDS AND REMEDIAL EFFECTIVENESS

5.1 Data Summary

Data from the annual groundwater sampling event and monthly remediation system sampling events are summarized in the following tables and charts and are included in Appendix C and Appendix D.

- APPENDIX C: Tables
 - Table 1: Groundwater Sampling Field Observations;
 - Table 2: Summary of Groundwater Analytical Results;
 - Table 3: Monthly Analytical Results May 2001 December 2013.



APPENDIX D: Charts

- Charts 1 through 4: Remediation System TCE Concentrations;
- Charts 5 & 6: TCE Concentrations in Perimeter Shallow Wells;
- Charts 7 & 8: TCE Concentrations in Perimeter Deep Wells;
- Charts 9 & 10: TCE Concentrations in Interior Shallow Wells;
- Charts 11 &12: TCE Concentrations in Interior Deep Wells;
- Chart13: TCE Concentrations in MW-L16.

The monitoring wells are categorized into four (4) groups (Perimeter Shallow, Perimeter Deep, Interior Shallow and Interior Deep). Charts 5 through 12 depict the TCE concentrations for both the last 10 years and 20 years for each well group (Appendix D).

It should also be noted that in 2008 monitoring well MW-L16 was installed and is located inside the facility adjacent to a former tumbling pit. The data from this well is included in Table 2, located in Appendix C. Chart 13 depicts the TCE concentrations detected in groundwater samples collected from MW-L16 (Appendix D).

5.2 Remediation System Data Trends

A total of twelve monthly sampling events have taken place during this reporting period. Sampling of the remediation system consists of collecting samples from three (3) locations: Cascade Outfall, Tower Discharge and Tower Influent. Charts 1 through 3, located in Appendix D, depict the TCE concentrations for each of the three sample locations. As indicated in Charts 1, 2 and 3 the TCE concentration at each of the sample locations exhibits a continued downward trend.

The average TCE concentrations for the 2013 samples are listed below:

Tower Influent: 8.56 μg/L
Tower Discharge: 3.44 μg/L
Cascade Outfall: 1.45 μg/L

5.3 Groundwater Quality Data Trends

Groundwater quality data trends are broken-down by the four groups of monitoring wells indicated below:

Perimeter Shallow Wells (MW-1S, MW-2S, MW-4S, MW-5S and MW-10S)

Four (4) of the five (5) perimeter shallow wells revealed TCE concentrations below the cleanup objective of 5 μ g/L. Well MW-10S, did not meet the cleanup objective (a TCE concentration of 6.76 μ g/L). 2013 year's results for all five (5) wells were similar to previous years and continue to indicate a long term downward trend. Charts 5 and 6, located in Appendix D, depict 10-Year and 20-Year TCE concentrations for the perimeter shallow wells.

Periodic Review Report - 2013 Former SCM - Cortlandville, Site No.: 712006

January 2014 Page 9 GeoLogic

Perimeter Deep Wells (MW-1D, MW-2D, MW-4D, MW-5D and MW-10D)

It should be noted that MW-2D could not be sampled due to a blockage. Three (3) of the four (4) perimeter deep wells sampled revealed TCE concentrations below the cleanup objective of 5 μ g/L. Well MW-10D, did not meet the cleanup objective (a TCE concentration of 6.85 μ g/L). 2013 year's results for all five (5) wells were similar to previous years and continue to indicate a long term downward trend. Charts 7 and 8, located in Appendix D, depict 10-Year and 20-Year TCE concentrations for the perimeter deep wells.

Interior Shallow Wells (MW-6, MW-7, MW-8, MW-11 and MW-12S)

Three (3) of the five (5) interior shallow wells revealed TCE concentrations below the cleanup objective of 5 μ g/L. Wells MW-6 and MW-12S, did not meet the cleanup objective (a TCE concentration of 6.54 and 32.20 μ g/L, respectively). 2013 year's results for all five (5) wells were similar to previous years and continue to indicate a long term downward trend. Charts 9 and 10, located in Appendix D, depict 10-Year and 20-Year TCE concentrations for the interior shallow wells.

• Interior Deep Wells (MW-9 and MW-12D)

Both of the interior deep wells revealed TCE concentrations below the cleanup objective of 5 μ g/L. Charts 11 and 12, located in Appendix D, depict 10-Year and 20-Year TCE Concentrations for the interior deep wells.

Overall the TCE concentrations detected in the wells continue to indicate a decreasing trend over a 20-year span since the current groundwater treatment system was activated.

5.4 Performance and Effectiveness of the IC's/EC's

The groundwater remediation system continued to be effective in 2013 as demonstrated by both the system operating conditions and the continued decreasing trend of TCE concentrations in the wells over time.

The groundwater pumping system was designed for:

Minimum Withdrawal Rate: 700 gpmMaximum Withdrawal Rate: 1,000 gpm

The average withdrawal rate for 2013 was 717 gpm. This is within the approved design operational range. Charts 13 and 14, located in Appendix D, depict a comparison of recovery well groundwater elevations and pumping rates for 2011, 2012 and 2013.

As stated in Section 5.3, contaminant concentrations have shown a declining trend over the past 20 years. This is particularly evident at the wells along Lime Hollow Road (the



downgradient side of the site (wells MW-1S & MW-1D, MW-2S & MW-2D, MW-4S & MW-4D, and MW-10S & MW-10D). In 1990, the highest yearly average concentration of TCE in these wells was observed at well cluster MW-10S & MW-10D, 76 μ g/L and 36 μ g/L respectively. Over the past three years (2011-2013), the highest average concentration of TCE has been 7.25 μ g/L at MW-10D. This represents a greater than 79% decline over the past 20 years.

Contaminant trends in the interior wells (MW-6, MW-7, MW-8, MW-9, MW-11, MW-12S and MW-12D) echo those along the downgradient boundary. The highest average TCE concentration in 1990 was 1,549 μ g/L at MW-11. Over the past three years, the highest average concentration has been 24.93 μ g/L at MW-12S. This represents a greater than 98% decline over the past 20 years.

Given the contaminant concentrations at the site have declined by more than 90% over the past 20 years, the system continues to be effective at removing contamination from the subsurface.

5.5 Contaminant Mass Removal

Using the following:

- Average pumping rate = 717 gpm
- Average influent concentration of TCE = 8.56 µg/L
- Density of TCE = 1.465 g/mL

The system removal rates for 2013 are:

- Total volume of water pumped = 376,855,200 gallons
- Total mass of TCE removed= 12.21 Kg or 26.92 lb.
- Total volume of TCE removed = 8.3 L or 2.2 gal.

6 RECOMMENDATIONS

It is recommended that the current monthly remediation system sampling, quarterly sampling of MW-10D and annual groundwater sampling be conducted for another year. In addition, an annual submission of Periodic Review Reports is thought to be adequate to document data trends at the site.

The distribution piping from the cascade to the lagoons will be inspected in the Spring of 2014. The need to scarify the lagoons will be assessed at that time.

The next annual sampling event is scheduled for November 2014. All seventeen (17) monitoring wells will be sampled.



7 REFERENCES

- ¹ 2009 Periodic Review Report, February 2010, Buck Engineering, LLC
- ² Remediation *System As-Built Report*, December 1991, O'Brien & Gere
- ³ Focused Feasibility Study, May 1988, O'Brien & Gere



8 CERTIFICATION

Signed Institutional and Engineering Controls Certification Forms are included in Appendix A.

We certify that to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in 312.10 of 40 CFR 312. We further certify this report to be factually presented to the best of our knowledge and belief.

Prepared by,

GeoLogic NY, Inc.

Senior Author

Forrest Earl

President / Principal Hydrogeologist


Senior Reviewer

Kenneth J. Teter, P.E./K. Teter Consulting, LLC

NYS LN 081583

TOP NEW YORK OF NE

\\GEO-SVR1\public\PROJECTS\2010\210087-CCC\REPORT\2013 Annual PRR\Periodic Review Report for CCC 2013 Text.DOC





Enclosure 2



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Site Management Periodic Review Report Notice
Institutional and Engineering Controls Certification Form

Sit	e No. 712006	Site Details	Box 1	
Sit	e Name SCM - Cortlandville			
Cit	e Address: 839 Route 13 South y/Town: Cortlandville unty: Cortland e Acreage: 47.3	Zip Code: 13045		
Re	porting Period: January 01, 2013 to	o January 01, 2014		
			YES	NO
1.	Is the information above correct?		×	
	If NO, include handwritten above of	or on a separate sheet.		
2.	Has some or all of the site propert tax map amendment during this R	y been sold, subdivided, merged, or undergone a eporting Period?		×
3.	Has there been any change of use (see 6NYCRR 375-1.11(d))?	e at the site during this Reporting Period		×
4.	Have any federal, state, and/or loc for or at the property during this Re	cal permits (e.g., building, discharge) been issued eporting Period?		×
		ns 2 thru 4, include documentation or evidenc reviously submitted with this certification form		
5.	Is the site currently undergoing de	velopment?		×
			Box 2	v.
			YES	NO
6.	Is the current site use consistent v Industrial	vith the use(s) listed below?	×	
7.	Are all ICs/ECs in place and function	ioning as designed?	X	
		R QUESTION 6 OR 7 IS NO, sign and date below THE REST OF THIS FORM. Otherwise continue.	and	
A	orrective Measures Work Plan mu	st be submitted along with this form to address	these is	sues.
COSC	nature of Owner, Remedial Party or I	Designated Representative Roate Port - JAN	232	014

GEOLOGI

SITE NO. 712006 Box 3

Description of Institutional Controls

Parcel

Owner

Institutional Control

95.00-10-01.100

David Yaman Realty Services

Site Management Plan

Decision Document (ROD), Site Management Plan (SMP).

Box 4

Description of Engineering Controls

Parcel

Engineering Control

95.00-10-01.100

Vapor Mitigation

Groundwater Treatment System Groundwater Containment

The ROD identified engineering controls required for OU1 (onsite). These controls include the continued operation and maintenance of the groundwater extraction & treatment system until groundwater quality meets the cleanup criteria of 5 ug/L for TCE for all wells.

The groundwater monitoring wells must be sampled at periodic intervals (currently annually). As outlined in 2001 correspondence, the groundwater extraction & treatment system may be operated without the blower component as long as effluent concentrations remain below 5 ug/L for TCE, and with monthly monitoring of the groundwater extraction & treatment system influent & effluent. The blower and a backup blower must remain in place and in working condition. The groundwater extraction system also acts as the onsite groundwater containment system, designed to eliminate contaminant migration offsite.

A Soil Vapor Extraction system was installed as part of the remedial program. The SVE was operational from August 1990 until operation was discontinued sometime after May 1994.

A sub-slab depressurization system (SSDS) is installed in portions of the main warehouse building in the area of the former Tumbling Pit. The SSDS is required to operate continuously.

Periodic Review Report (PRR) Certification Statements

1	Logrify	hu	checking	"VEC"	holow	that
1.	Certify	Dy	Checking	ILO	DEIOM	mal.

- a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;
- b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.

NO YES

X

- If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:
 - (a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;
 - (b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;
 - (c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;
 - (d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and
 - (e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.

NO

IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.

A Corrective Measures Work Plan must be submitted along with this form to address these issues.

IC CERTIFICATIONS SITE NO. 712006

Box 6

SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

print name print business address

am certifying as Presentative Form (Owner or Remedial Party)

for the Site named in the Site Details Section of this form.

Signature of Owner, Remedial Party, or Designated Representative Rendering Certification

For David Yaman, Pouter

IC/EC CERTIFICATIONS

Box 7

Professional Engineer Signature

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

print name at 32 CINTON ST. HOMER, NY. 130,77

am certifying as a Professional Engineer for the

Owner or Remedial Party)

Signature of Professional Engineer, for the Owner or Remedial Party, Rendering Certification

(Required for PE)

10. 081583

Date

Enclosure 1

Certification Instructions

I. Verification of Site Details (Box 1 and Box 2):

Answer the three questions in the Verification of Site Details Section. The Owner and/or Qualified Environmental Professional (QEP) may include handwritten changes and/or other supporting documentation, as necessary.

II. Certification of Institutional Controls/ Engineering Controls (IC/ECs)(Boxes 3, 4, and 5)

- 1.1.1. Review the listed IC/ECs, confirming that all existing controls are listed, and that all existing controls are still applicable. If there is a control that is no longer applicable the Owner / Remedial Party should petition the Department separately to request approval to remove the control.
- 2. In Box 5, complete certifications for all Plan components, as applicable, by checking the corresponding checkbox.
- 3. If you <u>cannot</u> certify "YES" for each Control listed in Box 3 & Box 4, sign and date the form in Box 5. Attach supporting documentation that explains why the **Certification** cannot be rendered, as well as a plan of proposed corrective measures, and an associated schedule for completing the corrective measures. Note that this **Certification** form must be submitted even if an IC or EC cannot be certified; however, the certification process will not be considered complete until corrective action is completed.

If the Department concurs with the explanation, the proposed corrective measures, and the proposed schedule, a letter authorizing the implementation of those corrective measures will be issued by the Department's Project Manager. Once the corrective measures are complete, a new Periodic Review Report (with IC/EC Certification) must be submitted within 45 days to the Department. If the Department has any questions or concerns regarding the PRR and/or completion of the IC/EC Certification, the Project Manager will contact you.


III. IC/EC Certification by Signature (Box 6 and Box 7):

If you certified "YES" for each Control, please complete and sign the IC/EC Certifications page as follows:

- For the Institutional Controls on the use of the property, the certification statement in Box 6 shall be completed and may be made by the property owner or designated representative.
- For the Engineering Controls, the certification statement in Box 7 must be completed by a Professional Engineer or Qualified Environmental Professional, as noted on the form.

APPENDIX B

DRAWINGS









GeoLogic


GeoLogic NY, Inc.

SITE LOCATION PLAN FORMER SCM-CORTLANDVILLE (SITE #: 712006) 839 NYS ROUTE 13 CORTLANDVILLE, NEW YORK

DRAWN BY:	SCALE:	PROJECT NO:
CTG	Not To Scale	210087
REVIEWED BY:	DATE:	DRAWING NO:
FCE	JAN. 2014	1







APPENDIX C
TABLES

TABLE 1. Field Observations: 2013 Annual Groundwater Sampling Event

Well#	CATEGORY	**TOP PVC ELEVATION	TOP PVC WATER LEVEL (FT)	GW ELEVATION	DEPTH OF WELL (FT)	VOLUME (GAL.) of WATER in WELL	APPROX. VOLUME PURGED (GAL.)	Notes
MW-1S	Shallow -Perimeter	1185.75	20.93	1164.82	39.50	2.97	10	Light brown.
MW-1D	Deep - Perimeter	1185.85	21.11	1164.74	70.50	7.90	25	Clear.
MW-2S	Shallow -Perimeter	1210.91	46.10	1164.81	70.20	3.86	12	Light brown.
MW-2D	Deep - Perimeter	N/A	-	-	104.00	-	-	No sample, well damaged.
MW-4S	Shallow -Perimeter	1209.72	44.64	1165.08	73.79	4.66	15	Light brown.
MW-4D	Deep - Perimeter	1210.14	45.40	1164.74	104.23	9.41	30	Clear.
MW-5S	Shallow -Perimeter	1178.46	12.88	1165.58	40.00	4.34	15.0	Clear.
MW-5D	Deep - Perimeter	1178.86	13.91	1164.95	71.88	9.28	30	Clear.
MW-6	Shallow - Interior	1211.42	44.22	1167.20	56.50	1.96	6.1	Brown, turbid.
MW-7	Shallow - Interior	1211.56	45.13	1166.43	58.75	2.18	7.2	Dark brown, turbid.
MW-8	Shallow - Interior	1212.76	45.53	1167.23	61.42	2.54	7.7	Brown.
MW-9	Deep - Interior	1212.94	46.85	1166.09	100.46	8.58	26	Clear.
MW-10S	Shallow -Perimeter	1207.23	42.52	1164.71	62.00	3.12	10	Light brown.
MW-10D	Deep - Perimeter	1207.52	42.92	1164.60	99.00	8.97	30	Clear.
MW-11	Shallow - Interior	1214.44	47.80	1166.64	59.50	1.87	7.20	Dark brown, turbid. Sheen.
MW-12S	Shallow - Interior	1212.94	47.08	1165.86	62.00	2.39	7.2	Dark Brown, turbid.
MW-12D	Deep - Interior	1212.80	47.23	1165.57	89.00	6.68	20	Clear.
MW-L16	Shallow	1212.99	45.50	1167.49	60.00	2.32	7	Dark brown, turbid.
Piezometer	Shallow	1212.59	47.66	1164.93				No sample, water level only.
Recovery Well	Shallow & Deep	1205.62	42.35	1163.27	94.00			No sample, water level only.

N/A = Not available, well casing have been damaged or modified.



^{**} Top of PVC elevations were determined from survey by Jim Stockwin, LS, 2006.

		Feb-90) Aug-90 Nov-9	0 Feb-91	May-91 Aug-9	1 Nov-91 Feb-9	2 May-92 Aug-9	2 Nov-92 Feb-93	3 May-93	Aug-93 Nov-93	Feb-94 J	un-94 S	Sep-94 De	c-94 Feb-95	May-95	Nov-95 May	y-96 Nov-96	May-97 Nov-	-97 May-	98 Nov-98 Aug	-99 Ja	an-00 Nov-01 Nov-02 Jun-	03 Nov-03	Nov-04	Dec-05	Sep-06 Nov-06	May-07	Nov-07 Nov-08	Nov-09 Dec-10 Nov-11 Nov-12 Nov-13
MW-1S	TCE	<1	1 47 4	1 25	17 1	9 12	9 13 1	5 2 1 ⁻	1 26	3 13	3 7	19	13	9 11	1 8	11	5 8	10	11	15 8	7	5 6 8		6 11	6	7 4	1 3	2 5	4 4.20 5.40 5.46 4.69
	TCE Yearly Ave. Total VOC's	<1	3 47 4		21 2	18 3 13	9 15 1	10 7 2 1;	3 34	3 13	3 7	22	15	13 9 13	3 8	10 11	5 8	10	11	12 16 8	7	5 6 8 5 6 8		5 11 5 11	6 6	7 4	3	2 5	4 4.20 5.40 5.59 4.82 J
MW-1D	Total VOC Yearly Ave.		3	2		21		11		16	6			13		11	7		11	12	7	5 6 8		5 11	6	4	l l		
11111-115	TCE	32		5 25	18 1	9 12 1	3 13 1	4 13 14	4 13	12 16	12	13	9	11 12 11	2 12	13	7 10	7	8	7 7	8	3 3 1		2 3	5	NS 3	NS NS	4 5	4 2.70 4.40 5.65 3.49
	TCE Yearly Ave. Total VOC's	32		5 25	24 2	4 12 1	3 14 1	6 15 16	6 16	115 17	13	13	10	13 14	1 14		7 11	7	8	7 7	8	3 3 3		2 3	5	3	3	4 5	4 2.70 4.40 5.85 3.60 J
MW-2S	Total VOC Yearly Ave.		2	1		21		15		16	5			12		14	٩		8	/	8	3 3 3	;	2 3	5	3	3		
	TCE TCE Yearly Ave.	4	5	6 8 5	6	8 10	5 7	5 5 5	5 7	7 4	4	4	3	4 4	1 4	NA 4	4 NA	3	NA 3	4 NA 4	4	2 2 2 2 2 2		2 2	2	2 2	2 3	2 2	2 1.70 1.80 1.66 1.48
	Total VOC's Total VOC Yearly Ave.	4	1 5	6 8 5	6	8 12	5 7	8 5 5	5 7	7 4	4	4	3	4 4	1 4	NA 3	4 NA	3	NA 3	4 NA 4	4	2 2 2		2 2	2	2 2	3	2 2	2 1.70 1.80 1.66 1.48
MW-2D																													
	TCE TCE Yearly Ave.	6	9	8 7 7	5	7 9 7	5 5	5 5 5	3 4	6 3	3	2	3	3 2	2 3	NA 3	2 NA	2	NA 2	1 NA	3 Dam 3 Dam	maged Damaged Damaged maged Damaged Damaged	Damage	Damaged I	Damaged Damaged	NS NS	NS NS	NS NS	NS NS NS NS
	Total VOC's	6	9	8 7	5	7 10	5 5	5 5 5	3 4	6 3	3	2	6	2 2	2 3	NA	2 NA	2	NA	1 NA	3 Dam	naged Damaged	Damage	Damaged I	Damaged				
MW-3	Total VOC Yearly Ave.			1		1		5		-				3		2	2		2	1	3 Dam	maged Damaged Damaged	Damage	Damaged I	Damaged				
	TCE TCE Yearly Ave.	<1		1 <1	<1 <	1 <1 <	1 <1 <	1 <1	1 <1	<1 <	<1	4	<1	<1 <1 1	1 <1	NA 1	19 NA		<1 1	8 NA 8	<1 <1	<1 <1 <1 <1 <1 <1		2 1	<1 <1	NS 2	NS NS	<1 NS	NS NS NS NS
	Total VOC's Total VOC Yearly Ave.	<1		1 <1	<1 <	1 <1 <	1 <1 <	1 2	1 <1	<1 <	<1	4	<1	<1 <1	1 <1	NA 0	33 NA 33		<1		<1 <1	<1 <1 <1 <1 <1 <1		3 1	2	5 5	5	<1	
MW-4S				2 .4		2 1	4 4	1 1	1 1	.4	NA	.4	-4	.1 .1		NA		.1	NA		.1	4 4 4			.4	.1 .1		.4 .4	4 4 064 046 1
	TCE Yearly Ave.	<1	S	1		2 1 <		1 1	1	<1 <) INA	<1	<1	<1 <1 0		NA 1	<1 NA	<1	0		<1	<1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <	<	1 <1	<1	<1 <1 <1		<1 <1 ·	<1 <1 <1 0.61 0.46 J
	Total VOC's Total VOC Yearly Ave.	<1	<1	∠ <1 1	1	2 1 <	1	1 1 <	1 1	<1 <	NA)	<1	<1	<1 <1 0	1	NA 0	<1 NA	<1	NA 0		<1 <1	<1 <1 <1 <1 <1	<	1 <1 1 <1	<1 <1	<1 <1 <1		<1 <1	<1 <1 <1 0.61 0.46 J
MW-4D	TCE	<1	1 1 <	1 1	<1	1 1 <	1 <1 <	:1 <1 <	1 <1	<1 <	NA	<1	<1	<1 <1	l <1	NA	<1 NA	<1	NA	<1 NA	<1	<1 <1 <1	<	1 <1	<1	NS <1	NS	<1 <1	<1 <1 <1 0.46 0.38 J
	TCE Yearly Ave. Total VOC's	c1	1 1 2	1 1	<1	1 1 <	1 <1 <	0 <1 <1 <	1 <1	<1 <	NA NA	<1	<i>c</i> 1	0 <1 <1	1 <1	1 NA	<1 NA	<1	0 NA	0 <1 NA	<1 <1	<1 <1 <1 <1 <1	<	1 <1	<1 <1	<1 <1		<1 <1	<1 <1 <1 0.46 0.38 J
MW-5S	Total VOC Yearly Ave.	1		1		1		0		11	0	- 1		0	1	0	- C	- 1	0		<1	<1 <1 <1	<	1 <1	<1	<1		- 1	41 41 6116 6166
IVIVV-33	TCE	1	2	3 <1	1	2 <1 <	1 <1 <	:1 <1 <	1 <1	<1 <	<1	<1	<1	<1 <1	1 <1	NA	<1 NA	<1	NA		<1	<1 <1 1		1 2	1	2 1	1	<1 <1	<1 <1 1.00 0.72 0.91
	TCE Yearly Ave. Total VOC's	1	3	3 <1	1	2 <1 <	1 <1 <	1 <1 <	1 <1	<1 <	<1	<1	<1	<1 <1	1 <1	NA.	<1 NA	<1	NA		<1 <1	<1 <1 1 <1 <1 2		1 2	1	2 1	1	<1 <1	<1 <1 1.00 0.72 0.91
MW-5D	Total VOC Yearly Ave.			2		1		0		(0		0			0	0	<1	<1 <1 2		1 2	1	1			
	TCE TCE Yearly Ave.	2	2 3	5 3	3	3 1 <	1 1	2 1 <	1 2	2 <	<1	<1	<1	<1 <1 0	1 1	NA 1	2 NA	2	NA 2		<1 <1	<1 <1 1 <1 <1 1		1 2	1	NS 1	NS	<1 2	1 1.10 1.30 1.62 1.17
	Total VOC's Total VOC Yearly Ave.	2	2 8	5 3	3	3 1 <	1 1	2 1 <	1 2	2 <	<1	<1	<1	<1 <1	1 2	NA 1	2 NA	2	NA 2	<1 NA	<1 <1	<1 <1 2 <1 <1 2		1 2	1	1		<1 2	1 1.10 1.30 1.62 1.17
MW-6	TOF	N/A	42 2	<i>E</i> 20	62	0 NA 4	0 20 4	10 24 2	1 70	22 40	45	F0	20	47 40	14		24 44	10	7	.1 10	-	44 44 44	1	20	45	NC 0	NC NC	10 6	5 25 00 0 00 2 20 6 54
	TCE Yearly Ave.	NA NA	3		62	8 NA 1	0 30 4	27	1 70	32 18	45	50	20	33	14	13	24 24		13	5	5	11 4 14	1	5 20	15	NS 0	B 1N5	10 6	5 35.00 8.60 2.29 6.54
	Total VOC's Total VOC Yearly Ave.	INA	43 3	5 38 6	02	8 NA 1	8 30 4	27 27	1 70	32 18	9 45	50	20	33	14	13	34 14		13	5	5	11 4 15	1	5 20	15	8	3	10 6	5 35.00 8.60 2.29 6.54
MW-7	TCE	290	, ,,,	3 190	57 1	9 NA 1	1 57 13	30 130 120	0 67	25 18	8 85	60	49	49 45	5 23	NA	56 NA		NA	26 NA	24	24 12 4		9 5	19	NS 6	s NS	8 3	2 6.40 7.20 2.14 3.08
	TCE Yearly Ave. Total VOC's	290	16	8 3 190	157 3	89 0 NA 1	5 167 25	82 50 250 175	5 136	25 19	9 137	153	84	61 82 84	1 25	NA NA	73 NA		25 NA	26 39 NA	31	24 12 4 30 23 5	1:	5 5	19 30	8	8	8 3	2 6.40 7.20 2.24 3.08
MW-8	Total VOC Yearly Ave.		16	8		94		171		89				114		55	73		35	39	31	30 23 5	1:	5	30	8	3		
	TCE TCE Yearly Ave.	70	10 4	8 31	110	8 3 3	1 31 4	16 12 32	2 14	18 10	61	11	10	12 9 24	8	3	98 6	8	2	10 3	2	2 <1 2		3 5	3	NS 3	NS NS	3 5	2 41.00 2.50 1.01 1.72
	Total VOC's Total VOC Yearly Ave.	70	10 4	8 31	110	8 3 3	1 31 4	8 16 12	2 14	18 10	61	11	10	12 9	8	3	98 6	8	2	10 3	2	2 <1 2		3 5	3	3	3	3 5	2 41.00 2.50 1.01 1.72
MW-9		- 10	10			00		02						27			10								Ů		1		
	TCE TCE Yearly Ave.	16	5 5 1	9	11	3 4	3 3	4 4 4	4 33	12	2	24	5	9	5	<1 3	18 2		1	<1 5	7	5 4 5		7 17	6	NS 11			
	Total VOC's Total VOC Yearly Ave.	16	5 5 1	9	14	6	3 3	4 4 4	4 42	8 14	1	24	5	9	5	<1 3	22 2	1	<1 1	<1 5	7	5 4 5		7 17 7 17	6	12 12		5 <1	<1 <1 <1 0.86 0.54
MW-10S	TCE	73		9 63	27 3		4 170 4	0 32 20	6 25		7 28	31	24	15 16	16	23	17 18	13	13	15 19	16	17 9 19	1	10	10	NS 7	6	8 6	7 6.70 5.80 6.56 6.76
	TCE Yearly Ave. Total VOC's	73	3 110 5	6 9 110	33 4	43 4 62 5	7 228 4	72 6 37 29	9 32	37 3		31	27	25 16 17	7 18		18 20		13 13	18 17 19	16 17	17 9 19 17 9 21	11	10	10 11		7 6	8 6	7 6.70 5.80 6.83 7.10 J
MW-10D	Total VOC Yearly Ave.		7	6		62		92		32				26		20	19		13	18	17	17 9 21	11	10	11	7			
100	TCE TCE Yearly Ave.	23		0 33	54 3	1 40 3	0 10 4	37 33	2 19	32 25	21	21	22	22 30 23	23	19 24	10 16	12	18	10 20 15	13	11 8 7		3 5	5	NS 6		6 7	8 4.70 5.40 9.49 6.85 6.67 5.90
	Total VOC's	23	3 33 6	0 33	66 3	9 45 3	5 12 4	6 43 36	6 21	32 28	3 22	21	25	24 32	2 26		10 16		18	10 20	13	11 8 7		3 5	5	6	6	6 7	8 4.70 5.40 9.75 7.02 J
MW-11	Total VOC Yearly Ave.		3					34		29				23		26	13		15		13	11 8 7		5	5				6.77 6.02 J
	TCE TCE Yearly Ave.	2600	154	9	290 3	1 NA 5	0 420 2	29 <50 54 125	4 170	56	S	<50	51	51 42 44	2 38	19 33	170 85 128		10 28	27 11 19	14 14	5 7 6 5 7 6	2	1 11	12 12	NS 18		8 6	6 38.00 15.00 4.32 3.60
	Total VOC's Total VOC Yearly Ave.	2600) 44 340 154		5090 14	1 NA 44 1428	0 630 37	75 230 344 419	4 1170	1700 <50 804		1260	105	130 101 639	1 87	144 111	300 415 358		41 69	49 11 30	35 35	5 31 6 5 31 6	4:	9 11				8 6	6 81.00 15.00 5.28 4.14 J
MW-12S	TCE	190	280 12	0 270	190 10	0 21 4	6 50 15	50 140 150	0 150	180 100	110	170	88	88 100) NA	24	82 60	82	11	80 23	11	59 10 44	6	2 46	27	NS 44		25 17	12 22.00 37.00 5.60 32.20
	TCE Yearly Ave. Total VOC's	190	20	3	330 13	145		97		180 109	5	192	99	114 102 101		62	93 73		47	52	11	59 10 44 59 10 46	6	2 46	27	44	ļ.	25 17	
BMA/ 405	Total VOC Yearly Ave.	190	200 12		330 13	190	02 18	130	_ 103	160 100		132	33	128	. INA	56	93 73		50	63	11	59 10 46	6	7 49				20 17	12 20.10 01.00 0.10 02.00
MW-12D	TCE	21		3 17	12 1	2 13 1	0 45 1		3 11	15 8	3 7	16	9	5 7	7 6	6	5 5	5	4	2 8	11	8 10 5		1 10	3	NS 6	6	4 3	2 1.70 <1 2.86 1.51
	TCE Yearly Ave. Total VOC's	21	17 2	9 3 17	14 1	14 2 13 1	1 52 1	19 2 9 1;	3 13	15 8	3 7	16	9	9 5 7	7 6	6	5 5	5	5 4	2 8	11 12	8 10 5 8 12 7		1 10 1 10	3	6	6	4 3	2 1.70 <1 2.86 1.51
MW-L16	Total VOC Yearly Ave.		1	9		14	1 1	21		12				9		6	5		5	5	12	8 12 7	+	1 10	3	6	6		
2.0	TCE TCE Yearly Ave.	1																										41	20 14.00 3.50 1.95 1.69
	Total VOC's Total VOC Yearly Ave.																		+		#							42	21 14.00 3.50 1.95 1.69
	Total VOC Teally Ave.	1		1 1	<u> </u>	<u> </u>		1 1	1 1	L	<u> </u>		l		1	l l				1 1				1 1	Į.	1		1	



Table 2: Page 2 of 2 Summary of Groundwater Analytical Results

		May-96	Nov-96	May-97 No	v-97 May-	98 No	v-98 Aug-	99 No	ov-00	Nov-01	Nov-02	Jun-03	3 Nov	/-03 N	lov-04	Dec-05	Sep-06	Nov-06	May-07	Nov-07	Nov-08	Nov-09	Dec-10	Nov-11	Nov-12 Nov-
MW-BE1			1 1	<u> </u>			<u> </u>					Ī	T									<u> </u>			
AIAA-DE I	TCE							-1	NA	NA	NA	<1	1	NA	NA	NA									
	TCE Yearly Ave.		+ +					<1 <1	NA	NA	NA NA			NA	NA	NA									
	Total VOC's		+					<1	NA	NA	NA NA			NA	NA										
	Total VOC Yearly Ave.							<1	NA	NA	NA NA			NA	NA										
/IW-BE2	Total VOC Tearly Ave.							<u> </u>	INA	INA	INA		'	INA	INA	INA									
	TCE		+					<1	NA	NA	NA	<1	1	NA	NA	NA									
	TCE Yearly Ave.		+					<1	NA	NA	NA	<1		NA	NA	NA									
	Total VOC's							<1	NA	NA	NA			NA	NA										
	Total VOC Yearly Ave.							<1	NA	NA	NA			NA	NA										
EC-23								1					-												
	TCE																<1		<1						
	Total VOC's																<1		<1						
EC-24	Total VOC 0																								
	TCE												1				NS		<1						
	Total VOC's																NS		<1						
EC-25																									
	TCE																2.3		2.2						
	Total VOC's																2.3		2.2						
EC-26																									
	TCE																9.9		NS						
	Total VOC's																9.9		NS						
EC-27																					ļ				
	TCE																4.7		NS						
	Total VOC's																4.7		NS						
EC-28																									
	TCE																3.5		NS						
	Total VOC's																3.5		NS						
EC-29																									
	TCE																2.4		NS						
	Total VOC's																2.4		NS						
DEC-30																									
	TCE		+ +														1.4		1.2						
	Total VOC's																1.4		1.2						
	Notes:		+	<u>J</u>		<u> </u>										<u> </u>									
	NS = Not Sampled.																								
	1. Units are μg/L.																								
	2. Well L16 was construc	cted inside th	ne building o	on 12/5/08.																					
	3. All data prior to 2010 p	provided to C	SeoLogic N	Y. Inc. by Bu	ck Enginee	ina. LL	.C.																		
				.,,																					



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
5/17/2001	Trichloroethene	19.0	7.6	5	3.5
3/17/2001	Total VOC's	19.0	7.6		3.5
6/4/2001	Trichloroethene	14.0	5.6	5	2.3
0/4/2001	Total VOC's	14.0	5.6		2.3
7/10/2001	Trichloroethene	9.7	3.5	5	1.8
7710/2001	Total VOC's	9.7	3.5		1.8
8/2/2001	Trichloroethene	13.0	5.4	5	3.0
0/2/2001	Total VOC's	13.0	5.4		3.0
9/7/2001	Trichloroethene	8.3	1.7	5	1.4
3/1/2001	Total VOC's	8.3	1.7		1.4
10/9/2001	Trichloroethene	8.0	ND<1	5	ND<1
10/9/2001	Total VOC's	8.0	ND<1		ND<1
11/13/2001	Trichloroethene	6.0	1.9	5	ND<1
11/13/2001	Total VOC's	6.0	1.9		ND<1
12/13/2001	Trichloroethene	5.7	2.6	5	1.2
12/13/2001	Total VOC's	5.7	2.6		1.2
1/9/2002	Trichloroethene	6.6	3.0	5	1.3
1/9/2002	Total VOC's	6.6	3.0		1.3
2/15/2002	Trichloroethene	9.4	2.6	5	1.6
2/15/2002	Total VOC's	10.6	2.6		1.6
3/8/2002	Trichloroethene	9.9	5.7	5	2.1
3/6/2002	Total VOC's	9.9	5.7		2.1
4/2/2002	Trichloroethene	11.0	4.4	5	2.2
4/2/2002	Total VOC's	11.0	4.4		2.2
5/1/2002	Trichloroethene	13.0	6.7	5	3.4
5/1/2002	Total VOC's	14.1	6.7		3.4
6/24/2002	Trichloroethene	14.0	4.7	5	3.4
0/24/2002	Total VOC's	14.0	4.7		3.4
7/9/2002	Trichloroethene	4.3	1.6	5	ND<1
1/9/2002	Total VOC's	4.3	1.6		1.3
8/12/2002	Trichloroethene	16.0	5.9	5	3.1
0/12/2002	Total VOC's	16.0	5.9		3.1
9/9/2002	Trichloroethene	12.0	3.9	5	1.8
3/3/2002	Total VOC's	12.0	3.9		1.8
10/2/2002	Trichloroethene	11.0	4.1	5	1.3
10/3/2002	Total VOC's	11.0	4.1		1.3
11/11/0000	Trichloroethene	10.0	4.3	5	2.0
11/14/2002	Total VOC's	10.0	4.3		2.0
10/04/0000	Trichloroethene	12.0	5.1	5	2.0
12/31/2002	Total VOC's	12.0	5.1		2.0



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
1/13/2003	Trichloroethene	13.0	5.8	5	2.1
1/13/2003	Total VOC's	13.0	5.8		2.1
2/19/2003	Trichloroethene	14.0	5.1	5	2.1
2/13/2003	Total VOC's	14.0	5.1		2.1
3/12/2003	Trichloroethene	14.0	5.9	5	2.2
3/12/2003	Total VOC's	14.0	5.9		2.2
4/9/2003	Trichloroethene	18.0	8.0	5	3.1
4/9/2003	Total VOC's	18.0	8.0		3.1
5/2/2003	Trichloroethene	16.0	5.8	5	3.0
5/2/2003	Total VOC's	16.0	5.8		3.0
0/00/0000	Trichloroethene	18.0	7.2	5	3.4
6/20/2003	Total VOC's	18.0	7.2		3.4
7/4/0000	Trichloroethene	16.0	5.8	5	2.4
7/1/2003	Total VOC's	16.0	5.8		2.4
2/1//2222	Trichloroethene	14.0	4.7	5	2.4
8/14/2003	Total VOC's	14.0	4.7		2.4
	Trichloroethene	9.6	3.5	5	1.8
9/11/2003	Total VOC's	9.6	3.5		1.8
	Trichloroethene	12.0	5.5	5	2.4
10/2/2003	Total VOC's	12.0	5.5		2.4
	Trichloroethene	10.0	1.1	5	1.4
11/24/2003	Total VOC's	10.0	1.1		1.4
	Trichloroethene	13.0	6.5	5	3.0
12/3/2003	Total VOC's	13.0	6.5		3.0
	Trichloroethene	12.0	6.4	5	3.0
1/5/2004	Total VOC's	12.0	6.4		3.0
	Trichloroethene	14.0	7.0	5	3.1
2/2/2004	Total VOC's	14.0	7.0		3.1
	Trichloroethene	13.0	4.8	5	2.0
3/1/2004	Total VOC's	13.0	4.8		2.0
	Trichloroethene	16.0	6.0	5	2.7
4/2/2004	Total VOC's	16.0	6.0		2.7
	Trichloroethene	14.0	5.3	5	2.5
5/6/2004	Total VOC's	14.0	5.3		2.5
	Trichloroethene	12.0	4.9	5	2.5
6/3/2004	Total VOC's	12.0	4.9		2.5
	Trichloroethene	13.0	4.6	5	2.0
7/1/2004	Total VOC's	13.0	4.6		2.0
	Trichloroethene	12.0	4.7	5	1.9
8/17/2004	Total VOC's	12.0	4.7		1.9



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
0/7/0004	Trichloroethene	11.0	3.9	5	1.5
9/7/2004	Total VOC's	11.0	3.9		1.5
10/10/0001	Trichloroethene	12.0	2.2	5	2.1
10/18/2004	Total VOC's	12.0	2.2		2.1
44/40/0004	Trichloroethene	13.0	4.6	5	2.2
11/18/2004	Total VOC's	13.0	4.6		2.2
40/0/0004	Trichloroethene	11.0	2.8	5	1.3
12/8/2004	Total VOC's	11.0	2.8		1.3
4/44/0005	Trichloroethene	13.0	6.5	5	2.7
1/11/2005	Total VOC's	13.0	6.5		2.7
0/0/0005	Trichloroethene	9.0	5.0	5	2.0
2/8/2005	Total VOC's	9.0	5.0		2.0
2/2/2025	Trichloroethene	13.0	3.3	5	1.6
3/3/2005	Total VOC's	13.0	3.3		1.6
4/4/0005	Trichloroethene	15.0	6.2	5	2.2
4/4/2005	Total VOC's	15.0	6.2		2.2
E/E/200E	Trichloroethene	11.0	4.5	5	1.9
5/5/2005	Total VOC's	11.0	4.5		1.9
6/0/2005	Trichloroethene	5.6	2.4	5	1.0
6/8/2005	Total VOC's	5.6	2.4		1.0
7/11/2005	Trichloroethene	12.0	4.3	5	2.0
7/11/2003	Total VOC's	12.0	4.3		2.0
8/1/2005	Trichloroethene	9.9	3.5	5	1.7
0/1/2000	Total VOC's	9.9	3.5		1.7
9/6/2005	Trichloroethene	7.2	2.8	5	1.1
0,0,200	Total VOC's	7.2	2.8		1.1
10/14/2005	Trichloroethene	6.0	2.3	5	ND<1
	Total VOC's	6.0	2.3		ND<1
11/18/2005	Trichloroethene	7.1	3.2	5	1.2
	Total VOC's	7.1	3.2		1.2
12/5/2005	Trichloroethene	7.4	3.1	5	1.2
	Total VOC's	7.4	3.1		1.2
1/3/2006	Trichloroethene	8.9	4.0	5	1.5
	Total VOC's	8.9	4.0	+	1.5
2/2/2006	Trichloroethene	9.5	4.0	5	1.7
	Total VOC's	9.5	4.0		1.7
3/20/2006	Trichloroethene	9.2	1.6	5	1.1
	Total VOC's	9.2	1.6		1.1
4/19/2006	Trichloroethene	10.0	4.0	5	1.6
	Total VOC's	10.0	4.0		1.6
5/4/2006	Trichloroethene	10.0	3.9	5	1.7
. , , , ,	Total VOC's	10.0	3.9		1.7



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
6/2/2006	Trichloroethene	9.6	3.6	5	1.7
0/2/2000	Total VOC's	9.6	3.6		1.7
7/6/2006	Trichloroethene	10.0	4.0	5	1.8
7/0/2000	Total VOC's	10.0	4.0		1.8
8/4/2006	Trichloroethene	10.0	4.2	5	1.7
0/4/2000	Total VOC's	10.0	4.2		1.7
9/5/2006	Trichloroethene	11.0	4.4	5	1.8
9/3/2000	Total VOC's	11.0	4.4		1.8
10/5/2006	Trichloroethene	11.0	4.4	5	1.8
10/3/2000	Total VOC's	11.0	4.4		1.8
11/20/2006	Trichloroethene	10.0	4.2	5	1.9
11/20/2000	Total VOC's	10.0	4.2		1.9
12/6/2006	Trichloroethene	11.0	2.9	5	1.2
12/0/2000	Total VOC's	11.0	2.9		1.2
1/8/2007	Trichloroethene	10.0	4.4	5	1.8
1/0/2007	Total VOC's	10.0	4.4		1.8
2/6/2007	Trichloroethene	12.0	3.1	5	ND<1
2/0/2007	Total VOC's	12.0	3.1		ND<1
3/21/2007	Trichloroethene	11.0	4.6	5	1.8
3/21/2007	Total VOC's	11.0	4.6		1.8
4/5/2007	Trichloroethene	10.0	4.8	5	1.6
4/3/2007	Total VOC's	10.0	4.8		1.6
5/18/2007	Trichloroethene	11.0	4.5	5	2.0
3/10/2007	Total VOC's	11.0	4.5		2.0
6/13/2007	Trichloroethene	12.0	4.3	5	2.0
0/13/2007	Total VOC's	12.0	4.3		2.0
7/9/2007	Trichloroethene	10.0	4.1	5	1.4
175/2001	Total VOC's	10.0	4.1		1.4
8/8/2007	Trichloroethene	9.2	3.4	5	1.4
0/0/2001	Total VOC's	9.2	3.4		1.4
9/7/2007	Trichloroethene	6.2	2.4	5	1.0
3/1/2001	Total VOC's	6.2	2.4		1.0
10/4/2007	Trichloroethene	5.9	2.2	5	1.2
10,7/2001	Total VOC's	5.9	2.2		1.2
11/26/2007	Trichloroethene	6.3	2.9	5	1.2
11/20/2007	Total VOC's	6.3	2.9		1.2
12/26/2007	Trichloroethene	10.0	4.8	5	1.9
12/20/2007	Total VOC's	10.0	4.8		3.0
1/11/2008	Trichloroethene	11.0	5.0	5	2.0
1/11/2000	Total VOC's	11.0	5.0		2.0



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
2/15/2008	Trichloroethene	8.9	3.5	5	1.3
	Total VOC's	8.9	3.5		1.3
3/24/2008	Trichloroethene	11.0	4.4	5	1.9
0/2 1/2000	Total VOC's	11.0	4.4		1.9
4/16/2008	Trichloroethene	9.6	3.9	5	1.7
17 10/2000	Total VOC's	9.6	3.9		1.7
5/21/2008	Trichloroethene	10.0	4.8	5	2.0
0/21/2000	Total VOC's	10.0	4.8		2.0
6/26/2008	Trichloroethene	8.5	3.4	5	1.7
0/20/2000	Total VOC's	8.5	3.4		1.7
7/22/2008	Trichloroethene	8.1	3.5	5	1.6
	Total VOC's	8.1	3.5		1.6
8/21/2008	Trichloroethene	6.0	3.0	5	1.3
	Total VOC's	6.0	3.0		1.3
9/18/2008	Trichloroethene	5.9	2.7	5	1.0
	Total VOC's	5.9	2.7		1.0
10/23/2008	Trichloroethene	3.5	2.2	5	<1
	Total VOC's	3.5	2.2		<1
11/26/2008	Trichloroethene	4.0	2.2	5	1.0
	Total VOC's	4.0	2.2		1.0
12/16/2008	Trichloroethene	4.2	2.2	5	1.1
	Total VOC's	4.2	2.2		1.1
1/20/2009	Trichloroethene	6.2	3.5	5	1.5
	Total VOC's	6.2	3.5		1.5
2/23/2009	Trichloroethene	5.0	2.1	5	<1
	Total VOC's	5.0	2.1		<1
3/17/2009	Trichloroethene	5.7	3.6	5	1.5
	Total VOC's	5.7	3.6		1.5
4/16/2009	Trichloroethene	6.0	3.5	5	1.8
	Total VOC's	6.0	3.5		1.8
5/19/2009	Trichloroethene	6.4	3.5	5	1.6
	Total VOC's	6.4	3.5		1.6
6/18/2009	Trichloroethene	6.2	2.8	5	1.6
	Total VOC's	6.2	2.8		1.6
7/14/2009	Trichloroethene	4.3	2.7	5	1.4
	Total VOC's	4.3	2.7		1.4
8/31/2009	Trichloroethene	3.7	1.9	5	1.0
	Total VOC's	3.7	1.9		1.0
9/24/2009	Trichloroethene	3.7	2.0	5	1.0
	Total VOC's	3.7	2.0		1.0



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006

Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
10/20/2009	Trichloroethene	3.9	2.0	5	1.0
	Total VOC's	3.9	2.0		1.0
11/30/2009	Trichloroethene	3.2	2.2	5	1.0
	Total VOC's	3.2	2.2		1.0
12/29/2009	Trichloroethene	5.1	1.7	5	<1
	Total VOC's	5.1	1.7		<1
1/28/2010	Trichloroethene	5.9	2.7	5	1.3
	Total VOC's	5.9	2.7		1.3
2/24/2010	Trichloroethene	6.9	2.9	5	1.4
	Total VOC's	6.9	2.9		1.4
3/30/2010	Trichloroethene	8.0	3.7	5	1.7
	Total VOC's	8.0	3.7		1.7
4/29/2010	Trichloroethene	8.6	3.5	5	1.7
	Total VOC's	8.6	3.5		1.7
5/27/2010	Trichloroethene	8.5	3.1	5	1.8
	Total VOC's	8.5	3.1		1.8
6/30/2010	Trichloroethene	8.0	3.1	5	1.6
	Total VOC's	8.0	3.1		1.6
7/29/2010	Trichloroethene	6.8	2.5	5	1.2
	Total VOC's	6.8	2.5		1.2
8/31/2010	Trichloroethene	4.6	2.0	5	1.1
	Total VOC's	4.6	2.0		1.1
9/29/2010	Trichloroethene	4.9	1.9	5	1.0
	Total VOC's	4.9	1.9		1.0
10/28/2010	Trichloroethene	5.4	2.2	5	1.0
	Total VOC's	5.4	2.2		1.0
11/29/2010	Trichloroethene	6.4	2.5	5	1.2
	Total VOC's	6.4	2.5		1.2
12/31/2010	Trichloroethene	9.9	3.7	5	1.3
	Total VOC's	9.9	3.7		1.3
1/24/2011	Trichloroethene	9.6	5.1	5	2.3
	Total VOC's	9.6	5.1		2.3
2/25/2011	Trichloroethene	8.0	5.3	5	2.0
	Total VOC's	8.0	5.3		2.0
3/31/2011	Trichloroethene	11.0	4.4	5	2.0
	Total VOC's	11.0	4.4		2.0
4/28/2011	Trichloroethene	11.0	4.1	5	1.9
	Total VOC's	11.0	4.1		1.9
5/31/2011	Trichloroethene	14.0	4.5	5	2.3
	Total VOC's	14.0	4.5		2.3



Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006

Date Influent Discharge Limit Cascade 6/29/2011 Trichloroethene 12.0 4.5 5 2.2 7/29/2011 Trichloroethene 9.9 3.4 5 1.8 8/19/2011 Trichloroethene 9.9 3.4 5 1.8 8/19/2011 Trichloroethene 9.8 3.5 5 1.8 9/27/2011 Trichloroethene 8.9 3.2 5 1.5 10/26/2011 Trichloroethene 9.7 3.9 5 1.7 Total VOC's 9.7 3.9 5 1.7 11/22/2011 Trichloroethene 9.7 3.9 5 1.7 11/22/2011 Trichloroethene 8.8 3.8 5 1.5 12/27/2012 Trichloroethene 10.4 4.3 5 1.7 11/27/2012 Trichloroethene 10.4 4.3 5 1.7 11/27/2012 Trichloroethene 10.3 4.1 5 1.6	Sampling	Compound	Tower	Tower	Reg	Outfall at
Total VOC's 12.0 4.5 2.2	Date		Influent	Discharge	Limit	Cascade
Trichloroethene	6/29/2011	Trichloroethene	12.0	4.5	5	2.2
Total VOC's 9.9 3.4 1.8		Total VOC's	12.0	4.5		2.2
8/19/2011 Trichloroethene 9.8 3.5 5 1.8 9/27/2011 Trichloroethene 8.9 3.2 5 1.5 Total VOC's 8.9 3.2 5 1.5 10/26/2011 Trichloroethene 9.7 3.9 5 1.7 Total VOC's 9.7 3.9 5 1.7 Total VOC's 8.8 3.8 5 1.5 Total VOC's 8.8 3.8 5 1.5 Total VOC's 8.8 3.8 5 1.5 Total VOC's 10.7 4.5 1.7 Trichloroethene 10.4 4.3 5 1.7 Trichloroethene 10.3 4.1 5 1.6 Total VOC's 10.5 4.3 1.6 Z024/2012 Trichloroethene 11.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 Total VOC's 11.9 4.7 5 2.0 Total VOC's 10.4 4.3 1.9 Foral VOC's 10.5 8.4 3.5 1.4 Total VOC's 8.4 3.5 1.4 Total VOC's 7.8 2.7 5 1.5 Foral VOC's 5.5 2.0 5 0.9 Foral VOC's 5.5 5.0 1.9 5 0.8 Foral VOC's 5.5 5.0 1.9 5 0.7 Total VOC's 5.5 5.0 1.9 5	7/29/2011	Trichloroethene	9.9	3.4	5	1.8
Total VOC's 9.8 3.5 1.8		Total VOC's	9.9	3.4		1.8
9/27/2011 Trichloroethene 8.9 3.2 5 1.5 Total VOC's 8.9 3.2 5 1.5 Total VOC's 9.7 3.9 5 1.7 Total VOC'S 9.7 3.9 1.7 Total VOC'S 9.7 3.9 1.7 Total VOC'S 8.8 3.8 5 1.5 Total VOC'S 8.8 3.8 5 1.5 Total VOC'S 8.8 3.8 5 1.5 Total VOC'S 10.7 4.5 1.7 Total VOC'S 10.7 4.5 1.7 Total VOC'S 10.5 4.3 1.6 Total VOC'S 10.5 4.3 1.6 Total VOC'S 12.3 5.2 2.1 Total VOC'S 11.9 4.7 5 2.0 Total VOC'S 11.9 4.7 5 2.0 Total VOC'S 10.4 4.3 1.9 Total VOC'S 10.4 4.3 1.9 Total VOC'S 11.9 4.7 5 2.0 Total VOC'S 11.9 4.7 5 2.0 Total VOC'S 10.4 4.3 1.9 Formal VOC'S 9.7 3.7 1.8 Formal VOC'S 8.4 3.5 1.4 Total VOC'S 8.4 3.5 1.4 Total VOC'S 8.4 3.5 1.4 Total VOC'S 7.8 2.7 1.5 Formal VOC'S 5.5 2.0 5 0.9 Formal VOC'S 5.5 2.0 5 0.9 Formal VOC'S 5.5 2.0 5 0.9 Formal VOC'S 5.0 1.9 5 0.8 Formal VOC'S 3.8 1.6 5 0.6 Total VOC'S 3.8 1.6 5 0.6 Total VOC'S 4.3 1.9 5 0.7 Total VOC'S 4.3 1.9 0.7 Total VOC'S 4.04 1.71 5 0.74	8/19/2011	Trichloroethene	9.8	3.5	5	1.8
Total VOC's 8.9 3.2 1.5		Total VOC's	9.8	3.5		1.8
10/26/2011 Trichloroethene	9/27/2011	Trichloroethene	8.9	3.2	5	1.5
Total VOC's 9.7 3.9 1.7 11/22/2011 Trichloroethene 8.8 3.8 5 1.5 12/27/2011 Trichloroethene 10.4 4.3 5 1.7 Total VOC's 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 10.5 4.3 1.6 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 5 2.0 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 <td></td> <td>Total VOC's</td> <td>8.9</td> <td>3.2</td> <td></td> <td>1.5</td>		Total VOC's	8.9	3.2		1.5
11/22/2011 Trichloroethene 8.8 3.8 5 1.5 12/27/2011 Trichloroethene 10.4 4.3 5 1.7 1/27/2012 Trichloroethene 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 3/27/2012 Trichloroethene 12.0 5.0 5 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 3/27/2012 Trichloroethene 10.2 4.2 5 1.9 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 <t< td=""><td>10/26/2011</td><td>Trichloroethene</td><td>9.7</td><td>3.9</td><td>5</td><td>1.7</td></t<>	10/26/2011	Trichloroethene	9.7	3.9	5	1.7
Total VOC's 8.8 3.8 1.5 12/27/2011 Trichloroethene 10.4 4.3 5 1.7 Total VOC's 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 Total VOC's 10.5 4.3 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 5 2.0 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 Total VOC's 9.7 2.7 5 1.5 8/29/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 7.7 2.7 5 0.9 Total VOC's 7.8 2.7 1.5 8/29/2012 Trichloroethene 7.7 2.7 5 0.9 Total VOC's 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 7.7 2.7 5 0.9 Total VOC's 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.7 Total VOC's 4.3 1.9 0.7		Total VOC's	9.7	3.9		1.7
12/27/2011 Trichloroethene 10.4 4.3 5 1.7 Total VOC's 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 1/27/2012 Trichloroethene 10.5 4.3 1.6 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 5 2.0 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 5 0.9	11/22/2011	Trichloroethene	8.8	3.8	5	1.5
Total VOC's 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 Total VOC's 10.5 4.3 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 Total VOC's 7.8 2.7 5 1.5 Total VOC's 7.8 2.7 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.0 1.9 5 0.8 Total VOC's 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7		Total VOC's	8.8	3.8		1.5
Total VOC's 10.7 4.5 1.7 1/27/2012 Trichloroethene 10.3 4.1 5 1.6 1/27/2012 Trichloroethene 10.5 4.3 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 5 2.0 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 1.4 7/26/2012 Trichloroethene 8.3 3.4 5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9	12/27/2011	Trichloroethene	10.4	4.3	5	1.7
1/27/2012 Trichloroethene 10.3 4.1 5 1.6 Total VOC's 10.5 4.3 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 T/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 <td></td> <td>Total VOC's</td> <td></td> <td></td> <td></td> <td></td>		Total VOC's				
Total VOC's 10.5 4.3 1.6 2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 T/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 <td< td=""><td>1/27/2012</td><td></td><td></td><td></td><td>5</td><td></td></td<>	1/27/2012				5	
2/24/2012 Trichloroethene 12.0 5.0 5 2.1 Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 10/29/02012		Total VOC's				
Total VOC's 12.3 5.2 2.1 3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.6	2/24/2012				5	
3/27/2012 Trichloroethene 11.9 4.7 5 2.0 Total VOC's 11.9 4.7 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.6 Total VOC's 3.8 1.6 5 0.6 Trichloroethen						
Total VOC's 11.9 4.7 2.6 4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 0.7<	3/27/2012			•	5	
4/23/2012 Trichloroethene 10.2 4.2 5 1.9 Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.8 Total VOC's 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.7 Total VOC's 4.3 1.9 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
Total VOC's 10.4 4.3 1.9 5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 5 0.8 Total VOC's 5.0 1.9 5 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 <td< td=""><td>4/23/2012</td><td></td><td></td><td></td><td>5</td><td></td></td<>	4/23/2012				5	
5/31/2012 Trichloroethene 9.6 3.6 5 1.8 Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 5 0.9 4/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.6 Total VOC's 3.8 1.6 5 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 <						
Total VOC's 9.7 3.7 1.8 6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 5 0.6 Total VOC's 3.8 1.6 5 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 5 0.7 Total VOC's 4.04 1.71 5 0.74	5/31/2012				5	
6/25/2012 Trichloroethene 8.3 3.4 5 1.4 Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 0.9 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 0.6 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 5 0.74 Total VO						
Total VOC's 8.4 3.5 1.4 7/26/2012 Trichloroethene 7.7 2.7 5 1.5 Total VOC's 7.8 2.7 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 0.9 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 5 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 0.74 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	6/25/2012				5	
7/26/2012 Trichloroethene 7.7 2.7 5 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74						
Total VOC's 7.8 2.7 1.5 8/29/2012 Trichloroethene 5.5 2.0 5 0.9 Total VOC's 5.5 2.0 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 0.74 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	7/26/2012	1			5	
8/29/2012 Trichloroethene 5.5 2.0 5 0.9 9/25/2012 Trichloroethene 5.5 2.0 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 0.74 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74						
Total VOC's 5.5 2.0 0.9 9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	8/29/2012	†			5	
9/25/2012 Trichloroethene 5.0 1.9 5 0.8 Total VOC's 5.0 1.9 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74						
Total VOC's 5.0 1.9 0.8 10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	9/25/2012				5	
10/29/02012 Trichloroethene 3.8 1.6 5 0.6 Total VOC's 3.8 1.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74						
Total VOC's 3.8 1.6 0.6 11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	10/29/02012			•	5	
11/21/2012 Trichloroethene 4.3 1.9 5 0.7 Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74						
Total VOC's 4.3 1.9 0.7 12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	11/21/2012	†			5	
12/18/2012 Trichloroethene 4.04 1.71 5 0.74 Total VOC's 4.04 1.71 0.74	11/21/2012					
Total VOC's 4.04 1.71 0.74	12/18/2012				5	
	12, 10,2012				5	
1/24/2013 Trichloroethene 6.25 1.68 5 1.08	1/24/2012	†				
1/24/2013 Trichloroethene 6.25 1.68 5 1.08 Total VOC's 6.25 1.68 1.08	1/24/2013				٥	




Table No. 3 Monthly Analytical Results May 2001- December 2013 Former SCM - Cortlandville

Site No. 712006


Sampling	Compound	Tower	Tower	Reg	Outfall at
Date		Influent	Discharge	Limit	Cascade
2/26/2013	Trichloroethene	6.97	2.83	5	1.17
	Total VOC's	7.10	2.83		1.17
3/21/2013	Trichloroethene	7.91	3.85	5	1.33
	Total VOC's	8.09 J	3.97 J		1.33
4/29/2013	Trichloroethene	7.57	3.08	5	1.36
	Total VOC's	7.73 J	3.18 J		1.36
5/21/2013	Trichloroethene	10.0	3.53	5	1.60
	Total VOC's	10.22 J	3.67 J		1.60
6/26/2013	Trichloroethene	7.42	2.56	5	1.27
	Total VOC's	7.56 J	2.56		1.27
7/29/2013	Trichloroethene	8.50	3.20	5	1.57
	Total VOC's	8.50	3.30 J		1.57
8/27/2013	Trichloroethene	10.60	3.78	5	1.65
	Total VOC's	10.75 J	3.78		1.65
9/25/2013	Trichloroethene	9.47	3.95	5	1.51
	Total VOC's	9.62 J	3.95		1.51
10/25/2013	Trichloroethene	9.23	4.18	5	1.62
	Total VOC's	9.41 J	4.31 J		1.62
11/26/2013	Trichloroethene	8.84	3.89	5	1.51
	Total VOC's	8.84	3.89		1.51
12/26/2013	Trichloroethene	10.00	4.71	5	1.77
	Total VOC's	10.14 J	4.71		1.77




APPENDIX D
CHARTS









































































APPENDIX E ANALYTICAL RESULTS FROM 2013 ANNUAL SAMPLING EVENT



Thursday, December 12, 2013

Mr. Christopher Gabriel GeoLogie NY, Inc. 37 Copeland Ave. Homer, NY 13077

TEL: 607 749-5000

Project: 210087 2013 ANNUAL

RE: Analytical Results Order No.: K1311319

Dear Mr. Christopher Gabriel:

Life Science Laboratories, Inc. received 19 sample(s) on 11/27/2013 for the analyses presented in the following report. Sample results relate only to the samples as received by the laboratory.

Very truly yours, Life Science Laboratories, Inc.

Anthony Crescenzi

any co

Project Manager



Project:

Inst. ID:

Life Science Laboratories, Inc.

Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 2013 Annual

W Order: K1311319 Matrix: WATER

MSK 75 %Moisture: ColumnID: Rtx-VMS

Revision: 12/09/13 11:06 Sample Size 10 mL

TestCode: 8260W

K1311319-001A Lab ID:

Client Sample ID: MW-1S

11/25/13 13:05 **Collection Date:** 11/27/13 14:00 Date Received:

PrepDate:

BatchNo: R26502

1-SAMP-K4595.D FileID:

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW826		
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 15:00
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 15:00
cis-1.2-Dichloroethene	0.13 J	0.50	0.10	μg/L	1	12/04/13 15:00
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 15:00
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 15:00
Trichloroethene	4.69	0.50	0.10	μg/L	1	12/04/13 15:00
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 15:00
Surr: 1,2-Dichloroethane-d4	108	75-130	0.16	%REC	1	12/04/13 15:00
Surr: Toluene-d8	114	75-125	0.10	%REC	1	12/04/13 15:00
Surr: 4-Bromofluorobenzene	99	75-125	0.10	%REC	1	12/04/13 15:00

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

664212 Project Supervisor: Anthony Crescenzi Print Datc: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 2013 Annual Project:

W Order: K1311319 WATER Matrix:

Inst. ID: MSK_75 ColumnID: Rtx-VMS

12/09/13 11:06 Revision:

Sample Size 10 mL

%Moisture:

TestCode: 8260W

K1311319-002A Lab ID:

Client Sample ID: MW-1D

11/25/13 13:25 Collection Date: 11/27/13 14:00 Date Received:

PrepDate:

R26502 BatchNo:

1-SAMP-K4596.D FileID:

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed	
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 15:32	
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 15:32	
cis-1,2-Dichloroethene	0.11 J	0.50	0.10	μg/L	1	12/04/13 15:32	
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 15:32	
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 15:32	
Trichloroethene	3.49	0.50	0.10	μg/L	1	12/04/13 15:32	
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 15:32	
Surr: 1,2-Dichloroethane-d4	110	75-130	0,16	%REC	1	12/04/13 15:32	
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/04/13 15:32	
Surr: 4-Bromofluorobenzene	96	75-125	0.10	%REC	1	12/04/13 15:32	

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664213 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 2013 Annual Project:

W Order: K1311319 WATER Matrix: Inst. ID:

MSK_75 ColumnID: Rtx-VMS

12/09/13 11:06 Revision:

Sample Size 10 mL

%Moisture:

TestCode: 8260W

K1311319-003A Lab ID:

Client Sample ID: MW-2S

11/25/13 15:45 Collection Date: 11/27/13 14:00 Date Received:

PrepDate:

BatchNo: R26502

1-SAMP-K4597.D FileID:

Col Type:

Analyte	Result Qu	ial PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW826	0B	
1.1.1-Trichloroethane	ND	0.50	0.10	μ g /L	1	12/04/13 16:04
1.1-Dichloroethene	ND	0.50	0.16	μ g/L	1	12/04/13 16:04
cis-1,2-Dichloroethene	ND	0.50	0.10	μ g/ L	1	12/04/13 16:04
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 16:04
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 16:04
Trichloroethene	1.48	0.50	0.10	μg/L	1	12/04/13 16:04
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 16:04
Surr: 1.2-Dichloroethane-d4	112	75-130	0.16	%REC	1	12/04/13 16:04
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/04/13 16:04
Surr: 4-Bromofluorobenzene	95	75-125	0.10	%REC	1	12/04/13 16:04

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664214 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 2013 Annual Project:

W Order: K1311319 WATER Matrix:

Inst. ID: MSK_75

ColumnID: Rtx-VMS

12/09/13 11:06 Revision:

Sample Size 10 mL %Moisture:

TestCode: 8260W

K1311319-004A Lab ID:

Client Sample ID: MW-4S

Collection Date: Date Received:

11/26/13 10:45 11/27/13 14:00

PrepDate:

FileID:

BatchNo:

R26502

1-SAMP-K4598.D

Col Type:

Analyte	Result Qual PQL		MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW8260	В	
1.1.1-Trichloroethane	ND	0,50	0.10	μg/L	1	12/04/13 16:36
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 16:36
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 16:36
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 16:36
trans-1,2-Dichloroethene	ND	0,50	0.10	μg/L	1	12/04/13 16:36
Trichloroethene	0.46 J	0.50	0.10	μg/L	1	12/04/13 16:36
Vinvi chloride	ND	1.00	0.33	μg/L	1	12/04/13 16:36
Surr: 1,2-Dichloroethane-d4	111	75-130	0.16	%REC	1	12/04/13 16:36
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/04/13 16:36
Surr: 4-Bromofluorobenzene	97	75-125	0.10	%REC	1	12/04/13 16:36

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664215 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project:

210087 2013 Annual

W Order:

K1311319 WATER

Matrix: Inst. ID:

MSK 75

ColumnID: Rtx-VMS 12/09/13 11:06

Revision:

Sample Size 10 mL

%Moisture: TestCode: 8260W

K1311319-005A Lab ID:

Client Sample ID: MW-4D

Collection Date: Date Received:

11/26/13 10:10 11/27/13 14:00

PrepDate:

BatchNo: R26502

1-SAMP-K4599.D FileID:

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	IDS BY GC/MS			SW826	В	
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 17:08
1,1-Dichloroethene	ND	0,50	0.16	μg/L	1	12/04/13 17:08
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 17:08
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 17:08
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 17:08
Trichloroethene	0.38 J	0.50	0.10	μg/L	1	12/04/13 17:08
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 17:08
Surr: 1.2-Dichloroethane-d4	110	75-130	0.16	%REC	1	12/04/13 17:08
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/04/13 17:08
Surr: 4-Bromofluorobenzene	97	75-125	0.10	%REC	1	12/04/13 17:08

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:49 664216



Analytical Results

5854 Butternut Drive

East Syraeuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project:

210087 2013 Annual

W Order:

K1311319 WATER

Matrix: Inst. ID:

MSK 75

Revision: 12/09/13 11:06 Col Type:

ColumnID: Rtx-VMS

Sample Size 10 mL

%Moisture:

TestCode: 8260W

K1311319-006A Lab ID:

Client Sample ID: MW-5S

Collection Date: Date Received:

11/25/13 11:25 11/27/13 14:00

PrepDate:

BatchNo: FileID:

R26502

1-SAMP-K4600.D

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed		
VOLATILE ORGANIC COMPOUN	NDS BY GC/MS			SW8260B				
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 17:40		
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 17:40		
cis-1.2-Dichloroethene	ND	0.50	0.10	µg/L	1	12/04/13 17:40		
Tetrachloroethene	ND	0.50	0.10	µg/L	1	12/04/13 17:40		
trans-1,2-Dichloroethene	ND	0.50	0,10	μg/L	1	12/04/13 17:40		
Trichloroethene	0.91	0.50	0.10	μg/L	1	12/04/13 17:40		
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 17:40		
Surr: 1,2-Dichloroethane-d4	109	75-130	0.16	%REC	1	12/04/13 17:40		
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/04/13 17:40		
Surr: 4-Bromofluorobenzene	98	75-125	0.10	%REC	1	12/04/13 17:40		

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Print Date: 12/09/13 14:49 Project Supervisor: Anthony Crescenzi 664217



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT

GeoLogic NY, Inc.

Lab ID:

K1311319-007A

Project:

210087 2013 Annual

Client Sample ID: MW-5D

W Order:

Collection Date:

11/25/13 11:35

Matrix:

K1311319 WATER

Date Received:

11/27/13 14:00

Inst. ID:

MSK 75

Sample Size 10 mL

8260W

PrepDate:

R26502

Revision:

ColumnID: Rtx-VMS

12/09/13 11:06

%Moisture: TestCode:

BatchNo: FileID:

1-SAMP-K4601.D

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	IDS BY GC/MS			SW826		
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 18:12
1,1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 18:12
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:12
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:12
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:12
Trichloroethene	1.17	0.50	0.10	μg/L	1	12/04/13 18:12
Vinyl chloride	ND	1,00	0.33	μg/L	1	12/04/13 18:12
Surr: 1,2-Dichloroethane-d4	113	75-130	0.16	%REC	1	12/04/13 18:12
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/04/13 18:12
Surr: 4-Bromofluorobenzene	98	75-125	0.10	%REC	1	12/04/13 18:12

Quallflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:49 664218



Project:

Life Science Laboratories, Inc.

Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

11/25/13 15:15

11/27/13 14:00

K1311319-008A

CLIENT GeoLogic NY, Inc.

210087 2013 Annual

W Order: K1311319 Matrix: WATER

MSK 75 Inst. ID: ColumnID: Rtx-VMS

Revision: 12/09/13 11:06 Sample Size 10 mL

%Moisture:

TestCode: 8260W **Collection Date:** Date Received:

Lab ID:

PrepDate:

R26502 BatchNo:

Client Sample ID: MW-6

1-SAMP-K4602.D FileID:

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	IDS BY GC/MS			SW826		
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 18:44
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 18:44
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:44
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:44
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:44
Trichloroethene	6.54	0.50	0.10	μg/L	1	12/04/13 18:44
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 18:44
Surr: 1.2-Dichloroethane-d4	114	75-130	0.16	%REC	1	12/04/13 18:44
Surr: Toluene-d8	112	75 -12 5	0.10	%REC	1	12/04/13 18:44
Surr: 4-Bromofluorobenzene	96	75-125	0.10	%REC	1	12/04/13 18:44

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664219 Print Date: 12/09/13 14:49



Analytical Results

East Syracuse, NY 13057

(315) 445-1900

8260W

StateCertNo: 10248

CLIENT

GeoLogic NY, Inc.

K1311319-009A Lab ID:

Project:

210087 2013 Annual

Client Sample ID: MW-7

W Order:

Matrix:

K1311319

Collection Date: Date Received:

11/25/13 13:20 11/27/13 14:00

Inst. ID:

WATER MSK 75

Sample Size 10 mL

Revision:

ColumnID: Rtx-VMS

12/09/13 11:06

%Moisture: TestCode:

PrepDate: BatchNo: FileID:

R26502 1-SAMP-K4603.D

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW826		
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 19:16
1,1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 19:16
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:16
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:16
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:16
Trichloroethene	3.08	0.50	0.10	μg/L	1	12/04/13 19:16
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 19:16
Surr: 1,2-Dichloroethane-d4	113	75-130	0.16	%REC	1	12/04/13 19:16
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/04/13 19:16
Surr: 4-Bromofluorobenzene	97	75-125	0.10	%REC	1	12/04/13 19:16

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664220 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

GeoLogic NY, Inc.

CLIENT Project:

210087 2013 Annual

W Order:

K1311319 WATER

Matrix: Inst. ID:

MSK_75

ColumnID: Rtx-VMS 12/09/13 11:06

Sample Size 10 mL

%Moisture: TestCode: 8260W Lab ID:

K1311319-010A

Client Sample ID: MW-8

Collection Date: Date Received:

11/25/13 13:58 11/27/13 14:00

PrepDate:

BatchNo: FileID:

R26502

1-SAMP-K4604.D

Revision: Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed		
VOLATILE ORGANIC COMPOUNDS BY GC/MS					SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 19:48		
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 19:48		
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:48		
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:48		
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:48		
Trichloroethene	1.72	0.50	0.10	μg/L	1	12/04/13 19:48		
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 19:48		
Surr: 1,2-Dichloroethane-d4	115	75-130	0.16	%REC	1	12/04/13 19:48		
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/04/13 19:48		
Surr: 4-Bromofluorobenzene	99	75-125	0.10	%REC	1	12/04/13 19:48		

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:49 664221



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 2013 Annual Project:

W Order: K1311319 Matrix: WATER

MSK 75 Inst. ID: ColumnID: Rtx-VMS

Revision: 12/09/13 14:48 Sample Size 10 mL

%Moisture: TestCode: 8260W

K1311319-011A Lab ID:

Client Sample ID: MW-9

Collection Date: Date Received:

11/25/13 11:33 11/27/13 14:00

PrepDate:

BatchNo: R26503

1-SAMP-K4617.D FileID:

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUNDS BY GC/MS				SW826	ов	
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 12:51
1.1-Dichloroethene	· ND	0.50	0.16	μg/L	1	12/05/13 12:51
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 12:51
Tetrachioroethene	ND	0.50	0.10	μg/L	1	12/05/13 12:51
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 12:51
Trichloroethene	0.54	0.50	0.10	μg/L	1	12/05/13 12:51
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 12:51
Surr: 1,2-Dichloroethane-d4	111	75-130	0.16	%REC	1	12/05/13 12:51
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/05/13 12:51
Surr: 4-Bromofluorobenzene	99	75-125	0.10	%REC	1	12/05/13 12:51

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664227 Print Date: 12/09/13 14:49



Analytical Results

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

GeoLogic NY, Inc.

CLIENT Project:

210087 2013 Annual

W Order:

K1311319 WATER

Matrix: Inst. ID:

MSK 75

ColumnID: Rtx-VMS Revision:

Col Type:

12/09/13 14:48

Sample Size 10 mL %Moisture:

TestCode: 8260W

K1311319-012A Lab ID:

Client Sample ID: MW-10S

Collection Date: Date Received:

11/25/13 15:00 11/27/13 14:00

PrepDate:

FileID:

BatchNo:

R26503

1-SAMP-K4618.D

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed		
VOLATILE ORGANIC COMPOUNDS BY GC/MS					SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 13:23		
1.1-Dichloroethene	· ND	0.50	0.16	μg/L	1	12/05/13 13:23		
cis-1,2-Dichloroethene	0,34 J	0.50	0,10	μg/L	1	12/05/13 13:23		
Tetrachioroethene	ND	0.50	0.10	μg/L	1	12/05/13 13:23		
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 13:23		
Trichloroethene	6.76	0.50	0.10	μg/L	1	12/05/13 13:23		
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 13:23		
Surr: 1,2-Dichloroethane-d4	: 113	75-130	0.16	%REC	1	12/05/13 13:23		
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/05/13 13:23		
Surr: 4-Bromofluorobenzene	100	75-125	0.10	%REC	1	12/05/13 13:23		

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664228 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project: 210087 2013 Annual

W Order: K1311319 Matrix: WATER

MSK 75 Inst. ID: %Moisture: Rtx-VMS

ColumnID:

Revision: 12/09/13 14:48 Sample Size 10 mL

TestCode: 8260W

K1311319-013A Lab ID:

Client Sample ID: MW-10D 11/25/13 15:50 **Collection Date:**

Date Received:

11/27/13 14:00

PrepDate:

R26503 BatchNo:

1-SAMP-K4619.D FileID:

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed		
VOLATILE ORGANIC COMPOUNDS BY GC/MS					SW8260B			
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 13:55		
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 13:55		
cis-1,2-Dichloroethene	0.17 J	0.50	0.10	μg/L	1	12/05/13 13:55		
Tetrachioroethene	ND	0.50	0.10	μg/L	1	12/05/13 13:55		
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 13:55		
Trichloroethene	6.85	0.50	0.10	μg/L	1	12/05/13 13:55		
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 13:55		
Surr: 1,2-Dichloroethane-d4	112	75-130	0.16	%REC	1	12/05/13 13:55		
Surr: Toluene-d8	111	75-125	0.10	%REC	1	12/05/13 13:55		
Surr: 4-Bromofluorobenzene	99	75-125	0.10	%REC	1	12/05/13 13:55		

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Print Date: 12/09/13 14:49 Project Supervisor: Anthony Crescenzi 664229



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT

GeoLogic NY, Inc.

Lab ID:

K1311319-014A

Project:

210087 2013 Annual

Client Sample ID: MW-11

W Order:

Collection Date:

11/25/13 12:18

Matrix:

K1311319

Date Received:

11/27/13 14:00

Inst. ID:

WATER **MSK 75**

Sample Size 10 mL

PrepDate: BatchNo:

R26503

Revision:

ColumnID: Rtx-VMS

12/09/13 14:48

%Moisture: TestCode: 8260W

FileID:

1-SAMP-K4620.D

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	SW8260B					
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 14:27
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 14:27
cls-1,2-Dichloroethene	0.54	0.50	0.10	μg/L	1	12/05/13 14:27
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/05/13 14:27
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 14:27
Trichloroethene	3.60	0,50	0.10	μg/L	1	12/05/13 14:27
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 14:27
Surr: 1.2-Dichloroethane-d4	115	75-130	0.16	%REC	1	12/05/13 14:27
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/05/13 14:27
Surr: 4-Bromofluorobenzene	105	75-125	0.10	%REC	1	12/05/13 14:27

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:49 664230



Sample Size 10 mL

8260W

%Moisture:

TestCode:

Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057 (315) 445-1900 StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project: 210087 2013 Annual

W Order: K1311319 Matrix: WATER

Inst. ID: MSK_75 ColumnID: Rtx-VMS

Revision: 12/09/13 14:48

Col Type:

Lab ID: K1311319-015A

Client Sample ID: MW-12S

Collection Date: 1
Date Received: 1

11/25/13 15:54 11/27/13 14:00

PrepDate:

BatchNo: R26503

FileID: 1-SAMP-K4621.D

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	SW8260B					
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 14:59
1,1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 14:59
cis-1,2-Dichloroethene	0.65	0.50	0.10	μg/L	1	12/05/13 14:59
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/05/13 14:59
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 14:59
Trichloroethene	32.2	0.50	0.10	μg/L	1	12/05/13 14:59
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 14:59
Surr: 1,2-Dichloroethane-d4	115	75-130	0.16	%REC	1	12/05/13 14:59
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/05/13 14:59
Surr: 4-Bromofluorobenzene	103	75-125	0.10	%REC	1	12/05/13 14:59

Quallfiers:

- Value exceeds Maximum Contaminant Level
- E Value exceeds the instrument calibration range
- J Analyte detected below the PQL
- P Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- S Spike Recovery outside accepted recovery limits

Print Date: 12/09/13 14:49 664231 Project Supervisor: Anthony Crescenzi



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project:

210087 2013 Annual

W Order:

K1311319 WATER

Matrix: Inst. ID:

 MSK_75

ColumnID: Rtx-VMS

12/09/13 14:48

Sample Size 10 mL

%Moisture:

TestCode: 8260W

K1311319-016A Lab ID:

Client Sample ID: MW-12D

Collection Date: Date Received:

11/25/13 17:15 11/27/13 14:00

PrepDate: BatchNo:

FileID:

R26503

1-SAMP-K4622.D

Revision: Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed	
VOLATILE ORGANIC COMPOUN	DS BY GC/MS		<u></u>	SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 15:31	
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 15:31	
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 15:31	
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/05/13 15:31	
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 15:31	
Trichloroethene	1.51	0.50	0.10	μg/L	1	12/05/13 15:31	
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 15:31	
Surr: 1,2-Dichloroethane-d4	117	75-130	0.16	%REC	1	12/05/13 15:31	
Surr: Toluene-d8	, 111	75-125	0.10	%REC	1	12/05/13 15:31	
Surr: 4-Bromofluorobenzene	98	75-125	0.10	%REC	1	12/05/13 15:31	

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664232 Print Date: 12/09/13 14:49



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

8260W

StateCertNo: 10248

CLIENT

GeoLogic NY, Inc.

Lab ID:

K1311319-017A

Project:

210087 2013 Annual

Client Sample ID: MW-L16

W Order:

Collection Date:

11/25/13 14:45

Matrix:

K1311319 WATER

Date Received:

11/27/13 14:00

Inst. ID:

MSK 75

Sample Size 10 mL

PrepDate: BatchNo:

R26503

Revision:

ColumnID: Rtx-VMS 12/09/13 14:48 %Moisture: TestCode:

FileID:

1-SAMP-K4623.D

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed		
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW826	OB			
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 16:03		
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 16:03		
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 16:03		
Tetrachioroethene	ND	0.50	0.10	μg/L	1	12/05/13 16:03		
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 16:03		
Trichloroethene	1.69	0.50	0.10	μg/L	1	12/05/13 16:03		
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 16:03		
Surr: 1.2-Dichloroethane-d4	114	75-130	0.16	%REC	1	12/05/13 16:03		
Surr: Toluene-d8	. 112	75-125	0.10	%REC	1	12/05/13 16:03		
Surr: 4-Bromofluorobenzene	102	75-125	0.10	%REC	1	12/05/13 16:03		

Qualifiers:

Print Date: 12/09/13 14:49

Value exceeds Maximum Contaminant Level

664233

- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
 - S Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

GeoLogic NY, Inc.

CLIENT Project:

210087 2013 Annual

W Order:

K1311319 WATER Q

Matrix: Inst. ID:

MSK_75

ColumnID: Rtx-VMS

%Moisture:

TestCode:

Revision: 12/09/13 14:48 Sample Size 10 mL

8260W

K1311319-018A Lab ID:

Client Sample ID: Trip Blank

Collection Date: Date Received:

11/25/13 0:00 11/27/13 14:00

PrepDate:

R26503 BatchNo:

1-SAMP-K4635.D FileID:

Col Type:

Analyte	Result Qu	ıal PQL	MDL	Units	DF	Date Analyzed			
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW826	0B	В			
1.1.1-Trichloroethane	ND	0,50	0,10	μg/L	1	12/05/13 22:28			
1.1-Dichloroethene	ND ND	0,50	0,16	μg/L	1	12/05/13 22:28			
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 22:28			
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/05/13 22:28			
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 22:28			
Trichloroethene	ND	0.50	0.10	µg/L	1	12/05/13 22:28			
Vinyi chloride	ND	1.00	0.33	µg/L	1	12/05/13 22:28			
Surr: 1,2-Dichloroethane-d4	114	75-130	0.16	%REC	1	12/05/13 22:28			
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/05/13 22:28			
Surr: 4-Bromofluorobenzene	106	75-125	0.10	%REC	1	12/05/13 22:28			

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:49 664236



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc. Project: 210087 2013 Annual

K1311319-019A Lab ID:

W Order:

Client Sample ID: Equipment Blank

K1311319

Collection Date: Date Received:

11/25/13 16:20

Matrix:

EQUIPMENT BLANK PrepDate: Sample Size 10 mL

11/27/13 14:00

MSK_75 Inst. ID: ColumnID: Rtx-VMS

%Moisture:

BatchNo:

R26503

12/09/13 14:48 Revision:

TestCode: 8260W

FileID:

1-SAMP-K4636.D

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOU	NDS BY GC/MS			SW826	0B	
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/05/13 23:00
1,1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/05/13 23:00
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 23:00
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/05/13 23:00
trans-1,2-Dichloroethene	ND	0.50	0.10	µg/L	1	12/05/13 23:00
Trichloroethene	ND	0.50	0.10	μg/L	1	12/05/13 23:00
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/05/13 23;00
Surr: 1,2-Dichloroethane-d4	318 S	75-130	0.16	%REC	1	12/05/13 23:00
Surr: Toluene-d8	95	75-125	0.10	%REC	1	12/05/13 23:00
Surr: 4-Bromofluorobenzene	44 S	75-125	0.10	%REC	1	12/05/13 23:00
NOTES:						

NOTES:

Severe matrix interference present. Internal standard abundances were outside control limits. Results may be biased.

Quali	fiers:
-------	--------

- Value exceeds Maximum Contaminant Level
- E Value exceeds the instrument calibration range
- J Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Print Date: 12/10/13 9:34 664237 Project Supervisor: Anthony Crescenzi

GeoLogic NY, Inc. KI311319 CHAIN OF CUSTODY RECORD

CLIENT: GeoLogic

SAMPLERS NAME(S):

PROJECT: 210087 2013 Annual Sampling 1of 2 C. T. Gabriel & J. A. Menzel

SAMPLE LOCATION	DATE	TIME	3	SAMPLE TYPE NO. 6 SAMPI			ANALYSIS REQUIRED	
			WATER	SOIL	AIR			
_{دن،} MW-1S	11-25	13:05	х			2	See	Below
cel MW-1D	11-25	13:25	х			2	See	Below
co3 MW-2S	11-25	15:45	х		: * .	2	See	Below
COY MW-4S	11-26	10:45	х			2	See	Below
cos MW-4D	11-26	10:10	х			2	See	Below
cub MW-5S	11-25	11:25	х			2	See	Below
067 MW-5D	11-25	11:35	х			2	See	Below
cos MW-6	11-25	15:15	Х			2	See	Below
οση MW-7	11-25	13:20	Х			2	See	Below
CIU MW-8	11-25	13:58	Х	2			See Below	
Relinquished by: C.T. Gabriel of Ger	luge NY Tic	Date 11-26-2013	Time 13:00	Sample	Received by	" :	Date 11-2-2-13	Time
Relinquished by: Sample Fridge		Date 11/27/213	Time 09:45	Jef	Received by	r:	Date 1/27/15	Time 94
Relinguished by:		Date	Time	ľ	Seived for La		Date 11-27-13	Time 4 (02
Method of Shipment: LAI	B PICK-L	JP		TEMP	55	unIa		
COMMENTALY			, ,					
COMMENTS: Sample Analysis (1 µg/L reportin	ıa limit)							
EPA 8260B for								
1,1,1-Trichloroethane								
1,1-Dichloroethene								
1,2-Dichloroethene								
Trichloroethene								
Tetrachloroethene						· *.		
Vinyl Chloride								

GeoLogic NY, Inc. CHAIN OF CUSTODY RECORD

CLIENT: GeoLogic

SAMPLERS NAME(S):

PROJECT: 210087 2013 Annual Sampling 2of 2 C. T. Gabriel & J. A. Menzel

SAMPLE LOCATION	DATE	TIME	S	AMPLE TYF	Æ	NO. of SAMPLES		ALYSIS QUIRED
			WATER	SOIL	AIR			
مار MW-9	11-25	11:33	Х	2			See	Below
مري MW-10S	11-25	15:00	X			2	See	Below
رزع MW-10D	11-25	15:50	x			2	See	Below
оц MW-11	11-25	12:18	x			2	See	Below
015 MW-12S	11-25	15:54	х			2	See	Below
oil MW-12D	11-25	17:15	х			2	See	Below
رن MW-L16	11-25	14:45	х			2	See	Below
ાજુ Trip Blank			х			2	See	Below
ાષ્ Equipment Blank	11-25	16:20	Х			2	See Below	
Relinquished by:		Date	Time		Received b	y:	Date	Time
C.T. George of Geologe	NY Ju.	11-26-213	13:00	Sample	Fridge		11-76-7113	13:00
Relinquished by: Sample Fridge		Date (1/27/2013	Time (9)45	Jef	Received by	/ :	Date 11/27/3	71me 945
Relinquished by:		Date	Time	Re	ceived for La	b by:	Date	Time
				9	Sit		11-27-13	14100
Method of Shipment:	B PICK-L	JP		_ TEMP	5.5	on I	â	
COMMENTS:								
Sample Analysis (1 μ g/L reporti EPA 8260B for	ng limit)							
1,1,1-Trichloroethane								
1,1-Dichloroethene								
1,2-Dichloroethene								
Trichloroethene								
Tetrachloroethene								
Vinyl Chloride								

Sample Receipt Checklist

F				
Client Name: GEOLOGIC		Date and 1	lime Received:	11/27/2013 2:00:00 PM
Work Order Number: K1311319		Received t	oy: gis	
Checklist completed by: Initials	13	Reviewe	d by: Ae	- 12-2-13 Date
Delivery Method:	Courier			
Shipping container/cooler in good condition?	Yes 🗹	No 🗆	Not Present	
Custody seals intact on shipping container/cooler?	Yes 🗌	No 🗔	Not Present	
Custody seals intact on sample bottles?	Yes 🗌	No 🗌	Not Applicable 🛭	2
Chain of custody present?	Yes 🗹	No 🗔		
Chain of custody signed when relinquished and received?	Yes 🗹	No 🗌		
Chain of custody agrees with sample labels?	Yes 🗹	No 🗌		
Samples in proper container/bottle?	Yes 🗹	No 🗌		
Sample containers intact?	Yes 🗹	No 🗌		
Sufficient sample volume for indicated test?	Yes 🗹	No 🗌		
All samples received within holding time?	Yes 🗹	No 🗆		
Container/Temp Blank temperature in compliance?	Yes 🗹	No 🔲		
Water - VOA vials have zero headspace?	Yes 🔽	No 🗌	No VOA vials subm	nitted
Water - pH acceptable upon receipt?	Yes 🗌	No 🗌	Not Applicable 🗵	

Comments:

Corrective Action:



Thursday, December 12, 2013

Mr. Christopher Gabriel GeoLogic NY, Inc. 37 Copeland Ave. Homer, NY 13077

TEL: 607 749-5000

Project: 210087

RE: Analytical Results Order No.: K1311317

Dear Mr. Christopher Gabriel:

Life Science Laboratories, Inc. received 4 sample(s) on 11/27/2013 for the analyses presented in the following report. Sample results relate only to the samples as received by the laboratory.

Very truly yours,

Life Science Laboratories, Inc.

de con

Anthony Crescenzi

Project Manager



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

8260W

Sample Size 10 mL

%Moisture:

TestCode:

StateCertNo: 10248 K1311317-001A

CLIENT GeoLogic NY, Inc.

Project:

210087

W Order: Matrix:

K1311317 WATER

Inst. ID:

MS01 11

ColumnID: Rtx-VMS

12/09/13 10:14

Lab ID:

Client Sample ID: Cascade 11/26/13 8:00

Collection Date: Date Received:

11/27/13 14:00

PrepDate:

BatchNo:

R26501

FileID:

1-SAMP-T7781.D

Revision: Col Type:

Analyte	Result Qu	ial PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUND	S BY GC/MS			SW8260)B	
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 18:26
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 18:26
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:26
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:26
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:26
Trichloroethene	1.51	0.50	0.10	μg/L	1	12/04/13 18:26
Vinyl chloride	. ND	1.00	0.33	μg/L	1	12/04/13 18:26
Surr: 1,2-Dichloroethane-d4	105	75-130	0.16	%REC	1	12/04/13 18:26
Surr: Toluene-d8	120	75-125	0.10	%REC	1	12/04/13 18:26
Surr: 4-Bromofluorobenzene	103	75-125	0,10	%REC	1	12/04/13 18:26

Qualiflers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- S Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:50 664203



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

210087 Project:

W Order: K1311317 Matrix: WATER

Inst. ID: MS01 11

ColumnID: Rtx-VMS

12/09/13 14:50 Revision:

Sample Size 10 mL

%Moisture: TestCode: 8260W

K1311317-002A Lab ID:

Client Sample ID: Tower Discharge

Collection Date: Date Received:

11/26/13 8:20 11/27/13 14:00

PrepDate:

BatchNo: R26501

1-SAMP-T7783.D FileID:

Col Type:

Analyte	Result Qu	ial PQL	MDL	Units	DF	Date Analyzed	
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 19:29	
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 19:29	
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:29	
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:29	
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 19:29	
Trichloroethene	3.89	0.50	0.10	μg/L	1	12/04/13 19:29	
Vinyl chloride	. ND	1.00	0.33	μg/L	1	12/04/13 19:29	
Surr: 1.2-Dichloroethane-d4	104	75-130	0.16	%REC	1	12/04/13 19:29	
Surr: Toluene-d8	120	75-125	0.10	%REC	1	12/04/13 19:29	
Surr: 4-Bromofluorobenzene	106	75-125	0.10	%REC	1	12/04/13 19:29	

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 12/09/13 14:50 664205



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248 K1311317-003A

Lab ID:

CLIENT GeoLogic NY, Inc. Client Sample ID: Tower Influent 210087 Project: 11/26/13 8:35

Collection Date: W Order: K1311317 11/27/13 14:00 Date Received: Matrix: WATER

PrepDate: Sample Size 10 mL MS01 11 Inst. ID:

BatchNo: R26501 %Moisture: ColumnID: Rtx-VMS

1-SAMP-T7782.D FileID: TestCode: 8260W Revision: 12/09/13 14:50

Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	SW826	0B				
1,1,1-Trichloroethane	ND	0.50	0.10	μ g /L	1	12/04/13 18:57
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/04/13 18:57
cis-1,2-Dichloroethene	0.12 J	0.50	0.10	μg/L	1	12/04/13 18:57
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:57
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 18:57
Trichioroethene	8.84	0.50	0.10	μg/L	1	12/04/13 18:57
Vinyl chloride	. ND	1.00	0.33	μg/L	1	12/04/13 18:57
Surr: 1,2-Dichloroethane-d4	105	75-130	0.16	%REC	1	12/04/13 18:57
Surr: Toluene-d8	118	75-125	0.10	%REC	1	12/04/13 18:57
Surr: 1 diuene-do Surr: 4-Bromofluorobenzene	104	75-125	0.10	%REC	1	12/04/13 18:57

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- S Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664204 Print Date: 12/09/13 14:50

Life Science Laboratories, Inc. 5854 Butternut Drive

Analytical Results

(315) 445-1900 East Syracuse, NY 13057

CLIENT GeoLogic NY, Inc.

210087 Project:

Col Type:

Surr: Toluene-d8

Surr: 4-Bromofluorobenzene

W Order: K1311317 WATER Q Matrix:

Inst. ID: MS01_11

12/09/13 10:14 Revision:

ColumnID: Rtx-VMS

%Moisture: TestCode:

8260W

103

Sample Size 10 mL

K1311317-004A Lab ID: Client Sample ID: Trip Blank

%REC

1

Collection Date: Date Received:

11/26/13 0:00 11/27/13 14:00

StateCertNo: 10248

PrepDate:

0.10

R26501 BatchNo:

FileID:

1-SAMP-T7784.D

12/04/13 20:00

Analyte	Result Qu	ial PQL	MDL	Units	DF	Date Analyzed	
VOLATILE ORGANIC COMPOU	NDS BY GC/MS			SW8260B			
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/04/13 20:00	
1,1-Dichloroethene	ND	0.50	0,16	μg/L	1	12/04/13 20:00	
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 20:00	
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/04/13 20:00	
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 20:00	
Trichloroethene	ND	0.50	0.10	μg/L	1	12/04/13 20:00	
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/04/13 20:00	
Surr: 1,2-Dichloroethane-d4	106	75-130	0.16	%REC	1	12/04/13 20:00	
Surr: Toluene-d8	117	75-125	0.10	%REC	1	12/04/13 20:00	

75-125

Qualifiers:

Value exceeds Maximum Contaminant Level

Value exceeds the instrument calibration range

Analyte detected below the PQL

Prim./Conf. column %D or RPD exceeds limit

Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

ND Not Detected at the Practical Quantitation Limit (PQL)

Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 664206 Print Date: 12/09/13 14:50

GeoLogic NY, Inc. CHAIN OF CUSTODY RECORD

CLIENT: GeoLogic

SAMPLERS NAME(S):

PROJECT: 210087 November 2013

J. A. Menzel

	SAMPLE LOCATION	DATE	TIME	S	AMPLE TYP	E	NO. of SAMPLES	ANALYSIS REQUIRED		
	CAMEL LOCATION	DAIL	11,412	WATER	SOIL	AIR	J SAMI LLS	, nec	IOIILD	
-1	Cascade	8:00	11-26	х			2	See	Below	
, [Tower Discharge * \$	¹⁰ 8:35	11-26	х			2		"	
3	Tower Influent ∜∜	يۇز 8:20	11-26	х			2		"	
٠٤	Trip Blank	9-27-15		х			2		"	
-										
									-	
-										
	Relinquished by:		Date 11-26-13	Time	Sand	Received by		Date	Time	
	Garyha Mory Relinguished by:	1	Date	Time	Jample	····		11-26-233		
	Sample Fridge			09:45	871	Received by	/:	Date 11/27/13	Time_	
	Relinquished by:		Date	Time	Rec	selved for La	b by:	Date //-27-15	Time 14100	
	Method of Shipment: LA	B PICK-L	JP		TEMP	5.5	c on La	T	_	
	COMMENTS: Sample Analysis (1 µg/L reporting limit) & Callel client (chris Cabid) To clarify Id's and Trong, EPA 8260B for Tower Effluent on Lubel is Tower Discharge and Recovery well 1.1.1-Trichloroethane on Lubel is Tower Influent on coc. 35 12-9-13 1.1-Dichloroethane chris who said Time for Tower discharge is 8:20 and									
	1,1-Dichloroethene 1,2-Dichloroethene		in Sail				S 8:20	a * *		
-	Trichloroethene Tetrachloroethene									

Sample Receipt Checklist

Client Name: GEOLOGIC		Date and T	îme Received:	11/27/2013 2:00:00 PM
Work Order Number: K1311317		Received b	y: gis	
Checklist completed by:	2-9-13 Date	Reviewed	d by: A-C	12 -9 - 12 Date
Delivery Mo	ethod: <u>Courier</u>			
Shipping container/cooler in good condition?	Yes 🗸	No 🗆	Not Present]
Custody seals intact on shipping container/cooler?	Yes 🗌	No 🗌	Not Present	
Custody seals intact on sample bottles?	Yes 🗌	No 🗌	Not Applicable 🗹	
Chain of custody present?	Yes 🗹	No 🗆		
Chain of custody signed when relinquished and received?	Yes 🗹	No 🗀		
Chain of custody agrees with sample labels?	Yes 🗌	No 🗹		
Samples in proper container/bottle?	Yes 🗹	No 🗆		
Sample containers intact?	Yes 🗹	No 🗆		
Sufficient sample volume for indicated test?	Yes 🗹	No 🗆		
All samples received within holding time?	Yes 🗹	No 🗌		
Container/Temp Blank temperature in compliance?	Yes 🗹	No 🗆		
Water - VOA vials have zero headspace?	Yes 🗹	No 🗆	No VOA vials subm	itted
Water - pH acceptable upon receipt?	Yes 🗌	No 🗌	Not Applicable 🗹]

Comments:

Labeling discrepancy corrected with a phone call to Chris Gabriel. Documented on COC.

Corrective Action:



Friday, January 03, 2014

Mr. Christopher Gabriel GeoLogic NY, Inc. 37 Copeland Ave. Homer, NY 13077

TEL: 607 749-5000

Project: 210087

RE: Analytical Results

Order No.: K1312307

Dear Mr. Christopher Gabriel:

Life Science Laboratories, Inc. received 4 sample(s) on 12/26/2013 for the analyses presented in the following report. Sample results relate only to the samples as received by the laboratory.

Very truly yours, Life Science Laboratories, Inc.

Anthony Crescenzi Project Manager



Col Type:

Life Science Laboratories, Inc.

Sample Size 10 mL

8260W

%Moisture:

TestCode:

Analytical Results

5854 Butternut Drive

StateCertNo: 10248 East Syracuse, NY 13057 (315) 445-1900

GeoLogic NY, Inc. **CLIENT**

Project: 210087 W Order: K1312307 Matrix: WATER

Inst. ID: MS01 11

Print Date: 01/03/14 15:08

ColumnID: Rtx-VMS Revision:

01/03/14 15:05

Lab ID:

K1312307-001A

Client Sample ID: Cascade 12/26/13 9:35 **Collection Date:**

Date Received:

12/26/13 15:55

PrepDate:

BatchNo: R26576

FileID:

1-SAMP-T7900.D

Analyte	Result Qi	ıal PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOU	NDS BY GC/MS			SW826	OB	
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/30/13 15:44
1.1-Dichloroethene	ND	0,50	0.16	μg/L	1	12/30/13 15:44
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 15:44
Tetrachloroethene	ND	0,50	0.10	μg/L	1	12/30/13 15:44
trans-1,2-Dichloroethene	ND	0,50	0,10	μg/L	1	12/30/13 15:44
Trichloroethene	1.77	0.50	0.10	μg/L	1	12/30/13 15:44
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/30/13 15:44
Surr: 1,2-Dichloroethane-d4	101	75-130	0.16	%REC	1	12/30/13 15:44
Surr: Toluene-d8	112	75-125	0.10	%REC	1	12/30/13 15:44
Surr: 4-Bromofluorobenzene	102	75-125	0.10	%REC	1	12/30/13 15:44

Qualifiers:	*	Value exceeds Maximum Contaminant Level	В	Analyte detected in the associated Method Blank
Quantiti	E	Value exceeds the instrument calibration range	Н	Holding times for preparation or analysis exceeded
	J	Analyte detected below the PQL	ND	Not Detected at the Practical Quantitation Limit (PQL)

666177

P Prim./Conf. column %D or RPD exceeds limit S Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi



Analytical Results

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248

CLIENT GeoLogic NY, Inc.

Project: 210087

W Order: K1312307 Matrix: WATER

MS01_11

ColumnID: Rtx-VMS Revision:

01/03/14 15:05

Sample Size 10 mL

%Moisture: TestCode: 8260W Lab ID:

K1312307-002A

Client Sample ID: Tower Discharge

Collection Date: Date Received:

12/26/13 9:50 12/26/13 15:55

PrepDate:

BatchNo: R26576

FileID:

1-SAMP-T7901.D

Col Type:

Inst. ID:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed	
VOLATILE ORGANIC COMPOUN	DS BY GC/MS			SW8260)B		
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/30/13 16:15	
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/30/13 16:15	
cis-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 16:15	
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/30/13 16:15	
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 16:15	
Trichloroethene	4.71	0.50	0.10	μg/L	1	12/30/13 16:15	
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/30/13 16:15	
Surr: 1,2-Dichloroethane-d4	100	75-130	0.16	%REC	1	12/30/13 16:15	
Surr: Toluene-d8	114	75-125	0.10	%REC	1	12/30/13 16:15	
Surr: 4-Bromofluorobenzene	104	75-125	0.10	%REC	1	12/30/13 16:15	

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- S Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi 666178 Print Date: 01/03/14 15:08

Life Science Laboratories, Inc. 5854 Butternut Drive

Analytical Results

StateCertNo: 10248 (315) 445-1900 East Syracuse, NY 13057

Sample Size 10 mL

TestCode: 8260W

116

103

%Moisture:

CLIENT GeoLogic NY, Inc.

210087 Project: W Order: K1312307 Matrix: WATER

Inst. ID: MS01_11

Surr: Toluene-d8

Surr: 4-Bromofluorobenzene

ColumnID: Rtx-VMS

01/03/14 15:05 Revision: Col Type:

Lab ID:

K1312307-003A

Client Sample ID: Tower Influent **Collection Date:**

12/26/13 10:00 12/26/13 15:55

PrepDate:

Date Received:

R26576

%REC

%REC

1

BatchNo:

FilcID:

0.10

0.10

1-SAMP-T7902.D

12/30/13 16:46

12/30/13 16:46

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOU	NDS BY GC/MS			SW826	0B	
1,1,1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/30/13 16:46
1,1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/30/13 16:46
cis-1,2-Dichloroethene	0.14 J	0.50	0.10	μg/L	1	12/30/13 16:46
Tetrachioroethene	ND	0.50	0.10	μg/L	1	12/30/13 16:46
trans-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 16:46
Trichloroethene	10.0	0,50	0.10	μg/L	1	12/30/13 16:46
Vinyl chloride	, ND	1.00	0,33	μg/L	1	12/30/13 16:46
Surr: 1.2-Dichloroethane-d4	100	75-130	0.16	%REC	1	12/30/13 16:46

75-125

75-125

Qualiflers:	*	Value exceeds Maximum Contaminant Level	В	Analyte detected in the associated Method Blank
Q	E	Value exceeds the instrument calibration range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below the PQL	ND	Not Detected at the Practical Quantitation Limit (PQL)
	P	Prim./Conf. column %D or RPD exceeds limit	S	Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 01/03/14 15:08 666179



Analytical Results

5854 Butternut Drive

East Syracuse, NY 13057

(315) 445-1900

StateCertNo: 10248 K1312307-004A

12/26/13 9:35

12/26/13 15:55

CLIENT GeoLogic NY, Inc.

Project:

210087

W Order: Matrix:

K1312307 WATER Q

Inst. ID:

MS01_11

ColumnID: Rtx-VMS

01/03/14 15:05

Sample Size 10 mL %Moisture:

8260W TestCode:

Date Received: PrepDate:

Collection Date:

Lab ID:

BatchNo:

R26576

Client Sample ID: Trip Blank

FileID:

1-SAMP-T7911.D

Revision: Col Type:

Analyte	Result Qu	al PQL	MDL	Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUN	IDS BY GC/MS			SW8260)B	
1.1.1-Trichloroethane	ND	0.50	0.10	μg/L	1	12/30/13 21:29
1.1-Dichloroethene	ND	0.50	0.16	μg/L	1	12/30/13 21:29
cis-1,2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 21:29
Tetrachloroethene	ND	0.50	0.10	μg/L	1	12/30/13 21:29
trans-1.2-Dichloroethene	ND	0.50	0.10	μg/L	1	12/30/13 21:29
Trichioroethene	ND	0.50	0.10	μg/L	1	12/30/13 21:29
Vinyl chloride	ND	1.00	0.33	μg/L	1	12/30/13 21:29
Surr: 1,2-Dichloroethane-d4	86	75-130	0.16	%REC	1	12/30/13 21:29
Surr: Toluene-d8	113	75-125	0.10	%REC	1	12/30/13 21:29
Surr: 4-Bromofluorobenzene	102	75-125	0.10	%REC	1	12/30/13 21:29

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Value exceeds the instrument calibration range
- Analyte detected below the PQL
- P Prim./Conf. column %D or RPD exceeds limit
- Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Practical Quantitation Limit (PQL)
- Spike Recovery outside accepted recovery limits

Project Supervisor: Anthony Crescenzi Print Date: 01/03/14 15:08 666180

GeoLogic NY, Inc. CHAIN OF CUSTODY RECORD

CLIENT: GeoLogic

SAMPLERS NAME(S):

PROJECT: 210087

C. T. Gabriel

SAMPLE LOCATION	DATE	TIME	S	PE	NO. of SAMPLES	ANALYSIS REQUIRED			
			WATER	SOIL	AIR				
Cascade	12-26	09:35	х			2	See	Below	
Tower Discharge	12-26	09:50	х			2		11	
Tower Influent	12-26	10:00	х			2	2 "		
Trip Blank	9-17-13		х			2		44	
Relinquished by: C.T. GzSnC1 . C Genta	x. VI	Date	Time	S((Received b	y:	Date	Time	
	TIC NIGHT								
Relinquished by: Sum the Gridge		Date	Time	Bell	Received by		Date 17-26-13	Time /505	
Relinquished by:		Date	Time	Received for Lab by:			Date	Time	
Bell Doraldon				137	Som	-	12-26-13	15:55	
Method of Shipment:	AB PICK-U	JP		TEM	P3.	7ª on.	<i>L</i> α		
COMMENTS: Sample Analysis (1 µg/L report EPA Method 8260B for 1,1,1-Trichloroethane 1,1-Dichloroethene 1,2-Dichloroethene Trichloroethene Tetrachloroethene Vinyl Chloride	ing limit)		<i>a</i> -						

Sample Receipt Checklist

Client Name: GEOLOGIC		Date and Time Received: 12/26/2013 3:55:00 PM					
Work Order Number: K1312307		Received by:	gis				
Checklist completed by: 6 5	12-26-13 Date	Reviewed by:	AC .	12 - 27 - 13 Date			
Delivery	Method: <u>Courier</u>						
Shipping container/cooler in good condition?	Yes 🗹	No 🗌 Not Pre	sent 🗌				
Custody seals intact on shipping container/cooler?	Yes 🗌	No 🗌 Not Pre	sent 🗹				
Custody seals intact on sample bottles?	Yes 🗌	No 🗌 Not Ap	olicable 🗹				
Chain of custody present?	Yes 🗹	No 🗆					
Chain of custody signed when relinquished and received?	Yes 🗹	No 🗆					
Chain of custody agrees with sample labels?	Yes 🗹	No 🗌					
Samples in proper container/bottle?	Yes 🔽	No 🗀					
Sample containers intact?	Yes 🗹	No 🗆					
Sufficient sample volume for indicated test?	Yes 🗹	No 🗀					
All samples received within holding time?	Yes 🗹	No 🗌					
Container/Temp Blank temperature in compliance?	Yes 🗹	No 🗆					
Water - VOA vials have zero headspace?	Yes 🗹	No 🗆 No VOA	ials submitted				
Water - pH acceptable upon receipt?	Yes 🗌	No 🗌 Not App	olicabie 🗹				

Comments:

Corrective Action:

APPENDIX F
SSD/SVE DATA

Phone (315) 431-9730 * Emergency 24/7 (315) 416-2752

NYSDOH ELAP Certificate No. 11830

Analytical Report

Chris Gabriel GeoLogic NY, Inc. 37 Copeland Ave. Homer, NY 13077

TEL: (607) 749-5000 FAX 607-749-5063

RE: 210087

Dear Chris Gabriel:

Monday, December 09, 2013 Order No.: C1312006

Centek Laboratories, LLC received 1 sample(s) on 12/2/2013 for the analyses presented in the following report.

I certify that this data package is in compliance with the terms and conditions of the Contract, both technically and for completeness. Release of the data contained in this hardcopy data package and/or in the computer readable data submitted has been authorized by the Laboratory Manager or his designee, as verified by the following signature.

Centek Laboratories performs all analyses according to EPA, NIOSH or OSHA-approved analytical methods. Centek Laboratories is dedicated to providing quality analyses and exceptional customer service. All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objective except as indicated in the case narrative. All samples were received and analyzed within the EPA recommended holding times. Test results are not Method Blank (MB) corrected for contamination.

We do our best to make our reporting format clear and understandable and hope you are thoroughly satisfied with our services. Please contact your client service representative at (315) 431-9730 or myself, if you would like any additional information regarding this report.

Thank you for using Centek Laboratories. This report can not be reproduced except in its entirety, without prior written authorization.

Sincerely,

William Dobbin

Lead Technical Director

Disclaimer: The test results and procedures utilized, and laboratory interpretations of the data obtained by Centek as contained in this report are believed by Centek to be accurate and reliable

for sample(s) tested. In accepting this report, the customer agrees that the full extent of any and all liability for actual and consequential damages of Centek for the services performed shall be equal to the fee charged to the customer for the services as liquidated damages. ELAP does not offer certification for the following parameters by this method at present time, they are: 4-ethyltoluene, ethyl acetate and propylene.

Centek Laboratories, LLC Terms and Conditions

Sample Submission

All samples sent to Centek Laboratories should be accompanied by our Request for Analysis Form or Chain of Custody Form. A Chain of Custody will be provided with each order shipped for all sampling events, or if needed, one is available at our website www.CentekLabs.com. Samples received after 3:00pm are considered to be a part of the next day's business.

Sample Media

Samples can be collected in an canister or a Tedlar bag. Depending on your analytical needs, Centek Laboratories may receive a bulk, liquid, soil or other matrix sample for headspace analysis.

Blanks

Every sample is run with a surrogate or tracer compound at a pre-established concentration. The surrogate compound run with each sample is used as a standard to measure the performance of each run of the instrument. If required, a Minican can be provided containing nitrogen to be run as a trip blank with your samples.

Sampling Equipment

Centek Laboratories will be happy to provide the canisters to carry-out your sampling event at no charge. The necessary accessories, such as regulators, tubing or personal sampling belts, are also provided to meet your sampling needs. The customer is responsible for all shipping charges to the client's destination and return shipping to the laboratory. Client assumes all responsibility for lost, stolen and any damages of equipment.

Turn Around time (TAT)

Centek Laboratories will provide results to its clients in one business-week by 6:00pm EST after receipt of samples. For example, if samples are received on a Monday they are due on the following Monday by 6:00pm EST. Results are faxed or emailed to the requested location indicated on the Chain of Custody. Non-routine analysis may require more than the one business-week turnaround time. Please confirm non-routine sample turnaround times.

Reporting

Results are emailed or faxed at no additional charge. A hard copy of the result report is mailed within 24 hours of the faxing or emailing of your results. Cat "B" like packages are within 3-4 weeks from time of analysis. Standard Electronic Disk Deliverables (EDD) is also available at no additional charge.

Payment Terms

Payment for all purchases shall be due within 30 days from date of invoice. The client agrees to pay a finance charge of 1.5% per month on the overdue balance and cost of collection, including attorney fees, if collection proceedings are necessary. You must have a completed credit application on file to extend credit. Purchase orders or checks information must be submitted

Rush Turnaround Samples

Expedited turn around times is available. Please confirm rush turnaround times with Client Services before submitting samples.

Applicable Surcharges for Rush Turnaround Samples: Same day TAT = 200%

Next business day TAT by Noon = 150%

Next business day TAT by 6:00pm = 100%

Second business day TAT by 6:00pm = 75%

Third business day TAT by 6:00pm = 50%

Fourth business day TAT by 6:00pm = 35%

Fifth business day = Standard

Statement of Confidentiality

Centek Laboratories, LLC is aware of the importance of the confidentiality of results to many of our clients. Your name and data will be held in the strictest of confidence. We will not accept business that may constitute a conflict of interest. We commonly sign Confidential Nondisclosure Agreements with clients prior to beginning work. All research, results and reports will be kept strictly confidential. Secrecy Agreements and Disclosure Statements will be signed for the client if so specified. Results will be provided only to the addressee specified on the Chain of Custody Form submitted with the samples unless law requires release. Written permission is required from the addressee to release results to any other party.

Limitation on Liability

Centek Laboratories, LLC warrants the test results to be accurate to the methodology and sample type for each sample submitted to Centek Laboratories, LLC. In no event shall Centek Laboratories, LLC be liable for direct, indirect, special, punitive, incidental, exemplary or consequential damages, or any damages whatsoever, even if Centek Laboratories, LLC has been previously advised of the possibility of such damages whether in an action under contract, negligence, or any other theory, arising out of or in connection with the use, inability to use or performance of the information, services, products and materials available from the laboratory or this site. These limitations shall apply notwithstanding any failure of essential purpose of any limited remedy. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, the above limitations may not apply to you. This is a comprehensive limitation of liability that applies to all damages of any kind, including (without limitation) compensatory, direct, indirect or consequential damages, loss of data, income or profit and or loss of or damage to property and claims of third parties.



Date: 11-Dec-13

CLIENT:

GeoLogic NY, Inc.

Project:

210087

Lab Order:

C1312006

CASE NARRATIVE

Samples were analyzed using the methods outlined in the following references:

Compendium of Methods for the Determination of Toxic Organic Compounds, Compendium Method TO-15, January 1999 and Centek Laboratories, LLC SOP TS-80:

All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objective except as indicated in the corrective action report(s). All samples were received and analyzed within the EPA recommended holding times. Test results are not Method Blank (MB) corrected for contamination.

NYSDEC ASP samples:

Canisters should be evacuated to a reading of less than or equal to 50 millitorr prior to shipment to sampling personnel. The vacuum in the canister will be field checked prior to sampling, and must read 28" of Hg (±2", vacuum, absolute) before a sample can be collected. After the sample has been collected, the pressure of the canister will be read and recorded again, and must be 5" of Hg (±1", vacuum, absolute) for the sample to be valid. Once received at the laboratory, the canister vacuum should be confirmed to be 5" of Hg,±1". Please record and report the pressure/vacuum of received canisters on the sample receipt paperwork. A pressure/vacuum reading should also be taken just prior to the withdrawal of sample from the canister, and recorded on the sample preparation log sheet. All regulators are calibrated to meet these requirements before they leave the laboratory. However, due to environmental conditions and use of the equipment Centek can not guarantee that this criteria can always be achieved.

	-	τ	J
	ς	U	١
(Ć	2)
	C	D	١
	,	5	
	C	2	١
	-	_	h
	-		_
	C)

		Centek Chain of Custody				Site Name:	Detection Limit Report Level				
Contak Laboratories		143 Midler Par	rk Drive			Project: 21008	7	5ppbv	Leve	<u> </u>	
		Syracuse, NY 315-431-9730 www.CentekL		Vapor Intrusion	n & IAQ	PO#: Quote # Q-	026	1ug/M3 1ug/M3 +TCE .25	Level		
Turnaround Time:	Check One	Rush TAT Surcharge %	Due Date:	Company:	eologic		Company:	e If Same: 🔽	<u> </u>		
5 Business Days 4 Business Days 3 Business Days 2 Business Days	25% Address: P 50% City, State, Z			Address: P	D BOX 350		Invoice to: Address:	Invoice to: Address: City, State, Zip Email:			
Next Day by 5pm Next Day by Noon Same Day		100% 150% 200%		Email: Chrisg @ Ge Phone: 607-749-5		risg @ Geologic-net					
Sample ID		Date	Sampled	Canister Number		Analysis Request	Phone:	Comments	Vacu Start/S		
SUE /55 D		11-26-1	3	460	-	TO-15			D-30	-4.0	
								hene hene ne nene	ers only:		
Chain of Custody Sampled by:	Jos	Print Name	» (Signature	Vonnel	Date/Time	Courter CIRCLE OF		, , , , , , , , , , , , , , , , , , , ,	
Relinquished by:	C.T.	Gasnel of	Gerloge	NY, In			11-26-13/14	FOR LAB USE ONLY		/	
Received at Lab by:	1/N	ik Maa	11)ARIN	$\mathcal{L}_{\mathcal{O}}$	1 /\ \ ~	\sim	WE-72-15	Mork Order # (/	グノクー() ()	(n 🚭	

^{***} By signing Centek Labs Chain of Custody, you are accepting Centek Labs Terms and Conditions listed on the reverse side.



Sample Receipt Checklist

Client Name GEOLOGIC				Date and Tir				12/2/2013
Work Order Numbe C1312006 Checklist completed by Signature		2-1	3	Received by Reviewed by)	_	/2/13
Matrix:	Carrier name:	<u>FedEx</u>						
Shipping container/cooler in good condition?		Yes 🖢	~	No 🗌	Not Presen			
Custody seals intact on shippping container/coo	ler?	Yes [No 🗆	Not Presen	✓		
Custody seals intact on sample bottles?		Yes [No 🗆	Not Presen	\checkmark		
Chain of custody present?		Yes 🛚	/	No 🗆				
Chain of custody signed when relinquished and	received?	Yes 🖸	/	No 🗌				
Chain of custody agrees with sample labels?		Yes 🛚	/	No 🗀				
Samples in proper container/bottle?		Yes 🖸	/	No 🗌				
Sample containers intact?		Yes 🖸	/	No 🗌				
Sufficient sample volume for indicated test?		Yes 🖸	7	No 🗌				
All samples received within holding time?		Yes 🖸	/	No 🗌				
Container/Temp Blank temperature in compliand	ce?	Yes 🛚	Z	No 🗆				
Water - VOA vials have zero headspace?	No VOA vials subm	itted 🛚	/	Yes 🗌	No 🗀			
Water - pH acceptable upon receipt?		Yes [No 🗹				
	Adjusted?		CI	necked by		_		
Any No and/or NA (not applicable) response mu	st be detailed in the co	omment	s sectio	n be				
Client contacted	Date contacted:			Pers	on contacted			
Contacted by:	Regarding:							
Comments:							· · · · · · · · · · · · · · · · · · ·	
Corrective Action								
			wit					t ala anda anda anda anda anda anda anda a



Date: 11-Dec-13

CLIENT:

GeoLogic NY, Inc.

Project:

210087

Lab Order:

C1312006

Work Order Sample Summary

Lab Sample ID Client Sample ID

Tag Number

Collection Date

Date Received

C1312006-001A SVE/SSD

460

11/26/2013

12/2/2013

Lab Order:

C1312006

Client:

GeoLogic NY, Inc.

Project:

210087

DATES REPORT

Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
C1312006-001A	SVE/SSD	11/26/2013	Аіг	lug/M3 by Method TO15			12/5/2013
				lug/M3 by Method TO15			12/3/2013
				lug/M3 by Method TO15			12/4/2013

Centek Laboratories, LLC

CLIENT: GeoLogic NY, Inc. Client Sample ID: SVE/SSD

Lab Order: C1312006 Tag Number: 460

Project: 210087 **Collection Date:** 11/26/2013

Lab ID: C1312006-001A **Matrix:** AIR

Analyses	Result	**Limit Qu	ual Units	DF	Date Analyzed	
FIELD PARAMETERS		FLD			Analyst:	
Lab Vacuum In	-2	"Hg		12/2/2013		
Lab Vacuum Out	-30	"Hg			12/2/2013	
1UG/M3 BY METHOD TO15		TO-15			Analyst: RJP	
1,1,1-Trichloroethane	6.8	1.5	ppbV	10	12/3/2013 6:12:00 PM	
1,1-Dichloroethene	0.25	0.15	ppbV	1	12/4/2013 4:24:00 AM	
1,2-Dichloroethane	< 0.15	0.15	ppbV	1	12/4/2013 4:24:00 AM	
Tetrachloroethylene	11	1.5	ppbV	10	12/3/2013 6:12:00 PM	
Trichloroethene	1800	120	ppbV	810	12/5/2013 9:42:00 PM	
Vinyl chloride	0.77	0.15	ppbV	1	12/4/2013 4:24:00 AM	
Surr: Bromofluorobenzene	90.0	70-130	%REC	1	12/4/2013 4:24:00 AM	

Qualifiers: ** Reporting Limit

B Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

JN Non-routine analyte. Quantitation estimated.

S Spike Recovery outside accepted recovery limits

. Results reported are not blank corrected

E Value above quantitation range

J Analyte detected at or below quantitation limits

Date: 30-Dec-13

ND Not Detected at the Reporting Limit

Page 1 of 1

Centek Laboratories, LLC

CLIENT: GeoLogic NY, Inc. Client Sample ID: SVE/SSD

Lab Order: C1312006 Tag Number: 460

Project: 210087 **Collection Date:** 11/26/2013

Lab ID: C1312006-001A **Matrix:** AIR

Analyses	ses Result **Limit Qual Units		DF	Date Analyzed		
1UG/M3 BY METHOD TO15		TO-15			Analyst: RJP	
1,1,1-Trichloroethane	38	8.3	ug/m3	10	12/3/2013 6:12:00 PM	
1,1-Dichloroethene	1.0	0.60	ug/m3	1	12/4/2013 4:24:00 AM	
1,2-Dichloroethane	< 0.62	0.62	ug/m3	1	12/4/2013 4:24:00 AM	
Tetrachloroethylene	77	10	ug/m3	10	12/3/2013 6:12:00 PM	
Trichloroethene	10000	660	ug/m3	810	12/5/2013 9:42:00 PM	
Vinyl chloride	2.0	0.39	ug/m3	1	12/4/2013 4:24:00 AM	

Qualifiers: ** Reporting Limit

B Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

JN Non-routine analyte. Quantitation estimated.

S Spike Recovery outside accepted recovery limits

. Results reported are not blank corrected

E Value above quantitation range

J Analyte detected at or below quantitation limits

Date: 30-Dec-13

ND Not Detected at the Reporting Limit

Page 1 of 1