


Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96 10 01

Site Name: Pollution Abatement Services		Class: 2	Number: 7-38-001
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
O&M Information:    O&M Start: 9004		End:	Annual Cost:    Estimated
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input checked="" type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input checked="" type="checkbox"/> Leachate Collection	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input type="checkbox"/> Other:			
<b>O&amp;M Review Information:</b>			
Reports: <u>Quarterly Progress Reports through September 2001,</u> <u>O&amp;M and LTM Plan (08/98) by the Performing Settling Defendants</u>			
Inspection: <u>06/04/01 by John Strang. Monthly inspections are done by RP and RP's consultant.</u>			
Sampling: <u>None by DEC. Long-term Monitoring for PCBs by BB&amp;L on 06/04/01 (sediment and fish - yearlings).</u>			
Other:			
<b>Conclusions:</b>			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>The Annual Report shows that removal of the leachate from the holding tank each month is helping to keep the groundwater level inside the slurry wall below the gw level outside of the slurry wall (inward gradient).</u>			
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>N/A</u>			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: _____			
Other: <u>Site was in good condition and could use a site mowing. This was discussed with the site project manager (6/4/01)</u>			
Recommendations: <u>Continue with O&amp;M oversight - the Superfund Cooperative Agreement Grant runs to 03/31/03.</u>			
Next Review Report <u>1212002.</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class: _____			
Comments: <u>An agreement between the USEPA and the Performing Settling Defendants (RP) was signed in Fall 1998. The RP has taken over all O&amp;M activities at the site starting November 1998.</u>			
<u>The PAS Site will stay a Class 2 Site. Though all remedial action is complete, the site will become a Class 4 (O&amp;M) when the site is deleted from the National Priority List.</u>			
<u>The EPA Support Agency Assistance Grant that pays the DEC to do O&amp;M oversight (i.e. read reports, analyze data) was approved between EPA and the DEC on July 21, 1999. We are submitting Superfund Cooperative Assistance Grant reports on a quarterly basis to the EPA.</u>			
Project Manager  Signature		Reviewer:  Signature	
John R. Strang    Bur. Of Haz Site Control    402-9640 Name    Region or Bureau    Telephone		Gerald J. Rider, Jr.    Bur. Of Haz Site Control    402-9640 Name    Region or Bureau    Telephone	