

#### November 28, 1983

New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12232

Attention: Mr. Norman H. Nosenchuck, P.E.

Director - Division of Solid Waste

RE: PHASE I - PRELIMINARY INVESTIGATION OF THE GOLDEN ROAD DISPOSAL SITE

Dear Mr. Nosenchuck:

Attached, please find our Phase I - Preliminary Investigation of the above referenced site. These activities have been carried out under the New York State "Superfund" legislation.

Pertinent information regarding this site is summarized below.

Briefly, this phase of the study found that the Golden Road Disposal Site (site I.D. 8-28-021) is an 8-acre, inactive landfill located in a once-rural area of the Town of Chili, Monroe County, New York. The site is divided by Conrail railroad tracks into two separate areas, both of which lie immediately adjacent to designated wetlands and are characterized by poor drainage and a high water table.

The site was active from 1955 through 1976, receiving a wide variety of waste types which included U.S. Army artillery shells, household refuse, metal slag, flyash and junked vehicles. Much of the actual filling of the site was accomplished using foundry sand hauled from a local casting company. Approximately 300 rusted, leaking barrels are piled in several places, some of which are lying in the ponded water of the wetland. Chemical spillage is obvious on the soil surface.

Preliminary investigative work at the site has included the sampling and analysis of the barrels, surface waters, soil and pond sediments on-site, as well as the monitoring of local water wells. The results of this preliminary program have indicated that the organic chemicals deposited at the site have contaminated the soil on-site, adjacent surface waters and the groundwater beneath the site. The site has a potential to impact both public health and the surrounding environment. Although most of the population in the vicinity of the site is served by the Monroe County Water Authority, there are some residences that rely upon the groundwater as a primary of backup water source.

In compiling the hazard ranking score, the Golden Road Disposal Site was found to have a score for  $S_m$  equal to 14.5. However, because some route rating factors, due to data inadequancies, involve a certain degree of subjectivity a range for the  $S_m$  score was developed and found to be 10.0 to 15.0.

Remedial action suggested as appropriate to this site to be carried out in Phase II - Field Investigations is summarized in Section 7.0 of the attached report. The total cost of the proposed work is \$32,980.00.

Should you have any questions or require additional information, please feel free to contact me directly.

Sincerely,

RECRA RESEARCH, INC.

Richard S. Crouch

Richard L. Crouch Project Manager GOLDEN ROAD DISPOSAL SITE

NEW YORK STATE SUPERFUND PHASE I SUMMARY REPORT

FINAL

November 28, 1983

Prepared By:

Recra Research, Inc. 4248 Ridge Lea Road Amherst, New York 14226

For:

New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233-0001

## GOLDEN ROAD DISPOSAL SITE

# NEW YORK STATE SUPERFUND PHASE I SUMMARY REPORT

## TABLE OF CONTENTS

					Page No.
1.0	) E	xecu	ıtive Summ	ary	1
2.0	) s	ite	Descripti	on	3
3.	) P	reli	iminary Ha	zard Ranking System Score	
	3	3.1	Documenta	tion Records for Hazard Ranking System	
	3	3.2	EPA Preli	minary Assessment (Form 2070-12)	~-
	3	3.3	EPA Site	Inspection Report (Form 2070-13)	
4.	o s	Site	History .		6
5.	o s	Site	Data		9
	5	5.1	Site Area	Surface Features	9
			5.1.1	Topography and Drainage	9
			5.1.2	Environmental Setting	10
	5	5.2	Site Hydr	ogeology	11
			5.2.1	Geology	11
			5.2.2	Soils	11
			5.2.3	Groundwater	12
	5	5.3	Previous	Sampling and Analyses	1.3
			5.3.1	Groundwater Quality Data	13

## TABLE OF CONTENTS (Cont.

				Page No.
		5.3.2	Surface Water Quality Data	13
		5.3.3	Air Quality Data	13
		5.3.4	Other Analytical Data	13
6.0	Adeq	uacy of	Available Data	15
7.0	Prop	osed Pha	ase II Work Plan	17
	7.1	Object	ives	17
	7.2	Scope	of Work	17
		7.2.1	Air Monitoring	. 17
		7.2.2	Geophysical Exploration	19
		7.2.3	Subsurface Investigation	19
		7.2.4	Monitoring Well Installation	21
		7.2.5	Sampling and Analysis	23
		7.2.6	Engineering Evaluation Report/HRS Score	27
	7.3	Estima	ted Costs	29

Appendix A - Data Sources and References

Appendix B - Revised "Hazardous Waste Disposal Site Report"

## List of Tables

	Page No.
Table 1 - Analytical Parameters	27
<u>List of Figures</u>	
	Page No.
Figure 1 - Vicinity Map	4
Figure 2 - Site Map	5

## 1.0 EXECUTIVE SUMMARY

The Golden Road Disposal Site is an 8-acre, inactive landfill located in a once-rural area of the Town of Chili, Monroe County, New York which is rapidly being developed for residential purposes. The site is divided by Conrail railroad tracks into two separate areas. Both of these disposal areas lie immediately adjacent to registered wetlands, and are characterized by poor drainage and a high water table. the relief of each disposal area is generally flat, the result of extensive landfilling which has elevated the site surface to approximately 10 feet above the surrounding terrain.

The site was active from 1955 through 1976, receiving a wide variety of waste types which included U.S. Army artillery shells, household refuse, metal slag, flyash and junked vehicles. Much of the actual filling of the site was accomplished using foundry sand hauled from a local casting company. Structural steel and large fuel storage tanks are scattered throughout the southern disposal area, which was also used for drum disposal. Approximately 300 rusted, leaking barrels are piled in several places, some of which are lying in the ponded water of the wetland. Chemical spillage is obvious on the soil surface.

This site has generated a great deal of interest in the agencies responsible for the environmental affairs of Monroe County. Preliminary investigative work has included the sampling and analysis of the barrels, surface waters, soil and pond sediments on-site, as well as the


monitoring of local water wells. The results of this preliminary program have indicated that the organic chemicals deposited at the site have contaminated the soil on-site, adjacent surface waters and the groundwater beneath the site.


The site has a potential to impact both public health and the surrounding environment. Although most of the population in the vicinity of the site is served by the Monroe County Water Authority, there are some residences that rely upon the groundwater as a primary or backup water source. In addition, three registered wetlands are down-gradient from the site, each with evident wildlife populations.

### 2.0 SITE DESCRIPTION

The Golden Road Disposal Site is located in the Town of Chili, Monroe County, New York (Figure 1). The site was operated from 1955 through 1976, during which it received solid wastes from a variety of sources in the Rochester area. The filling of the site was largely accomplished using foundry sand, but a great deal of structural steel, fuel tanks and barrels presently lie about the site (Figure 2). No records were kept concerning the volume of wastes entering the site. It is obvious upon inspection that a portion of the wetland area was filled during the operation of the site. Analytical testing has indicated that contamination of the associated water resources has occurred.

The owner of the site, Mr. Howard Fitzsimons, Jr., has been involved with the site throughout it's use as a disposal site. He denies any responsibility for the barrels containing chemical wastes, but has acknowledged that some of the drums on site were placed there by a contractor building Route 490.





## 3.0 PRELIMINARY HAZARD RANKING SYSTEM SCORE

Facility	Name: _	Golden Road Disposal	Site	_							
Location	GOLDEN MORE DISTORAL STILE										
EPA Regi	.on: _	2		_							
Person(s	) in Char	ge of the Facility:	Howard Fitzsimons, Jr.	_							
	•1		227 Golden Pond	_							
			Chili. New York 14624	_							
Name of	Reviewer:	Recra Research	Date: 6/3/83	_							
General	Description	on of the Facility:									
Inactive	nation rou for rating landfill Dumping o	site. Two disposal	areas separated by railroades, including barrels of	<b>-</b>							
chemical	s. Landfi	lling of wetland usi	ng foundry sand.	_							
				_							
				_, '							
			<del></del>	_							
Scores:	S <sub>M</sub> = 14.5	(S <sub>gw</sub> = 24.5 S	sw = 5.0 Sa = 0 )	_							
	SFE - N/	<b>A</b> ·									
	s <sub>DC</sub> - 16.	•									
		Range for	$S_{M} = 10^{\circ} - 15^{\circ}$								

HRS COVER SHEET

GROUND WATER ROUTE WORK SHEET									
Rating Pactor	r	Assigned Value (Circle One)		Multi- plier	Score	Max. Score	Ref. (Section)		
OBSERVED RE	LEASE	0 (65)		1	45	45	3.1		
If observed If observed	release	is given a score	e of 4 e of 0	5, proce , procee	ed to 1	line [	3] .  -		
2 ROUTE CHARAC	CTERISTIC	S					3.2		
Depth to Aqu Concern	ilfer of	0 1 2(3)		2	6	6			
Net Precipit Permembility	y of the	0 1 2 3 0 1 2 3		1	ス よ	3 3			
Unsaturated Physical Sta		012(3)		_1	3	3			
	Total	Route Character:	Lstics	Score	13	15			
3 CONTAINMENT		0 1 2(3)		1	3	3	3.3		
WASTE CHARAC	TERISTIC	S					3.4		
Toxicity/Per Hazardous Wa Quantity		0 3 6 9 12 3 0 1 2 3 4 5	15 18 6 7 8	1	3	18 8			
ſ	Total	Waste Character	ristic	s Score	12	26			
TARGETS						·	3.5		
Ground Vater Distance to est Well/Po Served	Near-	0 12 3 0 4 6 8 10 12 16 18 20 24 30 32 35	40	3	620	9 40			
	Total	Targets Score			26	49	. **		
6 If line 1 If line 1	is 45, m is 0, mu	ulciply [] x lciply [] x []		x [5] x [5]	, (*	37,330	14940		
7 Divide line	6 by 57,	330 and multiply	by 10	00 5	gu = 0	24.5			

GROUNDWATER ROUTE WORK SHEET

SURFACE WATER ROUTE WORK SHEET									
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Max. Score	Ref.				
OBSERVED RELEASE	υ <b>(</b> (3)	1	45	45	4.1				
	is given a value of 45, is given a value of 0.			4 21.					
2 ROUTE CHARACTERISTI	_				4.2				
Facility Slope and Intervening Terrai		1	3	3					
l-yr. 24-hr. Rainfa Distance to Nearest	11 0(1)2,3	1 2	6	3 6					
Surface Water Physical Sta <u>te</u>	0 1 2(3)	11	3	3					
Tota	l Route Characteristics	Score	13	15					
CONTAINMENT	0 1 2 3	1	3	3	4.3				
WASTE CHARACTERISTI	CS				4.4				
Toxicity/Persistenc Hazardous Waste Quantity	0 3 6 9 12 15 18 0 1 2 3 4 5 6 7 8		9	15 8					
Tota	l Waste Characteristics S	Score .	12	26	1				
I TARGETS	. ,				4.5				
Surface Water Use Distance to a Sensi Environment		3 2	090	9 6					
Population Served/ Distance to Water Intake Downstream	0 4 6 8 10 12 16 18 20 24 30 32 35 40	1	)	40					
Toca	L Targets Score		6	55					
	multiply 1 x 4 x ultiply 2 x 3 x 4	5 x 5	64	.,350	3,240				
ivide line 5 by 64	,350 and multiply by 100	Ss	<u>.</u> - 5.	0					

SURFACE WATER ROUTE WORK SHEET

	AIR ROUTE WORK SHEET									
	Rating Factor		Assigned (Circle		; Multi-   plier	Score	Max.	Ref. (Section		
	OBSERVED RELEAS	<u> </u>	0	45	:	10	45	5.2		
	Date and Location	)E:								
	Sampling Protoco	ol:				·				
	If line 1 is If line 1 is	0, Eb	ien Sa = 0. hen proces	. Enter of	n line 5	·				
	WASTE CHARACTERI	STICS			•			5.2		
	Reactivity and Incompatibility		0 1 2 3	3	1		3			
	Toxicity Hazardous Waste Quantity		0123	3 4 5 6 7 8	3 B 1		9 8			
	Te	tal W	este Chara	cteristics	Score		20			
D.	TARGETS							5.3		
	Population Within	n.	0 9 12 21 24 2		1 .		30			
	Distance to Sens Environment	izive	0 1 2 3		2		6	ļ		
	Land Use		0 1 2 3		1		3			
				·						
l										
			•							
	T	ocal '	Targets Sc	016			39			
0	Mulciply 1 x [	2 ×	<u> </u>			3	5,100			
3	Divide line 4 by	35,1	00 and mul	ciply by l	.00 \$	. · C	)			

AIR ROUTE WORK SHEET

	S	s <sup>2</sup>
Groundwater Route Score (Sgw)	24.5	400,3
Surface Water Route Score (S <sub>SW</sub> )	5.0	25.0
Air Route Score (S <sub>2</sub> )	0	0
$s_{gw}^2 + s_{sw}^2 + s_a^2$		625,3
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2}$		25.0
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2} / 1.73 (s_M)$		14.5

j

WORK SHEET FOR COMPUTING  $\mathbf{S}_{\mathbf{M}}$ 

I	IRE AND	EXP	TOZION MO	RK SHEET			
Rating Factor	Assigned (Circle			Multi- plier	•	Max.	Ref.
Containment	1	3 _		1		3	7.1
Waste Characteristics '							7.2
Direct Evidence	. 0	3		1		3	
lgnicability	0 1 2	: 3		1		3	
Reactivity	0 1 2	3		1		3	
incompatibility	0 1 2	. 3		1		3	
Hazardous Waste Quantity	0 1 2	3 4	5 6 7 8	1		8	
Total Was	te Chara	cter	istics Sc	ore		20	
Targets							7.3
Distance to Nearest Population	0 1 2	3 4	5	1		5	
Distance to Nearest Building	0 1 2	3		1		3	
Distance to Sensitive Environment	0 1 2	3		1		3	
Land Use	012	3		1 .		3	
Population Within 2-Mile Radius	0 1 2	3 4	5	1		5	
Buildings Wilhin 2-Mile Radius	012	3 4	5	1	÷	5	
			1				
Total Targe	t Score					24	
Miltiply 1 x 2 x 3						1,440	
vide line 5 by 1,440 and mu					SFE -	0///	

FIRE AND EXPLOSION WORK SHEET

	DIRECT CONTACT WORK	SHZET			
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Max. Score	Ref. (Section)
Observed Incident	<b>6</b> 45	1	0	45	8.1
	proceed to line 4 proceed to line 2				
2 Accessibility	0 1 2(3)	1	3	3	8.2
Containment	• 🕦	1	15	15	8.3
Waste Characteristic Toxicity	0 1(2)3	5	10	15	8.4
Targets  Population within l-mile radius Distance to a critical habitat	(O)1 2 3	4	80	20	8.5
	Total Targets Score		8	32	
	multiply $ 1  \times  4  \times  5 $ multiply $ 2  \times  3  \times  4  \times$	<u> </u>	3600	21,600	
7	21,600 and multiply by 100		S <sub>DC</sub> -	16.7	

DIRECT CONTACT WORK SHEET

## 3.1 <u>Documentation Records for Hazard Ranking System</u>

INSTRUCTIONS: The purpose of these records is to provide a convenient way to prepare an auditable record of the data and documentation used to apply the Hazard Ranking System to a given facility. As briefly as possible summarize the information you used to assign the score for each factor (e.g., "Waste quantity = 4,230 drums plus 800 cubic yards of sludges"). The source of information should be provided for each entry and should be a bibliographic-type reference that will make the document used for a given data point easier to find. Include the location of the document and consider appending a copy of the relevant page(s) for ease in review.

FACILITY	name: _	Golden Ro	oad Disp	<u>osal Sit</u>	<u>e</u>			
							•	
LOCATION:	Town	of Chili,	Monroe	County,	New	York		

#### GROUND WATER ROUTE

#### L OBSERVED RELEASE

Contaminants detected (5 maximum):

Copper (Ref. 1) Zinc Fluoride

Rationale for attributing the contaminants to the facility:

Disposal site located upgradient from contaminated wells

#### 2 ROUTE CHARACTERISTICS

## Depth to Aquifer of Concern

Name/description of aquifers(s) of concern:

No significant aquifers and few active wells in area. Most groundwater flow is through weathered zone at bedrock surface. Deep wells often in hydraulic contact with overburden, Aquifer of concern defined as overburden aquifer. (Ref. 2)

Depth(s) from the ground surface to the highest sessonal level of the saturated zone [vater table(s)] of the aquifer of concern:

Depth to saturated zone estimated to be less than 20 feet. No on-site data to confirm this; however, ponded water on site and adjacent to site. Site exists in wetland area.

Depth from the ground surface to the lowest point of waste disposal/ storage:

Estimated to be < 10 feet

## Net Precipitation

Mean annual or seasonal precipitation (list months for seasonal): 32.67 Inches per year (Ref. 3)

Mean annual lake or seasonal evaporation (list months for seasonal): 20.0 Inches per year (Ref. 4)

Net precipitation (subtract the above figures): 6.67 Inches per year

#### Permeability of Unsaturated Zone

Soil type in unsaturated zone:

Surface soils are shallow muck (poorly drained, gently sloping, often ponded for long periods) (Ref. 5)

Permeability associated with soil type:

Well decomposed much soils: rapid permeability

10-3 to 10-5 cm/sec

## Physical State

Physical state of substances at time of disposal (or at present time for generated gases):

Liquids studges (Ref. 6)

#### 3 CONTAINMENT

#### Containment

Method(s) of vaste or leachate containment evaluated: Containers: drums leaking, no liner (Ref. 7)

Method with highest score:

See above

#### 4 WASTE CHARACTERISTICS

## Toxicity and Persistence

Compound(s) evaluated:

tolvene (Ref. 6) xylene

## Compound with highest score:

Both of above: Combined Toxicity/Persistence score = 9.

multiply by 1.0 weighting factor:  $9 \times 1.0 = 9$ 

## Hazardous Waste Quantity

Total quantity of hazardous substances at the facility, excluding those with a containment score of 0 (Give a reasonable estimate even if quantity is above maximum):

300+ barrels on site (Ref. 8)

Basis of estimating and/or computing waste quantity:

(Ref. 8)

#### 5 TARGETS

#### Ground Water Use

Use(s) of equifer(s) of concern within a 3-mile radius of the facility:

Drinking water with alternate sources available (Ref. 9)

## Distance to Nearest Well

Location of nearest well drawing from aquifer of concern or occupied building not served by a public water supply:

227 Golden Road

Distance to above well or building:

400 feet

## Population Served by Ground Water Wells Within a 3-Mile Radius

Identified water-supply well(s) drawing from aquifer(s) of concern within a 3-mile radius and populations served by each:

Average 14.1 wells per square mile in Town of Chili (Ref. 10) (9.4 sq. miles X 14.1 wells/sq. mile) (3.8 people/well) = 504 people

Computation of land area irrigated by supply well(s) drawing from aquifer(s) of concern within a 3-mile radius, and conversion to population (1.5 people per acre):

300 acres x 1.5 = 450 people (Ref. 11)

Total population served by ground water within a 3-mile radius:

504 + 450 = 954 people

#### SURFACE WATER ROUTE

#### 1 OBSERVED RELEASE

Contaminants detected in surface water at the facility or downhill from it (5 maximum):

Cadmium (Ref. 12)

Benzene

Toluene

Rationale for attributing the contaminants to the facility:

Pond on site sampled

#### 2 ROUTE CHARACTERISTICS

## Facility Slope and Intervening Terrain

Average slope of facility in percent:

Approximately 0% (estimated using USGS goad map)

Name/description of nearest downslope surface water:

Un-named pond with intermittent stream draining it.

Drains to wetland

Average slope of terrain between facility and above-cited surface water body in percent:

Approximately 0% (estimated from USGS good map)

Is the facility located either totally or partially in surface water?

Is the facility completely surrounded by areas of higher elevation?  $\mathcal{N}_{\mathsf{O}}$ 

## 1-Year 24-Hour Rainfall in Inches

2.0 inches (Ref. 13)

## Distance to Nearest Downslope Surface Water

O feet (pond is on site)

## Physical State of Waste

Liquid, sludges (Ref. 6)

#### 3 CONTAINMENT

## Containment

Method(s) of waste or leachate containment evaluated:

Containers! Drums Leaking, no liner (Ref. 7)

Method with highest score:

See above

#### 4 WASTE CHARACTERISTICS

## Toxicity and Persistence

Compound(s) evaluated

toluene (Ref. 6) xylene

Compound with highest score:

Both of above: Combined Toxicity/Persistence score = 9 Multiply by 1.0 weighting factor: 9 x 1.0 = 9

## Hazardous Waste Quantity

Total quantity of hazardous substances at the facility, excluding those with a containment score of 0 (Give a reasonable estimate even if quantity is above maximum):

300+ barrels on site (Ref. 8)

Basis of estimating and/or computing waste quantity:

(Ref. 8)

#### 5 TARGETS

#### Surface Water Use

Use(s) of surface water within 3 miles downstream of the hazardous substance:

No known water intakes in area (Ref. 14)

Is there tidal influence?

No

## Distance to a Sensitive Environment

Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:

N/A

Distance to 5-acre (minimum) fresh-water wetland, if I mile or less:

Site adjacent to designated Class II wetland (Ref. 15)

Distance to critical habitat of an endangered species or national wildlife refuge, if I wile or less:

/Y/A

## Population Served by Surface Water

Location(s) of water-supply intake(s) within 3 miles (free-flowing bodies) or 1 mile (static water bodies) downstream of the hazardous substance and population served by each intake:

No known water intakes in area (Ref. 13)

Opeople served

Computation of land area irrigated by above-cited intake(s) and conversion to population (1.5 people per acre):

OAcres (Ref. 11)

Total population served:

O people

Name/description of nearest of above water bodies:

un-named ponds and intermitters streams

Distance to above-cited intakes, measured in stream miles.

Estimated to be 2-3 miles

1 OBSERVED RELEASE

Contaminants detected:

No data

Date and location of detection of contaminants

N/A

Methods used to detect the contaminants:

NA

Rationale for attributing the contaminants to the site:

N/A

2 WASTE CHARACTERISTICS

Reactivity and Incompatibility

Most reactive compound:

NA

Most incompatible pair of compounds:

N/A

## . Toxicity

Most toxic compound:

N/A.

## Hazardous Waste Quantity

Total quantity of hazardous waste:

N/A

Basis of estimating and/or computing waste quantity:

N/A

## 3 TARGETS

## Population Within 4-Mile Radius

Circle radius used, give population, and indicate how determined:

0 to 4 mi

0 to 1 mi

0 to 1/2 mi

0 to 1/4 mi

N/A

## Distance to a Sensitive Environment

Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:

N/A

Distance to 5-acre (minimum) fresh-water wetland, if I mile or less:

MA

Distance to critical habitat of an endangered species, if I mile or less:

N/A

#### Land Use

Distance to commercial/industrial area, if I mile or less:

NIA

Distance to national or state park, forest, or wildlife reserve, if 2 miles or less:

N/A

Distance to residential area, if 2 miles or less:

N/A

Distance to agricultural land in production within past 5 years, if 1 mile or less:

NIA

Distance to prime agricultural land in production within past 5 years, if 2 miles or less:

NIA

Is a historic or landmark site (National Register or Historic Places and National Natural Landmarks) within the view of the site?

NIA

SER	7
-----	---

# POTENTIAL HAZARDOUS WASTE SITE

LIDENTIFICATION				
	02 SITE NUMBER			
NY	8-28-021			

PART 1 - SITE INFORMATION AND ASSESSMENT NY 8-28-021					
IL SITE NAME AND LOCATION	<del></del>		<del></del>		
Golden Road Disposal	Site	Golden Ro	SPECIFIC LOCATION IDENTIFIER		
Town of Chili		04 STATE 05 ZIP COOE 0	Manroe -	07COUNTY 36 CONG COSE DIST	
	10 45 45:0				
Route 490 to Chili Ce Golden Road. A tracks on west	ccess roads	immediately	adjacent to	de Drive to	
IIL RESPONSIBLE PARTIES  01 OWNER ######		OZ STREET (Seconds, Prints), Prints	- desirable		
Howard Fitzsimons	:, JC	227 Go	Iden Road		
Chili (Town)		NY 14624	1714 594-233	s	
Oe CITY		10 STATE 11 ZP COOE	12 TELEPHONE NUMBER		
IS TYPE OF OWNERSHIP (Cross and)  A PRIVATE IS FEDERAL:  I F. OTHER:  14 OWNER/OPERATOR NOTIFICATION ON FILE count of the	(Secoly)	C. G. STATE	DD.COUNTY DE.M	UNICIPAL	
A. RCRA 3001 DATE RECEIVED:	YEAR IS BLUNCONTROLL	ED WASTE SITE CERCIA 100	DATE RECEIVED: /	GAY YEAR [] G. NONE	
IV. CHARACTERIZATION OF POTENTIAL HAZ			·	•	
XYES DATE 5,3,83		CONTRACTOR DE CIA DF. OTHER: RECTA Resear		RCONTRACTOR	
02 STE STATUS (Care) opt	CONTRACTOR NAME(S): _	ADON	<del></del>		
DALACTIVE TO BL INACTIVE II C. UNIONO		1955   1970 EGNY END ENDING Y		VIN	
toluene Xylene					
	NT ANDIOR POPULATION		<del></del>		
On-site soil, surface	water and o	ff-site ground	dwater contam	imation detected s II wetland	
No liner, high water	water and o	ff-site ground	dwater contam	imation detected SII wetland	
No liner, high water On-site soil, surface Drinking water wells us	water and o	ff-site ground	dwater contam	imation detected SII wetland	
NO liner, high water On-site soil, surface Drinking water wells us V. PRIORITY ASSESSMENT OI PROMITY FOR INSPECTION COMPANY	water and o	ff-site ground waters drain to	dwater contam	imation detected SII wetland	
NO liner, high water On-site soil, surface Drinking water wells us V. PRIORITY ASSESSMENT OI PROMITY FOR INSPECTION CO. A. MEDIUM	ed and surface u	ff-site ground waters drain to	dwater contam	imation detected SII wetland  COSTELEPHONE NUMBER  17161838-6200	
NO liner, high water On-site soil, surface Drinking water wells us V. PRIORITY ASSESSMENT OI PROMITY FOR INSPECTION INC.  VI. INFORMATION AVAILABLE FROM OI CONTACT	ed and surface u	exters drain to	d water contam designated Clas	CO TELEPHONE NUMBER  (7161838-6200)  CO DATE	

		$\Box \Lambda$	
,		-	
₹/	-	/	

EFAFORM 2070-12 (7-81)

# -POTENTIAL HAZARDOUS WASTE SITE

	TIFICATION
NIV	8-28-071

A SOLED I PUNCE TO CHER	R FINES D'AL LIQUID	TOME 75 +	03 WASTE CHARACTI DECA. TORIC ID S. CORRO ID C. RADIOA SLZO, PERSIS	U E SOL SIVE O F. INTE CTIME JECT FLA	LIBLE LI HIGHLY ECTIOUS II J. EXPLO MMAGLE II K. REACT	SIVE TIVE PATIBLE
WASTET			· [	,		
CL C	SUBSTANCE NAME SLUDGE	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 CCMMENTS	<del></del>	_ <del></del>
CLW	OILY WASTE	<del> </del>	<del> </del>	<del></del>	<del></del>	
SOL	SOLVENTS	300+	Barrels			
PS0	PESTICIOES .	3001	Carreis	<del></del>	<del> </del>	<del></del>
0CC ·	OTHER CRGANIC CHEMICALS	<del></del>	<del> </del>		<del></del>	
<del>2</del>	INORGANIC CHEMICALS					
AGD	ACIOS		<del>                                     </del>		<del></del>	
BAS	BASES					
MES.	HEAVY METALS		7		· · · · · · · · · · · · · · · · · · ·	<del></del>
HAZARDO	OUS SUBSTANCES (See Asserting SUC	I Proposity and CAS Homeway				
ATEGORY	QZ SUBSTANCE NAME	Q3 CAS MUMBER	04 STORAGE/DISP	OSAL METHOD	05 CONCENTRATION	OS MEASURE CONCENTRATIO
	toluene		DOUM			
	xulane		Drum	· _ · ·		
			·		<u> </u>	
						·
		2		·		
	State of the state of		<u>, , , , , , , , , , , , , , , , , , , </u>	<u></u>	1 1 1	
			·			
				**************************************		<u> </u>
					<u> </u>	
	·			·	· .	<u> </u>
	·					<u> </u>
	<del> </del>				ļ	ļ
					<del>                                     </del>	<u> </u>
					<del> </del>	ļ
<u> J</u>			<u> </u>	•. 	<u></u>	<u> </u>
EEDSTO	CKS See Assert CAS Markets K	J/A		·		
ATEGORY	01 FEEDSTOCK NAME	02 CAS NUMBER	CATEGORY	O1 FEEDST	OCK NAME	CZ CAS NUMBE
FOS :	•		FOS			
FOS			FDS .			
FO3			FOS			
FO3			FOS			· <del></del>
CURCES	OF INFORMATION COMMEN	was, a.g., state tive, surple or ryan, r				
	15 DEC Region 8		• .			

~	
5.37	
V	<i>B</i> <b>L</b>

## POTENTIAL HAZARDOUS WASTE SITE

L	DEN	<b>TIFICATION</b>	
)1	SIATE	OZ SITE NUMBER	•

	INARY ASSESSMENT AZARDOUS CONDITIONS AND INCIDEN	rs NY 8	-28-021
. HAZARDOUS CONDITIONS AND INCIDENTS			
01 NA GROUNDWATER CONTAMINATION 954	02 OF OBSERVED (DATE 4 13 72)	L) POTENTIAL	LI ALLEGED
Landfill unlined. Eviden		surface,	
Groundwater contaminates the Contaminated number of well	1: water overs within 3	mile radio	us af site
01 XB. SURFACE WATER CONTAINATION 03-POPULATION POTENTIALLY AFFECTED	02 OBSERVED (DATE S 12 F2 ) 04 NARRATIVE DESCRIPTION	D POTENTIAL .	
No known uses of surfa		from site	reaches
3 registered wetle			
01 (] C. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	IJ POTENTIAL	CI ALLEGED
	KNOWN		
01 D. FIRE/EXPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE) 04 NAPPATIVE DESCRIPTION	I POTENTIAL	C ALLEGED
- u	ÚW0M¥u		
01 (X.E. DIRECT CONTACT 03 POPULATION POTENTIALLY AFFECTED: 200	02 C OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	POTENTIAL	O ALLEGED
NO HISTORICAL RECO	PA*	STREPO	MPCC -
SSIBLE & NO ACCESS	COUTROL EXISTS.		
01 OF, CONTAMENATION OF SOIL 03 AREA POTENTIALLY AFFECTED:	02 E OBSERVED (DATE: 5/12/82)	☐ POTENTIAL	CI ALLEGED
■ Drums leaking, chem	rical spillage on soil	σρητώσης	•
			•*
MI O I G. ORINKING WATER CONTAMINATION- 03 POPULATION POTENTIALLY AFFECTED:	02 (I OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	POTEMAL	C ALLEGED
<u> </u>	KNOWN	• * .	
<u> </u>			
01 [] H. WORKER EXPOSURE/INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	O POTENTIAL	□ ALLEGED
	THE STATE OF THE S	•	
<u> </u>			
01 D L POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 CI OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	O POTENTIAL	D ALLEGED
	·		
	· ·		

10	<b>LPA</b>

#### POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

L IDENTIFICATION OT STATE OF SITE MANGER

PART 3 - DESCRIP	TION OF HAZARDOUS CONDITIONS AND INCIDEN	יו בייו	3-626-UL
AZARDOUS CONDITIONS AND INCIDENTS	Consume		
I DE L. DAMAGE TO FLORA 4 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:		ALLEGED
DAMAGE TO FL	ORA HAS NOT BEEN	SHECIFIC	CALLY
ATED HOWEVER, T	HE POTENTIAL EXIST HAT WASTE WAS DUMP	BASE	
ROUTIONS TREATERS !	HAT WASTE WAS OWNPI	=D 0010	I TIE
XK DAMAGE TO FAUNA NARRATIVE DESCRIPTION (STRONGS) OF THE PARTY OF THE	02 [] OBSERVED (DATE:)	POTENTIAL	C ALLEGED
	anim anima do A	T EXP	MOTTAL
AY BE AFFECTANE	THAND ANIMAL FPLAN BY PAST DUMPING AD	JACENT	TO WETL
CL L CONTAMINATION OF FOOD CHAIN	02 C OBSERVED (DATE:	<del></del>	C ALLEGED
	122 A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	nknown.	•	
M. UNSTABLE CONTAINMENT OF WASTES	02 C) OBSERVED (DATE:)	POTENTIAL	☐ ALLEGED
POPULATION POTENTIALLY AFFECTED	04 NARRATIVE DESCRIPTION		
RECORDS INC	DICATE NO CONTAIN	MENT H	DASURES
AKEN.			
☐ H. DAMAGETO OFFSITE PROPERTY	02 C OSSERVED (DATE:)	I POTENTIAL	C ALLEGED
NARRATIVE DESCRIPTION	A Start Destruction	, <u>, , , , , , , , , , , , , , , , , , </u>	
	UNKNOWN		
C O. CONTAMINATION OF SEWERS, STORM OR	ANS, WATPS 02 [] OBSERVED (DATE:]	D POTENTIAL	C ALLEGED
	WINKNOWN		·
		<u> </u>	
P. BLEGGE WINDTHOTHER CUMPTERS NARRATIVE DESCRIPTION	C2 TOPSERVED (DATE:)	- POTENTIAL	. ALLEGED
and the second of the second	er er er De state de la seus sont de seus en		
	N/A		
DESCRIPTION OF ANY OTHER KNOWN, POTENT	IAL OR ALLEGED HAZARDS		
7 · ••			
TOTAL POPULATION POTENTIALLY AFFECT	ED:		
COM2113		<del></del>	
•			
•			•
<u> </u>			
SOURCES OF PIFORMATION COMPANY	tion granted that the common or or productions		
NYSDEC Region	8, Census Data . ED YURKSTAS MONROE		
SITE INSPECTION	ED VURKSTAS MONROF	CTV HEA	LTH DEP

EPA FORM 2070-12 (7-61)

	POT	ENTIAL HAZAR	DOUS	WASTE SITE		LIDENTIF		
SITE INSPECTION REPORT					DISIALE	STENUMBER S-O-OZ	1	
PART 1 - SITE LOCATION AND INSPECTION INFORMATION						<u> </u>		
IL SITE NAME AND LOC	ATION	<u> </u>				_		
01 SITE NAME HOPE COMMEN	d description name of said			T, POUTE NO., OR SP		DENTIFIER		
	ad Disposal S	ite_	<u> </u>	polden Ro			_	
os any	01 11			05 ZP COOE	OG COUNTY		07COUNTY CODE	05.
Town of		10 TYPE OF OWNERSH	NY	14624	Monro			<u></u>
43 07 08.0	017 45 45.0	DX A. PRIVATE	C 8. FE	ERAL		D. COUNTY 3. UNKNOW		'AL'
III. INSPECTION INFORM	VIATION 02 SITE STATUS	03 YEARS OF OPERAT	BON					
5,3,83	D. ACTIVE SCINACTIVE	19	SS NNINGYEA	1 1976 A ENDING YEAR		INKNOWN		
04 AGENCY PERFORMING INS								
GAEPA GB.EPAC	CONTRACTOR <u>Recra</u>	restacch	C G OT	inicipal 🔯 0. M Her	UNICIPAL CONTR	ACTOR	(Marrie of Ferry	<del></del>
OS CHIEF INSPECTOR	(No	OG TITLE			(Specify)		08 TELEPHON	E NO
1	P			C., a				
Daniel W.	LOTUMAN	TOTILE	pali	- Deinser	11 ORGANIZAT	OINC	12 TEI EDMONE	
C. Mark	Hanna	Proje	ct	<u>Engineer</u> Engineer	- URS	Co Inc	(716) 883	- ,
							( )	
	· · · · · · · · · · · · · · · · · · ·		•.	•			( )	
							( )	
	•		• ,			•	( )	
13 SITE REPRESENTATIVES IN	ITERMEWED.	14 TITLE	. 1	SACORESS			16 TELEPHONE	ENO
NONE	•	1.					( )	
				· · ·			<b>( )</b> .	
							( )	
			1				( )	
	<u> </u>			,		-	( )	
				<del></del>		_	( )	
	w to			• • •				
17 ACCESS GAINED BY	18 TIME OF INSPECTION	19 WEATHER COND	TIONS.				<u> </u>	
TO PERMISSION WARRANT	8:30 AM	55° F	, 0	iercast.	calm			•
IV. INFORMATION AVAIL	LABLE FROM							
01 CONTACT		OZ OF PARAMENTURA		- 1		1 -	s telephone n 1716) & 38	
Rick Cro				search				-6600
Daniel W.	Rathman	OS AGENCY	1	o Colnc	716-883-	- 1	S DATE	<u> </u>
<u> </u>	1-01		<u> </u>	(110	<u> </u>		J <b>4</b> 00	

		PO1	TENTIAL HAZA	RDOUS WAST	E SITE		LIDENTIFICATION	
<b>FPA</b>	<b>.</b>	SITE INSPECTION REPORT  PART 2 - WASTE INFORMATION  OI STATE OZ SITE NUMBER  NY 8-28-02						
ASTE STATES	, QUANTITIES, AN	D CHARACTER	ISTICS		·			
/SICAL STATES .	Ches at the saon	02 WASTE QUANT		SITE 03 WASTE CHARACTERISTICS (CHOCK at their anoth)  DEA TOXIC				
. T 468	(Secony)	NO. OF DRUMS	300+			C M. NOTA		
ASTE TYPE		<del></del>						
GORY	SUBSTANCE N	AME	01 GROSS AMOUNT	02 UNIT OF MEASUR	E 03 COMMENTS			
	SLUDGE							
(	OILY WASTE			<b>\</b>				
	SOLVENTS		300+	Drums				
	PESTICIDES							
ce (	OTHER ORGANIC CH	HEMICALS						
	NORGANIC CHEMIC	'ALS					·	
- C	ACIO3							
	SASES					·		
	HEAVY METALS							
್ಷ ಸಾಂಚಿತ ಕ	UBSTANCES		e case CAE mumbers					
YNGE	02 SUBSTANCE N		03 CAS NUMBER	04 STORAGE/DE	SPOSAL METHOD	05 CONCENTRATION	CONCENTRATION	
30L -	tolvene		108-8B-3	Drum	· .			
2	xylene		1330-20-7	Dro	· ·			
				·				
		•						
		_ · ·						
	•							
STOCKS	ne Administra for CAS former	- N/A		·	<del>_</del>		<u>:</u>	
YAC	01 FEEDSTOCK		02 CAS NUMBER	CATEGORY	01 FEEDSTO	CK NAME	OZ CAS NUMBER	
FOS				FDS				
e				FDS				
3				FDS				
FÜS				FOS		-		
	EORNATION :							
A STATE OF IN	FORMATION .c.o.	PACIFIC PROMOTERS, 9 Q.,	State from Samon and one. 19					
—	NYSDEC	Panim !	A					
	1173000	Led lois						
2070-13(7-41			<u>.</u>					

# SFPA

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L IDENTIFICATION OI STATE OZ SITE NUMBER

PART 3-DESCRIPTION OF	AZARDOUS CONDITIONS AND INCIDENTS	S LIGATE	5-20-021
IL HAZARDOUS CONDITIONS AND INCIDENTS			
01 X A. GROUNDWATER CONTABINATION 954	02 % COSENVED (DATE: 4/13/52)	☐ POTENTIAL	☐ ALLEGED
Landfill unlined. Eviden	ce of chemicals on soi	Isorface.	
Groundwater contamination	m detected,		<b>6</b> /
Estimated number of w	ell mater osers inthin 3 1		z of cite
	075 OBSERVED (DATE: 5/12/52) 04 NAHHALIVE DESCRIPTION	POTENTIAL	[] ALLEGED
No known use of surfac	e water. Drainage f	rom site	enters
3 registered we-	flonds		· ·
01 C. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED:	02 (7 OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	S POTENTIAL	I ALLEGED
11014	NOWN		
UISE	300,40.0		-
	·	·	
01 [] D. FRE/EXPLOSIVE CONDITIONS -03 POPULATION POTENTIALLY AFFECTED:	02 (1 OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	POTENTIAL	II WITESED
	(4-4) (10-4) (10-4)		
	M.		
e e e e e e e e e e e e e e e e e e e		•	• . • •
01 IX.E. DIRECT CONTACT 03 POPULATION POTENTIALLY AFFECTED: 7 / 070	02 C OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	POTENTIAL	G ALLEGED
STORES, STORES	CLESSIBLE. NO AC	CESS	
		_	
CONTROL MEASURES:			
01 X.F. CONTAMINATION OF SOIL	02 (1) OBSERVED (DATE:	POTENTIAL	G ALLEGED
Drums leaking, then	nical spillage on soil	σουιως	•
3, 3	,		
01 G. DRINKING WATER CONTAMINATION	02 CL OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	□ POTENTIAL	C ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	O- INVANTAS DESCRIPTION	•	
unk	NOWN		
01 C H. WORKER EXPOSURE/INJURY	02 [] OBSERVED (DATE:)	I POTENTIAL	☐ ALLEGED
Q3 WORKERS POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		• •
	1c		•
01 C L POPULATION EXPOSURE/INJURY	02 C OBSERVED (DATE:)	G POTENTIAL	C ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION	- restaure	a medel
•	· 11		•
	,		

	 ٦٨.
10	冯

L IDENTIFICATION

PAR PAR	SITE INSPECTION T 3 - DESCRIPTION OF HAZARDOUS	INVI R	NY 8-28-021	
HAZARDOUS CONDITIONS	NO INCIDENTS (Company)			
YEU DAMAGE TO FLORA		ERVED (DATE:)	SEPOTENTIAL	C ALLEGED
94 MARRATIVE DESCRIPTION	WETLANDS- M	AV BE AFFEC	TED AS	. ^
ESULT OF PA	ST DUMPING A	CTIVITIES	•	·
OT OK DAMAGE TO FAUNA	02. [] C8SI	ERVED (DATE:)	SCHOTENTIAL	□ ALLEGED
<b>■</b>		· · · · · · · · · · · · · · · · · · ·		
1 (T) L. CONTAMINATION OF FOO 04 NARRATIVE DESCRIPTION	CICHAIN 02 (2 095)	ERVED (DATE:)	☐ POTENTIAL	C ALEGED
	UNKNOW			
01 M. UNSTABLE CONTAINMEN 33 POPULATION POTENTIALLY AF	FECTED: 20 04 NARRAT	ERVED (DATE: 5-3-63)  TIVE DESCRIPTION	SKPOTENTIAL .	CI ALLEGED
NO CONTA DRUMS LI	INMENT OF WAS	SPILLAGE OF	N SOIL	
D1 C N. DAMAGE TO OFFSITE PR D4 NARRATIVE DESCRIPTION	OPERTY 02 C OBSE	FRVED (DATE:)	C POTENTIAL	C ALLEGED
	UNKNOV	- · · · · · · · · · · · · · · · · · · ·		
01 C O. CONTAMINATION OF SEV 04 NARRATIVE DESCRIPTION	VERS. STORM DRAINS, WWTPs 02 - OBSE	RVED (DATE:)	I POTENTIAL	C ALLEGED
•			to the second	•••
01   P. ILLEGAL/UNAUTHORIZED 04 NARRATIVE DESCRIPTION	DUMPING 02 (1) OBSE	ERVED (DATE:)	C POTENTIAL	C) ALLEGED
in the second se				
OS DESCRIPTION OF ANY OTHER	ONOWN, POTENTIAL, OR ALLEGED HAZARD	s	<del></del>	<del></del>
	NONE	KNOWN		
			<del></del>	·
IL TOTAL POPULATION POTENTY. COMMENTS	HALLT APPELIEUT			
V. SOURCES OF INFORMATION	(Che apoche references, a. g., state Hea, service analysis, re-	porti,		
NYSDEC	Region 8, Census O	ata		

A PDA	POTENTIA	AL HAZAF	RDOUS WAST	ESITE	L IDENTIFICATION	
SEPA		SITE INSPECTION OT STATE OZ SITE NUMBER				
	PART4-PERMI	IT AND DE	SCRIPTIVE INF	FORMATION	N) 0-28-021	
IL PERMIT INFORMATION			,			
01 TYPE OF PERMIT ISSUED	02 PERMIT NUMBER	OZ DATE	SUED - 04 EXPIRA	TION BATE 05 COMM	ENTS	
				Ì		
TIA NPOES		<del></del> -	<del></del>			
CB. UIC		<del></del>	<del></del>			
G.C. AIR					- <del></del>	
C D. RCRA	<del>-  </del>					
E. RCRA INTERIM STATUS						
ITF. SPCC PLAN		<del></del>	<del>-</del> ·			
G. STATE STREET						
EH: LOCAL ISSUERY						
OIL OTHER (Speedy)						
XT NONE						
M. SITE DESCRIPTION						
01 STORAGE/DISPOSAL (Chief of their story)	TINU EQ TINUOMA SO	OF MEASURE	04 TREATMENT/C	heat of the spirit	06 OTHER	
A SURFACE IMPOUNDMENT	<del></del>	<del></del>	A INCENERA	TION	☐ A. BUILDINGS ON SITE	
DIS DRUMS, ABOVE GROUND	-300	UMS .		DUND INJECTION	a reporting of all	
CI B. TANIC ABOVE GROUND		<u> </u>	C C. CHEMICAL  D. BIOLOGICA	· · · · · · · · · · · · · · · · · · ·	·	
☐ E. TANK, BELOW GROUND			☐ E. WASTE OIL	-	OS AREA OF SITE	
JXF. LANDFILL	≈ 15 TO	<u>vs</u>	O F. SOLVENTA			
[] G. LANDFARM	<del></del>	<b></b>	CI GLOTHER RE	CYCLING/RECOVER	Y 8 1000	
II H. OPEN DUMP		<del></del> -	CI H. OTHER	(Scoce)	<u> </u>	
() I OTHER			<del></del> ·	(40-11		
07 COMMENTS						
	•					
					The second secon	
<u> </u>						
	•					
	· · · · · · · · · · · · · · · · · · ·					
IV. CONTAINMENT	-	_				
01 CONTAINMENT OF WASTES/Creat ever			<del></del>			
A ADEQUATE SECURE	LI B. MODERATE	C.N	NOEQUATE, POOP	D. INS	SECURE, UNSOUND, DANGEROUS	
22 DESCRIPTION OF ORUMS, DIKING, LINEAS	BARNERS FTC		<del>-</del>		<del></del> _	
N= 1.000	4 5000 500	h.1 a.	اموا ل	cina . la	ndfilled into wetland	
No liners,	CLOWS 108	יט פא	w read	21.73	natives in is wellar	
	entre de la companya		. <b>.</b>			
			—		·	
V. ACCESSIBILITY		<del></del>				
01 WASTE EASKY ACCESSIBLE: XYE	ES [] NO					
VL SOURCES OF INFORMATION ICA	LANCON CONTRACTOR O & MAND MAN. LANCO					
- NUChen Ro	C100 A					
- NYSDEC Re	4-1.0	···-	•	•	1	

		<del></del>			
	POT	ential Hazai	1. IDENTIFICATION		
SEPA		OF STATE CLE STE NUMBER			
	nmental data	NY 18-28-02			
<u> </u>		4 2 CH C G I IAF I I	IS AND ENTINU	MENIALUAIA	
IL DRINKING WATER SUPPLY	•				•
OF TYPE OF COMMUNICATION					
(Check on analyses)		- CE STATUS	•		03 DISTANCE TO SITE
SURFACE	WELL	ENDANGER	ED AFFECTED	. MONITORED	
-COMMUNETY AXX	. B.C	AG	B. J	C. L.	
NON-COMMUNITY C. []	0,52	0.0	· E.G	#. C	
				F. G.	B(mi)
III. CROUNDWATER					<u> </u>
01 GROUNOWATER USE IN VICINITY (Cheef	enal			<del></del>	
☐ A ONLY SOURCE FOR DRINKING	A B. DANKING	•	C) C. COMMERC	ZAL MOLISTRIAL SPRICA	non " o notused, unuseable
	/ \ 10ster services arter	-	سامه محمدار		o do deep outserses
	COMMERCIAL, IN	ADUSTRIAL, IRRIGATIO	N		
<del>-</del>	0011				
02 POPULATION SERVED BY GROUND WAT	ren <u>954</u>	· 	03 DISTANCE TO NE	AREST DRINKING WATER	MELL (C) (mil)
	T				
C4 CEPTH TO GROUNGWATER	OS DIRECTION OF GRO	WOJA RJIAWOWA	06 DEPTH TO AQUIFE OF CONCERN	OF ADJACES	D 08 SOLE SOURCE AQUIFER
<u>&lt;10 m</u>	Nor	-th	410	,,,,	TYES X NO
				. —	(gpd)
00 DESCRIPTION OF WELLS (texture) arrays.	, depth, and income relation to	فيوطونها لده موسعتهم	_		
Both dug a	- 4 - 4 - 11.	عااص د لم	used f	or roadou	tal purposes
both ang a	ana ariin	eo wers	1.0000 1		i = c Porpor
	•				
		•			
10 RECHARGE AREA			11 DISCHARGE AREA		
LI YES COMMENTS	•	• •	XYES COMM		<i>-</i> ••
				Ç113	•
75(m)			J	•	•
IV. SURFACE WATER		•			
OT SLITFACE WATER USE (Count and	<del></del>				
		• •			
() A PESETVOIR, RECREATION		N. ECONOMICALLY	C C. COLIME	rcial neustrial	X D. NOT CUFFENTLY USED
DRINKING WATER SOURCE	IMPORTAN	IT RESOURCES		•	, ,
02 APPECTED/POTENTIALLY AFFECTED 80	IDIES OF WATER				
NAME:				AFFECTED	DISTANCE TO SITE
,					
Un-named bo	and and	Mermitt	ent strec	<u> </u>	
		·	·	<b>=</b> `	(mi)
	·		•		(mi)
14 000000000000000000000000000000000000					
V. DEMOGRAPHIC AND PROPERTY	INPURMATION	<u> </u>			<u> </u>
01 TOTAL POPULATION WITHIN		•		02 DISTANCE.TO NEARE	ST POPULATION
ONE(1) MILEOF SITE TW	O (2) MILES OF SITE	. THREE (3	MILES OF SITE	_	i
A 500 B	7,500		0.000	·	0.01 <u>mu</u>
NO. CF FERSONS	NO. OF PERSONS	Nei	of PERSONS,	••	
GI NUMBER OF BUILDINGS WITHIN TWO (2)	MLES OF SITE		04 DISTANCE TO NEA	REST OFF-SITE BUILDING	
750	<u> </u>		•	0.01	
	<u> </u>	<u>.</u>			(mi)
06 POPULATION WITHIN VICINITY OF SITE (P	round managing do paragage of r		-	he terrest between note an	
_				•	
Rapidly dev	eloping a	rea			
Lithra 12 2100	7.7		and the second second second	. <b></b>	
***					
			•		
	•				
			·		
			•		·

EPA FORM 2070-13 (7-A1)

9	EPΛ

	TEICATION
OI STATE	02 SITE NUMBER - 021
<b>  V</b>	8-28-021

<b>≎</b> EPA	SITE INSPEC PART 5 - WATER, DEMOGRAPH	NY 8-28-02	
VL ENVIRONMENTAL INFORM	MATION		
01 PERMEABILITY OF UNSATURATED	20NE (Cress cos) 0-4 cm/sec   Cl 8, 10-4 - 10-4 cm/sec   )	(C. 10 <sup>-4</sup> 10 <sup>-3</sup> cm/sec □ 0. GREATE	ER THAN 10 <sup>-3</sup> cm/eec
02 PERMEABILITY OF BEDROCK C	. /		
C A MPG	# 10 <sup>-6</sup> exress( / * (10 <sup>-6</sup> - 10 <sup>-6</sup> carses)	ILE [] C. RELATIVELY PERMEABLE []	D. VERY PERMEABLE (Greater than 10 <sup>-2</sup> cm sec)
03 DEATH TO BESTROCK	GA CEPTH OF CONTAMNATED SOIL ZONE	06 SCILDH	
04 NET PRECIPITATION	- OF ONE YEAR 24 HOUR RAINFALL	04 SLOPE	
	Z.O (in)	SITE SLOPE OF SITE	E SLOPE TERRAIN AVERAGE SLOPE O-3 %
SITE IS IN YEAR FL	CODPLAIN C SITE IS ON BARR	IER ISLANO, COASTAL HIGH HAZARO ARE	A, RIVERINE FLOODWAY
11 DISTANCE TO WETLANDS IS ASSOCIA		12 DISTANCE TO CRITICAL MARITAT (of entiring	
ESTUARINE	OTHER	_NG	ONE (m)
A(ms)	8(mt)	ENDANGERED SPECIES:	•
13 LANGUES NOTICE -		•	•
DISTANCE TO:	RESIDENTIAL AREAS, NATIO	NAL STATE DADVS AC	RICULTURAL LANDS
COMMERCIALINDUST		E RESERVES PRIME AGU	
	<u>. 0.01</u>		
^W	·		
Filled at	rea approximately	10 feet higher	than wetland
THE RELIEF	FOR THE SITE IS	S QUITE FLA	T, SWITH
MAJOR TOPE	OSRAPHICAL VAR	ZIATIONS "RESI	ULTING .
	NO OF AREA	•	
- LOFT TIECT	134 C. MREA	<b>9.</b>	
	•	•••	
		•	
		•	
			er.
YN SOURCES OF INFORMATIO	IN dies accord entreuens, e.g. anno tina, samete mannes.	Accounts	
VN. SOURCES OF BIFORMATIC	IN Consessor returning a.g., once the second records.	Account .	
VN. SOURCES OF IMPORMATION	Region 8, U.S. Wear	ther Service	

SEPA		OTENTIAL MAZANDOUS WASTESHE	STATE 02 SITE NUMBER UV 8-28-024
IL SAMPLES TAKEN			
SAMPLE TYPE	OI NUMBER OF SAMPLES TAKEN	CO SAMPLES SENT TO	OJ ESTIMATED DATE
GROUNOWATER	2	Monroe County Dept. of Health	Now
SURFACE WATER	3	NYSDEC	Now
WASTE	13 .	· Monroe County Dept, of Health	Now
AIR			
RUNOFF			·
SPILL .			
SOIL	2	NYSOEC	Now_
VEGETATION			
other Sediments	2	MYSDEC	NOW
IL FIELD MEASUREMENTS TA			
OI TYPE	OS COMMENTS	·	
		NONE TAKEN AT SITE	
	INS	SPECTION	·
·			· .
IV. PHOTOGRAPHS AND MAPS			
01 TYPE : GROUND X AERIAL		OR MOUSTON OF MONROE COUNTY ENVIRON M	ANAGEMENT CONCIL
03 MAPS 04 LOCATION [] YES /BFNO	OF MAPS		
V. OTHER FIELD DATA COLLEC	CTED (Pro-in security of the	reprove	
	•		
	: '		
 	•		
· 			<del>-</del>
attage of the state of the stat			
VL SOURCES OF INFORMATIO	M		<u> </u>
		Monroe County Environmental Micha	gement Council,

EPAFORM 2070-13-(7-81)

	-	POTENTIAL HAZA	HAZARDOUS WASTE SITE LIDENTIFICATION  ON STATE OF STATE O			
SEPA						
# CLIRRENT OWNER(S)		774(1)	PARENT COMPANY of contracts		•	
• •		02 D+E MUMBER	GE NAME	<del></del>	REDMUM B+0 0	
	A COLO IN					
Howard Fitzsii	10107 J	104 SIC CODE	10 STREET ADDRESS (P.O. Ave. NO A		11 SIC COOE	
227 Golden Room				•		
+ City		07 ZP COGE	12014	13 STATE	14 ZP CODE	
Chili	MA	14624	<u></u>			
N. 4400		02 D+6 NUMBER	OB- NAME		P38MUM 8+0 60	
I STHLET ACCRESSING das, MO. , onli		SA SIC CODE	10 STREET ACCRESSIA G. Bas, MCC. and		11 SIC CODE	
					1	
. + caty	06 STATE	07 ZP CCOE	12 (317)	13 STATE	14 219 CODE	
		1		1	•	
P • • • • • • • • • • • • • • • • • • •		G2D-ENLAGER	C3 KAME	<del></del>	2 C+8 (C.248ER	
				- <del></del>		
THEET ADDRESS, P.O. See APRIL 1981		04 SIC CODE	10 STREET ADDRESS (P.O. Am. APD C. am.)		11.000000	
			TO STREET ALCHESSIFIC BL. MOV. BL.	•	11SIC COOE	
	- OS STATE	07 ZP COOE	IZCITY	13 STATE(1	4 ZIP-COOE	
	-					
A MANUEL		GE GOOD MAER	ùà nome		ADVENIUSER	
and the second second second		<b>.</b> .				
CISIPERI AULTESSIA D. Sec. Wold, and		04 SIC CODE	10 STREET AOORESS (F.O. Ann. AFG.)		I 1 SIC COOE	
		_				
Ran	142 241					
	- I-	07 ZP COOE	12017	- ISSTATE	4 ZP CODE	
			<u> </u>	ii		
RI PREYIOUS OWNERS	<del> </del>	<u> </u>	IV. REALTY OWNER(S) # moreon; he	ment record first		
1 NAME		C2 D+6 NUMBER	OI NAME		2 D+8 NUMBER	
- STREET ADDRESS:PO Bas MOD and 1		04 SIC COO€	03 STREET ADDRESS (P.O. Box, APD a, ore.)		IO4 SIC CODE	
aciv	OGSTATE	07 ZP COOE	los ary	OG STATE O	7 7/8 COOK	
and the second control of the second control		······································	The second secon			
4		02 D+8 MANGER	SI NAME		S D + S WINDER	
- 1-1-10 to 00/22 70 Att 00/ mal	•	94 SIG CODE	03 STREET ADDRESS (P.O. Box, MFO F. erc.)		04 SIC CODE.	
	OG STATE	07 ZP COOE	05 017	OS STATE O	7 20P CODE	
	- [ [	<u> </u>		-		
·		02 D+8 NUMBER	O1 NAME		7 D-A WINNER	
			1	l	:	
STREET ACONESSIPO BOL MOR. OR.)		04 SIG CODE _	O3 STREET ADDRESS (P G. See, AFO F. ME.)		04 SIC CODE	
₩.	OSTATE	of ZIP CODE	05 GTY	OS STATE O	1.79.CO05	
and the same of th				المعتدان		
				<u></u>		
SOUNCES OF INFORMATION COM	-	. g., actio fine, sample analysis, re				
		1 m = 0			•	
				•	·	
NUCTO D.	C (	<b>)</b> .			• •	
NYSDEC Re	Gion C	)·	•			
•	J ,	- '	•	*		

·							
0. F-7-3	•	PC		RDOUS WASTE SITE	I. IDENTIF	ICATION Z SILE NUMBER	
SEPA				CTION REPORT TOR REFORMATION	UY 8-28-021		
IL CURRENT OPERAT	OR investorances			OPERATOR'S PARENT COMPA	ANY is appreciately		
01 NAME			02 D+8 NUMBER	10 NAME		11 0+6 NUMBER	
NONE WHITELLAUMESS IF Q I							
US SINEEL AUGNESS (P.O. II	12, 100 0, oil 1		04 300 COME	12 STREET ACCRESS IN U. See, AFG P. ON	<u>-</u>	13 500 0000	
05 CITY		OG STATE	07 ZIP COOE	14 017	IS STATE	16 ZIP COOE	
DE YEARS OF CRUTATION	OS NAME OF CHARES				<del></del>		
III. PREVIOUS OPERAT	OR(S)	Trest provide an	y d affected from control	PREVIOUS OPERATORS' PARE	ENT COMPANIES #		
HOWARD FIT	12SIMHON	5	02 D+8 MJMBER	10 NAME		11 0+8 NUMBER	
03 STREET ADDRESS (P.O &	EN RD		04 SIG CODE	12 STREET ADDRESS (P. O. Box. AFO F. on	r.i	13 SIC CODE	
06 CITY	2.0	OS STATE	97 2P CODE	14 CTY	15 STATE	16 23P CODE	
CHILI	٠.	NY	14624		l l		
08 YEARS OF OPERATION	NAME OF OWNER	DURING THE	S PERIOD				
OI MAME			02 D+6 MUMRER	10 NAME		110+8 NUMBER	
03 STREET ADORESS (F.O. An	e, NOA, esc.)		04 8K2 COUN	12 STREET ACCRESS (P.O. Box, APO 4, etc.	ı	13 50 0004	
06 CITY		06 STATE	07 23P CODE	14 CIY	15 STATE	16 ZP CODE	
DE YEARS OF OPERATION	09 NAME OF OWNER	DUPING THE	I PENICO				
O1 NAME			02 D+8 NUMBER	10 NAME	·	11 D+8 NURABER	
03 STREET ADDRESS (P.O. Au	L MOA del	<del></del>	04 SIC COOE	12 STREET ADDRESS (P.O. Box. 1/70 F. oct.	<u> </u>	13 SIC CODE	
OS CITY		00 STATE	07 2P CO06	14 017	1557476	16 ZIP CODE	
OS YEARS OF OPERATION	OR NAME OF OWNER	OLIRING THE	PENCO				
IV. SOURCES OF INFO	RMATION (Cto manufil		G., Mayo Gris, semple empless	L reports			
HYSDEC	Region	8	•				
* * * *		· . · · ·		<del></del>		•	
			÷	ما ما دار المدادة دو			

EPA FORM-2070-13 (7-41)

	POTENTIAL HAZARDOUS WASTE SITE			RDOUS WASTE SITE	LIDENTIFICATION		
SEPA			SITE INSPE	OI STATE OF	8-28-02		
			ENERATORITE	ANSPORTER INFORMATION	104	0-20-04	
IL ON-SITE GENERATOR		-					
OI NAME		02.0	+ & NUMBER	T			
None		<b>-</b>				.,	
03 STREET ADDRESS (P.O. Bal, MOP. onl)			04 SIC CODE	7		•	
	<u> </u>			<u>.</u>		•	
06 CITY	OO STATE	07 Z	P C006	<u>_</u>			
·		_		<u> </u>			
III. OFF-SITE GENERATOR(S)		loa o	+ E NUMBER	OI NAME		02 0+8 NUMBER	
				01.0			
See below		Ц,	04 SIC CODE	03 STREET ADDRESS (P.O. Box, AFD P. com)		04 SIC CODE	
						~-	
05 CITY	00 STATE	07 Z	P C006	05 CITY	OS STATE	07 ZIP COOE	
•	<u></u>	1	_ •	ŀ	ł l		
O1 NAME	•	020	+6 NUMBER	01 NAME		02 0+8 NUMBER	
<u>_</u>						·	
03 STREET ADDRESS (P.O. Box. APD A. col.)			04 SIC CODE	03 STREET ADDRESS (P.Q. des. NFG F, sec.)		04 SIC CODE	
		<u> </u>					
os aty	04 STATE	107 Z	P 0004	(SC)	ICO STATE	07 ZP CODE	
		<u> </u>	<u> </u>				
IV. TRANSPORTERIS;		Lanen av		1		200101111111111111111111111111111111111	
OT NAME		1020	tunimier .	O1 NAME		02 0+6 NUMBER	
See be ou		Ц,	04 SIC CODE	OS STREET ADDRESS (A.O. BOLL MOD.), MAL		04.8IC.CO0E	
os sinegi neurassir.o. sa., mon aus	• •						
06 CTTY	OS STATE	107 Z	P COOE	OS CITY	OS STATE	07 ZIP CODE	
OI NAME		02 0	+SNUMBER	OI NAME		02 D+8 NUMBER	
		ŀ	•		ŀ	,	
DS STREET ACCRESS (P. O. See, APD 4, see.)		· ]	04 SIC CODE	03 STREET ADDRESS (P.Q. Sec., MO P. col.)	<del></del>	04 SIC CODE	
	· · ·			<u> </u>			
05 City	OG STATE	07 Z	P COOE	05 CITY	06 STATE	07 ZIP CODE	
·		<u> </u>	•				
V. SOURCES OF INFORMATION 1020 4000	-	-	Marie Santalia arrayana, r			<del></del>	
Note: This site	was i	۱۶۰	ed by a	i variety of haul	ers ar	rd "	
مماء ممامد	E	۱،۱ <u>۱</u>	dru Son	d originated from	Also x 1	Corporation	
general and s	., ., .	,		or Great and Cross	,,,,,,	, , , , , , , , , , , , , , , , , , ,	
in Rochest	er an	d	tiy ash	from Univ. of Rocke	ister.		
			•				
•	•						
•	•-		•	· • •		-	
NYSDEC Region	. 8						
,	. •		•				

EPA FORM 2070-13 (7-81)

S	EF	A
---	----	---

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10-PAST RESPONSE ACTIVITIES

	<u>PERCATION</u>
OI STATE	02 SITE NUMBER 8-28-021

PARI IU-PA	31 AESPONSE ACTIVITIES	
IL PAST RESPONSE ACTIVITIES		
01 M.A. WATER SUPPLY CLOSED 04 DESCRIPTION	02 DATE	03 AGENCY
NO ACTION O	F THIS NATURE	
01 C 8. TEMPORARY WATER SUPPLY PROVIDED 04 DESCRIPTION	02 DATE	03 AGENCY
UN DESCRIPTION	. <u></u>	•
01 C. PERMANENT WATER SUPPLY PROVIDED  1 04 DESCRIPTION	02 DATE	03 AGENCY
	. !! - <del>-</del>	
01 C D. SPILLED MATERIAL REMOVED 04 DESCRIPTION	02 DATE	03 AGENCY
		•
01 CI E. CONTAMINATED SOIL REMOVED - 04 DESCRIPTION	02 DATE	03 AGENCY
- 04 DESCRIPTION	11.	
01 G F. WASTE REPACKAGED	02 DATE	03 AGENCY
04 DESCRIPTION		
01 [] G. WASTE DISPOSED ELSEWHERE	02 DATE	03 AGENCY
04 DESCRIPTION	- 11	· · ·
01 H. ON SITE BURIAL	02 DATE	03 AGENCY
04 DESCRIPTION		•
01 I L IN SITU CHEMICAL TREATMENT	02 OATE	03 AGENCY
04 DESCRIPTION	u .	•
01 🖸 J. IN SITU BIOLOGICAL TREATMENT	OZ DATE	03 AGENCY
04 DESCRIPTION	F .	
01 C K. IN SITU PHYSICAL TREATMENT	02 DATE	03 AGENCY
04 DESCRIPTION	t <sub>1</sub>	
01 CL ENCAPSULATION 04 DESCRIPTION	02 DATE	03 AGENCY
• 04 DESCRIPTION	lţ	·
01 CLM. EMERGENCY WASTE TREATMENT 04 DESCRIPTION	02 DATE	03 AGENCY
ON DESCRIPTION		
01 D N. CUTOFF WALLS	02 DATE	03 AGENCY
04 DESCRIPTION	lt	
01 0. EMERGENCY DIKING/SURFACE WATER DIVERSION	02 DATE	03 AGENCY
04 DESCRIPTION	lı .	
01 CJ P. CUTOFF TRENCHES/SUMP	02 DATE	03 AGENCY
04 DESCRIPTION	N	
01 [] Q. SUBSURFACE CUTOFF WALL	02 DATE	03 AGENCY
04 DESCRIPTION	n	· · · · · · · · · · · · · · · · · · ·
EPA FORM 2070-13 (7-81)		<del>-</del>

	<u> </u>	7
100		4

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10-PAST RESPONSE ACTIVITIES

I. IDEN	TIFICATION
OI STATE	8-20-02

	PART 10-PAST RESPONSE ACTIVITIES	101020-021
N PAST RESPONSE ACTIVITIES (Comment)		
01 DR. BARRIER WALLS CONSTRUCTED	02 DATE	03 AGENCY
04 DESCRIPTION	ACTION OF THIS NAT	URE TAKEN.
01 S. CAPPING/COVERING	02 DATE	03 AGENCY
04 DESCRIPTION	. 11	
01 () T. BULK TANKAGE REPAIRED	02 DATE	03 AGENCY
04 DESCRIPTION	N/A "	
01 U. GROUT CURTAIN CONSTRUCTED	• 02 DATE	03 AGENCY
04 DESCRIPTION	10	
01 C V. BOTTOM SEALED	02 DATE	03 AGENCY
04 DESCRIPTION	<u>'</u>	
01 U. GAS CONTROL	02 DATE	03 AGENCY
04 DESCRIPTION	<b>'</b>	
01 🗆 X. FIRE CONTROL	O2 DATE	03 AGENCY
04 DESCRIPTION	1	
01 TY. LEACHATE TREATMENT	02 DATE	03 AGENCY
04 DESCRIPTION	<b>11</b>	
01 [] Z. AREA EVACUATED	02 DATE	03 AGENCY
04 DESCRIPTION	•	• •
01 1. ACCESS TO SITE RESTRICTED	02 DATE	03 AGENCY
04 DESCRIPTION	· ·	<u>.                                    </u>
01 2. POPULATION RELOCATED	02 DATE	03 AGENCY
04 DESCRIPTION	•	
'01 ( 3. OTHER REMEDIAL ACTIVITIES	OZ DATE	03 AGENCY
04 DESCRIPTION	Ji	•
•	•	
	•	
		•
	•	
·		
	•	
IIL SOURCES OF INFORMATION (Chr accepte red	protect, e.g., state flog, comple analysis, reports)	·



#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

L IDENTIFICATION

OI STATE OR SITE MININGER

LIY B-29-021

r enforcement information

OI PAST REGULATORY/ENFORCEMENT ACTION XYES. SI NO

02 DESCRIPTION OF FEDERAL STATE: LOCAL REGULATURY-ENFORCEMENT ACTION

MYSDEC Region 8 directed owner to stop dumping into wetland area

NYSDEC REGION 8 INFORMED OWNER OF VIOLATIONS OF 6 NYCRR PT 360 JURING 1981

HAULER OF FLYASH & FOUNDRY SANDCITED BY
NYSDEC FOR LACK OF PART 364 DEPTH

III. SOURCES OF INFORMATION (Car assess references, e.g., state time, service reference, recommended, e.g.,

NYSDEC Region 8.

#### 4.0 SITE HISTORY

According to Mr. Howard J. Fitzsimons, Jr., owner of the Golden Road disposal site, the approval to begin dumping wastes at this site was obtained in 1955 from former Chili Town Supervisor George Lusk (Ref. 16). Aerial photos taken during 1951 support his contention, since no dumping or filling activities were evident before that time (Ref. 17).

During the years 1958 through 1961, the construction of Route 490 was underway adjacent to the disposal site. Turner Construction Company, which worked on this highway for the New York State Department of Transportation, placed many barrels on this site which were subsequently used by the owner to store tar removed from large fuel tanks also located on the site (Ref. 16). During this early period of activity, Captain Ronald Yox of the United States Army Reserve in Rochester also delivered refuse to the site. Included in these loads were barrels of dried paints, artillery shells and scrap metal (Ref. 16). It is assumed that the materials listed above were disposed of in the northern area of the site, since aerial photos taken during May of 1961 show no activity occurring south of the Conrail tracks (formerly the Penn Central Rail-road), while dumping was obvious to the north.

By 1970, aerial photos provided evidence of surface disturbance in the north area, but no actual dumping or filling activities. Various junked vehicles were located about the area. To the south of the railroad tracks, active dumping had begun. This area was inspected by Mr. Ed Yurkstas of the Monroe County Health Department. He reported observing the open dumping of household refuse, metal slag, flyash and barrels. The site owner has denied any responsibility for these barrels, some of which reportedly appeared from an unknown origin in 1974.

During 1974, Mr. Fitzsimons obtained a contract from the Abex Corporation, a local casting facility, to allow the dumping of foundry sand containing metal slag (Ref. 16). This contract was sold to Mr. William Statt, the owner of a construction company, who began to transport the foundry sand. Mr. Statt also transported flyash from the University of Rochester for disposal at the Golden Road site (Ref. 18).

According to Mr. Fitzsimons, 1974 was the last year that refuse wastes were dumped at the site; however, the aerial photos taken during 1975 indicate that dumping may have been occurring in both the north and south areas at that time. In fact, in the south area materials were being dumped directly into ponded water. Mr. Fitzsimons was directed by the NYSDEC to stop dumping into the wetlands adjacent to the site (Ref 19). As a result, he filed a lawsuit against the state in an attempt obtain permission to continue the wetland dumping; however, by 1976 the filling practices in this area were stopped (Ref. 16).

This site was brought to the attention of the Monroe County Landfill Review Committee by Lt. Burton Verhay of the Monroe County Sheriff's Department. Lt. Verhay had found the site during an investigation in the area (Ref. 18). On May 21, 1981 Frank Shattuck, the NYSDEC

Regional Solid Waste Engineer, sent Mr. Fitzsimons a letter informing him of several violations of the 6NYCRR Part 360 regulations at this site, including operating the site without a permit. He was ordered to cease landfilling operations (Ref. 20). Subsequently, Mr. Statt was cited for hauling the flyash and foundry sand without a Part 364 permit, and was advised to stop the dumping (Ref. 18). Finally, the Monroe County Health Department and the NYSDEC began taking samples of the surface waters, waterway sediments, contents of barrels and close-proximity well water early in 1982 (Ref. 6, 11).

#### 5.0 SITE DATA

#### 5.1 Site Area Surface Features

5.1.1 Topography and Drainage - As previously mentioned, this disposal site is comprised of two areas separated from each other by Conrail railroad tracks which run in an east-west direction. Both of these disposal areas lie directly adjacent to large wetlands areas. The relief of the site is quite flat (natural slopes are near 0%), with the major topographical variations resulting from the filling of the areas.

During wet seasons, the south disposal area is bordered to the south and west by ponded water, while the north area also has ponded water to the west. Surface drainage from the north area appears to be into the wetland to the west. An intermittent stream flows from the pond adjacent to the south area eastward along Route 490 for a short distance, eventually reaching a pair of ponds along the railroad tracks (Figure 1). The on-site pond also drains to this stream. The ponds along the tracks, which were former borrow pits used during the

construction of the highway, are part of another wetlands area.

It should be noted that the levels of several metals, including cadmium and lead, are significantly higher than the National Drinking Water Standards. Although the surface waters draining from the site are not known to be used for drinking water purposes, they do flow into the protected wetlands, and may be capable of affecting the natural environment there.

Site is located directly adjacent to designated Class II wetland areas (CI-2-II and CI-3-II). In addition, the water which drains from the site eventually reaches the registered wetland CI-27-II adjacent to the railroad tracks. There are no critical habitats of endangered species located in the vicinity of the disposal area (Ref. 21), nor does the site lie within any 100-year flood boundaries, as designated by the Federal Emergency Management Agency (Ref. 22).

#### 5.2 Site Hydrogeology

- 5.2.1 Geology - Bedrock underlying the Golden Road Site is the Camillus Shale of the Salina Group and is Silurian in age. This unit consists mainly of gray shale: however, considerable amounts arav limestone and dolostone are found interbedded in the Gypsum and anhydrite are present within the unit. shale beds and many occurrences are found to be up to five (5) feet thick. Overall thickness of the Camillus Shale formation is approximately 400 feet. Regional dip of the bedrock is to the south at approximately 0.5°. The site is unconformably overlain by unconsolidated Pleistocene deposits.
- 5.2.2 Soils - The primary surficial soil found within the boundaries of the disposal site is shallow muck. Muck soils are characteristically very poorly drained. organic soils which developed in depressions. These soils are generally level, have a high seasonal water table and are often ponded for long periods of time. Permeability can be quite rapid in well-decomposed muck. No soil borings have been performed on-site, so a representative soil profile cannot be presented.

5.2.3 <u>Groundwater</u> - The general flow of groundwater in Monroe County is thought to be in a northward direction towards Lake Ontario. However, groundwater flow direction may vary depending on site geologic and hydrogeologic conditions.

Groundwater in the site vicinity may be transmitted through the unconsolidated overburden material and bedrock. As mentioned earlier, the bedrock underlying the site is the Camillus Shale. This formation is a water bearing unit with large reservoirs resulting from the dissolution of gypsum. However, water obtained from this formation is reported to have naturally occurring hydrogen sulfide.

Most of the productive wells in the county draw from the weathered zone which occurs at the interface of bedrock and the overlying glacial deposits.

#### 5.3 Previous Sampling and Analyses

- 5.3.1 Groundwater Quality Data A preliminary sampling and analysis program for the site was conducted during 1982 by the Monroe County Health Department and the NYSDEC. Samples were taken from barrels, soil, surface waters and local groundwater wells. Well water samples were analyzed for conventional parameters, as well as for metals and some other compounds. The tables on pages 52 through 54 provide the information available on these tests.
- 5.3.2 <u>Surface Water/Stream Sediment Data</u> As mentioned in the previous section of this report, a preliminary site sampling and analysis program was initiated, which included the sampling of adjacent and on-site surface waters and sediments. The data obtained for these samples is presented on pages 55 and 56.
- 5.3.3 Air Quality Data There has been no sampling of the atmosphere related to the release of chemical contaminants from this site as of May 3, 1983.
- 5.3.4 Other Analytical Data As previously mentioned in

this section on past analytical results, surface water (ponds) sediments and site soils have been sampled as part of a preliminary site investigation program. The analytical results are presented in the tables on pages 55 and 56. In addition, samples of the barrels stored on site were obtained and analyzed by the Monroe County Health Department. These results are indicated in the tables on pages 57 through 59.

# MEMORANDUM

DATE May 5, 1982

Richard S. Burton

Dr. Steadman

Private Well Water Samples - 4/26/82

### #45977B

Total Solids - 6.3 mg per 100 ml

Major Elements: Na, Mg, Ca Minor Elements: Si, Al Trace Elements: Cu, B, Fe

Not Detected: Pb, Cd, Cr, Ni, etc.

Cu is about 10 ppb

## #45978B

Total Solids - 44 mg per 100 ml

Major Elements: Na, Mg Minor Elements: Si, Ca

Trace Elements: Cu, B, Fe, Al

Not Detected: Pb, Cd, Cr, Ni, etc.

Cu is about 30 ppb

LTS: emh

rarameter	Units	240 Golden Road	Part 5 Standard	
r 	-	4-13-82	-	
Trbidity	Ņtu	7.0	5.0	
Odor	Odor Units	None	3	
	-	7.0	-	
kalinity	$mg/l$ as $CaCO_3$	414	-	
Total Hardness	$mg/l$ as $CaCO_3$	504	-	
<b>C</b> loride	mg/1	180	250	
lfate	mg/l	70	250	
Total Dissolved Solids	mg/l	748	-	
Specific Conductance	umhos/cm	982	<del>-</del>	
lcium	mg/1	153	-	
Magnesium	mg/1	41	entre de la companya	
Şodium	mg/l	8.4	270	
tassium	mg/l	2.4	_	
Total Cyanide	ug/1	<b>&lt;</b> 10	_	
Fluoride	ug/l	200	2200	
enol	ug/l	<b>4</b> 1	_	
Hee Ammonia	ug/l as N	50	• <u> </u>	
Total Kjeldahl Nitrogen	ug/l as N	1000	_	
trate	ug/1	300	10000	
tal Phosphate	ug/l as P	42	_	
Arsenic	ug/1	*	50	
irium	ug/1	*	1000	
dmium	ug/1	<b>4</b> 1	10	
Chromium	ug/1	19.	50	
pper	ug/1	19	1000	
on	ug/1	470	<u>300</u>	
Lead	ug/l	S	50	
Manganese	ug/1	37	300	
elenium	ug/1	*	10	
Silver	ug/1	<b>4</b> 5	50	
Zinc	ug/l	82	5000	
ercury	. ug/1	0.3	2	
	Anions	14.837	-	
<b>€</b>	Cations	14.722	-	
;	% Error	-0.4	<del>-</del>	

<sup>\*</sup>Results not yet available

| Gample collection and analysis by Monroe County Health Department

			-
Parameter	Units	227 Golden Road	Part 5 Standard
impling Date	-	4-13-82	-
hrbidity	Ntu	0.15	5.0
Oder	Odor Units	None	3
₹ f	-	7.5	_
kalinity	mg/l as CaCO <sub>3</sub>	377	-
· Total Hardness	mg/l as CaCO <sub>3</sub>	483	-
©`iloride	mg/1	70	250
ilfate	mg/l	81	250
Total Dissolved Solids	mg/l	600	<b></b>
Enecific Conductance	umhos/cm	984	
lcium	mg/l	135	-
Magnesium	mg/l	42	_
§odium	mg/l	• 40	270
otassium	mg/l	3.7	270
· Total Cyanide	ug/1	410	- -
Fluoride	ug/l	160	2200
lenol	ug/1	41	-
ree Ammonia	ug/l as N	20	-
Total Kjeldahl Nitrogen	ug/l as N	400	-
_trate	ug/1	4600	10000
. 🖶 tal Phosphate	ug/l as P	17	-
Arsenic	ug/1	*	50
rium	ug/l	• ,	1000
- dmium	ug/1	<b>4</b> 1	10
Chromium	ug/l	8	50
pper	ug/1	51	1000
on .	ug/l	230	300
Lead	ug/l	<b>4</b> 5	50
inganese	ug/1	46	300
elenium	ug/l	*	10
Silver	ug/1	45	50
inc .	ug/1	87	5000
ercury	ug/1	0.2	2
_	Anions	11.532	<b>-</b>
E	Cations	11.494	-
	% Error	-0.2	-

<sup>\*</sup>Results not yet available
Sample collection and analysis by Monroe County Health Department

confe Laboratory : ... Golden Rd. Tirum Disposel Site Sample Type: Camples: 5/12/82 Registry No. Silment to Seiment to Pow m Pond N 100ft. Soil around willing Sit. محسمه 82-132-05 82-132-06 82-132-03 82-132-01 82-132-04 82-132-02 Units 3/0 0.12 0.12 Cr 40.01 60.01 0.01 0.09 0.10 0.11 0.01 0.01 0.05 40.01 0.17 20.01 2.48 0.51 1.33 Mg/e 20 28 20 N9/2 135 0 115 49/1 NA MA NA LICHT POLITIVE TRACE POSITIVE LERANY H.C.

	f Solid Wasto	Diene	54.		C 1 T	FODITE LABO	ratory	
Date Sampled: 5/12/82					Sample Type:			
Date Sampl	ed: 5/12/82	<u></u>		•	Registry	No •		
		Soil Pace of	Tap outside	?	T	<u> </u>	-1	
ampling S	ite	Popular sul	Filzsipmons Residence					
ab. Numbe	Γ	82-132-07	82-132-08					
arameter	Units							
60	كافس							
CQ			0.13				- 10.	
<u>Cr</u>	~3/g		60.01				.0.	
Po	~g/ <sub>2</sub>		0.12				. 8 15	
Ni.	m/2		0.01					
2.	4	Applicate the equipment of the con-	0.21				<u>و</u>	
Fe	~ ~ <del>*</del>		0.03				.3	
BONAON	19/1		۷   0					
1957KW	Mg/8.		۷ اه			 		
Thene	19/1.	Adapta.	~~					
coleun U.C		HONE	_					
: 1			•					
4			•		)	·		
			- 1 • 1 • • • • • • • • • • • • • • • •					
			<del></del>		e deservice a series of the se		  .	
			•	•••• • • • • • • • • • • • • • • • • •			4	
			·			e de visa e de la compa	<u></u>	
1								
			}				· .	
-						į	•	
				- !	<del>.</del> .			
	• • • • • • • • • • • • • • • • • • •	. · •	,					

# MEMORANDUM

DATE May 19, 1982

Richard S. Burton - Associate Chemist

Ann Marie LaBella - Sanitary Chemist (Inf.

Samples Collected from Golden Road Site

# Laboratory #45995

Bluish black caked substance. Substance is soluble in water and methyl alcohol. In solution fluoresces pink under long wave ultraviolet light.

Fluorescence Spectrophotometer scan gives exciter wavelength of 320 mu and analyzer wavelength of 365 mu.

The substance appears to be an organic dye.

#### Laboratory #45996

Bluish black debris. The substance appears to be soil and debris with a bluish color. The bluish substance is water soluble, however it was not concentrated enough to be detected by Fluorescence Spectrophotometry.

#### Laboratory #45997

Bluish black caked substance, large pieces. Soluble in water and methyl alcohol. In solution fluoresces pink under long wave ultraviolet light. Fluorescence Spectrophotometer scan gives exciter wavelength of 320 mu and analyzer wavelength of 365 mu.

The substance appears to be an organic dye.

# Laboratory #45999

Bluish black debris. The debris appears to be a white substance with the bluish color adhering to it. A water solution fluoresces pink under ultra-violet light. Fluorescence Spectrophotometer scan gives exciter wavelength of 320 mu and analyzer wavelength of 365 mu.

The substance appears to be an organic dye.

# Laboratory #45998

Fibrous material impregnated with bluish black substance. When examined microscopically the substance appears to be blotter paper saturated with the bluish black substance. A portion of the sample was tested by placing it in water to extract the dye, however the dye did not leach out.

## Laboratory #45994

Whitish Powder. Microscopically it appears as fine waxy needles adhering to a powder substance. Physically separating the two forms and performing an Infrared Spectroscopic scan of both reveals they are the same compound in two different crystalline forms. The substance appears to be an aromatic amine.

### Laboratory #46000

Bluish black liquid. Miscible with water and methanol. Substance fluoresces pink under long wave ultra-violet light. Fluorescence Spectrophotometer scan gives exciter wavelength of 320 mu and analyzer wavelength of 365 mu.

The substance appears to be an organic dye.

## Laboratory #46004

Black liquid oily and viscous in appearance. Substance appears to be old motor oil mixed with water.

The following samples were analyzed by Gas Chromatography utilizing a 50 meter glass capillary column packed with OV 101, temperature programmed from 60° to 230°C at a rate of 4°/minute.

#### Laboratory #46001

Dark brown liquid. Sample prepared for Gas Chromatographic analysis by diluting with chloroform. Chromatogram indicative of that of toluene.

To determine whether the liquid was combustible a cotton swab was dipped into the sample and ignited. The sample burned immediately, therefore, the substance was combustible.

# Laboratory #46001a

Same dark brown liquid when extracted with freon formed a plasticlike precipitate. The freon was decanted and diluted with chloroform. Analysis of the sample revealed a chromatogram indicative of toluene.

# Laboratory #46002

Light brown liquid. A cotton swab was dipped with the sample and ignited, to determine whether the liquid was combustible. The sample burned immediately, therefore the substance was combustible. Sample placed in a porcelain crucible with a watch glass over it. Sample was gently warmed to 80-85°F at this temperature vapors ignited. Sample was injected into the Gas Chromatograph; analysis reveals a chromatogram indicative of a mid-range petroleum distillate containing both toluene and xylenes.

# Laboratory #46003

Light brown liquid. A cotton swab was dipped into the sample and ignited, to determine whether the liquid was combustible. The sample burned immediately, therefore the substance was combustible. Sample was injected into Gas Chromatograph undiluted; analysis reveals a chromatogram indicative of a mid-range petroleum distillate containing both toluene and xylenes.

### Laboratory #46005

Clear liquid. A cotton swab was dipped into the sample and ignited. The sample being predominately water did not burn. The sample was extracted with freon and concentrated to a volume of approximately .5 mls and injected into the Gas Chromatograph. Analyses of the concentrate reveals a chromatogram indicative of toluene and xylenes.

AML: emh

#### 6.0 ADEQUACY OF AVAILABLE DATA

In compiling the hazard ranking score, the Golden Road Disposal Site was found to have a score for  $S_m$  equal to 14.5. However, because some route rating factors, due to data inadequancies, involve a certain degree of subjectivity a range for the  $S_m$  score was developed and found to be 10.0 to 15.0.

The existing data base for the Golden Road Disposal Site is inadequate in the following respects:

- o The population served by and the uses of surface water and groundwater have been estimated. The possibility for use for irrigation has been noted, but not confirmed.
- o No soil borings have been performed on-site, and as such, an accurate characterization of the soil profile is not possible. Also, the soil permeability range used has been estimated from information which is not considered highly reliable.
- o No groundwater samples were obtained from wells on-site, although those showing contamination were located within 400 feet.

Beyond the HRS score itself, additional information is needed to assess the type and cost of alternative remedial actions at the site. The types of information include:

- o Is the site located within an area of groundwater discharge or groundwater recharge?
- o Has the original ground surface below the foundry sand been excavated? If so, to what depth?
- o What are the nature and hydraulic characteristic of the bedrock?

#### 7.0 PROPOSED PHASE II WORK PLAN

#### 7.1 Objectives

The objectives of the Phase II Field Investigation are to fill the data gaps identified in Section 6.0 of this report, in order to permit a complete site characterization/ranking (HRS score) and engineering evaluation of remedial alternatives. The field investigation includes the following items:

- o Air Monitoring
- o Geophysical Exploration
- o Subsurface Investigation
- o Monitoring Well Installation
- o Sampling and Analysis
- o Engineering Evaluation Report/HRS Score

Throughout the investigative effort, field activities will be performed in strict accordance with established safety protocol, as set forth by the New York State Department of Environmental Conservation.

#### 7.2 Scope of Work

#### 7.2.1 <u>Air Monitoring</u> - Prior to implementation of the

various field investigative techniques, an initial site screening will be conducted using a Century Organic Vapor Analyzer (OVA) and/or HNU photoionizer. Based upon described site characteristics, Recra team personnel engaged in this activity will enter the site, equipped with level 3 respiratory protection. A grid pattern will be established at the site and readings will be taken and recorded at each grid point. This survey will determine the initial level of protection necessary for worker's safety. In addition, upwind and downwind air monitoring stations will established in relation to the prevailing wind condition. If the results are indicative of air quality problems, additional testing will initiated as specified directions and distances away from the site.

During actual field investigative work, ambient and worker air monitoring will be conducted periodically using appropriate instrumentation, such as the photoionizer and/or OVA. When deemed necessary from actual readings, the level of respiratory protection will be adjusted to meet existing conditions. All disposable equipment necessary for worker safety will be placed daily into covered on-site drums

provided by Recra, and removed from the site and disposed of either upon reaching full capacity or upon completion of all field work.

- 7.2.2 Geophysical Exploration - Prior to the subsurface investigation, one surface geophysical method will be used to determine the possibility and extent of contaminant plume migration offsite. A VLF-EM terrain conductivity survey will be performed, using an EM-31 terrain conductivity meter, continuously along the southern and eastern boundaries of the southern disposal area at the offset distances of approximately 100 and 300 feet beyond the edge of the fill where it meets the wetland area. In addition, a terrain conductivity survey will be performed to both the west and north of the northern disposal area at similar offset distances. purpose of this survey will be to detect the possible migration of a contaminant plume from the site.
- 7..2.3 <u>Subsurface Investigation</u> The information obtained from the geophyscial exploration will be used to assist in locating the test borings and monitoring wells. Presently, it is proposed that five (5) test borings be installed: one (1) each on the west and

north side of the northern disposal landfill area; one (1) each on the south and east sides of the southern disposal area; and one (1) south of Route 490 which should not be influenced by contaminant migration in either surface water or groundwater. All borings will penetrate 10 feet into bedrock.

All test borings will be performed under the direct supervision of a qualified geologist or hydrogeologist. The test borings will be drilled with a truck, trailer, and/or all-terrain-mounted auger rig using hollow stem augers. During construction of the test borings, split spoon samples will be continuously obtained. Also, if a confining layer is encountered, Shelby tube samples will be obtained to determine its undisturbed permeability.

The acquired samples will be visually identified in the field following the procedure set forth in ASTM-D-2488, noted appropriately on boring logs with the sample number and recorded standard penetration test results (ASTM-D-1586), and placed in pre-cleaned, teflon-lined, screw-cap glass jars for return to Recra Research Inc.'s laboratory in Tonawanda, New York.

In order to avoid possible cross-contamination during construction of the test borings, the upgradient boring will be completed first; then the remaining holes will be drilled. Between each test boring the augers will be cleaned with water obtained from a known non-contaminated source. Also, between each split spoon sample, the split spoon will be cleaned with water, acetone and distilled water. All spend water/acetone liquid accumulated during this process will be disposed of in an on-site drum. Upon completion of each test boring to bedrock, the test boring will be backfilled with cement bentonite grout to approximately five (5) to six (6) feet below the first encountered water level, in order to avoid the possible vertical migration of contaminated groundwater from the first encountered water-bearing zone down to bedrock. Prior to leaving the site, the drill rig will be decontaminated using high pressure water.

7.2.4 <u>Monitoring Well Installation</u> - Pending review of the information obtained from the soil samples, geophysical results and approximate water levels in the test borings, it is proposed that eight (8) monitoring wells be installed at five (5) locations around the site. All wells will terminate 5 feet

below the encountered water table or at the top of bedrock, whichever comes first, except for the deeper wells in the well clusters, which will extend 10 feet into rock. The wells will be screened from immediately below the encountered water table to their termination, except for the deeper bedrock wells, which will be screened from the top of bedrock to their termination. Wells will be located as follows: one (1) well to the west of the northern disposal area; one (1) well to the south of the southern disposal area; one (1) well cluster to the south (upgradient) of Route 490; one (1) well cluster to the north (downgradient) of the landfill; and one (1) well cluster to the east of the southern disposal area. Where appropriate, wells will be installed within the original boring holes.

The monitoring wells will be constructed of two-inch I.D. cast iron riser pipe with a galvanized, wire-wound-wrapped steel screen. The annulars between the casing/screen and boring well will be properly sand-packed and sealed (cement/bentonite and cement) to the ground surface and the well provided with a locking cap.

Upon completion of well construction, all monitoring wells will be properly developed, and all test borings and/or top of well casings will be surveyed to determine their location and elevation above sea level. At that time, variable head tests will be performed on all wells around the site to estimate the on-site permeability of the screened interval. All field activity will be under the direct supervision of a qualified geologist and/or hydrogeologist.

7.2.5 Sampling and Analysis - The purpose of this task is to identify the magnitude and extent of groundwater and/or surface water contamination originating from the site, and to ascertain whether or not "hazardous substances" can be detected leaving the site.

Groundwater samples will be obtained from each of the monitoring wells. Following equilibrium of water levels within the installed wells, water elevations will be measured to determine the water table surface. Representative groundwater samples will then be collected after the wells have been fully evacuated or a volume three times the well contents has been removed. Evacuation of water from the wells and the acquisition of the samples will be

accomplished with an Isco Model 1580 peristaltic pump, using separate low-density polyethlene tubing for each well and changing the silicon rubber tubing within the Isco between wells. An exception to this procedure will be employed when obtaining the required volume of sample for volatile organic This will be accomplished using small analysis. volume galvanized steel bailers that have been separately designated for each well. Upon collection of the sample, field pH, temperature and conductivity measurements will be recorded. The samples will be placed in appropriate pre-cleaned bottles/septa vials, labeled, chilled and immediately returned to Recra's Tonawanda, New York laboratory for preservation and analyses of the parameters listed in Table 1. If the samples cannot be returned to Recra's laboratory in a timely fashion due to the distance between the site and Recra's laboratory, field preservation will be performed prior to chilling.

It is presently proposed that four (4) surface water samples be obtained: one (1) along the intermittent stream flowing toward Route 490; one (1) from the on-site pond; one (1) near the center of the southern wetland area; and from the wetland west of

the northern disposal area. The samples will be obtained using a pond sampler with separate sampling bottles designated for each sampling location. The same procedure as previously described for groundwater will be followed after acquisition of the surface water samples.

Analyses of all groundwater and surface water samples will be performed for the parameters listed in Table 1. The procedure to be utilized for analyses of all samples during this investigation are in basic accordance with one or more of the following reference texts:

- Methods for Chemical Analysis of Water and Wastes, United States Environmental Protection Agency,
- NIOSH Manual of Analytical Methods, 2nd Edition, United States Department of Health,
   Education and Welfare,
- <u>Standard Methods for the Examination of Water</u> and Wastewater, 14th Edition, APHA, AWWA, WPCF.

All analytical work will be in conformance with the overall Quality Assurance Program previously

submitted by Recra Research, Inc. to NYSDEC, entitled, "Operation Manual - Field and Analytical Services."

TABLE 1: ANALYTICAL PARAMETERS

Parameters	Surface Water	Groundwater
Number of Sample - This Site	4	8
рН	•	•
Specific Conductance	•	•
Chloride	•	•
Sulfate (T. 1)	•	•
Cyanide (Total)	•	•
Total Organic Carbon	:	:
Cadmium	*	0
Chromium (Total)	* .	0
Chromium (Hexavalent)	* .	0
Copper	* .	0
Iron	* .	0
Lead	* .	0
Mercury	*	0
Nickel	*	0
Silver	*	0
Zinc	*	0
Polychlorinated Biphenyls (PCB)	•	•
Volatite Organic Scan (VOS)	•	
Halogenated Organic Scan (HOS) Dry Weight	•	•

0 = Soluble Metals

\* = Total Metals

VOS is a screening procedure to identify the presence or absence of volatile chlorinated organic compounds Analyses are performed via purge and trap concentration, gas, liquid chromatography and an electrolytic conductivity detector.

HOS is a screening procedure to identify the presence or absence of halogenated organics. Analyses are performed via solvent extraction concentration gas liquid chromatography and an electron capture detector.

7.2.6 Engineering Evaluation Report/HRS Score - The purpose of this task is to compile all existing and newly-developed information concerning the site, and utilize this information to:

- o Prepare a Hazard Ranking System (HRS) score for the site
- o Preliminarily identify and evaluate feasible remedial alternatives at the site and prepare budget-level cost estimates for these alternatives

Close coordination with NYSDEC concerning this report is recognized as being essential, since it must be utilized by NYSDEC to prepare (in a short time frame) a State "Remedial Plan". Consequently, it is important that the format and contents of the report be clearly established early in the project. A Quality Control Committee will work closely with NYSDEC throughout the project to insure that this final report, and any other interim project outputs, are responsive to the Agency's needs.

## 7.3 <u>Estimated Costs</u>

The following are estimated costs to perform the Phase II Field Investigation outlined in the preceding section:

<u>Task</u>	Cost
Air Monitoring	\$ 590
Geophysical Exploration	\$ 8,240
Subsurface Investigation	\$ 4,780
Monitoring Well Installation	\$ 7,180
Sampling and Analysis	\$ 5,570
Report	\$ 6,170
Total	\$32,980

#### APPENDIX A

### DATA SOURCES AND REFERENCES

- 1. Monroe County Health Department Memorandum from Dr. Steadman to Richard Burton dated May 5, 1982.
- 2. Notes of interview with Dr. Richard Young of S.U.C. at Geneseo with Mark Hanna of URS Co. dated April 21, 1983.
- 3. Notes of interview with U.S. Weather Service by Mark Hanna dated April 20, 1983.
- 4. <u>Climatic Atlas of the United States</u>. U.S. Dept. of Commerce, National Climatic Center, Ashville, N.C. 1979.
- 5. <u>Monroe County, New York Soil Survey</u>. U.S. Dept. of Agriculture, Soil Conservation Service, 1973.
- 6. Monroe County Health Department memorandum from Ann Marie LaBella to Richard Burton dated May 19, 1982.
- NYSDEC Hazardous Waste Disposal Site Inspection Report dated August
   1980.
- 8. NYSDEC Hazardous Waste Disposal Site Inspection Report dated February 17, 1981.

- 9. Monroe County Health Department Memorandum from Richard Sutherland for the record dated March 30, 1982.
- 10. Notes of interview with Diane Salopek of the Center for Governmental Research by Mark Hanna of URS Company dated May 17, 1983.
- 11. Notes of interview with Jay Baker of the Soil Conservation Service by Mark Hanna of URS Co. dated April 28, 1983.
- 12. NYSDEC Memorandum from John Rankin to Paul Schmeid dated August 26, 1982.
- Rainfall Frequency Atlas of the United States. Technical Paper No.
   40, U.S. Dept. of Commerce, Washington D.C. 1963.
- 14. Map of Wetlands in Town of Chili as developed by the Monroe County Environmental Management Council/NYSDEC for the Monroe County Map Atlas.
- 16. Notes from interview with Howard Fitzsimons, Jr. by Jerry Thew of NYSDEC dated June 11, 1981.

17. Aerial photographs of the site obtained from the Monroe County Environmental Management Council are as follows:

October 16, 1951 ARK-2H-15,ARK-2H-16;
May 3, 1961 AQB-107, AQB-108;
April 15, 1970 1983-15-937, 1983-15-938;

April 22, 1975

18. Golden Road - Chili 6 Summary Report prepared by the Monroe County Environmental Management Council for the Monroe County Landfill Review Committee dated June 22, 1981.

2-077, 2-078.

- 19. Notes of conference between Carol Herrington and ECO Bill Wideman, both of NYSDEC, dated February 6, 1981.
- 20. Letter from Frank Shattuck of NYSDEC to Howard Fitzsimons dated May 20, 1981.
- 21. Notes from interview with Tom Sechrist of the U.S. Fish and Wildlife Service by Mark Hanna of URS Co. dated May 17, 1983.
- 22. Flood Insurance Study, Town of Chili, Monroe County, New York.

  Federal Emergency Management Agency. February 1, 1979.

- 23. Map of Subsurface Bedrock Contours in Monroe County, New York as developed by Dr. Richard Young for the Monroe County Environmental Management Council dated February 1980.
- 24. Boring logs obtained from the Monroe County Department of Engineering dated September 11, 1972.

#### APPENDIX B

# HAZARDOUS WASTE DISPOSAL SITE REPORT REVISED

Code: B

Site Code: 8-28-021

Name of Site: Golden Road Disposal Site

Region: 8

County: Monroe

Town/City: Chili (T)

Street Address:

#### Status of Site:

- o Inactive landfill. Poorly sited, improperly operated and inadequately closed. Industries known to have used the facility. Direct evidence of specific hazardous substances disposed of at the site. 300 + barrels on-site. Site drains to a wetland, which outlets to an intermittent stream flowing northward to another designated wetland. Approximately 10 feet of soil over bedrock.
- o Rural/developing residential area. Flat topography.
- o No dwellings within 500 feet.
- o Nearest water supply: Private wells at 60, 227 and 240 Golden Road

  Monroe County public water available
- o Seasonal high water table near ground surface

o Soil type: shallow muck

Type\_of Site: Landfill

Estimated Size: 8 acres

Hazardous Waste Disposed? Confirmed

Type and Quantity of Hazardous Wastes: Toluene and Xylene. 300 + drums on site.

Present Owner: Howard Fitzsimons, Jr./227 Golden Road/Chili, New York

<u>Time Period Site Was Used:</u> 1955 to 1976

594-2337

Site Status: Inactive

<u>Types of Samples:</u> Soil, surface water, groundwater, pond sediment, barrel contents

Remedial Action: None

Status of Legal Action: None

Permits Issued: None

Assessment of Environmental Problems: Contamination of groundwater, surface water and soil confirmed. Site surrounded by designated wetland with established wildlife population.

<u>Assessment of Health Problems:</u> None known, but residential wells are in use in the area.

<u>Persons Completing this Form:</u> C. Mark Hanna (URS Company) on behalf of Recra Research, Inc.

<u>Date:</u> June 3, 1983