1437

## New York State Department of Environmental Conservation Division of Environmental Remediation Bureau of Hazardous Site Control

828075

ADDITIONS/CHANGES TO REGISTRY: SUMMARY OF APPROVALS

SITE NAME: FORMER BURROUGHS - UNI Current Classification 2	575	Volunteer Yes	
Activity: Add as Class Reclassi	fy to <u> </u> [	Delist Category	Modify
Approvals:	7	K	
1. Regional Hazardous Waste Engineer	Yes V	No	
2. BEEI of NYSDOH	Yes V	No	
3. DEE	Yes Z	No O	
4. BWRA Remediation Action Bureau Director [Class 2]	Yes V	Y No	
5. BHSC - Investigation Section	Yes	No	
6. BHSC - O&M Section [Class 4]	Yes	Мо	
7. BPM - Brownfield & Voluntary Cleanup S	Section	n/a	Date
8. Site Control Section	A	of///Jarino	Date 12/10/98
9. Director		La Colomb	Date 12/24/98
Completion Checklist for Registry Sites		Complete Initials	
OWNER NOTIFICATION LETTER?			1-8-99 - 1-26-99
ADJACENT PROPERTY OWNER NOTIFICATION LETTE	ER?		1-26-99
ENB/LEGAL NOTICE SENT? (For Deletion Only)			
COMMENTS SUMMARIZED/PLACE IN REPOSITORY			
FINAL NOTIFICATION SENT TO OWNER? (For Deletion Only)			
			The state of the s



### SITE INVESTIGATION INFORMATION

B CURRENT 2 PROPOSED 4 MODIFY  1. LIGOATION OF STIE (Attrach U.S.G.S. Topographic Map showing site location)  2. Universingle Prohester  3. Site Lattrach 43 **11 **3 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **3 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. SITERY VESCRIPT STEE STEE LAttach as leps also showing disposal/swarpling locations)  This site is located in an Industrial/commercial section of Richester. The area is serviced by municipal water and sever. The acts is presently an active manufacturing factors and sever in the second state of	1. SITE NAME		2. SITE NUMBER	3. TOWN/CITY/VILLAGE	4. COUNTY		
B CURRENT 2 PROPOSED 4 MODIFY  1. LIGOATION OF STIE (Attrach U.S.G.S. Topographic Map showing site location)  2. Universingle Prohester  3. Site Lattrach 43 **11 **3 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **3 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. Site Statutude 43 **11 **13 ** Site Longitude 77 **39 **4 ***  2. Tak Map Numbers*  3. SITERY VESCRIPT STEE STEE LAttach as leps also showing disposal/swarpling locations)  This site is located in an Industrial/commercial section of Richester. The area is serviced by municipal water and sever. The acts is presently an active manufacturing factors and sever in the second state of	Former Burroughs-Ur	ner Burroughs-Unisys 8-28-075 City of Rochester Monroe					
A Conducting Robinster  5. Site Latitude 43 * 11 * 28 * Site Longitude 77 * 39 * 49 **  6. Tax Mas Numbers 2009 - 450 * 0001 - 001  7. Site Strest Address 1226 Ridgeway Ave. Rechester New York 14615  6. RRIERTY DESCRIBE THE STEE (Attach site plan showing disposal/sampling locations)  The site is located an industrial/commercial section of Robinster. The area is serviced by municipal water and saver. The site is presently an active manufacturing facility. University operated the site from 1979 - 1986, in 1986, underground strongs tests containing 2-bustness, methanical and isopreys dishoid were found to be leaking and the site from 1979 - 1986, in 1986, underground strongs tests containing 2-bustness, methanical and isopreys dishoid were found to be leaking and the site of the	5. REGION	6. CLASSIFICATION					
A Conducting Robinster  5. Site Latitude 43 * 11 * 28 * Site Longitude 77 * 39 * 49 **  6. Tax Mas Numbers 2009 - 450 * 0001 - 001  7. Site Strest Address 1226 Ridgeway Ave. Rechester New York 14615  6. RRIERTY DESCRIBE THE STEE (Attach site plan showing disposal/sampling locations)  The site is located an industrial/commercial section of Robinster. The area is serviced by municipal water and saver. The site is presently an active manufacturing facility. University operated the site from 1979 - 1986, in 1986, underground strongs tests containing 2-bustness, methanical and isopreys dishoid were found to be leaking and the site from 1979 - 1986, in 1986, underground strongs tests containing 2-bustness, methanical and isopreys dishoid were found to be leaking and the site of the	8		CURRENT 2	PROPOSED 4 MC	DIFY		
6. Site Latitude 43 * 11 * 35 * Site Longitude 77 * 39 * 48 * C. Tax Map Numbers - 300 - 450 * OOOI - OOI -							
6. Rax Map Numbers: 0.90 - 45.0 - COOT - COT  6. SRIERTY DESCRIBE THE STE Catach size plan showing disposal/sampling locations  7. But is to located in an industrial/commercial section of Rochaster. The area is serviced by municipal water and sever. The site is presently an active manufacturing inflictive, Unity or good process of the size of the control of the size is located in an industrial/commercial section of Rochaster. The area is serviced by municipal water and sever. The site is presently an active manufacturing inflictive, the process of the size of the	a. Quadrangle Rochester		-				
8. BRIEFLY DESCRIBET THE SITE (Attent his plan showing disposal/sampling locations) The sits is incested in an industrial/commercial section of Rochester. The area is serviced by movicinal waster and sown. The sits is presently as ective manufacturing. The sits is incested in an industrial/commercial section of Rochester. The area is serviced by movicinal waster and sown. The sits is presently as ective manufacturing and ware removed. Unites conducted environmental investigations in 1887-1989 and dispinal account of the sit of the si	b. Site Latitude 43 ° 11 ' 35	" Site Longitude 77 °	39 ' 49 ′"				
8. BREFLY DESCRIBE THE STEE (Attach site plans showing disposal-lamping locations) The size is biometed in an indusprision-increase action of Anchester. The area is savied by municipal writer and sawur. The size is presently an ective monufacturing in the size of the si	c. Tax Map Numbers: 090-	450-0001-001					
The site in located in an industrial/commercial section of Bothester. The sere is serviced by municipal water and serve. This site is presently wan active microlinary in the facility. University presented the sist from 1979 - 1988. In 1989, underground to storage tasks continuing 2-bitanone, methanol and superposition was not presented and superposition of the service of the ser	d. Site Street Address 1225	Ridgeway Ave, Rochester	New York 14615				
Itality to Unique operated the size from 1979-1986. In 1986, underground storage tanks containing 2-butanone, methanol and isopropal alcohol were found to be lesking and were removed. Unique control of the size devices and included acetone which is reported as a breakdown product of sporgeanol. 1990, Unique conducted a IRM which included control of the departs of a found base groundwater with its reported as a breakdown product of sporgeanol. 1990, Unique conductate a IRM which included control of the sporgeanol. 1990, Unique conducted a IRM which included control of the sporgeanol. 1990, Unique conducted a IRM which included control of the sporgeanol of a dual production of the sporgeanol and the sporgea	8. BRIEFLY DESCRIBE THE SI	TE (Attach site plan showing	disposal/sampling locations)				
2. Completed (X)Phase I (X)Phase II (X) PSA (X)RI/FS (Y)PA/SI (X)Other IRM/Remedial Design/Remedial Construction/ Long Term Monitoring Program  9. Hazardous Wasta Disposed (Include EPA Hazardous Wasta Numbers)  10. ANALYTICAL DATA AVAILABLE  2. (X)Air (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil (Y)Wasta (Y)Leachate (Y)EPTox (YTCLP  2. Contravention of Standards or Guidance Values - Yes  1. Contravention on Standards or Guidance Values - Yes  1. Contravention on Standards or Guidance Values - Yes  1. Contravention on Standards or Guidance Values - Yes  1. Contravention on Standards or Guidance Values - Yes  1. Contravention on Standards or Guidance Valu	facility. Unisys operated the and were removed. Unisys of initially at percent levels for si construction and operation of modification to the GW/SVE sarea was successfully remedia above the groundwater RAOs	site from 1979 - 1986. In 19 onducted environmental inves te solvents and included acett a dual phase groundwater/soi ystem. The GW/SVE system ated to below the remedial act (acetone is detected around C	86, underground storage tar tigations in 1987 -1989 and one which is reported as a bil vapor extraction system. was operated until 1997. ion objectives (RAOs) estab 0.5 ppm). LThe groundwater	nks containing 2-butanone, methanol and isopropyl a signed a consent order in 1990. Contaminant lev reakdown product of isopropanol. 1990, Unisys or In 1994, following a RI/FS, a ROD was signed whice Confirmation sampling indicated that soil in the formalished in the ROD. One small area of groundwater or contamination is no longer found off the site or in	alcohol were found to be leaking els in on-site groundwater were anducted a IRM which included th called for enhancements and ner underground storage tank contamination (GW-5) remains the deeper wells. A long terms		
2. Completed (X)Phase I (X)Phase II (X) PSA (X)RI/FS (Y)PA/SI (X)Other IRM/Remedial Design/Remedial Construction/ Long Term Monitoring Program  9. Hazardous Wasta Disposed (Include EPA Hazardous Wasta Numbers)  10. ANALYTICAL DATA AVAILABLE  2. (X)AIr (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil (Y)Waste (Y)Leachate (Y)EPTox (Y)TCLP  3. Contravention of Standards or Guidance Values - Yes  17. Contravention of Standards or Guidance Values - Yes  18. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Contravention of Standards or Guidance Values - Yes  19. Nearest Surface Water: Distance I mile  19. Nearest Surface Water: Distance I mile  19. Nearest Surface Water: Distance I Mile  20. Nearest Sur			z marin				
2. Completed (X)Phase I (X)Phase II (X) PSA (XIRI/FS (YPA/SI (X)Other IRM/Remedial Design/Remedial Construction/ Long Term Monitoring Program  9. Hazardous Wasta Disposed (Include EPA Hazardous Wasta Numbers)  10. ANALYTICAL DATA AVAILABLE  2. (X)Air (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil (YWaste (Yeachate (YEPTox (YTCLP)))  3. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  11. Contravention of Standards or Guidance Values - Yes  12. Contravention of Standards or Guidance Values - Yes  13. Contravention of Standards or Guidance Values - Yes  14. Contravention of Standards or Guidance Values - Yes  15. Tester Manual Values  16. Nearest Burdance Values - Yes  17. Approved  18. Nearest Verter Supply: Distance N/A.  19. Direction East  19. Classification class c  19. Nearest Surface Water: Distance 1 mile  19. Nearest Surface Water: Distance 1 of t.  19. Nearest Surface Water: Distance 1 of t.  20. Nearest Surface Water: Distance 1 of t.  21. Plow Direction nonth east  22. Nearest Verter Supply: Distance N/A.  23. Direction West  24. ADDRESS  24. ADDRESS  25. Nearest Verter Supply: Distance N/A.  26. Nearest Surface Verter: Distance 1 of t.  27. Nearest Surface Verter: Distance 1 of t.  28. Nearest Verter Supply: Distance N/A.  29. Documented fish or wildlife mortality?  29. Documented fish or wildlife mortality?  29. Documented fish or wildlife mortality?  20. Nearest Supplemented Verter Norte  20. Near			· •				
2. Completed (X)Phase I (X)Phase II (X) PSA (XIRI/FS (YPA/SI (X)Other IRM/Remedial Design/Remedial Construction/ Long Term Monitoring Program  9. Hazardous Wasta Disposed (Include EPA Hazardous Wasta Numbers)  10. ANALYTICAL DATA AVAILABLE  2. (X)Air (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil (YWaste (Yeachate (YEPTox (YTCLP)))  3. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  10. Contravention of Standards or Guidance Values - Yes  11. Contravention of Standards or Guidance Values - Yes  12. Contravention of Standards or Guidance Values - Yes  13. Contravention of Standards or Guidance Values - Yes  14. Contravention of Standards or Guidance Values - Yes  15. Tester Manual Values  16. Nearest Burdance Values - Yes  17. Approved  18. Nearest Verter Supply: Distance N/A.  19. Direction East  19. Classification class c  19. Nearest Surface Water: Distance 1 mile  19. Nearest Surface Water: Distance 1 of t.  19. Nearest Surface Water: Distance 1 of t.  20. Nearest Surface Water: Distance 1 of t.  21. Plow Direction nonth east  22. Nearest Verter Supply: Distance N/A.  23. Direction West  24. ADDRESS  24. ADDRESS  25. Nearest Verter Supply: Distance N/A.  26. Nearest Surface Verter: Distance 1 of t.  27. Nearest Surface Verter: Distance 1 of t.  28. Nearest Verter Supply: Distance N/A.  29. Documented fish or wildlife mortality?  29. Documented fish or wildlife mortality?  29. Documented fish or wildlife mortality?  20. Nearest Supplemented Verter Norte  20. Near					W		
Septopanol, Methanol, 2-Butanone quantities unknown  10. ANALYTICAL DATA AVAILABLE  a. XIAIr (XiGroundwater (XiSurface Water (storm sewer) (XiSediment (within storm sewer (XiSoil ())Waste ()Leachate ()EPTox ()TCLP  b. Contravention of Standards or Guidance Values - Yes Groundwater was initial contaminated with site solvents at percent levels, including acetone which is reported to be a breakdown product of isopropanol. Remediation has reduced soil levels in the former underground storage tank area to below RAOs. One small area of shallow on-site groundwater contamination persists (GM-5) with detections of acetone above the RAO's (acetone concentration range around 0.5 ppm).  11. CONCLUSION  Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination persists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  13. Nearest Surface Water: Distance 1 mile Direction East Classification class c  15. Nearest Surface Water: Distance 1 mile Direction morth east ()Sole Source ()Primary ()Principal Active ()Yes ()No  16. Nearest Groundwater: Depth 10 ft. Flow Direction morth east ()Sole Source ()Primary ()Principal Active ()Yes ()No  17. Nearest Building: Distance 10 ft. Direction west Use: manufacturing  18. Nearest Economic Development Zone? ()Y (XIN )  19. Corpos of livestock on site? ()Y (XIN )  19. Corpos of livestock on site? ()Y (XIN )  10. Controlled Site Access? ()Y (XIN )  11. Controlled Site Access? ()Y (XIN )  12. Site OWNER's NAME 14. ADDRESS 15. TELEPHONE NUMBER 15. TELEPHONE NUMBER 16. PREABER 17. APPROVED  Signature Date S							
10. ANALYTICAL DATA AVAILABLE a. (X)Air (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil ())Waste ()Leachate ()EPTox ()TCLP b. Contravention of Standards or Guidance Values - Yes Groundwater was initial contaminated with site solvents at percent levels, including acetone which is reported to be a breakdown product of isopropanol. Remediation has reduced soil levels in the former underground storage tank area to below RAOs. One small area of shallow on-site groundwater contamination persists (GM-5) with detections of acetone above the RAO's (acetone concentration range around 0.5 ppm).  11. CONCLUSION  Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination persists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  a. Nearest Surface Water: Distance 1 mile  Direction East Classification class c  O. Nearest Groundwater: Depth 10 ft.  Flow Direction north east Classification class c  O. Nearest Surface Water: Distance NIA.  Direction wast Use: manufacturing  Active (1)Yes (1)No  1. Nearest Building: Distance 10 ft.  Direction wast Use: manufacturing  O. Nearest Groundwater: Depth 10 ft.  Crops or livestock on site?  (1)Y (X)N   Exposed hexardous waste?  (1)Y (X)N    Direction special status fish or wildlife mortality?  (1)Y (X)N   For Class 2: Priority Category  13. SITE OWNER'S NAME  14. ADDRESS  Signature  Date  17. APPROVED  19. Signature  Date  Signature  Date  Signature  Date				COther IRM/Remedial Design/Remedial Construction	/ Long Term Monitoring Program		
a. (X)Air (X)Groundwater (X)Surface Water (storm sewer) (X)Sediment (within storm sewer (X)Soil ()Waste ()Leachate ()EPTox ()TCLP b. Contravention of Standards or Guidance Values - Yes (Groundwater was initial contaminated with site solvents at percent levels, including acetone which is reported to be a breakdown product of isopropanol. Remediation has educed soil levels in the former underground storage tank area to below RAOs. One small area of shallow on-site groundwater contamination persists (GM-5) with detections of acetone above the RAO's (acetone concentration range around 0.5 ppm).  11. CONCLUSION  Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination persists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  a. Nearest Surface Water: Distance 1 mile Direction East Classification class c  b. Nearest Gundwater: Depth 10 ft. Flow Direction north east ()Sole Source ()Primary ()Principal Active ()Yes ()No  d. Nearest Building: Distance 10 ft. Direction west Use: manufacturing  b. In State Economic Development Zone? ()Y (X)N i. Controlled Site Access? ()Y (X)N  crops or livestock on site? ()Y (X)N j. Exposed hazardous waste? ()Y (X)N  crops or livestock on site? ()Y (X)N i. For Class 2: Priority Category  13. SITE OWNER'S NAME  14. ADDRESS  3199 Pilot Knob Road, MS-F1BO5, Eagan MN 55121  15. TELEPHONE NUMBER  Signature Date  Signature Date	•						
b. Contravention of Standards or Guidance Values - Yes  Groundwater was initial contaminated with site solvents at percent levels, including acetone which is reported to be a breakdown product of isopropanol. Remediation has reduced soil levels in the former underground storage tank area to below RAOs. One small area of shallow on-site groundwater contamination persists (GM-5) with detections of acetone above the RAO's (acetone concentration range around 0.5 ppm).  11. CONCLUSION  Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination persists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  13. Nearest Surface Water: Distance 1 mile Direction East Classification class content of the content of t	10. ANALYTICAL DATA AVA	ILABLE					
neduced soil levels in the former underground storage tank area to below RAOs. One small area of shallow on-site groundwater contamination persists (GM-5) with detections of acetone above the RAO's (acetone concentration range around 0.5 ppm).  11. CONCLUSION  Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination persists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  a. Nearest Surface Water: Distance 1 mile Direction East () Sole Source () Primary () Principal Contact: Water: Distance 1 of ft. Direction west () Sole Source () Primary () Principal Contact: Water Supply: Distance 10 ft. Direction west Use: manufacturing () Sole Source () Primary () Principal Controlled Site Access? () Y (X)N () Exposed hazardous waste? () Y (X)N () Exposed hazardous was			sewer) (X)Sediment (with	in storm sewer (X)Soil ()Waste ()Leachate	()EPTox ()TCLP		
Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination bersists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  a. Nearest Surface Water: Distance 1 mile	reduced soil levels in the form	er underground storage tank a	rea to below RAOs. One sn				
Site soil has been successfully remediated by the dual phase GW/SVE system. One small area of on-site groundwater contamination bersists. A long term monitoring program, which evaluates natural attenuation, has been implemented. It is recommended that the site be reclassified from a class 2 to a class 4.  12. SITE IMPACT DATA  a. Nearest Surface Water: Distance 1 mile	11. CONCLUSION						
A. Nearest Surface Water: Distance 1 mile	Site soil has been succe persists. A long term n	nonitoring program, wh	ich evaluates natural e				
A. Nearest Surface Water: Distance 1 mile	12. SITE IMPACT DATA						
Direction Active ()Yes ()No  d. Nearest Building: Distance 10 ft. Direction west Use: manufacturing a. In State Economic Development Zone?  d. ()Y (X)N i. Controlled Site Access?  d. ()Y (X)N j. Exposed hazardous waste?  d. ()Y (X)N j. Exposed hazardous waste?  d. ()Y (X)N k. HRS Score a. Impact on special status fish or wildlife resource?  d. ()Y (X)N l. For Class 2: Priority Category  13. SITE OWNER'S NAME  Juisys Corporation Contact: Keith Rapp  14. ADDRESS  3199 Pilot Knob Road, MS-F1BO5, Eagan MN 55121  15. TELEPHONE NUMBER  612-687-3280  17. APPROVED  Signature Date  Date  Date  Date	a. Nearest Surface Water: Dis	tance 1 mile	Direction East	Classification class c			
d. Nearest Building: Distance 10 ft.  Direction west  Use: manufacturing  i. Controlled Site Access?  ()Y (X)N  j. Exposed hazardous waste? ()Y (X)N  g. Documented fish or wildlife mortality? ()Y (X)N  i. HRS Score  i. Impact on special status fish or wildlife resource? ()Y (X)N  j. Exposed hazardous waste? ()Y (X)N  k. HRS Score  j. Impact on special status fish or wildlife resource? ()Y (X)N  j. Exposed hazardous waste? ()Y (X)N  j. Exposed haz	b. Nearest Groundwater: Dept	h 10 ft.	Flow Direction north east	()Sole Source ()Primary ()Principa	ı		
e. In State Economic Development Zone?  ()Y (X)N i. Controlled Site Access? ()Y (X)N  c. Crops or livestock on site? ()Y (X)N j. Exposed hazardous waste? ()Y (X)N  g. Documented fish or wildlife mortality? ()Y (X)N k. HRS Score  n. Impact on special status fish or wildlife resource? ()Y (X)N I. For Class 2: Priority Category  13. SITE OWNER'S NAME  Juisys Corporation Contact: Keith Rapp  14. ADDRESS  Juisys Corporation Contact: Keith Rapp  15. TELEPHONE NUMBER  612-687-3280  17. APPROVED  Signature  Date  Date  Date  Date  Date	c. Nearest Water Supply: Dista	ance N/A.	Direction	_ Active ()Yes ()No	ĺ		
Crops or livestock on site?  G. Documented fish or wildlife mortality?  G. Y.	d. Nearest Building: Distance	10 ft.	Direction west	Use: manufacturing			
3. Documented fish or wildlife mortality? 3. Documented fish or wildlife mortality? 4. Impact on special status fish or wildlife resource? 5. Impact on special status fish or wildlife resource? 6. Impact on special status fish or wildlife resource? 7. Impact on special status fish or w	e. In State Economic Developr	nent Zone?	( )Y (X)N	i. Controlled Site Access?	( )Y (X)N		
13. SITE OWNER'S NAME 14. ADDRESS 15. TELEPHONE NUMBER 3199 Pilot Knob Road, MS-F1B05, Eagan MN 55121 16. PREPARER Signature Date Signature Date Signature Date Signature Date Signature Date Date Signature Date	f. Crops or livestock on site?		()Y (X)N	j. Exposed hazardous waste?	( )Y (X)N		
13. SITE OWNER'S NAME Unisys Corporation Contact: Keith Rapp 14. ADDRESS 3199 Pilot Knob Road, MS-F1B05, Eagan MN 55121 16. PREPARER 17. APPROVED X Signature Date David A. Crosby, P.E., Environmental Engineer, DER-BCS	g. Documented fish or wildlife	mortality?	()Y (X)N	k. HRS Score			
Jnisys Corporation Contact: Keith Rapp  3199 Pilot Knob Road, MS-F1B05, Eagan MN 55121  16. PREPARER  Signature  Date  David A. Crosby, P.E., Environmental Engineer, DER-BCS	h. Impact on special status fis	h or wildlife resource?	( )Y (X)N	I. For Class 2: Priority Category			
16. PREPARER  Postal Los II 18 98  Signature Date Signature Date  David A. Crosby, P.E., Environmental Engineer, DER-BCS	13. SITE OWNER'S NAME		14. ADDRESS		15. TELEPHONE NUMBER		
Signature Date Signature Date David A. Crosby, P.E., Environmental Engineer, DER-BCS	Unisys Corporation Contact:	Keith Rapp	3199 Pilot Knob Road,	MS-F1B05, Eagan MN 55121	612-687-3280		
David A. Crosby, P.E., Environmental Engineer, DER-BCS	16. PREPARER David 1 4	11/18/	<u>ዓያ</u>	17. APPROVED  ★			
David A. Crosby, P.E., Environmental Engineer, DER-BCS	Signature	Date	4 , 1	Signature Date			
		mental Engineer, DER-BCS					
Name, Title, Organization	Name, Ti	tle, Organization		Name, Title, Organization			



### SITE INVESTIGATION INFORMATION

1. SITE NAME		2. SITE NUMBER	3. TOWN/CITY/VILLAGE	4. COUNTY
Former Burroughs-U	nisys	8-28-075	City of Rochester	l Monroe
5. REGION	6. CLASSIFICATION			
8		CURRENT 2	PROPOSED 4 MC	DDIFY
7. LOCATION OF SITE (Attac	ch U.S.G.S. Topographic Map	showing site location)		
a. Quadrangle Rochester				
b. Site Latitude 43 ° 11 ' 3	5 " Site Longitude 77 °	39 ' 49 '"		
c. Tax Map Numbers				
d. Site Street Address 122	5 Ridgeway Ave, Rochester	New York 14615		
8. BRIEFLY DESCRIBE THE S	ITE (Attach site plan showing	disposal/sampling locations)		
facility. Unisys operated the and were removed. Unisys of initially at percent levels for sconstruction and operation of modification to the GW/SVE area was successfully remediabove the groundwater RAOs	site from 1979 - 1986. In 19 conducted environmental investite solvents and included acet is a dual phase groundwater/so system. The GW/SVE system ated to below the remedial acts (acetone is detected around)	986, underground storage tar stigations in 1987 -1989 and one which is reported as a b il vapor extraction system. In was operated until 1997. tion objectives (RAOs) estab 0.5 ppm). The groundwater	ed by municipal water and sewer. The site is presides containing 2-butanone, methanol and isopropyld signed a consent order in 1990. Contaminant le reakdown product of isopropanol. 1990, Unisys of the 1994, following a RI/FS, a ROD was signed whith Confirmation sampling indicated that soil in the for lished in the ROD. One small area of groundwater or contamination is no longer found off the site or in led to monitor the remaining groundwater contamination.	alcohol were found to be leaking wels in on-site groundwater were conducted a IRM which included ch called for enhancements and mer underground storage tank contamination (GW-5) remains the deeper wells. A long terms
a. Area 5 acres b. EPA ID c. Completed (X)Phase I	(X)Phase II ( ) PSA		K)Other IRM/Remedial Design/Remedial Construction	n/ Long Term Monitoring Program
9. Hazardous Waste Disposed	d (Include EPA Hazardous Wa	ste Numbers)		i
Isopropanol, Methanol, 2-But	tanone quantities unk	nown		
			<u> </u>	
10. ANALYTICAL DATA AVA	AILABLE			
a. (X)Air (X)Groundwate		sewer) (X)Sediment (with	nin storm sewer (X)Soil ()Waste ()Leachat	e ()EPTox ()TCLP
a. (X)Air (X)Groundwate     b. Contravention of Standa Groundwater was initial contareduced soil levels in the form	er (X)Surface Water (storm ards or Guidance Values - Yes aminated with site solvents at	percent levels, including ace area to below RAOs. One sr	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contamina	of isopropanol. Remediation has
a. (X)Air (X)Groundwate     b. Contravention of Standa Groundwater was initial contareduced soil levels in the form	er (X)Surface Water (storm ards or Guidance Values - Yes aminated with site solvents at her underground storage tank a	percent levels, including ace area to below RAOs. One sr	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contamina	of isopropanol. Remediation has
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta- reduced soil levels in the form detections of acetone above to 11. CONCLUSION Site soil has been succe	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentrates of the state) are sesfully remediated by monitoring program, will	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contamina	of isopropanol. Remediation has tion persists (GM-5) with
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above to  11. CONCLUSION  Site soil has been succe persists. A long term is site be reclassified from	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentrates of the state) are sesfully remediated by monitoring program, will	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contamina	of isopropanol. Remediation has tion persists (GM-5) with
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term of site be reclassified from  12. SITE IMPACT DATA	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentrates of the state of the st	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminates of shallow on-site groundwater contaminates.  WE system. One small area of on-site groundwater contaminates. It	of isopropanol. Remediation has tion persists (GM-5) with
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term in site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essfully remediated by monitoring program, when a class 2 to a class 4 stance 1 mile	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/SI hich evaluates natural	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminates.  WE system. One small area of on-site grattenuation, has been implemented. It	of isopropanol. Remediation has ation persists (GM-5) with a groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Stands Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term of site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essafully remediated by monitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft.	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/ST hich evaluates natural.  Direction East Flow Direction north east	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site gattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip	of isopropanol. Remediation has ation persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Stands Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term of site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essaully remediated by monitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/SI hich evaluates natural  Direction East Flow Direction north east	etone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site gattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No	of isopropanol. Remediation has ation persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Stands Groundwater was initial conta reduced soil levels in the form detections of acetone above to  11. CONCLUSION  Site soil has been succe persists. A long term of site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essentially remediated by monitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A. 10 ft.	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/St hich evaluates natural  Direction East Flow Direction north east Direction west	cetone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing	of isopropanol. Remediation has ition persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta- reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term of site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance e. In State Economic Develop	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essentially remediated by monitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A. 10 ft.	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural  Direction East Flow Direction north east Direction West ()Y (X)N	catone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access?	of isopropanol. Remediation has ition persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term is site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance e. In State Economic Develop f. Crops or livestock on site?	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essfully remediated by monitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.  10 ft. ement Zone?	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural.  Direction East Flow Direction north east Direction west ()Y (X)N ()Y (X)N	cetone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c ()Sole Source ()Primary ()Princip Active ()Yes ()No Use: manufacturing i. Controlled Site Access? j. Exposed hazardous waste?	of isopropanol. Remediation has ition persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term is site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance e. In State Economic Develop f. Crops or livestock on site? g. Documented fish or wildlife	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essfully remediated by monitoring program, when a class 2 to a class 4 estance 1 mile th 10 ft. tance N/A.  10 ft. tement Zone?	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/SV hich evaluates natural  Direction East Flow Direction north east Direction West ()Y (X)N	cetone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access?  j. Exposed hazardous waste?  k. HRS Score	of isopropanol. Remediation has ition persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial conta reduced soil levels in the form detections of acetone above of  11. CONCLUSION  Site soil has been succe persists. A long term is site be reclassified from  12. SITE IMPACT DATA a. Nearest Surface Water: Dis b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance e. In State Economic Develop f. Crops or livestock on site?	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essfully remediated by monitoring program, when a class 2 to a class 4 estance 1 mile th 10 ft. tance N/A.  10 ft. tement Zone?	percent levels, including ace area to below RAOs. One sr tion range around 0.5 ppm).  the dual phase GW/ST hich evaluates natural  Direction East Flow Direction north east Direction west ( )Y (X)N ( )Y (X)N	cetone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c ()Sole Source ()Primary ()Princip Active ()Yes ()No Use: manufacturing i. Controlled Site Access? j. Exposed hazardous waste?	of isopropanol. Remediation has ition persists (GM-5) with groundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial contraventions of acetone above of the contravention of acetone above of the contravention of acetone above of the contravential of the contrave	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essaully remediated by emonitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.  10 ft. ement Zone?	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/St hich evaluates natural  Direction East Flow Direction north east Direction Direction west ( )Y (X)N	catone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access?  j. Exposed hazardous waste?  k. HRS Score  I. For Class 2: Priority Category	of isopropanol. Remediation has ation persists (GM-5) with aroundwater contamination is recommended that the
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial contareduced soil levels in the form detections of acetone above of the soil has been succepersists. A long term of site be reclassified from 12. SITE IMPACT DATA a. Nearest Surface Water: Dies b. Nearest Groundwater: Dep c. Nearest Water Supply: Dist d. Nearest Building: Distance e. In State Economic Develop f. Crops or livestock on site? g. Documented fish or wildlift h. Impact on special status fis 13. SITE OWNER'S NAME	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essaully remediated by emonitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.  10 ft. ement Zone?	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/ST hich evaluates natural  Direction East Flow Direction north east Direction West ( )Y (X)N ( )Y (X)N ( )Y (X)N	catone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access?  j. Exposed hazardous waste?  k. HRS Score  I. For Class 2: Priority Category	of isopropanol. Remediation has ation persists (GM-5) with a groundwater contamination is recommended that the al ( )Y (X)N ( )Y (X)N
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial contareduced soil levels in the form detections of acetone above of the soil has been succepersists. A long term is site be reclassified from 12. SITE IMPACT DATA a. Nearest Surface Water: Distance be. In State Economic Develop f. Crops or livestock on site? g. Documented fish or wildlife. Impact on special status fis. 13. SITE OWNER'S NAME	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essaully remediated by emonitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.  10 ft. ement Zone?	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/St hich evaluates natural  Direction East Flow Direction north east Direction Direction west ( )Y (X)N	ctone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access?  j. Exposed hazardous waste?  k. HRS Score  I. For Class 2: Priority Category  MS-F1B05, Eagan MN 55121	of isopropanol. Remediation has ation persists (GM-5) with a groundwater contamination is recommended that the al ( )Y (X)N ( )Y (X)N
a. (X)Air (X)Groundwate b. Contravention of Standa Groundwater was initial contraventions of acetone above of the contravention of acetone above of the contraventions of acetone above of the contravention of acetone of the contravention of	er (X)Surface Water (storm ands or Guidance Values - Yes aminated with site solvents at her underground storage tank at the RAO's (acetone concentral essaully remediated by emonitoring program, when a class 2 to a class 4 stance 1 mile th 10 ft. tance N/A.  10 ft. ement Zone?  e mortality? sh or wildlife resource?  E Keith Rapp	percent levels, including ace area to below RAOs. One so tion range around 0.5 ppm).  the dual phase GW/St hich evaluates natural  Direction East Flow Direction north east Direction Direction west ( )Y (X)N	ctone which is reported to be a breakdown product mall area of shallow on-site groundwater contaminate.  WE system. One small area of on-site grattenuation, has been implemented. It  Classification class c  ()Sole Source ()Primary ()Princip  Active ()Yes ()No  Use: manufacturing  i. Controlled Site Access? j. Exposed hazardous waste? k. HRS Score  I. For Class 2: Priority Category  MS-F1B05, Eagan MN 55121  17. APPROVED	of isopropanol. Remediation has ation persists (GM-5) with a groundwater contamination is recommended that the al ( )Y (X)N ( )Y (X)N



II University Place

Albany, New York 12203

Barbara A. DeBuono, M.D., M.P.H. Commissioner of Health

Dennis P. Whalen Executive Deputy Commissioner

October 14, 1998

Mr. David Crosby
Bureau of Construction Services
Division of Environmental Remediation
NYS Department of Environmental Conservation
50 Wolf Road
Albany, New York 12233

OCT 22

Re: Groundwater Monitoring Plan Former Burroughs/Unysis Facility Site #828075

Rochester, Monroe County

Dear Mr. Crosby:

I reviewed the September 24, 1998 Post-Remediation Groundwater Monitoring Plan for the Former Burroughs/Unysis Facility. I have no comments on this proposed groundwater monitoring plan. As always, please contact the Monroe County Health Department for their input.

Sincerely,
Mark E. Var Valkenbur

Mark E. VanValkenburg
Public Health Specialist IV

Bureau of Environmental Exposure

Investigation


CC:


G.A. Carlson, Ph.D.

Mr. D. Napier - RFO Mr. R. Elliott - MCHD Mr. G. Harris - DEC

Ms. M.J. Peachey - DEC Region 8

J:\WESTERN\MARK\LETTERS\FBURUN1.WPD





**UNİSYS** 

CONTRACTOR STOMOES

October 30, 1998

Mr. David A. Crosby

New York State Department of Environmental Conservation Bureau of Western Remedial Action Division of Hazardous Waste Remediation 50 Wolf Road, Remedial Section C Albany, New York 12233-7010

Subject: Post-Remediation Groundwater Monitoring Plan

Former Burroughs\Unisys Facility

**NYSDEC Site #8-28-075** 

Rochester, Monroe County, New York

Dear Mr. Crosby:

The purpose of this correspondence is to provide the New York State Department of Environmental Conservation (NYSDEC) with the information requested in your October 30, 1998 letter to me concerning isopropyl alcohol (IPA) degradation at the former Burroughs facility located at 1227 Ridgeway Avenue, Rochester, New York.

The essential disappearance of IPA and corresponding occurrence of acetone at the Ridgeway Avenue site as biodegradation is evidenced by the persistence of acetone concentrations in the soil and groundwater environment. Acetone concentrations have increased at the site with a parallel and corresponding decrease in IPA concentrations. Acetone is less easily oxidized by microorganisms; however, inorganic compounds found in the environment such as nitrates, sulfates, ferric iron, and carbon dioxide can serve as electron acceptors to facilitate oxidation. Acetone was not store or used at the facility, and the appearance of acetone is attributed to the intrinsic biodegradation of IPA. IPA will be degraded by intrinsic microorganisms in groundwater to acetone as demonstrated by the following oxidation equation:

 $C_3H_8O + 1/2 O_2 \rightarrow H_2O + C_3H_6O$  *IPA Acetone* 

Once the acetone is reduced to acetic acid, it is readily degraded by microorganisms and the end products are water and carbon dioxide.

$$C_3H_6O + 2 O_2 \rightarrow CO_2 + H_2O + CH_3COOH$$
  
Acetone Acetic Acid

We hope this clarifies your concern about isopropyl alcohol degradation. Additionally, the enclosed fact sheet on isopropyl alcohol documents the breakdown of IPA to acetone (page 1, paragraph 3) and is published by EMBBS (the Emergency Medicine Bulletin Board System) and is available on the World Wide Web as a resource at - <a href="https://www.embbs.com/cr/alc/alc/s.html">www.embbs.com/cr/alc/alc/s.html</a>.

I have also attached a copy of the certification that the Remedial Action was conducted in accordance with the approved remedial design and the Record of Decision. I believe this documentation has already been provided to NYSDEC.

If you have any questions please feel free to contact me at (651) 687-3279.

Sincerely,

Keith B. Rapp

UNISYS

Corporate Environmental Affairs

Program Manager

Enclosures: - Isopropyl Alcohol Summary

- PE Certification

cc: Tom Roszak

-Day Environmental\Rochester

Todd Caffoe

-NYSDEC\Avon

### **Isopropyl Alcohol**

Isopropyl alcohol ingestion is common among children and adults as both accidental and suicidal ingestions because it is an easily available product. It is best known as the main ingredient in rubbing alcohol, but is also present in window cleaners, toiletries, disinfectants, antifreeze, and paint remover. To complicate matters some products that contain isopropyl alcohol also contain methanol, ethanol, or ethylene glycol.

Pharmacology: Isopropyl alcohol is a clear, colorless liquid with a somewhat bitter taste and a smell of acetone. Unless the ingested dose is large, absorption occurs in as little as 30 minutes. This agent is well absorbed through the lungs and rectal mucosa. The alcohol can also penetrate the skin, but with less success than via a pulmonary or GI exposure. Isopropyl alcohol is metabolized to acetone in the liver by alcohol dehydrogenase. Eighty percent of the absorbed dose is then excreted by the kidneys as acetone with 20% being excreted unchanged. The acetone is also excreted in the lungs, saliva, and gastric juices.

Animal studies have suggested that isopropyl alcohol is two-three times more potent than ethanol as a CNS depressant. The breakdown product, acetone, is also a CNS depressant.

Clinical Presentation: The symptoms of ingestion occur within 30 minutes, with GI complaints of pain, vomiting, and hematemesis being predominant. Central nervous system effects include headache, muscular incoordination, ataxia, confusion, and coma. The initial excitatory phase that is well recognized with ethanol intoxication does not seem to be present with isopropanol ingestion. Pupil size may vary, but it is not uncommon to have miotic pupils. Should the eyes have direct exposure to isopropyl alcohol corneal de-epithelialization has been reported. The patient may have a distinct odor of acetone. With very large doses cardiovascular effects include myocardial depression and severe hypotension. Less common presentations include renal tubular necrosis, hemolytic anemia, acute myopathy, and hypothermia.

Diagnosis: The patient presenting in coma who has a suspected exposure to some type of alcohol, the diagnosis can be challenging. The patient will be unresponsive to narcan and glucose, and usually entities such as DKA, hepatic coma (in an older patient), carbon monoxide, trauma, etc. can usually be quickly ruled out by a careful exam and a few simple tests. Once the diagnosis of a toxic alcohol (or a toxic amount of a usually nontoxic alcohol) is suspected the difficulty comes in making the diagnosis. The onset of the central nervous system effects of all the alcohols is rapid. The more severe consequences of ethylene glycol and methanol (the blindness, renal failure, and severe metabolic acidosis may be slightly delayed. All of the major alcohols have a distinct odor except ethylene glycol. In the case of isopropyl alcohol the odor is a sweet ketotic scent due to the release of acetone in the breath. Isopropyl alcohol tends to produce only a mild elevation of the anion gap and only a mild acidosis if any. It is alsounique in producing a very large amount of ketones (the acetone that is being excreted from the kidneys) in the urine.

Serum osmolality may be greater than calculated with all four alcohols, thus isopropanol is similar to ethanol in that it produces little to no anion gap metabolic acidosis (unless the patient has other problems such as hypotension, hypoxia, etc.), but does have an elevated osmolol gap. Isopropyl alcohol also tends to have significant hypoglycemia.

Treatment: The treatment of isopropyl alcohol exposure is recognition and support of the complications. If exposure was through the skin then decontamination is appropriate while trying to maintain body temperature. If the exposure was respiratory the patient should be removed from the environment. Hemorrhagic trachoebronchitis is a complication of inhaled isopropanol. If the exposure was a large, recent dose of isopropanol, gastric lavage and charcoal may be appropriate. Isopropanol does undergo gastric re-excretion and continuous gastric emptying has been recommended, but this is usually not required. Should the patient be stable after the initial evaluation it is reasonable to observe the patient and use simple supportive measures until the patient recovers. Suspicion should always be present about other ingestions and the labs previously discussed should be ordered.

Isopropanol is an ideal substance for dialysis because of its low molecular weight, low volume of distribution, and low protein plasma binding. The question then, is who requires dialysis? Those patients with isopropyl levels above 400-500 mg/dl are usually the ones that have significant hypotension and coma. Thus, patients with coma and hypotension with or without a level of 400-500 mg/dl should probably receive hemodialysis.

Pediatric Considerations: Young children may accidentally ingest isopropyl alcohol just as they can with any other available substance. However, children may develop a serious intoxication following topical application of isopropyl alcohol for the relief of fever. This exposure may actually be more of an inhalation injury than a dermal exposure, but the end result in the same. Isopropyl alcohol can come in concentrations of 70%. At this concentration as little as 2-2.5 ml/kg may lead to toxicity. The children may present with altered mental status or coma. The key to diagnosis is the same as with adults. The child should have acetonuria, coma, little to no acidosis and anion gap, with a wide osmolol gap. Treatment is the same as for adults.

$\sim$	. •			
(Cin	ntiniie	with	L)ISC	ussion
$\sim$	IIIIIII	AATCIA .	~~~	4221011

Return to EMBBS Home Page



### FOCUSED EVALUATION OF REMEDIAL ALTERNATIVES REPORT FORMER BURROUGHS-UNISYS FACILITY ROCHESTER, NEW YORK - NYSDEC SITE #82-8-075

Unisys Corporation, and BHE Environmental, Inc., (BHE) are submitting this final report to New York State Department of Environmental Conservation (NYSDEC) for work performed at the former Burroughs Facility located at 1227 Ridgeway Avenue, Rochester, New York. This report revises the draft copy of the <u>Focused Evaluation of Remedial Alternatives Report</u>, submitted to NYSDEC on January 15, 1997. This report was prepared in conformance with the strict quality assurance/quality control procedures of BHE and Unisys to ensure the report meets the highest standards in terms of methods used, data evaluated, and information presented.



Respectfully submitted,

John M. Bruck, P.E.

President, BHE Environmental

James C. Albertz, P.E.

Director of Engineering and Remediation

BHE Environmental

Keith B. Rapp

Program Manager

Unisys Corporate Environmental Affairs

Senior Hydrogeologist

Unisys Corporate Environmental Affairs

Kristin S. Yahnke Project Engineer

Unisys Corporate Environmental Affairs

Notice: This report was prepared by BHE Environmental Inc., and Unisys Corporation, solely for the benefit of its client in accordance with an approved scope of work. Neither BHE, nor Unisys, assumes liability for the unauthorized use of this report or the information contained in it by a third party.

Copyright © 1997 Unisys Corporation.

Copyright © 1997 by BHE Environmental.

The Remedial Action has been completed in accordance with the approved Remedial Design and Record of Decision.

### New York State Department of Environmental Conservation

Division of Environmental Remediation

Bureau of Construction Services, Room 267 50 Wolf Road, Albany, New York 12233-7010

Phone: (518) 457-9280 FAX: (518) 457-7743



**FAX** 

OCT 3 0 1998

Mr. Keith Rapp Project Manager Unisys Corporate Environmental Affairs 3199 Pilot knob Road - MS F1B05 Eagan, Minnesota 55121

Dear Mr. Rapp:

Burroughs/Unisys, Site #8-28-075 RE:

Monroe County

Post-Remediation Groundwater Monitoring Plan

The Department has completed the review of the Post-Remediation Groundwater Monitoring Plan, dated September 24, 1998. The Department requests that you provide a literature reference which supports biodegradation of isopropyl alcohol to acetone. With regards to the sampling frequency and analysis plan the Monitoring Plan is acceptable to the Department.

As requested in my September 16, 1998 letter to David Hume, and as required by the Consent Order, the Department requires a certification that the Remedial Action was conducted in accordance with the approved remedial design and the Record of Decision. The certification must be stamped and signed by a professional engineer registered in New York. When an acceptable certification is received, I will process the reclassification package.

Please be advised that when the site is reclassified the project lead will be turned over to Mr. Todd Caffoe, P.E., of our Region 8 Office in Avon. Therefore, until the site is reclassified, please copy Mr. Caffoe on site correspondence. Further, please remove Mr. Amar Nagi from the cc lists.

The Department appreciates Unisys' continued efforts to complete the remedial program at the Former Burroughs/Unisys site. If you have any questions, please feel free to contact me at (518) 457-9285.

Sincerely,

David A. Crosby, P.E.

**Environmental Engineer** 

Central Field Services Section

**Bureau of Construction Services** 

Division of Environmental Remediation

cc:

M. VanValkenburg - NYSDOH, Albany

R. Elliot - Monroe County DOH

T. Caffoe/M. J. Peachey - NYSDEC, Region 8

DAC/ts

bcc:


G. Harris

G. Rider - BHSC

D. Crosby

Dayfile

A:/longtermbu.wpd



### NEW YORK STATE DEPARTMENT OF

# ENVIRONMENTAL CONSERVATION

DIVISION OF HAZARDOUS WASTE REMEDIATION

### RECORD OF DECISION

**BURROUGHS-UNISYS** 

SITE #8-28-075

CITY OF ROCHESTER, MONROE COUNTY

March 1994

# Burroughs-Unisys Inactive Hazardous Waste Site City of Rochester, Monroe County, New York Site No. 8-28-075

### Statement of Purpose and Basis

The Record of Decision (ROD) presents the selected remedial action for the Burroughs-Unisys Inactive Hazardous Waste Disposal Site which was chosen in accordance with the New York State Environmental Conservation Law (ECL). The remedial program selected is not inconsistent with the National Oil and Hazardous Substances Pollution Contingency Plan of March 8, 1990 (40CFR300).

This decision is based upon the Administrative Record of the New York State Department of Environmental Conservation (NYSDEC) for the Burrough-Unisys Inactive Hazardous Waste Site and upon public input to the Proposed Remedial Action Plan (PRAP) presented by the NYSDEC. A bibliography of the documents included as a part of the Administrative Record is included in Appendix B of the ROD.

### Assessment of the Site

Actual or threatened release of hazardous waste constituents from this site, if not addressed by implementing the response action selected in this ROD, presents a current or potential threat to public health and the environment.

### Description of Selected Remedy

Based upon the results of the Remedial Investigation/Feasibility Study (RI/FS) for the Burroughs-Unisys Site and the criteria identified for evaluation of alternatives the NYSDEC has selected enhancements/modifications of the existing groundwater/vapor extraction system. The components of the remedy are as follows:

Continued operation of the existing IRM system with enhancement and modifications to the groundwater/vapor extraction system. These enhancement and modifications include system cycling, evaluation of pulsing of the existing system and an evaluation of either passive air or active water injection to assist mitigation.

These modifications will be evaluated in the design phase of the project.

- Temporary GW/SVE connection to existing monitoring wells.
- Installation of three (3) additional extraction wells located at identified pockets of contamination. These wells will be designed to mitigate contamination in the saturated/top-of-rock zone.
- It is recognized by the Department that in light of the low permeability of site subsurface soils, that Groundwater Vapor Extraction is an innovative technology that has the potential with modifications and enhancements to achieve the site Remedial Action Objectives (RAOs). Further, it is recognized that the groundwater unit under the site is not presently utilized for either industrial or potable purposes and because of the low site permeability and further use of the groundwater appears unlikely.

As such the Groundwater Vapor Extraction (GW/VE) system implemented during the Interim Remedial Measure and conceptually modified in the Detailed Analysis of the Feasibility Study will be designed and operated to remediate source area soils and groundwater to the extent technically practicable. The GW/VE system will be modified and/or enhanced and operated for a minimum of one year. After one year a determination will be made if the system has reached asymptotic conditions with regards to both contaminated vapor and groundwater extractions rates. If the system has reached asymptotic conditions, sampling of both the surface soils and groundwater will be conducted to determine if RAOs have been achieved. If either soil or groundwater RAOs are not achieved the system will continue operation and a focused evaluation of further remedial actions will be conducted. The focused study will include an evaluation of no further action.

If the remedy results in consequential hazardous waste remaining untreated at the site, a long term monitoring program will be instituted. This program will allow the effectiveness of the selected remedy to be monitored. This long term monitoring program will be a component of the operations and maintenance for the site, if appropriate.

### New York State Department of Health Acceptance

The New York State Department of Health concurs with the remedy selected for this site as being protective of human health.

#### **Declaration**

The selected remedy is protective of human health and the environment, complies with State and Federal requirements that are legally applicable or relevant and appropriate to the remedial action to the extent practicable, and is cost effective. This remedy utilizes permanent solutions and alternative treatment or resource recovery technologies, to the maximum extent practicable, and satisfies the preference for remedies that reduce toxicity, mobility, or volume as a principal element.

March 22, 1994
Date

Deputy Commissioner

### TABLE OF CONTENTS

SECTIO	N		PAGE
1.	Site	Location and Description	1
		History	1
	2.1	Operational/Disposal History	1
	2.2	Remedial History	1
	2.3	Interim Remedial Measure	1
3.	Curre	ent Status	2
	3.1	Summary of Remedial Investigation	2
	3.2	Summary of Human Exposure Pathways	3
	3.3	Summary of Environmental Exposure Pathways	3
4.	Enfo	rcement Status	3
5.	Summa	ary of the Remediation Goals	3
6.	Summa	ary of the Evaluation of Alternatives	4
	6.1	Description of Remedial Alternatives	4
	6.2	Evaluation of Remedial Alternatives	5
7.	Summa	ary of the Selected Remedy	6
	7.1	Elements of the Selected Remedy	6

#### APPENDICES

Appendix A: Responsiveness Summary

Appendix B: Administrative Record

### RECORD OF DECISION

### **BURROUGHS-UNISYS**

Rochester, Monroe County, New York Site No.8-28-075 March 1994

### SECTION 1: <u>SITE LOCATION AND</u> <u>DESCRIPTION</u>

The Burroughs- Unisys Site is listed on the New York State Registry of Inactive Hazardous Waste Disposal Sites as a class two site. A class 2 designation indicates that the site poses a significant threat to the environment and/or public health and action is required. The New York State Departments of Environmental Conservation (NYSDEC) and Health (NYSDOH) work together to implement remedial programs for sites listed on the registry.

As shown in Figures 1 and 2, the Burroughs-Unisys Site is located at 1227 Ridgeway Avenue, just west of Mt. Read Boulevard. The four acre site contains an active manufacturing facility which produces typewriter ribbons. The site is in a commercial/industrial area, however, residential properties are located approximately ½ mile west along Ridgeway Avenue. The entire area is serviced by public water and sewers provided by Monroe County.

#### SECTION 2: SITE HISTORY

### 2.1: Operational/Disposal History

The Unisys Corporation (formerly Burroughs Corporation) leased the industrial facility from Frank Dimino, Inc. between 1976 and 1987. The facility was utilized to manufacture carbon paper, printer ribbons and other office supply products. In 1987, Unisys sold the manufacturing operation to Nu-Kote International. Presently Nu-Kote conducts similar manufacturing operations at the site. As part of the sale agreement to Nu-Kote, Unisys agreed to conduct an environmental assessment.

The assessment indicated that underground storage tanks at the facility had leaked chemicals into the soils beneath the facility's parking lot, contaminating subsurface soils and shallow groundwater. The five underground tanks were removed in 1986. Analytical results of soil samples collected below the tanks indicated the presence of Isopropyl alcohol (IPA), Methyl Ethyl Ketone (MEK), methanol and toluene (see Table 1 for summary of initial soil concentrations).


#### 2.2: Remedial History


Because of the findings of the environmental assessment and the tank removal, Unisys conducted a groundwater investigation in 1987. The investigation revealed extensive groundwater contamination near the former tank areas (see Table 2 for a summary of initial concentrations). Based on the information, the NYSDEC listed the site on the Registry of Inactive Hazardous Waste Sites.

In 1988, 1989, and 1990 Unisys conducted additional studies to determine the extent and magnitude of the subsurface soil and groundwater contamination. Table 2 shows a summary of the groundwater data collected during that time period. Of interest is that acetone concentrations in both soil and groundwater were not detected during the initial investigations but increased over time. It is speculated that acetone is either a breakdown product of IPA or was unknowingly stored in one of the former underground storage tanks.

### 2.3 Interim Remedial Measure


Acting under a Consent Order negotiated with the NYSDEC, Unisys designed and implemented an Interim Remedial Measure (IRM) at the site.





THIS FIGURE IS BASED ON THE ROCHESTER WEST, N.Y. QUADRANGLE U.S.G.S. TOPOGRAPHIC MAP

UNISYS Corporation						
10011	SITE LOCATION M	AP				
Input Haveyar L.S.S.	BURROUGHS - UNISYS FACILITY, ROCHESTER, N.Y.					
INTEGRATED 105-0 EAST EVAID STREET WAS ORGED, FA 18480 SOLUTIONS, INC.						
1'=2000 SOLUTIONS, INC. FLORE (SIS) 411-143						
J.F.B.	NTH Consultants, Ltd.	Figure: 1				



An IRM is conducted at a site when a source of contamination and/or exposure pathway can be effectively addressed before completion of an RI/FS. The IRM was implemented to mitigate contamination derived from leaking underground storage tanks.

In November 1990, the IRM was implemented and is presently operational. The IRM consists of a Groundwater/Soil Vapor Extraction (GW/SVE) system (see Figure 2). GW/SVE system is designed to remove contaminants from both the groundwater and soil by use of a strong vacuum. The contaminants are withdrawn from a series of extraction wells placed in and around the former underground storage tank area. The extracted waters are then treated biologically prior to release to the local sewer authority. The vapor is released without treatment due to the low concentration of contamination in the vapor phase. The IRM system is still operational and over the last 3 years, the system has removed over 5000 pounds of contamination.

### **SECTION 3: CURRENT STATUS**

Unisys Corporation agreed to initiate a Remedial Investigation/ Feasibility Study (RI/FS) in November 1991 to evaluate the effectiveness of the IRM and to address the potential for contaminant migration off-site.

### 3.1: Summary of the Remedial Investigation

The purpose of the RI was to define the nature and extent of any contamination resulting from previous activities at the site.

The RI was conducted in two phases. The first phase was conducted during the summer of 1992 and the second phase during the spring of 1993. A report entitled Remedial Investigation Report, dated November 1992, Addendum I, dated February 12, 1993 and Addendum II, dated May 3, 1993 has been prepared describing the field activities and findings of the RI in detail. A summary of the RI follows:

The activities performed as part of the RI included background research, a literature review and field investigation activities. The

background review included regulatory history and permit status of the site, well inventory records within a 1-mile radius of the site. ecological information, underground storage tank removal information, on- and off-site utility locations and historic chemical use and waste Field investigative management practices. activities conducted under the RI included monitoring well installation, groundwater sampling, soil boring completion and subsurface soil sampling, IRM system operation and subsequent depth to water measurements, topographic surveying, sanitary and storm sewer sampling and laboratory analysis. The mobility and toxicity of identified chemical compounds were also evaluated and a baseline risk assessment was prepared.

The analytical data obtained from the RI was compared to applicable Standards, Criteria, and Guidance (SCGs) in determining remedial alternatives. Groundwater, drinking water and surface water SCGs identified for the Burroughs-Unisys site were based on NYSDEC Ambient Water Quality Standards and Guidance Values and 10 NYCRR Part 5. For the evaluation and interpretation of soil and sediment analytical results, NYSDEC soil cleanup guidelines for the protection of groundwater, background conditions, and risk-based remediation criteria were used to develop remediation goals for soil.

The remedial investigation noted that the IRM has been effective in remediating the site's groundwater and subsurface soils. As noted in Tables 1 and 2, there has been a significant decrease in the site related compounds. However, residual contamination still exists in isolated pockets, "hot spots", in soil at the top of the bedrock zone (10-15 ft. deep) and the groundwater contamination still exists in the overburden unit in the zone surrounding GM-5 (see Figure 2). Based on the results of the RI, it was concluded that the present IRM system is appropriate to remediate the contamination from the former underground storage tank area. Because of some residual contamination, additional work (a focused Feasibility Study) was necessary to determine how to effectively remainder of the site's the capture contamination.

### 3.2 Summary of Human Exposure Pathways:

The RI included an evaluation of human health risks, both current and probable future scenarios, that are posed by the contamination identified at the site. The health risk assessment evaluates the analytical results from various media (air, soils and groundwater) and identifies how the general public can possibly be exposed to the contamination.

The data from the RI indicated that contaminated soils are present only below the surface. Because the site is paved, little public exposure to these soils would be possible. Contaminated groundwater does exist in the area of GM-5; however, the entire area is serviced by public water supplies from Monroe County and a survey of local property owners indicates no uses of local groundwater. As such, with the implementation of the IRM, there is no present public exposure to site contaminants.

There are some hypothetical future land use scenarios which could cause possible exposure, including subsurface excavation for construction purposes and possible future municipal and industrial uses of groundwater. Although the extent of the residual contamination is limited and the possibility of the use of local groundwater is unlikely, the assessment does indicate the need to complete the remedial action at the site.

### 3.3 <u>Summary of Environmental Exposure</u> Pathways:

The site is located in a highly industrial/commercial setting, which lacks any significant wildlife habitat. Further, the extent of contamination is confined to the soils and groundwater below the surface. As such, there are no significant environmental exposure pathways at risk from the contamination identified at the site.

### SECTION 4: ENFORCEMENT STATUS

The NYSDEC and the Unisys Corporation entered into a Consent Order on February 12, 1990. The Order obligates the Unisys Corporation to implement an IRM and a RI/FS

remedial program. Upon issuance of the Record of Decision the NYSDEC will approach the responsible parties to implement the selected remedy under an Order on Consent.

#### Order on Consent

Date February 12, 1990

Subject
In the matter of Development and Implementation of an Interim Remedial Measure and a Remedial Investigation, Feasibility Study for an Inactive Hazardous Waste Disposal Site, pursuant to Article 27, Title 13 of the Environmental Conservation Law.

Index B8-0262-89-03, Site No. 8-28-075

### SECTION 5: <u>SUMMARY OF THE</u> REMEDIATION GOALS

Goals for the remedial program have been established through the remedy selection process stated in 6NYCRR 375-1.10. These goals are established under the guideline of meeting all Standards, Criteria, and Guidance (SCGs) and protecting human health and the environment.

At a minimum, the remedy selected, through the proper application of scientific and engineering principles, should eliminate or mitigate all significant threats to the public health and to the environment presented by the hazardous waste disposed at the site.

The goals selected for this site are:

- Reduce, control, or eliminate the contamination present within the soils on site.
- Mitigate the impacts of contaminated groundwater to the environment and provide the attainment of SCGs for groundwater to the extent technically practicable.
- Prevent, to the extent practicable, migration of contaminants.

- Provide for attainment of SCGs for soil which is protective of groundwater quality at the limits of the area of concern to the extent technically practicable.
- The Remedial Action Objectives (RAOs) are presented on Table 3.

### SECTION 6: <u>SUMMARY OF THE</u> <u>EVALUATION OF ALTERNATIVES</u>

Potential remedial alternatives for the Burroughs-Unisys site were identified, screened and evaluated in a two phase Feasibility Study. This evaluation is presented in the report entitled Feasibility Study, Burroughs-Unisys Facility, dated August 6, 1993.

The results of the first phase Feasibility Study indicated that the present IRM (groundwater/soil vapor extraction) system is more appropriate to mitigate the remaining site than more traditional remedial measures (e.g., excavation and off-site disposal). As such, the second phase of the Feasibility Study was focused on the existing IRM system and what modifications and/or enhancements to the system would remediate the remaining site contaminants to appropriate SCGs.

### 6.1: Description of Alternatives

The potential remedies are intended to address the contaminated subsurface soils and groundwater.

#### 1. No Action:

The no action alternative is evaluated as a procedural requirement and as a basis for comparison. It requires shutdown of the IRM and the site to remain in a partially remediated state.

This is an unacceptable alternative as the site would remain in its present condition, and human health and the environment would not be adequately protected.

#### 2. Limited Action:

This alternative would include shutdown of the IRM system with long-term periodic monitoring of groundwater.

Present Worth:	\$ 105,000
Capital Cost:	\$ 0
Annual O&M:	\$ 25,000
Time to Implement	5 years

### 3. Continued Operation of the IRM System:

This alternative would involve continued operation of the existing IRM system until SCGs are achieved. The alternative would include quarterly groundwater and monthly IRM system sampling.

Present Worth:	\$ 129,170
Capital Cost:	\$ 0
Annual O&M:	\$ 140;000
Time to Implement	l year

# 4. Cycling of the System and Temporary Hook-Up of Monitoring Wells to the GW/SVE System:

This alternative involves modification to the operation of the present IRM system. It would include continued operation of the IRM with cycling of the various arms of extraction system. The alternative also includes temporary hook-up of existing monitoring wells and more frequent groundwater sampling than Alternative 3.

Present Worth:	\$ 190,600
Capital Cost:	\$ 2,000
Annual O&M:	\$ 200,000
Time to Implement	1 year

### 5. Continued operation of the existing IRM System with enhancements and modifications:

This alternative is similar to alternative # 4 as it includes system cycling and the temporary hook-up of existing monitoring wells. The alternative also includes the installation of three additional extraction wells to capture "pockets" of the residual contamination. These three wells would be screened to remediate the distinct top-of-rock interval. Further, to possibly assist the remediation, air and/or water injection would be evaluated in the design phase.

 Present Worth:
 \$ 199,170

 . Capital Cost:
 \$ 20,000

 Annual O&M:
 \$ 190,000

 Time to Implement
 1 year

### 6.2 Evaluation of Remedial Alternatives

The criteria used to compare the potential remedial alternatives are defined in the regulation that directs the remediation of inactive hazardous waste sites in New York State (6NYCRR Part 375). For each of the criteria, a brief description is provided followed by an evaluation of the alternatives against that criteria and comparative analysis is contained in the Feasibility Study.

The first two evaluation criteria are termed threshold criteria and must be satisfied in order for an alternative to be considered for selection.

1. Compliance with New York State Standards, Criteria, and Guidance (SCGs). Compliance with SCGs addresses whether or not a remedy will meet applicable environmental laws, regulations, standards, and guidance.

The No Action (#1) and Limited Action (#2) alternatives do not meet this criterion because they do not address the site's remaining groundwater contamination. All of the other alternatives meet this criteria.

2. <u>Protection of Human Health and the Environment</u>. This criterion is an overall evaluation of the health and environmental impacts to assess whether each alternative is protective.

The No Action (#1) and Limited Action (#2) alternatives only partially meet this criterion because they do not address the remaining groundwater problems. The remaining alternatives meet this criterion.

The next five "primary balancing criteria" are used to compare the positive and negative aspects of each of the remedial strategies.

3. Short-term Effectiveness. The potential short-term adverse impacts of the remedial action upon the community, the workers, and the environment during the construction and implementation are evaluated. The length of time needed to achieve the remedial objectives is also estimated and compared with the other alternatives.

The No Action (#1) and the Limited Action (#2) altenatives only partially meet the criterion. All of the other alternatives meet this criterion.

4. Long-term Effectiveness and Permanence. This criterion evaluates the long-term effectiveness of alternatives after implementation of the response actions. If wastes or treated residuals remain on site after the selected remedy has been implemented, the following items are evaluated: 1) the magnitude of the remaining risks, 2) the adequacy of the controls intended to limit the risk, and 3) the reliability of these controls.

Alternative #5, enhancements /modification, meets this criterion because it adequately addresses the remaining residual contamination. The remaining alternatives do not directly address the residual contamination and only partially address this criterion.

5. Reduction of Toxicity, Mobility or Volume. Preference is given to alternatives that permanently and significantly reduce the toxicity, mobility or volume of the wastes at the site.

All the alternatives address this criterion.

6. Implementability. The technical and administrative feasibility of implementing each alternative is evaluated. Technically, this includes the difficulties associated with the construction, the reliability of the technology, and the ability to monitor the effectiveness of the remedy. Administratively, the availability of the necessary personal and material is evaluated along with potential difficulties in obtaining specific operating approvals, access for construction, etc..

The No Action (#1) and Limited Action (#2) alternatives only partially meet this criterion. The remaining alternatives meet this criterion.

7. Cost. Capital and operation and maintenance costs are estimated for each alternative and compared on a present worth basis. Although cost is the last balancing criterion evaluated, where two or more alternatives have met the requirements of the remaining criterion, cost effectiveness can be used as the basis for the final decision. The costs for each alternative are presented in Table 4.

This final criterion is considered a modifying criterion and is taken into account after evaluating those above. It is focused upon after public comments on the Proposed Remedial Action Plan have been received.

8. Community Acceptance - Concerns of the community regarding the RI/FS reports and the Proposed Remedial Action Plan are evaluated. A "Responsiveness Summary" was prepared that describes public comments received and how the Department addressed the concerns raised. If the final remedy selected had differed significantly from the proposed remedy, notices to the public would have been issued describing the differences and reasons for the changes. It is the position of the Department that comments received during the public comment period do not indicate a need to change the selected remedy (see appendix A).

### SECTION 7: SUMMARY OF THE SELECTED REMEDY

Based upon the results of the RI/FS, and the evaluation presented in Section 7, the NYSDEC has selected Alternative 5 as the remedy for this site. Alternative 5 is enhancement and modification of the existing system which includes installation of additional extraction wells.

This selection is based upon the following:

The No Action alternative (#1) and Limited Action (#2) do not meet the threshold criteria because they don't address the residual soil and groundwater contamination. Utilizing the

existing IRM system (#3) and alternative #4, system cycling, have concerns with their ability to capture the remaining contamination without the installation of additional extraction wells. Alternative #5, enhancements/ modifications, with its additional extraction wells placed in known "hot spot" areas is the most appropriate choice based on the evaluation criteria.

The estimated present worth cost to implement the preferred remedy is \$199,170. The cost to construct the remedy is estimated to be \$20,000 and the estimated average annual operation and maintenance cost for 1 year is \$190,000.

### 7.1 Element of the Selected Remedy:

- 1. Following the signing of the ROD, a remedial design program will be initiated to verify the components of the conceptual design and provide the details necessary for the construction, operation and maintenance, and monitoring of the remedial program. Also any uncertainties identified during the RI/FS will be resolved.
- 2. The proposed remedial action includes the following:
- System with enhancement and modifications to the groundwater/vapor extraction system. These enhancement and modifications include system cycling, evaluation of pulsing of the existing system and an evaluation of either passive air or active water injection to assist mitigation. These modifications will be evaluated in the design phase of the project.
- Temporary GW/SVE connection to existing monitoring wells.
- Installation of three (3) additional extraction wells located at identified pockets of contamination. These wells will be designed to mitigate contamination in the saturated/top-of-rock zone.

It is recognized by the Department that in light of the low permeability of site subsurface soils, that Groundwater Vapor Extraction is an innovative technology that has the potential with modifications and enhancements to achieve the site RAOs. Further, it is recognized that the groundwater unit under the site is not presently utilized for either industrial or potable purposes and because of the low site permeability any future use of the groundwater appears unlikely.

As such, the Groundwater Vapor system (GW/VE) Extraction during the Interim implemented Remedial Measure and conceptually modified in the Detailed Analysis of the Feasibility Study will be designed and operated to remediate source area soils groundwater to the extent The GW/VE technically practicable. system will be modified and/or enhanced and operated for a minimum of one year. After one year, a determination will be made if the system has reached asymptotic conditions with regards to both contaminated vapor and groundwater extractions rates. If the system has reached asymptotic conditions sampling of both the surface soils and groundwater will be conducted to determine if RAOs have been achieved. If either soil or groundwater RAOs are not achieved the system will continue operation and a focused evaluation of further remedial actions will be conducted. The focused study will include an evaluation of no further action.

If the remedy results in consequential hazardous waste remaining untreated at the site, a long term monitoring program will be instituted. This program will allow the effectiveness of the selected remedy to be monitored. This long term monitoring program will be a component of the operations and maintenance for the site, if appropriate.

# TABLE 1 Burroughs-Unisys, Site #828075 Summary of Soil Results (results mg/kg)

### (Source Area (Former UGST Area))

		Sampling Date	
Site Contaminants	11/86	6/92	11/92
Acetone	ND	93	440
IPA	63,080	ND	2,000
MEK	260	18	ND
Toluene	5,100	1	3.3
Methanol	13	2.1	ND

ND - Not Detected
IPA - Isopropyl Alcohol
MEK - Methyl Ethyl Ketone

٠,

#### TABLE 2 Burroughs-Unisys, Site #828075 Summary of Groundwater Results (results in ppm)

### (Source Area Wells (former UGST))

		Sam	pling Date	
Site Contaminants	2/87	6/90	6/91	12/92
Acetone	1,700	1,000	33.4	0.17
IPA	20,000	1,000	36.6	ND
MEK	2,200	120	ND	ND
Toluene	4.2	5.6	ND	0.072
Methanol	NA	NA	ND	ND %
Total VOCs	21,720	2,000	70	0.17

### DOWNGRADIENT (GM - 5)

		Sam	pling Data	
Site Contaminants	11/87	6/90	6/91	12/92
Acetone	0.43	420	54.6	25
IPA	ND	NA	35.2	ND
MEK	ND	8.5	1.5	ND
Toluene	0.27	2.3	0.72	1.2
Methanol	NA	NA	NA	ND
Total VOCs	0.70	431	92.1	26.2

Isopropyl Alcohol IPA -Methy Ethyl Ketone MEK -VOCs -

Volatile Organic Compounds

NA -ND -

Not Analyzed Not Detected

Remedial Action Objectives Burroughs-Unisys, Site #828075 TABLE 3

	, TIOS	Groundwater <sup>2</sup>
SSICs	(IIIB/KB)	(add)
Acetone	0.11	50
IPA	0.11	50
Methanol	0.11	50
MEK	0.23	50
Toluene	1.5	5

SSICs - Site Specific Indicator Compounds IPA - Isopropyl Alcohol MEK - Methyl Ethyl Ketone

<sup>1</sup>Soil RAOs reflect NYSDEC-TAGM-4046," Determination of Soil Clean Up Objectives and Clean Up levels. <sup>2</sup>Groundwater RAOs reflect SCGs, 10NYCRR Part 5 & 6NYCRR Part 700. note:

# TABLE 4 BURROUGHS-UNISYS, SITE NO. 8-28-075 SUMMARY OF COST

Remedial Alternative	Capital Cost \$	Annual O & M \$	Present Worth \$
1 (no action)	0	0	0
2 (limited action)	0	25,000	105,300
3 (existing IRM)	0	140,000	179,170
4 (system cycling)	2,000	200,000	190,600
5 (enhancements)	20,000	190,000	199,170

O & M - Operation and Maintenance

#### APPENDIX A

Burroughs-Unisys
Site #8-28-075
Monroe County
Responsiveness Summary
for
Record of Decision
Public Meeting
February 9, 1994
Marshall High School, Rochester, NY

This Responsiveness Summary responds to oral comments received during the February 9, 1994 public meeting. The public comment period opened on January 25, 1994 and closed on February 28, 1994. Written comments were received and a formal response was forwarded. A summary of this response is also included in the responsiveness summary.

- Q: Are all of the extraction wells pumping from the top-of-rock zone?
- A: The extraction wells installed for the Interim Remedial Measure were placed to the top-of-rock or between 15-20 feet below the surface. The additional extraction wells proposed will be designed to specifically target the top-of-rock zone in areas of remaining residual contamination.
- Q: What are the depths of the proposed additional extraction wells?
- A: The top-of-rock zone is approximately 15-20 feet below the surface. The additional extraction wells will be placed to this approximate depth.
- Q: Is the contaminant plume in the groundwater spreading quickly.
- A: The quick actions of the PRPs to implement an IRM have prevented extensive contaminant migration from the former underground storage tank area. The present Groundwater/Vapor Extraction System (GW/VES) creates a draw down in the groundwater table which prevents contaminant migration. As such, the remaining isolated pockets of contamination are not migrating and because of the continued operation of the GW/VES system. In the Remedial Investigation, downgradient monitoring wells were installed and no significant site related contamination was found. This is an indication of limited contaminant migration.

- Q: This is an exceptional situation because the site is flat and an extensive ridge is just north of the site. Has the prominent ridge north of Ridgeway Avenue affected the plume movement and have you looked for contamination below the ridge.
- A: There is a significant drop in elevation of almost 200 ft just north of the site. This ridge is reported to be the location of a glacial period lake shore line. The ridge does influence the hydrology of the site most noticeable by the drop in the site's bedrock water table from south to north. However, the bedrock monitoring wells both on-site and downgradient show no significant site related contamination. We do not expect an impact on groundwater quality below the ridge.
- Q: What are the concentrations for the Remedial Action Objectives?
- A: Two types of Remedial Action objective were developed for the site. The soil and groundwater goals are in the Proposed Remedial Action Plan as Table 3. They are as follows:

TABLE 3
Remedial Action Objectives
Burroughs-Unisys, Site #828075

SSICs	SOIL¹ (mg/kg)	Groundwater <sup>2</sup> (ppb)
Acetone	0.11	50
IPA	0.11	50
Methanol	0.11	50
MEK	0.23	50
Toluene	1.5	5

SSICs - Site Specific Indicator Compounds

IPA - Isopropyl Alcohol MEK - Methyl Ethyl Ketone

note: <sup>1</sup>Soil RAOs reflect NYSDEC-TAGM-4046," Determination of Soil Clean Up Objectives and Clean Up levels <sup>2</sup>Groundwater RAOs reflect SCGs, 10NYCRR Part 5 & 6NYCRR Part 700.

The following concern was received in writing during the public comment period:

- Q: As the current occupants of the site we are concerned with the progress of the remedial action.
- A: Thank you for your comments on the Proposed Remedial Action Plan for the above referenced site. We understand your concerns for a swift remedial program. The Remedial program outlined in the PRAP will be implemented this summer and is expect to take one year to complete. At the end of one year the site's soils and groundwater will be compared to the clean up objectives. If clean up objectives are met the remediation can be concluded. If the goals are not met additional work may be required.

We have placed your name and address on our site mailing list and will provide you updates of the remedial program through fact sheets and other site mailings. Site related information is also available at the document repository located at Rochester Public Library Ridgeway Avenue.

### APPENDIX B Adminstrative Record

### Burroughs-Unisys, Site #828-075 City of Rochester, Monroe County

- Record of Decision, Burroughs-Unisys, Site # 8-82-075, March 1994.
- Proposed Remedial Action Plan, Burroughs Unisys, Site #8-28-075, January 1994.
- Public Meeting Announcement, Burroughs-Unisys Inactive Hazardous Waste Site, Site #8-27-075, City of Rochester, Monroe County, dated January 24, 1994.
- Public Meeting Announcement, Burroughs-Unisys Inactive Hazardous Waste Site, Site #8-28-075, City of Rochester, Monroe County, dated January 24, 1994.
- Letter to Keith Rapp, Unisys Corporation from David A. Crosby, NYSDEC, subject, Burroughs-Unisys, Site #828075, Monroe Co. Approval of Remedial Investigation-Feasibility Study, dated December 21, 1993.
- Report, Feasibility Study, Burroughs-Unisys Facility, Rochester, New York, Site #828075, prepared by Integrated Environmental Solutions, Inc., dated August 6, 1993.
- Report, Preliminary Screening Document Feasibility Study for Burroughs/Unisys Site Rochester, New York, prepared by Integrated Environmental Solutions, Inc., dated May 3, 1993.
- Report Addendum II Remedial Investigation Report, Burroughs-Unisys Site #828075, Rochester, New York, prepared by Integrated Environmental Solutions Inc., dated May 3, 1993.
- Press release, Public Meeting set on Hazardous Waste Site in Rochester, dated April 14, 1993.
- Fact sheet/meeting announcement, Burroughs Unisys, Site #828075, Rochester, Monroe County, New York, dated April 14, 1993.
- Report, Addendum, Remedial Investigation Report, Burroughs-Unisys Site #828075, prepared by Integrated Environmental Solutions Inc., dated February 12, 1993.

- Report, Addendum, Remedial Investigation Report, Burroughs-Unisys Site #828075, prepared by Integrated Environmental Solutions Inc., dated February 12, 1993.
- Report, Remedial Investigation Report, Burroughs-Unisys Site, Rochester, New York, NYSDEC Site No. 828075, Volumes 1 through 17, prepared by Unisys Corporation, dated November 2, 1992.
- Letter to Kevin Earley, Unisys Corporation from David A. Crosby, NYSDEC, subject, Burroughs-Unisys, Site #828075, Monroe Co.-Removal of IRM System Air Controls, dated October 15, 1991.
- Letter to Mr. Kevin Earley, Unisys Corporation from David Crosby, NYSDEC, subject, Burroughs-Unisys, Site #828075, Monroe Co., Approval of RI/FS work plan, dated October 2, 1991.
- Report, Revised RI/FS Management Plan, Unisys-Nukote Rochester New York, prepared by Bruck, Hartman & Esposito, Inc., dated July 25, 1991.
- Report, Air Control Considerations for the Soil Vapor/Groundwater Extraction Process at the Unisys/Nu-Kote International Site in Rochester, New York, prepared by Environmental Standards, Inc., dated July 9, 1991.
- Fact Sheet, Burroughs-Unisys, Site #828075, Monroe County, dated March 22, 1991.
- Letter to Kevin Earley, Unisys Corporation from David A. Crosby, subject, Burroughs-Unisys, Site #828075, Monroe County-Approval of the Interim Remedial Measures Work Plan, dated December 7, 1990.
- Letter to Kevin Earley, Unisys Corporation from Michael B. Schifano, Monroe County Department of Public Works, subject, Discharge Conditions Nu-Kote/Unisys Facility, dated October 25, 1990.
- Report, The Soil Gas Survey and Soil Borings Analytical Analysis for Nu-Kote International Facility, prepared by Hydro Soil Tech, Inc., dated April 26, 1990.
- Order on Consent, Index #B8-0262-89-03, Site #828075, in the matter of the Development and Implementation of an Interim Remedial Measure and a Remedial Investigation/Feasibility Study for an Inactive Hazardous Waste Disposal Site Pursuant to Article 27, Title 13 of the Environmental Conservation Law of the State of New York by Unisys Corporation, Respondent, dated February 12, 1990.

- Memorandum, to David Markell, Director, DEE from Michael O'Toole, Director, DHWR, Sub: Referral of Burroughs-Unisys Site, dated March 17, 1989.
- Memorandum, to Michael O'Toole, Director, DHWR from Mike Khalil, Regional Hazardous Waste Remediation Engineer, Sub: Referral of Burroughs-Unisys to Division of Environmental Enforcement, dated February 23, 1989.
- Letter, to Unisys Corporation form Kernan Davis, Acting Director, Bureau of Hazardous Site Control, DHWR, NYSDEC, Subject Notice of Site Inclusion on the Registry of Inactive Hazardous Waste Disposal Sites, January 17, 1989.

wp51/a:appendix.bur