mitigation tech

vapor intrusion specialists

INSPECTION REPORT

January 18, 2022

Mr. Cody Martin
Project Manager
C & S Companies
141 Elm Street, Suite 100
Buffalo, NY 14203
Via email: Cody Martin < cmartin@cscos.com>

Re: Jamestown Container Companies – Buildings 5&6, 65 South Dow St., Falconer, NY Revised Inspection Report for Sub-slab Ventilation System

Note: This report supersedes report dated 11.24.20 in which language (in item #7) indicating degraded test point pressure readings was inadvertently copied from a previous report

For work completed November 22, 2021

- 1. Conducted a visual inspection of the complete System (e.g., vent fan, piping, warning device, labeling on systems, etc.): **SATISFACTORY**
- 2. Conducted an inspection of all surfaces to which vacuum is applied: SATISFACTORY
- 3. Inspected all components for condition and proper operation: SATISFACTORY
- 4. Identify and repair any leaks: NO LEAKS OBSERVED
- 5. Inspect the exhaust or discharge points to verify that no air intakes have been located nearby: **NO AIR INTAKES WITHIN TEN FEET**
- 6. Conduct an airstream velocity measurement: SATISFACTORY
- 7. Conduct pressure field extension testing (to ensure that the system is maintaining a vacuum beneath the slab sections per CCR dated 10.17.17): **SATISFACTORY**
- 8. Interview an appropriate individual seeking comments and observations regarding the operation of the System: **SATISFACTORY**

Thank you

Nicholas E. Mouganis EPA listing # 15415-I; NEHA ID# 100722 ***mitigationtech.com