

Specialty Materials

Honeywell
20 Peabody Street
Buffalo, NY 14210
716-827-6200

SR [initials]
KE —

██

X

November 29, 2011

Mr. Stanley F. Radon
Senior Engineering Geologist
Division of Solid and Hazardous Materials
New York State Department of Environmental Conservation
270 Michigan Ave.
Buffalo, N.Y. 14203-2999


RE: 2010 and 2011 Annual Soil Management Report

Dear Mr. Radon:

Attached you will find the 2010 and 2011 Annual Soil Management Report for Honeywell's Buffalo Research Laboratory. I have decided to combine both and get this on a more normal cycle of reporting at the end of each year.

If you have any questions or if you need additional information please call me at (716) 827-6318 or (716) 491-4977 (cell).

Sincerely,



Lana L. Dole
Health, Safety, and Environmental Leader
Honeywell International Inc., Buffalo Research Laboratory

ENCL
Cc: File

**Honeywell Buffalo Research Laboratory
2010 and 2011 Annual Soil Management Report**

There was one event that occurred in 2010 that required the implementation of our Soil Management Plan. It was related to 5/10 construction of a loading pad in a regulated area. This soil was redistributed on site, due to the low levels of contamination.

There was also only one event in 2011 related to excavation for drainage work between 513 and 514/516. The soil was sent off site as non-regulated waste.

As per our policy, contractors were trained in Arsenic Awareness, prior to starting this project.