

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 95.10.01

Site Name: Love Canal	Class: 4	Number: 932020
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party		
O&M Information:    December 1979    End: Continuing    Annual Cost: Unknown <input type="checkbox"/> Estimated		
Interim Remedial Measures/Operable Units in O&M Phase:		
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal
<input checked="" type="checkbox"/> Cap/Cover	<input checked="" type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security
<input type="checkbox"/> Groundwater Recovery/Treatment	<input checked="" type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System
<input type="checkbox"/> Other:		
Institutional Controls: <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling		
<input type="checkbox"/> Other: Consent Decree. Niagara Falls Dep't of Water Facilities. Niagara County Dep't of Health.		
O&M Review Information:		
Reports: <u>Quarterly RP Discharge Monitoring. 11/30/97, 2/28/98, 5/30/98, and 8/31/98. Effluent in compliance.</u>		
Inspection: <u>June 10 and June 11, 1998 of the Leachate Treatment Facility.</u>		
Sampling: <u>June 10 and June 11, 1998 split sampling of five monitoring wells with the RP.</u>		
Other:		
Conclusions:		
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: _____		
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: _____		
Other: _____		
Recommendations:		
_____		
_____		
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:		
Comments: <u>Corrective actions as determined by the M2P2 inspection on 7/23/98 have been implemented.</u>		
<u>Leachate continues to be collected, pumped and treated to maintain inward gradients. Analytical results from the</u>		
<u>Department's groundwater splits grabbed on 6/10 and 6/11 were non-detect. Miller Springs formerly Glenn Springs Holdings</u>		
<u>Inc. operates and maintains the site effectively. The double diaphragm air driven pumps in the leachate treatment room have</u>		
<u>been replaced with variable speed centrifugal pumps.</u>		
Project Manager: <u>Brian P. Sadowski</u>		Reviewer: <u>ABUL BARKAT</u>
Signature: <u>Brian P. Sadowski</u> Date: <u>10/16/98</u>		Signature: <u>Daniel King</u> Date: <u>10/16/98</u>
Name: <u>Brian P. Sadowski</u>	Region or Bureau: <u>9</u>	Telephone: <u>716-851-7220</u>
Name: <u>Daniel King</u>	Region or Bureau: <u>9</u>	Telephone: <u>716-851-7220</u>