ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES IN THE STATE OF NEW YORK

PRELIMINARY SITE ASSESSMENT TASK 1

Walmore Road - Johnson Property Site Site Number 932101 Town of Wheatfield, Niagara County

October 1991



Prepared for:

New York State Department of Environmental Conservation

50 Wolf Road, Albany, New York 12233 Thomas C. Jorling, Commissioner

Division of Hazardous Waste Remediation

Michael J. O'Toole, Jr., P.E., Director

Prepared by:

Ecology and Environment Engineering, P.C.

ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES IN THE STATE OF NEW YORK

PRELIMINARY SITE ASSESSMENT TASK 1

Walmore Road - Johnson Property Site Site Number 932101 Town of Wheatfield, Niagara County

October 1991

Prepared for:

New York State Department of Environmental Conservation

50 Wolf Road, Albany, New York 12233

Thomas C. Jorling, Commissioner

Division of Hazardous Waste Remediation Michael J. O'Toole, Jr., P.E., Director

Prepared by:



TABLE OF CONTENTS

Section		Page
1	EXECUTIVE SUMMARY	1-1
	1.1 ADDITIONS/CHANGES TO REGISTRY OF INACTIVE HAZARDOUS WASTE DISPOSAL SITES	1-10
2	PURPOSE	2-1
3	SCOPE OF WORK	3-1
4	SITE ASSESSMENT	4-1
	4.1 SITE HISTORY	4-1
	4.2 SITE TOPOGRAPHY	4-3
	4.3 SITE HYDROLOGY	4-4
	4.4 CONTAMINATION ASSESSMENT	4-7
5	ASSESSMENT OF DATA ADEQUACY AND RECOMMENDATIONS	5-1
	5.1 HAZARDOUS WASTE DEPOSITION	5-1
	5.2 SIGNIFICANT THREAT DETERMINATION	5-1
	5.3 RECOMMENDATIONS	5-2

Table of Contents (Cont.)

<u>Appendix</u>		
Α	REFERENCES	A-1
В	SITE INSPECTION REPORT (EPA FORM 2070-13)	B-1
С	INTERVIEW DOCUMENTATION FORMS	C-1

LIST OF TABLES

<u>Table</u>		<u>Page</u>
3-1	Sources Contacted for the NYSDEC PSA Investigation, Walmore Road-Johnson Property Site	3-3

LIST OF ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
1-1	Location Map, Walmore Road-Johnson Property Site	1-4
1-2	Site Map, Walmore Road-Johnson Property Site	1-5
1-3	Photographic Logs	1-6

1. EXECUTIVE SUMMARY

The Walmore Road-Johnson Property site (Site I.D. No. 932101) is located on Walmore Road in the Town of Wheatfield, Niagara County, New York (see Figures 1-1, 1-2, and 1-3). The site is now part of a 2- to 3-acre privately owned parcel of gently sloping land bordered by Cayuga Creek. The site (approximately 2 acres) received industrial waste for use as fill. Dates of landfilling are uncertain. Aerial photographs from 1968 show landfilling was occurring at that time (Ref. 18). The New York State Department of Environmental Conservation (NYSDEC) reported that the fill material consisted of heat-treating salt (caustic), plastic tank sludge, fly ash, and scrap wood generated by Bell Aerospace Textron Corporation (Bell Aerospace) (Ref. 2). Information obtained from the Bell Aerospace Right-to-Know Report showed wastes including PCB waste, solvents, sulfuric acid, nitric acid plating solution, and dimethylhydrazine were also generated (Ref. 16). Bell Aerospace's current manifest system, which would have tracked the composition and transfer of this material, was not in place until 1981 (Ref.10). It is likely that similar wastes were produced prior to 1981. As the disposal locations of these materials are unknown, it is possible that the Walmore Road - Johnson Property Site received some of these wastes. The NYSDEC Phase I investigation of the Walmore Road-Johnson Property site completed in June 1989 by E & E (Ref. 1) and the file search performed for this assessment did not discover any evidence of Bell Aerospace's involvement at this site.

1-1

There has been a significant amount of confusion regarding the alleged waste disposal at this site. Originally, the Walmore Road site was believed to be about 1,200 feet north of the present location of the Johnson property, which was later renamed Lockport Road Struzik Property site No. 932094 (Refs. 4 and 16). In the 1987 Registry of Inactive Hazardous Waste Disposal Sites, another site code, No. 932101, was given for the Walmore Road-Johnson property site. The main basis for listing the site was probably the complaint by the owner, Dean Johnson. Mr. Johnson, however, did not provide documented evidence of the waste disposal at the site other than his complaint about the alleged disposal by Haseley Trucking of wastes from Bell Aerospace Textron.

On May 2, 1991, Ecology and Environment Engineering, P.C. (E & E), conducted a site inspection in support of a Preliminary Site Assessment (PSA). The site inspection consisted of a visual survey of the property to evaluate overall site conditions and inspect filled areas.

An inspection of available state, federal, municipal, and private files was carried out and individuals knowledgeable of the site were contacted as part of the overall investigation.

According to the owner, T. Dean Johnson, the fill contents included graphite, hardened resin, crushed plastic battery cases, and similar materials (Ref. 1). There is little visible evidence of fill materials at this site; no effects from the fill materials on nearby residents or the environment have been reported. Additional attempts to contact Mr. Johnson to verify materials disposed of were not successful. No special capping or cover was used on the fill. The precise amount of fill deposited at the site is unknown. A 1968 aerial photograph shows landfilling activities occurring in an area which includes the front of the adjacent property to the south (Ref. 18). A well on the adjacent property, 6381 Walmore Road, was sampled in 1985, apparently because of potential migration of pollutants from previous sludge landfilling operations on the Air Force Base across the road. The sample was tested for bacteria and found positive, although NCDOH considers this result to be incidental for the

02:3424-11/03/92-D1 1-2


Niagara Falls area (Ref. 1, 7). A water line installed through the fill in 1980 corroded within 5 years (Ref. 8). Following this failure, Mr. Johnson asked the Niagara County Department of Health (NCDOH) to investigate. NCDOH inspected the site in 1984, taking a water sample from an on-site irrigation well. This was the only analysis completed for the site (Ref. 4).

Sherwood Herman of the Wheatfield Water District reported that the main water line along Walmore Road is made of asbestos concrete and that the original water line at 6373 Walmore Road was made of copper. He indicated that no other customers along Walmore Road have had corrosion problems. The water sample taken by NCDOH in 1984 from the irrigation well located upgradient of the fill was tested for halogenated hydrocarbons and metals. No contaminants were detected (Ref. 5). The evidence (corroded water line) suggests that corrosive fill was deposited at the site. This fill may have a pH lower than 2 and would then, by definition, be classified as a hazardous waste. NYSDEC's Registry of Inactive Hazardous Waste Disposal Sites reported that caustic was deposited on site, however no other documentation of actual hazardous waste disposal exists. Therefore, insufficient information exists to reclassify the Walmore Road-Johnson Property site.

Presently, insufficient data exist to accurately characterize the nature of the fill. There are currently no surface soil or fill sample data available for the Walmore Road-Johnson Property site. Area residents rely mainly on municipal surface water supplies for drinking water. Groundwater is used as a drinking water source on the Tuscarora Indian Reservation located approximately 3 miles north of the site.

It is recommended that NYSDEC perform a screening program consisting of several soil and groundwater samples collected from the fill area at a depth of at least 5 feet.





SOURCE: USGS 7.5 Minute Series (Topographic) Quadrangles, Tonawanda West, N.Y. 1980; Ransomville, N.Y. 1980




Figure 1-1
LOCATION MAP, WALMORE ROAD-JOHNSON PROPERTY SITE





FIGURE 1-3 PHOTOGRAPHIC LOGS

ecology and environment engineering, p.c. PHOTOGRAPHIC RECORD					
Client:	NYSDEC		E & E Job No.: SB5360		
Site:	: ✓ Walmore Road-Johnson Property				
Camera:	Make	Kodak 35mm	SN Disposable		
	Lens Type		SN		
			Photographer: Scott Glinski Date: 5/10/91		
			Time: 2:30 p.m. Frame No.: 1		
			Comments*: Eastern bank of Cayuga Creek shows		
			exposed debris.		
			*Comments to include location.		



ecology and environment engineering, p.c. PHOTOGRAPHIC RECORD				
Client:	NYSDEC		E & E Job No.: SB5360	
Site: /	Walmore Road	d-Johnson Property		
Camera:	Make	Kodak 35mm	SN Disposable	
	Lens Type	-	sn	
			Photographer: Scott Glinski Date: 5/10/91	
			Time: 2:32 p.m. Frame No.: 2	
			Comments*: Walmore Road drainage pipe emptying	
			into Cayuga Creek. Pipe runs partially through fill area.	
			No discharge, distressed vegetation noted in pipe area.	
			*Comments to include location.	



ecology and environment engineering, p.c. PHOTOGRAPHIC RECORD				
Client:	NYSDEC		E & E Job No.: SB5360	
Site:	Walmore Roa	d-Johnson Property		
Camera:	Make	Kodak 35mm	SN Disposable	
	Lens Type		SN	
			Photographer: Scott Glinski Date: 5/10/91	
			Time: 2:40 p.m. Frame No.: 3	
			Comments*: Chicken-wired rock drainage area along	
	eastern creek bank, irrigation well sampled		eastern creek bank, irrigation well sampled in 1984, and	
			orchard.	
		•		
			*Comments to include location.	



47-15-25 (11/90)-9d

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION OF HAZARDOUS WASTE REMEDIATION

Original - BHSC Copy - REGION Copy - DEE Copy - DOH

ADDITIONS/CHANGES TO REGISTRY OF INACTIVE HAZARDOUS WASTE DISPOSAL SITES Copy - PREPARER				
1. Site Name Walmore Road-Johnson Property	2. Site Number 932101	3. Town Wheatfield	4. County Niagara	
5. Region 6. Classification 9 Current 2a	/Proposed	7. Activity [] Add [] Reclassify	[] Delist [] Modi	fy
8a. Describe location of site (attach USGS topographic r		terrore and the second		
b. Quadrangle <u>Ransomville and Tonawanda West</u>	c. Site latitude 43° 06' 5	8* N Longitude 78° 55' 25* W	d. Tax Map Num	ber <u>147.00</u>
9a. Briefly describe the site (attach site plan showing di Bell Aerospace Textron used this site to dispose of h		stic tank sludge, fly ash, scrapwood,	and clay.	
b. Area ~2 acres c. EPA ID num	ber NYD000514463	d. PA/SI [X] Yes	[] No	
e. Completed: [X] Phase I [] Phase II	[X] PSA [] Sampli	ing		
10. Briefly list the type and quantity of the hazardous w	aste and the dates that it was	disposed of at this site.		
Waste disposal is not well documented. Materials w dimethylhydrazine, heat-treating salt (caustic), plasti	•			plating solution,
11a. Summarized sampling data attached				
[] Air [X] Groundwater []	Surface Water []	Soil [] Waste	[] EP Tox	[] TCLP
b. List contravened parameters and values.				
None. No new sampling done for this report.				
12. Site impact data				
a. Nearest surface water: Distance 0	ft. Direction <u>north</u>	Classification	С	
b. Nearest groundwater: Depth 6	ft. Flow direction southwe	est [] Sole source	[] Primary	[] Principal
c. Nearest water supply: Distance 15,000	ft. Direction <u>north</u>	Active [X] Yes	[] No	j
d. Nearest building: Distance adjacent D	rectioneast	Use residential		
e. Crops/livestock on site? [X] Yes [] No	j. Within a State Econo	omic Development Zone?	[] Yes	[X] No
f. Exposed hazardous waste? [] Yes [X] No	k. For Class 2A: Co	de	Health model score	
g. Controlled site access? [] Yes [X] No	l. For Class 2: Pri	ority category		
h. Documented fish or wildlife mortality? [] Yes [X] No	m. HRS Score NA			
i. Impact on special status fish or wildlife resource? [] Yes [X] No	n. Significant threat	[] Yes [[] No [X] Unknown
13. Site owner's name	14. Address		15. Telephone Nu	mber
T. Dean Johnson	4169 Purdy Road, Lo	ckport, New York	Not available	
16. Preparer	P1	noine and R.C.		
Scott Glinski, Land Use Planner Ecology and Environment Engineering, P.C. Name, title, and organization				
5/12/91 John	shire H. Bu		t Glins	ki_
Date /	Signature			
17. Approved				
	Name, title, and or	rganization		,
Date	Signature	.		

2. PURPOSE

Task 1 of the PSA, Data Records Search and Assessment, was conducted by E & E under contract to the NYSDEC Superfund Standby Contract (Contract No. D002625). Task 1 involves the search for proof of disposal of hazardous waste documentation and proof of a significant threat to human health or the environment. Additional investigation may also be recommended.

The purpose of the PSA is to provide the information for NYSDEC to reclassify the site according to the following classifications:

- Class 2. Significant threat to the public health or the environment--action required;
- Class 3. No significant threat to the public health or the environment--action may be deferred; and
- Delist. Site has been delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

The Walmore Road-Johnson Property site is currently classified as 2a (and not the above classifications) because there is insufficient information to document hazardous waste disposal and/or assess the significance of potential risks to public health or the environment.

3. SCOPE OF WORK

Task 1 of the PSA of the Walmore Road-Johnson Property comprised several interrelated tasks as follows:

File Reviews and Data Search

An extensive data search was conducted utilizing state, county, municipal, and site-specific sources. This information was compiled from existing data as well as new sources, and a preliminary characterization of the site was developed after review.

Sources contacted during the PSA are listed in Table 3-1.

Site Inspection

A site inspection was conducted on May 2, 1991 to assess the surface characterization of the site and vicinity, observe evidence, if any, of hazardous substances or wastes present, photograph the site, conduct preliminary air monitoring using a photoionization detector (HNu) and a radiation meter, and confirm information obtained from the initial data search. A Site Inspection Report (EPA Form 2070-13) form and the NYSDEC Additions/Changes to the Registry of Inactive Hazardous Waste Disposal Sites form were completed following the site inspection. At the time of the inspection there was little evidence of waste disposal. No leachate was observed during the inspection, and no readings above background levels were noted on any instruments.

The site inspection was conducted by the following personnel:

<u>Name</u>	<u>Title</u>	<u>Affiliation</u>
Scott Glinski	Land Use Planner	E & E
Linda Fischer	Environmental Analyst	E & E
Abul Barkat	Engineer	NYSDEC

Approaching the site from the north, gabions (rock and stones retained by wire) were observed on the south bank of Cayuga Creek, approximately 30 yards from the road. No signs of stressed vegetation or discolored, milky, or sheened water was observed along or in the creek for the length of the property.

There were no visible signs of stained ground or stressed vegetation around a pipe for drainage off Walmore Road into Cayuga Creek. The fill area was level and covered with a layer of topsoil and healthy grass. Vegetation in the creek bed was lush and unstressed.

Table 3-1

SOURCES CONTACTED FOR THE NYSDEC PSA INVESTIGATION WALMORE ROAD-JOHNSON PROPERTY SITE

New York State Department of Environmental Conservation

Bureau of Hazardous Site Control

50 Wolf Road

Albany, New York 12233

Contact: Mike Ryan and Jane Thapa

Telephone: 518/457-9538 Date: April 3 and 4, 1989

Information Gathered: File search for additional data and NYSDEC Phase I

reports.

New York State Department of Environmental Conservation

Division of Regulatory Affairs 600 Delaware Avenue Buffalo, New York 14202

Contact: Martin L. Doster Telephone: 716/847-4585

Date: April 3, 1990

Information Gathered: File search.

New York State Department of Environmental Conservation

584 Delaware Avenue Buffalo, New York 14202 Contact: Yavuz Erk

Telephone: 716/847-4585 Date: April 22, 1991

Information Gathered: File search.

New York State Department of Health Bureau of Environmental Exposure

2 University Place

Room 205

Albany, New York 12203 Contact: Andy Carlson Telephone: 518/458-6306 Date: April 16 and 17, 1991

Information Gathered: File information.

New York State Department of Health

Regional Toxic Program Office

584 Delaware Avenue Buffalo, New York 14202 Contact: Cameron O'Connor Telephone: 716/847-4365

Date: April 22, 1991

Information Gathered: File search.

Table 3-1

SOURCES CONTACTED FOR THE NYSDEC PSA INVESTIGATION WALMORE ROAD-JOHNSON PROPERTY SITE

Niagara County Department of Health

10th and Falls Streets

Niagara Falls, New York 14302

Contact: Paul Dicky

Telephone: 716/284-3128

Date: April 2, 1990

Information Gathered: Information about files pertaining to NYSDEC sites.

Niagara County Department of Planning

County Office Building Lockport, New York 14094

Contact: Theodore Billing, Rich Seekins

Telephone: 716/439-6033 Date: April 25, 1991

Information Gathered: U.S. Census of Population 1990 data, other

demographic data.

Niagara County Environmental Management Council

County Courthouse Building Lockport, New York 14094 Contact: Joann Ellsworth Telephone: 716/439-6170 Date: April 25, 1991

Information Gathered: Area floodplain, wetland, land use, zoning public/private

water systems.

Niagara County Highway Department

225 South Niagara Street Lockport, New York 14094 Contact: Gary Hinton Telephone: 716/439-6066 Date: April 29, 1991

Information Gathered: Aerial photographs.

Niagara County Real Property Tax Services

Tax Mapping Division County Courthouse Building Lockport, New York 14094 Contact: Hazel M. Hasely Telephone: 716/439-6111 Date: April 25, 1991

Information Gathered: Tax, ownership, tax map data.

Table 3-1

SOURCES CONTACTED FOR THE NYSDEC PSA INVESTIGATION WALMORE ROAD-JOHNSON PROPERTY SITE

USDA Soil Conservation Service Cornell Cooperative Extension 4487 Lake Avenue Lockport, New York 14094

Contact: Darcy Tone

Telephone: 716/434-4949 Date: April 26, 1991

Information Gathered: Soil survey, agriculture districts and prime farmland,

aerial photos.

4. SITE ASSESSMENT

4.1 SITE HISTORY

The Walmore Road-Johnson Property site is a landfilled area located on residential property at 6373 Walmore Road, Town of Wheatfield, Niagara County, New York. A private residence is located on the property, adjacent to the filled area. This residence was converted from a barn in 1979 to 1980 by property owner T. Dean Johnson.

Some time before this barn conversion, landfilling of industrial materials occurred in an approximately 2-acre area north, south, and west of the barn. A 1968 aerial photograph shows an extensive area of landfilling which includes the front yard of the adjacent house to the south (Ref. 18). The depth of fill measured 5 feet in certain areas (Ref. 4).

The NYSDEC Registry of Inactive Hazardous Waste Disposal Sites shows that Bell Aerospace used this site for disposal of heat-treating salt, plastic tank sludge, fly ash, scrapwood, and clay (Ref. 2). Information obtained from the Bell Aerospace Right-to-Know Report showed wastes including PCB waste, solvents, sulfuric acid, nitric acid plating solution, and dimethylhydrazine were also generated (Ref. 16). Bell Aerospace's current manifest system, which would have tracked the composition and transfer of this material, was not in place until 1981 (Ref. 10). It is likely that similar wastes were produced prior to 1981. As the disposal locations of these materials are unknown, it is possible that the Walmore Road - Johnson Property Site received some of these wastes. The NYSDEC Phase I investigation of the Walmore Road-Johnson

Property site completed in June 1989 by E & E (Ref. 1) and the file search performed for this assessment did not discover any evidence of Bell Aerospace's involvement at this site.

T. Dean Johnson reported that the fill received consisted of graphite, hardened resins, and crushed plastic battery cases, and was delivered to the site by Haseley Trucking Company (Ref. 1). When interviewed in 1989, the trucking company representative reported no knowledge of the contents or source of the fill (Ref. 1).

There has been a significant amount of confusion regarding the alleged waste disposal at this site. Originally, the Walmore Road site was believed to be about 1,200 feet north of the present location of the Johnson property, which was later renamed Lockport Road Struzik Property site No. 932094 (Refs. 4 and 16). In the 1987 Registry of Inactive Hazardous Waste Disposal Sites, another site code, No. 932101, was given for the Walmore Road-Johnson property site. The main basis for listing the site was probably the complaint by the owner, Dean Johnson. Mr. Johnson, however, did not provide documented evidence of the waste disposal at the site other than his complaint about the alleged disposal by Haseley Trucking of wastes from Bell Aerospace Textron (Ref. 1).

At the time of the barn conversion, 1979 to 1980, a water line and septic tank were installed to service the residence. The water line ran from the residence to a Town of Wheatfield asbestos concrete, 10-inch water main along Walmore Road. In 1984 the property owner noticed a loss of water pressure at the residence. Upon excavation the copper line was found to be corroded, and was subsequently replaced by a PVC water line (Ref. 1). No water pressure problems have been reported by the property owner to NCDOH since this new water line was installed. The Wheatfield water district reports no other customer complaints along Walmore Road due to corrosion.

In 1984 the property owner asked NCDOH inspectors to inspect the filled areas of the property. As part of the investigation a water sample was taken from a 13-foot-deep dug well located 100 feet northeast of the residence

02:3424-11/03/92-D1 4-2

and upgradient of the fill area. Analysis conducted by NYSDEC for total, halogenated organics, lead, chromium, and cadmium found no contaminants (Ref. 1).

Further investigation of the site is required to accurately assess overall health and environmental impacts. Site ownership has not changed, no remedial action has been taken, nor have any significant environmental or health effects, leachate outbreaks, or fishkills been noted at the site.

4.2 SITE TOPOGRAPHY

The Walmore Road-Johnson Property site consists of approximately 2 to 3 acres and is located on a nearly flat land parcel on the southern bank of Cayuga Creek between the Consolidated Railroad Corporation (Conrail) railroad tracks and Walmore Road. The topography of the regional area, a lacustrine plain, is essentially flat at an elevation of 590 feet (Ref. 15). Cayuga Creek has eroded a channel approximately 5 feet deep, and the Conrail tracks are elevated approximately 15 feet by fill. The lacustrine plain slopes upward slightly to the northeast rising 50 feet in 3 miles. The Niagara Escarpment is 3.5 miles to the north, and the Niagara River is 3 miles to the south. The site is on a 100-year floodplain according to FEMA flood insurance map #36051300018 (Ref. 3).

The site is located in the Town of Wheatfield in an area of diverse land uses. An international airport and United States Air Force base are located 0.5 mile southwest of the site. A commercial auto service business is located approximately 0.5 mile north of the site and a train embankment traverses the rear of the property in a southerly direction. A small fruit orchard (20 trees) and three residences are found in the immediate site vicinity. Cayuga Creek transects the Johnson property on Walmore Road and marks the northern edge of the landfilled area. There are no known critical habitats in the vicinity of the site (Ref. 1). All residents in this area of the Town of Wheatfield use water from public systems for drinking.

4.3 SITE HYDROLOGY

Niagara County lies within the Central Lowland physiographic province. Specifically, it lies in the Eastern Lake section and occupies part of the Huron and Ontario plains (Ref. 14).

This area, known as the Niagara Frontier, is relatively flat and broken by two east-west trending escarpments: the Niagara Escarpment and the Onondaga Escarpment. The site lies on the flat area between these escarpments called the Tonawanda Plain. This was the site of the postglacial Lake Tonawanda (Ref. 13).

Sediments in this area consist mainly of lacustrine deposits and glacial tills. The lacustrine deposits (i.e., silts and clays that settled to the bottom of the postglacial lake) are generally olive and brownish sediments overlying a red clay. The olive and brownish lacustrine sediments were deposited in glacial Lake Tonawanda following the Wisconsin Ice Age. These sediments blanket a red clay that was deposited following an earlier ice age in glacial Lake Lundy that at one time covered the entire county. Glacial till also occupies a large part of the surface area in the county and underlies most areas of lake sediments. The glacial till deposits consist of ground moraines, drumlins, eskers, and terminal moraines. Ground moraines occupy the low undulating till plain and are approximately 10 to 15 feet thick. Drumlins are rounded hills of bedrock or till that were molded beneath the ice and are elongated in the direction of ice flow. Drumlins in Niagara County are very subdued due to modification by the glacial lakes. Eskers are thin elongated ridges of pebbly till trending northeastsouthwest. The terminal moraines have a general east-west trend and were formed when the ice stagnated for a long period of time. Other deposits, consisting of glacial outwash and beach deposits, exist in large belts (up to 8 miles in length) and are generally 1 to 10 feet thick (Ref. 13).

Surface drainage of the Ontario Plan is northward into Lake Ontario and soil drainage is relatively poor. Surface drainage of the Huron Plain is southward into Tonawanda Creek and is also not well developed. Surface

02:3424-11/03/92-D1 4-4

drainage of the Tonawanda Plain is predominantly westward or southwestward into the upper Niagara River (Ref. 14).

The lacustrine sediments and glacial till of the Niagara Frontier are underlain by sedimentary rocks varying in thickness between 1,980 to 4,200 feet and are Ordovician, Silurian, and Devonian in age. The lower part of the Ordovician System is composed primarily of limestones and dolostones. The upper part is composed of massive shales, interbedded with thin sandstone layers primarily of the Queenston formation.

The Silurian system is composed of the Medina, Clinton, Lockport, and Salina groups. The Medina group consists of sandstones, shales, and dolostones of the Clinton, which in turn are overlain by the dolostones and limestones of the Lockport group. Above the Lockport are shales, siltstones, and dolostones, and the gypsum, anhydrite, and salt beds of the Salina group. The poorly drained Tonawanda Plain is formed on the weathered surface of the Lockport and Salina groups.

The Devonian system unconformably overlies Silurian rocks to the south of Niagara County. The formation at the Devonian-Silurian contact is the Onondaga limestone, which is a massive cherty limestone that outcrops across most of northern Erie County (Ref. 13).

Niagara County has abundant surface waters bordering it: Tonawanda Creek to the south, the Niagara River to the west, and Lake Ontario to the north. The county's municipal water district draws most of its water from the Niagara River. However, rural residents depend on both bedrock and overburden wells. The bedrock wells north of the Niagara Escarpment are dug or drilled into the Queenston shale. The yields of water are often inadequate during extended dry periods and may contain high levels of salt or sulfate. Bedrock wells to the south of the escarpment are drilled into the Lockport dolomite. Yields are generally higher, but the water typically contains high calcium and other cations. Shallow-dug wells and springs are most often completed in one or more of the three most permeable of the 11 soil associations in Niagara County: the Otisville-Altmar-Fredon-Stafford

association, the Howard-Arkport-Phelps association, and the Hilton-Ovid-Ontario association. The shallow wells are less desirable than bedrock wells due to increasing pollution of shallow groundwater, primarily by seepage and are therefore seldom used (Ref. 14).

Groundwater in the Niagara Falls area occurs in both the unconsolidated deposits and in the bedrock. The bedrock, specifically the Lockport dolomite, is, however, the principal source of groundwater in the Niagara Falls area. Three types of bedrock openings contain the groundwater: bedding joints, vertical joints, and solution cavities.

The bedding joints, which transmit most of the water in the Lockport, and fractures along prominent bedding planes have been widened up to 1/8 inch by solution of the rocks. These joints extend several miles, thus constituting effective water conduits.

The vertical joints are generally too short and sparse to account for significant groundwater storage and transmission, except in the top 10 to 25 feet of bedrock. Solution cavities, formed when gypsum is dissolved, are also not important components of the aquifer. Although they increase the storage capacity of the aquifer, they are isolated and do not contribute to groundwater transmission.

Two distinct sets of groundwater conditions exist in the Lockport dolomite. The first is the upper 10 to 25 feet of the bedrock. This region is highly fractured resulting in moderate permeabilities. In some areas in the region, a confining layer of clay above this zone can produce artesian groundwater conditions. The second class of groundwater conditions is found deeper in the bedrock, where at least seven different permeable zones have been identified. These zones are surrounded by impermeable bedrock, and it is not likely that they are hydraulically connected (Ref. 1). Groundwater flow in bedrock in the vicinity of the site is complex. Groundwater flow direction cannot be accurately determined at this time.

The soils at this site are Schoharie silty clay loam of the Odessa-Lakemont-Ovid association (Ref. 1). These soils are fine-textured and poorly-

02:3424-11/03/92-D1 4-6

drained. The soils are overlain by the industrial fill material at the Walmore Road-Johnson Property site.

The depth to the bedrock is not known at this site. Bedrock was encountered between 11 and 14 feet below ground surface at the nearby Lockport Road - Struzik Property site (Ref. 17). Borings have been made near the Carborundum plant 0.5 mile to the south, along Walmore Road. These borings indicated that the Lockport dolomite bedrock was greater than 15 feet below the surface (Ref. 1).

The well on site is screened in the overburden at a depth of 13 feet. Groundwater was encountered at 6 feet during NCDOH sampling in 1984.

The unconsolidated deposits, in which the on-site well is screened, constitute the aquifer of concern at this site because they are used to irrigate fruit and vegetables grown on site. Fill material is believed to have been placed adjacent to the creek. Water in these deposits is most likely hydraulically connected to Cayuga Creek, which flows through this site. Cayuga Creek, however, is not used for drinking water or recreation. After leaving the Walmore Road-Johnson Property site, the creek is inaccessible as it flows through the Niagara Falls Air Force Base and International Airport.

Boreholes adjacent to the Carborundum plant approximately 0.5 mile to the south revealed lacustrine clay deposits up to 10 feet thick (Ref. 1). These deposits may isolate the aquifer of concern from the deeper regolith and bedrock aquifers. Boring logs from the Lockport Road - Struzik Property site located approximately 0.4 mile to the north show 11 to 14 feet of unconsolidated sediments and glacial till overlying Lockport dolomite bedrock (Ref. 17).

4.4 CONTAMINATION ASSESSMENT

One to 3 acres of the Walmore Road-Johnson Property site received industrial fill measuring 5 feet in depth in certain areas. The exact date and nature of the fill are unknown, although the owner claims that the fill material included graphite, hardened resins, and plastic battery cases (Ref. 1). Other

reported fill material consists of heat-treating salt (caustic), plastic tank sludge, fly ash, and scrap wood (Ref. 2). Filled areas extend from Walmore Road, along the south bank of Cayuga Creek, to the areas north and east of the residence on site. In 1979, a water line was installed but by 1984 was severely corroded (Ref. 1).

In 1984, at the request of the owner, NCDOH sampled a water well on the property and analyzed it for halogenated organic compounds and three metals: lead, cadmium, and chromium. None of these contaminants was found above detection limits (Ref. 4). A well on the adjacent property located to the south, 6381 Walmore Road, was sampled in 1985, apparently because of potential migration of pollutants from previous sludge landfilling operations on the Air Force Base across the road. The sample was tested for bacteria and found positive, although NCDOH suspects this to be of incidental origin (Ref. 1, 7).

No soil sampling has been performed at the Walmore Road-Johnson Property site. Slag was noticed on the surface of alleged fill areas near Cayuga Creek by the E & E inspection team on June 24, 1987, and by Michael Hopkins of NCDOH in 1984.

The site inspection by E & E on May 2, 1991 showed little visible signs of fill materials. The waters of Cayuga Creek in the vicinity of the site showed no visible signs of contamination. A stormwater drainage pipe outlet into Cayuga Creek at the edge of the site showed no signs of discharge or distressed vegetation near it. Air monitoring for organic vapors and radiation sources on the site showed no readings above background levels.

No documentation exists to confirm the disposal of hazardous waste at this site. Evidence suggests that corrosive fill was deposited at the site but this does not constitute proof of hazardous waste disposal. At this time, the site is not considered to pose a significant threat to human health or the environment.

5. ASSESSMENT OF DATA ADEQUACY AND RECOMMENDATIONS

5.1 HAZARDOUS WASTE DEPOSITION

No actual documentation of hazardous waste disposal exists for this site. The NYSDEC Inactive Hazardous Waste Disposal Report lists Bell Aerospace as a reported waste disposer of heat-treating salts (caustic) and plastic tank sludge at the Walmore Road-Johnson Property site. However, this investigation and prior site studies establish no known link between Bell Aerospace and hazardous waste disposal on the site. The property owner claims graphite, hardened resins, and plastic battery cases are included in this fill.

The trucking company that delivered fill to the site, the property owner, and Bell Aerospace have no written record of the fill contents (Refs. 9, 10, 11).

An NCDOH water sample taken in 1984 from a private irrigation well on site did not contain THD, lead, chromium, or cadmium above minimum detection levels (Ref. 6).

5.2 SIGNIFICANT THREAT DETERMINATION

Based on the limited analytical data of selected contaminants from one groundwater sample, it is not known whether a significant threat to humans exists via the groundwater route. Nearby residents receive drinking water primarily from municipal surface water supplies. Groundwater is used for drinking water on the Tuscarora Indian Reservation located approximately 3 miles to the north.

5-1

Cayuga Creek, which borders the site to the north, is inaccessible downstream of the site as it flows through the Niagara Falls International Airport. Downstream of the airport, the creek has been posted as hazardous because of potential contaminant migration from Love Canal and the former Charles Gibson disposal site.

A potential threat to the current residents at 6373 Walmore Road exists should the soil cover be removed exposing the wastes. Evidence suggests that corrosive fill was deposited at the site and may pose a direct contact hazard. The water supply to the residence may also be threatened if the integrity of the PVC water line is lost due to the age or corrosive nature of the fill. However, at this time, the Walmore Road-Johnson Property site is not considered to pose a significant threat to human health or the environment.

5.3 RECOMMENDATIONS

Evidence (corroded water line) suggests that corrosive fill was deposited at the site. This fill may have a pH lower than 2 and would then, by definition, be classified as a hazardous waste. As no documentation of hazardous waste disposal exists, disposal cannot be confirmed and, therefore, insufficient information exists to reclassify the Walmore Road-Johnson Property site.

Presently, insufficient data exist to accurately characterize the nature of the fill. There are currently no surface soil or fill sample data available for the Walmore Road-Johnson Property site.

It is recommended that NYSDEC perform a screening program consisting of several soil and groundwater samples collected from the fill area at a depth of at least 5 feet. These samples should be analyzed for full Target Compound List (TCL) parameters as the composition of the fill material is unknown.

Groundwater samples should be collected from the existing on-site well and the adjacent neighbors' well also for full TCL analysis.

APPENDIX A REFERENCES

REFERENCES

- 1. New York State Department of Environmental Conservation, 1989, Phase I Engineering Investigation, Walmore Road-Johnson Property NYSDEC Site No. 932101.
- New York State Department of Environmental Conservation, 1991, Division of Hazardous Waste Remediation Inactive Hazardous Waste Disposal Report.
- 3. Elsworth, Joann, 1991, Niagara County Environmental Management Council Site information, land use, floodplain, zoning, water lines.
- Hopkins, Michael, Niagara County Department of Health, December 6, 1984, memorandum to Peter Beuchi, New York State Department of Environmental Conservation, Region 9, Buffalo, New York.
- 5. _____, February 15, 1985, personal communication to T. Dean Johnson, 6373 Walmore Road, Wheatfield, New York.
- 6. _____, November 13, 1984, Service Request Form called in to NCDOH by T. Dean Johnson.
- 7. Popovici, Michael, Niagara County Health Department, January 15, 1985, personal communication to James Johnson, 6381 Walmore Road, Niagara Falls, New York.
- 8. Ecology and Environment, Inc., July 6, 1987, personal communication with Debra Johnson, former owner of property at 6381 Walmore Road, with attachments from Advanced Environmental Systems, Inc.
- 9. _____, May 20, 1988, personal communication to Brian Smith, Bell Aerospace Textron, Inc.
- 10. Buzawa, Carl, 1988, Vice President-Division Counsel, Bell Aerospace Textron, personal communication with Ecology and Environment, Inc.

- 11. Haseley, Mark, 1991, personal communication, Owner, Haseley Trucking Company, Wheatfield, New York.
- 12. Tesmer, I.H., 1981, <u>Colossal Cataract</u>, State University of New York Press, Albany, New York.
- 13. United States Department of Agriculture, 1972, <u>Soil Survey of Niagara County</u>, New York, Soil Conservatory Service.
- 14. United States Geological Survey, 1980, 7.5-Minute Series (Topographic), Tonawanda West Quadrangle, United States Department of the Interior.
- 15. Tygert, J., New York State Department of Environmental Conservation, Region 9, September 17, 1986, Memorandum to Mr. Demick, New York State Department of Environmental Conservation, Western Investigation Section.
- 16. Bell Aerospace Textron, 1984, Community Right-to-Know Document, Generator Form, Part II.
- 17. New York State Department of Environmental Conservation, 1992, Engineering Investigations at Inactive Hazardous Waste Disposal Sites in the State of New York, Phase II Investigations, Lockport Road Struzik Property, Town of Wheatfield, Niagara County.
- 18. _____, 1968, Aerial Photograph of Walmore Road Johnson Property Site.

REFERENCE 1

ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES

PHASE I INVESTIGATION

WALMORE ROAD - JOHNSON PROPERTY, SITE NUMBER 932101 TOWN OF WHEATFIELD, NIAGARA COUNTY

June 1989



Prepared for: New York State Department of Environmental Conservation

50 Wolf Road, Albany, New York 12233
Thomas C. Jorling, Commissioner
Division of Hazardous Waste Remediation
Michael J. O'Toole, Jr., P.E., Director

Prepared by: Ecology and Environment Engineering, P.C.

DIVISION OF HAZARDOUS WASTE REMEDIATION INACTIVE HAZARDOUS WASTE DISPOSAL REPORT

CLASSIFICATION CODE: 2a

REGION: 9

SITE CODE: 932101

EPA ID: NYD000514463

NAME OF SITE: Walmore Road - Johnson Property

STREET ADDRESS: 6373 Walmore Road, Wheatfield, NY

TOWN/CITY:

COUNTY:

ZIP:

Wheatfield

Niagara

14304

SITE TYPE: Open Dump- Structure- Lagoon-X Landfill- Treatment Pond-Acres

ESTIMATED SIZE: 2

SITE OWNER/OPERATOR INFORMATION:

CURRENT OWNER NAME....: Mr. Dean Johnson

CURRENT OWNER ADDRESS .: 6373 Walmore Rd., Wheatfield, NY

OWNER(S) DURING USE...: Unknown

OPERATOR DURING USE...:

OPERATOR ADDRESS....:

PERIOD ASSOCIATED WITH HAZARDOUS WASTE: From

To

SITE DESCRIPTION:

Bell Aerospace Textron used this site to dispose of heat treating salt, caustic, plastic tank sludge, fly ash, scrapwood and clay. A Niagara County Health Dept. letter dated February 15, 1985 indicates that a water sample from a private well near the site did not contain THD, lead, chromium, or cadmium above the minimum detection levels. A Phase I investigation was completed in 1989.

HAZARDOUS WASTE DISPOSED: Confirmed-

TYPE

Suspected-X QUANTITY (units)

Heat treating salts - caustic plating

Unknown

---- Stoumwater-A Soll- Sediment-

CONTRAVENTION OF STANDARDS:

Groundwater- Drinking Water- Surface Water-

Air-

LEGAL ACTION:

LIPE..:

State-

Federal-

STATUS:

Negotiation in Progress-

Order Signed-

REMEDIAL ACTION:

NATURE OF ACTION:

Proposed- Under design-

In Progress-

Completed-

GEOTECHNICAL INFORMATION:


SOIL TYPE:


GROUNDWATER DEPTH:


ASSESSMENT OF ENVIRONMENTAL PROBLEMS:

There is limited data on the and groundwater at the site. Further investigation is needed to assess environmental problems.

ASSESSMENT OF HEALTH PROBLEMS:







SONING


A-R- AGRICULTURAL - RESIDENTIAL

R - RESIDENTIAL

R-C RESTRICTED COMMERCIA

C- COMMERCIAL

1- INDUSTRIAL



NIAGARA COUNTY HEALTH DEPARTMENT

MEMQRANDUM

DATE: December 6, 1984

TO:

Peter Buechi

FROM:

Mike Hopkins M. Refli

SUBJECT:

JOHNSON PROPERTY - 6373 WALMORE ROAD, WHEATFIELD, NY

In response to a complaint received from Mr. Dean Johnson of 6373 Walmore Rd., this department has begun an investigation of an apparent inactive disposal site at that address. According to Mr. Johnson, the site was filled with graph that hardened resin, crushed plastic battery cases and similar materials by the Hasely Trucking Company many years ago. The fill is reportedly five feet deep in some areas. An area of one to three acres may be involved. A site sketch is attached.

It seems likely that this site may be the site listed in the Disposal Site Registry as the "Walmore Road Site" which was previously believed to be located 1000 to 1200 feet north of 6373 Walmore Road. It appears likely that two distinct sites are present. The description of the waste materials present at both locations is similar (i.e., mainly graphite).

There is a well on the Johnson property which is used to water fruit trees, etc., but not for drinking water. It would be possible to sample water from this well.

Since it appears that there is evidence that waste materials are present beneath or adjacent to an occupied dwelling, this department recommends that samples be collected and analyzed. This department could collect the samples but does not currently have the resources to have the samples analyzed. We are therefore requesting that your department consider having one or more samples from this site analyzed. At a minimum, we feel that analysis of a well water sample for THO and heavy metals would be appropriate.

If DEC can arrange for analysis of samples from this site, please contact me so that arrangements for sampling can be made.

MEH:cs Attachment

CC:

Mr. M. N. Vaughan

Mr. A. Tyebbi/DEC-9

Mr. Peter Bucchi Dr. Frances Yang F. Y. Analytical Result of a Groundwater Sample from Town of Wheatfield February 11, 1985


A water sample (DEC-91) was submitted for THO and metals analysis on January 7, 1985. The sample was taken from Johnson residence, 9373 Walmore Road, by Niagara County Health Department.

Result:

Sample Designation	THO	Lead	Chronium	Cadmium
DEC-91	n.d.	n.d.	n.d.	n . d .

FY:jlw

cc: it. Mike Hopkins - MCHD



Walmore K.c.

HEALTH C

HEALTH DEPARTMENT
HUMAN RESOURCES BUILDING
MAIN POST-OFFICE BOX 428
10th AND EAST FALLS STREET
NIAGARA FALLS, NEW YORK 14302

February 15, 1985

Mr. Dean Johnson 6373 Walmore Road Niagara Falls, NY 14304

Dear Mr. Johnson:

Attached is a copy of the laboratory report submitted to this department from the Department of Environmental Conservation with the results of the analysis of water from your well. Please note that the Total Halogenated Organics (THO) concentration as well as the concentrations of Lead, Chromium and Cadmium were below detection limits.

Based on these results and considering that the well is not used for drinking water supply, this department sees no reason for concern regarding possible toxic contaminants in the well water. The water should be suitable for its present uses, which I understand to be as irrigation and washwater.

Please feel free to contact me with any questions.

Sincerely,

Michael E. Hopkins Ass't. P.H. Engineer

multil Elkoph

MEH:cs Attachment

cc: Mr. P. Buechi/DEC-9

Mr. J. J. Devald

NIAGARA COUNTY DEPARTMENT OF HEALTH

Code Accivity

Code Location

Service Results No.

,		Service Request No.
erv	rice Requ	west Well Water Dupples / Landfil Concerns
]) _{wn}	i Cit	
_)ccu	ipant	Address 73/-3888
]	· ·	Address
-:e · ••" "7	Hours	REPORT OF INVESTIGATION
11/1	3/84	thater received call from Mr. Deen Johnson who rea
<u> </u>		
1		
1		The steel my silend the dispersion
I		reperty matel to consult of elect the 2.
		surper In vila water brown now only used for watery and
		The state of the s
	·	uspent and well water supply. Told him we would set and
		and examine property and head problem!
		Phone 731-3888 Thur Am to set appointment.
		The state of the s
(0.1)		
39	2-pm	I met with M. Johnson He informed my tit.
-		7
		1) Portions of his property are filled with
	-	muste muterula naturing graphite jurdined rever
		1) Portions of his property are filled with no source materials including graphite, included resums plantin battery cases, ect.
		2) 77 (//)
		2) The filled areas are up to 5 feet Loop.
		Hasely Trucking.
-	_ _	Musely Irucking.
-	_	1) There is a little of
- '		There is a will on the property used for irrigation
		The state of the s

Date Abated A-22

14...



NIAGARA COUNTY

PATRICIA M. POWELL Public Health Director 716-439-6129

HEALTH DEPARTMENT 5467 UPPER MOUNTAIN ROAD LOCKPORT, NEW YORK 14094

January 15, 1985

Mr. James Johnson 6381 Walnows Road Niagara Falls, New York 14304

> Re: Unsafe Private Water Supply 6381 Walmore Road Town of Wheatfield

Dear Mr. Johnson:

On January 8, 1985, Mr. Stimson of this department made a sanitary survey of the well utilized as a source of private water supply for your residence at the above location. During this inspection, a sample of water was collected and submitted to the Niagara County Laboratory for bacterial examination. It is reported that organisms of the coliform group were present at the time of sampling, indicating that the supply was contaminated and unfit for human consumption at the time of sampling.

Inas much as the report of the survey indicates that this well is properly constructed and properly located with respect to known sources of pollution, it is quite possible that the contamination in this supply is of incidental origin. We would, therefore, suggest that this well be thoroughly disinfected in accordance with the enclosed instructions and this office notified so that a new sample may be taken. Until such time as a sanitary survey, confirmed by a bacterial analysis, indicates that this supply is of a safe sanitary quality, all water from it should be boiled before being used for human consumption, or culinary purposes.

Very truly yours,

Michael Popovici Supervisory Public

Health Sanitarian

MP/cg Enclosures



ecology and environment, inc.

195 SUGG ROAD, P.O. BOX D, BUFFALO, NEW YORK 14225, TEL. 716-632-4491, TELEX 91-9183

International Specialists in the Environment

July 6, 1987

Mrs. Debbie Johnson 2 Cranston Street Worcester, MA 01602

Dear Mrs. Johnson:

Thank you for calling last Friday, June 26, 1987 to provide information to Ecology and Environment, Inc. (E & E) concerning the Johnson property on Walmore Road in the Town of Wheatfield. To restate our role, E & E is working under a contract from the New York State Department of Environmental Conservation (DEC) to investigate suspected waste disposal sites in western New York. The Johnson property (specifically 6373 Walmore Road) is on the registry of such sites at the request of the owner, Mr. Dean Johnson, who suspected that industrial wastes may have been used as fill during the development of the property. For future reference, the DEC site code for this property is 932094. Any questions about the site or this investigation should be referred directly to the DEC.

With this letter, we would like to confirm the information you provided us over the telephone. This information is listed in Attachment 1. To provide sufficient documentation of this information, the DEC requires that we ask you to sign this document, acknowledging that the information (with any changes you may note) is correct to the best of your knowledge.

Thank you for your assistance in this investigation.

Sincerely,

Jon Sundquist

Attachment 1

Dean Johnson owns the property at 6373 Walmore Road (converted barn) and 6367 Walmore Rd. (Ranch-style house)

James a DEBRA

> Debbie Johnson owns the property at 6381 Walmore Rd. (2 story farm house)

Debbie Johnson is Dean Johnson's sister-in-law

Debbie Johnson's father-in-law owns the property between EN THE SOUTH 6 - 6381 the railword embankment and Walmore Road

- This land is leased to a farmer named Pfoul

- This farmer has farmed the land since at least 1979

The barn at 6373 Walmore Road was converted to a residence in 1988 APPROX. 1979 + 1980.

- Water line and septic tank installed at that time

- Water line runs from the road to the barn, parallel to the driveway on its north side

The water line had completely corroded and was leaking by 1984

7POSSIBLE - Water line was replaced with PVC piping

- Replacement work performed by Mr. Pete seeger, a PLUMBING IXDRE P licensed plumber *

OUTSIDE- Plumbing at both 6367 and 6381 Walmore Road is in Sure ON REPLACEM accordance with Town water regulations

*ORIGINAL INSTU P SEEBER NOT

WORK OR OUTSING PLUMBING.

A military agency has tested the water in the well on the property AT 6381 WALMORE RD.

- Analytical results were sent to Debbie Johnson

- Military agency indicated they were testing because of a leaking fuel tank and possible buried transformers on the air force base across Walmore Road from the property

MILITARY ANALYTICAL RESULTS ENCLOSED.

ecology and environment recycled paper

ADVANCED ENVIRONMENTAL SYSTEMS, INC.

MONITORING and SUPPORT LABORATORY

Location:


4626 Royal Avenue Niagara Falls, New York

P.O. Box Niagara Falls, N.Y. 14 (716) 28! 3

February 28, 1985



Mr. Dermont Smyth Engineering Office 914 TAC ALFT GP (AFRES) Niagara Falls Intl Aprt Niagara Falls, New York 14304-5320



Dear Mr. Smyth:

The oil and grease calculation I quoted to you over the telephone was in error. When I recalculated, I found the oil and grease to be virtually none. The flask used had actually lost weight, not gained, and I miscalculated it as a positive number.

My sincere apologies for this error.

Very truly yours,

ADVANCED ENVIRONMENTAL SYSTEMS, INC.

Marlene C. Moyer

MCM/mb

This explains we were the sure that some the sure of hore of the sure of the s Marin Chillian

AGALLS OF ONE

WEI IR SAMPLE



Repir spared For

NIAGARA FALLS TICAL AIRLIFT GROUP

·y

ADVANCED ENTRUCTAL SYSTEMS, INC.

Technical Evaluation

February 1, 1985

AES - Report APH

P.O. No.

F30617-85-17-023



SCOPE OF WORK

Under the direction of Mr. Smyth, this wc: s performed to fulfill an analytical requirement for the : ara Falls Tactical Airlift Group Facility.

RECEIPT OF SAMPLE

At 1:15 p.m., on January 7, 1985, Mr. Charl Calvert of Advanced Environmental Systems, Inc. sample he groundwater well at the TAG Facility. Mr. Calvert the rectly transported the sample to the Advanced Environme 1 Systems laboratory.

ON SWEETE HOTOTAN JOR ... SRY MEPORT

MILLIGRAMS/LITER, OR PPM RESULTS - WET CHEMISTRY TYPE OF ANALYSIS: UNITS OF MEASURE:

A.E.S. JOB CODE SAMPLE IDENTIFICATION DETERMINABLE LIMITS CLIENT: NIA AIR BASE REF METHOD ANALYSIS

Irecycled paper

recycled paper

TDS

7/85	WATE	
-	WELL	
		i

1 0.1 5 PPB 5 PPB 0.01		
160.1 3 503A 6 415.1 3 9020 5 9020 5	Dissolved Solids Organic Carbon Ible Cryanic Halidea	Organic Halidea.
TDS DIL & GREASE FOC POX* FOX*	TDS-Total Dissert TOC-Total Organ	10x-10tal

BDL 7.22 BDL 29.2 BDL

324

Results reported in micrograms/liter, or ppb ecology and env

ecology and environment

WET CHEMISTRY DIVISION MARLENE C. MOYER

MICHABE J. SIMESON METALS DIVISION

ADVANCED ENVIRONMENTAL SYSTEMS, INC. LABORATORY REPORT

TYPE OF ANALYSIS: RESULTS - METALS

A.E.S. JOB CODE 01APH UNITS OF MEASURE: MILLIGRAMS/LITER, OR PPM

CLIENT: NIA AIR BASE

METHOD

ANALYSIS

SAMPLE IDENTIFICATION REF

WELL WATER 1/7/85 DETERM INABLE LIMITS

BDL

0.10

239.1

A-32



ecology and environment, inc.

BUFFALO CORPORATE CENTER
368 PLEASANTVIEW DRIVE, LANCASTER, NEW YORK 14086, TEL. 716/684-8060
International Specialists in the Environment

May 20, 1988

Mr. Brian Smith
Bell Aerospace Textron
P.O. Box 1
Buffalo, New York 14240

Dear Mr. Smith:

Thank you for speaking with me last week concerning the suspected waste disposal site at 6373 Walmore Road in Wheatfield. As I mentioned on the telephone, E & E is currently under contract to the DEC to conduct a Phase 1 investigation of this property to determine whether the fill present there poses a threat to human health or the environment. As per our conversation, I am including a copy of the DEC Inactive Hazardous Waste Disposal Site registry form that indicates that the waste may have come from Bell Aerospace. I am also including a copy of the Niagara County Health Department memorandum that initially identified this properly as a site of possible concern.

I am sorry I didn't follow up on our telephone conversation earlier. I had been trying to track down references that indicated that the fill was emplaced in 1980. Unfortunately, no such documentation could be found. Thus, contrary to what I indicated on the telephone, it is not known precisely when the area was filled.

We would appreciate any information Bell Aerospace may have concerning this site. Your assistance in the investigation is greatly appreciated.

rdquistex

Sincerely yours,

JS:bf-9

Bell Aerospace Textron Division of Textron Inc.

Post Office Box One Buffalo, New York 14240-0001 716/297-1000

29 July 1988

Jon Sundquist
Ecology and Environment, Inc.
Buffalo Corporate Center
368 Pleasantview Drive
Lancaster, NY 14086

Dear Mr. Sundquist:

I am writing in response to your May 20, 1988 letter to Brian Smith.

While we would like to provide assistance we are unable to do so at this time. We have no record of involvement at this site. Our manifest system started in 1981, after the period in question.

Sincerely,

Carl G. Buzawa

Carl Dorman


Vice President - Division Counsel

cla

REFERENCE 11 (See Appendix C)


COLOSSAL CATARACT

QE 146.N6 C64 The Geologic History of Niagara Falls



SOIL SURVEY OF

Niagara County, New York





United States Department of Agriculture Soil Conservation Service In cooperation with Cornell University Agricultural Experiment Station

Issued October 1972

A-41

REFERENCE 14 (See Figure 1-1)

REFERENCE 15



New York State Department of Environmental Conservation

MEMORANDUM

TO:

Mr. Demick - Western Investigation Section

FROM:

Mr. Tygert - Region 9 100000

SUBJECT:

Walmore Road Site (932094)

DATE:

September 17, 1986

On September 17, 1986, Mr. Clare of Region 9 and Mr. Lupe of your Section discussed the problem with site identification of the Walmore Road site. It was agreed that the two sites should be separated in the Registry. We recommend the following division be made:

- 1. 932094 Existing file for Walmore Road. Change name to Lockport Road Site.
- Add new site identified by the Niagara County 2. Health Department in 1982. Name this site Johnson Site - Walmore Road.

It is also recommended that the Johnson Site - Walmore Road be added to the next schedule of Phase I Investigations.

This recommendation was previously made to your Office in a memorandum (undated, unfortunately) written on March 6, 1986. Mr. Lupe advises that this request is not available in your file.

Your consideration of this recommendation will be appreciated.

cc: Mr. Buechi

Mr. Clare

Mr. Olazaqasti

Mr. Lupe

Mr. Hopkins

REFERENCE 16

Aerospace 113X1KON

104144-29 127K#148

7111211

Post Office Box One Buffalo, New York 14240 716/297-1000

CATEGORIZED:

ICS F NONE

CATEGORY TRACKED:

+ October 1984

INTERPRETATION/FORMATTING:

nmental Conservation
Waste

ENTEREDOCT 1 5 1604
DATA ENTERED:

•

-FINAL CLASSIFICATION:

ching its records in order to prepare as accurate vernor Cuomo's Executive Order #33 of December, 1983. orders, vouchers, Accounts Payable records,

ords to be analyzed. The Company is in the process records using audit techniques to trace past disposal practice. The earliest of the purchase orders by which Bell purchased waste hauling services date to 1966. These records are commingled with all company purchase orders which number in the hundreds of thousands and are not specifically identified by subject.

The earliest records which deal specifically with the disposal of waste date to 1966. The earliest records which deal with processes involving chemicals date to 1958. These records require study to determine if they contain information which may suggest where and how waste may have been disposed of.

We have found the following data, thus far, which will be included in the Generator Questionnaire when it is prepared in final form:

- (1) An unknown quantity of Virgo Salts (caustic soda) was transported by an unknown carrier to the Niagara County Refuse Disposal District in November, 1972.
- (2) The following chemicals were picked up at Bell Aerospace Textron and disposed of by Frontier Chemical Waste Process, Inc. of Niagara Falls, New York in June, 1975:

3 - 55 gal. drums of acetone 4 - " " alcohol

2 - " " brush wash (mixed solvents)

22 - " " off-specification UDMH (unsymmetrical dimethyl hydrazine)

(3) Eight pounds of thorium were delivered to ATCOR in Peekskill, New York in December, 1976. The carrier was a company named "McCormacks".

As I indicated to NYSDEC previously, we have rehired a retired Bell Aerospace Textron employee specifically to work on this task. We are working the problem and will provide a report on our progress in December, 1984 by which time we expect that the principal relevant information will have been extracted from the available records.

Very truly yours,

Earl E. Kramer

Mgr., HRD, Safety and Environmental Affairs

EEK/jfs

(C)

GENERATOR FORM PART - II

Aerospace Textroh NYD002106276

Box 1

ADDRESS P. O.

NAME 3e11 Buffalo

ZIP 14240

STATE N.Y.

.

DATE 11/28/84

ENTERED COP JAN 1 7 1985

6. TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS) McCormacks (unknown) UN KNOWN Unknown Unknown Unknown = 11/9/72 WASTE DISPOSAL DATES 2/15/73 5/20/75 1/9/74 5/1/15 6/2/15 × × SMURG × × ××× FORM QOFID PRONID × × × × ××× WASTE DISPOSED OF QUANTITY OF WASTE (TONS) 6353556 0.06 tons Less than one ounce 0.08 tons tons tons Unknown 2:05 5.2 3. EPA WASTE CODE 2000 D002 None B001 D001 22 drums of Unsymmetrical 0098 Dimethylhydrazine **U002** D001 D001 DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS) Mattern (RA226 as Radium Sulfate Brushwash & Other Acetone, Alcohol, 4 drums of waste PCB container Aluminum of Acetone on-metal foil chips gals. Alcohol gals. Mixed Unknown quantity HAGAR DOUS Hydride caustic soda gals. 55 55 55 (E) $\overline{\mathfrak{Z}}$ ٥i 8 0 9 8-2 7-7 Niagara Falls, N.Y.14303 1. HAZARDOUS WASTE DISPOSAL SITE Waste Niagara County Refuse NKNOWY Elmsford, N.Y. 10523 Disposal District 5 Westchester Plaza SEE INSTRUCTIONS) Frontier Chemical 4626 Royal Avenue Process, Inc. Hamburg, N.Y. Lake Avenue Atcor, Inc. Chemtrol

G...теНАТОН FORM PART - 11

MADL THE THE MINDLE 109

P. O. Box 1

Buffalo

ZIF 14240

STATE N Y

NATE 11/28/84

DATE 11/28/84	6. TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS)	Unknown	Unknown	McCormacks (unknown)	(Unknown)	(Unknown)	(Unknown)	Lorber Trucking 1140 Military Rd. Buffalo, N.Y.	9X-015
	5. WASTE DISPOSAL DATES	x 5/20/76	x 9/14/76	12/14/75	6/28/77	10/2/78	10/2/78	1/23/81 LG	
		××		×	×	×	×	×	
ASTES 3. EPA 4. WASTE DISPOSED OF	WASTE	D002 3.5 tons	Unknown Unknown	None 8 lbs.	D001 4.11 tons x	D001 3.65 tons x	D001 0.60 tons x	ed D000 5.48 tons x D001 D002 D003	
2. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION	(SEE INSTRUCTIONS)	Jals. Aqueous Solition W/1575 lbs.	Small quantities of chemicals (Lab pack)	Natural Thoria	18 - 55 gals. cont. of brushwash	16 - drums of brushwash	5 drums of alcohol	73-55 gal drums discarded lab chemicals (lab pack)	
1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS)	Frontier Che	4626 Roy Nia. Fal	Wyoming Waste Disp. 22 Grant Street N. Tonawanda, NY 14120		Bison Waste Oil Co. 12866 Broadway Alden, N.Y. 14120	= SOEC		ECOS International 56th St. & Pine Ave. Via. Falls, N.Y. 14303	
r	ecycled pap	per		A-4	9	TAFF 60	оюдь ина сичге	**************************************	

THE PARTY OF THE P

GENERAL PROPERTY OF THE PROPER PART - II

ICS NUMBER - EPA 10 NUMBER NYD002106276

NAME Bell Aerospace Textron

ADDRESS BOX 1

Buffalo

ZIP 14240

STATE N.Y.

11/28/84 DATE _

The second of the second

6. THANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS)	Newco Waste 4626 Royal Ave. Nia. Falls, NY ήρ [·] εο β	Newco Waste 4626 Royal Aven Niagara Falls,	=	Cataract Trucki 2445 Allen Aver Niagara Falls, 14303	9 A - 0.9	=	: .
5. WASTE DISPOSAL DATES	8/19/81	8/19/81	10/9/81	10/26/81	10/26/81	10/26/81	10/26/81
SMURO SOLID SOLID	*	×	×	×	×	× .	×
	×	×	×	×	×	×	×
4. WASTE DISPOSED OF QUANTITY OF WASTE (TONS)	6.02 tons	6.62 tons	0.17 tons	1.37 tons	1.14 tons	0.68 tons	0.46 tons
3. EPA WASTE CODE	D001	D001	B006	F001	F002	F001	D001
2. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS)	28 drums Isospropyl Alcohol	29 drums Brushwash	PCB Solid Waste (Rags, clothing) 7 drums	6 drums Perchloroethylene γ_{O}	5 drums Freon	3 drums Trichlorethylene $\mathcal{T}^{\mathcal{L}}$	2 drums Liquid Tar
1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS)	CECOS International 56th St. & Pine Ave. Nia. Falls, N.Y. 14303	-		=	= 5.5050		=

The state of the s GENERATOR FORM PART - II

ICS NUMBER - EPA ID NUMBER NYD002106276

Aerospace Textron

P. Box 1

Buffalo

24240

DATE 11/28/84

6. TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS)	Cataract Truckii 2445 Allen Aven Nia. Falls, N.Y $q \wedge C^{\alpha}$ 14303	≖.	Newco Waste #1 4626 Royal Ave. Nia. Falls, N.Y Tonawanda Tank 1140 Military F	=	Tonawanda Tank Transport Servi 1140 Military R Buffalo, N.Y.	Nia. Industrial Warehouse 4626 Royal Aven Nia. Falls, N.Y	CECOS Internati 56th & N.F.Blvd Nia. Falls, N.Y
5. WASTE DISPOSAL DATES	10/26/81	10/26/81	11/10/81 0) × C 91,000	11/10/81	12/14/81	12/22/81 91/045	1/25/82
SWURD SALIDUR	×	×	×	×	×	×	/ _×
4. WASTE DISPOSED OF QUANTITY OF WASTE (TONS)	2.05 tons	1.37 tons	3.65 tons	0.06 tons	7.24 tons	6.23 tons	1.85 tons
3. EPA WASTE CODE	D002	D002	B001 B003	B007	D002	D002	B010
2. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS)	9 drums pickle liquor	6 drums Phosphoric Acid	16 drums PCB Contaminated Oil	1 drum (3 capacitors.w/PCB)	ă	Bulk - Pickle Liquor	1 empty high voltage transformer; decontami nated of PCB oil (3700
1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS)	CECOS International 56th St. & Pine Avenue Nia. Falls, N.Y. 14303	=	Ensco, Inc. American Oil Road Eldorado, Arkansas 71730	=	CECOS International F 56th St. & Nia.Falls Blvd. Nia. Falls, N.Y. 14303	=	=
ecycled paper			A-51	SEIVE	EDDEC 1 4 coology au	584 d environment	

A STATE OF THE STA

103 NVMB68-2170 8 24 MBE: Textron Aerospace Appress. Box Buffalo

21P14240 SIATE

PART - II

11/28/84

DATE.

4626 Royal Avent Falls, N.Y. TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS) Waste Process In 2445Allen Avenu Frontier Chemica Nia. Falls, N.Y 4626 Royal Aven Nia. Falls, N.Y Car Rental Newco Waste Cataract = Nia. WASTE DISPOSAL DATES 6/15/82 3/19/82 7/23/82 7/23/82 7/23/82 7/23/82 x 7/23/82 Š. × SMURG × × × × × WASTE DISPOSED OF QUANTITY OF WASTE (TONS) Tons tons tons 1.60 tons tons tons tons 6.23 0.11 0.91 1.6 12.7 ,6z/gal Borlic Acild 3. EPA WASTE CODE D002 D002 D002/ P104D001 P106₹000 DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS) Ampdizing Solution 7 drums Nickle Sulfamate 10 oz/gal Nickle/Sulfa-Sulfate Sodium Cyanide Silver Cyanide Plating Solution With Chromic Acid Plating Bath Salt Soln. Nickle Sulfamate Heat Treat Sa∆t mic acid and 4 Copper Sodium Nitrat 33 drums drums drums 7 drums drum ı Bulk જં 4 Ŋ 45232 1 HAZARDOUS WASTE DISPOSAL SITE Falls, N.Y. 14303 56th St. & N.F. Blvd. CECOS International CECOS International Niagara Falls, N.Y. (SEE INSTRUCTIONS) Williamsburg, Ohio Waste Process Inc. 4626 Royal Avenue Frontier Chemical 5092 Aber Rd. = Nia.

GENERATOR FORM

PART - II

DATE 11/28/84

Appness Box 1 State | State | State | State | State | State | Buffalo | N.Y. | 14240 | Buffalo | N.Y. | 14240 |

the subdivision of the subdivisi

Hade table of Charles of the Ha

Chemic Waste Process, I 4626 Royal Aven THANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS) Niagara Falls, Frontier 6 7/23/82 x 1/23/82 7/23/82 WASTE DISPOSAL DATES 7/23/82 7/23/82 7/23/82 × × × DRUMS × × × × × × WASTE DISPOSED OF QUANTITY OF WASTE (TONS) tons 1.14 tons tons tons tons tons 0,23 0/. 46 0.46 0.23/3,65 D007 U133 D001 P068 WASTE CODE D001 F002 3. EPA generated : No. 38) drums Sodium Dichromate DESCRIPTION OF HAZARDOUS WASTES
DEPOSITED AT THIS LOCATION
(SEE INSTRUCTIONS) 2 drums Aluminum Solids w/Monomethyl Hydrazine-(AF Plant No. drums Hydraulic\0i1 1 drum waste Alcohol generated at BTC (AF Plant No. 38) drum AviatXon Fuel Trichloroethylene, w/Hydrazine base drums Freon Humiseal Freon, 97 S Н ĸ 1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS) Niagara Falls, N.Y Waste Process, Inc 4626 Royal Avenue Frontier Chemical

A-53

10/18/82

×

tone

0.13

D001

Soldering Flux

l drum Kester I CS ANUMBER A BA ID NUMBER

Sell Aerospace Textrop NVD86260624V8669 14240 STATE O. Box Buffalo ADDRESS

The party of the party of the Bank and the control of the control of the party of t

PART - II

11/28/84

DATE

4626 Royal Avenue Waste Process Inc 11/15/82|Frontier Chemical Waste Process, Inc 4626 Royal Avenue CECOS Internation Falls, N.Y. Nia.Falls, NY 1430 x 10/18/82 Frontier Chemica 56th & N.F.Blvd. Niagara Falls,NY TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS) = = Nia. 8 x 11/15/82 x 11/15/82 11/15/82 x 10/18/82 11/15/82 WASTE DISPOSAL DATES × × × SMURO × × × × × × × 4. WASTE DISPOSED OF QUANTITY OF WASTE (TONS) 0.46 tons tons 0.23 tons 0.23 tons tons 0.33 tons tons 5.61 0.50 0.46 3. EPA WASTE CODE D002 D001 F002 1000 **7**000 D002 D002 drum Potassium Hydroxide DESCRIPTION OF HAZARDOUS WASTES
DEPOSITED AT THIS LOCATION
(SEE INSTRUCTIONS) 3drums Hazardous Solid Alkaline Solvents Hazardous Waste Solld Solution NOS (lab pack) 34 drums Hazardous Waste Acid Liquids 2 drums (40 gals) Solid Waste drums Waste 2 drums Waste (Lab Pack) 1 drum Waste ~ --~; Niagara Falls, N.Y.14303 1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS) "56th St. & N.F.Blvd. Vindagara Falls, N.Y. Waste Process, Inc. CECOS International Waste Process, Inc. 4626 Royal Avenue GFrontier Chemical Niagara Falls, NY 4626 Royal Avenue Frontier Chemical DE ٤ 1

GENERATOR FÖRM

Combined by the second of the

A Charles of Carlotter of Carlot

construction of the second second section

Aerospace Textron NYBB002106276

ZIP 14240

STATENY

Box

o

ADDRESS P.

Buffalo

CIT

DATE 11/28/84

N.Y 4626 Royal Aven Frontier Chemic TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS) Waste Process Falls, = = Nia. ဖ 11/15/82 11/15/82 11/15/82 WASTE DISPOSAL DATES x | 9/8/83 8/8/6 8/8/6 9/8/83 × × × × × × SMURG מרום ב × × × × × × WASTE DISPOSED OF QUANTITY OF WASTE (TONS) tons tons tons tons tons tons tons 0.72 66 0.84 1,16 0.46 0.33 D001 D001 3,133 £000 P068 3. EPA WASTE CODE D007 D001 DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS) Water Peroxide Methyl Alcohol w/Water lazardous Solid Waste Solvents Silicone 0'il Hydrazine w/Alumihum, Hydrazine - Brush Wakh ھ Lab Pack) Isopropy, บ water & Freon mixtur Organ Monomethyl w/water & drums drums Waste drum Waste 2 -2 ĸ HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS) Falls, N.Y. Waste Process, Inc. 4626 Royal Avenue Frontier Chemical Niagara

THE PROPERTY OF THE PROPERTY O GENERATOR FORM PART - 11

NAME NATIONAL TEXTRON NYD002106276

14240

dIZ

STAKY

ADDRESS P. O. BOX 1 Buffalo

CITY

DATE 11/28/84

6. THANSPOHTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS)	Frontier Chemic Waste Process I 4626 Royal Aven Nia. Falls, N.Y	=		=	Ξ .	=	=
5. WASTE DISPOSAL DATES	9/8/83	9/8/83	6/8/83	8/8/6	6/8/83	x 9/8/83	x 9/8/83
SMURO SMURO SMURO LIQUID	×	×	×	×	×	×	× /
4. WASTE DISPOSED OF FOR GUANTITY OF WASTE DO (TONS)	0.3 tons x	0.3 tons x	0.20 tons x	0.20 tons x	0.10 tons	0.10 tons	0.05 tons
3. EPA 4 WASTE CODE	F002	F002	D0001	D001	2002	6000	D001
2. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS)	1,1,1 Trichloroethane	Trichlorofluoromethane	Toluene	Waste Solvents NOS	Hazardous Waste Solids NOS (LAB PACK)	Hazardous Waste Solids NOS (Lab Pack)	Waste Flammable Liquid NOS
1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS)		Niagara Falls, W.1.	=	=	=	=	=

DATE 11/28/84

14240

STATE

CITY

Aerospace Textron P. 0. BOX Buffalo

energia di Maria di Sumano de la Alfra de Caral Armenamo de Maria de Santos de Caractes de Militaria de Caractes de Caractes de Militaria de Caractes de Caractes

6. TRANSPORTER OF HAZARDOUS WASTE (SEE INSTRUCTIONS)	Frontier Chemica Waste Process In 4626 Royal Avenu Niagara Falls, N				·		
5. WASTE DISPOSAL DATES	9/8/83						
E GIJOS	×						
NE GINOS	×						\dashv
4. WASTE DISPOSED OF OUANTITY OF WASTE (TONS)	0.7 tons						
3. FPA WASTE CODE	D002			r r r			
2. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS)	Waste Corrosive Liquid		astes were generated at nt #38, located 17 miles	lity) before 31 December 1981, Frontier Chemical Waste Process Test Center to the Frontier Inc. Facility.			
1 HAZARDOUS WASTE DISPOSAL SITE (SEE INSTRUCTIONS)	Maste	Niagara Falls, N.1.	NOTE: All of these hazardous wastes were gener	from the Wheatfield Facility) before and were transported by Frontier Chen Inc. directly from Bell Fest Center to Chemical Waste Process, Inc. Facility			

	4	37°.	ا د	
1				1
1			- /	

11/28/84

ADDRESS P. O. BOX 1 STATE NY 21 14240

TRANSPORTER FORM
PART-II

FORM 0.46 tonsk 0.46 tonsk 6. WASTE DISPOSED . EPA WASTE CODE U133 P068 Monomethylhydrazine Hydraulic Oil with 4. DESCRIPTION OF HAZARDOUS WASTES DEPOSITED AT THIS LOCATION (SEE INSTRUCTIONS) Aluminum Solids with Hydrazine base 8/20/81 DATES OF SHIPMENT (MONTH) (YEAR) 8/20/81 6 2. NAME OF FIRM-COMPANY THAT PRODUCED INDUSTRIAL WASTE (SEE INSTRUCTIONS) Test Center (AF Plant at Aerospace Textron Cobt! 16 Bel1 Bel1 #38) Niagara Falls, NY 14303 1. HAZARDOUS WASTE DISPOSAL SITE Waste Process, Inc. 4626 Royal Avenue (SEE INSTRUCTIONS) Frontier Chemical

disposed of by Front ier Plant until ultimatelly at main Wheatfield Placed in storage site. at their * NOTE: A-58

REFERENCE 17

ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES IN THE STATE OF NEW YORK

PHASE II INVESTIGATIONS

Lockport Road-Struzik Property Town of Wheatfield, Niagara County Site No. 932094

February 1992



Prepared for:

New York State Department of Environmental Conservation

50 Wolf Road, Albany, New York 12233 Thomas C. Jorling, Commissioner

Division of Hazardous Waste Remediation Michael J. O'Toole, Jr., P.E., Director


Prepared by:



BUFFALO CORPORATE CENTER
368 PLEASANTVIEW DRIVE, LANCASTER, NEW YORK 14086, TEL. 716/684-8060

REFERENCE 18

1968 April



APPENDIX B SITE INSPECTION REPORT (EPA FORM 2070-13)

POTENTIAL HAZAI	RDOUS WASTE SIT	ГE	I. IDENTIFICATION	N			
,		WOM.	01 State	02 Site Number	ः	1	
PART 1 - SITE LOCATION AN	D INSPECTION INFORMAT	ION	NY	932101			
II. SITE NAME AND LOCATION							
01 Site Name (legal, common, or descriptive na Walmore Road - Johnson Property	me of site)	02 Street, Route N 6373 Walmore	o., or specific location i Road	dentifier			
03 City		04 State	05 Zip Code	06 County	07 County	08 Cong.	
Town of Wheatfield		NY 14304 Niagara 063				Dist.	
Latitude Longitude D 43° 06' 58* N 78° 55' 25* W []			ship (check one) [] B. Federal pal [] F. Other	[] C.	State [] D. [] G.	County Unknown	
III. INSPECTION INFORMATION							
01 Date of Inspection	02 Site Status	03 Years of Opera	tion				
5 / 2 / 91 Month Day Year	[] Active [X] Inactive	Beginning Ye	ear Ending Year	[X] t	Jnknown		
04 Agency Performing Inspection (check all that [] A. EPA [] B. EPA Contractor [] E. State [X] F. State Contractor E		[] C. Municip		unicipal Contracto	or(name of	firm)	
05 Chief Inspector	06 Title	07 Organization		08 Telephone	No.		
Scott Glinski	Land Use Planner	E&E		(716) 684-8060			
09 Other Inspectors	10 Title	11 Organization		12 Telephone No.			
Linda Fischer	Environmental Scientist	E&E		(716) 684-6060			
Abul Barkat	Engineer	NYSDEC		(716) 847-	(716) 847-4585		
				()			
				()			
13 Site Representatives Interviewed	14 Title	15 Address		16 Telephone	No.		
				()			
				()			
				()			
				()			
17 Access Gained by (check one) [X] Permission	18 Time of Inspection	19 Weather Cond					
[] Warrant	3:00 p.m.	Overcast, Clou	dy Temperature 50°F				
IV. INFORMATION AVAILABLE FROM	1			1			
01 Contact	02 Of (Agency/Organizatio	n)		03 Telephone			
Abul Barkat	NYSDEC	I	1	(716) 847-	4585		
04 Person Responsible for Site Inspection Form	05 Agency	06 Organization	07 Telephone No.	08 Date	,		
Scott Glinski		E&E	(716) 684-8060	5 / 2 Month D			

	POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT		I. IDENTIFICATION			
		X1	01 State	02 Site Number		
PART	2 - WASTE INFORMATION		NY	932101		
II. WASTE STATES, QUAN	TITIES, AND CHARACTERIST	псѕ				
01 Physical States (check all t	hat apply)	02 Waste Quantity at		03 Waste Characteristics (chec	ck all that apply)	
[X] A. Solid [] E. Slurry [X] B. Powder, Fines [] F. Liquid [X] C. Sludge [] G. Gas [] D. Other		quantities must be independent) Tons Cubic Yards No. of Drums		[] B. Corrosive [] C. Radioactive [] D. Persistent [] E. Soluble	[] H. Ignitable [] I. Highly volatile [] J. Explosive [] K. Reactive [] L. Incompatible [] M. Not applicable	
III. WASTE TYPE						
Category	Substance Name	01 Gross Amount	02 Unit of Measure	03 Comments		
SLU	Sludge			This property reportedly h	as been backfilled with graphite,	
olw	Oily waste			plastic battery cases, harde	ened resins, heat-treating salts,	
SOL	Solvents			fly ash, plastic tank sludge	e, and scrap wood to a depth of 5	
PSD	Pesticides			feet. The amount and cha	racteristics of the wastes are	
00C	Other organic chemicals			unknown.		
IOC	Inorganic chemicals					
ACD	Acids					
BAS	Bases					
MES	Heavy metals					
IV. HAZARDOUS SUBSTA	NCES (see Appendix for most fre	equently cited CAS Numb	ers)			
01 Category	02 Substance Name	03 CAS Number	04 Storage/Disposal Method	05 Concentration	06 Measure of Concentration	
•						
V. FEEDSTOCKS (see Appea	ndix for CAS Numbers)					
Category	01 Feedstock Name	02 CAS Number	Category	01 Feedstock Name	02 CAS Number	
FDS			FDS			
FDS			FDS			
FDS			FDS			
FDS			FDS			
VI. SOURCES OF INFORM	ATION (cite specific references,	e.g., state files, sample a	nalysis, reports)			
Niagara County Departme	Niagara County Department of Health files, Niagara Falls, New York; NYSDEC, Division of Solid and Hazardous Wastes, Inactive Hazardous Waste Disposal Report.					

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

1. IDENTIFICATIO		
01 State	02 Site Number	
NY	932101	

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS A	ND INCIDENTS	01 State	02 Site Number	
		NY	932101	•
II. HAZARDOUS CONDITIONS AND INCIDENTS				
01 [X] A. Groundwater Contamination 03 Population Potentially Affected <u>Unknown</u>	02 [] Observed (c 04 Narrative Descr	date) ription:	[X] Potent	ial [] Alleged
Potential exists if waste is hazardous and leachate enters groundws Groundwater is used for drinking water within 3 miles of the site.	iter system. Well on si	ite was sampled 1985 N	CDOH; no contaminants detected.	
01 [X] B. Surface Water Contamination 03 Population Potentially Affected	02 [] Observed (c 04 Narrative Descr	date) ription:	[X] Potent	ial [] Alleged
Potential exists if waste is hazardous and leachate enters Cayuga C	reck, adjacent to site.	Surface water is not cur	rrently used.	i N
01 [] C. Contamination of Air 03 Population Potentially Affected <u>Unknown</u>	02 [] Observed (c 04 Narrative Descr		[] Potent	ial [] Alleged
01 [] D. Fire/Explosive Conditions 03 Population Potentially Affected <u>Unknown</u>	02 [] Observed (c 04 Narrative Descr		[] Potent	ial [] Alleged
01 [] E. Direct Contact 03 Population Potentially Affected <u>Unknown</u>	02 [] Observed (c 04 Narrative Descr		[] Potent	ial [] Alleged
01 [X] F. Contamination of Soil 03 Area Potentially Affected 2 acres_ Potential exists; fill material is in direct contact with soil.	02 [] Observed (d 04 Narrative Descr		[X] Potent	ial [] Alleged
01 [X] G. Drinking Water Contamination 03 Population Potentially Affected <u>Unknown</u> Potential exists as groundwater is used as a source of drinking water	02 [] Observed (d 04 Narrative Descr er on the Tuscarora Ind	iption:	[X] Poten	tial [] Alleged
01 [] H. Worker Exposure/Injury 03 Workers Potentially Affected None reported; fill material is covered with soil and vegetation.	02 [] Observed (d 04 Narrative Descr		[] Potent	ial [] Alleged
01 [] I. Population Exposure/Injury 03 Population Potentially Affected None reported; fill material is covered with soil and vegetation.	02 [] Observed (d 04 Narrative Descr		[] Potent	ial [] Alleged

I. IDENTIFICATION POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT 01 State 02 Site Number PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS 932101 NY II. HAZARDOUS CONDITIONS AND INCIDENTS (Cont.) 02 [] Observed (date _____) [] Potential [] Alleged 01 [] J. Damage to Flora 04 Narrative Description: None reported; waste is covered with soil and vegetation. 02 [] Observed (date _____) [] Potential [] Alleged 01 [] K. Damage to Fauna 04 Narrative Description: None reported; waste is covered with soil and vegetation. 02 [] Observed (date _____ [X] Potential [] Alleged 01 [X] L. Contamination of Food Chain 04 Narrative Description: Potential exists if waste is hazardous and migrates from soil or water to flow in fruit orchard, corn field, vegetable garden. Well on site is used for irrigation. 02 [] Observed (date _____) [X] Alleged [] Potential 01 [X] M. Unstable Containment of Wastes (spills/ runoff/standing liquids, leaking drums) 03 Population Potentially Affected: 04 Narrative Description: Alleged waste is covered by soil and vegetation, waste used for fill material. 02 [] Observed (date _____) [] Potential [] Alleged 01 [] N. Damage to Off-site Property 04 Narrative Description: None reported. 02 [] Observed (date _____ [] Potential [] Alleged 01 [] O. Contamination of Sewers, Storm Drains, WWIPs 04 Narrative Description: None reported. No storm sewers are located near site. 02 [] Observed (date _____) [] Potential [] Alleged 01 [] P. Illegal/Unauthorized Dumping 04 Narrative Description: 05 Description of Any Other Known, Potential, or Alleged Hazards None identified. III. TOTAL POPULATION POTENTIALLY AFFECTED 413 within 1 mile, total number within 3 miles is unknown. IV. COMMENTS V. SOURCES OF INFORMATION (cite specific references, e.g., state files, sample analysis, reports) NYSDEC Phase I investigation June 1989; Ecology and Environment Engineering, P.C. Site Inspection, May 2, 1991; Niagara County Health Department files, Niagara Falls, New York; Niagara County Department of Planning, Lockport, New York; Town of Wheatfield (NY) Water Division

POTENTIAL HAZARDOUS WASTE SITE	I. IDENTIFICATION	I. IDENTIFICATION		•	
SITE INSPECTION REPORT	01 State	02 Site Number			
PART 4 - PERMIT AND DESCRIPTIVE INFORMATION	NY	932101			
II. PERMIT INFORMATION					
01 Type of Permit Issued (check all that apply)	02 Permit Number	03 Date Issued	04 Expiration	05 Comments	
[] A. NPDES			Date		
[] B. UIC					
[] C. AIR					
[] D. RCRA					
[] E. RCRA Interim Status					
[] F. SPCC Plan					
[] G. State (specify)					
[] H. Local (specify)					
[] I. Other (specify)					
[] J. None					
III. SITE DESCRIPTION					
01 Storage Disposal (check all that apply) 02 Amount 03 Unit of Measure [] A. Surface Impoundment	04 Treatment (check all that apply) [] A. Incineration [] B. Underground Injection		05 Other [] Buildings On Site		
[] B. Piles [] C. Drum, Aboveground [] D. Tank, Aboveground [] E. Tank, Belowground [X] F. Landfill [] G. Landfarm	[] C. Chemical/ [] D. Biological	Physical			
[] E. Tank, Belowground [X] F. Landfill	[] E. Waste Oil [] F. Solvent Re	-	06 Area of Site		
[] G. Landfarm	[] G. Other Rec	ling Recovery	Acres		
[] I. Other Fill material Unknown (specify)		(specify)			
07 Comments	<u>L</u>				
It is not known if fill material contains any hazardous constituents.					
IV. CONTAINMENT					
01 Containment of Wastes (check one)					
[] A. Adequate, Secure [] B. Moderate [X] C. Inadequa	te, Poor [] D	. Insecure, Unsoun	l, Dangerous		
02 Description of Drums, Diking, Liners, Barriers, etc.					
Waste was used as fill material, placed on land surface, and covered.					
V. ACCESSIBILITY					
01 Waste Easily Accessible [X]Yes [] No 02 Comments					
Waste covered by soil and vegetation but cover thickness is unknown.					
VI. SOURCES OF INFORMATION (cite specific references, e.g., state files, a	ample analysis, reports)				
Niagara County Department of Health files, Niagara Falls, New York; Ecolo Investigation Phase I, June 1989.	gy and Environment Eng	gineering, P.C. Site	Inspection, May 2,	1991; NYSDEC Engineering	

Pe	OTENTIAL HAZARDOUS V SITE INSPECTION RE		I. IDENTIFICATION	`
PART	5 - WATER, DEMOGRAPHIC, AND EN		01 State	02 Site Number
			NY	932101
II. DRINKING WATER	SUPPLY			
01 Type of Drinking Sup	ply (check as applicable)	02 Status	03 Distance to Site	
Community	Surface Well A. [X] B. []	Endangered Affected Monitored	A5.5	(mi)
Non-community	C. [X] D. [D]	A. [] B. [] C. [X] D. [] E. [] F. [X]	B5.5/~3.0	(mi)
III. GROUNDWATER				
01 Groundwater Use in V	/icinity (check one)			
[] A. Only Source f	for Drinking [X] B. Drinking (other sou Commercial, Industri (no other water source	ial, Irrigation (limited other	Industrial, Irrigation []	D. Not Used, Unusable
02 Population Served by	Groundwater <u>Unknown</u>	03 Distance to Nearest Drinking Water We	ell (mi)	
04 Depth to Groundwater	05 Direction of Groundwater Flow	06 Depth to Aquifer of Concern	07 Potential Yield of Aquifer	08 Sole Source Aquifer
6(ft)	<u>Southwest</u>	13(ft)	<u>Unknown</u> (gpd)	[] Yes [X] No [] Unknown
09 Description of Wells (including usage, depth, and location relative t	o population and buildings)		
One well on site used i	for irrigation of garden and fruit trees. Wells	within 3 miles of site are used for irrigation	purposes only.	
10 Recharge Area		11 Discharge Area		
	nts: Unconsolidated deposits. Aquifer is ed with precipitation	[X] Yes Comments: Some discha	rge may occur into Cayuga Creck	
[] No				
IV. SURFACE WATER				
01 Surface Water (check	one)			
[] A. Reservoir, Rec Drinking Wate		, , , , , , , , , , , , , , , , , , , ,	lustrial [X] D. Not Curr	rently Used
02 Affected/Potentially Af	ffected Bodies of Water			
Name:			Affected Dis	tance to Site
Cayuga Creek			[] _0	(mi)
Niagara River			[]	5 (mi)
			[]	(mi)
V. DEMOGRAPHIC AN	D PROPERTY INFORMATION			
01 Total Population Withi	One (1) Mile of Site	Two (2) Miles of Site	Three (3) Miles of Site	02 Distance to Nearest Population
	A. 413 No. of Persons	B. 5,072 No. of Persons	C. 21,584 No. of Persons	0.1 (mi)
03 Number of Buildings V	Within Two (2) Miles of Site		04 Distance to Nearest Off-Site I	
1,181			0.1	(mi)
05 Population Within Vici	nity of Site (provide narrative description of	nature of population within vicinity of site, e.,	g., rural, village, densely populated	
		at to site. City of Niagara Falls approximate		,

recycled paper

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT		I. IDENTIFICATION	:	
,		01 State	02 Site Number	
PART 5 - WATER, DEMOGRAPHIC, A	ND ENVIRONMENTAL DATA	NY	932101	
VI. ENVIRONMENTAL INFORMATION				
01 Permeability of Unsaturated Zone (check	one)			
[] A. Impermeable (less than 10 ⁻⁶ cm/sec)	[X] B. Relatively Impermeable (10 ⁻⁴ - 10 ⁻⁶ cm/sec)	[] C. Relatively Permeable [] D. Very Permeable (10 ⁻² - 10 ⁻⁴ cm/sec) (greater	ermeable than 10° cm/sec)	
02 Permeability of Bedrock (check one)				
[] A. Impermeable (less than 10 ⁻⁶ cm/sec)	[] B. Relatively Impermeable (10 ⁻⁴ - 10 ⁻⁶ cm/sec)	[X] C. Relatively Permeable [] D. Very Permeable (10 ² - 10 ⁴ cm/sec) (greater	ermeable than 10 ² cm/sec)	
03 Depth to Bedrock	04 Depth of Contaminated Soil Z	one	05 Soil pH	
	Unknown	_ (ft)	<u>5.6-7.6</u>	
06 Net Precipitation	07 One Year 24-Hour Rainfall	08 Slope Site Slope Direction of Site Slope	Terrain Average Slope	
4 (in)	(in)	2%NW	%	
09 Flood Potential	10 [] Site is on Barrier Island,	Coastal High Hazard Area, Riverine Floodway		
Site is in 100 Year Floodplain				
11 Distance to Wetlands (5 acre minimum)		12 Distance to Critical Habitat (of endangered species)		
ESTUARINE OTHER		NA(mi)		
A. <u>NA</u> (mi) B. <u>2.25</u> (mi) Endangered Species:]!	
13 Land Use in Vicinity				
Distance to:				
COMMERCIAL/INDUSTRIAL	RESIDENTIAL AREAS, NATIONAL/STATE AGRICULTURAL LANDS COMMERCIAL/INDUSTRIAL PARKS, FORESTS, OR WILDLIFE RESERVES PRIME AG LAND AG LAND			
A. <u>.1</u> (mi)	B. <u>0</u> (mi)	C. <u>0</u> (mi)	D. <u>0</u> (mi)	
14 Description of Site in Relation to Surrou	nding Topography			
This site is located in a flat area. The property is bounded on the west by Walmore Road and Cayuga Creek and a Conrail railroad track embankment to the northeast. Rainwater runoff is expected to enter Cayuga Creek, which flows southwest to Niagara River.				
VII. SOURCES OF INFORMATION (cite	specific references, e.g., state files,	вашры впагувы, геропы)		
USGS 7.5 Minute Topographic Maps, Ransomville and Tonawanda West Quads FEMA Flood Insurance Maps Soil Survey of Niagara County, New York Niagara County Department of Health, Niagara Falls, New York Town of Wheatfield Water Department, Wheatfield, New York NYSDEC Phase I Investigation, June 1989				

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT		I. IDENTIFICATION .				
SHE INSPECT	ION REPORT	01 State	02 Site Number			
PART 6 - SAMPLE AND	FIELD INFORMATION	NY	932101			
II. SAMPLES TAKEN						
Sample Type	01 Number of Samples Taken 02 Samples Sent To 03 Estimated Date Results Available					
Groundwater	No samples taken during site inspection.					
Surface Water						
Waste						
Air						
Runoff		·				
Spill						
Soil						
Vegetation						
Other						
III. FIELD MEASUREMENTS TA	AKEN					
01 Type	02 Comments					
Air	Performed with HNu photoionization detector during site inspection. No readings (all types) above background noted.					
Radiation	Performed with Radiation Alert Monitor 4EC during site inspection. No readings above background noted.					
IV. PHOTOGRAPHS AND MAPS	3					
01 Type [X] Ground	[X] Aerial 02 In Custody of Ecology and Environment Engineering, P.C; Niagara County EMC					
		(nam	e of organization or individual)			
	-	<u> </u>	and the second s			
03 Maps	04 Location of Maps					
[X] Yes [] No	NYSDEC, Region 9 and Eco	ology and Environment Engineering, P.C. Buffalo				
V. OTHER FIELD DATA COLLECTED (provide narrative description of sampling activities)						
VI. SOURCES OF INFORMATIO	ON (cite specific references, e.g., sta	te files, sample analysis, reports)				
Niagara County Department of	Health					
Niagara County Environmental NYSDEC Phase I Investigation	Management Council		·			
Ecology and Environment Engineering, P.C., Site Inspection, May 2, 1991						

POTENTIAL HAZARDOUS WASTE SITE		I. IDENTIFICATION			
SITE INSPECTION REPORT					
PART 7 - OWNER INFORMATION		01 State	02 Site Number		
			NY 932101		
II. CURRENT OWNER(S)			PARENT COMPANY (if applicable)		
01 Name T. Dean Johnson	02 D&B Numl	er	08 Name	09 D&B Nt	mber
03 Street Address (P.O. Box, RFD #, etc.) 4425 Miller Road		04 SIC Code	ode 10 Street Address (P.O. Box, RFD #, etc.)		11 SIC Code
05 City Niagara Falls	06 State NY	07 Zip Code 14304	12 City	13 State	14 Zip Code
01 Name	02 D&B Numl	per	08 Name 09 D&B Number		umber
03 Street Address (P.O. Box, RFD #, etc.)	,	04 SIC Code	10 Street Address (P.O. Box, RFD #, etc.)		11 SIC Code
05 City	06 State	07 Zip Code	12 City 03 State		14 Zip Code
01 Name	02 D&B Numi	per	08 Name 09 D&B Num		ımber
03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	le 10 Street Address (P.O. Box, RFD #, etc.)		11 SIC Code
05 City	06 State	07 Zip Code	12 City	13 State	14 Zip Code
III. PREVIOUS OWNER(S) (list most recent first)			IV. REALTY OWNER(S) (if applicable, list most rec	ent first)	
01 Name	02 D&B Numi	per	01 Name 02 D&B Numb		ımber
03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	Code 03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
01 Name	02 D&B Numl	ber	01 Name 02 D&B Num		ımber
03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	Code 03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
01 Name	02 D&B Numi	ber	01 Name 02 D&B Num		umber
03 Street Address (P.O. Box, RFD #, etc.) 04 SIC Code		03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
V. SOURCES OF INFORMATION (cite specific references, e.g., state files, sample ana		lysis, reports)			
•					

POTENTIAL HAZARDOUS WASTE SITE			I. IDENTIFICATION		
SITE INSPECTION REPORT			01 State	02 Site Number	
PART 8 - OPERATOR INFORMATION			NY	932101	
I. CURRENT OPERATOR (provide if different fr	om owner)		OPERATOR'S PARENT COMPANY (if applications)	able)	
Name	02 D&B Numb	er	10 Name 11 D&B Number		umber
03 Street Address (P.O. Box, RFD #, etc.) 04 SI		04 SIC Code	12 Street Address (P.O. Box, RFD #, etc.)	Box, RFD #, etc.)	
95 City	06 State	07 Zip Code	14 City	16 Zip Code	
98 Years of Operation	09 Name of Ov	vner			
II. PREVIOUS OPERATOR(S) (list most recent fi	rst; provide if diffe	rent from	PREVIOUS OPERATORS' PARENT COMPA	NIES (if applicable)	
Name	02 D&B Numb	рег	10 Name 11 D&B Number		ımber
3 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	de 12 Street Address (P.O. Box, RFD #, etc.)		13 SIC Code
)5 City	06 State	07 Zip Code	14 City 15 State		16 Zip Code
98 Years of Operation	09 Name of O	wner During this	8		
01 Name	02 D&B Numb	er	10 Name 11 D&B Number		umber
33 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	Code 12 Street Address (P.O. Box, RFD #, etc.)		13 SIC Code
05 City	06 State	07 Zip Code	14 City 15 State		16 Zip Code
08 Years of Operation	09 Name of O Period	wner During this	iis .		
01 Name	02 D&B Numl	ber	10 Name 11 D&B Number		umber
33 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	Code 12 Street Address (P.O. Box, RFD #, etc.)		13 SIC Code
O5 City	06 State	07 Zip Code	14 City	15 State	16 Zip Code
98 Years of Operation	09 Name of O Period	wner During this	is		
			alysis, reports)		

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT		I. IDENTIFICATION			
		01 State	02 Site Num		
PART 9 - GENERATOR/TRANSPORTER INFORMATION		NY	932101		
II. ON-SITE GENERATOR					
01 Name	02 D&B Numb	er			
03 Street Address (P.O. Box, RFD #, etc.) 04 SIC Code		04 SIC Code			
05 City	06 State	07 Zip Code			:
III. OFF-SITE GENERATOR(S)					
01 Name	02 D&B Numb	ж	01 Name	02 D&B Nu	mber
03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
01 Name	02 D&B Numb	er	01 Name	c 02 D&B N	
03 Street Address (P.O. Box, RFD #, etc.)	03 Street Address (P.O. Box, RFD #, etc.) 04 SIC		03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
IV. TRANSPORTER(S)				<u> </u>	
01 Name Haseley Trucking Co.	02 D&B Number		01 Name 02 D&B N		mber
03 Street Address (P.O. Box, RFD #, etc.) 10315 Lockport Road 04 SIC Code		04 SIC Code	03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City Wheatfield	06 State NY	07 Zip Code	05 City	06 State	07 Zip Code
01 Name	02 D&B Numb	er	01 Name 02 D&B Number		mber
03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code	03 Street Address (P.O. Box, RFD #, etc.)		04 SIC Code
05 City	06 State	07 Zip Code	05 City	06 State	07 Zip Code
V. SOURCES OF INFORMATION (cite specific ref	ferences, e.g., state	e files, sample ana	lysis, reports)	*	
					-
					The state of the s

POTENTIAL HAZARDOUS WASTE SITE		I. IDENTIFICATION			
	SITE INSPECTION REPORT				02 Site Number
PART 10 - PAST RESPONSE ACTIVITIES		NY			932101
II. PAST RESPONSE ACTIVITIES					
01 [] A. Water Supply Closed 04 Description:	02 Da	te	03 Agency		
01 [] B. Temporary Water Supply Provided 04 Description:	02 Da	te	03 Agency		
01 [] C. Permanent Water Supply Provided 04 Description:	02 Da	te	03 Agency		
01 [] D. Spilled Material Removed 04 Description:	02 Da	te	03 Agency		
01 [] E. Contaminated Soil Removed 04 Description:	02 Da	te	03 Agency	4	
01 [] F. Waste Repackaged 04 Description:	02 Da	te	03 Agency		
01 [] G. Waste Disposed Elsewhere 04 Description:	02 Da	te	03 Agency		
01 [] H. On-Site Burial 04 Description:	02 Da	te	03 Agency		
01 [] I. <u>In Situ</u> Chemical Treatment 04 Description:	02 Da	te	03 Agency		
01 [] J. <u>In Situ</u> Biological Treatment 04 Description:	02 Da	te	03 Agency	4	
01 [] K. <u>In Situ</u> Physical Treatment 04 Description:	02 Da	te	03 Agency		
01 [] L. Encapsulation 04 Description:	02 Da	te	03 Agency		
01 [] M. Emergency Waste Treatment 04 Description:	02 Da	te	03 Agency		
01 [] N. Cutoff Walls 04 Description:	02 Da	te	03 Agency		
01 [] O. Emergency Diking/Surface Water Diversion 04 Description:	02 Da	te	03 Agency		
01 [] P. Cutoff Trenches/Sump 04 Description:	02 Da		03 Agency		,

POTENTIAL HAZARDOUS WASTE SITE		I. IDENTIFICATION .		
	SITE INSPECTION REPORT			02 Site Number
PART 10 - PAST RESPONSE ACTIVITIES		NY		932101
II. PAST RESPONSE ACTIVITIES (Cont.)				
01 [] Q. Subsurface Cutoff Wall 04 Description:	02 Dat	e	03 Agency	
01 [] R. Barrier Walls Constructed 04 Description:	02 Dat	c	03 Agency	
01 [] S. Capping/Covering 04 Description:	02 Dat	c	03 Agency	
01 [] T. Bulk Tankage Repaired 04 Description:	02 Dat	c	03 Agency	
01 [] U. Grout Curtain Constructed 04 Description:	02 Dat	e	03 Agency	
01 [] V. Bottom Sealed 04 Description:	02 Dat	e	03 Agency	
01 [] W. Gas Control 04 Description:	02 Dat	e	03 Agency	
01 [] X. Fire Control 04 Description:	02 Date	s	03 Agency	
01 [] Y. Leachate Treatment 04 Description:	02 Date		03 Agency	
01 [] Z. Area Evacuated 04 Description:	02 Date	E	O3 Agency	
01 [] 1. Access to Site Restricted 04 Description:	02 Date	e	O3 Agency	
01 [] 2. Population Relocated 04 Description:	02 Date	e	O3 Agency	
01 [] 3. Other Remedial Activities 04 Description:	02 Date	- (03 Agency	
III. SOURCES OF INFORMATION (cite specific references, e.g., state files, se	ample ans	lysis, reports)		
				,

		•	
POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT	I. IDENTIFICATION		
	01 State	02 Site Number	
PART 11 - ENFORCEMENT INFORMATION	NY	932101	
II. ENFORCEMENT INFORMATION			
01 Past Regulatory/Enforcement Action [] Yes [X] No			
02 Description of Federal, State, Local Regulatory/Enforcement Action			
•			
	•		
III SOLIDOES OF INFORMATION (-in			
III. SOURCES OF INFORMATION (cite specific references, e.g., state files, sample	: analysis, reports)		
NYSDEC Division of Solid and Hazardous Waste Inactive Hazardous Waste Site	Registry files, Region 9.		

APPENDIX C INTERVIEW DOCUMENTATION FORMS

An unsigned Document of Interview indicates that the person interviewed did not return the form as requested by the interviewer.

INTERVIEW ACKNOWLEDGMENT FORM

Walmore Road-Johnson Property Site

Mark Haseley

SITE NAME:

CONTACTED:

PERSON

AFFILIATION:	Haseley Trucking Company					
ADDRESS:	10315 Lockport Road, Wheatfield, New York					
TYPE OF CONTACT:	Telephone interview					
I.D. NUMBER:	932101					
DATE:	May 15, 1991					
PHONE NUMBER:	(716) 297-1550					
CONTACT PERSON(S):	S. Glinski					
INTERVIEW SUMMAR	XY:					
contents of his compa	ey Trucking Company manager could not recall the any's fill transported to the Johnson property. He will find documentation, if any. He remembers many haulers ne site.					
	y's file search has turned up no record of what was hauled ty for the time period in question.					
ACKNOWLEDGMENT						
the information verbal interviewer(s) (as revisional terms of the information verbal interviewer(s) (as revisional terms of the information verbal interviewer(s)).	transcript and I agree that it is an accurate summary of ly conveyed to Ecology and Environment, Inc. sed below, if necessary). ite in any corrections needed to the above transcript)					
Signature	Date					
02:3424INTE-05/29/91-D1						